HILLMANN
CONSULTING

PHASE I ENVIRONMENTAL SITE ASSESSMENT

Fulton
401 West 19th Street, 401 West 18th Street, 427 and 430 West 17th Street
New York, New York 10011

Prepared For:

Elliott Fulton LLC c/o Essence Development
30 Hudson Yards
New York, NY 10001

Report Issuance Date: April 21, 2022
Site Reconnaissance Date: April 19, 2022

Hillmann Project Number Z34898

Environmental Health & Safety | Due Diligence & Remediation Management | Construction Services
Making a better future for all the communities we touch.
www.HillmannConsulting.com

HILLMANN
CONSULTING

April 21, 2022

Mr. Jamar Adams
Elliott Fulton LLC c/o Essence Development
30 Hudson Yards
New York, NY 10001

RE: Phase I Environmental Site Assessment
Fulton
401 West 19th Street, 401 West 18th Street, 427 and 430 West 17th Street
New York, New York 10011
Hillmann Project No: Z34898

Dear Mr. Adams:

Hillmann Consulting LLC has completed a Phase I Environmental Site Assessment of the above referenced property. This assessment was performed in conformance with our contract agreement and the scope and limitations of ASTM Practice E 1527-21, which is the latest version of the E1527 standard published by the ASTM.

We appreciate the opportunity to provide environmental due diligence services. If you have any questions concerning this report, or if we can assist you in any other matter, please contact our office at 908-688-7800.

Sincerely,

Hillmann Consulting, LLC

Chris Hirschmann
Environmental Services Director

Etan Hindin
Senior Project Manager

TABLE OF CONTENTS

1.0 FINDINGS, OPINIONS, AND CONCLUSIONS 1
1.1 Summary of Project Details 1
1.2 Findings Summary Table 2
1.3 Findings, Opinions and Conclusions 2
1.4 Business Environmental Risks / Non-ASTM Scope 5

2.0 INTRODUCTION 6
2.1 Purpose and Scope 6
2.2 Property Location/Legal Description 8
2.3 Data Gaps 9
2.4 ESA Report Component Dates/Viability 9
2.5 User Reliance 9
2.6 Significant Assumptions 10
2.7 General Limitations and Exceptions 10

3.0 USER PROVIDED INFORMATION 13
3.1 Environmental Lien and Activity and Use Limitation (AUL) Search 13
3.2 Prior Environmental Reports/Documentation 13
3.3 User Responsibilities 13
3.4 User's Reason for Performing Phase I ESA 14

4.0 RECORDS REVIEW 15
4.1 Environmental Information 15
4.2 Historical Research 20

5.0 INTERVIEWS 26
5.1 Interviews with Owners, Operators and Occupants 26
5.2 Interviews with State and/or Local Government Officials 26

6.0 SITE RECONNAISSANCE 28
6.1 Methodology and Limiting Conditions 28
6.2 General Site Setting 28
6.3 Site Features and Conditions 29

7.0 BUSINESS ENVIRONMENTAL RISKS 33
7.1 Asbestos-Containing Material (ACM) 33
7.2 Lead-Based Paint 33
7.3 Radon 33
7.4 Mold/Microbial Damage 34
7.5 NWI Mapped Wetlands 34
7.6 Lead in Drinking Water 34

8.0 REFERENCES 35

9.0 APPENDICES 36
Appendix A Site Diagram/Vicinity Map
Appendix B Site Photographs
Appendix C Questionnaires / User Provided Information
Appendix D Historical Records Documentation
Appendix E Regulatory Records Documentation
Appendix F Other Documents / Lab Results
Appendix G Project Personnel Qualifications

List of Abbreviations/Acronyms

Hillmann may use the following abbreviations and acronyms for common terminology described in our report. Not all abbreviations or acronyms may be applicable to this report:

ACM	– Asbestos Containing Material
AOC	– Area of Concern
AST	– Aboveground Storage Tank
ASTM	– American Society for Testing Materials
BER	– Business Environmental Risk
CEA	– Classification Exception Area
CERCLA	– Comprehensive Environmental Response Compensation and Liability Act
CERCLIS	– Comprehensive Environmental Response Compensation and Liability Information System
CESQG	– Conditionally Exempt Small Quantity Generator
COC	– Chemicals of Concern
CORRACTS	– Corrective Action Sites
CREC	– Controlled Recognized Environmental Condition
DEC	– Department of Environmental Conservation
DEP	– Department of Environmental Protection
DHS	– Department of Health Services
DNPL	– Delisted National Priority List
DOB	– Department of Buildings
DOH	– Department of Health
DOT	– Department of Transportation
DTSC	– Department of Toxic Substances Control
ENG	– Engineering
EPA	– Environmental Protection Agency
ERNS	– Emergency Response Notification System
FD	– Fire Department
FOI/FOIA/FOIL	– Freedom of Information / Freedom of Information Act / Freedom of Information Letter
HVAC	– Heating Ventilation & Air Conditioning
HREC	– Historic Recognized Environmental Condition
IAQ	– Indoor Air Quality
ISRA	– Industrial Site Recovery Act
LBP	– Lead-Based Paint
LCP	– Lead-Containing Paint
LQG	– Large Quantity Generator
LTANK	– Leaking Storage Tank
LUST	– Leaking Underground Storage Tank
SDS/MSDS	– Safety Data Sheet / Material Safety Data Sheet
NA	– Not Applicable
NFA	– No Further Action
NFRAP	– No Further Remedial Actions Planned
NPDES	– National Pollutant Discharge Elimination System
NPL	– National Priority List
OER	– Office of Environmental Remediation
OPRA	– Open Public Records Act
PAH	– Polycyclic Aromatic Hydrocarbon
PCE	– Perchloroethylene
RAO	– Response Action Outcome
RCRA	– Resource Conservation and Recovery Act
RCRIS	– Resource Conservation and Recovery Information System
REC	– Recognized Environmental Condition
RWQCB	– Regional Water Quality Control Board
SCAQMD	– South Coast Air Quality Management District
SDG	– Significant Data Gap
SEMS	– Superfund Enterprise Management System
SRP	– Site Remediation Program
SQG	– Small Quantity Generator
SVOC	– Semi-Volatile Organic Compound
TCE	– Trichloroethylene
TSDF	– Treatment Storage and/or Disposal Facility
UST	– Underground Storage Tank
VEC	– Vapor Encroachment Condition
VOC	– Volatile Organic Compound

1.0 FINDINGS, OPINIONS, AND CONCLUSIONS

Hillmann Consulting, LLC (Hillmann) performed a Phase I Environmental Site Assessment (ESA) of 401 West 19th Street, 401 West 18th Street, 427 and 430 West 17th Street, New York, New York (the Subject Property). The assessment has been conducted in accordance with our contracted scope of work and the ASTM Standard Practice E 1527-21 for Phase I Environmental Site Assessments and All Appropriate Inquiries (AAI) Final Rule 40 CFR Part 312. This section contains a summary of findings, opinions and conclusions made by this assessment. However, this section, alone, does not constitute the complete assessment. The report must be read in its entirety.

1.1 Summary of Project Details

Primary Street Address:		401 West 19th Street, 401 West 18th Street, 427 and 430 West 17th Street			
City:	New York	**County:**	New York	**State:**	New York
Tax ID/Parcel Number:		401W19th: Block 717, Lot 19; 401W18th: Block 716, Lot 17; 427W17th: Block 715, Lot 10; 430W17th: Block 714, Lot 31			
Property Owner:		New York City Housing Authority (NYCHA)			
Zoning Designation:		R8-C2-5 (Residential with Commercial Overlay)			
Approx. Property Area:		6.21-acres (combined)			
Buildings:		Eleven residential apartment buildings: B2, B6, B9 are high-rise 25-story plus basement; B1, B3, B4, B5, B7, B8, B10, B11 each 6-story with no basement except B1 and B3 which have a basement; and B12 - freestanding garage (1-story / 2-bay) NOTE: See Appendix A for building numbering/locations			
Approx. Building Size:		974-units (combined)			
Approx. Year Built:		1963-1965			
Commercial Occupants:		Primarily residential with senior center, development/management office and computer lab			
Current Use:		Multifamily residential			
Inspected By:		Mr. Etan Hindin and Mr. Dominick Aponte			
Site Contact/Company:		Mr. Patrick Chan / Property Manager (NYCHA)			
Site Escort/Company:		Rico / Site Caretaker (NYCHA)			
Inspection Date:		April 19, 2022			
Weather Conditions:		Overcast 42 degrees Fahrenheit			

1.2 Findings Summary Table

Assessment Subject	No REC	REC	CREC	HREC	SDG	Rpt. Ref.
Property Regulatory Records Review:				X		4.3
Property Historical Records Review:		X				4.2
Bulk Petroleum Storage:	X					6.3
On-Site Operations:	X					6.3
On-Site Haz-Mat Storage/Use/Spills:	X					6.3
Transformers/Hydraulic Systems:	X					6.3
Waste Discharges:	X					6.3
Interviews:	X					5.0
Adjoining & Nearby Properties:	X					4.3 6.2
Prior Env. Reports/User Provided Info:	X					3.0

1.3 Findings, Opinions and Conclusions

Recognized Environmental Conditions & Significant Data Gaps

Hillmann has performed a Phase I Environmental Site Assessment in accordance with the scope and limitations of ASTM Practice E 1527-21 of the Subject Property as described in Section 2.2 of this report. Any additions to, exceptions to, or deletions from this practice are also described in Section 2 of this report. This assessment has revealed the following *recognized environmental conditions* (RECs), *controlled recognized environmental conditions* (CRECs) and/or *significant data gaps* (SDGs) in connection with the Subject Property:

RECOGNIZED ENVIRONMENTAL CONDITIONS

Multiple historic uses of potential environmental concern occurred at the Property prior to the 1963-1965 construction of the present Property buildings, per review of Sanborn Fire Insurance Maps, as follows:

- Vinegar Factory at 424-426 West 17th Street (off the east side of the present Property Building 4) in 1895;
- "Chinese Laundry" at 101 and 119 9th Avenue (near present Property Buildings 2 and 7) in 1904;
- 165-car garage with auto-repair operations in the basement and a 1,500-gallon gasoline buried tank (in the vicinity of the present asphalt surface parking south of Building 2) and a 15-car private garage with a buried gasoline tank (capacity indecipherable) at 409 West 17th Avenue (off the west side of the present Property Building 7), and iron works 434-436 West 17th Avenue and 414 19th Avenue in 1921;
- Filling station (gas station), taxi garage and auto repair with multiple gasoline tanks depicted along ninth avenue between West 16th and West 17th Avenue and along West 16th and West 17th Avenue (see Appendix A figure), and an additional auto filling/service station with multiple gasoline tanks depicted at the northwest corner of 9th Avenue and West 17th Street (near the southern edge of the present Building 7) and auto painting (431-433 West 17th) and repair (443-445 West 17th), a motor freight terminal (410-412 West 19th) in 1950.

The aforementioned historic uses including a factory, laundry, iron works, motor freight station, auto filling/service stations with multiple gasoline tanks is considered a REC. Two (2) groundwater monitoring wells were observed within the Property north of B12 (two-bay Property garage) and northwest of B4 on the south side of West 18th and West 17th Streets respectively. The trigger for the installation of these wells and their use for sampling/monitoring if any was unknown by the site escort/contact. Hillmann recommends obtaining records of a subsurface investigation (if already performed) or performing a subsurface investigation to determine the presence/absence of impact to underlying environmental media from aforementioned uses and the presence/absence of abandoned underground storage tanks (USTs) in areas not excavated in the 1960's for the construction of the present Property buildings. If the onsite groundwater monitoring wells observed during the site reconnaissance are no longer in use, said wells should be decommissioned in accordance with applicable regulations.
CONTROLLED RECOGNIZED ENVIRONMENTAL CONDITIONS (CRECs)
No CRECs were identified.
SIGNIFICANT DATA GAPS (SDGs)
No SDGs were identified.

Historical Recognized Environmental Conditions (HRECs)

This assessment has revealed the following *historical recognized environmental conditions* (HRECs) in connection with the Subject Property:

HISTORICAL RECOGNIZED ENVIRONMENTAL CONDITIONS	
	An NY SPILLS database listing for the "Excavation Site - Front of 413 West 16th Street" details the discovery of a fuel odor during an unrelated excavation (infrastructure work on a sewer line and transformer vault) leading to the removal of approximately 40 cubic yards of soil on May 27, 2005. Given the impact identified and subsequent remediation (soil removal) and regulatory closure, listed as closed on December 27, 2005, the NY SPILLS listing is considered an HREC. Hillmann notes that given the nature of the discovery of the impact (unrelated excavation likely along the sidewalk in front of 413 West 16th Street) and title of the listing "Front of…" the investigation/soil removal was likely not comprehensive enough to determine the presence/absence of impact from historical uses to the rest of the 430 West 17th Street Parcel (Block 714, Lot 31), a parcel noted above with historic uses including multiple gasoline tanks and an auto filling/service station.

De Minimis and Other Environmental Conditions

The following *de minimis* and other environmental conditions were identified:

OTHER ENVIRONMENTAL CONDITIONS / DE MINIMIS CONDITIONS
401-411 West 18th Street (Building 8) is listed on the UST database for a 1,500-gallon UST removed on June 5, 2017. The listing does not indicate any release was identified during the UST removal and is not considered a REC.
400 West 17th Street (Building 7) is listed on the NY SPILLS database due to an incident involving wastewater in June 2020. The case obtained regulatory closure and due to the nature of the spill and regulatory status is not considered a REC.
Multiple Con-Edison listings (MANIFEST, RCRA-NonGen, FINDS, ECHO) associated with Property addresses were identified. The listings are associated with infrastructure work generating regulated waste. The listings are not indicative of a release and not considered a REC.

427-431 West 17th Street / NYCHA-Fulton Houses is listed on the RCRA-NonGen, FINDS and ECHO databases likely associated with the removal of regulated waste. The listings are regulatory in nature, not indicative of a release and not considered a REC.
West 17th Street and 10th Avenue is listed on the Brownfields database. The site is located to the adjacent west of Property building 4. In 2004 during a Phase I and II, contaminants of concern were identified associated with past uses of petroleum and historic fill. Soils and groundwater were identified to be contaminated with VOCs, petroleum related and chlorinated solvents and SVOCs. The listings details the subsequent remediation as follows: "*A Track 4 cleanup was achieved for the site. Engineering and Institutional Controls have been instituted to manage the residual contamination. These controls have been memorialized in the Environmental Easement that has been recorded in the New York County Clerk's office. The Certificate of Completion was issued on October 6, 2008.* *Public water is provided to the area, thereby preventing exposures to groundwater. The remedial action work plan for the site calls for the removal of contaminated soil from the site prior to construction of a residential building on-site. Soil gas is contaminated by chlorinated solvents that are likely due to an off-site source. The site owner will include measures in the building construction to prevent soil vapor migration into the building.*" Given the above, a vapor encroachment condition to the Property cannot be ruled out.

Environmental Professional Statement

I/We declare that, to the best of my professional knowledge and belief, I/we meet the definition of *Environmental professional* as defined in § 312.10 of 40 C.F.R. 312. I/we have the specific qualifications based on education, training and experience to assess a *property* of the nature, history and setting of the *subject property*. I/We have developed and performed all appropriate inquiries in conformance with the standards and practices set forth in 40 C.F.R. Part 312.

_____

Etan Hindin
Environmental Professional

_____

Chris Hirschmann
Environmental Professional

1.4 Business Environmental Risks / Non-ASTM Scope

Hillmann has performed a limited review of the following potential Business Environmental Risks (BER), also known as "Non-ASTM Scope concerns", in accordance with the contracted scope of work scope for this assessment. BER is defined by ASTM E1527-21 as *"a risk which can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of a parcel of commercial real estate, not necessarily limited to those environmental issues required to be investigated in this practice."* The following is a summary of findings for the limited review of potential BERs, where applicable, as per the contracted scope of work and limitations outlined in Section 2. For a more detailed discussion of the findings and contracted scope of work, please see the referenced report section.

BUSINESS ENVIRONMENTAL RISKS / NON-ASTM SCOPE			
Subject	**Findings**	**Not Appl.**	**Rpt. Ref.**
Asbestos	Given the 1963-1965 years of construction, asbestos containing materials are suspected unless ruled out by laboratory analysis. Suspected ACM noted within the accessed building areas included floor tile, wall-board, spray-of insulation and roofing materials		7.1
Lead Paint	Given the 1963-1965 years of construction, lead-paint is suspected unless ruled out by field survey or laboratory analysis. Lead sampling was reportedly being performed due to the December 21, 2021 modification to the legal lead-based paint standard to 0.5 mg/cm^2 (Local Law 66 and rules adopted by the Department of Housing Preservation and Development [HPD]) The results of the survey have been requested by Hillmann.		7.2
Radon	The Property is located in the USEPA radon designation Zone 3 or 'low risk' area for radon.		7.3
Mold / Microbial Damage	The basement of Building 1 was observed to have standing water on the concrete surface with some discoloration. Intermittent pipe and roof leaks were reportedly common given the age of the building. Mold abatement, primarily removing water damaged wall-board is reportedly performed by NYCHA staff as needed.		7.4
NWI Wetlands	No NWI Wetlands were depicted within the Property.		7.5
Lead in Drinking Water	Potable water service at the Subject Property is provided by the City of New York. The water purveyor water supply is within acceptable standards. Property building specific lead-in-drinking water sampling was not performed.		7.6

2.0 INTRODUCTION

2.1 Purpose and Scope

This assessment was conducted utilizing generally accepted Phase I ESA industry standards in accordance with the ASTM Standard Practice E 1527-21. The ASTM describes these methodologies as representing good commercial and customary practice in the United States of America for conducting an environmental site assessment of a parcel of commercial real estate with respect to the range of contaminants within the scope of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) (42 U.S.C. § 9601) and petroleum products. As such, this practice is intended to permit a user to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner or bona fide prospective purchaser limitations on CERCLA liability (hereinafter, the "landowner liability protections," or "LLPs"): that is, the practice that constitutes all appropriate inquiries into the previous ownership and uses the property consistent with good commercial and customary practice as defined at 42 U.S.C. §9601(35) (B). The goal of the processes established by ASTM E1527-21 is to identify *recognized environmental conditions* in connection with the Subject Property.

The term *recognized environmental condition* (REC) is defined by ASTM E1527-21 as *"(1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment."*

The term *controlled recognized environmental condition* is a type of recognized environmental condition and defined by ASTM E1527-21 as a *"recognized environmental condition affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to implementation of required controls (for example, activity and use limitations or other property use limitations)."*

The term *historical recognized environmental condition* is defined as a *"previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls (for example, activity and use limitations or other property use limitations)."* The ASTM E1527-21 standard has clarified that a *historical recognized environmental condition* (HREC) is not a *recognized environmental condition* (REC).

The term *de minimis condition* is defined by the ASTM, *"…a condition related to a release that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies."* A condition determined to be a *de minimis condition* is not REC nor a CREC.

The chief components of this assessment are generally described as follows:

- A non-invasive visual reconnaissance of the Subject Property and adjoining properties in accordance with ASTM guidelines for evidence of RECs.

- Interviews of past and present owners and occupants and state and local government officials, seeking information related to the potential presence of RECs at the Subject Property.

- A review of standard physical record sources for available topographic, geologic and groundwater data.

- A review of standard historic record sources, such as fire insurance maps, city directories, aerial photographs, prior reports and interviews, etc., to determine prior uses of the Subject Property from the present, back to the Subject Property's first developed use, or back to 1940, whichever is earlier.

- A review of standard environmental record sources including federal and state environmental databases, and additional environmental record sources, to identify potential regulatory concerns with the Subject Property, adjoining properties and properties located within the surrounding area.

An evaluation of environmental or other regulatory compliance matters is excluded from the scope of this assessment.

These methodologies are described as representing good commercial and customary practice for conducting an Environmental Site Assessment of a property for the purpose of identifying recognized environmental conditions.

Business Environmental Risks/Non-ASTM Scope Considerations

In accordance with our contract agreement, Hillmann may have addressed the following potential environmental subject matters that are outside of the requirements of the ASTM E1527-21 standard:

- Asbestos-Containing Materials (ACM): A cursory non-intrusive visual screening for the presence of suspect ACM within the accessed areas of buildings built prior to 1990 on the Subject Property. If the Subject Property contains buildings built in 1990 or later, the contracted scope of work excludes a cursory non-intrusive visual screening or any other level of evaluation for suspect ACM; however, the exclusion for buildings built ≥1990 should not be interpreted to suggest that any such buildings are free of ACM or would not warrant evaluation of building materials for ACM prior to disturbance. It is emphasized that this cursory non-intrusive visual screening does not constitute an asbestos survey/inspection of the premises. An asbestos survey/inspection should be sought by the report User(s) if a greater certainty is desired regarding ACM and potential asbestos hazards at the Subject Property. Furthermore, a review of regulatory compliance matters pertaining to asbestos is excluded from the scope of work.

- Lead-Based Paint (LBP): A cursory non-intrusive visual screening of the condition of painted surfaces in the accessed areas of residential buildings/units built prior to 1980 on the Subject Property. If the Property contains buildings built in 1980 or later, the contracted scope of work excludes any cursory non-intrusive visual screening or other level of evaluation for suspect

LPB; however, the scope of work exclusion for building built ≥1980 should not be interpreted to suggest that any such buildings are free of LPB or other lead hazards. It is emphasized that this cursory non-intrusive visual screening does not constitute a comprehensive survey for LBP or potential lead hazards. A comprehensive inspection should be sought by the report User(s) if more certainty is desired regarding LBP at the Subject Property. Furthermore, a review of regulatory compliance matters pertaining to lead-based paint is excluded from the scope of work.

- USEPA Designated Radon Potential: Review of general non-site specific data published by the USEPA regarding the Radon Zone classification for the area of the Subject Property.

- Mold/Microbial Damage: A cursory non-intrusive visual screening within the accessed areas of buildings on the Subject Property for evidence of systemic microbial problems, including visible mold growth, water damaged building materials or musty odors. It is emphasized that this cursory non-intrusive visual screening does not constitute a comprehensive survey for moisture/mold/microbial damage. A more comprehensive inspection should be sought by the report User(s) if more certainty is desired regarding the potential for moisture/mold/microbial damages at the Subject Property.

- NWI Wetlands: The Property has been reviewed for jurisdictional wetlands using the National Wetlands Inventory Wetland Mapper (http://wetlandsfws.er.usgs.gov/NWI/download.html) to determine whether mapped federal wetlands have been indicated on the Subject Property. Any further evaluation or legal delineation of regulated wetlands areas is excluded from the scope of work. It is also emphasized that a field delineation of regulated wetlands by a qualified professional would be warranted to more fully determine the presence or absence of regulated wetlands at the Subject Property.

- Lead in Drinking Water: Review of the potential for elevated levels of lead in the drinking water by determining the source of the drinking water supply and a review of available testing or compliance data reports.

2.2 Property Location/Legal Description

Property location and legal description details are described as follows:

Primary Street Address:	401 West 19th Street, 401 West 18th Street, 427 and 430 West 17th Street				
City:	New York	**County:**	New York	**State:**	New York
Tax ID/Parcel Number:	401W19th: Block 717, Lot 19; 401W18th: Block 716, Lot 17; 427W17th: Block 715, Lot 10; 430W17th: Block 714, Lot 31				
Approx. Land Area:	6.21-acres (combined)				
Apprx. Latitude/Longitude:	North 40.7436330 degrees/West 74.0043040 degrees				
Additional Details (if appl.):	Secondary address range: 89-157 9th Avenue; 401-433 West 19th;				

	400-426 West 19th; 401-423 West 18th; 400-434 West 18th; 401-445 West 17th; 400-438 West 17th; 401-429 West 16th;
Property Owner:	New York City Housing Authority (NYCHA)
Zoning Designation:	R8-C2-5 (Residential with Commercial Overlay)

2.3 Data Gaps

A *data gap* is defined by the ASTM as a lack of or inability to obtain information required by this practice despite good faith efforts by the environmental professional to gather such information. A data gap is only significant if other information and/or professional experience raises reasonable concerns involving the data gap and the ability to determine the presence or absence of recognized environmental conditions. The following table summarizes data gaps encountered during the assessment as well as a discussion of their significance.

Data Gap:	Significant (Yes/No)?	Discussion
Historical records data failure	No	Records gaps exceeding five years were encountered; however, no significant site use changes are suspected during these intervals.
Response to agency records requests not received as of date of report.	No	Any additional information indicative of a REC will be forwarded upon receipt.

2.4 ESA Report Component Dates/Viability

The ASTM E1527-21 standard states that an environmental site assessment (ESA) is presumed to be viable when it is conducted within 180 days prior to the date of acquisition of the Subject Property (or, for transactions not involving an acquisition such as a lease or refinance, the date of the intended transaction). Specifically, all of the following components must be conducted or updated within 180 days prior to the date of acquisition or prior to the date of the transaction. The following table summarizes the component completion dates:

ESA Component	Completion Date
Interviews	April 19, 2022
Env Lien Search	(excluded from scope)
Government Records Review	March 31
Visual Inspections	April 19, 2022
Env. Professional Declaration	April 21, 2022

2.5 User Reliance

This report is for the exclusive use of Elliott Fulton LLC c/o Essence Development and additional relying entities, if any, named on the front cover. No additional individuals or entities shall be

permitted to rely upon any data, interpretation, reports or other information or documentation contained in this report, without first obtaining the consent of Elliott Fulton LLC c/o Essence Development; and without obtaining written consent from Hillmann in the form of a reliance agreement/letter.

Hillmann may, in its sole discretion, withhold its consent to additional reliance and/or Hillmann may condition consent for reliance upon payment of a fee or other conditions.

2.6 Significant Assumptions

The following significant assumptions are made:

- The site operations at the time of the site visit are assumed to reflect typical site conditions relative to potential environmental conditions and that no concealment of environmental conditions or releases by site owners or occupants has occurred. Likewise, it is assumed that no areas of the Subject Property with potential environmental concerns or RECs were concealed or otherwise not reported, intentionally or unknowingly, by the Subject Property owners/occupants and/or site escort at the time of the site visit.

- For the purpose of estimating the approximate direction of groundwater flow in the absence of site specific groundwater data, unless indicated otherwise, an assumption has been made that the gradient of groundwater flow follows the surface topography of the Subject Property and immediate surrounding area.

2.7 General Limitations and Exceptions

Limitations

The report turnaround time specified by the contract agreement for this assessment may present a limitation to the availability of pertinent regulatory agency records. Such limitations, if encountered, would be further specified in Section 4.1.

Significant limitations related to the condition or accessibility of the Subject Property at the time of the site reconnaissance, if encountered, are reported in Section 6.1.

Other Exceptions or Deletions

No other exceptions or deletions from the ASTM Standard E 1527-21 are reported.

Special Terms and Conditions

This Phase I Environmental Site Assessment has been prepared using reasonable efforts in each phase of its work to identify recognized environmental conditions associated with hazardous substances, wastes and petroleum products at the Subject Property. Findings within this report are based on information collected from observations made on the day of the site reconnaissance and from reasonably ascertainable information obtained from governing public agencies and private sources.

This report is not definitive and should not be assumed to be a complete or specific definition of the conditions above or below grade. Information in this report is not intended to be used as a construction document and should not be used for demolition, renovation, site development, redevelopment, or other construction purposes. No representation or warranty is made that the past or current operations at the Subject Property are, or have been, in compliance with all applicable federal, state and local laws, regulations and codes.

Findings, conclusions and recommendations presented in this report are based on visual observations of the Subject Property, interviews conducted, the records reviewed, information provided by the Client, and/or a review of readily available and supplied drawings and documents. Information obtained during the assessment, whether written, graphic or verbal, provided by the Subject Property contact(s) or as shown on any documents reviewed or received from the Subject Property contact, owner or agent, or government agency source; is assumed to be accurate except as specifically stated otherwise in this report. Independent verification of the accuracy or completeness of all information reviewed or received during the course of this assessment is not made and excluded from the scope of work for this assessment. No warranty or guarantee is made of the accuracy or completeness of information that was obtained from ostensibly knowledgeable individuals, regulatory agency representatives or other secondary sources.

Regardless of the findings stated in this report, Hillmann is not responsible for consequences or conditions arising from facts that were concealed, withheld or not fully disclosed at the time the assessment was conducted.

This report does not warrant against future operations or conditions, nor does it warrant against operations or conditions present of a type or at a location not investigated.

The regulatory database report provided is based on an evaluation of the data collected and compiled by a contracted data research company. Hillmann can neither warrant nor guarantee the accuracy or completeness of the information obtained from the regulatory database report provider during the course of this assessment.

Subsurface conditions may differ from the conditions implied by the surface observations and can only be reliably evaluated through intrusive techniques.

Reasonable efforts have been made during this assessment to identify aboveground and underground storage tanks and ancillary equipment. Reasonable efforts are limited to information gained from visual observation of largely unobstructed areas, recorded database information held in public record and available information gathered from interviews. Such methods may not identify surficial and subsurface features that may have been hidden from view due to parked automobiles and other vehicles, snow cover, vegetative growth, pavement, construction or debris pile storage or incorrect information from sources.

No guarantee, explicit or implied, is made that the records pertaining to historical ownership or occupancy which were reviewed represent a comprehensive or precise delineation of past Property ownership or tenancy for legal purposes.

The ASTM E1527-21 standard states that recommendations are not required to be included in a Phase I ESA report; however, further that recommendations are an additional service that may be useful in the User's analysis of landowner liability protections or business environmental risks; and that the User should consider whether recommendations for additional inquiries or other services are desired.

Recommended response actions offered in Section 1.3, if any, are provided as an option to the Client, and may have taken into account the Client's relation to the Subject Property and/or their intended purpose of this assessment. If included, it is not intended by Hillmann to represent the only course(s) of action, or inaction, to take. Furthermore, it is emphasized that additional response actions may become advisable depending on the outcome of the initial action(s) taken. Hillmann advises that Client and any additional authorized relying parties as specified on the report Cover and Section 2.5, or via letter of reliance extension, undertake consultation with legal counsel familiar with environmental and real estate law would be beneficial to the decision making process for the type and timing of a response action to identified RECs or Business Environmental Risks, if any.

Due to the limited nature of our review of potential Business Environmental Risks, the User(s) of the report should consider whether to take additional action(s) to further define, properly manage and/or mitigate potential BERs.

The User(s) assumes responsibility for business decisions that it makes utilizing information in the report provided by Hillmann. Hillmann shall not be responsible for any conclusions, interpretations and/or decisions of the User(s).

In the event of any conflict between the terms and conditions of this report and the terms and conditions of the consulting services agreement for this project, the consulting services agreement shall control.

3.0 USER PROVIDED INFORMATION

The term "User" is defined by ASTM as the party seeking to use Practice E1527 to complete an environmental site assessment of the Subject Property; specifically, the entity or entities named on the front cover to which the report has been addressed.

3.1 Environmental Lien and Activity and Use Limitation (AUL) Search

The User did not provide Hillmann with the results of an environmental lien and AUL search for the Subject Property.

3.2 Prior Environmental Reports/Documentation

No prior environmental reports/documentation were provided.

3.3 User Responsibilities

Section 6 of the ASTM E1527-21 standard describes certain tasks required to be performed by the report User in order to qualify for landowner liability protections to CERCLA liability. To assist the report User to meet these requirements, the ASTM E1527-21 standard recommends a questionnaire of inquiries (User Questionnaire) specified in 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31 be provided to the original report User. A User Questionnaire has been provided to the report User; however, a completed questionnaire was not returned to Hillmann.

Question:	Yes/No:	Detail:
Environmental liens that are filed or recorded against the property: Did a search of recorded land title records identify any environmental liens filed or recorded against the property under federal, tribal, state or local law?	NR	
Activity and use limitations that are in place on the property or that have been filed or recorded against the property: Did a search of recorded land title records (or judicial records where appropriate, identify any AULs, such as engineering controls, land use restrictions or institutional controls that are in place at the property and/or have been filed or recorded against the property under federal, tribal, state or local law?	NR	
Specialized knowledge or experience of the person seeking to qualify for the LLP: Do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?	NR	
Relationship of the purchase price to the fair market value of the property if it were not contaminated: Does the purchase price being paid for this property reasonably reflect the fair market value of the property? If you conclude that there is a difference, have you considered whether the lower	NR	

Question:	Yes/No:	Detail:
purchase price is because contamination is known or believed to be present at the property?		
Commonly Known or Reasonably Ascertainable Information: Are you aware of commonly known or reasonably ascertainable information about the property that would help the environmental professional to identify conditions indicative of releases or threatened releases? For example,		
-Do you know the past uses of the property?	NR	
-Do you know of specific chemicals that are present or were once present at the property?	NR	
-Do you know of spills or other chemical releases that have taken place at the property?	NR	
-Do you know of any environmental cleanups that have taken place at the property?	NR	
The degree of obviousness of the presence or likely presence of contamination at the property, and the ability to detect the contamination by appropriate investigation: Based on your knowledge and experience related to the property are there any obvious indicators that point to the presence or likely presence of releases at the property?	NR	
Litigation/Administrative Proceedings/Government Notices As the User of this ESA, do you have knowledge of (1) any pending, threatened, or past litigation relevant to hazardous substances or petroleum products in, on, or from the property; (2) any pending, threatened, or past administrative proceedings relevant to hazardous substances or petroleum products in, on or from the property; and (3) any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products.	NR	

NR-no response

3.4 User's Reason for Performing Phase I ESA

The User did not indicate the purpose of the assessment. In accordance with ASTM E1527-21, it is assumed that the Phase I ESA was being performed in order to qualify for landowner liability protection to CERCLA liability.

4.0 RECORDS REVIEW

4.1 Environmental Information

Physical Setting

Source	Discussion
USGS 7.5 minute Topographic Map Data: (EDR Geocheck-Physical Setting Source Addendum)	The Property lies at an elevation of approximately 14 feet above mean sea level. An interpretation of topographic contour lines as well as a review of the EDR Geocheck-General Topographic Gradient suggested terrain sloping downward towards the west-northwest. The closest down gradient water body is the Hudson River, located approximately 850-ft to the west-northwest.
USDA SCS Soil Data: (EDR Geocheck-Physical Setting Source Addendum)	The soil type at the Subject Property is classified as "Urban Land". The Urban Land designation indicates that a majority of the original soils on the site have been disturbed by development or covered with impervious surfaces, such as buildings or pavement.
Geologic Data: (EDR Geocheck-Physical Setting Source Addendum)	The Geologic Age Identification Category for the Property is Stratified Sequence, and the Rock Stratigraphic Unit is the Paleozoic Eta, Ordovicias System and Lower Orodovician and Cambrian carbonate rocks Series.
Prior Env. Reports: (Section 3.2)	None provided.
Additional Sources/ Data:	An eastern adjacent Property listed on the Brownfields database, 10th Avenue between West 16th and 17th Streets is listed as having groundwater at 10-14 feet below ground surface (bgs).
Groundwater Flow Discussion:	Based on a review of the above information as well as observation of the site, the direction of shallow groundwater flow at the site is inferred to be towards the west-northwest.

Federal, State and Tribal Environmental Record Sources

Standard government records were obtained and reviewed primarily via a third-party regulatory database report, titled EDR Radius Map™ Report, prepared by Environmental Data Resources of Shelton, CT. The report provided government records from the standard environmental resources and within minimum search distances specified by Section 8.2.2-Table 2 of the ASTM E1527-21; and were reviewed for the purpose of identifying potential RECs in connection with the Subject Property. Additional detail of the source and significance of the regulatory databases can be found in the regulatory database report in Appendix E. Hillmann has also included discussion of records pertaining to the Subject Property from other government record sources not specifically listed under Table 2, as applicable.

Reported distances for adjoining property listings, if applicable, are approximate and indicative of the presence of a public roadway or right-of-way between the adjoining site and Property.

The reported gradients have been estimated based on a number of factors including but not necessarily limited to field observation, review of topographic maps, database listing details and/or site specific geo-technical data.

Limited analysis of the details of on-site, adjoining and vicinity database sites was conducted to identify potential sources of sub-surface vapor encroachment. This review was based on elements of the ASTM "Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions" (ASTM E 2600-15); and also on elements of "Methodology for Identifying the Area of Concern Around a Property Potentially Impacted by Vapor Migration from Nearby

Contaminated Sources" (Buonicore, 2011-S-103-AWMA). Vicinity database sites pertaining to non-petroleum product releases within 1,760 feet of the Subject Property in the up-gradient direction, 365 feet of the Subject Property in the cross gradient direction and 100 feet of the Subject Property in the down gradient direction; and vicinity database sites pertaining to petroleum product releases within 528 feet of the Subject Property in the up-gradient direction, 165 feet of the Subject Property in the cross gradient direction and 100 feet of the Subject Property in the down gradient direction were reviewed to identify active contamination sites with the potential to affect subsurface vapor conditions at the Subject Property. The potential for vapor encroachment was considered in assessing whether or not a REC exists in connection with the Subject Property when reviewing applicable sites within those distances.

Regulatory database sites with active petroleum or non-petroleum releases that are considered to constitute a vapor encroachment condition (VEC) to the Subject Property, if any, are identified and discussed in this section.

The EDR Radius Map report is attached in Appendix E.

Property Listings

The following listings of the Subject Property were identified:

- An NY SPILLS database listing for the "Excavation Site - Front of 413 West 16th Street" details the discovery of a fuel odor during an unrelated excavation (sewer line to transformer vault) leading to the removal of approximately 40 cubic yards of soil on May 27, 2005. Given the impact identified and subsequent remediation (soil removal) and regulatory closure – listed as closed on December 27, 2005, the NY SPILLS listing is considered an HREC.

  Hillmann notes that given the nature of the discovery of the impact (unrelated excavation likely along the sidewalk in front of 413 West 16th Street) and title of the listing "Front of…" the investigation/soil removal was likely not comprehensive enough to determine the presence/absence of impact to the rest of the 430 West 17th Street Parcel (Block 714, Lot 31), a parcel noted above with historic uses including multiple gasoline tanks and an auto filling/service station.

- 401-411 West 18th Street (Building 8) is listed on the UST database for a 1,500-gallon UST removed on June 5, 2017. The listing does not indicate any release was identified during the UST removal and is not considered a REC.

- 400 West 17th Street (Building 7) is listed on the NY SPILLS database due to an incident involving wastewater in June 2020. The case obtained regulatory closure and due to the nature of the spill and regulatory status is not considered a REC.

- Multiple Con-Edison listings (MANIFEST, RCRA-NonGen, FINDS, ECHO) associated with Property addresses were identified. The listings are associated with infrastructure work generating regulated waste. The listings are not indicative of a release and not considered a REC.

- 427-431 West 17th Street / NYCHA-Fulton Houses is listed on the RCRA-NonGen, FINDS and ECHO databases likely associated with the removal of regulated waste. The listings are regulatory in nature, not indicative of a release and not considered a REC.

Adjoining Property Listings

The following adjoining property listings were identified.

- Multiple adjacent Con-Edison listings (MANIFEST, RCRA-NonGen, FINDS, ECHO) were identified. The listings are associated with infrastructure work generating regulated waste. The listings are not indicative of a release and not considered a REC in connection with the Property.

- Multiple adjacent sites are listed on the NY SPILLS and LTANKS databases. Each of the adjacent listings obtained regulatory closure and are not considered a REC in connection with the Property.

- West 17th Street and 10th Avenue is listed on the Brownfields database. The site is located to the adjacent west of Property building 4. In 2004 during a Phase I and II, contaminants of concern were identified associated with past uses of petroleum and historic fill. Soils and groundwater were identified to be contaminated with VOCs petroleum related and chlorinated solvents and SVOCs. The listings details the subsequent remediation as follows:

  "*A Track 4 cleanup was achieved for the site. Engineering and Institutional Controls have been instituted to manage the residual contamination. These controls have been memorialized in the Environmental Easement that has been recorded in the New York County Clerk's office. The Certificate of Completion was issued on October 6, 2008.*

  Public water is provided to the area, thereby preventing exposures to groundwater. The remedial action work plan for the site calls for the removal of contaminated soil from the site prior to construction of a residential building on-site. Soil gas is contaminated by chlorinated solvents that are likely due to an off-site source. The site owner will include measures in the building construction to prevent soil vapor migration into the building."

  Given the above, a vapor encroachment condition to the Property cannot be ruled out.

Surrounding Area Findings

The following is a discussion of non-adjoining sites identified as located within the ASTM specified search distance surrounding the Subject Property. In order to keep this discussion informative and concise, discussion(s) is/are provided of the listed site(s) for each database category that appears most likely to impact the Subject Property based on distance, area topography and/or regulatory status. Listings of sites within the applicable search distances not specifically discussed below were reviewed and concluded not to be RECs in connection with the Subject Property or VECs based on various factors including distance, area topography, known or inferred groundwater flow direction and/or regulatory status.

Federal NPL				**# of sites:**	1	**Search Distance:**	1-mile
Notable Listing:	Hudson River PCBs						
Distance in feet:	850	**Direction:**	WNW	**Gradient:**	Down		
Data Discussion:	Given the location and nature of the NPL case – PCBs in the Hudson River sediment, the listing is not considered a REC to the Property.						
REC Discussion:	Based on the details provided above, a REC is not suspected in connection with the Property.						
VEC Discussion:	Based on the available data, a VEC is not suspected.						

Federal Delisted NPL				**# of sites:**	0	**Search Distance:**	1-mile
Notable Listing:	None						
Distance in feet:		**Direction:**		**Gradient:**			
Data Discussion:							
REC Discussion:							
VEC Discussion:							

Federal SEMS				**# of sites:**	1	**Search Distance:**	½-mile
Notable Listing:	Hudson River PCBs						
Distance in feet:	850	**Direction:**	WNW	**Gradient:**	Down		
Data Discussion:	Given the location and nature of the SEMS case (also listed on the NPL database) – PCBs in the Hudson River sediment, the listing is not considered a REC to the Property.						
REC Discussion:	Based on the details provided above, a REC is not suspected in connection with the Property.						
VEC Discussion:	Based on the available data, a VEC is not suspected.						

Federal SEMS-ARCHIVE				**# of sites:**	2	**Search Distance:**	½-mile
Notable Listing:	Federal Building / 252 7th Avenue						
Distance in feet:	2,216	**Direction:**	E	**Gradient:**	Up/Cross		
Data Discussion:	Given the distance the SEMS-ARCHIVE sites are not considered a REC in connection with the Property.						
REC Discussion:	Based on the details provided above, a REC is not suspected in connection with the Property.						
VEC Discussion:	Based on the available data, a VEC is not suspected.						

Federal CORRACTS				**# of sites:**	0	**Search Distance:**	1-mile
Notable Listing:	None						
Distance in feet:		**Direction:**		**Gradient:**			
Data Discussion:							
REC Discussion:							
VEC Discussion:							

Federal RCRA-TSD				**# of sites:**	0	**Search Distance:**	½-mile
Notable Listing:	None						
Distance in feet:		**Direction:**		**Gradient:**			
Data Discussion:							
REC Discussion:							
VEC Discussion:							

State/Tribal SUPERFUND & HAZARDOUS WASTE	**# of sites:**	7	**Search Distance:**	1-mile

Notable Listing:	Bayview Correctional Facility / 550 West 20th Street				
Distance in feet:	987	**Direction:**	NW	**Gradient:**	Down
Data Discussion:	Given the distance, gradient and/or regulatory status the SHWS listing are not considered a REC in connection with the Property.				
REC Discussion:	Based on the details provided above, a REC is not suspected in connection with the Property.				
VEC Discussion:	Based on the available data, a VEC is not suspected.				

State/Tribal LANDFILL/SOLID WASTE DISPOSAL				**# of sites:**	1	**Search Distance:**	½-mile
Notable Listing:	NYCDOS Ganesvoort MTS (near 14th Street)						
Distance in feet:	1,718	**Direction:**	SSW	**Gradient:**	Down		
Data Discussion:	Given the distance and downgradient location, the NYCDOS transfer station is not considered a REC in connection with the Property.						
REC Discussion:	Based on the details provided above, a REC is not suspected in connection with the Property.						
VEC Discussion:	Based on the available data, a VEC is not suspected.						

State/Tribal LEAKING STORAGE TANKS				**# of sites:**	132	**Search Distance:**	½-mile
Notable Listing:	Auto Care West / 464 West 18th Street						
Distance in feet:	145	**Direction:**	W	**Gradient:**	Down		
Data Discussion:	Given the distance, gradient and/or regulatory status, the LTANKS listings are not considered a REC in connection with the Property.						
REC Discussion:	Based on the details provided above, a REC is not suspected in connection with the Property.						
VEC Discussion:	Based on the available data, a VEC is not suspected.						

State/Tribal VOLUNTARY CLEANUP SITES				**# of sites:**	20	**Search Distance:**	½-mile
Notable Listing:	118 10th Avenue / Hudson Yards-Chelsea-Flatiron Union Square						
Distance in feet:	209	**Direction:**	NW	**Gradient:**	Down		
Data Discussion:	Given the nature of the listings and/or distance/gradient the VCP sites are not considered a REC in connection with the Property.						
REC Discussion:	Based on the details provided above, a REC is not suspected in connection with the Property.						
VEC Discussion:	Based on the available data, a VEC is not suspected.						

State/Tribal BROWNFIELD SITES				**# of sites:**	11	**Search Distance:**	½-mile
Notable Listing:	515 West 18th Street						
Distance in feet:	575	**Direction:**	W	**Gradient:**	Down		
Data Discussion:	Given the distance and gradient, the Brownfields listings are not considered a REC in connection with the Property.						
REC Discussion:	Based on the details provided above, a REC is not suspected in connection with the Property.						
VEC Discussion:	Based on the available data, a VEC is not suspected.						

UNMAPPED/ORPHAN LIST SITES	
	Hillmann has also reviewed a list of unmapped sites (a.k.a. "Orphan List" sites) indicated by the database report. Unmapped sites that were identified as falling within an applicable specific search distance or warranting discussion have either been discussed in the preceding tables or are detailed below:

Notable Listings:	None

Additional Environmental Record Sources

Requests have been submitted to local, municipal and state agencies for pertinent records pertaining to the Subject Property, particularly with regard to potential environmental concerns such as petroleum storage tanks, storage and usage of hazardous substances and petroleum products, and/or known or suspected environmental contamination. Where applicable, internet research of government environmental regulatory databases was also conducted, as well as a general cursory internet search of the Subject Property address, for information indicative of a REC. The following table summarizes the findings of the research:

Source	Type of Request	Outcome
NYCFD-Public Records Unit / Tank Section	FOI request	No response was received prior to report issuance.
NYS DEC	FOI request	A response was received stating that no records were found.
NYCDEP	FOI request	No response was received prior to report issuance.
NY DOB	Online search	Records corroborating historic filling station within the Property identified.
USEPA	Online search	No records indicative of a REC identified.
Internet	Online Search	No records indicative of a REC identified.

Pertinent records referenced in the above table have been included in Appendix F.

4.2 Historical Research

Historical records have been compiled and analyzed for historical property information and developing a history of previous uses of the Subject Property, adjoining properties and surrounding area. These records were reviewed for the purpose of identifying the likelihood of past uses having led to RECs in connection with the Subject Property.

The historical record sources listed below have been sought with the objective to document past uses of the Subject Property from the present back to the Subject Property's first developed use, or back to 1940, whichever is earlier. The term "developed use" includes agricultural use, placement of fill dirt and other uses that do not involve structures. Hillmann has sought to review historical records in minimum intervals of five years.

Fire Insurance Maps

A Certified Sanborn Map Report was obtained from EDR for a review of published historic fire insurance maps for the Subject Property and surrounding area. The following is a summary of site uses and notable details depicted by the available maps:

430 West 17th Street (Block 714, Lot 31)

Year(s)	Prop/Adj	Depicted Use(s)	Notable Details
1895, 1904, 1919, 1921, 1928	**Property:**	Multiple multi-story dwellings and commercial occupants including of potential environmental concern.	Vinegar Factory (1895); Chinese Laundry (101 9th Avenue – 1904); 165-car garage with auto repair operation in basement and 1,500-gallon gasoline UST in basement (415-425 West 16th Street – 1921-1950); Iron works (1921).
	Adjoining:	National Biscuit Company factory/warehouse noted to the south.	
1950	**Property:**	Dwellings have been cleared and replaced with a filling station and a taxi garage.	Taxi garage and filling station each with multiple gasoline tanks along West 16th Street, 9th Avenue and West 17th Street (1950).
	Adjoining:	Warehouse to the south, residential and commercial in other directions.	Auto repair and freight terminal to the west.
1969, 1975, 1979, 1980, 1983, 1985, 1987, 1988, 1991-1996, 2001-2005	**Property:**	Four Property buildings corresponding to the present configuration are depicted.	
	Adjoining:	Manhattan Industrial Center to the south, residential and commercial in other directions.	

427 West 17th Street (Block 715, Lot 10)

Year(s)	Prop/Adj	Depicted Use(s)	Notable Details
1895, 1904, 1919, 1921, 1928	**Property:**	Multiple multi-story dwellings and commercial occupants including of potential environmental concern.	Chinese Laundry (119 9th Avenue in 1904)
	Adjoining:	Consolidated Gas Company Gas Holders to the west; residential and commercial in other directions. In	Gas holding silos depicted to the west (1895-1904);
1950	**Property:**	An auto service and filling station with three gasoline tanks with multiple gasoline tanks is noted at 109 9th Avenue. Auto painting and repair are noted along West 17th. A cheese dealer, lumber yard and waste paper are depicted in addition to multiple mixed-use store/dwelling buildings.	Auto painting, repair and filling with multiple gasoline tanks.
	Adjoining:	Garage with gasoline tanks noted to the adjacent west.	Gasoline tanks depicted to the adjacent west.
1969, 1975, 1979, 1980, 1983, 1985, 1987, 1988, 1991-1996, 2001-2005	**Property:**	Three Property buildings corresponding to the present configuration are depicted. The apartment complex is listed as "Fulton Houses Apartments" with 944 units and parking.	
	Adjoining:	Beginning in 2002 the western adjacent building is listed as a Verizon site.	

401 West 18th Street (Block 716, Lot 17)

Year(s)	Prop/Adj	Depicted Use(s)	Notable Details
1895, 1904, 1919, 1921, 1928	**Property:**	Multiple multi-story dwellings and commercial occupants including a pharmacy and bakery.	
	Adjoining:	Residential/commercial buildings.	
1950	**Property:**	Motor freight terminal noted at 410-412 West 19th Street.	Motor freight terminal

Year(s)	Prop/Adj	Depicted Use(s)	Notable Details
	Adjoining:	Auto body shop noted to the adjacent west.	
1969, 1975, 1979, 1980, 1983, 1985, 1987, 1988, 1991-1996, 2001-2005	**Property:**	Three Property buildings corresponding to the present configuration are depicted.	
	Adjoining:	No significant changes noted.	

401 West 19th Street (Block 717, Lot 19)

Year(s)	Prop/Adj	Depicted Use(s)	Notable Details
1895, 1904, 1919, 1921, 1928	**Property:**	Multiple multi-story dwellings and a convent.	
	Adjoining:	Residential/commercial buildings.	
1950	**Property:**	The dwellings are not listed as mixed-use (store/dwelling) buildings.	
	Adjoining:	Primarily mixed-use buildings.	
1969, 1975, 1979, 1980, 1983, 1985, 1987, 1988, 1991-1996, 2001-2005	**Property:**	One Property building corresponding to the present configuration is depicted.	
	Adjoining:	No significant changes noted.	

A copy of the Certified Sanborn Map Report is attached in Appendix D.

City Directories

An EDR City Directory Abstract report was reviewed for data of former occupants of the Subject Property's street address. The following is a generalized summary of the findings of city directory research for past occupants of the Subject Property.

Property	
Use(s) / Occupant(s):	**Years**
Residential and mixed-use listings	1920-2017
403 West 18th Street – Cleveland Automotive Prod Co, Unit Auto Parts Co	1950
424 West 18th Street – Drayer scrap metal, Dry Lee Plastic Co Inc.	1956-1958

The EDR City Directory Abstract report was also reviewed for listings of historic occupants of the adjoining properties. The following is a general summary of listings of historic adjoining property occupants:

Adjoining Properties	
Use and/or Occupant(s)	**Years**
Mix of residential and commercial occupants.	1920-2017

A copy of the EDR City Directory report is attached in Appendix D.

Historical Topographic Maps

Due to the availability of alternate historic sources, as well as the likelihood that this source would not provide any significant data, historical aerial photographs were not researched for this assessment.

Historical Aerial Photographs

Due to the availability of alternate historic sources, as well as the likelihood that this source would not provide any significant data, historical aerial photographs were not researched for this assessment.

EDR High-Risk Historical Records

The EDR Radius Map™ report, which is discussed in greater detail in Section 4.1 and attached in Appendix E, provided a search of proprietary databases of potential historical high-risk uses at or in the vicinity of the Subject Property. These databases include EDR Historic Cleaners – a database of property addresses with records of historical occupancy by suspected cleaners businesses; EDR Historic Auto – a database of property addresses with records of historical occupancy by potential automotive gas/filling stations and repair facilities; and EDR MGP- a database of sites historically occupied by manufactured gas plants and related facilities.

EDR Database	On-site Listings:	Adjoining/Off-Site Listings
Historic Cleaners: (on-site/adjoining only)	None	322 Franklin Street, Indigo Cleaners and Dyers, listed for the years 1957 to 1972
Historic Auto: (on-site/adjoining only)	None	None
MGP: (1-mile distance)	None	ConEdison-West 58th St. Station MGP 11th Ave Between W. 58th – W. 59th Sts, was incorrectly plotted by EDR, and is actually located over a mile to the west-northwest.

Petroleum/Natural Gas Well Review

The historical record sources were reviewed for records of historic petroleum and/or natural gas wells at the Subject Property. No record of any historical petroleum/natural gas wells at or adjoining the Property was identified.

Additional Historical Data

Where applicable, the following additional pertinent historical data was obtained:

Interviews/Anecdotal:	No additional pertinent historical data was obtained.
Local Gov't Records:	The following additional pertinent historical data was obtained: NYC DOB records corroborate Sanborn depictions of gasoline tanks/fillings stations historically within the Property.

Prior Env. Reports: (Section 3.2)	Not applicable; no prior reports were provided.
Site Observations:	Indications of historic uses of the Property or adjoining properties were not observed during the site reconnaissance.
Other Sources:	No additional pertinent historical data was obtained.

Summary of Identified Historic Uses

The following table presents a summary of the types and approximate date ranges of identified prior uses of the Subject Property:

Property	
Date Range	**Use**
Late 1800's to 1963	Residential and auto repair / fillings station among other commercial uses.
1963-Present	Fulton apartment buildings

The following table presents a summary of the types of identified prior uses of the adjoining properties:

Adjoining Properties	
Date Range	**Use**
Unk to Present	Residential, commercial and auto repair, industrial warehouses (south), Chelsea Market (south)

Historical Records Data Failure

The ASTM E1527-21 standard defines data failure as failure to achieve the historical research objective even after reviewing the standard historical sources that are reasonably ascertainable and likely to be useful. The objective is to identify all obvious uses of the property from the present, back to the property's first developed use, or back to 1940, whichever is earlier. Furthermore, records of historic use/conditions were sought in intervals no less than approximately five years, unless the property conditions appear unchanged over a longer interval. In encountered, data failure and its significance as a data gap is discussed below:

Objective	Met?	Detail	Significant?
First developed use/date determined?	Yes	The first developed use of the Property was for dwellings in the late 1800's.	No
Record sources at 5-year intervals back to 1940 or first developed use?	Yes	Historical record gaps exceeding five years were encountered. However, significant site-use changes or undiscovered site uses appear unlikely to have occurred during the record gaps.	No
All obvious prior uses identified?	Yes	See Summary of Identified Past Uses of this section.	No

Please refer to Section 2.3 for additional discussion of data gaps and their significance to the findings of the assessment.

Historic Uses REC Discussion

The review of historical records indicated evidence of the following potential RECs in connection with the Property:

Multiple historic uses of potential environmental concern, based on a review of Sanborn Fire Insurance Maps, occurred at the Property prior to the construction of the present Property buildings in the 1960's as follows:

- Vinegar Factory at 424-426 West 17th Street (off the east side of the present Property Building 4) in 1895;
- "Chinese Laundry" at 101 and 119 9th Avenue (near present Property Buildings 2 and 7) in 1904;
- 165-car garage with auto-repair operations in the basement and a 1,500-gallon gasoline buried tank (in the vicinity of the present asphalt surface parking south of Building 2) and a 15-car private garage with a buried gasoline tank (capacity indecipherable) at 409 West 17th Avenue (off the west side of the present Property Building 7), and iron works 434-436 West 17th Avenue and 414 19th Avenue in 1921;
- Filling station (gas station), taxi garage and auto repair with multiple gasoline tanks depicted along ninth avenue between West 16th and West 17th Avenue and along West 16th and West 17th Avenue (see Appendix A figure), and an additional auto filling/service station with multiple gasoline tanks depicted at the northwest corner of 9th Avenue and West 17th Street (near the southern edge of the present Building 7) and auto painting (431-433 West 17th) and repair (443-445 West 17th), a motor freight terminal (410-412 West 19th) in 1950.

The aforementioned historic uses including a factory, laundry, iron works, motor freight station, auto filling/service stations with multiple gasoline tanks is considered a REC.

5.0 INTERVIEWS

5.1 Interviews with Owners, Operators and Occupants

Current Owner / Key Site Operator

Property Owner	**Contact Name**	**Affiliation**	**Interview Type**
New York City Housing Authority (NYCHA) representative	Patrick Chan	Property Manager with NYCHA	In person
Interview Date:	April 19, 2022		
Interview Outcome/Findings:			
An interview for information pertinent to the assessment was conducted in person at the time of the site visit. The following pertinent information was indicated: The Property was reportedly always supplied with high pressure steam and no heating oil is or was present to Mr. Chan's knowledge.			

Prior Owners/Operators/Occupants

Name	**Company/Title**	**Yrs @ Site**	**Interview Type**
Interview Date:			
Interview Outcome/Findings:			
No prior owners, operators or occupants were interviewed.			

Neighboring Property Owner/Occupants

Name	**Company/Title**	**Yrs at site**	**Interview Type**
Interview Date:			
Interview Outcome/Findings:			
The Property was not an abandoned property with evidence of unauthorized uses or uncontrolled access; therefore, interviews with adjoining or nearby property owners or occupants were not conducted.			

5.2 Interviews with State and/or Local Government Officials

State and/or local governmental officials have been interviewed to obtain information of potential RECs in connection with the Subject Property. Many government agencies and their officials require submittal of written request for records in order to respond. The details in Section 4.1 list the various state and local government agencies contacted as part of this assessment, and the outcome of each inquiry. In addition, the details of regulatory database research in Section 4.1 may

have included detail of interviews with officials pertinent to government records review and identification of RECs.

Additional interview of government officials not previously detailed in Sections 4.1 are discussed below, if applicable.

Name	**Agency Name/Title**	**Interview Type**
Interview Outcome/Findings:		
No additional local/state government officials were interviewed.		

6.0 SITE RECONNAISSANCE

6.1 Methodology and Limiting Conditions

A site reconnaissance was conducted to collect information and make observations to help identify RECs in connection with the Subject Property. This included visual and/or physical observations of the Subject Property and its structures, adjoining properties as viewed from the Subject Property boundaries and the surrounding area based on visual observations from adjoining public thoroughfares and accessed Subject Property structures. Subject property building exteriors were observed at ground level, unless otherwise indicated. Where applicable, building interiors were accessed and observed to the extent they were made safely accessible with the cooperation of the site escort.

Site Inspection Personnel:	Mr. Etan Hindin and Mr. Dominick Aponte
Property Escort/Company:	Rico / Property Caretaker
Inspection Date:	April 19, 2022
Weather Conditions:	Overcast 45 degrees Fahrenheit

Significant Inaccessible Areas

Due to the pandemic occupied units were inaccessible. The inability to access these units is not considered a Significant Data Gap.

Significant Limiting Site Conditions

No significant limiting site conditions were noted at the time of the site reconnaissance.

6.2 General Site Setting

Site and Vicinity Characteristics

Abutting Roadways:	9th Avenue to the east; West 16th Street to the south; West 17th, 18th and 19th divide the Property parcels.
Current Property Use:	Multifamily residential
Evidence of Past Property Uses:	None observed.
Evidence of Past Adjoining Property Uses:	None observed.
Surrounding Area Uses:	Commercial, residential

Current Adjoining Property Uses

Dir	Street Address	Description
N	Multiple West 20th addresses	Primarily residential
W	Multiple West 16th-20th addresses	Residential and commercial
E	Multiple 9th Avenue addresses	Commercial and residential
S	75 9th Avenue	Commercial

No visual observations indicative of a potential environmental concern were noted on the adjoining properties.

Topographic Characteristics

Terrain:	Flat to gently sloping
Direction of Downward Slope:	Towards the northwest
On-site Water Bodies:	None observed
Other Significant Features:	None observed

General Description of Structures and Improvements

Buildings:	Twelve
Approx. Building Size:	974-units (combined)
Approx. Year Built:	1963-1965
Number of Stories:	B12 – 1; B2, B6, B9 – 25-story plus basement; B1, B3 6-story plus basement; B4, B5, B7, B8, B10, B11 – 6-story
Basement/Subgrade Levels:	See above
Exterior Ground Cover:	Asphalt, cement and landscaped areas,
Ancillary Structures:	B12 as noted above
Sources of Heating & Cooling:	High pressure steam supplied by Con Edison for heat and tenant-owned optional electric window units for cooling.
Potable Water/Sewage Disposal:	Municipal utility connections

6.3 Site Features and Conditions

Storage/Usage of Hazardous Substances and Petroleum Products

The following approximate number of containers, and general description of their contents, capacity, container types and storage conditions, were observed to be stored and/or used at the Subject Property:

Occupant	Substance	Qty/Container Type	Storage Conditions
NYCHA	Maintenance and cleaning materials (including paint)	1-30-gallon	All stored indoors on intact concrete. No storage concerns noted. Paint storage within western side of B4.

Bulk Petroleum/Hazardous Material Storage Tanks

The following storage tanks for bulk petroleum or hazardous material storage were identified or reported to be present; or are suspected to be present based on visual observations:

AST/UST	Product	Capacity	Construction	Year Installed	Status	Location/Notes
None observed						

One UST noted to have been removed from the Property, specifically, 401-411 West 18th Street (Building 8) is listed on the UST database for a 1,500-gallon UST removed on June 5, 2017.

While no visual evidence of a UST was noted, considering the history of development, the potential presence of abandoned USTs and/or associated buried piping at the Subject Property cannot be ruled out.

Strong, Pungent or Noxious Odors and their Sources

No strong, pungent or noxious odors were noted at the Subject Property.

Standing Surface Water/Pools & Sumps

No standing water, pools or sumps containing liquids likely to be hazardous substances or petroleum products were noted.

Drums, Totes and Intermediate Bulk Containers

No hazardous substance or petroleum product drums were noted.

Unidentified Substance Containers

No unidentified substance containers suspected of containing hazardous substance or petroleum product were noted.

PCBs in Oil Filled Electrical/Hydraulic Equipment

No oil-filled electrical or hydraulic equipment was identified at the Subject Property.

It is noted that identification of PCB containing fluorescent light ballasts, caulk, paint, or other materials located inside and are part of the building or structure is outside of the scope of the ASTM

E1527-21 standard and this assessment.

Stains or Corrosion on Floors, Walls or Ceilings

No stains or corrosion of floors, walls or ceilings, excluding any staining from water, were noted.

Drains and Sumps

Floor drains and a basement sump designed for the purpose of managing sanitary sewage were noted. No conditions indicative of a REC were observed.

Pits/Ponds/Lagoons

No pits, ponds or lagoons were identified in connection with waste treatment or disposal.

Stained Soil, Pavement/Stressed Vegetation

No stained soil, pavement or stressed vegetation was observed.

On-Site Solid Waste Disposal/Fill Material

No evidence of on-site disposal of trash, construction debris, demolition debris or other solid waste was observed.

Based on the history of previous site development, historical fill material may be present in the subsurface at areas of previous site grading or building structures.

Waste Water

Sanitary sewage generated at the Subject Property is discharged via a connection to the local public sewer system.

Storm water runoff at the Subject Property is discharged via roof drains into the municipal sewer system.

Septic Systems/Cesspools

No septic systems/cesspools identified.

Wells

The following wells were identified at the Subject Property:

Two (2) groundwater monitoring wells were observed within the Property north of B12 (two-bay Property garage) and northwest of B4 on the south side of West 18th and West 17th Streets respectively. The trigger for the installation of these wells and their use for sampling/monitoring, if any, was unknown by the site escort/contact.

Railroad Spurs

No railroad spurs were identified on the Subject Property.

7.0 BUSINESS ENVIRONMENTAL RISKS

In accordance with the contract agreement for this assessment, Hillmann has performed cursory reviews of several potential Business Environmental Risks (also known as "Non-Scope Considerations"). The ASTM E1527-21 standard defines the term business environmental risk (BER) as, *"a risk which can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of a parcel of commercial real estate, not necessarily limited to those environmental issues required to be investigated in this practice."*

7.1 Asbestos-Containing Material (ACM)

The contracted scope of work included a cursory visual screening of the accessed portions of buildings at the Subject Property built prior to 1990 for suspect asbestos containing materials (ACM). The information provided in this section, where applicable, is limited to identification of potential suspect materials in the readily accessible and observed areas of the building, and their general condition. This is not intended to be a comprehensive survey for the presence of ACM, and no testing has been conducted.

Given the 1963-1965 years of construction, asbestos containing materials are suspected unless ruled out by laboratory analysis.

Suspected ACM noted within the accessed building areas included floor tile, wall-board, spray-of insulation and roofing materials.

7.2 Lead-Based Paint

The contracted scope of work included a cursory visual screening of the condition of painted surfaces in the accessed areas of residential buildings/units built prior to 1980. This is not intended to constitute a comprehensive survey for LBP or potential lead hazards, and no testing has been conducted.

Given the 1963-1965 years of construction, lead-paint is suspected unless ruled out by field survey or laboratory analysis.

Lead sampling was reportedly being performed due to the December 21, 2021 modification to the legal lead-based paint standard to 0.5 mg/cm^2 (Local Law 66 and rules adopted by the Department of Housing Preservation and Development [HPD]) The results of the survey have been requested by Hillmann.

7.3 Radon

Data compiled by the USEPA, as summarized by the regulatory database report, indicated that the Subject Property is located in an area classified as Zone 3 or 'low risk' area for radon. Radon testing was not included in the scope of this assessment.

7.4 Mold/Microbial Damage

The contracted scope of work included a cursory visual screening of the accessed areas of the building for evidence of significant damage to building materials and finishes as result of moisture intrusion and/or mold/microbial growth.

The following evidence of significant moisture intrusion or mold/microbial growth was noted:

The basement of Building 1 was observed to have standing water on the concrete surface with some discoloration. Intermittent pipe and roof leaks were reportedly common given the age of the building. Mold abatement, primarily removing water damaged wall-board is reportedly performed by NYCHA staff as needed.

7.5 NWI Mapped Wetlands

The National Wetlands Inventory online Wetland Mapper (https://www.fws.gov/wetlands/data/mapper.html) was reviewed for indications of jurisdictional wetlands at or immediately adjoining the Subject Property. The scope of work for this assessment excluded a visual determination of regulated wetlands at the Subject Property. It is emphasized that, regardless of the data reviewed via the NWI Wetlands Mapper, a field delineation of regulated wetlands by a qualified professional would be warranted to determine the presence or absence of regulated wetlands at the Subject Property.

The review did not indicate regulated wetland areas on the Property.

7.6 Lead in Drinking Water

The scope of work for this assessment included a review of the potential for elevated levels of lead in drinking water by determining the source of the drinking water supply and a review of available compliance or testing data.

Potable water service at the Property is provided by a utility connection with the City of New York. A recently published water quality report from the utility indicated compliance with USEPA water quality standards for lead in drinking water. A copy of the report has been attached in Appendix F. Note – no site-specific lead-in-water sampling was performed within the context of the Phase I.

8.0 REFERENCES

ASTM E1527-21-Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process; ASTM International, 2021

ASTM E12600-15-Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transaction, ASTM International, 2015

EDR Radius Map Report, and historical record reports discussed in Section 4, Environmental Data Resources

Methodology for Identifying the Area of Concern Around a Property Potentially Impacted by Vapor Migration from Nearby Contaminated Sources; A. Buonicore, 2011

9.0 APPENDICES

Appendix A	Site Diagram / Vicinity Map
Appendix B	Site Photographs
Appendix C	Questionnaires / User Provided Information
Appendix D	Historical Records Documentation
Appendix E	Regulatory Records Documentation
Appendix F	Other Documents / Lab Results
Appendix G	Project Personnel Qualifications

APPENDIX A

MAPS / DIAGRAMS



HILLMANN CONSULTING

Figure 1: Site Vicinity Map

401 West 19th Street, 401 West 18th Street, 427 and 430 West 17th Street
New York, New York

N

Fulton	NYCHA Property	PROJECT No.: Z34898



Key: Monitoring Well: ▲ | B1 – B11: Buildings one through eleven (residential apartment buildings)
Compactor Area: ▭ | B12: two-bay garage

HILLMANN CONSULTING

Figure 2: Site Diagram

401 West 19th Street, 401 West 18th Street, 427 and 430 West 17th Street
New York, New York

N

Fulton | NYCHA Property | PROJECT No.: Z34898



Key| Gasoline Tanks:
Filling Station:
Auto Repair:
Motor Freight Terminal:

HILLMANN CONSULTING

Figure 3: Historic Features

401 West 19th Street, 401 West 18th Street,
427 and 430 West 17th Street
New York, New York

N

Fulton NYCHA Property

PROJECT No.: Z34898

APPENDIX B

SITE PHOTOGRAPHS

PHOTO LOG
Fulton
New York, NY

View of Property high-rise building

View of Property low-rise building and ground level community center

Western adjacent commercial properties

Western adjacent commercial properties

Eastern adjacent mixed-use properties

Northern adjacent residential properties

Z34898

PHOTO LOG
Fulton
New York, NY

Commercial Properties adjacent to the South

High pressure steam heating piping


Sump

Electric meter


Trash compactor

Floor drain in compactor room

PHOTO LOG
Fulton
New York, NY

Storage room and maintenance area

2-bay garage (B12)

High pressure steam system

High pressure steam system


Play area south of B4

Paint storage room (B4)

PHOTO LOG
Fulton
New York, NY

Typical tenant unit

Waste management area

Monitoring well on West 17th Street

Monitoring well on West 17th Street (cont.)

Monitoring well West 18th Street

APPENDIX C

QUESTIONNAIRES/USER PROVIDED DOCUMENTATION

None Provided

APPENDIX D

HISTORICAL RECORDS DOCUMENTATION

Fulton

401w16th St, 400 W17th St, 420w18th St, 420w19thst

New York, NY 10011

Inquiry Number: 6920743.3

March 31, 2022

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

03/31/22

Site Name:

Fulton
401w16th St, 400 W17th St, 42
New York, NY 10011
EDR Inquiry # 6920743.3

Client Name:

Hillmann Environmental Co.
1600 Route 22 East
Union, NJ 07083
Contact: Joanne Bedkowski

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Hillmann Environmental Co. were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 7839-4FC5-B09A

PO # NA

Project Z34898

Maps Provided:

2005	1993	1979	1895
2004	1992	1975	
2003	1991	1969	
2002	1988	1950	
2001	1987	1928	
1996	1985	1921	
1995	1983	1919	
1994	1980	1904	

Sanborn® Library search results

Certification #: 7839-4FC5-B09A

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Hillmann Environmental Co. (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2022 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2005 Source Sheets


Volume 3, Sheet 37
2005-2006


Volume 3, Sheet 40
2005-2006


Volume 3, Sheet 41
2005-2006


Volume 3, Sheet 42
2005-2006

2004 Source Sheets


Volume 3, Sheet 37
2004


Volume 3, Sheet 41
2004


Volume 3, Sheet 42
2004

2003 Source Sheets


Volume 3, Sheet 37
2003


Volume 3, Sheet 40
2003


Volume 3, Sheet 41
2003


Volume 3, Sheet 42
2003

Volume 1S, Sheet xxxx
2003

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2002 Source Sheets



Volume 3, Sheet 37
2002



Volume 3, Sheet 41
2002



Volume 3, Sheet 42
2002

2001 Source Sheets



Volume 3, Sheet 37
2001



Volume 3, Sheet 40
2001



Volume 3, Sheet 41
2001



Volume 3, Sheet 42
2001

1996 Source Sheets



Volume 3, Sheet 42
1996



Volume 3, Sheet 37
1996



Volume 3, Sheet 41
1996

1995 Source Sheets



Volume 3, Sheet 37
1995



Volume 3, Sheet 41
1995



Volume 3, Sheet 42
1995

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1994 Source Sheets


Volume 3, Sheet 37
1994


Volume 3, Sheet 40
1994


Volume 3, Sheet 41
1994


Volume 3, Sheet 42
1994

1993 Source Sheets


Volume 3, Sheet 37
1993


Volume 3, Sheet 40
1993


Volume 3, Sheet 41
1993


Volume 3, Sheet 42
1993

1992 Source Sheets


Volume 3, Sheet 37
1992


Volume 3, Sheet 41
1992


Volume 3, Sheet 42
1992

1991 Source Sheets


Volume 3, Sheet 37
1991


Volume 3, Sheet 40
1991


Volume 3, Sheet 41
1991


Volume 3, Sheet 42
1991

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1988 Source Sheets


Volume 3, Sheet 37
1988


Volume 3, Sheet 40
1988


Volume 3, Sheet 41
1988


Volume 3, Sheet 42
1988

1987 Source Sheets


Volume 3, Sheet 37
1987


Volume 3, Sheet 41
1987


Volume 3, Sheet 42
1987


Volume 3, Sheet 40
1987

1985 Source Sheets


Volume 3, Sheet 37
1985


Volume 3, Sheet 40
1985


Volume 3, Sheet 41
1985


Volume 3, Sheet 42
1985

1983 Source Sheets


Volume 3, Sheet 37
1983


Volume 3, Sheet 40
1983


Volume 3, Sheet 41
1983


Volume 3, Sheet 42
1983

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1980 Source Sheets


Volume 3, Sheet 37
1980

Volume 1S, Sheet xxxx
1980

Volume 2, Sheet xxxx
1980


Volume 3, Sheet 41
1980

Volume 3, Sheet xxxx
1980


Volume 3, Sheet 42
1980

1979 Source Sheets


Volume 3, Sheet 41
1979


Volume 3, Sheet 42
1979


Volume 3, Sheet 36
1979


Volume 3, Sheet 37
1979


Volume 3, Sheet 40
1979

1975 Source Sheets


Volume 3, Sheet 37
1975


Volume 3, Sheet 40
1975


Volume 3, Sheet 41
1975


Volume 3, Sheet 42
1975

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1969 Source Sheets



Volume 3, Sheet 37
1969



Volume 3, Sheet 41
1969



Volume 3, Sheet 42
1969

1950 Source Sheets

Volume 1S, Sheet xxxx
1950

Volume 2, Sheet xxxx
1950

Volume 3, Sheet xxxx
1950



Volume 3, Sheet 37
1950



Volume 3, Sheet 40
1950



Volume 3, Sheet 41
1950



Volume 3, Sheet 42
1950

1928 Source Sheets



Volume Pier Maps, Sheet 3
1928

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1921 Source Sheets


Volume 3, Sheet 37
1921


Volume 3, Sheet 41
1921


Volume 3, Sheet 42
1921

1919 Source Sheets


Volume Atlas Maps, Sheet 18
1919

1904 Source Sheets


Volume 3, Sheet 37
1904


Volume 3, Sheet 40
1904


Volume 3, Sheet 41
1904


Volume 3, Sheet 42
1904

1895 Source Sheets

Volume 3, Sheet 63
1895


Volume 3, Sheet 63
1895


Volume 3, Sheet 66
1895


Volume 3, Sheet 66
1895



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Fulton
Address:	401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP:	New York, NY 10011
Client:	Hillmann Environmental Co.
EDR Inquiry:	6920743.3
Order Date:	03/31/2022
Certification #:	7839-4FC5-B09A
Copyright	2005

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 40
Volume 3, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Fulton
Address:	401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP:	New York, NY 10011
Client:	Hillmann Environmental Co.
EDR Inquiry:	6920743.3
Order Date:	03/31/2022
Certification #:	7839-4FC5-B09A
Copyright	2004

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: Fulton
Address: 401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP: New York, NY 10011
Client: Hillmann Environmental Co.
EDR Inquiry: 6920743.3
Order Date: 03/31/2022
Certification #: 7839-4FC5-B09A
Copyright: 2003

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1S, Sheet xxxx
Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 40
Volume 3, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #7839-4FC5-B09A

Site Name:	Fulton
Address:	401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP:	New York, NY 10011
Client:	Hillmann Environmental Co.
EDR Inquiry:	6920743.3
Order Date:	03/31/2022
Certification #:	7839-4FC5-B09A
Copyright	2002

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #7839-4FC5-B09A

Site Name:	Fulton
Address:	401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP:	New York, NY 10011
Client:	Hillmann Environmental Co.
EDR Inquiry:	6920743.3
Order Date:	03/31/2022
Certification #:	7839-4FC5-B09A
Copyright	2001

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 40
Volume 3, Sheet 37

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #7839-4FC5-B09A

Site Name: Fulton
Address: 401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP: New York, NY 10011
Client: Hillmann Environmental Co.
EDR Inquiry: 6920743.3
Order Date: 03/31/2022
Certification #: 7839-4FC5-B09A
Copyright: 1996

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 3, Sheet 41
Volume 3, Sheet 37
Volume 3, Sheet 42

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: Fulton
Address: 401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP: New York, NY 10011
Client: Hillmann Environmental Co.
EDR Inquiry: 6920743.3
Order Date: 03/31/2022
Certification #: 7839-4FC5-B09A
Copyright: 1995

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 37

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: Fulton
Address: 401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP: New York, NY 10011
Client: Hillmann Environmental Co.
EDR Inquiry: 6920743.3
Order Date: 03/31/2022
Certification #: 7839-4FC5-B09A
Copyright 1994

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 40
Volume 3, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #7839-4FC5-B09A

Site Name: Fulton
Address: 401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP: New York, NY 10011
Client: Hillmann Environmental Co.
EDR Inquiry: 6920743.3
Order Date: 03/31/2022
Certification #: 7839-4FC5-B09A
Copyright: 1993

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 40
Volume 3, Sheet 37

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: Fulton
Address: 401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP: New York, NY 10011
Client: Hillmann Environmental Co.
EDR Inquiry: 6920743.3
Order Date: 03/31/2022
Certification #: 7839-4FC5-B09A
Copyright 1992

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 37

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: Fulton
Address: 401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP: New York, NY 10011
Client: Hillmann Environmental Co.
EDR Inquiry: 6920743.3
Order Date: 03/31/2022
Certification #: 7839-4FC5-B09A
Copyright: 1991

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 40
Volume 3, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #7839-4FC5-B09A

Site Name:	Fulton
Address:	401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP:	New York, NY 10011
Client:	Hillmann Environmental Co.
EDR Inquiry:	6920743.3
Order Date:	03/31/2022
Certification #:	7839-4FC5-B09A
Copyright	1988

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 40
Volume 3, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: Fulton
Address: 401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP: New York, NY 10011
Client: Hillmann Environmental Co.
EDR Inquiry: 6920743.3
Order Date: 03/31/2022
Certification #: 7839-4FC5-B09A
Copyright 1987

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 3, Sheet 40
Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 37

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #7839-4FC5-B09A

Site Name:	Fulton
Address:	401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP:	New York, NY 10011
Client:	Hillmann Environmental Co.
EDR Inquiry:	6920743.3
Order Date:	03/31/2022
Certification #:	7839-4FC5-B09A
Copyright	1985

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 40
Volume 3, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Fulton
Address:	401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP:	New York, NY 10011
Client:	Hillmann Environmental Co.
EDR Inquiry:	6920743.3
Order Date:	03/31/2022
Certification #:	7839-4FC5-B09A
Copyright	1983

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 40
Volume 3, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Fulton
Address:	401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP:	New York, NY 10011
Client:	Hillmann Environmental Co.
EDR Inquiry:	6920743.3
Order Date:	03/31/2022
Certification #:	7839-4FC5-B09A
Copyright	1980

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 3, Sheet 42
Volume 3, Sheet xxxx
Volume 3, Sheet 41
Volume 2, Sheet xxxx
Volume 1S, Sheet xxxx
Volume 3, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Fulton
Address:	401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP:	New York, NY 10011
Client:	Hillmann Environmental Co.
EDR Inquiry:	6920743.3
Order Date:	03/31/2022
Certification #	7839-4FC5-B09A
Copyright	1979

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 3, Sheet 40
Volume 3, Sheet 37
Volume 3, Sheet 36
Volume 3, Sheet 42
Volume 3, Sheet 41

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Fulton
Address:	401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP:	New York, NY 10011
Client:	Hillmann Environmental Co.
EDR Inquiry:	6920743.3
Order Date:	03/31/2022
Certification #:	7839-4FC5-B09A
Copyright	1975

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 40
Volume 3, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Fulton
Address:	401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP:	New York, NY 10011
Client:	Hillmann Environmental Co.
EDR Inquiry:	6920743.3
Order Date:	03/31/2022
Certification #:	7839-4FC5-B09A
Copyright	1969

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: Fulton
Address: 401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP: New York, NY 10011
Client: Hillmann Environmental Co.
EDR Inquiry: 6920743.3
Order Date: 03/31/2022
Certification #: 7839-4FC5-B09A
Copyright: 1950

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 40
Volume 3, Sheet 37
Volume 3, Sheet xxxx
Volume 2, Sheet xxxx
Volume 1S, Sheet xxxx

0 Feet 150 300 600

N

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #7839-4FC5-B09A

Site Name: Fulton
Address: 401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP: New York, NY 10011
Client: Hillmann Environmental Co.
EDR Inquiry: 6920743.3
Order Date: 03/31/2022
Certification #: 7839-4FC5-B09A
Copyright: 1928

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume Pier Maps, Sheet 3

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #7839-4FC5-B09A

Site Name:	Fulton
Address:	401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP:	New York, NY 10011
Client:	Hillmann Environmental Co.
EDR Inquiry:	6920743.3
Order Date:	03/31/2022
Certification #	7839-4FC5-B09A
Copyright	1921

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 37

0 Feet 150 300 600

N

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #7839-4FC5-B09A



Site Name: Fulton
Address: 401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP: New York, NY 10011
Client: Hillmann Environmental Co.
EDR Inquiry: 6920743.3
Order Date: 03/31/2022
Certification #: 7839-4FC5-B09A
Copyright: 1919

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume Atlas Maps, Sheet 18

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Fulton
Address:	401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP:	New York, NY 10011
Client:	Hillmann Environmental Co.
EDR Inquiry:	6920743.3
Order Date:	03/31/2022
Certification #:	7839-4FC5-B09A
Copyright	1904

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 3, Sheet 42
Volume 3, Sheet 41
Volume 3, Sheet 40
Volume 3, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: Fulton
Address: 401w16th St, 400 W17th St, 420w18th St, 420w19
City, ST, ZIP: New York, NY 10011
Client: Hillmann Environmental Co.
EDR Inquiry: 6920743.3
Order Date: 03/31/2022
Certification #: 7839-4FC5-B09A
Copyright: 1895

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 3, Sheet 66
Volume 3, Sheet 66
Volume 3, Sheet 63
Volume 3, Sheet 63

0 Feet 150 300 600

N

Fulton
401w16th St, 400 W17th St, 420w18th St, 420w19thst
New York, NY 10011

Inquiry Number: 6920743.5
March 31, 2022

The EDR-City Directory Abstract

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at five year intervals.

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1920 through 2017. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 200 feet of the target property.

A summary of the information obtained is provided in the text of this report.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.

Data by
infoUSA®
Copyright©2008
All Rights Reserved

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Year	Source	TP	Adjoining	Text Abstract	Source Image
2017	Cole Information Services	-	X	X	-
2014	Cole Information Services	-	X	X	-
2009	Cole Information Services	-	X	X	-
2006	Hill-Donnelly Information Services	-	X	X	-
2004	Cole Information Services	-	X	X	-
2000	Cole Information Services	-	X	X	-
1999	Cole Information Services	-	X	X	-
1998	NYNEX Telephone	-	-	-	-
1996	NYNEX	-	-	-	-
1994	Cole Information Services	-	X	X	-

EXECUTIVE SUMMARY

Year	Source	TP	Adjoining	Text Abstract	Source Image
1993	NYNEX Telephone	-	-	-	-
1988	NYNEX Telephone	-	X	X	-
1983	New York Telephone	-	X	X	-
1978	New York Telephone	-	X	X	-
1973	New York Telephone	-	X	X	-
1968	New York Telephone	-	X	X	-
1963	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1958	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1956	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1950	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1947	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1942	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1938	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1934	R. L. Polk & Co.	-	X	X	-
	R. L. Polk & Co.	X	X	X	-
1931	Manhattan and Bronx Directory Publishing Company Residential Directory	-	X	X	-
	Manhattan and Bronx Directory Publishing Company Residential Directory	X	X	X	-
1927	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1923	R. L. Polk & Co.	-	X	X	-
1920	R. L. Polk & Co.	-	X	X	-
	R. L. Polk & Co.	X	X	X	-

FINDINGS

TARGET PROPERTY INFORMATION

ADDRESS

401w16th St, 400 W17th St, 420w18th St, 420w19thst
New York, NY 10011

FINDINGS DETAIL

Target Property research detail.

W 18 ST

420 W 18 ST

Year	Uses	Source
1963	ANKERS WINIFRED J	New York Telephone
1958	BRITTON JAS W	New York Telephone
	STEWART CHAS EJR LWYR	New York Telephone
1956	BRITTON JAS W	New York Telephone
1950	RYAN JOS P ASSN	New York Telephone
1947	RYAN JOS P ASSN	New York Telephone
1942	RYAN JOS P ASSN	New York Telephone
1938	HENNESSY JAS	New York Telephone
	RYAN JOS P ASSN	New York Telephone
1931	CONNORS JAS	Manhattan and Bronx Directory Publishing Company Residential Directory
	HENNESSEY MARY	Manhattan and Bronx Directory Publishing Company Residential Directory
	RYAN THOS J	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	LAWLESS MARY H R	New York Telephone
	RYAN JOS P ASSN	New York Telephone

W 18TH

420 W 18TH

Year	Uses	Source
1934	Ryan Jos P Assn Jas Snoll pres Jas T Hennessy treas	R. L. Polk & Co.
1931	Connors Jas	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

Year	Uses	Source
1931	Hennessey Mary	Manhattan and Bronx Directory Publishing Company Residential Directory
	Ryan Thos J	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Lawless Mary H r	New York Telephone
	Ryan Jos P Assn	New York Telephone
1920	Avellanet Adolph Avelianet Printing Co	R. L. Polk & Co.
	Avellanet Artemio Avelianet Printing Co	R. L. Polk & Co.
	Dall Thos H chauf	R. L. Polk & Co.
	Richardson Del Bondis A w riter	R. L. Polk & Co.

FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

E 18TH ST

411 E 18TH ST

Year	Uses	Source
1983	Rock N	New York Telephone

427 E 18TH ST

Year	Uses	Source
1983	Pabon D	New York Telephone

429 E 18TH ST

Year	Uses	Source
1983	Latnberti Antonio	New York Telephone

W 117 ST

431 W 117 ST

Year	Uses	Source
1963	COLUMBIA UNIV	New York Telephone
1947	COLUMBIA UNIV PRESS	New York Telephone
1942	COLLEGE ENTRANCE EXAMINATION BD	New York Telephone
1931	CAVANAUGH JOHN A	Manhattan and Bronx Directory Publishing Company Residential Directory
	CAVANAUGH FLORENCE	Manhattan and Bronx Directory Publishing Company Residential Directory

W 17 %

419 W 17 %

Year	Uses	Source
1988	SWEIDERK R W 17	NYNEX Telephone

FINDINGS

W 17 R

419 W 17 R

Year	Uses	Source
1988	PETERS CHARLOTTA	NYNEX Telephone

W 17 ST

412 W 17 ST

Year	Uses	Source
1988	ARANA ALBERT	NYNEX Telephone
	ARANA HENRY	NYNEX Telephone
	CARROLL A	NYNEX Telephone
	DONOHUE WILLIAM F	NYNEX Telephone
	FLYNN M	NYNEX Telephone
	PALACIOS T	NYNEX Telephone
	PATTERSON OZZIE	NYNEX Telephone
	PATTERSON OZZIE JR	NYNEX Telephone
	VELEZ C	NYNEX Telephone
1983	ARANA HENRY	New York Telephone
	CARROLL A	New York Telephone
	DIAZ TRINIDAD	New York Telephone
	DONOHUE WILLIAM F	New York Telephone
	FLYNN M	New York Telephone
	PALACIOS JOHN	New York Telephone
	PATTERSON OZZIE	New York Telephone
	SALDANA ANGEL	New York Telephone
	VELEZ C	New York Telephone
1978	ADAMES RAMON	New York Telephone
	ARANA HENRY	New York Telephone
	CARROLL A	New York Telephone
	DONOHUE WILLIAM F	New York Telephone
	FLYRN M	New York Telephone
	KING MICHL	New York Telephone
	PALACIOS TELMO G	New York Telephone

FINDINGS

Year	Uses	Source
1978	PATTERSON OZZIE	New York Telephone
	VELEZ C	New York Telephone
1973	ARANA HENRY	New York Telephone
	CARROLL ANGIE	New York Telephone
	DONOHUE W LIIA F	New York Telephone
	FERRERA FRANK JR	New York Telephone
	FLORES MOISES	New York Telephone
	KING MICHL	New York Telephone
	PATTERSON OZZIE	New York Telephone
	ROSADO S	New York Telephone
	VAUGHAN ARLEEN	New York Telephone
	VELEZ CARMEN	New York Telephone
1968	ARANA HENRY	New York Telephone
	CARROLL CHAS F	New York Telephone
	CLEARY F MRS	New York Telephone
	FABER JOHN	New York Telephone
	FERRERA FRANK JR	New York Telephone
	FLORES MOISES	New York Telephone
	KING MICHL	New York Telephone
	NORMILE JAS J	New York Telephone
	ROSADO SANTA MRS	New York Telephone
1950	GEHRECKE FRANK T	New York Telephone
1938	DUNNING LLOYD	New York Telephone

413 W 17 ST

Year	Uses	Source
1958	BRAZIL JAS F	New York Telephone
	CARR JOSEPHINE MRS	New York Telephone
	DE ENTREMONT MARIE	New York Telephone
	DELANEY NELLIE MRS	New York Telephone
	MCCANN MARY B	New York Telephone
	MCDONNELL HARRY A	New York Telephone
	MOORE MARGARET	New York Telephone

FINDINGS

Year	Uses	Source
1958	RIVERA FELIX M	New York Telephone
1956	BRAZIL JAS F	New York Telephone
	CARLISLE CATHERINE A MRS	New York Telephone
	CARR JOSEPHINE MRS	New York Telephone
	DE ENTREMONT MARIE	New York Telephone
	DELANEY NELLIE MRS	New York Telephone
	KESSLER CHAS EDW	New York Telephone
	MCCANN MARY B	New York Telephone
	MCDONNELL HARRY A	New York Telephone
	MOORE MARGARET	New York Telephone
1950	BRAZIL JAS F	New York Telephone
	CARR JOSEPHINE MRS	New York Telephone
	DELANEY NELLIE MRS	New York Telephone
	MC CANN MARY B	New York Telephone
	MCDONNELL HARRY A	New York Telephone
	MOORE MARGARET	New York Telephone
	TOBIN DOROTHY F MRS	New York Telephone
1947	BAYNE S F JR REV	New York Telephone
	CARLISLE DOROTHY F	New York Telephone
	CARR JOSEPHINE MRS	New York Telephone
	DELANEY HELEN MRS	New York Telephone
	KESSLER CHAS EDW	New York Telephone
	MOORE MARGARET	New York Telephone
1942	MOORE MARGARET	New York Telephone
1938	MOORE MARGARET	New York Telephone
1931	CAREY ANNIE	Manhattan and Bronx Directory Publishing Company Residential Directory
	CAREY EDW	Manhattan and Bronx Directory Publishing Company Residential Directory
	CAREY EDW R POLICE	Manhattan and Bronx Directory Publishing Company Residential Directory
	CAREY THOS	Manhattan and Bronx Directory Publishing Company Residential Directory
	CAREY THOS F FIREMAN	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

Year	Uses	Source
1931	CLIFFORD MARGT	Manhattan and Bronx Directory Publishing Company Residential Directory
	DELANCY HELEN	Manhattan and Bronx Directory Publishing Company Residential Directory
	DELANEY THOS	Manhattan and Bronx Directory Publishing Company Residential Directory
	DUNPHY JAS	Manhattan and Bronx Directory Publishing Company Residential Directory
	LYNCH ANNA	Manhattan and Bronx Directory Publishing Company Residential Directory
	LYNCH JOS	Manhattan and Bronx Directory Publishing Company Residential Directory
	MOORE ADELAIDE	Manhattan and Bronx Directory Publishing Company Residential Directory
	MOORE WM	Manhattan and Bronx Directory Publishing Company Residential Directory
	ROGERS ANNIE	Manhattan and Bronx Directory Publishing Company Residential Directory
	TYSON MICHL	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	CAREY JOHN E R	New York Telephone
	DELANEY THOS R	New York Telephone
	WALSH HELEN E R	New York Telephone

414 W 17 ST

Year	Uses	Source
1927	N D RAG CO	New York Telephone

415 W 17 ST

Year	Uses	Source
1968	FERGUSON MAE	New York Telephone
	PURTELL FRANCES	New York Telephone
1958	DELGADO NILDA	New York Telephone
	DOHERTY KENNETH	New York Telephone
	FENTON CALVIN A	New York Telephone
	MALONEY LORETTA	New York Telephone
	MCCARTHY JEREMIAH	New York Telephone
	TWOMEY CORNELUS	New York Telephone
1956	DOHERTY KENNETH	New York Telephone

FINDINGS

Year	Uses	Source
1956	FENTON CECILIA A	New York Telephone
	MALONEY J J	New York Telephone
	MCCARTHY JEREMIAH	New York Telephone
	RICCA THOS	New York Telephone
	TWOMEY CORNELIUS	New York Telephone
1950	DOHERTY KENNETH	New York Telephone
	FENTON JOHN	New York Telephone
	MALONEY J J B	New York Telephone
	MC CARTHY JERMIANH	New York Telephone
1947	FENTON WINIFRED C	New York Telephone
	MALONEY J J B	New York Telephone
	SHARKEY THERESA C	New York Telephone
1942	FENTON WINIFRED C	New York Telephone
1938	TUNNEY HELEN G	New York Telephone
1931	O CONNOR WM J ENG	Manhattan and Bronx Directory Publishing Company Residential Directory
	THOLE LAWRENCE	Manhattan and Bronx Directory Publishing Company Residential Directory
	AUSTIN CHRISTOPHER	Manhattan and Bronx Directory Publishing Company Residential Directory
	AUSTIN VIOLA	Manhattan and Bronx Directory Publishing Company Residential Directory
	CLARK FRANK	Manhattan and Bronx Directory Publishing Company Residential Directory
	CLARK JAS	Manhattan and Bronx Directory Publishing Company Residential Directory
	CLARKE THERESA	Manhattan and Bronx Directory Publishing Company Residential Directory
	KENNEDY ANNA	Manhattan and Bronx Directory Publishing Company Residential Directory
	KENNEDY EDNA	Manhattan and Bronx Directory Publishing Company Residential Directory
	KENNEDY JAS	Manhattan and Bronx Directory Publishing Company Residential Directory
	MCDONALD FRANCIS	Manhattan and Bronx Directory Publishing Company Residential Directory
	MOLLOY ALOYSIUS G SUPT	Manhattan and Bronx Directory Publishing Company Residential Directory
	MOLLOY ELEANOR	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

Year	Uses	Source
1931	MURPHY ANNA	Manhattan and Bronx Directory Publishing Company Residential Directory
	MURPHY NELLIE	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	AUSTIN FRANCES R	New York Telephone
	CLARK AGNES E MISS R	New York Telephone
	KENNEDY JOHN A	New York Telephone
	MCNAMARA WM J R	New York Telephone
	REGAN JAS P R	New York Telephone
	TOBIN J P R	New York Telephone

417 W 17 ST

Year	Uses	Source
1988	MENDEZ MIGUEL	NYNEX Telephone
1983	MENDEZ MIGUEL	New York Telephone
	MALONE BARBARA MRS	New York Telephone
1978	ROMAN CECILIO	New York Telephone
	ROGERS JULIA M	New York Telephone
	MENDEZ MIGUEL	New York Telephone
	MALONE BARBARA MRS	New York Telephone
	FRANZI A	New York Telephone
1973	TERRAS AGNES	New York Telephone
	ROMAN CECILIO	New York Telephone
	PRIETO-BOTIFOLL DOLORES	New York Telephone
	MENDEZ MIGUEL	New York Telephone
	MALONE BARBARA MRS	New York Telephone
	FORMAN JEROME MRS	New York Telephone
	FLEESAK GREGORY	New York Telephone
1968	TERRAS AGNES	New York Telephone
	PRIETO-BOTIFOLL DOLORES	New York Telephone
	MENDEZ MIGUEL	New York Telephone
	MALONE BARBARA MRS	New York Telephone
	HALM JOHN C	New York Telephone
	FORMAN JENNIE MRS	New York Telephone

FINDINGS

Year	Uses	Source
1968	DRISCOLL JOHN	New York Telephone
	FLEESAK GREGORY	New York Telephone

419 W 17 ST

Year	Uses	Source
1988	ACEVEDO TOMAS	NYNEX Telephone
	ACEVEDO WILSON	NYNEX Telephone
	ALVAREZ SANTOS	NYNEX Telephone
	AVELLANEDA SONNIA	NYNEX Telephone
	AYI AFON	NYNEX Telephone
	BARON EDWARD	NYNEX Telephone
	BELL MAE	NYNEX Telephone
	BENDER JOEL	NYNEX Telephone
	BOHAN J	NYNEX Telephone
	BOONE WANDA	NYNEX Telephone
	BRASSIL W C	NYNEX Telephone
	BROWN B	NYNEX Telephone
	BURNS M	NYNEX Telephone
	CALANDRINO JEAN	NYNEX Telephone
	CAMPOS CRISTINO	NYNEX Telephone
	CAREY THOS B	NYNEX Telephone
	CARROLL M	NYNEX Telephone
	CARVAHO ALVARO	NYNEX Telephone
	CHUNG K	NYNEX Telephone
	CISTERNAS CARLOS	NYNEX Telephone
	CLARK A G	NYNEX Telephone
	CORSO ELVIRA	NYNEX Telephone
	CORTEZ L	NYNEX Telephone
	CRAWFORD MARY T MRS	NYNEX Telephone
	CRUZ EVELISSE	NYNEX Telephone
	CRUZ FRANCISCO	NYNEX Telephone
	CUMMINGS BERNARD MRS	NYNEX Telephone
	CUSHING JONNE	NYNEX Telephone

FINDINGS

Year	*Uses*	*Source*
1988	DAY M	NYNEX Telephone
	DEILY B & J	NYNEX Telephone
	DE PERCIN AGIS J	NYNEX Telephone
	DE SHIELDS D	NYNEX Telephone
	DIXON T	NYNEX Telephone
	DONOGHUE RAYMOND J	NYNEX Telephone
	DWAN JOSEPH	NYNEX Telephone
	FENCOTT GLADYS	NYNEX Telephone
	FERAT DAVID	NYNEX Telephone
	GARCIA N MRS	NYNEX Telephone
	GARCIA ROBERT	NYNEX Telephone
	GILIBERTO ANDREW	NYNEX Telephone
	GINER B	NYNEX Telephone
	GONZALEZ GILBERT A	NYNEX Telephone
	GONZALEZ JUAN	NYNEX Telephone
	GORDON R MRS	NYNEX Telephone
	HADDOCK T	NYNEX Telephone
	HENNESSY WILLIAM	NYNEX Telephone
	HERENCIA LUCRECIA	NYNEX Telephone
	HO TEAM	NYNEX Telephone
	HORTON R C	NYNEX Telephone
	JASPER A	NYNEX Telephone
	JOHN DOROTHY A	NYNEX Telephone
	JONES JAMES F	NYNEX Telephone
	JURIN GEO	NYNEX Telephone
	KANUIKA M	NYNEX Telephone
	KELLY MARY	NYNEX Telephone
	KIES EDITH	NYNEX Telephone
	KRAFT L	NYNEX Telephone
	KUSEY EVELYN	NYNEX Telephone
	LADIN J	NYNEX Telephone
	LANGTON WILLIAM	NYNEX Telephone

FINDINGS

Year	*Uses*	*Source*
1988	LEE H	NYNEX Telephone
	LEWIS FRANK J	NYNEX Telephone
	LOUGHRAN ANASTASIA	NYNEX Telephone
	MANRA O	NYNEX Telephone
	MARRERO JULIANA	NYNEX Telephone
	MARTINEZ CHRIS	NYNEX Telephone
	MC BRIDE P	NYNEX Telephone
	MC BRIDE P	NYNEX Telephone
	MCCARTHY BEATRICE M	NYNEX Telephone
	MC MAHON CATHARINE MRS	NYNEX Telephone
	MIELE-CLEVELAND M	NYNEX Telephone
	MILLER LAWRENCE	NYNEX Telephone
	MOLINA TOMAS	NYNEX Telephone
	MONTES FRANCESCO	NYNEX Telephone
	MONTESDEOCA EDUVIGAS	NYNEX Telephone
	MORRIS SANDY	NYNEX Telephone
	MURRAY MAUREEN	NYNEX Telephone
	O HAGAN M	NYNEX Telephone
	PAGAN L	NYNEX Telephone
	PALMARINI S	NYNEX Telephone
	PALMARINI V	NYNEX Telephone
	PALMER V	NYNEX Telephone
	PANUTO JAMES	NYNEX Telephone
	PEREZ J L	NYNEX Telephone
	PETRIK PETER N	NYNEX Telephone
	PITEO J	NYNEX Telephone
	PITT ANNETTE MRS	NYNEX Telephone
	POERIO FRANK	NYNEX Telephone
	POLLOCK SUSAN MRS	NYNEX Telephone
	RICHTER MAURICE MRS	NYNEX Telephone
	RODE NODAR	NYNEX Telephone
	ROSE JANET	NYNEX Telephone

FINDINGS

Year	Uses	Source
1988	SDHULMAN SAML	NYNEX Telephone
	SCHWERDTMAN MARTIN	NYNEX Telephone
	SCOTT LILLIAN H MRS	NYNEX Telephone
	SHEA G	NYNEX Telephone
	SHEPHERD RICHARD J & LORETTA	NYNEX Telephone
	SMITH F	NYNEX Telephone
	SOTO C	NYNEX Telephone
	STOKES TERRY	NYNEX Telephone
	TERRAS A	NYNEX Telephone
	TOMINOVICH A	NYNEX Telephone
	TOOMEY H	NYNEX Telephone
	TUOHEY T	NYNEX Telephone
	VALIENTE OSWALD E	NYNEX Telephone
	VILLA LUCRECIA	NYNEX Telephone
	WALSH HAL	NYNEX Telephone
	WARD ALVIN	NYNEX Telephone
	WAX R S	NYNEX Telephone
	WEISS CHARLES	NYNEX Telephone
	WHITEHEAD D	NYNEX Telephone
	WILLIAMSON M	NYNEX Telephone
	ZAMORA VIRGIL	NYNEX Telephone
	ZELAYA ALFREDO E	NYNEX Telephone
1983	ACEVEDO TUMAS	New York Telephone
	ACEVEDO WILSON	New York Telephone
	ALVAREZ SANTOS	New York Telephone
	ANSELMO ELVIRA MRS	New York Telephone
	AYALA M	New York Telephone
	AYI ALON	New York Telephone
	BARON EDWARD	New York Telephone
	BAYOUT PIERRE	New York Telephone
	BELL CHAS A	New York Telephone
	BELL MAE	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1983	BENDER WILLIAM & JOEL	New York Telephone
	BOHAN J	New York Telephone
	BRASSIL W C	New York Telephone
	BRODSKY L	New York Telephone
	BROWN B	New York Telephone
	BURNS M	New York Telephone
	CALANDRINO JEAN	New York Telephone
	CAMPOS CRISTINO	New York Telephone
	CAREY THOS B	New York Telephone
	CARVALHO ALVARO	New York Telephone
	CHUNG K	New York Telephone
	CISTEMAS CARLOS	New York Telephone
	CORSO ELVIRA	New York Telephone
	CRAWFORD MARY T MRS	New York Telephone
	CRUZ EVELISSE	New York Telephone
	CRUZ FRANCISCO	New York Telephone
	CUMMINGS BERNARD MRS	New York Telephone
	DELANEY JOHN M	New York Telephone
	DEPERCIN AGIS J	New York Telephone
	DESHIELDS O	New York Telephone
	DETRES JUAN	New York Telephone
	DIXON T	New York Telephone
	DONOGHUE RAYMOND J	New York Telephone
	DWAN JOSEPH	New York Telephone
	FENCOTT GLADYS	New York Telephone
	FERAT DAVID	New York Telephone
	FERLA ALBINA	New York Telephone
	GARCIA N MRS	New York Telephone
	GILIBERTO ANDREW	New York Telephone
	GILL ABELINO	New York Telephone
	GINER B	New York Telephone
	GONZALEZ GILBERT A	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1983	GONZALEZ JUAN	New York Telephone
	GONZALEZ MODESTO	New York Telephone
	GORDON R MRS	New York Telephone
	HADDOCK T	New York Telephone
	HANIOTIS J	New York Telephone
	HAYES ROLAND A	New York Telephone
	HERENCIA LUCRECIA	New York Telephone
	HERNANDEZ I	New York Telephone
	HO TEAM	New York Telephone
	HOLMES M	New York Telephone
	HORTON R C	New York Telephone
	JAMESON TEPHAN J	New York Telephone
	JOHN DOROTHY A	New York Telephone
	JURIN GEO	New York Telephone
	KALOMERIS A	New York Telephone
	KANUIKA M	New York Telephone
	KARGER JELL	New York Telephone
	KIES EDITH	New York Telephone
	KLEINMAN HYMAN S	New York Telephone
	KORT MARIE J	New York Telephone
	KRAFT L	New York Telephone
	KUSEY EVELYN	New York Telephone
	LADIN J	New York Telephone
	LEE H	New York Telephone
	LEITNER D	New York Telephone
	LEWIS FRANK J	New York Telephone
	LOONEY D	New York Telephone
	MARRA O	New York Telephone
	MARRERO JULIANA	New York Telephone
	MATHURA JAGGERNAUT	New York Telephone
	MC BRIDE P	New York Telephone
	MC CALLUM M	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1983	MC CARTHY BEATRICE M	New York Telephone
	MCLEAN PETER	New York Telephone
	MCMAHON CATHARINE MRS	New York Telephone
	MENAKER F ENGE	New York Telephone
	MILLER LAWRENCE	New York Telephone
	MOLINA TOMAS	New York Telephone
	MONTESDEOCA EDUVIGES	New York Telephone
	NATOLI NINO	New York Telephone
	NEARY JOS T	New York Telephone
	OBRIEN B A	New York Telephone
	O HAGEN M	New York Telephone
	PAGANO JOHN	New York Telephone
	PALMARINI S	New York Telephone
	PALMER V	New York Telephone
	PANUTO JAMES	New York Telephone
	PEREZ J L	New York Telephone
	PETRIK PETER N	New York Telephone
	PITEO J	New York Telephone
	PITT ANNETTE MRS	New York Telephone
	POERIO FRANK	New York Telephone
	POLLOCK SUSAN MRS	New York Telephone
	REGENSBURGER DOROTHY	New York Telephone
	RICHTER MAURICE MRS	New York Telephone
	SANFRATELLO M	New York Telephone
	SCHULER JOSEPH	New York Telephone
	SCHULMAN SAML	New York Telephone
	SCOTT LILLIAN H MRS	New York Telephone
	SHEA G	New York Telephone
	SOLAR HENRY	New York Telephone
	STEPHENSON TYSON	New York Telephone
	SULSONA M	New York Telephone
	SWEIDERK R	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1983	SYNAN PATRICK	New York Telephone
	TERRAS A	New York Telephone
	TNOVICH A	New York Telephone
	TOOMEY H	New York Telephone
	TORRES ANGEL	New York Telephone
	TUCKER E	New York Telephone
	TUOHEY T	New York Telephone
	VADILLO R	New York Telephone
	VALIENTE OSWALD E	New York Telephone
	WAX R S	New York Telephone
	WEISS CHARLES	New York Telephone
	WILLIAMS ROBT MRS	New York Telephone
	WILLIAMSON M	New York Telephone
	ZAMORA VIRGIL	New York Telephone
	ZELAYA ALFREDO E	New York Telephone
1978	ACEVEDO TOMAS	New York Telephone
	ALFAYA ANTONIO	New York Telephone
	ALLEN ALEXANDRIA MRS	New York Telephone
	ALVAREZ SANTOS	New York Telephone
	ANSELMO ELVIRA MRS	New York Telephone
	AYALA M	New York Telephone
	AYI AFON	New York Telephone
	BARTH CHARLES	New York Telephone
	BELL CHRS A	New York Telephone
	BRANDELL F J	New York Telephone
	BRODSKY L	New York Telephone
	BROWN B	New York Telephone
	BUNBURY JOSEPH	New York Telephone
	BURNS M	New York Telephone
	CAMPOS CRISTINO	New York Telephone
	CAREY THOS B	New York Telephone
	CARVALHO ALVARO	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1978	CHUNG K	New York Telephone
	CIDONI VINCENT	New York Telephone
	CISTERNAS CARLOS	New York Telephone
	CLEARY CATHERINE	New York Telephone
	COMBS K W	New York Telephone
	CORRIN IRENE	New York Telephone
	CRAWFORD MARY T MRS	New York Telephone
	CRUZ FRANCISCO	New York Telephone
	CUMMINGS BERNARD MRS	New York Telephone
	CUTLER E	New York Telephone
	DELANEY JOHN M	New York Telephone
	DEMPSEY M A	New York Telephone
	DEPERCIN AGIS J	New York Telephone
	DESHIELDS O	New York Telephone
	DETRES JUAN	New York Telephone
	DIXON T	New York Telephone
	DONOGHUE RAYMOND J	New York Telephone
	DRAYTON RUTH	New York Telephone
	FENCOTT GLADYS	New York Telephone
	FERAT DAVID	New York Telephone
	FERLA ALBINA	New York Telephone
	FESTINGER NICHOLAS	New York Telephone
	FIGUEROA BOLORE	New York Telephone
	FLYNN MOLLY MRS	New York Telephone
	GARCIA N MRS	New York Telephone
	GAUHARON JOHN	New York Telephone
	GILDERSLEEVE CHARLES O	New York Telephone
	GILL ABELINO	New York Telephone
	GINER B	New York Telephone
	GINNETTY MARGARET	New York Telephone
	GOLDBECK ERIK H	New York Telephone
	GONZALEZ GILBERT A	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1978	GONZALEZ JUAN	New York Telephone
	GONZALEZ MODESTO	New York Telephone
	GORDON R MRS	New York Telephone
	HADDOCK T	New York Telephone
	HANCOCK RICHARD	New York Telephone
	HAYES L A	New York Telephone
	HO TEAM	New York Telephone
	HOLMES M	New York Telephone
	HORTON R C	New York Telephone
	HULLIHAN JOHN	New York Telephone
	JAMES GLENDORINE	New York Telephone
	JAMESON STEPHAN J	New York Telephone
	JOHN DOROTHY A	New York Telephone
	JURIN GEO	New York Telephone
	KALOMERIS A	New York Telephone
	KEEFE ANNE MRS	New York Telephone
	KIES EDITH	New York Telephone
	KIRBATSOS A	New York Telephone
	KOENIGSBERG T	New York Telephone
	KORT MARIE J	New York Telephone
	KOZERSKI CHESTER S	New York Telephone
	LACEDONIA VINCENT	New York Telephone
	LADIN J	New York Telephone
	LEE H	New York Telephone
	LEWIS FRANK J	New York Telephone
	LOONEY D	New York Telephone
	MANGAN P J	New York Telephone
	MARRA O	New York Telephone
	MARTI I	New York Telephone
	MARTI VIRGINIA	New York Telephone
	MARTINEZ CHRIS	New York Telephone
	MARTINEZ LUIS	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1978	MARTIS R	New York Telephone
	MC MAHON CATHARINE MRS	New York Telephone
	MILLER LAWRENCE	New York Telephone
	MOLINA TOMAS	New York Telephone
	MONTES DE OCA EDUVIGES	New York Telephone
	NATOLI NINO	New York Telephone
	NEARY JOS T	New York Telephone
	NIPAR MARGARET	New York Telephone
	O BRIEN B A	New York Telephone
	PALMARINI S	New York Telephone
	PANUTO JAMES	New York Telephone
	PEREZ J L	New York Telephone
	PITT ANNETTE MRS	New York Telephone
	PROPPER MARY	New York Telephone
	REGENSBURGER DOROTHY MRS	New York Telephone
	RICHTER MAURICE MRS	New York Telephone
	ROCHE A	New York Telephone
	ROSADO THAMA	New York Telephone
	RYAN WILLIAM H	New York Telephone
	SCHOENBERGER HARRY	New York Telephone
	SCOTT LILLIAN H MRS	New York Telephone
	SHEA G	New York Telephone
	SLAMA M	New York Telephone
	SOLAR HENRY	New York Telephone
	SULSONA M	New York Telephone
	SYNAN PATRICK	New York Telephone
	TALAMO FRED	New York Telephone
	TORRAS AGNES	New York Telephone
	TOMINOVICH A	New York Telephone
	TUCKER E	New York Telephone
	VADILLO R	New York Telephone
	VARTERIAN R	New York Telephone

FINDINGS

Year	Uses	Source
1978	VECSEY S MRS	New York Telephone
	WAX R S	New York Telephone
	WILLIAMS I	New York Telephone
	WILLIAMS ROBT MRS	New York Telephone
	ZAMORA VIRGIL	New York Telephone
	ZELAYA ALFREDO E	New York Telephone
1973	ALFAYA ANTONIO	New York Telephone
	ALLEN ALEXANDRIA MRS	New York Telephone
	ALVAREZ SANTOS	New York Telephone
	AMSBAUGH M	New York Telephone
	ANSELMO ELVIRA MRS	New York Telephone
	ATHANASIOU KOSTAS	New York Telephone
	AYALA L	New York Telephone
	AYI AFON	New York Telephone
	BARTH CHARLES	New York Telephone
	BELL CHAS A	New York Telephone
	BELL MAE	New York Telephone
	BRASSIT JAMES F MRS	New York Telephone
	BRODSKY LINA	New York Telephone
	BROWN B	New York Telephone
	BUNBURY JOS	New York Telephone
	BURNS M	New York Telephone
	CAREY THOS B	New York Telephone
	CARTAGENTA H	New York Telephone
	CARVALHO ALVARO	New York Telephone
	CHUNG KATHERINE	New York Telephone
	CIDONI VINCENT	New York Telephone
	CISTERNAS CARLOS	New York Telephone
	CLARKE M	New York Telephone
	CLEARY CATHTIERINE	New York Telephone
	CONCEPCION LINE	New York Telephone
	CORRIN IRENE	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1973	COSENTINO FRED	New York Telephone
	CRAWFORD MARY T MRS	New York Telephone
	CROWLEY JOHN T	New York Telephone
	CRUZ FRANCISCO	New York Telephone
	CUMMINGS BERNARD MRS	New York Telephone
	CUTLER E	New York Telephone
	DAVIS ELIZ MRS	New York Telephone
	DE AGOSTINI DORIA	New York Telephone
	DELANEY JOHN M	New York Telephone
	DELGADO MARIA	New York Telephone
	DEPERCIN AGIS J	New York Telephone
	DESHIELDS O	New York Telephone
	DETRES JUAN	New York Telephone
	DEVILIN ISABELL	New York Telephone
	DONOGHUE RAYMOND J	New York Telephone
	FENCO	New York Telephone
	FERAT DAVID	New York Telephone
	FERLA ALBINA	New York Telephone
	FESTINGER NICHOLAS	New York Telephone
	FLYNN JO	New York Telephone
	FLYNN MOLLY MRS	New York Telephone
	FRANZI A	New York Telephone
	FUSCI C M MISS RN	New York Telephone
	GARCIA N MRS	New York Telephone
	GARY THEA	New York Telephone
	GAUHTARON JOHN	New York Telephone
	GENTILE MARIE	New York Telephone
	GILDERSLEEVE CHARLES O	New York Telephone
	GILL ABELINO	New York Telephone
	GINER B	New York Telephone
	GINNETTY MARGARET	New York Telephone
	GONZALEZ GILBERT	New York Telephone

FINDINGS

Year	Uses	Source
1973	GONZALEZ JUAN	New York Telephone
	GORDON MRS	New York Telephone
	GRAZIDE ROBT	New York Telephone
	HAYES L A	New York Telephone
	HERALD L SRABIANI	New York Telephone
	HERENCIA DORIS	New York Telephone
	HORTON RUBY C MRS	New York Telephone
	JAMES GLENDORINE	New York Telephone
	JAMESON STEPNAN J	New York Telephone
	JOHN DOROTHY A	New York Telephone
	JOHNSON JOHN J	New York Telephone
	JOUEPH RUBY	New York Telephone
	JOSEPHSON SAML	New York Telephone
	JURIN GEO	New York Telephone
	KALOMERIS A	New York Telephone
	KEEFE ANNE MRS	New York Telephone
	KIES EDITH	New York Telephone
	KOENIGSBERG T	New York Telephone
	KORT MARIE J	New York Telephone
	LEE H	New York Telephone
	LESSER ABRAHAM	New York Telephone
	LOONEY O	New York Telephone
	MARRA O	New York Telephone
	MARTIN E	New York Telephone
	MARTINEZ C	New York Telephone
	MARTINEZ V	New York Telephone
	MCGINN JOHN	New York Telephone
	MC KEEVER FRANK	New York Telephone
	MCKERNAN AGNES H COLONEL	New York Telephone
	MCMAHON CATHARINE MRS	New York Telephone
	MCNAMARA MICHAEL	New York Telephone
	MILLER LAWRENCE	New York Telephone

FINDINGS

Year	Uses	Source
1973	MOLLOY ALICE J	New York Telephone
	MOLLOY CATHERINE	New York Telephone
	NATOLI NINO	New York Telephone
	NEARY JOS T	New York Telephone
	O BRIEN B A	New York Telephone
	O CONNELL JOHN	New York Telephone
	O LEARY M	New York Telephone
	PANUTO JAMES	New York Telephone
	PHILIP J	New York Telephone
	PITT ANNETTE MRS	New York Telephone
	POSITI JANET	New York Telephone
	PROPPER MARY	New York Telephone
	REGENSBURGER DOROTHY MRS	New York Telephone
	RICHTER MAURICE	New York Telephone
	ROCHE A	New York Telephone
	RONDINONE MICHL	New York Telephone
	SANTILER DELORES	New York Telephone
	SAROSY ALICE MRS	New York Telephone
	SCHOENBERGER HARRY	New York Telephone
	SCOTT GEORGE	New York Telephone
	SCOTT WM H	New York Telephone
	SHEA G	New York Telephone
	SHINGHIRTIS TASSOS P	New York Telephone
	SLAMA M	New York Telephone
	SMALLWOOD L MRS	New York Telephone
	SNYDER MARY MRS	New York Telephone
	SOLAR HENRY	New York Telephone
	SULLIVAN ELIZ	New York Telephone
	SULLIVAN MARY T MRS	New York Telephone
	SULSONA M	New York Telephone
	SYNAN E M	New York Telephone
	TALAMO FRED	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1973	TOMINOVICH A	New York Telephone
	VADILLO R	New York Telephone
	VARTERIAN R	New York Telephone
	VECSEY S MRS	New York Telephone
	VECSLER FANI	New York Telephone
	VLACIC AMELIA MRS	New York Telephone
	WEGGE E	New York Telephone
	WEIGEL H	New York Telephone
	WILLIAMS ROBT MRS	New York Telephone
	ZELAYA ALFREDO E	New York Telephone
1968	ALFAYA ANTONIO	New York Telephone
	ALLEN ALEXAILDRIA MIS	New York Telephone
	ALVARADO WILFREDO	New York Telephone
	ALVAREZ HOPE	New York Telephone
	ALVAREZ SANTOS	New York Telephone
	ANSELMO ELVIRA MRS	New York Telephone
	ATHANASIOU KOSTAS	New York Telephone
	BARRY PHILIP J	New York Telephone
	BELL CHAS A	New York Telephone
	BELL MAE	New York Telephone
	BRODSKY LINA	New York Telephone
	BROWN B	New York Telephone
	BULNES EMELINA	New York Telephone
	BUNBUERY JOS	New York Telephone
	BURNS M	New York Telephone
	CAREY THOS B	New York Telephone
	CARLAFTES JOHN G	New York Telephone
	CARRILLO JOSE MANUEL	New York Telephone
	CARVALHO ALVARO	New York Telephone
	CHANG AH LIE	New York Telephone
	CHERICO ROSE MARIE	New York Telephone
	CLARKE M	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1968	CLEARY CATHERINE	New York Telephone
	COLEMAN NELLIE MRS	New York Telephone
	CRAWFORD MARY T MRS	New York Telephone
	CROWLEY JOHN T	New York Telephone
	CUMMINGS BERNARD MRS	New York Telephone
	CUTLER EDITH MRS	New York Telephone
	DAVIS ELIZ MRS	New York Telephone
	DELANEY JOHN M	New York Telephone
	DELGADO MARIA	New York Telephone
	DE PERCIN AGIS J	New York Telephone
	DE SHIELDS O	New York Telephone
	DIXON THERESA MRS	New York Telephone
	DONNELLY MATTHEW	New York Telephone
	DONOGHUE RAYMOND J	New York Telephone
	EAST FLORIZELLE	New York Telephone
	ELRICH DAVID	New York Telephone
	FENCOTT GLADYS	New York Telephone
	FERAT DAVID	New York Telephone
	FESTINGER NCHOLAS	New York Telephone
	FIGUEROA BOLORE	New York Telephone
	FLYNN JO	New York Telephone
	FLYNN MOLLY MRS	New York Telephone
	FOSTER MAY MRS	New York Telephone
	FRANZI ANNA	New York Telephone
	FRASCATI LINA MRS	New York Telephone
	FRIEDRICH JOHANNA MRS	New York Telephone
	FUSRYA C M RN	New York Telephone
	GARCIA N MRS	New York Telephone
	GARY THEA	New York Telephone
	GENTILE MARIE	New York Telephone
	GILL ABELINO	New York Telephone
	GINNETTY MARGARET	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1968	GIVENS ALFRED	New York Telephone
	GIVENS L	New York Telephone
	GONZALEZ FRANCISCO	New York Telephone
	GONZALEZ GILBERT A	New York Telephone
	GONZALEZ JUAN	New York Telephone
	GONZALEZ MICHL	New York Telephone
	GORDON R MRS	New York Telephone
	GRAZIDE ROBT	New York Telephone
	HANCOCK L	New York Telephone
	HAUGHEY ANNA MRS	New York Telephone
	HAYES L A	New York Telephone
	HERALD L SRABIAN	New York Telephone
	HICKEY CHAS	New York Telephone
	HORTON RUBY C MRS	New York Telephone
	HUM PHILIP DUTTON	New York Telephone
	ILORI J A	New York Telephone
	JAMES GLENRDORINE	New York Telephone
	JOHN DOROTHY A	New York Telephone
	JOHNSON JOHN J	New York Telephone
	JOHNSON L	New York Telephone
	JOSEPHSON SAML	New York Telephone
	JURIN GEO	New York Telephone
	KALOMERIS ALICE MRS	New York Telephone
	KANE F	New York Telephone
	KELLNER MARY V	New York Telephone
	KIES EDITH	New York Telephone
	KILGORE ANNA	New York Telephone
	KIRSCHNER JENNIE MRS	New York Telephone
	KART MARIE J	New York Telephone
	LEE H	New York Telephone
	LESSER ABRAHAM	New York Telephone
	LOONEY D	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1968	LYNCH CAROLINE E MRS	New York Telephone
	MARMION M	New York Telephone
	MARRA RALPH	New York Telephone
	MARTIN ELLEN	New York Telephone
	MASSON JOHN	New York Telephone
	MC DONOUGH ETHEL MRS	New York Telephone
	MC KERNAN AGNES H COLONEL	New York Telephone
	MC MAHON CATHERINE MRS	New York Telephone
	MIHALE JOHN	New York Telephone
	MILIAN ZAVEN	New York Telephone
	MILLER LAWRENCE	New York Telephone
	MOLLOY ALICE J	New York Telephone
	MOLLOY CATHERINE	New York Telephone
	MORAN CLAUDIA	New York Telephone
	NATOLL NINO	New York Telephone
	NEARY JOS T	New York Telephone
	O BRIEN B A	New York Telephone
	O LEARY M	New York Telephone
	ORFANSE BILL	New York Telephone
	PANUTO JAMES	New York Telephone
	PELLETIER JOHN	New York Telephone
	PHILIP JENNIE	New York Telephone
	PROPPER MARY	New York Telephone
	QUINONES EPIFANIO	New York Telephone
	REGENSBURGER DOROTHY MRS	New York Telephone
	RIGELY JOS J	New York Telephone
	ROSARIO PEDRO	New York Telephone
	RYAN T J	New York Telephone
	SAMUEL S	New York Telephone
	SANDAY JOHN	New York Telephone
	SANTILER DELORES	New York Telephone
	SCHOENBERGER HARRY	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1968	SCOTT WM H	New York Telephone
	SEMAN BOBDAN	New York Telephone
	SERENSON RAYMOND P	New York Telephone
	SHINGHIRTIS TASSOS P	New York Telephone
	SMITH ROY	New York Telephone
	SNELL JAS	New York Telephone
	SNYDER MARY MRS	New York Telephone
	SOLAR HENRY	New York Telephone
	SOMERS F X	New York Telephone
	SULLIVAN ELIZ	New York Telephone
	SIVAN MARY T MRS	New York Telephone
	TIBBETTS RICHD	New York Telephone
	TOMINOVICH L A	New York Telephone
	VARTERIAN R	New York Telephone
	VECSEY S MRS	New York Telephone
	VLACIC AMELIA MRS	New York Telephone
	WESTCOTT JAS	New York Telephone
	WEYANT ANNA	New York Telephone
	WILLIAMS ROBT MRS	New York Telephone
1958	FERNANDEZ BALTASAR	New York Telephone
	GUERRERO MIRTHA	New York Telephone
	OJEDA ROSE	New York Telephone
1956	GUERRERO MIRTHA	New York Telephone
1950	EDWARDS DOROTHY	New York Telephone
1931	BRANDOFF JOHN	Manhattan and Bronx Directory Publishing Company Residential Directory
	GALLAGHER HUGH	Manhattan and Bronx Directory Publishing Company Residential Directory
	GALLAHER ELIZ	Manhattan and Bronx Directory Publishing Company Residential Directory
	MIRANDA NICH	Manhattan and Bronx Directory Publishing Company Residential Directory
	MONKS EDMOND	Manhattan and Bronx Directory Publishing Company Residential Directory
	O CONNOR THOS	Manhattan and Bronx Directory Publishing Company Residential Directory

Year	Uses	Source
1931	TOBIN ANNA	Manhattan and Bronx Directory Publishing Company Residential Directory
	TOBIN MICHL	Manhattan and Bronx Directory Publishing Company Residential Directory
	TOBIN MICHL J FIREMAN	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	BRANCH	New York Telephone

421 W 17 ST

Year	Uses	Source
1988	CASTANO DOLLY	NYNEX Telephone
	NUNEZ MARIA MRS	NYNEX Telephone
1983	CASTANO DOLLY	New York Telephone
1978	GONCALVES FRANSCISCO	New York Telephone
	NY CITY OF	New York Telephone
	NUNEZ MARIA MRS	New York Telephone
1973	NY CITY OF HEALTH SVCES ADMINISTRATION MENTAL RETARDATION OFC OF	New York Telephone
	NUNEZ MACIA MRS	New York Telephone
1968	DEAGOSTINI DORIA	New York Telephone
	CURRICULUM RESEARCH BUREAU OF	New York Telephone
	NUNEZ MARIA MRS	New York Telephone
	SAROSY ALICE MRS	New York Telephone
1958	BANKS EDITH MRS	New York Telephone
	CHIN CHANG	New York Telephone
	CLARK PATTY M	New York Telephone
	LUCAS VICTORIA	New York Telephone
	MARMOL HORTENSIA	New York Telephone
	MOLLEUR LARRY	New York Telephone
	O KEEFE MICHL	New York Telephone
	ROMAN MANUELA	New York Telephone
1956	BASTLANICH JOS	New York Telephone
	DUIGNAN MURIEL R	New York Telephone
	LABOY ROMAN	New York Telephone
	MARMOL HORTENSIA	New York Telephone

Year	Uses	Source
1956	O KEEFE MICHL	New York Telephone
	ROLDOS ZORRIDA MRS	New York Telephone
	ROMAN MANUELA	New York Telephone
1950	SHERBURNE FRANK B	New York Telephone
	DULGNAN MURIEL R	New York Telephone
	FLEMING C B	New York Telephone
	MALDONADO ROMANA	New York Telephone
1942	GEIS WM	New York Telephone
1931	CHITTY JAS E	Manhattan and Bronx Directory Publishing Company Residential Directory
	MALONEY MARY	Manhattan and Bronx Directory Publishing Company Residential Directory
	O KEEFE MICHL	Manhattan and Bronx Directory Publishing Company Residential Directory
	ROGERS WM	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	GIBBINS SADIE NURSE	New York Telephone

W 17TH

414 W 17TH

Year	Uses	Source
1934	N D Rag Co RTN Jos and John Nesi Argelo Derrico junk	R. L. Polk & Co.
1927	N D Rag Co	New York Telephone
1920	Wager Wm	R. L. Polk & Co.
	Glendenning Margt	R. L. Polk & Co.

415 W 17TH

Year	Uses	Source
1931	Austin Christopher	Manhattan and Bronx Directory Publishing Company Residential Directory
	Austin Viola	Manhattan and Bronx Directory Publishing Company Residential Directory
	Clark Frank	Manhattan and Bronx Directory Publishing Company Residential Directory
	Clark Jas	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

Year	*Uses*	*Source*
1931	Clarke Theresa	Manhattan and Bronx Directory Publishing Company Residential Directory
	Kennedy Anna	Manhattan and Bronx Directory Publishing Company Residential Directory
	Kennedy Edna	Manhattan and Bronx Directory Publishing Company Residential Directory
	Kennedy Jas	Manhattan and Bronx Directory Publishing Company Residential Directory
	Mc Donald Francis	Manhattan and Bronx Directory Publishing Company Residential Directory
	Molloy Aloysius G supt	Manhattan and Bronx Directory Publishing Company Residential Directory
	Molloy Eleanor	Manhattan and Bronx Directory Publishing Company Residential Directory
	Murphy Anna	Manhattan and Bronx Directory Publishing Company Residential Directory
	Murphy Nellie	Manhattan and Bronx Directory Publishing Company Residential Directory
	OConnor Wm J eng	Manhattan and Bronx Directory Publishing Company Residential Directory
	Thole Law rence	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Austin Frances r	New York Telephone
	Clark Agnes E Miss r	New York Telephone
	Kennedy John A	New York Telephone
	Mc Namara Wm J r	New York Telephone
	Regan Jas P r	New York Telephone
	Tobin J P r	New York Telephone
1920	Austin Christopher clk	R. L. Polk & Co.
	Austin Christopher Jr lab	R. L. Polk & Co.
	Austin Clara L tchr NY Inst for the Educ of the Blind	R. L. Polk & Co.
	Buckley Danl W foremn	R. L. Polk & Co.
	Cannon Annie w id Jas	R. L. Polk & Co.
	Cannon Jas lab	R. L. Polk & Co.
	Clark Frank checker	R. L. Polk & Co.
	Clark Jas F w atchmnn	R. L. Polk & Co.
	Kennedy Jas F chauf	R. L. Polk & Co.
	Kennedy Jno A clk	R. L. Polk & Co.

Year	Uses	Source
1920	Miller Margt w id Jos	R. L. Polk & Co.
	McNamara Jno lab	R. L. Polk & Co.
	McMahon Thos stmfr	R. L. Polk & Co.
	OKeefe Dominick	R. L. Polk & Co.
	Regan Belinda w id Martin J	R. L. Polk & Co.
	Thole Geo I driver	R. L. Polk & Co.
	Thole Harry chauf	R. L. Polk & Co.
	Thole Law rence lab	R. L. Polk & Co.
	Thole Law rence Jr driver	R. L. Polk & Co.
	Tobin Cath w id Jas	R. L. Polk & Co.
	Tobin Jas P clk	R. L. Polk & Co.
	Tobin Jno A bkbndr	R. L. Polk & Co.

416 W 17TH

Year	Uses	Source
1931	Ertz Alex C	Manhattan and Bronx Directory Publishing Company Residential Directory
	Ertz Chas M	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Ertz Chas M truckman	New York Telephone
	Residence	New York Telephone
1920	Ertt Chas M pres treas Charles M Ertz Inc	R. L. Polk & Co.
	Anderson Harry lab	R. L. Polk & Co.

419 W 17TH

Year	Uses	Source
1931	Tobin Michl J fireman	Manhattan and Bronx Directory Publishing Company Residential Directory
	Tobin Michl	Manhattan and Bronx Directory Publishing Company Residential Directory
	Tobin Anna	Manhattan and Bronx Directory Publishing Company Residential Directory
	OConnor Thos	Manhattan and Bronx Directory Publishing Company Residential Directory
	Monks Edmond	Manhattan and Bronx Directory Publishing Company Residential Directory
	Miranda Nich	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

Year	Uses	Source
1931	Gallaher Eliz	Manhattan and Bronx Directory Publishing Company Residential Directory
	Gallagher Hugh	Manhattan and Bronx Directory Publishing Company Residential Directory
	Brandoff John	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Branch	New York Telephone
	Nash & Keeedall w eighers	New York Telephone
1920	Trotel Louis A lab	R. L. Polk & Co.
	Tobin Michl J chauf	R. L. Polk & Co.
	Sullivan Bartholomew J chauf	R. L. Polk & Co.
	Smith Steph	R. L. Polk & Co.
	Santiago Jose lab	R. L. Polk & Co.
	Sanders Martin rigger	R. L. Polk & Co.
	Ruhm Mathilda w id Jno	R. L. Polk & Co.
	Rubinish Anton lab	R. L. Polk & Co.
	Murphy Frances w id Patk	R. L. Polk & Co.
	Mullen Frank B	R. L. Polk & Co.
	Lindenberg Otto G	R. L. Polk & Co.
	Jordan Gerard S cabtmkr	R. L. Polk & Co.
	Guero Jno lab	R. L. Polk & Co.
	Grant Beseie w id Edw in	R. L. Polk & Co.
	Gonzales Emil clk	R. L. Polk & Co.
	Gaman Nicholas mgr	R. L. Polk & Co.
	Fleming Jas B	R. L. Polk & Co.
	Fenton Hy lab	R. L. Polk & Co.
	Dougherty Wm J mailer	R. L. Polk & Co.
	Christiansen Peter A boat capt	R. L. Polk & Co.
	Van Wm H clk	R. L. Polk & Co.

421 W 17TH

Year	Uses	Source
1931	Chitty Jas E	Manhattan and Bronx Directory Publishing Company Residential Directory
	Maloney Mary	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

Year	Uses	Source
1931	OKeefe Michl	Manhattan and Bronx Directory Publishing Company Residential Directory
	Rogers Wm	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Gibbins Sadie nurse	New York Telephone
1920	Karnetich Rondo stew ard	R. L. Polk & Co.
	Honovich Mario lab	R. L. Polk & Co.
	Firth Francis G clk	R. L. Polk & Co.
	Coseano Oreste cook	R. L. Polk & Co.
	Doran Eug J driver	R. L. Polk & Co.
	Kelleher Michl F lab	R. L. Polk & Co.
	Kelleher Michl I clk P O h Springfield BQ	R. L. Polk & Co.
	Low e Harry lab	R. L. Polk & Co.
	Lukeman Jno cooper	R. L. Polk & Co.
	McDermott Patk E driver	R. L. Polk & Co.
	OKeefe Michl lab	R. L. Polk & Co.
	Ostrow ski Stanley cbtmkr	R. L. Polk & Co.
	Quinn Edw mach	R. L. Polk & Co.
	Sannw aldt Aug cooper	R. L. Polk & Co.
	Sannw aldt Chas 2d v p E H Behrens & Co Inc h JC	R. L. Polk & Co.
	Sepich Frank oiler	R. L. Polk & Co.
	Spindler Julius clk	R. L. Polk & Co.
	Taylor Albert F plmbr	R. L. Polk & Co.
	Taylor Jas chauf	R. L. Polk & Co.
	Vaughan Jno lab	R. L. Polk & Co.
	Vaughan Thos lab	R. L. Polk & Co.
	Wally Jno baker	R. L. Polk & Co.
	Ward Jno T driver	R. L. Polk & Co.

W 17TH ST

412 W 17TH ST

Year	Uses	Source
2017	GREGORY CAMPBELL	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2017	ORLANDO WHITFIELD	Cole Information Services
	ARIEL LEITES	Cole Information Services
	PEDRO MERCADO	Cole Information Services
	ROBERT SOENARIE	Cole Information Services
	WILFREDO FLORES	Cole Information Services
	DULCE ROJAS	Cole Information Services
	JOHN VELEZ	Cole Information Services
	MOHAMMED EMRAN	Cole Information Services
	KERANI IBRAHIM	Cole Information Services
	ANA JIMENEZ	Cole Information Services
	ISAC PETERSON	Cole Information Services
	ROBERT EVERETT	Cole Information Services
	MOHAMMED IBRAHIM	Cole Information Services
	MANIQUA SPIVEY	Cole Information Services
	JOSE MATA	Cole Information Services
	DELENZO CROSBY	Cole Information Services
2014	DELIA ROSADO	Cole Information Services
	SHANNON PETERSON	Cole Information Services
	JOAQUIN QUINTANA	Cole Information Services
	DULCE ROJAS	Cole Information Services
	MILAGROS DIAZ	Cole Information Services
	MICHELLE HARRISON	Cole Information Services
	JOHN VELEZ	Cole Information Services
	DIAMOND CAMPBELL	Cole Information Services
	MOHAMMED EMRAN	Cole Information Services
	ANA JIMENEZ	Cole Information Services
	JUAN MARTINEZ	Cole Information Services
	TIFFANY VARGAS	Cole Information Services
	MOHAMMED IBRAHIM	Cole Information Services
	JANET WILLIAMS	Cole Information Services
	DELENZO CROSBY	Cole Information Services
	AGOLIA KINLAW	Cole Information Services

FINDINGS

Year	Uses	Source
2014	ROBERT SOENARIE	Cole Information Services
2009	ANDREA LOPEZ	Cole Information Services
	ALEX JIMENEZ	Cole Information Services
	AGOLIA KINLAW	Cole Information Services
	KEORNA HARRIS	Cole Information Services
	R DULCE	Cole Information Services
	DIANA SOENARIE	Cole Information Services
	SELAAD CROSBY	Cole Information Services
	WILLIAM DONOHUE	Cole Information Services
	JOHN VELEZ	Cole Information Services
	ISAC PETERSON	Cole Information Services
	MOHAMMED EMRAN	Cole Information Services
	XIN HUANG	Cole Information Services
	MILAGROS DIAZ	Cole Information Services
2006	Bynum Jermaine C	Hill-Donnelly Information Services
	Cedder Jaleesa	Hill-Donnelly Information Services
	Dulce R C	Hill-Donnelly Information Services
	h Huang Xmn Mei AC	Hill-Donnelly Information Services
	h Jimenez Luis CC	Hill-Donnelly Information Services
	Valez Carmen C	Hill-Donnelly Information Services
	h Velez JohnC	Hill-Donnelly Information Services
2004	CATHERINE DONOHUE	Cole Information Services
	JOSEPH VELEZ	Cole Information Services
	RAQUEL CRUZ	Cole Information Services
	LUIS JIMENEZ	Cole Information Services
	JERMAINE BYNUM	Cole Information Services
	DOLORES HARRIS	Cole Information Services
	MICHAEL MABALLERO	Cole Information Services
	ISAC PETERSON	Cole Information Services
	MAUREEN DONOVAN	Cole Information Services
	YASUTOMO TAKEDA	Cole Information Services
	MILAGROS DIAZ	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2004	JIN HUANG	Cole Information Services
	R DULCE	Cole Information Services
	JAMES HOLLEY	Cole Information Services
2000	APARTMENTS	Cole Information Services
	ANGEL DELGADO	Cole Information Services
	2C WILLIAM F DONOHUE	Cole Information Services
	FEI Y HUANG	Cole Information Services
	JIN C HUANG	Cole Information Services
	RACHEL MAPP	Cole Information Services
	6A RUBY PETERSON	Cole Information Services
	5C CARMEN VALEZ	Cole Information Services
	5C ANTHONY VELEZ JR	Cole Information Services
	SHERYL WILKINS	Cole Information Services
	5B MICHAEL CABALLERO	Cole Information Services
1999	DELGADO ANGEL	Cole Information Services
1994	HUANG, XIN NEI	Cole Information Services
	PATTERSON, OZZIE	Cole Information Services
	FLYNN, M	Cole Information Services
	VELEZ, C	Cole Information Services
	DELGADO, ANGEL	Cole Information Services
	DONOVAN, MARGARET	Cole Information Services
	DONOHUE, WILLIAM F	Cole Information Services
	ARANA, HENRY	Cole Information Services
	CARR, VINCENT	Cole Information Services
	CABALLERO, MICHAEL	Cole Information Services
	WILKINS, S	Cole Information Services
	PALACIOS, TELMO, JR	Cole Information Services
	CARROLL, A	Cole Information Services
1983	Saldana Angel	New York Telephone
	Patterson Ozzie	New York Telephone
	Palacios John	New York Telephone
	Flynn M	New York Telephone

FINDINGS

Year	Uses	Source
1983	Donohue William F	New York Telephone
	Diaz Trinidad	New York Telephone
	Carroll A	New York Telephone
	Arana Henry	New York Telephone
	Velez C	New York Telephone

414 W 17TH ST

Year	Uses	Source
2004	JON JONES	Cole Information Services

417 W 17TH ST

Year	Uses	Source
1983	Malone Barbara Mrs	New York Telephone
	Mendez Miguel	New York Telephone

419 W 17TH ST

Year	Uses	Source
2017	FERNANDO LOPEZ	Cole Information Services
	DELILAH MONTGOMERY	Cole Information Services
	JOSEPH MOORE	Cole Information Services
	PETER MULLIGAN	Cole Information Services
	CHRISTOPHER PRIMO	Cole Information Services
	ERIC QUINONES	Cole Information Services
	MARC RAVIZEE	Cole Information Services
	JANICE ROBERTS	Cole Information Services
	LOUIS SANABRIA	Cole Information Services
	RICK SAMAROO	Cole Information Services
	HILDA SMITH	Cole Information Services
	SEYMOUR SWAN	Cole Information Services
	EUREKKA WILSON	Cole Information Services
	BRYAN COLLAZO	Cole Information Services
	EUGENE DAVIS	Cole Information Services
	ANGELO DEJESUS	Cole Information Services
	BLANCA DELTORO	Cole Information Services

FINDINGS

Year	Uses	Source
2017	LEON DIAZ	Cole Information Services
	TASHA JOHNSON	Cole Information Services
	KIN LEE	Cole Information Services
	QIONG LIN	Cole Information Services
	CHRISTIA MADURO	Cole Information Services
	AMELIA MARTINEZ	Cole Information Services
	CHRIS MARTINEZ	Cole Information Services
	BENNY MEI	Cole Information Services
	ROSABEL PARRA	Cole Information Services
	RAYMOND VEGA	Cole Information Services
	EDWARD VILLEGAS	Cole Information Services
	WAYI WEI	Cole Information Services
	BRIAN WILLIAMSON	Cole Information Services
	JOSEPH CARRILLO	Cole Information Services
	KAITY CHAN	Cole Information Services
	TOM ARNEEL	Cole Information Services
	JOYCE HUNTER	Cole Information Services
	R IRIZARRY	Cole Information Services
	BERNICE JEFFERSON	Cole Information Services
	FELIPE JIMENEZ	Cole Information Services
	LUCIE KADAGE	Cole Information Services
	MICHEAL MARRERO	Cole Information Services
	JOSUE MORALES	Cole Information Services
	SENKA OCONNOR	Cole Information Services
	JOHN QUILES	Cole Information Services
	PORFIRIO RAMOS	Cole Information Services
	JANET RIVERA	Cole Information Services
	CECLIA RODRIGUEZ	Cole Information Services
	BETZAIDA SANTIAGO	Cole Information Services
	JOSE SKEET	Cole Information Services
	DIANA CARBONELL	Cole Information Services
	KATHERINE CHUNG	Cole Information Services

FINDINGS

Year	Uses	Source
2017	EDWARD CROWELL	Cole Information Services
	CARLYTHA DAIL	Cole Information Services
	ULMA DELGADO	Cole Information Services
	LASHAWN ASHE	Cole Information Services
	LAUREN GRASCH	Cole Information Services
	DESTINY HILL	Cole Information Services
	GUSTAVO MARIN	Cole Information Services
	PAMELA MIRAGLIA	Cole Information Services
	SEGUNDO NUNEZ	Cole Information Services
	CLARISA ORENGO	Cole Information Services
	FRANK PALACIOS	Cole Information Services
	JAIME RODRIGUEZ	Cole Information Services
	RACHEL STEPNEY	Cole Information Services
	ELIZABETH STERLING	Cole Information Services
	IMRON THOMPSON	Cole Information Services
	CASANDRA WILLIAMS	Cole Information Services
	ANTONIA CRESPO	Cole Information Services
	JANET DANIELS	Cole Information Services
	MARIA ESCOBAR	Cole Information Services
	EZEKIEL WITHERSPOON	Cole Information Services
	LAUREN WRIGHT	Cole Information Services
	WILFREDO ALICEA	Cole Information Services
	IRIS HADDOCK	Cole Information Services
	HUASCAR HERNANDEZ	Cole Information Services
	ANGELA JASPER	Cole Information Services
	GLENDA LEBRON	Cole Information Services
	MEIYU LI	Cole Information Services
	ENDI LOPEZ	Cole Information Services
	PEDRO MARRERO	Cole Information Services
	STEPHEN ORSINI	Cole Information Services
	JULIA OTERO	Cole Information Services
	PALMER ROXANNE	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2017	YVONNE SERRANO	Cole Information Services
	TONY SWEET	Cole Information Services
	MICHAEL CABALLERO	Cole Information Services
	DANIELL CASTRO	Cole Information Services
	HECTOR GARCIA	Cole Information Services
	JUN WU	Cole Information Services
	DINAH BODDEN	Cole Information Services
	GINA BROWN	Cole Information Services
	KEITH HAMMIE	Cole Information Services
	IVETTE RODRIGUEZ	Cole Information Services
	MICHAEL GONZALEZ	Cole Information Services
	DAVID JUDGE	Cole Information Services
	BEATA KOWAL	Cole Information Services
	FENG LI	Cole Information Services
	DAVID LINTON	Cole Information Services
	JOANNA HIRALDO	Cole Information Services
	GIL PEREZ	Cole Information Services
	ROSA REYES	Cole Information Services
	MITZIE RIVERA	Cole Information Services
	SOSA SUAREZ	Cole Information Services
	ANDY TEJADA	Cole Information Services
	ANGEL VAZQUEZ	Cole Information Services
	WILSON VAZQUEZ	Cole Information Services
	KATHY VIDAL	Cole Information Services
	ANA VINICIO	Cole Information Services
	JERMAINE BYNUM	Cole Information Services
	SHARHONDA CHAPPELL	Cole Information Services
	CHERYL EBEART	Cole Information Services
	LUIS FELICIANO	Cole Information Services
	FU YAN	Cole Information Services
	QING YUAN	Cole Information Services
	ORLANDO ACOSTA	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2017	JAVIER ANDINO	Cole Information Services
	FELIPE APONTE	Cole Information Services
	NAOMI GUTIERREZ	Cole Information Services
	GILBERT JACKSON	Cole Information Services
	NICK LUGO	Cole Information Services
	CHRISTINA MAR	Cole Information Services
	SHAUN MILLER	Cole Information Services
	EPIFANIE MEDINA	Cole Information Services
	LUIS MORA	Cole Information Services
	CHARLES MULDROW	Cole Information Services
	LUIS NATAL	Cole Information Services
	MILAGROS PADILLA	Cole Information Services
	PALMERIO SOLARES	Cole Information Services
	BRIAN SUMMERS	Cole Information Services
	HECTOR VALLENILLA	Cole Information Services
	MARY TOTARO	Cole Information Services
	S WALLACE	Cole Information Services
	GEORGE WEAVER	Cole Information Services
	CLAIRE CID	Cole Information Services
	KRYSTAL CRUZ	Cole Information Services
	EILEEN CULLEN	Cole Information Services
	JUDY BANKS	Cole Information Services
	CLARA BELL	Cole Information Services
	NELSON BENITEZ	Cole Information Services
	XIAOYAN GU	Cole Information Services
	DULCILI MAUROZA	Cole Information Services
	YOLANDA MEDINA	Cole Information Services
	KEVIN NEALS	Cole Information Services
	GUSTAVO PALACIOS	Cole Information Services
	ANGELA PLUGUES	Cole Information Services
	JASON POSEY	Cole Information Services
	GLORIA SMITH	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2017	VICTORIA WADE	Cole Information Services
	PATRICIA WALKER	Cole Information Services
	FELICIA WATSON	Cole Information Services
	CURTIS CAMPBELL	Cole Information Services
	CANDIDA CARO	Cole Information Services
	SUKYUNG CHU	Cole Information Services
	ALVIN COBB	Cole Information Services
	PABLO CURET	Cole Information Services
	WILMA FERNANDEZ	Cole Information Services
	MATILDE COLON	Cole Information Services
	CHARLIE EVANS	Cole Information Services
	JOVANNA FEBRES	Cole Information Services
	FENG GAI	Cole Information Services
	LORETTA WILSON	Cole Information Services
	SHUN ZHOU	Cole Information Services
2014	DIAZ GARCIA	Cole Information Services
	DECHANG GU	Cole Information Services
	ERIC HOWARD	Cole Information Services
	JOY KALLIO	Cole Information Services
	DULCILI MAUROZA	Cole Information Services
	JULIAN MORALES	Cole Information Services
	KEVIN NEALS	Cole Information Services
	GUSTAVO PALACIOS	Cole Information Services
	RAMONA PENA	Cole Information Services
	CHARLOTE SCOTT	Cole Information Services
	TERRENCE STOKES	Cole Information Services
	CHERYL TUCKER	Cole Information Services
	JAVIER VAZQUEZ	Cole Information Services
	VICTORIA WADE	Cole Information Services
	PATRICIA WALKER	Cole Information Services
	FELICIA WATSON	Cole Information Services
	HECTOR GARCIA	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2014	WILLIAM GONZALEZ	Cole Information Services
	HUASCAR HERNANDEZ	Cole Information Services
	IRIS HADDOCK	Cole Information Services
	MICHAEL HAMPTON	Cole Information Services
	MAYRA HERNANDEZ	Cole Information Services
	JEROME HILL	Cole Information Services
	ANGELA JASPER	Cole Information Services
	CHRISTINE KRAJNYK	Cole Information Services
	GLENDA LEBRON	Cole Information Services
	PEDRO MARRERO	Cole Information Services
	STEPHEN ORSINI	Cole Information Services
	PEDRO ROSARIO	Cole Information Services
	SIMON SAMUELS	Cole Information Services
	YVONNE SERRANO	Cole Information Services
	MICHELLE SINGLETON	Cole Information Services
	TONY SWEET	Cole Information Services
	GUY WILLIAMS	Cole Information Services
	JUN WU	Cole Information Services
	JERMAINE BYNUM	Cole Information Services
	SHARHONDA CHAPPELL	Cole Information Services
	LYDIA ECHEVARRIA	Cole Information Services
	HENRI EDWARDS	Cole Information Services
	KEITH HAMMIE	Cole Information Services
	JOANNA HIRALDO	Cole Information Services
	ANGELA JODHA	Cole Information Services
	IRIS MOLINA	Cole Information Services
	RAMONA MUNIZ	Cole Information Services
	TELMO PALACIOS	Cole Information Services
	MARCELLA SOUTH	Cole Information Services
	SOSA SUAREZ	Cole Information Services
	KATHY VIDAL	Cole Information Services
	ANA VINICIO	Cole Information Services

FINDINGS

Year	Uses	Source
2014	ORLANDO ACOSTA	Cole Information Services
	JAVIER ANDINO	Cole Information Services
	CLAIRE CID	Cole Information Services
	KRYSTAL CRUZ	Cole Information Services
	EILEEN CULLEN	Cole Information Services
	MILDRED DECKARD	Cole Information Services
	JOANNA FELICIANO	Cole Information Services
	KATHLEEN GILLETTE	Cole Information Services
	L GONCALVES	Cole Information Services
	GLADYS GONZALEZ	Cole Information Services
	GILBERT JACKSON	Cole Information Services
	NICK LUGO	Cole Information Services
	CHRISTINA MAR	Cole Information Services
	EPIFANIE MEDINA	Cole Information Services
	SHAUN MILLER	Cole Information Services
	LUIS MORA	Cole Information Services
	JASON PEREZ	Cole Information Services
	ANTHONY NAHORNEY	Cole Information Services
	THOMAS PROSSER	Cole Information Services
	MARVIN RUEDA	Cole Information Services
	BRIAN SUMMERS	Cole Information Services
	MARY TOTARO	Cole Information Services
	STEPHANIE WALLACE	Cole Information Services
	GEORGE WEAVER	Cole Information Services
	ALFREDO ZELAYA	Cole Information Services
	CLARA BELL	Cole Information Services
	NELSON BENITEZ	Cole Information Services
	CANDIDA CARO	Cole Information Services
	CURTIS CAMPBELL	Cole Information Services
	ALVIN COBB	Cole Information Services
	PABLO CURET	Cole Information Services
	JOSEPH CARRILLO	Cole Information Services

FINDINGS

Year	Uses	Source
2014	JAMI COOK	Cole Information Services
	FENG GAI	Cole Information Services
	MARLA GARRISON	Cole Information Services
	QIONG LIN	Cole Information Services
	RICHARD MARTINEZ	Cole Information Services
	OLIVIA MILLER	Cole Information Services
	ERNEST MOREIRA	Cole Information Services
	MAUREEN MURRAY	Cole Information Services
	ROSABEL PARRA	Cole Information Services
	JOSE REYES	Cole Information Services
	WAYI WEI	Cole Information Services
	BRIAN WILLIAMSON	Cole Information Services
	LORETTA WILSON	Cole Information Services
	SHUN ZHOU	Cole Information Services
	SHI YAN	Cole Information Services
	TOM ARNEEL	Cole Information Services
	LILIEN BLACK	Cole Information Services
	RONALD BREELAND	Cole Information Services
	JOHN BROWN	Cole Information Services
	DIANA CARBONELL	Cole Information Services
	KATHERINE CHUNG	Cole Information Services
	EDWARD CROWELL	Cole Information Services
	CARLYTHA DAIL	Cole Information Services
	EDUARDA GREEN	Cole Information Services
	MAI HUANG	Cole Information Services
	JOYCE HUNTER	Cole Information Services
	FELIPE JIMENEZ	Cole Information Services
	YA LU	Cole Information Services
	LUCIE KADAGE	Cole Information Services
	MICHEAL MARRERO	Cole Information Services
	DARRELL MCCRAY	Cole Information Services
	GERARD MCCUTHEN	Cole Information Services

FINDINGS

Year	Uses	Source
2014	SENKA OCONNOR	Cole Information Services
	JANET RIVERO	Cole Information Services
	PORFIRIO RAMOS	Cole Information Services
	PHYLLIS RUSSO	Cole Information Services
	BETZAIDA SANTIAGO	Cole Information Services
	JOSE SKEET	Cole Information Services
	JHANE WIGGINS	Cole Information Services
	JOHN BELLAMY	Cole Information Services
	JOBIERA BANKS	Cole Information Services
	MALIK BRUNO	Cole Information Services
	ANTONIA CRESPO	Cole Information Services
	JULIO GARCIA	Cole Information Services
	DUVON EVANS	Cole Information Services
	HERBERT LOPEZ	Cole Information Services
	GUSTAVO MARIN	Cole Information Services
	MARDEA MCCRUMADA	Cole Information Services
	FRANCISCO MIRANDA	Cole Information Services
	CLARISA ORENGO	Cole Information Services
	MICHAEL ORTIZ	Cole Information Services
	SEGUNDO NUNEZ	Cole Information Services
	TAESHYRALIN REEL	Cole Information Services
	JAIME RODRIGUEZ	Cole Information Services
	JANICE SIMS	Cole Information Services
	ELIZABETH STERLING	Cole Information Services
	ANTONIA SUS	Cole Information Services
	EDWARD VILA	Cole Information Services
	IMRON THOMPSON	Cole Information Services
	EZEKIEL WITHERSPOON	Cole Information Services
	WILFREDO ALICEA	Cole Information Services
	TELMO BARROS	Cole Information Services
	MICHAEL CABALLERO	Cole Information Services
	BRYAN COLLAZO	Cole Information Services

FINDINGS

Year	Uses	Source
2014	EUGENE DAVIS	Cole Information Services
	ANGELO DEJESUS	Cole Information Services
	BLANCA DELTORO	Cole Information Services
	EMILIO FELCIANO	Cole Information Services
	MICHAEL GONZALEZ	Cole Information Services
	DAVID JUDGE	Cole Information Services
	FENG LI	Cole Information Services
	PETER MULLIGAN	Cole Information Services
	CHRISTOPHER PRIMO	Cole Information Services
	MIRIAM QUINONES	Cole Information Services
	MARC RAVIZEE	Cole Information Services
	JANICE ROBERTS	Cole Information Services
	RICK SAMAROO	Cole Information Services
	LOUIS SANABRIA	Cole Information Services
	HILDA SMITH	Cole Information Services
	YESSENIA ANTONSANTI	Cole Information Services
2009	JAMES CRAWFORD	Cole Information Services
	JOSEPH SCHULER	Cole Information Services
	FULLY FRESH RECORDINGS INC	Cole Information Services
	JUN WU	Cole Information Services
	DEBRA MCCALLUM	Cole Information Services
	PEDRO MARRERO	Cole Information Services
	JUDITH LOPEZ	Cole Information Services
	JENNIFER JOHNSON	Cole Information Services
	IRIS HADDOCK	Cole Information Services
	VIRGINIA WALLACE	Cole Information Services
	JOSE ACOSTA	Cole Information Services
	YAO MEI	Cole Information Services
	STEPHEN ORSINI	Cole Information Services
	GLENDA LEBRON	Cole Information Services
	HELEN LEE	Cole Information Services
	ANGELA JASPER	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2009	MICHELLE SINGLETON	Cole Information Services
	MAUREEN DONOVAN	Cole Information Services
	CHRISTOPHER DOMOND	Cole Information Services
	LEW MCNEELY	Cole Information Services
	SHARHONDA CHAPPELL	Cole Information Services
	ANGELA JODHA	Cole Information Services
	SOSA SUAREZ	Cole Information Services
	PATRICIA HANLEY	Cole Information Services
	TENGIZ GOKADZE	Cole Information Services
	GINA BROWN	Cole Information Services
	JERMAINE BYNUM	Cole Information Services
	WILFREDA ALICEA	Cole Information Services
	JANET ALICEA	Cole Information Services
	RAMONA MUNIZ	Cole Information Services
	IRIS MOLINA	Cole Information Services
	ANA VINICIO	Cole Information Services
	R VADILLO	Cole Information Services
	MARCELLA SOUTH	Cole Information Services
	ALFREDO ZELAYA	Cole Information Services
	C GU	Cole Information Services
	MILAGROS PADILLA	Cole Information Services
	DONALD FREEMAN	Cole Information Services
	SONIA RIVERO	Cole Information Services
	ERIC RODRIGUEZ	Cole Information Services
	RICARDO CAMPOS	Cole Information Services
	DEBORAH JONES	Cole Information Services
	ANTHONY NAHORNEY	Cole Information Services
	IRIS GONZALEZ	Cole Information Services
	CLAIRE CID	Cole Information Services
	GILBERT JACKSON	Cole Information Services
	JONNE CUSHING	Cole Information Services
	ROBERTO DELGADO	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2009	CURTIS CAMPBELL	Cole Information Services
	CANDIDA CARO	Cole Information Services
	MAUREEN CARROLL	Cole Information Services
	TAYSHAWN SACKEY	Cole Information Services
	LISA HAMPTON	Cole Information Services
	ANTONIA NATAL	Cole Information Services
	ERIC HOWARD	Cole Information Services
	ANTONIO NUNEZ	Cole Information Services
	BRENDA GORDON	Cole Information Services
	RAMONA PENA	Cole Information Services
	J PEREZ	Cole Information Services
	JOY KALLIO	Cole Information Services
	PATRICIA WALKER	Cole Information Services
	MENZENA MILLER	Cole Information Services
	ALVIN COBB	Cole Information Services
	MIRIAM COTTO	Cole Information Services
	JAVIER VAZQUEZ	Cole Information Services
	WAN LU	Cole Information Services
	PABLO CURET	Cole Information Services
	BLANCA DELTORO	Cole Information Services
	LEON DIAZ	Cole Information Services
	RAYMOND DONOGHUE	Cole Information Services
	D MAUROZA	Cole Information Services
	FERNANDO LOPEZ	Cole Information Services
	KAREEM SACKY	Cole Information Services
	PAUL DURAN	Cole Information Services
	WILSON TORO	Cole Information Services
	A IRIZARRY	Cole Information Services
	VADIM PEVZNER	Cole Information Services
	ANNMARIE BARONOWSKI	Cole Information Services
	T KRILYNA	Cole Information Services
	JOHN REBOLLEDO	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2009	JANICE ROBERTS	Cole Information Services
	JOSEPH MOORE	Cole Information Services
	BRYAN COLLAZO	Cole Information Services
	WILFREDO VELEZ	Cole Information Services
	FENG LI	Cole Information Services
	SHI YAN	Cole Information Services
	COURTNEY DANIELS	Cole Information Services
	EDWARD HILLY	Cole Information Services
	EMERINDA MADURO	Cole Information Services
	PHILIP MARTINEZ	Cole Information Services
	CLAUDIA CASTRO	Cole Information Services
	KAITY CHAN	Cole Information Services
	JANICE HARRIS	Cole Information Services
	MARTHA NUNEZ	Cole Information Services
	FENG GAI	Cole Information Services
	MARLA GARRISON	Cole Information Services
	SAMUEL FLORES	Cole Information Services
	PAMELA BERBEDES	Cole Information Services
	CHARLIE EVANS	Cole Information Services
	BRIAN WILLIAMSON	Cole Information Services
	E WITHERSPOON	Cole Information Services
	JOSE REYES	Cole Information Services
	MAUREEN MURRAY	Cole Information Services
	LETICIA CONCEPCION	Cole Information Services
	JOSEPH VILLAMAR	Cole Information Services
	AURA VEGA	Cole Information Services
	QIONG LIN	Cole Information Services
	CARLYTHA DAIL	Cole Information Services
	AMINATA DIAGNE	Cole Information Services
	ELDA DIAZ	Cole Information Services
	PORFIRIO RAMOS	Cole Information Services
	BEATA MARSZALEK	Cole Information Services

FINDINGS

Year	Uses	Source
2009	SENKA OCONNOR	Cole Information Services
	DIANA CARBONELL	Cole Information Services
	TOM ARNEEL	Cole Information Services
	FELIPE JIMENEZ	Cole Information Services
	JOSE SKEET	Cole Information Services
	MARION DAY	Cole Information Services
	FRANK PALACIOS	Cole Information Services
	ANTONIA SUS	Cole Information Services
	OONA HAMLIN	Cole Information Services
	TYON HARRISON	Cole Information Services
	JOSEPH NEALS	Cole Information Services
	DUVON EVANS	Cole Information Services
	AIDA WILLIAMS	Cole Information Services
	FELICIA REYNOLDS	Cole Information Services
	JAIME RODRIGUEZ	Cole Information Services
	EDWARD VILA	Cole Information Services
	YONGCI LI	Cole Information Services
	HERBERT LIVERMAE	Cole Information Services
	JAMES DISCEPOLO	Cole Information Services
2006	Number 238 h Deltoro Blanca Cv	Hill-Donnelly Information Services
	Diaz Leon Lydia C	Hill-Donnelly Information Services
	Number 7 C h Donoghue Raymond J AC	Hill-Donnelly Information Services
	Number 15 H H Espada J HAC	Hill-Donnelly Information Services
	Number 19 A Evans Duvon Av	Hill-Donnelly Information Services
	Feliciano A C	Hill-Donnelly Information Services
	Number 4 H H Ferat David C	Hill-Donnelly Information Services
	Number 233 h Fernandez Wilma CC	Hill-Donnelly Information Services
	Number 4 E h Flores Arturo Av C	Hill-Donnelly Information Services
	h Freeman D	Hill-Donnelly Information Services
	Gai Feng Yun	Hill-Donnelly Information Services
	Number 2 F Garcia Luis R CC	Hill-Donnelly Information Services
	Number 9 H h Garrison Lillian Cv	Hill-Donnelly Information Services

FINDINGS

Year	*Uses*	*Source*
2006	Number 11 G h Gonzalez Anastacio Av	Hill-Donnelly Information Services
	Number 8D h Gonzalez Barbara CC	Hill-Donnelly Information Services
	Number 20 H h Gordon B CC	Hill-Donnelly Information Services
	Number 15D h Haddock T AC	Hill-Donnelly Information Services
	Number 23 C Hamlin Oona C o	Hill-Donnelly Information Services
	h Hilly Edw ard C	Hill-Donnelly Information Services
	Number 63 h Huang Nal Qin v	Hill-Donnelly Information Services
	Irizarry A Cv	Hill-Donnelly Information Services
	h Jackson Gilbert Av	Hill-Donnelly Information Services
	Number 10 B h Jasper A AC	Hill-Donnelly Information Services
	odha A C	Hill-Donnelly Information Services
	Number 25 G h Jones Deborah A Cv	Hill-Donnelly Information Services
	Number 6 E h Kallio Joy AC	Hill-Donnelly Information Services
	Number 18 A h ULi Feng Ping v	Hill-Donnelly Information Services
	Number 5 H h U Zhi Hong v	Hill-Donnelly Information Services
	Number 4 F h Lopez Fernando AC	Hill-Donnelly Information Services
	Lopez Judith C	Hill-Donnelly Information Services
	Lopez Samuel C oo	Hill-Donnelly Information Services
	Number 173 h Lopez Ydalia	Hill-Donnelly Information Services
	Number 25 C h Lu Ya Ung C	Hill-Donnelly Information Services
	Number 17 E h Maduro Emerinda +v	Hill-Donnelly Information Services
	Number 23 A Marin Gustavo AC	Hill-Donnelly Information Services
	Number 3 H h Marrero Orlando C	Hill-Donnelly Information Services
	Number 10 J h Marszalek Beata C	Hill-Donnelly Information Services
	Number 23 C Martinez Chris A	Hill-Donnelly Information Services
	Number 10 E Mauroza Dulcilida A	Hill-Donnelly Information Services
	Number 8 F h Mccallum Debra	Hill-Donnelly Information Services
	Number 10 C h Mcneely L E A	Hill-Donnelly Information Services
	Number 16 H h Molina I	Hill-Donnelly Information Services
	Number 22 G Moore Av	Hill-Donnelly Information Services
	Number 6 C h Murray Maureen AC	Hill-Donnelly Information Services
	Number 2 E h Nahorney Anthony Av	Hill-Donnelly Information Services

FINDINGS

Year	Uses	Source
2006	Number 6 A h Nunez Antonio AC	Hill-Donnelly Information Services
	Number 22 C Oconnor Nikola A	Hill-Donnelly Information Services
	Orengo C v	Hill-Donnelly Information Services
	Number 16 G h Palacios Frank K AC	Hill-Donnelly Information Services
	Number 28 h Pena Ramona v	Hill-Donnelly Information Services
	Number 128 Perez JL Av	Hill-Donnelly Information Services
	Number 20 B h Ramos Porfirio AC	Hill-Donnelly Information Services
	Rebolledo John v	Hill-Donnelly Information Services
	Number 18 B Reyes ose Av	Hill-Donnelly Information Services
	Reyes Rosa v	Hill-Donnelly Information Services
	Number 20 F h Rivera Carlos Av	Hill-Donnelly Information Services
	Number 16 B h Rivero S C o	Hill-Donnelly Information Services
	Number 20 H Roberts Janice v	Hill-Donnelly Information Services
	Number 21 E Rodriguez Eric o	Hill-Donnelly Information Services
	Number 18 H Rodriguez Milagros CC	Hill-Donnelly Information Services
	Number 13 H h Rodriguez R	Hill-Donnelly Information Services
	Samabia Louis	Hill-Donnelly Information Services
	Number 78 h Schuler Joseph	Hill-Donnelly Information Services
	Scott Charlotte v	Hill-Donnelly Information Services
	Multi Unit Address	Hill-Donnelly Information Services
	Number 18 H h Acevedo Tomas	Hill-Donnelly Information Services
	Number 14 C Alicea Wilfreda C	Hill-Donnelly Information Services
	Number 14 E H Ameel Tom	Hill-Donnelly Information Services
	Asaf Maria v o	Hill-Donnelly Information Services
	Berdedes Pam C	Hill-Donnelly Information Services
	Brooks Shakema C	Hill-Donnelly Information Services
	Number 15 E Campbell ICA C	Hill-Donnelly Information Services
	Number 158 Carbonell Diana	Hill-Donnelly Information Services
	Number 4D h Caro Candida	Hill-Donnelly Information Services
	Number 16 E h Carr Edw ard	Hill-Donnelly Information Services
	Number 16 E Carroll M	Hill-Donnelly Information Services
	Number 12 A h Chen Shao C	Hill-Donnelly Information Services

FINDINGS

Year	*Uses*	*Source*
2006	Number 17 G h Chung K Av	Hill-Donnelly Information Services
	Number 228 Cid Claire Av	Hill-Donnelly Information Services
	Number 148 Craw ford James v	Hill-Donnelly Information Services
	Number 12 G Cullen Ann A	Hill-Donnelly Information Services
	Number 113 Curet Pablo AC o	Hill-Donnelly Information Services
	Number 1 lF h Gushing Jonne Av	Hill-Donnelly Information Services
	Number 23D Davis Anthony	Hill-Donnelly Information Services
	Number 3 C h Dejesus Alda AC	Hill-Donnelly Information Services
	Number 138 Shapiro Marco v	Hill-Donnelly Information Services
	h Skeet Jose v	Hill-Donnelly Information Services
	Number 18D h Solares Palmerio	Hill-Donnelly Information Services
	Stamp Stephanie s C	Hill-Donnelly Information Services
	Number 58 h Sus Antonia AC	Hill-Donnelly Information Services
	Number 12 E Thalheimer Mark C	Hill-Donnelly Information Services
	Number 2 A h Torno W	Hill-Donnelly Information Services
	Ujkaj Ymer C	Hill-Donnelly Information Services
	Number 8 A Wallace Virginia A 0os	Hill-Donnelly Information Services
	Number 83 h Williams A C	Hill-Donnelly Information Services
	Number 8 H h Witherspoon E	Hill-Donnelly Information Services
	Wu Jun Jie v	Hill-Donnelly Information Services
	Number 24 C h Zelaya Alfredo E AC	Hill-Donnelly Information Services
	h Zhou Shun E CC	Hill-Donnelly Information Services
2004	BARBARA GONZALEZ	Cole Information Services
	BRENDA GORDON	Cole Information Services
	RAMONA PENA	Cole Information Services
	J PEREZ	Cole Information Services
	CHERYL TUCKER	Cole Information Services
	LUIS GARCIA	Cole Information Services
	SANDRA FLORES	Cole Information Services
	JOY KALLIO	Cole Information Services
	WILLIAM ANGOTTI	Cole Information Services
	JORGE ALVARADO	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2004	BLANCA DELTORO	Cole Information Services
	MARK THALL	Cole Information Services
	ANNMARIE BARONOWSKI	Cole Information Services
	NATASHA OCONNOR	Cole Information Services
	JASON ROSADO	Cole Information Services
	RAYMOND DONOGHUE	Cole Information Services
	NADINE GRIFFITH	Cole Information Services
	K PORTERFIELD	Cole Information Services
	ARTURO FLORES	Cole Information Services
	PAM BERDEBES	Cole Information Services
	T KRILYNA	Cole Information Services
	JANICE ROBERTS	Cole Information Services
	JOSEPH MOORE	Cole Information Services
	FENG LI	Cole Information Services
	FERNANDO LOPEZ	Cole Information Services
	DOROTHY JOHN	Cole Information Services
	RICK SAMAROO	Cole Information Services
	SHUN ZHOU	Cole Information Services
	RAUL DEJESUS	Cole Information Services
	JULIE THALHEIMER	Cole Information Services
	LINDA OCASIO	Cole Information Services
	LYDIA DIAZ-LEON	Cole Information Services
	EDWARD HILLY	Cole Information Services
	BRIAN WILLIAMSON	Cole Information Services
	E WITHERSPOON	Cole Information Services
	CHARLIE EVANS	Cole Information Services
	JOSE REYES	Cole Information Services
	EMERINDA MADURO	Cole Information Services
	MAUREEN MURRAY	Cole Information Services
	LUZ COTTO	Cole Information Services
	QIONG LIN	Cole Information Services
	MARCO SHAPIRO	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2004	GISELLE JOHNSON	Cole Information Services
	RAMONA SOLARES	Cole Information Services
	DIANA CARBONELL	Cole Information Services
	THOMAS CAREY	Cole Information Services
	CARLYTHA DAIL	Cole Information Services
	LUIS HERNANDEZ	Cole Information Services
	EDUARDA GREEN	Cole Information Services
	W TORO	Cole Information Services
	ANA GIL	Cole Information Services
	ELYSE GOLOB	Cole Information Services
	JOHN KING	Cole Information Services
	TOM ARNEEL	Cole Information Services
	QUINTON ANDINO	Cole Information Services
	PORFIRIO RAMOS	Cole Information Services
	MILAGROS RODRIGUEZ	Cole Information Services
	MICHEAL MARRERO	Cole Information Services
	KATHERINE CHUNG	Cole Information Services
	SAINT JAMES STUDIOS	Cole Information Services
	SOLEDAD RIVERA	Cole Information Services
	MENZENA MILLER	Cole Information Services
	EDUVIGES MONTESDEOCA	Cole Information Services
	PABLO CURET	Cole Information Services
	JAMES CRAWFORD	Cole Information Services
	JOSEPH SCHULER	Cole Information Services
	WAN LU	Cole Information Services
	SHIRLEY SANABRIA	Cole Information Services
	JOSE SANTIAGO	Cole Information Services
	JOSE SKEET	Cole Information Services
	MARION DAY	Cole Information Services
	OONA HAMLIN	Cole Information Services
	FRANK PALACIOS	Cole Information Services
	DUVON EVANS	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2004	FRANCISCO MIRANDA	Cole Information Services
	XUE CHEN	Cole Information Services
	I MOLINA	Cole Information Services
	EDWARD VILA	Cole Information Services
	EMELINDO SOSA	Cole Information Services
	ALLAN SIMS	Cole Information Services
	ANTONIA SUS	Cole Information Services
	HELEN LEE	Cole Information Services
	JAMES DISCEPOLO	Cole Information Services
	TANSY HADDOCK	Cole Information Services
	DRENEISH KELLY	Cole Information Services
	JUN WU	Cole Information Services
	DEBRA MCCALLUM	Cole Information Services
	PEDRO MARRERO	Cole Information Services
	SHAO CHEN	Cole Information Services
	MICHAEL CONATY	Cole Information Services
	ANGELA JASPER	Cole Information Services
	CHARLOTTE SCOTT	Cole Information Services
	MICHAEL JOHNSON	Cole Information Services
	MICHELLE SINGLETON	Cole Information Services
	MARSHA THOMPSON	Cole Information Services
	PATRICIA HANLEY	Cole Information Services
	TENGIZ GOKADZE	Cole Information Services
	LEW MCNEELY	Cole Information Services
	BENJAMIN CUI	Cole Information Services
	ALBA CRUZ	Cole Information Services
	R VADILLO	Cole Information Services
	IVETTE LORA	Cole Information Services
	KERMINE DURESTAL	Cole Information Services
	CHARLES THOMAS	Cole Information Services
	CLAIRE CID	Cole Information Services
	ANTHONY DAVIS	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2004	ANTHONY NAHORNEY	Cole Information Services
	KATHLEEN GILLETTE	Cole Information Services
	DONALD FREEMAN	Cole Information Services
	SARA ARMENDARIZ	Cole Information Services
	SONIA RIVERO	Cole Information Services
	CHARLES MULDROW	Cole Information Services
	CHRISTINE MODRICH	Cole Information Services
	JONNE CUSHING	Cole Information Services
	GILBERT JACKSON	Cole Information Services
	DEBORAH JONES	Cole Information Services
	ROBERTO DELGADO	Cole Information Services
	CURTIS CAMPBELL	Cole Information Services
	MAUREEN CARROLL	Cole Information Services
	ALISANDE DANIELS	Cole Information Services
	ANTONIA NATAL	Cole Information Services
	ANTONIO NUNEZ	Cole Information Services
	MBAYE NIANG	Cole Information Services
2000	APARTMENTS	Cole Information Services
	18H TOMAS ACEVEDO	Cole Information Services
	9B W ANGOTTI	Cole Information Services
	BEATRICE ARNAU	Cole Information Services
	14E TOM ARNEEL	Cole Information Services
	A BARONOWSKI	Cole Information Services
	3B STELLA BATTINO	Cole Information Services
	14F A BENITEZ	Cole Information Services
	14G PAM BERDEDES	Cole Information Services
	13C W C BRASSIL	Cole Information Services
	20F ROSE M BRIGGS	Cole Information Services
	15E CURTIS CAMPBELL	Cole Information Services
	13D CRISTINO CAMPOS	Cole Information Services
	22J H CANOSA	Cole Information Services
	11C THOMAS B CAREY	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2000	CLETHA CARR	Cole Information Services
	EDWARD CARR	Cole Information Services
	13G M CARROLL	Cole Information Services
	DOLLY CASTANO	Cole Information Services
	KAITY CHAN	Cole Information Services
	LING Y CHEN	Cole Information Services
	XUE Z CHEN	Cole Information Services
	17G K CHUNG	Cole Information Services
	22B CLAIRE CID	Cole Information Services
	2F MICHAEL CONATY	Cole Information Services
	6B L CORTEZ	Cole Information Services
	LUZ COTTO	Cole Information Services
	JAMES CRAWFORD	Cole Information Services
	EDWARD A CROWELL	Cole Information Services
	20H ALBA CRUZ	Cole Information Services
	BENJAMIN CUI	Cole Information Services
	11J PABLO CURET	Cole Information Services
	11F JONNE CUSHING	Cole Information Services
	ALISANDE DANIELS	Cole Information Services
	19D ANTHONY DAVIS	Cole Information Services
	MARION DAY	Cole Information Services
	8C AIDE DEJESUS	Cole Information Services
	RAUL DE JESUS	Cole Information Services
	RAUL DE JESUS	Cole Information Services
	21F ROBERTO DELGADO	Cole Information Services
	LYDIA DIAZ-LEON	Cole Information Services
	ANDREA DITREN	Cole Information Services
	7C RAYMOND J DONOGHUE	Cole Information Services
	KERMINE DURESTAL	Cole Information Services
	DUVON EVANS	Cole Information Services
	8J HASSIE FELICIANO	Cole Information Services
	DAVID FERAT	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2000	TRACEY L FLEMISTER	Cole Information Services
	4E ARTURO FLORES	Cole Information Services
	EDWARD FRAZIER	Cole Information Services
	D FREEMAN	Cole Information Services
	7 BONITO GARCIA	Cole Information Services
	ANASTACIO GONZALEZ	Cole Information Services
	20H B GORDON	Cole Information Services
	15D T HADDOCK	Cole Information Services
	JOSEPH HARVEY	Cole Information Services
	8J NANCY HASKIN	Cole Information Services
	EDWARD HILLY	Cole Information Services
	TEAM HO	Cole Information Services
	15 MILTON HOLMES	Cole Information Services
	NIDIA HUBBELL	Cole Information Services
	LESTER HUGGINS	Cole Information Services
	10B A JASPER	Cole Information Services
	25E DOROTHY A JOHN	Cole Information Services
	JOY KALLIO	Cole Information Services
	23B MARY KELLY	Cole Information Services
	JOHN R KING	Cole Information Services
	4F TERRY KIRK	Cole Information Services
	J KURDI	Cole Information Services
	5J J LADIN	Cole Information Services
	5E H LEE	Cole Information Services
	FENG P LI	Cole Information Services
	ZHI H LI	Cole Information Services
	QIONG P LIN	Cole Information Services
	24H JUDITH LOPEZ	Cole Information Services
	SAMUEL LOPEZ	Cole Information Services
	21B MIRIAM LUCAS	Cole Information Services
	2 TAI LY	Cole Information Services
	23E CHRIS MARTINEZ	Cole Information Services

FINDINGS

Year	Uses	Source
2000	L E MCNEELY	Cole Information Services
	23C OONA MC NEELY	Cole Information Services
	VICENTE A MIRANDA	Cole Information Services
	16H THOMAS MOLINA	Cole Information Services
	23A E MONTESDEOCA	Cole Information Services
	6C MAUREEN MURRAY	Cole Information Services
	3G MARIA NUNEZ	Cole Information Services
	21H J A OBRIEN	Cole Information Services
	NATASHA OCONNOR	Cole Information Services
	JUAN ORTEGA	Cole Information Services
	2B V PALMER	Cole Information Services
	19B J L PEREZ	Cole Information Services
	6G LEONARDO PINILLA	Cole Information Services
	JULIA QUINONES	Cole Information Services
	PORFIRIO RAMOS	Cole Information Services
	22E JOSE A REYES	Cole Information Services
	ROSA REYES	Cole Information Services
	CARMEN RIVERA	Cole Information Services
	HILDA RODRIGUEZ	Cole Information Services
	MILAGROS RODRIGUEZ	Cole Information Services
	ROSA RODRIGUEZ	Cole Information Services
	3D JOSEPHINE ROHAN	Cole Information Services
	7B JOSEPH SCHULER	Cole Information Services
	24E CHARLOTTE SCOTT	Cole Information Services
	H SEMAN	Cole Information Services
	JOSE SKEET	Cole Information Services
	15J RAMONA SOLARES	Cole Information Services
	5B ANTONIA SUS	Cole Information Services
	W TORO	Cole Information Services
	ALBERT T TUONEY	Cole Information Services
	25H R VADILLO	Cole Information Services
	20J OSWALD E VALIENTE	Cole Information Services

FINDINGS

Year	Uses	Source
2000	LEONOR VELASQUEZ	Cole Information Services
	9D BRIAN WILLIAMSON	Cole Information Services
	8H E WITHERSPOON	Cole Information Services
	24C ALFREDO E ZELAYA	Cole Information Services
1999	NATASHA OCONNOR	Cole Information Services
1994	THOMPSON, L	Cole Information Services
	CORTEZ, L	Cole Information Services
	LOUGHRAN, ANASTASIA	Cole Information Services
	MCCARTHY, BEATRICE M	Cole Information Services
	FELICIANO, HASSIE	Cole Information Services
	WILLIAMSON, BRIAN	Cole Information Services
	VADILLO, R	Cole Information Services
	CROWELL, EDWARD A	Cole Information Services
	CRUZ, ALBA	Cole Information Services
	KIRK, TERRY	Cole Information Services
	CHUNG, K	Cole Information Services
	BARON, EDWARD	Cole Information Services
	LEE, H	Cole Information Services
	FERAT, DAVID	Cole Information Services
	BUNBURY, ELLEN	Cole Information Services
	DIXON, T	Cole Information Services
	RAMOS, P	Cole Information Services
	ACEVEDO, TOMAS	Cole Information Services
	SEMAN, H	Cole Information Services
	FLORES, ARTURO	Cole Information Services
	PEREZ, J L	Cole Information Services
	PINILLA, LEONARDO	Cole Information Services
	GONZALEZ, JUAN	Cole Information Services
	MARTINEZ, R	Cole Information Services
	CURET, EDUARDO	Cole Information Services
	LADIN, J	Cole Information Services
	KRAFT, L	Cole Information Services

FINDINGS

Year	Uses	Source
1994	CORSO, ELVIRA	Cole Information Services
	SCOTT, CHARLOTTE	Cole Information Services
	ROSEBURGH, LYNDA	Cole Information Services
	BENITEZ, A	Cole Information Services
	PALMER, V	Cole Information Services
	DEILY, B & J	Cole Information Services
	GORDON, B	Cole Information Services
	MILLER, G	Cole Information Services
	ANDUZE, C	Cole Information Services
	FREEDEL, ANNA	Cole Information Services
	CAMPOS, CRISTINO	Cole Information Services
	MC BRIDE, P	Cole Information Services
	CID, CLAIRE	Cole Information Services
	THOMPSON, ROBERT	Cole Information Services
	DIAZ, M	Cole Information Services
	MURRAY, MAUREEN	Cole Information Services
	ROSE, JANET	Cole Information Services
	ANGOTTI, W	Cole Information Services
	BROWN, B	Cole Information Services
	WILLIAMS-GASKINS, JANNIE	Cole Information Services
	MIRAGLIA, VINCENT	Cole Information Services
	TORO, W	Cole Information Services
	PETRIK, PETER	Cole Information Services
	BURNS, M	Cole Information Services
	GORNAY, ANTHONY, JR	Cole Information Services
	MOLINA, TOMAS	Cole Information Services
	CARROLL, M	Cole Information Services
	CRAWFORD, JAMES	Cole Information Services
	REYES, JOSE A	Cole Information Services
	JONES, JAMES F	Cole Information Services
	GARCIA, N	Cole Information Services
	SMITH, F	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
1994	REID, J	Cole Information Services
	NILSEN, BJORN	Cole Information Services
	O BRIEN, J A	Cole Information Services
	TUOHEY, T	Cole Information Services
	MCMAHON, CATHARINE	Cole Information Services
	RICHTER, STANLEY	Cole Information Services
	HOLMES, MILTON	Cole Information Services
	DAVIS, ANTHONY	Cole Information Services
	SUS, ANTONIA	Cole Information Services
	CARR, EDWARD	Cole Information Services
	MARTINEZ, CHRIS	Cole Information Services
	KARGER, S	Cole Information Services
	TROTTA, E	Cole Information Services
	FRANKO, DONNA	Cole Information Services
	HO, TEAM	Cole Information Services
	JASPER, A	Cole Information Services
	POERIO, FRANK	Cole Information Services
	DONOGHUE, RAYMOND J	Cole Information Services
	KELLY, MARY	Cole Information Services
	DELGADO, ROBERTO	Cole Information Services
	HADDOCK, T	Cole Information Services
	CAREY, THOS B	Cole Information Services
	JOHN, DOROTHY A	Cole Information Services
	TORRES, G	Cole Information Services
	GONZALEZ, ANASTACIO	Cole Information Services
	NEYRA, BENIGNA	Cole Information Services
	COURAHANES, EFFIE	Cole Information Services
	CALANDRINO, JEAN	Cole Information Services
	CHEN, XUE ZHU	Cole Information Services
	MOLINA, M	Cole Information Services
	CLARKS-GREEN, M	Cole Information Services
	PAGAN, MONSERRATE	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
1994	LI, ZHI HONG	Cole Information Services
	VALIENTE, OSWALD E	Cole Information Services
	MONTESDEOCA, EDUVIGES	Cole Information Services
	BRASSIL, W C	Cole Information Services
	VASQUEZ, LUIS	Cole Information Services
	POLLOCK, SUSAN	Cole Information Services
	SHEA, G	Cole Information Services
	RIVERA, CRUZ	Cole Information Services
	WHISENHUNT, MICHAEL	Cole Information Services
	BATTINO, STELLA	Cole Information Services
	PENA, EDITH	Cole Information Services
	CONATY, MICHAEL	Cole Information Services
	CLARK, A G	Cole Information Services
	FENCOTT, GLADYS	Cole Information Services
	BARONOWSKI, PATRICIA	Cole Information Services
	ROHAN, JAMES	Cole Information Services
	CUSHING, JONNE	Cole Information Services
	ZELAYA, ALFREDO E	Cole Information Services
	CORDERO, RAMON	Cole Information Services
	HAMLIN, E C	Cole Information Services
	FREEMAN, D	Cole Information Services
	COTTO, L	Cole Information Services
1983	Acevedo Tumas	New York Telephone
	Acevedo Wilson	New York Telephone
	Alvarez Santos	New York Telephone
	Anselmo Elvira Mrs	New York Telephone
	Ayala M	New York Telephone
	Ayi Alon	New York Telephone
	Baron Edward	New York Telephone
	Bayout Pierre	New York Telephone
	Bell Chas A	New York Telephone
	Bell Mae	New York Telephone

FINDINGS

Year	Uses	Source
1983	Bender William & Joel	New York Telephone
	Bohan J	New York Telephone
	Brassil W C	New York Telephone
	Brodsky L	New York Telephone
	Brow n B	New York Telephone
	Burns M	New York Telephone
	Calandrino Jean	New York Telephone
	Campos Cristino	New York Telephone
	Carey Thos B	New York Telephone
	Carvalho Alvaro	New York Telephone
	Chung K	New York Telephone
	Corso Elvira	New York Telephone
	Craw ford Mary T Mrs	New York Telephone
	Cruz Evelisse	New York Telephone
	Cruz Francisco	New York Telephone
	Cummings Bernard Mrs	New York Telephone
	De Percin Agis J	New York Telephone
	De Shields O	New York Telephone
	Detres Juan	New York Telephone
	Dixon T	New York Telephone
	Donoghue Raymond J	New York Telephone
	Dw an Joseph	New York Telephone
	Fencott Gladys	New York Telephone
	Ferat David	New York Telephone
	Ferla Albina	New York Telephone
	Garcia N Mrs	New York Telephone
	Giliberto Andrew	New York Telephone
	Gill Abelino	New York Telephone
	Giner B	New York Telephone
	Gonzalez Gilbert A	New York Telephone
	Gonzalez Modesto	New York Telephone
	Gordon R Mrs	New York Telephone

FINDINGS

Year	Uses	Source
1983	Haddock T	New York Telephone
	Haniotis J	New York Telephone
	Hayes Roland A	New York Telephone
	Herencia Lucrecia	New York Telephone
	Hernandez I	New York Telephone
	Ho Team	New York Telephone
	Holmes M	New York Telephone
	Horton R C	New York Telephone
	Jameson tephan J	New York Telephone
	John Dorothy A	New York Telephone
	Jurin Geo	New York Telephone
	Kalomeris A	New York Telephone
	Kanuika M	New York Telephone
	Karger Jell	New York Telephone
	Kies Edith	New York Telephone
	Kleinman Hyman S	New York Telephone
	Kort Marie J	New York Telephone
	Kraft L	New York Telephone
	Kusey Evelyn	New York Telephone
	Ladin J	New York Telephone
	Lee H	New York Telephone
	Lew is Frank J	New York Telephone
	Looney D	New York Telephone
	Marra O	New York Telephone
	Marrero Juliana	New York Telephone
	Mathura Jaggernaut	New York Telephone
	Mc Bride P	New York Telephone
	Mc Callum M	New York Telephone
	Mc Carthy Beatrice M	New York Telephone
	Mc Lean Peter	New York Telephone
	Mc Mahon Catharine Mrs	New York Telephone
	Menaker F Enge	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1983	Miller Law rence	New York Telephone
	Molina Tomas	New York Telephone
	Montesdeoca Eduviges	New York Telephone
	Natoli Nino	New York Telephone
	Neary Jos T	New York Telephone
	OBrien B A	New York Telephone
	OHagen M	New York Telephone
	Pagano John	New York Telephone
	Palmarini S	New York Telephone
	Palmer V	New York Telephone
	Perez J L	New York Telephone
	Petrik Peter N	New York Telephone
	Piteo J	New York Telephone
	Pitt Annette Mrs	New York Telephone
	Poerio Frank	New York Telephone
	Pollock Susan Mrs	New York Telephone
	Regensburger Dorothy	New York Telephone
	Richter Maurice Mrs	New York Telephone
	Sanfratello M	New York Telephone
	Schuler Joseph	New York Telephone
	Schulman Saml	New York Telephone
	Scott Lillian H Mrs	New York Telephone
	Shea G	New York Telephone
	Solar Henry	New York Telephone
	Stephenson Tyson	New York Telephone
	Sw eiderk R	New York Telephone
	Synan Patrick	New York Telephone
	Terras A	New York Telephone
	Tominia Daniel Govrnrs Isl Tnovich A	New York Telephone
	Toomey H	New York Telephone
	Torres Angel	New York Telephone
	Tucker E	New York Telephone

Year	Uses	Source
1983	Tuohey T	New York Telephone
	Vadillo R	New York Telephone
	Valiente Osw ald E	New York Telephone
	Wax R S	New York Telephone
	Weiss Charles	New York Telephone
	Williams Robt Mrs	New York Telephone
	Williamson M	New York Telephone
	Zamora Virgil	New York Telephone
	Zelaya Alfredo E	New York Telephone

421 W 17TH ST

Year	Uses	Source
2014	CITY OF NEW YORK	Cole Information Services
2009	NEW YORK CITY HOUSING AUTHORITY	Cole Information Services
2006	h Sohanievich Oleg A	Hill-Donnelly Information Services
	New York City Housing	Hill-Donnelly Information Services
2004	NEW YORK CITY HOUSING AUTH	Cole Information Services
	OLEG SOHANIEVICH	Cole Information Services
2000	N Y CITY HOUSING	Cole Information Services
1999	N Y CITY OF HOUSING AUTHORITY	Cole Information Services
1994	CASTANO, DOLLY	Cole Information Services
	NUNEZ, MARIA	Cole Information Services
	NYC HOUSING AUTHORITY-PROJECTS-FULTON HSES	Cole Information Services
1983	Castano Dolly	New York Telephone

W 18 %

430 W 18 %

Year	Uses	Source
1958	GRIECO JOS & SONS WASTE PAPR W 18	New York Telephone

W 18 ST

400 W 18 ST

Year	Uses	Source
1978	AVIS TRUCK RENTAL	New York Telephone
1973	AVIS TRUCK RENTAL-	New York Telephone
1968	RINK DONALD	New York Telephone
1958	JG DISTRIBTG CO	New York Telephone
	JG DISTRIBTG CO	New York Telephone
1956	RAMIREZ J EXP	New York Telephone
	RODRIGUEZ JUAN GROCR	New York Telephone
	SPANISH EXPRESS	New York Telephone
1950	RAMIREZ J EXP	New York Telephone
	SPANISH EXPRESS	New York Telephone
1947	RAMIREZ J EXP	New York Telephone
	SPANISH EXPRESS	New York Telephone
1942	RAMIREZ J EXP	New York Telephone
	SPANISH EXPRESS	New York Telephone
1938	RMNIREZ J EXP	New York Telephone
	SPANISH EXPRESS	New York Telephone
1931	NEWTON MARY	Manhattan and Bronx Directory Publishing Company Residential Directory
	O TOOLE JOHN J	Manhattan and Bronx Directory Publishing Company Residential Directory
	SILVERMAN ISRAEL	Manhattan and Bronx Directory Publishing Company Residential Directory
	SILVERMAN MORRIS	Manhattan and Bronx Directory Publishing Company Residential Directory
	CRAWLEY DENNIS	Manhattan and Bronx Directory Publishing Company Residential Directory
	CROWLEY C	Manhattan and Bronx Directory Publishing Company Residential Directory

401 W 18 ST

Year	Uses	Source
1988	ACEVEDO EDWARD	NYNEX Telephone
	BARRAL EDW	NYNEX Telephone
	CANOSA ROCCO A	NYNEX Telephone

FINDINGS

Year	Uses	Source
1988	FLYNN CATHERINE	NYNEX Telephone
	HINNANT P	NYNEX Telephone
	MURPHY ROBT J	NYNEX Telephone
	NEDD STEPHANIE	NYNEX Telephone
	RIVERA NELIDA	NYNEX Telephone
	TUONEY ALBERT T	NYNEX Telephone
1983	BARRAL EDW	New York Telephone
	CANOSA ROCCO A	New York Telephone
	MURPHY ROBT J	New York Telephone
	NEDD LULA	New York Telephone
	SANTIAGO W	New York Telephone
	TUONEY ALBERT T	New York Telephone
1978	ALLENDORF DENNIS DR	New York Telephone
	BARRAL EDW	New York Telephone
	CANOSA ROCCO A	New York Telephone
	MURPHY ROBT J	New York Telephone
	NEDD CRAWFORD	New York Telephone
	OKEEFE R	New York Telephone
	SANTIAGO W	New York Telephone
1973	BARRAL EDW	New York Telephone
	BIANCO JAS JOS	New York Telephone
	CANOSA ROCCO A	New York Telephone
	CINGARI JOHN	New York Telephone
	DOARES WADE A	New York Telephone
	EDMONDS EDW	New York Telephone
	GROTE MARY	New York Telephone
	MATTHEWS E	New York Telephone
	MURPHY ROBT J	New York Telephone
	NEDD CRAWFORD	New York Telephone
	PEREIRA JOSE	New York Telephone
	SINGER CARL S	New York Telephone
	TAGUE KATHY	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1973	TUONEY ALBERT T	New York Telephone
	WALKER D	New York Telephone
1968	PEREIRA JOSE	New York Telephone
	RIVERA DORCAS	New York Telephone
	TUONEY ALBERT T	New York Telephone
	VASQUEZ HECTOR G	New York Telephone
	ZUPATA VIRGINIA MRS	New York Telephone
	BARRA EDW	New York Telephone
	BIANCO JAS JOS	New York Telephone
	CANOSA ROCCO A	New York Telephone
	CINGARI JOHN	New York Telephone
	GROTE MARY	New York Telephone
	HUJSA ROBT E	New York Telephone
	MURPHY ROBT J	New York Telephone
1958	BLAIR DAVID W	New York Telephone
	GRYGAO HENRY	New York Telephone
	RAPH JANET MRS	New York Telephone
1942	STEWART JOHN L MRS	New York Telephone
1931	CADUNZ CARLO	Manhattan and Bronx Directory Publishing Company Residential Directory
	CHEHRNI ARTH	Manhattan and Bronx Directory Publishing Company Residential Directory
	CONSIGLIO FRANK	Manhattan and Bronx Directory Publishing Company Residential Directory
	GROSSI MARIANO	Manhattan and Bronx Directory Publishing Company Residential Directory
	PIACENTINI K	Manhattan and Bronx Directory Publishing Company Residential Directory
	PIACENTINI M	Manhattan and Bronx Directory Publishing Company Residential Directory
	PIACENTINI PHIL	Manhattan and Bronx Directory Publishing Company Residential Directory
	ROGOVIN ALBERT	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

402 W 18 ST

Year	Uses	Source
1931	SHEEHAN MARY M	Manhattan and Bronx Directory Publishing Company Residential Directory
	SHEEHAN JOHN J	Manhattan and Bronx Directory Publishing Company Residential Directory

403 W 18 ST

Year	Uses	Source
1958	BARAHONA ALBERTO	New York Telephone
	BELL JAS	New York Telephone
	HASSETT JOS C	New York Telephone
	HERENCIA JULIO	New York Telephone
	KARAJICH ANTHONY	New York Telephone
	LUGO IRMA Z MRS	New York Telephone
	MATOS EDWARDO	New York Telephone
	OLCESE JOS J	New York Telephone
	PLACENTINI RAYMOND	New York Telephone
	RODRIGUEZ JOSE R	New York Telephone
	TOMINOVICH ANDREW	New York Telephone
	TORRES JOS J	New York Telephone
	ZECH KARL	New York Telephone
1956	OLCESE JOS J	New York Telephone
	PIACENTINI RAYMOND	New York Telephone
	RODRIGUEZ JOSE	New York Telephone
	SIDORICK ANN	New York Telephone
	STEFFANATOS BESSIE C	New York Telephone
	TORRES JOS J	New York Telephone
	BARAHONA ALBERTO	New York Telephone
	BARAHONA ALBERTO	New York Telephone
	BELL JAS	New York Telephone
	BLECICH DOMINIC	New York Telephone
	FRANCHAK MICHL	New York Telephone
	HASSETT JOS C	New York Telephone
	HERNANDEZ RAFAEL	New York Telephone

FINDINGS

Year	Uses	Source
1956	LAPUCH MICHL J	New York Telephone
	LUGO IRMA Z MRS	New York Telephone
1950	CLEVELAND AUTOMOTIVE PRODS CO	New York Telephone
	FARAGIRIA MARTIN	New York Telephone
	FRANK MICHL	New York Telephone
	HASSETT JOS	New York Telephone
	LOPEZ CLUDIA	New York Telephone
	PIACENTINI RAYMOND	New York Telephone
	ROBDAU LEO H	New York Telephone
	UNIT AUTO PARTS CO	New York Telephone
1947	HALSEY CERAMICS & LAMPS CO INC	New York Telephone
	MARTIN HELEN MRS	New York Telephone
	PLACENTINI GLORIA	New York Telephone
	ROBDAU CATHERINE E	New York Telephone
1927	AURELIO REALTY CORP	New York Telephone
	JONES MARY HELEN R	New York Telephone
	ROSSETTI N RL EST & INS	New York Telephone
	TOTO JOS R	New York Telephone

405 W 18 ST

Year	Uses	Source
1978	MASHECK J	New York Telephone
1963	REMAIL ROGER D	New York Telephone
	REMAIL GRACE B	New York Telephone
1958	MARGRO ANTHONY	New York Telephone
1956	LEWY GUENTER	New York Telephone
1950	O BRIEN DANL J	New York Telephone
	HEIGHTS PRNTNS CO	New York Telephone
1947	TRANSWORLD DISTRIBUTG CO INC EXPTRS	New York Telephone
1938	NY CITY OF CONTINUIED	New York Telephone
	BURCHARD ANNA T	New York Telephone
1931	ZINELL EDNA	Manhattan and Bronx Directory Publishing Company Residential Directory

Year	Uses	Source
1931	MCHUGH MICHL	Manhattan and Bronx Directory Publishing Company Residential Directory
	MCHUGH ANNIE	Manhattan and Bronx Directory Publishing Company Residential Directory
	ELMORE JOHN	Manhattan and Bronx Directory Publishing Company Residential Directory
	GARDNER PAUL	Manhattan and Bronx Directory Publishing Company Residential Directory
	MCCURLEY CARRIE	Manhattan and Bronx Directory Publishing Company Residential Directory
	CARLUCCI ANGELO	Manhattan and Bronx Directory Publishing Company Residential Directory
	COURTNAY EDITH	Manhattan and Bronx Directory Publishing Company Residential Directory

406 W 18 ST

Year	Uses	Source
1931	DICKER JOHN	Manhattan and Bronx Directory Publishing Company Residential Directory
	CONLIN MARY	Manhattan and Bronx Directory Publishing Company Residential Directory
	CONLIN EDW	Manhattan and Bronx Directory Publishing Company Residential Directory
	GORMLEY MARGERY	Manhattan and Bronx Directory Publishing Company Residential Directory
	MCCREERY MARY E	Manhattan and Bronx Directory Publishing Company Residential Directory
	O DONNELL JOHN	Manhattan and Bronx Directory Publishing Company Residential Directory
	SOHAR LILLIAN	Manhattan and Bronx Directory Publishing Company Residential Directory

407 W 18 ST

Year	Uses	Source
1958	VLACIC JANE	New York Telephone
	RUSSO VINCENT PLSTR MOULDR	New York Telephone
	RUBINICH GREGORY	New York Telephone
	LAUREANO ROSA MRS	New York Telephone
1956	VLACIC JANE	New York Telephone
	RUSSO VINCENT PLSTR MOULDR	New York Telephone
	RUBINICH GREGORY	New York Telephone

Year	Uses	Source
1956	RAMIREZ SALVADOR A	New York Telephone
	LARIACHE LUCINDA R	New York Telephone
	CEKADA ANGELA	New York Telephone
1950	ZWICHAROWSKL JOHN	New York Telephone
	VLACIC MARY	New York Telephone
	SANOUDES E G	New York Telephone
	RUSSO VINCENT PSTR MOULDR	New York Telephone
	MANOS IRENE MRS	New York Telephone
	DUFFY CATHERINE	New York Telephone
	BLAZINA MARY MRS	New York Telephone
	CEKADA ANGELA	New York Telephone
1947	RUSSO VINCENT PLSTR MOULDR	New York Telephone
1942	RUSSO VINCENT PISTR MOULDR	New York Telephone
1938	RUSSO VINCENT PLSTR MOULDR	New York Telephone
1927	SPANISH EXPRESS	New York Telephone
	RUSSO VINCENT PLASTER MOULDER	New York Telephone
	RAMIREZ J EXP D	New York Telephone
	KERR JOHN H R	New York Telephone
	ELMORE MARY MRS R	New York Telephone

408 W 18 ST

Year	Uses	Source
1958	MOORE RUSSELL	New York Telephone
1956	CUERVO JOS H	New York Telephone
	CISCOE BROUGH SARAH M FASHN STYLST	New York Telephone
1950	MCFADDEN THOS S	New York Telephone
	CUERVO JOS H	New York Telephone
1931	WATSON ATLER	Manhattan and Bronx Directory Publishing Company Residential Directory
	VAN WART MAE	Manhattan and Bronx Directory Publishing Company Residential Directory
	VAN WART EDW	Manhattan and Bronx Directory Publishing Company Residential Directory
	VAILLANCOURT E	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

Year	Uses	Source
1931	SHARKEY MARTHA F	Manhattan and Bronx Directory Publishing Company Residential Directory
	OMERA THOS	Manhattan and Bronx Directory Publishing Company Residential Directory
	O DONNELL MICHL	Manhattan and Bronx Directory Publishing Company Residential Directory
	O DONNELL ANNA	Manhattan and Bronx Directory Publishing Company Residential Directory
	MCDONALD JOS	Manhattan and Bronx Directory Publishing Company Residential Directory
	MCDONALD EDW	Manhattan and Bronx Directory Publishing Company Residential Directory
	MCCAHILL PATK	Manhattan and Bronx Directory Publishing Company Residential Directory
	MAGRO STELLA	Manhattan and Bronx Directory Publishing Company Residential Directory
	MAGRO DOMINICK	Manhattan and Bronx Directory Publishing Company Residential Directory
	HUGHES PATK	Manhattan and Bronx Directory Publishing Company Residential Directory
	HARTNETT THOS J	Manhattan and Bronx Directory Publishing Company Residential Directory
	DRISCOLL PATK	Manhattan and Bronx Directory Publishing Company Residential Directory
	COSTELLO MICHL J	Manhattan and Bronx Directory Publishing Company Residential Directory
	COSTELLO GRACE	Manhattan and Bronx Directory Publishing Company Residential Directory
	BUSBY MARGT	Manhattan and Bronx Directory Publishing Company Residential Directory
	BUSBY JAS	Manhattan and Bronx Directory Publishing Company Residential Directory
	BRICKMAN FRED	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	MCDONNELL D F R	New York Telephone
	MEILING GERTRUDE R	New York Telephone

409 W 18 ST

Year	Uses	Source
1958	KIMBALLS MOTOR DISPATCH INC	New York Telephone
1956	KIMBALL S MOTOR DISPATCH INC	New York Telephone
1950	IL & C CO TRUKNG	New York Telephone

Year	Uses	Source
1950	BERNSTEIN B L TRUKNG	New York Telephone
	ALBERT TRUCKING CO	New York Telephone
1947	ALBEE TRUCKING CO	New York Telephone
1931	KELLY KIERAN	Manhattan and Bronx Directory Publishing Company Residential Directory
	MCCAULEY HARRY	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	GILL HARRY R	New York Telephone

410 W 18 ST

Year	Uses	Source
1958	MOHEDANO LNEZ MRS	New York Telephone
1956	GALARA ATILANO T	New York Telephone
	JIMENEZ THAS	New York Telephone
	MOHEDANO INEZ MRS	New York Telephone
1950	SANDOVAL EDELMIRA	New York Telephone
1938	SIMON JOHN	New York Telephone
1931	CUMMINS CHAS	Manhattan and Bronx Directory Publishing Company Residential Directory

411 W 18 ST

Year	Uses	Source
1988	ARNEEL MARY	NYNEX Telephone
	CHAPMAN ROBT	NYNEX Telephone
	CHAU GIM CHIU	NYNEX Telephone
	CRAWLEY JOS H	NYNEX Telephone
	FONSECA	NYNEX Telephone
	GONZALEZ G	NYNEX Telephone
	GORNAY ANTHONY P	NYNEX Telephone
	MAK YUEN	NYNEX Telephone
	NATAL ANTONIA	NYNEX Telephone
	O CONNELL JAS	NYNEX Telephone
	ORFANOS DEMETRIOS	NYNEX Telephone
	SUAREZ MONICA	NYNEX Telephone
	TELESCO ROSE	NYNEX Telephone

FINDINGS

Year	*Uses*	*Source*
1983	ARNEEL JEANNE	New York Telephone
	CHAPMAN ROBT	New York Telephone
	CRAWLEY JOS H	New York Telephone
	GORNAY ANTHONY P	New York Telephone
	MARTINEZ A	New York Telephone
	NATAL ANTONIA	New York Telephone
	OCONNELL JAS	New York Telephone
	ORFANOS DEMETRIOS	New York Telephone
	OSORIO ELIZABETH	New York Telephone
	SCHIFF LEWIS A	New York Telephone
	TELESCO ROSE	New York Telephone
1978	CHAPMAN ROBT	New York Telephone
	CRAWLEY JOS H	New York Telephone
	EDMONDS EDW	New York Telephone
	GORNAY ANTHONY P	New York Telephone
	MARTINEZ A	New York Telephone
	O CONNELL JAS	New York Telephone
	ORFANOS DE METRIOS	New York Telephone
	RODRIGUEZ MARTA	New York Telephone
	SCHIFF LEWIS A	New York Telephone
	TELESIO ROSE	New York Telephone
1973	MARTINEZ A	New York Telephone
	MARTINEZ MARTIN	New York Telephone
	OCONNELL JAS	New York Telephone
	ORFANOS DE METRIOS	New York Telephone
	SCHIFF LEWIS A	New York Telephone
	SILVESTRI JOHN	New York Telephone
	TELESCO ROSE	New York Telephone
	CHAPMAN ROBT	New York Telephone
	DELGADO JESUS	New York Telephone
	GORNAY ANTHONY P	New York Telephone
1968	CRAWLEY JOS H	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1968	DELGADO JESUS	New York Telephone
	GORNAY ANTHONY P	New York Telephone
	MAHONEY LORRAINE M	New York Telephone
	MARTINEZ MARTIN	New York Telephone
	ORFANOS DEMETRIOS	New York Telephone
	YANAS T R	New York Telephone
1963	SIMMONS EURISE L MRS	New York Telephone
1958	CHERPIN MARGUERITE	New York Telephone
	COURAHANIS EFFIE MRS	New York Telephone
	EICHEN ROSE	New York Telephone
	HENKEL JAS	New York Telephone
	HENKEL JAS	New York Telephone
	JURIN GEO	New York Telephone
	LAWLER HELEN MRS	New York Telephone
	MANN F L	New York Telephone
	MILONE JOS	New York Telephone
	NUSIMOVICH MOSES	New York Telephone
	PEREZ ELISEO	New York Telephone
1956	AGLIETTI EDITH MRS	New York Telephone
	AMPAGOOMIAN ZAKAR	New York Telephone
	CHERPIN M MRS	New York Telephone
	COURAHANIS EFFIE MRS	New York Telephone
	EICHEN ROSE	New York Telephone
	JURIN GEO	New York Telephone
	LAWLER HELEN MRS	New York Telephone
	MANN F L	New York Telephone
	MILONE JOS	New York Telephone
	PEREZ ELISEO	New York Telephone
1950	AGLIETTI EDITH MRS	New York Telephone
	BOYESON FRED	New York Telephone
	ELCHEN ROSE	New York Telephone
	LAWLER HELEN MRS	New York Telephone

FINDINGS

Year	Uses	Source
1950	MILONE JOS	New York Telephone
	SANCHEZ DELFINA	New York Telephone
	TERRANOVA MURIEL	New York Telephone
1947	BOYESON FRED	New York Telephone
1938	TOTO LAWRENCE	New York Telephone
1931	BRADY ANDREW	Manhattan and Bronx Directory Publishing Company Residential Directory
	DALL JENNIE	Manhattan and Bronx Directory Publishing Company Residential Directory
	DALL WM J	Manhattan and Bronx Directory Publishing Company Residential Directory
	DONOVAN MARCELLA	Manhattan and Bronx Directory Publishing Company Residential Directory
	HARTNETT MARY A	Manhattan and Bronx Directory Publishing Company Residential Directory
	LEE PATK	Manhattan and Bronx Directory Publishing Company Residential Directory
	LUND ALMA	Manhattan and Bronx Directory Publishing Company Residential Directory
	LUND HARRY C	Manhattan and Bronx Directory Publishing Company Residential Directory
	MONOHAN GEO	Manhattan and Bronx Directory Publishing Company Residential Directory
	PISCOS TOHNS	Manhattan and Bronx Directory Publishing Company Residential Directory
	SULLIVAN NELLIE E	Manhattan and Bronx Directory Publishing Company Residential Directory
	UPTON B JAS BKBNDR DEPT FIN	Manhattan and Bronx Directory Publishing Company Residential Directory
	UPTON JAS B	Manhattan and Bronx Directory Publishing Company Residential Directory
	UPTON JANE	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	EGERLAND DORA MRS R	New York Telephone
	KOETHER WM R	New York Telephone
	LUND ALMA SCHUMAN R	New York Telephone
	WATTS A M MRS R	New York Telephone

412 W 18 ST

Year	Uses	Source
1958	GERMADE JOS	New York Telephone

Year	Uses	Source
1958	AMPAGOOMIAN ZAKAR	New York Telephone
1956	GERMADE JOS	New York Telephone
1950	ARCE MARIA P MRS	New York Telephone
1927	REILLY KATE MRS R	New York Telephone

413 W 18 ST

Year	Uses	Source
1956	HENKEL MAUREEN	New York Telephone

414 W 18 ST

Year	Uses	Source
1958	ALVAREZ SANTOS	New York Telephone
1956	ALVAREZ CECILIA	New York Telephone
1950	ALVAREZ SERVANDA	New York Telephone
	DOUGHTY G F B	New York Telephone
1947	ALVAREZ SERVANDA	New York Telephone
1942	ALVAREZ SERVANDA	New York Telephone
1938	YOUNG LOUISE M MRS	New York Telephone
	WILSON FRANCIS A	New York Telephone

415 W 18 ST

Year	Uses	Source
1983	GROSS AMES	New York Telephone
1978	CAMPBELL R	New York Telephone
1968	MALONEY WM H JR	New York Telephone
1963	MULLER DORIS MRS	New York Telephone
1958	CAMPBELL WM J	New York Telephone
	MORAN JULIETE M	New York Telephone
	RAMIREZ EULALIA	New York Telephone
1956	IZAGUIRRE ADAM	New York Telephone
	PAUL CHRSTPHR	New York Telephone
1950	BARLETT RAYMOND	New York Telephone
	BARTLETT RAYMOND	New York Telephone
	JURIN THELMA	New York Telephone

Year	Uses	Source
1947	DOMBROWSKI HENRY J	New York Telephone
	PAUL JOHN	New York Telephone
1938	AVRUTIS A	New York Telephone
	BAILEY ARLENE R	New York Telephone
1931	CARLUCCI LEONARDO	Manhattan and Bronx Directory Publishing Company Residential Directory
	MCNEARNEY ANNA	Manhattan and Bronx Directory Publishing Company Residential Directory
	REILLY F	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	BECK JOS ELEC CONTR	New York Telephone

416 W 18 ST

Year	Uses	Source
1958	DILLON WILTON S	New York Telephone
	MENDEZ FRANK	New York Telephone
1956	MENDEZ FRANK	New York Telephone
1950	MENDEZ FRANK	New York Telephone
1947	MENDEZ FRANK	New York Telephone
1942	MENDEZ FRANK	New York Telephone
1931	MOSSMANS CASPER C	Manhattan and Bronx Directory Publishing Company Residential Directory
	GRAHAM THOS	Manhattan and Bronx Directory Publishing Company Residential Directory
	BARRIE ANDREW	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	DEBELLIS VINCENT R	New York Telephone

417 W 18 ST

Year	Uses	Source
1973	OTERO PABLO	New York Telephone
1958	TOMLINSON WM	New York Telephone
	KING HAROLD J	New York Telephone
	KERINS DOROTHY	New York Telephone
	FARRELL SARAH MRS	New York Telephone
	DELANEY FRANK	New York Telephone
1956	TOMLINSON WM	New York Telephone

FINDINGS

Year	Uses	Source
1956	SANTASIRO ALFRED	New York Telephone
	KERINS DOROTHY	New York Telephone
	HARRIS GEO MISS	New York Telephone
	FARRELL SARAH MRS	New York Telephone
	CUMMINGS VIVIAN	New York Telephone
1950	TOMLINSON WM	New York Telephone
	KERINS JOHN T	New York Telephone
	COX PETER T	New York Telephone
	BRAUT NICHOLAS	New York Telephone
1938	BRUNNER E K MRS	New York Telephone
1931	WOLFE THERESA	Manhattan and Bronx Directory Publishing Company Residential Directory
	WOLFE DANL	Manhattan and Bronx Directory Publishing Company Residential Directory
	SWEENEY MARY	Manhattan and Bronx Directory Publishing Company Residential Directory
	SWEENEY FRANCIS	Manhattan and Bronx Directory Publishing Company Residential Directory
	QUINN MARGT E	Manhattan and Bronx Directory Publishing Company Residential Directory
	MARKHAM STEPHEN F LAB	Manhattan and Bronx Directory Publishing Company Residential Directory
	QUINN J B	Manhattan and Bronx Directory Publishing Company Residential Directory
	QUINN JOS	Manhattan and Bronx Directory Publishing Company Residential Directory
	BRENNAN PATK	Manhattan and Bronx Directory Publishing Company Residential Directory
	FARIER DELLA	Manhattan and Bronx Directory Publishing Company Residential Directory
	FARRELL FRANK	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	WALTON STILLMAN B R	New York Telephone
	SWEENEY F X R	New York Telephone

418 W 18 ST

Year	Uses	Source
1958	SCHNEIDER MARIA	New York Telephone
	NOWAK ARTHUR	New York Telephone

FINDINGS

Year	Uses	Source
1956	CARDELL SERAFIN	New York Telephone
1950	MOORE FRANK R	New York Telephone
	DUBOIS WINNIFRED	New York Telephone
1931	WALTERS CLARENCE	Manhattan and Bronx Directory Publishing Company Residential Directory
	PANNAL JAS W	Manhattan and Bronx Directory Publishing Company Residential Directory
	LACY JOHN	Manhattan and Bronx Directory Publishing Company Residential Directory
	FRANKLIN HENRY	Manhattan and Bronx Directory Publishing Company Residential Directory
	BROWN SAML	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	TYSON JOHN J R	New York Telephone

419 W 18 ST

Year	Uses	Source
1973	VIZCARRONDO PAUL	New York Telephone
1968	GARCIA CARMEN B MRS	New York Telephone
1963	TWERSKY RICKI	New York Telephone
1958	VESELIZZA JACK	New York Telephone
	SATRE HANS	New York Telephone
	KRIPAROS JAS	New York Telephone
	BUCICH AVELINO	New York Telephone
	BRENNAN PATK J	New York Telephone
1956	BRENNAN PATK J	New York Telephone
	KRIPAROS JAS	New York Telephone
	SATRE HANS	New York Telephone
	STEIMEL HENRY	New York Telephone
	STEIMEL WM	New York Telephone
1950	STEIMEL HENRY	New York Telephone
	SATRE HANS	New York Telephone
	KRIPAROS JOSEPHINE	New York Telephone
	BRENNAN PATK J	New York Telephone
1938	MISKELL MAE J MRS	New York Telephone

FINDINGS

Year	Uses	Source
1931	DUENSKI JOS	Manhattan and Bronx Directory Publishing Company Residential Directory
	DRODHEAD ELIZ	Manhattan and Bronx Directory Publishing Company Residential Directory

421 W 18 ST

Year	Uses	Source
1978	SHAH SHEKHAR	New York Telephone
1958	COUGHLIN JOHN	New York Telephone
	DUNHAM ROBT C	New York Telephone
	GILCHRIST ELIZ MRS	New York Telephone
	KANE M L	New York Telephone
	PARSONS MARY P	New York Telephone
	PEREZ FRANCISCO M	New York Telephone
	SEAMAN GEO C	New York Telephone
	TEMPLE ROBT	New York Telephone
1956	COUGHLIN JOHN	New York Telephone
	DUNHAM ROBT C	New York Telephone
	GILCHRIST ELIZ MRS	New York Telephone
	GOMEZ JOSE	New York Telephone
	KANE M L	New York Telephone
	KING HAROLD	New York Telephone
	QUIJANO VICTOR MANUEL	New York Telephone
1950	K & K TRUCKING & DELIVERY CO	New York Telephone
	KANE M L	New York Telephone
	KING HAROLD	New York Telephone
	MAHONEY FRANCIS J ATTY	New York Telephone
	MURTHA CATHERINE V	New York Telephone
	CONNORS MARGARET M RS	New York Telephone
	FOSTER LAURA M	New York Telephone
	GLOBE EQUIP CO	New York Telephone
1947	K & K TRUCKING & DELIVERY CO	New York Telephone
	KANE M L	New York Telephone
	MAHONEY FRANCIS J LWYR	New York Telephone

FINDINGS

Year	Uses	Source
1947	MURTHA CATHERINE V	New York Telephone
1942	KANE M L	New York Telephone
	MAHONEY FRANCIS J LWYR	New York Telephone
1938	GARRITY C MRS CANDY	New York Telephone
	KANE M L	New York Telephone
1931	CONWAY DELIA	Manhattan and Bronx Directory Publishing Company Residential Directory
	CONWAY JAS	Manhattan and Bronx Directory Publishing Company Residential Directory
	CONWAY PATR	Manhattan and Bronx Directory Publishing Company Residential Directory
	FITZPATRICK ROBT	Manhattan and Bronx Directory Publishing Company Residential Directory
	GRAHAM BRIDGET	Manhattan and Bronx Directory Publishing Company Residential Directory
	KANE MARY	Manhattan and Bronx Directory Publishing Company Residential Directory
	MURTHA CATH	Manhattan and Bronx Directory Publishing Company Residential Directory
	MURTHA MARY	Manhattan and Bronx Directory Publishing Company Residential Directory
	SPANGLER DANL	Manhattan and Bronx Directory Publishing Company Residential Directory
	TOOHEY J J	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	ANCHOR B CIGARS	New York Telephone
	DREYER A SCRAP METAL	New York Telephone
	GARABEDIAN PAUL GROCER	New York Telephone
	KANE M L R	New York Telephone

422 W 18 ST

Year	Uses	Source
1958	ARMADA IMPOTERS INC	New York Telephone
1956	ARMADA IMPORTERS INC	New York Telephone
1947	K & T DISTRIBUTG CO OFC	New York Telephone
1931	SMITH JAS	Manhattan and Bronx Directory Publishing Company Residential Directory
	PUGLIESI JOS G	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

Year	Uses	Source
1931	LEVY MORRIS	Manhattan and Bronx Directory Publishing Company Residential Directory
	LENNON JAS	Manhattan and Bronx Directory Publishing Company Residential Directory
	HALL JOHN H	Manhattan and Bronx Directory Publishing Company Residential Directory
	AMNELIOS THOS	Manhattan and Bronx Directory Publishing Company Residential Directory
	CRUMIN PETER	Manhattan and Bronx Directory Publishing Company Residential Directory

423 W 18 ST

Year	Uses	Source
1988	COLUMBIA UNIV	NYNEX Telephone
	SHILOFF D	NYNEX Telephone
1983	SCHREIBER MAYO JR	New York Telephone
1978	KORNFIELD ROSE MRS	New York Telephone
1963	SIMMS R M MRS	New York Telephone
	KINSINGER ROHT E DIR	New York Telephone
	FOX BERNARD	New York Telephone
1958	WALSH WALTER J	New York Telephone
	SUSSMANN PAULA MRS	New York Telephone
	O NEILL DENNIS	New York Telephone
	O BRIEN MARGARET E	New York Telephone
	NORMILE HARRY	New York Telephone
	DUNNE JAS S	New York Telephone
	MURPHY THOS J	New York Telephone
1956	MURPHY THOS J	New York Telephone
	O BRIEN MARGARET E	New York Telephone
	O NEILL DENNIS	New York Telephone
	WALSH WALTER J	New York Telephone
1950	MURPHY THES J	New York Telephone
	ONEILL DENNIS	New York Telephone
	STROSSNER ALFRED	New York Telephone
1947	MURPHY THOS J	New York Telephone
	O BRIEN MARGARET E	New York Telephone

Year	Uses	Source
1942	O BRIEN MARGARET E	New York Telephone
1931	DOYLE CHRISTOPHER	Manhattan and Bronx Directory Publishing Company Residential Directory
	DOYLE MARY	Manhattan and Bronx Directory Publishing Company Residential Directory
	MCGOWAN JOHN F	Manhattan and Bronx Directory Publishing Company Residential Directory
	O CONNOR THOS PAVER P B M	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	CONWAY ELIZABETH R	New York Telephone

424 W 18 ST

Year	Uses	Source
1958	DRAYER A SCRAP METAL	New York Telephone
	DREYER GEO SCRAP MTL	New York Telephone
	DRYLEE PLASTIC CO INC	New York Telephone
	WOODLAWN METAL CO	New York Telephone
1956	BATES BRAINERD S	New York Telephone
	DREYER A SCRAP METAL	New York Telephone
	DREYER GEO SCRAP MTL	New York Telephone
	DRYLEE PLASTIC CO INC	New York Telephone
	GUERRERO JOSE	New York Telephone
	WOODLAWN METAL CO	New York Telephone
1950	DREYER A SCRAP METAL	New York Telephone
	DREYER GEO SCRAP MTL	New York Telephone
	FLOCKING & NOVELTY SILK SCREEN CO	New York Telephone
	TALBOT WM SCLPTR	New York Telephone
	WOODLAWN METAL CO	New York Telephone
1947	DREYER A SCRAP METAL	New York Telephone
	DREYER GEO SCRAP MTL	New York Telephone
	FLOCKING & NOVELTY SILK SCREEN CO	New York Telephone
	TALBOT WM SCLPTR	New York Telephone
	WOODLAWN METAL CO	New York Telephone
1942	CERTOX PRODS CO	New York Telephone
	DREYER A SCRAP METAL	New York Telephone

Year	Uses	Source
1942	DREYER GEO SCRAP MTL	New York Telephone
	WOODLAWN METAL CO	New York Telephone
	YORK CHEMCL CO	New York Telephone
1938	CERTOX PRODS CO	New York Telephone
	DREYER GEO SCINP MTL	New York Telephone
	WOODLAWN METAL CO	New York Telephone
	YORK CHEMCL CO	New York Telephone
1931	DEVINE JAS J	Manhattan and Bronx Directory Publishing Company Residential Directory
	KEARNS DANL F	Manhattan and Bronx Directory Publishing Company Residential Directory
	TYRSELL ALEX	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	DREYER GEO SCRAP MTL	New York Telephone
	POSITIVE CHEMICAL & DISINFECTING CO	New York Telephone
	WOODLAWN METAL CO	New York Telephone

425 W 18 ST

Year	Uses	Source
1983	CHRISTOPHER ARTHUR M	New York Telephone
1978	CHRISTOPHER ARTHUR M	New York Telephone
1973	CHRISTOPHER ARTHUR M	New York Telephone
1968	CHRISTOPHER ARTHUR M	New York Telephone
1963	CHRISTOPHER ARTHUR M	New York Telephone
1958	WEADOCK ED W	New York Telephone
	VLACICH BANI	New York Telephone
	MURPHY ROBT J	New York Telephone
	HEALY THOS	New York Telephone
	CHRISTOPHER ARTHUR M	New York Telephone
	BULGER JAS	New York Telephone
1956	SLEVIN ANN M	New York Telephone
	CHRISTOPHER ARTHUR M	New York Telephone
	BULGER JAS	New York Telephone
1950	WEADOCK EDW	New York Telephone
	KENNY RICHD J	New York Telephone

FINDINGS

Year	Uses	Source
1950	CHRISTOPHER ARTHUR M	New York Telephone
	BEGGS MARGARET	New York Telephone
1947	HEALY THOS MRS	New York Telephone
	KENNY RICHD J	New York Telephone
1942	NETHERCOTT ADELAIDE MRS	New York Telephone
1931	COYNE PETER	Manhattan and Bronx Directory Publishing Company Residential Directory
	DONOVAN ELLEN	Manhattan and Bronx Directory Publishing Company Residential Directory
	DONOVAN JAS	Manhattan and Bronx Directory Publishing Company Residential Directory
	DONOVAN MARY	Manhattan and Bronx Directory Publishing Company Residential Directory
	DONOVAN PATK	Manhattan and Bronx Directory Publishing Company Residential Directory
	KOBERLEIN ANNA	Manhattan and Bronx Directory Publishing Company Residential Directory
	MCGLONE ANNA	Manhattan and Bronx Directory Publishing Company Residential Directory
	MORAN JAS	Manhattan and Bronx Directory Publishing Company Residential Directory
	SULLIVAN CATH	Manhattan and Bronx Directory Publishing Company Residential Directory
	CARR HERBERT	Manhattan and Bronx Directory Publishing Company Residential Directory
	CARR HERBERT J MACH FIRE DEPT	Manhattan and Bronx Directory Publishing Company Residential Directory

426 W 18 ST

Year	Uses	Source
1988	REIGADA VICENTA	NYNEX Telephone
1958	TURNER JOHN	New York Telephone
	KEDEKIAN MESROP	New York Telephone
1956	PAIGE RICHD	New York Telephone
	CURTISS WESLEY	New York Telephone
	TURNER JOHN	New York Telephone
1950	TURNER JOHN	New York Telephone
	PAIGE RICHD	New York Telephone
1947	TURNER JOHN	New York Telephone

FINDINGS

Year	Uses	Source
1947	PAIGE RICHD	New York Telephone
	PAIGE JOHN A	New York Telephone
1942	SWAN DAN	New York Telephone
1938	PAIGE RICHD	New York Telephone
1931	TURNER MARGT J	Manhattan and Bronx Directory Publishing Company Residential Directory
	TURNER JOHN	Manhattan and Bronx Directory Publishing Company Residential Directory
	SLEVIN JOHN	Manhattan and Bronx Directory Publishing Company Residential Directory
	SLEVIN ANNA	Manhattan and Bronx Directory Publishing Company Residential Directory
	RYAN MARGT	Manhattan and Bronx Directory Publishing Company Residential Directory
	RYAN DENIS	Manhattan and Bronx Directory Publishing Company Residential Directory
	ROGERS JAS	Manhattan and Bronx Directory Publishing Company Residential Directory
	MONAHAN MARY	Manhattan and Bronx Directory Publishing Company Residential Directory
	MONAHAN JULIA	Manhattan and Bronx Directory Publishing Company Residential Directory
	MONAHAN JOHN	Manhattan and Bronx Directory Publishing Company Residential Directory
	MANGAN JOHN	Manhattan and Bronx Directory Publishing Company Residential Directory
	JORDAN THOS	Manhattan and Bronx Directory Publishing Company Residential Directory
	JORDAN MARGT M	Manhattan and Bronx Directory Publishing Company Residential Directory
	DUFFY LAWRENCE	Manhattan and Bronx Directory Publishing Company Residential Directory
	DONAHUE JAS	Manhattan and Bronx Directory Publishing Company Residential Directory
	CROWLEY J	Manhattan and Bronx Directory Publishing Company Residential Directory
	COSTELLA JULIA	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	STACK THOS M R	New York Telephone
	TURNER MARGARET R	New York Telephone

FINDINGS

427 W 18 ST

Year	*Uses*	*Source*
1958	SCHUITEMA NICHOLAS	New York Telephone
	MOHEDANO CANDIDO MRS	New York Telephone
	MAXFIELD IRENE	New York Telephone
	LEONARD MURIEL M MRS	New York Telephone
	KANAZAWA MANIE	New York Telephone
	HIGGINS J	New York Telephone
	FUKAGAWA MANIE	New York Telephone
1956	MOHEDANO CANDIDO MRS	New York Telephone
	MAXFIELD IRENE	New York Telephone
	LEONARD MURIEL M MRS	New York Telephone
	KANAZAWA MANIE	New York Telephone
	HIGGINS J	New York Telephone
	FUKAGAWA MANIE	New York Telephone
	CAHILL EDGAR J	New York Telephone
1950	MOHEDANO CANDIDO MRS	New York Telephone
	MAXFIELD IRENE H	New York Telephone
	LEONARD MURIEL M MRS	New York Telephone
	KANAZAWA MANIE	New York Telephone
	HIGGINS J	New York Telephone
	FUKAGAWA MANIE	New York Telephone
1947	SCOTT HARRY A	New York Telephone
	NAKANO YUKI MRS	New York Telephone
	HIGGINS J	New York Telephone
1931	BOLSTER JAS	Manhattan and Bronx Directory Publishing Company Residential Directory
	CASEY ANNA	Manhattan and Bronx Directory Publishing Company Residential Directory
	COX FRANCES	Manhattan and Bronx Directory Publishing Company Residential Directory
	DEVLIN JOS	Manhattan and Bronx Directory Publishing Company Residential Directory
	HICKEY ELIZ	Manhattan and Bronx Directory Publishing Company Residential Directory
	HICKEY JOHN	Manhattan and Bronx Directory Publishing Company Residential Directory

Year	Uses	Source
1931	RYAN JOSEPHINE	Manhattan and Bronx Directory Publishing Company Residential Directory
	RYAN PATK	Manhattan and Bronx Directory Publishing Company Residential Directory
	SPARKS JOHN	Manhattan and Bronx Directory Publishing Company Residential Directory
	TRUCEY ESTHER	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	CASEY E R R	New York Telephone

428 W 18 ST

Year	Uses	Source
1958	WARWICK THOS M	New York Telephone
	JENKIN CONTRACTC CO INC	New York Telephone
	CLATIRGLIILORG H	New York Telephone
	ARNOLD ROY	New York Telephone
1956	LIGHTHOUSE FLASHER CO	New York Telephone
	BETTS & BETTS CORP ELECTRCL MFRS	New York Telephone
1950	LIGHTHOUSE FLASHER CO	New York Telephone
	BETTS & BETTS CORP ELECTRCL SPCLTS	New York Telephone
1942	MORRISSEY LUKE F	New York Telephone
1931	HOUGHTALING MARY J	Manhattan and Bronx Directory Publishing Company Residential Directory
	WEGMAN ALB	Manhattan and Bronx Directory Publishing Company Residential Directory
	WEGMAN ANNA	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	HOUGHTALING MARY J MRS R	New York Telephone

429 W 18 ST

Year	Uses	Source
1958	MALLEN EVELYN S MRS	New York Telephone
	LEVENTOYANNIS KATHERINE	New York Telephone
	KENNEY RAYMOND	New York Telephone
	KELLBACH MARIE MRS	New York Telephone
1956	LEVENTOYANNIS KATHERINE	New York Telephone
	WATERS J	New York Telephone
	INGRAM JAS D	New York Telephone

FINDINGS

Year	Uses	Source
1956	INGRAM W	New York Telephone
1950	GRAHAM JOHN	New York Telephone
1947	STOCKMAN EDW L	New York Telephone
	LEONARD MURIEL M MRS	New York Telephone
	GRAHAM JOHN	New York Telephone
	CARNEY THOS F	New York Telephone
1942	GRAHAM JOHN	New York Telephone
1931	O LEARY HELEN	Manhattan and Bronx Directory Publishing Company Residential Directory
	MCDOUGAL JAS	Manhattan and Bronx Directory Publishing Company Residential Directory
	DALL REBECCA	Manhattan and Bronx Directory Publishing Company Residential Directory
	DALL NORMAN	Manhattan and Bronx Directory Publishing Company Residential Directory
	DALL MARY	Manhattan and Bronx Directory Publishing Company Residential Directory

430 W 18 ST

Year	Uses	Source
1958	STAR WASTE PAPR CO	New York Telephone
1956	STAR WASTE PAPR CO	New York Telephone
	REDD JEAN C	New York Telephone
	GRIECO JOS & SONS WASTE PAPR	New York Telephone
1950	COLLINS VINCENT P MD	New York Telephone
	STAR WASTE PAPR CO	New York Telephone
	GRIECO JOS & SONS WASTE PAPR	New York Telephone
1947	STAR WASTE PAPR CO	New York Telephone
1938	OBERMAN SAM	New York Telephone
1931	FAULKNER EDW	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	PRESSER A W USN	New York Telephone
	GRAY EDEN R	New York Telephone
	COHEN LESTER R	New York Telephone
	BOWER S NOVELTIES	New York Telephone

FINDINGS

431 W 18 ST

Year	*Uses*	*Source*
1958	KATZ A	New York Telephone
	SMITH MATTHEW	New York Telephone
	WIRTH EMILIE MRS	New York Telephone
1956	FISHBACH FRANCES M MRS	New York Telephone
	KATZ A	New York Telephone
	KENNEY RAYMOND	New York Telephone
	MORIARTY DANL	New York Telephone
	MUNRO MIGNON MRS	New York Telephone
	SMITH MATTHEW	New York Telephone
	WIRTH EMILIE MRS	New York Telephone
1950	FISHBACH FRANCES N MRS	New York Telephone
	MORIARTY DANL	New York Telephone
	SMITH MATHEW	New York Telephone
	TENDICK LOIS	New York Telephone
	TETSUEWARI K	New York Telephone
	TETZSUWARI K	New York Telephone
	WIRTH EMILE MRS	New York Telephone
1947	LANDIS RUTH	New York Telephone
	O NEILL A MISS	New York Telephone
1942	O NEILL A MISS	New York Telephone
1938	O NEIL A MISS	New York Telephone
1931	WALKER BERTHA	Manhattan and Bronx Directory Publishing Company Residential Directory
	CALDWELL JAS F	Manhattan and Bronx Directory Publishing Company Residential Directory
	JACKSON HERVERT	Manhattan and Bronx Directory Publishing Company Residential Directory
	MCCUE THOS	Manhattan and Bronx Directory Publishing Company Residential Directory
	STAMARD JOS S	Manhattan and Bronx Directory Publishing Company Residential Directory
	STANNARD JAS	Manhattan and Bronx Directory Publishing Company Residential Directory
	TALBOT JAS E	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

433 W 18 ST

Year	Uses	Source
1958	FUJII YUKIO	New York Telephone
	GUCK EDNA	New York Telephone
1956	GUCK EDNA	New York Telephone
1950	ROHAN JOSEPHINE M MRS	New York Telephone
	KENNY JOHN P	New York Telephone
	GUCK EDNA	New York Telephone
	ANDREWS GEO	New York Telephone
1947	ROHAN JOSEPHINE M MRS	New York Telephone

W 180 ST

420 W 180 ST

Year	Uses	Source
1931	SHELDRICK ELIZ	Manhattan and Bronx Directory Publishing Company Residential Directory

W 18TH

402 W 18TH

Year	Uses	Source
1931	Sheehan John J	Manhattan and Bronx Directory Publishing Company Residential Directory
	Sheehan Mary M	Manhattan and Bronx Directory Publishing Company Residential Directory
1920	Boyle Daniel eng	R. L. Polk & Co.

403 W 18TH

Year	Uses	Source
1927	Aurelio Realty Corp	New York Telephone
	Jones Mary Helen r	New York Telephone
	Rossetti N rl est & ins	New York Telephone
	Toto Jos r	New York Telephone
1920	Adler Rubin variety	R. L. Polk & Co.
	Toto Jos	R. L. Polk & Co.
	Hanauer Wm C meats	R. L. Polk & Co.

FINDINGS

405 W 18TH

Year	*Uses*	*Source*
1931	Carlucci Angelo	Manhattan and Bronx Directory Publishing Company Residential Directory
	Courtnay Edith	Manhattan and Bronx Directory Publishing Company Residential Directory
	Zinell Edna	Manhattan and Bronx Directory Publishing Company Residential Directory
	Mc Hugh Michl	Manhattan and Bronx Directory Publishing Company Residential Directory
	Mc Hugh Annie	Manhattan and Bronx Directory Publishing Company Residential Directory
	Mc Curley Carrie	Manhattan and Bronx Directory Publishing Company Residential Directory
	Gardner Paul	Manhattan and Bronx Directory Publishing Company Residential Directory
	Elmore John	Manhattan and Bronx Directory Publishing Company Residential Directory
1923	Vaccaro Louis shoe parlor	R. L. Polk & Co.
1920	Farmanian Paul A gro	R. L. Polk & Co.
	Urband Bernard Urband Leather Goods Co	R. L. Polk & Co.
	Farmanian Paul A gro	R. L. Polk & Co.

406 W 18TH

Year	*Uses*	*Source*
1931	Conlin Edw	Manhattan and Bronx Directory Publishing Company Residential Directory
	Conlin Mary	Manhattan and Bronx Directory Publishing Company Residential Directory
	Dicker John	Manhattan and Bronx Directory Publishing Company Residential Directory
	Gormley Margery	Manhattan and Bronx Directory Publishing Company Residential Directory
	Mc Creery Mary E	Manhattan and Bronx Directory Publishing Company Residential Directory
	ODonnell John	Manhattan and Bronx Directory Publishing Company Residential Directory
	Sohar Lillian	Manhattan and Bronx Directory Publishing Company Residential Directory
1923	Smith Wm H	R. L. Polk & Co.
1920	Riegert Raymond C printer	R. L. Polk & Co.
	McNamara Jas J	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1920	Law rence	R. L. Polk & Co.
	Riegg Richd Schelling & Reigg h W N Y N J	R. L. Polk & Co.
	Smith Wm H w ood	R. L. Polk & Co.

407 W 18TH

Year	Uses	Source
1934	Zahtila John Mary gro	R. L. Polk & Co.
	Russo Vincent plaster casts	R. L. Polk & Co.
	Morales Julius B barber	R. L. Polk & Co.
1927	Spanish Express	New York Telephone
	Russo Vincent plaster moulder	New York Telephone
	Ramirez J exp D	New York Telephone
	Kerr John H r	New York Telephone
	Elmore Mary Mrs r	New York Telephone
1923	Weinberg & Son Saml & living Weinberg butchers	R. L. Polk & Co.
	Weinberg Irving Weinberg & Son	R. L. Polk & Co.
	Russo Vincent moulds	R. L. Polk & Co.
	Weinberg Saml Weinberg & Son	R. L. Polk & Co.
1920	Stern Edw clk	R. L. Polk & Co.
	Millane Mary	R. L. Polk & Co.
	McCurley Frank	R. L. Polk & Co.
	Kerr Jno H tmstr	R. L. Polk & Co.
	Kerr Edith	R. L. Polk & Co.
	Jennings P J	R. L. Polk & Co.
	Fenrick Frank	R. L. Polk & Co.
	Elmore Jno	R. L. Polk & Co.
	Bressan Chas New Ocean Travelers Hotel	R. L. Polk & Co.
	Zinell Edna E	R. L. Polk & Co.

408 W 18TH

Year	Uses	Source
1931	Watson Atler	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

Year	Uses	Source
1931	Van Wart Mae	Manhattan and Bronx Directory Publishing Company Residential Directory
	Van Wart Edw	Manhattan and Bronx Directory Publishing Company Residential Directory
	Vaillancourt E	Manhattan and Bronx Directory Publishing Company Residential Directory
	Sharkey Martha F	Manhattan and Bronx Directory Publishing Company Residential Directory
	Omera Thos	Manhattan and Bronx Directory Publishing Company Residential Directory
	ODonnell Michl	Manhattan and Bronx Directory Publishing Company Residential Directory
	ODonnell Anna	Manhattan and Bronx Directory Publishing Company Residential Directory
	Mc Donald Jos	Manhattan and Bronx Directory Publishing Company Residential Directory
	Mc Donald Edw	Manhattan and Bronx Directory Publishing Company Residential Directory
	Mc Cahill Patk	Manhattan and Bronx Directory Publishing Company Residential Directory
	Magro Stella	Manhattan and Bronx Directory Publishing Company Residential Directory
	Magro Dominick	Manhattan and Bronx Directory Publishing Company Residential Directory
	Hughes Patk	Manhattan and Bronx Directory Publishing Company Residential Directory
	Hartnett Thos J	Manhattan and Bronx Directory Publishing Company Residential Directory
	Driscoll Patk	Manhattan and Bronx Directory Publishing Company Residential Directory
	Costello Michl J	Manhattan and Bronx Directory Publishing Company Residential Directory
	Costello Grace	Manhattan and Bronx Directory Publishing Company Residential Directory
	Busby Margt	Manhattan and Bronx Directory Publishing Company Residential Directory
	Busby Jas	Manhattan and Bronx Directory Publishing Company Residential Directory
	Brickman Fred	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Mc Donnell D F r	New York Telephone
	Meiling Gertrude r	New York Telephone
1920	McConnell Patk	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1920	Malloy Jas lab	R. L. Polk & Co.
	Haren Danl J clk	R. L. Polk & Co.
	Effervescent Salts Products Co RTN Abr E Sperber	R. L. Polk & Co.
	Degner Arnold E gro	R. L. Polk & Co.
	Brady L & M Ellen Brady apron supply	R. L. Polk & Co.
	Brady Ellen L & M Brady	R. L. Polk & Co.
	Merling Otto P clk	R. L. Polk & Co.

409 W 18TH

Year	Uses	Source
1931	Kelly Kieran	Manhattan and Bronx Directory Publishing Company Residential Directory
	Mc Cauley Harry	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Gill Harry r	New York Telephone
1920	Rochefort Brew ster furn rms	R. L. Polk & Co.
	Lidenthal Florence	R. L. Polk & Co.

410 W 18TH

Year	Uses	Source
1931	Cummins Chas	Manhattan and Bronx Directory Publishing Company Residential Directory
1920	Charles Hy furn rms	R. L. Polk & Co.
	Charles Wm Mrs	R. L. Polk & Co.
	Fix Eliz	R. L. Polk & Co.

411 W 18TH

Year	Uses	Source
1931	Hartnett Mary A	Manhattan and Bronx Directory Publishing Company Residential Directory
	Donovan Marcella	Manhattan and Bronx Directory Publishing Company Residential Directory
	Dall Wm J	Manhattan and Bronx Directory Publishing Company Residential Directory
	Dall Jennie	Manhattan and Bronx Directory Publishing Company Residential Directory
	Brady Andrew	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

Year	Uses	Source
1931	Lee Patk	Manhattan and Bronx Directory Publishing Company Residential Directory
	Lund Alma	Manhattan and Bronx Directory Publishing Company Residential Directory
	Lund Harry C	Manhattan and Bronx Directory Publishing Company Residential Directory
	Monohan Geo	Manhattan and Bronx Directory Publishing Company Residential Directory
	Piscos Tohns	Manhattan and Bronx Directory Publishing Company Residential Directory
	Sullivan Nellie E	Manhattan and Bronx Directory Publishing Company Residential Directory
	Upton B Jas Bkbndr Dept Fin	Manhattan and Bronx Directory Publishing Company Residential Directory
	Upton Jas B	Manhattan and Bronx Directory Publishing Company Residential Directory
	Upton Jane	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Watts A M Mrs r	New York Telephone
	Lund Alma Schuman r	New York Telephone
	Koether Wm r	New York Telephone
	Egerland Dora Mrs r	New York Telephone
1923	Marcole Arth	R. L. Polk & Co.
1920	Whalen Thos slsmn	R. L. Polk & Co.
	Weldon Hugh A	R. L. Polk & Co.
	Sullivan Jeremiah cond	R. L. Polk & Co.
	Reidy Michl E clk	R. L. Polk & Co.
	Piscos Jno baker	R. L. Polk & Co.
	Phillips Wm G sten	R. L. Polk & Co.
	OHare Edw O printer	R. L. Polk & Co.
	Murphy Jno slsmn	R. L. Polk & Co.
	Mead Alonzo mach	R. L. Polk & Co.
	Marcoli Arth opr	R. L. Polk & Co.
	Mahoney Michl J	R. L. Polk & Co.
	Law son Edw	R. L. Polk & Co.
	Johnson Louis butcher	R. L. Polk & Co.
	Graves Michl E checker	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1920	Goodman Frank	R. L. Polk & Co.
	Germain Eliz clk NY Life Ins Co h Yonkers NY	R. L. Polk & Co.
	Goodman Francis shipbldr	R. L. Polk & Co.
	Casey Marie matron Dept Cor	R. L. Polk & Co.
	Germain Edw	R. L. Polk & Co.

412 W 18TH

Year	Uses	Source
1927	Reilly Kate Mrs r	New York Telephone
1920	Blauvelt Jos N	R. L. Polk & Co.

413 W 18TH

Year	Uses	Source
1920	Farmer Grace G Mrs gen sec	R. L. Polk & Co.

414 W 18TH

Year	Uses	Source
1920	Hammond Cath w id Jno	R. L. Polk & Co.
	Heinrich Albert	R. L. Polk & Co.
	Mahoney Dennls clk	R. L. Polk & Co.
	Martin Jno F	R. L. Polk & Co.

415 W 18TH

Year	Uses	Source
1931	Reilly F	Manhattan and Bronx Directory Publishing Company Residential Directory
	Carlucci Leonardo	Manhattan and Bronx Directory Publishing Company Residential Directory
	Mc Nearney Anna	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Beck Jos elec contr	New York Telephone
1920	Donnelly Geo H chauf	R. L. Polk & Co.
	McInerney Thos J	R. L. Polk & Co.

FINDINGS

416 W 18TH

Year	Uses	Source
1931	Graham Thos	Manhattan and Bronx Directory Publishing Company Residential Directory
	Mossmans Casper C	Manhattan and Bronx Directory Publishing Company Residential Directory
	Barrie Andrew	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Debellis Vincent r	New York Telephone
1920	MacKey Robt J	R. L. Polk & Co.
	MacKey Robt checker	R. L. Polk & Co.
	Kent Harry police	R. L. Polk & Co.
	Kent Helen sten Willard Storage Battery Co h Pelham NY	R. L. Polk & Co.
	Kent Henrietta w id John	R. L. Polk & Co.
	Kent Hy R Henry R Kent & Co h Montclair NJ	R. L. Polk & Co.
	Kent Jno F chauf	R. L. Polk & Co.
	MacKey Geo	R. L. Polk & Co.
	MacKey Geo W clk Dept Fin	R. L. Polk & Co.

417 W 18TH

Year	Uses	Source
1934	Greenw ich Apartments	R. L. Polk & Co.
1931	Brennan Patk	Manhattan and Bronx Directory Publishing Company Residential Directory
	Farier Della	Manhattan and Bronx Directory Publishing Company Residential Directory
	Farrell Frank	Manhattan and Bronx Directory Publishing Company Residential Directory
	Markham Stephen F lab	Manhattan and Bronx Directory Publishing Company Residential Directory
	Quinn J B	Manhattan and Bronx Directory Publishing Company Residential Directory
	Quinn Jos	Manhattan and Bronx Directory Publishing Company Residential Directory
	Quinn Margt E	Manhattan and Bronx Directory Publishing Company Residential Directory
	Sw eeney Francis	Manhattan and Bronx Directory Publishing Company Residential Directory
	Sw eeney Mary	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

Year	Uses	Source
1931	Wolfe Danl	Manhattan and Bronx Directory Publishing Company Residential Directory
	Wolfe Theresa	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Sweeney F X r	New York Telephone
	Walton Stillman B r	New York Telephone
1920	Brennan Patk J	R. L. Polk & Co.
	Farrell Francis T	R. L. Polk & Co.
	Holder Harry J clk	R. L. Polk & Co.
	Holder Jas W police	R. L. Polk & Co.
	Holder Walter	R. L. Polk & Co.
	Quinn Jas R clk PO	R. L. Polk & Co.
	Quinn Jas D asst br mgr F W Woolworth Co h Bkn	R. L. Polk & Co.
	Quinn Jos D	R. L. Polk & Co.
	Schumacher Geo H	R. L. Polk & Co.

418 W 18TH

Year	Uses	Source
1931	Brown Saml	Manhattan and Bronx Directory Publishing Company Residential Directory
	Walters Clarence	Manhattan and Bronx Directory Publishing Company Residential Directory
	Pannal Jas W	Manhattan and Bronx Directory Publishing Company Residential Directory
	Lacy John	Manhattan and Bronx Directory Publishing Company Residential Directory
	Franklin Henry	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Tyson John J r	New York Telephone
1923	International Supply Co RTN Jno J Tyson	R. L. Polk & Co.
1920	Tyson Michl G driver	R. L. Polk & Co.
	Tyson Jno J bkpr	R. L. Polk & Co.
	McClernan Robt	R. L. Polk & Co.
	Pierson Edna decorator	R. L. Polk & Co.
	Rooney Jas P eng	R. L. Polk & Co.
	Rooney Jos J	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1920	Tyson Jas J stein	R. L. Polk & Co.
	Tyson Jeo H W S Lunch h Flush BQ	R. L. Polk & Co.
	Lamb Jas	R. L. Polk & Co.
	Johnston Margt A w id Wm	R. L. Polk & Co.
	Clifford Fred F	R. L. Polk & Co.

419 W 18TH

Year	Uses	Source
1931	Drodhead Eliz	Manhattan and Bronx Directory Publishing Company Residential Directory
	Duenski Jos	Manhattan and Bronx Directory Publishing Company Residential Directory
1920	Upton Jas clk	R. L. Polk & Co.
	Upton Jas B mach	R. L. Polk & Co.
	Shevlin Jno F detective sergt P D	R. L. Polk & Co.
	Conw ay Jno eng	R. L. Polk & Co.
	Shafer J V	R. L. Polk & Co.
	Shevlin Alice w id Wm	R. L. Polk & Co.
	Shevlin Frank J	R. L. Polk & Co.

421 W 18TH

Year	Uses	Source
1934	Chelsea Soda & Candy Shoppe RTN Mrs Cath Garrity confr	R. L. Polk & Co.
	Garrity Cath Chelsea Soda & Candy	R. L. Polk & Co.
1931	Conw ay Delia	Manhattan and Bronx Directory Publishing Company Residential Directory
	Conw ay Jas	Manhattan and Bronx Directory Publishing Company Residential Directory
	Conw ay Patr	Manhattan and Bronx Directory Publishing Company Residential Directory
	Fitzpatrick Robt	Manhattan and Bronx Directory Publishing Company Residential Directory
	Toohey J J	Manhattan and Bronx Directory Publishing Company Residential Directory
	Spangler Danl	Manhattan and Bronx Directory Publishing Company Residential Directory
	Murtha Mary	Manhattan and Bronx Directory Publishing Company Residential Directory

Year	Uses	Source
1931	Murtha Cath	Manhattan and Bronx Directory Publishing Company Residential Directory
	Kane Mary	Manhattan and Bronx Directory Publishing Company Residential Directory
	Graham Bridget	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Anchor B cigars	New York Telephone
	Dreyer A scrap metal	New York Telephone
	Garabedian Paul grocer	New York Telephone
	Kane M L r	New York Telephone
1920	Kane Thos lab	R. L. Polk & Co.
	Kiernan Peter J	R. L. Polk & Co.
	Rogers Peter clk	R. L. Polk & Co.
	Rogers Terrance	R. L. Polk & Co.
	Schw ake Herman jr	R. L. Polk & Co.
	Wade Thos	R. L. Polk & Co.
	Fitzpatrick Robt driver	R. L. Polk & Co.

422 W 18TH

Year	Uses	Source
1931	Crumin Peter	Manhattan and Bronx Directory Publishing Company Residential Directory
	Amnelios Thos	Manhattan and Bronx Directory Publishing Company Residential Directory
	Hall John H	Manhattan and Bronx Directory Publishing Company Residential Directory
	Smith Jas	Manhattan and Bronx Directory Publishing Company Residential Directory
	Pugliesi Jos G	Manhattan and Bronx Directory Publishing Company Residential Directory
	Levy Morris	Manhattan and Bronx Directory Publishing Company Residential Directory
	Lennon Jas	Manhattan and Bronx Directory Publishing Company Residential Directory
1920	Gilmore Harry firm rms	R. L. Polk & Co.

423 W 18TH

Year	Uses	Source
1931	OConnor Thos paver P B M	Manhattan and Bronx Directory Publishing Company Residential Directory

Year	Uses	Source
1931	Mc Gow an John F	Manhattan and Bronx Directory Publishing Company Residential Directory
	Doyle Mary	Manhattan and Bronx Directory Publishing Company Residential Directory
	Doyle Christopher	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Conw ay Elizabeth r	New York Telephone
1920	Gormley Edw bartndr	R. L. Polk & Co.
	Babcock Jno	R. L. Polk & Co.
	OConnor Thos electn	R. L. Polk & Co.

424 W 18TH

Year	Uses	Source
1934	Positive Chemical & Disinfecting Co RTN Ruth Miller	R. L. Polk & Co.
	Woodlaw n Metal Co Inc NY; cap $ 80 000 Geo Dreyer pres Abr Dreyer sec treas metals scraps	R. L. Polk & Co.
1931	Tyrsell Alex	Manhattan and Bronx Directory Publishing Company Residential Directory
	Devine Jas J	Manhattan and Bronx Directory Publishing Company Residential Directory
	Kearns Danl F	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Positive Chemical & Disinfecting Co	New York Telephone
	Woodlaw n Metal Co	New York Telephone
	Dreyer Geo scrap mtl	New York Telephone
1920	Ennis Harry D hostler	R. L. Polk & Co.

425 W 18TH

Year	Uses	Source
1931	Sullivan Cath	Manhattan and Bronx Directory Publishing Company Residential Directory
	Moran Jas	Manhattan and Bronx Directory Publishing Company Residential Directory
	Mc Glone Anna	Manhattan and Bronx Directory Publishing Company Residential Directory
	Koberlein Anna	Manhattan and Bronx Directory Publishing Company Residential Directory
	Donovan Patk	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

Year	Uses	Source
1931	Donovan Mary	Manhattan and Bronx Directory Publishing Company Residential Directory
	Donovan Jas	Manhattan and Bronx Directory Publishing Company Residential Directory
	Donovan Ellen	Manhattan and Bronx Directory Publishing Company Residential Directory
	Coyne Peter	Manhattan and Bronx Directory Publishing Company Residential Directory
	Carr Herbert J mach Fire Dept	Manhattan and Bronx Directory Publishing Company Residential Directory
	Carr Herbert	Manhattan and Bronx Directory Publishing Company Residential Directory
1920	Meyer Jos	R. L. Polk & Co.
	Maguire Patk clk Mutual Life Ins Co	R. L. Polk & Co.
	Koherlein Frank A	R. L. Polk & Co.
	Koherlein Edw	R. L. Polk & Co.
	Gilgallon Michl F marshal	R. L. Polk & Co.
	Curran Walter A	R. L. Polk & Co.

426 W 18TH

Year	Uses	Source
1931	Turner Margt J	Manhattan and Bronx Directory Publishing Company Residential Directory
	Slevin John	Manhattan and Bronx Directory Publishing Company Residential Directory
	Slevin Anna	Manhattan and Bronx Directory Publishing Company Residential Directory
	Ryan Margt	Manhattan and Bronx Directory Publishing Company Residential Directory
	Ryan Denis	Manhattan and Bronx Directory Publishing Company Residential Directory
	Rogers Jas	Manhattan and Bronx Directory Publishing Company Residential Directory
	Monahan Julia	Manhattan and Bronx Directory Publishing Company Residential Directory
	Monahan Mary	Manhattan and Bronx Directory Publishing Company Residential Directory
	Turner John	Manhattan and Bronx Directory Publishing Company Residential Directory
	Monahan John	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

Year	Uses	Source
1931	Mangan John	Manhattan and Bronx Directory Publishing Company Residential Directory
	Jordan Thos	Manhattan and Bronx Directory Publishing Company Residential Directory
	Jordan Margt M	Manhattan and Bronx Directory Publishing Company Residential Directory
	Duffy Law rence	Manhattan and Bronx Directory Publishing Company Residential Directory
	Donahue Jas	Manhattan and Bronx Directory Publishing Company Residential Directory
	Crow ley J	Manhattan and Bronx Directory Publishing Company Residential Directory
	Costella Julia	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Turner Margaret r	New York Telephone
	Stack Thos M r	New York Telephone
1920	Turner Wm bdgh	R. L. Polk & Co.
	Turner Jas	R. L. Polk & Co.
	Toomey David	R. L. Polk & Co.
	Stack Thos M carrier PO	R. L. Polk & Co.
	Stack Michl chauf Gouverneur Hosp	R. L. Polk & Co.
	Stack Michl clk	R. L. Polk & Co.
	Goggin Jno driver	R. L. Polk & Co.

427 W 18TH

Year	Uses	Source
1931	Trucey Esther	Manhattan and Bronx Directory Publishing Company Residential Directory
	Sparks John	Manhattan and Bronx Directory Publishing Company Residential Directory
	Ryan Patk	Manhattan and Bronx Directory Publishing Company Residential Directory
	Ryan Josephine	Manhattan and Bronx Directory Publishing Company Residential Directory
	Hickey John	Manhattan and Bronx Directory Publishing Company Residential Directory
	Hickey Eliz	Manhattan and Bronx Directory Publishing Company Residential Directory
	Devlin Jos	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

Year	Uses	Source
1931	Cox Frances	Manhattan and Bronx Directory Publishing Company Residential Directory
	Casey Anna	Manhattan and Bronx Directory Publishing Company Residential Directory
	Bolster Jas	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Casey E R r	New York Telephone
1920	Walsh Timothy eng NY Times	R. L. Polk & Co.
	Miller Carl	R. L. Polk & Co.
	McHugh Michl	R. L. Polk & Co.
	Leonard Josephine	R. L. Polk & Co.
	Leon Edw slsmn	R. L. Polk & Co.
	Hogan Thos E carrier PO	R. L. Polk & Co.
	Hogan Jno chauf	R. L. Polk & Co.
	Gilburn Robt w atchmn Dept P & S	R. L. Polk & Co.
	Gallagher Wm electn	R. L. Polk & Co.
	Cumisky Mary	R. L. Polk & Co.
	Bergen Margt w id Martin	R. L. Polk & Co.

428 W 18TH

Year	Uses	Source
1931	Wegman Anna	Manhattan and Bronx Directory Publishing Company Residential Directory
	Wegman Alb	Manhattan and Bronx Directory Publishing Company Residential Directory
	Houghtaling Mary J	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Houghtaling Mary J Mrs r	New York Telephone
1920	Houghtaling Mary J	R. L. Polk & Co.
	Commercial Garage Inc NY Morris Segall pres Julius segall sec	R. L. Polk & Co.
	Wegman Albert	R. L. Polk & Co.

429 W 18TH

Year	Uses	Source
1931	OLeary Helen	Manhattan and Bronx Directory Publishing Company Residential Directory
	Mc Dougal Jas	Manhattan and Bronx Directory Publishing Company Residential Directory

Year	Uses	Source
1931	Dall Rebecca	Manhattan and Bronx Directory Publishing Company Residential Directory
	Dall Norman	Manhattan and Bronx Directory Publishing Company Residential Directory
	Dall Mary	Manhattan and Bronx Directory Publishing Company Residential Directory
1920	Kavanagh Hy	R. L. Polk & Co.
	Kane Jno lab	R. L. Polk & Co.
	Herche Geo	R. L. Polk & Co.
	Garriga Juan	R. L. Polk & Co.
	Devlin Jos F	R. L. Polk & Co.
	Kavanagh Jas lab	R. L. Polk & Co.
	Costello Michl J clk	R. L. Polk & Co.
	Cleary Hy	R. L. Polk & Co.
	Bergen Jos driver	R. L. Polk & Co.

430 W 18TH

Year	Uses	Source
1934	Bower S M v pres F R Peixatto Inc r Palisades pk NJ	R. L. Polk & Co.
	Bower S RTN Grace B Pressey prntr	R. L. Polk & Co.
1931	Faulkner Edw	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Presser A W USN	New York Telephone
	Gray Eden r	New York Telephone
	Cohen Lester r	New York Telephone
	Bower S novelties	New York Telephone
1923	Parker Warren Co TN Alf W Pressey cutlery	R. L. Polk & Co.
1920	Quigg Francis F	R. L. Polk & Co.
	Daly Mary w id Jno	R. L. Polk & Co.

431 W 18TH

Year	Uses	Source
1931	Walker Bertha	Manhattan and Bronx Directory Publishing Company Residential Directory
	Caldwell Jas F	Manhattan and Bronx Directory Publishing Company Residential Directory

FINDINGS

Year	Uses	Source
1931	Jackson Hervert	Manhattan and Bronx Directory Publishing Company Residential Directory
	Mc Cue Thos	Manhattan and Bronx Directory Publishing Company Residential Directory
	Stamard Jos S	Manhattan and Bronx Directory Publishing Company Residential Directory
	Stannard Jas	Manhattan and Bronx Directory Publishing Company Residential Directory
	Talbot Jas E	Manhattan and Bronx Directory Publishing Company Residential Directory
1923	Caldwell Sumpter L carrier PO	R. L. Polk & Co.
1920	Caldwell Mary A clk PO	R. L. Polk & Co.
	Stannard Jos S clk	R. L. Polk & Co.
	Stannard Jas chauf	R. L. Polk & Co.
	Phoenix Leonzo	R. L. Polk & Co.
	Cunningham Jas	R. L. Polk & Co.
	Talbot Jas E clk PO	R. L. Polk & Co.
	Caldwell Jas F watchmn Centl Union Trust Co	R. L. Polk & Co.

432 W 18TH

Year	Uses	Source
1920	Timmerman Chas pntr	R. L. Polk & Co.
	Kimmerman Chas foremn	R. L. Polk & Co.
	Carlson Nathaniel pilot	R. L. Polk & Co.

433 W 18TH

Year	Uses	Source
1920	Brennan Marie wid Thos	R. L. Polk & Co.
	Brennan Wm S clk	R. L. Polk & Co.
	Hughes Reginald C timekpr	R. L. Polk & Co.
	Hughes Reese J mgr NY Confection Co h Bkn	R. L. Polk & Co.
	Jenkins Mary B	R. L. Polk & Co.
	Snell Jas J clk	R. L. Polk & Co.

FINDINGS

W 18TH H DO

403 W 18TH H DO

Year	Uses	Source
1934	Rouco Anthony clo clnr	R. L. Polk & Co.
1923	Rodriquez Felipe tailor	R. L. Polk & Co.

405 W 18TH H DO

Year	Uses	Source
1920	Boorgian Richd tailor	R. L. Polk & Co.
	Vaccaio Louis shoemkr	R. L. Polk & Co.

406 W 18TH H DO

Year	Uses	Source
1934	Schmidt Leon Emily plmbr	R. L. Polk & Co.

407 W 18TH H DO

Year	Uses	Source
1923	Julius B Morales barber	R. L. Polk & Co.
1920	Yimenez Manuel barber	R. L. Polk & Co.

409 W 18TH H DO

Year	Uses	Source
1934	Gill Harry furn emp	R. L. Polk & Co.

410 W 18TH H DO

Year	Uses	Source
1934	Michel Alf furn rms	R. L. Polk & Co.
1923	Charles Wm Mrs room	R. L. Polk & Co.

412 W 18TH H DO

Year	Uses	Source
1934	Wiltenburg Leonard Filomena furn	R. L. Polk & Co.
1920	Reilly Edw D real est	R. L. Polk & Co.

414 W 18TH H DO

Year	Uses	Source
1934	Cusack Patk Ellen furn rms	R. L. Polk & Co.

FINDINGS

416 W 18TH H DO

Year	Uses	Source
1934	Doyle Mary w id Jas furn rms	R. L. Polk & Co.
1923	Tracey Martin J funeral director	R. L. Polk & Co.

421 W 18TH H DO

Year	Uses	Source
1934	Garrity Patk J Cath candy	R. L. Polk & Co.
	Ampagoomin Zakar gro	R. L. Polk & Co.
1923	Schw acke Herman gro	R. L. Polk & Co.
	Rubin J variety	R. L. Polk & Co.
1920	Schw acke Herman gro	R. L. Polk & Co.

422 W 18TH H DO

Year	Uses	Source
1934	Olsen Olaf Jennie furn rms	R. L. Polk & Co.

430 W 18TH H DO

Year	Uses	Source
1934	Pressey Grace B w id Alf W printer	R. L. Polk & Co.

W 18TH ST

401 W 18TH ST

Year	Uses	Source
2017	AIESHA BETHENCOURT	Cole Information Services
	0 AA 24 HR LOCKSMITH	Cole Information Services
	JUAN ROSARIO	Cole Information Services
	EMILY WU	Cole Information Services
	LOUELLA GRAHAM	Cole Information Services
	HARUN ISLAM	Cole Information Services
	JANE DOW	Cole Information Services
	WILLIAMS EBONY	Cole Information Services
	DORIS PAGAN	Cole Information Services
	ANGEL DELGADO	Cole Information Services
	LYDIA PEREZ	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2017	CARLOS CALDERON	Cole Information Services
	ANA FIGUEROA	Cole Information Services
	NICOLE HINNANT	Cole Information Services
	TASHARA FRANCIS	Cole Information Services
	LITO MARASIGAN	Cole Information Services
	SHU YE	Cole Information Services
	HUI CHEN	Cole Information Services
	XIOMARA GARCIA	Cole Information Services
	JACKIE RODRIGUEZ	Cole Information Services
	RUBEN RIVERA	Cole Information Services
2014	ANA FIGUEROA	Cole Information Services
	TASHARA POWELL	Cole Information Services
	CHRISTINA JONES	Cole Information Services
	KEISHA MCDOUGAL	Cole Information Services
	HE HUANG	Cole Information Services
	BRIAN OCONNELL	Cole Information Services
	KAHNDOKAR RASN	Cole Information Services
	RUBEN RIVERA	Cole Information Services
	MATTIE MOORE	Cole Information Services
	HE WU	Cole Information Services
	CIRA AVECILLAS	Cole Information Services
	JAYVON RAWLINGS	Cole Information Services
	DORIS PAGAN	Cole Information Services
	ANGEL DELGADO	Cole Information Services
	NICOLE HINNANT	Cole Information Services
2009	NICOLE HINNANT	Cole Information Services
	RUBIN RIVERA	Cole Information Services
	CARLOS CALDERON	Cole Information Services
	SHU YE	Cole Information Services
	TASHARA FRANCIS	Cole Information Services
	KEISHA MCDOUGAL	Cole Information Services
	JULIA MARINE	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2009	HUI CHEN	Cole Information Services
	FELICITA DELVALLE	Cole Information Services
	NANCY SANTIAGO	Cole Information Services
	L JOHNSON	Cole Information Services
	LOUELLA GRAHAM	Cole Information Services
	DELKIS BALBUENA	Cole Information Services
	AUBERT BETHENCOURT	Cole Information Services
	MATTIE MOORE	Cole Information Services
	JAMES GALLARDO	Cole Information Services
	JOSEPH CONWAY	Cole Information Services
	LESLIE ROSADO	Cole Information Services
	DORIS PAGAN	Cole Information Services
	EDISON AVECALLAS	Cole Information Services
	RAHIMA RASHID	Cole Information Services
2006	Number 6 A h Avecillas Zoila AO	Hill-Donnelly Information Services
	Number 6 C Barral G A	Hill-Donnelly Information Services
	Campos Tomes	Hill-Donnelly Information Services
	Chen Hui Juan	Hill-Donnelly Information Services
	Number 1 C h Delvalle Felicita A	Hill-Donnelly Information Services
	Graham Louella	Hill-Donnelly Information Services
	Number 4 A h Hinnant Nicole A	Hill-Donnelly Information Services
	Number 4 C h Mcdougal Keisha vo	Hill-Donnelly Information Services
	Number 28 h NG Xiao Mei A	Hill-Donnelly Information Services
	Number 6 C h Rashid Rahima A vo	Hill-Donnelly Information Services
	Number 3 C h Rivera Nelida A	Hill-Donnelly Information Services
	Number 58 h Rosado Leslie	Hill-Donnelly Information Services
	Thompson Ernest o	Hill-Donnelly Information Services
	Trece Shaun v 0 os	Hill-Donnelly Information Services
	Multi Unit Address	Hill-Donnelly Information Services
2004	AMANDA HINNANT	Cole Information Services
	PHYLLIS CINGARI	Cole Information Services
	CARLOS RIVERA	Cole Information Services

FINDINGS

Year	Uses	Source
2004	XIAO NG	Cole Information Services
	LESLIE ROSADO	Cole Information Services
	USBALDA FRANCISQUINI	Cole Information Services
	ANGEL DELGADO	Cole Information Services
	DAVID NEDD	Cole Information Services
	G BARRAL	Cole Information Services
	CARMELO RODRIGUEZ	Cole Information Services
	MOSELLE LAVEZZARI	Cole Information Services
	ERNEST THOMPSON	Cole Information Services
	RAHIMA RASHID	Cole Information Services
	TASHARA FRANCIS	Cole Information Services
	SANDRO ZAPATA	Cole Information Services
	CARLOS CALDERON	Cole Information Services
1999	RAW FLUSH BATHROOM ATTENDENT	Cole Information Services
1994	RIVERA, NELIDA	Cole Information Services
	NEDD, DAVID	Cole Information Services
	CINGARI, PHYLLIS	Cole Information Services
	CANOSA, ROCCO A	Cole Information Services
	ISLAM, NURUL	Cole Information Services
	MURPHY, ROBT J	Cole Information Services
	BARRAL, G	Cole Information Services
	TUONEY, ALBERT T	Cole Information Services
	RIVERA, CARLOS	Cole Information Services
1983	Tuoney Albert T	New York Telephone
	Barral Edw	New York Telephone
	Canosa Rocco A	New York Telephone
	Murphy Robt J	New York Telephone
	Nedd Lula	New York Telephone
	Santiago W	New York Telephone

411 W 18TH ST

Year	Uses	Source
2017	ANNELOT MARTINEZ	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2017	WINIFR OCONNELL	Cole Information Services
	DANIEL GENOVESE	Cole Information Services
	LONNIE NG	Cole Information Services
	ALFONSO FONSECA	Cole Information Services
	RADHAMES GUZMAN	Cole Information Services
	CHRISTOPHER RIVERA	Cole Information Services
	LINDA MEJIA	Cole Information Services
	JOHN HASKIN	Cole Information Services
	CHRISTOPHER OQUENDO	Cole Information Services
	EMILY RODRIGUEZ	Cole Information Services
	ROBERT CHAPMAN	Cole Information Services
	SOPHIE CHAU	Cole Information Services
	TAI HUYNH	Cole Information Services
	VANESSA ROSARIO	Cole Information Services
2014	VANESSA ROSARIO	Cole Information Services
	WINIFR OCONNELL	Cole Information Services
	DANIEL GENOVESE	Cole Information Services
	LONNIE NG	Cole Information Services
	ALFONSO FONSECA	Cole Information Services
	JUDITH LOZANO	Cole Information Services
	ZULMA MEJIA	Cole Information Services
	JOHN HASKIN	Cole Information Services
	CHRISTOPHER OQUENDO	Cole Information Services
	JACK BELAYET	Cole Information Services
	STAR BERMUDEZ	Cole Information Services
	ROBERT CHAPMAN	Cole Information Services
	SOPHIE CHAU	Cole Information Services
	TAI HUYNH	Cole Information Services
	ALICIA CEDANO	Cole Information Services
2009	JIAN WU	Cole Information Services
	MAGDIEL CEDANO	Cole Information Services
	ROBERT CHAPMAN	Cole Information Services

FINDINGS

Year	Uses	Source
2009	NUAN NG	Cole Information Services
	HILDA OQUENDO	Cole Information Services
	RADHAMES GUZMAN	Cole Information Services
	JUDITH LOZANO	Cole Information Services
	JACQUELIN RODRIGUEZ	Cole Information Services
	SUMUI CHAU	Cole Information Services
	MONICA SUAREZ	Cole Information Services
	TAI HUYNH	Cole Information Services
	WINIFR OCONNELL	Cole Information Services
2006	Number 1 E h Suarez Monica	Hill-Donnelly Information Services
	Rodriguez Jacqueline o	Hill-Donnelly Information Services
	Number 30 h Oquendo Inocencia	Hill-Donnelly Information Services
	Number 6D h Oconnell James A	Hill-Donnelly Information Services
	Number 2 F h NG Nuan Kw an A	Hill-Donnelly Information Services
	Number 5 E h Natal Antonia AO a	Hill-Donnelly Information Services
	Number 6 F h Lozano Judith	Hill-Donnelly Information Services
	Lozano J	Hill-Donnelly Information Services
	Number 4D h Fonseca Alfonso AO	Hill-Donnelly Information Services
	Chau Gim Chiu	Hill-Donnelly Information Services
	Number 1 F h Huynh Tai	Hill-Donnelly Information Services
	Number 5D 1 h Chau Gim C A	Hill-Donnelly Information Services
	Number 2 E h Chapman Robert AO	Hill-Donnelly Information Services
	Number 4 F h Cedano	Hill-Donnelly Information Services
	Multi Unit Address	Hill-Donnelly Information Services
2004	JAMES OCONNELL	Cole Information Services
	ROBERTO OQUENDO	Cole Information Services
	NUAN NG	Cole Information Services
	RODRIGUEZ EMILY	Cole Information Services
	IRVING CEDANO	Cole Information Services
	ALFONSO FONSECA	Cole Information Services
	JUDITH LOZANO	Cole Information Services
	SUMUI CHAU	Cole Information Services

FINDINGS

Year	Uses	Source
2004	MONICA SUAREZ	Cole Information Services
	ROBERT CHAPMAN	Cole Information Services
	TAI HUYNH	Cole Information Services
1999	JAMES OCONNELL	Cole Information Services
1994	NG, NUAN KWAN	Cole Information Services
	FONSECA, DEBORAH	Cole Information Services
	CHAU, GIM CHIU	Cole Information Services
	NATAL, ANTONIA	Cole Information Services
	O'CONNELL, JAS	Cole Information Services
	HUYNH, TAI	Cole Information Services
	SUAREZ, MONICA	Cole Information Services
	GENOVESE, ROBERT	Cole Information Services
	CHAPMAN, ROBT	Cole Information Services
	EDMONDS, DONN	Cole Information Services
	CEDANO, PILAR H	Cole Information Services
	TELESCO, ROSE	Cole Information Services
1983	Telesco Rose	New York Telephone
	Schiff Lew is A	New York Telephone
	Osorio Elizabeth	New York Telephone
	OConnell Jas	New York Telephone
	Natal Antonia	New York Telephone
	Martinez A	New York Telephone
	Gornay Anthony P	New York Telephone
	Craw ley Jos H	New York Telephone
	Chapman Robt	New York Telephone
	Arneel Jeanne	New York Telephone

415 W 18TH ST

Year	Uses	Source
1983	Gross Ames	New York Telephone

417 W 18TH ST

Year	Uses	Source
2004	JOEL ARBERNAN	Cole Information Services

FINDINGS

423 W 18TH ST

Year	*Uses*	*Source*
2004	C WEINSTEIN	Cole Information Services
1983	Schreiber Mayo Jr	New York Telephone

425 W 18TH ST

Year	*Uses*	*Source*
2004	ROBERT HUBNER	Cole Information Services
1983	Christopher Arthur M	New York Telephone

429 W 18TH ST

Year	*Uses*	*Source*
2004	JOHN LEVINE	Cole Information Services

FINDINGS

ADJOINING PROPERTY: ADDRESSES NOT IDENTIFIED IN RESEARCH SOURCE

The following Adjoining Property addresses were researched for this report, and the addresses were not identified in research source.

Address Researched	Address Not Identified in Research Source
400 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1963, 1934, 1927, 1923, 1920
401 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1963, 1956, 1950, 1947, 1938, 1934, 1927, 1923, 1920
401 W 18TH ST	2017, 2014, 2009, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
401 W 18TH ST	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
402 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1927, 1923, 1920
402 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1927, 1923
403 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1942, 1938, 1934, 1931, 1923, 1920
403 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923
403 W 18TH H DO	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1920
405 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1973, 1968, 1942, 1934, 1927, 1923, 1920
405 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1927
405 W 18TH H DO	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923
406 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1927, 1923, 1920
406 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1927
406 W 18TH H DO	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
407 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1934, 1931, 1923, 1920
407 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931
407 W 18TH H DO	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927

FINDINGS

Address Researched	Address Not Identified in Research Source
408 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1947, 1942, 1938, 1934, 1923, 1920
408 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1923
409 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1942, 1938, 1934, 1923, 1920
409 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1923
409 W 18TH H DO	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
410 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1947, 1942, 1934, 1927, 1923, 1920
410 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1927, 1923
410 W 18TH H DO	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1920
411 E 18TH ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
411 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1942, 1934, 1923, 1920
411 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934
411 W 18TH ST	2017, 2014, 2009, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
411 W 18TH ST	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
412 W 17 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1963, 1958, 1956, 1947, 1942, 1934, 1931, 1927, 1923, 1920
412 W 17TH ST	2017, 2014, 2009, 2004, 1999, 1998, 1996, 1994, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
412 W 17TH ST	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
412 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1947, 1942, 1938, 1934, 1931, 1923, 1920
412 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923
412 W 18TH H DO	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923
413 W 17 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1934, 1923, 1920
413 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920

FINDINGS

Address Researched	Address Not Identified in Research Source
413 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923
414 W 17 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
414 W 17TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1923
414 W 17TH ST	2017, 2014, 2009, 2006, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
414 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1934, 1931, 1927, 1923, 1920
414 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923
414 W 18TH H DO	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
415 W 17 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1963, 1934, 1923, 1920
415 W 17TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1923
415 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1973, 1942, 1934, 1923, 1920
415 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1923
415 W 18TH ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
416 W 17TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1923
416 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1938, 1934, 1923, 1920
416 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1923
416 W 18TH H DO	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1920
417 W 17 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
417 W 17TH ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
417 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1968, 1963, 1947, 1942, 1934, 1923, 1920
417 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1923

FINDINGS

Address Researched	Address Not Identified in Research Source
417 W 18TH ST	2017, 2014, 2009, 2006, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
418 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1947, 1942, 1938, 1934, 1923, 1920
418 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934
419 W 17 %	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
419 W 17 R	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
419 W 17 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1963, 1947, 1942, 1938, 1934, 1923, 1920
419 W 17TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1923
419 W 17TH ST	2017, 2014, 2009, 2004, 1999, 1998, 1996, 1994, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
419 W 17TH ST	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
419 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1947, 1942, 1934, 1927, 1923, 1920
419 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1927, 1923
420 W 180 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1927, 1923, 1920
421 W 17 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1963, 1947, 1938, 1934, 1923, 1920
421 W 17TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1923
421 W 17TH ST	2017, 2014, 2009, 2004, 1999, 1998, 1996, 1994, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
421 W 17TH ST	2017, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
421 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1973, 1968, 1963, 1934, 1923, 1920
421 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1923
421 W 18TH H DO	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927
422 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1950, 1942, 1938, 1934, 1927, 1923, 1920
422 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1927, 1923

FINDINGS

Address Researched	Address Not Identified in Research Source
422 W 18TH H DO	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
423 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1973, 1968, 1938, 1934, 1923, 1920
423 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1923
423 W 18TH ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
423 W 18TH ST	2017, 2014, 2009, 2006, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
424 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1934, 1923, 1920
424 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1923
425 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1938, 1934, 1927, 1923, 1920
425 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1927, 1923
425 W 18TH ST	2017, 2014, 2009, 2006, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
425 W 18TH ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
426 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1983, 1978, 1973, 1968, 1963, 1934, 1923, 1920
426 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1923
427 E 18TH ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
427 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1942, 1938, 1934, 1923, 1920
427 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1923
428 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1947, 1938, 1934, 1923, 1920
428 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1923
429 E 18TH ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
429 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1938, 1934, 1927, 1923, 1920

FINDINGS

Address Researched	Address Not Identified in Research Source
429 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1927, 1923
429 W 18TH ST	2017, 2014, 2009, 2006, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
430 W 18 %	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
430 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1942, 1934, 1923, 1920
430 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938
430 W 18TH H DO	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
431 W 117 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1958, 1956, 1950, 1938, 1934, 1927, 1923, 1920
431 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1934, 1927, 1923, 1920
431 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1927
432 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923
433 W 18 ST	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1942, 1938, 1934, 1931, 1927, 1923, 1920
433 W 18TH	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923

TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

Address Researched	Address Not Identified in Research Source
401w16th St, 400 W17th St, 420w18th St, 420w19thst	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1998, 1996, 1994, 1993, 1988, 1983, 1978, 1973, 1968, 1923

APPENDIX E

REGULATORY RECORDS DOCUMENTATION

Fulton
401w16th St, 400 W17th St, 420w18th St, 420w19thst
New York, NY 10011

Inquiry Number: 6920743.2s
March 31, 2022

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	9
Orphan Summary	2959
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-9
Physical Setting Source Map Findings	A-10
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527-21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

COORDINATES

Latitude (North):	40.7436330 - 40ˆ 44' 37.07''
Longitude (West):	74.0043040 - 74ˆ 0' 15.49''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	584066.1
UTM Y (Meters):	4510564.0
Elevation:	14 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	14317809 JERSEY CITY, NJ
Version Date:	2019
Northeast Map:	14115942 CENTRAL PARK, NY
Version Date:	2019
Southeast Map:	14115940 BROOKLYN, NY
Version Date:	2019
Northwest Map:	14327276 WEEHAWKEN, NJ
Version Date:	2019

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20150729, 20150522
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	CON EDISON	F/O 420 WEST 18 ST	NY MANIFEST		TP
A2	RESIDENTIAL	400 WEST 17TH ST	NY Spills		TP
Reg	HUDSON RIVER PCBS	NO STREET APPLICABLE	NPL, SEMS, RCRA-LQG, US ENG CONTROLS, US INST...	Same	1292, 0.245, West
B3	CON EDISON	429 W 19TH ST	RCRA NonGen / NLR	Higher	1 ft.
B4	CON EDISON VAULT: 93	419 W 19TH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1 ft.
A5	CON EDISON SERVICE B	424 W 18TH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1 ft.
B6	CON EDISON VAULT: 93	419 W 19TH ST	FINDS, ECHO	Higher	1 ft.
A7	CON EDISON SERVICE B	424 W 18TH ST	FINDS, ECHO	Higher	1 ft.
B8	CON EDISON	429 W 19TH ST	FINDS, ECHO	Higher	1 ft.
A9	401-411 WEST 18TH ST	401-425 WEST 18TH ST	NY UST	Higher	1 ft.
B10	CON EDISON	429 W 19TH ST	NJ MANIFEST	Higher	1 ft.
A11	CON EDISON SERVICE B	419 W 17TH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1 ft.
A12	CON EDISON	418 W 17TH ST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	1 ft.
C13	WEST 17TH STREET AND	440-452 WEST 17TH ST	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS	Lower	1 ft.
A14	NYCHA - FULTON HOUSE	427-431 W 17TH ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1 ft.
A15	CON EDISON	418 W 17TH ST	FINDS, ECHO	Higher	1 ft.
D16	EXCAVATION SITE	FRONT OF 413 W. 16TH	NY Spills	Higher	1 ft.
A17	MIDTOWN SERVICE CENT	436 W 18TH ST	EDR Hist Auto	Lower	8, 0.002, WNW
A18	LOT 50,TAXBLOCK 715	436 WEST 18 STREET	NY E DESIGNATION	Lower	8, 0.002, WNW
B19	157-21 9TH AVE/QUEEN	157021 9TH AVENUE	NY Spills	Higher	17, 0.003, NE
C20	FREEDMAN CUTOUTS	444 WEST 17TH STREET	NY LTANKS	Lower	18, 0.003, West
E21	BASEMENT	435 WEST 19TH ST	NY Spills	Higher	22, 0.004, North
E22	CON EDISON SERVICE B	426 W 19TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	24, 0.005, NNW
A23	CON EDISON SERVICE B	121 9TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	28, 0.005, SE
A24	CON EDISON SERVICE B	117 9TH AVE	NJ MANIFEST	Higher	28, 0.005, SE
A25	CON EDISON SERVICE B	117 9TH AVE SB 39650	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	28, 0.005, SE
D26	CON EDISON SERVICE B	87 9TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	29, 0.005, South
A27	COE BRANDT CAREFUL	419 423 E 18TH TEL M	EDR Hist Cleaner	Lower	30, 0.006, NW
A28	CON EDISON SERVICE B	103 9TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	32, 0.006, SSE
C29	LOT 7,TAXBLOCK 715	447 WEST 17 STREET	NY E DESIGNATION	Lower	34, 0.006, WNW
C30	LOT 16,TAXBLOCK 714	431 WEST 16 STREET	NY E DESIGNATION	Lower	34, 0.006, WSW
D31	CON EDISON	9 AVE & 16 ST	NY MANIFEST	Higher	36, 0.007, South
D32	CON EDISON	9 AVE & 16 ST	NY MANIFEST	Higher	36, 0.007, South
D33	CON EDISON	W 16TH ST & 9TH AVE	RCRA-LQG	Higher	36, 0.007, South
B34	CON EDISON	W 19TH ST & 9TH AVE	NJ MANIFEST	Higher	43, 0.008, ENE
B35	CON EDISON	W 19TH ST & 9TH AVE	RCRA NonGen / NLR, ECHO	Higher	43, 0.008, ENE
B36	CON EDISON	9 AVE & EAST 19 ST	NY MANIFEST	Higher	43, 0.008, ENE
B37	CON EDISON	9TH AVE & W 19TH ST	NY MANIFEST	Higher	43, 0.008, ENE
B38	CON EDISON	W 19TH ST & 9TH AVE	NY MANIFEST	Higher	43, 0.008, ENE

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
B39	CON ED	19TH ST & 9TH AVE NW	NY MANIFEST	Higher	43, 0.008, ENE
B40	CON ED ROADSIDE	WEST 19TH STREET/ AN	NY Spills	Higher	45, 0.009, ENE
C41	CON EDISON	440 W 16TH ST	NJ MANIFEST	Lower	48, 0.009, SW
C42	CON EDISON	440 W 16TH ST	NY MANIFEST	Lower	48, 0.009, SW
C43	CON EDISON	440 W 16TH ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	48, 0.009, SW
F44	CON EDISON	9 AVE & 17 ST	NY MANIFEST	Higher	49, 0.009, SSE
C45	VERIZON NEW YORK INC	438-454 WEST 18TH ST	NY AST	Lower	50, 0.009, WNW
C46	VERIZON	438 WEST 18TH ST	NY Spills	Lower	50, 0.009, WNW
E47	METROPOLITAN OLDSMOB	440 W 19TH ST	NY UST, RCRA NonGen / NLR, FINDS, ECHO	Lower	53, 0.010, NNW
C48	LOT 59,TAXBLOCK 715	442 WEST 18 STREET	NY E DESIGNATION	Lower	53, 0.010, WNW
A49	188TH STREET AND	188TH ST & COLUMBUS	NY Spills	Higher	53, 0.010, ESE
C50	SPILL NUMBER 0012292	448 WEST 16TH ST	NY Spills	Lower	55, 0.010, SW
C51	VAULT 632	448 W 16TH ST	NY Spills	Lower	55, 0.010, SW
C52	OXYGEN MEDIA	448 W 16TH ST	RCRA NonGen / NLR	Lower	55, 0.010, SW
D53	GOOGLE LLC	76 9TH AVE	RCRA-VSQG, NY MANIFEST	Higher	56, 0.011, South
D54	GIVAUDAN CORP C/O FR	76 NINTH AVE	RCRA NonGen / NLR	Higher	56, 0.011, South
D55	GEORGE UHE CO INC	76 NINTH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	56, 0.011, South
D56	CON EDISON	76 9TH AVE	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	56, 0.011, South
C57	LOT 14,TAXBLOCK 714	437 WEST 16 STREET	NY E DESIGNATION	Lower	57, 0.011, WSW
C58	CON EDISON	437 W 16TH ST	NJ MANIFEST	Lower	57, 0.011, WSW
C59	CON EDISON	437 W 16TH ST	NY MANIFEST	Lower	57, 0.011, WSW
C60	CON EDISON	437 W 16TH ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	57, 0.011, WSW
F61	CON EDISON SERVICE B	96 9TH AVE N OF W 35	NJ MANIFEST	Higher	62, 0.012, SSE
F62	CON EDISON SERVICE B	96 9TH AVE N OF W 35	RCRA NonGen / NLR, NY MANIFEST	Higher	62, 0.012, SSE
B63	SPILL NUMBER 9912769	414 W 20TH ST	NY Spills	Higher	62, 0.012, NNE
B64	SPILL NUMBER 0111849	414 WEST 20TH STREET	NY Spills	Higher	62, 0.012, NNE
B65	414 W. 20TH ST	414 WEST 20TH ST	NY Spills	Higher	62, 0.012, NNE
E66	SPILL NUMBER 0111434	416 W. 20TH ST	NY Spills	Higher	63, 0.012, NNE
C67	ACROSS FROM WEINBURG	450 W 16TH ST	NY Spills	Lower	65, 0.012, WSW
E68	438 WEST 19TH STREET	438 WEST 19TH STREET	NY UST	Lower	68, 0.013, NNW
E69	BETW. 9TH/10TH AVE.	438 WEST 19TH ST	NY Spills	Lower	68, 0.013, NNW
E70	CON EDISON	428 W 20TH ST	NY MANIFEST	Higher	69, 0.013, North
E71	CON EDISON	428 W 20TH ST	NJ MANIFEST	Higher	69, 0.013, North
E72	CON EDISON	428 W 20TH ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	69, 0.013, North
C73	MENDON LEASING CORP	440 W 18TH ST	NY UST, RCRA NonGen / NLR, FINDS, ECHO, NY...	Lower	70, 0.013, WNW
C74	CON EDISON SERVICE B	439 W 16TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	73, 0.014, WSW
C75	445-459 W. 16TH ST	445-459 WEST 16TH ST	NY Spills	Lower	75, 0.014, WSW
E76	ALJOBET AUTOMATIC TR	435 WEST 18TH ST	EDR Hist Auto	Lower	83, 0.016, NW
E77	ALCAM PROPERTY MANAG	435 WEST 18TH STREET	NY UST	Lower	83, 0.016, NW

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
E78	THE GENERAL THEOLOGI	422 WEST 20TH STREET	NY AST	Higher	84, 0.016, North
C79	CON EDISON SERVICE B	455 W 16TH ST FRONT	RCRA NonGen / NLR, NY MANIFEST	Lower	90, 0.017, WSW
C80	FREEDMAN CUT-OUTS	455 W 16TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	90, 0.017, WSW
C81	455 WEST 16TH STREET	455 WEST 16TH STREET	NY UST	Lower	90, 0.017, WSW
C82	LOT 5,TAXBLOCK 715	453 WEST 17 STREET	NY E DESIGNATION	Lower	96, 0.018, WNW
A83	VELAZQUEZ 9TH AVENUE	126 9TH AVE	RCRA-SQG, ICIS, FINDS, ECHO, NY DRYCLEANERS, NY...	Higher	97, 0.018, ESE
A84	BARBARA DRY CLEANERS	126 9TH AVE	EDR Hist Cleaner	Higher	97, 0.018, ESE
B85	YAU CLEANERS	150 9TH AVE	EDR Hist Cleaner	Higher	108, 0.020, ENE
G86	MANHOLE 3245	441 W 18TH ST	NY Spills	Lower	108, 0.020, NW
C87	THE CALEDONIA	450 WEST 17TH STREET	NY AST	Lower	109, 0.021, West
E88	CON EDISON	432 W 20 ST	NY MANIFEST	Lower	110, 0.021, North
E89	CON EDISON SERVICE B	434-436 W 20TH ST &	NJ MANIFEST	Lower	111, 0.021, North
B90	CON EDISON	136 9 AVE	NY MANIFEST	Higher	112, 0.021, East
F91	110 NINTH AVENUE	110 NINTH AVENUE	NY UST	Higher	116, 0.022, SE
G92	LOT 60,TAXBLOCK 715	456 WEST 18 STREET	NY E DESIGNATION	Lower	118, 0.022, WNW
G93	456-464 W. 18TH STRE	456-464 W 18TH STREE	NY UST	Lower	118, 0.022, WNW
B94	400 WEST 20TH STREET	400 WEST 20TH STREET	NY AST	Higher	119, 0.023, NE
B95	NINTH AVENUE APT COR	162 NINTH AVENUE	NY AST	Higher	125, 0.024, ENE
G96	CON EDISON SERVICE B	458 W 18TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	131, 0.025, WNW
B97	CON EDISON SERVICE B	315-313 W 20TH ST &	RCRA NonGen / NLR, FINDS	Higher	139, 0.026, NE
B98	CON EDISON SERVICE B	359 W 20TH ST & 9TH	RCRA NonGen / NLR, FINDS	Higher	139, 0.026, NE
B99	CON EDISON SERVICE B	326-324 W 20TH ST &	RCRA NonGen / NLR, FINDS	Higher	139, 0.026, NE
B100	NYC DEP	20TH ST BETW 8TH & 9	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	139, 0.026, NE
B101	CON EDISON SERVICE B	337-335 W 20TH ST &	RCRA NonGen / NLR, FINDS	Higher	139, 0.026, NE
B102	CON EDISON SERVICE B	309-307 W 20TH ST &	RCRA NonGen / NLR, FINDS	Higher	139, 0.026, NE
B103	CON EDISON SERVICE B	365 W 20TH ST & 9TH	RCRA NonGen / NLR, FINDS	Higher	139, 0.026, NE
C104	CON EDISON - MANHOLE	460-454 W 16TH ST	NY MANIFEST	Lower	139, 0.026, WSW
C105	CON EDISON - MANHOLE	460-454 W 16TH ST	NJ MANIFEST	Lower	139, 0.026, WSW
C106	CON EDISON - MANHOLE	460-454 W 16TH ST	RCRA-LQG	Lower	139, 0.026, WSW
B107	WEST 20TH ST & 9TH A	WEST 20TH ST / 9TH A	NY Spills	Higher	139, 0.026, NE
G108	AUTO CARE WEST	464 WEST 18TH ST	NY LTANKS	Lower	145, 0.027, WNW
F109	CON EDISON	F/O 108 9 AV	NY MANIFEST	Higher	149, 0.028, SE
F110	CON EDISON MANHOLE 3	108 9TH AVE	NJ MANIFEST	Higher	149, 0.028, SE
F111	CON EDISON MANHOLE 3	108 9TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	149, 0.028, SE
F112	CON EDISON	108 9TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	149, 0.028, SE
H113	MANHOLE #57478	359 WEST 18 STREET	NY Spills	Higher	171, 0.032, ESE
G114	SPILL NUMBER 0013277	445 WEST 18TH ST (OP	NY Spills	Lower	171, 0.032, NW
B115	GENERAL THEOLOGICAL	175 9TH AVE	RCRA-SQG, FINDS, ECHO, NY MANIFEST	Higher	180, 0.034, NE
G116	CON EDISON - MANHOLE	447 W 18TH ST	NY MANIFEST	Lower	189, 0.036, NW

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
G117	CON EDISON - MANHOLE	447 W 18TH ST	RCRA-LQG	Lower	189, 0.036, NW
B118	SPILL NUMBER 0013164	364 WEST 19TH ST	NY Spills	Higher	191, 0.036, East
B119	365 WEST 20TH STREET	365 WEST 20TH ST.	NY AST	Higher	195, 0.037, ENE
I120	LOT 63,TAXBLOCK 715	128 10 AVENUE	NY E DESIGNATION	Lower	201, 0.038, WNW
F121	SP 364 W 18 LLC	364 WEST 18TH STREET	NY AST	Higher	205, 0.039, ESE
F122	LAWRENCE ENVIRONMENT	364 WEST 18TH STREET	NY LTANKS, NY Spills	Higher	205, 0.039, ESE
I123	CON EDISON MANHOLE:	116 10TH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	209, 0.040, WNW
I124	LOT 2,TAXBLOCK 715	116 10 AVENUE	NY E DESIGNATION	Lower	209, 0.040, WNW
I125	118 10TH AVENUE	118 10TH AVENUE	NY VCP	Lower	209, 0.040, WNW
I126	LOT 3,TAXBLOCK 715	118 10 AVENUE	NY E DESIGNATION	Lower	209, 0.040, WNW
F127	CON EDISON	FO 362 W 18 ST	NY MANIFEST	Higher	210, 0.040, ESE
J128	CON EDISON	74 9TH AVE	RCRA NonGen / NLR	Higher	211, 0.040, South
F129	CON EDISON SERVICE B	357 W 17TH ST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	213, 0.040, SE
I130	LOT 64,TAXBLOCK 715	124 10 AVENUE	NY E DESIGNATION	Lower	213, 0.040, WNW
F131	CON EDISON	364 W 17 ST	NY MANIFEST	Higher	217, 0.041, SSE
J132	VERIZON	75 9TH AVE	RCRA NonGen / NLR, NJ MANIFEST	Higher	217, 0.041, SSW
J133	OXYGEN MEDIA	75 9TH AVENUE	NY Spills, NY MANIFEST, NY COOLING TOWERS	Higher	217, 0.041, SSW
J134	CHELSEA MARKET	75TH NINTH AVENUE	NY AST	Higher	217, 0.041, SSW
J135	NBC UNIVERSAL INC -	75 9TH AVE - 7TH FLO	RCRA-VSQG	Higher	217, 0.041, SSW
J136	CHELSEA MARKET	75TH NINTH AVENUE	NY UST	Higher	217, 0.041, SSW
J137	NY1 NEWS	75 NINTH AVE	NY AST	Higher	217, 0.041, SSW
I138	CON ED	FO 120 10TH AVE	NY MANIFEST	Lower	225, 0.043, WNW
J139	CON EDISON	72 9TH AVE	RCRA NonGen / NLR	Higher	225, 0.043, South
J140	CON EDISON	72 9TH AVE	RCRA NonGen / NLR	Higher	225, 0.043, South
B141	CON EDISON	361 W 19 ST	NY MANIFEST	Higher	231, 0.044, ENE
B142	CON EDISON	OPP 361 W 19TH ST	NY MANIFEST	Higher	231, 0.044, ENE
F143	CON EDISON	357 W 16TH ST	NY MANIFEST	Higher	231, 0.044, SSE
F144	CON EDISON	357 W 16 ST	NY MANIFEST	Higher	231, 0.044, SSE
F145	CON EDISON	360 W 17 ST	NY MANIFEST	Higher	232, 0.044, SSE
K146	409 W. 15TH STREET	409 W. 15TH STREET	NY Spills	Lower	233, 0.044, SW
H147	CON EDISON	FO 358 W 19 ST	NY MANIFEST	Higher	245, 0.046, East
H148	CON EDISON	358 W 19 ST	NY MANIFEST	Higher	245, 0.046, East
H149	BAYARD RUSTIN EDUCAT	351 WEST 18TH STREET	NY AST	Higher	246, 0.047, ESE
H150	NYC BD OF ED - HUMAN	351 W 18TH ST	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Higher	246, 0.047, ESE
K151	CON EDISON - VAULT 4	421 W 15TH ST	RCRA-LQG	Lower	248, 0.047, SW
K152	CON EDISON	421 W 15TH ST	NY MANIFEST	Lower	248, 0.047, SW
K153	CON EDISON	421 W 15TH ST	NY MANIFEST	Lower	248, 0.047, SW
K154	CON EDISON - VAULT S	421 W 15TH ST	RCRA-LQG	Lower	248, 0.047, SW
F155	CON EDISON	353 W 17TH ST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	251, 0.048, SE

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
I156	FREEDMAN REALTY	110 TENTH AVENUE	NY UST	Lower	257, 0.049, WNW
E157	448 E. 19TH ST	448 E. 19TH ST	NY Spills	Lower	264, 0.050, NW
I158	CON EDISON	10 AVE & 17TH ST	NY MANIFEST	Lower	277, 0.052, WNW
I159	HY FLUID FROM VEHICL	10 AVENUE & WEST 17	NY Spills	Lower	277, 0.052, WNW
I160	MANHOLE #43054, SOUT	WEST 17 STREET & 10	NY Spills	Lower	277, 0.052, WNW
J161	CON EDISON - VAULT V	69 9TH AVE	NY MANIFEST	Higher	280, 0.053, SSW
J162	VAULT 0505	69 9TH AVE	NY Spills	Higher	280, 0.053, SSW
F163	CON EDISON - VAULT V	346 W 17 ST	NY MANIFEST	Higher	282, 0.053, SSE
F164	COVENANT HOUSE THE	346 W 17TH ST	RCRA-SQG, NY MANIFEST	Higher	282, 0.053, SSE
F165	MANHOLE # UNK	IFO 346 W 17TH ST	NY Spills	Higher	282, 0.053, SSE
J166	9TH AVE & 15TH ST	9TH AVE & 15TH ST	NY Spills	Higher	283, 0.054, SSW
H167	D S K ASSOC	352-354 W 18 ST	NY AST	Higher	286, 0.054, ESE
K168	VAULT 4188	15TH ST BTW 9 & 10TH	NY Spills	Lower	287, 0.054, SW
L169	CON EDISON	351 W 16 ST	NY MANIFEST	Higher	291, 0.055, SSE
J170	CON EDISON MANHOLE 2	400 W 15TH ST & 9TH	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	294, 0.056, SSW
H171	CON EDISON	FO 342 WEST 18 ST	NY MANIFEST	Higher	296, 0.056, ESE
H172	CON EDISON	342-340 W 18 ST & 9	NY MANIFEST	Higher	296, 0.056, ESE
I173	WEST 18TH ST & TENTH	W. 18TH ST &TENTH AV	NY Spills	Lower	300, 0.057, WNW
I174	SPILL NUMBER 0107030	18TH ST/11TH AVE	NY Spills	Lower	300, 0.057, WNW
I175	214187; 18 ST & 10 A	18 ST & 10 AV	NY Spills	Lower	300, 0.057, WNW
I176	OIL ON SOIL	10TH AVE AND WEST 18	NY Spills	Lower	300, 0.057, WNW
M177	CON EDISON	OPP 353 W 19TH ST	NY MANIFEST	Higher	304, 0.058, East
H178	VAULT 8126	335 W. 18TH ST	NY Spills	Higher	310, 0.059, ESE
H179	SCHOOL OF HUMANITES	18TH-19TH	NY LTANKS	Higher	313, 0.059, ESE
H180	350 WEST 18TH ST	350 WEST 18TH ST	NY AST	Higher	313, 0.059, ESE
H181	CON EDISON	FO 350 W 18 ST	NY MANIFEST	Higher	313, 0.059, ESE
H182	CON EDISON	FO 350 WEST 18 ST	NY MANIFEST	Higher	313, 0.059, ESE
M183	CON EDISON SERVICE B	346 W 20TH ST FRONT	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	316, 0.060, ENE
N184	458 WEST 20TH ST	458 WEST 20TH STREET	NY AST	Lower	318, 0.060, NNW
I185	CON EDISON SERVICE B	136 10TH AVE OPPOSIT	RCRA NonGen / NLR, NY MANIFEST	Lower	319, 0.060, NW
O186	CON EDISON SERVICE B	432 W 21ST ST FRONT	RCRA NonGen / NLR	Higher	328, 0.062, NNE
P187	CON EDISON - MANHOLE	179 9TH AVE	NY MANIFEST	Higher	328, 0.062, NE
P188	CON EDISON - MANHOLE	179 9TH AVE	RCRA-LQG	Higher	328, 0.062, NE
J189	CON EDISON	402 W 15TH ST	NJ MANIFEST	Higher	330, 0.062, SSW
J190	CON EDISON	402 W 15TH ST	RCRA NonGen / NLR	Higher	330, 0.062, SSW
J191	CON EDISON	402 W 15TH ST	NY MANIFEST	Higher	330, 0.062, SSW
L192	CON EDISON - SERVICE	347 W 17TH ST	NY MANIFEST	Higher	331, 0.063, SE
K193	430 WEST 15TH STREET	430 WEST 15TH STREET	NY UST	Lower	331, 0.063, SW
K194	455 WEST 15TH STREET	455 WEST 15TH STREET	NY Spills	Lower	332, 0.063, WSW

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
L195	RESIDENCE/APARTMENT	347 WEST 16TH ST	NY Spills	Higher	332, 0.063, SSE
L196	347 WEST 16 STREET L	347 WEST 16TH STREET	NY AST	Higher	332, 0.063, SSE
J197	AABIS SERVICE STATIO	65 9TH AVE	EDR Hist Auto	Higher	336, 0.064, SSW
I198	456 WEST 19TH STREET	456 WEST 19TH STREET	NY UST	Lower	344, 0.065, NW
K199	FORMER PARKING GARAG	422-430 WEST 15TH ST	NY Spills	Lower	344, 0.065, SW
K200	CON EDISON - MANHOLE	412 W 15TH ST	NJ MANIFEST	Lower	345, 0.065, SW
K201	CON EDISON - MANHOLE	412 W 15TH ST	RCRA-LQG, FINDS, ECHO	Lower	345, 0.065, SW
K202	CON EDISON - VAULT 2	412 W 15TH ST	RCRA-LQG	Lower	345, 0.065, SW
K203	CON EDISON - VAULT 2	412 W 15TH ST	NY MANIFEST	Lower	345, 0.065, SW
K204	CON EDISON	412 W 15TH ST	NY MANIFEST	Lower	345, 0.065, SW
K205	408 W 15TH ST/MANHAT	408 WEST 15TH STREET	NY Spills	Higher	346, 0.066, SSW
J206	PRINCE LUMBER COMPAN	404 WEST 15TH STREET	NY Spills	Higher	346, 0.066, SSW
J207	LOT 38,TAXBLOCK 712	404 WEST 15 STREET	NY E DESIGNATION	Higher	346, 0.066, SSW
M208	CON EDISON	FO 349 W 19 ST	NY MANIFEST	Higher	346, 0.066, East
K209	CON EDISON	440 W 15TH ST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	348, 0.066, SW
H210	CON EDISON	FO 332 WEST 18 ST	NY MANIFEST	Higher	349, 0.066, ESE
H211	CON EDISON	332-320 18 ST & 9 AV	NY MANIFEST	Higher	349, 0.066, ESE
L212	345 W 16 STREET	345 WEST 16TH STREET	NY AST	Higher	357, 0.068, SSE
L213	CON EDISON	345 W 16 ST	NY MANIFEST	Higher	357, 0.068, SSE
L214	345-347 WEST 16TH ST	345-347 W 16TH ST	NY Spills	Higher	357, 0.068, SSE
J215	LOT 7502,TAXBLOCK 73	66 9 AVENUE	NY E DESIGNATION	Higher	364, 0.069, South
J216	216617; 404 15 ST AN	404 15 ST AND 7 AVE	NY Spills	Higher	364, 0.069, SSW
J217	PRINCE LUMBER	61-67 9TH AVENUE	NY UST	Higher	365, 0.069, SSW
J218	LOT 36,TAXBLOCK 712	61 9 AVENUE	NY E DESIGNATION	Higher	365, 0.069, SSW
J219	PRINCE LUMBER FORMER	61 9TH AVE	RCRA NonGen / NLR	Higher	365, 0.069, SSW
J220	61 NINTH DEVELOPMENT	61 9TH AVE	NY MANIFEST	Higher	365, 0.069, SSW
J221	FORMER PRINCE LUMBER	61-67 9TH AVE	NY Spills	Higher	365, 0.069, SSW
J222	SOIL	61-67 9TH AVE	NY Spills	Higher	365, 0.069, SSW
Q223	MANHOLE # 43048	WEST 16 STREET & 10	NY Spills	Lower	365, 0.069, West
Q224	CON EDISON MANHOLE 4	W 16 ST & 10 AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	365, 0.069, West
Q225	CON EDISON	10TH AVE & 16TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	365, 0.069, West
Q226	CON EDISON	10TH AVE & 16TH ST	NJ MANIFEST	Lower	365, 0.069, West
Q227	CON EDISON	10TH AVE & 16TH ST	RCRA NonGen / NLR	Lower	365, 0.069, West
Q228	CON EDISON	10TH AVE & 16TH ST	NY MANIFEST	Lower	365, 0.069, West
Q229	BET.9TH & 10TH AVE W	10TH AVE / W 16ST ST	NY Spills	Lower	365, 0.069, West
P230	CHELTONCORT OWNERS C	360 WEST 21ST STREET	NY AST	Higher	372, 0.070, NE
M231	CON EDISON	344 W 19 ST	NY MANIFEST	Higher	373, 0.071, East
Q232	COMML STRUCTURE	503 W 16TH ST BET 10	NY Spills	Lower	377, 0.071, West
Q233	NEW YORK MOTORCOACH	90 TEN BROECK AVE	NY Spills	Lower	377, 0.071, West

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
P234	CON EDISON SERVICE B	328-326 W 21ST ST &	RCRA NonGen / NLR, FINDS	Higher	378, 0.072, NE
P235	CON EDISON SERVICE B	W 21ST ST & 9TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	378, 0.072, NE
P236	CON EDISON SERVICE B	353-351 W 21ST ST &	RCRA NonGen / NLR, FINDS	Higher	378, 0.072, NE
J237	364 W. 15TH ST	364 W. 15TH ST	NY Spills	Higher	378, 0.072, South
P238	CON EDISON	352-35- W 21ST ST &	NY MANIFEST	Higher	380, 0.072, ENE
P239	CON EDISON	FO 352 WEST 21 ST	NY MANIFEST	Higher	380, 0.072, ENE
J240	CHELSEA CONDOMINIUMS	62-66 NINTH AVENUE	NY AST	Higher	381, 0.072, South
P241	MANHOLE #3794	WEST 21ST ST & 9TH A	NY Spills	Higher	381, 0.072, NE
N242	CONSOLIDATED EDISON	F/O 146-148 10TH AVE	NY MANIFEST	Lower	385, 0.073, NNW
K243	TENTH AVENUE CAR WAS	450 WEST 15TH STREET	NY AST	Lower	386, 0.073, WSW
K244	CON EDISON - VAULT 6	450 W 15 ST	RCRA-LQG, NY MANIFEST	Lower	386, 0.073, WSW
K245	CON EDISON - VAULT S	450 W 15 ST	NY MANIFEST	Lower	386, 0.073, WSW
K246	CON EDISON - TRENCH	450 W15 ST. W/O 9TH	RCRA-LQG, NY MANIFEST	Lower	386, 0.073, WSW
K247	RP STELLAR MILK LLC	450 WEST 15 STREET	NY AST	Lower	386, 0.073, WSW
K248	CHELSEA CAR WASH	450 W 15TH ST	NY LTANKS	Lower	386, 0.073, WSW
K249	BABOON PRODS	450 W 15TH ST - 3RD	RCRA NonGen / NLR, FINDS, ECHO	Lower	386, 0.073, WSW
K250	CON EDISON - VAULT V	450 W 15 ST	NY MANIFEST	Lower	386, 0.073, WSW
K251	TENTH AVENUE CAR WAS	450 WEST 15TH STREET	NY CBS, NY MANIFEST	Lower	386, 0.073, WSW
K252	CHELSEA CAR WASH	450 W 15TH ST	NY Spills	Lower	386, 0.073, WSW
K253	CONSTRUCTION SITE	450 WEST 15TH ST	NY Spills	Lower	386, 0.073, WSW
N254	CON EDISON SERVICE B	462 W 20TH ST OPPOSI	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	387, 0.073, NNW
L255	CON EDISON	OPP 342 W 17TH ST	NY MANIFEST	Higher	402, 0.076, SE
M256	ST. PETER'S EPISCOPA	336 WEST 20TH STREET	NY UST	Higher	402, 0.076, East
M257	CONSTR SITE	336 WEST 20TH ST	NY Spills	Higher	402, 0.076, East
K258	CON EDISON - VAULT S	454 W 15 ST	NY MANIFEST	Lower	406, 0.077, WSW
N259	150-10 BEAVER RD/QUE	150-10 BEAVER ROAD	NY Spills	Lower	410, 0.078, NNW
I260	LOT 29,TAXBLOCK 690	131 10 AVENUE	NY E DESIGNATION	Lower	416, 0.079, NW
I261	131 10TH AVENUE	131 10TH AVENUE	NY Spills	Lower	416, 0.079, NW
I262	MENDON LEASING CORP	131 TENTH AVE	NY UST	Lower	416, 0.079, NW
J263	VAULT 5311	W 14TH ST/9TH AVE	NY Spills	Higher	416, 0.079, SSW
I264	LEAVITT HOUSES -NYCH	139-10 34TH AVENUE	NY LTANKS	Lower	423, 0.080, NW
N265	152-156 TENTH AVE/MA	152-156 TENTH AVENUE	NY LTANKS	Lower	427, 0.081, NNW
N266	GETTY PETROLEUM CORP	152 10TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	427, 0.081, NNW
N267	GETTY 58542	152 TENTH AVE	NY LTANKS, NY UST	Lower	427, 0.081, NNW
N268	AA AAAA 24 HOUR EMRG	152 10TH AVE	EDR Hist Auto	Lower	427, 0.081, NNW
R269	342 WEST 21ST STREET	342 WEST 21ST STREET	NY AST	Higher	429, 0.081, ENE
N270	COMMERCIAL	156 TENTH AVE	NY Spills	Lower	429, 0.081, NNW
N271	CON EDISON SERVICE B	156 10TH AVE OPPOSIT	RCRA NonGen / NLR, NY MANIFEST	Lower	429, 0.081, NNW
O272	CON EDISON SERVICE B	437 W 21ST ST FRONT	RCRA NonGen / NLR, NY MANIFEST	Higher	432, 0.082, NNE

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
L273	338 WEST 17 LLC	338 WEST 17TH STREET	NY AST	Higher	432, 0.082, SE
J274	CON EDISON	56 9 AVE	NY MANIFEST	Higher	434, 0.082, South
J275	CON EDISON	56 9TH AVE	NY MANIFEST	Higher	434, 0.082, South
J276	OLD HOMESTEAD REST	56 NINTH AVE	NY Spills	Higher	434, 0.082, South
J277	CON EDISON	56 9TH AVE	RCRA NonGen / NLR	Higher	434, 0.082, South
J278	CON EDISON - SERVICE	59 9 AVE	NY MANIFEST	Higher	439, 0.083, SSW
O279	CHELSEA MANOR	421 WEST 21ST STREET	NY AST	Higher	439, 0.083, NNE
O280	DR. SERSINI	415 WEST 21ST STREET	NY LTANKS	Higher	439, 0.083, NNE
O281	415 W. 21ST STREET	415 W. 21ST STREET	NY LTANKS	Higher	439, 0.083, NNE
L282	CON EDISON	341 W 16TH ST FRONT	RCRA NonGen / NLR, NY MANIFEST	Higher	440, 0.083, SSE
L283	CON EDISON	341 W 16TH ST FRONT	NJ MANIFEST	Higher	440, 0.083, SSE
L284	BTWN 8TH & 9TH AVE	335 WEST 16TH ST	NY Spills	Higher	444, 0.084, SSE
L285	FRANK J DENOIA	335 WEST 16 ST	NY UST	Higher	444, 0.084, SSE
L286	A PARABLES TAIL	335 W 16TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	444, 0.084, SSE
O287	CON EDISON MANHOLE:	427 W 21ST ST FRONT	RCRA NonGen / NLR, NY MANIFEST	Higher	445, 0.084, NNE
O288	433 W. 21 STREET	433 WEST 21ST STREET	NY AST	Higher	445, 0.084, NNE
M289	CON EDISON	337-335 W 20TH ST &	NY MANIFEST	Higher	451, 0.085, ENE
Q290	89-10 63RD DR/QUEENS	89-10 63RD DRIVE	NY Spills	Lower	451, 0.085, West
R291	TEN GAL XFMR OIL IN	340 W 21 STREET	NY Spills	Higher	451, 0.085, ENE
N292	CON EDISON	438 W 19TH ST & 10TH	RCRA NonGen / NLR, FINDS, ECHO	Lower	453, 0.086, NW
P293	APHRODITE FRENCH CLE	182 9TH AVE	EDR Hist Cleaner	Higher	456, 0.086, NE
M294	CON EDISON	336 W 19TH ST	NY MANIFEST	Higher	458, 0.087, East
I295	CON EDISON - WEST 18	WEST 16TH - WEST 20T	EDR MGP	Lower	458, 0.087, NW
Q296	87-10 126TH ST/QUEEN	87-10 126TH STREET	NY Spills	Lower	460, 0.087, West
O297	445 WEST 21ST STREET	445 WEST 21ST STREET	NY UST	Lower	467, 0.088, North
P298	CON EDISON SERVICE B	189 9TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	478, 0.091, NE
S299	CON EDISON	48 9TH AVE	NY AST, NY Spills, NY MANIFEST	Higher	482, 0.091, South
S300	CON EDISON - SERVICE	48 9TH AVENUE	RCRA-LQG, NY MANIFEST, NJ MANIFEST	Higher	482, 0.091, South
M301	CON EDISON	FO 334 W 19 ST	NY MANIFEST	Higher	482, 0.091, ESE
Q302	85 TENTH AVENUE ASSO	85 10TH AVE	RCRA-LQG, FINDS, ECHO	Lower	483, 0.091, West
Q303	85 TENTH AVENUE ASSO	85 10TH AVE 1ST FLOO	NY MANIFEST	Lower	483, 0.091, West
Q304	85-10 120TH ST/QUEEN	85-10 120TH STREET	NY Spills	Lower	483, 0.091, West
Q305	85TH AVENUE ASSOCIAT	85TH 10TH AVE	PA MANIFEST	Lower	483, 0.091, West
Q306	BLENHEIM LLC	85 10TH AVE - BASEME	RCRA-VSQG, NY MANIFEST	Lower	483, 0.091, West
Q307	MANARK ASSOCIATES DI	85 10TH AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	483, 0.091, West
Q308	CON EDISON TRANSFORM	85 10TH AVE	NY Spills	Lower	483, 0.091, West
Q309	LODO REALTY	85 10TH AVE - 3RD FL	RCRA NonGen / NLR, FINDS, ECHO	Lower	483, 0.091, West
Q310	COMMERCIAL BUILDING	85 10TH AVE	NY Spills	Lower	483, 0.091, West
Q311	RELATED MANAGEMENT	85 TENTH AVENUE	NY AST	Lower	483, 0.091, West

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Q312	HAMMEL	85-10 ROCKAWAY BCH B	NY LTANKS	Lower	483, 0.091, West
L313	CARRIER CORP	332 W 16TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	485, 0.092, SSE
P314	BROWNSTONE	351 WEST 21ST STREET	NY Spills	Higher	487, 0.092, NE
M315	ROTA HOLDING CORP	335 W 19 STREET	NY AST	Higher	492, 0.093, East
N316	OLD GAS STATION	10TH AV / 20TH ST	NY Spills	Lower	494, 0.094, NNW
N317	CON EDISON SERVICE B	W 20TH ST & 10TH AVE	RCRA NonGen / NLR	Lower	494, 0.094, NNW
N318	CON EDISON SERVICE B	434-436 W 20TH ST &	RCRA NonGen / NLR	Lower	494, 0.094, NNW
N319	W 20 ST AND 10TH AVE	WEST 20TH ST & 10TH	NY Spills	Lower	494, 0.094, NNW
N320	CON EDISON SPLICE BO	W 20TH & 10TH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	494, 0.094, NNW
N321	CON EDISON SERVICE B	W 20TH ST & 10TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	494, 0.094, NNW
N322	CON EDISON	10 AVE & 20 ST	NY MANIFEST	Lower	494, 0.094, NNW
P323	CON EDISON	FO 353 WEST 21 ST	NY MANIFEST	Higher	495, 0.094, NE
N324	178-10 69TH AVE/QUEE	178-10 69TH AVE	NY LTANKS	Lower	495, 0.094, NNW
S325	ABBIS	55 NINTH AV	EDR Hist Auto	Higher	496, 0.094, SSW
Q326	NORTHEAST LABORATORY	99 10TH AVE ROOM 721	RCRA-SQG, FINDS, ECHO, NY MANIFEST, NJ MANIFEST	Lower	504, 0.095, West
Q327	DEA	99 10TH AVE.	NY AST, NY MANIFEST	Lower	504, 0.095, West
Q328	ABLE EMPIRE GROUP	99 TENTH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	504, 0.095, West
P329	APHRODITE FRENCH CLE	186 9TH AVE	NY DRYCLEANERS	Higher	505, 0.096, NE
P330	CHELSEA TAILOR	186 9TH AVE	EDR Hist Cleaner	Higher	505, 0.096, NE
T331	NYC BOARD OF EDUCATI	333 W 17TH ST	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Higher	507, 0.096, SE
T332	I.S. 70 - MANHATTAN	333 WEST 17TH STREET	NY AST	Higher	507, 0.096, SE
L333	CON EDISON	OPP 332 W 17TH ST	NY MANIFEST	Higher	507, 0.096, SE
L334	CON EDISON	332 W 17TH ST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	507, 0.096, SE
P335	RITE AID # 4196	188 9TH AVENUE	PA MANIFEST	Higher	520, 0.098, NE
P336	RITE AID #04196	188 9TH AVE	RCRA-VSQG, NY MANIFEST	Higher	520, 0.098, NE
U337	LOT 17,TAXBLOCK 689	501 WEST 17 STREET	NY E DESIGNATION	Lower	521, 0.099, WNW
U338	HLP PROPERTIES LOT	501-515 W 17TH ST	RCRA-SQG, NY MANIFEST	Lower	521, 0.099, WNW
U339	HLP PROPERTIES LOT	501-515 W 17TH ST	NJ MANIFEST	Lower	521, 0.099, WNW
U340	WEST 17TH STREET DEV	501-515 WEST 17TH ST	NY UST	Lower	521, 0.099, WNW
S341	401 WEST 14TH STREET	401 W 14TH ST	RCRA-VSQG, NY MANIFEST	Higher	522, 0.099, SSW
S342	401 WEST 14TH STREET	401 WEST 14TH STREET	PA MANIFEST	Higher	522, 0.099, SSW
V343	FEEDER MANHOLE #0256	WEST 15 STREET & 10	NY Spills	Lower	522, 0.099, WSW
R344	CON EDISON	347-345 W 21ST ST &	NY MANIFEST	Higher	526, 0.100, ENE
N345	214765; 184-10 JAMAI	184-10 JAMAICA AVENU	NY Spills	Lower	526, 0.100, NNW
T346	CONSOLIDATED EDISON	330 WEST 17 ST	NY MANIFEST	Higher	531, 0.101, SE
T347	CON EDISON	OPP 330 W 17TH ST	NY MANIFEST	Higher	531, 0.101, SE
T348	CON EDISON SERVICE B	330 W 17TH ST SB 302	RCRA NonGen / NLR	Higher	531, 0.101, SE
T349	CONSOLIDATED EDISON	330 W 17TH ST	NY MANIFEST	Higher	531, 0.101, SE
L350	ROJAS RAFAEL	331 W 16TH ST	EDR Hist Auto	Higher	531, 0.101, SSE

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
T351	CON EDISON	FO 326 W 18 ST	NY MANIFEST	Higher	534, 0.101, ESE
W352	SERVICE BOX #02343	427 WEST 14TH ST BTW	NY Spills	Lower	539, 0.102, SW
W353	SEVICE BOX 2343	427 WEST 14TH ST.	NY Spills	Lower	539, 0.102, SW
X354	CON EDISON	OP 344 W 15 ST	NY MANIFEST	Higher	541, 0.102, South
N355	LOT 33,TAXBLOCK 691	161 10 AVENUE	NY E DESIGNATION	Lower	543, 0.103, NNW
N356	DANNY'S PARKING LOT	161-165 10TH AVE	NY Spills	Lower	543, 0.103, NNW
N357	CON EDISON SERVICE B	161 10TH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	543, 0.103, NNW
V358	V0600	81 10TH AVENUE	RCRA NonGen / NLR, NY MANIFEST	Lower	544, 0.103, WSW
N359	LOT 35,TAXBLOCK 691	165 10 AVENUE	NY E DESIGNATION	Lower	547, 0.104, NNW
N360	D VITANZA REPAIR & S	165 10TH AVE	EDR Hist Auto	Lower	547, 0.104, NNW
T361	CON EDISON	F/O 329 W 17TH ST	NY MANIFEST	Higher	553, 0.105, SE
Y362	CON EDISON	326-324 W 20TH ST &	NY MANIFEST	Higher	553, 0.105, East
S363	351 WEST 14TH ST	351 WEST 14TH STREET	NY UST	Higher	556, 0.105, South
S364	351-355 W 14TH ST	351-355 W 14TH ST	NY Spills	Higher	556, 0.105, South
S365	351 WEST 14TH ST	351 WEST 14TH STREET	NY AST	Higher	556, 0.105, South
Z366	KAMCO SUPPLY CORP.	501 WEST 19TH STREET	NY UST	Lower	561, 0.106, NW
Z367	FORMER BUILDING SUPP	501-513 WEST 19TH ST	NY Spills	Lower	561, 0.106, NW
Z368	KAMCO SUPPLY CORP.	501 WEST 19TH STREET	NY AST	Lower	561, 0.106, NW
AA369	EMPIRE CITY SUBWAY C	177-183 10TH AVE	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Lower	567, 0.107, NNW
AA370	EMPIRE CITY SUBWAY C	177-83 10TH AVENUE	NY AST	Lower	567, 0.107, NNW
AA371	EMPIRE CITY SUBWAY C	177-83 10TH AVENUE	NY UST	Lower	567, 0.107, NNW
T372	325 WEST 16TH STREET	325 WEST 16TH STREET	NY AST	Higher	568, 0.108, SSE
O373	MINICK HOME	440 WEST 22ND STREET	NY LTANKS	Higher	570, 0.108, NNE
S374	CON EDISON SERVICE B	45 9TH AVE N OF 205	NJ MANIFEST	Higher	570, 0.108, SSW
S375	CON EDISON SERVICE B	45 9TH AVE N OF 205	RCRA NonGen / NLR	Higher	570, 0.108, SSW
AA376	CON EDISON SERVICE B	467 W 21ST ST	RCRA NonGen / NLR, FINDS	Lower	571, 0.108, North
AA377	CON EDISON	467 W 21ST ST	NY MANIFEST	Lower	571, 0.108, North
S378	CON EDISON - SERVICE	WEST 14TH STREET AND	RCRA-LQG	Higher	571, 0.108, SSW
S379	CON EDISON SERVICE B	14TH ST & 9TH AVE	RCRA NonGen / NLR	Higher	571, 0.108, SSW
380	SPERANZA PROPERTIES	448 W 22ND ST	RCRA-VSQG, NY MANIFEST	Higher	574, 0.109, NNE
V381	70 TENTH AVENUE	70 TENTH AVE	NY Spills	Lower	574, 0.109, WSW
V382	CHELSEA CAR WASH	70 10TH AVE	EDR Hist Auto	Lower	574, 0.109, WSW
V383	CHELSEA CAR WASH / M	70 TENTH AVE	NY Spills	Lower	574, 0.109, WSW
U384	LOT 20,TAXBLOCK 690	511 WEST 18 STREET	NY E DESIGNATION	Lower	575, 0.109, NW
U385	515 WEST 18TH STREET	511 WEST 18TH STREET	NY BROWNFIELDS	Lower	575, 0.109, NW
U386	WAREHOUSE BUILDING	511 WEST 18TH STREET	NY Spills	Lower	575, 0.109, NW
W387	CON EDISON - TRANSFO	WASHINGTON ST & W 14	NJ MANIFEST	Lower	577, 0.109, SW
W388	CON ED	WASHINGTON ST & W 14	NY MANIFEST	Lower	577, 0.109, SW
W389	CON EDISON - TRANSFO	WASHINGTON ST & W 14	RCRA-LQG	Lower	577, 0.109, SW

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Z390	CON ED	505 W 19TH ST	NY MANIFEST	Lower	580, 0.110, NW
Z391	HFZ HIGHLINE PROPERT	505 W. 19TH STREET	PA MANIFEST	Lower	580, 0.110, NW
Z392	LOT 7502,TAXBLOCK 69	505 WEST 19 STREET	NY E DESIGNATION	Lower	580, 0.110, NW
Z393	HFZ HIGHLINE PROPERT	505 W 19TH ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	580, 0.110, NW
Z394	CON EDISON SERVICE B	507 W 19TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	581, 0.110, NW
S395	CON EDISON	345 W 14TH ST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	583, 0.110, South
X396	CON EDISON	338 W 15TH ST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	583, 0.110, South
V397	LOT 1,TAXBLOCK 712	58 10 AVENUE	NY E DESIGNATION	Lower	584, 0.111, WSW
S398	CON EDISON SERVICE B	340-338 W 14TH ST &	RCRA NonGen / NLR, FINDS	Higher	584, 0.111, SSW
V399	CON EDISON SERVICE B	69 10TH AVE FRONT OF	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	584, 0.111, WSW
U400	515 W 18 ST	515 WEST 18TH ST	NY Spills	Lower	587, 0.111, NW
U401	MENDON LEASING CORP	515 W 18TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST, NY...	Lower	587, 0.111, NW
U402	MENDON LEASING CORP.	515 WEST 18TH STREET	NY LTANKS	Lower	587, 0.111, NW
U403	515 W 18TH ST	515 WEST 18TH STREET	NY UST	Lower	587, 0.111, NW
S404	CON EDISON	HUDSON ST & W 14TH S	RCRA NonGen / NLR	Higher	588, 0.111, SSW
S405	CON EDISON	HUDSON ST & W 14TH S	NJ MANIFEST	Higher	588, 0.111, SSW
S406	CON EDISON	HUDSON ST & W 14 ST	NY MANIFEST	Higher	588, 0.111, SSW
AB407	SPILL NUMBER 0104249	360 WEST 22ND ST	NY Spills	Higher	598, 0.113, NE
T408	CON EDISON	325-323 W 17 ST & 9	NY MANIFEST	Higher	599, 0.113, SE
AA409	CON EDISON	500 W 21ST ST	NJ MANIFEST	Lower	602, 0.114, NNW
AA410	CON EDISON	500 W 21ST ST	NY MANIFEST	Lower	602, 0.114, NNW
AA411	CON EDISON SB3769	500 W 21ST ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	602, 0.114, NNW
AA412	CON EDISON SERVICE B	W 21ST ST & 10TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	607, 0.115, NNW
AA413	CON EDISON SERVICE B	W 21ST ST & 10TH AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	607, 0.115, NNW
U414	555 WEST 17TH ST/MAN	555 WEST 17TH STREET	NY LTANKS	Lower	607, 0.115, WNW
Y415	CON EDISON SERVICE B	320-318 W 20TH ST &	NJ MANIFEST	Higher	607, 0.115, East
Y416	CON EDISON	320-318 W 20TH ST &	NY MANIFEST	Higher	607, 0.115, East
T417	324 W 17 ST	324 WEST 17TH STREET	NY AST	Higher	607, 0.115, SE
AC418	319 WEST 18TH ST. OW	319 WEST 18TH STREET	NY AST	Higher	608, 0.115, ESE
AA419	CON EDISON SERVICE B	473 W 21ST ST & 10TH	RCRA NonGen / NLR	Lower	611, 0.116, NNW
AA420	CON EDISON SERVICE B	W 21ST ST & 10 TH AV	NJ MANIFEST	Lower	611, 0.116, NNW
AA421	CON ED MANHOLE 43089	10TH AVE AND W 21ST	NY Spills	Lower	611, 0.116, NNW
AA422	SW CORNER OF	WEST 21ST AND TENTH	NY Spills	Lower	611, 0.116, NNW
X423	APARTMENT	335 WEST 14TH ST	NY Spills	Higher	615, 0.116, South
X424	335-7 WEST 14TH STRE	335-7 WEST 14TH STRE	NY AST	Higher	615, 0.116, South
AA425	177-82 10TH AVE	BETWEEN 20TH & 21ST	NY Spills	Lower	617, 0.117, NNW
AD426	CON EDISON SERVICE B	408 W 14TH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	621, 0.118, SSW
AD427	CONSOLIDATED EDISON	416 W 14 ST MH2355	NY MANIFEST	Lower	621, 0.118, SSW
Y428	CHELSEA 19TH ST. OWN	320 WEST 19TH STREET	NY AST	Higher	621, 0.118, ESE

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
R429	PUBLIC SCHOOL 11 - M	320 WEST 21ST STREET	NY AST	Higher	623, 0.118, ENE
R430	NYC BD OF ED WILLIAM	320 W 21ST ST	RCRA-VSQG, US AIRS, NY MANIFEST	Higher	623, 0.118, ENE
Y431	CON EDISON	315-313 W 20TH ST &	NY MANIFEST	Higher	623, 0.118, East
AA432	EMPIRE CITY SUBWAY G	169 10TH AVE	NY Spills	Lower	626, 0.119, NNW
AA433	LOT 30,TAXBLOCK 692	169 10 AVENUE	NY E DESIGNATION	Lower	626, 0.119, NNW
W434	MOBIL	451 WEST 14TH ST	NY Spills	Lower	628, 0.119, WSW
U435	CON EDISON SERVICE B	525 W 18TH ST OPPOSI	RCRA NonGen / NLR, NY MANIFEST	Lower	628, 0.119, NW
U436	CON EDISON SERVICE B	525 W 18TH ST E OF 1	NJ MANIFEST	Lower	628, 0.119, NW
U437	CON EDISON SERVICE B	525 W 18TH ST E OF 1	RCRA NonGen / NLR, NY MANIFEST	Lower	628, 0.119, NW
V438	HUDSON PIER BUS DEPO	W 15TH ST + 11TH AVE	NY Spills	Lower	631, 0.120, West
T439	CON EDISON	322 W 17TH ST	NY MANIFEST	Higher	632, 0.120, SE
T440	CON EDISON	322 W 17TH ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	632, 0.120, SE
T441	CON EDISON	F/O 322 W 17 ST	NY MANIFEST	Higher	632, 0.120, SE
T442	CON EDISON	322 W 17TH ST	NJ MANIFEST	Higher	632, 0.120, SE
AA443	RESIDENCE	188 10TH AVE	NY Spills	Lower	634, 0.120, North
AB444	CON EDISON - MANHOLE	22 ST & 9TH AVE	NY MANIFEST	Higher	635, 0.120, NE
R445	CON EDISION - SB3785	F/O 331 W.21 ST. F/O	RCRA NonGen / NLR, NY MANIFEST	Higher	637, 0.121, ENE
AD446	LOMEL REALTY CORP	418 WEST 14TH ST	NY AST	Lower	637, 0.121, SW
Z447	520 WEST 19TH STREET	516-522 W 19TH ST	RCRA-VSQG, NY MANIFEST	Lower	643, 0.122, NW
Y448	CON EDISON	316-12 W 20TH ST & 9	NY MANIFEST	Higher	647, 0.123, East
Z449	LOT 37,TAXBLOCK 691	504 WEST 20 STREET	NY E DESIGNATION	Lower	651, 0.123, NNW
Z450	CON EDISON SERVICE B	511 W 19TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	657, 0.124, NW
W451	TENTH AVENUE CAR WAS	461-469 WEST 14TH ST	NY AST	Lower	657, 0.124, WSW
W452	GAS STATION/CAR WASH	461-469 WEST 14TH ST	NY Spills	Lower	657, 0.124, WSW
W453	EXPLOSION AT FORMER	461-469 WEST 14TH ST	NY Spills	Lower	657, 0.124, WSW
W454	TENTH AVENUE CAR WAS	461-469 WEST 14TH ST	NY UST	Lower	657, 0.124, WSW
W455	CON EDISON	442 W 14TH ST	NY MANIFEST	Lower	657, 0.124, SW
W456	CON EDISON SERVICE B	442 W 14TH ST	RCRA NonGen / NLR	Lower	657, 0.124, SW
T457	CON EDISON	319 W 16TH ST	NY MANIFEST	Higher	657, 0.124, SE
X458	328 W 15TH OWNER COR	328 W 15TH ST	NY AST	Higher	658, 0.125, SSE
X459	SUZUKI RESIDENCE	328 WEST 15TH ST	NY Spills	Higher	658, 0.125, SSE
W460	CON EDISON SERVICE B	872 WASHINGTON ST	RCRA NonGen / NLR, NY MANIFEST	Lower	658, 0.125, SW
X461	MOUNT SINAI - BETH I	325 W 15TH ST	RCRA-LQG, NY MANIFEST	Higher	680, 0.129, SSE
AB462	JEAN'S MANHATTAN CLE	198 9TH AVE	RCRA-VSQG, FINDS, ECHO, NY MANIFEST, RI MANIFEST	Higher	688, 0.130, NE
AB463	JEAN'S MANHATTAN FRE	198 9TH AVENUE	NY DRYCLEANERS	Higher	688, 0.130, NE
AE464	NYCT HUDSON DEPOT	1101 11TH AVENUE	NY LTANKS	Lower	695, 0.132, West
X465	342 W 14 ST	342 WEST 14TH STREET	NY AST	Higher	696, 0.132, South
AF466	CON EDISON SERVICE B	419 W 22ND ST OPPOSI	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	696, 0.132, NNE
S467	CON EDISON	348-346 W 14TH ST &	NY MANIFEST	Higher	701, 0.133, South

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Y468	CON EDISON	FO 317 W 19 ST	NY MANIFEST	Higher	704, 0.133, East
X469	CON EDISON	340-338 W 14TH ST &	NY MANIFEST	Higher	706, 0.134, South
X470	CON EDISON	310 W 15TH ST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	708, 0.134, SSE
AB471	CON EDISON SERVICE B	200 E 9TH AVE FRONT	RCRA NonGen / NLR	Higher	709, 0.134, NE
AB472	CON EDISON	200 E 9TH AVE FRONT	NY MANIFEST	Higher	709, 0.134, NE
AG473	CON EDISON SERVICE B	196 10TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	710, 0.134, North
Z474	CON EDISON	522 W 19 ST	NY MANIFEST	Lower	710, 0.134, NW
AH475	CON EDISON SERVICE B	323 W 21ST ST FRONT	RCRA NonGen / NLR, NY MANIFEST	Higher	711, 0.135, ENE
AE476	CON EDISON SERVICE B	11TH AVE & 16TH ST O	RCRA NonGen / NLR	Lower	716, 0.136, West
X477	CON EDISON	327 W 14TH ST	NY MANIFEST	Higher	718, 0.136, South
W478	CON EDISON SERVICE B	866 WASHINGTON ST	RCRA NonGen / NLR	Lower	725, 0.137, SW
W479	V0508	866 WASHINGTON STREE	RCRA NonGen / NLR, NY MANIFEST	Lower	725, 0.137, SW
W480	V0508	866 WASHINGTON AVENU	RCRA NonGen / NLR, NY MANIFEST	Lower	725, 0.137, SW
AE481	NYCT - HUDSON DEPOT	WEST 15TH ST & 11TH	RCRA-VSQG	Lower	727, 0.138, West
AE482	HUDSON PIER DEPOT	WEST 15TH ST & 11TH	NY LTANKS, NY Spills	Lower	727, 0.138, West
AB483	CON EDISON	FO 361 WEST 22 ST	NY MANIFEST	Higher	727, 0.138, NE
T484	CON EDISON	F/O 317 W 17TH ST	NY MANIFEST	Higher	728, 0.138, SE
AB485	CON EDISON	FO 357 WEST 22ND ST	NY MANIFEST	Higher	738, 0.140, NE
AA486	GUARDIAN ANGEL SCHOO	193 10TH AVE	NY LTANKS, NY Spills	Lower	740, 0.140, North
AA487	GUARDIAN ANGEL	193 10TH AVENUE	NY UST	Lower	740, 0.140, North
AA488	193-10 PECK AVE	193-10 PECK AVE	NY LTANKS	Lower	740, 0.140, North
AA489	GUARDIAN ANGEL CHURC	193 10TH AVE	NY LTANKS	Lower	740, 0.140, North
T490	HIGH LINE	GANSEVOORT STREET TO	US BROWNFIELDS	Higher	741, 0.140, SE
AI491	CON EDISON	304 W 15TH ST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	743, 0.141, SSE
AB492	CON ED	355 W 22 ST	NY MANIFEST	Higher	744, 0.141, NE
T493	NYC BD OF ED - PUBLI	315 W 17TH ST	RCRA NonGen / NLR	Higher	744, 0.141, SE
T494	NYC BD OF ED - PUBLI	315 W 17TH ST - NEW	RCRA NonGen / NLR	Higher	744, 0.141, SE
Y495	CON EDISON	309-307 W 20TH ST &	NY MANIFEST	Higher	745, 0.141, East
AJ496	CON EDISON	344-342 W 14TH ST &	NY MANIFEST	Higher	746, 0.141, South
AC497	THE 305 CONDOMINIUM	305 WEST 18TH STREET	NY AST	Higher	750, 0.142, ESE
AK498	WEST 19TH STREET DEV	528 WEST 19TH STREET	NY UST	Lower	755, 0.143, NW
AK499	MUCCIO JOHN	528 W 19TH ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	755, 0.143, NW
AH500	301-303 WEST 21ST ST	301-303 WEST 21ST ST	NY AST	Higher	755, 0.143, ENE
AB501	CON ED	351 W 22ND ST	NY MANIFEST	Higher	755, 0.143, NE
Y502	CON EDISON	306 W 20TH ST	NY MANIFEST	Higher	757, 0.143, East
AC503	CON EDISON	308-306 W 19TH ST &	NY MANIFEST	Higher	759, 0.144, ESE
AK504	IAC BUILDING	555 WEST 18TH STREET	NY AST	Lower	759, 0.144, NW
AC505	310 WEST 18TH STREET	310 WEST 18TH STREET	NY TANKS, NY Spills	Higher	760, 0.144, ESE
AC506	310 WEST 18TH STREET	310 WEST 18TH STREET	NY LTANKS	Higher	760, 0.144, ESE

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AJ507	CON EDISON	334-30 W 14TH ST & H	NY MANIFEST	Higher	764, 0.145, South
Y508	CON EDISON	307 W 20TH ST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	767, 0.145, East
Z509	WESTSIDE AUTO CARE I	521 WEST 19TH STREET	NY AST	Lower	769, 0.146, NW
AH510	CON EDISON	OPP 317 W 21 ST	NY MANIFEST	Higher	771, 0.146, ENE
AA511	513 WEST 20TH STREET	513 WEST 20TH STREET	NY AST	Lower	777, 0.147, NNW
AH512	ISMO, LLC	315 WEST 21ST STREET	NY AST	Higher	777, 0.147, ENE
AD513	CON EDISON SERVICE B	29 9TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	779, 0.148, SSW
AD514	29-35 NINTH AVE (AT	29-35 NINTH AVENUE	NY AST	Higher	779, 0.148, SSW
AD515	CON EDISON SERVICE B	29 9TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	779, 0.148, SSW
AD516	CON EDISON	29 9TH AVE	NJ MANIFEST	Higher	779, 0.148, SSW
AD517	CON EDISON	29 9TH AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	779, 0.148, SSW
AC518	308 WEST 18TH ST	308 WEST 18TH ST	NY LTANKS	Higher	782, 0.148, ESE
AL519	CON EDISON	F/O 311 WEST 17 ST	NY MANIFEST	Higher	787, 0.149, SE
AL520	CON EDISON	311 W 17TH ST	NJ MANIFEST	Higher	787, 0.149, SE
AL521	CON EDISON	311 W 17TH ST	RCRA NonGen / NLR	Higher	787, 0.149, SE
AL522	CON EDISON	311 W 17TH ST	RCRA NonGen / NLR	Higher	787, 0.149, SE
AL523	CON EDISON	311 W 17TH ST	NY MANIFEST	Higher	787, 0.149, SE
AL524	CON EDISON	311 W 17TH ST	NY MANIFEST	Higher	787, 0.149, SE
AL525	CON EDISON	311 W 17TH ST	NJ MANIFEST	Higher	787, 0.149, SE
AK526	MENDON	542 WEST 19TH STREET	NY LTANKS	Lower	790, 0.150, NW
AK527	MENDON LEASING CORP	542 WEST 19TH ST	NY UST	Lower	790, 0.150, NW
W528	860 WASHINGTON STREE	860 WASHINGTON ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	794, 0.150, SW
AG529	CONSOLIDATED EDISON	10TH AVE & W 22ND ST	NY MANIFEST	Lower	796, 0.151, North
AG530	CON EDISON GASMAIN 8	10TH AVE & W 22 ST	RCRA-LQG	Lower	796, 0.151, North
AG531	CON EDISON - MANHOLE	OPP 197 10TH AVE	RCRA-LQG, NY MANIFEST	Lower	797, 0.151, North
AM532	SUNOCO S/S-501 W 14T	501 WEST 14TH STREET	RCRA NonGen / NLR, US AIRS, FINDS, ECHO	Lower	798, 0.151, WSW
AM533	1014 GAS CORP	501 WEST 14TH ST	NY UST	Lower	798, 0.151, WSW
AM534	501 W 14TH ST	501 W 14TH ST	NY LTANKS	Lower	798, 0.151, WSW
AM535	505 W.14TH ST	505 W.14TH ST / 10TH	NY LTANKS	Lower	799, 0.151, WSW
AM536	HUDSON PIER BUS DEPO	11 AVE/WEST 15 STREE	NY CBS, NY AST, NY CBS AST	Lower	801, 0.152, WSW
Y537	CON EDISON SERVICE B	305 W 20TH ST FRONT	RCRA NonGen / NLR, FINDS	Higher	804, 0.152, East
Y538	CON EDISON	305 W 20TH ST FRONT	NY MANIFEST	Higher	804, 0.152, East
AC539	306 W. 18 REALTY LLC	306 WEST 18TH ST	NY UST	Higher	807, 0.153, ESE
AI540	312-316 WEST 15TH ST	312-316 WEST 15TH ST	NY AST	Higher	808, 0.153, SSE
AA541	STORAGE USA	510 WEST 21ST STREET	NY UST	Lower	812, 0.154, NNW
AD542	CON EDISON - SERVICE	407 WEST 13TH ST	RCRA-LQG, NY MANIFEST	Lower	814, 0.154, SSW
AK543	17TH STREET DEVELOPM	76 11TH AVE	RCRA-LQG	Lower	819, 0.155, NW
AK544	17TH STREET DEVELOPM	76 11TH AVENUE	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS	Lower	819, 0.155, NW
AK545	76 ELEVENTH AVENUE P	76 11TH AVENUE	PA MANIFEST	Lower	819, 0.155, NW

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AN546	CON ED	307 W 19TH STREET	NY MANIFEST	Higher	823, 0.156, East
AG547	NEW YORK STATE DEC	507 W 21ST ST	NY LTANKS, NY Spills, RCRA NonGen / NLR, NY...	Lower	826, 0.156, NNW
AG548	HENRY & LLOYD CO THE	507 W 21ST ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	826, 0.156, NNW
AG549	THE HENRY LLOYD COMP	507 WEST 21ST STREET	NY UST	Lower	826, 0.156, NNW
AN550	CON EDISON	300 W 20TH ST FRONT	NY MANIFEST	Higher	832, 0.158, East
AN551	CON EDISON SERVICE B	300 W 20TH ST FRONT	RCRA NonGen / NLR	Higher	832, 0.158, East
AH552	311 WEST 21ST STREET	311 WEST 21ST STREET	NY AST	Higher	833, 0.158, ENE
AK553	19TH STREET DEVELOPM	80 11TH AVENUE	EDR MGP	Lower	835, 0.158, NW
AK554	19TH STREET DEVELOPM	80 11TH AVENUE	NY ENG CONTROLS, NY INST CONTROL, NY VCP, NY...	Lower	835, 0.158, NW
AM555	11 ELEVENTH AVENUE	11 ELEVENTH AVENUE	NY LTANKS	Lower	836, 0.158, WSW
AH556	304-306 WEST 21ST ST	304-306 WEST 21ST ST	NY UST	Higher	836, 0.158, East
AO557	CON EDISON	FO 333 WEST 22ND ST	NY MANIFEST	Higher	837, 0.159, ENE
AI558	CON EDISON-SERVICE B	317 W 15TH ST & 8TH	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	843, 0.160, SSE
AI559	CON EDISON SERVICE B	317 W 15TH ST & 8TH	RCRA NonGen / NLR	Higher	843, 0.160, SSE
AM560	GLUE FAST EQUIPMENT	9-11 WHITE ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	844, 0.160, WSW
AF561	CON EDISON	426 W 23RD ST	RCRA NonGen / NLR	Higher	845, 0.160, NNE
AF562	CON EDISON SERVICE B	428 W 23RD ST FRONT	RCRA NonGen / NLR, NY MANIFEST	Higher	846, 0.160, NNE
AF563	WEST 23RD STREET OWN	410 W 23RD ST	NY AST	Higher	846, 0.160, NNE
AM564	CON EDISON SERVICE B	55 10TH AVE N OF 34T	NJ MANIFEST	Lower	848, 0.161, WSW
AM565	CON EDISON SERVICE B	55 10TH AVE N OF 34T	RCRA NonGen / NLR	Lower	848, 0.161, WSW
AM566	CON EDISON	55 10TH AVE N OF 34T	NY MANIFEST	Lower	848, 0.161, WSW
AF567	CON EDISON	400 W 23RD ST	NY MANIFEST	Higher	848, 0.161, NE
AF568	CON EDISON	400 W 23RD ST	NJ MANIFEST	Higher	848, 0.161, NE
AF569	CON EDISON	400 W 23RD ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	848, 0.161, NE
AK570	535 WEST 19TH STREET	535 WEST 19TH STREET	NY UST	Lower	849, 0.161, NW
AK571	535 WEST 19TH STREET	535 WEST 19TH STREET	NY BROWNFIELDS, NY Spills	Lower	849, 0.161, NW
AK572	WEST CHELSEA DEVELOP	535 W 19TH ST - VACA	RCRA-VSQG, NY MANIFEST	Lower	849, 0.161, NW
AK573	84-11 ELMHURST AVE/Q	84-11 EILMHURST AVEN	NY LTANKS	Lower	852, 0.161, NW
AK574	84-11 ELMHURST AV/QU	84-11 ELMHURST AVENU	NY LTANKS	Lower	852, 0.161, NW
AK575	86-11 34TH AVENUE	86-11 34TH AVENUE	NY LTANKS	Lower	861, 0.163, NW
AP576	TIME WARNER CABLE OF	511 WEST 21ST STREET	NY UST	Lower	861, 0.163, NNW
AP577	TIME WARNER CABLE	511 WEST 21ST ST	NY AST, NY ENG CONTROLS, NY INST CONTROL, NY...	Lower	861, 0.163, NNW
AQ578	CON EDISON SERVICE B	316 W 14TH ST & 8TH	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	861, 0.163, South
AI579	309 WEST 14TH STREET	309 WEST 14TH STREET	NY AST	Higher	862, 0.163, SSE
AC580	CON EDISON	161-163 W 8TH AVE &	NY MANIFEST	Higher	863, 0.163, ESE
AR581	NYCDEP	13TH ST & 9TH AVE	NY MANIFEST	Higher	866, 0.164, SSW
AS582	CON EDISON SERVICE B	451 W 13TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	875, 0.166, SW
AO583	350 WEST 23RD, LLC	350 WEST 23RD STREET	NY AST	Higher	875, 0.166, NE
AO584	CON EDISON SERVICE B	350 W 23RD ST	NJ MANIFEST	Higher	875, 0.166, NE

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AO585	CON EDISON SERVICE B	350 W 23RD ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	875, 0.166, NE
AM586	CON EDISON VAULT SUB	1-11 WEST ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	879, 0.166, WSW
AN587	JOYCE THEATER	171-175 8TH AVENUE	NY AST	Higher	882, 0.167, ESE
AJ588	CON EDISON MANHOLE:	W 13TH ST & HUDSON S	RCRA NonGen / NLR, NY MANIFEST	Higher	892, 0.169, SSW
AJ589	CON EDISON MANHOLE:	W 13TH ST & HUDSON S	RCRA NonGen / NLR, NY MANIFEST	Higher	892, 0.169, SSW
AN590	MANHATTAN ASSOCIATES	301-317 WEST 19TH ST	NY AST	Higher	895, 0.170, ESE
AM591	SUNOCO STATION (VACA	14TH STREET & WEST S	NY AST	Lower	897, 0.170, WSW
AL592	CON EDISON	135-37 8TH AVE & 16T	NY MANIFEST	Higher	897, 0.170, SE
AL593	CON ED	133 8TH AVE	NY MANIFEST	Higher	898, 0.170, SE
AT594	KWIK INTL COLOR LTD	111 8TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	899, 0.170, SE
AT595	CABLEVIEW PUBLICATIO	111 8TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	899, 0.170, SE
AT596	NEW YORK TELEPHONE C	111 8TH AVE - 2ND FL	RCRA NonGen / NLR, FINDS, ECHO	Higher	899, 0.170, SE
AT597	SPRINT COMMUNICATION	111 EIGHTH AVENUE	NY AST	Higher	899, 0.170, SE
AT598	V L G NORTH AMERICA	111 8TH AVE STE 500	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	899, 0.170, SE
AT599	ONE CITY BLOCK, LLC	111 8TH AVE	NY AST	Higher	899, 0.170, SE
AT600	STATE INSURANCE FUND	111 8TH AVE 10TH FLO	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	899, 0.170, SE
AT601	INSIGNIA ESG	111 8TH AVE - BASEME	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	899, 0.170, SE
AT602	EFFECTS HOUSE THE	111 8TH AVE RM 914	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	899, 0.170, SE
AT603	CON EDISON - 111 8TH	111 8TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	899, 0.170, SE
AT604	GOLDMAN SACHS & CO-1	111 8TH AVENUE ROOM	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	899, 0.170, SE
AT605	MORGAN GUARANTY TRUS	111 8TH AVE	RCRA NonGen / NLR	Higher	899, 0.170, SE
AJ606	CON EDISON SERVICE B	339 W 13TH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	900, 0.170, South
AJ607	MONADNOCK CONSTRUCTI	339-345 W 13TH ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	900, 0.170, South
AM608	GOTHAM WEST DEVELOPM	592 11TH AVE	NY UST	Lower	900, 0.170, WSW
AU609	CON EDISON SERVICE B	350 W 23RD ST & 9TH	RCRA NonGen / NLR, FINDS	Higher	906, 0.172, NE
AU610	CON EDISON SERVICE B	335 W 23RD ST & 9TH	RCRA NonGen / NLR, FINDS	Higher	906, 0.172, NE
AU611	CON EDISON SERVICE B	366 W 23RD ST & 9TH	RCRA NonGen / NLR, FINDS	Higher	906, 0.172, NE
AU612	CON EDISON SERVICE B	363-61 W 23RD ST & 9	RCRA NonGen / NLR, FINDS	Higher	906, 0.172, NE
AU613	CON EDISON SERVICE B	316 W 23RD ST & 9TH	RCRA NonGen / NLR, FINDS	Higher	906, 0.172, NE
AU614	CON EDISON SERVICE B	341 W 23RD ST & 9TH	RCRA NonGen / NLR, FINDS	Higher	906, 0.172, NE
AU615	CON EDISON SERVICE B	324-22 W 23RD ST & 9	RCRA NonGen / NLR, FINDS	Higher	906, 0.172, NE
AU616	CON EDISON	9TH AVE & W 23RD ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	916, 0.173, NE
AU617	CON EDISON	9TH AVE & W 23RD ST	NY MANIFEST	Higher	916, 0.173, NE
AU618	CON EDISON	9TH AVE & W 23RD ST	NJ MANIFEST	Higher	916, 0.173, NE
AU619	CON EDISON - MANHOLE	23 & 9TH AVE	NY MANIFEST	Higher	916, 0.173, NE
AG620	505 W 22ND STREET	505 W 22ND STREET	NY AST	Lower	923, 0.175, North
AK621	CON ED - V 4289	532 W 20 ST	RCRA NonGen / NLR, NY MANIFEST	Lower	926, 0.175, NW
AG622	211-10-02 73RD AVE/Q	211-10-02 73RD AVENU	NY LTANKS	Lower	927, 0.176, North
AG623	CON EDISON MANHOLE:	211 10TH AVE FRONT O	RCRA NonGen / NLR, NY MANIFEST	Lower	927, 0.176, North

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AV624	GREENWAY MEWS REALTY	416 WEST 13TH STREET	PA MANIFEST	Lower	929, 0.176, SSW
AV625	GREENWAY MEWS REALTY	416 WEST 13TH STREET	NY AST	Lower	929, 0.176, SSW
AV626	GREENWAY MEWS REALTY	416 W 13TH ST #300	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Lower	929, 0.176, SSW
AQ627	304-10 W. 14 REALTY	310 W 14TH STREET	NY AST	Higher	931, 0.176, South
AQ628	EVERGREEN CLEANERS	310 W 14TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	931, 0.176, South
AW629	300 WEST 21ST STREET	300 WEST 21ST STREET	NY AST	Higher	933, 0.177, East
AI630	C D O REALTY CORP	301 W 154 ST	NY AST	Higher	935, 0.177, SSE
AJ631	ST BERNARD SCHOOL	327 WEST 13TH STREET	NY AST	Higher	936, 0.177, South
AN632	RITE AID # 10531	195 8TH AVENUE	PA MANIFEST	Higher	937, 0.177, East
AN633	RITE AID #10531	195 8TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	937, 0.177, East
AE634	PIER 57- 11TH AVENUE	PIER 57 / 11TH AVENU	NY LTANKS	Lower	939, 0.178, West
AE635	PIER 57 & HUDSON DEP	15TH ST & ROUTE 9A	NY LTANKS	Lower	939, 0.178, West
AE636	PIER 57- WESTSIDE HI	W.17TH ST WESTSIDE H	NY LTANKS	Lower	939, 0.178, West
AP637	CONSOLIDATED EDISON	519 W 21 ST SB3762	NY MANIFEST	Lower	939, 0.178, NNW
AS638	A B GREEN GANSEVOORT	856 WASHINGTON ST	RCRA-VSQG, NY MANIFEST	Lower	940, 0.178, SW
AN639	CON EDISON SERVICE B	W 19TH ST & 8TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	940, 0.178, ESE
AS640	CON EDISON - VAULT 3	42 10 AVE	NY MANIFEST	Lower	943, 0.179, WSW
AS641	CON EDISON	42 10TH AVE	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	943, 0.179, WSW
AS642	42-46 10TH AVENUE	42 10TH AVENUE	NY VCP	Lower	943, 0.179, WSW
AS643	CON EDISON	837 WASHINGTON ST	NY MANIFEST, NY COOLING TOWERS	Lower	944, 0.179, SW
AS644	CON EDISON SERVICE B	837 WASHINGTON ST	RCRA NonGen / NLR	Lower	944, 0.179, SW
AL645	CON EDISON	W 17TH ST & 8TH AVE	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	944, 0.179, SE
AG646	AMOCO STATION	213-10 JAMAICA AVENU	NY LTANKS	Lower	944, 0.179, North
AX647	CON EDISON	410 W 42ND ST & 9TH	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	946, 0.179, NNE
AT648	CON EDISON - SERVICE	WEST 16TH STREET AND	RCRA-LQG, NJ MANIFEST	Higher	949, 0.180, SE
AT649	CONSOLIDATED EDISON	W 16TH ST & 8TH AVE	NY MANIFEST	Higher	949, 0.180, SE
AL650	NYCT - PUMP ROOM #20	18TH ST & 8TH AVE	RCRA-VSQG, NY MANIFEST, NJ MANIFEST	Higher	950, 0.180, ESE
AP651	CONSOLIDATED EDISON	520 W 22ND ST	NY MANIFEST	Lower	959, 0.182, NNW
AP652	CON EDISON SERVICE B	518 W 22ND ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	959, 0.182, NNW
AG653	EXXON	215 10TH AVE & W 23R	NY Spills, NY MANIFEST	Lower	960, 0.182, North
AG654	EXXON DIV OF CFI #70	215 10TH AVE & W 23R	RCRA-VSQG, NY UST, FINDS, ECHO	Lower	960, 0.182, North
AU655	CON EDISON	FO 401 WEST 23RD ST	NY MANIFEST	Higher	963, 0.182, NE
AI656	85 EIGHT AVENUE OWNE	85 EIGHTH AVENUE	NY AST	Higher	967, 0.183, SSE
AX657	CON EDISON - SERVICE	N/W/C WEST 48TH ST.	RCRA-LQG, NY MANIFEST	Higher	968, 0.183, NNE
AP658	CHELSEA OPERATING, I	521 WEST 21ST STREET	NY UST	Lower	970, 0.184, NNW
AU659	CON EDISON	373 W 23RD ST	NJ MANIFEST	Higher	970, 0.184, NE
AU660	CON EDISON	373 W 23RD ST	NY MANIFEST	Higher	970, 0.184, NE
AU661	CON EDISON	373 W 23RD ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	970, 0.184, NE
AY662	529 WEST 20TH ST LLC	529 WEST 20TH STREET	NY AST	Lower	972, 0.184, NNW

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AX663	CON EDISON - VAULT 4	433 W 23RD ST	RCRA-LQG	Higher	975, 0.185, NNE
AX664	CON EDISON - VAULT 4	433 W 23RD ST	NY MANIFEST	Higher	975, 0.185, NNE
AS665	38-52, 38-56 10TH AV	38-52, 38-56 10TH AV	NY LTANKS	Lower	975, 0.185, SW
AX666	LONDON TERRACE GARDE	435 WEST 23RD STREET	NY AST	Higher	977, 0.185, NNE
AR667	CON EDISON	F/O 19 9TH AVE	NY MANIFEST	Higher	980, 0.186, SSW
AR668	CON EDISON SERVICE B	19 9TH AVE FRONT OF	RCRA NonGen / NLR, FINDS, ECHO	Higher	980, 0.186, SSW
AO669	GERMAN EV LUTHERAN C	315 WEST 22ND STREET	NY AST	Higher	981, 0.186, ENE
AX670	LONDON TERRACE GARDE	415-55 WEST 23RD STR	NY UST	Higher	981, 0.186, NNE
AO671	CON EDISON SERVICE B	352 W 23RD ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	983, 0.186, NE
AO672	CON EDISON SERVICE B	352 W 23RD ST	NJ MANIFEST	Higher	983, 0.186, NE
AZ673	ALLERTON HOTEL	302 WEST 22ND STREET	NY AST	Higher	983, 0.186, ENE
BA674	GULF SERVICE STA	500 W 23RD ST	NY UST	Lower	984, 0.186, North
BA675	CVS PHARMACY #10041	500 W 23RD ST	RCRA-VSQG, NY MANIFEST	Lower	984, 0.186, North
BA676	CVS # 10041	500 W 23RD ST	PA MANIFEST	Lower	984, 0.186, North
AS677	BELL ATLANTIC-NY	10 AVE & 13TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	986, 0.187, WSW
AY678	BAYVIEW CORRECTIONAL	550 W 20TH ST	RCRA-VSQG, NY SHWS, NY MANIFEST	Lower	987, 0.187, NW
AY679	BAYVIEW CORRECTIONAL	550 WEST 20TH ST	NY UST, NY AST, FINDS, ECHO	Lower	987, 0.187, NW
BB680	CONSOLIDATED EDISON	8TH AVE & W 15TH ST	NY MANIFEST	Higher	989, 0.187, SSE
BB681	CONSOLIDATED EDISON	15TH ST & 8TH AVE	NY MANIFEST	Higher	989, 0.187, SSE
BB682	15TH ST & 8TH AVE/BK	15TH ST / 8TH AVE	NY LTANKS	Higher	989, 0.187, SSE
BB683	CON EDISON	8TH AVE & W 15TH ST	RCRA NonGen / NLR, NJ MANIFEST	Higher	989, 0.187, SSE
684	INDUSTRIAL ELECTRONI	103-11 PRINCE ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	995, 0.188, NW
AO685	CON EDISON	363-61 W 23RD ST & 9	NY MANIFEST	Higher	995, 0.188, NE
AO686	CON EDISON	363-61 W 23RD ST & 9	NY MANIFEST	Higher	995, 0.188, NE
AT687	CHELSEA 1 HOUR PHOTO	128 8TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	996, 0.189, SE
AT688	CVS PHARMACY #2919	126 8TH AVE	RCRA-VSQG, NY MANIFEST	Higher	996, 0.189, SE
AT689	RAYMAX ASSOC	114 EIGHTH AVENUE	NY AST	Higher	997, 0.189, SE
AT690	RAYMAX ASSOCIATES	106 EIGHTH AVENUE	NY AST	Higher	998, 0.189, SE
AL691	ST FRANCIS RESIDENCE	148 8TH AVE	NY AST	Higher	1001, 0.190, SE
BC692	GANSEVOORT COOPERATI	652 HUDSON STREET	NY AST	Higher	1006, 0.191, South
BC693	APARTMENT BUILDING	652 HUDSON STREET	NY LTANKS, NY Spills	Higher	1006, 0.191, South
BC694	GANSEVOORT CORPERATI	652 HUDSON ST	RCRA-VSQG, NY MANIFEST, NJ MANIFEST	Higher	1006, 0.191, South
AN695	CELIMAR CLEANERS	188 8TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1008, 0.191, East
AQ696	CON EDISON SERVICE B	312 W 14TH ST & 8TH	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	1012, 0.192, SSE
AT697	CON EDISON	124 8TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1013, 0.192, SE
BA698	CON EDISON SERVICE B	208 10TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1014, 0.192, North
AN699	170 8TH AVE.	170 8TH AVE.	NY AST	Higher	1015, 0.192, ESE
BB700	CVS PHARMACY #1618	81 8TH AVE	RCRA-VSQG, NY MANIFEST	Higher	1015, 0.192, SSE
BB701	CENTRAL RUG & CARPET	81 8TH AVENUE	NY UST	Higher	1015, 0.192, SSE

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BB702	CVS # 01618	81 8TH AVENUE	PA MANIFEST	Higher	1015, 0.192, SSE
AW703	CON EDISON MANHOLE 3	W 21ST ST & 8TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1015, 0.192, East
AL704	SUN JINN CLEANERS IN	156 EIGHTH AVE	RCRA NonGen / NLR, NY DRYCLEANERS, NY MANIFEST	Higher	1015, 0.192, ESE
AL705	CON EDISON	154-156 E 8TH AVE &	NY MANIFEST	Higher	1016, 0.192, ESE
AW706	CON EDISON	8TH AVE & W 21 ST	NY MANIFEST	Higher	1017, 0.193, East
AK707	CE - W. 18TH ST. GAS	WEST 16TH - WEST 20T	NY VCP	Lower	1018, 0.193, NW
AO708	CON EDISON - MANHOLE	326 W 23RD ST	NY MANIFEST	Higher	1029, 0.195, ENE
AO709	CON EDISON - MANHOLE	326 W 23RD ST	RCRA-LQG	Higher	1029, 0.195, ENE
BA710	CON EDISON	W 23RD ST & 10 TH AV	NY MANIFEST	Lower	1029, 0.195, North
BA711	CON EDISON SERVICE B	W 10TH AVE & 23RD ST	NJ MANIFEST	Lower	1029, 0.195, North
BA712	CON EDISON - MANHOLE	W 5 AVE ESW 15 ST	RCRA-LQG	Lower	1029, 0.195, North
AR713	CON EDISON - GAS MAI	17 9TH AVE	RCRA-LQG, FINDS, ECHO	Higher	1031, 0.195, SSW
AR714	CON EDISON - GAS MAI	17 9TH AVE	NJ MANIFEST	Higher	1031, 0.195, SSW
AR715	CON EDISON	17 9TH AVE	NY MANIFEST	Higher	1031, 0.195, SSW
AY716	CON EDISON - 19TH ST	11TH AVE BETWEEN W 1	EDR MGP	Lower	1037, 0.196, NW
AR717	CON EDISON	8 9TH AVE	NY MANIFEST	Higher	1040, 0.197, SSW
AR718	CON EDISON SERVICE B	8 9TH AVE	RCRA NonGen / NLR	Higher	1040, 0.197, SSW
BA719	CON EDISON SERVICE B	212 10TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1042, 0.197, North
BC720	SPECTRANOME PLATING	330 W 13TH ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1046, 0.198, South
AO721	CON EDISON	322 W 23RD ST	NY MANIFEST	Higher	1051, 0.199, ENE
AW722	SINO REALTY REALTY	204 8TH AVENUE	NY LTANKS, NY Spills	Higher	1055, 0.200, East
BD723	CON EDISON	258 W 20TH ST	NJ MANIFEST	Higher	1063, 0.201, East
BD724	CON EDISON	258 W 20TH ST	RCRA NonGen / NLR	Higher	1063, 0.201, East
BD725	CON EDISON	258 W 20TH ST	NY MANIFEST	Higher	1063, 0.201, East
AV726	CON EDISON SERVICE B	13 LITTLE WEST 12TH	RCRA NonGen / NLR, NY MANIFEST	Lower	1063, 0.201, SSW
AV727	CON EDISON - 12TH ST	13 LITTLE W 12TH ST	PA MANIFEST	Lower	1063, 0.201, SSW
AQ728	305 W 13 ST	305 WEST 13TH STREET	NY AST	Higher	1068, 0.202, South
BD729	CON EDISON - MANHOLE	256 W 20TH ST	NY MANIFEST	Higher	1069, 0.202, East
AY730	BERMUDA MOTOR CAR RE	537 WEST 20TH STREET	NY UST	Lower	1071, 0.203, NW
BB731	SPILL NUMBER 9912064	96 8TH AVE	NY LTANKS	Higher	1076, 0.204, SSE
BE732	CON EDISON SERVICE B	13TH AVE & GANSEVOOR	RCRA NonGen / NLR, NY MANIFEST	Higher	1080, 0.205, South
AR733	CON EDISON	7 WEST LITTLE W 12TH	NY MANIFEST	Higher	1080, 0.205, SSW
AR734	CON EDISON SERVICE B	7 WEST LITTLE W 12TH	RCRA NonGen / NLR	Higher	1080, 0.205, SSW
AV735	CON EDISON SERVICE B	41 LITTLE WEST 12TH	RCRA NonGen / NLR, NY MANIFEST	Lower	1080, 0.205, SW
AT736	CON EDISON	263 W 16 ST	NY MANIFEST	Higher	1081, 0.205, SE
AW737	CON EDISON	214-212 W 15 ST & 8T	NY MANIFEST	Higher	1081, 0.205, East
AZ738	301 WEST 22ND ST	301 WEST 22ND ST	NY AST	Higher	1085, 0.205, ENE
AT739	THE GRAND CHELSEA CO	270 WEST 17TH STREET	NY AST	Higher	1089, 0.206, SE
BB740	MR CLEAN	92 8TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1091, 0.207, SSE

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BB741	ULTRA CLEANERS INC -	92 8TH AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	1091, 0.207, SSE
AS742	CON EDISON - SERVICE	51 LITTLE W12TH ST.	RCRA-LQG, NY MANIFEST	Lower	1091, 0.207, SW
AS743	CON EDISON - SERVICE	51 LITTLE W12TH ST.	NJ MANIFEST	Lower	1091, 0.207, SW
AY744	540 WEST 21ST STREET	540 WEST 21ST STREET	NY VCP	Lower	1095, 0.207, NNW
AY745	540 W 21ST ST HOLDIN	540-558 W 21ST ST	RCRA NonGen / NLR	Lower	1095, 0.207, NNW
AY746	540 W 21ST ST HOLDIN	540-558 W 21ST ST	NY MANIFEST	Lower	1095, 0.207, NNW
BF747	CON EDISON SERVICE B	273 W 17TH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1097, 0.208, SE
BE748	M DISTRICT 2/4/5 GAR	2 GANSEVOORT STREET	NY AST	Higher	1098, 0.208, South
BE749	M DISTRICT 2/4/5 GAR	2 GANSEVOORT STREET	NY UST	Higher	1098, 0.208, South
BG750	CON EDISON	324-22 W 23RD ST & 9	NY MANIFEST	Higher	1100, 0.208, ENE
BG751	CON EDISON	FO 324 W 23RD ST	NY MANIFEST	Higher	1100, 0.208, ENE
BH752	NYCTA - 14TH ST STAT	14TH ST & 8TH AVE	RCRA-VSQG, NY MANIFEST, NJ MANIFEST	Higher	1107, 0.210, SSE
BH753	CON EDISON	8TH AVE & W 14TH ST	NY MANIFEST	Higher	1107, 0.210, SSE
BH754	CON EDISON	8TH AVE & 14TH ST	NY MANIFEST	Higher	1107, 0.210, SSE
BH755	CON EDISON	8TH AVE & W 14TH ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1107, 0.210, SSE
BH756	CON EDISON	8TH AVE & W 14TH ST	NJ MANIFEST	Higher	1107, 0.210, SSE
BH757	CON EDISON	8TH AVE & 14TH ST	NJ MANIFEST	Higher	1107, 0.210, SSE
BH758	CON EDISON	8TH AVE & 14TH ST	RCRA NonGen / NLR	Higher	1107, 0.210, SSE
BH759	CON EDISON	14 ST & 8TH AVE	NY MANIFEST	Higher	1107, 0.210, SSE
AQ760	CON EDISON - TRANSFO	73 8TH AVE	RCRA-LQG	Higher	1109, 0.210, SSE
AQ761	CON EDISON - TRANSFO	73 8TH AVE	NJ MANIFEST	Higher	1109, 0.210, SSE
AQ762	CON EDISON	73 8TH AVE	NY MANIFEST	Higher	1109, 0.210, SSE
AY763	535 EAST 21ST STREET	535 EAST 21ST STREET	NY LTANKS	Lower	1111, 0.210, NNW
AZ764	LUIS PHILLIP CLEANER	320 W 23RD ST	RCRA NonGen / NLR, ICIS, US AIRS, FINDS, ECHO	Higher	1113, 0.211, ENE
AZ765	CON EDISON - SERVICE	320 W 23 ST	NJ MANIFEST	Higher	1113, 0.211, ENE
AZ766	CON EDISON	320 W 23 ST	NY MANIFEST	Higher	1113, 0.211, ENE
AZ767	CON EDISON - SERVICE	320 W 23 ST	RCRA-LQG	Higher	1113, 0.211, ENE
AZ768	LUIS PHILLIP CLEANER	320 W 23RD ST	NY MANIFEST	Higher	1113, 0.211, ENE
AZ769	ROYAL CHICE FRENCH/L	320 WEST 23RD STREET	NY DRYCLEANERS	Higher	1113, 0.211, ENE
BB770	CON EDISON	262 W 15TH ST	NY MANIFEST	Higher	1113, 0.211, SSE
BB771	CON EDISON	78 8TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1114, 0.211, SSE
BB772	80 8TH AVENUE	80 EIGHTH AVENUE	NY UST	Higher	1119, 0.212, SSE
BB773	80 8TH AVENUE	80 EIGHTH AVENUE	NY AST	Higher	1119, 0.212, SSE
BB774	NATIONAL ENVIRONMENT	80 8TH AVE ROOM 303	RCRA NonGen / NLR, FINDS, ECHO	Higher	1119, 0.212, SSE
BB775	APARTMENT BUILDING	80 8TH AVENUE	NY LTANKS, NY Spills	Higher	1119, 0.212, SSE
AZ776	LOUIS PHILIPPE CONDO	312 WEST 23RD STREET	NY UST	Higher	1122, 0.213, ENE
AZ777	APT. BUILDING	312 WEST 23RD ST	NY LTANKS	Higher	1122, 0.213, ENE
AR778	CON EDISON	2 9TH AVE	NY MANIFEST	Higher	1123, 0.213, SSW
AR779	CON EDISON	2 9TH AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	1123, 0.213, SSW

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AW780	224 EIGHTH AVE CORP	224 8TH AVENUE	NY AST	Higher	1124, 0.213, East
AT781	250 WEST 16TH STREET	250 WEST 16TH STREET	NY AST	Higher	1124, 0.213, SE
AZ782	CON EDISON	237-235 W 15 ST & 8T	NY MANIFEST	Higher	1125, 0.213, ENE
BA783	CONSOLIDATED EDISON	520 W 23 ST MH4171	NY MANIFEST	Lower	1127, 0.213, North
BA784	MARAJS	520 WEST 23RD STREET	NY AST	Lower	1127, 0.213, North
AR785	CON EDISON	9TH AVE & LITTLE W 1	NY MANIFEST	Higher	1130, 0.214, SSW
AR786	CON EDISON SERVICE B	9TH AVE & LITTLE W 1	RCRA NonGen / NLR, FINDS	Higher	1130, 0.214, SSW
BF787	CON EDISON	FO 252 W 18 ST	NY MANIFEST	Higher	1132, 0.214, ESE
BB788	CON EDISON	259-257 W 15 ST & 8	NY MANIFEST	Higher	1133, 0.215, SE
BB789	CON EDISON	259 W 15TH ST	NY MANIFEST	Higher	1133, 0.215, SE
AZ790	CON EDISON SERVICE B	253 8TH AVE & 22ND S	RCRA NonGen / NLR, FINDS	Higher	1137, 0.215, ENE
AZ791	CON EDISON - MANHOLE	8TH AVE & 22ND ST IN	RCRA-LQG	Higher	1137, 0.215, ENE
AZ792	CON EDISON SERVICE B	257 8TH AVE & 22ND S	RCRA NonGen / NLR, FINDS	Higher	1137, 0.215, ENE
AZ793	CON EDISON	22ND ST & 8TH AVE SW	RCRA NonGen / NLR, FINDS, ECHO	Higher	1137, 0.215, ENE
AZ794	CON EDISON	22ND ST & 8TH AVE	NY MANIFEST	Higher	1137, 0.215, ENE
AZ795	CON EDISON	8TH AVE & 22ND ST	NY MANIFEST	Higher	1137, 0.215, ENE
AZ796	CON EDISON	22ND ST & 8TH AVE	RCRA NonGen / NLR	Higher	1137, 0.215, ENE
AZ797	CON EDISON	22ND ST & 8TH AVE	NJ MANIFEST	Higher	1137, 0.215, ENE
AZ798	CON EDISON SERVICE B	8TH AVE & 22ND ST	RCRA NonGen / NLR	Higher	1137, 0.215, ENE
BF799	NYC DEPT OF EDUCATIO	250 W 18TH ST	RCRA-SQG	Higher	1138, 0.216, ESE
BF800	NYC DEPT OF EDUCATIO	250 W 18TH ST	NY AST, NY MANIFEST	Higher	1138, 0.216, ESE
BI801	CON EDISON	FO 272 W 19 ST	NY MANIFEST	Higher	1143, 0.216, ESE
AW802	ENS/21 LLC	264/268 WEST 21ST ST	NY AST	Higher	1145, 0.217, East
BD803	EIGHTH-19TH COMPANY	259-265 WEST 19TH ST	NY AST	Higher	1148, 0.217, ESE
BB804	ROSAR REALTY CORP.	258 WEST 15TH STREET	NY UST	Higher	1155, 0.219, SSE
BB805	258 WEST 15TH ST/MAN	258 WEST 15TH STREET	NY LTANKS	Higher	1155, 0.219, SSE
BA806	CON EDISON SERVICE B	505 W 23RD ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1157, 0.219, North
AT807	253 W 16 ST	253 WEST 16TH STREET	NY UST	Higher	1157, 0.219, SE
BJ808	FORMER OLYMPIA GARAG	9-19 9TH AVENUE	NY UST	Higher	1160, 0.220, SSW
BF809	257 W 17TH ST	257 W 17TH ST	NY AST	Higher	1161, 0.220, SE
BA810	CON EDISON SERVICE B	517 W 23RD ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1161, 0.220, North
BH811	CON EDISON	259 W 14TH ST	NY MANIFEST	Higher	1164, 0.220, SSE
AY812	SYLVOR COMPANY	120-126 11TH AVENUE	NY AST	Lower	1166, 0.221, NW
AY813	HERTZ PENSKE TRUCK L	542 W 21ST ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	1166, 0.221, NNW
BK814	LONDON TERRACE TOWER	420 WEST 24 STREET	NY UST, NY AST	Higher	1168, 0.221, NNE
BK815	LONDON TERRACE/CIM C	410 W. 24TH STREET	NY DRYCLEANERS	Higher	1169, 0.221, NNE
BK816	LONDON TERRACE CLEAN	410 W 24TH ST	RCRA-VSQG, ICIS, US AIRS, NY MANIFEST	Higher	1169, 0.221, NNE
BK817	LONDON TERRACE TOWER	410 WEST 24 STREET	NY AST	Higher	1169, 0.221, NNE
BK818	LONDON TERRACE TOWER	410 WEST 24 STREET	NY UST	Higher	1169, 0.221, NNE

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BL819	CON EDISON	58 LITTLE W 12TH ST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1170, 0.222, SW
AU820	CON EDISON - VAULT 3	400 W 24 ST	RCRA-LQG, NY MANIFEST	Higher	1170, 0.222, NE
BD821	245-259 W 20 ST	251 W 20 ST	NY AST	Higher	1171, 0.222, East
BB822	CHELSEA DEVELOPMENT	255 WEST 15TH STREET	NY UST	Higher	1172, 0.222, SE
BE823	JOHN'S TAILOR & CLEA	6903 8TH AVE	RCRA-VSQG, ICIS, US AIRS, FINDS, ECHO, NY MANIFEST	Higher	1172, 0.222, SSE
AW824	261 WEST 21ST STREET	261 WEST 21ST STREET	NY AST	Higher	1176, 0.223, East
AW825	261 WEST 21ST ST	261 WEST 21ST STREET	NY UST	Higher	1176, 0.223, East
AV826	CON EDISON	38 LITTLE W 12 ST	NY MANIFEST	Lower	1177, 0.223, SW
AV827	CON EDISON SERVICE B	38 LITTLE WEST 12TH	RCRA NonGen / NLR	Lower	1177, 0.223, SW
BL828	CON EDISON - SERVICE	44 LITTLE W12TH ST.	RCRA-LQG, NY MANIFEST, NJ MANIFEST	Lower	1177, 0.223, SW
BB829	256 W 15TH ST.	256 W 15 ST	NY UST	Higher	1179, 0.223, SSE
BG830	BROADMOOR APTS	315 WEST 23RD STREET	NY UST	Higher	1179, 0.223, ENE
AZ831	300 WEST 23RD STREET	300 WEST 23RD STREET	NY AST	Higher	1179, 0.223, ENE
BF832	CON EDISON	266 W 17 & 8TH AVE	NY MANIFEST	Higher	1182, 0.224, SE
AX833	LONDON TERRACE TOWER	470 W 24TH ST	NY UST, NY AST, ICIS, US AIRS	Higher	1188, 0.225, NNE
BF834	246 WEST 18 ST	246 WEST 18 STREET	NY AST	Higher	1189, 0.225, ESE
BK835	CON EDISON SERVICE B	235 9TH AVE & 24TH S	RCRA NonGen / NLR, FINDS	Higher	1190, 0.225, NE
BK836	CON EDISON SERVICE B	W 24TH ST & 9TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1191, 0.226, NE
BM837	CON EDISON - GAS MAI	E HOUSTON AT COLUMBI	RCRA-LQG	Lower	1194, 0.226, SSW
BM838	CON EDISON	E HOUSTON AT COLUMBI	NY MANIFEST	Lower	1194, 0.226, SSW
BJ839	CON EDISON SERVICE B	8 LITTLE WEST 12TH S	RCRA NonGen / NLR, NY MANIFEST	Lower	1195, 0.226, SSW
BF840	CON EDISON	250 W 17TH ST	NJ MANIFEST	Higher	1198, 0.227, SE
BF841	CON EDISON	250 W 17TH ST	NY MANIFEST	Higher	1198, 0.227, SE
BF842	CON EDISON	250 W 17TH ST	RCRA NonGen / NLR	Higher	1198, 0.227, SE
BL843	CON EDISON SERVICE B	LITTLE WEST 12TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1199, 0.227, SW
BL844	CON EDISON SERVICE B	10TH AVE & W 12TH ST	RCRA NonGen / NLR	Lower	1199, 0.227, SW
BL845	CON EDISON	10TH AVE & W 12TH ST	NY MANIFEST	Lower	1199, 0.227, SW
BH846	CON EDISON	74 8 AVE	NY MANIFEST	Higher	1199, 0.227, SSE
BA847	CON EDISON SERVICE B	511 W 23RD ST OPPOSI	RCRA NonGen / NLR, NY MANIFEST	Lower	1202, 0.228, North
BH848	CON EDISON - TRANSFO	72 8TH AVE	NY MANIFEST	Higher	1203, 0.228, SSE
BG849	CON EDISON	323-11 W 23RD ST & 9	NY MANIFEST	Higher	1209, 0.229, ENE
BI850	APARTMENT HOUSE	264 W. 19TH ST	NY LTANKS, NY Spills	Higher	1211, 0.229, ESE
BI851	UNITED CHELSEA LLC	264 WEST 19TH STREET	NY AST	Higher	1211, 0.229, ESE
BE852	320 WEST 13TH ST	320 WEST 13TH STREET	NY AST	Higher	1212, 0.230, South
BE853	MICR ENCODING INC	320 W 13TH ST BASEME	RCRA NonGen / NLR, FINDS, ECHO	Higher	1212, 0.230, South
BN854	DIA ART FOUNDATION	535 W 22ND ST	RCRA-SQG, NY MANIFEST	Lower	1213, 0.230, NNW
BJ855	CON EDISON - SERVICE	53 GANSEVOORT ST	RCRA-LQG	Lower	1214, 0.230, SSW
BJ856	CON EDISON	53 GANSEVOORT ST FRO	NY MANIFEST	Lower	1214, 0.230, SSW
BO857	244 WEST 16TH STREET	244 WEST 16TH STREET	NY AST	Higher	1219, 0.231, SE

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BE858	CON EDISON	347 W 4TH ST	NY MANIFEST	Higher	1221, 0.231, South
BB859	APARTMENT BUILDING	250 W. 15TH ST	NY LTANKS	Higher	1222, 0.231, SSE
BB860	250 W. 15TH ST OWNER	250 WEST 15TH STREET	NY AST	Higher	1222, 0.231, SSE
BF861	CON EDISON	248 W 17TH ST	NY AST, NY MANIFEST	Higher	1223, 0.232, SE
BL862	570-578 WEST 193RD S	570-578 WEST 193TH S	NY AST	Lower	1231, 0.233, SW
BP863	547-551 WEST 21ST ST	547-551 WEST 21ST ST	NY UST	Lower	1231, 0.233, NNW
BP864	547-551 WEST 21ST ST	547-551 W 21ST ST	NY MANIFEST	Lower	1231, 0.233, NNW
BQ865	CON EDISON	266-264 W 22ND ST &	NY MANIFEST	Higher	1232, 0.233, East
BQ866	CON EDISON	266-264 W 22ND ST &	NJ MANIFEST	Higher	1232, 0.233, East
BQ867	CON EDISON	266-264 W 22ND ST &	RCRA NonGen / NLR, FINDS, ECHO	Higher	1232, 0.233, East
BP868	551 WEST 21ST STREET	551 WEST 21ST STREET	NY VCP	Lower	1232, 0.233, NNW
BP869	547-551 WEST 21ST ST	547-551 W 21ST ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	1232, 0.233, NNW
BA870	ARTISTS' CONDOMINIUM	521 WEST 23RD STREET	NY UST	Lower	1233, 0.234, North
BA871	EMSIG MFG CORP	521 W 23RD ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	1233, 0.234, North
BA872	COMMERICAL BUILDLING	521 WEST 23RD STREET	NY LTANKS	Lower	1233, 0.234, North
BH873	GETTY	63 8TH AVENUE	NY LTANKS, NY Spills	Higher	1236, 0.234, SSE
BH874	GETTY REALTY CORP 58	63 8TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1236, 0.234, SSE
BH875	GETTY 58205	63 EIGHTH AVENUE	NY UST	Higher	1236, 0.234, SSE
BO876	CON ED	242 W 16 ST	NY MANIFEST	Higher	1237, 0.234, SE
BO877	CON EDISON - SERVICE	242 W 16 ST	NJ MANIFEST	Higher	1237, 0.234, SE
BO878	CON EDISON	242-240 W 16TH ST &	NY MANIFEST	Higher	1237, 0.234, SE
BO879	CON EDISON - SERVICE	242 W 16 ST	RCRA-LQG	Higher	1237, 0.234, SE
BK880	GOLDEN EQUITIES CORP	401 WEST 24TH STREET	NY AST	Higher	1238, 0.234, NE
BP881	PENSKE TRUCK LEASING	550 W 21ST ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1240, 0.235, NW
BQ882	264 WEST 22ND STREET	264 WEST 22ND STREET	NY AST	Higher	1243, 0.235, East
BE883	345 W. 4TH-306 W. 13	345 W 4 STREET	NY AST	Higher	1248, 0.236, South
BD884	CHELSEA 19 CONDOMINI	251 WEST 19TH STREET	NY AST	Higher	1251, 0.237, ESE
BD885	SPILL NUMBER 0010929	251 W. 19TH ST	NY LTANKS	Higher	1251, 0.237, ESE
BR886	CON EDISON SERVICE B	445 W 24TH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1251, 0.237, NNE
BR887	CON EDISON SERVICE B	445 W 24TH ST	NJ MANIFEST	Higher	1251, 0.237, NNE
BK888	SILVERBOW REALTY CO	415 WEST 24TH ST	NY AST	Higher	1252, 0.237, NNE
BK889	CON EDISON	411 W 24TH ST	NY MANIFEST	Higher	1253, 0.237, NNE
BS890	CON EDISON SERVICE B	525 W 23RD ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1256, 0.238, North
BQ891	NISHI CLEANERS	244 8TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1258, 0.238, ENE
BQ892	PETERS DRY CLEANERS	244 8TH AVE	RCRA NonGen / NLR, ICIS, US AIRS, FINDS	Higher	1258, 0.238, ENE
BK893	OXFORD DRY CLEANERS	232 9TH AVENUE	RCRA-SQG, FINDS, ECHO, NY DRYCLEANERS, NY MANIFEST	Higher	1259, 0.238, NE
BH894	BONJOUR CLEANERS	252 W 14TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1260, 0.239, SSE
BT895	PIER 57	25 11TH AVE	NY MANIFEST	Lower	1261, 0.239, West
BT896	HUDSON DEPOT	11TH AVE & 15TH ST	NY AST, NY Spills	Lower	1261, 0.239, West

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BT897	PIER 57 LLC	25 11TH AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	1261, 0.239, West
BT898	PIER 57, HUDSON RIVE	25 ELEVENTH AVENUE	NY UST	Lower	1261, 0.239, West
BQ899	CON EDISON	F/O 251 W 21ST ST	NY MANIFEST	Higher	1264, 0.239, East
BQ900	262 WEST 22ND ST/MAN	262 WEST 22ND ST	NY AST, NY Spills	Higher	1265, 0.240, East
BQ901	CON EDISON	262 W 22ND ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1265, 0.240, East
BQ902	CON EDISON	262 W 22ND ST	NY MANIFEST	Higher	1265, 0.240, East
BQ903	CON EDISON	262 W 22ND ST	NJ MANIFEST	Higher	1265, 0.240, East
BU904	571-573 WEST 159 STR	571-573 WEST 159 STR	NY AST	Lower	1266, 0.240, SW
BO905	APT HOUSE	240 WEST 16TH ST	NY LTANKS, NY Spills	Higher	1269, 0.240, SE
BO906	SPILL NUMBER 9811171	240 WEST 16TH ST	NY LTANKS	Higher	1269, 0.240, SE
BV907	CON EDISON SERVICE B	641 HUDSON ST FRONT	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1271, 0.241, SSW
BV908	641 HUDSON STREET	641 HUDSON STREET	NY AST	Higher	1271, 0.241, SSW
BD909	238 W 20 STREET	238 WEST 20TH STREET	NY AST	Higher	1275, 0.241, ESE
BH910	251 WEST 14 ST	251 WEST 14TH STREET	NY AST	Higher	1278, 0.242, SSE
BH911	CON EDISON	250 W 14 ST	NY MANIFEST	Higher	1279, 0.242, SSE
BW912	CON EDISON - MANHOLE	W 24TH ST & 10TH AVE	NY MANIFEST	Lower	1280, 0.242, North
BW913	CON EDISON SERVICE B	W 10TH AVE & 24TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1280, 0.242, North
BW914	CONSOLIDATED EDISON	24 ST & 10 AVE MH431	NY MANIFEST	Lower	1281, 0.243, North
BQ915	CON EDISON	F/O 260 W 22 ST	NY MANIFEST	Higher	1287, 0.244, East
BH916	CON EDISON	122 GREENWICH AVE	NY MANIFEST	Higher	1288, 0.244, SSE
BO917	236 E. 16 ST REALTY	236 EAST 16TH STREET	NY LTANKS, NY UST, NY Spills	Higher	1292, 0.245, SE
BO918	236 WEST 16 STREET	236 WEST 16TH STREET	NY AST	Higher	1292, 0.245, SE
BI919	250 W 19TH STREET	250 WEST 19TH STREET	NY AST	Higher	1295, 0.245, ESE
BM920	CON EDISON SERVICE B	67 GANSEVOORT ST FRO	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1297, 0.246, SSW
BQ921	EARTH CLEANER	250 8TH AVE	RCRA NonGen / NLR, ICIS, US AIRS, NY DRYCLEANERS	Higher	1301, 0.246, ENE
BN922	DIA ART FOUNDATION	548 W 22ND ST	NY UST, NY AST	Lower	1304, 0.247, NNW
BE923	CON EDISON	21-25 HORATIO ST & H	NY MANIFEST	Higher	1305, 0.247, South
BF924	243 WEST 17TH STREET	243 WEST 17TH STREET	NY AST	Higher	1306, 0.247, SE
BE925	CON EDISON	17 HORATIO ST	NY MANIFEST	Higher	1308, 0.248, South
BH926	CON EDISON MANHOLE 2	246 W 14TH ST & 8 AV	RCRA NonGen / NLR, NJ MANIFEST	Higher	1308, 0.248, SSE
BX927	CON EDISON	W 23RD ST & 8TH AVE	NJ MANIFEST	Higher	1310, 0.248, ENE
BX928	CON EDISON	W 23RD ST & 8TH AVE	NY MANIFEST	Higher	1310, 0.248, ENE
BX929	MTA NYCT - 23RD STRE	23RD ST & 8TH AVE	RCRA-SQG	Higher	1310, 0.248, ENE
BX930	NYCT - MH 1027	23RD ST & 8TH AVE	RCRA-LQG	Higher	1310, 0.248, ENE
BX931	CON EDISON MANHOLE:	8TH AVE & 23RD ST	RCRA NonGen / NLR	Higher	1310, 0.248, ENE
BX932	CON EDISON	8TH AVE & 23RD ST	NY MANIFEST	Higher	1310, 0.248, ENE
BX933	MTA NYCT - 23RD STRE	23RD ST & 8TH AVE	NY MANIFEST	Higher	1310, 0.248, ENE
BX934	CON EDISON	W 23RD ST & 8TH AVE	RCRA NonGen / NLR	Higher	1310, 0.248, ENE
BX935	MTA NYCT - 23RD STRE	23RD ST & 8TH AVE	NJ MANIFEST	Higher	1310, 0.248, ENE

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BI936	237 REALTY NY LLC	237 WEST 18TH STREET	NY AST	Higher	1311, 0.248, ESE
BX937	CON EDISON SERVICE B	220-218 W 23RD ST &	RCRA NonGen / NLR, FINDS	Higher	1313, 0.249, ENE
BX938	CON EDISON SERVICE B	206 W 23RD ST & 8TH	RCRA NonGen / NLR, FINDS	Higher	1313, 0.249, ENE
BX939	CON EDISON SERVICE B	209-207 W 23RD ST &	RCRA NonGen / NLR, FINDS	Higher	1313, 0.249, ENE
BS940	MARY BOONE GALLERY	537-541 W. 24TH ST	NY LTANKS	Lower	1319, 0.250, North
BS941	508 WEST 24TH STREET	508 WEST 24TH STREET	NY VCP	Lower	1323, 0.251, North
BU942	NYC DEPT SANITATION	2 BLOOMFIELD ST	NY LTANKS, NY Spills	Lower	1349, 0.255, SW
BS943	514 WEST 24TH STREET	514 WEST 24TH STREET	NY VCP	Lower	1372, 0.260, North
BW944	FORMER GETTY SERVICE	239 10TH AVENUE	NY LTANKS, NY BROWNFIELDS, NY Spills	Lower	1373, 0.260, North
BW945	239 10TH AVE/MANH/GE	239 10TH AVENUE	NY LTANKS	Lower	1373, 0.260, North
BW946	239 10TH AVENUE	239 10TH AVENUE	NY VCP	Lower	1373, 0.260, North
BS947	EDISON PARKING GARAG	527 WEST 23RD ST	NY LTANKS	Lower	1394, 0.264, North
BS948	MENDON LEASING	527 WEST 23RD STREET	NY LTANKS, NY Spills	Lower	1394, 0.264, North
BV949	53 HORACIO STREET	53 HORACIO STREET	NY LTANKS	Higher	1395, 0.264, SSW
950	ELK INVESTOR - COMME	400 WEST 25TH ST	NY LTANKS, NY AST	Higher	1396, 0.264, NE
BY951	APARTMENT COMPLEX	238 WEST 14TH STREET	NY LTANKS	Higher	1409, 0.267, SSE
BN952	555 WEST 22ND STREET	555 WEST 22ND STREET	NY BROWNFIELDS	Lower	1411, 0.267, NNW
BW953	507 WEST 24TH STREET	507 WEST 24TH STREET	NY VCP	Lower	1425, 0.270, North
BS954	VACANT LOT	511 WEST 24TH STREET	NY LTANKS	Lower	1461, 0.277, North
BZ955	CON EDISON	2 HORATIO ST	NY LTANKS, NY MANIFEST	Higher	1471, 0.279, SSE
BZ956	2 HORATIO ST	2 HORATIO ST	NY LTANKS	Higher	1471, 0.279, SSE
CA957	555 WEST 23RD ST	555 WEST 23RD ST	NY LTANKS	Lower	1472, 0.279, NNW
BR958	CHELSEA HOUSES -NYCH	431 WEST 25TH ST	NY LTANKS, NY Spills	Higher	1475, 0.279, NNE
BY959	APARTMENT BUILDING	241 WEST 13TH STREET	NY LTANKS	Higher	1497, 0.284, SSE
CA960	UHAUL INC	562 WEST 23RD ST	NY LTANKS, NY Spills	Lower	1512, 0.286, NNW
BW961	500 WEST 25TH STREET	500 WEST 25TH STREET	NY VCP	Lower	1514, 0.287, North
BY962	229 WEST 14TH STREET	229 WEST 14TH STREET	NY LTANKS	Higher	1519, 0.288, SSE
CB963	168-11 12TH AVENUE	168-11 12TH AVENUE	NY LTANKS	Lower	1525, 0.289, NNW
CC964	COMMERCIAL TTF	61 JANE AVE	NY LTANKS, NY Spills	Higher	1561, 0.296, South
965	APARTMENT	214 WEST 20TH STREET	NY LTANKS	Higher	1576, 0.298, ESE
CD966	APRT	213 WEST 18TH STREET	NY LTANKS	Higher	1598, 0.303, ESE
CE967	APT BLDG	255 WEST 23RD ST	NY LTANKS, NY Spills	Higher	1600, 0.303, ENE
CE968	255 W. 23RD ST	255 W. 23RD ST	NY LTANKS	Higher	1600, 0.303, ENE
CF969	CLOSED-LACKOF RECENT	315 W. 25TH ST	NY LTANKS	Higher	1607, 0.304, NE
CF970	MUTUAL REDEVELOPMENT	315 WEST 25TH STREET	NY LTANKS, NY AST	Higher	1607, 0.304, NE
CD971	VERIZON	210 W. 18TH ST	NY LTANKS	Higher	1636, 0.310, ESE
CA972	186-188 11TH AVENUE	186 11TH AVENUE	NY VCP	Lower	1639, 0.310, NNW
CG973	RESIDENCE	92 HORATIO ST	NY LTANKS	Lower	1664, 0.315, SSW
BZ974	APT HOUSE	16 JANE STREET	NY LTANKS	Higher	1676, 0.317, South

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
CH975	APT BLDG TTF	15 ABINGDON SQUARE	NY LTANKS	Higher	1685, 0.319, South
CB976	23RD ST & EAST RIVER	600 E.23RD ST	NY LTANKS	Lower	1701, 0.322, NNW
CB977	GULF GAS STATION	600 E.23RD ST, E. RI	NY LTANKS	Lower	1701, 0.322, NNW
CC978	APARTMENT BLDG	299 WEST 12TH ST	NY LTANKS	Higher	1711, 0.324, South
979	NYCDOS GANESVOORT MT	GANESVOORT ST & WEST	NY SWF/LF	Lower	1718, 0.325, SW
CG980	85-89 JANE STREET	89 JANE STREET	NY VCP	Lower	1726, 0.327, SSW
CD981	CLOSED-LACKOF RECENT	200 WEST 18TH STREET	NY LTANKS	Higher	1739, 0.329, ESE
CC982	317 WEST 12TH ST	317 WEST 12TH ST	NY LTANKS	Higher	1742, 0.330, SSW
983	DEL. SPILL /W.28ST.&	W. 26TH ST & 10TH AV	NY LTANKS	Higher	1775, 0.336, North
CI984	201 WEST 16TH ST COR	201 WEST 16TH ST	NY LTANKS	Higher	1794, 0.340, SE
985	BUSINESS AT LOCATION	205 WEST 14TH ST	NY LTANKS, NY Spills	Higher	1805, 0.342, SE
CJ986	SPILL NUMBER 0104073	304 8TH AV	NY LTANKS, NY Spills	Higher	1841, 0.349, ENE
CK987	SPILL NUMBER 0201897	543 - 545 WEST 25TH	NY LTANKS	Lower	1849, 0.350, North
CH988	GOODSTEIN MNGMT	302 W 12TH ST	NY LTANKS	Higher	1852, 0.351, South
CL989	PUBLIC SCHOOL #33	281 9TH AVENUE	NY LTANKS	Higher	1860, 0.352, NNE
CM990	EXXONMOBIL	153-169 SEVENTH AVE	NY LTANKS	Higher	1865, 0.353, ESE
CM991	MOBIL STATION #17Q53	153-169 SEVENTH AVE	NY LTANKS	Higher	1865, 0.353, ESE
CM992	EXXONMOBIL	153-169 SEVENTH AVE	NY LTANKS	Higher	1865, 0.353, ESE
993	328 WEST 12TH STREET	328 WEST 12TH STREET	NY LTANKS	Higher	1906, 0.361, SSW
CI994	PRIVATE RES	160 W 16TH ST	NY LTANKS	Higher	1923, 0.364, SE
995	ELLIOTT HOUSES -NYCH	426 WEST 27TH ST	NY LTANKS, NY Spills	Higher	1941, 0.368, NNE
996	514 WEST END AVENUE	514 WEST AVENUE	NY LTANKS	Lower	1966, 0.372, SW
CK997	PENSKE TRUCK LEASING	536 W 26TH ST	NY LTANKS, NY Spills, RCRA NonGen / NLR, FINDS,...	Lower	1989, 0.377, North
CJ998	260 WEST 26TH STREET	260 WEST 26TH STREET	NY VCP	Higher	2005, 0.380, ENE
CN999	771 WASHINGTON STREE	771 WASHINGTON STREE	NY VCP	Lower	2036, 0.386, SSW
1000	APRTMENT BUILDING	161 WEST 15TH ST	NY LTANKS	Higher	2044, 0.387, SE
1001	ANN'S SERVICE CORP	166 WEST 22ND STREET	NY LTANKS, NY Spills	Higher	2056, 0.389, East
CO1002	1 BANK ST/CASTLE COA	1 BANK STREET	NY LTANKS, NY AST	Higher	2057, 0.390, SSE
CJ1003	HAG REALITY	250 WEST 26TH ST	NY LTANKS	Higher	2065, 0.391, ENE
CP1004	28TH UNDER HIGHLINE	505 W 27TH ST	NY LTANKS, NY MANIFEST	Higher	2082, 0.394, North
CL1005	CLOSED-LACKOF RECENT	303 9TH AVENUE	NY LTANKS	Higher	2090, 0.396, NNE
1006	393 WEST 12TH ST	393 WEST 12TH ST	NY LTANKS	Lower	2111, 0.400, SSW
1007	201 11TH AVE/MANH/US	201 11TH AVENUE	NY LTANKS	Lower	2163, 0.410, NNW
1008	226 WEST 26TH STREET	226 WEST 26TH STREET	NY LTANKS, NY Spills	Higher	2179, 0.413, ENE
CP1009	10TH AVE. W 27/W 28	303 10TH AVE	NY LTANKS, NY Spills	Higher	2187, 0.414, NNE
CQ1010	FEDERAL BUILDING THE	252 7TH AVE	SEMS-ARCHIVE, RCRA NonGen / NLR	Higher	2216, 0.420, ENE
CQ1011	FEDERAL BUILDING SIT	252 7TH AVE	NY HSWDS	Higher	2216, 0.420, ENE
CO1012	THE DERMOT COMPANY	207-209 WEST 11TH ST	NY LTANKS	Higher	2231, 0.423, SSE
CO1013	X	201 W. 11TH ST	NY LTANKS	Higher	2239, 0.424, SSE

MAPPED SITES SUMMARY

Target Property Address:
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
CP1014	311 10TH AVENUE	311 10TH AVENUE	NY VCP	Higher	2248, 0.426, NNE
1015	APARTMENT BLDG.- TTF	135 W. 17TH ST.	NY LTANKS	Higher	2251, 0.426, ESE
CN1016	SUPERIOR PRINTING IN	70 BETHUNE ST	NY LTANKS, NY UST, NY BROWNFIELDS, NY Spills, RCRA...	Lower	2279, 0.432, SSW
CR1017	514-520 WEST 28TH ST	514-520 WEST 28TH ST	NY BROWNFIELDS	Higher	2320, 0.439, North
CS1018	COMMERCIAL BUILDING	260 11TH AVE	NY LTANKS	Lower	2328, 0.441, North
CT1019	SPILL NUMBER 0110039	153 W 23RD ST	NY LTANKS	Higher	2335, 0.442, East
CR1020	526-532 WEST 28TH ST	526 WEST 28TH STREET	NY VCP	Lower	2338, 0.443, North
CR1021	507-515 WEST 28TH ST	507 WEST 28TH STREET	NY VCP	Higher	2358, 0.447, North
CT1022	APARTMENT BUILDING	148 WEST 24TH STREET	NY LTANKS, NY Spills	Higher	2372, 0.449, East
CR1023	PARKING LOT OF	515 WEST 28TH ST	NY LTANKS	Higher	2416, 0.458, North
CT1024	SPILL NUMBER 0110441	142 WEST 24TH ST	NY LTANKS	Higher	2419, 0.458, East
CU1025	NYC DEPT OF SANITATI	640 WEST 26TH ST	NY LTANKS	Lower	2431, 0.460, NNW
CU1026	NYC SANITATION	640 WEST 26TH STREET	NY LTANKS	Lower	2431, 0.460, NNW
1027	OLD GAS STATION	276 7TH AVE	NY LTANKS	Higher	2463, 0.466, ENE
1028	MANHATTAN GENERAL MA	WEST 29TH & 9TH AVE	SEMS-ARCHIVE	Higher	2473, 0.468, NNE
1029	UNKNOWN RESIDENCE	55 PERRY ST	NY LTANKS	Higher	2478, 0.469, South
CU1030	601 WEST 26TH STREET	601 WEST 26TH STREET	NY LTANKS, NY Spills	Lower	2479, 0.470, NNW
CU1031	ELECTRICAL BUSS COMP	601 W 26TH ST	NY LTANKS, NY Spills	Lower	2479, 0.470, NNW
1032	APARTMENT BUILDING	347 WEST 29TH ST	NY LTANKS	Higher	2556, 0.484, NE
CS1033	271 11TH AVE/MANHATT	271 11TH AVE	NY LTANKS	Lower	2567, 0.486, North
CV1034	117 W 13TH ST/MANHAT	117 WEST 13TH STREET	NY LTANKS	Higher	2583, 0.489, SE
CW1035	522-532 WEST 29TH ST	522 WEST 29TH STREET	NY VCP	Higher	2585, 0.490, North
CW1036	HIGH RIDGE ENTERPRIS	524 WEST 29TH STREET	NY LTANKS, NY Spills	Higher	2605, 0.493, North
CV1037	SPOONS	110 WEST 14TH STREET	NY LTANKS, NY Spills	Higher	2610, 0.494, SE
1038	241 WEST 28TH STREET	241 WEST 28TH STREET	NY BROWNFIELDS	Higher	2612, 0.495, ENE
CW1039	534 WEST 29TH STREET	534 WEST 29TH STREET	NY VCP	Lower	2617, 0.496, North
1040	HELIPORT W 30TH ST/M	HELIPORT/W.30TH ST &	NY LTANKS	Higher	2631, 0.498, NNE
CW1041	542 WEST 29TH STREET	538-542 WEST 29TH ST	NY BROWNFIELDS	Lower	2636, 0.499, North
1042	MARKITE CO.	155 WAVERLY PLACE	FUSRAP	Higher	3401, 0.644, SSE
1043	FORMER GUARDIAN CLEA	27-35 WEST 24TH STRE	NY SHWS, NY ENG CONTROLS, NY INST CONTROL	Higher	3405, 0.645, East
1044	PIER 45 STORAGE/BERT		FUDS	Lower	3849, 0.729, SSW
1045	HUDSON DRY CLEANERS	462 HUDSON STREET	NY SHWS, NY DRYCLEANERS	Higher	3995, 0.757, South
1046	LIRR WEST SIDE YARD	12TH AVE AND W 33RD	NY SHWS	Lower	4180, 0.792, North
1047	PIER 42 STORAGE/BERT		FUDS	Lower	4409, 0.835, SSW
1048	STEVENS INSTITUTE OF	CASTLE POINT TER	NJ SHWS	Higher	4943, 0.936, West
1049	UNION DRY DOCK & REP	901 SINATRA DR	NJ SHWS, NJ UST, NJ AIRS, NJ Financial Assurance,...	Higher	4999, 0.947, WNW
1050	STEVENS INSTITUTE OF	600 SINATRA DR	NJ SHWS	Higher	5201, 0.985, West

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 9 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
CON EDISON F/O 420 WEST 18 ST NEW YORK, NY 10011	NY MANIFEST EPA ID: NYP004680872	N/A
RESIDENTIAL 400 WEST 17TH ST MANHATTAN, NY	NY Spills Spill Number/Closed Date: 2001535 / 2020-08-05 Site ID: 606183 Spill Date: 2020-06-02	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---------- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---------- Federal Facility Site Information listing

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS ---------- Corrective Action Report

Lists of Federal RCRA TSD facilities

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System

EXECUTIVE SUMMARY

Federal ERNS list

ERNS ---------- Emergency Response Notification System

Lists of state and tribal landfills and solid waste disposal facilities

NJ SWF/LF ---------- Solid Waste Facility Directory

Lists of state and tribal leaking storage tanks

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS ---------- Listing of Leaking Storage Tanks

Lists of state and tribal registered storage tanks

FEMA UST ---------- Underground Storage Tank Listing
NY CBS UST ---------- Chemical Bulk Storage Database
NY MOSF UST ---------- Major Oil Storage Facilities Database
NY MOSF ---------- Major Oil Storage Facility Site Listing
NY MOSF AST ---------- Major Oil Storage Facilities Database
INDIAN UST ---------- Underground Storage Tanks on Indian Land

State and tribal institutional control / engineering control registries

NY RES DECL ---------- Restrictive Declarations Listing
NJ ENG CONTROLS ---------- Declaration Environmental Restriction/Deed Notice Sites
NJ INST CONTROL ---------- Classification Exception Area Sites

Lists of state and tribal voluntary cleanup sites

INDIAN VCP ---------- Voluntary Cleanup Priority Listing
NJ VCP ---------- Voluntary Cleanup Program Sites

Lists of state and tribal brownfield sites

NJ BROWNFIELDS ---------- Brownfields Database
NY ERP ---------- Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWRCY ---------- Registered Recycling Facility List
NY SWTIRE ---------- Registered Waste Tire Storage & Facility List
NJ SWRCY ---------- Approved Class B Recycling Facilities
INDIAN ODI ---------- Report on the Status of Open Dumps on Indian Lands
ODI ---------- Open Dump Inventory
DEBRIS REGION 9 ---------- Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ---------- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---------- Delisted National Clandestine Laboratory Register

NY DEL SHWS ---- Delisted Registry Sites
US CDL ---- National Clandestine Laboratory Register
NY PFAS ---- PFAS Contamination Site Location Listing
NJ PFAS ---- PFAS Contamination Site Location

Local Lists of Registered Storage Tanks

NY HIST UST ---- Historical Petroleum Bulk Storage Database
NY HIST AST ---- Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS ---- Spill Liens Information
NJ LIENS ---- Environmental LIENS
LIENS 2 ---- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---- Hazardous Materials Information Reporting System
NY Hist Spills ---- SPILLS Database
NY SPILLS 90 ---- SPILLS 90 data from FirstSearch
NJ SPILLS 90 ---- SPILLS 90 data from FirstSearch
NY SPILLS 80 ---- SPILLS 80 data from FirstSearch
NJ SPILLS 80 ---- SPILLS 80 data from FirstSearch

Other Ascertainable Records

DOD ---- Department of Defense Sites
SCRD DRYCLEANERS ---- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---- Financial Assurance Information
EPA WATCH LIST ---- EPA WATCH LIST
2020 COR ACTION ---- 2020 Corrective Action Program List
TSCA ---- Toxic Substances Control Act
TRIS ---- Toxic Chemical Release Inventory System
SSTS ---- Section 7 Tracking Systems
RMP ---- Risk Management Plans
RAATS ---- RCRA Administrative Action Tracking System
PADS ---- PCB Activity Database System
FTTS ---- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ---- Material Licensing Tracking System
COAL ASH DOE ---- Steam-Electric Plant Operation Data
COAL ASH EPA ---- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---- PCB Transformer Registration Database
RADINFO ---- Radiation Information Database
HIST FTTS ---- FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ---- Incident and Accident Data
INDIAN RESERV ---- Indian Reservations
UMTRA ---- Uranium Mill Tailings Sites
LEAD SMELTERS ---- Lead Smelter Sites
US MINES ---- Mines Master Index File
ABANDONED MINES ---- Abandoned Mines
UXO ---- Unexploded Ordnance Sites
DOCKET HWC ---- Hazardous Waste Compliance Docket Listing
FUELS PROGRAM ---- EPA Fuels Program Registered Listing

NY AIRS ---------- Air Emissions Data
NY COAL ASH ---------- Coal Ash Disposal Site Listing
NJ COAL ASH ---------- Coal Ash Listing
NJ DRYCLEANERS ---------- Drycleaner List
NY Financial Assurance ---------- Financial Assurance Information Listing
NY SPDES ---------- State Pollutant Discharge Elimination System
NY VAPOR REOPENED ---------- Vapor Intrusion Legacy Site List
NY UIC ---------- Underground Injection Control Wells
NJ UIC ---------- Underground Injection Wells Database
NY LEAD ---------- Lead-based Paint Testing Results
MINES MRDS ---------- Mineral Resources Data System

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS ---------- Recovered Government Archive State Hazardous Waste Facilities List
NJ RGA HWS ---------- Recovered Government Archive State Hazardous Waste Facilities List
NY RGA LF ---------- Recovered Government Archive Solid Waste Facilities List
NJ RGA LF ---------- Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: Also known as Superfund, the National Priority List database is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund program. The source of this database is the U.S. EPA.

A review of the NPL list, as provided by EDR, and dated 01/25/2022 has revealed that there is 1 NPL site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HUDSON RIVER PCBS Cerclis ID:: 202229 EPA Id: NYD980763841	***NO STREET APPLICABLE***	***W 1/8 - 1/4 (0.245 mi.)***	***0***	***11***

EXECUTIVE SUMMARY

Lists of Federal sites subject to CERCLA removals and CERCLA orders

SEMS: SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

A review of the SEMS list, as provided by EDR, and dated 01/25/2022 has revealed that there is 1 SEMS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HUDSON RIVER PCBS Site ID: 0202229 EPA Id: NYD980763841	***NO STREET APPLICABLE***	***W 1/8 - 1/4 (0.245 mi.)***	***0***	***11***

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 01/25/2022 has revealed that there are 2 SEMS-ARCHIVE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FEDERAL BUILDING THE Site ID: 0203218 EPA Id: NY2470000157	***252 7TH AVE***	***ENE 1/4 - 1/2 (0.420 mi.)***	***CQ1010***	***2834***
MANHATTAN GENERAL MA Site ID: 0203777 EPA Id: NY6180000352	WEST 29TH & 9TH AVE	NNE 1/4 - 1/2 (0.468 mi.)	1028	2877

Lists of Federal RCRA generators

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA)

of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 02/28/2022 has revealed that there are 36 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HUDSON RIVER PCBS EPA ID:: NYD980763841	***NO STREET APPLICABLE***	***W 1/8 - 1/4 (0.245 mi.)***	***0***	***11***
CON EDISON EPA ID:: NYP005244868	W 16TH ST & 9TH AVE	S 0 - 1/8 (0.007 mi.)	D33	121
CON EDISON - MANHOLE EPA ID:: NYP005127950	179 9TH AVE	NE 0 - 1/8 (0.062 mi.)	P188	470
CON EDISON - SERVICE EPA ID:: NYP004171443	***48 9TH AVENUE***	***S 0 - 1/8 (0.091 mi.)***	***S300***	***704***
CON EDISON - SERVICE EPA ID:: NYP004171435	WEST 14TH STREET AND	SSW 0 - 1/8 (0.108 mi.)	S378	918
MOUNT SINAI - BETH I EPA ID:: NYR000060384	***325 W 15TH ST***	***SSE 1/8 - 1/4 (0.129 mi.)***	***X461***	***1148***
CON EDISON - SERVICE EPA ID:: NYP004171476	***WEST 16TH STREET AND***	***SE 1/8 - 1/4 (0.180 mi.)***	***AT648***	***1814***
CON EDISON - SERVICE EPA ID:: NYP004270161	***N/W/C WEST 48TH ST.***	***NNE 1/8 - 1/4 (0.183 mi.)***	***AX657***	***1860***
CON EDISON - VAULT 4 EPA ID:: NYP005137918	433 W 23RD ST	NNE 1/8 - 1/4 (0.185 mi.)	AX663	1877
CON EDISON - MANHOLE EPA ID:: NYP005115142	326 W 23RD ST	ENE 1/8 - 1/4 (0.195 mi.)	AO709	2044
CON EDISON - GAS MAI EPA ID:: NYP004706669	***17 9TH AVE***	***SSW 1/8 - 1/4 (0.195 mi.)***	***AR713***	***2053***
CON EDISON - TRANSFO EPA ID:: NYP004852667	73 8TH AVE	SSE 1/8 - 1/4 (0.210 mi.)	AQ760	2169
CON EDISON - SERVICE EPA ID:: NYP004858819	320 W 23 ST	ENE 1/8 - 1/4 (0.211 mi.)	AZ767	2184
CON EDISON - MANHOLE EPA ID:: NYP004508479	8TH AVE & 22ND ST IN	ENE 1/8 - 1/4 (0.215 mi.)	AZ791	2232
CON EDISON - VAULT 3 EPA ID:: NYP004402095	***400 W 24 ST***	***NE 1/8 - 1/4 (0.222 mi.)***	***AU820***	***2317***
CON EDISON - SERVICE EPA ID:: NYP004863813	242 W 16 ST	SE 1/8 - 1/4 (0.234 mi.)	BO879	2484
NYCT - MH 1027 EPA ID:: NYP000975258	23RD ST & 8TH AVE	ENE 1/8 - 1/4 (0.248 mi.)	BX930	2641

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - MANHOLE EPA ID:: NYP004868594	460-454 W 16TH ST	WSW 0 - 1/8 (0.026 mi.)	C106	302
CON EDISON - MANHOLE	447 W 18TH ST	NW 0 - 1/8 (0.036 mi.)	G117	327

EPA ID:: NYP005138595				
CON EDISON - VAULT 4 EPA ID:: NYP005015581	421 W 15TH ST	SW 0 - 1/8 (0.047 mi.)	K151	403
CON EDISON - VAULT S EPA ID:: NYP005015599	421 W 15TH ST	SW 0 - 1/8 (0.047 mi.)	K154	407
CON EDISON - MANHOLE EPA ID:: NYP004866644	***412 W 15TH ST***	***SW 0 - 1/8 (0.065 mi.)***	***K201***	***497***
CON EDISON - VAULT 2 EPA ID:: NYP005064621	412 W 15TH ST	SW 0 - 1/8 (0.065 mi.)	K202	500
CON EDISON - VAULT 6 EPA ID:: NYP004380184	***450 W 15 ST***	***WSW 0 - 1/8 (0.073 mi.)***	***K244***	***582***
CON EDISON - TRENCH EPA ID:: NYP004372488	***450 W15 ST. W/O 9TH***	***WSW 0 - 1/8 (0.073 mi.)***	***K246***	***587***
85 TENTH AVENUE ASSO EPA ID:: NYR000099978	***85 10TH AVE***	***W 0 - 1/8 (0.091 mi.)***	***Q302***	***711***
CON EDISON - TRANSFO EPA ID:: NYP004861403	WASHINGTON ST & W 14	SW 0 - 1/8 (0.109 mi.)	W389	936
CON EDISON GASMAIN 8	10TH AVE & W 22 ST	N 1/8 - 1/4 (0.151 mi.)	AG530	1365
CON EDISON - MANHOLE EPA ID:: NYP004259933	***OPP 197 10TH AVE***	***N 1/8 - 1/4 (0.151 mi.)***	***AG531***	***1367***
CON EDISON - SERVICE EPA ID:: NYP004291878	***407 WEST 13TH ST***	***SSW 1/8 - 1/4 (0.154 mi.)***	***AD542***	***1403***
17TH STREET DEVELOPM EPA ID:: NYR000227256	76 11TH AVE	NW 1/8 - 1/4 (0.155 mi.)	AK543	1408
CON EDISON - MANHOLE EPA ID:: NYP004278271	W 5 AVE ESW 15 ST	N 1/8 - 1/4 (0.195 mi.)	BA712	2050
CON EDISON - SERVICE EPA ID:: NYP004171062	***51 LITTLE W12TH ST.***	***SW 1/8 - 1/4 (0.207 mi.)***	***AS742***	***2118***
CON EDISON - SERVICE EPA ID:: NYP004171047	***44 LITTLE W12TH ST.***	***SW 1/8 - 1/4 (0.223 mi.)***	***BL828***	***2341***
CON EDISON - GAS MAI EPA ID:: NYP004249585	E HOUSTON AT COLUMBI	SSW 1/8 - 1/4 (0.226 mi.)	BM837	2380
CON EDISON - SERVICE EPA ID:: NYP004289096	53 GANSEVOORT ST	SSW 1/8 - 1/4 (0.230 mi.)	BJ855	2423

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 02/28/2022 has revealed that there are 9 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
VELAZQUEZ 9TH AVENUE EPA ID:: NYD987017241	***126 9TH AVE***	***ESE 0 - 1/8 (0.018 mi.)***	***A83***	***249***
GENERAL THEOLOGICAL	***175 9TH AVE***	***NE 0 - 1/8 (0.034 mi.)***	***B115***	***320***

EPA ID:: NYR000050716				
COVENANT HOUSE THE EPA ID:: NYR000160358	***346 W 17TH ST***	***SSE 0 - 1/8 (0.053 mi.)***	***F164***	***425***
NYC DEPT OF EDUCATIO EPA ID:: NYR000214536	250 W 18TH ST	ESE 1/8 - 1/4 (0.216 mi.)	BF799	2252
OXFORD DRY CLEANERS EPA ID:: NYD981492663	***232 9TH AVENUE***	***NE 1/8 - 1/4 (0.238 mi.)***	***BK893***	***2529***
MTA NYCT - 23RD STRE EPA ID:: NYR000168245	23RD ST & 8TH AVE	ENE 1/8 - 1/4 (0.248 mi.)	BX929	2639

Lower Elevation	Address	Direction / Distance	Map ID	Page
NORTHEAST LABORATORY EPA ID:: NYD987017514	***99 10TH AVE ROOM 721***	***W 0 - 1/8 (0.095 mi.)***	***Q326***	***778***
HLP PROPERTIES LOT EPA ID:: NYR000194449	***501-515 W 17TH ST***	***WNW 0 - 1/8 (0.099 mi.)***	***U338***	***828***
DIA ART FOUNDATION EPA ID:: NYR000144089	***535 W 22ND ST***	***NNW 1/8 - 1/4 (0.230 mi.)***	***BN854***	***2419***

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 02/28/2022 has revealed that there are 26 RCRA-VSQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GOOGLE LLC EPA ID:: NYD001328368	***76 9TH AVE***	***S 0 - 1/8 (0.011 mi.)***	***D53***	***163***
NBC UNIVERSAL INC - EPA ID:: NYR000161091	75 9TH AVE - 7TH FLO	SSW 0 - 1/8 (0.041 mi.)	J135	369
NYC BD OF ED - HUMAN EPA ID:: NYR000080705	***351 W 18TH ST***	***ESE 0 - 1/8 (0.047 mi.)***	***H150***	***398***
NYC BOARD OF EDUCATI EPA ID:: NYR000062604	***333 W 17TH ST***	***SE 0 - 1/8 (0.096 mi.)***	***T331***	***804***
RITE AID #04196 EPA ID:: NYR000188623	***188 9TH AVE***	***NE 0 - 1/8 (0.098 mi.)***	***P336***	***820***
401 WEST 14TH STREET EPA ID:: NYR000141937	***401 W 14TH ST***	***SSW 0 - 1/8 (0.099 mi.)***	***S341***	***839***
SPERANZA PROPERTIES EPA ID:: NYR000166579	***448 W 22ND ST***	***NNE 0 - 1/8 (0.109 mi.)***	***380***	***923***
NYC BD OF ED WILLIAM EPA ID:: NYR000080580	***320 W 21ST ST***	***ENE 0 - 1/8 (0.118 mi.)***	***R430***	***1034***
JEAN'S MANHATTAN CLE	***198 9TH AVE***	***NE 1/8 - 1/4 (0.130 mi.)***	***AB462***	***1160***

EPA ID:: NYR000104232				
NYCT - PUMP ROOM #20 EPA ID:: NYR000122010	***18TH ST & 8TH AVE***	***ESE 1/8 - 1/4 (0.180 mi.)***	***AL650***	***1820***
CVS PHARMACY #2919 EPA ID:: NYR000193342	***126 8TH AVE***	***SE 1/8 - 1/4 (0.189 mi.)***	***AT688***	***1955***
GANSEVOORT CORPERATI EPA ID:: NYR000124727	***652 HUDSON ST***	***S 1/8 - 1/4 (0.191 mi.)***	***BC694***	***1970***
CVS PHARMACY #1618 EPA ID:: NYR000193383	***81 8TH AVE***	***SSE 1/8 - 1/4 (0.192 mi.)***	***BB700***	***1995***
NYCTA - 14TH ST STAT EPA ID:: NY0000973719	***14TH ST & 8TH AVE***	***SSE 1/8 - 1/4 (0.210 mi.)***	***BH752***	***2151***
LONDON TERRACE CLEAN EPA ID:: NYD981137185	***410 W 24TH ST***	***NNE 1/8 - 1/4 (0.221 mi.)***	***BK816***	***2300***
JOHN'S TAILOR & CLEA EPA ID:: NYR000078899	***6903 8TH AVE***	***SSE 1/8 - 1/4 (0.222 mi.)***	***BE823***	***2325***

Lower Elevation	Address	Direction / Distance	Map ID	Page
BLENHEIM LLC EPA ID:: NYR000143867	***85 10TH AVE - BASEME***	***W 0 - 1/8 (0.091 mi.)***	***Q306***	***719***
EMPIRE CITY SUBWAY C EPA ID:: NY0000821736	***177-183 10TH AVE***	***NNW 0 - 1/8 (0.107 mi.)***	***AA369***	***900***
520 WEST 19TH STREET EPA ID:: NYR000142745	***516-522 W 19TH ST***	***NW 0 - 1/8 (0.122 mi.)***	***Z447***	***1092***
NYCT - HUDSON DEPOT EPA ID:: NYD980642235	WEST 15TH ST & 11TH	W 1/8 - 1/4 (0.138 mi.)	AE481	1218
WEST CHELSEA DEVELOP EPA ID:: NYR000142117	***535 W 19TH ST - VACA***	***NW 1/8 - 1/4 (0.161 mi.)***	***AK572***	***1540***
GREENWAY MEWS REALTY EPA ID:: NYR000200550	***416 W 13TH ST #300***	***SSW 1/8 - 1/4 (0.176 mi.)***	***AV626***	***1749***
A B GREEN GANSEVOORT EPA ID:: NYR000129114	***856 WASHINGTON ST***	***SW 1/8 - 1/4 (0.178 mi.)***	***AS638***	***1784***
EXXON DIV OF CFI #70 EPA ID:: NYD987026069	***215 10TH AVE & W 23R***	***N 1/8 - 1/4 (0.182 mi.)***	***AG654***	***1846***
CVS PHARMACY #10041 EPA ID:: NYR000198234	***500 W 23RD ST***	***N 1/8 - 1/4 (0.186 mi.)***	***BA675***	***1904***
BAYVIEW CORRECTIONAL EPA ID:: NYR000117242	***550 W 20TH ST***	***NW 1/8 - 1/4 (0.187 mi.)***	***AY678***	***1922***

Federal institutional controls / engineering controls registries

US ENG CONTROLS: A listing of sites with engineering controls in place.

A review of the US ENG CONTROLS list, as provided by EDR, and dated 11/19/2021 has revealed that there is 1 US ENG CONTROLS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HUDSON RIVER PCBS	***NO STREET APPLICABLE***	***W 1/8 - 1/4 (0.245 mi.)***	***0***	***11***
EPA ID:: NYD980763841				
EPA ID:: NYD980763841				

US INST CONTROLS: A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

A review of the US INST CONTROLS list, as provided by EDR, and dated 11/19/2021 has revealed that there is 1 US INST CONTROLS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HUDSON RIVER PCBS	***NO STREET APPLICABLE***	***W 1/8 - 1/4 (0.245 mi.)***	***0***	***11***
EPA ID:: NYD980763841				

Lists of state- and tribal hazardous waste facilities

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 01/06/2022 has revealed that there are 4 NY SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FORMER GUARDIAN CLEA	***27-35 WEST 24TH STRE***	***E 1/2 - 1 (0.645 mi.)***	***1043***	***2923***
Site Code: 440109				
HUDSON DRY CLEANERS	***462 HUDSON STREET***	***S 1/2 - 1 (0.757 mi.)***	***1045***	***2943***
Site Code: 486480				

Lower Elevation	Address	Direction / Distance	Map ID	Page
BAYVIEW CORRECTIONAL	***550 W 20TH ST***	***NW 1/8 - 1/4 (0.187 mi.)***	***AY678***	***1922***
Site Code: 582178				
LIRR WEST SIDE YARD	12TH AVE AND W 33RD	N 1/2 - 1 (0.792 mi.)	1046	2945
Site Code: 478613				

NJ SHWS: Known contaminated sites in New Jersey except those associated with Bureau of Underground Storage Sites (BUST)

A review of the NJ SHWS list, as provided by EDR, and dated 11/01/2021 has revealed that there are 3 NJ SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
STEVENS INSTITUTE OF Site ID: 22064 Status: Active	CASTLE POINT TER	W 1/2 - 1 (0.936 mi.)	1048	2949
UNION DRY DOCK & REP Site ID: 21300 Status: Active	***901 SINATRA DR***	***WNW 1/2 - 1 (0.947 mi.)***	***1049***	***2949***
STEVENS INSTITUTE OF Site ID: 92532 Status: Closed	600 SINATRA DR	W 1/2 - 1 (0.985 mi.)	1050	2957

Lists of state and tribal landfills and solid waste disposal facilities

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 12/21/2021 has revealed that there is 1 NY SWF/LF site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NYCDOS GANESVOORT MT	GANESVOORT ST & WEST	SW 1/4 - 1/2 (0.325 mi.)	979	2753

Lists of state and tribal leaking storage tanks

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 03/15/2022 has revealed that there are 132 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LAWRENCE ENVIRONMENT Spill Number/Closed Date: 1107687 / 2011-10-31 Site ID: 455396 Spill Date: 2011-09-16	***364 WEST 18TH STREET***	***ESE 0 - 1/8 (0.039 mi.)***	***F122***	***336***
SCHOOL OF HUMANITES Spill Number/Closed Date: 0013005 / 2001-03-15 Site ID: 113466 Spill Date: 2001-03-10	18TH-19TH	ESE 0 - 1/8 (0.059 mi.)	H179	451
DR. SERSINI Spill Number/Closed Date: 9411689 / 1994-12-02 Site ID: 151614 Spill Date: 1994-12-02	415 WEST 21ST STREET	NNE 0 - 1/8 (0.083 mi.)	O280	663
415 W. 21ST STREET Spill Number/Closed Date: 9412289 / 1994-12-14	415 W. 21ST STREET	NNE 0 - 1/8 (0.083 mi.)	O281	664

Site ID: 267931
Spill Date: 1994-12-14

MINICK HOME — 440 WEST 22ND STREET — NNE 0 - 1/8 (0.108 mi.) — O373 — 909
Spill Number/Closed Date: 0512757 / 2006-03-10
Site ID: 359128
Spill Date: 2006-02-03

310 WEST 18TH STREET — 310 WEST 18TH STREET — ESE 1/8 - 1/4 (0.144 mi.) — AC506 — 1308
Spill Number/Closed Date: 9612959 / 2000-02-09
Site ID: 163174
Spill Date: 1997-02-01

308 WEST 18TH ST — 308 WEST 18TH ST — ESE 1/8 - 1/4 (0.148 mi.) — AC518 — 1338
Spill Number/Closed Date: 9511332 / 1995-12-08
Site ID: 233856
Spill Date: 1995-12-07

15TH ST & 8TH AVE/BK — 15TH ST / 8TH AVE — SSE 1/8 - 1/4 (0.187 mi.) — BB682 — 1938
Spill Number/Closed Date: 8905987 / 2004-01-12
Site ID: 93820
Spill Date: 1989-09-18

APARTMENT BUILDING — 652 HUDSON STREET — S 1/8 - 1/4 (0.191 mi.) — BC693 — 1968
Spill Number/Closed Date: 0312193 / 2004-02-02
Site ID: 279919
Spill Date: 2004-02-02

SINO REALTY REALTY — 204 8TH AVENUE — E 1/8 - 1/4 (0.200 mi.) — AW722 — 2072
Spill Number/Closed Date: 8905180 / 1997-09-15
Site ID: 304456
Spill Date: 1989-08-25

SPILL NUMBER 9912064 — 96 8TH AVE — SSE 1/8 - 1/4 (0.204 mi.) — BB731 — 2090
Spill Number/Closed Date: 9912064 / 2003-07-24
Site ID: 158669
Spill Date: 2000-01-19

APARTMENT BUILDING — 80 8TH AVENUE — SSE 1/8 - 1/4 (0.212 mi.) — BB775 — 2201
Spill Number/Closed Date: 1305350 / 2014-04-11
Site ID: 485913
Spill Date: 2013-08-16

APT. BUILDING — 312 WEST 23RD ST — ENE 1/8 - 1/4 (0.213 mi.) — AZ777 — 2205
Spill Number/Closed Date: 0706771 / 2007-10-11
Site ID: 387352
Spill Date: 2007-09-18

258 WEST 15TH ST/MAN — 258 WEST 15TH STREET — SSE 1/8 - 1/4 (0.219 mi.) — BB805 — 2268
Spill Number/Closed Date: 8807781 / 1992-12-04
Site ID: 241507
Spill Date: 1988-12-23

APARTMENT HOUSE — 264 W. 19TH ST — ESE 1/8 - 1/4 (0.229 mi.) — BI850 — 2408
Spill Number/Closed Date: 0209894 / 2003-03-26
Site ID: 147581
Spill Date: 2002-12-30

APARTMENT BUILDING — 250 W. 15TH ST — SSE 1/8 - 1/4 (0.231 mi.) — BB859 — 2431
Spill Number/Closed Date: 9802344 / 2015-04-01
Site ID: 138189
Spill Date: 1998-05-22

GETTY — 63 8TH AVENUE — SSE 1/8 - 1/4 (0.234 mi.) — BH873 — 2465

Spill Number/Closed Date: 0210903 / 2003-12-24
Site ID: 123040
Spill Date: 2003-01-30

SPILL NUMBER 0010929 | 251 W. 19TH ST | ESE 1/8 - 1/4 (0.237 mi.) | BD885 | 2504
Spill Number/Closed Date: 0010929 / 2003-07-29
Site ID: 267564
Spill Date: 2000-01-03

APT HOUSE | ***240 WEST 16TH ST*** | ***SE 1/8 - 1/4 (0.240 mi.)*** | ***BO905*** | ***2581***
Spill Number/Closed Date: 9800017 / 1998-04-01
Site ID: 84991
Spill Date: 1998-04-01

SPILL NUMBER 9811171 | 240 WEST 16TH ST | SE 1/8 - 1/4 (0.240 mi.) | BO906 | 2583
Spill Number/Closed Date: 9811171 / 1998-12-07
Site ID: 320054
Spill Date: 1998-12-05

236 E. 16 ST REALTY | ***236 EAST 16TH STREET*** | ***SE 1/8 - 1/4 (0.245 mi.)*** | ***BO917*** | ***2604***
Spill Number/Closed Date: 0411114 / 2005-11-17
Site ID: 336367
Spill Date: 2005-01-13

53 HORACIO STREET | 53 HORACIO STREET | SSW 1/4 - 1/2 (0.264 mi.) | BV949 | 2694
Spill Number/Closed Date: 9406077 / 1994-08-04
Site ID: 205771
Spill Date: 1994-08-04

ELK INVESTOR - COMME | ***400 WEST 25TH ST*** | ***NE 1/4 - 1/2 (0.264 mi.)*** | ***950*** | ***2695***
Spill Number/Closed Date: 1812190 / 2019-08-22
Spill Number/Closed Date: 9310011 / 1993-11-17
Site ID: 584153
Site ID: 300724
Spill Date: 2019-03-12
Spill Date: 1993-11-17

APARTMENT COMPLEX | 238 WEST 14TH STREET | SSE 1/4 - 1/2 (0.267 mi.) | BY951 | 2700
Spill Number/Closed Date: 9610832 / 1996-12-02
Site ID: 239500
Spill Date: 1996-12-02

CON EDISON | ***2 HORATIO ST*** | ***SSE 1/4 - 1/2 (0.279 mi.)*** | ***BZ955*** | ***2706***
Spill Number/Closed Date: 9912024 / 2000-02-08
Site ID: 152651
Spill Date: 2000-01-18

2 HORATIO ST | 2 HORATIO ST | SSE 1/4 - 1/2 (0.279 mi.) | BZ956 | 2709
Spill Number/Closed Date: 9601839 / 1996-05-09
Site ID: 152650
Spill Date: 1996-05-07

CHELSEA HOUSES -NYCH | ***431 WEST 25TH ST*** | ***NNE 1/4 - 1/2 (0.279 mi.)*** | ***BR958*** | ***2711***
Spill Number/Closed Date: 9806339 / 2013-08-27
Site ID: 158080
Spill Date: 1998-08-21

APARTMENT BUILDING | 241 WEST 13TH STREET | SSE 1/4 - 1/2 (0.284 mi.) | BY959 | 2715
Spill Number/Closed Date: 9809486 / 2005-06-14
Site ID: 84573
Spill Date: 1998-10-28

229 WEST 14TH STREET | 229 WEST 14TH STREET | SSE 1/4 - 1/2 (0.288 mi.) | BY962 | 2720

Spill Number/Closed Date: 9312989 / 1994-02-03
Spill Number/Closed Date: 9801147 / 2005-07-08
Spill Number/Closed Date: 1002102 / 2010-07-28
Site ID: 229780
Site ID: 229781
Site ID: 435201
Spill Date: 1994-02-03
Spill Date: 1998-04-20
Spill Date: 2010-05-24

COMMERCIAL TTF	***61 JANE AVE***	***S 1/4 - 1/2 (0.296 mi.)***	***CC964***	***2724***
Spill Number/Closed Date: 1504935 / 2015-10-13 Site ID: 511290 Spill Date: 2015-08-06				
APARTMENT	214 WEST 20TH STREET	ESE 1/4 - 1/2 (0.298 mi.)	965	2726
Spill Number/Closed Date: 0601208 / 2006-07-20 Site ID: 363391 Spill Date: 2006-05-02				
APRT	213 WEST 18TH STREET	ESE 1/4 - 1/2 (0.303 mi.)	CD966	2728
Spill Number/Closed Date: 0800354 / 2010-04-13 Site ID: 396095 Spill Date: 2008-04-09				
APT BLDG	***255 WEST 23RD ST***	***ENE 1/4 - 1/2 (0.303 mi.)***	***CE967***	***2729***
Spill Number/Closed Date: 0209070 / 2007-06-21 Site ID: 79684 Spill Date: 2002-12-04				
255 W. 23RD ST	255 W. 23RD ST	ENE 1/4 - 1/2 (0.303 mi.)	CE968	2732
Spill Number/Closed Date: 0205799 / 2003-06-20 Site ID: 324079 Spill Date: 2002-09-04				
CLOSED-LACKOF RECENT	315 W. 25TH ST	NE 1/4 - 1/2 (0.304 mi.)	CF969	2734
Spill Number/Closed Date: 8908445 / 2003-03-06 Site ID: 138350 Spill Date: 1989-11-27				
MUTUAL REDEVELOPMENT	***315 WEST 25TH STREET***	***NE 1/4 - 1/2 (0.304 mi.)***	***CF970***	***2735***
Spill Number/Closed Date: 9602633 / 2005-09-16 Site ID: 257575 Spill Date: 1996-05-23				
VERIZON	210 W. 18TH ST	ESE 1/4 - 1/2 (0.310 mi.)	CD971	2744
Spill Number/Closed Date: 0303667 / 2003-07-08 Site ID: 207814 Spill Date: 2003-07-08				
APT HOUSE	16 JANE STREET	S 1/4 - 1/2 (0.317 mi.)	BZ974	2747
Spill Number/Closed Date: 0509778 / 2005-12-12 Site ID: 355610 Spill Date: 2005-11-15				
APT BLDG TTF	15 ABINGDON SQUARE	S 1/4 - 1/2 (0.319 mi.)	CH975	2748
Spill Number/Closed Date: 0909695 / 2010-02-25 Site ID: 422421 Spill Date: 2009-12-02				
APARTMENT BLDG	299 WEST 12TH ST	S 1/4 - 1/2 (0.324 mi.)	CC978	2752
Spill Number/Closed Date: 9603973 / 1996-07-03				

Site ID: 182231
Spill Date: 1996-06-23

CLOSED-LACKOF RECENT — 200 WEST 18TH STREET — ESE 1/4 - 1/2 (0.329 mi.) — CD981 — 2754
Spill Number/Closed Date: 9004954 / 2003-03-06
Site ID: 306974
Spill Date: 1990-08-03

317 WEST 12TH ST — 317 WEST 12TH ST — SSW 1/4 - 1/2 (0.330 mi.) — CC982 — 2756
Spill Number/Closed Date: 9612484 / 1997-04-21
Site ID: 134462
Spill Date: 1997-01-16

DEL. SPILL /W.28ST.& — W. 26TH ST & 10TH AV — N 1/4 - 1/2 (0.336 mi.) — 983 — 2757
Spill Number/Closed Date: 8605584 / 1986-12-04
Site ID: 295262
Spill Date: 1986-12-04

201 WEST 16TH ST COR — 201 WEST 16TH ST — SE 1/4 - 1/2 (0.340 mi.) — CI984 — 2758
Spill Number/Closed Date: 0008506 / 2005-12-22
Site ID: 304546
Spill Date: 2000-10-20

BUSINESS AT LOCATION — ***205 WEST 14TH ST*** — ***SE 1/4 - 1/2 (0.342 mi.)*** — ***985*** — ***2759***
Spill Number/Closed Date: 0400657 / 2004-05-10
Site ID: 159682
Spill Date: 2004-04-20

SPILL NUMBER 0104073 — ***304 8TH AV*** — ***ENE 1/4 - 1/2 (0.349 mi.)*** — ***CJ986*** — ***2763***
Spill Number/Closed Date: 0104060 / 2001-07-18
Site ID: 310569
Spill Date: 2001-07-17

GOODSTEIN MNGMT — 302 W 12TH ST — S 1/4 - 1/2 (0.351 mi.) — CH988 — 2767
Spill Number/Closed Date: 8805303 / 1988-09-29
Site ID: 110169
Spill Date: 1988-09-29

PUBLIC SCHOOL #33 — 281 9TH AVENUE — NNE 1/4 - 1/2 (0.352 mi.) — CL989 — 2768
Spill Number/Closed Date: 9713196 / 2003-03-03
Spill Number/Closed Date: 9614151 / 1997-12-31
Site ID: 224963
Site ID: 252801
Spill Date: 1998-02-26
Spill Date: 1997-03-05

EXXONMOBIL — 153-169 SEVENTH AVE — ESE 1/4 - 1/2 (0.353 mi.) — CM990 — 2770
Spill Number/Closed Date: 9209472 / 1992-12-07
Site ID: 188431
Spill Date: 1992-11-13

MOBIL STATION #17Q53 — 153-169 SEVENTH AVE — ESE 1/4 - 1/2 (0.353 mi.) — CM991 — 2771
Spill Number/Closed Date: 9911365 / 2002-09-24
Site ID: 188433
Spill Date: 1999-12-28

EXXONMOBIL — 153-169 SEVENTH AVE — ESE 1/4 - 1/2 (0.353 mi.) — CM992 — 2772
Spill Number/Closed Date: 0009966 / 2003-07-11
Site ID: 188430
Spill Date: 2000-12-04

328 WEST 12TH STREET — 328 WEST 12TH STREET — SSW 1/4 - 1/2 (0.361 mi.) — 993 — 2773
Spill Number/Closed Date: 9211532 / 1993-01-07

Site ID: 162054
Spill Date: 1993-01-07

PRIVATE RES | 160 W 16TH ST | SE 1/4 - 1/2 (0.364 mi.) | CI994 | 2774
Spill Number/Closed Date: 0404859 / 2004-08-05
Site ID: 317600
Spill Date: 2004-08-03

ELLIOTT HOUSES -NYCH | ***426 WEST 27TH ST*** | ***NNE 1/4 - 1/2 (0.368 mi.)*** | ***995*** | ***2775***
Spill Number/Closed Date: 9602200 / 2006-02-06
Spill Number/Closed Date: 9002184 / 2006-02-06
Site ID: 309346
Site ID: 246287
Spill Date: 1996-05-15
Spill Date: 1990-05-25

APRTMENT BUILDING | 161 WEST 15TH ST | SE 1/4 - 1/2 (0.387 mi.) | 1000 | 2801
Spill Number/Closed Date: 0508110 / 2006-01-31
Site ID: 353635
Spill Date: 2005-10-06

ANN'S SERVICE CORP | ***166 WEST 22ND STREET*** | ***E 1/4 - 1/2 (0.389 mi.)*** | ***1001*** | ***2803***
Spill Number/Closed Date: 9400302 / 2003-02-04
Spill Number/Closed Date: 0006798 / 2001-01-02
Site ID: 178963
Site ID: 193473
Spill Date: 1994-04-07
Spill Date: 2000-09-08

1 BANK ST/CASTLE COA | ***1 BANK STREET*** | ***SSE 1/4 - 1/2 (0.390 mi.)*** | ***CO1002*** | ***2811***
Spill Number/Closed Date: 8801019 / 1988-05-13
Site ID: 161089
Spill Date: 1988-05-02

HAG REALITY | 250 WEST 26TH ST | ENE 1/4 - 1/2 (0.391 mi.) | CJ1003 | 2814
Spill Number/Closed Date: 9813015 / 2004-05-20
Site ID: 65132
Spill Date: 1999-01-22

28TH UNDER HIGHLINE | ***505 W 27TH ST*** | ***N 1/4 - 1/2 (0.394 mi.)*** | ***CP1004*** | ***2815***
Spill Number/Closed Date: 9109614 / 2003-12-15
Site ID: 172881
Spill Date: 1991-12-10

CLOSED-LACKOF RECENT | 303 9TH AVENUE | NNE 1/4 - 1/2 (0.396 mi.) | CL1005 | 2818
Spill Number/Closed Date: 8807152 / 2003-03-05
Site ID: 67824
Spill Date: 1988-11-29

226 WEST 26TH STREET | ***226 WEST 26TH STREET*** | ***ENE 1/4 - 1/2 (0.413 mi.)*** | ***1008*** | ***2824***
Spill Number/Closed Date: 9510264 / 1995-11-16
Spill Number/Closed Date: 9510269 / 1995-11-16
Site ID: 147988
Site ID: 147989
Spill Date: 1995-11-16

10TH AVE. W 27/W 28 | ***303 10TH AVE*** | ***NNE 1/4 - 1/2 (0.414 mi.)*** | ***CP1009*** | ***2829***
Spill Number/Closed Date: 8606807 / 1987-02-05
Spill Number/Closed Date: 8605682 / 1986-12-05
Site ID: 225246
Site ID: 256335

Spill Date: 1987-02-05
Spill Date: 1986-12-04

THE DERMOT COMPANY Spill Number/Closed Date: 0801458 / 2008-12-23 Site ID: 397380 Spill Date: 2008-05-06	207-209 WEST 11TH ST	SSE 1/4 - 1/2 (0.423 mi.)	CO1012	2841
X Spill Number/Closed Date: 0301325 / 2004-10-20 Site ID: 69102 Spill Date: 2003-05-06	201 W. 11TH ST	SSE 1/4 - 1/2 (0.424 mi.)	CO1013	2843
APARTMENT BLDG.- TTF Spill Number/Closed Date: 0501089 / 2005-11-02 Site ID: 344227 Spill Date: 2005-04-26	135 W. 17TH ST.	ESE 1/4 - 1/2 (0.426 mi.)	1015	2845
SPILL NUMBER 0110039 Spill Number/Closed Date: 0110039 / 2003-04-11 Site ID: 139032 Spill Date: 2002-01-18	153 W 23RD ST	E 1/4 - 1/2 (0.442 mi.)	CT1019	2866
APARTMENT BUILDING Spill Number/Closed Date: 0500940 / 2005-04-22 Site ID: 344050 Spill Date: 2005-04-22	***148 WEST 24TH STREET***	***E 1/4 - 1/2 (0.449 mi.)***	***CT1022***	***2868***
PARKING LOT OF Spill Number/Closed Date: 9811167 / 1998-12-07 Site ID: 86623 Spill Date: 1998-12-05	515 WEST 28TH ST	N 1/4 - 1/2 (0.458 mi.)	CR1023	2871
SPILL NUMBER 0110441 Spill Number/Closed Date: 0110441 / 2002-01-31 Site ID: 66626 Spill Date: 2002-01-31	142 WEST 24TH ST	E 1/4 - 1/2 (0.458 mi.)	CT1024	2872
OLD GAS STATION Spill Number/Closed Date: 9813276 / 2002-10-24 Site ID: 116261 Spill Date: 1999-01-29	276 7TH AVE	ENE 1/4 - 1/2 (0.466 mi.)	1027	2876
UNKNOWN RESIDENCE Spill Number/Closed Date: 1506662 / 2015-11-05 Site ID: 514089 Spill Date: 2015-09-23	55 PERRY ST	S 1/4 - 1/2 (0.469 mi.)	1029	2878
APARTMENT BUILDING Spill Number/Closed Date: 9608521 / 1996-11-22 Site ID: 111829 Spill Date: 1996-10-08	347 WEST 29TH ST	NE 1/4 - 1/2 (0.484 mi.)	1032	2900
117 W 13TH ST/MANHAT Spill Number/Closed Date: 9004345 / 1995-05-25 Site ID: 73731 Spill Date: 1990-07-19	117 WEST 13TH STREET	SE 1/4 - 1/2 (0.489 mi.)	CV1034	2902
HIGH RIDGE ENTERPRIS Spill Number/Closed Date: 9008960 / 2003-03-04 Site ID: 235183 Spill Date: 1990-11-14	***524 WEST 29TH STREET***	***N 1/4 - 1/2 (0.493 mi.)***	***CW1036***	***2903***
SPOONS	***110 WEST 14TH STREET***	***SE 1/4 - 1/2 (0.494 mi.)***	***CV1037***	***2910***

Spill Number/Closed Date: 0412387 / 2005-11-08
Site ID: 337798
Spill Date: 2005-02-21

HELIPORT W 30TH ST/M — HELIPORT/W.30TH ST & — NNE 1/4 - 1/2 (0.498 mi.) — 1040 — 2917
Spill Number/Closed Date: 8903684 / 2014-10-27
Site ID: 116887
Spill Date: 1989-07-13

Lower Elevation	Address	Direction / Distance	Map ID	Page
FREEDMAN CUTOUTS Spill Number/Closed Date: 9206441 / 2000-12-21 Site ID: 235146 Spill Date: 1992-09-03	444 WEST 17TH STREET	W 0 - 1/8 (0.003 mi.)	C20	95
AUTO CARE WEST Spill Number/Closed Date: 9909074 / 2000-01-26 Site ID: 228626 Spill Date: 1999-10-26	464 WEST 18TH ST	WNW 0 - 1/8 (0.027 mi.)	G108	306
CHELSEA CAR WASH Spill Number/Closed Date: 0412142 / 2006-05-17 Site ID: 337522 Spill Date: 2005-01-13	450 W 15TH ST	WSW 0 - 1/8 (0.073 mi.)	K248	595
LEAVITT HOUSES -NYCH Spill Number/Closed Date: 9008383 / 1995-04-26 Spill Number/Closed Date: 9108997 / 2008-07-18 Site ID: 88424 Site ID: 222984 Spill Date: 1990-10-31 Spill Date: 1991-11-22	139-10 34TH AVENUE	NW 0 - 1/8 (0.080 mi.)	I264	621
152-156 TENTH AVE/MA Spill Number/Closed Date: 8903509 / 1989-08-24 Site ID: 318167 Spill Date: 1989-04-06	152-156 TENTH AVENUE	NNW 0 - 1/8 (0.081 mi.)	N265	624
GETTY 58542 Spill Number/Closed Date: 9210231 / 2004-03-10 Site ID: 141401 Spill Date: 1992-12-03	***152 TENTH AVE***	***NNW 0 - 1/8 (0.081 mi.)***	***N267***	***630***
HAMMEL Spill Number/Closed Date: 8908028 / 1992-12-08 Site ID: 313781 Spill Date: 1989-06-01	85-10 ROCKAWAY BCH B	W 0 - 1/8 (0.091 mi.)	Q312	748
178-10 69TH AVE/QUEE Spill Number/Closed Date: 8708234 / 1988-01-12 Site ID: 69350 Spill Date: 1987-12-22	178-10 69TH AVE	NNW 0 - 1/8 (0.094 mi.)	N324	777
MENDON LEASING CORP. Spill Number/Closed Date: 9514181 / 2009-03-18 Site ID: 235191 Spill Date: 1996-02-07	515 WEST 18TH STREET	NW 0 - 1/8 (0.111 mi.)	U402	978
555 WEST 17TH ST/MAN Spill Number/Closed Date: 9006677 / 1990-09-19	555 WEST 17TH STREET	WNW 0 - 1/8 (0.115 mi.)	U414	1006

Site ID: 193520 Spill Date: 1990-09-18				
NYCT HUDSON DEPOT Spill Number/Closed Date: 9106100 / 2016-01-04 Site ID: 246928 Spill Date: 1991-09-06	1101 11TH AVENUE	W 1/8 - 1/4 (0.132 mi.)	AE464	1169
HUDSON PIER DEPOT Spill Number/Closed Date: 8807870 / 1989-03-24 Site ID: 144380 Spill Date: 1988-12-28	***WEST 15TH ST & 11TH***	***W 1/8 - 1/4 (0.138 mi.)***	***AE482***	***1223***
GUARDIAN ANGEL SCHOO Spill Number/Closed Date: 9211918 / 1993-01-19 Site ID: 163796 Spill Date: 1993-01-19	***193 10TH AVE***	***N 1/8 - 1/4 (0.140 mi.)***	***AA486***	***1230***
193-10 PECK AVE Spill Number/Closed Date: 8708499 / 1992-09-30 Site ID: 69386 Spill Date: 1987-12-16	193-10 PECK AVE	N 1/8 - 1/4 (0.140 mi.)	AA488	1235
GUARDIAN ANGEL CHURC Spill Number/Closed Date: 2007298 / 2020-11-13 Site ID: 613186 Spill Date: 2020-11-13	193 10TH AVE	N 1/8 - 1/4 (0.140 mi.)	AA489	1236
MENDON Spill Number/Closed Date: 9011674 / 2004-12-23 Site ID: 133724 Spill Date: 1991-02-06	542 WEST 19TH STREET	NW 1/8 - 1/4 (0.150 mi.)	AK526	1352
501 W 14TH ST Spill Number/Closed Date: 9103563 / 2006-05-22 Site ID: 66953 Spill Date: 1991-07-01	501 W 14TH ST	WSW 1/8 - 1/4 (0.151 mi.)	AM534	1386
505 W.14TH ST Spill Number/Closed Date: 8806146 / 2006-05-01 Site ID: 130664 Spill Date: 1988-10-20	505 W.14TH ST / 10TH	WSW 1/8 - 1/4 (0.151 mi.)	AM535	1388
NEW YORK STATE DEC Spill Number/Closed Date: 9510154 / 1997-12-17 Site ID: 312315 Spill Date: 1993-06-08	***507 W 21ST ST***	***NNW 1/8 - 1/4 (0.156 mi.)***	***AG547***	***1456***
11 ELEVENTH AVENUE Spill Number/Closed Date: 9405274 / 1996-12-17 Site ID: 280857 Spill Date: 1994-07-18	11 ELEVENTH AVENUE	WSW 1/8 - 1/4 (0.158 mi.)	AM555	1498
84-11 ELMHURST AVE/Q Spill Number/Closed Date: 8907043 / 1992-12-08 Site ID: 113979 Spill Date: 1989-10-17	84-11 EILMHURST AVEN	NW 1/8 - 1/4 (0.161 mi.)	AK573	1545
84-11 ELMHURST AV/QU Spill Number/Closed Date: 9012626 / 1991-03-11 Site ID: 279195 Spill Date: 1991-03-08	84-11 ELMHURST AVENU	NW 1/8 - 1/4 (0.161 mi.)	AK574	1546
86-11 34TH AVENUE	86-11 34TH AVENUE	NW 1/8 - 1/4 (0.163 mi.)	AK575	1547

Spill Number/Closed Date: 8900634 / 2003-03-04
Site ID: 240000
Spill Date: 1989-04-20

211-10-02 73RD AVE/Q — 211-10-02 73RD AVENU — N 1/8 - 1/4 (0.176 mi.) — AG622 — 1742
Spill Number/Closed Date: 9010783 / 1991-01-09
Site ID: 123862
Spill Date: 1991-01-02

PIER 57- 11TH AVENUE — PIER 57 / 11TH AVENU — W 1/8 - 1/4 (0.178 mi.) — AE634 — 1780
Spill Number/Closed Date: 9408802 / 2000-12-27
Site ID: 257282
Spill Date: 1994-09-30

PIER 57 & HUDSON DEP — 15TH ST & ROUTE 9A — W 1/8 - 1/4 (0.178 mi.) — AE635 — 1781
Spill Number/Closed Date: 9407577 / 1998-05-07
Site ID: 62357
Spill Date: 1994-09-07

PIER 57- WESTSIDE HI — W.17TH ST WESTSIDE H — W 1/8 - 1/4 (0.178 mi.) — AE636 — 1782
Spill Number/Closed Date: 9412040 / 1994-12-09
Site ID: 117349
Spill Date: 1994-12-09

AMOCO STATION — 213-10 JAMAICA AVENU — N 1/8 - 1/4 (0.179 mi.) — AG646 — 1808
Spill Number/Closed Date: 8604698 / 1987-03-24
Site ID: 224510
Spill Date: 1986-10-21

38-52, 38-56 10TH AV — 38-52, 38-56 10TH AV — SW 1/8 - 1/4 (0.185 mi.) — AS665 — 1880
Spill Number/Closed Date: 9311497 / 1993-12-24
Site ID: 79206
Spill Date: 1993-12-24

535 EAST 21ST STREET — 535 EAST 21ST STREET — NNW 1/8 - 1/4 (0.210 mi.) — AY763 — 2173
Spill Number/Closed Date: 8803752 / 1993-02-25
Site ID: 81225
Spill Date: 1988-07-29

COMMERICAL BUILDLING — 521 WEST 23RD STREET — N 1/8 - 1/4 (0.234 mi.) — BA872 — 2461
Spill Number/Closed Date: 1010869 / 2012-11-27
Site ID: 444486
Spill Date: 2011-01-24

MARY BOONE GALLERY — 537-541 W. 24TH ST — N 1/8 - 1/4 (0.250 mi.) — BS940 — 2666
Spill Number/Closed Date: 0005393 / 2007-06-08
Site ID: 229980
Spill Date: 2000-08-05

NYC DEPT SANITATION — ***2 BLOOMFIELD ST*** — ***SW 1/4 - 1/2 (0.255 mi.)*** — ***BU942*** — ***2670***
Spill Number/Closed Date: 9505382 / 2007-07-05
Spill Number/Closed Date: 0306368 / 2003-10-20
Site ID: 302328
Site ID: 132227
Spill Date: 1995-08-01
Spill Date: 2003-09-16

FORMER GETTY SERVICE — ***239 10TH AVENUE*** — ***N 1/4 - 1/2 (0.260 mi.)*** — ***BW944*** — ***2675***
Spill Number/Closed Date: 8806159 / 1994-07-29
Site ID: 315130
Spill Date: 1988-10-20

239 10TH AVE/MANH/GE — 239 10TH AVENUE — N 1/4 - 1/2 (0.260 mi.) — BW945 — 2680

Spill Number/Closed Date: 8806160 / 1994-07-29
Spill Number/Closed Date: 9005116 / 1992-07-16
Site ID: 86009
Site ID: 86010
Spill Date: 1988-10-20
Spill Date: 1990-08-08

EDISON PARKING GARAG	527 WEST 23RD ST	N 1/4 - 1/2 (0.264 mi.)	BS947	2683
Spill Number/Closed Date: 9808740 / 2004-05-27 Site ID: 103493 Spill Date: 1998-10-14				
MENDON LEASING	***527 WEST 23RD STREET***	***N 1/4 - 1/2 (0.264 mi.)***	***BS948***	***2684***
Spill Number/Closed Date: 9513588 / 2001-02-22 Spill Number/Closed Date: 9511782 / 2004-05-27 Spill Number/Closed Date: 8605564 / 1986-12-03 Site ID: 216215 Site ID: 301889 Site ID: 301566 Spill Date: 1996-01-26 Spill Date: 1995-12-18 Spill Date: 1986-12-03				
VACANT LOT	511 WEST 24TH STREET	N 1/4 - 1/2 (0.277 mi.)	BS954	2705
Spill Number/Closed Date: 0412228 / 2005-03-16 Site ID: 337632 Spill Date: 2005-02-16				
555 WEST 23RD ST	555 WEST 23RD ST	NNW 1/4 - 1/2 (0.279 mi.)	CA957	2710
Spill Number/Closed Date: 0306399 / 2006-04-07 Site ID: 203961 Spill Date: 2003-09-17				
UHAUL INC	***562 WEST 23RD ST***	***NNW 1/4 - 1/2 (0.286 mi.)***	***CA960***	***2716***
Spill Number/Closed Date: 9000199 / 2000-06-21 Spill Number/Closed Date: 0205608 / 2002-12-10 Site ID: 313585 Site ID: 149950 Spill Date: 1990-03-26 Spill Date: 2002-08-27				
168-11 12TH AVENUE	168-11 12TH AVENUE	NNW 1/4 - 1/2 (0.289 mi.)	CB963	2723
Spill Number/Closed Date: 8803037 / 1992-09-30 Site ID: 212375 Spill Date: 1988-07-07				
RESIDENCE	92 HORATIO ST	SSW 1/4 - 1/2 (0.315 mi.)	CG973	2745
Spill Number/Closed Date: 0301865 / 2004-05-25 Site ID: 205279 Spill Date: 2003-05-21				
23RD ST & EAST RIVER	600 E.23RD ST	NNW 1/4 - 1/2 (0.322 mi.)	CB976	2749
Spill Number/Closed Date: 9506116 / 2003-04-15 Site ID: 84527 Spill Date: 1995-08-17				
GULF GAS STATION	600 E.23RD ST, E. RI	NNW 1/4 - 1/2 (0.322 mi.)	CB977	2751
Spill Number/Closed Date: 8906042 / 2006-09-11 Site ID: 283247 Spill Date: 1989-09-19				
SPILL NUMBER 0201897	543 - 545 WEST 25TH	N 1/4 - 1/2 (0.350 mi.)	CK987	2765

Spill Number/Closed Date: 0201897 / 2003-04-11
Site ID: 291496
Spill Date: 2002-05-22

514 WEST END AVENUE | 514 WEST AVENUE | SW 1/4 - 1/2 (0.372 mi.) | 996 | 2780
Spill Number/Closed Date: 9414188 / 1995-01-26
Site ID: 278357
Spill Date: 1995-01-26

PENSKE TRUCK LEASING | 536 W 26TH ST | N 1/4 - 1/2 (0.377 mi.) | CK997 | 2781
Spill Number/Closed Date: 9211726 / 1993-01-21
Site ID: 144036
Spill Date: 1993-01-13

393 WEST 12TH ST | 393 WEST 12TH ST | SSW 1/4 - 1/2 (0.400 mi.) | 1006 | 2819
Spill Number/Closed Date: 9606714 / 2007-09-10
Site ID: 236242
Spill Date: 1996-08-26

201 11TH AVE/MANH/US | 201 11TH AVENUE | NNW 1/4 - 1/2 (0.410 mi.) | 1007 | 2822
Spill Number/Closed Date: 8908706 / 2003-03-04
Spill Number/Closed Date: 9005469 / 1990-05-11
Site ID: 131667
Site ID: 131668
Spill Date: 1989-11-27
Spill Date: 1990-08-17

SUPERIOR PRINTING IN | 70 BETHUNE ST | SSW 1/4 - 1/2 (0.432 mi.) | CN1016 | 2847
Spill Number/Closed Date: 0312534 / 2004-02-23
Site ID: 292057
Spill Date: 2004-02-10

COMMERCIAL BUILDING | 260 11TH AVE | N 1/4 - 1/2 (0.441 mi.) | CS1018 | 2865
Spill Number/Closed Date: 0109855 / 2005-06-27
Site ID: 275745
Spill Date: 2002-01-09

NYC DEPT OF SANITATI | 640 WEST 26TH ST | NNW 1/4 - 1/2 (0.460 mi.) | CU1025 | 2873
Spill Number/Closed Date: 0813987 / 2009-05-22
Site ID: 411708
Spill Date: 2009-03-26

NYC SANITATION | 640 WEST 26TH STREET | NNW 1/4 - 1/2 (0.460 mi.) | CU1026 | 2874
Spill Number/Closed Date: 1410686 / Not Reported
Site ID: 504387
Spill Date: 2015-02-04

601 WEST 26TH STREET | 601 WEST 26TH STREET | NNW 1/4 - 1/2 (0.470 mi.) | CU1030 | 2879
Spill Number/Closed Date: 9100519 / 1997-10-16
Site ID: 154650
Spill Date: 1991-04-12

ELECTRICAL BUSS COMP | 601 W 26TH ST | NNW 1/4 - 1/2 (0.470 mi.) | CU1031 | 2898
Spill Number/Closed Date: 9412158 / 1994-12-12
Site ID: 120666
Spill Date: 1994-12-12

271 11TH AVE/MANHATT | 271 11TH AVE | N 1/4 - 1/2 (0.486 mi.) | CS1033 | 2901
Spill Number/Closed Date: 8710036 / 1988-12-29
Site ID: 255435
Spill Date: 1988-02-29

Lists of state and tribal registered storage tanks

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 61 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
401-411 WEST 18TH ST Database: UST, Date of Government Version: 12/16/2021	401-425 WEST 18TH ST	0 - 1/8 (0.000 mi.)	A9	49
110 NINTH AVENUE Database: UST, Date of Government Version: 12/16/2021	110 NINTH AVENUE	SE 0 - 1/8 (0.022 mi.)	F91	266
CHELSEA MARKET Database: UST, Date of Government Version: 12/16/2021	75TH NINTH AVENUE	SSW 0 - 1/8 (0.041 mi.)	J136	371
PRINCE LUMBER Database: UST, Date of Government Version: 12/16/2021	61-67 9TH AVENUE	SSW 0 - 1/8 (0.069 mi.)	J217	523
ST. PETER'S EPISCOPA Database: UST, Date of Government Version: 12/16/2021	336 WEST 20TH STREET	E 0 - 1/8 (0.076 mi.)	M256	610
FRANK J DENOIA Database: UST, Date of Government Version: 12/16/2021	335 WEST 16 ST	SSE 0 - 1/8 (0.084 mi.)	L285	672
351 WEST 14TH ST Database: UST, Date of Government Version: 12/16/2021	351 WEST 14TH STREET	S 0 - 1/8 (0.105 mi.)	S363	873
306 W. 18 REALTY LLC Database: UST, Date of Government Version: 12/16/2021	306 WEST 18TH ST	ESE 1/8 - 1/4 (0.153 mi.)	AC539	1397
304-306 WEST 21ST ST Database: UST, Date of Government Version: 12/16/2021	304-306 WEST 21ST ST	E 1/8 - 1/4 (0.158 mi.)	AH556	1499
LONDON TERRACE GARDE Database: UST, Date of Government Version: 12/16/2021	415-55 WEST 23RD STR	NNE 1/8 - 1/4 (0.186 mi.)	AX670	1890
CENTRAL RUG & CARPET Database: UST, Date of Government Version: 12/16/2021	81 8TH AVENUE	SSE 1/8 - 1/4 (0.192 mi.)	BB701	2005
M DISTRICT 2/4/5 GAR Database: UST, Date of Government Version: 12/16/2021	2 GANSEVOORT STREET	S 1/8 - 1/4 (0.208 mi.)	BE749	2139
80 8TH AVENUE Database: UST, Date of Government Version: 12/16/2021	80 EIGHTH AVENUE	SSE 1/8 - 1/4 (0.212 mi.)	BB772	2193
LOUIS PHILIPPE CONDO Database: UST, Date of Government Version: 12/16/2021	312 WEST 23RD STREET	ENE 1/8 - 1/4 (0.213 mi.)	AZ776	2203
ROSAR REALTY CORP. Database: UST, Date of Government Version: 12/16/2021	258 WEST 15TH STREET	SSE 1/8 - 1/4 (0.219 mi.)	BB804	2266
253 W 16 ST Database: UST, Date of Government Version: 12/16/2021	253 WEST 16TH STREET	SE 1/8 - 1/4 (0.219 mi.)	AT807	2273
FORMER OLYMPIA GARAG Database: UST, Date of Government Version: 12/16/2021	9-19 9TH AVENUE	SSW 1/8 - 1/4 (0.220 mi.)	BJ808	2275
LONDON TERRACE TOWER Database: UST, Date of Government Version: 12/16/2021	***420 WEST 24 STREET***	***NNE 1/8 - 1/4 (0.221 mi.)***	***BK814***	***2295***
LONDON TERRACE TOWER Database: UST, Date of Government Version: 12/16/2021	410 WEST 24 STREET	NNE 1/8 - 1/4 (0.221 mi.)	BK818	2309
CHELSEA DEVELOPMENT Database: UST, Date of Government Version: 12/16/2021	255 WEST 15TH STREET	SE 1/8 - 1/4 (0.222 mi.)	BB822	2323

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
261 WEST 21ST ST Database: UST, Date of Government Version: 12/16/2021	261 WEST 21ST STREET	E 1/8 - 1/4 (0.223 mi.)	AW825	2335
256 W 15TH ST. Database: UST, Date of Government Version: 12/16/2021	256 W 15 ST	SSE 1/8 - 1/4 (0.223 mi.)	BB829	2347
BROADMOOR APTS Database: UST, Date of Government Version: 12/16/2021	315 WEST 23RD STREET	ENE 1/8 - 1/4 (0.223 mi.)	BG830	2349
LONDON TERRACE TOWER Database: UST, Date of Government Version: 12/16/2021	***470 W 24TH ST***	***NNE 1/8 - 1/4 (0.225 mi.)***	***AX833***	***2355***
GETTY 58205 Database: UST, Date of Government Version: 12/16/2021	63 EIGHTH AVENUE	SSE 1/8 - 1/4 (0.234 mi.)	BH875	2478
236 E. 16 ST REALTY Database: UST, Date of Government Version: 12/16/2021	***236 EAST 16TH STREET***	***SE 1/8 - 1/4 (0.245 mi.)***	***BO917***	***2604***

Lower Elevation	Address	Direction / Distance	Map ID	Page
METROPOLITAN OLDSMOB Database: UST, Date of Government Version: 12/16/2021	***440 W 19TH ST***	***NNW 0 - 1/8 (0.010 mi.)***	***E47***	***149***
438 WEST 19TH STREET Database: UST, Date of Government Version: 12/16/2021	438 WEST 19TH STREET	NNW 0 - 1/8 (0.013 mi.)	E68	206
MENDON LEASING CORP Database: UST, Date of Government Version: 12/16/2021	***440 W 18TH ST***	***WNW 0 - 1/8 (0.013 mi.)***	***C73***	***217***
ALCAM PROPERTY MANAG Database: UST, Date of Government Version: 12/16/2021	435 WEST 18TH STREET	NW 0 - 1/8 (0.016 mi.)	E77	232
455 WEST 16TH STREET Database: UST, Date of Government Version: 12/16/2021	455 WEST 16TH STREET	WSW 0 - 1/8 (0.017 mi.)	C81	244
456-464 W. 18TH STRE Database: UST, Date of Government Version: 12/16/2021	456-464 W 18TH STREE	WNW 0 - 1/8 (0.022 mi.)	G93	269
FREEDMAN REALTY Database: UST, Date of Government Version: 12/16/2021	110 TENTH AVENUE	WNW 0 - 1/8 (0.049 mi.)	I156	414
430 WEST 15TH STREET Database: UST, Date of Government Version: 12/16/2021	430 WEST 15TH STREET	SW 0 - 1/8 (0.063 mi.)	K193	478
456 WEST 19TH STREET Database: UST, Date of Government Version: 12/16/2021	456 WEST 19TH STREET	NW 0 - 1/8 (0.065 mi.)	I198	487
MENDON LEASING CORP Database: UST, Date of Government Version: 12/16/2021	131 TENTH AVE	NW 0 - 1/8 (0.079 mi.)	I262	616
GETTY 58542 Database: UST, Date of Government Version: 12/16/2021	***152 TENTH AVE***	***NNW 0 - 1/8 (0.081 mi.)***	***N267***	***630***
445 WEST 21ST STREET Database: UST, Date of Government Version: 12/16/2021	445 WEST 21ST STREET	N 0 - 1/8 (0.088 mi.)	O297	694
WEST 17TH STREET DEV Database: UST, Date of Government Version: 12/16/2021	501-515 WEST 17TH ST	WNW 0 - 1/8 (0.099 mi.)	U340	833
KAMCO SUPPLY CORP. Database: UST, Date of Government Version: 12/16/2021	501 WEST 19TH STREET	NW 0 - 1/8 (0.106 mi.)	Z366	880
EMPIRE CITY SUBWAY C Database: UST, Date of Government Version: 12/16/2021	177-83 10TH AVENUE	NNW 0 - 1/8 (0.107 mi.)	AA371	906
515 W 18TH ST Database: UST, Date of Government Version: 12/16/2021	515 WEST 18TH STREET	NW 0 - 1/8 (0.111 mi.)	U403	979

Lower Elevation	Address	Direction / Distance	Map ID	Page
TENTH AVENUE CAR WAS Database: UST, Date of Government Version: 12/16/2021	461-469 WEST 14TH ST	WSW 0 - 1/8 (0.124 mi.)	W454	1131
GUARDIAN ANGEL Database: UST, Date of Government Version: 12/16/2021	193 10TH AVENUE	N 1/8 - 1/4 (0.140 mi.)	AA487	1233
WEST 19TH STREET DEV Database: UST, Date of Government Version: 12/16/2021	528 WEST 19TH STREET	NW 1/8 - 1/4 (0.143 mi.)	AK498	1284
MENDON LEASING CORP Database: UST, Date of Government Version: 12/16/2021	542 WEST 19TH ST	NW 1/8 - 1/4 (0.150 mi.)	AK527	1353
1014 GAS CORP Database: UST, Date of Government Version: 12/16/2021	501 WEST 14TH ST	WSW 1/8 - 1/4 (0.151 mi.)	AM533	1376
STORAGE USA Database: UST, Date of Government Version: 12/16/2021	510 WEST 21ST STREET	NNW 1/8 - 1/4 (0.154 mi.)	AA541	1401
THE HENRY LLOYD COMP Database: UST, Date of Government Version: 12/16/2021	507 WEST 21ST STREET	NNW 1/8 - 1/4 (0.156 mi.)	AG549	1466
535 WEST 19TH STREET Database: UST, Date of Government Version: 12/16/2021	535 WEST 19TH STREET	NW 1/8 - 1/4 (0.161 mi.)	AK570	1534
TIME WARNER CABLE OF Database: UST, Date of Government Version: 12/16/2021	511 WEST 21ST STREET	NNW 1/8 - 1/4 (0.163 mi.)	AP576	1548
GOTHAM WEST DEVELOPM Database: UST, Date of Government Version: 12/16/2021	592 11TH AVE	WSW 1/8 - 1/4 (0.170 mi.)	AM608	1704
EXXON DIV OF CFI #70 Database: UST, Date of Government Version: 12/16/2021	***215 10TH AVE & W 23R***	***N 1/8 - 1/4 (0.182 mi.)***	***AG654***	***1846***
CHELSEA OPERATING, I Database: UST, Date of Government Version: 12/16/2021	521 WEST 21ST STREET	NNW 1/8 - 1/4 (0.184 mi.)	AP658	1865
GULF SERVICE STA Database: UST, Date of Government Version: 12/16/2021	500 W 23RD ST	N 1/8 - 1/4 (0.186 mi.)	BA674	1900
BAYVIEW CORRECTIONAL Database: UST, Date of Government Version: 12/16/2021	***550 WEST 20TH ST***	***NW 1/8 - 1/4 (0.187 mi.)***	***AY679***	***1930***
BERMUDA MOTOR CAR RE Database: UST, Date of Government Version: 12/16/2021	537 WEST 20TH STREET	NW 1/8 - 1/4 (0.203 mi.)	AY730	2087
547-551 WEST 21ST ST Database: UST, Date of Government Version: 12/16/2021	547-551 WEST 21ST ST	NNW 1/8 - 1/4 (0.233 mi.)	BP863	2441
ARTISTS' CONDOMINIUM Database: UST, Date of Government Version: 12/16/2021	521 WEST 23RD STREET	N 1/8 - 1/4 (0.234 mi.)	BA870	2455
PIER 57, HUDSON RIVE Database: UST, Date of Government Version: 12/16/2021	25 ELEVENTH AVENUE	W 1/8 - 1/4 (0.239 mi.)	BT898	2566
DIA ART FOUNDATION Database: UST, Date of Government Version: 12/16/2021	***548 W 22ND ST***	***NNW 1/8 - 1/4 (0.247 mi.)***	***BN922***	***2622***

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 12/16/2021 has revealed that there are 2 NY CBS sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TENTH AVENUE CAR WAS	***450 WEST 15TH STREET***	***WSW 0 - 1/8 (0.073 mi.)***	***K251***	***601***
Facility Status: Unregulated/Closed CBS Number: 2-000497				
HUDSON PIER BUS DEPO	***11 AVE/WEST 15 STREE***	***WSW 1/8 - 1/4 (0.152 mi.)***	***AM536***	***1389***
Facility Status: Unregulated/Closed CBS Number: 2-000287				

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 119 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
THE GENERAL THEOLOGI	422 WEST 20TH STREET	N 0 - 1/8 (0.016 mi.)	E78	234
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-608842				
400 WEST 20TH STREET	400 WEST 20TH STREET	NE 0 - 1/8 (0.023 mi.)	B94	272
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-606340				
NINTH AVENUE APT COR	162 NINTH AVENUE	ENE 0 - 1/8 (0.024 mi.)	B95	274
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-244236				
365 WEST 20TH STREET	365 WEST 20TH ST.	ENE 0 - 1/8 (0.037 mi.)	B119	331
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-206644				
SP 364 W 18 LLC	364 WEST 18TH STREET	ESE 0 - 1/8 (0.039 mi.)	F121	334
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-256552				
CHELSEA MARKET	75TH NINTH AVENUE	SSW 0 - 1/8 (0.041 mi.)	J134	366
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-216674				
NY1 NEWS	75 NINTH AVE	SSW 0 - 1/8 (0.041 mi.)	J137	375
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-611943				
BAYARD RUSTIN EDUCAT	351 WEST 18TH STREET	ESE 0 - 1/8 (0.047 mi.)	H149	395
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-607209				
D S K ASSOC	352-354 W 18 ST	ESE 0 - 1/8 (0.054 mi.)	H167	431
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-063533				
350 WEST 18TH ST	350 WEST 18TH ST	ESE 0 - 1/8 (0.059 mi.)	H180	452
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-219878				
347 WEST 16 STREET L	347 WEST 16TH STREET	SSE 0 - 1/8 (0.063 mi.)	L196	484
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-605961				
345 W 16 STREET	345 WEST 16TH STREET	SSE 0 - 1/8 (0.068 mi.)	L212	516
Database: AST, Date of Government Version: 12/16/2021				

Facility Id: 2-605954				
CHELTONCORT OWNERS C Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-452491	360 WEST 21ST STREET	NE 0 - 1/8 (0.070 mi.)	P230	557
CHELSEA CONDOMINIUMS Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-608020	62-66 NINTH AVENUE	S 0 - 1/8 (0.072 mi.)	J240	576
342 WEST 21ST STREET Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-207160	342 WEST 21ST STREET	ENE 0 - 1/8 (0.081 mi.)	R269	640
338 WEST 17 LLC Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-603665	338 WEST 17TH STREET	SE 0 - 1/8 (0.082 mi.)	L273	651
CHELSEA MANOR Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-311375	421 WEST 21ST STREET	NNE 0 - 1/8 (0.083 mi.)	O279	661
433 W. 21 STREET Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-608134	433 WEST 21ST STREET	NNE 0 - 1/8 (0.084 mi.)	O288	683
CON EDISON Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-398829	***48 9TH AVE***	***S 0 - 1/8 (0.091 mi.)***	***S299***	***700***
ROTA HOLDING CORP Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-398810	335 W 19 STREET	E 0 - 1/8 (0.093 mi.)	M315	755
I.S. 70 - MANHATTAN Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-353914	333 WEST 17TH STREET	SE 0 - 1/8 (0.096 mi.)	T332	809
351 WEST 14TH ST Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-605606	351 WEST 14TH STREET	S 0 - 1/8 (0.105 mi.)	S365	878
325 WEST 16TH STREET Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-047481	325 WEST 16TH STREET	SSE 0 - 1/8 (0.108 mi.)	T372	907
324 W 17 ST Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-470139	324 WEST 17TH STREET	SE 0 - 1/8 (0.115 mi.)	T417	1010
319 WEST 18TH ST. OW Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-257834	319 WEST 18TH STREET	ESE 0 - 1/8 (0.115 mi.)	AC418	1012
335-7 WEST 14TH STRE Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-090654	335-7 WEST 14TH STRE	S 0 - 1/8 (0.116 mi.)	X424	1021
CHELSEA 19TH ST. OWN Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-189421	320 WEST 19TH STREET	ESE 0 - 1/8 (0.118 mi.)	Y428	1029
PUBLIC SCHOOL 11 - M Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-604515	320 WEST 21ST STREET	ENE 0 - 1/8 (0.118 mi.)	R429	1031
328 W 15TH OWNER COR Database: AST, Date of Government Version: 12/16/2021	328 W 15TH ST	SSE 0 - 1/8 (0.125 mi.)	X458	1141

Facility Id: 2-241563				
342 W 14 ST Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-106895	342 WEST 14TH STREET	S 1/8 - 1/4 (0.132 mi.)	X465	1177
THE 305 CONDOMINIUM Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-091219	305 WEST 18TH STREET	ESE 1/8 - 1/4 (0.142 mi.)	AC497	1282
301-303 WEST 21ST ST Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-294934	301-303 WEST 21ST ST	ENE 1/8 - 1/4 (0.143 mi.)	AH500	1298
ISMO, LLC Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-318604	315 WEST 21ST STREET	ENE 1/8 - 1/4 (0.147 mi.)	AH512	1322
29-35 NINTH AVE (AT Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-248436	29-35 NINTH AVENUE	SSW 1/8 - 1/4 (0.148 mi.)	AD514	1329
312-316 WEST 15TH ST Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-081043	312-316 WEST 15TH ST	SSE 1/8 - 1/4 (0.153 mi.)	AI540	1399
311 WEST 21ST STREET Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-085871	311 WEST 21ST STREET	ENE 1/8 - 1/4 (0.158 mi.)	AH552	1479
WEST 23RD STREET OWN Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-147222	410 W 23RD ST	NNE 1/8 - 1/4 (0.160 mi.)	AF563	1521
309 WEST 14TH STREET Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-159182	309 WEST 14TH STREET	SSE 1/8 - 1/4 (0.163 mi.)	AI579	1601
350 WEST 23RD, LLC Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-610490	350 WEST 23RD STREET	NE 1/8 - 1/4 (0.166 mi.)	AO583	1609
JOYCE THEATER Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-205036	171-175 8TH AVENUE	ESE 1/8 - 1/4 (0.167 mi.)	AN587	1621
MANHATTAN ASSOCIATES Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-274992	301-317 WEST 19TH ST	ESE 1/8 - 1/4 (0.170 mi.)	AN590	1630
SPRINT COMMUNICATION Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-604532	111 EIGHTH AVENUE	SE 1/8 - 1/4 (0.170 mi.)	AT597	1657
ONE CITY BLOCK, LLC Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-601905	111 8TH AVE	SE 1/8 - 1/4 (0.170 mi.)	AT599	1663
304-10 W. 14 REALTY Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-110701	310 W 14TH STREET	S 1/8 - 1/4 (0.176 mi.)	AQ627	1754
300 WEST 21ST STREET Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-046892	300 WEST 21ST STREET	E 1/8 - 1/4 (0.177 mi.)	AW629	1760
C D O REALTY CORP Database: AST, Date of Government Version: 12/16/2021	301 W 154 ST	SSE 1/8 - 1/4 (0.177 mi.)	AI630	1762

Facility Id: 2-202673				
ST BERNARD SCHOOL Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-155640	327 WEST 13TH STREET	S 1/8 - 1/4 (0.177 mi.)	AJ631	1765
85 EIGHT AVENUE OWNE Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-242810	85 EIGHTH AVENUE	SSE 1/8 - 1/4 (0.183 mi.)	AI656	1858
LONDON TERRACE GARDE Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-608055	435 WEST 23RD STREET	NNE 1/8 - 1/4 (0.185 mi.)	AX666	1881
GERMAN EV LUTHERAN C Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-258334	315 WEST 22ND STREET	ENE 1/8 - 1/4 (0.186 mi.)	AO669	1888
ALLERTON HOTEL Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-091642	302 WEST 22ND STREET	ENE 1/8 - 1/4 (0.186 mi.)	AZ673	1898
RAYMAX ASSOC Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-148016	114 EIGHTH AVENUE	SE 1/8 - 1/4 (0.189 mi.)	AT689	1959
RAYMAX ASSOCIATES Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-148008	106 EIGHTH AVENUE	SE 1/8 - 1/4 (0.189 mi.)	AT690	1961
ST FRANCIS RESIDENCE Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-328804	148 8TH AVE	SE 1/8 - 1/4 (0.190 mi.)	AL691	1964
GANSEVOORT COOPERATI Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-098620	652 HUDSON STREET	S 1/8 - 1/4 (0.191 mi.)	BC692	1966
170 8TH AVE. Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-085901	170 8TH AVE.	ESE 1/8 - 1/4 (0.192 mi.)	AN699	1993
305 W 13 ST Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-267953	305 WEST 13TH STREET	S 1/8 - 1/4 (0.202 mi.)	AQ728	2083
301 WEST 22ND ST Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-046906	301 WEST 22ND ST	ENE 1/8 - 1/4 (0.205 mi.)	AZ738	2106
THE GRAND CHELSEA CO Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-600846	270 WEST 17TH STREET	SE 1/8 - 1/4 (0.206 mi.)	AT739	2108
M DISTRICT 2/4/5 GAR Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-455768	2 GANSEVOORT STREET	S 1/8 - 1/4 (0.208 mi.)	BE748	2131
80 8TH AVENUE Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-111953	80 EIGHTH AVENUE	SSE 1/8 - 1/4 (0.212 mi.)	BB773	2195
224 EIGHTH AVE CORP Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-256900	224 8TH AVENUE	E 1/8 - 1/4 (0.213 mi.)	AW780	2211
250 WEST 16TH STREET Database: AST, Date of Government Version: 12/16/2021	250 WEST 16TH STREET	SE 1/8 - 1/4 (0.213 mi.)	AT781	2214

Facility Id: 2-147168

NYC DEPT OF EDUCATIO	***250 W 18TH ST***	***ESE 1/8 - 1/4 (0.216 mi.)***	***BF800***	***2255***
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-238597				
ENS/21 LLC	264/268 WEST 21ST ST	E 1/8 - 1/4 (0.217 mi.)	AW802	2261
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-604504				
EIGHTH-19TH COMPANY	259-265 WEST 19TH ST	ESE 1/8 - 1/4 (0.217 mi.)	BD803	2263
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-096121				
257 W 17TH ST	257 W 17TH ST	SE 1/8 - 1/4 (0.220 mi.)	BF809	2281
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-321958				
LONDON TERRACE TOWER	***420 WEST 24 STREET***	***NNE 1/8 - 1/4 (0.221 mi.)***	***BK814***	***2295***
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-600237				
LONDON TERRACE TOWER	410 WEST 24 STREET	NNE 1/8 - 1/4 (0.221 mi.)	BK817	2307
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-365696				
245-259 W 20 ST	251 W 20 ST	E 1/8 - 1/4 (0.222 mi.)	BD821	2321
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-258091				
261 WEST 21ST STREET	261 WEST 21ST STREET	E 1/8 - 1/4 (0.223 mi.)	AW824	2333
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-508942				
300 WEST 23RD STREET	300 WEST 23RD STREET	ENE 1/8 - 1/4 (0.223 mi.)	AZ831	2351
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-311286				
LONDON TERRACE TOWER	***470 W 24TH ST***	***NNE 1/8 - 1/4 (0.225 mi.)***	***AX833***	***2355***
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-365688				
246 WEST 18 ST	246 WEST 18 STREET	ESE 1/8 - 1/4 (0.225 mi.)	BF834	2371
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-197742				
UNITED CHELSEA LLC	264 WEST 19TH STREET	ESE 1/8 - 1/4 (0.229 mi.)	BI851	2410
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-194638				
320 WEST 13TH ST	320 WEST 13TH STREET	S 1/8 - 1/4 (0.230 mi.)	BE852	2412
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-043990				
244 WEST 16TH STREET	244 WEST 16TH STREET	SE 1/8 - 1/4 (0.231 mi.)	BO857	2427
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-608458				
250 W. 15TH ST OWNER	250 WEST 15TH STREET	SSE 1/8 - 1/4 (0.231 mi.)	BB860	2433
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-093173				
CON EDISON	***248 W 17TH ST***	***SE 1/8 - 1/4 (0.232 mi.)***	***BF861***	***2435***
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-207942				
GOLDEN EQUITIES CORP	401 WEST 24TH STREET	NE 1/8 - 1/4 (0.234 mi.)	BK880	2487
Database: AST, Date of Government Version: 12/16/2021				

Facility Id: 2-108928

264 WEST 22ND STREET | 264 WEST 22ND STREET | E 1/8 - 1/4 (0.235 mi.) | BQ882 | 2494
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-247227

345 W. 4TH-306 W. 13 | 345 W 4 STREET | S 1/8 - 1/4 (0.236 mi.) | BE883 | 2497
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-373419

CHELSEA 19 CONDOMINI | 251 WEST 19TH STREET | ESE 1/8 - 1/4 (0.237 mi.) | BD884 | 2499
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-332372
Facility Id: 2-510572

SILVERBOW REALTY CO | 415 WEST 24TH ST | NNE 1/8 - 1/4 (0.237 mi.) | BK888 | 2510
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-109142

262 WEST 22ND ST/MAN | 262 WEST 22ND ST | E 1/8 - 1/4 (0.240 mi.) | BQ900 | 2570
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-401234

641 HUDSON STREET | 641 HUDSON STREET | SSW 1/8 - 1/4 (0.241 mi.) | BV908 | 2588
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-607300

238 W 20 STREET | 238 WEST 20TH STREET | ESE 1/8 - 1/4 (0.241 mi.) | BD909 | 2590
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-108766

251 WEST 14 ST | 251 WEST 14TH STREET | SSE 1/8 - 1/4 (0.242 mi.) | BH910 | 2592
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-246816

236 WEST 16 STREET | 236 WEST 16TH STREET | SE 1/8 - 1/4 (0.245 mi.) | BO918 | 2609
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-607115

250 W 19TH STREET | 250 WEST 19TH STREET | ESE 1/8 - 1/4 (0.245 mi.) | BI919 | 2611
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-600027

243 WEST 17TH STREET | 243 WEST 17TH STREET | SE 1/8 - 1/4 (0.247 mi.) | BF924 | 2628
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-281255

237 REALTY NY LLC | 237 WEST 18TH STREET | ESE 1/8 - 1/4 (0.248 mi.) | BI936 | 2655
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-097470

Lower Elevation	Address	Direction / Distance	Map ID	Page

VERIZON NEW YORK INC | 438-454 WEST 18TH ST | WNW 0 - 1/8 (0.009 mi.) | C45 | 141
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-608026

THE CALEDONIA | 450 WEST 17TH STREET | W 0 - 1/8 (0.021 mi.) | C87 | 259
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-611055

458 WEST 20TH ST | 458 WEST 20TH STREET | NNW 0 - 1/8 (0.060 mi.) | N184 | 461
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-258040

TENTH AVENUE CAR WAS | 450 WEST 15TH STREET | WSW 0 - 1/8 (0.073 mi.) | K243 | 581
Database: AST, Date of Government Version: 12/16/2021

Facility Id: 2-000497

RP STELLAR MILK LLC | 450 WEST 15 STREET | WSW 0 - 1/8 (0.073 mi.) | K247 | 592
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-403938

RELATED MANAGEMENT | 85 TENTH AVENUE | W 0 - 1/8 (0.091 mi.) | Q311 | 744
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-216682

DEA | 99 10TH AVE. | W 0 - 1/8 (0.095 mi.) | Q327 | 795
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-613110

KAMCO SUPPLY CORP. | 501 WEST 19TH STREET | NW 0 - 1/8 (0.106 mi.) | Z368 | 897
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-610897

EMPIRE CITY SUBWAY C | 177-83 10TH AVENUE | NNW 0 - 1/8 (0.107 mi.) | AA370 | 905
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-604451

LOMEL REALTY CORP | 418 WEST 14TH ST | SW 0 - 1/8 (0.121 mi.) | AD446 | 1090
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-098604

TENTH AVENUE CAR WAS | 461-469 WEST 14TH ST | WSW 0 - 1/8 (0.124 mi.) | W451 | 1103
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-604379

IAC BUILDING | 555 WEST 18TH STREET | NW 1/8 - 1/4 (0.144 mi.) | AK504 | 1304
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-611018

WESTSIDE AUTO CARE I | 521 WEST 19TH STREET | NW 1/8 - 1/4 (0.146 mi.) | Z509 | 1316
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-603038

513 WEST 20TH STREET | 513 WEST 20TH STREET | NNW 1/8 - 1/4 (0.147 mi.) | AA511 | 1319
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-611302

HUDSON PIER BUS DEPO | 11 AVE/WEST 15 STREE | WSW 1/8 - 1/4 (0.152 mi.) | AM536 | 1389
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-000287

TIME WARNER CABLE | 511 WEST 21ST ST | NNW 1/8 - 1/4 (0.163 mi.) | AP577 | 1552
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-285919

SUNOCO STATION (VACA | 14TH STREET & WEST S | WSW 1/8 - 1/4 (0.170 mi.) | AM591 | 1632
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-603197

505 W 22ND STREET | 505 W 22ND STREET | N 1/8 - 1/4 (0.175 mi.) | AG620 | 1737
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-611981

GREENWAY MEWS REALTY | 416 WEST 13TH STREET | SSW 1/8 - 1/4 (0.176 mi.) | AV625 | 1747
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-608304

529 WEST 20TH ST LLC | 529 WEST 20TH STREET | NNW 1/8 - 1/4 (0.184 mi.) | AY662 | 1875
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 2-611117

BAYVIEW CORRECTIONAL | 550 WEST 20TH ST | NW 1/8 - 1/4 (0.187 mi.) | AY679 | 1930
Database: AST, Date of Government Version: 12/16/2021

Facility Id: 2-399515

MARAJS	520 WEST 23RD STREET	N 1/8 - 1/4 (0.213 mi.)	BA784	2218
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-609043				
SYLVOR COMPANY	120-126 11TH AVENUE	NW 1/8 - 1/4 (0.221 mi.)	AY812	2289
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-349208				
570-578 WEST 193RD S	570-578 WEST 193TH S	SW 1/8 - 1/4 (0.233 mi.)	BL862	2439
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-601628				
HUDSON DEPOT	***11TH AVE & 15TH ST***	***W 1/8 - 1/4 (0.239 mi.)***	***BT896***	***2552***
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-190284				
571-573 WEST 159 STR	571-573 WEST 159 STR	SW 1/8 - 1/4 (0.240 mi.)	BU904	2579
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-607292				
DIA ART FOUNDATION	***548 W 22ND ST***	***NNW 1/8 - 1/4 (0.247 mi.)***	***BN922***	***2622***
Database: AST, Date of Government Version: 12/16/2021 Facility Id: 2-272256				

NY CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY CBS AST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
HUDSON PIER BUS DEPO	***11 AVE/WEST 15 STREE***	***WSW 1/8 - 1/4 (0.152 mi.)***	***AM536***	***1389***
Facility Status: 1 Facility Status: 1 CBS Number: 2-000287				

NY TANKS: This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

A review of the NY TANKS list, as provided by EDR, has revealed that there is 1 NY TANKS site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
310 WEST 18TH STREET	***310 WEST 18TH STREET***	***ESE 1/8 - 1/4 (0.144 mi.)***	***AC505***	***1307***
Database: TANKS, Date of Government Version: 12/16/2021 Facility Id: 2-610670 Site Status: Inactive				

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: Environmental Remediation sites that have engineering controls in place.

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 01/06/2022 has revealed that there are 4 NY ENG CONTROLS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
WEST 17TH STREET AND Site Code: 59118	***440-452 WEST 17TH ST***	***0 - 1/8 (0.000 mi.)***	***C13***	***61***
17TH STREET DEVELOPM Site Code: 58929	***76 11TH AVENUE***	***NW 1/8 - 1/4 (0.155 mi.)***	***AK544***	***1410***
19TH STREET DEVELOPM Site Code: 57373	***80 11TH AVENUE***	***NW 1/8 - 1/4 (0.158 mi.)***	***AK554***	***1482***
TIME WARNER CABLE Site Code: 475372	***511 WEST 21ST ST***	***NNW 1/8 - 1/4 (0.163 mi.)***	***AP577***	***1552***

Environmental Remediation sites that have institutional controls in place.

A review of the NY INST CONTROL list, as provided by EDR, and dated 01/06/2022 has revealed that there are 4 NY INST CONTROL sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
WEST 17TH STREET AND Site Code: 59118	***440-452 WEST 17TH ST***	***0 - 1/8 (0.000 mi.)***	***C13***	***61***
17TH STREET DEVELOPM Site Code: 58929	***76 11TH AVENUE***	***NW 1/8 - 1/4 (0.155 mi.)***	***AK544***	***1410***
19TH STREET DEVELOPM Site Code: 57373	***80 11TH AVENUE***	***NW 1/8 - 1/4 (0.158 mi.)***	***AK554***	***1482***
TIME WARNER CABLE Site Code: 475372	***511 WEST 21ST ST***	***NNW 1/8 - 1/4 (0.163 mi.)***	***AP577***	***1552***

Lists of state and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, has revealed that there are 20 NY VCP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
260 WEST 26TH STREET Database: VCP NYC, Date of Government Version: 12/06/2021	260 WEST 26TH STREET	ENE 1/4 - 1/2 (0.380 mi.)	CJ998	2800
311 10TH AVENUE Database: VCP NYC, Date of Government Version: 12/06/2021	311 10TH AVENUE	NNE 1/4 - 1/2 (0.426 mi.)	CP1014	2845
507-515 WEST 28TH ST Database: VCP NYC, Date of Government Version: 12/06/2021	507 WEST 28TH STREET	N 1/4 - 1/2 (0.447 mi.)	CR1021	2867

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
522-532 WEST 29TH ST Database: VCP NYC, Date of Government Version: 12/06/2021	522 WEST 29TH STREET	N 1/4 - 1/2 (0.490 mi.)	CW1035	2903

Lower Elevation	Address	Direction / Distance	Map ID	Page
118 10TH AVENUE Database: VCP NYC, Date of Government Version: 12/06/2021	118 10TH AVENUE	WNW 0 - 1/8 (0.040 mi.)	I125	345
19TH STREET DEVELOPM Database: VCP, Date of Government Version: 01/06/2022 Site Code: 57143	***80 11TH AVENUE***	***NW 1/8 - 1/4 (0.158 mi.)***	***AK554***	***1482***
42-46 10TH AVENUE Database: VCP NYC, Date of Government Version: 12/06/2021	42 10TH AVENUE	WSW 1/8 - 1/4 (0.179 mi.)	AS642	1798
CE - W. 18TH ST. GAS Database: VCP, Date of Government Version: 01/06/2022 Site Code: 57083	WEST 16TH - WEST 20T	NW 1/8 - 1/4 (0.193 mi.)	AK707	2040
540 WEST 21ST STREET Database: VCP NYC, Date of Government Version: 12/06/2021	540 WEST 21ST STREET	NNW 1/8 - 1/4 (0.207 mi.)	AY744	2124
551 WEST 21ST STREET Database: VCP NYC, Date of Government Version: 12/06/2021	551 WEST 21ST STREET	NNW 1/8 - 1/4 (0.233 mi.)	BP868	2450
508 WEST 24TH STREET Database: VCP NYC, Date of Government Version: 12/06/2021	508 WEST 24TH STREET	N 1/4 - 1/2 (0.251 mi.)	BS941	2669
514 WEST 24TH STREET Database: VCP NYC, Date of Government Version: 12/06/2021	514 WEST 24TH STREET	N 1/4 - 1/2 (0.260 mi.)	BS943	2675
239 10TH AVENUE Database: VCP NYC, Date of Government Version: 12/06/2021	239 10TH AVENUE	N 1/4 - 1/2 (0.260 mi.)	BW946	2682
507 WEST 24TH STREET Database: VCP NYC, Date of Government Version: 12/06/2021	507 WEST 24TH STREET	N 1/4 - 1/2 (0.270 mi.)	BW953	2705
500 WEST 25TH STREET Database: VCP NYC, Date of Government Version: 12/06/2021	500 WEST 25TH STREET	N 1/4 - 1/2 (0.287 mi.)	BW961	2719
186-188 11TH AVENUE Database: VCP NYC, Date of Government Version: 12/06/2021	186 11TH AVENUE	NNW 1/4 - 1/2 (0.310 mi.)	CA972	2745
85-89 JANE STREET Database: VCP NYC, Date of Government Version: 12/06/2021	89 JANE STREET	SSW 1/4 - 1/2 (0.327 mi.)	CG980	2754
771 WASHINGTON STREE Database: VCP NYC, Date of Government Version: 12/06/2021	771 WASHINGTON STREE	SSW 1/4 - 1/2 (0.386 mi.)	CN999	2800
526-532 WEST 28TH ST Database: VCP NYC, Date of Government Version: 12/06/2021	526 WEST 28TH STREET	N 1/4 - 1/2 (0.443 mi.)	CR1020	2867
534 WEST 29TH STREET Database: VCP NYC, Date of Government Version: 12/06/2021	534 WEST 29TH STREET	N 1/4 - 1/2 (0.496 mi.)	CW1039	2917

Lists of state and tribal brownfield sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 01/06/2022 has revealed that there

are 12 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
514-520 WEST 28TH ST Site Code: 477443	514-520 WEST 28TH ST	N 1/4 - 1/2 (0.439 mi.)	CR1017	2861
241 WEST 28TH STREET Site Code: 592785	241 WEST 28TH STREET	ENE 1/4 - 1/2 (0.495 mi.)	1038	2913

Lower Elevation	Address	Direction / Distance	Map ID	Page
WEST 17TH STREET AND Site Code: 59118	***440-452 WEST 17TH ST***	***0 - 1/8 (0.000 mi.)***	***C13***	***61***
515 WEST 18TH STREET Site Code: 506209	511 WEST 18TH STREET	NW 0 - 1/8 (0.109 mi.)	U385	930
17TH STREET DEVELOPM Site Code: 58929	***76 11TH AVENUE***	***NW 1/8 - 1/4 (0.155 mi.)***	***AK544***	***1410***
19TH STREET DEVELOPM Site Code: 57373	***80 11TH AVENUE***	***NW 1/8 - 1/4 (0.158 mi.)***	***AK554***	***1482***
535 WEST 19TH STREET Site Code: 370424	***535 WEST 19TH STREET***	***NW 1/8 - 1/4 (0.161 mi.)***	***AK571***	***1538***
TIME WARNER CABLE Site Code: 475372	***511 WEST 21ST ST***	***NNW 1/8 - 1/4 (0.163 mi.)***	***AP577***	***1552***
FORMER GETTY SERVICE Site Code: 488150	***239 10TH AVENUE***	***N 1/4 - 1/2 (0.260 mi.)***	***BW944***	***2675***
555 WEST 22ND STREET Site Code: 525716	555 WEST 22ND STREET	NNW 1/4 - 1/2 (0.267 mi.)	BN952	2701
SUPERIOR PRINTING IN Site Code: 373205	***70 BETHUNE ST***	***SSW 1/4 - 1/2 (0.432 mi.)***	***CN1016***	***2847***
542 WEST 29TH STREET Site Code: 588955	538-542 WEST 29TH ST	N 1/4 - 1/2 (0.499 mi.)	CW1041	2919

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: The EPA's listing of Brownfields properties from the Cleanups in My Community program, which provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

A review of the US BROWNFIELDS list, as provided by EDR, and dated 02/23/2022 has revealed that there is 1 US BROWNFIELDS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HIGH LINE ACRES property ID: 90521 Cleanup Completion Date: - Cleanup Completion Date: 10/23/2008	GANSEVOORT STREET TO	SE 1/8 - 1/4 (0.140 mi.)	T490	1237

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 03/15/2022 has revealed that there are 92 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
EXCAVATION SITE Spill Number/Closed Date: 0501928 / 2005-12-27 Site ID: 346188 Spill Date: 2005-05-17	FRONT OF 413 W. 16TH	0 - 1/8 (0.000 mi.)	D16	91
157-21 9TH AVE/QUEEN Spill Number/Closed Date: 8900505 / 2003-02-10 Site ID: 243994 Spill Date: 1989-04-17	157021 9TH AVENUE	NE 0 - 1/8 (0.003 mi.)	B19	94
BASEMENT Spill Number/Closed Date: 1500497 / 2015-06-04 Site ID: 506653 Spill Date: 2015-04-15	435 WEST 19TH ST	N 0 - 1/8 (0.004 mi.)	E21	96
CON ED ROADSIDE Spill Number/Closed Date: 0900837 / 2009-06-03 Site ID: 412795 Spill Date: 2009-04-22	WEST 19TH STREET/ AN	ENE 0 - 1/8 (0.009 mi.)	B40	133
188TH STREET AND Spill Number/Closed Date: 0207606 / 2002-12-23 Site ID: 104941 Spill Date: 2002-10-22	188TH ST & COLUMBUS	ESE 0 - 1/8 (0.010 mi.)	A49	156
SPILL NUMBER 9912769 Spill Number/Closed Date: 9912769 / 2003-07-29 Site ID: 79724 Spill Date: 2000-02-09	414 W 20TH ST	NNE 0 - 1/8 (0.012 mi.)	B63	200
SPILL NUMBER 0111849 Spill Number/Closed Date: 0111849 / 2003-12-10 Site ID: 269103 Spill Date: 2002-03-15	414 WEST 20TH STREET	NNE 0 - 1/8 (0.012 mi.)	B64	201
414 W. 20TH ST Spill Number/Closed Date: 0313042 / 2004-02-27 Site ID: 246511 Spill Date: 2004-02-26	414 WEST 20TH ST	NNE 0 - 1/8 (0.012 mi.)	B65	202
SPILL NUMBER 0111434 Spill Number/Closed Date: 0111434 / 2003-12-10 Site ID: 268536 Spill Date: 2002-03-04	416 W. 20TH ST	NNE 0 - 1/8 (0.012 mi.)	E66	204
WEST 20TH ST & 9TH A Spill Number/Closed Date: 9309450 / 2010-09-01 Site ID: 160295 Spill Date: 1993-11-04	WEST 20TH ST / 9TH A	NE 0 - 1/8 (0.026 mi.)	B107	305
MANHOLE #57478	359 WEST 18 STREET	ESE 0 - 1/8 (0.032 mi.)	H113	318

Spill Number/Closed Date: 0508731 / 2007-05-03 Site ID: 354374 Spill Date: 2005-10-21				
SPILL NUMBER 0013164 Spill Number/Closed Date: 0013164 / 2003-06-09 Site ID: 179743 Spill Date: 2001-03-16	364 WEST 19TH ST	E 0 - 1/8 (0.036 mi.)	B118	330
LAWRENCE ENVIRONMENT Spill Number/Closed Date: 0905371 / 2009-08-10 Site ID: 417633 Spill Date: 2009-08-07	***364 WEST 18TH STREET***	***ESE 0 - 1/8 (0.039 mi.)***	***F122***	***336***
OXYGEN MEDIA Spill Number/Closed Date: 1411925 / Not Reported Site ID: 505730 Spill Date: 2015-03-20	***75 9TH AVENUE***	***SSW 0 - 1/8 (0.041 mi.)***	***J133***	***360***
VAULT 0505 Spill Number/Closed Date: 0012059 / 2003-06-23 Site ID: 65355 Spill Date: 2001-02-09	69 9TH AVE	SSW 0 - 1/8 (0.053 mi.)	J162	423
MANHOLE # UNK Spill Number/Closed Date: 0006310 / 2001-12-18 Site ID: 263846 Spill Date: 2000-08-28	IFO 346 W 17TH ST	SSE 0 - 1/8 (0.053 mi.)	F165	429
9TH AVE & 15TH ST Spill Number/Closed Date: 9503308 / 2003-08-11 Site ID: 143861 Spill Date: 1995-06-16	9TH AVE & 15TH ST	SSW 0 - 1/8 (0.054 mi.)	J166	430
VAULT 8126 Spill Number/Closed Date: 9905335 / 1999-11-05 Site ID: 129824 Spill Date: 1999-08-03	335 W. 18TH ST	ESE 0 - 1/8 (0.059 mi.)	H178	449
RESIDENCE/APARTMENT Spill Number/Closed Date: 1306529 / 2013-09-24 Site ID: 487151 Spill Date: 2013-09-21	347 WEST 16TH ST	SSE 0 - 1/8 (0.063 mi.)	L195	483
408 W 15TH ST/MANHAT Spill Number/Closed Date: 9004861 / 1990-08-01 Site ID: 170999 Spill Date: 1990-08-01	408 WEST 15TH STREET	SSW 0 - 1/8 (0.066 mi.)	K205	504
PRINCE LUMBER COMPAN Spill Number/Closed Date: 0208837 / 2004-06-15 Site ID: 241295 Spill Date: 2002-11-26	404 WEST 15TH STREET	SSW 0 - 1/8 (0.066 mi.)	J206	505
345-347 WEST 16TH ST Spill Number/Closed Date: 0207660 / 2005-04-29 Site ID: 196262 Spill Date: 2002-04-01	345-347 W 16TH ST	SSE 0 - 1/8 (0.068 mi.)	L214	520
216617; 404 15 ST AN Spill Number/Closed Date: 0914186 / 2009-05-16 Site ID: 432979 Spill Date: 2009-04-29	404 15 ST AND 7 AVE	SSW 0 - 1/8 (0.069 mi.)	J216	522
FORMER PRINCE LUMBER	61-67 9TH AVE	SSW 0 - 1/8 (0.069 mi.)	J221	534

Spill Number/Closed Date: 1606101 / 2017-03-23
Site ID: 532698
Spill Date: 2016-09-19

SOIL	61-67 9TH AVE	SSW 0 - 1/8 (0.069 mi.)	J222	539
Spill Number/Closed Date: 1407795 / 2015-03-26 Site ID: 501325 Spill Date: 2014-10-26				
364 W. 15TH ST	364 W. 15TH ST	S 0 - 1/8 (0.072 mi.)	J237	572
Spill Number/Closed Date: 9408540 / 1994-09-27 Site ID: 191286 Spill Date: 1994-09-01				
MANHOLE #3794	WEST 21ST ST & 9TH A	NE 0 - 1/8 (0.072 mi.)	P241	578
Spill Number/Closed Date: 9810284 / 2003-11-04 Site ID: 268236 Spill Date: 1998-11-14				
CONSTR SITE	336 WEST 20TH ST	E 0 - 1/8 (0.076 mi.)	M257	612
Spill Number/Closed Date: 1810742 / 2019-01-25 Site ID: 581649 Spill Date: 2019-01-23				
VAULT 5311	W 14TH ST/9TH AVE	SSW 0 - 1/8 (0.079 mi.)	J263	620
Spill Number/Closed Date: 9913020 / 2002-02-27 Site ID: 74930 Spill Date: 2000-02-15				
OLD HOMESTEAD REST	56 NINTH AVE	S 0 - 1/8 (0.082 mi.)	J276	656
Spill Number/Closed Date: 9707247 / 2005-12-21 Site ID: 138619 Spill Date: 1997-09-18				
BTWN 8TH & 9TH AVE	335 WEST 16TH ST	SSE 0 - 1/8 (0.084 mi.)	L284	670
Spill Number/Closed Date: 9901094 / 2005-10-06 Site ID: 64133 Spill Date: 1999-04-28				
TEN GAL XFMR OIL IN	340 W 21 STREET	ENE 0 - 1/8 (0.085 mi.)	R291	687
Spill Number/Closed Date: 0704215 / 2007-08-20 Site ID: 384313 Spill Date: 2007-07-14				
CON EDISON	***48 9TH AVE***	***S 0 - 1/8 (0.091 mi.)***	***S299***	***700***
Spill Number/Closed Date: 0814530 / 2008-10-15 Site ID: 432682 Spill Date: 2008-10-12				
BROWNSTONE	351 WEST 21ST STREET	NE 0 - 1/8 (0.092 mi.)	P314	754
Spill Number/Closed Date: 0800648 / 2009-12-23 Site ID: 396431 Spill Date: 2008-04-16				
351-355 W 14TH ST	351-355 W 14TH ST	S 0 - 1/8 (0.105 mi.)	S364	875
Spill Number/Closed Date: 0009297 / 2009-03-12 Site ID: 257095 Spill Date: 2000-11-13				
SPILL NUMBER 0104249	360 WEST 22ND ST	NE 0 - 1/8 (0.113 mi.)	AB407	989
Spill Number/Closed Date: 0104249 / 2001-08-07 Site ID: 129261 Spill Date: 2001-07-01				
APARTMENT	335 WEST 14TH ST	S 0 - 1/8 (0.116 mi.)	X423	1020

Spill Number/Closed Date: 0401258 / 2004-05-06
Site ID: 183989
Spill Date: 2004-05-05

SUZUKI RESIDENCE — 328 WEST 15TH ST — SSE 0 - 1/8 (0.125 mi.) — X459 — 1143
Spill Number/Closed Date: 9701821 / 1998-10-01
Site ID: 106725
Spill Date: 1997-05-12

Lower Elevation	Address	Direction / Distance	Map ID	Page
VERIZON Spill Number/Closed Date: 0103363 / 2015-04-15 Site ID: 233558 Spill Date: 2001-06-27	438 WEST 18TH ST	WNW 0 - 1/8 (0.009 mi.)	C46	142
SPILL NUMBER 0012292 Spill Number/Closed Date: 0012292 / 2003-05-09 Site ID: 126808 Spill Date: 2001-02-15	448 WEST 16TH ST	SW 0 - 1/8 (0.010 mi.)	C50	157
VAULT 632 Spill Number/Closed Date: 9911744 / 2002-03-04 Site ID: 285735 Spill Date: 2000-01-09	448 W 16TH ST	SW 0 - 1/8 (0.010 mi.)	C51	158
ACROSS FROM WEINBURG Spill Number/Closed Date: 0107670 / 2001-10-29 Site ID: 327409 Spill Date: 2001-10-26	450 W 16TH ST	WSW 0 - 1/8 (0.012 mi.)	C67	205
BETW. 9TH/10TH AVE. Spill Number/Closed Date: 0313332 / 2004-03-10 Spill Number/Closed Date: 0311002 / 2006-04-19 Spill Number/Closed Date: 0311976 / 2004-01-26 Site ID: 189354 Site ID: 236116 Site ID: 236117 Spill Date: 2004-03-04 Spill Date: 2003-12-24 Spill Date: 2004-01-26	438 WEST 19TH ST	NNW 0 - 1/8 (0.013 mi.)	E69	207
445-459 W. 16TH ST Spill Number/Closed Date: 0401167 / 2008-10-06 Site ID: 82933 Spill Date: 2004-05-04	445-459 WEST 16TH ST	WSW 0 - 1/8 (0.014 mi.)	C75	230
MANHOLE 3245 Spill Number/Closed Date: 9908043 / 2004-02-05 Site ID: 304531 Spill Date: 1999-10-02	441 W 18TH ST	NW 0 - 1/8 (0.020 mi.)	G86	257
SPILL NUMBER 0013277 Spill Number/Closed Date: 0013277 / 2001-05-10 Site ID: 204578 Spill Date: 2001-03-14	445 WEST 18TH ST (OP	NW 0 - 1/8 (0.032 mi.)	G114	319
409 W. 15TH STREET Spill Number/Closed Date: 9500757 / 1995-04-19 Site ID: 93342 Spill Date: 1995-04-19	409 W. 15TH STREET	SW 0 - 1/8 (0.044 mi.)	K146	391
448 E. 19TH ST	448 E. 19TH ST	NW 0 - 1/8 (0.050 mi.)	E157	418

Spill Number/Closed Date: 9410491 / 1994-11-07 Site ID: 240641 Spill Date: 1994-11-07				
HY FLUID FROM VEHICL Spill Number/Closed Date: 0612352 / 2007-03-16 Site ID: 377180 Spill Date: 2007-02-10	10 AVENUE & WEST 17	WNW 0 - 1/8 (0.052 mi.)	I159	420
MANHOLE #43054, SOUT Spill Number/Closed Date: 0600835 / 2006-05-15 Site ID: 362936 Spill Date: 2006-04-21	WEST 17 STREET & 10	WNW 0 - 1/8 (0.052 mi.)	I160	421
VAULT 4188 Spill Number/Closed Date: 0405039 / 2009-10-26 Site ID: 285822 Spill Date: 2004-08-07	15TH ST BTW 9 & 10TH	SW 0 - 1/8 (0.054 mi.)	K168	433
WEST 18TH ST & TENTH Spill Number/Closed Date: 9902463 / 2006-07-12 Site ID: 322102 Spill Date: 1999-06-03	W. 18TH ST &TENTH AV	WNW 0 - 1/8 (0.057 mi.)	I173	444
SPILL NUMBER 0107030 Spill Number/Closed Date: 0107030 / 2002-07-29 Site ID: 87401 Spill Date: 2001-10-06	18TH ST/11TH AVE	WNW 0 - 1/8 (0.057 mi.)	I174	445
214187; 18 ST & 10 A Spill Number/Closed Date: 0814545 / 2008-11-24 Site ID: 432691 Spill Date: 2008-10-18	18 ST & 10 AV	WNW 0 - 1/8 (0.057 mi.)	I175	446
OIL ON SOIL Spill Number/Closed Date: 1103935 / 2014-02-25 Site ID: 451513 Spill Date: 2011-07-09	10TH AVE AND WEST 18	WNW 0 - 1/8 (0.057 mi.)	I176	447
455 WEST 15TH STREET Spill Number/Closed Date: 9312219 / 1994-01-17 Site ID: 208077 Spill Date: 1994-01-17	455 WEST 15TH STREET	WSW 0 - 1/8 (0.063 mi.)	K194	482
FORMER PARKING GARAG Spill Number/Closed Date: 1303087 / 2014-09-30 Site ID: 483554 Spill Date: 2013-06-21	422-430 WEST 15TH ST	SW 0 - 1/8 (0.065 mi.)	K199	489
MANHOLE # 43048 Spill Number/Closed Date: 0603182 / 2006-10-05 Site ID: 365851 Spill Date: 2006-06-22	WEST 16 STREET & 10	W 0 - 1/8 (0.069 mi.)	Q223	541
BET.9TH & 10TH AVE W Spill Number/Closed Date: 9306675 / 1996-07-15 Site ID: 291344 Spill Date: 1993-08-31	10TH AVE / W 16ST ST	W 0 - 1/8 (0.069 mi.)	Q229	556
COMML STRUCTURE Spill Number/Closed Date: 0501993 / 2005-09-28 Site ID: 346267 Spill Date: 2005-05-18	503 W 16TH ST BET 10	W 0 - 1/8 (0.071 mi.)	Q232	560
NEW YORK MOTORCOACH	90 TEN BROECK AVE	W 0 - 1/8 (0.071 mi.)	Q233	561

Spill Number/Closed Date: 9903444 / 1999-06-28
Site ID: 253508
Spill Date: 1999-06-24

CHELSEA CAR WASH — 450 W 15TH ST — WSW 0 - 1/8 (0.073 mi.) — K252 — 602
Spill Number/Closed Date: 0412147 / 2005-02-15
Site ID: 337527
Spill Date: 2005-02-14

CONSTRUCTION SITE — 450 WEST 15TH ST — WSW 0 - 1/8 (0.073 mi.) — K253 — 603
Spill Number/Closed Date: 0909957 / 2009-12-08
Site ID: 422693
Spill Date: 2009-12-08

150-10 BEAVER RD/QUE — 150-10 BEAVER ROAD — NNW 0 - 1/8 (0.078 mi.) — N259 — 614
Spill Number/Closed Date: 9100573 / 2008-07-23
Site ID: 73431
Spill Date: 1991-03-15

131 10TH AVENUE — 131 10TH AVENUE — NW 0 - 1/8 (0.079 mi.) — I261 — 615
Spill Number/Closed Date: 9414276 / 1995-01-27
Site ID: 64825
Spill Date: 1995-01-27

COMMERCIAL — 156 TENTH AVE — NNW 0 - 1/8 (0.081 mi.) — N270 — 642
Spill Number/Closed Date: 1904821 / 2019-08-12
Site ID: 592823
Spill Date: 2019-08-06

89-10 63RD DR/QUEENS — 89-10 63RD DRIVE — W 0 - 1/8 (0.085 mi.) — Q290 — 686
Spill Number/Closed Date: 9003282 / 1995-05-25
Site ID: 81489
Spill Date: 1990-06-21

87-10 126TH ST/QUEEN — 87-10 126TH STREET — W 0 - 1/8 (0.087 mi.) — Q296 — 693
Spill Number/Closed Date: 9102059 / 1991-05-23
Site ID: 217162
Spill Date: 1991-05-21

85-10 120TH ST/QUEEN — 85-10 120TH STREET — W 0 - 1/8 (0.091 mi.) — Q304 — 717
Spill Number/Closed Date: 9011539 / 1991-02-01
Site ID: 68709
Spill Date: 1991-02-01

CON EDISON TRANSFORM — 85 10TH AVE — W 0 - 1/8 (0.091 mi.) — Q308 — 728
Spill Number/Closed Date: 1306955 / 2014-01-28
Site ID: 487603
Spill Date: 2013-10-03

COMMERCIAL BUILDING — 85 10TH AVE — W 0 - 1/8 (0.091 mi.) — Q310 — 732
Spill Number/Closed Date: 0607761 / 2007-09-21
Spill Number/Closed Date: 9908159 / 2007-06-22
Spill Number/Closed Date: 0607745 / 2006-10-10
Site ID: 371578
Site ID: 258732
Site ID: 371562
Spill Date: 2003-10-06
Spill Date: 1999-10-05
Spill Date: 2006-10-06

OLD GAS STATION — 10TH AV / 20TH ST — NNW 0 - 1/8 (0.094 mi.) — N316 — 758
Spill Number/Closed Date: 9907805 / 2003-03-04

Site ID: 170063
Spill Date: 1999-09-28

W 20 ST AND 10TH AVE Spill Number/Closed Date: 0030004 / 2020-01-10 Site ID: 264326 Spill Date: 2000-05-22	WEST 20TH ST & 10TH	NNW 0 - 1/8 (0.094 mi.)	N319	763
FEEDER MANHOLE #0256 Spill Number/Closed Date: 0611348 / 2007-02-16 Site ID: 375978 Spill Date: 2007-01-12	WEST 15 STREET & 10	WSW 0 - 1/8 (0.099 mi.)	V343	844
214765; 184-10 JAMAI Spill Number/Closed Date: 0814631 / 2010-07-08 Site ID: 432367 Spill Date: 2008-12-02	184-10 JAMAICA AVENU	NNW 0 - 1/8 (0.100 mi.)	N345	847
SERVICE BOX #02343 Spill Number/Closed Date: 0313020 / 2004-04-27 Site ID: 296736 Spill Date: 2004-02-25	427 WEST 14TH ST BTW	SW 0 - 1/8 (0.102 mi.)	W352	856
SEVICE BOX 2343 Spill Number/Closed Date: 0308999 / 2003-12-22 Site ID: 131130 Spill Date: 2003-11-24	427 WEST 14TH ST.	SW 0 - 1/8 (0.102 mi.)	W353	857
DANNY'S PARKING LOT Spill Number/Closed Date: 9614310 / 2004-03-05 Site ID: 237550 Spill Date: 1997-03-10	161-165 10TH AVE	NNW 0 - 1/8 (0.103 mi.)	N356	861
FORMER BUILDING SUPP Spill Number/Closed Date: 9406402 / 2016-04-05 Site ID: 167544 Spill Date: 1994-08-10	501-513 WEST 19TH ST	NW 0 - 1/8 (0.106 mi.)	Z367	883
70 TENTH AVENUE Spill Number/Closed Date: 0102822 / 2005-03-28 Site ID: 198259 Spill Date: 2001-06-13	70 TENTH AVE	WSW 0 - 1/8 (0.109 mi.)	V381	927
CHELSEA CAR WASH / M Spill Number/Closed Date: 0103052 / 2006-07-12 Site ID: 198260 Spill Date: 2001-06-19	70 TENTH AVE	WSW 0 - 1/8 (0.109 mi.)	V383	929
WAREHOUSE BUILDING Spill Number/Closed Date: 0905252 / 2009-08-10 Site ID: 417512 Spill Date: 2009-08-05	511 WEST 18TH STREET	NW 0 - 1/8 (0.109 mi.)	U386	933
515 W 18 ST Spill Number/Closed Date: 9612012 / 2013-01-11 Site ID: 178360 Spill Date: 1997-01-06	515 WEST 18TH ST	NW 0 - 1/8 (0.111 mi.)	U400	966
CON ED MANHOLE 43089 Spill Number/Closed Date: 2106862 / 2022-02-15 Site ID: 625774 Spill Date: 2021-10-22	10TH AVE AND W 21ST	NNW 0 - 1/8 (0.116 mi.)	AA421	1018
SW CORNER OF	WEST 21ST AND TENTH	NNW 0 - 1/8 (0.116 mi.)	AA422	1019

Spill Number/Closed Date: 1409519 / 2015-06-04 Site ID: 503154 Spill Date: 2014-12-21				
177-82 10TH AVE Spill Number/Closed Date: 9708598 / 2003-02-25 Site ID: 98764 Spill Date: 1997-10-23	BETWEEN 20TH & 21ST	NNW 0 - 1/8 (0.117 mi.)	AA425	1023
EMPIRE CITY SUBWAY G Spill Number/Closed Date: 0609814 / 2016-06-08 Site ID: 374150 Spill Date: 2006-11-28	169 10TH AVE	NNW 0 - 1/8 (0.119 mi.)	AA432	1040
MOBIL Spill Number/Closed Date: 1112855 / 2012-02-27 Site ID: 460818 Spill Date: 2012-02-09	451 WEST 14TH ST	WSW 0 - 1/8 (0.119 mi.)	W434	1066
HUDSON PIER BUS DEPO Spill Number/Closed Date: 9514224 / 1996-02-08 Site ID: 148275 Spill Date: 1996-02-08	W 15TH ST + 11TH AVE	W 0 - 1/8 (0.120 mi.)	V438	1076
RESIDENCE Spill Number/Closed Date: 0000570 / 2000-05-01 Site ID: 231981 Spill Date: 2000-04-14	188 10TH AVE	N 0 - 1/8 (0.120 mi.)	AA443	1085
GAS STATION/CAR WASH Spill Number/Closed Date: 0911962 / 2015-04-10 Site ID: 424821 Spill Date: 2010-02-11	461-469 WEST 14TH ST	WSW 0 - 1/8 (0.124 mi.)	W452	1109
EXPLOSION AT FORMER Spill Number/Closed Date: 1202128 / 2012-06-04 Site ID: 464882 Spill Date: 2012-06-01	461-469 WEST 14TH ST	WSW 0 - 1/8 (0.124 mi.)	W453	1128

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 02/28/2022 has revealed that there are 241 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA ID:: NYP004876890	429 W 19TH ST	0 - 1/8 (0.000 mi.)	B3	38
CON EDISON VAULT: 93 EPA ID:: NYP004420113	***419 W 19TH ST***	***0 - 1/8 (0.000 mi.)***	***B4***	***40***
CON EDISON SERVICE B	***424 W 18TH ST***	***0 - 1/8 (0.000 mi.)***	***A5***	***44***

EPA ID:: NYP004256566				
CON EDISON SERVICE B EPA ID:: NYP004257309	***419 W 17TH ST***	***0 - 1/8 (0.000 mi.)***	***A11***	***52***
CON EDISON EPA ID:: NYP004171484	***418 W 17TH ST***	***0 - 1/8 (0.000 mi.)***	***A12***	***56***
NYCHA - FULTON HOUSE EPA ID:: NYR000053405	***427-431 W 17TH ST***	***0 - 1/8 (0.000 mi.)***	***A14***	***86***
CON EDISON SERVICE B EPA ID:: NYP004255345	***121 9TH AVE***	***SE 0 - 1/8 (0.005 mi.)***	***A23***	***101***
CON EDISON SERVICE B EPA ID:: NYP004255287	***117 9TH AVE SB 39650***	***SE 0 - 1/8 (0.005 mi.)***	***A25***	***106***
CON EDISON SERVICE B EPA ID:: NYP004252888	***87 9TH AVE***	***S 0 - 1/8 (0.005 mi.)***	***D26***	***110***
CON EDISON SERVICE B EPA ID:: NYP004254470	***103 9TH AVE***	***SSE 0 - 1/8 (0.006 mi.)***	***A28***	***114***
CON EDISON EPA ID:: NYP004848620	***W 19TH ST & 9TH AVE***	***ENE 0 - 1/8 (0.008 mi.)***	***B35***	***125***
GIVAUDAN CORP C/O FR EPA ID:: NYD986934305	76 NINTH AVE	S 0 - 1/8 (0.011 mi.)	D54	173
GEORGE UHE CO INC EPA ID:: NYD982797888	***76 NINTH AVE***	***S 0 - 1/8 (0.011 mi.)***	***D55***	***180***
CON EDISON EPA ID:: NYP004171427	***76 9TH AVE***	***S 0 - 1/8 (0.011 mi.)***	***D56***	***185***
CON EDISON SERVICE B EPA ID:: NYP004264719	***96 9TH AVE N OF W 35***	***SSE 0 - 1/8 (0.012 mi.)***	***F62***	***197***
CON EDISON EPA ID:: NYP004730107	***428 W 20TH ST***	***N 0 - 1/8 (0.013 mi.)***	***E72***	***214***
CON EDISON SERVICE B EPA ID:: NYP004506994	***315-313 W 20TH ST &***	***NE 0 - 1/8 (0.026 mi.)***	***B97***	***280***
CON EDISON SERVICE B EPA ID:: NYP004508503	***359 W 20TH ST & 9TH***	***NE 0 - 1/8 (0.026 mi.)***	***B98***	***283***
CON EDISON SERVICE B EPA ID:: NYP004506960	***326-324 W 20TH ST &***	***NE 0 - 1/8 (0.026 mi.)***	***B99***	***285***
NYC DEP EPA ID:: NYP003669017	***20TH ST BETW 8TH & 9***	***NE 0 - 1/8 (0.026 mi.)***	***B100***	***288***
CON EDISON SERVICE B EPA ID:: NYP004508495	***337-335 W 20TH ST &***	***NE 0 - 1/8 (0.026 mi.)***	***B101***	***292***
CON EDISON SERVICE B EPA ID:: NYP004508420	***309-307 W 20TH ST &***	***NE 0 - 1/8 (0.026 mi.)***	***B102***	***295***
CON EDISON SERVICE B EPA ID:: NYP004508487	***365 W 20TH ST & 9TH***	***NE 0 - 1/8 (0.026 mi.)***	***B103***	***298***
CON EDISON MANHOLE 3 EPA ID:: NYP004246312	***108 9TH AVE***	***SE 0 - 1/8 (0.028 mi.)***	***F111***	***311***
CON EDISON EPA ID:: NYP004170601	***108 9TH AVE***	***SE 0 - 1/8 (0.028 mi.)***	***F112***	***314***
CON EDISON	74 9TH AVE	S 0 - 1/8 (0.040 mi.)	J128	347

EPA ID:: NYP005241369				
CON EDISON SERVICE B EPA ID:: NYP004222774	***357 W 17TH ST***	***SE 0 - 1/8 (0.040 mi.)***	***F129***	***349***
VERIZON EPA ID:: NYP000967695	***75 9TH AVE***	***SSW 0 - 1/8 (0.041 mi.)***	***J132***	***356***
CON EDISON EPA ID:: NYP005243076	72 9TH AVE	S 0 - 1/8 (0.043 mi.)	J139	379
CON EDISON EPA ID:: NYP005242342	72 9TH AVE	S 0 - 1/8 (0.043 mi.)	J140	382
CON EDISON EPA ID:: NYP004171468	***353 W 17TH ST***	***SE 0 - 1/8 (0.048 mi.)***	***F155***	***410***
CON EDISON MANHOLE 2 EPA ID:: NYP004215760	***400 W 15TH ST & 9TH***	***SSW 0 - 1/8 (0.056 mi.)***	***J170***	***435***
CON EDISON SERVICE B EPA ID:: NYP004288411	***346 W 20TH ST FRONT***	***ENE 0 - 1/8 (0.060 mi.)***	***M183***	***457***
CON EDISON SERVICE B EPA ID:: NYP004412771	432 W 21ST ST FRONT	NNE 0 - 1/8 (0.062 mi.)	O186	467
CON EDISON EPA ID:: NYP004788501	402 W 15TH ST	SSW 0 - 1/8 (0.062 mi.)	J190	474
PRINCE LUMBER FORMER EPA ID:: NYR000227678	61 9TH AVE	SSW 0 - 1/8 (0.069 mi.)	J219	530
CON EDISON SERVICE B EPA ID:: NYP004506853	***328-326 W 21ST ST &***	***NE 0 - 1/8 (0.072 mi.)***	***P234***	***562***
CON EDISON SERVICE B EPA ID:: NYP004261814	***W 21ST ST & 9TH AVE***	***NE 0 - 1/8 (0.072 mi.)***	***P235***	***565***
CON EDISON SERVICE B EPA ID:: NYP004506887	***353-351 W 21ST ST &***	***NE 0 - 1/8 (0.072 mi.)***	***P236***	***569***
CON EDISON SERVICE B EPA ID:: NYP004412755	***437 W 21ST ST FRONT***	***NNE 0 - 1/8 (0.082 mi.)***	***O272***	***647***
CON EDISON EPA ID:: NYP005241500	56 9TH AVE	S 0 - 1/8 (0.082 mi.)	J277	657
CON EDISON EPA ID:: NYP004433629	***341 W 16TH ST FRONT***	***SSE 0 - 1/8 (0.083 mi.)***	***L282***	***665***
A PARABLES TAIL EPA ID:: NYD981483340	***335 W 16TH ST***	***SSE 0 - 1/8 (0.084 mi.)***	***L286***	***674***
CON EDISON MANHOLE: EPA ID:: NYP004412763	***427 W 21ST ST FRONT***	***NNE 0 - 1/8 (0.084 mi.)***	***O287***	***679***
CON EDISON SERVICE B EPA ID:: NYP004261046	***189 9TH AVE***	***NE 0 - 1/8 (0.091 mi.)***	***P298***	***696***
CARRIER CORP EPA ID:: NYD982536849	***332 W 16TH ST***	***SSE 0 - 1/8 (0.092 mi.)***	***L313***	***750***
CON EDISON EPA ID:: NYP004171385	***332 W 17TH ST***	***SE 0 - 1/8 (0.096 mi.)***	***L334***	***814***
CON EDISON SERVICE B EPA ID:: NYP004171393	330 W 17TH ST SB 302	SE 0 - 1/8 (0.101 mi.)	T348	851
CON EDISON SERVICE B	45 9TH AVE N OF 205	SSW 0 - 1/8 (0.108 mi.)	S375	912

EPA ID:: NYP004279196				
CON EDISON SERVICE B EPA ID:: NYP005173240	14TH ST & 9TH AVE	SSW 0 - 1/8 (0.108 mi.)	S379	921
CON EDISON EPA ID:: NYP004171450	***345 W 14TH ST***	***S 0 - 1/8 (0.110 mi.)***	***S395***	***949***
CON EDISON EPA ID:: NYP004171419	***338 W 15TH ST***	***S 0 - 1/8 (0.110 mi.)***	***X396***	***954***
CON EDISON SERVICE B EPA ID:: NYP004493854	***340-338 W 14TH ST &***	***SSW 0 - 1/8 (0.111 mi.)***	***S398***	***959***
CON EDISON EPA ID:: NYP004804290	HUDSON ST & W 14TH S	SSW 0 - 1/8 (0.111 mi.)	S404	984
CON EDISON SERVICE B EPA ID:: NYP004254066	***408 W 14TH ST***	***SSW 0 - 1/8 (0.118 mi.)***	***AD426***	***1024***
CON EDISON EPA ID:: NYP004742441	***322 W 17TH ST***	***SE 0 - 1/8 (0.120 mi.)***	***T440***	***1080***
CON EDISION - SB3785 EPA ID:: NYP004076832	***F/O 331 W.21 ST. F/O***	***ENE 0 - 1/8 (0.121 mi.)***	***R445***	***1087***
CON EDISON SERVICE B EPA ID:: NYP004309415	***419 W 22ND ST OPPOSI***	***NNE 1/8 - 1/4 (0.132 mi.)***	***AF466***	***1179***
CON EDISON EPA ID:: NYP004164943	***310 W 15TH ST***	***SSE 1/8 - 1/4 (0.134 mi.)***	***X470***	***1188***
CON EDISON SERVICE B EPA ID:: NYP004507075	200 E 9TH AVE FRONT	NE 1/8 - 1/4 (0.134 mi.)	AB471	1193
CON EDISON SERVICE B EPA ID:: NYP004410288	***323 W 21ST ST FRONT***	***ENE 1/8 - 1/4 (0.135 mi.)***	***AH475***	***1202***
CON EDISON EPA ID:: NYP004208258	***304 W 15TH ST***	***SSE 1/8 - 1/4 (0.141 mi.)***	***AI491***	***1266***
NYC BD OF ED - PUBLI EPA ID:: NYR000081604	315 W 17TH ST	SE 1/8 - 1/4 (0.141 mi.)	T493	1272
NYC BD OF ED - PUBLI EPA ID:: NYR000082248	315 W 17TH ST - NEW	SE 1/8 - 1/4 (0.141 mi.)	T494	1275
CON EDISON EPA ID:: NYP004183125	***307 W 20TH ST***	***E 1/8 - 1/4 (0.145 mi.)***	***Y508***	***1311***
CON EDISON SERVICE B EPA ID:: NYP004297487	***29 9TH AVE***	***SSW 1/8 - 1/4 (0.148 mi.)***	***AD513***	***1324***
CON EDISON SERVICE B EPA ID:: NYP004254256	***29 9TH AVE***	***SSW 1/8 - 1/4 (0.148 mi.)***	***AD515***	***1331***
CON EDISON EPA ID:: NYP004841462	***29 9TH AVE***	***SSW 1/8 - 1/4 (0.148 mi.)***	***AD517***	***1336***
CON EDISON EPA ID:: NYP004849984	311 W 17TH ST	SE 1/8 - 1/4 (0.149 mi.)	AL521	1343
CON EDISON EPA ID:: NYP004842064	311 W 17TH ST	SE 1/8 - 1/4 (0.149 mi.)	AL522	1345
CON EDISON SERVICE B EPA ID:: NYP004506978	***305 W 20TH ST FRONT***	***E 1/8 - 1/4 (0.152 mi.)***	***Y537***	***1393***
CON EDISON SERVICE B	300 W 20TH ST FRONT	E 1/8 - 1/4 (0.158 mi.)	AN551	1477

EPA ID:: NYP004507000				
CON EDISON-SERVICE B EPA ID:: NYP004165353	***317 W 15TH ST & 8TH***	***SSE 1/8 - 1/4 (0.160 mi.)***	***AI558***	***1503***
CON EDISON SERVICE B EPA ID:: NYP004165361	317 W 15TH ST & 8TH	SSE 1/8 - 1/4 (0.160 mi.)	AI559	1508
CON EDISON EPA ID:: NYP004193736	426 W 23RD ST	NNE 1/8 - 1/4 (0.160 mi.)	AF561	1515
CON EDISON SERVICE B EPA ID:: NYP004461109	***428 W 23RD ST FRONT***	***NNE 1/8 - 1/4 (0.160 mi.)***	***AF562***	***1517***
CON EDISON EPA ID:: NYP004753067	***400 W 23RD ST***	***NE 1/8 - 1/4 (0.161 mi.)***	***AF569***	***1531***
CON EDISON SERVICE B EPA ID:: NYP004224242	***316 W 14TH ST & 8TH***	***S 1/8 - 1/4 (0.163 mi.)***	***AQ578***	***1596***
CON EDISON SERVICE B EPA ID:: NYP004259487	***350 W 23RD ST***	***NE 1/8 - 1/4 (0.166 mi.)***	***AO585***	***1613***
CON EDISON MANHOLE: EPA ID:: NYP004325296	***W 13TH ST & HUDSON S***	***SSW 1/8 - 1/4 (0.169 mi.)***	***AJ588***	***1623***
CON EDISON MANHOLE: EPA ID:: NYP004325270	***W 13TH ST & HUDSON S***	***SSW 1/8 - 1/4 (0.169 mi.)***	***AJ589***	***1626***
KWIK INTL COLOR LTD EPA ID:: NYD986933539	***111 8TH AVE***	***SE 1/8 - 1/4 (0.170 mi.)***	***AT594***	***1645***
CABLEVIEW PUBLICATIO EPA ID:: NYD058235219	***111 8TH AVE***	***SE 1/8 - 1/4 (0.170 mi.)***	***AT595***	***1649***
NEW YORK TELEPHONE C EPA ID:: NYD987035185	***111 8TH AVE - 2ND FL***	***SE 1/8 - 1/4 (0.170 mi.)***	***AT596***	***1653***
V L G NORTH AMERICA EPA ID:: NYR000099721	***111 8TH AVE STE 500***	***SE 1/8 - 1/4 (0.170 mi.)***	***AT598***	***1658***
STATE INSURANCE FUND EPA ID:: NYR000089128	***111 8TH AVE 10TH FLO***	***SE 1/8 - 1/4 (0.170 mi.)***	***AT600***	***1669***
INSIGNIA ESG EPA ID:: NYR000084640	***111 8TH AVE - BASEME***	***SE 1/8 - 1/4 (0.170 mi.)***	***AT601***	***1674***
EFFECTS HOUSE THE EPA ID:: NYD986887370	***111 8TH AVE RM 914***	***SE 1/8 - 1/4 (0.170 mi.)***	***AT602***	***1678***
CON EDISON - 111 8TH EPA ID:: NYD982279598	***111 8TH AVE***	***SE 1/8 - 1/4 (0.170 mi.)***	***AT603***	***1683***
GOLDMAN SACHS & CO-1 EPA ID:: NY0000094524	***111 8TH AVENUE ROOM***	***SE 1/8 - 1/4 (0.170 mi.)***	***AT604***	***1688***
MORGAN GUARANTY TRUS EPA ID:: NYD981877624	111 8TH AVE	SE 1/8 - 1/4 (0.170 mi.)	AT605	1693
CON EDISON SERVICE B EPA ID:: NYP004450409	***339 W 13TH ST***	***S 1/8 - 1/4 (0.170 mi.)***	***AJ606***	***1696***
MONADNOCK CONSTRUCTI EPA ID:: NYR000049114	***339-345 W 13TH ST***	***S 1/8 - 1/4 (0.170 mi.)***	***AJ607***	***1700***
CON EDISON SERVICE B EPA ID:: NYP004507042	***350 W 23RD ST & 9TH***	***NE 1/8 - 1/4 (0.172 mi.)***	***AU609***	***1711***
CON EDISON SERVICE B	***335 W 23RD ST & 9TH***	***NE 1/8 - 1/4 (0.172 mi.)***	***AU610***	***1714***

EPA ID:: NYP004507083				
CON EDISON SERVICE B	***366 W 23RD ST & 9TH***	***NE 1/8 - 1/4 (0.172 mi.)***	***AU611***	***1717***
EPA ID:: NYP004508396				
CON EDISON SERVICE B	***363-61 W 23RD ST & 9***	***NE 1/8 - 1/4 (0.172 mi.)***	***AU612***	***1720***
EPA ID:: NYP004508370				
CON EDISON SERVICE B	***316 W 23RD ST & 9TH***	***NE 1/8 - 1/4 (0.172 mi.)***	***AU613***	***1722***
EPA ID:: NYP004508719				
CON EDISON SERVICE B	***341 W 23RD ST & 9TH***	***NE 1/8 - 1/4 (0.172 mi.)***	***AU614***	***1725***
EPA ID:: NYP004508404				
CON EDISON SERVICE B	***324-22 W 23RD ST & 9***	***NE 1/8 - 1/4 (0.172 mi.)***	***AU615***	***1728***
EPA ID:: NYP004508685				
CON EDISON	***9TH AVE & W 23RD ST***	***NE 1/8 - 1/4 (0.173 mi.)***	***AU616***	***1731***
EPA ID:: NYP004794798				
EVERGREEN CLEANERS	***310 W 14TH ST***	***S 1/8 - 1/4 (0.176 mi.)***	***AQ628***	***1756***
EPA ID:: NYD981489172				
RITE AID #10531	***195 8TH AVE***	***E 1/8 - 1/4 (0.177 mi.)***	***AN633***	***1770***
EPA ID:: NYR000188748				
CON EDISON SERVICE B	***W 19TH ST & 8TH AVE***	***ESE 1/8 - 1/4 (0.178 mi.)***	***AN639***	***1788***
EPA ID:: NYP004250270				
CON EDISON	***W 17TH ST & 8TH AVE***	***SE 1/8 - 1/4 (0.179 mi.)***	***AL645***	***1803***
EPA ID:: NYP004214870				
CON EDISON	***410 W 42ND ST & 9TH***	***NNE 1/8 - 1/4 (0.179 mi.)***	***AX647***	***1809***
EPA ID:: NYP004167839				
CON EDISON	***373 W 23RD ST***	***NE 1/8 - 1/4 (0.184 mi.)***	***AU661***	***1872***
EPA ID:: NYP004794780				
CON EDISON SERVICE B	***19 9TH AVE FRONT OF***	***SSW 1/8 - 1/4 (0.186 mi.)***	***AR668***	***1885***
EPA ID:: NYP004289153				
CON EDISON SERVICE B	***352 W 23RD ST***	***NE 1/8 - 1/4 (0.186 mi.)***	***AO671***	***1893***
EPA ID:: NYP004259495				
CON EDISON	***8TH AVE & W 15TH ST***	***SSE 1/8 - 1/4 (0.187 mi.)***	***BB683***	***1939***
EPA ID:: NYP004208456				
CHELSEA 1 HOUR PHOTO	***128 8TH AVE***	***SE 1/8 - 1/4 (0.189 mi.)***	***AT687***	***1951***
EPA ID:: NY0000228924				
CELIMAR CLEANERS	***188 8TH AVE***	***E 1/8 - 1/4 (0.191 mi.)***	***AN695***	***1976***
EPA ID:: NYD987013240				
CON EDISON SERVICE B	***312 W 14TH ST & 8TH***	***SSE 1/8 - 1/4 (0.192 mi.)***	***AQ696***	***1980***
EPA ID:: NYP004224234				
CON EDISON	***124 8TH AVE***	***SE 1/8 - 1/4 (0.192 mi.)***	***AT697***	***1985***
EPA ID:: NYP004190179				
CON EDISON MANHOLE 3	***W 21ST ST & 8TH AVE***	***E 1/8 - 1/4 (0.192 mi.)***	***AW703***	***2008***
EPA ID:: NYP004143947				
SUN JINN CLEANERS IN	***156 EIGHTH AVE***	***ESE 1/8 - 1/4 (0.192 mi.)***	***AL704***	***2011***
EPA ID:: NYD982719072				
CON EDISON SERVICE B	8 9TH AVE	SSW 1/8 - 1/4 (0.197 mi.)	AR718	2060
EPA ID:: NYP004495594				
SPECTRANOME PLATING	***330 W 13TH ST***	***S 1/8 - 1/4 (0.198 mi.)***	***BC720***	***2067***

EPA ID:: NYD001233295				
CON EDISON EPA ID:: NYP004777918	258 W 20TH ST	E 1/8 - 1/4 (0.201 mi.)	BD724	2075
CON EDISON SERVICE B EPA ID:: NYP004287827	***13TH AVE & GANSEVOOR***	***S 1/8 - 1/4 (0.205 mi.)***	***BE732***	***2092***
CON EDISON SERVICE B EPA ID:: NYP004255949	7 WEST LITTLE W 12TH	SSW 1/8 - 1/4 (0.205 mi.)	AR734	2097
MR CLEAN EPA ID:: NYD986872299	***92 8TH AVE***	***SSE 1/8 - 1/4 (0.207 mi.)***	***BB740***	***2110***
ULTRA CLEANERS INC - EPA ID:: NYD982282204	***92 8TH AVE***	***SSE 1/8 - 1/4 (0.207 mi.)***	***BB741***	***2114***
CON EDISON SERVICE B EPA ID:: NYP004412474	***273 W 17TH ST***	***SE 1/8 - 1/4 (0.208 mi.)***	***BF747***	***2128***
CON EDISON EPA ID:: NYP004729406	***8TH AVE & W 14TH ST***	***SSE 1/8 - 1/4 (0.210 mi.)***	***BH755***	***2159***
CON EDISON EPA ID:: NYP004789400	8TH AVE & 14TH ST	SSE 1/8 - 1/4 (0.210 mi.)	BH758	2164
LUIS PHILLIP CLEANER EPA ID:: NYD981083371	***320 W 23RD ST***	***ENE 1/8 - 1/4 (0.211 mi.)***	***AZ764***	***2175***
CON EDISON EPA ID:: NYP004161949	***78 8TH AVE***	***SSE 1/8 - 1/4 (0.211 mi.)***	***BB771***	***2189***
NATIONAL ENVIRONMENT EPA ID:: NYD986912475	***80 8TH AVE ROOM 303***	***SSE 1/8 - 1/4 (0.212 mi.)***	***BB774***	***2197***
CON EDISON EPA ID:: NYP004742490	***2 9TH AVE***	***SSW 1/8 - 1/4 (0.213 mi.)***	***AR779***	***2209***
CON EDISON SERVICE B EPA ID:: NYP004495651	***9TH AVE & LITTLE W 1***	***SSW 1/8 - 1/4 (0.214 mi.)***	***AR786***	***2222***
CON EDISON SERVICE B EPA ID:: NYP004508461	***253 8TH AVE & 22ND S***	***ENE 1/8 - 1/4 (0.215 mi.)***	***AZ790***	***2229***
CON EDISON SERVICE B EPA ID:: NYP004508453	***257 8TH AVE & 22ND S***	***ENE 1/8 - 1/4 (0.215 mi.)***	***AZ792***	***2235***
CON EDISON EPA ID:: NYP004744520	***22ND ST & 8TH AVE SW***	***ENE 1/8 - 1/4 (0.215 mi.)***	***AZ793***	***2238***
CON EDISON EPA ID:: NYP004792693	22ND ST & 8TH AVE	ENE 1/8 - 1/4 (0.215 mi.)	AZ796	2244
CON EDISON SERVICE B EPA ID:: NYP004509931	8TH AVE & 22ND ST	ENE 1/8 - 1/4 (0.215 mi.)	AZ798	2250
CON EDISON SERVICE B EPA ID:: NYP004511507	***235 9TH AVE & 24TH S***	***NE 1/8 - 1/4 (0.225 mi.)***	***BK835***	***2373***
CON EDISON SERVICE B EPA ID:: NYP004310504	***W 24TH ST & 9TH AVE***	***NE 1/8 - 1/4 (0.226 mi.)***	***BK836***	***2376***
CON EDISON EPA ID:: NYP004837977	250 W 17TH ST	SE 1/8 - 1/4 (0.227 mi.)	BF842	2391
MICR ENCODING INC EPA ID:: NYR000048462	***320 W 13TH ST BASEME***	***S 1/8 - 1/4 (0.230 mi.)***	***BE853***	***2415***
CON EDISON	***266-264 W 22ND ST &***	***E 1/8 - 1/4 (0.233 mi.)***	***BQ867***	***2448***

EPA ID:: NYP004726881				
GETTY REALTY CORP 58 EPA ID:: NY0001492248	***63 8TH AVE***	***SSE 1/8 - 1/4 (0.234 mi.)***	***BH874***	***2473***
CON EDISON SERVICE B EPA ID:: NYP004290805	***445 W 24TH ST***	***NNE 1/8 - 1/4 (0.237 mi.)***	***BR886***	***2505***
NISHI CLEANERS EPA ID:: NYD981559545	***244 8TH AVE***	***ENE 1/8 - 1/4 (0.238 mi.)***	***BQ891***	***2518***
PETERS DRY CLEANERS EPA ID:: NYD982534521	***244 8TH AVE***	***ENE 1/8 - 1/4 (0.238 mi.)***	***BQ892***	***2522***
BONJOUR CLEANERS EPA ID:: NYD125665075	***252 W 14TH ST***	***SSE 1/8 - 1/4 (0.239 mi.)***	***BH894***	***2546***
CON EDISON EPA ID:: NYP004728648	***262 W 22ND ST***	***E 1/8 - 1/4 (0.240 mi.)***	***BQ901***	***2573***
CON EDISON SERVICE B EPA ID:: NYP004284485	***641 HUDSON ST FRONT***	***SSW 1/8 - 1/4 (0.241 mi.)***	***BV907***	***2584***
EARTH CLEANER EPA ID:: NYR000094615	***250 8TH AVE***	***ENE 1/8 - 1/4 (0.246 mi.)***	***BQ921***	***2617***
CON EDISON MANHOLE 2 EPA ID:: NYP004234829	***246 W 14TH ST & 8 AV***	***SSE 1/8 - 1/4 (0.248 mi.)***	***BH926***	***2632***
CON EDISON MANHOLE: EPA ID:: NYP004511424	8TH AVE & 23RD ST	ENE 1/8 - 1/4 (0.248 mi.)	BX931	2644
CON EDISON EPA ID:: NYP004793493	W 23RD ST & 8TH AVE	ENE 1/8 - 1/4 (0.248 mi.)	BX934	2650
CON EDISON SERVICE B EPA ID:: NYP004506929	***220-218 W 23RD ST &***	***ENE 1/8 - 1/4 (0.249 mi.)***	***BX937***	***2658***
CON EDISON SERVICE B EPA ID:: NYP004506937	***206 W 23RD ST & 8TH***	***ENE 1/8 - 1/4 (0.249 mi.)***	***BX938***	***2660***
CON EDISON SERVICE B EPA ID:: NYP004510087	***209-207 W 23RD ST &***	***ENE 1/8 - 1/4 (0.249 mi.)***	***BX939***	***2663***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON SERVICE B EPA ID:: NYP004255865	***426 W 19TH ST***	***NNW 0 - 1/8 (0.005 mi.)***	***E22***	***97***
CON EDISON EPA ID:: NYP004777686	***440 W 16TH ST***	***SW 0 - 1/8 (0.009 mi.)***	***C43***	***137***
METROPOLITAN OLDSMOB EPA ID:: NYD981489230	***440 W 19TH ST***	***NNW 0 - 1/8 (0.010 mi.)***	***E47***	***149***
OXYGEN MEDIA EPA ID:: NYR000076299	448 W 16TH ST	SW 0 - 1/8 (0.010 mi.)	C52	159
CON EDISON EPA ID:: NYP004798542	***437 W 16TH ST***	***WSW 0 - 1/8 (0.011 mi.)***	***C60***	***193***
MENDON LEASING CORP EPA ID:: NY0000071357	***440 W 18TH ST***	***WNW 0 - 1/8 (0.013 mi.)***	***C73***	***217***
CON EDISON SERVICE B EPA ID:: NYP004256533	***439 W 16TH ST***	***WSW 0 - 1/8 (0.014 mi.)***	***C74***	***226***
CON EDISON SERVICE B	***455 W 16TH ST FRONT***	***WSW 0 - 1/8 (0.017 mi.)***	***C79***	***236***

EPA ID:: NYP004289492				
FREEDMAN CUT-OUTS	***455 W 16TH ST***	***WSW 0 - 1/8 (0.017 mi.)***	***C80***	***240***
EPA ID:: NYD986997070				
CON EDISON SERVICE B	***458 W 18TH ST***	***WNW 0 - 1/8 (0.025 mi.)***	***G96***	***276***
EPA ID:: NYP004256541				
CON EDISON MANHOLE:	***116 10TH AVE***	***WNW 0 - 1/8 (0.040 mi.)***	***I123***	***341***
EPA ID:: NYP004257150				
CON EDISON SERVICE B	***136 10TH AVE OPPOSIT***	***NW 0 - 1/8 (0.060 mi.)***	***I185***	***463***
EPA ID:: NYP004256558				
CON EDISON	***440 W 15TH ST***	***SW 0 - 1/8 (0.066 mi.)***	***K209***	***508***
EPA ID:: NYP004172425				
CON EDISON MANHOLE 4	***W 16 ST & 10 AVE***	***W 0 - 1/8 (0.069 mi.)***	***Q224***	***542***
EPA ID:: NYP004143483				
CON EDISON	***10TH AVE & 16TH ST***	***W 0 - 1/8 (0.069 mi.)***	***Q225***	***546***
EPA ID:: NYP004289484				
CON EDISON	10TH AVE & 16TH ST	W 0 - 1/8 (0.069 mi.)	Q227	551
EPA ID:: NYP004798732				
BABOON PRODS	***450 W 15TH ST - 3RD***	***WSW 0 - 1/8 (0.073 mi.)***	***K249***	***597***
EPA ID:: NYR000026377				
CON EDISON SERVICE B	***462 W 20TH ST OPPOSI***	***NNW 0 - 1/8 (0.073 mi.)***	***N254***	***604***
EPA ID:: NYP004259925				
GETTY PETROLEUM CORP	***152 10TH AVE***	***NNW 0 - 1/8 (0.081 mi.)***	***N266***	***625***
EPA ID:: NYR000052845				
CON EDISON SERVICE B	***156 10TH AVE OPPOSIT***	***NNW 0 - 1/8 (0.081 mi.)***	***N271***	***643***
EPA ID:: NYP004257119				
CON EDISON	***438 W 19TH ST & 10TH***	***NW 0 - 1/8 (0.086 mi.)***	***N292***	***688***
EPA ID:: NYP004724811				
MANARK ASSOCIATES DI	***85 10TH AVE***	***W 0 - 1/8 (0.091 mi.)***	***Q307***	***724***
EPA ID:: NY0000861534				
LODO REALTY	***85 10TH AVE - 3RD FL***	***W 0 - 1/8 (0.091 mi.)***	***Q309***	***729***
EPA ID:: NYR000077701				
CON EDISON SERVICE B	W 20TH ST & 10TH AVE	NNW 0 - 1/8 (0.094 mi.)	N317	759
EPA ID:: NYP004277141				
CON EDISON SERVICE B	434-436 W 20TH ST &	NNW 0 - 1/8 (0.094 mi.)	N318	761
EPA ID:: NYP004277083				
CON EDISON SPLICE BO	***W 20TH & 10TH AVE***	***NNW 0 - 1/8 (0.094 mi.)***	***N320***	***765***
EPA ID:: NYP004278222				
CON EDISON SERVICE B	***W 20TH ST & 10TH AVE***	***NNW 0 - 1/8 (0.094 mi.)***	***N321***	***768***
EPA ID:: NYP004276945				
ABLE EMPIRE GROUP	***99 TENTH AVE***	***W 0 - 1/8 (0.095 mi.)***	***Q328***	***798***
EPA ID:: NYD986878601				
CON EDISON SERVICE B	***161 10TH AVE***	***NNW 0 - 1/8 (0.103 mi.)***	***N357***	***862***
EPA ID:: NYP004257028				
V0600	***81 10TH AVENUE***	***WSW 0 - 1/8 (0.103 mi.)***	***V358***	***866***
EPA ID:: NYP004030193				
CON EDISON SERVICE B	***467 W 21ST ST***	***N 0 - 1/8 (0.108 mi.)***	***AA376***	***914***

EPA ID:: NYP004563086				
HFZ HIGHLINE PROPERT EPA ID:: NYR000203869	***505 W 19TH ST***	***NW 0 - 1/8 (0.110 mi.)***	***Z393***	***941***
CON EDISON SERVICE B EPA ID:: NYP004266904	***507 W 19TH ST***	***NW 0 - 1/8 (0.110 mi.)***	***Z394***	***945***
CON EDISON SERVICE B EPA ID:: NYP004289583	***69 10TH AVE FRONT OF***	***WSW 0 - 1/8 (0.111 mi.)***	***V399***	***962***
MENDON LEASING CORP EPA ID:: NYR000022665	***515 W 18TH ST***	***NW 0 - 1/8 (0.111 mi.)***	***U401***	***973***
CON EDISON SB3769 EPA ID:: NYP004725354	***500 W 21ST ST***	***NNW 0 - 1/8 (0.114 mi.)***	***AA411***	***994***
CON EDISON SERVICE B EPA ID:: NYP004281119	***W 21ST ST & 10TH AVE***	***NNW 0 - 1/8 (0.115 mi.)***	***AA412***	***998***
CON EDISON SERVICE B EPA ID:: NYP004257499	***W 21ST ST & 10TH AVE***	***NNW 0 - 1/8 (0.115 mi.)***	***AA413***	***1003***
CON EDISON SERVICE B EPA ID:: NYP004280889	473 W 21ST ST & 10TH	NNW 0 - 1/8 (0.116 mi.)	AA419	1014
CON EDISON SERVICE B EPA ID:: NYP004258083	***525 W 18TH ST OPPOSI***	***NW 0 - 1/8 (0.119 mi.)***	***U435***	***1067***
CON EDISON SERVICE B EPA ID:: NYP004258729	***525 W 18TH ST E OF 1***	***NW 0 - 1/8 (0.119 mi.)***	***U437***	***1072***
CON EDISON SERVICE B EPA ID:: NYP004266086	***511 W 19TH ST***	***NW 0 - 1/8 (0.124 mi.)***	***Z450***	***1099***
CON EDISON SERVICE B EPA ID:: NYP004249734	442 W 14TH ST	SW 0 - 1/8 (0.124 mi.)	W456	1137
CON EDISON SERVICE B EPA ID:: NYP004258349	***872 WASHINGTON ST***	***SW 0 - 1/8 (0.125 mi.)***	***W460***	***1144***
CON EDISON SERVICE B EPA ID:: NYP004263737	***196 10TH AVE***	***N 1/8 - 1/4 (0.134 mi.)***	***AG473***	***1197***
CON EDISON SERVICE B EPA ID:: NYP004289633	11TH AVE & 16TH ST O	W 1/8 - 1/4 (0.136 mi.)	AE476	1206
CON EDISON SERVICE B EPA ID:: NYP004320982	866 WASHINGTON ST	SW 1/8 - 1/4 (0.137 mi.)	W478	1209
V0508 EPA ID:: NYP004045506	***866 WASHINGTON STREE***	***SW 1/8 - 1/4 (0.137 mi.)***	***W479***	***1212***
V0508 EPA ID:: NYP004039236	***866 WASHINGTON AVENU***	***SW 1/8 - 1/4 (0.137 mi.)***	***W480***	***1215***
MUCCIO JOHN EPA ID:: NYD986981272	***528 W 19TH ST***	***NW 1/8 - 1/4 (0.143 mi.)***	***AK499***	***1294***
860 WASHINGTON STREE EPA ID:: NYR000206458	***860 WASHINGTON ST***	***SW 1/8 - 1/4 (0.150 mi.)***	***W528***	***1359***
SUNOCO S/S-501 W 14T EPA ID:: NYD986988210	***501 WEST 14TH STREET***	***WSW 1/8 - 1/4 (0.151 mi.)***	***AM532***	***1371***
NEW YORK STATE DEC EPA ID:: NYP000920066	***507 W 21ST ST***	***NNW 1/8 - 1/4 (0.156 mi.)***	***AG547***	***1456***
HENRY & LLOYD CO THE	***507 W 21ST ST***	***NNW 1/8 - 1/4 (0.156 mi.)***	***AG548***	***1461***

EPA ID:: NYR000031443				
GLUE FAST EQUIPMENT	***9-11 WHITE ST***	***WSW 1/8 - 1/4 (0.160 mi.)***	***AM560***	***1511***
EPA ID:: NYD001356542				
CON EDISON SERVICE B	55 10TH AVE N OF 34T	WSW 1/8 - 1/4 (0.161 mi.)	AM565	1525
EPA ID:: NYP004264826				
CON EDISON SERVICE B	***451 W 13TH ST***	***SW 1/8 - 1/4 (0.166 mi.)***	***AS582***	***1605***
EPA ID:: NYP004249882				
CON EDISON VAULT SUB	***1-11 WEST ST***	***WSW 1/8 - 1/4 (0.166 mi.)***	***AM586***	***1617***
EPA ID:: NYP004278701				
CON ED - V 4289	***532 W 20 ST***	***NW 1/8 - 1/4 (0.175 mi.)***	***AK621***	***1739***
EPA ID:: NYP000928655				
CON EDISON MANHOLE:	***211 10TH AVE FRONT O***	***N 1/8 - 1/4 (0.176 mi.)***	***AG623***	***1743***
EPA ID:: NYP004410155				
CON EDISON	***42 10TH AVE***	***WSW 1/8 - 1/4 (0.179 mi.)***	***AS641***	***1792***
EPA ID:: NYP004171013				
CON EDISON SERVICE B	837 WASHINGTON ST	SW 1/8 - 1/4 (0.179 mi.)	AS644	1801
EPA ID:: NYP004250155				
CON EDISON SERVICE B	***518 W 22ND ST***	***NNW 1/8 - 1/4 (0.182 mi.)***	***AP652***	***1826***
EPA ID:: NYP004261889				
BELL ATLANTIC-NY	***10 AVE & 13TH ST***	***WSW 1/8 - 1/4 (0.187 mi.)***	***AS677***	***1919***
EPA ID:: NYP000935692				
INDUSTRIAL ELECTRONI	***103-11 PRINCE ST***	***NW 1/8 - 1/4 (0.188 mi.)***	***684***	***1942***
EPA ID:: NYD001367630				
CON EDISON SERVICE B	***208 10TH AVE***	***N 1/8 - 1/4 (0.192 mi.)***	***BA698***	***1989***
EPA ID:: NYP004259719				
CON EDISON SERVICE B	***212 10TH AVE***	***N 1/8 - 1/4 (0.197 mi.)***	***BA719***	***2063***
EPA ID:: NYP004259917				
CON EDISON SERVICE B	***13 LITTLE WEST 12TH***	***SSW 1/8 - 1/4 (0.201 mi.)***	***AV726***	***2079***
EPA ID:: NYP004249569				
CON EDISON SERVICE B	***41 LITTLE WEST 12TH***	***SW 1/8 - 1/4 (0.205 mi.)***	***AV735***	***2099***
EPA ID:: NYP004297495				
540 W 21ST ST HOLDIN	540-558 W 21ST ST	NNW 1/8 - 1/4 (0.207 mi.)	AY745	2124
EPA ID:: NYR000236521				
CON EDISON SERVICE B	***505 W 23RD ST***	***N 1/8 - 1/4 (0.219 mi.)***	***BA806***	***2269***
EPA ID:: NYP004259271				
CON EDISON SERVICE B	***517 W 23RD ST***	***N 1/8 - 1/4 (0.220 mi.)***	***BA810***	***2283***
EPA ID:: NYP004259503				
HERTZ PENSKE TRUCK L	***542 W 21ST ST***	***NNW 1/8 - 1/4 (0.221 mi.)***	***AY813***	***2291***
EPA ID:: NYD981563430				
CON EDISON	***58 LITTLE W 12TH ST***	***SW 1/8 - 1/4 (0.222 mi.)***	***BL819***	***2312***
EPA ID:: NYP004171377				
CON EDISON SERVICE B	38 LITTLE WEST 12TH	SW 1/8 - 1/4 (0.223 mi.)	AV827	2339
EPA ID:: NYP004293478				
CON EDISON SERVICE B	***8 LITTLE WEST 12TH S***	***SSW 1/8 - 1/4 (0.226 mi.)***	***BJ839***	***2385***
EPA ID:: NYP004256178				
CON EDISON SERVICE B	***LITTLE WEST 12TH ST***	***SW 1/8 - 1/4 (0.227 mi.)***	***BL843***	***2393***

EPA ID:: NYP004258562				
CON EDISON SERVICE B EPA ID:: NYP004248817	10TH AVE & W 12TH ST	SW 1/8 - 1/4 (0.227 mi.)	BL844	2397
CON EDISON SERVICE B EPA ID:: NYP004260618	***511 W 23RD ST OPPOSI***	***N 1/8 - 1/4 (0.228 mi.)***	***BA847***	***2402***
547-551 WEST 21ST ST EPA ID:: NYR000201616	***547-551 W 21ST ST***	***NNW 1/8 - 1/4 (0.233 mi.)***	***BP869***	***2451***
EMSIG MFG CORP EPA ID:: NYD000818609	***521 W 23RD ST***	***N 1/8 - 1/4 (0.234 mi.)***	***BA871***	***2457***
PENSKE TRUCK LEASING EPA ID:: NYD981563448	***550 W 21ST ST***	***NW 1/8 - 1/4 (0.235 mi.)***	***BP881***	***2489***
CON EDISON SERVICE B EPA ID:: NYP004260642	***525 W 23RD ST***	***N 1/8 - 1/4 (0.238 mi.)***	***BS890***	***2514***
PIER 57 LLC EPA ID:: NYR000226514	***25 11TH AVE***	***W 1/8 - 1/4 (0.239 mi.)***	***BT897***	***2562***
CON EDISON SERVICE B EPA ID:: NYP004275376	***W 10TH AVE & 24TH ST***	***N 1/8 - 1/4 (0.242 mi.)***	***BW913***	***2597***
CON EDISON SERVICE B EPA ID:: NYP004289088	***67 GANSEVOORT ST FRO***	***SSW 1/8 - 1/4 (0.246 mi.)***	***BM920***	***2613***

FUDS: The Listing includes locations of Formerly Used Defense Sites Properties where the US Army Corps Of Engineers is actively working or will take necessary cleanup actions.

A review of the FUDS list, as provided by EDR, and dated 10/26/2021 has revealed that there are 2 FUDS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PIER 45 STORAGE/BERT		SSW 1/2 - 1 (0.729 mi.)	1044	2942
PIER 42 STORAGE/BERT		SSW 1/2 - 1 (0.835 mi.)	1047	2948

ROD: Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid the cleanup.

A review of the ROD list, as provided by EDR, and dated 01/25/2022 has revealed that there is 1 ROD site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HUDSON RIVER PCBS EPA ID:: NYD980763841	***NO STREET APPLICABLE***	***W 1/8 - 1/4 (0.245 mi.)***	***0***	***11***

CONSENT: Major Legal settlements that establish responsibility and standards for cleanup at NPL (superfund) sites. Released periodically by U.S. District Courts after settlement by parties to litigation matters.

A review of the CONSENT list, as provided by EDR, and dated 12/31/2021 has revealed that there is 1

CONSENT site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HUDSON RIVER PCBS	***NO STREET APPLICABLE***	***W 1/8 - 1/4 (0.245 mi.)***	***0***	***11***

FUSRAP: DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

A review of the FUSRAP list, as provided by EDR, and dated 07/26/2021 has revealed that there is 1 FUSRAP site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MARKITE CO.	155 WAVERLY PLACE	SSE 1/2 - 1 (0.644 mi.)	1042	2922
Site Status: Eliminated from consideration under FUSRAP				
Site ID: NY.49				

FINDS: The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 11/04/2021 has revealed that there are 5 FINDS sites within approximately 0.001 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON VAULT: 93	***419 W 19TH ST***	***0 - 1/8 (0.000 mi.)***	***B6***	***47***
Registry ID:: 110062945595				
CON EDISON SERVICE B	***424 W 18TH ST***	***0 - 1/8 (0.000 mi.)***	***A7***	***48***
Registry ID:: 110055935939				
CON EDISON	***429 W 19TH ST***	***0 - 1/8 (0.000 mi.)***	***B8***	***48***
Registry ID:: 110069696564				
NYCHA - FULTON HOUSE	***427-431 W 17TH ST***	***0 - 1/8 (0.000 mi.)***	***A14***	***86***
Registry ID:: 110004542228				
CON EDISON	***418 W 17TH ST***	***0 - 1/8 (0.000 mi.)***	***A15***	***90***
Registry ID:: 110041670670				

ECHO: ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

A review of the ECHO list, as provided by EDR, and dated 01/01/2022 has revealed that there are 5 ECHO sites within approximately 0.001 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON VAULT: 93	***419 W 19TH ST***	***0 - 1/8 (0.000 mi.)***	***B6***	***47***

Registry ID: 110062945595				
CON EDISON SERVICE B Registry ID: 110055935939	***424 W 18TH ST***	***0 - 1/8 (0.000 mi.)***	***A7***	***48***
CON EDISON Registry ID: 110069696564	***429 W 19TH ST***	***0 - 1/8 (0.000 mi.)***	***B8***	***48***
NYCHA - FULTON HOUSE Registry ID: 110004542228	***427-431 W 17TH ST***	***0 - 1/8 (0.000 mi.)***	***A14***	***86***
CON EDISON Registry ID: 110041670670	***418 W 17TH ST***	***0 - 1/8 (0.000 mi.)***	***A15***	***90***

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 12/10/2021 has revealed that there are 8 NY DRYCLEANERS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
VELAZQUEZ 9TH AVENUE Facility Id: 2-6205-01534	***126 9TH AVE***	***ESE 0 - 1/8 (0.018 mi.)***	***A83***	***249***
APHRODITE FRENCH CLE Facility Id: ---	186 9TH AVE	NE 0 - 1/8 (0.096 mi.)	P329	803
JEAN'S MANHATTAN FRE Facility Id: 2-6205-01454	198 9TH AVENUE	NE 1/8 - 1/4 (0.130 mi.)	AB463	1169
SUN JINN CLEANERS IN Facility Id: 2-6205-00310	***156 EIGHTH AVE***	***ESE 1/8 - 1/4 (0.192 mi.)***	***AL704***	***2011***
ROYAL CHICE FRENCH/L Facility Id: 2-6205-00304	320 WEST 23RD STREET	ENE 1/8 - 1/4 (0.211 mi.)	AZ769	2187
LONDON TERRACE/CIM C Facility Id: 2-6205-00284	410 W. 24TH STREET	NNE 1/8 - 1/4 (0.221 mi.)	BK815	2299
OXFORD DRY CLEANERS Facility Id: 2-6205-00294	***232 9TH AVENUE***	***NE 1/8 - 1/4 (0.238 mi.)***	***BK893***	***2529***
EARTH CLEANER Facility Id: 2-6205-01615	***250 8TH AVE***	***ENE 1/8 - 1/4 (0.246 mi.)***	***BQ921***	***2617***

NY E DESIGNATION: Lots designation with an ?E? on the Zoning Maps of the City of New York for potential hazardous material contamination, air and/or noise quality impacts.

A review of the NY E DESIGNATION list, as provided by EDR, and dated 12/13/2021 has revealed that there are 23 NY E DESIGNATION sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LOT 38,TAXBLOCK 712	404 WEST 15 STREET	SSW 0 - 1/8 (0.066 mi.)	J207	506
LOT 7502,TAXBLOCK 73	66 9 AVENUE	S 0 - 1/8 (0.069 mi.)	J215	521
LOT 36,TAXBLOCK 712	61 9 AVENUE	SSW 0 - 1/8 (0.069 mi.)	J218	529
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
LOT 50,TAXBLOCK 715	436 WEST 18 STREET	WNW 0 - 1/8 (0.002 mi.)	A18	93
LOT 7,TAXBLOCK 715	447 WEST 17 STREET	WNW 0 - 1/8 (0.006 mi.)	C29	117
LOT 16,TAXBLOCK 714	431 WEST 16 STREET	WSW 0 - 1/8 (0.006 mi.)	C30	118

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOT 59,TAXBLOCK 715	442 WEST 18 STREET	WNW 0 - 1/8 (0.010 mi.)	C48	155
LOT 14,TAXBLOCK 714	437 WEST 16 STREET	WSW 0 - 1/8 (0.011 mi.)	C57	190
LOT 5,TAXBLOCK 715	453 WEST 17 STREET	WNW 0 - 1/8 (0.018 mi.)	C82	249
LOT 60,TAXBLOCK 715	456 WEST 18 STREET	WNW 0 - 1/8 (0.022 mi.)	G92	268
LOT 63,TAXBLOCK 715	128 10 AVENUE	WNW 0 - 1/8 (0.038 mi.)	I120	333
LOT 2,TAXBLOCK 715	116 10 AVENUE	WNW 0 - 1/8 (0.040 mi.)	I124	344
LOT 3,TAXBLOCK 715	118 10 AVENUE	WNW 0 - 1/8 (0.040 mi.)	I126	345
LOT 64,TAXBLOCK 715	124 10 AVENUE	WNW 0 - 1/8 (0.040 mi.)	I130	354
LOT 29,TAXBLOCK 690	131 10 AVENUE	NW 0 - 1/8 (0.079 mi.)	I260	615
LOT 17,TAXBLOCK 689	501 WEST 17 STREET	WNW 0 - 1/8 (0.099 mi.)	U337	828
LOT 33,TAXBLOCK 691	161 10 AVENUE	NNW 0 - 1/8 (0.103 mi.)	N355	860
LOT 35,TAXBLOCK 691	165 10 AVENUE	NNW 0 - 1/8 (0.104 mi.)	N359	869
LOT 20,TAXBLOCK 690	511 WEST 18 STREET	NW 0 - 1/8 (0.109 mi.)	U384	930
LOT 7502,TAXBLOCK 69	505 WEST 19 STREET	NW 0 - 1/8 (0.110 mi.)	Z392	941
LOT 1,TAXBLOCK 712	58 10 AVENUE	WSW 0 - 1/8 (0.111 mi.)	V397	959
LOT 30,TAXBLOCK 692	169 10 AVENUE	NNW 0 - 1/8 (0.119 mi.)	AA433	1066
LOT 37,TAXBLOCK 691	504 WEST 20 STREET	NNW 0 - 1/8 (0.123 mi.)	Z449	1098

NY HSWDS: The List includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity The latest version of the study is frozen in time. The sites on the study will not automatically be made superfund sites, rather each site will be further evaluated for listing in the registry. So overtime they will be added to the registry or not.

A review of the NY HSWDS list, as provided by EDR, and dated 01/01/2003 has revealed that there is 1 NY HSWDS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FEDERAL BUILDING SIT	252 7TH AVE	ENE 1/4 - 1/2 (0.420 mi.)	CQ1011	2840

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 01/01/2019 has revealed that there are 371 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON VAULT: 93 EPA ID: NYP004420113	***419 W 19TH ST***	***0 - 1/8 (0.000 mi.)***	***B4***	***40***
CON EDISON SERVICE B EPA ID: NYP004256566	***424 W 18TH ST***	***0 - 1/8 (0.000 mi.)***	***A5***	***44***
CON EDISON SERVICE B EPA ID: NYP004257309	***419 W 17TH ST***	***0 - 1/8 (0.000 mi.)***	***A11***	***52***
CON EDISON EPA ID: NYP004171484	***418 W 17TH ST***	***0 - 1/8 (0.000 mi.)***	***A12***	***56***
CON EDISON SERVICE B	***121 9TH AVE***	***SE 0 - 1/8 (0.005 mi.)***	***A23***	***101***

EPA ID: NYP004255345				
CON EDISON SERVICE B EPA ID: NYP004255287	***117 9TH AVE SB 39650***	***SE 0 - 1/8 (0.005 mi.)***	***A25***	***106***
CON EDISON SERVICE B EPA ID: NYP004252888	***87 9TH AVE***	***S 0 - 1/8 (0.005 mi.)***	***D26***	***110***
CON EDISON SERVICE B EPA ID: NYP004254470	***103 9TH AVE***	***SSE 0 - 1/8 (0.006 mi.)***	***A28***	***114***
CON EDISON EPA ID: NYP004504361	9 AVE & 16 ST	S 0 - 1/8 (0.007 mi.)	D31	118
CON EDISON EPA ID: NYP004503157	9 AVE & 16 ST	S 0 - 1/8 (0.007 mi.)	D32	120
CON EDISON EPA ID: NYP004603163	9 AVE & EAST 19 ST	ENE 0 - 1/8 (0.008 mi.)	B36	127
CON EDISON EPA ID: NYP004603247	9TH AVE & W 19TH ST	ENE 0 - 1/8 (0.008 mi.)	B37	129
CON EDISON EPA ID: NYP004848620	W 19TH ST & 9TH AVE	ENE 0 - 1/8 (0.008 mi.)	B38	130
CON ED EPA ID: NYP004350559	19TH ST & 9TH AVE NW	ENE 0 - 1/8 (0.008 mi.)	B39	132
CON EDISON EPA ID: NYP004503363	9 AVE & 17 ST	SSE 0 - 1/8 (0.009 mi.)	F44	139
GOOGLE LLC EPA ID: NYD001328368	***76 9TH AVE***	***S 0 - 1/8 (0.011 mi.)***	***D53***	***163***
GEORGE UHE CO INC EPA ID: NYD986934305 EPA ID: NYD982797888	***76 NINTH AVE***	***S 0 - 1/8 (0.011 mi.)***	***D55***	***180***
CON EDISON EPA ID: NYP004171427	***76 9TH AVE***	***S 0 - 1/8 (0.011 mi.)***	***D56***	***185***
CON EDISON SERVICE B EPA ID: NYP004264719	***96 9TH AVE N OF W 35***	***SSE 0 - 1/8 (0.012 mi.)***	***F62***	***197***
CON EDISON EPA ID: NYP004730107	428 W 20TH ST	N 0 - 1/8 (0.013 mi.)	E70	212
VELAZQUEZ 9TH AVENUE EPA ID: NYD987017241	***126 9TH AVE***	***ESE 0 - 1/8 (0.018 mi.)***	***A83***	***249***
CON EDISON EPA ID: NYP004504379	136 9 AVE	E 0 - 1/8 (0.021 mi.)	B90	264
NYC DEP EPA ID: NYP003669017	***20TH ST BETW 8TH & 9***	***NE 0 - 1/8 (0.026 mi.)***	***B100***	***288***
CON EDISON EPA ID: NYP004603320	F/O 108 9 AV	SE 0 - 1/8 (0.028 mi.)	F109	308
CON EDISON MANHOLE 3 EPA ID: NYP004246312	***108 9TH AVE***	***SE 0 - 1/8 (0.028 mi.)***	***F111***	***311***
CON EDISON EPA ID: NYP004170601	***108 9TH AVE***	***SE 0 - 1/8 (0.028 mi.)***	***F112***	***314***
GENERAL THEOLOGICAL EPA ID: NYR000050716	***175 9TH AVE***	***NE 0 - 1/8 (0.034 mi.)***	***B115***	***320***
CON EDISON	FO 362 W 18 ST	ESE 0 - 1/8 (0.040 mi.)	F127	346

EPA ID: NYP004603262				
CON EDISON SERVICE B EPA ID: NYP004222774	***357 W 17TH ST***	***SE 0 - 1/8 (0.040 mi.)***	***F129***	***349***
CON EDISON EPA ID: NYP004503371	364 W 17 ST	SSE 0 - 1/8 (0.041 mi.)	F131	355
OXYGEN MEDIA EPA ID: NYR000076299	***75 9TH AVENUE***	***SSW 0 - 1/8 (0.041 mi.)***	***J133***	***360***
CON EDISON EPA ID: NYP004504627	361 W 19 ST	ENE 0 - 1/8 (0.044 mi.)	B141	384
CON EDISON EPA ID: NYP004857959	OPP 361 W 19TH ST	ENE 0 - 1/8 (0.044 mi.)	B142	385
CON EDISON EPA ID: NYP004858580	357 W 16TH ST	SSE 0 - 1/8 (0.044 mi.)	F143	387
CON EDISON EPA ID: NYP004503165	357 W 16 ST	SSE 0 - 1/8 (0.044 mi.)	F144	388
CON EDISON EPA ID: NYP004503355	360 W 17 ST	SSE 0 - 1/8 (0.044 mi.)	F145	390
CON EDISON EPA ID: NYP004602033	FO 358 W 19 ST	E 0 - 1/8 (0.046 mi.)	H147	392
CON EDISON EPA ID: NYP004504619	358 W 19 ST	E 0 - 1/8 (0.046 mi.)	H148	394
NYC BD OF ED - HUMAN EPA ID: NYR000080705	***351 W 18TH ST***	***ESE 0 - 1/8 (0.047 mi.)***	***H150***	***398***
CON EDISON EPA ID: NYP004171468	***353 W 17TH ST***	***SE 0 - 1/8 (0.048 mi.)***	***F155***	***410***
CON EDISON - VAULT V EPA ID: NYP005197342	69 9TH AVE	SSW 0 - 1/8 (0.053 mi.)	J161	422
CON EDISON - VAULT V EPA ID: NYP004991871	346 W 17 ST	SSE 0 - 1/8 (0.053 mi.)	F163	424
COVENANT HOUSE THE EPA ID: NYR000160358	***346 W 17TH ST***	***SSE 0 - 1/8 (0.053 mi.)***	***F164***	***425***
CON EDISON EPA ID: NYP004503173	351 W 16 ST	SSE 0 - 1/8 (0.055 mi.)	L169	434
CON EDISON MANHOLE 2 EPA ID: NYP004215760	***400 W 15TH ST & 9TH***	***SSW 0 - 1/8 (0.056 mi.)***	***J170***	***435***
CON EDISON EPA ID: NYP004603288	FO 342 WEST 18 ST	ESE 0 - 1/8 (0.056 mi.)	H171	441
CON EDISON EPA ID: NYP004499109	342-340 W 18 ST & 9	ESE 0 - 1/8 (0.056 mi.)	H172	442
CON EDISON EPA ID: NYP004857942	OPP 353 W 19TH ST	E 0 - 1/8 (0.058 mi.)	M177	448
CON EDISON EPA ID: NYP004603270	FO 350 W 18 ST	ESE 0 - 1/8 (0.059 mi.)	H181	454
CON EDISON EPA ID: NYP004603254	FO 350 WEST 18 ST	ESE 0 - 1/8 (0.059 mi.)	H182	456
CON EDISON SERVICE B	***346 W 20TH ST FRONT***	***ENE 0 - 1/8 (0.060 mi.)***	***M183***	***457***

EPA ID: NYP004288411				
CON EDISON - MANHOLE EPA ID: NYP005127950	179 9TH AVE	NE 0 - 1/8 (0.062 mi.)	P187	469
CON EDISON EPA ID: NYP004788501	402 W 15TH ST	SSW 0 - 1/8 (0.062 mi.)	J191	476
CON EDISON - SERVICE EPA ID: NYP005215645	347 W 17TH ST	SE 0 - 1/8 (0.063 mi.)	L192	477
CON EDISON EPA ID: NYP004602041	FO 349 W 19 ST	E 0 - 1/8 (0.066 mi.)	M208	507
CON EDISON EPA ID: NYP004603296	FO 332 WEST 18 ST	ESE 0 - 1/8 (0.066 mi.)	H210	513
CON EDISON EPA ID: NYP004499117	332-320 18 ST & 9 AV	ESE 0 - 1/8 (0.066 mi.)	H211	515
CON EDISON EPA ID: NYP004504353	345 W 16 ST	SSE 0 - 1/8 (0.068 mi.)	L213	518
61 NINTH DEVELOPMENT EPA ID: NYR000227678	61 9TH AVE	SSW 0 - 1/8 (0.069 mi.)	J220	533
CON EDISON EPA ID: NYP004504601	344 W 19 ST	E 0 - 1/8 (0.071 mi.)	M231	559
CON EDISON SERVICE B EPA ID: NYP004261814	***W 21ST ST & 9TH AVE***	***NE 0 - 1/8 (0.072 mi.)***	***P235***	***565***
CON EDISON EPA ID: NYP004506879	352-35- W 21ST ST &	ENE 0 - 1/8 (0.072 mi.)	P238	573
CON EDISON EPA ID: NYP004604757	FO 352 WEST 21 ST	ENE 0 - 1/8 (0.072 mi.)	P239	575
CON EDISON EPA ID: NYP004858058	OPP 342 W 17TH ST	SE 0 - 1/8 (0.076 mi.)	L255	608
CON EDISON SERVICE B EPA ID: NYP004412755	***437 W 21ST ST FRONT***	***NNE 0 - 1/8 (0.082 mi.)***	***O272***	***647***
CON EDISON EPA ID: NYP004502035	56 9 AVE	S 0 - 1/8 (0.082 mi.)	J274	653
CON EDISON EPA ID: NYP005241500	56 9TH AVE	S 0 - 1/8 (0.082 mi.)	J275	654
CON EDISON - SERVICE EPA ID: NYP004981153	59 9 AVE	SSW 0 - 1/8 (0.083 mi.)	J278	660
CON EDISON EPA ID: NYP004433629	***341 W 16TH ST FRONT***	***SSE 0 - 1/8 (0.083 mi.)***	***L282***	***665***
A PARABLES TAIL EPA ID: NYD981483340	***335 W 16TH ST***	***SSE 0 - 1/8 (0.084 mi.)***	***L286***	***674***
CON EDISON MANHOLE: EPA ID: NYP004412763	***427 W 21ST ST FRONT***	***NNE 0 - 1/8 (0.084 mi.)***	***O287***	***679***
CON EDISON EPA ID: NYP004508495	337-335 W 20TH ST &	ENE 0 - 1/8 (0.085 mi.)	M289	685
CON EDISON EPA ID: NYP004856843	336 W 19TH ST	E 0 - 1/8 (0.087 mi.)	M294	691
CON EDISON SERVICE B	***189 9TH AVE***	***NE 0 - 1/8 (0.091 mi.)***	***P298***	***696***

EPA ID: NYP004261046				
CON EDISON EPA ID: NYP004858132	***48 9TH AVE***	***S 0 - 1/8 (0.091 mi.)***	***S299***	***700***
CON EDISON - SERVICE EPA ID: NYP004171443	***48 9TH AVENUE***	***S 0 - 1/8 (0.091 mi.)***	***S300***	***704***
CON EDISON EPA ID: NYP004602058	FO 334 W 19 ST	ESE 0 - 1/8 (0.091 mi.)	M301	710
CARRIER CORP EPA ID: NYD982536849	***332 W 16TH ST***	***SSE 0 - 1/8 (0.092 mi.)***	***L313***	***750***
CON EDISON EPA ID: NYP004604740	FO 353 WEST 21 ST	NE 0 - 1/8 (0.094 mi.)	P323	775
NYC BOARD OF EDUCATI EPA ID: NYR000062604	***333 W 17TH ST***	***SE 0 - 1/8 (0.096 mi.)***	***T331***	***804***
CON EDISON EPA ID: NYP004857934	OPP 332 W 17TH ST	SE 0 - 1/8 (0.096 mi.)	L333	812
CON EDISON EPA ID: NYP004171385	***332 W 17TH ST***	***SE 0 - 1/8 (0.096 mi.)***	***L334***	***814***
RITE AID #04196 EPA ID: NYR000188623	***188 9TH AVE***	***NE 0 - 1/8 (0.098 mi.)***	***P336***	***820***
401 WEST 14TH STREET EPA ID: NYR000141937	***401 W 14TH ST***	***SSW 0 - 1/8 (0.099 mi.)***	***S341***	***839***
CON EDISON EPA ID: NYP004506895	347-345 W 21ST ST &	ENE 0 - 1/8 (0.100 mi.)	R344	845
CONSOLIDATED EDISON EPA ID: NYP004227041	330 WEST 17 ST	SE 0 - 1/8 (0.101 mi.)	T346	848
CON EDISON EPA ID: NYP004857983	OPP 330 W 17TH ST	SE 0 - 1/8 (0.101 mi.)	T347	849
CONSOLIDATED EDISON EPA ID: NYP004171401	330 W 17TH ST	SE 0 - 1/8 (0.101 mi.)	T349	853
CON EDISON EPA ID: NYP004603304	FO 326 W 18 ST	ESE 0 - 1/8 (0.101 mi.)	T351	855
CON EDISON EPA ID: NYP004500740	OP 344 W 15 ST	S 0 - 1/8 (0.102 mi.)	X354	859
CON EDISON EPA ID: NYP004404562	F/O 329 W 17TH ST	SE 0 - 1/8 (0.105 mi.)	T361	870
CON EDISON EPA ID: NYP004506960	326-324 W 20TH ST &	E 0 - 1/8 (0.105 mi.)	Y362	871
SPERANZA PROPERTIES EPA ID: NYR000166579	***448 W 22ND ST***	***NNE 0 - 1/8 (0.109 mi.)***	***380***	***923***
CON EDISON EPA ID: NYP004171450	***345 W 14TH ST***	***S 0 - 1/8 (0.110 mi.)***	***S395***	***949***
CON EDISON EPA ID: NYP004171419	***338 W 15TH ST***	***S 0 - 1/8 (0.110 mi.)***	***X396***	***954***
CON EDISON EPA ID: NYP004627162	HUDSON ST & W 14 ST	SSW 0 - 1/8 (0.111 mi.)	S406	988
CON EDISON	325-323 W 17 ST & 9	SE 0 - 1/8 (0.113 mi.)	T408	990

EPA ID: NYP004599007				
CON EDISON EPA ID: NYP004507018	320-318 W 20TH ST &	E 0 - 1/8 (0.115 mi.)	Y416	1008
CON EDISON SERVICE B EPA ID: NYP004254066	***408 W 14TH ST***	***SSW 0 - 1/8 (0.118 mi.)***	***AD426***	***1024***
NYC BD OF ED WILLIAM EPA ID: NYR000080580	***320 W 21ST ST***	***ENE 0 - 1/8 (0.118 mi.)***	***R430***	***1034***
CON EDISON EPA ID: NYP004506994	315-313 W 20TH ST &	E 0 - 1/8 (0.118 mi.)	Y431	1039
CON EDISON EPA ID: NYP004863672 EPA ID: NYP004742441	322 W 17TH ST	SE 0 - 1/8 (0.120 mi.)	T439	1077
CON EDISON EPA ID: NYP004404554	F/O 322 W 17 ST	SE 0 - 1/8 (0.120 mi.)	T441	1083
CON EDISON - MANHOLE EPA ID: NYP004929812	22 ST & 9TH AVE	NE 0 - 1/8 (0.120 mi.)	AB444	1086
CON EDISION - SB3785 EPA ID: NYP004076832	***F/O 331 W.21 ST. F/O***	***ENE 0 - 1/8 (0.121 mi.)***	***R445***	***1087***
CON EDISON EPA ID: NYP004508412	316-12 W 20TH ST & 9	E 0 - 1/8 (0.123 mi.)	Y448	1097
CON EDISON EPA ID: NYP004824153	319 W 16TH ST	SE 0 - 1/8 (0.124 mi.)	T457	1140
MOUNT SINAI - BETH I EPA ID: NYR000060384	***325 W 15TH ST***	***SSE 1/8 - 1/4 (0.129 mi.)***	***X461***	***1148***
JEAN'S MANHATTAN CLE EPA ID: NYR000104232	***198 9TH AVE***	***NE 1/8 - 1/4 (0.130 mi.)***	***AB462***	***1160***
CON EDISON SERVICE B EPA ID: NYP004309415	***419 W 22ND ST OPPOSI***	***NNE 1/8 - 1/4 (0.132 mi.)***	***AF466***	***1179***
CON EDISON EPA ID: NYP004493821	348-346 W 14TH ST &	S 1/8 - 1/4 (0.133 mi.)	S467	1183
CON EDISON EPA ID: NYP004601878	FO 317 W 19 ST	E 1/8 - 1/4 (0.133 mi.)	Y468	1185
CON EDISON EPA ID: NYP004493854	340-338 W 14TH ST &	S 1/8 - 1/4 (0.134 mi.)	X469	1186
CON EDISON EPA ID: NYP004164943	***310 W 15TH ST***	***SSE 1/8 - 1/4 (0.134 mi.)***	***X470***	***1188***
CON EDISON EPA ID: NYP004507075	200 E 9TH AVE FRONT	NE 1/8 - 1/4 (0.134 mi.)	AB472	1195
CON EDISON SERVICE B EPA ID: NYP004410288	***323 W 21ST ST FRONT***	***ENE 1/8 - 1/4 (0.135 mi.)***	***AH475***	***1202***
CON EDISON EPA ID: NYP004858082	327 W 14TH ST	S 1/8 - 1/4 (0.136 mi.)	X477	1208
CON EDISON EPA ID: NYP004604765	FO 361 WEST 22 ST	NE 1/8 - 1/4 (0.138 mi.)	AB483	1225
CON EDISON EPA ID: NYP004404547	F/O 317 W 17TH ST	SE 1/8 - 1/4 (0.138 mi.)	T484	1227
CON EDISON	FO 357 WEST 22ND ST	NE 1/8 - 1/4 (0.140 mi.)	AB485	1228

EPA ID: NYP004604724				
CON EDISON	***304 W 15TH ST***	***SSE 1/8 - 1/4 (0.141 mi.)***	***AI491***	***1266***
EPA ID: NYP004208258				
CON ED	355 W 22 ST	NE 1/8 - 1/4 (0.141 mi.)	AB492	1271
EPA ID: NYP004858751				
CON EDISON	309-307 W 20TH ST &	E 1/8 - 1/4 (0.141 mi.)	Y495	1279
EPA ID: NYP004508420				
CON EDISON	344-342 W 14TH ST &	S 1/8 - 1/4 (0.141 mi.)	AJ496	1280
EPA ID: NYP004493839				
CON ED	351 W 22ND ST	NE 1/8 - 1/4 (0.143 mi.)	AB501	1300
EPA ID: NYP004858777				
CON EDISON	306 W 20TH ST	E 1/8 - 1/4 (0.143 mi.)	Y502	1301
EPA ID: NYP004697157				
CON EDISON	308-306 W 19TH ST &	ESE 1/8 - 1/4 (0.144 mi.)	AC503	1303
EPA ID: NYP004508537				
CON EDISON	334-30 W 14TH ST & H	S 1/8 - 1/4 (0.145 mi.)	AJ507	1309
EPA ID: NYP004493847				
CON EDISON	***307 W 20TH ST***	***E 1/8 - 1/4 (0.145 mi.)***	***Y508***	***1311***
EPA ID: NYP004183125				
CON EDISON	OPP 317 W 21 ST	ENE 1/8 - 1/4 (0.146 mi.)	AH510	1318
EPA ID: NYP004584249				
CON EDISON SERVICE B	***29 9TH AVE***	***SSW 1/8 - 1/4 (0.148 mi.)***	***AD513***	***1324***
EPA ID: NYP004297487				
EPA ID: NYP004841462				
CON EDISON SERVICE B	***29 9TH AVE***	***SSW 1/8 - 1/4 (0.148 mi.)***	***AD515***	***1331***
EPA ID: NYP004254256				
CON EDISON	F/O 311 WEST 17 ST	SE 1/8 - 1/4 (0.149 mi.)	AL519	1340
EPA ID: NYP004603239				
CON EDISON	311 W 17TH ST	SE 1/8 - 1/4 (0.149 mi.)	AL523	1348
EPA ID: NYP004842064				
CON EDISON	311 W 17TH ST	SE 1/8 - 1/4 (0.149 mi.)	AL524	1349
EPA ID: NYP004849984				
CON EDISON	305 W 20TH ST FRONT	E 1/8 - 1/4 (0.152 mi.)	Y538	1395
EPA ID: NYP004506978				
CON ED	307 W 19TH STREET	E 1/8 - 1/4 (0.156 mi.)	AN546	1454
EPA ID: NYP004856009				
CON EDISON	300 W 20TH ST FRONT	E 1/8 - 1/4 (0.158 mi.)	AN550	1475
EPA ID: NYP004507000				
CON EDISON	FO 333 WEST 22ND ST	ENE 1/8 - 1/4 (0.159 mi.)	AO557	1501
EPA ID: NYP004604732				
CON EDISON-SERVICE B	***317 W 15TH ST & 8TH***	***SSE 1/8 - 1/4 (0.160 mi.)***	***AI558***	***1503***
EPA ID: NYP004165353				
CON EDISON SERVICE B	***428 W 23RD ST FRONT***	***NNE 1/8 - 1/4 (0.160 mi.)***	***AF562***	***1517***
EPA ID: NYP004461109				
CON EDISON	400 W 23RD ST	NE 1/8 - 1/4 (0.161 mi.)	AF567	1529
EPA ID: NYP004753067				
CON EDISON SERVICE B	***316 W 14TH ST & 8TH***	***S 1/8 - 1/4 (0.163 mi.)***	***AQ578***	***1596***

EPA ID: NYP004224242				
CON EDISON EPA ID: NYP004507034	161-163 W 8TH AVE &	ESE 1/8 - 1/4 (0.163 mi.)	AC580	1603
NYCDEP EPA ID: NYP003660131	13TH ST & 9TH AVE	SSW 1/8 - 1/4 (0.164 mi.)	AR581	1605
CON EDISON SERVICE B EPA ID: NYP004259487	***350 W 23RD ST***	***NE 1/8 - 1/4 (0.166 mi.)***	***AO585***	***1613***
CON EDISON MANHOLE: EPA ID: NYP004325296	***W 13TH ST & HUDSON S***	***SSW 1/8 - 1/4 (0.169 mi.)***	***AJ588***	***1623***
CON EDISON MANHOLE: EPA ID: NYP004325270	***W 13TH ST & HUDSON S***	***SSW 1/8 - 1/4 (0.169 mi.)***	***AJ589***	***1626***
CON EDISON EPA ID: NYP004532230	135-37 8TH AVE & 16T	SE 1/8 - 1/4 (0.170 mi.)	AL592	1642
CON ED EPA ID: NYP004857017	133 8TH AVE	SE 1/8 - 1/4 (0.170 mi.)	AL593	1644
KWIK INTL COLOR LTD EPA ID: NYD986933539	***111 8TH AVE***	***SE 1/8 - 1/4 (0.170 mi.)***	***AT594***	***1645***
CABLEVIEW PUBLICATIO EPA ID: NYD058235219	***111 8TH AVE***	***SE 1/8 - 1/4 (0.170 mi.)***	***AT595***	***1649***
V L G NORTH AMERICA EPA ID: NYR000099721	***111 8TH AVE STE 500***	***SE 1/8 - 1/4 (0.170 mi.)***	***AT598***	***1658***
STATE INSURANCE FUND EPA ID: NYR000089128	***111 8TH AVE 10TH FLO***	***SE 1/8 - 1/4 (0.170 mi.)***	***AT600***	***1669***
INSIGNIA ESG EPA ID: NYR000084640	***111 8TH AVE - BASEME***	***SE 1/8 - 1/4 (0.170 mi.)***	***AT601***	***1674***
EFFECTS HOUSE THE EPA ID: NYD986887370	***111 8TH AVE RM 914***	***SE 1/8 - 1/4 (0.170 mi.)***	***AT602***	***1678***
CON EDISON - 111 8TH EPA ID: NYD982279598	***111 8TH AVE***	***SE 1/8 - 1/4 (0.170 mi.)***	***AT603***	***1683***
GOLDMAN SACHS & CO-1 EPA ID: NY0000094524	***111 8TH AVENUE ROOM***	***SE 1/8 - 1/4 (0.170 mi.)***	***AT604***	***1688***
CON EDISON SERVICE B EPA ID: NYP004450409	***339 W 13TH ST***	***S 1/8 - 1/4 (0.170 mi.)***	***AJ606***	***1696***
CON EDISON EPA ID: NYP004794798	9TH AVE & W 23RD ST	NE 1/8 - 1/4 (0.173 mi.)	AU617	1733
CON EDISON - MANHOLE EPA ID: NYP004929804	23 & 9TH AVE	NE 1/8 - 1/4 (0.173 mi.)	AU619	1736
EVERGREEN CLEANERS EPA ID: NYD981489172	***310 W 14TH ST***	***S 1/8 - 1/4 (0.176 mi.)***	***AQ628***	***1756***
RITE AID #10531 EPA ID: NYR000188748	***195 8TH AVE***	***E 1/8 - 1/4 (0.177 mi.)***	***AN633***	***1770***
CON EDISON SERVICE B EPA ID: NYP004250270	***W 19TH ST & 8TH AVE***	***ESE 1/8 - 1/4 (0.178 mi.)***	***AN639***	***1788***
CON EDISON EPA ID: NYP004214870	***W 17TH ST & 8TH AVE***	***SE 1/8 - 1/4 (0.179 mi.)***	***AL645***	***1803***
CON EDISON	***410 W 42ND ST & 9TH***	***NNE 1/8 - 1/4 (0.179 mi.)***	***AX647***	***1809***

EPA ID: NYP004167839				
CONSOLIDATED EDISON EPA ID: NYP004171476	W 16TH ST & 8TH AVE	SE 1/8 - 1/4 (0.180 mi.)	AT649	1818
NYCT - PUMP ROOM #20 EPA ID: NYR000122010	***18TH ST & 8TH AVE***	***ESE 1/8 - 1/4 (0.180 mi.)***	***AL650***	***1820***
CON EDISON EPA ID: NYP004623575	FO 401 WEST 23RD ST	NE 1/8 - 1/4 (0.182 mi.)	AU655	1857
CON EDISON - SERVICE EPA ID: NYP004270161	***N/W/C WEST 48TH ST.***	***NNE 1/8 - 1/4 (0.183 mi.)***	***AX657***	***1860***
CON EDISON EPA ID: NYP004794780	373 W 23RD ST	NE 1/8 - 1/4 (0.184 mi.)	AU660	1871
CON EDISON - VAULT 4 EPA ID: NYP005137918	433 W 23RD ST	NNE 1/8 - 1/4 (0.185 mi.)	AX664	1880
CON EDISON EPA ID: NYP004289161	F/O 19 9TH AVE	SSW 1/8 - 1/4 (0.186 mi.)	AR667	1884
CON EDISON SERVICE B EPA ID: NYP004259495	***352 W 23RD ST***	***NE 1/8 - 1/4 (0.186 mi.)***	***AO671***	***1893***
CONSOLIDATED EDISON EPA ID: NYP004208456	8TH AVE & W 15TH ST	SSE 1/8 - 1/4 (0.187 mi.)	BB680	1936
CONSOLIDATED EDISON EPA ID: NYP004097382	15TH ST & 8TH AVE	SSE 1/8 - 1/4 (0.187 mi.)	BB681	1937
CON EDISON EPA ID: NYP004508388	363-61 W 23RD ST & 9	NE 1/8 - 1/4 (0.188 mi.)	AO685	1948
CON EDISON EPA ID: NYP004508370	363-61 W 23RD ST & 9	NE 1/8 - 1/4 (0.188 mi.)	AO686	1949
CHELSEA 1 HOUR PHOTO EPA ID: NY0000228924	***128 8TH AVE***	***SE 1/8 - 1/4 (0.189 mi.)***	***AT687***	***1951***
CVS PHARMACY #2919 EPA ID: NYR000193342	***126 8TH AVE***	***SE 1/8 - 1/4 (0.189 mi.)***	***AT688***	***1955***
GANSEVOORT CORPERATI EPA ID: NYR000124727	***652 HUDSON ST***	***S 1/8 - 1/4 (0.191 mi.)***	***BC694***	***1970***
CELIMAR CLEANERS EPA ID: NYD987013240	***188 8TH AVE***	***E 1/8 - 1/4 (0.191 mi.)***	***AN695***	***1976***
CON EDISON SERVICE B EPA ID: NYP004224234	***312 W 14TH ST & 8TH***	***SSE 1/8 - 1/4 (0.192 mi.)***	***AQ696***	***1980***
CON EDISON EPA ID: NYP004190179	***124 8TH AVE***	***SE 1/8 - 1/4 (0.192 mi.)***	***AT697***	***1985***
CVS PHARMACY #1618 EPA ID: NYR000193383	***81 8TH AVE***	***SSE 1/8 - 1/4 (0.192 mi.)***	***BB700***	***1995***
CON EDISON MANHOLE 3 EPA ID: NYP004143947	***W 21ST ST & 8TH AVE***	***E 1/8 - 1/4 (0.192 mi.)***	***AW703***	***2008***
SUN JINN CLEANERS IN EPA ID: NYD982719072	***156 EIGHTH AVE***	***ESE 1/8 - 1/4 (0.192 mi.)***	***AL704***	***2011***
CON EDISON EPA ID: NYP004511374	154-156 E 8TH AVE &	ESE 1/8 - 1/4 (0.192 mi.)	AL705	2037
CON EDISON	8TH AVE & W 21 ST	E 1/8 - 1/4 (0.193 mi.)	AW706	2038

EPA ID: NYP004601860				
CON EDISON - MANHOLE EPA ID: NYP005115142	326 W 23RD ST	ENE 1/8 - 1/4 (0.195 mi.)	AO708	2044
CON EDISON EPA ID: NYP004706669	17 9TH AVE	SSW 1/8 - 1/4 (0.195 mi.)	AR715	2057
CON EDISON EPA ID: NYP004495594	8 9TH AVE	SSW 1/8 - 1/4 (0.197 mi.)	AR717	2059
CON EDISON EPA ID: NYP004858801	322 W 23RD ST	ENE 1/8 - 1/4 (0.199 mi.)	AO721	2071
CON EDISON EPA ID: NYP004777918	258 W 20TH ST	E 1/8 - 1/4 (0.201 mi.)	BD725	2078
CON EDISON - MANHOLE EPA ID: NYP004854937	256 W 20TH ST	E 1/8 - 1/4 (0.202 mi.)	BD729	2086
CON EDISON SERVICE B EPA ID: NYP004287827	***13TH AVE & GANSEVOOR***	***S 1/8 - 1/4 (0.205 mi.)***	***BE732***	***2092***
CON EDISON EPA ID: NYP004255949	7 WEST LITTLE W 12TH	SSW 1/8 - 1/4 (0.205 mi.)	AR733	2095
CON EDISON EPA ID: NYP004503421	263 W 16 ST	SE 1/8 - 1/4 (0.205 mi.)	AT736	2103
CON EDISON EPA ID: NYP004600391	214-212 W 15 ST & 8T	E 1/8 - 1/4 (0.205 mi.)	AW737	2104
MR CLEAN EPA ID: NYD986872299	***92 8TH AVE***	***SSE 1/8 - 1/4 (0.207 mi.)***	***BB740***	***2110***
CON EDISON SERVICE B EPA ID: NYP004412474	***273 W 17TH ST***	***SE 1/8 - 1/4 (0.208 mi.)***	***BF747***	***2128***
CON EDISON EPA ID: NYP004508685	324-22 W 23RD ST & 9	ENE 1/8 - 1/4 (0.208 mi.)	BG750	2148
CON EDISON EPA ID: NYP004605911	FO 324 W 23RD ST	ENE 1/8 - 1/4 (0.208 mi.)	BG751	2149
NYCTA - 14TH ST STAT EPA ID: NY0000973719	***14TH ST & 8TH AVE***	***SSE 1/8 - 1/4 (0.210 mi.)***	***BH752***	***2151***
CON EDISON EPA ID: NYP004729406	8TH AVE & W 14TH ST	SSE 1/8 - 1/4 (0.210 mi.)	BH753	2156
CON EDISON EPA ID: NYP004789400	8TH AVE & 14TH ST	SSE 1/8 - 1/4 (0.210 mi.)	BH754	2158
CON EDISON EPA ID: NYP004594628	14 ST & 8TH AVE	SSE 1/8 - 1/4 (0.210 mi.)	BH759	2167
CON EDISON EPA ID: NYP004852667	73 8TH AVE	SSE 1/8 - 1/4 (0.210 mi.)	AQ762	2173
CON EDISON EPA ID: NYP004858819	320 W 23 ST	ENE 1/8 - 1/4 (0.211 mi.)	AZ766	2183
LUIS PHILLIP CLEANER EPA ID: NYD981083371	320 W 23RD ST	ENE 1/8 - 1/4 (0.211 mi.)	AZ768	2187
CON EDISON EPA ID: NYP004857827	262 W 15TH ST	SSE 1/8 - 1/4 (0.211 mi.)	BB770	2188
CON EDISON	***78 8TH AVE***	***SSE 1/8 - 1/4 (0.211 mi.)***	***BB771***	***2189***

EPA ID: NYP004161949				
CON EDISON EPA ID: NYP004742490	2 9TH AVE	SSW 1/8 - 1/4 (0.213 mi.)	AR778	2207
CON EDISON EPA ID: NYP004599080	237-235 W 15 ST & 8T	ENE 1/8 - 1/4 (0.213 mi.)	AZ782	2216
CON EDISON EPA ID: NYP004495651	9TH AVE & LITTLE W 1	SSW 1/8 - 1/4 (0.214 mi.)	AR785	2221
CON EDISON EPA ID: NYP004603171	FO 252 W 18 ST	ESE 1/8 - 1/4 (0.214 mi.)	BF787	2225
CON EDISON EPA ID: NYP004599056	259-257 W 15 ST & 8	SE 1/8 - 1/4 (0.215 mi.)	BB788	2226
CON EDISON EPA ID: NYP004857819	259 W 15TH ST	SE 1/8 - 1/4 (0.215 mi.)	BB789	2228
CON EDISON EPA ID: NYP004792693	22ND ST & 8TH AVE	ENE 1/8 - 1/4 (0.215 mi.)	AZ794	2241
CON EDISON EPA ID: NYP004509931	8TH AVE & 22ND ST	ENE 1/8 - 1/4 (0.215 mi.)	AZ795	2243
NYC DEPT OF EDUCATIO EPA ID: NYR000214536	***250 W 18TH ST***	***ESE 1/8 - 1/4 (0.216 mi.)***	***BF800***	***2255***
CON EDISON EPA ID: NYP004601902	FO 272 W 19 ST	ESE 1/8 - 1/4 (0.216 mi.)	BI801	2260
CON EDISON EPA ID: NYP004699062	259 W 14TH ST	SSE 1/8 - 1/4 (0.220 mi.)	BH811	2287
LONDON TERRACE CLEAN EPA ID: NYD981137185	***410 W 24TH ST***	***NNE 1/8 - 1/4 (0.221 mi.)***	***BK816***	***2300***
CON EDISON - VAULT 3 EPA ID: NYP004402095	***400 W 24 ST***	***NE 1/8 - 1/4 (0.222 mi.)***	***AU820***	***2317***
JOHN'S TAILOR & CLEA EPA ID: NYR000078899	***6903 8TH AVE***	***SSE 1/8 - 1/4 (0.222 mi.)***	***BE823***	***2325***
CON EDISON EPA ID: NYP004501276	266 W 17 & 8TH AVE	SE 1/8 - 1/4 (0.224 mi.)	BF832	2354
CON EDISON SERVICE B EPA ID: NYP004310504	***W 24TH ST & 9TH AVE***	***NE 1/8 - 1/4 (0.226 mi.)***	***BK836***	***2376***
CON EDISON EPA ID: NYP004837977	250 W 17TH ST	SE 1/8 - 1/4 (0.227 mi.)	BF841	2390
CON EDISON EPA ID: NYP004501706	74 8 AVE	SSE 1/8 - 1/4 (0.227 mi.)	BH846	2401
CON EDISON - TRANSFO EPA ID: NYP005240247	72 8TH AVE	SSE 1/8 - 1/4 (0.228 mi.)	BH848	2406
CON EDISON EPA ID: NYP004509808	323-11 W 23RD ST & 9	ENE 1/8 - 1/4 (0.229 mi.)	BG849	2407
CON EDISON EPA ID: NYP004858710	347 W 4TH ST	S 1/8 - 1/4 (0.231 mi.)	BE858	2430
CON EDISON EPA ID: NYP004861213	***248 W 17TH ST***	***SE 1/8 - 1/4 (0.232 mi.)***	***BF861***	***2435***
CON EDISON	266-264 W 22ND ST &	E 1/8 - 1/4 (0.233 mi.)	BQ865	2445

EPA ID: NYP004726881				
GETTY REALTY CORP 58 EPA ID: NY0001492248	***63 8TH AVE***	***SSE 1/8 - 1/4 (0.234 mi.)***	***BH874***	***2473***
CON ED EPA ID: NYP004863813	242 W 16 ST	SE 1/8 - 1/4 (0.234 mi.)	BO876	2481
CON EDISON EPA ID: NYP004509964	242-240 W 16TH ST &	SE 1/8 - 1/4 (0.234 mi.)	BO878	2483
CON EDISON SERVICE B EPA ID: NYP004290805	***445 W 24TH ST***	***NNE 1/8 - 1/4 (0.237 mi.)***	***BR886***	***2505***
CON EDISON EPA ID: NYP004666749	411 W 24TH ST	NNE 1/8 - 1/4 (0.237 mi.)	BK889	2512
NISHI CLEANERS EPA ID: NYD981559545	***244 8TH AVE***	***ENE 1/8 - 1/4 (0.238 mi.)***	***BQ891***	***2518***
OXFORD DRY CLEANERS EPA ID: NYD981492663	***232 9TH AVENUE***	***NE 1/8 - 1/4 (0.238 mi.)***	***BK893***	***2529***
BONJOUR CLEANERS EPA ID: NYD125665075	***252 W 14TH ST***	***SSE 1/8 - 1/4 (0.239 mi.)***	***BH894***	***2546***
CON EDISON EPA ID: NYP004261384	F/O 251 W 21ST ST	E 1/8 - 1/4 (0.239 mi.)	BQ899	2569
CON EDISON EPA ID: NYP004728648	262 W 22ND ST	E 1/8 - 1/4 (0.240 mi.)	BQ902	2576
CON EDISON SERVICE B EPA ID: NYP004284485	***641 HUDSON ST FRONT***	***SSW 1/8 - 1/4 (0.241 mi.)***	***BV907***	***2584***
CON EDISON EPA ID: NYP004560708	250 W 14 ST	SSE 1/8 - 1/4 (0.242 mi.)	BH911	2595
CON EDISON EPA ID: NYP004728739	F/O 260 W 22 ST	E 1/8 - 1/4 (0.244 mi.)	BQ915	2601
CON EDISON EPA ID: NYP004858157	122 GREENWICH AVE	SSE 1/8 - 1/4 (0.244 mi.)	BH916	2602
CON EDISON EPA ID: NYP004597530	21-25 HORATIO ST & H	S 1/8 - 1/4 (0.247 mi.)	BE923	2627
CON EDISON EPA ID: NYP004857991	17 HORATIO ST	S 1/8 - 1/4 (0.248 mi.)	BE925	2630
CON EDISON EPA ID: NYP004793493	W 23RD ST & 8TH AVE	ENE 1/8 - 1/4 (0.248 mi.)	BX928	2637
CON EDISON EPA ID: NYP004511424	8TH AVE & 23RD ST	ENE 1/8 - 1/4 (0.248 mi.)	BX932	2647
MTA NYCT - 23RD STRE EPA ID: NYR000168245	23RD ST & 8TH AVE	ENE 1/8 - 1/4 (0.248 mi.)	BX933	2648

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON SERVICE B EPA ID: NYP004255865	***426 W 19TH ST***	***NNW 0 - 1/8 (0.005 mi.)***	***E22***	***97***
CON EDISON EPA ID: NYP004777686	440 W 16TH ST	SW 0 - 1/8 (0.009 mi.)	C42	135
CON EDISON	437 W 16TH ST	WSW 0 - 1/8 (0.011 mi.)	C59	191

EPA ID: NYP004798542				
MENDON LEASING CORP EPA ID: NY0000071357	***440 W 18TH ST***	***WNW 0 - 1/8 (0.013 mi.)***	***C73***	***217***
CON EDISON SERVICE B EPA ID: NYP004256533	***439 W 16TH ST***	***WSW 0 - 1/8 (0.014 mi.)***	***C74***	***226***
CON EDISON SERVICE B EPA ID: NYP004289492	***455 W 16TH ST FRONT***	***WSW 0 - 1/8 (0.017 mi.)***	***C79***	***236***
FREEDMAN CUT-OUTS EPA ID: NYD986997070	***455 W 16TH ST***	***WSW 0 - 1/8 (0.017 mi.)***	***C80***	***240***
CON EDISON EPA ID: NYP004699484	432 W 20 ST	N 0 - 1/8 (0.021 mi.)	E88	261
CON EDISON SERVICE B EPA ID: NYP004256541	***458 W 18TH ST***	***WNW 0 - 1/8 (0.025 mi.)***	***G96***	***276***
CON EDISON - MANHOLE EPA ID: NYP004868594	460-454 W 16TH ST	WSW 0 - 1/8 (0.026 mi.)	C104	300
CON EDISON - MANHOLE EPA ID: NYP005138595	447 W 18TH ST	NW 0 - 1/8 (0.036 mi.)	G116	327
CON EDISON MANHOLE: EPA ID: NYP004257150	***116 10TH AVE***	***WNW 0 - 1/8 (0.040 mi.)***	***I123***	***341***
CON ED EPA ID: NYP004405429	FO 120 10TH AVE	WNW 0 - 1/8 (0.043 mi.)	I138	378
CON EDISON EPA ID: NYP005015599	421 W 15TH ST	SW 0 - 1/8 (0.047 mi.)	K152	406
CON EDISON EPA ID: NYP005015581	421 W 15TH ST	SW 0 - 1/8 (0.047 mi.)	K153	406
CON EDISON EPA ID: NYP004504460	10 AVE & 17TH ST	WNW 0 - 1/8 (0.052 mi.)	I158	419
CON EDISON SERVICE B EPA ID: NYP004256558	***136 10TH AVE OPPOSIT***	***NW 0 - 1/8 (0.060 mi.)***	***I185***	***463***
CON EDISON - VAULT 2 EPA ID: NYP005064621	412 W 15TH ST	SW 0 - 1/8 (0.065 mi.)	K203	503
CON EDISON EPA ID: NYP004866644	412 W 15TH ST	SW 0 - 1/8 (0.065 mi.)	K204	503
CON EDISON EPA ID: NYP004172425	***440 W 15TH ST***	***SW 0 - 1/8 (0.066 mi.)***	***K209***	***508***
CON EDISON MANHOLE 4 EPA ID: NYP004143483	***W 16 ST & 10 AVE***	***W 0 - 1/8 (0.069 mi.)***	***Q224***	***542***
CON EDISON EPA ID: NYP004289484	***10TH AVE & 16TH ST***	***W 0 - 1/8 (0.069 mi.)***	***Q225***	***546***
CON EDISON EPA ID: NYP004798732	10TH AVE & 16TH ST	W 0 - 1/8 (0.069 mi.)	Q228	554
CONSOLIDATED EDISON EPA ID: NYP004253266	F/O 146-148 10TH AVE	NNW 0 - 1/8 (0.073 mi.)	N242	580
CON EDISON - VAULT 6 EPA ID: NYP004380184	***450 W 15 ST***	***WSW 0 - 1/8 (0.073 mi.)***	***K244***	***582***
CON EDISON - VAULT S	450 W 15 ST	WSW 0 - 1/8 (0.073 mi.)	K245	587

EPA ID: NYP004995278				
CON EDISON - TRENCH	***450 W15 ST. W/O 9TH***	***WSW 0 - 1/8 (0.073 mi.)***	***K246***	***587***
EPA ID: NYP004372488				
CON EDISON - VAULT V	450 W 15 ST	WSW 0 - 1/8 (0.073 mi.)	K250	601
EPA ID: NYP004995260				
TENTH AVENUE CAR WAS	***450 WEST 15TH STREET***	***WSW 0 - 1/8 (0.073 mi.)***	***K251***	***601***
EPA ID: NYP000928440				
CON EDISON SERVICE B	***462 W 20TH ST OPPOSI***	***NNW 0 - 1/8 (0.073 mi.)***	***N254***	***604***
EPA ID: NYP004259925				
CON EDISON - VAULT S	454 W 15 ST	WSW 0 - 1/8 (0.077 mi.)	K258	613
EPA ID: NYP004995252				
GETTY PETROLEUM CORP	***152 10TH AVE***	***NNW 0 - 1/8 (0.081 mi.)***	***N266***	***625***
EPA ID: NYR000052845				
CON EDISON SERVICE B	***156 10TH AVE OPPOSIT***	***NNW 0 - 1/8 (0.081 mi.)***	***N271***	***643***
EPA ID: NYP004257119				
85 TENTH AVENUE ASSO	85 10TH AVE 1ST FLOO	W 0 - 1/8 (0.091 mi.)	Q303	715
EPA ID: NYR000099978				
BLENHEIM LLC	***85 10TH AVE - BASEME***	***W 0 - 1/8 (0.091 mi.)***	***Q306***	***719***
EPA ID: NYP000949040				
EPA ID: NYR000143867				
CON EDISON SPLICE BO	***W 20TH & 10TH AVE***	***NNW 0 - 1/8 (0.094 mi.)***	***N320***	***765***
EPA ID: NYP004278222				
CON EDISON SERVICE B	***W 20TH ST & 10TH AVE***	***NNW 0 - 1/8 (0.094 mi.)***	***N321***	***768***
EPA ID: NYP004276945				
EPA ID: NYP004277083				
CON EDISON	10 AVE & 20 ST	NNW 0 - 1/8 (0.094 mi.)	N322	774
EPA ID: NYP004504478				
NORTHEAST LABORATORY	***99 10TH AVE ROOM 721***	***W 0 - 1/8 (0.095 mi.)***	***Q326***	***778***
EPA ID: NYD987017514				
DEA	***99 10TH AVE.***	***W 0 - 1/8 (0.095 mi.)***	***Q327***	***795***
EPA ID: NYP000907337				
EPA ID: NYP000924514				
ABLE EMPIRE GROUP	***99 TENTH AVE***	***W 0 - 1/8 (0.095 mi.)***	***Q328***	***798***
EPA ID: NYD986878601				
HLP PROPERTIES LOT	***501-515 W 17TH ST***	***WNW 0 - 1/8 (0.099 mi.)***	***U338***	***828***
EPA ID: NYR000194449				
CON EDISON SERVICE B	***161 10TH AVE***	***NNW 0 - 1/8 (0.103 mi.)***	***N357***	***862***
EPA ID: NYP004257028				
V0600	***81 10TH AVENUE***	***WSW 0 - 1/8 (0.103 mi.)***	***V358***	***866***
EPA ID: NYP004030193				
EMPIRE CITY SUBWAY C	***177-183 10TH AVE***	***NNW 0 - 1/8 (0.107 mi.)***	***AA369***	***900***
EPA ID: NY0000821736				
CON EDISON	467 W 21ST ST	N 0 - 1/8 (0.108 mi.)	AA377	917
EPA ID: NYP004563086				
CON ED	WASHINGTON ST & W 14	SW 0 - 1/8 (0.109 mi.)	W388	935
EPA ID: NYP004861403				
CON ED	505 W 19TH ST	NW 0 - 1/8 (0.110 mi.)	Z390	938

EPA ID: NYP004849604				
CON EDISON SERVICE B EPA ID: NYP004266904	***507 W 19TH ST***	***NW 0 - 1/8 (0.110 mi.)***	***Z394***	***945***
CON EDISON SERVICE B EPA ID: NYP004289583	***69 10TH AVE FRONT OF***	***WSW 0 - 1/8 (0.111 mi.)***	***V399***	***962***
MENDON LEASING CORP EPA ID: NYR000022665	***515 W 18TH ST***	***NW 0 - 1/8 (0.111 mi.)***	***U401***	***973***
CON EDISON EPA ID: NYP004725354	500 W 21ST ST	NNW 0 - 1/8 (0.114 mi.)	AA410	993
CON EDISON SERVICE B EPA ID: NYP004280889 EPA ID: NYP004281119	***W 21ST ST & 10TH AVE***	***NNW 0 - 1/8 (0.115 mi.)***	***AA412***	***998***
CONSOLIDATED EDISON EPA ID: NYP004101770	416 W 14 ST MH2355	SSW 0 - 1/8 (0.118 mi.)	AD427	1028
CON EDISON SERVICE B EPA ID: NYP004258083	***525 W 18TH ST OPPOSI***	***NW 0 - 1/8 (0.119 mi.)***	***U435***	***1067***
CON EDISON SERVICE B EPA ID: NYP004258729	***525 W 18TH ST E OF 1***	***NW 0 - 1/8 (0.119 mi.)***	***U437***	***1072***
520 WEST 19TH STREET EPA ID: NYR000142745	***516-522 W 19TH ST***	***NW 0 - 1/8 (0.122 mi.)***	***Z447***	***1092***
CON EDISON SERVICE B EPA ID: NYP004266086	***511 W 19TH ST***	***NW 0 - 1/8 (0.124 mi.)***	***Z450***	***1099***
CON EDISON EPA ID: NYP004249734	442 W 14TH ST	SW 0 - 1/8 (0.124 mi.)	W455	1136
CON EDISON SERVICE B EPA ID: NYP004258349	***872 WASHINGTON ST***	***SW 0 - 1/8 (0.125 mi.)***	***W460***	***1144***
CON EDISON SERVICE B EPA ID: NYP004263737	***196 10TH AVE***	***N 1/8 - 1/4 (0.134 mi.)***	***AG473***	***1197***
CON EDISON EPA ID: NYP004504486	522 W 19 ST	NW 1/8 - 1/4 (0.134 mi.)	Z474	1201
V0508 EPA ID: NYP004045506	***866 WASHINGTON STREE***	***SW 1/8 - 1/4 (0.137 mi.)***	***W479***	***1212***
V0508 EPA ID: NYP004039236	***866 WASHINGTON AVENU***	***SW 1/8 - 1/4 (0.137 mi.)***	***W480***	***1215***
860 WASHINGTON STREE EPA ID: NYR000206458	***860 WASHINGTON ST***	***SW 1/8 - 1/4 (0.150 mi.)***	***W528***	***1359***
CONSOLIDATED EDISON EPA ID: NYP004072974	10TH AVE & W 22ND ST	N 1/8 - 1/4 (0.151 mi.)	AG529	1364
CON EDISON - MANHOLE EPA ID: NYP004259933	***OPP 197 10TH AVE***	***N 1/8 - 1/4 (0.151 mi.)***	***AG531***	***1367***
CON EDISON - SERVICE EPA ID: NYP004291878	***407 WEST 13TH ST***	***SSW 1/8 - 1/4 (0.154 mi.)***	***AD542***	***1403***
17TH STREET DEVELOPM EPA ID: NYR000227256	***76 11TH AVENUE***	***NW 1/8 - 1/4 (0.155 mi.)***	***AK544***	***1410***
NEW YORK STATE DEC EPA ID: NYP000920066	***507 W 21ST ST***	***NNW 1/8 - 1/4 (0.156 mi.)***	***AG547***	***1456***
HENRY & LLOYD CO THE	***507 W 21ST ST***	***NNW 1/8 - 1/4 (0.156 mi.)***	***AG548***	***1461***

EPA ID: NYR000031443				
CON EDISON EPA ID: NYP004264826	55 10TH AVE N OF 34T	WSW 1/8 - 1/4 (0.161 mi.)	AM566	1527
WEST CHELSEA DEVELOP EPA ID: NYR000142117	***535 W 19TH ST - VACA***	***NW 1/8 - 1/4 (0.161 mi.)***	***AK572***	***1540***
CON EDISON SERVICE B EPA ID: NYP004249882	***451 W 13TH ST***	***SW 1/8 - 1/4 (0.166 mi.)***	***AS582***	***1605***
CON EDISON VAULT SUB EPA ID: NYP004278701	***1-11 WEST ST***	***WSW 1/8 - 1/4 (0.166 mi.)***	***AM586***	***1617***
CON ED - V 4289 EPA ID: NYP000928655	***532 W 20 ST***	***NW 1/8 - 1/4 (0.175 mi.)***	***AK621***	***1739***
CON EDISON MANHOLE: EPA ID: NYP004410155	***211 10TH AVE FRONT O***	***N 1/8 - 1/4 (0.176 mi.)***	***AG623***	***1743***
GREENWAY MEWS REALTY EPA ID: NYR000200550	***416 W 13TH ST #300***	***SSW 1/8 - 1/4 (0.176 mi.)***	***AV626***	***1749***
CONSOLIDATED EDISON EPA ID: NYP004125605	519 W 21 ST SB3762	NNW 1/8 - 1/4 (0.178 mi.)	AP637	1783
A B GREEN GANSEVOORT EPA ID: NYR000129114	***856 WASHINGTON ST***	***SW 1/8 - 1/4 (0.178 mi.)***	***AS638***	***1784***
CON EDISON - VAULT 3 EPA ID: NYP004923908	42 10 AVE	WSW 1/8 - 1/4 (0.179 mi.)	AS640	1792
CON EDISON EPA ID: NYP004171013 EPA ID: NYP004286860	***42 10TH AVE***	***WSW 1/8 - 1/4 (0.179 mi.)***	***AS641***	***1792***
CON EDISON EPA ID: NYP004250155	***837 WASHINGTON ST***	***SW 1/8 - 1/4 (0.179 mi.)***	***AS643***	***1799***
CONSOLIDATED EDISON EPA ID: NYP004019741	520 W 22ND ST	NNW 1/8 - 1/4 (0.182 mi.)	AP651	1825
CON EDISON SERVICE B EPA ID: NYP004261889	***518 W 22ND ST***	***NNW 1/8 - 1/4 (0.182 mi.)***	***AP652***	***1826***
EXXON EPA ID: NYD987026069	***215 10TH AVE & W 23R***	***N 1/8 - 1/4 (0.182 mi.)***	***AG653***	***1830***
CVS PHARMACY #10041 EPA ID: NYR000198234	***500 W 23RD ST***	***N 1/8 - 1/4 (0.186 mi.)***	***BA675***	***1904***
BELL ATLANTIC-NY EPA ID: NYP000935692	***10 AVE & 13TH ST***	***WSW 1/8 - 1/4 (0.187 mi.)***	***AS677***	***1919***
BAYVIEW CORRECTIONAL EPA ID: NYR000117242	***550 W 20TH ST***	***NW 1/8 - 1/4 (0.187 mi.)***	***AY678***	***1922***
CON EDISON SERVICE B EPA ID: NYP004259719	***208 10TH AVE***	***N 1/8 - 1/4 (0.192 mi.)***	***BA698***	***1989***
CON EDISON EPA ID: NYP004278271	W 23RD ST & 10 TH AV	N 1/8 - 1/4 (0.195 mi.)	BA710	2047
CON EDISON SERVICE B EPA ID: NYP004259917	***212 10TH AVE***	***N 1/8 - 1/4 (0.197 mi.)***	***BA719***	***2063***
CON EDISON SERVICE B EPA ID: NYP004249569	***13 LITTLE WEST 12TH***	***SSW 1/8 - 1/4 (0.201 mi.)***	***AV726***	***2079***
CON EDISON SERVICE B	***41 LITTLE WEST 12TH***	***SW 1/8 - 1/4 (0.205 mi.)***	***AV735***	***2099***

EPA ID: NYP004297495				
CON EDISON - SERVICE EPA ID: NYP004171062	***51 LITTLE W12TH ST.***	***SW 1/8 - 1/4 (0.207 mi.)***	***AS742***	***2118***
540 W 21ST ST HOLDIN EPA ID: NYR000236521	540-558 W 21ST ST	NNW 1/8 - 1/4 (0.207 mi.)	AY746	2127
CONSOLIDATED EDISON EPA ID: NYP004097556	520 W 23 ST MH4171	N 1/8 - 1/4 (0.213 mi.)	BA783	2218
CON EDISON SERVICE B EPA ID: NYP004259271	***505 W 23RD ST***	***N 1/8 - 1/4 (0.219 mi.)***	***BA806***	***2269***
CON EDISON SERVICE B EPA ID: NYP004259503	***517 W 23RD ST***	***N 1/8 - 1/4 (0.220 mi.)***	***BA810***	***2283***
CON EDISON EPA ID: NYP004171377	***58 LITTLE W 12TH ST***	***SW 1/8 - 1/4 (0.222 mi.)***	***BL819***	***2312***
CON EDISON EPA ID: NYP004293498	38 LITTLE W 12 ST	SW 1/8 - 1/4 (0.223 mi.)	AV826	2338
CON EDISON - SERVICE EPA ID: NYP004171047	***44 LITTLE W12TH ST.***	***SW 1/8 - 1/4 (0.223 mi.)***	***BL828***	***2341***
CON EDISON EPA ID: NYP004249585	E HOUSTON AT COLUMBI	SSW 1/8 - 1/4 (0.226 mi.)	BM838	2383
CON EDISON SERVICE B EPA ID: NYP004256178	***8 LITTLE WEST 12TH S***	***SSW 1/8 - 1/4 (0.226 mi.)***	***BJ839***	***2385***
CON EDISON SERVICE B EPA ID: NYP004258562	***LITTLE WEST 12TH ST***	***SW 1/8 - 1/4 (0.227 mi.)***	***BL843***	***2393***
CON EDISON EPA ID: NYP004248817	10TH AVE & W 12TH ST	SW 1/8 - 1/4 (0.227 mi.)	BL845	2399
CON EDISON SERVICE B EPA ID: NYP004260618	***511 W 23RD ST OPPOSI***	***N 1/8 - 1/4 (0.228 mi.)***	***BA847***	***2402***
DIA ART FOUNDATION EPA ID: NYR000144089	***535 W 22ND ST***	***NNW 1/8 - 1/4 (0.230 mi.)***	***BN854***	***2419***
CON EDISON EPA ID: NYP004289096	53 GANSEVOORT ST FRO	SSW 1/8 - 1/4 (0.230 mi.)	BJ856	2426
547-551 WEST 21ST ST EPA ID: NYR000201616	547-551 W 21ST ST	NNW 1/8 - 1/4 (0.233 mi.)	BP864	2444
PENSKE TRUCK LEASING EPA ID: NYD981563448	***550 W 21ST ST***	***NW 1/8 - 1/4 (0.235 mi.)***	***BP881***	***2489***
CON EDISON SERVICE B EPA ID: NYP004260642	***525 W 23RD ST***	***N 1/8 - 1/4 (0.238 mi.)***	***BS890***	***2514***
PIER 57 EPA ID: NYR000226514	25 11TH AVE	W 1/8 - 1/4 (0.239 mi.)	BT895	2550
CON EDISON - MANHOLE EPA ID: NYP004914279	W 24TH ST & 10TH AVE	N 1/8 - 1/4 (0.242 mi.)	BW912	2596
CON EDISON SERVICE B EPA ID: NYP004275376	***W 10TH AVE & 24TH ST***	***N 1/8 - 1/4 (0.242 mi.)***	***BW913***	***2597***
CONSOLIDATED EDISON EPA ID: NYP004124988	24 ST & 10 AVE MH431	N 1/8 - 1/4 (0.243 mi.)	BW914	2600
CON EDISON SERVICE B	***67 GANSEVOORT ST FRO***	***SSW 1/8 - 1/4 (0.246 mi.)***	***BM920***	***2613***

EXECUTIVE SUMMARY

EPA ID: NYP004289088

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 77 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA Id: NYP004876890	429 W 19TH ST	0 - 1/8 (0.000 mi.)	B10	51
CON EDISON EPA Id: NYP004171484	***418 W 17TH ST***	***0 - 1/8 (0.000 mi.)***	***A12***	***56***
CON EDISON SERVICE B EPA Id: NYP004255287	117 9TH AVE	SE 0 - 1/8 (0.005 mi.)	A24	105
CON EDISON EPA Id: NYP004848620	W 19TH ST & 9TH AVE	ENE 0 - 1/8 (0.008 mi.)	B34	123
CON EDISON EPA Id: NYP004171427	***76 9TH AVE***	***S 0 - 1/8 (0.011 mi.)***	***D56***	***185***
CON EDISON SERVICE B EPA Id: NYP004264719	96 9TH AVE N OF W 35	SSE 0 - 1/8 (0.012 mi.)	F61	195
CON EDISON EPA Id: NYP004730107	428 W 20TH ST	N 0 - 1/8 (0.013 mi.)	E71	213
CON EDISON MANHOLE 3 EPA Id: NYP004246312	108 9TH AVE	SE 0 - 1/8 (0.028 mi.)	F110	309
CON EDISON SERVICE B EPA Id: NYP004222774	***357 W 17TH ST***	***SE 0 - 1/8 (0.040 mi.)***	***F129***	***349***
VERIZON EPA Id: NYP000967695	***75 9TH AVE***	***SSW 0 - 1/8 (0.041 mi.)***	***J132***	***356***
CON EDISON EPA Id: NYP004171468	***353 W 17TH ST***	***SE 0 - 1/8 (0.048 mi.)***	***F155***	***410***
CON EDISON MANHOLE 2 EPA Id: NYP004215760	***400 W 15TH ST & 9TH***	***SSW 0 - 1/8 (0.056 mi.)***	***J170***	***435***
CON EDISON EPA Id: NYP004788501	402 W 15TH ST	SSW 0 - 1/8 (0.062 mi.)	J189	472
CON EDISON EPA Id: NYP004433629	341 W 16TH ST FRONT	SSE 0 - 1/8 (0.083 mi.)	L283	669
CON EDISON - SERVICE EPA Id: NYP004171443	***48 9TH AVENUE***	***S 0 - 1/8 (0.091 mi.)***	***S300***	***704***
CON EDISON EPA Id: NYP004171385	***332 W 17TH ST***	***SE 0 - 1/8 (0.096 mi.)***	***L334***	***814***
CON EDISON SERVICE B EPA Id: NYP004279196	45 9TH AVE N OF 205	SSW 0 - 1/8 (0.108 mi.)	S374	910
CON EDISON EPA Id: NYP004171450	***345 W 14TH ST***	***S 0 - 1/8 (0.110 mi.)***	***S395***	***949***
CON EDISON EPA Id: NYP004171419	***338 W 15TH ST***	***S 0 - 1/8 (0.110 mi.)***	***X396***	***954***
CON EDISON	HUDSON ST & W 14TH S	SSW 0 - 1/8 (0.111 mi.)	S405	987

EPA Id: NYP004804290				
CON EDISON SERVICE B EPA Id: NYP004507018	320-318 W 20TH ST &	E 0 - 1/8 (0.115 mi.)	Y415	1007
CON EDISON EPA Id: NYP004742441	322 W 17TH ST	SE 0 - 1/8 (0.120 mi.)	T442	1084
CON EDISON EPA Id: NYP004164943	***310 W 15TH ST***	***SSE 1/8 - 1/4 (0.134 mi.)***	***X470***	***1188***
CON EDISON EPA Id: NYP004208258	***304 W 15TH ST***	***SSE 1/8 - 1/4 (0.141 mi.)***	***AI491***	***1266***
CON EDISON EPA Id: NYP004183125	***307 W 20TH ST***	***E 1/8 - 1/4 (0.145 mi.)***	***Y508***	***1311***
CON EDISON EPA Id: NYP004841462	29 9TH AVE	SSW 1/8 - 1/4 (0.148 mi.)	AD516	1335
CON EDISON EPA Id: NYP004842064	311 W 17TH ST	SE 1/8 - 1/4 (0.149 mi.)	AL520	1341
CON EDISON EPA Id: NYP004849984	311 W 17TH ST	SE 1/8 - 1/4 (0.149 mi.)	AL525	1351
CON EDISON-SERVICE B EPA Id: NYP004165361 EPA Id: NYP004165353	***317 W 15TH ST & 8TH***	***SSE 1/8 - 1/4 (0.160 mi.)***	***AI558***	***1503***
CON EDISON EPA Id: NYP004753067	400 W 23RD ST	NE 1/8 - 1/4 (0.161 mi.)	AF568	1530
CON EDISON SERVICE B EPA Id: NYP004224242	***316 W 14TH ST & 8TH***	***S 1/8 - 1/4 (0.163 mi.)***	***AQ578***	***1596***
CON EDISON SERVICE B EPA Id: NYP004259487	350 W 23RD ST	NE 1/8 - 1/4 (0.166 mi.)	AO584	1611
CON EDISON EPA Id: NYP004794798	9TH AVE & W 23RD ST	NE 1/8 - 1/4 (0.173 mi.)	AU618	1735
CON EDISON EPA Id: NYP004214870	***W 17TH ST & 8TH AVE***	***SE 1/8 - 1/4 (0.179 mi.)***	***AL645***	***1803***
CON EDISON EPA Id: NYP004167839	***410 W 42ND ST & 9TH***	***NNE 1/8 - 1/4 (0.179 mi.)***	***AX647***	***1809***
CON EDISON - SERVICE EPA Id: NYP004171476	***WEST 16TH STREET AND***	***SE 1/8 - 1/4 (0.180 mi.)***	***AT648***	***1814***
NYCT - PUMP ROOM #20 EPA Id: NYR000122010	***18TH ST & 8TH AVE***	***ESE 1/8 - 1/4 (0.180 mi.)***	***AL650***	***1820***
CON EDISON EPA Id: NYP004794780	373 W 23RD ST	NE 1/8 - 1/4 (0.184 mi.)	AU659	1870
CON EDISON SERVICE B EPA Id: NYP004259495	352 W 23RD ST	NE 1/8 - 1/4 (0.186 mi.)	AO672	1897
CON EDISON EPA Id: NYP004208456	***8TH AVE & W 15TH ST***	***SSE 1/8 - 1/4 (0.187 mi.)***	***BB683***	***1939***
GANSEVOORT CORPERATI EPA Id: NYR000124727	***652 HUDSON ST***	***S 1/8 - 1/4 (0.191 mi.)***	***BC694***	***1970***
CON EDISON SERVICE B EPA Id: NYP004224234	***312 W 14TH ST & 8TH***	***SSE 1/8 - 1/4 (0.192 mi.)***	***AQ696***	***1980***
CON EDISON - GAS MAI	17 9TH AVE	SSW 1/8 - 1/4 (0.195 mi.)	AR714	2056

EPA Id: NYP004706669				
CON EDISON EPA Id: NYP004777918	258 W 20TH ST	E 1/8 - 1/4 (0.201 mi.)	BD723	2074
NYCTA - 14TH ST STAT EPA Id: NY0000973719	***14TH ST & 8TH AVE***	***SSE 1/8 - 1/4 (0.210 mi.)***	***BH752***	***2151***
CON EDISON EPA Id: NYP004729406	8TH AVE & W 14TH ST	SSE 1/8 - 1/4 (0.210 mi.)	BH756	2162
CON EDISON EPA Id: NYP004789400	8TH AVE & 14TH ST	SSE 1/8 - 1/4 (0.210 mi.)	BH757	2163
CON EDISON - TRANSFO EPA Id: NYP004852667	73 8TH AVE	SSE 1/8 - 1/4 (0.210 mi.)	AQ761	2172
CON EDISON - SERVICE EPA Id: NYP004858819	320 W 23 ST	ENE 1/8 - 1/4 (0.211 mi.)	AZ765	2181
CON EDISON EPA Id: NYP004792693	22ND ST & 8TH AVE	ENE 1/8 - 1/4 (0.215 mi.)	AZ797	2247
CON EDISON EPA Id: NYP004837977	250 W 17TH ST	SE 1/8 - 1/4 (0.227 mi.)	BF840	2388
CON EDISON EPA Id: NYP004726881	266-264 W 22ND ST &	E 1/8 - 1/4 (0.233 mi.)	BQ866	2447
CON EDISON - SERVICE EPA Id: NYP004863813	242 W 16 ST	SE 1/8 - 1/4 (0.234 mi.)	BO877	2482
CON EDISON SERVICE B EPA Id: NYP004290805	445 W 24TH ST	NNE 1/8 - 1/4 (0.237 mi.)	BR887	2509
CON EDISON EPA Id: NYP004728648	262 W 22ND ST	E 1/8 - 1/4 (0.240 mi.)	BQ903	2578
CON EDISON MANHOLE 2 EPA Id: NYP004234829	***246 W 14TH ST & 8 AV***	***SSE 1/8 - 1/4 (0.248 mi.)***	***BH926***	***2632***
CON EDISON EPA Id: NYP004793493	W 23RD ST & 8TH AVE	ENE 1/8 - 1/4 (0.248 mi.)	BX927	2636
MTA NYCT - 23RD STRE EPA Id: NYR000168245	23RD ST & 8TH AVE	ENE 1/8 - 1/4 (0.248 mi.)	BX935	2652

Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
CON EDISON EPA Id: NYP004777686	440 W 16TH ST	SW 0 - 1/8 (0.009 mi.)	C41	134
CON EDISON EPA Id: NYP004798542	437 W 16TH ST	WSW 0 - 1/8 (0.011 mi.)	C58	190
CON EDISON SERVICE B EPA Id: NYP004277083	434-436 W 20TH ST &	N 0 - 1/8 (0.021 mi.)	E89	262
CON EDISON - MANHOLE EPA Id: NYP004868594	460-454 W 16TH ST	WSW 0 - 1/8 (0.026 mi.)	C105	301
CON EDISON - MANHOLE EPA Id: NYP004866644	412 W 15TH ST	SW 0 - 1/8 (0.065 mi.)	K200	494
CON EDISON EPA Id: NYP004172425	***440 W 15TH ST***	***SW 0 - 1/8 (0.066 mi.)***	***K209***	***508***
CON EDISON	10TH AVE & 16TH ST	W 0 - 1/8 (0.069 mi.)	Q226	550

EPA Id: NYP004798732				
NORTHEAST LABORATORY EPA Id: NYD987017514	***99 10TH AVE ROOM 721***	***W 0 - 1/8 (0.095 mi.)***	***Q326***	***778***
HLP PROPERTIES LOT EPA Id: NYR000194449	501-515 W 17TH ST	WNW 0 - 1/8 (0.099 mi.)	U339	832
CON EDISON - TRANSFO EPA Id: NYP004861403	WASHINGTON ST & W 14	SW 0 - 1/8 (0.109 mi.)	W387	934
CON EDISON EPA Id: NYP004725354	500 W 21ST ST	NNW 0 - 1/8 (0.114 mi.)	AA409	992
CON EDISON SERVICE B EPA Id: NYP004280889	W 21ST ST & 10 TH AV	NNW 0 - 1/8 (0.116 mi.)	AA420	1016
CON EDISON SERVICE B EPA Id: NYP004258729	525 W 18TH ST E OF 1	NW 0 - 1/8 (0.119 mi.)	U436	1071
CON EDISON SERVICE B EPA Id: NYP004264826	55 10TH AVE N OF 34T	WSW 1/8 - 1/4 (0.161 mi.)	AM564	1524
CON EDISON EPA Id: NYP004171013	***42 10TH AVE***	***WSW 1/8 - 1/4 (0.179 mi.)***	***AS641***	***1792***
CON EDISON SERVICE B EPA Id: NYP004276382	W 10TH AVE & 23RD ST	N 1/8 - 1/4 (0.195 mi.)	BA711	2048
CON EDISON - SERVICE EPA Id: NYP004171062	51 LITTLE W12TH ST.	SW 1/8 - 1/4 (0.207 mi.)	AS743	2123
CON EDISON EPA Id: NYP004171377	***58 LITTLE W 12TH ST***	***SW 1/8 - 1/4 (0.222 mi.)***	***BL819***	***2312***
CON EDISON - SERVICE EPA Id: NYP004171047	***44 LITTLE W12TH ST.***	***SW 1/8 - 1/4 (0.223 mi.)***	***BL828***	***2341***

RI MANIFEST: Hazardous waste manifest information

A review of the RI MANIFEST list, as provided by EDR, and dated 12/31/2020 has revealed that there is 1 RI MANIFEST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
JEAN'S MANHATTAN CLE EPA Id: NYR000104232 Manifest Document Number: 001929972SKS	***198 9TH AVE***	***NE 1/8 - 1/4 (0.130 mi.)***	***AB462***	***1160***

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 06/30/2018 has revealed that there are 10 PA MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
RITE AID # 4196 Generator EPA Id: NYR000188623	188 9TH AVENUE	NE 0 - 1/8 (0.098 mi.)	P335	818
401 WEST 14TH STREET Generator EPA Id: NYR000141937	401 WEST 14TH STREET	SSW 0 - 1/8 (0.099 mi.)	S342	843
RITE AID # 10531	195 8TH AVENUE	E 1/8 - 1/4 (0.177 mi.)	AN632	1767

Generator EPA Id: NYR000188748				
CVS # 01618 Generator EPA Id: NYR000193383	81 8TH AVENUE	SSE 1/8 - 1/4 (0.192 mi.)	BB702	2007

Lower Elevation	Address	Direction / Distance	Map ID	Page
85TH AVENUE ASSOCIAT Generator EPA Id: NYR000099978	85TH 10TH AVE	W 0 - 1/8 (0.091 mi.)	Q305	718
HFZ HIGHLINE PROPERT Generator EPA Id: NYR000203869	505 W. 19TH STREET	NW 0 - 1/8 (0.110 mi.)	Z391	940
76 ELEVENTH AVENUE P Generator EPA Id: NYR000227256	76 11TH AVENUE	NW 1/8 - 1/4 (0.155 mi.)	AK545	1453
GREENWAY MEWS REALTY Generator EPA Id: NYR000200550	416 WEST 13TH STREET	SSW 1/8 - 1/4 (0.176 mi.)	AV624	1747
CVS # 10041 Generator EPA Id: NYR000198234	500 W 23RD ST	N 1/8 - 1/4 (0.186 mi.)	BA676	1914
CON EDISON - 12TH ST Generator EPA Id: NYP004713335	13 LITTLE W 12TH ST	SSW 1/8 - 1/4 (0.201 mi.)	AV727	2083

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there are 3 EDR MGP sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - WEST 18	WEST 16TH - WEST 20T	NW 0 - 1/8 (0.087 mi.)	I295	693
19TH STREET DEVELOPM	80 11TH AVENUE	NW 1/8 - 1/4 (0.158 mi.)	AK553	1482
CON EDISON - 19TH ST	11TH AVE BETWEEN W 1	NW 1/8 - 1/4 (0.196 mi.)	AY716	2059

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past

sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 8 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
AABIS SERVICE STATIO	65 9TH AVE	SSW 0 - 1/8 (0.064 mi.)	J197	486
ABBIS	55 NINTH AV	SSW 0 - 1/8 (0.094 mi.)	S325	778
ROJAS RAFAEL	331 W 16TH ST	SSE 0 - 1/8 (0.101 mi.)	L350	854

Lower Elevation	Address	Direction / Distance	Map ID	Page
MIDTOWN SERVICE CENT	436 W 18TH ST	WNW 0 - 1/8 (0.002 mi.)	A17	93
ALJOBET AUTOMATIC TR	435 WEST 18TH ST	NW 0 - 1/8 (0.016 mi.)	E76	231
AA AAAA 24 HOUR EMRG	152 10TH AVE	NNW 0 - 1/8 (0.081 mi.)	N268	640
D VITANZA REPAIR & S	165 10TH AVE	NNW 0 - 1/8 (0.104 mi.)	N360	869
CHELSEA CAR WASH	70 10TH AVE	WSW 0 - 1/8 (0.109 mi.)	V382	928

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 5 EDR Hist Cleaner sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BARBARA DRY CLEANERS	126 9TH AVE	ESE 0 - 1/8 (0.018 mi.)	A84	256
YAU CLEANERS	150 9TH AVE	ENE 0 - 1/8 (0.020 mi.)	B85	257
APHRODITE FRENCH CLE	182 9TH AVE	NE 0 - 1/8 (0.086 mi.)	P293	691
CHELSEA TAILOR	186 9TH AVE	NE 0 - 1/8 (0.096 mi.)	P330	804

Lower Elevation	Address	Direction / Distance	Map ID	Page
COE BRANDT CAREFUL	419 423 E 18TH TEL M	NW 0 - 1/8 (0.006 mi.)	A27	114

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 10 records.

Site Name	Database(s)
HOSPITAL FOR JOINT DISEASES	PRP
TOTTENVILLE COPPER CO.	SEMS-ARCHIVE, LEAD SMELTERS
JACKSON STREET ROW BETWEEN 7TH & 8	NJ SHWS, NJ ENG CONTROLS
TARRAGON CORPORATION BLOCK 103	NJ SHWS, NJ ENG CONTROLS
WEST 29TH STREET GW	NY SHWS
CE - E. 21ST ST. WORKS	NY SHWS
WEST 9TH STREET GW	NY SHWS
NYC STEAM PIPE RUPTURE 2018	SEMS, FINDS
NYC DOS WEST 30TH STREET RECYCLING	NY SWF/LF
PROPOSED FEDERAL EXPRESS DISTRIBUT	NY VCP

OVERVIEW MAP - 6920743.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

0 1/4 1/2 1 Miles

Indian Reservations BIA

County Boundary

Power transmission lines

Special Flood Hazard Area (1%)

0.2% Annual Chance Flood Hazard

National Wetland Inventory

State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Fulton	CLIENT:	Hillmann Environmental Co.
ADDRESS:	401w16th St, 400 W17th St, 420w18th St, 420w19thst New York NY 10011	CONTACT:	Joanne Bedkowski
LAT/LONG:	40.743633 / 74.004304	INQUIRY #:	6920743.2s
		DATE:	March 31, 2022 6:42 am

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 6920743.2S



0 1/16 1/8 1/4 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Fulton	CLIENT:	Hillmann Environmental Co.
ADDRESS:	401w16th St, 400 W17th St, 420w18th St, 420w19thst New York NY 10011	CONTACT:	Joanne Bedkowski
LAT/LONG:	40.743633 / 74.004304	INQUIRY #:	6920743.2s
		DATE:	March 31, 2022 6:43 am

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	1	0	0	NR	1
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	1	0	NR	NR	1
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		0	0	2	NR	NR	2
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	0	0	NR	0
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		14	22	NR	NR	NR	36
RCRA-SQG	0.250		5	4	NR	NR	NR	9
RCRA-VSQG	0.250		11	15	NR	NR	NR	26
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	1	0	NR	NR	1
US INST CONTROLS	0.500		0	1	0	NR	NR	1
Federal ERNS list								
ERNS	0.001		0	NR	NR	NR	NR	0
Lists of state- and tribal hazardous waste facilities								
NY SHWS	1.000		0	1	0	3	NR	4
NJ SHWS	1.000		0	0	0	3	NR	3
Lists of state and tribal landfills and solid waste disposal facilities								
NY SWF/LF	0.500		0	0	1	NR	NR	1
NJ SWF/LF	0.500		0	0	0	NR	NR	0
Lists of state and tribal leaking storage tanks								
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY LTANKS	0.500		15	38	79	NR	NR	132
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
NY UST	0.250		24	37	NR	NR	NR	61
NJ UST	0.250		0	0	NR	NR	NR	0
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY MOSF	0.500		0	0	0	NR	NR	0
NY CBS	0.250		1	1	NR	NR	NR	2
NY AST	0.250		40	79	NR	NR	NR	119
NY CBS AST	0.250		0	1	NR	NR	NR	1
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	1	NR	NR	NR	1
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		1	3	0	NR	NR	4
NJ ENG CONTROLS	0.500		0	0	0	NR	NR	0
NY INST CONTROL	0.500		1	3	0	NR	NR	4
NJ INST CONTROL	0.500		0	0	0	NR	NR	0
Lists of state and tribal voluntary cleanup sites								
NY VCP	0.500		1	5	14	NR	NR	20
INDIAN VCP	0.500		0	0	0	NR	NR	0
NJ VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
NY BROWNFIELDS	0.500		2	4	6	NR	NR	12
NJ BROWNFIELDS	0.500		0	0	0	NR	NR	0
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	1	0	NR	NR	1
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWRCY	0.500		0	0	0	NR	NR	0
NY SWTIRE	0.500		0	0	0	NR	NR	0
NJ SWRCY	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	0.001		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	0.001		0	NR	NR	NR	NR	0
NY PFAS	0.500		0	0	0	NR	NR	0
NJ PFAS	0.500		0	0	0	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0
NY HIST AST	0.001		0	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	0.001		0	NR	NR	NR	NR	0
NJ LIENS	0.001		0	NR	NR	NR	NR	0
LIENS 2	0.001		0	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	0.001		0	NR	NR	NR	NR	0
NY Spills	0.125	1	92	NR	NR	NR	NR	93
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NJ SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
NJ SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		101	140	NR	NR	NR	241
FUDS	1.000		0	0	0	2	NR	2
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	0.001		0	NR	NR	NR	NR	0
EPA WATCH LIST	0.001		0	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	0.001		0	NR	NR	NR	NR	0
TRIS	0.001		0	NR	NR	NR	NR	0
SSTS	0.001		0	NR	NR	NR	NR	0
ROD	1.000		0	1	0	0	NR	1
RMP	0.001		0	NR	NR	NR	NR	0
RAATS	0.001		0	NR	NR	NR	NR	0
PRP	0.001		0	NR	NR	NR	NR	0
PADS	0.001		0	NR	NR	NR	NR	0
ICIS	0.001		0	NR	NR	NR	NR	0
FTTS	0.001		0	NR	NR	NR	NR	0
MLTS	0.001		0	NR	NR	NR	NR	0
COAL ASH DOE	0.001		0	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	0.001		0	NR	NR	NR	NR	0
RADINFO	0.001		0	NR	NR	NR	NR	0
HIST FTTS	0.001		0	NR	NR	NR	NR	0
DOT OPS	0.001		0	NR	NR	NR	NR	0
CONSENT	1.000		0	1	0	0	NR	1
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	1	NR	1

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	0.001		0	NR	NR	NR	NR	0
US AIRS	0.001		0	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	0.001		5	NR	NR	NR	NR	5
ECHO	0.001		5	NR	NR	NR	NR	5
UXO	1.000		0	0	0	0	NR	0
DOCKET HWC	0.001		0	NR	NR	NR	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
NY AIRS	0.001		0	NR	NR	NR	NR	0
NJ AIRS	0.001		0	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NJ COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		2	6	NR	NR	NR	8
NJ DRYCLEANERS	0.250		0	0	NR	NR	NR	0
NY E DESIGNATION	0.125		23	NR	NR	NR	NR	23
NJ Financial Assurance	0.001		0	NR	NR	NR	NR	0
NY Financial Assurance	0.001		0	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	1	NR	NR	1
NY MANIFEST	0.250	1	167	204	NR	NR	NR	372
NJ MANIFEST	0.250		35	42	NR	NR	NR	77
RI MANIFEST	0.250		0	1	NR	NR	NR	1
PA MANIFEST	0.250		4	6	NR	NR	NR	10
NY SPDES	0.001		0	NR	NR	NR	NR	0
NJ NPDES	0.001		0	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	0.001		0	NR	NR	NR	NR	0
NJ UIC	0.001		0	NR	NR	NR	NR	0
NY COOLING TOWERS	0.001		0	NR	NR	NR	NR	0
NY LEAD	0.001		0	NR	NR	NR	NR	0
MINES MRDS	0.001		0	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		1	2	0	0	NR	3
EDR Hist Auto	0.125		8	NR	NR	NR	NR	8
EDR Hist Cleaner	0.125		5	NR	NR	NR	NR	5
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	0.001		0	NR	NR	NR	NR	0
NJ RGA HWS	0.001		0	NR	NR	NR	NR	0
NY RGA LF	0.001		0	NR	NR	NR	NR	0
NJ RGA LF	0.001		0	NR	NR	NR	NR	0
- Totals --		2	563	622	103	9	0	1299

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **CON EDISON** **NY MANIFEST** **S117535734**
Target **F/O 420 WEST 18 ST** **N/A**
Property **NEW YORK, NY 10011**

Site 1 of 19 in cluster A

Actual:
14 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	F/O 420 WEST 18 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004680872
Facility Status:	Not reported
Location Address 1:	F/O 420 WEST 18 ST
Code:	BP
Location Address 2:	VAULT 5389
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004680872
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	10/20/2014
Trans1 Recv Date:	10/20/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/27/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004680872
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002609456GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117535734**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	800
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A2 **RESIDENTIAL** **NY Spills** **S126399841**
Target **400 WEST 17TH ST** **N/A**
Property **MANHATTAN, NY**

Site 2 of 19 in cluster A

Actual: **14 ft.**

SPILLS:

Name:	RESIDENTIAL
Address:	400 WEST 17TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	2001535 / 2020-08-05
Facility ID:	2001535
Facility Type:	ER
DER Facility ID:	554638
Site ID:	606183
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2020-06-02
Investigator:	RJFENG
Referred To:	Not reported
Reported to Dept:	2020-06-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

RESIDENTIAL (Continued) **S126399841**

Remediation Phase:	0
Date Entered In Computer:	2020-06-02
Spill Record Last Update:	2020-08-05
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ROBERTO GARCIA
DEC Memo:	"8/5/2020 - Feng - Desk Duty. Spoke to Roberto Garcia. On 6/2/2020, there was backup wastewater into the building. The building management hired a company to pump out the wastewater. The hose leaked wastewater to the lobby, sidewalk and street (about 12 feet long puddle). At the end, they cleaned up with the absorbent pads and left it in the corner. He complained that they had to walk on the wastewater and the super ignored him. I Recommended him to report to NYCDEP since it is related to wastewater/sewer water discharge. Roberto Garcia 917-558-6819 The wastewater has been cleaned up. No spill of any oil related product. No further action is required by NYSDEC. Spill is closed. "
Remarks:	"UNKNOWN AMOUNT CLEAN UP PENDING"

All Materials:

Site ID:	606183
Operable Unit ID:	1353353
Operable Unit:	01
Material ID:	2364311
Material Code:	0060A
Material Name:	wastewater
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

NPL **HUDSON RIVER PCBS** **NPL** **1000384273**
Region **NO STREET APPLICABLE** **SEMS** **NYD980763841**
West **HUDSON RIVER, NY 12871** **RCRA-LQG**
1/8-1/4 **US ENG CONTROLS**
1292 ft. **US INST CONTROLS**
NY Spills
ROD
PRP
CONSENT

NPL:

EPA Region:	2
EPA ID:	NYD980763841
Site ID:	202229
Name:	HUDSON RIVER PCBS
Address:	NO STREET APPLICABLE
City,State,Zip:	HUDSON RIVER, NY 12871
Federal:	N
Final Date:	1984-09-21 00:00:00
Latitude:	43.1102
Longitude:	-73.5765
Site Score:	54.659999999999997

HUDSON RIVER PCBS (Continued) **1000384273**

NAI: Not reported
Native American Entity: Not reported

NPL:
NPL Status: Currently on the Final NPL
Substance ID: Not reported
CAS Number: Not reported
Substance: Not reported
Pathway: Not reported
Scoring: Not reported

NPL Status: Currently on the Final NPL
Substance ID: A046
CAS Number: 1336-36-3
Substance: POLYCHLORINATED BIPHENYLS
Pathway: AIR PATHWAY
Scoring: 4

NPL Status: Currently on the Final NPL
Substance ID: A046
CAS Number: 1336-36-3
Substance: POLYCHLORINATED BIPHENYLS
Pathway: SURFACE WATER PATHWAY
Scoring: 4

Summary Details:

Conditions at listing September 1983): The Hudson River PCBs Site is a 40-mile stretch of the Hudson River between Mechanicville and Fort Edward, New York. General Electric Co. discharged an estimated l.l million pounds of PCBs into this stretch of river. The State has identified 40 hot spots, defined as sediments contaminated with greater than 50 parts per million ppm) of PCBs. Also included in the site are five remnant areas, which are river sediments exposed when thelevel of the river was lowered due to removal of the Fort Edward Dam. The State has taken initial measures to stabili e the remnant areas from erosion. In September 1980, Congress passed an amendment to the Clean Water Act CWA) that included the Hudson River PCB Reclamation Demonstration Project. Under this legislation, the EPA Administrator could authori e a 75 percent grant, not to exceed 20 million. EPA issued a final Environmental Impact Statement in October 1982 evaluating various dredging alternatives for a demonstration project. EPA has prepared a feasibility study to evaluate alternative remedial actions under CERCLA. The Administrator has determined that CERCLA funds may be used for remedial action atthe remnant areas and for evaluating the effectiveness of the water supply system at Waterford, New York. Status June 1984): EPA has completed a draft feasibility study identifying alternatives for remedial action. A search for partiespotentially responsible for wastes associated with the site has been completed, and EPA has sent letters to two potentially responsible parties notifying them of possible legal action under CERCLA.

NPL:
NPL Status: Currently on the Final NPL
Category Description: Depth To Aquifer-<= 10 Feet
Category Value: 0

NPL Status: Currently on the Final NPL
Category Description: Distance To Nearest Population-> 0 And <= 1/4 Mile
Category Value: 10

HUDSON RIVER PCBS (Continued) **1000384273**

NPL:
NPL Name: HUDSON RIVER PCBS

NPL:
EPA Region: 02
Site ID: 0202229
Site Status: F
Federal Site: N
Date Deleted: Not reported
Date Finalized: 09/21/84
Date Proposed: 09/08/83

NPL:
Proposed Date: 09/08/1983
Final Date: 09/21/1984
Deleted Date: Not reported
NPL Status: Final

SEMS:
Site ID: 0202229
EPA ID: NYD980763841
Name: HUDSON RIVER PCBS
Address: NO STREET APPLICABLE
Address 2: Not reported
City,State,Zip: HUDSON RIVER, NY 12871-2834
Cong District: 21
FIPS Code: 36115
Latitude: +43.110200
Longitude: -073.576500
FF: N
NPL: Currently on the Final NPL
Non NPL Status: Not reported

SEMS Detail:
Region: 02
Site ID: 0202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 03
Action Code: RS
Action Name: RV ASSESS
SEQ: 4
Start Date: 1998-10-14 04:00:00
Finish Date: 1/7/1999 5:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N

HUDSON RIVER PCBS (Continued) **1000384273**

OU: 00
Action Code: MA
Action Name: ST COOP
SEQ: 2
Start Date: 1991-02-22 05:00:00
Finish Date: 4/3/2007 4:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 00
Action Code: NP
Action Name: PROPOSED
SEQ: 1
Start Date: 1983-09-08 04:00:00
Finish Date: 9/8/1983 4:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: 1983-09-01 04:00:00
Finish Date: 9/1/1983 4:00:00 AM
Qual: L
Current Action Lead: EPA Perf

Region: 02
Site ID: 0202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 00
Action Code: SI
Action Name: SI
SEQ: 1
Start Date: 1983-08-01 04:00:00
Finish Date: 9/1/1983 4:00:00 AM
Qual: H
Current Action Lead: EPA Perf

Region: 02
Site ID: 0202229
EPA ID: NYD980763841

HUDSON RIVER PCBS (Continued) **1000384273**

Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	03
Action Code:	RV
Action Name:	RMVL
SEQ:	1
Start Date:	1999-10-06 04:00:00
Finish Date:	9/14/2001 4:00:00 AM
Qual:	S
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	03
Action Code:	RS
Action Name:	RV ASSESS
SEQ:	2
Start Date:	1992-11-19 05:00:00
Finish Date:	12/1/1992 5:00:00 AM
Qual:	S
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	01
Action Code:	RD
Action Name:	RD
SEQ:	2
Start Date:	1989-02-02 05:00:00
Finish Date:	6/5/1989 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	01
Action Code:	CO
Action Name:	RI/FS
SEQ:	1
Start Date:	1984-03-30 06:00:00
Finish Date:	9/25/1984 5:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf

HUDSON RIVER PCBS (Continued) **1000384273**

Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	00
Action Code:	TG
Action Name:	TA GRANT
SEQ:	1
Start Date:	1995-09-29 04:00:00
Finish Date:	9/20/2005 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	00
Action Code:	CR
Action Name:	CI
SEQ:	2
Start Date:	2002-03-25 05:00:00
Finish Date:	11/2/2006 5:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1983-07-01 04:00:00
Finish Date:	7/1/1983 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	00
Action Code:	CR
Action Name:	CI
SEQ:	3
Start Date:	2005-11-07 05:00:00
Finish Date:	Not reported

HUDSON RIVER PCBS (Continued) **1000384273**

Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 02
Action Code: AR
Action Name: ADMIN REC
SEQ: 1
Start Date: 1992-04-24 04:00:00
Finish Date: Not reported
Qual: E
Current Action Lead: EPA Perf

Region: 02
Site ID: 0202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 00
Action Code: NF
Action Name: NPL FINL
SEQ: 1
Start Date: 1984-09-21 05:00:00
Finish Date: 9/21/1984 5:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 02
Action Code: CO
Action Name: RI/FS
SEQ: 2
Start Date: 1990-07-25 04:00:00
Finish Date: 2/1/2002 5:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 01
Action Code: RO
Action Name: ROD

HUDSON RIVER PCBS (Continued) **1000384273**

SEQ: 1
Start Date: 1984-09-25 05:00:00
Finish Date: 9/25/1984 5:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 02
Action Code: RO
Action Name: ROD
SEQ: 2
Start Date: 2002-02-01 05:00:00
Finish Date: 2/1/2002 5:00:00 AM
Qual: R
Current Action Lead: EPA Perf

Region: 02
Site ID: 0202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 00
Action Code: CR
Action Name: CI
SEQ: 1
Start Date: 1991-09-30 04:00:00
Finish Date: Not reported
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 03
Action Code: RS
Action Name: RV ASSESS
SEQ: 3
Start Date: 1998-06-03 04:00:00
Finish Date: 6/24/1999 4:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N

HUDSON RIVER PCBS (Continued) **1000384273**

OU:	00
Action Code:	RS
Action Name:	RV ASSESS
SEQ:	1
Start Date:	1990-04-17 04:00:00
Finish Date:	8/21/1990 4:00:00 AM
Qual:	S
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	02
Action Code:	RA
Action Name:	RA
SEQ:	2
Start Date:	2008-05-09 04:00:00
Finish Date:	11/24/2009 5:00:00 AM
Qual:	FR
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	00
Action Code:	SS
Action Name:	ESI RI
SEQ:	1
Start Date:	2002-06-30 04:00:00
Finish Date:	8/31/2005 4:00:00 AM
Qual:	W
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	00
Action Code:	FE
Action Name:	5 YEAR
SEQ:	1
Start Date:	2012-06-01 05:00:00
Finish Date:	6/1/2012 5:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0202229
EPA ID:	NYD980763841

HUDSON RIVER PCBS (Continued) **1000384273**

Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	00
Action Code:	AR
Action Name:	ADMIN REC
SEQ:	2
Start Date:	2000-03-28 05:00:00
Finish Date:	Not reported
Qual:	V
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	00
Action Code:	FE
Action Name:	5 YEAR
SEQ:	2
Start Date:	2016-03-29 05:00:00
Finish Date:	4/11/2019 5:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	02
Action Code:	RA
Action Name:	RA
SEQ:	3
Start Date:	2008-12-04 05:00:00
Finish Date:	12/23/2009 5:00:00 AM
Qual:	FR
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	00
Action Code:	EL
Action Name:	PRP CR
SEQ:	1
Start Date:	1989-07-07 04:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght

HUDSON RIVER PCBS (Continued) **1000384273**

Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	01
Action Code:	BE
Action Name:	PRP RD
SEQ:	2
Start Date:	1989-09-27 04:00:00
Finish Date:	9/28/1990 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Ovrsght

Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	01
Action Code:	BE
Action Name:	PRP RD
SEQ:	1
Start Date:	1989-05-18 04:00:00
Finish Date:	1/7/1991 5:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Ovrsght

Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	01
Action Code:	BF
Action Name:	PRP RA
SEQ:	1
Start Date:	1989-10-13 04:00:00
Finish Date:	9/29/1992 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Ovrsght

Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	02
Action Code:	BF
Action Name:	PRP RA
SEQ:	3
Start Date:	2005-09-06 04:00:00
Finish Date:	9/4/2012 5:00:00 AM

HUDSON RIVER PCBS (Continued) **1000384273**

Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	02
Action Code:	BF
Action Name:	PRP RA
SEQ:	4
Start Date:	2010-12-31 05:00:00
Finish Date:	4/11/2019 5:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	01
Action Code:	BF
Action Name:	PRP RA
SEQ:	2
Start Date:	1990-09-28 04:00:00
Finish Date:	9/29/1992 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	04
Action Code:	BD
Action Name:	PRP RI/FS
SEQ:	1
Start Date:	2008-09-08 04:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	00
Action Code:	PJ
Action Name:	RP EM REM

HUDSON RIVER PCBS (Continued) **1000384273**

SEQ: 1
Start Date: 2007-08-24 04:00:00
Finish Date: 8/27/2007 4:00:00 AM
Qual: C
Current Action Lead: EPA Ovrsght

Region: 02
Site ID: 0202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 02
Action Code: BE
Action Name: PRP RD
SEQ: 6
Start Date: 2003-08-14 04:00:00
Finish Date: 4/26/2011 5:00:00 AM
Qual: Not reported
Current Action Lead: EPA Ovrsght

Region: 02
Site ID: 0202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 02
Action Code: BE
Action Name: PRP RD
SEQ: 4
Start Date: 2003-08-14 04:00:00
Finish Date: 1/25/2008 5:00:00 AM
Qual: Not reported
Current Action Lead: EPA Ovrsght

Region: 02
Site ID: 0202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 02
Action Code: BE
Action Name: PRP RD
SEQ: 3
Start Date: 2002-07-23 04:00:00
Finish Date: Not reported
Qual: Not reported
Current Action Lead: EPA Ovrsght

Region: 02
Site ID: 0202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N

HUDSON RIVER PCBS (Continued) **1000384273**

OU:	04
Action Code:	BB
Action Name:	PRP RV
SEQ:	1
Start Date:	2007-09-11 04:00:00
Finish Date:	4/10/2012 4:00:00 AM
Qual:	S
Current Action Lead:	EPA Ovrsght
Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	02
Action Code:	OM
Action Name:	OM
SEQ:	1
Start Date:	2019-04-11 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	02
Site ID:	0202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	01
Action Code:	RD
Action Name:	RD
SEQ:	1
Start Date:	1984-09-28 05:00:00
Finish Date:	5/18/1990 4:00:00 AM
Qual:	Not reported
Current Action Lead:	St Perf

RCRA-LQG:

Date Form Received by Agency:	20180215
Handler Name:	GE HUDSON RIVER SEDIMENT REMEDIATION PROCESSING AND TRANSPORTATION FACILITY
Handler Address:	446 LOCK 8 WAY
Handler City,State,Zip:	HUDSON FALLS, NY 12839
EPA ID:	NYD980763841
Contact Name:	ROBERT G GIBSON
Contact Address:	RIVER ROAD
Contact City,State,Zip:	SCHENECTADY, NY 12345
Contact Telephone:	518-388-7505
Contact Fax:	Not reported
Contact Email:	BOB.GIBSON@GE.COM
Contact Title:	SENIOR PROJECT MANAGER
EPA Region:	02
Land Type:	Other
Federal Waste Generator Description:	Large Quantity Generator

HUDSON RIVER PCBS (Continued) **1000384273**

Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R5
Mailing Address:	RIVER ROAD
Mailing City,State,Zip:	SCHENECTADY, NY 12345
Owner Name:	SEE COMMENTS IN SECTION 18
Owner Type:	Other
Operator Name:	GENERAL ELECTRIC COMPANY
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No

HUDSON RIVER PCBS (Continued) **1000384273**

Significant Non-Complier With a Compliance Schedule Universe: No
Financial Assurance Required: Not reported
Handler Date of Last Change: 20181106
Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:
Year: 2013

Click Here for Biennial Reporting System Data:
Year: 2011

Click Here for Biennial Reporting System Data:
Year: 2009

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D006
Waste Description: CADMIUM

Waste Code: D007
Waste Description: CHROMIUM

Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: GENERAL ELECTRIC COMPANY
Legal Status: Private
Date Became Current: 20070423
Date Ended Current: Not reported
Owner/Operator Address: 1 RIVER ROAD
Owner/Operator City,State,Zip: SCHENECTADY, NY 12345
Owner/Operator Telephone: 518-388-7505
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: GENERAL ELECTRIC COMPANY
Legal Status: Private
Date Became Current: 20070423
Date Ended Current: Not reported
Owner/Operator Address: 9TH AVE SW
Owner/Operator City,State,Zip: CALGARY T2P 4Z4
Owner/Operator Telephone: Not reported

HUDSON RIVER PCBS (Continued) **1000384273**

Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	CANADIAN PACIFIC RR
Legal Status:	Private
Date Became Current:	20070423
Date Ended Current:	Not reported
Owner/Operator Address:	9TH AVE SW
Owner/Operator City,State,Zip:	CALGARY T2P 4Z4
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	GENERAL ELECTRIC COMPANY
Legal Status:	Private
Date Became Current:	20070423
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	USEPA
Legal Status:	Federal
Date Became Current:	20080604
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	SEE SECTION 11 COMMENTS
Legal Status:	State
Date Became Current:	20070502
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	NY
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	SEE COMMENTS IN SECTION 18
Legal Status:	Other
Date Became Current:	20070204
Date Ended Current:	Not reported

HUDSON RIVER PCBS (Continued) **1000384273**

Owner/Operator Address:	446 LOCK WAY
Owner/Operator City,State,Zip:	HUDSON FALLS, NY 12839
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	WCC LLC
Legal Status:	Private
Date Became Current:	20070402
Date Ended Current:	Not reported
Owner/Operator Address:	67 WILLOW GLEN
Owner/Operator City,State,Zip:	MECHANICVILLE, NY 12188
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	GE HUDSON RIVER SEDIMENT REMEDIATION
Legal Status:	Private
Date Became Current:	20070423
Date Ended Current:	Not reported
Owner/Operator Address:	381 BROADWAY
Owner/Operator City,State,Zip:	FORT EDWARD, NY 12828
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	GENERAL ELECTRIC CO
Legal Status:	Private
Date Became Current:	20070402
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	GE HUDSON RIVER SEDIMENT REMEDIATION
Legal Status:	Private
Date Became Current:	20070423
Date Ended Current:	Not reported
Owner/Operator Address:	381 BROADWAY
Owner/Operator City,State,Zip:	FORT EDWARD, NY 12828
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	CANADIAN PACIFIC RAILROAD

HUDSON RIVER PCBS (Continued) **1000384273**

Legal Status: Private
Date Became Current: 20070502
Date Ended Current: Not reported
Owner/Operator Address: 401 9TH AVE SW
Owner/Operator City,State,Zip: CALGARY, AB T2P4Z4
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20100303
Handler Name: GE HUDSON RIVER SEDIMENT REMEDIATION PROCESSING AND TRANSPORTATION FACILITY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20120301
Handler Name: GE HUDSON RIVER SEDIMENT REMEDIATION PROCESSING AND TRANSPORTATION FACILITY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140303
Handler Name: GE HUDSON RIVER SEDIMENT REMEDIATION PROCESSING AND TRANSPORTATION FACILITY
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20180215
Handler Name: GE HUDSON RIVER SEDIMENT REMEDIATION PROCESSING AND TRANSPORTATION FACILITY
Federal Waste Generator Description: Large Quantity Generator

HUDSON RIVER PCBS (Continued) **1000384273**

State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20060101
Handler Name: HUDSON RIVER PCBS (ROGERS ISLAND) USEPA
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: HUDSON RIVER PCBS (ROGERS ISLAND) USEPA
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080829
Handler Name: HUDSON RIVER PCBS (ROGERS ISLAND) SUPERFUND USEPA
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010101
Handler Name: HUDSON RIVER PCBS (ROGERS ISLAND) USEPA
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

HUDSON RIVER PCBS (Continued) **1000384273**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56291
NAICS Description: REMEDIATION SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

SIte:
Name: HUDSON RIVER PCBS
Address: NO STREET APPLICABLE
Address 2: Not reported
City,State,Zip: HUDSON RIVER, NY 12871-2834
Event Code: Not reported
Action Taken Date: 02/01/2002
EPA ID: NYD980763841
Action Name: Record of Decision
Action ID: 2
Operable Unit: 02
Contaminated Media: Sediment
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 2002
NPL Status: Currently on the Final NPL
Superfund Alternative Agreement: N
Latitude: +43.110200
Longitude: -073.576500

Media:
EPA ID: NYD980763841
Contaminated Media: Sediment
Action ID: 1
Operable Unit: 01
Action Name: Record of Decision
Action Taken Date: 09/25/1984
Event Code: Not reported
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 1984
NPL Status: Currently on the Final NPL
Superfund Alternative Agreement: N
Latitude: +43.110200
Longitude: -073.576500

HUDSON RIVER PCBS (Continued) **1000384273**

EPA ID:	NYD980763841
Contaminated Media:	Sediment
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/25/1984
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1984
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+43.110200
Longitude:	-073.576500

EPA ID:	NYD980763841
Contaminated Media:	Sediment
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/25/1984
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1984
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+43.110200
Longitude:	-073.576500

EPA ID:	NYD980763841
Contaminated Media:	Sediment
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/25/1984
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1984
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+43.110200
Longitude:	-073.576500

EPA ID:	NYD980763841
Contaminated Media:	Sediment
Action ID:	2
Operable Unit:	02
Action Name:	Record of Decision
Action Taken Date:	02/01/2002

HUDSON RIVER PCBS (Continued) **1000384273**

Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2002
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+43.110200
Longitude:	-073.576500

EPA ID:	NYD980763841
Contaminated Media:	Sediment
Action ID:	2
Operable Unit:	02
Action Name:	Record of Decision
Action Taken Date:	02/01/2002
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2002
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+43.110200
Longitude:	-073.576500

EPA ID:	NYD980763841
Contaminated Media:	Sediment
Action ID:	2
Operable Unit:	02
Action Name:	Record of Decision
Action Taken Date:	02/01/2002
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2002
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+43.110200
Longitude:	-073.576500

EPA ID:	NYD980763841
Contaminated Media:	Surface Water
Action ID:	2
Operable Unit:	02
Action Name:	Record of Decision
Action Taken Date:	02/01/2002
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2002

HUDSON RIVER PCBS (Continued) **1000384273**

NPL Status: Currently on the Final NPL
Superfund Alternative Agreement: N
Latitude: +43.110200
Longitude: -073.576500

EPA ID: NYD980763841
Contaminated Media: Surface Water
Action ID: 2
Operable Unit: 02
Action Name: Record of Decision
Action Taken Date: 02/01/2002
Event Code: Not reported
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 2002
NPL Status: Currently on the Final NPL
Superfund Alternative Agreement: N
Latitude: +43.110200
Longitude: -073.576500

EPA ID: NYD980763841
Contaminated Media: Sediment
Action ID: 2
Operable Unit: 02
Action Name: Record of Decision
Action Taken Date: 02/01/2002
Event Code: Not reported
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 2002
NPL Status: Currently on the Final NPL
Superfund Alternative Agreement: N
Latitude: +43.110200
Longitude: -073.576500

US INST CONTROLS:
Name: HUDSON RIVER PCBS
Address: NO STREET APPLICABLE
Address 2: Not reported
City,State,Zip: HUDSON RIVER, NY 12871-2834
EPA ID: NYD980763841
Action Name: Record of Decision
Action ID: 2
Operable Unit: 02
Actual Date: 02/01/2002
Contaminated Media: Surface Water
Event Code: Not reported
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 2002

HUDSON RIVER PCBS (Continued) **1000384273**

NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+43.110200
Longitude:	-073.576500

SPILLS:

Name:	HUDSON RIVER
Address:	HUDSON RIVER
City,State,Zip:	OSSINING, NY
Spill Number/Closed Date:	0308107 / 2003-10-31
Facility ID:	0308107
Facility Type:	ER
DER Facility ID:	278391
Site ID:	237813
DEC Region:	3
Spill Cause:	Abandoned Drums
Spill Class:	D4
SWIS:	6000
Spill Date:	2003-10-31
Investigator:	rxamato
Referred To:	Not reported
Reported to Dept:	2003-10-31
CID:	297
Water Affected:	HUDSON RIVER
Spill Source:	Unknown
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-31
Spill Record Last Update:	2003-11-06
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	PETTY OFFFICER HAWKINS
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SMITH 10/31/03: MEG hired by USCG to remove test and dispose. Container did not leak."
Remarks:	"CALL TO NRC REPORTING A 55 GALLON DRUM OF UNKNOWN PETROLEUM FLOATING - USCG IS REPOSNDING TO THE SITE"

All Materials:

Site ID:	237813
Operable Unit ID:	874400
Operable Unit:	01
Material ID:	501630
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	55.00
Units:	G
Recovered:	.00

HUDSON RIVER PCBS (Continued) **1000384273**

Oxygenate: Not reported

ROD:
Name: HUDSON RIVER PCBS
Address: NO STREET APPLICABLE
City,State,Zip: HUDSON RIVER, NY 12871
EPA ID: NYD980763841
RG: 2
Site ID: 202229
Action: GOVT Decision Document (ROD)
Operable Unit Number: REMNANT DEPOSIT CAPPING
SEQ ID: 1
Action Completion: 1984-09-25 00:00:00
NPL Status: Final
Non NPL Status: Not reported

Name: HUDSON RIVER PCBS
Address: NO STREET APPLICABLE
City,State,Zip: HUDSON RIVER, NY 12871
EPA ID: NYD980763841
RG: 2
Site ID: 202229
Action: GOVT Decision Document (ROD)
Operable Unit Number: REASSESSMENT RIVER
SEQ ID: 2
Action Completion: 2002-02-01 00:00:00
NPL Status: Final
Non NPL Status: Not reported

PRP:
PRP Name: DELAWARE AND HUDSON RAILWAY CO INC
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GOLUB PROPERTIES OF WATERVLIET INC
NEW YORK STATE CANAL CORPORATION
NIAGARA MOHAWK POWER COMPANY
TOWN OF HALFMOON NEW YORK
VILLAGE OF STILLWATER
WATER COMMISSIONERS OF THE TOWN OF WATERFORD

CONSENT:
EPA ID: NYD980763841
Site ID: 0284
Case Title: U.S.V. GENERAL ELECTRIC COMPANY (HUDSON RIVER) (EPA-SUPERFUND)
Court Num: 05-1270
District: New York, North
Entered Date: 11/02/06

HUDSON RIVER PCBS (Continued) **1000384273**

Name: HUDSON RIVER PCBS
Name: HUDSON RIVER PCBS
Address: NO STREET APPLICABLE
City,State,Zip: HUDSON RIVER, NY 12801
County: WASHINGTON

EPA ID: NYD980763841
Site ID: 0284
Case Title: U.S.V. GENERAL ELECTRIC COMPANY (HUDSON RIVER) (EPA-SUPERFUND)
Court Num: 05-1270
District: New York, North
Entered Date: 11/02/06
Name: HUDSON RIVER PCBS
Name: HUDSON RIVER PCBS
Address: NO STREET APPLICABLE
City,State,Zip: HUDSON RIVER, NY 12801
County: WASHINGTON

EPA ID: NYD980763841
Site ID: 0284
Case Title: U.S.V. GENERAL ELECTRIC COMPANY (HUDSON RIVER) (EPA-SUPERFUND)
Court Num: 05-1270
District: New York, North
Entered Date: 11/02/06
Name: HUDSON RIVER PCBS
Name: HUDSON RIVER PCBS
Address: NO STREET APPLICABLE
City,State,Zip: HUDSON RIVER, NY 12801
County: WASHINGTON

EPA ID: NYD980763841
Site ID: Not reported
Case Title: Not reported
Court Num: Not reported
District: Not reported
Entered Date: Not reported
Name: US V. GENERAL ELECTRIC COMPANY
Name: HUDSON RIVER PCBS
Address: NO STREET APPLICABLE
City,State,Zip: HUDSON RIVER, NY 12801
County: WASHINGTON

EPA ID: NYD980763841
Site ID: 0284
Case Title: U.S.V. GENERAL ELECTRIC COMPANY (HUDSON RIVER) (EPA-SUPERFUND)
Court Num: 05-1270
District: New York, North
Entered Date: 11/02/06
Name: HUDSON RIVER PCBS
Name: HUDSON RIVER PCBS
Address: NO STREET APPLICABLE
City,State,Zip: HUDSON RIVER, NY 12801
County: WASHINGTON

B3 **CON EDISON** **RCRA NonGen / NLR** **1019908745**
429 W 19TH ST **NYP004876890**
< 1/8 **NEW YORK, NY 10001**
1 ft.

Site 1 of 33 in cluster B

Relative: RCRA NonGen / NLR:
Higher

Date Form Received by Agency:		20151205
Handler Name:	CON EDISON	
Handler Address:		429 W 19TH ST
Handler City,State,Zip:		NEW YORK, NY 10001
EPA ID:		NYP004876890
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

Actual:
15 ft.

CON EDISON (Continued) **1019908745**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20151205
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20151205
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1019908745**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

B4 **CON EDISON VAULT: 9354** **RCRA NonGen / NLR** **1016968400**
419 W 19TH ST **NY MANIFEST** **NYP004420113**
< 1/8 **NEW YORK, NY 10011**
1 ft.

Site 2 of 33 in cluster B

Relative: Higher
Actual: 15 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20140216
Handler Name:	CON EDISON VAULT: 9354	
Handler Address:		419 W 19TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004420113
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No

CON EDISON VAULT: 9354 (Continued) **1016968400**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140116
Handler Name: CON EDISON VAULT: 9354	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CON EDISON VAULT: 9354 (Continued) **1016968400**

Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20140216
Handler Name: CON EDISON VAULT: 9354	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	419 W 19TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004420113
Facility Status:	Not reported
Location Address 1:	419 W 19TH ST
Code:	BP
Location Address 2:	SB9354
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004420113
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON VAULT: 9354 (Continued) **1016968400**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	01/16/2014
Trans1 Recv Date:	01/16/2014
Trans2 Recv Date:	01/17/2014
TSD Site Recv Date:	01/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004420113
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002328776GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A5 **CON EDISON SERVICE BOX: 3235** **RCRA NonGen / NLR** **1016449952**
424 W 18TH ST **NY MANIFEST** **NYP004256566**
< 1/8 **NEW YORK, NY 10011**
1 ft.

Site 3 of 19 in cluster A

Relative: RCRA NonGen / NLR:
Higher

Date Form Received by Agency:		20130319
Handler Name:	CON EDISON SERVICE BOX:	3235
Handler Address:		424 W 18TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004256566
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

Actual:
14 ft.

CON EDISON SERVICE BOX: 3235 (Continued) **1016449952**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130219
Handler Name: CON EDISON SERVICE BOX:	3235
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130319
Handler Name: CON EDISON SERVICE BOX:	3235
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 3235 (Continued) **1016449952**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	424 W 18TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004256566
Facility Status:	Not reported
Location Address 1:	424 W 18TH ST
Code:	BP
Location Address 2:	SERV BOX 3235
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004256566
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/19/2013
Trans1 Recv Date:	02/19/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/19/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004256566

CON EDISON SERVICE BOX: 3235 (Continued) **1016449952**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840424JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B6 **CON EDISON VAULT: 9354** **FINDS** **1017395495**
419 W 19TH ST **ECHO** **N/A**
< 1/8 **NEW YORK, NY 10011**
1 ft.

Site 3 of 33 in cluster B

Relative:
Higher

Actual:
15 ft.

FINDS:
Registry ID: 110062945595

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

CON EDISON VAULT: 9354 (Continued) **1017395495**

ECHO:
Envid: 1017395495
Registry ID: 110062945595
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110062945595
Name: CON EDISON VAULT: 9354
Address: 419 W 19TH ST
City,State,Zip: NEW YORK, NY 10011

A7 **CON EDISON SERVICE BOX: 3235** **FINDS** **1016439005**
424 W 18TH ST **ECHO** **N/A**
< 1/8 **NEW YORK, NY 10011**
1 ft.

Site 4 of 19 in cluster A

Relative: Higher
Actual: 14 ft.

FINDS:
Registry ID: 110055935939

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016439005
Registry ID: 110055935939
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055935939
Name: CON EDISON SERVICE BOX: 3235
Address: 424 W 18TH ST
City,State,Zip: NEW YORK, NY 10011

B8 **CON EDISON** **FINDS** **1018390232**
429 W 19TH ST **ECHO** **N/A**
< 1/8 **NEW YORK, NY 10001**
1 ft.

Site 4 of 33 in cluster B

Relative: Higher
Actual: 15 ft.

FINDS:
Registry ID: 110069696564

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON (Continued) **1018390232**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018390232
Registry ID:	110069696564
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069696564
Name:	CON EDISON
Address:	429 W 19TH ST
City,State,Zip:	NEW YORK, NY 10001

A9 **401-411 WEST 18TH STREET** **NY UST** **U004272337**
401-425 WEST 18TH STREET **N/A**
< 1/8 **MANHATTAN, NY 10011**
1 ft.

Site 5 of 19 in cluster A

Relative: Higher
Actual: 14 ft.

UST:

Name:	401-411 WEST 18TH STREET
Address:	401-425 WEST 18TH STREET
City,State,Zip:	MANHATTAN, NY 10011
Id/Status:	2-612757 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	Not reported
UTM Y:	Not reported
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	557127
Affiliation Type:	Facility Owner
Company Name:	18TH STREET FULTON EQUITIES LLC
Contact Type:	MANAGING MEMBER
Contact Name:	ROBERT EZRAPOUR
Address1:	316 WEST 118TH STREET
Address2:	Not reported
City:	MANHATTAN
State:	NY
Zip Code:	10026
Country Code:	001
Phone:	(646) 831-0749
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-29

Site Id:	557127
Affiliation Type:	Mail Contact
Company Name:	ARTIMUS
Contact Type:	Not reported
Contact Name:	ARTHUR DAVYDOV
Address1:	316 WEST 118TH STREET
Address2:	Not reported
City:	MANHATTAN
State:	NY
Zip Code:	10026

401-411 WEST 18TH STREET (Continued) **U004272337**

Country Code:	001
Phone:	(646) 831-0749
EMail:	ARTHUR@ARTIMUSNYC.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-29

Site Id:	557127
Affiliation Type:	Facility Operator
Company Name:	401-411 WEST 18TH STREET
Contact Type:	Not reported
Contact Name:	NELSON BERMEO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 291-3259
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-29

Site Id:	557127
Affiliation Type:	Emergency Contact
Company Name:	18TH STREET FULTON EQUITIES LLC
Contact Type:	Not reported
Contact Name:	NELSON BERMEO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(347) 291-3259
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-29

Tank Info:

Tank Number:	01
Tank ID:	270410
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1500
Install Date:	Not reported
Date Tank Closed:	06/05/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported

401-411 WEST 18TH STREET (Continued) **U004272337**

Modified By: MFLEONAR
Last Modified: 11/29/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None

B10 **CON EDISON** **NJ MANIFEST** **S120677964**
429 W 19TH ST **N/A**
< 1/8 **NEW YORK, NY 10001**
1 ft.

Site 5 of 33 in cluster B

Relative: Higher
Actual: 15 ft.

NJ MANIFEST:

EPA Id:	NYP004876890
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002613656GBF
EPA ID:	NYP004876890
Date Shipped:	12/5/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

CON EDISON (Continued) **S120677964**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

A11 **CON EDISON SERVICE BOX: 2996** **RCRA NonGen / NLR** **1016143001**
419 W 17TH ST **NY MANIFEST** **NYP004257309**
< 1/8 **NEW YORK, NY 10014**
1 ft.

Site 6 of 19 in cluster A

Relative: **Higher**
Actual: **14 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130320
Handler Name:	CON EDISON SERVICE BOX:	2996
Handler Address:		419 W 17TH ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004257309
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported

CON EDISON SERVICE BOX: 2996 (Continued) **1016143001**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON SERVICE BOX: 2996 (Continued) **1016143001**

Historic Generators:
Receive Date: 20130220
Handler Name: CON EDISON SERVICE BOX: 2996
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130320
Handler Name: CON EDISON SERVICE BOX: 2996
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 419 W 17TH ST
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYP004257309
Facility Status: Not reported
Location Address 1: 419 W 17TH ST
Code: BP
Location Address 2: SERV BOX 2996
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004257309

CON EDISON SERVICE BOX: 2996 (Continued) **1016143001**

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/20/2013
Trans1 Recv Date:	02/20/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/21/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004257309
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010846493JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON SERVICE BOX: 2996 (Continued) **1016143001**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

A12 **CON EDISON** **RCRA NonGen / NLR** **1014395682**
418 W 17TH ST **NJ MANIFEST** **NYP004171484**
< 1/8 **NEW YORK, NY 10014** **NY MANIFEST**
1 ft.

Site 7 of 19 in cluster A

Relative: Higher
Actual: 15 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		418 W 17TH ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004171484
Contact Name:		DAVID DUKE
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		917-559-8971
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported

CON EDISON (Continued) **1014395682**

Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160726
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090609
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON (Continued) **1014395682**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:
EPA Id: NYP004171484
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DAVID DUKE
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 003532084JJK
EPA ID: NYP004171484
Date Shipped: 06/09/2009
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 06/09/2009
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported

CON EDISON (Continued) **1014395682**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/09/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	500 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	418 W 17TH ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004171484
Facility Status:	Not reported
Location Address 1:	418 W 17TH ST.
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004171484
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	CONSOLIDATED EDISON
Mailing Address 1:	4 IRVINGPLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

CON EDISON (Continued) **1014395682**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/09/2009
Trans1 Recv Date:	06/09/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/09/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004171484
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003532084JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C13 **WEST 17TH STREET AND 10TH AVENUE** **NY ENG CONTROLS** **S109321176**
440-452 WEST 17TH ST., 445-459 WEST 16TH STREET, **NY INST CONTROL** **N/A**
< 1/8 **MANHATTAN, NY 10011** **NY BROWNFIELDS**
1 ft.

Site 1 of 29 in cluster C

Relative: **Lower**

Actual: **13 ft.**

ENG CONTROLS:

Name:	WEST 17TH STREET AND 10TH AVENUE
Address:	440-452 WEST 17TH ST., 445-459 WEST 16TH STREET,
City,State,Zip:	MANHATTAN, NY 10011
Site Code:	59118
HW Code:	C231040
Control Code:	15
Control Type:	ENG
Date Record Added:	10/15/2008
Date Rec Updated:	12/31/2021
Updated By:	SNBOLLER
Site Description:	"Location: The Site is located in an urban area of New York County (Manhattan) on the east side of 10th Avenue between W. 16th and W. 17th Streets (the site does not include the building on the southeast corner of 10th Ave. and W. 17th St.). Site Features: The former site features include several buildings and a paved parking lot. The site buildings were unused and were demolished. Past Uses: The most recent uses of the Site include a warehouse for electrical construction equipment; an electrical contractor area; a vehicle garage and outdoor parking area; an outdoor garden supplies store; a restaurant; auto body shop; and classroom space for a theater company. Prior uses include various freight and automobile uses, with underground fuel storage tanks, and unspecified manufacturing. Surrounding uses include multi-story residential buildings with and without lower-level commercial uses, parking, and playgrounds. The High Line , an elevated rail line which was used in the past for freight and is now unused, is to the west of and partially over the western end of the site (with aerial easement). An investigation pertaining to the removal of underground storage tanks occurred in the early 1990's. A Phase I and limited Phase II Environmental Site Assessment was performed in 2004. Operable Units: For remedial purposes, the site was divided into two Operable Units (OUs). An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 1 (OU1) is the eastern portion of the site which is fully occupied by the new residential building. Operable Unit 2 (OU2) is the High Line area that extends along 10th Avenue and the western portion of 16th Street. Site Geology and Hydrogeology: The generalized subsurface profile consists of urban fill overlying sand, with bedrock at depths between 40 and 70 feet below grade (ft-bg). The fill consisted of brown and grey, coarse to fine sand, some silt, gravel and brick fragments. Fill thickness ranged from about four to twelve feet. The thickness of the lower coarse to fine sand and gravelly sand ranges from 31 to 47 feet. The upper medium to fine sand extends typically to depths of about 20 ft-bg. Bedrock was encountered below the sand and consists of moderately fractured, medium-hard mica schist and moderately fractured, hard pegmatite. Bedrock was found at depths ranging from about 21 to 77 ft-bg. Bedrock is shallowest at the east end of the Site and slopes downward to the west toward the Hudson River. The net groundwater flow is to the west, toward the Hudson River. Depth to groundwater is 10 to 14 ft-bgs. "

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

Env Problem: "Nature and Extent of Contamination Prior to Remediation: Soil - Based on the investigations conducted at the site, the primary contaminants of concern were related to the past uses of petroleum, and to historic fill which was present across the entire site. The site soils were contaminated with volatile organic compounds (VOCs) related to petroleum (benzene, toluene, ethylbenzene, xylene, naphthalene) and, to a much lesser degree with chlorinated solvents (e.g. tetrachloroethene). Contaminants also included semi-volatile organic compounds of petroleum origin. Exceedances of applicable standards, criteria and guidance for soil were identified. Groundwater - Petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) were present at elevated levels of concentration in groundwater throughout the Site. Concentrations of VOCs above Class GA Standards included chloroform, BTEX compounds and methyl-tert butyl ether (MTBE). SVOCs were prevalent at concentrations above NYSDEC regulatory levels in the groundwater in the southern and western portions of the Site and included dibenzofuran, 2-methylnaphthalene and naphthalene. The VOCs and SVOCs appear to be related to the prior use of the Site for vehicle fueling and repair. Iron, magnesium, manganese and sodium, common earth minerals, were detected in concentrations exceeding groundwater standards in all of the filtered groundwater samples. Soil Vapor - During the remedial investigation, VOCs were detected across the Site in subsurface soil gas samples, as well as in the one ambient air sample. The highest concentration of VOCs was found at soil gas sample location FLS-4, collected at soil boring FLS-4. PID readings in boring FLS-4 peaked at 1,684 parts per million (ppm) at a depth of 16 ft-bg. Post Remediation: Remediation at the Site is complete. Prior to remediation, the primary contaminants of concern were petroleum related VOCs in soil and groundwater. Remedial actions have successfully achieved the site specific soil cleanup objectives. Residual contamination in the soil, groundwater and sub-slab vapor are being managed under a Site Management Plan. As part of the remediation, the petroleum contaminated soil and the historic fill was excavated from OU-1 and disposed of at regulated facilities. Groundwater was treated on site, and the clean effluent was discharged to the New York City sewer under a permit. The contaminated soil and groundwater in OU-2 were remediated through injection of ORC (Oxygen Release Compound) into the underlying groundwater and subsoil. The top one foot of soil in OU-2 was removed through excavation. A Track 4 cleanup was achieved for the site. Engineering and Institutional Controls have been instituted to manage the residual contamination. These controls have been memorialized in the Environmental Easement that has been recorded in the New York County Clerk’s office. The Certificate of Completion was issued on October 6, 2008. "

Health Problem: "Public water is provided to the area, thereby preventing exposures to groundwater. The remedial action work plan for the site calls for the removal of contaminated soil from the site prior to construction of a residential building on-site. Soil gas is contaminated by chlorinated solvents that are likely due to an off-site source. The site owner will include measures in the building construction to prevent soil vapor migration into the building."

Dump: False
Structure: False
Lagoon: False
Landfill: False

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	40.743291 / 74.007009
Dell:	False
Record Add:	2004-09-07 12:00:00
Record Upd:	2008-11-17 16:26:00
Updated By:	jdjarrat
Own Op:	1
Sub Type:	06
Owner Name:	C/O THE RELATED COMPANIES, LP
Owner Company:	17TH AND 10TH ASSOCIATES, LLC
Owner Address:	60 COLUMBUS CIRCLE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10023
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	NEW YORK PUBLIC LIBRARY
Owner Company:	WEST 17TH & 10TH ASSOCIATES, LLC
Owner Address:	MUHLENBERG BRANCH
Owner Addr2:	209 WEST 23RD STREET
Owner City,St,Zip:	NEW YORK, NY 10011
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Greg Gushee
Owner Company:	17TH AND 10TH ASSOCIATES, LLC
Owner Address:	THE RELATED COMPANIES, L.P.
Owner Addr2:	60 COLUMBUS CIRCLE
Owner City,St,Zip:	NEW YORK, NY 10023
Owner Country:	United States of America
HW Code:	C231040
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231040
Waste Type:	ETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231040
Waste Type:	NAPHTHALENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231040
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231040
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	W2-1034-04-11
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2008-11-17 14:24:00
Record Updated:	2008-11-18 09:25:00

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

Updated By:	jdjarrat
Crossref ID:	CRFN 2008000370558
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2008-11-17 16:28:00
Record Updated:	2008-11-17 16:28:00
Updated By:	jdjarrat
Crossref ID:	0401167
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2008-05-13 14:37:00
Record Updated:	2008-05-13 14:37:00
Updated By:	snboller
Name:	WEST 17TH STREET AND 10TH AVENUE
Address:	440-452 WEST 17TH ST., 445-459 WEST 16TH STREET,
City,State,Zip:	MANHATTAN, NY 10011
Site Code:	59118
HW Code:	C231040
Control Code:	13
Control Type:	ENG
Date Record Added:	10/15/2008
Date Rec Updated:	12/31/2021
Updated By:	SNBOLLER
Site Description:	"Location: The Site is located in an urban area of New York County (Manhattan) on the east side of 10th Avenue between W. 16th and W. 17th Streets (the site does not include the building on the southeast corner of 10th Ave. and W. 17th St.). Site Features: The former site features include several buildings and a paved parking lot. The site buildings were unused and were demolished. Past Uses: The most recent uses of the Site include a warehouse for electrical construction equipment; an electrical contractor area; a vehicle garage and outdoor parking area; an outdoor garden supplies store; a restaurant; auto body shop; and classroom space for a theater company. Prior uses include various freight and automobile uses, with underground fuel storage tanks, and unspecified manufacturing. Surrounding uses include multi-story residential buildings with and without lower-level commercial uses, parking, and playgrounds. The High Line , an elevated rail line which was used in the past for freight and is now unused, is to the west of and partially over the western end of the site (with aerial easement). An investigation pertaining to the removal of underground storage tanks occurred in the early 1990's. A Phase I and limited Phase II Environmental Site Assessment was performed in 2004. Operable Units: For remedial purposes, the site was divided into two Operable Units (OUs). An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 1 (OU1) is the eastern portion of the site which is fully occupied by the new residential building. Operable Unit 2 (OU2) is the High Line area that extends along 10th Avenue and the western portion of 16th Street. Site Geology and Hydrogeology: The generalized subsurface profile consists of urban fill overlying sand, with bedrock at depths between 40 and 70 feet below grade (ft-bg). The fill consisted of brown and grey, coarse to fine sand, some silt, gravel and brick fragments. Fill thickness ranged from about four to twelve feet. The

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

thickness of the lower coarse to fine sand and gravelly sand ranges from 31 to 47 feet. The upper medium to fine sand extends typically to depths of about 20 ft-bg. Bedrock was encountered below the sand and consists of moderately fractured, medium-hard mica schist and moderately fractured, hard pegmatite. Bedrock was found at depths ranging from about 21 to 77 ft-bg. Bedrock is shallowest at the east end of the Site and slopes downward to the west toward the Hudson River. The net groundwater flow is to the west, toward the Hudson River. Depth to groundwater is 10 to 14 ft-bgs. "

Env Problem: "Nature and Extent of Contamination Prior to Remediation: Soil - Based on the investigations conducted at the site, the primary contaminants of concern were related to the past uses of petroleum, and to historic fill which was present across the entire site. The site soils were contaminated with volatile organic compounds (VOCs) related to petroleum (benzene, toluene, ethylbenzene, xylene, naphthalene) and, to a much lesser degree with chlorinated solvents (e.g. tetrachloroethene). Contaminants also included semi-volatile organic compounds of petroleum origin. Exceedances of applicable standards, criteria and guidance for soil were identified.
Groundwater - Petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) were present at elevated levels of concentration in groundwater throughout the Site. Concentrations of VOCs above Class GA Standards included chloroform, BTEX compounds and methyl-tert butyl ether (MTBE). SVOCs were prevalent at concentrations above NYSDEC regulatory levels in the groundwater in the southern and western portions of the Site and included dibenzofuran, 2-methylnaphthalene and naphthalene. The VOCs and SVOCs appear to be related to the prior use of the Site for vehicle fueling and repair. Iron, magnesium, manganese and sodium, common earth minerals, were detected in concentrations exceeding groundwater standards in all of the filtered groundwater samples.
Soil Vapor - During the remedial investigation, VOCs were detected across the Site in subsurface soil gas samples, as well as in the one ambient air sample. The highest concentration of VOCs was found at soil gas sample location FLS-4, collected at soil boring FLS-4. PID readings in boring FLS-4 peaked at 1,684 parts per million (ppm) at a depth of 16 ft-bg. Post Remediation: Remediation at the Site is complete. Prior to remediation, the primary contaminants of concern were petroleum related VOCs in soil and groundwater. Remedial actions have successfully achieved the site specific soil cleanup objectives. Residual contamination in the soil, groundwater and sub-slab vapor are being managed under a Site Management Plan. As part of the remediation, the petroleum contaminated soil and the historic fill was excavated from OU-1 and disposed of at regulated facilities. Groundwater was treated on site, and the clean effluent was discharged to the New York City sewer under a permit. The contaminated soil and groundwater in OU-2 were remediated through injection of ORC (Oxygen Release Compound) into the underlying groundwater and subsoil. The top one foot of soil in OU-2 was removed through excavation. A Track 4 cleanup was achieved for the site. Engineering and Institutional Controls have been instituted to manage the residual contamination. These controls have been memorialized in the Environmental Easement that has been recorded in the New York County Clerk's office. The Certificate of Completion was issued on October 6, 2008. "

Health Problem: "Public water is provided to the area, thereby preventing exposures to groundwater. The remedial action work plan for the site calls for

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

the removal of contaminated soil from the site prior to construction of a residential building on-site. Soil gas is contaminated by chlorinated solvents that are likely due to an off-site source. The site owner will include measures in the building construction to prevent soil vapor migration into the building."

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	40.743291 / 74.007009
Dell:	False
Record Add:	2004-09-07 12:00:00
Record Upd:	2008-11-17 16:26:00
Updated By:	jdjarrat
Own Op:	1
Sub Type:	06
Owner Name:	C/O THE RELATED COMPANIES, LP
Owner Company:	17TH AND 10TH ASSOCIATES, LLC
Owner Address:	60 COLUMBUS CIRCLE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10023
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	NEW YORK PUBLIC LIBRARY
Owner Company:	WEST 17TH & 10TH ASSOCIATES, LLC
Owner Address:	MUHLENBERG BRANCH
Owner Addr2:	209 WEST 23RD STREET
Owner City,St,Zip:	NEW YORK, NY 10011
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Greg Gushee
Owner Company:	17TH AND 10TH ASSOCIATES, LLC
Owner Address:	THE RELATED COMPANIES, L.P.
Owner Addr2:	60 COLUMBUS CIRCLE
Owner City,St,Zip:	NEW YORK, NY 10023
Owner Country:	United States of America
HW Code:	C231040
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231040
Waste Type:	ETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231040
Waste Type:	NAPHTHALENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231040
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

HW Code:	C231040
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	W2-1034-04-11
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2008-11-17 14:24:00
Record Updated:	2008-11-18 09:25:00
Updated By:	jdjarrat
Crossref ID:	CRFN 2008000370558
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2008-11-17 16:28:00
Record Updated:	2008-11-17 16:28:00
Updated By:	jdjarrat
Crossref ID:	0401167
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2008-05-13 14:37:00
Record Updated:	2008-05-13 14:37:00
Updated By:	snboller

INST CONTROL:

Name:	WEST 17TH STREET AND 10TH AVENUE
Address:	440-452 WEST 17TH ST., 445-459 WEST 16TH STREET,
City,State,Zip:	MANHATTAN, NY 10011
Site Code:	59118
Control Name:	Ground Water Use Restriction
HW Code:	C231040
Control Code:	08
Control Type:	INST
Dt record added:	10/15/2008
Dt rec updated:	12/31/2021
Updated By:	SNBOLLER
Site Code:	59118
Site Description:	"Location: The Site is located in an urban area of New York County (Manhattan) on the east side of 10th Avenue between W. 16th and W. 17th Streets (the site does not include the building on the southeast corner of 10th Ave. and W. 17th St.). Site Features: The former site features include several buildings and a paved parking lot. The site buildings were unused and were demolished. Past Uses: The most recent uses of the Site include a warehouse for electrical construction equipment; an electrical contractor area; a vehicle garage and outdoor parking area; an outdoor garden supplies store; a restaurant; auto body shop; and classroom space for a theater company. Prior uses include various freight and automobile uses, with underground fuel storage tanks, and unspecified manufacturing. Surrounding uses include multi-story residential buildings with and without lower-level commercial uses, parking, and playgrounds. The High Line , an elevated rail line which was used in the past for freight and is now unused, is to the west of and partially over the western end of the site (with aerial easement). An investigation pertaining to the removal of underground storage tanks occurred in the early 1990's. A Phase I and limited Phase II Environmental Site Assessment was performed in 2004. Operable Units: For remedial purposes, the site was divided into two Operable Units (OUs). An operable unit

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 1 (OU1) is the eastern portion of the site which is fully occupied by the new residential building. Operable Unit 2 (OU2) is the High Line area that extends along 10th Avenue and the western portion of 16th Street. Site Geology and Hydrogeology: The generalized subsurface profile consists of urban fill overlying sand, with bedrock at depths between 40 and 70 feet below grade (ft-bg). The fill consisted of brown and grey, coarse to fine sand, some silt, gravel and brick fragments. Fill thickness ranged from about four to twelve feet. The thickness of the lower coarse to fine sand and gravelly sand ranges from 31 to 47 feet. The upper medium to fine sand extends typically to depths of about 20 ft-bg. Bedrock was encountered below the sand and consists of moderately fractured, medium-hard mica schist and moderately fractured, hard pegmatite. Bedrock was found at depths ranging from about 21 to 77 ft-bg. Bedrock is shallowest at the east end of the Site and slopes downward to the west toward the Hudson River. The net groundwater flow is to the west, toward the Hudson River. Depth to groundwater is 10 to 14 ft-bgs. "

Env Problem: "Nature and Extent of Contamination Prior to Remediation: Soil - Based on the investigations conducted at the site, the primary contaminants of concern were related to the past uses of petroleum, and to historic fill which was present across the entire site. The site soils were contaminated with volatile organic compounds (VOCs) related to petroleum (benzene, toluene, ethylbenzene, xylene, naphthalene) and, to a much lesser degree with chlorinated solvents (e.g. tetrachloroethene). Contaminants also included semi-volatile organic compounds of petroleum origin. Exceedances of applicable standards, criteria and guidance for soil were identified.
Groundwater - Petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) were present at elevated levels of concentration in groundwater throughout the Site. Concentrations of VOCs above Class GA Standards included chloroform, BTEX compounds and methyl-tert butyl ether (MTBE). SVOCs were prevalent at concentrations above NYSDEC regulatory levels in the groundwater in the southern and western portions of the Site and included dibenzofuran, 2-methylnaphthalene and naphthalene. The VOCs and SVOCs appear to be related to the prior use of the Site for vehicle fueling and repair. Iron, magnesium, manganese and sodium, common earth minerals, were detected in concentrations exceeding groundwater standards in all of the filtered groundwater samples.
Soil Vapor - During the remedial investigation, VOCs were detected across the Site in subsurface soil gas samples, as well as in the one ambient air sample. The highest concentration of VOCs was found at soil gas sample location FLS-4, collected at soil boring FLS-4. PID readings in boring FLS-4 peaked at 1,684 parts per million (ppm) at a depth of 16 ft-bg. Post Remediation: Remediation at the Site is complete. Prior to remediation, the primary contaminants of concern were petroleum related VOCs in soil and groundwater. Remedial actions have successfully achieved the site specific soil cleanup objectives. Residual contamination in the soil, groundwater and sub-slab vapor are being managed under a Site Management Plan. As part of the remediation, the petroleum contaminated soil and the historic fill was excavated from OU-1 and disposed of at regulated facilities. Groundwater was treated on site, and the clean effluent was

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

discharged to the New York City sewer under a permit. The contaminated soil and groundwater in OU-2 were remediated through injection of ORC (Oxygen Release Compound) into the underlying groundwater and subsoil. The top one foot of soil in OU-2 was removed through excavation. A Track 4 cleanup was achieved for the site. Engineering and Institutional Controls have been instituted to manage the residual contamination. These controls have been memorialized in the Environmental Easement that has been recorded in the New York County Clerk's office. The Certificate of Completion was issued on October 6, 2008. "

Health Problem: "Public water is provided to the area, thereby preventing exposures to groundwater. The remedial action work plan for the site calls for the removal of contaminated soil from the site prior to construction of a residential building on-site. Soil gas is contaminated by chlorinated solvents that are likely due to an off-site source. The site owner will include measures in the building construction to prevent soil vapor migration into the building."
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40.743291 / 74.007009
Dell: False
Record Add: 2004-09-07 12:00:00
Record Upd: 2008-11-17 16:26:00
Updated By: jdjarrat
Own Op: 1
Sub Type: 06
Owner Name: C/O THE RELATED COMPANIES, LP
Owner Company: 17TH AND 10TH ASSOCIATES, LLC
Owner Address: 60 COLUMBUS CIRCLE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10023
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: NEW YORK PUBLIC LIBRARY
Owner Company: WEST 17TH & 10TH ASSOCIATES, LLC
Owner Address: MUHLENBERG BRANCH
Owner Addr2: 209 WEST 23RD STREET
Owner City,St,Zip: NEW YORK, NY 10011
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Greg Gushee
Owner Company: 17TH AND 10TH ASSOCIATES, LLC
Owner Address: THE RELATED COMPANIES, L.P.
Owner Addr2: 60 COLUMBUS CIRCLE
Owner City,St,Zip: NEW YORK, NY 10023
Owner Country: United States of America
HW Code: C231040
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

HW Code: C231040
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W2-1034-04-11
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2008-11-17 14:24:00
Record Updated: 2008-11-18 09:25:00
Updated By: jdjarrat
Crossref ID: CRFN 2008000370558
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2008-11-17 16:28:00
Record Updated: 2008-11-17 16:28:00
Updated By: jdjarrat
Crossref ID: 0401167
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2008-05-13 14:37:00
Record Updated: 2008-05-13 14:37:00
Updated By: snboller

Name: WEST 17TH STREET AND 10TH AVENUE
Address: 440-452 WEST 17TH ST., 445-459 WEST 16TH STREET,
City,State,Zip: MANHATTAN, NY 10011
Site Code: 59118
Control Name: Building Use Restriction
HW Code: C231040
Control Code: 26
Control Type: INST
Dt record added: 10/15/2008
Dt rec updated: 12/31/2021
Updated By: SNBOLLER
Site Code: 59118
Site Description: "Location: The Site is located in an urban area of New York County (Manhattan) on the east side of 10th Avenue between W. 16th and W. 17th Streets (the site does not include the building on the southeast corner of 10th Ave. and W. 17th St.). Site Features: The former site features include several buildings and a paved parking lot. The site buildings were unused and were demolished. Past Uses: The most recent uses of the Site include a warehouse for electrical construction equipment; an electrical contractor area; a vehicle garage and outdoor parking area; an outdoor garden supplies store; a restaurant; auto body shop; and classroom space for a theater company. Prior uses

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

include various freight and automobile uses, with underground fuel storage tanks, and unspecified manufacturing. Surrounding uses include multi-story residential buildings with and without lower-level commercial uses, parking, and playgrounds. The High Line , an elevated rail line which was used in the past for freight and is now unused, is to the west of and partially over the western end of the site (with aerial easement). An investigation pertaining to the removal of underground storage tanks occurred in the early 1990's. A Phase I and limited Phase II Environmental Site Assessment was performed in 2004. Operable Units: For remedial purposes, the site was divided into two Operable Units (OUs). An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 1 (OU1) is the eastern portion of the site which is fully occupied by the new residential building. Operable Unit 2 (OU2) is the High Line area that extends along 10th Avenue and the western portion of 16th Street. Site Geology and Hydrogeology: The generalized subsurface profile consists of urban fill overlying sand, with bedrock at depths between 40 and 70 feet below grade (ft-bg). The fill consisted of brown and grey, coarse to fine sand, some silt, gravel and brick fragments. Fill thickness ranged from about four to twelve feet. The thickness of the lower coarse to fine sand and gravelly sand ranges from 31 to 47 feet. The upper medium to fine sand extends typically to depths of about 20 ft-bg. Bedrock was encountered below the sand and consists of moderately fractured, medium-hard mica schist and moderately fractured, hard pegmatite. Bedrock was found at depths ranging from about 21 to 77 ft-bg. Bedrock is shallowest at the east end of the Site and slopes downward to the west toward the Hudson River. The net groundwater flow is to the west, toward the Hudson River. Depth to groundwater is 10 to 14 ft-bgs. "

Env Problem: "Nature and Extent of Contamination Prior to Remediation: Soil - Based on the investigations conducted at the site, the primary contaminants of concern were related to the past uses of petroleum, and to historic fill which was present across the entire site. The site soils were contaminated with volatile organic compounds (VOCs) related to petroleum (benzene, toluene, ethylbenzene, xylene, naphthalene) and, to a much lesser degree with chlorinated solvents (e.g. tetrachloroethene). Contaminants also included semi-volatile organic compounds of petroleum origin. Exceedances of applicable standards, criteria and guidance for soil were identified.
Groundwater - Petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) were present at elevated levels of concentration in groundwater throughout the Site. Concentrations of VOCs above Class GA Standards included chloroform, BTEX compounds and methyl-tert butyl ether (MTBE). SVOCs were prevalent at concentrations above NYSDEC regulatory levels in the groundwater in the southern and western portions of the Site and included dibenzofuran, 2-methylnaphthalene and naphthalene. The VOCs and SVOCs appear to be related to the prior use of the Site for vehicle fueling and repair. Iron, magnesium, manganese and sodium, common earth minerals, were detected in concentrations exceeding groundwater standards in all of the filtered groundwater samples.
Soil Vapor - During the remedial investigation, VOCs were detected across the Site in subsurface soil gas samples, as well as in the one ambient air sample. The highest concentration of VOCs was found at

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

soil gas sample location FLS-4, collected at soil boring FLS-4. PID readings in boring FLS-4 peaked at 1,684 parts per million (ppm) at a depth of 16 ft-bg. Post Remediation: Remediation at the Site is complete. Prior to remediation, the primary contaminants of concern were petroleum related VOCs in soil and groundwater. Remedial actions have successfully achieved the site specific soil cleanup objectives. Residual contamination in the soil, groundwater and sub-slab vapor are being managed under a Site Management Plan. As part of the remediation, the petroleum contaminated soil and the historic fill was excavated from OU-1 and disposed of at regulated facilities. Groundwater was treated on site, and the clean effluent was discharged to the New York City sewer under a permit. The contaminated soil and groundwater in OU-2 were remediated through injection of ORC (Oxygen Release Compound) into the underlying groundwater and subsoil. The top one foot of soil in OU-2 was removed through excavation. A Track 4 cleanup was achieved for the site. Engineering and Institutional Controls have been instituted to manage the residual contamination. These controls have been memorialized in the Environmental Easement that has been recorded in the New York County Clerk's office. The Certificate of Completion was issued on October 6, 2008. "

Health Problem: "Public water is provided to the area, thereby preventing exposures to groundwater. The remedial action work plan for the site calls for the removal of contaminated soil from the site prior to construction of a residential building on-site. Soil gas is contaminated by chlorinated solvents that are likely due to an off-site source. The site owner will include measures in the building construction to prevent soil vapor migration into the building."
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40.743291 / 74.007009
Dell: False
Record Add: 2004-09-07 12:00:00
Record Upd: 2008-11-17 16:26:00
Updated By: jdjarrat
Own Op: 1
Sub Type: 06
Owner Name: C/O THE RELATED COMPANIES, LP
Owner Company: 17TH AND 10TH ASSOCIATES, LLC
Owner Address: 60 COLUMBUS CIRCLE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10023
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: NEW YORK PUBLIC LIBRARY
Owner Company: WEST 17TH & 10TH ASSOCIATES, LLC
Owner Address: MUHLENBERG BRANCH
Owner Addr2: 209 WEST 23RD STREET
Owner City,St,Zip: NEW YORK, NY 10011
Owner Country: United States of America
Own Op: 6

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

Sub Type: P03
Owner Name: Greg Gushee
Owner Company: 17TH AND 10TH ASSOCIATES, LLC
Owner Address: THE RELATED COMPANIES, L.P.
Owner Addr2: 60 COLUMBUS CIRCLE
Owner City,St,Zip: NEW YORK, NY 10023
Owner Country: United States of America
HW Code: C231040
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W2-1034-04-11
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2008-11-17 14:24:00
Record Updated: 2008-11-18 09:25:00
Updated By: jdjarrat
Crossref ID: CRFN 2008000370558
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2008-11-17 16:28:00
Record Updated: 2008-11-17 16:28:00
Updated By: jdjarrat
Crossref ID: 0401167
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2008-05-13 14:37:00
Record Updated: 2008-05-13 14:37:00
Updated By: snboller

Name: WEST 17TH STREET AND 10TH AVENUE
Address: 440-452 WEST 17TH ST., 445-459 WEST 16TH STREET,
City,State,Zip: MANHATTAN, NY 10011
Site Code: 59118
Control Name: Site Management Plan
HW Code: C231040
Control Code: 32
Control Type: INST
Dt record added: 10/15/2008
Dt rec updated: 12/31/2021
Updated By: SNBOLLER

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

Site Code: 59118

Site Description: "Location: The Site is located in an urban area of New York County (Manhattan) on the east side of 10th Avenue between W. 16th and W. 17th Streets (the site does not include the building on the southeast corner of 10th Ave. and W. 17th St.). Site Features: The former site features include several buildings and a paved parking lot. The site buildings were unused and were demolished. Past Uses: The most recent uses of the Site include a warehouse for electrical construction equipment; an electrical contractor area; a vehicle garage and outdoor parking area; an outdoor garden supplies store; a restaurant; auto body shop; and classroom space for a theater company. Prior uses include various freight and automobile uses, with underground fuel storage tanks, and unspecified manufacturing. Surrounding uses include multi-story residential buildings with and without lower-level commercial uses, parking, and playgrounds. The High Line , an elevated rail line which was used in the past for freight and is now unused, is to the west of and partially over the western end of the site (with aerial easement). An investigation pertaining to the removal of underground storage tanks occurred in the early 1990's. A Phase I and limited Phase II Environmental Site Assessment was performed in 2004. Operable Units: For remedial purposes, the site was divided into two Operable Units (OUs). An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 1 (OU1) is the eastern portion of the site which is fully occupied by the new residential building. Operable Unit 2 (OU2) is the High Line area that extends along 10th Avenue and the western portion of 16th Street. Site Geology and Hydrogeology: The generalized subsurface profile consists of urban fill overlying sand, with bedrock at depths between 40 and 70 feet below grade (ft-bg). The fill consisted of brown and grey, coarse to fine sand, some silt, gravel and brick fragments. Fill thickness ranged from about four to twelve feet. The thickness of the lower coarse to fine sand and gravelly sand ranges from 31 to 47 feet. The upper medium to fine sand extends typically to depths of about 20 ft-bg. Bedrock was encountered below the sand and consists of moderately fractured, medium-hard mica schist and moderately fractured, hard pegmatite. Bedrock was found at depths ranging from about 21 to 77 ft-bg. Bedrock is shallowest at the east end of the Site and slopes downward to the west toward the Hudson River. The net groundwater flow is to the west, toward the Hudson River. Depth to groundwater is 10 to 14 ft-bgs. "

Env Problem: "Nature and Extent of Contamination Prior to Remediation: Soil - Based on the investigations conducted at the site, the primary contaminants of concern were related to the past uses of petroleum, and to historic fill which was present across the entire site. The site soils were contaminated with volatile organic compounds (VOCs) related to petroleum (benzene, toluene, ethylbenzene, xylene, naphthalene) and, to a much lesser degree with chlorinated solvents (e.g. tetrachloroethene). Contaminants also included semi-volatile organic compounds of petroleum origin. Exceedances of applicable standards, criteria and guidance for soil were identified.
Groundwater - Petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) were present at elevated levels of concentration in groundwater throughout the Site. Concentrations of VOCs above Class GA Standards included chloroform,

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

BTEX compounds and methyl-tert butyl ether (MTBE). SVOCs were prevalent at concentrations above NYSDEC regulatory levels in the groundwater in the southern and western portions of the Site and included dibenzofuran, 2-methylnaphthalene and naphthalene. The VOCs and SVOCs appear to be related to the prior use of the Site for vehicle fueling and repair. Iron, magnesium, manganese and sodium, common earth minerals, were detected in concentrations exceeding groundwater standards in all of the filtered groundwater samples. Soil Vapor - During the remedial investigation, VOCs were detected across the Site in subsurface soil gas samples, as well as in the one ambient air sample. The highest concentration of VOCs was found at soil gas sample location FLS-4, collected at soil boring FLS-4. PID readings in boring FLS-4 peaked at 1,684 parts per million (ppm) at a depth of 16 ft-bg. Post Remediation: Remediation at the Site is complete. Prior to remediation, the primary contaminants of concern were petroleum related VOCs in soil and groundwater. Remedial actions have successfully achieved the site specific soil cleanup objectives. Residual contamination in the soil, groundwater and sub-slab vapor are being managed under a Site Management Plan. As part of the remediation, the petroleum contaminated soil and the historic fill was excavated from OU-1 and disposed of at regulated facilities. Groundwater was treated on site, and the clean effluent was discharged to the New York City sewer under a permit. The contaminated soil and groundwater in OU-2 were remediated through injection of ORC (Oxygen Release Compound) into the underlying groundwater and subsoil. The top one foot of soil in OU-2 was removed through excavation. A Track 4 cleanup was achieved for the site. Engineering and Institutional Controls have been instituted to manage the residual contamination. These controls have been memorialized in the Environmental Easement that has been recorded in the New York County Clerk’s office. The Certificate of Completion was issued on October 6, 2008. "

Health Problem: "Public water is provided to the area, thereby preventing exposures to groundwater. The remedial action work plan for the site calls for the removal of contaminated soil from the site prior to construction of a residential building on-site. Soil gas is contaminated by chlorinated solvents that are likely due to an off-site source. The site owner will include measures in the building construction to prevent soil vapor migration into the building."
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40.743291 / 74.007009
Dell: False
Record Add: 2004-09-07 12:00:00
Record Upd: 2008-11-17 16:26:00
Updated By: jdjarrat
Own Op: 1
Sub Type: 06
Owner Name: C/O THE RELATED COMPANIES, LP
Owner Company: 17TH AND 10TH ASSOCIATES, LLC
Owner Address: 60 COLUMBUS CIRCLE
Owner Addr2: Not reported

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

Owner City,St,Zip: NEW YORK, NY 10023
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: NEW YORK PUBLIC LIBRARY
Owner Company: WEST 17TH & 10TH ASSOCIATES, LLC
Owner Address: MUHLENBERG BRANCH
Owner Addr2: 209 WEST 23RD STREET
Owner City,St,Zip: NEW YORK, NY 10011
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Greg Gushee
Owner Company: 17TH AND 10TH ASSOCIATES, LLC
Owner Address: THE RELATED COMPANIES, L.P.
Owner Addr2: 60 COLUMBUS CIRCLE
Owner City,St,Zip: NEW YORK, NY 10023
Owner Country: United States of America
HW Code: C231040
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W2-1034-04-11
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2008-11-17 14:24:00
Record Updated: 2008-11-18 09:25:00
Updated By: jdjarrat
Crossref ID: CRFN 2008000370558
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2008-11-17 16:28:00
Record Updated: 2008-11-17 16:28:00
Updated By: jdjarrat
Crossref ID: 0401167
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2008-05-13 14:37:00
Record Updated: 2008-05-13 14:37:00
Updated By: snboller

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

Name: WEST 17TH STREET AND 10TH AVENUE
Address: 440-452 WEST 17TH ST., 445-459 WEST 16TH STREET,
City,State,Zip: MANHATTAN, NY 10011
Site Code: 59118
Control Name: Environmental Easement
HW Code: C231040
Control Code: J
Control Type: INST
Dt record added: 10/15/2008
Dt rec updated: 12/31/2021
Updated By: SNBOLLER
Site Code: 59118
Site Description: "Location: The Site is located in an urban area of New York County (Manhattan) on the east side of 10th Avenue between W. 16th and W. 17th Streets (the site does not include the building on the southeast corner of 10th Ave. and W. 17th St.). Site Features: The former site features include several buildings and a paved parking lot. The site buildings were unused and were demolished. Past Uses: The most recent uses of the Site include a warehouse for electrical construction equipment; an electrical contractor area; a vehicle garage and outdoor parking area; an outdoor garden supplies store; a restaurant; auto body shop; and classroom space for a theater company. Prior uses include various freight and automobile uses, with underground fuel storage tanks, and unspecified manufacturing. Surrounding uses include multi-story residential buildings with and without lower-level commercial uses, parking, and playgrounds. The High Line , an elevated rail line which was used in the past for freight and is now unused, is to the west of and partially over the western end of the site (with aerial easement). An investigation pertaining to the removal of underground storage tanks occurred in the early 1990's. A Phase I and limited Phase II Environmental Site Assessment was performed in 2004. Operable Units: For remedial purposes, the site was divided into two Operable Units (OUs). An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 1 (OU1) is the eastern portion of the site which is fully occupied by the new residential building. Operable Unit 2 (OU2) is the High Line area that extends along 10th Avenue and the western portion of 16th Street. Site Geology and Hydrogeology: The generalized subsurface profile consists of urban fill overlying sand, with bedrock at depths between 40 and 70 feet below grade (ft-bg). The fill consisted of brown and grey, coarse to fine sand, some silt, gravel and brick fragments. Fill thickness ranged from about four to twelve feet. The thickness of the lower coarse to fine sand and gravelly sand ranges from 31 to 47 feet. The upper medium to fine sand extends typically to depths of about 20 ft-bg. Bedrock was encountered below the sand and consists of moderately fractured, medium-hard mica schist and moderately fractured, hard pegmatite. Bedrock was found at depths ranging from about 21 to 77 ft-bg. Bedrock is shallowest at the east end of the Site and slopes downward to the west toward the Hudson River. The net groundwater flow is to the west, toward the Hudson River. Depth to groundwater is 10 to 14 ft-bgs. "
Env Problem: "Nature and Extent of Contamination Prior to Remediation: Soil - Based on the investigations conducted at the site, the primary contaminants of concern were related to the past uses of petroleum,

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

and to historic fill which was present across the entire site. The site soils were contaminated with volatile organic compounds (VOCs) related to petroleum (benzene, toluene, ethylbenzene, xylene, naphthalene) and, to a much lesser degree with chlorinated solvents (e.g. tetrachloroethene). Contaminants also included semi-volatile organic compounds of petroleum origin. Exceedances of applicable standards, criteria and guidance for soil were identified.
Groundwater - Petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) were present at elevated levels of concentration in groundwater throughout the Site. Concentrations of VOCs above Class GA Standards included chloroform, BTEX compounds and methyl-tert butyl ether (MTBE). SVOCs were prevalent at concentrations above NYSDEC regulatory levels in the groundwater in the southern and western portions of the Site and included dibenzofuran, 2-methylnaphthalene and naphthalene. The VOCs and SVOCs appear to be related to the prior use of the Site for vehicle fueling and repair. Iron, magnesium, manganese and sodium, common earth minerals, were detected in concentrations exceeding groundwater standards in all of the filtered groundwater samples.
Soil Vapor - During the remedial investigation, VOCs were detected across the Site in subsurface soil gas samples, as well as in the one ambient air sample. The highest concentration of VOCs was found at soil gas sample location FLS-4, collected at soil boring FLS-4. PID readings in boring FLS-4 peaked at 1,684 parts per million (ppm) at a depth of 16 ft-bg. Post Remediation: Remediation at the Site is complete. Prior to remediation, the primary contaminants of concern were petroleum related VOCs in soil and groundwater. Remedial actions have successfully achieved the site specific soil cleanup objectives. Residual contamination in the soil, groundwater and sub-slab vapor are being managed under a Site Management Plan. As part of the remediation, the petroleum contaminated soil and the historic fill was excavated from OU-1 and disposed of at regulated facilities. Groundwater was treated on site, and the clean effluent was discharged to the New York City sewer under a permit. The contaminated soil and groundwater in OU-2 were remediated through injection of ORC (Oxygen Release Compound) into the underlying groundwater and subsoil. The top one foot of soil in OU-2 was removed through excavation. A Track 4 cleanup was achieved for the site. Engineering and Institutional Controls have been instituted to manage the residual contamination. These controls have been memorialized in the Environmental Easement that has been recorded in the New York County Clerk’s office. The Certificate of Completion was issued on October 6, 2008. "

Health Problem: "Public water is provided to the area, thereby preventing exposures to groundwater. The remedial action work plan for the site calls for the removal of contaminated soil from the site prior to construction of a residential building on-site. Soil gas is contaminated by chlorinated solvents that are likely due to an off-site source. The site owner will include measures in the building construction to prevent soil vapor migration into the building."
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

Lat/Long: 40.743291 / 74.007009
Dell: False
Record Add: 2004-09-07 12:00:00
Record Upd: 2008-11-17 16:26:00
Updated By: jdjarrat
Own Op: 1
Sub Type: 06
Owner Name: C/O THE RELATED COMPANIES, LP
Owner Company: 17TH AND 10TH ASSOCIATES, LLC
Owner Address: 60 COLUMBUS CIRCLE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10023
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: NEW YORK PUBLIC LIBRARY
Owner Company: WEST 17TH & 10TH ASSOCIATES, LLC
Owner Address: MUHLENBERG BRANCH
Owner Addr2: 209 WEST 23RD STREET
Owner City,St,Zip: NEW YORK, NY 10011
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Greg Gushee
Owner Company: 17TH AND 10TH ASSOCIATES, LLC
Owner Address: THE RELATED COMPANIES, L.P.
Owner Addr2: 60 COLUMBUS CIRCLE
Owner City,St,Zip: NEW YORK, NY 10023
Owner Country: United States of America
HW Code: C231040
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W2-1034-04-11
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2008-11-17 14:24:00
Record Updated: 2008-11-18 09:25:00
Updated By: jdjarrat
Crossref ID: CRFN 2008000370558
Cross Ref Type Code: 25

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

Cross Ref Type: County Recording Identifier
Record Added Date: 2008-11-17 16:28:00
Record Updated: 2008-11-17 16:28:00
Updated By: jdjarrat
Crossref ID: 0401167
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2008-05-13 14:37:00
Record Updated: 2008-05-13 14:37:00
Updated By: snboller

Name: WEST 17TH STREET AND 10TH AVENUE
Address: 440-452 WEST 17TH ST., 445-459 WEST 16TH STREET,
City,State,Zip: MANHATTAN, NY 10011
Site Code: 59118
Control Name: Soil Management Plan
HW Code: C231040
Control Code: 14
Control Type: INST
Dt record added: 10/15/2008
Dt rec updated: 12/31/2021
Updated By: SNBOLLER
Site Code: 59118
Site Description: "Location: The Site is located in an urban area of New York County (Manhattan) on the east side of 10th Avenue between W. 16th and W. 17th Streets (the site does not include the building on the southeast corner of 10th Ave. and W. 17th St.). Site Features: The former site features include several buildings and a paved parking lot. The site buildings were unused and were demolished. Past Uses: The most recent uses of the Site include a warehouse for electrical construction equipment; an electrical contractor area; a vehicle garage and outdoor parking area; an outdoor garden supplies store; a restaurant; auto body shop; and classroom space for a theater company. Prior uses include various freight and automobile uses, with underground fuel storage tanks, and unspecified manufacturing. Surrounding uses include multi-story residential buildings with and without lower-level commercial uses, parking, and playgrounds. The High Line , an elevated rail line which was used in the past for freight and is now unused, is to the west of and partially over the western end of the site (with aerial easement). An investigation pertaining to the removal of underground storage tanks occurred in the early 1990's. A Phase I and limited Phase II Environmental Site Assessment was performed in 2004. Operable Units: For remedial purposes, the site was divided into two Operable Units (OUs). An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 1 (OU1) is the eastern portion of the site which is fully occupied by the new residential building. Operable Unit 2 (OU2) is the High Line area that extends along 10th Avenue and the western portion of 16th Street. Site Geology and Hydrogeology: The generalized subsurface profile consists of urban fill overlying sand, with bedrock at depths between 40 and 70 feet below grade (ft-bg). The fill consisted of brown and grey, coarse to fine sand, some silt, gravel and brick fragments. Fill thickness ranged from about four to twelve feet. The thickness of the lower coarse to fine sand and gravelly sand ranges

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

from 31 to 47 feet. The upper medium to fine sand extends typically to depths of about 20 ft-bg. Bedrock was encountered below the sand and consists of moderately fractured, medium-hard mica schist and moderately fractured, hard pegmatite. Bedrock was found at depths ranging from about 21 to 77 ft-bg. Bedrock is shallowest at the east end of the Site and slopes downward to the west toward the Hudson River. The net groundwater flow is to the west, toward the Hudson River. Depth to groundwater is 10 to 14 ft-bgs. "

Env Problem: "Nature and Extent of Contamination Prior to Remediation: Soil - Based on the investigations conducted at the site, the primary contaminants of concern were related to the past uses of petroleum, and to historic fill which was present across the entire site. The site soils were contaminated with volatile organic compounds (VOCs) related to petroleum (benzene, toluene, ethylbenzene, xylene, naphthalene) and, to a much lesser degree with chlorinated solvents (e.g. tetrachloroethene). Contaminants also included semi-volatile organic compounds of petroleum origin. Exceedances of applicable standards, criteria and guidance for soil were identified. Groundwater - Petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) were present at elevated levels of concentration in groundwater throughout the Site. Concentrations of VOCs above Class GA Standards included chloroform, BTEX compounds and methyl-tert butyl ether (MTBE). SVOCs were prevalent at concentrations above NYSDEC regulatory levels in the groundwater in the southern and western portions of the Site and included dibenzofuran, 2-methylnaphthalene and naphthalene. The VOCs and SVOCs appear to be related to the prior use of the Site for vehicle fueling and repair. Iron, magnesium, manganese and sodium, common earth minerals, were detected in concentrations exceeding groundwater standards in all of the filtered groundwater samples. Soil Vapor - During the remedial investigation, VOCs were detected across the Site in subsurface soil gas samples, as well as in the one ambient air sample. The highest concentration of VOCs was found at soil gas sample location FLS-4, collected at soil boring FLS-4. PID readings in boring FLS-4 peaked at 1,684 parts per million (ppm) at a depth of 16 ft-bg. Post Remediation: Remediation at the Site is complete. Prior to remediation, the primary contaminants of concern were petroleum related VOCs in soil and groundwater. Remedial actions have successfully achieved the site specific soil cleanup objectives. Residual contamination in the soil, groundwater and sub-slab vapor are being managed under a Site Management Plan. As part of the remediation, the petroleum contaminated soil and the historic fill was excavated from OU-1 and disposed of at regulated facilities. Groundwater was treated on site, and the clean effluent was discharged to the New York City sewer under a permit. The contaminated soil and groundwater in OU-2 were remediated through injection of ORC (Oxygen Release Compound) into the underlying groundwater and subsoil. The top one foot of soil in OU-2 was removed through excavation. A Track 4 cleanup was achieved for the site. Engineering and Institutional Controls have been instituted to manage the residual contamination. These controls have been memorialized in the Environmental Easement that has been recorded in the New York County Clerk’s office. The Certificate of Completion was issued on October 6, 2008. "

Health Problem: "Public water is provided to the area, thereby preventing exposures to groundwater. The remedial action work plan for the site calls for the removal of contaminated soil from the site prior to construction

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

of a residential building on-site. Soil gas is contaminated by chlorinated solvents that are likely due to an off-site source. The site owner will include measures in the building construction to prevent soil vapor migration into the building."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40.743291 / 74.007009
Dell: False
Record Add: 2004-09-07 12:00:00
Record Upd: 2008-11-17 16:26:00
Updated By: jdjarrat
Own Op: 1
Sub Type: 06
Owner Name: C/O THE RELATED COMPANIES, LP
Owner Company: 17TH AND 10TH ASSOCIATES, LLC
Owner Address: 60 COLUMBUS CIRCLE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10023
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: NEW YORK PUBLIC LIBRARY
Owner Company: WEST 17TH & 10TH ASSOCIATES, LLC
Owner Address: MUHLENBERG BRANCH
Owner Addr2: 209 WEST 23RD STREET
Owner City,St,Zip: NEW YORK, NY 10011
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Greg Gushee
Owner Company: 17TH AND 10TH ASSOCIATES, LLC
Owner Address: THE RELATED COMPANIES, L.P.
Owner Addr2: 60 COLUMBUS CIRCLE
Owner City,St,Zip: NEW YORK, NY 10023
Owner Country: United States of America
HW Code: C231040
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231040

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W2-1034-04-11
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2008-11-17 14:24:00
Record Updated: 2008-11-18 09:25:00
Updated By: jdjarrat
Crossref ID: CRFN 2008000370558
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2008-11-17 16:28:00
Record Updated: 2008-11-17 16:28:00
Updated By: jdjarrat
Crossref ID: 0401167
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2008-05-13 14:37:00
Record Updated: 2008-05-13 14:37:00
Updated By: snboller

BROWNFIELDS:

Name:	WEST 17TH STREET AND 10TH AVENUE
Address:	440-452 WEST 17TH ST., 445-459 WEST 16TH STREET,
City,State,Zip:	MANHATTAN, NY 10011
Program:	BCP
Site Code:	59118
Acres:	1.213
HW Code:	C231040
SWIS:	3101
Town:	New York City
Record Added Date:	09/07/2004
Record Updated Date:	10/29/2018
Update By:	JHOCONNE
Site Description:	"Location: The Site is located in an urban area of New York County (Manhattan) on the east side of 10th Avenue between W. 16th and W. 17th Streets (the site does not include the building on the southeast corner of 10th Ave. and W. 17th St.). Site Features: The former site features include several buildings and a paved parking lot. The site buildings were unused and were demolished. Past Uses: The most recent uses of the Site include a warehouse for electrical construction equipment; an electrical contractor area; a vehicle garage and outdoor parking area; an outdoor garden supplies store; a restaurant; auto body shop; and classroom space for a theater company. Prior uses include various freight and automobile uses, with underground fuel storage tanks, and unspecified manufacturing. Surrounding uses include multi-story residential buildings with and without lower-level commercial uses, parking, and playgrounds. The High Line , an elevated rail line which was used in the past for freight and is now unused, is to the west of and partially over the western end of the site (with aerial easement). An investigation pertaining to the removal of underground storage tanks occurred in the early 1990's. A Phase I and limited Phase II Environmental Site Assessment was performed in 2004. Operable Units: For remedial purposes, the site was divided into two Operable Units (OUs). An operable unit represents a portion of a remedial program for a site that for

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 1 (OU1) is the eastern portion of the site which is fully occupied by the new residential building. Operable Unit 2 (OU2) is the High Line area that extends along 10th Avenue and the western portion of 16th Street. Site Geology and Hydrogeology: The generalized subsurface profile consists of urban fill overlying sand, with bedrock at depths between 40 and 70 feet below grade (ft-bg). The fill consisted of brown and grey, coarse to fine sand, some silt, gravel and brick fragments. Fill thickness ranged from about four to twelve feet. The thickness of the lower coarse to fine sand and gravelly sand ranges from 31 to 47 feet. The upper medium to fine sand extends typically to depths of about 20 ft-bg. Bedrock was encountered below the sand and consists of moderately fractured, medium-hard mica schist and moderately fractured, hard pegmatite. Bedrock was found at depths ranging from about 21 to 77 ft-bg. Bedrock is shallowest at the east end of the Site and slopes downward to the west toward the Hudson River. The net groundwater flow is to the west, toward the Hudson River. Depth to groundwater is 10 to 14 ft-bgs. "

Env Problem:

"Nature and Extent of Contamination Prior to Remediation: Soil - Based on the investigations conducted at the site, the primary contaminants of concern were related to the past uses of petroleum, and to historic fill which was present across the entire site. The site soils were contaminated with volatile organic compounds (VOCs) related to petroleum (benzene, toluene, ethylbenzene, xylene, naphthalene) and, to a much lesser degree with chlorinated solvents (e.g. tetrachloroethene). Contaminants also included semi-volatile organic compounds of petroleum origin. Exceedances of applicable standards, criteria and guidance for soil were identified.
Groundwater - Petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) were present at elevated levels of concentration in groundwater throughout the Site. Concentrations of VOCs above Class GA Standards included chloroform, BTEX compounds and methyl-tert butyl ether (MTBE). SVOCs were prevalent at concentrations above NYSDEC regulatory levels in the groundwater in the southern and western portions of the Site and included dibenzofuran, 2-methylnaphthalene and naphthalene. The VOCs and SVOCs appear to be related to the prior use of the Site for vehicle fueling and repair. Iron, magnesium, manganese and sodium, common earth minerals, were detected in concentrations exceeding groundwater standards in all of the filtered groundwater samples.
Soil Vapor - During the remedial investigation, VOCs were detected across the Site in subsurface soil gas samples, as well as in the one ambient air sample. The highest concentration of VOCs was found at soil gas sample location FLS-4, collected at soil boring FLS-4. PID readings in boring FLS-4 peaked at 1,684 parts per million (ppm) at a depth of 16 ft-bg. Post Remediation: Remediation at the Site is complete. Prior to remediation, the primary contaminants of concern were petroleum related VOCs in soil and groundwater. Remedial actions have successfully achieved the site specific soil cleanup objectives. Residual contamination in the soil, groundwater and sub-slab vapor are being managed under a Site Management Plan. As part of the remediation, the petroleum contaminated soil and the historic fill was excavated from OU-1 and disposed of at regulated facilities. Groundwater was treated on site, and the clean effluent was discharged to the New York City sewer under a permit. The

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

	contaminated soil and groundwater in OU-2 were remediated through injection of ORC (Oxygen Release Compound) into the underlying groundwater and subsoil. The top one foot of soil in OU-2 was removed through excavation. A Track 4 cleanup was achieved for the site. Engineering and Institutional Controls have been instituted to manage the residual contamination. These controls have been memorialized in the Environmental Easement that has been recorded in the New York County Clerk's office. The Certificate of Completion was issued on October 6, 2008. "
Health Problem:	"Public water is provided to the area, thereby preventing exposures to groundwater. The remedial action work plan for the site calls for the removal of contaminated soil from the site prior to construction of a residential building on-site. Soil gas is contaminated by chlorinated solvents that are likely due to an off-site source. The site owner will include measures in the building construction to prevent soil vapor migration into the building."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	40.743291 / 74.007009
Dell:	False
Record Add:	2004-09-07 12:00:00
Record Upd:	2008-11-17 16:26:00
Updated By:	jdjarrat
Own Op:	1
Sub Type:	06
Owner Name:	C/O THE RELATED COMPANIES, LP
Owner Company:	17TH AND 10TH ASSOCIATES, LLC
Owner Address:	60 COLUMBUS CIRCLE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10023
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	NEW YORK PUBLIC LIBRARY
Owner Company:	WEST 17TH & 10TH ASSOCIATES, LLC
Owner Address:	MUHLENBERG BRANCH
Owner Addr2:	209 WEST 23RD STREET
Owner City,St,Zip:	NEW YORK, NY 10011
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Greg Gushee
Owner Company:	17TH AND 10TH ASSOCIATES, LLC
Owner Address:	THE RELATED COMPANIES, L.P.
Owner Addr2:	60 COLUMBUS CIRCLE
Owner City,St,Zip:	NEW YORK, NY 10023
Owner Country:	United States of America
HW Code:	C231040
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231040

WEST 17TH STREET AND 10TH AVENUE (Continued) **S109321176**

Waste Type:	ETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231040
Waste Type:	NAPHTHALENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231040
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231040
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	W2-1034-04-11
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2008-11-17 14:24:00
Record Updated:	2008-11-18 09:25:00
Updated By:	jdjarrat
Crossref ID:	CRFN 2008000370558
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2008-11-17 16:28:00
Record Updated:	2008-11-17 16:28:00
Updated By:	jdjarrat
Crossref ID:	0401167
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2008-05-13 14:37:00
Record Updated:	2008-05-13 14:37:00
Updated By:	snboller

A14 **NYCHA - FULTON HOUSES** **RCRA NonGen / NLR** **1001224124**
427-431 W 17TH ST **FINDS** **NYR000053405**
< 1/8 **NEW YORK, NY 10011** **ECHO**
1 ft.

Site 8 of 19 in cluster A

Relative: Higher
Actual: 14 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	NYCHA - FULTON HOUSES	
Handler Address:		427-431 W 17TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYR000053405
Contact Name:		Not reported
Contact Address:		BROADWAY
Contact City,State,Zip:		NEW YORK, NY 10007
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Municipal
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported

NYCHA - FULTON HOUSES (Continued) **1001224124**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	BROADWAY
Mailing City,State,Zip:	NEW YORK, NY 10007
Owner Name:	NYCHA
Owner Type:	Municipal
Operator Name:	NYCHA
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

NYCHA - FULTON HOUSES (Continued) **1001224124**

Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYCHA
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	250 BROADWAY 16TH FLOOR
Owner/Operator City,State,Zip:	NEW YORK, NY 10007
Owner/Operator Telephone:	212-306-3229
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYCHA
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	250 BROADWAY 16TH FLOOR
Owner/Operator City,State,Zip:	NEW YORK, NY 10007
Owner/Operator Telephone:	212-306-3229
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYCHA
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	250 BROADWAY 16TH FLOOR
Owner/Operator City,State,Zip:	NEW YORK, NY 10007
Owner/Operator Telephone:	212-306-3229
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: NYCHA - FULTON HOUSES	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY

NYCHA - FULTON HOUSES (Continued) **1001224124**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: NYCHA - FULTON HOUSES	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: NYCHA - FULTON HOUSES	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980402
Handler Name: NYCHA - FULTON HOUSES	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NYCHA - FULTON HOUSES (Continued) **1001224124**

FINDS:
Registry ID: 110004542228

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001224124
Registry ID: 110004542228
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004542228
Name: NYCHA - FULTON HOUSES
Address: 427-431 W 17TH ST
City,State,Zip: NEW YORK, NY 10011

A15 **CON EDISON** **FINDS** **1014818236**
418 W 17TH ST **ECHO** **N/A**
< 1/8 **NEW YORK, NY 10014**
1 ft.

Site 9 of 19 in cluster A

Relative: Higher
Actual: 15 ft.

FINDS:
Registry ID: 110041670670

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1014818236
Registry ID: 110041670670
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110041670670
Name: CON EDISON
Address: 418 W 17TH ST
City,State,Zip: NEW YORK, NY 10014

D16 **EXCAVATION SITE** **NY Spills** **S106970842**
FRONT OF 413 W. 16TH ST. **N/A**
< 1/8 **MANHATTAN, NY**
1 ft.

Site 1 of 9 in cluster D

Relative: SPILLS:
Higher

Actual:
14 ft.

Name:	EXCAVATION SITE
Address:	FRONT OF 413 W. 16TH ST.
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0501928 / 2005-12-27
Facility ID:	0501928
Facility Type:	ER
DER Facility ID:	292444
Site ID:	346188
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	2005-05-17
Investigator:	SKARAKHA
Referred To:	Not reported
Reported to Dept:	2005-05-17
CID:	406
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-05-17
Spill Record Last Update:	2005-12-27
Spiller Name:	UNKNOWN NAME
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT DESK
DEC Memo:	"e2mis no 158642 M Sieber # 19114 reports that while safeway contractors were digging an excavation to install a sewer line to a transformer vault in front of 413 w 16 st, he discovered that there was an odor of fuel oil in the soil of the excavation. No sewer or waterway affected. The amount of 1 gallon of fuel oi is being used for record keeping purposes. Cause and source are unknown. No private property affected. Chem lab is to be called to take samples. No initial cleanup action taken. None of the affected soil was excavated. uPDATE 5-25-05 @ 16:45 Lab Sequence Number: 05-04675-001 Aroclor 1016 < 106 ug/Kg EPA 8082 Aroclor 1221 < 106 ug/Kg EPA 8082 Aroclor 1232 < 106 ug/Kg EPA 8082 Aroclor 1242 < 106 ug/Kg EPA 8082 Aroclor 1248 < 106 ug/Kg EPA 8082 Aroclor 1254 < 106 ug/Kg EPA 8082 Aroclor 1260 < 106 ug/Kg EPA 8082 % Solids 87.5 % Lab Sequence Number: 05-04675-002 Date Approved: 5/25/2005 Benzene 0.5 < 200 ug/L EPA 8260B Carbon Tetrachloride 0.5 < 200 ug/L EPA 8260B Chlorobenzene 100.0 < 200 ug/L EPA 8260B Chloroform 6.0 < 200 ug/L EPA 8260B 1,4-Dichlorobenzene 7.5 < 200 ug/L EPA 8260B 1,2-Dichloroethane 0.5 < 200 ug/L EPA 8260B 1,1-Dichloroethene 0.7 < 200 ug/L EPA 8260B Methyl Ethyl Ketone (MEK) 200.0 < 1000 ug/L EPA 8260B Tetrachloroethene 0.7

EXCAVATION SITE (Continued) **S106970842**

< 200 ug/L EPA 8260B Trichloroethene 0.5 < 200 ug/L EPA 8260B Vinyl Chloride 0.2 < 200 ug/L EPA 8260B Lab Sequence Number: 05-04675-003 Date Approved: 5/25/2005 o-Cresol 200.0 < 25 ug/L EPA 8270C m,p-Cresol 200.0 < 50 ug/L EPA 8270C 1,4-Dichlorobenzene < 25 ug/L EPA 8270C 2,4-Dinitrotoluene 0.1 < 25 ug/L EPA 8270C Hexachlorobenzene 0.1 < 25 ug/L EPA 8270C Hexachlorobutadiene 0.5 < 25 ug/L EPA 8270C Hexachloroethane 3.0 < 25 ug/L EPA 8270C Nitrobenzene 2.0 < 25 ug/L EPA 8270C Pentachlorophenol 100.0 < 25 ug/L EPA 8270C Pyridine 5.0 < 25 ug/L EPA 8270C 2,4,5-Trichlorophenol 400.0 < 25 ug/L EPA 8270C 2,4,6-Trichlorophenol 2.0 < 25 ug/L EPA 8270C Lab Sequence Number: 05-04675-004 Date Approved: 5/25/2005 Arsenic as As 5.0 < 1.00 mg/L 1311/6010B, SW-846 Barium as Ba 100.0 < 10.0 mg/L 1311/6010B SW-846 Cadmium as Cd 1.0 < 0.100 mg/L 1311/6010B SW-846 Chromium as Cr 5.0 < 0.500 mg/L 1311/6010B SW-846 Lead as Pb 5.0 < 0.500 mg/L 1311/6010B SW-846 Mercury as Hg 0.2 < 0.0200 mg/L SW-846 7470 Selenium as Se 1.0 < 1.00 mg/L 1311/6010B, SW-846 Silver as Ag 5.0 < 0.100 mg/L 1311/6010B SW-846 Lab Sequence Number: 05-04675-005 Date Approved: 5/25/2005 DiChevrol Fluid 100 Cable Oil < 54.7 mg/Kg EPA 8100 Mod DiChevrol Fluid 500 Cable Oil < 54.7 mg/Kg EPA 8100 Mod Silicone Base Transformer Oil < 54.7 mg/Kg EPA 8100 Mod High Visc. Polybutene Cable Oil < 54.7 mg/Kg EPA 8100 Mod Low Visc. Polybutene Cable Oil < 54.7 mg/Kg EPA 8100 Mod Sun #2 Base Transformer Oil < 54.7 mg/Kg EPA 8100 Mod Sun #4 Cable Oil < 54.7 mg/Kg EPA 8100 Mod Sun #6 Cable Oil < 54.7 mg/Kg EPA 8100 Mod Sun #8 II Base Transformer Oil < 54.7 mg/Kg EPA 8100 Mod Gasoline < 54.7 mg/Kg EPA 8100 Mod Kerosene < 54.7 mg/Kg EPA 8100 Mod #4 Fuel Oil < 54.7 mg/Kg EPA 8100 Mod #6 Fuel Oil < 54.7 mg/Kg EPA 8100 Mod THC by Method 8100 (Modified) 3270 mg/Kg EPA 8100 (MOD.) Univolt 60 Transformer Oil < 54.7 mg/Kg EPA 8100 Mod Diesel Fuel Oil < 54.7 mg/Kg EPA 8100 MOD Motor Oil < 54.7 mg/Kg EPA 8100 Mod JP4 (Aviation Fuel) < 54.7 mg/Kg EPA 8100 Mod Feeder 24032 Oil < 54.7 mg/Kg EPA 8100 Mod Feeder 28242 Oil < 54.7 mg/Kg EPA 8100 Mod Feeder 38m35 Oil < 54.7 mg/Kg EPA 8100 Mod Feeder 51/52 Oil < 54.7 mg/Kg EPA 8100 Mod Feeder 69M43 Oil < 54.7 mg/Kg EPA 8100 Mod Dielectric Fluid 100 Oil < 54.7 mg/Kg EPA 8100 Mod Petroleum Contaminant 3270 mg/Kg EPA 8100 Mod #2 Fuel Oil < 54.7 mg/Kg EPA 8100 Mod Feeder 69M41 Oil < 54.7 mg/Kg EPA 8100 Mod Feeder 38R51 Oil < 54.7 mg/Kg EPA 8100 Mod Feeder 38R52 Oil < 54.7 mg/Kg EPA 8100 Mod Feeder 69M65 Oil < 54.7 mg/Kg EPA 8100 Mod Feeder 63 Oil < 54.7 mg/Kg EPA 8100 Mod % Solids 86.9 % 07/25/05 @ 13:25 - As per Gino Frabsile, Project Specialist, CM-EHS, Approx. 40 cy of soil was removed using lined roll-off containers by Clean Harbors on May 27, 2005. The soil was taken to Clean Harbors facility in Bristol, CT (Us EPA No. CTD000604488). Clean up complete."

Remarks: "During an open excavation fuel odor was discovered. No cleanup at this time. ConEd#158642"

All Materials:

Site ID:	346188
Operable Unit ID:	1103923
Operable Unit:	01
Material ID:	584127
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00

EXCAVATION SITE (Continued) **S106970842**

Oxygenate: Not reported

A17 **MIDTOWN SERVICE CENTER INC** **EDR Hist Auto** **1020209138**
WNW **436 W 18TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.002 mi.
8 ft. **Site 10 of 19 in cluster A**

Relative: EDR Hist Auto
Lower

Actual:
13 ft.

Year:	Name:	Type:
1995	MIDTOWN SERVICE CENTER INC	Automotive Transmission Repair Shops
1996	MIDTOWN SERVICE CENTER INC	Automotive Transmission Repair Shops
1997	MIDTOWN SERVICE CENTER INC	Automotive Transmission Repair Shops
1998	MIDTOWN SERVICE CENTER INC	Automotive Transmission Repair Shops
1999	MIDTOWN SERVICE CENTER INC	Automotive Transmission Repair Shops
2000	MIDTOWN SERVICE CENTER INC	Automotive Transmission Repair Shops
2001	MIDTOWN SERVICE CENTER INC	Automotive Transmission Repair Shops
2002	MIDTOWN SERVICE CENTER INC	Automotive Transmission Repair Shops
2003	MIDTOWN SERVICE CENTER INC	Automotive Transmission Repair Shops
2004	MIDTOWN SERVICE CENTER INC	Automotive Transmission Repair Shops
2005	MIDTOWN SERVICE CENTER INC	Automotive Repair Shops, NEC
2006	MIDTOWN SERVICE CENTER INC	Automotive Repair Shops, NEC
2007	MIDTOWN SERVICE CENTER INC	Automotive Repair Shops, NEC
2008	MIDTOWN SERVICE CENTER INC	Automotive Repair Shops, NEC
2009	MIDTOWN SERVICE CENTER INC	Automotive Repair Shops, NEC
2010	MIDTOWN SERVICE CENTER INC	Automotive Repair Shops, NEC
2011	MIDTOWN SERVICE CENTER INC	Automotive Repair Shops, NEC
2012	MIDTOWN SERVICE CENTER INC	Automotive Repair Shops, NEC

A18 **LOT 50,TAXBLOCK 715** **NY E DESIGNATION** **S108076964**
WNW **436 WEST 18 STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.002 mi.
8 ft. **Site 11 of 19 in cluster A**

Relative: E DESIGNATION:
Lower

Actual:
13 ft.

Name:	LOT 50,TAXBLOCK 715
Address:	436 WEST 18 STREET
City,State,Zip:	MANHATTAN, NY
Tax Lot(s):	50
Tax Block:	715
Borough Code:	Not reported
E-No:	E-142
Effective Date:	6/23/2005
Satisfaction Date:	Not reported
Ceqr Number:	03DCP069M
Ulurp Number:	050161 ZRM
Zoning Map No:	8b
Description:	Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date:	Not reported
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported

LOT 50,TAXBLOCK 715 (Continued) **S108076964**

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

B19 **157-21 9TH AVE/QUEENS** **NY Spills** **S102141876**
NE **157021 9TH AVENUE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.003 mi.
17 ft. **Site 6 of 33 in cluster B**

Relative: Higher
Actual: 15 ft.

SPILLS:

Name:	157-21 9TH AVE/QUEENS
Address:	157021 9TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8900505 / 2003-02-10
Facility ID:	8900505
Facility Type:	ER
DER Facility ID:	200398
Site ID:	243994
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	4101
Spill Date:	1989-04-17
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1989-04-17
CID:	Not reported
Water Affected:	LITTLE NECK BAY
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-04-18
Spill Record Last Update:	2003-02-10
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"USCG TO INVESTIGATE, WANT CALL BACK FROM DEC, USCG WILL SEND CAR TO INVESTIGATE."

All Materials:

Site ID:	243994
Operable Unit ID:	926789
Operable Unit:	01
Material ID:	451843
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L

157-21 9TH AVE/QUEENS (Continued) **S102141876**

Recovered: .00
Oxygenate: Not reported

C20 **FREEDMAN CUTOUTS** **NY LTANKS** **S100493965**
West **444 WEST 17TH STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.003 mi.
18 ft. **Site 2 of 29 in cluster C**

Relative:
Lower

Actual:
12 ft.

LTANKS:

Name:	FREEDMAN CUTOUTS
Address:	444 WEST 17TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9206441 / 2000-12-21
Facility ID:	9206441
Site ID:	235146
Spill Date:	1992-09-03
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1992-09-03
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-09-04
Spill Record Last Update:	2008-05-22
Spiller Name:	Not reported
Spiller Company:	FREEDMAN CUTOUTS
Spiller Address:	444 WEST 17TH STREET
Spiller County:	001
Spiller Contact:	DONALD FREEDMAN
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	193681
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE TRANSFERED FROM TANG TO TIBBE ON 12/21/00. AKA 455 WEST 16TH STR."
Remarks:	"DISCOVERED DURING TANK PULL, GENE SULLIVAN OFFICE WAS NOTIFIED ABOUT JAN - FEB 92' ARE WORKING ON REMEDIATION."

All Materials:

Site ID:	235146
Operable Unit ID:	970151
Operable Unit:	01
Material ID:	410603
Material Code:	0009
Material Name:	gasoline

FREEDMAN CUTOUTS (Continued) **S100493965**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

E21 **BASEMENT** **NY Spills** **S117852170**
North **435 WEST 19TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.004 mi.
22 ft. **Site 1 of 15 in cluster E**

Relative: SPILLS:
Higher

Actual:
14 ft.

Name:	BASEMENT
Address:	435 WEST 19TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	1500497 / 2015-06-04
Facility ID:	1500497
Facility Type:	ER
DER Facility ID:	461425
Site ID:	506653
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3101
Spill Date:	2015-04-15
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2015-04-15
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-04-15
Spill Record Last Update:	2015-06-04
Spiller Name:	JASON LEE
Spiller Company:	JASON LEE
Spiller Address:	435 WEST 19TH ST
Spiller Company:	999
Contact Name:	FF RADOVIC
DEC Memo:	"04/15/15-Hiralkumar Patel. alternate address: 435-437 West 19th Street no PBS or other spills found. 11:29 AM:- spoke with FDNY Hazmat 1. during excavation for basement in existing building under renovation, contractor hit a previously closed-in-place tank. the tank was filled with water and some residual fuel. oil/water mixture spilled onto soil in the excavation. 11:33 AM:- spoke with Mr. Lee, property owner. he is in process of hiring an environmental contractor. Mr. Lee mentioned that the tank is 4 ft long. Project 19 Highline LLC. **property owner** c/o Six Sigma NYC 213 W 35th Street, Suite 400A New York, NY 10001 Attn.: Jason Lee PH. (212) 381-0010

BASEMENT (Continued) **S117852170**

(646) 275-0764 email: jlee@sixsigmanyc.com 12:17 PM:- sent letter to Mr. Lee requiring endpoint samples. asked him to submit report by the end of 05/29/15. letter emailed to Mr. Lee. 05/26/15-Hiralkumar Patel. 3:00 PM:- visited site and met Linda, on-site supervisor. inspected building basement. odors noted in basement. Linda mentioned that they are spraying vinegar in basement to control any petroleum odors from tank excavation pit. found tank on basement floor. Linda mentioned that Mellenium Tank Maintenance removed the tank and has collected samples for lab analysis. found groundwater in tank excavation, approx. 5 ft below basement floor. no sheen or product noted on groundwater. Israel Mellenium Tank Maintenance Ph. (917) 600-3268 **report due on 05/29/15.** 6/4/15 TJD File review. Spill reassigned Patel to DeMeo - Patel on extended vacation leave. Pending real estate transaction of property. Millenium tank service has submitted required closure documentation including: Tank Test report - (failing) prior to removal of out of service tank Lab Report - 4/23/15 Lab report - 5/15/15 FDNY tank closure affidavit Waste manifests Scrap metal disposal ticket photos email Based upon review of documentation submitted in support of spill closure - all target analytes are within acceptable concentrations. A total of 10 drums of petroleum impacted soils were excavated, transported offsite and properly disposed of. No further action is required. Spill closed."

Remarks: "An abandoned tank was struck while an excavation was being done in the basement. The contents spilled to soil in the basement. Clean up has been done."

All Materials:

Site ID:	506653
Operable Unit ID:	1255998
Operable Unit:	01
Material ID:	2258790
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

E22 **CON EDISON SERVICE BOX: 3424** **RCRA NonGen / NLR 1016449945**
NNW **426 W 19TH ST** **NY MANIFEST NYP004255865**
< 1/8 **NEW YORK, NY 10011**
0.005 mi.
24 ft. **Site 2 of 15 in cluster E**

Relative: **Lower**
Actual: **13 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130319
Handler Name:	CON EDISON SERVICE BOX: 3424
Handler Address:	426 W 19TH ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004255865
Contact Name:	JUAN RODRIGUEZ
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	347-865-5931
Contact Fax:	Not reported

CON EDISON SERVICE BOX: 3424 (Continued) **1016449945**

Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A

CON EDISON SERVICE BOX: 3424 (Continued) **1016449945**

Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130219
Handler Name: CON EDISON SERVICE BOX:	3424
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130319
Handler Name: CON EDISON SERVICE BOX:	3424
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON SERVICE BOX: 3424 (Continued) **1016449945**

NY MANIFEST:

Name:	CON EDISON
Address:	426 W 19TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004255865
Facility Status:	Not reported
Location Address 1:	426 W 19TH ST
Code:	BP
Location Address 2:	SERV BOX 3424
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004255865
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/19/2013
Trans1 Recv Date:	02/19/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004255865
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840417JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON SERVICE BOX: 3424 (Continued) **1016449945**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A23 **CON EDISON SERVICE BOX: 39651** **RCRA NonGen / NLR** **1016449943**
SE **121 9TH AVE** **NY MANIFEST** **NYP004255345**
< 1/8 **NEW YORK, NY 10011**
0.005 mi.
28 ft. **Site 12 of 19 in cluster A**

Relative: **Higher**

Actual: **15 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130319
Handler Name:	CON EDISON SERVICE BOX: 39651
Handler Address:	121 9TH AVE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004255345
Contact Name:	JUAN RODRIGUEZ
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	347-865-5931
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No

CON EDISON SERVICE BOX: 39651 (Continued) **1016449943**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:
Receive Date: 20130219

CON EDISON SERVICE BOX: 39651 (Continued) **1016449943**

Handler Name: CON EDISON SERVICE BOX: 39651
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130319
Handler Name: CON EDISON SERVICE BOX: 39651
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 121 9TH AVE
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004255345
Facility Status: Not reported
Location Address 1: 121 9TH AVE
Code: BP
Location Address 2: SERV BOX 39651
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004255345
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL

CON EDISON SERVICE BOX: 39651 (Continued) **1016449943**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/19/2013
Trans1 Recv Date:	02/19/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004255345
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840415JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A24
SE
< 1/8
0.005 mi.
28 ft.

CON EDISON SERVICE BOX: 39650
117 9TH AVE
NEW YORK, NY 10011

Site 13 of 19 in cluster A

NJ MANIFEST **S120665926**
N/A

Relative:
Higher

Actual:
15 ft.

NJ MANIFEST:

EPA Id:	NYP004255287
Mail Address:	Not reported
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JUAN RODRIGUEZ
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	000262623GBF
EPA ID:	NYP004255287
Date Shipped:	6/17/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON SERVICE BOX: 39650 (Continued) **S120665926**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	300.00 gallons

A25 **CON EDISON SERVICE BOX: 39650** **RCRA NonGen / NLR** **1016449942**
SE **117 9TH AVE SB 39650** **FINDS** **NYP004255287**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.005 mi. **NY MANIFEST**
28 ft. **Site 14 of 19 in cluster A**

Relative:
Higher

Actual:
15 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20130319
Handler Name:	CON EDISON SERVICE BOX:	39650
Handler Address:		117 9TH AVE SB 39650
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004255287
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No

CON EDISON SERVICE BOX: 39650 (Continued) **1016449942**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130219
Handler Name: CON EDISON SERVICE BOX:	39650
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON SERVICE BOX: 39650 (Continued) **1016449942**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130319
Handler Name: CON EDISON SERVICE BOX: 39650
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055935831

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016449942
Registry ID: 110055935831
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055935831
Name: CON EDISON SERVICE BOX: 39650
Address: 117 9TH AVE SB 39650
City,State,Zip: NEW YORK, NY 10011

NY MANIFEST:
Name: CON EDISON
Address: 117 9TH AVE
City,State,Zip: NEW YORK, NY 10011

CON EDISON SERVICE BOX: 39650 (Continued) **1016449942**

Country:	USA
EPA ID:	NYP004255287
Facility Status:	Not reported
Location Address 1:	117 9TH AVE
Code:	BP
Location Address 2:	SERV BOX 39650
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004255287
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/19/2013
Trans1 Recv Date:	02/19/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004255287
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840414JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON SERVICE BOX: 39650 (Continued) **1016449942**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

D26 **CON EDISON SERVICE BOX: 39635** **RCRA NonGen / NLR** **1016449927**
South **87 9TH AVE** **NY MANIFEST** **NYP004252888**
< 1/8 **NEW YORK, NY 10014**
0.005 mi.
29 ft. **Site 2 of 9 in cluster D**

Relative: **Higher**
Actual: **15 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130318
Handler Name:	CON EDISON SERVICE BOX:	39635
Handler Address:		87 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004252888
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No

CON EDISON SERVICE BOX: 39635 (Continued) **1016449927**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130218
Handler Name: CON EDISON SERVICE BOX:	39635
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

CON EDISON SERVICE BOX: 39635 (Continued) **1016449927**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130318
Handler Name: CON EDISON SERVICE BOX: 39635
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 87 9TH AVE
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYP004252888
Facility Status: Not reported
Location Address 1: 87 9TH AVE
Code: BP
Location Address 2: SERV BOX 39635
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004252888
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003

CON EDISON SERVICE BOX: 39635 (Continued) **1016449927**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/18/2013
Trans1 Recv Date:	02/18/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004252888
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840404JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A27
NW
< 1/8
0.006 mi.
30 ft.

COE BRANDT CAREFUL CARPET CLEANING CO INC — **EDR Hist Cleaner** — **1009163522**
419 423 E 18TH TEL MURRAY HITL 0132 — **N/A**
MANHATTAN, NY

Site 15 of 19 in cluster A

Relative:
Lower

Actual:
13 ft.

EDR Hist Cleaner

Year:	Name:	Type:
1923	COE BRANDT CAREFUL CARPET CLE	ORIENTAL RUG CLEANERS

A28
SSE
< 1/8
0.006 mi.
32 ft.

CON EDISON SERVICE BOX: 39641 — **RCRA NonGen / NLR** — **1016449935**
103 9TH AVE — **NY MANIFEST** — **NYP004254470**
NEW YORK, NY 10014

Site 16 of 19 in cluster A

Relative:
Higher

Actual:
15 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20130318
Handler Name:	CON EDISON SERVICE BOX:	39641
Handler Address:		103 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004254470
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported

CON EDISON SERVICE BOX: 39641 (Continued) **1016449935**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130218
Handler Name: CON EDISON SERVICE BOX:	39641
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130318

CON EDISON SERVICE BOX: 39641 (Continued) **1016449935**

Handler Name: CON EDISON SERVICE BOX: 39641
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 103 9TH AVE
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYP004254470
Facility Status: Not reported
Location Address 1: 103 9TH AVE
Code: BP
Location Address 2: SERV BOX 39641
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004254470
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE FLOOR 15
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported

CON EDISON SERVICE BOX: 39641 (Continued) **1016449935**

Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/18/2013
Trans1 Recv Date:	02/18/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/19/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004254470
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840409JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C29 **LOT 7,TAXBLOCK 715** **NY E DESIGNATION** **S108077007**
WNW **447 WEST 17 STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.006 mi.
34 ft. **Site 3 of 29 in cluster C**

Relative: E DESIGNATION:
Lower

Name:	LOT 7,TAXBLOCK 715
Address:	447 WEST 17 STREET
City,State,Zip:	MANHATTAN, NY
Tax Lot(s):	7
Tax Block:	715

Actual:
12 ft.

LOT 7,TAXBLOCK 715 (Continued) **S108077007**

Borough Code:	Not reported
E-No:	E-142
Effective Date:	6/23/2005
Satisfaction Date:	Not reported
Ceqr Number:	03DCP069M
Ulurp Number:	050161 ZRM
Zoning Map No:	8b
Description:	Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date:	Not reported
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

C30 **LOT 16,TAXBLOCK 714** **NY E DESIGNATION** **S108076878**
WSW **431 WEST 16 STREET** **N/A**
< 1/8 **MANHATTAN, NY 10011**
0.006 mi.
34 ft. **Site 4 of 29 in cluster C**

Relative: **Lower**
Actual: **13 ft.**

E DESIGNATION:

Name:	LOT 16,TAXBLOCK 714
Address:	431 WEST 16 STREET
City,State,Zip:	MANHATTAN, NY 10011
Tax Lot(s):	16
Tax Block:	714
Borough Code:	MN
E-No:	E-142
Effective Date:	6/23/2005
Satisfaction Date:	Not reported
Ceqr Number:	03DCP069M
Ulurp Number:	050161 ZRM
Zoning Map No:	8b
Description:	Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date:	Not reported
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

D31 **CON EDISON** **NY MANIFEST** **S117058351**
South **9 AVE & 16 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.007 mi.
36 ft. **Site 3 of 9 in cluster D**

Relative: **Higher**
Actual: **15 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	9 AVE & 16 ST
City,State,Zip:	NEW YORK, NY 10011

CON EDISON (Continued) **S117058351**

Country:	USA
EPA ID:	NYP004504361
Facility Status:	Not reported
Location Address 1:	9 AVE & 16 ST
Code:	BP
Location Address 2:	SB63404
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004504361
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/17/2014
Trans1 Recv Date:	04/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004504361
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694207JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117058351**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

D32 **CON EDISON** **NY MANIFEST** **S117058295**
South **9 AVE & 16 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.007 mi.
36 ft. **Site 4 of 9 in cluster D**

Relative:
Higher

Actual:
15 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	9 AVE & 16 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004503157
Facility Status:	Not reported
Location Address 1:	9 AVE & 16 ST
Code:	BP
Location Address 2:	SB39642
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004503157
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018

CON EDISON (Continued) **S117058295**

Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/16/2014
Trans1 Recv Date:	04/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004503157
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694210JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

D33 **CON EDISON** **RCRA-LQG** **1026059514**
South **W 16TH ST & 9TH AVE** **NYP005244868**
< 1/8 **NEW YORK, NY 10011**
0.007 mi.
36 ft. **Site 5 of 9 in cluster D**

Relative: RCRA-LQG:
Higher

Date Form Received by Agency:		20191203
Handler Name:	CON EDISON	
Handler Address:		W 16TH ST & 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP005244868
Contact Name:		THOMAS TEELING

Actual:
15 ft.

CON EDISON (Continued) **1026059514**

Contact Address:	IRVING PL, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	Yes
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking

CON EDISON (Continued) **1026059514**

Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200219
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20191203
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

B34 **CON EDISON** **NJ MANIFEST** **S120677598**
ENE **W 19TH ST & 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.008 mi.
43 ft. **Site 7 of 33 in cluster B**

Relative: **Higher**
Actual: **16 ft.**

NJ MANIFEST:

EPA Id:	NYP004848620
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported

CON EDISON (Continued) **S120677598**

Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	013245398JJK
EPA ID:	NYP004848620
Date Shipped:	10/6/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

B35 **CON EDISON** **RCRA NonGen / NLR** **1019908677**
ENE **W 19TH ST & 9TH AVE** **ECHO** **NYP004848620**
< 1/8 **NEW YORK, NY 10011**
0.008 mi.
43 ft. **Site 8 of 33 in cluster B**

Relative: **Higher**
Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20151006
Handler Name:	CON EDISON	
Handler Address:		W 19TH ST & 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004848620
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1019908677**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20151006
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20151006
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1019908677**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

ECHO:
Envid: 1019908677
Registry ID: 110069680786
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069680786
Name: CON EDISON
Address: W 19TH ST & 9TH AVE
City,State,Zip: NEW YORK, NY 10011

B36 **CON EDISON** **NY MANIFEST** **S117067453**
ENE **9 AVE & EAST 19 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.008 mi.
43 ft. **Site 9 of 33 in cluster B**

Relative:
Higher

Actual:
16 ft.

NY MANIFEST:
Name: CON EDISON
Address: 9 AVE & EAST 19 ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004603163
Facility Status: Not reported
Location Address 1: 9 AVE & EAST 19 ST
Code: BP
Location Address 2: SB 39670
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004603163
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

CON EDISON (Continued) **S117067453**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/21/2014
Trans1 Recv Date:	07/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004603163
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504407GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	700
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B37 **CON EDISON** **NY MANIFEST** **S117067457**
ENE **9TH AVE & W 19TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.008 mi.
43 ft. **Site 10 of 33 in cluster B**

Relative:
Higher

Actual:
16 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	9TH AVE & W 19TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004603247
Facility Status:	Not reported
Location Address 1:	9TH AVE & W 19TH ST
Code:	BP
Location Address 2:	MH 39671
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004603247
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/21/2014
Trans1 Recv Date:	07/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004603247
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504408GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117067457**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B38 **CON EDISON** **NY MANIFEST** **S119078201**
ENE **W 19TH ST & 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.008 mi.
43 ft. **Site 11 of 33 in cluster B**

Relative: **Higher**
Actual: **16 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	W 19TH ST & 9TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004848620
Facility Status:	Not reported
Location Address 1:	W 19TH & 9TH AVE
Code:	BP
Location Address 2:	DRIP WATER
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004848620
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S119078201**

Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/06/2015
Trans1 Recv Date:	10/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004848620
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245398JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B39 **CON ED** **NY MANIFEST** **S119073728**
ENE **19TH ST & 9TH AVE NW** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.008 mi.
43 ft. **Site 12 of 33 in cluster B**

Relative:
Higher

Actual:
16 ft.

NY MANIFEST:

Name:	CON ED
Address:	19TH ST & 9TH AVE NW
City,State,Zip:	NEW YORK, NY 10003
Country:	USA
EPA ID:	NYP004350559
Facility Status:	Not reported
Location Address 1:	19 STREET NW 9 AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004350559
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/24/2013
Trans1 Recv Date:	08/24/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/29/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004350559
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002016906GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON ED (Continued) **S119073728**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1514
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	B007
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B40 **CON ED ROADSIDE** **NY Spills** **S109582125**
ENE **WEST 19TH STREET/ AND 9TH AVE** **N/A**
< 1/8 **MANHATTAN, NY**
0.009 mi.
45 ft. **Site 13 of 33 in cluster B**

Relative: **Higher**
Actual: **16 ft.**

SPILLS:

Name:	CON ED ROADSIDE
Address:	WEST 19TH STREET/ AND 9TH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0900837 / 2009-06-03
Facility ID:	0900837
Facility Type:	ER
DER Facility ID:	361972
Site ID:	412795
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2009-04-22
Investigator:	Con Ed Unassigned
Referred To:	Not reported
Reported to Dept:	2009-04-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

CON ED ROADSIDE (Continued) **S109582125**

Remediation Phase:	0
Date Entered In Computer:	2009-04-22
Spill Record Last Update:	2009-06-03
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"06/03/09 - See eDocs for Con Ed report detailing cleanup and closure. "
Remarks:	"Clean up pending crew availability.-1/2 Gallon in to catch Basin-Unsure of the direction and path of the catch basin."

All Materials:

Site ID:	412795
Operable Unit ID:	1169250
Operable Unit:	01
Material ID:	2160905
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

C41 **CON EDISON** **NJ MANIFEST** **S120671338**
SW **440 W 16TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.009 mi.
48 ft. **Site 5 of 29 in cluster C**

Relative: **Lower**

Actual: **13 ft.**

NJ MANIFEST:

EPA Id:	NYP004777686
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002612032GBF
EPA ID:	NYP004777686
Date Shipped:	5/1/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported

CON EDISON (Continued) **S120671338**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

C42 **CON EDISON** **NY MANIFEST** **S119075026**
SW **440 W 16TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.009 mi.
48 ft. **Site 6 of 29 in cluster C**

Relative: NY MANIFEST:
Lower

Actual:
13 ft.

Name:	CON EDISON
Address:	440 W 16TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004777686
Facility Status:	Not reported
Location Address 1:	440 E 16TH ST
Code:	BP
Location Address 2:	BC 11554
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

CON EDISON (Continued) **S119075026**

NY MANIFEST:

EPAID:	NYP004777686
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	05/01/2015
Trans1 Recv Date:	05/01/2015
Trans2 Recv Date:	05/07/2015
TSD Site Recv Date:	05/07/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004777686
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002612032GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S119075026**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C43 **CON EDISON** **RCRA NonGen / NLR** **1019902774**
SW **440 W 16TH ST** **FINDS** **NYP004777686**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.009 mi.
48 ft. **Site 7 of 29 in cluster C**

Relative: **Lower**
Actual: **13 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150501
Handler Name:	CON EDISON	
Handler Address:		440 W 16TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004777686
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---

CON EDISON (Continued) **1019902774**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150501
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150501
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified

CON EDISON (Continued) **1019902774**

State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069694600

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019902774
Registry ID: 110069694600
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069694600
Name: CON EDISON
Address: 440 W 16TH ST
City,State,Zip: NEW YORK, NY 10011

F44 **CON EDISON** **NY MANIFEST** **S117058301**
SSE **9 AVE & 17 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.009 mi.
49 ft. **Site 1 of 20 in cluster F**

Relative: **Higher**
Actual: **16 ft.**

NY MANIFEST:
Name: CON EDISON
Address: 9 AVE & 17 ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004503363
Facility Status: Not reported

CON EDISON (Continued) **S117058301**

Location Address 1:	9 AVE & 17 ST
Code:	BP
Location Address 2:	SB39648
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004503363
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/17/2014
Trans1 Recv Date:	04/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004503363
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694213JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117058301**

Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C45 **VERIZON NEW YORK INC. (NY12048)** **NY AST** **A100382385**
WNW **438-454 WEST 18TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.009 mi.
50 ft. **Site 8 of 29 in cluster C**

Relative:
Lower

Actual:
13 ft.

AST:

Name:	VERIZON NEW YORK INC. (NY12048)
Address:	438-454 WEST 18TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-608026
Program Type:	PBS
UTM X:	584031.19197
UTM Y:	4510800.34633
Expiration Date:	N/A
Site Type:	Utility (Other than Municipal)

Tank Info:

Tank Number:	001
Tank Id:	64185
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/2002
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/05/2012
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	Not reported

C46 **VERIZON** **NY Spills** **S105058434**
WNW **438 WEST 18TH ST** **N/A**
< 1/8 **MANHATTAN, NY 10011**
0.009 mi.
50 ft. **Site 9 of 29 in cluster C**

Relative: **Lower**

Actual: **13 ft.**

SPILLS:

Name:	VERIZON
Address:	438 WEST 18TH ST
City,State,Zip:	MANHATTAN, NY 10011
Spill Number/Closed Date:	0103363 / 2015-04-15
Facility ID:	0103363
Facility Type:	ER
DER Facility ID:	192434
Site ID:	233558
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	3101
Spill Date:	2001-06-27
Investigator:	RVKETANI
Referred To:	030415 FINISHED REVIEW ENVIROTRAC 060409 RPT
Reported to Dept:	2001-06-27
CID:	396
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-06-27
Spill Record Last Update:	2015-11-12
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	JOHN QUATRALE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SUN 09/02/03 Reassigned from Tibbe to Rommel. 8/26/03 David Lorthioir e-mail 08/26/03 10:02AM It is currently owned by Retaco Holding Corp., which is affiliated with Mendon Leasing. The spill happened when construction was being performed on the building in 2001. While excavating near a former tank pit (tanks removed in 1993) contamination was encountered. Wells were installed and one of the wells on the sidewalk did show a small amount of product. Tibbe wanted the site investigated due to the possibility that the source of the floating product could have been an old coal-gas plant. The results show the product is gasoline. A short summary of this site, with maps and the lab analysis that Tibbe requested, is being sent to you today. We are requesting that we monitor the well in the sidewalk for a period of time and if no floating product is observed we be given a closure. Please call myself or John about this. David Lorthioir, Project Manager, EnviroTrac Ltd. 80B Air Park Dr. Ronkonkoma, NY 11779 p 631.471.1500 f 631.471.6363 For more information regarding our company's services, please visit our website at http://www.envirotrac.com. 11/17/03 Reassigned from Rommel

VERIZON (Continued) **S105058434**

to Sun. 01/30/04-Sun-File Update by Sun: On January 8, 2004, Sun sent a Stipulation Agreement to Patrick Veechione of Retaco Holding Corporation requiring the complete delineation of the contamination, including the installation of borings /wells at west of MW-8, east of MW-8 and north of MW-8, and submittal of Remedial Action Plan and Operation, Maintenance and Monitoring Plan. The Department set a deadline of February 9, 2004 for the Respondent to return the signed Stipulation Agreement. (WJS) 03/09/05-File Update by Sun: The investigation report submitted by the consultant, EnviroTrac, dated 06/02/04 summarizes the results of groundwater sampling performed on 04/13/04 at this site. The report indicated that groundwater samples secured from all the monitoring wells had BTEX and MTBE concentrations in excess of NYSDEC TAGM groundwater criteria., except MW-10, where MTBE was not detected. In particular, MW-8 had the highestBTEX concentration of 23,870 ug/L, which is higher than the BTEX concentrations of 13,870 ug/L sampled on January 17, 2004. On 10/28/04, Joe Sun conducted a site visit and had a site meeting with the consultant, David Lorthioir of EnviroTrac on the location for the additional off-site monitoring wells. After inspecting the site and discussing the current monitoring results, the Department requested the following three off-site wells be installed: 1)in the sidewalk outside the building, approximately 60 feet east of MW-8. Best location is just east of the roll-up door; 2) in the sidewalk outside the building, approximately 60 feet west of MW-8; and 3)in the sidewalk across the street from the building, approximately 30 feet west of MW-8. The above three off-site wells were installed on February 10, 2005. The results of the groundwater samples will be submitted in the next quarterly status report. The Department will request a remedial action plan be submitted after reviewing the next investigation summary report. (WJS) 03/14/05-File Update by Sun: On 03/11/05, Leonard Morrow (Phone # 212-964-4140 x303), Attorney representing the Property owner of this site (Retaco),informing Joe Sun by an e-mail that Con Ed and the DEC have entered into a Voluntary Cleanup Agreement (VCA) in regard to the site. The VCA number is D2-0003-02-08, dated August 15, 2002. Mr.Morrow requested in his e-mail that the DEC not require the owner to sign the Stipulation Agreement and not pursue enforcement of its remedies against Retaco. On 03/14/04, Joe Sun caled Mr. Morrow informing him that ConEd's VCA is to treat the MGP residuals, such as coal tar and purifier waste, not the petroleum related contaminations. Therefore, Retaco still has to sign the Stipulation Agreement and to perform the site characterization investigation followed by the submittal of a remedial action plan as required by the Corrective Action Plan attached to the Stipulation Agreement.(WJS) 12/13/05: Reviewed RAP dated 10/25/05. Bioremediation proposed to treat contamination. it will be impossible to remediate the site as petroleum contamination from off-site sources will constantly migrate onto the site. Therefore, it is EnviroTrac's plan to remediate groundwater at the site until background conditions, as defined by the upgradient wells . RAP approved. Many wells not sampled on 2/15/05. Max BTEX 19,410ppb (MW11) and max MTBE 520ppb (MW11). 3/23/06: Biorem application scheduled for 3/28/06 8:30am. 4/13/06: Received letter stating that biorem was applied. 7/26/06: Emailed David Lorthior for update on site. 7/31/06: Received email from David Lorthior. Wells will be sampled in August and a report submitted to the Department. 10/6/06: Emailed David Lorthior to followup on monitoring report submission. 10/13/06: Received email from David Lorthior: wells will be sampled

VERIZON (Continued) **S105058434**

on Friday, October 20. 10/25/06: Received email from David Lorthior: Just to update you on the above site, we went there to sample on Monday and discovered a drastic change in site conditions. Historically, all of the wells in the sidewalk and one well in the building (Wells MW-8, 9, 11, 12 & 13) all exhibited depth to water (DTW) that were about 4 to 5 feet lower than the other wells. This was attributed to some type of perched water condition or bedrock ledge beneath the building. On Monday we discovered that Wells MW-8, 9, 11, 12 & 13 are dry, or only have a slight amount of water in them. The interior wells are all at the expected DTWs. I do not know why the wells are dry. There is some major construction going on 1.5 blocks downgradient of the site. They could be de-watering. The building across the street has been demolished in the last few months. Other than that, I do not know. We sampled the interior wells. Results will be sent to you when we receive them. 12/11/06: Spoke to David Lorthior. He will submit report. 1/2/06: Emailed David Lorthior to followup on report submission. 1/11/07: Received and reviewed update report. Groundwater samples collected on 10/23/06. Four wells dry, including three on the sidewalk with high concentrations. Bioremediation parameters not monitored because many of the wells that were injected with bioremediation solution were dry. Sent letter requiring the following by 3/12/07: 1) new wells on the sidewalk to replace the mw that were dry, 2) bioremediation parameter monitoring, and 3) triannual monitoring and reporting instead of sem-annual. 2/15/07: Meeting scheduled on Thursday 2/22/07 at 10am with Retaco and EnviroTrac to discuss progress of remediation. 3/1/07: Meeting on 2/22/07 to discuss site progress. A FOIL request will be submitted for the CONED spills (BCP C231017, and Voluntary Cleanup site V00530). An upgradient well may be installed on W 18th Street. Wells will be sampled and a monitoring report submitted. 4/2/07: Emailed Dave Lorthior to followup on groundwater sampling, FOIL requests, and upgradient well installation. Received email from Dave Lorthior: Wells were sampled last week, results pending from Lab. We have been trying to obtain a copy of Keyspan's subsurface investigation report from Keyspan, but still waiting on that. Some interesting verbal information from Neil O'Hallaran of Keyspan. He said that two large foundations for the gas holders are present beneath the building. These foundations are 21 feet deep, and were simply filled in when the current building was constructed. Most of the wells in the building are located within these foundations. These foundations are not waterproof, but are resistant . This would explain why water beneath the building behaves separately from the water beneath 18th Street. Retaco and EnviroTrac are meeting with Keyspan on April 10 to try to hammer out some details regarding this matter. I will forward the laboratory results to you upon receipt. 5/2/07: Received email from Dave Lorthior. There are MGP foundations under the bldg that affect gw flow. Monitoring wells were sampled on 3/19/07. High BTEX concentrations in sidewalk wells. Bioremediation parameters weren't sampled? Off site source is still suspect in sidewalk wells. A formal report will be submitted in a few weeks . 7/9/07: Received report from EnviroTrac. Wells sampled on 3/17/07. Max BTEX 150,000 ppb (MW9), max MTBE 390 ppb (MW11). Eight MW's and former tanks are located within two holders that are relics of former MGP activity at this site. These holders extend into the groundwater, preventing any significant groundwater movement. Impact present in sidewalk wells may be migrating from off-site. MGP soil impact (VOC and sVOC) is present at 19-21 ft bg, well below the gw table (6 ft).

VERIZON (Continued) **S105058434**

Report states: It is EnviroTrac's opinion that any petroleum hydrocarbons found in the soil at that depth could not have migrated down through the groundwater, especially lighter hydrocarbons such as VOCs. However, MTBE present in the on-site wells within the holders contains low levels of MTBE, indicating gasoline impact. Called Dave Lorthior of EnviroTrac to discuss report. Spoke to Bill Ottaway (518-402-9564) in Central Office regarding ConEd MGP BCP C231017. 7/25/07: Con Ed. Contact is Neil O'Hallaran (718) 204-4145 or o'hallorann@coned.com. 7/30/07: Left voice message for Neil O'Hallaran. 8/9/07: Emailed Neil O'Hallaran and requested that he call to discuss site status. 8/15/07: Meeting on 8/14/07 with Neil O'Hallaran (Coned), DEC Region 2 Brevdo, Sun, Carlson and DEC CO Attaway (518-402-9686). Coned borings indicate that MGP and gasoline are vertically separated. Coned supplied boring logs and sampling data. The Department requested a site plan for the soil boring locations. CO has approved a Coned workplan to additionally delineate MGP waste. This property is Area 1 of a larger MGP cleanup extending over a number of properties. A remedial action plan will not be proprosed until after additional delineation. The site will probably not be excavated. Possible remedial options consist of chemox, SVE, and a SSDS. 9/24/07: Sent letter to Retaco and EnviroTrac indicating that an upgradient well, a RAP for impacted groundwater in the mgp foundations, and triannual groundwater sampling is required by November 2, 2007. 4/28/08 - Carlson: Reviewed a letter from 11/2/07 proposing two install two off-site wells and one on-site cluster well to delineate the vertical extent of the gasoline and MGP plumes. Emailed Dave Lorthior requesting a site plan with well locations. 5/7/08 - Carlson: Reviewed site plan with proposed well locations. 5/12/08 - Carlson: Approved investigation plan for installation of two on-site cluster wells and two off-site sidewalk wells. Cluster wells will four 1 wells each screened at : 20-21', 16-17', 12-13', 8-9'. The cluster wells will be located adjacent to MW5 (inside the MGP foundation), and MW9 (outside the MGP foundation). Remedial investigation report due 8/12/08. 7/24/08 - Carlson: Spoke to Dave Lorthior. Coned is planning on installing cluster wells in the building on August 10th. Envirotrac will install the off-site wells. He will call to confirm well installation date. 8/21/08 - Carlson: Witnessed well installation by Coned. Dave Lorthior of Envirotrac said he is going to install sidewalk wells tomorrow. 12/10/08 - Carlson: Called Dave Lorthior to check on status of investigation report. He has not received sampling data from Coned. He will check with Coned. 12/11/08 - Carlson: Received email from Dave Lorthior: I just spoke to Craig Massaro of Arcadis. He said that the data should be tabulated and sent to EnviroTrac in the next week or so. After I receive it we will generate a report. 1/16/09 - Carlson: Spoke to Dave Lorthior - he is waiting for Coned's data to finish report. Spoke to Neil O'Halloran - he will send boring logs to Dave Lorthior early next week. 5/13/09 - Carlson: Received letter from Neil O'Halloran, Coned report was sent to Central Office. Spoke to Dave Lorthior - his report will be submitted next week. 6/3/09 - Carlson: Received inquiry's from DEC Ottaway (Central Office), and Neil O'Halloran (Coned) regarding Retaco's report. Spoke to Dave Lorthior, report will be submitted by Monday. 6/4/09 - Carlson: Received Envirotrac report; 7/14/09 - Carlson: Spoke to Bill Ottaway in central office - he will draft letter in response to report.; 8/20/09 - Carlson: Received email from bill ottaway - albany will have meeting with coned before issuing letter; 3/1/2010 - Carlson: DEC

VERIZON (Continued) **S105058434**

Ottaway issued letter regarding Con Ed report. 2/25/15 - Raphael Ketani. I restarted the spill case. The spill was called in on 6/27/01. Contaminated soil was discovered while excavating for an elevator pit. An elevator never existed before at this specific location of the site. During an investigation, gasoline contamination was discovered. MGP waste was also discovered under the same location. The site used to be part of the location of two gas holders. The MGP site extends from West 16th Street to West 20th Street. The foundations for the gas holders go down 22 feet. In some places, the gasoline contamination and the MGP waste are colocated. In other places they are at different horizons. The MGP waste case is being managed as a voluntary cleanup project through an agreement between Con Ed and the DEC. The voluntary cleanup case number is V00530. The MGP waste case manager is Richard Dana in Albany Remediation (richard.dana@dec.ny.gov). The PBS case is #2-032298. The owner is Retaco Holding Corp at 362 Kingsland Avenue, Brooklyn, 11222. The contact is listed as Jim McElhinney at (718) 389-2100. There were 6 gasoline USTs (though one is depicted in the reports as a 550 gal. diesel UST). Five were 550 gals. each and one was 4,000 gals. All were closed on 12/1/93. I contacted the former consultant for Retaco Holding Corporation, Dave Lorthioir of EnviroTrac (631) 924-3001/cell (631) 872-0231, regarding the site. He said that Retaco was owned by Mendon Truck Leasing. Verizon was a tenant. EnviroTrac excavated lots of impacted soil around the tanks. So, the soil was cleaned up, but the problem was then the groundwater. EnviroTrac couldn't cleanup the groundwater due to the MGP waste always being present. Mr. Lorthioir stated that the amount of gasoline contamination was very small compared to the huge amount of MGP waste that was being recovered. 3/4/15 - Raphael Ketani. I finished my review of the EnviroTrac 6/4/09 Status Report. The investigation was perfomred during 2008 and gauging and sampling took place during January 2009. The site is block 715 and lot 59. The West 18th Street gas works were bounded by West 16th Street and West 20th Street and by the Hudson River and 10th Avenue. The parcel of land between West 17th Street and West 18th Street and West 10th Avenue was also part of the MGP area. The parcel is 438 West 18th Street (the Site). The diameter of the two gas holders reached from the northern boundary of the existing building footprint to the southern boundary. The former gas holder foundations went down to 21 feet below grade. The site was occupied by VERIZON as a parking garage and office space. Six USTs were removed on 12/12/93 from under the east side of the garage in the northeast corner. One was a 4,000 gal. diesel UST and the others were 550 gal. gasoline USTs. There was no evidence of soil contamination. When VERIZON installed an elevator pit in 2001, they found soil contamination. From June to September 2001, 120 cu. yds. of soil were removed and wells were installed. EnviroTrac installed 13 wells. Initially, the groundwater elevations in MW-1 to 7 and MW-10 were 4 to 5 feet higher than the interior well MW-09 and the exterior wells MW-8 and 11 to 13. EnviroTrac gauged and sampled all of the wells on 10/23/06. The exterior wells MW-8, 9, and 11 to 13 were either dry or had just 1 foot of water. Interior wells MW-1 to 7 and MW-10 had groundwater elevations comparable to the historic norms. The 11/17/06 gauging event showed that the exterior wells were still dry. Later, it was found that the interior wells, except MW-9, were within the footprints of the gas holder foundations. Wells MW-3 to 5 and MW-7 were within the eastern holder and MW-1, 2 and 10 were within the western holder. MW-9 was outside the holders. During March

VERIZON (Continued) **S105058434**

2007, all of the wells were sampled. The groundwater elevations in MW-8, 9 and 11 to 13 had dropped 6 to 7 feet in the wells in the former gas holders. This indicated that the holder foundations impeded groundwater migration. Con Ed investigated the site and determined that all of the BTEX was the result of the gasoline spill. However, MGP waste can contain BTEX (a lot of benzene). EnviroTrac contends that the migration of the BTEX to the groundwater 14 down inside of the holders was not plausible. EnviroTrac contends that the MGP waste in the western holder contributes to the VOC impacts to the groundwater in the western holder. EnviroTrac contends that the VOCs in the groundwater in MW-9 are from offsite as they appear in the groundwater at MW-12, which is upgradient of the USTs. Con Ed referred to the Retaco property as Area 1. The Con Ed January 2006 investigation report stated that they did test pits and found the gas holder foundations. The reports noted that soil samples from 15 feet down and deeper within the holders had MGP waste odors. Soil samples that were taken at SB-2 at 19 to 20.5 feet down and that were taken at SB-4 at 19 to 21 feet down had VOC exceedences. A fingerpint analysis showed that the soil had coal tar. Coal tar was not found in the borings outside of the gas holder foundations. Con Ed did an additional set of borings and wells on 8/21, 22 and 28/08 and on 9/5/08. Con Ed did 6 borings at the site. Boring SB-A was installed in the east holder. Boring SB-D was installed in the west holder. Boring SB-C was installed outside the holders near MW-9. Con Ed stated that no MGP sludge nor coal tar was encountered in any of the borings. However, some samples did have MGP waste odors. Soil samples above and below the water table had elevated PID readings. The soil samples consisted of fill. Well clusters A, B and C were installed by Con Ed in August and September 2008. Clusters A and C were installed in the west holder and B was installed in the east holder. The screens were set at 7 to 11 feet below grade as groundwater in the holders was 6 to 8 feet below grade. Intermediate screens were set at 13 to 15 feet below grade and deep screens were set at 18 to 20 feet below grade. On 8/21/08, EnviroTrac isntalled 2 borings, B-14 and B-15. The MW-14 well was installed 15 feet west of the property line between the site and the Midtown Chelsea Auto Center. The borings went to 15 feet below grade. All of the material encountered was fill. In boring B-14, the soil from grade to 7 feet below had petroleum odors. From 7 to 13 feet below grade there were slight odors. B-15 did not have petroleum odors nor stains and was made into well MW-15. Groundwater was monitored on 1/15/09 by EnviroTrac. The shallow wells at clusters A-1, B-1 and C-1 were all dry. The measured groundwater elevations indicated that the wells in the gas holder foundations and the wells outside the foundations now were at the same elevation. The difference of 7 feet between outside and inside the foundations no longer existed. Groundwater flow had been to the west and was now to the south. Shallow soil samples from SB-A at 2 and 8 feet below grade had minor or no VOCs, SVOCs or cyanide. The sample from 21 feet below grade had 1700 ppb benzene, 24,000 ppb naphthalene and 58,000 ppb cyanide. The soil sample from SB-B at 1 and 10 feet had minor to moderate VOCs, SVOCs and cyanide. The 20 foot sample from SB-B had 800 ppb benzene, 16,000 ppb naphthalene and 17,400 ppb cyanide. Soil samples were collected from well cluster A, well cluster C and boring SB-D in the former west holder foundation. Well cluster A had moderate benzene in the 12 foot, 17 foot and 20 foot samples. Naphthalene was 10,000 ppb in the 12 foot sample and 760 ppb in the 20 foot sample. Cyanide was present only in the 20

VERIZON (Continued) **S105058434**

foot sample at 1100 ppb. Well cluster C did not have benzene in the shallow samples. The 21 foot sample had 600,000 ppb of benzene and 640,000 ppb of naphthalene. Cyanide was 2200 ppb in the 11 foot sample and 27,700 ppb in the 21 foot sample. SB-D was non-detect for benzene and had minor hits of other VOCs in the 21 foot sample and the 24 foot sample. There was no naphthalene nor cyanide in the 12 foot sample, but minor naphthalene and cyanide in the 24 foot sample. For SB-C, there were no detectable target VOCs. The 14 foot sample and the 22 foot sample had 22,000 ppb naphthalene and 47,000 ppb napthalene, respectively. Cyanide was at a minor concentration. The 36 foot sample did not have naphthalene nor cyanide. EnviroTrac had soil samples from SB-B (20 feet down), B-14 (5-7 feet down), B-14 (11-13 feet down) and B-15 (11-13 feet down) analyzed. SB-B had 1500 ppb benzene, 3800 ppb total xylenes and 14,000 ppb naphthalene. B-14 in the 5-7 foot sample had 50,000 ppb naphthalene, 10,000 ppb 1,2,4-trimethylbenzene and 29,000 ppb naphthalene as an SVOC. The 11-13 foot sample from B-14 had 18,000 ppb naphthalene. The 11-13 foot sample from B-15 had SVOCs with slight exceedences of the benzo series of analytes. Con Ed and EnviroTrac performed joint groundwater sampling on 9/30, 10/1 and 10/2/08. Wells MW-1 to 5, 5A, 5B, 7, 8, 10 to 12 and cluster wells A-2, A-3, B-2, B-3, C-2 and C-3 were sampled. EnviroTrac by itself sampled MW-9, 14 and 15. The Con Ed data shows that all of the wells except 5A had exceedences of VOCs above the TAGM standards. All of the wells except 5A had elevated benzene - above what would have been expectde if gasoline was the sole source. The deeper cluster wells A-3, B-3 and C-3 had higher benzene concentrations than shallow wells A-2, B-2 and C-2. All of the samples except 5A, 8, 9, 14 and 15 had low to moderate MTBE. MW-8 and MW-9 had 4800ppb and 85,000 ppb of naphthalene, respectively. A comparison of the EnviroTrac lab results to the draft Con Ed data supports the VOC results obtained by EnviroTrac. EnviroTrac sampled groundwater on 1/15/09. All of the samples except MW-7, 14 and 15 had elevated VOCs above the standards. All of the samples except MW-7, 14 and 15 had elevated benzene - more than would be expected with gasoline as a source. The samples from the deeper cluster wells A-3, B-3 and C-3 had greater benzene than the samples from the shallow wells A-2 , B-2 and C-2. Several wells had low to moderate MTBE concentrations. EnviroTrac discussion in report: EnviroTrac notes that though no coal tar was found in the deep soil samples, there were coal tar odors. They also state that the deepest soil samples from within the eastern former gas holder foundation (21 feet at SB-A, 20 feet at SB-B) had elevated benzene, naphthalene and cyanide. The 20 foot sample from cluster C had extremely high conentrations of benzene, naphthalene and cyanide. The sample from SB-D did not exhibit elevated benzene, naphthalene and cyanide. The deep soil sample from cluster A had moderate concentrations. In EnviroTrac's opinion, the petroleum VOCs could not have moved down through the water table. The VOC contamination at depth is not related to the petroleum spill. The 14 to 22 foot samples from SB-C had elevated naphthalene. This sample was 10 feet below the water table. EnviroTrac believes that the contamination is due to the MGP waste. The impacted soil at B-14 was impacted down to the water table. This area is not near the USTs or any remote fills. The source may be the Midtown Chelsea Auto Center. The data from the September to October 2008 and January 2009 sampling events show that benzene concentrations were higher in the deep cluster wells than the shallow cluster wells. There were elevated benzene concentrations in the soil

VERIZON (Continued) **S105058434**

samples from just above the bottom of the former gas holder foundations indicating that benzene was diffusing from the MGP impacted fill and was becoming soluble in the groundwater. The former USTs were in the eastern former gas holder foundation. The former gas holder foundations are not hydraulically connected. In EnviroTrac's opinion, the VOC contamination in the western former gas holder foundation is not related to the former USTs. As MTBE is low, gasoline is not the primary contaminant. 3/26/15 - Raphael Ketani. I drafted a letter to Mendy Taffel, Chief Executive Officer, Retaco Holding Corp., 362 Kingsland Avenue, Brklyn., NY, 11222-1905. In the letter, I stated that Retaco had to do additional delineation of the gasoline contamination on the north side of the site. I added that wells must be installed in a series along the sidewalk on the north side of West 18th Street. These wells must be part of the well monitoring array and sampled at the same time as the other wells during the quarterly monitoring events. Lastly, quarterly groundwater analytical reports must be submitted to the Department. 3/30/15 - Raphael Ketani. The letter was approved by Hassan Hussein, EE III and head of Unit C. I sent the letter out today. 4/14/15 - Raphael Ketani. I received an email from Ronald Tramposch of Core Environmental that he is the new consultant for Retaco (rpt@coreenv.com). 4/15/15 - Raphael Ketani. Richard Dana of Albany DEC Remediation (518) 402-9662 sent an email to Barry at Mendon Leasing informing him that he will be handling both the MGP waste remediation and the gasoline spill remediation. As the gasoline spill will be managed by Mr. Dana as part of the remediation of the entire site, I am closing spill case effective today."

Remarks: "cont. soil found during excavation for new elevator pit. no elevator existed prior."

All Materials:

Site ID:	233558
Operable Unit ID:	840070
Operable Unit:	01
Material ID:	535451
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E47 **METROPOLITAN OLDSMOBILE INC** **NY UST** **1000367827**
NNW **440 W 19TH ST** **RCRA NonGen / NLR** **NYD981489230**
< 1/8 **NEW YORK, NY 10011** **FINDS**
0.010 mi. **ECHO**
53 ft. **Site 3 of 15 in cluster E**

Relative: **Lower**
Actual: **13 ft.**

UST:

Name:	METROPOLITAN OLDS, INC
Address:	440 WEST 19TH STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-349372 / Inactive
Program Type:	PBS
Region:	STATE

METROPOLITAN OLDSMOBILE INC (Continued) **1000367827**

DEC Region: 2
Expiration Date: N/A
UTM X: 583962.08734
UTM Y: 4510959.40563
Site Type: Unknown

Affiliation Records:

Site Id: 17197
Affiliation Type: Facility Owner
Company Name: METROPOLITAN OLDS, INC
Contact Type: Not reported
Contact Name: Not reported
Address1: 440 W 19TH ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10011
Country Code: 001
Phone: (212) 620-5800
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 17197
Affiliation Type: Mail Contact
Company Name: METROPOLITAN OLDS, INC
Contact Type: Not reported
Contact Name: Not reported
Address1: 440 W 19TH ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10011
Country Code: 001
Phone: (212) 620-5800
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 17197
Affiliation Type: Facility Operator
Company Name: METROPOLITAN OLDS, INC
Contact Type: Not reported
Contact Name: ROBERT RUBIN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NY
Zip Code: Not reported
Country Code: 001
Phone: (212) 620-5800
EMail: Not reported
Fax Number: Not reported
Modified By: ajsigona
Date Last Modified: 2004-06-08

METROPOLITAN OLDSMOBILE INC (Continued) **1000367827**

Site Id:	17197
Affiliation Type:	Emergency Contact
Company Name:	METROPOLITAN OLDS, INC
Contact Type:	Not reported
Contact Name:	A B C FUEL OIL CO, INC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 633-5600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ajsigona
Date Last Modified:	2004-06-08

Tank Info:

Tank Number:	001
Tank ID:	33487
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	1500
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	METROPOLITAN OLDSMOBILE INC
Handler Address:	440 W 19TH ST
Handler City,State,Zip:	NEW YORK, NY 10011-3802
EPA ID:	NYD981489230

METROPOLITAN OLDSMOBILE INC (Continued) **1000367827**

Contact Name:	Not reported
Contact Address:	W 19TH ST
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 19TH ST
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	OPERATING CORP
Owner Type:	Private
Operator Name:	OPERATING CORP
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No

METROPOLITAN OLDSMOBILE INC (Continued) **1000367827**

Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	OPERATING CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	438 W 19TH ST
Owner/Operator City,State,Zip:	NEW YORK, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	OPERATING CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	438 W 19TH ST
Owner/Operator City,State,Zip:	NEW YORK, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	OPERATING CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported

METROPOLITAN OLDSMOBILE INC (Continued) **1000367827**

Owner/Operator Address: 438 W 19TH ST
Owner/Operator City,State,Zip: NEW YORK, NY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19990708
Handler Name: METROPOLITAN OLDSMOBILE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: METROPOLITAN OLDSMOBILE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: METROPOLITAN OLDSMOBILE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19860716
Handler Name: METROPOLITAN OLDSMOBILE INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

METROPOLITAN OLDSMOBILE INC (Continued) **1000367827**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004406367

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000367827
Registry ID: 110004406367
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004406367
Name: METROPOLITAN OLDSMOBILE INC
Address: 440 W 19TH ST
City,State,Zip: NEW YORK, NY 10011

C48 **LOT 59,TAXBLOCK 715** **NY E DESIGNATION** **S108076983**
WNW **442 WEST 18 STREET** **N/A**
< 1/8 **MANHATTAN, NY 10011**
0.010 mi.
53 ft. **Site 10 of 29 in cluster C**

Relative: **Lower**
Actual: **12 ft.**

E DESIGNATION:
Name: LOT 59,TAXBLOCK 715
Address: 442 WEST 18 STREET
City,State,Zip: MANHATTAN, NY 10011
Tax Lot(s): 59
Tax Block: 715
Borough Code: MN
E-No: E-142
Effective Date: 6/23/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP069M
Ulurp Number: 050161 ZRM
Zoning Map No: 8b

LOT 59,TAXBLOCK 715 (Continued) **S108076983**

Description: Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date: Not reported

Description: Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

A49 **188TH STREET AND** **NY Spills** **S106008612**
ESE **188TH ST & COLUMBUS AVE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.010 mi.
53 ft. **Site 17 of 19 in cluster A**

Relative:
Higher

Actual:
16 ft.

SPILLS:

Name:	188TH STREET AND
Address:	188TH ST & COLUMBUS AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	0207606 / 2002-12-23
Facility ID:	0207606
Facility Type:	ER
DER Facility ID:	92646
Site ID:	104941
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2002-10-22
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2002-10-22
CID:	282
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-10-22
Spill Record Last Update:	2003-04-08
Spiller Name:	PASHKO CAMAJ
Spiller Company:	NEW YORK CITY TRANSIT
Spiller Address:	370 JAY STREET
Spiller Company:	001
Contact Name:	PASHKO CAMAJ
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 10/23/02 - All contained and no sewer or drain involved. It had been cleaned up by Department of Sanitation by the time of notify. jz Contained and cleaned by NYCT. No impact to sewers or soil."
Remarks:	"bus number 1047 power steering line broke on the bus spill cleaned up. cell number for pashko 516-902-0588"

All Materials:

Site ID:	104941

188TH STREET AND (Continued) **S106008612**

Operable Unit ID:	860414
Operable Unit:	01
Material ID:	518182
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	9.00
Units:	G
Recovered:	9.00
Oxygenate:	Not reported

C50 **SPILL NUMBER 0012292** **NY Spills** **S104951390**
SW **448 WEST 16TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.010 mi.
55 ft. **Site 11 of 29 in cluster C**

Relative: **Lower**

Actual: **13 ft.**

SPILLS:

Name:	SPILL NUMBER 0012292
Address:	448 WEST 16TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0012292 / 2003-05-09
Facility ID:	0012292
Facility Type:	ER
DER Facility ID:	109546
Site ID:	126808
DEC Region:	2
Spill Cause:	Traffic Accident
Spill Class:	C3
SWIS:	3101
Spill Date:	2001-02-15
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2001-02-15
CID:	211
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-02-15
Spill Record Last Update:	2003-05-09
Spiller Name:	Not reported
Spiller Company:	KATZMAN PRODUCE
Spiller Address:	NY CITY TERMINAL MARKET
Spiller Company:	001
Contact Name:	JOHN GIORDANO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND 5/9/2003 Spill Administratively Closed."
Remarks:	"SADDLE TANK RUPTURED AFTER ACCIDENT - FIRE DEPT ON SCENE AND SPILL CLEANED UP"

SPILL NUMBER 0012292 (Continued) **S104951390**

All Materials:

Site ID:	126808
Operable Unit ID:	833815
Operable Unit:	01
Material ID:	542568
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	40.00
Oxygenate:	Not reported

C51 **VAULT 632** **NY Spills** **S104508951**
SW **448 W 16TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.010 mi.
55 ft. **Site 12 of 29 in cluster C**

Relative: **Lower**

Actual: **13 ft.**

SPILLS:

Name:	VAULT 632
Address:	448 W 16TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9911744 / 2002-03-04
Facility ID:	9911744
Facility Type:	ER
DER Facility ID:	231619
Site ID:	285735
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2000-01-09
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-01-09
CID:	312
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-01-09
Spill Record Last Update:	2002-03-04
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL "

VAULT 632 (Continued) **S104508951**

Remarks: "FROM FEEDER# 13M64 - 1 QT SPILLED - CASE #129538 - CLEANUP PENDING SAMPLE RESULTS - MARK TIBBE ADVISED"

All Materials:

Site ID:	285735
Operable Unit ID:	1090436
Operable Unit:	01
Material ID:	297191
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C52 **OXYGEN MEDIA** **RCRA NonGen / NLR** **1001818145**
SW **448 W 16TH ST** **NYR000076299**
< 1/8 **NEW YORK, NY 10011**
0.010 mi.
55 ft. **Site 13 of 29 in cluster C**

Relative: **Lower**
Actual: **13 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	OXYGEN MEDIA	
Handler Address:		448 W 16TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYR000076299
Contact Name:		IRWIN COHEN
Contact Address:		W 16TH ST
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		212-243-6005
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		W 16TH ST
Mailing City,State,Zip:		NEW YORK, NY 10011
Owner Name:		CFG AGSCB CHELSEA NINTH LLC
Owner Type:		Private
Operator Name:		CFG AGSCB CHELSEA NINTH LLC
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No

OXYGEN MEDIA (Continued) **1001818145**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D002
Waste Description:	CORROSIVE WASTE

OXYGEN MEDIA (Continued) **1001818145**

Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CFG AGSCB CHELSEA NINTH LLC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 88 10TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 212-243-6005
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CFG AGSCB CHELSEA NINTH LLC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 88 10TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 212-243-6005
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CFG AGSCB CHELSEA NINTH LLC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 88 10TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 212-243-6005
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: OXYGEN MEDIA
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: OXYGEN MEDIA

OXYGEN MEDIA (Continued) **1001818145**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19990908
Handler Name: OXYGEN MEDIA	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010101
Handler Name: OXYGEN MEDIA	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	51321
NAICS Description:	SOFTWARE PUBLISHERS

Facility Has Received Notices of Violation:

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Records/Reporting
Date Violation was Determined:	20000719
Actual Return to Compliance Date:	20001016
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	20000729
Enforcement Identifier:	000
Date of Enforcement Action:	20000719
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	NY
Corrective Action Component:	No

OXYGEN MEDIA (Continued) **1001818145**

Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYDEC
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20000301
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20001016
Scheduled Compliance Date:	20000729
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

D53 **GOOGLE LLC** **RCRA-VSQG** **1000423858**
South **76 9TH AVE** **NY MANIFEST** **NYD001328368**
< 1/8 **NEW YORK, NY 10011**
0.011 mi.
56 ft. **Site 6 of 9 in cluster D**

Relative: RCRA-VSQG:
Higher

Date Form Received by Agency:		20180919
Handler Name:	GOOGLE LLC	
Handler Address:		76 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYD001328368
Contact Name:		JOE CLARK
Contact Address:		AMPHITHEATRE PKWY
Contact City,State,Zip:		MOUNTAIN VIEW, CA 94043
Contact Telephone:		408-921-0508
Contact Fax:		Not reported
Contact Email:		EHS-ENV@GOOGLE.COM

Actual:
16 ft.

GOOGLE LLC (Continued) **1000423858**

Contact Title:	EHS MANAGER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	AMPHITHEATRE PKWY
Mailing City,State,Zip:	MOUNTAIN VIEW, CA 94043
Owner Name:	GOOGLE LLC
Owner Type:	Private
Operator Name:	GOOGLE LLC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported

GOOGLE LLC (Continued) **1000423858**

Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181116
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GOOGLE INC
Legal Status:	Private
Date Became Current:	20101201
Date Ended Current:	Not reported
Owner/Operator Address:	1600 AMPHITHEATRE PKWY
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94043
Owner/Operator Telephone:	925-413-7150
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

GOOGLE LLC (Continued) **1000423858**

Owner/Operator Indicator:	Owner
Owner/Operator Name:	FRITZSCHE DODGE & OLCOTT INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	FRITZSCHE DODGE & OLCOTT INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	FRITZSCHE DODGE & OLCOTT INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	GOOGLE INC
Legal Status:	Private
Date Became Current:	20101201
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	GOOGLE LLC
Legal Status:	Private
Date Became Current:	20101201
Date Ended Current:	Not reported
Owner/Operator Address:	1600 AMPHITHEATRE PKWY
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94043
Owner/Operator Telephone:	925-413-7150
Owner/Operator Telephone Ext:	Not reported

GOOGLE LLC (Continued) **1000423858**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: GOOGLE LLC
Legal Status: Private
Date Became Current: 20101201
Date Ended Current: Not reported
Owner/Operator Address: 1600 AMPHITHEATRE PKWY
Owner/Operator City,State,Zip: MOUNTAIN VIEW, CA 94043
Owner/Operator Telephone: 925-413-7150
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19961004
Handler Name: FRITZSCHE DODGE & OLCOTT INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: FRITZSCHE DODGE & OLCOTT INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: FRITZSCHE DODGE & OLCOTT INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800818
Handler Name: FRITZSCHE DODGE & OLCOTT INC

GOOGLE LLC (Continued) **1000423858**

Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160614
Handler Name: GOOGLE INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180919
Handler Name: GOOGLE LLC	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	19960301
Handler Name: BASF CORP	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	32511
NAICS Description:	PETROCHEMICAL MANUFACTURING

NAICS Code:	325998
NAICS Description:	ALL OTHER MISCELLANEOUS CHEMICAL PRODUCT AND PREPARATION MANUFACTURING

GOOGLE LLC (Continued) **1000423858**

NAICS Code: 511210
NAICS Description: SOFTWARE PUBLISHERS

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported

GOOGLE LLC (Continued) **1000423858**

Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported

GOOGLE LLC (Continued) **1000423858**

Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19860919
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYDEC
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19960912
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2ME
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19960606
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2RDL
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

NY MANIFEST:
Name: BASF CORPORATION
Address: 76 9TH AVE
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYD001328368
Facility Status: Not reported
Location Address 1: 76 9TH AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported

GOOGLE LLC (Continued) **1000423858**

Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD001328368
Mailing Name: BASF CORPORATION
Mailing Contact: MARCOLLE PERRY
Mailing Address 1: 111 9TH AVENUE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10048
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2014262662

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD080631369
Trans2 State ID: Not reported
Generator Ship Date: 09/12/2017
Trans1 Recv Date: 09/12/2017
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/12/2017
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001328368
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD980536593
TSDF ID 2: Not reported
Manifest Tracking Number: 001163613VES
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 1
Units: P - Pounds
Number of Containers: 1

GOOGLE LLC (Continued) **1000423858**

Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

D54 **GIVAUDAN CORP C/O FRITZSCHE DIV** **RCRA NonGen / NLR** **1000458101**
South **76 NINTH AVE** **NYD986934305**
< 1/8 **NEW YORK, NY 10011**
0.011 mi.
56 ft. **Site 7 of 9 in cluster D**

Relative: **Higher**
Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	GIVAUDAN CORP C/O FRITZSCHE DIV
Handler Address:	76 NINTH AVE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYD986934305
Contact Name:	Not reported
Contact Address:	NINTH AVE 13TH FLR
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	NINTH AVE 13TH FLR
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	PA BLDG CO
Owner Type:	Private
Operator Name:	PA BLDG CO
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

GIVAUDAN CORP C/O FRITZSCHE DIV (Continued) **1000458101**

Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D003
Waste Description:	REACTIVE WASTE
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE,

GIVAUDAN CORP C/O FRITZSCHE DIV (Continued) **1000458101**

CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F003
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: NONE
Waste Description: Not Defined

Waste Code: U001
Waste Description: ACETALDEHYDE (I) (OR) ETHANAL (I)

Waste Code: U002
Waste Description: 2-PROPANONE (I) (OR) ACETONE (I)

Waste Code: U004
Waste Description: ACETOPHENONE (OR) ETHANONE, 1-PHENYL-

Waste Code: U031
Waste Description: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Waste Code: U052
Waste Description: CRESOL (CRESYLIC ACID) (OR) PHENOL, METHYL-

Waste Code: U056
Waste Description: BENZENE, HEXAHYDRO- (I) (OR) CYCLOHEXANE (I)

Waste Code: U057
Waste Description: CYCLOHEXANONE (I)

Waste Code: U075
Waste Description: DICHLORODIFLUOROMETHANE (OR) METHANE, DICHLORODIFLUORO-

Waste Code: U080

GIVAUDAN CORP C/O FRITZSCHE DIV (Continued) **1000458101**

Waste Description: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

Waste Code: U088
Waste Description: 1,2-BENZENEDICARBOXYLIC ACID, DIETHYL ESTER (OR) DIETHYL PHTHALATE

Waste Code: U102
Waste Description: 1,2-BENZENEDICARBOXYLIC ACID, DIMETHYL ESTER (OR) DIMETHYL PHTHALATE

Waste Code: U103
Waste Description: DIMETHYL SULFATE (OR) SULFURIC ACID, DIMETHYL ESTER

Waste Code: U112
Waste Description: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

Waste Code: U123
Waste Description: FORMIC ACID (C,T)

Waste Code: U125
Waste Description: 2-FURANCARBOXALDEHYDE (I) (OR) FURFURAL (I)

Waste Code: U140
Waste Description: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

Waste Code: U154
Waste Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Waste Code: U159
Waste Description: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Waste Code: U202
Waste Description: 1,2-BENZISOTHIAZOL-3(2H)-ONE, 1,1-DIOXIDE, & SALTS (OR) SACCHARIN, & SALTS

Waste Code: U203
Waste Description: 1,3-BENZODIOXOLE, 5-(2-PROPENYL)- (OR) SAFROLE

Waste Code: U220
Waste Description: BENZENE, METHYL- (OR) TOLUENE

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	PA BLDG CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	100 WILLIAMS ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10038
Owner/Operator Telephone:	212-344-0044
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	PA BLDG CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported

GIVAUDAN CORP C/O FRITZSCHE DIV (Continued) **1000458101**

Owner/Operator Address:	100 WILLIAMS ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10038
Owner/Operator Telephone:	212-344-0044
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	PA BLDG CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	100 WILLIAMS ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10038
Owner/Operator Telephone:	212-344-0044
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	PA BLDG CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	100 WILLIAMS ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10038
Owner/Operator Telephone:	212-344-0044
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19920713
Handler Name:	GIVAUDAN CORP C/O FRITZSCHE DIV
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name:	GIVAUDAN CORP C/O FRITZSCHE DIV
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

GIVAUDAN CORP C/O FRITZSCHE DIV (Continued) **1000458101**

Receive Date: 20070101
Handler Name: GIVAUDAN CORP C/O FRITZSCHE DIV
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19901226
Handler Name: GIVAUDAN CORP C/O FRITZSCHE DIV
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920228
Handler Name: GIVAUDAN CORP.
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 31193
NAICS Description: FLAVORING SYRUP AND CONCENTRATE MANUFACTURING

NAICS Code: 32511
NAICS Description: PETROCHEMICAL MANUFACTURING

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported

GIVAUDAN CORP C/O FRITZSCHE DIV (Continued) **1000458101**

Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported

GIVAUDAN CORP C/O FRITZSCHE DIV (Continued) **1000458101**

SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19960912
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2ME
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19960606
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2RDL
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

D55 **GEORGE UHE CO INC** **RCRA NonGen / NLR** **1000357187**
South **76 NINTH AVE** **NY MANIFEST** **NYD982797888**
< 1/8 **NEW YORK, NY 10011**
0.011 mi.
56 ft. **Site 8 of 9 in cluster D**

Relative: **Higher**

Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	GEORGE UHE CO INC	
Handler Address:		76 NINTH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYD982797888
Contact Name:		LARRY MASLOW
Contact Address:		NINTH AVE
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		212-929-0870
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported

GEORGE UHE CO INC (Continued) **1000357187**

EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	NINTH AVE
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	SYLVAN LAWRENCE INC
Owner Type:	Private
Operator Name:	SYLVAN LAWRENCE INC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported

GEORGE UHE CO INC (Continued) **1000357187**

Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D009
Waste Description:	MERCURY

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SYLVAN LAWRENCE INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	SYLVAN LAWRENCE INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	SYLVAN LAWRENCE INC
Legal Status:	Private

GEORGE UHE CO INC (Continued) **1000357187**

Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: GEORGE UHE CO INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: GEORGE UHE CO INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19891103
Handler Name: GEORGE UHE CO INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

GEORGE UHE CO INC (Continued) **1000357187**

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: GIVAUDAN CORPORATION
Address: 76 NINTH AVE
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYD986934305
Facility Status: Not reported
Location Address 1: 76 9TH AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986934305
Mailing Name: GIVAUDAN CORPORATION
Mailing Contact: TED HEIART
Mailing Address 1: 76 9TH AVENUE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10011
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2129294100

Name: GEORGE UHE COMPANY
Address: 76 NINTH AVE
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYD982797888
Facility Status: Not reported
Location Address 1: 76 NINTH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD982797888
Mailing Name: GEORGE UHE COMPANY
Mailing Contact: GEORGE UHE COMPANY
Mailing Address 1: 76 NINTH AVE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY

GEORGE UHE CO INC (Continued) **1000357187**

Mailing Zip: 10011
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2129290870

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

D56 **CON EDISON** **RCRA NonGen / NLR** **1014395676**
South **76 9TH AVE** **NJ MANIFEST** **NYP004171427**
< 1/8 **NEW YORK, NY 10014** **NY MANIFEST**
0.011 mi.
56 ft. **Site 9 of 9 in cluster D**

Relative: **Higher**
Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		76 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004171427
Contact Name:		DAVID DUKE
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		917-559-8971
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported

CON EDISON (Continued) **1014395676**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160727
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090609
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601

CON EDISON (Continued) **1014395676**

Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:
EPA Id: NYP004171427
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DAVID DUKE
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 003532082JJK
EPA ID: NYP004171427
Date Shipped: 06/09/2009
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 06/09/2009

CON EDISON (Continued) **1014395676**

Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/09/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	1500 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	76 9TH AVE
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004171427
Facility Status:	Not reported
Location Address 1:	76 9TH AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004171427
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK

CON EDISON (Continued) **1014395676**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/09/2009
Trans1 Recv Date:	06/09/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/09/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004171427
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003532082JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C57
WSW
< 1/8
0.011 mi.
57 ft.

LOT 14,TAXBLOCK 714
437 WEST 16 STREET
MANHATTAN, NY

Site 14 of 29 in cluster C

NY E DESIGNATION **S108076874**
N/A

Relative:
Lower

Actual:
12 ft.

E DESIGNATION:

Name:	LOT 14,TAXBLOCK 714
Address:	437 WEST 16 STREET
City,State,Zip:	MANHATTAN, NY
Tax Lot(s):	14
Tax Block:	714
Borough Code:	Not reported
E-No:	E-142
Effective Date:	6/23/2005
Satisfaction Date:	Not reported
Ceqr Number:	03DCP069M
Ulurp Number:	050161 ZRM
Zoning Map No:	8b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date:	Not reported

C58
WSW
< 1/8
0.011 mi.
57 ft.

CON EDISON
437 W 16TH ST
NEW YORK, NY 10011

Site 15 of 29 in cluster C

NJ MANIFEST **S120673159**
N/A

Relative:
Lower

Actual:
12 ft.

NJ MANIFEST:

EPA Id:	NYP004798542
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002614127GBF
EPA ID:	NYP004798542
Date Shipped:	6/24/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported

CON EDISON (Continued) **S120673159**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

C59 **CON EDISON** **NY MANIFEST** **S118257176**
WSW **437 W 16TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.011 mi.
57 ft. **Site 16 of 29 in cluster C**

Relative: NY MANIFEST:
Lower

Actual:
12 ft.

Name:	CON EDISON
Address:	437 W 16TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004798542
Facility Status:	Not reported
Location Address 1:	437 W 16TH ST
Code:	BP
Location Address 2:	SB 2783
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

CON EDISON (Continued) **S118257176**

NY MANIFEST:

EPAID:	NYP004798542
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/24/2015
Trans1 Recv Date:	06/24/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004798542
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002614127GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S118257176**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C60 **CON EDISON** **RCRA NonGen / NLR** **1019904485**
WSW **437 W 16TH ST** **FINDS** **NYP004798542**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.011 mi.
57 ft. **Site 17 of 29 in cluster C**

Relative: **Lower**
Actual: **12 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150624
Handler Name:	CON EDISON	
Handler Address:		437 W 16TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004798542
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---

CON EDISON (Continued) **1019904485**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150624
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150624
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified

CON EDISON (Continued) **1019904485**

State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069702771

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019904485
Registry ID:	110069702771
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069702771
Name:	CON EDISON
Address:	437 W 16TH ST
City,State,Zip:	NEW YORK, NY 10011

F61 **CON EDISON SERVICE BOX: 39803** **NJ MANIFEST** **S117985932**
SSE **96 9TH AVE N OF W 35TH ST FRONT** **N/A**
< 1/8 **NEW YORK, NY 10001**
0.012 mi.
62 ft. **Site 2 of 20 in cluster F**

Relative:
Higher

Actual:
16 ft.

NJ MANIFEST:

EPA Id:	NYP004264719
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JOSE MONTALVO

CON EDISON SERVICE BOX: 39803 (Continued) **S117985932**

Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010456183JJK
EPA ID:	NYP004264719
Date Shipped:	8/24/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	1,000.00 Pounds

F62 **CON EDISON SERVICE BOX: 39803** **RCRA NonGen / NLR** **1016143689**
SSE **96 9TH AVE N OF W 35TH ST FRONT OF** **NY MANIFEST** **NYP004264719**
< 1/8 **NEW YORK, NY 10001**
0.012 mi.
62 ft. **Site 3 of 20 in cluster F**

Relative: **Higher**
Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20170728
Handler Name:	CON EDISON SERVICE BOX:	39803
Handler Address:		96 9TH AVE N OF W 35TH ST FRONT OF
Handler City,State,Zip:		NEW YORK, NY 10001
EPA ID:		NYP004264719
Contact Name:		JOSE MONTALVO
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-427-1331
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 39803 (Continued) **1016143689**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170928
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20120824
Handler Name: CON EDISON SERVICE BOX:	39803
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20170728
Handler Name: CON EDISON SERVICE BOX:	39803
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 39803 (Continued) **1016143689**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 96 9TH AVE N OF W 35TH ST FRON
City,State,Zip: NEW YORK, NY 10001
Country: USA
EPA ID: NYP004264719
Facility Status: Not reported
Location Address 1: FO 96 9TH AVE NO W 35TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10001
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004264719
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 08/24/2012
Trans1 Recv Date: 08/24/2012
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/24/2012
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004264719

CON EDISON SERVICE BOX: 39803 (Continued) **1016143689**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010456183JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B63 **SPILL NUMBER 9912769** **NY Spills** **S104650275**
NNE **414 W 20TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.012 mi.
62 ft. **Site 14 of 33 in cluster B**

Relative: **Higher**

Actual: **14 ft.**

SPILLS:

Name:	SPILL NUMBER 9912769
Address:	414 W 20TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9912769 / 2003-07-29
Facility ID:	9912769
Facility Type:	ER
DER Facility ID:	73985
Site ID:	79724
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	2000-02-09
Investigator:	SMSANGES
Referred To:	Not reported

SPILL NUMBER 9912769 (Continued) **S104650275**

Reported to Dept:	2000-02-09
CID:	257
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-09
Spill Record Last Update:	2003-07-29
Spiller Name:	Not reported
Spiller Company:	VIJAX OIL CORP
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	ISOINO FERNANDEZ
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND "
Remarks:	"caller is the home owner and says last 4 times oil company has spilled product and today they spill alot and odor is giving hima a headack"

All Materials:

Site ID:	79724
Operable Unit ID:	1087298
Operable Unit:	01
Material ID:	294640
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B64 **SPILL NUMBER 0111849** **NY Spills** **S106001893**
NNE **414 WEST 20TH STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.012 mi.
62 ft. **Site 15 of 33 in cluster B**

Relative: **Higher**
Actual: **14 ft.**

SPILLS:

Name:	SPILL NUMBER 0111849
Address:	414 WEST 20TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0111849 / 2003-12-10
Facility ID:	0111849
Facility Type:	ER
DER Facility ID:	219180
Site ID:	269103
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101

SPILL NUMBER 0111849 (Continued) **S106001893**

Spill Date:	2002-03-15
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2002-03-15
CID:	266
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-03-15
Spill Record Last Update:	2003-12-10
Spiller Name:	Not reported
Spiller Company:	CHARLES O'NEAL
Spiller Address:	414 WEST 20TH STREET
Spiller Company:	001
Contact Name:	CHARLES O'NEAL
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 12/10/03 TJD No spill. No recent complaints. Spill administratively closed."
Remarks:	"CROSS REFERENCE 0111434. ONGOING PROBLEM. WHENEVER THE SPILLER RECEIVES A DELIVERY THERE'S A STRONG ODOR IN BOTH THE CALLER'S BUILDING (416 WEST 2OTH STREET) AND THE SPILLER'S BUILDING. THERE HAVE ALSO BEEN VISIBLE SPILLS ON THE GROUND IN THE PAST. IT IS UNKNOWN IF THERE IS A VISIBLE SPILL TODAY. CALLER NOTICED THE ODOR AND CALLED US BEFORE LOOKING ANY FURTHER. CALLER WOULD LIKE A CALL BACK FROM DEC."

All Materials:

Site ID:	269103
Operable Unit ID:	850652
Operable Unit:	01
Material ID:	525868
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B65 **414 W. 20TH ST** **NY Spills** **S106383153**
NNE **414 WEST 20TH ST** **N/A**
< 1/8 **NEW YORK, NY**
0.012 mi.
62 ft. **Site 16 of 33 in cluster B**

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name:	414 W. 20TH ST
Address:	414 WEST 20TH ST
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0313042 / 2004-02-27

414 W. 20TH ST (Continued) **S106383153**

Facility ID:	0313042
Facility Type:	ER
DER Facility ID:	202427
Site ID:	246511
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2004-02-26
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2004-02-26
CID:	444
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-02-26
Spill Record Last Update:	2007-04-26
Spiller Name:	MARIA MANDARINO
Spiller Company:	Not reported
Spiller Address:	414 WEST 20TH
Spiller Company:	001
Contact Name:	MR. WELLS
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND Payless Fuel subbed the delivery from Vijax Fuel. Customer(Mr. Wells 212-924-7087) called in a request for 300 gallons. At 281 gallons the vent line blew. Also the gauge on the top of the tank blew and sprayed oil in the basement. Vijax had a crew on site for several hours on 2/26. 2/27/2004 - Mr. Wells says the site is still a problem. Vijax has hired ABC Tank to come today to clean the site. ABC Tank 212-272-2800 2/27/2004 - Mr. Wells called back to say the cleanup was done. Closed"
Remarks:	"GAUGE WAS BROKEN ON TANK< HAS BEEN FIXED AND CLEANED UP: "

All Materials:

Site ID:	246511
Operable Unit ID:	880226
Operable Unit:	01
Material ID:	498211
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	3.00
Oxygenate:	Not reported

E66 **SPILL NUMBER 0111434** **NY Spills** **S106001557**
NNE **416 W. 20TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.012 mi.
63 ft. **Site 4 of 15 in cluster E**

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name:	SPILL NUMBER 0111434
Address:	416 W. 20TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0111434 / 2003-12-10
Facility ID:	0111434
Facility Type:	ER
DER Facility ID:	218754
Site ID:	268536
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	2002-03-04
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2002-03-04
CID:	322
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-03-04
Spill Record Last Update:	2003-12-10
Spiller Name:	FERNANDEZ
Spiller Company:	Not reported
Spiller Address:	414 W. 2OTH ST
Spiller Company:	001
Contact Name:	CHARLES ONEIL
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 12/10/03 TJD No spill. Oil company was servicing heating equipment. No further action required. Spill closed."
Remarks:	"CALLER STATES THAT THE NEIGHBORS ARE THE ONLY ONES THAT HAVE OIL HEAT - CALLER HAS A STRONG OIL ODOR IN HIS BASEMENT - THERE IS A OIL COMPANY REPAIR TRUCK PARKED NEXT DOOR AT THIS TIME - CALLER IS CONCERNED THERE IS A SPILL - TRUCK WAS FROM N.J."

All Materials:

Site ID:	268536
Operable Unit ID:	848478
Operable Unit:	01
Material ID:	525460
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

SPILL NUMBER 0111434 (Continued) **S106001557**

Oxygenate: Not reported

C67 **ACROSS FROM WEINBURG RES.** **NY Spills** **S105235716**
WSW **450 W 16TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.012 mi.
65 ft. **Site 18 of 29 in cluster C**

Relative: SPILLS:
Lower

Actual: Name: ACROSS FROM WEINBURG RES.
13 ft. Address: 450 W 16TH ST
City,State,Zip: MANHATTAN, NY
Spill Number/Closed Date: 0107670 / 2001-10-29
Facility ID: 0107670
Facility Type: ER
DER Facility ID: 263549
Site ID: 327409
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 3101
Spill Date: 2001-10-26
Investigator: MXTIPPLE
Referred To: Not reported
Reported to Dept: 2001-10-26
CID: 390
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Citizen
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-10-26
Spill Record Last Update: 2001-10-29
Spiller Name: Not reported
Spiller Company: UNK
Spiller Address: UNK
Spiller Company: 999
Contact Name: MR WEINBURG
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 10/29/2001 NO MR. WEINBURG AT THE ABOVE ADDRESS. SPILL IS NO LONGER THERE."
Remarks: "caller states the caller was a neighbor - across the st saw the spill"

All Materials:
Site ID: 327409
Operable Unit ID: 844893
Operable Unit: 01
Material ID: 528937
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum

ACROSS FROM WEINBURG RES. (Continued) **S105235716**

Quantity: 55.00
Units: G
Recovered: .00
Oxygenate: Not reported

E68 **438 WEST 19TH STREET** **NY UST** **U004198847**
NNW **438 WEST 19TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.013 mi.
68 ft. **Site 5 of 15 in cluster E**

Relative:
Lower

Actual:
13 ft.

UST:
Name: 438 WEST 19TH STREET
Address: 438 WEST 19TH STREET
City,State,Zip: NEW YORK, NY 10011
Id/Status: 2-605131 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 583962.08734
UTM Y: 4510959.40563
Site Type: Storage Terminal/Petroleum Distributor

Tank Info:

Tank Number: #1
Tank ID: 163017
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1500
Install Date: Not reported
Date Tank Closed: 12/30/2001
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: 21
Date Test: 01/09/2001
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Tank Number: #1-A
Tank ID: 163018
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 275
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported

438 WEST 19TH STREET (Continued) **U004198847**

Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Tank Number:	002
Tank ID:	67441
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Tank Number:	003
Tank ID:	67442
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

E69 **BETW. 9TH/10TH AVE.** **NY Spills** **S106127254**
NNW **438 WEST 19TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.013 mi.
68 ft. **Site 6 of 15 in cluster E**

Relative: SPILLS:
Lower

Name:	BETW. 9TH/10TH AVE.
Address:	438 WEST 19TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0313332 / 2004-03-10
Facility ID:	0313332
Facility Type:	ER
DER Facility ID:	308319
Site ID:	189354
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	D4

Actual:
13 ft.

BETW. 9TH/10TH AVE. (Continued) **S106127254**

SWIS:	3101
Spill Date:	2004-03-04
Investigator:	CESAWYER
Referred To:	Not reported
Reported to Dept:	2004-03-04
CID:	406
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-04
Spill Record Last Update:	2006-01-19
Spiller Name:	Not reported
Spiller Company:	CHELSEA CLUB
Spiller Address:	438 WEST 19TH STREET
Spiller Company:	001
Contact Name:	WILLIAMSON
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER Sangesland spoke to Mr. Williamson. Appears to be a neighborhood fight. Next door is a construction site and Mr. Williamson's building has been hit by construction equipment from next door. Fire Dept was called to the site. Mr. Williamson says the problem site address is probably 438 West 19th St (anything below 446 west 19th). He says the site is going to be a new highrise apartment building. Site is already dug 30 ft down with a basement/sub-basement level. Sidewalls have been poured and the foundation walls now rise to street level. Strong smell of diesel at the site. spill closed Ref to #0311002"
Remarks:	"Smell of diesel fuel possible spill. The resource is in the air right now unsure if there is actually a spill. All other info is unknown."

All Materials:

Site ID:	189354
Operable Unit ID:	878575
Operable Unit:	01
Material ID:	555244
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	CONSTRUCTION SITE
Address:	438 WEST 19TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0311002 / 2006-04-19
Facility ID:	0311002
Facility Type:	ER

BETW. 9TH/10TH AVE. (Continued) **S106127254**

DER Facility ID:	308319
Site ID:	236116
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	3101
Spill Date:	2003-12-24
Investigator:	KMFOLEY
Referred To:	NFA, 4/19/06
Reported to Dept:	2003-12-26
CID:	402
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-26
Spill Record Last Update:	2006-04-19
Spiller Name:	LABIB NADER
Spiller Company:	FUTURE CONDOMINIUM
Spiller Address:	438 WEST 19TH STREET
Spiller Company:	001
Contact Name:	LABIB NADER
DEC Memo:	"12/26/03 11:30 Hrs - Sawyer - Responded to the site to check a minor spill of 35 gallon tank and a larger spill from the removal of the 1500 gallon tank. The project manager who I had spoken to on the phone before I left was not at the site when I arrived. His name is Labib Nader,the superintendent (cell) 201-532-9302 and he would arrive later on after lunch. When he arrived I notified him that the excavator had uncovered two more tanks and they should also be registered before removal. From the latest PBS registration, the two 550 gallon tanks are registered and classified as removed per 1/20/04. 01/26/04 0929 Hrs - Sawyer - Received a call from Richard Parrish of Impact Environmental (631)269-8800, (516)805-8900 who has been retained by the contractor, Breeze International. He was giving the background to a spill reported this morning from the same site. He explained that when the two 550 gallon tanks were removed major petroleum contamination was found. They will remove as much of the contaminated soil as they can and get ground water samples to see the extent of its pollution. 2/17/04 Investigation Plan received. 2/26/04 Investigation report prepared by Impact Env. Gasoline release from the two 550gal USTs has impacted soil and groundwater. 4/19/04 RAP dated 4/7/04 received. 06/24/04 Transferred from Sawyer to Foley. Reference spills #0311976, 0313332. 6/30/04 Rich Parrish hand-delivered RAP dated 4/15/04. Explained that construction has already begun for the Chelsea Club. Vapor barrier, resistant to petroleum, will be installed. Proposing an SVE/AS system which will be horizontal on the west side of building with two vertical points on north side. They were planning on horizontal piping on north side but changed due to a change in construction details. 7/6/04 Reviewed and conditionally approved RAP. Faxed to R. Parrish. 5/6/05 Update from Hal Benjamin, Impact. Wells installed early in the project were destroyed during construction activities, so the following wells are

BETW. 9TH/10TH AVE. (Continued) **S106127254**

in place at this time: Horizontal SVE-1, MW-1, and AS-1. Hit refusal on several tries at the location of MW-2. Location is now inside a parking garage with a seven foot ceiling.(requested that we skip this install) Scheduled to drill MW/SVE-2, AS-2, MW/SVE-3, and AS-3 next week(5/9/05). Pilot testing has been completed & equipment has been installed. Piping is in place except to MW/SVE-3, AS-3. Those lines will be connected during drilling event. Looking to start up the system within a month. 5/19/05 Update from H. Benjamin, Impact. MW-1, SVE/MW-2, SVE/MW-3 installed. Gave approval to not install MW-4. Horizontal SVE also already in. Electric to be installed followed by startup. Will notify of startup and send in the data with first report. 5/24/05 System start-up. 9/9/05 Update from H. Benjamin. They started the system at the end of May and just performed the first quarterly sampling. Will send a startup/quarterly report when the lab data comes back. 10/31/05 Start-up procedures and 1Q05 report received.Effluent concentrations were monitored to verify compliance with discharge limits. Once SVE effluent stabilized, sparge was started. Effluent was measured weekly for first five weeks and at least monthly thereafter. Estimated 96lbs of total hydrocarbons removed from 5/24-10/17/05. Groundwater concentrations decreased from 5/19 to 10/6. 1/18/06 Quarterly dated 1/11/06 received. GW concentrations have decreased. Sampling from 12/7/05 showed no VOCs detected in MW-2. Two VOCs were detected in MW-1 but below GWQS. Two VOCs were detected in MW-3 marginally exceeding GWQS. SVE effluent is approaching asymptotic. 4/3/06 3Q06- MW-1 and MW-2/SVE-2 are ND for BTEX and MTBE. MW-3/SVE-3 shows exceedances for xylenes, ethylbenzene, napthalene and 1,2,4-trimethylbenzene with total BTEX at 330ppb. 4/19/06 NFA issued. "

Remarks: "CALLER FOUND TwO TANKS IN GROUND ONE THEY RUPTURED WITH MACHINE. UKNOWN MATERIAL SEEPKING OUT."

All Materials:

Site ID:	236116
Operable Unit ID:	876247
Operable Unit:	01
Material ID:	2106574
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	True

Site ID:	236116
Operable Unit ID:	876247
Operable Unit:	01
Material ID:	499835
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	True

BETW. 9TH/10TH AVE. (Continued) **S106127254**

Name:	CONSTRUCTION SITE
Address:	438 WEST 19TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0311976 / 2004-01-26
Facility ID:	0311976
Facility Type:	ER
DER Facility ID:	308319
Site ID:	236117
DEC Region:	2
Spill Cause:	Other
Spill Class:	C3
SWIS:	3101
Spill Date:	2004-01-26
Investigator:	CESAWYER
Referred To:	Not reported
Reported to Dept:	2004-01-26
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-01-26
Spill Record Last Update:	2006-01-19
Spiller Name:	RICHARD PARRISH
Spiller Company:	CONSTRUCTION SITE
Spiller Address:	438 WEST 19TH STREET
Spiller Company:	999
Contact Name:	RICHARD BREEZE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 01/26/04 See spill number 0311002. Closed."
Remarks:	"FOUND TWO OLD GAS TANKS UNDERGROUND LEAKING, REMOVE SOIL AND TANKS: IT IS LOCATED IN THE CENTRAL NORTHERN PART OF PROPERTY;"

All Materials:

Site ID:	236117
Operable Unit ID:	877206
Operable Unit:	01
Material ID:	497213
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

E70 **CON EDISON** **NY MANIFEST** **S117739869**
North **428 W 20TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.013 mi.
69 ft. **Site 7 of 15 in cluster E**

Relative:
Higher

Actual:
14 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	428 W 20TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004730107
Facility Status:	Not reported
Location Address 1:	F/O 428 W 20 ST
Code:	BP
Location Address 2:	SB3610
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004730107
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	02/10/2015
Trans1 Recv Date:	02/10/2015
Trans2 Recv Date:	02/13/2015
TSD Site Recv Date:	02/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004730107
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610598GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117739869**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

E71 **CON EDISON** **NJ MANIFEST** **S120667136**
North **428 W 20TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.013 mi.
69 ft. **Site 8 of 15 in cluster E**

Relative: **Higher**
Actual: **14 ft.**

NJ MANIFEST:

EPA Id:	NYP004730107
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610598GBF
EPA ID:	NYP004730107
Date Shipped:	2/10/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **S120667136**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

E72 **CON EDISON** **RCRA NonGen / NLR** **1018278250**
North **428 W 20TH ST** **FINDS** **NYP004730107**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.013 mi.
69 ft. **Site 9 of 15 in cluster E**

Relative: **Higher**

Actual: **14 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150210
Handler Name:	CON EDISON	
Handler Address:		428 W 20TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004730107
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified

CON EDISON (Continued) **1018278250**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No

CON EDISON (Continued) **1018278250**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150210
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150210
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067702301

Click Here:

Environmental Interest/Information System:

CON EDISON (Continued) **1018278250**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018278250
Registry ID:	110067702301
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067702301
Name:	CON EDISON
Address:	428 W 20TH ST
City,State,Zip:	NEW YORK, NY 10011

C73 **MENDON LEASING CORP** **NY UST** **1000871565**
WNW **440 W 18TH ST** **RCRA NonGen / NLR** **NY0000071357**
< 1/8 **NEW YORK, NY 10011** **FINDS**
0.013 mi. **ECHO**
70 ft. **Site 19 of 29 in cluster C** **NY MANIFEST**

Relative:
Lower

Actual:
13 ft.

UST:

Name:	MENDON LEASING CORP
Address:	440 WEST 18TH ST
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-032298 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583984.85633
UTM Y:	4510826.31217
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	203
Affiliation Type:	Facility Operator
Company Name:	MENDON LEASING CORP
Contact Type:	Not reported
Contact Name:	MENDON LEASING CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 255-0900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-07-21

Site Id:	203
Affiliation Type:	Facility Owner
Company Name:	RETACO HOLDING CORP
Contact Type:	Not reported

MENDON LEASING CORP (Continued) **1000871565**

Contact Name:	Not reported
Address1:	362 KINGSLAND AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 389-2100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	203
Affiliation Type:	Mail Contact
Company Name:	RETACO HOLDING CORP
Contact Type:	Not reported
Contact Name:	JIM MCELHINNEY
Address1:	362 KINGSLAND AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 389-2100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	203
Affiliation Type:	Emergency Contact
Company Name:	RETACO HOLDING CORP
Contact Type:	Not reported
Contact Name:	JIM MCELHINNEY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 437-5305
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	884
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	12/01/1993
Registered:	True

MENDON LEASING CORP (Continued) **1000871565**

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

Tank Number: 002
Tank ID: 47362
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 003
Tank ID: 47363

MENDON LEASING CORP (Continued) **1000871565**

Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 004
Tank ID: 47364
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

MENDON LEASING CORP (Continued) **1000871565**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	005
Tank ID:	47365
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	12/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	006
Tank ID:	885
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	12/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground

MENDON LEASING CORP (Continued) **1000871565**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	MENDON LEASING CORP	
Handler Address:		440 W 18TH ST
Handler City,State,Zip:		NEW YORK, NY 10011-3801
EPA ID:		NY0000071357
Contact Name:		Not reported
Contact Address:		KINGSLAND AVE
Contact City,State,Zip:		BROOKLYN, NY 11222
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		KINGSLAND AVE
Mailing City,State,Zip:		BROOKLYN, NY 11222
Owner Name:		RETACO HOLDING CORP
Owner Type:		Private
Operator Name:		RETACO HOLDING CORP
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported

MENDON LEASING CORP (Continued) **1000871565**

Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	RETACO HOLDING CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	362 KINGSLAND AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11222
Owner/Operator Telephone:	718-389-2100
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	RETACO HOLDING CORP

MENDON LEASING CORP (Continued) **1000871565**

Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	362 KINGSLAND AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11222
Owner/Operator Telephone:	718-389-2100
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	RETACO HOLDING CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	362 KINGSLAND AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11222
Owner/Operator Telephone:	718-389-2100
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: MENDON LEASING CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20060101
Handler Name: MENDON LEASING CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: MENDON LEASING CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

MENDON LEASING CORP (Continued) **1000871565**

Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19931207
Handler Name: MENDON LEASING CORP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004309944

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000871565
Registry ID: 110004309944
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004309944
Name: MENDON LEASING CORP
Address: 440 W 18TH ST
City,State,Zip: NEW YORK, NY 10011

NY MANIFEST:
Name: RETACO HOLDEN CORP MENDON
Address: 440 W 18TH ST
City,State,Zip: NEW YORK, NY 10011-3801

MENDON LEASING CORP (Continued) **1000871565**

Country:	USA
EPA ID:	NY0000071357
Facility Status:	Not reported
Location Address 1:	440 W 18TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NY0000071357
Mailing Name:	RETACO HOLDEN CORP MENDON
Mailing Contact:	PAUL KIRRONE
Mailing Address 1:	362 KINGSLAND AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11222
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183982100

C74 **CON EDISON SERVICE BOX: 2783** **RCRA NonGen / NLR** **1016449949**
WSW **439 W 16TH ST** **NY MANIFEST** **NYP004256533**
< 1/8 **NEW YORK, NY 10011**
0.014 mi.
73 ft. **Site 20 of 29 in cluster C**

Relative: **Lower**

Actual: **12 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130319
Handler Name:	CON EDISON SERVICE BOX:	2783
Handler Address:		439 W 16TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004256533
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported

CON EDISON SERVICE BOX: 2783 (Continued) **1016449949**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON SERVICE BOX: 2783 (Continued) **1016449949**

Historic Generators:
Receive Date: 20130219
Handler Name: CON EDISON SERVICE BOX: 2783
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130319
Handler Name: CON EDISON SERVICE BOX: 2783
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 439 W 16TH ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004256533
Facility Status: Not reported
Location Address 1: 439 W 16TH ST
Code: BP
Location Address 2: SERV BOX 2783
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004256533

CON EDISON SERVICE BOX: 2783 (Continued) **1016449949**

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/19/2013
Trans1 Recv Date:	02/19/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/19/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004256533
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840421JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON SERVICE BOX: 2783 (Continued) **1016449949**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

C75 **445-459 W. 16TH ST** **NY Spills** **S106468692**
WSW **445-459 WEST 16TH STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.014 mi.
75 ft. **Site 21 of 29 in cluster C**

Relative: SPILLS:
Lower
Actual: Name: 445-459 W. 16TH ST
12 ft. Address: 445-459 WEST 16TH STREET
City,State,Zip: MANHATTAN, NY
Spill Number/Closed Date: 0401167 / 2008-10-06
Facility ID: 0401167
Facility Type: ER
DER Facility ID: 76387
Site ID: 82933
DEC Region: 2
Spill Cause: Other
Spill Class: C4
SWIS: 3101
Spill Date: 2004-05-04
Investigator: snboller
Referred To: Not reported
Reported to Dept: 2004-05-04
CID: 444
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-05-04
Spill Record Last Update: 2012-12-20
Spiller Name: ROSALIE FRIEDMAN
Spiller Company: Not reported
Spiller Address: 445-459 WEST 16TH STREET
Spiller Company: 001
Contact Name: ROSALIE FRIEDMAN
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 6/8/2004 Sangesland spoke with Johnathan Hacker. He said the property was sold and the new owner is: 17th & 10th Associates LLC c/o Taconic Investment Properties 111 Eighth Ave - 15th Flr New York, NY 10011 Attn: Charles Bendit 212-220-9945 A new contaminated soil letter was sent out 6/8/2004 6/24/2004 Sangesland spoke with Mr. Bendit asking for an update on the cleanup of the site. He said he has a meeting scheduled with Dan Walsh and Vadim Brevdo of DEC Brownfields on July 21st. At that time the owners will probably bring the property into the Brownfields program for a redevelopment/cleanup. 12/12/05- DEC Piper determined that this site has entered into the BCP. Re-Assigned to Joe O'Connell. 1/27/2005 - BCA fully executed 10/6/2008 - COC issued END. "
Remarks: "SOIL IMPACTED WITH PETROLEUM: THERE WAS ALSO A PREVIOUSE SPILL

445-459 W. 16TH ST (Continued) **S106468692**

ABOUIT 10-15 YEARS AGO:"

All Materials:

Site ID:	82933
Operable Unit ID:	885279
Operable Unit:	01
Material ID:	492392
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

E76 **ALJOBET AUTOMATIC TRANSM*** **EDR Hist Auto** **1020515477**
NW **435 WEST 18TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.016 mi.
83 ft. **Site 10 of 15 in cluster E**

Relative: EDR Hist Auto
Lower

Actual:
13 ft.

Year:	Name:	Type:
1976	ALJOBET AUTOMATIC TRANSM*	Automotive Repair Shops, NEC
1977	ALJOBET AUTOMATIC TRANSM*	Automotive Repair Shops, NEC
1978	ALJOBET AUTOMATIC TRANSM*	Automotive Repair Shops, NEC
1979	ALJOBET AUTOMATIC TRANSM*	Automotive Repair Shops, NEC
1980	ALJOBET AUTOMATIC TRANSM*	Automotive Repair Shops, NEC
1982	ALJOBET AUTOMATIC TRANSM*	Automotive Repair Shops, NEC
1983	ALJOBET AUTOMATIC TRANSM*	Automotive Repair Shops, NEC
1986	JARICK AUTOMATIC TRANSMISSION*	Automotive Repair Shops, NEC
1988	FIVE BOROS TRANSMISSION INC	Automotive Repair Shops, NEC
1989	FIVE BOROS TRANSMISSION INC	Automotive Transmission Repair Shops
1990	FIVE BOROS TRANSMISSION INC	Automotive Transmission Repair Shops
1991	FIVE BOROS TRANSMISSION INC	Automotive Transmission Repair Shops
1992	FIVE BOROS TRANSMISSION INC	Automotive Transmission Repair Shops
1993	FIVE BOROS TRANSMISSION INC	Automotive Transmission Repair Shops
1994	FIVE BOROS TRANSMISSION INC	Automotive Transmission Repair Shops
1995	PETER DOUGLAS QUALITY ASSOC	Automotive Transmission Repair Shops
1996	PETER DOUGLAS QUALITY ASSOC	Automotive Transmission Repair Shops
1997	PETER DOUGLAS QUALITY ASSOC	Automotive Transmission Repair Shops
2001	MARTYS 18TH STREET REPAIR INC	General Automotive Repair Shops
2002	MARTYS 18TH STREET REPAIR INC	General Automotive Repair Shops
2003	MARTYS 18TH STREET REPAIR INC	General Automotive Repair Shops
2004	MARTYS 18TH STREET REPAIR INC	General Automotive Repair Shops
2005	MARTYS 18TH STREET REPAIR INC	General Automotive Repair Shops
2006	MARTYS 18TH STREET REPAIR INC	General Automotive Repair Shops
2007	MARTYS 18TH STREET REPAIR INC	General Automotive Repair Shops

E77 **ALCAM PROPERTY MANAGEMENT, LLC** **NY UST** **U003790887**
NW **435 WEST 18TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.016 mi.
83 ft. **Site 11 of 15 in cluster E**

Relative:
Lower

Actual:
13 ft.

UST:

Name:	ALCAM PROPERTY MANAGEMENT, LLC
Address:	435 WEST 18TH STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-606190 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	07/05/2026
UTM X:	583997.72358
UTM Y:	4510838.85252
Site Type:	Other

Affiliation Records:

Site Id:	28054
Affiliation Type:	Mail Contact
Company Name:	ALCAM PROPERTY MANAGEMENT, LLC
Contact Type:	MANAGING MEMBER
Contact Name:	MICHAEL SAVINO
Address1:	435 W. 18TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(917) 940-2568
EMail:	MICHAELSAVINO@GMAIL.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-12-03

Site Id:	28054
Affiliation Type:	Facility Operator
Company Name:	ALCAM PROPERTY MANAGEMENT, LLC
Contact Type:	Not reported
Contact Name:	MICHAEL SAVINO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 940-2568
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-12-03

Site Id:	28054
Affiliation Type:	Emergency Contact
Company Name:	ALCAM PROPERTY MANAGEMENT, LLC
Contact Type:	Not reported
Contact Name:	MICHAEL SAVINO
Address1:	Not reported

ALCAM PROPERTY MANAGEMENT, LLC (Continued) **U003790887**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 940-2568
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-12-03

Site Id:	28054
Affiliation Type:	Facility Owner
Company Name:	ALCAM PROPERTY MANAGEMENT, LLC
Contact Type:	MANAGING MEMBER
Contact Name:	MICHAEL SAVINO
Address1:	525 CLINTON STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11231
Country Code:	001
Phone:	(917) 940-2568
EMail:	MICHAELSAVINO@GMAIL.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-12-03

Tank Info:

Tank Number:	001
Tank ID:	61085
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	2000
Install Date:	09/24/1979
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	21
Date Test:	01/23/2018
Next Test Date:	01/23/2019
Pipe Model:	Not reported
Modified By:	ACDANIEL
Last Modified:	12/03/2021

Equipment Records:

I05 - Overfill - Vent Whistle
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

ALCAM PROPERTY MANAGEMENT, LLC (Continued) **U003790887**

C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

E78 **THE GENERAL THEOLOGICAL SEMINARY** **NY AST** **A100296313**
North **422 WEST 20TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.016 mi.
84 ft. **Site 12 of 15 in cluster E**

Relative:
Higher

Actual:
14 ft.

AST:

Name:	THE GENERAL THEOLOGICAL SEMINARY
Address:	422 WEST 20TH STREET
City,State,Zip:	NEW YORK, NY 10011-2902
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-608842
Program Type:	PBS
UTM X:	584138.52263
UTM Y:	4510911.14225
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30691
Affiliation Type:	Mail Contact
Company Name:	URBAN ASSOCIATES, LLC
Contact Type:	Not reported
Contact Name:	RICHARD MASON
Address1:	400 WEST 59TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10019
Country Code:	001
Phone:	(212) 315-5555
EMail:	RMASON@BRODSKYORG.COM
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-04-25

Site Id:	30691
Affiliation Type:	Facility Operator
Company Name:	THE GENERAL THEOLOGICAL SEMINARY
Contact Type:	Not reported
Contact Name:	PETER HOFF
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 243-5150
EMail:	Not reported

THE GENERAL THEOLOGICAL SEMINARY (Continued) **A100296313**

Fax Number: Not reported
Modified By: msbaptis
Date Last Modified: 2008-04-04

Site Id: 30691
Affiliation Type: Emergency Contact
Company Name: THE GENERAL THEOLOGICAL SEMINARY
Contact Type: Not reported
Contact Name: PETER HOFF
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 243-5150
EMail: Not reported
Fax Number: Not reported
Modified By: msbaptis
Date Last Modified: 2008-04-04

Site Id: 30691
Affiliation Type: Facility Owner
Company Name: 420 WEST 20TH STREET, LLC C/O URBAN ASSOCIATES
Contact Type: EXEC. DIR. OF MANAGEMENT
Contact Name: RICHARD MASON
Address1: 400 WEST 59TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 315-5555
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2014-04-25

Tank Info:

Tank Number: 001
Tank Id: 65864
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
I01 - Overfill - Float Vent Valve
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser

THE GENERAL THEOLOGICAL SEMINARY (Continued) **A100296313**

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1969
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/03/2012
Register:	True
Modified By:	CGFREEDM
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

C79 **CON EDISON SERVICE BOX: 2781** **RCRA NonGen / NLR** **1016150277**
WSW **455 W 16TH ST FRONT OF** **NY MANIFEST** **NYP004289492**
< 1/8 **NEW YORK, NY 10011**
0.017 mi.
90 ft. **Site 22 of 29 in cluster C**

Relative: RCRA NonGen / NLR:
Lower

Actual: Date Form Received by Agency:		20130315
12 ft. Handler Name:	CON EDISON SERVICE BOX:	2781
Handler Address:		455 W 16TH ST FRONT OF
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004289492
Contact Name:		RICARDO CARTY
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		646-772-3407
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No

CON EDISON SERVICE BOX: 2781 (Continued) **1016150277**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130215
Handler Name:	CON EDISON SERVICE BOX: 2781
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON SERVICE BOX: 2781 (Continued) **1016150277**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130315
Handler Name: CON EDISON SERVICE BOX: 2781
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 455 W 16TH ST FRONT OF
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004289492
Facility Status: Not reported
Location Address 1: F/O 455 W 16 ST
Code: BP
Location Address 2: SERVICE BOX # 2781
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004289492
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA

CON EDISON SERVICE BOX: 2781 (Continued) **1016150277**

Mailing Phone: 2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/15/2013
Trans1 Recv Date:	02/15/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/16/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004289492
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010841359JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C80 **FREEDMAN CUT-OUTS** **RCRA NonGen / NLR** **1000693642**
WSW **455 W 16TH ST** **FINDS** **NYD986997070**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.017 mi. **NY MANIFEST**
90 ft. **Site 23 of 29 in cluster C**

Relative: **Lower**
Actual: **12 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	FREEDMAN CUT-OUTS	
Handler Address:		455 W 16TH ST
Handler City,State,Zip:		NEW YORK, NY 10011-5892
EPA ID:		NYD986997070
Contact Name:		Not reported
Contact Address:		W 17TH ST
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		W 17TH ST
Mailing City,State,Zip:		NEW YORK, NY 10011
Owner Name:		FREEDMAN REALTY
Owner Type:		Private
Operator Name:		FREEDMAN REALTY
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

FREEDMAN CUT-OUTS (Continued) **1000693642**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	FREEDMAN REALTY
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	FREEDMAN REALTY
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999

FREEDMAN CUT-OUTS (Continued) **1000693642**

Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	FREEDMAN REALTY
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: FREEDMAN CUT-OUTS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20060101
Handler Name: FREEDMAN CUT-OUTS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: FREEDMAN CUT-OUTS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

FREEDMAN CUT-OUTS (Continued) **1000693642**

Receive Date:	19920330
Handler Name: FREEDMAN CUT-OUTS	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004487957

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000693642
Registry ID:	110004487957
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004487957
Name:	FREEDMAN CUT-OUTS
Address:	455 W 16TH ST
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	FREEDMAN CUT OUT
Address:	455 W 16TH ST
City,State,Zip:	NEW YORK, NY 10011-5892
Country:	USA
EPA ID:	NYD986997070
Facility Status:	Not reported
Location Address 1:	455 WEST 16TH STREET
Code:	BP

FREEDMAN CUT-OUTS (Continued) **1000693642**

Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986997070
Mailing Name: FREEDMAN CUT OUT
Mailing Contact: FREEDMAN CUT OUT
Mailing Address 1: 444 WEST 17TH STREET
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10011
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2122434700

C81 **455 WEST 16TH STREET** **NY UST** **U001841438**
WSW **455 WEST 16TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.017 mi.
90 ft. **Site 24 of 29 in cluster C**

Relative:
Lower

Actual:
12 ft.

UST:
Name: 455 WEST 16TH STREET
Address: 455 WEST 16TH STREET
City,State,Zip: NEW YORK, NY 10011
Id/Status: 2-600410 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 583927.71757
UTM Y: 4510703.10398
Site Type: Manufacturing (Other than Chemical)/Processing

Affiliation Records:
Site Id: 22393
Affiliation Type: Facility Owner
Company Name: FREEDMAN REALTY
Contact Type: Not reported
Contact Name: Not reported
Address1: 455 WEST 16TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10011
Country Code: 001
Phone: (212) 243-4700
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 22393

455 WEST 16TH STREET (Continued) **U001841438**

Affiliation Type:	Mail Contact
Company Name:	FREEDMAN REALTY
Contact Type:	Not reported
Contact Name:	MR. PHILIP FRIEDMAN
Address1:	444 WEST 17TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 243-4700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	22393
Affiliation Type:	Facility Operator
Company Name:	455 WEST 16TH STREET
Contact Type:	Not reported
Contact Name:	PHILIP FRIEDMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 243-4700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	22393
Affiliation Type:	Emergency Contact
Company Name:	FREEDMAN REALTY
Contact Type:	Not reported
Contact Name:	PHILIP FRIEDMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 243-4700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	42545
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550

455 WEST 16TH STREET (Continued) **U001841438**

Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B99 - Tank External Protection - Other
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number: 002
Tank ID: 42546
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B99 - Tank External Protection - Other
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

455 WEST 16TH STREET (Continued) **U001841438**

Tank Number: 003
Tank ID: 42547
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B99 - Tank External Protection - Other
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number: 004
Tank ID: 42548
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B99 - Tank External Protection - Other
D02 - Pipe Type - Galvanized Steel

455 WEST 16TH STREET (Continued) **U001841438**

F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 005
Tank ID: 42549
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I00 - Overfill - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B99 - Tank External Protection - Other
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 006
Tank ID: 42550
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

455 WEST 16TH STREET (Continued) **U001841438**

Equipment Records:

I00 - Overfill - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B99 - Tank External Protection - Other
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

C82 **LOT 5,TAXBLOCK 715** **NY E DESIGNATION** **S108076962**
WNW **453 WEST 17 STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.018 mi.
96 ft. **Site 25 of 29 in cluster C**

Relative:
Lower

Actual:
12 ft.

E DESIGNATION:

Name:	LOT 5,TAXBLOCK 715
Address:	453 WEST 17 STREET
City,State,Zip:	MANHATTAN, NY
Tax Lot(s):	5
Tax Block:	715
Borough Code:	Not reported
E-No:	E-142
Effective Date:	6/23/2005
Satisfaction Date:	Not reported
Ceqr Number:	03DCP069M
Ulurp Number:	050161 ZRM
Zoning Map No:	8b
Description:	Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date:	Not reported
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

A83 **VELAZQUEZ 9TH AVENUE DRY CLEANERS** **RCRA-SQG** **1000790246**
ESE **126 9TH AVE** **ICIS** **NYD987017241**
< 1/8 **NEW YORK, NY 10011** **FINDS**
0.018 mi. **ECHO**
97 ft. **Site 18 of 19 in cluster A** **NY DRYCLEANERS**
NY MANIFEST

Relative:
Higher

Actual:
16 ft.

RCRA-SQG:

Date Form Received by Agency:		20070101
Handler Name:	TAMARA DRY CLEANERS	
Handler Address:		126 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011-4902
EPA ID:		NYD987017241
Contact Name:		Not reported
Contact Address:		9TH AVE
Contact City,State,Zip:		NEW YORK, NY 10011

VELAZQUEZ 9TH AVENUE DRY CLEANERS (Continued) **1000790246**

Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	9TH AVE
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	GEORGE ORELLANA
Owner Type:	Private
Operator Name:	GEORGE ORELLANA
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

VELAZQUEZ 9TH AVENUE DRY CLEANERS (Continued) **1000790246**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GEORGE ORELLANA
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	GEORGE ORELLANA
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

VELAZQUEZ 9TH AVENUE DRY CLEANERS (Continued) **1000790246**

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GEORGE ORELLANA
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: TAMARA DRY CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: TAMARA DRY CLEANERS	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: TAMARA DRY CLEANERS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19921007
Handler Name: TAMARA DRY CLEANERS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

VELAZQUEZ 9TH AVENUE DRY CLEANERS (Continued) **1000790246**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

ICIS:

Enforcement Action ID:	NY000A0000262050153400313
FRS ID:	110002367652
Action Name:	VELAZQUEZ 9TH AVENUE DRY CLEANERS 36061R078000313
Facility Name:	VELAZQUEZ 9TH AVENUE DRY CLEANERS
Facility Address:	126 9TH AVE NEW YORK, NY 100114902
Enforcement Action Type:	Notice of Violation
Facility County:	BRONX
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.743418
Longitude in Decimal Degrees:	-74.003544
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002620501534
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000262050153400306
FRS ID:	110002367652
Action Name:	VELAZQUEZ 9TH AVENUE DRY CLEANERS 36061R078000306
Facility Name:	VELAZQUEZ 9TH AVENUE DRY CLEANERS
Facility Address:	126 9TH AVE NEW YORK, NY 100114902
Enforcement Action Type:	Administrative Order
Facility County:	BRONX
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	SCAAAO
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.743418
Longitude in Decimal Degrees:	-74.003544
Permit Type Desc:	Not reported

VELAZQUEZ 9TH AVENUE DRY CLEANERS (Continued) **1000790246**

Program System Acronym: NY0000002620501534
Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000262050153400302
FRS ID: 110002367652
Action Name: VELAZQUEZ 9TH AVENUE DRY CLEANERS 36061R078000302
Facility Name: VELAZQUEZ 9TH AVENUE DRY CLEANERS
Facility Address: 126 9TH AVE
NEW YORK, NY 100114902
Enforcement Action Type: Notice of Violation
Facility County: BRONX
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.743418
Longitude in Decimal Degrees: -74.003544
Permit Type Desc: Not reported
Program System Acronym: NY0000002620501534
Facility NAICS Code: 812320
Tribal Land Code: Not reported

FINDS:
Registry ID: 110002367652

Click Here:

Environmental Interest/Information System:
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000790246

VELAZQUEZ 9TH AVENUE DRY CLEANERS (Continued) **1000790246**

Registry ID:	110002367652
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110002367652
Name:	VELAZQUEZ 9TH AVENUE DRY CLEANERS
Address:	126 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10011

DRYCLEANERS:

Name:	VELAZQUEZ/TAMARA DRY CLEANERS
Address:	126 9TH AVE.
City,State,Zip:	NEW YORK, NY 10011
Facility ID:	2-6205-01534
Phone Number:	212-989-5470
Region:	Not reported
Registration Effective Date:	5/30/2000 12:50:52:263
Inspection Date:	2012-03-13 00:00:00
Install Date:	98/12
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

NY MANIFEST:

Name:	TAMARA CLEANER
Address:	126 9TH AVE
City,State,Zip:	NEW YORK, NY 10011-4902
Country:	USA
EPA ID:	NYD987017241
Facility Status:	Not reported
Location Address 1:	126 9TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987017241
Mailing Name:	TAMARA CLEANER
Mailing Contact:	JORGE ORELLANA
Mailing Address 1:	126 9TH AVE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2129895470

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported

VELAZQUEZ 9TH AVENUE DRY CLEANERS (Continued) **1000790246**

Year:	2018
Trans1 State ID:	TXR000081205
Trans2 State ID:	NJD071629976
Generator Ship Date:	12/03/2012
Trans1 Recv Date:	12/03/2012
Trans2 Recv Date:	12/11/2012
TSD Site Recv Date:	12/12/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987017241
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID084802842
TSDF ID 2:	Not reported
Manifest Tracking Number:	003521395SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	5
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	D007
Waste Code 1_3:	D029
Waste Code 1_4:	D039
Waste Code 1_5:	D040
Waste Code 1_6:	Not reported

A84 **BARBARA DRY CLEANERS** **EDR Hist Cleaner** **1018553085**
ESE **126 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.018 mi.
97 ft. **Site 19 of 19 in cluster A**

Relative: EDR Hist Cleaner
Higher

Actual:
16 ft.

Year:	Name:	Type:
1970	ADMIRATION CLEANERS INC	Drycleaning Plants, Except Rugs
1971	ADMIRATION CLEANERS INC	Drycleaning Plants, Except Rugs
1972	ADMIRATION CLEANERS INC	Drycleaning Plants, Except Rugs

BARBARA DRY CLEANERS (Continued) **1018553085**

1972	BARBARA DRY CLEANERS	Drycleaning Plants, Except Rugs
1973	BARBARA DRY CLEANERS	Drycleaning Plants, Except Rugs
1973	ADMIRATION CLEANERS INC	Drycleaning Plants, Except Rugs
1974	ADMIRATION CLEANERS INC	Drycleaning Plants, Except Rugs
1974	BARBARA DRY CLEANERS	Drycleaning Plants, Except Rugs
1975	BARBARA DRY CLEANERS	Drycleaning Plants, Except Rugs
1975	ADMIRATION CLEANERS INC	Drycleaning Plants, Except Rugs
1976	BARBARA DRY CLEANERS	Drycleaning Plants, Except Rugs
1987	BARBARA DRY CLEANERS	Coin-Operated Laundries And Cleaning
1988	BARBARA DRY CLEANERS	Coin-Operated Laundries And Cleaning
1990	BARBARA DRY CLEANERS	Coin-Operated Laundries And Cleaning, NEC
1991	BARBARA DRY CLEANERS	Coin-Operated Laundries And Cleaning, NEC
1992	BARBARA DRY CLEANERS	Coin-Operated Laundries And Cleaning, NEC
1993	BARBARA DRY CLEANERS	Coin-Operated Laundries And Cleaning, NEC
1994	BARBARA DRY CLEANERS	Coin-Operated Laundries And Cleaning, NEC
1996	TAMARA DRY CLEANERS CORP	Drycleaning Plants, Except Rugs
1997	TAMARA DRY CLEANERS CORP	Drycleaning Plants, Except Rugs
1998	TAMARA DRY CLEANERS CORP	Drycleaning Plants, Except Rugs
2008	TAMARA DRY CLEANERS CORP	Drycleaning Plants, Except Rugs
2009	TAMARA DRY CLEANERS CORP	Drycleaning Plants, Except Rugs
2010	TAMARA DRY CLEANERS CORP	Drycleaning Plants, Except Rugs
2011	TAMARA DRY CLEANERS CORP	Drycleaning Plants, Except Rugs
2012	TAMARA DRY CLEANERS CORP	Drycleaning Plants, Except Rugs

---

B85 **YAU CLEANERS** **EDR Hist Cleaner** **1018822917**
ENE **150 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.020 mi.
108 ft. **Site 17 of 33 in cluster B**

Relative: EDR Hist Cleaner
Higher

Actual:
16 ft.

Year:	Name:	Type:
2001	YAU CLEANERS	Garment Pressing And Cleaners' Agents
2002	YAU CLEANERS	Garment Pressing And Cleaners' Agents
2003	YAU CLEANERS	Garment Pressing And Cleaners' Agents
2004	YAU CLEANERS	Garment Pressing And Cleaners' Agents
2005	YAU CLEANERS	Garment Pressing And Cleaners' Agents
2006	YAU CLEANERS	Garment Pressing And Cleaners' Agents
2007	YAU CLEANERS	Garment Pressing And Cleaners' Agents
2008	YAU CLEANERS	Garment Pressing And Cleaners' Agents
2009	YAU CLEANERS	Garment Pressing And Cleaners' Agents
2010	YAU CLEANERS	Garment Pressing And Cleaners' Agents
2011	YAU CLEANERS	Garment Pressing And Cleaners' Agents
2012	YAU CLEANERS	Garment Pressing And Cleaners' Agents

G86 **MANHOLE 3245** **NY Spills** **S104195891**
NW **441 W 18TH ST** **N/A**
< 1/8 **NEW YORK, NY**
0.020 mi.
108 ft. **Site 1 of 8 in cluster G**

Relative: SPILLS:
Lower

Actual:
13 ft.

Name:	MANHOLE 3245
Address:	441 W 18TH ST
City,State,Zip:	NEW YORK, NY

MANHOLE 3245 (Continued) **S104195891**

Spill Number/Closed Date:	9908043 / 2004-02-05
Facility ID:	9908043
Facility Type:	ER
DER Facility ID:	245985
Site ID:	304531
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3101
Spill Date:	1999-10-02
Investigator:	COMENALE
Referred To:	Not reported
Reported to Dept:	1999-10-02
CID:	211
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-02
Spill Record Last Update:	2004-02-05
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PL
Spiller Company:	001
Contact Name:	RICHARD ROCHE
DEC Memo:	""
Remarks:	"blown joint caused spill - sample taken clean up pending results con ed #"

All Materials:

Site ID:	304531
Operable Unit ID:	1082323
Operable Unit:	01
Material ID:	300728
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C87 **THE CALEDONIA** **NY AST** **A100326241**
West **450 WEST 17TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.021 mi.
109 ft. **Site 26 of 29 in cluster C**

Relative:
Lower

Actual:
12 ft.

AST:

Name:	THE CALEDONIA
Address:	450 WEST 17TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-611055
Program Type:	PBS
UTM X:	583908.60829
UTM Y:	4510777.47837
Expiration Date:	11/01/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	412310
Affiliation Type:	Facility Owner
Company Name:	17TH AND 10TH ASSOCIATES
Contact Type:	AGENT
Contact Name:	SUP
Address1:	423 WEST 55TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10019
Country Code:	001
Phone:	(212) 506-5800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2018-02-05

Site Id:	412310
Affiliation Type:	Mail Contact
Company Name:	RELATED MANAGEMENT
Contact Type:	Not reported
Contact Name:	TAMI VEIKOS
Address1:	423 WEST 55TH STREET, 9TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10019
Country Code:	001
Phone:	(212) 506-5800
EMail:	TVEIKOS@REALTED.COM
Fax Number:	Not reported
Modified By:	LNROSARI
Date Last Modified:	2016-01-19

Site Id:	412310
Affiliation Type:	Facility Operator
Company Name:	THE CALEDONIA
Contact Type:	Not reported
Contact Name:	ANDRE MASLOVJULIA C DEL ORBE JR

THE CALEDONIA (Continued) **A100326241**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 842-1930
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2018-02-05

Site Id:	412310
Affiliation Type:	Emergency Contact
Company Name:	17TH AND 10TH ASSOCIATES
Contact Type:	Not reported
Contact Name:	ANDRE MASLOVJULIA C DEL ORBE JR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 842-1930
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2018-02-05

Tank Info:

Tank Number:	1
Tank Id:	228004
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

	G02 - Tank Secondary Containment - Vault (w/access)
	F00 - Pipe External Protection - None
	J00 - Dispenser - None
	H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
	L00 - Piping Leak Detection - None
	I02 - Overfill - High Level Alarm
	B04 - Tank External Protection - Fiberglass
	E00 - Piping Secondary Containment - None
	C03 - Pipe Location - Aboveground/Underground Combination
	K00 - Spill Prevention - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	A00 - Tank Internal Protection - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/2007
Capacity Gallons:	15000

THE CALEDONIA (Continued) **A100326241**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	LNROSARI
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

E88 **CON EDISON** **NY MANIFEST** **S117537388**
North **432 W 20 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.021 mi.
110 ft. **Site 13 of 15 in cluster E**

Relative: **Lower**

Actual: **13 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	432 W 20 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004699484
Facility Status:	Not reported
Location Address 1:	432 W 20 ST
Code:	BP
Location Address 2:	SB3609
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004699484
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	11/25/2014
Trans1 Recv Date:	11/25/2014
Trans2 Recv Date:	12/03/2014
TSD Site Recv Date:	12/03/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004699484

CON EDISON (Continued) **S117537388**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002609945GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

E89 **CON EDISON SERVICE BOX: 3608** **NJ MANIFEST** **S120665930**
North **434-436 W 20TH ST & 10TH AVE E OF** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.021 mi.
111 ft. **Site 14 of 15 in cluster E**

Relative: NJ MANIFEST:
Lower

Actual:
13 ft.

EPA Id:	NYP004277083
Mail Address:	Not reported
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JOSE MONTALVO
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported

CON EDISON SERVICE BOX: 3608 (Continued) **S120665930**

Date Change: Not reported

Manifest:
Manifest Number: 010708016JJK
EPA ID: NYP004277083
Date Shipped: 2/25/2013
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: Not reported
Quantity: 1,000.00 Pounds

Manifest Number: 001675123GBF
EPA ID: NYP004277083
Date Shipped: 11/4/2012
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported

CON EDISON SERVICE BOX: 3608 (Continued) **S120665930**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	300.00 gallons

B90 **CON EDISON** **NY MANIFEST** **S116551816**
East **136 9 AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.021 mi.
112 ft. **Site 18 of 33 in cluster B**

Relative:
Higher

Actual:
16 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	136 9 AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004504379
Facility Status:	Not reported
Location Address 1:	136 9 AVE
Code:	BP

CON EDISON (Continued) **S116551816**

Location Address 2:	SB39664
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004504379
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/18/2014
Trans1 Recv Date:	04/18/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004504379
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416633GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300

CON EDISON (Continued) **S116551816**

Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

F91 **110 NINTH AVENUE** **NY UST** **U004330245**
SE **110 NINTH AVENUE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.022 mi.
116 ft. **Site 4 of 20 in cluster F**

Relative:
Higher

Actual:
16 ft.

UST:

Name:	110 NINTH AVENUE
Address:	110 NINTH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-364789 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	01/27/2024
UTM X:	584116.99938
UTM Y:	4510702.08105
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	18502
Affiliation Type:	Facility Owner
Company Name:	110 NINTH AVENUE CORP.
Contact Type:	AGENT
Contact Name:	GRACE WOO
Address1:	138 ATLANTIC AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201
Country Code:	001
Phone:	(718) 625-4114
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2009-01-21

Site Id:	18502
Affiliation Type:	Facility Operator
Company Name:	110 NINTH AVENUE
Contact Type:	Not reported
Contact Name:	GRANITE INTERNATIONAL MGMT
Address1:	Not reported
Address2:	Not reported
City:	Not reported

110 NINTH AVENUE (Continued) **U004330245**

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 625-4114
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2018-09-20

Site Id: 18502
Affiliation Type: Emergency Contact
Company Name: 110 NINTH AVENUE CORP.
Contact Type: Not reported
Contact Name: IRINEO ACEVEDO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 515-1936
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2018-09-20

Site Id: 18502
Affiliation Type: Mail Contact
Company Name: 110 NINTH AVENUE CORP.
Contact Type: Not reported
Contact Name: NOT PROVIDED
Address1: C/O GRANITE INT'L MGMT., LLC
Address2: 138 ATLANTIC AVENUE
City: BROOKLYN
State: NY
Zip Code: 11201-5585
Country Code: 001
Phone: (718) 625-4114
EMail: Not reported
Fax Number: Not reported
Modified By: KXLIU
Date Last Modified: 2020-07-20

Tank Info:

Tank Number: 001
Tank ID: 22639
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 3000
Install Date: 10/12/1984
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

110 NINTH AVENUE (Continued) **U004330245**

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXLIU
Last Modified: 07/20/2020

Equipment Records:

I05 - Overfill - Vent Whistle
C01 - Pipe Location - Aboveground
L09 - Piping Leak Detection - Exempt Suction Piping
H08 - Tank Leak Detection - Weep holes in Vaults with no access for inspection
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
E02 - Piping Secondary Containment - Vault (with Access)
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other
K00 - Spill Prevention - None

G92 **LOT 60,TAXBLOCK 715** **NY E DESIGNATION** **S108076986**
WNW **456 WEST 18 STREET** **N/A**
< 1/8 **MANHATTAN, NY 10011**
0.022 mi.
118 ft. **Site 2 of 8 in cluster G**

Relative:
Lower

Actual:
12 ft.

E DESIGNATION:
Name: LOT 60,TAXBLOCK 715
Address: 456 WEST 18 STREET
City,State,Zip: MANHATTAN, NY 10011
Tax Lot(s): 60
Tax Block: 715
Borough Code: MN
E-No: E-142
Effective Date: 6/23/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP069M
Ulurp Number: 050161 ZRM
Zoning Map No: 8b

Description: Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date: Not reported

Description: Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

G93 **456-464 W. 18TH STREET** **NY UST** **U003740180**
WNW **456-464 W 18TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.022 mi.
118 ft. **Site 3 of 8 in cluster G**

Relative:
Lower

Actual:
12 ft.

UST:

Name:	456-464 W. 18TH STREET
Address:	456-464 W 18TH STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-604449 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583979.13551
UTM Y:	4510840.68279
Site Type:	Unknown

Affiliation Records:

Site Id:	26323
Affiliation Type:	Facility Owner
Company Name:	KOSTAS NANIS
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	24-02 24TH AVENUE
Address2:	Not reported
City:	ASTORIA
State:	NY
Zip Code:	11102
Country Code:	001
Phone:	(718) 545-8852
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	26323
Affiliation Type:	Mail Contact
Company Name:	NANIS & RINALDI, LLP
Contact Type:	Not reported
Contact Name:	WILLIAM NANIS, ESG
Address1:	30-97 STEINWAY STREET
Address2:	Not reported
City:	ASTORIA
State:	NY
Zip Code:	11103
Country Code:	001
Phone:	(718) 777-8887
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	26323
Affiliation Type:	Facility Operator
Company Name:	456-464 W. 18TH STREET
Contact Type:	Not reported
Contact Name:	KOSTAS NANIS
Address1:	Not reported

456-464 W. 18TH STREET (Continued) **U003740180**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 545-8852
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	26323
Affiliation Type:	Emergency Contact
Company Name:	KOSTAS NANIS
Contact Type:	Not reported
Contact Name:	KOSTAS NANIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 545-8852
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	1
Tank ID:	57791
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2642
Common Name of Substance:	Used Oil (Heating, On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I05 - Overfill - Vent Whistle
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None

456-464 W. 18TH STREET (Continued) **U003740180**

D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number:	2
Tank ID:	57792
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0013
Common Name of Substance:	Lube Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle

Tank Number:	3
Tank ID:	57793
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0013
Common Name of Substance:	Lube Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

456-464 W. 18TH STREET (Continued) **U003740180**

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None

B94 **400 WEST 20TH STREET** **NY AST** **U004078466**
NE **400 WEST 20TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.023 mi.
119 ft. **Site 19 of 33 in cluster B**

Relative:
Higher

Actual:
16 ft.

AST:

Name:	400 WEST 20TH STREET
Address:	400 WEST 20TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-606340
Program Type:	PBS
UTM X:	584190.67353
UTM Y:	4510884.20125
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	28203
Affiliation Type:	Mail Contact
Company Name:	LMS REALTY LLC
Contact Type:	Not reported
Contact Name:	ROBERT MALTA
Address1:	119 W 72ND STREET
Address2:	P.O. BOX 400
City:	NEW YORK
State:	NY
Zip Code:	10023
Country Code:	001
Phone:	(212) 874-0035
EMail:	ESCARZA19@HOTMAIL.COM
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-09-25

Site Id:	28203
Affiliation Type:	Facility Operator
Company Name:	400 WEST 20TH STREET
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported

400 WEST 20TH STREET (Continued) **U004078466**

Country Code:	001
Phone:	N/A
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-09-25

Site Id:	28203
Affiliation Type:	Emergency Contact
Company Name:	LMS REALTY LLC
Contact Type:	Not reported
Contact Name:	ROBERT MALTA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 874-0035
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-09-25

Site Id:	28203
Affiliation Type:	Facility Owner
Company Name:	LMS REALTY LLC
Contact Type:	MEMBER/OWNER
Contact Name:	ROBERT MALTA
Address1:	119 W 72ND STREET BOX 400
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10023
Country Code:	001
Phone:	(212) 874-0035
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-09-25

Tank Info:

Tank Number:	001
Tank Id:	61285
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping

400 WEST 20TH STREET (Continued) **U004078466**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I05 - Overfill - Vent Whistle

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/06/2012
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

B95 **NINTH AVENUE APT CORP** **NY AST** **U003387260**
ENE **162 NINTH AVENUE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.024 mi.
125 ft. **Site 20 of 33 in cluster B**

Relative:
Higher

Actual:
16 ft.

AST:

Name:	NINTH AVENUE APT CORP
Address:	162 NINTH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-244236
Program Type:	PBS
UTM X:	584205.87603
UTM Y:	4510865.49878
Expiration Date:	07/07/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	9444
Affiliation Type:	Facility Owner
Company Name:	NINTH AVE APT CORP
Contact Type:	MANAGING AGENT
Contact Name:	RICARDO VON PUTTKAMMER
Address1:	167 MADISON AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 683-3200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-08-22

Site Id:	9444

NINTH AVENUE APT CORP (Continued) **U003387260**

Affiliation Type:	Facility Operator
Company Name:	NINTH AVENUE APT CORP
Contact Type:	Not reported
Contact Name:	JOSEPH ATTARD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 944-1132
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9444
Affiliation Type:	Emergency Contact
Company Name:	NINTH AVE APT CORP
Contact Type:	Not reported
Contact Name:	RVP MANAGEMENT CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 683-3200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9444
Affiliation Type:	Mail Contact
Company Name:	RVP MANAGEMENT CORP.
Contact Type:	Not reported
Contact Name:	RICARDO VON PUTTKAMMER
Address1:	167 MADISON AVENUE
Address2:	ROOM 401
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 683-3200
EMail:	RVP@RVPMANAGEMENT.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-08-22

Tank Info:

Tank Number:	001
Tank Id:	11532
Material Code:	0009
Common Name of Substance:	Gasoline

NINTH AVENUE APT CORP (Continued) **U003387260**

Equipment Records:

B05 - Tank External Protection - Jacketed
G00 - Tank Secondary Containment - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
L00 - Piping Leak Detection - None
H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm
E00 - Piping Secondary Containment - None
C01 - Pipe Location - Aboveground
J01 - Dispenser - Pressurized Dispenser
F00 - Pipe External Protection - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/27/1962
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	KAKYER
Last Modified:	04/14/2017
Material Name:	gasoline

G96 **CON EDISON SERVICE BOX: 3231** **RCRA NonGen / NLR** **1016449950**
WNW **458 W 18TH ST** **NY MANIFEST** **NYP004256541**
< 1/8 **NEW YORK, NY 10011**
0.025 mi.
131 ft. **Site 4 of 8 in cluster G**

Relative: **Lower**
Actual: **12 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130319
Handler Name:	CON EDISON SERVICE BOX: 3231
Handler Address:	458 W 18TH ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004256541
Contact Name:	JUAN RODRIGUEZ
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	347-865-5931
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2

CON EDISON SERVICE BOX: 3231 (Continued) **1016449950**

Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

CON EDISON SERVICE BOX: 3231 (Continued) **1016449950**

Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20130219
Handler Name: CON EDISON SERVICE BOX: 3231
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130319
Handler Name: CON EDISON SERVICE BOX: 3231
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 458 W 18TH ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004256541
Facility Status: Not reported
Location Address 1: 458 W 18TH ST
Code: BP
Location Address 2: SERV BOX 3231
Total Tanks: Not reported
Location City: NEW YORK

CON EDISON SERVICE BOX: 3231 (Continued) **1016449950**

Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004256541
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 02/19/2013
Trans1 Recv Date: 02/19/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/20/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004256541
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 010840422JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 500
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks

CON EDISON SERVICE BOX: 3231 (Continued) **1016449950**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B97 **CON EDISON SERVICE BOX: 3621** **RCRA NonGen / NLR** **1017772922**
NE **315-313 W 20TH ST & 9TH AVE** **FINDS** **NYP004506994**
< 1/8 **NEW YORK, NY 10011**
0.026 mi.
139 ft. **Site 21 of 33 in cluster B**

Relative:
Higher

Actual:
16 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	20140522
Handler Name:	CON EDISON SERVICE BOX: 3621
Handler Address:	315-313 W 20TH ST & 9TH AVE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004506994
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported

CON EDISON SERVICE BOX: 3621 (Continued) **1017772922**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 3621 (Continued) **1017772922**

Receive Date: 20140422
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140522
Handler Name: CON EDISON SERVICE BOX: 3621
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063802853

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

B98 **CON EDISON SERVICE BOX: 3616** **RCRA NonGen / NLR** **1017773072**
NE **359 W 20TH ST & 9TH AVE E OF** **FINDS** **NYP004508503**
< 1/8 **NEW YORK, NY 10011**
0.026 mi.
139 ft. **Site 22 of 33 in cluster B**

Relative: **Higher**
Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140522
Handler Name:	CON EDISON SERVICE BOX:	3616
Handler Address:		359 W 20TH ST & 9TH AVE E OF
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004508503
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 3616 (Continued) **1017773072**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 3616 (Continued) **1017773072**

Electronic Manifest Broker: Not reported

Receive Date: 20140522
Handler Name: CON EDISON SERVICE BOX: 3616
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063760880

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

B99 **CON EDISON SERVICE BOX: 3628** **RCRA NonGen / NLR** **1017772919**
NE **326-324 W 20TH ST & 9TH AVE** **FINDS** **NYP004506960**
< 1/8 **NEW YORK, NY 10011**
0.026 mi.
139 ft. **Site 23 of 33 in cluster B**

Relative: Higher
Actual: 16 ft.

RCRA NonGen / NLR:
Date Form Received by Agency: 20140522
Handler Name: CON EDISON SERVICE BOX: 3628
Handler Address: 326-324 W 20TH ST & 9TH AVE
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYP004506960
Contact Name: THOMAS TEELING
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-3770

CON EDISON SERVICE BOX: 3628 (Continued) **1017772919**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

CON EDISON SERVICE BOX: 3628 (Continued) **1017772919**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140522
Handler Name: CON EDISON SERVICE BOX: 3628	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 3628 (Continued) **1017772919**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063802826

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

B100 **NYC DEP** **RCRA NonGen / NLR** **1016454055**
NE **20TH ST BETW 8TH & 9TH AVE** **FINDS** **NYP003669017**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.026 mi. **NY MANIFEST**
139 ft. **Site 24 of 33 in cluster B**

Relative:
Higher

Actual:
16 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	20140609
Handler Name:	NYC DEP
Handler Address:	20TH ST BETW 8TH & 9TH AVE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP003669017
Contact Name:	JOANNE NURSE
Contact Address:	JUNCTION BLVD
Contact City,State,Zip:	FLUSHING, NY 11373
Contact Telephone:	718-595-4675
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ADMIN MGR
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	JUNCTION BLVD
Mailing City,State,Zip:	FLUSHING, NY 11373
Owner Name:	Not reported

NYC DEP (Continued) **1016454055**

Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170526
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

NYC DEP (Continued) **1016454055**

Sub-Part P Indicator: No

Historic Generators:

Receive Date:	20131219
Handler Name: NYC DEP	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140609
Handler Name: NYC DEP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110057075221

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

NYC DEP (Continued) **1016454055**

ECHO:

Envid:	1016454055
Registry ID:	110057075221
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110057075221
Name:	NYC DEP
Address:	20TH ST BETW 8TH & 9TH AVE
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	NYC DEP
Address:	20TH ST BETW 8TH & 9TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP003669017
Facility Status:	Not reported
Location Address 1:	20TH ST BETW 8TH & 9TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP003669017
Mailing Name:	NYC DEP
Mailing Contact:	NYC DEP
Mailing Address 1:	9505 HORACE HARDING EXPRESSWAY
Mailing Address 2:	Not reported
Mailing City:	CORONA
Mailing State:	NY
Mailing Zip:	11368
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9177094005

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	12/11/2013
Trans1 Recv Date:	12/11/2013
Trans2 Recv Date:	12/17/2013
TSD Site Recv Date:	12/23/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP003669017
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	008760087JJK

NYC DEP (Continued) **1016454055**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	15
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B101 **CON EDISON SERVICE BOX: 3619** **RCRA NonGen / NLR** **1017773071**
NE **337-335 W 20TH ST & 9TH AVE E OF** **FINDS** **NYP004508495**
< 1/8 **NEW YORK, NY 10011**
0.026 mi.
139 ft. **Site 25 of 33 in cluster B**

Relative: **Higher**

Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140522
Handler Name:	CON EDISON SERVICE BOX:	3619
Handler Address:		337-335 W 20TH ST & 9TH AVE E OF
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004508495
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY

CON EDISON SERVICE BOX: 3619 (Continued) **1017773071**

State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No

CON EDISON SERVICE BOX: 3619 (Continued) **1017773071**

Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:

Receive Date: 20140422
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140422
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140522
Handler Name: CON EDISON SERVICE BOX: 3619
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

CON EDISON SERVICE BOX: 3619 (Continued) **1017773071**

FINDS:
Registry ID: 110063760871

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

B102 **CON EDISON SERVICE BOX: 3622** **RCRA NonGen / NLR** **1017773064**
NE **309-307 W 20TH ST & 9TH AVE E OF** **FINDS** **NYP004508420**
< 1/8 **NEW YORK, NY 10011**
0.026 mi.
139 ft. **Site 26 of 33 in cluster B**

Relative:
Higher

Actual:
16 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20140522
Handler Name:	CON EDISON SERVICE BOX:	3622
Handler Address:		309-307 W 20TH ST & 9TH AVE E OF
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004508420
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No

CON EDISON SERVICE BOX: 3622 (Continued) **1017773064**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON SERVICE BOX: 3622 (Continued) **1017773064**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140422
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140522
Handler Name: CON EDISON SERVICE BOX: 3622
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063760808

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

B103
NE
< 1/8
0.026 mi.
139 ft.

CON EDISON SERVICE BOX: 3615
365 W 20TH ST & 9TH AVE E OF
NEW YORK, NY 10011

Site 27 of 33 in cluster B

RCRA NonGen / NLR
FINDS

1017773070
NYP004508487

Relative:
Higher

Actual:
16 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20140522
Handler Name:	CON EDISON SERVICE BOX:	3615
Handler Address:		365 W 20TH ST & 9TH AVE E OF
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004508487
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 3615 (Continued) **1017773070**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 3615 (Continued) **1017773070**

Electronic Manifest Broker: Not reported

Receive Date: 20140522
Handler Name: CON EDISON SERVICE BOX: 3615
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063760862

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

C104 **CON EDISON - MANHOLE 2787** **NY MANIFEST** **S120957807**
WSW **460-454 W 16TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.026 mi.
139 ft. **Site 27 of 29 in cluster C**

Relative:
Lower

Actual:
12 ft.

NY MANIFEST:
Name: CON EDISON - MANHOLE 2787
Address: 460-454 W 16TH ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004868594
Facility Status: Not reported
Location Address 1: 460-454 W 16TH ST
Code: BP
Location Address 2: Not reported

CON EDISON - MANHOLE 2787 (Continued) **S120957807**

Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004868594
Mailing Name:	CON EDISON - MANHOLE 2787
Mailing Contact:	THERESA BURKARD
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602262

C105 **CON EDISON - MANHOLE 2787** **NJ MANIFEST** **S123565212**
WSW **460-454 W 16TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.026 mi.
139 ft. **Site 28 of 29 in cluster C**

Relative:
Lower

Actual:
12 ft.

NJ MANIFEST:

EPA Id:	NYP004868594
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	ALYSSA SOTTO
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002613522GBF
EPA ID:	NYP004868594
Date Shipped:	11/12/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

CON EDISON - MANHOLE 2787 (Continued) **S123565212**

Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

C106 **CON EDISON - MANHOLE 2787** **RCRA-LQG** **1024890486**
WSW **460-454 W 16TH ST** **NYP004868594**
< 1/8 **NEW YORK, NY 10011**
0.026 mi.
139 ft. **Site 29 of 29 in cluster C**

Relative: RCRA-LQG:
Lower

Date Form Received by Agency:	20180410
Handler Name:	CON EDISON - MANHOLE 2787
Handler Address:	460-454 W 16TH ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004868594
Contact Name:	ALYSSA SOTTO
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE

Actual:
12 ft.

CON EDISON - MANHOLE 2787 (Continued) **1024890486**

Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

CON EDISON - MANHOLE 2787 (Continued) **1024890486**

Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20151112
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20151112
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180410
Handler Name: CON EDISON - MANHOLE 2787
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

CON EDISON - MANHOLE 2787 (Continued) **1024890486**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

B107 **WEST 20TH ST & 9TH AVENUE** **NY Spills** **S102147250**
NE **WEST 20TH ST / 9TH AVENUE** **N/A**
< 1/8 **MANHATTAN, NY**
0.026 mi.
139 ft. **Site 28 of 33 in cluster B**

Relative:
Higher

Actual:
16 ft.

SPILLS:

Name:	WEST 20TH ST & 9TH AVENUE
Address:	WEST 20TH ST / 9TH AVENUE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9309450 / 2010-09-01
Facility ID:	9309450
Facility Type:	ER
DER Facility ID:	135372
Site ID:	160295
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	1993-11-04
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	1993-11-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-11-04
Spill Record Last Update:	2010-09-01
Spiller Name:	Not reported
Spiller Company:	COLUMBIA PRESBYTIRIAN HOS
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 10/10/95: This is additional information about material spilled from the translation of the old spill file: POSSIBLE HISTORIC SP. 4/12/04-Vought-Spill transferred from Miller to Rommel as per Rommel. 6/7/07-Matthew Klaas (Albany DER) -Attempted to call Willian Silver of AKRF inc. at 212-340-9827, Got a machine recording stating that they had moved, and listing a new phone number to reach them at. Tried the new telephone number of 212-646-3889, this number only leads to a machine recorded error message. -Found corperate phone number on AKRF website, and was transfered to a Maggie Douglas at

WEST 20TH ST & 9TH AVENUE (Continued) **S102147250**

212-646-3889530. She was not in the office so I left a message stating who I was and what I was looking for, left my telephone number and a call back. 6/11/07-Matthew Klaas (Albany DER) -Drafted a letter to AKRF requesting additional information to the reported spill. 6/19/07 - Matthew Klaas (Albany DER) -Maggie Douglas called back requesting a copy of the spill file, Martin Brand (Albany DER) faxed a copy to 212-726-0942 3/31/09 - Austin - Transferred from Needs Reassignment to Rahman for further work to remeidate and close - end 06/21/10 Left a messege for Maggie Douglas@(212)696-0670 asking any relevant info they may have regarding the spill.Later in the day, Maggie returned my call and spill report was emailed to her, as per her request.(sr) 09/01/10 AKRF does n't have anything in the files.Moreover, the site location is not specific.It says intersection of West 20th St & 9th Avenue.Therefore, unable to verify the nature of the complaint.Case closed.(sr)"

Remarks: "LAB. TEST SHOWS PETRO ON AROUND WATER - TO FURTHER INVEST. & POSSIBLE TAKE CORRECTIVE ACTION."

All Materials:

Site ID:	160295
Operable Unit ID:	988539
Operable Unit:	01
Material ID:	392104
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

G108 **AUTO CARE WEST** **NY LTANKS** **S106719717**
WNW **464 WEST 18TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.027 mi.
145 ft. **Site 5 of 8 in cluster G**

Relative: **Lower**
Actual: **12 ft.**

LTANKS:

Name:	AUTO CARE WEST
Address:	464 WEST 18TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9909074 / 2000-01-26
Facility ID:	9909074
Site ID:	228626
Spill Date:	1999-10-26
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	1999-10-26
CID:	252
Water Affected:	Not reported
Spill Notifier:	Other

AUTO CARE WEST (Continued) **S106719717**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-26
Spill Record Last Update:	2002-01-23
Spiller Name:	Not reported
Spiller Company:	COSTAS MANIS
Spiller Address:	464 WEST 18TH ST
Spiller County:	001
Spiller Contact:	BOBBY MARINO
Spiller Phone:	(212) 255-8412
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	188548
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND 11/17/99 Call from Mark Turoff - Environmental consultant hired to work this job. pager 917-525-3087 cell 917-750-1843 Mr. Turoff requested an extension in time until late December. Sangesland asked several specific questions about what was being done on the site now (new tenent moving in?) Are there any other tanks on the site? will the tank be removed or abandoned in place? Mr. Turoff knew nothing. Sangesland asked him to answer these questions and plan what needed to be done. Submit that in writing and then PERHAPS the actual work could be postponed until late Dec. '99 11/26/99 - Mr. Turoff sent a letter dated 11/22/99 requesting an extension of deadline date. NONE of the information requested in 11/17/99 telephone conversation was submitted in this letter. Mr. Turoff requested a written extension of the deadline, but since he did not submit what was requested, no such letter will be sent out. 12/6/99 - Call from owner saying Trinity Consulting was on site chopping open the floor .... (no notification was made to DEC about this work).... Sampling will be done 12/7/99 early AM 12/7/99 - Six GeoProbe borings were pushed down to 10' - 12' to bedrock. Sangesland was on site for the first 4 borings - all appeared clean. Borings will be sent in for testing. If the results come back clean, the site will be closed out. 12/29/99 - Trinity sent in data from several soil borings. After Sangesland left the site on 11/7/99 another tank was found in the garage. This new tank was a clean motor oil storage tank used to put into cars during service. Borings were done around this one also. All borings were tested to EPA 8270. All results were below detection limits except for 1 taken near the fill line of the used motor oil tank. The one high sample had the following values: (Eco Test Lab) all below 300 ug/kg except: Fluoranthese = 420 Pyrene = 380 Benzo(a)anthracene = 440 Chrysene = 440 Benzo(b)fluoranthene = 500 Benzo(k)fluoranthene = 500 DEC status on this site is NOT closed, but it will be listed as inactive with no further action required. Since the source is gone and the contamination was just around the fill line and not wide spread, DEC direction is to have the tanks filled and taken out of service. Over time natural attenuation should remediate the site. In it's expected use as an art gallery with a concrete floor, this should have no impact on either health or environment. In the future if the use of the property changes, this issue may need to be addressed again. 1/11/2000 - Vinnie Lovari from Island Tank (718-967-9424) was given permission to open up the tanks, recheck size and then closed them out in place. PBS Registration

AUTO CARE WEST (Continued) **S106719717**

paperwork will be sent after the work is done. 1/26/2000 - Spill event is closed out."

Remarks: "TANK IN GROUND FOUND TO BE LEAKING-NO FURTHER INFO AT THIS TIME. "

All Materials:

Site ID:	228626
Operable Unit ID:	1083671
Operable Unit:	01
Material ID:	298170
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F109 **CON EDISON** **NY MANIFEST** **S117313556**
SE **F/O 108 9 AV** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.028 mi.
149 ft. **Site 5 of 20 in cluster F**

Relative:
Higher

Actual:
16 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	F/O 108 9 AV
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004603320
Facility Status:	Not reported
Location Address 1:	F/O 108 9 AV
Code:	BP
Location Address 2:	MH39653
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004603320
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported

CON EDISON (Continued) **S117313556**

Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/2014
Trans1 Recv Date:	07/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004603320
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504417GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

F110 **CON EDISON MANHOLE 39653** **NJ MANIFEST** **S117984976**
SE **108 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.028 mi.
149 ft. **Site 6 of 20 in cluster F**

Relative: NJ MANIFEST:
Higher

EPA Id:	NYP004246312
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported

Actual:
16 ft.

CON EDISON MANHOLE 39653 (Continued) **S117984976**

Contact:	BENJAMIN BAMONTE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	009204646JJK
EPA ID:	NYP004246312
Date Shipped:	1/12/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported

CON EDISON MANHOLE 39653 (Continued) **S117984976**

Quantity: 5,000.00 Pounds

F111 **CON EDISON MANHOLE 39653** **RCRA NonGen / NLR** **1015746638**
SE **108 9TH AVE** **NY MANIFEST** **NYP004246312**
< 1/8 **NEW YORK, NY 10011**
0.028 mi.
149 ft. **Site 7 of 20 in cluster F**

Relative: **Higher**
Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20120211
Handler Name:	CON EDISON MANHOLE 39653
Handler Address:	108 9TH AVE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004246312
Contact Name:	BENJAMIN BAMONTE
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-894-9549
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN

CON EDISON MANHOLE 39653 (Continued) **1015746638**

Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20120712
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20120112
Handler Name:	CON EDISON MANHOLE 39653
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20120211
Handler Name:	CON EDISON MANHOLE 39653
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

CON EDISON MANHOLE 39653 (Continued) **1015746638**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CONED
Address:	108 9TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004246312
Facility Status:	Not reported
Location Address 1:	108 9TH AVE.
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004246312
Mailing Name:	CONED
Mailing Contact:	CONED
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FLOOR
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	01/12/2012

CON EDISON MANHOLE 39653 (Continued) **1015746638**

Trans1 Recv Date:	01/12/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/13/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004246312
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	009204646JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	5000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

F112 **CON EDISON** **RCRA NonGen / NLR** **1012186222**
SE **108 9TH AVE** **NY MANIFEST** **NYP004170601**
< 1/8 **NEW YORK, NY 10001**
0.028 mi.
149 ft. **Site 8 of 20 in cluster F**

Relative: **Higher**
Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		108 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10001
EPA ID:		NYP004170601
Contact Name:		PAUL WALSH
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-203-0646

CON EDISON (Continued) **1012186222**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

CON EDISON (Continued) **1012186222**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160711
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090529
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON (Continued) **1012186222**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	108 9TH AVE
City,State,Zip:	NEW YORK, NY 10001
Country:	USA
EPA ID:	NYP004170601
Facility Status:	Not reported
Location Address 1:	9th AVE & WEAT 17th ST- MH 396653
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MANHATTAN
Location State:	NY
Location Zip:	10020
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004170601
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/29/2009
Trans1 Recv Date:	05/29/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/01/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004170601
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001440639FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON (Continued) **1012186222**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	270
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	3
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	B002
Waste Code 1_3:	B007
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H113 **MANHOLE #57478** **NY Spills** **S107416249**
ESE **359 WEST 18 STREET** **N/A**
< 1/8 **NEW YORK, NY**
0.032 mi.
171 ft. **Site 1 of 15 in cluster H**

Relative: **Higher**

Actual: **16 ft.**

SPILLS:

Name:	MANHOLE #57478
Address:	359 WEST 18 STREET
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0508731 / 2007-05-03
Facility ID:	0508731
Facility Type:	ER
DER Facility ID:	301711
Site ID:	354374
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2005-10-21
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2005-10-21
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-10-21
Spill Record Last Update:	2007-05-03
Spiller Name:	ERT DESK

MANHOLE #57478 (Continued) **S107416249**

Spiller Company:	CON EDISON
Spiller Address:	359 WEST 18TH
Spiller Company:	999
Contact Name:	ERT DESK'
DEC Memo:	"05/03/07 - See e-docs for Con Ed report detailing cleanup and closure. 161589. 10-21-05 06:05. SPILL CABLE OIL (LEAKING JOINT)AT 06:13 Ray Jenkins 56029 Flush dept supervisor reports to control board , J Moran 01182 , that he found 1 PT of cable oil leaking from joint in M57478, located opp. 359 w 18 St Mr Jenkins was on location to flush manhole for B TICKET # ME05017941 and found oil leaking from joint and reported it as a D-fault. Emergency Dept. foreman Carl Bruce 89045 responded to D-fault on tag 3 04380 and authorized taking of samples. No fire or smoke involved . No sewers or waterways affected . No injurys related to spill . No weather conditions added to hazard of spill . ACCT # 14320. Oil spilled on concrete floor of manhole and no private property was affected. Environmental tag # 49492. No standing water. Existing sewer connection. No substantial cracks. No dielectric filled feeders in structure. Liquid sample taken for PCB. Chain of custody # EE00627. Initial cleanup----- oil absorbent pads applied to area. Logged by D. Gaynair 20079 CIG T. Enright 48536 notified at 07:43 "
Remarks:	"DEFAULT ;NO TO 5 QUESTIONS; CONED # 161589"

All Materials:

Site ID:	354374
Operable Unit ID:	1111788
Operable Unit:	01
Material ID:	2101834
Material Code:	0020B
Material Name:	cable oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

G114 **SPILL NUMBER 0013277** **NY Spills** **S104951543**
NW **445 WEST 18TH ST (OPP)** **N/A**
< 1/8 **MANHATTAN, NY**
0.032 mi.
171 ft. **Site 6 of 8 in cluster G**

Relative: **Lower**
Actual: **12 ft.**

SPILLS:

Name:	SPILL NUMBER 0013277
Address:	445 WEST 18TH ST (OPP)
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0013277 / 2001-05-10
Facility ID:	0013277
Facility Type:	ER
DER Facility ID:	170064
Site ID:	204578
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C4
SWIS:	3101
Spill Date:	2001-03-14

SPILL NUMBER 0013277 (Continued) **S104951543**

Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2001-03-20
CID:	207
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-03-20
Spill Record Last Update:	2001-05-16
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	ELIE SAINT-JEAN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 5/15/2001 TJD Drum emptied 5/10/2001 see spill#9930008 PIN#01036"
Remarks:	"drum intact and not leaking - hydrocarbon oil"

B115 **GENERAL THEOLOGICAL SEMINARY** **RCRA-SQG** **1001223855**
NE **175 9TH AVE** **FINDS** **NYR000050716**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.034 mi. **NY MANIFEST**
180 ft. **Site 29 of 33 in cluster B**

Relative: **Higher**
Actual: **16 ft.**

RCRA-SQG:

Date Form Received by Agency:	20070101
Handler Name:	GENERAL THEOLOGICAL SEMINARY
Handler Address:	175 9TH AVE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYR000050716
Contact Name:	KEVIN FALOWSKI
Contact Address:	9TH AVE
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	914-654-8800
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	9TH AVE
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	GENERAL THEOLOGICAL SEMINARY
Owner Type:	Private
Operator Name:	GENERAL THEOLOGICAL SEMINARY

GENERAL THEOLOGICAL SEMINARY (Continued) **1001223855**

Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211116
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

GENERAL THEOLOGICAL SEMINARY (Continued) **1001223855**

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D002
Waste Description: CORROSIVE WASTE

Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: GENERAL THEOLOGICAL SEMINARY
Legal Status: Private
Date Became Current: 19801231
Date Ended Current: Not reported
Owner/Operator Address: 175 9TH AVE - CHELSEA #2 3 4
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 914-654-8800
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: GENERAL THEOLOGICAL SEMINARY
Legal Status: Private
Date Became Current: 19801231
Date Ended Current: Not reported
Owner/Operator Address: 175 9TH AVE - CHELSEA #2 3 4
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 914-654-8800
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE GENERAL THEOLOGICAL SEMINAR
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 175 9TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 212-243-5150
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: GENERAL THEOLOGICAL SEMINARY
Legal Status: Private
Date Became Current: 19801231
Date Ended Current: Not reported
Owner/Operator Address: 175 9TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 914-654-8800
Owner/Operator Telephone Ext: Not reported

GENERAL THEOLOGICAL SEMINARY (Continued) **1001223855**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: GENERAL THEOLOGICAL SEMINARY
Legal Status: Private
Date Became Current: 19801231
Date Ended Current: Not reported
Owner/Operator Address: 175 9TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 914-654-8800
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: GENERAL THEOLOGICAL SEMINARY
Legal Status: Private
Date Became Current: 19801231
Date Ended Current: Not reported
Owner/Operator Address: 175 9TH AVE - CHELSEA #2 3 4
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 914-654-8800
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: GENERAL THEOLOGICAL SEMINARY
Legal Status: Private
Date Became Current: 19801231
Date Ended Current: Not reported
Owner/Operator Address: 175 9TH AVE - CHELSEA #2 3 4
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 914-654-8800
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: GENERAL THEOLOGIEAL SEMINARY
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: GENERAL THEOLOGICAL SEMINARY
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY

GENERAL THEOLOGICAL SEMINARY (Continued) **1001223855**

Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19980218
Handler Name: GENERAL THEOLOGICAL SEMINAR THE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20030522
Handler Name: GENERAL THEOLOGIEAL SEMINARY
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20030808
Handler Name: GENERAL THEOLOGIEAL SEMINARY
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56291
NAICS Description: REMEDIATION SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

GENERAL THEOLOGICAL SEMINARY (Continued) **1001223855**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004540523

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001223855
Registry ID:	110004540523
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004540523
Name:	GENERAL THEOLOGIEAL SEMINARY
Address:	175 9TH AVE - CHELSEA #2 3 4
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	GENERAL THEOLOGICAL SEMINARY
Address:	175 9TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYR000050716
Facility Status:	Not reported
Location Address 1:	175 9TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000050716
Mailing Name:	GENERAL THEOLOGICAL SEMINARY
Mailing Contact:	FREDDIE HORNEDO
Mailing Address 1:	175 9TH AVE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2122935150

GENERAL THEOLOGICAL SEMINARY (Continued) **1001223855**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NY0000148163
Trans2 State ID:	Not reported
Generator Ship Date:	12/07/2006
Trans1 Recv Date:	12/07/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/08/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000050716
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	000283128FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	225
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

G116 **CON EDISON - MANHOLE MH3224** **NY MANIFEST** **S121968654**
NW **447 W 18TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.036 mi.
189 ft. **Site 7 of 8 in cluster G**

Relative: **Lower**

Actual: **12 ft.**

NY MANIFEST:

Name:	CON EDISON - MANHOLE MH3224
Address:	447 W 18TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP005138595
Facility Status:	Not reported
Location Address 1:	447 W 18TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005138595
Mailing Name:	CON EDISON - MANHOLE MH3224
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

G117 **CON EDISON - MANHOLE MH3224** **RCRA-LQG** **1024891721**
NW **447 W 18TH ST** **NYP005138595**
< 1/8 **NEW YORK, NY 10011**
0.036 mi.
189 ft. **Site 8 of 8 in cluster G**

Relative: **Lower**

Actual: **12 ft.**

RCRA-LQG:

Date Form Received by Agency:	20180410
Handler Name:	CON EDISON - MANHOLE MH3224
Handler Address:	447 W 18TH ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP005138595
Contact Name:	ALYSSA SOTTO
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017

CON EDISON - MANHOLE MH3224 (Continued) **1024891721**

Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

CON EDISON - MANHOLE MH3224 (Continued) **1024891721**

Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20170911
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-460-2757
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20170911
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-460-2757
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20180410
Handler Name:	CON EDISON - MANHOLE MH3224
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No

CON EDISON - MANHOLE MH3224 (Continued) **1024891721**

Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

B118 **SPILL NUMBER 0013164** **NY Spills** **S104951519**
East **364 WEST 19TH ST** **N/A**
< 1/8 **NEW YORK, NY**
0.036 mi.
191 ft. **Site 30 of 33 in cluster B**

Relative:
Higher

Actual:
16 ft.

SPILLS:

Name:	SPILL NUMBER 0013164
Address:	364 WEST 19TH ST
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0013164 / 2003-06-09
Facility ID:	0013164
Facility Type:	ER
DER Facility ID:	150851
Site ID:	179743
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3101
Spill Date:	2001-03-16
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2001-03-16
CID:	405
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-03-16
Spill Record Last Update:	2003-06-09
Spiller Name:	Not reported
Spiller Company:	ABC PROPERTY
Spiller Address:	152 WEST 57TH ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND administrative closure"
Remarks:	"have a spill crew enroute will clean entire area"

SPILL NUMBER 0013164 (Continued) **S104951519**

All Materials:

Site ID:	179743
Operable Unit ID:	835093
Operable Unit:	01
Material ID:	539891
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B119 **365 WEST 20TH STREET** **NY AST** **U003386255**
ENE **365 WEST 20TH ST.** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.037 mi.
195 ft. **Site 31 of 33 in cluster B**

Relative:
Higher

Actual:
16 ft.

AST:

Name:	365 WEST 20TH STREET
Address:	365 WEST 20TH ST.
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-206644
Program Type:	PBS
UTM X:	584225.54410
UTM Y:	4510884.67307
Expiration Date:	08/24/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	7293
Affiliation Type:	Facility Owner
Company Name:	365 W. 20 OWNERS CORP.
Contact Type:	AGENT
Contact Name:	FRANK YAN
Address1:	50 WEST 17TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 896-8600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-09-13

Site Id:	7293
Affiliation Type:	Facility Operator
Company Name:	365 WEST 20TH STREET
Contact Type:	Not reported
Contact Name:	CARLOS CAJAMARCAS 917-207-8160

365 WEST 20TH STREET (Continued) **U003386255**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 896-8600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-09-13

Site Id:	7293
Affiliation Type:	Emergency Contact
Company Name:	365 W. 20 OWNERS CORP.
Contact Type:	Not reported
Contact Name:	JESSICA TUSING
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 896-8600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-09-13

Site Id:	7293
Affiliation Type:	Mail Contact
Company Name:	ARGO REAL ESTATE
Contact Type:	Not reported
Contact Name:	JESSICA TUSING
Address1:	50 W 17TH ST
Address2:	Not reported
City:	BROOKLYN,
State:	NY
Zip Code:	11224
Country Code:	001
Phone:	(212)896-8600
EMail:	COMPLIANCE@ARGO.COM
Fax Number:	Not reported
Modified By:	TLYE
Date Last Modified:	2018-02-22

Tank Info:

Tank Number:	001
Tank Id:	9541
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

J05 - Dispenser - On Site Heating System (Supply/Return)
F00 - Pipe External Protection - None

365 WEST 20TH STREET (Continued) **U003386255**

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
G02 - Tank Secondary Containment - Vault (w/access)
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/15/2001
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DAFRANCI
Last Modified:	10/19/2017
Material Name:	#2 fuel oil (on-site consumption)

I120 **LOT 63,TAXBLOCK 715** **NY E DESIGNATION** **S108076995**
WNW **128 10 AVENUE** **N/A**
< 1/8 **MANHATTAN, NY**
0.038 mi.
201 ft. **Site 1 of 22 in cluster I**

Relative: **Lower**
Actual: **11 ft.**

E DESIGNATION:

Name:	LOT 63,TAXBLOCK 715
Address:	128 10 AVENUE
City,State,Zip:	MANHATTAN, NY
Tax Lot(s):	63
Tax Block:	715
Borough Code:	Not reported
E-No:	E-142
Effective Date:	6/23/2005
Satisfaction Date:	Not reported
Ceqr Number:	03DCP069M
Ulurp Number:	050161 ZRM
Zoning Map No:	8b
Description:	Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date:	Not reported
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

F121 **SP 364 W 18 LLC** **NY AST** **U003388117**
ESE **364 WEST 18TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.039 mi.
205 ft. **Site 9 of 20 in cluster F**

Relative:
Higher

Actual:
16 ft.

AST:

Name:	SP 364 W 18 LLC
Address:	364 WEST 18TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-256552
Program Type:	PBS
UTM X:	584148.44360
UTM Y:	4510733.84626
Expiration Date:	02/14/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	10537
Affiliation Type:	Facility Operator
Company Name:	SP 364 W 18 LLC
Contact Type:	Not reported
Contact Name:	MICHAEL BONILLA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 937-2508
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-05-24

Site Id:	10537
Affiliation Type:	Emergency Contact
Company Name:	SP 364 W 18 LLC
Contact Type:	Not reported
Contact Name:	JOSE LOPEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 937-2505
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-05-24

Site Id:	10537
Affiliation Type:	Mail Contact
Company Name:	STONEHENGE MANAGEMENT
Contact Type:	Not reported
Contact Name:	ADAM GRUSHKO

SP 364 W 18 LLC (Continued) **U003388117**

Address1:	888 SEVENTH AVENUE
Address2:	3RD FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10106
Country Code:	001
Phone:	(646) 878-2091
EMail:	AGRUSHKO@STONEHENGENYC.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-05-24

Site Id:	10537
Affiliation Type:	Facility Owner
Company Name:	SP 364 W 18 LLC
Contact Type:	VP BUILDING OPERATION
Contact Name:	ADAM GRUSHKO
Address1:	888 SEVENTH AVE. STONEHENGE MGMT. LLC
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10106
Country Code:	001
Phone:	(212) 977-5000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-05-24

Tank Info:

Tank Number:	001
Tank Id:	13188
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

	L09 - Piping Leak Detection - Exempt Suction Piping
	E00 - Piping Secondary Containment - None
	H00 - Tank Leak Detection - None
	J02 - Dispenser - Suction Dispenser
	G00 - Tank Secondary Containment - None
	I04 - Overfill - Product Level Gauge (A/G)
	C01 - Pipe Location - Aboveground
	K00 - Spill Prevention - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	A00 - Tank Internal Protection - None
	F00 - Pipe External Protection - None
	B00 - Tank External Protection - None
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/1940
Capacity Gallons:	4000

SP 364 W 18 LLC (Continued) **U003388117**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/25/2013
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)
Tank Number:	002
Tank Id:	248209
Equipment Records:	G01 - Tank Secondary Containment - Diking (Aboveground) H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G) L09 - Piping Leak Detection - Exempt Suction Piping E00 - Piping Secondary Containment - None I02 - Overfill - High Level Alarm J02 - Dispenser - Suction Dispenser C01 - Pipe Location - Aboveground K00 - Spill Prevention - None A00 - Tank Internal Protection - None B01 - Tank External Protection - Painted/Asphalt Coating D01 - Pipe Type - Steel/Carbon Steel/Iron F00 - Pipe External Protection - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/25/2013
Capacity Gallons:	2500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	05/24/2017
Material Name:	#2 fuel oil (on-site consumption)

F122 **LAWRENCE ENVIRONMENTAL GROUP LLC** **NY LTANKS** **S109828460**
ESE **364 WEST 18TH STREET** **NY Spills** **N/A**
< 1/8 **MANHATTAN, NY**
0.039 mi.
205 ft. **Site 10 of 20 in cluster F**

Relative: **Higher**
Actual: **16 ft.**

LTANKS:

Name:	LAWRENCE ENVIRONMENTAL GROUP LLC
Address:	364 WEST 18TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	1107687 / 2011-10-31
Facility ID:	1107687
Site ID:	455396
Spill Date:	2011-09-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial

LAWRENCE ENVIRONMENTAL GROUP LLC (Continued) **S109828460**

Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2011-09-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-09-16
Spill Record Last Update:	2011-10-31
Spiller Name:	Not reported
Spiller Company:	UNKNOWN AT THIS TIME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	SCOTT SMITH
Spiller Phone:	(212) 682-2001
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	409967
DEC Memo:	"09/19/11-Hiralkumar Patel. 2:49 PM:- left message for Greg at GC Environmental. 2:52 PM:- spoke with Scott at Lawrence Environmental and Greg at GC Environmental. GC environmental performed a tightness test as part of potential property sale. site has one 4,000 gal #6 oil AST which is about 10% underground. supply/return lines runs aboveground in building. fill line runs underground below the sidewalk and then runs aboveground in the building. during test, Greg observed a tell-tale line from tank, but they could not find other open end of tell-tale line. Scott Smith Lawrence Environmental Group LLC. Ph. (212) 682-2001 09/21/11-Hiralkumar Patel. 1:51 PM:- left message for Scott. 2:29 PM:- received message from Scott. 09/23/11-Hiralkumar Patel. 12:53 PM:- spoke with Scott. he mentioned that Lawrence environmental was hired by James Bush. he asked to contact James for property owner's contact information. 1:03 PM:- left message for James. James Bush Ph. (212) 977-5000 09/23/11-Hiralkumar Patel. 11:31 AM:- spoke with James. James mentioned that his company is planning to buy this property and they are dealing with broker. as part of possible property transcation, they did Phase I report and found some issues. so they hired Lawrence environmental, who did soil borings and tank test. James asked to contact Paul at Eastern Consolidated. Paul Nigido **broker** Eastern Consolidated Ph. (212) 499-7700 alternate addresses: 364-370 W 18th Street, 112-126 9th Ave PBS #: 2-256552. as per PBS record, site has one 4,000 gal #6 oil AST in contact with soil. tank was installed in Apr. 1940. other spill: 0905371. spill was reported by tenant due to petroleum odors in building. DEC Vought inspected site and found no problem. case closed. 1:07 PM:- spoke with Ben Haghani, property owner. informed him about tank test failure. he mentioned that they already corrected the problem. he doesn't know much but will send update after talking to person who is handling this issue. FRG 9th Avenue LLC. **property owner** 380 Madison Avenue, Suite 2401 New York, NY 10017 Attn.: Ben Haghani Ph. (212) 922-1220 Ext. 303 email:

LAWRENCE ENVIRONMENTAL GROUP LLC (Continued) **S109828460**

ben@fortunarealtygroup.com 1:47 PM:- sent TTF to Mr. Haghani. letter emailed to Mr. Haghani. case assigned to DEC Falvey. 10/13/11-Hiralkumar Patel. 3:42 PM:- received call from Mark Cherchio (212-922-1220 Ext. 303) from management. he mentioned that the tank failed the tightness test because of old tell-tale line. they have cut that line and now system is tight. asked Mark to submit letter from contractor confirming reason for tank test failure and passing test result. 10/31/11-Hiralkumar Patel. received letter report from Mr. Cherchio including tank test results. based on submitted information, case closed."

Remarks: "1555 THE CALLER ADVISED DISPATCH OF A TANK TEST FAILURE. FAILURE IS UNDER INVESTIGATION."

All Materials:

Site ID:	455396
Operable Unit ID:	1205545
Operable Unit:	01
Material ID:	2202397
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Name:	REM RESIDENTIAL APARTMENTS
Address:	364 WEST 18TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0905371 / 2009-08-10
Facility ID:	0905371
Facility Type:	ER
DER Facility ID:	366781
Site ID:	417633
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	D6
SWIS:	3101
Spill Date:	2009-08-07
Investigator:	jbvought
Referred To:	Not reported
Reported to Dept:	2009-08-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-08-07
Spill Record Last Update:	2009-11-17

LAWRENCE ENVIRONMENTAL GROUP LLC (Continued) **S109828460**

Spiller Name: Not reported
Spiller Company: REM RESIDENTIAL
Spiller Address: Not reported
Spiller Company: 999
Contact Name: RICK ELEZI
DEC Memo: "08/10/09-Vought-Off hours responder. DEC Ahmed (primary off hours responder called caller Rick Elezi (212-260-8060) who was contact for REM Residential (management company for building) and left message to return call immediately. Due to no call back Vought responded to site and called and left second urgent message for emergency hotline at REM Residential (left message with Victoria). Onsite Vought met with building super Jose Lopez (ph:914-490-0806) who when informed of the odor complaint, immediately referred that the call most likely came from Apt 3K (Rick) who was repeatedly calling various city agencies with numerous complaints. Lopez also mentioned that Rick was in current litigation with landlords of building. Vought noticed no odors in lobby of building. Vought inspected basement and found minor spill (12 patch of stained concrete) by oil burners and noted speedy dry was already applied to spill. No odors in basement. Also no observable spills or odors in secondary containment room of 4000-gallon #2 fuel oil AST (registered as in contact with soil). Spill closed by Vought due to no odors, very minor spill on concrete. 11/16/09-Vought-Received call from Richard Saler(917-414-7379) who was inquiring as to status of above spill. Rick mentioned numerous toxic hazards to his building including illegal venting from new sandwich shop, mold, fire hazard from stored oil and adjacent electrical supply (note that fuel oil has very high flashpoint and presents minor explosion hazards). Rick noted that three large of drums of oil were formerly stored in a room with a half door and there was a large oil spill there and suggested that Vought missed room during last site visit. Rick also mentioned that NYCDOH was onsite but would not provide Vought contact information for NYCDOH representative despite repeated requests and said that he would only provide it to Vought if additional site visit was performed. Vought discussed that if source of initial complaint was known than Department would have responded immediately back in August to have NYCDOH site visit to ensure health and safety of residents. Rick mentioned that he was made report to NYC Department of Investigations due to his lack of satisfaction with NYCDOH. Vought informed DEC Austin of second complaint. Rick will send pictures to Vought with spill and stated that door was closed at time of DEC Site visit. Vought arranged site visit for 11/17 at 10am during which NYCDEP rep would be onsite also arranged by Rick. Rick mentioned that there were presently no odors in his apartment. Vought called Jose and informed him of DEC site visit and requested that he leave room with half door open. Jose noted that room with half door was room that Vought inspected on 8/10/09. 11/17/09-Vought-Site visit by Vought with Richard and NYCDOH Eric Joseph (212-442-3372)from unit of P. Stallbohm. Joseph indicated that this was his second time responding to site and meeting with Richard. Richard indicated that building was being impacted by food odors from Subway sandwich shop. NYCDOH Joseph inspected Subway sandwich shop and inquired as to ventilation system. No sources of petroleum in Subway Sandwich shop. Vought requested to inspect residence of Richard for vapors and Richard declined request and said that there were no petroleum odors in his apartment . Vought inquired as to pictures of spill he said yesterday he had and he stated that he could not find them . Vought noted no odors in hallway

LAWRENCE ENVIRONMENTAL GROUP LLC (Continued) **S109828460**

of building or in basement hallway. Vought requested that Richard show Vought specific room where spill was because he stated Vought missed room on last inspection. Vought inspected room with Richard and NYCDOH Joseph and room was same room that was subject of inspection (and 12 oil stain on poured concrete floor) as last site visit on 8/7/09. No additional signs of spillage from last site visit and no petroleum vapors. NYCDOH Joseph confirmed that during his prior visit he performed PID survey of basement and found no odors. No additional cracks or routes of entry to subsurface. Vought explained results of inspection to Richard and spill will remain closed. See edocs for photos of site visit. "

Remarks: "caller lives at this address...claims that there are open containers of what looks like oil in the basement of building, containers have overflowed onto the basement floor...Odor of petro in apartment"

All Materials:

Site ID:	417633
Operable Unit ID:	1173849
Operable Unit:	01
Material ID:	2165907
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	417633
Operable Unit ID:	1173849
Operable Unit:	01
Material ID:	2165908
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	417633
Operable Unit ID:	1173849
Operable Unit:	01
Material ID:	2165906
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

I123 **CON EDISON MANHOLE: 57308** **RCRA NonGen / NLR** **1016142986**
WNW **116 10TH AVE** **NY MANIFEST** **NYP004257150**
< 1/8 **NEW YORK, NY 10014**
0.040 mi.
209 ft. **Site 2 of 22 in cluster I**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130320
Handler Name:	CON EDISON MANHOLE: 57308
Handler Address:	116 10TH AVE
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYP004257150
Contact Name:	JUAN RODRIGUEZ
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	347-865-5931
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON MANHOLE: 57308 (Continued) **1016142986**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130220
Handler Name:	CON EDISON MANHOLE: 57308
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130320
Handler Name:	CON EDISON MANHOLE: 57308
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON MANHOLE: 57308 (Continued) **1016142986**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 116 10TH AVE
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYP004257150
Facility Status: Not reported
Location Address 1: 116 10TH AVE
Code: BP
Location Address 2: MH 57308
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004257150
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 02/20/2013
Trans1 Recv Date: 02/20/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/20/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004257150

CON EDISON MANHOLE: 57308 (Continued) **1016142986**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010846487JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

I124 **LOT 2,TAXBLOCK 715** **NY E DESIGNATION** **S108076882**
WNW **116 10 AVENUE** **N/A**
< 1/8 **MANHATTAN, NY**
0.040 mi.
209 ft. **Site 3 of 22 in cluster I**

Relative: **Lower**
Actual: **11 ft.**

E DESIGNATION:

Name:	LOT 2,TAXBLOCK 715
Address:	116 10 AVENUE
City,State,Zip:	MANHATTAN, NY
Tax Lot(s):	2
Tax Block:	715
Borough Code:	Not reported
E-No:	E-142
Effective Date:	6/23/2005
Satisfaction Date:	Not reported
Ceqr Number:	03DCP069M
Ulurp Number:	050161 ZRM
Zoning Map No:	8b
Description:	Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date:	Not reported

LOT 2,TAXBLOCK 715 (Continued) **S108076882**

Description: Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

I125 **118 10TH AVENUE** **NY VCP** **S127094518**
WNW **118 10TH AVENUE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.040 mi.
209 ft. **Site 4 of 22 in cluster I**

Relative:
Lower

Actual:
11 ft.

VCP NYC:
Project ID: 18TMP1257M,18EHAN428M,21CVCP027M
Name: 118 10TH AVENUE
Address: 118 10TH AVENUE
City,State,Zip: NEW YORK CITY, NY
Borough: Manhattan
BBL: 1.00715000210071E+29
OER Program: VCP (Enrolled), E/RD (Review)
Phase: Approved Remedial Plan
Latitude: 40.744261
Longitude: -74.006651
Postcode: 4
Community Board: 3
Council District: 83
Census Tract: 1012547
BIN: 1007150003
NTA: Hudson Yards-Chelsea-Flatiron-Union Square

I126 **LOT 3,TAXBLOCK 715** **NY E DESIGNATION** **S108076906**
WNW **118 10 AVENUE** **N/A**
< 1/8 **MANHATTAN, NY**
0.040 mi.
209 ft. **Site 5 of 22 in cluster I**

Relative:
Lower

Actual:
11 ft.

E DESIGNATION:
Name: LOT 3,TAXBLOCK 715
Address: 118 10 AVENUE
City,State,Zip: MANHATTAN, NY
Tax Lot(s): 3
Tax Block: 715
Borough Code: Not reported
E-No: E-142
Effective Date: 6/23/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP069M
Ulurp Number: 050161 ZRM
Zoning Map No: 8b

Description: Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date: Not reported

Description: Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date: Not reported

LOT 3,TAXBLOCK 715 (Continued) **S108076906**

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

F127 **CON EDISON** **NY MANIFEST** **S117067459**
ESE **FO 362 W 18 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.040 mi.
210 ft. **Site 11 of 20 in cluster F**

Relative:
Higher

Actual:
16 ft.

NY MANIFEST:
Name: CON EDISON
Address: FO 362 W 18 ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004603262
Facility Status: Not reported
Location Address 1: FO 362 W 18 ST
Code: BP
Location Address 2: SB 3247
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004603262
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/22/2014
Trans1 Recv Date: 07/22/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/25/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004603262
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002504412GBF
Import Indicator: N

CON EDISON (Continued) **S117067459**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J128 **CON EDISON** **RCRA NonGen / NLR** **1025504635**
South **74 9TH AVE** **NYP005241369**
< 1/8 **NEW YORK, NY 10011**
0.040 mi.
211 ft. **Site 1 of 35 in cluster J**

Relative: **Higher**
Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20200413
Handler Name:	CON EDISON	
Handler Address:		74 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP005241369
Contact Name:		Not reported
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2

CON EDISON (Continued) **1025504635**

Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200413
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

CON EDISON (Continued) **1025504635**

Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20181003
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20200413
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

F129 **CON EDISON SERVICE BOX 3007** **RCRA NonGen / NLR** **1014918661**
SE **357 W 17TH ST** **NJ MANIFEST** **NYP004222774**
< 1/8 **NEW YORK, NY 10011** **NY MANIFEST**
0.040 mi.
213 ft. **Site 12 of 20 in cluster F**

Relative: **Higher**
Actual: **16 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20110131
Handler Name: CON EDISON SERVICE BOX 3007
Handler Address: 357 W 17TH ST
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYP004222774
Contact Name: JUAN RODRIGUEZ

CON EDISON SERVICE BOX 3007 (Continued) **1014918661**

Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	347-865-5931
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking

CON EDISON SERVICE BOX 3007 (Continued) **1014918661**

Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20110701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20110101
Handler Name:	CON EDISON SERVICE BOX 3007
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20110131
Handler Name:	CON EDISON SERVICE BOX 3007
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

CON EDISON SERVICE BOX 3007 (Continued) **1014918661**

Evaluations: No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004222774
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JUAN RODRIGUEZ
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001128792GBF
EPA ID:	NYP004222774
Date Shipped:	1/1/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	NJD003812047
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON SERVICE BOX 3007 (Continued) **1014918661**

Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H141
Quantity: 400.00 Pounds

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 357 W 17TH ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004222774
Facility Status: Not reported
Location Address 1: FRONT OF 357 WEST 17th STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10023
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004222774
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 01/01/2011
Trans1 Recv Date: 01/01/2011
Trans2 Recv Date: 01/04/2011
TSD Site Recv Date: 01/04/2011
Part A Recv Date: Not reported
Part B Recv Date: Not reported

CON EDISON SERVICE BOX 3007 (Continued) **1014918661**

Generator EPA ID:	NYP004222774
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	001128792GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

I130 **LOT 64,TAXBLOCK 715** **NY E DESIGNATION** **S108076997**
WNW **124 10 AVENUE** **N/A**
< 1/8 **MANHATTAN, NY**
0.040 mi.
213 ft. **Site 6 of 22 in cluster I**

Relative: **Lower**
Actual: **11 ft.**

E DESIGNATION:

Name:	LOT 64,TAXBLOCK 715
Address:	124 10 AVENUE
City,State,Zip:	MANHATTAN, NY
Tax Lot(s):	64
Tax Block:	715
Borough Code:	Not reported
E-No:	E-142
Effective Date:	6/23/2005
Satisfaction Date:	Not reported
Ceqr Number:	03DCP069M
Ulurp Number:	050161 ZRM
Zoning Map No:	8b
Description:	Air Quality - HVAC fuel limited to natural gas

LOT 64,TAXBLOCK 715 (Continued) **S108076997**

Lot Remediation Date: Not reported

Description: Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

F131 **CON EDISON** **NY MANIFEST** **S117058302**
SSE **364 W 17 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.041 mi.
217 ft. **Site 13 of 20 in cluster F**

Relative:
Higher

Actual:
16 ft.

NY MANIFEST:
Name: CON EDISON
Address: 364 W 17 ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004503371
Facility Status: Not reported
Location Address 1: 364 W 17 ST
Code: BP
Location Address 2: SB3017
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004503371
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/17/2014
Trans1 Recv Date: 04/17/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/23/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004503371
Trans1 EPA ID: Not reported

CON EDISON (Continued) **S117058302**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694212JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J132 **VERIZON** **RCRA NonGen / NLR** **1014917901**
SSW **75 9TH AVE** **NJ MANIFEST** **NYP000967695**
< 1/8 **NEW YORK, NY 10011**
0.041 mi.
217 ft. **Site 2 of 35 in cluster J**

Relative: RCRA NonGen / NLR:
Higher

Date Form Received by Agency:		20110930
Handler Name:	VERIZON	
Handler Address:		75 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP000967695
Contact Name:		JOHN QUATRALE
Contact Address:		N OCEAN AVE BASEMENT
Contact City,State,Zip:		PATCHOGUE, NY 11772
Contact Telephone:		631-475-3450
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		MGR
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported

Actual:
15 ft.

VERIZON (Continued) **1014917901**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	N OCEAN AVE -BASEMENT
Mailing City,State,Zip:	PATCHOGUE, NY 11772
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No

VERIZON (Continued) **1014917901**

Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170505
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20110915
Handler Name: VERIZON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20110930
Handler Name: VERIZON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP000967695
Mail Address:	N OCEAN AVE BASEMENT
Mail City/State/Zip:	PATCHOGUE, NY 11772
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JOHN QUATRALE

VERIZON (Continued) **1014917901**

Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	000896002GBF
EPA ID:	NYP000967695
Date Shipped:	8/29/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	PATCHOGUE, NY 11772
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	300.00 Pounds

VERIZON (Continued) **1014917901**

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	50.00 Pounds

J133 **OXYGEN MEDIA** **NY Spills** **S117851371**
SSW **75 9TH AVENUE** **NY MANIFEST** **N/A**
< 1/8 **NEW YORK, NY 10011** **NY COOLING TOWERS**
0.041 mi.
217 ft. **Site 3 of 35 in cluster J**

Relative:
Higher

Actual:
15 ft.

SPILLS:

Name:	CHELSEA MARKET
Address:	75 9TH AVE
City,State,Zip:	MANHATTAN, NY 10011
Spill Number/Closed Date:	1411925 / Not Reported
Facility ID:	1411925
Facility Type:	ER
DER Facility ID:	460545
Site ID:	505730
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2015-03-20
Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	2015-03-20
CID:	Not reported
Water Affected:	GROUND WATER
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2015-03-20
Spill Record Last Update:	2021-06-15
Spiller Name:	RYAN TUNSTALL
Spiller Company:	CHELSEA MARKET
Spiller Address:	75 9TH AVE
Spiller Company:	999
Contact Name:	KARYN MARSH
DEC Memo:	"3/20/15- Ahmed - Spoke to Karyn marsh (202 887 3679). Her client is renovating the basement. During the renovation they found 4 vaulted above ground tanks. they retained environmental consultant, Partner Engineering and Science to do investigation. They collected soil samples and received the results. asked her to email me the sample results. Assigned it to Mahat for follow up. 3/27/15: Mahat DEC Mahat leaft a voice message to Ms. Marsh to call back for a touch base. 6/1/15: Mahat DEC Mahat received an email from Mr. Karyn B. Marsh: Dear Santosh, As we discussed on Friday, please find the Draft Remedial Investigation Report, prepared by Partner Engineering and

OXYGEN MEDIA (Continued) **S117851371**

Science (April 2015) attached. The Draft RIR was recently prepared by the consultant who has been investigating the basement contamination and includes a description of the circumstances leading up to the discovery of the soil staining and abandoned tanks, the investigation procedures and protocol, findings and recommendations for addressing the contamination, as well as the laboratory reports. I will also send you the Phase I Environmental Site Assessment for Chelsea Market, 75 Ninth Avenue, prepared by ATC (2011). The Phase I ESA discusses the property s use history, among other things. However, it is 17 MB and after attempting to send both these files to you, I received a message from the post master stating that the email was too large. I will explore options for reducing the file size. I may need to send it in pieces. Please let me know if you have any questions regarding the attached or need further information. After you have reviewed the attached, feel free to contact me to set up a site visit. Thank you, Karyn B. Marsh GIBSON DUNN Gibson, Dunn & Crutcher LLP 1050 Connecticut Avenue, N.W., Washington, DC 20036-5306 Tel +1 202.887.3679 " Fax +1 202.530.9544 KMarsh@gibsondunn.com " www.gibsondunn.com RIR Final Draft has been uploaded on D2 for reference. 8/21/15: Mahat e/c: RAP has been submitted to the Department. It has been uploaded to D2 for reference. DEC Mahat will get back to the contractor once the review is done. 9/15/15: Mahat RAP has been approved. DEC Mahat is waiting for a final report for the closure of the spill case. 12/2/15: Mahat A letter approving RAP has been sent to the property owner and retained contractor. It has been uploaded on D2 for reference. 9/12/2016 - V. Brevdo Spill Case is transferred from Spill Prevention and Response to Remediation Section B due to project manager Santosh Mahat departure to the other DEC Program, as per 9/9/16 discussion between Randall Austin and Vadim Brevdo. VB 9/13/2016 Transferred to Alex Zhitomirsky, as per Vadim Brevdo. 6/26/2018 I have contacted Chris Batista (Roux ph.516-250-0382). The site was sold to a new owner a few months ago. A recovery system was restarted about two weeks ago. It doesn't recover any product. Roux will submit a Summary Report and a Work Plan. AZ+ 9-20-2018 Contacted Chris Batista. The recovery system is not recovering any product for about ten months. No free-phase product is encountered by the existing wells. Oil is seeping through the walls of the building into the pit between the two vaults. Minor amount of oil seeping through the bottom of the wall in the boiler room. Roux proposed to advance four soil borings near the tank vaults. I have reviewed the Site Status update report, dated August 28, 2018. The report proposed advancement of four borings and installation of test pits. Roux also proposed opening the sidewalk and top slab above each vault to expose the vault contents and to complete test pits/cores within the vaults. I requested the following; 1. All borings must be finished as wells 2. Two soil samples should taken and analyzed from each boring. One soil sample should be collected from each test pit. 3. Groundwater samples should be taken from all wells. 4. All soil and groundwater samples should be analyzed for VOCs and SVOCs A revised Work Plan should be submitted to DEC for approval. Also, instead of well installation Roux might first open the vaults and investigate using the test pits. They will try to expose the top of the tanks. There are presumably four tanks. AZ 10-15-2018 Conference call with Chis Batista (Roux) and John Soden (Taconic, owner's managing company ph. 212-243-5060). According to Roux, neither recovery system nor recovery wells are recovering any product. There are currently two recovery wells, a

OXYGEN MEDIA (Continued) **S117851371**

sump pump and a monitoring well at the site. The tanks are old tanks, probably belonged to Nabisco. The tanks were not used for years. Probably, in 2015 product was evacuated from the tanks. The tanks are not registered and not closed. Roux doesn't know the location of the piping and fill ports. Roux plans to open the sidewalks and investigate the tanks. GWT is about 15-20' bgs, about 4' below the tank slab. Roux will submit a report summarizing the findings and the investigation plan. The owner will register the tanks. AZ 12-17-2019: An email from Roux: Alex, We had discussed this project a last year and have since been working on a strategy to remove the USTs from beneath the Sidewalk and clean out the vaults the USTs are contained within. The project is extremely difficult due to the logistics and layers of concrete, etc. overlying the USTs. It has been a complicated process to evaluate the situation and select a contractor to perform the work. The attached document details our plans to remove these USTs and clean the vaults, etc. I am also sending you a paper copy via Fed Ex. Based on the timing for acquiring permits from NYC DOT and NYC DOB, we anticipate starting this work around March 2020. We will notify you and NYSDEC PBS at least 30 days in advance. Can you please review the attached summary and let us know if you have any questions, concerns or objections to this work proceeding. Please feel free to contact me any time via phone, cell or email to discuss. Thanks, Chris. Christopher Battista, P.G. NY - Senior Construction Manager 209 Shafter Street - Islandia, New York 11749 Main: (631) 232-2600 - Direct: (631) 630-2391 - Mobile: (516) 250-0382 Email: cbattista@rouxinc.com - Website: http://www.rouxinc.com 2-4-2020 I have reviewed a proposed UST Removal Work Plan dated 12-16-2019. As part of the former bakery operations, four underground storage tanks (USTs) were used to store heating oil (likely used historically for heating the bakery ovens) and are located in concrete vaults below the north sidewalk of West 15th Street immediately adjacent to the Site. Roux recommends cleaning and removing the USTs and cleaning the inside of the tank vaults. The utility pit located between the UST vaults will also be steam cleaned, as necessary. All piping and injection lines running through the current boiler room will also be removed and disposed. Three, four-inch diameter holes will be cored through the floor slab of each vault for collection of soil samples. Samples will be collected from the zero to one-foot interval immediately below the vault slab. I have contacted Chris Batista, Roux, and asked him to include in the report tank registration information. I also requested that Roux attempts to collect samples down to groundwater level, locate and, if feasible, excavate the fill ports and associated piping. Roux will revise the report and send it back to DEC. AZ 2-21-2020 The following e-mail was sent to C. Batista and V. Brevdo: Dear Chris, I have reviewed the revised Site Status Update and Proposed UST Removal Work Plan received on February 20, 2020. I concur with this plan. The Responsible Party and its contractors are solely responsible for the safe execution of all invasive work performed at the site, and in particular, are responsible for identifying subsurface utilities and safeguarding the structural integrity of any excavations, buildings, utilities, and other structures both on- and off-site that may be adversely affected by the work. The Responsible Party and its contractors must obtain any local, state or federal permits or approvals that may be required to perform the work necessary to address this spill. Furthermore, the Responsible Party and its contractors are solely responsible for the

OXYGEN MEDIA (Continued) **S117851371**

implementation of all appropriate health and safety measures during the performance of this work. Sincerely, Alex Zhitomirsky 10-26-2020 The following email was received from Christopher Battista (cbattista@rouxinc.com): Alex, We hope that you, your collegues and your families are well. We wanted to update you regarding this Site. Jones Lang Lasalle has taken over as the Property Manager for the Chelsea Market Site. The Market was essentially closed for much of 2020 Due to the COVID-19 Pandemic. The Market has reopened, with restrictions and outdoor dining is now established on the Sidewalk of West 15th Street. Obviously, the pandemic has had a very significant impact on the Market and its tenants. The Owner still intends to move forward with the UST removal and vault cleaning work, but the work will likely occur in the First Quarter of 2022 when/if unrestricted operations of the tenants resume and the work can be performed with less significant additional impacts on their businesses. Please feel free to contact me anytime, if you have any questions. Thanks, Chris. 6-15-2021 The following email was sent to Chris Battista (Christopher Battista cbattista@rouxinc.com):Re: Spill No. 1411925 - Chelsea Market Site - 75 Ninth Avenue, New York, New York Zhitomirsky, Alexander (DEC) Tue 6/15/2021 8:35 AM Chris, Could you provide me with the mailing address for the current owner? I believe it is Taconic Management Company. Thank you, Alex Alexander Zhitomirsky Professional Geologist I, Division of Environmental Remediation"

Remarks: "Soil samples taken after the discovery of 4 tanks that were is a vault that no one knew about. Sample results received were about exceptable limits. Further investigation and cleanup is pending."

All Materials:

Site ID:	505730
Operable Unit ID:	1255037
Operable Unit:	01
Material ID:	2257725
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

NY MANIFEST:

Name:	OXYGEN MEDIA
Address:	75 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10011-0000
Country:	USA
EPA ID:	NYR000076299
Facility Status:	Not reported
Location Address 1:	75-9TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

OXYGEN MEDIA (Continued) **S117851371**

NY MANIFEST:

EPAID:	NYR000076299
Mailing Name:	OXYGEN MEDIA
Mailing Contact:	ERWIN COHEN
Mailing Address 1:	88 TENTH AVE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2122436005

COOLING TOWERS:

Name:	Not reported
Address:	75 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Equipment Unique ID:	13826
Equipment Borough:	Manhattan
Intended Use:	Refrigeration
Manufacturer:	Marley
Model:	MD5010NCFIL
Cooling Capacity:	225
Cooling Capacity Unit:	Tonnage
Commissioned Date:	10/01/2014
Inspection Date:	10/04/2019
Date of Bacteriological Collection:	10/23/2019
Date of Legionella Collection:	10/04/2019
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	40.742227
Longitude:	-74.004466

Name:	Not reported
Address:	75 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Equipment Unique ID:	13827
Equipment Borough:	Manhattan
Intended Use:	Refrigeration
Manufacturer:	Marley
Model:	NC8402QCN2GF
Cooling Capacity:	600
Cooling Capacity Unit:	Tonnage
Commissioned Date:	10/01/2016
Inspection Date:	10/04/2019
Date of Bacteriological Collection:	10/23/2019
Date of Legionella Collection:	10/04/2019
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	40.742227
Longitude:	-74.004466

Name:	Not reported
Address:	75 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Equipment Unique ID:	13822
Equipment Borough:	Manhattan

OXYGEN MEDIA (Continued) **S117851371**

Intended Use:	Air Conditioning
Manufacturer:	Marley
Model:	494G
Cooling Capacity:	50
Cooling Capacity Unit:	Tonnage
Commissioned Date:	10/01/2009
Inspection Date:	10/04/2019
Date of Bacteriological Collection:	10/23/2019
Date of Legionella Collection:	10/04/2019
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	40.742227
Longitude:	-74.004466

Name:	Not reported
Address:	75 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Equipment Unique ID:	13823
Equipment Borough:	Manhattan
Intended Use:	Air Conditioning
Manufacturer:	Marley
Model:	494G
Cooling Capacity:	50
Cooling Capacity Unit:	Tonnage
Commissioned Date:	10/01/2009
Inspection Date:	10/04/2019
Date of Bacteriological Collection:	10/23/2019
Date of Legionella Collection:	10/04/2019
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	40.742227
Longitude:	-74.004466

Name:	Not reported
Address:	75 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Equipment Unique ID:	13825
Equipment Borough:	Manhattan
Intended Use:	Refrigeration
Manufacturer:	Evapco
Model:	LRT5-68
Cooling Capacity:	75
Cooling Capacity Unit:	Tonnage
Commissioned Date:	10/01/2012
Inspection Date:	10/04/2019
Date of Bacteriological Collection:	10/23/2019
Date of Legionella Collection:	10/04/2019
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	40.742227
Longitude:	-74.004466

Name:	Not reported
Address:	75 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Equipment Unique ID:	13824
Equipment Borough:	Manhattan
Intended Use:	Refrigeration
Manufacturer:	BAC
Model:	15201

OXYGEN MEDIA (Continued) **S117851371**

Cooling Capacity:	200
Cooling Capacity Unit:	Tonnage
Commissioned Date:	10/01/2012
Inspection Date:	10/04/2019
Date of Bacteriological Collection:	10/23/2019
Date of Legionella Collection:	10/04/2019
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	40.742227
Longitude:	-74.004466

J134 **CHELSEA MARKET** **NY AST** **U004081712**
SSW **75TH NINTH AVENUE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.041 mi.
217 ft. **Site 4 of 35 in cluster J**

Relative:
Higher

Actual:
15 ft.

AST:

Name:	CHELSEA MARKET
Address:	75TH NINTH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-216674
Program Type:	PBS
UTM X:	584024.62673
UTM Y:	4510582.96126
Expiration Date:	03/20/2023
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	8160
Affiliation Type:	Mail Contact
Company Name:	TACONIC MANAGEMENT COMPANY LLC
Contact Type:	Not reported
Contact Name:	MICHAEL DOUGHERTY
Address1:	111 EIGTH AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	1011
Country Code:	001
Phone:	(917) 275-5989
EMail:	MDOUGHERTY@111EIGHTH.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-01-04

Site Id:	8160
Affiliation Type:	Facility Operator
Company Name:	CHELSEA MARKET
Contact Type:	Not reported
Contact Name:	TACONIC MANAGEMENT COMPANY LLC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported

CHELSEA MARKET (Continued) **U004081712**

Country Code:	001
Phone:	(212) 652-2110
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-01-04

Site Id:	8160
Affiliation Type:	Emergency Contact
Company Name:	MANHATTAN CHELSEA MARKET LLC
Contact Type:	Not reported
Contact Name:	MICHAEL DOUGHERTY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 760-3386
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-01-04

Site Id:	8160
Affiliation Type:	Facility Owner
Company Name:	MANHATTAN CHELSEA MARKET LLC
Contact Type:	PROPERTY MANAGER
Contact Name:	MICHAEL DOUGHERTY
Address1:	1600 AMPHITHEATRE PARKWAY
Address2:	Not reported
City:	MOUNTAIN VIEW
State:	CA
Zip Code:	94043
Country Code:	001
Phone:	(646) 760-5386
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-01-04

Tank Info:

Tank Number:	001
Tank Id:	22403
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
L00 - Piping Leak Detection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J05 - Dispenser - On Site Heating System (Supply/Return)
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None

CHELSEA MARKET (Continued) **U004081712**

B00 - Tank External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1959
Capacity Gallons:	17000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/20/2015
Register:	True
Modified By:	MRBARROW
Last Modified:	04/20/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	22404
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
J05 - Dispenser - On Site Heating System (Supply/Return)
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
G10 - Tank Secondary Containment - Impervious Underlayment
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1959
Capacity Gallons:	17000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/20/2015
Register:	True
Modified By:	MRBARROW
Last Modified:	04/20/2017
Material Name:	#2 fuel oil (on-site consumption)

J135 **NBC UNIVERSAL INC - OXYGEN MEDIA** **RCRA-VSQG** **1012186248**
SSW **75 9TH AVE - 7TH FLOOR** **NYR000161091**
< 1/8 **NEW YORK, NY 10011**
0.041 mi.
217 ft. **Site 5 of 35 in cluster J**

Relative: RCRA-VSQG:
Higher

Date Form Received by Agency:	20081027
Handler Name:	NBC UNIVERSAL INC - OXYGEN MEDIA
Handler Address:	75 9TH AVE - 7TH FLOOR
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYR000161091
Contact Name:	ANNETTE VEGA
Contact Address:	9TH AVE - 7TH FLOOR
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	212-651-6264
Contact Fax:	Not reported
Contact Email:	ANNETT.VEGA@NBCUNI.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	9TH AVE - 7TH FLOOR
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	NBC UNIVERSAL INC
Owner Type:	Private
Operator Name:	NBC UNIVERSAL INC - OXYGEN MEDIA
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

Actual:
15 ft.

NBC UNIVERSAL INC - OXYGEN MEDIA (Continued) **1012186248**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D009
Waste Description:	MERCURY

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NBC UNIVERSAL INC
Legal Status:	Private
Date Became Current:	20071115
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator

NBC UNIVERSAL INC - OXYGEN MEDIA (Continued) **1012186248**

Owner/Operator Name:	NBC UNIVERSAL INC - OXYGEN MEDIA
Legal Status:	Private
Date Became Current:	20071115
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20081027
Handler Name:	NBC UNIVERSAL INC - OXYGEN MEDIA
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	51521
NAICS Description:	CABLE AND OTHER SUBSCRIPTION PROGRAMMING

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

J136 **CHELSEA MARKET** **NY UST** **U004293460**
SSW **75TH NINTH AVENUE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.041 mi.
217 ft. **Site 6 of 35 in cluster J**

Relative: **Higher**
Actual: **15 ft.**

UST:

Name:	CHELSEA MARKET
Address:	75TH NINTH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-216674 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	03/20/2023
UTM X:	584024.62673
UTM Y:	4510582.96126
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

CHELSEA MARKET (Continued) **U004293460**

Site Id:	8160
Affiliation Type:	Mail Contact
Company Name:	TACONIC MANAGEMENT COMPANY LLC
Contact Type:	Not reported
Contact Name:	MICHAEL DOUGHERTY
Address1:	111 EIGTH AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	1011
Country Code:	001
Phone:	(917) 275-5989
EMail:	MDOUGHERTY@111EIGHTH.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-01-04

Site Id:	8160
Affiliation Type:	Facility Operator
Company Name:	CHELSEA MARKET
Contact Type:	Not reported
Contact Name:	TACONIC MANAGEMENT COMPANY LLC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 652-2110
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-01-04

Site Id:	8160
Affiliation Type:	Emergency Contact
Company Name:	MANHATTAN CHELSEA MARKET LLC
Contact Type:	Not reported
Contact Name:	MICHAEL DOUGHERTY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 760-3386
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-01-04

Site Id:	8160
Affiliation Type:	Facility Owner
Company Name:	MANHATTAN CHELSEA MARKET LLC
Contact Type:	PROPERTY MANAGER
Contact Name:	MICHAEL DOUGHERTY
Address1:	1600 AMPHITHEATRE PARKWAY

CHELSEA MARKET (Continued) **U004293460**

Address2:	Not reported
City:	MOUNTAIN VIEW
State:	CA
Zip Code:	94043
Country Code:	001
Phone:	(646) 760-5386
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-01-04

Tank Info:

Tank Number:	003
Tank ID:	278736
Tank Status:	Temporarily Out of Service
Material Name:	Temporarily Out of Service
Capacity Gallons:	20000
Install Date:	12/01/1959
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JSMACRI
Last Modified:	01/04/2019

Equipment Records:

J00 - Dispenser - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None

Tank Number:	004
Tank ID:	278737
Tank Status:	Temporarily Out of Service
Material Name:	Temporarily Out of Service
Capacity Gallons:	20000
Install Date:	12/01/1959
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported

CHELSEA MARKET (Continued) **U004293460**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JSMACRI
Last Modified: 01/04/2019

Equipment Records:

J00 - Dispenser - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Number: 005
Tank ID: 278738
Tank Status: Temporarily Out of Service
Material Name: Temporarily Out of Service
Capacity Gallons: 20000
Install Date: 12/01/1959
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JSMACRI
Last Modified: 01/04/2019

Equipment Records:

J00 - Dispenser - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Number: 008
Tank ID: 278739
Tank Status: Temporarily Out of Service
Material Name: Temporarily Out of Service
Capacity Gallons: 20000
Install Date: 12/01/1959

CHELSEA MARKET (Continued) **U004293460**

Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JSMACRI
Last Modified:	01/04/2019

Equipment Records:

J00 - Dispenser - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

J137 **NY1 NEWS** **NY AST** **A100366133**
SSW **75 NINTH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.041 mi.
217 ft. **Site 7 of 35 in cluster J**

Relative:
Higher

Actual:
15 ft.

AST:

Name:	NY1 NEWS
Address:	75 NINTH AVE
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-611943
Program Type:	PBS
UTM X:	584035.04359
UTM Y:	4510619.23666
Expiration Date:	08/01/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	477606
Affiliation Type:	Facility Owner
Company Name:	JAMESTOWN PREMIER CHELSEA MARKET, LP
Contact Type:	FACILITIES MANAGER
Contact Name:	ANTHONY MARTINEZ
Address1:	75 NINTH AVE. 5TH FLOOR
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 652-2121
EMail:	Not reported

NY1 NEWS (Continued) **A100366133**

Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2013-03-06
Site Id:	477606
Affiliation Type:	Mail Contact
Company Name:	JAMESTOWN PREMIER CHELSEA MARKET, LP
Contact Type:	Not reported
Contact Name:	A MARTINEZ
Address1:	NY1 NEWS
Address2:	75 NINTH AVE. 6TH FLOOR
City:	NY
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 379-3565
EMail:	ANTHONY.MARTINEZ@NY1NEWS.COM
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2013-03-06
Site Id:	477606
Affiliation Type:	Facility Operator
Company Name:	NY1 NEWS
Contact Type:	Not reported
Contact Name:	A. MARTINEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 379-3565
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2013-03-06
Site Id:	477606
Affiliation Type:	Emergency Contact
Company Name:	JAMESTOWN PREMIER CHELSEA MARKET, LP
Contact Type:	Not reported
Contact Name:	ANTHONY MARTINEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 379-3565
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2013-03-06

Tank Info:

NY1 NEWS (Continued) **A100366133**

Tank Number: 1
Tank Id: 246885
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:
G02 - Tank Secondary Containment - Vault (w/access)
C01 - Pipe Location - Aboveground
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
J02 - Dispenser - Suction Dispenser
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/2001
Capacity Gallons: 1280
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DMPOKRZY
Last Modified: 04/14/2017
Material Name: diesel

Tank Number: 2
Tank Id: 246886
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:
C01 - Pipe Location - Aboveground
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G11 - Tank Secondary Containment - Double-bottom (Aboveground)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron

NY1 NEWS (Continued) **A100366133**

Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/2001
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	diesel

I138 **CON ED** **NY MANIFEST** **S116044151**
WNW **FO 120 10TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10034**
0.043 mi.
225 ft. **Site 7 of 22 in cluster I**

Relative:
Lower

Actual:
11 ft.

NY MANIFEST:

Name:	CON ED
Address:	FO 120 10TH AVE
City,State,Zip:	NEW YORK, NY 10034
Country:	USA
EPA ID:	NYP004405429
Facility Status:	Not reported
Location Address 1:	FO 120 10TH AVE
Code:	BP
Location Address 2:	SB 43458
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10034
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004405429
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	12/12/2013
Trans1 Recv Date:	12/12/2013
Trans2 Recv Date:	Not reported

CON ED (Continued) **S116044151**

TSD Site Recv Date:	12/13/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004405429
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002299853GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J139 **CON EDISON** **RCRA NonGen / NLR** **1025887475**
South **72 9TH AVE** **NYP005243076**
< 1/8 **NEW YORK, NY 10014**
0.043 mi.
225 ft. **Site 8 of 35 in cluster J**

Relative: RCRA NonGen / NLR:
Higher

Date Form Received by Agency:		20220203
Handler Name:	CON EDISON	
Handler Address:		72 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP005243076
Contact Name:		THOMAS TEELING
Contact Address:		IRVING PL 15TH FL NE
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported

Actual:
16 ft.

CON EDISON (Continued) **1025887475**

Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported

CON EDISON (Continued) **1025887475**

Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220203
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20220203
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20190403
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

J140 **CON EDISON** **RCRA NonGen / NLR** **1025504725**
South **72 9TH AVE** **NYP005242342**
< 1/8 **NEW YORK, NY 10014**
0.043 mi.
225 ft. **Site 9 of 35 in cluster J**

Relative: **Higher**
Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20220126
Handler Name:	CON EDISON	
Handler Address:		72 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP005242342
Contact Name:		THOMAS TEELING
Contact Address:		IRVING PL, 15TH FL NE
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		State
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1025504725**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220126
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20220126
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20190115
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No

CON EDISON (Continued) **1025504725**

Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

B141 **CON EDISON** **NY MANIFEST** **S117058366**
ENE **361 W 19 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.044 mi.
231 ft. **Site 32 of 33 in cluster B**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	361 W 19 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004504627
Facility Status:	Not reported
Location Address 1:	361 W 19 ST
Code:	BP
Location Address 2:	SB3421
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004504627
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRIVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/18/2014
Trans1 Recv Date:	04/18/2014

CON EDISON (Continued) **S117058366**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004504627
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406251GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B142 **CON EDISON** **NY MANIFEST** **S118463849**
ENE **OPP 361 W 19TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.044 mi.
231 ft. **Site 33 of 33 in cluster B**

Relative: **Higher**
Actual: **17 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	OPP 361 W 19TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004857959
Facility Status:	Not reported
Location Address 1:	OPP 361 W 19TH ST
Code:	BP
Location Address 2:	SB 3436
Total Tanks:	Not reported

CON EDISON (Continued) **S118463849**

Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004857959
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 10/22/2015
Trans1 Recv Date: 10/22/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/23/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004857959
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014085578JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 1000
Units: P - Pounds
Number of Containers: 1

CON EDISON (Continued) **S118463849**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

F143 **CON EDISON** **NY MANIFEST** **S118463895**
SSE **357 W 16TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.044 mi.
231 ft. **Site 14 of 20 in cluster F**

Relative: **Higher**
Actual: **17 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	357 W 16TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004858580
Facility Status:	Not reported
Location Address 1:	357 W 16TH ST
Code:	BP
Location Address 2:	SB 2793
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004858580
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/2015
Trans1 Recv Date:	10/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported

CON EDISON (Continued) **S118463895**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004858580
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014085580JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

F144 **CON EDISON** **NY MANIFEST** **S117058296**
SSE **357 W 16 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.044 mi.
231 ft. **Site 15 of 20 in cluster F**

Relative: **Higher**
Actual: **17 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	357 W 16 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004503165
Facility Status:	Not reported
Location Address 1:	357 W 16 ST
Code:	BP
Location Address 2:	SB2793
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011

CON EDISON (Continued) **S117058296**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004503165
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/16/2014
Trans1 Recv Date: 04/16/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/23/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004503165
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011694211JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 500
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON (Continued) **S117058296**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

F145 **CON EDISON** **NY MANIFEST** **S117058300**
SSE **360 W 17 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.044 mi.
232 ft. **Site 16 of 20 in cluster F**

Relative:
Higher

Actual:
16 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	360 W 17 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004503355
Facility Status:	Not reported
Location Address 1:	360 W 17 ST
Code:	BP
Location Address 2:	SB3018
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004503355
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/17/2014
Trans1 Recv Date:	04/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004503355
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S117058300**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694214JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

K146 **409 W. 15TH STREET** **NY Spills** **S104496024**
SW **409 W. 15TH STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.044 mi.
233 ft. **Site 1 of 28 in cluster K**

Relative: SPILLS:
Lower

Actual: Name:	409 W. 15TH STREET
13 ft. Address:	409 W. 15TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9500757 / 1995-04-19
Facility ID:	9500757
Facility Type:	ER
DER Facility ID:	83687
Site ID:	93342
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	1995-04-19
Investigator:	MMMULQUE
Referred To:	Not reported
Reported to Dept:	1995-04-19

409 W. 15TH STREET (Continued) **S104496024**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1995-04-19
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-05-15
Spill Record Last Update:	2002-11-25
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MULQUEEN 1ST FLR OPERATING TENANTS PRINTING PRESSES LBRICATING OIL DRIPS DOWN INTO PAN BUY DUE TO SLOPPY HOUSE KEEPING TI SEEPED INTO CELLING"
Remarks:	"PRINTING PRESS IS LEAKING OIL - STAIN IS ON THE CEILING OF BASEMENT - ONGOING PROBLEM - CLOSED - DUPLICATE REPORT - SEE SPILL #95-00225"

All Materials:

Site ID:	93342
Operable Unit ID:	1014871
Operable Unit:	01
Material ID:	369373
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

H147 **CON EDISON** **NY MANIFEST** **S117067397**
East **FO 358 W 19 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.046 mi.
245 ft. **Site 2 of 15 in cluster H**

Relative: **Higher**

Actual: **17 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	FO 358 W 19 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004602033
Facility Status:	Not reported
Location Address 1:	FO 358 W 19 ST
Code:	BP
Location Address 2:	SB 3437
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY

CON EDISON (Continued) **S117067397**

Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004602033
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/21/2014
Trans1 Recv Date:	07/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004602033
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002608432GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.

CON EDISON (Continued) **S117067397**

Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H148 **CON EDISON** **NY MANIFEST** **S117058365**
East **358 W 19 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.046 mi.
245 ft. **Site 3 of 15 in cluster H**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	358 W 19 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004504619
Facility Status:	Not reported
Location Address 1:	358 W 19 ST
Code:	BP
Location Address 2:	SB3436
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004504619
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRIVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/18/2014
Trans1 Recv Date:	04/18/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004504619

CON EDISON (Continued) **S117058365**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407425GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H149 **BAYARD RUSTIN EDUCATIONAL COMP- M440** **NY AST** **A100194237**
ESE **351 WEST 18TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.047 mi.
246 ft. **Site 4 of 15 in cluster H**

Relative: **Higher**

Actual: **17 ft.**

AST:

Name:	BAYARD RUSTIN EDUCATIONAL COMP- M440
Address:	351 WEST 18TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-607209
Program Type:	PBS
UTM X:	584231.18943
UTM Y:	4510713.21514
Expiration Date:	11/20/2021
Site Type:	School

Affiliation Records:

Site Id:	29062

BAYARD RUSTIN EDUCATIONAL COMP- M440 (Continued) **A100194237**

Affiliation Type:	Facility Operator
Company Name:	BAYARD RUSTIN EDUCATIONAL COMP- M440
Contact Type:	Not reported
Contact Name:	MICHAEL KYPRIOS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 647-1060
EMail:	Not reported
Fax Number:	Not reported
Modified By:	HDDUPIGN
Date Last Modified:	2015-09-30

Site Id:	29062
Affiliation Type:	Mail Contact
Company Name:	NYC DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	JOSEPH YOUNGHESE
Address1:	FIELD OPERATIONS-FUEL DIVISION
Address2:	44-36 VERNON BLVD.
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5779
EMail:	JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-12-14

Site Id:	29062
Affiliation Type:	Emergency Contact
Company Name:	NYC DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	KEN MAHADEO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 210-7918
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2020-02-04

Site Id:	29062
Affiliation Type:	Facility Owner
Company Name:	NYC DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	MUNENDRA SHARMA
Address1:	44-36 VERNON BLVD.
Address2:	Not reported

BAYARD RUSTIN EDUCATIONAL COMP- M440 (Continued) **A100194237**

City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-07-28

Tank Info:

Tank Number:	001
Tank Id:	62507
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	K00 - Spill Prevention - None
	H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
	F01 - Pipe External Protection - Painted/Asphalt Coating
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	L00 - Piping Leak Detection - None
	H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
	G02 - Tank Secondary Containment - Vault (w/access)
	I04 - Overfill - Product Level Gauge (A/G)
	C01 - Pipe Location - Aboveground
	J02 - Dispenser - Suction Dispenser
	I02 - Overfill - High Level Alarm
	E00 - Piping Secondary Containment - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/2001
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MRBARROW
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

H150 **NYC BD OF ED - HUMANITIES H S** **RCRA-VSQG** **1001968889**
ESE **351 W 18TH ST** **FINDS** **NYR000080705**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.047 mi. **NY MANIFEST**
246 ft. **Site 5 of 15 in cluster H**

Relative: **Higher**
Actual: **17 ft.**

RCRA-VSQG:

Date Form Received by Agency:	20070101
Handler Name:	NYC BD OF ED - HUMANITIES H S
Handler Address:	351 W 18TH ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYR000080705
Contact Name:	BERNARD ORLAN
Contact Address:	W 18TH ST
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	718-391-6475
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 18TH ST
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	NYC BD OF ED
Owner Type:	Municipal
Operator Name:	NYC BD OF ED
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

NYC BD OF ED - HUMANITIES H S (Continued) **1001968889**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D009
Waste Description:	MERCURY

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYC BD OF ED
Legal Status:	Municipal
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	2811 QUEENS PLZ N
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101

NYC BD OF ED - HUMANITIES H S (Continued) **1001968889**

Owner/Operator Telephone: 718-391-6475
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC BD OF ED
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 2811 QUEENS PLZ N
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-391-6475
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC BD OF ED
Legal Status: Municipal
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 2811 QUEENS PLZ N
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-391-6475
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYC BD OF ED - HUMANITIES H S
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYC BD OF ED - HUMANITIES H S
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20000329

NYC BD OF ED - HUMANITIES H S (Continued) **1001968889**

Handler Name: NYC BD OF ED - HUMANITIES H S
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20001031
Handler Name: NYC BD OF ED - HUMANITIES H S
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004558513

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001968889
Registry ID: 110004558513
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004558513
Name: NYC BD OF ED - HUMANITIES H S

NYC BD OF ED - HUMANITIES H S (Continued) **1001968889**

Address: 351 W 18TH ST
City,State,Zip: NEW YORK, NY 10011

NY MANIFEST:
Name: HUMANITIES HIGH SCHOOL
Address: 351 W 18TH ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYR000080705
Facility Status: Not reported
Location Address 1: 351 W 18TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000080705
Mailing Name: HUMANITIES HIGH SCHOOL
Mailing Contact: MARINO JOHN LEWIS
Mailing Address 1: 351 W 18TH ST
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10011
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2128070674

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NYD986938645
Trans2 State ID: PAD146714878
Generator Ship Date: 12/02/2010
Trans1 Recv Date: 12/02/2010
Trans2 Recv Date: 12/03/2010
TSD Site Recv Date: 12/06/2010
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000080705
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NYD049836679
TSDF ID 2: Not reported
Manifest Tracking Number: 007051510JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N

NYC BD OF ED - HUMANITIES H S (Continued) **1001968889**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H132
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	15
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	B007
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

K151 **CON EDISON - VAULT 4188** **RCRA-LQG** **1024890579**
SW **421 W 15TH ST** **NYP005015581**
< 1/8 **NEW YORK, NY 10011**
0.047 mi.
248 ft. **Site 2 of 28 in cluster K**

Relative: RCRA-LQG:
Lower

Date Form Received by Agency:		20180410
Actual: Handler Name:	CON EDISON - VAULT 4188	
13 ft. Handler Address:		421 W 15TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP005015581
Contact Name:		ALYSSA SOTTO
Contact Address:		IRVING PLACE, 15TH FL NE
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-2757
Contact Fax:		Not reported
Contact Email:		SOTTOA@CONED.COM
Contact Title:		ASSOCIATE SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Large Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		2017
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:		Private
Operator Name:		CONSOLIDATED EDISON COMPANY OF NY, INC.

CON EDISON - VAULT 4188 (Continued) **1024890579**

Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

CON EDISON - VAULT 4188 (Continued) **1024890579**

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20170408
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-460-2757
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20170408
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-460-2757
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20180410
Handler Name: CON EDISON - VAULT 4188	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

CON EDISON - VAULT 4188 (Continued) **1024890579**

Evaluation Action Summary:
Evaluations: No Evaluations Found

K152 **CON EDISON** **NY MANIFEST** **S121967488**
SW **421 W 15TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.047 mi.
248 ft. **Site 3 of 28 in cluster K**

Relative:
Lower

Actual:
13 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	421 W 15TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP005015599
Facility Status:	Not reported
Location Address 1:	421 W 15TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005015599
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

K153 **CON EDISON** **NY MANIFEST** **S121967487**
SW **421 W 15TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.047 mi.
248 ft. **Site 4 of 28 in cluster K**

Relative:
Lower

Actual:
13 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	421 W 15TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP005015581
Facility Status:	Not reported
Location Address 1:	421 W 15TH ST
Code:	BP
Location Address 2:	Not reported

CON EDISON (Continued) **S121967487**

Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP005015581
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

K154 **CON EDISON - VAULT SUBMERSIBLE 5981** **RCRA-LQG** **1024890580**
SW **421 W 15TH ST** **NYP005015599**
< 1/8 **NEW YORK, NY 10011**
0.047 mi.
248 ft. **Site 5 of 28 in cluster K**

Relative: RCRA-LQG:
Lower
Actual: Date Form Received by Agency: 20180410
13 ft. Handler Name: CON EDISON - VAULT SUBMERSIBLE 5981
Handler Address: 421 W 15TH ST
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYP005015599
Contact Name: ALYSSA SOTTO
Contact Address: IRVING PLACE, 15TH FL NE
Contact City,State,Zip: NEW YORK, NY 10003
Contact Telephone: 212-460-2757
Contact Fax: Not reported
Contact Email: SOTTOA@CONED.COM
Contact Title: ASSOCIATE SCIENTIST
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Large Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: 2017
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: NY
State District: NYSDEC R2
Mailing Address: IRVING PLACE, 15TH FL NE
Mailing City,State,Zip: NEW YORK, NY 10003
Owner Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type: Private
Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type: Private
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No

CON EDISON - VAULT SUBMERSIBLE 5981 (Continued) **1024890580**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

CON EDISON - VAULT SUBMERSIBLE 5981 (Continued) **1024890580**

Hazardous Waste Summary:
- Waste Code: D008
- Waste Description: LEAD

Handler - Owner Operator:
- Owner/Operator Indicator: Owner
- Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
- Legal Status: Private
- Date Became Current: 20170105
- Date Ended Current: Not reported
- Owner/Operator Address: 4 IRVING PLACE
- Owner/Operator City,State,Zip: NEW YORK, NY 10003
- Owner/Operator Telephone: 212-460-2757
- Owner/Operator Telephone Ext: Not reported
- Owner/Operator Fax: Not reported
- Owner/Operator Email: Not reported

- Owner/Operator Indicator: Operator
- Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
- Legal Status: Private
- Date Became Current: 20170105
- Date Ended Current: Not reported
- Owner/Operator Address: 4 IRVING PLACE
- Owner/Operator City,State,Zip: NEW YORK, NY 10003
- Owner/Operator Telephone: 212-460-2757
- Owner/Operator Telephone Ext: Not reported
- Owner/Operator Fax: Not reported
- Owner/Operator Email: Not reported

Historic Generators:
- Receive Date: 20180410
- Handler Name: CON EDISON - VAULT SUBMERSIBLE 5981
- Federal Waste Generator Description: Large Quantity Generator
- State District Owner: NY
- Large Quantity Handler of Universal Waste: No
- Recognized Trader Importer: No
- Recognized Trader Exporter: No
- Spent Lead Acid Battery Importer: No
- Spent Lead Acid Battery Exporter: No
- Current Record: Yes
- Non Storage Recycler Activity: No
- Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
- NAICS Code: 221122
- NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
- Violations: No Violations Found

Evaluation Action Summary:
- Evaluations: No Evaluations Found

F155 **CON EDISON** **RCRA NonGen / NLR** **1014395680**
SE **353 W 17TH ST** **NJ MANIFEST** **NYP004171468**
< 1/8 **NEW YORK, NY 10014** **NY MANIFEST**
0.048 mi.
251 ft. **Site 17 of 20 in cluster F**

Relative: **Higher**
Actual: **17 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		353 W 17TH ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004171468
Contact Name:		DAVID DUKE
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		917-559-8971
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1014395680**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160727
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090609
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1014395680**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004171468
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DAVID DUKE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	003532083JJK
EPA ID:	NYP004171468
Date Shipped:	06/09/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/09/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/09/2009

CON EDISON (Continued) **1014395680**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	550 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	353 W 17TH ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004171468
Facility Status:	Not reported
Location Address 1:	OPP 353 W 17TH ST.
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MANHATTAN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004171468
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	NEW YORKLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON (Continued) **1014395680**

seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/09/2009
Trans1 Recv Date:	06/09/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/09/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004171468
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003532083JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	550
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

I156 **FREEDMAN REALTY** **NY UST** **U001736499**
WNW **110 TENTH AVENUE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.049 mi.
257 ft. **Site 8 of 22 in cluster I**

Relative: UST:
Lower

Name:	FREEDMAN REALTY
Address:	110 TENTH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-601567 / Inactive

Actual:
10 ft.

FREEDMAN REALTY (Continued) **U001736499**

Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583887.09762
UTM Y:	4510818.33906
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	23529
Affiliation Type:	Facility Owner
Company Name:	FREEDMAN REALTY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	P.O. BOX 306
Address2:	Not reported
City:	SOUTH EGREMOUNT
State:	MA
Zip Code:	01258-0306
Country Code:	001
Phone:	(413) 229-2931
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23529
Affiliation Type:	Mail Contact
Company Name:	FREEDMAN REALTY
Contact Type:	Not reported
Contact Name:	MR. DONALD FREEDMAN
Address1:	P.O. BOX 306
Address2:	Not reported
City:	SOUTH EGREMOUNT
State:	MA
Zip Code:	01258-0306
Country Code:	001
Phone:	(413) 229-2931
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23529
Affiliation Type:	Facility Operator
Company Name:	FREEDMAN REALTY
Contact Type:	Not reported
Contact Name:	DONALD FREEDMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 243-4700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT

FREEDMAN REALTY (Continued) **U001736499**

Date Last Modified: 2004-03-04

Site Id: 23529
Affiliation Type: Emergency Contact
Company Name: FREEDMAN REALTY
Contact Type: Not reported
Contact Name: DONALD FREEDMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 243-4700
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank ID: 46887
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 03/17/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 002
Tank ID: 46888
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use

FREEDMAN REALTY (Continued) **U001736499**

Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/17/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None

Tank Number:	003
Tank ID:	46889
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/17/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None

E157 **448 E. 19TH ST** **NY Spills** **S104495803**
NW **448 E. 19TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.050 mi.
264 ft. **Site 15 of 15 in cluster E**

Relative:
Lower

Actual:
12 ft.

SPILLS:

Name:	448 E. 19TH ST
Address:	448 E. 19TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9410491 / 1994-11-07
Facility ID:	9410491
Facility Type:	ER
DER Facility ID:	197907
Site ID:	240641
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	4101
Spill Date:	1994-11-07
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1994-11-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	1994-11-07
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-12-08
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks:	"DEFECTIVE GAUGE? WILL SEND SOME ONE TO CLEANUP."

All Materials:

Site ID:	240641
Operable Unit ID:	1004406
Operable Unit:	01
Material ID:	376357
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	6.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I158 **CON EDISON** **NY MANIFEST** **S117058359**
WNW **10 AVE & 17TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.052 mi.
277 ft. **Site 9 of 22 in cluster I**

Relative:
Lower

Actual:
10 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	10 AVE & 17TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004504460
Facility Status:	Not reported
Location Address 1:	10 AVE & 17TH ST
Code:	BP
Location Address 2:	SB43508
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004504460
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/18/2014
Trans1 Recv Date:	04/18/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004504460
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011697551JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117058359**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	750
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

I159 **HY FLUID FROM VEHICLE IN SBOX 43058** **NY Spills** **S108465932**
WNW **10 AVENUE & WEST 17 STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.052 mi.
277 ft. **Site 10 of 22 in cluster I**

Relative: SPILLS:
Lower

Actual:
10 ft.

Name:	HY FLUID FROM VEHICLE IN SBOX 43058
Address:	10 AVENUE & WEST 17 STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0612352 / 2007-03-16
Facility ID:	0612352
Facility Type:	ER
DER Facility ID:	326742
Site ID:	377180
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2007-02-10
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2007-02-10
CID:	78
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

HY FLUID FROM VEHICLE IN SBOX 43058 (Continued) **S108465932**

Remediation Phase:	0
Date Entered In Computer:	2007-02-12
Spill Record Last Update:	2007-03-15
Spiller Name:	Not reported
Spiller Company:	Con Edison
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	ERTS
DEC Memo:	"03/16/07 - See e-docs for Con Ed report detailing cleanup and closure. 204520. see eDocs."
Remarks:	"no to five questions approx 1 gal into service box and that the service box is inaccessable at this time due to a car parked on top of it crew clean up with absorant material. 204520"

All Materials:

Site ID:	377180
Operable Unit ID:	1134732
Operable Unit:	01
Material ID:	2124616
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	9.00
Oxygenate:	Not reported

I160
WNW
< 1/8
0.052 mi.
277 ft.

MANHOLE #43054, SOUTHEAST
WEST 17 STREET & 10 AVENUE
MANHATTAN, NY

NY Spills **S107787564**
N/A

Site 11 of 22 in cluster I

Relative:
Lower

Actual:
10 ft.

SPILLS:

Name:	MANHOLE #43054, SOUTHEAST
Address:	WEST 17 STREET & 10 AVENUE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0600835 / 2006-05-15
Facility ID:	0600835
Facility Type:	ER
DER Facility ID:	313146
Site ID:	362936
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2006-04-21
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2006-04-21
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

MANHOLE #43054, SOUTHEAST (Continued) **S107787564**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-04-21
Spill Record Last Update:	2006-06-12
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	999
Contact Name:	ERT DESK'
DEC Memo:	"05/15/06 - See e-docs for Con Ed report detailing cleanup and closure. 05/15/06 - See e-docs for Con Ed report detailing cleanup and closure. 163902. 4-21-06 13:48. Corry Cust #87113 calls at 12:31 to report that at 12:25 he found approx 1/2 pint of oil on some soil in MH 43054 located at the S.W.C. of W.17 ST & 10th Ave. The spill is contained at this time is coming from a feeder cable located in the structure. Mr. Cust was there to do repairs and was working under acct 42228. There were no sewers or waterways affected. No fire or smoke involved. There were no injuries and weather conditions did not contribute to the spill. No private property was affected. There is no water present and no sumps or pumps running. Mr. Cust has installed an environmental tag in the structure # 42790. At this time no lab samples will be taken due to the fact the feeder needs to be D-Faulted by #9 and will be put in as a regular spill. Edgar Rios # 85938"
Remarks:	"1/2 pint, unable to clean it up because there is a default in the hole. no to five questions. con ed#163902 "

All Materials:

Site ID:	362936
Operable Unit ID:	1121006
Operable Unit:	01
Material ID:	2110491
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

J161 **CON EDISON - VAULT V505** **NY MANIFEST** **S123692389**
SSW **69 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.053 mi.
280 ft. **Site 10 of 35 in cluster J**

Relative: NY MANIFEST:
Higher

Actual: Name:	CON EDISON - VAULT V505
15 ft. Address:	69 9TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP005197342
Facility Status:	Not reported
Location Address 1:	69 9TH AVE

CON EDISON - VAULT V505 (Continued) **S123692389**

Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP005197342
Mailing Name: CON EDISON - VAULT V505
Mailing Contact: ANNAMARIE MOYLAN
Mailing Address 1: 4 IRVING PLACE 15TH FL NE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602278

J162 **VAULT 0505** **NY Spills** **S104952685**
SSW **69 9TH AVE** **N/A**
< 1/8 **MANHATTAN, NY**
0.053 mi.
280 ft. **Site 11 of 35 in cluster J**

Relative:
Higher

Actual:
15 ft.

SPILLS:
Name: VAULT 0505
Address: 69 9TH AVE
City,State,Zip: MANHATTAN, NY
Spill Number/Closed Date: 0012059 / 2003-06-23
Facility ID: 0012059
Facility Type: ER
DER Facility ID: 62794
Site ID: 65355
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 3101
Spill Date: 2001-02-09
Investigator: OKWUOHA
Referred To: Not reported
Reported to Dept: 2001-02-09
CID: 396
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-02-09
Spill Record Last Update: 2003-06-23
Spiller Name: Not reported

VAULT 0505 (Continued) **S104952685**

Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: BILL MURPHY
DEC Memo: ""
Remarks: "1 gal spilled. samples taken clean up pending. ref # 135453. leak from a bushing on a transformer. samples taken from transformer and spilled material. pcb hx = 22ppm."

All Materials:
Site ID: 65355
Operable Unit ID: 833433
Operable Unit: 01
Material ID: 542341
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

F163 **CON EDISON - VAULT V7157** **NY MANIFEST** **S120959096**
SSE **346 W 17 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.053 mi.
282 ft. **Site 18 of 20 in cluster F**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:
Name: CON EDISON - VAULT V7157
Address: 346 W 17 ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004991871
Facility Status: Not reported
Location Address 1: 346 W 17 ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004991871
Mailing Name: CON EDISON - VAULT V7157
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL NE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

F164 **COVENANT HOUSE THE** **RCRA-SQG** **1011863523**
SSE **346 W 17TH ST** **NY MANIFEST** **NYR000160358**
< 1/8 **NEW YORK, NY 10011**
0.053 mi.
282 ft. **Site 19 of 20 in cluster F**

Relative: **Higher**
Actual: **17 ft.**

RCRA-SQG:

Date Form Received by Agency:		20081015
Handler Name:	COVENANT HOUSE THE	
Handler Address:		346 W 17TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYR000160358
Contact Name:		JULIE REQUARTH
Contact Address:		W 17TH ST
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		212-229-5102
Contact Fax:		Not reported
Contact Email:		JR@MCGOWANBUILDERS.COM
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		W 17TH ST
Mailing City,State,Zip:		NEW YORK, NY 10011
Owner Name:		346 WEST 17TH LLC
Owner Type:		Private
Operator Name:		346 WEST 17TH LLC
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

COVENANT HOUSE THE (Continued) **1011863523**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	346 WEST 17TH LLC
Legal Status:	Private
Date Became Current:	20070410
Date Ended Current:	Not reported
Owner/Operator Address:	1251 AVENUE OF THE AMERICAS STE 934
Owner/Operator City,State,Zip:	NEW YORK, NY 10022
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	346 WEST 17TH LLC
Legal Status:	Private
Date Became Current:	20070410

COVENANT HOUSE THE (Continued) **1011863523**

Date Ended Current:	Not reported
Owner/Operator Address:	1251 AVENUE OF THE AMERICAS STE 934
Owner/Operator City,State,Zip:	NEW YORK, NY 10022
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20081015
Handler Name: COVENANT HOUSE THE	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	23622
NAICS Description:	COMMERCIAL AND INSTITUTIONAL BUILDING CONSTRUCTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	COVENANT HOUSE THE
Address:	346 W 17TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYR000160358
Facility Status:	Not reported
Location Address 1:	346 W 17TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000160358
Mailing Name:	COVENANT HOUSE THE
Mailing Contact:	JOE MARTINO
Mailing Address 1:	346 W 17TH ST
Mailing Address 2:	Not reported

COVENANT HOUSE THE (Continued) **1011863523**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2122295102

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYR000134957
Trans2 State ID:	NJD054126154
Generator Ship Date:	11/18/2008
Trans1 Recv Date:	11/18/2008
Trans2 Recv Date:	11/20/2008
TSD Site Recv Date:	12/09/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000160358
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD066060609
TSDF ID 2:	Not reported
Manifest Tracking Number:	005194017JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

F165 **MANHOLE # UNK** **NY Spills** **S104788873**
SSE **IFO 346 W 17TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.053 mi.
282 ft. **Site 20 of 20 in cluster F**

Relative:
Higher

Actual:
17 ft.

SPILLS:

Name:	MANHOLE # UNK
Address:	IFO 346 W 17TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0006310 / 2001-12-18
Facility ID:	0006310
Facility Type:	ER
DER Facility ID:	215065
Site ID:	263846
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	2000-08-28
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-08-28
CID:	390
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-08-28
Spill Record Last Update:	2001-12-18
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	STEVEN ROMERO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL "
Remarks:	"2 PTS ON 5 GALS OF WATER - UNK IF SEWERS OR WATERWAYS AQFFECTED CLEAN UP PENDING LAB RESULTS"

All Materials:

Site ID:	263846
Operable Unit ID:	827320
Operable Unit:	01
Material ID:	547428
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

J166 **9TH AVE & 15TH ST** **NY Spills** **S102150329**
SSW **9TH AVE & 15TH ST** **N/A**
< 1/8 **NEW YORK, NY**
0.054 mi.
283 ft. **Site 12 of 35 in cluster J**

Relative:
Higher

Actual:
15 ft.

SPILLS:

Name:	9TH AVE & 15TH ST
Address:	9TH AVE & 15TH ST
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	9503308 / 2003-08-11
Facility ID:	9503308
Facility Type:	ER
DER Facility ID:	122662
Site ID:	143861
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	C3
SWIS:	3101
Spill Date:	1995-06-16
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1995-06-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-06-21
Spill Record Last Update:	2003-08-11
Spiller Name:	Not reported
Spiller Company:	STAR TAXI MGMT
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"TAXI COMPANY IS DUMPING BARRELS DOWN SEWER EVERY MORNING - REFER TO IWCS/HAZMAT DEP"

All Materials:

Site ID:	143861
Operable Unit ID:	1014523
Operable Unit:	01
Material ID:	368358
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

H167 **D S K ASSOC** **NY AST** **U004046490**
ESE **352-354 W 18 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.054 mi.
286 ft. **Site 6 of 15 in cluster H**

Relative:
Higher

Actual:
17 ft.

AST:

Name:	D S K ASSOC
Address:	352-354 W 18 ST
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-063533
Program Type:	PBS
UTM X:	584239.41989
UTM Y:	4510689.35393
Expiration Date:	N/A
Site Type:	Unknown

Affiliation Records:

Site Id:	1266
Affiliation Type:	Facility Owner
Company Name:	HARRY J DEMOTT
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	165 9TH AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 242-5050
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1266
Affiliation Type:	Mail Contact
Company Name:	HARRY J DEMOTT
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	165 9TH AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 242-5050
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1266
Affiliation Type:	Facility Operator
Company Name:	D S K ASSOC
Contact Type:	Not reported
Contact Name:	CLARENCE ROBERSON

D S K ASSOC (Continued) **U004046490**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 242-5050
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1266
Affiliation Type:	Emergency Contact
Company Name:	HARRY J DEMOTT
Contact Type:	Not reported
Contact Name:	KATHERINE LANDINI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 741-9082
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	2315
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	I04 - Overfill - Product Level Gauge (A/G)
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	F00 - Pipe External Protection - None
	H00 - Tank Leak Detection - None
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
	A00 - Tank Internal Protection - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

D S K ASSOC (Continued) **U004046490**

Date Tank Closed:	01/01/1991
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

K168 **VAULT 4188** **NY Spills** **S106698121**
SW **15TH ST BTW 9 & 10TH AVE** **N/A**
< 1/8 **MANHATTAN, NY**
0.054 mi.
287 ft. **Site 6 of 28 in cluster K**

Relative: **Lower**
Actual: **12 ft.**

SPILLS:

Name:	VAULT 4188
Address:	15TH ST BTW 9 & 10TH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0405039 / 2009-10-26
Facility ID:	0405039
Facility Type:	ER
DER Facility ID:	231689
Site ID:	285822
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	2004-08-07
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2004-08-07
CID:	64
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-08-07
Spill Record Last Update:	2009-10-26
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	999
Contact Name:	ERT DESK
DEC Memo:	"10/26/09. As was stated during initial reporting there are no spill. Case closed. JK."
Remarks:	"NO SPILL JUST FIRE. DUE TO FIRE, A LOT OF PRIVATE PROPERTY DAMAGED. "
	Not reported

L169 **CON EDISON** **NY MANIFEST** **S117058297**
SSE **351 W 16 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.055 mi.
291 ft. **Site 1 of 18 in cluster L**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	351 W 16 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004503173
Facility Status:	Not reported
Location Address 1:	351 W 16 ST
Code:	BP
Location Address 2:	SB2794
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004503173
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/16/2014
Trans1 Recv Date:	04/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004503173
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694215JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117058297**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J170 **CON EDISON MANHOLE 2576** **RCRA NonGen / NLR** **1014917993**
SSW **400 W 15TH ST & 9TH AVE OPP** **NJ MANIFEST** **NYP004215760**
< 1/8 **NEW YORK, NY 10011** **NY MANIFEST**
0.056 mi.
294 ft. **Site 13 of 35 in cluster J**

Relative: **Higher**
Actual: **15 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20101016
Handler Name:	CON EDISON MANHOLE 2576
Handler Address:	400 W 15TH ST & 9TH AVE OPP
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004215760
Contact Name:	JUAN RODRIGUEZ
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	347-865-5931
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported

CON EDISON MANHOLE 2576 (Continued) **1014917993**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20110701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON MANHOLE 2576 (Continued) **1014917993**

Historic Generators:
Receive Date: 20100916
Handler Name: CON EDISON MANHOLE 2576
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20101016
Handler Name: CON EDISON MANHOLE 2576
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:
EPA Id: NYP004215760
Mail Address: IRVING PL RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: JUAN RODRIGUEZ
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

CON EDISON MANHOLE 2576 (Continued) **1014917993**

Manifest:

Manifest Number:	007656840JJK
EPA ID:	NYP004215760
Date Shipped:	09/16/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/16/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/17/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	8000 P

Manifest Number:	007865840JJK
EPA ID:	NYP004215760
Date Shipped:	09/16/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported

CON EDISON MANHOLE 2576 (Continued) **1014917993**

Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/16/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/17/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	8000 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	400 W 15TH ST & 9TH AVE OPP
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004215760
Facility Status:	Not reported
Location Address 1:	OPPOSITE 400 W 15TH ST AND 9TH
Code:	BP
Location Address 2:	AVE
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

CON EDISON MANHOLE 2576 (Continued) **1014917993**

NY MANIFEST:

EPAID:	NYP004215760
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/16/2010
Trans1 Recv Date:	09/16/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/17/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004215760
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007656840JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	8000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON MANHOLE 2576 (Continued) **1014917993**

Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

H171 **CON EDISON** **NY MANIFEST** **S117067461**
ESE **FO 342 WEST 18 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.056 mi.
296 ft. **Site 7 of 15 in cluster H**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:
Name: CON EDISON
Address: FO 342 WEST 18 ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004603288
Facility Status: Not reported
Location Address 1: FO 342 WEST 18 ST
Code: BP
Location Address 2: SB 3250
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004603288
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/22/2014
Trans1 Recv Date: 07/22/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/25/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004603288
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported

CON EDISON (Continued) **S117067461**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504414GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H172 **CON EDISON** **NY MANIFEST** **S116551446**
ESE **342-340 W 18 ST & 9 AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.056 mi.
296 ft. **Site 8 of 15 in cluster H**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	342-340 W 18 ST & 9 AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004499109
Facility Status:	Not reported
Location Address 1:	342-340 W 18 ST & 9 AVE
Code:	BP
Location Address 2:	SB3250
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004499109

CON EDISON (Continued) **S116551446**

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/13/2014
Trans1 Recv Date:	04/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004499109
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407480GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **S116551446**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

I173 **WEST 18TH ST & TENTH AVE** **NY Spills** **S103937925**
WNW **W. 18TH ST &TENTH AVE** **N/A**
< 1/8 **MANHATTAN, NY**
0.057 mi.
300 ft. **Site 12 of 22 in cluster I**

Relative: **Lower**

Actual: **11 ft.**

SPILLS:

Name:	WEST 18TH ST & TENTH AVE
Address:	W. 18TH ST &TENTH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9902463 / 2006-07-12
Facility ID:	9902463
Facility Type:	ER
DER Facility ID:	259477
Site ID:	322102
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	1999-06-03
Investigator:	SXLASDIN
Referred To:	Not reported
Reported to Dept:	1999-06-03
CID:	198
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-06-03
Spill Record Last Update:	2006-07-12
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MIKE CESARE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 7/12/06. only 5 gallons gasoline spilled in 1999, close spill."
	Not reported
Remarks:	"CALLER AGENCY DIGGING ON PROPERTY FOR A NATURAL GAS MAIN AND NOTICED CONTAMINATED SOIL. VACANT LOT THAT POSSIBLY HAD GAS STATION ON IT AT ONE TIME. CON ED #125297."

All Materials:

Site ID:	322102
Operable Unit ID:	1081393
Operable Unit:	01
Material ID:	305967
Material Code:	0009
Material Name:	gasoline

WEST 18TH ST & TENTH AVE (Continued) **S103937925**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I174 **SPILL NUMBER 0107030** **NY Spills** **S105234708**
WNW **18TH ST/11TH AVE** **N/A**
< 1/8 **MANHATTAN, NY**
0.057 mi.
300 ft. **Site 13 of 22 in cluster I**

Relative: **Lower**

Actual: **11 ft.**

SPILLS:

Name:	SPILL NUMBER 0107030
Address:	18TH ST/11TH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0107030 / 2002-07-29
Facility ID:	0107030
Facility Type:	ER
DER Facility ID:	80084
Site ID:	87401
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	2001-10-06
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2001-10-06
CID:	396
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-10-06
Spill Record Last Update:	2002-08-02
Spiller Name:	JAMES CRANDALL
Spiller Company:	NEW YORK CITY TRANSIT AUT
Spiller Address:	HORITY
Spiller Company:	001
Contact Name:	JOSEPHINE BROWN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE CONTAINED AND CLEANED BY NYCT AND NYC DOS."
Remarks:	"speedy dry put down waithing for sanitation dept to respond to finish clean up."

All Materials:

Site ID:	87401
Operable Unit ID:	845222
Operable Unit:	01
Material ID:	531866

SPILL NUMBER 0107030 (Continued) **S105234708**

Material Code:	0021
Material Name:	transmission fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	8.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I175 **214187; 18 ST & 10 AV** **NY Spills** **S110306651**
WNW **18 ST & 10 AV** **N/A**
< 1/8 **NEW YORK, NY**
0.057 mi.
300 ft. **Site 14 of 22 in cluster I**

Relative:
Lower

Actual:
11 ft.

SPILLS:

Name:	214187; 18 ST & 10 AV
Address:	18 ST & 10 AV
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0814545 / 2008-11-24
Facility ID:	0814545
Facility Type:	ER
DER Facility ID:	386327
Site ID:	432691
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	2401
Spill Date:	2008-10-18
Investigator:	DMPOKRZY
Referred To:	Not reported
Reported to Dept:	2008-12-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	Not reported
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2010-04-16
Spill Record Last Update:	2010-04-16
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	5030 BROADWAY
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	""
Remarks:	""

All Materials:

Site ID:	432691
Operable Unit ID:	1183752
Operable Unit:	01
Material ID:	2177940

214187; 18 ST & 10 AV (Continued) **S110306651**

Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

I176 **OIL ON SOIL** **NY Spills** **S121982149**
WNW **10TH AVE AND WEST 18TH** **N/A**
< 1/8 **MANHATTAN, NY**
0.057 mi.
300 ft. **Site 15 of 22 in cluster I**

Relative: **Lower**

Actual: **11 ft.**

SPILLS:

Name:	OIL ON SOIL
Address:	10TH AVE AND WEST 18TH
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	1103935 / 2014-02-25
Facility ID:	1103935
Facility Type:	ER
DER Facility ID:	406076
Site ID:	451513
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	2011-07-09
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2011-07-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-07-09
Spill Record Last Update:	2014-02-25
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"2/25/14 - Austin - Con Ed encountered some minor (4 oz.) unk. oil (un analylized) soil contamination while driling a test pit got a gas regulator station at this location - Con Ed disposed of the contaminated soil and drilled in another location to take their sample for the construction project - See Edocs files for further information - Spill closed - end"
Remarks:	"4 oz unk oil and unk source found"

OIL ON SOIL (Continued) **S121982149**

All Materials:
- Site ID: 451513
- Operable Unit ID: 1201707
- Operable Unit: 01
- Material ID: 2198259
- Material Code: 0066A
- Material Name: unknown petroleum
- Case No.: Not reported
- Material FA: Petroleum
- Quantity: Not reported
- Units: Not reported
- Recovered: Not reported
- Oxygenate: Not reported

M177 **CON EDISON** **NY MANIFEST** **S118463848**
East **OPP 353 W 19TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.058 mi.
304 ft. **Site 1 of 10 in cluster M**

Relative: **Higher**
Actual: **17 ft.**

NY MANIFEST:
- Name: CON EDISON
- Address: OPP 353 W 19TH ST
- City,State,Zip: NEW YORK, NY 10011
- Country: USA
- EPA ID: NYP004857942
- Facility Status: Not reported
- Location Address 1: OPP 353 W 19TH ST
- Code: BP
- Location Address 2: SB 3437
- Total Tanks: Not reported
- Location City: NEW YORK
- Location State: NY
- Location Zip: 10011
- Location Zip 4: Not reported

NY MANIFEST:
- EPAID: NYP004857942
- Mailing Name: CON EDISON
- Mailing Contact: DENNIS HUACON
- Mailing Address 1: 4 IRVING PL 15TH FL
- Mailing Address 2: Not reported
- Mailing City: NEW YORK
- Mailing State: NY
- Mailing Zip: 10003
- Mailing Zip 4: Not reported
- Mailing Country: USA
- Mailing Phone: 2124603770

NY MANIFEST:
- Document ID: Not reported
- Manifest Status: Not reported
- seq: Not reported
- Year: 2018
- Trans1 State ID: NJ0000027193
- Trans2 State ID: Not reported

CON EDISON (Continued) **S118463848**

Generator Ship Date:	10/22/2015
Trans1 Recv Date:	10/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004857942
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014085577JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H178 **VAULT 8126** **NY Spills** **S104507818**
ESE **335 W. 18TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.059 mi.
310 ft. **Site 9 of 15 in cluster H**

Relative: **Higher**
Actual: **17 ft.**

SPILLS:

Name:	VAULT 8126
Address:	335 W. 18TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9905335 / 1999-11-05
Facility ID:	9905335
Facility Type:	ER
DER Facility ID:	111900
Site ID:	129824

VAULT 8126 (Continued) **S104507818**

DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3101
Spill Date:	1999-08-03
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1999-08-03
CID:	322
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-08-03
Spill Record Last Update:	2000-05-25
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PL
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL con ed e2mis notes: 3 gal of transformer oil (dielectric fluid) mixed in dirt that came from a bottom leak on the transformer. Took a sample. A partial cleanup is in progress, full cleanup will be pending deenergizing and removal of unit. The count as per cinde records are 33 ppm. No smoke, no fire, no sump pump running, no sewer connection, and it did not enter sewer. PCB count 21.ppm Unit was denergized as OOE cat 1. Partial cleanup completed at 17:00. Generated 2 55-gallons split ring drums of <50ppm solid waste. Transported same to W. 28 St. WOL. applied oil absorbant to vault floor. Found weephole to adjacent Vault (V6052) plugged. Boomed same. Also, disconnected and boomed pump in V6052. Final cleanup pending transformer removal. Unit is drained by Astoria <50 ppm tanker truck. 300 gallons of oil was drained. Max capacity of transformer is 330 gallons in accordance with nameplate data. Transformer was also disconnected. The clean up was completed by M.Prystup #02394; K.Christiansen time 0800 to 1130, removed 3 drums of solid waste transported to west 28 St. Industrial waste pit. Double washed floor with slix and oil free, re-rinsed with flush truck. Removed oil tag, reported by J.Gnall O.S. Logger R. Smith."
Remarks:	"leak from a transformer - contained in vault & mixed with dirt -partial clean up has been done already - con ed #127012- full clean up will be done pending deenergization of transfromer history shows 30ppm"

All Materials:

Site ID:	129824
Operable Unit ID:	1079779
Operable Unit:	01
Material ID:	301635
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported

VAULT 8126 (Continued) **S104507818**

Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

H179 **SCHOOL OF HUMANITES** **NY LTANKS** **S104951052**
ESE **18TH-19TH** **N/A**
< 1/8 **MANHATTAN, NY**
0.059 mi.
313 ft. **Site 10 of 15 in cluster H**

Relative:
Higher

Actual:
17 ft.

LTANKS:

Name:	SCHOOL OF HUMANITES
Address:	18TH-19TH
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0013005 / 2001-03-15
Facility ID:	0013005
Site ID:	113466
Spill Date:	2001-03-10
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2001-03-12
CID:	382
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-03-12
Spill Record Last Update:	2001-03-15
Spiller Name:	UNKNOWN
Spiller Company:	SCHOOL OF HUMANITES
Spiller Address:	18TH-19TH ST
Spiller County:	001
Spiller Contact:	UNKNOWN
Spiller Phone:	(000) 000-0000
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	99023
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 3/12/01 TJD 8000 gallon temporary tank at location. Approximately 1 gallon spilled during fuel delivery. Cleaned up using absorbents by building staff. No further action required."
Remarks:	"temporary tank at location leaking oil onto roadway"

All Materials:

Site ID:	113466
Operable Unit ID:	834540
Operable Unit:	01

SCHOOL OF HUMANITES (Continued) **S104951052**

Material ID:	539732
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

H180 **350 WEST 18TH ST** **NY AST** **A100412801**
ESE **350 WEST 18TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.059 mi.
313 ft. **Site 11 of 15 in cluster H**

Relative: **Higher**
Actual: **17 ft.**

AST:

Name:	350 WEST 18TH ST
Address:	350 WEST 18TH ST
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-219878
Program Type:	PBS
UTM X:	584193.56500
UTM Y:	4510709.32279
Expiration Date:	05/14/2020
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	8448
Affiliation Type:	Emergency Contact
Company Name:	350 W 18 STONE LLC
Contact Type:	Not reported
Contact Name:	FRANK DELGADO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 510-4618
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-06-26

Site Id:	8448
Affiliation Type:	Facility Operator
Company Name:	350 WEST 18TH ST
Contact Type:	Not reported
Contact Name:	GARY REATZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

350 WEST 18TH ST (Continued) **A100412801**

Zip Code:	Not reported
Country Code:	001
Phone:	(917) 647-7001
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-04-21

Site Id:	8448
Affiliation Type:	Facility Owner
Company Name:	350 W 18 STONE LLC
Contact Type:	AUTHORIZED SIGNATORY
Contact Name:	JEFFREY KAYE
Address1:	148 MADISON AVE, 5TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(646) 795-3160
EMail:	INFO@SSPNY.COM
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-06-26

Site Id:	8448
Affiliation Type:	Mail Contact
Company Name:	JEFFREY KAYE
Contact Type:	Not reported
Contact Name:	FRANK DELGADO
Address1:	148 MADISON AVE
Address2:	5TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(646) 795-3160
EMail:	INFO@SSPNY.COM
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-06-26

Tank Info:

Tank Number:	2-219878
Tank Id:	28353
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel

350 WEST 18TH ST (Continued) **A100412801**

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
C01 - Pipe Location - Aboveground

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1978
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MRBARROW
Last Modified:	06/26/2018
Material Name:	#2 fuel oil (on-site consumption)

H181 **CON EDISON** **NY MANIFEST** **S117067460**
ESE **FO 350 W 18 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.059 mi.
313 ft. **Site 12 of 15 in cluster H**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FO 350 W 18 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004603270
Facility Status:	Not reported
Location Address 1:	FO 350 W 18 ST
Code:	BP
Location Address 2:	SB 3249
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004603270
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON (Continued) **S117067460**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/2014
Trans1 Recv Date:	07/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004603270
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504413GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H182 **CON EDISON** **NY MANIFEST** **S117067458**
ESE **FO 350 WEST 18 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.059 mi.
313 ft. **Site 13 of 15 in cluster H**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FO 350 WEST 18 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004603254
Facility Status:	Not reported
Location Address 1:	FO 350 WEST 18 ST
Code:	BP
Location Address 2:	SB 3248
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004603254
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/2014
Trans1 Recv Date:	07/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004603254
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504411GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117067458**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

M183 **CON EDISON SERVICE BOX: 3625** **RCRA NonGen / NLR** **1016150170**
ENE **346 W 20TH ST FRONT OF** **FINDS** **NYP004288411**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.060 mi. **NY MANIFEST**
316 ft. **Site 2 of 10 in cluster M**

Relative: **Higher**
Actual: **17 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20170728
Handler Name:	CON EDISON SERVICE BOX:	3625
Handler Address:		346 W 20TH ST FRONT OF
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004288411
Contact Name:		RICARDO CARTY
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		646-772-3407
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported

CON EDISON SERVICE BOX: 3625 (Continued) **1016150170**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180118
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

CON EDISON SERVICE BOX: 3625 (Continued) **1016150170**

Historic Generators:

Receive Date:		20130212
Handler Name:	CON EDISON SERVICE BOX:	3625
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20170728
Handler Name:	CON EDISON SERVICE BOX:	3625
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		No
Electronic Manifest Broker:		No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055458598

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016150170
Registry ID: 110055458598

CON EDISON SERVICE BOX: 3625 (Continued) **1016150170**

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055458598
Name: CON EDISON SERVICE BOX: 3625
Address: 346 W 20TH ST FRONT OF
City,State,Zip: NEW YORK, NY 10011

NY MANIFEST:
Name: CON EDISON
Address: 346 W 20TH ST FRONT OF
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004288411
Facility Status: Not reported
Location Address 1: F/O 346 E 20TH ST
Code: BP
Location Address 2: SERV BOX 3625
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004288411
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 02/12/2013
Trans1 Recv Date: 02/12/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/15/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004288411
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 010707303JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N

CON EDISON SERVICE BOX: 3625 (Continued) **1016150170**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

N184 **458 WEST 20TH ST** **NY AST** **U003388153**
NNW **458 WEST 20TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.060 mi.
318 ft. **Site 1 of 25 in cluster N**

Relative: **Lower**

Actual: **12 ft.**

AST:

Name:	458 WEST 20TH ST
Address:	458 WEST 20TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-258040
Program Type:	PBS
UTM X:	583994.61290
UTM Y:	4510982.53649
Expiration Date:	08/24/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	10670
Affiliation Type:	Facility Owner
Company Name:	458 WEST 20TH ST OWNERS INC.
Contact Type:	MANAGER
Contact Name:	AVI BEHAR
Address1:	450 SEVENTH AVENUE, SUITE #2107
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10123

458 WEST 20TH ST (Continued) **U003388153**

Country Code:	001
Phone:	(212) 736-3680
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-02-08

Site Id:	10670
Affiliation Type:	Mail Contact
Company Name:	VINTAGE REAL ESTATE SERVICES LTD
Contact Type:	Not reported
Contact Name:	AVI BEHAR
Address1:	11-11 44TH DRIVE
Address2:	2ND FLOOR
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(212) 736-3680
EMail:	AVI@VINTAGERESL.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-02-08

Site Id:	10670
Affiliation Type:	Facility Operator
Company Name:	458 WEST 20TH ST
Contact Type:	Not reported
Contact Name:	ARNOLD HERRGRAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 736-3680
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-02-08

Site Id:	10670
Affiliation Type:	Emergency Contact
Company Name:	458 WEST 20TH ST OWNERS INC.
Contact Type:	Not reported
Contact Name:	AVI BEHAR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 736-3680
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-02-08

458 WEST 20TH ST (Continued) **U003388153**

Tank Info:

Tank Number:	001
Tank Id:	13257
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	07/12/1900
Capacity Gallons:	2000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	02/08/2018
Material Name:	#2 fuel oil (on-site consumption)

I185 **CON EDISON SERVICE BOX: 43063** **RCRA NonGen / NLR** **1016449951**
NW **136 10TH AVE OPPOSITE** **NY MANIFEST** **NYP004256558**
< 1/8 **NEW YORK, NY 10011**
0.060 mi.
319 ft. **Site 16 of 22 in cluster I**

Relative: **Lower**
Actual: **12 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130319
Handler Name:	CON EDISON SERVICE BOX:	43063
Handler Address:		136 10TH AVE OPPOSITE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004256558
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private

CON EDISON SERVICE BOX: 43063 (Continued) **1016449951**

Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No

CON EDISON SERVICE BOX: 43063 (Continued) **1016449951**

Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130219
Handler Name: CON EDISON SERVICE BOX:	43063
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130319
Handler Name: CON EDISON SERVICE BOX:	43063
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	136 10TH AVE OPPOSITE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA

CON EDISON SERVICE BOX: 43063 (Continued) **1016449951**

EPA ID:	NYP004256558
Facility Status:	Not reported
Location Address 1:	OPP 136 10TH AVE
Code:	BP
Location Address 2:	SERV BOX 43063
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004256558
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/19/2013
Trans1 Recv Date:	02/19/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004256558
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840423JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON SERVICE BOX: 43063 (Continued) **1016449951**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

O186 **CON EDISON SERVICE BOX: 3777** **RCRA NonGen / NLR** **1016967679**
NNE **432 W 21ST ST FRONT OF** **NYP004412771**
< 1/8 **NEW YORK, NY 10011**
0.062 mi.
328 ft. **Site 1 of 9 in cluster O**

Relative: **Higher**
Actual: **14 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140206
Handler Name:	CON EDISON SERVICE BOX:	3777
Handler Address:		432 W 21ST ST FRONT OF
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004412771
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No

CON EDISON SERVICE BOX: 3777 (Continued) **1016967679**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140106
Handler Name: CON EDISON SERVICE BOX:	3777
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON SERVICE BOX: 3777 (Continued) **1016967679**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140206
Handler Name: CON EDISON SERVICE BOX:	3777
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

P187 **CON EDISON - MANHOLE 9536** **NY MANIFEST** **S121968548**
NE **179 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.062 mi.
328 ft. **Site 1 of 17 in cluster P**

Relative:
Higher

Actual:
16 ft.

NY MANIFEST:

Name:	CON EDISON - MANHOLE 9536
Address:	179 9TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP005127950
Facility Status:	Not reported
Location Address 1:	179 9TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005127950
Mailing Name:	CON EDISON - MANHOLE 9536
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL

CON EDISON - MANHOLE 9536 (Continued) **S121968548**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

P188 **CON EDISON - MANHOLE 9536** **RCRA-LQG** **1024891618**
NE **179 9TH AVE** **NYP005127950**
< 1/8 **NEW YORK, NY 10011**
0.062 mi.
328 ft. **Site 2 of 17 in cluster P**

Relative: RCRA-LQG:
Higher

Date Form Received by Agency:	20180410
Handler Name:	CON EDISON - MANHOLE 9536
Handler Address:	179 9TH AVE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP005127950
Contact Name:	ALYSSA SOTTO
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported

Actual:
16 ft.

CON EDISON - MANHOLE 9536 (Continued) **1024891618**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20170817
Date Ended Current:	Not reported

CON EDISON - MANHOLE 9536 (Continued) **1024891618**

Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-460-2757
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20170817
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-460-2757
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20180410
Handler Name:	CON EDISON - MANHOLE 9536
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

J189 **CON EDISON** **NJ MANIFEST** **S120672284**
SSW **402 W 15TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.062 mi.
330 ft. **Site 14 of 35 in cluster J**

Relative: **Higher**
Actual: **15 ft.**

NJ MANIFEST:

EPA Id:	NYP004788501
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported

CON EDISON (Continued) **S120672284**

Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002614103GBF
EPA ID:	NYP004788501
Date Shipped:	6/1/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

J190 **CON EDISON** **RCRA NonGen / NLR** **1019903673**
SSW **402 W 15TH ST** **NYP004788501**
< 1/8 **NEW YORK, NY 10011**
0.062 mi.
330 ft. **Site 15 of 35 in cluster J**

Relative: **Higher**
Actual: **15 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150601
Handler Name:	CON EDISON	
Handler Address:		402 W 15TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004788501
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1019903673**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1019903673**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

J191 **CON EDISON** **NY MANIFEST** **S118091180**
SSW **402 W 15TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.062 mi.
330 ft. **Site 16 of 35 in cluster J**

Relative:
Higher

Actual:
15 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	402 W 15TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004788501
Facility Status:	Not reported
Location Address 1:	402 W 15TH ST
Code:	BP
Location Address 2:	SB 2574
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004788501
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/01/2015
Trans1 Recv Date:	06/01/2015

CON EDISON (Continued) **S118091180**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/03/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004788501
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002614103GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L192 **CON EDISON - SERVICE BOX 3009** **NY MANIFEST** **S123692534**
SE **347 W 17TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.063 mi.
331 ft. **Site 2 of 18 in cluster L**

Relative: NY MANIFEST:
Higher

Name:	CON EDISON - SERVICE BOX 3009
Address:	347 W 17TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP005215645
Facility Status:	Not reported
Location Address 1:	347 W 17TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported

Actual:
17 ft.

CON EDISON - SERVICE BOX 3009 (Continued) **S123692534**

Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP005215645
Mailing Name: CON EDISON - SERVICE BOX 3009
Mailing Contact: ANNAMARIE MOYLAN
Mailing Address 1: 4 IRVING PLACE 15TH FL NE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602278

K193 **430 WEST 15TH STREET** **NY UST** **U004227342**
SW **430 WEST 15TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10017**
0.063 mi.
331 ft. **Site 7 of 28 in cluster K**

Relative:
Lower

Actual:
12 ft.

UST:
Name: 430 WEST 15TH STREET
Address: 430 WEST 15TH STREET
City,State,Zip: NEW YORK, NY 10017
Id/Status: 2-612360 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 583935.09019
UTM Y: 4510590.25454
Site Type: Other

Affiliation Records:
Site Id: 504139
Affiliation Type: Facility Owner
Company Name: BRK GARAGE CO., LLC C/O WOHL, FRIED & KIRCHENBERG
Contact Type: MANAGER, BRK GARAGE, LLC
Contact Name: DANNY BENAU
Address1: 3 COLUMBUS CIR., SUITE 1420
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019-1903
Country Code: 001
Phone: (212) 586-0800
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2015-01-27

Site Id: 504139
Affiliation Type: Mail Contact
Company Name: C/O ATLAS CAPITAL GROUP LLC

430 WEST 15TH STREET (Continued) **U004227342**

Contact Type:	Not reported
Contact Name:	STEPHEN NUCKEL, 15TH STREET LESSEE LLC
Address1:	505 FIFTH AVENUE
Address2:	28TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 554-2250
EMail:	SNUCKEL@ATLAS-CAP.COM
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2015-01-27

Site Id:	504139
Affiliation Type:	Facility Operator
Company Name:	430 WEST 15TH STREET
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	N/A
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2015-01-27

Site Id:	504139
Affiliation Type:	Emergency Contact
Company Name:	BRK GARAGE CO., LLC C/O WOHL, FRIED & KIRCHENBERG
Contact Type:	Not reported
Contact Name:	DANNY BENAU
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(610) 864-1901
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2015-01-27

Tank Info:

Tank Number:	001
Tank ID:	254339
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/06/2014

430 WEST 15TH STREET (Continued) **U004227342**

Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NTFREEMA
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number:	002
Tank ID:	254340
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/06/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NTFREEMA
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Number: 003

430 WEST 15TH STREET (Continued) **U004227342**

Tank ID:	254341
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/06/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NTFREEMA
Last Modified:	04/14/2017

Equipment Records:

L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	004
Tank ID:	254342
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/06/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NTFREEMA
Last Modified:	04/14/2017

Equipment Records:

J00 - Dispenser - None
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

430 WEST 15TH STREET (Continued) **U004227342**

D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None

K194 **455 WEST 15TH STREET** **NY Spills** **S104495606**
WSW **455 WEST 15TH STREET** **N/A**
< 1/8 **NYC, NY**
0.063 mi.
332 ft. **Site 8 of 28 in cluster K**

Relative:
Lower

Actual:
11 ft.

SPILLS:

Name:	455 WEST 15TH STREET
Address:	455 WEST 15TH STREET
City,State,Zip:	NYC, NY
Spill Number/Closed Date:	9312219 / 1994-01-17
Facility ID:	9312219
Facility Type:	ER
DER Facility ID:	172644
Site ID:	208077
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	1994-01-17
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1994-01-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	1994-01-17
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-01-20
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"CONTAINERS INSIDE BLDG UNMARKED - NO ACTIONS TAKEN BACK."

All Materials:

Site ID:	208077
Operable Unit ID:	990840
Operable Unit:	01
Material ID:	391209
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported

455 WEST 15TH STREET (Continued) **S104495606**

Recovered: .00
Oxygenate: Not reported

L195 **RESIDENCE/APARTMENT BUILDING** **NY Spills** **S113916274**
SSE **347 WEST 16TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.063 mi.
332 ft. **Site 3 of 18 in cluster L**

Relative:
Higher

Actual:
17 ft.

SPILLS:

Name:	RESIDENCE/APARTMENT BUILDING
Address:	347 WEST 16TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	1306529 / 2013-09-24
Facility ID:	1306529
Facility Type:	ER
DER Facility ID:	442254
Site ID:	487151
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	2013-09-21
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2013-09-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-09-21
Spill Record Last Update:	2013-09-24
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JENNIFER SALINAS
DEC Memo:	"09/21/13-Hiralkumar Patel. 4:25 AM:- left message for Jennifer. 09/23/13-Hiralkumar Patel. 12:49 PM:- left message for Jennifer. 09/24/13-Hiralkumar Patel. 9:00 AM:- went to site for inspection, but no access. spoke with Jennifer. she mentioned that FDNY responded on 09/21/13 and found issues with boiler. super fixed the boiler and there is no more smoke in building. case closed."
Remarks:	"JENNIFER NOTICED THAT LAST EVENING SHE NOTICED A STRONG ODOR IN THE APARTMENT COMPLEX. THE ODOR HAD SUBSIDED BUT HAS COME BACK AND IS STRONGER. DOES NOT SMELL LIKE GAS. SHE HAS NOTICED A BLACK ASHE COMING FROM HER NOSE FROM THE ODOR AND IT GIVES HER A HEADACHE."

All Materials:

Site ID:	487151
Operable Unit ID:	1236782

RESIDENCE/APARTMENT BUILDING (Continued) **S113916274**

Operable Unit:	01
Material ID:	2236292
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

L196 **347 WEST 16 STREET LLC** **NY AST** **A100178196**
SSE **347 WEST 16TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.063 mi.
332 ft. **Site 4 of 18 in cluster L**

Relative:
Higher

Actual:
17 ft.

AST:

Name:	347 WEST 16 STREET LLC
Address:	347 WEST 16TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-605961
Program Type:	PBS
UTM X:	584140.32127
UTM Y:	4510593.68441
Expiration Date:	06/07/2026
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	27826
Affiliation Type:	Mail Contact
Company Name:	BENEDICT PROPERTIES LLC
Contact Type:	Not reported
Contact Name:	D. BENEDICT
Address1:	150 GREAT NECK ROAD, SUITE 402
Address2:	Not reported
City:	GREAT NECK
State:	NY
Zip Code:	11021
Country Code:	001
Phone:	(516) 498-9100
EMail:	BARRY.SENDROVIC@BRGNY.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-05-13

Site Id:	27826
Affiliation Type:	Emergency Contact
Company Name:	347 WEST 16 LLC
Contact Type:	Not reported
Contact Name:	D. BENEDICT
Address1:	Not reported
Address2:	Not reported
City:	Not reported

347 WEST 16 STREET LLC (Continued) **A100178196**

State: NN
Zip Code: Not reported
Country Code: 999
Phone: (516) 498-9100
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-04-26

Site Id: 27826
Affiliation Type: Facility Operator
Company Name: 347 WEST 16 STREET LLC
Contact Type: Not reported
Contact Name: FRANK LUGO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (516) 369-0908
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-05-13

Site Id: 27826
Affiliation Type: Facility Owner
Company Name: 347 WEST 16, LLC
Contact Type: OFFICER
Contact Name: BARRY SENDROVIC
Address1: 150 GREAT NECK RD. SUITE 402
Address2: Not reported
City: GREAT NECK
State: NY
Zip Code: 11021
Country Code: 001
Phone: (516) 498-9100
EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2021-05-04

Tank Info:

Tank Number: 01
Tank Id: 60765
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

347 WEST 16 STREET LLC (Continued) **A100178196**

G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
D10 - Pipe Type - Copper

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel Tank in Concrete
Tank Status:	In Service
Pipe Model:	F
Install Date:	03/01/1905
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MRBARROW
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

J197 **AABIS SERVICE STATION INC** **EDR Hist Auto** **1020900253**
SSW **65 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.064 mi.
336 ft. **Site 17 of 35 in cluster J**

Relative: EDR Hist Auto
Higher

Actual:
15 ft.

Year:	Name:	Type:
1982	AABIS SERVICE STATION INC	Gasoline Service Stations
1983	AABIS SERVICE STATION INC	Gasoline Service Stations
1985	AABIS SERVICE STATION INC	Gasoline Service Stations
1986	AABIS SERVICE STATION INC	Gasoline Service Stations
1987	AABIS SERVICE STATION INC	Gasoline Service Stations
1988	AABIS SERVICE STATION INC	Gasoline Service Stations
1989	AABIS SERVICE STATION INC	Gasoline Service Stations
1989	ABBIS	Gasoline Service Stations
1990	ABBIS	Gasoline Service Stations
1990	AABIS SERVICE STATION INC	Gasoline Service Stations
1991	AABIS SERVICE STATION INC	Gasoline Service Stations
1991	ABBIS	Gasoline Service Stations
1992	AABIS SERVICE STATION INC	Gasoline Service Stations
1992	ABBIS	Gasoline Service Stations
1993	ABBIS	Gasoline Service Stations
1993	AABIS SERVICE STATION INC	Gasoline Service Stations
1994	ABBIS	Gasoline Service Stations
1994	AABIS SERVICE STATION INC	Gasoline Service Stations
1995	ABBIS	Gasoline Service Stations

I198 **456 WEST 19TH STREET, LLC** **NY UST** **U004047610**
NW **456 WEST 19TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.065 mi.
344 ft. **Site 17 of 22 in cluster I**

Relative:
Lower

Actual:
12 ft.

UST:

Name:	456 WEST 19TH STREET, LLC
Address:	456 WEST 19TH STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-609333 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583916.11737
UTM Y:	4510925.71767
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	31177
Affiliation Type:	Facility Operator
Company Name:	456 WEST 19TH STREET, LLC
Contact Type:	Not reported
Contact Name:	MIKE SARACCO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 989-5370
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-05-12

Site Id:	31177
Affiliation Type:	Emergency Contact
Company Name:	140 WEST 19TH STREET, LLC
Contact Type:	Not reported
Contact Name:	T.G. NICKEL ASSOC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(631) 738-7750
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-05-12

Site Id:	31177
Affiliation Type:	Facility Owner
Company Name:	140 WEST 19TH STREET, LLC
Contact Type:	Not reported
Contact Name:	\\
Address1:	56 WEST 22ND STREET, 5TH FLOOR

456 WEST 19TH STREET, LLC (Continued) **U004047610**

Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10010
Country Code:	001
Phone:	(212) 414-2701
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-05-12

Site Id:	31177
Affiliation Type:	Mail Contact
Company Name:	456 WEST 18TH STREET LLC
Contact Type:	Not reported
Contact Name:	ROSA CHANG
Address1:	% TAMARKIN DVLPT 10TH AVE LLC
Address2:	56 WEST 22ND STREET, 5TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10010
Country Code:	001
Phone:	(212) 414-2701
EMail:	ROSA@TAMARKINCO.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-05-12

Tank Info:

Tank Number:	001
Tank ID:	67159
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	551
Install Date:	Not reported
Date Tank Closed:	04/06/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

I00 - Overfill - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None

456 WEST 19TH STREET, LLC (Continued) **U004047610**

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	002
Tank ID:	67160
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	551
Install Date:	Not reported
Date Tank Closed:	04/06/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

K199 **FORMER PARKING GARAGE/FUTURE OFFICES** **NY Spills** **S113818221**
SW **422-430 WEST 15TH STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.065 mi.
344 ft. **Site 9 of 28 in cluster K**

Relative:
Lower

Actual:
13 ft.

SPILLS:

Name:	FORMER PARKING GARAGE/FUTURE OFFICES
Address:	422-430 WEST 15TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	1303087 / 2014-09-30
Facility ID:	1303087
Facility Type:	ER
DER Facility ID:	438763
Site ID:	483554
DEC Region:	2

FORMER PARKING GARAGE/FUTURE OFFICES (Continued) **S113818221**

Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2013-06-21
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2013-06-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-06-21
Spill Record Last Update:	2014-09-30
Spiller Name:	DANIEL CARRUS
Spiller Company:	PARKING GARAGE
Spiller Address:	422-430 W 15TH ST
Spiller Company:	999
Contact Name:	DANIEL CARRUS
DEC Memo:	"06/21/13-Zhune spoke to Daniel Carrus from Langan Engineering 646-434-8211. He said client is doing real state transaction. As part of due diligence langan conducted investigation at this site. During investigation they found staining, elevated PID and odors in the soil. They installed four borings arround the tank and three borings downgradient the tank. They collected samples of soil and groundwater. The analytical results indicated no exceedance in the soil. Groundwater indicated elevated VOCs in couple of locations. Once they completed the investigation report they will send a copy to DEC. 08/05/13- Zhune received and reviewed the Phase II Report dated 07/25/13. The site building will be renovated for commercial usage as retail and office space. Proposed site redevelopment will consist of converting the basement area for usage as a restaurant or retail space, and converting of the above -grade parking areas to office space. Seven soil borings were installed. Two borings SB-1(MW) and SB-2(MW) were installed along West 15th steert near Anomaly 1. The remaining borings SB-3 through SB-7 were installed in the basement of the building near to anamaly 2. The soil analitycal result detected four VOCs at concentrations exceeding the limit: 1,2,3 -trimethyl benzene (5.1 mg /kg) in SB-3 6-8')and TPO1 (54 mg/kg) (4 0; 1,3,5 -trimethyl benzene (56 mg/kg)in TP01 (4); Ethylbenzene (2.1 mg/kg) and n-propylbenzene (6.2 mg/kg) in SB-4(MW)(5-9') The Groundwater analitycal result detected concentrations of VOCs exceeeding the limit in groundwater samples collected from SB-2(MW) and SB-4(MW): 1,2,4,5 tetramethylbenzene (7 ug/l) in sample SB-2(MW) and (49 ug/l) in sample SB-4(MW) 1,2.4-trimethybenzene (33 ug/l) in sample SB-4(MW) and (8.9 ug/l) in sample SB-2(MW). 1,3,5-trimethybenzene(33 mg/kr), Ethylbenzen(480 mg/kg), Isopropylbenzene(58 ug/l), n-ptopylbenzene(120 ug/l), P/m-xylene(49 ug/l)and tricloroethene in sample SB-4(MW) Langan recommended to expose the area of anomaly 1 (removal of the oncrete floor and soil as necessary to confirm the presence and conditons of USTS. 08/05/13-Zhune spoke to Daniel Carro. He said Langan is going to send the work plan. Work activities at

FORMER PARKING GARAGE/FUTURE OFFICES (Continued) **S113818221**

this site are going to star in February. 12/18/13-Zhune received and reviewed the work plan dated 12/18/13. The plan includes 1. Removal of the concrete slab in anomaly 1, exposing suspected tank and evaluating 2.Decommission, closure and the removal of the suspected USTs identified inthevacinity of anolay 1 3.Removal of soil with concnetration s of petroleum-related contaminants above the NYSDEC CP-51 4. Dewatering and disposal of groundwater, where necessary, to complete the removal od USTs and remedial excavation. 5.collection and analysis of endpoint samples soil and groundwater samples. 6. Bench-scale pilot study for determining ISCO parameters (If required, based on the endpoint sampling results) 7. Site restoration-backfilling of remedial excavation area to development grade with certified fill. Submission of a Remedial Action Report (RAR). 01/15/14-In a letter dated January 15, 2014 the Department approved the Remedial Action Plan. 02/26/14- Ilka sent the following email dated 02/26/14 As discussed last week and earlier today, the tank closure activities started on 2/14/2013. Based on the site observations, there are four 550-gallon tanks onsite. After the basement slab and the soil between the slab and concrete encasement were removed, we found that the concrete encasement of the tanks is placed in very close proximity to the building foundation elements (see attached cross section). In particular, the northernmost tank (Tank #1) is abutting the northern building foundation and exterior wall, and the portion of the southernmost tank (Tank #4) is situated adjacent and below the two column footings. Continuous dewatering requirement and location of tanks and encasement raised questions and concerns over the removal of the tanks and the stability of the building foundation elements. We consulted with our in-house geotechnical engineer and the client's structural engineer. Although our approved Remedial Action Plan proposed the removal of the tanks, based on the findings, the geotechnical and structural engineers recommended that the tanks be closed in place and not to be removed in order not to compromise the structural integrity and stability of the building. The closure activities will still include removal of all piping and contents of the tanks and cleaning of the tanks. After the tanks are cleaned, they will be filled with concrete, and impacted soil around the tanks (to the east and south) will be excavated to an extent practical and feasible. Following completion of the tank closure and soil removal activities, we will collect endpoint soil samples from the eastern and southern part of the tank excavation. Groundwater samples will be collected from the existing monitoring wells located on the sidewalk. We also collected soil and groundwater samples from the excavation for treatability study. When we have the results of endpoint soil and groundwater and treatability study results, we will present them to you for further discussions. The details of the tank closure activities and all associated data, documentation, and manifest will be included in our tank/spill closure report. 02/27/14-Ilka sent the following email: The site activities are still ongoing and tanks will be filled with concrete tomorrow and the site will be restored on Monday. Today, we removed some impacted soil from south and east sides of the tanks to an extent possible. Because the groundwater table is at about 6 inches below the basement slab, all soil around the tank encasement is saturated. As you know, we can only do small amounts of dewatering because of the location of the tanks and building foundation elements. Therefore, we will not be collecting any soils samples. We will collect groundwater samples from the two existing monitoring

FORMER PARKING GARAGE/FUTURE OFFICES (Continued) **S113818221**

wells on West 15th Street (see the site plan for well locations). The monitoring well, SB4(MW) was destroyed during the tank closure activities. We will reinstall and sample this well also. 3/11/14- Ilkay sent the following email. the email stated the following As discussed, we install the monitoring well on the south side of the tank excavation last week. The well was developed on Friday, March 7, 2014. We would like to sample the new well and also the other two wells on the sidewalk, tomorrow. 3/11/14- Ilkay sent the following email. As discussed on our phone conversation, we will be conducting the groundwater sampling tomorrow 4/24/14-Vought-DEC Zhune out of office on extended vacation. Vought received email from Langan (Spanos) on 4/17 that Jeff,I understand from Veronica s voice message recording that she is out of the office until May 7th. Based on my earlier conversations with her, and since you are already aware of this project; I would like to give you an update and discuss the results of our tank closure activities and groundwater sampling results early next week. Below is the summary of the tank closure activities conducted at the site in February and March 2014: Langan contracted Brookside Environmental (Brookside) for the closure of four 550-gallon underground storage tanks (USTs). After removal of the cellar slab on top of the tank area in the cellar level of the building on site, Brookside excavated the soil between the cellar slab and tanks concrete encasement. The excavated material exhibited evidence of petroleum impacts, odor, staining, and photoionization detector (PID) readings of up to 200 parts per million (ppm). During soil removal, groundwater was encountered within a foot below the cellar level. Therefore, dewatering was necessary during soil removal and tank closure activities. Due to structural concerns arising from the tanks proximity to column footings and foundation walls, we were not able to remove the tanks. This was discussed with Veronica, and following her approval, the tanks were closed in place after cutting them open and cleaning. Following is the summary of the material removed offsite: o Two drums of residual sludge derived from tank cleaning was disposed of at the Clean Water of New York facility in Staten Island, New York. Tanks were found to be intact and no holes were observed at the bottom of the tanks. o Petroleum-impacted soil was stockpiled on and covered with poly onsite until the waste characterization sampling results were received, reviewed and approved by a disposal facility. Stockpiled material was loaded onto approximately 20 cubic yard dump truck approved under New York State Department of Environmental Conservation (NYSDEC) Part 364 permit No. PA-263 for off-site disposal at the Clean Earth of Carteret facility in Carteret, New Jersey. o Petroleum-impacted concrete was loaded into one approximately 20 cubic yard truck-mounted roll-off container approved under NYSDEC Part 364 permit No. PA-263 for off-site disposal at the Clean Earth of New Jersey facility in Kearny, New Jersey. o A total of approximately 42,650 gallons of groundwater derived from excavation dewatering was pumped into holding tanks on site than it was disposed of at the Clean Water of New York facility in Staten Island, New York by vacuum trucks. Following our discussions with the case manager, tanks were backfilled with concrete and the remainder of the excavation was backfilled with -inch gravel followed by replacement of the concrete floor slab. Because of the shallow groundwater table, soil around the tank was saturated; therefore, no soil samples were collected for laboratory analysis, as per our discussions with the case manager. During tank closure activities, monitoring well SB-4(MW) located south of the

FORMER PARKING GARAGE/FUTURE OFFICES (Continued) **S113818221**

USTs in the cellar level was destroyed. Under Langan oversight, Eastern Environmental installed a new 1-inch groundwater monitoring well, SB-4R(MW), to replace destroyed monitoring well MW-4. Following development of the new monitoring well, Langan collected groundwater samples from monitoring wells SB-1(MW) and SB-2(MW) which are located on West 15th Street sidewalk, and SB-4R(MW) on 3/12/2014 (see attached figure for well locations). o Groundwater analytical results from the 3/12/2014 sampling event were significantly lower compared to the samples collected on 6/14/2013. There were no concentrations above TOGS AWQS except for cis-1,2-dichloroethene (offsite well SB-2[MW]), sodium, and iron. The attached figure shows the results from both sampling events, and the groundwater analytical results are summarized in the attached table. The source of the spill was identified as the USTs/associated piping which were removed in accordance with city, state and federal regulations. The NYSDEC PBS registration was updated accordingly, and post excavation/tank closure groundwater sampling indicated no impacts. Based on these conclusions, we are recommending that the spill No. 1303087 be closed. We will compile the details of site activities, soil and groundwater disposal, and analytical data into a report and submit it to you in couple of weeks. Copies of all the manifests, truck permits, tank closure affidavit, and facility approval letter will be included in the closure report. Please let me know if Tuesday or Wednesday of next week (April 22 or 23) 10AM is convenient for your to discuss the above information. Thanks, Ilkay.
4/24/14-Vought-Called and spoke to Langan (Spanos) and based on above and as well as discussion had with Spanos that noted new groundwater samples at MW4R that are non-detect for petroleum related VOCS, that she should submit a Closure Report to DEC Zhune. Vought replied to Spanos email dated 4/22 that Ilkay, As per our telephone discussion today, the Department has reviewed the below and if no new information is noted apart from the below in the report (once received and reviewed) the Department will close the Spill Case. We look forward to receiving the Closure Report you noted below, Thanks.
9/30/14- Spill closure Report received. Spill Closed."

Remarks: "5-7 UST on site suspected of leaking. Further action and cleanup is pending investigation."

All Materials:

Site ID:	483554
Operable Unit ID:	1233258
Operable Unit:	01
Material ID:	2232147
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

K200 **CON EDISON - MANHOLE 2573** **NJ MANIFEST** **S120677832**
SW **412 W 15TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.065 mi.
345 ft. **Site 10 of 28 in cluster K**

Relative:
Lower

Actual:
13 ft.

NJ MANIFEST:

EPA Id:	NYP004866644
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002613524GBF
EPA ID:	NYP004866644
Date Shipped:	11/12/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON - MANHOLE 2573 (Continued) **S120677832**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported
Manifest Number:	002613762GBF
EPA ID:	NYP004866644
Date Shipped:	12/15/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported
Manifest Number:	002613390GBF
EPA ID:	NYP004866644
Date Shipped:	11/6/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

CON EDISON - MANHOLE 2573 (Continued) **S120677832**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Manifest Number:	002613439GBF
EPA ID:	NYP004866644
Date Shipped:	11/9/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported

CON EDISON - MANHOLE 2573 (Continued) **S120677832**

QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

K201 **CON EDISON - MANHOLE 2573** **RCRA-LQG 1019325869**
SW **412 W 15TH ST** **FINDS NYP004866644**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.065 mi.
345 ft. **Site 11 of 28 in cluster K**

Relative: **Lower**
Actual: **13 ft.**

RCRA-LQG:

Date Form Received by Agency:	20160226
Handler Name:	CON EDISON - MANHOLE 2573
Handler Address:	412 W 15TH ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004866644
Contact Name:	THERESA BURKARD
Contact Address:	IRVING PL 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2262
Contact Fax:	Not reported
Contact Email:	BURKARDT@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2015
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON CO OF NY INC
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON CO OF NY INC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No

CON EDISON - MANHOLE 2573 (Continued) **1019325869**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161107
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008

CON EDISON - MANHOLE 2573 (Continued) **1019325869**

Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON CO OF NY INC
Legal Status: Private
Date Became Current: 20151106
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON CO OF NY INC
Legal Status: Private
Date Became Current: 20151106
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160226
Handler Name: CON EDISON - MANHOLE 2573
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069379853

CON EDISON - MANHOLE 2573 (Continued) **1019325869**

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019325869
Registry ID:	110070433324
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070433324
Name:	CON EDISON - VAULT 22505
Address:	412 W 15TH ST
City,State,Zip:	NEW YORK, NY 10011

Envid:	1019325869
Registry ID:	110069379853
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069379853
Name:	CON EDISON - MANHOLE 2573
Address:	412 W 15TH ST
City,State,Zip:	NEW YORK, NY 10011

K202 **CON EDISON - VAULT 22505** **RCRA-LQG** **1024891022**
SW **412 W 15TH ST** **NYP005064621**
< 1/8 **NEW YORK, NY 10011**
0.065 mi.
345 ft. **Site 12 of 28 in cluster K**

Relative: **Lower**
Actual: **13 ft.**

RCRA-LQG:

Date Form Received by Agency:		20180410
Handler Name:	CON EDISON - VAULT 22505	
Handler Address:		412 W 15TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP005064621
Contact Name:		ALYSSA SOTTO
Contact Address:		IRVING PLACE, 15TH FL NE
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-2757
Contact Fax:		Not reported
Contact Email:		SOTTOA@CONED.COM
Contact Title:		ASSOCIATE SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Large Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		2017
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PLACE, 15TH FL NE

CON EDISON - VAULT 22505 (Continued) **1024891022**

Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

CON EDISON - VAULT 22505 (Continued) **1024891022**

Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170412
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170412
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180410
Handler Name: CON EDISON - VAULT 22505
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

CON EDISON - VAULT 22505 (Continued) **1024891022**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

K203 **CON EDISON - VAULT 22505** **NY MANIFEST** **S121967936**
SW **412 W 15TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.065 mi.
345 ft. **Site 13 of 28 in cluster K**

Relative: **Lower**
Actual: **13 ft.**

NY MANIFEST:

Name:	CON EDISON - VAULT 22505
Address:	412 W 15TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP005064621
Facility Status:	Not reported
Location Address 1:	412 W 15TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005064621
Mailing Name:	CON EDISON - VAULT 22505
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

K204 **CON EDISON** **NY MANIFEST** **S119078232**
SW **412 W 15TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.065 mi.
345 ft. **Site 14 of 28 in cluster K**

Relative: **Lower**
Actual: **13 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	412 W 15TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004866644
Facility Status:	Not reported

CON EDISON (Continued) **S119078232**

Location Address 1: 412 W 15 ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004866644
Mailing Name: CON EDISON
Mailing Contact: CON ED
Mailing Address 1: 4 IRVING PL 15TH FL NE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

K205 **408 W 15TH ST/MANHATTAN** **NY Spills** **S104495248**
SSW **408 WEST 15TH STREET** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.066 mi.
346 ft. **Site 15 of 28 in cluster K**

Relative:
Higher

Actual:
14 ft.

SPILLS:
Name: 408 W 15TH ST/MANHATTAN
Address: 408 WEST 15TH STREET
City,State,Zip: NEW YORK CITY, NY
Spill Number/Closed Date: 9004861 / 1990-08-01
Facility ID: 9004861
Facility Type: ER
DER Facility ID: 143895
Site ID: 170999
DEC Region: 2
Spill Cause: Human Error
Spill Class: Not reported
SWIS: 3101
Spill Date: 1990-08-01
Investigator: WILSON
Referred To: Not reported
Reported to Dept: 1990-08-01
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Police Department
Cleanup Ceased: 1990-08-01
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1990-08-08
Spill Record Last Update: 2004-09-30

408 W 15TH ST/MANHATTAN (Continued) **S104495248**

Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"55 GAL DRUM OF METHYL MAPHACRYLAPE SPILLED WHEN THE DRUM WAS BEING TRANSFERRED FROM THE BUILDING TO THE VEHICLE, NYCDEP RESPONDED, SPILL CLEANED UP."

All Materials:

Site ID:	170999
Operable Unit ID:	945347
Operable Unit:	01
Material ID:	562114
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

J206 **PRINCE LUMBER COMPANY** **NY Spills** **S106009573**
SSW **404 WEST 15TH STREET** **N/A**
< 1/8 **NEW YORK, NY**
0.066 mi.
346 ft. **Site 18 of 35 in cluster J**

Relative: **Higher**

Actual: **14 ft.**

SPILLS:

Name:	PRINCE LUMBER COMPANY
Address:	404 WEST 15TH STREET
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0208837 / 2004-06-15
Facility ID:	0208837
Facility Type:	ER
DER Facility ID:	198399
Site ID:	241295
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2002-11-26
Investigator:	CESAWYER
Referred To:	Not reported
Reported to Dept:	2002-11-26
CID:	204
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

PRINCE LUMBER COMPANY (Continued) **S106009573**

Date Entered In Computer:	2002-11-26
Spill Record Last Update:	2004-06-15
Spiller Name:	GUY APICELLA
Spiller Company:	PRINCE LUMBER COMPANY
Spiller Address:	404 WEST 15TH STREET
Spiller Company:	001
Contact Name:	JOHN BRENNAN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 12:00pm called John Brennan requested to call back for inf. update. 12:28pm affected area 15 x 12'. 2 lift removed hoses are still there. contaminated soil found. RP willing to spend up the clean up process. dirty soil letter sent to owner and faxed to contractor. faxed 973-781-1804 x 15. 12/17/2002-Vought-Spoke with Kevin Ziegler (973-781-1801, Brennan Environmental Inc.) who was hired by property owner (Prince Lumber, Guy Appicello). Brennan will excavate impacted area and analyze 5 endpoint soil samples for STARS 8270. Will send closure report by 2/15/02. 12/31/2002-Vought-Spoke with Kevin Ziegler. They encountered 275 UST waste oil tank. Tank was removed and PBS registration will be ammended. Tank was in poor condition (holes). Will add STARS 8260 to analyses. Will send report by 2/15/2003. 1/23/2004-Vought-Spill transferred from Vought to Austin. 1/27/04 - Sawyer - Spill transferred from Austin to Sawyer. 4/27/04 - Sawyer - Called Kevin Ziegler of Brennan and requested closure documentation for this site. There was a final report, which the Department did not have a copy. Kevin is mailing the report as soon as possible. I will review the report upon receipt. 5/03/04 - Sawyer - I received the report from Brennan Environmental. I am presently reviewing the report. 6/15/04 - Sawyer - Though there are some semi-volatiles which are barely above TAGM levels for clean up most of the samples analyzed did not detect any other contatmination. No further action required. Closed."
Remarks:	"HYDROLIC LIFT REMOVAL"

All Materials:

Site ID:	241295
Operable Unit ID:	862020
Operable Unit:	01
Material ID:	515828
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

J207 **LOT 38,TAXBLOCK 712** **NY E DESIGNATION** **S118191072**
SSW **404 WEST 15 STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.066 mi.
346 ft. **Site 19 of 35 in cluster J**

Relative: **Higher**
Actual: **14 ft.**

E DESIGNATION:

Name:	LOT 38,TAXBLOCK 712
Address:	404 WEST 15 STREET
City,State,Zip:	MANHATTAN, NY

LOT 38,TAXBLOCK 712 (Continued) **S118191072**

Tax Lot(s):	38
Tax Block:	712
Borough Code:	Not reported
E-No:	E-350
Effective Date:	1/22/2015
Satisfaction Date:	Not reported
Ceqr Number:	15DCP037M
Ulurp Number:	150101ZMM, 150102ZRM
Zoning Map No:	8b
Description:	Exhaust stack location limitations
Lot Remediation Date:	8/3/2018
Description:	Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date:	8/3/2018

M208 **CON EDISON** **NY MANIFEST** **S117067398**
East **FO 349 W 19 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.066 mi.
346 ft. **Site 3 of 10 in cluster M**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FO 349 W 19 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004602041
Facility Status:	Not reported
Location Address 1:	FO 349 W 19 ST
Code:	BP
Location Address 2:	SB 3429
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004602041
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported

CON EDISON (Continued) **S117067398**

Generator Ship Date:	07/21/2014
Trans1 Recv Date:	07/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004602041
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002608433GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

K209 **CON EDISON** **RCRA NonGen / NLR** **1014395776**
SW **440 W 15TH ST** **NJ MANIFEST** **NYP004172425**
< 1/8 **NEW YORK, NY 10014** **NY MANIFEST**
0.066 mi.
348 ft. **Site 16 of 28 in cluster K**

Relative: **Lower**
Actual: **12 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		440 W 15TH ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004172425
Contact Name:		PATRICK HANLEY
Contact Address:		Not reported
Contact City,State,Zip:		Not reported

CON EDISON (Continued) **1014395776**

Contact Telephone:	347-203-1475
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1014395776**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160726
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090609
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON (Continued) **1014395776**

NJ MANIFEST:

EPA Id:	NYP004172425
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	PATRICK HANLEY
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	003534451JJK
EPA ID:	NYP004172425
Date Shipped:	06/09/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/09/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/11/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported

CON EDISON (Continued) **1014395776**

Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 2000 P

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 440 W 15TH ST
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYP004172425
Facility Status: Not reported
Location Address 1: F/O 440 W 15TH ST & 10TH AVE
Code: BP
Location Address 2: SB# 2571
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004172425
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: CONSOLIDATED EDISON
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 06/09/2009
Trans1 Recv Date: 06/09/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/11/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004172425
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported

CON EDISON (Continued) **1014395776**

TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003534451JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H210 **CON EDISON** **NY MANIFEST** **S117067462**
ESE **FO 332 WEST 18 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.066 mi.
349 ft. **Site 14 of 15 in cluster H**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FO 332 WEST 18 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004603296
Facility Status:	Not reported
Location Address 1:	FO 332 WEST 18 ST
Code:	BP
Location Address 2:	SB 3251
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004603296

CON EDISON (Continued) **S117067462**

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/2014
Trans1 Recv Date:	07/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004603296
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504415GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **S117067462**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

H211 **CON EDISON** **NY MANIFEST** **S116551447**
ESE **332-320 18 ST & 9 AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.066 mi.
349 ft. **Site 15 of 15 in cluster H**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:
Name: CON EDISON
Address: 332-320 18 ST & 9 AVE
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004499117
Facility Status: Not reported
Location Address 1: 332-320 18 ST & 9 AVE
Code: BP
Location Address 2: SB3251
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004499117
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 04/13/2014
Trans1 Recv Date: 04/13/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/14/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004499117
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002407479GBF

CON EDISON (Continued) **S116551447**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L212 **345 W 16 STREET** **NY AST** **A100178191**
SSE **345 WEST 16TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.068 mi.
357 ft. **Site 5 of 18 in cluster L**

Relative:
Higher

Actual:
17 ft.

AST:

Name:	345 W 16 STREET
Address:	345 WEST 16TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-605954
Program Type:	PBS
UTM X:	584147.04466
UTM Y:	4510590.13755
Expiration Date:	06/06/2026
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	27820
Affiliation Type:	Mail Contact
Company Name:	BENEDICT PROPERTIES LLC
Contact Type:	Not reported
Contact Name:	D. BENEDICT
Address1:	150 GREAT NECK ROAD

345 W 16 STREET (Continued) **A100178191**

Address2:	ST 402
City:	GREAT NECK
State:	NY
Zip Code:	11021
Country Code:	001
Phone:	(516) 498-9100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27820
Affiliation Type:	Emergency Contact
Company Name:	345 WEST 16 STREET LLC
Contact Type:	Not reported
Contact Name:	D.BENEOIT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 498-9100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27820
Affiliation Type:	Facility Operator
Company Name:	345 W 16 STREET
Contact Type:	Not reported
Contact Name:	FRANK LUGO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 334-2603
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-05-04

Site Id:	27820
Affiliation Type:	Facility Owner
Company Name:	345 WEST 16TH STREET L.L.C.
Contact Type:	OFFICER
Contact Name:	BARRY JENDROVIC
Address1:	150 GREAT NECK ROAD #402
Address2:	Not reported
City:	GREAT NECK
State:	NY
Zip Code:	11021
Country Code:	001
Phone:	(516) 498-9100

345 W 16 STREET (Continued) **A100178191**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-05-04

Tank Info:

Tank Number:	01
Tank Id:	60753
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

D10 - Pipe Type - Copper
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel Tank in Concrete
Tank Status:	In Service
Pipe Model:	F
Install Date:	03/01/1905
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MRBARROW
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

L213 **CON EDISON** **NY MANIFEST** **S117058350**
SSE **345 W 16 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.068 mi.
357 ft. **Site 6 of 18 in cluster L**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	345 W 16 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004504353
Facility Status:	Not reported
Location Address 1:	345 W 16 ST
Code:	BP
Location Address 2:	SB2795

CON EDISON (Continued) **S117058350**

Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004504353
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/17/2014
Trans1 Recv Date:	04/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004504353
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694208JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	750
Units:	P - Pounds

CON EDISON (Continued) **S117058350**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L214 **345-347 WEST 16TH STREET** **NY Spills** **S106008685**
SSE **345-347 W 16TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.068 mi.
357 ft. **Site 7 of 18 in cluster L**

Relative: **Higher**

Actual: **17 ft.**

SPILLS:

Name:	345-347 WEST 16TH STREET
Address:	345-347 W 16TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0207660 / 2005-04-29
Facility ID:	0207660
Facility Type:	ER
DER Facility ID:	163507
Site ID:	196262
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	C3
SWIS:	3101
Spill Date:	2002-04-01
Investigator:	JXZHAO
Referred To:	Not reported
Reported to Dept:	2002-10-24
CID:	255
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-10-24
Spill Record Last Update:	2005-04-29
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ADAM WOODS
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHAO 10/28/02 10:00am - Tipple and Zhao inspected the site this morning. It was found that oil evidence at the boilor room at 345 W 16 Street. It might seeped to backyard. No evidence on the surface of backyard. Clean up the boilor room and investigation of subsurface contamination is required. jz 4/30/2005 jz: No investigation has been

345-347 WEST 16TH STREET (Continued) **S106008685**

conducted by owner. Spill closed based on that there is no other impact reported for the past 2 yaers."

Remarks: "TENANT'S ASSOC DISCOVERED OIL IN SOIL OF BACKYARD WHEN THEY STARTED RESTRUCTURING THE BACK YARD - THEY DID THEIR OWN TESTS BY PLANTING IN THE AREA - NOTHING WOULD GROW - WHEN YOU DIG, YOU CAN SEE THE OIL. SUPERINTENDENT STATED THAT NOTHING WOULD GROW DUE TO SOMEONE DUMPING WASTE OIL IN THE YARD."

All Materials:

Site ID:	196262
Operable Unit ID:	860472
Operable Unit:	01
Material ID:	518238
Material Code:	0013
Material Name:	lube oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

J215 **LOT 7502,TAXBLOCK 738** **NY E DESIGNATION** **S117676575**
South **66 9 AVENUE** **N/A**
< 1/8 **MANHATTAN, NY 10011**
0.069 mi.
364 ft. **Site 20 of 35 in cluster J**

Relative:
Higher

Actual:
16 ft.

E DESIGNATION:

Name:	LOT 7502,TAXBLOCK 738
Address:	66 9 AVENUE
City,State,Zip:	MANHATTAN, NY 10011
Tax Lot(s):	7502
Tax Block:	738
Borough Code:	MN
E-No:	E-92
Effective Date:	9/9/1999
Satisfaction Date:	Not reported
Ceqr Number:	99DCP030M
Ulurp Number:	990453 ZMM
Zoning Map No:	8b, 8d, 12c
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

J216 **216617; 404 15 ST AND 7 AVE** **NY Spills** **S110307127**
SSW **404 15 ST AND 7 AVE** **N/A**
< 1/8 **NEW YORK, NY**
0.069 mi.
364 ft. **Site 21 of 35 in cluster J**

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name:	216617; 404 15 ST AND 7 AVE
Address:	404 15 ST AND 7 AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0914186 / 2009-05-16
Facility ID:	0914186
Facility Type:	ER
DER Facility ID:	386997
Site ID:	432979
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	2401
Spill Date:	2009-04-29
Investigator:	DMPOKRZY
Referred To:	Not reported
Reported to Dept:	2009-03-30
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	Not reported
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2010-04-16
Spill Record Last Update:	2010-04-16
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	5030 BROADWAY
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	""
Remarks:	""

All Materials:

Site ID:	432979
Operable Unit ID:	1183890
Operable Unit:	01
Material ID:	2178252
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

J217 **PRINCE LUMBER** **NY UST** **U004048018**
SSW **61-67 9TH AVENUE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.069 mi.
365 ft. **Site 22 of 35 in cluster J**

Relative:
Higher

Actual:
15 ft.

UST:

Name:	PRINCE LUMBER
Address:	61-67 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-608138 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584003.28459
UTM Y:	4510535.91028
Site Type:	Other

Affiliation Records:

Site Id:	29990
Affiliation Type:	Facility Owner
Company Name:	G.D.C.L. HOLDINGS, LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	61-67 9TH AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 777-1150
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29990
Affiliation Type:	Mail Contact
Company Name:	BRENNAN ENVIRONMENTAL, INC.
Contact Type:	Not reported
Contact Name:	KEVEN ZIEGLER
Address1:	8-D GREAT MEADOW LANE
Address2:	Not reported
City:	EAST HANOVER
State:	NJ
Zip Code:	07936
Country Code:	001
Phone:	(973) 781-1801
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29990
Affiliation Type:	Facility Operator
Company Name:	PRINCE LUMBER
Contact Type:	Not reported
Contact Name:	PRINCE LUMBER
Address1:	Not reported

PRINCE LUMBER (Continued) **U004048018**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 261-8001
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29990
Affiliation Type:	Emergency Contact
Company Name:	G.D.C.L. HOLDINGS, LLC
Contact Type:	Not reported
Contact Name:	GUY APICELLA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 777-1150
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	64620
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	11/01/2002
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

PRINCE LUMBER (Continued) **U004048018**

G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
J00 - Dispenser - None

Tank Number: 002
Tank ID: 64621
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J00 - Dispenser - None

Tank Number: 003
Tank ID: 64622
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

PRINCE LUMBER (Continued) **U004048018**

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J00 - Dispenser - None

Tank Number: 004
Tank ID: 64623
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None

Tank Number: 005
Tank ID: 64624
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported

PRINCE LUMBER (Continued) **U004048018**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J00 - Dispenser - None

Tank Number: 006
Tank ID: 64625
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J00 - Dispenser - None

Tank Number: 007
Tank ID: 64626
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/2002
Registered: True
Tank Location: Underground

PRINCE LUMBER (Continued) **U004048018**

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J00 - Dispenser - None

Tank Number: 008
Tank ID: 64627
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
J00 - Dispenser - None

Tank Number: 009
Tank ID: 64798
Tank Status: Closed - Removed

PRINCE LUMBER (Continued) **U004048018**

Material Name:	Closed - Removed
Capacity Gallons:	275
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
J00 - Dispenser - None

J218 **LOT 36,TAXBLOCK 712** **NY E DESIGNATION** **S118191071**
SSW **61 9 AVENUE** **N/A**
< 1/8 **MANHATTAN, NY**
0.069 mi.
365 ft. **Site 23 of 35 in cluster J**

Relative:
Higher

Actual:
15 ft.

E DESIGNATION:

Name:	LOT 36,TAXBLOCK 712
Address:	61 9 AVENUE
City,State,Zip:	MANHATTAN, NY
Tax Lot(s):	36
Tax Block:	712
Borough Code:	Not reported
E-No:	E-350
Effective Date:	1/22/2015
Satisfaction Date:	Not reported
Ceqr Number:	15DCP037M
Ulurp Number:	150101ZMM, 150102ZRM
Zoning Map No:	8b
Description:	Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date:	8/3/2018
Description:	Exhaust stack location limitations
Lot Remediation Date:	8/3/2018

J219 **PRINCE LUMBER FORMER** **RCRA NonGen / NLR** **1019326154**
SSW **61 9TH AVE** **NYR000227678**
< 1/8 **NEW YORK, NY 10019**
0.069 mi.
365 ft. **Site 24 of 35 in cluster J**

Relative: **Higher**
Actual: **15 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20170418
Handler Name:	PRINCE LUMBER FORMER	
Handler Address:		61 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10019
EPA ID:		NYR000227678
Contact Name:		PETER SEGAL
Contact Address:		7TH AVE
Contact City,State,Zip:		NEW YORK, NY 10001
Contact Telephone:		516-398-0377
Contact Fax:		631-738-7748
Contact Email:		PSEGAL@TGNICKEL.COM
Contact Title:		PROJECT MANAGER
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		BROADWAY
Mailing City,State,Zip:		NEW YORK, NY 10018
Owner Name:		61 NINTH DEVELOPMENT LLC
Owner Type:		Private
Operator Name:		61 NINTH DEVELOPMENT LLC
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

PRINCE LUMBER FORMER (Continued) **1019326154**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170524
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	61 NINTH DEVELOPMENT LLC
Legal Status:	Private
Date Became Current:	20160311
Date Ended Current:	Not reported
Owner/Operator Address:	1407 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10018
Owner/Operator Telephone:	212-789-7228
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	61 NINTH DEVELOPMENT LLC
Legal Status:	Private
Date Became Current:	20160311
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported

PRINCE LUMBER FORMER (Continued) **1019326154**

Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	61 NINTH DEVELOPMENT LLC
Legal Status:	Private
Date Became Current:	20160311
Date Ended Current:	Not reported
Owner/Operator Address:	1407 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10018
Owner/Operator Telephone:	212-789-7228
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	61 NINTH DEVELOPMENT LLC
Legal Status:	Private
Date Became Current:	20160311
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20170418
Handler Name: PRINCE LUMBER FORMER	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20160713
Handler Name: PRINCE LUMBER FORMER	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

PRINCE LUMBER FORMER (Continued) **1019326154**

List of NAICS Codes and Descriptions:
NAICS Code: 531120
NAICS Description: LESSORS OF NONRESIDENTIAL BUILDINGS (EXCEPT MINIWAREHOUSES)

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

J220 **61 NINTH DEVELOPMENT LLC** **NY MANIFEST** **S118954261**
SSW **61 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10019**
0.069 mi.
365 ft. **Site 25 of 35 in cluster J**

Relative:
Higher

Actual:
15 ft.

NY MANIFEST:
Name: 61 NINTH DEVELOPMENT LLC
Address: 61 9TH AVE
City,State,Zip: NEW YORK, NY 10019
Country: USA
EPA ID: NYR000227678
Facility Status: Not reported
Location Address 1: 61-67 9TH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000227678
Mailing Name: 61 NINTH DEVELOPMENT LLC
Mailing Contact: 61 NINTH DEVELOPMENT LLC
Mailing Address 1: 1407 BROADWAY
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10018
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2126319000

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 07/27/2016
Trans1 Recv Date: 07/27/2016
Trans2 Recv Date: Not reported

61 NINTH DEVELOPMENT LLC (Continued) **S118954261**

TSD Site Recv Date:	07/27/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000227678
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	015979539JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	22
Units:	T - Tons
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D009
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J221 **FORMER PRINCE LUMBER** **NY Spills** **S118951782**
SSW **61-67 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY**
0.069 mi.
365 ft. **Site 26 of 35 in cluster J**

Relative:
Higher

Actual:
15 ft.

SPILLS:

Name:	FORMER PRINCE LUMBER
Address:	61-67 9TH AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	1606101 / 2017-03-23
Facility ID:	1606101
Facility Type:	ER
DER Facility ID:	456321
Site ID:	532698
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4

FORMER PRINCE LUMBER (Continued) **S118951782**

SWIS:	3101
Spill Date:	2016-09-19
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2016-09-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2016-09-19
Spill Record Last Update:	2017-03-23
Spiller Name:	Not reported
Spiller Company:	61-67 9 AVE
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CAYRE
DEC Memo:	"9/19/16- DEC Piper spoke with William from WCD Group. The site is being redeveloped and they encountered free phase hydraulic Oil in one well. There is a previous closed spill on this site dealing with the removal of hydraulic lifts. Spill 0208837. They are planning to further delineate via test pit. GW is 17 feet bgs. Once they have plume defined, they will excavate. Email summary of findings will be sent to DEC Piper and will be reviewed and forwarded. Assigned to DEC Omar for follow up. 9/26/2016: Rashad Received email from WCD Group: In accordance with our phone conversation earlier this week, WCD performed an investigation to delineate the extent of the above-referenced petroleum spill. Evidence of a petroleum release was observed on groundwater during installation of well points for future de-watering, and fingerprint analysis of the oil indicated that its source was hydraulic oil. As previously reported, the Site is undergoing construction, and soils across most of the Site have been excavated to 15 feet below ground surface (bgs), which is two feet above the groundwater table (17 feet bgs). WCD s investigation consisted of installing four test pits to delineate the extent of petroleum-impacted groundwater at the Site. The attached figure shows the estimated extent of petroleum-impacted groundwater based on field observations of the groundwater conditions within test pits as well as prior temporary groundwater wells installed during a previous investigation. WCD also collected soil samples for waste classification and end-points and will forward such results when they become available. Proposed remedial actions for the Site will include: " As part of Site-wide development (see next bulleted item), soils across the entire Site will be excavated to approximately 22 feet below ground surface (bgs), which corresponds to 5 feet below the water table, " Petroleum-impacted soils within the planned depth of excavation will be disposed at an appropriate off-site disposal facility, " Installation of a waterproof/vapor barrier beneath the floor slab and behind foundation walls of the new building, and " On-site treatment for discharge to New York City sewer via a discharge permit or off-site disposal of de-watered fluids at off-site facility (Note: this an option) Please let me know if you

FORMER PRINCE LUMBER (Continued) **S118951782**

have any questions or require additional information figure was received in email and uploaded to D2. Figure has 4 test pits down to a depth of 22 feet to delineate groundwater contamination. Test pit 4 did not show contamination. The proposed remedy is to excavate to about 22 ftbgs which is 5 feet below the water table, and installation of a waterproof/vapor barrier beneath the floor slab of the new building. The remedial actions for this site are adequate as it will remove all impacted soil and extend to soils below the water table, building will also include installation of waterproof/vapor barrier. 9/28/2016: Rashad 61 9th Avenue has an alternate address of 61-67 9th Avenue. Additional spill found #1407795 spill was closed in 2015 after a tank was found during a phase 2 investigation. 10/5/2016: Rashad Sent email to Bill (bsilveri@wcdgroup.com) approving remedial measures and asking him to keep me updated as remediation continues. 12/5/2016: Rashad Received email from Bill: In accordance with your prior email of October 5th, I m providing you with a brief update of the project status. For the past two months, Site work has consisted of completing necessary Support of Excavation (SOE) work to allow for site-wide excavation of soils to 22 feet bgs. This depth is approximately 5 feet below the water table. Due to this fact, installation of SOE work (i.e. underpinning of adjacent buildings) has required de-watering and treatment of de-watered fluids by on-site treatment plant in accordance with a New York City Sewer discharge permit. It is now anticipated that the SOE work will be completed within next two weeks and removal and off-site disposal of petroleum-impacted soils will commence shortly thereafter. At the Site, excavation will proceed from east (closest to 9th Avenue) to west. This approach for excavation offers the advantage of first removing the source of petroleum-impacted soils, thereby minimizing cross-contamination with uncontaminated soils towards the west of portion of the Site. As an additional remedial measure, an oxygen releasing compound (ORC advanced) will be placed in the excavation bottom for treatment of any residual contamination. Finally, an appropriate waterproofing and vapor barrier membrane system by Carlisle Coatings & Waterproofing Incorporated (MiraPLY) has been selected and will be installed beneath the basement slab and lower floor slab elements (elevator pit, sump pits, etc.) and behind foundation walls. We will update you on the start date of soil excavation when this date becomes better understood. Please feel free to call us if you have any questions. 12/14/2016: Rashad Received email from Bill: I m writing to let you know that removal and off-site disposal of petroleum-impacted soils at the Site is anticipated to start this Friday. 12/19/2016: Rashad Received email from Sarah Vitro of CBRE Inc: I was reviewing an email chain that was sent to me regarding the proposed remedial actions for the referenced site. CBRE conducted a Phase I Environmental Assessment during the time this Spill was assigned. At this point where does this spill stand? Has the remaining contamination been removed? I responded: I received an update last week from WCD Group that the removal of contaminated soil has commenced, and is ongoing. Sarah responded asking if dewatering has taken place on this site. I emailed Bill from WCD Group to obtain information. 12/20/2016: Rashad Received email from Danielle of CBRE: I was wondering if you could also give us some clarification on what is considered reportable to the NYSDEC in regarding to concentrations of VOCs, SVOCs, metals, pesticides, and PCBs exceeding regulatory criteria. The Phase II from 2014 for this property prepared by WCD identified the following: 7

FORMER PRINCE LUMBER (Continued) **S118951782**

SVOCs[benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, and indeno(1,2,3-cd)pyrene] including polycyclic aromatic hydrocarbons (PAHs) were detected at concentrations above the Unrestricted Use SCOs. Metals, Pesticides, and PCBs were also detected at concentrations exceeding regulatory criteria. 4 groundwater samples were analyzed. No SVOCs, metals, pesticides, or PCBs above GQS were identified, however three VOCs (1,2,4-trimethylbenzene (13 g/L), o-xylene (10 g/L) and p/m-Xylene (9.5 g/L) were detected above their respective GQS in one sample. Soil vapor revealed elevated petroleum and chlorinated solvent related concentrations. Methylene chloride was not detected in any of the samples collected. Trichloroethene (TCE) was detected in four soil vapor samples at concentrations ranging from 12.1 g/m3 to 166 g/m3 above the corresponding Air Guidance Value (AGV) of 5 g/m3. Tetrachloroethene (PCE) was detected in all four soil vapor samples at concentrations ranging from 107 ?g/m3 to 319 ?g/m3 above the corresponding AGV of 100 g/m3. It doesn t appear that any of the above exceedances were reported to the NYSDEC and based on our review of the Spill Guidance Manual, it doesn t appear that it would have been required as the contamination was not a result of a confirmed petroleum release. Can you confirm if this is accurate? In regards to the exceedance in groundwater, is this also the case and would the fact that it was contained to the property boundary also be a reason why it would not be considered reportable? Just trying to get some clarification for our Client. Thanks for your help. Consulted DEC Vought and replied: How is CBRE involved in this site? In general with respect to spill reporting, as per Navigation Law, The Department considers a discharge to be an exceedance of Soil Cleanup Levels for Gasoline Contaminated Soils and Fuel Oil Contaminated Soils (Table 2 and Table 3) of the Soil Cleanup Guidance CP-51, available on our website. With respect to other contaminates including chlorinated solvents, metals, pesticides, and PCBs there are no requirements as per Navigation Law for reporting. However there is an obligation to report exceedances of these contaminants via ECL, NYCRR, and CFR to our Hazardous Waste Section so that they may provide appropriate oversight and guidance. In lieu of a report being made to our Hazardous Waste Section, a report to the Spill Hotline is acceptable. Groundwater exceedances of TOGS 1.1.1 of petroleum compounds are considered a discharge and are reportable regardless of where they occur in reference to property boundaries. See section 1.1.1 Notification Requirements for Oil Spills and Hazardous Material Spills as per the Spill Response Guidance Manuel, in particular Exhibit 1.1-1 for more information. Please let me know if you have any other questions. Thanks. Bill responded: De-watering has occurred for the past several months in order to perform necessary underpinning of adjacent buildings. Danielle responded: Thanks for clarifying. We recently conducted a Phase I Environmental Site Assessment on this property. 1/17/2017 Austin This spill report is being transferred from Rashad Omar to Timothy DeMeo end. 3/23/17 TJD File review. WCD has submitted a closure report pertaining to this open spill file. As per report, the entire site has been excavated to a depth of 22 ft bgs, which is 5 feet below the water table. The scope of the remedial action as presented in closure report is as follows: 1. Removal and treatment of petroleum-impacted dewatering effluent generated by site-wide development activities. The treated effluent was discharged to the New York City sewer system; 2. Mass removal of petroleum-impacted soils and

FORMER PRINCE LUMBER (Continued) **S118951782**

uncontaminated soils across the entire Site to a depth of 22 feet bgs, a depth that corresponded to 5 feet below the water table; 3. Applying oxygen-releasing compound (ORC Advanced"!) to the excavation bottom at the eastern portion of the Site; 4. Installing a waterproofing/vapor barrier beneath the new building floor slab and behind new foundation walls; and 5. Collecting and analyzing post-remediation end-point soil and post-remediation groundwater samples. Report contains further discussion of each of the above listed remedial action items. Removal and Treatment of Petroleum-Impacted Dewatering Effluent The discharge of dewatering effluent was conducted in accordance with the New York City Department of Environmental Protection (NYCDEP) permit number 781234 that allowed for the discharge of up to 6,408,000 gallons of groundwater from the Site. The on-site treatment plant consisted of a 9,000-gallon settling tank, an oil-water separator, two bag filters for removal of suspended particulates, and two liquid phase activated carbon units. Contaminant Mass Removal On December 20, December 21, and December 22, 2016, 56 truckloads containing 2,046 tons of petroleum-contaminated soil were removed from the eastern portion of Site and disposed of at Soil Safe Inc. s Metro 12 Facility, located at 300 Salt Meadow Road in Carteret, New Jersey 07008. Application of Oxygen Release Compound During our oversight of soil excavation and off-site disposal activities, WCD observed the application of ORC Advanced"! to the excavation bottom. A total of 1,488 pounds of ORC Advanced"! was applied directly to the excavation throughout the eastern portion of the Site in the area containing petroleum impacted groundwater (Figure 2). This work was completed following removal of petroleum-impacted soils on December 23, 2016. Waterproofing/Vapor Barrier A waterproofing/vapor barrier system with the capability of functioning as a vapor retardant was installed beneath the basement floor slab and behind foundation walls, and this work was overseen by others. Carlisle Coatings and Waterproofing (CCW) 70-mil MiraPLY-H was installed beneath footings, grade beams, elevator pit bases, and slab on grade. CCW 47-mil MiraPLY- V was installed on blindside foundation walls, and CCW MiraDRI 860/861 was installed on 2-sided foundation walls and pit walls. Both CCW-MiraPLY and CCW-MiraDRI conform to ASTM standards for specifications of water vapor retarders (ASTM E1643, ASTM E1993, and ASTM E1745). Post-Remediation Sampling Post remediation sampling was performed to verify the completeness of the remediation and consisted of collecting and analyzing 9 discrete, end-point soil samples and 3 discrete groundwater samples from dewatering points at the Site. The location of post-remediation soil and groundwater samples are shown on Figure 3. The post-remediation end-point soil samples were collected on December 22, 2016 and January 5, 2017 and submitted to York Analytical Laboratories of Stratford, Connecticut for analysis for CP-51 VOCs by United States Environmental Protection Agency (EPA) method 8260, CP-51 SVOCs by EPA method 8270, and TPH DRO by EPA method 8015. The soil sampling results for VOCs and SVOCs were compared to the CP-51 soil cleanup objectives (SCOs) for gasoline and fuel oil-contaminated soils to assess the need for further action. The soil samples were analyzed for TPH DRO for information purposes only, and were evaluated based on prior experience on similar projects and consideration of guidance values established for other states. Post-remediation groundwater samples were collected on January 16, 2017 utilizing dedicated bailers and were submitted to York Analytical Laboratories for analysis for CP-51 VOCs and CP-51 SVOCs by the aforementioned EPA

FORMER PRINCE LUMBER (Continued) **S118951782**

methods. Groundwater samples were compared to Class GA groundwater standards, as presented in the document titled Technical Operational Guidance Series 1.1.1 (TOGs). During sample collection, soil and groundwater samples were evaluated for the presence of gross petroleum contamination utilizing appropriate field observations (odor, staining, instrument readings, etc.). None of the soil and groundwater samples exhibited evidence of field contamination. As discussed further in the following section, post-remediation soil and groundwater sampling results were below the evaluation criteria for CP-51 VOCs and CP-51 SVOCs. Significant findings and results of the remedial action are as follows: 1. After completion of remediation, soils at the base of the excavation and groundwater from dewatering points exhibited no field evidence of residual petroleum contamination (e.g., odors, staining, PID readings, sheen on soil or groundwater); 2. No VOCs or SVOCs were detected above their respective DEC CP-51 Soil Cleanup Guidance evaluation criteria in the post-excavation endpoint soil samples; and 3. Other than Methyl tert-butyl ether (MTBE), no detectable concentrations of VOCs and SVOCs were found in the groundwater samples. Low concentrations of MTBE were found in 2 of the 3 groundwater samples and were well below their Class GA Groundwater Standard/Guidance value (10 micrograms per liter). Based upon the documentation provided the residual contamination has been removed from the site as part of the remedial actions described above. A review of the laboratory data collected post-remediation reveals all target analytes are within acceptable concentrations. No further remedial action is required at this time. All documentation has been uploaded to DECDOCS. Spill closed."

Remarks: "contamination based on sample results"

All Materials:

Site ID:	532698
Operable Unit ID:	1281439
Operable Unit:	01
Material ID:	2286714
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

J222 **SOIL** **NY Spills** **S117363915**
SSW **61-67 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY**
0.069 mi.
365 ft. **Site 27 of 35 in cluster J**

Relative: **Higher**

Actual: **15 ft.**

SPILLS:

Name:	SOIL
Address:	61-67 9TH AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	1407795 / 2015-03-26
Facility ID:	1407795
Facility Type:	ER
DER Facility ID:	456321

SOIL (Continued) **S117363915**

Site ID:	501325
DEC Region:	2
Spill Cause:	Other
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2014-10-26
Investigator:	SXMAHAT
Referred To:	Not reported
Reported to Dept:	2014-10-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-10-28
Spill Record Last Update:	2015-10-28
Spiller Name:	Not reported
Spiller Company:	GDCL HOLDINGS LLC
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	WES LINDEMUTH
DEC Memo:	"10/28/14- Ahmed - Spoke to Wes at WCD (212-631-9000). As per him there while doing a phase II investigation, the drill hit an unknown tank (tank top was 1 ft below ground) and spilled some gasolene. The site used to be a taxi repair and filling station in 1940s. The site was last used for lumber yard. They want to demo and develop the site. They are in a process to e-designate the site under City's OER program. The consultant are putting together a plan to propose tank removal to the owners. Asked him to contact Santosh for future correspondance. 11/7/14: Mahat e/c: An email was sent to Wes to keep DEC informed about the progess on the case. 11/18/14: Mahat t/c: DEC Mahat is receiving a proposal to pump/remove the tank from the site. WES will provide the phase II investigation to prove the tank was never leaking and the vicinity of the tank is clean (soil boring). 11/18/14: Mahat Email Correspondace from Bryan: Mr. Mahat, Ref: 1407795 As discussed earlier this morning, with your approval we would like to go ahead and pump out the contents of an underground storage tank (UST) uncovered during WCD Group's Phase II Site Investigation of the property. If you have any questions please do not hesitate to contact me at: Work: (212) 505-4926 Cell: (917) 545-9226 Thank you for time! Brian. Brian will provide a report on pumping out the tank. 12/09/14: Mahat A voice message was left for Brian to call back with a report. 2/11/15: Mahat A closure report was submitted to DEC via dropbox application. The closure report has been uploaded on D2 for reference. 3/26/15: Mahat DEC Mahat reviewed the closure reprot: Following are the key items from the closure reprot : Summary and Environmental Findings # 8, 9, 10 and 11 verify that futher remediation is not required on the site. Hence, the spill case will be closed in DEC Spill Database. "
Remarks:	"Caller advised during the phase 2 boring of soil they hit a tank under the soil that they didnt know was there and aprx 2 gal of gas spilled ontop of the soil unknown is any more spilled out of the

SOIL (Continued) **S117363915**

tank."

All Materials:

Site ID:	501325
Operable Unit ID:	1250726
Operable Unit:	01
Material ID:	2252513
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Q223 **MANHOLE # 43048** **NY Spills** **S108057682**
West **WEST 16 STREET & 10 AVENUE** **N/A**
< 1/8 **MANHATTAN, NY**
0.069 mi.
365 ft. **Site 1 of 25 in cluster Q**

Relative: **Lower**

Actual: **10 ft.**

SPILLS:

Name:	MANHOLE # 43048
Address:	WEST 16 STREET & 10 AVENUE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0603182 / 2006-10-05
Facility ID:	0603182
Facility Type:	ER
DER Facility ID:	315967
Site ID:	365851
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2006-06-22
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2006-06-22
CID:	406
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-06-22
Spill Record Last Update:	2006-10-05
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	999
Contact Name:	ERT DESK
DEC Memo:	"10/05/06 - See e-docs for Con Ed report detailing cleanup and

MANHOLE # 43048 (Continued) **S108057682**

closure. 200757. see eDocs"
Remarks: ".01 gallons of material spilled from a cable joint in a manhole. Location is at the South East corner of those streets. Clean up deenergizing of the feeder. ConEd#200757 No to the five questions."

All Materials:
Site ID: 365851
Operable Unit ID: 1123821
Operable Unit: 01
Material ID: 2113299
Material Code: 0020B
Material Name: cable oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

Q224 **CON EDISON MANHOLE 43048** **RCRA NonGen / NLR** **1010326872**
West **W 16 ST & 10 AVE** **NY MANIFEST** **NYP004143483**
< 1/8 **NEW YORK, NY 10011**
0.069 mi.
365 ft. **Site 2 of 25 in cluster Q**

Relative: **Lower**
Actual: **10 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20061117
Handler Name: CON EDISON MANHOLE 43048
Handler Address: W 16 ST & 10 AVE
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYP004143483
Contact Name: ANTONIO DELGADO
Contact Address: 4 IRVING PL, RM 828
Contact City,State,Zip: NEW YORK, NY 10003
Contact Telephone: 718-204-4201
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY
State District: NYSDEC R2
Mailing Address: 4 IRVING PL, RM 828
Mailing City,State,Zip: NEW YORK, NY 10003
Owner Name: Not reported
Owner Type: Not reported
Operator Name: Not reported
Operator Type: Not reported
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No

CON EDISON MANHOLE 43048 (Continued) **1010326872**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20061115
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not reported

CON EDISON MANHOLE 43048 (Continued) **1010326872**

State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20061116
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20061117
Handler Name: CON EDISON MANHOLE 43048
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: W 16 ST & 10 AVE
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004143483
Facility Status: Not reported
Location Address 1: MH43048-W 16TH ST & 10TH AVE
Code: BP

CON EDISON MANHOLE 43048 (Continued) **1010326872**

Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004143483
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	07/11/2006
Trans1 Recv Date:	07/11/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/17/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004143483
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	NYE1539882
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	336

CON EDISON MANHOLE 43048 (Continued) **1010326872**

Units:	K - Kilograms (2.2 pounds)
Number of Containers:	4
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	B007
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Q225 **CON EDISON** **RCRA NonGen / NLR** **1016150276**
West **10TH AVE & 16TH ST** **FINDS** **NYP004289484**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.069 mi. **NY MANIFEST**
365 ft. **Site 3 of 25 in cluster Q**

Relative: **Lower**

Actual: **10 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130314
Handler Name:	CON EDISON SERVICE BOX:	43049
Handler Address:		10TH AVE & 16TH ST NW
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004289484
Contact Name:		RICARDO CARTY
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		646-772-3407
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No

CON EDISON (Continued) **1016150276**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130214
Handler Name: CON EDISON SERVICE BOX:	43049
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

CON EDISON (Continued) **1016150276**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130314
Handler Name: CON EDISON SERVICE BOX: 43049
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069389717

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016150276
Registry ID: 110069389717
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069389717
Name: CON EDISON
Address: 10TH AVE & 16TH ST
City,State,Zip: NEW YORK, NY 10011

NY MANIFEST:
Name: CON EDISON
Address: 10TH AVE & 16TH ST NW
City,State,Zip: NEW YORK, NY 10011
Country: USA

CON EDISON (Continued) **1016150276**

EPA ID: NYP004289484
Facility Status: Not reported
Location Address 1: N/W 10 AVE & 16 ST
Code: BP
Location Address 2: SERVICE BOX # 43049
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004289484
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 02/14/2013
Trans1 Recv Date: 02/14/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/16/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004289484
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 010841385JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

CON EDISON (Continued) **1016150276**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Q226 **CON EDISON** **NJ MANIFEST** **S120673175**
West **10TH AVE & 16TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.069 mi.
365 ft. **Site 4 of 25 in cluster Q**

Relative: **Lower**
Actual: **10 ft.**

NJ MANIFEST:

EPA Id:	NYP004798732
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002614304GBF
EPA ID:	NYP004798732
Date Shipped:	6/24/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported

CON EDISON (Continued) **S120673175**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Q227 **CON EDISON** **RCRA NonGen / NLR** **1019325152**
West **10TH AVE & 16TH ST** **NYP004798732**
< 1/8 **NEW YORK, NY 10011**
0.069 mi.
365 ft. **Site 5 of 25 in cluster Q**

Relative: **Lower**
Actual: **10 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150624
Handler Name:	CON EDISON	
Handler Address:		10TH AVE & 16TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004798732
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported

CON EDISON (Continued) **1019325152**

Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

CON EDISON (Continued) **1019325152**

Sub-Part P Indicator: No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150624
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150624
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - MANHOLE 43048
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150624
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No

CON EDISON (Continued) **1019325152**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20150624
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

Q228 **CON EDISON** **NY MANIFEST** **S119076090**
West **10TH AVE & 16TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.069 mi.
365 ft. **Site 6 of 25 in cluster Q**

Relative: **Lower**
Actual: **10 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	10TH AVE & 16TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004798732
Facility Status:	Not reported
Location Address 1:	10TH AVE & WEST 16TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004798732
Mailing Name:	CON EDISON

CON EDISON (Continued) **S119076090**

Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/24/2015
Trans1 Recv Date:	06/24/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004798732
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002614304GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON EDISON (Continued) **S119076090**

Waste Code 1_6: Not reported

Q229 **BET.9TH & 10TH AVE W.16ST** **NY Spills** **S102146949**
West **10TH AVE / W 16ST ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.069 mi.
365 ft. **Site 7 of 25 in cluster Q**

Relative: SPILLS:
Lower

Actual:
10 ft.

Name:	BET.9TH & 10TH AVE W.16ST
Address:	10TH AVE / W 16ST ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9306675 / 1996-07-15
Facility ID:	9306675
Facility Type:	ER
DER Facility ID:	235901
Site ID:	291344
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	1993-08-31
Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	1993-08-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-09-09
Spill Record Last Update:	1996-07-15
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"UNDER CONTROL - NEEDS DEC TO RESPOND. WAS LEAKED SECURED INTO SEWER."
	Not reported

P230 **CHELTONCORT OWNERS CORP.** **NY AST** **U003394415**
NE **360 WEST 21ST STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.070 mi.
372 ft. **Site 3 of 17 in cluster P**

Relative:
Higher

Actual:
16 ft.

AST:

Name:	CHELTONCORT OWNERS CORP.
Address:	360 WEST 21ST STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-452491
Program Type:	PBS
UTM X:	584252.32228
UTM Y:	4510931.69536
Expiration Date:	08/23/2023
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	19773
Affiliation Type:	Emergency Contact
Company Name:	CHELTONCORT OWNERS C/O CENTURY MGMT
Contact Type:	Not reported
Contact Name:	ALEX RUBEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 560-6424
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-03-28

Site Id:	19773
Affiliation Type:	Mail Contact
Company Name:	CHELTONCORT OWNERS CORP.
Contact Type:	AGENT
Contact Name:	TONY SEIURNARINE
Address1:	360 WEST 21ST STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(646) 244-0983
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-08-27

Site Id:	19773
Affiliation Type:	Facility Operator
Company Name:	CHELTONCORT OWNERS CORP.
Contact Type:	Not reported
Contact Name:	TONY SEIUNARINE

CHELTONCORT OWNERS CORP. (Continued) **U003394415**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 244-0983
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-08-27

Site Id:	19773
Affiliation Type:	Facility Owner
Company Name:	CHELTONCORT OWNERS CORP.
Contact Type:	AGENT
Contact Name:	NICK CORNISH
Address1:	440 NINTH AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 560-6406
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-08-27

Tank Info:

Tank Number:	001
Tank Id:	35479
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	K00 - Spill Prevention - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	A00 - Tank Internal Protection - None
	E00 - Piping Secondary Containment - None
	J05 - Dispenser - On Site Heating System (Supply/Return)
	L00 - Piping Leak Detection - None
	H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
	C01 - Pipe Location - Aboveground
	F00 - Pipe External Protection - None
	B00 - Tank External Protection - None
	I05 - Overfill - Vent Whistle
	G02 - Tank Secondary Containment - Vault (w/access)
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/09/1928
Capacity Gallons:	4500

CHELTONCORT OWNERS CORP. (Continued) **U003394415**

Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	08/27/2019
Material Name:	#2 fuel oil (on-site consumption)

M231 **CON EDISON** **NY MANIFEST** **S117058364**
East **344 W 19 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.071 mi.
373 ft. **Site 4 of 10 in cluster M**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	344 W 19 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004504601
Facility Status:	Not reported
Location Address 1:	344 W 19 ST
Code:	BP
Location Address 2:	SB3431
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004504601
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRIVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/18/2014
Trans1 Recv Date:	04/18/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004504601

CON EDISON (Continued) **S117058364**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406247GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Q232 **COMML STRUCTURE** **NY Spills** **S106968043**
West **503 W 16TH ST BET 10 AND** **N/A**
< 1/8 **MANHATTAN, NY**
0.071 mi.
377 ft. **Site 8 of 25 in cluster Q**

Relative: **Lower**

Actual: **10 ft.**

SPILLS:

Name:	COMML STRUCTURE
Address:	503 W 16TH ST BET 10 AND
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0501993 / 2005-09-28
Facility ID:	0501993
Facility Type:	ER
DER Facility ID:	292522
Site ID:	346267
DEC Region:	2
Spill Cause:	Other
Spill Class:	C5
SWIS:	3101
Spill Date:	2005-05-18
Investigator:	JXZHAO
Referred To:	Not reported

COMML STRUCTURE (Continued) **S106968043**

Reported to Dept:	2005-05-18
CID:	75
Water Affected:	N/A
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-05-19
Spill Record Last Update:	2005-09-28
Spiller Name:	PAOLO IMPELLOZZERI
Spiller Company:	COMML STRUCTURE
Spiller Address:	503 W 16TH ST BET 10 AND
Spiller Company:	001
Contact Name:	PAOLO IMPELLOZZERI
DEC Memo:	""
Remarks:	"Fire on roof at the site-after put out water and oil came from a motor and ran down into sqewer-none recovered at present time-"

All Materials:

Site ID:	346267
Operable Unit ID:	1103997
Operable Unit:	01
Material ID:	584205
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Q233 **NEW YORK MOTORCOACH BUS TEN BROECK AVE** **NY Spills** **S106719713**
West **90 TEN BROECK AVE** **N/A**
< 1/8 **GREENPORT HUDSON ZIP, NY**
0.071 mi.
377 ft. **Site 9 of 25 in cluster Q**

Relative: **Lower**
Actual: **10 ft.**

SPILLS:

Name:	NEW YORK MOTORCOACH BUS TEN BROECK AVE
Address:	90 TEN BROECK AVE
City,State,Zip:	GREENPORT HUDSON ZIP, NY
Spill Number/Closed Date:	9903444 / 1999-06-28
Facility ID:	9903444
Facility Type:	ER
DER Facility ID:	207668
Site ID:	253508
DEC Region:	4
Spill Cause:	Human Error
Spill Class:	B3
SWIS:	1140
Spill Date:	1999-06-24
Investigator:	WEBLAIN

NEW YORK MOTORCOACH BUS TEN BROECK AVE (Continued) **S106719713**

Referred To:	Not reported
Reported to Dept:	1999-06-24
CID:	999
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	1999-06-28
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-06-25
Spill Record Last Update:	2012-09-26
Spiller Name:	Not reported
Spiller Company:	NEW YORK MOTORCOACH
Spiller Address:	90 TENBROECK AVE
Spiller Company:	001
Contact Name:	EMMET LARSON
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was BLAIN See EDOCs for additional information. 6/24 Christensen onsite. Needs cleanup. 6/25 Blain checked-- insufficient. 6/28 Blain checked. Cleanup done. closed. SEE 9807306?, 0400717?"
Remarks:	"looks like ny motorcoach overfilled a fuel tank on bus. diesel ran down street and contaminated som soil across the street. its possible that they tried washing it down and this caused it to travel. blacktop very soft"

All Materials:

Site ID:	253508
Operable Unit ID:	1078044
Operable Unit:	01
Material ID:	303361
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

P234 **CON EDISON SERVICE BOX: 3796** **RCRA NonGen / NLR** **1017772908**
NE **328-326 W 21ST ST & 9TH AVE** **FINDS** **NYP004506853**
< 1/8 **NEW YORK, NY 10011**
0.072 mi.
378 ft. **Site 4 of 17 in cluster P**

Relative: **Higher**
Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20140521
Handler Name:	CON EDISON SERVICE BOX: 3796
Handler Address:	328-326 W 21ST ST & 9TH AVE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004506853
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported

CON EDISON SERVICE BOX: 3796 (Continued) **1017772908**

Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 3796 (Continued) **1017772908**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140421
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140421
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140521
Handler Name: CON EDISON SERVICE BOX: 3796	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 3796 (Continued) **1017772908**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063799858

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

P235 **CON EDISON SERVICE BOX: 39680** **RCRA NonGen / NLR** **1016143404**
NE **W 21ST ST & 9TH AVE SB 39680** **FINDS** **NYP004261814**
< 1/8 **NEW YORK, NY 10014** **ECHO**
0.072 mi. **NY MANIFEST**
378 ft. **Site 5 of 17 in cluster P**

Relative: Higher
Actual: 16 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20130321
Handler Name:	CON EDISON SERVICE BOX:	39680
Handler Address:		W 21ST ST & 9TH AVE SB 39680
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004261814
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported

CON EDISON SERVICE BOX: 39680 (Continued) **1016143404**

Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

CON EDISON SERVICE BOX: 39680 (Continued) **1016143404**

Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:

Receive Date: 20130221
Handler Name: CON EDISON SERVICE BOX: 39680
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130321
Handler Name: CON EDISON SERVICE BOX: 39680
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055458687

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON SERVICE BOX: 39680 (Continued) **1016143404**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016143404
Registry ID:	110055458687
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055458687
Name:	CON EDISON SERVICE BOX: 39680
Address:	W 21ST ST & 9TH AVE SB 39680
City,State,Zip:	NEW YORK, NY 10014

NY MANIFEST:

Name:	CON EDISON
Address:	W 21ST & 9TH AVE NW COR
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004261814
Facility Status:	Not reported
Location Address 1:	NWC W 21ST ST & 9TH AVE
Code:	BP
Location Address 2:	SERV BOX 39680
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004261814
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/21/2013
Trans1 Recv Date:	02/21/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/22/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004261814
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON SERVICE BOX: 39680 (Continued) **1016143404**

TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010707146JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P236 **CON EDISON SERVICE BOX: 3782** **RCRA NonGen / NLR** **1017772911**
NE **353-351 W 21ST ST & 9TH AVE** **FINDS** **NYP004506887**
< 1/8 **NEW YORK, NY 10011**
0.072 mi.
378 ft. **Site 6 of 17 in cluster P**

Relative: **Higher**

Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140522
Handler Name:	CON EDISON SERVICE BOX:	3782
Handler Address:		353-351 W 21ST ST & 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004506887
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported

CON EDISON SERVICE BOX: 3782 (Continued) **1017772911**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

CON EDISON SERVICE BOX: 3782 (Continued) **1017772911**

Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140522
Handler Name: CON EDISON SERVICE BOX: 3782	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON SERVICE BOX: 3782 (Continued) **1017772911**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063799803

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

J237 **364 W. 15TH ST** **NY Spills** **S104495761**
South **364 W. 15TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.072 mi.
378 ft. **Site 28 of 35 in cluster J**

Relative:
Higher

Actual:
16 ft.

SPILLS:

Name:	364 W. 15TH ST
Address:	364 W. 15TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9408540 / 1994-09-27
Facility ID:	9408540
Facility Type:	ER
DER Facility ID:	159549
Site ID:	191286
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	1994-09-01
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1994-09-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Citizen
Cleanup Ceased:	1994-09-27
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-10-31
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported

364 W. 15TH ST (Continued) **S104495761**

Spiller Company: 999
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT 10/10/95: This is additional information about material spilled from the translation of the old spill file: ODOR."
Remarks: "LEAVES A BLACK FILM ON EVERYTHING IN HIS HOME- REFER TO DEP-AIR UNIT REFER TO AIR RESOURCES."

All Materials:
Site ID: 191286
Operable Unit ID: 1002670
Operable Unit: 01
Material ID: 377980
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

P238 **CON EDISON** **NY MANIFEST** **S117058562**
ENE **352-35- W 21ST ST & 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.072 mi.
380 ft. **Site 7 of 17 in cluster P**

Relative: **Higher**
Actual: **17 ft.**

NY MANIFEST:
Name: CON EDISON
Address: 352-35- W 21ST ST & 9TH AVE
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004506879
Facility Status: Not reported
Location Address 1: 328 W 21 ST & 9TH AVE
Code: BP
Location Address 2: SB 3796
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004506879
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

CON EDISON (Continued) **S117058562**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/21/2014
Trans1 Recv Date:	04/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004506879
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416690GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P239 **CON EDISON** **NY MANIFEST** **S117067535**
ENE **FO 352 WEST 21 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.072 mi.
380 ft. **Site 8 of 17 in cluster P**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FO 352 WEST 21 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004604757
Facility Status:	Not reported
Location Address 1:	FO 352 WEST 21 ST
Code:	BP
Location Address 2:	SB 3772
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004604757
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/23/2014
Trans1 Recv Date:	07/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004604757
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504471GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117067535**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J240 **CHELSEA CONDOMINIUMS** **NY AST** **A100293532**
South **62-66 NINTH AVENUE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.072 mi.
381 ft. **Site 29 of 35 in cluster J**

Relative:
Higher

Actual:
16 ft.

AST:

Name:	CHELSEA CONDOMINIUMS
Address:	62-66 NINTH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608020
Program Type:	PBS
UTM X:	584020.33538
UTM Y:	4510532.85856
Expiration Date:	09/16/2007
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	29872
Affiliation Type:	Facility Owner
Company Name:	66 NINTH, LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	200 EAST 37TH ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001

CHELSEA CONDOMINIUMS (Continued) **A100293532**

Phone:	(212) 279-9422
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29872
Affiliation Type:	Mail Contact
Company Name:	66 NINTH, LLC
Contact Type:	Not reported
Contact Name:	KENNETH A. SMUB
Address1:	200 EAST 37TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 279-9422
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29872
Affiliation Type:	Facility Operator
Company Name:	CHELSEA CONDOMINIUMS
Contact Type:	Not reported
Contact Name:	DAVID LO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 288-9040
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29872
Affiliation Type:	Emergency Contact
Company Name:	66 NINTH, LLC
Contact Type:	Not reported
Contact Name:	NICK SACCENTI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 816-5137
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

CHELSEA CONDOMINIUMS (Continued) **A100293532**

Tank Info:

Tank Number:	001
Tank Id:	64166
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	F00 - Pipe External Protection - None
	J02 - Dispenser - Suction Dispenser
	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	C01 - Pipe Location - Aboveground
	I04 - Overfill - Product Level Gauge (A/G)
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/2002
Capacity Gallons:	2500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

P241 **MANHOLE #3794** **NY Spills** **S103574325**
NE **WEST 21ST ST & 9TH AVE** **N/A**
< 1/8 **MANHATTAN, NY**
0.072 mi.
381 ft. **Site 9 of 17 in cluster P**

Relative: **Higher**
Actual: **16 ft.**

SPILLS:

Name:	MANHOLE #3794
Address:	WEST 21ST ST & 9TH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9810284 / 2003-11-04
Facility ID:	9810284
Facility Type:	ER
DER Facility ID:	218497
Site ID:	268236
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	1998-11-14
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1998-11-14

MANHOLE #3794 (Continued) **S103574325**

CID:	384
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-11-14
Spill Record Last Update:	2003-11-12
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT E2MIS 121251 THIS INCIDENT HAS TWO LAB RESULTS: ONE FOR M3794 AND ONE FOR M3800 THERE IS NO INDICATION WHY THE LAB RESULT FOR M3800 IS ASSOCIATED WITH THIS SPILL If this is a Con Edison manhole it contains electrical cable and splices. Many manholes have a sealed sump in the floor which is used to allow runoff when pumping the structure. A hose is place in this sump and water on the floor will flow into the sump allowing the floor to be cleaned. If cleaned prior to analysis of the fluid, the structure will be cleaned as >50 PPM and all liquid and waste will be manifested accordingly. The structure will be double washed with a degreaser, i.e. Slix. All cleaning material and PPE will also be treated as >50. If any sludge is found within a manhole it is treated as lead contaminated and manifested accordingly. The spill identification tag will remain secured to the structure until the analysis is completed and if <500 PPM the signage will be removed. If the analysis is >499 PPM, a grid will be prepared for wipe testing the area. Until the analysis of the wipes are proven to be <10ugs/100cme2 all additional waste produced from the structure will be treated as the original analysis. If this spill occurred in a transformer vault containing a sump pump and there was a possible release, the drainpipe trap will be dismantled to determine if oil was released. Sludge found in a vault, through historical analysis, has been determined not to contain lead. 11/14/98 12:39 R. MAHONEY #97417 (FOD) WORKING ON TROUBLE FEEDER 13M55 IN M-3794 S/S W.21 ST. 275' E/O 9 AVE. FOUND APPROX. 1 GAL OF UNKNOWN OIL ON APPROX. 300 GALS OF WATER. OIL IS CONTAINED TO THE MANHOLE DIDN'T ENTER ANY WATERWAYS OR SEWER SYSTEMS. TOOK SAMPLE AND HUNG SIGN #18115. MANHOLE HAS NO CRACKS WAS UNABLE TO VARIFY IF MANHOLE HAS A SUMP OR SEWER CONNECTION..... 11/14/98 22:02 HRS. LAB SEQ.#98-12572 11/14/98 21:25 AROCLOR #1260 PCB <1.0 PPM 11/16/98 O.S. P. Reidmiller #52281 reports clean up complete in MH 03794 W 21 St. 275' E/O 9th Ave on 11/15/98 @ 19:30 hrs. <1. ppm PCB Removed sheen from water with absorbent pads Pumped 535 gals. Water to sewer Used flush truck to clean & rinse structure Generated 2 drums PPE Removed Spill Tag # 18115 upon completion Crews: O.S. (UG) P. Reidmiller # 52281 P. Mullholland # 18565, J. Ruiz # 74673, W. Nichols #25857 "
Remarks:	"CON ED #121251 "

MANHOLE #3794 (Continued) **S103574325**

All Materials:

Site ID:	268236
Operable Unit ID:	1071205
Operable Unit:	01
Material ID:	314148
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

N242 **CONSOLIDATED EDISON OF NY** **NY MANIFEST** **S112140557**
NNW **F/O 146-148 10TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.073 mi.
385 ft. **Site 2 of 25 in cluster N**

Relative:
Lower

Actual:
12 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON OF NY
Address:	F/O 146-148 10TH AVE
City,State,Zip:	NEW YORK, NY 10003
Country:	USA
EPA ID:	NYP004253266
Facility Status:	Not reported
Location Address 1:	F/O 146-148 10TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004253266
Mailing Name:	CONSOLIDATED EDISON OF NY
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE FLOOR 15
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported

CONSOLIDATED EDISON OF NY (Continued) **S112140557**

Generator Ship Date:	05/16/2012
Trans1 Recv Date:	05/16/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/16/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004253266
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	009202668JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

K243 **TENTH AVENUE CAR WASH, LLC** **NY AST** **A100514857**
WSW **450 WEST 15TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.073 mi.
386 ft. **Site 17 of 28 in cluster K**

Relative: AST:
Lower

Actual:
12 ft.

Name:	TENTH AVENUE CAR WASH, LLC
Address:	450 WEST 15TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-000497
Program Type:	CBS

TENTH AVENUE CAR WASH, LLC (Continued) **A100514857**

UTM X:	583822.51319
UTM Y:	4510648.00665
Expiration Date:	N/A
Site Type:	Other

Tank Info:

Tank Number:	10
Tank Id:	237364
Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Plastic
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	01/01/1999
Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/30/2010
Register:	True
Modified By:	LXZIELIN
Last Modified:	12/15/2010
Material Name:	Not reported

K244 **CON EDISON - VAULT 6746** **RCRA-LQG** **1016965124**
WSW **450 W 15 ST** **NY MANIFEST** **NYP004380184**
< 1/8 **NEW YORK, NY 10011**
0.073 mi.
386 ft. **Site 18 of 28 in cluster K**

Relative: **Lower**

Actual: **12 ft.**

RCRA-LQG:

Date Form Received by Agency:		20140327
Handler Name:	CON EDISON - VAULT 6746	
Handler Address:		450 W 15 ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004380184
Contact Name:		DENNIS HUACON
Contact Address:		IRVING PLACE, 15TH FL NE
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-2757
Contact Fax:		518-473-8034
Contact Email:		HUACOND@CONED.COM
Contact Title:		ASSOCIATE SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Large Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		2013
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:		Private
Operator Name:		CONSOLIDATED EDISON COMPANY OF NY, INC.

CON EDISON - VAULT 6746 (Continued) **1016965124**

Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON - VAULT 6746 (Continued) **1016965124**

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20131025
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20131025
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140327
Handler Name: CON EDISON - VAULT 6746
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131025
Handler Name: CON EDISON VAULT: 6746
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

CON EDISON - VAULT 6746 (Continued) **1016965124**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131125
Handler Name: CON EDISON VAULT: 6746
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 450 W 15TH ST FRONT OF
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004380184
Facility Status: Not reported
Location Address 1: F/O 450 W 15TH ST
Code: BP
Location Address 2: SB6746
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004380184
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported

CON EDISON - VAULT 6746 (Continued) **1016965124**

Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	10/25/2013
Trans1 Recv Date:	10/25/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004380184
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002236061GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	5000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

K245 **CON EDISON - VAULT SUBMERSIBLE VS6915** **NY MANIFEST** **S120959140**
WSW **450 W 15 ST** **N/A**
< 1/8 **MANHATTAN, NY 10011**
0.073 mi.
386 ft. **Site 19 of 28 in cluster K**

Relative: **Lower**
Actual: **12 ft.**

NY MANIFEST:

Name:	CON EDISON - VAULT SUBMERSIBLE VS6915
Address:	450 W 15 ST
City,State,Zip:	MANHATTAN, NY 10011
Country:	USA
EPA ID:	NYP004995278
Facility Status:	Not reported
Location Address 1:	450 W 15 ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MANHATTAN
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004995278
Mailing Name:	CON EDISON - VAULT SUBMERSIBLE VS6915
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

K246 **CON EDISON - TRENCH 6915** **RCRA-LQG** **1016964316**
WSW **450 W15 ST. W/O 9TH AVE** **NY MANIFEST** **NYP004372488**
< 1/8 **NEW YORK, NY 10011**
0.073 mi.
386 ft. **Site 20 of 28 in cluster K**

Relative: **Lower**
Actual: **12 ft.**

RCRA-LQG:

Date Form Received by Agency:	20140327
Handler Name:	CON EDISON - TRENCH 6915
Handler Address:	450 W15 ST. W/O 9TH AVE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004372488
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	518-473-8034
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013

CON EDISON - TRENCH 6915 (Continued) **1016964316**

Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

CON EDISON - TRENCH 6915 (Continued) **1016964316**

Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20131010
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20131010
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20140327
Handler Name:	CON EDISON - TRENCH 6915
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON - TRENCH 6915 (Continued) **1016964316**

Electronic Manifest Broker: Not reported

Receive Date: 20131010
Handler Name: CON EDISON TRENCH: 6915
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131110
Handler Name: CON EDISON TRENCH: 6915
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 450 W 15TH ST W OF 9TH AVE
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004372488
Facility Status: Not reported
Location Address 1: S/W/C 450 W 15TH ST & 10TH AVE
Code: BP
Location Address 2: V6915
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

CON EDISON - TRENCH 6915 (Continued) **1016964316**

NY MANIFEST:

EPAID:	NYP004372488
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	10/10/2013
Trans1 Recv Date:	10/10/2013
Trans2 Recv Date:	10/14/2013
TSD Site Recv Date:	10/14/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004372488
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002291735GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON - TRENCH 6915 (Continued) **1016964316**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

K247 **RP STELLAR MILK LLC** **NY AST** **U004077721**
WSW **450 WEST 15 STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.073 mi.
386 ft. **Site 21 of 28 in cluster K**

Relative:
Lower

Actual:
12 ft.

AST:

Name:	RP STELLAR MILK LLC
Address:	450 WEST 15 STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-403938
Program Type:	PBS
UTM X:	583822.51319
UTM Y:	4510648.00665
Expiration Date:	01/15/2018
Site Type:	Other

Affiliation Records:

Site Id:	19409
Affiliation Type:	Mail Contact
Company Name:	STELLAR MGMT.
Contact Type:	Not reported
Contact Name:	KATINA V. VAZQUEZ
Address1:	156 WILLIAMS STREET
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 843-3783
EMail:	KVAZQUEZ@STELLARMANAGEMENT.COM
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-03-06

Site Id:	19409
Affiliation Type:	Emergency Contact
Company Name:	RP STELLAR MILK OWNER, LLC
Contact Type:	Not reported
Contact Name:	JASON BERLELEY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 294-5738
EMail:	Not reported

RP STELLAR MILK LLC (Continued) **U004077721**

Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-03-06

Site Id:	19409
Affiliation Type:	Facility Operator
Company Name:	RP STELLAR MILK LLC
Contact Type:	Not reported
Contact Name:	JASON BERKELEY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 294-5738
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-03-06

Site Id:	19409
Affiliation Type:	Facility Owner
Company Name:	RP STELLAR MILK OWNER, LLC
Contact Type:	PERMIT COORD
Contact Name:	KATINA V. VAZQUEZ
Address1:	156 WILLIAMS STREET
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 406-0030
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-03-06

Tank Info:

Tank Number:	001
Tank Id:	22030
Material Code:	0009
Common Name of Substance:	Gasoline

Equipment Records:

L00 - Piping Leak Detection - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
I01 - Overfill - Float Vent Valve
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)

RP STELLAR MILK LLC (Continued) **U004077721**

H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/30/2008
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	gasoline

Tank Number:	002
Tank Id:	22031
Material Code:	0009
Common Name of Substance:	Gasoline

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
I01 - Overfill - Float Vent Valve
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
L00 - Piping Leak Detection - None

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/30/2008
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	gasoline

K248 **CHELSEA CAR WASH** **NY LTANKS** **S106868684**
WSW **450 W 15TH ST** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.073 mi.
386 ft. **Site 22 of 28 in cluster K**

Relative: **Lower**
Actual: **12 ft.**

LTANKS:

Name:	CHELSEA CAR WASH
Address:	450 W 15TH ST
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	0412142 / 2006-05-17
Facility ID:	0412142
Site ID:	337522
Spill Date:	2005-01-13
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	2005-02-14
CID:	408
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-02-14
Spill Record Last Update:	2010-02-22
Spiller Name:	HECTOR CAPINERI
Spiller Company:	ISLAND TRANSPORTATION
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	QUILVIO MONOZ
Spiller Phone:	(646) 486-4541
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	272857
DEC Memo:	"See duplicate spill #0412147. 2/14/2005 - Sangesland spoke to Quilvio who manages the Chelsea Car Wash/Gas Station. Station is only about 5 years old - all new equipment & alarms - Also the site is right next to the West Side Hwy and the water table is quite high. A water sump pump under the station runs constantly at a very high rate. Any groundwater which may have been under the station around the time of the spill is long gone at this point. Quilvio said he got a gasoline delivery about 3 or 4 weeks ago from Island Transportation. Island overfilled the tanks and the alarms went off. The Island delivery man left without doing any remediation. Quilvio says there was gasoline in 3 manholes around on the site. He called American Resource Technology (Chelsea's regular test & repair company). They came and cleaned the overfill buckets and checked the system. ExxonMobil is somehow involved as a distributer??? Exxon environmental people came to the site to test the air in 2 nearby basements. There continues to be a problem with gasoline smell in the basement next door. Quilvio is now going to hire a contractor to run a couple of test borings in the area to determine if any of the

CHELSEA CAR WASH (Continued) **S106868684**

gasoline went into the ground, or if it was all contained in the overfill buckets. 2/14/05 Spoke to Frank Messina, ExxonMobil Global Remediation (908-730-2055). ExxonMobil only supplies the station with fuel. He stated that ExxonMobil may have initially sent someone to test the air if they did not realize the station was independent. Filed spill report #1016151 with DEP. (KMF) 2/15/05 Changed address from 62-76 10th Ave to 450 W 15th St. Spoke to Quilvio Monoz, operator of Tenth Avenue Car Wash (PBS 2-604379). Quilvio called ExxonMobil territory manager, Mike Romano. ExxonMobil sent Geologic Services Corp., Michael Meyerhofer, with PID. He tested basements which returned negative. Q. Monoz hired American Resource Technology (Bob Arcaro, 718-234-0024) to test the lines. They will also be doing borings around the tanks. Q. Monoz stated he will be taking responsibility for now but feels Island Transportation is responsible for the overfill. (KMF) 2/15/05 Spoke to Bob Arcaro, American Resource Technology. Will be testing fill lines since Q. Monoz stated there was product in the sumps during delivery. The drain plugs in the spill containment boxes would not open. They will probably change these first and then test fill lines. He stated he wasn't sure that there was product lost to the subsurface or that borings were necessary. I requested he do the line tests and speak further with the operator to determine how much product was lost. If borings are necessary, Bill Klein from Franklin will probably do the work. (KMF) 07/28/05 A limited subsurface investigation report by Fenley & Nicol dated 4-13-05 (See File) was reveiwed. Report recommends an extended subsurface investigation to determine the extent of hydrocarbon impact. Attempted to contact Fenley & Nicol- unsuccessful. 2:00pm Called Bob Arcaro (718-234-0024). No answer. LNK. 08/19/05 Bob Arcaro never returned call. Next step- recontact either Fenley & Nicol or Bob Arcaro to determine if a subsurface investigation was completed and if there is a report available. LNK. 04/12/06 - Hough - Received additional documents from Fenley & Nicol concerning limited subsurface investigation. Report concludes that there was no significant impact from the overfill event. Spill should be closed. However there is another open spill on the site 01-03052. Next Step: Regional follow-up on older open spill and verification of finding of report from the most recent spill. Activities may include site visit and obtaining documentation of other remedial activities related to residual impacts from older spill. 02/22/10-Hiralkumar Patel. while investigating spill #: 0911962, came across this spill number. this spill was reported as 500 gal gasoline spilled during delivery at the gas station which is located at 70 10th Avenue. Mr. Shternlicht owned two properties during spill event: 450 W 15th STreet (address in spill report) and 70 10th AVenue (where gas tanks located and actual spill occured). then Mr. Shternlicht sold property at 450 W 15th Street and new owner Mr. Randberg baught it in late 2006. Mulnick LLC. **owner of car wash/gas station property** c/o Milk Studios 450 W 15th Street, 8th Floor New York, NY 10011 Attn.: Erez Shternlicht PH. (212) 645-2797 email: erez@milkstudios.com base on available information, spill was happened on 70 10th AVenue (aka 461-469 W 14th STreet and 58-76 10th Ave). refer to spill #: 0911962 for further details."

Remarks: "The delivery guy pumped 72 inches of material into the tank. The alarms went off and the delivery man just drove off. 200 gallons have been recovered and lost 200-300 gallons into the ground. (OFF TEH WESTSIDE HIGHWAY)"

CHELSEA CAR WASH (Continued) **S106868684**

All Materials:

Site ID:	337522
Operable Unit ID:	1099476
Operable Unit:	01
Material ID:	579814
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	500.00
Units:	G
Recovered:	200.00
Oxygenate:	Not reported

K249 **BABOON PRODS** **RCRA NonGen / NLR** **1004759937**
WSW **450 W 15TH ST - 3RD FLOOR** **FINDS** **NYR000026377**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.073 mi.
386 ft. **Site 23 of 28 in cluster K**

Relative: **Lower**
Actual: **12 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	BABOON PRODS	
Handler Address:		450 W 15TH ST - 3RD FLOOR
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYR000026377
Contact Name:		DAVID GREENHOUSE
Contact Address:		8TH AVE
Contact City,State,Zip:		NEW YORK, NY 10019
Contact Telephone:		212-367-7407
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		8TH AVE
Mailing City,State,Zip:		NEW YORK, NY 10019
Owner Name:		WEST 15TH ST MINI STORAGE INC
Owner Type:		Private
Operator Name:		WEST 15TH ST MINI STORAGE INC
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No

BABOON PRODS (Continued) **1004759937**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WEST 15TH ST MINI STORAGE INC

BABOON PRODS (Continued) **1004759937**

Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	450 W 15TH ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	212-691-7877
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	WEST 15TH ST MINI STORAGE INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	450 W 15TH ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	212-691-7877
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WEST 15TH ST MINI STORAGE INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	450 W 15TH ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	212-691-7877
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: BABOON PRODS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: BABOON PRODS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

BABOON PRODS (Continued) **1004759937**

Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	19960709
Handler Name: BABOON PRODS	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004526442

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004759937
Registry ID:	110004526442
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004526442
Name:	BABOON PRODS
Address:	450 W 15TH ST - 3RD FLOOR
City,State,Zip:	NEW YORK, NY 10011

K250 **CON EDISON - VAULT V6850** **NY MANIFEST** **S120959139**
WSW **450 W 15 ST** **N/A**
< 1/8 **MANHATTAN, NY 10011**
0.073 mi.
386 ft. **Site 24 of 28 in cluster K**

Relative:
Lower

Actual:
12 ft.

NY MANIFEST:

Name:	CON EDISON - VAULT V6850
Address:	450 W 15 ST
City,State,Zip:	MANHATTAN, NY 10011
Country:	USA
EPA ID:	NYP004995260
Facility Status:	Not reported
Location Address 1:	450 W 15 ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MANHATTAN
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004995260
Mailing Name:	CON EDISON - VAULT V6850
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

K251 **TENTH AVENUE CAR WASH, LLC** **NY CBS** **U003712153**
WSW **450 WEST 15TH STREET** **NY MANIFEST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.073 mi.
386 ft. **Site 25 of 28 in cluster K**

Relative:
Lower

Actual:
12 ft.

CBS:

Name:	TENTH AVENUE CAR WASH, LLC
Address:	450 WEST 15TH STREET
City,State,Zip:	NEW YORK, NY 10011
CBS Number:	2-000497
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	583822.51319
UTMY:	4510648.00665

NY MANIFEST:

Name:	BABOON PRODUCTIONS
Address:	450 WEST 15TH STREET
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP000928440

TENTH AVENUE CAR WASH, LLC (Continued) **U003712153**

Facility Status:	Not reported
Location Address 1:	450 WEST 15TH STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000928440
Mailing Name:	BABOON PRODUCTIONS
Mailing Contact:	BABOON PRODUCTIONS
Mailing Address 1:	450 WEST 15TH STREET
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2126377407

K252 **CHELSEA CAR WASH** **NY Spills** **S106866591**
WSW **450 W 15TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.073 mi.
386 ft. **Site 26 of 28 in cluster K**

Relative:
Lower

Actual:
12 ft.

SPILLS:

Name:	CHELSEA CAR WASH
Address:	450 W 15TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0412147 / 2005-02-15
Facility ID:	0412147
Facility Type:	ER
DER Facility ID:	272862
Site ID:	337527
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2005-02-14
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	2005-02-14
CID:	408
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-02-15

CHELSEA CAR WASH (Continued) **S106866591**

Spill Record Last Update:	2005-10-28
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	FOLEY
DEC Memo:	"Address was reported as 62 10th Ave. Consolidated under spill #0412142. Chelsea/Tenth Avenue Car Wash is listed at 450 W. 15th St on PBS #2-604379.(KMF)"
Remarks:	"***** this is the second time this call has been reported. the addresses are different****** "

All Materials:

Site ID:	337527
Operable Unit ID:	1099481
Operable Unit:	01
Material ID:	579819
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	300.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

K253 **CONSTRUCTION SITE** **NY Spills** **S110138743**
WSW **450 WEST 15TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.073 mi.
386 ft. **Site 27 of 28 in cluster K**

Relative: **Lower**

Actual: **12 ft.**

SPILLS:

Name:	CONSTRUCTION SITE
Address:	450 WEST 15TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0909957 / 2009-12-08
Facility ID:	0909957
Facility Type:	ER
DER Facility ID:	371613
Site ID:	422693
DEC Region:	2
Spill Cause:	Other
Spill Class:	D5
SWIS:	3101
Spill Date:	2009-12-08
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2009-12-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported

CONSTRUCTION SITE (Continued) **S110138743**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-12-08
Spill Record Last Update:	2009-12-08
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MICHELE SMITH
DEC Memo:	"This is a duplicate to spill #0909956"
Remarks:	"people at this site have been complaining about a foul smell that has been occuring for about the 3 weeks"

All Materials:

Site ID:	422693
Operable Unit ID:	1178524
Operable Unit:	01
Material ID:	2171932
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

N254 **CON EDISON SERVICE BOX: 3602** **RCRA NonGen / NLR** **1016143256**
NNW **462 W 20TH ST OPPOSITE** **FINDS** **NYP004259925**
< 1/8 **NEW YORK, NY 10014** **ECHO**
0.073 mi. **NY MANIFEST**
387 ft. **Site 3 of 25 in cluster N**

Relative: **Lower**
Actual: **12 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130321
Handler Name:	CON EDISON SERVICE BOX:	3602
Handler Address:		462 W 20TH ST OPPOSITE
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004259925
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003

CON EDISON SERVICE BOX: 3602 (Continued) **1016143256**

Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported

CON EDISON SERVICE BOX: 3602 (Continued) **1016143256**

Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:

Receive Date: 20130221
Handler Name: CON EDISON SERVICE BOX: 3602
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130321
Handler Name: CON EDISON SERVICE BOX: 3602
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063923009

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON SERVICE BOX: 3602 (Continued) **1016143256**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016143256
Registry ID:	110063923009
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110063923009
Name:	CON EDISON SERVICE BOX: 3602
Address:	462 W 20TH ST OPPOSITE
City,State,Zip:	NEW YORK, NY 10014

NY MANIFEST:

Name:	CON EDISON
Address:	462 W 20TH ST OPPOSITE
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004259925
Facility Status:	Not reported
Location Address 1:	OPP 462 W 20TH ST
Code:	BP
Location Address 2:	SERV BOX 3602
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004259925
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/21/2013
Trans1 Recv Date:	02/21/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/22/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004259925
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON SERVICE BOX: 3602 (Continued) **1016143256**

TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010707139JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L255 **CON EDISON** **NY MANIFEST** **S118463855**
SE **OPP 342 W 17TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.076 mi.
402 ft. **Site 8 of 18 in cluster L**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	OPP 342 W 17TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004858058
Facility Status:	Not reported
Location Address 1:	OPP 342 W 17TH ST
Code:	BP
Location Address 2:	SB 3010
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004858058

CON EDISON (Continued) **S118463855**

Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/2015
Trans1 Recv Date:	10/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004858058
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014087634JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **S118463855**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

M256 **ST. PETER'S EPISCOPAL CHURCH** **NY UST** **U001837484**
East **336 WEST 20TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.076 mi.
402 ft. **Site 5 of 10 in cluster M**

Relative:
Higher

Actual:
17 ft.

UST:
Name: ST. PETER'S EPISCOPAL CHURCH
Address: 336 WEST 20TH STREET
City,State,Zip: NEW YORK, NY 10011
Id/Status: 2-401331 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 584306.33958
UTM Y: 4510817.27486
Site Type: Other

Affiliation Records:
Site Id: 19182
Affiliation Type: Facility Owner
Company Name: ST. PETERS EPISCOPAL CHURCH
Contact Type: RECTOR
Contact Name: THE REV. K. DENNIS WINSLOW
Address1: 346 WEST 20TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10011
Country Code: 001
Phone: (212) 929-2390
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2005-10-18

Site Id: 19182
Affiliation Type: Mail Contact
Company Name: ST. PETERS EPISCOPAL CHURCH
Contact Type: Not reported
Contact Name: REV. K. DENNIS WINSLOW
Address1: 346 WEST 20TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10011
Country Code: 001
Phone: (212) 929-2390
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2005-10-18

ST. PETER'S EPISCOPAL CHURCH (Continued) **U001837484**

Site Id:	19182
Affiliation Type:	Facility Operator
Company Name:	ST. PETERS EPISCOPAL CHURCH
Contact Type:	Not reported
Contact Name:	THE REV. K. DENNIS WINSLOW
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 929-2390
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-10-18

Site Id:	19182
Affiliation Type:	Emergency Contact
Company Name:	ST. PETERS EPISCOPAL CHURCH
Contact Type:	Not reported
Contact Name:	THE REV. K. DENNIS WINSLOW
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 929-2390
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-10-18

Tank Info:

Tank Number:	001
Tank ID:	21797
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2500
Install Date:	Not reported
Date Tank Closed:	09/27/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	18
Date Test:	12/12/2002
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

ST. PETER'S EPISCOPAL CHURCH (Continued) **U001837484**

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
I04 - Overfill - Product Level Gauge (A/G)
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None

M257 **CONSTR SITE** **NY Spills** **S123660422**
East **336 WEST 20TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.076 mi.
402 ft. **Site 6 of 10 in cluster M**

Relative: **Higher**
Actual: **17 ft.**

SPILLS:

Name:	CONSTR SITE
Address:	336 WEST 20TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	1810742 / 2019-01-25
Facility ID:	1810742
Facility Type:	ER
DER Facility ID:	534201
Site ID:	581649
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2019-01-23
Investigator:	RHLIN
Referred To:	Not reported
Reported to Dept:	2019-01-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-01-23
Spill Record Last Update:	2019-01-25
Spiller Name:	FASIL
Spiller Company:	TBD
Spiller Address:	336 WEST 20TH ST
Spiller Company:	999
Contact Name:	FASIL
DEC Memo:	"1/25/19-Lin-Spoke to Alex Castro from DEP industrial waste. DEP industrial waste responded and discovered that it was not oil that went into the catch basin but water mixed with cement. Case closed. "
Remarks:	"construction crew spilled oil, unk type, washed to catch basin."

All Materials:

Site ID:	581649

CONSTR SITE (Continued) **S123660422**

Operable Unit ID:	1329339
Operable Unit:	01
Material ID:	2338399
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

K258 **CON EDISON - VAULT SUBMERSIBLE VS6746** **NY MANIFEST** **S120959138**
WSW **454 W 15 ST** **N/A**
< 1/8 **MANHATTAN, NY 10011**
0.077 mi.
406 ft. **Site 28 of 28 in cluster K**

Relative:
Lower

Actual:
11 ft.

NY MANIFEST:

Name:	CON EDISON - VAULT SUBMERSIBLE VS6746
Address:	454 W 15 ST
City,State,Zip:	MANHATTAN, NY 10011
Country:	USA
EPA ID:	NYP004995252
Facility Status:	Not reported
Location Address 1:	454 W 15 ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MANHATTAN
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004995252
Mailing Name:	CON EDISON - VAULT SUBMERSIBLE VS6746
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

N259 **150-10 BEAVER RD/QUEENS** **NY Spills** **S102140928**
NNW **150-10 BEAVER ROAD** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.078 mi.
410 ft. **Site 4 of 25 in cluster N**

Relative: **Lower**

Actual: **11 ft.**

SPILLS:

Name:	150-10 BEAVER RD/QUEENS
Address:	150-10 BEAVER ROAD
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9100573 / 2008-07-23
Facility ID:	9100573
Facility Type:	ER
DER Facility ID:	69118
Site ID:	73431
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	D4
SWIS:	4101
Spill Date:	1991-03-15
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	1991-04-15
CID:	Not reported
Water Affected:	JAMAICA BAY
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-04-17
Spill Record Last Update:	2008-07-23
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY 10/10/95: This is additional information about material spilled from the translation of the old spill file: ANTIFREEZE/BATT.ACID. 07/23/08: Based on age of spill report, lack of ongoing source (so quantities involved were likely relatively small), fact that caller remarks do not indicate release to environment (products were washed into storm drains, which likely discharge to sewage treatment facility), and low likelihood that products involved and location of spill could result in any vapor intrusion impacts to inhabited structures, this spill case is closed. - J. Kolleeny "
Remarks:	"EMPLOYEES CUTTING UP & SALVAGING CARS IN STREET, PRODUCTS WASHED DOWN STREET WITH HOSE FROM HYDRANT INTO STORM DRAIN,REFERRED TO ECO'S."

All Materials:

Site ID:	73431
Operable Unit ID:	951707
Operable Unit:	01
Material ID:	426762
Material Code:	0009

150-10 BEAVER RD/QUEENS (Continued) **S102140928**

Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

I260 **LOT 29,TAXBLOCK 690** **NY E DESIGNATION** **S108076902**
NW **131 10 AVENUE** **N/A**
< 1/8 **MANHATTAN, NY**
0.079 mi.
416 ft. **Site 18 of 22 in cluster I**

Relative: **Lower**
Actual: **11 ft.**

E DESIGNATION:

Name:	LOT 29,TAXBLOCK 690
Address:	131 10 AVENUE
City,State,Zip:	MANHATTAN, NY
Tax Lot(s):	29
Tax Block:	690
Borough Code:	Not reported
E-No:	E-142
Effective Date:	6/23/2005
Satisfaction Date:	Not reported
Ceqr Number:	03DCP069M
Ulurp Number:	050161 ZRM
Zoning Map No:	8b
Description:	Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date:	Not reported
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

I261 **131 10TH AVENUE** **NY Spills** **S102149458**
NW **131 10TH AVENUE** **N/A**
< 1/8 **MANHATTAN, NY**
0.079 mi.
416 ft. **Site 19 of 22 in cluster I**

Relative: **Lower**
Actual: **11 ft.**

SPILLS:

Name:	131 10TH AVENUE
Address:	131 10TH AVENUE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9414276 / 1995-01-27
Facility ID:	9414276
Facility Type:	ER
DER Facility ID:	62393
Site ID:	64825
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B4

131 10TH AVENUE (Continued) **S102149458**

SWIS:	3101
Spill Date:	1995-01-27
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	1995-01-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	1995-01-27
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-02
Spill Record Last Update:	2009-05-29
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was R. AUSTIN "
Remarks:	"WATER MAIN BREAK - BRINGING GASOLINE VAPORS TO SURFACE TO STREET. FD ON SCENE, DEP RESPONDING REQUESTED DEC ON SCENE, 2205 DEC (AUSTIN) ARRIVED ON SCENE, FD / DEC , NO VAPORS, 131 10TH AVE TANK CLOSE"

All Materials:

Site ID:	64825
Operable Unit ID:	1007843
Operable Unit:	01
Material ID:	373019
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I262 **MENDON LEASING CORP** **NY UST** **U001831290**
NW **131 TENTH AVE** **N/A**
< 1/8 **NEW YORK, NY 10023**
0.079 mi.
416 ft. **Site 20 of 22 in cluster I**

Relative: **Lower**
Actual: **11 ft.**

UST:

Name:	MENDON LEASING CORP
Address:	131 TENTH AVE
City,State,Zip:	NEW YORK, NY 10023
Id/Status:	2-032255 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A

MENDON LEASING CORP (Continued) **U001831290**

UTM X: 585700.67425
UTM Y: 4514215.60331
Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id: 200
Affiliation Type: Emergency Contact
Company Name: COTARD REATLY ASSOCIATES
Contact Type: Not reported
Contact Name: THOMAS FASINI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (516) 795-1193
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 200
Affiliation Type: Facility Operator
Company Name: MENDON LEASING CORP
Contact Type: Not reported
Contact Name: MENDON LEASING CORP
Address1: Not reported
Address2: Not reported
City: Not reported
State: NY
Zip Code: Not reported
Country Code: 001
Phone: (212) 255-0900
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2008-07-21

Site Id: 200
Affiliation Type: Facility Owner
Company Name: COTARD REALTY ASSOCIATES
Contact Type: Not reported
Contact Name: Not reported
Address1: 362 KINGSLAND AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 389-2100
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 200
Affiliation Type: Mail Contact

MENDON LEASING CORP (Continued) **U001831290**

Company Name:	COTARD REALTY ASSOCIATES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	362 KINGSLAND AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 389-2100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	880
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	002
Tank ID:	51637
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/01/1996
Registered:	True

MENDON LEASING CORP (Continued) **U001831290**

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 003
Tank ID: 51638
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 03/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 004
Tank ID: 51639

MENDON LEASING CORP (Continued) **U001831290**

Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

J263 **VAULT 5311** **NY Spills** **S104509963**
SSW **W 14TH ST/9TH AVE** **N/A**
< 1/8 **NY, NY**
0.079 mi.
416 ft. **Site 30 of 35 in cluster J**

Relative:
Higher

Actual:
16 ft.

SPILLS:

Name:	VAULT 5311
Address:	W 14TH ST/9TH AVE
City,State,Zip:	NY, NY
Spill Number/Closed Date:	9913020 / 2002-02-27
Facility ID:	9913020
Facility Type:	ER
DER Facility ID:	70222
Site ID:	74930
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3101
Spill Date:	2000-02-15
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-02-15
CID:	371
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

VAULT 5311 (Continued) **S104509963**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-15
Spill Record Last Update:	2002-02-28
Spiller Name:	SAME
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL "
Remarks:	"clean up crew en route."

All Materials:

Site ID:	74930
Operable Unit ID:	1087547
Operable Unit:	01
Material ID:	294882
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I264 **LEAVITT HOUSES -NYCHA** **NY LTANKS** **S100146451**
NW **139-10 34TH AVENUE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.080 mi.
423 ft. **Site 21 of 22 in cluster I**

Relative:
Lower

Actual:
11 ft.

LTANKS:

Name:	LEAVITT HOUSES
Address:	139-10 34TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9008383 / 1995-04-26
Facility ID:	9008383
Site ID:	88424
Spill Date:	1990-10-31
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	1995-04-26
SWIS:	4101
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1990-10-31
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True

LEAVITT HOUSES -NYCHA (Continued) **S100146451**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-11-07
Spill Record Last Update:	1995-04-26
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	80894
DEC Memo:	""
Remarks:	"5K TANK FAILED HORNER EZY CHECK WITH A GROSS LEAK, VISUAL LEAK AT MANHOLE. SEE SPILL # 9108997."

All TTF:

Facility ID:	9008383
Spill Number:	9008383
Spill Tank Test:	1537801
Site ID:	88424
Tank Number:	001
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	88424
Operable Unit ID:	949032
Operable Unit:	01
Material ID:	432215
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Name:	LEAVITT HOUSES -NYCHA
Address:	139-10 34TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9108997 / 2008-07-18
Facility ID:	9108997
Site ID:	222984

LEAVITT HOUSES -NYCHA (Continued) **S100146451**

Spill Date:	1991-11-22
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	jkkann
Referred To:	Not reported
Reported to Dept:	1991-11-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-11-26
Spill Record Last Update:	2008-07-18
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	80894
DEC Memo:	"01/19/06: This spill transferred from J.Kolleeny to S.Kraszewski. 5K tank installed in 1974, two known TTFs. Has passed all subsquent tank tests since this one. Needs a site investigation to determine the impact to soil and GW. - SK 09/01/06: DEC Lead for this spill changed from unassigned to S. Kraszewski. - J. Kolleeny 02/09/07 - J.Kann - Spill reassigned from S.Kraszewski to J.Kann. 07/16/07 - J.Kann - recvd a call from Tara Kam (609-548-1318) requesting information on the spill - specifically if it was still open. I told her it was still open and that it was related to a tank test failure and that I have very little information in my file. She was doing a site assessment for an adjacent property. 07/17/2008- J.Kann - Based on information provided by NYCHA, after manway nuts and bolts were replaced, the tank passed subsequent tightness testing. The latest test was performed on 4/28/08. Based on this information, soil impacts should not have occurred and the spill was closed. NFA."
Remarks:	"5K; E I & R"

All TTF:

Facility ID:	9108997
Spill Number:	9108997
Spill Tank Test:	1539337
Site ID:	222984
Tank Number:	001
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00

LEAVITT HOUSES -NYCHA (Continued) **S100146451**

Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	222984
Operable Unit ID:	963036
Operable Unit:	01
Material ID:	417658
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

N265 **152-156 TENTH AVE/MANHATT** **NY LTANKS** **S104275542**
NNW **152-156 TENTH AVENUE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.081 mi.
427 ft. **Site 5 of 25 in cluster N**

Relative: **Lower**
Actual: **11 ft.**

LTANKS:

Name:	152-156 TENTH AVE/MANHATT
Address:	152-156 TENTH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8903509 / 1989-08-24
Facility ID:	8903509
Site ID:	318167
Spill Date:	1989-04-06
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	1989-08-24
SWIS:	3101
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1989-07-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1989-07-11
Spill Record Last Update:	1989-10-13
Spiller Name:	Not reported
Spiller Company:	GETTY?-CLOSED GAS STA
Spiller Address:	152-156 TENTH AVENUE
Spiller County:	001

152-156 TENTH AVE/MANHATT (Continued) **S104275542**

Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 256475
DEC Memo: ""
Remarks: "STRONG GAS ODOR, DARK STAINS ON CONCRETE & ASPHALT. DEC INSPECTED."

All TTF:
Facility ID: 8903509
Spill Number: 8903509
Spill Tank Test: 1535688
Site ID: 318167
Tank Number: Not reported
Tank Size: 0
Material: 0009
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 318167
Operable Unit ID: 928934
Operable Unit: 01
Material ID: 447596
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

N266 **GETTY PETROLEUM CORP 58542** **RCRA NonGen / NLR** **1001224068**
NNW **152 10TH AVE** **FINDS** **NYR000052845**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.081 mi. **NY MANIFEST**
427 ft. **Site 6 of 25 in cluster N**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20070101
Handler Name: GETTY PETROLEUM CORP 58542
Handler Address: 152 10TH AVE
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYR000052845
Contact Name: Not reported
Contact Address: JERICHO TNPK
Contact City,State,Zip: JERICHO, NY 11753
Contact Telephone: Not reported

GETTY PETROLEUM CORP 58542 (Continued) **1001224068**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	JERICHO TNPK
Mailing City,State,Zip:	JERICHO, NY 11753
Owner Name:	GETTY PETROLEUM CORP
Owner Type:	Private
Operator Name:	GETTY PETROLEUM CORP
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

GETTY PETROLEUM CORP 58542 (Continued) **1001224068**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	GETTY PETROLEUM CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	125 JERICHO TNPK
Owner/Operator City,State,Zip:	JERICHO, NY 11753
Owner/Operator Telephone:	516-286-2600
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GETTY PETROLEUM CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	125 JERICHO TNPK
Owner/Operator City,State,Zip:	JERICHO, NY 11753
Owner/Operator Telephone:	516-286-2600
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GETTY PETROLEUM CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	125 JERICHO TNPK
Owner/Operator City,State,Zip:	JERICHO, NY 11753
Owner/Operator Telephone:	516-286-2600
Owner/Operator Telephone Ext:	Not reported

GETTY PETROLEUM CORP 58542 (Continued) **1001224068**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19990714
Handler Name: GETTY PETROLEUM CORP 58542
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: GETTY PETROLEUM CORP 58542
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: GETTY PETROLEUM CORP 58542
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980331
Handler Name: GETTY PETROLEUM CORP 58542
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

GETTY PETROLEUM CORP 58542 (Continued) **1001224068**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004541808

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001224068
Registry ID: 110004541808
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004541808
Name: GETTY PETROLEUM CORP 58542
Address: 152 10TH AVE
City,State,Zip: NEW YORK, NY 10011

NY MANIFEST:
Name: GETTY PETROLEUM
Address: 152 10TH AVE
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYR000052845
Facility Status: Not reported
Location Address 1: 152 10TH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000052845
Mailing Name: GETTY PETROLEUM
Mailing Contact: STEVE GORDON
Mailing Address 1: 152 10TH AVE
Mailing Address 2: Not reported

GETTY PETROLEUM CORP 58542 (Continued) **1001224068**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5162862600

N267 **GETTY 58542** **NY LTANKS** **U001839223**
NNW **152 TENTH AVE** **NY UST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.081 mi.
427 ft. **Site 7 of 25 in cluster N**

Relative: LTANKS:
Lower

Actual:
11 ft.

Name:	GETTY
Address:	152 10TH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9210231 / 2004-03-10
Facility ID:	9210231
Site ID:	141401
Spill Date:	1992-12-03
Spill Cause:	Tank Test Failure
Spill Source:	Unknown
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	1992-12-03
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-12-03
Spill Record Last Update:	2008-06-09
Spiller Name:	Not reported
Spiller Company:	GETTY
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	120725
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 3/14/03 REASSIGNED FROM ROMMEL TO VOUGHT. 3/9/04-Vought-File review by Vought: Letter from DEC(O'Dowd) to Getty(Ochoterena)-12/10/97. Letter sent requiring installation of three monitoring wells in response to tank test failure on 12/3/92. Report due to DEC by close of business 1/30/98. Site notes by DEC O'Dowd-meeting held on 11/12/97. Site planned for construction of new residential building. Tank Closure Report (Tyree Organization William Conroy)-April 1998. Reason for tank closure is property divestment.

GETTY 58542 (Continued) **U001839223**

One pump island located adjacent to 10th Avenue. Removal of twelve (550-gallon) gasoline USTs and one (550-gallon) waste oil from 3/23-3/25/98. Multistory commercial and apartment buildings located across 10th Avenue to the west, church with a school and playground lcoated across West 20th Street to the north of the subject property . Six endpoint samples were collected including five from the gasoline excavation and one composite sample from the waste oil excavation. Soil analytials show 9990ppb toluene(south wall), 10600ppb napthalene(south wall), 10000ppb toulene(west wall), 15900ppb napthalene(west wall), 156ppb MTBE (Bottom). Waste oil soil endpoint shows 427ppb benzo(a)anthracene and 411ppb benzo(b)fluoranthene. Addendum to the Tank Closure Report (Tyree Org)-5/25/98. The additional work consisted of further excavation of th west wall and the south wall of the gasoline tankfield excavation. The additional excavation resulted in clean(STARS Memo) endpoint soil samples from the two walls. Excavation indicated the presence of a former basement filled with demolition debris. Depth to groundwater estimated at 9 below grade. Two additional soil endpoints were collected for analysis. Soil endpoint analyticals show not TAGM 4046 Soil Cleanup Objective exceedances after second excavation event. Project Summary Report (Tyree Org)-5/25/98. One groundwater sampling event prior to the destruction of the wells during removal of underground storage tanks. Groundwater analyticals show 173ppb MTBE(W-1), 1200ppb MTBE(W-2) and 1890ppb MTBE(W-3). Groundwater flow direction not determined. Closure Request (Tyree Org)-7/8/99. The property was sold by Tyree's client to the 20th Street Association, LLC. The owner has excavated the property for construction purposes . These three wells were destroyed in March 1998 when the gasoline tanks were removed . A total of 305.11 tons of soil were removed from teh tankfield excavation. The entire lot (approximately 114' x 100') has been excavated to the property lines and to a depth of approximately 15'. Tyree requests closure based on 1)only ethylbenzene in one well at 6.1ppb 2)the levels of MTBE were probably significantly reduced by removal of approximately 9 feet of unsaturated and 6' of saturated soil 3)approximately 8550 tons of soil were removed. Tyree requests no further action. Vought reviewed site with DEC Rommel which resulted in spill closure."

Remarks: "ORIGINAL SPILL ASSIGNED TO O'DOWD."

All Materials:

Site ID:	141401
Operable Unit ID:	976702
Operable Unit:	01
Material ID:	407234
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

UST:

Name:	GETTY 58542
Address:	152 TENTH AVE

GETTY 58542 (Continued) **U001839223**

City,State,Zip: NEW YORK, NY 10011
Id/Status: 2-326267 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 583959.99214
UTM Y: 4510985.94346
Site Type: Unknown

Affiliation Records:

Site Id: 15194
Affiliation Type: Mail Contact
Company Name: GETY
Contact Type: Not reported
Contact Name: LUIS OCHONTORENA
Address1: 30-23 GREENPOINT AVENUE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (516) 694-9696
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 15194
Affiliation Type: Facility Operator
Company Name: GETTY 58542
Contact Type: Not reported
Contact Name: L BARKER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 675-5854
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 15194
Affiliation Type: Emergency Contact
Company Name: GETTY
Contact Type: Not reported
Contact Name: EDWARD WALDRON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 729-6500
EMail: Not reported

GETTY 58542 (Continued) **U001839223**

Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	15194
Affiliation Type:	Facility Owner
Company Name:	GETTY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	125 JERICHO TURNPIKE
Address2:	Not reported
City:	JERICHO
State:	NY
Zip Code:	11753
Country Code:	001
Phone:	(516) 576-9500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RDBENDEL
Date Last Modified:	2007-08-07

Tank Info:

Tank Number:	001
Tank ID:	30830
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	03/01/1998
Date Tank Closed:	03/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	00
Date Test:	09/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number:	002
Tank ID:	30831

GETTY 58542 (Continued) **U001839223**

Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/01/1998
Date Tank Closed: 03/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: 09/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number: 003
Tank ID: 30832
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/01/1998
Date Tank Closed: 03/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: 09/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground

GETTY 58542 (Continued) **U001839223**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 004
Tank ID: 30833
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/01/1998
Date Tank Closed: 03/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: 09/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number: 005
Tank ID: 30834
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/01/1998
Date Tank Closed: 02/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: 09/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None

GETTY 58542 (Continued) **U001839223**

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None

Tank Number:	006
Tank ID:	30835
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	03/01/1998
Date Tank Closed:	03/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	00
Date Test:	09/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	007
Tank ID:	30836
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	03/01/1998
Date Tank Closed:	03/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	00
Date Test:	09/01/1993
Next Test Date:	Not reported

GETTY 58542 (Continued) **U001839223**

Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None

Tank Number: 008
Tank ID: 30837
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/01/1998
Date Tank Closed: 03/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: 09/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None

Tank Number: 009
Tank ID: 30838
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/01/1998
Date Tank Closed: 03/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel

GETTY 58542 (Continued) **U001839223**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: 09/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None

Tank Number: 010
Tank ID: 30839
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/01/1998
Date Tank Closed: 03/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: 09/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None

Tank Number: 011
Tank ID: 30840
Tank Status: Closed - Removed
Material Name: Closed - Removed

GETTY 58542 (Continued) **U001839223**

Capacity Gallons: 550
Install Date: 03/01/1998
Date Tank Closed: 03/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: 09/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 012
Tank ID: 30841
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/01/1998
Date Tank Closed: 03/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: 09/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

N268 **AA AAAA 24 HOUR EMRGNCY TOWING** **EDR Hist Auto** **1021618776**
NNW **152 10TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.081 mi.
427 ft. **Site 8 of 25 in cluster N**

Relative: EDR Hist Auto
Lower

Actual: **11 ft.**

Year:	Name:	Type:
1969	MENDON SERVICE STATIONS INC	Gasoline Service Stations
1970	MENDON SERVICE STATIONS INC	Gasoline Service Stations
1971	MENDON SERVICE STATIONS INC	Gasoline Service Stations
1972	MENDON SERVICE STATIONS INC	Gasoline Service Stations
1973	MENDON SERVICE STATIONS INC	Gasoline Service Stations
1974	MENDON SERVICE STATIONS INC	Gasoline Service Stations
1975	MENDON SERVICE STATIONS INC	Gasoline Service Stations
1996	LUCKY SERVICE STATION	Gasoline Service Stations
1997	LUCKY SERVICE STATION	Gasoline Service Stations
2002	LARRY & BERNIES SERVICE STN	Gasoline Service Stations
2003	LARRY & BERNIES SERVICE STN	Gasoline Service Stations
2004	LARRY & BERNIES SERVICE STN	Gasoline Service Stations

R269 **342 WEST 21ST STREET** **NY AST** **U003392612**
ENE **342 WEST 21ST STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.081 mi.
429 ft. **Site 1 of 6 in cluster R**

Relative: AST:
Higher

Actual: **17 ft.**

Name:	342 WEST 21ST STREET
Address:	342 WEST 21ST STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-207160
Program Type:	PBS
UTM X:	584295.94592
UTM Y:	4510907.50112
Expiration Date:	10/29/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	7337
Affiliation Type:	Facility Owner
Company Name:	342 WEST 21 STREET OWNERS INC
Contact Type:	ASSISTANT SECRETARY
Contact Name:	MARSHA KOLKER
Address1:	342 WEST 21ST STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 268-0494
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-04-11

342 WEST 21ST STREET (Continued) **U003392612**

Site Id:	7337
Affiliation Type:	Mail Contact
Company Name:	SANDBERG MANAGEMENT CORP
Contact Type:	Not reported
Contact Name:	MARSHA KOLKER
Address1:	345 SEVENTH AVENUE
Address2:	8TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 268-0494
EMail:	MARSHA@SANDBERGMGMT.COM
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-04-11

Site Id:	7337
Affiliation Type:	Facility Operator
Company Name:	342 WEST 21ST STREET
Contact Type:	Not reported
Contact Name:	ARNOLD HERRERA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 399-8383
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-07-23

Site Id:	7337
Affiliation Type:	Emergency Contact
Company Name:	342 WEST 21 STREET OWNERS INC
Contact Type:	Not reported
Contact Name:	MARSHA KOLKER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 268-0494
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-04-11

Tank Info:

Tank Number:	001
Tank Id:	24952
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

342 WEST 21ST STREET (Continued) **U003392612**

Equipment Records:

	I04 - Overfill - Product Level Gauge (A/G)
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1950
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

N270 **COMMERCIAL** **NY Spills** **S124519589**
NNW **156 TENTH AVE** **N/A**
< 1/8 **MANHATTAN, NY**
0.081 mi.
429 ft. **Site 9 of 25 in cluster N**

Relative: **Lower**
Actual: **11 ft.**

SPILLS:

Name:	COMMERCIAL
Address:	156 TENTH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	1904821 / 2019-08-12
Facility ID:	1904821
Facility Type:	ER
DER Facility ID:	542874
Site ID:	592823
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2019-08-06
Investigator:	HSSEKHON
Referred To:	Not reported
Reported to Dept:	2019-08-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported

COMMERCIAL (Continued) **S124519589**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-08-07
Spill Record Last Update:	2019-08-12
Spiller Name:	Not reported
Spiller Company:	COOK SHOP RESTAURANT
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ROBERT GROFF
DEC Memo:	"8/7/19 - Sekhon Notifier complained that restaurant workers at 156 tenth Avenue Manhattan, On weekday mornings at 6am washing garbage cans on the street and dumping oil and garbage onto street & into catch basin on corner of 10th Avenue and west 20th street. Spoke with Malarie Gilmore at DEP Communications and complaint was forwarded to DEP (gilmorem@dep.nyc.gov) for further action. Reference number # 186844381. Spill closed. "
Remarks:	"The following information was received through the DEC website "Report an Environmental Violation Online" or sent directly by the complainant to an OPP dispatch mailbox: Who Did It: Restaurant workers at 156 tenth Avenue Manhattan by 10011 What Occurred: Weekday mornings at 6am washing garbage cans on the street and dumping oil and garbage into catch basin on corner of 10th Avenue and west 20th street When Did It Occur: August 6th 2019 and daily at 6am week days County: New York Municipality: Manhattan ny Location Or Address: 156 tenth Avenue ny,ny 10011 Cook shop restaurant How Did It Occur: Dumping liquid waste from garbage cans into storm drain and sidewalk / street Additional Details: Photo available by email or text. 914 557 0178 Complainants Name: Robert Groff Complainants Phone: 9145570178 Complainants Email: Mrmomx2@aol.com Date of Submittal: 08/07/2019 DLE ADVISED"

All Materials:

Site ID:	592823
Operable Unit ID:	1340423
Operable Unit:	01
Material ID:	2350129
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

N271 **CON EDISON SERVICE BOX: 43072** **RCRA NonGen / NLR** **1016142982**
NNW **156 10TH AVE OPPOSITE** **NY MANIFEST** **NYP004257119**
< 1/8 **NEW YORK, NY 10014**
0.081 mi.
429 ft. **Site 10 of 25 in cluster N**

Relative: RCRA NonGen / NLR:
Lower

Date Form Received by Agency:	20130320
Handler Name:	CON EDISON SERVICE BOX: 43072
Handler Address:	156 10TH AVE OPPOSITE
Handler City,State,Zip:	NEW YORK, NY 10014

Actual:
11 ft.

CON EDISON SERVICE BOX: 43072 (Continued) **1016142982**

EPA ID:	NYP004257119
Contact Name:	JUAN RODRIGUEZ
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	347-865-5931
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No

CON EDISON SERVICE BOX: 43072 (Continued) **1016142982**

TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130220
Handler Name: CON EDISON SERVICE BOX:	43072
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130320
Handler Name: CON EDISON SERVICE BOX:	43072
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON SERVICE BOX: 43072 (Continued) **1016142982**

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 156 10TH AVE OPPOSITE
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYP004257119
Facility Status: Not reported
Location Address 1: OPP 156 10TH AVE
Code: BP
Location Address 2: SERV BOX 43072
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004257119
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 02/20/2013
Trans1 Recv Date: 02/20/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/20/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004257119
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 010846483JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N

CON EDISON SERVICE BOX: 43072 (Continued) **1016142982**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

O272 **CON EDISON SERVICE BOX: 3775** **RCRA NonGen / NLR** **1016967677**
NNE **437 W 21ST ST FRONT OF** **NY MANIFEST** **NYP004412755**
< 1/8 **NEW YORK, NY 10011**
0.082 mi.
432 ft. **Site 2 of 9 in cluster O**

Relative: **Higher**
Actual: **14 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140206
Handler Name:	CON EDISON SERVICE BOX:	3775
Handler Address:		437 W 21ST ST FRONT OF
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004412755
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported

CON EDISON SERVICE BOX: 3775 (Continued) **1016967677**

Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 3775 (Continued) **1016967677**

Sub-Part P Indicator: No

Historic Generators:

Receive Date:	20140106
Handler Name: CON EDISON SERVICE BOX:	3775
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140206
Handler Name: CON EDISON SERVICE BOX:	3775
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	437 W 21ST ST FRONT OF
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004412755
Facility Status:	Not reported
Location Address 1:	437 W 21ST ST
Code:	BP
Location Address 2:	SB3775
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

CON EDISON SERVICE BOX: 3775 (Continued) **1016967677**

NY MANIFEST:

EPAID:	NYP004412755
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/06/2014
Trans1 Recv Date:	01/06/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004412755
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002328536GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON SERVICE BOX: 3775 (Continued) **1016967677**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L273 **338 WEST 17 LLC** **NY AST** **U003397341**
SE **338 WEST 17TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.082 mi.
432 ft. **Site 9 of 18 in cluster L**

Relative:
Higher

Actual:
18 ft.

AST:

Name:	338 WEST 17 LLC
Address:	338 WEST 17TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-603665
Program Type:	PBS
UTM X:	584191.96844
UTM Y:	4510626.42066
Expiration Date:	11/27/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	25572
Affiliation Type:	Mail Contact
Company Name:	338 W 17 ST HOLDINGS LLC
Contact Type:	Not reported
Contact Name:	LEOR SABET
Address1:	38 WEST 31ST STREET
Address2:	SUITE 3
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 461-4039
EMail:	LEOR@SABETGROUP.COM
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-02-23

Site Id:	25572
Affiliation Type:	Emergency Contact
Company Name:	338 W 17 ST HOLDINGS LLC
Contact Type:	Not reported
Contact Name:	LEOR SABET
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 582-9978
EMail:	Not reported

338 WEST 17 LLC (Continued) **U003397341**

Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-02-23

Site Id:	25572
Affiliation Type:	Facility Operator
Company Name:	338 WEST 17 LLC
Contact Type:	Not reported
Contact Name:	LEOR SABET
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 461-4039
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-02-23

Site Id:	25572
Affiliation Type:	Facility Owner
Company Name:	338 W 17 ST HOLDINGS LLC
Contact Type:	MEMBER
Contact Name:	LEOR SABET
Address1:	38 WEST 31ST STREET, SUITE 3
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 461-4039
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-02-23

Tank Info:

Tank Number:	001
Tank Id:	55134
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	B00 - Tank External Protection - None
	F00 - Pipe External Protection - None
	C01 - Pipe Location - Aboveground
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.

338 WEST 17 LLC (Continued) **U003397341**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/01/1965
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

J274 **CON EDISON** **NY MANIFEST** **S116551669**
South **56 9 AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.082 mi.
434 ft. **Site 31 of 35 in cluster J**

Relative:
Higher

Actual:
16 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	56 9 AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004502035
Facility Status:	Not reported
Location Address 1:	56 9 AVE
Code:	BP
Location Address 2:	SB39631
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004502035
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRIVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/16/2014
Trans1 Recv Date:	04/16/2014

CON EDISON (Continued) **S116551669**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004502035
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406253GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J275 **CON EDISON** **NY MANIFEST** **S126115976**
South **56 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.082 mi.
434 ft. **Site 32 of 35 in cluster J**

Relative: **Higher**
Actual: **16 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	56 9TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP005241500
Facility Status:	Not reported
Location Address 1:	9TH AVE & 15TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported

CON EDISON (Continued) **S126115976**

Location City:	MANHATTAN
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005241500
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	11/03/2018
Trans1 Recv Date:	11/03/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/05/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP005241500
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	008165845FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1

CON EDISON (Continued) **S126115976**

Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	B007
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J276 **OLD HOMESTEAD REST** **NY Spills** **S102663644**
South **56 NINTH AVE** **N/A**
< 1/8 **MANHATTAN, NY**
0.082 mi.
434 ft. **Site 33 of 35 in cluster J**

Relative: **Higher**
Actual: **16 ft.**

SPILLS:

Name:	OLD HOMESTEAD REST
Address:	56 NINTH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9707247 / 2005-12-21
Facility ID:	9707247
Facility Type:	ER
DER Facility ID:	118521
Site ID:	138619
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	B3
SWIS:	3101
Spill Date:	1997-09-18
Investigator:	JMPELTON
Referred To:	Not reported
Reported to Dept:	1997-09-18
CID:	267
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-09-18
Spill Record Last Update:	2005-12-21
Spiller Name:	MARK CHERRY
Spiller Company:	OLD HOMESTEAD REST
Spiller Address:	56 NINTH AVE
Spiller Company:	001
Contact Name:	MARK CHERRY
DEC Memo:	"SEPTEMBER, 2004 Prior to Sept, 2004 data translation this spill Lead_DEC Field was M TIBBE June, 2005 As part of Spills Backlog Reduction Initiative, petroleum spill #9707247 was transferred to Jason Pelton. August 16, 2005 Jason Pelton contacted the current property owner at 56 9th Avenue where the spill was reported. The current owner is Greg Cherry. Greg and his brother Mark own the Old Homestead Restaurant. The petroleum spill was reported when the

OLD HOMESTEAD REST (Continued) **S102663644**

kitchen-area of the restaurant was being expanded and a 500-gallon underground storage tank was closed in-place. The tank closure involved removal of the remaining oil, cutting open the tank, and the backfilling of the tank with sand. The underground storage tank was replaced with an above ground liquid propane tank. During the restaurant expansion, there was no evidence of a petroleum spill. The restaurant expansion and tank closure were completed by Quality General Contractors ((917)494-9103). The contact person for Quality General Contractors is Patsy and he was contacted to provide documentation on the underground storage tank closure. Patsy confirmed the information provided by Greg Cherry and indicated that the closure included removal of residual oil from 500-gallon tank, opening of the the tank, and backfilling with sand. Patsy indicated that there was no evidence of a petroleum spill. December 21, 2005 Based on information provided by contractor and current property owner that the tank was closed in-place, there was no evidence of a petroleum spill during the building construction work, no quantity of petroleum was actually spilled, and the tank was closed out over eight years ago, Spill #9707247 was closed by Jason Pelton on December 21, 2005."

Remarks: "CALLER STATES THAT THE ABOVE LOCATION REPLACED THE UNDERGROUND TANK WITH AN AB0VE GROUND TANK AND LEFT THE UNDERGROUND TANK IN THE GROUND TANK IS A 500 GALLONS TANK TANK IS UNDERGROUND NEXT TO BEER BOX AND UNDER THE SPRINKLER PIPES WHERE YOU OPEN AND CLOSE THE SPRINKLERS"

All Materials:

Site ID:	138619
Operable Unit ID:	1050607
Operable Unit:	01
Material ID:	332827
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

J277 **CON EDISON** **RCRA NonGen / NLR** **1025504649**
South **56 9TH AVE** **NYP005241500**
< 1/8 **NEW YORK, NY 10011**
0.082 mi.
434 ft. **Site 34 of 35 in cluster J**

Relative: RCRA NonGen / NLR:
Higher

Actual: Date Form Received by Agency:		20200413
16 ft. Handler Name:	CON EDISON	
Handler Address:		56 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP005241500
Contact Name:		Not reported
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported

CON EDISON (Continued) **1025504649**

Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported

CON EDISON (Continued) **1025504649**

Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200413
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20181119
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20181017
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20200413
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

CON EDISON (Continued) **1025504649**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

J278 **CON EDISON - SERVICE BOX 39626** **NY MANIFEST** **S120958977**
SSW **59 9 AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.083 mi.
439 ft. **Site 35 of 35 in cluster J**

Relative:
Higher

Actual:
15 ft.

NY MANIFEST:

Name:	CON EDISON - SERVICE BOX 39626
Address:	59 9 AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004981153
Facility Status:	Not reported
Location Address 1:	59 9 AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004981153
Mailing Name:	CON EDISON - SERVICE BOX 39626
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

O279 **CHELSEA MANOR** **NY AST** **U003392320**
NNE **421 WEST 21ST STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.083 mi.
439 ft. **Site 3 of 9 in cluster O**

Relative:
Higher

Actual:
15 ft.

AST:

Name:	CHELSEA MANOR
Address:	421 WEST 21ST STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-311375
Program Type:	PBS
UTM X:	584153.71040
UTM Y:	4511011.19896
Expiration Date:	10/19/2024
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	14270
Affiliation Type:	Facility Owner
Company Name:	421 WEST 21ST STREET LLC C/O SILVERSTONE PROPERTY
Contact Type:	DIRECTOR OF FACILITES MANAGEMENT
Contact Name:	MIKE RADONCIC
Address1:	520 MADISON AVE, SUITE 3501
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(646) 786-8000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-09-05

Site Id:	14270
Affiliation Type:	Facility Operator
Company Name:	CHELSEA MANOR
Contact Type:	Not reported
Contact Name:	DRITON SINISTAJ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 870-3271
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-09-05

Site Id:	14270
Affiliation Type:	Mail Contact
Company Name:	SILVERSTONE PROPERTY GROUP, LLC
Contact Type:	Not reported
Contact Name:	MIKE RADONCIC

CHELSEA MANOR (Continued) **U003392320**

Address1:	520 MADISON AVE
Address2:	SUITE 3501
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(646) 786-8000
EMail:	SERVICE@SILVERSTONEPG.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-09-05

Site Id:	14270
Affiliation Type:	Emergency Contact
Company Name:	421 WEST 21ST STREET LLC C/O SILVERSTONE PROPERTY
Contact Type:	Not reported
Contact Name:	TONY SINISTAJ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 988-7635
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-09-05

Tank Info:

Tank Number:	001
Tank Id:	24405
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F02 - Pipe External Protection - Original Sacrificial Anode
I05 - Overfill - Vent Whistle

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/19/1939
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

CHELSEA MANOR (Continued) **U003392320**

Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	09/05/2019
Material Name:	#4 fuel oil (on-site consumption)

O280 **DR. SERSINI** **NY LTANKS** **S104275721**
NNE **415 WEST 21ST STREET** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.083 mi.
439 ft. **Site 4 of 9 in cluster O**

Relative:
Higher

Actual:
15 ft.

LTANKS:

Name:	DR. SERSINI
Address:	415 WEST 21ST STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9411689 / 1994-12-02
Facility ID:	9411689
Site ID:	151614
Spill Date:	1994-12-02
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	1994-12-02
SWIS:	3101
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1994-12-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-01-12
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	WHALECO FUEL
Spiller Address:	1 COFFEY STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	128850
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks:	"TANK WAS ALREADY FULL. WHALECO WENT TO FILL AND IT OVERFILLED. IN PROCESS OF CLEANING UP. NCB."

All Materials:

Site ID:	151614
Operable Unit ID:	1009558
Operable Unit:	01
Material ID:	374028
Material Code:	0001A

DR. SERSINI (Continued) **S104275721**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

O281 **415 W. 21ST STREET** **NY LTANKS** **S102672732**
NNE **415 W. 21ST STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.083 mi.
439 ft. **Site 5 of 9 in cluster O**

Relative:
Higher

Actual:
15 ft.

LTANKS:

Name:	415 W. 21ST STREET
Address:	415 W. 21ST STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9412289 / 1994-12-14
Facility ID:	9412289
Site ID:	267931
Spill Date:	1994-12-14
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	1994-12-14
SWIS:	3101
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	1994-12-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-01-30
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	WHALECO
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	218276
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD "
Remarks:	"SPILL CONTAINED ON CONCRETE WALKWAY-SERVICE TO DO CLEANUP"

All Materials:

Site ID:	267931
Operable Unit ID:	1010003
Operable Unit:	01

415 W. 21ST STREET (Continued) **S102672732**

Material ID:	374612
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

L282 **CON EDISON** **RCRA NonGen / NLR** **1016969683**
SSE **341 W 16TH ST FRONT OF** **NY MANIFEST** **NYP004433629**
< 1/8 **NEW YORK, NY 10011**
0.083 mi.
440 ft. **Site 10 of 18 in cluster L**

Relative: **Higher**
Actual: **18 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20151214
Handler Name:	CON EDISON	
Handler Address:		341 W 16TH ST FRONT OF
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004433629
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No

CON EDISON (Continued) **1016969683**

Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20151214
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON (Continued) **1016969683**

Receive Date: 20151214
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140304
Handler Name: CON EDISON SERVICE BOX: 2796
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON ED
Address: 341 W 16TH ST FRONT OF
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004433629
Facility Status: Not reported
Location Address 1: 341 W 16 ST
Code: BP
Location Address 2: SB 2796
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004433629
Mailing Name: CON ED
Mailing Contact: TOM TEELING

CON EDISON (Continued) **1016969683**

Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/04/2014
Trans1 Recv Date:	02/04/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/06/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004433629
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002328758GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L283 **CON EDISON** **NJ MANIFEST** **S120666084**
SSE **341 W 16TH ST FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.083 mi.
440 ft. **Site 11 of 18 in cluster L**

Relative:
Higher

Actual:
18 ft.

NJ MANIFEST:

EPA Id:	NYP004433629
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002613567GBF
EPA ID:	NYP004433629
Date Shipped:	12/14/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120666084**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

L284 **BTWN 8TH & 9TH AVE** **NY Spills** **S104507153**
SSE **335 WEST 16TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.084 mi.
444 ft. **Site 12 of 18 in cluster L**

Relative: **Higher**
Actual: **18 ft.**

SPILLS:

Name:	BTWN 8TH & 9TH AVE
Address:	335 WEST 16TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9901094 / 2005-10-06
Facility ID:	9901094
Facility Type:	ER
DER Facility ID:	61847
Site ID:	64133
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	3101
Spill Date:	1999-04-28
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	1999-04-28
CID:	199
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-04-28
Spill Record Last Update:	2005-10-06
Spiller Name:	FRANK J. DENOIA
Spiller Company:	FRANK J. DENOIA
Spiller Address:	335 WEST 16 ST.
Spiller Company:	001
Contact Name:	JOHN RAGUSO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 5/5/99 - Saccacio - On 4/28/99 DEC (Saccacio) responded to the spill location after several attempts to contact the parties involved. On scene the building was closed up hindering any entry or further investigation. Called the contacts (John Raguso) home telephone and spoke w/ his wife. She said that he was on the train home and she would have him call me when he got in. I stood by until John called. He said that they never saw any spilled oil but they suspect oil is spilling because strong odors are detected when the tank(s) are being filled. The odors are coming from the under the

BTWN 8TH & 9TH AVE (Continued) **S104507153**

sidewalk vault that is currently inaccessible. On 4/29/30, I spoke with John and told him I wanted him to set up a tightness test for the line. Instead we agreed to visually inspect the site line on 5/7/99. He asked that the state send him a letter detailing its requirements. He asked if I could fax it to 212-631-8066. On 5/5/99 I called to get the owners name and PBS # so I could send him the letter he requested. The bricked in stairwell window was removed, there was lots of old contaminated soil behind it. The contractor uncovered the fill line and confirmed it was the source of the leak. The consultant Dave Pelletier of Jade Environmental estimates that the fill line had been leaking for approx. 50 years and that the total amount of product in the window vault is in excess of 100 gallons. He said that the oil appears to have decomposed and aged further confirming his suspicion the fill line leak was created when the window vault was filled in some 50 years ago. I have requested that they install a monitoring well in the sidewalk south of the window vault and two soil borings east and west of the vault. They agreed. John Raguso of Emteque the lead consultant on the job said that they were going to close the tank and do 4 Goeprober samples around the outside. I asked him to cut a hole in the bottom of the tank and sample and he agreed. They are also bringing in a structural consultant to assess the structural integrity of the sidewalk. As per my request, they are also going to do a horizontal boring through the wall to sample the soil underneath the window vault. I have looked into the tightness test report because the site conditions indicate the pipe has been leaking for some time. I gave a copy of the report to Peter Huang and asked him to look into it. On the surface the report it appears that the water level outside the tank was not measured and that the water in the tank was reported as 0 once and 0.5 in another section. The report also says that the tester used a water sensor but I have not seen any signs that one was actually used because the there was not place to put the sensor. Dave reported that groundwater is 2 feet above the tank bottom. Turned over false tank test report to Peter Chao. He is investigating John and Dave will be submitting a work plan for DEC approval. 5/27/99 - Saccacio - Workplan was received and conditionally accepted by DEC. Letter went out requesting further investigation. 5/10/04 - AUSTIN - TRANSFERRED FROM SACCACIO TO AUSTIN FOR REASSIGNMENT - END 8/25/05 - Austin - Reassigned to Rahman, to investigate status of this matter. 10.06.05 SR// Steven P. Saccacio closed this spill on 02.09.2000. NFA letter is in file."

Remarks: "APPEARS TO BE A PROBLEM WITH THE FILL LINE THAT GOES INTO A STORAGE AREA - ALL EQUIPMENT HAS NOT BEEN CHECKED AS OF YET - APPEARS TO HAVE BEEN A CRONIC PROBLEM"

All Materials:

Site ID:	64133
Operable Unit ID:	1075880
Operable Unit:	01
Material ID:	304634
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

L285 **FRANK J DENOIA** **NY UST** **U001832833**
SSE **335 WEST 16 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.084 mi.
444 ft. **Site 13 of 18 in cluster L**

Relative:
Higher

Actual:
18 ft.

UST:

Name:	FRANK J DENOIA
Address:	335 WEST 16 ST
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-112739 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584169.86454
UTM Y:	4510576.66620
Site Type:	Unknown

Affiliation Records:

Site Id:	3587
Affiliation Type:	Facility Owner
Company Name:	FRANK J DENOIA
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	335 WEST 16 ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 242-5560
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	3587
Affiliation Type:	Mail Contact
Company Name:	FRANK J DENOIA
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	335 WEST 16 ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 242-5560
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	3587
Affiliation Type:	Facility Operator
Company Name:	FRANK J DENOIA
Contact Type:	Not reported
Contact Name:	FRANK J DENOIA
Address1:	Not reported

FRANK J DENOIA (Continued) **U001832833**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 242-5560
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	3587
Affiliation Type:	Emergency Contact
Company Name:	FRANK J DENOIA
Contact Type:	Not reported
Contact Name:	FRANK J DENOIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 242-5560
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	5541
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	3000
Install Date:	Not reported
Date Tank Closed:	09/30/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	03
Date Test:	06/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	LXZIELIN
Last Modified:	04/14/2017

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

FRANK J DENOIA (Continued) **U001832833**

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

L286 **A PARABLES TAIL** **RCRA NonGen / NLR** **1000345178**
SSE **335 W 16TH ST** **FINDS** **NYD981483340**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.084 mi. **NY MANIFEST**
444 ft. **Site 14 of 18 in cluster L**

Relative: **Higher**
Actual: **18 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	A PARABLES TAIL	
Handler Address:		335 W 16TH ST
Handler City,State,Zip:		NEW YORK, NY 10011-5902
EPA ID:		NYD981483340
Contact Name:		Not reported
Contact Address:		9TH AVE
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		9TH AVE
Mailing City,State,Zip:		NEW YORK, NY 10011
Owner Name:		BARRY SILVERBERG
Owner Type:		Private
Operator Name:		BARRY SILVERBERG
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No

A PARABLES TAIL (Continued) **1000345178**

Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	BARRY SILVERBERG
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	BARRY SILVERBERG
Legal Status:	Private

A PARABLES TAIL (Continued) **1000345178**

Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	BARRY SILVERBERG
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: A PARABLES TAIL	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20060101
Handler Name: A PARABLES TAIL	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: A PARABLES TAIL	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

A PARABLES TAIL (Continued) **1000345178**

Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	19860421
Handler Name: A PARABLES TAIL	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violation:

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19900329
Actual Return to Compliance Date:	19901003
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	19900817
Enforcement Identifier:	001
Date of Enforcement Action:	19900426
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYDEC
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported

A PARABLES TAIL (Continued) **1000345178**

Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19900329
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYDEC
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 19901003
Scheduled Compliance Date: 19900817
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

FINDS:
Registry ID: 110004404350

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000345178
Registry ID: 110004404350
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004404350
Name: A PARABLES TAIL
Address: 335 W 16TH ST
City,State,Zip: NEW YORK, NY 10011

NY MANIFEST:
Name: A PARABLES TAIL
Address: 335 W 16TH ST
City,State,Zip: NEW YORK, NY 10011-5902
Country: USA
EPA ID: NYD981483340
Facility Status: Not reported
Location Address 1: 172 9TH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

A PARABLES TAIL (Continued) **1000345178**

NY MANIFEST:

EPAID:	NYD981483340
Mailing Name:	A PARABLES TAIL
Mailing Contact:	A PARABLES TAIL
Mailing Address 1:	172 9TH AVENUE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2122551457

O287 **CON EDISON MANHOLE: 3776** **RCRA NonGen / NLR** **1016967678**
NNE **427 W 21ST ST FRONT OF** **NY MANIFEST** **NYP004412763**
< 1/8 **NEW YORK, NY 10011**
0.084 mi.
445 ft. **Site 6 of 9 in cluster O**

Relative: **Higher**
Actual: **14 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20140206
Handler Name:	CON EDISON MANHOLE: 3776
Handler Address:	427 W 21ST ST FRONT OF
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004412763
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No

CON EDISON MANHOLE: 3776 (Continued) **1016967678**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140106
Handler Name:	CON EDISON MANHOLE: 3776
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON MANHOLE: 3776 (Continued) **1016967678**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140206
Handler Name: CON EDISON MANHOLE: 3776
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 427 W 21ST ST FRONT OF
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004412763
Facility Status: Not reported
Location Address 1: 427 W 21ST ST
Code: BP
Location Address 2: SB3776
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004412763
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

CON EDISON MANHOLE: 3776 (Continued) **1016967678**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/06/2014
Trans1 Recv Date:	01/06/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004412763
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002328537GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	700
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

O288 **433 W. 21 STREET** **NY AST** **A100292361**
NNE **433 WEST 21ST STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.084 mi.
445 ft. **Site 7 of 9 in cluster O**

Relative:
Higher

Actual:
14 ft.

AST:

Name:	433 W. 21 STREET
Address:	433 WEST 21ST STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608134
Program Type:	PBS
UTM X:	584121.24570
UTM Y:	4511028.57927
Expiration Date:	12/06/2017
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	29986
Affiliation Type:	Facility Owner
Company Name:	433 WEST ASSOC.
Contact Type:	PROPERTY MANAGER
Contact Name:	LOUIS ZADRIMA
Address1:	400 W. 59TH ST.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10019
Country Code:	001
Phone:	(212) 245-1870
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2007-11-27

Site Id:	29986
Affiliation Type:	Mail Contact
Company Name:	URBAN ASSOC., LLC
Contact Type:	Not reported
Contact Name:	LOUIS ZADRIMA
Address1:	400 WEST 59TH STREET
Address2:	3RD FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10019
Country Code:	001
Phone:	(212) 245-1870
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2013-01-15

Site Id:	29986
Affiliation Type:	Facility Operator
Company Name:	433 W. 21 STREET
Contact Type:	Not reported
Contact Name:	JOSEPH PITRE

433 W. 21 STREET (Continued) **A100292361**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 255-1501
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2007-11-27

Site Id:	29986
Affiliation Type:	Emergency Contact
Company Name:	433 WEST ASSOC.
Contact Type:	Not reported
Contact Name:	LOUIS ZADRIMA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 245-1870
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	1
Tank Id:	64601
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

	I05 - Overfill - Vent Whistle
	F06 - Pipe External Protection - Wrapped
	H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
	J03 - Dispenser - Gravity
	L00 - Piping Leak Detection - None
	E02 - Piping Secondary Containment - Vault (with Access)
	G03 - Tank Secondary Containment - Vault (w/o access)
	K01 - Spill Prevention - Catch Basin
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	C01 - Pipe Location - Aboveground
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/1965
Capacity Gallons:	3000

433 W. 21 STREET (Continued) **A100292361**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	KAKYER
Last Modified:	04/14/2017
Material Name:	#4 fuel oil (on-site consumption)

M289 **CON EDISON** **NY MANIFEST** **S117058716**
ENE **337-335 W 20TH ST & 9TH AVE E** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.085 mi.
451 ft. **Site 7 of 10 in cluster M**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	337-335 W 20TH ST & 9TH AVE E
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004508495
Facility Status:	Not reported
Location Address 1:	337 W 20 ST & 9TH AVE
Code:	BP
Location Address 2:	SB 3619
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004508495
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2014
Trans1 Recv Date:	04/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004508495

CON EDISON (Continued) **S117058716**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416541GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Q290 **89-10 63RD DR/QUEENS** **NY Spills** **S102141594**
West **89-10 63RD DRIVE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.085 mi.
451 ft. **Site 10 of 25 in cluster Q**

Relative: SPILLS:
Lower

Actual: Name:	89-10 63RD DR/QUEENS
10 ft. Address:	89-10 63RD DRIVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9003282 / 1995-05-25
Facility ID:	9003282
Facility Type:	ER
DER Facility ID:	75392
Site ID:	81489
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	4101
Spill Date:	1990-06-21
Investigator:	WILSON
Referred To:	Not reported

89-10 63RD DR/QUEENS (Continued) **S102141594**

Reported to Dept:	1990-06-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	1995-05-25
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-06-27
Spill Record Last Update:	1995-05-25
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"SPEEDY DRY BEING APPLIED, SPILL TO BE HANDLED BY BAERENKLAU."

All Materials:

Site ID:	81489
Operable Unit ID:	943426
Operable Unit:	01
Material ID:	437987
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

R291 **TEN GAL XFMR OIL IN VAULT # 9770** **NY Spills** **S108762662**
ENE **340 W 21 STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.085 mi.
451 ft. **Site 2 of 6 in cluster R**

Relative: **Higher**
Actual: **17 ft.**

SPILLS:

Name:	TEN GAL XFMR OIL IN VAULT # 9770
Address:	340 W 21 STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0704215 / 2007-08-20
Facility ID:	0704215
Facility Type:	ER
DER Facility ID:	333725
Site ID:	384313
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	3101
Spill Date:	2007-07-14
Investigator:	gdbreen
Referred To:	Not reported

TEN GAL XFMR OIL IN VAULT # 9770 (Continued) **S108762662**

Reported to Dept:	2007-07-14
CID:	76
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-07-16
Spill Record Last Update:	2007-08-20
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	340 W 21ST ST
Spiller Company:	999
Contact Name:	ERT DESK
DEC Memo:	"08/20/07 - See eDocs for Con Ed report detailing cleanup and closure. 207009. see eDocs"
Remarks:	"CALLER REPORTS CLEANUP PENDING LAB RESULTS. NO TO QUESTIONS 1-4;YES TO 5. REF #207009."

All Materials:

Site ID:	384313
Operable Unit ID:	1141623
Operable Unit:	01
Material ID:	2131832
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

N292 **CON EDISON** **RCRA NonGen / NLR** **1018277743**
NW **438 W 19TH ST & 10TH AVE** **FINDS** **NYP004724811**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.086 mi.
453 ft. **Site 11 of 25 in cluster N**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150204
Handler Name:	CON EDISON	
Handler Address:		432 W 19TH ST & 10TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004724811
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02

CON EDISON (Continued) **1018277743**

Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No

CON EDISON (Continued) **1018277743**

Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150204
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150204
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID:	110067693678

CON EDISON (Continued) **1018277743**

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018277743
Registry ID:	110067693678
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067693678
Name:	CON EDISON
Address:	438 W 19TH ST & 10TH AVE
City,State,Zip:	NEW YORK, NY 10011

P293 **APHRODITE FRENCH CLEANERS** **EDR Hist Cleaner** **1019929978**
NE **182 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.086 mi.
456 ft. **Site 10 of 17 in cluster P**

Relative: EDR Hist Cleaner
Higher

Actual: **16 ft.**

Year:	Name:	Type:
2009	APHRODITE FRENCH CLEANERS	Drycleaning Plants, Except Rugs

---

M294 **CON EDISON** **NY MANIFEST** **S118463774**
East **336 W 19TH ST** **N/A**
< 1/8 **NEW YORK, NY**
0.087 mi.
458 ft. **Site 8 of 10 in cluster M**

Relative: NY MANIFEST:
Higher

Actual: **18 ft.**

Name:	CON EDISON
Address:	336 W 19TH ST
City,State,Zip:	NEW YORK, NY
Country:	USA
EPA ID:	NYP004856843
Facility Status:	Not reported
Location Address 1:	336 W 19TH ST
Code:	BP
Location Address 2:	M 3410
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004856843
Mailing Name:	CON EDISON

CON EDISON (Continued) **S118463774**

Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	10/20/2015
Trans1 Recv Date:	10/20/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/27/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004856843
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002832282GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON EDISON (Continued) **S118463774**

Waste Code 1_6: Not reported

I295
NW
< 1/8
0.087 mi.
458 ft.

CON EDISON - WEST 18TH ST. GAS WORKS MGP **EDR MGP** **1008407994**
WEST 16TH - WEST 20TH STS. **N/A**
NEW YORK, NY 10011

Site 22 of 22 in cluster I

Relative:
Lower

Actual:
10 ft.

Manufactured Gas Plants:
No additional information available

Q296
West
< 1/8
0.087 mi.
460 ft.

87-10 126TH ST/QUEENS **NY Spills** **S102141114**
87-10 126TH STREET **N/A**
NEW YORK CITY, NY

Site 11 of 25 in cluster Q

Relative:
Lower

Actual:
10 ft.

SPILLS:

Name:	87-10 126TH ST/QUEENS
Address:	87-10 126TH STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9102059 / 1991-05-23
Facility ID:	9102059
Facility Type:	ER
DER Facility ID:	179780
Site ID:	217162
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	Not reported
SWIS:	4101
Spill Date:	1991-05-21
Investigator:	GELLER
Referred To:	Not reported
Reported to Dept:	1991-05-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	1991-05-23
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-06-03
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"APPEARS TO BE CLEANING OUT BLDG,DUMPING & WASHING IN HYDRANT &

87-10 126TH ST/QUEENS (Continued) **S102141114**

SEWER, NYCPD (102PCT) NOTIFIED, DOSEN'T APPEAR TO BE REGULATED SUBSTANCE, NO ACTION."

All Materials:

Site ID:	217162
Operable Unit ID:	955798
Operable Unit:	01
Material ID:	424583
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

O297 **445 WEST 21ST STREET** **NY UST** **U004330255**
North **445 WEST 21ST STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.088 mi.
467 ft. **Site 8 of 9 in cluster O**

Relative: **Lower**

Actual: **13 ft.**

UST:

Name:	445 WEST 21ST STREET
Address:	445 WEST 21ST STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-613168 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	Not reported
UTM Y:	Not reported
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	608853
Affiliation Type:	Facility Owner
Company Name:	JUNJI HADA C/O ECA NY REAL ESTATE ADVISORS
Contact Type:	POWER OF ATTORNEY
Contact Name:	WILLIAM CRABLE
Address1:	611 BROADWAY, SUITE 714
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(917) 733-4573
EMail:	WILL@ECAJAPAN.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2020-07-21

Site Id:	608853
Affiliation Type:	Mail Contact
Company Name:	ECA NEW YORK REAL ESTATE ADVISORS
Contact Type:	Not reported

445 WEST 21ST STREET (Continued) **U004330255**

Contact Name:	WILLIAM CRABLE
Address1:	611 BROADWAY
Address2:	SUITE 714
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(917) 733-4573
EMail:	WILL@ECAJAPAN.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2020-07-21

Site Id:	608853
Affiliation Type:	Facility Operator
Company Name:	445 WEST 21ST STREET
Contact Type:	Not reported
Contact Name:	WILLIAM CRABLE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2020-07-21

Site Id:	608853
Affiliation Type:	Emergency Contact
Company Name:	JUNJI HADA C/O ECA NY REAL ESTATE ADVISORS
Contact Type:	Not reported
Contact Name:	WILLIAM CRABLE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 733-4573
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2020-07-21

Tank Info:

Tank Number:	01
Tank ID:	287069
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1500
Install Date:	09/15/1910
Date Tank Closed:	10/14/2020
Registered:	True

445 WEST 21ST STREET (Continued) **U004330255**

Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXLIU
Last Modified:	11/10/2020

Equipment Records:

I05 - Overfill - Vent Whistle
B05 - Tank External Protection - Jacketed
C01 - Pipe Location - Aboveground
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
J05 - Dispenser - On Site Heating System (Supply/Return)
F00 - Pipe External Protection - None

P298 **CON EDISON SERVICE BOX: 39682** **RCRA NonGen / NLR** **1016143366**
NE **189 9TH AVE** **NY MANIFEST** **NYP004261046**
< 1/8 **NEW YORK, NY 10014**
0.091 mi.
478 ft. **Site 11 of 17 in cluster P**

Relative: **Higher**

Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130321
Handler Name:	CON EDISON SERVICE BOX: 39682
Handler Address:	189 9TH AVE
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYP004261046
Contact Name:	JUAN RODRIGUEZ
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	347-865-5931
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No

CON EDISON SERVICE BOX: 39682 (Continued) **1016143366**

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON SERVICE BOX: 39682 (Continued) **1016143366**

Historic Generators:

Receive Date:		20130221
Handler Name:	CON EDISON SERVICE BOX:	39682
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20130321
Handler Name:	CON EDISON SERVICE BOX:	39682
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	189 9TH AVE
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004261046
Facility Status:	Not reported
Location Address 1:	189 9TH AVE
Code:	BP
Location Address 2:	SERV BOX 39682
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004261046

CON EDISON SERVICE BOX: 39682 (Continued) **1016143366**

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/21/2013
Trans1 Recv Date:	02/21/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/22/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004261046
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010707145JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON SERVICE BOX: 39682 (Continued) **1016143366**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

S299 **CON EDISON** **NY AST** **U003391475**
South **48 9TH AVE** **NY Spills** **N/A**
< 1/8 **NEW YORK, NY 10014** **NY MANIFEST**
0.091 mi.
482 ft. **Site 1 of 18 in cluster S**

Relative:
Higher

Actual:
16 ft.

AST:
Name: HARNYE STRATFORD REALTY CORP
Address: 48 9TH AVE
City,State,Zip: NEW YORK, NY 10014
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-398829
Program Type: PBS
UTM X: 584011.72172
UTM Y: 4510485.96279
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 18966
Affiliation Type: Facility Owner
Company Name: HARNYE STRATFORD REALTY WRP
Contact Type: Not reported
Contact Name: Not reported
Address1: 200 W 24ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10011
Country Code: 001
Phone: (212) 255-3579
EMail: Not reported
Fax Number: Not reported
Modified By: LXZIELIN
Date Last Modified: 2016-10-13

Site Id: 18966
Affiliation Type: Mail Contact
Company Name: HARNYE STRATFORD REALTY WRP
Contact Type: Not reported
Contact Name: Not reported
Address1: 200 W 24ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10011
Country Code: 001
Phone: (212) 255-3579
EMail: Not reported
Fax Number: Not reported
Modified By: LXZIELIN
Date Last Modified: 2016-10-13

CON EDISON (Continued) **U003391475**

Site Id:	18966
Affiliation Type:	Facility Operator
Company Name:	HARNYE STRATFORD REALTY CORP
Contact Type:	Not reported
Contact Name:	STUYVESANT FUEL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 255-3579
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	18966
Affiliation Type:	Emergency Contact
Company Name:	HARNYE STRATFORD REALTY WRP
Contact Type:	Not reported
Contact Name:	RAYMOND CASANOVA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 675-3905
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	21536
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	G99 - Tank Secondary Containment - Other
	A00 - Tank Internal Protection - None
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	B02 - Tank External Protection - Original Sacrificial Anode
	C00 - Pipe Location - No Piping
	D02 - Pipe Type - Galvanized Steel
	F00 - Pipe External Protection - None
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service

CON EDISON (Continued) **U003391475**

Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1080
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	LXZIELIN
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

SPILLS:

Name:	214063; 48TH ST AND 9TH AVE
Address:	48TH ST AND 9TH AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0814530 / 2008-10-15
Facility ID:	0814530
Facility Type:	ER
DER Facility ID:	386379
Site ID:	432682
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	3101
Spill Date:	2008-10-12
Investigator:	DMPOKRZY
Referred To:	Not reported
Reported to Dept:	2008-12-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	Not reported
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2010-04-16
Spill Record Last Update:	2010-04-16
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	5030 BROADWAY
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	""
Remarks:	""

All Materials:

Site ID:	432682
Operable Unit ID:	1183743
Operable Unit:	01
Material ID:	2177931
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported

CON EDISON (Continued) **U003391475**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

NY MANIFEST:

Name:	CON EDISON
Address:	48 9TH AVE
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004858132
Facility Status:	Not reported
Location Address 1:	48 9TH AVE
Code:	BP
Location Address 2:	SB 39629
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004858132
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/2015
Trans1 Recv Date:	10/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004858132
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014087615JJK
Import Indicator:	N
Export Indicator:	N

CON EDISON (Continued) **U003391475**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

S300 **CON EDISON - SERVICE BOX 39629** **RCRA-LQG** **1014395678**
South **48 9TH AVENUE** **NY MANIFEST** **NYP004171443**
< 1/8 **NEW YORK, NY 10014** **NJ MANIFEST**
0.091 mi.
482 ft. **Site 2 of 18 in cluster S**

Relative: **Higher**
Actual: **16 ft.**

RCRA-LQG:

Date Form Received by Agency:	20100323
Handler Name:	CON EDISON - SERVICE BOX 39629
Handler Address:	48 9TH AVENUE
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYP004171443
Contact Name:	FRANKLYN MURRAY
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-2808
Contact Fax:	Not reported
Contact Email:	MURRAYFR@CONED.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2009
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	4 IRVING PLACE

CON EDISON - SERVICE BOX 39629 (Continued) **1014395678**

Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

CON EDISON - SERVICE BOX 39629 (Continued) **1014395678**

Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Biennial: List of Years
Year: 2009

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20090609
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20090609
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20100323
Handler Name: CON EDISON - SERVICE BOX 39629
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090609
Handler Name: CON EDISON
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator

CON EDISON - SERVICE BOX 39629 (Continued) **1014395678**

State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	48 9TH AVE
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004171443
Facility Status:	Not reported
Location Address 1:	48 9TH AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004171443
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602807

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018

CON EDISON - SERVICE BOX 39629 (Continued) **1014395678**

Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/08/2009
Trans1 Recv Date:	06/08/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/09/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004171443
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003534446JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

NJ MANIFEST:

EPA Id:	NYP004171443
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DAVID DUKE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported

CON EDISON - SERVICE BOX 39629 (Continued) **1014395678**

Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	003534446JJK
EPA ID:	NYP004171443
Date Shipped:	06/08/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/08/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/09/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	2500 P

M301 **CON EDISON** **NY MANIFEST** **S117067399**
ESE **FO 334 W 19 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.091 mi.
482 ft. **Site 9 of 10 in cluster M**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FO 334 W 19 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004602058
Facility Status:	Not reported
Location Address 1:	FO 334 W 19 ST
Code:	BP
Location Address 2:	SB 3439
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004602058
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/21/2014
Trans1 Recv Date:	07/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004602058
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002608434GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117067399**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Q302 **85 TENTH AVENUE ASSOCIATES LLC** **RCRA-LQG** **1004762738**
West **85 10TH AVE** **FINDS** **NYR000099978**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.091 mi.
483 ft. **Site 12 of 25 in cluster Q**

Relative: **Lower**
Actual: **9 ft.**

RCRA-LQG:

Date Form Received by Agency:	20180517
Handler Name:	85 TENTH AVENUE ASSOCIATES LLC
Handler Address:	85 10TH AVE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYR000099978
Contact Name:	ED HILLA
Contact Address:	W 55TH ST
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	646-767-4598
Contact Fax:	Not reported
Contact Email:	ED.HILL@RELATED.COM
Contact Title:	SENIOR GENERAL MANAGER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	10TH AVE
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	85 TENTH AVENUE ASSOCIATES LLC
Owner Type:	Private

85 TENTH AVENUE ASSOCIATES LLC (Continued) **1004762738**

Operator Name:	85 TENTH AVENUE ASSOCIATES LLC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180518
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

85 TENTH AVENUE ASSOCIATES LLC (Continued) **1004762738**

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	LEVEL 3 COMMUNICATIONS
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	85 10TH AVE 1ST FLOOR
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	212-399-3600
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	85 TENTH AVENUE ASSOCIATES LLC
Legal Status:	Private
Date Became Current:	20070511
Date Ended Current:	Not reported
Owner/Operator Address:	85 10TH AVE 1ST FLOOR
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	646-767-4598
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	LEVEL 3 COMMUNICATIONS
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	85 10TH AVE 1ST FLOOR
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	212-399-3600
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	85 TENTH AVENUE ASSOCIATES LLC
Legal Status:	Private
Date Became Current:	20070511
Date Ended Current:	Not reported
Owner/Operator Address:	85 10TH AVE 1ST FLOOR
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	646-767-4598
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	LEVEL 3 COMMUNICATIONS
Legal Status:	Private

85 TENTH AVENUE ASSOCIATES LLC (Continued) **1004762738**

Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	85 10TH AVE 1ST FLOOR
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	212-399-3600
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name:	LEVEL 3 COMMUNICATIONS
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	LEVEL 3 COMMUNICATIONS
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010808
Handler Name:	LEVEL 3 COMMUNICATIONS
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180517
Handler Name:	85 TENTH AVENUE ASSOCIATES LLC
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

85 TENTH AVENUE ASSOCIATES LLC (Continued) **1004762738**

Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 531120
NAICS Description: LESSORS OF NONRESIDENTIAL BUILDINGS (EXCEPT MINIWAREHOUSES)

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110012235526

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004762738
Registry ID: 110012235526
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110012235526
Name: 85 TENTH AVENUE ASSOCIATES LLC
Address: 85 10TH AVE
City,State,Zip: NEW YORK, NY 10011

Q303 **85 TENTH AVENUE ASSOCIATES LLC** **NY MANIFEST** **S123160500**
West **85 10TH AVE 1ST FLOOR** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.091 mi.
483 ft. **Site 13 of 25 in cluster Q**

Relative: NY MANIFEST:
Lower
Actual: Name: 85 TENTH AVENUE ASSOCIATES LLC
9 ft. Address: 85 10TH AVE 1ST FLOOR
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYR000099978
Facility Status: Not reported
Location Address 1: 85 10TH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported

85 TENTH AVENUE ASSOCIATES LLC (Continued) **S123160500**

Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000099978
Mailing Name:	85 TENTH AVENUE ASSOCIATES LLC
Mailing Contact:	85 TENTH AVENUE ASSOCIATES LLC
Mailing Address 1:	85 10TH AVE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYR000134940
Trans2 State ID:	PAD982661381
Generator Ship Date:	06/11/2018
Trans1 Recv Date:	06/11/2018
Trans2 Recv Date:	06/14/2018
TSD Site Recv Date:	06/18/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099978
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	016297449JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H070
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	5600
Units:	P - Pounds
Number of Containers:	14

85 TENTH AVENUE ASSOCIATES LLC (Continued) **S123160500**

Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	D008
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Q304 **85-10 120TH ST/QUEENS** **NY Spills** **S102146169**
West **85-10 120TH STREET** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.091 mi.
483 ft. **Site 14 of 25 in cluster Q**

Relative: **Lower**
Actual: **9 ft.**

SPILLS:

Name:	85-10 120TH ST/QUEENS
Address:	85-10 120TH STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9011539 / 1991-02-01
Facility ID:	9011539
Facility Type:	ER
DER Facility ID:	65409
Site ID:	68709
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	4101
Spill Date:	1991-02-01
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1991-02-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	1991-02-01
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-02-11
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"OIL DELIVERY WAS MADE TO WRONG ADDRESS,TANK WAS ALREADY FULL AT 85-10 120TH ST RESULTING IN FUEL SPILL, PETRO TANK CLEANERS TO USE VAC TRUCK & SPEEDY DRY,DEC NOTIFIED NYCDEP HAZMAT."

All Materials:

Site ID:	68709

85-10 120TH ST/QUEENS (Continued) **S102146169**

Operable Unit ID:	951574
Operable Unit:	01
Material ID:	428073
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1500.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Q305 **85TH AVENUE ASSOCIATES LLC** **PA MANIFEST** **S125059578**
West **85TH 10TH AVE** **N/A**
< 1/8 **NY, NY 10011**
0.091 mi.
483 ft. **Site 15 of 25 in cluster Q**

Relative: **Lower**

Actual: **9 ft.**

Manifest Details:

Year:	2018
Manifest Number:	016297449JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000099978
Generator Date:	06/11/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	14
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	5600
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Q306 **BLENHEIM LLC** **RCRA-VSQG** **1010328577**
West **85 10TH AVE - BASEMENT** **NY MANIFEST** **NYR000143867**
< 1/8 **NEW YORK, NY 10011**
0.091 mi.
483 ft. **Site 16 of 25 in cluster Q**

Relative: **Lower**
Actual: **9 ft.**

RCRA-VSQG:

Date Form Received by Agency:		20070104
Handler Name:	BLENHEIM LLC	
Handler Address:		85 10TH AVE - BASEMENT
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYR000143867
Contact Name:		KERRIE BRESLIN
Contact Address:		10TH AVE - BASEMENT
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		212-929-8510
Contact Fax:		Not reported
Contact Email:		KBRESLIN@GVAWILLIAMS.COM
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		10TH AVE - BASEMENT
Mailing City,State,Zip:		NEW YORK, NY 10011
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

BLENHEIM LLC (Continued) **1010328577**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	GVA WILLIAMS
Legal Status:	Private
Date Became Current:	20050721
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	BLENHEIM LLC
Legal Status:	Private
Date Became Current:	20050721
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

BLENHEIM LLC (Continued) **1010328577**

Historic Generators:

Receive Date:		20070104
Handler Name:	BLENHEIM LLC	
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20070104
Handler Name:	BLENHEIM LLC	
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20070105
Handler Name:	BLENHEIM LLC	
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	51791
NAICS Description:	OTHER TELECOMMUNICATIONS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	LEVEL 3 COMMUNICATIONS
Address:	85 10TH AVE
City,State,Zip:	NEW YORK, NY 10027

BLENHEIM LLC (Continued) **1010328577**

Country: USA
EPA ID: NYP000949040
Facility Status: Not reported
Location Address 1: 85 10TH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10027
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP000949040
Mailing Name: LEVEL 3 COMMUNICATIONS
Mailing Contact: N/S
Mailing Address 1: 85 10TH AVE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10027
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 6315860002

Name: BLENHEIM LLC
Address: 85 10TH AVE - BASEMENT
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYR000143867
Facility Status: Not reported
Location Address 1: 85 10TH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000143867
Mailing Name: BLENHEIM LLC
Mailing Contact: BRIAN DUNN
Mailing Address 1: 85 10TH AVE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10011
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 6315865900

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported

BLENHEIM LLC (Continued) **1010328577**

Year:	2018
Trans1 State ID:	NYR000107326
Trans2 State ID:	NJD054126164
Generator Ship Date:	03/20/2007
Trans1 Recv Date:	03/20/2007
Trans2 Recv Date:	03/22/2007
TSD Site Recv Date:	04/02/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000143867
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported
Manifest Tracking Number:	002771041JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	430
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Q307 **MANARK ASSOCIATES DIP** **RCRA NonGen / NLR** **1000912544**
West **85 10TH AVE** **FINDS** **NY0000861534**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.091 mi.
483 ft. **Site 17 of 25 in cluster Q**

Relative: **Lower**
Actual: **9 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	MANARK ASSOCIATES DIP	
Handler Address:		85 10TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011-4725
EPA ID:		NY0000861534
Contact Name:		Not reported
Contact Address:		47TH AVE
Contact City,State,Zip:		LONG ISLAND CITY, NY 11101
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		47TH AVE
Mailing City,State,Zip:		LONG ISLAND CITY, NY 11101
Owner Name:		MANARK ASSOCIATES DIP
Owner Type:		Private
Operator Name:		MANARK ASSOCIATES DIP
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

MANARK ASSOCIATES DIP (Continued) **1000912544**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D018
Waste Description:	BENZENE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MANARK ASSOCIATES DIP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	31-00 47TH AVE
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-937-8700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	MANARK ASSOCIATES DIP
Legal Status:	Private
Date Became Current:	Not reported

MANARK ASSOCIATES DIP (Continued) **1000912544**

Date Ended Current:	Not reported
Owner/Operator Address:	31-00 47TH AVE
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-937-8700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	MANARK ASSOCIATES DIP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	31-00 47TH AVE
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-937-8700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: MANARK ASSOCIATES DIP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20060101
Handler Name: MANARK ASSOCIATES DIP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: MANARK ASSOCIATES DIP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

MANARK ASSOCIATES DIP (Continued) **1000912544**

Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	19940929
Handler Name: MANARK ASSOCIATES DIP	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004320002

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000912544
Registry ID:	110004320002
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004320002
Name:	MANARK ASSOCIATES DIP
Address:	85 10TH AVE
City,State,Zip:	NEW YORK, NY 10011

Q308 **CON EDISON TRANSFORMER SPILL** **NY Spills** **S114560425**
West **85 10TH AVE** **N/A**
< 1/8 **MANHATTAN, NY**
0.091 mi.
483 ft. **Site 18 of 25 in cluster Q**

Relative: **Lower**

Actual: **9 ft.**

SPILLS:

Name:	CON EDISON TRANSFORMER SPILL
Address:	85 10TH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	1306955 / 2014-01-28
Facility ID:	1306955
Facility Type:	ER
DER Facility ID:	442716
Site ID:	487603
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2013-10-03
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2013-10-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-10-03
Spill Record Last Update:	2014-01-28
Spiller Name:	ERT
Spiller Company:	CON EDISON
Spiller Address:	85 10TH AVE
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"1/28/14 - Austin - 6 oz of dielectric fluid discovered in the sumps of 3 walk-in transformer vaults (2 oz in each vault) - Con Ed contained and cleaned up the spill - See eDocs files for further information - Spill closed - end"
Remarks:	"6 oz (2 oz in 3 different vaults). Cleanup is pending. Vault involved are 7288, 8026, 9686."

All Materials:

Site ID:	487603
Operable Unit ID:	1237236
Operable Unit:	01
Material ID:	2236859
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.01
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Q309 **LODO REALTY** **RCRA NonGen / NLR** **1004761157**
West **85 10TH AVE - 3RD FLOOR** **FINDS** **NYR000077701**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.091 mi.
483 ft. **Site 19 of 25 in cluster Q**

Relative: **Lower**
Actual: **9 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	LODO REALTY	
Handler Address:		85 10TH AVE - 3RD FLOOR
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYR000077701
Contact Name:		JOSEPH CATALFANO
Contact Address:		INFINITE AVE
Contact City,State,Zip:		LOUISVILLE, NY 80027
Contact Telephone:		212-829-0880
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		INFINITE AVE
Mailing City,State,Zip:		LOUISVILLE, NY 80027
Owner Name:		LODO REALTY
Owner Type:		Private
Operator Name:		LODO REALTY
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

LODO REALTY (Continued) **1004761157**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	LODO REALTY
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1450 INFINITE DR
Owner/Operator City,State,Zip:	LOUISVILLE, CO 80027
Owner/Operator Telephone:	212-691-2254
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	LODO REALTY
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1450 INFINITE DR
Owner/Operator City,State,Zip:	LOUISVILLE, CO 80027

LODO REALTY (Continued) **1004761157**

Owner/Operator Telephone: 212-691-2254
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: LODO REALTY
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1450 INFINITE DR
Owner/Operator City,State,Zip: LOUISVILLE, CO 80027
Owner/Operator Telephone: 212-691-2254
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: LODO REALTY
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: LODO REALTY
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19991014
Handler Name: LODO REALTY
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

LODO REALTY (Continued) **1004761157**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004557006

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004761157
Registry ID:	110004557006
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004557006
Name:	LODO REALTY
Address:	85 10TH AVE - 3RD FLOOR
City,State,Zip:	NEW YORK, NY 10011

Q310 **COMMERCIAL BUILDING** **NY Spills** **S108294794**
West **85 10TH AVE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.091 mi.
483 ft. **Site 20 of 25 in cluster Q**

Relative: **Lower**
Actual: **9 ft.**

SPILLS:

Name:	GVA WILLIAMS
Address:	85 10TH AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	0607761 / 2007-09-21
Facility ID:	0607761
Facility Type:	ER
DER Facility ID:	211709
Site ID:	371578
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	2003-10-06
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	2006-10-07

COMMERCIAL BUILDING (Continued) **S108294794**

CID:	72
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-10-07
Spill Record Last Update:	2007-09-21
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	DAWN VOUGHT
DEC Memo:	"10/24/06: This spill case transferred from Shariff Rahman to Jon Kolleeny, since JK is already managing another spill case at this location (9908159) which is being addressed by a remedial system (dual-phase extraction) and is under a Stipulation Agreement. On Oct. 6, during installation of telecommunications equipment/cables beneath floor of on-site building, a 4' x 4' concrete vault was discovered, partly filled with soil and containing an 18 pipe with valve of unknown use. Strong odors were noted, and Fire Dept. and NYCDEP responded. LEL measured up to 30%. On Oct.7, consultant working on other spill at this site, Groundwater Environmental Services, Inc. (GES) was called to site. They had PID reading in vault of 1,100 ppm, and 8.5 ppm in the room. They called in a spill, and NYSDEC responded (S. Rahman). They dug soil from vault and cleaned vault interior. PID in vault went down to 2 ppm, but after half hour, went back up to 300 ppm. They closed and sealed vault. Heather Cloud of GES provided information and updates on the situation by email: 10/11/06, 1:19 PM email: As requested, please find attached Site Map showing location of vault and 18 pipe [see eDocs image folder]. Also, I have attached a proposed well location map depicting 5 soil borings in vicinity of vault. As soon as I get photos, I will forward them to you. We are scheduled to advance soil borings tomorrow and Friday (10/12 & 10/13). At a minimum, we will advance 5 soil borings (1 in vault and 1 in all principal directions surrounding vault) to identify source and delineate. If any of 4 borings surrounding vault come back impacted, we will step off and delineate horizontally. All soil borings will be advanced until soil is vertically delineated or until we can't go any farther with hand tools (hand auger), whichever comes first. We will screen soils from each boring in 6-inch intervals. Additionally, we will submit select samples for laboratory analysis. The analysis will be dependent on results of most recent samples submitted [i.e., waste characterization samples]. If we encounter groundwater while advancing soil borings, we will also collect groundwater samples. As an interim remedial plan, we are currently onsite installing an XP blower and duct to properly vent room. At this point, we will utilize this setup until we have identified source and defined extent of impact. As soon as we have identified source and extent of impact, we will design/install a more permanent system to address impacted area. We are also currently monitoring air space within room as well as in vault. As soon as I hear back from my crew, I will provide you with most recent PID & LEL readings.

COMMERCIAL BUILDING (Continued) **S108294794**

10/11/06, 5:21 Heather Cloud email: I wanted to give you an update on the PID/LEL readings, interim remedial plan, and plans for investigation - PID/LEL Readings: - When we arrived onsite, PID/LEL readings in breathing space were 0ppm/0% LEL - We opened vault and PID/LEL readings inside vault were 1,100 ppm/38% LEL; PID/LEL readings in breathing space after opening vault were 25 ppm/0% LEL - Currently vault is closed, and PID/LEL readings in breathing space are 18 ppm/0% LEL and PID/LEL readings next to vault at floor are 50-60 ppm/30% LEL Interim Remedial Plan: We have decided to pipe vault to one of our recovery wells (RW-1) that is tied in to system. We will then have influent air go through carbon unit and discharge through existing vapor exhaust stack. We will complete this work this week. Once we get this all piped, we will collect influent and effluent air samples and submit them for TO-15 analysis. In meantime, we are still venting room and have area secured without access. Soil boring Investigation: - We have to use a core drill to break through concrete within vault and outside of vault before we can use hand auger. Since LEL level within vault is 38% and core drill can create a spark, we will not be able to advance a soil boring within vault until LEL level is below 10%. We will continue to monitor this area and advance a soil boring as soon as LEL level is within an acceptable range. Also, we will advance soil borings as close to vault as possible. If levels outside of vault continue to be above 10%, we will have to step off until we are within an acceptable LEL range. - To answer your question regarding soil boring proposed to south of vault, that boring is actually in basement in a walkway located beneath sidewalk. Since it is not outside, we will have to advance it by hand as well. I will continue to update you as we progress. 10/20/06 Heather Cloud email: Below is an update on spill #06-07761. Soil Analytical Results: We just received soil analytical results [waste classification] from lab (see attached [in eDocs document folder]). Based upon results, it appears that impact is leaded gasoline. Lead came back hazardous. With exception of Bis(2-ethylhexyl)phthalate (a common lab contaminant), SVOCs were non-detect. Fingerprint ID came back as diesel. Since SVOCs were non-detect, we have a call in to lab to see how this was determined. Based upon recent analytical results, we anticipate submitting future samples for VOCs-STARS list and RCRA Metals. Interim Remedial Plan: Last Friday, we completed piping from vault to our existing remedial system at site (I have attached a couple of photos [in eDocs image folder]). As discussed below, we have piping tied into RW-1, which is tied into system. Influent air goes into air stripper and then to 1,000-pound vapor phase carbon unit. Following completion of piping, we started system and collected influent and effluent air samples [see PID screening of air samples in eDocs document folder]. Both samples were submitted for TO-15 analysis (standard turnaround). I anticipate receiving samples either late next week or early following week. As soon as I have results, I will forward them to you. As a follow-up, we conducted site visits on Monday and Tuesday of this week to monitor background air space in telecommunications room (vault room) as well as influent and effluent to system. On Monday, LEL readings were 0 and PID readings were <5 ppm. Background readings and O&M data from Tuesday visit are attached. Soil boring Investigation: We advanced 4 soil borings surrounding vault (as indicated on previously submitted proposed boring location map). All soil borings were advanced to refusal. Concrete and construction debris was encountered in all borings; therefore, hand borings could

COMMERCIAL BUILDING (Continued) **S108294794**

not be advanced past concrete/construction debris. Additionally, water was not encountered in any borings, so groundwater samples were not collected. - Soil boring B-1 was advanced approximately 6 inches off of pipe to south of vault. We encountered refusal (concrete/construction debris) at 6.5 feet and could not advance hand auger any farther. Impact was noted between 4.5 and 6 feet below surface. Highest PID reading was encountered at 5.5 feet (181 ppm). Based upon recent soil analytical results, we will submit sample with highest PID reading (5.5 feet) and bottom sample (6.5 feet) for VOCs-STARS list and RCRA Metals. - Soil boring B-2 was advanced approximately 6 inches off eastern edge of concrete vault. We encountered refusal (concrete/construction debris) at 4 feet and could not advance hand auger any farther. Highest PID reading (8.8 ppm) was noted at 2 feet below surface. Because all samples were <10 ppm PID, we are planning on submitting sample collected at bottom of boring for laboratory analysis. - Soil boring B-3 was advanced 1 foot off northern edge of concrete vault. We encountered refusal (concrete/construction debris) at 1.5 feet and could not advance hand auger any farther. Highest PID reading (9.6 ppm) was noted at 1 foot below surface. Because all samples were <10 ppm PID, we are planning on submitting sample collected at bottom of boring for laboratory analysis. - Soil boring B-4 was advanced 6 inches off western edge of concrete vault. We encountered refusal (concrete/construction debris) at 2.5 feet and could not advance hand auger any farther. Highest PID reading (0.6 ppm) was noted at 2.5 feet below surface. We are planning on submitting sample collected at bottom of boring for laboratory analysis. We should receive analytical results back within 10 days. Based upon initial results, we will evaluate plan of action for further investigation and remediation. JK 11/12/06: Received email from Heather Cloud of GES on 11/20/06 with results of soil borings around vault, weekly PID monitoring of recovered vapors, and lab analyses of influent/effluent vapor samples for October 2006. Soil results showed all VOCs either non-detect or below TAGM 4046. PID monitoring shows decreasing VOC levels at vault. Lab analyses of influent/effluent show some hydrocarbons detected, but benzene in discharge is in compliance (non-detect). I sent email back on 11/20/06 asking if these data, and summaries of associated activities, can be incorporated into quarterly monitoring reports for spill 9908159 at this site, which is under stipulation agreement. I also asked if vapors were being extracted only from vault area, or from recovery wells for groundwater extraction system at site in addition to vault area, pointing out that recent drop in water table afforded opportunity to treat contaminated soil that was formerly under water. Heather sent reply on 11/21/06 saying data and discussion for vault area will be incorporated into quarterly reports for site, which will reference both spill numbers, and that vapors are currently only being extracted from vault area. She stated: In order to extract vapors from existing recovery wells, we would have to make modifications to existing GW extraction piping configuration. With existing setup, we just have flexible hosing that extracts groundwater. Considering that GW concentrations in recovery wells are close to NYSDEC Groundwater Standards, we would not anticipate there being a lot of vapors to extract. For further discussion of this issue, see remarks for spill no. 9908157. - J. Kolleeny 12/08/06: Received email from Heather Cloud of GES reporting that vapors have been detected in building basement. GES sent a field tech, who got PID readings of 70 ppm in vault room, and 120 ppm adjacent to vault.

COMMERCIAL BUILDING (Continued) **S108294794**

They believe a portion of vault may not be properly sealed; they are making sure vault is completely sealed, monitoring for vapors in breathing space of vault room, and keeping people out of room. I sent email reply expressing surprise that after weeks of SVE on vault, and presumably negative pressure exerted on vault, vapors would escape from an improperly sealed portion of vault. I suggested that a more aggressive approach be taken, asked if vault and pipe within are active, have any current use, and if not, suggested that entire vault be removed to access contaminated source material below/around vault. Asked that Heather get back to me with her opinion on this. - J. Kolleeny 02/01/07: Received email update on 1/24/07 from Heather Cloud of GES: Vault is still tied into system and we are conducting weekly visits to monitor vapors. During last 2 O&M visits, PID readings at vault sample port were 10.2 ppm and 5.1 ppm. All activities conducted for Spill #06-07761 between October and December 2006 will be included in Site Status Update Report we are currently preparing. [Report will be archived in eDocs folder for spill 9908159.] - J. Kolleeny 03/16/07: Reviewed hard copy of GES 4th Quarter '06 site status report (in eDocs for spill no. 9908159). Report provides details of vapor problems in Level 3 telecommunications room associated with spill 0607761, when vault with contaminated soil was found. Also notes that no groundwater was present in monitoring wells and that DEC therefore approved a waiver of requirement to start up and operate groundwater recovery & treatment system. Information regarding return of groundwater to wells and collection/analysis of GW samples will appear in 1st Quarter '07 report. - J. Kolleeny 06/22/07: Reviewed 1st & 2nd Quarter 2007 Site Status Update Report / Spill Closure Request dated 6/7/07, by Groundwater & Environmental Services, Inc. (GES). Report (in eDocs) presents groundwater data for Jan. and Apr. '07 events, as well as historical data, showing no significant residual groundwater contamination, and SVE system monitoring data (related to spill no. 0607761, reported when vault beneath floor of on-site bldg's telecom room was found and emitting petroleum odors) showing vapors from vault appear to have abated and system is no longer recovering significant hydrocarbons. Based on data, GES requests closure of spills 9908159 and 0607761. I sent letter (in eDocs) to Ms. Jessica Chiamulera of 85 Tenth Avenue Associates, LLC (new property owner, replacing Kerrie Breslin of GVA Williams), copies to Heather Cloud and Matthew Schiefferstein of GES, approving closure of spill 9908159, related to groundwater contamination, saying NFA letter will be sent separately, but asking that for spill 0607761, SVE system be pulsed by shutting down for 2 weeks and re-starting, to see if vapors are detected in telecom room while system is off and if there is a spike in vapor recovery when system is re-started. - J. Kolleeny 09/21/07: Reviewed GES report, Spill Closure Request dated Sept. 7, 2007 (in eDocs). Report presents PID and lab data for vapor influent and effluent of SVE system operating to address vapor problem emanating from vault discovered beneath floor of telecommunications room in on-site building. PID results show no positive readings since June 2007 (last screening 8/14/07), lab results show very low levels of a few VOC compounds in SVE influent. Based on data, GES requested closure of spill case. I contacted Heather Cloud of GES on 9/20/07 and asked about ultimate disposition of vault. She sent email reply stating: As discussed on phone, vault in Level 3 Communications room will be properly abandoned upon receipt of spill closure. Specifically, vault lid will be removed, vault will be filled with

COMMERCIAL BUILDING (Continued) **S108294794**

bentonite, and vault will be capped with concrete. Based on data in report and Ms. Cloud's statement regarding vault, I closed spill and issued NFA letter (in eDocs). - J. Kolleeny "

Remarks: "Odor eminating from concrete vault in basement. PID readings went down, now starting to come back up. ~300. Soil has been cleaned out that was in vault. Will caulk/seal cover. Reg. #2 is already addressing spill @ this location."

All Materials:

Site ID:	371578
Operable Unit ID:	1129335
Operable Unit:	01
Material ID:	2118990
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	COMMERCIAL BUILDING
Address:	85 10TH AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9908159 / 2007-06-22
Facility ID:	9908159
Facility Type:	ER
DER Facility ID:	211709
Site ID:	258732
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	1999-10-05
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	1999-10-05
CID:	252
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-05
Spill Record Last Update:	2007-06-25
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	ROBERT MARLOW
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER OLD BUILDING. #6 FUEL OIL SPILL. sCALE PIT FULL OF OIL.

COMMERCIAL BUILDING (Continued) **S108294794**

sIDEWALK ELEVATOR W/ OIL. gEOTECHNICAL BEING DONE IN BASEMENT. #6 OIL UNDER SLAB. gROUNDWATER PROBLEM UNder building. Could have been over filling. confirming contamination is comming from site with wells. Will then put in a drainage system and oil water system. I said make corings into wells. Deliniate extent of plume and put in a system. Jim Allen Nac Env 212-829-0880. 11/30/99. Preliminary GW sampling shows MTBE. 1/10/2000 jIM ALLEN, nAC eNV. 212-829-0880 REMOVED AN ABOVE GROUND TANK, NOT SOURCE. REDOOING ENTIRE BUILDING, TRENCH SYSTEM IN BUILDING FULL OF OIL, LEAD TO SUMP PUMP. cLEANED WITH GUZZLERS.bRIAN cOSTELLO,PROJECT MANAGER. REMOVED 60,000 GALLONS OF OIL/WATER. oIL CAME FROM 16000 GALLON ast. uNDER THAT AND ELEVATOR PIT AND ALL OVER THE ROOM . oVER FILLING AND TURNING OFF THE BOILER. COULD HAVE BEEN DUMPING. TANK CLEANED, NOT CLOSED (TANK #6, NOW #2) CLEANED OUT. WANT TO PUT IN o/W SEPPERATOR. oIL UNDER BASEMENT SLAB. nEED TO PUT IN A SYSTEM. oil definitely from the site. central drainage pit still loaded with oil. 3/11/03 - SAMUEL- File available in active unassigned spill files. 1/21/2004 Case reassigned from Tomasello to Sawyer. 11.30.05 Sharif// I rec'd a call yesterday from Ms. Dawn Ruffini(Ground Water & Environmental Services),631-582-4187 ext.23 regarding the current status of that spill case.As per our telephone conversation, GES, on behalf of their client, is requesting that RW-5 be allowed to be covered with floor tile. Due to the recent renovations to this building, RW-5 is located directly within the catering hall that has been constructed in the basement of the building, and would prove to be detrimental to the tenants in the course of their business.From a technical standpoint, RW-5 does not seem to be a critical monitoring/sampling point. It has not shown any floating product since GES began monitoring the site in 2003,but the current level of contaminants require remedial works to be continued.Recovery piping has already been installed in RW-5 (and runs within the floor and walls), so this well would still be utilized for remedial purposes. A Total Phase/Vacuum Enhanced Groundwater Extraction system is currently installed at the site, and RW-5 is connected into the system. When this spill is considered to be inactivated, RW-5 would be accessed and properly abandoned at that time.I received reports/maps/most recent data for this site. GES is currently in the process of completing the 2nd and 3rd Quarter Status reports for this site, which will be sent to DEC shortly. However, they request a determination on the acceptability of covering RW-5 with floor tile in the mean time, as construction in this area should be completed within the next few days/week. Project Manager's decision on this matter is requested as soon as possible. This case has been transferred from Sharif Rahman to Koon Tang for reassignment to his staff. 12/07/05: This spill case transferred from S. Rahman to J. Kolleeny. 12/07/05: Spoke with Dawn Ruffini of GES about the site, which has a high-vac. extraction system installed but not yet started up, and also reviewed Dawn's email to Sharif about covering over recovery well RW-5 with floor tile. Sent email to Dawn requesting additional information (most recent gw data for other wells) and asking about feasibility of installing a monitoring well somewhere to the east of RW-5. Also, Dawn said that GES is behind in their quarterly report submissions, but they will submit combined 2nd & 3rd Quarter 2005 report within two weeks. I pointed out that they must complete SVE data sheets and have a monitoring & maintenance plan before system can be activated. - J. Kolleeny 01/04/06: Received Site Status Update Report for 2nd & 3rd Quarters 2005; will review. - J. Kolleeny 03/28/06: Spoke with Matt Schieferststein of GES on phone,

COMMERCIAL BUILDING (Continued) **S108294794**

he said they plan to start-up remedial system soon but asked about air permitting requirement. I told him that the RP must sign a stipulation agreement and SVE/air stripper data sheets must be completed for system's vapor discharge before start-up. I emailed him a link to DEC's Guidance for Petroleum Spill Stipulation Agreements, and told him I would prepare a stip for his client, GVA Williams (it was formerly ATC Management). - J. Kolleeny 04/14/06: Reviewed Site Status Update Reports for 2nd & 3rd Quarters 2005, 4th Quarter 2005, and 1st Quarter 2006. Groundwater monitoring results show decreasing trend in dissolved contaminant levels. GES emailed pdf copies of a Corrective Action Plan prepared by Impact Environmental in October 2001, and a DEC approval letter of CAP signed by Kevin Hale. I prepared a Stipulation Agreement with cover letter and CAP (implementation schedule), requesting remedial design plans and completed air stripper data sheets within 30 days of effective date of STIP, and mailed it to Kerri Breslin of GVA Williams on 4/14/06. Requested signed Stip back by May 5, 2006. - J. Kolleeny 5/17/06: Received signed stip from RP (Kerri Breslin) in early May, had it counter-signed by Acting Regional Director Lou Oliva on 5/15/06. Sent copies of fully executed Stip to RP and GES. - J. Kolleeny 6/23/06: Received Remedial Design Plan on 6/20/06, requested by STIP Corrective Action Plan. On 6/23/06, sent email requesting modifications: 1. In discussion of Monitoring & Maintenance Plan, paragraph describing monthly collection of air samples from air stripper should explicitly state that both influent (untreated) and effluent (treated) air samples will be collected for analysis. Also, laboratory analysis should include a number for Total VOCs or TPH or an equivalent, to better evaluate nature of contaminants being stripped from recovered groundwater. 2. Monitoring & Maintenance Plan states that five accessible groundwater recovery wells will be gauged, purged and sampled on a quarterly basis and analyzed for BTEX and MTBE. However, to better evaluate impacts to groundwater and progress of remediation, I request that samples be analyzed for full range of petroleum-related VOCs and SVOCs, at least for a baseline sampling event which should be conducted prior to system activation (unless a quarterly sampling event has been performed since January '06 First Quarter sampling event), and for first round of quarterly sampling after system start-up. If these requested changes are acceptable to you and your client, please revise Remedial Design Plan accordingly and submit revised page(s) to my attention. - J. Kolleeny 07/25/06: Having received no response to my 6/23/06 email, sent another email to Heather Cloud of GES, asking her to respond to my request for modifications to the Remedial Design Plan, and for revised hard and electronic copies of the report. - J. Kolleeny 07/26/06: Received revised version of Remedial Design Plan via email from Heather Cloud of GES. Will review. - J. Kolleeny 8/17/06: Reviewed revised Remedial Design Plan, called Heather Cloud and pointed out possible error in air stripper data sheet calculations, asked for corrected data sheets with supporting calculations, and also asked for monitoring and maintenance requirements to be summarized in an O&M table. She said no problem, will get these items to me soon. - J. Kolleeny 8/21/06: Reviewed 2nd Quarter 2006 Site Status Update Report by GES, dated 8/14/06. Groundwater sampling in May '06 indicated huge, anomalous increase in toluene in recovery well RW-1 (from 1.5 ppb in January '06 to 4,720 ppb in May '06). Other recovery wells sampled showed relatively low levels of BTEX & MTBE. Upcoming sampling rounds will be analyzed for full list of VOCs

COMMERCIAL BUILDING (Continued) **S108294794**

and SVOCs. GES plans to connect RW-1 to the installed pump & treat system, and will start up system upon receipt of NYCDEP sewer discharge permit, hopefully before end of August '06. No response needed. - J. Kolleeny 08/28/06: Received 2nd revised remedial design plan from GES, with corrected air stripper data sheets and relevant text, plus table with monitoring and maintenance requirements (in eDocs). Mailed approval letter (also in eDocs) to Kerri Breslin of GVA Williams; emailed pdf of letter to Heather Cloud and Matthew Schieferstein of GES. - J. Kolleeny 10/31/06: Received email on 10/13/06 from Heather Cloud of GES with electronic copy of letter report Project Status Update (in eDocs) summarizing baseline groundwater sampling event on Aug. 18, 2006, noting that only benzene exceeds limit in two wells, at 5.7 ppb in RW-2 and 4.0 ppb in RW-3. In light of this, GES requested waiver of requirement to activate and operate groundwater extraction portion of on-site remedial system. They also requested reducing groundwater analytical parameters from full list of VOCs to BTEX plus MTBE. Subsequently spoke with Heather who said recent well gauging at site found there has been a drop in water table so there is currently no water in any recovery wells. On Oct. 23, I emailed Heather asking for documentation of water table drop. On Oct. 24th, she sent email with groundwater gauging and sampling data table showing all wells were dry on 9/22/06, and stating: On August 18, 2006, GES conducted 3rd quarter groundwater sampling event. During event, all recovery wells had approximately 8-9 feet of water column except RW-1 which was dry. Since RW-1 was dry during August event, GES visited site again on September 22 to sample RW-1. During this visit, it was noted that RW-1 as well as other on-site recovery wells (RW-2 through RW-4 and RW-6) were dry. Total depth of recovery wells ranges from 9-10 feet below grade. Historically, depth to water on-site has ranged from 0.21 to 3.85 feet below top of casing. During additional site visits on September 29, October 7, October 12-13, and October 16, all on-site recovery wells were dry. During September 22 visit, it was noted that 2 dewatering projects are currently taking place northwest of site approximately 3 blocks away and northeast of site approximately 2 blocks away. Specifics regarding dewatering projects is unknown; however, these activities could explain sudden drop in water table. Received hard copy of Project Status Update report on Oct. 30th. On Oct. 31, 2006, I issued a letter (in eDocs) to Kerrie Breslin of GVA Williams (copied Heather Cloud and Matt Schieferstein of GES) approving request to waive system startup requirement, on condition that vapor extraction portion of system continue to operate to address soil contamination recently discovered in and around small vault under floor (see spill no. 0607761), and noting that DEC may require activation of system if groundwater monitoring shows increase in contaminant levels, so system should be maintained in state of readiness. My letter requested one more round of groundwater sampling with samples analyzed for full range of VOCs, then reconsidering request to reduce parameters to BTEX + MTBE. - JK 11/24/06: Received electronic copy of 3rd Quarter '06 monitoring report by email from Heather Cloud of GES on 11/21/06 (in eDocs). Sent email to Heather saying: I have two comments: First, report states that a waiver will be requested. Actually, waiver was requested and request was approved in a letter I sent on October 31, 2006. Since this report is dated Nov. 21st, this should be reflected in it. Second, in your recent email responding to my suggestion that drop in water table afforded an oppportunity to treat soil contamination that was formerly in

COMMERCIAL BUILDING (Continued) **S108294794**

saturated zone, you said that system at site was designed to recover groundwater not vapors, and that since latest groundwater results were so low, little or nothing would be gained by modifying system to recover soil vapors. [See remarks for spill 0607761, for contaminated vault area which is being treated by vapor extraction.] I'm not sure I agree. Last time well RW-1 was sampled (May '06), groundwater had 4,720 ppb toluene, and only BTEX + MtBE were analyzed for. Last time RW-5 was sampled (October '05), it had 23.6 ppb benzene and 228 ppb MTBE. I think it's likely, or at least possible, that there was a smear zone of soil contamination that's been left high and dry (and thus accessible to vapor extraction). If and when water table rises again, this smear zone may contribute to groundwater contamination and necessitate operation of groundwater recovery system. What difficulties would be involved in modifying system to recover soil vapors? If recovery wells had tubing in them, those tubes must now terminate in vadose zone rather than saturated zone; can tubes be hooked up to a vacuum blower? At least, could a pilot test be done with one recovery well and a sample of recovered vapor be screened with a PID and analyzed at a lab for petroleum hydrocarbons? Please let me know what you think. Have not yet received response. - J. Kolleeny 11/27/06: Received email response from Heather Cloud of GES: In response to your questions: 1) 3rd QTR Report covers activities from July 1 to September 30, 2006; therefore, we did not incorporate any activities or requests conducted/made in October. These will be incorporated in 4th QTR Report. 2) In terms of RW-1, we had a sudden increase in toluene between 1st QTR (1.5 ppb toluene) and 2nd QTR (4,720 ppb toluene) sampling events. Historically, toluene concentrations in this well have been relatively low and depth to groundwater did not fluctuate. As we previously discussed, we believe that this was possibly an anomalous reading; however, since water table dropped significantly we could not verify with another round of sampling. To modify system, we will have to hard pipe wells to pull vapors from smear zone. We will not be able to just hook up vacuum blower to existing tubing. It's not that difficult of a task, so we can make modifications if this is something you would like us to proceed with. If so, can you please give me something in writing saying so? I spoke with Heather on 11/28/06 and asked if it would be possible to modify one recovery well to extract vapors, and perform a pilot test? She said she thought it could be done with a portable blower. I agreed to send corresponce to RP Kerry Breslin requesting that this be done. - J. Kolleeny 11/29/06: Received hard copy of 3rd Quarter Site Status Report by GES dated 11/21/06; as noted above, report was already reviewed as electronic document. Put report in file cabinet. - JK 12/04/06: Sent letter (in eDocs) to Kerrie Breslin of GVA Williams by email (with cc to Heather Cloud and Matthew Schieferstein of GES) and by regular mail requesting that one of on-site groundwater recovery wells be modified to perform a SVE pilot test, to see if residual soil contamination left in unsaturated zone because of recent drop in water table can be addressed by SVE. - J. Kolleeny 12/18/06: Received email from Heather Cloud of GES saying that on Dec. 14th they tied in well RW-1 to SVE system for pilot test I requested. They ran system for 2 hours and got PID reading at wellhead of 4.2 ppm; since PID was low, they didn't take sample for lab analysis. They left RW-1 tied in to system and will return on Dec. 21st to monitor vapors. I asked them to take a sample for lab even if PID readings are low, since PID doesn't always correlate well with lab results. Heather agreed to analyze a sample for BTEX + MTBE

COMMERCIAL BUILDING (Continued) **S108294794**

and TPH. - J. Kolleeny 02/01/07: Sent email to Heather Cloud of GES on 1/2/07 asking if they took a lab sample of recovered vapors from RW-1 on 12/21/06, as I had requested. Received email reply from Heather on 1/4/07 saying sample was taken on 21st but data not back yet; will forward as soon as she gets it. On 1/9/07 received email from Heather with lab results; air sample was analyzed for BTEX, MTBE and TPH, all were non-detect. Based on this, she proposed discontinuing vapor extraction from RW-1 and not tying in extraction wells to SVE system. I reviewed data and noted that detection limits seemed high; sent following email to Heather on 1/10/07: I looked at air results, and I noticed that method reporting limits seem unusually high: 0.5 milligrams per cubic meter (mg/m3) for MTBE & BET, 1.5 mg/m3 for X, and 50 mg/m3 for TPH (which I'm guessing is C1-C4 Hydrocarbons and C4-C10 Hydrocarbons). For comparison, I looked at Oct. '06 lab results for influent/effluent samples from vault area (spill 0607761), and detection limits were mostly below 100 micrograms/cubic meter (ug/m3), an order of magnitude lower, at least. I also noticed that Oct. '06 analyses were done by Air Toxics Ltd., whereas recent SVE pilot test analyses were done by TestAmerica. Can you please look into this and let me know why detection/reporting limits were so high? Also, was PID reading taken on sample collected for lab, and was it non-detect as before? I may be beating a dead horse, but I wouldn't want to miss some BTEX recovery in sample because of elevated lab detection limit. On 1/24/07, received email reply from Heather: 1. Laboratory Reporting Method: I touched base with Test America, they informed me that method reporting/detection limits for air analytical results (BTEX, MTBE, & TPH via EPA Method 18) are their standard values. These are limits they calibrate their equipment to; therefore, they cannot lower detection limits. In terms of October samples, we submitted those samples to Test America for VOCs via Method TO-15. Test America could not run this analysis, so they subbed it out to Air Toxics. For Method TO-15, Air Toxics has a lower detection limit. In terms of PID readings, we recorded 14.2 ppm when we collected air sample from RW-1. 2. Groundwater: While at site last week to conduct weekly O&M for Spill #06-07761, we checked all wells for groundwater. Groundwater has returned in ALL wells. Average depth to water is approximately 0.5-1 ft below surface. In light of this, we can no longer extract vapors from RW-1, so we disconnected RW-1 from system. Also, since water is back, we collected a full round of samples from ALL wells, and submitted water samples for VOCs STARS list. We collected samples yesterday, so we should have analytical results back in a couple of weeks. If you'd like, I can forward you results once we get them. Additionally, these results will be submitted in 1st Qtr. '07 Site Status Update Report that will be submitted in April. I replied to Heather on 1/29/07 that GW results need not be submitted prior to 1st Quarter '07 Site Status Update Report. - J. Kolleeny 03/05/07: Received electronic copy of 4th Quarter '06 Site Status Report (in eDocs) by email on 3/2/07 from Heather Cloud of GES; will review when hard copy is received. - J. Kolleeny 03/16/07: Received hard copy of 4th Quarter '06 site status report, provides details of vapor problems in Level 3 telecommunications room associated with spill 0607761, when vault with contaminated soil was found. Also notes that no groundwater was present in monitoring wells and that DEC therefore approved a waiver of requirement to start up and operate groundwater recovery & treatment system. Information regarding return of groundwater to wells and collection/analysis of

COMMERCIAL BUILDING (Continued) **S108294794**

GW samples will appear in 1st Quarter '07 report. - J. Kolleeny
06/22/07: Reviewed 1st & 2nd Quarter 2007 Site Status Update Report / Spill Closure Request dated 6/7/07, by Groundwater & Environmental Services, Inc. (GES). Report (in eDocs) presents groundwater data for Jan. and Apr. '07 events, as well as historical data, showing no significant residual groundwater contamination, and SVE system monitoring data (related to spill no. 0607761, reported when vault beneath floor of on-site bldg's telecom room was found and emitting petroleum odors) showing vapors from vault appear to have abated and system is no longer recovering significant hydrocarbons. Based on data, GES requests closure of spills 9908159 and 0607761. I sent letter (in eDocs) to Ms. Jessica Chiamulera of 85 Tenth Avenue Associates, LLC (new property owner, replacing Kerrie Breslin of GVA Williams), copies to Heather Cloud and Matthew Schiefferstein of GES, approving closure of spill 9908159, related to groundwater contamination, saying NFA letter will be sent separately, but asking that for spill 0607761, SVE system be pulsed by shutting down for 2 weeks and re-starting, to see if vapors are detected in telecom room while system is off and if there is a spike in vapor recovery when system is re-started. I then sent NFA letter (in eDocs) to Ms. Chiamulera, with copies to Heather Cloud and Matt Schiefferstein of GES. - J. Kolleeny "

Remarks: "SPILL IN SIDEWALK VAULT WEIGH SCALE PIT AND SIDEWALK ELEVATOR PIT. ARRANGEMENTS ARE BEING MADE FOR CLEANUP. BETWEEN 15TH AND 16TH sTREETS"

All Materials:

Site ID:	258732
Operable Unit ID:	1082453
Operable Unit:	01
Material ID:	300839
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	BUILDING
Address:	85 10TH AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	0607745 / 2006-10-10
Facility ID:	0607745
Facility Type:	ER
DER Facility ID:	211709
Site ID:	371562
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	2006-10-06
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2006-10-06
CID:	410

COMMERCIAL BUILDING (Continued) **S108294794**

Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-10-06
Spill Record Last Update:	2006-10-18
Spiller Name:	SHAWN DONOHUE
Spiller Company:	BUILDING
Spiller Address:	85 10TH AVE
Spiller Company:	001
Contact Name:	SHAWN DONOHUE
DEC Memo:	"10/10/06 Rahman- Cross reference to Spill# 0607761."
Remarks:	"CALLER REPORSTS UNKNONW HAZORDOUS MATERIAL / FUMES AT THIS LOCATION, POSSIBLY FLAMABLE: FIRE DEPT ON SCENE: REQUESTS DEC CALL BACK'"

All Materials:

Site ID:	371562
Operable Unit ID:	1129319
Operable Unit:	01
Material ID:	2118976
Material Code:	0063A
Material Name:	unknown hazardous material
Case No.:	Not reported
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Q311 **RELATED MANAGEMENT** **NY AST** **U001837689**
West **85 TENTH AVENUE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.091 mi.
483 ft. **Site 21 of 25 in cluster Q**

Relative: **Lower**
Actual: **9 ft.**

AST:

Name:	RELATED MANAGEMENT
Address:	85 TENTH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-216682
Program Type:	PBS
UTM X:	583770.41338
UTM Y:	4510705.43909
Expiration Date:	05/11/2017
Site Type:	Other

Affiliation Records:

Site Id:	8161
Affiliation Type:	Facility Owner
Company Name:	85 TENTH AVENUE ASSOC. C/O THE RELATED CO.

RELATED MANAGEMENT (Continued) **U001837689**

Contact Type:	PROPERTY MANAGER
Contact Name:	LORI LIBBY
Address1:	60 COLUMBUS CIRCLE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10023
Country Code:	001
Phone:	(212) 421-5333
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-04-02

Site Id:	8161
Affiliation Type:	Mail Contact
Company Name:	RELATED MANAGEMENT
Contact Type:	Not reported
Contact Name:	CRISTIN BRADY
Address1:	423 WEST 55TH ST
Address2:	9TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10019
Country Code:	001
Phone:	(212) 929-8510
EMail:	LORI.LIBBY@RELATED.COM
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-04-02

Site Id:	8161
Affiliation Type:	Facility Operator
Company Name:	RELATED MANAGEMENT
Contact Type:	Not reported
Contact Name:	PROPERTY MANAGER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 929-8510
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-08-06

Site Id:	8161
Affiliation Type:	Emergency Contact
Company Name:	85 TENTH AVENUE ASSOC. C/O THE RELATED CO.
Contact Type:	Not reported
Contact Name:	LORI LIBBY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

RELATED MANAGEMENT (Continued) **U001837689**

Zip Code:	Not reported
Country Code:	999
Phone:	(212) 929-8510
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-04-02

Tank Info:

Tank Number:	01
Tank Id:	22405
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1959
Capacity Gallons:	15000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/31/2004
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	diesel

Tank Number:	02
Tank Id:	66565
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
C01 - Pipe Location - Aboveground
F05 - Pipe External Protection - Jacketed
A01 - Tank Internal Protection - Epoxy Liner
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

RELATED MANAGEMENT (Continued) **U001837689**

E12 - Piping Secondary Containment - Double-Walled (AG only)
F06 - Pipe External Protection - Wrapped
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/15/2002
Capacity Gallons:	13500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	KXTANG
Last Modified:	04/14/2017
Material Name:	diesel

Tank Number:	03
Tank Id:	66566
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
C01 - Pipe Location - Aboveground
F05 - Pipe External Protection - Jacketed
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A01 - Tank Internal Protection - Epoxy Liner
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
D01 - Pipe Type - Steel/Carbon Steel/Iron
B01 - Tank External Protection - Painted/Asphalt Coating
J02 - Dispenser - Suction Dispenser
E12 - Piping Secondary Containment - Double-Walled (AG only)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F06 - Pipe External Protection - Wrapped

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/15/2002
Capacity Gallons:	13500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	KXTANG
Last Modified:	04/14/2017
Material Name:	diesel

RELATED MANAGEMENT (Continued) **U001837689**

Tank Number: 04
Tank Id: 57309
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
J00 - Dispenser - None
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 4000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 11/01/1999
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Q312 **HAMMEL** **NY LTANKS** **S102671453**
West **85-10 ROCKAWAY BCH BLVD** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.091 mi.
483 ft. **Site 22 of 25 in cluster Q**

Relative: **Lower**
Actual: **9 ft.**

LTANKS:
Name: HAMMEL
Address: 85-10 ROCKAWAY BCH BLVD
City,State,Zip: NEW YORK CITY, NY
Spill Number/Closed Date: 8908028 / 1992-12-08
Facility ID: 8908028
Site ID: 313781
Spill Date: 1989-06-01
Spill Cause: Tank Overfill
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: 1992-12-08
SWIS: 4101
Investigator: HEALY
Referred To: Not reported
Reported to Dept: 1989-11-13
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported

HAMMEL (Continued) **S102671453**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-11-15
Spill Record Last Update:	1993-12-27
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	250 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	253010
DEC Memo:	""
Remarks:	"TANK OVERFLOW FROM VENT ONTO LAWN, EXCAVATED (15) 55 GALLON DRUMS OF CONTAMINATED SOIL, WILL DISPOSE, BELCHER FUEL OIL (SUPPLIER)."

All TTF:

Facility ID:	8908028
Spill Number:	8908028
Spill Tank Test:	1536394
Site ID:	313781
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	02
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	313781
Operable Unit ID:	935536
Operable Unit:	01
Material ID:	444793
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

L313 **CARRIER CORP** **RCRA NonGen / NLR** **1000361642**
SSE **332 W 16TH ST** **FINDS** **NYD982536849**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.092 mi. **NY MANIFEST**
485 ft. **Site 15 of 18 in cluster L**

Relative: **Higher**
Actual: **18 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	CARRIER CORP	
Handler Address:		332 W 16TH ST
Handler City,State,Zip:		NEW YORK, NY 10011-5904
EPA ID:		NYD982536849
Contact Name:		Not reported
Contact Address:		W 16TH ST
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		W 16TH ST
Mailing City,State,Zip:		NEW YORK, NY 10011
Owner Name:		SYLVAN LAWRENCE CO
Owner Type:		Private
Operator Name:		SYLVAN LAWRENCE CO
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CARRIER CORP (Continued) **1000361642**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	U075
Waste Description:	DICHLORODIFLUOROMETHANE (OR) METHANE, DICHLORODIFLUORO-
Waste Code:	U121
Waste Description:	METHANE, TRICHLOROFLUORO- (OR) TRICHLOROMONOFLUOROMETHANE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SYLVAN LAWRENCE CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

CARRIER CORP (Continued) **1000361642**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SYLVAN LAWRENCE CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SYLVAN LAWRENCE CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: CARRIER CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: CARRIER CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: CARRIER CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY

CARRIER CORP (Continued) **1000361642**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19880411
Handler Name: CARRIER CORP	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004423222

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000361642
Registry ID:	110004423222
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004423222
Name:	CARRIER CORP
Address:	332 W 16TH ST
City,State,Zip:	NEW YORK, NY 10011

CARRIER CORP (Continued) **1000361642**

NY MANIFEST:

Name:	CARRIER CORPORATION
Address:	332 W 16TH ST
City,State,Zip:	NEW YORK, NY 10011-5904
Country:	USA
EPA ID:	NYD982536849
Facility Status:	Not reported
Location Address 1:	332 WEST 16TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD982536849
Mailing Name:	CARRIER CORPORATION
Mailing Contact:	CARRIER CORPORATION
Mailing Address 1:	1133 SIXTH AVE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10036
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2123028960

P314 **BROWNSTONE** **NY Spills** **S109061907**
NE **351 WEST 21ST STREET** **N/A**
< 1/8 **MANHATTEN, NY**
0.092 mi.
487 ft. **Site 12 of 17 in cluster P**

Relative:
Higher

Actual:
17 ft.

SPILLS:

Name:	BROWNSTONE
Address:	351 WEST 21ST STREET
City,State,Zip:	MANHATTEN, NY
Spill Number/Closed Date:	0800648 / 2009-12-23
Facility ID:	0800648
Facility Type:	ER
DER Facility ID:	345920
Site ID:	396431
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	2008-04-16
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2008-04-16
CID:	444
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported

BROWNSTONE (Continued) **S109061907**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-04-16
Spill Record Last Update:	2009-12-23
Spiller Name:	RYAN SHAWNHUES
Spiller Company:	Not reported
Spiller Address:	351 WEST 21ST STREET
Spiller Company:	001
Contact Name:	RYAN SHAWNHUES
DEC Memo:	"Piper - I visited the building and met with the impacted neighbor at 353 W 21st. Upon arrival I noticed an iverfill at 351. The spill entered a drain and the entrance to the basement. No one answered the door at 351. I went into inpacted house and immediately smelled cooking. I had smelled a slight odor though as I went downstairs I smelled a paint like substance. I let the homowner know that just because I don;t smell it, it doesn;t mean that you don't. I was just around #2 oil outside and could be desensitized to it. I use a pid meter and highest reading was 8.5 ppm. I left info with affected party to contact me with neighbors # t ohave them perform cleanup as htis would be the fastest way of addressing the issue. 4/25/08- csl sent to: West 21 Street Realty 351 West 21st St. NY, NY 10011 Based on spill info and age of spill, this spill is closed."
Remarks:	"in basement and no further"

All Materials:

Site ID:	396431
Operable Unit ID:	1153398
Operable Unit:	01
Material ID:	2144158
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

M315 **ROTA HOLDING CORP** **NY AST** **U004048178**
East **335 W 19 STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.093 mi.
492 ft. **Site 10 of 10 in cluster M**

Relative:
Higher

Actual:
18 ft.

AST:

Name:	ROTA HOLDING CORP
Address:	335 W 19 STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-398810
Program Type:	PBS
UTM X:	584288.80291

ROTA HOLDING CORP (Continued) **U004048178**

UTM Y: 4510766.26134
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 18965
Affiliation Type: Facility Operator
Company Name: ROTA HOLDING CORP
Contact Type: Not reported
Contact Name: DAVID BARON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 706-7755
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2006-01-10

Site Id: 18965
Affiliation Type: Emergency Contact
Company Name: ROTA HOLDING CORP
Contact Type: Not reported
Contact Name: DAVID BARON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 706-7755
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2006-01-10

Site Id: 18965
Affiliation Type: Facility Owner
Company Name: ROTA HOLDING CORP
Contact Type: AGENT
Contact Name: DAVID BARON
Address1: 335 WEST 19TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10011
Country Code: 001
Phone: (718) 706-7755
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2006-01-10

Site Id: 18965
Affiliation Type: Mail Contact

ROTA HOLDING CORP (Continued) **U004048178**

Company Name:	METRO MGMT DEVELOPMENT CORP.
Contact Type:	Not reported
Contact Name:	DAVID BARON
Address1:	42-25 21ST STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 706-7755
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-01-10

Tank Info:

Tank Number:	001
Tank Id:	21535
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	B02 - Tank External Protection - Original Sacrificial Anode
	F00 - Pipe External Protection - None
	C01 - Pipe Location - Aboveground
	J02 - Dispenser - Suction Dispenser
	G99 - Tank Secondary Containment - Other
	K00 - Spill Prevention - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	H00 - Tank Leak Detection - None
	E00 - Piping Secondary Containment - None
	L00 - Piping Leak Detection - None
	I05 - Overfill - Vent Whistle
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	11/17/2005
Register:	True
Modified By:	KXTANG
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

N316 **OLD GAS STATION** **NY Spills** **S104195688**
NNW **10TH AV / 20TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.094 mi.
494 ft. **Site 12 of 25 in cluster N**

Relative: **Lower**

Actual: **11 ft.**

SPILLS:

Name:	OLD GAS STATION
Address:	10TH AV / 20TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9907805 / 2003-03-04
Facility ID:	9907805
Facility Type:	ER
DER Facility ID:	143100
Site ID:	170063
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	3101
Spill Date:	1999-09-28
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1999-09-28
CID:	312
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1999-09-28
Spill Record Last Update:	2003-03-04
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"DIGGING UP THE OLD TANKS AT THE OLD GAS STATION - SEVERE ODORS PRESENT - COMP HAS CALLED NYC DEP ALREADY CASE #75955"

All Materials:

Site ID:	170063
Operable Unit ID:	1082077
Operable Unit:	01
Material ID:	300488
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

N317 **CON EDISON SERVICE BOX: 3610** **RCRA NonGen / NLR** **1016149057**
NNW **W 20TH ST & 10TH AVE** **NYP004277141**
< 1/8 **NEW YORK, NY 10011**
0.094 mi.
494 ft. **Site 13 of 25 in cluster N**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130325
Handler Name:	CON EDISON SERVICE BOX:	3610
Handler Address:		W 20TH ST & 10TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004277141
Contact Name:		JOSE MONTALVO
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-427-1331
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 3610 (Continued) **1016149057**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130225
Handler Name: CON EDISON SERVICE BOX:	3610
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130325
Handler Name: CON EDISON SERVICE BOX:	3610
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 3610 (Continued) **1016149057**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

N318 **CON EDISON SERVICE BOX: 3608** **RCRA NonGen / NLR** **1016149051**
NNW **434-436 W 20TH ST & 10TH AVE E OF** **NYP004277083**
< 1/8 **NEW YORK, NY 10011**
0.094 mi.
494 ft. **Site 14 of 25 in cluster N**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130325
Handler Name:	CON EDISON SERVICE BOX: 3608
Handler Address:	434-436 W 20TH ST & 10TH AVE E OF
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004277083
Contact Name:	JOSE MONTALVO
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-427-1331
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

CON EDISON SERVICE BOX: 3608 (Continued) **1016149051**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130225
Handler Name: CON EDISON SERVICE BOX:	3608
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CON EDISON SERVICE BOX: 3608 (Continued) **1016149051**

Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20130325
Handler Name: CON EDISON SERVICE BOX:	3608
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

N319 **W 20 ST AND 10TH AVE** **NY Spills** **S104652993**
NNW **WEST 20TH ST & 10TH AVE** **N/A**
< 1/8 **MANHATTAN, NY**
0.094 mi.
494 ft. **Site 15 of 25 in cluster N**

Relative:
Lower

Actual:
11 ft.

SPILLS:

Name:	W 20 ST AND 10TH AVE
Address:	WEST 20TH ST & 10TH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0030004 / 2020-01-10
Facility ID:	0030004
Facility Type:	ER
DER Facility ID:	215437
Site ID:	264326
DEC Region:	2
Spill Cause:	Other
Spill Class:	C3
SWIS:	3101
Spill Date:	2000-05-22
Investigator:	EJKIM
Referred To:	Not reported
Reported to Dept:	2000-05-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

W 20 ST AND 10TH AVE (Continued) **S104652993**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-22
Spill Record Last Update:	2020-01-10
Spiller Name:	Not reported
Spiller Company:	GAS STATION
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 6/8/07-Matthew Klaas (Albany DER) -Tried contacting Charles Rosenblum at 212-924-9086, the number is no longer in service. -There are no other contacts listed, and I was unable to locate a new number for the listed company. 6/13/07-Matthew Klaas (Albany DER) -Wrote a letter to Charles Rosenblum at 452 West 20th Street Apt. 1 New York, NY 10011-2942 requesting information regarding this spill. 4/1/09 - Austin - Transferred from Needs Reassignment to Zhune for further work to remediate and close - end 8/26/19 - Spill reassigned to Kim as per Obligado. 1/10/20 - Kim - Received an inquiry about the spill from Dan Love; he is performing a Phase 2 Environmental Assessment at nearby properties at 146-150 10th Ave, 3 buildings undergoing a gut renovation. Dan stated that they have excavated at their site to access plumbing and did not notice any petroleum odors. 2-326267: GETTY 58542, 152 10TH AVE, NY, NY 10011; Status: Unregulated/Closed This spill is associated with Spill # 9210231 at 152 10th Ave managed by Jeff Vought. 152 10th Ave underwent substantial remediation and the case was closed 3/10/04; at that time, the entire lot was excavated to property lines and to a depth of approximately 15'. This spill no longer seems to be a threat to human health or the environment. Spill closed."
Remarks:	"CONSTRUCTION GOING ON AT OLD GAS STATION SITE - NEW BUILDING BEING CONSTRUCTED. ODOR OF GASOLINE - IN STREET AND IN BASEMENT ROOMS. AT 452 W 20TH. NEIGHBORS HAVE SAME PROBLEM."

All Materials:

Site ID:	264326
Operable Unit ID:	835549
Operable Unit:	01
Material ID:	540893
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

N320 **CON EDISON SPLICE BOX: 3610** **RCRA NonGen / NLR** **1016149163**
NNW **W 20TH & 10TH AVE** **NY MANIFEST** **NYP004278222**
< 1/8 **NEW YORK, NY 10011**
0.094 mi.
494 ft. **Site 16 of 25 in cluster N**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130325
Handler Name:	CON EDISON SPLICE BOX: 3610
Handler Address:	W 20TH & 10TH AVE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004278222
Contact Name:	JOSE MONTALVO
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-427-1331
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON SPLICE BOX: 3610 (Continued) **1016149163**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130225
Handler Name:	CON EDISON SPLICE BOX: 3610
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130325
Handler Name:	CON EDISON SPLICE BOX: 3610
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON SPLICE BOX: 3610 (Continued) **1016149163**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: W 20TH & 10TH AVE
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004278222
Facility Status: Not reported
Location Address 1: F/O 428-424 W 20TH ST & 10TH AVE
Code: BP
Location Address 2: SERV BOX 3610
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004278222
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 02/26/2013
Trans1 Recv Date: 02/26/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/26/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004278222

CON EDISON SPLICE BOX: 3610 (Continued) **1016149163**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010708028JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

N321 **CON EDISON SERVICE BOX: 3604** **RCRA NonGen / NLR** **1016149037**
NNW **W 20TH ST & 10TH AVE** **FINDS** **NYP004276945**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.094 mi. **NY MANIFEST**
494 ft. **Site 17 of 25 in cluster N**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130325
Handler Name:	CON EDISON SERVICE BOX:	3604
Handler Address:		W 20TH ST & 10TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004276945
Contact Name:		JOSE MONTALVO
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-427-1331
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified

CON EDISON SERVICE BOX: 3604 (Continued) **1016149037**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No

CON EDISON SERVICE BOX: 3604 (Continued) **1016149037**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130225
Handler Name: CON EDISON SERVICE BOX:	3604
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130325
Handler Name: CON EDISON SERVICE BOX:	3604
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063898929

Click Here:

Environmental Interest/Information System:

CON EDISON SERVICE BOX: 3604 (Continued) **1016149037**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016149037
Registry ID:	110063898929
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110063898929
Name:	CON EDISON SERVICE BOX: 3604
Address:	W 20TH ST & 10TH AVE
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	CON EDISON
Address:	W 20TH ST & 10TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004276945
Facility Status:	Not reported
Location Address 1:	OPP 418 W 20TH ST E/O 110TH AVE
Code:	BP
Location Address 2:	SERV BOX 3604
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004276945
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/25/2013
Trans1 Recv Date:	02/25/2013
Trans2 Recv Date:	Not reported

CON EDISON SERVICE BOX: 3604 (Continued) **1016149037**

TSD Site Recv Date:	02/26/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004276945
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010708015JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Name:	CON EDISON
Address:	434-436 W 20TH ST & 10TH AVE E
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004277083
Facility Status:	Not reported
Location Address 1:	F/O 436-434 W 20TH ST E/O 10TH AVE
Code:	BP
Location Address 2:	SERV BOX 3608
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004277083
Mailing Name:	CON EDISON

CON EDISON SERVICE BOX: 3604 (Continued) **1016149037**

Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/25/2013
Trans1 Recv Date:	02/25/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/26/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004277083
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010708016JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON EDISON SERVICE BOX: 3604 (Continued) **1016149037**

Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

N322 **CON EDISON** **NY MANIFEST** **S117058360**
NNW **10 AVE & 20 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.094 mi.
494 ft. **Site 18 of 25 in cluster N**

Relative:
Lower

Actual:
11 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	10 AVE & 20 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004504478
Facility Status:	Not reported
Location Address 1:	10 AVE & 20 ST
Code:	BP
Location Address 2:	SB43082
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004504478
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/18/2014
Trans1 Recv Date:	04/18/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004504478
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046

CON EDISON (Continued) **S117058360**

TSDF ID 2:	Not reported
Manifest Tracking Number:	011697553JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P323 **CON EDISON** **NY MANIFEST** **S117067534**
NE **FO 353 WEST 21 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.094 mi.
495 ft. **Site 13 of 17 in cluster P**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FO 353 WEST 21 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004604740
Facility Status:	Not reported
Location Address 1:	FO 353 WEST 21 ST
Code:	BP
Location Address 2:	SB 3782
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004604740
Mailing Name:	CON EDISON

CON EDISON (Continued) **S117067534**

Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/23/2014
Trans1 Recv Date:	07/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004604740
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504470GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON EDISON (Continued) **S117067534**

Waste Code 1_6: Not reported

N324 **178-10 69TH AVE/QUEENS** **NY LTANKS** **S102671227**
NNW **178-10 69TH AVE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.094 mi.
495 ft. **Site 19 of 25 in cluster N**

Relative: **Lower**

Actual: **11 ft.**

LTANKS:

Name:	178-10 69TH AVE/QUEENS
Address:	178-10 69TH AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8708234 / 1988-01-12
Facility ID:	8708234
Site ID:	69350
Spill Date:	1987-12-22
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1987-12-23
SWIS:	4101
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1987-12-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-01-13
Spill Record Last Update:	1989-03-13
Spiller Name:	Not reported
Spiller Company:	CENTRAL PETROLEUM
Spiller Address:	642 SOUTHERN BLVD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	65936
DEC Memo:	""
Remarks:	"SPILLER CLEANED AND PICKED UP CONTAMINATED SOIL, PLACED ABSORBENTS ON SIDEWALK AND REMOVED THEM, NO ACTION REQUIRED BY DEC."

All Materials:

Site ID:	69350
Operable Unit ID:	913753
Operable Unit:	01
Material ID:	463628
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00

178-10 69TH AVE/QUEENS (Continued) **S102671227**

Units: Not reported
Recovered: .00
Oxygenate: Not reported

S325 **ABBIS** **EDR Hist Auto** **1020324237**
SSW **55 NINTH AV** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.094 mi.
496 ft. **Site 3 of 18 in cluster S**

Relative: EDR Hist Auto
Higher

Actual:
15 ft.

Year:	Name:	Type:
1986	ABBIS	Gasoline Service Stations
1987	ABBIS	Gasoline Service Stations
1988	ABBIS	Gasoline Service Stations

Q326 **NORTHEAST LABORATORY - DRUG ENFORCEMENT** **RCRA-SQG** **1000833453**
West **99 10TH AVE ROOM 721** **FINDS** **NYD987017514**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.095 mi. **NY MANIFEST**
504 ft. **Site 23 of 25 in cluster Q** **NJ MANIFEST**

Relative: RCRA-SQG:
Lower

Actual:
8 ft.

Date Form Received by Agency:	20070101
Handler Name:	NORTHEAST LABORATORY - DRUG ENFORCEMENT
Handler Address:	99 10TH AVE ROOM 721
Handler City,State,Zip:	NEW YORK, NY 10011-4713
EPA ID:	NYD987017514
Contact Name:	ROGER GODINO
Contact Address:	10TH AVE ROOM 721
Contact City,State,Zip:	NEW YORK, NY 10011-4713
Contact Telephone:	212-620-3677
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	10TH AVE ROOM 721
Mailing City,State,Zip:	NEW YORK, NY 10011-4713
Owner Name:	ABLE EMPIRE
Owner Type:	Private
Operator Name:	ABLE EMPIRE
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No

NORTHEAST LABORATORY - DRUG ENFORCEMENT (Continued) **1000833453**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined

NORTHEAST LABORATORY - DRUG ENFORCEMENT (Continued) **1000833453**

Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D002
Waste Description: CORROSIVE WASTE

Waste Code: U044
Waste Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Waste Code: U117
Waste Description: ETHANE, 1,1'-OXYBIS-(I) (OR) ETHYL ETHER (I)

Waste Code: U154
Waste Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: ABLE EMPIRE
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 99 10TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10011-4713
Owner/Operator Telephone: 212-989-0175
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ABLE EMPIRE
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 99 10TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10011-4713
Owner/Operator Telephone: 212-989-0175
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ABLE EMPIRE
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 99 10TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10011-4713
Owner/Operator Telephone: 212-989-0175
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NORTHEAST LABORATORY - DRUG ENFORCEMENT
Federal Waste Generator Description: Small Quantity Generator

NORTHEAST LABORATORY - DRUG ENFORCEMENT (Continued) **1000833453**

State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NORTHEAST LABORATORY - DRUG ENFORCEMENT
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920702
Handler Name: NORTHEAST LABORATORY - DRUG ENFORCEMENT
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Listing - General
Date Violation was Determined: 20030801
Actual Return to Compliance Date: 20031201
Return to Compliance Qualifier: Documented
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported

NORTHEAST LABORATORY - DRUG ENFORCEMENT (Continued) **1000833453**

Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20030801
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2CFP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	20031201
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:

Registry ID: 110004495984

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000833453
Registry ID:	110004495984
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004495984

NORTHEAST LABORATORY - DRUG ENFORCEMENT (Continued) **1000833453**

Name:	NORTHEAST LABORATORY - DRUG ENFORCEMENT
Address:	99 10TH AVE ROOM 721
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	DRUG ENFORCEMENT AGENCY NORTHEAST LABORA
Address:	99 10TH AVE ROOM 721
City,State,Zip:	NEW YORK, NY 10011-4713
Country:	USA
EPA ID:	NYD987017514
Facility Status:	Not reported
Location Address 1:	99 10TH AVE RM 721
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987017514
Mailing Name:	DRUG ENFORCEMENT AGENCY NORTHEAST LABORA
Mailing Contact:	ROGER W GODINO
Mailing Address 1:	99 10TH AVE RM 721
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2126203684

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	12/21/2006
Trans1 Recv Date:	12/21/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/21/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987017514
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	001029773JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

NORTHEAST LABORATORY - DRUG ENFORCEMENT (Continued) **1000833453**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

NJ MANIFEST:

EPA Id:	NYD987017514
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	2126204925
Emergency Phone:	Not reported
Contact:	LEON BROUN
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	NJA5282122
EPA ID:	NYD987017514
Date Shipped:	07/06/2006
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

NORTHEAST LABORATORY - DRUG ENFORCEMENT (Continued) **1000833453**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/06/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/06/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08090622
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5254998
EPA ID:	NYD987017514
Date Shipped:	07/13/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/13/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/13/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported

NORTHEAST LABORATORY - DRUG ENFORCEMENT (Continued) **1000833453**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08250521
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5212308
EPA ID:	NYD987017514
Date Shipped:	01/14/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/14/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/14/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	02040521
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	003634088JJK
EPA ID:	NYD987017514
Date Shipped:	3/1/2011

NORTHEAST LABORATORY - DRUG ENFORCEMENT (Continued) **1000833453**

TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	15.00 gallons
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	110.00 gallons
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	30.00 gallons
Manifest Number:	NJA5313750
EPA ID:	NYD987017514
Date Shipped:	02/28/2006

NORTHEAST LABORATORY - DRUG ENFORCEMENT (Continued) **1000833453**

TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/28/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/28/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	04200621
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	003531936JJK
EPA ID:	NYD987017514
Date Shipped:	07/24/2008
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/24/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported

NORTHEAST LABORATORY - DRUG ENFORCEMENT (Continued) **1000833453**

Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/24/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	110 G
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	30 G
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	5 G
Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	5 G
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H061
Quantity:	55 G
Manifest Number:	NJA5212309
EPA ID:	NYD987017514
Date Shipped:	01/14/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported

NORTHEAST LABORATORY - DRUG ENFORCEMENT (Continued) **1000833453**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/14/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/14/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	02040521
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5243177
EPA ID:	NYD987017514
Date Shipped:	09/19/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/19/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/19/2005

NORTHEAST LABORATORY - DRUG ENFORCEMENT (Continued) **1000833453**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	11100521
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	003634077JJK
EPA ID:	NYD987017514
Date Shipped:	8/1/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

NORTHEAST LABORATORY - DRUG ENFORCEMENT (Continued) **1000833453**

Waste:

Manifest Year:	Not reported
Waste Code:	D009
Hand Code:	H141
Quantity:	5.00 gallons
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	110.00 gallons
Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	15.00 gallons
Manifest Number:	003634050JJK
EPA ID:	NYD987017514
Date Shipped:	12/13/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

NORTHEAST LABORATORY - DRUG ENFORCEMENT (Continued) **1000833453**

Waste:

Manifest Year:	Not reported
Waste Code:	U138
Hand Code:	H141
Quantity:	1.00 Pounds
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	1.00 Pounds
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	1.00 Pounds
Manifest Year:	Not reported
Waste Code:	D022
Hand Code:	H141
Quantity:	240.00 Pounds
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H061
Quantity:	10.00 Pounds
Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	40.00 Pounds
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H061
Quantity:	80.00 Pounds
Manifest Year:	Not reported
Waste Code:	D009
Hand Code:	H141
Quantity:	5.00 Pounds
Manifest Number:	NJA5243178
EPA ID:	NYD987017514
Date Shipped:	09/19/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/19/2005

NORTHEAST LABORATORY - DRUG ENFORCEMENT (Continued) **1000833453**

Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/19/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	11100521
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	009205216JJK
EPA ID:	NYD987017514
Date Shipped:	5/29/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

NORTHEAST LABORATORY - DRUG ENFORCEMENT (Continued) **1000833453**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	600.00 Pounds
Manifest Year:	Not reported
Waste Code:	D002 D022
Hand Code:	Not reported
Quantity:	20.00 Pounds
Manifest Year:	Not reported
Waste Code:	D001 F003 D022
Hand Code:	Not reported
Quantity:	100.00 Pounds

Q327 **DEA** **NY AST** **1009233110**
West **99 10TH AVE.** **NY MANIFEST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.095 mi.
504 ft. **Site 24 of 25 in cluster Q**

Relative: **Lower**

Actual: **8 ft.**

AST:

Name:	DEA
Address:	99 10TH AVE.
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-613110
Program Type:	PBS
UTM X:	Not reported
UTM Y:	Not reported
Expiration Date:	11/01/2024
Site Type:	Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:

Site Id:	599210
Affiliation Type:	Mail Contact
Company Name:	CBRE, INC.
Contact Type:	Not reported
Contact Name:	ALICE VALENTINE
Address1:	99 TENTH AVE
Address2:	Not reported
City:	NEW YORK
State:	NY

DEA (Continued) **1009233110**

Zip Code: 10011
Country Code: 001
Phone: (646) 946-3914
EMail: ALICE.VALENTINE@CBRE.COM
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2020-01-06

Site Id: 599210
Affiliation Type: Emergency Contact
Company Name: ABLE EMPIRE GROUP
Contact Type: Not reported
Contact Name: IVAN RIVERA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 533-7621
EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2019-12-13

Site Id: 599210
Affiliation Type: Facility Operator
Company Name: DEA
Contact Type: Not reported
Contact Name: ALICE VALENTINE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 946-3914
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2020-01-06

Site Id: 599210
Affiliation Type: Facility Owner
Company Name: ABLE EMPIRE GROUP
Contact Type: REAL ESTATE MANAGER
Contact Name: ALICE VALENTINE
Address1: 100 PEABODY PLACE, SUITE 1400
Address2: Not reported
City: MEMPHIS
State: TN
Zip Code: 38103
Country Code: 001
Phone: (901) 260-7278
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI

DEA (Continued) **1009233110**

Date Last Modified: 2020-01-06

Tank Info:

Tank Number: 001
Tank Id: 283313

Equipment Records:

G00 - Tank Secondary Containment - None
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E00 - Piping Secondary Containment - None
C01 - Pipe Location - Aboveground
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
K00 - Spill Prevention - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 11/01/2019
Capacity Gallons: 1223
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: JSMACRI
Last Modified: 01/06/2020
Material Name: #2 fuel oil (resale/redistribute)

NY MANIFEST:
Name: DRUG ENFORCEMENT AGENCY
Address: 99 10TH AVE
City,State,Zip: NEW YORK, NY 10010
Country: USA
EPA ID: NYP000907337
Facility Status: Not reported
Location Address 1: 99 10TH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10010
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP000907337
Mailing Name: DRUG ENFORCEMENT AGENCY
Mailing Contact: WILLIAM A GURLEY
Mailing Address 1: 99 10TH AVE

DEA (Continued) **1009233110**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10010
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9145671280

Name:	DWG ENFORCEMENT AGENCY
Address:	99 10TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP000924514
Facility Status:	Not reported
Location Address 1:	99 10TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000924514
Mailing Name:	DWG ENFORCEMENT AGENCY
Mailing Contact:	LARRY MENDOZA
Mailing Address 1:	99 10TH ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2123371545

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Q328 **ABLE EMPIRE GROUP** **RCRA NonGen / NLR** **1000994402**
West **99 TENTH AVE** **NY MANIFEST** **NYD986878601**
< 1/8 **NEW YORK, NY 10011**
0.095 mi.
504 ft. **Site 25 of 25 in cluster Q**

Relative: **Lower**
Actual: **8 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	ABLE EMPIRE GROUP	
Handler Address:		99 TENTH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYD986878601
Contact Name:		Not reported
Contact Address:		FIFTH AVE
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		Not reported
Contact Fax:		Not reported

ABLE EMPIRE GROUP (Continued) **1000994402**

Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	FIFTH AVE
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	ABE HIRSCHFELD
Owner Type:	Private
Operator Name:	ABE HIRSCHFELD
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A

ABLE EMPIRE GROUP (Continued) **1000994402**

Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ABE HIRSCHFELD
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ABE HIRSCHFELD
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

ABLE EMPIRE GROUP (Continued) **1000994402**

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ABE HIRSCHFELD
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19950414
Handler Name: ABLE EMPIRE GROUP	
Federal Waste Generator Description:	Not reported
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: ABLE EMPIRE GROUP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: ABLE EMPIRE GROUP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19881201
Handler Name: ABLE EMPIRE GROUP	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

ABLE EMPIRE GROUP (Continued) **1000994402**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	DRUG ENFORCEMENT ADMINISTRATION
Address:	99 TENTH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYD986878601
Facility Status:	Not reported
Location Address 1:	N EAST LABORATORY SUITE 721
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986878601
Mailing Name:	DRUG ENFORCEMENT ADMINISTRATION
Mailing Contact:	ROGER GODINO
Mailing Address 1:	99 TENTH AVE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2126203677

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	10/14/2010

ABLE EMPIRE GROUP (Continued) **1000994402**

Trans1 Recv Date:	10/14/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/14/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986878601
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000434534VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	720
Units:	P - Pounds
Number of Containers:	3
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P329 **APHRODITE FRENCH CLEANERS** **NY DRYCLEANERS** **S110245931**
NE **186 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.096 mi.
505 ft. **Site 14 of 17 in cluster P**

Relative:
Higher

Actual:
16 ft.

DRYCLEANERS:

Name:	APHRODITE FRENCH CLEANERS
Address:	186 9TH AVE
City,State,Zip:	NEW YORK, NY 10011
Facility ID:	---
Phone Number:	Not reported
Region:	2
Registration Effective Date:	???
Inspection Date:	Not reported
Install Date:	Not reported

APHRODITE FRENCH CLEANERS (Continued) **S110245931**

Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	???

P330 **CHELSEA TAILOR** **EDR Hist Cleaner** **1018842674**
NE **186 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.096 mi.
505 ft. **Site 15 of 17 in cluster P**

Relative: EDR Hist Cleaner
Higher

Actual:
16 ft.

Year:	Name:	Type:
2004	LUXOR CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2005	LUXOR CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2006	LUXOR CLEANERS INC	Drycleaning Plants, Except Rugs, NEC

T331 **NYC BOARD OF EDUCATION INTERMEDIATE SCHOOL 70** **RCRA-VSQG** **1001233145**
SE **333 W 17TH ST** **FINDS** **NYR000062604**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.096 mi. **NY MANIFEST**
507 ft. **Site 1 of 20 in cluster T**

Relative: RCRA-VSQG:
Higher

Actual:
18 ft.

Date Form Received by Agency:	20070101
Handler Name:	NYC BOARD OF EDUCATION INTERMEDIATE SCHOOL 70
Handler Address:	333 W 17TH ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYR000062604
Contact Name:	FRANK CARDELLO
Contact Address:	QUEENS PLAZA N
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-391-6832
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	QUEENS PLAZA N
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	NYC BD OF ED
Owner Type:	Municipal
Operator Name:	NYC BD OF ED
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No

NYC BOARD OF EDUCATION INTERMEDIATE SCHOOL 70 (Continued) **1001233145**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:
Waste Code: D000

NYC BOARD OF EDUCATION INTERMEDIATE SCHOOL 70 (Continued) **1001233145**

Waste Description: Not Defined

Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D002
Waste Description: CORROSIVE WASTE

Waste Code: D003
Waste Description: REACTIVE WASTE

Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: NYC BD OF ED
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 28-11 QUEENS PLZ N
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-391-6832
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC BD OF ED
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 28-11 QUEENS PLZ N
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-391-6832
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYC BD OF ED
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 28-11 QUEENS PLZ N
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-391-6832
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYC BD OF ED - INTERMEDIATE SCHOOL 70
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY

NYC BOARD OF EDUCATION INTERMEDIATE SCHOOL 70 (Continued) **1001233145**

Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYC BOARD OF EDUCATION INTERMEDIATE SCHOOL 70
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19981026
Handler Name: NYC BD OF ED - INTERMEDIATE SCHOOL 70
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 61111
NAICS Description: ELEMENTARY AND SECONDARY SCHOOLS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004548099

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

NYC BOARD OF EDUCATION INTERMEDIATE SCHOOL 70 (Continued) **1001233145**

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001233145
Registry ID:	110004548099
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004548099
Name:	NYC BD OF ED - INTERMEDIATE SCHOOL 70
Address:	333 W 17TH ST
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	NYC LAB SCHOOL M IS 70
Address:	333 W 17TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYR000062604
Facility Status:	Not reported
Location Address 1:	333 WEST 17TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000062604
Mailing Name:	NYC LAB SCHOOL M IS 70
Mailing Contact:	KASHIF MIAN
Mailing Address 1:	333 WEST 17TH ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2129896344

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	10/30/2015
Trans1 Recv Date:	10/30/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000062604

NYC BOARD OF EDUCATION INTERMEDIATE SCHOOL 70 (Continued) **1001233145**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	008915241FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

T332 **I.S. 70 - MANHATTAN M070** **NY AST** **U003394165**
SE **333 WEST 17TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.096 mi.
507 ft. **Site 2 of 20 in cluster T**

Relative:
Higher

Actual:
18 ft.

AST:

Name:	I.S. 70 - MANHATTAN M070
Address:	333 WEST 17TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-353914
Program Type:	PBS
UTM X:	584236.59606
UTM Y:	4510626.80736
Expiration Date:	06/28/2023
Site Type:	School

Affiliation Records:

Site Id:	17577

I.S. 70 - MANHATTAN M070 (Continued) **U003394165**

Affiliation Type:	Facility Operator
Company Name:	I.S. 70 - MANHATTAN M070
Contact Type:	Not reported
Contact Name:	SALVATORE CALDERONE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 691-6119
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-02-23

Site Id:	17577
Affiliation Type:	Mail Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	JOSEPH YOUNGESE
Address1:	FIELD OPERATIONS - FUEL DIVISION
Address2:	44-36 VERNON BOULEVARD
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5751
EMail:	JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2020-12-18

Site Id:	17577
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	KEN MAHADEO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 210-7918
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2021-05-05

Site Id:	17577
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	MUNENDRA SHARMA
Address1:	44-36 VERNON BOULEVARD
Address2:	Not reported

I.S. 70 - MANHATTAN M070 (Continued) **U003394165**

City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-07-17

Tank Info:

Tank Number:	001
Tank Id:	34379
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1966
Capacity Gallons:	10000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	02/23/2018
Material Name:	#4 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	34380
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

I.S. 70 - MANHATTAN M070 (Continued) **U003394165**

L00 - Piping Leak Detection - None
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1966
Capacity Gallons:	10000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	02/23/2018
Material Name:	#4 fuel oil (on-site consumption)

L333 **CON EDISON** **NY MANIFEST** **S118463847**
SE **OPP 332 W 17TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.096 mi.
507 ft. **Site 16 of 18 in cluster L**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	OPP 332 W 17TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004857934
Facility Status:	Not reported
Location Address 1:	OPP 332 W 17TH ST
Code:	BP
Location Address 2:	SB 3012
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004857934
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003

CON EDISON (Continued) **S118463847**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/2015
Trans1 Recv Date:	10/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004857934
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014087632JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L334 **CON EDISON** **RCRA NonGen / NLR** **1014395673**
SE **332 W 17TH ST** **NJ MANIFEST** **NYP004171385**
< 1/8 **NEW YORK, NY 10014** **NY MANIFEST**
0.096 mi.
507 ft. **Site 17 of 18 in cluster L**

Relative: **Higher**
Actual: **18 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		332 W 17TH ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004171385
Contact Name:		DAVID DUKE
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		917-559-8971
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1014395673**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160727
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090608
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1014395673**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004171385
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DAVID DUKE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	003532079JJK
EPA ID:	NYP004171385
Date Shipped:	06/08/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/08/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/09/2009

CON EDISON (Continued) **1014395673**

TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 1000 P

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 332 W 17TH ST
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYP004171385
Facility Status: Not reported
Location Address 1: OPP 332 W 17TH ST.
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004171385
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: CONSOLIDATED EDISON
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported

CON EDISON (Continued) **1014395673**

seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/08/2009
Trans1 Recv Date:	06/08/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/09/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004171385
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003532079JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P335 **RITE AID # 4196** **PA MANIFEST** **S118891114**
NE **188 9TH AVENUE** **N/A**
< 1/8 **NY, NY 10011**
0.098 mi.
520 ft. **Site 16 of 17 in cluster P**

Relative: Manifest Details:
Higher

Year:	2015
Manifest Number:	007394887FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000188623

Actual:
16 ft.

RITE AID # 4196 (Continued) **S118891114**

Generator Date:	02/28/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	P001
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	007394887FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000188623
Generator Date:	02/28/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D010
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	15
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	007394887FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000188623
Generator Date:	02/28/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported

RITE AID # 4196 (Continued) **S118891114**

Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D011
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	15
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

P336 **RITE AID #04196** **RCRA-VSQG 1014927072**
NE **188 9TH AVE** **NY MANIFEST NYR000188623**
< 1/8 **NEW YORK, NY 10011**
0.098 mi.
520 ft. **Site 17 of 17 in cluster P**

Relative: RCRA-VSQG:
Higher

Date Form Received by Agency:		20190417
Actual: Handler Name:	RITE AID #04196	
16 ft. Handler Address:		188 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYR000188623
Contact Name:		JOSEPH A CHEST
Contact Address:		HUNTER LN
Contact City,State,Zip:		CAMP HILL, PA 17011
Contact Telephone:		717-975-8643
Contact Fax:		717-972-3989
Contact Email:		EHS@RITEAID.COM
Contact Title:		MANAGER ENVIRONMENTAL HEALTH SERVICES
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		HUNTER LN
Mailing City,State,Zip:		CAMP HILL, PA 17011
Owner Name:		LTH ASSOCIATES LP
Owner Type:		Private
Operator Name:		RITE AID OF NEW YORK INC
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No

RITE AID #04196 (Continued) **1014927072**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200228
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

RITE AID #04196 (Continued) **1014927072**

Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D005
Waste Description:	BARIUM
Waste Code:	D007
Waste Description:	CHROMIUM
Waste Code:	D009
Waste Description:	MERCURY
Waste Code:	D010
Waste Description:	SELENIUM
Waste Code:	D011
Waste Description:	SILVER
Waste Code:	D013
Waste Description:	LINDANE (1,2,3,4,5,6-HEXA-CHLOROCYCLOHEXANE, GAMMA ISOMER)
Waste Code:	D016
Waste Description:	2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)
Waste Code:	D018
Waste Description:	BENZENE
Waste Code:	D022
Waste Description:	CHLOROFORM
Waste Code:	D024
Waste Description:	M-CRESOL
Waste Code:	D026
Waste Description:	CRESOL
Waste Code:	D027
Waste Description:	1,4-DICHLOROBENZENE
Waste Code:	D035
Waste Description:	METHYL ETHYL KETONE
Waste Code:	P001
Waste Description:	2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Waste Code:	P075
Waste Description:	NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS
Waste Code:	U002
Waste Description:	2-PROPANONE (I) (OR) ACETONE (I)
Waste Code:	U035
Waste Description:	BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

RITE AID #04196 (Continued) **1014927072**

Waste Code: U044
Waste Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Waste Code: U058
Waste Description: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

Waste Code: U072
Waste Description: BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE

Waste Code: U122
Waste Description: FORMALDEHYDE

Waste Code: U129
Waste Description: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

Waste Code: U154
Waste Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Waste Code: U165
Waste Description: NAPHTHALENE

Waste Code: U188
Waste Description: PHENOL

Waste Code: U201
Waste Description: 1,3-BENZENEDIOL (OR) RESORCINOL

Waste Code: U205
Waste Description: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

Waste Code: U211
Waste Description: CARBON TETRACHLORIDE (OR) METHANE, TETRACHLORO-

Waste Code: U240
Waste Description: 2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D

Waste Code: U279
Waste Description: U279

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: RITE AID OF NEW YORK INC
Legal Status: Private
Date Became Current: 19960219
Date Ended Current: Not reported
Owner/Operator Address: 30 HUNTER LN
Owner/Operator City,State,Zip: CAMP HILL, PA 17011
Owner/Operator Telephone: 717-761-2633
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: 717-972-3989
Owner/Operator Email: EHS@RITEAID.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: RITE AID OF NEW YORK INC

RITE AID #04196 (Continued) **1014927072**

Legal Status:	Private
Date Became Current:	19960219
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	RITE AID CORP
Legal Status:	Private
Date Became Current:	19960219
Date Ended Current:	Not reported
Owner/Operator Address:	30 HUNTER LN
Owner/Operator City,State,Zip:	CAMP HILL, PA 17011
Owner/Operator Telephone:	717-761-2633
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	RITE AID
Legal Status:	Private
Date Became Current:	19960219
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	LTH ASSOCIATES LP
Legal Status:	Private
Date Became Current:	19950901
Date Ended Current:	Not reported
Owner/Operator Address:	770 LEXINGTON AVE 18TH FL
Owner/Operator City,State,Zip:	NEW YORK, NY 10065
Owner/Operator Telephone:	212-876-4200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	LTH ASSOCIATES LP
Legal Status:	Private
Date Became Current:	19950901
Date Ended Current:	Not reported
Owner/Operator Address:	770 LEXINGTON AVE 18TH FL
Owner/Operator City,State,Zip:	NEW YORK, NY 10065
Owner/Operator Telephone:	212-876-4200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

RITE AID #04196 (Continued) **1014927072**

Owner/Operator Indicator:	Owner
Owner/Operator Name:	RITE AID CORP
Legal Status:	Private
Date Became Current:	19960219
Date Ended Current:	Not reported
Owner/Operator Address:	30 HUNTER LN
Owner/Operator City,State,Zip:	CAMP HILL, PA 17011
Owner/Operator Telephone:	717-761-2633
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	RITE AID OF NEW YORK INC
Legal Status:	Private
Date Became Current:	19960219
Date Ended Current:	Not reported
Owner/Operator Address:	30 HUNTER LANE
Owner/Operator City,State,Zip:	CAMP HILL, PA 17011
Owner/Operator Telephone:	717-761-2633
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20111104
Handler Name: RITE AID #4196	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130510
Handler Name: RITE AID #4196	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20151120
Handler Name: RITE AID #04196	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	Not reported

RITE AID #04196 (Continued) **1014927072**

Recognized Trader Exporter:	Not reported
Spent Lead Acid Battery Importer:	Not reported
Spent Lead Acid Battery Exporter:	Not reported
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20190417
Handler Name: RITE AID #04196	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	44611
NAICS Description:	PHARMACIES AND DRUG STORES

NAICS Code:	446110
NAICS Description:	PHARMACIES AND DRUG STORES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	RITE AID #4196
Address:	188 9TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYR000188623
Facility Status:	Not reported
Location Address 1:	188 9TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000188623
Mailing Name:	RITE AID #4196
Mailing Contact:	RITE AID #4196
Mailing Address 1:	188 9TH AVE
Mailing Address 2:	Not reported

RITE AID #04196 (Continued) **1014927072**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	CTD983872698
Trans2 State ID:	NJR000063677
Generator Ship Date:	12/02/2014
Trans1 Recv Date:	12/02/2014
Trans2 Recv Date:	12/03/2014
TSD Site Recv Date:	12/10/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000188623
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	007259892FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30
Units:	P - Pounds
Number of Containers:	1
Container Type:	BA - Burlap, plastic, paper bags
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	D010
Waste Code 1_3:	D011
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

U337 **LOT 17,TAXBLOCK 689** **NY E DESIGNATION** **S108076879**
WNW **501 WEST 17 STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.099 mi.
521 ft. **Site 1 of 15 in cluster U**

Relative: **Lower**
Actual: **9 ft.**

E DESIGNATION:

Name:	LOT 17,TAXBLOCK 689
Address:	501 WEST 17 STREET
City,State,Zip:	MANHATTAN, NY
Tax Lot(s):	17
Tax Block:	689
Borough Code:	Not reported
E-No:	E-142
Effective Date:	6/23/2005
Satisfaction Date:	Not reported
Ceqr Number:	03DCP069M
Ulurp Number:	050161 ZRM
Zoning Map No:	8b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

U338 **HLP PROPERTIES LOT** **RCRA-SQG** **1014958199**
WNW **501-515 W 17TH ST** **NY MANIFEST** **NYR000194449**
< 1/8 **NEW YORK, NY 10011**
0.099 mi.
521 ft. **Site 2 of 15 in cluster U**

Relative: **Lower**
Actual: **9 ft.**

RCRA-SQG:

Date Form Received by Agency:		20120614
Handler Name:	HLP PROPERTIES LOT	
Handler Address:		501-515 W 17TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYR000194449
Contact Name:		GARY DEBODE
Contact Address:		WASHINGTON ST
Contact City,State,Zip:		NEWARK, NJ 07102
Contact Telephone:		973-849-2597
Contact Fax:		973-643-2256
Contact Email:		GARYD@EDPROP.COM
Contact Title:		PRESIDENT
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		WASHINGTON ST
Mailing City,State,Zip:		NEWARK, NJ 07102
Owner Name:		HLP PROPERTIES LLC
Owner Type:		Private
Operator Name:		EDISON NY PARKING LLC
Operator Type:		Private

HLP PROPERTIES LOT (Continued) **1014958199**

Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

HLP PROPERTIES LOT (Continued) **1014958199**

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D002
Waste Description: CORROSIVE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	HLP PROPERTIES LLC
Legal Status:	Private
Date Became Current:	20041022
Date Ended Current:	Not reported
Owner/Operator Address:	100 WASHINGTON ST
Owner/Operator City,State,Zip:	NEWARK, NJ 07102
Owner/Operator Telephone:	973-643-7700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	EDISON NY PARKING LLC
Legal Status:	Private
Date Became Current:	20081001
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20120614
Handler Name: HLP PROPERTIES LOT	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 81293
NAICS Description: PARKING LOTS AND GARAGES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:

HLP PROPERTIES LOT (Continued) **1014958199**

Evaluations: No Evaluations Found

NY MANIFEST:

Name:	HLP PROPERTIES LOT
Address:	501-515 W 17TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYR000194449
Facility Status:	Not reported
Location Address 1:	501-515 W 17TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000194449
Mailing Name:	HLP PROPERTIES LOT
Mailing Contact:	MATT DAVIS
Mailing Address 1:	100 WASHINGTON ST
Mailing Address 2:	Not reported
Mailing City:	NEWARK
Mailing State:	NJ
Mailing Zip:	07102
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9738492597

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/03/2012
Trans1 Recv Date:	08/09/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/09/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194449
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	008923086JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N

HLP PROPERTIES LOT (Continued) **1014958199**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	380
Units:	L
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

U339 **HLP PROPERTIES LOT** **NJ MANIFEST** **S117987429**
WNW **501-515 W 17TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.099 mi.
521 ft. **Site 3 of 15 in cluster U**

Relative: **Lower**

Actual: **9 ft.**

NJ MANIFEST:

EPA Id:	NYR000194449
Mail Address:	WASHINGTON ST
Mail City/State/Zip:	NEWARK, NJ 07102
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	GARY DEBODE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	008923086JJK
EPA ID:	NYR000194449
Date Shipped:	8/3/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported

HLP PROPERTIES LOT (Continued) **S117987429**

Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEWARK, NJ 07102
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	380.00 Pounds

U340 **WEST 17TH STREET DEVELOPMENT PROJECT** **NY UST** **U004220632**
WNW **501-515 WEST 17TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.099 mi.
521 ft. **Site 4 of 15 in cluster U**

Relative: UST:
Lower

Actual:
9 ft.

Name:	WEST 17TH STREET DEVELOPMENT PROJECT
Address:	501-515 WEST 17TH STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-612194 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583821.98214

WEST 17TH STREET DEVELOPMENT PROJECT (Continued) **U004220632**

UTM Y: 4510843.39236
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 492539
Affiliation Type: Facility Owner
Company Name: HLP PROPERTIES, LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 100 WASHINGTON STREET
Address2: Not reported
City: NEWARK
State: NJ
Zip Code: 07102
Country Code: 001
Phone: (973) 643-7700
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-04-18

Site Id: 492539
Affiliation Type: Mail Contact
Company Name: LARRY PEREZ
Contact Type: Not reported
Contact Name: Not reported
Address1: 100 WASHINGTON STREET
Address2: Not reported
City: NEWARK
State: NJ
Zip Code: 07102
Country Code: 001
Phone: (973) 849-2587
EMail: LARRYP@EDPROP.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-04-18

Site Id: 492539
Affiliation Type: Facility Operator
Company Name: WEST 17TH STREET DEVELOPMENT PROJECT
Contact Type: Not reported
Contact Name: NOT A CLASS BE FACILITY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: N/A
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-04-18

Site Id: 492539
Affiliation Type: Emergency Contact
Company Name: HLP PROPERTIES, LLC

WEST 17TH STREET DEVELOPMENT PROJECT (Continued) **U004220632**

Contact Type:	Not reported
Contact Name:	LARRY PEREZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(973) 849-2587
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-03-13

Tank Info:

Tank Number:	001
Tank ID:	251366
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	02/07/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	002
Tank ID:	251367
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	02/07/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR

WEST 17TH STREET DEVELOPMENT PROJECT (Continued) **U004220632**

Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Number: 003
Tank ID: 251368
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 02/07/2014
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Number: 004
Tank ID: 251369
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 02/07/2014
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None

WEST 17TH STREET DEVELOPMENT PROJECT (Continued) **U004220632**

D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Number: 005
Tank ID: 251370
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 02/07/2014
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Number: 006
Tank ID: 251371
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 02/07/2014
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None

Tank Number: 007
Tank ID: 251372

WEST 17TH STREET DEVELOPMENT PROJECT (Continued) **U004220632**

Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 02/18/2014
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Number: 008
Tank ID: 251373
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 02/18/2014
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

S341 **401 WEST 14TH STREET FEE LLC** **RCRA-VSQG** **1010328183**
SSW **401 W 14TH ST** **NY MANIFEST** **NYR000141937**
< 1/8 **NEW YORK, NY 10014**
0.099 mi.
522 ft. **Site 4 of 18 in cluster S**

Relative: **Higher**
Actual: **15 ft.**

RCRA-VSQG:

Date Form Received by Agency:	20070101
Handler Name:	401 WEST 14TH STREET FEE LLC
Handler Address:	401 W 14TH ST
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYR000141937
Contact Name:	JOHN WEIR
Contact Address:	W 14TH ST
Contact City,State,Zip:	NEW YORK, NY 10014
Contact Telephone:	212-220-9945
Contact Fax:	Not reported
Contact Email:	JWEIR@TACON.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 14TH ST
Mailing City,State,Zip:	NEW YORK, NY 10014
Owner Name:	401 WEST 14TH STREET FEE LLC
Owner Type:	Private
Operator Name:	TACONIC MANAGEMENT CO LLC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

401 WEST 14TH STREET FEE LLC (Continued) **1010328183**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211214
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	401 WEST 14TH STREET FEE LLC
Legal Status:	Private
Date Became Current:	20051215
Date Ended Current:	Not reported
Owner/Operator Address:	111 8TH AVE SUITE 1501
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	TACONIC MANAGEMENT CO LLC
Legal Status:	Private
Date Became Current:	20051215
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported

401 WEST 14TH STREET FEE LLC (Continued) **1010328183**

Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TACONIC MANAGEMENT CO LLC
Legal Status: Private
Date Became Current: 20051215
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: 401 WEST 14TH STREET FEE LLC
Legal Status: Private
Date Became Current: 20051215
Date Ended Current: Not reported
Owner/Operator Address: 111 8TH AVE SUITE 1501
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060924
Handler Name: 401 WEST 14TH STREET FEE LLC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: 401 WEST 14TH STREET FEE LLC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20060925

401 WEST 14TH STREET FEE LLC (Continued) **1010328183**

Handler Name: 401 WEST 14TH STREET FEE LLC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 53119
NAICS Description: LESSORS OF OTHER REAL ESTATE PROPERTY

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: 401 WEST 14TH STREET LLC
Address: 401 W 14TH ST
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYR000141937
Facility Status: Not reported
Location Address 1: 401 WEST 14TH STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000141937
Mailing Name: 401 WEST 14TH STREET LLC
Mailing Contact: LUIS CASILLAS
Mailing Address 1: 111 8TH AVENUE SUITE 1501
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10011
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2122209945

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported

401 WEST 14TH STREET FEE LLC (Continued) **1010328183**

seq:	Not reported
Year:	2018
Trans1 State ID:	NJD986607380
Trans2 State ID:	Not reported
Generator Ship Date:	11/08/2006
Trans1 Recv Date:	11/08/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/15/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000141937
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	000390046JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	320
Units:	P - Pounds
Number of Containers:	8
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

S342 **401 WEST 14TH STREET LLC** **PA MANIFEST** **S108850110**
SSW **401 WEST 14TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10014**
0.099 mi.
522 ft. **Site 5 of 18 in cluster S**

Relative: **Higher**

Actual: **15 ft.**

Manifest Details:

Year:	2006
Manifest Number:	000390046JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000141937

401 WEST 14TH STREET LLC (Continued) **S108850110**

Generator Date:	11/08/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	PAD085690592
TSD Date:	Not reported
TSD Facility Name:	REPUBLIC ENVIRONMENTAL SYSTEMS OF PA INC
TSD Facility Address:	2869 SANDSTONE DRIVE
TSD Facility City:	HATFIELD
TSD Facility State:	PA
Facility Telephone:	212-220-9945
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	8
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	320
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

V343 **FEEDER MANHOLE #02567** **NY Spills** **S108297436**
WSW **WEST 15 STREET & 10 AVENUE** **N/A**
< 1/8 **MANHATTAN, NY**
0.099 mi.
522 ft. **Site 1 of 8 in cluster V**

Relative: **Lower**

Actual: **10 ft.**

SPILLS:

Name:	FEEDER MANHOLE #02567
Address:	WEST 15 STREET & 10 AVENUE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0611348 / 2007-02-16
Facility ID:	0611348
Facility Type:	ER
DER Facility ID:	325576
Site ID:	375978
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2007-01-12
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2007-01-12
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-01-12
Spill Record Last Update:	2007-02-16

FEEDER MANHOLE #02567 (Continued) **S108297436**

Spiller Name:	ERTS
Spiller Company:	CON EDISON MH #02567
Spiller Address:	WEST 15TH & 10TH AVE
Spiller Company:	001
Contact Name:	ERTS
DEC Memo:	"02/16/07 - See e-docs for Con Ed report detailing cleanup and closure. 204049. see eDocs"
Remarks:	"STAINING: DUE TO A HOLE IN A CABLE: CONED # 204049"

All Materials:

Site ID:	375978
Operable Unit ID:	1133591
Operable Unit:	01
Material ID:	2123407
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

R344 **CON EDISON** **NY MANIFEST** **S117058563**
ENE **347-345 W 21ST ST & 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.100 mi.
526 ft. **Site 3 of 6 in cluster R**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	347-345 W 21ST ST & 9TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004506895
Facility Status:	Not reported
Location Address 1:	347 W 21 ST & 9TH AVE
Code:	BP
Location Address 2:	SB 3793
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004506895
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

CON EDISON (Continued) **S117058563**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/21/2014
Trans1 Recv Date:	04/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004506895
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416688GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

N345 **214765; 184-10 JAMAICA AVENUE** **NY Spills** **S110306737**
NNW **184-10 JAMAICA AVENUE** **N/A**
< 1/8 **NEW YORK, NY**
0.100 mi.
526 ft. **Site 20 of 25 in cluster N**

Relative:
Lower

Actual:
11 ft.

SPILLS:

Name:	214765; 184-10 JAMAICA AVENUE
Address:	184-10 JAMAICA AVENUE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0814631 / 2010-07-08
Facility ID:	0814631
Facility Type:	ER
DER Facility ID:	386328
Site ID:	432367
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	4101
Spill Date:	2008-12-02
Investigator:	dmpokrzy
Referred To:	Not reported
Reported to Dept:	2008-12-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2010-04-16
Spill Record Last Update:	2010-07-08
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	5030 BROADWAY
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	"07/08/2010 See eDocs for Con Ed report detailing cleanup and closure DMP"
Remarks:	""

All Materials:

Site ID:	432367
Operable Unit ID:	1183428
Operable Unit:	01
Material ID:	2177616
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

T346 **CONSOLIDATED EDISON** **NY MANIFEST** **S110823776**
SE **330 WEST 17 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.101 mi.
531 ft. **Site 3 of 20 in cluster T**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	330 WEST 17 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004227041
Facility Status:	Not reported
Location Address 1:	330 WEST 17 ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004227041
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/06/2011
Trans1 Recv Date:	02/06/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/08/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004227041
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007660072JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CONSOLIDATED EDISON (Continued) **S110823776**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

T347 **CON EDISON** **NY MANIFEST** **S118463851**
SE **OPP 330 W 17TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.101 mi.
531 ft. **Site 4 of 20 in cluster T**

Relative: **Higher**
Actual: **18 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	OPP 330 W 17TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004857983
Facility Status:	Not reported
Location Address 1:	OPP 330 W 17TH ST
Code:	BP
Location Address 2:	SB 3013
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004857983
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S118463851**

Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/2015
Trans1 Recv Date:	10/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004857983
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014087633JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

T348 **CON EDISON SERVICE BOX: 3021** **RCRA NonGen / NLR** **1014395674**
SE **330 W 17TH ST SB 3021** **NYP004171393**
< 1/8 **NEW YORK, NY 10014**
0.101 mi.
531 ft. **Site 5 of 20 in cluster T**

Relative: **Higher**
Actual: **18 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON SERVICE BOX:	3021
Handler Address:		330 W 17TH ST SB 3021
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004171393
Contact Name:		DAVID DUKE
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		917-559-8971
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 3021 (Continued) **1014395674**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160727
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090608
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601
Handler Name: CON EDISON SERVICE BOX: 3021	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 3021 (Continued) **1014395674**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

T349 **CONSOLIDATED EDISON** **NY MANIFEST** **S109825474**
SE **330 W 17TH ST** **N/A**
< 1/8 **NEW YORK, NY**
0.101 mi.
531 ft. **Site 6 of 20 in cluster T**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	330 W 17TH ST
City,State,Zip:	NEW YORK, NY
Country:	USA
EPA ID:	NYP004171401
Facility Status:	Not reported
Location Address 1:	330 W 17TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004171401
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	CONSOLIDATED EDISON
Mailing Address 1:	NEW YORKLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/08/2009
Trans1 Recv Date:	06/08/2009

CONSOLIDATED EDISON (Continued) **S109825474**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/09/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004171401
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003532080JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	550
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L350 **ROJAS RAFAEL** **EDR Hist Auto** **1021618949**
SSE **331 W 16TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.101 mi.
531 ft. **Site 18 of 18 in cluster L**

Relative: EDR Hist Auto
Higher

Actual:
18 ft.

Year:	Name:	Type:
1985	ROJAS RAFAEL	Gasoline Service Stations
1986	ROJAS RAFAEL	Gasoline Service Stations
1987	ROJAS RAFAEL	Gasoline Service Stations
1988	ROJAS RAFAEL	Gasoline Service Stations
1989	ROJAS RAFAEL	Gasoline Service Stations
1990	ROJAS RAFAEL	Gasoline Service Stations
1991	ROJAS RAFAEL	Gasoline Service Stations
1992	ROJAS RAFAEL	Gasoline Service Stations

ROJAS RAFAEL (Continued) **1021618949**

1993 ROJAS RAFAEL Gasoline Service Stations

T351 **CON EDISON** **NY MANIFEST** **S117067463**
ESE **FO 326 W 18 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.101 mi.
534 ft. **Site 7 of 20 in cluster T**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FO 326 W 18 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004603304
Facility Status:	Not reported
Location Address 1:	FO 326 W 18 ST
Code:	BP
Location Address 2:	SB 3252
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004603304
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/2014
Trans1 Recv Date:	07/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004603304
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504416GBF
Import Indicator:	N
Export Indicator:	N

CON EDISON (Continued) **S117067463**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

W352 **SERVICE BOX #02343** **NY Spills** **S106383129**
SW **427 WEST 14TH ST BTW 9TH/** **N/A**
< 1/8 **MANHATTAN, NY**
0.102 mi.
539 ft. **Site 1 of 17 in cluster W**

Relative: **Lower**
Actual: **12 ft.**

SPILLS:

Name:	SERVICE BOX #02343
Address:	427 WEST 14TH ST BTW 9TH/
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0313020 / 2004-04-27
Facility ID:	0313020
Facility Type:	ER
DER Facility ID:	240129
Site ID:	296736
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	2004-02-25
Investigator:	SKARAKHA
Referred To:	Not reported
Reported to Dept:	2004-02-25
CID:	64
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

SERVICE BOX #02343 (Continued) **S106383129**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-02-25
Spill Record Last Update:	2004-04-27
Spiller Name:	MAUREEN FICHERMAN
Spiller Company:	SERVICE BOX #02343
Spiller Address:	427 WEST 14TH ST BTW 9TH/
Spiller Company:	001
Contact Name:	MAUREEN FICHERMAN
DEC Memo:	"e2mis 152226 2/25/04 Sal Leto #42, Energy Services, reported at 10:42 hrs. that Arlin Sexton from Clean Ventures found at 09:00 hrs. approx. one pint of unknown oil on top of approx. 30 gal water in service box SB02343 located at 427 West 14 Street between 9th & 10th Avenue. The source and cause of this spill is unknown. They were working under Account #F8252. Clean Ventures did a field test of the unknown oil with results of 50 ppm but less than 500 ppm. There was no fire or smoke involved and no sewer or waterway was affected. Samples taken by Con Edison personnel. 2-26-04 cleanup has been completed as of 09:30 on 2/26/2004. No solid waster was removed.. No solid waster was removed. The Vactor truck removed all liquids in the structure. The structure was then double-washed with SLIX degreaser Environemntal tag # 35915 was removed. amd"
Remarks:	"1 pint of unknown petroleum spilled and mixed with approximately 30 gallons of water in service box 02343. "

All Materials:

Site ID:	296736
Operable Unit ID:	878258
Operable Unit:	01
Material ID:	498190
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

W353 **SEVICE BOX 2343** **NY Spills** **S106126657**
SW **427 WEST 14TH ST.** **N/A**
< 1/8 **MANHATTAN, NY**
0.102 mi.
539 ft. **Site 2 of 17 in cluster W**

Relative: **Lower**

Actual: **12 ft.**

SPILLS:

Name:	SEVICE BOX 2343
Address:	427 WEST 14TH ST.
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0308999 / 2003-12-22
Facility ID:	0308999
Facility Type:	ER
DER Facility ID:	112977
Site ID:	131130
DEC Region:	2

SEVICE BOX 2343 (Continued) **S106126657**

Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	2003-11-24
Investigator:	AERODRIG
Referred To:	Not reported
Reported to Dept:	2003-11-24
CID:	428
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-11-24
Spill Record Last Update:	2003-12-22
Spiller Name:	Not reported
Spiller Company:	UNKOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	SCHLAGEL
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RODRIGUEZ e2mis 151252 On 11/24/03 at 09:58 B. Prescod # 53868 I&A Splicer called to report that he found a spill of unknown substance that he believes to be of an oil type. He reports that there is 15 gal. of oil & 15 gal of water. He says that it maybe a type of fuel but it does not smell like a fuel. He tried to diaper it up but was unable he says some came up but there was more there. He found this at 09:55 lacated at F/O 427 W. 14 St. He was there responding to a B ticket of a water leak. The cause and source are unknown at this time. He does not have sample jars or a chain of custody on the truck so he called his supervisor & they will be going over to the location. He was told to take 3 samples pcb.ID, & flashpoint. & mark it priority E. Than call back with the follow up information. He was also instucted to stay on location. 11/24/03 10:48 J. Cumberbatch # 10660 supervisor called to report that there was only 1 pt of oil & that it would be able to be diapered up. He will call back when it is finished. 11/24/03 11:07 J. Cumberbatch # 10660 I&A supervisor called to report that the oil was completly diapered up. The diapers will be disposed of at the W. 28 St. yard in the pcb drum. He says that the cleanup was completed at 11:05. He also states that there is no visible sign of any oil in the structure. 11/24/03 12:23 J. Cumberbatch called back with the spill tag # 18035 & a chain of custody # AA-03059. He will take 3 samples pcb,ID, & flashpoint. 11/24 @ 23:45 Lab Sequence Number: 03-09510-001 Total PCB <1.0 ppm 11/25/03 @08:59 Lab Sequence Number: 03-09510-002 Flash point > 140 deg F 11/26/03 Lab Sequence Number: 03-09511-001 Insufficient amount of sample extracted to perform oil identification. Note: Based on the above lab results of less than 1 ppm PCB and no aroclor and insufficient amount extracted to perform an oil ID, it is apparent that all the oil was cleaned up as detailed above. No source of oil was discovered."
Remarks:	"POSSIBLE 3RD PARTY SPILL/ POSSIBLE GASOLINE CLEAN UP PENDING SAMPLES "

SEVICE BOX 2343 (Continued) **S106126657**

All Materials:

Site ID:	131130
Operable Unit ID:	877616
Operable Unit:	01
Material ID:	498915
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

X354 **CON EDISON** **NY MANIFEST** **S116551566**
South **OP 344 W 15 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.102 mi.
541 ft. **Site 1 of 11 in cluster X**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	OP 344 W 15 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004500740
Facility Status:	Not reported
Location Address 1:	OP 344 W 15 ST
Code:	BP
Location Address 2:	SB2579
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004500740
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported

CON EDISON (Continued) **S116551566**

Generator Ship Date:	04/15/2014
Trans1 Recv Date:	04/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/15/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004500740
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407426GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

N355 **LOT 33,TAXBLOCK 691** **NY E DESIGNATION** **S108076921**
NNW **161 10 AVENUE** **N/A**
< 1/8 **MANHATTAN, NY 10011**
0.103 mi.
543 ft. **Site 21 of 25 in cluster N**

Relative: **Lower**
Actual: **11 ft.**

E DESIGNATION:

Name:	LOT 33,TAXBLOCK 691
Address:	161 10 AVENUE
City,State,Zip:	MANHATTAN, NY 10011
Tax Lot(s):	33
Tax Block:	691
Borough Code:	MN
E-No:	E-142
Effective Date:	6/23/2005

LOT 33,TAXBLOCK 691 (Continued) **S108076921**

Satisfaction Date: Not reported
Ceqr Number: 03DCP069M
Ulurp Number: 050161 ZRM
Zoning Map No: 8b

Description: Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date: Not reported

Description: Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

N356 **DANNY'S PARKING LOT** **NY Spills** **S102560422**
NNW **161-165 10TH AVE** **N/A**
< 1/8 **MANHATTAN, NY**
0.103 mi.
543 ft. **Site 22 of 25 in cluster N**

Relative: **Lower**
Actual: **11 ft.**

SPILLS:
Name: DANNY'S PARKING LOT
Address: 161-165 10TH AVE
City,State,Zip: MANHATTAN, NY
Spill Number/Closed Date: 9614310 / 2004-03-05
Facility ID: 9614310
Facility Type: ER
DER Facility ID: 195657
Site ID: 237550
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: B3
SWIS: 3101
Spill Date: 1997-03-10
Investigator: MMMULQUE
Referred To: Not reported
Reported to Dept: 1997-03-10
CID: 252
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: 1997-03-11
Recommended Penalty: False
UST Trust: True
Remediation Phase: 0
Date Entered In Computer: 1997-03-10
Spill Record Last Update: 2004-03-05
Spiller Name: DAN VITANZA
Spiller Company: DANNY'S PARKING LOT
Spiller Address: 161-165 10TH AVE
Spiller Company: 001
Contact Name: DAN VITANZA
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MULQUEEN 04/18/97 mmm: DEC DID INSPECTION ON 4/11/97 AND OBSERVED GROSSLY CONTAMINATED SOILS BEING STOCKPILED FOR REMOVAL(150 TONS OUT). WASTE OIL TANK HAD LEAK AND ALSO CONTAMINATED PROPERTY. HARDPAN

DANNY'S PARKING LOT (Continued) **S102560422**

CLAY WAS ENCOUNTERED IN BOTTOM OF EXCAVATION AND MAY BE POSSIBLE BARRIER AGAINST ADDITIONAL VERTICAL MIGRATION. NEED TO ASSESS GROUNDWATER CONDTIONS. 3/45/04 TIPPLE SPOKE WITH MULQUEEN, MULQUEEN INSPECTED AREA, NFA"

Remarks: "PROPERTY WAS A GAS STATION PRIOR TO 1978 - TODAY 3 STEEL TANKS HOLDING 4000 GAL EACH HAVE BEEN EXCAVATED FROM PROPERTY - POSS ANOTHER TANK WILL BE EXCAVATED ALSO-TANKS WERE ENCASED IN CONCRETE TESTING FOR SOIL CONTAMINATION WAS POSITIVE-SOIL STOCK PILED "

All Materials:

Site ID:	237550
Operable Unit ID:	1045736
Operable Unit:	01
Material ID:	339411
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

N357 **CON EDISON SERVICE BOX: 43071** **RCRA NonGen / NLR** **1016142973**
NNW **161 10TH AVE** **NY MANIFEST** **NYP004257028**
< 1/8 **NEW YORK, NY 10014**
0.103 mi.
543 ft. **Site 23 of 25 in cluster N**

Relative: **Lower**

Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130320
Handler Name:	CON EDISON SERVICE BOX:	43071
Handler Address:		161 10TH AVE
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004257028
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported

CON EDISON SERVICE BOX: 43071 (Continued) **1016142973**

Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON SERVICE BOX: 43071 (Continued) **1016142973**

Historic Generators:

Receive Date:		20130220
Handler Name:	CON EDISON SERVICE BOX:	43071
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20130320
Handler Name:	CON EDISON SERVICE BOX:	43071
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	161 10TH AVE
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004257028
Facility Status:	Not reported
Location Address 1:	161 10TH AVE
Code:	BP
Location Address 2:	SERV BOX 43071
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004257028

CON EDISON SERVICE BOX: 43071 (Continued) **1016142973**

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/20/2013
Trans1 Recv Date:	02/20/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004257028
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010846481JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON SERVICE BOX: 43071 (Continued) **1016142973**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

V358 **V0600** **RCRA NonGen / NLR** **1007206777**
WSW **81 10TH AVENUE** **NY MANIFEST** **NYP004030193**
< 1/8 **NEW YORK CITY, NY 10011**
0.103 mi.
544 ft. **Site 2 of 8 in cluster V**

Relative: **Lower**
Actual: **10 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20010103
Handler Name:	V0600	
Handler Address:		81 10TH AVENUE
Handler City,State,Zip:		NEW YORK CITY, NY 10011
EPA ID:		NYP004030193
Contact Name:		ANTHONY DRUMMINGS
Contact Address:		CONSOLIDATED EDISON INC.
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		CONSOLIDATED EDISON INC.
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported

V0600 (Continued) **1007206777**

Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20010102
Handler Name: V0600	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010103
Handler Name: V0600	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

V0600 (Continued) **1007206777**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20010101
Handler Name: V0600	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	2211
NAICS Description:	ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION
NAICS Code:	22111
NAICS Description:	ELECTRIC POWER GENERATION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	81 10TH AVENUE
City,State,Zip:	NEW YORK CITY, NY 10011
Country:	USA
EPA ID:	NYP004030193
Facility Status:	Not reported
Location Address 1:	V0600-F/081 10TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004030193
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported

V0600 (Continued) **1007206777**

Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

N359 **LOT 35,TAXBLOCK 691** **NY E DESIGNATION** **S108076927**
NNW **165 10 AVENUE** **N/A**
< 1/8 **MANHATTAN, NY 10011**
0.104 mi.
547 ft. **Site 24 of 25 in cluster N**

Relative: **Lower**
Actual: **11 ft.**

E DESIGNATION:
Name: LOT 35,TAXBLOCK 691
Address: 165 10 AVENUE
City,State,Zip: MANHATTAN, NY 10011
Tax Lot(s): 35
Tax Block: 691
Borough Code: MN
E-No: E-142
Effective Date: 6/23/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP069M
Ulurp Number: 050161 ZRM
Zoning Map No: 8b

Description: Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

Description: Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date: Not reported

N360 **D VITANZA REPAIR & SERVICE** **EDR Hist Auto** **1021996751**
NNW **165 10TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.104 mi.
547 ft. **Site 25 of 25 in cluster N**

Relative: **Lower**
Actual: **11 ft.**

EDR Hist Auto

Year:	Name:	Type:
1994	D VITANZA REPR & SVCE	Gasoline Service Stations
1995	D VITANZA REPR & SVCE	Gasoline Service Stations
1996	D VITANZA REPR & SVCE	Gasoline Service Stations
1997	D VITANZA REPAIR & SERVICE	Gasoline Service Stations
1998	D VITANZA REPAIR & SERVICE	Gasoline Service Stations
1999	D VITANZA REPAIR & SERVICE	Gasoline Service Stations

T361 **CON EDISON** **NY MANIFEST** **S116044067**
SE **F/O 329 W 17TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.105 mi.
553 ft. **Site 8 of 20 in cluster T**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	F/O 329 W 17TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004404562
Facility Status:	Not reported
Location Address 1:	F/O 329 W 17TH ST
Code:	BP
Location Address 2:	SB3013
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004404562
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	12/11/2013
Trans1 Recv Date:	12/11/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/13/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004404562
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002299727GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S116044067**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Y362 **CON EDISON** **NY MANIFEST** **S117058570**
East **326-324 W 20TH ST & 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.105 mi.
553 ft. **Site 1 of 12 in cluster Y**

Relative: **Higher**
Actual: **18 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	326-324 W 20TH ST & 9TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004506960
Facility Status:	Not reported
Location Address 1:	326 W 20 ST & 9TH AVE
Code:	BP
Location Address 2:	SB 3628
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004506960
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S117058570**

Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/21/2014
Trans1 Recv Date:	04/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004506960
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416544GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

S363 **351 WEST 14TH ST** **NY UST** **U004078304**
South **351 WEST 14TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10014**
0.105 mi.
556 ft. **Site 6 of 18 in cluster S**

Relative:
Higher

Actual:
17 ft.

UST:

Name:	351 WEST 14TH ST
Address:	351 WEST 14TH STREET
City,State,Zip:	NEW YORK, NY 10014
Id/Status:	2-605606 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585890.95313
UTM Y:	4509464.17186
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	27473
Affiliation Type:	Facility Owner
Company Name:	CHELSEA/VILLAGE ASSOC LP % KINSEY CO
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	163 WEST 23RD STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 255-3579
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27473
Affiliation Type:	Mail Contact
Company Name:	CHELSEA VILLAGE ASSOC LP
Contact Type:	Not reported
Contact Name:	ROBERT KOSA
Address1:	% KINSEY CO.
Address2:	163 WEST 23RD STREET
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 255-3579
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27473
Affiliation Type:	Facility Operator
Company Name:	351 WEST 14TH ST
Contact Type:	Not reported
Contact Name:	TONY, SUPER
Address1:	Not reported

351 WEST 14TH ST (Continued) **U004078304**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 387-4328
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27473
Affiliation Type:	Emergency Contact
Company Name:	CHELSEA/VILLAGE ASSOC LP % KINSEY CO
Contact Type:	Not reported
Contact Name:	ROBERT KOSA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 255-3579
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	60111
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2500
Install Date:	03/01/2001
Date Tank Closed:	12/01/2001
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None

351 WEST 14TH ST (Continued) **U004078304**

I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I05 - Overfill - Vent Whistle

S364 **351-355 W 14TH ST** **NY Spills** **S104877200**
South **351-355 W 14TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.105 mi.
556 ft. **Site 7 of 18 in cluster S**

Relative: **Higher**
Actual: **17 ft.**

SPILLS:

Name:	351-355 W 14TH ST
Address:	351-355 W 14TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0009297 / 2009-03-12
Facility ID:	0009297
Facility Type:	ER
DER Facility ID:	210515
Site ID:	257095
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2000-11-13
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2000-11-13
CID:	257
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-11-13
Spill Record Last Update:	2009-03-12
Spiller Name:	KINSEY CORP
Spiller Company:	Not reported
Spiller Address:	351-355 W 14TH ST
Spiller Company:	001
Contact Name:	KINSEY CORP
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 11/29/05 - L. Alden - Sent letter seeking information to owner: Chelsea/Village Associates, LLC., c/o Vectra Management Group, 424 W. 33rd St., Suite 540, NY, NY 10001. 12/8/05 - L. Alden - Received reply from Kinsey Corp, owner's agent. Letter included documents regarding replacement of the tank with the hole in the top, but did not indicate if soil was investigated. If there was a hole in the top of the tank, oil could have easily seeped out, contaminating soil. Kinsey info only tells of abandoning the tank and replacing it with an AST. 12/30/05 - L. Alden - Phoned John Calcaterra, of Kinsey. He had no further information. Called Eastmond. Was told I needed to speak with Rene Lewis, but he was on vacation. 4/10/06 - L. Alden - Called Rene Lewis (718-378-3000), but he is again on vacation.

351-355 W 14TH ST (Continued) **S104877200**

Suggested action: Call Lewis again for information. 11/16/06 - Austin - Reassigned to Ketani for followup/review - end 12/5/06 - Raphael Ketani. The site is 351-355 West 14 St., NY, 10011. Block and lot 00738/0008. Phone number is (212) 255-3579. According to the PBS record #2-605606, the owners are Chelsea/Village GE Associates LP c/o Kinsey Corp., 163 W. 23 St., NY, 10011. There was a 2500 gal. tank with #6 oil installed in 3/1/01, but a hole was found in it while a cleaning was being performed by A. L. Eastmond (718) 378-3000. The spill date is 11/13/2000. The tank was removed on 12/1/01 and a 1080 gal. tank was installed in its place with #2 oil. According to the NYC Property Tax database, the owners are Chelsea/Village Associates, LLC. However, Cooper Square Realty, Inc., 6 East 43 St., NY, 10017-4609 is listed as the addressee one page in from the first results web page. The phone numbers to Cooper Square are (212) 634-8900/682-7373. I tried the phone numbers for Cooper Square. I was told that Joe Simson ext. 407 was the property manager, but I could not get through. Also, there was no phone listing in the Manhattan White Pages for Chelsea/Village GE Associates or Chelsea/Village Associates, LLC. I sent out CSLs. 12/6/06 - Raphael Ketani. Mr. Simpson called me back. He said that he works for Cooper Square Realty Inc. He said he will do a records search and send DEC the information we need. 6/22/07 - Raphael Ketani. I tried to reach Mr. Simpson, but could only leave a message. I may have to make a site visit to find out what the situation is. 6/25/07 - Raphael Ketani. Mr. Simpson called to say that he will FAX over the documents DEC needs regarding the tank replacement. He said that, as far as he knew, there was no soil contamination. 10/23/07 - Raphael Ketani. I tried to reach Mr. Simpson, but was told he was no longer with the company. I was connected to Mike Basile (bay-zil) (212) 634-8900, ext. 408. I explained to him that there had been a leaking tank that was replaced and contaminated soil. I told him that DEC needed manifests for the contaminated soil that was removed, possible end point results, and a revision of the PBS database to show that the old tank was removed. He said that he will look into the matter and get back to me. 12/7/07 - Raphael Ketani. I checked the PBS record. The old 2500 gal. tank is listed as removed and the newer 1080 gal. tank is listed as installed. I tried to contact Mr. Basile, but could only leave a message that manifests and end point results were needed. 12/12/07 - Raphael Ketani. I reached Mr. Basile. He said that the property manager is David Lipsik, (212) 634-5445. He transfered me over, but I could only leave a message regarding the manifests and end point results. 12/13/07 - Raphael Ketani. I contacted Mr. Lipsik. He said he didn't have any information regarding the spill and tank removal as Cooper Square wasn't the managing company during 2000. I told him that I needed documentation regarding the soil removal, end point sample results, and an updated PBS. He directed me to Melissa Wilson in the Compliance Division of his company (212) 634-5437. I told Ms. Wilson what DEC needed and she said she will research the records for the building and get back to me. 2/25/08 - Raphael Ketani. I tried to contact Ms. Wilson, but could only leave a message. Ms. Wilson called me back. She said she had left a voice mail on 1/3/08. I told her that we have nothing in our records regarding this. She asked what documents DEC needed. I told her that DEC needed manifests for the tank and removed soil, and soil end point analytical results. She said that she will look in her records and try to find these documents. I told her to let me know one way or the other. She said she will. 2/26/08 - Raphael Ketani. Ben Hawkins

351-355 W 14TH ST (Continued) **S104877200**

of Cooper Square Realty (212) 634-8988 called to say that he is taking over the case from Ms. Wilson. He said he will look for the missing soil manifests and the end point analytical results. I told him that if these documents can't be found, then a new investigation will need to be performed. I told him an investigation plan will have to be written and submitted to DEC for approval. I asked him where the new tank is. He said it's in the same place as the old tank. I told him that the owners of the property, Cooper Square, and the cleanup company will have to work something out. With that, the conversation ended. 3/24/08 - Raphael Ketani. I tried to contact Mr. Hawkins, but could only leave a message. 3/26/08 - Raphael Ketani. I contacted Mr. Hawkins. I asked him why DEC hasn't received an investigation report. He sounded hesitant and said that he didn't know which investigation/remediation company to choose. He said that there were many listed in the phone books. I told him to pick some, tell them that the job entails 6 borings and samples and get some prices to present to the board or the owner of the building. He said he will do this. I warned him that if DEC doesn't hear back that things are moving forward, then we will send a warning letter that legal action can and may be taken. He said that he understood. 8/18/08 - Raphael Ketani. The case is being prepared for transfer due to a case realignment within the unit. The site needs an investigation for contaminated soil and groundwater. Mr. Hawkins has not responded back to me. Therefore, a more strongly worded letter needs to go out explaining that if there is no action by a certain date, then the Department will consider the parties in violation. 3/11/09- A. L.Eastmond and Sons, INC. sent the report dated 2/17/09, The report included the soil results of two samples taken 12/2/08 under the tank from right and left side. The analytical results for the samples collected indicate non detectables levels of VOCs and SVOCs. Spill Closed. "

Remarks: "caller cleaned tank and found a hole in tank - tank is underneath the sidewalk"

All Materials:

Site ID:	257095
Operable Unit ID:	831588
Operable Unit:	01
Material ID:	543252
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

S365 **351 WEST 14TH ST** **NY AST** **U003790769**
South **351 WEST 14TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10014**
0.105 mi.
556 ft. **Site 8 of 18 in cluster S**

Relative:
Higher

Actual:
17 ft.

AST:

Name:	351 WEST 14TH ST
Address:	351 WEST 14TH STREET
City,State,Zip:	NEW YORK, NY 10014
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-605606
Program Type:	PBS
UTM X:	585890.95313
UTM Y:	4509464.17186
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	27473
Affiliation Type:	Facility Owner
Company Name:	CHELSEA/VILLAGE ASSOC LP % KINSEY CO
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	163 WEST 23RD STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 255-3579
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27473
Affiliation Type:	Mail Contact
Company Name:	CHELSEA VILLAGE ASSOC LP
Contact Type:	Not reported
Contact Name:	ROBERT KOSA
Address1:	% KINSEY CO.
Address2:	163 WEST 23RD STREET
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 255-3579
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27473
Affiliation Type:	Facility Operator
Company Name:	351 WEST 14TH ST
Contact Type:	Not reported
Contact Name:	TONY, SUPER

351 WEST 14TH ST (Continued) **U003790769**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 387-4328
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27473
Affiliation Type:	Emergency Contact
Company Name:	CHELSEA/VILLAGE ASSOC LP % KINSEY CO
Contact Type:	Not reported
Contact Name:	ROBERT KOSA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 255-3579
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	002
Tank Id:	60112
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	C01 - Pipe Location - Aboveground
	G05 - Tank Secondary Containment - Synthetic Liner
	I04 - Overfill - Product Level Gauge (A/G)
	H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
	L09 - Piping Leak Detection - Exempt Suction Piping
	J02 - Dispenser - Suction Dispenser
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	F01 - Pipe External Protection - Painted/Asphalt Coating
	G99 - Tank Secondary Containment - Other
	B05 - Tank External Protection - Jacketed
	I05 - Overfill - Vent Whistle
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/2001

351 WEST 14TH ST (Continued) **U003790769**

Capacity Gallons:	1080
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/04/2021
Register:	True
Modified By:	KXLIU
Last Modified:	07/13/2021
Material Name:	#2 fuel oil (on-site consumption)

Z366 **KAMCO SUPPLY CORP.** **NY UST** **U004189556**
NW **501 WEST 19TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.106 mi.
561 ft. **Site 1 of 13 in cluster Z**

Relative:
Lower

Actual:
10 ft.

UST:

Name:	KAMCO SUPPLY CORP.
Address:	501 WEST 19TH STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-610897 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583877.98279
UTM Y:	4510981.82021
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	402108
Affiliation Type:	Facility Owner
Company Name:	TENTH AVENUE REALTY ASSOCIATES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	362 KINGSLAND AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 391-5300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-02-02

Site Id:	402108
Affiliation Type:	Mail Contact
Company Name:	MENDON LEASING CORP.
Contact Type:	Not reported
Contact Name:	ROGER PALAZZO
Address1:	362 KINGSLAND AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001

KAMCO SUPPLY CORP. (Continued) **U004189556**

Phone: (718) 391-5300
EMail: ROGER@MENDONLEASING.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-11-01

Site Id: 402108
Affiliation Type: Facility Operator
Company Name: KAMCO SUPPLY CORP.
Contact Type: Not reported
Contact Name: CESAR CHAVEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 378-2140
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-11-01

Site Id: 402108
Affiliation Type: Emergency Contact
Company Name: TENTH AVENUE REALTY ASSOCIATES
Contact Type: Not reported
Contact Name: PETE DOMANTE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 255-0120
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 2008-08-01

Tank Info:

Tank Number: 009
Tank ID: 242674
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 12/01/1994
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported

KAMCO SUPPLY CORP. (Continued) **U004189556**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Number: 010
Tank ID: 242675
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 12/01/1994
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Z367 **FORMER BUILDING SUPPLY/FUTURE RESIDENTIAL** **NY Spills** **S101340991**
NW **501-513 WEST 19TH STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.106 mi.
561 ft. **Site 2 of 13 in cluster Z**

Relative: **Lower**

Actual: **10 ft.**

SPILLS:

Name:	FORMER BUILDING SUPPLY/FUTURE RESIDENTIAL
Address:	501-513 WEST 19TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9406402 / 2016-04-05
Facility ID:	9406402
Facility Type:	ER
DER Facility ID:	141173
Site ID:	167544
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C1
SWIS:	3101
Spill Date:	1994-08-10
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	1994-08-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1994-10-20
Spill Record Last Update:	2016-04-05
Spiller Name:	Not reported
Spiller Company:	BROADWAY BLDG MATERIALS
Spiller Address:	501-513 W. 19TH STREET
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"DPrior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 4/12/04-Vought-Spill transferred from Sullivan to Rommel as per Rommel. letter to be sent Previous note by JBMCCULL of C.O. Spill transferred back to R-2 3/7/08 - Austin - Assigned to Ketani for further investigation - end 7/10/08 - Raphael Ketani. There is no paper file. The spill happened on 8/10/94. They stuck a probe to 9' and found contaminated soil. The contaminant is #2 oil or diesel. They were planning to pull the tanks and remove the contaminated soil. The address is 501-513 W. 19 Street, Manhattan. I could not find a PBS case no matter which address, or which alternate address I used. I checked Property Shark for the alternate addresses. 513 W. 19 Street has an alternate address of 511 W. 19 Street, and block and lot 691/25. 501 W. 19 Street has alternate addresses of 153 10th Avenue, 501-505 W. 19 Street, and 153-159 10th Avenue. Block and lot are 691/29. In the NYC Property Tax listings, the owner of these two parcels is Tenth Avenue Realty Associates, LP, 362 Kingsland Avenue, Brklyn, 11222-1905. I sent a CSL to Tenth Avenue Realty Associates. 7/14/08 - Raphael Ketani. I received a call today from Ron Tramposch of Core Environmental (718) 762-0544. He said he represents his

FORMER BUILDING SUPPLY/FUTURE RESIDENTIAL (Continued) **S101340991**

client, 10th Avenue Realty. He said they gave him a the CSL letter. He explained that the property was bought in May 1995 from Broadway Building Materials. The site was changed from a building materials store to a truck servicing business (Mendon Trucking). During August 2006, they received an offer to sell the property. It consists of 3 lots, each of which fronts on 10th Avenue. Core did a Phase I. During September 2007, Core was asked to do a Phase II. This was when the two 550 diesel tanks were discovered. The NYC DOB records showed the 2 tanks. They were installed in 1940 and removed in 1994. The primary address is 153 10th Avenue. The soil and groundwater samples show contamination. There is also contamination from the MGP site across the street - 8200 ppb of 2-methyl naphthalene. There will be condos built on the site. There is an E-designation, but the project has not moved through the NYC DEP offices, yet. I told him that the tanks have to be registered and that the DEC needs copies of a plan showing the installation of a vapor barrier. He said both of these items will be taken care of. I told him that DEC can't close its spill case until these things are done. He said he understood. Lastly, I told him that DEC will review the Phase I and Phase II, and that we may require additional investigative work. 7/16/08 - Raphael Ketani. Yesterday, I received the Phase I and Phase II for the site. The work and reports were put together and submitted by CORE Environmental. I began my review of the reports. The Phase I stated that the proposed site remedy will be: excavation to 13' below grade for construction; installation of a containment wall; installation of vapor barrier below foundation and an active venting system; site management plan to address residual contamination; institutional controls in the form of an environmental easement. The Phase I also stated that there is an adjoining site to the north that had leaking gas tanks, an adjoining site to the southwest that had a leaking diesel tank, and a site to the southwest that was an MGP factory. There are 8 active ASTs on the site for storing various oil and waste oil products, and two 550 gal. USTs. An oil water separator is below ground. Groundwater is believed to be 7' to 9' below the surface. The Phase II had the soil and groundwater analytical results. Boring SB-10 was the only soil sample with elevated results. Ethylbenzene had 5600 ppb (limit 5500 ppb) and n-propylbenzene had 4800 ppb (limit 3700 ppb). There were 4 other VOC analytes with hits in the thousands of ppbs, but they didn't exceed TAGM. All of the other borings were completely non-detect for all of the VOCs. For the SVOCs, almost all of the analytes were non-detect in soil samples. SB-6 had 6 TAGM exceedences, but these were benzo series analytes and the hits were in the low thousands of ppbs. No hits for VOCs and SVOCs were detected in the groundwater sample from MW-3. However, MW-1 had 6 VOC hits from 53 ppb to 180 ppb, and 3 SVOC hits from 1100 ppb to 8200 ppb. MW-1 is near the fuel USTs and the fuel pump. With the exception of the 3 SVOC hits, no other SVOC analytes were detected. These SVOC analytes (2-methynaphthalene, fluorene, and phenanthrene) can all come from the MGP process. The former MGP site and its gas tanks were very near the site to the west and south. I finished my review and sent an approval letter for the Phase I and Phase II. I also stated in the letter that they should collect as much of the groundwater as possible and take another water sample to check on the level of contamination. Lastly, I told them that the two USTs and the waste oil tanks need to be registered, and that DEC needs something in writing confirming that a vapor barrier will be installed. The area the site is in was heavily industrialized. The low level VOC

FORMER BUILDING SUPPLY/FUTURE RESIDENTIAL (Continued) **S101340991**

contamination probably originated from the USTs and/or the fuel pump and associated lines. I spoke to Mr. Tramposch (718) 762-0544 and told him about the letter that will be sent to Tenth Avenue Realty Associates, regarding the Phase I and Phase II and the analytical results. I mentioned that the letter will contain a request to do groundwater collection, the taking of another groundwater sample at MW-1 to confirm the contamination levels, submission of a PBS registration form for all of the USTs and waste oil tanks, and submission of a document stating that a vapor barrier will be installed. The contact person at NYC DEP is: Angela Licita, Permitting, NYC DEP, 59-17 Junction Blvd., 10th Floor, Elmhurst, NY, 11373. 7/22/08 - Raphael Ketani. Mr. Tramposch called regarding the 7/16/08 letter I had sent. The main issue was the installation of a vapor barrier. He said that the owner of the property doesn't have a developer on board, or in mind for the property. Development of the site for a condominium building is years away. I told him that the Spills Unit deals with short term cases, and can not wait several years for the developer to produce an architectural plan showing a vapor barrier. I reminded Mr. Tramposch that the DEC is requiring groundwater extraction, water resampling one month from the extraction date, along with a plan showing the vapor barrier. I told him that DEC is concerned with the public safety and that NYC DEP will also require the vapor barrier as this will be a residential building. He said he understood. I told him that a possible solution is for DEC to issue an NFA letter when the contaminated groundwater is gone, or present at much lower levels near TAGM, and have the vapor barrier listed on the letter as a requirement of construction. Mr. Tramposch said this would be a reasonable solution. 8/18/08 - Raphael Ketani. The case is being prepared for transfer due to a case realignment within the unit. A report needs to be submitted containing the volume of water collected and the analytical results from a groundwater sample taken one month later. All of the tanks that were or still are present on site need to be registered. The case manager may want to request specs for the vapor barrier. 10/27/11 - Austin - Spill Transferred from Ahmed to Vought - end 11/16/2011- Intern Wade- Began file review of Spill # 9406402: Broadway Building Materials Address:501-513 W 19th St Manhattan, NY 153 10 Ave Owner: Tenth Avenue Realty Associates, L.P. 362 Kingsland Avenue, Brooklyn, New York 11215 Alternate Addresses: 501 505 WEST 19 St 153 159 Tenth AVENUE Tax lot 25, 27, & 29. Zip 10011 PBS Search: 2-610897- KAMCO SUPPLY CORP.- 501 WEST 19TH STREET- received: 08/08- Expiration: 12/01/2010. : 275 AST Installed 12/01/1995-REMOVED-04/30/2009 [Waste Oil/Used Oil] 275 AST Installed 12/01/1995-REMOVED-04/30/2009 [Waste Oil/Used Oil] Spill search: 9907805- Old Gas station 10th Ave & 20th ST. (09/28/1999) Status: Closed- Odors while digging up gas station tank 1103935- Oil in Soil- 10th Ave & W 18th ST. (07/09/2011) Status: Open Con Ed- Petroleum in soil. 9210231-getty- 152 10th Ave.(12/03/1992) Status: Closed- 92 tank test failure 8903509- 152-156 Tenth Ave-Potential spiller Getty gas station?-(07/07/1989) Status: Closed-Odor w/ staining on concrete &asphalt. 9902463-WEST 18TH ST & TENTH AVE-(60/03/1999) Status: Closed- 06- Contaminated soil found while digging for a natural gas main. Site is located in/near VCP # V-00530 (W 16th to 20th Sts) Complete file review by Intern Wade: Caller Remarks: Stuck probe in ground found contaminated soil @ 9 ft. Will pull tanks out-Once they can see all contaminated soil they can remove it stuck pile Spill occurred 08/10/1994 Spill Material- Diesel Oil & Haz waste material

FORMER BUILDING SUPPLY/FUTURE RESIDENTIAL (Continued) **S101340991**

Spill fact sheet- 08/10/1994 Report sent from L. Evans (ORE Group ph: 212-343-5139) to M. Tibbe-11/01/1994. (Document is Difficult to read, cannot tell what location the sample is from). GW analyticals Tw-05-Benzene [140 ug/L] , Toluene [6.5 ug/ L], Xylene [49.5 ug/L]. Tw-09-Toluene [2.5 ug/L]. Closure Letter from M. Tibbe (DEC) to Ms. L Evans (Bank Leumi Trust Company of NY)- 11/09/1994- Upon review of closure report from Advanced Cleanup Technologies investigation shows no significant contamination of soil or GW. remaining contaminations should biodegrade naturally . The spill number referenced above will be closed as of this date . PERSONAL NOTE: No information in file as to why or when this spill number remains open or was reopened. As per Spill Remarks, spill assigned to DEC Rommel prior to 9/04 and was transferred to her from DEC Sullivan on 4/12/04. Spill was then managed in DEC Central Office by DEC McCull and then transferred back to Region 2 in 3/08. Letter from Edward Jones (Erdman, Anthony and Associates, Inc ph: 716-325-1866)-01/17/1995- request for fact sheet & any test results regarding spill # 9406402. Letter from R. Ketani (DEC) to Tenth Ave Realty Associates, LP (362 Kingsland Ave Brooklyn, NY 1222-1905)-07/11/2008- DEC requires documentation (regarding the 08/10/1994 spill) verifying that the contamination was removed & the fuel sys was repaired. Required PBS registration for existing & removed tanks. Tenth Ave Realty Associates is RP. Letter from R. Tramposch (CORE)-07/14/2008- CORE is providing Environmental consultation to the property owner. Core Phase 1 showed historical records of two 550 gal underground diesel tanks. They were removed in 1994, Broadway buildings supplies. Results indicate low levels of petroleum contamination Phase 1 ESA-12/29/2006- DEC received 07/15/2008- UST s containing gasoline may be located on lot 29 near bay doors along West 19th. Oil/water separator is located on site. Site north of lot 29 was a gas station from 1950 to 2000. Spills on W 515 18th . MGP s south & West of site. 1 block south of site was the retort house, coal storage, tar separators, scrubbers, tanks, wells, & underground piping. 18th St Gas Works Site may have contaminated the subject site . (18th Gas Works Site [Consolidated Gas Company](200 ft), Danny s parking lot/ old gas station 501 19th St, 515 W. 18th St. Spill). Recommend Phase II. Current site is being used by a Mendon Truck Leasing. Building in single story, 9600 sq ft w/ a mezzanine area. Build constructed in 1945. Has 6 AST s for oils & fluids (not fuels). 507 W 19th (Lot 27) Pino Lyptol Chemical Company. Chelsea area of Manhattan 300 ft from Hudson. 12 above sea level. GW believed to be SW To NE. Current property petroleum storage tanks include: (3) 55 gallon oil & anti-freeze drums & (2) 20 gallon grease drums. (4) empty 55 gal drums. (2) empty 275 gal UST s. Historical maps indicate (2) 550 gal gasoline tanks. (6) 275 gal ASTs (oil & fluid ,not fuel). Found 3 monitoring wells on adjacent property. - Con Edison Remedial Action work plan-2006- W. 18th St MGP Voluntary Cleanup program (VCP) # V-005302. Project loc 535 W 19th ST. Proposed remedy excavation, containment wall, use restrictions. From the Phase I relatively little contamination in and immediately around the existing holder . staining found around the drums (8 drums). staining found on site was minor . Letter from R. Ketani (DEC) to Tenth Ave Realty Associates-07/17/2008- Dec reviewed the phase I ESA& Phase II ESA (produced by CORE Env) cc: Ronald Tramposch, CORE Env. Request for GW collection @ MW-1 to reduce contaminant conc. Request for PBS reg. Request: architectural/ eng. Plan for the apartment building showing position of the vapor barrier & the venting system. Email from R. Tramposch (CORE Env. ; 46-11 54th

FORMER BUILDING SUPPLY/FUTURE RESIDENTIAL (Continued) **S101340991**

Ave; Maspeth, NY 11378 Ph: 917-804-8717) to H. Amed (DEC)-07/02/2009-requesting a status update on sp# 9406402 (based on submitted Doc). Post it: Tramosch (Probably R. Tramposch) # 917-804-8710 11/17/2011-Intern Wade-continued file review Limited Phase II Env. Site investigation (ESI) (CORE)-09/24/2007- DEC rec 07/15/2008- 10 soil borings (SB). Monitoring wells (MW) installed @ 3 SB locations. 2 wells were sampled. (MW-2 did not produce enough water) CORE recommends excavation of abandoned UST s and excavation of contaminated soil, followed by end point samples. (Estimated cost $69,000) SBs done w/ Earth probe 200 (direct push). Soil cores screened w/ PID. SB 4 pushed to 20ft to investigate for potential coal tar waste, none was found. SB was advanced to silty clay area reported to be under the site. GW is 7 to 8 ft. GW is unfiltered. Highest PID reading were selected for analysis. Bedrock ~ 75 ft below Manhattan (generally). Contaminant values: SB 10- Ethyl Benzene (5500 ppb), npropylbenzene (4800 ppb). SB 6-Benzo(a)anthracene (2000 ppb), Benzo(a)pryene (1200 ppb), Benzo(b)flouranthene (1000 ppb), Benzo(k)flouranthene (1100 ppb), Chrysene (1900 ppb), Dibenzo(a,h)anthracene (310 ppb). MW1- Benzene (53 ppb), Isopropylbenzene (73 ppb), n-Butylbenzene (140 ppb), n-Propylbensene (180 ppb), sec-Butlbenzene (120 ppb), MTBE (120 ppb), 2-Methylnapthalene (8200 ppb), Fluorene (1100 ppb), Phenanthrene (1900 ppb). Barium (1820 ppb), Chromium (182 ppb), Lead (4140 ppb), Selenium (18 ppb), Mercury (2 ppb). MW-3- Selenium (27 ppb). 11/23/2011- Intern Wade-continued file review Email from Ron Tramposch to H Ahmed -07/02/2009-requesting the status of the review VCP # V-00530- 516 W 19th- no methylnapthalene of note. 524 W 19th Gasser Lot 29 was owned by MGP (1848) 11/30/11-Vought-Reviewed and approved above notes by Intern Wade. Teleconference with R. Tramposch. (Core office: 718-786-4730, Cell: 917-804-8717). The property is being proposed for sale. It will be residential w/ about 5 stories and a garage. Langan has been hired to conduct the do the environmental due diligence. Langan should be submitting a Phase II sometime in the future. Tramposch will call the owner today & email Vought detailing the most current information on the site. - The Site owner also possesses another site under Semantic Realty. Spill # 9612012. Address 511 West 18th st.Owner admits to a spill regarding a leaky tank. However, will not pay the full cost of clean-up due to Con Edison (MGP) tanks located under the site. Case was sent to Albany under the VCP- 000530, however it was referred back to Spills division. Owner owns a 3rd site called Brooklyn Operating facility ~ which is currently managed under the Petroleum & Remediation division. Dec notes on Sp# 9612012 shows owner s name to be Mendy Taffel [Ph: 718-391-5300, Fax: 561-995-7578, email: mendy@mendonleasing.com] Semantic Realty, Inc 362 Kingsland Ave Brooklyn NY 1222-1905 11/30/2011-Intern Wade-Vought received email from Tramposch. Tramposch was unable to contact the owner & will follow up 12/01/2011 to determine when he will receive the Langan report. Tramposch mentioned Spill # 9612012 & attached Core s Letter Analysis of Sub& Information was forwarded to K. Patel [DEC] for follow up. Intern Wade-Vought replied to email, indicating that he spoke w/ K. Patel regarding Sp # 9612012. He also asked to remain updated on the langan report, sales of the site, & on its development. Intern Wade-Tramposch emails Vought- Owners rep indicated that the PBS [regarding AST removal] was filed on 10/10. Intern Wade-Vought replied to email asking for a copy of the PBS submission. 12/21/2011-Intern Wade- Tramposch emailed Vought on

FORMER BUILDING SUPPLY/FUTURE RESIDENTIAL (Continued) **S101340991**

12/06/2011 w/ a PBS registration from the owner. PBS Does not look right R.T. He requests a copy of DEC s PBS facility report. Intern Wade- Vought emailed Tramposch DEC s copy of PBS for the site 12/22/2011-Intern Wade- Email from Tramposch to Vought attaching a copy of the PBS registration form including the 2-550 s. The original was placed in the mail. There are no AST s on-site. Regarding the Langan report. I am told it will be available shortly.
1/10/12-Vought-Sent email request to Tramposch for status of Langan report and Tramposch replied that he left message to owner for report. 2/9/12-Vought-Received email from Tramposch that Good morning Jeffery. Last month we discussed the Langan investigation report on this property. After discussion with the owner and purchaser, it was agreed upon that Langan would contact you directly regarding the investigation results. I am attaching the Langan contact information. I assume he will be in contact with you shortly.Sorry for this delay, but it appears that it was unavoidable because of the sale of the property. 2/10/12-Vought-Received call from and spoke to Steve Ciambruschini (Langan Ph:201-398-4549 email:sciambruschini@langan.com and Chris McMahon (cmcmahon@langan.com). They will contact Tramposch and also sumbit Langan report to Vought for review.
8/8/12-Vought-Received email from NYCOER Chawla on 8/1/12 that Randy and Jeff: 501 West 19th Street property with an old Spill #94-06402 is in the process of getting permits for redevelopment. They have E hazmat and intend to enter City BCP. Langan has proposed attached sampling locations. We briefly discussed this Spill during our last meeting. Please let me know who is DEC PM on this project so that we can coordinate and move this project along. Thanks, Shaminder . Teleconference requested by NYCOER Chawla for 1pm today. Vought sent email with spill notes, requirements as per 2/10/12 from above and a copy of summary site plans to Chawla, Langan(Ciambrushini) and Tramposch. Vought reviewed boring proposal from OER Chawla dated 8/1/12 and site plan does not include samples on proposed summary sample collection table and unclear as to whether groundwater samples will be collected downgradient of MW1. Proposal also did not include requirements above dated 2/10/12. Vought added site plans to e-docs. Note also that plan includes collection of soil, soil vapor and groundwater samples and no collection methodologies included. Vought spoke to OER Bertini and requested copy of sampling methodology and he noted that OER had requested same from Langan but did not receive it. Vought noted that DEC could not approve proposal without written sampling methodology. Vought also noted to OER Bertini that NYSDOH review of soil vapor sampling procedure once received may also be required and may also take time. 8/8/12-Vought-Teleconference with OER Chawla and OER Maurizio Bertini (Ph:212-788-3922 email:mbertini@dep.nyc.gov) and they noted that site was currently in E-designation program and that they were considering NYC LBCP Program. Chawla noted that OER had received a Phase II Report that noted LNAPL by MW1 and that future use of the site included excavation at some areas below groundwater and development with a ten-story residential structure. Vought noted that DEC would also approve immediate remedial excavation as part of development (including endpoints for investigation) to facilitate timely investigation and OER Chawla noted that OER was seeking installation of soil borings first. OER Chawla noted that they had not received any finalized development plans to date. Vought discussed outstanding DEC requirements and emails/discussions with Tramposch and Langan in 2/12. OER Chawla requested that Vought send DEC requirements to him

FORMER BUILDING SUPPLY/FUTURE RESIDENTIAL (Continued) **S101340991**

and not directly to owner so as to have a unified command with respect to further investigation/remediationn. Received and reviewed following report: Limited Phase II Environmental Investigation Report (Langan)-November 2011. Added Report to E-docs. Contact for Langan is Chris McMahon (Ph:201-794-6900). Report prepared for: HFZ Capital Group 600 Madison Avenue 17th Floor New York, NY 10022 Site E designated for hazardous materials, noise and air quality. The scope of work was not intended to meet the requirements for hazardous material investigations as defined by the E-designation program or brownfields program or to delineate sol and groundwater contamination... but was completed solely to identify all areas of contamination that may impact the proposed site redevelopment . Lot 29 is currently owned by CTR Realty Corporation. Previous commerical businesses that were identified at the site include Tuxedo Dairy, the Express Depot, meat companies, metal working facilities, trucking companies and building supply companies. Groundwater at 5-9'bg as perched water on a silt layer from 13-17'bg. Groundwater flow to the west as per Core Investigation in 2007. Phase II included six soil borings, collection of four soil samples and installation of two monitoring wells. GPR survey use was limited to due rebar in floor. Groundwater in borings at 5-10'bg. Soil sample from ELB-1 collected at highest PID reading and ELB3 sample collected from one foot interval directly above water table and the rest of the samples were collected from the base of the boring. Borings logs show strong petroleum odor at 7.5'bg(ELB1). LNAPL noted in MW1 but thickness of product not measured. Soil and groundwater analyticals show: 194ppb benzene(ELB1 9-9.5'bg). PERSONAL NOTE: Many of these groundwater samples collected within zone of tidal fluctuation and hence cannot be used for soil source characterization. Groundwater analyticals show no TOGS 1.1.1 Groundwater exceedences (however sample not collected at ELB1 due to LNAPL). Report concludes that a small area of impacted soil may be present in the area of the abandoned USTs and report recommends removal of USTs along with any impacted soils and possible removal of oil/water separator as part of development, installation of groundwater monitoring wells. 8/9/12-Vought-Sent email to OER Chawla with note that DEC cannot approve 8/1/12 proposal from Langan until a detailed sampling methodology is submitted for soil, soil vapor and groundwater and that complete proposal may also needed to be reviewed by NYSDOH. Vought also copied DEC Richard Dana as site also may be located in VCP V00530. Vought noted to OER to follow up with Vought if they need letter directly from DEC to Responsible Party. Vought attached summary site plans and copy of spill report as FYI for DEC Dana as well as DEC requirements including: 1)Submission of sampling methodology for collection of soil vapor, soil and groundwater sampling 2)possible NYSDOH review of soil vapor sampling methodology. 3)installation of soil boring on sidewalk of West 19th Street to delineate groundwater contamination to the south as well 4) Collection of groundwater sample down gradient from two 550-gallon former USTs 5) Referral of data, Methylnapthalene 8200 ppb, to V00530 under DEC PM Richard Dana pending new GW analyticals 6) Future and current use of site including possible installation of vapor barrier/SSDS and review of these plans by NYSDOH as site will be developed residential 10-story building with garage 7)Submittal of PBS registration based on two 275 Waste Oil tanks & also based on the total tank capacity of the site exceeding 1,100 gals. 8)Placement of proposed sample summary table locations (MW1 thru MW3) on Proposed Site plan. 9)Collection of

FORMER BUILDING SUPPLY/FUTURE RESIDENTIAL (Continued) **S101340991**

deepest dry soil sample AND highest PID sample at all boring locations and TWO deepest dry samples if no elevated PID readings due to likely water table fluctuation in tidal zone. 10)cc to Langan, OER Chawla and Bertini and DEC Dana. 9/21/12-Vought-Received call from and email inquiry from OER Chawla on status of Review of Phase II. To date file review by Vought: Email from Maurizio Bertini(NYCDEP) to Vought-8/30/12. Bertini noted that he received Work Plan for project and asked if Vought received a copy as well. Email from DEC Dana to Vought-8/30/12. DEC Dana also requested review of Work Plan by Langan. Email from Langan McMahon to Vought-9/5/12. McMahon posted copy of Work Plan on access site and notified Vought. Email from OER Chawla to Vought-9/20/12. Note that he will contact Vought at 11am to discuss Work Plan with attached copy of Phase II Subsurface Investigation Work Plan by Langan dated 8/28/12. Vought added Work Plan to e-docs. 9/21/12-Vought-Forwarded copy of Phase II Work Plan dated 8/28/12 to DEC Dana via email for his review as per his request. 9/24/12-Vought-Called and spoke to OER Chawla who noted that he had sent Phase II WOrk Plan to NYCDOH Chris D'Andrea for review and approval. OER Chawla later sent email to Vought from himself to Maureen Little with cc to NYCDOH D'Andrea that Langan Engineer has submitted the attached Phase II Work Plan to further investigate the environmental conditions at the 501-513 West 19th Street (block: 691, lots: 25, 27, 29) in Manhattan. The lots have been designated with Hazardous Materials, Air Quality and Noise E-designation. The site will be redeveloped with two residential building with sub-grade level, except for the section under the HighLine; a tunnel will connect the two subgrade levels. In addition to the HazMat E-designation, there is an open spill at the site. Previous investigations have identified levels of VOCs and SVOCs in both soil and groundwater due to abandoned USTs and fill material. The attached Work Plan proposes additional testing of soil and groundwater and investigation of soil vapor conditions. OER has reviewed the plan and asked for two additional soil borings to be installed in the lot East of the HighLine. The boring will be located one on the NE corner (10th Avenue side) and NW corner (Highline side) of the site. The former will be converted into a temporary groundwater monitoring well and the latter into an soil vapor sampling location. DEC (spill # 9406402) is also involved in review of this work plan. Your prompt review of soil gas investigation is greatly appreciated. Reviewed Phase II Work Plan dated 8/28/12. Site currently used as a building supply warehouse with associated offices and the remaining two lots are used for the storage of building supplies. Historically the site was operated as a dairy, a manufacturing flat, an Express Depot, a parking facility, a truck rental and repair facility, a labor staging area and commercial and residential units . Development to include construction of a residential building with basement that covers entie footprint. Copies of building plans included in Appendix. Formal plans have not been developed to date. Proposed scope of work includes collection of on sub-slab and two soil vapor samples, installation of eight soil borings with collection of two soil samples per boring, installation of five permanent monitoring wells, completion of a Phase II Subsurface Investigation Report and Remedial Action Work Plan. Plan includes soil vapor sampling procedures in accordance with NYSDOH 2006 Guidance. Soil borings will be performed to depth of 20'bg (below expected depth of future foundation with collection of continous samples and analysis of deepest dry or highest PID and second sample will be from the base of the boring to

FORMER BUILDING SUPPLY/FUTURE RESIDENTIAL (Continued) **S101340991**

correspond with proposed foundation elements. Plan includes details for the collection of soil, groundwater and soil vapor samples. Field activities to begin within two weeks of approval of Work Plan. Vought spoke with NYSDOH Mike Hughes who noted that as NYCDOH D'Andrea was reviewing Work Plan, that NYSDOH review was not needed. Vought sent email to OER Chawla with cc to DEC Dana and NYCDOH D'Andrea that REGIONAL approval of work plan was provided however Vought must receive comments from DEC Dana and NYCDOH D'Andrea on Work Plan before DEC can finalize approval. Vought also sent note that PBS registration still outstanding. 9/27/12-Vought-Received email from NYCDOH Andrea that Maureen received the Phase II workplan from Shaminder. She reviewed the workplan and had the following thoughts: The number of SV samples seems adequate for characterization, based on the information provided. Is there a reason no samples were collected in the back part of the lot bordering 10th Avenue? I am not sure how they are distinguishing between soil gas and soil vapor . Is the soil gas sample the one that is being taken sub-slab? It did not seem as though the sampling otherwise differed. This is the only information that we have reviewed regarding this project. If the project comes though the Brownfield program we will review all analytical results as well as other project related information. Chris. 3/6/13-Vought-Received call from and spoke to Langan (McMahon) and he will submit will have development plans, Phase I, OER RIR and OER RAP. Vought received plans via two CDs. 3/7/13-Vought-Received call from and spoke to Langan (McMahon) who noted that he needs Notice to Proceed from NYCOER who are witholding due to outstaning DEC requirements and open spill and he does not received Notice then there will be high expense with contractors lined to begin foundation emplacement. McMahon noted that proposed development includes excavation of entire site below the water table with dewatering and installation of a moisture/vapor barrier and no SSDS possible as foundation will be below water table. Site visit scheduled by Vought to inspect site. Received email from DEP Maurizio Bertini with cc to OER Cole that am the PM for the above site, which has an E-designation. It was once a VCP with OER, but the developer has chosen to remain in the E. We discussed the work plan sometime ago, either during the summer or fall. I believe Chris from Langan contacted you about the spill on this site and he should have sent you all documents, including the most recent RIR and RAP. The remedial actions described in the RAP focus on the development and as a consequence on the spill. I would like to discuss this project soon so we can sign off. I think we should segregate any DEC requirements in a combined RAP if that works for you. 3/12/13-Vought-Received additional call from McMahon regarding file review and site visit by Vought. 3/19/13-Vought-File review by Vought including review of recently received RIR and RAP from Langan. Vought called and spoke to OER Chawla who noted that site was not in LBCP and was in OER E-designation unit. Remedial Investigation Report (Langan- Chris McMahon)-2/6/13. Report prepared for: HFZ Capital Group 600 Madison Avenue 17th Floor New York, NY 10022 Onsite building built in 1945 and two asphalt lots also included in site. Building most recently used as building supply warehouse and two lots used for storage of building supplies. Future use of site will consist of mixed use condominium building that will completely occupy all three lots with a single subgrade level basement and two 10-story towers on either side of the highline with residential apartments. Onsite building will be demolished and new building basement will be occupied by

FORMER BUILDING SUPPLY/FUTURE RESIDENTIAL (Continued) **S101340991**

mechanical rooms, shared tenant amenities and storage. Building will have rear yard constructed above cellar level of building and as such there will be on potential contact with onsite at grade soils . New basement will be built to 10-12'bg and occupy entire site footpring with exception of areas that support foundation for highline with an estimated removal of 14,435 tons of soil and it is anticipated that dewatering will be required for installation of new foundation. Phase I site was formerly used as a dairy in 1904, manufacturing in 1924, parking lot in 1950. HFZ Highline LLC puchased site in March 2012. AOCs include abandoned gasoline/diesel USTs, oil water separator, on-site historic fill, surrounding sites, and additional industrial/commerical usage. Report includes results of installation of nine soil borings, collection of 23 soil samples and installation of six groundwater monitoring wells and four soil vapor probes. Groundwater flow is inferred to be from east to west beneath the site . ...petroleum impacted soils exist in the vicinity of the former USTs... . As per report upgradient wells show low level VOCs attributed with possible gas station that was formerly upgradient from site. Soil vapor analyticals for PCE show mitigation is required for SV3 and ...the source of chlorinated VOCs in soil vapor is attributable to an undocumented off-site release . ...waterproofing to be installed below and along foundation walls as part of proposed building redevelopment will adequately address the potential for soil vapor intrusion into the building. A remote fill port was observed on sidewalk along southern side of building . Petroleum odors noted in ELB11(6.5-10'bg), ELB12(6.5-9.5'bg), ELB13(7-15'bg), ELB14(7.5-10'bg). Three soil samples collected from each soil boring consisting of: directly beneath building slab (or highest PID), deepest dry and proposed final depth of excavation. Six groundwater samples collected as well for this investigation. Approximately .3 feet of yellowish brown free product in MW1.Site will be excavated to a depth of approximately 14'bg. Soil analyticals show: 8500ppb n-propylbenzene (ELB11 7.5-9.5'bg), 13,000ppb ethylbenzene(ELB12 7.5-9.5'bg), 17,000ppb xylene(ELB12 7.5-9.5'bg), 2000ppb ethylbenzene(ELB13 12-14'bg), 1100ppb xylene(ELB13 12-14'bg), 20,000ppb napthalene(ELB13 12-14'bg), 19,000ppb n-propylbenzene(ELB14 8-10'bg), 30,000ppb napthalene (ELB14 8-10'bg). Groundwater analyticals show: 9ppb benzene(ELB14), 15ppb napthalene(ELB14), 330ppb benzene(ELB13), 41ppb ethylbenzene(ELB13), 26ppb xylene(ELB13), 130ppb napthalene(ELB 13), 44ppb benzene(ELB12), 160ppb ethylbenzene(ELB12), 400ppb xylene(ELB12), 23ppb napthalene(ELB12). Soil vapor analyticals show: 2400ug/m3 PCE(SV3) and 13ug/m3 PCE(SV4). Remedial Action Plan (Langan)-2/26/13. ...a waterproofing/vapor barrier system will be installed below the proposed building... . Proposed collection of seven endpoint soil samples and sidewall samples will not be collected since the excavated areas will extend to property limites and sampling will be conducted within setback areas via the collection of five endpoint samples. It is anticipated that the support of the excavation for the proposed development will be isntalled three feet beyond the property line into the sidewalk and as such it is likely that all impacted materials that are located off-site may not be completely removed . Proposal for 20-mil vapor barrier also included beneath the building and on the outside of the foundation walls. Site also includes CAMP as well for VOCs, dust and odors as well as submission of a Closure Report upon completion of work. Vought called and spoke to Langan (McMahon) and noted that vapor issues may arise from pedestrian

FORMER BUILDING SUPPLY/FUTURE RESIDENTIAL (Continued) **S101340991**

traffic on the Highline above the site during excavation activities. McMahon noted that if issues arose that he would place a monitor above the site on the Highline in addition to a the proposed downwind location. 3/21/13-Vought-Called NYSDOH Hughes to discuss possible necessity of DOH review due to off-site PCE soil vapor plume and installation of proposed 20mil vapor moisture barrier along foundation walls. Vought sent the following email to NYSDOH Hughes and NYCDOH Andrea with cc to Dana, RHWRE, DEC Cozzy, OER Chawla and Bertini and Langan (McMahon) that have recently reviewed a Remedial Action Plan (RAP) and Remedial Investigation Report (RIR) for the above site that includes excavation of the entire site to below groundwater (5-8'bg) with dewatering as part of the development. The contractor is set to begin work by April 1 and as such is looking for an expedited review and approval of the RAP. The site may also be part of a VCP as well (V00530) being managed by Richard Dana in DEC Albany and is also under the E-designation Program in NYCOER. The RIR noted a concentration of 2400ug/m3 PCE in a soil vapor that was attributed to an off-site source and that location is almost center to the remedial excavation. I have attached one of my summary site plans for your review below. Soil and groundwater analyticals across the site were non-detect for PCE and MDLs were appropriate for SCOs'. Prior uses of the site include: storage and shipment of building supplies and automobile storage. No former uses were directly related to the presence of PCE on-site. Proposed development includes installation of a 20-mil vapor/moisture barrier underneath slab and along foundation walls. Question: Does NYCDOH or NYSDOH need to review vapor barrier or moisture barrier specifications in the RAP? Please note that I have also copied Jane O'Connell and Bob Cozzy as I will be discussing the PCE hit in soil vapor and if they feel the need for a P-Site Plume trackdown. I have also copied the environmental consultant (Langan) above as well so that they may remain informed. Thanks gentlemen and to everyone copied above as well for their assistance as always, 3/21/13-Vought-Called McMahon and informed him of draft DEC review letter of RIR and RAP that includes requirements for regular intermittent sampling of dewatering fluids and installation of monitoring well if excavation does removal all contaminated soil under 19th Street sidewalk. Vought also noted that via email sent by Vought above that NYSDOH or NYCDOH may have requirements with respect to vapor barrier which if the case, the review letter will need to be rewritten by Vought. If DOH has no further requirements by DOH then letter will be sent to owner as drafted by Patel. 3/27/13-Vought-Correspondence review to date: Email from Langan (McMahon) to All Parties-3/25/13. All I just spoke with Mike Hughes of the NYSDOH regarding the email that Jeff Vought sent, and he will verify with his engineering department but he strongly believes that the remedial action that is taking place including the removal of soils to a depth below the groundwater table in the area of the PCE hit and the installation of the waterproofing barrier should be sufficient to address any soil vapor issues and that the NYSDOH or NYCDOH will not need to review any of the information formally. He will respond formally either tomorrow or Wednesday. Email from McMahon to All Parties-3/26/13. All please find the attached letter from Grace, stating that the waterproofing membrane that will be used for this project will not be adversely affected by the contaminants at the site. Vought added letter to e-docs and as per letter dated 3/25/13 I have reviewed the following documents for the above referenced project:? Tables 1-6 prepared by Langan

FORMER BUILDING SUPPLY/FUTURE RESIDENTIAL (Continued) **S101340991**

Engineering and Environmental Services dated 12-2012 ? Figures 1-7 prepared by Langan Engineering and Environmental Services dated 1-31-2013 Based on the identified contaminants at the levels reported, the waterproofing or vapor barrier properties of Preprufe 300R/160R or Bituthene 3000/4000 systems and all system accessories will not be adversely affected, provided standard design and application procedures are followed. Email from McMahon to All Parties-3/27/13. Email that Mike we discussed this project on Monday and you had indicated that you would follow-up with an email stating that based on the results of the investigation and the proposed redevelopment activities which will excavate into the groundwater table on 2/3rds of the property and the use of a Grace waterproofing system beneath the entire redevelopment would be sufficient and not require NYSDOH or NYCDOH review. It is my understanding (Jeffrey please correct me if I m wrong) that this email would be sufficient to satisfy Jeffrey s question and would close out this issue with the NYSDEC.Please also find the attached letter from Grace which states that the contamination at the site in soil, soil vapor and groundwater should not have a negative effect on the performance of their waterproofing system. Regards . Email from NYSDOH Hughes to All Parties-3/27/13. Email that In general, the DOH does not have a formal policy to review the specifications of moisture/gas barriers. Our only stipulation is that the barrier is a true impermeable vapor barrier and not just a moisture barrier. If the proposed barrier for this site meets that requirement then DOH has no further comments and concurs with the proposed course of action. 3/27/13-Vought-Finalized RAP review letter and sent to all parties including requirements of regular sampling of dewatering discharge and reinstallation of well MW6 if all contaminated soil under the sidewalk cannot be removed (also in consideration of groundwater contamination levels in this well). 3/28/13-Vought-Received email from DEC Cozzy that since no PCE in GW, no need for plume trackdown. 10/24/13-Vought-Received phone message from McMahon that they located and removed the USTs and noted some impact and plan is to dig close to water to dewater and collect endpoint samples. Vought left message to return call to Vought to confirm below requirements. Vought received call from McMahon and tanks were not adjacent to sidewalk but more into building. The second excavation was performed to just above water table to install cassions, install dewatering system and then continue excavation. One hole noted in one UST but they were encased in concrete and some PID hits underconcrete. He will verify extent of proposed soil excavation to remote fill areas. He noted that no piping was attached to tanks as it may have been removed. 4/1/16-Vought-Received message from McMahon (Ph:973-560-4861)that he want to submit closure report to DEC for review so that NYOER can grant Certificate of Occupancy. Vought returned call to McMahon and left message. 4/5/16-Vought-Received email from Langan (McMahon) that Good Evening Jeff got your voicemail, thanks for getting back to me. The link below is the draft of the Remedial Closure Report that we sent over to the OER about a year ago. I m not sure that Maurizio fully reviewed it but his one comment was that he wanted me to get it over to you, so here you go. The answer is yes. We did find the tanks, removed them accordingly, dug below the groundwater table, collected all kinds of post-ex samples and three groundwater samples during dewatering. Actually, two during dewatering then when we went to take the third the dewatering system had broken the day before and they decided to not turn it back on, so the third sample was from a piezometer outside of

FORMER BUILDING SUPPLY/FUTURE RESIDENTIAL (Continued) **S101340991**

the excavation area that was used primarily for the monitoring of drawdown outside of the SOE sheeting. This we can and likely should discuss more. If you could, please confirm receipt and let me know when a good time is for you to discuss. Regards. Vought added DRAFT RCR dated May 2015 to D2 and reviewed: Draft Hazardous Materials Remedial Closure Report (Langan)-May 2015. Site part of E-designation and CEQR review. Prior to site development the site was occupied by a building supply company. Site also was occupied by Tuxedo Dairy, the Express Depot, commercial meat companies, metal working facilities, and trucking companies. The new development consists of a mixed use residential condominium building that completely occupies (full build-out) the site. The new building has a common ground floor and single subgrade level basement and two 10-story towers on either side of the highline that will contain 35 residential condominiums. Based on the location of the rear yard which is located above a below grade structure, there is no potential contact with impacted soils that were left on-site as part of the site redevelopment. The proposed building has one basement level extending approximately 16-feet below sidewalk grade and occupying the entire Site footprint, with exception of a portion of the site that is below the Highline (approximately 2,550 square feet) which remains unexcavated due to the existing structural and foundation elements that support the Highline. Approximately 21,829 tons of soil was removed as part of the foundation installation. Groundwater was encountered between depths of approximately 5- to 10-feet below existing site grade. Four dewatering wells installed and NYCDEP discharge permit obtained. Report noted Installed a Vapor Barrier System that consisted of a certified Grace Preprufe/300R waterproofing/vapor barrier with a minimum thickness of 46-mil beneath the entire building foundation and certified Grace Bituthene3000 with a minimum thickness of 62-mil along all foundation sidewalls. new buildings have a below grade cellar that is occupied by mechanical rooms (approximately 10,400 SF), shared tenant amenities (approximately 2,000 SF), and storage (Residential is approximately 2,000 SF and Commercial will be approximately 3,000 SF). Three underground storage tanks and an oil-water separator were removed during the Remedial Action. Two USTs were identified in the vicinity of the area where the tanks were suspected to be were encountered during site re-development activities. It is assumed that these were the USTs that were reported to the NYSDEC due to tank tightness failure that resulted in NYSDEC Spill No. 9406402 being assigned to the site. On 10 October 2013 the two 1,100-gallon USTs were cleaned and removed from the eastern side of the site. The previously abandoned in place USTs and associated piping were removed from the ground and the contents, consisting of a concrete slurry, were removed. 80-gallon UST associated with the oil water separator was also removed as well as surrounding contaminated soil. Six endpoint samples collected from development excavation for NYCOER and five additional endpoints collected around USTs for consideration of spill closure as per Report. The fill port was removed from the sidewalk on the north side of West 19th Street, south of former Lot 29. The excavation measured approximately 11-feet long by 8-feet wide x 9.5-feet deep and abutted the support of excavation wall to the north and extended south until the excavation boundary reached the NYCDOT right of way at West 19th Street. Staining and/or elevated PID readings were observed along the entire depth of the excavation on the eastern, southern, and western sidewalls. Five fill port area samples and one duplicate sample were

FORMER BUILDING SUPPLY/FUTURE RESIDENTIAL (Continued) **S101340991**

collected on 13 May 2014 at a depth of 9.5-feet bgs. GW-1 and GW-2 were collected from the dewatering system s effluent stream prior to reaching the settling tank or carbon units. GW-3 and its duplicate were collected from the dewatering system piezometer located outside the subject site due to a malfunction in the dewatering system on the date of sampling and the subsequent shut-down of the system following the malfunction. No exceedances of the NYSDEC GQS for VOCs were detected in any of the samples. with respect to dewatering samples. Dewatering samples were collected in June 2014, two years after last groundwater samples were collected during an subsurface investigation. As there is no exposure pathways to future site occupants and groundwater is not approved for potable use on site; the groundwater impacts that were identified do not pose a threat to public health. An approximately 12- to 14-inch thick concrete building slab was installed in areas of the site surrounding support columns for the High Line open space, the remainder of the site was finished with a 36-inch thick steel-reinforced pressure slab. Report also contained air monitoring data collected during the site development. Laboratory analyses and disposal manifests included in report. 4/5/16-Vought-After file review spill closed by Vought due to excavation of entire site to below the groundwater table and development of the foundation also below the water table and as such no remaining soil contamination or potential for soil vapor intrusion, installation of Grace petroleum compatible moisture and vapor barrier, documented historical groundwater petroleum VOC concentrations within attenuation parameters as per guidance from DEC BTS Central Office, three dewatering samples collected after soil source removal that were non-detect for VOCs and review of development plans by NYSDOH. Vought called and spoke to NYCOER Chawla who had no objections to Spill Closure. Spill closure letter sent to: HFZ Capital Group 600 Madison Avenue, 17th Floor New York, NY 1002 with cc to OER Chawla and Langan (McMahon). Spill closure letter also added to D2 and email sent to Langan (McMahon) that Chris, There is no need to discuss the spill as Closure is warranted after I reviewed the DRAFT Hazardous Waste Remedial Closure Report dated May 2015, prepared by Langan, and submitted to NYCOER. I have copied NYCDOH and NYSDOH above as they were also consulted on the spill. As we have not worked on this spill for some time here are relevant entries of my DEC Remarks sent as a refresher for DEC Central Office and NYSDOH copied above: 8/9/12-Vought-Sent email to OER Chawla with note that DEC cannot approve 8/1/12 proposal from Langan until a detailed sampling methodology is submitted for soil, soil vapor and groundwater and that complete proposal may also needed to be reviewed by NYSDOH. Vought also copied DEC Richard Dana as site also may be located in VCP V00530. Email from McMahon to NYSDOH Hughes and All Parties-3/27/13. Email that Mike we discussed this project on Monday and you had indicated that you would follow-up with an email stating that based on the results of the investigation and the proposed redevelopment activities which will excavate into the groundwater table on 2/3rds of the property and the use of a Grace waterproofing system beneath the entire redevelopment would be sufficient and not require NYSDOH or NYCDOH review. It is my understanding (Jeffrey please correct me if I m wrong) that this email would be sufficient to satisfy Jeffrey s question and would close out this issue with the NYSDEC. Please also find the attached letter from Grace which states that the contamination at the site in soil, soil vapor and groundwater should not have a negative effect on the performance of

FORMER BUILDING SUPPLY/FUTURE RESIDENTIAL (Continued) **S101340991**

their waterproofing system. Regards . Email from NYSDOH Hughes to All Parties-3/27/13. Email that In general, the DOH does not have a formal policy to review the specifications of moisture/gas barriers. Our only stipulation is that the barrier is a true impermeable vapor barrier and not just a moisture barrier. If the proposed barrier for this site meets that requirement then DOH has no further comments and concurs with the proposed course of action. A copy of the Department s closure letter is attached above and an original is in the US Mail to HFZ Capital Group. Thanks to you and all those copied above for their help. "

Remarks: "STUCK PROBE IN GROUND FOUND CONTAMINATED SOIL AT 9 FEET. WILL PULL TANKS OUT -ONCE THEY CAN SEE ALL CONTAMINATED SOIL THEY CAN REMOVE IT STUCK PILE."

All Materials:

Site ID:	167544
Operable Unit ID:	1003785
Operable Unit:	01
Material ID:	379446
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Z368 **KAMCO SUPPLY CORP.** **NY AST** **U004122428**
NW **501 WEST 19TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.106 mi.
561 ft. **Site 3 of 13 in cluster Z**

Relative: **Lower**
Actual: **10 ft.**

AST:

Name:	KAMCO SUPPLY CORP.
Address:	501 WEST 19TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-610897
Program Type:	PBS
UTM X:	583877.98279
UTM Y:	4510981.82021
Expiration Date:	N/A
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	402108
Affiliation Type:	Facility Owner
Company Name:	TENTH AVENUE REALTY ASSOCIATES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	362 KINGSLAND AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY

KAMCO SUPPLY CORP. (Continued) **U004122428**

Zip Code: 11222
Country Code: 001
Phone: (718) 391-5300
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2012-02-02

Site Id: 402108
Affiliation Type: Mail Contact
Company Name: MENDON LEASING CORP.
Contact Type: Not reported
Contact Name: ROGER PALAZZO
Address1: 362 KINGSLAND AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 391-5300
EMail: ROGER@MENDONLEASING.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-11-01

Site Id: 402108
Affiliation Type: Facility Operator
Company Name: KAMCO SUPPLY CORP.
Contact Type: Not reported
Contact Name: CESAR CHAVEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 378-2140
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-11-01

Site Id: 402108
Affiliation Type: Emergency Contact
Company Name: TENTH AVENUE REALTY ASSOCIATES
Contact Type: Not reported
Contact Name: PETE DOMANTE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 255-0120
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving

KAMCO SUPPLY CORP. (Continued) **U004122428**

Date Last Modified: 2008-08-01

Tank Info:

Tank Number: 007
Tank Id: 224391
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K02 - Spill Prevention - Transfer Station Containment
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1995
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 04/30/2009
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: waste oil/used oil

Tank Number: 008
Tank Id: 224392
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

L00 - Piping Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K02 - Spill Prevention - Transfer Station Containment
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

KAMCO SUPPLY CORP. (Continued) **U004122428**

	I04 - Overfill - Product Level Gauge (A/G)
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1995
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/30/2009
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

AA369 **EMPIRE CITY SUBWAY CO LTD** **RCRA-VSQG** **1000912482**
NNW **177-183 10TH AVE** **FINDS** **NY0000821736**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.107 mi. **NY MANIFEST**
567 ft. **Site 1 of 24 in cluster AA**

Relative: **Lower**
Actual: **11 ft.**

RCRA-VSQG:

Date Form Received by Agency:	20070101
Handler Name:	EMPIRE CITY SUBWAY CO LTD
Handler Address:	177-183 10TH AVE
Handler City,State,Zip:	NEW YORK, NY 10011-4708
EPA ID:	NY0000821736
Contact Name:	Not reported
Contact Address:	10TH AVE
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	10TH AVE
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	EMPIRE CITY SUBWAY CO LTD
Owner Type:	Private
Operator Name:	EMPIRE CITY SUBWAY CO LTD
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No

EMPIRE CITY SUBWAY CO LTD (Continued) **1000912482**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D008
Waste Description:	LEAD

EMPIRE CITY SUBWAY CO LTD (Continued) **1000912482**

Waste Code: D018
Waste Description: BENZENE

Waste Code: D035
Waste Description: METHYL ETHYL KETONE

Waste Code: F001
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F003
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: EMPIRE CITY SUBWAY CO LTD
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 177-183 10TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 212-242-1173
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: EMPIRE CITY SUBWAY CO LTD
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 177-183 10TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10011

EMPIRE CITY SUBWAY CO LTD (Continued) **1000912482**

Owner/Operator Telephone: 212-242-1173
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: EMPIRE CITY SUBWAY CO LTD
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 177-183 10TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 212-242-1173
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: EMPIRE CITY SUBWAY CO LTD
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: EMPIRE CITY SUBWAY CO LTD
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: EMPIRE CITY SUBWAY CO LTD
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

EMPIRE CITY SUBWAY CO LTD (Continued) **1000912482**

Receive Date: 19950310
Handler Name: EMPIRE CITY SUBWAY CO LTD
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004319639

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000912482
Registry ID: 110004319639
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004319639
Name: EMPIRE CITY SUBWAY CO LTD
Address: 177-183 10TH AVE
City,State,Zip: NEW YORK, NY 10011

NY MANIFEST:
Name: EMPIRE CITY SUBWAY
Address: 177-183 10TH AVE
City,State,Zip: NEW YORK, NY 10011-4708
Country: USA
EPA ID: NY0000821736
Facility Status: Not reported
Location Address 1: 177 10TH AVE
Code: BP

EMPIRE CITY SUBWAY CO LTD (Continued) **1000912482**

Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NY0000821736
Mailing Name: EMPIRE CITY SUBWAY
Mailing Contact: HUGH GILLESPIE
Mailing Address 1: 177 10TH AVENUE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10011
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2122421173

AA370 **EMPIRE CITY SUBWAY COMPANY LTD.** **NY AST** **A100382374**
NNW **177-83 10TH AVENUE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.107 mi.
567 ft. **Site 2 of 24 in cluster AA**

Relative:
Lower

Actual:
11 ft.

AST:
Name: EMPIRE CITY SUBWAY COMPANY LTD.
Address: 177-83 10TH AVENUE
City,State,Zip: NEW YORK, NY 10011
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-604451
Program Type: PBS
UTM X: 583966.80550
UTM Y: 4511062.05587
Expiration Date: N/A
Site Type: Utility (Other than Municipal)

Tank Info:

Tank Number: 002
Tank Id: 57799
Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 01/01/1989
Capacity Gallons: 250
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 06/01/1998
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017

EMPIRE CITY SUBWAY COMPANY LTD. (Continued) **A100382374**

Material Name:	Not reported

Tank Number:	003
Tank Id:	215830
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	05/01/1999
Capacity Gallons:	350
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/14/2007
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	Not reported

Tank Number:	004
Tank Id:	215831
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1999
Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/04/2007
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	Not reported

AA371 **EMPIRE CITY SUBWAY COMPANY LTD.** **NY UST** **U004198841**
NNW **177-83 10TH AVENUE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.107 mi.
567 ft. **Site 3 of 24 in cluster AA**

Relative: UST:
Lower

Actual:
11 ft.

Name:	EMPIRE CITY SUBWAY COMPANY LTD.
Address:	177-83 10TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-604451 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583966.80550
UTM Y:	4511062.05587
Site Type:	Utility (Other than Municipal)

EMPIRE CITY SUBWAY COMPANY LTD. (Continued) **U004198841**

Tank Info:

Tank Number:	001
Tank ID:	57798
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	3000
Install Date:	01/01/1989
Date Tank Closed:	11/27/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

T372 **325 WEST 16TH STREET TENANTS CORP** **NY AST** **U003383551**
SSE **325 WEST 16TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.108 mi.
568 ft. **Site 9 of 20 in cluster T**

Relative:
Higher

Actual:
18 ft.

AST:

Name:	325 WEST 16TH STREET TENANTS CORP
Address:	325 WEST 16TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-047481
Program Type:	PBS
UTM X:	584199.66287
UTM Y:	4510560.64364
Expiration Date:	12/02/2026
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	749
Affiliation Type:	Mail Contact
Company Name:	FRANCOUER/ COOKE MANAGEMENT LLC
Contact Type:	Not reported
Contact Name:	DOROTHY FRANCOEUR
Address1:	245 8TH AVE, SUITE 873
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 727-7660
EMail:	FEMET@ME.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-10-21

Site Id:	749

325 WEST 16TH STREET TENANTS CORP (Continued) **U003383551**

Affiliation Type:	Facility Operator
Company Name:	325 WEST 16TH STREET
Contact Type:	Not reported
Contact Name:	WEST 16TH STREET TENANTS CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 242-3703
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-10-21

Site Id:	749
Affiliation Type:	Emergency Contact
Company Name:	WEST 16TH STREET TENANTS CORP
Contact Type:	Not reported
Contact Name:	DOROTHY FRANCEUR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 727-7660
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-10-21

Site Id:	749
Affiliation Type:	Facility Owner
Company Name:	WEST 16TH STREET TENANTS CORP.
Contact Type:	MANAGING AGENT
Contact Name:	DOROTYH FRANCOEUR
Address1:	325 WEST 16TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 727-7660
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-10-21

Tank Info:

Tank Number:	001
Tank Id:	1667
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

325 WEST 16TH STREET TENANTS CORP (Continued) **U003383551**

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
J05 - Dispenser - On Site Heating System (Supply/Return)
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/19/1957
Capacity Gallons:	3000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	10/21/2021
Material Name:	#4 fuel oil (on-site consumption)

O373 **MINICK HOME** **NY LTANKS** **S107523558**
NNE **440 WEST 22ND STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.108 mi.
570 ft. **Site 9 of 9 in cluster O**

Relative:
Higher

Actual:
14 ft.

LTANKS:

Name:	MINICK HOME
Address:	440 WEST 22ND STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0512757 / 2006-03-10
Facility ID:	0512757
Site ID:	359128
Spill Date:	2006-02-03
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	Con Ed Unassigned
Referred To:	Not reported
Reported to Dept:	2006-02-03
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False

MINICK HOME (Continued) **S107523558**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-03
Spill Record Last Update:	2006-03-10
Spiller Name:	MINICK HOME
Spiller Company:	MINICK HOME
Spiller Address:	440 WEST 22ND STREET
Spiller County:	001
Spiller Contact:	MARK SALAMACK
Spiller Phone:	(917) 559-5519
Spiller Extention:	CELL
DEC Region:	2
DER Facility ID:	309129
DEC Memo:	"02/03/06 Feroze talked with Mr. Minick (owner) 212-604-9898. He informed that there was a leak in the tank, they have closed the leak and pumped the oil out. It is above ground tank, floor is made of concrete. An environmental company is working for them. TTF is sent to : Mr. Minick 440 west 22nd Street New york, NY 10011. 02/10/06 Mr. Minick called and told me that they will close the tank by PTC. He will submit DEC the documents soon. 03/02/06 Feroze,: Mr.Minick told me that PTC has taken soil sample. He will submit soil analysis result and tank closer report to DEC soon.It was 275 gallon tank. 03/10/06 Feroze received a certificate and soil analysis result. The result shows that VOC and SVOC are within accepatble limit. They also submited a manifest for removal of contaminated soil. The spill is closed."
Remarks:	"ruptured tank in basement:"

All Materials:

Site ID:	359128
Operable Unit ID:	1116352
Operable Unit:	01
Material ID:	2106499
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	8.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

S374 **CON EDISON SERVICE BOX: 40042** **NJ MANIFEST** **S117987052**
SSW **45 9TH AVE N OF 205 ST FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10034**
0.108 mi.
570 ft. **Site 9 of 18 in cluster S**

Relative: NJ MANIFEST:
Higher

Actual: EPA Id:	NYP004279196
15 ft. Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JOSE MONTALVO
Comments:	Not reported
SIC Code:	Not reported

CON EDISON SERVICE BOX: 40042 (Continued) **S117987052**

County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010840168JJK
EPA ID:	NYP004279196
Date Shipped:	11/8/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	500.00 Pounds

S375
SSW
< 1/8
0.108 mi.
570 ft.

CON EDISON SERVICE BOX: 40042
45 9TH AVE N OF 205 ST FRONT OF
NEW YORK, NY 10034

Site 10 of 18 in cluster S

RCRA NonGen / NLR | **1016149256** | **NYP004279196**

Relative:
Higher

Actual:
15 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20170728
Handler Name:	CON EDISON SERVICE BOX:	40042
Handler Address:		45 9TH AVE N OF 205 ST FRONT OF
Handler City,State,Zip:		NEW YORK, NY 10034
EPA ID:		NYP004279196
Contact Name:		JOSE MONTALVO
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-427-1331
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 40042 (Continued) **1016149256**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20171127
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20121128
Handler Name: CON EDISON SERVICE BOX:	40042
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20170728
Handler Name: CON EDISON SERVICE BOX:	40042
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No

CON EDISON SERVICE BOX: 40042 (Continued) **1016149256**

Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AA376 **CON EDISON SERVICE BOX: 3771** **RCRA NonGen / NLR** **1017778384**
North **467 W 21ST ST** **FINDS** **NYP004563086**
< 1/8 **NEW YORK, NY 10011**
0.108 mi.
571 ft. **Site 4 of 24 in cluster AA**

Relative:
Lower

Actual:
12 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	20140712
Handler Name:	CON EDISON SERVICE BOX: 3771
Handler Address:	467 W 21ST ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004563086
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

CON EDISON SERVICE BOX: 3771 (Continued) **1017778384**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140612
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CON EDISON SERVICE BOX: 3771 (Continued) **1017778384**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140612
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140712
Handler Name: CON EDISON SERVICE BOX: 3771
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063836951

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AA377 **CON EDISON** **NY MANIFEST** **S117063858**
North **467 W 21ST ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.108 mi.
571 ft. **Site 5 of 24 in cluster AA**

Relative:
Lower

Actual:
12 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	467 W 21ST ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004563086
Facility Status:	Not reported
Location Address 1:	FO 467 WEST 21ST
Code:	BP
Location Address 2:	SB 3771
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004563086
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/12/2014
Trans1 Recv Date:	06/12/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/13/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004563086
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013255185JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117063858**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

S378 **CON EDISON - SERVICE BOX 39629** **RCRA-LQG** **1014395677**
SSW **WEST 14TH STREET AND 9TH AVE** **NYP004171435**
< 1/8 **NEW YORK, NY 10014**
0.108 mi.
571 ft. **Site 11 of 18 in cluster S**

Relative: **Higher**
Actual: **15 ft.**

RCRA-LQG:

Date Form Received by Agency:	20100323
Handler Name:	CON EDISON - SERVICE BOX 39629
Handler Address:	WEST 14TH STREET AND 9TH AVE
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYP004171435
Contact Name:	FRANKLYN MURRAY
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-2808
Contact Fax:	Not reported
Contact Email:	MURRAYFR@CONED.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2009
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	4 IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private

CON EDISON - SERVICE BOX 39629 (Continued) **1014395677**

Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON - SERVICE BOX 39629 (Continued) **1014395677**

Biennial: List of Years
Year: 2009

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20090609
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20090609
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20100323
Handler Name: CON EDISON - SERVICE BOX 39629
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090609
Handler Name: CON EDISON
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

CON EDISON - SERVICE BOX 39629 (Continued) **1014395677**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

S379 **CON EDISON SERVICE BOX: M39624** **RCRA NonGen / NLR** **1025504539**
SSW **14TH ST & 9TH AVE** **NYP005173240**
< 1/8 **NEW YORK, NY 10014**
0.108 mi.
571 ft. **Site 12 of 18 in cluster S**

Relative: **Higher**
Actual: **15 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20200413
Handler Name: CON EDISON SERVICE BOX: M39624
Handler Address: 14TH ST & 9TH AVE
Handler City,State,Zip: NEW YORK, NY 10014
EPA ID: NYP005173240
Contact Name: Not reported
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: Not reported
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY
State District: NYSDEC R2
Mailing Address: Not reported
Mailing City,State,Zip: Not reported
Owner Name: Not reported
Owner Type: Not reported
Operator Name: Not reported
Operator Type: Not reported
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No

CON EDISON SERVICE BOX: M39624 (Continued) **1025504539**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200413
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20180108
Handler Name: CON EDISON SERVICE BOX:	M39624
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY

CON EDISON SERVICE BOX: M39624 (Continued) **1025504539**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20200413
Handler Name: CON EDISON SERVICE BOX:	M39624
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

---

380 **SPERANZA PROPERTIES LLC** **RCRA-VSQG** **1012186795**
NNE **448 W 22ND ST** **NY MANIFEST** **NYR000166579**
< 1/8 **NEW YORK, NY 10011**
0.109 mi.
574 ft.

Relative:
Higher

Actual:
14 ft.

RCRA-VSQG:

Date Form Received by Agency:	20090709
Handler Name:	SPERANZA PROPERTIES LLC
Handler Address:	448 W 22ND ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYR000166579
Contact Name:	KATHY REBER
Contact Address:	W 22ND ST
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	212-206-6314
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported

SPERANZA PROPERTIES LLC (Continued) **1012186795**

Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 22ND ST
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	SPERANZA PROPERTIES LLC
Owner Type:	Private
Operator Name:	ABATEK COR
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

SPERANZA PROPERTIES LLC (Continued) **1012186795**

Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ABATEK COR
Legal Status:	Private
Date Became Current:	20090317
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SPERANZA PROPERTIES LLC
Legal Status:	Private
Date Became Current:	20070129
Date Ended Current:	Not reported
Owner/Operator Address:	750 GREENWICH ST #2N
Owner/Operator City,State,Zip:	NEW YORK, NY 10014
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20090709
Handler Name: SPERANZA PROPERTIES LLC	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	53111

SPERANZA PROPERTIES LLC (Continued) **1012186795**

NAICS Description: LESSORS OF RESIDENTIAL BUILDINGS AND DWELLINGS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	SPERANZA PROPERTIES LLC
Address:	448 W 22ND ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYR000166579
Facility Status:	Not reported
Location Address 1:	448 W 22ND ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000166579
Mailing Name:	SPERANZA PROPERTIES LLC
Mailing Contact:	SPERANZA PROPERTIES LLC
Mailing Address 1:	448 W 22ND ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6312253044

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD054126164
Trans2 State ID:	Not reported
Generator Ship Date:	08/20/2009
Trans1 Recv Date:	08/20/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/17/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000166579
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported

SPERANZA PROPERTIES LLC (Continued) **1012186795**

Manifest Tracking Number:	005194483JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	523
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

V381 **70 TENTH AVENUE** **NY Spills** **S105058129**
WSW **70 TENTH AVE** **N/A**
< 1/8 **NEW YORK, NY**
0.109 mi.
574 ft. **Site 3 of 8 in cluster V**

Relative: **Lower**

Actual: **10 ft.**

SPILLS:

Name:	70 TENTH AVENUE
Address:	70 TENTH AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0102822 / 2005-03-28
Facility ID:	0102822
Facility Type:	ER
DER Facility ID:	355277
Site ID:	198259
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	2001-06-13
Investigator:	JMROMMEL
Referred To:	Not reported
Reported to Dept:	2001-06-13
CID:	216
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility

70 TENTH AVENUE (Continued) **S105058129**

Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2001-06-13
Spill Record Last Update:	2008-10-30
Spiller Name:	Not reported
Spiller Company:	MOBIL
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	BATT CHIEF 7
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 12/9/03 MT////TRANSFERRED FROM TIPPLE TO ROMMEL 3/28/05 - spill closed, refer to 0103052 for tracking. KST"
Remarks:	"SPILL IS IN A MOBIL GAS STATION IN THE CELLAR VERY LITTLE INFO AT THIS TIME NYCFD IS ON THE SCENE DEP REP CALLED AT 00:50 ANDREW KELLY WANTS REP FROM DEC TO CALL HIM AT 917-226-1888 REF TO ABOVE SPILL REP FROM DEC WAS PAGED AND GIVEN MESSAGE AT 00:56 "

All Materials:

Site ID:	198259
Operable Unit ID:	841518
Operable Unit:	01
Material ID:	534930
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

V382 **CHELSEA CAR WASH** **EDR Hist Auto** **1021333880**
WSW **70 10TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.109 mi.
574 ft. **Site 4 of 8 in cluster V**

Relative: EDR Hist Auto
Lower

Actual:
10 ft.

Year:	Name:	Type:
1999	10TH AVE CARWASH LLC NOT LLC	Carwashes, NEC
2000	10TH AVENUE CARWASH LLC	Carwashes, NEC
2001	10TH AVENUE CARWASH LLC	Carwashes, NEC
2002	10TH AVENUE CARWASH LLC	Carwashes, NEC
2003	10TH AVENUE CARWASH LLC	Carwashes, NEC
2004	CHELSEA CAR WASH	Carwashes, NEC
2005	CHELSEA CAR WASH	Carwashes, NEC
2006	CHELSEA CAR WASH	Carwashes, NEC
2007	CHELSEA CAR WASH	Carwashes, NEC
2008	CHELSEA CAR WASH	Carwashes, NEC
2009	CHELSEA CAR WASH	Carwashes, NEC
2010	CHELSEA CAR WASH	Carwashes, NEC

CHELSEA CAR WASH (Continued) **1021333880**

2011 CHELSEA CAR WASH Carwashes, NEC

V383 **CHELSEA CAR WASH / MOBIL** **NY Spills** **S105055971**
WSW **70 TENTH AVE** **N/A**
< 1/8 **NEW YORK, NY**
0.109 mi.
574 ft. **Site 5 of 8 in cluster V**

Relative: **Lower**
Actual: **10 ft.**

SPILLS:

Name:	CHELSEA CAR WASH / MOBIL
Address:	70 TENTH AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0103052 / 2006-07-12
Facility ID:	0103052
Facility Type:	ER
DER Facility ID:	355277
Site ID:	198260
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2001-06-19
Investigator:	SXLASDIN
Referred To:	Not reported
Reported to Dept:	2001-06-19
CID:	207
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2001-06-19
Spill Record Last Update:	2008-10-30
Spiller Name:	TONY PABON
Spiller Company:	CHELSEA CAR WASH/MOBIL
Spiller Address:	70 TENTH AVE
Spiller Company:	001
Contact Name:	TONY PABON
DEC Memo:	"Sepe is the senior tank tester. Unknown if any product lost - exposing lines next couple of days. 3/28/05 - also see spill # 0102822. KST repairs and cleanup in progress at time of spill, unknown if any product lost. assume completed. close spill"
Remarks:	"repairs and cleanup in progress"

All Materials:

Site ID:	198260
Operable Unit ID:	839653
Operable Unit:	01
Material ID:	535151
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

CHELSEA CAR WASH / MOBIL (Continued) **S105055971**

Units: G
Recovered: .00
Oxygenate: Not reported

U384 **LOT 20,TAXBLOCK 690** **NY E DESIGNATION** **S108076883**
NW **511 WEST 18 STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.109 mi.
575 ft. **Site 5 of 15 in cluster U**

Relative: **Lower**
Actual: **9 ft.**

E DESIGNATION:
Name: LOT 20,TAXBLOCK 690
Address: 511 WEST 18 STREET
City,State,Zip: MANHATTAN, NY
Tax Lot(s): 20
Tax Block: 690
Borough Code: Not reported
E-No: E-142
Effective Date: 6/23/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP069M
Ulurp Number: 050161 ZRM
Zoning Map No: 8b

Description: Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date: Not reported

Description: Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

U385 **515 WEST 18TH STREET** **NY BROWNFIELDS** **S117851117**
NW **511 WEST 18TH STREET AND 131 10TH AVENUE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.109 mi.
575 ft. **Site 6 of 15 in cluster U**

Relative: **Lower**
Actual: **9 ft.**

BROWNFIELDS:
Name: 515 WEST 18TH STREET
Address: 511 WEST 18TH STREET AND 131 10TH AVENUE
City,State,Zip: NEW YORK, NY 10011
Program: BCP
Site Code: 506209
Acres: 1.056
HW Code: C231093
SWIS: 3101
Town: New York City
Record Added Date: 04/03/2015
Record Updated Date: 06/09/2021
Update By: DJEATON
Site Description: "Location: The 515 West 18th Street site is approximately 1 acre in size located in an urban area in the West Chelsea section of the Borough of Manhattan. The site is bounded by West 19th Street on the

515 WEST 18TH STREET (Continued) **S117851117**

north, West 18th Street to the south, and 10th Avenue to the east. Site Features: The site consists of two adjacent lots, designated as Lots 20 and 29. Lot 20 is currently improved with two 2-story buildings, with slab on grade foundations. The first building has the first floor utilized as a parking garage and the second floor as an art gallery. The other building is a residential space. Lot 29 is a paved parking lot. The High Line Park, an elevated and open recreational walkway, runs north to south over the western portion of Lot 29. Current Zoning/Use: The site is zoned C6-4 for mixed commercial and residential use and is currently vacant. Past Uses of the Site: Both lots were historically used to support the nearby Manufactured Gas Plant (MGP) operations of the West 18th Street Gas Works. In approximately 1848, two gas holders were constructed on Lot 29 and used for storage of manufactured gas until the early 1900s. Lot 20 was used as a storage yard by the MGP from about 1870 until the early 1900s. The gas works produced gas using the coal carbonization process throughout its entire history. After the site was sold in 1919, a large garage was constructed on the 18th Street side of Lot 20 that included buried gasoline tanks. In 1947, a private garage was built on the 19th Street side of Lot 20 as well. On Lot 29, the gas holders were razed in 1914. After being sold in 1917, Lot 29 was used as a wagon yard, automobile parking lot, and commercial truck parking lot with several small structures and underground petroleum storage tanks. These properties were originally part of a Voluntary Cleanup Program project, subject to a legal agreement between Con Edison and the Department, for the Con Edison West 18th Street Gas Works site, site #V00530. Site Geology and Hydrogeology: The site is underlain by a thick deposit of urban fill materials which was placed along the Hudson River shoreline to create additional land for development. The fill, 7 to 30 feet deep, consists of a variety of man-made materials such as bricks and ash, mixed with soil. The fill is underlain by sands, silts and glacial till, which extend to bedrock, found between 40 and 60 feet below the surface. Groundwater occurs between 8 and 9 feet below grade. Regional groundwater flow is westerly towards the Hudson River; local groundwater flow is generally the same. "

Env Problem:	"Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were naphthalene, lead, and xylene in soil, and naphthalene and xylene in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2017-07-20 12:25:00
Record Upd:	2018-12-04 12:42:00

515 WEST 18TH STREET (Continued) **S117851117**

Updated By:	DKMACNEA
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Ashley Forrest Curran
Owner Company:	New York Public Library - Muhlenberg Branch
Owner Address:	209 West 23rd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Frank Monterisi, Jr.
Owner Company:	18th Highline Associates, L.L.C.
Owner Address:	c/o The Related Companies
Owner Addr2:	60 Columbus Circle
Owner City,St,Zip:	New York, NY 10023
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Frank Monterisi, Jr.
Owner Company:	18th Highline Associates, L.L.C.
Owner Address:	c/o The Related Companies
Owner Addr2:	60 Columbus Circle
Owner City,St,Zip:	New York, NY 10023
Owner Country:	United States of America
HW Code:	C231093
Waste Type:	polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231093
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231093
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231093
Waste Type:	benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231093
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231093
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C231093-05-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2018-12-04 12:45:00
Record Updated:	2018-12-04 12:45:00
Updated By:	DKMACNEA
Crossref ID:	2018000393460
Cross Ref Type Code:	25

515 WEST 18TH STREET (Continued) **S117851117**

Cross Ref Type:	County Recording Identifier
Record Added Date:	2018-12-04 12:43:00
Record Updated:	2018-12-04 12:43:00
Updated By:	DKMACNEA

U386 **WAREHOUSE BUILDING** **NY Spills** **S109828364**
NW **511 WEST 18TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.109 mi.
575 ft. **Site 7 of 15 in cluster U**

Relative: **Lower**

Actual: **9 ft.**

SPILLS:

Name:	WAREHOUSE BUILDING
Address:	511 WEST 18TH STREET
City,State,Zip:	NEW YORK, NY 10011
Spill Number/Closed Date:	0905252 / 2009-08-10
Facility ID:	0905252
Facility Type:	ER
DER Facility ID:	366690
Site ID:	417512
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	2009-08-05
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2009-08-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-08-05
Spill Record Last Update:	2009-08-10
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	YUSEPH FLEEM
DEC Memo:	"08/05/09-Hiralkumar Patel. 4:15 PM:- visited site. its abandoned warehouse. found about 2 gal of dark oil in front of one of the entrance. put some absorbent pads. 08/06/09 Spoke with 555 w 18th street property manager Tom Panissidi(PBS: 2-611018). He told me that the garage which is the source of the oil, belong to property one building east to them, which is 511 W 18th St.CSL was sent to Semantic Realty LLC address taken from property shark 362 Kingsland Avenue Brooklyn, NY 11222 (sr) 08/10/09 Performed site visit today. The building is being used as a parking garage.Hydraulic oil hose leak caused the spill of minor quantity by the shutter.Hose is being repaired.Speedy dry was placed to clean the spill. No tank in the building.Spill was on concrete floor.Case closed.Site owner Mendy Taffel at Semantic Realty LLC.(sr)"

WAREHOUSE BUILDING (Continued) **S109828364**

Remarks: "neighboring property owner to warehouse at above address reports approx 3 gallons of waste oil leaking out from under garge door, unkown what it is coming from. Warehouse is abandoned does not appear that anyone is coming to clean it up."

All Materials:

Site ID:	417512
Operable Unit ID:	1173724
Operable Unit:	01
Material ID:	2165693
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

W387 **CON EDISON - TRANSFORMER MANHOLE 1879** **NJ MANIFEST** **S120677776**
SW **WASHINGTON ST & W 14 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.109 mi.
577 ft. **Site 3 of 17 in cluster W**

Relative: **Lower**

Actual: **12 ft.**

NJ MANIFEST:

EPA Id:	NYP004861403
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002612300GBF
EPA ID:	NYP004861403
Date Shipped:	10/28/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

CON EDISON - TRANSFORMER MANHOLE 1879 (Continued) **S120677776**

Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

W388 **CON ED** **NY MANIFEST** **S118563601**
SW **WASHINGTON ST & W 14 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.109 mi.
577 ft. **Site 4 of 17 in cluster W**

Relative:
Lower

Actual:
12 ft.

NY MANIFEST:

Name:	CON ED
Address:	WASHINGTON ST & W 14 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004861403
Facility Status:	Not reported
Location Address 1:	WASHINGTON ST & W 14 ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004861403
Mailing Name:	CON ED
Mailing Contact:	CON ED
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK

CON ED (Continued) **S118563601**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

W389 **CON EDISON - TRANSFORMER MANHOLE 1879** **RCRA-LQG** **1019325817**
SW **WASHINGTON ST & W 14 ST** **NYP004861403**
< 1/8 **NEW YORK, NY 10011**
0.109 mi.
577 ft. **Site 5 of 17 in cluster W**

Relative: RCRA-LQG:
Lower

Actual:
12 ft.

Date Form Received by Agency:	20160226
Handler Name:	CON EDISON - TRANSFORMER MANHOLE 1879
Handler Address:	WASHINGTON ST & W 14 ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004861403
Contact Name:	THERESA BURKARD
Contact Address:	IRVING PL 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2262
Contact Fax:	Not reported
Contact Email:	BURKARDT@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2015
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---

CON EDISON - TRANSFORMER MANHOLE 1879 (Continued) **1019325817**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161107
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20151028
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003

CON EDISON - TRANSFORMER MANHOLE 1879 (Continued) **1019325817**

Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20151028
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160226
Handler Name: CON EDISON - TRANSFORMER MANHOLE 1879
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

Z390 **CON ED** **NY MANIFEST** **S118463302**
NW **505 W 19TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.110 mi.
580 ft. **Site 4 of 13 in cluster Z**

Relative: **Lower**
Actual: **10 ft.**

NY MANIFEST:
Name: CON ED
Address: 505 W 19TH ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004849604
Facility Status: Not reported
Location Address 1: 505 W 19TH ST

CON ED (Continued) **S118463302**

Code:	BP
Location Address 2:	SB 3405
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004849604
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	10/07/2015
Trans1 Recv Date:	10/07/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/12/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004849604
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002612359GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON ED (Continued) **S118463302**

Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Z391 **HFZ HIGHLINE PROPERTY OWNERS L.L.C.** **PA MANIFEST** **S116737563**
NW **505 W. 19TH STREET** **N/A**
< 1/8 **MANHATTAN, NY 10011**
0.110 mi.
580 ft. **Site 5 of 13 in cluster Z**

Relative: **Lower**

Actual: **10 ft.**

Manifest Details:

Year:	2013
Manifest Number:	011812603JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000203869
Generator Date:	11/26/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems of PA Inc
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	46000
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Z392 **LOT 7502,TAXBLOCK 691** **NY E DESIGNATION** **S122872810**
NW **505 WEST 19 STREET** **N/A**
< 1/8 **MANHATTAN, NY 10011**
0.110 mi.
580 ft. **Site 6 of 13 in cluster Z**

Relative: **Lower**
Actual: **10 ft.**

E DESIGNATION:

Name:	LOT 7502,TAXBLOCK 691
Address:	505 WEST 19 STREET
City,State,Zip:	MANHATTAN, NY 10011
Tax Lot(s):	7502
Tax Block:	691
Borough Code:	MN
E-No:	E-142
Effective Date:	6/23/2005
Satisfaction Date:	Not reported
Ceqr Number:	03DCP069M
Ulurp Number:	050161 ZRM
Zoning Map No:	8b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	9/7/2016
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date:	Not reported

Z393 **HFZ HIGHLINE PROPERTY OWNER LLC** **RCRA NonGen / NLR** **1016451793**
NW **505 W 19TH ST** **FINDS** **NYR000203869**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.110 mi.
580 ft. **Site 7 of 13 in cluster Z**

Relative: **Lower**
Actual: **10 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20140428
Handler Name:	HFZ HIGHLINE PROPERTY OWNER LLC
Handler Address:	505 W 19TH ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYR000203869
Contact Name:	JOHNATHON HOTETZ
Contact Address:	2ND ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	646-773-9513
Contact Fax:	Not reported
Contact Email:	JHOTETZ@LEEDINGBUILDERSGROUP.COM
Contact Title:	SITE SUPERINTENDENT LEEDING BUILDERS GROUP
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	HFZ CAPITAL GROUP
Mailing City,State,Zip:	NEW YORK, NY 10022
Owner Name:	HFZ HIGHLINE PROPERTY OWNER LLC

HFZ HIGHLINE PROPERTY OWNER LLC (Continued) **1016451793**

Owner Type:	Private
Operator Name:	SKY MATERIALS OF MASPETH NEW YORK
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20151117
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

HFZ HIGHLINE PROPERTY OWNER LLC (Continued) **1016451793**

Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: SKY MATERIALS OF MASPETH NEW YORK
Legal Status: Private
Date Became Current: 20130821
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HFZ HIGHLINE PROPERTY OWNER LLC
Legal Status: Private
Date Became Current: 20121205
Date Ended Current: Not reported
Owner/Operator Address: 600 MADISON AVE 17TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10022
Owner/Operator Telephone: 212-897-2395
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HFZ HIGHLINE PROPERTY OWNER LLC
Legal Status: Private
Date Became Current: 20121205
Date Ended Current: Not reported
Owner/Operator Address: 600 MADISON AVE 17TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10022
Owner/Operator Telephone: 212-897-2395
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SKY MATERIALS OF MASPETH NEW YORK
Legal Status: Private
Date Became Current: 20130821
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

HFZ HIGHLINE PROPERTY OWNER LLC (Continued) **1016451793**

Historic Generators:

Receive Date:	20140428
Handler Name:	HFZ HIGHLINE PROPERTY OWNER LLC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131017
Handler Name:	HFZ HIGHLINE PROPERTY OWNER LLC
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	236116
NAICS Description:	NEW MULTIFAMILY HOUSING CONSTRUCTION (EXCEPT OPERATIVE BUILDERS)

NAICS Code:	23622
NAICS Description:	COMMERCIAL AND INSTITUTIONAL BUILDING CONSTRUCTION

Facility Has Received Notices of Violations:

Violations: No Violations Found

Evaluation Action Summary:

Evaluations: No Evaluations Found

FINDS:

Registry ID: 110056331465

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HFZ HIGHLINE PROPERTY OWNER LLC (Continued) **1016451793**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016451793
Registry ID:	110056331465
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110056331465
Name:	HFZ HIGHLINE PROPERTY OWNER LLC
Address:	505 W 19TH ST
City,State,Zip:	NEW YORK, NY 10011

Z394 **CON EDISON SERVICE BOX: 3405** **RCRA NonGen / NLR** **1016143903**
NW **507 W 19TH ST** **FINDS** **NYP004266904**
< 1/8 **NEW YORK, NY 10014** **ECHO**
0.110 mi. **NY MANIFEST**
581 ft. **Site 8 of 13 in cluster Z**

Relative: **Lower**
Actual: **10 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130322
Handler Name:	CON EDISON SERVICE BOX: 3405
Handler Address:	507 W 19TH ST
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYP004266904
Contact Name:	JUAN RODRIGUEZ
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	347-865-5931
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No

CON EDISON SERVICE BOX: 3405 (Continued) **1016143903**

Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130222
Handler Name: CON EDISON SERVICE BOX:	3405
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 3405 (Continued) **1016143903**

Electronic Manifest Broker: Not reported

Receive Date: 20130322
Handler Name: CON EDISON SERVICE BOX: 3405
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110064102448

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016143903
Registry ID: 110064102448
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110064102448
Name: CON EDISON SERVICE BOX: 3405
Address: 507 W 19TH ST
City,State,Zip: NEW YORK, NY 10014

NY MANIFEST:
Name: CON EDISON
Address: 507 W 19TH ST
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYP004266904
Facility Status: Not reported

CON EDISON SERVICE BOX: 3405 (Continued) **1016143903**

Location Address 1:	5074 19TH ST
Code:	BP
Location Address 2:	SERV BOX 3405
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004266904
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/22/2013
Trans1 Recv Date:	02/22/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/22/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004266904
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010408530JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON SERVICE BOX: 3405 (Continued) **1016143903**

Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

S395 **CON EDISON** **RCRA NonGen / NLR** **1014395679**
South **345 W 14TH ST** **NJ MANIFEST** **NYP004171450**
< 1/8 **NEW YORK, NY 10014** **NY MANIFEST**
0.110 mi.
583 ft. **Site 13 of 18 in cluster S**

Relative: **Higher**

Actual: **17 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		345 W 14TH ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004171450
Contact Name:		DAVID DUKE
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		917-559-8971
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No

CON EDISON (Continued) **1014395679**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160727
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090609
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON (Continued) **1014395679**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160601
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:
EPA Id: NYP004171450
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DAVID DUKE
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 003534448JJK
EPA ID: NYP004171450
Date Shipped: 06/09/2009
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported

CON EDISON (Continued) **1014395679**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/09/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/09/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	2000 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	345 W 14TH ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004171450
Facility Status:	Not reported
Location Address 1:	F/O 345 W 14TH STREET
Code:	BP
Location Address 2:	SB# 2360
Total Tanks:	Not reported
Location City:	MANHATTAN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

CON EDISON (Continued) **1014395679**

NY MANIFEST:

EPAID:	NYP004171450
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/09/2009
Trans1 Recv Date:	06/09/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/09/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004171450
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003534448JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **1014395679**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

X396 **CON EDISON** **RCRA NonGen / NLR** **1014395675**
South **338 W 15TH ST** **NJ MANIFEST** **NYP004171419**
< 1/8 **NEW YORK, NY 10014** **NY MANIFEST**
0.110 mi.
583 ft. **Site 2 of 11 in cluster X**

Relative: **Higher**
Actual: **18 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		338 W 15TH ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004171419
Contact Name:		DAVID DUKE
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		917-559-8971
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---

CON EDISON (Continued) **1014395675**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160727
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090608
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified

CON EDISON (Continued) **1014395675**

State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:
EPA Id: NYP004171419
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DAVID DUKE
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 003532081JJK
EPA ID: NYP004171419
Date Shipped: 06/08/2009
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 06/08/2009
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported

CON EDISON (Continued) **1014395675**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/09/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	550 P

NY MANIFEST:

Name:	CONSOLLIDATED EDISON
Address:	338 W 15TH ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004171419
Facility Status:	Not reported
Location Address 1:	338 W 15TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004171419
Mailing Name:	CONSOLLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003

CON EDISON (Continued) **1014395675**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/08/2009
Trans1 Recv Date:	06/08/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/09/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004171419
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003532081JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	550
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

V397 **LOT 1,TAXBLOCK 712** **NY E DESIGNATION** **S118191066**
WSW **58 10 AVENUE** **N/A**
< 1/8 **MANHATTAN, NY**
0.111 mi.
584 ft. **Site 6 of 8 in cluster V**

Relative: **Lower**
Actual: **10 ft.**

E DESIGNATION:

Name:	LOT 1,TAXBLOCK 712
Address:	58 10 AVENUE
City,State,Zip:	MANHATTAN, NY
Tax Lot(s):	1
Tax Block:	712
Borough Code:	Not reported
E-No:	E-350
Effective Date:	1/22/2015
Satisfaction Date:	Not reported
Ceqr Number:	15DCP037M
Ulurp Number:	150101ZMM, 150102ZRM
Zoning Map No:	8b
Description:	Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

S398 **CON EDISON SERVICE BOX: 2371** **RCRA NonGen / NLR** **1017772427**
SSW **340-338 W 14TH ST & HUDSON ST E OF** **FINDS** **NYP004493854**
< 1/8 **NEW YORK, NY 10014**
0.111 mi.
584 ft. **Site 14 of 18 in cluster S**

Relative: **Higher**
Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140508
Handler Name:	CON EDISON SERVICE BOX:	2371
Handler Address:		340-338 W 14TH ST & HUDSON ST E OF
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004493854
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported

CON EDISON SERVICE BOX: 2371 (Continued) **1017772427**

Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON SERVICE BOX: 2371 (Continued) **1017772427**

Historic Generators:

Receive Date:		20140408
Handler Name:	CON EDISON	
Federal Waste Generator Description:		Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20140408
Handler Name:	CON EDISON	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20140508
Handler Name:	CON EDISON SERVICE BOX:	2371
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063777211

Click Here:

CON EDISON SERVICE BOX: 2371 (Continued) **1017772427**

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

V399 **CON EDISON SERVICE BOX: 43039** **RCRA NonGen / NLR** **1016150286**
WSW **69 10TH AVE FRONT OF** **FINDS** **NYP004289583**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.111 mi. **NY MANIFEST**
584 ft. **Site 7 of 8 in cluster V**

Relative: **Lower**
Actual: **10 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130315
Handler Name:	CON EDISON SERVICE BOX: 43039
Handler Address:	69 10TH AVE FRONT OF
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004289583
Contact Name:	RICARDO CARTY
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	646-772-3407
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

CON EDISON SERVICE BOX: 43039 (Continued) **1016150286**

Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130215
Handler Name: CON EDISON SERVICE BOX:	43039
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 43039 (Continued) **1016150286**

Receive Date:	20130315
Handler Name: CON EDISON SERVICE BOX:	43039
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055461931

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016150286
Registry ID:	110055461931
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055461931
Name:	CON EDISON SERVICE BOX: 43039
Address:	69 10TH AVE FRONT OF
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	CON EDISON
Address:	69 10TH AVE FRONT OF
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004289583
Facility Status:	Not reported
Location Address 1:	F/O 69 10 AVE
Code:	BP

CON EDISON SERVICE BOX: 43039 (Continued) **1016150286**

Location Address 2:	SERVICE BOX # 43039
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004289583
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/15/2013
Trans1 Recv Date:	02/15/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/16/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004289583
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010841360JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000

CON EDISON SERVICE BOX: 43039 (Continued) **1016150286**

Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

U400 **515 W 18 ST** **NY Spills** **S104502660**
NW **515 WEST 18TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.111 mi.
587 ft. **Site 8 of 15 in cluster U**

Relative: **Lower**

Actual: **9 ft.**

SPILLS:

Name:	515 W 18 ST
Address:	515 WEST 18TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9612012 / 2013-01-11
Facility ID:	9612012
Facility Type:	ER
DER Facility ID:	149797
Site ID:	178360
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	3101
Spill Date:	1997-01-06
Investigator:	hrpatel
Referred To:	Not reported
Reported to Dept:	1997-01-06
CID:	297
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-01-06
Spill Record Last Update:	2013-01-11
Spiller Name:	MR RICCIO
Spiller Company:	MENDON LEASING
Spiller Address:	515 WEST 18TH ST
Spiller Company:	001
Contact Name:	CHRISTOPHER HONOR
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MULQUEEN 9514181 TANK TEST FAILURE. ORIGINALLY ASSIGNED TO MARTINKAT - FILE TRANSFERRED TO MULQUEEN 06/16/06: This spill is transferred from Mike Mulqueen to Mr. Koon Tang. 03/18/09-Hiralkumar Patel. received call from Suzanne Maxx from World Team. she mentioned that

515 W 18 ST (Continued) **S104502660**

her organization is planning to buy this property and she inquired about work required to close the spill. mentioned to her that two spill cases reported (including this) at the site: Spill #: 9514181 - tank test failure reported on 02/07/1996 for two 1,500 gal tanks. spill #: 9612012 - contaminated soil found, on 01/06/1997, during replacement of two 1,500 gal tanks with one 4,000 gal tank based on information reported in spill reports, mentioned to Ms. Maxx that the department requires soil and groundwater investigation at the location of two 1500 gal tanks and one 4,000 gal tanks unless both locations are the same. mentioned to her that the department may require additional investigation and remediation, if contamination found on the site. sent email to Ms. Maxx with copy of spill reports and PBS record. Suzanne Maxx World Team **potential buyer** Ph. (310) 917-9106 email: suzanne@worldteamnow.org alternate addresses: 508-510 W 19 St, 511-525 W 18 St no other spill found. spill case 9514181 closed and consolidated with this case. case transferred from DEC Tang to DEC Patel. according to building permit record dated 06/25/1996: removed two 1,500 gal diesel USTs and one dispenser with associated piping and installed one 4,000 gal diesel UST and dispenser with associated piping <---------- PBS #: 2-032212. according to PBS record, site had following tanks: - three 550 gal gasoline USTs, closed-removed in Jan. 1999 - two 1,500 gal diesel USTs, closed-in place in Jan. 1997 - one 4,000 gal diesel UST, closed-in place in Nov. 2004 Semantic Realty, Inc. **property owner** 362 Kingsland Ave Brooklyn NY 11222-1905 Attn.: Mendy Taffel Ph. (718) 391-5300 Fax (561) 995-7578 email: mendy@mendonleasing.com spoke with Aida Diaz, book keeper for the property. she will ask property owner to call back. received call from Mendy Taffel, property owner. he asked for copy of spill reports. faxed copy of spill reports to Mr. Taffel. Mr. Taffel is in Florida and will be in NY after 10 days and at that time he will call with company's name who really owns the property. 04/23/09-Hiralkumar Patel. left message for Mr. Taffel. 04/24/09-Hiralkumar Patel. received message from Mr. Taffel. 04/28/09-Hiralkumar Patel. received call from Mr. Taffel. he will ask his consultant to submit documents. received letter from Ron from Core environmental. abstract: - subject property is located at block # 690/ lot # 20 - lot is entirely covered by two-story brick building - first floor is utilized as parking lot and the second floor is currently vacant - two 1,500 gal tanks failed tightness test in 1996; both tanks removed in 1997 and were replaced by one 4,000 gal tank which was closed in place in 2004 - tanks were located below the first floor slab - property is part of the West 18th Street Gas Works (MGP site) - previous investigatory work performed by ConEd along the western property line of this lot and the parking lot to the east has confirmed MGP related contaminants in the soil and groundwater Ronald Tramposch Core Environmental, Inc. Ph. (718) 762-0544 (O) (718) 786-4730 (917) 804-8717 (C) Fax (718) 762-0545 email: rpt@coreenv.com 05/04/09-Hiralkumar Patel. found documents on e-docs. CSL was sent out to property owner/manager on 01/07/97. spoke with DEC Jane. she asked to contact William Ottaway in Central office as he is handling MGP case. sent email to Mr. Ottaway, with copy of spill report, to know whether this case be part of MGP case or will it be separate. received email from Mr. Ottaway. he mentioned that the site is within the boundary of the ConEdison W18th Street MGP site (V00530). he has not seen any significant MGP contamination there, but believes there are some residual MGP related contamination at depth. he will receive the site-wide RI for this site this summer,

515 W 18 ST (Continued) **S104502660**

and will make determinations at that time regarding the extent of contamination and whether any active remediation is needed at this property. Mr. Ottaway does not anticipate any active remediation at this time. he expects this property to be covered by the site management plan (SMP) for the MGP site, but would not assume that the petroleum contamination would necessarily be addressed by an MGP remedy. It might be appropriate for the SMP to reference this spill so future development will understand the need to address this issue appropriately. he will discuss that with the ConEd project manager. Mr. Ottaway thinks that this spill needs to be addressed separately from the MGP site. William S. Ottaway Remedial Bureau C, MGP Section Division of Environmental Remediation NYS DEC PH. (518) 402-9686 Fax (518) 402-9022 email: wsottawa@gw.dec.state.ny.us 05/26/09-Hiralkumar Patel. spoke with Ms. Maxx regarding status of property purchase. she mentioned that they haven't purchased yet. during conversation, Ms. Maxx mentioned that there are phase I and Phase II investigation performed on the site by property owner. she mentioned that reports were made in 1996 and in 2004/2005. spoke with Mr. Taffel about previous investigation reports. he asked to contact Ron at Core environmental. left message for Ron at Core environmental. 05/27/09-Hiralkumar Patel. 11:45 AM:- received call from Ron. he spoke with property owner and owner's doesn't have any reports and doesn't remember any investigation work done on his property. 11:48 AM:- spoke with Ms. Maxx regarding previous reports. she refused to provide copy of reports for review. 08/06/09-Hiralkumar Patel. 10:31 AM:- spoke with Mr. Ottaway. he hasn't got investigation report yet. 11:05 AM:- sent letter to Mr. Taffel requiring soil/GW investigation around 4000 gal tank system (including piping, remote fill port and disepenser islands) and site map with location of current/former tanks. letter faxed to Mr. Taffel and emailed to Mr. Ottaway and Ron. 12:13 PM:- recevied message from Mr. Taffel. 12:53 PM:- spoke with Mr. Taffel. he asked for meeting to discuss this matter. he will ask Ron to call to discuss technical matter. 1:00 PM:- received call from Ron. explained him that the Department requires soil/gw investigation based on earlier tank test failure and soil contamination complaints. also explained that if MGP contamination found on property, then this case may be transferred to project manager in Albany for cleanup under MGP case. Ron will talk to Mr. Taffel. 09/09/09-Hiralkumar Patel. 3:52 PM:- received email from Ron stating that ConEd has done some investigation on the site and are waiting for documents from ConEd. 3:57 PM:- sent email to Ron and asked him to submit required investigation report (according to letter dated 08/06/09) by the end of 09/18/09 or else case may be referred to legal division. 5:00 PM:- received email from Ron. he mentioned that: letter of August 6th did give a 30 day requirement for conducting an investigation. At that time, my client was reluctant and still is reluctant to conduct an investigation at a site that poses very little threat to the environmental from the diesel tank and there is an overwhelming concern regarding the contamination from the 2 very large MGP gas holders adjacent to this former tank. Ron requested deadline extension as waiting for ConEd documents. 09/14/09-Hiralkumar Patel. 11:16 AM:- spoke with Ron. he found two access agreement between owner and ConEd and after further investigation, he found that ConEd did some soil investigation on site. and he is waiting for investigation report. based on this information, approved his request to extend deadline. asked Ron to submit report or soil sample data (with site map including sampling locaitons) by the end of 09/28/09

515 W 18 ST (Continued) **S104502660**

or else case will be referred to legal. 09/16/09-Hiralkumar Patel. 1:17 PM:- received email from Ron with site map and sample analyticals that he received from ConEd. Ron mentioned that according to Con Edison, they have prepared a site wide Remedial Action Plan to address the contamination on this property and all other properties related to the MGP plant. according to submitted site map: - 12 borings were advanced on site (MW-12A, MW-12B, SB-14, SB-14A, SB-208, SB-209, MW/SB-213, SB-214, SB-221, SB-222, SB-254 and SB-MTP-3) and two borings were advanced near property line (MW/SB-219 and SB-220) - boring MW-12A, MW-12B, MW/SB-213 and MW/SB-219 were converted into wells - strong petroleum odors noticed in soil from 5-10 ft bg in SB-214 (PID: 15 to 594 ppm), from 5-10 ft in SB-221 (PID: 11 to 222 ppm), from 5-10 ft in SB-220 (PID: 232 to 1583 ppm) and 7-19 ft in SB-14A (PID: 0-135 ppm) - high PID (217 to 514 ppm) found from 0-5 ft in SB-222 - solvent like odors noticed from 1-6 ft in SB-14A (PID: 96 to 244 ppm) - found 1,400 ppb benzene in groundwater sample from MW-12 <--------- - found soil contamination in some samples - samples were collected between 2004 and 2007 soil analtyicals:
----------SB-208------SB-209-----SB-221-----SB-222-----SB-222---
---SB-MTP-3 19-20 ft 19-20 ft 24-25 ft 1-3 ft 19-20 ft 24-25 ft
Benzene----------860-------2,100--------710--------390------4,
400---------6,700
Ethylbenzne----------2,400----------17,000------1,500
Xylene----------2,000----------160,000------1,300
Naphthalene----------42,000 after reviewing submitted sample analtyicals and previously submitted site map with approx. location of previous tanks at the site, it is found that strong petroleum odors noticed between 5 to 10 ft depth in area of previous diesel tanks and gasoline odors noticed in off-site boring SB-272 (between 6-7 ft). also heavy VOC contamination found in soil sample from 1-3 ft depth from boring SB-222 which is in area of previous diesel tanks. soil contamination found in deeper soil in other areas of site. 4:32 PM:- received email from Mr. Ottaway. he mentioned that ..I have taken a quick look at the submitted data. On the Roxy property, about half the boring logs were clean and the other half (SB-14A, SB-214, SB-221, SB-220) noted petroleum odors in the logs. None noted MGP contamination. The analytical results on this parcel showed relatively low levels of organic contamination, so I'm not sure how much of a problem this property represents. 09/17/09-Hiralkumar Patel. 2:34 PM:- spoke with Mr. Ottaway. he will review data again and will discuss with his supervisor regarding responsibility of remediation. discussed with DEC Austin. he mentioned that cleaning at MGP site requires extra precaution due to hazardous substances in ground. as per him, MGP issue is bigger than tank test failure/petroleum contamination from tank and as no immediate threat to occupants, he asked to wait for reply from Mr. Ottaway. he mentioned that no investigation/remediation required for leaking tank issue at this time. 09/22/09-Hiralkumar Patel. 4:13 PM:- received email from Mr. Ottaway. ...I reviewed the specific tests that you referenced SB-208 (18-20'), SB-209 (19-20'), SB-MPT-3 (24-25') and SB-222 (1-3'). The PAH results for the deeper tests were all quite low. PAHs are the most family of chemicals in highest concentration in MGP tar, so these results clearly show that there is not MGP tar in the immediate vicinity of these borings. In addition, the VOC analyses were predominantly benzene, with relatively little of the other VOCs typical of MGP tar. In short, I am skeptical that the benzene contamination in these 3 samples is attributable to MGP

515 W 18 ST (Continued) **S104502660**

related contamination. Looking at both SVOC and VOC results, the shallow contamination at SB-222 appears to be fairly typical of diesel or fuel oil contamination. The contamination on Lot 29 does not appear to have significantly impacted Lot 20, and I do not believe that this contamination should represent a significant complication in the remediation of the relatively small area of contamination in the vicinity of SB-222. 09/23/09-Hiralkumar Patel. spoke with DEC Austin about response from Mr. Ottaway. he wants to review file again next week and then will discuss with Mr. Ottaway and Mr. Cross. 05/17/10-Hiralkumar Patel. after revewing available information, DEC Austin required for soil/groundwater investigation by property owner and mentioned that the case will not be transferred to MGP case manager in Albany. 4:29 PM:- left message for Mr. Taffel. 09/13/10-Hiralkumar Patel. 12:51 PM:- left message for Mr. Taffel. 12:53 PM:- left message for Ron. 10/20/10-Hiralkumar Patel. 10:13 AM:- received email from Ron including review of analysis of soil/groundwater samples collected by ConEd's consultant. Ron claimed that contamination found under the site is mixed from former diesel tanks and previous MGP use of the site, based on following: - soil under the site is sand and black, organic, clayey silt - groundwater found at average 9 ft depth - fomer diesel oil tanks were six ft in diameter and tanks were two ft below grade, so tank bottom was around 8 ft bg - bottom of gas holders on adjacent lot 29 were at 18.5 ft bg (Holder #4) and at 20 ft bg (Holder #3) - high contamination found at 20 ft depth (about 12 ft below water table) reviewed previously submitted SVOC and VOC data. VOC compounds found in deeper soil but no SVOC compounds. as there were no SVOCs found in deeper soil, DEC Ottaway does not believe that contamiantion on lot 29 has impacted site on lot 20. 10/28/10-Hiralkumar Patel. 10:10 AM:- left message for DEC Ottaway. 10/29/10-Hiralkumar Patel. 3:27 PM:- spoke with DEC Ottaway. he has spoke with his supervisor and waiting for response. Ottaway will send written response about findings of soil investigation. 11/30/10-Hiralkumar Patel. 2:18 PM:- left message for (and sent email to) DEC Ottaway. 12/07/10-Hiralkumar Patel. 11:10 AM:- spoke with DEC Ottaway. he is waiting for response from his supervisor. 12/09/10-Hiralkumar Patel. 1:29 PM:- received email from DEC Ottaway. 01/05/11-Hiralkumar Patel. discussed with DEC Austin. he mentioned that the department requires complete soil delineation around the diesel tanks and remediation of contamination. 11:51 AM:- left message for Ron informing that the department requires soil/gw delineation. 01/20/11-Hiralkumar Patel. 2:17 PM:- left message for Mr. Taffel informing that the department requires soil/gw delineation as per letter dated 08/06/2009. 2:20 PM:- spoke with Ron. he mentioned that recently Verizon has signed a six year lease and just moved in. Ron doesn't know when will the property be sold. 04/19/11-Hiralkumar Patel. 11:05 AM:- left message for Ron. 11/30/11-Hiralkumar Patel. 2:52 PM:- left message for Ron. 2:54 PM:- left message for Mr. Taffel. 3:10 PM:- received message from Ron. 3:55 PM:- sent letter to Mr. Taffel requiring submission of an investigation report (for soil/gw delineation as per letter dated 08/06/09) by the end of 01/31/12. letter emailed to Mr. Taffel and Ron. 3:57 PM:- email sent to Mr. Taffel came back. 12/06/11-Hiralkumar Patel. 2:01 PM:- received call from Ron. he mentioned that Mr. Taffel is sick and may not have seen the letter. he will talk to Mr. Taffel and will submit response. 01/13/12-Hiralkumar Patel. 10:27 AM:- received email from Ron. he mentioned that Mr. Taffel has agreed to perform the site

515 W 18 ST (Continued) **S104502660**

investigation. they have reached an access agreement with the tenant (Verizon) and have scheduled the drilling of borings/monitoring wells for 01/23/12. Ron asked for time extension to submit report. he proposed to submit report by 03/15/12. 11:09 AM:- sent email to Ron. asked him to submit an investigation work plan (including map showing former tank and proposed boring/well locations), prior to any approval for time extension. 11:55 AM:- received message from Ron. 1:26 PM:- spoke with Ron. he will send work plan for review. 4:20 PM:- received work plan from Ron. abstract: - total of eight soil borings will be installed to a maximum depth of 20 ft bg - one soil sample will be collected from each boring based on visual/olfactory/PID evidence of contamination or else at soil/water interface - based on previous investigations, groundwater elevation is approx. 8-10 ft bg - previous investigation activities suggets that groundwater flow direction is likely towards the west - six soil borings will be converted to 2 inch diameter wells - will collect water samples from existing wells MW/SB-219, MW/SB-224 and MW-7, if found and accessible 01/17/12-Hiralkumar Patel. 11:26 AM:- sent work plan approval letter to Mr. Taffel and asked to submit investigation report by 03/15/12. letter emailed to Mr. Taffel, Ron, Leonard Morrow (lmpc@verizon.net - tenant) and Barry (barry@mendonleasing.com). 03/15/12-Hiralkumar Patel. Phase II report was hand-delivered. abstract: - installed eight soil borings to maximum depth fo 20 ft bg - fill material extended from approx. 5 to 20 ft bg, described as brown fine to medium sand with debris including gravel, concrete, brick, glass and wood - native soils were identified below fill material and were typically brown, fine to medium sand and varying amounts of silt - silt area was followed by gray clay which was also identified at approx. 19 to 20 ft bg - bedrock was not encountered - bedrock is reportedly located from 60-80 ft bg - six of the soil borings were converted to 2 inch monitoring wells - groundwater found between 8 and 9.5 ft bg <---------- - based on well survey, groundwater flow is toward the southwest <---------- - three existing monitoring wells (MW-7A, MW-224 and MW-219) and six newly installed monitoring wells (MW-1 through MW-6) were sampled - well MW-7A located near the corner of 10th ave and 19th St - well MW-224 located southeast of the site near the corner of 10th ave and 18th st - well MW-219 located int he sidewalk on the north side of 18th st near the subject site building - found high PID readings and petroleum odors in borings - SB-1: 0.3 to 1,185 ppm with max at 5-10 ft bg; water at 8.05-8.15 ft bg - SB-2: 8.7 to 98 ppm with max at 5-10 ft bg; water at 8.70-8.86 ft bg - SB-3: 73 to 1,485 ppm with max at 5-7 ft bg; water at 8.90-9.0 ft bg - SB-4: 3 to 217 ppm with max at 7-9 ft bg; water at 8.70-8.75 ft bg - SB-5: 8 to 1,658 ppm with max at 9-11 ft bg; water at 8.70-8.76 ft bg - SB-6: 7 to 878 ppm with max at 11-13 ft bg; water at 9.30-9.30 ft bg - SB-7: 6 to 348 ppm with max at 7-9 ft bg - SB-8: 2 to 124 ppm with max at 7-11 ft bg - found VOCs and SVOCs in soil samples - found mostly Benzene in groundwater samples, with other VOCs below 44 ppb soil analyticals: ----------SB-3----------SB-5 6-6.5 ft 9-9.5 ft Toluene----------1,200 Ethylbenzene----------7,400 Xylene----------68,000 1,2,4-Trimethylbenzene------49,000 1,3,5-Trimethylbenzene------18,000 Naphthalene----------20,000 n-Propylbenzene----------5,500----------7,100 groundwater analyticals: ----------MW-1----MW-2----MW-3----MW-4----MW-5----MW-6----MW-224---- MW-7A

515 W 18 ST (Continued) **S104502660**

Benzene-------50-----350-----120------83------30------16--------32----
---23 04/03/12-Hiralkumar Patel. discussed with DEC Austin. based on available data and based on earlier response from DEC Ottaway, Austin asked for remediation of contamination. he also asked to resampling of existing wells as found high Benzene around diesel tank area. 3:11 PM:- spoke with Ron. informed him that the department requires resampling of existing monitoring well and remediate the soil contamination. he agreed for resampling of wells, but did not agreed on remediation of soil contamination. he mentioned that diesel tanks must have leaked and caused contamination, but it is localized and there is much bigger MGP waste issue. he mentioned that cleanup of diesel contamination can be achieved together with cleanup of MGP waste. he also mentioned that the subject site is part of ConEd's MGP cleanup area and the site is referred as Area 2. he will send copy of document showing the subject site as part of ConEd's MGP investigation. during conversation, Ron mentioned that Mendy Taffel has passed away and he will send contact info of his son who is handling the site now. 3:29 PM:- spoke with Richard Dana, new project manager of MGP site in Albany. he mentioned that ConEd has recently started working in this area. he will talk to DEC Ottaway, previous project manager and review availabe document. asked him to send contact details of project manager at ConEd. Richard Dana NYS DEC Ph. (518) 402-9662 4:51 PM:- received message from DEC Dana. he could not find coned's report for 2007 data and was looking for a copy, if available. 04/05/12-Hiralkumar Patel. 6:52 AM:- received email from Ron. he requested a written requirement for groundwater re-sampling. he also sent contact info of owner-in-charge. Barry Haskell **property owner's representative** Semantic Realty LLC. 362 Kingsland Avenue Brooklyn, NY 11222 Ph. (718) 391-5300 email: barry@mendonleasing.com 5:02 PM:- received email from DEC Dana. he reviewed available data (for the subject site) and concluded that there is no overlap in depths, where petroleum contamination (shallow) and MGP contamination (deep), are identified. 04/16/12-Hiralkumar Patel. 4:39 PM:- sent email to Ron. informed him that the department requires re-sampling of existing monitoring wells. asked him to submit schedule for well sampling. also asked him to submit document confirming that the subject site is part of ConEd's MGP clenaup area. email copied to Mr. Haskell. 04/17/12-Hiralkumar Patel. received email from Ron (at 7:49 PM on 04/16/12). he asked for a letter for re-sampling of existing wells. he will send coned's report regarding the subject site. 04/23/12-Hiralkumar Patel. 1:58 PM:- sent letter to Mr. Haskell requiring analysis (via 8260) of groundwater samples from the existing monitoring wells MW1 through MW6. asked him to submit report by 05/31/12. letter emailed to Ms. Haskell and Ron. 04/24/12-Hiralkumar Patel. received email from Ron (at 9:00 PM on 04/23/12) including report summary and map prepared by TRC as part of MGP investigation for ConEd. report mentioned that the subject site is included in Area 2 of the MGP investigation. reviewed submitted map with soil sample analyticals. one boring SB-14 and two wells MW-12A and MW-12B were installed on lot 20. minor SVOC contamination detected in soil from 4-5 ft depth in boring SB-14 and only 110 ppb Benzene detected in soil sample from 25-27 ft depth in boring SB-12. Ron suggested to include off-site wells MW-7A and MW-224 also. due to access issue with on-site tenant, he requested to extend time (to 06/30/12 instead of 05/31/12) for submission of groundwater sampling report. 05/02/12-Hiralkumar Patel. 1:50 PM:- sent email to Ron.

515 W 18 ST (Continued) **S104502660**

approved his request to submit report by 06/30/12. email copied to Mr. Haskell and Amy Edwards (Amy.Edwards@hklaw.com). 08/20/12-Hiralkumar Patel. 11:38 AM:- spoke with Ron regarding groundwater sampling report. he mentioned that report was sent in first week of July 2012. he will send copy again. 08/23/12-Hiralkumar Patel. 6:09 AM:- received email from Ron including groundwater sample results. Benzene found in groundwater samples. groundwater analyticals:
----------MW-1----MW-2----MW-3----MW-4----MW-5----MW-6----MW-224
Benzene-------49-----180-----220-----180------71------14--------20
01/11/13-Hiralkumar Patel. 12:52 PM:- left message for DEC Richard. 2:12 PM:- spoke with DEC Richard. he mentioned that as part of VCP cleanup, RP is required to do soil-vapor sampling and vapor mitigation is required based on the results. after discussion with DEC Austin, DEC Vought and DEC Dana, case closed based on following: - age of spill (spill reported in Jan. 1997) - status of on-site tanks (old tanks which failed test were removed and most recent tank has been abandoned in ground) - type of subsurface soil (clayey silt, organic) - findings of only benzene in groundwater (some other compounds but at minor levels) regardless of other BTEX compounds in soil above water table and - requirement of soil-vapor sampling as part of VCP project (V00530) 2:30 PM:- sent spill closure letter to Ms. Haskell. letter emailed to Mr. Haskell and Ron."

Remarks: "THE CALLERS COMPANY WAS HIRED TO REPLACE 2 1500 GALLON TANKS WITH 1 4000 GALLON TANK AND THEY DISCOVERED CONTAMINATED SOIL AROUND THE AREA OF THE TANKS - SOIL IS BEING EXCAVATED"

All Materials:

Site ID:	178360
Operable Unit ID:	1039877
Operable Unit:	01
Material ID:	340667
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

U401 **MENDON LEASING CORP** **RCRA NonGen / NLR** **1004759829**
NW **515 W 18TH ST** **FINDS** **NYR000022665**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.111 mi. **NY MANIFEST**
587 ft. **Site 9 of 15 in cluster U** **NY COOLING TOWERS**

Relative: **Lower**
Actual: **9 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	MENDON LEASING CORP	
Handler Address:		515 W 18TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYR000022665
Contact Name:		RICHARD RICCO
Contact Address:		W 23RD ST
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		212-255-0900

MENDON LEASING CORP (Continued) **1004759829**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 23RD ST
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	COTARD REALTY ASSOCIATES
Owner Type:	Private
Operator Name:	COTARD REALTY ASSOCIATES
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

MENDON LEASING CORP (Continued) **1004759829**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F005
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	COTARD REALTY ASSOCIATES
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	362 KINGLAND AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11222
Owner/Operator Telephone:	718-389-2100
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

MENDON LEASING CORP (Continued) **1004759829**

Owner/Operator Indicator:	Owner
Owner/Operator Name:	COTARD REALTY ASSOCIATES
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	362 KINGLAND AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11222
Owner/Operator Telephone:	718-389-2100
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	COTARD REALTY ASSOCIATES
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	362 KINGLAND AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11222
Owner/Operator Telephone:	718-389-2100
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: MENDON LEASING CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: MENDON LEASING CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19960424
Handler Name: MENDON LEASING CORP	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

MENDON LEASING CORP (Continued) **1004759829**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004524211

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004759829
Registry ID: 110004524211
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004524211
Name: MENDON LEASING CORP
Address: 515 W 18TH ST
City,State,Zip: NEW YORK, NY 10011

NY MANIFEST:
Name: MENDON LEASING
Address: 515 W 18TH ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYR000022665
Facility Status: Not reported
Location Address 1: 515 W 18TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: 2822

MENDON LEASING CORP (Continued) **1004759829**

NY MANIFEST:

EPAID:	NYR000022665
Mailing Name:	MENDON LEASING
Mailing Contact:	GEORGE TAKO
Mailing Address 1:	515 W 18TH ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	2822
Mailing Country:	USA
Mailing Phone:	N/S

COOLING TOWERS:

Name:	Not reported
Address:	515 WEST 18TH STREET
City,State,Zip:	NEW YORK, NY 10011
Equipment Unique ID:	14612
Equipment Borough:	Manhattan
Intended Use:	Air Conditioning
Manufacturer:	Marley
Model:	NC8405QCN2
Cooling Capacity:	733
Cooling Capacity Unit:	Tonnage
Commissioned Date:	11/16/2020
Inspection Date:	11/16/2020
Date of Bacteriological Collection:	11/18/2020
Date of Legionella Collection:	11/18/2020
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	40.744921
Longitude:	-74.007061

U402 **MENDON LEASING CORP.** **NY LTANKS** **S102232664**
NW **515 WEST 18TH STREET** **N/A**
< 1/8 **NYC, NY**
0.111 mi.
587 ft. **Site 10 of 15 in cluster U**

Relative:
Lower

Actual:
9 ft.

LTANKS:

Name:	MENDON LEASING CORP.
Address:	515 WEST 18TH STREET
City,State,Zip:	NYC, NY
Spill Number/Closed Date:	9514181 / 2009-03-18
Facility ID:	9514181
Site ID:	235191
Spill Date:	1996-02-07
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	hrpatel
Referred To:	Not reported
Reported to Dept:	1996-02-07
CID:	205
Water Affected:	Not reported

MENDON LEASING CORP. (Continued) **S102232664**

Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-02-07
Spill Record Last Update:	2009-03-18
Spiller Name:	TOM FASINI
Spiller Company:	MENDON LEASING CORP.
Spiller Address:	515 WEST 18TH STREET
Spiller County:	001
Spiller Contact:	TOM FASINI
Spiller Phone:	(718) 389-2100
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	193722
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MULQUEEN ORIGINALLY ASSIGNED TO MARTINKAT - FILE TRANSFERRED TO MULQUEEN 06/16/06: This spill is transferred from Mike Mulqueen to Mr. Koon Tang. 03/18/09-Hiralkumar Patel. spill closed. refer to spill #: 9612012."
Remarks:	"tank test faliure."

All TTF:

Facility ID:	9514181
Spill Number:	9514181
Spill Tank Test:	1544391
Site ID:	235191
Tank Number:	4n5
Tank Size:	1500
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	01
Test Method 2:	Petro-Tite/Petro Comp
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

U403 **515 W 18TH ST** **NY UST** **U003159461**
NW **515 WEST 18TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.111 mi.
587 ft. **Site 11 of 15 in cluster U**

Relative: **Lower**
Actual: **9 ft.**

UST:

Name:	515 W 18TH ST
Address:	515 WEST 18TH STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-032212 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2

515 W 18TH ST (Continued) **U003159461**

Expiration Date:	N/A
UTM X:	583840.41054
UTM Y:	4510917.30526
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	196
Affiliation Type:	Mail Contact
Company Name:	COTARD REALTY ASSOCIATES
Contact Type:	Not reported
Contact Name:	THOMAS P. FASINI
Address1:	362 KINGSLAND AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 391-5300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2004-10-14

Site Id:	196
Affiliation Type:	Facility Operator
Company Name:	515 W 18TH ST
Contact Type:	Not reported
Contact Name:	MENDON LEASING CORP.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 255-0900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2004-10-14

Site Id:	196
Affiliation Type:	Emergency Contact
Company Name:	COTARD REALTY ASSOCIATES
Contact Type:	Not reported
Contact Name:	THOMAS P. FASINI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 795-1197
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2004-10-14

Site Id: 196

515 W 18TH ST (Continued) **U003159461**

Affiliation Type:	Facility Owner
Company Name:	COTARD REALTY ASSOCIATES
Contact Type:	PRESIDENT
Contact Name:	BARRY J HASKELL
Address1:	362 KINGSLAND AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 391-5300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2004-10-14

Tank Info:

Tank Number:	012A
Tank ID:	51735
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	1500
Install Date:	Not reported
Date Tank Closed:	01/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number:	012B
Tank ID:	51736
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	1500
Install Date:	Not reported
Date Tank Closed:	01/01/1997

515 W 18TH ST (Continued) **U003159461**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number: 123A
Tank ID: 51737
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 02/01/1996
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number: 123B

515 W 18TH ST (Continued) **U003159461**

Tank ID:	51738
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	01
Date Test:	02/01/1996
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	123C
Tank ID:	51739
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	01
Date Test:	02/01/1996
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

515 W 18TH ST (Continued) **U003159461**

J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number:	12C
Tank ID:	54368
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	05/01/1997
Date Tank Closed:	11/08/2004
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)

S404 **CON EDISON** **RCRA NonGen / NLR** **1019904972**
SSW **HUDSON ST & W 14TH ST** **NYP004804290**
< 1/8 **NEW YORK, NY 10013**
0.111 mi.
588 ft. **Site 15 of 18 in cluster S**

Relative: **Higher**

Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150709
Handler Name:	CON EDISON	
Handler Address:		HUDSON ST & W 14TH ST
Handler City,State,Zip:		NEW YORK, NY 10013
EPA ID:		NYP004804290
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported

CON EDISON (Continued) **1019904972**

EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported

CON EDISON (Continued) **1019904972**

Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150709
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150709
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

S405 **CON EDISON** **NJ MANIFEST** **S120673663**
SSW **HUDSON ST & W 14TH ST** **N/A**
< 1/8 **NEW YORK, NY 10013**
0.111 mi.
588 ft. **Site 16 of 18 in cluster S**

Relative:
Higher

Actual:
16 ft.

NJ MANIFEST:

EPA Id:	NYP004804290
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002614475GBF
EPA ID:	NYP004804290
Date Shipped:	7/9/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120673663**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

S406 **CON EDISON** **NY MANIFEST** **S117315538**
SSW **HUDSON ST & W 14 ST** **N/A**
< 1/8 **NEW YORK, NY 10014**
0.111 mi.
588 ft. **Site 17 of 18 in cluster S**

Relative:
Higher

Actual:
16 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	HUDSON ST & W 14 ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004627162
Facility Status:	Not reported
Location Address 1:	HUDSON ST & W 14 ST
Code:	BP
Location Address 2:	MH37466
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004627162
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/13/2014
Trans1 Recv Date:	08/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/18/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004627162
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S117315538**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002608791GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AB407 **SPILL NUMBER 0104249** **NY Spills** **S105140233**
NE **360 WEST 22ND ST** **N/A**
< 1/8 **NEW YORK, NY**
0.113 mi.
598 ft. **Site 1 of 10 in cluster AB**

Relative: SPILLS:
Higher

Name:	SPILL NUMBER 0104249
Address:	360 WEST 22ND ST
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0104249 / 2001-08-07
Facility ID:	0104249
Facility Type:	ER
DER Facility ID:	111440
Site ID:	129261
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	2001-07-01
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2001-07-20

Actual:
17 ft.

SPILL NUMBER 0104249 (Continued) **S105140233**

CID:	405
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-07-20
Spill Record Last Update:	2001-08-07
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	ZAZEL LAVEN
DEC Memo:	""
Remarks:	"caller states that for a month now there is a truck that has boiling water spilling out of the rear of the truck"

All Materials:

Site ID:	129261
Operable Unit ID:	842684
Operable Unit:	01
Material ID:	532747
Material Code:	0065A
Material Name:	unknown non-petro/non-haz material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

T408 **CON EDISON** **NY MANIFEST** **S117067160**
SE **325-323 W 17 ST & 9 AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.113 mi.
599 ft. **Site 10 of 20 in cluster T**

Relative: **Higher**
Actual: **18 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	325-323 W 17 ST & 9 AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004599007
Facility Status:	Not reported
Location Address 1:	325-323 W 17 ST & 9 AVE
Code:	BP
Location Address 2:	SB 3014
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

CON EDISON (Continued) **S117067160**

NY MANIFEST:

EPAID:	NYP004599007
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/16/2014
Trans1 Recv Date:	07/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/18/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004599007
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002422130GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S117067160**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AA409 **CON EDISON** **NJ MANIFEST** **S120666715**
NNW **500 W 21ST ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.114 mi.
602 ft. **Site 6 of 24 in cluster AA**

Relative:
Lower

Actual:
11 ft.

NJ MANIFEST:

EPA Id:	NYP004725354
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610453GBF
EPA ID:	NYP004725354
Date Shipped:	2/4/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported

CON EDISON (Continued) **S120666715**

QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AA410 **CON EDISON** **NY MANIFEST** **S117739418**
NNW **500 W 21ST ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.114 mi.
602 ft. **Site 7 of 24 in cluster AA**

Relative: **Lower**
Actual: **11 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	500 W 21ST ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004725354
Facility Status:	Not reported
Location Address 1:	500 W 21 ST
Code:	BP
Location Address 2:	SB3769
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004725354
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047

CON EDISON (Continued) **S117739418**

Trans2 State ID:	Not reported
Generator Ship Date:	02/04/2015
Trans1 Recv Date:	02/04/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/09/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004725354
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610453GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AA411 **CON EDISON SB3769** **RCRA NonGen / NLR** **1018277796**
NNW **500 W 21ST ST** **FINDS** **NYP004725354**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.114 mi.
602 ft. **Site 8 of 24 in cluster AA**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20220125
Handler Name:	CON EDISON SB3769	
Handler Address:		500 W 21ST ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004725354
Contact Name:		THOMAS TEELING
Contact Address:		IRVING PL, 15TH FL NE

CON EDISON SB3769 (Continued) **1018277796**

Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No

CON EDISON SB3769 (Continued) **1018277796**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220125
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20220125
Handler Name: CON EDISON SB3769	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20150204
Handler Name: CON EDISON SB3769	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	Not reported
Recognized Trader Exporter:	Not reported
Spent Lead Acid Battery Importer:	Not reported
Spent Lead Acid Battery Exporter:	Not reported
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20170705
Handler Name: CON EDISON SB3769	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

CON EDISON SB3769 (Continued) **1018277796**

Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No
Receive Date:	20150204
Handler Name: CON EDISON SB3769	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	Not reported
Recognized Trader Exporter:	Not reported
Spent Lead Acid Battery Importer:	Not reported
Spent Lead Acid Battery Exporter:	Not reported
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067694105

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018277796
Registry ID:	110067694105
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067694105
Name:	CON EDISON SB3769
Address:	500 W 21ST ST
City,State,Zip:	NEW YORK, NY 10011

AA412 **CON EDISON SERVICE BOX: 3771** **RCRA NonGen / NLR** **1016149448**
NNW **W 21ST ST & 10TH AVE SB 3771** **FINDS** **NYP004281119**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.115 mi. **NY MANIFEST**
607 ft. **Site 9 of 24 in cluster AA**

Relative:
Lower

Actual:
11 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20130328
Handler Name:	CON EDISON SERVICE BOX:	3771
Handler Address:		W 21ST ST & 10TH AVE SB 3771
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004281119
Contact Name:		JOSE MONTALVO
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-427-1331
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 3771 (Continued) **1016149448**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130228
Handler Name: CON EDISON SERVICE BOX:	3771
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130328
Handler Name: CON EDISON SERVICE BOX:	3771
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 3771 (Continued) **1016149448**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055456233

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016149448
Registry ID:	110055456233
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055456233
Name:	CON EDISON SERVICE BOX: 3771
Address:	W 21ST ST & 10TH AVE SB 3771
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	CON EDISON
Address:	473 W 21ST ST & 10TH AVE SB 37
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004280889
Facility Status:	Not reported
Location Address 1:	350 ALBANY ST
Code:	BP
Location Address 2:	SOUTH END AVE
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10006
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004280889
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING

CON EDISON SERVICE BOX: 3771 (Continued) **1016149448**

Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	12/20/2012
Trans1 Recv Date:	12/20/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/27/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004280889
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010707064JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON SERVICE BOX: 3771 (Continued) **1016149448**

Name:	CON EDISON
Address:	W 21ST ST & 10TH AVE SB 3771
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004281119
Facility Status:	Not reported
Location Address 1:	F/O 467 W 21 ST & 10TH AVE
Code:	BP
Location Address 2:	SERVICE BOX # 3771
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004281119
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/28/2013
Trans1 Recv Date:	02/28/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/28/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004281119
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010708144JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

CON EDISON SERVICE BOX: 3771 (Continued) **1016149448**

MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AA413 **CON EDISON SERVICE BOX: 43089** **RCRA NonGen / NLR** **1016143020**
NNW **W 21ST ST & 10TH AVE SB 43089** **FINDS** **NYP004257499**
< 1/8 **NEW YORK, NY 10014** **ECHO**
0.115 mi.
607 ft. **Site 10 of 24 in cluster AA**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130320
Handler Name:	CON EDISON SERVICE BOX: 43089
Handler Address:	W 21ST ST & 10TH AVE SB 43089
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYP004257499
Contact Name:	JUAN RODRIGUEZ
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	347-865-5931
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported

CON EDISON SERVICE BOX: 43089 (Continued) **1016143020**

Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON SERVICE BOX: 43089 (Continued) **1016143020**

Historic Generators:

Receive Date:		20130220
Handler Name:	CON EDISON SERVICE BOX:	43089
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20130320
Handler Name:	CON EDISON SERVICE BOX:	43089
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055431723

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016143020
Registry ID: 110055431723

CON EDISON SERVICE BOX: 43089 (Continued) **1016143020**

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055431723
Name: CON EDISON SERVICE BOX: 43089
Address: W 21ST ST & 10TH AVE SB 43089
City,State,Zip: NEW YORK, NY 10014

U414 **555 WEST 17TH ST/MANH** **NY LTANKS** **S104275597**
WNW **555 WEST 17TH STREET** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.115 mi.
607 ft. **Site 12 of 15 in cluster U**

Relative: **Lower**
Actual: **7 ft.**

LTANKS:

Name:	555 WEST 17TH ST/MANH
Address:	555 WEST 17TH STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9006677 / 1990-09-19
Facility ID:	9006677
Site ID:	193520
Spill Date:	1990-09-18
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1990-09-19
SWIS:	3101
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1990-09-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-10-09
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	SILSID REALTY CO
Spiller Address:	P O BOX 443
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	161343
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG 09/19/90: VAULT TO BE CLEANED, TO CLEAN TANK & INSPECT FOR STRUCTURAL SOUNDNESS, TO TEST THE FILL PIPE & VENT PIPE, IF TANK FAILS INSPECTION TO REPLACE THE TANK. "
Remarks:	"5K TANK VAULTED, DRAIN PLUG OF TANK IS STRIPPED, OIL LEAKED OUT, SITE WAS INSPECTED, TANK WAS FOUND TO BE VERY RUSTY, PIPING WAS VERY OLD & RUSTY, OIL SOAKED DEBRIS FOUND IN TANK ROOM."

All Materials:

Site ID:	193520
Operable Unit ID:	947220
Operable Unit:	01

555 WEST 17TH ST/MANH (Continued) **S104275597**

Material ID:	434126
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Y415 **CON EDISON SERVICE BOX: 3629** **NJ MANIFEST** **S120666177**
East **320-318 W 20TH ST & 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.115 mi.
607 ft. **Site 2 of 12 in cluster Y**

Relative:
Higher

Actual:
19 ft.

NJ MANIFEST:

EPA Id:	NYP004507018
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002613758GBF
EPA ID:	NYP004507018
Date Shipped:	12/15/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

CON EDISON SERVICE BOX: 3629 (Continued) **S120666177**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Y416 **CON EDISON** **NY MANIFEST** **S117058575**
East **320-318 W 20TH ST & 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.115 mi.
607 ft. **Site 3 of 12 in cluster Y**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	320-318 W 20TH ST & 9TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004507018
Facility Status:	Not reported
Location Address 1:	320 W 20 ST & 9TH AVE
Code:	BP
Location Address 2:	SB 3629
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004507018
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported

CON EDISON (Continued) **S117058575**

Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/21/2014
Trans1 Recv Date:	04/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004507018
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416545GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

T417 **324 W 17 ST** **NY AST** **U003394952**
SE **324 WEST 17TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.115 mi.
607 ft. **Site 11 of 20 in cluster T**

Relative:
Higher

Actual:
19 ft.

AST:

Name:	324 W 17 ST
Address:	324 WEST 17TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-470139
Program Type:	PBS
UTM X:	584239.02376
UTM Y:	4510601.19767
Expiration Date:	11/15/2026
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	20573
Affiliation Type:	Facility Owner
Company Name:	322-24-26 WEST 17 STREET HDFC
Contact Type:	MANAGING AGENT
Contact Name:	JAMES MAISTRE
Address1:	322-326 W 17TH ST.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 799-2365
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-10-01

Site Id:	20573
Affiliation Type:	Facility Operator
Company Name:	324 WEST 17TH STREET
Contact Type:	Not reported
Contact Name:	CANDIDO MOLINA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 306-3556
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2006-09-11

Site Id:	20573
Affiliation Type:	Emergency Contact
Company Name:	322-24-26 WEST 17 ST HDFC % VERITAS PROP MGMT
Contact Type:	Not reported
Contact Name:	CANDIDO MOLINA

324 W 17 ST (Continued) **U003394952**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 306-3556
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-08-15

Site Id:	20573
Affiliation Type:	Mail Contact
Company Name:	VERITAS PROPERTY MGMT LLC
Contact Type:	Not reported
Contact Name:	JIM MAISTRE
Address1:	1995 BROADWAY
Address2:	SUITE 201
City:	NEW YORK
State:	NY
Zip Code:	10023
Country Code:	001
Phone:	(212) 799-2365
EMail:	JIMMY@VERITASMANAGEMENT.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-10-01

Tank Info:

Tank Number:	001
Tank Id:	37310
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	C01 - Pipe Location - Aboveground
	J00 - Dispenser - None
	G00 - Tank Secondary Containment - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	B00 - Tank External Protection - None
	F00 - Pipe External Protection - None
	H00 - Tank Leak Detection - None
	I05 - Overfill - Vent Whistle
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Concrete
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1980
Capacity Gallons:	5000
Tightness Test Method:	34
Date Test:	04/13/2021
Next Test Date:	Not reported

324 W 17 ST (Continued) **U003394952**

Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	10/01/2021
Material Name:	#2 fuel oil (on-site consumption)

AC418 **319 WEST 18TH ST. OWNERS CORP.** **NY AST** **U003388139**
ESE **319 WEST 18TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.115 mi.
608 ft. **Site 1 of 8 in cluster AC**

Relative:
Higher

Actual:
19 ft.

AST:

Name:	319 WEST 18TH ST. OWNERS CORP.
Address:	319 WEST 18TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-257834
Program Type:	PBS
UTM X:	584283.00122
UTM Y:	4510684.72519
Expiration Date:	07/10/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	10650
Affiliation Type:	Facility Operator
Company Name:	319 WEST 18TH ST. OWNERS CORP.
Contact Type:	Not reported
Contact Name:	MANUEL GONZALEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 526-1498
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2012-06-12

Site Id:	10650
Affiliation Type:	Emergency Contact
Company Name:	319 WEST 18TH ST. OWNERS, BUCHBINDER & WARREN
Contact Type:	Not reported
Contact Name:	ROBERT J. HALABOV
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 243-6722
EMail:	Not reported
Fax Number:	Not reported

319 WEST 18TH ST. OWNERS CORP. (Continued) **U003388139**

Modified By: MXLAY
Date Last Modified: 2018-02-22

Site Id: 10650
Affiliation Type: Mail Contact
Company Name: ABILENE, INC.
Contact Type: Not reported
Contact Name: FRANK YAN
Address1: 2402 NEPTUNE AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11224
Country Code: 001
Phone: (718) 372-4210
EMail: FRANK@ABILENEINC.COM
Fax Number: Not reported
Modified By: KXLIU
Date Last Modified: 2021-11-22

Site Id: 10650
Affiliation Type: Facility Owner
Company Name: 319 WEST 18TH ST. OWNERS, BUCHBINDER & WARREN
Contact Type: Not reported
Contact Name: Not reported
Address1: ONE UNION SQ. WEST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 243-6722
EMail: Not reported
Fax Number: Not reported
Modified By: MXLAY
Date Last Modified: 2018-02-22

Tank Info:

Tank Number: 001
Tank Id: 13234
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J05 - Dispenser - On Site Heating System (Supply/Return)
E00 - Piping Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
L99 - Piping Leak Detection - Other
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

319 WEST 18TH ST. OWNERS CORP. (Continued) **U003388139**

	G02 - Tank Secondary Containment - Vault (w/access)
	I05 - Overfill - Vent Whistle
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/18/1927
Capacity Gallons:	4000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MXLAY
Last Modified:	03/06/2018
Material Name:	#4 fuel oil (on-site consumption)

AA419 **CON EDISON SERVICE BOX: 3770** **RCRA NonGen / NLR** **1016149425**
NNW **473 W 21ST ST & 10TH AVE SB 3770** **NYP004280889**
< 1/8 **NEW YORK, NY 10011**
0.116 mi.
611 ft. **Site 11 of 24 in cluster AA**

Relative: RCRA NonGen / NLR:
Lower

Actual: Date Form Received by Agency:		20130328
11 ft. Handler Name:	CON EDISON SERVICE BOX:	3770
Handler Address:		473 W 21ST ST & 10TH AVE SB 3770
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004280889
Contact Name:		JOSE MONTALVO
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-427-1331
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No

CON EDISON SERVICE BOX: 3770 (Continued) **1016149425**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130228
Handler Name: CON EDISON SERVICE BOX:	3770
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

CON EDISON SERVICE BOX: 3770 (Continued) **1016149425**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20130328
Handler Name: CON EDISON SERVICE BOX:	3770
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AA420 **CON EDISON SERVICE BOX: 3770** **NJ MANIFEST** **S117987195**
NNW **W 21ST ST & 10 TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.116 mi.
611 ft. **Site 12 of 24 in cluster AA**

Relative: **Lower**
Actual: **11 ft.**

NJ MANIFEST:

EPA Id:	NYP004280889
Mail Address:	Not reported
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JOSE MONTALVO
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:
Manifest Number: 010707064JJK

CON EDISON SERVICE BOX: 3770 (Continued) **S117987195**

EPA ID:	NYP004280889
Date Shipped:	12/20/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	3,000.00 Pounds

AA421 **CON ED MANHOLE 43089** **NY Spills** **S128170666**
NNW **10TH AVE AND W 21ST ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.116 mi.
611 ft. **Site 13 of 24 in cluster AA**

Relative: **Lower**

Actual: **11 ft.**

SPILLS:

Name:	CON ED MANHOLE 43089
Address:	10TH AVE AND W 21ST ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	2106862 / 2022-02-15
Facility ID:	2106862
Facility Type:	ER
DER Facility ID:	572929
Site ID:	625774
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	2021-10-22
Investigator:	EJKIM
Referred To:	Not reported
Reported to Dept:	2021-10-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2021-10-22
Spill Record Last Update:	2022-02-15
Spiller Name:	ERT
Spiller Company:	UNKNOWN
Spiller Address:	10TH AVE AND W 21ST ST
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"10/25/21-Hiralkumar Patel. received updated emis report from ConEd. product sample analysis indicates the presence of substance similar to a lubricating oil. EMIS 282613 2/15/22 - Kim - On 10/22/21, Con Ed was working on Feeder 13M54, and discovered 1gal of unknown oil on the floor of Con Ed manhole MH-43089 that leaked in from a duct. Con Ed Lab Oil ID and analysis results (Con Ed approval date: 10/23/21) indicated the presence of a substance similar to a lubricating oil containing 2.00ppm PCB. On 10/26/21, Con Ed vendor Clean Harbors crew cleaned up the unknown oil in manhole MH-43089. Clean Harbors double-washed and rinsed the structure with the Safe Wash Technologies Solution. Clean Harbors used a Vactor to remove all wash water and debris. The waste was transported to Clean Earth of North Jersey for disposal. Con Ed inspected the structure after and found no visible oil or leaks. See document files for further information Spill closed end"
Remarks:	"LEAKING INTO MANHOLE"

All Materials:

Site ID:	625774
Operable Unit ID:	1372906

CON ED MANHOLE 43089 (Continued) **S128170666**

Operable Unit:	01
Material ID:	2386273
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AA422 **SW CORNER OF** **NY Spills** **S117393983**
NNW **WEST 21ST AND TENTH AVE** **N/A**
< 1/8 **MANHATTAN, NY**
0.116 mi.
611 ft. **Site 14 of 24 in cluster AA**

Relative: SPILLS:
Lower

Actual:
11 ft.

Name:	SW CORNER OF
Address:	WEST 21ST AND TENTH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	1409519 / 2015-06-04
Facility ID:	1409519
Facility Type:	ER
DER Facility ID:	458093
Site ID:	503154
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2014-12-21
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2014-12-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-12-21
Spill Record Last Update:	2015-06-04
Spiller Name:	RYDER CONTRACTING
Spiller Company:	K-VACK MECHANICAL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	THOMAS VITA
DEC Memo:	"6/4/15 TJD File review. Reassigned Ahmed to DeMeo. FDNY responded to antifreeze spill on roadway. No further action required. Spill closed."
Remarks:	"SPILL ONGOING, HAZ-MAT ATTEMPTING TO STOP. DEP CONTACTED FOR RESPONSE AS WELL."

SW CORNER OF (Continued) **S117393983**

All Materials:

Site ID:	503154
Operable Unit ID:	1252504
Operable Unit:	01
Material ID:	2254618
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	30.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

X423 **APARTMENT** **NY Spills** **S106719372**
South **335 WEST 14TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.116 mi.
615 ft. **Site 3 of 11 in cluster X**

Relative: **Higher**
Actual: **18 ft.**

SPILLS:

Name:	APARTMENT
Address:	335 WEST 14TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0401258 / 2004-05-06
Facility ID:	0401258
Facility Type:	ER
DER Facility ID:	153999
Site ID:	183989
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	D2
SWIS:	3101
Spill Date:	2004-05-05
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2004-05-05
CID:	41
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-05-05
Spill Record Last Update:	2004-05-06
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	NOBORU KAWABUCHI
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 5/6/04 tipple updating// I received a call from the hotline at

APARTMENT (Continued) **S106719372**

10PM on 5/5/04. It was a referral from the EPA. I returned the call of the Notifier Noboru Kawabuchi who reported that he believed that he was smelling poisons which were making him ill. I spent about 15 minutes on the phone with this gentleman attempting to gather enough details to be able to refer him to the correct agency and assure him that this situation would not be dropped. An hour and 20 minutes later when I was asleep, my Nextel phone rang, I awoke to Mr. Noboru Kawabuchi yelling into the phone accusing me of poisoning him. This is not a spill// no further action necessary"

Remarks: "TENANT SMELLS WHAT HE BELIEVES ARE POISONS, WHICH ARE MAKING HIM ILL. THE SMELL HAS BEEN AROUND FOR ABOUT 3 MONTHS. HE HAS HAD AUTHORITIES AT SCENE, BUT NOTHING IS BEING DONE. PER NOTIFIER, HE FEELS THE COMPLAINANT IS SINCERE."

All Materials:

Site ID:	183989
Operable Unit ID:	885331
Operable Unit:	01
Material ID:	492471
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

X424 **335-7 WEST 14TH STREET** **NY AST** **U003384301**
South **335-7 WEST 14TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10014**
0.116 mi.
615 ft. **Site 4 of 11 in cluster X**

Relative: **Higher**

Actual: **18 ft.**

AST:

Name:	335-7 WEST 14TH STREET
Address:	335-7 WEST 14TH STREET
City,State,Zip:	NEW YORK, NY 10014
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-090654
Program Type:	PBS
UTM X:	584142.83377
UTM Y:	4510395.21092
Expiration Date:	03/24/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	2223
Affiliation Type:	Mail Contact
Company Name:	335-7 LLC
Contact Type:	Not reported
Contact Name:	KENNETH NAGIN
Address1:	50 BANK ST
Address2:	Not reported
City:	NEW YORK
State:	NY

335-7 WEST 14TH STREET (Continued) **U003384301**

Zip Code:	10014
Country Code:	001
Phone:	(212) 243-7757
EMail:	JEFF@NTSMI.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-06-02

Site Id:	2223
Affiliation Type:	Facility Operator
Company Name:	335-7 WEST 14TH STREET
Contact Type:	Not reported
Contact Name:	SUPERIOR MANAGEMENT INC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 243-7757
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	2223
Affiliation Type:	Emergency Contact
Company Name:	335-7 LLC
Contact Type:	Not reported
Contact Name:	SUPERIOR MANAGEMENT INC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 243-7757
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	2223
Affiliation Type:	Facility Owner
Company Name:	335-7 LLC
Contact Type:	MANAGING AGENT
Contact Name:	KENNETH L. NAGIN
Address1:	50 BANK ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10014
Country Code:	001
Phone:	(212) 243-7757
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING

335-7 WEST 14TH STREET (Continued) **U003384301**

Date Last Modified: 2006-12-05

Tank Info:

Tank Number: 001
Tank Id: 3534
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 03/01/1960
Capacity Gallons: 3000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DMPOKRZY
Last Modified: 06/02/2017
Material Name: #2 fuel oil (on-site consumption)

AA425 **177-82 10TH AVE** **NY Spills** **S102961690**
NNW **BETWEEN 20TH & 21ST ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.117 mi.
617 ft. **Site 15 of 24 in cluster AA**

Relative: **Lower**
Actual: **11 ft.**

SPILLS:
Name: 177-82 10TH AVE
Address: BETWEEN 20TH & 21ST ST
City,State,Zip: MANHATTAN, NY
Spill Number/Closed Date: 9708598 / 2003-02-25
Facility ID: 9708598
Facility Type: ER
DER Facility ID: 87830
Site ID: 98764
DEC Region: 2
Spill Cause: Human Error
Spill Class: C3
SWIS: 2401
Spill Date: 1997-10-23

177-82 10TH AVE (Continued) **S102961690**

Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1997-10-23
CID:	257
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-10-23
Spill Record Last Update:	2003-02-25
Spiller Name:	HUGE GILLESPIE
Spiller Company:	EMPIRE CITY SUBWAY
Spiller Address:	177-82 10TH AVE
Spiller Company:	001
Contact Name:	HUGE GILLESPIE
DEC Memo:	""
Remarks:	"NO FURTHER DETAILS AS OF NOW SPILL IS BEING CONTAINED AND A SPILL CLEANUP TEAM IS ON THE WAY - CALLER THINKS SOME MIGHT HAVE GOTTEN INTO A DRAIN BUT NOT SURE YET"

All Materials:

Site ID:	98764
Operable Unit ID:	1055089
Operable Unit:	01
Material ID:	330559
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	55.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AD426 **CON EDISON SERVICE BOX: 2357** **RCRA NonGen / NLR** **1016449933**
SSW **408 W 14TH ST** **NY MANIFEST** **NYP004254066**
< 1/8 **NEW YORK, NY 10014**
0.118 mi.
621 ft. **Site 1 of 9 in cluster AD**

Relative: **Higher**
Actual: **14 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130318
Handler Name:	CON EDISON SERVICE BOX: 2357
Handler Address:	408 W 14TH ST
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYP004254066
Contact Name:	JUAN RODRIGUEZ
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	347-865-5931
Contact Fax:	Not reported
Contact Email:	Not reported

CON EDISON SERVICE BOX: 2357 (Continued) **1016449933**

Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported

CON EDISON SERVICE BOX: 2357 (Continued) **1016449933**

Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130218
Handler Name: CON EDISON SERVICE BOX:	2357
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130318
Handler Name: CON EDISON SERVICE BOX:	2357
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON

CON EDISON SERVICE BOX: 2357 (Continued) **1016449933**

Address:	408 W 14TH ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004254066
Facility Status:	Not reported
Location Address 1:	408 W 14TH ST
Code:	BP
Location Address 2:	SERV BOX 2357
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004254066
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/18/2013
Trans1 Recv Date:	02/18/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/19/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004254066
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840407JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110

CON EDISON SERVICE BOX: 2357 (Continued) **1016449933**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	560
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AD427 **CONSOLIDATED EDISON** **NY MANIFEST** **1009241675**
SSW **416 W 14 ST MH2355** **N/A**
< 1/8 **NEW YORK, NY 10027**
0.118 mi.
621 ft. **Site 2 of 9 in cluster AD**

Relative: **Lower**
Actual: **13 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	416 W 14 ST MH2355
City,State,Zip:	NEW YORK, NY 10027
Country:	USA
EPA ID:	NYP004101770
Facility Status:	Not reported
Location Address 1:	416 W 14 ST MH2355
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10027
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004101770
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Y428 **CHELSEA 19TH ST. OWNERS CORP.** **NY AST** **U003385430**
ESE **320 WEST 19TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.118 mi.
621 ft. **Site 4 of 12 in cluster Y**

Relative:
Higher

Actual:
19 ft.

AST:

Name:	CHELSEA 19TH ST. OWNERS CORP.
Address:	320 WEST 19TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-189421
Program Type:	PBS
UTM X:	584313.93523
UTM Y:	4510728.90838
Expiration Date:	06/05/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	5789
Affiliation Type:	Facility Owner
Company Name:	CHELSEA 19TH ST OWNERS CORP
Contact Type:	PROPERTY MANAGER
Contact Name:	ALEX RUBEN
Address1:	440 NINTH AVENUE, SUITE #1500
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 560-6400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-02-01

Site Id:	5789
Affiliation Type:	Mail Contact
Company Name:	CENTURY MANAGEMENT SERVICES
Contact Type:	Not reported
Contact Name:	ALEX RUBEN
Address1:	440 NINTH AVENUE
Address2:	SUITE #1500
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 560-6424
EMail:	ARUBEN@CENTURYNY.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-02-01

Site Id:	5789
Affiliation Type:	Facility Operator
Company Name:	CHELSEA 19TH ST. OWNERS CORP.
Contact Type:	Not reported
Contact Name:	JOEY CAUCHI

CHELSEA 19TH ST. OWNERS CORP. (Continued) **U003385430**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 401-2223
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-02-01

Site Id:	5789
Affiliation Type:	Emergency Contact
Company Name:	CHELSEA 19TH ST OWNERS CORP
Contact Type:	Not reported
Contact Name:	ALEX RUBEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 560-6424
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-02-01

Tank Info:

Tank Number:	001
Tank Id:	6418
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

	I05 - Overfill - Vent Whistle
	F00 - Pipe External Protection - None
	B00 - Tank External Protection - None
	C01 - Pipe Location - Aboveground
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	L00 - Piping Leak Detection - None
	J03 - Dispenser - Gravity
	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	K01 - Spill Prevention - Catch Basin
	E00 - Piping Secondary Containment - None
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/1950
Capacity Gallons:	3000

CHELSEA 19TH ST. OWNERS CORP. (Continued) **U003385430**

Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	02/01/2018
Material Name:	#4 fuel oil (on-site consumption)

R429 **PUBLIC SCHOOL 11 - MANHATTAN** **NY AST** **A100166660**
ENE **320 WEST 21ST STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.118 mi.
623 ft. **Site 4 of 6 in cluster R**

Relative:
Higher

Actual:
18 ft.

AST:

Name:	PUBLIC SCHOOL 11 - MANHATTAN
Address:	320 WEST 21ST STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-604515
Program Type:	PBS
UTM X:	584360.84233
UTM Y:	4510872.07384
Expiration Date:	05/12/2025
Site Type:	School

Affiliation Records:

Site Id:	26387
Affiliation Type:	Emergency Contact
Company Name:	NYC DEPT. OF EDUCATION
Contact Type:	Not reported
Contact Name:	KEN MAHADEO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 210-7918
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-03-18

Site Id:	26387
Affiliation Type:	Facility Operator
Company Name:	PUBLIC SCHOOL 11 - MANHATTAN
Contact Type:	Not reported
Contact Name:	JAMES FAVILLA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

PUBLIC SCHOOL 11 - MANHATTAN (Continued) **A100166660**

Phone:	(212) 929-1743
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2020-10-22

Site Id:	26387
Affiliation Type:	Facility Owner
Company Name:	NYC DEPT. OF EDUCATION
Contact Type:	MANAGER,FUEL DIVISION
Contact Name:	JOSEPH YOUNGHESE
Address1:	44-36 VERNON BOULEVARD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5751
EMail:	JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-03-09

Site Id:	26387
Affiliation Type:	Mail Contact
Company Name:	NYC DEPT. OF EDUCATION
Contact Type:	Not reported
Contact Name:	JOSEPH YOUNGHESE
Address1:	FIELD OPERATIONS-FUEL DIVISION
Address2:	44-36 VERNON BOULEVARD
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5779
EMail:	JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-01-25

Tank Info:

Tank Number:	001
Tank Id:	58045
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm

PUBLIC SCHOOL 11 - MANHATTAN (Continued) **A100166660**

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/2000
Capacity Gallons:	7500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	10/22/2020
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	58046
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/2000
Capacity Gallons:	7500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	10/22/2020

PUBLIC SCHOOL 11 - MANHATTAN (Continued) **A100166660**

Material Name: #2 fuel oil (on-site consumption)

R430 **NYC BD OF ED WILLIAM T HARRIS SCH PS 11M** **RCRA-VSQG** **1001968879**
ENE **320 W 21ST ST** **US AIRS** **NYR000080580**
< 1/8 **NEW YORK, NY 10011** **NY MANIFEST**
0.118 mi.
623 ft. **Site 5 of 6 in cluster R**

Relative: **Higher**
Actual: **18 ft.**

RCRA-VSQG:

Date Form Received by Agency:	20070101
Handler Name:	NYC BD OF ED WILLIAM T HARRIS SCH PS 11M
Handler Address:	320 W 21ST ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYR000080580
Contact Name:	WILLIAM SLADE
Contact Address:	W 21ST ST
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	914-681-6405
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 21ST ST
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	CITY OF NEW YORK
Owner Type:	Municipal
Operator Name:	CITY OF NEW YORK
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported

NYC BD OF ED WILLIAM T HARRIS SCH PS 11M (Continued) **1001968879**

2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CITY OF NEW YORK
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1 CENTRE ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10007
Owner/Operator Telephone:	212-669-8730
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner

NYC BD OF ED WILLIAM T HARRIS SCH PS 11M (Continued) **1001968879**

Owner/Operator Name:	CITY OF NEW YORK
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1 CENTRE ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10007
Owner/Operator Telephone:	212-669-8730
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CITY OF NEW YORK
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1 CENTRE ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10007
Owner/Operator Telephone:	212-669-8730
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name:	NYC BD OF ED WILLIAM T HARRIS SCH PS 11M
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	NYC BD OF ED WILLIAM T HARRIS SCH PS 11M
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20000327
Handler Name:	NYC BD OF ED WILLIAM T HARRIS SCH PS 11M
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

NYC BD OF ED WILLIAM T HARRIS SCH PS 11M (Continued) **1001968879**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

US AIRS MINOR:
Envid: 1001968879
Region Code: 02
Programmatic ID: AIR NY0000002620500337
Facility Registry ID: 110009487634
D and B Number: Not reported
Primary SIC Code: 8211
NAICS Code: 611110
Default Air Classification Code: MIN
Facility Type of Ownership Code: CTG
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002620500337
Facility Registry ID: 110009487634
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1999-11-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NY MANIFEST:
Name: WILLIAM T HARRIS SCHOOL
Address: 320 W 21ST ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYR000080580
Facility Status: Not reported
Location Address 1: 320 W 21ST ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK

NYC BD OF ED WILLIAM T HARRIS SCH PS 11M (Continued) **1001968879**

Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000080580
Mailing Name:	WILLIAM T HARRIS SCHOOL
Mailing Contact:	LINDA DELLA DONNA
Mailing Address 1:	123 MAIN ST
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	N/S

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/07/2015
Trans1 Recv Date:	08/07/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/07/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000080580
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014162165JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels

NYC BD OF ED WILLIAM T HARRIS SCH PS 11M (Continued) **1001968879**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Y431 **CON EDISON** **NY MANIFEST** **S117058573**
East **315-313 W 20TH ST & 9TH AVE** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.118 mi.
623 ft. **Site 5 of 12 in cluster Y**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	315-313 W 20TH ST & 9TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004506994
Facility Status:	Not reported
Location Address 1:	315 W 20 ST & 9TH AVE
Code:	BP
Location Address 2:	SB 3621
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004506994
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/21/2014
Trans1 Recv Date:	04/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

CON EDISON (Continued) **S117058573**

Generator EPA ID:	NYP004506994
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416547GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AA432 **EMPIRE CITY SUBWAY GARAGE** **NY Spills** **S108296336**
NNW **169 10TH AVE** **N/A**
< 1/8 **NEW YORK, NY**
0.119 mi.
626 ft. **Site 16 of 24 in cluster AA**

Relative: **Lower**

Actual: **11 ft.**

SPILLS:

Name:	EMPIRE CITY SUBWAY GARAGE
Address:	169 10TH AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0609814 / 2016-06-08
Facility ID:	0609814
Facility Type:	ER
DER Facility ID:	323857
Site ID:	374150
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	2006-11-28
Investigator:	AXDORONO

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

Referred To:	Not reported
Reported to Dept:	2006-11-28
CID:	408
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2006-11-28
Spill Record Last Update:	2016-06-08
Spiller Name:	Not reported
Spiller Company:	UNKOWN.
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	JEFF BOHLEN
DEC Memo:	"Sangesland spoke to Jeff at Envirotrack. They've done investigation work on the site and think its coming from next door. They will submit an investigation report to Patel for review. If this is a long term case (groundwater impacts) or part of another case (next door?) it will be reassigned to remediation. 01/02/07-Hiralkumar Patel. received call from Ellis Koch (PH. 631-389-2000 Ext. 282, Cell: 516-983-7333, Fax: 631-752-3008) from Metron Development Services, consultant working for potential buyer. Verizon ownes this property and empire city subway is tenant. property is on sell and Mr. Koch wanted to know that what work requires to close this case. told Mr. Koch that department requires site plan with sampling location and sample analyticals for review prior to any comments on cleanup requirements. he will send site plan and sample analyticals once he has it. he believes that this spill was related to old spill across a street in 1997. 01/03/07-Hiralkumar Patel. received subsurface investigation report from Envirotrac. Envirtract is consultant for owner. abstract: - phase I conducted in 2005 indicated the potential for USTs associated with the former heating units at the site - GPR survey was performed, but did not indiate the presence of any anomalies that could be associated with suspect USTs - subsurface investigation was based on the findings and conclusions presented in Phase-I report - off-site spill incidents related to former gasoline station at 152 10th ave and 161 10th ave - currently property is occupied by Empire City, a construction firm - site has active 3000 gal Diesel UST located within the building's garage area - according to Empire city, UST is double-walled fiberglass tank and is protected by an interstitial monitoring system - no spills or tank test failure associated with this tank - seven soil and groundwater samples taken from site - groundwater was encountered at depths ranging from approx. 9 to 10 ft bg - soil sample collected from immediately above the groundwater interface each boring location - monitoring wells were installed to an approx. depth of 15 ft bg - liquid-phase hydrocarbons (LPH) was not encountered in any of monitoring wells. gauging event was conducted during high tide on Nov. 20, 2006 - LPH was detected at a thickness of 0.82 ft in MW-3 during low tide on Nov. 28, 2006 - groundwater flow direction was determined westerly during high tide and southwesterly during low tide - few SVOC compounds found over limit in soil sample B-1 and B-4 - heavy VOC and

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

SVOC contamiantion found in groundwater samples MW-3 and MW-7 alternate addresses: 169-183 10th ave, 500 W 21st Street, 501 W 20th Street no other spill record found. PBS#: 2-604451 for 3000 gal UST. UST registered at 177-83 10th Ave address. 01/05/07-Hiralkumar Patel. spoke with DEC Austin. he asked to find details on site background, UST on site and buildings and any spill in surrounding area. spoke with Mr. Koch. he doesn't have Phase-I report. he asked to contact Jeff at Envirotrac. spoke with Jeffrey Bohlen at Envirotrac. he will send copy of Phase-I report in mail and site map with spill cases in surrouding area in email. Owner: Verizon Contact: Jerome Kung 221 East 37th Street 6th floor NY, NY 10016 Ph. (212) 338-6754 email: jerome.kung@verizon.com Jeffrey Bohlen Envirotrac Ph. (631) 924-3001 Fax (631) 924-5001 email: jeffb@envirotrac.com received email from Mr. Bohlen with site plan including surrounding area with past spills. site plan has following spill #s in surrounding area: ******** 9614310: 161-165 10Th AVE DEC Mulqueen inspected site. observed contaminated soil excavated for disposal. found hardpan clay at bottom of excavation and as per Mulqueen, this clay layer is possible barrier against additional vertical migration. no details on groundwater samples or endpoint samples from excavation. case closed. ******** 9210231: 152 10th Ave (old getty station) DEC O'Dowd asked Getty to install monitoring wells based on tank test failure complaint. three monirtoring wells installed. groundwater showed contamination. 173 ppb MTBE (MW-1), 1200 ppb MTBE (MW-2) and 1890 ppb MTBE (MW-3) DEC Vought reviewed closure report. entire lot has excavated to depth of 15 ft. removed 8850 tons of soil. groundwater concentration decreased after soil removal. case closed on 03/10/2004. ******** 0030004: 152 10th Ave (old getty station) spill reported after gasoline odors at site and in neighbours. case still open. ******** 0012876: 510 West 21St Street #2 oil spill. project manager: Andre Obligado spill reported because oil observed in sump and found broken supply and return lines. DEC ECO Smith issued violation for not vaccuming sumps as directed by DEC. 10 wells installed at site. NAPL present in groundwater. as of June 2004, 4000 gallons of total fluids removed includieng 128 gallons of NAPL. groundwater impact due to #2 oil in MW0, MW5 and MW6. in Feb. 06 another well installed based on soil contamiantion and found 1 ft of product. case still open. ******** 0010394: 511 West 21St Street Gasoline spill. project manager: Andre Obligado spill reported due to leaking product line. corrosion in fill line at fill port. Fenley & Nicol did soil investigatio and found soil contaminated. high contamination at SP3 with 93000 ppb MTBE and 2242 ppb benzene. did groundwater delineation. Greatest soil and ground water impacts detected west of dispensers and southwest of UST field (TW1/SB4). GW results in ppb from TW1 show 7327 benzene, 41,697 toluene, 2783 ethlybenzene, ~23500 total xylenes, 321,467 MTBE. case still open. ******** discussed with DEC Austin. he suggested more groundwater investigation off-site which has open spills (0012876 and 0010394). spoke with DEC Andre Obligado. he mentioned that he will get latest investigation data by end of Jan. 07. he will give copy of these reports. received Phase-I report from Mr. Bohlen from Envirotrac. abstract: - Certificate of Occupancy indicates that fuel oil storage tanks were present at subject property in 1946 - groundwater is estimated to occur at depth of 10 ft bgs - Empire city subway has occupied this property since 1977. prior to 1977, the building was utilized for truck repair - 3000 gal UST was installed in 1991 - all floor drains in the building are connected to one of the oil-water

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

separator - three self contained ASTs were indentified in maintenance area less than --------- - ASTs were in good condition, with no visible rust or corrosion - seven 55-gal drums were identified in maintenanace area - concrete floor under ASTs and in vicinity of drum area was in good condition - an inspection of the southern vault indicated that it was empty. a 1000 gal fuel oil AST had been removed from the vault in 1997 and building converted to gas heat less than -------- - inspection of northern vault indicated the presence of a gas-fired boiler - from 1950 Sanborn map: existing building at the site divided into two separate halves - the southwest and southeast corners of 10th ave and w 20th st are occupied by a gasoline station - two properties to the west are utilized as auto body/collision shops - tracks for an abandoned elevated railroad line are located above the auto body shops - as per sanborn map of 1895, manufactured gas plant (MGP) was located on 11th ave between 19th and 20th streets, on 10th ave between 18th and 19th street and on 18th street, east of 10th ave less than ------ - MGP doesn't exist on 1921 sanborn map - subject site is listed on NYC DEP database for City Environmental Quality Review (little E restricted) and for Underground Gasoline Storage Tanks Testing Protocol, which indicates that prior to redevelopment the NYCDEP may require soil and/or groundwater sampling less than ------- 01/10/07-Hiralkumar Patel. received message from Jeff from Envirotrac inquiring what work required at site regarding groundwater contamination. spoke with Jeff. explained him that there are three more open cases in neighbourhood which has soil/groundwater contaminated. told Jeff that the Department is waiting for latest investigation reports from these other sites and after reviewing these reports, the Department will ask responsible parties to do more investigation along boundries to check any migration to this Verizon site. asked him to wait till then. also asked him to notify buyer about contamination and possible remediation work in future at subject site. 02/20/07-Hiralkumar Patel. spoke with DEC Andre. he got analyticals for #2 oil spill site (spill# 0012876: 510 WEST 21ST ST, Manhattan). he will send letter requiring groundwater investigation between 510 West 21st STreet and 169 10th AVe sites. Andre is waiting for analyticals for gasoline spill site (spill# 0010394: 511 WEST 21ST ST, Manhattan). 05/08/07-Hiralkumar Patel. DEC Andre still waiting for data. 06/01/07-Hiralkumar Patel. recieved call from Jeff. Jeff mentioned that property closing will be done in Nov. 2007 and buyer of property is: Scott Resnick SNR Realty LLC 1100 E 59th Street New York, NY 10022 Ph. (212) 421-1960 10/31/07-Hiralkumar Patel. spoke with Mr. Kung at Verizon. he will check who really ownes this land. explained Mr. Kung that the department requires groundwater investigation as found contaminated groundwater in two wells. asked him for site specific groundwater flow direction at site. Mr. Kung will call back. spoke with DEC Andre. he mentioned that property at 510 W 21st street, which has #2 oil spill and contaminated groundwater, installed well on eastern side and found no product. also property at 511 W 21st street, where gasoline spill reported, found groundwater flowing in west direction (away from subject site at 169 10th ave). they also did tidal survey and found no change in groundwater flow direction. summary: - no product/contamination found in groundwater from well on eastern side of property at 510 w 21st street, which is close to well # 3 on subject site where found high naphthalene - groundwater at 511 w 21st street is flowing in west direction, away from well # 7 on subject site where found high MTBE

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

11/06/07-Hiralkumar Patel. received call from Jeff from Envirotrac. as per Jeff, Verizon still ownes the site, but will be out by end of Nov. 2007. explained to Jeff that the department requires site specific groundwater flow direction and complete groundwater delineation with off-site wells to confirm any contamination coming from off-site, if any. site specific groundwater direction was determined earlier and data showing that groundwater was flowing in two different directions. asked Jeff to survey existing wells again to confirm groundwater flow or variation in flow direction. and based on confirmed groundwater flow direction, need upgradient well to see any off-site contamination. 11/27/07-Hiralkumar Patel. spoke with Jeff at Envirotrac. he mentioned that there is new manager at verizon for the site. Empire City Subway Company Ltd. (subsidiary of Verizon) 199 Fulton Avenue 4th Floor Hampstead, NY 11550 Contact: John Quatrale Ph. (516) 292-8166 (O) (917) 846-4423 (C) email: john.n.quatrale@verizon.com from Dept. of State record, owner's address: Chairman or Chief Executive officer: Empire City Subway Company Limited W. Rober Mudge One Verizon Way, 4th Floor, Room # E204 Basking Ridge, NJ 07920 Principal Executive Office Empire City Subway Company Limited 140 West Street, Room # 1900 New York, NY 10007 sent letter to Mr. Quatrale requiring complete groundwater delineation (including upgradient well around previous well locations MW-3 and MW-7) and tidal survey at site. letter emailed to Mr. Quatrale and Jeff at Envirotrac. received call from Mr. Quatrale. Verizon has sold property and will be out of site in couple of weeks. Mr. Quatrale hesitate to install any further wells based on soil data and confirmed contamination in neighbouring properties. asked Mr. Quatrale to perform required work as stated in letter before pointing any site as source. also asked Mr. Quatrale to submit site map with all exisiting wells on sidewalk near site, towards area which looks like source of existing contamination. also asked to submit new owner's information. Mr. Quatrale also asked for letter to DOT requesting permit to remove diesel tank from site. spoke with DEC Austin regarding letter to DOT. Austin mentioned that as there is no soil or groundwater contamination where diesel tank is, no letter should be issued. sent email to Mr. Quatrale with this information. 12/26/07-Hiralkumar Patel. received call from Mr. Quatrale. they sold property and are out of site. as per sale agreement, new owner is taking responsibility of further work. asked Mr. Quatrale to provide new owner's information and confirmation letter from new owner regarding responsibility of investigation. Mr. Quatrale will call back after Jan. 2, 2008. 01/11/08-Hiralkumar Patel. received tank closure report from Envirotrac. abstrac: - removed one 3000 gal diesel UST, one diesel dispenser, one remote fill and associated subsurface piping - groundwater was encountered within the excavation at an approx. depth of 8 ft bg less than ------- - no holes or cracks were observed in tank or product piping - five endpoint samples collected - no contamination found in endpoint samples sent email to Mr. Quatrale requiring submission of groundwater investigation report (as per letter dated Nov. 27, 2007) also asked for confirmation letter from new owner regarding responsiblity of further investigation and any remediation. 01/14/08-Hiralkumar Patel. received email from Mr. Quatrale. as per Mr. Quatrale, Verizon Environmental management will do additional soil/groundwater investigation and currently working with new owner to get access for such investigation. new property owner is: Scott Resnick HLC Development Holdings, LLC. 375 Park Avenue, Suite 2703 New York, NY

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

10152 Ph. (212) 421-1960 FAx (212) 421-3095 email: SResnick@srcapitalnyc.com left message for Mr. Resnick. 01/17/08-Hiralkumar Patel. sent copy of letter, that was sent on 11/27/07 to old owner, to new owner. 03/25/08-Hiralkumar Patel. sent email to Mr. Quatrale and Mr. Resnick to submit updates. received email from Mr. Quatrale. they finished work and will submit report in two weeks. 04/08/08-Hiralkumar Patel. received investigation report from Jeff. abstract: - during UST removal, two newly-installed apparent monitoring wells were discovered in the sidewalks to the north and south of the site along west 20th and west 21st streets - the apparent monitoring well identified in the sidewalk of west 20th street was observed to include a manhole cover that resembles a fill port for a tank (but its not a fill port, but a well) less than --------- - installed twenty additional soil borings (B-8 through B-27) - installed tweleve additiona wells (MW-8 through MW-19) - groundwater was encountered at depths ranging from approx. 9 to 10 ft bg - soil sample collected from immeidately above the groundwater interface from the soil borings less than -------- - monitoring wells were installed to an approx. depth of 15 ft bg - groundwater flow direction was calculated to be to the west - analytical results revealed that the liquid phase hydrocarbons (LPH) samples from both MW-12 and MW-17 appear to be of an extremely weathered middle distillate, either diesel fuel or fuel oil. based on analytical report, the age of the LPH collected at MW-12 is estimated to be at least 18+/-2 years and the age of the LPH from MW-17 is estimated to be at least 19+/-2 years less than ---------- - groundwater samples were not collected at wells confirmed to contain LPH - only one soil sample found contaminated; B-19 where found 13,000 ppb Naphthalene - found free product in following wells ----------MW-3-----MW-9------MW-11-----MW-12-----MW-13-----MW-17----MW-18 product thickness------0.05-----0.01------0.47------1.02------0.01------0.03-----0.15 (in ft on 02/15/08) discussed with DEC Austin. he mentioned that as upgradient and downgradient wells are clean, there could be another source on the site. asked to review well logs to make sure proper depth of screen in each well. as per Phase I, site had three ASTs. sent email to Jeff to submit scaled site map with location of all tanks (including ASTs). reviewed tank closure report again. found that groundwater was encountered in tank excavation pit at 8 ft depth. and as per tank closure report, Envirotrac took five endpoint soil samples, but no groundwater sample was taken. no sample taken along underground lines and at remote fill port and dispenser island. from latest subsurface investigation report, found that wells MW-11 and MW-12 have highest thickness of product and both are located in middle of site. and there are no wells between previous diesel tank location and locations of MW-11 and MW-12. spoke with Jeff at Envirotrac. asked him about depht of previous tank invert. Jeff mentioned that tank was installed inside concrete box and groundwater was found right under concretre box. asked Jeff to submit depth of tank invert, excavation and endpoint samples. also asked him location of lines to/from tank. Jeff believes that lines were installed in two layers of concrete, but will confirm that. left message for Mr. Resnick to find future use of property. received call from Mr. Resnick. they are planning to redevelop this entire site. there will be hotel/residential building at site with 7 story above grade and about 1 or 2 levels below grade and as part of redevelopment they will excavate entire site below water table. sent

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

letter to Mr. Resnick and Mr. Quatrale requiring implementation of interim remedial measures (to remove product from wells) and soil/groundwater delineation via installation of monitoring well at previous diesel UST location. also asked to submit RAP including CAMP, endpoint samples, sampling of dewatering discharge (if occurs) and installation of vapor barrier and possible SSDS. letter emailed to Mr. Quatrale, Mr. Resnick and Jeff. 05/07/08-Hiralkumar Patel. received letter from Mr. Quatrale. as Verizon sold the property and as per sales agreement, new owner HLC development will do required remediation. 05/08/08-Hiralkumar Patel. received call from Frank from Roux associates. Frank requested deadline extension as current property owner just got possession. Frank is currently reviewing previous reports and will submit cost estmiates for future work. Frank is planning to start work by June 25th, 2008. asked Frank to call back by end of May, 2008 with updates about further work and based on that the department may approve their request. but asked Frank to gauge and recover any free product from wells, immediately. Frank Cherena Roux Associates Ph. (631) 232-2600 email: fcherena@rouxinc.com 05/09/08-Hiralkumar Patel. received email from Frank confirming above conversation. 05/22/08-Hiralkumar Patel. received call from Frank. they will install wells next week and will start gauging and recovery of any product from these wells. 07/10/08-Hiralkumar Patel. spoke with Frank at Roux. they are currently gauging and recovering product from one inch wells. still waiting for approval to install monitoring wells. asked Frank to submit report for work done till date with proposed well location map. left message for Mr. Resnick (new owner). 07/11/08-Hiralkumar Patel. left message for Mr. Resnick to submit work plan for well installation by end of 07/18/08. received call from Frank from Roux. he will submit gauging and product recovery result by end of 07/18/08 and will submit work plan for well installation by 07/31/08. approved his request. 07/23/08-Hiralkumar Patel. received monitoring well gauging report. abstract: - four weekly monitoring and product recovery events were completed from 06/19/08 to 07/15/08 - groundwater was observed to flow towards the Hudson river in a west-northwesterly direction - separate-phase petroleum product was observed in five of the 21 wells - appor. 0.50-0.75 gal of separate-phase petroleum product was removed during monitoring period - will submit work plan for installation of wells downgradient from previous tank location well monitoring results (depth of product in ft):
----------02/15/08-------06/19/08------06/25/08------07/02/08--------07/15/08
MW-3----------0.05----------0.02----------0.02----------0.02----------0.04
MW-11---------0.47----------1.05----------0.20----------0.51----------0.59
MW-12---------1.02----------2.03----------1.82----------1.65----------1.70
MW-13---------0.01----------0.34----------0.04----------0.04
MW-17---------0.03----------0.01
MW-18---------0.15----------1.03----------1.12----------0.84----------1.44 08/12/08-Hiralkumar Patel. received message from Matt Boeckel (631-249-3150) from Tyree environmental. spoke with Matt. they are preparing proposal for required work and he wanted to confirm what needs to be done. explained him that the department requires further groundwater delineation and remediation at the site.

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

09/18/08-Hiralkumar Patel. spoke with Matt at Tyree. he has submitted proposal but haven't heard yet. left message for Mr. Resnick. 09/19/08-Hiralkumar Patel. left message for Mr. Resnick. received message from Mr. Resnick's office. lady mentioned that Mr. Resnick doesn't own this property and asked to contact Mr. Neuringer. spoke with Mr. Neuringer. he mentioned that they are currently in planning phase and will not excavate site for at least six months. asked Mr. Neuringer to submit owner's contact info and consultant's contact info. Mr. Neuringer mentioned that they have copies of all previous reports and corrensponddence from the department and they are working on installation of additional wells. Mr. Neuringer asked to contact Tony Leichter, project manager in his office who will be point of contact. HLC Development LLC **current property owner** c/o CB Developers 565 5th Avenue New York, NY 10017 contact: Anthony Leichter **project manager and contact person** Ph. (212) 697-8601 x 225 (914) 659-1989 (C) email: wooster42@aol.com Shane Neuringer VP, Aquisitions & Development CB Developers 161 Chrystie Street, 2nd Floor New York, NY 10002 PH. (212) 505-5270 Fax (212) 260-7033 email: shane@cbdevelopers.com discussed with DEC Austin and DEC Urda. they both agreed to send STIP to all three parties: Verizon, HLC Development Holdings LLC. and HLC Development LLC. DEC Urda asked to send STIP letter to all three address of Empire city subway (verizon): Hampstead, Basking Ridge and Manhattan. 09/24/08-Hiralkumar Patel. ACRIS record shows that property was sold to HLC Development LLC only and there is no record of HLC Development Holdings LLC. spoke with Mr. Neuringer regarding property ownership. Mr. Neuringer mentioned that property transaction was between Empire city subway and HLC development LLC, but HLC Development HOlding LLC was partner in new ownership and then HLC Development Holdings sold their part to main company that is HLC Development LLC. 09/29/08-Hiralkumar Patel. from NYC DOB record found that site is little E restricted for hazmat/noise. multiple addresses: 169-175 10 Ave, 177-183 10 Ave, 500 W 21 St, 501 W 20 St sent email to Daniel Cole (Ph.: 718-595-4536, email: DanielCo@dep.nyc.gov) requesting project manager's information regarding this e site. spoke with Mr. Leichter at CB developers. he mentioned that currently site has vacant building and they are planning to build a hotel. 10/01/08-Hiralkumar Patel. spoke with Mr. Cole at DEP. he hasn't found any record yet. sent letter with STIP to Mr. Quatrale at Verizon, Mr. Resnick and Mr. Neuringer requiring further soil/groundwater delineation and submission of RAP according to previous letter dated 04/10/08. sent copy of previous letter with the STIP letter. letter emailed to Mr. Quatrale, Mr. Resnick, Mr. Neuringer and Mr. Cole. 10/06/08-Hiralkumar Patel. received call from Matt from Tyree. they have been hired by current property owner. Matt will submit site map with proposed well location and RAP based on groundwater investigation report. Matt Boeckel Tyree Ph. (508) 922-9044 (C) (631) 249-3150 Ext. 241 email: mboeckel@tyreeorg.com 10/09/08-Hiralkumar Patel. received signed STIP from HLC Development LLC. signed STIP forwarded to regional director for execution. 10/10/08-Hiralkumar Patel. received fully executed STIP from regional director. sent copy (mail and email) of final STIP to Mr. Neuringer. 10/17/08-Hiralkumar Patel. received message from Matt from Tyree. they are planning to install wells next week. 10/21/08-Hiralkumar Patel. left message for Matt to send site map with proposed well locations, before any drilling. 11/06/08-Hiralkumar Patel. received fax from Matt with proposed well locations. Matt proposed to install

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

four more wells: two wells between previous diesel tank and MW-12, one on northeast side of MW-12 and one southwest side of MW-18 along property boundry. left message for Matt. asked him to install one well at previous tank location itself. 11/14/08-Hiralkumar Patel. received message from Matt. left message for Matt. received call from Matt. he mentioned that due to presence of art gallary people inside building, they can't pump out product until first week of Dec. discussed with DEC Austin and he mentioned that the department can't wait such long as free product in well. spoke to Matt. and asked him to pump out product as per required schedule. he will send crew on monday 11/17/08. also asked to submit revised site map with proposed well locations. 11/25/08-Hiralkumar Patel. left message for Matt. left message for Mr. Neuringer. recived call from Matt. they are pumping out product from wells via small pump and will use vacuum truck next week. will send revised site map with proposed well locations and wells will be installed in second or third week of DEc. 08. receivec call from Mr. Neuringer and Mr. Leichter. they confirmed that revised map will be submitted today/tomorrow and will start well installation in next month. 11/26/08-Hiralkumar Patel. received revised site plan with proposed well locations. sent email to Matt, Mr. Neuringer and Mr. Leichter approving proposed well locations and asked Matt to notify a week before drilling. 12/05/08-Hiralkumar Patel. left message for Matt regarding well installation dates. 12/12/08-Hiralkumar Patel. left message for Matt regarding well installation dates. 01/16/09-Hiralkumar Patel. received weekly monitoring report from Tyree. increased product thickness was observed in all wells during monitoring on 11/21/08 and then product thickness reduced. no monitoring and product recovery happened from 07/15/08 to 11/21/08. found product in wells MW-09 and MW-14 where no product was found before 07/15/2008. will do weekly monitoring and product removal and will sample all wells by end of this month (quarterly sampling). Matt mentioned that they are waiting for third bid for well installation and will install well soon once contractor decided. he asked whether 2 inch wells acceptable. sent email to Matt requiring installation of 4 inch wells (as suspecting free product based on product in other wells). received email from Matt. due to space restriction in one of the proposed well location, inside office area, Matt asked if 2 inch well accpeted in one location. sent email to Matt approving installation of one 2 inch well and asked to put remaining 4 inch wells. 02/03/09-Hiralkumar Patel. received well monitoring/product removal report. product thickness increase during well gauging on 01/09/09. total of approx. 471 gal of product and contaminated water was removed in Jan. 2009. 02/04/09-Hiralkumar Patel. left message for Matt inquiring work schedule for required wells installation. spoke with Mr. Leichter regarding well installation work schedule. will call back. 02/23/08-Hiralkumar Patel. left message for Matt. spoke with Mr. Leichter regarding well installation. he will call back by tomorrow. received message from Matt. they installed wells on 02/11/09 and collected groundwater samples from all wells. will submit groundwater sampling report once data available from lab. 03/03/09-Hiralkumar Patel. received email from Matt with well monitoring/gauging report for Feb. 2009. depth to water at the site ranged from 7 to 10 ft bg. product thickness ranged from 0.01 to 1.07 ft. total of approx. 520 gal of product and contaminated water removed in Feb. 2009. 03/19/09-Hiralkumar Patel. received email from Matt. will submit report by 03/27/09. 04/02/09-Hiralkumar Patel. received monthly groundwater monitoring

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

and product recovery report for month of March. product thickness during the monitoring period ranged from 0.02 ft to 1.01 ft. total of approx. 483 gal of product and contaminated groundwater removed. 04/08/09-Hiralkumar Patel. received monitoring well installation report. abstract: - original scope of work was to install 4 monitoring wells. total of two wells (MW-20 and MW-21) were installed. total of six additional attempts were made to install two wells in the approved locations however due to refusal the wells could not be installed - two soil samples were collected (at 5-10 ft and 10-15 ft bg) from each well borings for analysis - groundwater was encountered at approx. 9 ft bg less than --------- - well screen installed from 5 ft to 12.5 ft depth - no PID readings noticed during well installation - no VOC contamination found in soil samples - high SVOC contamination found in soil samples below 5 ft depth - no groundwater samples collected at this time, samples wil be collected separately received quarterly monitoring report. abstract: - groundwater samples collected from total of 23 wells (21 installed by owner and two previously installed unknown wells) - found high naphthalene in samples from wells MW-3 (135 ppb), MW-8 (821 ppb), MW-12 (436 ppb), MW-13 (848 ppb) and MW-14 (1,180 ppb) - found MTBE in wells MW-13 (103 ppb) and MW-14 (240 ppb) - found minor contamination of other VOCs in wells - recommends to continue weekly monitoring and EFR events and samples on a quarterlly basis 04/09/09-Hiralkumar Patel. discussed with DEC Austin. he asked for tidal survey, confirmation of groundwater flow direction and off-site groundwater investigation towards west of the property. 04/10/09-Hiralkumar Patel. visited site. saw tyree crew on-site pumping product out from seven wells which had product. visited adjacent site on west side (downgradient). there is a building material supply business on adjacent property at 507-509 W 20th Street (alternate address: 506-508 W 21 St) which is downgradient from the subject spill site. met with Cesar Chavez at Kamco supply corp. at 507 W 20th street. informed him about spill next door and possible soil/groundwater investigation inside building. he agreed to allow consultant to perform required investigation work. spoke with Alan Swerdlick, business owner. he asked to contact Ray Barter in his office to get property owner’s info. left message for Mr. Barter. Kamco Supply Corp. **business at 507 W 20th street** Alan Swerdlick **business owner** 80 21st Street Brooklyn, NY 11232 contact: Ray Barter **vice president of financial matters at Kamco** Ph. (718) 768-1234 Fax (718) 788-8607 email: rbarter@kamco.com Cesar Chavez **business manager at Kamco** Ph. (212) 736-7350 Fax (212) 564-6436 email: cchavez@kamco.com spoke with Mr. Azani, property owner of 507 W 20th street and informed him about current situation and future investigation work on his property. Liron Realty Inc. **property owner of 507 W 20th street** 2025 Broadway, # 28B New York, NY 10023-5017 contact: Shalom Azani Ph. (917) 498-2773 (C) Fax (212) 496-1846 sent letter to Mr. Neuringer requiring off-site soil/gw investigation at 507 W 20th street & tidal survey of all wells. letter emailed to Mr. Neuringer, Matt, Mr. Barter and Mr. Quatrale. letter faxed to Mr. Azani. 04/10/09-Hiralkumar Patel. received message from Matt. 04/15/09-Hiralkumar Patel. left message for Matt. 04/16/09-Hiralkumar Patel. received call from Matt. he will contact owner/tenant at 507 W 20th street and will visit the site. he also mentioned about tidal survey. he believes that tidal survey will not help in this case and he suggest not to do so. asked him to visit neighbour’s site and to submit proposed well location map and

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

explanation for not doing tidal survey. 04/24/09-Hiralkumar Patel. received email from Matt requesting to extend deadline for report submissiong. 04/29/09-Hiralkumar Patel. spoke with Matt. he is going to site tomorrow morning and then will submit work plan with proposed well location on adjacent property. he is expecting to submit report by end of May 2009. approved his request to extend deadline. 05/05/09-Hiralkumar Patel. received monthly report from Matt. product thickness during monitoring period ranged from 0.02 ft to 1.10 ft. 05/12/09-Hiralkumar Patel. received email from Matt. he asked for approval to install 2-inch diameter wells for off-site investigation. 05/14/09-Hiralkumar Patel. sent email to Matt requiring to install 4-inch diameter wells (not 2-inch) which can be used in future. 06/04/09-Hiralkumar Patel. 11:30 AM:- received email from Matt with monthly status report for May 2009. product thickness ranged from 0.01 ft to 0.92 ft. total of approx. 500 gal of product and contaminated groundwater was removed in May 2009. about 0.5 ft of product re-appeared in well MW-11. no product was measured in well MW-11 since 02/26/09. 06/25/09-Hiralkumar Patel. 3:12 PM:- received quarterly monitoring report. abstract: - groundwater samples collected from total of 23 wells (21 installed by owner and two previously installed unknown wells) - found minor contamination in wells - recommends to continue weekly monitoring and EFR events and samples on a quarterlly basis 07/06/09-Hiralkumar Patel. 11:13 AM:- received call from Mr. Neuringer. he got proposals for off-site well installation and will start soon. he will ask Matt to call back with work schedule. 07/06/09-Hiralkumar Patel. 3:19 PM:-received email from Matt with monthly status report for June 2009. product thickness ranged from 0.02 ft to 1.17 ft. total of approx. 428 gal of product and contaminated groundwater was removed in June 2009. four wells are proposed to be installed along the adjacent down-gradient property in July 2009. 07/15/09-Hiralkumar Patel. 4:46 PM:- received email from Matt. offsite wells will be installed on 07/30/09-07/31/09. 08/06/09-Hiralkumar Patel. 4:19 PM:- received monthly monitoring report from Matt. product thickness ranged from 0.00 ft to 1.24 ft. total of approx. 362 gal of product and contaminated groundwater was removed in July 2009. 09/02/09-Hiralkumar Patel. 4:31 PM:- received off-site monitoring well installation report. abstract: - three monitoring wells (MW-22, MW-23 and MW-24) were installed - wells were set at 13 ft bg - soil samples were collected in continour 5 ft intervals starting at ground surface to a depth of 10 ft bg - soil samples collected at 5 to 10 ft bg from each well location were submitted for analysis - groundwater was found at about 8 ft bg - no contamination found in soil samples - will submit groundwater sampling report separately 09/03/09-Hiralkumar Patel. 12:10 PM:- received monthly status report for Aug. 2009. product thickness ranged from 0.00 ft to 1.19 ft. total of approx. 493 gal of product and contaminated groundwater was removed in Aug. 2009. 09/16/09-Hiralkumar Patel. 12:20 PM:- received quarterly groundwater sampling report. found free product in wells MW-3, MW-9, MW-11, MW-12, MW-13, MW-14 and MW-18. product thickness ranged from non-detectable to 1.19 ft. total of 26 wells sampled (including 3 recently installed wells on adjacent downgradient property). next quarterly well sampling will happen in Nov. 2009. very minor dissolved contamination found in few wells. 09/23/09-Hiralkumar Patel. 2:28 PM:- spoke with Matt regarding any product found in off-site wells as no data in recently submitted quarterly sampling report. Matt mentioned that no product was found earlier, but product

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

found in off-site wells in month of September 2009. will submit monthly report in Oct. 2009. 10/01/09-Hiralkumar Patel. 10:36 AM:- received monthly status report for Sept. 2009. product thickness ranged from 0.00 ft to 0.75 ft. total of approx. 546 gal of product and contaminated groundwater was removed in Sept. 2009. product re-appeared in well MW-9 (last seen on 05/29/09). found 0.48 to 0.66 ft product in off-site well MW-24. 10/06/09-Hiralkumar Patel. discussed with DEC Austin and DEC Vadim. based on available information, case transferred to DEC Vadim. 11:19 AM:- sent email to Matt and informed about case transfer. summary: - one 3000 gal diesel tank was located in garage area, no contamination found in endpoint soil samples after removal of the tank - no spills or tank test failure associated with diesel tank - groundwater at 8-9 ft bg - according to subsurface investigation, conducted in Dec. 2006, gw flow direction was determined westerly during high tide and southwesterly during low tide - according to phase I, three self contained ASTs were identified in maintenance area, a 1000 gal fuel oil AST had been removed from the southern vault in 1997 - auto body shops located on west side of property (downgradient from the site) - elevated abandoned railroad is located adjacent to western property boundary, above auto body shops - as per sanborn map of 1895, manufactured gas plant (MGP) was located on 11th ave between 19th and 20th streets, on 10th ave between 18th and 19th street and on 18th street, east of 10th ave less than ------ - according to Additonal subsurface investigation report, from March 2008: analytical results for product samples from MW-12 and MW-17 shows that product appears to be of an extremely weathered middle distillate, eigher diesel fue or fuel oil. based on analyticals result, age of the LPH at MW-12 is estimated to be at least 18+/-2 years and age of LPH from MW-17 is estimated to be at least 19+/-2 years less than --------- (this could be from previous heating oil tanks on property) - fill material and medium to fine grained sand found in all borings/wells to depth of 15 ft - owner is planning to develope this site as hotel/residential complex - found free product in off-site well, downgradient from the site - e-designated site less than -------- 11/03/2009: This spill case was transferred to A. Doronova. - AD 01/11/2010: Received a Quarterly Monitoring report for the period of September - November 2009. Will review. AD 02/02/2010: Reviewed the report. It states that there 26 GW monitoring wells. During the monitoing period free product was detected in 10 wells: MW-3, MW-7, MW-9, MW-11, MW-12, MW-13, MW-14, MW-18, MW-23 and MW-24. The product thickness ranged from non-detectable to 1.19 ft. The free product is removed on a weekly basis using VEFR. Since November 2008 a total of 5,939 gallons of free product/GW mixture have been removed from the site. Total of 26 wells sampled. Total VOCs ranged from ND to 571ppb (MW-13) and total SVOCs ranged from ND to 2,298ppb (MW-13). Product absorbent socks will be placed into wells containing free product. Weekly EFR events and quarterly GW monitoring will continue at the site. GW contour map is abcent. To request wells survey. AD 02/04/2010: Received a Summary Monitoring report for January 2010. Will review. AD 03/08/2010: Reviewed the summary report. It states that there 26 GW monitoring wells. The work completed included monitoring of the wells for depth to water and product (if present). Recovery of a free product was performed using VEFR. During the monitoing period free product was detected in 7 wells: MW-3 (0.03'), MW-7 (0.01'), MW-9, MW-12(0.37'), MW-13 (0.04'), MW-14(0.21'), MW-18(0.43'), and MW-24(0.12'). The product thickness ranged from non-detectable to

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

0.43 ft. The free product is removed on a weekly basis using VEFR. Since November 2008 a total of 6,381 gallons of free product/GW mixture have been removed from the site. Product absorbent socks have been placed into wells containing free product. Weekly EFR events and quarterly GW monitoring will continue at the site. AD 03/10/2010: Received a Quarterly Monitoring report for the period of December 2009 through February 2010. Will review. AD 03/30/2010: Reviewed the quarterly monitoring report prepared by Tyree. It states that during the monitoring period 9 wells out of 26 contained free product: MW-3, MW-7, MW-9, MW-11, MW-12, MW-13, MW-14, MW-18 and MW-24. The product thickness ranged from ND to 1.19 ft. The work completed included monitoring of the wells for depth to water and product (if present) and sampling of the wells. Recovery of a free product was performed using weekly VEFR. Since November 2008 a total of 6,791 gallons of free product/GW mixture have been removed from the site. 24 GW wells were sampled for VOCs and SVOCs. Total VOCs ranged from ND to 832ppb (MW-12); and SVOCs ranged from ND to 1,312ppb (MW-13). Weekly EFR events and quarterly GW monitoring will continue at the site. AD 04/01/2010: Received a Summary Monitoring report for March 2010. Will review. AD 04/21/2010: Reviewed the summary report. It states that work completed included monitoring of the wells for depth to water and product (if present). Recovery of a free product was performed using VEFR. During the monitoing period in the beginning of March, free product was detected in 5 wells: MW-3 (0.03'), MW-12(0.82'), MW-13 (0.29'), MW-14(1.59') and MW-18(0.21'). The product thickness ranged from 0.01' to 1.59 ft. In the end of March - free product was detected in three wells: MW-11 (0.49'), MW-12 (0.32') and MW-18 (0.50'). The free product is removed on a weekly basis using VEFR. A total of 586 gallons of free product/GW mixture have been removed from the site during March 2010. Product absorbent socks have been placed into wells MW-23 and MW-24. Weekly EFR events and quarterly GW monitoring will continue at the site. AD 05/06/2010: Received a Summary Monitoring report for April 2010. Will review. AD 05/12/2010: Reviewed the summary report. It states that there are 26 GW monitoring wells at the site. The work completed included monitoring of the wells for depth to water and product (if present). Recovery of a free product was performed using VEFR. During the monitoing period in the beginning of April, free product was detected in 3 wells: MW-11(0.63'), MW-12 (0.92') and MW-18(0.68'). In the end of April - free product was detected in 2 wells: MW-11 (0.70'), and MW-18(0.86'). Well MW-12 was not sampled in the end of April. The free product is removed on a weekly basis using VEFR. A total of 548 gallons of free product/GW mixture have been removed from the site during April 2010. Product absorbent socks have been placed into wells MW-23 and MW-24. Weekly EFR events and quarterly GW monitoring will continue at the site. AD Received a phone call from Mr. Eric Telemaque of Etex Corp. (212)631-9000. His company is a new consultant for the site. He asked for latest reports from Tyree. Told him to submit FOIL request to DEC. AD 06/01/2010: Received a Summary Monitoring report for May 2010. Will review. AD 09/2010: Reviewed the summary report. The work completed included monitoring of the wells for depth to water and product (if present). Recovery of a free product was performed using VEFR. During the monitoring period on May 14, 2010, free product was detected in 2 wells: MW-11(0.38') and MW-18(0.50'). A total of 97 gallons of free product/GW mixture have been removed from the site during May 2010. Product absorbent socks have been placed into wells MW-23 and MW-24. Weekly EFR events and

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

quarterly GW monitoring will continue at the site. AD 09/14/2011: Called and left a message to Mr. Boeckel of Tyree. AD 09/15/2011: Called and left a message to Mr. Eric Telemaque of EMTEQUE Corp. (212)631-9000. AD 09/16/2011: Called and left a message to Mr. Resnick of HLC Development LLC (site owner). AD 09/20/2011: Received a message from Mr. Resnick of HLC Developments LLC. This site is no longer owned by HLC DEvelopment. The new owner of the site is: Sherwood Equities, contact phone number - 212-980-8000. Called to Sherwood Equities and spoke with Paul Callan (212-515-1414). He said that remediation continue at the site and that Mr. Mitch Soloman (vice-president of construction of Sherwood Equities) will get back to me with info on consulting company performing the remediation. Later received a call from Mr. Soloman. He said that Sherwood Equities plan to do some re-development project at the site and will excavate contaminated soils during this re-development. Asked him about approximate start date of the construction. He told me that it will probably beging in a year. Explained to Mr. Soloman that the site should be monitored during this waiting period, because it has history of a free product and already has not been not monitored for a year. Mr. Soloman said that thay have consultant company which oversees demolition and asbestos cleanup at their properties (EMTEQUE Corp. - Mr. Eric Telemaque). Mr. Telemaque will contact DEC. AD 09/23/2011: Received a phone call from Mr. Telemaque. Discussed with him the next course of actions for the site. He proposed monthly EFR events untill disappearance of the free product, after that start groundwater sampling. Requested him to submit this proposal for review and approval. AD 11/01/2011: Did not received the proposal. Called and spoke with Mr. Telemaque of EMTEQUE. He told me that he sent an e-mail to me on September 27, 2011. Informed him that e-mail was not received. It was clarified that Mr. Telemaque used wrong e-address. He re-sent that e-mail to the correct address and it says: From: Eric Telemaque [mailto:eric@emteque.com] Sent: Tuesday, September 27, 2011 8:35 AM To: 'axdoronova@gw.dec.state.ny.us' Subject: 169 10th Avenue - Spill 06-09814 Ainura, As discussed, we have been retained by the owner to advise them on the open spill for this site. They are in the process of meeting with architects and engineers for the design of the development of a new facility at this location at which time, they will undertake an aggressive program through excavation for foundation to address the spill at the site. As an interim measure, we are proposing the evacuation of free product along with some dissolved components from the existing wells on site. This work will be performed once a month and will include gauging of the wells as well. On a quarterly basis, this information shall be summarized in a report issued to NYSDEC. As long as free product continues to exist in the wells, sampling for VOCs and SVOCs will not be performed. Once free product is absent, we would develop and propose a sampling program to NYSDEC. If this meets with the NYSDEC s approval and we commence the well evacuation immediately. Please advise. Eric M. Telemaque President EMTEQUE Corporation 505 Eighth Avenue, Suite 900 New York, NY 10018-4546 212.631.9000 Office 646.529.6526 Cellular 212.631.8066 Fax eric@emteque.com www.emteque.com Will review. AD 11/02/2011: Reviewed the previous reports. Last GW sampling was performed in March of 2009. Discussed the monthly EFR proposal with J. Kolleeny of DEC. Baseline GW sampling is needed. Called and spoke with Mr. Telemaque. Requested baseline GW sampling of site perimeter wells and few site wells. He will discuss this request with the site owner. AD 12/08/2011:

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

Received a phone call from Mr. Telemaque. He informed me that they performed a GW sampling at the site, and asked for firther actions. required to prepare a summary report with recommendations for DEC review. He will submit the report shortly. AD 12/14/2011: Received an e-mail from Mr. Telemaque saying: Ainura, Please review and call to discuss at your convenience. Report is being forwarded as a draft, once final hard copy of results are received from the lab, we will resubmit. Regards, Eric M. Telemaque President Emteque LLC 505 Eighth Avenue, Suite 900 New York, NY 10018-4546 212.631.9000 Office 646.529.6526 Cellular 212.631.8066 Fax AD 02/09/2012; Reviewed the report. It states that Emteque visited the site on November 19, 2011, to gauge and sample the wells. Free product was detected in wells Mw-11 (0.66'), MW-12 (0.72') and MW-18 (0.81'). SVOCs were detected in wells: MW-11 (3,713ppb), MW-12 (4,364ppb), MW-17 (5,950ppb) and MW-18 (6,650ppb). Low levels of TVOCs were detected in wells: MW-11 (14ppb), MW-12 (111.8ppb), MW-17 (6.5ppb) and MW-18 (59.4ppb). Based on the data the consultant states that groundwater contamination has decreased in the wells in comparison with 2010 GW sampling, but that free products is still present in three wells. Emteque recommends to perform monthly product recovery and quarterly GW sampling at the site. Once free product is abcent, a more agressive approach to remediate the site will be proposed. AD Talked with Mr. Telemaque regarding site monitoring and free product recovery proposal. Approved Emteque's recommendations. Next report is due. AD 07/02/2012: Received May 2012 groundwater monitoring report from Emteque. No pdf copy was submitted to request e-copy of the report. Sent an e-mail to Mr. Telmaque of Emteque with a request to submit CD with pdf copy of the report. Later in the day received an e-mail with attached pdf copy of the report. DL the report to eDocs. Will review. AD 08/07/2012: Reviewed the report. It states that that Emteque visited the site on May 24, 2012, to gauge and sample the wells. There are a total of 26 monitoring wells at the site. Emteque gauges and samples ten selected wells. Those wells are: MW-5, MW-6, MW-11, MW-12, MW-16, MW-17, MW-18, MW-23, MW-24 and MW-Unknown North. Free product was detected in 5 wells MW-11 (1.39'), MW-12 (2.19'), MW-17 (0.68') MW-18 (1.45') and MW-24 (0.22'). Approximately 150 gallons of free product/GW mixture was recovered from the wells. After free product was removed from the wells, GW samples were collected for lab analysis. SVOCs were detected in wells: MW-11 (275ppb), MW-12 (712ppb), MW-17 (1070ppb) and MW-18 (1372ppb). Low levels of TVOCs were detected in MW-11 (11ppb), MW-12 (63ppb), MW-17 (20ppb) and MW-18 (38ppb). Emteque will continue performing monthly product recovery and quarterly GW sampling at the site. Once free product is abcent, a more agressive approach to remediate the site will be proposed. AD 10/22/2012: Sent an e-mail to Mr. Telemaque of Emteque with a requiremnt to submit a next report by November 2, 2012. later in the day received an e-mail from Mr. Telemaque saying that the report is ready and will be submitted by e-mail shortly. Around 11:00 AM I received the report via e-mail. DL it to eDocs. Took a quick look at the submitted report. Summary tables with analytical data, site plan and GW contour map are missing. Called and spoke with Jim Blaney of Emteque (cell: 609-613-2004). Requested to submit all missing data. Also mentioned that all site-related well should be sampled on next quarterly round. AD 11/14/2012: Received an e-mail from Chawla, Shaminder of OER which states that developer for this site wants to enter City Voluntary Cleanup Program. Developer has proposed remedial investigation work involving eight soil borings, 6

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

soil vapor points and monitoring 4 existing groundwater wells for full analysis. OER woud like to discuss this investigation proposal and proposed remediation through 17 feet of excavation with DEC. Sent available dates for a meeting to Paul John of DEC. AD 11/21/2012: Reviewed the report. It states that Emteque visited the site on May 24, 2012, to gauge and sample the wells. There are a total of 26 monitoring wells at the site. Emteque gauges and samples ten selected wells on August 22, 2012. Those wells are: MW-5, MW-6, MW-11, MW-12, MW-16, MW-17, MW-18, MW-23, MW-24 and MW-Unknown North. On September 28, 2018 gauging event free product was detected in 5 wells MW-12 (0.24'), MW-17 (0.96') MW-18 (0.02'), MW-23 (0.04) and MW-24 (0.21'). Approximately 420 gallons of free product/GW mixture was recovered from the wells. After free product was removed from the wells, GW samples were collected for lab analysis. SVOCs were detected in wells: MW-11 (633ppb), MW-12 (358ppb), MW-17 (27ppb) and MW-18 (104ppb). Low levels of TVOCs were detected in MW-11 (6ppb), MW-12 (26ppb), MW-23 (26ppb), MW-24 (122ppb) and MW-18 (13ppb). In general terms, both VOC and SVOC groundwater impacts appear to be attenuating over time when compared to the May 2012 data. Emteque will continue performing monthly product recovery and quarterly GW sampling at the site. Emteque s next well monitoring is scheduled for October, 2012. AD 11/26/2012: Received the following e-mail from Impact Environmental: Ms. Doronova, Attached please find a Notification of New Environmental Consultant for; NYSDEC Spill No. 06?09814 169 10th Avenue, New York NY Best Regards, Ben Hernandez Salazar Environmental Engineer IMPACT ENVIRONMENTAL welcome to solid ground& www.impactenvironmental.com There is a letter attachment, which states that Impact Env. will peform IRM and GW monitoring at the site. AD 11/30/2012: Received a phone call from Kevin Kleaka of Impact Environmental. Discussed the site conditions and further required actions for the site. Later received the following e-mail from Mr. Kleaka: Ainuna, As per our discussion today, this email shall memorialize the existing groundwater wells required for sampling by the NYSDEC for the above referenced site with respect to the 4th quarter 2012. The existing groundwater wells to be sampled and testing requirements shall be as follows: Twelve (12) existing monitoring wells: MW-5, MW-13, MW-14, MW-15, MW-16, MW-22, MW-23, MW-24, MW-19, Unknown Well-South, Unknown Well-North and Unknown Well (10th Ave). The wells will be sampled for dissolved phase contamination if they do not indicate the presence of LNAPL or free phase product. If free phase product is present, it s thickness will be reported and the groundwater will not analyzed for dissolved concentrations. The analysis of the groundwater sampled from the wells will be performed to include VOCs and SVOCs for the gasoline and fuel oil contamination compound list (Table 3 list from CP-51). In addition, monthly well gauging and product recovery will continue as previously performed. A groundwater survey will be performed to measure water table elevations and determine flow direction. Thank you, please contact me with any comments or misunderstandings. Kevin Kleaka Vice President IMPACT ENVIRONMENTAL www.impactenvironmental.com Corporate Headquarters 170 Keyland Court - Bohemia - NY - 11716 T - 631.269.8800 C - 516.805.8892 F - 631-269-1599 AD 12/20/2012: Had a conference call meeting with OER and Impact Environment regarding handling of the project by all involved parties. Scheduled tentative scope meeting on January 10, 2012. 01/10/2013: I and J. Kolleeny attended a meeting with Breanna Gribble of OER; Kevin Kleaka, Ben Hernandez, Joel Rogers of Impact

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

Environmental and Jason Roth of Sherwood Equities. DEC met with the RP s consultant and NYCOER staff to discuss the proposed remedial actions and end-point sampling requirements. On the meeting RAP preparation, reporting and other remediation related issues were discussed. It was agreed that one RAWP addressing both DEC s and OER s concerns will be prepared, rather than two separate RAWPs, and that post-remediation groundwater monitoring will be included in the RAWP. The final RAWP will be submitted to DEC soon. 01/30/2013: Received a RAP. The first page of the RAP addressed only to OER. Sent an e-mail to Ben Hernandez of Impact Env. with a request to include DEC. AD 02/07/2013: Received the revised RAP. Reviewed the RAP. The consultant proposed excavation of contaminated soil during site redevelopment. The entire site will be excavated down to 14-17 feet below grade, with dewatering. End-point soil samples will be collected and a waterproof membrane will be installed beneath the planned on-site building to prevent intrusion of any residual petroleum vapors. Remediation is scheduled to begin in March of 2013. End-point soil sampless are planned to be collected every 30 linear feet. Site plan with the proposed end-point soil sampling locations is missing. DEC is not included in the new spill, citizen complains or RAP modifications reporting. The RAP needs to be revised. AD 02/11/2013: Spoke with Ben. Required to revise the RAP to incude DEC in notifications and reporting process. Also requested to add a site map with a end-point soil sampling locations. AD 02/12/2013: Received revised work plan. The required changes were made in the RAP. Have concerns regarding depth of the bottom soil samples collected by Impact Env. in-situ. Discussed the RAP with J. Kolleeny of DEC. Will request to add three more end-point soil samples from the bottom of the excavation. AD 02/15/2013: Called and spoke with Mr. Salazar of Impact Env regarding additional soil samples. Sent the following e-mail to B. Salazar: Ben, I have reviewed the revised RAP submitted to DEC on February 11, 2013 and discussed it with my supervisor - Jonathan Kolleeny. The revisions to the RAP are accepted by DEC. We have one more requirement for the work plan. Since all soil samples from soil borings SB-1 through SB-8 were collected by Impact Env. from the 18-20' bgs interval, we would like you to collect three additional end-point soil samples from the center part of the property. If you are planning to collect them in the same manner as SB-1 and others using soil borings before start of the excavation, then soil samples from 14-17' bgs interval should be collected for analysis. Please submit site map with additional soil sampling locations for review and approval, and verify method of their collection, before submitting final RAP to the Department. Sincerely, Ainura Doronova AD 02/19/2013: Received the revised site plan with additional end-point soil sampling locations and revised RAP with addition to the text regarding collection of the soil samples from the bottom of excavation. Will review. AD 02/21/2013: Received the following e-mail from Ben: Hi Ainura, I have been going over the RAP with my supervisor and we would like to discuss the sidewall end point samples with you. Could you please give me a call at your earliest convenience to discuss? My number is 631-334-2354. Thanks, Ben Hernandez Salazar Called and spoke with Mr. Hernandez of Impact. He informed me that they would like to change the number of sidewall end-point samples from previously proposed 18 samples down to 10, arguing this decision by technical difficulties to obtain these samples due to sheet-piling installation. Requested to submit a site map with new end-point soil sampling locations along with detailed

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

explanation for such changes. AD 02/28/2013: Received the following correspondence from Mr. Hermandez of Impact Environmental: Ainura, Based on discussions with the Construction Manager on the 500 E. 21st Street project, there are a number of logistical and cost prohibitive issues with collection of soil sidewall endpoint samples via test pits. Each alternative is presented below. " Excavation of test pits outside of the sheetpiles this approach would require an excavator of sufficient size to dig test pits to 6-8 below existing grade (BEG), which is not expected to be on-site for the early pavement demolition activities. Since the test pits would be within the existing sidewalk area, backfilling the test pits would require compaction of the backfill material in lifts (to avoid future sidewalk settlement); this would require installation of shoring at each test pit. In addition, due to the prevalence of underground utilities in the surrounding sidewalk areas, excavating the large test pits would not be a viable alternative, as it could result in undo risk of damage to utilities and safety issues. " Excavation of test pits inside the sheetpiles - this would result in sampling of materials that will be removed during the construction activities, and would therefore not be representative. " Test pits installed prior to sheeting installation this approach would potentially destabilize ground for the sheetpile contractor, unless backfilled in compacted lifts as described above, and may not result in a representative sample. " Cutting holes in the sheet pile walls this approach presents potential sheetpile strength and stability issues. " In-situ Soil boreholes in the sidewalk this is the least obtrusive method, but carries significant costs. Due to these considerations, the most viable method is to collect in-situ sidewall samples by drilling boreholes. Based on the limited options for sidewall sample collection, we are proposing collection of a total of 10 samples, with 3 collected from each long side of the excavation (running north-south) and 2 collected from each short side of the excavation (running east-west). In addition, 3 bottom samples will be collected following excavation. Below is a Dropbox link of the Final RAP/RAWP reflecting the in-situ borehole sidewall samples for your review and approval. A hardcopy along with digital files on CD will be mailed to your office.
https://www.dropbox.com/s/6zoahbhmzywpjwe/2013-2-26_%2006-098141_13EH-N124M_500%20West%20212%20Street_Final%20RAP.pdf
Please contact me with any questions or comments. Thank You, Ben Hernandez Salazar Discussed the changes to the number of end-point soil samples with J. Kolleeny of DEC. The proposed number of end-point samples is not acceptable. Since the western part of the property is more contaminated esp. along the property line, few more end-point soil samples should be collected from western sidewall. Called and spoke with B. Salazar of Impact. Later sent him the following e-mail: Ben, I have reviewed the changes to the proposed number of the end-point soil samples and discussed them with my supervisor - Jonathan Kolleeny. Please add two more soil samples along the western property line to the proposed number of samples. The total number of the end-point soil samples for the site should be 15, including bottom samples. Thank you, Ainura Doronova AD 03/05/2013: received a phone call from K. Kleaka of Impact. He asked for what compounds they should analyze the end-point samples. Informed him that soil should be analyzed for Fuel Oil Contaminated Soil compounds from Table 3 of CP-51. Also I mentioned how many soil samples per boring should be collected. Later in the day received the

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

final RAP in dporbox. Reviewed the RAP. The changed the total number of the proposed end-point soil samples from 13 to 15. Two more soil samples were added along the western property line. Again, only one soul samples per boring was proposed in the RAP instead of the required two samples. Will discuss this with J. Kolleeny. AD 03/06/2013: Discussed the proposed soil sampling interval with J. Kolleeny of DEC. Issued a RAP approval letter with the following comment: Two soil samples should be collected for analysis per each in-situ sidewall soil boring location: one sample from directly above the water table and a second from the sampling interval with the highest PID reading. In the absence of any field indications of contamination, a single soil sample should be collected from just above the water table. Sent the approval letter to Mr. Roth of Sherwood 21 Associates LLC. DL pdf copy of the letter and copy of the final RAP to eDocs. AD 07/30/2013: During the month of July, 2013, I was continuously receiving Daily Reports for remedial activities from Impact Env. I had combined 15 July daily reports into one monthly report and DL the report to eDocs. Will review. AD 09/04/2013: Reviewed the July Daily Reports. According to them, during the month of July, Ryder Construction performed demolition and removal of existing concrete foundation slab and footings and was disposing loads of concrete debris off-site. Empty 30 gallon flammable liquid storage tank was discovered in Zone 6. Ryder Construction did removal of oil impacted soil from oil-water separator release in Zone 6. During all site construction activities, Impact Env. performed air monitoring for particulates and VOC levels which were within acceptable range. AD 09/05/2013: During the month of August, 2013, I was continuously receiving Daily Status Reports for remedial activities from Impact Env. I had combined 24 August daily reports into one monthly report and DL the report into eDocs. Will review. AD 09/26/2013: Reviewed the August Daily Reports. According to them, during the month of August, Ryder Construction performed installation of walls sheet piles. Impact Env. colected 3 compound samples and 1 VOC sample for waste characterization of oil impacted soils (from OWS release). On August 20, 2013, unknown buried used oil tank was discovered during excavation in Zone 5. Tank was damaged during excavation causing residual oil release onto surrounding soils. Impacted soils were excavated and placed on plastic sheeting for sampling and off-site disposal. On August 21, 2013 Impact Env. collected waste characterization sample from used oil impacted soil stockpile (from used oil tank release on 8.20.13). On August 23, 2013 unknown UST was discovered between Zones 4 and 5 (approx. 550 gal). UST was placed in secure location and covered for proper abatement and disposal. On August 28, 2013 another unknown UST (approximately 550 gallon) was discovered in Zone 5 possibly containing used oil residuals. Tank was placed in secure location and covered for proper abatement and disposal. The site was excavated down to 6 feet below existing grade. During the month of August, Ryder Construction was continuously excavating and removing soils and concrete debries from site originating from different Zones of excavation. Soil being loaded for off-site disposal to Former NJ Zinc Facility, Pennsylvania (3420 c.y -total) and to Pure Soil Technologies Jackson, NJ (740 c.y.-total). Air monitoring (particulate and VOC) levels were within acceptable range. Dewatering system installation planned for Tuesday 9/3. AD 09/30/2013: During the month of September, 2013, I was continuously receiving Daily Status Reports for remedial activities performed at the site in September 2013 from Impact Env. I had

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

combined 15 September daily reports into one monthly report and DL the report into eDocs. Will review. AD 10/23/2013: Reviewed the September 2013 daily reports. According to reports, during the month of September 2013, Ryder Construction performed installation of a suction wells for a site dewatering system. Ryder Construction also performed pumping of a surface water using pump trucks. Approximately 9,000 gallons of water was removed off-site. Carbon tanks for the dewatering system were set up on September 18, 2013. Air monitoring was done continuously and (particulate and VOC) levels were within acceptable range. On September 24, 2013 Ryder Construction did pre-stress test on tiebacks and set up suction well pumps to the dewatering system. They plan to start the dewatering system in October 2013. AD 10/24/2013: Received the following e-mail from B. Salazar saying: Shana / Ainura, Attached please find copies of the Daily Reports for work performed at the 500 West 21st Street site from October 3rd to October 18th . Currently, foundation piles are being installed and most of the site has been excavated to sub grade except for the soil entrance ramp. Please let me know if you have any questions or comments. Thank you, Ben Hernandez Salazar IMPACT ENVIRONMENTAL I combined 12 October 2013 daily reports into one monthly report and DL the report into eDocs. Will review. AD 11/14/2013: Reviewed the October 2013 daily reports. According to reports, during the month of October 2013, Ryder Construction performed off-site disposal of excavated contaminated soil to Palmerton, PA; performed pre-stress test on tiebacks and set up suction well pumps to the dewatering system. On October 8, 2013 Impact Env. installed well points along eastern side of the site. On October 18, 2013 piles were installed along 10th Avenue. Air monitoring (particulate and VOC) levels during the reported period were within acceptable range. No soil samples were collected during the reported period. AD 11/25/2013: Received the following e-mail from B. Hernandez Salazar: Good Evening Ainura, Attached please find the 500 West 21st Street, Manhattan (NYSDEC Spill #06-09814) Quarterly Monitoring Reports for the Fourth Quarter 2012 and First Quarter 2013 for your review. Please let me know if you will require hard copies. Thank you, Ben Hernandez Salazar IMPACT ENVIRONMENTAL DL the reports to eDocs. Will review. AD 12/11/2013: Reviewed the 4th GW QMR for 2012. The report summarizes the activities of the groundwater well gauging and quarterly sampling for the months of November and December 2012. The Quarterly Monitoring Program consists of the gauging of 27 groundwater monitoring wells, identified as MW-1 through MW-24, Unknown Well-South, Unknown Well-North, and Unknown Well-10th Avenue and the sampling of 12 groundwater monitoring wells, identified as MW-5, MW-13, MW-14, MW-15, MW-16, MW-19, MW-22, MW-23, MW-24, Unknown Well-South, Unknown Well-North, and Unknown Well-10th Avenue. The groundwater flow direction at the Site is to the east. November 2012 Monitoring: On November 30, 2012, Impact Environmental gauged 25 wells with an oil-water interface meter. Measurable free phase product was observed in 8 monitoring wells: MW-3, MW-7, MW-11, MW-12, MW-17, MW-18, MW-23 and MW-24 with a thickness of 0.12 feet, 0.02 feet, 0.14 feet, 0.01 feet, 0.01 feet, 0.01 feet, 0.02 feet and 0.01 feet, respectively. Monitoring wells MW-13 and MW-14 were unable to be located during this monitoring event. Groundwater was not detected in monitoring well Unknown Well-South which appeared to have an obstruction at the 8 foot depth. December 2012 Monitoring and Sampling: On December 11 and 12, 2012, Impact Environmental gauged 27 wells with an oilwater interface meter and sampled 8 wells (MW-5,

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

MW-15, MW-16, MW-19, MW-22, MW-24, Unknown Well-North and Unknown Well-10th Avenue). Measurable free phase product was observed in 8 wells: MW-3, MW-7, MW-11, MW-12, MW-13, MW-14, MW-17 and MW-23 with a thickness of 0.02 feet, 0.01 feet, 0.10 feet, 0.01 feet, 0.36 feet, 0.02 feet, 0.01 feet and 0.02 feet, respectively. Groundwater was not detected in well Unknown Well-South which appeared to have an obstruction at the 8 foot depth. Monitoring wells that contained free product were not sampled. Product Recovery: Measurable free phase product has been observed in 10 wells: MW-3, MW-7, MW-11, MW-12, MW-13, MW-14, MW-17, MW-18, MW-23 and MW-24 since November 2012. Monitoring of LNAPL will continue to be conducted on a monthly basis. The LNAPL has been removed through the use of a peristaltic pump. Impact Environmental has removed approximately 88.5 gallons of LNAPL and contaminated groundwater during product recovery efforts since November 30, 2012 contributing to a total of approximately 8,495 gallons since the commencement of product recovery in December 2008. The laboratory analysis performed on the groundwater samples MW-5, MW-15, MW-16, MW-19, MW- 22, MW-24, Unknown Well-North and Unknown Well-10th Avenue detected target concentrations of four VOCs above the NYSDEC ambient water quality standards in wells MW-24 and Unknown Well-North. Concentrations of MTBE ranged from ND in MW-5, MW-16 and MW-22 to 31.0 ug/L in MW-24. Concentrations of BTEX were not detected in any of the groundwater samples. Concentrations of Total VOCs ranged from 0.07 ug/L in MW-22 to 60.40 ug/L in MW-24. The laboratory analysis also detected target concentrations of two SVOCs above the NYSDEC ambient water quality standards in monitoring well MW-24. Concentrations of PAHs were not detected in any of the groundwater samples. Concentrations of Total SVOCs ranged from 0.78 ug/L in MW-22 to 175.40 ug/L in MW-24. Quarterly sampling planned to be performed in the first quarter of 2013 prior to the start of construction. AD 12/18/2013: Reviewed the 1st quarter of 2013 GW monitoring report. This Quarterly Monitoring Report summarizes the groundwater monitoring activities performed at the site from January through April 2013. The groundwater flow direction at the Site is to the east. January 2013 GW Monitoring: On January 17, 2013, Impact Environmental gauged 26 wells with an oil-water interface meter. Measurable free phase product was observed in 8 wells: MW-3, MW-7, MW-11, MW-12, MW-13, MW-17, MW-18 and MW-23 with a thickness of 0.05 feet, 1.20 feet, 0.50 feet, 0.10 feet, 0.15 feet, 0.05 feet, 0.05 feet and 0.09 feet, respectively. Groundwater was not detected in monitoring well Unknown Well-South which appeared to have an obstruction at the 8 foot depth. February 2013 GW Monitoring: On January 17, 2013, Impact Environmental gauged 26 wells with an oil-water interface meter. Measurable free phase product was observed in 8 wells: MW-7, MW-11, MW-12, MW-13, MW-17, MW-18, MW-23 and MW-24 with a thickness of 0.05 feet, 0.50 feet, 0.01 feet, 0.07 feet, 0.02 feet, 0.85 feet, 0.01 feet and 0.01 feet, respectively. Groundwater was not detected in monitoring well Unknown Well-South which appeared to have an obstruction at the 8 foot depth. March 2013 GW Monitoring and Sampling: On March 8, 2013, Impact Environmental gauged 26 wells with an oil-water interface meter and sampled 10 wells (MW-5, MW-14, MW-15, MW-16, MW-19, MW-22, MW-23, MW-24, Unknown Well-North and Unknown Well-10th Avenue). Measurable free phase product was observed in 6 wells: MW-7, MW-11, MW-12, MW-13, MW-17 and MW-18 with a thickness of 1.41 feet, 0.27 feet, 0.02 feet, 0.05 feet, 0.02 feet, and 0.03 feet, respectively. Groundwater was not detected in well Unknown Well-South which appeared to have an obstruction at the 8

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

foot depth. Monitoring wells that contained free product were not sampled. April 2013 GW Monitoring: On April 9, 2013, Impact Environmental gauged 26 wells with an oil-water interface meter. Measurable free phase product was observed in 5 wells MW-6, MW-7, MW-11, MW-12, and MW-13 with a thickness of 0.60 feet, 1.45 feet, 0.60 feet, 0.20 feet, and 0.10 feet, respectively. Groundwater was not detected in well Unknown Well-South which appeared to have an obstruction at the 8 foot depth. Impact Environmental has removed approximately 245-gallons of LNAPL and contaminated groundwater during product recovery efforts since November 30, 2012 contributing to a total of approximately 8,652-gallon since the commencement of product recovery in December 2008. GW data: The laboratory analysis performed on the groundwater samples detected elevated levels of MTBE in monitoring wells: MW-14, MW-15, MW-19, MW-23, MW-24, Unknown Well-10th Avenue and Unknown Well-North, ranging from 13ppb to 117ppb. The laboratory analysis detected trace concentrations of SVOCs below the NYSDEC ambient water quality standards in all monitoring wells, except Unknown Well-10th Avenue. In accordance with the approved Remedial Action Plan, groundwater monitoring and analysis will be performed on the nine remaining site perimeter wells (MW-16, MW-17, MW-19, MW-23, MW-24, Unknown Well-North, Unknown Well-South, and Unknown Well-10th Avenue) after excavation and foundation construction at the site is completed. AD 01/27/2014: During the month of January, 2014, I was continuously receiving from Impact Env. Daily Status Reports for remedial activities performed at the site in January 2014. I had combined 6 January daily reports into one monthly report and DL the report into eDocs. Will review. AD 02/20/2014: Reviewed the report. It states that the following activities were performed at the site since last reporting: - Continued Site dewatering. - Installation of compacted RCA sub base and of concrete mud slab. - Installation of PrePrufe 300R Waterproofing/Vapor Barrier over mud slab on northern portion of site. - Site grading/excavation to final sub grade level in Zones 1, 2, and 4. - Offsite soil disposal. - Installation of foundation wall formwork and rebar. - Concrete pour in section of foundation wall. - Excavated elevator pit, and installed elevator pit concrete formwork and rebar. No samples were collected. Air monitoring (particulate and VOC) levels within acceptable range. AD 01/14/2015: Called and left a message to Mr. Hernandez of Impact Environmental. AD 01/21/2014: Spoke with B. Hernandez. He said that there are construction activities going at the site. They are planing to install some wells for post-remediation GW monitoring. WP for wells installation will be submitted shortly. AD 01/22/2015: Received the following e-mail from Mr. Hernandez: Hi Ainura, Attached for your review and approval, please find the Replacement Well Installation Work Plan for the site located at 500 West 21st Street (169 10th Avenue) in Manhattan. This work plan addresses the installation of new monitoring wells to replace the existing perimeter sidewalk wells destroyed during redevelopment construction activities and required for post-remediation monitoring as stipulated in the March 2013 Remedial Action Work Plan. Due to the contractor s new sidewalk installation schedule, the wells will be required to be installed no later than early next week. Please let me know if you have any questions or require additional information. Thank you, Ben Hernandez Salazar Reviewed the work plan submitted by Impact Environmental Closures, Inc. (Impact Env.) on behalf of Sherwood 21 Associates LLC. The work plan proposes replacement of the off-site perimeter wells destroyed

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

during site redevelopment activities. A total of six monitoring wells are proposed to be installed on the sidewalks adjacent to the site for the required post-remediation groundwater monitoring. The locations for the proposed wells are adequate. Will issue an approval letter. Off-site wells on the ajacent property should be monitored on a continuous basis. DL the work plan to DDocs. AD 01/23/2015: Spoke with Ben Hermandez and Jason Roth regarding the work plan. Requested to check the exsisting off-site wells for the free product. Issued and sent the approval letter. DL copy of the letter to DDocs. AD 03/16/2015: Received the following e-mail from Shana Holberton: Hi Ainura, I am the NYCOER project manager for the 500 West 21st Street site and recently received the Remedial Closure Report for 500 West 21st Street for review I understand it was submitted to you for review as well. Would you be available tomorrow to discuss the open spill at the site (Spill No. 06-09814) and outstanding DEC requirements? Best, Shana Holberton Project Manager NYC Mayor s Office of Environmental Remediation 100 Gold Street, 2nd Floor, New York, NY 10038 Direct: (212)788-3220 Mobile: (917)974-4604 sholberton@dep.nyc.gov Sent her an e-mail stating that DEC did not receive the report yet. AD 03/17/2015: Received the following e-mail from B. Hernandez: Good Afternoon Ainura, Attached for your review please find the Drop Box link to the Remedial Closure Report for the site located at 500 West 21st Street (previously known as 169 10th Avenue), Spill No. 0609814. Remedial Closure Report https://www.dropbox.com/s/49kc98jgpga2lbw/2015-2-26.13EHN124M.RAR.DRAFT.BH.pdf?dl=0 Appendices https://www.dropbox.com/s/whkssjtjmq5ck02/2015-3-2.13EHN124M.RAR%20APPENDICES.BH.pdf?dl=0 Please let me know if you have any questions or comments. Thank you, Ben Hernandez Salazar IMPACT ENVIRONMENTAL Will review. AD 03/18/2015: Received the following e-mail from S. Holberton: Hi Ainura, After you have had an opportunity to look over the closure report would you please notify me if you have any objections to OER issuing a notice to DOB which would allow for residential occupation of the building? Thanks in advance, Shana Holberton Project Manager NYC Mayor s Office of Environmental Remediation Sent her e-mail that her office will be notified after DEC will review the report. AD 03/20/2015: Reviewed the submitted report. It states that Impact Environmental peformed at the site the following actions: - Mitigated and removed to the extent feasible LNAPL observed in the on-site monitoring wells; - Collected and analyzed in-situ sidewall soil samples and in-situ and post excavation bottom soil samples. Soil sample results were compared to NYSDEC Unrestricted Use (Track 1) and Restricted Residential Use (Track 2) Soil Cleanup Objectives (SCOs) as presented in NYSDEC Part 375-6 and CP51. Laboratory analysis did not detect pesticides or PCBs in any of the three samples. Trace levels of VOCs, SVOCs and metals were detected well below Track 1 Unrestricted Use SCOs. - Removed two 1080-gallon and one 550 gallon USTs found during excavation at the site. - Constructed an engineered composite cover consisting of a 24-inch thick concrete foundation floor slab, 18-inch thick concrete basement walls, and a permanent abandoned SOE system consisting of a grout secant pile wall and interlocking steel sheet piles, to prevent human exposure to residual soil/fill remaining under the Site. The concrete foundation structure covered the full extents of the site, to all property lines. - Installed a certified waterproofing/vapor barrier system beneath the building slab and upwards along all foundation sidewalls to grade. - Imported materials used for backfill

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

in compliance the RAP and in accordance with applicable laws and regulations. - Historic fill, construction and demolition debris and native soil were excavated and removed from the entire Site footprint to 18-19 feet below sidewalk grade to allow for the installation of the building s foundation structure. Transported and disposed off-Site soil/fill material at permitted facilities in accordance with the RAP and applicable laws and regulations for handling, transport, and disposal. A total of 24,098.49 tons of material were excavated from the Site. Sampled and analyzed excavated media as required by disposal facilities. Appropriately segregated excavated media onsite. - Screened excavated soil/fill during intrusive work for indications of contamination by visual means, odor, and monitoring with a photoionization detector (PID). - Mobilized site security, equipment, utility mark outs and marking & staking of excavation areas. - Implemented storm-water pollution prevention measures in compliance with applicable laws and regulations. - Performed all activities required for the remedial action, including permitting requirements and pretreatment requirements, in compliance with applicable laws and regulations. AD 03/26/2015: Called and left a message to S. Holberton. AD 03/27/2015: Called and spoke with Ms. Holberton of OER. Informed her that based on the performed activities and soil analytical results,DEC does not have any objections to OER issuing a notice to DOB which would allow for residential occupation of the building. Spill case will remain open pending submission of the groundwater sampling results. Later received an e-mail from Ms. Holberton saying: Hello Ainura, Thanks again for reviewing the remedial closure report that was submitted by Impact Environmental to OER and DEC. Per our conversation, OER and DEC are in agreement that the remedial action as outlined in the Remedial Action Plan has been performed and the owner may seek a Temporary Certificate of Occupancy for the residential units within the building. The spill at the site will remain open and will be addressed under DEC s oversight. Best, Shana Holberton Project Manager NYC Mayor s Office of Environmental Remediation AD 05/20/2016: Received the following e-mail from Impact Environmental: Good Evening Ainura, We have completed post-remediation groundwater monitoring events for the 2015 Year and First Quarter 2016 for the site located at 169 10th Avenue / 500 West 21st Street, New York NY (Spill No. 06-09814). We had previously sent the 2015 Annual Report hard copy. For convenience, below please find links to both electronic copies of the reports: 2015 Annual Post-Remediation Groundwater Monitoring Report https://impactenvironmental.filecamp.com/public/file/2n8d-h7m5sqer First Quarter 2016 Post-Remediation Quarterly Monitoring Report https://impactenvironmental.filecamp.com/public/file/2n8e-5gatolh0 Please contact me with any questions or comments. Thank You, Ben Hernandez Salazar Senior Project Engineer O: 631-269-8800 Ext. 142 C: 631-334-2354 Uploaded reports. Will review. AD 06/02/2016: Reviewed the Annual Monitoring Report-2015. The report states that the site was remediated in conjunction with site redevelopment and in accordance with the scope of work presented in the NYSDEC and NYC OER-approved Remedial Action Plan (RAP) dated March 5, 2013. Redevelopment of the site commenced in April 2013 with the demolition of the former one-story masonry building. Remedial activities began shortly after building demolition in July 2013. Redevelopment of the Site consisted of the demolition of the one story structure and the construction of an eight-story, 116,000 gross square foot, 103-foot high mixed-use residential / commercial retail building. The building

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

includes one basement level, which is approximately 18-19 feet below the 10th Avenue sidewalk grade. Soil excavation: The entire site was excavated to a depth of 20 feet below grade and a total of 24,098.49 tons of soil/fill material was excavated from the site between August 19, 2013 and February 5, 2014. All excavated soil/fill material was exported for off-site disposal at properly licensed/regulated facilities. No onsite material was reused as backfill. Groundwater: Construction dewatering was performed during excavation to allow for the construction of the new foundation structure. A total of 7,092,000 gallons of groundwater was pumped from the Site, pretreated onsite via settling tank; oil/water separator; bag filters; and granular activated carbon vessels, and discharged to a NYCDEP combined sewer in accordance with NYCDEP Discharge Permit (#C-5275). Underground Storage Tanks: During excavation activities, two (2) 1,080 gallon and one (1) 550 gallon fuel oil underground storage tanks (USTs) were encountered. No evidence of leaks was observed and the tanks were properly cleaned and disposed off-site. End-point soil sampling: Collected and analyzed 18 sidewall and 3 bottom documentation soil samples to determine the performance of the remedy with respect to attainment of Site-Specific SCOs. A waterproofing/vapor barrier system consisting of Grace Preprufe 300R membrane consisting of a 46-mil, high-density polyethylene (HDPE) sheet with a synthetic adhesive and weather resistant protective coating was installed beneath the entire concrete foundation slab and pile caps. GW sampling: In accordance with the approved RAP, groundwater monitoring was performed on eight of the nine remaining and reinstalled perimeter wells in April 2015 (MW-UW10-A, MW-16-A, MW-17A, MW-22, MW-23, MW-24, MW-25 and MW-UWN-A), and seven of the nine remaining and reinstalled perimeter wells in June 2015 (MW-UW10-A, MW-16-A, MW-22, MW-23, MW-24, MW-25 and MW-UWN-A), after remedial excavation and foundation construction. No measurable free phase product was observed in any the sampled wells on either the April or June 2015 sampling events. A general trend of decreasing concentrations of target VOCs and SVOCs in comparison to pre-remediation findings was observed during this post-remediation monitoring period. The most contaminated well MW-17A in April 2015 had 35ppb TVOCs. The most contaminated well in June 2015 sampling was MW-24 with 86ppb of total VOCs. Impact Environmental will continue to perform the groundwater sampling. Frequency of post-excavation groundwater monitoring and analysis will be based on the results of the initial post-excavation groundwater monitoring and analysis event. Closure of NYSDEC Spill #06-09814 will be attempted based on the results of the post-remediation groundwater sampling. AD 06/03/2016: Reviewed the Post-Remediation Groundwater Quality Report. It states that Impact Environmental has continued the post-remediation groundwater monitoring program and conducted the 1st Quarter event on January 20, 2016. Measurable free phase product was not observed in any of the nine (9) wells during the quarterly monitoring event. Groundwater samples were collected from each well MW-UW10-A, MW-16-A, MW-17-A, MW-22, MW-23, MW-24, MW-25, MW-UWN-A, and MW-19A. All purged groundwater was pumped out of the well and transferred to a 55-gallon drum. The depth to water, depth to product and product thickness were recorded. The monitoring wells were sampled as part of this investigation. One groundwater sample was secured from each of these monitoring wells for laboratory analysis. The groundwater samples secured from monitoring wells on the Site were labeled for identification purposes as MW-UW10-A, MW-16-A,

EMPIRE CITY SUBWAY GARAGE (Continued) **S108296336**

MW-17-A, MW-22, MW-23, MW-24, MW-25, MW-UWN-A, and MW-19A. Based on the GW survey results, the groundwater flow direction at the Site is to the west and northwest. No measurable free phase product was observed in any the sampled wells during this monitoring event. A general trend of decreasing concentrations of target VOCs and SVOCs in comparison to pre-remediation findings was observed in the site wells. Total VOCs decreased from 0.77 ug/L to non-detect in MW-16; 1.51 ug/ L to non-detect in MW-22; 55.4 ug/ L to 14.9 ug/ L in MW-23; 117.2 ug/L to 16.13 ug/L in MW-24; 23.01 ug/ L to 3.4 ug/ L in Unknown Well North; 21 ug/l to non-detect in Unknown Well 10th Ave. Total SVOC concentrations decreased from 1.27 ug/L to non-detect in MW-16; 0.78 ug/ L to non-detect in MW-22; 24.38 ug/ L to 11.1 ug/ L in MW-23; 175.4 ug/L to 13.36 ug/L in MW-24; 4.57 ug/ L to non-detect in Unknown Well North; 2.54 ug/l to 0.06 ug/L in Unknown Well 10th Ave. The most contaminated levels of TVOCs of 42.4ppb at well MW-17A. According to the consultant, the sustained absence of free phase product and decrease in VOC and SVOC concentrations in the remaining site perimeter wells during the post-remediation monitoring events of 2015 and First Quarter 2016 is attributable to the remedial actions conducted at the site, including the excavation to 20 feet below grade and offsite disposal of 24,098.49 tons of soil/fill and the pumping and permitted discharge of 7,092,000 gallons of groundwater during construction dewatering. In addition, the Engineering Controls implemented during Site remediation and redevelopment, are protective of public health and the environment and address any potential future offsite contamination sources at the Site. Based on the findings of the post-remediation groundwater monitoring and the remedial actions performed on the Site, Impact requests the NYSDEC to close Spill #06-09814. AD 06/07/2016: Discussed the spill closure request with J. Kolleeny of DEC. Based on the remediation work performed at the site such as: - removal of USTs; - excavation of the site to 20 feet below grade and offsite disposal of 24,098.49 tons of soil/fill; - pumping and permitted discharge of 7,092,000 gallons of groundwater during construction dewatering; - applied Engineering Controls during Site remediation and redevelopment, that are protective of public health and the environment; - post-remediation groundwater monitoring, which confirms the effectiveness of the performed remediation, The Department approves the spill closure request. Will issue a closure letter. AD 06/08/2016: Issued and sent the closure letter to Mr. Roth of Sherwood 21 Associates LLC. Case closed. AD "

Remarks: "material could be gasoline or fuel oil or even a mixture; INSTALLED SEVERAL WELLS AND CONTAIMINATION SEEMS TO BE COMING FROM OFF SIGHT; NOT YET CLEAN;"

All Materials:

Site ID:	374150
Operable Unit ID:	1131827
Operable Unit:	01
Material ID:	2121539
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AA433 **LOT 30,TAXBLOCK 692** **NY E DESIGNATION** **S108076907**
NNW **169 10 AVENUE** **N/A**
< 1/8 **MANHATTAN, NY**
0.119 mi.
626 ft. **Site 17 of 24 in cluster AA**

Relative: E DESIGNATION:
Lower

Actual: Name:	LOT 30,TAXBLOCK 692
11 ft. Address:	169 10 AVENUE
City,State,Zip:	MANHATTAN, NY
Tax Lot(s):	30
Tax Block:	692
Borough Code:	Not reported
E-No:	E-142
Effective Date:	6/23/2005
Satisfaction Date:	Not reported
Ceqr Number:	03DCP069M
Ulurp Number:	050161 ZRM
Zoning Map No:	8b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

W434 **MOBIL** **NY Spills** **S111458276**
WSW **451 WEST 14TH ST** **N/A**
< 1/8 **NEW YORK, NY**
0.119 mi.
628 ft. **Site 6 of 17 in cluster W**

Relative: SPILLS:
Lower

Actual: Name:	MOBIL
11 ft. Address:	451 WEST 14TH ST
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	1112855 / 2012-02-27
Facility ID:	1112855
Facility Type:	ER
DER Facility ID:	415292
Site ID:	460818
DEC Region:	2
Spill Cause:	Other
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2012-02-09
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2012-02-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-02-09

MOBIL (Continued) **S111458276**

Spill Record Last Update:	2012-02-28
Spiller Name:	FRANK CASTA
Spiller Company:	MOBIL
Spiller Address:	451 WEST 14TH ST
Spiller Company:	999
Contact Name:	FRANK CASTA
DEC Memo:	"02/10/12-Hiralkumar Patel. tried caller's number multiple times, but call could not be completed. alternate addresses: 447-459 W 14th Street, 444-454 W 15th Street other spill : 0911962. as per last notes from 0911962, buyer of the subject site was planning for removal of tanks and excavation of contaminated soil. 3:03 PM:- left message for Richard Stumbo (914-232-7355) at Environmental Maintenance Contractors, who is working on spill # 0911962. 02/13/12-Hiralkuamr Patel. 10:01 AM:- received message from Richard. 10:51 AM:- spoke with Richard. asked him about any excavation at the site. he will contact on-site person and will call back. 02/14/12-Hiralkumar Patel. 2:05 PM:- received call from Allen from EMC. he spoke with owner and confirmed that there is no excavation work in progress at the site, at this time. Paul Jedziniak **owner's rep** Ph. (732) 491-4243 02/27/12-Hiralkumar Patel. 10:00 AM:- went to site. site is currently vacant. no sign of excavation found. based on available information, case closed."
Remarks:	"while excavating soil contamination found, c/u unknown"

All Materials:

Site ID:	460818
Operable Unit ID:	1210922
Operable Unit:	01
Material ID:	2208594
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

U435 **CON EDISON SERVICE BOX: 3221** **RCRA NonGen / NLR** **1016143078**
NW **525 W 18TH ST OPPOSITE** **NY MANIFEST** **NYP004258083**
< 1/8 **NEW YORK, NY 10014**
0.119 mi.
628 ft. **Site 13 of 15 in cluster U**

Relative: **Lower**
Actual: **9 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130320
Handler Name:	CON EDISON SERVICE BOX:	3221
Handler Address:		525 W 18TH ST OPPOSITE
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004258083
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR

CON EDISON SERVICE BOX: 3221 (Continued) **1016143078**

EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported

CON EDISON SERVICE BOX: 3221 (Continued) **1016143078**

Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130220
Handler Name: CON EDISON SERVICE BOX:	3221
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130320
Handler Name: CON EDISON SERVICE BOX:	3221
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	525 W 18TH ST OPPOSITE

CON EDISON SERVICE BOX: 3221 (Continued) **1016143078**

City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004258083
Facility Status:	Not reported
Location Address 1:	OPP 525 W 18TH ST
Code:	BP
Location Address 2:	SERV BOX 3221
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004258083
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/20/2013
Trans1 Recv Date:	02/20/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004258083
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010846489JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported

CON EDISON SERVICE BOX: 3221 (Continued) **1016143078**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

U436 **CON EDISON SERVICE BOX: 3220** **NJ MANIFEST** **S117985453**
NW **525 W 18TH ST E OF 11 TH AVE FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.119 mi.
628 ft. **Site 14 of 15 in cluster U**

Relative: **Lower**

Actual: **9 ft.**

NJ MANIFEST:

EPA Id:	NYP004258729
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JOSE MONTALVO
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	009209622JJK
EPA ID:	NYP004258729
Date Shipped:	7/17/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

CON EDISON SERVICE BOX: 3220 (Continued) **S117985453**

Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	1,000.00 Pounds

U437 **CON EDISON SERVICE BOX: 3220** **RCRA NonGen / NLR** **1016143139**
NW **525 W 18TH ST E OF 11 TH AVE FRONT OF** **NY MANIFEST** **NYP004258729**
< 1/8 **NEW YORK, NY 10011**
0.119 mi.
628 ft. **Site 15 of 15 in cluster U**

Relative: **Lower**
Actual: **9 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20170728
Handler Name:	CON EDISON SERVICE BOX:	3220
Handler Address:		525 W 18TH ST E OF 11 TH AVE FRONT OF
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004258729
Contact Name:		JOSE MONTALVO
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-427-1331
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified

CON EDISON SERVICE BOX: 3220 (Continued) **1016143139**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No

CON EDISON SERVICE BOX: 3220 (Continued) **1016143139**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170828
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20120717
Handler Name: CON EDISON SERVICE BOX:	3220
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20170728
Handler Name: CON EDISON SERVICE BOX:	3220
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CONSOLIDATED EDISON - SERV BOX 3220
Address:	525 W 18TH ST E OF 11 TH AVE F
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004258729

CON EDISON SERVICE BOX: 3220 (Continued) **1016143139**

Facility Status:	Not reported
Location Address 1:	F/O 525 W 18 ST E/O 11TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004258729
Mailing Name:	CONSOLIDATED EDISON - SERV BOX 3220
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	07/17/2012
Trans1 Recv Date:	07/17/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004258729
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	009209622JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON SERVICE BOX: 3220 (Continued) **1016143139**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

V438 **HUDSON PIER BUS DEPOT** **NY Spills** **S102239025**
West **W 15TH ST + 11TH AVE** **N/A**
< 1/8 **MANHATTAN, NY**
0.120 mi.
631 ft. **Site 8 of 8 in cluster V**

Relative: SPILLS:
Lower

Actual: Name:	HUDSON PIER BUS DEPOT
7 ft. Address:	W 15TH ST + 11TH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9514224 / 1996-02-08
Facility ID:	9514224
Facility Type:	ER
DER Facility ID:	126199
Site ID:	148275
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	1996-02-08
Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	1996-02-08
CID:	351
Water Affected:	HUDSON RIVER
Spill Source:	Unknown
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-02-08
Spill Record Last Update:	1996-02-21
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERIC JONES
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY USCG DIDN'T FIND ANY PROBLEMS "

HUDSON PIER BUS DEPOT (Continued) **S102239025**

Remarks: "notifier found a sheen on water"

All Materials:
Site ID: 148275
Operable Unit ID: 1025055
Operable Unit: 01
Material ID: 354357
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

T439 **CON EDISON** **NY MANIFEST** **S118464189**
SE **322 W 17TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.120 mi.
632 ft. **Site 12 of 20 in cluster T**

Relative: **Higher**
Actual: **19 ft.**

NY MANIFEST:
Name: CON EDISON
Address: 322 W 17TH ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004863672
Facility Status: Not reported
Location Address 1: 322 W 17TH ST
Code: BP
Location Address 2: SB 3014
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004863672
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193

CON EDISON (Continued) **S118464189**

Trans2 State ID:	Not reported
Generator Ship Date:	11/01/2015
Trans1 Recv Date:	11/01/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004863672
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014085966JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D003
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Name:	CON EDISON
Address:	322 W 17TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004742441
Facility Status:	Not reported
Location Address 1:	322 W 17 ST
Code:	BP
Location Address 2:	SB3022
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011

CON EDISON (Continued) **S118464189**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004742441
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 03/04/2015
Trans1 Recv Date: 03/04/2015
Trans2 Recv Date: 03/06/2015
TSD Site Recv Date: 03/06/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004742441
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002611054GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 500
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON (Continued) **S118464189**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

T440 **CON EDISON** **RCRA NonGen / NLR** **1018279427**
SE **322 W 17TH ST** **FINDS** **NYP004742441**
< 1/8 **NEW YORK, NY 10011** **ECHO**
0.120 mi.
632 ft. **Site 13 of 20 in cluster T**

Relative: RCRA NonGen / NLR:
Higher

Actual: Date Form Received by Agency:		20150304
19 ft. Handler Name:	CON EDISON	
Handler Address:		322 W 17TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004742441
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No

CON EDISON (Continued) **1018279427**

Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150304
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON (Continued) **1018279427**

Receive Date:	20150304
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067690804

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018279427
Registry ID:	110067690804
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067690804
Name:	CON EDISON
Address:	322 W 17TH ST
City,State,Zip:	NEW YORK, NY 10011

T441 **CON EDISON** **NY MANIFEST** **S116044066**
SE **F/O 322 W 17 ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.120 mi.
632 ft. **Site 14 of 20 in cluster T**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	F/O 322 W 17 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004404554
Facility Status:	Not reported
Location Address 1:	F/O 322 W 17 ST
Code:	BP
Location Address 2:	SB3022
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004404554
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	12/11/2013
Trans1 Recv Date:	12/11/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/13/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004404554
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002299726GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S116044066**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

T442 **CON EDISON** **NJ MANIFEST** **S120668246**
SE **322 W 17TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.120 mi.
632 ft. **Site 15 of 20 in cluster T**

Relative: **Higher**
Actual: **19 ft.**

NJ MANIFEST:

EPA Id:	NYP004742441
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002611054GBF
EPA ID:	NYP004742441
Date Shipped:	3/4/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **S120668246**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AA443 **RESIDENCE** **NY Spills** **S104651833**
North **188 10TH AVE** **N/A**
< 1/8 **NEW YORK, NY**
0.120 mi.
634 ft. **Site 18 of 24 in cluster AA**

Relative: **Lower**

Actual: **12 ft.**

SPILLS:

Name:	RESIDENCE
Address:	188 10TH AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0000570 / 2000-05-01
Facility ID:	0000570
Facility Type:	ER
DER Facility ID:	191172
Site ID:	231981
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	2000-04-14
Investigator:	SIGONA
Referred To:	Not reported

RESIDENCE (Continued) **S104651833**

Reported to Dept:	2000-04-14
CID:	389
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-04-14
Spill Record Last Update:	2004-01-05
Spiller Name:	Not reported
Spiller Company:	ET MINOR FUEL
Spiller Address:	6205 5TH AVE
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	""
Remarks:	"CALLER REPORTING A SPILL OF MATERIAL FROM AN UNK SOURCE APROX 2 GAL OF MATERIAL SPILLED NO CLEANUP AS OF YET NO CALLBACK NECESSARY"

All Materials:

Site ID:	231981
Operable Unit ID:	822351
Operable Unit:	01
Material ID:	288814
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AB444 **CON EDISON - MANHOLE 39692** **NY MANIFEST** **S120958322**
NE **22 ST & 9TH AVE** **N/A**
< 1/8 **MANHATTAN, NY 10001**
0.120 mi.
635 ft. **Site 2 of 10 in cluster AB**

Relative: **Higher**
Actual: **17 ft.**

NY MANIFEST:

Name:	CON EDISON - MANHOLE 39692
Address:	22 ST & 9TH AVE
City,State,Zip:	MANHATTAN, NY 10001
Country:	USA
EPA ID:	NYP004929812
Facility Status:	Not reported
Location Address 1:	22 ST & 9TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MANHATTAN
Location State:	NY
Location Zip:	10001
Location Zip 4:	Not reported

CON EDISON - MANHOLE 39692 (Continued) **S120958322**

NY MANIFEST:

EPAID:	NYP004929812
Mailing Name:	CON EDISON - MANHOLE 39692
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

R445 **CON EDISION - SB3785** **RCRA NonGen / NLR** **1007207850**
ENE **F/O 331 W.21 ST. F/O 331 W.21** **NY MANIFEST** **NYP004076832**
< 1/8 **NEW YORK, NY 10003**
0.121 mi.
637 ft. **Site 6 of 6 in cluster R**

Relative: **Higher**
Actual: **18 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20020602
Handler Name:	CON EDISION - SB3785	
Handler Address:		F/O 331 W.21 ST. F/O 331 W.21
Handler City,State,Zip:		NEW YORK, NY 10003
EPA ID:		NYP004076832
Contact Name:		ANTHONY DRUMMINGS
Contact Address:		IRVING PLACE
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PLACE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No

CON EDISION - SB3785 (Continued) **1007207850**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2001

Click Here for Biennial Reporting System Data:

Historic Generators:
Receive Date: 20020601
Handler Name: CON EDISION - SB3785
Federal Waste Generator Description: Not a generator, verified

CON EDISION - SB3785 (Continued) **1007207850**

State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020602
Handler Name: CON EDISION - SB3785
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020531
Handler Name: CON EDISION - SB3785
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: F/O 331 W.21 ST. F/O 331 W.21
City,State,Zip: NEW YORK, NY 10003
Country: USA
EPA ID: NYP004076832
Facility Status: Not reported
Location Address 1: 331 W 21ST ST

CON EDISION - SB3785 (Continued) **1007207850**

Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10020
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004076832
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

AD446 **LOMEL REALTY CORP** **NY AST** **U004047444**
SW **418 WEST 14TH ST** **N/A**
< 1/8 **NEW YORK, NY 10014**
0.121 mi.
637 ft. **Site 3 of 9 in cluster AD**

Relative:
Lower

Actual:
13 ft.

AST:
Name: LOMEL REALTY CORP
Address: 418 WEST 14TH ST
City,State,Zip: NEW YORK, NY 10014
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-098604
Program Type: PBS
UTM X: 583878.88399
UTM Y: 4510511.48208
Expiration Date: N/A
Site Type: Unknown

Affiliation Records:
Site Id: 2886
Affiliation Type: Facility Owner
Company Name: LOMEL REALTY CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 418 WEST 14TH ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10014-1063
Country Code: 001
Phone: (212) 242-5267
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

LOMEL REALTY CORP (Continued) **U004047444**

Site Id:	2886
Affiliation Type:	Mail Contact
Company Name:	MEILMAN MANAGEMENT & DEVELOPMENT LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	418 WEST 14TH ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10014-1063
Country Code:	001
Phone:	(212) 242-5267
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	2886
Affiliation Type:	Facility Operator
Company Name:	LOMEL REALTY CORP
Contact Type:	Not reported
Contact Name:	LOMEL REALTY CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 242-5267
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	2886
Affiliation Type:	Emergency Contact
Company Name:	LOMEL REALTY CORP
Contact Type:	Not reported
Contact Name:	JACK MEILMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 242-5267
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	3664
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

LOMEL REALTY CORP (Continued) **U004047444**

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/01/1996
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Z447 **520 WEST 19TH STREET** **RCRA-VSQG** **1010328350**
NW **516-522 W 19TH ST** **NY MANIFEST** **NYR000142745**
< 1/8 **NEW YORK, NY 10011**
0.122 mi.
643 ft. **Site 9 of 13 in cluster Z**

Relative: **Lower**
Actual: **9 ft.**

RCRA-VSQG:

Date Form Received by Agency:		20070101
Handler Name:	520 WEST 19TH STREET	
Handler Address:		516-522 W 19TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYR000142745
Contact Name:		JOHN JACOBSON
Contact Address:		W 14TH ST
Contact City,State,Zip:		NEW YORK, NY 10014
Contact Telephone:		212-367-8604
Contact Fax:		Not reported
Contact Email:		JOHN@BISHOPSCOURT.NET
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		W 14TH ST
Mailing City,State,Zip:		NEW YORK, NY 10014
Owner Name:		516-522 WEST 19TH STREET LLC

520 WEST 19TH STREET (Continued) **1010328350**

Owner Type:	Private
Operator Name:	NO NAME FOUND
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

520 WEST 19TH STREET (Continued) **1010328350**

Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D002
Waste Description: CORROSIVE WASTE

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: 516-522 WEST 19TH STREET LLC
Legal Status: Private
Date Became Current: 20041223
Date Ended Current: Not reported
Owner/Operator Address: 430 W 14TH ST
Owner/Operator City,State,Zip: NEW YORK, NY 10014
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NO NAME FOUND
Legal Status: Private
Date Became Current: 20001223
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: 516-522 WEST 19TH STREET LLC
Legal Status: Private
Date Became Current: 20001223
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: 516-522 WEST 19TH STREET LLC
Legal Status: Private
Date Became Current: 20041223
Date Ended Current: Not reported
Owner/Operator Address: 430 W 14TH ST
Owner/Operator City,State,Zip: NEW YORK, NY 10014
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

520 WEST 19TH STREET (Continued) **1010328350**

Historic Generators:

Receive Date:		20061108
Handler Name:	520 WEST 19TH STREET	
Federal Waste Generator Description:		Large Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20070101
Handler Name:	520 WEST 19TH STREET	
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20061109
Handler Name:	520 WEST 19TH STREET	
Federal Waste Generator Description:		Large Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	23611
NAICS Description:	RESIDENTIAL BUILDING CONSTRUCTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	520 WEST 19TH ST LLC
Address:	516-522 W 19TH ST
City,State,Zip:	NEW YORK, NY 10011

520 WEST 19TH STREET (Continued) **1010328350**

Country:	USA
EPA ID:	NYR000142745
Facility Status:	Not reported
Location Address 1:	416-522 WEST 19TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000142745
Mailing Name:	520 WEST 19TH ST LLC
Mailing Contact:	JOHN JACOBSEN
Mailing Address 1:	516 WEST 19TH ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10014
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2123678604

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJR000029987
Trans2 State ID:	Not reported
Generator Ship Date:	11/27/2006
Trans1 Recv Date:	11/27/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/27/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000142745
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD045995693
TSDF ID 2:	Not reported
Manifest Tracking Number:	000294613JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported

520 WEST 19TH STREET (Continued) **1010328350**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	20
Units:	T - Tons
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Y448 **CON EDISON** **NY MANIFEST** **S117058708**
East **316-12 W 20TH ST & 9TH AVE E O** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.123 mi.
647 ft. **Site 6 of 12 in cluster Y**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	316-12 W 20TH ST & 9TH AVE E O
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004508412
Facility Status:	Not reported
Location Address 1:	316 W 20 ST & 9TH AVE
Code:	BP
Location Address 2:	SB 3630
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004508412
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018

CON EDISON (Continued) **S117058708**

Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2014
Trans1 Recv Date:	04/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004508412
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407487GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Z449 **LOT 37,TAXBLOCK 691** **NY E DESIGNATION** **S108076933**
NNW **504 WEST 20 STREET** **N/A**
< 1/8 **MANHATTAN, NY 10011**
0.123 mi.
651 ft. **Site 10 of 13 in cluster Z**

Relative: E DESIGNATION:
Lower

Actual: Name:	LOT 37,TAXBLOCK 691
10 ft. Address:	504 WEST 20 STREET
City,State,Zip:	MANHATTAN, NY 10011
Tax Lot(s):	37
Tax Block:	691
Borough Code:	MN

LOT 37,TAXBLOCK 691 (Continued) **S108076933**

E-No:	E-142
Effective Date:	6/23/2005
Satisfaction Date:	Not reported
Ceqr Number:	03DCP069M
Ulurp Number:	050161 ZRM
Zoning Map No:	8b
Description:	Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date:	Not reported
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

Z450 **CON EDISON SERVICE BOX: 3404** **RCRA NonGen / NLR** **1016143823**
NW **511 W 19TH ST** **NY MANIFEST** **NYP004266086**
< 1/8 **NEW YORK, NY 10014**
0.124 mi.
657 ft. **Site 11 of 13 in cluster Z**

Relative: **Lower**
Actual: **10 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130322
Handler Name:	CON EDISON SERVICE BOX:	3404
Handler Address:		511 W 19TH ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004266086
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No

CON EDISON SERVICE BOX: 3404 (Continued) **1016143823**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130222
Handler Name:	CON EDISON SERVICE BOX: 3404
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON SERVICE BOX: 3404 (Continued) **1016143823**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130322
Handler Name: CON EDISON SERVICE BOX:	3404
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	511 W 19TH ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004266086
Facility Status:	Not reported
Location Address 1:	511 W 19TH ST
Code:	BP
Location Address 2:	SERV BOX 3404
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004266086
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA

CON EDISON SERVICE BOX: 3404 (Continued) **1016143823**

Mailing Phone: 2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/22/2013
Trans1 Recv Date:	02/22/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/22/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004266086
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010408531JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

W451 **TENTH AVENUE CAR WASH** **NY AST** **A100514949**
WSW **461-469 WEST 14TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.124 mi.
657 ft. **Site 7 of 17 in cluster W**

Relative:
Lower

Actual:
10 ft.

AST:

Name:	TENTH AVENUE CAR WASH
Address:	461-469 WEST 14TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-604379
Program Type:	PBS
UTM X:	583799.25699
UTM Y:	4510578.75253
Expiration Date:	N/A
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	26253
Affiliation Type:	Mail Contact
Company Name:	HOUSE CASTINGTENTH AVENUE CAR WASH
Contact Type:	Not reported
Contact Name:	DANIEL SCHULMAN
Address1:	% TENTH AVENUE CAR WASH
Address2:	450 WEST 15TH STREET - STE 202
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 645-2797
EMail:	SCHULMAN.DAN@GMAIL.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-01-28

Site Id:	26253
Affiliation Type:	Emergency Contact
Company Name:	TENTH AVENUE CAR WASH
Contact Type:	Not reported
Contact Name:	EREZ SCHTERNLICHT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 855-0560
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-08-13

Site Id:	26253
Affiliation Type:	Facility Owner
Company Name:	TENTH AVENUE CAR WASH
Contact Type:	Not reported
Contact Name:	Not reported

TENTH AVENUE CAR WASH (Continued) **A100514949**

Address1:	461-469 WEST 14TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 645-2797
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-01-28

Site Id:	26253
Affiliation Type:	Facility Operator
Company Name:	TENTH AVENUE CAR WASH
Contact Type:	Not reported
Contact Name:	QUILVIO MUNOZ (PRIOR TO CLOSE)
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 645-2797
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-01-28

Tank Info:

Tank Number:	201
Tank Id:	58106
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
D00 - Pipe Type - No Piping
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
G99 - Tank Secondary Containment - Other
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/2000

TENTH AVENUE CAR WASH (Continued) **A100514949**

Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/15/2012
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

Tank Number:	202
Tank Id:	58107
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
G99 - Tank Secondary Containment - Other
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/2000
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/15/2012
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	203
Tank Id:	58108
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground

TENTH AVENUE CAR WASH (Continued) **A100514949**

D00 - Pipe Type - No Piping
G99 - Tank Secondary Containment - Other
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/2000
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/15/2012
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	lube oil
Tank Number:	204
Tank Id:	58109
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
D00 - Pipe Type - No Piping
G99 - Tank Secondary Containment - Other
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/2000
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/14/2012

TENTH AVENUE CAR WASH (Continued) **A100514949**

Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: lube oil

Tank Number: 205
Tank Id: 58110
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
G99 - Tank Secondary Containment - Other
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 04/01/2000
Capacity Gallons: 1000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 06/14/2012
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: lube oil

Tank Number: 206
Tank Id: 58111
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
D00 - Pipe Type - No Piping
G99 - Tank Secondary Containment - Other
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin

TENTH AVENUE CAR WASH (Continued) **A100514949**

L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/2000
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/14/2012
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	207
Tank Id:	58112
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G99 - Tank Secondary Containment - Other
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/2000
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/14/2012
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	lube oil

TENTH AVENUE CAR WASH (Continued) **A100514949**

Tank Number: 208
Tank Id: 58113
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
G99 - Tank Secondary Containment - Other
A00 - Tank Internal Protection - None
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 04/01/2000
Capacity Gallons: 500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 06/14/2012
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: lube oil

W452 **GAS STATION/CAR WASH** **NY Spills** **S110140247**
WSW **461-469 WEST 14TH STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.124 mi.
657 ft. **Site 8 of 17 in cluster W**

Relative: **Lower**
Actual: **10 ft.**

SPILLS:
Name: GAS STATION/CAR WASH
Address: 461-469 WEST 14TH STREET
City,State,Zip: MANHATTAN, NY
Spill Number/Closed Date: 0911962 / 2015-04-10
Facility ID: 0911962
Facility Type: ER
DER Facility ID: 373747
Site ID: 424821
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 3101
Spill Date: 2010-02-11
Investigator: JAKOLLEE
Referred To: Not reported

GAS STATION/CAR WASH (Continued) **S110140247**

Reported to Dept:	2010-02-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-02-11
Spill Record Last Update:	2015-06-22
Spiller Name:	RICHARD STUMBO
Spiller Company:	UNKNOWN
Spiller Address:	461-469 WEST 14TH STREET
Spiller Company:	999
Contact Name:	RICHARD STUMBO
DEC Memo:	"02/12/10-Hiralkumar Patel. alternate addresses: 444-460 W 15th St, 447-469 W 14th St, 58-76 10th Ave PBS #: 2-604379. as per PBS record, site has following tanks, in-service: - five 6,000 gal gasoline USTs - one 6,000 gal diesel UST - one 2,000 gal waste oil AST in contact with soil - two 2,000 gal lube oil ASTs in contact with soil - two 1,000 gal lube oil ASTs in contact with soil - three 500 gal lube oil ASTs in contact with soil Other spills on property: 0102822, 0103052, 0412142, 0412147, 0909956, 0909957 spill # 0102822 reported on 06/13/2001 by FDNY about spill in gas station. spill closed on 03/28/2005 and referred to spill # 0103052. documents found on e-docs. as per document, line failed a test on super un-leaded on 06/23/2001. spill # 0103052 reported on 06/19/2001 by Fenley & Nicol due to equipment failure. no info about any actual leak. spill closed on 07/12/2006 assuming work completed. nothing in e-docs. spill # 0412142 reported on 02/14/2005 as 500 gal gasoline spilled during delivery. According to caller's remarks, 200 gal was recovered and ~300 gal went into ground. Fenley & Nicol was hired to do subsurface investigation. case closed on 05/17/2006 and referred to old case 0103052. documents found on e-docs. spill # 0412147 reported on 02/14/2005, duplicate spill number for 500 gal gasoline spill. spill # 0909556 reported on 12/08/2009 due to foul smell of unknown material. DEC Ketani inspected site and based on inspection, he close the case on 12/08/2009. few pics on e-docs. spill # 0909957 reported on 12/08/2009 due to foul smell. duplicate spill. spill closed and referred to spill # 0909956. reviewed old files. 1) 06/09/2001: letter from Chelsea Car Wash: - FDNY responded to site on 06/13/2001 due to gasoline odors in basement - FDNY issued violation (violation # A03676) - Fenley & Nicol was hired to do tank and line test - all tanks passed test. lines for regular product tank passed test - testing of super line revealed a problem with line that feeds super and special to dispensers on 10th ave side of station - no problem with line that feeds super and special to dispensers (# 2, 3 and 5) along 14th street side of station - according to document from F&N, leak was found in super line going from dispenser #7 to #6 2) 04/13/2005: Limited Subsurface Investigation Report from Fenley & Nicol: - advanced 1 soil boring (SB-1) to depth of 10-14 ft bg in vicinity of spill area (# 0412142) - collected soil and groundwater sample from this one boring - depth to groundwater in the vicinity of the site is approx. 14 ft bg - regional groundwater flow in the

GAS STATION/CAR WASH (Continued) **S110140247**

vicinity of the site appears to be toward the west - found 556 ppb MTBE in soil sample from 10-14 ft depth less than ---------- - found 8,207 ppb MTBE in groundwater sample less than --------- 3) 09/09/2005: Limited Subsurface Investigation Report from Fenley & Nicol: - three borings (SB-1 to SB-3) were advanced to a depth of 14 ft bg (to groundwater interface) and five soil samples were collected - one boring (SB-1) was advanced in area of the spill # 0412142; south of the car wash exit - two other borings were advanced on the northwest corner (SB-2) and southwest edge (SB-3) of the property where a previous spill (0103052) occured - soil samples generally consisted of medium to coarse-grained brown sand less than --------- - soil samples SB-2 at 14 ft depth and SB-3 at 14 ft depth indicated olfactory evidence of impact and detected 2,878 ppm (at 14 ft in SB-2) and 2,598 ppm (at 14 ft depth in SB-3) on PID - found heavy soil contamination in SB-2 and SB-3 at 14 ft depth - no contamination found in shallow soil samples from SB-2 and SB-3 at 8 ft depth - no groundwater samples collected soil analyticals:
----------SB-2----------SB-3 14 ft 14 ft
Benzene----------500*----------500*
Toluene----------39,698----------58,397
Ethylbenzene----------24,720
Xylene----------209,336----------205,834
1,2,4-Trimethylbenzene----113,000----------86,052
1,3,5-Trimethylbenzene-----23,939----------30,175
Naphthalene----------12,431
MTBE----------500*----------1,000* * - MDL for Benzene was 500 ppb (above limit) in both samples and MDL for MTBE was 500 ppb for sample SB-2 and was 1,000 ppb for sample SB-3 11:50 AM:- received call from Oliver from Envt'l Maintenance contractor. Oliver is preparing rpt. asked Oliver to submit lab data and site plan for review and rpt once its ready. Richard Stumbo Environmental Maintenance Contractors, Inc. Ph. (914) 232-7355; email: rstumbo@enviromain.com Francis Oliver Ciriaco Environmental Maintenance Contractors, Inc. PH. (914) 232-7355; Fax (914) 232-7357; email: fciriaco@enviromain.com 02/16/10-Hiralkumar Patel. received email from Allan Ciriaco (at 3:16 PM on 02/15/10) from EMC. Allan forgot to attach Phase II report. Sent email to Allan asking to send report. 02/17/10-Hiralkumar Patel. 10:36 AM:- spoke with Mr. Stumbo about Phase II rpt, he will send copy of rpt. Mr. Stumbo mentioned that currently site has Mobil gas station and car wash center. current owner is planning to demolish existing structures and build multi-story commercial. owner is planning to dig to 18 ft depth. asked Mr. Stumbo to send property owner's contact info also. 10:45 AM:- spoke with Mr. Munoz, general manager of 10th ave car wash llc. Mr. Munoz mentioned that they owned gas station and car wash business. 10th ave car wash llc. owns all gas tank systems and operate/maintain it. Mr. Munoz is on-site for 10 years (and was there during spill in 2005). Mobil is providing gas only. 10th Avenue Car Wash LLC. **business and tanks owner** 70 10th Avenue New York, NY 10011 Attn.: Quiolvio Munoz, General Manager Ph. (646) 486-4541; Fax (646) 486-4538 email: chelcarwas@aol.com reviewed old reports and found confusing data about dispenser locations along 10th ave. as per site map from 2001, site had three dispensers # 6, 7 & 8 in row. as per site map from Apr 2005, site had three pump islands (dispensers 1/2, 3/4 and 5/6) in row close to 10th ave and two pump island (dispensers 7 and 8) in row next to on-site building. this map doesn't show dispenser #6 in row of dispenser #7. and as per site map

GAS STATION/CAR WASH (Continued) **S110140247**

from Nov. 2005 only two dispenser islands are in row in each group (instead of three as per Apr 2005 map). 02/18/10-Hiralkumar Patel. 11:17 AM:- spoke with Mr. Stumbo and informed that Phase II hasn't received yet. Mr. Stumbo will email report by noon. 11:50 AM:- received email from Allan Ciriaco (aciriaco@enviromain.com) from EMC with their client's contact info. Brandon Miller **potential buyer** Real Estate Equities Corporation 18 East 48th Street, Penthouse New York, NY 10017 Ph. (212) 682-2121 (O);(917) 750-1138 (C); Fax (212) 682-3920 email: brandon@reec-ny.com 1:33 PM:- left message for Mr. Miller. 1:36 PM:- spoke with Mr. Brill at Real Estate Equities. Mr. Brill mentioned that they are in process of buying this property and will redevelop this property into retail stores. site will have basement and ground floor structure. no planning for residential complex. Jordan Brill email: jordan@reec-ny.com owner of 450 W 15th Street, adjacent property which was part of subject site in past, is: RP Stellar Milk Owner, LLC. c/o Stellar Management 156 William Street New York, NY 10038 Attn.: Richard Randberg Ph. (212) 840-7625; email: rrandberg@stellarmanagement.com 1:48 PM:- received Phase II report from Allan. - limited Phase II was dated 08/22/08 and was performed by Property Solutions - Phase I was performed by Property Solutions dated 06/24/08 - property is utilized as gasoline service station, oil change garage, carwash and convenience store - total of 8 dispenser islands are located on property: 5 in southern portion of site parallel to W. 14th st. and 3 in northern portion of site parallel to 10th ave. - six 6,000 gal USTs and ten ASTs of various volumes on-site less than ---------- - subject property is covered by a portion of the highline elevated railway - historically, subject property consisted of several stores, dwellings, offices, wagon yard, lumber yards and scrap iron & metal yard - property was utilized as a parking lot from at least 1979 until 1996 - subject building was constructed after 1997 and prior to 2000 - from 07/29/08 through 08/01/08, Property Solutions advanced total of ten soil borings (SB-01 through SB-10) to a depth of 20 ft bg - boring SB-01 was advanced to the northwest of the gasoline USTs - borings SB-02 to SB-05 were advanced on northern portion of site in vicinity of former fuel supply line leak - borings SB-06 to SB-10 were advanced on southern portion of site in area of gasoline USTs - groundwater was encountered in all ten borings at 12 ft bg less than ---------- - two soil samples collected from each borings except SB-09 where three soil samples were collected for analysis - on 08/04/08 to 08/06/08, Property Solutions installed total of six monitoring wells (MW-01 through MW-06) to a depth of 20 ft bg, with 10 ft of screen - well MW-01 was installed in former location of SB-06 located to west of gasoline USTs - wells MW-02 and MW-03 in the northern portion of the site to the west of fuel dispenser islands (at former boring locations SB-02 and SB-3, respectively) - well MW-04 was installed in location of former boring SB-04 located to north of gsoline USTs - well MW-05 was installed in location of former boring SB-09 located to east of gasoline USTs - well MW-06 was installed approx. two ft from SB-01 located to the west of the subject building along 10th ave - soil encountered at the site generally consisted of red to brown coarse to fine sand with some gravel to a depth of approx. 14 ft bg - from 14 ft bg to 20 ft bg the soils encountered consisted of red to brown coarse to fine sand with some areas of sand and gravel - several areas of silt were also encountered at approx. 17 to 20 ft bg - found high PID readings in few borings - found petroleum odors around 16 ft bg in borings SB-03, SB-04, SB-05 - found petroleum

GAS STATION/CAR WASH (Continued) **S110140247**

odors around 19 ft bg in boring SB-06, but no PID readings - found some VOC contamination in few samples and in groundwater samples soil analyticals:
----------SB-02----------SB-03----------SB-05
18.5-19.5 ft 16.5-17.5 ft 15-16 ft
Xylene----------2,900----------620
1,2,4-Trimethylbenzene----------2,200----------20,000----------5,900
1,3,5-Trimethylbenzene----------690----------8,300----------1,900
Naphthalene----------840
water analyticals:
----------MW-01-------MW-02-------MW-03-------MW-06
Benzene----------220----------220
Toluene----------13,000----------2,400
Ethylbenzene----------3,200-------1,600---------110---------860
Xylene----------15,000------24,000---------350-------3,700
1,2,4-Trimethylbenzene------2,900-------5,000-------4,500---------750
1,3,5-Trimethylbenzene--------740-------1,300-------1,300---------170
Naphthalene----------580-------1,000---------170---------180
MTBE----------390 PID values:
sample #/depth (in ft bg)----------PID values (in ppm)
SB-03/16.5----------247
SB-03/17.0----------311
SB-03/17.5----------236
SB-03/18.0----------162
SB-03/19.0----------20
SB-04/15.0----------229
SB-04/15.5----------295
SB-04/16.0----------0
SB-05/15.0----------241
SB-05/16.0----------398
SB-05/16.5----------10
SB-05/18.0----------111
SB-05/18.5----------28 report missing boring logs for borings SB-07 to SB-10. 2:54 PM:- spoke with Allan and asked him to submit copy of Phase I report and boring logs for SB-07 to SB-10 and scaled site map including locations of all existing tanks, dispenser islands, borings and wells and site specific groundwater flow direction. Allan mentioned that Phase II work was done by Property Solutions Inc. in 2008 and EMC was reported spill based on results of Phase II in 2008. EMC hasn't done any soil/groundwater investigation themselves. 4:37 PM:- left message for Mr. Randberg at Stellar managment. 02/22/10-Hiralkumar Patel. 10:09 AM:- received message from Mr. Randberg. 10:42 AM:- received email from Francis Oliver from EMC with boring logs for borings B-7 to B-10. no high PID noted in these borings. 10:48 AM:- spoke with Mr. Randberg. Mr. Randberg mentioned that his company owns office building at 450 W 15th Street and doesn't own gas station/car wash. Mr. Randberg mentioned that gas station, car wash and office building were owned by single company back in days, but was separated and someone else owns property of gas station/car wash. Mr. Randberg baught 450 W 15th street in late 2006. 1:30 PM:- left message for Mr. Munoz. 1:52 PM:- spoke with Mr. Miller who gave property owner's contact info. Mulnick LLC. **owner of car wash/gas station property** c/o Milk Studios 450 W 15th Street, 8th Floor New York, NY 10011 Attn.: Erez Shternlicht PH. (212) 645-2797 email: erez@milkstudios.com 2:02 PM:- left message for Ketty at Mr. Shternlicht's office. 2:12 PM:- received message from Ketty

GAS STATION/CAR WASH (Continued) **S110140247**

(917-515-2055). 2:35 PM:- spoke with Mr. Shternlicht. he confirmed that he owned both properties in 2005 and then sold office building in 2006. informed him about unresolved spill issue from 2005. 02/23/10-Hiralkumar Patel. 8:08 AM:- sent email to Mr. Munoz with copy of PBS form to correct site address (as tanks are located at 70 10th ave and not at 450 W 15th street). 9:08 AM:- sent letter to Mr. Munoz and Mr. Shternlicht requiring Phase I, scaled site plan including former tank systems and boring/wells and work plan for complete delineation of soil and groundwater contamination. Phase I and work plan are due on 03/23/10. letter emailed to Mr. Munoz, Mr. Shternlicht, Mr. Miller, Mr. Stumbo and Mr. Randberg. 02/25/10-Hiralkumar Patel. 10:50 AM:- received email from EMC with letter from Mulnick Realty, LLC. authorizing 459 W 14th Realty Associates, LLC. to conduct remediation at the site. 03/02/10-Hiralkumar Patel. 2:35 PM:- received work plan including two scaled site maps. first map, dated 03/13/1998, is plan with proposed tanks and pump islands locations (that could be before tank system installed). and this map doesn't show location of other tanks on property. second map, dated 02/15/2009, shows recent boring/well locations and proposed well locations on map. proposed work plan is not acceptable as proposing to install three wells more than 90 ft apart from each other. requires monitoring wells within 25 ft distance from each other. 2:41 PM:- received Phase I report from Allan from EMC. as per Sanborn maps review, site was wagon yard and iron and metal yard from 1895 to 1921, vacant lot from 1950 to 2000 and then convereted to gas station/car wash/lube change facility. 03/11/10-Hiralkumar Patel. 3:26 PM:- spoke with (and sent email to) Francis at EMC. informed him that proposed wells are more than 90 ft away from each other and any underground utility/structure can affect GW flow direction. asked Francis to submit revised work plan including wells within 25 ft from each other in each affected area. also asked for scaled site map showing all existing tank systems (including remote fill ports, dispenser islands/boiler, piping etc. and not proposed plan as submitted earlier), all former/current borings/wells, and location of proposed wells. 03/17/10-Hiralkumar Patel. 1:27 PM:- received investigation work plan from Allan Ciriaco from EMC. proposed to install total of 13 monitoring wells. proposed work plan is not acceptable as doesn't include any investigation downgradient from the site (along 10th ave). 03/23/10-Hiralkumar Patel. 11:03 AM:- left message for Mr. Stumbo at EMC. 3:54 PM:- received message from Mr. Stumbo. 03/24/10-Hiralkumar Patel. 8:20 AM:- sent email to Mr. Stumbo informing that the proposed work plan is not acceptable as doesn't include any downgradient investigation. asked to submit revised work plan. email copied to Fancis (EMC), Mr. Munoz, Mr. Miller and Mr. Shternlicht. 9:55 AM:- received revised work plan. 11:25 AM:- sent work plan approval letter to Mr. Munoz and Mr. Shternlicht. letter emailed to Mr. Munoz, Mr. Shternlicht, Mr. Miller and Mr. Stumbo. 05/04/10-Hiralkumar Patel. 11:27 AM:- received email from Allan from EMC with investigation report. abstract: - installed total of 13 soil borings to a depth of 20 ft bg - collected soil sample at highest PID reading - installed monitoring wells at each boring location to depth of 20 ft bg with 10 ft of screen - found groundwater at 13 ft bg - soil encountered at site generally consisted of brown coarse to fine sand with some gravel soil analyticals:

----------SB-04-------SB-08-------SB-09-------SB-10

16 ft 18 ft 16 ft 16 ft

GAS STATION/CAR WASH (Continued) **S110140247**

Ethylbenzene----------4,900
Xylene----------18,400------49,400
1,2,4-Trimethylbenzene-----1,400-------2,500------14,000------42,000
1,3,5-Trimethylbenzene-------300---------620-------3,900------13,000
Naphthalene----------2,300-------5,600
Isopropylbenzene----------3,300
n-Propylbenzene----------6,200
groundwater analyticals:
----------MW-04-----MW-05-----MW-06-----MW-07-----MW-08-----MW-09-----MW-10 Benzene----------20
Toluene----------160
Ethylbenzene----------810-------230----------290-----4,400-----2,600
Xylene----------3,450-----1,250--------84-----2,100----32,000----25,000
1,2,4-Trimeth.ben.-----4,600-----2,200-----1,200-----3,400----12,000----68,000-----6,900
1,3,5-Trimeth.ben.-------700-------720--------50-------590-----1,700-----1,100-----1,400
Naphthalene----------100-------300-------210-------220-------610-----1,000-----1,300
Isopro.ben.
----------220----------220-------730----------
----500
n-Pro.ben.
----------800----------290-------730-------700-----620 05/05/10-Hiralkumar Patel. 2:19 PM:- sent email to Allan requiring him to submit revised report as following missing: - boring logs doesn't include PID radings and any petroluem odors at different depths - sample recovery info missing in boring logs MW-7 and MW-8 - boring log for MW-2 is missing - well size - no info about soil sampling depths - submitted site map is not clear and un-scaled - site-specific groundwater flow direction asked Allan to submit scaled site map showing following: - existing tanks, dispenser island and remote fill ports - all current/previous boring/wells - site specific groundwater flow direction also asked Allan about deepest dry soil sample, as report only indicates about soil sample at highest PID readings. email copied to Mr. Stumbo, Mr. Munoz, Mr. Shternlicht and Mr. Miller. 3:45 PM:- received call from Allan requesting extension for submitting required scaled site map. approved request and asked to submit revised rpt with missing info by end of 05/14/10. 05/06/10-Hiralkumar Patel. 2:24 PM:- received email from Allan with revised report. revised report is not acceptable as doesn't include site-specific groundwater flow direction and scaled site map. also report has added appendix with PID readings during boring, but requires to have detailed boring logs with soil description, observations and PID readings on one page. as per report, wells installed on-site are 2 inch in diameter. 05/07/10-Hiralkumar Patel. 11:30 AM:- spoke with Allan. informed him that the submitted revised report is not acceptable. asked him to submire re-revised report with: - detailed boring log with soil type, observation and PID readings (instead of separate appendix for PID readings) - site-specific groundwater flow direction (instead of assumptions based on nearby river) - scaled site map including only property line, building outline, underground gasoline tanks, remote fill ports, dispenser islands, current/former boring/well locations and site-specific groundwater flow direction - sample depth info in

GAS STATION/CAR WASH (Continued) **S110140247**

summary table of soil analyticals 12:45 PM:- left message for Mr. Shternlicht. 12:47 PM:- left message for Mr. Miller. 1:51 PM:- sent email to Allan requiring to submit re-revised report. email copied to Mr. Miller, Mr. Munoz and Mr. Shternlicht. checked PBS record. site address in PBS record hasn't changed yet. 2:01 PM:- sent email to Mr. Munoz with PBS correction form and asked him to submit form by end of 05/21/10 to avoid legal referral. email copied to Mr. Miller and Mr. Shternlicht. 05/11/10-Hiralkumar Patel. 4:51 PM:- received email from Allan with work plan for addt'l soil/groundwater investigation. 05/12/10-Hiralkumar Patel. 2:00 PM:- received call from Allan inquiring about approval status on submitted work plan. informed Allan that the department is still waiting for re-revised investigation report. so, once report is received and reviewed, the department will send STIP to property owner and submitted work plan will be reviewed only after STIP signed. 2:15 PM:- received re-revised report from Allan which is still missing site-specific groundwater flow direction. 3:25 pm:- spoke with Rich at EMC about site-specific groundwater flow direction. Rich mentioned that they can't triangulate existing wells as GW in all wells found at same depth during soil borings. no well survey done yet. asked Rich to survey existing wells to confirm groundwater depth and determine site-specific groundwater flow direction and then submit revised report including site-specific groundwater flow direction and groundwater contour map. 05/17/10-Hiralkumar Patel. 11:15 AM:- spoke with Allan. asked him to find out source and discharge of water used in car wash operation. 12:35 PM:- received call from Allan. he stated that water for car wash comes from city supply system and used water goes into city sewer system. 05/18/10-Hiralkumar Patel. 9:10 AM:- received email from Allan with GW contour map. after discussing with DEC Austin, case transferred to DEC Vadim Brevdo. summary: - line was found leaking suppling super gas to dispenser #6 (leak was found in portion between dispenser #7 to #6) - found high MTBE (no other components) in soil and groundwater sample from boring installed in area betweeen dispenser #7 and #6 along 10th ave - found high VOC contamination (BTEX and MTBE) in soil samples at groundwater interface along 10th Avenue which is western (and downgradient) side of the property - according to Phase II done in Aug. 2008, groundwater was found at 12 ft bg - according to Phase II done in Aug. 2008, site has total of eight dispenser islands: five are located in the southern portion of the site parallel to West 14th street and three are located in the northern portion of the site parallel to 10th ave DEC requires: 1) scaled site plan including all current/former tank systems, 2) complete soil and GW investigation, 3) site specific GW flow direction, 4) correction of PBS record (PBS record shows site address as 450 W 15th street, but tanks are located at 70 10th Ave) **refer to spill #: 0412142 also.** 05/28/10: This spill case transferred from K. Patel to J. Kolleeny. - JK 06/10/10: Reviewed Supplemental Investigation Work Plan rpt by Envt'l Maintenance Contractors (consultant), dated 6/9/10 (in eDocs). Work plan proposes drilling 13 soil borings adjacent to existing monitoring wells to delineate contamination vertically (below water table) as requested by Kumar Patel of DEC, and 4 borings off-site, to be converted into monitoring wells. Based on field observations, addt'l off-site borings/wells may be drilled. I sent approval letter (in eDocs) to Mr. Brandon Miller (RP), cc's to Rich Stumbo & Allan Ciriaco of EMC, asking for 1 more off-site boring/well across 10th Ave. from MW-9 (currently worst well), asked for highest PID interval

GAS STATION/CAR WASH (Continued) **S110140247**

in on-site borings to be sampled for lab analysis, asked for all wells to be sampled, and asked that summary rpt include conceptual remedial strategy proposal. Set deadline of 8/20/10 for submission of summary rpt. - J. Kolleeny 06/15/10: On 6/11/10, received email from Allan Ciriaco of EMC, with attached revised site plan, modified to include addt'l off-site boring/well (in eDocs). - J. Kolleeny 06/22/10: On 6/18/10, received email from Rich Stumbo of EMC: Please find attached copy of revised drawing [in eDocs] indicating locations of proposed boring & mon well locations for site. Based on site reconnaissance, DIG SAFE search and ground penetrating survey (GPS), we discovered there is no access across street from property on 15th St (north side of property) because there are markings on sidewalk that state no drilling and DIG SAFE & GPS indicate that there are utility lines under areas of sidewalk on that side of street, therefore we will not perform any borings on that side of property; there are also no drilling markings in areas across street from property on 10th Ave, however we did find location SW of property across 10th Ave as indicated on attached drawing. Please note that for supplemental investig work being performed we will only be drilling an addt'l two boring and mon well locations across streets from property, one being S across street on 14th and other SW across street on 10th Ave. We plan to start drilling activities on 6/18/10. Please review & approve or comment upon receipt. I sent reply: That's unfortunate; water table map sent earlier by Allan seemed to indicate more westerly GW flow direction, rather than southwesterly, and since most contaminated on-site wells were MW-8, MW-9 and MW-10, I felt that most likely area for off-site impacts would be directly across 10th Ave. I noticed that no drilling area along west side of 10th Ave seems to end at point where Avenue begins to curve to southwest to merge with West 14th Street - would it be possible to put well there? Also, I don't see indication that western edge of triangular median is off limits to drilling - could well be put there? If you can think of any other possible ways to safely investigate these areas for off-site impacts, please let me know. In any case, you should proceed with supplemental invest using revised site plan showing most recent proposed drilling locations, based on site recon, DIG SAFE search and GPR survey. If you can also put well or wells at locations I suggested above, please let me know. Rich wrote back: Unfortunately we will be unable to drill along West Side of B'way marking no drilling extends around that corner also I did not notice that we didn't mark that on drawing submitted a revised drawing will be submitted with this correction. Also western edge of triangular median has utilities and municipal pipe markings within as per DIG SAFE. We have permits available to drill in these areas, however it does not look like we will be able to safely access subsurface soils in these areas to further assess. We plan to be on site to begin with off-site borings that we can safely access. I will update you on any new info that becomes available as project moves along. - J. Kolleeny 08/19/10: On 8/18/10, received email from Allan Ciriaco of EMC with pdf file of supplemental investig rpt; after quick prelim review, called Allan and pointed out that fig in rpt only has estimated GW flow direction, not calculated water table contour map. I asked that gauging data for wells be used to generate map each time GW is sampled. He said he would prepare map, and asked if I had any other comments on rpt; I told him I would let him know. On 8/19/10, sent email to Allan, cc to Richard Stumbo of EMC, saying I had no other suggested revisions to rpt and requesting that he forward hard copy

GAS STATION/CAR WASH (Continued) **S110140247**

of rpt with GW gauging data table and water table contour map, and either a pdf of entire revised rpt or pdf of addt'l materials, upon receipt of which I will complete rpt review and respond to recommendations. - J. Kolleeny 08/23/10: Received email from Allan Ciriaco of EMC with attached pdf of water table contour map I requested (in eDocs). Awaiting hard copy of rpt. Sent email reply to Allan: Thanks for water table contour map. In future rpts, please include not only up-to-date water table map but also table with well gauging data. Do you have any idea why map you sent shows all well locations either as cones of depression in water table or mounding locations? - J. Kolleeny 08/26/10: Received email from Allan Ciriaco of EMC responding to my 8/23/10 question: 10th Avenue houses a large number of municipal utilities including water, electric, sewer, gas, etc. In addition, a number of large buildings could cause these anomalies in form of cones of depression at sampling/measuring locations. Also, please note that there are three (3) large buildings located in close proximity locations with subject site as detailed in contour map which could also cause these anomalies. (???) - J. Kolleeny 08/31/10: Received hard copy of 8/13/10 Supplemental Subsurface Investigation Rpt by EMC on 8/26/10 (in eDocs). Results of on-site soil borings for addt'l vertical delineation of soil contam and two off-site borings/wells, and GW sampling from all on- and off-site wells showed high levels of petroleum contam on-site, but lab analyses did not show significant contam in off-site samples (although there were elevated PID readings, signs of staining and odors). Rpt recommends preparation of remedial action plan for DEC approval prior to starting any construction work at site, and abatement of contaminated subsurf materials at site in accordance with DEC-approved RAP during proposed construction activities. On 8/31/10, I sent letter (in eDocs) approving recommendations to Brandon Miller, cc's to Allan Ciriaco and Richard Stumbo of EMC. Set due date of 11/05/10 for submission of RAP. - J. Kolleeny 09/09/10: Received email from Allan Ciriaco of EMC with attached pdf files of RAP and HASP on 9/2/10. Reviewed and on 9/9/10 sent email to Allan, cc's to Richard Stumbo of EMC and Brandon Miller: I've looked over RAP & HASP. While I agree with general approach of soil excavation to remove contaminated material that may be acting as on-going source of GW contamination and soil vapors, there are a number of things that should be added to or revised in rpts. 1. RAP should include data tables summarizing all available soil & GW sample results, and a site plan diagram (not aerial photo) showing all sampling locations, plus other site features (USTs, dispensers, etc.). Site plan should also show outline of area to be excavated. 2. RAP mentions collection of soil samples after removal of USTs plus associated piping and dispensers, but does not discuss collection of end-point soil samples following excavation of entire site to target depth of 24 feet. End-point samples should be collected from multiple locations at bottom of excavation (even though it will be below water table) and from excavation sidewalls (this may be difficult due to presence of sheeting, but must be done) to characterize any residual contamination left behind by remedial action. RAP should include an end-point sampling plan and discussion. 3. I strongly suggest that some sort of oxygen-enhancing compound or chemical oxidant be applied to open excavation bottom, regardless of whether or not residual contamination is present, to expedite cleanup of GW contamination, which RAP does not currently address. 4. RAP should mention that weekly updates will be provided to DEC during remediation, as we

GAS STATION/CAR WASH (Continued) **S110140247**

discussed, and that DEC case manager will be consulted (and if possible will visit site) before proceeding with backfilling of excavation and construction of planned on-site building. 5. RAP mentions that planned on-site building will include vapor barrier. Unless building will have basement that will extend into, or nearly to, water table, construction plans should also include install'n of sub-slab depressurization system to prevent potential vapor intrusion from any residual soil and/or GW contamination. This should be discussed in RAP. 6. RAP must include plans for follow-up GW monitoring, with replacement of wells destroyed during construction and/or install'n of new wells, to evaluate effectiveness of remedial actions. 7. Discussion in HASP of air monitoring during excavation is not adequate (Section 8.2 Air Emission Control). I have attached generic Community Air Monitoring Plan. This plan should be modified to be site-specific and either incorporated into HASP or submitted as a separate document (CAMP). Please make necessary changes and additions to these documents and re-submit them to my attention. Feel free to contact me if you have any questions. P.S.: Before removing UST system, Petroleum Bulk Storage application form must be submitted to our PBS unit notifying them of tank removal, within 30 days prior to removal. - J. Kolleeny 11/04/10: On 11/2/10, received email from Richard Stumbo of EMC with attached letter (in eDocs) requesting extension of Nov. 5th deadline for submission of RAP until Dec. 1, 2010. Letter states that addt'l time is needed for all parties involved to become familiar with requirements of RAP and associated HASP, and to review and make changes to those documents to finalize them. On Nov. 4th, I sent letter (in eDocs) to Brandon Miller, cc's to Rich Stumbo and Allan Ciriaco of EMC, approving deadline extension to Dec. 1st. - J. Kolleeny 12/14/10: On 12/7/10, received revised RAP and HASP from EMC. After review, contacted Rich Stumbo of EMC on 12/14/10 and listed following problems with RAP: needs more specific info on collection of end-point soil samples; needs more specific info on type and quantity of chem ox and/or oxygen-enhancing product(s) to be applied to subsurface; and needs to have post-remediation/construction replacement monitoring wells installed at locations of current wells MW-9 and MW-10. Rich said they will revise RAP and re-send. - J. Kolleeny 12/20/10: Spoke with Rich Stumbo of EMC, he said project engineer Langan wants to again reduce depth of excavation, this time from proposed 16 ft bgs to 13 ft bgs, due to concerns about quantity of dewatering required and possible adverse impacts on nearby structures. I expressed concern that remedial plan keeps being reduced in scope, and that I don't want construction to proceed at site without spill being adequately addressed. I pointed out that worst soil and GW contam are localized in NW area of site, and asked if deeper excavation could be done in that area. Rich stated he will consult with developer and engineers and get back to me, including with another revised RAP. I also noted that GW samples haven't been collected since April 2010, and would be beneficial to have up-to-date data. He agreed. I sent email to Brandon Miller (RP rep), cc to Rich Stumbo & Allan Ciriaco of EMC: Dear Mr. Miller: I have been reviewing draft Remedial Action Plan for this spill site, and also discussing project with Richard Stumbo of Envt'l Maintenance Contractors. I believe it would be useful and appropriate to collect addt'l GW data, since monitoring wells at site were last sampled in April 2010, more than 7 months ago. I'd like to request that round of GW samples be collected from all existing on- and off-site wells and submitted for lab analysis of gasoline-related

GAS STATION/CAR WASH (Continued) **S110140247**

compounds, and results forwarded to DEC to assist in our review of RAP. Prior to sampling, wells should be gauged for depth to GW and for presence of free product. Depth to water measurements should be used to construct up-to-date water table contour map showing GW flow direction. Any measurable free product should be recovered by appropriate methods. Feel free to contact me if you have any questions. - J. Kolleeny 01/10/11: On 1/7/11, received email from Allan Ciriaco of EMC: Per your request please find attached groundwater sample results for 70 10th Avenue Project. Should you have any questions or require addt'l information please don't hesitate to give us a call. Attached was lab data for 12/23/10 GW sampling event performed at my request (in eDocs). I sent email reply: These data should be tabulated, listing only results for gasoline-related compounds, and presented in revised RAP for this site. Spoke with Richard Stumbo of EMC on 1/10/11, he said these results would be incorporated into revised RAP currently in preparation. He also said that since they now plan to excavate soil only to about 10 ft bgs, they are considering injecting RegenOx into monitoring wells, rather than applying to open excavation, which will likely not extend into water table. I suggested injecting by GeoProbe rather than using existing wells, which could be compromised by injections. He agreed to explore this option. - J. Kolleeny 02/03/11: On 2/1/11, received email from Rich Stumbo of EMC: Please find attached drawing [in eDocs] detailing locations of injection points (noted in color red including SB-7A, SB-8A, SB-9A and SB-10A) for bio-remedial product injection via GeoProbe for this project. Please note that injection points will be same locations as borings advanced during supplt'l investigative site work (SISW). Current monitoring wells MW-05, -06, -07, -08, -09, and -10 noted in green color will be sampled approx 2 months after injections & prior to construction activities that will destroy these wells. These are wells that when GW samples were collected & analyzed indicated elevated concentrations of VOCs and/or SVOCs. If time permits before excavation activities, a second round of injections will occur and same wells if still available will be re-sampled to determine effectiveness of bioremediation. In addition please find attached post-construction monitoring well locations for monitoring GW after completion of construction. For further reference we have included Project Architect Site Plan [in eDocs] showing proposed cellar/subgrade construction. This site plan indicates locations of post-construction injection wells in cellar that we would install in order to continue injecting bioremedial product into GW after building has been completed. We would like to schedule bio-remedial product injections as soon as possible and wanted to see if you had any issues with locations of injection points and wells that would be sampled. We look forward to hearing back from you as soon as you get chance. On 2/3/11, I spoke with Aaron of EMC, suggested they also inject at boring locations SB-3A and SB-4A; then I sent email to Rich Stumbo: I spoke with Aaron at your office today, and I suggested also injecting at former boring locations SB-3A and SB-4A, in addition to locations you have proposed. Please include this in revised RAP and send it to me as soon as possible, as I would like to formally approve RAP prior to you beginning to implement work. Also, please always remember to reference project's DEC Spill Number (0911962) in any emails regarding this project, and in all other project-related correspondence. - J. Kolleeny 02/08/11: Reviewed final revised RAP by EMC, dated 1/25/11, received 2/7/11 (in eDocs). RAP proposes removal

GAS STATION/CAR WASH (Continued) **S110140247**

of all ASTs/USTs at site, injections of RegenOx in most impacted area, excavation of soil in most impacted area, down to 12 ft bg, application of RegenOx to bottom of pit, collection of end-pt samples, install'n of vapor barrier, install'n of three post-construction mon wells for follow-up monitoring, and if monitoring continues to show impacts, install'n of four post-construction injection wells in bldg cellar for addt'l RegenOx injections. I sent approval letter (in eDocs) to Brandon Miller, cc to Rich Stumbo of EMC, stating that in addition to 3 post-construction wells, any on- and/or off-site mon wells remaining after site development should be included in follow-up GW monitoring, and that if monitoring shows contamination remains elevated, addt'l remedial actions may be required. - JK 09/26/11: Received email from Allan Ciriaco of EMC with attached pdf file of GW Sample Analysis Rpt. After prelim review, sent email reply: Mr. Ciriaco, Can you please revise GW data comparison table to include line for Total VOCs and for Total SVOCs? I find that is more convenient way to evaluate changes in GW quality than looking at increases and decreases in concentrations of individual compounds. Please also include site plan diagram showing monitoring well locations and injection locations, and site location figure with USGS Topo Quadrangle as base map, or Hagstrom Map, Google Earth Map, or equivalent as base map. - JK 09/27/11: Received email from Allan Ciriaco of EMC with GW Sample Analysis Rpt dated 9/23/11, with data table revised as I requested to include lines for total VOCs/SVOCs (rpt in eDocs). Table gives GW results for Dec. 2010, prior to injections, for April 2011 after 1st round of injections, and for July 2011 after 2nd round of injections. Data show total VOCs increased significantly for most wells after injections (esp after 2nd round). For example, MW-5 had 285 ug/L tVOCs in Dec. 2010, 877 ug/L tVOCs in April 2011, and 1,125 ug/L in July 2011; MW-6 had 172 ug/L tVOCs in Dec. 2010, 97 ug/L in April 2011, and 17,452 ug/L in July 2011; MW-7 had 1,830 ug/L tVOCs in Dec. 2010, 1,198 ug/L in April 2011, and 4,214 ug/L in July 2011; MW-8 had 1,138 ug/L tVOCs in Dec. 2010, 2,110 ug/L in April 2011, and 4,075 ug/L in July 2011; MW-9 had 9,607 ug/L tVOCs in Dec. 2010, 29,718 ug/L in April 2011, and 27,310 ug/L in July 2011. Of seriously contaminated wells, only MW-10 showed decreases from initial contam levels: 17,109 ug/L tVOCs in Dec. 2010, 13,374 ug/L in April 2011, and 9,810 ug/L in July 2011. Rpt states that a 3rd round of RegenOx injections was performed on Sept. 21-22, 2011, and that GW will be sampled again on Nov. 17, 2011. - J. Kolleeny 09/28/11: Sent email to Allan Ciriaco of EMC: Allan, I looked over rpt and notice that on 1st page, it says that another round of injections is recommended, but then on next page it says that injections were performed on Sept. 21st & 22nd. So am I correct in assuming that this rpt does not require DEC response/approval? Also, I noticed that levels of total VOCs in many wells increased after first two rounds of injections and are pretty high in several wells. If high levels of total VOCs persist after 3rd round of injections, you might consider doing vacuum-enhanced fluid recovery with vac truck on worst wells to try to bring dissolved-phase contam levels down and pull water through soil to strip soluble contaminants off soil. This would also bring air into subsurface to promote biodegradation. Later, sent another email: Allan, I have another question: besides RegenOx injections, are other elements of approved RAP, such as UST removal, contaminated soil removal, application of RegenOx to excavation pit, etc., yet to be performed? - J. Kolleeny 09/30/11: On 9/29/11, received email from

GAS STATION/CAR WASH (Continued) **S110140247**

Richard Stumbo of EMC, responding to my question: Jonathan, There are other elements of RAP that have not been done. Ownership is still waiting on closing of property to occur. We anticipate that this may happen within next month, at which time existing USTs will be decommissioned and removed and area of contamination will be excavated as per RAP. - J. Kolleeny 12/20/11: Reviewed GW Sample Analysis Comparison Rpt dated 12/14/11 by EMC, received on CD by mail on 12/19/11 (in eDocs). Rpt states that 3rd round of RegenOx injections was performed Sept. 21-22, 2011; EMC returned to site on Nov. 28, 2011 to properly develop monitoring wells, and sampled wells on Nov. 29th. Results show well MW-4 had 447 ug/L total VOCs (down from 825 ug/L in July 2011 after 2nd round of injections; had 886 ug/L tVOCs prior to any injections); well MW-5 had 2,976 ug/L tVOCs (up from 1,125 ug/L in July 2011; had 285 ug/L prior to injections); well MW-6 had 25 ug/L tVOCs (down from 17,452 ug/L in July 2011; had 172 ug/L prior to injections); well MW-7 had 845 ug/L tVOCs (down from 4,214 ug/L in July 2011; had 1,830 ug/L prior to injections); well MW-8 had 1,133 ug/L tVOCs (down from 4,075 ug/L in July 2011; had 1,138 ug/L prior to injections); well MW-9 had 16,890 ug/L tVOCs (down from 27,310 ug/L in July 2011; had 9,607 ug/L prior to injections); and well MW-10 had 7,804 ug/L tVOCs (down from 9,810 ug/L in July 2011; had 17,109 ug/L prior to injections). Overall, results are mixed; most wells showed decreases from higher levels of contam detected after 1st and/or 2nd round of injections, but not necessarily decreases from pre-injection contam levels. Rpt states that new property ownership will proceed with excavation of contam soil, as per approved RAP, in March 2012, and that USTs will be slated for removal. - J. Kolleeny 06/01/12: DEC was notified that during UST removal activities at this site, a flash/explosion occurred when a worker was sawing a metal conduit. Jeffrey Vought of DEC spill response responded to site. Two workers were taken to a hospital, treated for minor injuries and released. Residents of two nearby buildings were evacuated; residents of one bldg were allowed to return but other bldg was kept evacuated for engineering evaluation of structural integrity. I contacted Richard Stumbo of Envt'l Maintenance Contractors (consultant) and requested summary of incident, sending follow-up email: Rich, As we discussed today, please provide DEC with a written summary of flash/explosion incident which occurred today during UST removal activities at your earliest convenience. In particular, summary should address whether or not proper procedures were followed to render USTs free of explosive vapors prior to any cutting or piercing of tanks or of piping leading into/out of tanks. Vadim Brevdo (my supervisor) sent follow-up email: Dear Mr. Stumbo, I am Vadim Brevdo, Chief of Petroleum Remediation Section in DEC in which this project is being managed by Jon Kolleeny as project manager. I am requesting that in addition to written summary of flash/explosion incident which Jon requested, you also provide summary of actions that will be undertaken on this project to address this accident and prevent similar accidents in future. This should include but not be limited to following: what steps/measures will be taken to prevent similar accidents in future, what is being undertaken to address situation, what is being done to return residents of one of buildings evacuated, and what measures you intend to undertake to ensure safe operations on site in future. Please note that this is time-sensitive and I want to have your summary no later than noon, Monday, June 4. Please keep Jon Kolleeny promptly informed on all further developments associated with this accident. Send all

GAS STATION/CAR WASH (Continued) **S110140247**

information to Jon Kolleeny and cc me on your e-mails. - J. Kolleeny 6/4/12-Vought-See also closed spill #1202128 for info regarding explosion on 6/1/12 during UST removal at this same site. 06/6/12: On 6/5/12, received email from Allan Ciriaco of Envt'l Maintenance Contractors with attached summary of 6/1/12 flash/explosion incident (in eDocs as brief). Summary states that USTs were properly cleaned and purged of vapors, and speculates that a spark generated by cutting conduit with saw ignited pocket of vapor in tank area or in pea gravel surrounding tank. Tank removal contractor, Justin Group, Inc., will implement a procedure to include addt'l tool box meetings during this type of work and perform screening for combustible gases before any activities that produce a flammable environment are performed. I sent email to Allan and to Richard Stumbo: Allan and Richard, Thanks for summary. I'm a little unclear about metal conduit that was being cut. Was that a part of UST system, e.g, a line into or out of tank for electronics, or maybe for cathodic protection? If possible, please provide a little more detail about metal conduit that was being cut at time of flash. Received email response from Rich Stumbo on 6/6/12: Jonathan I don t know if anyone is positive at this time as to what conduit was part of. My understanding is that there were no wires in conduit may have been pulled?? but once contractor is back on site they will try to determine what conduit serviced. - J. Kolleeny 10/19/12: On 10/9/12, received Final Rpt for UST Removal Project dated 10/2/12, by Envt'l Maintenance Contractors, Inc. On 10/8/12, received email from Rich Stumbo of EMC: Jonathan, Per our correspondance last week we submitted a hard copy of UST closeout rpt. Please let me know if there are any questions or if addt'l information is required. Clean soils surrounding remedial area have been excavated to allow for required shoring for access to contaminated materials. Upon completion of install of shoring required, excavation activities will commence and contaminated soils will be enountered. All work is to be performed in accordance with RAP. We are tentatively scheduled to remove contaminated materials on Wednesday or Thursday of this week. We will contact you when we are confirmed with a start date. On 10/18/12, received email from Rich Stumbo: Jonathan just wanted to follow up on status of rpt submitted. Have you had chance to review and comment on. If all is acceptable please let us know as ownership is anxious to close out that part of project. Currently we do not have a schedule as to when we will be digging out contaminated soils as part of RAP, however we will contact you as soon as we have been informed by ownership. I sent reply: Richard, I did receive rpt, but haven't yet had a chance to look at it. I'm not sure what you mean when you say owner is anxious to close out this part of project ; I'm assuming tank excavation has already been backfilled, you're not waiting on my review of rpt to do that, are you? Does rpt specifically request a DEC response, to confirm something along lines of no further action with respect to UST closure is required ? We don't usually issue statements like that until a site is ready for spill closure. Anyway, I'm out of office tomorrow but I will try to look at rpt early next week and I'll get back to you with any questions and/or comments. On 10/19/12, Rich sent reply: Jonathan, I guess ownership just wants to make sure that you have everything that you need as it relates to removal of USTs. If there is something else that you would need please let me know after your revew. Remaining remedial work will possibly be starting up this morning but will let you know as we find out info needed. - J. Kolleeny 10/23/12: After reviewing UST removal rpt, I spoke with

GAS STATION/CAR WASH (Continued) **S110140247**

Rich Stumbo of EMC, requested revised site plan diagram showing end-point soil sample locations, modified to show other pertinent site features such as existing wells, dispensers, etc. Rich agreed to provide this. - JK 11/19/12: Sent email to Rich Stumbo of EMC: Richard, I was wondering if there's been any progress on revising site plan diagram in UST closure rpt for this site? I'd like to upload rpt into our database, but I want to wait for a pdf file of rpt with a site plan diagram revised as we recently discussed, to show pertinent site features with labels, and with monitoring wells and injections wells more clearly labeled. Please let me know. Rich sent reply: Jonathan, I apologize we have been so busy that I have not had chance to pull that info and revise, but will take care of it this week. Please note that contractor will be excavating tomorrow and we should be collecting end-point samples either this Wed or next Monday depending on how quickly they can complete work. - J. Kolleeny 12/10/12: Received email from Allan Ciriaco of EMC: Mr. Kolleeny, sorry for delay, please find attached revised drawing as per your request. Should you have any question or addt'l required information please don't hesitate to give us a call. I inserted revised site plan into pdf file of 10/2/12 UST Removal Rpt, uploaded rpt into eDocs. Rpt summarizes removal of six 6,000-gal USTs, collection of 7 end-pt soil samples. Only one end-pt sample (#3, from near SW corner of tank pit, had several SVOCs above cleanup guidelines. Rpt states that this area will be addressed through DEC-approved RAP. - J. Kolleeny 12/11/12: Received email from Allan Ciriaco of EMC: Mr. Kolleeny, please find attached rpt for endpoint samples collected from pit at 461 West 14th Street, New York City, NY. Should you have any question or addt'l required information please don't hesitate to give us a call. Letter rpt dated 12/10/12 (in eDocs) says excavation was completed on 11/25/12, twenty end-pt samples were collected on 11/26/12. Results show no VOC or SVOC exceedances of cleanup guidelines (in fact, no VOCs detected, some minor SVOCs detected in a couple of samples). Allan sent follow-up email: Mr. Kolleeny, can you confirm if you received revised drawing and endpoint sample rpt that we sent. I sent email reply: Mr. Ciriaco, Yes, I received revised drawing of UST excavation with end-point sample locations yesterday, and today I received letter with end-point results from remedial excavation and diagram showing those end-point sample locations, thanks. I have several questions. Was RegenOx applied to excavation prior to backfilling, as per approved RAP? Also, will soil excavation and end-point sample data, and all other remedial actions, be summarized in a Final Rpt, to be submitted after completion of first round of post-remedial GW sampling, as per approved RAP? And will 3 post-construction replacement monitoring wells be installed as per approved RAP? When do you plan to conduct first post-remedial GW sampling event? Please let me know. - J. Kolleeny 12/18/12: Spoke with Richard Stumbo of EMC on 12/17/12, he noted that end-pt soil samples showed very little remaining soil contam in excavation pit, and suggested that instead of applying chem ox to pit as proposed in approved RAP, they backfill and install injection wells in basement of new bldg and inject chem ox into GW. I asked that he prepare an amendment to RAP for my review/approval. He sent such Amendment (in eDocs); after prelim review, I sent email: Richard, I have a question. Amendment to RAP states that vapor barrier will be installed prior to backfilling excavation, and that three injection wells will be installed within excavated area. Doesn't this mean that you will be drilling through vapor barrier to install injection

GAS STATION/CAR WASH (Continued) **S110140247**

wells? Won't that compromise vapor barrier? Please let me know. Then sent another email: Richard, I have another question. Approved RAP for this project included statement that if follow-up GW monitoring continues to show elevated contaminant levels, 4 post-construction injection wells will be installed in completed building's cellar for addt'l bio-remedial injections (this statement is in section, Follow Up GW Testing, on pages 14-15). Would those 4 addt'l injection wells be in addition to 3 injection wells proposed in Amendment to RAP, or would 3 injection wells proposed in Amendment to RAP supercede statement in original RAP about installing 4 addt'l injection wells? (Are 3 injection wells proposed in Amendment to RAP all located within anticipated basement?) Please let me know, and please clarify this issue when you revise Amendment to RAP. - J. Kolleeny 01/02/13: Received email from Richard Stumbo of EMC: Jonathan, Happy new year. We will have a drawing and narrative sent to you by end of this week detailing answers to your questions. We are just trying to see what we can fit into basement of building at this time because of bathroom and mechanicals that are being installed in basement. - J. Kolleeny 01/07/13: Randy Austin (R2 Spill Engineer) was copied on letter from NYCDEP Bureau of Envt'l Planning & Analysis to CEQR examiner at NYC Board of Standards & Appeals, with comments on site assessment rpts by Langan Engrng for this property and an adjacent property, which are planned for one development. Randy forwarded letter (in eDocs) to me. - J. Kolleeny 01/11/13: On 1/8/13, received email from Allan Ciriaco of EMC with attached revised Amendment to RAP. I contacted Richard Stumbo of EMC and noted that new proposal for post-construction monitoring wells no longer includes proposed well at location of former well MW-9, which was most impacted well at site. Rich agreed to add back in that well and re-submit. On 1/10/13, received email from Allan Ciriaco with Amendment to RAP revised as of 1/10/13 (in eDocs). RAP Amendment notes that end-point soil samples from remedial excavation showed little to no residual soil contamination. Therefore, EMS recommends injection of bio-remedial product into subsurface to treat contaminated GW, rather than application of bio-remedial product to excavation pit as originally proposed in approved RAP. To accomplish this, three 4-inch injection wells will be installed within excavation area and incorporated into planned building s basement during construction. A vapor barrier will be installed after backfilling excavation and placing six inches of gravel on top; barrier will be flashed up basement walls and up well casings. Amendment also shows proposed locations for 4 post-construction monitoring wells for follow-up GW monitoring, with one well in excavation/basement area (4-inch) and 3 wells in sidewalk along 10th Ave (2-inch), including well at former location of MW-9. EMC proposes to collect GW samples from two of three injection wells and monitoring well in basement area to determine type of bio-remedial product to inject and necessary quantities. After construction, 4 post-construction monitoring wells will be sampled, and final rpt will be prepared documenting all remedial activities and post-construction GW sample results, with recommendations for further action as appropriate. I sent approval letter (in eDocs) to RP Brandon Miller, cc's to Richard Stumbo & Allan Ciriaco of EMC. - JK 05/02/13: On 4/30/13, received email from Richard Stumbo of Envt'l Maintenance Contractors, with attached info on vapor barrier and tape they intend to install beneath planned building at site (info in eDocs as brief). Email stated: Jonathan please find attached a copy of specs for vapor barrier that ownership would like to apply in pit.

GAS STATION/CAR WASH (Continued) **S110140247**

Vapor barrier that ownership would like to apply is EnviroLiner 6030 (30 mil) and based on our review we believed that vapor barrier complies with ASTM standards and with NYSDOH guidance on soil vapor intrusion. Let us know if it meets with satisfaction of your office. I sent email reply: Yes, proposed vapor barrier complies with ASTM standards and with NYSDOH guidance on soil vapor intrusion. As such, it should provide adequate protection from potential intrusion of any petroleum vapors emitted by residual soil and/or GW contamination at site. Care should be taken during install'n of vapor barrier to insure it is properly sealed at critical points, such as where utilities or GW monitoring/injection wells enter building. Thanks for providing this documentation. - J. Kolleeny 03/11/14: On 3/6/14, received an email from Allan Ciriaco of Envt'l Maintenance Contractors, Inc. with attached pdf file of GW Sample Analysis Rpt dated 3/5/14. I sent email reply noting that rpt does not include a site plan showing GW sample location and other pertinent site features. I requested that he send a site plan showing current site conditions, including on-site structure(s), locations of existing injection and monitoring wells, and three proposed monitoring well locations for inclusion in rpt. On 3/10/14, received two site plans (one of which appears to be an as-built architectural drawing of new on-site bldg); I inserted diagrams into 3/5/14 rpt and uploaded to eDocs. Rpt presents results of one GW sample collected from monitoring well RMW1 (located within cellar of bldg), showing no detections of any petroleum-related VOCs or SVOCs. Rpt recommends that three monitoring wells be installed in sidewalk along 10th Ave (to west of site) and sampled to determine current GW conditions in those areas, as per amended RAP dated 1/10/13. I sent email to Mr. Ciriaco stating: Mr. Ciriaco, Thank you for site plan diagrams; I have added them into GW Sample Analysis Rpt you submitted in your earlier email. Rpt includes a recommendation to install and sample three post-construction monitoring wells in sidewalk along 10th Avenue. Since these actions were already proposed as part of January 2013 amended Remedial Action Plan which I approved, I do not intend to issue a formal response approving current recommendation in this rpt. If there is any problem with this, please let me know. - J. Kolleeny 05/28/14: Received phone call from Allan Ciriaco of EMC, who said they have successfully installed two of three proposed post-construction monitoring wells in sidewalk along 10th Ave. (wells RMW-2 and RMW-4), but were not able to install 3rd well RMW-3 due to repeated refusals (see well locations in DecDocs as drawing dated 2/5/13). He asked if it would be okay to not install that 3rd well due to difficult drilling conditions, and to go ahead with sampling of 2 new wells. I asked what kind of drill rig they were using and he replied it was a GeoProbe rig but with hollow-stem auger drilling capability. I said I needed to review available historical GW data and well locations, but would get back to him later in day. After reviewing past GW data and well locations, I sent email to Allan, cc to Richard Stumbo of EMC: Allan, I took a closer look at past GW data, and I'm okay with holding off on installing proposed well RMW-3 for now. However, when you go to site to sample wells RMW-2 and RMW-4, please re-sample well RMW-1 as well. If results for well RMW-1 and/or RMW-2 show significant levels of GW contamination, then I'll again ask that another effort be made to re-install a well at approx proposed location of RMW-3, perhaps using a more heavy-duty drill rig. Please let me know when you have GW sample results, and also please forward details about GeoProbe rig with hollow-stem auger that

GAS STATION/CAR WASH (Continued) **S110140247**

we discussed earlier today. - J. Kolleeny 05/29/14: Received email from Allan Ciriaco of EMC with attached info on GeoProbe drill rig used to install post-construction monitoring wells (in DecDocs). I sent email reply, with cc to Richard Stumbo of EMC: Mr. Ciriaco, Thanks for this info. I believe a heavier-duty drill rig should be used for hollow-stem auger drilling in this setting, where rocks and other subsurface obstructions are likely to be encountered. Was soil sampling performed during install'n of two successful wells? Received email reply from Rich Stumbo: Jonathan, We did not collect any samples, however we did screen soils as they were coming up with a PID. Screening indicated very low concentrations of volatiles. Technicians on site did not observe or smell any contamination within soils encountered during borings. We will forward your recommendation to boring company that we used for future reference. We will be collecting water samples during next week and will forward you a copy of rpt by some time around June 16, if not sooner. Appreciate your time with this. - J. Kolleeny 07/09/14: On 7/7/14, received Post-Construction Mon Well Install'n and Sampling Rpt by EMC, sent by email from Allan Ciriaco of EMC. Rpt summarizes install'n of 3 post-construction mon wells in sidewalk along 10th Ave., and sampling of those wells plus mon well installed in new bldg's basement. Results show significant dissolved impacts in 2 of sidewalk wells, moderate impacts in basement well. Based on data, EMC recommends an addt'l bio-remedial application. I sent email to Ciriaco requesting that rpt be revised to include lines for total VOCs/SVOCs in GW data tables, and to provide details re bio-remedial application. On 7/8/14, received revised rpt (in DecDocs) by email from Ciriaco. Data table shows sidewalk replacement well RMW-2 had 3,969 ug/L total VOCs (near former well MW-9 which had 16,890 ug/L tVOCs when last sampled in Nov. 2011), sidewalk replacement well RMW-3 had 1,000 ug/L tVOCs (near former well MW-10 which had 7,804 ug/L when last sampled in Nov. 2011), and basement well RMW-1 had 336 ug/L tVOCs (was ND when sampled in Feb. 2014). Based on data, EMC recommends bio-remedial application involving injections of RegenOx into 3 injection wells in bldg basement, then deployment of ORC Advanced socks into injection wells for continuous slow release, with follow-up GW sampling of 4 post-construction wells (1 in basement, 3 in sidewalk). I sent letter (in DecDocs) approving addt'l bioremedial applicatn to Brandon Miller (RP), cc's to Allan Ciriaco & Richard Stumbo of EMC, noting that if injections do not bring contam down to levels suitable for spill closure, addt'l GW mon and/or remedial actions may be necessary. Then sent email to Ciriaco & Stumbo noting that follow-up GW samples need only be analyzed for VOCs (not SVOCs), that when requesting spill closure, rpt should include spill history and risk assmt, and that address on site's PBS reg should be corrected. - J. Kolleeny 12/30/14: Reviewed rpt by Envt'l Maintenance Contractors, Inc. dated 12/4/14 (in DecDocs), which summarizes application of bioremedial product (RegenOx & ORC Advanced) at site in August 2014, and presents results of follow-up GW sampling on 11/19/14. GW samples from four post-construction mon wells show well RMW1 (in cellar of new bldg) had 36.7 ug/L total VOCs (down from 335.9 ug/L in June 2014, prior to bioremedial application), well RMW2 had 1,232.1 ug/L tVOCs (down from 3,969.2 ug/L in June 2014), well RMW3 had 651.1 ug/L tVOCs (down from 1,000.3 ug/L in June 2014), and well RMW4 was ND (had 6 ug/L tVOCs with no exceedances in June 2014). Based on improvement in GW quality, EMC requests spill closure. I sent letter (in DecDocs) to RP Brandon Miller, cc's to Rich Stumbo and Allan Ciriaco of EMC,

GAS STATION/CAR WASH (Continued) **S110140247**

requesting another round of GW sampling from 4 wells to confirm improvement in GW quality and show that contam levels are continuing to decrease. Mr. Miller sent email to Rich Stumbo of EMC, cc'ing me: Rich- How many more times do you think we need to do this? I need a conservative estimate of cost associated with it. I sent email to Mr. Miller, cc's to Stumbo and Ciriaco, stating that well RMW4 can be omitted from next sampling round to save a little on cost. - JK 04/10/15: Reviewed gw sampling rpt by Envt'l Maintenance Contractors, Inc., dated 3/12/15 (in DecDocs). Rpt presents results of GW sampling on 2/24/15 showing well RMW1 had 0 ug/L total VOCs (had 36.7 ug/L tVOCs in Nov. 2014 and 335.9 ug/L tVOCs in June 2014); well RMW2 had 201.3 ug/L tVOCs (had 1,232.1 ug/L tVOCs in Nov. 2014 and 3,969.2 ug/L tVOCs in June 2014); and well RMW3 had 292.5 ug/L tVOCs (had 651.1 ug/L tVOCs in Nov. 2014 and 1,000.3 ug/L tVOCs in June 2014). Rpt notes that data show VOC levels significantly lower than previous sampling events, indicating continued improvement in GW quality. Based on data, rpt recommends spill closure. In light of significant remedial actions performed at site (removal of USTs, soil excavation, ISCO injections) continued downward trend in residual dissolved-phase GW impacts, and engineering control (vapor barrier) implemented to prevent any petroleum vapor intrusion into new site building related to any residual petroleum impacts at site, I concur that spill closure is appropriate. I closed spill, sent closure letter (in DecDocs) to Brandon Miller (RP), cc's to Richard Stumbo and Allan Ciriaco of EMC. - J. Kolleeny 06/10/15: Received Well Decommissioning Rpt by Envt'l Maintenance Contractors, dated 5/17/15, via email from Allan Ciriaco of EMC (in DecDocs). Rpt presents photo documentation of proper abandonment of monitoring wells and ISCO injection wells at site. - J. Kolleeny"

Remarks: "SOIL SAMPLES POSITIVE FOR PETROCHEMICAL CONTAMINATION."

All Materials:

Site ID:	424821
Operable Unit ID:	1180567
Operable Unit:	01
Material ID:	2174524
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

W453 **EXPLOSION AT FORMER GAS STATION** **NY Spills** **S112146593**
WSW **461-469 WEST 14TH STREET** **N/A**
< 1/8 **NEW YORK, NY**
0.124 mi.
657 ft. **Site 9 of 17 in cluster W**

Relative: **Lower**
Actual: **10 ft.**

SPILLS:

Name:	EXPLOSION AT FORMER GAS STATION
Address:	461-469 WEST 14TH STREET
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	1202128 / 2012-06-04
Facility ID:	1202128

EXPLOSION AT FORMER GAS STATION (Continued) **S112146593**

Facility Type:	ER
DER Facility ID:	419271
Site ID:	464882
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	B3
SWIS:	3101
Spill Date:	2012-06-01
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2012-06-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2012-06-01
Spill Record Last Update:	2012-06-04
Spiller Name:	Not reported
Spiller Company:	EXXONMOBIL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"06/01/12-Hiralkumar Patel. DEC received notification from NYC OEM about explosion at former gas station during removal of the gasoline tanks. 11:15 AM:- visited site. met with NYC OEM. contractor, Justin Group, was hired to remove six 6,000 gal gasoline USTs. tank content was removed by Fenley & Nicol. contractor has removed four of the tank. while cutting pipes on the fifth tank, explosion occurred around 10:45 AM due to vapors in the tank. as per the contractor, tanks were gas free and that work was done by the same company, Justin Group. two people were injured: one person who was doing LEL and PID monitoring and other person who was doing the work. FDNY checked nearby buildings and overhead park (Highline park). no LEL or odors detected on- or off-site. two buildings (449 W. 14th St. and 450 W. 15th St) were evacuated by FDNY and NYC DOB. the residents of the 15th St. location have returned to their building, but the 14th St. building is still vacated, subject to a structural integrity inspection, since it adjoins the explosion location. a Stop Work order was issued by NYC DOB, and the Highline Park (adjoining structure) is being inspected for damage, as well. no petroleum vapors currently are present either in the exploded tank or in the area. 6/4/12-Vought-Spill transferred from DEC Patel to DEC Vought as Vought responded to site on 6/1/12 with Patel as Patel had committment elsewhere. See also open spill #0911962 at this same site managed by DEC Kolleeny. Vought received paperwork from DEC Patel that included the following contact information: Russell Agruja *Tank Removal Company* Justin Group Ph:(718)449-9500 Kenneth Fisher *Owner* Cozen O'Conner Ph:(917)806-9563 Nate Stone *Construction Manager* Ph:(732)904-4277 As per DEC Patel, contractor was onsite in process of full gas station decomissioning and was removing six(6,000-gallon) gasoline USTs and during removal of fifth UST, explosion occurred due

EXPLOSION AT FORMER GAS STATION (Continued) **S112146593**

to ignition of vapors inside UST. Liquid was removed from UST prior to decomissioning by Fenley & Nicol approximately two weeks ago. No product or liquid observed in tank as well as time of DEC site visit however 4'x4' burnt hole was observable in side of UST in excvation at approximately 8'below grade. DEC Patel noted that site represenatives noted that they were performing LEL monitoring via a CAMP when explosion occurred and two workers were in area(one performing air monitoring via PID and one doing tank cutting work). One worker was treated on-scene and released and the second worker was taken to local hospital and examined for internal injuries and was then released. No signs of soil contamination adjacent to UST however soils may have been backilled when USTs originally installed. Excavation immediately adjacent to pile support for Highline as well as adjacent to 449 West 14th Street and 450 West 15th Street. Both buildings were initially evacuated and then checked for explosive vapors by FDNY and levels were determined to be safe and both buildings were reoccupied. FDNY however did issue Stop Work Order for tank work onsite. Onsite agencies included: NYCOEM (Robert Treiland Ph:718-422-4868) FDNY Bureau of Fire Investigation (Randall Wilson Ph:718-921-9705) FDNY Bureau of Fire Investigation Fire Marshall (Joseph Pruden Ph:718-492-1880) FDNY Bureau of Fire Prevention (Prosalov) Friends of the Highline (Ronnit Bendavid-val Ph:212-229-4890) OSHA (Chung Huang Ph:212-620-3200) NYCDEP Hazmat (Harry Mayer) NYPD NYCDOB At time of site visit, NYCDOB inspected both the structural support for the Highline and well as the adjacent building at 449 West 14th Street and determined both were structurally sound and as such both were reoccupied and reopened. Vought returned to office and updated RSE and also spoke with DEC Kolleeny who will follow up with Richared Stumbo with respect to open spill #0911962. Vought spoke with DEC Kolleeny and Petroleum Remediation Unit will request summary of incident and preventive measures. Vought spoke with RSE on 6/1/12 who noted that as no release of product to soil or groundwater, that spill could be closed. RSE also noted via email that DEC had the hard copy paperwork for the tank closure filing for this site, under PBS #2-604379 and recently received this tank closure notification, and it hadn't been entered yet into the UIS Database but will be done so. Vought also received call from ECO Dainack and sent him copy of report as he responded to site after DEC left on 6/1/12. Spill closed by Vought."

Remarks: "explosion at former gas station during removal of gasoline tanks. two people injured."

All Materials:

Site ID:	464882
Operable Unit ID:	1214916
Operable Unit:	01
Material ID:	2212985
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

W454 **TENTH AVENUE CAR WASH** **NY UST** **U004064627**
WSW **461-469 WEST 14TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.124 mi.
657 ft. **Site 10 of 17 in cluster W**

Relative:
Lower

Actual:
10 ft.

UST:

Name:	TENTH AVENUE CAR WASH
Address:	461-469 WEST 14TH STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-604379 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583799.25699
UTM Y:	4510578.75253
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	26253
Affiliation Type:	Mail Contact
Company Name:	HOUSE CASTINGTENTH AVENUE CAR WASH
Contact Type:	Not reported
Contact Name:	DANIEL SCHULMAN
Address1:	% TENTH AVENUE CAR WASH
Address2:	450 WEST 15TH STREET - STE 202
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 645-2797
EMail:	SCHULMAN.DAN@GMAIL.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-01-28

Site Id:	26253
Affiliation Type:	Emergency Contact
Company Name:	TENTH AVENUE CAR WASH
Contact Type:	Not reported
Contact Name:	EREZ SCHTERNLICHT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 855-0560
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-08-13

Site Id:	26253
Affiliation Type:	Facility Owner
Company Name:	TENTH AVENUE CAR WASH
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	461-469 WEST 14TH STREET

TENTH AVENUE CAR WASH (Continued) **U004064627**

Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 645-2797
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-01-28

Site Id:	26253
Affiliation Type:	Facility Operator
Company Name:	TENTH AVENUE CAR WASH
Contact Type:	Not reported
Contact Name:	QUILVIO MUNOZ (PRIOR TO CLOSE)
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 645-2797
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-01-28

Tank Info:

Tank Number:	101
Tank ID:	57492
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	08/01/1999
Date Tank Closed:	05/17/2012
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
J01 - Dispenser - Pressurized Dispenser
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
B04 - Tank External Protection - Fiberglass

TENTH AVENUE CAR WASH (Continued) **U004064627**

D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
H05 - Tank Leak Detection - In-Tank System (ATG)
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	102
Tank ID:	57493
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	08/01/1999
Date Tank Closed:	05/18/2012
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
J01 - Dispenser - Pressurized Dispenser
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	103
Tank ID:	57494
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	08/01/1999
Date Tank Closed:	05/22/2012
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline

TENTH AVENUE CAR WASH (Continued) **U004064627**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
J01 - Dispenser - Pressurized Dispenser
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E00 - Piping Secondary Containment - None
B04 - Tank External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 104
Tank ID: 57495
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 6000
Install Date: 08/01/1999
Date Tank Closed: 05/31/2012
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
J01 - Dispenser - Pressurized Dispenser
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
H05 - Tank Leak Detection - In-Tank System (ATG)
G04 - Tank Secondary Containment - Double-Walled (Underground)

TENTH AVENUE CAR WASH (Continued) **U004064627**

Tank Number:	105
Tank ID:	57496
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	08/01/1999
Date Tank Closed:	06/11/2012
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J01 - Dispenser - Pressurized Dispenser
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E00 - Piping Secondary Containment - None
B04 - Tank External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	106
Tank ID:	57497
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	08/01/1999
Date Tank Closed:	06/12/2012
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

TENTH AVENUE CAR WASH (Continued) **U004064627**

F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
J01 - Dispenser - Pressurized Dispenser
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

W455 **CON EDISON** **NY MANIFEST** **S119073444**
SW **442 W 14TH ST** **N/A**
< 1/8 **NEW YORK, NY 10014**
0.124 mi.
657 ft. **Site 11 of 17 in cluster W**

Relative: **Lower**

Actual: **11 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	442 W 14TH ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004249734
Facility Status:	Not reported
Location Address 1:	442 W 14TH ST
Code:	BP
Location Address 2:	SERV BOX 2353
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004249734
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/17/2013
Trans1 Recv Date:	02/17/2013
Trans2 Recv Date:	Not reported

CON EDISON (Continued) **S119073444**

TSD Site Recv Date:	02/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004249734
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840397JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

W456 **CON EDISON SERVICE BOX: 2353** **RCRA NonGen / NLR** **1015746972**
SW **442 W 14TH ST** **NYP004249734**
< 1/8 **NEW YORK, NY 10014**
0.124 mi.
657 ft. **Site 12 of 17 in cluster W**

Relative: RCRA NonGen / NLR:
Lower

Date Form Received by Agency:		20130317
Handler Name:	CON EDISON SERVICE BOX:	2353
Handler Address:		442 W 14TH ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004249734
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported

Actual:
11 ft.

CON EDISON SERVICE BOX: 2353 (Continued) **1015746972**

Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported

CON EDISON SERVICE BOX: 2353 (Continued) **1015746972**

Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130217
Handler Name:	CON EDISON SERVICE BOX: 2353
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20120413
Handler Name:	CON EDISON TRANSFORMER VAULT 0469
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130317
Handler Name:	CON EDISON SERVICE BOX: 2353
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 2353 (Continued) **1015746972**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

T457 **CON EDISON** **NY MANIFEST** **S118258978**
SE **319 W 16TH ST** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.124 mi.
657 ft. **Site 16 of 20 in cluster T**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	319 W 16TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004824153
Facility Status:	Not reported
Location Address 1:	319 W 16TH ST
Code:	BP
Location Address 2:	SB 2798
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004824153
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/14/2015
Trans1 Recv Date:	08/14/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/18/2015

CON EDISON (Continued) **S118258978**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004824153
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002612848GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

X458 **328 W 15TH OWNER CORP** **NY AST** **U003386442**
SSE **328 W 15TH ST** **N/A**
< 1/8 **NY, NY 10011**
0.125 mi.
658 ft. **Site 5 of 11 in cluster X**

Relative: **Higher**
Actual: **19 ft.**

AST:

Name:	328 W 15TH OWNER CORP
Address:	328 W 15TH ST
City,State,Zip:	NY, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Inactive
Facility Id:	2-241563
Program Type:	PBS
UTM X:	584221.16806
UTM Y:	4510467.31267
Expiration Date:	N/A
Site Type:	Unknown

328 W 15TH OWNER CORP (Continued) **U003386442**

Affiliation Records:

Site Id:	9209
Affiliation Type:	Facility Owner
Company Name:	328 W 15TH OWNER CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	5224-13TH AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(071) 897-2880
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9209
Affiliation Type:	Mail Contact
Company Name:	328 W 15TH OWNER CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	5224-13TH AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(071) 897-2880
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9209
Affiliation Type:	Facility Operator
Company Name:	328 W 15TH OWNER CORP
Contact Type:	Not reported
Contact Name:	FELIX SOLAR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 972-8880
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9209
Affiliation Type:	Emergency Contact
Company Name:	328 W 15TH OWNER CORP
Contact Type:	Not reported
Contact Name:	RELIABLE MANAGEMENT CORP

328 W 15TH OWNER CORP (Continued) **U003386442**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 436-8001
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	9951
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
	I04 - Overfill - Product Level Gauge (A/G)
	H00 - Tank Leak Detection - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	D02 - Pipe Type - Galvanized Steel
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/01/1996
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

X459 **SUZUKI RESIDENCE** **NY Spills** **S104503145**
SSE **328 WEST 15TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.125 mi.
658 ft. **Site 6 of 11 in cluster X**

Relative: **Higher**
Actual: **19 ft.**

SPILLS:

Name:	SUZUKI RESIDENCE
Address:	328 WEST 15TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9701821 / 1998-10-01
Facility ID:	9701821

SUZUKI RESIDENCE (Continued) **S104503145**

Facility Type:	ER
DER Facility ID:	93946
Site ID:	106725
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	3101
Spill Date:	1997-05-12
Investigator:	MMMULQUE
Referred To:	Not reported
Reported to Dept:	1997-05-12
CID:	297
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-05-12
Spill Record Last Update:	1998-10-01
Spiller Name:	SUZUKI ASSOC
Spiller Company:	SUZUKI RESIDENCE
Spiller Address:	328 WEST 15TH ST
Spiller Company:	001
Contact Name:	SUZUKI ASSOC
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MULQUEEN "
Remarks:	"THE FILL PIPE WAS RUPTURE LEADING TO THE TANK IN THE BASEMENT OF THE BUILDING - CASTLE OIL CLEANED UP THE SPILL WITH ABSORBANTS"

All Materials:

Site ID:	106725
Operable Unit ID:	1047850
Operable Unit:	01
Material ID:	334763
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

W460 **CON EDISON SERVICE BOX: 49201** **RCRA NonGen / NLR** **1016143104**
SW **872 WASHINGTON ST** **NY MANIFEST** **NYP004258349**
< 1/8 **NEW YORK, NY 10014**
0.125 mi.
658 ft. **Site 13 of 17 in cluster W**

Relative: RCRA NonGen / NLR:
Lower
Actual: Date Form Received by Agency: 20130320
11 ft. Handler Name: CON EDISON SERVICE BOX: 49201
Handler Address: 872 WASHINGTON ST

CON EDISON SERVICE BOX: 49201 (Continued) **1016143104**

Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYP004258349
Contact Name:	JUAN RODRIGUEZ
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	347-865-5931
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No

CON EDISON SERVICE BOX: 49201 (Continued) **1016143104**

TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130220
Handler Name: CON EDISON SERVICE BOX:	49201
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130320
Handler Name: CON EDISON SERVICE BOX:	49201
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON SERVICE BOX: 49201 (Continued) **1016143104**

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 872 WASHINGTON ST
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYP004258349
Facility Status: Not reported
Location Address 1: 872 WASHINGTON ST
Code: BP
Location Address 2: SERV BOX 49201
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004258349
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 02/20/2013
Trans1 Recv Date: 02/20/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/20/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004258349
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 010846485JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N

CON EDISON SERVICE BOX: 49201 (Continued) **1016143104**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

X461 **MOUNT SINAI - BETH ISRAEL COMPREHENSIVE CANCER CEN** **RCRA-LQG** **1001229432**
SSE **325 W 15TH ST** **NY MANIFEST** **NYR000060384**
1/8-1/4 **NEW YORK, NY 10011**
0.129 mi.
680 ft. **Site 7 of 11 in cluster X**

Relative: **Higher**

Actual: **19 ft.**

RCRA-LQG:

Date Form Received by Agency:	20210225
Handler Name:	MOUNT SINAI - BETH ISRAEL COMPREHENSIVE CANCER CENTER
Handler Address:	325 W 15TH ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYR000060384
Contact Name:	GREGORY J CAMACHO
Contact Address:	1ST AVE & 16TH ST
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-420-2442
Contact Fax:	212-420-3841
Contact Email:	GREGORY.CAMACHO@MOUNTSINAI.ORG
Contact Title:	DIRECTOR, ENVIRONMENTAL HEALTH AND SAFETY
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2020
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	E 17TH ST
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	MOUNT SINAI - BETH ISRAEL

MOUNT SINAI - BETH ISRAEL COMPREHENSIVE CANCER CENTER (Continued) **1001229432**

Owner Type:	Private
Operator Name:	MOUNT SINAI - BETH ISRAEL
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20210301
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

MOUNT SINAI - BETH ISRAEL COMPREHENSIVE CANCER CENTER (Continued) **1001229432**

Sub-Part P Indicator: No

Biennial: List of Years
Year: 2019

Click Here for Biennial Reporting System Data:
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D002
Waste Description: CORROSIVE WASTE

Waste Code: D005
Waste Description: BARIUM

Waste Code: D008
Waste Description: LEAD

Waste Code: D009
Waste Description: MERCURY

Waste Code: D010
Waste Description: SELENIUM

Waste Code: D011
Waste Description: SILVER

Waste Code: D024
Waste Description: M-CRESOL

Waste Code: F003
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: P001
Waste Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Waste Code: P075

MOUNT SINAI - BETH ISRAEL COMPREHENSIVE CANCER CENTER (Continued) 1001229432

Waste Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Waste Code: P188
Waste Description: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

Waste Code: U010
Waste Description: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

Waste Code: U035
Waste Description: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

Waste Code: U058
Waste Description: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

Waste Code: U059
Waste Description: 5,12-NAPHTHACENEDIONE, 8-ACETYL-10-[(3-AMINO-2,3,6-TRIDEOXY)-ALPHA-L-LYXO-HEXOPYRANOSYL)OXY]-7,8,9,10-TETRAHYDRO-6,8,11-TRIHYDROXY-1-METHOXY-, (8S-CIS)- (OR) DAUNOMYCIN

Waste Code: U129
Waste Description: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

Waste Code: U132
Waste Description: HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-

Waste Code: U150
Waste Description: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

Waste Code: U200
Waste Description: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL)OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

Waste Code: U205
Waste Description: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: MOUNT SINAI - BETH ISRAEL
Legal Status: Private
Date Became Current: 19700101
Date Ended Current: Not reported
Owner/Operator Address: 1ST AVENUE & 16TH STREET
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-420-2442
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

MOUNT SINAI - BETH ISRAEL COMPREHENSIVE CANCER CENTER (Continued) **1001229432**

Owner/Operator Indicator:	Owner
Owner/Operator Name:	TACONIC INVESTMENT PARTNER LLC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1500 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10036
Owner/Operator Telephone:	212-220-9945
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MOUNT SINAI - BETH ISRAEL
Legal Status:	Private
Date Became Current:	19700101
Date Ended Current:	Not reported
Owner/Operator Address:	1ST AVENUE & 16TH STREET
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-420-2442
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	TACONIC INVESTMENT PARTNER LLC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1500 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10036
Owner/Operator Telephone:	212-220-9945
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MOUNT SINAI - BETH ISRAEL
Legal Status:	Private
Date Became Current:	19700101
Date Ended Current:	Not reported
Owner/Operator Address:	1ST AVENUE & 16TH STREET
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-420-2442
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MOUNT SINAI - BETH ISRAEL
Legal Status:	Private
Date Became Current:	19700101
Date Ended Current:	Not reported
Owner/Operator Address:	1ST AVENUE & 16TH STREET
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-420-2442
Owner/Operator Telephone Ext:	Not reported

MOUNT SINAI - BETH ISRAEL COMPREHENSIVE CANCER CENTER (Continued) **1001229432**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MOUNT SINAI - BETH ISRAEL
Legal Status: Private
Date Became Current: 19700101
Date Ended Current: Not reported
Owner/Operator Address: 1ST AVENUE & 16TH STREET
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-420-2442
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MOUNT SINAI - BETH ISRAEL
Legal Status: Private
Date Became Current: 19700101
Date Ended Current: Not reported
Owner/Operator Address: 1ST AVENUE & 16TH STREET
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-420-2442
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TACONIC INVESTMENT PARTNER LLC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1500 BROADWAY
Owner/Operator City,State,Zip: NEW YORK, NY 10036
Owner/Operator Telephone: 212-220-9945
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180226
Handler Name: MOUNT SINAI - BETH ISRAEL COMPREHENSIVE CANCER CENTER
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20200226
Handler Name: MOUNT SINAI - BETH ISRAEL COMPREHENSIVE CANCER CENTER
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY

MOUNT SINAI - BETH ISRAEL COMPREHENSIVE CANCER CENTER (Continued) **1001229432**

Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20210225
Handler Name: MOUNT SINAI - BETH ISRAEL COMPREHENSIVE CANCER CENTER
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20060101
Handler Name: SALICK HEALTH CARE ST VINCENTS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SALICK HEALTH CARE ST VINCENTS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980916
Handler Name: SALICK HEALTH CARE ST VINCENTS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

MOUNT SINAI - BETH ISRAEL COMPREHENSIVE CANCER CENTER (Continued) **1001229432**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 62211
NAICS Description: GENERAL MEDICAL AND SURGICAL HOSPITALS

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20190530
Actual Return to Compliance Date: 20190605
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20190612
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 20190530
Actual Return to Compliance Date: 20190530
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001

MOUNT SINAI - BETH ISRAEL COMPREHENSIVE CANCER CENTER (Continued) **1001229432**

Date of Enforcement Action: 20190612
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 20190530
Actual Return to Compliance Date: 20190530
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20190612
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported

MOUNT SINAI - BETH ISRAEL COMPREHENSIVE CANCER CENTER (Continued) **1001229432**

SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-General Facility Standards
Date Violation was Determined: 20190530
Actual Return to Compliance Date: 20190708
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20190612
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20190530
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYSC
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20190605
Scheduled Compliance Date: Not reported

MOUNT SINAI - BETH ISRAEL COMPREHENSIVE CANCER CENTER (Continued) **1001229432**

Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20190530
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSC
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20190530
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20190530
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSC
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20190530
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20190530
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSC
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20190708
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

NY MANIFEST:

Name:	MOUNT SINAI - COMPREHENSIVE CANCER GORP
Address:	325 W 15TH ST
City,State,Zip:	NEW YORK, NY 10011-5903
Country:	USA
EPA ID:	NYR000060384
Facility Status:	Not reported
Location Address 1:	325 WEST 15TH STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK

MOUNT SINAI - BETH ISRAEL COMPREHENSIVE CANCER CENTER (Continued) **1001229432**

Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000060384
Mailing Name:	MOUNT SINAI - COMPREHENSIVE CANCER GORP
Mailing Contact:	GREGORY CAMACHO
Mailing Address 1:	350 EAST 17TH ST
Mailing Address 2:	BAIRD HALL 4TH FL RM40
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124202442

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	12/20/2017
Trans1 Recv Date:	12/20/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/22/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000060384
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	011510702FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	43
Units:	P - Pounds
Number of Containers:	2
Container Type:	CF - Fiber or plastic boxes, cartons

MOUNT SINAI - BETH ISRAEL COMPREHENSIVE CANCER CENTER (Continued) **1001229432**

Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	D005
Waste Code 1_3:	D009
Waste Code 1_4:	D010
Waste Code 1_5:	D011
Waste Code 1_6:	Not reported

AB462 **JEAN'S MANHATTAN CLEANERS** **RCRA-VSQG** **1005417297**
NE **198 9TH AVE** **FINDS** **NYR000104232**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.130 mi. **NY MANIFEST**
688 ft. **Site 3 of 10 in cluster AB** **RI MANIFEST**

Relative: **Higher**
Actual: **17 ft.**

RCRA-VSQG:

Date Form Received by Agency:	20070101
Handler Name:	MANHATTAN FRENCH CLEANERS
Handler Address:	198 9TH AVE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYR000104232
Contact Name:	JEAN SHIH
Contact Address:	9TH AVE
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	212-675-6669
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	9TH AVE
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	JEAN SHIH
Owner Type:	Private
Operator Name:	JEAN SHIH
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported

JEAN'S MANHATTAN CLEANERS (Continued) **1005417297**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F039
Waste Description:	LEACHATE RESULTING FROM THE TREATMENT, STORAGE, OR DISPOSAL OF WASTES

JEAN'S MANHATTAN CLEANERS (Continued) **1005417297**

CLASSIFIED BY MORE THAN ONE WASTE CODE UNDER SUBPART D, OR FROM A MIXTURE OF WASTES CLASSIFIED UNDER SUBPARTS C AND D OF THIS PART. (LEACHATE RESULTING FROM THE MANAGEMENT OF ONE OR MORE OF THE FOLLOWING EPA HAZARDOUS WASTES AND NO OTHER HAZARDOUS WASTES RETAINS ITS HAZARDOUS WASTE CODE(S): F020, F021, F022, F023, F026, F027, AND/OR F028.)

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	JEAN SHIH
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	360 W 22ND ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	212-675-6669
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	JEAN SHIH
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	360 W 22ND ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	212-675-6669
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	JEAN SHIH
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	360 W 22ND ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	212-675-6669
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name:	MANHATTAN FRENCH CLEANERS
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

JEAN'S MANHATTAN CLEANERS (Continued) **1005417297**

Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MANHATTAN FRENCH CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020222
Handler Name: MANHATTAN FRENCH CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110016686852

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

JEAN'S MANHATTAN CLEANERS (Continued) **1005417297**

ECHO:

Envid:	1005417297
Registry ID:	110016686852
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110016686852
Name:	JEAN'S MANHATTAN CLEANERS
Address:	198 9TH AVE
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	MANHATTAN FRENCH CLNRS
Address:	198 9TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYR000104232
Facility Status:	Not reported
Location Address 1:	198 9TH AVE & 22ND ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000104232
Mailing Name:	MANHATTAN FRENCH CLNRS
Mailing Contact:	N/S
Mailing Address 1:	198 9TH AVE & 22ND ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2126756669

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	12/06/2010
Trans1 Recv Date:	12/06/2010
Trans2 Recv Date:	12/13/2010
TSD Site Recv Date:	12/14/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000104232
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID084802842
TSDF ID 2:	Not reported
Manifest Tracking Number:	001929972SKS

JEAN'S MANHATTAN CLEANERS (Continued) **1005417297**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	110
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	D007
Waste Code 1_3:	D029
Waste Code 1_4:	D039
Waste Code 1_5:	D040
Waste Code 1_6:	Not reported

RI MANIFEST:

Name:	MANHATTAN FRENCH CLEANERS
Address:	198 9TH AVE
City,State,Zip:	NEW YORK, NY 10011
EPA Id:	NYR000104232
GEN Cert Date:	12/6/2010
Manifest Document Number:	001929972SKS
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
TSDF Id:	RID084802842
TSDF Name:	SAFETY KLEEN
Qty:	110
WT/Vol Units:	P
TSDF Date:	12/13/2010
Transporter 2 Id:	NJD071629976
Item Number:	1
Transporter 2 Name:	12/13/2010
Transporter Name 2:	SAFETY KLEEN
Transporter EPAID:	TXR000050930
Transporter Receipt Date:	12/6/2010
Number Of Containers:	1
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported

JEAN'S MANHATTAN CLEANERS (Continued) **1005417297**

Waste Code6:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
Quarter:	Not reported
Transporter Contact Name:	Not reported
Transporter Contact Email:	Not reported
Filing Date:	Not reported
Total Fee:	Not reported
Billing Name:	Not reported
Paid Date:	Not reported
Paid Time:	Not reported
Facility Receipt Date:	Not reported
Fee:	Not reported
Manifest Created Date:	Not reported
Manifest Updated Date:	Not reported

RI MANIFEST:

Transporter Receipt Date:	10/4/2012
Number Of Containers:	2
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000104232
Manifest Docket Number:	003521140SKS
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	200
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	10/4/2012
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	10/16/2012
Manifest Created Date:	Not reported
TSDF Receipt Date:	10/16/2012

JEAN'S MANHATTAN CLEANERS (Continued) **1005417297**

Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	9/16/2011
Number Of Containers:	1
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000104232
Manifest Docket Number:	002822091SKS
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	100
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	9/16/2011
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	9/22/2011
Manifest Created Date:	Not reported
TSDF Receipt Date:	9/22/2011
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	12/6/2010
Number Of Containers:	1
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842

JEAN'S MANHATTAN CLEANERS (Continued) **1005417297**

Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000104232
Manifest Docket Number:	001929972SKS
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	110
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	12/6/2010
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	12/13/2010
Manifest Created Date:	Not reported
TSDF Receipt Date:	12/13/2010
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported

Transporter Receipt Date:	12/6/2010
Number Of Containers:	1
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000104232
Manifest Docket Number:	001929972SKS
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	110
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported

JEAN'S MANHATTAN CLEANERS (Continued) **1005417297**

Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	12/6/2010
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	12/13/2010
Manifest Created Date:	Not reported
TSDF Receipt Date:	12/13/2010
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported

AB463 **JEAN'S MANHATTAN FRENCH CLEANERS** **NY DRYCLEANERS** **S106435885**
NE **198 9TH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.130 mi.
688 ft. **Site 4 of 10 in cluster AB**

Relative: **Higher**
Actual: **17 ft.**

DRYCLEANERS:

Name:	JEAN'S MANHATTAN FRENCH CLEANERS
Address:	198 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Facility ID:	2-6205-01454
Phone Number:	212-675-6669
Region:	Not reported
Registration Effective Date:	12/8/2003
Inspection Date:	2009-10-13 00:00:00
Install Date:	97/13
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

AE464 **NYCT HUDSON DEPOT** **NY LTANKS** **S100177042**
West **1101 11TH AVENUE** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.132 mi.
695 ft. **Site 1 of 7 in cluster AE**

Relative: **Lower**
Actual: **5 ft.**

LTANKS:

Name:	NYCT HUDSON DEPOT
Address:	1101 11TH AVENUE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9106100 / 2016-01-04
Facility ID:	9106100
Site ID:	246928
Spill Date:	1991-09-06
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	RVKETANI

NYCT HUDSON DEPOT (Continued) **S100177042**

Referred To:	123115 RVWD CLOSURE REQUEST REPORT
Reported to Dept:	1991-09-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1991-09-10
Spill Record Last Update:	2018-03-29
Spiller Name:	GREGORY MATHELIER
Spiller Company:	NYCTA HUDSON DEPOT
Spiller Address:	1101 11TH AVENUE
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	202743
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 11/18/94: REASSIGNED FROM SIGONA TO ZHITOMIRSKY ON 11/18/94. transfered from Hale to Tibbe. see also 94-05274 & 98-05205. Piping repaired, spill investigation, investigation/remediation ongoing. 11/12/10 - spill re-assigned from Tibbe to Joe O'Connell 5/19/2011 The spill was reassigned from Joe O'Connell to Linda Ross 3/2/12 - Raphael Ketani. During February 2012, the spill case was reassigned to me. I reviewed the Work Plan for Monitored Natural Attenuation Program. The USTs in question failed their tightness tests during 1993. Subsequent to this, 430 gal. of diesel were collected from the water table. The subsurface is tidally influenced with a smear zone from 4 feet to 15 feet below grade. During 2002, bioremediation was conducted. The soil results from 3/18/03 showed very high concentrations for specific VOC analytes in the tens of thousands of parts per billions for the samples from SB-01 from 9 to 11 feet bgs, and from SB-02 from 5 to 9 feet bgs. The groundwater results were from non-detect to just slightly above standards. TCLP results were from non-detect to very low hits. No product has been seen on the water table since 2004. Groundwater sampling had been taking place quarterly at W-5, W-20, W-21, W-23 and W-24. From the review of the data, it appears that a new round of soil sampling should take place in order to confirm subsurface conditions. Later, John Lysiak of URS (the consultant for the MTA bus depot program) sent me tables of soil and groundwater analytical data from samples that were taken after 2003. I reviewed the data. The first sets of tables listed the total VOCs in parts per billion for each interval sampled for each boring (i.e. SSP-6: 5'-7'; 9,565 ppb total VOCs; 7'-9'; 35,318 ppb total VOCs; etc.) and then the total SVOCs (see the e-doc title DEC Hand Tabulation of Totals). These tables were followed by others listing the individual VOC analytes and the individual SVOC analytes for each interval sampled for each boring. I looked at only the latest sets of data for each boring. These were usually sets of data for samples collected during 2010 or 2011. While there sometimes were exceedences of particular VOC analytes that were double the standard or more, there were usually only one or two exceedences per sample. Sometimes the exceedence(s) was accompanied by analyte hits that were well

NYCT HUDSON DEPOT (Continued) **S100177042**

below standards. So, even though the VOC totals looked very high, the total value was mostly one analyte (i.e. 61,000 ppb of n-propylbenzene with a total of 61,636 ppb). Also, the exceeding analyte(s) was usually a degradation product of benzene. In short, the VOC contamination was low. However, the 10' to 11' sample from SSP-2 taken on 7/17/08 had 12,000 ppb of n-propylbenzene. The 5' to 7' sample from SSP-4 taken on 1/12/09 had 61,000 ppb of p-isopropyltoluene. The 9' to 11' sample from SSP-5 taken on 8/26/09 had 48,000 ppb of p-isopropyltoluene. The 7' to 9' sample taken from SSP-6 on 6/2/10 had 10,000 ppb of n-propylbenzene. The 11' to 13' sample from SSP-7 taken on 11/13/09 had 12,000 ppb of n-propylbenzene. The individual SVOC exceedences were almost exclusively those of the benzo series and the associated combustion products (chrysene, dibenzo(a)anthracene, indeno(1,2,3-cd)pyrene). While the exceedences may have been ten times the standard or more, they were not above several thousand parts per billion. Anthracene, acenaphthene, acenaphthalene, naphthalene, phenanthrene and pyrene were typically low throughout all of the soil samples. In total, the analytical results were very similar to those of historical fill, and not an oil spill. Recent groundwater samples were also taken from 2009 to 2011. The results were almost entirely non-detect for all of the samples. In some samples there were estimated values, but these were typically only slightly above the standards or below the standards. The groundwater didn't seem to be affected by the spill. This was probably due to the years of tidal flushing. I was informed that letters to the NYCT should go to: GREGORY MATHELIER CONSTRUCTION ADMINISTRATOR UST & ENVIRONMENTAL REMEDIATION PROGRAM ON-CALL PROJECTS/ CAPITAL PROGRAM MANAGEMENT MTA NEW YORK CITY TRANSIT 2 BROADWAY, D2.91, NY 10004 PHONE: 646-252-3470 FAX: 646-252-3140 E-MAIL: GREGORY.MATHELIER@NYCT.COM 3/12/12 - Raphael Ketani. A search of the PBS database did not reveal a registration for the two side by side tanks, nor the other two tanks to the north. I sent an e-mail to Toni Watts of the Safety Division of the NYCT (646) 252-5939/Toni.Watts@NYCT.com requesting that the tanks be investigated and that a PBS registration be established. I added that the lack of a registration was a violation of 6NYCRR Part 612. Ms. Watts found the PBS registration. It is #2-190284. However, it lists 6 above ground tanks. Not the two USTs that were of concern. The document doesn't list what type of fuels were in the tanks. 3/13/12 - Raphael Ketani. Gregory Mathelier of NYCT (646) 252-3470 called. He said that he is the point of contact for all correspondences regarding NYCT sites which are under the Consent Order. We discussed the tank registration for the site. I commented that there used to be a 550 gal. UST north of the twin large tanks and also a 5,000 gal. heating oil UST. These tanks were removed some time ago. I also stated that the twin 7,100 gal. tanks are not indicated as being either USTs or ASTs. Mr. Mathelier said that the 7,100 gal. tanks are USTs. I responded by saying that all four tanks had to be added to the PBS registration for the site as they were not on there. I added that this was a violation and that the spill would not be closed without a proper PBS registration. Mr. Mathelier said that he will take care of this. Later, Mr. Mathelier sent me an e-mail containing a map showing the 4 USTs in question and a PBS registration form indicating that the twin 7,100 gal. USTs are registered. As Mr. Mathelier explained and as the map shows, the 550 gal. UST and the 5,000 gal. UST are on NYC DOS property, not the NYCT property. 3/15/12 - Raphael Ketani. A case review meeting took place today. In

NYCT HUDSON DEPOT (Continued) **S100177042**

attendance were Hassan Hussein, EE 3 and head of the Hazardous Materials Unit, myself and the other members of the unit. The soil and groundwater analytical data were presented. Staff at the meeting stated that more information was needed in order to understand the case. Kevin Connare of URS (716) 856-5636 (the NYCT consultant) was contacted by phone and a teleconference ensued. Mr. Connare explained that the tanks were closed by cleaning them and then pumping in concrete slurry. The oil was first addressed by pumping and treating. About 430 gallons of product were collected from 1994 to 1997. A sheen hasn't been seen since at least a year ago. During April 4 to 7, 2002, RegenOx was pumped into 5 existing wells. Each well received 100 gal. of a mixture. There were 7 injection events. This work was done by Fenley & Nicol. RegenOx was pumped quarterly into the wells during 2007. Monitored natural attenuation was allowed to reduce the soil analyte concentrations since 2007. This involved taking confirmatory samples quarterly since 2007 and up until last fall. Since 1999, groundwater samples have been taken bi-annually. I asked Mr. Connare about the boring locations that were marked on one of the site maps which extend well north of the site. He stated that these were done in 1994 and 1995 by ADT and he knew nothing about them. 3/29/12 - Raphael Ketani. A case review meeting took place today. In attendance were Hassan Hussein, EE 3 and head of the Hazardous Materials Unit, myself and the other members of the unit. The soil and groundwater analytical data were presented. Kevin Connare of URS (716) 856-5636 lead the meeting. Mr. Connare stated that a comprehensive report will be submitted to the DEC regarding the site in the near future. 4/26/12 - Raphael Ketani. During this monthly meeting, the consultant, URS, stated that there was no remediation or monitoring activity at the site. Previous soil sampling via monitored natural attenuation was being allowed to reduce the analyte concentrations. Staff at the Department expressed concerns that no soil samples had been taken on the east side of the twin tanks and that the last set of soil results showed up to 60,000 ppb and 70,000 ppb of particular analytes in the soil on the west sides of the tanks. Staff from the NYCT stated that a petition for closure will be submitted. 1/31/2013 - Raphael Ketani. I received the URS Petition for Spill Closure Report dated January 2013 and began my review. 2/5/13 - Raphael Ketani. I finished my review of the Petition for Spill Closure Report. In summation from the report: Groundwater is present below the site from 4 to 8 feet below grade with a 4 foot tidal fluctuation. The ground below the site contains a thick layer of artificial/anthropogenic fill - from the soil analytical chemistry and the boring logs, the fill appears to be ash and cinder with wood, concrete, brick and other manmade materail. The twin 7100 gal. UST systems were integrity tested during September and October 1991 and each system failed its respective test. According to the closure report, the failed portion of the systems was the piping. A subsurface investigation took place during 1993 and 1994 and a plume of oil was discovered on the water table. Wells W-1 to W-3 were installed during July and August 1993 and up to 4.26 feet of oil was found on the water table. The plume turned out to be diesel fuel from the twin 7100 gal. UST systems and fuel oil from a UST under the adjacent NYC DOT site to the north. An estimated 550 to 1100 gals. of product was lost from the NYCT UST systems. From April to June 1994, wells W-5 to W-7 were installed. A sheen was present in W-5. In 1994, wells W-8, W-11, W-13 to W-17 were installed. A product recovery system was installed and operated from June 1994 to December 1997

NYCT HUDSON DEPOT (Continued) **S100177042**

when recoverable product was no longer present. About 430 gals. of product was recovered. During December 1998, the USTs were cleaned out and abandoned in place with sand. During January 1999, borings GP-1 to GP-4: GP-1 to GP-3 were installed around the tanks and GP-4 was installed in the vicinity of the pump house. All of the borings had odors and product. During February 2000, wells W-19 to W-23 were installed west, north and south fo the USTs. No wells were installed east of the USTs due to the bike path. During September 2000, borings GP-5 to GP-10 were installed to the south, north, east and west of the USTs. During 2002, the bioremediation program was started. Monitored natural atttenuation was started during May 2007. From May 2007 to June 2011, quarterly soil and groundwater sampling took place. Residual VOCs and SVOCs were found in the soil and the absence or minor presence of VOCs in the groundwater. Wells W-25 and W-26 were installed northeast and southeast of the USTs during July 2007 and had a few soil VOCs above CP-51 standards, but few SVOCs. Confirmatory soil borings SSP-1 to SSP-3 were installed on the west side of the USTs in order to minimize disruptions to the bike path. Soil borings up to SSP-10 were sampled from 5 to 15 feet below grade between June 2007 and July 2011 at consecutive 2 foot intervals. On June 2, 2010, the NYCT did in-situ chemical oxidation by injecting RegenOx into some wells. No product has been seen on the groundwater since 2010. The last soil sampling event took place during June 2011 and showed VOCs in only one of the three borings and SVOCs in two of the three borings. Only one groundwater sample had VOCs above standards. Quarterly sampling stopped as agreed upon by the NYCT, DEC and URS as it was agreed that the site was a candidate for closure. As part of the decommissioning of the wells, ORC solution will be mixed into the backfill for the wells before plugging and abandoning them. However, historical soil hot spots had been identified at locations SB-01 and SB-02, GP-06 and GP-07, SSP-01, SSP-02, SSP-04 to SSP-07 and SSP-09. Many of these moderate to very high VOC exceedences were from soil samples taken during 2009 to 2011. So, it is not clear whether the analytes would have been reduced by natural weathering during the past several years to the present. Confirmatory soil sampling needs to be performed. Though, no product has been seen during 2012 and the groundwater results do not show more than low exceedences of the TOGS 1.1.1 standards. Additionally, no borings or wells were ever installed on the east side of the east UST. Despite the bike path, there is a need to find out what is below the surface under this area. The soil results for GP-06 and GP-07 suggest that elevated concentrations of the analytes may be present. Because of the VOC exceedences in the soil samples from the recent past and the lack of information regarding subsurface conditions east of the twin USTs I could not close the spill case. I drafted a letter to the NYCT requesting a work plan for conducting confirmatory soil borings to the west of the USTs and new soil borings and new wells east of the USTs. The letter was submitted to Hassan Hussein, supervisor of Unit C Region 2 DER, for his approval. Mr. Hussein approved the letter and it was sent out with a due date of March 22, 2013 for submission of the work plan for doing the requested borings and wells. 3/22/13 - Raphael Ketani. Mr. Mathelier sent me a request by e-mail asking that the DEC obtain permission from the Hudson River Park Trust for the NYCT so that they may install more borings next to the two USTs. The area above the USTs is presently crossed by bike paths and walkways. The draft letter was forwarded to Hassan Hussein for his approval. 3/29/13 - Raphael Ketani. Mr. Hussein approved the letter to Ms.

NYCT HUDSON DEPOT (Continued) **S100177042**

Silberfeld, General Counsel of the Hudson River Park Trust, in which her cooperation was requested for the soil investigation at the USTs. The letter was sent out. 5/31/13 - Raphael Ketani. I reviewed the May 2013 Site Specific Investigation Work Plan. Historical hot spots were identified as SB-01, 2, 6 and 7, SSP-01, 2, 4 to 7 and 9. The soil MNA and groundwater sampling program had continued until June 2011. Product had not been seen in the wells until 8/20/10 when 0.01' of product appeared in W-21. Five borings will be installed. These will be HDSB-1 to 3, HDMW-01 and HDMW-02. Two of the borings will be converted into wells. The wells will be installed to 15 feet below grade with 12 feet of screen. The borings will be installed east of the east tank, west of the west tank, north of both tanks and in the vicinities of the historical hot spots. I looked at Figure 3-1 which showed the proposed boring locations and determined that there were not enough borings or wells to delineate the extent of any undiscovered contamination. I revised the figure to show where the DEC wanted more borings and wells. I indicated that borings should be installed midway on the east side of the east tank, between SSP-01 and SSP-07, between SB-01 and SSP-09, between SSP-02 and SSP-06, and between SSP-05 and SSP-04. Wells should be installed at the southern and northern ends of each tank and closer to GP-06 and GP-07. In total, I asked for 2 additional borings and 4 additional wells. An e-mail was sent with the revised Figure 3-1. A deadline was set for June 28 for submission of the revised SSIWP. 6/26/13 - Raphael Ketani. I reviewed the Hudson Depot Site Specific Investigation Work Plan dated May 2013 and revised June 2013. The work plan contained a revised Figure 3-1 with the boring and well locations as requested by the DEC in its 5/31/13 e-mail. I approved the revised work plan. I sent Mr. Hussein a draft letter approving the revised SSIWP. 6/27/13 - Raphael Ketani. Mr. Hussein approved the letter and it was sent out. 8/1/13 - Raphael Ketani. I reviewed a set of task orders that Ms. Cadecia Josephs had sent to Ms. Silberfeld of the Hudson River Park Trust. These task order were: CPM-23 dated 5/23/13 and regarding the writing and submission of the SSIWP (which was previously approved in its revised version); CPM-24 dated 7/17/13 and regarding the addition of 2 soil borings and 4 wells to the SSIWP (the document as approved); and CPM-25 dated 7/31/13 and regarding the abandonment of well W-05. 4/3/14 - Raphael Ketani. I sent an e-mail to Noreen Doyle, General Counsel, Hudson River Park Trust (212) 627-2020/ndoyle@hrpt.ny.gov. In the e-mail, I requested her help in getting the NYCT's plan approved for doing the site investigation. I added that this step was necessary before the NYCT could apply for a permit to the NYC DOT for doing the work. 12/31/15 - Raphael Ketani. I reviewed the NYCT December 2015 Soil and Groundwater Investigation/Petition for Spill Closure Report. A historical review of the site was contained in the beginning of the report. The consultants estimated from the product thicknesses in the wells that 550 to 1100 gallons of product was released. A recovery pump was installed and operated from June 1994 to December 1997. The pump was shut down after this as no product was seen. Two 7100 gallon USTs were located below grade and had been closed in place during December 1998. Several investigations took place and some remedial actions from 1999 to 2011. Bioremediation of the soil took place during 2002. The sheens and product thicknesses were reduced after this action. The DEC allowed monitored natural attenuation (MNA) to drive the remediation. The first soil and groundwater sampling took place during 2007. Chemical oxidation took place during 2010 to enhance the

NYCT HUDSON DEPOT (Continued) **S100177042**

MNA. Groundwater monitoring has continued to the present time. The soil and groundwater investigation work east of the USTs was completed from December 4 to 30, 2014. Sixteen (16) borings and 6 wells were installed. The borings were HDSB-1 to HDSB-10. The wells were HDMW-01 to HDMW-06. Groundwater was found to be at from 4' to 9' bgs and tidally influenced. Thirty (30) soil samples and 6 groundwater samples were collected. The soil results were compared to the CP-51 standards and the groundwater results were compared to the TOGS 1.1.1 standards. The soil samples were taken on 12/5, 8, 11, 12/2014. The upper portion of each boring had brown to dark brown fine to medium sub-angular sand with varying amounts of gravel and silt and fill. The PID readings varied. Oil stains and odors were present in several borings and generally only within the 5' to 15' interval. The most significant stains, PID readings (to 175 ppm) and odors were at borings to the northwest of the USTs (HDSB-01 and HDSB-04). Sheen and oil blebs appeared in some borings west of the USTs at 6' to 12' bgs. SB-1 (7'-9') was taken on 12/5/14 and had 4 analytes from 14,800 ppb to 36,400 ppb (benzene species analytes), but no benzene. The rest of the results were non-detect. The results for SB-1 (16'-18'), SB-2 to 7 and SB-10 were either all non-detect or mostly non-detect with 1 high exceedence. SB-6 (10'-12') was taken on 12/8/14 and had 6 exceedences from 180 ppb to 1400 ppb. The soil sample results for HDMW-01 (15'-16'), HDMW-03 (10'-11'), HDMW-04 (17'-19'), HDMW-05 (16'-18') and HDMW-06 (15'-16') were all non-detect or had 3 to 4 low hits with the rest non-detect. HDMW-01 (10'-12'), HDMW-02 (5.5'-7.5'), HDMW-04 (5'-7'), HDMW-05 (10'-12') and HDMW-06 (10'-12') each had 2 to 4 high hits and/or exceedences from 1500 ppb to 12,300 ppb with the rest of the results non-detect. Groundwater samples were taken from HDMW-01 to HDMW-06 on 12/30/14. The samples had from 4 to 11 very low to moderate (highest 21.5 ppb) hits and exceedences. The rest of the results were non-detect. The consultants recommended closure based upon the fact that the VOC results for the soil were either mostly non-detect or below standards. They also stated that the groundwater VOCs were either non-detect or mostly below standards with no free phase product. The NYCT believes that monitoring should be discontinued based upon the results. Also, the area is a paved bike path, which is part of the Hudson River Linear Park. So contact with any residual contamination is not possible. I approved the report and agreed with the recommendations of NYCT and their consultants that the spill case should be closed. This was also based upon the generally very low soil analytical results and the very low groundwater results. It was also based upon the fact that the USTs had been closed in place, bioremediation had been attempted and chemical oxidation had also been attempted in order to remediate the contamination. As the site could not be dug up due to the disruption this would cause to activities in the area, there was not anything else that could be done to reduce the contaminant concentrations. Also, the subsurface is subject to tidal action twice a day and so the soil and materials below grade will continue to be washed - thereby removing more contamination or oxidizing it. However, as the tidal waters can enter below grade, so can spills that originate on the river from boat and shipping activity. So, the subsurface will never be pristine and will maintain itself in equilibrium with the Hudson River water chemistry. 1/4/2016 - Raphael Ketani. I closed the spill case effective today and issued a Spill Closure Letter to NYCT for the site. 4/7/16 - Raphael Ketani. A progress update meeting took place on 3/31/16 for

NYCT HUDSON DEPOT (Continued) **S100177042**

all of the NYCT depot sites. During the meeting, Mr. Mathelier asked that I contact the administrative staff at the Hudson River Linear Park in order to find out what construction activities are taking place so that the NYCT can plan for closing the wells. I contacted Ms. Doyle by email (General Counsel, Hudson River Park Trust (212) 627-2020/ndoyle@hrpt.ny.gov) and asked her for a construction update and whether well abandonment can proceed. Ms. Doyle sent the following response email: The short answer is that no Trust-sponsored construction has occurred on the site as of yet. However, our Board of Directors approved a lease last week that will allow construction at and in the vicinity of Pier 57. I was just speaking with Rachel Seebacher of DEC this morning about this. She was going to contact the DEC staff involved with the NYCT spill to get a better understanding of the status of this spill and clean-up and any continuing obligations that may exist. I think it makes sense for that conversation to occur. I ve looped her in above. She will be back in touch with HRPT after getting an update so that we can figure out next steps. Later, I sent Ms. Doyle an air photo of the site, along with maps and a pdf of the extracted pages concerning the site from the December 2015 Monthly Progress Report. 4/26/16 - Raphael Ketani. Mr. Mathelier (Gregory.Mathelier@nyct.com) copied me in an email to David Boyle regarding future development of the site. Mr. Mathelier stated that the NYCT CPM would provide some assistance to RXR (the developer) concerning the removal of oil contaminated soil, should this be encountered. The possibility of encountering contaminated soil would arise from the installation of new utilities which are associated with the reconstruction of the Pier 57 facility. 6/22/16 - Raphael Ketani. Late today, I received an email from Yasin Rahman, Assistant Environmental Engineer in the NYCT CPM/UST and Environmental Remediation Program (718) 613-0294/yasin.rahman@nyct.com. The email was addressed to representatives of the owner of Pier 57, RXR Realty, and HRCG and EIC Associates. Excavation drawings dated and revised on 10/19/15 were attached to the email. The email stated that NYCT would assist RXR is the hauling and disposal of the contaminated soil. The excavating would be for the installation of various utilities and would extend down to as much as 13 feet below grade. About 94.8 cu. yds. of soil and fill are expected to be removed. I archived the documentation and had no comments. The contact information for RXR Realty is 1330 Avenue of the Americas, Ste. 500, NY, NY, 10019, (212) 797-1330. Another address for RXR Realty is: 230 Park Avenue, Ste. 1500, NY, NY, 10169, (516) 874-2966, Attn: Michael Rem, PE, Senior Project Manager, Development. 7/27/16 - Raphael Ketani. Mr. Rem copied me in an email that was sent to Mr. Yasin. The first paragraph of the email stated that the wells had been decommissioned and removed. Shortly after this email, Mr. Yasin sent an email to Mr. Rem regarding the contaminated soil excavation plan. 3/29/18 - Raphael Ketani. Yesterday, I received the Dvirka & Bartilucci Monitoring Well Decommissioning/Abandonment Report dated 3/28/18. The work was performed in accordance with CP-43 Groundwater Monitoring Well Decommissioning Policy. The work was performed on 6/6/16, 6/7/16 and 12/19/16. For each well, the concrete well head box was broken up and the casing with its screen was pulled out. Then the wells were filled with grout and an asphalt patch placed on top of the depression where the well used to be. Boring locations were also covered with an asphalt patch. "

Remarks: "75K TANK, PETRO; GROSS LEAK. SYSTEM"

NYCT HUDSON DEPOT (Continued) **S100177042**

All TTF:

Facility ID:	9106100
Spill Number:	9106100
Spill Tank Test:	1539010
Site ID:	246928
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	246928
Operable Unit ID:	956597
Operable Unit:	01
Material ID:	421840
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1100.00
Units:	G
Recovered:	473.00
Oxygenate:	Not reported

X465 **342 W 14 ST** **NY AST** **U004045440**
South **342 WEST 14TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.132 mi.
696 ft. **Site 8 of 11 in cluster X**

Relative:
Higher

Actual:
18 ft.

AST:

Name:	342 W 14 ST
Address:	342 WEST 14TH STREET
City,State,Zip:	NEW YORK, NY 10014
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-106895
Program Type:	PBS
UTM X:	584054.48946
UTM Y:	4510416.90237
Expiration Date:	N/A
Site Type:	Unknown

Affiliation Records:

Site Id:	3065
Affiliation Type:	Facility Owner

342 W 14 ST (Continued) **U004045440**

Company Name:	HUDSON LOFTS ASSOCIATES LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	155 THIRD STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11231
Country Code:	001
Phone:	(718) 875-8500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	3065
Affiliation Type:	Mail Contact
Company Name:	HUDSON LOFTS ASSOCIATES LLC
Contact Type:	Not reported
Contact Name:	DAVID KRAMER
Address1:	155 THIRD STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11231
Country Code:	001
Phone:	(718) 875-8500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	3065
Affiliation Type:	Facility Operator
Company Name:	342 W 14 ST
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	3065
Affiliation Type:	Emergency Contact
Company Name:	HUDSON LOFTS ASSOCIATES LLC
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported

342 W 14 ST (Continued) **U004045440**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	1
Tank Id:	3787
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	F06 - Pipe External Protection - Wrapped
	J02 - Dispenser - Suction Dispenser
	I04 - Overfill - Product Level Gauge (A/G)
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	7500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/01/1997
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)

AF466 **CON EDISON SERVICE BOX: 3973** **RCRA NonGen / NLR** **1016677353**
NNE **419 W 22ND ST OPPOSITE** **FINDS** **NYP004309415**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.132 mi. **NY MANIFEST**
696 ft. **Site 1 of 7 in cluster AF**

Relative: **Higher**
Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130608
Handler Name:	CON EDISON SERVICE BOX: 3973
Handler Address:	419 W 22ND ST OPPOSITE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004309415
Contact Name:	RICARDO CARTY
Contact Address:	Not reported
Contact City,State,Zip:	Not reported

CON EDISON SERVICE BOX: 3973 (Continued) **1016677353**

Contact Telephone:	646-772-3407
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	VING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 3973 (Continued) **1016677353**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140402
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130508
Handler Name: CON EDISON SERVICE BOX:	3973
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130608
Handler Name: CON EDISON SERVICE BOX:	3973
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON SERVICE BOX: 3973 (Continued) **1016677353**

FINDS:
Registry ID: 110058872297

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016677353
Registry ID:	110058872297
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110058872297
Name:	CON EDISON SERVICE BOX: 3973
Address:	419 W 22ND ST OPPOSITE
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	CON EDISON
Address:	419 W 22ND ST OPPOSITE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004309415
Facility Status:	Not reported
Location Address 1:	OPP 419 W 22 ST
Code:	BP
Location Address 2:	SERVICE BOX # 3973
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004309415
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported

CON EDISON SERVICE BOX: 3973 (Continued) **1016677353**

Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/08/2013
Trans1 Recv Date:	05/08/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/10/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004309415
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010842844JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

S467 **CON EDISON** **NY MANIFEST** **S116550954**
South **348-346 W 14TH ST & HUDSON ST** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.133 mi.
701 ft. **Site 18 of 18 in cluster S**

Relative: NY MANIFEST:
Higher

Name:	CON EDISON
Address:	348-346 W 14TH ST & HUDSON ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004493821

Actual:
17 ft.

CON EDISON (Continued) **S116550954**

Facility Status:	Not reported
Location Address 1:	348 W 14 ST
Code:	BP
Location Address 2:	SERVICE BOX # 2369
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004493821
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/08/2014
Trans1 Recv Date:	04/08/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004493821
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002360725GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S116550954**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Y468 **CON EDISON** **NY MANIFEST** **S117067383**
East **FO 317 W 19 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.133 mi.
704 ft. **Site 7 of 12 in cluster Y**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FO 317 W 19 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004601878
Facility Status:	Not reported
Location Address 1:	FO 317 W 19 ST
Code:	BP
Location Address 2:	SB 3434
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004601878
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported

CON EDISON (Continued) **S117067383**

Generator Ship Date:	07/20/2014
Trans1 Recv Date:	07/20/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004601878
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002608398GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

X469 **CON EDISON** **NY MANIFEST** **S116550957**
South **340-338 W 14TH ST & HUDSON ST** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.134 mi.
706 ft. **Site 9 of 11 in cluster X**

Relative: **Higher**

Actual: **18 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	340-338 W 14TH ST & HUDSON ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004493854
Facility Status:	Not reported
Location Address 1:	340 W 14 ST
Code:	BP

CON EDISON (Continued) **S116550957**

Location Address 2: SB2371
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004493854
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 04/08/2014
Trans1 Recv Date: 04/08/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/09/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004493854
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002407336GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 500

CON EDISON (Continued) **S116550957**

Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

X470 **CON EDISON** **RCRA NonGen / NLR** **1012185661**
SSE **310 W 15TH ST** **NJ MANIFEST** **NYP004164943**
1/8-1/4 **NEW YORK, NY 10011** **NY MANIFEST**
0.134 mi.
708 ft. **Site 10 of 11 in cluster X**

Relative: **Higher**
Actual: **19 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		310 W 15TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004164943
Contact Name:		ANTHONY BUDA
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		917-440-1809
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No

CON EDISON (Continued) **1012185661**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160726
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090327
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

CON EDISON (Continued) **1012185661**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160601
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:
EPA Id: NYP004164943
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: ANTHONY BUDA
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 001029500JJK
EPA ID: NYP004164943
Date Shipped: 03/27/2009
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported

CON EDISON (Continued) **1012185661**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/27/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/27/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	1500 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	310 W 15TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004164943
Facility Status:	Not reported
Location Address 1:	310 W 15th ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10020
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004164943
Mailing Name:	CONSOLIDATED EDISON

CON EDISON (Continued) **1012185661**

Mailing Contact:	CONSOLIDATED EDISON
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/27/2009
Trans1 Recv Date:	03/27/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/27/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004164943
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	001029500JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON EDISON (Continued) **1012185661**

Waste Code 1_6: Not reported

AB471 **CON EDISON SERVICE BOX: 39695** **RCRA NonGen / NLR** **1017772930**
NE **200 E 9TH AVE FRONT OF** **NYP004507075**
1/8-1/4 **NEW YORK, NY 10011**
0.134 mi.
709 ft. **Site 5 of 10 in cluster AB**

Relative:
Higher

Actual:
17 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20140522
Handler Name:	CON EDISON SERVICE BOX:	39695
Handler Address:		200 E 9TH AVE FRONT OF
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004507075
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No

CON EDISON SERVICE BOX: 39695 (Continued) **1017772930**

Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON SERVICE BOX: 39695 (Continued) **1017772930**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20140522
Handler Name: CON EDISON SERVICE BOX:	39695
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AB472 **CON EDISON** **NY MANIFEST** **S117058581**
NE **200 E 9TH AVE FRONT OF** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.134 mi.
709 ft. **Site 6 of 10 in cluster AB**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	200 E 9TH AVE FRONT OF
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004507075
Facility Status:	Not reported
Location Address 1:	200 9TH AVE & 22 ST
Code:	BP
Location Address 2:	SB 39695
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004507075
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported

CON EDISON (Continued) **S117058581**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2014
Trans1 Recv Date:	04/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/22/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004507075
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416667GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG473 **CON EDISON SERVICE BOX: 43092** **RCRA NonGen / NLR** **1016143592**
North **196 10TH AVE** **FINDS** **NYP004263737**
1/8-1/4 **NEW YORK, NY 10014** **ECHO**
0.134 mi. **NY MANIFEST**
710 ft. **Site 1 of 13 in cluster AG**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130321
Handler Name:	CON EDISON SERVICE BOX:	43092
Handler Address:		196 10TH AVE
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004263737
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 43092 (Continued) **1016143592**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130221
Handler Name: CON EDISON SERVICE BOX:	43092
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130321
Handler Name: CON EDISON SERVICE BOX:	43092
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 43092 (Continued) **1016143592**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063917169

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016143592
Registry ID: 110063917169
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110063917169
Name: CON EDISON SERVICE BOX: 43092
Address: 196 10TH AVE
City,State,Zip: NEW YORK, NY 10014

NY MANIFEST:
Name: CON EDISON
Address: 196 10TH AVE
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYP004263737
Facility Status: Not reported
Location Address 1: 196 10 AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004263737
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING

CON EDISON SERVICE BOX: 43092 (Continued) **1016143592**

Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/21/2013
Trans1 Recv Date:	02/21/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/22/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004263737
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010707144JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Z474 **CON EDISON** **NY MANIFEST** **S117058361**
NW **522 W 19 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.134 mi.
710 ft. **Site 12 of 13 in cluster Z**

Relative:
Lower

Actual:
9 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	522 W 19 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004504486
Facility Status:	Not reported
Location Address 1:	522 W 19 ST
Code:	BP
Location Address 2:	SB3408
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004504486
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/18/2014
Trans1 Recv Date:	04/18/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004504486
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011697552JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117058361**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	750
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AH475 **CON EDISON SERVICE BOX: 3797** **RCRA NonGen / NLR** **1016967413**
ENE **323 W 21ST ST FRONT OF** **NY MANIFEST** **NYP004410288**
1/8-1/4 **NEW YORK, NY 10011**
0.135 mi.
711 ft. **Site 1 of 6 in cluster AH**

Relative: **Higher**
Actual: **19 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140122
Handler Name:	CON EDISON SERVICE BOX:	3797
Handler Address:		323 W 21ST ST FRONT OF
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004410288
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported

CON EDISON SERVICE BOX: 3797 (Continued) **1016967413**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON SERVICE BOX: 3797 (Continued) **1016967413**

Historic Generators:

Receive Date:	20131222
Handler Name: CON EDISON SERVICE BOX:	3797
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140122
Handler Name: CON EDISON SERVICE BOX:	3797
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	323 W 21ST ST FRONT OF
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004410288
Facility Status:	Not reported
Location Address 1:	OPP 323 W 21ST ST
Code:	BP
Location Address 2:	SB 3797
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004410288

CON EDISON SERVICE BOX: 3797 (Continued) **1016967413**

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	12/22/2013
Trans1 Recv Date:	12/22/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/23/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004410288
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002299558GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON SERVICE BOX: 3797 (Continued) **1016967413**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

AE476 **CON EDISON SERVICE BOX: 33034** **RCRA NonGen / NLR** **1016150291**
West **11TH AVE & 16TH ST OPPOSITE** **NYP004289633**
1/8-1/4 **NEW YORK, NY 10011**
0.136 mi.
716 ft. **Site 2 of 7 in cluster AE**

Relative: **Lower**
Actual: **4 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130315
Handler Name:	CON EDISON SERVICE BOX:	33034
Handler Address:		11TH AVE & 16TH ST OPPOSITE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004289633
Contact Name:		RICARDO CARTY
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		646-772-3407
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported

CON EDISON SERVICE BOX: 33034 (Continued) **1016150291**

Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130215
Handler Name: CON EDISON SERVICE BOX:	33034
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130315
Handler Name: CON EDISON SERVICE BOX:	33034
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON SERVICE BOX: 33034 (Continued) **1016150291**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

X477 **CON EDISON** **NY MANIFEST** **S118463858**
South **327 W 14TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.136 mi.
718 ft. **Site 11 of 11 in cluster X**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:
Name: CON EDISON
Address: 327 W 14TH ST
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYP004858082
Facility Status: Not reported
Location Address 1: 327 W 14TH ST
Code: BP
Location Address 2: SB 2363
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004858082
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported

CON EDISON (Continued) **S118463858**

Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/2015
Trans1 Recv Date:	10/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004858082
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014087614JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

W478 **CON EDISON SERVICE BOX: 49200** **RCRA NonGen / NLR** **1016960236**
SW **866 WASHINGTON ST** **NYP004320982**
1/8-1/4 **NEW YORK, NY 10014**
0.137 mi.
725 ft. **Site 14 of 17 in cluster W**

Relative: RCRA NonGen / NLR:
Lower

Date Form Received by Agency:		20130714
Handler Name:	CON EDISON SERVICE BOX:	49200
Handler Address:		866 WASHINGTON ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004320982

Actual:
11 ft.

CON EDISON SERVICE BOX: 49200 (Continued) **1016960236**

Contact Name:	BENJAMIN BAMONTE
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-894-9549
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No

CON EDISON SERVICE BOX: 49200 (Continued) **1016960236**

Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130614
Handler Name: CON EDISON SERVICE BOX:	49200
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130714
Handler Name: CON EDISON SERVICE BOX:	49200
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON SERVICE BOX: 49200 (Continued) **1016960236**

Evaluation Action Summary:
Evaluations: No Evaluations Found

W479 **V0508** **RCRA NonGen / NLR** **1007207432**
SW **866 WASHINGTON STREET** **NY MANIFEST** **NYP004045506**
1/8-1/4 **NEW YORK CITY, NY 10013**
0.137 mi.
725 ft. **Site 15 of 17 in cluster W**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20010103
Handler Name:	V0508	
Handler Address:		866 WASHINGTON STREET
Handler City,State,Zip:		NEW YORK CITY, NY 10013
EPA ID:		NYP004045506
Contact Name:		ANTHONY DRUMMINGS
Contact Address:		CONSOLIDATED EDISON INC.
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		CONSOLIDATED EDISON INC.
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N

V0508 (Continued) **1007207432**

Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:		20010102
Handler Name:	V0508	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20010103
Handler Name:	V0508	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No

V0508 (Continued) **1007207432**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010101
Handler Name: V0508	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	2211
NAICS Description:	ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code:	22111
NAICS Description:	ELECTRIC POWER GENERATION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	866 WASHINGTON STREET
City,State,Zip:	NEW YORK CITY, NY 10013
Country:	USA
EPA ID:	NYP004045506
Facility Status:	Not reported
Location Address 1:	V0508-F/O 866 WASHINGTON ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004045506
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828

V0508 (Continued) **1007207432**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

W480 **V0508** **RCRA NonGen / NLR** **1007207175**
SW **866 WASHINGTON AVENUE** **NY MANIFEST** **NYP004039236**
1/8-1/4 **NEW YORK CITY, NY 10012**
0.137 mi.
725 ft. **Site 16 of 17 in cluster W**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20010103
Handler Name:	V0508	
Handler Address:		866 WASHINGTON AVENUE
Handler City,State,Zip:		NEW YORK CITY, NY 10012
EPA ID:		NYP004039236
Contact Name:		ANTHONY DRUMMINGS
Contact Address:		CONSOLIDATED EDISON INC.
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		CONSOLIDATED EDISON INC.
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported

V0508 (Continued) **1007207175**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20010102
Handler Name: V0508	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010103

V0508 (Continued) **1007207175**

Handler Name: V0508
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010101
Handler Name: V0508
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code: 22111
NAICS Description: ELECTRIC POWER GENERATION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 866 WASHINGTON AVENUE
City,State,Zip: NEW YORK CITY, NY 10012
Country: USA
EPA ID: NYP004039236
Facility Status: Not reported
Location Address 1: V0508-866 WASHINGTON AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10027
Location Zip 4: Not reported

V0508 (Continued) **1007207175**

NY MANIFEST:

EPAID:	NYP004039236
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

AE481 **NYCT - HUDSON DEPOT** **RCRA-VSQG** **1000140961**
West **WEST 15TH ST & 11TH AVE** **NYD980642235**
1/8-1/4 **NEW YORK, NY 10011**
0.138 mi.
727 ft. **Site 3 of 7 in cluster AE**

Relative: **Lower**

Actual: **6 ft.**

RCRA-VSQG:

Date Form Received by Agency:		20070101
Handler Name:	NYCT - HUDSON DEPOT	
Handler Address:		WEST 15TH ST & 11TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYD980642235
Contact Name:		JOSEPHINE F BROWN
Contact Address:		370 JAY STREET, ROOM 819
Contact City,State,Zip:		BROOKLYN, NY 11201
Contact Telephone:		718-243-4581
Contact Fax:		Not reported
Contact Email:		JOBROWN4@NYCT.COM
Contact Title:		Not reported
EPA Region:		02
Land Type:		State
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		370 JAY STREET, ROOM 819
Mailing City,State,Zip:		BROOKLYN, NY 11201
Owner Name:		NYCT
Owner Type:		State
Operator Name:		NO NAME FOUND
Operator Type:		State
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No

NYCT - HUDSON DEPOT (Continued) **1000140961**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2003

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

NYCT - HUDSON DEPOT (Continued) **1000140961**

Waste Code: D002
Waste Description: CORROSIVE WASTE

Waste Code: D006
Waste Description: CADMIUM

Waste Code: D007
Waste Description: CHROMIUM

Waste Code: D008
Waste Description: LEAD

Waste Code: X001
Waste Description: Not Defined

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: NYCT
Legal Status: State
Date Became Current: 19901023
Date Ended Current: Not reported
Owner/Operator Address: 370 JAY STREET
Owner/Operator City,State,Zip: BROOKLYN, NY 11201
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF NEW YORK
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYCT
Legal Status: State
Date Became Current: 19901023
Date Ended Current: Not reported
Owner/Operator Address: 370 JAY STREET
Owner/Operator City,State,Zip: BROOKLYN, NY 11201
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYCT
Legal Status: State
Date Became Current: 19901023
Date Ended Current: Not reported

NYCT - HUDSON DEPOT (Continued) **1000140961**

Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	NO NAME FOUND
Legal Status:	State
Date Became Current:	19901023
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990714
Handler Name: NYCTA	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20060101
Handler Name: NYCT - HUDSON DEPOT	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: NYCT - HUDSON DEPOT	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

NYCT - HUDSON DEPOT (Continued) **1000140961**

Electronic Manifest Broker: Not reported

Receive Date: 19820521
Handler Name: NYCTA
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940330
Handler Name: NYCTA
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960320
Handler Name: HUDSON DEPOT / NYCT
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010101
Handler Name: NYC TRANSIT AUTHORITY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040209
Handler Name: NYCT - HUDSON DEPOT
Federal Waste Generator Description: Large Quantity Generator

NYCT - HUDSON DEPOT (Continued) **1000140961**

State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	485111
NAICS Description:	MIXED MODE TRANSIT SYSTEMS
NAICS Code:	561599
NAICS Description:	ALL OTHER TRAVEL ARRANGEMENT AND RESERVATION SERVICES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AE482 **HUDSON PIER DEPOT** **NY LTANKS S100166630**
West **WEST 15TH ST & 11TH AVE** **NY Spills N/A**
1/8-1/4 **NEW YORK, NY**
0.138 mi.
727 ft. **Site 4 of 7 in cluster AE**

Relative: **Lower**

Actual: **6 ft.**

LTANKS:

Name:	NYC TRANSIT AUTH/MANHATTA
Address:	WEST 15TH ST & 11TH AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	8807870 / 1989-03-24
Facility ID:	8807870
Site ID:	144380
Spill Date:	1988-12-28
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1989-03-24
SWIS:	3101
Investigator:	JCGRATHW
Referred To:	Not reported
Reported to Dept:	1988-12-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-12-30
Spill Record Last Update:	1989-08-04

HUDSON PIER DEPOT (Continued) **S100166630**

Spiller Name:	Not reported
Spiller Company:	NYC TRANSIT AUTHORITY
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	283772
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GRATHWOL "
Remarks:	"7.5K TANK FAILED TEST, COULDN'T STABILIZE, WILL EMPTY DOWN TANK TO DO LINE TEST."

All TTF:

Facility ID:	8807870
Spill Number:	8807870
Spill Tank Test:	1535045
Site ID:	144380
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	144380
Operable Unit ID:	923344
Operable Unit:	01
Material ID:	452644
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	HUDSON PIER DEPOT
Address:	WEST 15TH ST & 11TH AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	9614511 / 1997-03-18
Facility ID:	9614511
Facility Type:	ER
DER Facility ID:	123078
Site ID:	144383

HUDSON PIER DEPOT (Continued) **S100166630**

DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3101
Spill Date:	1997-03-17
Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	1997-03-17
CID:	205
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-03-17
Spill Record Last Update:	1997-03-20
Spiller Name:	ERIC JONES
Spiller Company:	NYC TRANSIT
Spiller Address:	666 WEST 133RD ST
Spiller Company:	001
Contact Name:	ERIC JONES
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY OIL LEAKED ON THE CONCRETE FLOOR. OIL WAS CLEANEDUP BY TA E. JONES."
Remarks:	"VALVE BROKE IN BUILDING."

All Materials:

Site ID:	144383
Operable Unit ID:	1045884
Operable Unit:	01
Material ID:	558277
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AB483 **CON EDISON** **NY MANIFEST** **S117067536**
NE **FO 361 WEST 22 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.138 mi.
727 ft. **Site 7 of 10 in cluster AB**

Relative: **Higher**

Actual: **17 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	FO 361 WEST 22 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004604765
Facility Status:	Not reported

CON EDISON (Continued) **S117067536**

Location Address 1:	FO 361 WEST 22 ST
Code:	BP
Location Address 2:	SB 3976
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004604765
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/23/2014
Trans1 Recv Date:	07/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004604765
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504472GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117067536**

Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

T484 **CON EDISON** **NY MANIFEST** **S116044065**
SE **F/O 317 W 17TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.138 mi.
728 ft. **Site 17 of 20 in cluster T**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	F/O 317 W 17TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004404547
Facility Status:	Not reported
Location Address 1:	F/O 317 W 17TH ST
Code:	BP
Location Address 2:	SB3015
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004404547
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	12/11/2013

CON EDISON (Continued) **S116044065**

Trans1 Recv Date:	12/11/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/13/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004404547
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002237560GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AB485 **CON EDISON** **NY MANIFEST** **S117067532**
NE **FO 357 WEST 22ND ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.140 mi.
738 ft. **Site 8 of 10 in cluster AB**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FO 357 WEST 22ND ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004604724
Facility Status:	Not reported
Location Address 1:	FO 357 WEST 22ND ST
Code:	BP
Location Address 2:	SB 3977

CON EDISON (Continued) **S117067532**

Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004604724
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/23/2014
Trans1 Recv Date:	07/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004604724
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504468GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds

CON EDISON (Continued) **S117067532**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AA486 **GUARDIAN ANGEL SCHOOL** **NY LTANKS S102672077**
North **193 10TH AVE** **NY Spills N/A**
1/8-1/4 **MANHATTAN, NY**
0.140 mi.
740 ft. **Site 19 of 24 in cluster AA**

Relative: **Lower**

Actual: **11 ft.**

LTANKS:

Name:	193 10TH AVE
Address:	193 10TH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9211918 / 1993-01-19
Facility ID:	9211918
Site ID:	163796
Spill Date:	1993-01-19
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C4
Cleanup Ceased:	1993-01-19
SWIS:	3101
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1993-01-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-01-28
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	GOTHAM PETRO
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	138144
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks:	"CONTAINED ON CONCRETE-CLEANUP IS DONE BY SPILLER CREW"

All Materials:

GUARDIAN ANGEL SCHOOL (Continued) **S102672077**

Site ID:	163796
Operable Unit ID:	976484
Operable Unit:	01
Material ID:	405301
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	GUARDIAN ANGEL SCHOOL
Address:	193 10TH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	2007295 / 2021-01-26
Facility ID:	2007295
Facility Type:	ER
DER Facility ID:	138144
Site ID:	613183
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2020-11-13
Investigator:	VSZHUNE
Referred To:	Not reported
Reported to Dept:	2020-11-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2020-11-13
Spill Record Last Update:	2021-01-26
Spiller Name:	Not reported
Spiller Company:	GUARDIAN ANGEL SCHOOL
Spiller Address:	193 10TH AVE
Spiller Company:	999
Contact Name:	PAUL TYREE
DEC Memo:	"11/13/2020 - Feng - Desk Duty in office. Spoke to Paul Tyree and James Ross. It is a 5,000-gallon UST in the school's basement. It failed the tank test today. The tank tester is still at the site. There is still 3,500 gallons of #2 oil still inside the tank. They are planning to pump out the tank and to investigate whether there is a leak. They are looking for subcontractor to do the pump out. They are setting up temporary tank in the basement to hold the pumped oil. And they are setting a temporary heat system for the school. So far no determination of any loss. No signs of spills. There is potential

GUARDIAN ANGEL SCHOOL (Continued) **S102672077**

smell in the basement and not sure about the building. Briefed to Veronica Zhune and assign her the spill for further follow up. She might inspect the site tomorrow to make sure the tank is pumped out. PBS 2-608435 Paul Tyree Metro Environmental office: 631-393-6655 Cell: 516-426-5224 ptyree@mesllc.org Property Manager: Andi Metaliaj 917-513-1023 11/14/20-Zhune responded to this spill. the tank is a 5000 -gallon tank UST and failed the test . About 3500 gallons of oil #2 were pumped out by Metro Environmental. There is staining in the boiler room. Waited for Custodian to walk me 5 floors of the school to check for odors in the school. Found room #1 (first grade) second floor with slightly oil odors. Did air monitoring in the 5 floors with the PID meter. The meter indicated 1PPM in some areas of the school. Installed scrubbers in the 5 floors. 11/16/20-Zhune spoke to Ms. Perez the principal of the school. She said everything is fine. No odors complaint in the school. 11/23/20-Paul Tyree email- I hope all is well. I just wanted to give you a quick update on the work that was completed at Guardian Angel today. . Took soil borings, groundwater and soil samples in the court yard and boiler room . Screen soils . Air monitoring continues . Ventilation system is up and operating in the school we expected to have the analytical results in hand within 10 days business days. We will send you the report with the data and our recommended next steps no later than 48 hours after. We should have it to you by 12/3/20. 12/12/20 - Obligado - I reviewed an email provided by Paul Tyree which included a request to abandon the leaking tank in place. The email included soil sampling results, ground water sampling, and indoor air sampling results. The tank is present below a concrete covered courtyard. The tank is located adjacent to the area where oil staining was observed on the basement wall. Soil borings were advanced to a depth of 2 feet on all sites of the tank. No exceedences of CP51 soil clean up objectives were detected in any of the soil samples. One Gw sample was collected which also did not have any exceedences of GW standards. Indoor air samples were also cRollected from the basement, 1st floor, and 2nd floor. I sent the indoor air sampling results to NYSDOH to review. According to Nathan Walz there are some minor hits above background in the science and classroom that I expect will continue to decrease with time, since this is a school I would recommend that another round of samples be collected to confirm a downward trend. I forwarded the request for confirmatory indoor air sampling to Paul Tyree. 12/16/20 - Obligado - I inspected the site with Paul Tyree. No significant odors were observed in the cellar. No oil seepage into the boiler room was observed. The courtyard is completely surrounded by Church and School buildings. Removal of the UST not feasible or practical. I told Paul Tyree that they could proceed with the tank abandonment. 1/26/21-Paul Tyre from Metro Environmental Services LLC emailed the closure report dated 1/20/21. The report stated that MES properly close in place 1 x 5000 gallon UST. Soil samples were taken and analyzed for VOCs and SVOCs at an accredited laboratory. All results were below NYSDEC clean up criteria. A groundwater was obtained and submitted for analyzes. Groundwater sampling results were below NYDSDEC standards. Qualitative and Quantitative air sampling was conduct6ed and the last qualitative air sampling was below NYSDOH standards. Based on the information of the re[port this spill is closed. Spill closed."

Remarks: "ust in vault, unknown amount"

All Materials:

Site ID: 613183

GUARDIAN ANGEL SCHOOL (Continued) **S102672077**

Operable Unit ID:	1360306
Operable Unit:	01
Material ID:	2372277
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AA487 **GUARDIAN ANGEL** **NY UST** **U004047022**
North **193 10TH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.140 mi.
740 ft. **Site 20 of 24 in cluster AA**

Relative: **Lower**

Actual: **11 ft.**

UST:

Name:	GUARDIAN ANGEL
Address:	193 10TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-608435 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	02/27/2018
UTM X:	583997.60014
UTM Y:	4511127.64407
Site Type:	School

Affiliation Records:

Site Id:	30287
Affiliation Type:	Emergency Contact
Company Name:	GUARDIAN ANGEL
Contact Type:	Not reported
Contact Name:	REV. FERNANDO HERNANDEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 929-5966
EMail:	Not reported
Fax Number:	Not reported
Modified By:	kakyer
Date Last Modified:	2008-02-06

Site Id:	30287
Affiliation Type:	Facility Owner
Company Name:	GUARDIAN ANGEL
Contact Type:	PASTOR
Contact Name:	REV. FERNANDO HERNANDEZ
Address1:	193 10TH AVENUE
Address2:	Not reported
City:	NEW YORK

GUARDIAN ANGEL (Continued) **U004047022**

State: NY
Zip Code: 10011
Country Code: 001
Phone: (212) 929-5966
EMail: Not reported
Fax Number: Not reported
Modified By: kakyer
Date Last Modified: 2008-02-06

Site Id: 30287
Affiliation Type: Mail Contact
Company Name: GUARDIAN ANGEL
Contact Type: PASTOR
Contact Name: REV. FERNANDO HERNANDEZ
Address1: 193 10TH AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10011
Country Code: 001
Phone: (212) 929-5966
EMail: Not reported
Fax Number: Not reported
Modified By: kakyer
Date Last Modified: 2008-02-06

Site Id: 30287
Affiliation Type: Facility Operator
Company Name: GUARDIAN ANGEL
Contact Type: Not reported
Contact Name: MSGR MICHAEL HULL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 929-5966
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2013-02-11

Tank Info:

Tank Number: 001
Tank ID: 65168
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 5000
Install Date: 01/01/1930
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

GUARDIAN ANGEL (Continued) **U004047022**

Tightness Test Method: 21
Date Test: 10/23/2012
Next Test Date: 10/11/2016
Pipe Model: Not reported
Modified By: TankSys
Last Modified: 02/19/2020

Equipment Records:

H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)

AA488 **193-10 PECK AVE** **NY LTANKS** **S100144935**
North **193-10 PECK AVE** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.140 mi.
740 ft. **Site 21 of 24 in cluster AA**

Relative: **Lower**

Actual: **11 ft.**

LTANKS:

Name: 193-10 PECK AVE
Address: 193-10 PECK AVE
City,State,Zip: NEW YORK CITY, NY
Spill Number/Closed Date: 8708499 / 1992-09-30
Facility ID: 8708499
Site ID: 69386
Spill Date: 1987-12-16
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: B3
Cleanup Ceased: 1992-09-30
SWIS: 4101
Investigator: BATTISTA
Referred To: Not reported
Reported to Dept: 1988-01-05
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1988-01-21
Spill Record Last Update: 1994-05-12
Spiller Name: Not reported
Spiller Company: FRESH MEADOWS JEWISH CENT
Spiller Address: 193-10 PECK AVE
Spiller County: 001
Spiller Contact: Not reported

193-10 PECK AVE (Continued) **S100144935**

Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	65971
DEC Memo:	""
Remarks:	"4K TANK SYSTEM FAILED PETRO TITE WITH A LEAK RATE OF -.245GPH, TANK TECH SUB CONTRACTOR WAS RANSHAW CO."

All TTF:

Facility ID:	8708499
Spill Number:	8708499
Spill Tank Test:	1532899
Site ID:	69386
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	69386
Operable Unit ID:	913912
Operable Unit:	01
Material ID:	565215
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AA489 **GUARDIAN ANGEL CHURCH** **NY LTANKS** **S127292013**
North **193 10TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY**
0.140 mi.
740 ft. **Site 22 of 24 in cluster AA**

Relative: **Lower**
Actual: **11 ft.**

LTANKS:

Name:	GUARDIAN ANGEL CHURCH
Address:	193 10TH AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	2007298 / 2020-11-13
Facility ID:	2007298
Site ID:	613186
Spill Date:	2020-11-13
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other

GUARDIAN ANGEL CHURCH (Continued) **S127292013**

Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	RJFENG
Referred To:	Not reported
Reported to Dept:	2020-11-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2020-11-13
Spill Record Last Update:	2020-11-13
Spiller Name:	Not reported
Spiller Company:	N/A
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	JAMES ROSS
Spiller Phone:	(518) 527-3384
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	561209
DEC Memo:	"11/13/2020 - Feng - Desk Duty in office. Duplicated spill. see spill 2007295. Spill is closed. "
Remarks:	"tank test failure, tank is being pumped and investigations being conducted to find out if there is any leakage"

All Materials:

Site ID:	613186
Operable Unit ID:	1360309
Operable Unit:	01
Material ID:	2372280
Material Code:	9999
Material Name:	other - TANK TEST FAILURE
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

T490 **HIGH LINE** **US BROWNFIELDS** **1012098490**
SE **GANSEVOORT STREET TO 34TH STREET, GENERALLY BETWEEN 10TH & 1** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.140 mi.
741 ft. **Site 18 of 20 in cluster T**

Relative: **Higher**
Actual: **19 ft.**

US BROWNFIELDS:

Name:	HIGH LINE
Address:	GANSEVOORT STREET TO 34TH STREET, GENERALLY BETWEEN 10TH & 11TH AVENUES
City,State,Zip:	NEW YORK, NY 10011
Recipient Name:	New York, City of
Grant Type:	Cleanup

HIGH LINE (Continued) **1012098490**

Property Number:	-
Parcel size:	6.6
Latitude:	40.7419
Longitude:	-74.0018
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	Former Use: The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.
Datum:	World Geodetic System of 1984
Acres Property ID:	90521
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	20267000
Redev. Funding Source:	City of New York
Redev. Funding Entity Name:	Local Funding
Redevelopment Start Date:	9/5/2007
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	Hazardous
Accomplishment Type:	-
Accomplishment Count:	-
Cooperative Agreement Number:	97255906
Start Date:	-
Ownership Entity:	Government
Completion Date:	-
Current Owner:	City of New York
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	-
State/tribal program date:	-
State/tribal program ID:	-

HIGH LINE (Continued) **1012098490**

State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	Y
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	Y
Lead cleaned up:	Y
No media affected:	-
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	Y
Other metals cleaned:	-
Other contaminants found:	Y
Other contams found description:	SVOCs
PAHs found:	Y
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	Y
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	6.6
Future use greenspace acreage:	6.6
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-

HIGH LINE (Continued) **1012098490**

Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	-
Property Description:	The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.
Below Poverty Number:	2931
Below Poverty Percent:	9.1
Meidan Income:	38210
Meidan Income Number:	5651
Meidan Income Percent:	17.54
Vacant Housing Number:	2634
Vacant Housing Percent:	12.37
Unemployed Number:	1867
Unemployed Percent:	5.8
Name:	HIGH LINE
Address:	GANSEVOORT STREET TO 34TH STREET, GENERALLY BETWEEN 10TH & 11TH AVENUES
City,State,Zip:	NEW YORK, NY 10011
Recipient Name:	New York, City of
Grant Type:	Cleanup
Property Number:	-
Parcel size:	6.6
Latitude:	40.7419
Longitude:	-74.0018
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	Former Use: The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High

HIGH LINE (Continued) **1012098490**

Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.

Datum:	World Geodetic System of 1984
Acres Property ID:	90521
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	2500000
Redev. Funding Source:	-
Redev. Funding Entity Name:	Private/Other Funding
Redevelopment Start Date:	9/5/2007
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	Hazardous
Accomplishment Type:	-
Accomplishment Count:	-
Cooperative Agreement Number:	97255906
Start Date:	-
Ownership Entity:	Government
Completion Date:	-
Current Owner:	City of New York
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	-
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	Y
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	Y

HIGH LINE (Continued) **1012098490**

Lead cleaned up:	Y
No media affected:	-
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	Y
Other metals cleaned:	-
Other contaminants found:	Y
Other contams found description:	SVOCs
PAHs found:	Y
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	Y
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	6.6
Future use greenspace acreage:	6.6
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-

HIGH LINE (Continued) **1012098490**

Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	-
Property Description:	The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.
Below Poverty Number:	2931
Below Poverty Percent:	9.1
Meidan Income:	38210
Meidan Income Number:	5651
Meidan Income Percent:	17.54
Vacant Housing Number:	2634
Vacant Housing Percent:	12.37
Unemployed Number:	1867
Unemployed Percent:	5.8
Name:	HIGH LINE
Address:	GANSEVOORT STREET TO 34TH STREET, GENERALLY BETWEEN 10TH & 11TH AVENUES
City,State,Zip:	NEW YORK, NY 10011
Recipient Name:	New York, City of
Grant Type:	Cleanup
Property Number:	-
Parcel size:	6.6
Latitude:	40.7419
Longitude:	-74.0018
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	Former Use: The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.
Datum:	World Geodetic System of 1984
Acres Property ID:	90521
IC Data Access:	-

HIGH LINE (Continued) **1012098490**

Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	-
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	Hazardous
Accomplishment Type:	-
Accomplishment Count:	-
Cooperative Agreement Number:	97255906
Start Date:	-
Ownership Entity:	Government
Completion Date:	-
Current Owner:	City of New York
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	-
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	Y
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	Y
Lead cleaned up:	Y
No media affected:	-
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	Y
Other metals cleaned:	-
Other contaminants found:	Y
Other contams found description:	SVOCs
PAHs found:	Y
PAHs cleaned up:	-
PCBs found:	-

HIGH LINE (Continued) **1012098490**

PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	Y
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	6.6
Future use greenspace acreage:	6.6
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	-
Property Description:	The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an

HIGH LINE (Continued) **1012098490**

active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.

Below Poverty Number:	2931
Below Poverty Percent:	9.1
Meidan Income:	38210
Meidan Income Number:	5651
Meidan Income Percent:	17.54
Vacant Housing Number:	2634
Vacant Housing Percent:	12.37
Unemployed Number:	1867
Unemployed Percent:	5.8

Name:	HIGH LINE
Address:	GANSEVOORT STREET TO 34TH STREET, GENERALLY BETWEEN 10TH & 11TH AVENUES
City,State,Zip:	NEW YORK, NY 10011
Recipient Name:	New York, City of
Grant Type:	Cleanup
Property Number:	-
Parcel size:	6.6
Latitude:	40.7419
Longitude:	-74.0018
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	Former Use: The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.
Datum:	World Geodetic System of 1984
Acres Property ID:	90521
IC Data Access:	-
Start Date:	1/3/2006
Redev Completition Date:	-
Completed Date:	10/23/2008
Acres Cleaned Up:	5
Cleanup Funding:	3750000
Cleanup Funding Source:	City of New York
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-

HIGH LINE (Continued) **1012098490**

Redevelopment Start Date:	-
Assessment Funding Entity:	-
Cleanup Funding Entity:	Local Funding
Grant Type:	Hazardous
Accomplishment Type:	-
Accomplishment Count:	-
Cooperative Agreement Number:	97255906
Start Date:	-
Ownership Entity:	Government
Completion Date:	-
Current Owner:	City of New York
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	-
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	Y
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	Y
Lead cleaned up:	Y
No media affected:	-
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	Y
Other metals cleaned:	-
Other contaminants found:	Y
Other contams found description:	SVOCs
PAHs found:	Y
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	Y
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-

HIGH LINE (Continued) **1012098490**

Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	6.6
Future use greenspace acreage:	6.6
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	-
Property Description:	The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.
Below Poverty Number:	2931
Below Poverty Percent:	9.1
Meidan Income:	38210

HIGH LINE (Continued) **1012098490**

Meidan Income Number:	5651
Meidan Income Percent:	17.54
Vacant Housing Number:	2634
Vacant Housing Percent:	12.37
Unemployed Number:	1867
Unemployed Percent:	5.8
Name:	HIGH LINE
Address:	GANSEVOORT STREET TO 34TH STREET, GENERALLY BETWEEN 10TH & 11TH AVENUES
City,State,Zip:	NEW YORK, NY 10011
Recipient Name:	New York, City of
Grant Type:	Cleanup
Property Number:	-
Parcel size:	6.6
Latitude:	40.7419
Longitude:	-74.0018
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	Former Use: The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.
Datum:	World Geodetic System of 1984
Acres Property ID:	90521
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	4990000
Redev. Funding Source:	FTA
Redev. Funding Entity Name:	Other Federal Funding
Redevelopment Start Date:	9/5/2007
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	Hazardous
Accomplishment Type:	-
Accomplishment Count:	-
Cooperative Agreement Number:	97255906
Start Date:	-
Ownership Entity:	Government
Completion Date:	-
Current Owner:	City of New York

HIGH LINE (Continued) **1012098490**

Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	-
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	Y
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	Y
Lead cleaned up:	Y
No media affected:	-
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	Y
Other metals cleaned:	-
Other contaminants found:	Y
Other contams found description:	SVOCs
PAHs found:	Y
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	Y
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	6.6
Future use greenspace acreage:	6.6
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-

HIGH LINE (Continued) **1012098490**

Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	-
Property Description:	The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.
Below Poverty Number:	2931
Below Poverty Percent:	9.1
Meidan Income:	38210
Meidan Income Number:	5651
Meidan Income Percent:	17.54
Vacant Housing Number:	2634
Vacant Housing Percent:	12.37
Unemployed Number:	1867
Unemployed Percent:	5.8
Name:	HIGH LINE
Address:	GANSEVOORT STREET TO 34TH STREET, GENERALLY BETWEEN 10TH & 11TH AVENUES
City,State,Zip:	NEW YORK, NY 10011

HIGH LINE (Continued) **1012098490**

Recipient Name:	New York, City of
Grant Type:	Cleanup
Property Number:	-
Parcel size:	6.6
Latitude:	40.7419
Longitude:	-74.0018
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	Former Use: The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.
Datum:	World Geodetic System of 1984
Acres Property ID:	90521
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	5510000
Redev. Funding Source:	FHWA
Redev. Funding Entity Name:	Other Federal Funding
Redevelopment Start Date:	9/5/2007
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	Hazardous
Accomplishment Type:	-
Accomplishment Count:	-
Cooperative Agreement Number:	97255906
Start Date:	-
Ownership Entity:	Government
Completion Date:	-
Current Owner:	City of New York
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	-

HIGH LINE (Continued) **1012098490**

State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	Y
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	Y
Lead cleaned up:	Y
No media affected:	-
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	Y
Other metals cleaned:	-
Other contaminants found:	Y
Other contams found description:	SVOCs
PAHs found:	Y
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	Y
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	6.6
Future use greenspace acreage:	6.6
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-

HIGH LINE (Continued) **1012098490**

Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	-
Property Description:	The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.
Below Poverty Number:	2931
Below Poverty Percent:	9.1
Meidan Income:	38210
Meidan Income Number:	5651
Meidan Income Percent:	17.54
Vacant Housing Number:	2634
Vacant Housing Percent:	12.37
Unemployed Number:	1867
Unemployed Percent:	5.8
Name:	HIGH LINE
Address:	GANSEVOORT STREET TO 34TH STREET, GENERALLY BETWEEN 10TH & 11TH AVENUES
City,State,Zip:	NEW YORK, NY 10011
Recipient Name:	New York, City of
Grant Type:	Cleanup
Property Number:	-
Parcel size:	6.6
Latitude:	40.7419
Longitude:	-74.0018
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	Former Use: The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980.

HIGH LINE (Continued) **1012098490**

It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.

Datum:	World Geodetic System of 1984
Acres Property ID:	90521
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	-
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	Hazardous
Accomplishment Type:	-
Accomplishment Count:	-
Cooperative Agreement Number:	97255906
Start Date:	-
Ownership Entity:	Government
Completion Date:	-
Current Owner:	City of New York
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	-
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	Y
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-

HIGH LINE (Continued) **1012098490**

Groundwater cleaned:	-
Lead contaminant found:	Y
Lead cleaned up:	Y
No media affected:	-
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	Y
Other metals cleaned:	-
Other contaminants found:	Y
Other contams found description:	SVOCs
PAHs found:	Y
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	Y
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	6.6
Future use greenspace acreage:	6.6
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-

HIGH LINE (Continued) **1012098490**

SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	-
Property Description:	The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.
Below Poverty Number:	2931
Below Poverty Percent:	9.1
Meidan Income:	38210
Meidan Income Number:	5651
Meidan Income Percent:	17.54
Vacant Housing Number:	2634
Vacant Housing Percent:	12.37
Unemployed Number:	1867
Unemployed Percent:	5.8
Name:	HIGH LINE
Address:	GANSEVOORT STREET TO 34TH STREET, GENERALLY BETWEEN 10TH & 11TH AVENUES
City,State,Zip:	NEW YORK, NY 10011
Recipient Name:	New York, City of
Grant Type:	Cleanup
Property Number:	-
Parcel size:	6.6
Latitude:	40.7419
Longitude:	-74.0018
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	Former Use: The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.
Datum:	World Geodetic System of 1984

HIGH LINE (Continued) **1012098490**

Acres Property ID:	90521
IC Data Access:	-
Start Date:	1/3/2006
Redev Completition Date:	-
Completed Date:	10/23/2008
Acres Cleaned Up:	5
Cleanup Funding:	50000
Cleanup Funding Source:	DOT
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	-
Assessment Funding Entity:	-
Cleanup Funding Entity:	State/Tribal Funding (non-section 128(a))
Grant Type:	Hazardous
Accomplishment Type:	-
Accomplishment Count:	-
Cooperative Agreement Number:	97255906
Start Date:	-
Ownership Entity:	Government
Completion Date:	-
Current Owner:	City of New York
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	-
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	Y
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	Y
Lead cleaned up:	Y
No media affected:	-
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	Y
Other metals cleaned:	-
Other contaminants found:	Y
Other contams found description:	SVOCs
PAHs found:	Y

HIGH LINE (Continued) **1012098490**

PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	Y
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	6.6
Future use greenspace acreage:	6.6
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	-
Property Description:	The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was

HIGH LINE (Continued) **1012098490**

constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.

Below Poverty Number:	2931
Below Poverty Percent:	9.1
Meidan Income:	38210
Meidan Income Number:	5651
Meidan Income Percent:	17.54
Vacant Housing Number:	2634
Vacant Housing Percent:	12.37
Unemployed Number:	1867
Unemployed Percent:	5.8
Name:	HIGH LINE
Address:	GANSEVOORT STREET TO 34TH STREET, GENERALLY BETWEEN 10TH & 11TH AVENUES
City,State,Zip:	NEW YORK, NY 10011
Recipient Name:	New York, City of
Grant Type:	Cleanup
Property Number:	-
Parcel size:	6.6
Latitude:	40.7419
Longitude:	-74.0018
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	Former Use: The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.
Datum:	World Geodetic System of 1984
Acres Property ID:	90521
IC Data Access:	-
Start Date:	1/3/2006
Redev Completition Date:	-
Completed Date:	10/23/2008
Acres Cleaned Up:	5
Cleanup Funding:	200000
Cleanup Funding Source:	EPA
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-

HIGH LINE (Continued) **1012098490**

Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	-
Assessment Funding Entity:	-
Cleanup Funding Entity:	US EPA - Brownfields Cleanup Cooperative Agreement
Grant Type:	Hazardous
Accomplishment Type:	-
Accomplishment Count:	-
Cooperative Agreement Number:	97255906
Start Date:	-
Ownership Entity:	Government
Completion Date:	-
Current Owner:	City of New York
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	-
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	Y
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	Y
Lead cleaned up:	Y
No media affected:	-
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	Y
Other metals cleaned:	-
Other contaminants found:	Y
Other contams found description:	SVOCs
PAHs found:	Y
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	Y
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-

HIGH LINE (Continued) **1012098490**

VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	6.6
Future use greenspace acreage:	6.6
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	-
Property Description:	The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.
Below Poverty Number:	2931

HIGH LINE (Continued) **1012098490**

Below Poverty Percent:	9.1
Meidan Income:	38210
Meidan Income Number:	5651
Meidan Income Percent:	17.54
Vacant Housing Number:	2634
Vacant Housing Percent:	12.37
Unemployed Number:	1867
Unemployed Percent:	5.8
Name:	HIGH LINE
Address:	GANSEVOORT STREET TO 34TH STREET, GENERALLY BETWEEN 10TH & 11TH AVENUES
City,State,Zip:	NEW YORK, NY 10011
Recipient Name:	New York, City of
Grant Type:	Cleanup
Property Number:	-
Parcel size:	6.6
Latitude:	40.7419
Longitude:	-74.0018
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	Former Use: The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.
Datum:	World Geodetic System of 1984
Acres Property ID:	90521
IC Data Access:	-
Start Date:	1/3/2006
Redev Completition Date:	-
Completed Date:	10/23/2008
Acres Cleaned Up:	5
Cleanup Funding:	10500000
Cleanup Funding Source:	FHWA
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	-
Assessment Funding Entity:	-
Cleanup Funding Entity:	Other Federal Funding
Grant Type:	Hazardous
Accomplishment Type:	-
Accomplishment Count:	-
Cooperative Agreement Number:	97255906
Start Date:	-
Ownership Entity:	Government

HIGH LINE (Continued) **1012098490**

Completion Date:	-
Current Owner:	City of New York
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	-
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	Y
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	Y
Lead cleaned up:	Y
No media affected:	-
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	Y
Other metals cleaned:	-
Other contaminants found:	Y
Other contams found description:	SVOCs
PAHs found:	Y
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	Y
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	6.6
Future use greenspace acreage:	6.6
Future use residential acreage:	-
Future use commercial acreage:	-

HIGH LINE (Continued) **1012098490**

Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	-
Property Description:	The High Line is an elevated 1.5-mile long freight rail line on the West side of Manhattan that has not been used since 1980. It was constructed between 1929 and 1934 as part of the West Side Improvement Project. During the period from 1934 to 1982, the High Line was an active railroad servicing the warehouses and terminals adjacent to the active waterfront industries in this section of Manhattan. Since 1980, when the last train utilized the structure, it has been unused. In June 2005, the Federal Surface Transportation Board granted a Certificate of Interim Trail Use (CITU) to allow the High Line to be used as public open space in the Rails-to-Trails Program. The City of New York took title to the High Line from CSX Transportation, Inc. in November 2005.
Below Poverty Number:	2931
Below Poverty Percent:	9.1
Meidan Income:	38210
Meidan Income Number:	5651
Meidan Income Percent:	17.54
Vacant Housing Number:	2634
Vacant Housing Percent:	12.37
Unemployed Number:	1867
Unemployed Percent:	5.8

HIGH LINE (Continued) **1012098490**

Click this hyperlink while viewing on your computer to access additional US BROWNFIELDS: detail in the EDR Site Report.

AI491 **CON EDISON** **RCRA NonGen / NLR** **1014398472**
SSE **304 W 15TH ST** **NJ MANIFEST** **NYP004208258**
1/8-1/4 **NEW YORK, NY 10023** **NY MANIFEST**
0.141 mi.
743 ft. **Site 1 of 7 in cluster AI**

Relative: **Higher**
Actual: **19 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20200413
Handler Name:	CON EDISON	
Handler Address:		304 W 15TH ST
Handler City,State,Zip:		NEW YORK, NY 10023
EPA ID:		NYP004208258
Contact Name:		Not reported
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		Not reported
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No

CON EDISON (Continued) **1014398472**

Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200413
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20100608
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20200413
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON (Continued) **1014398472**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:
EPA Id: NYP004208258
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DENNIS MICHAELIDES
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 000894965GBF
EPA ID: NYP004208258
Date Shipped: 06/08/2010
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: NJD003812047
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 06/08/2010
Date Trans2 Transported Waste: 06/09/2010
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported

CON EDISON (Continued) **1014398472**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/09/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	6600 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	304 W 15TH ST
City,State,Zip:	NEW YORK, NY 10023
Country:	USA
EPA ID:	NYP004208258
Facility Status:	Not reported
Location Address 1:	304 304 WEST 15 ST.
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10023
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004208258
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

CON EDISON (Continued) **1014398472**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	06/08/2010
Trans1 Recv Date:	06/08/2010
Trans2 Recv Date:	06/09/2010
TSD Site Recv Date:	06/09/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004208258
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000894965GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	6600
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AB492 **CON ED** **NY MANIFEST** **S118463903**
NE **355 W 22 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.141 mi.
744 ft. **Site 9 of 10 in cluster AB**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON ED
Address:	355 W 22 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004858751
Facility Status:	Not reported
Location Address 1:	355 W 22 ST
Code:	BP
Location Address 2:	SB 3977
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004858751
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2015
Trans1 Recv Date:	10/23/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004858751
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014087546JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON ED (Continued) **S118463903**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

T493 **NYC BD OF ED - PUBLIC SCHOOL 70** **RCRA NonGen / NLR** **1001968962**
SE **315 W 17TH ST** **NYR000081604**
1/8-1/4 **NEW YORK, NY 10011**
0.141 mi.
744 ft. **Site 19 of 20 in cluster T**

Relative: **Higher**
Actual: **19 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	NYC BD OF ED - PUBLIC SCHOOL 70
Handler Address:	315 W 17TH ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYR000081604
Contact Name:	WILLIAM SLADE
Contact Address:	W 17TH ST
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	914-681-6405
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 17TH ST
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	CITY OF NY DEPT OF CITYWIDE ADMIN SVCS
Owner Type:	Municipal

NYC BD OF ED - PUBLIC SCHOOL 70 (Continued) **1001968962**

Operator Name:	CITY OF NY DEPT OF CITYWIDE ADMIN SVCS
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

NYC BD OF ED - PUBLIC SCHOOL 70 (Continued) **1001968962**

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D008
Waste Description: LEAD

Waste Code: D009
Waste Description: MERCURY

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF NY DEPT OF CITYWIDE ADMIN SVCS
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1 CENTRE ST
Owner/Operator City,State,Zip: NEW YORK, NY 10007
Owner/Operator Telephone: 212-669-8730
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF NY DEPT OF CITYWIDE ADMIN SVCS
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1 CENTRE ST
Owner/Operator City,State,Zip: NEW YORK, NY 10007
Owner/Operator Telephone: 212-669-8730
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF NY DEPT OF CITYWIDE ADMIN SVCS
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1 CENTRE ST
Owner/Operator City,State,Zip: NEW YORK, NY 10007
Owner/Operator Telephone: 212-669-8730
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYC BD OF ED - PUBLIC SCHOOL 70
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

NYC BD OF ED - PUBLIC SCHOOL 70 (Continued) **1001968962**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYC BD OF ED - PUBLIC SCHOOL 70
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20000424
Handler Name: NYC BD OF ED - PUBLIC SCHOOL 70
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

T494 **NYC BD OF ED - PUBLIC SCHOOL 70** **RCRA NonGen / NLR** **1004761248**
SE **315 W 17TH ST - NEW SCHOOL** **NYR000082248**
1/8-1/4 **NEW YORK, NY 10011**
0.141 mi.
744 ft. **Site 20 of 20 in cluster T**

Relative: **Higher**
Actual: **19 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20070101
Handler Name: NYC BD OF ED - PUBLIC SCHOOL 70
Handler Address: 315 W 17TH ST - NEW SCHOOL
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYR000082248
Contact Name: WILLIAM SLADE
Contact Address: W 17TH ST - NEW SCHOOL
Contact City,State,Zip: NEW YORK, NY 10011

NYC BD OF ED - PUBLIC SCHOOL 70 (Continued) **1004761248**

Contact Telephone:	914-681-6405
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 17TH ST - NEW SCHOOL
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	THE CITY OF NEW YORK CITYWIDE ADMIN SVCS
Owner Type:	Municipal
Operator Name:	THE CITY OF NEW YORK CITYWIDE ADMIN SVCS
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

NYC BD OF ED - PUBLIC SCHOOL 70 (Continued) **1004761248**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D009
Waste Description:	MERCURY

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	THE CITY OF NEW YORK CITYWIDE ADMIN SVCS
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1 CENTRE ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10007
Owner/Operator Telephone:	212-669-8730
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	THE CITY OF NEW YORK CITYWIDE ADMIN SVCS
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1 CENTRE ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10007
Owner/Operator Telephone:	212-669-8730
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	THE CITY OF NEW YORK CITYWIDE ADMIN SVCS

NYC BD OF ED - PUBLIC SCHOOL 70 (Continued) **1004761248**

Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1 CENTRE ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10007
Owner/Operator Telephone:	212-669-8730
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name:	NYC BD OF ED - PUBLIC SCHOOL 70
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	NYC BD OF ED - PUBLIC SCHOOL 70
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20000329
Handler Name:	NYC BD OF ED - PUBLIC SCHOOL 70
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

NYC BD OF ED - PUBLIC SCHOOL 70 (Continued) **1004761248**

Evaluation Action Summary:
Evaluations: No Evaluations Found

Y495 **CON EDISON** **NY MANIFEST** **S117058709**
East **309-307 W 20TH ST & 9TH AVE E** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.141 mi.
745 ft. **Site 8 of 12 in cluster Y**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	309-307 W 20TH ST & 9TH AVE E
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004508420
Facility Status:	Not reported
Location Address 1:	309 W 20 ST & 9TH AVE
Code:	BP
Location Address 2:	SB 3622
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004508420
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2014
Trans1 Recv Date:	04/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004508420
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported

CON EDISON (Continued) **S117058709**

Manifest Tracking Number:	002407486GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AJ496 **CON EDISON** **NY MANIFEST** **S116550955**
South **344-342 W 14TH ST & HUDSON ST** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.141 mi.
746 ft. **Site 1 of 7 in cluster AJ**

Relative: **Higher**
Actual: **17 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	344-342 W 14TH ST & HUDSON ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004493839
Facility Status:	Not reported
Location Address 1:	344 W 14 ST
Code:	BP
Location Address 2:	SB2370
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004493839
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON

CON EDISON (Continued) **S116550955**

Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/08/2014
Trans1 Recv Date:	04/08/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004493839
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406265GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AC497 **THE 305 CONDOMINIUM** **NY AST** **U003384334**
ESE **305 WEST 18TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.142 mi.
750 ft. **Site 2 of 8 in cluster AC**

Relative:
Higher

Actual:
19 ft.

AST:

Name:	THE 305 CONDOMINIUM
Address:	305 WEST 18TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-091219
Program Type:	PBS
UTM X:	584329.39815
UTM Y:	4510659.78206
Expiration Date:	03/24/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	2274
Affiliation Type:	Facility Owner
Company Name:	THE 305 CONDOMINIUM
Contact Type:	PAOPERTY MANAGER
Contact Name:	MARIA SANCHEZ
Address1:	ONE UNION SQUARE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 243-6722
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-04-12

Site Id:	2274
Affiliation Type:	Facility Operator
Company Name:	THE 305 CONDOMINIUM
Contact Type:	Not reported
Contact Name:	FAUSTO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 309-4274
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-04-06

Site Id:	2274
Affiliation Type:	Emergency Contact
Company Name:	THE 305 CONDOMINIUM
Contact Type:	Not reported
Contact Name:	EDDIE

THE 305 CONDOMINIUM (Continued) **U003384334**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 243-6722
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-04-12

Site Id:	2274
Affiliation Type:	Mail Contact
Company Name:	THE 305 CONDOMINIUM
Contact Type:	Not reported
Contact Name:	KAREN REUCH
Address1:	% BUCHBINDER & WARREN, LLC
Address2:	ONE UNION SQUARE WEST
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 243-6722
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-04-12

Tank Info:

Tank Number:	001
Tank Id:	3600
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	07/29/1998
Capacity Gallons:	5000

THE 305 CONDOMINIUM (Continued) **U003384334**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AK498 **WEST 19TH STREET DEVELOPMENT SITE** **NY UST** **U004048739**
NW **528 WEST 19TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.143 mi.
755 ft. **Site 1 of 18 in cluster AK**

Relative:
Lower

Actual:
8 ft.

UST:

Name:	WEST 19TH STREET DEVELOPMENT SITE
Address:	528 WEST 19TH STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-609671 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583839.32335
UTM Y:	4510989.38263
Site Type:	Other

Affiliation Records:

Site Id:	59048
Affiliation Type:	Facility Owner
Company Name:	RESPONSIVE RLTY LLC % GEORGETOWN 19 ST LLC
Contact Type:	PROJECT MANAGER
Contact Name:	PAUL LIPOF
Address1:	667 MADISON AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10021
Country Code:	001
Phone:	(212) 755-2323
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-07-28

Site Id:	59048
Affiliation Type:	Mail Contact
Company Name:	ENVIRONMENTAL LIABILITY MGT. OF NY, INC.
Contact Type:	Not reported
Contact Name:	PETER ZIMMERMANN
Address1:	250 WEST 57TH STREET
Address2:	SUITE 2421
City:	NEW YORK
State:	NY
Zip Code:	10107
Country Code:	001
Phone:	(212) 581-8023

WEST 19TH STREET DEVELOPMENT SITE (Continued) **U004048739**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-07-28

Site Id:	59048
Affiliation Type:	Facility Operator
Company Name:	WEST 19TH STREET DEVELOPMENT SITE
Contact Type:	Not reported
Contact Name:	TURNER CONSTRUCTION COMPANY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 691-0280
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-07-28

Site Id:	59048
Affiliation Type:	Emergency Contact
Company Name:	RESPONSIVE RLTY LLC % GEORGETOWN 19 ST LLC
Contact Type:	Not reported
Contact Name:	JOHN BURKHARDT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 208-3550
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-07-28

Tank Info:

Tank Number:	01
Tank ID:	179732
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/30/2004
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

WEST 19TH STREET DEVELOPMENT SITE (Continued) **U004048739**

Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None

Tank Number: 02
Tank ID: 179733
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/30/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None

Tank Number: 03
Tank ID: 179734
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/30/2004
Registered: True

WEST 19TH STREET DEVELOPMENT SITE (Continued) **U004048739**

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 04
Tank ID: 179735
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/30/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D00 - Pipe Type - No Piping
J00 - Dispenser - None

WEST 19TH STREET DEVELOPMENT SITE (Continued) **U004048739**

Tank Number:	05
Tank ID:	179736
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/30/2004
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	04/14/2017

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None

Tank Number:	06
Tank ID:	179737
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/30/2004
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

WEST 19TH STREET DEVELOPMENT SITE (Continued) **U004048739**

K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None

Tank Number: 07
Tank ID: 179738
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/30/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

J00 - Dispenser - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping

Tank Number: 08
Tank ID: 179739
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/30/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported

WEST 19TH STREET DEVELOPMENT SITE (Continued) **U004048739**

Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None

Tank Number: 09
Tank ID: 179740
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/30/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None

Tank Number: 10
Tank ID: 179741
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/30/2004
Registered: True
Tank Location: Underground

WEST 19TH STREET DEVELOPMENT SITE (Continued) **U004048739**

Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None

Tank Number: 11
Tank ID: 179742
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/30/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 12

WEST 19TH STREET DEVELOPMENT SITE (Continued) **U004048739**

Tank ID:	179743
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/30/2004
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	04/14/2017

Equipment Records:

D00 - Pipe Type - No Piping
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None

Tank Number:	13
Tank ID:	179744
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/30/2004
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None

WEST 19TH STREET DEVELOPMENT SITE (Continued) **U004048739**

K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping

Tank Number: 14
Tank ID: 179745
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/30/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

J00 - Dispenser - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None

Tank Number: 15
Tank ID: 207404
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: 07/15/2005
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR

WEST 19TH STREET DEVELOPMENT SITE (Continued) **U004048739**

Last Modified: 04/14/2017

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None

AK499 **MUCCIO JOHN** **RCRA NonGen / NLR** **1000555587**
NW **528 W 19TH ST** **FINDS** **NYD986981272**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.143 mi.
755 ft. **Site 2 of 18 in cluster AK**

Relative: **Lower**
Actual: **8 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	MUCCIO JOHN	
Handler Address:		528 W 19TH ST
Handler City,State,Zip:		NEW YORK, NY 10011-2807
EPA ID:		NYD986981272
Contact Name:		Not reported
Contact Address:		W 23RD ST
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		W 23RD ST
Mailing City,State,Zip:		NEW YORK, NY 10011
Owner Name:		MENDON LEASING
Owner Type:		Private
Operator Name:		MENDON LEASING
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No

MUCCIO JOHN (Continued) **1000555587**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MENDON LEASING

MUCCIO JOHN (Continued) **1000555587**

Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MENDON LEASING
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MENDON LEASING
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: MUCCIO JOHN	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: MUCCIO JOHN	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

MUCCIO JOHN (Continued) **1000555587**

Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: MUCCIO JOHN	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	19911127
Handler Name: MUCCIO JOHN	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004480106

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

MUCCIO JOHN (Continued) **1000555587**

ECHO:
- Envid: 1000555587
- Registry ID: 110004480106
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004480106
- Name: MUCCIO JOHN
- Address: 528 W 19TH ST
- City,State,Zip: NEW YORK, NY 10011

AH500 **301-303 WEST 21ST STREET** **NY AST** **U004045371**
ENE **301-303 WEST 21ST ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.143 mi.
755 ft. **Site 2 of 6 in cluster AH**

Relative:
Higher

Actual:
19 ft.

AST:
- Name: 301-303 WEST 21ST STREET
- Address: 301-303 WEST 21ST ST
- City,State,Zip: NEW YORK, NY 10011
- Region: STATE
- DEC Region: 2
- Site Status: Unregulated/Closed
- Facility Id: 2-294934
- Program Type: PBS
- UTM X: 584470.72650
- UTM Y: 4510831.49083
- Expiration Date: N/A
- Site Type: Unknown

Affiliation Records:
- Site Id: 13515
- Affiliation Type: Facility Owner
- Company Name: JOHN CATSIMATIDIS
- Contact Type: Not reported
- Contact Name: Not reported
- Address1: 823 ELEVENTH AVENUE
- Address2: Not reported
- City: NEW YORK
- State: NY
- Zip Code: 10019
- Country Code: 001
- Phone: (212) 956-5803
- EMail: Not reported
- Fax Number: Not reported
- Modified By: TRANSLAT
- Date Last Modified: 2004-03-04

- Site Id: 13515
- Affiliation Type: Mail Contact
- Company Name: DALTON MANAGEMENT CO., LLC
- Contact Type: Not reported
- Contact Name: MS. NEALLE SEAVEY
- Address1: 3 PARK AVENUE
- Address2: Not reported
- City: NEW YORK
- State: NY
- Zip Code: 10016
- Country Code: 001
- Phone: (212) 532-0333

301-303 WEST 21ST STREET (Continued) **U004045371**

EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 13515
Affiliation Type: Facility Operator
Company Name: 301-303 WEST 21ST STREET
Contact Type: Not reported
Contact Name: VICTOR ANGELILLO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 974-0780
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 13515
Affiliation Type: Emergency Contact
Company Name: JOHN CATSIMATIDIS
Contact Type: Not reported
Contact Name: MS. NEALLE SEAVEY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 532-0333
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank Id: 12046
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

301-303 WEST 21ST STREET (Continued) **U004045371**

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/01/2001
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AB501 **CON ED** **NY MANIFEST** **S118463904**
NE **351 W 22ND ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.143 mi.
755 ft. **Site 10 of 10 in cluster AB**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CON ED
Address:	351 W 22ND ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004858777
Facility Status:	Not reported
Location Address 1:	351 W 22ND ST
Code:	BP
Location Address 2:	SB 3978
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004858777
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported

CON ED (Continued) **S118463904**

Generator Ship Date:	10/23/2015
Trans1 Recv Date:	10/23/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004858777
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014087544JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Y502 **CON EDISON** **NY MANIFEST** **S117537182**
East **306 W 20TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.143 mi.
757 ft. **Site 9 of 12 in cluster Y**

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	306 W 20TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004697157
Facility Status:	Not reported
Location Address 1:	306 W 20TH ST
Code:	BP

CON EDISON (Continued) **S117537182**

Location Address 2:	MH 57555
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004697157
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	11/18/2014
Trans1 Recv Date:	11/18/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004697157
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002502151GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000

CON EDISON (Continued) **S117537182**

Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AC503 **CON EDISON** **NY MANIFEST** **S117058720**
ESE **308-306 W 19TH ST & 9TH AVE E** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.144 mi.
759 ft. **Site 3 of 8 in cluster AC**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	308-306 W 19TH ST & 9TH AVE E
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004508537
Facility Status:	Not reported
Location Address 1:	308 W 19 ST & 9TH AVE
Code:	BP
Location Address 2:	SB 3443
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004508537
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2014
Trans1 Recv Date:	04/22/2014
Trans2 Recv Date:	Not reported

CON EDISON (Continued) **S117058720**

TSD Site Recv Date:	04/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004508537
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416579GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AK504 **IAC BUILDING** **NY AST** **A100326242**
NW **555 WEST 18TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.144 mi.
759 ft. **Site 3 of 18 in cluster AK**

Relative: **Lower**
Actual: **7 ft.**

AST:

Name:	IAC BUILDING
Address:	555 WEST 18TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-611018
Program Type:	PBS
UTM X:	583771.96870
UTM Y:	4510966.67886
Expiration Date:	09/01/2026

IAC BUILDING (Continued) **A100326242**

Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 409790
Affiliation Type: Mail Contact
Company Name: INTER ACTIVE CORP/ IAC
Contact Type: Not reported
Contact Name: LUIS ACEVEDO, HEAD OF CORPORATE FACILITIES
Address1: 555 WEST 18TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10011
Country Code: 001
Phone: (212) 314-7300
EMail: LUIS.ACEVEDO@IAC.COM
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-08-13

Site Id: 409790
Affiliation Type: Facility Owner
Company Name: IAC/GEORGETOWN 19TH STREET, LLC.
Contact Type: HEAD OF CORPORATE FACILITIES
Contact Name: LUIS ACEVEDO
Address1: 555 WEST 18TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10011
Country Code: 001
Phone: (212) 314-7300
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-08-13

Site Id: 409790
Affiliation Type: Emergency Contact
Company Name: HTRF VENTURES LLC/IAC
Contact Type: Not reported
Contact Name: INTERACTIVE CORP/IAC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 314-7300
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-08-13

Site Id: 409790
Affiliation Type: Facility Operator
Company Name: IAC BLDG
Contact Type: Not reported

IAC BUILDING (Continued) **A100326242**

Contact Name:	INTER ACTIVE CORP/IAC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 314-7257
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-08-13

Tank Info:

Tank Number:	01
Tank Id:	227264
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	G02 - Tank Secondary Containment - Vault (w/access) L07 - Piping Leak Detection - Pressurized Piping Leak Detector H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G) J00 - Dispenser - None F05 - Pipe External Protection - Jacketed C01 - Pipe Location - Aboveground K01 - Spill Prevention - Catch Basin I02 - Overfill - High Level Alarm I03 - Overfill - Automatic Shut-Off D01 - Pipe Type - Steel/Carbon Steel/Iron A00 - Tank Internal Protection - None B01 - Tank External Protection - Painted/Asphalt Coating E02 - Piping Secondary Containment - Vault (with Access)
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/2006
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	08/13/2021
Material Name:	#2 fuel oil (on-site consumption)

AC505 **310 WEST 18TH STREET OWNERS CORP.** **NY TANKS** **S110772153**
ESE **310 WEST 18TH STREET** **NY Spills** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.144 mi.
760 ft. **Site 4 of 8 in cluster AC**

Relative:
Higher

Actual:
19 ft.

TANKS:

Name:	310 WEST 18TH STREET OWNERS CORP.
Address:	310 WEST 18TH STREET
City,State,Zip:	NEW YORK, NY 10011
Facility Id:	2-610670
Region:	STATE
DEC Region:	2
Site Status:	Inactive
Program Type:	PBS
Expiration Date:	N/A
UTM X:	584340.71952
UTM Y:	4510633.72784

SPILLS:

Name:	APT
Address:	310 WEST 18TH ST
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	1214170 / 2016-01-21
Facility ID:	1214170
Facility Type:	ER
DER Facility ID:	432708
Site ID:	477391
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	3101
Spill Date:	2012-12-30
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2012-12-30
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-12-30
Spill Record Last Update:	2016-01-21
Spiller Name:	MILTON
Spiller Company:	AGGRESSIVE ENERGY
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JANET LEON/ TENANT AVAIL 9-5 ONLY
DEC Memo:	"7/13/15 TJD File review. Spill reassigned from AH Primary (Ahmed) to AH Secondary (Patel). 12/23/15-Hiralkumar Patel. alternate address: none. PBS #: 2-610670. a PBS application was submitted in Oct. 2007, but it was returned on 10/10/2007 due to missing Section B of the application and incorrect information. PBS registration was never completed. other spills #: 9510451, 9612959, 9613049 spill # 9510451

310 WEST 18TH STREET OWNERS CORP. (Continued) **S110772153**

was reported on 11/20/1995 as odor complaint due to vent pipe close to caller's apartment window. case closed. spill # 9612959 was reported on 02/01/1997 by NYC DEP due to #2 fuel oil spill as a result of overfill. case closed without remarks. spill # 9613049 was reported on 02/04/1997 as #2 fuel oil spilled during delivery. case closed without remarks. based on google pic, site has five story building with a basement, next to a playground. 3:13 PM:- left message for Mr. Cohen. 310 West 18th Street Owners Corp. **property owner** c/o A. Michael Tyler Realty Corp. 122 East 42nd Street, Suite 1700 New York, NY 10168 Attn.: Irwin Cohen PH. (877) 641-5900 email: irwinc@amtrealtyny.com 01/20/16-Hiralkumar Patel. 3:10 PM:- visited site. noted fill port close to street curb, in front of building entrance. noted vent pipe on building's foundation wall in northwest corner of the building. no access to the building for an inspection. 3:14 PM:- left message for Mr. Cohen. 01/21/16-Hiralkumar Patel. 2:47 PM:- spoke with Mr. Cohen, property manager. informed him about open spill case and incomplete PBS registration for the tank system at the site. Mr. Cohen mentioned that spill occurred from vent pipe due to overfill and material spilled onto concrete surface outside the building. he stated that there was no impact inside the building and the spill was immediately cleaned up by Aggressive Energy. Mr. Cohen mentioned that East Coast Petroleum delivers oil to the building now. 3:17 PM:- spoke with Anthony Milanese at East Coast Petroleum. he stated that the site has 550 gal tank. case closed based on available information."

Remarks: "while filling company overflows into in basement, loss occurred on floor, not cleaned up properly"

All Materials:

Site ID:	477391
Operable Unit ID:	1227200
Operable Unit:	01
Material ID:	2224432
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AC506 **310 WEST 18TH STREET** **NY LTANKS** **S102238235**
ESE **310 WEST 18TH STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.144 mi.
760 ft. **Site 5 of 8 in cluster AC**

Relative: **Higher**
Actual: **19 ft.**

LTANKS:

Name:	310 WEST 18TH STREET
Address:	310 WEST 18TH STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9612959 / 2000-02-09
Facility ID:	9612959
Site ID:	163174
Spill Date:	1997-02-01
Spill Cause:	Tank Overfill

310 WEST 18TH STREET (Continued) **S102238235**

Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	1997-02-01
CID:	282
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-02-01
Spill Record Last Update:	2000-02-09
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	N/A
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	282988
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY "
Remarks:	"APPARENTLY OIL TANK WAS OVERFILLED IN THE APARTMENT COMPLEX CASTLE OIL MADE A DELIVERY THERE UNKNOWN IF THEY DID IT ABSORBENT WAS PUT DOWN BUT THERE IS PRODUCT STILL ON THE OUTSIDE OF BUILDING."

All Materials:

Site ID:	163174
Operable Unit ID:	1044498
Operable Unit:	01
Material ID:	341608
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AJ507 **CON EDISON** **NY MANIFEST** **S116550956**
South **334-30 W 14TH ST & HUDSON ST E** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.145 mi.
764 ft. **Site 2 of 7 in cluster AJ**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	334-30 W 14TH ST & HUDSON ST E
City,State,Zip:	NEW YORK, NY 10014
Country:	USA

CON EDISON (Continued) **S116550956**

EPA ID: NYP004493847
Facility Status: Not reported
Location Address 1: 334 W 14 ST
Code: BP
Location Address 2: SB2372
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004493847
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 04/08/2014
Trans1 Recv Date: 04/08/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/09/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004493847
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002406266GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

CON EDISON (Continued) **S116550956**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	800
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Y508 **CON EDISON** **RCRA NonGen / NLR** **1014396132**
East **307 W 20TH ST** **NJ MANIFEST** **NYP004183125**
1/8-1/4 **NEW YORK, NY 10011** **NY MANIFEST**
0.145 mi.
767 ft. **Site 10 of 12 in cluster Y**

Relative: **Higher**
Actual: **20 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		307 W 20TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004183125
Contact Name:		DAVID DUKE
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		917-559-8971
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No

CON EDISON (Continued) **1014396132**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160726
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090714
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON (Continued) **1014396132**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20160601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004183125
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DAVID DUKE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001083955GBF
EPA ID:	NYP004183125
Date Shipped:	07/14/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **1014396132**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/14/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/14/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	1000 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	307 W 20TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004183125
Facility Status:	Not reported
Location Address 1:	307 WEST 20th ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MANHATTAN
Location State:	NY
Location Zip:	10020

CON EDISON (Continued) **1014396132**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004183125
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 07/14/2009
Trans1 Recv Date: 07/14/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/14/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004183125
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 001083955GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H111
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 1000
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON (Continued) **1014396132**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Z509 **WESTSIDE AUTO CARE INC** **NY AST** **U004048753**
NW **521 WEST 19TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.146 mi.
769 ft. **Site 13 of 13 in cluster Z**

Relative:
Lower

Actual:
9 ft.

AST:

Name:	WESTSIDE AUTO CARE INC
Address:	521 WEST 19TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-603038
Program Type:	PBS
UTM X:	583927.52886
UTM Y:	4510983.77125
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	24992
Affiliation Type:	Facility Owner
Company Name:	LAN CHEN PEE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	521 WEST 19TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 989-5993
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24992
Affiliation Type:	Mail Contact
Company Name:	LAN CHEN PEE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	521 WEST 19TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 989-5993

WESTSIDE AUTO CARE INC (Continued) **U004048753**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24992
Affiliation Type:	Facility Operator
Company Name:	WESTSIDE AUTO CARE INC
Contact Type:	Not reported
Contact Name:	LAN CHEN PEE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 989-5993
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24992
Affiliation Type:	Emergency Contact
Company Name:	LAN CHEN PEE
Contact Type:	Not reported
Contact Name:	LAN CHEN PEE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 989-5993
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	01
Tank Id:	52753
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

G00 - Tank Secondary Containment - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

WESTSIDE AUTO CARE INC (Continued) **U004048753**

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/01/2000
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

AH510 **CON EDISON** **NY MANIFEST** **S117065829**
ENE **OPP 317 W 21 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.146 mi.
771 ft. **Site 3 of 6 in cluster AH**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	OPP 317 W 21 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004584249
Facility Status:	Not reported
Location Address 1:	OPP 317 W 21 ST
Code:	BP
Location Address 2:	SB3798
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004584249
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISION
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported

CON EDISON (Continued) **S117065829**

Generator Ship Date:	07/02/2014
Trans1 Recv Date:	07/02/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/07/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004584249
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002503277GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AA511 **513 WEST 20TH STREET LLC** **NY AST** **U004151153**
NNW **513 WEST 20TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.147 mi.
777 ft. **Site 23 of 24 in cluster AA**

Relative: AST:
Lower

Actual:
9 ft.

Name:	513 WEST 20TH STREET LLC
Address:	513 WEST 20TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-611302
Program Type:	PBS

513 WEST 20TH STREET LLC (Continued) **U004151153**

UTM X: 583892.16611
UTM Y: 4511064.82152
Expiration Date: 08/24/2024
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 426761
Affiliation Type: Facility Operator
Company Name: 513 WEST 20TH STREET LLC
Contact Type: Not reported
Contact Name: FRANK PISANI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 229-0853
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2010-03-29

Site Id: 426761
Affiliation Type: Emergency Contact
Company Name: 513 WEST 20 STREET LLC
Contact Type: Not reported
Contact Name: FRANK PISANI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (570) 807-6379
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2010-03-29

Site Id: 426761
Affiliation Type: Mail Contact
Company Name: 513 WEST 20 STREET LLC
Contact Type: MEMBER
Contact Name: RITA K. SAKHAIE
Address1: 600 LEXINGTON AVE 14TH FLR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10022
Country Code: 001
Phone: (212) 751-8050
EMail: JIM@ROY-AL.COM
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2019-06-06

Site Id: 426761

513 WEST 20TH STREET LLC (Continued) **U004151153**

Affiliation Type:	Facility Owner
Company Name:	513 WEST 20 STREET LLC
Contact Type:	AUTHORIZED REP.
Contact Name:	JAMES SHEEHAN
Address1:	600 LEXINGTON AVE 14TH FLR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(212) 751-8050
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-06-06

Tank Info:

Tank Number:	001
Tank Id:	233605
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	E00 - Piping Secondary Containment - None
	H00 - Tank Leak Detection - None
	F00 - Pipe External Protection - None
	L00 - Piping Leak Detection - None
	J02 - Dispenser - Suction Dispenser
	C03 - Pipe Location - Aboveground/Underground Combination
	K00 - Spill Prevention - None
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	G02 - Tank Secondary Containment - Vault (w/access)
	I05 - Overfill - Vent Whistle
Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/24/1994
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	06/06/2019
Material Name:	#2 fuel oil (on-site consumption)

AH512 **ISMO, LLC** **NY AST** **U003389443**
ENE **315 WEST 21ST STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.147 mi.
777 ft. **Site 4 of 6 in cluster AH**

Relative:
Higher

Actual:
19 ft.

AST:

Name:	ISMO, LLC
Address:	315 WEST 21ST STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-318604
Program Type:	PBS
UTM X:	584406.49041
UTM Y:	4510871.45648
Expiration Date:	05/20/2024
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	14700
Affiliation Type:	Facility Operator
Company Name:	MARHEF CORP.
Contact Type:	Not reported
Contact Name:	DANNY BIZATTI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 633-2701
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2004-09-28

Site Id:	14700
Affiliation Type:	Emergency Contact
Company Name:	ISMO,LLC
Contact Type:	Not reported
Contact Name:	NADER SHALOM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 686-5588
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-08-11

Site Id:	14700
Affiliation Type:	Mail Contact
Company Name:	GATSBY ENTERPRISES, LLC
Contact Type:	Not reported
Contact Name:	NADER SHALOM

ISMO, LLC (Continued) **U003389443**

Address1:	347 FIFTH AVE, SUITE 300
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 686-5588
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-04-09

Site Id:	14700
Affiliation Type:	Facility Owner
Company Name:	ISMO,LLC
Contact Type:	OWNER
Contact Name:	NADER SHALOM
Address1:	347 5TH AVE ,SUITE 300
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 686-5588
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-08-11

Tank Info:

Tank Number:	001
Tank Id:	16709
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B02 - Tank External Protection - Original Sacrificial Anode
E02 - Piping Secondary Containment - Vault (with Access)
F00 - Pipe External Protection - None

Tank Location:	Partially buried tank (tank with 10% or more below ground).... Tank is less than 90% above grade, partially buried.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/1986
Capacity Gallons:	3500
Tightness Test Method:	21
Date Test:	10/05/2018

ISMO, LLC (Continued) **U003389443**

Next Test Date:	10/05/2019
Date Tank Closed:	Not reported
Register:	True
Modified By:	TankSys
Last Modified:	01/31/2020
Material Name:	#2 fuel oil (on-site consumption)

AD513 **CON EDISON SERVICE BOX: 39622** **RCRA NonGen / NLR** **1016450721**
SSW **29 9TH AVE** **NY MANIFEST** **NYP004297487**
1/8-1/4 **NEW YORK, NY 10014**
0.148 mi.
779 ft. **Site 4 of 9 in cluster AD**

Relative: **Higher**

Actual: **15 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130501
Handler Name:	CON EDISON SERVICE BOX:	39622
Handler Address:		29 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004297487
Contact Name:		BENJAMIN BAMONTE
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-894-9549
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---

CON EDISON SERVICE BOX: 39622 (Continued) **1016450721**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130401
Handler Name: CON EDISON SERVICE BOX:	39622
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130501
Handler Name: CON EDISON SERVICE BOX:	39622
Federal Waste Generator Description:	Not a generator, verified

CON EDISON SERVICE BOX: 39622 (Continued) **1016450721**

State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	29 9TH AVE
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004297487
Facility Status:	Not reported
Location Address 1:	FO 29 9TH AVE
Code:	BP
Location Address 2:	SERV BOX 39622
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004297487
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193

CON EDISON SERVICE BOX: 39622 (Continued) **1016450721**

Trans2 State ID:	Not reported
Generator Ship Date:	04/01/2013
Trans1 Recv Date:	04/01/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/04/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004297487
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010456751JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Name:	CON EDISON
Address:	29 9TH AVE
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004841462
Facility Status:	Not reported
Location Address 1:	29 9TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported

CON EDISON SERVICE BOX: 39622 (Continued) **1016450721**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004841462
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 09/21/2015
Trans1 Recv Date: 09/21/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/21/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004841462
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014086304JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 30
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON SERVICE BOX: 39622 (Continued) **1016450721**

Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	D018
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AD514 **29-35 NINTH AVE (AT 13TH ST)** **NY AST** **U004045351**
SSW **29-35 NINTH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.148 mi.
779 ft. **Site 5 of 9 in cluster AD**

Relative:
Higher

Actual:
15 ft.

AST:

Name:	29-35 NINTH AVE (AT 13TH ST)
Address:	29-35 NINTH AVENUE
City,State,Zip:	NEW YORK, NY 10014
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-248436
Program Type:	PBS
UTM X:	583928.28866
UTM Y:	4510435.69105
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	9815
Affiliation Type:	Facility Owner
Company Name:	2935 EQUITIES LLC % SURTSEY REALTY CO.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	2130 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10023
Country Code:	001
Phone:	(212) 362-4772
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9815
Affiliation Type:	Mail Contact
Company Name:	SURTSEY REALTY CO.
Contact Type:	Not reported
Contact Name:	MR. HOWARD KATZ
Address1:	2130 BROADWAY
Address2:	SUITE 203
City:	NEW YORK
State:	NY

29-35 NINTH AVE (AT 13TH ST) (Continued) **U004045351**

Zip Code:	10023
Country Code:	001
Phone:	(212) 362-4772
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9815
Affiliation Type:	Facility Operator
Company Name:	29-35 NINTH AVE (AT 13TH ST)
Contact Type:	Not reported
Contact Name:	JAMES GALES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 299-6969
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9815
Affiliation Type:	Emergency Contact
Company Name:	2935 EQUITIES LLC % SURTSEY REALTY CO.
Contact Type:	Not reported
Contact Name:	HOWARD KATZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 362-4772
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	11124
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G03 - Tank Secondary Containment - Vault (w/o access)
C00 - Pipe Location - No Piping

29-35 NINTH AVE (AT 13TH ST) (Continued) **U004045351**

	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	F01 - Pipe External Protection - Painted/Asphalt Coating
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AD515 **CON EDISON SERVICE BOX: 39622** **RCRA NonGen / NLR** **1016449934**
SSW **29 9TH AVE** **NY MANIFEST** **NYP004254256**
1/8-1/4 **NEW YORK, NY 10014**
0.148 mi.
779 ft. **Site 6 of 9 in cluster AD**

Relative: **Higher**
Actual: **15 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130318
Handler Name:	CON EDISON SERVICE BOX:	39622
Handler Address:		29 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004254256
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No

CON EDISON SERVICE BOX: 39622 (Continued) **1016449934**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130218
Handler Name: CON EDISON SERVICE BOX:	39622
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY

CON EDISON SERVICE BOX: 39622 (Continued) **1016449934**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130318
Handler Name: CON EDISON SERVICE BOX:	39622
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	29 9TH AVE
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004254256
Facility Status:	Not reported
Location Address 1:	29 9TH AVE
Code:	BP
Location Address 2:	SERV BOX 39622
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004254256
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY

CON EDISON SERVICE BOX: 39622 (Continued) **1016449934**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/18/2013
Trans1 Recv Date:	02/18/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/19/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004254256
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840408JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AD516 **CON EDISON** **NJ MANIFEST** **S120676963**
SSW **29 9TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.148 mi.
779 ft. **Site 7 of 9 in cluster AD**

Relative:
Higher

Actual:
15 ft.

NJ MANIFEST:

EPA Id:	NYP004841462
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014086304JJK
EPA ID:	NYP004841462
Date Shipped:	9/21/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120676963**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AD517 **CON EDISON** **RCRA NonGen / NLR** **1019908054**
SSW **29 9TH AVE** **FINDS** **NYP004841462**
1/8-1/4 **NEW YORK, NY 10014** **ECHO**
0.148 mi.
779 ft. **Site 8 of 9 in cluster AD**

Relative: **Higher**
Actual: **15 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150921
Handler Name:	CON EDISON	
Handler Address:		29 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004841462
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

CON EDISON (Continued) **1019908054**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150921
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150921
Handler Name: CON EDISON	

CON EDISON (Continued) **1019908054**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069654305

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019908054
Registry ID:	110069654305
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069654305
Name:	CON EDISON
Address:	29 9TH AVE
City,State,Zip:	NEW YORK, NY 10014

AC518 **308 WEST 18TH ST** **NY LTANKS** **S102673112**
ESE **308 WEST 18TH ST** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.148 mi.
782 ft. **Site 6 of 8 in cluster AC**

Relative: **Higher**
Actual: **20 ft.**

LTANKS:

Name:	308 WEST 18TH ST
Address:	308 WEST 18TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9511332 / 1995-12-08
Facility ID:	9511332

308 WEST 18TH ST (Continued) **S102673112**

Site ID:	233856
Spill Date:	1995-12-07
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	1995-12-08
CID:	312
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-12-08
Spill Record Last Update:	1996-01-04
Spiller Name:	Not reported
Spiller Company:	BAERENKLAU
Spiller Address:	740 JAMAICA AVE
Spiller County:	001
Spiller Contact:	HOFFMAN
Spiller Phone:	(212) 924-0972
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	192678
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD GET THE ROOM OPENED AT 12/08/95 - 1 GALLON SPILLED - CLEANED BY BAERENKLAU FUEL."
Remarks:	"DRIVER OVERFILLED TANK - COULD NOT GET IN TO CLEANUP THE 1 QUART SPILL DUE TO THE ROOM BEING LOCKED"

All Materials:

Site ID:	233856
Operable Unit ID:	1025557
Operable Unit:	01
Material ID:	358681
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AL519 **CON EDISON** **NY MANIFEST** **S117313555**
SE **F/O 311 WEST 17 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.149 mi.
787 ft. **Site 1 of 14 in cluster AL**

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	F/O 311 WEST 17 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004603239
Facility Status:	Not reported
Location Address 1:	F/O 311 WEST 17 ST
Code:	BP
Location Address 2:	SB3016
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004603239
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/21/2014
Trans1 Recv Date:	07/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004603239
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002608469GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117313555**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AL520 **CON EDISON** **NJ MANIFEST** **S120677015**
SE **311 W 17TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.149 mi.
787 ft. **Site 2 of 14 in cluster AL**

Relative: **Higher**
Actual: **20 ft.**

NJ MANIFEST:

EPA Id:	NYP004842064
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002613259GBF
EPA ID:	NYP004842064
Date Shipped:	9/22/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **S120677015**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Manifest Number:	002613314GBF
EPA ID:	NYP004842064
Date Shipped:	9/24/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

CON EDISON (Continued) **S120677015**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AL521 **CON EDISON** **RCRA NonGen / NLR** **1019908726**
SE **311 W 17TH ST** **NYP004849984**
1/8-1/4 **NEW YORK, NY 10011**
0.149 mi.
787 ft. **Site 3 of 14 in cluster AL**

Relative: **Higher**
Actual: **20 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20151211
Handler Name:	CON EDISON	
Handler Address:		311 W 17TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004849984
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No

CON EDISON (Continued) **1019908726**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20151211
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator

CON EDISON (Continued) **1019908726**

State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20151211
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AL522 **CON EDISON** **RCRA NonGen / NLR** **1019908109**
SE **311 W 17TH ST** **NYP004842064**
1/8-1/4 **NEW YORK, NY 10011**
0.149 mi.
787 ft. **Site 4 of 14 in cluster AL**

Relative: **Higher**
Actual: **20 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20150922
Handler Name: CON EDISON	
Handler Address:	311 W 17TH ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004842064
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

CON EDISON (Continued) **1019908109**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No

CON EDISON (Continued) **1019908109**

Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150922
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150922
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AL523 **CON EDISON** **NY MANIFEST** **S118462835**
SE **311 W 17TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.149 mi.
787 ft. **Site 5 of 14 in cluster AL**

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	311 W 17TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004842064
Facility Status:	Not reported
Location Address 1:	311 W 17TH ST
Code:	BP
Location Address 2:	SB 3016
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004842064
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/24/2015
Trans1 Recv Date:	09/24/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004842064
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002613314GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S118462835**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AL524 **CON EDISON** **NY MANIFEST** **S118463331**
SE **311 W 17TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.149 mi.
787 ft. **Site 6 of 14 in cluster AL**

Relative: **Higher**
Actual: **20 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	311 W 17TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004849984
Facility Status:	Not reported
Location Address 1:	311 W 17TH ST
Code:	BP
Location Address 2:	SB 3016
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004849984
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S118463331**

Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	10/08/2015
Trans1 Recv Date:	10/08/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/12/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004849984
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002612452GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AL525 **CON EDISON** **NJ MANIFEST** **S120677657**
SE **311 W 17TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.149 mi.
787 ft. **Site 7 of 14 in cluster AL**

Relative:
Higher

Actual:
20 ft.

NJ MANIFEST:

EPA Id:	NYP004849984
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002612452GBF
EPA ID:	NYP004849984
Date Shipped:	10/8/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120677657**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AK526 **MENDON** **NY LTANKS** **S104275639**
NW **542 WEST 19TH STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.150 mi.
790 ft. **Site 4 of 18 in cluster AK**

Relative: **Lower**
Actual: **8 ft.**

LTANKS:

Name:	MENDON
Address:	542 WEST 19TH STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9011674 / 2004-12-23
Facility ID:	9011674
Site ID:	133724
Spill Date:	1991-02-06
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1991-11-14
SWIS:	3101
Investigator:	JMROMMEL
Referred To:	Not reported
Reported to Dept:	1991-02-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1991-02-12
Spill Record Last Update:	2004-12-23
Spiller Name:	Not reported
Spiller Company:	MENDON PARKING GARAGE
Spiller Address:	528 WEST 19TH STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	114912
DEC Memo:	"Spill originally assigned to Sullivan and closed on 11/14/1991. Re-opened due to spill 0012509 (Merritt Engineering working for potential buyer, found contamiantion) and 9504874 (Con Ed excavation on south side of street, soils saturated with diesel). Site investigation and remediation to be tracked by this spill number 9011674. Rommel. 12/6/04 Spill address originally 528 W19th Street, changed to 542 (both of which are actually listed by City as 80-94 11th Street or just 80 11th Street. 542 W19th Street is address on PBS 2-032239. Stip mailed to Barry Haskell 362 Kingsland Avenue

MENDON (Continued) **S104275639**

Brooklyn NY 11222 Deadline for return of signed stip 1/24/05. Rommel 12/23/04 Received call from Mark at Sive, Paget and Riesel, PC 212-421-2150 who represent the developer (Georgetown). MGP site is being handled by Joe Moloughney under BCP program.The remediation will remove all soil between 18th and 19th Streets to 15 feet. The four tanks were already pulled during remediation and ten others were found and also pulled. The developer has been informed that they must complete the tank registration and closure process for all the tanks on-site and they have assured me they will do so. Spill closed. Rommel "

Remarks: "(4) 550 GAL TANKS WERE DISCOVERED DURING A ROUTINE CON ED STREET PATROL,NYCDEP WAS TOLD THAT TANKS FAILED 10 YEAR PBS TEST IN 1990, TANKS WERE NOT IN USE BUT NOT CLOSED PROPERLY."

All Materials:

Site ID:	133724
Operable Unit ID:	951649
Operable Unit:	01
Material ID:	428204
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AK527 **MENDON LEASING CORP** **NY UST** **U001831289**
NW **542 WEST 19TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.150 mi.
790 ft. **Site 5 of 18 in cluster AK**

Relative: **Lower**
Actual: **8 ft.**

UST:

Name:	MENDON LEASING CORP
Address:	542 WEST 19TH ST
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-032239 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583821.77528
UTM Y:	4510998.71321
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	198
Affiliation Type:	Facility Owner
Company Name:	COTARD REALTY ASSOCIATES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	362 KINGSLAND AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222

MENDON LEASING CORP (Continued) **U001831289**

Country Code:	001
Phone:	(718) 389-2100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	198
Affiliation Type:	Mail Contact
Company Name:	COTARD REALTY COMPANY
Contact Type:	Not reported
Contact Name:	JIM MCELHINNEY
Address1:	362 KINGSLAND AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 389-2100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	198
Affiliation Type:	Facility Operator
Company Name:	MENDON LEASING CORP
Contact Type:	Not reported
Contact Name:	MENDON LEASING CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 255-0900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-07-21

Site Id:	198
Affiliation Type:	Emergency Contact
Company Name:	COTARD REALTY COMPANY
Contact Type:	Not reported
Contact Name:	THOMAS FASINI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 795-1137
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

MENDON LEASING CORP (Continued) **U001831289**

Tank Info:

Tank Number:	001
Tank ID:	43215
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	002
Tank ID:	43216
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

MENDON LEASING CORP (Continued) **U001831289**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number: 003
Tank ID: 43217
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number: 004
Tank ID: 43218
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT

MENDON LEASING CORP (Continued) **U001831289**

Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 005
Tank ID: 43219
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number: 006
Tank ID: 43220
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

MENDON LEASING CORP (Continued) **U001831289**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number: 023
Tank ID: 876
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 3300
Install Date: Not reported
Date Tank Closed: 11/01/1991
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 123
Tank ID: 875
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 2200
Install Date: Not reported
Date Tank Closed: 11/01/1991

MENDON LEASING CORP (Continued) **U001831289**

Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

W528 **860 WASHINGTON STREET CONSTRUCTION SITE** **RCRA NonGen / NLR** **1016455542**
SW **860 WASHINGTON ST** **FINDS** **NYR000206458**
1/8-1/4 **NEW YORK, NY 10014** **ECHO**
0.150 mi. **NY MANIFEST**
794 ft. **Site 17 of 17 in cluster W**

Relative: **Lower**

Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20150630
Handler Name:	860 WASHINGTON STREET CONSTRUCTION SITE
Handler Address:	860 WASHINGTON ST
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYR000206458
Contact Name:	ROMAN IWASIW
Contact Address:	5TH AVE FL 6
Contact City,State,Zip:	NEW YORK, NY 10017
Contact Telephone:	212-490-2626
Contact Fax:	212-490-1060
Contact Email:	RIWASIW@PGP.US.COM
Contact Title:	SR VICE PRES CONSTR DEV
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	WASHINGTON ST
Mailing City,State,Zip:	NEW YORK, NY 10014
Owner Name:	860 WASHINGTON STREET LLC
Owner Type:	Private
Operator Name:	860 WASHINGTON CONSTRUCTION SITE
Operator Type:	Private

860 WASHINGTON STREET CONSTRUCTION SITE (Continued) **1016455542**

Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20151117
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

860 WASHINGTON STREET CONSTRUCTION SITE (Continued) **1016455542**

Hazardous Waste Summary:
- Waste Code: D008
- Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	860 WASHINGTON CONSTRUCTION SITE
Legal Status:	Private
Date Became Current:	20131231
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	860 WASHINGTON STREET LLC
Legal Status:	Private
Date Became Current:	20131231
Date Ended Current:	Not reported
Owner/Operator Address:	609 5TH AVE FL 6
Owner/Operator City,State,Zip:	NEW YORK, NY 10017
Owner/Operator Telephone:	212-490-2626
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	860 WASHINGTON STREET LLC
Legal Status:	Private
Date Became Current:	20131231
Date Ended Current:	Not reported
Owner/Operator Address:	609 5TH AVE FL 6
Owner/Operator City,State,Zip:	NEW YORK, NY 10017
Owner/Operator Telephone:	212-490-2626
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	860 WASHINGTON CONSTRUCTION SITE
Legal Status:	Private
Date Became Current:	20131231
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:
- Receive Date: 20150630
- Handler Name: 860 WASHINGTON STREET CONSTRUCTION SITE

860 WASHINGTON STREET CONSTRUCTION SITE (Continued) **1016455542**

Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131223
Handler Name: 860 WASHINGTON CONSTRUCTION SITE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 236220
NAICS Description: COMMERCIAL AND INSTITUTIONAL BUILDING CONSTRUCTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110056505553

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016455542
Registry ID: 110056505553
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110056505553
Name: 860 WASHINGTON STREET CONSTRUCTION SITE

860 WASHINGTON STREET CONSTRUCTION SITE (Continued) **1016455542**

Address: 860 WASHINGTON ST
City,State,Zip: NEW YORK, NY 10014

NY MANIFEST:
Name: 860 WASHINGTON CONSTRUCTION SITE
Address: 860 WASHINGTON ST
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYR000206458
Facility Status: Not reported
Location Address 1: 860 WASHINGTON ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000206458
Mailing Name: 860 WASHINGTON CONSTRUCTION SITE
Mailing Contact: ROMAN IWASIW
Mailing Address 1: 609 5TH AVE - FLOOR 6
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10014
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 04/28/2014
Trans1 Recv Date: 04/28/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/28/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000206458
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 012791270JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: Y
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N

860 WASHINGTON STREET CONSTRUCTION SITE (Continued) **1016455542**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	63520
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG529 **CONSOLIDATED EDISON** **NY MANIFEST** **1009240244**
North **10TH AVE & W 22ND ST** **N/A**
1/8-1/4 **NEW YORK, NY**
0.151 mi.
796 ft. **Site 2 of 13 in cluster AG**

Relative: **Lower**
Actual: **11 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	10TH AVE & W 22ND ST
City,State,Zip:	NEW YORK, NY
Country:	USA
EPA ID:	NYP004072974
Facility Status:	Not reported
Location Address 1:	10TH AVE & W 22ND ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004072974
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA

CONSOLIDATED EDISON (Continued) **1009240244**

Mailing Phone: 2124602808

AG530 **CON EDISON GASMAIN 87924367** **RCRA-LQG** **1026726654**
North **10TH AVE & W 22 ST** **NYP005246394**
1/8-1/4 **NEW YORK, NY 10011**
0.151 mi.
796 ft. **Site 3 of 13 in cluster AG**

Relative: **Lower**

Actual: **11 ft.**

RCRA-LQG:

Date Form Received by Agency:	20201007
Handler Name:	CON EDISON GASMAIN 87924367
Handler Address:	10TH AVE & W 22 ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP005246394
Contact Name:	THOMAS TEELING
Contact Address:	IRVING PL, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	Yes
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No

CON EDISON GASMAIN 87924367 (Continued) **1026726654**

Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211231
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20201007
Handler Name: CON EDISON GASMAIN 87924367	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON GASMAIN 87924367 (Continued) **1026726654**

Evaluation Action Summary:
Evaluations: No Evaluations Found

AG531 **CON EDISON - MANHOLE 43093** **RCRA-LQG** **1016143257**
North **OPP 197 10TH AVE** **NY MANIFEST** **NYP004259933**
1/8-1/4 **NEW YORK, NY 10014**
0.151 mi.
797 ft. **Site 4 of 13 in cluster AG**

Relative: **Lower**

Actual: **11 ft.**

RCRA-LQG:

Date Form Received by Agency:	20140327
Handler Name:	CON EDISON - MANHOLE 43093
Handler Address:	OPP 197 10TH AVE
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYP004259933
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	631-208-0233
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN

CON EDISON - MANHOLE 43093 (Continued) **1016143257**

Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20130221
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported

CON EDISON - MANHOLE 43093 (Continued) **1016143257**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20130221
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140327
Handler Name: CON EDISON - MANHOLE 43093
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130221
Handler Name: CON EDISON MANHOLE: 43093
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130321
Handler Name: CON EDISON MANHOLE: 43093
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:

CON EDISON - MANHOLE 43093 (Continued) **1016143257**

NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 197 10TH AVE OPPOSITE
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYP004259933
Facility Status: Not reported
Location Address 1: OPP 197 10TH AVE
Code: BP
Location Address 2: MH 43093
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004259933
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 02/21/2013
Trans1 Recv Date: 02/21/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/22/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004259933
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046

CON EDISON - MANHOLE 43093 (Continued) **1016143257**

TSDF ID 2:	Not reported
Manifest Tracking Number:	010707135JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	4000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AM532 **SUNOCO S/S-501 W 14TH ST** **RCRA NonGen / NLR** **1000556261**
WSW **501 WEST 14TH STREET** **US AIRS** **NYD986988210**
1/8-1/4 **NEW YORK, NY 10014** **FINDS**
0.151 mi. **ECHO**
798 ft. **Site 1 of 13 in cluster AM**

Relative: RCRA NonGen / NLR:
Lower

Actual: Date Form Received by Agency:		20070101
8 ft. Handler Name:	1014 GAS INC	
Handler Address:		501 W 14TH ST
Handler City,State,Zip:		NEW YORK, NY 10014-1006
EPA ID:		NYD986988210
Contact Name:		Not reported
Contact Address:		W 14TH ST
Contact City,State,Zip:		NEW YORK, NY 10014
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported

SUNOCO S/S-501 W 14TH ST (Continued) **1000556261**

Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 14TH ST
Mailing City,State,Zip:	NEW YORK, NY 10014
Owner Name:	DAVID OIL CO
Owner Type:	Private
Operator Name:	DAVID OIL CO
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414

SUNOCO S/S-501 W 14TH ST (Continued) **1000556261**

Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D018
Waste Description:	BENZENE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	DAVID OIL CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1158 BROADWAY
Owner/Operator City,State,Zip:	HEWLETT, NY 11557
Owner/Operator Telephone:	516-295-3400
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	DAVID OIL CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1158 BROADWAY
Owner/Operator City,State,Zip:	HEWLETT, NY 11557
Owner/Operator Telephone:	516-295-3400
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	DAVID OIL CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1158 BROADWAY
Owner/Operator City,State,Zip:	HEWLETT, NY 11557
Owner/Operator Telephone:	516-295-3400
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

SUNOCO S/S-501 W 14TH ST (Continued) **1000556261**

Historic Generators:

Receive Date:	19990708
Handler Name: 1014 GAS INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: 1014 GAS INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: 1014 GAS INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19911213
Handler Name: 1014 GAS INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

SUNOCO S/S-501 W 14TH ST (Continued) **1000556261**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

US AIRS MINOR:
Envid: 1000556261
Region Code: 02
Programmatic ID: AIR NY0000002620500229
Facility Registry ID: 110001577605
D and B Number: Not reported
Primary SIC Code: 5541
NAICS Code: 999999
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002620500229
Facility Registry ID: 110001577605
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-06-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:
Registry ID: 110001577605

Click Here:

Environmental Interest/Information System:
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

SUNOCO S/S-501 W 14TH ST (Continued) **1000556261**

corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000556261
Registry ID:	110001577605
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110001577605
Name:	SUNOCO S/S-501 W 14TH ST
Address:	501 WEST 14TH STREET
City,State,Zip:	NEW YORK, NY 10014

AM533 **1014 GAS CORP** **NY UST** **U001838977**
WSW **501 WEST 14TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.151 mi.
798 ft. **Site 2 of 13 in cluster AM**

Relative: **Lower**

Actual: **8 ft.**

UST:

Name:	1014 GAS CORP
Address:	501 WEST 14TH ST
City,State,Zip:	NEW YORK, NY 10014
Id/Status:	2-204420 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583767.25903
UTM Y:	4510625.58638
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	7104
Affiliation Type:	Mail Contact
Company Name:	DAVID OIL CORP
Contact Type:	Not reported
Contact Name:	AL CARUOLO V.P. MKTG
Address1:	1158 BROADWAY
Address2:	Not reported
City:	HEWLETT
State:	NY
Zip Code:	11557
Country Code:	001
Phone:	(516) 295-3400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	7104
Affiliation Type:	Facility Operator
Company Name:	1014 GAS CORP
Contact Type:	Not reported
Contact Name:	1014 GAS CORP

1014 GAS CORP (Continued) **U001838977**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 989-2802
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	7104
Affiliation Type:	Emergency Contact
Company Name:	DAVID OIL CORP.
Contact Type:	Not reported
Contact Name:	MIKE YARDENI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 989-2802
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	7104
Affiliation Type:	Facility Owner
Company Name:	DAVID OIL CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1158 BROADWAY
Address2:	Not reported
City:	HEWLETT
State:	NY
Zip Code:	11557
Country Code:	001
Phone:	(516) 295-3400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	28006
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	05/01/1950
Date Tank Closed:	08/01/1993
Registered:	True
Tank Location:	Underground

1014 GAS CORP (Continued) **U001838977**

Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 002
Tank ID: 28007
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 05/01/1950
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 003
Tank ID: 28008
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550

1014 GAS CORP (Continued) **U001838977**

Install Date: 10/01/1957
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 004
Tank ID: 28009
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 10/01/1957
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 005

1014 GAS CORP (Continued) **U001838977**

Tank ID: 28010
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 10/01/1957
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 006
Tank ID: 28011
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 03/01/1967
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

1014 GAS CORP (Continued) **U001838977**

F00 - Pipe External Protection - None

Tank Number: 007
Tank ID: 28012
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 03/01/1967
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 008
Tank ID: 28013
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 03/01/1967
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

1014 GAS CORP (Continued) **U001838977**

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 009
Tank ID: 28014
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 09/01/1964
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 010
Tank ID: 28015
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 09/01/1964
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

1014 GAS CORP (Continued) **U001838977**

Equipment Records:

G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 011
Tank ID: 28016
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 07/01/1964
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 012
Tank ID: 28017
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 07/01/1964
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported

1014 GAS CORP (Continued) **U001838977**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 013
Tank ID: 28018
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 4000
Install Date: 04/01/1984
Date Tank Closed: 04/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 07/01/1991
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None

Tank Number: 014
Tank ID: 28019
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 4000
Install Date: 04/01/1984
Date Tank Closed: 04/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel

1014 GAS CORP (Continued) **U001838977**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 07/01/1991
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser

Tank Number: 015
Tank ID: 28020
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 2000
Install Date: 04/01/1971
Date Tank Closed: 04/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 07/01/1991
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Tank Number: 016
Tank ID: 28021
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use

1014 GAS CORP (Continued) **U001838977**

Capacity Gallons:	4000
Install Date:	04/01/1971
Date Tank Closed:	04/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	01
Date Test:	07/01/1991
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser

AM534 **501 W 14TH ST** **NY LTANKS** **S100153686**
WSW **501 W 14TH ST** **N/A**
1/8-1/4 **NEW YORK, NY**
0.151 mi.
798 ft. **Site 3 of 13 in cluster AM**

Relative: **Lower**

Actual: **8 ft.**

LTANKS:

Name:	501 W 14TH ST
Address:	501 W 14TH ST
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	9103563 / 2006-05-22
Facility ID:	9103563
Site ID:	66953
Spill Date:	1991-07-01
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	1991-07-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1991-07-01

501 W 14TH ST (Continued) **S100153686**

Spill Record Last Update:	2006-05-22
Spiller Name:	Not reported
Spiller Company:	SPARTAN PETROLEUM-A
Spiller Address:	1158 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	64044
DEC Memo:	"A consultant (no name) called on 6/24/2003 to say the station had been condemned and removed as part of the west side highway improvements. This specific site is now a part of developed city park (Part of Hudson River Park). 4/12/04-Vought-Spill transferred from Sullivan to Sun as per Rommel. 6/29/04 PBS shows tanks removed in 1993. David Oil was owner. Transferred from Sun to Foley. (KMF) 5/3/05 501 W 14th St is also known as 65-79 11th Ave. Property is vacant land between 14th and 15th Streets and 10th and 11th Avenues. Block 686, Lot 29. Requested Hank Alpert submit tank closure report for tanks removed in 1993. 5/3/05 Email from Hank Alpert, owner of David Oil. In December of 1996, the NYS Department of Transporation, Real Estate Division acquired the property under a condemnation involving the restructuring of the Westside Highway. As a result of the condemnation, NYS now owns the property. As part of the settlement, the State purchased all underground storage tanks and presumably removed them."
Remarks:	"4K TANK, PETROTITE .6GPH, SYSTEM TEST; WILL EXCAVATE, ISOLATE & RETEST"

All TTF:

Facility ID:	9103563
Spill Number:	9103563
Spill Tank Test:	1538720
Site ID:	66953
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	66953
Operable Unit ID:	954363
Operable Unit:	01
Material ID:	422704
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum

501 W 14TH ST (Continued) **S100153686**

Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AM535 **505 W.14TH ST** **NY LTANKS** **S106703283**
WSW **505 W.14TH ST / 10TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY**
0.151 mi.
799 ft. **Site 4 of 13 in cluster AM**

Relative: LTANKS:
Lower

Actual: Name:	505 W.14TH ST
8 ft. Address:	505 W.14TH ST / 10TH AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	8806146 / 2006-05-01
Facility ID:	8806146
Site ID:	130664
Spill Date:	1988-10-20
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SKCARLSO
Referred To:	NFA 05/01/2006
Reported to Dept:	1988-10-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-10-31
Spill Record Last Update:	2006-05-03
Spiller Name:	Not reported
Spiller Company:	SUNOCO
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	112589
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SUN 11/02 transferred from sullivan to tipple 11/03 TANKS ADMIN CLOSED 4/1/1998 NO REPORT FOUND//TANKS MAY STILL CONTAIN PRODUCT AND BE IN GROUND///THEN OWNED BY DAVID OIL COMPANY, 1158 BROADWAY HEWLETT NY 11557 12/10/03 mt/// Transferred from Tipple to Sun 12/16/2005 - Feng - Reassigned from Sun to Feng as per Sun. (RJF) 3/2/06: Case reassigned from Feng to Andersen. Mailed assessment required letter, due back 5/2/06. 3/21/06: Letter returned to sender. Resent letter. 4/3/06: Email from Annesta says that the State of NY took ownership of this property by eminent domain on 10/16/96. 4/5/06: Emailed City DOT asking if they own the property and requesting permission for

505 W.14TH ST (Continued) **S106703283**

Annesta to drill on the site. 4/17/06: Resent letter to Annesta stating that, as a previous owner, they are still required to conduct an investigation. I noted that they should contact DOT prior to scheduling work at the site. Investigation due by 6/17/06. 4/20/06: Received call from Tom Fink, attorney (phone 585-546-6448). This lot was taken over by the city during the west side highway expansion. It is not accessible to perform an investigation. 5/1/06: Case closed. NFA issued. 5/3/06: Received a letter from city DOT indicating that the site is privately owned."

Remarks: "4K TK FAILED PETRO, L R =-0.086 GPH. 4K TK SYS FAILED PETRO, L R = -1.77 GPH."

All TTF:

Facility ID:	8806146
Spill Number:	8806146
Spill Tank Test:	1534789
Site ID:	130664
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	130664
Operable Unit ID:	922978
Operable Unit:	01
Material ID:	454502
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AM536 **HUDSON PIER BUS DEPOT** **NY CBS** **S104073311**
WSW **11 AVE/WEST 15 STREET** **NY AST** **N/A**
1/8-1/4 **NEW YORK, NY 10011** **NY CBS AST**
0.152 mi.
801 ft. **Site 5 of 13 in cluster AM**

Relative: **Lower**
Actual: **6 ft.**

CBS:

Name:	HUDSON PIER BUS DEPOT
Address:	11 WEST 15 STREET
City,State,Zip:	NEW YORK, NY 10011
CBS Number:	2-000287
Program Type:	CBS

HUDSON PIER BUS DEPOT (Continued) **S104073311**

Facility Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 2
UTMX: 584985.96189
UTMY: 4510039.53111

AST:
Name: HUDSON PIER BUS DEPOT
Address: 11 WEST 15 STREET
City,State,Zip: NEW YORK, NY 10011
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-000287
Program Type: CBS
UTM X: 584985.96189
UTM Y: 4510039.53111
Expiration Date: N/A
Site Type: Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Tank Info:

Tank Number: CBS-HUD-1
Tank Id: 191635
Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 11/01/1957
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 12/01/1999
Register: True
Modified By: CBSInit
Last Modified: 03/21/2005
Material Name: Not reported

Tank Number: CBS-HUD-2
Tank Id: 194238
Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 04/01/2001
Capacity Gallons: 650
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 10/01/2003
Register: True
Modified By: CBSInit
Last Modified: 03/21/2005

HUDSON PIER BUS DEPOT (Continued) **S104073311**

Material Name: Not reported

CBS AST:

CBS Number:	2-000287
ICS Number:	Not reported
PBS Number:	2-190284
MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	IN SERVICE
Facility Type:	F
Telephone:	(212) 690-9602
Facility Town:	NEW YORK CITY
Region:	STATE
Expiration Date:	08/11/2003
Total Capacity of All Active Tanks(gal):	650
Operator:	NEW YORK CITY TRANSIT
Emergency Contact:	HOWARD MATZA
Emergency Phone:	(718) 243-4581
Owner Name:	NEW YORK CITY TRANSIT
Owner Address:	370 JAY STREET ROOM 819
Owner City,St,Zip:	BROOKLYN, NY 11201
Owner Telephone:	(718) 243-4581
Owner Type:	State Government
Owner Sub Type:	None
Mail Name:	NEW YORK CITY TRANSIT
Mail Contact Addr:	370 JAY STREET
Mail Contact Addr2:	ROOM 819
Mail Contact Contact:	JOSEPHINE BROWN
Mail Contact City,St,Zip:	BROOKLYN, NY 11201
Mail Phone:	(718) 243-4581

Tank Id:	CBS-HUD-1
CAS Number:	107211
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	11/57
Tank Closed:	12/99
Capacity (Gal):	550
Chemical:	Ethylene glycol
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	1
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	08/10/1995
Certified Date:	06/06/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	Galvanized Steel
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Pipe Flag:	Painted/Asphalt Coating
Leak Detection:	None
Overfill Protection:	Product Level Gauge

HUDSON PIER BUS DEPOT (Continued) **S104073311**

Haz Percent:	100
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6201
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	04/30/2001

Tank Id:	CBS-HUD-2
CAS Number:	107211
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	04/01
Tank Closed:	Not reported
Capacity (Gal):	650
Chemical:	Ethylene glycol
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	1
Tank Secret:	False
Tank Secondary Containment:	Cut-off Walls
Tank Error Status:	No Missing Data
Date Entered:	02/12/2001
Certified Date:	06/06/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Galvanized Steel
Pipe Internal:	None
Pipe External:	Other
Pipe Flag:	Other
Leak Detection:	46
Overfill Protection:	High Level Alarm
Haz Percent:	100
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6201
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True

HUDSON PIER BUS DEPOT (Continued) **S104073311**

Pre-Printed Renewal App Last Printed: 04/30/2001

Y537 **CON EDISON SERVICE BOX: 3631** **RCRA NonGen / NLR** **1017772920**
East **305 W 20TH ST FRONT OF SB3631** **FINDS** **NYP004506978**
1/8-1/4 **NEW YORK, NY 10011**
0.152 mi.
804 ft. **Site 11 of 12 in cluster Y**

Relative: **Higher**

Actual: **20 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140522
Handler Name:	CON EDISON SERVICE BOX:	3631
Handler Address:		305 W 20TH ST FRONT OF SB3631
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004506978
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported

CON EDISON SERVICE BOX: 3631 (Continued) **1017772920**

2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON SERVICE BOX: 3631 (Continued) **1017772920**

Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140522
Handler Name: CON EDISON SERVICE BOX:	3631
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063802835

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

Y538 **CON EDISON** **NY MANIFEST** **S117058571**
East **305 W 20TH ST FRONT OF SB3631** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.152 mi.
804 ft. **Site 12 of 12 in cluster Y**

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	305 W 20TH ST FRONT OF SB3631
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004506978
Facility Status:	Not reported

CON EDISON (Continued) **S117058571**

Location Address 1:	306 W 20 ST & 9TH
Code:	BP
Location Address 2:	SB 3631
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004506978
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/21/2014
Trans1 Recv Date:	04/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004506978
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416549GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117058571**

Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AC539 **306 W. 18 REALTY LLC** **NY UST** **U004289022**
ESE **306 WEST 18TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.153 mi.
807 ft. **Site 7 of 8 in cluster AC**

Relative:
Higher

Actual:
20 ft.

UST:

Name:	306 W. 18 REALTY LLC
Address:	306 WEST 18TH ST
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-207969 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	06/30/2022
UTM X:	584326.48490
UTM Y:	4510638.36119
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	7408
Affiliation Type:	Mail Contact
Company Name:	306 W. 18 REALTY LLC
Contact Type:	Not reported
Contact Name:	306 W.18 REALTY LLC
Address1:	145 HUGUENOT STREET, 5TH FLOOR
Address2:	Not reported
City:	NEW ROCHELLE
State:	NY
Zip Code:	10801
Country Code:	001
Phone:	(914) 637-6200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-05-01

Site Id:	7408
Affiliation Type:	Facility Operator
Company Name:	306 W 18 REALTY LLC
Contact Type:	Not reported
Contact Name:	SCOTT MCDONALD
Address1:	Not reported

306 W. 18 REALTY LLC (Continued) **U004289022**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 989-0687
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	7408
Affiliation Type:	Emergency Contact
Company Name:	306 W 18 REALTY LLC
Contact Type:	Not reported
Contact Name:	BAUER BOILERS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 299-1650
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2007-03-14

Site Id:	7408
Affiliation Type:	Facility Owner
Company Name:	306 W. 18 REALTY LLC
Contact Type:	GENERAL MANAGER
Contact Name:	MARTIN BLUM
Address1:	145 HUGUENOT STREET, 5TH FLOOR
Address2:	Not reported
City:	NEW ROCHELLE
State:	NY
Zip Code:	10801
Country Code:	001
Phone:	(914) 637-6200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-05-01

Tank Info:

Tank Number:	001
Tank ID:	9653
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	1500
Install Date:	01/01/1910
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]

306 W. 18 REALTY LLC (Continued) **U004289022**

Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	34
Date Test:	05/16/2019
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	LABATIST
Last Modified:	05/21/2019

Equipment Records:

C01 - Pipe Location - Aboveground
L99 - Piping Leak Detection - Other
G99 - Tank Secondary Containment - Other
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I05 - Overfill - Vent Whistle
E00 - Piping Secondary Containment - None
H08 - Tank Leak Detection - Weep holes in Vaults with no access for inspection
J05 - Dispenser - On Site Heating System (Supply/Return)

AI540 **312-316 WEST 15TH ST** **NY AST** **U003384052**
SSE **312-316 WEST 15TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.153 mi.
808 ft. **Site 2 of 7 in cluster AI**

Relative: **Higher**
Actual: **20 ft.**

AST:

Name:	312-316 WEST 15TH ST
Address:	312-316 WEST 15TH ST
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-081043
Program Type:	PBS
UTM X:	584224.15341
UTM Y:	4510437.59592
Expiration Date:	03/24/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	1667
Affiliation Type:	Mail Contact
Company Name:	FELIX BERNARDO
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	323 WEST 14TH ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10014
Country Code:	001
Phone:	(212) 255-3732
EMail:	Not reported

312-316 WEST 15TH ST (Continued) **U003384052**

Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1667
Affiliation Type:	Emergency Contact
Company Name:	FELIX BERNARDO
Contact Type:	Not reported
Contact Name:	FELIX BERNARDO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 255-3732
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1667
Affiliation Type:	Facility Operator
Company Name:	312-316 WEST 15TH ST
Contact Type:	Not reported
Contact Name:	FELIX BERNARDO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 255-3732
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2006-12-29

Site Id:	1667
Affiliation Type:	Facility Owner
Company Name:	FELIX BERNARDO
Contact Type:	OWNER
Contact Name:	FELIX BERNARDO
Address1:	323 WEST 14TH ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10014
Country Code:	001
Phone:	(212) 255-3732
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2006-12-29

Tank Info:

312-316 WEST 15TH ST (Continued) **U003384052**

Tank Number: 001
Tank Id: 2876
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/17/1985
Capacity Gallons: 4000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DMPOKRZY
Last Modified: 05/19/2017
Material Name: #2 fuel oil (on-site consumption)

AA541 **STORAGE USA** **NY UST** **U001834792**
NNW **510 WEST 21ST STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.154 mi.
812 ft. **Site 24 of 24 in cluster AA**

Relative: **Lower**
Actual: **10 ft.**

UST:
Name: STORAGE USA
Address: 510 WEST 21ST STREET
City,State,Zip: NEW YORK, NY 10011
Id/Status: 2-238325 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 583913.77716
UTM Y: 4511112.50433
Site Type: Other

Affiliation Records:
Site Id: 8920
Affiliation Type: Facility Owner
Company Name: SUSA PARTNERSHIP LP DBA STORAGE USA #541
Contact Type: Not reported
Contact Name: Not reported
Address1: 175 TOYOTA PLAZA, SUITE 700

STORAGE USA (Continued) **U001834792**

Address2:	Not reported
City:	MEMPHIS
State:	TN
Zip Code:	38103
Country Code:	001
Phone:	(901) 252-2000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8920
Affiliation Type:	Mail Contact
Company Name:	STORAGE USA
Contact Type:	Not reported
Contact Name:	KEVIN TALLMAN
Address1:	175 TOYOTA PLAZA
Address2:	SUITE 700
City:	MEMPHIS
State:	TN
Zip Code:	38103
Country Code:	001
Phone:	(901) 252-2000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8920
Affiliation Type:	Facility Operator
Company Name:	STORAGE USA
Contact Type:	Not reported
Contact Name:	CARLOS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 924-5111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8920
Affiliation Type:	Emergency Contact
Company Name:	SUSA PARTNERSHIP LP DBA STORAGE USA #541
Contact Type:	Not reported
Contact Name:	KEVIN TALLMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(410) 721-3666

STORAGE USA (Continued) **U001834792**

EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank ID: 12716
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 05/01/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J00 - Dispenser - None

AD542 **CON EDISON - SERVICE BOX 2142** **RCRA-LQG** **1016450190**
SSW **407 WEST 13TH ST** **NY MANIFEST** **NYP004291878**
1/8-1/4 **NEW YORK, NY 10009**
0.154 mi.
814 ft. **Site 9 of 9 in cluster AD**

Relative: RCRA-LQG:
Lower
Actual: Date Form Received by Agency: 20140327
13 ft. Handler Name: CON EDISON - SERVICE BOX 2142
Handler Address: 407 WEST 13TH ST
Handler City,State,Zip: NEW YORK, NY 10009
EPA ID: NYP004291878
Contact Name: DENNIS HUACON
Contact Address: IRVING PLACE, 15TH FL NE
Contact City,State,Zip: NEW YORK, NY 10003
Contact Telephone: 212-460-2757
Contact Fax: 518-473-8034
Contact Email: HUACOND@CONED.COM
Contact Title: ASSOCIATE SCIENTIST
EPA Region: 02

CON EDISON - SERVICE BOX 2142 (Continued) **1016450190**

Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No

CON EDISON - SERVICE BOX 2142 (Continued) **1016450190**

Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20130306
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20130306
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20140327
Handler Name:	CON EDISON - SERVICE BOX 2142
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON - SERVICE BOX 2142 (Continued) **1016450190**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130306
Handler Name: CON EDISON SERVICE BOX: 2142
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130406
Handler Name: CON EDISON SERVICE BOX: 2142
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 407 WEST 13TH ST
City,State,Zip: NEW YORK, NY 10009
Country: USA
EPA ID: NYP004291878
Facility Status: Not reported
Location Address 1: 407 WEST 13TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK

CON EDISON - SERVICE BOX 2142 (Continued) **1016450190**

Location State:	NY
Location Zip:	10009
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004291878
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/06/2013
Trans1 Recv Date:	03/06/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/08/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004291878
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010841199JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	5000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks

CON EDISON - SERVICE BOX 2142 (Continued) **1016450190**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AK543 **17TH STREET DEVELOPMENT PROJECT** **RCRA-LQG** **1019326111**
NW **76 11TH AVE** **NYR000227256**
1/8-1/4 **NEW YORK, NY 10011**
0.155 mi.
819 ft. **Site 6 of 18 in cluster AK**

Relative: RCRA-LQG:
Lower

Actual: Date Form Received by Agency:	20160615
6 ft. Handler Name:	17TH STREET DEVELOPMENT PROJECT
Handler Address:	76 11TH AVE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYR000227256
Contact Name:	RAYMOND J TOTILLO
Contact Address:	MADISON AVE
Contact City,State,Zip:	NEW YORK, NY 10022
Contact Telephone:	212-297-9888
Contact Fax:	212-300-8001
Contact Email:	RTOTILLO@HFZCAP.COM
Contact Title:	SENIOR PROJECT EXECUTIVE
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	MADISON AVE
Mailing City,State,Zip:	NEW YORK, NY 10022
Owner Name:	76 ELEVENTH AVENUE PROPERTY OWNER LLC
Owner Type:	Private
Operator Name:	OMNI CONSTRUCTION
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported

17TH STREET DEVELOPMENT PROJECT (Continued) **1019326111**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160713
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D018
Waste Description:	BENZENE

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	OMNI CONSTRUCTION
Legal Status:	Private
Date Became Current:	20160501
Date Ended Current:	Not reported

17TH STREET DEVELOPMENT PROJECT (Continued) **1019326111**

Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	76 ELEVENTH AVENUE PROPERTY OWNER LLC
Legal Status:	Private
Date Became Current:	20150507
Date Ended Current:	Not reported
Owner/Operator Address:	600 MADISON AVE
Owner/Operator City,State,Zip:	NEW YORK, NY 10022
Owner/Operator Telephone:	212-297-9888
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20160615
Handler Name:	17TH STREET DEVELOPMENT PROJECT
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	23611
NAICS Description:	RESIDENTIAL BUILDING CONSTRUCTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AK544 **17TH STREET DEVELOPMENT PROJECT** **NY ENG CONTROLS** **S110748434**
NW **76 11TH AVENUE** **NY INST CONTROL** **N/A**
1/8-1/4 **NEW YORK, NY 10011** **NY BROWNFIELDS**
0.155 mi. **NY MANIFEST**
819 ft. **Site 7 of 18 in cluster AK**

Relative: **Lower**
Actual: **6 ft.**

ENG CONTROLS:

Name:	17TH STREET DEVELOPMENT PROJECT
Address:	76 11TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Site Code:	58929
HW Code:	C231036

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Control Code: 17
Control Type: ENG
Date Record Added: 06/08/2012
Date Rec Updated: 12/06/2019
Updated By: LSZINOMA
Site Description: "Location: The 17th Street Development Project site encompasses the entire block between 17th and 18th Streets, and between 10th and 11th Avenues in the lower west side of Manhattan. Site Features: The site contains two residential towers with commercial space on the first floor and subsurface parking. The main distinguishing feature is a former elevated rail line that cuts across the eastern edge of the site, which was recently converted to use as a city park, High Line Park. Current Zoning/Use(s): This 1.75 acre site is currently zoned for commercial/residential. Surrounding Uses: The surrounding land use is historically commercial, but new residential development has been proceeding rapidly in recent years. Past Use of the Site: This site is one parcel in the larger Consolidated Edison W 18th Street Former Manufactured Gas Plant (MGP) site, ID No. V00530. Most of the gas making and purification facilities of the MGP were located on this parcel. Prior to its use as an Manufactured Gas Plant, the property experienced very little development, consisting of the construction of five houses which were torn down after about 20 years to make room for expansion of the MGP operations. The plant began distribution of coal gas in November 1834 and operated continuously until it shut down in 1901 or 1902. In 1932, the railroad acquired the property. Some of the buildings were razed and a rail yard was built. The remaining buildings were used for other uses. Later, the tracks were removed, the remaining buildings razed and the site used as a parking lot. In the 1950s an automobile fueling and service station was built on the west end of the site. In the 1980s the service station was demolished and since then the site has been used exclusively as a parking lot. 17th Street Development Corporation is the BCP Volunteer for this block/site only. The remainder of the former MGP site remains under the Con Edison Voluntary Cleanup Agreement. Site Geology and Hydrogeology: Between 50 and 80 feet of unconsolidated materials overlie schist bedrock at the site. The fill deepens significantly from east to west. Overburden consists of three distinct stratigraphic units. The top unit is fill, generally highly permeable, ranging from 13 to 45 feet thick. The upper 5 to 10 feet of fill contains significant man-made materials and the remnants of former structures and debris. Below that fill is mostly fine to medium or fine to coarse sand with trace brick, ash wood fibers and concrete. Buried in the fill along the western border of the site is timber cribbing that formed the shoreline and bulkhead at one time. Below the fill is a Silty-Clay Unit which forms a low permeability aquitard. Water and other liquids such as coal tar do not readily pass through this layer. It varies in thickness from 40 feet to as little as 2 feet. Below the Silty-Clay Unit is the Sand Unit, a moderately permeable aquifer ranging from 20 to 40 feet thick. Permeability is far greater in a horizontal direction than vertical. The water table is located approximately 9 feet bgs and is nearly flat. Flow is generally toward the Hudson River to the west. In some areas, groundwater flow is influenced by man-made factors such as the Hudson River bulkhead, sheet pile walls, utilities, and by various man-made flows such as leaking water lines, drains, sewers, and building dewatering systems."
Env Problem: "Nature and Extent of Contamination: Remediation, which is complete,

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

	was a combination of shallow excavation and removal between 3 and 7 feet over the entire site, in-situ solidification of the middle third of the site, and containment with the installation of a sealed sheet pile wall keyed into a confining clay-silt layer in the western third of the site. Remaining behind are: 1) very minor contamination under the High Line (eastern part of the site), inaccessible due to extensive High Line foundations and 2) significant mobile tar contained by the sheet pile wall and the underlying confining clay-silt layer. In this western third of the site, coal tar continues to slowly accumulate and is collected from 4 collection wells and removed from the site. Special Resources Impacted/Threatened: Before the remediation, which cut off any offsite migration of contaminants via groundwater, manufactured gas plant (MGP) contamination appears to have migrated from this property primarily to the north and west, but has not been observed in the Hudson River 160 feet to the west of the site. Off-site groundwater and/or soil gas contamination will be addressed as part of the overall remedy for the larger West 18th Street MGP site. "
Health Problem:	"People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by the site. Direct contact with contaminated soil is unlikely since it is located under pavement. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying or nearby buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Although no buildings currently occupy the site, future site development is likely to include at least one structure and the potential for soil vapor intrusion will be evaluated. Any concerns related to soil vapor intrusion in nearby buildings will be addressed under the voluntary agreement for the West 18th Street MGP Site."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	40:44:41 / 73:59:58
Dell:	False
Record Add:	2004-07-01 08:31:00
Record Upd:	2014-12-09 10:57:00
Updated By:	GWHEITZM
Own Op:	4
Sub Type:	D
Owner Name:	Laureen Weinshall
Owner Company:	U.S. Drug Enforcement Administration, New York Division
Owner Address:	99 Tenth Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10011
Owner Country:	United States of America
Own Op:	6
Sub Type:	E
Owner Name:	John Shannon
Owner Company:	76 Eleventh Avenue Property Owner LLC
Owner Address:	c/o HFZ Capital Group

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Owner Addr2:	600 Madison Avenue, 15th Floor
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Scott M. Stringer
Owner Company:	Office of Manhattan Borough President
Owner Address:	One Centre Street
Owner Addr2:	Municipal Building, 19th Floor South
Owner City,St,Zip:	New York, NY 10007
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Theresa Mirhol
Owner Company:	Mid-Manhattan Library
Owner Address:	455 Fifth Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10016
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	John Shannon
Owner Company:	76 Eleventh Avenue Property Owner LLC
Owner Address:	c/o HFZ Capital Group
Owner Addr2:	600 Madison Ave, 15th Floor
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	John Flood
Owner Company:	Hudson Park Branch Library
Owner Address:	66 Leroy Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10014-3929
Owner Country:	United States of America
HW Code:	C231036
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	benzene, toluene, ethylbenzene and xylenes (BTEX)

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	Polycyclic Aromatic Hydrocarbons (PAHs), Total
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	v00248
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2008-02-01 14:48:00
Record Updated:	2008-02-01 14:48:00
Updated By:	WSOTTAWA
Crossref ID:	v00530
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2008-02-01 14:48:00
Record Updated:	2008-02-01 14:48:00
Updated By:	WSOTTAWA
Crossref ID:	C231036-12-10
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2014-12-04 16:49:00
Record Updated:	2014-12-04 16:49:00
Updated By:	GWHEITZM
Crossref ID:	2014000399345
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2014-12-04 15:32:00
Record Updated:	2014-12-15 16:25:00
Updated By:	RHDANA
Crossref ID:	December 31, 2010
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2014-12-04 16:50:00
Record Updated:	2014-12-04 16:50:00
Updated By:	GWHEITZM

Name:	17TH STREET DEVELOPMENT PROJECT
Address:	76 11TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Site Code:	58929
HW Code:	C231036
Control Code:	15
Control Type:	ENG
Date Record Added:	06/08/2012
Date Rec Updated:	12/06/2019
Updated By:	LSZINOMA
Site Description:	"Location: The 17th Street Development Project site encompasses the entire block between 17th and 18th Streets, and between 10th and 11th Avenues in the lower west side of Manhattan. Site Features: The site contains two residential towers with commercial space on the first floor and subsurface parking. The main distinguishing feature is a former elevated rail line that cuts across the eastern edge of the site, which was recently converted to use as a city park, High Line Park. Current Zoning/Use(s): This 1.75 acre site is currently zoned for commercial/residential. Surrounding Uses: The surrounding land use is historically commercial, but new residential development has

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

been proceeding rapidly in recent years. Past Use of the Site: This site is one parcel in the larger Consolidated Edison W 18th Street Former Manufactured Gas Plant (MGP) site, ID No. V00530. Most of the gas making and purification facilities of the MGP were located on this parcel. Prior to its use as an Manufactured Gas Plant, the property experienced very little development, consisting of the construction of five houses which were torn down after about 20 years to make room for expansion of the MGP operations. The plant began distribution of coal gas in November 1834 and operated continuously until it shut down in 1901 or 1902. In 1932, the railroad acquired the property. Some of the buildings were razed and a rail yard was built. The remaining buildings were used for other uses. Later, the tracks were removed, the remaining buildings razed and the site used as a parking lot. In the 1950s an automobile fueling and service station was built on the west end of the site. In the 1980s the service station was demolished and since then the site has been used exclusively as a parking lot. 17th Street Development Corporation is the BCP Volunteer for this block/site only. The remainder of the former MGP site remains under the Con Edison Voluntary Cleanup Agreement. Site Geology and Hydrogeology: Between 50 and 80 feet of unconsolidated materials overlie schist bedrock at the site. The fill deepens significantly from east to west. Overburden consists of three distinct stratigraphic units. The top unit is fill, generally highly permeable, ranging from 13 to 45 feet thick. The upper 5 to 10 feet of fill contains significant man-made materials and the remnants of former structures and debris. Below that fill is mostly fine to medium or fine to coarse sand with trace brick, ash wood fibers and concrete. Buried in the fill along the western border of the site is timber cribbing that formed the shoreline and bulkhead at one time. Below the fill is a Silty-Clay Unit which forms a low permeability aquitard. Water and other liquids such as coal tar do not readily pass through this layer. It varies in thickness from 40 feet to as little as 2 feet. Below the Silty-Clay Unit is the Sand Unit, a moderately permeable aquifer ranging from 20 to 40 feet thick. Permeability is far greater in a horizontal direction than vertical. The water table is located approximately 9 feet bgs and is nearly flat. Flow is generally toward the Hudson River to the west. In some areas, groundwater flow is influenced by man-made factors such as the Hudson River bulkhead, sheet pile walls, utilities, and by various man-made flows such as leaking water lines, drains, sewers, and building dewatering systems."

Env Problem: "Nature and Extent of Contamination: Remediation, which is complete, was a combination of shallow excavation and removal between 3 and 7 feet over the entire site, in-situ solidification of the middle third of the site, and containment with the installation of a sealed sheet pile wall keyed into a confining clay-silt layer in the western third of the site. Remaining behind are: 1) very minor contamination under the High Line (eastern part of the site), inaccessible due to extensive High Line foundations and 2) significant mobile tar contained by the sheet pile wall and the underlying confining clay-silt layer. In this western third of the site, coal tar continues to slowly accumulate and is collected from 4 collection wells and removed from the site. Special Resources Impacted/Threatened: Before the remediation, which cut off any offsite migration of contaminants via groundwater, manufactured gas plant (MGP) contamination appears to have migrated from this property primarily to the north and west, but has not been observed in the

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

	Hudson River 160 feet to the west of the site. Off-site groundwater and/or soil gas contamination will be addressed as part of the overall remedy for the larger West 18th Street MGP site. "
Health Problem:	"People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by the site. Direct contact with contaminated soil is unlikely since it is located under pavement. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying or nearby buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Although no buildings currently occupy the site, future site development is likely to include at least one structure and the potential for soil vapor intrusion will be evaluated. Any concerns related to soil vapor intrusion in nearby buildings will be addressed under the voluntary agreement for the West 18th Street MGP Site."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	40:44:41 / 73:59:58
Dell:	False
Record Add:	2004-07-01 08:31:00
Record Upd:	2014-12-09 10:57:00
Updated By:	GWHEITZM
Own Op:	4
Sub Type:	D
Owner Name:	Laureen Weinshall
Owner Company:	U.S. Drug Enforcement Administration, New York Division
Owner Address:	99 Tenth Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10011
Owner Country:	United States of America
Own Op:	6
Sub Type:	E
Owner Name:	John Shannon
Owner Company:	76 Eleventh Avenue Property Owner LLC
Owner Address:	c/o HFZ Capital Group
Owner Addr2:	600 Madison Avenue, 15th Floor
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Scott M. Stringer
Owner Company:	Office of Manhattan Borough President
Owner Address:	One Centre Street
Owner Addr2:	Municipal Building, 19th Floor South
Owner City,St,Zip:	New York, NY 10007
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Theresa Mirhol
Owner Company:	Mid-Manhattan Library

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Owner Address:	455 Fifth Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10016
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	John Shannon
Owner Company:	76 Eleventh Avenue Property Owner LLC
Owner Address:	c/o HFZ Capital Group
Owner Addr2:	600 Madison Ave, 15th Floor
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	John Flood
Owner Company:	Hudson Park Branch Library
Owner Address:	66 Leroy Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10014-3929
Owner Country:	United States of America
HW Code:	C231036
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	Polycyclic Aromatic Hydrocarbons (PAHs), Total
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	v00248
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2008-02-01 14:48:00
Record Updated:	2008-02-01 14:48:00
Updated By:	WSOTTAWA
Crossref ID:	v00530
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Record Added Date:	2008-02-01 14:48:00
Record Updated:	2008-02-01 14:48:00
Updated By:	WSOTTAWA
Crossref ID:	C231036-12-10
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2014-12-04 16:49:00
Record Updated:	2014-12-04 16:49:00
Updated By:	GWHEITZM
Crossref ID:	2014000399345
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2014-12-04 15:32:00
Record Updated:	2014-12-15 16:25:00
Updated By:	RHDANA
Crossref ID:	December 31, 2010
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2014-12-04 16:50:00
Record Updated:	2014-12-04 16:50:00
Updated By:	GWHEITZM

Name:	17TH STREET DEVELOPMENT PROJECT
Address:	76 11TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Site Code:	58929
HW Code:	C231036
Control Code:	18
Control Type:	ENG
Date Record Added:	06/08/2012
Date Rec Updated:	12/06/2019
Updated By:	LSZINOMA
Site Description:	"Location: The 17th Street Development Project site encompasses the entire block between 17th and 18th Streets, and between 10th and 11th Avenues in the lower west side of Manhattan. Site Features: The site contains two residential towers with commercial space on the first floor and subsurface parking. The main distinguishing feature is a former elevated rail line that cuts across the eastern edge of the site, which was recently converted to use as a city park, High Line Park. Current Zoning/Use(s): This 1.75 acre site is currently zoned for commercial/residential. Surrounding Uses: The surrounding land use is historically commercial, but new residential development has been proceeding rapidly in recent years. Past Use of the Site: This site is one parcel in the larger Consolidated Edison W 18th Street Former Manufactured Gas Plant (MGP) site, ID No. V00530. Most of the gas making and purification facilities of the MGP were located on this parcel. Prior to its use as an Manufactured Gas Plant, the property experienced very little development, consisting of the construction of five houses which were torn down after about 20 years to make room for expansion of the MGP operations. The plant began distribution of coal gas in November 1834 and operated continuously until it shut down in 1901 or 1902. In 1932, the railroad acquired the property. Some of the buildings were razed and a rail yard was built. The remaining buildings were used for other uses. Later, the tracks were removed, the remaining buildings razed and the site used as a parking lot. In the 1950s an automobile fueling and service station was built on the west end of the site. In the 1980s the

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

service station was demolished and since then the site has been used exclusively as a parking lot. 17th Street Development Corporation is the BCP Volunteer for this block/site only. The remainder of the former MGP site remains under the Con Edison Voluntary Cleanup Agreement. Site Geology and Hydrogeology: Between 50 and 80 feet of unconsolidated materials overlie schist bedrock at the site. The fill deepens significantly from east to west. Overburden consists of three distinct stratigraphic units. The top unit is fill, generally highly permeable, ranging from 13 to 45 feet thick. The upper 5 to 10 feet of fill contains significant man-made materials and the remnants of former structures and debris. Below that fill is mostly fine to medium or fine to coarse sand with trace brick, ash wood fibers and concrete. Buried in the fill along the western border of the site is timber cribbing that formed the shoreline and bulkhead at one time. Below the fill is a Silty-Clay Unit which forms a low permeability aquitard. Water and other liquids such as coal tar do not readily pass through this layer. It varies in thickness from 40 feet to as little as 2 feet. Below the Silty-Clay Unit is the Sand Unit, a moderately permeable aquifer ranging from 20 to 40 feet thick. Permeability is far greater in a horizontal direction than vertical. The water table is located approximately 9 feet bgs and is nearly flat. Flow is generally toward the Hudson River to the west. In some areas, groundwater flow is influenced by man-made factors such as the Hudson River bulkhead, sheet pile walls, utilities, and by various man-made flows such as leaking water lines, drains, sewers, and building dewatering systems."

Env Problem: "Nature and Extent of Contamination: Remediation, which is complete, was a combination of shallow excavation and removal between 3 and 7 feet over the entire site, in-situ solidification of the middle third of the site, and containment with the installation of a sealed sheet pile wall keyed into a confining clay-silt layer in the western third of the site. Remaining behind are: 1) very minor contamination under the High Line (eastern part of the site), inaccessible due to extensive High Line foundations and 2) significant mobile tar contained by the sheet pile wall and the underlying confining clay-silt layer. In this western third of the site, coal tar continues to slowly accumulate and is collected from 4 collection wells and removed from the site. Special Resources Impacted/Threatened: Before the remediation, which cut off any offsite migration of contaminants via groundwater, manufactured gas plant (MGP) contamination appears to have migrated from this property primarily to the north and west, but has not been observed in the Hudson River 160 feet to the west of the site. Off-site groundwater and/or soil gas contamination will be addressed as part of the overall remedy for the larger West 18th Street MGP site. "

Health Problem: "People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by the site. Direct contact with contaminated soil is unlikely since it is located under pavement. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying or nearby buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Although no buildings currently occupy the site, future site development is likely to include at least one structure and the potential for soil vapor intrusion will be evaluated. Any concerns

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

	related to soil vapor intrusion in nearby buildings will be addressed under the voluntary agreement for the West 18th Street MGP Site."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	40:44:41 / 73:59:58
Dell:	False
Record Add:	2004-07-01 08:31:00
Record Upd:	2014-12-09 10:57:00
Updated By:	GWHEITZM
Own Op:	4
Sub Type:	D
Owner Name:	Laureen Weinshall
Owner Company:	U.S. Drug Enforcement Administration, New York Division
Owner Address:	99 Tenth Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10011
Owner Country:	United States of America
Own Op:	6
Sub Type:	E
Owner Name:	John Shannon
Owner Company:	76 Eleventh Avenue Property Owner LLC
Owner Address:	c/o HFZ Capital Group
Owner Addr2:	600 Madison Avenue, 15th Floor
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Scott M. Stringer
Owner Company:	Office of Manhattan Borough President
Owner Address:	One Centre Street
Owner Addr2:	Municipal Building, 19th Floor South
Owner City,St,Zip:	New York, NY 10007
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Theresa Mirhol
Owner Company:	Mid-Manhattan Library
Owner Address:	455 Fifth Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10016
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	John Shannon
Owner Company:	76 Eleventh Avenue Property Owner LLC
Owner Address:	c/o HFZ Capital Group
Owner Addr2:	600 Madison Ave, 15th Floor
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	John Flood

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Owner Company:	Hudson Park Branch Library
Owner Address:	66 Leroy Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10014-3929
Owner Country:	United States of America
HW Code:	C231036
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	Polycyclic Aromatic Hydrocarbons (PAHs), Total
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	v00248
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2008-02-01 14:48:00
Record Updated:	2008-02-01 14:48:00
Updated By:	WSOTTAWA
Crossref ID:	v00530
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2008-02-01 14:48:00
Record Updated:	2008-02-01 14:48:00
Updated By:	WSOTTAWA
Crossref ID:	C231036-12-10
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2014-12-04 16:49:00
Record Updated:	2014-12-04 16:49:00
Updated By:	GWHEITZM
Crossref ID:	2014000399345
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2014-12-04 15:32:00
Record Updated:	2014-12-15 16:25:00
Updated By:	RHDANA

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Crossref ID: December 31, 2010
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2014-12-04 16:50:00
Record Updated: 2014-12-04 16:50:00
Updated By: GWHEITZM

INST CONTROL:
Name: 17TH STREET DEVELOPMENT PROJECT
Address: 76 11TH AVENUE
City,State,Zip: NEW YORK, NY 10011
Site Code: 58929
Control Name: Ground Water Use Restriction
HW Code: C231036
Control Code: 08
Control Type: INST
Dt record added: 06/08/2012
Dt rec updated: 12/06/2019
Updated By: LSZINOMA
Site Code: 58929
Site Description: "Location: The 17th Street Development Project site encompasses the entire block between 17th and 18th Streets, and between 10th and 11th Avenues in the lower west side of Manhattan. Site Features: The site contains two residential towers with commercial space on the first floor and subsurface parking. The main distinguishing feature is a former elevated rail line that cuts across the eastern edge of the site, which was recently converted to use as a city park, High Line Park. Current Zoning/Use(s): This 1.75 acre site is currently zoned for commercial/residential. Surrounding Uses: The surrounding land use is historically commercial, but new residential development has been proceeding rapidly in recent years. Past Use of the Site: This site is one parcel in the larger Consolidated Edison W 18th Street Former Manufactured Gas Plant (MGP) site, ID No. V00530. Most of the gas making and purification facilities of the MGP were located on this parcel. Prior to its use as an Manufactured Gas Plant, the property experienced very little development, consisting of the construction of five houses which were torn down after about 20 years to make room for expansion of the MGP operations. The plant began distribution of coal gas in November 1834 and operated continuously until it shut down in 1901 or 1902. In 1932, the railroad acquired the property. Some of the buildings were razed and a rail yard was built. The remaining buildings were used for other uses. Later, the tracks were removed, the remaining buildings razed and the site used as a parking lot. In the 1950s an automobile fueling and service station was built on the west end of the site. In the 1980s the service station was demolished and since then the site has been used exclusively as a parking lot. 17th Street Development Corporation is the BCP Volunteer for this block/site only. The remainder of the former MGP site remains under the Con Edison Voluntary Cleanup Agreement. Site Geology and Hydrogeology: Between 50 and 80 feet of unconsolidated materials overlie schist bedrock at the site. The fill deepens significantly from east to west. Overburden consists of three distinct stratigraphic units. The top unit is fill, generally highly permeable, ranging from 13 to 45 feet thick. The upper 5 to 10 feet of fill contains significant man-made materials and the remnants of former structures and debris. Below that fill is mostly fine to medium or fine to coarse sand with trace brick, ash wood fibers and

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

concrete. Buried in the fill along the western border of the site is timber cribbing that formed the shoreline and bulkhead at one time. Below the fill is a Silty-Clay Unit which forms a low permeability aquitard. Water and other liquids such as coal tar do not readily pass through this layer. It varies in thickness from 40 feet to as little as 2 feet. Below the Silty-Clay Unit is the Sand Unit, a moderately permeable aquifer ranging from 20 to 40 feet thick. Permeability is far greater in a horizontal direction than vertical. The water table is located approximately 9 feet bgs and is nearly flat. Flow is generally toward the Hudson River to the west. In some areas, groundwater flow is influenced by man-made factors such as the Hudson River bulkhead, sheet pile walls, utilities, and by various man-made flows such as leaking water lines, drains, sewers, and building dewatering systems."

Env Problem: "Nature and Extent of Contamination: Remediation, which is complete, was a combination of shallow excavation and removal between 3 and 7 feet over the entire site, in-situ solidification of the middle third of the site, and containment with the installation of a sealed sheet pile wall keyed into a confining clay-silt layer in the western third of the site. Remaining behind are: 1) very minor contamination under the High Line (eastern part of the site), inaccessible due to extensive High Line foundations and 2) significant mobile tar contained by the sheet pile wall and the underlying confining clay-silt layer. In this western third of the site, coal tar continues to slowly accumulate and is collected from 4 collection wells and removed from the site. Special Resources Impacted/Threatened: Before the remediation, which cut off any offsite migration of contaminants via groundwater, manufactured gas plant (MGP) contamination appears to have migrated from this property primarily to the north and west, but has not been observed in the Hudson River 160 feet to the west of the site. Off-site groundwater and/or soil gas contamination will be addressed as part of the overall remedy for the larger West 18th Street MGP site. "

Health Problem: "People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by the site. Direct contact with contaminated soil is unlikely since it is located under pavement. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying or nearby buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Although no buildings currently occupy the site, future site development is likely to include at least one structure and the potential for soil vapor intrusion will be evaluated. Any concerns related to soil vapor intrusion in nearby buildings will be addressed under the voluntary agreement for the West 18th Street MGP Site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:44:41 / 73:59:58
Dell: False
Record Add: 2004-07-01 08:31:00

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Record Upd: 2014-12-09 10:57:00
Updated By: GWHEITZM
Own Op: 4
Sub Type: D
Owner Name: Laureen Weinshall
Owner Company: U.S. Drug Enforcement Administration, New York Division
Owner Address: 99 Tenth Avenue
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10011
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: John Shannon
Owner Company: 76 Eleventh Avenue Property Owner LLC
Owner Address: c/o HFZ Capital Group
Owner Addr2: 600 Madison Avenue, 15th Floor
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Scott M. Stringer
Owner Company: Office of Manhattan Borough President
Owner Address: One Centre Street
Owner Addr2: Municipal Building, 19th Floor South
Owner City,St,Zip: New York, NY 10007
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Theresa Mirhol
Owner Company: Mid-Manhattan Library
Owner Address: 455 Fifth Avenue
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10016
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: John Shannon
Owner Company: 76 Eleventh Avenue Property Owner LLC
Owner Address: c/o HFZ Capital Group
Owner Addr2: 600 Madison Ave, 15th Floor
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: John Flood
Owner Company: Hudson Park Branch Library
Owner Address: 66 Leroy Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10014-3929
Owner Country: United States of America
HW Code: C231036
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity: UNKNOWN

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Waste Code: Not reported
HW Code: C231036
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: Polycyclic Aromatic Hydrocarbons (PAHs), Total
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: v00248
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-02-01 14:48:00
Record Updated: 2008-02-01 14:48:00
Updated By: WSOTTAWA
Crossref ID: v00530
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-02-01 14:48:00
Record Updated: 2008-02-01 14:48:00
Updated By: WSOTTAWA
Crossref ID: C231036-12-10
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2014-12-04 16:49:00
Record Updated: 2014-12-04 16:49:00
Updated By: GWHEITZM
Crossref ID: 2014000399345
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-04 15:32:00
Record Updated: 2014-12-15 16:25:00
Updated By: RHDANA
Crossref ID: December 31, 2010
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2014-12-04 16:50:00
Record Updated: 2014-12-04 16:50:00
Updated By: GWHEITZM

Name: 17TH STREET DEVELOPMENT PROJECT
Address: 76 11TH AVENUE
City,State,Zip: NEW YORK, NY 10011
Site Code: 58929
Control Name: Site Management Plan

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

HW Code: C231036
Control Code: 32
Control Type: INST
Dt record added: 06/08/2012
Dt rec updated: 12/06/2019
Updated By: LSZINOMA
Site Code: 58929
Site Description: "Location: The 17th Street Development Project site encompasses the entire block between 17th and 18th Streets, and between 10th and 11th Avenues in the lower west side of Manhattan. Site Features: The site contains two residential towers with commercial space on the first floor and subsurface parking. The main distinguishing feature is a former elevated rail line that cuts across the eastern edge of the site, which was recently converted to use as a city park, High Line Park. Current Zoning/Use(s): This 1.75 acre site is currently zoned for commercial/residential. Surrounding Uses: The surrounding land use is historically commercial, but new residential development has been proceeding rapidly in recent years. Past Use of the Site: This site is one parcel in the larger Consolidated Edison W 18th Street Former Manufactured Gas Plant (MGP) site, ID No. V00530. Most of the gas making and purification facilities of the MGP were located on this parcel. Prior to its use as an Manufactured Gas Plant, the property experienced very little development, consisting of the construction of five houses which were torn down after about 20 years to make room for expansion of the MGP operations. The plant began distribution of coal gas in November 1834 and operated continuously until it shut down in 1901 or 1902. In 1932, the railroad acquired the property. Some of the buildings were razed and a rail yard was built. The remaining buildings were used for other uses. Later, the tracks were removed, the remaining buildings razed and the site used as a parking lot. In the 1950s an automobile fueling and service station was built on the west end of the site. In the 1980s the service station was demolished and since then the site has been used exclusively as a parking lot. 17th Street Development Corporation is the BCP Volunteer for this block/site only. The remainder of the former MGP site remains under the Con Edison Voluntary Cleanup Agreement. Site Geology and Hydrogeology: Between 50 and 80 feet of unconsolidated materials overlie schist bedrock at the site. The fill deepens significantly from east to west. Overburden consists of three distinct stratigraphic units. The top unit is fill, generally highly permeable, ranging from 13 to 45 feet thick. The upper 5 to 10 feet of fill contains significant man-made materials and the remnants of former structures and debris. Below that fill is mostly fine to medium or fine to coarse sand with trace brick, ash wood fibers and concrete. Buried in the fill along the western border of the site is timber cribbing that formed the shoreline and bulkhead at one time. Below the fill is a Silty-Clay Unit which forms a low permeability aquitard. Water and other liquids such as coal tar do not readily pass through this layer. It varies in thickness from 40 feet to as little as 2 feet. Below the Silty-Clay Unit is the Sand Unit, a moderately permeable aquifer ranging from 20 to 40 feet thick. Permeability is far greater in a horizontal direction than vertical. The water table is located approximately 9 feet bgs and is nearly flat. Flow is generally toward the Hudson River to the west. In some areas, groundwater flow is influenced by man-made factors such as the Hudson River bulkhead, sheet pile walls, utilities, and by various man-made flows such as leaking water lines, drains, sewers, and

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

building dewatering systems."

Env Problem: "Nature and Extent of Contamination: Remediation, which is complete, was a combination of shallow excavation and removal between 3 and 7 feet over the entire site, in-situ solidification of the middle third of the site, and containment with the installation of a sealed sheet pile wall keyed into a confining clay-silt layer in the western third of the site. Remaining behind are: 1) very minor contamination under the High Line (eastern part of the site), inaccessible due to extensive High Line foundations and 2) significant mobile tar contained by the sheet pile wall and the underlying confining clay-silt layer. In this western third of the site, coal tar continues to slowly accumulate and is collected from 4 collection wells and removed from the site. Special Resources Impacted/Threatened: Before the remediation, which cut off any offsite migration of contaminants via groundwater, manufactured gas plant (MGP) contamination appears to have migrated from this property primarily to the north and west, but has not been observed in the Hudson River 160 feet to the west of the site. Off-site groundwater and/or soil gas contamination will be addressed as part of the overall remedy for the larger West 18th Street MGP site. "

Health Problem: "People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by the site. Direct contact with contaminated soil is unlikely since it is located under pavement. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying or nearby buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Although no buildings currently occupy the site, future site development is likely to include at least one structure and the potential for soil vapor intrusion will be evaluated. Any concerns related to soil vapor intrusion in nearby buildings will be addressed under the voluntary agreement for the West 18th Street MGP Site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:44:41 / 73:59:58
Dell: False
Record Add: 2004-07-01 08:31:00
Record Upd: 2014-12-09 10:57:00
Updated By: GWHEITZM
Own Op: 4
Sub Type: D
Owner Name: Laureen Weinshall
Owner Company: U.S. Drug Enforcement Administration, New York Division
Owner Address: 99 Tenth Avenue
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10011
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: John Shannon

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Owner Company: 76 Eleventh Avenue Property Owner LLC
Owner Address: c/o HFZ Capital Group
Owner Addr2: 600 Madison Avenue, 15th Floor
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Scott M. Stringer
Owner Company: Office of Manhattan Borough President
Owner Address: One Centre Street
Owner Addr2: Municipal Building, 19th Floor South
Owner City,St,Zip: New York, NY 10007
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Theresa Mirhol
Owner Company: Mid-Manhattan Library
Owner Address: 455 Fifth Avenue
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10016
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: John Shannon
Owner Company: 76 Eleventh Avenue Property Owner LLC
Owner Address: c/o HFZ Capital Group
Owner Addr2: 600 Madison Ave, 15th Floor
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: John Flood
Owner Company: Hudson Park Branch Library
Owner Address: 66 Leroy Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10014-3929
Owner Country: United States of America
HW Code: C231036
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

HW Code: C231036
Waste Type: benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: Polycyclic Aromatic Hydrocarbons (PAHs), Total
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: v00248
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-02-01 14:48:00
Record Updated: 2008-02-01 14:48:00
Updated By: WSOTTAWA
Crossref ID: v00530
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-02-01 14:48:00
Record Updated: 2008-02-01 14:48:00
Updated By: WSOTTAWA
Crossref ID: C231036-12-10
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2014-12-04 16:49:00
Record Updated: 2014-12-04 16:49:00
Updated By: GWHEITZM
Crossref ID: 2014000399345
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-04 15:32:00
Record Updated: 2014-12-15 16:25:00
Updated By: RHDANA
Crossref ID: December 31, 2010
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2014-12-04 16:50:00
Record Updated: 2014-12-04 16:50:00
Updated By: GWHEITZM

Name: 17TH STREET DEVELOPMENT PROJECT
Address: 76 11TH AVENUE
City,State,Zip: NEW YORK, NY 10011
Site Code: 58929
Control Name: O&M Plan
HW Code: C231036
Control Code: 33
Control Type: INST
Dt record added: 06/08/2012
Dt rec updated: 12/06/2019
Updated By: LSZINOMA
Site Code: 58929
Site Description: "Location: The 17th Street Development Project site encompasses the entire block between 17th and 18th Streets, and between 10th and 11th Avenues in the lower west side of Manhattan. Site Features: The site contains two residential towers with commercial space on the first floor and subsurface parking. The main distinguishing feature is a former elevated rail line that cuts across the eastern edge of the

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

site, which was recently converted to use as a city park, High Line Park. Current Zoning/Use(s): This 1.75 acre site is currently zoned for commercial/residential. Surrounding Uses: The surrounding land use is historically commercial, but new residential development has been proceeding rapidly in recent years. Past Use of the Site: This site is one parcel in the larger Consolidated Edison W 18th Street Former Manufactured Gas Plant (MGP) site, ID No. V00530. Most of the gas making and purification facilities of the MGP were located on this parcel. Prior to its use as an Manufactured Gas Plant, the property experienced very little development, consisting of the construction of five houses which were torn down after about 20 years to make room for expansion of the MGP operations. The plant began distribution of coal gas in November 1834 and operated continuously until it shut down in 1901 or 1902. In 1932, the railroad acquired the property. Some of the buildings were razed and a rail yard was built. The remaining buildings were used for other uses. Later, the tracks were removed, the remaining buildings razed and the site used as a parking lot. In the 1950s an automobile fueling and service station was built on the west end of the site. In the 1980s the service station was demolished and since then the site has been used exclusively as a parking lot. 17th Street Development Corporation is the BCP Volunteer for this block/site only. The remainder of the former MGP site remains under the Con Edison Voluntary Cleanup Agreement. Site Geology and Hydrogeology: Between 50 and 80 feet of unconsolidated materials overlie schist bedrock at the site. The fill deepens significantly from east to west. Overburden consists of three distinct stratigraphic units. The top unit is fill, generally highly permeable, ranging from 13 to 45 feet thick. The upper 5 to 10 feet of fill contains significant man-made materials and the remnants of former structures and debris. Below that fill is mostly fine to medium or fine to coarse sand with trace brick, ash wood fibers and concrete. Buried in the fill along the western border of the site is timber cribbing that formed the shoreline and bulkhead at one time. Below the fill is a Silty-Clay Unit which forms a low permeability aquitard. Water and other liquids such as coal tar do not readily pass through this layer. It varies in thickness from 40 feet to as little as 2 feet. Below the Silty-Clay Unit is the Sand Unit, a moderately permeable aquifer ranging from 20 to 40 feet thick. Permeability is far greater in a horizontal direction than vertical. The water table is located approximately 9 feet bgs and is nearly flat. Flow is generally toward the Hudson River to the west. In some areas, groundwater flow is influenced by man-made factors such as the Hudson River bulkhead, sheet pile walls, utilities, and by various man-made flows such as leaking water lines, drains, sewers, and building dewatering systems."

Env Problem: "Nature and Extent of Contamination: Remediation, which is complete, was a combination of shallow excavation and removal between 3 and 7 feet over the entire site, in-situ solidification of the middle third of the site, and containment with the installation of a sealed sheet pile wall keyed into a confining clay-silt layer in the western third of the site. Remaining behind are: 1) very minor contamination under the High Line (eastern part of the site), inaccessible due to extensive High Line foundations and 2) significant mobile tar contained by the sheet pile wall and the underlying confining clay-silt layer. In this western third of the site, coal tar continues to slowly accumulate and is collected from 4 collection wells and removed from the site. Special Resources

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Impacted/Threatened: Before the remediation, which cut off any offsite migration of contaminants via groundwater, manufactured gas plant (MGP) contamination appears to have migrated from this property primarily to the north and west, but has not been observed in the Hudson River 160 feet to the west of the site. Off-site groundwater and/or soil gas contamination will be addressed as part of the overall remedy for the larger West 18th Street MGP site. "

Health Problem: "People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by the site. Direct contact with contaminated soil is unlikely since it is located under pavement. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying or nearby buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Although no buildings currently occupy the site, future site development is likely to include at least one structure and the potential for soil vapor intrusion will be evaluated. Any concerns related to soil vapor intrusion in nearby buildings will be addressed under the voluntary agreement for the West 18th Street MGP Site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:44:41 / 73:59:58
Dell: False
Record Add: 2004-07-01 08:31:00
Record Upd: 2014-12-09 10:57:00
Updated By: GWHEITZM
Own Op: 4
Sub Type: D
Owner Name: Laureen Weinshall
Owner Company: U.S. Drug Enforcement Administration, New York Division
Owner Address: 99 Tenth Avenue
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10011
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: John Shannon
Owner Company: 76 Eleventh Avenue Property Owner LLC
Owner Address: c/o HFZ Capital Group
Owner Addr2: 600 Madison Avenue, 15th Floor
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Scott M. Stringer
Owner Company: Office of Manhattan Borough President
Owner Address: One Centre Street
Owner Addr2: Municipal Building, 19th Floor South
Owner City,St,Zip: New York, NY 10007
Owner Country: United States of America

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Own Op: Document Repository
Sub Type: NNN
Owner Name: Theresa Mirhol
Owner Company: Mid-Manhattan Library
Owner Address: 455 Fifth Avenue
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10016
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: John Shannon
Owner Company: 76 Eleventh Avenue Property Owner LLC
Owner Address: c/o HFZ Capital Group
Owner Addr2: 600 Madison Ave, 15th Floor
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: John Flood
Owner Company: Hudson Park Branch Library
Owner Address: 66 Leroy Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10014-3929
Owner Country: United States of America
HW Code: C231036
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: Polycyclic Aromatic Hydrocarbons (PAHs), Total
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: v00248
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-02-01 14:48:00
Record Updated: 2008-02-01 14:48:00

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Updated By: WSOTTAWA
Crossref ID: v00530
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-02-01 14:48:00
Record Updated: 2008-02-01 14:48:00
Updated By: WSOTTAWA
Crossref ID: C231036-12-10
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2014-12-04 16:49:00
Record Updated: 2014-12-04 16:49:00
Updated By: GWHEITZM
Crossref ID: 2014000399345
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-04 15:32:00
Record Updated: 2014-12-15 16:25:00
Updated By: RHDANA
Crossref ID: December 31, 2010
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2014-12-04 16:50:00
Record Updated: 2014-12-04 16:50:00
Updated By: GWHEITZM

Name: 17TH STREET DEVELOPMENT PROJECT
Address: 76 11TH AVENUE
City,State,Zip: NEW YORK, NY 10011
Site Code: 58929
Control Name: Landuse Restriction
HW Code: C231036
Control Code: 25
Control Type: INST
Dt record added: 06/08/2012
Dt rec updated: 12/06/2019
Updated By: LSZINOMA
Site Code: 58929
Site Description: "Location: The 17th Street Development Project site encompasses the entire block between 17th and 18th Streets, and between 10th and 11th Avenues in the lower west side of Manhattan. Site Features: The site contains two residential towers with commercial space on the first floor and subsurface parking. The main distinguishing feature is a former elevated rail line that cuts across the eastern edge of the site, which was recently converted to use as a city park, High Line Park. Current Zoning/Use(s): This 1.75 acre site is currently zoned for commercial/residential. Surrounding Uses: The surrounding land use is historically commercial, but new residential development has been proceeding rapidly in recent years. Past Use of the Site: This site is one parcel in the larger Consolidated Edison W 18th Street Former Manufactured Gas Plant (MGP) site, ID No. V00530. Most of the gas making and purification facilities of the MGP were located on this parcel. Prior to its use as an Manufactured Gas Plant, the property experienced very little development, consisting of the construction of five houses which were torn down after about 20 years to make room for expansion of the MGP operations. The plant began distribution of coal gas in November 1834 and operated continuously

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

until it shut down in 1901 or 1902. In 1932, the railroad acquired the property. Some of the buildings were razed and a rail yard was built. The remaining buildings were used for other uses. Later, the tracks were removed, the remaining buildings razed and the site used as a parking lot. In the 1950s an automobile fueling and service station was built on the west end of the site. In the 1980s the service station was demolished and since then the site has been used exclusively as a parking lot. 17th Street Development Corporation is the BCP Volunteer for this block/site only. The remainder of the former MGP site remains under the Con Edison Voluntary Cleanup Agreement. Site Geology and Hydrogeology: Between 50 and 80 feet of unconsolidated materials overlie schist bedrock at the site. The fill deepens significantly from east to west. Overburden consists of three distinct stratigraphic units. The top unit is fill, generally highly permeable, ranging from 13 to 45 feet thick. The upper 5 to 10 feet of fill contains significant man-made materials and the remnants of former structures and debris. Below that fill is mostly fine to medium or fine to coarse sand with trace brick, ash wood fibers and concrete. Buried in the fill along the western border of the site is timber cribbing that formed the shoreline and bulkhead at one time. Below the fill is a Silty-Clay Unit which forms a low permeability aquitard. Water and other liquids such as coal tar do not readily pass through this layer. It varies in thickness from 40 feet to as little as 2 feet. Below the Silty-Clay Unit is the Sand Unit, a moderately permeable aquifer ranging from 20 to 40 feet thick. Permeability is far greater in a horizontal direction than vertical. The water table is located approximately 9 feet bgs and is nearly flat. Flow is generally toward the Hudson River to the west. In some areas, groundwater flow is influenced by man-made factors such as the Hudson River bulkhead, sheet pile walls, utilities, and by various man-made flows such as leaking water lines, drains, sewers, and building dewatering systems."

Env Problem: "Nature and Extent of Contamination: Remediation, which is complete, was a combination of shallow excavation and removal between 3 and 7 feet over the entire site, in-situ solidification of the middle third of the site, and containment with the installation of a sealed sheet pile wall keyed into a confining clay-silt layer in the western third of the site. Remaining behind are: 1) very minor contamination under the High Line (eastern part of the site), inaccessible due to extensive High Line foundations and 2) significant mobile tar contained by the sheet pile wall and the underlying confining clay-silt layer. In this western third of the site, coal tar continues to slowly accumulate and is collected from 4 collection wells and removed from the site. Special Resources Impacted/Threatened: Before the remediation, which cut off any offsite migration of contaminants via groundwater, manufactured gas plant (MGP) contamination appears to have migrated from this property primarily to the north and west, but has not been observed in the Hudson River 160 feet to the west of the site. Off-site groundwater and/or soil gas contamination will be addressed as part of the overall remedy for the larger West 18th Street MGP site. "

Health Problem: "People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by the site. Direct contact with contaminated soil is unlikely since it is located under pavement. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying or nearby

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Although no buildings currently occupy the site, future site development is likely to include at least one structure and the potential for soil vapor intrusion will be evaluated. Any concerns related to soil vapor intrusion in nearby buildings will be addressed under the voluntary agreement for the West 18th Street MGP Site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:44:41 / 73:59:58
Dell: False
Record Add: 2004-07-01 08:31:00
Record Upd: 2014-12-09 10:57:00
Updated By: GWHEITZM
Own Op: 4
Sub Type: D
Owner Name: Laureen Weinshall
Owner Company: U.S. Drug Enforcement Administration, New York Division
Owner Address: 99 Tenth Avenue
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10011
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: John Shannon
Owner Company: 76 Eleventh Avenue Property Owner LLC
Owner Address: c/o HFZ Capital Group
Owner Addr2: 600 Madison Avenue, 15th Floor
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Scott M. Stringer
Owner Company: Office of Manhattan Borough President
Owner Address: One Centre Street
Owner Addr2: Municipal Building, 19th Floor South
Owner City,St,Zip: New York, NY 10007
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Theresa Mirhol
Owner Company: Mid-Manhattan Library
Owner Address: 455 Fifth Avenue
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10016
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: John Shannon
Owner Company: 76 Eleventh Avenue Property Owner LLC
Owner Address: c/o HFZ Capital Group

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Owner Addr2: 600 Madison Ave, 15th Floor
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: John Flood
Owner Company: Hudson Park Branch Library
Owner Address: 66 Leroy Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10014-3929
Owner Country: United States of America
HW Code: C231036
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: Polycyclic Aromatic Hydrocarbons (PAHs), Total
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: v00248
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-02-01 14:48:00
Record Updated: 2008-02-01 14:48:00
Updated By: WSOTTAWA
Crossref ID: v00530
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-02-01 14:48:00
Record Updated: 2008-02-01 14:48:00
Updated By: WSOTTAWA
Crossref ID: C231036-12-10
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2014-12-04 16:49:00
Record Updated: 2014-12-04 16:49:00
Updated By: GWHEITZM

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Crossref ID: 2014000399345
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-04 15:32:00
Record Updated: 2014-12-15 16:25:00
Updated By: RHDANA
Crossref ID: December 31, 2010
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2014-12-04 16:50:00
Record Updated: 2014-12-04 16:50:00
Updated By: GWHEITZM

Name: 17TH STREET DEVELOPMENT PROJECT
Address: 76 11TH AVENUE
City,State,Zip: NEW YORK, NY 10011
Site Code: 58929
Control Name: Monitoring Plan
HW Code: C231036
Control Code: 31
Control Type: INST
Dt record added: 06/08/2012
Dt rec updated: 12/06/2019
Updated By: LSZINOMA
Site Code: 58929
Site Description: "Location: The 17th Street Development Project site encompasses the entire block between 17th and 18th Streets, and between 10th and 11th Avenues in the lower west side of Manhattan. Site Features: The site contains two residential towers with commercial space on the first floor and subsurface parking. The main distinguishing feature is a former elevated rail line that cuts across the eastern edge of the site, which was recently converted to use as a city park, High Line Park. Current Zoning/Use(s): This 1.75 acre site is currently zoned for commercial/residential. Surrounding Uses: The surrounding land use is historically commercial, but new residential development has been proceeding rapidly in recent years. Past Use of the Site: This site is one parcel in the larger Consolidated Edison W 18th Street Former Manufactured Gas Plant (MGP) site, ID No. V00530. Most of the gas making and purification facilities of the MGP were located on this parcel. Prior to its use as an Manufactured Gas Plant, the property experienced very little development, consisting of the construction of five houses which were torn down after about 20 years to make room for expansion of the MGP operations. The plant began distribution of coal gas in November 1834 and operated continuously until it shut down in 1901 or 1902. In 1932, the railroad acquired the property. Some of the buildings were razed and a rail yard was built. The remaining buildings were used for other uses. Later, the tracks were removed, the remaining buildings razed and the site used as a parking lot. In the 1950s an automobile fueling and service station was built on the west end of the site. In the 1980s the service station was demolished and since then the site has been used exclusively as a parking lot. 17th Street Development Corporation is the BCP Volunteer for this block/site only. The remainder of the former MGP site remains under the Con Edison Voluntary Cleanup Agreement. Site Geology and Hydrogeology: Between 50 and 80 feet of unconsolidated materials overlie schist bedrock at the site. The fill deepens significantly from east to west. Overburden consists of three

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

distinct stratigraphic units. The top unit is fill, generally highly permeable, ranging from 13 to 45 feet thick. The upper 5 to 10 feet of fill contains significant man-made materials and the remnants of former structures and debris. Below that fill is mostly fine to medium or fine to coarse sand with trace brick, ash wood fibers and concrete. Buried in the fill along the western border of the site is timber cribbing that formed the shoreline and bulkhead at one time. Below the fill is a Silty-Clay Unit which forms a low permeability aquitard. Water and other liquids such as coal tar do not readily pass through this layer. It varies in thickness from 40 feet to as little as 2 feet. Below the Silty-Clay Unit is the Sand Unit, a moderately permeable aquifer ranging from 20 to 40 feet thick. Permeability is far greater in a horizontal direction than vertical. The water table is located approximately 9 feet bgs and is nearly flat. Flow is generally toward the Hudson River to the west. In some areas, groundwater flow is influenced by man-made factors such as the Hudson River bulkhead, sheet pile walls, utilities, and by various man-made flows such as leaking water lines, drains, sewers, and building dewatering systems."

Env Problem: "Nature and Extent of Contamination: Remediation, which is complete, was a combination of shallow excavation and removal between 3 and 7 feet over the entire site, in-situ solidification of the middle third of the site, and containment with the installation of a sealed sheet pile wall keyed into a confining clay-silt layer in the western third of the site. Remaining behind are: 1) very minor contamination under the High Line (eastern part of the site), inaccessible due to extensive High Line foundations and 2) significant mobile tar contained by the sheet pile wall and the underlying confining clay-silt layer. In this western third of the site, coal tar continues to slowly accumulate and is collected from 4 collection wells and removed from the site. Special Resources Impacted/Threatened: Before the remediation, which cut off any offsite migration of contaminants via groundwater, manufactured gas plant (MGP) contamination appears to have migrated from this property primarily to the north and west, but has not been observed in the Hudson River 160 feet to the west of the site. Off-site groundwater and/or soil gas contamination will be addressed as part of the overall remedy for the larger West 18th Street MGP site. "

Health Problem: "People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by the site. Direct contact with contaminated soil is unlikely since it is located under pavement. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying or nearby buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Although no buildings currently occupy the site, future site development is likely to include at least one structure and the potential for soil vapor intrusion will be evaluated. Any concerns related to soil vapor intrusion in nearby buildings will be addressed under the voluntary agreement for the West 18th Street MGP Site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:44:41 / 73:59:58
Dell: False
Record Add: 2004-07-01 08:31:00
Record Upd: 2014-12-09 10:57:00
Updated By: GWHEITZM
Own Op: 4
Sub Type: D
Owner Name: Laureen Weinshall
Owner Company: U.S. Drug Enforcement Administration, New York Division
Owner Address: 99 Tenth Avenue
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10011
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: John Shannon
Owner Company: 76 Eleventh Avenue Property Owner LLC
Owner Address: c/o HFZ Capital Group
Owner Addr2: 600 Madison Avenue, 15th Floor
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Scott M. Stringer
Owner Company: Office of Manhattan Borough President
Owner Address: One Centre Street
Owner Addr2: Municipal Building, 19th Floor South
Owner City,St,Zip: New York, NY 10007
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Theresa Mirhol
Owner Company: Mid-Manhattan Library
Owner Address: 455 Fifth Avenue
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10016
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: John Shannon
Owner Company: 76 Eleventh Avenue Property Owner LLC
Owner Address: c/o HFZ Capital Group
Owner Addr2: 600 Madison Ave, 15th Floor
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: John Flood
Owner Company: Hudson Park Branch Library
Owner Address: 66 Leroy Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10014-3929
Owner Country: United States of America
HW Code: C231036
Waste Type: MERCURY

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: Polycyclic Aromatic Hydrocarbons (PAHs), Total
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: v00248
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-02-01 14:48:00
Record Updated: 2008-02-01 14:48:00
Updated By: WSOTTAWA
Crossref ID: v00530
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-02-01 14:48:00
Record Updated: 2008-02-01 14:48:00
Updated By: WSOTTAWA
Crossref ID: C231036-12-10
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2014-12-04 16:49:00
Record Updated: 2014-12-04 16:49:00
Updated By: GWHEITZM
Crossref ID: 2014000399345
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-04 15:32:00
Record Updated: 2014-12-15 16:25:00
Updated By: RHDANA
Crossref ID: December 31, 2010
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2014-12-04 16:50:00
Record Updated: 2014-12-04 16:50:00
Updated By: GWHEITZM

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Name: 17TH STREET DEVELOPMENT PROJECT
Address: 76 11TH AVENUE
City,State,Zip: NEW YORK, NY 10011
Site Code: 58929
Control Name: Environmental Easement
HW Code: C231036
Control Code: J
Control Type: INST
Dt record added: 06/08/2012
Dt rec updated: 12/06/2019
Updated By: LSZINOMA
Site Code: 58929
Site Description: "Location: The 17th Street Development Project site encompasses the entire block between 17th and 18th Streets, and between 10th and 11th Avenues in the lower west side of Manhattan. Site Features: The site contains two residential towers with commercial space on the first floor and subsurface parking. The main distinguishing feature is a former elevated rail line that cuts across the eastern edge of the site, which was recently converted to use as a city park, High Line Park. Current Zoning/Use(s): This 1.75 acre site is currently zoned for commercial/residential. Surrounding Uses: The surrounding land use is historically commercial, but new residential development has been proceeding rapidly in recent years. Past Use of the Site: This site is one parcel in the larger Consolidated Edison W 18th Street Former Manufactured Gas Plant (MGP) site, ID No. V00530. Most of the gas making and purification facilities of the MGP were located on this parcel. Prior to its use as an Manufactured Gas Plant, the property experienced very little development, consisting of the construction of five houses which were torn down after about 20 years to make room for expansion of the MGP operations. The plant began distribution of coal gas in November 1834 and operated continuously until it shut down in 1901 or 1902. In 1932, the railroad acquired the property. Some of the buildings were razed and a rail yard was built. The remaining buildings were used for other uses. Later, the tracks were removed, the remaining buildings razed and the site used as a parking lot. In the 1950s an automobile fueling and service station was built on the west end of the site. In the 1980s the service station was demolished and since then the site has been used exclusively as a parking lot. 17th Street Development Corporation is the BCP Volunteer for this block/site only. The remainder of the former MGP site remains under the Con Edison Voluntary Cleanup Agreement. Site Geology and Hydrogeology: Between 50 and 80 feet of unconsolidated materials overlie schist bedrock at the site. The fill deepens significantly from east to west. Overburden consists of three distinct stratigraphic units. The top unit is fill, generally highly permeable, ranging from 13 to 45 feet thick. The upper 5 to 10 feet of fill contains significant man-made materials and the remnants of former structures and debris. Below that fill is mostly fine to medium or fine to coarse sand with trace brick, ash wood fibers and concrete. Buried in the fill along the western border of the site is timber cribbing that formed the shoreline and bulkhead at one time. Below the fill is a Silty-Clay Unit which forms a low permeability aquitard. Water and other liquids such as coal tar do not readily pass through this layer. It varies in thickness from 40 feet to as little as 2 feet. Below the Silty-Clay Unit is the Sand Unit, a moderately permeable aquifer ranging from 20 to 40 feet thick. Permeability is far greater in a horizontal direction than vertical.

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

The water table is located approximately 9 feet bgs and is nearly flat. Flow is generally toward the Hudson River to the west. In some areas, groundwater flow is influenced by man-made factors such as the Hudson River bulkhead, sheet pile walls, utilities, and by various man-made flows such as leaking water lines, drains, sewers, and building dewatering systems."

Env Problem: "Nature and Extent of Contamination: Remediation, which is complete, was a combination of shallow excavation and removal between 3 and 7 feet over the entire site, in-situ solidification of the middle third of the site, and containment with the installation of a sealed sheet pile wall keyed into a confining clay-silt layer in the western third of the site. Remaining behind are: 1) very minor contamination under the High Line (eastern part of the site), inaccessible due to extensive High Line foundations and 2) significant mobile tar contained by the sheet pile wall and the underlying confining clay-silt layer. In this western third of the site, coal tar continues to slowly accumulate and is collected from 4 collection wells and removed from the site. Special Resources Impacted/Threatened: Before the remediation, which cut off any offsite migration of contaminants via groundwater, manufactured gas plant (MGP) contamination appears to have migrated from this property primarily to the north and west, but has not been observed in the Hudson River 160 feet to the west of the site. Off-site groundwater and/or soil gas contamination will be addressed as part of the overall remedy for the larger West 18th Street MGP site. "

Health Problem: "People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by the site. Direct contact with contaminated soil is unlikely since it is located under pavement. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying or nearby buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Although no buildings currently occupy the site, future site development is likely to include at least one structure and the potential for soil vapor intrusion will be evaluated. Any concerns related to soil vapor intrusion in nearby buildings will be addressed under the voluntary agreement for the West 18th Street MGP Site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:44:41 / 73:59:58
Dell: False
Record Add: 2004-07-01 08:31:00
Record Upd: 2014-12-09 10:57:00
Updated By: GWHEITZM
Own Op: 4
Sub Type: D
Owner Name: Laureen Weinshall
Owner Company: U.S. Drug Enforcement Administration, New York Division
Owner Address: 99 Tenth Avenue
Owner Addr2: Not reported

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Owner City,St,Zip: New York, NY 10011
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: John Shannon
Owner Company: 76 Eleventh Avenue Property Owner LLC
Owner Address: c/o HFZ Capital Group
Owner Addr2: 600 Madison Avenue, 15th Floor
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Scott M. Stringer
Owner Company: Office of Manhattan Borough President
Owner Address: One Centre Street
Owner Addr2: Municipal Building, 19th Floor South
Owner City,St,Zip: New York, NY 10007
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Theresa Mirhol
Owner Company: Mid-Manhattan Library
Owner Address: 455 Fifth Avenue
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10016
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: John Shannon
Owner Company: 76 Eleventh Avenue Property Owner LLC
Owner Address: c/o HFZ Capital Group
Owner Addr2: 600 Madison Ave, 15th Floor
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: John Flood
Owner Company: Hudson Park Branch Library
Owner Address: 66 Leroy Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10014-3929
Owner Country: United States of America
HW Code: C231036
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: ARSENIC
Waste Quantity: UNKNOWN

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Waste Code: Not reported
HW Code: C231036
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: Polycyclic Aromatic Hydrocarbons (PAHs), Total
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: v00248
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-02-01 14:48:00
Record Updated: 2008-02-01 14:48:00
Updated By: WSOTTAWA
Crossref ID: v00530
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-02-01 14:48:00
Record Updated: 2008-02-01 14:48:00
Updated By: WSOTTAWA
Crossref ID: C231036-12-10
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2014-12-04 16:49:00
Record Updated: 2014-12-04 16:49:00
Updated By: GWHEITZM
Crossref ID: 2014000399345
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-04 15:32:00
Record Updated: 2014-12-15 16:25:00
Updated By: RHDANA
Crossref ID: December 31, 2010
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2014-12-04 16:50:00
Record Updated: 2014-12-04 16:50:00
Updated By: GWHEITZM

Name: 17TH STREET DEVELOPMENT PROJECT
Address: 76 11TH AVENUE
City,State,Zip: NEW YORK, NY 10011
Site Code: 58929
Control Name: IC/EC Plan
HW Code: C231036
Control Code: 34
Control Type: INST
Dt record added: 06/08/2012
Dt rec updated: 12/06/2019
Updated By: LSZINOMA
Site Code: 58929
Site Description: "Location: The 17th Street Development Project site encompasses the

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

entire block between 17th and 18th Streets, and between 10th and 11th Avenues in the lower west side of Manhattan. Site Features: The site contains two residential towers with commercial space on the first floor and subsurface parking. The main distinguishing feature is a former elevated rail line that cuts across the eastern edge of the site, which was recently converted to use as a city park, High Line Park. Current Zoning/Use(s): This 1.75 acre site is currently zoned for commercial/residential. Surrounding Uses: The surrounding land use is historically commercial, but new residential development has been proceeding rapidly in recent years. Past Use of the Site: This site is one parcel in the larger Consolidated Edison W 18th Street Former Manufactured Gas Plant (MGP) site, ID No. V00530. Most of the gas making and purification facilities of the MGP were located on this parcel. Prior to its use as an Manufactured Gas Plant, the property experienced very little development, consisting of the construction of five houses which were torn down after about 20 years to make room for expansion of the MGP operations. The plant began distribution of coal gas in November 1834 and operated continuously until it shut down in 1901 or 1902. In 1932, the railroad acquired the property. Some of the buildings were razed and a rail yard was built. The remaining buildings were used for other uses. Later, the tracks were removed, the remaining buildings razed and the site used as a parking lot. In the 1950s an automobile fueling and service station was built on the west end of the site. In the 1980s the service station was demolished and since then the site has been used exclusively as a parking lot. 17th Street Development Corporation is the BCP Volunteer for this block/site only. The remainder of the former MGP site remains under the Con Edison Voluntary Cleanup Agreement. Site Geology and Hydrogeology: Between 50 and 80 feet of unconsolidated materials overlie schist bedrock at the site. The fill deepens significantly from east to west. Overburden consists of three distinct stratigraphic units. The top unit is fill, generally highly permeable, ranging from 13 to 45 feet thick. The upper 5 to 10 feet of fill contains significant man-made materials and the remnants of former structures and debris. Below that fill is mostly fine to medium or fine to coarse sand with trace brick, ash wood fibers and concrete. Buried in the fill along the western border of the site is timber cribbing that formed the shoreline and bulkhead at one time. Below the fill is a Silty-Clay Unit which forms a low permeability aquitard. Water and other liquids such as coal tar do not readily pass through this layer. It varies in thickness from 40 feet to as little as 2 feet. Below the Silty-Clay Unit is the Sand Unit, a moderately permeable aquifer ranging from 20 to 40 feet thick. Permeability is far greater in a horizontal direction than vertical. The water table is located approximately 9 feet bgs and is nearly flat. Flow is generally toward the Hudson River to the west. In some areas, groundwater flow is influenced by man-made factors such as the Hudson River bulkhead, sheet pile walls, utilities, and by various man-made flows such as leaking water lines, drains, sewers, and building dewatering systems."

Env Problem: "Nature and Extent of Contamination: Remediation, which is complete, was a combination of shallow excavation and removal between 3 and 7 feet over the entire site, in-situ solidification of the middle third of the site, and containment with the installation of a sealed sheet pile wall keyed into a confining clay-silt layer in the western third of the site. Remaining behind are: 1) very minor contamination under the High Line (eastern part of the site), inaccessible due to

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

extensive High Line foundations and 2) significant mobile tar contained by the sheet pile wall and the underlying confining clay-silt layer. In this western third of the site, coal tar continues to slowly accumulate and is collected from 4 collection wells and removed from the site. Special Resources Impacted/Threatened: Before the remediation, which cut off any offsite migration of contaminants via groundwater, manufactured gas plant (MGP) contamination appears to have migrated from this property primarily to the north and west, but has not been observed in the Hudson River 160 feet to the west of the site. Off-site groundwater and/or soil gas contamination will be addressed as part of the overall remedy for the larger West 18th Street MGP site. "

Health Problem: "People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by the site. Direct contact with contaminated soil is unlikely since it is located under pavement. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying or nearby buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Although no buildings currently occupy the site, future site development is likely to include at least one structure and the potential for soil vapor intrusion will be evaluated. Any concerns related to soil vapor intrusion in nearby buildings will be addressed under the voluntary agreement for the West 18th Street MGP Site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:44:41 / 73:59:58
Dell: False
Record Add: 2004-07-01 08:31:00
Record Upd: 2014-12-09 10:57:00
Updated By: GWHEITZM
Own Op: 4
Sub Type: D
Owner Name: Laureen Weinshall
Owner Company: U.S. Drug Enforcement Administration, New York Division
Owner Address: 99 Tenth Avenue
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10011
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: John Shannon
Owner Company: 76 Eleventh Avenue Property Owner LLC
Owner Address: c/o HFZ Capital Group
Owner Addr2: 600 Madison Avenue, 15th Floor
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Scott M. Stringer

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Owner Company: Office of Manhattan Borough President
Owner Address: One Centre Street
Owner Addr2: Municipal Building, 19th Floor South
Owner City,St,Zip: New York, NY 10007
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Theresa Mirhol
Owner Company: Mid-Manhattan Library
Owner Address: 455 Fifth Avenue
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10016
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: John Shannon
Owner Company: 76 Eleventh Avenue Property Owner LLC
Owner Address: c/o HFZ Capital Group
Owner Addr2: 600 Madison Ave, 15th Floor
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: John Flood
Owner Company: Hudson Park Branch Library
Owner Address: 66 Leroy Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10014-3929
Owner Country: United States of America
HW Code: C231036
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231036
Waste Type: Polycyclic Aromatic Hydrocarbons (PAHs), Total
Waste Quantity: UNKNOWN
Waste Code: Not reported

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Crossref ID: v00248
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-02-01 14:48:00
Record Updated: 2008-02-01 14:48:00
Updated By: WSOTTAWA
Crossref ID: v00530
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-02-01 14:48:00
Record Updated: 2008-02-01 14:48:00
Updated By: WSOTTAWA
Crossref ID: C231036-12-10
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2014-12-04 16:49:00
Record Updated: 2014-12-04 16:49:00
Updated By: GWHEITZM
Crossref ID: 2014000399345
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-04 15:32:00
Record Updated: 2014-12-15 16:25:00
Updated By: RHDANA
Crossref ID: December 31, 2010
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2014-12-04 16:50:00
Record Updated: 2014-12-04 16:50:00
Updated By: GWHEITZM

BROWNFIELDS:

Name:	17TH STREET DEVELOPMENT PROJECT
Address:	76 11TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Program:	BCP
Site Code:	58929
Acres:	1.750
HW Code:	C231036
SWIS:	3101
Town:	New York City
Record Added Date:	07/01/2004
Record Updated Date:	06/09/2021
Update By:	DJEATON
Site Description:	"Location: The 17th Street Development Project site encompasses the entire block between 17th and 18th Streets, and between 10th and 11th Avenues in the lower west side of Manhattan. Site Features: The site contains two residential towers with commercial space on the first floor and subsurface parking. The main distinguishing feature is a former elevated rail line that cuts across the eastern edge of the site, which was recently converted to use as a city park, High Line Park. Current Zoning/Use(s): This 1.75 acre site is currently zoned for commercial/residential. Surrounding Uses: The surrounding land use is historically commercial, but new residential development has been proceeding rapidly in recent years. Past Use of the Site: This site is one parcel in the larger Consolidated Edison W 18th Street Former Manufactured Gas Plant (MGP) site, ID No. V00530. Most of the

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

gas making and purification facilities of the MGP were located on this parcel. Prior to its use as an Manufactured Gas Plant, the property experienced very little development, consisting of the construction of five houses which were torn down after about 20 years to make room for expansion of the MGP operations. The plant began distribution of coal gas in November 1834 and operated continuously until it shut down in 1901 or 1902. In 1932, the railroad acquired the property. Some of the buildings were razed and a rail yard was built. The remaining buildings were used for other uses. Later, the tracks were removed, the remaining buildings razed and the site used as a parking lot. In the 1950s an automobile fueling and service station was built on the west end of the site. In the 1980s the service station was demolished and since then the site has been used exclusively as a parking lot. 17th Street Development Corporation is the BCP Volunteer for this block/site only. The remainder of the former MGP site remains under the Con Edison Voluntary Cleanup Agreement. Site Geology and Hydrogeology: Between 50 and 80 feet of unconsolidated materials overlie schist bedrock at the site. The fill deepens significantly from east to west. Overburden consists of three distinct stratigraphic units. The top unit is fill, generally highly permeable, ranging from 13 to 45 feet thick. The upper 5 to 10 feet of fill contains significant man-made materials and the remnants of former structures and debris. Below that fill is mostly fine to medium or fine to coarse sand with trace brick, ash wood fibers and concrete. Buried in the fill along the western border of the site is timber cribbing that formed the shoreline and bulkhead at one time. Below the fill is a Silty-Clay Unit which forms a low permeability aquitard. Water and other liquids such as coal tar do not readily pass through this layer. It varies in thickness from 40 feet to as little as 2 feet. Below the Silty-Clay Unit is the Sand Unit, a moderately permeable aquifer ranging from 20 to 40 feet thick. Permeability is far greater in a horizontal direction than vertical. The water table is located approximately 9 feet bgs and is nearly flat. Flow is generally toward the Hudson River to the west. In some areas, groundwater flow is influenced by man-made factors such as the Hudson River bulkhead, sheet pile walls, utilities, and by various man-made flows such as leaking water lines, drains, sewers, and building dewatering systems."

Env Problem:

"Nature and Extent of Contamination: Remediation, which is complete, was a combination of shallow excavation and removal between 3 and 7 feet over the entire site, in-situ solidification of the middle third of the site, and containment with the installation of a sealed sheet pile wall keyed into a confining clay-silt layer in the western third of the site. Remaining behind are: 1) very minor contamination under the High Line (eastern part of the site), inaccessible due to extensive High Line foundations and 2) significant mobile tar contained by the sheet pile wall and the underlying confining clay-silt layer. In this western third of the site, coal tar continues to slowly accumulate and is collected from 4 collection wells and removed from the site. Special Resources Impacted/Threatened: Before the remediation, which cut off any offsite migration of contaminants via groundwater, manufactured gas plant (MGP) contamination appears to have migrated from this property primarily to the north and west, but has not been observed in the Hudson River 160 feet to the west of the site. Off-site groundwater and/or soil gas contamination will be addressed as part of the overall remedy for the larger West 18th Street MGP site. "

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Health Problem:	"People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by the site. Direct contact with contaminated soil is unlikely since it is located under pavement. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying or nearby buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Although no buildings currently occupy the site, future site development is likely to include at least one structure and the potential for soil vapor intrusion will be evaluated. Any concerns related to soil vapor intrusion in nearby buildings will be addressed under the voluntary agreement for the West 18th Street MGP Site."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	40:44:41 / 73:59:58
Dell:	False
Record Add:	2004-07-01 08:31:00
Record Upd:	2014-12-09 10:57:00
Updated By:	GWHEITZM
Own Op:	4
Sub Type:	D
Owner Name:	Laureen Weinshall
Owner Company:	U.S. Drug Enforcement Administration, New York Division
Owner Address:	99 Tenth Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10011
Owner Country:	United States of America
Own Op:	6
Sub Type:	E
Owner Name:	John Shannon
Owner Company:	76 Eleventh Avenue Property Owner LLC
Owner Address:	c/o HFZ Capital Group
Owner Addr2:	600 Madison Avenue, 15th Floor
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Scott M. Stringer
Owner Company:	Office of Manhattan Borough President
Owner Address:	One Centre Street
Owner Addr2:	Municipal Building, 19th Floor South
Owner City,St,Zip:	New York, NY 10007
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Theresa Mirhol
Owner Company:	Mid-Manhattan Library
Owner Address:	455 Fifth Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10016

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	John Shannon
Owner Company:	76 Eleventh Avenue Property Owner LLC
Owner Address:	c/o HFZ Capital Group
Owner Addr2:	600 Madison Ave, 15th Floor
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	John Flood
Owner Company:	Hudson Park Branch Library
Owner Address:	66 Leroy Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10014-3929
Owner Country:	United States of America
HW Code:	C231036
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231036
Waste Type:	Polycyclic Aromatic Hydrocarbons (PAHs), Total
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	v00248
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2008-02-01 14:48:00
Record Updated:	2008-02-01 14:48:00
Updated By:	WSOTTAWA
Crossref ID:	v00530
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2008-02-01 14:48:00
Record Updated:	2008-02-01 14:48:00
Updated By:	WSOTTAWA

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Crossref ID:	C231036-12-10
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2014-12-04 16:49:00
Record Updated:	2014-12-04 16:49:00
Updated By:	GWHEITZM
Crossref ID:	2014000399345
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2014-12-04 15:32:00
Record Updated:	2014-12-15 16:25:00
Updated By:	RHDANA
Crossref ID:	December 31, 2010
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2014-12-04 16:50:00
Record Updated:	2014-12-04 16:50:00
Updated By:	GWHEITZM

NY MANIFEST:

Name:	17TH STREET DEVELOPMENT PROJECT
Address:	76 11TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYR000227256
Facility Status:	Not reported
Location Address 1:	76 ELEVENTH AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000227256
Mailing Name:	17TH STREET DEVELOPMENT PROJECT
Mailing Contact:	76 ELEVNTH AVENUE PROPERTY OWNER LLC
Mailing Address 1:	600 MADISON AVE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10022
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2122979888

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	PAR000501577
Trans2 State ID:	PAD146714878
Generator Ship Date:	11/07/2017
Trans1 Recv Date:	11/07/2017

17TH STREET DEVELOPMENT PROJECT (Continued) **S110748434**

Trans2 Recv Date:	11/08/2017
TSD Site Recv Date:	11/09/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000227256
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	017923557JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	325
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AK545 **76 ELEVENTH AVENUE PROPERTY OWNER LLC** **PA MANIFEST** **S120844098**
NW **76 11TH AVENUE** **N/A**
1/8-1/4 **NY, NY 10011**
0.155 mi.
819 ft. **Site 8 of 18 in cluster AK**

Relative: Manifest Details:
Lower

Year:	2017
Manifest Number:	017923557JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000227256
Generator Date:	11/07/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported

Actual:
6 ft.

76 ELEVENTH AVENUE PROPERTY OWNER LLC (Continued) **S120844098**

TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	325
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD067098822
Date TSP Sig:	Not reported

Year:	2016
Manifest Number:	015378742JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000227256
Generator Date:	09/13/2016
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	3
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	1200
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD067098822
Date TSP Sig:	Not reported

AN546 **CON ED** **NY MANIFEST** **S118463719**
East **307 W 19TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.156 mi.
823 ft. **Site 1 of 10 in cluster AN**

Relative: NY MANIFEST:
Higher

Name:	CON ED
Address:	307 W 19TH STREET
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004856009
Facility Status:	Not reported
Location Address 1:	307 W 19TH STREET

Actual:
20 ft.

CON ED (Continued) **S118463719**

Code:	BP
Location Address 2:	SB 3434
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004856009
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2015
Trans1 Recv Date:	10/19/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/19/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004856009
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002612662GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON ED (Continued) **S118463719**

Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG547 **NEW YORK STATE DEC** **NY LTANKS** **1007205199**
NNW **507 W 21ST ST** **NY Spills** **NYP000920066**
1/8-1/4 **NEW YORK, NY 10201** **RCRA NonGen / NLR**
0.156 mi. **NY MANIFEST**
826 ft. **Site 5 of 13 in cluster AG**

Relative: LTANKS:
Lower

Actual: Name:	507 WEST 21ST STREET
10 ft. Address:	507 WEST 21ST STREET
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	9510154 / 1997-12-17
Facility ID:	9510154
Site ID:	312315
Spill Date:	1993-06-08
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B2
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1995-11-14
CID:	266
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1995-11-14
Spill Record Last Update:	1997-12-17
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	251830
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE SEE FILE. SEE ALSO 91-12111 & 96-10012. "
Remarks:	"SITE OWNER HENRY & LLOYD COMPANY. ATTORNEY OF THE OWNER NOTIFIED NEW

NEW YORK STATE DEC (Continued) **1007205199**

YORK CITY LAW DEPARTMENT ABOUT LEAKAGE FROM 14X550 GALLON TANKS AT SITE. (SEE COPY OF HIS LETTER)"

All Materials:

Site ID:	312315
Operable Unit ID:	1024627
Operable Unit:	01
Material ID:	361077
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	312315
Operable Unit ID:	1024627
Operable Unit:	01
Material ID:	361078
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	VACANT LOT
Address:	507 WEST 21ST STREET
City,State,Zip:	NEW YORK, NY 10011
Spill Number/Closed Date:	9416028 / 1996-01-02
Facility ID:	9416028
Facility Type:	ER
DER Facility ID:	432415
Site ID:	312314
DEC Region:	2
Spill Cause:	Other
Spill Class:	C3
SWIS:	3101
Spill Date:	1995-03-11
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1995-03-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

NEW YORK STATE DEC (Continued) **1007205199**

Remediation Phase:	0
Date Entered In Computer:	1995-04-13
Spill Record Last Update:	2012-12-26
Spiller Name:	Not reported
Spiller Company:	RED BALL DEMO DUMPSTER
Spiller Address:	UNKNOWN CONSTRUCTION CO.
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE "
Remarks:	"DEMOLITION DUMPSTER, 20 GALLONS IN MANHOLE COVER, CON EDISON TOOK SAMPLES. REQ CONTACT BY NYSDEC."

All Materials:

Site ID:	312314
Operable Unit ID:	1009479
Operable Unit:	01
Material ID:	371195
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	60.00
Units:	G
Recovered:	60.00
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date Form Received by Agency:		19960103
Handler Name:	NEW YORK STATE DEC	
Handler Address:		507 W 21ST ST
Handler City,State,Zip:		NEW YORK, NY 10201-0000
EPA ID:		NYP000920066
Contact Name:		SECTION REPORTING
Contact Address:		50 WOLF RD
Contact City,State,Zip:		ALBANY, NY 12233-0000
Contact Telephone:		999-999-9999 x9999
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		50 WOLF RD
Mailing City,State,Zip:		ALBANY, NY 12233-0000
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No

NEW YORK STATE DEC (Continued) **1007205199**

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

NEW YORK STATE DEC (Continued) **1007205199**

Historic Generators:

Receive Date:	19960102
Handler Name: NEW YORK STATE DEC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19960103
Handler Name: NEW YORK STATE DEC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19960101
Handler Name: NEW YORK STATE DEC	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	92411
NAICS Description:	ADMINISTRATION OF AIR AND WATER RESOURCE AND SOLID WASTE MANAGEMENT PROGRAMS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	NYSDEC REGION 2 DIV OF SPILL PREVENTION
Address:	507 W 21ST ST

NEW YORK STATE DEC (Continued) **1007205199**

City,State,Zip:	NEW YORK, NY 10201-0000
Country:	USA
EPA ID:	NYP000920066
Facility Status:	Not reported
Location Address 1:	507 WEST 21ST ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	2811

NY MANIFEST:

EPAID:	NYP000920066
Mailing Name:	NYSDEC REGION 2 DIV OF SPILL PREVENTION
Mailing Contact:	MARK C TIBBE
Mailing Address 1:	50 WOLF RD RM 340
Mailing Address 2:	Not reported
Mailing City:	ALBANY
Mailing State:	NY
Mailing Zip:	12233
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	0000000000

AG548 **HENRY & LLOYD CO THE** **RCRA NonGen / NLR** **1001124824**
NNW **507 W 21ST ST** **FINDS** **NYR000031443**
1/8-1/4 **NEW YORK, NY 10036** **ECHO**
0.156 mi. **NY MANIFEST**
826 ft. **Site 6 of 13 in cluster AG**

Relative: **Lower**
Actual: **10 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	HENRY & LLOYD CO THE	
Handler Address:		507 W 21ST ST
Handler City,State,Zip:		NEW YORK, NY 10036
EPA ID:		NYR000031443
Contact Name:		Not reported
Contact Address:		W 83RD ST
Contact City,State,Zip:		NEW YORK, NY 10024
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		W 83RD ST
Mailing City,State,Zip:		NEW YORK, NY 10024
Owner Name:		THE HENRY & LLOYD CO

HENRY & LLOYD CO THE (Continued) **1001124824**

Owner Type:	Private
Operator Name:	THE HENRY & LLOYD CO
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

HENRY & LLOYD CO THE (Continued) **1001124824**

Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: NONE
Waste Description: Not Defined

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: THE HENRY & LLOYD CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 12 W 83RD ST
Owner/Operator City,State,Zip: NEW YORK, NY 10024
Owner/Operator Telephone: 212-581-6500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE HENRY & LLOYD CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 12 W 83RD ST
Owner/Operator City,State,Zip: NEW YORK, NY 10024
Owner/Operator Telephone: 212-581-6500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE HENRY & LLOYD CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 12 W 83RD ST
Owner/Operator City,State,Zip: NEW YORK, NY 10024
Owner/Operator Telephone: 212-581-6500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19970122
Handler Name: HENRY & LLOYD CO THE
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

HENRY & LLOYD CO THE (Continued) **1001124824**

Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20060101
Handler Name: HENRY & LLOYD CO THE	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: HENRY & LLOYD CO THE	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	19961025
Handler Name: HENRY & LLOYD CO THE	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:

HENRY & LLOYD CO THE (Continued) **1001124824**

Registry ID: 110004529751

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001124824
Registry ID:	110004529751
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004529751
Name:	HENRY & LLOYD CO THE
Address:	507 W 21ST ST
City,State,Zip:	NEW YORK, NY 10036

NY MANIFEST:

Name:	HENRY AND LLOYED CO THE
Address:	507 W 21ST ST
City,State,Zip:	NEW YORK, NY 10036
Country:	USA
EPA ID:	NYR000031443
Facility Status:	Not reported
Location Address 1:	507 WEST 21ST STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10036
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000031443
Mailing Name:	HENRY AND LLOYED CO THE
Mailing Contact:	ARTHUR SHAPOLSKY
Mailing Address 1:	12 WEST 83RD STREET
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10024
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2125816500

AG549 **THE HENRY LLOYD COMPANY** **NY UST** **U003127203**
NNW **507 WEST 21ST STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.156 mi.
826 ft. **Site 7 of 13 in cluster AG**

Relative:
Lower

Actual:
10 ft.

UST:

Name:	THE HENRY LLOYD COMPANY
Address:	507 WEST 21ST STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-602777 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583948.49910
UTM Y:	4511112.82612
Site Type:	Other

Affiliation Records:

Site Id:	24733
Affiliation Type:	Facility Owner
Company Name:	THE HENRY LLOYD COMPANY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	348 WEST 42ND STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10036
Country Code:	001
Phone:	(212) 244-1762
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24733
Affiliation Type:	Mail Contact
Company Name:	THE HENRY LLOYD COMPANY
Contact Type:	Not reported
Contact Name:	ARTHUR SHAPOLSKY
Address1:	348 WEST 42ND STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10036
Country Code:	001
Phone:	(212) 244-1762
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24733
Affiliation Type:	Facility Operator
Company Name:	THE HENRY LLOYD COMPANY
Contact Type:	Not reported
Contact Name:	ARTHUR SHAPOLSKY
Address1:	Not reported

THE HENRY LLOYD COMPANY (Continued) **U003127203**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 244-1762
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24733
Affiliation Type:	Emergency Contact
Company Name:	THE HENRY LLOYD COMPANY
Contact Type:	Not reported
Contact Name:	ARTHUR SHAPOLSKY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 244-1762
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	51480
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	11/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground

THE HENRY LLOYD COMPANY (Continued) **U003127203**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number:	002
Tank ID:	51481
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	11/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number:	003
Tank ID:	51482
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	11/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

THE HENRY LLOYD COMPANY (Continued) **U003127203**

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number: 004
Tank ID: 51483
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number: 005
Tank ID: 51484
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported

THE HENRY LLOYD COMPANY (Continued) **U003127203**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 006
Tank ID: 51485
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number: 007
Tank ID: 51486
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/1996
Registered: True
Tank Location: Underground

THE HENRY LLOYD COMPANY (Continued) **U003127203**

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 008
Tank ID: 51487
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number: 009
Tank ID: 51488
Tank Status: Closed - Removed

THE HENRY LLOYD COMPANY (Continued) **U003127203**

Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	11/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number:	010
Tank ID:	51489
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	11/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

THE HENRY LLOYD COMPANY (Continued) **U003127203**

A00 - Tank Internal Protection - None

Tank Number: 011
Tank ID: 51490
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number: 012
Tank ID: 51491
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None

THE HENRY LLOYD COMPANY (Continued) **U003127203**

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number:	013
Tank ID:	51492
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	11/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number:	014
Tank ID:	52052
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	11/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported

THE HENRY LLOYD COMPANY (Continued) **U003127203**

Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number: 015
Tank ID: 52053
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: 11/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0013
Common Name of Substance: Lube Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

AN550 **CON EDISON** **NY MANIFEST** **S117058574**
East **300 W 20TH ST FRONT OF** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.158 mi.
832 ft. **Site 2 of 10 in cluster AN**

Relative: NY MANIFEST:
Higher
Name: CON EDISON
Actual: Address: 300 W 20TH ST FRONT OF
20 ft. City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004507000
Facility Status: Not reported

CON EDISON (Continued) **S117058574**

Location Address 1:	300 W 20 ST & 9TH AVE
Code:	BP
Location Address 2:	SB 3632
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004507000
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/21/2014
Trans1 Recv Date:	04/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004507000
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416546GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117058574**

Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AN551 **CON EDISON SERVICE BOX: 3632** **RCRA NonGen / NLR** **1017772923**
East **300 W 20TH ST FRONT OF** **NYP004507000**
1/8-1/4 **NEW YORK, NY 10011**
0.158 mi.
832 ft. **Site 3 of 10 in cluster AN**

Relative: RCRA NonGen / NLR:
Higher

Actual: Date Form Received by Agency: 20140522
20 ft. Handler Name: CON EDISON SERVICE BOX: 3632
Handler Address: 300 W 20TH ST FRONT OF
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYP004507000
Contact Name: THOMAS TEELING
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-3770
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: SENIOR SCIENTIST
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY
State District: NYSDEC R2
Mailing Address: IRVING PL, 15TH FL NE
Mailing City,State,Zip: NEW YORK, NY 10003
Owner Name: Not reported
Owner Type: Not reported
Operator Name: Not reported
Operator Type: Not reported
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No
Recycler Activity with Storage: No
Small Quantity On-Site Burner Exemption: No
Smelting Melting and Refining Furnace Exemption: No
Underground Injection Control: No

CON EDISON SERVICE BOX: 3632 (Continued) **1017772923**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON SERVICE BOX: 3632 (Continued) **1017772923**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140422
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140522
Handler Name: CON EDISON SERVICE BOX: 3632
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AH552 **311 WEST 21ST STREET** **NY AST** **U003384238**
ENE **311 WEST 21ST STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.158 mi.
833 ft. **Site 5 of 6 in cluster AH**

Relative: **Higher**
Actual: **20 ft.**

AST:
Name: 311 WEST 21ST STREET
Address: 311 WEST 21ST STREET
City,State,Zip: NEW YORK, NY 10011
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-085871
Program Type: PBS

311 WEST 21ST STREET (Continued) **U003384238**

UTM X: 584416.48898
UTM Y: 4510866.03338
Expiration Date: 08/30/2026
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 2088
Affiliation Type: Mail Contact
Company Name: 311 W 21 LLC
Contact Type: AGENT
Contact Name: ENIS CECUNJANIN
Address1: 381 PARK AVE SOUTH, 15TH FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10016
Country Code: 001
Phone: (917) 242-6277
EMail: ARI@NYCMGMT.COM
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-08-23

Site Id: 2088
Affiliation Type: Facility Operator
Company Name: 311 W 21 LLC
Contact Type: Not reported
Contact Name: N/A
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 242-6277
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-08-23

Site Id: 2088
Affiliation Type: Emergency Contact
Company Name: 311 W 21 LLC
Contact Type: Not reported
Contact Name: N/A
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: n/a
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-08-23

Site Id: 2088

311 WEST 21ST STREET (Continued) **U003384238**

Affiliation Type:	Facility Owner
Company Name:	311 W 21 LLC
Contact Type:	AGENT
Contact Name:	ARI WEISFOGEL
Address1:	381 PARK AVE SOUTH, 15TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(917) 242-6277
EMail:	ARI@NYCMGMT.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-08-23

Tank Info:

Tank Number:	001
Tank Id:	3356
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	E00 - Piping Secondary Containment - None
	G03 - Tank Secondary Containment - Vault (w/o access)
	L09 - Piping Leak Detection - Exempt Suction Piping
	I04 - Overfill - Product Level Gauge (A/G)
	J02 - Dispenser - Suction Dispenser
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	K00 - Spill Prevention - None
	H99 - Tank Leak Detection - Other
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/20/2000
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	08/23/2021
Material Name:	#2 fuel oil (on-site consumption)

AK553 **19TH STREET DEVELOPMENT SITE** **EDR MGP** **1008407974**
NW **80 11TH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.158 mi.
835 ft. **Site 9 of 18 in cluster AK**

Relative: Manufactured Gas Plants:
Lower No additional information available

Actual:
6 ft.

AK554 **19TH STREET DEVELOPMENT SITE** **NY ENG CONTROLS** **S105857225**
NW **80 11TH AVENUE** **NY INST CONTROL** **N/A**
1/8-1/4 **NEW YORK, NY 10011** **NY VCP**
0.158 mi. **NY BROWNFIELDS**
835 ft. **Site 10 of 18 in cluster AK**

Relative: ENG CONTROLS:
Lower

Actual:
6 ft.

Name:	19TH STREET DEVELOPMENT SITE
Address:	80 11TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Site Code:	57373
HW Code:	C231017
Control Code:	13
Control Type:	ENG
Date Record Added:	12/28/2009
Date Rec Updated:	06/02/2021
Updated By:	SXDEYETT
Site Description:	"Location: The 19th Street Development site is located along 11th Avenue, between 18th and 19th Streets. Site Features: The site is primarily comprised of a large multi-story office building with underground parking. Current Zoning/Use(s): The site is zoned commercial, industrial and is used as office space. Surrounding parcels are a combination of commercial and residential uses. The nearest residential area is within 500 feet to the east. Past Use of the Site: The site is one parcel of numerous parcels that comprise the former West 18th Street Gas Works site. Prior to remediation and redevelopment, the Site contained a two-story brick structure that served as a mid- to long-term truck parking garage and small fenced vacant lot in the SW corner. Geology and Hydrogeology: The site consists of urban fill material, silty sands with some gravel, and a clayey silt layer with varying amounts of organic material. The clayey silt layer varies in depth from approximately 11 feet below ground surface (bgs) to 28 feet bgs and is approximately 30 feet thick. Groundwater is encountered at depths between 6 and 8 feet bgs, and generally flows to the west. "
Env Problem:	"Prior to Remediation: Based upon investigations completed at the site, the primary contaminants of concern at the site include Benzene, Toluene, Ethylbenzene and Xylene (BTEX), as well as Polycyclic Aromatic Hydrocarbons (PAHs). The impacted soils mainly were found above 15 feet bgs, with the higher concentrations of BTEX and PAHs where Non-Aqueous Phase Liquid (NAPL) was seen. Groundwater was also impacted with BTEX, PAHs and/or phenolic constituents concentrations exceeding ambient water quality criteria. Post-remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzene, toluene, ethylbenzene, and xylene (BTEX), and PAHs in soil and groundwater. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil and groundwater is being managed under a site management plan."

19TH STREET DEVELOPMENT SITE (Continued) **S105857225**

Health Problem:	"Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The on-site building has a sub-grade parking garage that is partially below the natural groundwater level and incorporated a vapor barrier into its construction. A ventilation system installed in the garage inhibits the accumulation of soil gases within the building. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	False
Record Add:	2004-04-05 13:50:00
Record Upd:	2009-06-10 10:40:00
Updated By:	THKNIZEK
Own Op:	6
Sub Type:	E
Owner Name:	Luis Acevedo
Owner Company:	IAC
Owner Address:	555 West 18th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	NY, NY 10011
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Joseph B. Rose
Owner Company:	IAC/Georgetown 19th Street, LLC
Owner Address:	667 Madison Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10021
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Joseph B. Rose
Owner Company:	Georgetown 19th Street Phase I, LLC
Owner Address:	667 Madison Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10021
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Alanna Niemetz
Owner Company:	IAC
Owner Address:	555 West 18th Street
Owner Addr2:	Not reported

19TH STREET DEVELOPMENT SITE (Continued) **S105857225**

Owner City,St,Zip:	New York, NY 10011
Owner Country:	United States of America
HW Code:	C231017
Waste Type:	COAL TAR PITCH VOLATILES
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	231005
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2021-09-10 10:36:00
Record Updated:	2021-09-10 10:37:00
Updated By:	DKMACNEA
Crossref ID:	V00624
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2007-03-13 13:32:00
Record Updated:	2007-03-13 13:32:00
Updated By:	mobarrie
Crossref ID:	v00530
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2007-03-13 13:32:00
Record Updated:	2007-03-13 13:32:00
Updated By:	mobarrie
Crossref ID:	w2-1012-04-07
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2009-06-01 09:30:00
Record Updated:	2009-06-01 09:30:00
Updated By:	THKNIZEK
Crossref ID:	2006000437027
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2009-06-01 09:44:00
Record Updated:	2009-06-01 09:44:00
Updated By:	THKNIZEK

Name:	19TH STREET DEVELOPMENT SITE
Address:	80 11TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Site Code:	57373
HW Code:	C231017
Control Code:	18
Control Type:	ENG
Date Record Added:	12/28/2009
Date Rec Updated:	06/02/2021
Updated By:	SXDEYETT
Site Description:	"Location: The 19th Street Development site is located along 11th Avenue, between 18th and 19th Streets. Site Features: The site is primarily comprised of a large multi-story office building with underground parking. Current Zoning/Use(s): The site is zoned commercial, industrial and is used as office space. Surrounding parcels are a combination of commercial and residential uses. The nearest residential area is within 500 feet to the east. Past Use of the Site: The site is one parcel of numerous parcels that comprise the former West 18th Street Gas Works site. Prior to remediation and redevelopment, the Site contained a two-story brick structure that

19TH STREET DEVELOPMENT SITE (Continued) **S105857225**

served as a mid- to long-term truck parking garage and small fenced vacant lot in the SW corner. Geology and Hydrogeology: The site consists of urban fill material, silty sands with some gravel, and a clayey silt layer with varying amounts of organic material. The clayey silt layer varies in depth from approximately 11 feet below ground surface (bgs) to 28 feet bgs and is approximately 30 feet thick. Groundwater is encountered at depths between 6 and 8 feet bgs, and generally flows to the west. "

Env Problem: "Prior to Remediation: Based upon investigations completed at the site, the primary contaminants of concern at the site include Benzene, Toluene, Ethylbenzene and Xylene (BTEX), as well as Polycyclic Aromatic Hydrocarbons (PAHs). The impacted soils mainly were found above 15 feet bgs, with the higher concentrations of BTEX and PAHs where Non-Aqueous Phase Liquid (NAPL) was seen. Groundwater was also impacted with BTEX, PAHs and/or phenolic constituents concentrations exceeding ambient water quality criteria. Post-remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzene, toluene, ethylbenzene, and xylene (BTEX), and PAHs in soil and groundwater. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil and groundwater is being managed under a site management plan."

Health Problem: "Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The on-site building has a sub-grade parking garage that is partially below the natural groundwater level and incorporated a vapor barrier into its construction. A ventilation system installed in the garage inhibits the accumulation of soil gases within the building. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2004-04-05 13:50:00
Record Upd: 2009-06-10 10:40:00
Updated By: THKNIZEK
Own Op: 6
Sub Type: E
Owner Name: Luis Acevedo
Owner Company: IAC
Owner Address: 555 West 18th Street
Owner Addr2: Not reported
Owner City,St,Zip: NY, NY 10011
Owner Country: United States of America

19TH STREET DEVELOPMENT SITE (Continued) **S105857225**

Own Op:	6
Sub Type:	P03
Owner Name:	Joseph B. Rose
Owner Company:	IAC/Georgetown 19th Street, LLC
Owner Address:	667 Madison Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10021
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Joseph B. Rose
Owner Company:	Georgetown 19th Street Phase I, LLC
Owner Address:	667 Madison Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10021
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Alanna Niemetz
Owner Company:	IAC
Owner Address:	555 West 18th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10011
Owner Country:	United States of America
HW Code:	C231017
Waste Type:	COAL TAR PITCH VOLATILES
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	231005
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2021-09-10 10:36:00
Record Updated:	2021-09-10 10:37:00
Updated By:	DKMACNEA
Crossref ID:	V00624
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2007-03-13 13:32:00
Record Updated:	2007-03-13 13:32:00
Updated By:	mobarrie
Crossref ID:	v00530
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2007-03-13 13:32:00
Record Updated:	2007-03-13 13:32:00
Updated By:	mobarrie
Crossref ID:	w2-1012-04-07
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2009-06-01 09:30:00
Record Updated:	2009-06-01 09:30:00
Updated By:	THKNIZEK
Crossref ID:	2006000437027
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2009-06-01 09:44:00
Record Updated:	2009-06-01 09:44:00

19TH STREET DEVELOPMENT SITE (Continued) **S105857225**

Updated By: THKNIZEK

INST CONTROL:
Name: 19TH STREET DEVELOPMENT SITE
Address: 80 11TH AVENUE
City,State,Zip: NEW YORK, NY 10011
Site Code: 57373
Control Name: Landuse Restriction
HW Code: C231017
Control Code: 25
Control Type: INST
Dt record added: 12/28/2009
Dt rec updated: 06/02/2021
Updated By: SXDEYETT
Site Code: 57373
Site Description: "Location: The 19th Street Development site is located along 11th Avenue, between 18th and 19th Streets. Site Features: The site is primarily comprised of a large multi-story office building with underground parking. Current Zoning/Use(s): The site is zoned commercial, industrial and is used as office space. Surrounding parcels are a combination of commercial and residential uses. The nearest residential area is within 500 feet to the east. Past Use of the Site: The site is one parcel of numerous parcels that comprise the former West 18th Street Gas Works site. Prior to remediation and redevelopment, the Site contained a two-story brick structure that served as a mid- to long-term truck parking garage and small fenced vacant lot in the SW corner. Geology and Hydrogeology: The site consists of urban fill material, silty sands with some gravel, and a clayey silt layer with varying amounts of organic material. The clayey silt layer varies in depth from approximately 11 feet below ground surface (bgs) to 28 feet bgs and is approximately 30 feet thick. Groundwater is encountered at depths between 6 and 8 feet bgs, and generally flows to the west. "
Env Problem: "Prior to Remediation: Based upon investigations completed at the site, the primary contaminants of concern at the site include Benzene, Toluene, Ethylbenzene and Xylene (BTEX), as well as Polycyclic Aromatic Hydrocarbons (PAHs). The impacted soils mainly were found above 15 feet bgs, with the higher concentrations of BTEX and PAHs where Non-Aqueous Phase Liquid (NAPL) was seen. Groundwater was also impacted with BTEX, PAHs and/or phenolic constituents concentrations exceeding ambient water quality criteria.
Post-remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzene, toluene, ethylbenzene, and xylene (BTEX), and PAHs in soil and groundwater. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil and groundwater is being managed under a site management plan."
Health Problem: "Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil

19TH STREET DEVELOPMENT SITE (Continued) **S105857225**

vapor intrusion. The on-site building has a sub-grade parking garage that is partially below the natural groundwater level and incorporated a vapor barrier into its construction. A ventilation system installed in the garage inhibits the accumulation of soil gases within the building. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2004-04-05 13:50:00
Record Upd: 2009-06-10 10:40:00
Updated By: THKNIZEK
Own Op: 6
Sub Type: E
Owner Name: Luis Acevedo
Owner Company: IAC
Owner Address: 555 West 18th Street
Owner Addr2: Not reported
Owner City,St,Zip: NY, NY 10011
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Joseph B. Rose
Owner Company: IAC/Georgetown 19th Street, LLC
Owner Address: 667 Madison Ave
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10021
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Joseph B. Rose
Owner Company: Georgetown 19th Street Phase I, LLC
Owner Address: 667 Madison Avenue
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10021
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Alanna Niemetz
Owner Company: IAC
Owner Address: 555 West 18th Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10011
Owner Country: United States of America
HW Code: C231017
Waste Type: COAL TAR PITCH VOLATILES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 231005
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2021-09-10 10:36:00

19TH STREET DEVELOPMENT SITE (Continued) **S105857225**

Record Updated: 2021-09-10 10:37:00
Updated By: DKMACNEA
Crossref ID: V00624
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2007-03-13 13:32:00
Record Updated: 2007-03-13 13:32:00
Updated By: mobarrie
Crossref ID: v00530
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2007-03-13 13:32:00
Record Updated: 2007-03-13 13:32:00
Updated By: mobarrie
Crossref ID: w2-1012-04-07
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2009-06-01 09:30:00
Record Updated: 2009-06-01 09:30:00
Updated By: THKNIZEK
Crossref ID: 2006000437027
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2009-06-01 09:44:00
Record Updated: 2009-06-01 09:44:00
Updated By: THKNIZEK

Name: 19TH STREET DEVELOPMENT SITE
Address: 80 11TH AVENUE
City,State,Zip: NEW YORK, NY 10011
Site Code: 57373
Control Name: Site Management Plan
HW Code: C231017
Control Code: 32
Control Type: INST
Dt record added: 12/28/2009
Dt rec updated: 06/02/2021
Updated By: SXDEYETT
Site Code: 57373
Site Description: "Location: The 19th Street Development site is located along 11th Avenue, between 18th and 19th Streets. Site Features: The site is primarily comprised of a large multi-story office building with underground parking. Current Zoning/Use(s): The site is zoned commercial, industrial and is used as office space. Surrounding parcels are a combination of commercial and residential uses. The nearest residential area is within 500 feet to the east. Past Use of the Site: The site is one parcel of numerous parcels that comprise the former West 18th Street Gas Works site. Prior to remediation and redevelopment, the Site contained a two-story brick structure that served as a mid- to long-term truck parking garage and small fenced vacant lot in the SW corner. Geology and Hydrogeology: The site consists of urban fill material, silty sands with some gravel, and a clayey silt layer with varying amounts of organic material. The clayey silt layer varies in depth from approximately 11 feet below ground surface (bgs) to 28 feet bgs and is approximately 30 feet thick. Groundwater is encountered at depths between 6 and 8 feet bgs, and generally flows to the west. "

19TH STREET DEVELOPMENT SITE (Continued) **S105857225**

Env Problem: "Prior to Remediation: Based upon investigations completed at the site, the primary contaminants of concern at the site include Benzene, Toluene, Ethylbenzene and Xylene (BTEX), as well as Polycyclic Aromatic Hydrocarbons (PAHs). The impacted soils mainly were found above 15 feet bgs, with the higher concentrations of BTEX and PAHs where Non-Aqueous Phase Liquid (NAPL) was seen. Groundwater was also impacted with BTEX, PAHs and/or phenolic constituents concentrations exceeding ambient water quality criteria.
Post-remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzene, toluene, ethylbenzene, and xylene (BTEX), and PAHs in soil and groundwater. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil and groundwater is being managed under a site management plan."
Health Problem: "Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The on-site building has a sub-grade parking garage that is partially below the natural groundwater level and incorporated a vapor barrier into its construction. A ventilation system installed in the garage inhibits the accumulation of soil gases within the building. "
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2004-04-05 13:50:00
Record Upd: 2009-06-10 10:40:00
Updated By: THKNIZEK
Own Op: 6
Sub Type: E
Owner Name: Luis Acevedo
Owner Company: IAC
Owner Address: 555 West 18th Street
Owner Addr2: Not reported
Owner City,St,Zip: NY, NY 10011
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Joseph B. Rose
Owner Company: IAC/Georgetown 19th Street, LLC
Owner Address: 667 Madison Ave
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10021
Owner Country: United States of America

19TH STREET DEVELOPMENT SITE (Continued) **S105857225**

Own Op: 6
Sub Type: P03
Owner Name: Joseph B. Rose
Owner Company: Georgetown 19th Street Phase I, LLC
Owner Address: 667 Madison Avenue
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10021
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Alanna Niemetz
Owner Company: IAC
Owner Address: 555 West 18th Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10011
Owner Country: United States of America
HW Code: C231017
Waste Type: COAL TAR PITCH VOLATILES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 231005
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2021-09-10 10:36:00
Record Updated: 2021-09-10 10:37:00
Updated By: DKMACNEA
Crossref ID: V00624
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2007-03-13 13:32:00
Record Updated: 2007-03-13 13:32:00
Updated By: mobarrie
Crossref ID: v00530
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2007-03-13 13:32:00
Record Updated: 2007-03-13 13:32:00
Updated By: mobarrie
Crossref ID: w2-1012-04-07
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2009-06-01 09:30:00
Record Updated: 2009-06-01 09:30:00
Updated By: THKNIZEK
Crossref ID: 2006000437027
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2009-06-01 09:44:00
Record Updated: 2009-06-01 09:44:00
Updated By: THKNIZEK

Name: 19TH STREET DEVELOPMENT SITE
Address: 80 11TH AVENUE
City,State,Zip: NEW YORK, NY 10011
Site Code: 57373
Control Name: Environmental Easement
HW Code: C231017

19TH STREET DEVELOPMENT SITE (Continued) **S105857225**

Control Code: J
Control Type: INST
Dt record added: 12/28/2009
Dt rec updated: 06/02/2021
Updated By: SXDEYETT
Site Code: 57373
Site Description: "Location: The 19th Street Development site is located along 11th Avenue, between 18th and 19th Streets. Site Features: The site is primarily comprised of a large multi-story office building with underground parking. Current Zoning/Use(s): The site is zoned commercial, industrial and is used as office space. Surrounding parcels are a combination of commercial and residential uses. The nearest residential area is within 500 feet to the east. Past Use of the Site: The site is one parcel of numerous parcels that comprise the former West 18th Street Gas Works site. Prior to remediation and redevelopment, the Site contained a two-story brick structure that served as a mid- to long-term truck parking garage and small fenced vacant lot in the SW corner. Geology and Hydrogeology: The site consists of urban fill material, silty sands with some gravel, and a clayey silt layer with varying amounts of organic material. The clayey silt layer varies in depth from approximately 11 feet below ground surface (bgs) to 28 feet bgs and is approximately 30 feet thick. Groundwater is encountered at depths between 6 and 8 feet bgs, and generally flows to the west. "
Env Problem: "Prior to Remediation: Based upon investigations completed at the site, the primary contaminants of concern at the site include Benzene, Toluene, Ethylbenzene and Xylene (BTEX), as well as Polycyclic Aromatic Hydrocarbons (PAHs). The impacted soils mainly were found above 15 feet bgs, with the higher concentrations of BTEX and PAHs where Non-Aqueous Phase Liquid (NAPL) was seen. Groundwater was also impacted with BTEX, PAHs and/or phenolic constituents concentrations exceeding ambient water quality criteria.
Post-remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzene, toluene, ethylbenzene, and xylene (BTEX), and PAHs in soil and groundwater. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil and groundwater is being managed under a site management plan."
Health Problem: "Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The on-site building has a sub-grade parking garage that is partially below the natural groundwater level and incorporated a vapor barrier into its construction. A ventilation system installed in the garage inhibits the accumulation of soil gases within the building. "
Dump: False
Structure: False
Lagoon: False
Landfill: False

19TH STREET DEVELOPMENT SITE (Continued) **S105857225**

Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2004-04-05 13:50:00
Record Upd: 2009-06-10 10:40:00
Updated By: THKNIZEK
Own Op: 6
Sub Type: E
Owner Name: Luis Acevedo
Owner Company: IAC
Owner Address: 555 West 18th Street
Owner Addr2: Not reported
Owner City,St,Zip: NY, NY 10011
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Joseph B. Rose
Owner Company: IAC/Georgetown 19th Street, LLC
Owner Address: 667 Madison Ave
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10021
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Joseph B. Rose
Owner Company: Georgetown 19th Street Phase I, LLC
Owner Address: 667 Madison Avenue
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10021
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Alanna Niemetz
Owner Company: IAC
Owner Address: 555 West 18th Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10011
Owner Country: United States of America
HW Code: C231017
Waste Type: COAL TAR PITCH VOLATILES
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 231005
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2021-09-10 10:36:00
Record Updated: 2021-09-10 10:37:00
Updated By: DKMACNEA
Crossref ID: V00624
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2007-03-13 13:32:00
Record Updated: 2007-03-13 13:32:00
Updated By: mobarrie
Crossref ID: v00530

19TH STREET DEVELOPMENT SITE (Continued) **S105857225**

Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2007-03-13 13:32:00
Record Updated: 2007-03-13 13:32:00
Updated By: mobarrie
Crossref ID: w2-1012-04-07
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2009-06-01 09:30:00
Record Updated: 2009-06-01 09:30:00
Updated By: THKNIZEK
Crossref ID: 2006000437027
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2009-06-01 09:44:00
Record Updated: 2009-06-01 09:44:00
Updated By: THKNIZEK

VCP:
Name: 19TH STREET DEVELOPMENT SITE
Address: 80 11TH AVENUE
City,State,Zip: NEW YORK, NY 10011-
Program Type: VCP
Site Code: 57143
HW Code: V00624
Site Class: N
SWIS: 3101
Region: 2
Town: New York City
Acres: 0.600
Date Record Added: 12/02/2002
Date Record Updated: 12/07/2009
Updated By: MOBARRIE
Site Description: "Description Not Available"
Env Problem: ""
Health Problem: ""
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 6
Sub Type: ZZZ
Owner Name: JOSEPH P. ROSE
Owner Company: GEORGETOWN 19TH ST. DEVELOPMENT LLC
Owner Address: 677 MADISON AVENUE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10021
Owner Country: United States of America
Own Op: 1

19TH STREET DEVELOPMENT SITE (Continued) **S105857225**

Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	COTARD REALTY ASSOCIATES
Owner Address:	362 KINGSLAND AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11222
Owner Country:	United States of America
Own Op:	4
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	COTARD REALTY ASSOCIATES
Owner Address:	362 KINGSLAND AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11222
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

BROWNFIELDS:

Name:	19TH STREET DEVELOPMENT SITE
Address:	80 11TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Program:	BCP
Site Code:	57373
Acres:	0.680
HW Code:	C231017
SWIS:	3101
Town:	New York City
Record Added Date:	04/05/2004
Record Updated Date:	11/05/2021
Update By:	JEBROWN
Site Description:	"Location: The 19th Street Development site is located along 11th Avenue, between 18th and 19th Streets. Site Features: The site is primarily comprised of a large multi-story office building with underground parking. Current Zoning/Use(s): The site is zoned commercial, industrial and is used as office space. Surrounding parcels are a combination of commercial and residential uses. The nearest residential area is within 500 feet to the east. Past Use of the Site: The site is one parcel of numerous parcels that comprise the former West 18th Street Gas Works site. Prior to remediation and redevelopment, the Site contained a two-story brick structure that served as a mid- to long-term truck parking garage and small fenced vacant lot in the SW corner. Geology and Hydrogeology: The site consists of urban fill material, silty sands with some gravel, and a clayey silt layer with varying amounts of organic material. The clayey silt layer varies in depth from approximately 11 feet below ground surface (bgs) to 28 feet bgs and is approximately 30 feet thick. Groundwater is encountered at depths between 6 and 8 feet bgs, and generally flows to the west. "

19TH STREET DEVELOPMENT SITE (Continued) **S105857225**

Env Problem:	"Prior to Remediation: Based upon investigations completed at the site, the primary contaminants of concern at the site include Benzene, Toluene, Ethylbenzene and Xylene (BTEX), as well as Polycyclic Aromatic Hydrocarbons (PAHs). The impacted soils mainly were found above 15 feet bgs, with the higher concentrations of BTEX and PAHs where Non-Aqueous Phase Liquid (NAPL) was seen. Groundwater was also impacted with BTEX, PAHs and/or phenolic constituents concentrations exceeding ambient water quality criteria. Post-remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzene, toluene, ethylbenzene, and xylene (BTEX), and PAHs in soil and groundwater. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil and groundwater is being managed under a site management plan."
Health Problem:	"Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The on-site building has a sub-grade parking garage that is partially below the natural groundwater level and incorporated a vapor barrier into its construction. A ventilation system installed in the garage inhibits the accumulation of soil gases within the building. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	False
Record Add:	2004-04-05 13:50:00
Record Upd:	2009-06-10 10:40:00
Updated By:	THKNIZEK
Own Op:	6
Sub Type:	E
Owner Name:	Luis Acevedo
Owner Company:	IAC
Owner Address:	555 West 18th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	NY, NY 10011
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Joseph B. Rose
Owner Company:	IAC/Georgetown 19th Street, LLC
Owner Address:	667 Madison Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10021
Owner Country:	United States of America
Own Op:	6

19TH STREET DEVELOPMENT SITE (Continued) **S105857225**

Sub Type:	P03
Owner Name:	Joseph B. Rose
Owner Company:	Georgetown 19th Street Phase I, LLC
Owner Address:	667 Madison Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10021
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Alanna Niemetz
Owner Company:	IAC
Owner Address:	555 West 18th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10011
Owner Country:	United States of America
HW Code:	C231017
Waste Type:	COAL TAR PITCH VOLATILES
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	231005
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2021-09-10 10:36:00
Record Updated:	2021-09-10 10:37:00
Updated By:	DKMACNEA
Crossref ID:	V00624
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2007-03-13 13:32:00
Record Updated:	2007-03-13 13:32:00
Updated By:	mobarrie
Crossref ID:	v00530
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2007-03-13 13:32:00
Record Updated:	2007-03-13 13:32:00
Updated By:	mobarrie
Crossref ID:	w2-1012-04-07
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2009-06-01 09:30:00
Record Updated:	2009-06-01 09:30:00
Updated By:	THKNIZEK
Crossref ID:	2006000437027
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2009-06-01 09:44:00
Record Updated:	2009-06-01 09:44:00
Updated By:	THKNIZEK

AM555 **11 ELEVENTH AVENUE** **NY LTANKS** **S102618890**
WSW **11 ELEVENTH AVENUE** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.158 mi.
836 ft. **Site 6 of 13 in cluster AM**

Relative:
Lower

Actual:
4 ft.

LTANKS:

Name:	11 ELEVENTH AVENUE
Address:	11 ELEVENTH AVENUE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9405274 / 1996-12-17
Facility ID:	9405274
Site ID:	280857
Spill Date:	1994-07-18
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1994-07-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1994-10-06
Spill Record Last Update:	2000-12-27
Spiller Name:	Not reported
Spiller Company:	NYCTA
Spiller Address:	11 ELEVENTH AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	228069
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE transfered from Hale to Tibbe on 12/27/00. refer to 91-06100. piping repaired, investigation/tremediation ongoing."
Remarks:	"BROKEN VENT-URS WILL UNCOVER TANK. ISOLATE-RETEST"

All TTF:

Facility ID:	9405274
Spill Number:	9405274
Spill Tank Test:	1542955
Site ID:	280857
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown

11 ELEVENTH AVENUE (Continued) **S102618890**

Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	280857
Operable Unit ID:	999465
Operable Unit:	01
Material ID:	381867
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AH556 **304-306 WEST 21ST ST.** **NY UST** **U004289035**
East **304-306 WEST 21ST STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.158 mi.
836 ft. **Site 6 of 6 in cluster AH**

Relative:
Higher

Actual:
20 ft.

UST:

Name:	304-306 WEST 21ST ST.
Address:	304-306 WEST 21ST STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-309451 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	07/20/2022
UTM X:	584455.98458
UTM Y:	4510825.28160
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	14107
Affiliation Type:	Facility Operator
Company Name:	304-306 WEST 21ST ST
Contact Type:	Not reported
Contact Name:	VASSILI TROUBITCH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 929-4163
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-03

Site Id:	14107

304-306 WEST 21ST ST. (Continued) **U004289035**

Affiliation Type:	Emergency Contact
Company Name:	AVANTI REALTY CORP
Contact Type:	Not reported
Contact Name:	SCHILDWACHTER FUEL OIL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(800) 642-3646
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-03

Site Id:	14107
Affiliation Type:	Facility Owner
Company Name:	AVANTI REALTY CORP.
Contact Type:	VICE PRESIDENT
Contact Name:	JOHN A. VERNI
Address1:	P.O. BOX 601
Address2:	Not reported
City:	MANARONECK
State:	NY
Zip Code:	10543
Country Code:	001
Phone:	(914) 777-6770
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-05-10

Site Id:	14107
Affiliation Type:	Mail Contact
Company Name:	AVANTI REALTY CORP.
Contact Type:	VICE PRESIDENT
Contact Name:	JOHN A. VERNI
Address1:	P.O. BOX 601
Address2:	Not reported
City:	MANARONECK
State:	NY
Zip Code:	10543
Country Code:	001
Phone:	(914) 777-6770
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-05-10

Tank Info:

Tank Number:	001
Tank ID:	17807
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	1500

304-306 WEST 21ST ST. (Continued) **U004289035**

Install Date:	06/18/1976
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DAFRANCI
Last Modified:	05/10/2018

Equipment Records:

I05 - Overfill - Vent Whistle
B05 - Tank External Protection - Jacketed
C01 - Pipe Location - Aboveground
F00 - Pipe External Protection - None
H08 - Tank Leak Detection - Weep holes in Vaults with no access for inspection
G03 - Tank Secondary Containment - Vault (w/o access)
L99 - Piping Leak Detection - Other
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

AO557 **CON EDISON** **NY MANIFEST** **S117067533**
ENE **FO 333 WEST 22ND ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.159 mi.
837 ft. **Site 1 of 12 in cluster AO**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FO 333 WEST 22ND ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004604732
Facility Status:	Not reported
Location Address 1:	FO 333 WEST 22ND ST
Code:	BP
Location Address 2:	STRUCTURE 3980
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004604732
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S117067533**

Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/23/2014
Trans1 Recv Date:	07/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004604732
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504469GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI558 **CON EDISON-SERVICE BOX 2579** **RCRA NonGen / NLR** **1012185702**
SSE **317 W 15TH ST & 8TH AVE** **NJ MANIFEST** **NYP004165353**
1/8-1/4 **NEW YORK, NY 10011** **NY MANIFEST**
0.160 mi.
843 ft. **Site 3 of 7 in cluster AI**

Relative: **Higher**
Actual: **20 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20090401
Handler Name:	CON EDISON-SERVICE BOX	2579
Handler Address:		317 W 15TH ST & 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004165353
Contact Name:		HERMAN BAKER
Contact Address:		IRVING PL RM 828
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		718-267-3853
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		Yes
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON-SERVICE BOX 2579 (Continued) **1012185702**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211026
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090401
Handler Name:	CON EDISON-SERVICE BOX 2579
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	Not reported
Recognized Trader Exporter:	Not reported
Spent Lead Acid Battery Importer:	Not reported
Spent Lead Acid Battery Exporter:	Not reported
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON-SERVICE BOX 2579 (Continued) **1012185702**

NJ MANIFEST:

EPA Id:	NYP004165361
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	HERMAN BAKER
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001028128JJK
EPA ID:	NYP004165361
Date Shipped:	04/01/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/01/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/03/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported

CON EDISON-SERVICE BOX 2579 (Continued) **1012185702**

Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 100 P

EPA Id: NYP004165353
Mail Address: IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: HERMAN BAKER
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 001028129JJK
EPA ID: NYP004165353
Date Shipped: 04/01/2009
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 04/01/2009
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 04/03/2009
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported

CON EDISON-SERVICE BOX 2579 (Continued) **1012185702**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	75 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	317 W 15TH ST & 8TH AVE 2579SB
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004165353
Facility Status:	Not reported
Location Address 1:	371 WEST 1ST ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10009
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004165353
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANLYN MURRAY
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193

CON EDISON-SERVICE BOX 2579 (Continued) **1012185702**

Trans2 State ID:	Not reported
Generator Ship Date:	04/01/2009
Trans1 Recv Date:	04/01/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/03/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004165353
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	001028129JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	75
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI559 **CON EDISON SERVICE BOX: 2580** **RCRA NonGen / NLR** **1012185703**
SSE **317 W 15TH ST & 8TH AVE 2580SB** **NYP004165361**
1/8-1/4 **NEW YORK, NY 10011**
0.160 mi.
843 ft. **Site 4 of 7 in cluster AI**

Relative: RCRA NonGen / NLR:
Higher

Date Form Received by Agency:		20160601
Actual: Handler Name:	CON EDISON SERVICE BOX:	2580
20 ft. Handler Address:		317 W 15TH ST & 8TH AVE 2580SB
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004165361
Contact Name:		HERMAN BAKER
Contact Address:		IRVING PL RM 828

CON EDISON SERVICE BOX: 2580 (Continued) **1012185703**

Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	718-267-3853
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No

CON EDISON SERVICE BOX: 2580 (Continued) **1012185703**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160726
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090401
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601
Handler Name: CON EDISON SERVICE BOX: 2580	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AM560 **GLUE FAST EQUIPMENT CO INC** **RCRA NonGen / NLR** **1000196633**
WSW **9-11 WHITE ST** **FINDS** **NYD001356542**
1/8-1/4 **NEW YORK, NY 10013** **ECHO**
0.160 mi.
844 ft. **Site 7 of 13 in cluster AM**

Relative: **Lower**
Actual: **4 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	GLUE FAST EQUIPMENT CO INC
Handler Address:	9-11 WHITE ST
Handler City,State,Zip:	NEW YORK, NY 10013
EPA ID:	NYD001356542
Contact Name:	Not reported
Contact Address:	WHITE ST
Contact City,State,Zip:	NEW YORK, NY 10013
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	X
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	WHITE ST
Mailing City,State,Zip:	NEW YORK, NY 10013
Owner Name:	OWNERNAME
Owner Type:	Private
Operator Name:	OWNERNAME
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

GLUE FAST EQUIPMENT CO INC (Continued) **1000196633**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	OWNERNAME
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	OWNERNAME
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

GLUE FAST EQUIPMENT CO INC (Continued) **1000196633**

Owner/Operator Indicator: Owner
Owner/Operator Name: OWNERNAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19801231
Handler Name: GLUE FAST EQUIPMENT CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: GLUE FAST EQUIPMENT CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: GLUE FAST EQUIPMENT CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:

NAICS Code: 32552
NAICS Description: ADHESIVE MANUFACTURING

GLUE FAST EQUIPMENT CO INC (Continued) **1000196633**

NAICS Code: 42184
NAICS Description: INDUSTRIAL SUPPLIES WHOLESALERS

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19901113
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYDEC
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

GLUE FAST EQUIPMENT CO INC (Continued) **1000196633**

FINDS:
Registry ID: 110004334024

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000196633
Registry ID:	110004334024
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004334024
Name:	GLUE FAST EQUIPMENT CO INC
Address:	9-11 WHITE ST
City,State,Zip:	NEW YORK, NY 10013

AF561 **CON EDISON** **RCRA NonGen / NLR** **1014397056**
NNE **426 W 23RD ST** **NYP004193736**
1/8-1/4 **NEW YORK, NY 10007**
0.160 mi.
845 ft. **Site 2 of 7 in cluster AF**

Relative: **Higher**

Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		426 W 23RD ST
Handler City,State,Zip:		NEW YORK, NY 10007
EPA ID:		NYP004193736
Contact Name:		DANIEL PONTECORVO
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-203-2573
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported

CON EDISON (Continued) **1014397056**

Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160719
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON (Continued) **1014397056**

Historic Generators:
Receive Date: 20090904
Handler Name: CON EDISON
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160601
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AF562 **CON EDISON SERVICE BOX: 4192** **RCRA NonGen / NLR** **1016972342**
NNE **428 W 23RD ST FRONT OF** **NY MANIFEST** **NYP004461109**
1/8-1/4 **NEW YORK, NY 10011**
0.160 mi.
846 ft. **Site 3 of 7 in cluster AF**

Relative:
Higher

Actual:
15 ft.

RCRA NonGen / NLR:
Date Form Received by Agency: 20140407
Handler Name: CON EDISON SERVICE BOX: 4192
Handler Address: 428 W 23RD ST FRONT OF
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYP004461109
Contact Name: THOMAS TEELING
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-3770
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: SENIOR SCIENTIST

CON EDISON SERVICE BOX: 4192 (Continued) **1016972342**

EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported

CON EDISON SERVICE BOX: 4192 (Continued) **1016972342**

Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140307
Handler Name: CON EDISON SERVICE BOX:	4192
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140407
Handler Name: CON EDISON SERVICE BOX:	4192
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON ED
Address:	428 W 23RD ST FRONT OF

CON EDISON SERVICE BOX: 4192 (Continued) **1016972342**

City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004461109
Facility Status:	Not reported
Location Address 1:	428 W 23 ST
Code:	BP
Location Address 2:	SB 4192
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004461109
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/07/2014
Trans1 Recv Date:	03/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/07/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004461109
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002330309GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported

CON EDISON SERVICE BOX: 4192 (Continued) **1016972342**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AF563 **WEST 23RD STREET OWNERS CORP** **NY AST** **U003390497**
NNE **410 W 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.160 mi.
846 ft. **Site 4 of 7 in cluster AF**

Relative:
Higher

Actual:
16 ft.

AST:

Name:	WEST 23RD STREET OWNERS CORP
Address:	410 W 23RD ST
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-147222
Program Type:	PBS
UTM X:	584253.12876
UTM Y:	4511108.93019
Expiration Date:	05/01/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	4315
Affiliation Type:	Facility Owner
Company Name:	WEST 23RD STREET OWNERS CORP
Contact Type:	MANAGER
Contact Name:	KEITH SCANDORE
Address1:	410 WEST 23RD STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 736-3680
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-05-25

Site Id:	4315

WEST 23RD STREET OWNERS CORP (Continued) **U003390497**

Affiliation Type:	Mail Contact
Company Name:	ALL AREA REALTY SERVICES, INC.
Contact Type:	Not reported
Contact Name:	KEITH SCANDORE
Address1:	99 TULIP AVENUE
Address2:	SUITE #302
City:	FLORAL PARK
State:	NY
Zip Code:	11001
Country Code:	001
Phone:	(718) 721-0700
EMail:	KS@AARSNY.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-05-25

Site Id:	4315
Affiliation Type:	Facility Operator
Company Name:	WEST 23RD STREET OWNERS CORP
Contact Type:	Not reported
Contact Name:	RENNIS LAMI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 721-0700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-05-25

Site Id:	4315
Affiliation Type:	Emergency Contact
Company Name:	WEST 23RD STREET OWNERS CORP
Contact Type:	Not reported
Contact Name:	KEITH SCANDORE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 721-0700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-05-25

Tank Info:

Tank Number:	001
Tank Id:	19284
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

WEST 23RD STREET OWNERS CORP (Continued) **U003390497**

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/1973
Capacity Gallons:	7500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	05/25/2017
Material Name:	#2 fuel oil (on-site consumption)
Tank Number:	002
Tank Id:	19285
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	05/01/1973
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	11/01/1995

WEST 23RD STREET OWNERS CORP (Continued) **U003390497**

Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AM564 **CON EDISON SERVICE BOX: 43206** **NJ MANIFEST** **S117985943**
WSW **55 10TH AVE N OF 34TH ST FRONT OF** **N/A**
1/8-1/4 **NEW YORK, NY 10001**
0.161 mi.
848 ft. **Site 8 of 13 in cluster AM**

Relative:
Lower

Actual:
8 ft.

NJ MANIFEST:

EPA Id:	NYP004264826
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JOSE MONTALVO
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010456194JJK
EPA ID:	NYP004264826
Date Shipped:	8/24/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported

CON EDISON SERVICE BOX: 43206 (Continued) **S117985943**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	1,000.00 Pounds

AM565 **CON EDISON SERVICE BOX: 43206** **RCRA NonGen / NLR** **1016143700**
WSW **55 10TH AVE N OF 34TH ST FRONT OF** **NYP004264826**
1/8-1/4 **NEW YORK, NY 10001**
0.161 mi.
848 ft. **Site 9 of 13 in cluster AM**

Relative: RCRA NonGen / NLR:
Lower

Actual: Date Form Received by Agency:		20170728
8 ft. Handler Name:	CON EDISON SERVICE BOX:	43206
Handler Address:		55 10TH AVE N OF 34TH ST FRONT OF
Handler City,State,Zip:		NEW YORK, NY 10001
EPA ID:		NYP004264826
Contact Name:		JOSE MONTALVO
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-427-1331
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No

CON EDISON SERVICE BOX: 43206 (Continued) **1016143700**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170928
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:
Receive Date: 20120824

CON EDISON SERVICE BOX: 43206 (Continued) **1016143700**

Handler Name: CON EDISON SERVICE BOX:	43206
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20170728
Handler Name: CON EDISON SERVICE BOX:	43206
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AM566 **CON EDISON** **NY MANIFEST** **S121967047**
WSW **55 10TH AVE N OF 34TH ST FRONT** **N/A**
1/8-1/4 **NEW YORK, NY 10001**
0.161 mi.
848 ft. **Site 10 of 13 in cluster AM**

Relative: **Lower**
Actual: **8 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	55 10TH AVE N OF 34TH ST FRONT
City,State,Zip:	NEW YORK, NY 10001
Country:	USA
EPA ID:	NYP004264826
Facility Status:	Not reported
Location Address 1:	FO 55 10TH AVE NO 34TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10001
Location Zip 4:	Not reported

CON EDISON (Continued) **S121967047**

NY MANIFEST:

EPAID:	NYP004264826
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/24/2012
Trans1 Recv Date:	08/24/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/24/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004264826
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010456194JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S121967047**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AF567 **CON EDISON** **NY MANIFEST** **S117742048**
NE **400 W 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.161 mi.
848 ft. **Site 5 of 7 in cluster AF**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	400 W 23RD ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004753067
Facility Status:	Not reported
Location Address 1:	400 W 23 ST
Code:	BP
Location Address 2:	TM3153
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004753067
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	03/18/2015
Trans1 Recv Date:	03/18/2015
Trans2 Recv Date:	03/20/2015
TSD Site Recv Date:	03/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004753067
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **S117742048**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002611420GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AF568 **CON EDISON** **NJ MANIFEST** **S120669173**
NE **400 W 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.161 mi.
848 ft. **Site 6 of 7 in cluster AF**

Relative: NJ MANIFEST:
Higher

EPA Id:	NYP004753067
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Actual:
17 ft.

CON EDISON (Continued) **S120669173**

Manifest:

Manifest Number:	002611420GBF
EPA ID:	NYP004753067
Date Shipped:	3/18/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AF569 **CON EDISON** **RCRA NonGen / NLR** **1018280426**
NE **400 W 23RD ST** **FINDS** **NYP004753067**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.161 mi.
848 ft. **Site 7 of 7 in cluster AF**

Relative:
Higher

Actual:
17 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20150318
Handler Name:	CON EDISON	
Handler Address:		400 W 23RD ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004753067
Contact Name:		THOMAS TEELING

CON EDISON (Continued) **1018280426**

Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking

CON EDISON (Continued) **1018280426**

Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150318
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150318
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

CON EDISON (Continued) **1018280426**

Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067706405

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018280426
Registry ID:	110067706405
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067706405
Name:	CON EDISON
Address:	400 W 23RD ST
City,State,Zip:	NEW YORK, NY 10011

AK570 **535 WEST 19TH STREET DEVELOPMENT SITE** **NY UST** **U004061766**
NW **535 WEST 19TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.161 mi.
849 ft. **Site 11 of 18 in cluster AK**

Relative:
Lower

Actual:
8 ft.

UST:

Name:	535 WEST 19TH STREET DEVELOPMENT SITE
Address:	535 WEST 19TH STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-610314 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583841.40820
UTM Y:	4511002.08241
Site Type:	Other

Affiliation Records:

Site Id:	369159
Affiliation Type:	Facility Owner
Company Name:	WEST CHELSEA DEVELOPMENT PARTNERS, INC.
Contact Type:	AUTHORIZED SIGNATORY
Contact Name:	CRAIG WOOD
Address1:	460 PARK AVENUE, 22ND FL
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(212) 751-5432

535 WEST 19TH STREET DEVELOPMENT SITE (Continued) **U004061766**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-08-22

Site Id:	369159
Affiliation Type:	Mail Contact
Company Name:	ROUX ASSOCIATES, INC.
Contact Type:	Not reported
Contact Name:	NATHAN EPLER
Address1:	209 SHAFTER STREET
Address2:	Not reported
City:	ISLANDIA
State:	NY
Zip Code:	11749
Country Code:	001
Phone:	(631) 232-2600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-08-22

Site Id:	369159
Affiliation Type:	Facility Operator
Company Name:	535 WEST 19TH STREET DEVELOPMENT SITE
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	N/A
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-08-22

Site Id:	369159
Affiliation Type:	Emergency Contact
Company Name:	WEST CHELSEA DEVELOPMENT PARTNERS, INC.
Contact Type:	Not reported
Contact Name:	CRAIG WOOD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 343-1700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-08-22

535 WEST 19TH STREET DEVELOPMENT SITE (Continued) **U004061766**

Tank Info:

Tank Number:	1
Tank ID:	213244
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	02/02/2006
Date Tank Closed:	02/02/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	2
Tank ID:	213245
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	02/02/2006
Date Tank Closed:	02/02/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	04/14/2017

535 WEST 19TH STREET DEVELOPMENT SITE (Continued) **U004061766**

Equipment Records:

L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
J00 - Dispenser - None

Tank Number:	3
Tank ID:	213246
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	02/02/2006
Date Tank Closed:	02/02/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	04/14/2017

Equipment Records:

J00 - Dispenser - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

AK571 **535 WEST 19TH STREET RE-DEVELOPMENT SITE** **NY BROWNFIELDS** **S107488445**
NW **535 WEST 19TH STREET** **NY Spills** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.161 mi.
849 ft. **Site 12 of 18 in cluster AK**

Relative: **Lower**
Actual: **8 ft.**

BROWNFIELDS:

Name:	535 WEST 19TH STREET RE-DEVELOPMENT SITE
Address:	535 WEST 19TH STREET
City,State,Zip:	NEW YORK, NY 10011
Program:	BCP
Site Code:	370424
Acres:	0.290
HW Code:	C231056
SWIS:	3101
Town:	New York City
Record Added Date:	09/18/2006
Record Updated Date:	12/07/2009
Update By:	MOBARRIE
Site Description:	"See V00530"
Env Problem:	""
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	NNN
Owner Name:	CRAIG WOOD
Owner Company:	WEST CHELSEA DEVELOPMENT PARTNERS, LLC
Owner Address:	150 LAFAYETTE STREET, 9TH FLOOR
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10013
Owner Country:	United States of America
Own Op:	6
Sub Type:	NNN
Owner Name:	CRAIG D. WOOD
Owner Company:	WEST CHELSEA DEVELOPMENT PARTNERS, LLC
Owner Address:	150 LAFAYETTE STREET, 9TH FLOOR
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10013
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	RANDOLPH PRICE
Owner Company:	CONSOLIDATED EDISON COMPANY OF NEW YORK, INC.
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	6

535 WEST 19TH STREET RE-DEVELOPMENT SITE (Continued) **S107488445**

Sub Type:	NNN
Owner Name:	RANDOLPH PRICE
Owner Company:	CONSOLIDATED EDISON COMPANY OF NEW YORK. INC.
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	PARKING LOT
Address:	535 WEST 19TH STREET
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0509807 / 2006-07-18
Facility ID:	0509807
Facility Type:	ER
DER Facility ID:	305676
Site ID:	355643
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	3101
Spill Date:	2005-11-16
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2005-11-16
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-11-16
Spill Record Last Update:	2006-08-17
Spiller Name:	NATHAN EMPLIER
Spiller Company:	PARKING LOT
Spiller Address:	535 WEST 19TH STREET
Spiller Company:	001
Contact Name:	NATHAN EMPLIER
DEC Memo:	"Need to trace owner of site and then send Contaminated Soil Letter. 05/17/06-Vought-Spill transferred from DEC Vought to DEC Ketani as per DEC Austin. 6/21/06 - Raphael Ketani. I reached Nathan Epler of Roux Associates (631) 232-2600. He said that he had sent in all of the paperwork some time ago. I told him that DEC had nothing for the

535 WEST 19TH STREET RE-DEVELOPMENT SITE (Continued) **S107488445**

case. He said he will get back to me. The 3 550 gal. tanks mentioned in the spill report are not on any PBS record. Mr. Epler and an associate called me back. They said that the tanks had already been removed, along with the liquids they contained and the soil that was found to be contaminated. I asked them for the manifests, pictures, a site plan, clean end point sample results, and a PBS registration form. They said they had all of that and that they will send it to me by the beginning of next week. 7/5/06 - Raphael Ketani. Chris Batista of Roux called to say that he has the manifests, soil analytical results, and soon the signed PBS registration form. He said he will send them very soon. 7/17/06 - Raphael Ketani. I received the closure report today. 7/18/06 - Raphael Ketani. I reviewed the closure report and found it to be acceptable. Based upon the analytical results, pictures, manifests, and narrative in the 7/13/06 closure report from Roux Associates, I am closing the spill case. 8/17/06 - Raphael Ketani. I received a cover letter from ROUX Associates date 7/14/06. The letter was given to me by Nick Lombardo of the PBS Unit. He said that PBS application was alright and that he received a check with the application. I will have the document E-DOCed."

Remarks: "DURING A PHASE TWO INVESTIGATION FOUND CONTAMINATED AND FOUND THREE 550 GALLON TANKS: DID NOT REMOVE AS OF YET:"

All Materials:

Site ID:	355643
Operable Unit ID:	1112991
Operable Unit:	01
Material ID:	2103037
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AK572 **WEST CHELSEA DEVELOPMENT PARTNERS LLC** **RCRA-VSQG** **1010328220**
NW **535 W 19TH ST - VACANT LOT** **NY MANIFEST** **NYR000142117**
1/8-1/4 **NEW YORK, NY 10014**
0.161 mi.
849 ft. **Site 13 of 18 in cluster AK**

Relative: **Lower**
Actual: **8 ft.**

RCRA-VSQG:

Date Form Received by Agency:	20070101
Handler Name:	WEST CHELSEA DEVELOPMENT PARTNERS LLC
Handler Address:	535 W 19TH ST - VACANT LOT
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYR000142117
Contact Name:	JOHN MCMULLEN
Contact Address:	LAFAYETTE ST - 9TH FLOOR
Contact City,State,Zip:	NEW YORK, NY 10013
Contact Telephone:	212-343-1700
Contact Fax:	Not reported
Contact Email:	JMCMULLEN@CAPEADVISORS.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private

WEST CHELSEA DEVELOPMENT PARTNERS LLC (Continued) **1010328220**

Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	LAFAYETTE ST - 9TH FLOOR
Mailing City,State,Zip:	NEW YORK, NY 10013
Owner Name:	WEST CHELSEA DEVELOPMENT PARTNERS LLC
Owner Type:	Private
Operator Name:	GOTHAM CONSTRUCTION CO LLC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No

WEST CHELSEA DEVELOPMENT PARTNERS LLC (Continued) **1010328220**

Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	GOTHAM CONSTRUCTION CO LLC
Legal Status:	Private
Date Became Current:	20060405
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WEST CHELSEA DEVELOPMENT PARTNERS LLC
Legal Status:	Private
Date Became Current:	20051221
Date Ended Current:	Not reported
Owner/Operator Address:	150 LAFAYETTE ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10013
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WEST CHELSEA DEVELOPMENT PARTNERS LLC
Legal Status:	Private
Date Became Current:	20051221
Date Ended Current:	Not reported
Owner/Operator Address:	150 LAFAYETTE ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10013
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	GOTHAM CONSTRUCTION CO LLC

WEST CHELSEA DEVELOPMENT PARTNERS LLC (Continued) **1010328220**

Legal Status: Private
Date Became Current: 20060405
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20061005
Handler Name: WEST CHELSEA DEVELOPMENT PARTNERS LLC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: WEST CHELSEA DEVELOPMENT PARTNERS LLC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20061006
Handler Name: WEST CHELSEA DEVELOPMENT PARTNERS LLC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:

NAICS Code: 81293
NAICS Description: PARKING LOTS AND GARAGES

Facility Has Received Notices of Violations:

Violations: No Violations Found

WEST CHELSEA DEVELOPMENT PARTNERS LLC (Continued) **1010328220**

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	WEST CHELSEA DEV PARTNERS LLC
Address:	535 W 19TH ST - VACANT LOT
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYR000142117
Facility Status:	Not reported
Location Address 1:	535 WEST 19TH STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10001
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000142117
Mailing Name:	WEST CHELSEA DEV PARTNERS LLC
Mailing Contact:	WEST CHELSEA DEV PARTNERS LLC
Mailing Address 1:	535 WEST 19TH STREET
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10001
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6106370963

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	10/13/2006
Trans1 Recv Date:	10/13/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/13/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000142117
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000476789JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N

WEST CHELSEA DEVELOPMENT PARTNERS LLC (Continued) **1010328220**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	51680
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AK573 **84-11 ELMHURST AVE/QUEENS** **NY LTANKS** **S102671441**
NW **84-11 EILMHURST AVENUE** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.161 mi.
852 ft. **Site 14 of 18 in cluster AK**

Relative: LTANKS:
Lower

Name:	84-11 ELMHURST AVE/QUEENS
Address:	84-11 EILMHURST AVENUE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8907043 / 1992-12-08
Facility ID:	8907043
Site ID:	113979
Spill Date:	1989-10-17
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1992-12-08
SWIS:	4101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1989-10-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-10-20

Actual:
6 ft.

84-11 ELMHURST AVE/QUEENS (Continued) **S102671441**

Spill Record Last Update:	1992-12-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	99447
DEC Memo:	""
Remarks:	"GAUGE ON TANK WAS FAULTY, HESS SENDING OUT CLEAN UP CREW."

All Materials:

Site ID:	113979
Operable Unit ID:	932131
Operable Unit:	01
Material ID:	443843
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AK574 **84-11 ELMHURST AV/QUEENS** **NY LTANKS** **S102671654**
NW **84-11 ELMHURST AVENUE** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.161 mi.
852 ft. **Site 15 of 18 in cluster AK**

Relative: **Lower**
Actual: **6 ft.**

LTANKS:

Name:	84-11 ELMHURST AV/QUEENS
Address:	84-11 ELMHURST AVENUE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9012626 / 1991-03-11
Facility ID:	9012626
Site ID:	279195
Spill Date:	1991-03-08
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1991-03-11
SWIS:	4101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1991-03-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0

84-11 ELMHURST AV/QUEENS (Continued) **S102671654**

Date Entered In Computer:	1991-03-15
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	LACERETOSA PETRO
Spiller Address:	12605 36TH AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	226703
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE "
Remarks:	"TANK OVERFILL, SPEEDY DRY APPLIED,CLEANED UP BY PETROLEUM CO."

All Materials:

Site ID:	279195
Operable Unit ID:	949809
Operable Unit:	01
Material ID:	429096
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AK575 **86-11 34TH AVENUE** **NY LTANKS** **S102671387**
NW **86-11 34TH AVENUE** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.163 mi.
861 ft. **Site 16 of 18 in cluster AK**

Relative:
Lower

Actual:
6 ft.

LTANKS:

Name:	86-11 34TH AVENUE
Address:	86-11 34TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8900634 / 2003-03-04
Facility ID:	8900634
Site ID:	240000
Spill Date:	1989-04-20
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	FINGER
Referred To:	Not reported
Reported to Dept:	1989-04-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False

86-11 34TH AVENUE (Continued) **S102671387**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-04-20
Spill Record Last Update:	2003-04-15
Spiller Name:	Not reported
Spiller Company:	AMERADA HESS
Spiller Address:	420 HOOK ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	197417
DEC Memo:	""
Remarks:	"CUSTOMER SERVICE FROM AMERADA HESS ON WAY TO SCENE TO ASSESS THE EXTENT OF THE CLEAN UP."

All Materials:

Site ID:	240000
Operable Unit ID:	926916
Operable Unit:	01
Material ID:	451968
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AP576 **TIME WARNER CABLE OFFICES** **NY UST** **U004064676**
NNW **511 WEST 21ST STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.163 mi.
861 ft. **Site 1 of 6 in cluster AP**

Relative: **Lower**
Actual: **10 ft.**

UST:

Name:	TIME WARNER CABLE OFFICES
Address:	511 WEST 21ST STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-285919 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584007.51842
UTM Y:	4511108.13116
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	12731
Affiliation Type:	Mail Contact
Company Name:	FLEMING-LEE SHUE, INC.
Contact Type:	Not reported
Contact Name:	ARNOLD FLEMING-ENVIRONMENTAL CONSULTANT
Address1:	158 WEST 29TH STREET, 9TH FL.
Address2:	Not reported

TIME WARNER CABLE OFFICES (Continued) **U004064676**

City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 675-3225
EMail:	ARNIE@FLEMINGLEESHUE.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2016-12-02

Site Id:	12731
Affiliation Type:	Facility Operator
Company Name:	TIME WARNER CABLE OFFICES
Contact Type:	Not reported
Contact Name:	N'A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2016-12-02

Site Id:	12731
Affiliation Type:	Emergency Contact
Company Name:	510 WEST 22ND STRETT OWNER, LLC
Contact Type:	Not reported
Contact Name:	ARNOLD FLEMING
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 675-3225
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2016-12-02

Site Id:	12731
Affiliation Type:	Facility Owner
Company Name:	510 WEST 22ND STRETT OWNER, LLC
Contact Type:	AUTHORIZED PERSON
Contact Name:	CHRISTOPHER ALBANESE
Address1:	1050 FRANKLIN AVE., C/O ALBANESE ORG.
Address2:	Not reported
City:	GARDEN CITY
State:	NY
Zip Code:	10002
Country Code:	001
Phone:	(516) 746-6000
EMail:	Not reported

TIME WARNER CABLE OFFICES (Continued) **U004064676**

Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2016-12-02

Tank Info:

Tank Number:	101
Tank ID:	47834
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	03/01/1990
Date Tank Closed:	10/11/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	CGFREEDM
Last Modified:	04/14/2017

Equipment Records:

J01 - Dispenser - Pressurized Dispenser
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	102
Tank ID:	47835
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	03/01/1990
Date Tank Closed:	10/11/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	CGFREEDM

TIME WARNER CABLE OFFICES (Continued) **U004064676**

Last Modified: 04/14/2017

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass

Tank Number: 103
Tank ID: 47836
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/01/1990
Date Tank Closed: 10/11/2007
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: CGFREEDM
Last Modified: 04/14/2017

Equipment Records:

B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J00 - Dispenser - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 106
Tank ID: 264985
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 08/11/2016
Date Tank Closed: 08/11/2016
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: -

TIME WARNER CABLE OFFICES (Continued) **U004064676**

Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	ACDANIEL
Last Modified:	04/14/2017

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None

AP577 **TIME WARNER CABLE** **NY AST** **U003074535**
NNW **511 WEST 21ST ST** **NY ENG CONTROLS** **N/A**
1/8-1/4 **NEW YORK, NY 10011** **NY INST CONTROL**
0.163 mi. **NY BROWNFIELDS**
861 ft. **Site 2 of 6 in cluster AP** **NY Spills**

Relative:
Lower

Actual:
10 ft.

AST:

Name:	TIME WARNER CABLE OFFICES
Address:	511 WEST 21ST STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-285919
Program Type:	PBS
UTM X:	584007.51842
UTM Y:	4511108.13116
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	12731
Affiliation Type:	Mail Contact
Company Name:	FLEMING-LEE SHUE, INC.
Contact Type:	Not reported
Contact Name:	ARNOLD FLEMING-ENVIRONMENTAL CONSULTANT
Address1:	158 WEST 29TH STREET, 9TH FL.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 675-3225
EMail:	ARNIE@FLEMINGLEESHUE.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2016-12-02

Site Id:	12731
Affiliation Type:	Facility Operator

TIME WARNER CABLE (Continued) **U003074535**

Company Name:	TIME WARNER CABLE OFFICES
Contact Type:	Not reported
Contact Name:	N'A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2016-12-02

Site Id:	12731
Affiliation Type:	Emergency Contact
Company Name:	510 WEST 22ND STRETT OWNER, LLC
Contact Type:	Not reported
Contact Name:	ARNOLD FLEMING
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 675-3225
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2016-12-02

Site Id:	12731
Affiliation Type:	Facility Owner
Company Name:	510 WEST 22ND STRETT OWNER, LLC
Contact Type:	AUTHORIZED PERSON
Contact Name:	CHRISTOPHER ALBANESE
Address1:	1050 FRANKLIN AVE., C/O ALBANESE ORG.
Address2:	Not reported
City:	GARDEN CITY
State:	NY
Zip Code:	10002
Country Code:	001
Phone:	(516) 746-6000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2016-12-02

Tank Info:

Tank Number:	001
Tank Id:	17644
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

TIME WARNER CABLE (Continued) **U003074535**

Equipment Records:
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	CGFREEDM
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)
Tank Number:	104
Tank Id:	47837
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
I01 - Overfill - Float Vent Valve
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
J00 - Dispenser - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	05/01/1994
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/11/2007
Register:	True
Modified By:	CGFREEDM

TIME WARNER CABLE (Continued) **U003074535**

Last Modified: 04/14/2017
Material Name: other

Tank Number: 105
Tank Id: 47838
Material Code: 9999
Common Name of Substance: Other

Equipment Records:
D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 03/01/1990
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 10/11/2007
Register: True
Modified By: CGFREEDM
Last Modified: 04/14/2017
Material Name: other

ENG CONTROLS:
Name: 511 WEST 21ST STREET
Address: 511 WEST 21ST STREET
City,State,Zip: NEWYORK, NY 10011
Site Code: 475372
HW Code: C231080
Control Code: 15
Control Type: ENG
Date Record Added: 10/03/2016
Date Rec Updated: 09/08/2021
Updated By: JXPEREZM
Site Description: "Location: The site is located at 511 West 21st Street in Manhattan, NY. The property is bounded by West 21st Street to the south and West 22nd Street to the north between 10th Avenue and 11th Avenue in Manhattan. The property has frontage on the north side of West 21st Street and the south side of West 22nd Street. Site Features: The site is approximately 0.45 acres in size, is currently an active construction site and there are no site occupants. The property is flat with average elevation approximately 10 feet above mean sea level and the elevated High Line Park runs along the eastern property boundary. Current Zoning and Land Use: The area is zoned for

TIME WARNER CABLE (Continued) **U003074535**

	manufacturing and commercial use, and the City's zoning code for the site is M1-5. Past Use of the Site: The site has been used for manufacturing by a gas meter company and also as a service station. Most recently it has been used by a television cable company for vehicle parking and maintenance, storage and offices. Site Geology and Hydrogeology: The site is underlain by 13 to 17 feet of man-made/historic fill. Native soils beneath the fill layer consist of organic silty clay of estuarine origin as well as sand and silt of glacial origin. The depth-to-bedrock varies from approximately 33 feet below grade at the northern end of the site to 65 feet below grade at the southern end of the site. The depth-to-groundwater at the site is approximately 6 to 7 feet below sidewalk grade and the local groundwater flow direction is to the southwest."
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included metals, semi-volatile organic compounds (SVOCs), and volatile organic compounds (VOCs)in soil and /or groundwater. Remedial actions have successfully achieved soil cleanup objectives for commercial use. A Site Management Plan (SMP) will be implemented to manage remaining contamination in the future. An environmental easement will limit the future use of property, restrict the use of groundwater and require compliance with the SMP. All engineering controls (e.g., soil cover/cap) of the remedy will be operated and maintained under the SMP."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2012-11-20 15:11:00
Record Upd:	2016-11-16 15:41:00
Updated By:	JXPEREZM
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New York Public Library
Owner Address:	Muhlenberg Branch
Owner Addr2:	209 West 23rd Street
Owner City,St,Zip:	New York, NY 10011-2379
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	MARTIN DETTLING
Owner Company:	510 West 22nd Street Partners LLC
Owner Address:	c/o Albanese Development Corporation
Owner Addr2:	1050 Franklin Avenue
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Christopher Albanese

TIME WARNER CABLE (Continued) **U003074535**

Owner Company:	510 West 22nd Street Owner, LLC
Owner Address:	c/o Albanese Organization, Inc
Owner Addr2:	1050 Franklin Avenue
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	MARTIN DETTLING
Owner Company:	510 West 22nd Street Owner, LLC
Owner Address:	c/o Albanese Organization, Inc.
Owner Addr2:	1050 FRANKLIN AVENUE
Owner City,St,Zip:	GARDEN CITY, NY 11530
Owner Country:	United States of America
HW Code:	C231080
Waste Type:	ETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231080
Waste Type:	METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231080
Waste Type:	DIBENZ[A,H]ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231080
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231080
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231080
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231080
Waste Type:	METHYL ETHYL KETONE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231080
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231080
Waste Type:	COPPER
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231080
Waste Type:	DICHLORODIFLUOROMETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	1309055
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2013-12-11 14:05:00

TIME WARNER CABLE (Continued) **U003074535**

Record Updated:	2013-12-11 14:05:00
Updated By:	JXPEREZM
Crossref ID:	8907798
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2012-11-23 11:18:00
Record Updated:	2012-11-23 11:18:00
Updated By:	JDJARRAT
Crossref ID:	0010394
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2012-11-23 11:19:00
Record Updated:	2012-11-23 11:19:00
Updated By:	JDJARRAT
Crossref ID:	2-285919
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2012-11-23 11:21:00
Record Updated:	2012-11-23 11:21:00
Updated By:	JDJARRAT
Crossref ID:	2016000216749
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2016-07-11 15:58:00
Record Updated:	2016-07-11 15:58:00
Updated By:	JEBROWN
Crossref ID:	C231080+02+13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2016-11-16 15:43:00
Record Updated:	2016-11-16 15:43:00
Updated By:	JXPEREZM

INST CONTROL:

Name:	511 WEST 21ST STREET
Address:	511 WEST 21ST STREET
City,State,Zip:	NEWYORK, NY 10011
Site Code:	475372
Control Name:	Ground Water Use Restriction
HW Code:	C231080
Control Code:	08
Control Type:	INST
Dt record added:	10/03/2016
Dt rec updated:	09/08/2021
Updated By:	JXPEREZM
Site Code:	475372
Site Description:	"Location: The site is located at 511 West 21st Street in Manhattan, NY. The property is bounded by West 21st Street to the south and West 22nd Street to the north between 10th Avenue and 11th Avenue in Manhattan. The property has frontage on the north side of West 21st Street and the south side of West 22nd Street. Site Features: The site is approximately 0.45 acres in size, is currently an active construction site and there are no site occupants. The property is flat with average elevation approximately 10 feet above mean sea level and the elevated High Line Park runs along the eastern property boundary. Current Zoning and Land Use: The area is zoned for manufacturing and commercial use, and the City's zoning code for the

TIME WARNER CABLE (Continued) **U003074535**

site is M1-5. Past Use of the Site: The site has been used for manufacturing by a gas meter company and also as a service station. Most recently it has been used by a television cable company for vehicle parking and maintenance, storage and offices. Site Geology and Hydrogeology: The site is underlain by 13 to 17 feet of man-made/historic fill. Native soils beneath the fill layer consist of organic silty clay of estuarine origin as well as sand and silt of glacial origin. The depth-to-bedrock varies from approximately 33 feet below grade at the northern end of the site to 65 feet below grade at the southern end of the site. The depth-to-groundwater at the site is approximately 6 to 7 feet below sidewalk grade and the local groundwater flow direction is to the southwest."

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included metals, semi-volatile organic compounds (SVOCs), and volatile organic compounds (VOCs)in soil and /or groundwater. Remedial actions have successfully achieved soil cleanup objectives for commercial use. A Site Management Plan (SMP) will be implemented to manage remaining contamination in the future. An environmental easement will limit the future use of property, restrict the use of groundwater and require compliance with the SMP. All engineering controls (e.g., soil cover/cap) of the remedy will be operated and maintained under the SMP."

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-11-20 15:11:00
Record Upd: 2016-11-16 15:41:00
Updated By: JXPEREZM
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: New York Public Library
Owner Address: Muhlenberg Branch
Owner Addr2: 209 West 23rd Street
Owner City,St,Zip: New York, NY 10011-2379
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: MARTIN DETTLING
Owner Company: 510 West 22nd Street Partners LLC
Owner Address: c/o Albanese Development Corporation
Owner Addr2: 1050 Franklin Avenue
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Christopher Albanese
Owner Company: 510 West 22nd Street Owner, LLC

TIME WARNER CABLE (Continued) **U003074535**

Owner Address: c/o Albanese Organization, Inc
Owner Addr2: 1050 Franklin Avenue
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: MARTIN DETTLING
Owner Company: 510 West 22nd Street Owner, LLC
Owner Address: c/o Albanese Organization, Inc.
Owner Addr2: 1050 FRANKLIN AVENUE
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
HW Code: C231080
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: METHYL ETHYL KETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: DICHLORODIFLUOROMETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1309055
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-12-11 14:05:00
Record Updated: 2013-12-11 14:05:00

TIME WARNER CABLE (Continued) **U003074535**

Updated By: JXPEREZM
Crossref ID: 8907798
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2012-11-23 11:18:00
Record Updated: 2012-11-23 11:18:00
Updated By: JDJARRAT
Crossref ID: 0010394
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2012-11-23 11:19:00
Record Updated: 2012-11-23 11:19:00
Updated By: JDJARRAT
Crossref ID: 2-285919
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2012-11-23 11:21:00
Record Updated: 2012-11-23 11:21:00
Updated By: JDJARRAT
Crossref ID: 2016000216749
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-07-11 15:58:00
Record Updated: 2016-07-11 15:58:00
Updated By: JEBROWN
Crossref ID: C231080+02+13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-11-16 15:43:00
Record Updated: 2016-11-16 15:43:00
Updated By: JXPEREZM

Name: 511 WEST 21ST STREET
Address: 511 WEST 21ST STREET
City,State,Zip: NEWYORK, NY 10011
Site Code: 475372
Control Name: Soil Management Plan
HW Code: C231080
Control Code: 14
Control Type: INST
Dt record added: 10/03/2016
Dt rec updated: 09/08/2021
Updated By: JXPEREZM
Site Code: 475372
Site Description: "Location: The site is located at 511 West 21st Street in Manhattan, NY. The property is bounded by West 21st Street to the south and West 22nd Street to the north between 10th Avenue and 11th Avenue in Manhattan. The property has frontage on the north side of West 21st Street and the south side of West 22nd Street. Site Features: The site is approximately 0.45 acres in size, is currently an active construction site and there are no site occupants. The property is flat with average elevation approximately 10 feet above mean sea level and the elevated High Line Park runs along the eastern property boundary. Current Zoning and Land Use: The area is zoned for manufacturing and commercial use, and the City's zoning code for the site is M1-5. Past Use of the Site: The site has been used for manufacturing by a gas meter company and also as a service station.

TIME WARNER CABLE (Continued) **U003074535**

Most recently it has been used by a television cable company for vehicle parking and maintenance, storage and offices. Site Geology and Hydrogeology: The site is underlain by 13 to 17 feet of man-made/historic fill. Native soils beneath the fill layer consist of organic silty clay of estuarine origin as well as sand and silt of glacial origin. The depth-to-bedrock varies from approximately 33 feet below grade at the northern end of the site to 65 feet below grade at the southern end of the site. The depth-to-groundwater at the site is approximately 6 to 7 feet below sidewalk grade and the local groundwater flow direction is to the southwest."

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included metals, semi-volatile organic compounds (SVOCs), and volatile organic compounds (VOCs)in soil and /or groundwater. Remedial actions have successfully achieved soil cleanup objectives for commercial use. A Site Management Plan (SMP) will be implemented to manage remaining contamination in the future. An environmental easement will limit the future use of property, restrict the use of groundwater and require compliance with the SMP. All engineering controls (e.g., soil cover/cap) of the remedy will be operated and maintained under the SMP."

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-11-20 15:11:00
Record Upd: 2016-11-16 15:41:00
Updated By: JXPEREZM
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: New York Public Library
Owner Address: Muhlenberg Branch
Owner Addr2: 209 West 23rd Street
Owner City,St,Zip: New York, NY 10011-2379
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: MARTIN DETTLING
Owner Company: 510 West 22nd Street Partners LLC
Owner Address: c/o Albanese Development Corporation
Owner Addr2: 1050 Franklin Avenue
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Christopher Albanese
Owner Company: 510 West 22nd Street Owner, LLC
Owner Address: c/o Albanese Organization, Inc
Owner Addr2: 1050 Franklin Avenue

TIME WARNER CABLE (Continued) **U003074535**

Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: MARTIN DETTLING
Owner Company: 510 West 22nd Street Owner, LLC
Owner Address: c/o Albanese Organization, Inc.
Owner Addr2: 1050 FRANKLIN AVENUE
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
HW Code: C231080
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: METHYL ETHYL KETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: DICHLORODIFLUOROMETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1309055
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-12-11 14:05:00
Record Updated: 2013-12-11 14:05:00
Updated By: JXPEREZM
Crossref ID: 8907798

TIME WARNER CABLE (Continued) **U003074535**

Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2012-11-23 11:18:00
Record Updated: 2012-11-23 11:18:00
Updated By: JDJARRAT
Crossref ID: 0010394
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2012-11-23 11:19:00
Record Updated: 2012-11-23 11:19:00
Updated By: JDJARRAT
Crossref ID: 2-285919
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2012-11-23 11:21:00
Record Updated: 2012-11-23 11:21:00
Updated By: JDJARRAT
Crossref ID: 2016000216749
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-07-11 15:58:00
Record Updated: 2016-07-11 15:58:00
Updated By: JEBROWN
Crossref ID: C231080+02+13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-11-16 15:43:00
Record Updated: 2016-11-16 15:43:00
Updated By: JXPEREZM

Name: 511 WEST 21ST STREET
Address: 511 WEST 21ST STREET
City,State,Zip: NEWYORK, NY 10011
Site Code: 475372
Control Name: Landuse Restriction
HW Code: C231080
Control Code: 25
Control Type: INST
Dt record added: 10/03/2016
Dt rec updated: 09/08/2021
Updated By: JXPEREZM
Site Code: 475372
Site Description: "Location: The site is located at 511 West 21st Street in Manhattan, NY. The property is bounded by West 21st Street to the south and West 22nd Street to the north between 10th Avenue and 11th Avenue in Manhattan. The property has frontage on the north side of West 21st Street and the south side of West 22nd Street. Site Features: The site is approximately 0.45 acres in size, is currently an active construction site and there are no site occupants. The property is flat with average elevation approximately 10 feet above mean sea level and the elevated High Line Park runs along the eastern property boundary. Current Zoning and Land Use: The area is zoned for manufacturing and commercial use, and the City's zoning code for the site is M1-5. Past Use of the Site: The site has been used for manufacturing by a gas meter company and also as a service station. Most recently it has been used by a television cable company for vehicle parking and maintenance, storage and offices. Site Geology

TIME WARNER CABLE (Continued) **U003074535**

and Hydrogeology: The site is underlain by 13 to 17 feet of man-made/historic fill. Native soils beneath the fill layer consist of organic silty clay of estuarine origin as well as sand and silt of glacial origin. The depth-to-bedrock varies from approximately 33 feet below grade at the northern end of the site to 65 feet below grade at the southern end of the site. The depth-to-groundwater at the site is approximately 6 to 7 feet below sidewalk grade and the local groundwater flow direction is to the southwest."

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included metals, semi-volatile organic compounds (SVOCs), and volatile organic compounds (VOCs)in soil and /or groundwater. Remedial actions have successfully achieved soil cleanup objectives for commercial use. A Site Management Plan (SMP) will be implemented to manage remaining contamination in the future. An environmental easement will limit the future use of property, restrict the use of groundwater and require compliance with the SMP. All engineering controls (e.g., soil cover/cap) of the remedy will be operated and maintained under the SMP."

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-11-20 15:11:00
Record Upd: 2016-11-16 15:41:00
Updated By: JXPEREZM
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: New York Public Library
Owner Address: Muhlenberg Branch
Owner Addr2: 209 West 23rd Street
Owner City,St,Zip: New York, NY 10011-2379
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: MARTIN DETTLING
Owner Company: 510 West 22nd Street Partners LLC
Owner Address: c/o Albanese Development Corporation
Owner Addr2: 1050 Franklin Avenue
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Christopher Albanese
Owner Company: 510 West 22nd Street Owner, LLC
Owner Address: c/o Albanese Organization, Inc
Owner Addr2: 1050 Franklin Avenue
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America

TIME WARNER CABLE (Continued) **U003074535**

Own Op: 6
Sub Type: P03
Owner Name: MARTIN DETTLING
Owner Company: 510 West 22nd Street Owner, LLC
Owner Address: c/o Albanese Organization, Inc.
Owner Addr2: 1050 FRANKLIN AVENUE
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
HW Code: C231080
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: METHYL ETHYL KETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: DICHLORODIFLUOROMETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1309055
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-12-11 14:05:00
Record Updated: 2013-12-11 14:05:00
Updated By: JXPEREZM
Crossref ID: 8907798
Cross Ref Type Code: 01
Cross Ref Type: Spill No.

TIME WARNER CABLE (Continued) **U003074535**

Record Added Date: 2012-11-23 11:18:00
Record Updated: 2012-11-23 11:18:00
Updated By: JDJARRAT
Crossref ID: 0010394
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2012-11-23 11:19:00
Record Updated: 2012-11-23 11:19:00
Updated By: JDJARRAT
Crossref ID: 2-285919
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2012-11-23 11:21:00
Record Updated: 2012-11-23 11:21:00
Updated By: JDJARRAT
Crossref ID: 2016000216749
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-07-11 15:58:00
Record Updated: 2016-07-11 15:58:00
Updated By: JEBROWN
Crossref ID: C231080+02+13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-11-16 15:43:00
Record Updated: 2016-11-16 15:43:00
Updated By: JXPEREZM

Name: 511 WEST 21ST STREET
Address: 511 WEST 21ST STREET
City,State,Zip: NEWYORK, NY 10011
Site Code: 475372
Control Name: Environmental Easement
HW Code: C231080
Control Code: J
Control Type: INST
Dt record added: 10/03/2016
Dt rec updated: 09/08/2021
Updated By: JXPEREZM
Site Code: 475372
Site Description: "Location: The site is located at 511 West 21st Street in Manhattan, NY. The property is bounded by West 21st Street to the south and West 22nd Street to the north between 10th Avenue and 11th Avenue in Manhattan. The property has frontage on the north side of West 21st Street and the south side of West 22nd Street. Site Features: The site is approximately 0.45 acres in size, is currently an active construction site and there are no site occupants. The property is flat with average elevation approximately 10 feet above mean sea level and the elevated High Line Park runs along the eastern property boundary. Current Zoning and Land Use: The area is zoned for manufacturing and commercial use, and the City's zoning code for the site is M1-5. Past Use of the Site: The site has been used for manufacturing by a gas meter company and also as a service station. Most recently it has been used by a television cable company for vehicle parking and maintenance, storage and offices. Site Geology and Hydrogeology: The site is underlain by 13 to 17 feet of man-made/historic fill. Native soils beneath the fill layer consist

TIME WARNER CABLE (Continued) **U003074535**

of organic silty clay of estuarine origin as well as sand and silt of glacial origin. The depth-to-bedrock varies from approximately 33 feet below grade at the northern end of the site to 65 feet below grade at the southern end of the site. The depth-to-groundwater at the site is approximately 6 to 7 feet below sidewalk grade and the local groundwater flow direction is to the southwest."

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included metals, semi-volatile organic compounds (SVOCs), and volatile organic compounds (VOCs)in soil and /or groundwater. Remedial actions have successfully achieved soil cleanup objectives for commercial use. A Site Management Plan (SMP) will be implemented to manage remaining contamination in the future. An environmental easement will limit the future use of property, restrict the use of groundwater and require compliance with the SMP. All engineering controls (e.g., soil cover/cap) of the remedy will be operated and maintained under the SMP."

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-11-20 15:11:00
Record Upd: 2016-11-16 15:41:00
Updated By: JXPEREZM
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: New York Public Library
Owner Address: Muhlenberg Branch
Owner Addr2: 209 West 23rd Street
Owner City,St,Zip: New York, NY 10011-2379
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: MARTIN DETTLING
Owner Company: 510 West 22nd Street Partners LLC
Owner Address: c/o Albanese Development Corporation
Owner Addr2: 1050 Franklin Avenue
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Christopher Albanese
Owner Company: 510 West 22nd Street Owner, LLC
Owner Address: c/o Albanese Organization, Inc
Owner Addr2: 1050 Franklin Avenue
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 6
Sub Type: P03

TIME WARNER CABLE (Continued) **U003074535**

Owner Name: MARTIN DETTLING
Owner Company: 510 West 22nd Street Owner, LLC
Owner Address: c/o Albanese Organization, Inc.
Owner Addr2: 1050 FRANKLIN AVENUE
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
HW Code: C231080
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: METHYL ETHYL KETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: DICHLORODIFLUOROMETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1309055
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-12-11 14:05:00
Record Updated: 2013-12-11 14:05:00
Updated By: JXPEREZM
Crossref ID: 8907798
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2012-11-23 11:18:00
Record Updated: 2012-11-23 11:18:00

TIME WARNER CABLE (Continued) **U003074535**

Updated By: JDJARRAT
Crossref ID: 0010394
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2012-11-23 11:19:00
Record Updated: 2012-11-23 11:19:00
Updated By: JDJARRAT
Crossref ID: 2-285919
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2012-11-23 11:21:00
Record Updated: 2012-11-23 11:21:00
Updated By: JDJARRAT
Crossref ID: 2016000216749
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-07-11 15:58:00
Record Updated: 2016-07-11 15:58:00
Updated By: JEBROWN
Crossref ID: C231080+02+13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-11-16 15:43:00
Record Updated: 2016-11-16 15:43:00
Updated By: JXPEREZM

Name: 511 WEST 21ST STREET
Address: 511 WEST 21ST STREET
City,State,Zip: NEWYORK, NY 10011
Site Code: 475372
Control Name: IC/EC Plan
HW Code: C231080
Control Code: 34
Control Type: INST
Dt record added: 10/03/2016
Dt rec updated: 09/08/2021
Updated By: JXPEREZM
Site Code: 475372
Site Description: "Location: The site is located at 511 West 21st Street in Manhattan, NY. The property is bounded by West 21st Street to the south and West 22nd Street to the north between 10th Avenue and 11th Avenue in Manhattan. The property has frontage on the north side of West 21st Street and the south side of West 22nd Street. Site Features: The site is approximately 0.45 acres in size, is currently an active construction site and there are no site occupants. The property is flat with average elevation approximately 10 feet above mean sea level and the elevated High Line Park runs along the eastern property boundary. Current Zoning and Land Use: The area is zoned for manufacturing and commercial use, and the City's zoning code for the site is M1-5. Past Use of the Site: The site has been used for manufacturing by a gas meter company and also as a service station. Most recently it has been used by a television cable company for vehicle parking and maintenance, storage and offices. Site Geology and Hydrogeology: The site is underlain by 13 to 17 feet of man-made/historic fill. Native soils beneath the fill layer consist of organic silty clay of estuarine origin as well as sand and silt of glacial origin. The depth-to-bedrock varies from approximately 33

TIME WARNER CABLE (Continued) **U003074535**

feet below grade at the northern end of the site to 65 feet below grade at the southern end of the site. The depth-to-groundwater at the site is approximately 6 to 7 feet below sidewalk grade and the local groundwater flow direction is to the southwest."

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included metals, semi-volatile organic compounds (SVOCs), and volatile organic compounds (VOCs)in soil and /or groundwater. Remedial actions have successfully achieved soil cleanup objectives for commercial use. A Site Management Plan (SMP) will be implemented to manage remaining contamination in the future. An environmental easement will limit the future use of property, restrict the use of groundwater and require compliance with the SMP. All engineering controls (e.g., soil cover/cap) of the remedy will be operated and maintained under the SMP."

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-11-20 15:11:00
Record Upd: 2016-11-16 15:41:00
Updated By: JXPEREZM
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: New York Public Library
Owner Address: Muhlenberg Branch
Owner Addr2: 209 West 23rd Street
Owner City,St,Zip: New York, NY 10011-2379
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: MARTIN DETTLING
Owner Company: 510 West 22nd Street Partners LLC
Owner Address: c/o Albanese Development Corporation
Owner Addr2: 1050 Franklin Avenue
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Christopher Albanese
Owner Company: 510 West 22nd Street Owner, LLC
Owner Address: c/o Albanese Organization, Inc
Owner Addr2: 1050 Franklin Avenue
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: MARTIN DETTLING
Owner Company: 510 West 22nd Street Owner, LLC

TIME WARNER CABLE (Continued) **U003074535**

Owner Address: c/o Albanese Organization, Inc.
Owner Addr2: 1050 FRANKLIN AVENUE
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
HW Code: C231080
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: METHYL ETHYL KETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: DICHLORODIFLUOROMETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1309055
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-12-11 14:05:00
Record Updated: 2013-12-11 14:05:00
Updated By: JXPEREZM
Crossref ID: 8907798
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2012-11-23 11:18:00
Record Updated: 2012-11-23 11:18:00
Updated By: JDJARRAT
Crossref ID: 0010394

TIME WARNER CABLE (Continued) **U003074535**

Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2012-11-23 11:19:00
Record Updated: 2012-11-23 11:19:00
Updated By: JDJARRAT
Crossref ID: 2-285919
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2012-11-23 11:21:00
Record Updated: 2012-11-23 11:21:00
Updated By: JDJARRAT
Crossref ID: 2016000216749
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-07-11 15:58:00
Record Updated: 2016-07-11 15:58:00
Updated By: JEBROWN
Crossref ID: C231080+02+13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-11-16 15:43:00
Record Updated: 2016-11-16 15:43:00
Updated By: JXPEREZM

Name: 511 WEST 21ST STREET
Address: 511 WEST 21ST STREET
City,State,Zip: NEWYORK, NY 10011
Site Code: 475372
Control Name: Site Management Plan
HW Code: C231080
Control Code: 32
Control Type: INST
Dt record added: 10/03/2016
Dt rec updated: 09/08/2021
Updated By: JXPEREZM
Site Code: 475372
Site Description: "Location: The site is located at 511 West 21st Street in Manhattan, NY. The property is bounded by West 21st Street to the south and West 22nd Street to the north between 10th Avenue and 11th Avenue in Manhattan. The property has frontage on the north side of West 21st Street and the south side of West 22nd Street. Site Features: The site is approximately 0.45 acres in size, is currently an active construction site and there are no site occupants. The property is flat with average elevation approximately 10 feet above mean sea level and the elevated High Line Park runs along the eastern property boundary. Current Zoning and Land Use: The area is zoned for manufacturing and commercial use, and the City's zoning code for the site is M1-5. Past Use of the Site: The site has been used for manufacturing by a gas meter company and also as a service station. Most recently it has been used by a television cable company for vehicle parking and maintenance, storage and offices. Site Geology and Hydrogeology: The site is underlain by 13 to 17 feet of man-made/historic fill. Native soils beneath the fill layer consist of organic silty clay of estuarine origin as well as sand and silt of glacial origin. The depth-to-bedrock varies from approximately 33 feet below grade at the northern end of the site to 65 feet below grade at the southern end of the site. The depth-to-groundwater at

TIME WARNER CABLE (Continued) **U003074535**

	the site is approximately 6 to 7 feet below sidewalk grade and the local groundwater flow direction is to the southwest."
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included metals, semi-volatile organic compounds (SVOCs), and volatile organic compounds (VOCs)in soil and /or groundwater. Remedial actions have successfully achieved soil cleanup objectives for commercial use. A Site Management Plan (SMP) will be implemented to manage remaining contamination in the future. An environmental easement will limit the future use of property, restrict the use of groundwater and require compliance with the SMP. All engineering controls (e.g., soil cover/cap) of the remedy will be operated and maintained under the SMP."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2012-11-20 15:11:00
Record Upd:	2016-11-16 15:41:00
Updated By:	JXPEREZM
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New York Public Library
Owner Address:	Muhlenberg Branch
Owner Addr2:	209 West 23rd Street
Owner City,St,Zip:	New York, NY 10011-2379
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	MARTIN DETTLING
Owner Company:	510 West 22nd Street Partners LLC
Owner Address:	c/o Albanese Development Corporation
Owner Addr2:	1050 Franklin Avenue
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Christopher Albanese
Owner Company:	510 West 22nd Street Owner, LLC
Owner Address:	c/o Albanese Organization, Inc
Owner Addr2:	1050 Franklin Avenue
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	MARTIN DETTLING
Owner Company:	510 West 22nd Street Owner, LLC
Owner Address:	c/o Albanese Organization, Inc.
Owner Addr2:	1050 FRANKLIN AVENUE

TIME WARNER CABLE (Continued) **U003074535**

Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
HW Code: C231080
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: METHYL ETHYL KETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: DICHLORODIFLUOROMETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1309055
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-12-11 14:05:00
Record Updated: 2013-12-11 14:05:00
Updated By: JXPEREZM
Crossref ID: 8907798
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2012-11-23 11:18:00
Record Updated: 2012-11-23 11:18:00
Updated By: JDJARRAT
Crossref ID: 0010394
Cross Ref Type Code: 01
Cross Ref Type: Spill No.

TIME WARNER CABLE (Continued) **U003074535**

Record Added Date: 2012-11-23 11:19:00
Record Updated: 2012-11-23 11:19:00
Updated By: JDJARRAT
Crossref ID: 2-285919
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2012-11-23 11:21:00
Record Updated: 2012-11-23 11:21:00
Updated By: JDJARRAT
Crossref ID: 2016000216749
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-07-11 15:58:00
Record Updated: 2016-07-11 15:58:00
Updated By: JEBROWN
Crossref ID: C231080+02+13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-11-16 15:43:00
Record Updated: 2016-11-16 15:43:00
Updated By: JXPEREZM

Name: 511 WEST 21ST STREET
Address: 511 WEST 21ST STREET
City,State,Zip: NEWYORK, NY 10011
Site Code: 475372
Control Name: Monitoring Plan
HW Code: C231080
Control Code: 31
Control Type: INST
Dt record added: 10/03/2016
Dt rec updated: 09/08/2021
Updated By: JXPEREZM
Site Code: 475372
Site Description: "Location: The site is located at 511 West 21st Street in Manhattan, NY. The property is bounded by West 21st Street to the south and West 22nd Street to the north between 10th Avenue and 11th Avenue in Manhattan. The property has frontage on the north side of West 21st Street and the south side of West 22nd Street. Site Features: The site is approximately 0.45 acres in size, is currently an active construction site and there are no site occupants. The property is flat with average elevation approximately 10 feet above mean sea level and the elevated High Line Park runs along the eastern property boundary. Current Zoning and Land Use: The area is zoned for manufacturing and commercial use, and the City's zoning code for the site is M1-5. Past Use of the Site: The site has been used for manufacturing by a gas meter company and also as a service station. Most recently it has been used by a television cable company for vehicle parking and maintenance, storage and offices. Site Geology and Hydrogeology: The site is underlain by 13 to 17 feet of man-made/historic fill. Native soils beneath the fill layer consist of organic silty clay of estuarine origin as well as sand and silt of glacial origin. The depth-to-bedrock varies from approximately 33 feet below grade at the northern end of the site to 65 feet below grade at the southern end of the site. The depth-to-groundwater at the site is approximately 6 to 7 feet below sidewalk grade and the local groundwater flow direction is to the southwest."

TIME WARNER CABLE (Continued) **U003074535**

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included metals, semi-volatile organic compounds (SVOCs), and volatile organic compounds (VOCs)in soil and /or groundwater. Remedial actions have successfully achieved soil cleanup objectives for commercial use. A Site Management Plan (SMP) will be implemented to manage remaining contamination in the future. An environmental easement will limit the future use of property, restrict the use of groundwater and require compliance with the SMP. All engineering controls (e.g., soil cover/cap) of the remedy will be operated and maintained under the SMP."
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site."
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-11-20 15:11:00
Record Upd: 2016-11-16 15:41:00
Updated By: JXPEREZM
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: New York Public Library
Owner Address: Muhlenberg Branch
Owner Addr2: 209 West 23rd Street
Owner City,St,Zip: New York, NY 10011-2379
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: MARTIN DETTLING
Owner Company: 510 West 22nd Street Partners LLC
Owner Address: c/o Albanese Development Corporation
Owner Addr2: 1050 Franklin Avenue
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Christopher Albanese
Owner Company: 510 West 22nd Street Owner, LLC
Owner Address: c/o Albanese Organization, Inc
Owner Addr2: 1050 Franklin Avenue
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: MARTIN DETTLING
Owner Company: 510 West 22nd Street Owner, LLC
Owner Address: c/o Albanese Organization, Inc.
Owner Addr2: 1050 FRANKLIN AVENUE
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America

TIME WARNER CABLE (Continued) **U003074535**

HW Code: C231080
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: METHYL ETHYL KETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C231080
Waste Type: DICHLORODIFLUOROMETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1309055
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-12-11 14:05:00
Record Updated: 2013-12-11 14:05:00
Updated By: JXPEREZM
Crossref ID: 8907798
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2012-11-23 11:18:00
Record Updated: 2012-11-23 11:18:00
Updated By: JDJARRAT
Crossref ID: 0010394
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2012-11-23 11:19:00
Record Updated: 2012-11-23 11:19:00

TIME WARNER CABLE (Continued) **U003074535**

Updated By: JDJARRAT
Crossref ID: 2-285919
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2012-11-23 11:21:00
Record Updated: 2012-11-23 11:21:00
Updated By: JDJARRAT
Crossref ID: 2016000216749
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-07-11 15:58:00
Record Updated: 2016-07-11 15:58:00
Updated By: JEBROWN
Crossref ID: C231080+02+13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-11-16 15:43:00
Record Updated: 2016-11-16 15:43:00
Updated By: JXPEREZM

BROWNFIELDS:

Name:	511 WEST 21ST STREET
Address:	511 WEST 21ST STREET
City,State,Zip:	NEWYORK, NY 10011
Program:	BCP
Site Code:	475372
Acres:	0.453
HW Code:	C231080
SWIS:	3101
Town:	New York City
Record Added Date:	11/20/2012
Record Updated Date:	01/26/2021
Update By:	JCGRATHW
Site Description:	"Location: The site is located at 511 West 21st Street in Manhattan, NY. The property is bounded by West 21st Street to the south and West 22nd Street to the north between 10th Avenue and 11th Avenue in Manhattan. The property has frontage on the north side of West 21st Street and the south side of West 22nd Street. Site Features: The site is approximately 0.45 acres in size, is currently an active construction site and there are no site occupants. The property is flat with average elevation approximately 10 feet above mean sea level and the elevated High Line Park runs along the eastern property boundary. Current Zoning and Land Use: The area is zoned for manufacturing and commercial use, and the City's zoning code for the site is M1-5. Past Use of the Site: The site has been used for manufacturing by a gas meter company and also as a service station. Most recently it has been used by a television cable company for vehicle parking and maintenance, storage and offices. Site Geology and Hydrogeology: The site is underlain by 13 to 17 feet of man-made/historic fill. Native soils beneath the fill layer consist of organic silty clay of estuarine origin as well as sand and silt of glacial origin. The depth-to-bedrock varies from approximately 33 feet below grade at the northern end of the site to 65 feet below grade at the southern end of the site. The depth-to-groundwater at the site is approximately 6 to 7 feet below sidewalk grade and the local groundwater flow direction is to the southwest."
Env Problem:	"Remediation at the site is complete. Prior to remediation, the

TIME WARNER CABLE (Continued) **U003074535**

	primary contaminants of concern included metals, semi-volatile organic compounds (SVOCs), and volatile organic compounds (VOCs)in soil and /or groundwater. Remedial actions have successfully achieved soil cleanup objectives for commercial use. A Site Management Plan (SMP) will be implemented to manage remaining contamination in the future. An environmental easement will limit the future use of property, restrict the use of groundwater and require compliance with the SMP. All engineering controls (e.g., soil cover/cap) of the remedy will be operated and maintained under the SMP."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2012-11-20 15:11:00
Record Upd:	2016-11-16 15:41:00
Updated By:	JXPEREZM
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New York Public Library
Owner Address:	Muhlenberg Branch
Owner Addr2:	209 West 23rd Street
Owner City,St,Zip:	New York, NY 10011-2379
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	MARTIN DETTLING
Owner Company:	510 West 22nd Street Partners LLC
Owner Address:	c/o Albanese Development Corporation
Owner Addr2:	1050 Franklin Avenue
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Christopher Albanese
Owner Company:	510 West 22nd Street Owner, LLC
Owner Address:	c/o Albanese Organization, Inc
Owner Addr2:	1050 Franklin Avenue
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	MARTIN DETTLING
Owner Company:	510 West 22nd Street Owner, LLC
Owner Address:	c/o Albanese Organization, Inc.
Owner Addr2:	1050 FRANKLIN AVENUE
Owner City,St,Zip:	GARDEN CITY, NY 11530
Owner Country:	United States of America
HW Code:	C231080

TIME WARNER CABLE (Continued) **U003074535**

Waste Type:	ETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231080
Waste Type:	METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231080
Waste Type:	DIBENZ[A,H]ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231080
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231080
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231080
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231080
Waste Type:	METHYL ETHYL KETONE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231080
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231080
Waste Type:	COPPER
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231080
Waste Type:	DICHLORODIFLUOROMETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	1309055
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2013-12-11 14:05:00
Record Updated:	2013-12-11 14:05:00
Updated By:	JXPEREZM
Crossref ID:	8907798
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2012-11-23 11:18:00
Record Updated:	2012-11-23 11:18:00
Updated By:	JDJARRAT
Crossref ID:	0010394
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2012-11-23 11:19:00
Record Updated:	2012-11-23 11:19:00
Updated By:	JDJARRAT

TIME WARNER CABLE (Continued) **U003074535**

Crossref ID:	2-285919
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2012-11-23 11:21:00
Record Updated:	2012-11-23 11:21:00
Updated By:	JDJARRAT
Crossref ID:	2016000216749
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2016-07-11 15:58:00
Record Updated:	2016-07-11 15:58:00
Updated By:	JEBROWN
Crossref ID:	C231080+02+13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2016-11-16 15:43:00
Record Updated:	2016-11-16 15:43:00
Updated By:	JXPEREZM

SPILLS:

Name:	TIME WARNER CABLE
Address:	511 WEST 21ST ST
City,State,Zip:	NEW YORK, NY 10011
Spill Number/Closed Date:	0010394 / 2018-10-02
Facility ID:	0010394
Facility Type:	ER
DER Facility ID:	163326
Site ID:	196043
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	3101
Spill Date:	2000-12-15
Investigator:	JXPEREZM
Referred To:	12-17-12 - NEW RAP REQUIRED WITHIN 60 DAYS
Reported to Dept:	2000-12-15
CID:	252
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-12-15
Spill Record Last Update:	2018-10-02
Spiller Name:	ROGER CHATTOO
Spiller Company:	TIME WARNER CABLE
Spiller Address:	511 WEST 21ST ST
Spiller Company:	001
Contact Name:	ROGER CHATTOO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 12/9/03 TJD Reassigned Demeo greater than greater than greater than Rommel. 11/23/05- Obligado - Spill transferred from Tang to Obligado 11/29/05 - Obligado - From Caller Remarks: UNDER GROUND

TIME WARNER CABLE (Continued) **U003074535**

PRODUCT LINE WAS FOUND TO BE LEAKING. CONTACT PERSON WAS NOTIFIED OF THIS WITH THE RECOMMENDATION TO EXCAVATE AND REPAIR . No files were found to document repairs or tests. Review PBS records - PBS# 2-285919 listed for site. Site has one 2000 gallon #2 fuel oil AST, two 4000 gallon gasoline USTs, one 550 gallon and two 275 gallon other ASTs. Time Warner Facility Manager Phone # (212) 598-7357 11/30/05 - Obligado - call Time Warner at number listed above. No answer. 12/15/05 - Obligado - called again, no answer. Called Dave Greffinius (consultant for neighboring property) to see if he was able to get any facility information for Time Warner building. 12/19/05 - Obligado - voice mail from Greffinius (12/15). Gave contact names and a phone number for Time Warner Facility: Frank Soto, Barry Rosenblume, and Tom Lonst (212) 379-2852 12/20/05 - Obligado - tried calling above listed number, appears to be a wrong number. 12/28/05 - Obligado - Site visit. Contact information for manager - Terrence Charlton (212) 598-7358. Called, spoke with secretary, Terrence Charlton on vacation, will call back next Tuesday. 1/3/05 - Obligado - Called Terrence Charlton. He does not know anything about spill. He will contact the Operations Manager - Britt Wenzel. Tell him the DEC requires information regarding the tank failure, if repairs were made, if soil/gw was impacted, if tanks were retested. 1/4/05 - Obligado - Received phone call from Abbas - engineer from Time Warner. Gave him my contanct info with instructions to send/fax any files he had regarding this spill number. 1/19/05 - Obigado - Call Abbas Family (718-474-3400) to inquire about documents. Left message. Abbas called back, he will send the information the beginning of next week. 3/31/06 - Obligado - Review documents sent by Abbas, received by Department on 1/25/06. Documents installation of new fill box in 1999 and 2002, and passing tightness tests in 2004 adn 2005. Documents do not shed any light on spill incident reported by Crompco on 12/15/00. Call Mr. Abbas and he said he will research the file for more information. He requested a spill report. I will email the spill report so he can find pertanent information. 5/5/06 - Obligado - Received additional documents. 5/11/06 - Reviewed documents. Corrosion in fill port pipe, caused leak to soil, soil excavated to 2 ft bgs. No mention of endpoint soil sampling. Send letter to Time Warner requiring soil boring investigation and collection of gw sample from below line where leak occured. 5/16/06 - Obligado - Delivery confirmation on 5/13/06 6/6/06 - Obligado - Received Limited Subsurface Investigation Report, submitted by Fenley and Nicol Environmental. Three soil borings advanced. Refusat at SB1. Soil impacts above TAGM at SP-2@10 ft, SP-3@5 ft, and SP-3@10 ft. Greates contamination at SP3 with 93,000 ppb MTBE and 2,242 ppb benzene. Recommends lateral and vertical extent of impact be delineated including offsite sampling. After delineation a Remedial Action Workplan will be submitted. 6/20/06 - Obligado - Phone conversation with Kristin Dillner 631-586-4900. She will email a workplan for additional delineation. Obligado - received workplan approved with minor changes. Required one soil boring to be moved closer to former remote fill area and collection of 3 ground water samples. One from previous soil boring area above, one from remote fill area, and one inbetween the dispensers. 8/7/06 - Obligado - Received Limited Subsurface Investigation Report, submitted by Fenley and Nicol Enviornmental. Six soil borings, 3 ground water samples collected from temporary well points. Ground water impacts detected at all 3 gw samplng points. Greatest soil and ground water impacts detected west of dispensers and southwest of UST field

TIME WARNER CABLE (Continued) **U003074535**

(TW1/SB4). GW results in ppb from TW1 show 7327 benzene, 41,697 toluene, 2783 ethlybenzene, ~23500 total xylenes, 321,467 MTBE. 8/21/06 - Obligado - Phone conversation with Kristin Dilner from F&N. Told her that permanent monitoring wells needed to be installed, the plume would need to be delineated, and a RAP submitted. I told her I would send Abbas a Stipulation agreement this week. 8/28/06 - Obligado - Sent STIP to Azzaro. Due date for signature is 9/25/06. CC to Dilner and Abbas Family. 90 days for ISR and 60 days for RAP. 8/31/06 - Obligado - Received delivery confirmaiton of Stip Agreeement. 10/10/06 - Obligado - Signed STIP received by Department on 9/26/06. CAP has been modified and signed by RP. Called Abbas to schedule a meeting to discuss. 11/1/06 - Obligado - Had a meeting with Sal Azarro, Manfred Bohms, Abbas Family. Discussed scope of work. UST excavation will probably take place in May 2007. They can proceed with monitoring well installation in meanwhile. I will send them another CAP with modifications based on discussions. 11/22/06 - Obligado - Email from Abbas with another revised CAP. After review the CAP looked acceptable. I attached it to the STIP and and emailed it as a final version back to Abbas requesting signature by 12/2/06. 11/27/06 - Obligado - Signed STIP received by Department. 12/4/06 - Obligado - Stipulation Agreement executed by Oliva 1/17/07 - Obligado - Called Manfred Bohms to discuss the status of project. He said 4 wells were installed, 2 onsite and 2 in the sidewalk. He is trying to gain access to the other sidewalk wells to sample. He will need a 2 week extension and will send an email request. 2/27/07 - Obligado - Received a letter from Abbas Family of Water Gorman engineers. The letter documents ground water results from 4 monitoring wells that were installed. Requests to collect samples from sidewalks in front of adjacent buildings. Upon the sampling and testing of the groundwater from the neighboring premises they will submit investigation report. 3/16/07 - Obligado - Abbas Family asked to get access to wells in sidewalks infront of 521 and 510 w. 21st street to do ground water sampling and guaging. Since this would help to allow a more accurate picture of ground water conditions in the area I sent a letter to Guy Roberts and to the owner of Sorage USA and asked for them to grant access to Time Warner to do the work. 4/17/07 - Obligado - Email from Greffinius from Delta stating they would grant access but asked to be copied on analytical results. 4/18/07 - Obligado - Spoke with Jessica from Gannette Fleming. She said they will be doing a tidals study on using the wells in the sidewalk and they would not be collecting samples. I forwarded this information to Greffinius. Additioanlly, Jessica said I should expect a report by May 31 and UST excavation in June. 5/9/07 - Obligado - Recevied a phone call from Andy Rudko of AKRF, 646-388-9526, who is working for a party looking to purchase the site from Time Warner and had some questions. I didn't give him any details, but that Time Warner signed a Stipulation agreement and I am waiting for an investigation for well installations. 5/14/07 - Obligado - Spoke with Abbas Family. He said project has been delayed because the new facility where Time Warner Cable will be moving to in Brooklyn is not ready yet. He will send a letter stating the same. They surveyed all the wells to get a ground water flow map. 5/18/07 - Obligado - Received a progress reprot letter. Delays have been incurred at new Time Warner facility in Brooklyn. So Time Warner will vacate the 21st street faciliity by the end of August. At that time the USTS and piping will be removed. Called Abbas, asking him when I will receive a report of all the investigation activities. He said 3-4 weeks. I told him I needed the

TIME WARNER CABLE (Continued) **U003074535**

report sooner than that. He will talk to Time Warner to expedite the report. 7/19/07 - Obligado - Reviewed documents entitled Investigation Summary Report , dated February 27, 2007, Update on CAP s Milestone and Monitoring Well Survey Report , dated June 11, 2007, and Monitoring Well Survey and Tidal Study , dated June 8, 2007. The documents summarize investigation activities performed to delineate soil and ground water contamination. After review of documents sent a letter to Time Warner requiring the following by Nov 1, 2007. 1) Quarterly Ground Water Monitoring - Collection of ground water samples for laboratory analysis from monitoring wells GF-MW1 through GF-MW4 and monitoring wells R-MW-1, R-MW-3, and either R-MW2 or R-MW-9. 2) Additional Delineation - Due to the extremely high concentrations of BTEX and MTBE in ground water, the Department requires installation and sampling of 3 additional monitoring wells to delineate the areal extent of the contaminant plume. One monitoring well must be installed in the north sidewalk of 21st street approximately 45 ft west of GFMW-2 to determine the down-gradient extent of plume and the extent to which the plume from Time Warner site is impacting other properties. One monitoring well must be installed north of GFMW-1 to delineate the areal extent of plume in the cross-gradient direction. One monitoring well must be installed northeast of GF-MW-4 to establish up-gradient background ground water conditions. 3) Summary of UST Removal - Documentation of the UST system and contaminated soil removal and endpoint sampling results must be submitted to the Department. 4) Remedial Action Plan - A Remedial Action Plan (RAP) should be submitted to the Department. The RAP must contain a plan to remediate residual soil and ground water contamination subsequent to source removal. The RAP must also include an Operation, Maintenance, and Monitoring Plan. If the property is to be redeveloped for a different use, the RAP must state the future intended use of the site and include a Vapor Intrusion Mitigation Plan. 7/19/07 - Obligado - Received call from Abbas Family. He received the letter and he said they would do the work. He asked if they need to do ground water remediation. I told him yes. He said the deadline might be hard to meet but he would let me know later. 10/19/07 - Obligado - PBS Violation hearing with DEC Urda and Falvey, Scott Furman (Time Warner attorney), Tradewinds Contractors, and Abass Family. During removal of USTs Brian Falvey visited the site for a PBS Inspection and found several PBS violations. Tank removal was put on hold due to violations, however they did continue to move some contaminated soil found in area of dispenser product lines. They found 2 additional USTs, that will be properly closed. Prior to any excavation, I will visit the site to inspect. A site visit is tentatively scheduled for Thursday November 1. The 4000 gallon USTs were encased in concrete and according to the attorney the tank vault is clean, but I will inspect. They will also core through the dispenser island concrete vaults. 12/4/07 - Obligado - Met on site with Scott Furman and Paul Woodel. The gasoline USTs have been removed as well as some contaminated soil. Endpoint samples only showed one hit for MTBE on eastern sidewall. Bottom was a concrete slab, but I couldn't see it because when they previously cored through the bottom the gw infiltrated up the whole and filled the bottom of the excavation. According to Scott Furman, at no time during work did they notice any sheen or petroleum smell from the water. And the tanks were in good condition. He said they would excavate a little more on the east to try and get clean side walls, then back fill. They showed me two additional excavations in the back

TIME WARNER CABLE (Continued) **U003074535**

of the building, one for a 550 UST of unknown contents, and the other was a suspected UST location which they didn't find any USt. From the 550 USt they took sidewall samples and only found several PAHs, but it appeared to be levels similar to urban fill. After looking at the data I approved backfilling those 2 excavations. The major contamination is in the area around the dispenser and the vent lines, with elevated MTBE and BTEX, in the southwestern corner of the site and the sidewalk. Moving forward they will 1) excavate a little more on eastern sidewall of tank excavation then backfill, 2) install 2 additional wells to delineate the southwest gw plume area, 2) additional excavation to remove as much contaminated soil as site constraints allow around vents and dispensers 3) propose a plan for gw water treatment they may due treatment at time of excavation since soils and gw will be exposed. Since the new tenant plans to build a hotel in 1 years time, timely remediation is required, so we agreed that chem ox might be the best strategy for ground water. They will submit a memo summarizing our discussions. 12/17/07 - Obligado - Received Memo from Woodell via email, detailing above meeting minutes. The memo proposes excavation and chemical injection with regenox. I sent an email to Paul concurring the planned course of action. 1/8/08 - Obligado - Conference call with Paul Woodel and Mark Furman. They are planning to use regenox as chemical oxidant followed by injection of advanced ORC to enhance bioremediation subsequent to chemical oxidation. They will submit a formal RAP today. 1/11/08 - Obligado - Approved RAP. Sent email with RAP approval letter. 1/15/08 - Obligado - Email from Woodel : We have begun the tasks described in the work plan. The holes in the north room have been backfilled. Today I was on site to scrape back the east wall of the gasoline UST excavation in the south room. We took it back an additional 2-3 feet and I collected another sidewall sample. This excavation is also being backfilled. We anticipate that the first test pit between the 2 former dispenser islands will be dug on Friday. 1/28/08 - Obligado - Email update from Woodel - LBG has supervised the excavation of the 2 test pits described in the workplan. Impacted soil and pockets of free-phase product were encountered in the western pit and were removed. The eastern pit contained impacted soil at the water table but there was no free product and no apparent source zone above the water table. Both pits have been extended to their practical limit (interior walls, sewer lines, column footers, etc.). We plan to backfill the level at the water table with stone on Tuesday and apply the chemical-oxidation product Tuesday and Wednesday. 5/14/08 - Obligado - Review UST Closure Report. 2 3000 gallon gasoline USTs, 1 550 gallon 2ASTs, 2 product dispensers, associated piping and 1 oil water separator were removed. Endpoint samples were collected from UST excavations. East wall of gasline UST excavation had MTBE above TAGM. The waste oil UST excavation idicated residual SVOCs adn chromium typical of urban fill thorughout the city. Test pits TP1 adn TP2 were excavated adn 78 tons of contaminated soil was removed and disposed off-site and waste manifests were included. End point sampling from test pits show that gross contamination present at and below the water table. No evidence of the specific source of the contamination was obvious. Contamination above TAGM and limited free-phase product appears to have accumulated around the buried concrete and structural components of th ebuildings. Test pits were backfilled with gravel and chemical oxidation products were applied to the subsurface to promote remediation. Three treatment sumps were installed with 4 diameter slotted screen set 3 ft into water. 1120

TIME WARNER CABLE (Continued) **U003074535**

lbs of RegenOx adn 150 lbs of ORC were mixed and applied to the gravel backfill on January 31, 2008. On Feb 29, 180 lbs of RegenOx and 75 lbs of ORC were applied. 3 borings and 2 wells were installed at the site. 1st round of smapling will be completed March 10, 2008. Review 1Q08 MOnitoring Report - 5 wells were guaged and sampled. Based on most recent results Max contamination at S3 (former GFMW4) with 2570 ug/L BTEX and 33,000 ug/L MTBE. According to the report, the whole building will be torn down in the summerof 2008. When this occurs LBG will supervise additional soil removal. LBG will inform the NYSDEC of future remedial activities. 9/25/08 - Obligado - review 2Q08 report. Elevated concentration still present in wells. Effectiveness of REgenOx not yet apparent. Max MTBE at 48,000 ug/L. According to report building is still scheduled to be demolished. LBG will inform the DEC of any redevelopment or additional remediation 7/7/09 - Obligado - Review 1Q09 Update Report - S3 and GFMW4 have been destroyed, so there is no monitoring wells in the source area. Downgradient well GFW-1 still has significant impacts. S3 and GFMW4 before destroyed had the max concentrations. Send a letter requiring the installation of additional monitoring wells. Require work plan submission within 30 days. 10/29/09 - Obligado - Review Investigation Work Plan, submitted 8/13/09. The workplan proposes 3 additional wells as requested, however, one of the upgradient is over 100 feet away and to far north. This well won't provide and meaningfull data. SEnt letter requiring relocation of well to the east of the tanks and also revise soil sampling plan so soil sampling begins above the water table. Also requested that they revise the implementation schedule. 6/7/10 - Obligado - I reviewed the revised Investigation Work Plan. The soil sampling plan was modified and the location of the upgradient well was moved to a more appropriate location. I sent a letter via email for approval of the three wells. 8/12/2010 - Obligado - I reviewed the July 2010 Update Report. The report documented the installation of 3 additional monitoring wells and quarterly sampling. Only one soil sample, MW8, had soil impacts with 980 ug/kg MTBE. Maximum BTEX concentrations were found at MW8 with 4100 BTEX. Maximum MTBE also detected at MW8 with 3400 ug/L. the report recommends continued monitoring. I emailed Paul Woodell at LBG and requested a BTEX plume map on future reports. 10/11/11 - Obligado - I emailed Paul Woodell to inquire about the status of the monitoring. I received a phone call from Sean Groszkowski of LBG ((914) 694-5711) who is now managing the project. He said they are planning to do another chemox event using REgenOx. I asked him to send me a work plan as well as any monitoring reports since July 2010. 11/9/11 - Obligado - I reviewed a plan to do additional chemical injections at the site. They plan to do injections via geoprobe. They proposed 10 injection points using Regenox and ORC advanced. I gave approval to proceed with the additional injections. I also had a conference call with Sean Groszkowski (LBG), Scott Furman (time Warner attorney), and repsensentatives of a potential purchaser, Arnie Fleming (consultant) and Karen of Kramer LEvin (attorney). We discussed the pending injections and the planned purchase and redevlopment. A purchaser plans to redevelop the property as an office building. They will use and reinforce the existing structure, as well as add several floors. The building will not have basement. They will install a vapor barrier and SSDS. The planned start for the work is 6 to 9 months. I recommended Time Warner to try and treat the soil and ground water as aggressively as possible prior to starting the development. They concurred. The

TIME WARNER CABLE (Continued) **U003074535**

injections are scheduled to begin tomorrow (11/10/11). 11/16/11 - Obligado - I spoke with Sean. The injections went well. All the material was accepted. They plan to sample again in December. According to Sean I will receive a report documenting baseline sampling in early December. 1/17/12 - Obligado - Meeting with Time Warner, LBG, FLS, DEC, and the site developer. They will continue with current strategy but DEC will require additionl remedial actions if not effective. 1/19/12 - Obligado - DEC, LBG, Albanese, meet on site to go over injection locations. We discussed potential remedial options for soil under footings. We also discussed installation of a well immediatley down gradient of footers in TP2 to monitor effects of residaul source on gw concentrations. According to LBG, multiple refusals were encountered in downgradient plume area. DEC recommended evaluating alternate injection approaches. 1/27/12 - Obligado - I sent a letter to Time Warner ccing all parties in meetings describing DEC requirements: 1) additional well downgradient of footer area 2)evaluate alternate remedies for residual source 3) alternate injection strategy in plume area due to refusals. 3/5/12 - Obligado - I received 4th Quarter 2011 report. The report documents baseline sampling on October 28, 2011, 1st chemical injection on November 10 and 11, 2011, fourth quarter sampling on December 27, 2011, and the 2nd chemical injection on December 28 and Jan 3 2012. The report documents a spike in BTEX concentrations following the 1st chemical injection, which may represent release of adsorbed contaminants from the soil. They will continue monitoring. 5/8/12 - Obligado - I emailed Sean Growzkowski to inquire when I would receive 1st Quarter sampling results. He indicated 1 to 2 weeks. 7/16/12 - Obligado - I received the 1st Quarter Sampling report. MW10 was installed downgradient of the excavated area. Gross contamination was present in soil. 38000 ug/L BTEX and 53,000 ug/L MTBE found in MW10 groundwater. 42 ppm BTEX and 27 ppm MTBE was found in soil. I sent an email to LBG with a cc to FLS and Albanese requiring a remediation plan within 30 days to indicate whether they plan to continue with chemox or try alternate methods. 7/17/12 - Obligado - recieved an email from LBG Sean Groqzkowski including 2nd Quarter 2012 data which showed significant ground water improvement in MW10. BTEX reduced 98%. LBG requesting determination on need for new plan to be delayed until review of 3rd Quarter 2012 data. 7/24/12 - Obligado - sent an email deffering requirement for new plan until review of the 3rd quarter data. 12/17/12 - Obligado - received and and reviewed 3rd Quarter results. BTEX concentrations rebounded to over 15,000 ug/L, including 5,400 ug/L benzene. I sent a letter to Time Warner requiring a new RAP within 60 days. 12/24/12 - Obligado - DEC receives notification letter of BCP application from Sive Paget. BCP Site No. C231080. 04/29/2013 - Spill transferred from Obligado to Perez-Maldonado. Property Owner applied to the BCP (Site #C231080) to address environmental issues at the site. Spill administrative closure pending to implementation of a remedial program to address contamination in connection with this spill. 11/15/2013 - Remedial Investigation Work Plan have been approved. Remedial investigation ongoing under the BCP program(511 West 21st Street Site, Site ID C231080). (Perez) 03/31/2015 - BCP Site (511 West 21st Street Site, Site ID C231080) Remedial Action Work Plan (RAWP) have been approved. 04/03/2016 - Field work in connection the approved RAWP ongoing. (Perez) 03/30/2017 - Construction of the on-site BCP remedy completed on October 2016 and CoC issued on December 2016. Post-remedy groundwater sampling event scheduled for the first quarter of 2017.

TIME WARNER CABLE (Continued) **U003074535**

(Perez) 10/02/2018 - The vast majority of the source of groundwater contamination (soil with contamination levels above protection groundwater soil cleanup objectives) has been removed. On- and off-site groundwater will be monitor under the Brownfield Cleanup Program project 511 West 21th Street (C231080). There are no pathways considered complete or potential exposure to any identified sensitive receptors. Based on available documents, case closed. NFA letter sent to RP. "

Remarks: "UNDER GROUND PRODUCT LINE WAS FOUND TO BE LEAKING. CONTACT PERSON WAS NOTIFIED OF THIS WITH THE RECOMMENDATION TO EXCAVATE AND REPAIR."

All Materials:

Site ID:	196043
Operable Unit ID:	831512
Operable Unit:	01
Material ID:	544300
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	TIME WARNER CABLE
Address:	511 WEST 21ST ST
City,State,Zip:	NEW YORK, NY 10011
Spill Number/Closed Date:	0010394 / 2018-10-02
Facility ID:	0010394
Facility Type:	ER
DER Facility ID:	163326
Site ID:	196043
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	3101
Spill Date:	2000-12-15
Investigator:	JXPEREZM
Referred To:	12-17-12 - NEW RAP REQUIRED WITHIN 60 DAYS
Reported to Dept:	2000-12-15
CID:	252
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-12-15
Spill Record Last Update:	2018-10-02
Spiller Name:	ROGER CHATTOO
Spiller Company:	TIME WARNER CABLE
Spiller Address:	511 WEST 21ST ST
Spiller Company:	001

TIME WARNER CABLE (Continued) **U003074535**

Contact Name: Serena M. Parker
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 12/9/03 TJD Reassigned Demeo greater than greater than greater than Rommel. 11/23/05- Obligado - Spill transferred from Tang to Obligado 11/29/05 - Obligado - From Caller Remarks: UNDER GROUND PRODUCT LINE WAS FOUND TO BE LEAKING. CONTACT PERSON WAS NOTIFIED OF THIS WITH THE RECOMMENDATION TO EXCAVATE AND REPAIR . No files were found to document repairs or tests. Review PBS records - PBS# 2-285919 listed for site. Site has one 2000 gallon #2 fuel oil AST, two 4000 gallon gasoline USTs, one 550 gallon and two 275 gallon other ASTs. Time Warner Facility Manager Phone # (212) 598-7357 11/30/05 - Obligado - call Time Warner at number listed above. No answer. 12/15/05 - Obligado - called again, no answer. Called Dave Greffinius (consultant for neighboring property) to see if he was able to get any facility information for Time Warner building. 12/19/05 - Obligado - voice mail from Greffinius (12/15). Gave contact names and a phone number for Time Warner Facility: Frank Soto, Barry Rosenblume, and Tom Lonst (212) 379-2852 12/20/05 - Obligado - tried calling above listed number, appears to be a wrong number. 12/28/05 - Obligado - Site visit. Contact information for manager - Terrence Charlton (212) 598-7358. Called, spoke with secretary, Terrence Charlton on vacation, will call back next Tuesday. 1/3/05 - Obligado - Called Terrence Charlton. He does not know anything about spill. He will contact the Operations Manager - Britt Wenzel. Tell him the DEC requires information regarding the tank failure, if repairs were made, if soil/gw was impacted, if tanks were retested. 1/4/05 - Obligado - Received phone call from Abbas - engineer from Time Warner. Gave him my contanct info with instructions to send/fax any files he had regarding this spill number. 1/19/05 - Obigado - Call Abbas Family (718-474-3400) to inquire about documents. Left message. Abbas called back, he will send the information the beginning of next week. 3/31/06 - Obligado - Review documents sent by Abbas, received by Department on 1/25/06. Documents installation of new fill box in 1999 and 2002, and passing tightness tests in 2004 adn 2005. Documents do not shed any light on spill incident reported by Crompco on 12/15/00. Call Mr. Abbas and he said he will research the file for more information. He requested a spill report. I will email the spill report so he can find pertanent information. 5/5/06 - Obligado - Received additional documents. 5/11/06 - Reviewed documents. Corrosion in fill port pipe, caused leak to soil, soil excavated to 2 ft bgs. No mention of endpoint soil sampling. Send letter to Time Warner requiring soil boring investigation and collection of gw sample from below line where leak occured. 5/16/06 - Obligado - Delivery confirmation on 5/13/06 6/6/06 - Obligado - Received Limited Subsurface Investigation Report, submitted by Fenley and Nicol Environmental. Three soil borings advanced. Refusat at SB1. Soil impacts above TAGM at SP-2@10 ft, SP-3@5 ft, and SP-3@10 ft. Greates contamination at SP3 with 93,000 ppb MTBE and 2,242 ppb benzene. Recommends lateral and vertical extent of impact be delineated including offsite sampling. After delineation a Remedial Action Workplan will be submitted. 6/20/06 - Obligado - Phone conversation with Kristin Dillner 631-586-4900. She will email a workplan for additional delineation. Obligado - received workplan approved with minor changes. Required one soil boring to be moved closer to former remote fill area and collection of 3 ground water samples. One from previous soil boring area above, one from remote fill area, and one inbetween the dispensers. 8/7/06 - Obligado

TIME WARNER CABLE (Continued) **U003074535**

- Received Limited Subsurface Investigation Report, submitted by Fenley and Nicol Enviornmental. Six soil borings, 3 ground water samples collected from temporary well points. Ground water impacts detected at all 3 gw samplng points. Greatest soil and ground water impacts detected west of dispensers and southwest of UST field (TW1/SB4). GW results in ppb from TW1 show 7327 benzene, 41,697 toluene, 2783 ethlybenzene, ~23500 total xylenes, 321,467 MTBE. 8/21/06 - Obligado - Phone conversation with Kristin Dilner from F&N. Told her that permanent monitoring wells needed to be installed, the plume would need to be delineated, and a RAP submitted. I told her I would send Abbas a Stipulation agreement this week. 8/28/06 - Obligado - Sent STIP to Azzaro. Due date for signature is 9/25/06. CC to Dilner and Abbas Family. 90 days for ISR and 60 days for RAP. 8/31/06 - Obligado - Received delivery confirmaiton of Stip Agreeement. 10/10/06 - Obligado - Signed STIP received by Department on 9/26/06. CAP has been modified and signed by RP. Called Abbas to schedule a meeting to discuss. 11/1/06 - Obligado - Had a meeting with Sal Azarro, Manfred Bohms, Abbas Family. Discussed scope of work. UST excavation will probably take place in May 2007. They can proceed with monitoring well installation in meanwhile. I will send them another CAP with modifications based on discussions. 11/22/06 - Obligado - Email from Abbas with another revised CAP. After review the CAP looked acceptable. I attached it to the STIP and and emailed it as a final version back to Abbas requesting signature by 12/2/06. 11/27/06 - Obligado - Signed STIP received by Department. 12/4/06 - Obligado - Stipulation Agreement executed by Oliva 1/17/07 - Obligado - Called Manfred Bohms to discuss the status of project. He said 4 wells were installed, 2 onsite and 2 in the sidewalk. He is trying to gain access to the other sidewalk wells to sample. He will need a 2 week extension and will send an email request. 2/27/07 - Obligado - Received a letter from Abbas Family of Water Gorman engineers. The letter documents ground water results from 4 monitoring wells that were installed. Requests to collect samples from sidewalks in front of adjacent buildings. Upon the sampling and testing of the groundwater from the neighboring premises they will submit investigation report. 3/16/07 - Obligado - Abbas Family asked to get access to wells in sidewalks infront of 521 and 510 w. 21st street to do ground water sampling and guaging. Since this would help to allow a more accurate picture of ground water conditions in the area I sent a letter to Guy Roberts and to the owner of Sorage USA and asked for them to grant access to Time Warner to do the work. 4/17/07 - Obligado - Email from Greffinius from Delta stating they would grant access but asked to be copied on analytical results. 4/18/07 - Obligado - Spoke with Jessica from Gannette Fleming. She said they will be doing a tidals study on using the wells in the sidewalk and they would not be collecting samples. I forwarded this information to Greffinius. Additioanlly, Jessica said I should expect a report by May 31 and UST excavation in June. 5/9/07 - Obligado - Recevied a phone call from Andy Rudko of AKRF, 646-388-9526, who is working for a party looking to purchase the site from Time Warner and had some questions. I didn't give him any details, but that Time Warner signed a Stipulation agreement and I am waiting for an investigation for well installations. 5/14/07 - Obligado - Spoke with Abbas Family. He said project has been delayed because the new facility where Time Warner Cable will be moving to in Brooklyn is not ready yet. He will send a letter stating the same. They surveyed all the wells to get a ground water flow map. 5/18/07 - Obligado - Received a progress

TIME WARNER CABLE (Continued) **U003074535**

reprot letter. Delays have been incurred at new Time Warner facility in Brooklyn. So Time Warner will vacate the 21st street faciliity by the end of August. At that time the USTS and piping will be removed. Called Abbas, asking him when I will receive a report of all the investigation activities. He said 3-4 weeks. I told him I needed the report sooner than that. He will talk to Time Warner to expedite the report. 7/19/07 - Obligado - Reviewed documents entitled Investigation Summary Report , dated February 27, 2007, Update on CAP s Milestone and Monitoring Well Survey Report , dated June 11, 2007, and Monitoring Well Survey and Tidal Study , dated June 8, 2007. The documents summarize investigation activities performed to delineate soil and ground water contamination. After review of documents sent a letter to Time Warner requiring the following by Nov 1, 2007. 1) Quarterly Ground Water Monitoring - Collection of ground water samples for laboratory analysis from monitoring wells GF-MW1 through GF-MW4 and monitoring wells R-MW-1, R-MW-3, and either R-MW2 or R-MW-9. 2) Additional Delineation - Due to the extremely high concentrations of BTEX and MTBE in ground water, the Department requires installation and sampling of 3 additional monitoring wells to delineate the areal extent of the contaminant plume. One monitoring well must be installed in the north sidewalk of 21st street approximately 45 ft west of GFMW-2 to determine the down-gradient extent of plume and the extent to which the plume from Time Warner site is impacting other properties. One monitoring well must be installed north of GFMW-1 to delineate the areal extent of plume in the cross-gradient direction. One monitoring well must be installed northeast of GF-MW-4 to establish up-gradient background ground water conditions. 3) Summary of UST Removal - Documentation of the UST system and contaminated soil removal and endpoint sampling results must be submitted to the Department. 4) Remedial Action Plan - A Remedial Action Plan (RAP) should be submitted to the Department. The RAP must contain a plan to remediate residual soil and ground water contamination subsequent to source removal. The RAP must also include an Operation, Maintenance, and Monitoring Plan. If the property is to be redeveloped for a different use, the RAP must state the future intended use of the site and include a Vapor Intrusion Mitigation Plan. 7/19/07 - Obligado - Received call from Abbas Family. He received the letter and he said they would do the work. He asked if they need to do ground water remediation. I told him yes. He said the deadline might be hard to meet but he would let me know later. 10/19/07 - Obligado - PBS Violation hearing with DEC Urda and Falvey, Scott Furman (Time Warner attorney), Tradewinds Contractors, and Abass Family. During removal of USTs Brian Falvey visited the site for a PBS Inspection and found several PBS violations. Tank removal was put on hold due to violations, however they did continue to move some contaminated soil found in area of dispenser product lines. They found 2 additional USTs, that will be properly closed. Prior to any excavation, I will visit the site to inspect. A site visit is tentatively scheduled for Thursday November 1. The 4000 gallon USTs were encased in concrete and according to the attorney the tank vault is clean, but I will inspect. They will also core through the dispenser island concrete vaults. 12/4/07 - Obligado - Met on site with Scott Furman and Paul Woodel. The gasoline USTs have been removed as well as some contaminated soil. Endpoint samples only showed one hit for MTBE on eastern sidewall. Bottom was a concrete slab, but I couldn’t see it because when they previously cored through the bottom the gw infiltrated up the whole and filled the

TIME WARNER CABLE (Continued) **U003074535**

bottom of the excavation. According to Scott Furman, at no time during work did they notice any sheen or petroleum smell from the water. And the tanks were in good condition. He said they would excavate a little more on the east to try and get clean side walls, then back fill. They showed me two additional excavations in the back of the building, one for a 550 UST of unknown contents, and the other was a suspected UST location which they didn't find any USt. From the 550 USt they took sidewall samples and only found several PAHs, but it appeared to be levels similar to urban fill. After looking at the data I approved backfilling those 2 excavations. The major contamination is in the area around the dispenser and the vent lines, with elevated MTBE and BTEX, in the southwestern corner of the site and the sidewalk. Moving forward they will 1) excavate a little more on eastern sidewall of tank excavation then backfill, 2) install 2 additional wells to delineate the southwest gw plume area, 2) additional excavation to remove as much contaminated soil as site constraints allow around vents and dispensers 3) propose a plan for gw water treatment they may due treatment at time of excavation since soils and gw will be exposed. Since the new tenant plans to build a hotel in 1 years time, timely remediation is required, so we agreed that chem ox might be the best strategy for ground water. They will submit a memo summarizing our discussions. 12/17/07 - Obligado - Received Memo from Woodell via email, detailing above meeting minutes. The memo proposes excavation and chemical injection with regenox. I sent an email to Paul concurring the planned course of action. 1/8/08 - Obligado - Conference call with Paul Woodel and Mark Furman. They are planning to use regenox as chemical oxidant followed by injection of advanced ORC to enhance bioremediation subsequent to chemical oxidation. They will submit a formal RAP today. 1/11/08 - Obligado - Approved RAP. Sent email with RAP approval letter. 1/15/08 - Obligado - Email from Woodel : We have begun the tasks described in the work plan. The holes in the north room have been backfilled. Today I was on site to scrape back the east wall of the gasoline UST excavation in the south room. We took it back an additional 2-3 feet and I collected another sidewall sample. This excavation is also being backfilled. We anticipate that the first test pit between the 2 former dispenser islands will be dug on Friday. 1/28/08 - Obligado - Email update from Woodel - LBG has supervised the excavation of the 2 test pits described in the workplan. Impacted soil and pockets of free-phase product were encountered in the western pit and were removed. The eastern pit contained impacted soil at the water table but there was no free product and no apparent source zone above the water table. Both pits have been extended to their practical limit (interior walls, sewer lines, column footers, etc.). We plan to backfill the level at the water table with stone on Tuesday and apply the chemical-oxidation product Tuesday and Wednesday. 5/14/08 - Obligado - Review UST Closure Report. 2 3000 gallon gasoline USTs, 1 550 gallon 2ASTs, 2 product dispensers, associated piping and 1 oil water separator were removed. Endpoint samples were collected from UST excavations. East wall of gasline UST excavation had MTBE above TAGM. The waste oil UST excavation idicated residual SVOCs adn chromium typical of urban fill thorughout the city. Test pits TP1 adn TP2 were excavated adn 78 tons of contaminated soil was removed and disposed off-site and waste manifests were included. End point sampling from test pits show that gross contamination present at and below the water table. No evidence of the specific source of the contamination was obvious. Contamination above TAGM and limited

TIME WARNER CABLE (Continued) **U003074535**

free-phase product appears to have accumulated around the buried concrete and structural components of th ebuildings. Test pits were backfilled with gravel and chemical oxidation products were applied to the subsurface to promote remediation. Three treatment sumps were installed with 4 diameter slotted screen set 3 ft into water. 1120 lbs of RegenOx adn 150 lbs of ORC were mixed and applied to the gravel backfill on January 31, 2008. On Feb 29, 180 lbs of RegenOx and 75 lbs of ORC were applied. 3 borings and 2 wells were installed at the site. 1st round of smapling will be completed March 10, 2008. Review 1Q08 MOnitoring Report - 5 wells were guaged and sampled. Based on most recent results Max contamination at S3 (former GFMW4) with 2570 ug/L BTEX and 33,000 ug/L MTBE. According to the report, the whole building will be torn down in the summerof 2008. When this occurs LBG will supervise additional soil removal. LBG will inform the NYSDEC of future remedial activities. 9/25/08 - Obligado - review 2Q08 report. Elevated concentration still present in wells. Effectiveness of REgenOx not yet apparent. Max MTBE at 48,000 ug/L. According to report building is still scheduled to be demolished. LBG will inform the DEC of any redevelopment or additional remediation 7/7/09 - Obligado - Review 1Q09 Update Report - S3 and GFMW4 have been destroyed, so there is no monitoring wells in the source area. Downgradient well GFW-1 still has significant impacts. S3 and GFMW4 before destroyed had the max concentrations. Send a letter requiring the installation of additional monitoring wells. Require work plan submission within 30 days. 10/29/09 - Obligado - Review Investigation Work Plan, submitted 8/13/09. The workplan proposes 3 additional wells as requested, however, one of the upgradient is over 100 feet away and to far north. This well won't provide and meaningfull data. SEnt letter requiring relocation of well to the east of the tanks and also revise soil sampling plan so soil sampling begins above the water table. Also requested that they revise the implementation schedule. 6/7/10 - Obligado - I reviewed the revised Investigation Work Plan. The soil sampling plan was modified and the location of the upgradient well was moved to a more appropriate location. I sent a letter via email for approval of the three wells. 8/12/2010 - Obligado - I reviewed the July 2010 Update Report. The report documented the installation of 3 additional monitoring wells and quarterly sampling. Only one soil sample, MW8, had soil impacts with 980 ug/kg MTBE. Maximum BTEX concentrations were found at MW8 with 4100 BTEX. Maximum MTBE also detected at MW8 with 3400 ug/L. the report recommends continued monitoring. I emailed Paul Woodell at LBG and requested a BTEX plume map on future reports. 10/11/11 - Obligado - I emailed Paul Woodell to inquire about the status of the monitoring. I received a phone call from Sean Groszkowski of LBG ((914) 694-5711) who is now managing the project. He said they are planning to do another chemox event using REgenOx. I asked him to send me a work plan as well as any monitoring reports since July 2010. 11/9/11 - Obligado - I reviewed a plan to do additional chemical injections at the site. They plan to do injections via geoprobe. They proposed 10 injection points using Regenox and ORC advanced. I gave approval to proceed with the additional injections. I also had a conference call with Sean Groszkowski (LBG), Scott Furman (time Warner attorney), and repsensentatives of a potential purchaser, Arnie Fleming (consultant) and Karen of Kramer LEvin (attorney). We discussed the pending injections and the planned purchase and redevlopment. A purchaser plans to redevelop the property as an office building. They will use and reinforce the

TIME WARNER CABLE (Continued) **U003074535**

existing structure, as well as add several floors. The building will not have basement. They will install a vapor barrier and SSDS. The planned start for the work is 6 to 9 months. I recommended Time Warner to try and treat the soil and ground water as aggressively as possible prior to starting the development. They concurred. The injections are scheduled to begin tomorrow (11/10/11). 11/16/11 - Obligado - I spoke with Sean. The injections went well. All the material was accepted. They plan to sample again in December. According to Sean I will receive a report documenting baseline sampling in early December. 1/17/12 - Obligado - Meeting with Time Warner, LBG, FLS, DEC, and the site developer. They will continue with current strategy but DEC will require additionl remedial actions if not effective. 1/19/12 - Obligado - DEC, LBG, Albanese, meet on site to go over injection locations. We discussed potential remedial options for soil under footings. We also discussed installation of a well immediatley down gradient of footers in TP2 to monitor effects of residaul source on gw concentrations. According to LBG, multiple refusals were encountered in downgradient plume area. DEC recommended evaluating alternate injection approaches. 1/27/12 - Obligado - I sent a letter to Time Warner ccing all parties in meetings describing DEC requirements: 1) additional well downgradient of footer area 2)evaluate alternate remedies for residual source 3) alternate injection strategy in plume area due to refusals. 3/5/12 - Obligado - I received 4th Quarter 2011 report. The report documents baseline sampling on October 28, 2011, 1st chemical injection on November 10 and 11, 2011, fourth quarter sampling on December 27, 2011, and the 2nd chemical injection on December 28 and Jan 3 2012. The report documents a spike in BTEX concentrations following the 1st chemical injection, which may represent release of adsorbed contaminants from the soil. They will continue monitoring. 5/8/12 - Obligado - I emailed Sean Growzkowski to inquire when I would receive 1st Quarter sampling results. He indicated 1 to 2 weeks. 7/16/12 - Obligado - I received the 1st Quarter Sampling report. MW10 was installed downgradient of the excavated area. Gross contamination was present in soil. 38000 ug/L BTEX and 53,000 ug/L MTBE found in MW10 groundwater. 42 ppm BTEX and 27 ppm MTBE was found in soil. I sent an email to LBG with a cc to FLS and Albanese requiring a remediation plan within 30 days to indicate whether they plan to continue with chemox or try alternate methods. 7/17/12 - Obligado - recieved an email from LBG Sean Groqzkowski including 2nd Quarter 2012 data which showed significant ground water improvement in MW10. BTEX reduced 98%. LBG requesting determination on need for new plan to be delayed until review of 3rd Quarter 2012 data. 7/24/12 - Obligado - sent an email deffering requirement for new plan until review of the 3rd quarter data. 12/17/12 - Obligado - received and and reviewed 3rd Quarter results. BTEX concentrations rebounded to over 15,000 ug/L, including 5,400 ug/L benzene. I sent a letter to Time Warner requiring a new RAP within 60 days. 12/24/12 - Obligado - DEC receives notification letter of BCP application from Sive Paget. BCP Site No. C231080. 04/29/2013 - Spill transferred from Obligado to Perez-Maldonado. Property Owner applied to the BCP (Site #C231080) to address environmental issues at the site. Spill administrative closure pending to implementation of a remedial program to address contamination in connection with this spill. 11/15/2013 - Remedial Investigation Work Plan have been approved. Remedial investigation ongoing under the BCP program(511 West 21st Street Site, Site ID C231080). (Perez) 03/31/2015 - BCP Site (511 West 21st Street Site,

TIME WARNER CABLE (Continued) **U003074535**

Site ID C231080) Remedial Action Work Plan (RAWP) have been approved. 04/03/2016 - Field work in connection the approved RAWP ongoing. (Perez) 03/30/2017 - Construction of the on-site BCP remedy completed on October 2016 and CoC issued on December 2016. Post-remedy groundwater sampling event scheduled for the first quarter of 2017. (Perez) 10/02/2018 - The vast majority of the source of groundwater contamination (soil with contamination levels above protection groundwater soil cleanup objectives) has been removed. On- and off-site groundwater will be monitor under the Brownfield Cleanup Program project 511 West 21th Street (C231080). There are no pathways considered complete or potential exposure to any identified sensitive receptors. Based on available documents, case closed. NFA letter sent to RP. "

Remarks: "UNDER GROUND PRODUCT LINE WAS FOUND TO BE LEAKING. CONTACT PERSON WAS NOTIFIED OF THIS WITH THE RECOMMENDATION TO EXCAVATE AND REPAIR."

All Materials:

Site ID:	196043
Operable Unit ID:	831512
Operable Unit:	01
Material ID:	544300
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AQ578 **CON EDISON SERVICE BOX 2376** **RCRA NonGen / NLR** **1014918805**
South **316 W 14TH ST & 8TH AVE OPP** **NJ MANIFEST** **NYP004224242**
1/8-1/4 **NEW YORK, NY 10014** **NY MANIFEST**
0.163 mi.
861 ft. **Site 1 of 8 in cluster AQ**

Relative: **Higher**
Actual: **20 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20110215
Handler Name:	CON EDISON SERVICE BOX 2376
Handler Address:	316 W 14TH ST & 8TH AVE OPP
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYP004224242
Contact Name:	JOSE MONTALVO
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-427-1331
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY

CON EDISON SERVICE BOX 2376 (Continued) **1014918805**

State District:	NYSDEC R2
Mailing Address:	IRVING PL RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20110701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No

CON EDISON SERVICE BOX 2376 (Continued) **1014918805**

Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20110116
Handler Name:	CON EDISON SERVICE BOX 2376
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20110215
Handler Name:	CON EDISON SERVICE BOX 2376
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004224242
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JOSE MONTALVO
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported

CON EDISON SERVICE BOX 2376 (Continued) **1014918805**

Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655913JJK
EPA ID:	NYP004224242
Date Shipped:	1/16/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	500.00 Pounds

CON EDISON SERVICE BOX 2376 (Continued) **1014918805**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	316 W 14TH ST & 8TH AVE OPP
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004224242
Facility Status:	Not reported
Location Address 1:	OPP 316 W 14TH ST & 8TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004224242
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602757

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	01/16/2011
Trans1 Recv Date:	01/16/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/17/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004224242
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655913JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON SERVICE BOX 2376 (Continued) **1014918805**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI579 **309 WEST 14TH STREET** **NY AST** **U003390602**
SSE **309 WEST 14TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.163 mi.
862 ft. **Site 5 of 7 in cluster AI**

Relative:
Higher

Actual:
20 ft.

AST:

Name:	309 WEST 14TH STREET
Address:	309 WEST 14TH STREET
City,State,Zip:	NEW YORK, NY 10014
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-159182
Program Type:	PBS
UTM X:	584166.44939
UTM Y:	4510394.44431
Expiration Date:	08/26/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	5369
Affiliation Type:	Facility Owner
Company Name:	HOUSING DEVELOPMENT ASSOCIATES LLC
Contact Type:	PROPERTY MANAGER
Contact Name:	JEFF SEGAL
Address1:	50 BANK ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10014
Country Code:	001
Phone:	(212) 243-7757
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR

309 WEST 14TH STREET (Continued) **U003390602**

Date Last Modified: 2017-12-06

Site Id: 5369
Affiliation Type: Mail Contact
Company Name: SUPERIOR MANAGEMENTS INC.
Contact Type: Not reported
Contact Name: S.M.I.
Address1: 50 BANK ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10014
Country Code: 001
Phone: (212) 243-7757
EMail: INFO@SMI.COM
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-12-06

Site Id: 5369
Affiliation Type: Facility Operator
Company Name: 309 WEST 14TH STREET
Contact Type: Not reported
Contact Name: ANGEL QUITO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 243-7757
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2012-08-29

Site Id: 5369
Affiliation Type: Emergency Contact
Company Name: HOUSING DEVELOPMENT ASSOCIATES LLC
Contact Type: Not reported
Contact Name: DANIEL TOBIAS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 243-7757
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-12-06

Tank Info:

Tank Number: 001
Tank Id: 19634

309 WEST 14TH STREET (Continued) **U003390602**

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1965
Capacity Gallons: 1500
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MFLEONAR
Last Modified: 12/06/2017
Material Name: #2 fuel oil (on-site consumption)

AC580 **CON EDISON** **NY MANIFEST** **S117058577**
ESE **161-163 W 8TH AVE & 18TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.163 mi.
863 ft. **Site 8 of 8 in cluster AC**

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:
Name: CON EDISON
Address: 161-163 W 8TH AVE & 18TH ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004507034
Facility Status: Not reported
Location Address 1: 161 8TH AVE & 18 ST
Code: BP
Location Address 2: SB 32077
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004507034
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported

CON EDISON (Continued) **S117058577**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2014
Trans1 Recv Date:	04/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004507034
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416668GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AR581 **NYCDEP** **NY MANIFEST** **1009235554**
SSW **13TH ST & 9TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY**
0.164 mi.
866 ft. **Site 1 of 14 in cluster AR**

Relative: **Higher**

Actual: **15 ft.**

NY MANIFEST:

Name:	NYCDEP
Address:	13TH ST & 9TH AVE
City,State,Zip:	NEW YORK, NY
Country:	USA
EPA ID:	NYP003660131
Facility Status:	Not reported
Location Address 1:	13TH ST & 9TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP003660131
Mailing Name:	NYCDEP
Mailing Contact:	WAI MAN WONG
Mailing Address 1:	96-05 HORACE HARDING EXP
Mailing Address 2:	Not reported
Mailing City:	FLUSHING
Mailing State:	NY
Mailing Zip:	11368
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7185954784

AS582 **CON EDISON SERVICE BOX: 2137** **RCRA NonGen / NLR** **1015746987**
SW **451 W 13TH ST** **NY MANIFEST** **NYP004249882**
1/8-1/4 **NEW YORK, NY 10014**
0.166 mi.
875 ft. **Site 1 of 11 in cluster AS**

Relative: **Lower**

Actual: **10 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130317
Handler Name:	CON EDISON SERVICE BOX:	2137
Handler Address:		451 W 13TH ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004249882
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported

CON EDISON SERVICE BOX: 2137 (Continued) **1015746987**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

CON EDISON SERVICE BOX: 2137 (Continued) **1015746987**

Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130217
Handler Name: CON EDISON SERVICE BOX:	2137
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20120415
Handler Name: CON EDISON TRENCH NONE	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130317
Handler Name: CON EDISON SERVICE BOX:	2137
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON SERVICE BOX: 2137 (Continued) **1015746987**

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	451 W 13TH ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004249882
Facility Status:	Not reported
Location Address 1:	451 W 13TH ST
Code:	BP
Location Address 2:	SERV BOX 2137
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004249882
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/17/2013
Trans1 Recv Date:	02/17/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004249882
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840399JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N

CON EDISON SERVICE BOX: 2137 (Continued) **1015746987**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AO583 **350 WEST 23RD, LLC** **NY AST** **A100300904**
NE **350 WEST 23RD STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.166 mi.
875 ft. **Site 2 of 12 in cluster AO**

Relative:
Higher

Actual:
18 ft.

AST:

Name:	350 WEST 23RD, LLC
Address:	350 WEST 23RD STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-610490
Program Type:	PBS
UTM X:	584464.91607
UTM Y:	4511004.90454
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	377513
Affiliation Type:	Facility Owner
Company Name:	350 WEST 23RD, LLC
Contact Type:	MANAGING AGENT
Contact Name:	MARTIN HOLLANDER
Address1:	350 WEST 23RD STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011

350 WEST 23RD, LLC (Continued) **A100300904**

Country Code:	001
Phone:	(212) 213-0123
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-02-21

Site Id:	377513
Affiliation Type:	Facility Operator
Company Name:	350 WEST 23RD, LLC
Contact Type:	Not reported
Contact Name:	SANTOS RODRIGUZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 924-9364
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-02-21

Site Id:	377513
Affiliation Type:	Emergency Contact
Company Name:	350 WEST 23RD, LLC
Contact Type:	Not reported
Contact Name:	MARTIN HOLLANDER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 213-0123
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-02-21

Site Id:	377513
Affiliation Type:	Mail Contact
Company Name:	MARIN MANAGEMENT CORP.
Contact Type:	Not reported
Contact Name:	MARTIN HOLLANDER
Address1:	114 EAST 39TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 213-0123
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-02-21

350 WEST 23RD, LLC (Continued) **A100300904**

Tank Info:

Tank Number:	0001
Tank Id:	215953
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	I05 - Overfill - Vent Whistle
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	A00 - Tank Internal Protection - None
	K02 - Spill Prevention - Transfer Station Containment
	B00 - Tank External Protection - None
	D02 - Pipe Type - Galvanized Steel
	F00 - Pipe External Protection - None
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
	C01 - Pipe Location - Aboveground
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/02/1958
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/11/2006
Register:	True
Modified By:	msbaptis
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AO584 **CON EDISON SERVICE BOX: 4210** **NJ MANIFEST** **S117985512**
NE **350 W 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.166 mi.
875 ft. **Site 3 of 12 in cluster AO**

Relative:
Higher

Actual:
18 ft.

NJ MANIFEST:

EPA Id:	NYP004259487
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JUAN RODRIGUEZ
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported

CON EDISON SERVICE BOX: 4210 (Continued) **S117985512**

Date Change:	Not reported

Manifest:

Manifest Number:	009209919JJK
EPA ID:	NYP004259487
Date Shipped:	7/22/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	750.00 Pounds

AO585 **CON EDISON SERVICE BOX: 4210** **RCRA NonGen / NLR** **1016143212**
NE **350 W 23RD ST** **FINDS** **NYP004259487**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.166 mi. **NY MANIFEST**
875 ft. **Site 4 of 12 in cluster AO**

Relative: **Higher**
Actual: **18 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20170728
Handler Name:	CON EDISON SERVICE BOX:	4210
Handler Address:		350 W 23RD ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004259487
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 4210 (Continued) **1016143212**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170905
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20120722
Handler Name: CON EDISON SERVICE BOX:	4210
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20170728
Handler Name: CON EDISON SERVICE BOX:	4210
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 4210 (Continued) **1016143212**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055453478

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016143212
Registry ID:	110055453478
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055453478
Name:	CON EDISON SERVICE BOX: 4210
Address:	350 W 23RD ST
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	CONSOLIDATED EDISON OF NY
Address:	350 W 23RD ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004259487
Facility Status:	Not reported
Location Address 1:	350 W 23RD ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004259487
Mailing Name:	CONSOLIDATED EDISON OF NY
Mailing Contact:	TOM TEELING

CON EDISON SERVICE BOX: 4210 (Continued) **1016143212**

Mailing Address 1:	4 IRVING PLACE FLOOR 15
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/2012
Trans1 Recv Date:	07/22/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004259487
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	009209919JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	750
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AM586 **CON EDISON VAULT SUBMERSIBLE: 2930** **RCRA NonGen / NLR** **1016149208**
WSW **1-11 WEST ST** **FINDS** **NYP004278701**
1/8-1/4 **NEW YORK, NY 10004** **ECHO**
0.166 mi. **NY MANIFEST**
879 ft. **Site 11 of 13 in cluster AM**

Relative: **Lower**
Actual: **4 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20170728
Handler Name:	CON EDISON VAULT SUBMERSIBLE: 2930
Handler Address:	1-11 WEST ST
Handler City,State,Zip:	NEW YORK, NY 10004
EPA ID:	NYP004278701
Contact Name:	RICARDO CARTY
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-643-3044
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON VAULT SUBMERSIBLE: 2930 (Continued) **1016149208**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20171122
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20121121
Handler Name:	CON EDISON VAULT SUBMERSIBLE: 2930
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20170728
Handler Name:	CON EDISON VAULT SUBMERSIBLE: 2930
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No

CON EDISON VAULT SUBMERSIBLE: 2930 (Continued) **1016149208**

Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055436808

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016149208
Registry ID:	110055436808
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055436808
Name:	CON EDISON VAULT SUBMERSIBLE: 2930
Address:	1-11 WEST ST
City,State,Zip:	NEW YORK, NY 10004

NY MANIFEST:

Name:	CON EDISON
Address:	1-11 WEST ST
City,State,Zip:	NEW YORK, NY 10004
Country:	USA
EPA ID:	NYP004278701
Facility Status:	Not reported
Location Address 1:	111 WEST ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10004
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004278701
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON

CON EDISON VAULT SUBMERSIBLE: 2930 (Continued) **1016149208**

Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	11/21/2012
Trans1 Recv Date:	11/21/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/03/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004278701
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840077JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	453
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	B007
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AN587 **JOYCE THEATER** **NY AST** **U003389636**
ESE **171-175 8TH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.167 mi.
882 ft. **Site 4 of 10 in cluster AN**

Relative:
Higher

Actual:
20 ft.

AST:

Name:	JOYCE THEATER
Address:	171-175 8TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-205036
Program Type:	PBS
UTM X:	584389.31950
UTM Y:	4510674.75628
Expiration Date:	07/20/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	7157
Affiliation Type:	Facility Owner
Company Name:	JOYCE THEATER FOUNDATION
Contact Type:	EXECUTIVE DIRECTOR
Contact Name:	LINDA SHELTON
Address1:	175 8TH AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 691-9740
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-05-19

Site Id:	7157
Affiliation Type:	Mail Contact
Company Name:	JOYCE THEATER FOUNDATION
Contact Type:	Not reported
Contact Name:	SUPER/ FACILITY MANAGER
Address1:	175 EIGHTH AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 691-9740
EMail:	JORTIZ@JOYCE.ORG
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-06-29

Site Id:	7157
Affiliation Type:	Facility Operator
Company Name:	JOYCE THEATER
Contact Type:	Not reported
Contact Name:	JOYCE THEATER FOUNDATION

JOYCE THEATER (Continued) **U003389636**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 691-9740
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-05-19

Site Id:	7157
Affiliation Type:	Emergency Contact
Company Name:	JOYCE THEATER FOUNDATION
Contact Type:	Not reported
Contact Name:	PHILLIP SCHMIEDL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 691-9740
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-06-08

Tank Info:

Tank Number:	001
Tank Id:	17081
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	I04 - Overfill - Product Level Gauge (A/G)
	J02 - Dispenser - Suction Dispenser
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	G03 - Tank Secondary Containment - Vault (w/o access)
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1982
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported

JOYCE THEATER (Continued) **U003389636**

Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	06/29/2018
Material Name:	#2 fuel oil (on-site consumption)

AJ588 **CON EDISON MANHOLE: VC2** **RCRA NonGen / NLR** **1016960533**
SSW **W 13TH ST & HUDSON ST NE** **NY MANIFEST** **NYP004325296**
1/8-1/4 **NEW YORK, NY 10014**
0.169 mi.
892 ft. **Site 3 of 7 in cluster AJ**

Relative: **Higher**
Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130807
Handler Name:	CON EDISON MANHOLE: VC2
Handler Address:	W 13TH ST & HUDSON ST NE
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYP004325296
Contact Name:	JUAN RODRIGUEZ
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	347-865-5931
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---

CON EDISON MANHOLE: VC2 (Continued) **1016960533**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130707
Handler Name:	CON EDISON MANHOLE: VC2
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130807
Handler Name:	CON EDISON MANHOLE: VC2
Federal Waste Generator Description:	Not a generator, verified

CON EDISON MANHOLE: VC2 (Continued) **1016960533**

State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	W 13TH ST & HUDSON ST NE
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004325296
Facility Status:	Not reported
Location Address 1:	NE INTERSECTION W 13 ST & HUDSON ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004325296
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047

CON EDISON MANHOLE: VC2 (Continued) **1016960533**

Trans2 State ID:	NJD003812047
Generator Ship Date:	07/07/2013
Trans1 Recv Date:	07/07/2013
Trans2 Recv Date:	07/08/2013
TSD Site Recv Date:	07/08/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004325296
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002085266GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AJ589 **CON EDISON MANHOLE: VC1** **RCRA NonGen / NLR** **1016960532**
SSW **W 13TH ST & HUDSON ST** **NY MANIFEST** **NYP004325270**
1/8-1/4 **NEW YORK, NY 10014**
0.169 mi.
892 ft. **Site 4 of 7 in cluster AJ**

Relative: **Higher**
Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130807
Handler Name:	CON EDISON MANHOLE: VC1
Handler Address:	W 13TH ST & HUDSON ST
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYP004325270
Contact Name:	JUAN RODRIGUEZ
Contact Address:	Not reported

CON EDISON MANHOLE: VC1 (Continued) **1016960532**

Contact City,State,Zip:	Not reported
Contact Telephone:	347-865-5931
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No

CON EDISON MANHOLE: VC1 (Continued) **1016960532**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130707
Handler Name: CON EDISON MANHOLE: VC1	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130807
Handler Name: CON EDISON MANHOLE: VC1	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON MANHOLE: VC1 (Continued) **1016960532**

NY MANIFEST:

Name:	CON EDISON
Address:	W 13TH ST & HUDSON ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004325270
Facility Status:	Not reported
Location Address 1:	E INT W 13 ST & HUDSON ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004325270
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	07/07/2013
Trans1 Recv Date:	07/07/2013
Trans2 Recv Date:	07/08/2013
TSD Site Recv Date:	07/08/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004325270
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002085267GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON MANHOLE: VC1 (Continued) **1016960532**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AN590 **MANHATTAN ASSOCIATES.** **NY AST** **U004077260**
ESE **301-317 WEST 19TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.170 mi.
895 ft. **Site 5 of 10 in cluster AN**

Relative:
Higher

Actual:
21 ft.

AST:

Name:	MANHATTAN ASSOCIATES.
Address:	301-317 WEST 19TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-274992
Program Type:	PBS
UTM X:	584400.94000
UTM Y:	4510700.73295
Expiration Date:	06/18/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	11773
Affiliation Type:	Facility Owner
Company Name:	MANHATTAN ASSOCIATES
Contact Type:	PRESIDENT
Contact Name:	EYTAN CHISSICK
Address1:	305A WEST 19TH STREET
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 727-8208
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR

MANHATTAN ASSOCIATES. (Continued) **U004077260**

Date Last Modified: 2017-06-21

Site Id: 11773
Affiliation Type: Facility Operator
Company Name: MANHATTAN ASSOCIATES.
Contact Type: Not reported
Contact Name: IDRIZ OSMANAJ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 727-8208
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-06-21

Site Id: 11773
Affiliation Type: Emergency Contact
Company Name: MANHATTAN ASSOCIATES
Contact Type: Not reported
Contact Name: IDRIZ OSMANAJ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 331-9147
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-06-21

Site Id: 11773
Affiliation Type: Mail Contact
Company Name: MANHATTAN ASSOCIATES
Contact Type: PRESIDENT
Contact Name: EYTAN CHISSICK
Address1: 305A WEST 19TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10011
Country Code: 001
Phone: (212) 727-8208
EMail: EYTAN@EMORMANAGEMENT.COM
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2018-04-25

Tank Info:

Tank Number: 001
Tank Id: 9261

MANHATTAN ASSOCIATES. (Continued) **U004077260**

Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

K00 - Spill Prevention - None
L99 - Piping Leak Detection - Other
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
D02 - Pipe Type - Galvanized Steel
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
J05 - Dispenser - On Site Heating System (Supply/Return)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/10/1964
Capacity Gallons: 7500
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DAFRANCI
Last Modified: 04/25/2018
Material Name: #2 fuel oil (on-site consumption)

AM591 **SUNOCO STATION (VACANT)** **NY AST** **U004078196**
WSW **14TH STREET & WEST SIDE HIGHWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.170 mi.
897 ft. **Site 12 of 13 in cluster AM**

Relative: **Lower**
Actual: **3 ft.**

AST:
Name: SUNOCO STATION (VACANT)
Address: 14TH STREET & WEST SIDE HIGHWAY
City,State,Zip: NEW YORK, NY 10014
Region: STATE
DEC Region: 2
Site Status: Inactive
Facility Id: 2-603197
Program Type: PBS
UTM X: 583671.25000
UTM Y: 4510639.00000
Expiration Date: N/A
Site Type: Other

Affiliation Records:
Site Id: 25134
Affiliation Type: Facility Owner
Company Name: NEW YORK STATE DEPT. OF TRANSPORTATION
Contact Type: Not reported

SUNOCO STATION (VACANT) (Continued) **U004078196**

Contact Name:	Not reported
Address1:	29 BROADWAY, SUITE 1125
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10006
Country Code:	001
Phone:	(212) 425-8574
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25134
Affiliation Type:	Mail Contact
Company Name:	CORE CONTRACTING L.L.C.
Contact Type:	Not reported
Contact Name:	ELIZABETH KILKEARY
Address1:	513 WEST 54TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10019
Country Code:	001
Phone:	(212) 581-1598
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25134
Affiliation Type:	Facility Operator
Company Name:	SUNOCO STATION (CAVANT)
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25134
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK STATE DEPT. OF TRANSPORTATION
Contact Type:	Not reported
Contact Name:	ELIZABETH KILKEARY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported

SUNOCO STATION (VACANT) (Continued) **U004078196**

Country Code:	001
Phone:	(212) 581-1598
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	53392
Material Code:	0000
Common Name of Substance:	Empty

Equipment Records:

J00 - Dispenser - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/1997
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JAAVERSA
Last Modified:	04/14/2017
Material Name:	empty

Tank Number:	002
Tank Id:	53393
Material Code:	0000
Common Name of Substance:	Empty

Equipment Records:

J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

SUNOCO STATION (VACANT) (Continued) **U004078196**

Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Temporarily Out of Service
Pipe Model:	Not reported
Install Date:	10/01/1997
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JAAVERSA
Last Modified:	04/14/2017
Material Name:	empty

Tank Number:	003
Tank Id:	53394
Material Code:	0000
Common Name of Substance:	Empty

Equipment Records:

J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Temporarily Out of Service
Pipe Model:	Not reported
Install Date:	10/01/1997
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JAAVERSA
Last Modified:	04/14/2017
Material Name:	empty

Tank Number:	004
Tank Id:	53395
Material Code:	0000
Common Name of Substance:	Empty

Equipment Records:

J00 - Dispenser - None

SUNOCO STATION (VACANT) (Continued) **U004078196**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Temporarily Out of Service
Pipe Model:	Not reported
Install Date:	10/01/1997
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JAAVERSA
Last Modified:	04/14/2017
Material Name:	empty

Tank Number:	005
Tank Id:	53396
Material Code:	0000
Common Name of Substance:	Empty

Equipment Records:

J00 - Dispenser - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Temporarily Out of Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JAAVERSA
Last Modified:	04/14/2017
Material Name:	empty

SUNOCO STATION (VACANT) (Continued) **U004078196**

Tank Number: 006
Tank Id: 53397
Material Code: 0000
Common Name of Substance: Empty

Equipment Records:

J00 - Dispenser - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Temporarily Out of Service
Pipe Model: Not reported
Install Date: 10/01/1997
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: JAAVERSA
Last Modified: 04/14/2017
Material Name: empty

Tank Number: 007
Tank Id: 53398
Material Code: 0000
Common Name of Substance: Empty

Equipment Records:

J00 - Dispenser - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Temporarily Out of Service
Pipe Model: Not reported
Install Date: 10/01/1997
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported

SUNOCO STATION (VACANT) (Continued) **U004078196**

Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JAAVERSA
Last Modified:	04/14/2017
Material Name:	empty
Tank Number:	008
Tank Id:	53399
Material Code:	0000
Common Name of Substance:	Empty

Equipment Records:

J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Temporarily Out of Service
Pipe Model:	Not reported
Install Date:	10/01/1997
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JAAVERSA
Last Modified:	04/14/2017
Material Name:	empty
Tank Number:	009
Tank Id:	53400
Material Code:	0000
Common Name of Substance:	Empty

Equipment Records:

J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

Tank Location:	Aboveground in subterranean vault with access for inspections.....

SUNOCO STATION (VACANT) (Continued) **U004078196**

	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Temporarily Out of Service
Pipe Model:	Not reported
Install Date:	10/01/1997
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JAAVERSA
Last Modified:	04/14/2017
Material Name:	empty
Tank Number:	010
Tank Id:	53401
Material Code:	0000
Common Name of Substance:	Empty

Equipment Records:

J00 - Dispenser - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Temporarily Out of Service
Pipe Model:	Not reported
Install Date:	10/01/1997
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JAAVERSA
Last Modified:	04/14/2017
Material Name:	empty
Tank Number:	011
Tank Id:	53402
Material Code:	0000
Common Name of Substance:	Empty

Equipment Records:

J00 - Dispenser - None
C00 - Pipe Location - No Piping

SUNOCO STATION (VACANT) (Continued) **U004078196**

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Temporarily Out of Service
Pipe Model:	Not reported
Install Date:	10/01/1997
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JAAVERSA
Last Modified:	04/14/2017
Material Name:	empty

Tank Number:	012
Tank Id:	53403
Material Code:	0000
Common Name of Substance:	Empty

Equipment Records:

J00 - Dispenser - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Temporarily Out of Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JAAVERSA
Last Modified:	04/14/2017
Material Name:	empty

Tank Number:	013

SUNOCO STATION (VACANT) (Continued) **U004078196**

Tank Id: 53404
Material Code: 0000
Common Name of Substance: Empty

Equipment Records:

J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Temporarily Out of Service
Pipe Model: Not reported
Install Date: 10/01/1997
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: JAAVERSA
Last Modified: 04/14/2017
Material Name: empty

Tank Number: 014
Tank Id: 53405
Material Code: 0000
Common Name of Substance: Empty

Equipment Records:

J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Temporarily Out of Service
Pipe Model: Not reported
Install Date: 10/01/1997
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported

SUNOCO STATION (VACANT) (Continued) **U004078196**

Date Tank Closed:	Not reported
Register:	True
Modified By:	JAAVERSA
Last Modified:	04/14/2017
Material Name:	empty
Tank Number:	015
Tank Id:	53406
Material Code:	0000
Common Name of Substance:	Empty

Equipment Records:

J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Temporarily Out of Service
Pipe Model:	Not reported
Install Date:	10/01/1997
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JAAVERSA
Last Modified:	04/14/2017
Material Name:	empty

AL592 **CON EDISON** **NY MANIFEST** **S117060962**
SE **135-37 8TH AVE & 16TH ST N OF** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.170 mi.
897 ft. **Site 8 of 14 in cluster AL**

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	135-37 8TH AVE & 16TH ST N OF
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004532230
Facility Status:	Not reported
Location Address 1:	514 W 153 ST
Code:	BP
Location Address 2:	SB23059
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY

CON EDISON (Continued) **S117060962**

Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004532230
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/15/2014
Trans1 Recv Date:	05/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/16/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004532230
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002422022GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.

CON EDISON (Continued) **S117060962**

Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AL593 **CON ED** **NY MANIFEST** **S121967391**
SE **133 8TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.170 mi.
898 ft. **Site 9 of 14 in cluster AL**

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:

Name:	CON ED
Address:	133 8TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004857017
Facility Status:	Not reported
Location Address 1:	133 8TH AVE
Code:	BP
Location Address 2:	SB 32058
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004857017
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/20/2015
Trans1 Recv Date:	10/20/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004857017

CON ED (Continued) **S121967391**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014085730JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AT594 **KWIK INTL COLOR LTD** **RCRA NonGen / NLR** **1000458033**
SE **111 8TH AVE** **NY MANIFEST** **NYD986933539**
1/8-1/4 **NEW YORK, NY 10011**
0.170 mi.
899 ft. **Site 1 of 23 in cluster AT**

Relative: **Higher**
Actual: **21 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	KWIK INTL COLOR LTD	
Handler Address:		111 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYD986933539
Contact Name:		BART LUFF
Contact Address:		8TH AVE
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		212-929-3800
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified

KWIK INTL COLOR LTD (Continued) **1000458033**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	8TH AVE
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	KWIK INTERNATIONAL COLOR LTD
Owner Type:	Private
Operator Name:	KWIK INTERNATIONAL COLOR LTD
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No

KWIK INTL COLOR LTD (Continued) **1000458033**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	KWIK INTERNATIONAL COLOR LTD
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	KWIK INTERNATIONAL COLOR LTD
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	KWIK INTERNATIONAL COLOR LTD
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name:	KWIK INTL COLOR LTD

KWIK INTL COLOR LTD (Continued) **1000458033**

Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: KWIK INTL COLOR LTD
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19901219
Handler Name: KWIK INTL COLOR LTD
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: KWIK INTERNATIONAL COLOR
Address: 111 8TH AVE
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYD986933539
Facility Status: Not reported
Location Address 1: 111 8TH AVENUE

KWIK INTL COLOR LTD (Continued) **1000458033**

Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986933539
Mailing Name: KWIK INTERNATIONAL COLOR
Mailing Contact: BART LUFF
Mailing Address 1: 111 8TH AVENUE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10011
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2129293800

AT595 **CABLEVIEW PUBLICATIONS** **RCRA NonGen / NLR** **1000282230**
SE **111 8TH AVE** **NY MANIFEST** **NYD058235219**
1/8-1/4 **NEW YORK, NY 10011**
0.170 mi.
899 ft. **Site 2 of 23 in cluster AT**

Relative: **Higher**
Actual: **21 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20070101
Handler Name: CABLEVIEW PUBLICATIONS
Handler Address: 111 8TH AVE
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYD058235219
Contact Name: Not reported
Contact Address: 8TH AVE
Contact City,State,Zip: NEW YORK, NY 10011
Contact Telephone: Not reported
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY
State District: NYSDEC R2
Mailing Address: 8TH AVE
Mailing City,State,Zip: NEW YORK, NY 10011
Owner Name: IRWIN COHEN
Owner Type: Private
Operator Name: IRWIN COHEN
Operator Type: Private
Short-Term Generator Activity: No
Importer Activity: No

CABLEVIEW PUBLICATIONS (Continued) **1000282230**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:
Waste Code: D011

CABLEVIEW PUBLICATIONS (Continued) **1000282230**

Waste Description: SILVER

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	IRWIN COHEN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	IRWIN COHEN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	IRWIN COHEN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: CABLEVIEW PUBLICATIONS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: CABLEVIEW PUBLICATIONS	
Federal Waste Generator Description:	Not a generator, verified

CABLEVIEW PUBLICATIONS (Continued) **1000282230**

State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: CABLEVIEW PUBLICATIONS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19870806
Handler Name: CABLEVIEW PUBLICATIONS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CABLEVIEW PUBLICATIONS
Address: 111 8TH AVE
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYD058235219
Facility Status: Not reported
Location Address 1: 111 8TH AVE
Code: BP

CABLEVIEW PUBLICATIONS (Continued) **1000282230**

Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD058235219
Mailing Name: CABLEVIEW PUBLICATIONS
Mailing Contact: CABLEVIEW PUBLICATIONS
Mailing Address 1: 725 RVER RD-ATTN: MIKE FISHER
Mailing Address 2: Not reported
Mailing City: EDGEWATER
Mailing State: NJ
Mailing Zip: 07020
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2019416900

AT596 **NEW YORK TELEPHONE CO** **RCRA NonGen / NLR** **1000872305**
SE **111 8TH AVE - 2ND FLOOR** **FINDS** **NYD987035185**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.170 mi.
899 ft. **Site 3 of 23 in cluster AT**

Relative:
Higher

Actual:
21 ft.

RCRA NonGen / NLR:
Date Form Received by Agency: 20070101
Handler Name: NEW YORK TELEPHONE CO
Handler Address: 111 8TH AVE - 2ND FLOOR
Handler City,State,Zip: NEW YORK, NY 10011-5201
EPA ID: NYD987035185
Contact Name: Not reported
Contact Address: 11TH AVE
Contact City,State,Zip: NEW YORK, NY 10019
Contact Telephone: Not reported
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY
State District: NYSDEC R2
Mailing Address: 11TH AVE
Mailing City,State,Zip: NEW YORK, NY 10019
Owner Name: P A BUILDING CO
Owner Type: Private
Operator Name: P A BUILDING CO
Operator Type: Private
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No

NEW YORK TELEPHONE CO (Continued) **1000872305**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

NEW YORK TELEPHONE CO (Continued) **1000872305**

Waste Code: D002
Waste Description: CORROSIVE WASTE

Waste Code: D018
Waste Description: BENZENE

Waste Code: D039
Waste Description: TETRACHLOROETHYLENE

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: P A BUILDING CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 100 WILLIAM ST
Owner/Operator City,State,Zip: NEW YORK, NY 11021
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: P A BUILDING CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 100 WILLIAM ST
Owner/Operator City,State,Zip: NEW YORK, NY 11021
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: P A BUILDING CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 100 WILLIAM ST
Owner/Operator City,State,Zip: NEW YORK, NY 11021
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: NEW YORK TELEPHONE CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

NEW YORK TELEPHONE CO (Continued) **1000872305**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: NEW YORK TELEPHONE CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NEW YORK TELEPHONE CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19930315
Handler Name: NEW YORK TELEPHONE CO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004505465

NEW YORK TELEPHONE CO (Continued) **1000872305**

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000872305
Registry ID:	110004505465
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004505465
Name:	NEW YORK TELEPHONE CO
Address:	111 8TH AVE - 2ND FLOOR
City,State,Zip:	NEW YORK, NY 10011

AT597 **SPRINT COMMUNICATIONS** **NY AST** **A100382375**
SE **111 EIGHTH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.170 mi.
899 ft. **Site 4 of 23 in cluster AT**

Relative:
Higher

Actual:
21 ft.

AST:

Name:	SPRINT COMMUNICATIONS
Address:	111 EIGHTH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-604532
Program Type:	PBS
UTM X:	584306.38136
UTM Y:	4510466.61657
Expiration Date:	N/A
Site Type:	Utility (Other than Municipal)

Tank Info:

Tank Number:	001
Tank Id:	58096
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/01/2006
Register:	True
Modified By:	NRLOMBAR

SPRINT COMMUNICATIONS (Continued) **A100382375**

Last Modified:	04/14/2017
Material Name:	Not reported

Tank Number:	002
Tank Id:	58097
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/01/2006
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	Not reported

Tank Number:	003
Tank Id:	58098
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	100
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/01/2006
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	Not reported

AT598 **V L G NORTH AMERICA INC** **RCRA NonGen / NLR** **1004762714**
SE **111 8TH AVE STE 500** **FINDS** **NYR000099721**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.170 mi. **NY MANIFEST**
899 ft. **Site 5 of 23 in cluster AT**

Relative: RCRA NonGen / NLR:
Higher

Date Form Received by Agency:		20070101
Handler Name:	V L G NORTH AMERICA INC	
Handler Address:		111 8TH AVE STE 500
Handler City,State,Zip:		NEW YORK, NY 10011-5200
EPA ID:		NYR000099721
Contact Name:		JERRY WEBERS
Contact Address:		8TH AVE STE 500
Contact City,State,Zip:		NEW YORK, NY 10011-5200
Contact Telephone:		917-606-7035
Contact Fax:		Not reported

Actual:
21 ft.

V L G NORTH AMERICA INC (Continued) **1004762714**

Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	8TH AVE STE 500
Mailing City,State,Zip:	NEW YORK, NY 10011-5200
Owner Name:	INSIGNIA E S G
Owner Type:	Private
Operator Name:	INSIGNIA E S G
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A

V L G NORTH AMERICA INC (Continued) **1004762714**

Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	INSIGNIA E S G
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	111 8TH AVE STE 500
Owner/Operator City,State,Zip:	NEW YORK, NY 10011-5200
Owner/Operator Telephone:	212-243-5060
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	INSIGNIA E S G
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	111 8TH AVE STE 500
Owner/Operator City,State,Zip:	NEW YORK, NY 10011-5200
Owner/Operator Telephone:	212-243-5060
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	INSIGNIA E S G
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	111 8TH AVE STE 500
Owner/Operator City,State,Zip:	NEW YORK, NY 10011-5200

V L G NORTH AMERICA INC (Continued) **1004762714**

Owner/Operator Telephone: 212-243-5060
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: V L G NORTH AMERICA INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: V L G NORTH AMERICA INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010803
Handler Name: V L G NORTH AMERICA INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

V L G NORTH AMERICA INC (Continued) **1004762714**

FINDS:
Registry ID: 110012235624

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004762714
Registry ID:	110012235624
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110012235624
Name:	V L G NORTH AMERICA INC
Address:	111 8TH AVE STE 500
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	VLG NORTH AMERICA
Address:	111 8TH AVE STE 500
City,State,Zip:	NEW YORK, NY 10011-5200
Country:	USA
EPA ID:	NYR000099721
Facility Status:	Not reported
Location Address 1:	111 8TH AVE STE 500
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000099721
Mailing Name:	VLG NORTH AMERICA
Mailing Contact:	JERRY WEBERS
Mailing Address 1:	111 8TH AVE STE 500
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9176067035

AT599 **ONE CITY BLOCK, LLC** **NY AST** **U004078114**
SE **111 8TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.170 mi.
899 ft. **Site 6 of 23 in cluster AT**

Relative:
Higher

Actual:
21 ft.

AST:

Name:	ONE CITY BLOCK, LLC
Address:	111 8TH AVE
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-601905
Program Type:	PBS
UTM X:	584264.63337
UTM Y:	4510467.92384
Expiration Date:	12/23/2025
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	23867
Affiliation Type:	Facility Owner
Company Name:	ONE CITY BLOCK, LLC.
Contact Type:	CHIEF ENGINEER
Contact Name:	BRIAN ALTINI
Address1:	11 8TH AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 243-5060
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-01-06

Site Id:	23867
Affiliation Type:	Emergency Contact
Company Name:	ONE CITY BLOCK C/O TACONIC MGMT CO.
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	n/a
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-01-06

Site Id:	23867
Affiliation Type:	Facility Operator
Company Name:	111 EIGTH AVENUE
Contact Type:	Not reported
Contact Name:	BRIAN ALTINI

ONE CITY BLOCK, LLC (Continued) **U004078114**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 243-5060
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-01-06

Site Id:	23867
Affiliation Type:	Mail Contact
Company Name:	JONES LIANGE LASALLE
Contact Type:	Not reported
Contact Name:	BRIAN ALTINI
Address1:	11 8TH AVENUE, SUITE 1513
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 243-5060
EMail:	BRIAN.ALTINI@AM.JLL.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-01-06

Tank Info:

Tank Number:	001
Tank Id:	48251
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	G01 - Tank Secondary Containment - Diking (Aboveground)
	J02 - Dispenser - Suction Dispenser
	C03 - Pipe Location - Aboveground/Underground Combination
	F00 - Pipe External Protection - None
	H00 - Tank Leak Detection - None
	I02 - Overfill - High Level Alarm
	L09 - Piping Leak Detection - Exempt Suction Piping
	E00 - Piping Secondary Containment - None
	K00 - Spill Prevention - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	A00 - Tank Internal Protection - None
Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/1994
Capacity Gallons:	20000

ONE CITY BLOCK, LLC (Continued) **U004078114**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DMPOKRZY
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 002
Tank Id: 56988
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
F00 - Pipe External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 05/01/1994
Capacity Gallons: 20000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DMPOKRZY
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 003
Tank Id: 56989
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm

ONE CITY BLOCK, LLC (Continued) **U004078114**

L09 - Piping Leak Detection - Exempt Suction Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/1994
Capacity Gallons:	20000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)
Tank Number:	004
Tank Id:	56990
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
F00 - Pipe External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/1997
Capacity Gallons:	20000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

ONE CITY BLOCK, LLC (Continued) **U004078114**

Tank Number: 005
Tank Id: 56991
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
G01 - Tank Secondary Containment - Diking (Aboveground)
F00 - Pipe External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 05/01/1997
Capacity Gallons: 20000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DMPOKRZY
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 006
Tank Id: 56992
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron

ONE CITY BLOCK, LLC (Continued) **U004078114**

Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/1997
Capacity Gallons:	20000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	007
Tank Id:	56993
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G01 - Tank Secondary Containment - Diking (Aboveground)
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/1997
Capacity Gallons:	20000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	008
Tank Id:	56994
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G01 - Tank Secondary Containment - Diking (Aboveground)

ONE CITY BLOCK, LLC (Continued) **U004078114**

C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/1997
Capacity Gallons:	16200
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AT600 **STATE INSURANCE FUND THE** **RCRA NonGen / NLR** **1004761661**
SE **111 8TH AVE 10TH FLOOR** **FINDS** **NYR000089128**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.170 mi. **NY MANIFEST**
899 ft. **Site 7 of 23 in cluster AT**

Relative: **Higher**
Actual: **21 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	STATE INSURANCE FUND THE
Handler Address:	111 8TH AVE 10TH FLOOR
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYR000089128
Contact Name:	RAYMOND ARROYO
Contact Address:	8TH AVE 10TH FLOOR
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	212-462-2190
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	8TH AVE 10TH FLOOR
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	THE STATE INSURANCE FUND

STATE INSURANCE FUND THE (Continued) **1004761661**

Owner Type:	Private
Operator Name:	THE STATE INSURANCE FUND
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

STATE INSURANCE FUND THE (Continued) **1004761661**

Sub-Part P Indicator: No

Hazardous Waste Summary:

Waste Code: D002
Waste Description: CORROSIVE WASTE

Waste Code: D008
Waste Description: LEAD

Waste Code: F001
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator: Owner
Owner/Operator Name: THE STATE INSURANCE FUND
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 111 8TH AVE 10TH FLOOR
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 212-462-2190
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE STATE INSURANCE FUND
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 111 8TH AVE 10TH FLOOR
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 212-462-2190
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

STATE INSURANCE FUND THE (Continued) **1004761661**

Owner/Operator Indicator:	Owner
Owner/Operator Name:	THE STATE INSURANCE FUND
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	111 8TH AVE 10TH FLOOR
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	212-462-2190
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name:	STATE INSURANCE FUND THE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	STATE INSURANCE FUND THE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20000825
Handler Name:	STATE INSURANCE FUND THE
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

STATE INSURANCE FUND THE (Continued) **1004761661**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004564061

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004761661
Registry ID:	110004564061
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004564061
Name:	STATE INSURANCE FUND THE
Address:	111 8TH AVE 10TH FLOOR
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	STATE INSURANCE FUND
Address:	111 8TH AVE 10TH FLOOR
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYR000089128
Facility Status:	Not reported
Location Address 1:	111 8TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000089128
Mailing Name:	STATE INSURANCE FUND
Mailing Contact:	RAYMOND ARROYO
Mailing Address 1:	111 8TH AVE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported

STATE INSURANCE FUND THE (Continued) **1004761661**

Mailing Country: USA
Mailing Phone: 2124622190

AT601 **INSIGNIA ESG** **RCRA NonGen / NLR** **1001961651**
SE **111 8TH AVE - BASEMENT** **FINDS** **NYR000084640**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.170 mi. **NY MANIFEST**
899 ft. **Site 8 of 23 in cluster AT**

Relative: **Higher**
Actual: **21 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	INSIGNIA ESG	
Handler Address:		111 8TH AVE - BASEMENT
Handler City,State,Zip:		NEW YORK, NY 10011-5201
EPA ID:		NYR000084640
Contact Name:		WAYNE WIEDMAN
Contact Address:		8TH AVE - BASEMENT
Contact City,State,Zip:		NEW YORK, NY 10011-5201
Contact Telephone:		212-243-5060
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		8TH AVE - BASEMENT
Mailing City,State,Zip:		NEW YORK, NY 10011-5201
Owner Name:		TACOWIC INVESTMENTS PARTNERS
Owner Type:		Private
Operator Name:		TACOWIC INVESTMENTS PARTNERS
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported

INSIGNIA ESG (Continued) **1001961651**

Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D002
Waste Description:	CORROSIVE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	TACOWIC INVESTMENTS PARTNERS
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	111 8TH AVE
Owner/Operator City,State,Zip:	NEW YORK, NY 10011-5201
Owner/Operator Telephone:	212-243-5060
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	TACOWIC INVESTMENTS PARTNERS

INSIGNIA ESG (Continued) **1001961651**

Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	111 8TH AVE
Owner/Operator City,State,Zip:	NEW YORK, NY 10011-5201
Owner/Operator Telephone:	212-243-5060
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	TACOWIC INVESTMENTS PARTNERS
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	111 8TH AVE
Owner/Operator City,State,Zip:	NEW YORK, NY 10011-5201
Owner/Operator Telephone:	212-243-5060
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: INSIGNIA ESG	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: INSIGNIA ESG	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20000209
Handler Name: INSIGNIA ESG	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

INSIGNIA ESG (Continued) **1001961651**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004561331

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001961651
Registry ID: 110004561331
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004561331
Name: INSIGNIA ESG
Address: 111 8TH AVE - BASEMENT
City,State,Zip: NEW YORK, NY 10011

NY MANIFEST:
Name: INSIGNIA
Address: 111 8TH AVE - BASEMENT
City,State,Zip: NEW YORK, NY 10011-5201
Country: USA
EPA ID: NYR000084640
Facility Status: Not reported
Location Address 1: 111 8TH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10001
Location Zip 4: Not reported

NY MANIFEST:

INSIGNIA ESG (Continued) **1001961651**

EPAID:	NYR000084640
Mailing Name:	INSIGNIA
Mailing Contact:	N/S
Mailing Address 1:	111 8TH AVE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10001
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2122435060

AT602 **EFFECTS HOUSE THE** **RCRA NonGen / NLR** **1000201177**
SE **111 8TH AVE RM 914** **FINDS** **NYD986887370**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.170 mi. **NY MANIFEST**
899 ft. **Site 9 of 23 in cluster AT**

Relative: **Higher**
Actual: **21 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	EFFECTS HOUSE THE	
Handler Address:		111 8TH AVE RM 914
Handler City,State,Zip:		NEW YORK, NY 10011-5201
EPA ID:		NYD986887370
Contact Name:		Not reported
Contact Address:		8TH AVE RM 914
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		8TH AVE RM 914
Mailing City,State,Zip:		NEW YORK, NY 10011
Owner Name:		J ALAGNA, D NOLAN & R ROWOHLT
Owner Type:		Private
Operator Name:		J ALAGNA, D NOLAN & R ROWOHLT
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No

EFFECTS HOUSE THE (Continued) **1000201177**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	U226
Waste Description:	ETHANE, 1,1,1-TRICHLORO- (OR) METHYL CHLOROFORM

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	J ALAGNA, D NOLAN & R ROWOHLT
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported

EFFECTS HOUSE THE (Continued) **1000201177**

Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	J ALAGNA, D NOLAN & R ROWOHLT
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	J ALAGNA, D NOLAN & R ROWOHLT
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: EFFECTS HOUSE THE	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20060101
Handler Name: EFFECTS HOUSE THE	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

EFFECTS HOUSE THE (Continued) **1000201177**

Receive Date: 20070101
Handler Name: EFFECTS HOUSE THE
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900118
Handler Name: EFFECTS HOUSE THE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19910614
Actual Return to Compliance Date: 19910809
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19910714
Enforcement Identifier: 000
Date of Enforcement Action: 19910614
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported

EFFECTS HOUSE THE (Continued) **1000201177**

SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19910517
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19910809
Scheduled Compliance Date:	19910714
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110004440882

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000201177
Registry ID:	110004440882
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004440882
Name:	EFFECTS HOUSE THE
Address:	111 8TH AVE RM 914
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	EFFECTS HOUSE INCORPORATED
Address:	111 8TH AVE RM 914
City,State,Zip:	NEW YORK, NY 10011-5201
Country:	USA
EPA ID:	NYD986887370

EFFECTS HOUSE THE (Continued) **1000201177**

Facility Status:	Not reported
Location Address 1:	111 EIGHTH AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986887370
Mailing Name:	EFFECTS HOUSE INCORPORATED
Mailing Contact:	EFFECTS HOUSE INCORPORATED
Mailing Address 1:	111 EIGHTH AVENUE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2129249150

AT603 **CON EDISON - 111 8TH AVENUE SERVICE** **RCRA NonGen / NLR** **1000111685**
SE **111 8TH AVE** **NY MANIFEST** **NYD982279598**
1/8-1/4 **NEW YORK, NY 10011**
0.170 mi.
899 ft. **Site 10 of 23 in cluster AT**

Relative:
Higher

Actual:
21 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	CON EDISON - 111 8TH AVENUE SERVICE
Handler Address:	111 8TH AVE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYD982279598
Contact Name:	Not reported
Contact Address:	IRVING PL ROOM 300
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL ROOM 300
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	P A BUILDING CO
Owner Type:	Private
Operator Name:	P A BUILDING CO
Operator Type:	Private

CON EDISON - 111 8TH AVENUE SERVICE (Continued) **1000111685**

Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

CON EDISON - 111 8TH AVENUE SERVICE (Continued) **1000111685**

Hazardous Waste Summary:
Waste Code: X002
Waste Description: Not Defined

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: P A BUILDING CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: P A BUILDING CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: P A BUILDING CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: CON EDISON - 111 8TH AVENUE SERVICE
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101

CON EDISON - 111 8TH AVENUE SERVICE (Continued) **1000111685**

Handler Name: CON EDISON - 111 8TH AVENUE SERVICE
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: CON EDISON - 111 8TH AVENUE SERVICE
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19871120
Handler Name: CON EDISON - 111 8TH AVENUE SERVICE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960329
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010101
Handler Name: 111 EIGHTH AVENUE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

CON EDISON - 111 8TH AVENUE SERVICE (Continued) **1000111685**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code: 22111
NAICS Description: ELECTRIC POWER GENERATION

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19970109
Evaluation Responsible Agency: State

CON EDISON - 111 8TH AVENUE SERVICE (Continued) **1000111685**

Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYADS
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

NY MANIFEST:

Name:	CONSOLIDATED EDISON COMPANY OF NEW YORK
Address:	111 8TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYD982279598
Facility Status:	Not reported
Location Address 1:	111 EIGHTH AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD982279598
Mailing Name:	CONSOLIDATED EDISON COMPANY OF NEW YORK
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

AT604 **GOLDMAN SACHS & CO-111 8TH AVE** **RCRA NonGen / NLR** **1000871739**
SE **111 8TH AVENUE ROOM 815** **FINDS** **NY0000094524**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.170 mi. **NY MANIFEST**
899 ft. **Site 11 of 23 in cluster AT**

Relative:
Higher

Actual:
21 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	GOLDMAN SACHS & CO	
Handler Address:		111 8TH AVE ROOM 815
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NY0000094524
Contact Name:		ROBERT NEEDLE
Contact Address:		8TH AVE ROOM 815
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		212-902-1156

GOLDMAN SACHS & CO-111 8TH AVE (Continued) **1000871739**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	8TH AVE ROOM 815
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	GOLDMAN SACHS & CO
Owner Type:	Private
Operator Name:	GOLDMAN SACHS & CO
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

GOLDMAN SACHS & CO-111 8TH AVE (Continued) **1000871739**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	GOLDMAN SACHS & CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	85 BROAD ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	212-902-1000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GOLDMAN SACHS & CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	85 BROAD ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	212-902-1000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner

GOLDMAN SACHS & CO-111 8TH AVE (Continued) **1000871739**

Owner/Operator Name:	GOLDMAN SACHS & CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	85 BROAD ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	212-902-1000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: GOLDMAN SACHS & CO	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: GOLDMAN SACHS & CO	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19940107
Handler Name: GOLDMAN SACHS & CO	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

GOLDMAN SACHS & CO-111 8TH AVE (Continued) **1000871739**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004310996

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000871739
Registry ID:	110004310996
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004310996
Name:	GOLDMAN SACHS & CO-111 8TH AVE
Address:	111 8TH AVENUE ROOM 815
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	GOLDMAN-SACHS
Address:	111 8TH AVE ROOM 815
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NY0000094524
Facility Status:	Not reported
Location Address 1:	111 8TH AVE RM 815 8TH FLOOR
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10036
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NY0000094524
Mailing Name:	GOLDMAN-SACHS
Mailing Contact:	SCOTT LAUER
Mailing Address 1:	111 8TH AVE RM 815 8TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10036
Mailing Zip 4:	Not reported

GOLDMAN SACHS & CO-111 8TH AVE (Continued) **1000871739**

Mailing Country: USA
Mailing Phone: 2129021158

AT605 **MORGAN GUARANTY TRUST CO** **RCRA NonGen / NLR** **1000232547**
SE **111 8TH AVE** **NYD981877624**
1/8-1/4 **NEW YORK, NY 10011**
0.170 mi.
899 ft. **Site 12 of 23 in cluster AT**

Relative: **Higher**
Actual: **21 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	MORGAN GUARANTY TRUST CO
Handler Address:	111 8TH AVE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYD981877624
Contact Name:	Not reported
Contact Address:	8TH AVE
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	8TH AVE
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	PA BUILDING
Owner Type:	Private
Operator Name:	PA BUILDING
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported

MORGAN GUARANTY TRUST CO (Continued) **1000232547**

Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	X001
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	PA BUILDING
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212

MORGAN GUARANTY TRUST CO (Continued) **1000232547**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: PA BUILDING
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: PA BUILDING
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: MORGAN GUARANTY TRUST CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: MORGAN GUARANTY TRUST CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MORGAN GUARANTY TRUST CO

MORGAN GUARANTY TRUST CO (Continued) **1000232547**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19870310
Handler Name:	MORGAN GUARANTY TRUST CO
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AJ606 **CON EDISON SERVICE BOX: 2145** **RCRA NonGen / NLR** **1016971304**
South **339 W 13TH ST** **NY MANIFEST** **NYP004450409**
1/8-1/4 **NEW YORK, NY 10014**
0.170 mi.
900 ft. **Site 5 of 7 in cluster AJ**

Relative: **Higher**
Actual: **18 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20140324
Handler Name:	CON EDISON SERVICE BOX: 2145
Handler Address:	339 W 13TH ST
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYP004450409
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified

CON EDISON SERVICE BOX: 2145 (Continued) **1016971304**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No

CON EDISON SERVICE BOX: 2145 (Continued) **1016971304**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140224
Handler Name: CON EDISON SERVICE BOX:	2145
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140324
Handler Name: CON EDISON SERVICE BOX:	2145
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	339 W 13TH ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004450409

CON EDISON SERVICE BOX: 2145 (Continued) **1016971304**

Facility Status:	Not reported
Location Address 1:	F/O 339 WEST 13TH ST
Code:	BP
Location Address 2:	SB2145
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004450409
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/24/2014
Trans1 Recv Date:	02/24/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/26/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004450409
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002358541GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON SERVICE BOX: 2145 (Continued) **1016971304**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AJ607 **MONADNOCK CONSTRUCTION INC** **RCRA NonGen / NLR** **1001223696**
South **339-345 W 13TH ST** **FINDS** **NYR000049114**
1/8-1/4 **NEW YORK, NY 10014** **ECHO**
0.170 mi.
900 ft. **Site 6 of 7 in cluster AJ**

Relative: **Higher**

Actual: **18 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	MONADNOCK CONSTRUCTION INC
Handler Address:	339-345 W 13TH ST
Handler City,State,Zip:	NEW YORK, NY 10014-1207
EPA ID:	NYR000049114
Contact Name:	Not reported
Contact Address:	W 13TH ST
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 13TH ST
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	NEWTON LOFT
Owner Type:	Private
Operator Name:	NEWTON LOFT
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No

MONADNOCK CONSTRUCTION INC (Continued) **1001223696**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D008
Waste Description:	LEAD

MONADNOCK CONSTRUCTION INC (Continued) **1001223696**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NEWTON LOFT
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	155 3RD ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11231
Owner/Operator Telephone:	718-875-8160
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NEWTON LOFT
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	155 3RD ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11231
Owner/Operator Telephone:	718-875-8160
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NEWTON LOFT
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	155 3RD ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11231
Owner/Operator Telephone:	718-875-8160
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name:	MONADNOCK CONSTRUCTION INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name:	MONADNOCK CONSTRUCTION INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

MONADNOCK CONSTRUCTION INC (Continued) **1001223696**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MONADNOCK CONSTRUCTION INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980122
Handler Name: MONADNOCK CONSTRUCTION INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004539768

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MONADNOCK CONSTRUCTION INC (Continued) **1001223696**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001223696
Registry ID:	110004539768
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004539768
Name:	MONADNOCK CONSTRUCTION INC
Address:	339-345 W 13TH ST
City,State,Zip:	NEW YORK, NY 10014

AM608 **GOTHAM WEST DEVELOPMENT** **NY UST** **U004180311**
WSW **592 11TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.170 mi.
900 ft. **Site 13 of 13 in cluster AM**

Relative:
Lower

Actual:
7 ft.

UST:

Name:	GOTHAM WEST DEVELOPMENT
Address:	592 11TH AVE
City,State,Zip:	NEW YORK, NY 10014
Id/Status:	2-611602 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583691.99265
UTM Y:	4510578.80650
Site Type:	Other

Affiliation Records:

Site Id:	450398
Affiliation Type:	Facility Operator
Company Name:	GOTHAM WEST DEVELOPMENT
Contact Type:	Not reported
Contact Name:	DEREK PARSONS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 559-4337
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BKFALVEY
Date Last Modified:	2011-10-14

Site Id:	450398
Affiliation Type:	Emergency Contact
Company Name:	NYS HPD
Contact Type:	Not reported
Contact Name:	DEREK PARSONS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported

GOTHAM WEST DEVELOPMENT (Continued) **U004180311**

Country Code:	999
Phone:	(917) 559-4337
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BKFALVEY
Date Last Modified:	2011-10-14

Site Id:	450398
Affiliation Type:	Facility Owner
Company Name:	44TH STREET DEVELOPMENT, LLC
Contact Type:	PRES
Contact Name:	DAVID L. PICKET
Address1:	1010 AVENUE OF THE AMERICAS, 4TH FLR
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10018
Country Code:	001
Phone:	(212) 599-0520
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2011-11-16

Site Id:	450398
Affiliation Type:	Mail Contact
Company Name:	LANGDAN ENGR & ENVIRONMENTAL SERVICES
Contact Type:	Not reported
Contact Name:	STUART KNOOP
Address1:	1010 AVENUE OF THE AMERICAS, 4TH FLR
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10018
Country Code:	001
Phone:	(212) 599-0520
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2011-11-16

Tank Info:

Tank Number:	01
Tank ID:	239679
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	05/01/1950
Date Tank Closed:	08/16/2011
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN

GOTHAM WEST DEVELOPMENT (Continued) **U004180311**

Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MSBAPTIS
Last Modified:	04/14/2017

Equipment Records:

J00 - Dispenser - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	02
Tank ID:	239680
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	05/01/1950
Date Tank Closed:	08/16/2011
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MSBAPTIS
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
I00 - Overfill - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number:	03
Tank ID:	239681

GOTHAM WEST DEVELOPMENT (Continued) **U004180311**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	05/01/1950
Date Tank Closed:	08/16/2011
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MSBAPTIS
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J00 - Dispenser - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping

Tank Number:	04
Tank ID:	239682
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	05/01/1950
Date Tank Closed:	08/16/2011
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MSBAPTIS
Last Modified:	04/14/2017

Equipment Records:

J00 - Dispenser - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None

GOTHAM WEST DEVELOPMENT (Continued) **U004180311**

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 05
Tank ID: 239683
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1950
Date Tank Closed: 08/16/2011
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MSBAPTIS
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
J00 - Dispenser - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None

Tank Number: 06
Tank ID: 239684
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1950
Date Tank Closed: 08/16/2011
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

GOTHAM WEST DEVELOPMENT (Continued) **U004180311**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MSBAPTIS
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J00 - Dispenser - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping

Tank Number: 07
Tank ID: 239685
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1950
Date Tank Closed: 08/16/2011
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MSBAPTIS
Last Modified: 04/14/2017

Equipment Records:

D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None

Tank Number: 08

GOTHAM WEST DEVELOPMENT (Continued) **U004180311**

Tank ID:	239686
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	05/01/1950
Date Tank Closed:	08/16/2011
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MSBAPTIS
Last Modified:	04/14/2017

Equipment Records:

J00 - Dispenser - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None

Tank Number:	09
Tank ID:	239687
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	05/01/1950
Date Tank Closed:	08/16/2011
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MSBAPTIS
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

GOTHAM WEST DEVELOPMENT (Continued) **U004180311**

B00 - Tank External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping

Tank Number:	10
Tank ID:	239688
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	05/01/1950
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	CGFREEDM
Last Modified:	04/14/2017

Equipment Records:

D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None

AU609 **CON EDISON SERVICE BOX: 4211** **RCRA NonGen / NLR** **1017772927**
NE **350 W 23RD ST & 9TH AVE** **FINDS** **NYP004507042**
1/8-1/4 **NEW YORK, NY 10011**
0.172 mi.
906 ft. **Site 1 of 16 in cluster AU**

Relative:
Higher

Actual:
17 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	20140522
Handler Name:	CON EDISON SERVICE BOX: 4211
Handler Address:	350 W 23RD ST & 9TH AVE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004507042
Contact Name:	THOMAS TEELING

CON EDISON SERVICE BOX: 4211 (Continued) **1017772927**

Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking

CON EDISON SERVICE BOX: 4211 (Continued) **1017772927**

Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140522
Handler Name: CON EDISON SERVICE BOX:	4211
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CON EDISON SERVICE BOX: 4211 (Continued) **1017772927**

Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063802906

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AU610 **CON EDISON SERVICE BOX: 4202** **RCRA NonGen / NLR** **1017772931**
NE **335 W 23RD ST & 9TH AVE** **FINDS** **NYP004507083**
1/8-1/4 **NEW YORK, NY 10011**
0.172 mi.
906 ft. **Site 2 of 16 in cluster AU**

Relative: **Higher**
Actual: **17 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20140522
Handler Name: CON EDISON SERVICE BOX: 4202
Handler Address: 335 W 23RD ST & 9TH AVE
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYP004507083
Contact Name: THOMAS TEELING
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-3770
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: SENIOR SCIENTIST
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY

CON EDISON SERVICE BOX: 4202 (Continued) **1017772931**

State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No

CON EDISON SERVICE BOX: 4202 (Continued) **1017772931**

Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:

Receive Date: 20140422
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140422
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140522
Handler Name: CON EDISON SERVICE BOX: 4202
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

CON EDISON SERVICE BOX: 4202 (Continued) **1017772931**

FINDS:
Registry ID: 110063802942

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AU611 **CON EDISON SERVICE BOX: 4207** **RCRA NonGen / NLR** **1017773061**
NE **366 W 23RD ST & 9TH AVE E OF** **FINDS** **NYP004508396**
1/8-1/4 **NEW YORK, NY 10011**
0.172 mi.
906 ft. **Site 3 of 16 in cluster AU**

Relative:
Higher

Actual:
17 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	20140522
Handler Name:	CON EDISON SERVICE BOX: 4207
Handler Address:	366 W 23RD ST & 9TH AVE E OF
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004508396
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No

CON EDISON SERVICE BOX: 4207 (Continued) **1017773061**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON SERVICE BOX: 4207 (Continued) **1017773061**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140422
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140522
Handler Name: CON EDISON SERVICE BOX: 4207
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063806966

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AU612
NE
1/8-1/4
0.172 mi.
906 ft.

CON EDISON SERVICE BOX: 4198
363-61 W 23RD ST & 9TH AVE E OF
NEW YORK, NY 10011

Site 4 of 16 in cluster AU

RCRA NonGen / NLR **1017773059**
FINDS **NYP004508370**

Relative:
Higher

Actual:
17 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20140522
Handler Name:	CON EDISON SERVICE BOX:	4198
Handler Address:		363-61 W 23RD ST & 9TH AVE E OF
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004508370
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 4198 (Continued) **1017773059**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 4198 (Continued) **1017773059**

Electronic Manifest Broker: Not reported

Receive Date: 20140522
Handler Name: CON EDISON SERVICE BOX: 4198
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063806948

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AU613
NE
1/8-1/4
0.172 mi.
906 ft.

CON EDISON SERVICE BOX: 4220 **RCRA NonGen / NLR** **1017773093**
316 W 23RD ST & 9TH AVE E OF **FINDS** **NYP004508719**
NEW YORK, NY 10011

Site 5 of 16 in cluster AU

Relative: Higher

Actual: 17 ft.

RCRA NonGen / NLR:
Date Form Received by Agency: 20140523
Handler Name: CON EDISON SERVICE BOX: 4220
Handler Address: 316 W 23RD ST & 9TH AVE E OF
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYP004508719
Contact Name: THOMAS TEELING
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-3770

CON EDISON SERVICE BOX: 4220 (Continued) **1017773093**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

CON EDISON SERVICE BOX: 4220 (Continued) **1017773093**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140423
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140423
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140523
Handler Name: CON EDISON SERVICE BOX: 4220	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 4220 (Continued) **1017773093**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063761095

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AU614 **CON EDISON SERVICE BOX: 4201** **RCRA NonGen / NLR** **1017773062**
NE **341 W 23RD ST & 9TH AVE E OF** **FINDS** **NYP004508404**
1/8-1/4 **NEW YORK, NY 10011**
0.172 mi.
906 ft. **Site 6 of 16 in cluster AU**

Relative: Higher
Actual: 17 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20140522
Handler Name:	CON EDISON SERVICE BOX:	4201
Handler Address:		341 W 23RD ST & 9TH AVE E OF
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004508404
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported

CON EDISON SERVICE BOX: 4201 (Continued) **1017773062**

Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 4201 (Continued) **1017773062**

Sub-Part P Indicator: No

Historic Generators:

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140522
Handler Name: CON EDISON SERVICE BOX:	4201
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063806975

CON EDISON SERVICE BOX: 4201 (Continued) **1017773062**

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AU615 **CON EDISON SERVICE BOX: 4218** **RCRA NonGen / NLR** **1017773090**
NE **324-22 W 23RD ST & 9TH AVE E OF** **FINDS** **NYP004508685**
1/8-1/4 **NEW YORK, NY 10011**
0.172 mi.
906 ft. **Site 7 of 16 in cluster AU**

Relative: **Higher**
Actual: **17 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140523
Handler Name:	CON EDISON SERVICE BOX:	4218
Handler Address:		324-22 W 23RD ST & 9TH AVE E OF
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004508685
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No

CON EDISON SERVICE BOX: 4218 (Continued) **1017773090**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140423
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

CON EDISON SERVICE BOX: 4218 (Continued) **1017773090**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140423
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140523
Handler Name: CON EDISON SERVICE BOX: 4218
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063761068

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AU616 **CON EDISON** **RCRA NonGen / NLR** **1019904184**
NE **9TH AVE & W 23RD ST** **FINDS** **NYP004794798**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.173 mi.
916 ft. **Site 8 of 16 in cluster AU**

Relative: **Higher**

Actual: **17 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150615
Handler Name:	CON EDISON	
Handler Address:		9TH AVE & W 23RD ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004794798
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1019904184**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150615
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150615
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1019904184**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069691872

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019904184
Registry ID:	110069691872
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069691872
Name:	CON EDISON
Address:	9TH AVE & W 23RD ST
City,State,Zip:	NEW YORK, NY 10011

AU617 **CON EDISON** **NY MANIFEST** **S119075899**
NE **9TH AVE & W 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.173 mi.
916 ft. **Site 9 of 16 in cluster AU**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	9TH AVE & W 23RD ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004794798
Facility Status:	Not reported
Location Address 1:	9TH AVE & 23RD ST
Code:	BP
Location Address 2:	SB 4196
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

CON EDISON (Continued) **S119075899**

NY MANIFEST:

EPAID:	NYP004794798
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/15/2015
Trans1 Recv Date:	06/15/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/16/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004794798
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002614400GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S119075899**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AU618 **CON EDISON** **NJ MANIFEST** **S120672838**
NE **9TH AVE & W 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.173 mi.
916 ft. **Site 10 of 16 in cluster AU**

Relative:
Higher

Actual:
17 ft.

NJ MANIFEST:

EPA Id:	NYP004794798
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002614400GBF
EPA ID:	NYP004794798
Date Shipped:	6/15/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported

CON EDISON (Continued) **S120672838**

QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AU619 **CON EDISON - MANHOLE 39690** **NY MANIFEST** **S120958321**
NE **23 & 9TH AVE** **N/A**
1/8-1/4 **MANHATTAN, NY 10010**
0.173 mi.
916 ft. **Site 11 of 16 in cluster AU**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON - MANHOLE 39690
Address:	23 & 9TH AVE
City,State,Zip:	MANHATTAN, NY 10010
Country:	USA
EPA ID:	NYP004929804
Facility Status:	Not reported
Location Address 1:	23 & 9TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MANHATTAN
Location State:	NY
Location Zip:	10010
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004929804
Mailing Name:	CON EDISON - MANHOLE 39690
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

AG620 **505 W 22ND STREET** **NY AST** **A100366161**
North **505 W 22ND STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.175 mi.
923 ft. **Site 8 of 13 in cluster AG**

Relative:
Lower

Actual:
10 ft.

AST:

Name:	505 W 22ND STREET
Address:	505 W 22ND STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-611981
Program Type:	PBS
UTM X:	583997.94575
UTM Y:	4511181.24156
Expiration Date:	12/27/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	479563
Affiliation Type:	Mail Contact
Company Name:	ARCHANGEL MICHAEL REALTY, INC
Contact Type:	Not reported
Contact Name:	MICHAEL TSOUMPAS
Address1:	157 LEXINGTON AVE.
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(646) 692-8991
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-12-30

Site Id:	479563
Affiliation Type:	Facility Operator
Company Name:	505 W22ND STREET
Contact Type:	Not reported
Contact Name:	MICHAEL P
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 692-8911
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-03-08

Site Id:	479563
Affiliation Type:	Emergency Contact
Company Name:	ARCHANGEL MICHAEL REALTY, INC
Contact Type:	Not reported
Contact Name:	MICHAEL TSOUMPAS

505 W 22ND STREET (Continued) **A100366161**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 428-1972
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-12-30

Site Id:	479563
Affiliation Type:	Facility Owner
Company Name:	ARCHANGEL MICHAEL REALTY, INC
Contact Type:	VP
Contact Name:	MICHAEL TSOUMPAS
Address1:	157 LEXINGTON AVE.
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(917) 428-1972
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-12-30

Tank Info:

Tank Number:	CA5721-88P
Tank Id:	247437
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

J04 - Dispenser - On Site Heating System (Suction)
L00 - Piping Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I05 - Overfill - Vent Whistle

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1984
Capacity Gallons:	3000
Tightness Test Method:	NN

505 W 22ND STREET (Continued) **A100366161**

Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AK621 **CON ED - V 4289** **RCRA NonGen / NLR** **1007205281**
NW **532 W 20 ST** **NY MANIFEST** **NYP000928655**
1/8-1/4 **NEW YORK, NY 10011**
0.175 mi.
926 ft. **Site 17 of 18 in cluster AK**

Relative: **Lower**
Actual: **8 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		19980228
Handler Name:	CON ED - V 4289	
Handler Address:		532 W 20 ST
Handler City,State,Zip:		NEW YORK, NY 10011-0000
EPA ID:		NYP000928655
Contact Name:		ANTHONY DRUMMINGS
Contact Address:		CONSOLIDATED EDISON INC
Contact City,State,Zip:		NEW YORK, NY 10003-0000
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		CONSOLIDATED EDISON INC
Mailing City,State,Zip:		NEW YORK, NY 10003-0000
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

CON ED - V 4289 (Continued) **1007205281**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19980227
Handler Name: CON ED - V 4289	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980228
Handler Name: CON ED - V 4289	

CON ED - V 4289 (Continued) **1007205281**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980226
Handler Name: CON ED - V 4289	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	2211
NAICS Description:	ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code:	22111
NAICS Description:	ELECTRIC POWER GENERATION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	NYNEX
Address:	532 W 20 ST
City,State,Zip:	NEW YORK, NY 10011-0000
Country:	USA
EPA ID:	NYP000928655
Facility Status:	Not reported
Location Address 1:	NW 145TH STREET AND LENOX
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000928655

CON ED - V 4289 (Continued) **1007205281**

Mailing Name:	NYNEX
Mailing Contact:	S BISWAS
Mailing Address 1:	221 EAST 37TH STREET
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10016
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2123387126

AG622 **211-10-02 73RD AVE/QUEENS** **NY LTANKS** **S102671623**
North **211-10-02 73RD AVENUE** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.176 mi.
927 ft. **Site 9 of 13 in cluster AG**

Relative: **Lower**

Actual: **11 ft.**

LTANKS:

Name:	211-10-02 73RD AVE/QUEENS
Address:	211-10-02 73RD AVENUE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9010783 / 1991-01-09
Facility ID:	9010783
Site ID:	123862
Spill Date:	1991-01-02
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1991-01-09
SWIS:	4101
Investigator:	WILSON
Referred To:	Not reported
Reported to Dept:	1991-01-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-01-29
Spill Record Last Update:	1991-01-29
Spiller Name:	Not reported
Spiller Company:	HESS
Spiller Address:	1 HESS PLAZA
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	107351
DEC Memo:	""
Remarks:	"DRIVER DELIVERED TO WRONG TANK,OVERFILL RESULTED FROM VENT TO SOIL AREA,SPEEDY DRY WAS APPLIED, WILL PICK UP & DISPOSE."

All Materials:

211-10-02 73RD AVE/QUEENS (Continued) **S102671623**

Site ID:	123862
Operable Unit ID:	947926
Operable Unit:	01
Material ID:	430901
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AG623 **CON EDISON MANHOLE: 43454** **RCRA NonGen / NLR** **1016967399**
North **211 10TH AVE FRONT OF** **NY MANIFEST** **NYP004410155**
1/8-1/4 **NEW YORK, NY 10034**
0.176 mi.
927 ft. **Site 10 of 13 in cluster AG**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20140121
Handler Name:	CON EDISON MANHOLE: 43454
Handler Address:	211 10TH AVE FRONT OF
Handler City,State,Zip:	NEW YORK, NY 10034
EPA ID:	NYP004410155
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

CON EDISON MANHOLE: 43454 (Continued) **1016967399**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131221
Handler Name:	CON EDISON MANHOLE: 43454
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CON EDISON MANHOLE: 43454 (Continued) **1016967399**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140121
Handler Name: CON EDISON MANHOLE: 43454
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 211 10TH AVE FRONT OF
City,State,Zip: NEW YORK, NY 10034
Country: USA
EPA ID: NYP004410155
Facility Status: Not reported
Location Address 1: OPP SW COR W 211 ST & 10TH AVE
Code: BP
Location Address 2: MH 43454
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10034
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004410155
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

CON EDISON MANHOLE: 43454 (Continued) **1016967399**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	12/21/2013
Trans1 Recv Date:	12/21/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/24/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004410155
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002299457GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AV624 **GREENWAY MEWS REALTY L.L.C** **PA MANIFEST** **S116737461**
SSW **416 WEST 13TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.176 mi.
929 ft. **Site 1 of 8 in cluster AV**

Relative:
Lower

Actual:
13 ft.

Manifest Details:

Year:	2013
Manifest Number:	009181738JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000200550
Generator Date:	06/06/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems of PA Inc
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	175
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

AV625 **GREENWAY MEWS REALTY LLC** **NY AST** **A100294269**
SSW **416 WEST 13TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.176 mi.
929 ft. **Site 2 of 8 in cluster AV**

Relative:
Lower

Actual:
13 ft.

AST:

Name:	GREENWAY MEWS REALTY LLC
Address:	416 WEST 13TH STREET
City,State,Zip:	NEW YORK, NY 10014
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608304
Program Type:	PBS
UTM X:	583858.50823
UTM Y:	4510430.13533
Expiration Date:	02/19/2023
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30156
Affiliation Type:	Mail Contact
Company Name:	GREENWAY MEWS REALTY LLC
Contact Type:	Not reported
Contact Name:	Not reported

GREENWAY MEWS REALTY LLC (Continued) **A100294269**

Address1:	416 WEST 13TH STREET
Address2:	ROOM 300
City:	NEW YORK
State:	NY
Zip Code:	10014
Country Code:	001
Phone:	(212) 989-7930
EMail:	INFO@GREENWAYMEWS.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-17

Site Id:	30156
Affiliation Type:	Facility Operator
Company Name:	GREENWAY MEWS REALTY LLC
Contact Type:	Not reported
Contact Name:	BARBARA ISKRA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 982-2880
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-17

Site Id:	30156
Affiliation Type:	Emergency Contact
Company Name:	GREENWAY MEWS REALTY LLC
Contact Type:	Not reported
Contact Name:	BARABARA ISKRA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 989-7930
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-17

Site Id:	30156
Affiliation Type:	Facility Owner
Company Name:	GREENWAY MEWS REALTY LLC
Contact Type:	MANAGING PARTNER
Contact Name:	RACHEL OSTRY
Address1:	416 WEST 13TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10014
Country Code:	001

GREENWAY MEWS REALTY LLC (Continued) **A100294269**

Phone:	(212) 989-7930
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-17

Tank Info:

Tank Number:	001
Tank Id:	65011
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/01/1998
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	01/17/2018
Material Name:	#2 fuel oil (on-site consumption)

AV626 **GREENWAY MEWS REALTY LLC** **RCRA-VSQG** **1016144474**
SSW **416 W 13TH ST #300** **FINDS** **NYR000200550**
1/8-1/4 **NEW YORK, NY 10014** **ECHO**
0.176 mi. **NY MANIFEST**
929 ft. **Site 3 of 8 in cluster AV**

Relative: **Lower**
Actual: **13 ft.**

RCRA-VSQG:

Date Form Received by Agency:	20130520
Handler Name:	GREENWAY MEWS REALTY LLC
Handler Address:	416 W 13TH ST 300
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYR000200550
Contact Name:	PAUL KRICH
Contact Address:	W 13TH ST 300
Contact City,State,Zip:	NEW YORK, NY 10014

GREENWAY MEWS REALTY LLC (Continued) **1016144474**

Contact Telephone:	212-989-7930
Contact Fax:	Not reported
Contact Email:	GREENWAYMEWS@AOL.COM
Contact Title:	MANAGER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 13TH ST 300
Mailing City,State,Zip:	NEW YORK, NY 10014
Owner Name:	GREENWAY MEWS REALTY LLC
Owner Type:	Private
Operator Name:	GREENWAY MEWS REALTY LLC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

GREENWAY MEWS REALTY LLC (Continued) **1016144474**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211116
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GREENWAY MEWS REALTY LLC
Legal Status:	Private
Date Became Current:	19890131
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	GREENWAY MEWS REALTY LLC
Legal Status:	Private
Date Became Current:	19890131
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20130520
Handler Name:	GREENWAY MEWS REALTY LLC
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	Not reported
Recognized Trader Exporter:	Not reported

GREENWAY MEWS REALTY LLC (Continued) **1016144474**

Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 53111
NAICS Description: LESSORS OF RESIDENTIAL BUILDINGS AND DWELLINGS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055471001

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016144474
Registry ID: 110055471001
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055471001
Name: GREENWAY MEWS REALTY LLC
Address: 416 W 13TH ST #300
City,State,Zip: NEW YORK, NY 10014

NY MANIFEST:
Name: GREENWAY MEWS REALTY LLC
Address: 416 W 13TH ST #300
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYR000200550
Facility Status: Not reported
Location Address 1: 416 W 13TH ST #300
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

GREENWAY MEWS REALTY LLC (Continued) **1016144474**

NY MANIFEST:

EPAID:	NYR000200550
Mailing Name:	GREENWAY MEWS REALTY LLC
Mailing Contact:	GREENWAY MEWS REALTY LLC
Mailing Address 1:	416 W 13TH ST #300
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10014
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYR000134957
Trans2 State ID:	PAD982661381
Generator Ship Date:	06/06/2013
Trans1 Recv Date:	06/06/2013
Trans2 Recv Date:	06/07/2013
TSD Site Recv Date:	06/12/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000200550
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	009181738JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	175
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

GREENWAY MEWS REALTY LLC (Continued) **1016144474**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AQ627 **304-10 W. 14 REALTY LLC** **NY AST** **A100168799**
South **310 W 14TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.176 mi.
931 ft. **Site 2 of 8 in cluster AQ**

Relative:
Higher

Actual:
20 ft.

AST:

Name:	304-10 W. 14 REALTY LLC
Address:	310 W 14TH STREET
City,State,Zip:	NEW YORK, NY 10014
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-110701
Program Type:	PBS
UTM X:	584159.79186
UTM Y:	4510360.38321
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	3403
Affiliation Type:	Facility Owner
Company Name:	304-10 W. 14 REALTY LLC
Contact Type:	GENERAL MANAGER
Contact Name:	MARTIN BLUM
Address1:	145 HUGUENOT STREET - SUITE 503
Address2:	Not reported
City:	NEW ROCHELLE
State:	NY
Zip Code:	10801
Country Code:	001
Phone:	(914) 637-6200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-08-13

Site Id:	3403
Affiliation Type:	Mail Contact
Company Name:	S.W. MANAGEMENT LLC
Contact Type:	Not reported
Contact Name:	304-10 W. 14 REALTY LLC
Address1:	145 HUGUENOT STREET
Address2:	SUITE 503
City:	NEW ROCHELLE
State:	NY
Zip Code:	10801
Country Code:	001
Phone:	(914) 637-6200
EMail:	Not reported

304-10 W. 14 REALTY LLC (Continued) **A100168799**

Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-08-13

Site Id:	3403
Affiliation Type:	Facility Operator
Company Name:	304-10 W. 14 REALTY LLC
Contact Type:	Not reported
Contact Name:	FRANK REDZEPAGIC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 414-0917
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	3403
Affiliation Type:	Emergency Contact
Company Name:	304-10 W. 14 REALTY LLC
Contact Type:	Not reported
Contact Name:	BAUER BOILERS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 299-1650
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-02-02

Tank Info:

Tank Number:	242
Tank Id:	4856
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None

304-10 W. 14 REALTY LLC (Continued) **A100168799**

	F00 - Pipe External Protection - None
	I05 - Overfill - Vent Whistle
Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	03/05/1940
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/31/2017
Register:	True
Modified By:	MXLAY
Last Modified:	09/05/2017
Material Name:	#4 fuel oil (on-site consumption)

AQ628 **EVERGREEN CLEANERS** **RCRA NonGen / NLR** **1000357848**
South **310 W 14TH ST** **FINDS** **NYD981489172**
1/8-1/4 **NEW YORK, NY 10014** **ECHO**
0.176 mi. **NY MANIFEST**
931 ft. **Site 3 of 8 in cluster AQ**

Relative: **Higher**
Actual: **20 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	EVERGREEN CLEANERS	
Handler Address:		310 W 14TH ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYD981489172
Contact Name:		YUNG TIEN
Contact Address:		W 14TH ST
Contact City,State,Zip:		NEW YORK, NY 10014
Contact Telephone:		212-989-9800
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		W 14TH ST
Mailing City,State,Zip:		NEW YORK, NY 10014
Owner Name:		YUNG C TIEN
Owner Type:		Private
Operator Name:		YUNG C TIEN
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No

EVERGREEN CLEANERS (Continued) **1000357848**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE,

EVERGREEN CLEANERS (Continued) **1000357848**

METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	YUNG C TIEN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	YUNG C TIEN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	YUNG C TIEN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: EVERGREEN CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

EVERGREEN CLEANERS (Continued) **1000357848**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: EVERGREEN CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19860723
Handler Name: EVERGREEN CLEANERS
Federal Waste Generator Description: Not reported
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110009472917

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

EVERGREEN CLEANERS (Continued) **1000357848**

ECHO:

Envid:	1000357848
Registry ID:	110009472917
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009472917
Name:	EVERGREEN CLEANERS
Address:	310 W 14TH ST
City,State,Zip:	NEW YORK, NY 10014

NY MANIFEST:

Name:	EVERGREEN CLEANERS
Address:	310 W 14TH ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYD981489172
Facility Status:	Not reported
Location Address 1:	310 WEST 14TH STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD981489172
Mailing Name:	EVERGREEN CLEANERS
Mailing Contact:	EVERGREEN CLEANERS
Mailing Address 1:	310 WEST 14TH STREET
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10014
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2129898800

AW629 **300 WEST 21ST STREET** **NY AST** **U003383519**
East **300 WEST 21ST STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.177 mi.
933 ft. **Site 1 of 9 in cluster AW**

Relative:
Higher

Actual:
20 ft.

AST:

Name:	300 WEST 21ST STREET
Address:	300 WEST 21ST STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-046892
Program Type:	PBS
UTM X:	584451.12618
UTM Y:	4510823.45489
Expiration Date:	12/30/2026
Site Type:	Apartment Building/Office Building

300 WEST 21ST STREET (Continued) **U003383519**

Affiliation Records:

Site Id:	696
Affiliation Type:	Facility Owner
Company Name:	DORAL REALTY LLC
Contact Type:	MANAGING MEMBER
Contact Name:	ZEV FELDSTEIN
Address1:	301 WEST 22ND STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 989-0955
EMail:	ZEVFELD@GMAIL.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-10-13

Site Id:	696
Affiliation Type:	Mail Contact
Company Name:	DORAL REALTY LLC
Contact Type:	Not reported
Contact Name:	ZEV FELDSTEIN
Address1:	301 WEST 22ND STREET
Address2:	Not reported
City:	NEW YORK,
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 989-0955
EMail:	ZEVFELD@GMAIL.COM
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2006-09-29

Site Id:	696
Affiliation Type:	Facility Operator
Company Name:	300 WEST 21ST STREET
Contact Type:	Not reported
Contact Name:	DRITAN TONY DOBI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 989-0955
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2006-09-29

Site Id:	696
Affiliation Type:	Emergency Contact
Company Name:	DORAL REALTY LLC
Contact Type:	Not reported
Contact Name:	ZEV FELDSTEIN

300 WEST 21ST STREET (Continued) **U003383519**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 744-8631
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2006-09-29

Tank Info:

Tank Number:	001
Tank Id:	1608
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H99 - Tank Leak Detection - Other
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/03/1971
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AI630 **C D O REALTY CORP** **NY AST** **U003389605**
SSE **301 W 154 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10039**
0.177 mi.
935 ft. **Site 6 of 7 in cluster AI**

Relative: **Higher**
Actual: **21 ft.**

AST:

Name:	C D O REALTY CORP
Address:	301 W 154 ST
City,State,Zip:	NEW YORK, NY 10039
Region:	STATE

C D O REALTY CORP (Continued) **U003389605**

DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-202673
Program Type: PBS
UTM X: 589545.61804
UTM Y: 4520286.05379
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 6954
Affiliation Type: Facility Owner
Company Name: C D O REALTY CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: DRAWER B LINECLINTON STATION
Address2: Not reported
City: NY
State: NY
Zip Code: 10037
Country Code: 001
Phone: (212) 368-4247
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 6954
Affiliation Type: Mail Contact
Company Name: C D O REALTY CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: P.O. BOX 1725 LINCOLN STATION
Address2: Not reported
City: NY
State: NY
Zip Code: 10037
Country Code: 001
Phone: (212) 368-4247
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 6954
Affiliation Type: Facility Operator
Company Name: C D O REALTY CORP
Contact Type: Not reported
Contact Name: DONALD GENTRY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 368-4247
EMail: Not reported
Fax Number: Not reported

C D O REALTY CORP (Continued) **U003389605**

Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	6954
Affiliation Type:	Emergency Contact
Company Name:	C D O REALTY CORP
Contact Type:	Not reported
Contact Name:	DONALD GENTRY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 368-4247
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	16985
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/23/2016
Register:	True
Modified By:	CGFREEDM
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AJ631 **ST BERNARD SCHOOL** **NY AST** **U000396869**
South **327 WEST 13TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.177 mi.
936 ft. **Site 7 of 7 in cluster AJ**

Relative:
Higher

Actual:
18 ft.

AST:

Name:	ST BERNARD SCHOOL
Address:	327 WEST 13TH STREET
City,State,Zip:	NEW YORK, NY 10014
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-155640
Program Type:	PBS
UTM X:	584058.25852
UTM Y:	4510346.59104
Expiration Date:	09/19/2012
Site Type:	School

Affiliation Records:

Site Id:	5053
Affiliation Type:	Facility Owner
Company Name:	ST BERNARD CHURCH
Contact Type:	PASTOR
Contact Name:	KEVIN NELAN
Address1:	328 WEST 14TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10014
Country Code:	001
Phone:	(212) 243-0265
EMail:	Not reported
Fax Number:	Not reported
Modified By:	kakyer
Date Last Modified:	2007-09-20

Site Id:	5053
Affiliation Type:	Mail Contact
Company Name:	ST BERNARD CHURCH
Contact Type:	PASTOR
Contact Name:	KEVIN NELAN
Address1:	328 WEST 14TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10014
Country Code:	001
Phone:	(212) 243-0265
EMail:	Not reported
Fax Number:	Not reported
Modified By:	kakyer
Date Last Modified:	2007-09-20

Site Id:	5053
Affiliation Type:	Facility Operator
Company Name:	ST BERNARD SCHOOL
Contact Type:	Not reported
Contact Name:	ST BERNARD CHRUCH

ST BERNARD SCHOOL (Continued) **U000396869**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 243-0265
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	5053
Affiliation Type:	Emergency Contact
Company Name:	ST BERNARD CHURCH
Contact Type:	Not reported
Contact Name:	ST BERNARD CHRUCH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 243-0265
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	8433
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	G00 - Tank Secondary Containment - None
	D00 - Pipe Type - No Piping
Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/1980
Capacity Gallons:	4000
Tightness Test Method:	03
Date Test:	07/09/1998
Next Test Date:	Not reported
Date Tank Closed:	Not reported

ST BERNARD SCHOOL (Continued) **U000396869**

Register:	True
Modified By:	kakyer
Last Modified:	04/14/2017
Material Name:	#4 fuel oil (on-site consumption)

AN632 **RITE AID # 10531** **PA MANIFEST** **S118891040**
East **195 8TH AVENUE** **N/A**
1/8-1/4 **NY, NY 10011**
0.177 mi.
937 ft. **Site 6 of 10 in cluster AN**

Relative: **Higher**

Actual: **21 ft.**

Manifest Details:

Year:	2015
Manifest Number:	007395303FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000188748
Generator Date:	05/01/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	D007
Container Number:	1
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	3
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	007395303FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000188748
Generator Date:	05/01/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D007

RITE AID # 10531 (Continued) **S118891040**

Container Number:	2
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	72
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	007395303FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000188748
Generator Date:	05/01/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D011
Container Number:	2
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	72
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	007395303FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000188748
Generator Date:	05/01/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	P001
Container Number:	1
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	1

RITE AID # 10531 (Continued) **S118891040**

Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	007395303FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000188748
Generator Date:	05/01/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	D010
Container Number:	1
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	3
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	007395303FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000188748
Generator Date:	05/01/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	D011
Container Number:	1
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	3
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592

RITE AID # 10531 (Continued) **S118891040**

Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	007395303FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000188748
Generator Date:	05/01/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D010
Container Number:	2
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	72
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

AN633 **RITE AID #10531** **RCRA NonGen / NLR** **1014927084**
East **195 8TH AVE** **NY MANIFEST** **NYR000188748**
1/8-1/4 **NEW YORK, NY 10011**
0.177 mi.
937 ft. **Site 7 of 10 in cluster AN**

Relative: **Higher**
Actual: **21 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20220106
Handler Name:	RITE AID #10531	
Handler Address:		195 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYR000188748
Contact Name:		JOSEPH A CHEST
Contact Address:		PO BOX 3165
Contact City,State,Zip:		HARRISBURG, PA 17105
Contact Telephone:		717-975-8643
Contact Fax:		717-972-3989
Contact Email:		EHS@RITEAID.COM
Contact Title:		MANAGER ENVIRONMENTAL HEALTH SERVICES
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		PO BOX 3165

RITE AID #10531 (Continued) **1014927084**

Mailing City,State,Zip:	HARRISBURG, PA 17105
Owner Name:	TREVI 189 EIGHT AVE LLC
Owner Type:	Private
Operator Name:	GENOVESE DRUG STORES INC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

RITE AID #10531 (Continued) **1014927084**

Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D002
Waste Description: CORROSIVE WASTE

Waste Code: D005
Waste Description: BARIUM

Waste Code: D007
Waste Description: CHROMIUM

Waste Code: D009
Waste Description: MERCURY

Waste Code: D010
Waste Description: SELENIUM

Waste Code: D011
Waste Description: SILVER

Waste Code: D013
Waste Description: LINDANE (1,2,3,4,5,6-HEXA-CHLOROCYCLOHEXANE, GAMMA ISOMER)

Waste Code: D016
Waste Description: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Waste Code: D018
Waste Description: BENZENE

Waste Code: D022
Waste Description: CHLOROFORM

Waste Code: D024
Waste Description: M-CRESOL

Waste Code: D026
Waste Description: CRESOL

Waste Code: D027
Waste Description: 1,4-DICHLOROBENZENE

Waste Code: D035

RITE AID #10531 (Continued) **1014927084**

Waste Description: METHYL ETHYL KETONE

Waste Code: P001
Waste Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Waste Code: P075
Waste Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Waste Code: U002
Waste Description: 2-PROPANONE (I) (OR) ACETONE (I)

Waste Code: U035
Waste Description: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

Waste Code: U044
Waste Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Waste Code: U058
Waste Description: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

Waste Code: U072
Waste Description: BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE

Waste Code: U122
Waste Description: FORMALDEHYDE

Waste Code: U129
Waste Description: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

Waste Code: U154
Waste Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Waste Code: U165
Waste Description: NAPHTHALENE

Waste Code: U188
Waste Description: PHENOL

Waste Code: U201
Waste Description: 1,3-BENZENEDIOL (OR) RESORCINOL

Waste Code: U205
Waste Description: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

Waste Code: U211
Waste Description: CARBON TETRACHLORIDE (OR) METHANE, TETRACHLORO-

Waste Code: U240
Waste Description: 2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D

Waste Code: U279

RITE AID #10531 (Continued) **1014927084**

Waste Description: U279

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	TREVI 189 EIGHT AVE LLC
Legal Status:	Private
Date Became Current:	20041004
Date Ended Current:	Not reported
Owner/Operator Address:	130 EAST 59TH STREET
Owner/Operator City,State,Zip:	NEW YORK, NY 10022
Owner/Operator Telephone:	717-975-8643
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	GENOVESE DRUG STORES, INC.
Legal Status:	Private
Date Became Current:	20080501
Date Ended Current:	Not reported
Owner/Operator Address:	30 HUNTER LANE
Owner/Operator City,State,Zip:	CAMP HILL, PA 17011
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	GENOVESE DRUG STORES INC
Legal Status:	Private
Date Became Current:	20080501
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 3165
Owner/Operator City,State,Zip:	HARRISBURG, PA 17105
Owner/Operator Telephone:	717-761-2633
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	717-972-3989
Owner/Operator Email:	EHS@RITEAID.COM

Owner/Operator Indicator:	Owner
Owner/Operator Name:	TREVI 189 EIGHT AVE LLC
Legal Status:	Private
Date Became Current:	20041004
Date Ended Current:	Not reported
Owner/Operator Address:	130 EAST 59TH STREET
Owner/Operator City,State,Zip:	NEW YORK, NY 10022
Owner/Operator Telephone:	717-975-8643
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	RITE AID CORP
Legal Status:	Private
Date Became Current:	20080501
Date Ended Current:	Not reported
Owner/Operator Address:	30 HUNTER LN

RITE AID #10531 (Continued) **1014927084**

Owner/Operator City,State,Zip:	CAMP HILL, PA 17011
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	TREVI 189 EIGHT AVE LLC
Legal Status:	Private
Date Became Current:	20041004
Date Ended Current:	Not reported
Owner/Operator Address:	130 E59TH ST 14A
Owner/Operator City,State,Zip:	NEW YORK, NY 10022
Owner/Operator Telephone:	717-975-8643
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	GENOVESE DRUG STORES INC
Legal Status:	Private
Date Became Current:	20080501
Date Ended Current:	Not reported
Owner/Operator Address:	30 HUNTER LN
Owner/Operator City,State,Zip:	CAMP HILL, PA 17011
Owner/Operator Telephone:	717-761-2633
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	RITE AID CORP
Legal Status:	Private
Date Became Current:	20080501
Date Ended Current:	Not reported
Owner/Operator Address:	30 HUNTER LN
Owner/Operator City,State,Zip:	CAMP HILL, PA 17011
Owner/Operator Telephone:	717-761-2633
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	GENOVESE DRUG STORES INC
Legal Status:	Private
Date Became Current:	20080501
Date Ended Current:	Not reported
Owner/Operator Address:	30 HUNTER LANE
Owner/Operator City,State,Zip:	CAMP HILL, PA 17011
Owner/Operator Telephone:	717-761-2633
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	TREVI 189 EIGHT AVE LLC
Legal Status:	Private

RITE AID #10531 (Continued) **1014927084**

Date Became Current:	20041004
Date Ended Current:	Not reported
Owner/Operator Address:	130 E 59TH ST 14A
Owner/Operator City,State,Zip:	NEW YORK, NY, NY 10022
Owner/Operator Telephone:	717-975-8643
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	GENOVESE DRUG STORES INC
Legal Status:	Private
Date Became Current:	20080501
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	RITE AID CORP
Legal Status:	Private
Date Became Current:	20080501
Date Ended Current:	Not reported
Owner/Operator Address:	30 HUNTER LN
Owner/Operator City,State,Zip:	CAMP HILL, PA 17011
Owner/Operator Telephone:	717-761-2633
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	RITE AID
Legal Status:	Private
Date Became Current:	20080501
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	GENOVESE DRUG STORES, INC.
Legal Status:	Private
Date Became Current:	20080501
Date Ended Current:	Not reported
Owner/Operator Address:	30 HUNTER LANE
Owner/Operator City,State,Zip:	CAMP HILL, PA 17011
Owner/Operator Telephone:	717-761-2633
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	717-972-3989
Owner/Operator Email:	EHS@RITEAID.COM

RITE AID #10531 (Continued) **1014927084**

Historic Generators:

Receive Date:	20140228
Handler Name: RITE AID #10531	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160212
Handler Name: RITE AID #10531	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20220106
Handler Name: RITE AID #10531	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20111104
Handler Name: RITE AID #10531	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130510
Handler Name: RITE AID #10531	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported

RITE AID #10531 (Continued) **1014927084**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20151120
Handler Name: RITE AID #10531	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20190417
Handler Name: RITE AID #10531	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	44611
NAICS Description:	PHARMACIES AND DRUG STORES

NAICS Code:	446110
NAICS Description:	PHARMACIES AND DRUG STORES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	RITE AID #10531
Address:	195 8TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYR000188748

RITE AID #10531 (Continued) **1014927084**

Facility Status:	Not reported
Location Address 1:	195 8TH AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000188748
Mailing Name:	RITE AID #10531
Mailing Contact:	RITE AID #10531
Mailing Address 1:	195 8TH AVE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	12/12/2013
Trans1 Recv Date:	12/12/2013
Trans2 Recv Date:	12/18/2013
TSD Site Recv Date:	12/23/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000188748
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	INR000110197
TSDF ID 2:	Not reported
Manifest Tracking Number:	006341481FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

RITE AID #10531 (Continued) **1014927084**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	4
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AE634 **PIER 57- 11TH AVENUE** **NY LTANKS** **S101341073**
West **PIER 57 / 11TH AVENUE** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.178 mi.
939 ft. **Site 5 of 7 in cluster AE**

Relative: **Lower**

Actual: **1 ft.**

LTANKS:

Name:	PIER 57- 11TH AVENUE
Address:	PIER 57 / 11TH AVENUE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9408802 / 2000-12-27
Facility ID:	9408802
Site ID:	257282
Spill Date:	1994-09-30
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1994-10-03
CID:	Not reported
Water Affected:	HUDSON RIVER
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-11-01
Spill Record Last Update:	2000-12-27
Spiller Name:	Not reported
Spiller Company:	NYCTA
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	210660
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

PIER 57- 11TH AVENUE (Continued) **S101341073**

TIBBE transfered from Hale to Tibbe. spill cleaned by NYCT. no impact to soil or groundwater."
Remarks: "W.O. TANK LEAKS-NO CLEAN UP DONE"

All Materials:
Site ID: 257282
Operable Unit ID: 1002931
Operable Unit: 01
Material ID: 378226
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: Not reported

AE635 **PIER 57 & HUDSON DEPOT** **NY LTANKS** **S105053992**
West **15TH ST & ROUTE 9A** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.178 mi.
939 ft. **Site 6 of 7 in cluster AE**

Relative: **Lower**
Actual: **1 ft.**

LTANKS:
Name: PIER 57 & HUDSON DEPOT
Address: 15TH ST & ROUTE 9A
City,State,Zip: MANHATTAN, NY
Spill Number/Closed Date: 9407577 / 1998-05-07
Facility ID: 9407577
Site ID: 62357
Spill Date: 1994-09-07
Spill Cause: Tank Failure
Spill Source: Unknown
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 1994-09-07
CID: Not reported
Water Affected: HUDSON RIVER
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1994-10-24
Spill Record Last Update: 2000-05-11
Spiller Name: Not reported
Spiller Company: NYCTA & NYS DOT
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported

PIER 57 & HUDSON DEPOT (Continued) **S105053992**

DEC Region: 2
DER Facility ID: 60464
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE SEE PIN FILE. SEE ALSO 94-12040."
Remarks: "COMING FROM TRANSIT AUTHORIT-DEPLOY BOOM IF NECESSARY-RESPONSE ENTER SAYS TRANSIT AUTHORITY IS THE SPILLER."

All Materials:
Site ID: 62357
Operable Unit ID: 1005155
Operable Unit: 01
Material ID: 380581
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 62357
Operable Unit ID: 1005155
Operable Unit: 01
Material ID: 380580
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AE636 **PIER 57- WESTSIDE HIGHWAY** **NY LTANKS** **S101341228**
West **W.17TH ST WESTSIDE HWY** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.178 mi.
939 ft. **Site 7 of 7 in cluster AE**

Relative: **Lower**
Actual: **1 ft.**

LTANKS:
Name: PIER 57- WESTSIDE HIGHWAY
Address: W.17TH ST WESTSIDE HWY
City,State,Zip: MANHATTAN, NY
Spill Number/Closed Date: 9412040 / 1994-12-09
Facility ID: 9412040
Site ID: 117349
Spill Date: 1994-12-09
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 1994-12-09
CID: Not reported

PIER 57- WESTSIDE HIGHWAY (Continued) **S101341228**

Water Affected:	HUDSON RIVER
Spill Notifier:	Federal Government
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-01-25
Spill Record Last Update:	2002-10-08
Spiller Name:	Not reported
Spiller Company:	NYCTA & NYSDOT
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	102099
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE SEE 94-07577 & SP93876. "
Remarks:	"ON GOING - SEE PAGE SITE BREACHED -CONTAINED UNDERGROUND STORAGE TANKS CONTRACTORS ENROUTE, ALSO USCG GOING OUT."

All Materials:

Site ID:	117349
Operable Unit ID:	1009834
Operable Unit:	01
Material ID:	374376
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AP637 **CONSOLIDATED EDISON** **NY MANIFEST** **1009243195**
NNW **519 W 21 ST SB3762** **N/A**
1/8-1/4 **NEW YORK, NY 10037**
0.178 mi.
939 ft. **Site 3 of 6 in cluster AP**

Relative: **Lower**

Actual: **9 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	519 W 21 ST SB3762
City,State,Zip:	NEW YORK, NY 10037
Country:	USA
EPA ID:	NYP004125605
Facility Status:	Not reported
Location Address 1:	519 W 21 ST SB3762
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10037

CONSOLIDATED EDISON (Continued) **1009243195**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004125605
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

AS638 **A B GREEN GANSEVOORT LLC** **RCRA-VSQG** **1007881003**
SW **856 WASHINGTON ST** **NY MANIFEST** **NYR000129114**
1/8-1/4 **NEW YORK, NY 10014**
0.178 mi.
940 ft. **Site 2 of 11 in cluster AS**

Relative: **Lower**
Actual: **11 ft.**

RCRA-VSQG:
Date Form Received by Agency: 20070101
Handler Name: A B GREEN GANSEVOORT LLC
Handler Address: 856 WASHINGTON ST
Handler City,State,Zip: NEW YORK, NY 10014
EPA ID: NYR000129114
Contact Name: JEREMY L SELMAN
Contact Address: LAFAYETTE ST - SUITE 708
Contact City,State,Zip: NEW YORK, NY 10012
Contact Telephone: 212-965-4314
Contact Fax: Not reported
Contact Email: JEREMY.SELMAN@HOTELSAB.COM
Contact Title: Not reported
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: NY
State District: NYSDEC R2
Mailing Address: LAFAYETTE ST - SUITE 708
Mailing City,State,Zip: NEW YORK, NY 10012
Owner Name: A B GREEN GANSEVOORT LLC
Owner Type: Private
Operator Name: A B GREEN GANSEVOORT LLC
Operator Type: Private
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No
Recycler Activity with Storage: No
Small Quantity On-Site Burner Exemption: No
Smelting Melting and Refining Furnace Exemption: No

A B GREEN GANSEVOORT LLC (Continued) **1007881003**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	A B GREEN GANSEVOORT LLC

A B GREEN GANSEVOORT LLC (Continued) **1007881003**

Legal Status:	Private
Date Became Current:	20040527
Date Ended Current:	Not reported
Owner/Operator Address:	856 WASHINGTON ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10014
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	A B GREEN GANSEVOORT LLC
Legal Status:	Private
Date Became Current:	20040527
Date Ended Current:	Not reported
Owner/Operator Address:	295 LAFAYETTE ST - SUITE 708
Owner/Operator City,State,Zip:	NEW YORK, NY 10012
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	A B GREEN GANSEVOORT LLC
Legal Status:	Private
Date Became Current:	20040527
Date Ended Current:	Not reported
Owner/Operator Address:	856 WASHINGTON ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10014
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	A B GREEN GANSEVOORT LLC
Legal Status:	Private
Date Became Current:	20040527
Date Ended Current:	Not reported
Owner/Operator Address:	295 LAFAYETTE ST - SUITE 708
Owner/Operator City,State,Zip:	NEW YORK, NY 10012
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name:	A B GREEN GANSEVOORT LLC
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

A B GREEN GANSEVOORT LLC (Continued) **1007881003**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: A B GREEN GANSEVOORT LLC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20041209
Handler Name: A B GREEN GANSEVOORT LLC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 72111
NAICS Description: HOTELS (EXCEPT CASINO HOTELS) AND MOTELS

NAICS Code: 72211
NAICS Description: FULL-SERVICE RESTAURANTS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: STANDARD AROMATICS
Address: 856 WASHINGTON ST
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYR000129114
Facility Status: Not reported
Location Address 1: W 13TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK

A B GREEN GANSEVOORT LLC (Continued) **1007881003**

Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000129114
Mailing Name: STANDARD AROMATICS
Mailing Contact: N/S
Mailing Address 1: 295 LAFAYETTE ST SUITE 708
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10012
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: N/S

AN639 **CON EDISON SERVICE BOX 32087** **RCRA NonGen / NLR** **1015747025**
ESE **W 19TH ST & 8TH AVE SE COR** **NY MANIFEST** **NYP004250270**
1/8-1/4 **NEW YORK, NY 10011**
0.178 mi.
940 ft. **Site 8 of 10 in cluster AN**

Relative:
Higher

Actual:
21 ft.

RCRA NonGen / NLR:
Date Form Received by Agency: 20120421
Handler Name: CON EDISON SERVICE BOX 32087
Handler Address: W 19TH ST & 8TH AVE SE COR
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYP004250270
Contact Name: JUAN RODRIGUEZ
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 347-865-5931
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: OPERATING SUPERVISOR
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY
State District: NYSDEC R2
Mailing Address: 4 IRVING PL, RM 828
Mailing City,State,Zip: NEW YORK, NY 10003
Owner Name: Not reported
Owner Type: Not reported
Operator Name: Not reported
Operator Type: Not reported
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No
Recycler Activity with Storage: No

CON EDISON SERVICE BOX 32087 (Continued) **1015747025**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20120712
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20120322
Handler Name:	CON EDISON SERVICE BOX 32087
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

CON EDISON SERVICE BOX 32087 (Continued) **1015747025**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20120421
Handler Name:	CON EDISON SERVICE BOX 32087
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CONSOLIDATED EDISON - SERV BOX
Address:	W 19TH ST & 8TH AVE SE COR
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004250270
Facility Status:	Not reported
Location Address 1:	S/E/C WEST 19TH ST & 8TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004250270
Mailing Name:	CONSOLIDATED EDISON - SERV BOX
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003

CON EDISON SERVICE BOX 32087 (Continued) **1015747025**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/22/2012
Trans1 Recv Date:	03/22/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/22/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004250270
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	009204830JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AS640 **CON EDISON - VAULT 3638** **NY MANIFEST** **S120958233**
WSW **42 10 AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.179 mi.
943 ft. **Site 3 of 11 in cluster AS**

Relative: **Lower**
Actual: **7 ft.**

NY MANIFEST:

Name:	CON EDISON - VAULT 3638
Address:	42 10 AVE
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004923908
Facility Status:	Not reported
Location Address 1:	42 10 AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004923908
Mailing Name:	CON EDISON - VAULT 3638
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

AS641 **CON EDISON** **RCRA NonGen / NLR** **1014395636**
WSW **42 10TH AVE** **NJ MANIFEST** **NYP004171013**
1/8-1/4 **NEW YORK, NY 10014** **NY MANIFEST**
0.179 mi.
943 ft. **Site 4 of 11 in cluster AS**

Relative: **Lower**
Actual: **7 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		42 10TH AVE
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004171013
Contact Name:		HERMAN BAKER
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		718-267-3853
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported

CON EDISON (Continued) **1014395636**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

CON EDISON (Continued) **1014395636**

Handler Date of Last Change: 20160727
Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20090604
Handler Name: CON EDISON
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160601
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:
EPA Id: NYP004171013
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: HERMAN BAKER
Comments: Not reported

CON EDISON (Continued) **1014395636**

SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	003532070JJK
EPA ID:	NYP004171013
Date Shipped:	06/04/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/04/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/05/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	1500 P

CON EDISON (Continued) **1014395636**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	42 10TH AVE
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004171013
Facility Status:	Not reported
Location Address 1:	42 10th AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MANHATTAN
Location State:	NY
Location Zip:	10020
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004171013
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/04/2009
Trans1 Recv Date:	06/04/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/05/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004171013
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003532070JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON (Continued) **1014395636**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Name:	CON EDISON
Address:	10TH AVE & 31ST ST
City,State,Zip:	NEW YORK, NY 10001
Country:	USA
EPA ID:	NYP004286860
Facility Status:	Not reported
Location Address 1:	10TH AVE N 31 FO 42
Code:	BP
Location Address 2:	SERV BOX 43177
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10001
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004286860
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported

CON EDISON (Continued) **1014395636**

Generator Ship Date:	02/28/2013
Trans1 Recv Date:	02/28/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/28/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004286860
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010708158JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AS642 **42-46 10TH AVENUE** **NY VCP** **S127989943**
WSW **42 10TH AVENUE** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.179 mi.
943 ft. **Site 5 of 11 in cluster AS**

Relative: VCP NYC:
Lower

Project ID:	12TMP0564M,12EHAZ564M,12CBCP027M
Name:	42-46 10TH AVENUE
Address:	42 10TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Manhattan

Actual:
7 ft.

42-46 10TH AVENUE (Continued) **S127989943**

BBL:	1006460001
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed
Latitude:	40.741673
Longitude:	-74.008563
Postcode:	2
Community Board:	3
Council District:	79
Census Tract:	1090681
BIN:	1006460001
NTA:	West Village

AS643 **CON EDISON** **NY MANIFEST** **S121990222**
SW **837 WASHINGTON ST** **NY COOLING TOWERS** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.179 mi.
944 ft. **Site 6 of 11 in cluster AS**

Relative:
Lower

Actual:
11 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	837 WASHINGTON ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004250155
Facility Status:	Not reported
Location Address 1:	837 WASHINGTON ST
Code:	BP
Location Address 2:	SERV BOX 49198
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004250155
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/17/2013
Trans1 Recv Date:	02/17/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/20/2013

CON EDISON (Continued) **S121990222**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004250155
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840398JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

COOLING TOWERS:

Name:	Not reported
Address:	837 WASHINGTON ST
City,State,Zip:	NEW YORK, NY 10014
Equipment Unique ID:	11531
Equipment Borough:	Manhattan
Intended Use:	Air Conditioning
Manufacturer:	Evapco
Model:	vtl-185m
Cooling Capacity:	370
Cooling Capacity Unit:	Tonnage
Commissioned Date:	Not reported
Inspection Date:	10/25/2017
Date of Bacteriological Collection:	10/23/2017
Date of Legionella Collection:	05/15/2017
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	40.740734
Longitude:	-74.007629

AS644 **CON EDISON SERVICE BOX: 49198** **RCRA NonGen / NLR** **1015747014**
SW **837 WASHINGTON ST** **NYP004250155**
1/8-1/4 **NEW YORK, NY 10014**
0.179 mi.
944 ft. **Site 7 of 11 in cluster AS**

Relative: **Lower**

Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130317
Handler Name:	CON EDISON SERVICE BOX:	49198
Handler Address:		837 WASHINGTON ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004250155
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 49198 (Continued) **1015747014**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130217
Handler Name:	CON EDISON SERVICE BOX: 49198
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20120420
Handler Name:	CON EDISON MANHOLE 43864
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 49198 (Continued) **1015747014**

Electronic Manifest Broker: Not reported

Receive Date: 20130317
Handler Name: CON EDISON SERVICE BOX: 49198
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AL645 **CON EDISON** **RCRA NonGen / NLR** **1014399110**
SE **W 17TH ST & 8TH AVE NE COR** **NJ MANIFEST** **NYP004214870**
1/8-1/4 **NEW YORK, NY 10011** **NY MANIFEST**
0.179 mi.
944 ft. **Site 10 of 14 in cluster AL**

Relative: **Higher**
Actual: **21 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20200413
Handler Name: CON EDISON
Handler Address: W 17TH ST & 8TH AVE NE COR
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYP004214870
Contact Name: Not reported
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: Not reported
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY
State District: NYSDEC R2
Mailing Address: Not reported
Mailing City,State,Zip: Not reported
Owner Name: Not reported

CON EDISON (Continued) **1014399110**

Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200413
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

CON EDISON (Continued) **1014399110**

Sub-Part P Indicator: No

Historic Generators:

Receive Date:	20100903
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20200413
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004214870
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JUAN RODRIGUEZ
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported

CON EDISON (Continued) **1014399110**

Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007656797JJK
EPA ID:	NYP004214870
Date Shipped:	09/02/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/02/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/03/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	2000 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	W 17TH ST & 8TH AVE NE COR
City,State,Zip:	NEW YORK, NY 10011

CON EDISON (Continued) **1014399110**

Country:	USA
EPA ID:	NYP004214870
Facility Status:	Not reported
Location Address 1:	N/E/C W 17ST & 8TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004214870
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/02/2010
Trans1 Recv Date:	09/02/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/03/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004214870
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007656797JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **1014399110**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG646 **AMOCO STATION** **NY LTANKS** **S100143360**
North **213-10 JAMAICA AVENUE** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.179 mi.
944 ft. **Site 11 of 13 in cluster AG**

Relative: LTANKS:
Lower

Actual: **11 ft.**

Name:	AMOCO STATION
Address:	213-10 JAMAICA AVENUE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8604698 / 1987-03-24
Facility ID:	8604698
Site ID:	224510
Spill Date:	1986-10-21
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	1987-03-24
SWIS:	4101
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	1986-10-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-03-31
Spill Record Last Update:	2004-02-03
Spiller Name:	Not reported
Spiller Company:	SPARTAN PETROLEUM
Spiller Address:	3333 NEW HYDE PARK RD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(914) 667-5800
Spiller Extention:	Not reported
DEC Region:	2

AMOCO STATION (Continued) **S100143360**

DER Facility ID:	185557
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was K FOLEY 10/10/95: This is additional information about material spilled from the translation of the old spill file: PREMIUM NO-LEAD. 2/3/04 Reassigned to K Foley. No case lead previously assigned. See spill #9607176."
Remarks:	"FOUR K U/G TANK SYSTEM FAILED HYDRO-STATIC TEST."

All TTF:

Facility ID:	8604698
Spill Number:	8604698
Spill Tank Test:	1530314
Site ID:	224510
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	224510
Operable Unit ID:	901896
Operable Unit:	01
Material ID:	473934
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AX647 **CON EDISON** **RCRA NonGen / NLR** **1012185948**
NNE **410 W 42ND ST & 9TH AVE** **NJ MANIFEST** **NYP004167839**
1/8-1/4 **NEW YORK, NY 10036** **NY MANIFEST**
0.179 mi.
946 ft. **Site 1 of 7 in cluster AX**

Relative:
Higher

Actual:
14 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		410 W 42ND ST & 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10036
EPA ID:		NYP004167839
Contact Name:		MICHAEL BETO
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		917-337-5519

CON EDISON (Continued) **1012185948**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

CON EDISON (Continued) **1012185948**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161003
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090420
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON (Continued) **1012185948**

NJ MANIFEST:

EPA Id:	NYP004167839
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	MICHAEL BETO
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001028453JJK
EPA ID:	NYP004167839
Date Shipped:	04/20/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/20/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/21/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported

CON EDISON (Continued) **1012185948**

Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 30 P

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 410 W 42ND ST & 9TH AVE
City,State,Zip: NEW YORK, NY 10036
Country: USA
EPA ID: NYP004167839
Facility Status: Not reported
Location Address 1: A/F 410 W 42ND ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: MANHATTAN
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004167839
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City: MANHATTAN
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/20/2009
Trans1 Recv Date: 04/20/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/21/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004167839
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported

CON EDISON (Continued) **1012185948**

TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	001028453JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AT648 **CON EDISON - SERVICE BOX 32061** **RCRA-LQG** **1014395681**
SE **WEST 16TH STREET AND 8TH AVE** **NJ MANIFEST** **NYP004171476**
1/8-1/4 **NEW YORK, NY 10014**
0.180 mi.
949 ft. **Site 13 of 23 in cluster AT**

Relative: RCRA-LQG:
Higher

Actual: Date Form Received by Agency: 20100323
21 ft. Handler Name: CON EDISON - SERVICE BOX 32061
Handler Address: WEST 16TH STREET AND 8TH AVE
Handler City,State,Zip: NEW YORK, NY 10014
EPA ID: NYP004171476
Contact Name: FRANKLYN MURRAY
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-2808
Contact Fax: Not reported
Contact Email: MURRAYFR@CONED.COM
Contact Title: Not reported
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Large Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: 2009

CON EDISON - SERVICE BOX 32061 (Continued) **1014395681**

Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	4 IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

CON EDISON - SERVICE BOX 32061 (Continued) **1014395681**

Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2009

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20090609
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20090609
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20100323
Handler Name:	CON EDISON - SERVICE BOX 32061
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON - SERVICE BOX 32061 (Continued) **1014395681**

Electronic Manifest Broker: Not reported

Receive Date: 20090609
Handler Name: CON EDISON
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:
EPA Id: NYP004171476
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DAVID DUKE
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 003534450JJK
EPA ID: NYP004171476
Date Shipped: 06/09/2009
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported

CON EDISON - SERVICE BOX 32061 (Continued) **1014395681**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/09/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/09/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	3200 P

AT649 **CONSOLIDATED EDISON** **NY MANIFEST** **S119073146**
SE **W 16TH ST & 8TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.180 mi.
949 ft. **Site 14 of 23 in cluster AT**

Relative:
Higher

Actual:
21 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	W 16TH ST & 8TH AVE
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004171476
Facility Status:	Not reported
Location Address 1:	WEST 16TH STREET AND 8TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY

CONSOLIDATED EDISON (Continued) **S119073146**

Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004171476
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/09/2009
Trans1 Recv Date:	06/09/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/09/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004171476
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003534450JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.

CONSOLIDATED EDISON (Continued) **S119073146**

Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AL650 **NYCT - PUMP ROOM #2069** **RCRA-VSQG** **1007208660**
ESE **18TH ST & 8TH AVE** **NY MANIFEST** **NYR000122010**
1/8-1/4 **NEW YORK, NY 10011** **NJ MANIFEST**
0.180 mi.
950 ft. **Site 11 of 14 in cluster AL**

Relative: **Higher**
Actual: **21 ft.**

RCRA-VSQG:

Date Form Received by Agency:		20070101
Handler Name:	NYCT - PUMP ROOM #2069	
Handler Address:		18TH ST & 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYR000122010
Contact Name:		THOMAS A ABDALLAH
Contact Address:		BROADWAY 2ND FLOOR
Contact City,State,Zip:		NEW YORK, NY 10004
Contact Telephone:		646-252-3500
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		State
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		BROADWAY 2ND FLOOR
Mailing City,State,Zip:		NEW YORK, NY 10004
Owner Name:		MTA NYCT
Owner Type:		State
Operator Name:		NYCT -
Operator Type:		State
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported

NYCT - PUMP ROOM #2069 (Continued) **1007208660**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MTA NYCT
Legal Status:	State
Date Became Current:	19200101
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported

NYCT - PUMP ROOM #2069 (Continued) **1007208660**

Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYCT -
Legal Status:	State
Date Became Current:	19200101
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	MTA NYCT
Legal Status:	State
Date Became Current:	19200101
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYCT -
Legal Status:	State
Date Became Current:	19200101
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: NYCT - PUMP ROOM #2069	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: NYCT - PUMP ROOM #2069	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY

NYCT - PUMP ROOM #2069 (Continued) **1007208660**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20040121
Handler Name: NYCT - PUMP ROOM #2069	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	485111
NAICS Description:	MIXED MODE TRANSIT SYSTEMS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	NYCTA PUMP ROOM 2069
Address:	18TH ST & 8TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYR000122010
Facility Status:	Not reported
Location Address 1:	10 ST & 6 AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000122010
Mailing Name:	NYCTA PUMP ROOM 2069
Mailing Contact:	NYCTA PUMP ROOM 2069
Mailing Address 1:	2 BROADWAY 2ND FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK

NYCT - PUMP ROOM #2069 (Continued) **1007208660**

Mailing State:	NY
Mailing Zip:	10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6462523500

NJ MANIFEST:

EPA Id:	NYR000122010
Mail Address:	2 BROADWAY
Mail City/State/Zip:	NEW YORK 10004
Facility Phone:	6462523500
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	NJA5104678
EPA ID:	NYR000122010
Date Shipped:	05/06/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/06/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/06/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

NYCT - PUMP ROOM #2069 (Continued) **1007208660**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06090422
Was Load Rejected:	NEW YORK 10004
Reason Load Was Rejected:	Not reported

AP651 **CONSOLIDATED EDISON** **NY MANIFEST** **1009236814**
NNW **520 W 22ND ST** **N/A**
1/8-1/4 **NEW YORK, NY 10001**
0.182 mi.
959 ft. **Site 4 of 6 in cluster AP**

Relative:
Lower

Actual:
9 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	520 W 22ND ST
City,State,Zip:	NEW YORK, NY 10001
Country:	USA
EPA ID:	NYP004019741
Facility Status:	Not reported
Location Address 1:	520 W 22ND ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10001
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004019741
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

AP652 **CON EDISON SERVICE BOX: 3952** **RCRA NonGen / NLR** **1016143410**
NNW **518 W 22ND ST** **FINDS** **NYP004261889**
1/8-1/4 **NEW YORK, NY 10014** **ECHO**
0.182 mi. **NY MANIFEST**
959 ft. **Site 5 of 6 in cluster AP**

Relative: **Lower**
Actual: **10 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130321
Handler Name:	CON EDISON SERVICE BOX:	3952
Handler Address:		518 W 22ND ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004261889
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 3952 (Continued) **1016143410**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130221
Handler Name: CON EDISON SERVICE BOX:	3952
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130321
Handler Name: CON EDISON SERVICE BOX:	3952
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 3952 (Continued) **1016143410**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063925800

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016143410
Registry ID:	110063925800
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110063925800
Name:	CON EDISON SERVICE BOX: 3952
Address:	518 W 22ND ST
City,State,Zip:	NEW YORK, NY 10014

NY MANIFEST:

Name:	CON EDISON
Address:	518 W 22ND ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004261889
Facility Status:	Not reported
Location Address 1:	518 W 22ND ST
Code:	BP
Location Address 2:	SERV BOX 3952
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004261889
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING

CON EDISON SERVICE BOX: 3952 (Continued) **1016143410**

Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/21/2013
Trans1 Recv Date:	02/21/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/22/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004261889
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010707141JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG653 **EXXON** **NY Spills** **S107415886**
North **215 10TH AVE & W 23RD ST** **NY MANIFEST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.182 mi.
960 ft. **Site 12 of 13 in cluster AG**

Relative: **Lower**

Actual: **11 ft.**

SPILLS:

Name:	FORMER EXXON STATION - CUMBERLAND FARMS
Address:	215 10TH AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0508226 / 2013-05-02
Facility ID:	0508226
Facility Type:	ER
DER Facility ID:	317601
Site ID:	353766
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	3101
Spill Date:	2005-10-10
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	2005-10-10
CID:	27
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-10-10
Spill Record Last Update:	2013-05-02
Spiller Name:	Not reported
Spiller Company:	FORMER EXXON STATION
Spiller Address:	215 10TH AVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"10.11.05 SR//Sharif spoke with Bill Simmons, they are removing five 4000-gal tanks and found contamination. Apparently, there are no holes in tank. I suggested to dig out as much as possible and take end point sample, send result to DEC. If problem is major i.e., ground water affected, needs long term remediation, then it goes to Koon Tang. 01/26/05 Sharif//Rec'd UST cosure report prepeared by ECS. Five 4000 gallon gasoline single-wall USTs and associated piping were removed. Ground water was encountered during excavation at 6 to 7 feet below grade. Petroleum-impacted soils were encountered within UST grave and beneath former dispenser islands. Dewatering activities were performed in UST grave area to remove impacted soil to 13 ft below ground. Twenty-three post excavation soil samples out of 44 had VOC concentrations above TAGM. Level of remaining soil contamination below groundwater level warrants delineation of groundwater contamination and may require additional long-term remedial efforts. Case has been transferred to Koon Tang for reassignment. 02/03/06: Spill transferred from S. Rahman to J. Kolleeny. Spoke with Bill Simmons of ECS; site had wells put in years ago after soil contam was found, but was closed by J. Rommel of DEC after BTEX levels in GW

EXXON (Continued) **S107415886**

showed decreasing trend and sensitive receptor survey showed no SR's (see spill 9912838). Cumberland Farms sold site, but retain responsibility for env'tal investigation and cleanup. Current owner plans to develop site with 15-story residential building, involving further excavation of soil and possibly dewatering. Owner's consultant is currently doing Phase II investigation and preparing a report. ECS will forward this report, when available, to DEC with their recommendations for further action. - J. Kolleeny 04/06/06: Spoke with Bill Simmons of ECS, he sent an email on 3/30/06 with outline of draft RAP and attached data tables and site plans from upcoming Phase II report being prepared by Impact Env'tal. ECS's draft remedial plan involves soil excavation during site re-development activities, plus mitigation measures like sealing basement of planned residential building with moisture barrier (basement likely to extend into water table, 6-8 feet bg). ECS is pushing RP to do more, rather than less, soil excavation to remove as much potential source material as possible and help GW quality improve. I agreed with this, and suggested applying ORC to open excavation. I also stated that plume is not delineated and addt'l wells are needed, plus after soil excavation there will likely be need for follow-up GW monitoring. GW data from Impact, collected in Jan. '06, showed worst GW along southeastern and northwestern edges of site. I also suggested that another round of GW sampling be conducted soon, approx. 3 mos. (one quarter) after last round. Bill Simmons agreed with these suggestions/statements and indicated that RAP would be submitted in several weeks. - J. Kolleeny 07/26/06: Reviewed Remedial Action Plan (received April 24, 2006), plus diagrams I requested from Bill Simmons of ECS, sent by email on 7/26/06, showing site with historic soil sampling locations, excavated areas, and proposed post-remedial monitoring wells (in eDocs Image Folder). RAP involves excavation of petroleum-contaminated soil encountered during site re-development, de-watering during construction activities, post-excavation soil sampling, and application of ORC to open excavation. In addition, ECS proposes quarterly GW monitoring of existing wells prior to re-development, and installation of 5 new wells (existing wells will be destroyed during construction) for post-remediation monitoring. I sent approval letter (by email and hard copy to Angela Pimental of CFI and Bill Simmons) requesting two more post-remediation monitoring wells, stating that number and locations of post-remediation wells may need to be adjusted based on results of post-ex soil samples, and asking that soil screening and sampling be performed during installation of post-remediation wells. - J. Kolleeny 06/14/07: Spoke with Bill Simmons of ECS, mentioned that approved RAP included implementing quarterly GW monitoring prior to site remediation by excavation, asked if any quarterly monitoring has been done. He indicated that current owner/developer has been unwilling to undertake sampling, and it's unclear which consultant (ECS, Langan or other), should be doing it (site remediation apparently not being done by CFI). I said DEC was being cooperative by allowing remdiation to be linked with site re-development, but that it's not acceptable for all work on spill case to be stalled. Bill said he is attending big meeting regarding project today and will bring up this issue, also said excavation is projected to start in late July; I said in that case it's even more important that baseline GW sampling be performed. He agreed and said he would mention this at meeting and let me know result. I said if RP is not cooperative, he should give

EXXON (Continued) **S107415886**

me contact info and I will pursue them directly. - J. Kolleeny
06/19/07: Sent email to Bill Simmons of ECS to follow up on 6/14/07 conversation: We spoke last week about site, where quartly GW monitoring is to be done while awaiting implementation of approved RAP. You mentioned you were going to meet with parties involved and would bring this up. Can you let me know outcome of meeting? Has anyone agreed to do GW monitoring? Please let me know. Got email from Bill saying: Owner & developers allowed us access, went to Site on June 15, found 2 wells in vicinity of former USTs on northern and NE portions of Site. We sampled them, should have results next week. I reviewed DEC notes and RAP, sent back reply: Thanks for sampling wells. However, I looked back over my notes and RAP and have some concerns. Worst contamination has historically been in well MW-4, which doesn't exist anymore. When sampled by Impact Env'tal in Jan. '06, well had > 35,000 ppb total VOCs! Other well which had significant contam was MW-5, east of former tanks/dispensers, which also doesn't exist anymore. GW flow direction at site has varied, but has at times been to south and/or east. This warrants further delin to evaluate potential off-site migration. When I reviewed/approved RAP in July '06, I thought remedial action would be implemented in near future, and that post-remed mon wells would be installed to evaluate residual GW contam. However, given that nothing has been done for almost a year, I don't think sampling of 2 existing wells on north and NE portions of site is sufficient to determine baseline, pre-remediation GW conditions. I think it's important to install minimum of 2 new wells, either along SE and eastern boundaries of site (in sidewalk along 10th Ave.), or across street to south and SE. Got reply from Bill: Site is currently under development. Plans, to begin next week and continue thru Oct., include install'n of sheet piling, install'n of dewatering treatment system that will operate for 2-3 months, potentially removing millions of gals of water, excavation of petroleum-impacted soil, collection of post-ex soil samples, and mixing of ORC in excavation. RAP details what is to occur at site after development and includes install'n of post-remed mon wells to evaluate potential off-site plume and effects RAP and construction activities have on GW. We were told last year that plans were moving quickly and also thought project would have started several months ago if not late last year. DEP is also involved with reviewing/approving all documents due to Site having E-Designation. Further, access to sidewalks around site will be blocked for construction. Due to logistics involved with installing wells at this time in project (i.e.: lack of access, construction traffic) and certain destruction of any wells installed due to construction and RAP activities that will be performed (i.e.: removal of millions of gals of water, soil excavation and ORC mixing) that will have significant positive effect on subsurface conditions at site, we do not believe install'n of monitoring wells at this time is feasible or warranted. Add'ly, historical GW data (Nov.'00 thru May'04) & data from Jan.'06 sampling event provide adequate baseline info for evaluating pre- & post-remedial impacts. I've attached results of 2 GW samples collected in March '07 for waste characteriz'n data for dewatering and DEP discharge permit criteria by Langan Engrg & Env'tal Svcs on behalf of developer plus Site Plan showing location of samples [in eDocs]. We look forward to discussing further, hear your comments. I reviewed GW waste charact. sample data, wrote back: Thanks for waste charact. GW data. Your arguments are reasonable & persuasive; I withdraw request for install'n of addt'l delin wells at

EXXON (Continued) **S107415886**

this time. As you stated, post-remed wells will have to be installed to evaluate on- & off-site subsurface conditions after remediation and development at site. Please send lab results of 2 wells ECS recently sampled when available, and let me know when soil excavation and de-watering activities have been scheduled; I'd like to come to site to observe. - J. Kolleeny 06/22/07: Received/reviewed copy of Langan Engrg Supplemental Site Invest Rpt dated 6/19/07, and on 6/21/07 sent email to Bill Simmons of ECS: Yesterday I received copy of a Supplemental Site Invest Rpt dated 6/19/07, prepared by Langan Engrg & Envt'l Svcs, addressed to Gary Heath of NYCDEP. This rpt has caused me some concern. Rpt summarizes excavation of 10 test pits across site in March '07, with collection of soil samples. Rpt concludes that there is widespread soil contam at site, but mainly below 8 feet bgs. GW was encountered in test pits, but no free product or sheen was observed. Based on these observations, Langan suggests that removal of contam soil from much of site, in accordance with approved remedial plan, will require unnecessary removal of upper 8 feet of relatively uncontaminated fill material, and that since planned site building will only have small cellar and will have on-grade slab over rest of site, with vapor barrier & sub-slab depressuriz'n system, excavation of contam soil should only be performed in proposed cellar area and petroleum-impacted soil identified elsewhere on site should be left in place. Langan's recommendation seems to be based on premise that only relevant concern posed by petroleum contam is its potential impact on building occupants via vapor intrusion. In fact, there is significant GW contaminant plume beneath site (which may extend off-site) which must be addressed under NYS Envt'l Conserv Law. Based on most recent GW data available to me (Jan. '06), very high levels of GW contam were found outside of planned cellar area (former well MW-4). GW contam at site must be addressed to resolve open spill 0508226. Best way to accomplish this, in light of fact that site is undergoing redevelopment, is to excavate as much contam soil as possible, since soil contam acts as source material for GW contam. This was recognized by ECS in April '06 Remedial Action Plan, which stated ECS proposes performance of exploratory test pits...Any petroleum-impacted soil that is discovered will be excavated and disposed of off-site. This remedial action will remove source areas and ultimately improve GW quality. RAP further proposed application of ORC to open excavation(s), to enhance biodegradation processes which reduce dissolved petroleum contam. DEC has approved April '06 RAP; any change in remedial plan must be submitted to NYSDEC in writing and approved by DEC. This may require collection and submission of up-to-date GW quality data to support revised remedial proposal. Again, I express my concern over Langan's suggestion that soil known to be petroleum contaminated be left in place at site, which contradicts RAP. Please let me know your thoughts on this. - JK 06/27/07: Received call from Bill Simmons of ECS, discussing recent Langan Engrng rpt and my email of 6/22/07. I stated that either impacted soil in southern areas of site (i.e., outside of planned cellar area) must be excavated, or alternative remedial plan must be proposed, which may require addt'l supporting data. Bill sent email summarizing conversation, with attached results for GW samples collected 6/15/07 from two wells in north, NE portions of site. Results (in eDocs) showed no petroleum-related compounds detected. Bill's email stated: Please find attached analytical results of GW sampling of wells MW-7 and MW-8 on 6/15/07. Data indicate no VOCs

EXXON (Continued) **S107415886**

besides chloroform. As follow-up to our phone conversation this a.m. regarding your email: I will discuss with all parties involved need for soil excavation to remove source of GW contam and further migration off site, specifically in vicinity of former well MW-4 located on SE part of site, of which most recent data collected in Jan. '06 by Impact Envt'l indicated total VOCs at 36,901 ppb. We specifically discussed Grids 7, 13, 14, 15, 19 & 20 (per Langan Engrg Site Plan in Supplt'l Site Invest Rpt dated 6/19/07) with depths from 5 fbg to minimally 10 fbg. Note that excavation of southern parts of Grids 7, 13 & 19 will be limited due to presence of abutting building and its structural integrity. If soil excavation is not performed, Revised RAP will be required with new GW data from SE, southern and eastern parts of site with proposal of alternative remedial methods to treat identified soil impact. I will keep you updated on progress. - J. Kolleeny 06/29/07: Received email from Bill Simmons of ECS: We are all in process of determining best strategy for excavation of petroleum-impacted soils in grids discussed along southern and eastern portions of Site. Developer has involved a structural engineering firm to provide geotechnical input specifically about abutting building to south and structural integrity concerns of getting too close to building without likely collapse. We request that you visit property to meet with certain people so an on-site discussion and meeting can better relate all site concerns. I have cc'd Joel Landes of Langan Engineering as he will be heading this issue. I was unable to attend site meeting on July 11, 2007. - J. Kolleeny 07/12/07: Received email from Bill Simmons: I want to provide you with update and status on project site meeting we had on Wednesday July 11. We determined that excavation of petroleum-impacted soils up to 10-12 feet in Grids along southern portions of Site(7,13 and 19) can be completed safely by coming no closer than 10 feet to building benching out 5 feet and using a 1 to 1 slope. As for eastern sidewalk portion (Grids 20, 21 and 22), we can likely get closer to sidewalk property border using a 1 to 1 slope. We will also excavate soils where we see impact in Grids 14 and 15 in addition to already proposed cellar area. ORC will be placed in all completed excavation areas. We anticipate this work will begin week of July 23. - JK 08/02/07: On 7/31/07, received letter from Bill Simmons of ECS dated 7/30/07 (in eDocs), informing DEC of progress at site and addressing my recent concerns. Letter restates comments in his 7/12/07 email regarding depth of excav in various grids with sloping rqmnts to protect struct integrity of abutting bldg, says excavation is expected to begin week of 8/6/07. - JK 01/02/08: Sent email to Bill Simmons of ECS requesting remediation update: I was going through my spills and noticed I haven't had an update on this case since August. Can you send an update on progess of soil excavation? Has de-watering been performed, or application of ORC to excavation? Has end-point soil sampling been performed, and if so, are any lab results available? I think it would be advisable to have DEC review end-point sampling data prior to backfilling excavation. Also, has any additional GW sampling been done? I remind you that RAP I approved for Cumberland Farms - who are, to my knowledge, Responsible Party for this spill - included quarterly GW monitoring prior to remediation. If CFI no longer considers themselves responsible for addressing this spill (which would be news to me), please let me know right away. I re-read my notes on this site, including comments in an email from you which gave impression that there may be more than one RAP for site. In other words, I sense

EXXON (Continued) **S107415886**

that some parties involved (i.e., Langan) are operating under RAP that was not submitted to, reviewed and approved by DEC. If property owner and/or responsible party wish to achieve closure of this spill, we all need to be on same page. Got email reply from Bill: Project is progressing. We are all operating under same RAP so I do not know what you are referring to. Impact Environmental operates dewatering system for CFI and developer and performs daily on-site Health & Safety Monitoring per DEP requirements. Langan is not doing anything except overseeing that things are being performed per all requirements on behalf of developer. 1. From Aug. 27 - Sept. 22, 2007, 1,213.71 tons of soil were removed from GRIDS 7, 10, 11, 13, 14, 15, 19 & 20, up to 12'-13' feet below grade. ORC was added to GRIDS 7, 13, 14, 19 and 20 - See Attached Plan. Post-Ex data from these GRIDS is attached in Table [in eDocs]. 2. Dewatering system was started on 12/12/07. Soil excavation within cellar area down to 15'-17' feet in GRIDS 10, 11, 12, 16, 17, 18, 22, 23 & 24 began on 12/19/07, and is on-going. 3. As we discussed in June '07 it was not possible to do any GW monitoring prior to soil excavation other than what I sent you on 6/19/07, because all wells had been destroyed. 4. I expect cellar soil excavation, post-excavation sampling and ORC application to be completed in next few weeks, but lagging construction for sidewalls for sidewalks will determine this schedule. I sent email to Bill: Thanks for update and soil data. I'm glad end-points look pretty good so far. I guess I got impression there may be more than one remedial plan (besides April '06 ECS plan I approved) because in my notes I've written that Langan mentioned installation of a vapor barrier and sub-slab depressurization system. I recall that RAP I approved mentioned installation of moisture barrier, with presumption that there would be basement extending into water table, and only mentioned passive sub-slab venting system as a possibility. I thought maybe Langan had submitted a more detailed proposal for sub-slab system to NYCDEP because of e-designation - I know they've been submitting reports to DEP and I'm not sure if I'm copied on all of them. Do you have any sampling data for de-watering discharge? I know this is regulated by DEP, not DEC, but I figured if you have data, it could provide some clue as to GW conditions at site. and sent another email: P.S. to my last email, you're right that we discussed GW sampling in June and agreed GW sampling is not possible because wells are destroyed (your item #3 below). Please let me know when you think it might be possible to begin installing some perimeter wells to do follow-up GW monitoring - can this be done once excavation, dewatering, and sidewalk construction are completed, or will it have to wait until site re-development (i.e., new building) is fully complete? Bill wrote back: Wells will not be able to be installed until after development likely - utilities have been moved and sidewalk will be closed until then, and there are site trailers on sidewalks etc... Then Bill sent another email with attachments, stating: I want us all to be clear on all of this. DEP did require installation of vapor barrier and sub-slab depressurization system for building due to e-designation and Langan did previously submit plans to DEP which were approved for developer. I thought you were referring to RAP for Soil and GW issues only. Documents are attached for SSDS and waterproofing. I will forward anything else I can find from Langan regarding this. As for de-watering - I have not seen any data but I can and will request this from Impact - which I will receive eventually anyways in their discharge report/documentation. Attachments (in eDocs) were specs, product info & site plans for

EXXON (Continued) **S107415886**

waterproofing, vapor barrier and sub-slab depressurization system, plus NYCDEP approval letter of same, and DEP Notice To Proceed letter. I sent another email to Bill: I had a chance to look more closely at post-excavation soil data (I didn't initially see there were multiple sheets to Excel file), and noticed there was one sample that had some significant exceedances of TAGM 4046 recommended cleanup objectives - GRID 13 Eastbase 12'-13' sample. Is excavation still open in area where this sample was collected, and would it be feasible to dig a little more soil out in this area? - J. Kolleeny 01/03/08: Received email reply from Bill Simmons of ECS to my 1/2/08 query about excavating addt'l contam soil: Could not dig any further or deeper in that area. Abutting building structure began to be compromised with sidewall cave-ins exposing foundation which was original brick, and GW was not helping - they had to backfill immediately after sample was collected and ORC was added. This is only very small area (less than 5x5 feet) of this sample that exceeded and we dosed it with ORC extremely well. Also, received emails from Bill with attached documents: an 8/1/07 letter rpt from Langan Engrg to NYCDEP, modifying and providing details of their earlier conceptual proposal for waterproofing/vapor barrier system for planned site building, and 12/6/06 letter rpt by Langan to DEP, serving as an addendum to ECS's April '06 RAP; Langan's addendum provides info regarding: (1) capping open areas of site with clean fill/top soil, (2) providing construction health & safety plan, (3) vapor barrier, and (4) active sub-slab venting system. Both Langan documents are in eDocs. I sent email to Bill Simmons: Thanks for providing these documents. I'm satisfied that remediation of subsurf petroleum contam at site is being performed in accordance with April '06 Remedial Action Plan by ECS which I reviewed & approved. Issues addressed in various documents Langan submitted to NYCDEP, including waterproof membrane, vapor barrier, sub-slab depressuriz'n system, and capping of open areas of site with 2 feet of certified clean fill material, are issues that I do get involved with at some of my sites. In most of those cases, I also request involvement of NYS Dept. of Health in reviewing & commenting on such plans. However, in this case, since NYCDEP is taking such an active oversight role because of property's e-designation, I do not feel need to be directly involved in reviewing and evaluating various engineering controls and vapor mitigation measures planned for site, or to request involvement of NYSDOH. Nevertheless, I would appreciate being copied on correspondence regarding such issues between Langan and DEP. - J. Kolleeny 03/16/09: Sent email to Bill Simmons of ECS: I don't think I've heard anything about this site in long while. Can you provide an update? Bill sent reply: No envt'l or construction work has been done at Site since Oct.'08, we think developer has some financial issue which has put project on hold. We have occasionally tried to contact them for their plans, but no response yet. However, here is an envt'l RAP summary so far: We believe that all petroleum-impacted soil excavation has been completed that has generated approx 5,555 tons of soil for off-site recycling -unless developer plans to excavate other areas of site in future and it is discovered - but remaining plans we know of now only consist of removal of top 4 feet of urban fill to be replaced. > 100 post-excavation soils samples were collected from completed excavation areas for lab analysis. ORC (Chemical treatment) in base limits of soil excavation has also been completed. Over 10 million gals of GW were de-watered, treated and discharged until system was shut down last week of Aug.'08. GW samples collected just

EXXON (Continued) **S107415886**

prior to shutting down system on 8/27/08 from INFLUENT before bag filters had 6 VOCs at low levels but still above DEC standards (7 ppb toluene, 6.7 ppb ethylbenzene, 30 ppb xylenes, 11.3 ppb MtBE, 11.5 ppb 1,2,4-Trimethylbenzene, and 5.2 ppb 1,3,5-Trimethylbenzene) and sample collected after bag filters only had MtBE at 10.6 ppb (DEC standard of 10 ppb). Moisture/chemical barrier was installed in basement part of bldg, which has been constructed and formed to grade. Once development resumes, we will know timetable for install'n of off-site post-construction GW monitoring wells and sampling program. Let me know if you have any other questions. I sent back reply: Thanks for update. Will rpt be coming at some point summarizing work done to date, with end-pt soil sample results, details on amount of ORC applied to excavation, and recommendations for install'n of wells and post-remedial GW monitoring? - J. Kolleeny 09/10/09: On 9/9/09, received email from Bill Simmons of ECS: There is some action with this site. Developers are working on selling assets to new developer and they want to push forward install'n of wells in sidewalks soon, before any more work begins in future. To do so, driller (Zebra) need letter to DOT from NYSDEC authorizing access under Spill # to do this work in sidewalks of 10th Ave and 23rd Ave [Street]. Can you provide one asap? We want to try and install 2 wells in each sidewalk (total of 4) but this will be determined once utilities are located and access is available to those locations. We will also install 2 on-site along downgradient western boundary since building is not up yet. I sent sidewalk opening permit request letter (in eDocs) to Bill, cc to Chris Johnson of Cumberland Farms. - J. Kolleeny 12/14/09: Reviewed Remedial Action Plan Closure Rpt by ECS, dated 11/4/09 (parts in eDocs). Rpt summarizes all site invest & remed performed (including excavation of > 5,700 tons of soil, dewatering, and application of RegenOx & ORC Advanced), and presents results of post-remed soil & GW sampling that shows residual contamin in several areas of site. Based on substantial remedial work done to remove contam materials from site and fact that post-remed samples show decreased levels of contam compared with pre-remed samples, ECS recommended spill closure. I sent letter (in eDocs) to Chris Johnson of CFI, cc to Bill Simmons of ECS, saying DEC cannot close spill yet, because of need to monitor residual contam. I asked for quarterly GW monitoring, install'n of one new well NW of most contam well (MW-2) when site conditions permit, surveying of wells to determine up-to-date GW flow direction, submission of quarterly mon rpts. Also said if contam levels stay elevated, site may need addt'l remediation. Changed priority ranking to P2, since site is in monitoring phase. - J. Kolleeny 02/09/10: Reviewed Groundwater Monitoring Report & Work Plan by ECS, dated 2/5/10 (in eDocs). Rpt presents results of Jan. 2010 GW sampling of 6 on-site wells and work plan for install'n of addt'l well as I requested in 12/14/09 letter. GW results show total VOCs in worst well MW-2 decreased from 2,434 ug/L in Oct.'09 to 99 ug/L in Jan. 2010; 2nd worst well City MW-6 had 522 ug/L in Jan. 2010, down slightly from 550 ug/L tVOCs in Oct.'09. Work plan proposes new well in sidewalk along W. 23rd St. (west of SW corner of W. 23rd St. & 10th Ave.). I sent approval letter (in eDocs) to Chris Johnson of CFI, cc to Bill Simmons of ECS, saying new and existing wells should be surveyed to determine up-to-date GW flow direction. - J. Kolleeny 02/10/10: Received email from Bill Simmons of ECS: New wrinkle to discuss. DOT plans to install an elevator to High Tran that abuts Site to west. Elevator will be installed in sidewalk along West 23rd St in NW portion of sidewalk. Attached is

EXXON (Continued) **S107415886**

their plan [in eDocs]depicting where they plan on digging etc., which is to start week of Feb. 22. Our monitoring well MW-1 and their well CITY-MW-6 are in this area and will likely be destroyed but I ll find out next week. Newly proposed well MW-7 is east of this area and should be ok. I'll be meeting with them next week to discuss their plan including likelihood that if they dig to 15 -17 they will find petroleum-impacted soil since we only excavated up to these edges. We will plan on being there to cooperate management of this and collect closure samples. My question is this: We have to survey wells to get GW flow. These are options: 1. Survey all 6 wells before this works starts and use gauging data to get flow direction now. However, 2 wells will be destroyed in next few weeks so we will not have any more data from them and do not know if we will be able to install any replacement wells in this area. 2. Wait until this work is done, then install MW-7 and survey 5 existing wells. Maybe we will know once elevator project is done if any replacement wells can go in this zone and we could install it and survey it also. Please advise. I wrote back: I prefer option 2 - wait until DOT finishes installing elevator, then install MW-7 and see if it's possible to install one replacement well for 2 destroyed wells (since well CITY-MW-6 had moderately elevated contamination), and survey wells at that point. Thanks for keeping me posted. - J. Kolleeny 05/03/10: Reviewed GW Mon Update Rpt dated 4/28/10, by ECS (in eDocs). Rpt summarizes March 2010 post-remediation GW sampling event. Worst well, MW-2, had total VOCs of 558.5 ug/L, up from 99 ug/L in Jan. 2010 (but down from 2,395 ug/L in Oct.'09). Well City MW-6 had tVOCs of 39 ug/L, down from 349 ug/L in Jan. 2010; well MW-3 had 67 ug/L tVOCs, about same as 59 ug/L in Jan. 2010. Wells MW-1, MW-4 & MW-5 were ND for VOCs. Rpt states that DOT sidewalk elevator project is anticipated to start in May 2010. Future Work section of rpt states that ECS will notify DEC when DOT provides start date for elevator work, and will be on-site during soil excavation to collect post-ex samples; once DOT work is complete, ECS will install well I requested near NE corner of W. 23rd St & 10th Ave., and if applicable, replacement well in elevator area. These events and data from next qtrly GW event will be in next rpt. - JK 06/15/10: On 6/14/10, received email from Bill Simmons of ECS: An update: Due to ongoing delay on start of elevator sidewalk project (any day now for past 3 months) we plan to install proposed monitoring well MW-7 in sidewalk on June 16. On May 27, 2010 a construction crew discovered an abandoned 250 gal oil tank during pile cap excavation on SW portion of Site. Tank was partly filled with soil & concrete, was removed from ground and is currently stored at site covered in plastic tarp; it will be removed soon, as access to this area is now blocked. We collected soil samples from beneath tank that field-screened at Zero and submitted some samples for lab analysis. This will be summarized in next rpt. On 6/15/10 I replied: Thanks for update, glad you're proceeding with install'n of MW-7, and thanks for taking necessary steps with discovered 250-gallon tank. Keep me posted on progress. - JK 11/10/10: Reviewed GW Mon Update Rpt by ECS, dated 8/18/10, rcvd at DEC on 9/7/10 (in eDocs). Rpt summarizes install'n of addt'l well MW-7 in sidewalk along W. 23rd St. north of MW-2, as requested by DEC, in June 2010, and sampling of wells MW-1, MW-2, MW-3, CITY MW-6 and MW-7, also in June 2010. Worst well was CITY MW-6, with 660 ug/L total VOCs. In June & July 2010, 483 tons of soil was excavated/removed from site for construction. Rpt states, for Future Work, that DEC will be notified when High Line Park elevator sidewalk construction project will start; once project is

EXXON (Continued) **S107415886**

completed, need for replacement wells will be evaluated. - JK 12/10/10: Sent email to Bill Simmons of ECS: Any update on Highline Park elevator constructn project? Has any GW monitoring been performed since June 2010 event, which was summarized in update rpt dated 8/18/10? Bill wrote back: City began elevator project ~Aug. 23 by installing shoring in 44 x20 area in sidewalk. Between then and Sept. 7 they removed soil - 22 trucks, which equates to somewhere around 550-650 tons or so removed from surface to 17 ft deep. They dewatered and treated via carbon from around Sept. 7 through sometime around end of Oct. or early Nov., reportedly at around at least 8,500/GPD. June 2010 GW sampling event was last. All site wells have been destroyed, even wells in east sidewalk along 10th Ave. Building is going up and taking up every inch of space they have to street edges. We were on-site during portions of this work but no post-ex soil samples could be collected due to shoring walls and base at 17 was all mud. We are trying to get any soil disposal manifests and dewatering backup, but I can t promise. I will at least try to get specifics # s on any of tonnage and gallons if I can. I sent back response: Thanks for update. Do you know if City did any sampling of untreated and/or treated dewatering water, and if so, if it's possible to get hold of any of sampling results? He wrote back: That is what we are looking to get. They told us prior to installing dewatering pump and setting up system that they were planning on collecting an influent untreated sample and they were discharging to sewer so they must have been sampling that according to whatever permit they had but they have not provided us any info. I will try again and let you know they are very evasive. - JK 05/02/13: Reviewed Spill Closure Rqst rpt by ECS, dated 4/22/13 (in eDocs). Rpt summarizes all investigative & remedial actions performed at site. In particular, rpt notes that in Oct. 2005, ~1,565 tons of petroleum-impacted soil were removed from former UST area on northern portion of site and 5,741 gals of GW were pumped during dewatering activities; between July & Aug. of 2007, ~1,924 tons of soil classed as clean fill were excavated from top 5 ft of entire site; between Aug. 2007 and Oct. 2008, 5,712 tons of soil were excavated at depths ranging from 8-18 ft, from 70% of site (some end-point samples showed residual soil impacts); RegenOx and ORC Advanced were applied to excavation; and ~ 9,158,400 gals of GW were pumped out, treated and discharged to DEP combined sewer as part of construction- and excavation-related dewatering. Also, in Aug.-Oct. 2010, as part of construction activities for NYCEDC elevator (along west 23rd St) to High Line Park, ~850-950 tons of petroleum-impacted soil were excavated to depth of 17-18 ft (9-10 ft below water table) from 44' x 20' area of sidewalk along 23rd St., along NE site boundary, and a GW dewatering system operated for 6 weeks pumping ~8,500 gals/day, for total of ~380,000 gals recovered, treated & discharged (ECS was not able to obtain actual data on soil or GW from NYCEDC). In addition to these remedial actions, a vapor barrier membrane and active sub-membrane depressurization system were installed beneath bldg (except cellar area which extends into GW and has waterproofing); these engineering controls will mitigate potential vapor intrusion from any residual soil & GW impacts. Last available post-remedial GW data, from June 2010, showed worst result was 660 ug/L total VOCs in well CITY MW-6; this well & several others were destroyed during NYCEDC's High Line elevator install'n project, but presumably soil excavated and GW dewatered during project would have helped reduce residual GW contaminant levels and promote further natural

EXXON (Continued) **S107415886**

attenuation of any remaining impacts. Based on all remedial actions performed and engineering controls implemented, ECS concludes that no further action is warranted at site and requests spill closure. I concur. I closed spill, sent closure letter (in eDocs) to Chris Johnson of Cumberland-Gulf Group of Companies, cc to Bill Simmons of ECS. - J. Kolleeny "

Remarks: "Caller reports removing five 4000 gallon tanks. There is contamination at the site. Caller reports no holes in the tanks. Cumberland Farms will be contacting a company for cleanup. Contractor on the site removing the tanks is: Tyree Orginazation Roland Fisher 631.300.6753."

All Materials:

Site ID:	353766
Operable Unit ID:	1111215
Operable Unit:	01
Material ID:	2101258
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	215 EAST 10TH STREET
Address:	215 EAST 10TH STREET
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	9514249 / 1996-02-08
Facility ID:	9514249
Facility Type:	ER
DER Facility ID:	138323
Site ID:	164026
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	1996-02-08
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1996-02-08
CID:	204
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-02-08
Spill Record Last Update:	1996-02-21
Spiller Name:	SERGIO ALLEFRETTI
Spiller Company:	BAYSIDE OIL
Spiller Address:	1810 SHORE PKWY

EXXON (Continued) **S107415886**

Spiller Company: 001
Contact Name: SERGIO ALLEFRETTI
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG SPILL CLEANED UP, CLOSED "
Remarks: "hose broke while filling"

All Materials:
Site ID: 164026
Operable Unit ID: 1028789
Operable Unit: 01
Material ID: 354381
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 30.00
Units: G
Recovered: 30.00
Oxygenate: Not reported

Name: EXXONMOBIL
Address: 215 10TH AVE
City,State,Zip: NEW YORK, NY
Spill Number/Closed Date: 9209044 / 1992-11-05
Facility ID: 9209044
Facility Type: ER
DER Facility ID: 317601
Site ID: 189187
DEC Region: 2
Spill Cause: Traffic Accident
Spill Class: C3
SWIS: 3101
Spill Date: 1992-11-04
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1992-11-04
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Responsible Party
Cleanup Ceased: 1992-11-05
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1992-11-05
Spill Record Last Update: 2006-07-24
Spiller Name: JOANNE WALLACH
Spiller Company: EXXONMOBIL
Spiller Address: 3225 GALLOWS ROAD
Spiller Company: 001
Contact Name: Not reported
DEC Memo: ""
Remarks: "CUSTOMER DRIVEN OFF W/NOZZLE OPEN ON TANK,WASHED DOWN W/HOSE"

All Materials:

EXXON (Continued) **S107415886**

Site ID: 189187
Operable Unit ID: 975798
Operable Unit: 01
Material ID: 406112
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: EXXONMOBIL
Address: 215 10TH AVE
City,State,Zip: NEW YORK, NY
Spill Number/Closed Date: 9402020 / 1994-10-18
Facility ID: 9402020
Facility Type: ER
DER Facility ID: 317601
Site ID: 189188
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 3101
Spill Date: 1994-05-11
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1994-05-11
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Responsible Party
Cleanup Ceased: 1994-10-18
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: True
Remediation Phase: 0
Date Entered In Computer: 1994-05-25
Spill Record Last Update: 2006-07-24
Spiller Name: JOANNE WALLACH
Spiller Company: EXXONMOBIL
Spiller Address: 3225 GALLOWS ROAD
Spiller Company: 001
Contact Name: Not reported
DEC Memo: ""
Remarks: "WIPING DISPENSER- SOIL GROUND WET) NOW OUT OF SERVICE. LARRY WATSON TO FOLLOW UP."

All Materials:
Site ID: 189188
Operable Unit ID: 999075
Operable Unit: 01
Material ID: 385762
Material Code: 0009
Material Name: gasoline

EXXON (Continued) **S107415886**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	CHEVRON W. 23 ST GW SPILL
Address:	215 10TH AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	8600912 / 1987-08-31
Facility ID:	8600912
Facility Type:	ER
DER Facility ID:	317601
Site ID:	187376
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	3101
Spill Date:	1986-05-07
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1986-05-07
CID:	Not reported
Water Affected:	GROUNDWATER
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	1987-08-31
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1986-06-09
Spill Record Last Update:	2006-07-24
Spiller Name:	Not reported
Spiller Company:	CHEVRON/GULF
Spiller Address:	SAME AS ABOVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"4/22/05 From Old Spill File(KMF): Letter from Fenley and Nichol dated 11/30/89: On 11/29/89 and 11/30/89, Fenley & Nichol excavated, cleaned and legally disposed of four 2000gal gasoline tanks from the site. Eight soil samples were taken. The site has a vapor recovery system that was installed at the beginning of 1989 and will continue to operate. PBS #2-336939"
Remarks:	"18 OF PRODUCTION OBSERVATION WELL. CLEANED UP BY GULF."

All Materials:

Site ID:	187376
Operable Unit ID:	898582
Operable Unit:	01
Material ID:	477478
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum

EXXON (Continued) **S107415886**

Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	EXXONMOBIL #32253
Address:	215 10TH AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0204459 / 2003-09-29
Facility ID:	0204459
Facility Type:	ER
DER Facility ID:	317601
Site ID:	267659
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	3101
Spill Date:	2000-02-10
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2002-07-29
CID:	205
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2002-07-29
Spill Record Last Update:	2006-07-24
Spiller Name:	JOANNE WALLACH
Spiller Company:	EXXONMOBIL
Spiller Address:	3225 GALLOWS RAOD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"Site investigation by Conoco Phillips revealed that the site has indications of historic soil contamination."

All Materials:

Site ID:	267659
Operable Unit ID:	855617
Operable Unit:	01
Material ID:	518709
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

EXXON (Continued) **S107415886**

Name:	EXXON STATION
Address:	215 10TH AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	9912838 / 2004-07-12
Facility ID:	9912838
Facility Type:	ER
DER Facility ID:	317601
Site ID:	267660
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	3101
Spill Date:	2000-02-10
Investigator:	JMROMMEL
Referred To:	Not reported
Reported to Dept:	2000-02-10
CID:	252
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2000-02-10
Spill Record Last Update:	2006-07-24
Spiller Name:	JOANNE WALLACH
Spiller Company:	EXXONMOBIL
Spiller Address:	3225 GALLOWS ROAD
Spiller Company:	001
Contact Name:	MICHAEL FREY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL This spill case was reassigned from DEC (Sigona) to Rommel on 02/10/2004. This spill site cleanup has been consolidated under Spill No. 9912838. 2/5/04 Current PBS owner Cumberland Farms. 07/12/04 Reviewed Site Status Update - Dec 2003 trhu Feb 04. Hottest well, MW4 on upgradient corner, BTEX 2219 ppb. Downward trend (max 10,375 ppb in MW4. Downgradient wells <5ppb BTEX. Sensitive receptor survey performed. Spill closed. Rommel"
Remarks:	"SOIL CONTAMINATION WAS DISCOVERED - SOIL SAMPLES TAKEN - CLEANUP PENDING LAB RESULTS."

All Materials:

Site ID:	267660
Operable Unit ID:	1091541
Operable Unit:	01
Material ID:	294703
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

EXXON (Continued) **S107415886**

NY MANIFEST:

Name:	EXXON
Address:	215 10TH AVE & W 23RD ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYD987026069
Facility Status:	Not reported
Location Address 1:	EXXON 3-2253 - 215 10TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987026069
Mailing Name:	EXXON
Mailing Contact:	C H CRUTCHFIELD
Mailing Address 1:	P O BOX 4415
Mailing Address 2:	Not reported
Mailing City:	HOUSTON
Mailing State:	TX
Mailing Zip:	77210
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	8009923647

AG654 **EXXON DIV OF CFI #70289** **RCRA-VSQG** **1000791102**
North **215 10TH AVE & W 23RD ST** **NY UST** **NYD987026069**
1/8-1/4 **NEW YORK, NY 10011** **FINDS**
0.182 mi. **ECHO**
960 ft. **Site 13 of 13 in cluster AG**

Relative: **Lower**

Actual: **11 ft.**

RCRA-VSQG:

Date Form Received by Agency:		20070101
Handler Name:	EXXON DIV OF CFI #70289	
Handler Address:		215 10TH AVE & W 23RD ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYD987026069
Contact Name:		MAUREEN JERNSTEDT
Contact Address:		DEDHAM ST
Contact City,State,Zip:		CANTON, MA 02021
Contact Telephone:		800-225-9702 3378
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2

EXXON DIV OF CFI #70289 (Continued) **1000791102**

Mailing Address:	DEDHAM ST
Mailing City,State,Zip:	CANTON, MA 02021
Owner Name:	TOSCO
Owner Type:	Private
Operator Name:	NO NAME FOUND
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

EXXON DIV OF CFI #70289 (Continued) **1000791102**

Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Biennial: List of Years
Year: 2003

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D018
Waste Description: BENZENE

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: TOSCO
Legal Status: Private
Date Became Current: 20000301
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 52085
Owner/Operator City,State,Zip: PHOENIX, AZ 85072-2085
Owner/Operator Telephone: 602-728-8000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CUMBERLAND FARMS INC
Legal Status: Private
Date Became Current: 20030910
Date Ended Current: Not reported
Owner/Operator Address: 777 DEDHAM ST
Owner/Operator City,State,Zip: CANTON, MA 02021
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TOSCO
Legal Status: Private
Date Became Current: 20000301
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 52085
Owner/Operator City,State,Zip: PHOENIX, AZ 85072-2085
Owner/Operator Telephone: 602-728-8000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

EXXON DIV OF CFI #70289 (Continued) **1000791102**

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CUMBERLAND JFARMS INC
Legal Status:	Private
Date Became Current:	20030910
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	TOSCO
Legal Status:	Private
Date Became Current:	20000301
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 52085
Owner/Operator City,State,Zip:	PHOENIX, AZ 85072-2085
Owner/Operator Telephone:	602-728-8000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NO NAME FOUND
Legal Status:	Private
Date Became Current:	20030910
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CUMBERLAND FARMS
Legal Status:	Private
Date Became Current:	20030910
Date Ended Current:	Not reported
Owner/Operator Address:	777 DEDHAM ST
Owner/Operator City,State,Zip:	CANTON, MA 02021
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	BIG APPLE TIGER INC.
Legal Status:	Private
Date Became Current:	20030910
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported

EXXON DIV OF CFI #70289 (Continued) **1000791102**

Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	CUMBERLAND FARMS INC
Legal Status:	Private
Date Became Current:	20030910
Date Ended Current:	Not reported
Owner/Operator Address:	777 DEDHAM ST
Owner/Operator City,State,Zip:	CANTON, MA 02021
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: TOSCO #34649	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: EXXON DIV OF CFI #70289	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: EXXON DIV OF CFI #70289	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19930115
Handler Name: TOSCO #34649	

EXXON DIV OF CFI #70289 (Continued) **1000791102**

Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010808
Handler Name: TOSCO #34649	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20041005
Handler Name: EXXON DIV OF CFI #70289	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20040810
Handler Name: EXXON #70289	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	44711
NAICS Description:	GASOLINE STATIONS WITH CONVENIENCE STORES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

EXXON DIV OF CFI #70289 (Continued) **1000791102**

Evaluation Action Summary:
Evaluations: No Evaluations Found

UST:
Name: #70289 - EXXON DIV. OF CFI
Address: 215 10TH AVENUE
City,State,Zip: NEW YORK, NY 10023
Id/Status: 2-600799 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 585848.99132
UTM Y: 4514490.85745
Site Type: Retail Gasoline Sales

Affiliation Records:
Site Id: 22775
Affiliation Type: Facility Operator
Company Name: #70289 EXXON DIV. OF CFI
Contact Type: Not reported
Contact Name: CUMBERLAND FARMS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 828-4900
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2005-10-24

Site Id: 22775
Affiliation Type: Facility Owner
Company Name: CUMBERLAND FARMS, INC.
Contact Type: SR. ENV. OPERATIONS MANAGER
Contact Name: ANGELA PIMENTAL
Address1: 100 CROSSING BOULEVARD
Address2: Not reported
City: FRAMINGHAM
State: MA
Zip Code: 01702
Country Code: 999
Phone: (800) 225-9702
EMail: Not reported
Fax Number: Not reported
Modified By: RBMULVEY
Date Last Modified: 2019-01-02

Site Id: 22775
Affiliation Type: Mail Contact
Company Name: CUMBERLAND FARMS, INC.
Contact Type: SR. ENV. OPERATIONS MANAGER
Contact Name: ANGELA PIMENTAL

EXXON DIV OF CFI #70289 (Continued) **1000791102**

Address1:	100 CROSSING BOULEVARD
Address2:	Not reported
City:	FRAMINGHAM
State:	MA
Zip Code:	01702
Country Code:	999
Phone:	(800) 225-9702
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RBMULVEY
Date Last Modified:	2019-01-02

Site Id:	22775
Affiliation Type:	Emergency Contact
Company Name:	CUMBERLAND FARMS INC.
Contact Type:	Not reported
Contact Name:	STORE MANAGER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(781) 828-4900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-10-24

Tank Info:

Tank Number:	01
Tank ID:	43761
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	11/01/1991
Date Tank Closed:	10/01/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	21
Date Test:	04/10/2003
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

J01 - Dispenser - Pressurized Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
E04 - Piping Secondary Containment - Double walled UG
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground

EXXON DIV OF CFI #70289 (Continued) **1000791102**

K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 02
Tank ID: 43762
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1991
Date Tank Closed: 10/01/2005
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 04/10/2003
Next Test Date: Not reported
Pipe Model: D
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

J01 - Dispenser - Pressurized Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
E04 - Piping Secondary Containment - Double walled UG
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 03
Tank ID: 43763
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1991
Date Tank Closed: 10/01/2005
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21

EXXON DIV OF CFI #70289 (Continued) **1000791102**

Date Test: 04/10/2003
Next Test Date: Not reported
Pipe Model: D
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

J01 - Dispenser - Pressurized Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
E04 - Piping Secondary Containment - Double walled UG
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 04
Tank ID: 43764
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1991
Date Tank Closed: 10/01/2005
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 04/10/2003
Next Test Date: Not reported
Pipe Model: D
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
E04 - Piping Secondary Containment - Double walled UG
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J01 - Dispenser - Pressurized Dispenser
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 05
Tank ID: 43765

EXXON DIV OF CFI #70289 (Continued) **1000791102**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	11/01/1991
Date Tank Closed:	10/01/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	21
Date Test:	04/10/2003
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

J01 - Dispenser - Pressurized Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
E04 - Piping Secondary Containment - Double walled UG
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G04 - Tank Secondary Containment - Double-Walled (Underground)

FINDS:
Registry ID: 110064189293

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000791102
Registry ID:	110064189293
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110064189293
Name:	EXXON DIV OF CFI #70289
Address:	215 10TH AVE & W 23RD ST
City,State,Zip:	NEW YORK, NY 10011

AU655 **CON EDISON** **NY MANIFEST** **S117315219**
NE **FO 401 WEST 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10010**
0.182 mi.
963 ft. **Site 12 of 16 in cluster AU**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FO 401 WEST 23RD ST
City,State,Zip:	NEW YORK, NY 10010
Country:	USA
EPA ID:	NYP004623575
Facility Status:	Not reported
Location Address 1:	FO 401 WEST 23RD ST
Code:	BP
Location Address 2:	VAULT 3842
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10010
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004623575
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/11/2014
Trans1 Recv Date:	08/11/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/13/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004623575
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407385GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117315219**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI656 **85 EIGHT AVENUE OWNERS CORPORATION** **NY AST** **U003392769**
SSE **85 EIGHTH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.183 mi.
967 ft. **Site 7 of 7 in cluster AI**

Relative:
Higher

Actual:
21 ft.

AST:

Name:	85 EIGHT AVENUE OWNERS CORPORATION
Address:	85 EIGHTH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-242810
Program Type:	PBS
UTM X:	584230.06204
UTM Y:	4510402.39380
Expiration Date:	01/07/2018
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	9321
Affiliation Type:	Facility Owner
Company Name:	85 8TH AVENUE OWNERS CORP. C/O PRIDE PROPERTY MGMT
Contact Type:	MANAGING AGENT
Contact Name:	MONICA KELLER LARGE
Address1:	11 NEW STREET
Address2:	Not reported
City:	ENGLEWOOD CLIFFS
State:	NJ
Zip Code:	07632
Country Code:	001

85 EIGHT AVENUE OWNERS CORPORATION (Continued) **U003392769**

Phone:	(212) 690-0800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-08-17

Site Id:	9321
Affiliation Type:	Mail Contact
Company Name:	PRIDE PROPERTY MANAGEMENT
Contact Type:	Not reported
Contact Name:	MONICA KELLER LARGE
Address1:	11 NEW STREET
Address2:	Not reported
City:	ENGLEWOOD CLIFFS
State:	NJ
Zip Code:	07632
Country Code:	001
Phone:	(201) 567-2150
EMail:	MONICA@PRIDE22.COM
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-08-17

Site Id:	9321
Affiliation Type:	Facility Operator
Company Name:	85 EIGHT AVENUE OWNERS CORPORATION
Contact Type:	Not reported
Contact Name:	VIRGIL FERREIRA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(848) 218-1416
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-08-17

Site Id:	9321
Affiliation Type:	Emergency Contact
Company Name:	85 8TH AVENUE OWNERS CORP. C/O PRIDE PROPERTY MGMT
Contact Type:	Not reported
Contact Name:	MONICA KELLER LARGE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 690-0800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-08-17

85 EIGHT AVENUE OWNERS CORPORATION (Continued) **U003392769**

Tank Info:

Tank Number:	001
Tank Id:	25364
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	C01 - Pipe Location - Aboveground
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	I05 - Overfill - Vent Whistle
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	J02 - Dispenser - Suction Dispenser
	G01 - Tank Secondary Containment - Diking (Aboveground)
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/07/1961
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AX657 **CON EDISON - SERVICE BOX 32428** **RCRA-LQG** **1016144227**
NNE **N/W/C WEST 48TH ST. & 8TH AVE.** **NY MANIFEST** **NYP004270161**
1/8-1/4 **NEW YORK, NY 10036**
0.183 mi.
968 ft. **Site 2 of 7 in cluster AX**

Relative: RCRA-LQG:
Higher

Date Form Received by Agency:	20140327
Handler Name:	CON EDISON - SERVICE BOX 32428
Handler Address:	N/W/C WEST 48TH ST. & 8TH AVE.
Handler City,State,Zip:	NEW YORK, NY 10036
EPA ID:	NYP004270161
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	631-208-0233
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported

Actual:
15 ft.

CON EDISON - SERVICE BOX 32428 (Continued) **1016144227**

Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No

CON EDISON - SERVICE BOX 32428 (Continued) **1016144227**

Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20130222
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20130222
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20140327
Handler Name:	CON EDISON - SERVICE BOX 32428
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

CON EDISON - SERVICE BOX 32428 (Continued) **1016144227**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130222
Handler Name: CON EDISON SERVICE BOX: 4179
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130322
Handler Name: CON EDISON SERVICE BOX: 4179
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 425 W 23RD ST
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYP004270161
Facility Status: Not reported
Location Address 1: 425 W 23RD ST
Code: BP
Location Address 2: SERV BOX 4179
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

CON EDISON - SERVICE BOX 32428 (Continued) **1016144227**

NY MANIFEST:

EPAID:	NYP004270161
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/22/2013
Trans1 Recv Date:	02/22/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/22/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004270161
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840427JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON - SERVICE BOX 32428 (Continued) **1016144227**

Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

AP658 **CHELSEA OPERATING, INC.** **NY UST** **U001736518**
NNW **521 WEST 21ST STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.184 mi.
970 ft. **Site 6 of 6 in cluster AP**

Relative:
Lower

Actual:
9 ft.

UST:
Name: CHELSEA OPERATING, INC.
Address: 521 WEST 21ST STREET
City,State,Zip: NEW YORK, NY 10011
Id/Status: 2-601593 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 583908.49308
UTM Y: 4511140.57247
Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:
Site Id: 23555
Affiliation Type: Emergency Contact
Company Name: CHELSEA OPERATING, INC.
Contact Type: Not reported
Contact Name: GUY ROBERTS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 217-2441
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2005-11-29

Site Id: 23555
Affiliation Type: Facility Operator
Company Name: CHELSEA OPERATING, INC.
Contact Type: Not reported
Contact Name: CHELSEA OPERATING INC.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 675-4979
EMail: Not reported
Fax Number: Not reported

CHELSEA OPERATING, INC. (Continued) **U001736518**

Modified By:	NRLOMBAR
Date Last Modified:	2005-11-29
Site Id:	23555
Affiliation Type:	Mail Contact
Company Name:	CHELSEA OPERATING, INC.
Contact Type:	Not reported
Contact Name:	GUY ROBERTS
Address1:	415 WEST 127TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10027
Country Code:	001
Phone:	(212) 665-4900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-11-29
Site Id:	23555
Affiliation Type:	Facility Owner
Company Name:	CHELSEA OPERATING, INC.
Contact Type:	PRESIDENT
Contact Name:	CHELSEA OPERATING' INC.
Address1:	415 W 127TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10027
Country Code:	001
Phone:	(212) 665-4900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-11-29

Tank Info:

Tank Number:	001
Tank ID:	47076
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1997
Date Tank Closed:	10/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT

CHELSEA OPERATING, INC. (Continued) **U001736518**

Last Modified: 04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number: 002
Tank ID: 47077
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1997
Date Tank Closed: 10/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number: 003
Tank ID: 47078
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1997
Date Tank Closed: 10/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

CHELSEA OPERATING, INC. (Continued) **U001736518**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Number: 004
Tank ID: 47079
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1997
Date Tank Closed: 10/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping

Tank Number: 005
Tank ID: 47080
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1997
Date Tank Closed: 10/01/1997

CHELSEA OPERATING, INC. (Continued) **U001736518**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number: 007
Tank ID: 208780
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 1500
Install Date: Not reported
Date Tank Closed: 11/09/2005
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None
D10 - Pipe Type - Copper
L00 - Piping Leak Detection - None

AU659 **CON EDISON** **NJ MANIFEST** **S120672837**
NE **373 W 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.184 mi.
970 ft. **Site 13 of 16 in cluster AU**

Relative:
Higher

Actual:
19 ft.

NJ MANIFEST:

EPA Id:	NYP004794780
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002614401GBF
EPA ID:	NYP004794780
Date Shipped:	6/15/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120672837**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AU660 **CON EDISON** **NY MANIFEST** **S118256933**
NE **373 W 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.184 mi.
970 ft. **Site 14 of 16 in cluster AU**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	373 W 23RD ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004794780
Facility Status:	Not reported
Location Address 1:	373 W 23RD ST
Code:	BP
Location Address 2:	SB 4197
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004794780
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/15/2015
Trans1 Recv Date:	06/15/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/16/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004794780
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S118256933**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002614401GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AU661 **CON EDISON** **RCRA NonGen / NLR** **1019904183**
NE **373 W 23RD ST** **FINDS** **NYP004794780**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.184 mi.
970 ft. **Site 15 of 16 in cluster AU**

Relative: RCRA NonGen / NLR:
Higher

Date Form Received by Agency:		20150615
Actual: Handler Name:	CON EDISON	
19 ft. Handler Address:		373 W 23RD ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004794780
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported

CON EDISON (Continued) **1019904183**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No

CON EDISON (Continued) **1019904183**

Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150615
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150615
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069691863

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource

CON EDISON (Continued) **1019904183**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019904183
Registry ID:	110069691863
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069691863
Name:	CON EDISON
Address:	373 W 23RD ST
City,State,Zip:	NEW YORK, NY 10011

AY662 **529 WEST 20TH ST LLC** **NY AST** **U004138379**
NNW **529 WEST 20TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.184 mi.
972 ft. **Site 1 of 11 in cluster AY**

Relative: **Lower**

Actual: **8 ft.**

AST:

Name:	529 WEST 20TH ST LLC
Address:	529 WEST 20TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-611117
Program Type:	PBS
UTM X:	583835.80348
UTM Y:	4511097.07233
Expiration Date:	07/02/2024
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	415707
Affiliation Type:	Facility Operator
Company Name:	KALIMIAN WEST 20TH LLC
Contact Type:	Not reported
Contact Name:	FRANK PISANI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 229-0853
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2009-06-26

Site Id:	415707
Affiliation Type:	Emergency Contact
Company Name:	KALIMIAN WEST 20TH LLC
Contact Type:	Not reported

529 WEST 20TH ST LLC (Continued) **U004138379**

Contact Name:	FRANK PISANI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(570) 807-6379
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2009-06-26

Site Id:	415707
Affiliation Type:	Facility Owner
Company Name:	529 WEST 20TH STREET LLC
Contact Type:	DIRECTOR OF MANGEMENT
Contact Name:	JAMES W. SHEEHAN
Address1:	600 LEXINGTON AVE 14TH FLOOR
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(212) 751-8050 105
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-04-11

Site Id:	415707
Affiliation Type:	Mail Contact
Company Name:	529 WEST 20TH STREET LLC
Contact Type:	Not reported
Contact Name:	JAMES SHEEHAN
Address1:	600 LEXINGTON AVE
Address2:	14TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(212) 751-8050
EMail:	JIM@ROY-AL.COM
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-07-18

Tank Info:

Tank Number:	001
Tank Id:	229087
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)

529 WEST 20TH ST LLC (Continued) **U004138379**

C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/15/1999
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AX663 **CON EDISON - VAULT 4749** **RCRA-LQG** **1024891710**
NNE **433 W 23RD ST** **NYP005137918**
1/8-1/4 **NEW YORK, NY 10011**
0.185 mi.
975 ft. **Site 3 of 7 in cluster AX**

Relative: **Higher**
Actual: **14 ft.**

RCRA-LQG:

Date Form Received by Agency:		20180410
Handler Name:	CON EDISON - VAULT 4749	
Handler Address:		433 W 23RD ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP005137918
Contact Name:		ALYSSA SOTTO
Contact Address:		IRVING PLACE, 15TH FL NE
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-2757
Contact Fax:		Not reported
Contact Email:		SOTTOA@CONED.COM
Contact Title:		ASSOCIATE SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Large Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		2017
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		CONSOLIDATED EDISON COMPANY OF NY, INC.

CON EDISON - VAULT 4749 (Continued) **1024891710**

Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

CON EDISON - VAULT 4749 (Continued) **1024891710**

Sub-Part P Indicator: No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170908
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170908
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180410
Handler Name: CON EDISON - VAULT 4749
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

CON EDISON - VAULT 4749 (Continued) **1024891710**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AX664 **CON EDISON - VAULT 4749** **NY MANIFEST** **S121968642**
NNE **433 W 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.185 mi.
975 ft. **Site 4 of 7 in cluster AX**

Relative: **Higher**
Actual: **14 ft.**

NY MANIFEST:

Name:	CON EDISON - VAULT 4749
Address:	433 W 23RD ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP005137918
Facility Status:	Not reported
Location Address 1:	433 W 23RD ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005137918
Mailing Name:	CON EDISON - VAULT 4749
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

AS665 **38-52, 38-56 10TH AVE** **NY LTANKS** **S102672294**
SW **38-52, 38-56 10TH AVE** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.185 mi.
975 ft. **Site 8 of 11 in cluster AS**

Relative: **Lower**
Actual: **7 ft.**

LTANKS:

Name:	38-52, 38-56 10TH AVE
Address:	38-52, 38-56 10TH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9311497 / 1993-12-24
Facility ID:	9311497
Site ID:	79206

38-52, 38-56 10TH AVE (Continued) **S102672294**

Spill Date:	1993-12-24
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1993-12-24
SWIS:	3101
Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	1993-12-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-12-28
Spill Record Last Update:	2003-08-08
Spiller Name:	Not reported
Spiller Company:	COASTAL OIL
Spiller Address:	31-70 COLLEGE PT BLVD.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	73632
DEC Memo:	""
Remarks:	"TANK OVERFILLED FROM FAULTY GAUGE READING - NO OTHER AGENCIES - OIL CAME OUT VENT - BO OTHER AGENCIES - (COASTAL CLEANED UP W/SP)."

All Materials:

Site ID:	79206
Operable Unit ID:	993381
Operable Unit:	01
Material ID:	390532
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AX666 **LONDON TERRACE GARDENS** **NY AST** **A100294864**
NNE **435 WEST 23RD STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.185 mi.
977 ft. **Site 5 of 7 in cluster AX**

Relative:
Higher

Actual:
14 ft.

AST:

Name:	LONDON TERRACE GARDENS
Address:	435 WEST 23RD STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE

LONDON TERRACE GARDENS (Continued) **A100294864**

DEC Region: 2
Site Status: Active
Facility Id: 2-608055
Program Type: PBS
UTM X: 584199.37483
UTM Y: 4511176.87157
Expiration Date: 10/01/2022
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 29907
Affiliation Type: Facility Owner
Company Name: LONDON TERRACE GARDENS % ROSE ASSOC. INC.
Contact Type: PROPERTY MANAGER
Contact Name: MITCH GELBERG
Address1: 200 MADISON AVE., 5TH FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10016
Country Code: 001
Phone: (212) 210-6666
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2012-11-26

Site Id: 29907
Affiliation Type: Mail Contact
Company Name: ROSE ASSOCIATES, INC.
Contact Type: Not reported
Contact Name: COMPLIANCE DEPT.
Address1: 200 MADISON AVE., 5TH FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10016
Country Code: 001
Phone: (212) 210-6762
EMail: APINTO@ROSENYC.COM
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-09-18

Site Id: 29907
Affiliation Type: Facility Operator
Company Name: LONDON TERRACE GARDENS
Contact Type: Not reported
Contact Name: RAY CRAWLEY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 638-7422
EMail: Not reported
Fax Number: Not reported

LONDON TERRACE GARDENS (Continued) **A100294864**

Modified By:	DXLIVING
Date Last Modified:	2007-06-27
Site Id:	29907
Affiliation Type:	Emergency Contact
Company Name:	LONDON TERRACE GARDENS % ROSE ASSOC. INC.
Contact Type:	Not reported
Contact Name:	ELLEN BORNET
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 243-7000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2007-06-27

Tank Info:

Tank Number:	1
Tank Id:	64258
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
I05 - Overfill - Vent Whistle
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
L00 - Piping Leak Detection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
E01 - Piping Secondary Containment - Diking (AG only)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/04/1999
Capacity Gallons:	9500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	09/18/2017
Material Name:	#2 fuel oil (on-site consumption)

AR667 **CON EDISON** **NY MANIFEST** **S113495216**
SSW **F/O 19 9TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.186 mi.
980 ft. **Site 2 of 14 in cluster AR**

Relative:
Higher

Actual:
14 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	F/O 19 9TH AVE
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004289161
Facility Status:	Not reported
Location Address 1:	F/O 19 9TH AVE
Code:	BP
Location Address 2:	SERV BOX 39616
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004289161
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/14/2013
Trans1 Recv Date:	02/14/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/15/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004289161
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010841370JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S113495216**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AR668 **CON EDISON SERVICE BOX: 39616** **RCRA NonGen / NLR** **1016150244**
SSW **19 9TH AVE FRONT OF** **FINDS** **NYP004289153**
1/8-1/4 **NEW YORK, NY 10014** **ECHO**
0.186 mi.
980 ft. **Site 3 of 14 in cluster AR**

Relative: **Higher**
Actual: **14 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20170728
Handler Name:	CON EDISON SERVICE BOX:	39616
Handler Address:		19 9TH AVE FRONT OF
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004289153
Contact Name:		RICARDO CARTY
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		646-772-3407
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported

CON EDISON SERVICE BOX: 39616 (Continued) **1016150244**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180208
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

CON EDISON SERVICE BOX: 39616 (Continued) **1016150244**

Historic Generators:

Receive Date:		20130214
Handler Name:	CON EDISON SERVICE BOX:	39616
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20170728
Handler Name:	CON EDISON SERVICE BOX:	39616
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		No
Electronic Manifest Broker:		No

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID:	110055460816

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016150244
Registry ID:	110055460816

CON EDISON SERVICE BOX: 39616 (Continued) **1016150244**

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055460816
Name: CON EDISON SERVICE BOX: 39616
Address: 19 9TH AVE FRONT OF
City,State,Zip: NEW YORK, NY 10014

AO669 **GERMAN EV LUTHERAN CHURCH OF ST. PAUL** **NY AST** **U003388167**
ENE **315 WEST 22ND STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.186 mi.
981 ft. **Site 5 of 12 in cluster AO**

Relative:
Higher

Actual:
20 ft.

AST:
Name: GERMAN EV LUTHERAN CHURCH OF ST. PAUL
Address: 315 WEST 22ND STREET
City,State,Zip: NEW YORK, NY 10011
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-258334
Program Type: PBS
UTM X: 584450.34446
UTM Y: 4510938.87105
Expiration Date: 07/10/2022
Site Type: Religious Building (Church, Synagogue, Mosque, Temple, etc.)

Affiliation Records:
Site Id: 10695
Affiliation Type: Facility Owner
Company Name: GERMAN EV. LUTHERAN CHURCH OF ST PAUL
Contact Type: ADMINISTRATOR
Contact Name: SANDRA MESONEIC
Address1: 315 WEST 22ND ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10011
Country Code: 001
Phone: (212) 929-1955
EMail: Not reported
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-08-10

Site Id: 10695
Affiliation Type: Mail Contact
Company Name: GERMAN EV. LUTHERAN CHURCH
Contact Type: Not reported
Contact Name: PASTOR
Address1: OF ST. PAUL
Address2: P.O. BOX 1971
City: NEW YORK
State: NY
Zip Code: 10113-1971
Country Code: 001
Phone: (212) 929-1955
EMail: STPAUL@STPAULNY.ORG
Fax Number: Not reported
Modified By: KXTANG

GERMAN EV LUTHERAN CHURCH OF ST. PAUL (Continued) **U003388167**

Date Last Modified: 2007-04-06

Site Id: 10695
Affiliation Type: Facility Operator
Company Name: GERMAN EV LUTHERAN CHURCH OF ST. PAUL
Contact Type: Not reported
Contact Name: PASTOR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 929-1955
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2005-10-13

Site Id: 10695
Affiliation Type: Emergency Contact
Company Name: GERMAN EV. LUTHERAN CHURCH OF ST PAUL
Contact Type: Not reported
Contact Name: PASTOR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 929-1955
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2005-10-13

Tank Info:

Tank Number: 001
Tank Id: 13291
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G10 - Tank Secondary Containment - Impervious Underlayment
B05 - Tank External Protection - Jacketed

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.

GERMAN EV LUTHERAN CHURCH OF ST. PAUL (Continued) **U003388167**

Tank Type:	Steel Tank in Concrete
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/01/1948
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AX670 **LONDON TERRACE GARDENS** **NY UST** **U000405442**
NNE **415-55 WEST 23RD STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.186 mi.
981 ft. **Site 6 of 7 in cluster AX**

Relative: **Higher**

Actual: **15 ft.**

UST:

Name:	LONDON TERRACE GARDENS
Address:	415-55 WEST 23RD STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-364819 / Inactive
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584266.65459
UTM Y:	4511127.27256
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	18505
Affiliation Type:	Facility Owner
Company Name:	LONDON TERRACE GARDENS
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	435 WEST 23RD STREET
Address2:	Not reported
City:	NEW YORK CITY
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 243-7000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	18505
Affiliation Type:	Mail Contact
Company Name:	LONDON TERRACE GARDENS
Contact Type:	Not reported
Contact Name:	ANDREW HOFFMAN
Address1:	435 WEST 23RD STREET
Address2:	Not reported

LONDON TERRACE GARDENS (Continued) **U000405442**

City: NEW YORK CITY
State: NY
Zip Code: 10011
Country Code: 001
Phone: (212) 243-7000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 18505
Affiliation Type: Facility Operator
Company Name: LONDON TERRACE GARDENS
Contact Type: Not reported
Contact Name: ANDREW HOFFMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 243-7000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 18505
Affiliation Type: Emergency Contact
Company Name: LONDON TERRACE GARDENS
Contact Type: Not reported
Contact Name: GEORGE MONDRAGON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 633-9860
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank ID: 22642
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 10000
Install Date: 12/01/1929
Date Tank Closed: 06/06/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0003

LONDON TERRACE GARDENS (Continued) **U000405442**

Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)

Tank Number: 002
Tank ID: 22643
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 10000
Install Date: 12/01/1929
Date Tank Closed: 06/06/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)

AO671 **CON EDISON SERVICE BOX: 9172** **RCRA NonGen / NLR** **1016143213**
NE **352 W 23RD ST** **FINDS** **NYP004259495**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.186 mi. **NY MANIFEST**
983 ft. **Site 6 of 12 in cluster AO**

Relative: **Higher**
Actual: **19 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20170728
Handler Name:	CON EDISON SERVICE BOX:	9172
Handler Address:		352 W 23RD ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004259495
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 9172 (Continued) **1016143213**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170905
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20120722
Handler Name: CON EDISON SERVICE BOX:	9172
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20170728
Handler Name: CON EDISON SERVICE BOX:	9172
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 9172 (Continued) **1016143213**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055426702

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016143213
Registry ID:	110055426702
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055426702
Name:	CON EDISON SERVICE BOX: 9172
Address:	352 W 23RD ST
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	CONSOLIDATED EDISON OF NY
Address:	352 W 23RD ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004259495
Facility Status:	Not reported
Location Address 1:	352 W 23RD ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004259495
Mailing Name:	CONSOLIDATED EDISON OF NY
Mailing Contact:	TOM TEELING

CON EDISON SERVICE BOX: 9172 (Continued) **1016143213**

Mailing Address 1:	4 IRVING PLACE FLOOR 15
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/2012
Trans1 Recv Date:	07/22/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004259495
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	009209920JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AO672 **CON EDISON SERVICE BOX: 9172** **NJ MANIFEST** **S117985513**
NE **352 W 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.186 mi.
983 ft. **Site 7 of 12 in cluster AO**

Relative:
Higher

Actual:
19 ft.

NJ MANIFEST:

EPA Id:	NYP004259495
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JUAN RODRIGUEZ
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	009209920JJK
EPA ID:	NYP004259495
Date Shipped:	7/22/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON SERVICE BOX: 9172 (Continued) **S117985513**

Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: Not reported
Quantity: 500.00 Pounds

AZ673 **ALLERTON HOTEL** **NY AST** **U003387091**
ENE **302 WEST 22ND STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.186 mi.
983 ft. **Site 1 of 21 in cluster AZ**

Relative:
Higher

Actual:
20 ft.

AST:
Name: ALLERTON HOTEL
Address: 302 WEST 22ND STREET
City,State,Zip: NEW YORK, NY 10011
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-091642
Program Type: PBS
UTM X: 584499.32044
UTM Y: 4510892.05306
Expiration Date: N/A
Site Type: Other

Affiliation Records:
Site Id: 2312
Affiliation Type: Facility Owner
Company Name: 300 WEST 22 REALTY, LLC
Contact Type: MANAGING MEMBER
Contact Name: TODD COHEN
Address1: 433 WEST 14TH STREET (429-3R)
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10011
Country Code: 001
Phone: (212) 661-2700
EMail: Not reported
Fax Number: Not reported
Modified By: msbaptis
Date Last Modified: 2007-06-25

Site Id: 2312
Affiliation Type: Mail Contact
Company Name: 300 WEST 22 REALTY, LLC
Contact Type: Not reported
Contact Name: TODD COHEN
Address1: 433 WEST 14TH STREET

ALLERTON HOTEL (Continued) **U003387091**

Address2:	SUITE 429-3R
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 661-2700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2007-06-25

Site Id:	2312
Affiliation Type:	Facility Operator
Company Name:	ALLERTON HOTEL
Contact Type:	Not reported
Contact Name:	TODD COHEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 661-2700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2007-06-25

Site Id:	2312
Affiliation Type:	Emergency Contact
Company Name:	LAWRENCE MEINWALD
Contact Type:	Not reported
Contact Name:	VIJAX FUEL CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 497-4491
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	11251
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G01 - Tank Secondary Containment - Diking (Aboveground)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

ALLERTON HOTEL (Continued) **U003387091**

K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	10/01/1988
Capacity Gallons:	4020
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/18/2007
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

BA674 **GULF SERVICE STA** **NY UST** **U001839074**
North **500 W 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.186 mi.
984 ft. **Site 1 of 16 in cluster BA**

Relative: **Lower**
Actual: **11 ft.**

UST:

Name:	GULF SERVICE STA
Address:	500 W 23RD ST
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-336939 / Inactive
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584036.53311
UTM Y:	4511224.47845
Site Type:	Unknown

Affiliation Records:

Site Id:	16131
Affiliation Type:	Facility Operator
Company Name:	GULF SERVICE STA
Contact Type:	Not reported
Contact Name:	EARL MURRAY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 924-1260

GULF SERVICE STA (Continued) **U001839074**

EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 16131
Affiliation Type: Emergency Contact
Company Name: CUMBERLAND FARMS INC
Contact Type: Not reported
Contact Name: EARL MURRAY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 860-0656
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 16131
Affiliation Type: Facility Owner
Company Name: CUMBERLAND FARMS, INC.
Contact Type: Not reported
Contact Name: Not reported
Address1: 777 DEDHAM STREET
Address2: Not reported
City: CANTON
State: MA
Zip Code: 02021
Country Code: 001
Phone: (617) 828-4912
EMail: Not reported
Fax Number: Not reported
Modified By: wlsteven
Date Last Modified: 2008-02-11

Site Id: 16131
Affiliation Type: Mail Contact
Company Name: CUMBERLAND FARMS, INC.
Contact Type: Not reported
Contact Name: Not reported
Address1: 777 DEDHAM STREET
Address2: Not reported
City: CANTON
State: MA
Zip Code: 02021
Country Code: 001
Phone: (617) 828-4912
EMail: Not reported
Fax Number: Not reported
Modified By: wlsteven
Date Last Modified: 2008-02-11

GULF SERVICE STA (Continued) **U001839074**

Tank Info:

Tank Number:	001
Tank ID:	28565
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	04/01/1971
Date Tank Closed:	12/01/1989
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
J02 - Dispenser - Suction Dispenser

Tank Number:	002
Tank ID:	28566
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	04/01/1971
Date Tank Closed:	12/01/1989
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

GULF SERVICE STA (Continued) **U001839074**

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None

Tank Number: 003
Tank ID: 28567
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 10/01/1978
Date Tank Closed: 12/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None

Tank Number: 004
Tank ID: 28568
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 10/01/1978
Date Tank Closed: 12/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT

GULF SERVICE STA (Continued) **U001839074**

Last Modified: 04/14/2017

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
J02 - Dispenser - Suction Dispenser

Tank Number: 005
Tank ID: 28569
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 550
Install Date: 04/01/1964
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

BA675 **CVS PHARMACY #10041** **RCRA-VSQG** **1015754402**
North **500 W 23RD ST** **NY MANIFEST** **NYR000198234**
1/8-1/4 **NEW YORK, NY 10010**
0.186 mi.
984 ft. **Site 2 of 16 in cluster BA**

Relative: RCRA-VSQG:
Lower
Date Form Received by Agency: 20190408
Actual: Handler Name: CVS PHARMACY #10041
11 ft. Handler Address: 500 W 23RD ST
Handler City,State,Zip: NEW YORK, NY 10010
EPA ID: NYR000198234
Contact Name: NICOLE WILKINSON
Contact Address: CVS DR MC2340
Contact City,State,Zip: WOONSOCKET, RI 02895

CVS PHARMACY #10041 (Continued) **1015754402**

Contact Telephone:	401-770-7132
Contact Fax:	315-454-4467
Contact Email:	NICOLE.WILKINSON@CVSHEALTH.COM
Contact Title:	DIRECTOR, CORPORATE ENVIRONMENTAL
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	CVS DR MC2340
Mailing City,State,Zip:	WOONSOCKET, RI 02895
Owner Name:	EQUITY RESIDENTIAL MGMT LLC
Owner Type:	Private
Operator Name:	CVS ALBANY LLC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CVS PHARMACY #10041 (Continued) **1015754402**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20190628
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D002
Waste Description: CORROSIVE WASTE

Waste Code: D004
Waste Description: ARSENIC

Waste Code: D005
Waste Description: BARIUM

Waste Code: D006
Waste Description: CADMIUM

Waste Code: D007
Waste Description: CHROMIUM

Waste Code: D008
Waste Description: LEAD

Waste Code: D009
Waste Description: MERCURY

Waste Code: D010
Waste Description: SELENIUM

Waste Code: D011
Waste Description: SILVER

CVS PHARMACY #10041 (Continued) **1015754402**

Waste Code: D016
Waste Description: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Waste Code: D018
Waste Description: BENZENE

Waste Code: D024
Waste Description: M-CRESOL

Waste Code: D027
Waste Description: 1,4-DICHLOROBENZENE

Waste Code: D035
Waste Description: METHYL ETHYL KETONE

Waste Code: D039
Waste Description: TETRACHLOROETHYLENE

Waste Code: P001
Waste Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Waste Code: P012
Waste Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Waste Code: P042
Waste Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Waste Code: P075
Waste Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Waste Code: P081
Waste Description: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

Waste Code: P188
Waste Description: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

Waste Code: U002
Waste Description: 2-PROPANONE (I) (OR) ACETONE (I)

Waste Code: U010
Waste Description: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

Waste Code: U031
Waste Description: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Waste Code: U034
Waste Description: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

CVS PHARMACY #10041 (Continued) **1015754402**

Waste Code: U035
Waste Description: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

Waste Code: U044
Waste Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Waste Code: U058
Waste Description: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

Waste Code: U059
Waste Description: 5,12-NAPHTHACENEDIONE, 8-ACETYL-10-[(3-AMINO-2,3,6-TRIDEOXY)-ALPHA-L-LYXO-HEXOPYRANOSYL)OXY]-7,8,9,10-TETRAHYDRO-6,8,11-TRIHYDROXY-1-METHOXY-, (8S-CIS)- (OR) DAUNOMYCIN

Waste Code: U070
Waste Description: BENZENE, 1,2-DICHLORO- (OR) O-DICHLOROBENZENE

Waste Code: U072
Waste Description: BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE

Waste Code: U089
Waste Description: DIETHYLSTILBESTEROL (OR) PHENOL, 4,4'-(1,2-DIETHYL-1,2-ETHENEDIYL)BIS, (E)-

Waste Code: U122
Waste Description: FORMALDEHYDE

Waste Code: U129
Waste Description: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

Waste Code: U132
Waste Description: HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-

Waste Code: U150
Waste Description: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

Waste Code: U151
Waste Description: MERCURY

Waste Code: U154
Waste Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Waste Code: U165
Waste Description: NAPHTHALENE

Waste Code: U188
Waste Description: PHENOL

Waste Code: U200
Waste Description: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL)OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

Waste Code: U201

CVS PHARMACY #10041 (Continued) **1015754402**

Waste Description: 1,3-BENZENEDIOL (OR) RESORCINOL

Waste Code: U204
Waste Description: SELENIOUS ACID (OR) SELENIUM DIOXIDE

Waste Code: U205
Waste Description: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

Waste Code: U206
Waste Description: D-GLUCOSE, 2-DEOXY-2-[[(METHYLNITROSOAMINO)-CARBONYL]AMINO]- (OR) GLUCOPYRANOSE, 2-DEOXY-2-(3-METHYL-3-NITROSOUREIDO)-,D- (OR) STREPTOZOTOCIN

Waste Code: U210
Waste Description: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

Waste Code: U279
Waste Description: U279

Waste Code: U411
Waste Description: U411

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CVS ALBANY LLC
Legal Status:	Private
Date Became Current:	20121125
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	EQUITY RESIDENTIAL MGMT LLC
Legal Status:	Private
Date Became Current:	20120504
Date Ended Current:	Not reported
Owner/Operator Address:	5 LONGFELLOW PL
Owner/Operator City,State,Zip:	BOSTON, MA 02114
Owner/Operator Telephone:	617-973-2222
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CVS ALBANY LLC
Legal Status:	Private
Date Became Current:	20121125
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

CVS PHARMACY #10041 (Continued) **1015754402**

Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	EQUITY RESIDENTIAL MANAGEMENT LLC
Legal Status:	Private
Date Became Current:	20120504
Date Ended Current:	Not reported
Owner/Operator Address:	4 LONGFELLOW PL
Owner/Operator City,State,Zip:	BOSTON, MA 02114
Owner/Operator Telephone:	617-973-2222
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	CVS ALBANY LLC
Legal Status:	Private
Date Became Current:	20121125
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	CVS ALBANY LLC
Legal Status:	Private
Date Became Current:	20121125
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	EQUITY RESIDENTIAL MANAGEMENT LLC
Legal Status:	Private
Date Became Current:	20120504
Date Ended Current:	Not reported
Owner/Operator Address:	5 LONGFELLOW PL
Owner/Operator City,State,Zip:	BOSTON, MA 02114
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	EQUITY RESIDENTIAL MANAGEMENT LLC
Legal Status:	Private
Date Became Current:	20120504
Date Ended Current:	Not reported
Owner/Operator Address:	5 LONGFELLOW PL
Owner/Operator City,State,Zip:	BOSTON, MA 02114

CVS PHARMACY #10041 (Continued) **1015754402**

Owner/Operator Telephone: 617-973-2222
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CVS ALBANY LLC
Legal Status: Private
Date Became Current: 20121125
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: EQUITY RESIDENTIAL MGMT LLC
Legal Status: Private
Date Became Current: 20120504
Date Ended Current: Not reported
Owner/Operator Address: 5 LONGFELLOW PL
Owner/Operator City,State,Zip: BOSTON, MA 02114
Owner/Operator Telephone: 617-973-2222
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20160318
Handler Name: CVS PHARMACY #10041
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20180125
Handler Name: CVS PHARMACY #10041
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20121227

CVS PHARMACY #10041 (Continued) **1015754402**

Handler Name: CVS PHARMACY #10041
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150213
Handler Name: CVS PHARMACY #10041
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20190408
Handler Name: CVS PHARMACY #10041
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 44611
NAICS Description: PHARMACIES AND DRUG STORES

NAICS Code: 446110
NAICS Description: PHARMACIES AND DRUG STORES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CVS PHARMACY #10041
Address: 500 W 23RD ST

CVS PHARMACY #10041 (Continued) **1015754402**

City,State,Zip: NEW YORK, NY 10010
Country: USA
EPA ID: NYR000198234
Facility Status: Not reported
Location Address 1: 500 W 23RD ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10010
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000198234
Mailing Name: CVS PHARMACY #10041
Mailing Contact: CVS PHARMACY #10041
Mailing Address 1: 500 W 23RD ST
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10010
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: PAD982661381
Trans2 State ID: Not reported
Generator Ship Date: 12/19/2017
Trans1 Recv Date: 12/19/2017
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/29/2017
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000198234
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: RID040098352
TSDF ID 2: Not reported
Manifest Tracking Number: 011309938FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported

CVS PHARMACY #10041 (Continued) **1015754402**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	17
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	D007
Waste Code 1_3:	D010
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BA676 **CVS # 10041** **PA MANIFEST** **S118068841**
North **500 W 23RD ST** **N/A**
1/8-1/4 **MANHATTAN, NY 10011**
0.186 mi.
984 ft. **Site 3 of 16 in cluster BA**

Relative: **Lower**

Actual: **11 ft.**

Manifest Details:

Year:	2018
Manifest Number:	011451546FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000198234
Generator Date:	06/12/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	4
Waste Number:	R015
Container Number:	1
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	24
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2018
Manifest Number:	011451546FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000198234
Generator Date:	06/12/2018

CVS # 10041 (Continued) **S118068841**

Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D010
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	3
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2018
Manifest Number:	011451546FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000198234
Generator Date:	06/12/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	16
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2018
Manifest Number:	011451546FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000198234
Generator Date:	06/12/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported

CVS # 10041 (Continued) **S118068841**

Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	P001
Container Number:	1
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2018
Manifest Number:	011451546FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000198234
Generator Date:	06/12/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D007
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	3
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	006299662FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000198234
Generator Date:	03/10/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported

CVS # 10041 (Continued) **S118068841**

TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	2
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	34
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	006299662FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000198234
Generator Date:	03/10/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	U002
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	15
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	006299662FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000198234
Generator Date:	03/10/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield

CVS # 10041 (Continued) **S118068841**

TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	D001
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	15
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	006299662FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000198234
Generator Date:	03/10/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D002
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	21
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2014
Manifest Number:	007299930FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000198234
Generator Date:	12/18/2014
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1

CVS # 10041 (Continued) **S118068841**

Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	6
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional PA_MANIFEST: record(s) in the EDR Site Report.

AS677 **BELL ATLANTIC-NY** **RCRA NonGen / NLR** **1007205555**
WSW **10 AVE & 13TH ST** **NY MANIFEST** **NYP000935692**
1/8-1/4 **NEW YORK, NY 10001**
0.187 mi.
986 ft. **Site 9 of 11 in cluster AS**

Relative: **Lower**
Actual: **6 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		19980301
Handler Name:	BELL ATLANTIC-NY	
Handler Address:		10 AVE & 13TH ST
Handler City,State,Zip:		NEW YORK, NY 10001
EPA ID:		NYP000935692
Contact Name:		JOHN QUATRALE
Contact Address:		E 37TH ST 4TH FL
Contact City,State,Zip:		NEW YORK, NY 10016-0000
Contact Telephone:		212-338-7141
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		E 37TH ST 4TH FL
Mailing City,State,Zip:		NEW YORK, NY 10016-0000
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No

BELL ATLANTIC-NY (Continued) **1007205555**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211207
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19980228
Handler Name: BELL ATLANTIC-NY	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

BELL ATLANTIC-NY (Continued) **1007205555**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980301
Handler Name: BELL ATLANTIC-NY
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19980227
Handler Name: BELL ATLANTIC-NY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 5133
NAICS Description: TELECOMMUNICATIONS

NAICS Code: 51331
NAICS Description: WIRED TELECOMMUNICATIONS CARRIERS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: BELL ATLANTIC-NY
Address: 10 AVE/13 ST
City,State,Zip: MANHATTAN, NY 00000-0000
Country: USA
EPA ID: NYP000935692
Facility Status: Not reported
Location Address 1: 10 AVE/13 ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK

BELL ATLANTIC-NY (Continued) **1007205555**

Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP000935692
Mailing Name: BELL ATLANTIC-NY
Mailing Contact: Not reported
Mailing Address 1: Not reported
Mailing Address 2: Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Mailing Zip 4: Not reported
Mailing Country: Not reported
Mailing Phone: Not reported

AY678 **BAYVIEW CORRECTIONAL FACILITY** **RCRA-VSQG** **1007112519**
NW **550 W 20TH ST** **NY SHWS** **NYR000117242**
1/8-1/4 **NEW YORK, NY 10011** **NY MANIFEST**
0.187 mi.
987 ft. **Site 2 of 11 in cluster AY**

Relative: **Lower**
Actual: **7 ft.**

RCRA-VSQG:
Date Form Received by Agency: 20090921
Handler Name: BAYVIEW CORRECTIONAL FACILITY
Handler Address: 550 W 20TH ST
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYR000117242
Contact Name: ANTONIO VASQUEZ
Contact Address: W 20TH ST
Contact City,State,Zip: NEW YORK, NY 10011
Contact Telephone: 212-255-7590 3972
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: State
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: NY
State District: NYSDEC R2
Mailing Address: W 20TH ST
Mailing City,State,Zip: NEW YORK, NY 10011
Owner Name: NYS DEPT OF CORRECTIONAL FACILITIES
Owner Type: State
Operator Name: ABATEK CORP
Operator Type: Private
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No
Recycler Activity with Storage: No

BAYVIEW CORRECTIONAL FACILITY (Continued) **1007112519**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

BAYVIEW CORRECTIONAL FACILITY (Continued) **1007112519**

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NEW YORK STATE DOCES
Legal Status:	State
Date Became Current:	19740912
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYC DEPT OF CORRECTIONS
Legal Status:	Municipal
Date Became Current:	19740912
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	NY
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYC DEPT OF CORRECTIONS
Legal Status:	Municipal
Date Became Current:	19740912
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	NY
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYS DEPT OF CORRECTIONAL SERVICES
Legal Status:	State
Date Became Current:	19740101
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	NY 12226
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ABATEK CORP
Legal Status:	Private
Date Became Current:	20090226
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported

BAYVIEW CORRECTIONAL FACILITY (Continued) **1007112519**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NEW YORK STATE DOCES
Legal Status: State
Date Became Current: 19740912
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, NY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYS DEPT OF CORRECTIONAL FACILITIES
Legal Status: State
Date Became Current: 19740912
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYS DEPT OF CORRECTIONAL SERVICES
Legal Status: State
Date Became Current: 19740101
Date Ended Current: Not reported
Owner/Operator Address: 1220 WASHINGTON AVE
Owner/Operator City,State,Zip: ALBANY, NY 12226
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYCDOC - BAYVIEW CORRECTIONAL FACILITY
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20071028
Handler Name: BAYVIEW CORRECTIONAL FACILITY
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY

BAYVIEW CORRECTIONAL FACILITY (Continued) **1007112519**

Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20030721
Handler Name: NYSDOCS - BAYVIEW CORRECTIONAL FACILITY
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040504
Handler Name: NYCDOC - BAYVIEW CORRECTIONAL FACILITY
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20071029
Handler Name: BAYVIEW CORRECTIONAL FACILITY
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090921
Handler Name: BAYVIEW CORRECTIONAL FACILITY
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

BAYVIEW CORRECTIONAL FACILITY (Continued) **1007112519**

Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 92214
NAICS Description: CORRECTIONAL INSTITUTIONS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

SHWS:
Name: BAYVIEW PROPERTY
Address: 550 WEST 20TH STREET
City,State,Zip: NEW YORK, NY 10011
Program: HW
Site Code: 582178
Classification: A
Region: 2
Acres: 0.363
HW Code: 231132
Record Add: 02/07/2019
Record Upd: 06/07/2021
Updated By: DJEATON
Site Description: "This site is a portion of site 231005 and previously referred to as V00530. Location: The 0.4 acre site is the northwestern part of a larger, historic manufactured gas plant (MGP) operation which once encompassed portions of five city blocks along the western side of Manhattan, New York City. Remediation has already been accomplished at several other portions of the larger site. The descriptions of the other sections can be found under the listings for the sites noted above. This site is bounded by the West Side Highway (NY Route 9A) on the west, and West 18th and 19th Streets to the south and north, respectively. To the east, the rest of the block is made up mixed use commercial properties. Site Features: The site is almost flat, with a slight slope to the west, toward the Hudson River. Most recently, the site housed the Bayview Prison facility for women, which was closed following major flood damage from Tropical Storm Sandy in 2013. The entire site is covered with buildings or pavement. Current Zoning and Land Use: The former prison building and a building annex remain vacant on the site. Current site zoning is C6-3, for commercial purposes. The site is included in the Special West Chelsea District, a 14-square block area established in 2005 to allow mixed commercial and residential development, and to promote development around the adjacent High Line city park. Adjacent properties to the east are being redeveloped for residential and commercial uses. Past Use of the Site: The West 18th Street Gas Works began operations in 1834 and continued to expand through most of the 1800s, but was closed in the early 1900s. Manufactured gas was produced by heating coal in a closed vessel, collecting the gas and purifying it, and then delivering it through underground networks of pipes into the

BAYVIEW CORRECTIONAL FACILITY (Continued) **1007112519**

surrounding area. The gas was used in homes and businesses for heating, lighting, and cooking in much the same way that natural gas is used today. Operable Unit 5 contained two gas holders during the period when the MGP was active. The gas manufacturing process produced a byproduct consisting of a black, oily liquid waste known as coal tar. This tar escaped from underground storage tanks and pipes into surrounding subsurface soils. The tar is resistant to decay and is commonly found in soils at former MGP sites decades after operations ceased. Most of the tar contamination found at the West 18th Street MGP was found on neighboring properties, which have already been remediated or are in the process of being remediated. Relatively minor impacts have been detected on Operable Unit 5. Following closure of the MGP, the gas manufacturing facility was torn down and the site was subdivided and sold to a number of different owners. Subsurface structures such as building foundations and subsurface piping, however, were often not removed and remain in place today. A variety of commercial and industrial operations developed throughout the former MGP site in the middle and late 1900s. Based on investigation work conducted to date, it appears that gas holder foundations still exist beneath the site. Site Geology and Hydrogeology: Between 50 and 80 feet of unconsolidated materials overlie Cambrian Hartland Formation bedrock. The unconsolidated units are divided in to three distinct stratigraphic units. From the surface down, the units consist of a fill unit (highly heterogeneous, generally highly permeable) a silty-clay unit (a low-permeability aquitard consisting of tidal marsh deposits), and a sand unit (highly permeable stratified alluvial sands). "

Env Problem: "Nature and Extent of Contamination: Sampling at the site was limited due to the presence of buildings that did not permit extensive sampling. Based on the limited sampling to date, which included analysis for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), and metals, no significant contamination has been detected on this operable unit. There is a possibility that some source material may be present within the holder structure under the former prison building, however, there is no evidence that source material is migrating from the operable unit. The soil samples collected on this site contained SVOCs and metal contamination; the highest concentration of total SVOCs is 610 parts per million (ppm). Concentrations of mercury exceed the restricted residential SCOs, with a maximum concentration of 1.9 ppm. Groundwater collected north of this operable unit met ambient water quality standards, and the groundwater south of the adjacent operable unit (south of the site) contained minor contamination of SVOCs, with only naphthalene exceeding its groundwater standards at a concentration of 11 parts per billion. Soil vapor and indoor air sampling have not indicated the potential for soil vapor exposure. "

Health Problem: "As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns."

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported

BAYVIEW CORRECTIONAL FACILITY (Continued) **1007112519**

Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	231005
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2019-03-25 11:03:00
Record Updated:	2019-03-25 11:15:00
Updated By:	DKMACNEA

NY MANIFEST:

Name:	BAYVIEW CORRECTIONAL
Address:	550 W 20TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYR000117242
Facility Status:	Not reported
Location Address 1:	550 WEST 20TH STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000117242
Mailing Name:	BAYVIEW CORRECTIONAL
Mailing Contact:	GLENN T
Mailing Address 1:	550 WEST 20TH STREET
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183490900

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018

BAYVIEW CORRECTIONAL FACILITY (Continued) **1007112519**

Trans1 State ID:	NJD054126164
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/2009
Trans1 Recv Date:	10/22/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/17/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000117242
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported
Manifest Tracking Number:	006325555JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	250
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D006
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AY679 **BAYVIEW CORRECTIONAL FACILITY** **NY UST** **1007805093**
NW **550 WEST 20TH ST** **NY AST** **N/A**
1/8-1/4 **NEW YORK, NY 10011** **FINDS**
0.187 mi. **ECHO**
987 ft. **Site 3 of 11 in cluster AY**

Relative: UST:
Lower

Actual: Name:	BAYVIEW CORRECTIONAL FACILITY
7 ft. Address:	550 WEST 20TH STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-399515 / Unregulated/Closed
Program Type:	PBS
Region:	STATE

BAYVIEW CORRECTIONAL FACILITY (Continued) **1007805093**

DEC Region: 2
Expiration Date: N/A
UTM X: 583795.06834
UTM Y: 4511092.76851
Site Type: Other

Affiliation Records:

Site Id: 19029
Affiliation Type: Facility Owner
Company Name: NYS DOCCS
Contact Type: Not reported
Contact Name: Not reported
Address1: 1220 WASHINGTON AVE
Address2: Not reported
City: ALBANY
State: NY
Zip Code: 12226
Country Code: 001
Phone: (518) 485-5576
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2015-10-27

Site Id: 19029
Affiliation Type: Facility Operator
Company Name: BAYVIEW CORRECTIONAL FACILITY
Contact Type: Not reported
Contact Name: ANTONIO VAZQUEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 255-7590
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2013-11-20

Site Id: 19029
Affiliation Type: Emergency Contact
Company Name: NYS DOCCS
Contact Type: Not reported
Contact Name: ERIC GREPPO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (518) 473-3582
EMail: Not reported
Fax Number: Not reported
Modified By: BHYUKOWE
Date Last Modified: 2013-12-06

BAYVIEW CORRECTIONAL FACILITY (Continued) **1007805093**

Site Id:	19029
Affiliation Type:	Mail Contact
Company Name:	DOCCS - FACILITIES PLANNING & DEVELOPMENT
Contact Type:	Not reported
Contact Name:	DIRECTOR OF FACILITIES PLANNING
Address1:	1220 WASHINGTON AVENUE
Address2:	Not reported
City:	ALBANY
State:	NY
Zip Code:	12226
Country Code:	001
Phone:	(518) 473-3582
EMail:	ERIC.GREPPO@DOCCS.NY.GOV
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-03-13

Tank Info:

Tank Number:	001
Tank ID:	21633
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	7500
Install Date:	12/24/1930
Date Tank Closed:	08/15/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	11/14/2011
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
A01 - Tank Internal Protection - Epoxy Liner
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

AST:

Name:	BAYVIEW CORRECTIONAL FACILITY
Address:	550 WEST 20TH STREET
City,State,Zip:	NEW YORK, NY 10011

BAYVIEW CORRECTIONAL FACILITY (Continued) **1007805093**

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-399515
Program Type:	PBS
UTM X:	583795.06834
UTM Y:	4511092.76851
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	19029
Affiliation Type:	Facility Owner
Company Name:	NYS DOCCS
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1220 WASHINGTON AVE
Address2:	Not reported
City:	ALBANY
State:	NY
Zip Code:	12226
Country Code:	001
Phone:	(518) 485-5576
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-10-27

Site Id:	19029
Affiliation Type:	Facility Operator
Company Name:	BAYVIEW CORRECTIONAL FACILITY
Contact Type:	Not reported
Contact Name:	ANTONIO VAZQUEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 255-7590
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2013-11-20

Site Id:	19029
Affiliation Type:	Emergency Contact
Company Name:	NYS DOCCS
Contact Type:	Not reported
Contact Name:	ERIC GREPPO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(518) 473-3582
EMail:	Not reported

BAYVIEW CORRECTIONAL FACILITY (Continued) **1007805093**

Fax Number:	Not reported
Modified By:	BHYUKOWE
Date Last Modified:	2013-12-06
Site Id:	19029
Affiliation Type:	Mail Contact
Company Name:	DOCCS - FACILITIES PLANNING & DEVELOPMENT
Contact Type:	Not reported
Contact Name:	DIRECTOR OF FACILITIES PLANNING
Address1:	1220 WASHINGTON AVENUE
Address2:	Not reported
City:	ALBANY
State:	NY
Zip Code:	12226
Country Code:	001
Phone:	(518) 473-3582
EMail:	ERIC.GREPPO@DOCCS.NY.GOV
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-03-13

Tank Info:

Tank Number:	002
Tank Id:	21634
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	B00 - Tank External Protection - None
	J02 - Dispenser - Suction Dispenser
	K00 - Spill Prevention - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	A00 - Tank Internal Protection - None
	L00 - Piping Leak Detection - None
	E00 - Piping Secondary Containment - None
	H00 - Tank Leak Detection - None
	I04 - Overfill - Product Level Gauge (A/G)
	I05 - Overfill - Vent Whistle
	G04 - Tank Secondary Containment - Double-Walled (Underground)
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	08/01/1996
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/08/2013
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

BAYVIEW CORRECTIONAL FACILITY (Continued) **1007805093**

Material Name: diesel

Tank Number: 003
Tank Id: 21635
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 05/01/1996
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 03/08/2013
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: diesel

FINDS:
Registry ID: 110019676224

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

BAYVIEW CORRECTIONAL FACILITY (Continued) **1007805093**

ECHO:
- Envid: 1007805093
- Registry ID: 110019676224
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110019676224
- Name: BAYVIEW CORRECTIONAL FACILITY
- Address: 550 WEST 20TH ST
- City,State,Zip: NEW YORK, NY 10011

BB680 **CONSOLIDATED EDISON** **NY MANIFEST** **S110490970**
SSE **8TH AVE & W 15TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10016**
0.187 mi.
989 ft. **Site 1 of 24 in cluster BB**

Relative:
Higher

Actual:
21 ft.

NY MANIFEST:
- Name: CONSOLIDATED EDISON
- Address: 8TH AVE & W 15TH ST
- City,State,Zip: NEW YORK, NY 10016
- Country: USA
- EPA ID: NYP004208456
- Facility Status: Not reported
- Location Address 1: 8TH AVE & W 15TH ST
- Code: BP
- Location Address 2: Not reported
- Total Tanks: Not reported
- Location City: NEW YORK
- Location State: NY
- Location Zip: Not reported
- Location Zip 4: Not reported

NY MANIFEST:
- EPAID: NYP004208456
- Mailing Name: CONSOLIDATED EDISON
- Mailing Contact: THOMAS TEELING
- Mailing Address 1: 4 IRVING PL RM 828
- Mailing Address 2: Not reported
- Mailing City: NEW YORK
- Mailing State: NY
- Mailing Zip: 10003
- Mailing Zip 4: Not reported
- Mailing Country: USA
- Mailing Phone: 2124603770

NY MANIFEST:
- Document ID: Not reported
- Manifest Status: Not reported
- seq: Not reported
- Year: 2018
- Trans1 State ID: NJ0000027193
- Trans2 State ID: Not reported
- Generator Ship Date: 06/11/2010
- Trans1 Recv Date: 06/11/2010
- Trans2 Recv Date: Not reported
- TSD Site Recv Date: 06/15/2010
- Part A Recv Date: Not reported
- Part B Recv Date: Not reported
- Generator EPA ID: NYP004208456

CONSOLIDATED EDISON (Continued) **S110490970**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	001085277GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BB681 **CONSOLIDATED EDISON** **NY MANIFEST** **1009241320**
SSE **15TH ST & 8TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY**
0.187 mi.
989 ft. **Site 2 of 24 in cluster BB**

Relative: **Higher**
Actual: **21 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	15TH ST & 8TH AVE
City,State,Zip:	NEW YORK, NY
Country:	USA
EPA ID:	NYP004097382
Facility Status:	Not reported
Location Address 1:	15TH ST & 8TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

CONSOLIDATED EDISON (Continued) **1009241320**

NY MANIFEST:

EPAID:	NYP004097382
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

BB682 **15TH ST & 8TH AVE/BKLYN** **NY LTANKS** **S102671425**
SSE **15TH ST / 8TH AVE** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.187 mi.
989 ft. **Site 3 of 24 in cluster BB**

Relative:
Higher

Actual:
21 ft.

LTANKS:

Name:	15TH ST & 8TH AVE/BKLYN
Address:	15TH ST / 8TH AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8905987 / 2004-01-12
Facility ID:	8905987
Site ID:	93820
Spill Date:	1989-09-18
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C2
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	1989-09-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-10-12
Spill Record Last Update:	2004-01-12
Spiller Name:	Not reported
Spiller Company:	NYSOGS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	84058
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 09/18/89: BRIAN CONTRACTING CORP WILL DISPOSE OF 80YDS OF

15TH ST & 8TH AVE/BKLYN (Continued) **S102671425**

Remarks: CONTAMINATED SAND. 1/12/04 - AUSTIN - SURF. SPILL FROM 14 YRS AGO - CLOSED - ORIG. ASSIGNED TO GEORGE JAMES - END "
"BACKFILL CONTAMINATED WITH PRODUCT WHEN TANK WAS PREPARED TO BE REMOVED, TANK ENCLOSED BY CONCRETE VAULT."

All Materials:

Site ID:	93820
Operable Unit ID:	933626
Operable Unit:	01
Material ID:	446381
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

BB683 **CON EDISON** **RCRA NonGen / NLR** **1014398492**
SSE **8TH AVE & W 15TH ST** **NJ MANIFEST** **NYP004208456**
1/8-1/4 **NEW YORK, NY 10016**
0.187 mi.
989 ft. **Site 4 of 24 in cluster BB**

Relative: **Higher**
Actual: **21 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20200413
Handler Name:	CON EDISON	
Handler Address:		8TH AVE & W 15TH ST
Handler City,State,Zip:		NEW YORK, NY 10016
EPA ID:		NYP004208456
Contact Name:		Not reported
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		Not reported
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No

CON EDISON (Continued) **1014398492**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200413
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20100611
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified

CON EDISON (Continued) **1014398492**

State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20200413
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:
EPA Id: NYP004208456
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: HERMAN BAKER
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 001085277GBF
EPA ID: NYP004208456
Date Shipped: 06/11/2010
TSDF EPA ID: NJD002200046

CON EDISON (Continued) **1014398492**

Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/11/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/15/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	50 P

---

684 **INDUSTRIAL ELECTRONIC HDWR** **RCRA NonGen / NLR** **1000428076**
NW **103-11 PRINCE ST** **FINDS** **NYD001367630**
1/8-1/4 **NEW YORK, NY 10012** **ECHO**
0.188 mi.
995 ft.

Relative: **Lower**
Actual: **4 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	INDUSTRIAL ELECTRONIC HDWR
Handler Address:	103-11 PRINCE ST
Handler City,State,Zip:	NEW YORK, NY 10012
EPA ID:	NYD001367630

INDUSTRIAL ELECTRONIC HDWR (Continued) **1000428076**

Contact Name:	FRANK FAZZIO
Contact Address:	PRINCE ST
Contact City,State,Zip:	NEW YORK, NY 10012
Contact Telephone:	212-677-1881
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	PRINCE ST
Mailing City,State,Zip:	NEW YORK, NY 10012
Owner Name:	SEYMOUR OFFERMAN PRESIDENT
Owner Type:	Private
Operator Name:	SEYMOUR OFFERMAN PRESIDENT
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No

INDUSTRIAL ELECTRONIC HDWR (Continued) **1000428076**

Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: F001
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F003
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT

INDUSTRIAL ELECTRONIC HDWR (Continued) **1000428076**

MIXTURES.

Waste Code: P036
Waste Description: ARSONOUS DICHLORIDE, PHENYL- (OR) DICHLOROPHENYLARSINE

Waste Code: U002
Waste Description: 2-PROPANONE (I) (OR) ACETONE (I)

Waste Code: U019
Waste Description: BENZENE (I,T)

Waste Code: U159
Waste Description: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: SEYMOUR OFFERMAN PRESIDENT
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SEYMOUR OFFERMAN PRESIDENT
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SEYMOUR OFFERMAN PRESIDENT
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: INDUSTRIAL ELECTRONIC HDWR
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY

INDUSTRIAL ELECTRONIC HDWR (Continued) **1000428076**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	INDUSTRIAL ELECTRONIC HDWR
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19800818
Handler Name:	INDUSTRIAL ELECTRONIC HDWR
Federal Waste Generator Description:	Not reported
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	334419
NAICS Description:	OTHER ELECTRONIC COMPONENT MANUFACTURING

Facility Has Received Notices of Violation:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported

INDUSTRIAL ELECTRONIC HDWR (Continued) **1000428076**

Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19850109
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

FINDS:
Registry ID: 110004334140

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000428076
Registry ID: 110004334140
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004334140

INDUSTRIAL ELECTRONIC HDWR (Continued) **1000428076**

Name: INDUSTRIAL ELECTRONIC HDWR
Address: 103-11 PRINCE ST
City,State,Zip: NEW YORK, NY 10012

AO685 **CON EDISON** **NY MANIFEST** **S117058705**
NE **363-61 W 23RD ST & 9TH AVE E O** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.188 mi.
995 ft. **Site 8 of 12 in cluster AO**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:
Name: CON EDISON
Address: 363-61 W 23RD ST & 9TH AVE E O
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004508388
Facility Status: Not reported
Location Address 1: 362 W 23 ST & 9 AVE
Code: BP
Location Address 2: SB4208
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004508388
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 04/22/2014
Trans1 Recv Date: 04/22/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/23/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004508388
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002407482GBF

CON EDISON (Continued) **S117058705**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AO686 **CON EDISON** **NY MANIFEST** **S117058704**
NE **363-61 W 23RD ST & 9TH AVE E O** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.188 mi.
995 ft. **Site 9 of 12 in cluster AO**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	363-61 W 23RD ST & 9TH AVE E O
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004508370
Facility Status:	Not reported
Location Address 1:	363 W 23 ST & 9 AV
Code:	BP
Location Address 2:	SB4198
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004508370
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL

CON EDISON (Continued) **S117058704**

Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2014
Trans1 Recv Date:	04/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004508370
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407845GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AT687 **CHELSEA 1 HOUR PHOTO** **RCRA NonGen / NLR** **1000890023**
SE **128 8TH AVE** **FINDS** **NY0000228924**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.189 mi. **NY MANIFEST**
996 ft. **Site 15 of 23 in cluster AT**

Relative: **Higher**
Actual: **21 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	CHELSEA 1 HOUR PHOTO	
Handler Address:		128 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NY0000228924
Contact Name:		MATTHEW HAN
Contact Address:		8TH AVE
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		212-727-2702
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		8TH AVE
Mailing City,State,Zip:		NEW YORK, NY 10011
Owner Name:		WALKER MALLOY & CO
Owner Type:		Private
Operator Name:		WALKER MALLOY & CO
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CHELSEA 1 HOUR PHOTO (Continued) **1000890023**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D011
Waste Description:	SILVER
Waste Code:	X003
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WALKER MALLOY & CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	101 W 70TH ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10023
Owner/Operator Telephone:	212-874-1686
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

CHELSEA 1 HOUR PHOTO (Continued) **1000890023**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WALKER MALLOY & CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 101 W 70TH ST
Owner/Operator City,State,Zip: NEW YORK, NY 10023
Owner/Operator Telephone: 212-874-1686
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WALKER MALLOY & CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 101 W 70TH ST
Owner/Operator City,State,Zip: NEW YORK, NY 10023
Owner/Operator Telephone: 212-874-1686
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: CHELSEA 1 HOUR PHOTO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: CHELSEA 1 HOUR PHOTO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19970606
Handler Name: CHELSEA 1 HOUR PHOTO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY

CHELSEA 1 HOUR PHOTO (Continued) **1000890023**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004314091

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000890023
Registry ID:	110004314091
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004314091
Name:	CHELSEA 1 HOUR PHOTO
Address:	128 8TH AVE
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	CHELSEA 1 HOUR PHOTO CENTER
Address:	128 8TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NY0000228924
Facility Status:	Not reported
Location Address 1:	128 8TH AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY

CHELSEA 1 HOUR PHOTO (Continued) **1000890023**

Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NY0000228924
Mailing Name: CHELSEA 1 HOUR PHOTO CENTER
Mailing Contact: MATTHEW HAN
Mailing Address 1: 128 8TH AVENUE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10011
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2127272702

AT688 **CVS PHARMACY #2919** **RCRA-VSQG** **1014958097**
SE **126 8TH AVE** **NY MANIFEST** **NYR000193342**
1/8-1/4 **NEW YORK, NY 10011**
0.189 mi.
996 ft. **Site 16 of 23 in cluster AT**

Relative: **Higher**
Actual: **21 ft.**

RCRA-VSQG:
Date Form Received by Agency: 20120305
Handler Name: CVS PHARMACY #2919
Handler Address: 126 8TH AVE
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYR000193342
Contact Name: WENDY L BRANT
Contact Address: CVS DR
Contact City,State,Zip: WOONSOCKET, RI 02895
Contact Telephone: 401-765-1500
Contact Fax: 401-216-0138
Contact Email: WENDY.BRANT@CVSCAREMARK.COM
Contact Title: CVS CORP ENVIRON MGR
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: NY
State District: NYSDEC R2
Mailing Address: CVS DR
Mailing City,State,Zip: WOONSOCKET, RI 02895
Owner Name: CHELSEA EIGHT LTD PARTNERSHIP
Owner Type: Private
Operator Name: CVS ALBANY LLC
Operator Type: Private
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No
Recycler Activity with Storage: No
Small Quantity On-Site Burner Exemption: No

CVS PHARMACY #2919 (Continued) **1014958097**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20151116
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE

CVS PHARMACY #2919 (Continued) **1014958097**

Waste Code: P001
Waste Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Waste Code: P042
Waste Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Waste Code: P075
Waste Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Waste Code: P081
Waste Description: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CHELSEA EIGHT LTD PARTNERSHIP
Legal Status:	Private
Date Became Current:	19940315
Date Ended Current:	Not reported
Owner/Operator Address:	101 2 70TH ST APT 2N
Owner/Operator City,State,Zip:	NEW YORK, NY 10023
Owner/Operator Telephone:	212-874-1686
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CVS ALBANY LLC
Legal Status:	Private
Date Became Current:	20000918
Date Ended Current:	Not reported
Owner/Operator Address:	ONE CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20120305
Handler Name: CVS PHARMACY #2919	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CVS PHARMACY #2919 (Continued) **1014958097**

List of NAICS Codes and Descriptions:
NAICS Code: 44611
NAICS Description: PHARMACIES AND DRUG STORES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CVS PHARMACY #2919
Address: 126 8TH AVE
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYR000193342
Facility Status: Not reported
Location Address 1: 126 8TH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000193342
Mailing Name: CVS PHARMACY #2919
Mailing Contact: CVS PHARMACY
Mailing Address 1: 126 8TH AVE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10011
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: PAD982661381
Trans2 State ID: Not reported
Generator Ship Date: 12/21/2016
Trans1 Recv Date: 12/21/2016
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/23/2016
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193342
Trans1 EPA ID: Not reported

CVS PHARMACY #2919 (Continued) **1014958097**

Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	010036474FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	D007
Waste Code 1_3:	D010
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AT689 **RAYMAX ASSOC** **NY AST** **U004048095**
SE **114 EIGHTH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.189 mi.
997 ft. **Site 17 of 23 in cluster AT**

Relative:
Higher

Actual:
21 ft.

AST:

Name:	RAYMAX ASSOC
Address:	114 EIGHTH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-148016
Program Type:	PBS
UTM X:	584303.35233
UTM Y:	4510468.96883
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	4385
Affiliation Type:	Facility Owner

RAYMAX ASSOC (Continued) **U004048095**

Company Name:	102-116 EIGHTH AVENUE ASSOCIATES, LP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	425 59TH STREET, 10TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10019-1183
Country Code:	001
Phone:	(212) 315-5555
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4385
Affiliation Type:	Mail Contact
Company Name:	NEW YORK URBAN PROPERTY MANAGEMENT, CORPORATION
Contact Type:	Not reported
Contact Name:	MARGARET BERGIN, DIRECTOR
Address1:	425 59TH STREET, 10TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10019-1183
Country Code:	001
Phone:	(212) 315-5555
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4385
Affiliation Type:	Facility Operator
Company Name:	RAYMAX ASSOC
Contact Type:	Not reported
Contact Name:	JOSE MEDINA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 645-9356
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4385
Affiliation Type:	Emergency Contact
Company Name:	102-116 EIGHTH AVENUE ASSOCIATES, LP
Contact Type:	Not reported
Contact Name:	STEVEN STEINBERG
Address1:	Not reported
Address2:	Not reported
City:	Not reported

RAYMAX ASSOC (Continued) **U004048095**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 556-5553
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	8012
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	04/01/1950
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/01/1994
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AT690 **RAYMAX ASSOCIATES** **NY AST** **U004048096**
SE **106 EIGHTH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.189 mi.
998 ft. **Site 18 of 23 in cluster AT**

Relative:
Higher

Actual:
21 ft.

AST:

Name:	RAYMAX ASSOCIATES
Address:	106 EIGHTH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-148008
Program Type:	PBS

RAYMAX ASSOCIATES (Continued) **U004048096**

UTM X: 584288.35028
UTM Y: 4510441.23606
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 4384
Affiliation Type: Facility Owner
Company Name: 102-116 EIGHTH AVENUE ASSOCIATES, L.P.
Contact Type: Not reported
Contact Name: Not reported
Address1: 425 WEST 59TH STREET, 10TH FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019-1183
Country Code: 001
Phone: (212) 315-5555
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 4384
Affiliation Type: Mail Contact
Company Name: NEW YORK URBAN PROPERTY MANAGEMENT CORPORATION
Contact Type: Not reported
Contact Name: MARGARET BERGIN, DIRECTOR
Address1: 425 WEST 59TH STREET, 10TH FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019-1183
Country Code: 001
Phone: (212) 315-5555
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 4384
Affiliation Type: Facility Operator
Company Name: RAYMAX ASSOCIATES
Contact Type: Not reported
Contact Name: TOM CAMPBELL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 288-7652
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 4384

RAYMAX ASSOCIATES (Continued) **U004048096**

Affiliation Type:	Emergency Contact
Company Name:	102-116 EIGHTH AVENUE ASSOCIATES, LP
Contact Type:	Not reported
Contact Name:	STEVEN STEINBERG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 556-5553
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	8011
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	I04 - Overfill - Product Level Gauge (A/G)
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	H00 - Tank Leak Detection - None
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	04/01/1950
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/01/1994
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AL691 **ST FRANCIS RESIDENCE III** **NY AST** **U003391061**
SE **148 8TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.190 mi.
1001 ft. **Site 12 of 14 in cluster AL**

Relative:
Higher

Actual:
21 ft.

AST:

Name:	ST FRANCIS RESIDENCE III
Address:	148 8TH AVE
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-328804
Program Type:	PBS
UTM X:	584358.95786
UTM Y:	4510571.81887
Expiration Date:	10/02/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	15416
Affiliation Type:	Facility Operator
Company Name:	ST FRANCIS RESIDENCE III
Contact Type:	Not reported
Contact Name:	ABDUL ALHASSAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 627-4131
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-11-06

Site Id:	15416
Affiliation Type:	Emergency Contact
Company Name:	ST FRANCIS FRIENDS OF THE POOR,INC.
Contact Type:	Not reported
Contact Name:	THOMAS CABRERA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 389-9480
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-25

Site Id:	15416
Affiliation Type:	Facility Owner
Company Name:	ST FRANCIS FRIENDS OF THE POOR,INC.
Contact Type:	EXECUTIVE DIRECTOR
Contact Name:	FR. STEPHEN MIMNAUGH, OFM

ST FRANCIS RESIDENCE III (Continued) **U003391061**

Address1:	155 WEST 22ND ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 354-6400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-25

Site Id:	15416
Affiliation Type:	Mail Contact
Company Name:	ST FRANCIS FRIENDS OF THE POOR,INC.
Contact Type:	Not reported
Contact Name:	CHARLES SCHADE
Address1:	155 WEST 22ND ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 254-6400
EMail:	CSCHADE@STFRANCISFRIENDS.ORG
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2019-02-14

Tank Info:

Tank Number:	001
Tank Id:	20682
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	D00 - Pipe Type - No Piping
	I04 - Overfill - Product Level Gauge (A/G)
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/02/1987
Capacity Gallons:	2000
Tightness Test Method:	-
Date Test:	Not reported

ST FRANCIS RESIDENCE III (Continued) **U003391061**

Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	10/25/2017
Material Name:	#2 fuel oil (on-site consumption)

BC692 **GANSEVOORT COOPERATIVE CORP** **NY AST** **U003384374**
South **652 HUDSON STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.191 mi.
1006 ft. **Site 1 of 4 in cluster BC**

Relative:
Higher

Actual:
17 ft.

AST:

Name:	GANSEVOORT COOPERATIVE CORP
Address:	652 HUDSON STREET
City,State,Zip:	NEW YORK, NY 10014
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-098620
Program Type:	PBS
UTM X:	583995.70740
UTM Y:	4510337.45659
Expiration Date:	03/24/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	2888
Affiliation Type:	Mail Contact
Company Name:	MAXWELL-KATES, INC
Contact Type:	Not reported
Contact Name:	ADAM DEMSKY
Address1:	9 EAST 38TH STREET, 6TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 684-8282
EMail:	JZELIN@MAXWELLKATES.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-08-18

Site Id:	2888
Affiliation Type:	Facility Operator
Company Name:	GANSEVOORT COOPERATIVE CORP
Contact Type:	Not reported
Contact Name:	GANSEVOORT COOPERATIVE CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 242-2499
EMail:	Not reported

GANSEVOORT COOPERATIVE CORP (Continued) **U003384374**

Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	2888
Affiliation Type:	Emergency Contact
Company Name:	GANSEVOORT COOPERATIVE CORP
Contact Type:	Not reported
Contact Name:	SAM CARSON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 242-1873
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	2888
Affiliation Type:	Facility Owner
Company Name:	GANSEVOORT COOPERATIVE CORP
Contact Type:	AGENT
Contact Name:	ADAM DEMSKY
Address1:	652 HUDSON STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10014
Country Code:	001
Phone:	(212) 242-1873
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-08-18

Tank Info:

Tank Number:	001
Tank Id:	3666
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser

GANSEVOORT COOPERATIVE CORP (Continued) **U003384374**

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/16/1974
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	08/18/2017
Material Name:	#2 fuel oil (on-site consumption)

BC693 **APARTMENT BUILDING** **NY LTANKS** **S106125650**
South **652 HUDSON STREET** **NY Spills** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.191 mi.
1006 ft. **Site 2 of 4 in cluster BC**

Relative: **Higher**

Actual: **17 ft.**

LTANKS:

Name:	652 HUDSON ST
Address:	652 HUDSON STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0312193 / 2004-02-02
Facility ID:	0312193
Site ID:	279919
Spill Date:	2004-02-02
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2004-02-02
CID:	403
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-02-02
Spill Record Last Update:	2004-02-02
Spiller Name:	PAUL
Spiller Company:	NEW UTRECHT FUEL
Spiller Address:	978 39 ST
Spiller County:	001
Spiller Contact:	PAUL
Spiller Phone:	(718) 435-5103
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	227262
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

APARTMENT BUILDING (Continued) **S106125650**

SANGESLAND duplicate spill 0312179"
Remarks: "the tank couldnt take as much oil as they put in it causing it to overfill. People are cleaning up the spill right now"

All Materials:
Site ID: 279919
Operable Unit ID: 879657
Operable Unit: 01
Material ID: 497422
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 20.00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: APARTMENT BUILDING
Address: 652 HUDSON STREET
City,State,Zip: MANHATTAN, NY
Spill Number/Closed Date: 0312179 / 2004-02-02
Facility ID: 0312179
Facility Type: ER
DER Facility ID: 157427
Site ID: 188486
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2004-02-02
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 2004-02-02
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Citizen
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-02-02
Spill Record Last Update: 2004-02-02
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND Sangesland spoke to property manager for 652 Hudeson St. Mr. Arnold 212-217-0633. He knew nothing about an oil spill, but he gave me the oil company name & number. New Utrech Fuel Oil -

APARTMENT BUILDING (Continued) **S106125650**

212-217-0633 Dispatch manager said his driver told him it was a minor spill. He will send a crew back to the site to clean up any oil that's left. Spill Closed"

Remarks: "CALLER STATES THAT SOME PETROLUEM SPILLED AT APRTMENT AND IS CAUSING STRONG ODERS IN APARTMENTS, SPILL WAS NOT CALLE DINTO US, NO FURTHER INFO AVAILABLE:"

All Materials:

Site ID:	188486
Operable Unit ID:	879639
Operable Unit:	01
Material ID:	497407
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

BC694 **GANSEVOORT CORPERATIVE CORP** **RCRA-VSQG** **1007371405**
South **652 HUDSON ST** **NY MANIFEST** **NYR000124727**
1/8-1/4 **NEW YORK, NY 10014** **NJ MANIFEST**
0.191 mi.
1006 ft. **Site 3 of 4 in cluster BC**

Relative: **Higher**
Actual: **17 ft.**

RCRA-VSQG:

Date Form Received by Agency:	20070101
Handler Name:	GANSEVOORT CORPERATIVE CORP
Handler Address:	652 HUDSON ST
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYR000124727
Contact Name:	ARNOLD WARWICK
Contact Address:	CHARLES ST
Contact City,State,Zip:	NEW YORK, NY 10014
Contact Telephone:	212-633-6500 223
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	CHARLES ST
Mailing City,State,Zip:	NEW YORK, NY 10014
Owner Name:	GANSEVOORT CORPERATIVE CORP
Owner Type:	Private
Operator Name:	ARNOLD WARWICK & CO LTD
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No

GANSEVOORT CORPERATIVE CORP (Continued) **1007371405**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:
Waste Code: D008

GANSEVOORT CORPERATIVE CORP (Continued) **1007371405**

Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GANSEVOORT CORPERATIVE CORP
Legal Status:	Private
Date Became Current:	19750101
Date Ended Current:	Not reported
Owner/Operator Address:	652 HUDSON ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10014
Owner/Operator Telephone:	212-633-6500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ARNOLD WARWICK & CO LTD
Legal Status:	Private
Date Became Current:	19960101
Date Ended Current:	Not reported
Owner/Operator Address:	129 CHARLES ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10014
Owner/Operator Telephone:	212-633-6500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GANSEVOORT CORPERATIVE CORP
Legal Status:	Private
Date Became Current:	19750101
Date Ended Current:	Not reported
Owner/Operator Address:	652 HUDSON ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10014
Owner/Operator Telephone:	212-633-6500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ARNOLD WARWICK & CO LTD
Legal Status:	Private
Date Became Current:	19960101
Date Ended Current:	Not reported
Owner/Operator Address:	129 CHARLES ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10014
Owner/Operator Telephone:	212-633-6500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name:	GANSEVOORT CORPERATIVE CORP
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY

GANSEVOORT CORPERATIVE CORP (Continued) **1007371405**

Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: GANSEVOORT CORPERATIVE CORP
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040524
Handler Name: GANSEVOORT CORPERATIVE CORP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 45299
NAICS Description: ALL OTHER GENERAL MERCHANDISE STORES

NAICS Code: 72119
NAICS Description: OTHER TRAVELER ACCOMMODATION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: GANSVOORT CORPERATIVE CORP
Address: 652 HUDSON ST
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYR000124727

GANSEVOORT CORPERATIVE CORP (Continued) **1007371405**

Facility Status: Not reported
Location Address 1: 652 HUDSON ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000124727
Mailing Name: GANSVOORT CORPERATIVE CORP
Mailing Contact: ARNOLD S. WARWICK
Mailing Address 1: 129 CHARLES STREET
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10014
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2126336500

NJ MANIFEST:
EPA Id: NYR000124727
Mail Address: 652 HUDSON STREET
Mail City/State/Zip: NEW YORK 10014
Facility Phone: 2126336500
Emergency Phone: Not reported
Contact: ARTHUR BALDWIN
Comments: Not reported
SIC Code: Not reported
County: 00
Municipal: 00
Previous EPA Id: Not reported
Gen Flag: X
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: NJA5076138
EPA ID: NYR000124727
Date Shipped: 06/17/2004
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD054126164
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 06/17/2004

GANSEVOORT CORPERATIVE CORP (Continued) **1007371405**

Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/17/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08030421
Was Load Rejected:	NEW YORK 10014
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5076139
EPA ID:	NYR000124727
Date Shipped:	06/17/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD054126164
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/17/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/17/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

GANSEVOORT CORPERATIVE CORP (Continued) **1007371405**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08060421
Was Load Rejected:	NEW YORK 10014
Reason Load Was Rejected:	Not reported

AN695 **CELIMAR CLEANERS** **RCRA NonGen / NLR** **1000789858**
East **188 8TH AVE** **FINDS** **NYD987013240**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.191 mi. **NY MANIFEST**
1008 ft. **Site 9 of 10 in cluster AN**

Relative: **Higher**
Actual: **21 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	CELIMAR CLEANERS	
Handler Address:		188 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYD987013240
Contact Name:		Not reported
Contact Address:		8TH AVE
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		8TH AVE
Mailing City,State,Zip:		NEW YORK, NY 10011
Owner Name:		GEORGE ORELLANA
Owner Type:		Private
Operator Name:		GEORGE ORELLANA
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No

CELIMAR CLEANERS (Continued) **1000789858**

Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

CELIMAR CLEANERS (Continued) **1000789858**

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GEORGE ORELLANA
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	GEORGE ORELLANA
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GEORGE ORELLANA
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: CELIMAR CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: CELIMAR CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

CELIMAR CLEANERS (Continued) **1000789858**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: CELIMAR CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920903
Handler Name: CELIMAR CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004494486

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CELIMAR CLEANERS (Continued) **1000789858**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000789858
Registry ID:	110004494486
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004494486
Name:	CELIMAR CLEANERS
Address:	188 8TH AVE
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	CELIMAR CLEANERS
Address:	188 8TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYD987013240
Facility Status:	Not reported
Location Address 1:	188 8TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987013240
Mailing Name:	CELIMAR CLEANERS
Mailing Contact:	JORGE ORELLIANO
Mailing Address 1:	188 8TH AVE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2122425900

AQ696 **CON EDISON SERVICE BOX 2377** **RCRA NonGen / NLR** **1014918804**
SSE **312 W 14TH ST & 8TH AVE OPP** **NJ MANIFEST** **NYP004224234**
1/8-1/4 **NEW YORK, NY 10014** **NY MANIFEST**
0.192 mi.
1012 ft. **Site 4 of 8 in cluster AQ**

Relative:
Higher

Actual:
21 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	20110215
Handler Name:	CON EDISON SERVICE BOX 2377
Handler Address:	312 W 14TH ST & 8TH AVE OPP
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYP004224234
Contact Name:	JOSE MONTALVO
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-427-1331

CON EDISON SERVICE BOX 2377 (Continued) **1014918804**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

CON EDISON SERVICE BOX 2377 (Continued) **1014918804**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20110701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20110116
Handler Name:	CON EDISON SERVICE BOX 2377
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20110215
Handler Name:	CON EDISON SERVICE BOX 2377
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON SERVICE BOX 2377 (Continued) **1014918804**

NJ MANIFEST:

EPA Id:	NYP004224234
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JOSE MONTALVO
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655891JJK
EPA ID:	NYP004224234
Date Shipped:	1/16/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported

CON EDISON SERVICE BOX 2377 (Continued) **1014918804**

Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 500.00 Pounds

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 312 W 14TH ST & 8TH AVE OPP
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYP004224234
Facility Status: Not reported
Location Address 1: OPP 312 W 14TH ST & 8TH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004224234
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602757

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 01/16/2011
Trans1 Recv Date: 01/16/2011
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/17/2011
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004224234
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported

CON EDISON SERVICE BOX 2377 (Continued) **1014918804**

TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655891JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AT697 **CON EDISON** **RCRA NonGen / NLR** **1014396702**
SE **124 8TH AVE** **NY MANIFEST** **NYP004190179**
1/8-1/4 **NEW YORK, NY 10011**
0.192 mi.
1013 ft. **Site 19 of 23 in cluster AT**

Relative: **Higher**
Actual: **21 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		124 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004190179
Contact Name:		STEVEN MARTIS
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		917-416-5423
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported

CON EDISON (Continued) **1014396702**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

CON EDISON (Continued) **1014396702**

Handler Date of Last Change:	20160726
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090812
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	124 8TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004190179
Facility Status:	Not reported
Location Address 1:	EAST 16 ST & AVE 8

CON EDISON (Continued) **1014396702**

Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: MANHATTAN
Location State: NY
Location Zip: 10020
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004190179
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 08/11/2009
Trans1 Recv Date: 08/11/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/13/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004190179
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 003532227JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H111
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

CON EDISON (Continued) **1014396702**

Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BA698 **CON EDISON SERVICE BOX: 43101** **RCRA NonGen / NLR** **1016143235**
North **208 10TH AVE** **FINDS** **NYP004259719**
1/8-1/4 **NEW YORK, NY 10014** **ECHO**
0.192 mi. **NY MANIFEST**
1014 ft. **Site 4 of 16 in cluster BA**

Relative: **Lower**
Actual: **12 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130321
Handler Name:	CON EDISON SERVICE BOX:	43101
Handler Address:		208 10TH AVE
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004259719
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No

CON EDISON SERVICE BOX: 43101 (Continued) **1016143235**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130221
Handler Name: CON EDISON SERVICE BOX:	43101
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CON EDISON SERVICE BOX: 43101 (Continued) **1016143235**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130321
Handler Name: CON EDISON SERVICE BOX: 43101
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063917338

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016143235
Registry ID: 110063917338
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110063917338
Name: CON EDISON SERVICE BOX: 43101
Address: 208 10TH AVE
City,State,Zip: NEW YORK, NY 10014

NY MANIFEST:
Name: CON EDISON
Address: 208 10TH AVE
City,State,Zip: NEW YORK, NY 10014
Country: USA

CON EDISON SERVICE BOX: 43101 (Continued) **1016143235**

EPA ID:	NYP004259719
Facility Status:	Not reported
Location Address 1:	208 10TH AVE
Code:	BP
Location Address 2:	SERV BOX 43101
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004259719
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/21/2013
Trans1 Recv Date:	02/21/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/22/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004259719
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010707133JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON SERVICE BOX: 43101 (Continued) **1016143235**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AN699 **170 8TH AVE.** **NY AST** **U003384240**
ESE **170 8TH AVE.** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.192 mi.
1015 ft. **Site 10 of 10 in cluster AN**

Relative: **Higher**
Actual: **21 ft.**

AST:

Name:	170 8TH AVE.
Address:	170 8TH AVE.
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-085901
Program Type:	PBS
UTM X:	584403.32207
UTM Y:	4510654.40818
Expiration Date:	03/24/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	2090
Affiliation Type:	Facility Owner
Company Name:	FRANKLIN HOLDING CO. C/O SIDNEY RUBELL COMPANY L
Contact Type:	MGR
Contact Name:	ELAINE GORLECHEN
Address1:	348 W 23RD ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 243-2370
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-01-17

Site Id:	2090
Affiliation Type:	Mail Contact
Company Name:	FRANKLIN HOLDING CO

170 8TH AVE. (Continued) **U003384240**

Contact Type:	Not reported
Contact Name:	ELAINE GORLECHEN
Address1:	C/O SIDNEY RUBELL COMPANY LLC
Address2:	348 WEST 23RD STREET
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 243-2370
EMail:	RUBELL@AOL.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-03-29

Site Id:	2090
Affiliation Type:	Facility Operator
Company Name:	170 8TH AVE.
Contact Type:	Not reported
Contact Name:	ABRAHAM MANZO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 974-0896
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-01-17

Site Id:	2090
Affiliation Type:	Emergency Contact
Company Name:	FRANKLIN HOLDING CO. C/O SIDNEY RUBELL COMPANY L
Contact Type:	Not reported
Contact Name:	ELAINE GORLECHEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 243-2370
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-01-17

Tank Info:

Tank Number:	001
Tank Id:	3358
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

170 8TH AVE. (Continued) **U003384240**

F99 - Pipe External Protection - Other
H99 - Tank Leak Detection - Other
B05 - Tank External Protection - Jacketed
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/14/1984
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)

BB700 **CVS PHARMACY #1618** **RCRA-VSQG** **1014958101**
SSE **81 8TH AVE** **NY MANIFEST** **NYR000193383**
1/8-1/4 **NEW YORK, NY 10011**
0.192 mi.
1015 ft. **Site 5 of 24 in cluster BB**

Relative: **Higher**
Actual: **21 ft.**

RCRA-VSQG:

Date Form Received by Agency:		20190406
Handler Name:	CVS PHARMACY #1618	
Handler Address:		81 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYR000193383
Contact Name:		NICOLE WILKINSON
Contact Address:		CVS DR MC2340
Contact City,State,Zip:		WOONSOCKET, RI 02895
Contact Telephone:		401-770-7132
Contact Fax:		315-454-4467
Contact Email:		NICOLE.WILKINSON@CVSHEALTH.COM
Contact Title:		DIRECTOR, CORPORATE ENVIRONMENTAL
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		CVS DR MC2340
Mailing City,State,Zip:		WOONSOCKET, RI 02895

CVS PHARMACY #1618 (Continued) **1014958101**

Owner Name:	CENTRAL RUG & CARPET MART LLC
Owner Type:	Private
Operator Name:	CVS ALBANY LLC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20190710
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No

CVS PHARMACY #1618 (Continued) **1014958101**

Manifest Broker: No
Sub-Part P Indicator: No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D002
Waste Description: CORROSIVE WASTE

Waste Code: D004
Waste Description: ARSENIC

Waste Code: D005
Waste Description: BARIUM

Waste Code: D006
Waste Description: CADMIUM

Waste Code: D007
Waste Description: CHROMIUM

Waste Code: D008
Waste Description: LEAD

Waste Code: D009
Waste Description: MERCURY

Waste Code: D010
Waste Description: SELENIUM

Waste Code: D011
Waste Description: SILVER

Waste Code: D016
Waste Description: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Waste Code: D018
Waste Description: BENZENE

Waste Code: D024
Waste Description: M-CRESOL

Waste Code: D027
Waste Description: 1,4-DICHLOROBENZENE

Waste Code: D035
Waste Description: METHYL ETHYL KETONE

CVS PHARMACY #1618 (Continued) **1014958101**

Waste Code: D039
Waste Description: TETRACHLOROETHYLENE

Waste Code: P001
Waste Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Waste Code: P012
Waste Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Waste Code: P042
Waste Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Waste Code: P075
Waste Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Waste Code: P081
Waste Description: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

Waste Code: P188
Waste Description: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

Waste Code: U002
Waste Description: 2-PROPANONE (I) (OR) ACETONE (I)

Waste Code: U010
Waste Description: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

Waste Code: U031
Waste Description: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Waste Code: U034
Waste Description: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

Waste Code: U035
Waste Description: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

Waste Code: U044
Waste Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Waste Code: U058
Waste Description: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

Waste Code: U059
Waste Description: 5,12-NAPHTHACENEDIONE, 8-ACETYL-10-[(3-AMINO-2,3,6-TRIDEOXY)-ALPHA-L-LYXO-HEXOPYRANOSYL)OXY]-7,8,9,10-TETRAHYDRO-6,8,11-TRIHYDROXY-1-METHOXY-, (8S-CIS)- (OR) DAUNOMYCIN

CVS PHARMACY #1618 (Continued) **1014958101**

Waste Code: U070
Waste Description: BENZENE, 1,2-DICHLORO- (OR) O-DICHLOROBENZENE

Waste Code: U072
Waste Description: BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE

Waste Code: U089
Waste Description: DIETHYLSTILBESTEROL (OR) PHENOL, 4,4'-(1,2-DIETHYL-1,2-ETHENEDIYL)BIS, (E)-

Waste Code: U122
Waste Description: FORMALDEHYDE

Waste Code: U129
Waste Description: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

Waste Code: U132
Waste Description: HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-

Waste Code: U150
Waste Description: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

Waste Code: U151
Waste Description: MERCURY

Waste Code: U154
Waste Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Waste Code: U165
Waste Description: NAPHTHALENE

Waste Code: U188
Waste Description: PHENOL

Waste Code: U200
Waste Description: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL)OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

Waste Code: U201
Waste Description: 1,3-BENZENEDIOL (OR) RESORCINOL

Waste Code: U204
Waste Description: SELENIOUS ACID (OR) SELENIUM DIOXIDE

Waste Code: U205
Waste Description: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

Waste Code: U206
Waste Description: D-GLUCOSE, 2-DEOXY-2-[[(METHYLNITROSOAMINO)-CARBONYL]AMINO]- (OR) GLUCOPYRANOSE, 2-DEOXY-2-(3-METHYL-3-NITROSOUREIDO)-,D- (OR) STREPTOZOTOCIN

Waste Code: U210
Waste Description: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

CVS PHARMACY #1618 (Continued) **1014958101**

Waste Code: U279
Waste Description: U279

Waste Code: U411
Waste Description: U411

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CENTRAL RUG & CARPET MART LLC
Legal Status: Private
Date Became Current: 20100515
Date Ended Current: Not reported
Owner/Operator Address: 4 MILL POND RD
Owner/Operator City,State,Zip: CLOSTER, NJ 07624
Owner/Operator Telephone: 201-787-9705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CENTRAL RUG & CARPET MART LLC
Legal Status: Private
Date Became Current: 20100515
Date Ended Current: Not reported
Owner/Operator Address: 4 MILL POND RD
Owner/Operator City,State,Zip: CLOSTER, NJ 07624
Owner/Operator Telephone: 201-787-9705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CVS ALBANY LLC
Legal Status: Private
Date Became Current: 20110301
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CENTRAL RUG & CARPET MART LLC
Legal Status: Private
Date Became Current: 20100515
Date Ended Current: Not reported
Owner/Operator Address: 4 MILL POND RD
Owner/Operator City,State,Zip: CLOSTER, NJ 07624-0363
Owner/Operator Telephone: 201-787-9705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CENTRAL RUG & CARPET MART LLC

CVS PHARMACY #1618 (Continued) **1014958101**

Legal Status:	Private
Date Became Current:	20100515
Date Ended Current:	Not reported
Owner/Operator Address:	4 MILL POND RD
Owner/Operator City,State,Zip:	CLOSTER, NJ 07624-0363
Owner/Operator Telephone:	201-787-9705
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CVS ALBANY LLC
Legal Status:	Private
Date Became Current:	20110301
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CENTRAL RUG & CARPET MART LLC
Legal Status:	Private
Date Became Current:	20100515
Date Ended Current:	Not reported
Owner/Operator Address:	4 MILL POND RD
Owner/Operator City,State,Zip:	CLOSTER, NJ 07624
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CVS ALBANY LLC
Legal Status:	Private
Date Became Current:	20110301
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CVS ALBANY LLC
Legal Status:	Private
Date Became Current:	20110301
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

CVS PHARMACY #1618 (Continued) **1014958101**

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CVS ALBANY LLC
Legal Status:	Private
Date Became Current:	20110301
Date Ended Current:	Not reported
Owner/Operator Address:	ONE CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20160317
Handler Name: CVS PHARMACY #1618	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180126
Handler Name: CVS PHARMACY #1618	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20120305
Handler Name: CVS PHARMACY #1618	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150213
Handler Name: CVS PHARMACY #1618	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

CVS PHARMACY #1618 (Continued) **1014958101**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20190406
Handler Name: CVS PHARMACY #1618	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	44611
NAICS Description:	PHARMACIES AND DRUG STORES

NAICS Code:	446110
NAICS Description:	PHARMACIES AND DRUG STORES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CVS PHARMACY #1618
Address:	81 8TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYR000193383
Facility Status:	Not reported
Location Address 1:	81 8TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000193383
Mailing Name:	CVS PHARMACY #1618
Mailing Contact:	CVS PHARMACY
Mailing Address 1:	81 8TH AVE

CVS PHARMACY #1618 (Continued) **1014958101**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2123664085

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MNS000110924
Trans2 State ID:	PAD982661381
Generator Ship Date:	12/12/2014
Trans1 Recv Date:	12/12/2014
Trans2 Recv Date:	12/15/2014
TSD Site Recv Date:	12/31/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000193383
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	INR000110197
TSDF ID 2:	Not reported
Manifest Tracking Number:	007386145FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	0.04
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	P001
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BB701 **CENTRAL RUG & CARPET MART** **NY UST** **U003241906**
SSE **81 8TH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.192 mi.
1015 ft. **Site 6 of 24 in cluster BB**

Relative:
Higher

Actual:
21 ft.

UST:

Name:	CENTRAL RUG & CARPET MART
Address:	81 8TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-603303 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584252.86785
UTM Y:	4510367.86698
Site Type:	Unknown

Affiliation Records:

Site Id:	25225
Affiliation Type:	Facility Owner
Company Name:	CENTRAL RUG & CARPET MART
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	81ST 8TH AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 741-3700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25225
Affiliation Type:	Facility Operator
Company Name:	CENTRAL RUG & CARPET MART
Contact Type:	Not reported
Contact Name:	IKE TIMIANKO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 741-3700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25225
Affiliation Type:	Emergency Contact
Company Name:	CENTRAL RUG & CARPET MART
Contact Type:	Not reported
Contact Name:	IKE TIMIANKO
Address1:	Not reported

CENTRAL RUG & CARPET MART (Continued) **U003241906**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 741-3700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25225
Affiliation Type:	Mail Contact
Company Name:	M.M.I. MECHANICAL INC.
Contact Type:	Not reported
Contact Name:	LESTER STARR
Address1:	137 HIGHLAWN AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11223
Country Code:	001
Phone:	(718) 449-4166
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	01
Tank ID:	53752
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2500
Install Date:	Not reported
Date Tank Closed:	12/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping

CENTRAL RUG & CARPET MART (Continued) **U003241906**

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

BB702 **CVS # 01618** **PA MANIFEST** **S118889255**
SSE **81 8TH AVENUE** **N/A**
1/8-1/4 **MANHATTAN, NY 10011**
0.192 mi.
1015 ft. **Site 7 of 24 in cluster BB**

Relative:
Higher

Actual:
21 ft.

Manifest Details:

Year:	2015
Manifest Number:	007396061FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000193383
Generator Date:	05/12/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	3
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	007396061FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000193383
Generator Date:	05/12/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D002
Container Number:	1

CVS # 01618 (Continued) **S118889255**

Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	4
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	006299619FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000193383
Generator Date:	03/02/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	4
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

AW703 **CON EDISON MANHOLE 32101** **RCRA NonGen / NLR** **1010326964**
East **W 21ST ST & 8TH AVE** **FINDS** **NYP004143947**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.192 mi. **NY MANIFEST**
1015 ft. **Site 2 of 9 in cluster AW**

Relative: RCRA NonGen / NLR:
Higher

Actual: Date Form Received by Agency:		20061116
21 ft. Handler Name:	CON EDISON MANHOLE 32101	
Handler Address:		W 21ST ST & 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004143947
Contact Name:		DANIEL PONTECORVO
Contact Address:		IRVING PL- RM 828
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-580-8383
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported

CON EDISON MANHOLE 32101 (Continued) **1010326964**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL- RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

CON EDISON MANHOLE 32101 (Continued) **1010326964**

Handler Date of Last Change: 20170425
Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20061115
Handler Name: CON EDISON
Federal Waste Generator Description: Not reported
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20061116
Handler Name: CON EDISON MANHOLE 32101
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110031443560

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

CON EDISON MANHOLE 32101 (Continued) **1010326964**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1010326964
Registry ID:	110031443560
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110031443560
Name:	CON EDISON MANHOLE 32101
Address:	W 21ST ST & 8TH AVE
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	SW C W 21 ST & 8 AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004143947
Facility Status:	Not reported
Location Address 1:	W 21ST ST & 8TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10002
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004143947
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

AL704 **SUN JINN CLEANERS INC** **RCRA NonGen / NLR** **1000132721**
ESE **156 EIGHTH AVE** **NY DRYCLEANERS** **NYD982719072**
1/8-1/4 **NEW YORK, NY 10011** **NY MANIFEST**
0.192 mi.
1015 ft. **Site 13 of 14 in cluster AL**

Relative: **Higher**
Actual: **21 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	SUN JINN CLEANERS INC	
Handler Address:		156 EIGHTH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYD982719072

SUN JINN CLEANERS INC (Continued) **1000132721**

Contact Name:	Not reported
Contact Address:	EIGHTH AVE
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	EIGHTH AVE
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	SUN JINN CLEANERS INC
Owner Type:	Municipal
Operator Name:	SUN JINN CLEANERS INC
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No

SUN JINN CLEANERS INC (Continued) **1000132721**

Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	SUN JINN CLEANERS INC
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SUN JINN CLEANERS INC
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported

SUN JINN CLEANERS INC (Continued) **1000132721**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SUN JINN CLEANERS INC
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, NY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: SUN JINN CLEANERS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: SUN JINN CLEANERS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SUN JINN CLEANERS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19911118
Handler Name: SUN JINN CLEANERS INC

SUN JINN CLEANERS INC (Continued) **1000132721**

Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

DRYCLEANERS:

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2001-08-21 15:42:41
Inspection Date:	2000-07-07 08:50:00
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2001-08-21 15:42:41
Inspection Date:	2002-07-10 09:30:00
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name: BELLCLAIRE DRY CLEANERS

SUN JINN CLEANERS INC (Continued) **1000132721**

Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2001-08-21 15:42:41
Inspection Date:	2003-07-10 09:30:00
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2001-08-21 15:42:41
Inspection Date:	2004-06-29 08:30:00
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2001-08-21 15:42:41
Inspection Date:	2005-06-22 07:50:00
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2001-08-21 15:42:41
Inspection Date:	2006-06-22 08:00:00
Install Date:	Not reported
Expiration Date:	07/16/2003

SUN JINN CLEANERS INC (Continued) **1000132721**

Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2001-08-21 15:42:41
Inspection Date: 2007-06-18 07:40:00
Install Date: Not reported
Expiration Date: 07/16/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2001-08-21 15:42:41
Inspection Date: 2008-06-17 07:45:00
Install Date: Not reported
Expiration Date: 07/16/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2001-08-21 15:42:41
Inspection Date: 2009-06-15 08:00:00
Install Date: Not reported
Expiration Date: 07/16/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY

SUN JINN CLEANERS INC (Continued) **1000132721**

Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2001-08-21 15:42:41
Inspection Date:	2010-06-14 08:00:00
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2001-08-21 15:42:41
Inspection Date:	2011-06-15 08:00:00
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2001-08-21 15:42:41
Inspection Date:	2012-06-22 07:10:00
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2001-08-21 15:42:41
Inspection Date:	2013-06-20 11:15:00
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported

SUN JINN CLEANERS INC (Continued) **1000132721**

Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2001-08-21 15:42:41
Inspection Date: 2014-06-17 11:00:00
Install Date: Not reported
Expiration Date: 07/16/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2001-08-21 15:42:41
Inspection Date: 2015-06-19 07:20:00
Install Date: Not reported
Expiration Date: 07/16/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2001-08-21 15:42:41
Inspection Date: 2016-06-24 08:00:00
Install Date: Not reported
Expiration Date: 07/16/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577

SUN JINN CLEANERS INC (Continued) **1000132721**

Region:	Not reported
Registration Effective Date:	2001-08-21 15:42:41
Inspection Date:	2017-06-28 07:30:00
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2001-08-21 15:42:41
Inspection Date:	2018-06-07 08:20:00
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2001-08-21 15:42:41
Inspection Date:	2019-06-27 07:40:00
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2003-07-16 09:38:14
Inspection Date:	2000-07-07 08:50:00
Install Date:	Not reported
Expiration Date:	10/16/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil

SUN JINN CLEANERS INC (Continued) **1000132721**

Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2003-07-16 09:38:14
Inspection Date: 2002-07-10 09:30:00
Install Date: Not reported
Expiration Date: 10/16/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2003-07-16 09:38:14
Inspection Date: 2003-07-10 09:30:00
Install Date: Not reported
Expiration Date: 10/16/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2003-07-16 09:38:14
Inspection Date: 2004-06-29 08:30:00
Install Date: Not reported
Expiration Date: 10/16/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2003-07-16 09:38:14

SUN JINN CLEANERS INC (Continued) **1000132721**

Inspection Date:	2005-06-22 07:50:00
Install Date:	Not reported
Expiration Date:	10/16/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2003-07-16 09:38:14
Inspection Date:	2006-06-22 08:00:00
Install Date:	Not reported
Expiration Date:	10/16/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2003-07-16 09:38:14
Inspection Date:	2007-06-18 07:40:00
Install Date:	Not reported
Expiration Date:	10/16/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2003-07-16 09:38:14
Inspection Date:	2008-06-17 07:45:00
Install Date:	Not reported
Expiration Date:	10/16/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

SUN JINN CLEANERS INC (Continued) **1000132721**

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2003-07-16 09:38:14
Inspection Date:	2009-06-15 08:00:00
Install Date:	Not reported
Expiration Date:	10/16/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2003-07-16 09:38:14
Inspection Date:	2010-06-14 08:00:00
Install Date:	Not reported
Expiration Date:	10/16/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2003-07-16 09:38:14
Inspection Date:	2011-06-15 08:00:00
Install Date:	Not reported
Expiration Date:	10/16/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2003-07-16 09:38:14
Inspection Date:	2012-06-22 07:10:00
Install Date:	Not reported

SUN JINN CLEANERS INC (Continued) **1000132721**

Expiration Date:	10/16/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2003-07-16 09:38:14
Inspection Date:	2013-06-20 11:15:00
Install Date:	Not reported
Expiration Date:	10/16/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2003-07-16 09:38:14
Inspection Date:	2014-06-17 11:00:00
Install Date:	Not reported
Expiration Date:	10/16/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2003-07-16 09:38:14
Inspection Date:	2015-06-19 07:20:00
Install Date:	Not reported
Expiration Date:	10/16/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE

SUN JINN CLEANERS INC (Continued) **1000132721**

City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2003-07-16 09:38:14
Inspection Date: 2016-06-24 08:00:00
Install Date: Not reported
Expiration Date: 10/16/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2003-07-16 09:38:14
Inspection Date: 2017-06-28 07:30:00
Install Date: Not reported
Expiration Date: 10/16/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2003-07-16 09:38:14
Inspection Date: 2018-06-07 08:20:00
Install Date: Not reported
Expiration Date: 10/16/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2003-07-16 09:38:14
Inspection Date: 2019-06-27 07:40:00
Install Date: Not reported
Expiration Date: 10/16/2008
Removal Date: Not reported

SUN JINN CLEANERS INC (Continued) **1000132721**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2008-10-16 17:22:58
Inspection Date: 2000-07-07 08:50:00
Install Date: Not reported
Expiration Date: 10/08/2021
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2008-10-16 17:22:58
Inspection Date: 2002-07-10 09:30:00
Install Date: Not reported
Expiration Date: 10/08/2021
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2008-10-16 17:22:58
Inspection Date: 2003-07-10 09:30:00
Install Date: Not reported
Expiration Date: 10/08/2021
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310

SUN JINN CLEANERS INC (Continued) **1000132721**

Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2008-10-16 17:22:58
Inspection Date:	2004-06-29 08:30:00
Install Date:	Not reported
Expiration Date:	10/08/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2008-10-16 17:22:58
Inspection Date:	2005-06-22 07:50:00
Install Date:	Not reported
Expiration Date:	10/08/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2008-10-16 17:22:58
Inspection Date:	2006-06-22 08:00:00
Install Date:	Not reported
Expiration Date:	10/08/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2008-10-16 17:22:58
Inspection Date:	2007-06-18 07:40:00
Install Date:	Not reported
Expiration Date:	10/08/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported

SUN JINN CLEANERS INC (Continued) **1000132721**

Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2008-10-16 17:22:58
Inspection Date: 2008-06-17 07:45:00
Install Date: Not reported
Expiration Date: 10/08/2021
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2008-10-16 17:22:58
Inspection Date: 2009-06-15 08:00:00
Install Date: Not reported
Expiration Date: 10/08/2021
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2008-10-16 17:22:58
Inspection Date: 2010-06-14 08:00:00
Install Date: Not reported
Expiration Date: 10/08/2021
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported

SUN JINN CLEANERS INC (Continued) **1000132721**

Registration Effective Date:	2008-10-16 17:22:58
Inspection Date:	2011-06-15 08:00:00
Install Date:	Not reported
Expiration Date:	10/08/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2008-10-16 17:22:58
Inspection Date:	2012-06-22 07:10:00
Install Date:	Not reported
Expiration Date:	10/08/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2008-10-16 17:22:58
Inspection Date:	2013-06-20 11:15:00
Install Date:	Not reported
Expiration Date:	10/08/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2008-10-16 17:22:58
Inspection Date:	2014-06-17 11:00:00
Install Date:	Not reported
Expiration Date:	10/08/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

SUN JINN CLEANERS INC (Continued) **1000132721**

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2008-10-16 17:22:58
Inspection Date:	2015-06-19 07:20:00
Install Date:	Not reported
Expiration Date:	10/08/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2008-10-16 17:22:58
Inspection Date:	2016-06-24 08:00:00
Install Date:	Not reported
Expiration Date:	10/08/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2008-10-16 17:22:58
Inspection Date:	2017-06-28 07:30:00
Install Date:	Not reported
Expiration Date:	10/08/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2008-10-16 17:22:58
Inspection Date:	2018-06-07 08:20:00
Install Date:	Not reported

SUN JINN CLEANERS INC (Continued) **1000132721**

Expiration Date:	10/08/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2008-10-16 17:22:58
Inspection Date:	2019-06-27 07:40:00
Install Date:	Not reported
Expiration Date:	10/08/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2021-10-08 14:20:50
Inspection Date:	2000-07-07 08:50:00
Install Date:	Not reported
Expiration Date:	10/07/2031
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2021-10-08 14:20:50
Inspection Date:	2002-07-10 09:30:00
Install Date:	Not reported
Expiration Date:	10/07/2031
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE

SUN JINN CLEANERS INC (Continued) **1000132721**

City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2021-10-08 14:20:50
Inspection Date: 2003-07-10 09:30:00
Install Date: Not reported
Expiration Date: 10/07/2031
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2021-10-08 14:20:50
Inspection Date: 2004-06-29 08:30:00
Install Date: Not reported
Expiration Date: 10/07/2031
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2021-10-08 14:20:50
Inspection Date: 2005-06-22 07:50:00
Install Date: Not reported
Expiration Date: 10/07/2031
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2021-10-08 14:20:50
Inspection Date: 2006-06-22 08:00:00
Install Date: Not reported
Expiration Date: 10/07/2031
Removal Date: Not reported

SUN JINN CLEANERS INC (Continued) **1000132721**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2021-10-08 14:20:50
Inspection Date: 2007-06-18 07:40:00
Install Date: Not reported
Expiration Date: 10/07/2031
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2021-10-08 14:20:50
Inspection Date: 2008-06-17 07:45:00
Install Date: Not reported
Expiration Date: 10/07/2031
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2021-10-08 14:20:50
Inspection Date: 2009-06-15 08:00:00
Install Date: Not reported
Expiration Date: 10/07/2031
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310

SUN JINN CLEANERS INC (Continued) **1000132721**

Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2021-10-08 14:20:50
Inspection Date:	2010-06-14 08:00:00
Install Date:	Not reported
Expiration Date:	10/07/2031
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2021-10-08 14:20:50
Inspection Date:	2011-06-15 08:00:00
Install Date:	Not reported
Expiration Date:	10/07/2031
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2021-10-08 14:20:50
Inspection Date:	2012-06-22 07:10:00
Install Date:	Not reported
Expiration Date:	10/07/2031
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2021-10-08 14:20:50
Inspection Date:	2013-06-20 11:15:00
Install Date:	Not reported
Expiration Date:	10/07/2031
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported

SUN JINN CLEANERS INC (Continued) **1000132721**

Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2021-10-08 14:20:50
Inspection Date: 2014-06-17 11:00:00
Install Date: Not reported
Expiration Date: 10/07/2031
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2021-10-08 14:20:50
Inspection Date: 2015-06-19 07:20:00
Install Date: Not reported
Expiration Date: 10/07/2031
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported
Registration Effective Date: 2021-10-08 14:20:50
Inspection Date: 2016-06-24 08:00:00
Install Date: Not reported
Expiration Date: 10/07/2031
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: BELLCLAIRE DRY CLEANERS
Address: 156 EIGHTH AVE
City,State,Zip: NEW YORK, NY
Facility ID: 2-6205-00310
Phone Number: 2122423577
Region: Not reported

SUN JINN CLEANERS INC (Continued) **1000132721**

Registration Effective Date:	2021-10-08 14:20:50
Inspection Date:	2017-06-28 07:30:00
Install Date:	Not reported
Expiration Date:	10/07/2031
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2021-10-08 14:20:50
Inspection Date:	2018-06-07 08:20:00
Install Date:	Not reported
Expiration Date:	10/07/2031
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	BELLCLAIRE DRY CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY
Facility ID:	2-6205-00310
Phone Number:	2122423577
Region:	Not reported
Registration Effective Date:	2021-10-08 14:20:50
Inspection Date:	2019-06-27 07:40:00
Install Date:	Not reported
Expiration Date:	10/07/2031
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

NY MANIFEST:

Name:	SUNJINN CLEANERS
Address:	156 EIGHTH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYD982719072
Facility Status:	Not reported
Location Address 1:	156 EIGHTH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

SUN JINN CLEANERS INC (Continued) **1000132721**

NY MANIFEST:

EPAID:	NYD982719072
Mailing Name:	SUNJINN CLEANERS
Mailing Contact:	SUNJINN CLEANERS
Mailing Address 1:	156 EIGHTH AVE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2122423577

AL705 **CON EDISON** **NY MANIFEST** **S117058995**
ESE **154-156 E 8TH AVE & 17TH ST N** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.192 mi.
1016 ft. **Site 14 of 14 in cluster AL**

Relative:
Higher

Actual:
21 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	154-156 E 8TH AVE & 17TH ST N
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004511374
Facility Status:	Not reported
Location Address 1:	154-156 8TH AVE
Code:	BP
Location Address 2:	SB 32074
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004511374
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/24/2014

CON EDISON (Continued) **S117058995**

Trans1 Recv Date:	04/24/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004511374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416522GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AW706 **CON EDISON** **NY MANIFEST** **S117067382**
East **8TH AVE & W 21 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.193 mi.
1017 ft. **Site 3 of 9 in cluster AW**

Relative:
Higher

Actual:
21 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	8TH AVE & W 21 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004601860
Facility Status:	Not reported
Location Address 1:	8TH AVE & W 21 ST
Code:	BP
Location Address 2:	SB32106

CON EDISON (Continued) **S117067382**

Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004601860
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/20/2014
Trans1 Recv Date:	07/20/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/22/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004601860
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002608467GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds

CON EDISON (Continued) **S117067382**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AK707 **CE - W. 18TH ST. GAS WORKS** **NY VCP** **S105684667**
NW **WEST 16TH - WEST 20TH STS.** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.193 mi.
1018 ft. **Site 18 of 18 in cluster AK**

Relative: **Lower**

Actual: **5 ft.**

VCP:

Name:	CE - W. 18TH ST. GAS WORKS
Address:	WEST 16TH - WEST 20TH STS.
City,State,Zip:	NEW YORK, NY 10011
Program Type:	VCP
Site Code:	57083
HW Code:	V00530
Site Class:	A
SWIS:	3101
Region:	2
Town:	New York City
Acres:	11.600
Date Record Added:	03/05/2002
Date Record Updated:	07/03/2018
Updated By:	GWCROSS
Site Description:	"Location: The site is the northwestern part of a larger, historic gas manufacturing site which once encompassed portions of five city blocks along the western side of Manhattan, New York City. Remediation has already been accomplished at several other portions of the larger site, as detailed below. The portion of the site covered by this document (Operable Unit 5, as described below) is bounded by the West Side Highway (NY Route 9A) on the west, and West 18th and 19th Streets to the south and north, respectively. To the east, the rest of the block is made up mixed use commercial properties. Site Features: The site is almost flat, with a slight slope to the west, toward the Hudson River. Most recently, the site housed the Bayview Prison facility for women, which was closed following major flood damage from Tropical Storm Sandy in 2013. The entire site is covered with buildings or pavement. Current Zoning and Land Use: The former prison building and a building annex remain vacant on the site. Current site zoning is C6-3, for commercial purposes. The site is included in the Special West Chelsea District, a 14-square block area established in 2005 to allow mixed commercial and residential development, and to promote development around the adjacent High Line city park. Adjacent properties to the east are being redeveloped for residential and commercial uses. Past Use of the Site: The West 18th Street Gas Works began operations in 1834 and continued to expand through most of the 1800s, but was closed in the early 1900s. Manufactured gas was produced by heating coal in a closed vessel, collecting and purifying it, and then delivering it

CE - W. 18TH ST. GAS WORKS (Continued) **S105684667**

through underground networks of pipes into the surrounding area. The gas was used in homes and businesses for heating, lighting, and cooking in much the same way that natural gas is used today. Operable Unit 5 contained two gas holders during the period when the MGP was active. The gas manufacturing process produced a black, oily liquid waste known as coal tar. This tar escaped from underground storage tanks and pipes into surrounding subsurface soils. The tar is resistant to decay and is commonly found in soils at former MGP sites decades after operations ceased. Most of the tar contamination found at the West 18th Street MGP was found on neighboring properties, which have already been remediated or are in the process of being remediated. Relatively minor impacts have been detected on Operable Unit 5. Following closure of the MGP, the gas manufacturing facility was torn down and the site was subdivided and sold to a number of different owners. Subsurface structures such as building foundations and subsurface piping, however, were often not removed and remain in place today. A variety of commercial and industrial operations developed throughout the former MGP site in the middle and late 1900s. Based on investigation work conducted to date, it appears that gas holder foundations still exist beneath Operable Unit 5. Operable Units: An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Although the entire West 18th Street MGP site is included in a Voluntary Cleanup Agreement with Consolidated Edison, the former MGP site is now split between several different current owners and operable units, which has enabled a piece-by-piece approach to site cleanup. Some of this cleanup work has been accomplished under the original Voluntary Cleanup Agreement, and some has been accomplished by third party developers under the New York State Brownfield Cleanup program. The following is a summary of the operable units comprising the site. Operable Unit 1 (OU 01) is the entire historical footprint of the MGP site. Operable Unit 2 (OU 02), the West Chelsea Development property (535 West 19th Street), was designated as OU-2 to facilitate redevelopment. Remedial Action took place from September 2006-February 2008, for which a release letter, closing out remediation of this property, was issued in November 2009. Operable Unit 3 (OU 03), 524 West 19th Street, also known as the Gasser Property, was remediated from September 2007 - September 2008. A final engineering report was approved in August, 2009, and a deed restriction was filed in October 2009. Operable Unit 4 (OU 04) is the portion of the site that sits between West 16th and West 17th Street and 10th and 11th Avenue. Another part of the original MGP site, the 19th Street Development site, located at 80 11th Avenue, was remediated under the Brownfield Cleanup Program as site number C231017, and received a Certificate of Completion in September 2006. No formal Operable Unit designation was made for this property. The block bounded by West 17th and 18th Streets, and by 10th and 11th Avenues, entered into the BCP as two different projects. The western portion (known as the 17th Street Development Site, C231036) completed remedial action in December 2014, and is currently being redeveloped. The eastern portion, surrounding the High Line Park, is known as the 515 West 18th Street Site (C231093) has been thoroughly investigated and is currently awaiting remedial action. No formal Operable Unit designation was made for this property. Site Geology and Hydrogeology: Between 50 and 80 feet of unconsolidated materials

CE - W. 18TH ST. GAS WORKS (Continued) **S105684667**

overlie Cambrian Hartland Formation bedrock. The unconsolidated units are divided in to three distinct stratigraphic units. From the surface down, the units consist of a fill unit (highly heterogeneous, generally highly permeable) a silty-clay unit (a low-permeability aquitard consisting of tidal marsh deposits), and a sand unit (highly permeable stratified alluvial sands). Operable Unit 5 (OU 05) is the subject of this document, and represents one of the last two portions of the West 18th Street MGP Site which have not been remediated or have a remedy selected. A remedy for the other remaining portion at the northeastern corner of the site, and the city streets which traverse the site, will be determined in the future. "

Env Problem: "Nature and Extent of Contamination: Groundwater and subsurface soil are contaminated with BTEX and PAH. A significant amount of coal tar contamination is associated with the former MGP structures on this property. Significant contamination on many parcels extends to the bottom of the fill unit at depths approaching 50 feet below ground surface. Soils saturated with coal tar are found at depths between 1.5 feet and 35 feet below ground surface. Wells spontaneously accumulate up to 8 feet of mobile tar. Special Resources Impacted/Threatened: The heaviest concentration of coal tar is found along the western, downgradient edge of the site. MGP contamination appears to have migrated from this property primarily to the north and west, but has not yet been observed in the Hudson River 160 feet to the west of the site. Tar accumulates spontaneously (without pumping) in monitoring wells at the western property line, so off-site migration can occur readily. Significant Threat: This site presents a significant environmental threat due to the presence of tar moving off-site in the direction of the Hudson River 160 feet away. OU5: Nature and Extent of Contamination: Sampling at the site was limited due to the presence of buildings that did not permit extensive sampling. Based on the limited sampling to date, which included analysis for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), and metals, no significant contamination has been detected on this operable unit. There is a possibility that some source material may be present within the holder structure under the former prison building, however, there is no evidence that source material is migrating from the operable unit. The soil samples collected on Operable Unit 5 contained SVOCs and metal contamination; the highest concentration of total SVOCs is 610 parts per million (ppm). Concentrations of mercury exceed the restricted residential SCOs, with a maximum concentration of 1.9 ppm. Groundwater collected north of this operable unit met ambient water quality standards, and the groundwater south of the adjacent operable unit (south of the site) contained minor contamination of SVOCs, with only naphthalene exceeding its groundwater standards at a concentration of 11 parts per billion. Soil vapor and indoor air sampling have not indicated the potential for soil vapor exposure. "

Health Problem: "Public water is provided to the area, thereby preventing exposures to groundwater. The area is covered with buildings or pavement, thereby preventing direct contact with contamination. The investigation of the whole site is on-going and data will be evaluated as they become available."

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported

CE - W. 18TH ST. GAS WORKS (Continued) **S105684667**

Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	6
Sub Type:	01
Owner Name:	Kenneth J. Kaiser, PE, BCEE
Owner Company:	CONSOLIDATED EDISON CO OF NY.,INC.
Owner Address:	EH&S, MGP Remediation
Owner Addr2:	3101 20th Avenue - Bldg 136, 2nd Flr
Owner City,St,Zip:	Long Island City, NY 11105
Owner Country:	United States of America
Own Op:	1
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	VARIOUS - SEE PROGRAM FOLDER
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	1
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	NYS URBAN DEVELOPMENT CORP.
Owner Address:	112 11TH AVE.
Owner Addr2:	Not reported
Owner City,St,Zip:	NY, NY 10011
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Attn: Ms. Lee
Owner Company:	New York Public Library
Owner Address:	Muhlenberg Branch
Owner Addr2:	209 West 23rd Street
Owner City,St,Zip:	New York, NY 10011-2379
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Manhattan Community Board 4
Owner Address:	330 West 42nd Street
Owner Addr2:	Suite 2618
Owner City,St,Zip:	New York, NY 10036
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AO708 **CON EDISON - MANHOLE M4217** **NY MANIFEST** **S121968406**
ENE **326 W 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.195 mi.
1029 ft. **Site 10 of 12 in cluster AO**

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:

Name:	CON EDISON - MANHOLE M4217
Address:	326 W 23RD ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP005115142
Facility Status:	Not reported
Location Address 1:	326 W 23RD ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005115142
Mailing Name:	CON EDISON - MANHOLE M4217
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

AO709 **CON EDISON - MANHOLE M4217** **RCRA-LQG** **1024891477**
ENE **326 W 23RD ST** **NYP005115142**
1/8-1/4 **NEW YORK, NY 10011**
0.195 mi.
1029 ft. **Site 11 of 12 in cluster AO**

Relative:
Higher

Actual:
20 ft.

RCRA-LQG:

Date Form Received by Agency:	20180410
Handler Name:	CON EDISON - MANHOLE M4217
Handler Address:	326 W 23RD ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP005115142
Contact Name:	ALYSSA SOTTO
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017

CON EDISON - MANHOLE M4217 (Continued) **1024891477**

Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

CON EDISON - MANHOLE M4217 (Continued) **1024891477**

Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20170722
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-460-2757
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20170722
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-460-2757
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20180410
Handler Name:	CON EDISON - MANHOLE M4217
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No

CON EDISON - MANHOLE M4217 (Continued) **1024891477**

Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

BA710 **CON EDISON** **NY MANIFEST** **S126115941**
North **W 23RD ST & 10 TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.195 mi.
1029 ft. **Site 5 of 16 in cluster BA**

Relative:
Lower

Actual:
12 ft.

NY MANIFEST:
Name: CON EDISON
Address: W 23RD ST & 10 TH AVE
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004278271
Facility Status: Not reported
Location Address 1: F/O 435 W 23RD ST & 10TH AVE
Code: BP
Location Address 2: MH 4178
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004278271
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 02/26/2013

CON EDISON (Continued) **S126115941**

Trans1 Recv Date:	02/26/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/26/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004278271
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010708029JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	8000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BA711 **CON EDISON SERVICE BOX: 43108** **NJ MANIFEST** **S120665929**
North **W 10TH AVE & 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.195 mi.
1029 ft. **Site 6 of 16 in cluster BA**

Relative: **Lower**
Actual: **12 ft.**

NJ MANIFEST:

EPA Id:	NYP004276382
Mail Address:	Not reported
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JOSE MONTALVO
Comments:	Not reported
SIC Code:	Not reported
County:	NY061

CON EDISON SERVICE BOX: 43108 (Continued) **S120665929**

Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001675373GBF
EPA ID:	NYP004276382
Date Shipped:	10/26/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	400.00 gallons

BA712 **CON EDISON - MANHOLE 33595** **RCRA-LQG** **1016149168**
North **W 5 AVE ESW 15 ST** **NYP004278271**
1/8-1/4 **NEW YORK, NY 10003**
0.195 mi.
1029 ft. **Site 7 of 16 in cluster BA**

Relative: RCRA-LQG:
Lower

Actual:
12 ft.

Date Form Received by Agency:	20140327
Handler Name:	CON EDISON - MANHOLE 33595
Handler Address:	W 5 AVE ESW 15 ST
Handler City,State,Zip:	NEW YORK, NY 10003
EPA ID:	NYP004278271
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	631-208-0233
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON - MANHOLE 33595 (Continued) **1016149168**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20130225
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private

CON EDISON - MANHOLE 33595 (Continued) **1016149168**

Date Became Current: 20130225
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140327
Handler Name: CON EDISON - MANHOLE 33595
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130225
Handler Name: CON EDISON MANHOLE: 4178
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130325
Handler Name: CON EDISON MANHOLE: 4178
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

CON EDISON - MANHOLE 33595 (Continued) **1016149168**

Evaluation Action Summary:
Evaluations: No Evaluations Found

AR713 **CON EDISON - GAS MAIN** **RCRA-LQG** **1019324652**
SSW **17 9TH AVE** **FINDS** **NYP004706669**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.195 mi.
1031 ft. **Site 4 of 14 in cluster AR**

Relative: **Higher**

Actual: **14 ft.**

RCRA-LQG:

Date Form Received by Agency:		20160205
Handler Name:	CON EDISON - GAS MAIN	
Handler Address:		17 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004706669
Contact Name:		THERESA BURKARD
Contact Address:		IRVING PL 15TH FL NE
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-2262
Contact Fax:		Not reported
Contact Email:		BURKARDT@CONED.COM
Contact Title:		ASSOCIATE SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Large Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		2015
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		CONSOLIDATED EDISON CO OF NY INC
Owner Type:		Private
Operator Name:		CONSOLIDATED EDISON CO OF NY INC
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN

CON EDISON - GAS MAIN (Continued) **1019324652**

Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161107
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years

Year:	2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D018
Waste Description:	BENZENE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON CO OF NY INC
Legal Status:	Private
Date Became Current:	20141215
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PL
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported

CON EDISON - GAS MAIN (Continued) **1019324652**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON CO OF NY INC
Legal Status: Private
Date Became Current: 20141215
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - GAS MAIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069376696

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER

CON EDISON - GAS MAIN (Continued) **1019324652**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019324652
Registry ID:	110069376696
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069376696
Name:	CON EDISON - GAS MAIN
Address:	17 9TH AVE
City,State,Zip:	NEW YORK, NY 10011

AR714 **CON EDISON - GAS MAIN** **NJ MANIFEST** **S120666347**
SSW **17 9TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.195 mi.
1031 ft. **Site 5 of 14 in cluster AR**

Relative:
Higher

Actual:
14 ft.

NJ MANIFEST:

EPA Id:	NYP004706669
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014086982JJK
EPA ID:	NYP004706669
Date Shipped:	2/4/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

CON EDISON - GAS MAIN (Continued) **S120666347**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AR715 **CON EDISON** **NY MANIFEST** **S119073946**
SSW **17 9TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.195 mi.
1031 ft. **Site 6 of 14 in cluster AR**

Relative:
Higher

Actual:
14 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	17 9TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004706669
Facility Status:	Not reported
Location Address 1:	17 9 AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004706669
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported

CON EDISON (Continued) **S119073946**

Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAD039322250
Trans2 State ID:	Not reported
Generator Ship Date:	12/18/2014
Trans1 Recv Date:	12/18/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004706669
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MDD980555189
TSDF ID 2:	Not reported
Manifest Tracking Number:	007748007FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H129
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	31
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AY716
NW
1/8-1/4
0.196 mi.
1037 ft.

CON EDISON - 19TH ST. WORKS MGP — **EDR MGP** — **1008407976**
11TH AVE BETWEEN W 19TH AND W 20TH STS — **N/A**
NEW YORK, NY 10011

Site 4 of 11 in cluster AY

Relative:
Lower

Actual:
5 ft.

Manufactured Gas Plants:
No additional information available

AR717
SSW
1/8-1/4
0.197 mi.
1040 ft.

CON EDISON — **NY MANIFEST** — **S116551124**
8 9TH AVE — **N/A**
NEW YORK, NY 10014

Site 7 of 14 in cluster AR

Relative:
Higher

Actual:
15 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	8 9TH AVE
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004495594
Facility Status:	Not reported
Location Address 1:	8 9 AVE
Code:	BP
Location Address 2:	SB39619
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004495594
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/09/2014
Trans1 Recv Date:	04/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/15/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004495594

CON EDISON (Continued) **S116551124**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407382GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AR718 **CON EDISON SERVICE BOX: 39619** **RCRA NonGen / NLR** **1017772599**
SSW **8 9TH AVE** **NYP004495594**
1/8-1/4 **NEW YORK, NY 10014**
0.197 mi.
1040 ft. **Site 8 of 14 in cluster AR**

Relative: RCRA NonGen / NLR:
Higher

Actual: **15 ft.**

Date Form Received by Agency:		20140509
Handler Name:	CON EDISON SERVICE BOX:	39619
Handler Address:		8 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004495594
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified

CON EDISON SERVICE BOX: 39619 (Continued) **1017772599**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No

CON EDISON SERVICE BOX: 39619 (Continued) **1017772599**

Significant Non-Complier With a Compliance Schedule Universe: No
Financial Assurance Required: Not reported
Handler Date of Last Change: 20150211
Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:

Receive Date: 20140409
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140409
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140509
Handler Name: CON EDISON SERVICE BOX: 39619
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

CON EDISON SERVICE BOX: 39619 (Continued) **1017772599**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

BA719 **CON EDISON SERVICE BOX: 43102** **RCRA NonGen / NLR** **1016143255**
North **212 10TH AVE** **FINDS** **NYP004259917**
1/8-1/4 **NEW YORK, NY 10014** **ECHO**
0.197 mi. **NY MANIFEST**
1042 ft. **Site 8 of 16 in cluster BA**

Relative: **Lower**
Actual: **12 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130321
Handler Name:	CON EDISON SERVICE BOX:	43102
Handler Address:		212 10TH AVE
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004259917
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

CON EDISON SERVICE BOX: 43102 (Continued) **1016143255**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130321
Handler Name: CON EDISON SERVICE BOX:	43102
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130221
Handler Name: CON EDISON SERVICE BOX:	43102

CON EDISON SERVICE BOX: 43102 (Continued) **1016143255**

Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063922992

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016143255
Registry ID:	110063922992
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110063922992
Name:	CON EDISON SERVICE BOX: 43102
Address:	212 10TH AVE
City,State,Zip:	NEW YORK, NY 10014

NY MANIFEST:

Name:	CON EDISON
Address:	212 10TH AVE
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004259917
Facility Status:	Not reported
Location Address 1:	212 10TH AVE
Code:	BP
Location Address 2:	SERV BOX 43102
Total Tanks:	Not reported

CON EDISON SERVICE BOX: 43102 (Continued) **1016143255**

Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004259917
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/21/2013
Trans1 Recv Date:	02/21/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/22/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004259917
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010707134JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1

CON EDISON SERVICE BOX: 43102 (Continued) **1016143255**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BC720 **SPECTRANOME PLATING CO INC** **RCRA NonGen / NLR** **1000181167**
South **330 W 13TH ST** **FINDS** **NYD001233295**
1/8-1/4 **NEW YORK, NY 10014** **ECHO**
0.198 mi.
1046 ft. **Site 4 of 4 in cluster BC**

Relative: **Higher**
Actual: **19 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	SPECTRANOME PLATING CO INC
Handler Address:	330 W 13TH ST
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYD001233295
Contact Name:	CHARLES CAMPANA
Contact Address:	W 13TH ST
Contact City,State,Zip:	NEW YORK, NY 10014
Contact Telephone:	212-620-4300
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 13TH ST
Mailing City,State,Zip:	NEW YORK, NY 10014
Owner Name:	CHARLES CAMPANA
Owner Type:	Private
Operator Name:	CHARLES CAMPANA
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

SPECTRANOME PLATING CO INC (Continued) **1000181167**

Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F008
Waste Description:	PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.
Waste Code:	F009
Waste Description:	SPENT STRIPPING AND CLEANING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.
Waste Code:	P029
Waste Description:	COPPER CYANIDE (OR) COPPER CYANIDE CU(CN)
Waste Code:	P104

SPECTRANOME PLATING CO INC (Continued) **1000181167**

Waste Description: SILVER CYANIDE (OR) SILVER CYANIDE AG(CN)

Waste Code: P106
Waste Description: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Waste Code: P121
Waste Description: ZINC CYANIDE (OR) ZINC CYANIDE ZN(CN)2

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CHARLES CAMPANA
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CHARLES CAMPANA
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CHARLES CAMPANA
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name:	SPECTRANOME PLATING CO INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

SPECTRANOME PLATING CO INC (Continued) **1000181167**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SPECTRANOME PLATING CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800818
Handler Name: SPECTRANOME PLATING CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 332813
NAICS Description: ELECTROPLATING, PLATING, POLISHING, ANODIZING, AND COLORING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004332801

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

SPECTRANOME PLATING CO INC (Continued) **1000181167**

ECHO:
- Envid: 1000181167
- Registry ID: 110004332801
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004332801
- Name: SPECTRANOME PLATING CO INC
- Address: 330 W 13TH ST
- City,State,Zip: NEW YORK, NY 10014

AO721 **CON EDISON** **NY MANIFEST** **S118463906**
ENE **322 W 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.199 mi.
1051 ft. **Site 12 of 12 in cluster AO**

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:
- Name: CON EDISON
- Address: 322 W 23RD ST
- City,State,Zip: NEW YORK, NY 10011
- Country: USA
- EPA ID: NYP004858801
- Facility Status: Not reported
- Location Address 1: 322 W 23RD ST
- Code: BP
- Location Address 2: SB 4218
- Total Tanks: Not reported
- Location City: NEW YORK
- Location State: NY
- Location Zip: 10011
- Location Zip 4: Not reported

NY MANIFEST:
- EPAID: NYP004858801
- Mailing Name: CON EDISON
- Mailing Contact: DENNIS HUACON
- Mailing Address 1: 4 IRVING PL 15TH FL
- Mailing Address 2: Not reported
- Mailing City: NEW YORK
- Mailing State: NY
- Mailing Zip: 10003
- Mailing Zip 4: Not reported
- Mailing Country: USA
- Mailing Phone: 2124603770

NY MANIFEST:
- Document ID: Not reported
- Manifest Status: Not reported
- seq: Not reported
- Year: 2018
- Trans1 State ID: NJ0000027193
- Trans2 State ID: Not reported
- Generator Ship Date: 10/23/2015
- Trans1 Recv Date: 10/23/2015
- Trans2 Recv Date: Not reported
- TSD Site Recv Date: 10/23/2015
- Part A Recv Date: Not reported
- Part B Recv Date: Not reported
- Generator EPA ID: NYP004858801

CON EDISON (Continued) **S118463906**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014085581JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AW722 **SINO REALTY REALTY** **NY LTANKS** **S100145554**
East **204 8TH AVENUE** **NY Spills** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.200 mi.
1055 ft. **Site 4 of 9 in cluster AW**

Relative: **Higher**

Actual: **21 ft.**

LTANKS:

Name:	UNKNOWN APARTMNT BUILDING
Address:	204 8TH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	8905180 / 1997-09-15
Facility ID:	8905180
Site ID:	304456
Spill Date:	1989-08-25
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1989-08-25

SINO REALTY REALTY (Continued) **S100145554**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-09-01
Spill Record Last Update:	2004-03-25
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	274947
DEC Memo:	""
Remarks:	"TWO 275 GALLON TANKS LEAKING. NYFD ATTEMPTING TO PLUG LEAK."

All Materials:

Site ID:	304456
Operable Unit ID:	932917
Operable Unit:	01
Material ID:	559415
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	SINO REALTY REALTY
Address:	204 8TH AVENUE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9414845 / 1995-02-24
Facility ID:	9414845
Facility Type:	ER
DER Facility ID:	185084
Site ID:	223922
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	3101
Spill Date:	1995-02-11
Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	1995-02-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck

SINO REALTY REALTY (Continued) **S100145554**

Spill Notifier:	Responsible Party
Cleanup Ceased:	1995-02-24
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-17
Spill Record Last Update:	2004-03-25
Spiller Name:	Not reported
Spiller Company:	A. RUSSELL /PETRO
Spiller Address:	6-16 19TH AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY "
Remarks:	""

All Materials:

Site ID:	223922
Operable Unit ID:	1012302
Operable Unit:	01
Material ID:	373571
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

BD723 **CON EDISON** **NJ MANIFEST** **S120671360**
East **258 W 20TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.201 mi.
1063 ft. **Site 1 of 9 in cluster BD**

Relative:
Higher

Actual:
22 ft.

NJ MANIFEST:

EPA Id:	NYP004777918
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002611822GBF

CON EDISON (Continued) **S120671360**

EPA ID:	NYP004777918
Date Shipped:	5/2/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

BD724 **CON EDISON** **RCRA NonGen / NLR** **1019902794**
East **258 W 20TH ST** **NYP004777918**
1/8-1/4 **NEW YORK, NY 10011**
0.201 mi.
1063 ft. **Site 2 of 9 in cluster BD**

Relative: **Higher**
Actual: **22 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150502
Handler Name:	CON EDISON	
Handler Address:		258 W 20TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004777918
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770

CON EDISON (Continued) **1019902794**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

CON EDISON (Continued) **1019902794**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150502
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150502
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

BD725 **CON EDISON** **NY MANIFEST** **S119075042**
East **258 W 20TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.201 mi.
1063 ft. **Site 3 of 9 in cluster BD**

Relative:
Higher

Actual:
22 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	258 W 20TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004777918
Facility Status:	Not reported
Location Address 1:	250 W 20TH ST
Code:	BP
Location Address 2:	M 57361
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004777918
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/02/2015
Trans1 Recv Date:	05/02/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/05/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004777918
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002611822GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S119075042**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AV726 **CON EDISON SERVICE BOX: 39343** **RCRA NonGen / NLR** **1016449918**
SSW **13 LITTLE WEST 12TH ST** **NY MANIFEST** **NYP004249569**
1/8-1/4 **NEW YORK, NY 10014**
0.201 mi.
1063 ft. **Site 4 of 8 in cluster AV**

Relative: **Lower**
Actual: **13 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130317
Handler Name:	CON EDISON SERVICE BOX: 39343
Handler Address:	13 LITTLE WEST 12TH ST
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYP004249569
Contact Name:	JUAN RODRIGUEZ
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	347-865-5931
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported

CON EDISON SERVICE BOX: 39343 (Continued) **1016449918**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON SERVICE BOX: 39343 (Continued) **1016449918**

Historic Generators:

Receive Date:		20130217
Handler Name:	CON EDISON SERVICE BOX:	39343
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20130317
Handler Name:	CON EDISON SERVICE BOX:	39343
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	13 LITTLE WEST 12TH ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004249569
Facility Status:	Not reported
Location Address 1:	13 LITTLE W 12TH ST
Code:	BP
Location Address 2:	SERV BOX 39343
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004249569

CON EDISON SERVICE BOX: 39343 (Continued) **1016449918**

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/17/2013
Trans1 Recv Date:	02/17/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/19/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004249569
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840395JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON SERVICE BOX: 39343 (Continued) **1016449918**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

AV727 **CON EDISON - 12TH ST** **PA MANIFEST** **S118888906**
SSW **13 LITTLE W 12TH ST** **N/A**
1/8-1/4 **NY, NY 10014**
0.201 mi.
1063 ft. **Site 5 of 8 in cluster AV**

Relative: **Lower**
Actual: **13 ft.**

Manifest Details:

Year:	2015
Manifest Number:	002659512GBF
Manifest Type:	TSD Copy
Generator EPA Id:	NYP004713335
Generator Date:	01/09/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Cargo tanks (tank trucks)
Waste Quantity:	1000
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

AQ728 **305 W 13 ST** **NY AST** **A100433595**
South **305 WEST 13TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.202 mi.
1068 ft. **Site 5 of 8 in cluster AQ**

Relative: **Higher**
Actual: **21 ft.**

AST:

Name:	305 W 13 ST
Address:	305 WEST 13TH STREET
City,State,Zip:	NEW YORK, NY 10014
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-267953
Program Type:	PBS
UTM X:	584116.25877
UTM Y:	4510316.94072
Expiration Date:	08/24/2022

305 W 13 ST (Continued) **A100433595**

Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 11143
Affiliation Type: Facility Operator
Company Name: 305 W 13 ST
Contact Type: Not reported
Contact Name: SHERMAN BERISHA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 640-8645
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2017-02-15

Site Id: 11143
Affiliation Type: Emergency Contact
Company Name: SUPREME COMPANY I LLC % MANOCHERIAN BROTHERS
Contact Type: Not reported
Contact Name: SHERMAN BERIISHA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 640-8645
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2017-02-15

Site Id: 11143
Affiliation Type: Mail Contact
Company Name: SUPREME COMPANY I LLC
Contact Type: Not reported
Contact Name: MS.
Address1: % MANOCHERIAN BROTHERS
Address2: 150 EAST 58TH STREET - 28TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10022
Country Code: 001
Phone: (212) 355-4900
EMail: LSEIGEL@MANOCHERIANBROTHERS.COM
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-09-18

Site Id: 11143
Affiliation Type: Facility Owner
Company Name: SUPREME COMPANY I LLC % MANOCHERIAN BROTHERS
Contact Type: PROPERTY MANAGER

305 W 13 ST (Continued) **A100433595**

Contact Name:	LORI SEIGEL
Address1:	150 EAST 58TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(212) 355-4900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-09-18

Tank Info:

Tank Number:	001
Tank Id:	13452
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	08/27/1997
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/12/2015
Register:	True
Modified By:	DAFRANCI
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	266797

Equipment Records:

K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I01 - Overfill - Float Vent Valve

305 W 13 ST (Continued) **A100433595**

B01 - Tank External Protection - Painted/Asphalt Coating
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
G02 - Tank Secondary Containment - Vault (w/access)
E00 - Piping Secondary Containment - None
A01 - Tank Internal Protection - Epoxy Liner
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/07/2016
Capacity Gallons:	4000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DAFRANCI
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

BD729 **CON EDISON - MANHOLE 57361** **NY MANIFEST** **S123692169**
East **256 W 20TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.202 mi.
1069 ft. **Site 4 of 9 in cluster BD**

Relative: **Higher**
Actual: **22 ft.**

NY MANIFEST:

Name:	CON EDISON - MANHOLE 57361
Address:	256 W 20TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004854937
Facility Status:	Not reported
Location Address 1:	256 W 20TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004854937
Mailing Name:	CON EDISON - MANHOLE 57361
Mailing Contact:	ANNAMARIE MOYLAN
Mailing Address 1:	4 IRVING PLACE 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA

CON EDISON - MANHOLE 57361 (Continued) **S123692169**

Mailing Phone: 2124602278

AY730 **BERMUDA MOTOR CAR RENTING CO** **NY UST** **U001839677**
NW **537 WEST 20TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.203 mi.
1071 ft. **Site 5 of 11 in cluster AY**

Relative:
Lower

Actual:
7 ft.

UST:

Name:	BERMUDA MOTOR CAR RENTING CO
Address:	537 WEST 20TH STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-349402 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583807.83301
UTM Y:	4511108.97432
Site Type:	Unknown

Affiliation Records:

Site Id:	17200
Affiliation Type:	Facility Owner
Company Name:	ROBERT A VERDI
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	537 W 20TH ST
Address2:	Not reported
City:	N Y C
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 249-8400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	17200
Affiliation Type:	Mail Contact
Company Name:	ROBERT A VERDI
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	537 W 20TH ST
Address2:	Not reported
City:	N Y C
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 249-8400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	17200

BERMUDA MOTOR CAR RENTING CO (Continued) **U001839677**

Affiliation Type:	Facility Operator
Company Name:	BERMUDA MOTOR CAR RENTING CO
Contact Type:	Not reported
Contact Name:	ROBERT A VERDI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 249-8400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	17200
Affiliation Type:	Emergency Contact
Company Name:	ROBERT A VERDI
Contact Type:	Not reported
Contact Name:	ROBERT A VERDI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 249-8400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	33495
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

D00 - Pipe Type - No Piping

BERMUDA MOTOR CAR RENTING CO (Continued) **U001839677**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number: 002
Tank ID: 33496
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D00 - Pipe Type - No Piping
I04 - Overfill - Product Level Gauge (A/G)

Tank Number: 003
Tank ID: 33497
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported

BERMUDA MOTOR CAR RENTING CO (Continued) **U001839677**

Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Number: 004
Tank ID: 47613
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D00 - Pipe Type - No Piping
I04 - Overfill - Product Level Gauge (A/G)

BB731 **SPILL NUMBER 9912064** **NY LTANKS** **S104620801**
SSE **96 8TH AVE** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.204 mi.
1076 ft. **Site 8 of 24 in cluster BB**

Relative:
Higher

Actual:
22 ft.

LTANKS:
Name: SPILL NUMBER 9912064
Address: 96 8TH AVE
City,State,Zip: MANHATTAN, NY
Spill Number/Closed Date: 9912064 / 2003-07-24
Facility ID: 9912064

SPILL NUMBER 9912064 (Continued) **S104620801**

Site ID:	158669
Spill Date:	2000-01-19
Spill Cause:	Tank Overfill
Spill Source:	Commercial Vehicle
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2000-01-19
CID:	388
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-01-19
Spill Record Last Update:	2003-07-24
Spiller Name:	PHILIP CAPUTO
Spiller Company:	ECONOMY FUEL
Spiller Address:	354 HUMBOLDT ST
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	(718) 599-5100
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	134070
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND 212 627-5264, OWNER HOME. 212 243-9946, WORK."
Remarks:	"CALLER REPORTS CUSTOMER OVERORDERED AND NO VENT ALARM ON TANK, CAUSING 10-12 GALLONS TO SPILL TO BASEMENT. HAS BEEN CONTAINED. TRUCK EN ROUTE FOR CLEANUP TO PUMP OUT TANK."

All Materials:

Site ID:	158669
Operable Unit ID:	1090754
Operable Unit:	01
Material ID:	293960
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	12.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BE732 **CON EDISON SERVICE BOX: 45850** **RCRA NonGen / NLR** **1016150111**
South **13TH AVE & GANSEVOORT ST** **NY MANIFEST** **NYP004287827**
1/8-1/4 **NEW YORK, NY 10014**
0.205 mi.
1080 ft. **Site 1 of 10 in cluster BE**

Relative: **Higher**

Actual: **20 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20170728
Handler Name:	CON EDISON SERVICE BOX:	45850
Handler Address:		13TH AVE & GANSEVOORT ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004287827
Contact Name:		BENJAMIN BAMONTE
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-894-9549
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 45850 (Continued) **1016150111**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180118
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130208
Handler Name: CON EDISON SERVICE BOX:	45850
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20170728
Handler Name: CON EDISON SERVICE BOX:	45850
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No

CON EDISON SERVICE BOX: 45850 (Continued) **1016150111**

Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	13TH AVE & GANSEVOORT ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004287827
Facility Status:	Not reported
Location Address 1:	13TH AVE & GANSEVOORT ST
Code:	BP
Location Address 2:	SERV BOX 45850
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004287827
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/08/2013
Trans1 Recv Date:	02/08/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/11/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004287827

CON EDISON SERVICE BOX: 45850 (Continued) **1016150111**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010408731JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AR733 **CON EDISON** **NY MANIFEST** **S117564479**
SSW **7 WEST LITTLE W 12TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.205 mi.
1080 ft. **Site 9 of 14 in cluster AR**

Relative:
Higher

Actual:
14 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	7 WEST LITTLE W 12TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004255949
Facility Status:	Not reported
Location Address 1:	7 LITTLE W 120TH ST
Code:	BP
Location Address 2:	SERV BOX 39344
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

CON EDISON (Continued) **S117564479**

NY MANIFEST:

EPAID:	NYP004255949
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/19/2013
Trans1 Recv Date:	02/19/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004255949
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840418JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S117564479**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AR734 **CON EDISON SERVICE BOX: 39344** **RCRA NonGen / NLR** **1016449946**
SSW **7 WEST LITTLE W 12TH ST** **NYP004255949**
1/8-1/4 **NEW YORK, NY 10011**
0.205 mi.
1080 ft. **Site 10 of 14 in cluster AR**

Relative: **Higher**
Actual: **14 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130319
Handler Name:	CON EDISON SERVICE BOX:	39344
Handler Address:		7 WEST LITTLE W 12TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004255949
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---

CON EDISON SERVICE BOX: 39344 (Continued) **1016449946**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130219
Handler Name: CON EDISON SERVICE BOX:	39344
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130319
Handler Name: CON EDISON SERVICE BOX:	39344
Federal Waste Generator Description:	Not a generator, verified

CON EDISON SERVICE BOX: 39344 (Continued) **1016449946**

State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AV735 **CON EDISON SERVICE BOX: 55818** **RCRA NonGen / NLR** **1016450722**
SW **41 LITTLE WEST 12TH ST OPPOSITE** **NY MANIFEST** **NYP004297495**
1/8-1/4 **NEW YORK, NY 10014**
0.205 mi.
1080 ft. **Site 6 of 8 in cluster AV**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20130501
Handler Name: CON EDISON SERVICE BOX: 55818
Handler Address: 41 LITTLE WEST 12TH ST OPPOSITE
Handler City,State,Zip: NEW YORK, NY 10014
EPA ID: NYP004297495
Contact Name: BENJAMIN BAMONTE
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-894-9549
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: OPERATING SUPERVISOR
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY
State District: NYSDEC R2
Mailing Address: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Owner Name: Not reported
Owner Type: Not reported
Operator Name: Not reported
Operator Type: Not reported
Short-Term Generator Activity: No
Importer Activity: No

CON EDISON SERVICE BOX: 55818 (Continued) **1016450722**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:
Receive Date: 20130401

CON EDISON SERVICE BOX: 55818 (Continued) **1016450722**

Handler Name: CON EDISON SERVICE BOX: 55818
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130501
Handler Name: CON EDISON SERVICE BOX: 55818
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 41 LITTLE WEST 12TH ST OPPOSIT
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYP004297495
Facility Status: Not reported
Location Address 1: OPP 41-49 LITTLE W 12TH
Code: BP
Location Address 2: SERV BOX 55818
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004297495
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR

CON EDISON SERVICE BOX: 55818 (Continued) **1016450722**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/01/2013
Trans1 Recv Date:	04/01/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/02/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004297495
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010456750JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AT736 **CON EDISON** **NY MANIFEST** **S116551779**
SE **263 W 16 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.205 mi.
1081 ft. **Site 20 of 23 in cluster AT**

Relative:
Higher

Actual:
22 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	263 W 16 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004503421
Facility Status:	Not reported
Location Address 1:	263 W 16 ST
Code:	BP
Location Address 2:	SB2611
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004503421
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRIVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/17/2014
Trans1 Recv Date:	04/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004503421
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416706GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S116551779**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AW737 **CON EDISON** **NY MANIFEST** **S117067279**
East **214-212 W 15 ST & 8TH AV** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.205 mi.
1081 ft. **Site 5 of 9 in cluster AW**

Relative: **Higher**
Actual: **21 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	214-212 W 15 ST & 8TH AV
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004600391
Facility Status:	Not reported
Location Address 1:	214-212 W 15 ST & 8TH AV
Code:	BP
Location Address 2:	SB2612
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004600391
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S117067279**

Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/18/2014
Trans1 Recv Date:	07/18/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/22/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004600391
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002422104GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AZ738 **301 WEST 22ND ST** **NY AST** **U003383520**
ENE **301 WEST 22ND ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.205 mi.
1085 ft. **Site 2 of 21 in cluster AZ**

Relative:
Higher

Actual:
21 ft.

AST:

Name:	301 WEST 22ND ST
Address:	301 WEST 22ND ST
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-046906
Program Type:	PBS
UTM X:	584499.31714
UTM Y:	4510927.45690
Expiration Date:	12/30/2026
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	697
Affiliation Type:	Facility Owner
Company Name:	FELDS REALTY LLC
Contact Type:	MANAGING MEMBER
Contact Name:	ZEV FELDSTEIN
Address1:	301 WEST 22ND STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 989-0955
EMail:	ZEVFELD@GMAIL.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-10-13

Site Id:	697
Affiliation Type:	Mail Contact
Company Name:	FELDS REALTY CO
Contact Type:	Not reported
Contact Name:	ZEV FELDSTEIN
Address1:	301 WEST 22ND STREET
Address2:	Not reported
City:	NEW YORK,
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 989-0955
EMail:	ZEVFELD@GMAIL.COM
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2006-09-29

Site Id:	697
Affiliation Type:	Facility Operator
Company Name:	301 WEST 22ND ST
Contact Type:	Not reported
Contact Name:	DRITAN TONY DOBI

301 WEST 22ND ST (Continued) **U003383520**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 989-0955
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2006-09-29

Site Id:	697
Affiliation Type:	Emergency Contact
Company Name:	FELDS REALTY LLC
Contact Type:	Not reported
Contact Name:	ZEV FELDSTEIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 744-8631
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2006-09-29

Tank Info:

Tank Number:	001
Tank Id:	1609
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

	I04 - Overfill - Product Level Gauge (A/G)
	J02 - Dispenser - Suction Dispenser
	H99 - Tank Leak Detection - Other
	G03 - Tank Secondary Containment - Vault (w/o access)
	L09 - Piping Leak Detection - Exempt Suction Piping
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1971
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported

301 WEST 22ND ST (Continued) **U003383520**

Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)

AT739 **THE GRAND CHELSEA CONDOMINIUM** **NY AST** **A100177835**
SE **270 WEST 17TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.206 mi.
1089 ft. **Site 21 of 23 in cluster AT**

Relative:
Higher

Actual:
22 ft.

AST:

Name:	THE GRAND CHELSEA CONDOMINIUM
Address:	270 WEST 17TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-600846
Program Type:	PBS
UTM X:	584360.02764
UTM Y:	4510534.78686
Expiration Date:	07/29/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	22818
Affiliation Type:	Facility Owner
Company Name:	THE GRAND CHELSEA CONDOMINIUM % FIRST SERVICE RES
Contact Type:	MANAIGN AGENT
Contact Name:	ISAH IBRAHAM
Address1:	622 THIRD AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 634-8911
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-08-22

Site Id:	22818
Affiliation Type:	Mail Contact
Company Name:	FIRST SERVICE RESIDENTIAL NY
Contact Type:	Not reported
Contact Name:	GRAND CHELSEA CONDO
Address1:	622 THIRD AVENUE
Address2:	14 PL COMPLIANCE DEPT
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 634-8900
EMail:	COMPLIANCE.NY@FSRESIDENTIAL.COM

THE GRAND CHELSEA CONDOMINIUM (Continued) **A100177835**

Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-08-22

Site Id:	22818
Affiliation Type:	Facility Operator
Company Name:	THE GRAND CHELSEA CONDOMINIUM
Contact Type:	Not reported
Contact Name:	ANGEL OLVARRIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 645-6547
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-08-22

Site Id:	22818
Affiliation Type:	Emergency Contact
Company Name:	THE GRAND CHELSEA CONDOMINIUM % FIRST SERVICE RES
Contact Type:	Not reported
Contact Name:	ISAH IBRAHAM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 634-8900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-08-22

Tank Info:

Tank Number:	1
Tank Id:	44030
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser

THE GRAND CHELSEA CONDOMINIUM (Continued) **A100177835**

	L00 - Piping Leak Detection - None
	G02 - Tank Secondary Containment - Vault (w/access)
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	07/15/1997
Capacity Gallons:	15000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	08/22/2017
Material Name:	#2 fuel oil (on-site consumption)

BB740 **MR CLEAN** **RCRA NonGen / NLR** **1000107355**
SSE **92 8TH AVE** **NY MANIFEST** **NYD986872299**
1/8-1/4 **NEW YORK, NY 10011**
0.207 mi.
1091 ft. **Site 9 of 24 in cluster BB**

Relative: **Higher**
Actual: **22 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	MR CLEAN	
Handler Address:		92 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYD986872299
Contact Name:		Not reported
Contact Address:		8TH AVE
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		8TH AVE
Mailing City,State,Zip:		NEW YORK, NY 10011
Owner Name:		FOWLER LYNN CORP
Owner Type:		Private
Operator Name:		FOWLER LYNN CORP
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No

MR CLEAN (Continued) **1000107355**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	F001
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING:

MR CLEAN (Continued) **1000107355**

TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator: Owner
Owner/Operator Name: FOWLER LYNN CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: FOWLER LYNN CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: FOWLER LYNN CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

MR CLEAN (Continued) **1000107355**

Historic Generators:

Receive Date:		19990708
Handler Name:	MR CLEAN	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20060101
Handler Name:	MR CLEAN	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20070101
Handler Name:	MR CLEAN	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		19880713
Handler Name:	MR CLEAN	
Federal Waste Generator Description:		Large Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

MR CLEAN (Continued) **1000107355**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: MR DRYCLEAN
Address: 92 8TH AVE
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYD986872299
Facility Status: Not reported
Location Address 1: 92 EIGHTH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986872299
Mailing Name: MR DRYCLEAN
Mailing Contact: MR DRYCLEAN
Mailing Address 1: 92 EIGHTH ST
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10011
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2126775890

BB741 **ULTRA CLEANERS INC - MR DRY CLEAN** **RCRA NonGen / NLR** **1000352349**
SSE **92 8TH AVE** **FINDS** **NYD982282204**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.207 mi.
1091 ft. **Site 10 of 24 in cluster BB**

Relative: **Higher**
Actual: **22 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20070101
Handler Name: ULTRA CLEANERS INC - MR DRY CLEAN
Handler Address: 92 8TH AVE
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYD982282204
Contact Name: Not reported
Contact Address: 8TH AVE
Contact City,State,Zip: NEW YORK, NY 10011
Contact Telephone: Not reported
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02

ULTRA CLEANERS INC - MR DRY CLEAN (Continued) **1000352349**

Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	8TH AVE
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	ULTRA CLEANERS INC
Owner Type:	Private
Operator Name:	ULTRA CLEANERS INC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No

ULTRA CLEANERS INC - MR DRY CLEAN (Continued) **1000352349**

Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ULTRA CLEANERS INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ULTRA CLEANERS INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ULTRA CLEANERS INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported

ULTRA CLEANERS INC - MR DRY CLEAN (Continued) **1000352349**

Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19990708
Handler Name: ULTRA CLEANERS INC - MR DRY CLEAN
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: ULTRA CLEANERS INC - MR DRY CLEAN
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ULTRA CLEANERS INC - MR DRY CLEAN
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19871120
Handler Name: ULTRA CLEANERS INC - MR DRY CLEAN
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

ULTRA CLEANERS INC - MR DRY CLEAN (Continued) **1000352349**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004420261

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000352349
Registry ID: 110004420261
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004420261
Name: ULTRA CLEANERS INC - MR DRY CLEAN
Address: 92 8TH AVE
City,State,Zip: NEW YORK, NY 10011

AS742 **CON EDISON - SERVICE BOX 39341** **RCRA-LQG** **1014395641**
SW **51 LITTLE W12TH ST.** **NY MANIFEST** **NYP004171062**
1/8-1/4 **NEW YORK, NY 10014**
0.207 mi.
1091 ft. **Site 10 of 11 in cluster AS**

Relative: **Lower**
Actual: **10 ft.**

RCRA-LQG:
Date Form Received by Agency: 20100323
Handler Name: CON EDISON - SERVICE BOX 39341
Handler Address: 51 LITTLE W12TH ST.
Handler City,State,Zip: NEW YORK, NY 10014
EPA ID: NYP004171062
Contact Name: FRANKLYN MURRAY
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-2808
Contact Fax: Not reported
Contact Email: MURRAYFR@CONED.COM
Contact Title: Not reported
EPA Region: 02

CON EDISON - SERVICE BOX 39341 (Continued) **1014395641**

Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2009
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	4 IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No

CON EDISON - SERVICE BOX 39341 (Continued) **1014395641**

Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2009

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20090605
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20090605
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20100323
Handler Name:	CON EDISON - SERVICE BOX 39341
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON - SERVICE BOX 39341 (Continued) **1014395641**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20090605
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	51 LITTLE W12TH ST.
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004171062
Facility Status:	Not reported
Location Address 1:	51 LITTLE W12TH ST.
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004171062
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	CONSOLIDATED EDISON
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON - SERVICE BOX 39341 (Continued) **1014395641**

Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/05/2009
Trans1 Recv Date:	06/05/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/05/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004171062
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003532073JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	4000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AS743 **CON EDISON - SERVICE BOX 39341** **NJ MANIFEST** **S120665694**
SW **51 LITTLE W12TH ST.** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.207 mi.
1091 ft. **Site 11 of 11 in cluster AS**

Relative:
Lower

Actual:
10 ft.

NJ MANIFEST:

EPA Id:	NYP004171062
Mail Address:	4 IRVING PLACE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	FRANKLYN MURRAY
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	003532073JJK
EPA ID:	NYP004171062
Date Shipped:	06/05/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/05/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/05/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON - SERVICE BOX 39341 (Continued) **S120665694**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	4000 P

AY744 **540 WEST 21ST STREET** **NY VCP** **S125317147**
NNW **540 WEST 21ST STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.207 mi.
1095 ft. **Site 6 of 11 in cluster AY**

Relative: **Lower**
Actual: **7 ft.**

VCP NYC:

Project ID:	11TMP0164M,11EHAN164M,18CVCP057M
Name:	540 WEST 21ST STREET
Address:	540 WEST 21ST STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Manhattan
BBL:	1.00692005310069E+39
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Construction
Latitude:	40.74697
Longitude:	-74.006475
Postcode:	4
Community Board:	3
Council District:	99
Census Tract:	1000000
BIN:	1006920053
NTA:	Hudson Yards-Chelsea-Flatiron-Union Square

AY745 **540 W 21ST ST HOLDINGS LLC** **RCRA NonGen / NLR** **1024892061**
NNW **540-558 W 21ST ST** **NYR000236521**
1/8-1/4 **NEW YORK, NY 10011**
0.207 mi.
1095 ft. **Site 7 of 11 in cluster AY**

Relative: **Lower**
Actual: **7 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20190503
Handler Name:	540 W 21ST ST HOLDINGS LLC
Handler Address:	540-558 W 21ST ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYR000236521
Contact Name:	NOAM TELTCH
Contact Address:	W 21ST ST
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

540 W 21ST ST HOLDINGS LLC (Continued) **1024892061**

Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 21ST ST
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported

540 W 21ST ST HOLDINGS LLC (Continued) **1024892061**

Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20221228
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	540 W 21ST STREET HOLDINGS LLC
Legal Status:	Private
Date Became Current:	20140130
Date Ended Current:	Not reported
Owner/Operator Address:	548 W 21ST ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	917-388-2423
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	NOAM@CASCO-RE.COM

Owner/Operator Indicator:	Operator
Owner/Operator Name:	540 W 21ST STREET HOLDINGS LLC
Legal Status:	Private
Date Became Current:	20140130
Date Ended Current:	Not reported
Owner/Operator Address:	548 W 21ST ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	917-388-2423
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	NOAM@CASCO-RE.COM

Historic Generators:

Receive Date:	20190503
Handler Name: 540 W 21ST ST HOLDINGS LLC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

540 W 21ST ST HOLDINGS LLC (Continued) **1024892061**

Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20180612
Handler Name: 540 W 21ST ST HOLDINGS LLC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 238910
NAICS Description: SITE PREPARATION CONTRACTORS

NAICS Code: 531312
NAICS Description: NONRESIDENTIAL PROPERTY MANAGERS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AY746 **540 W 21ST ST HOLDINGS LLC** **NY MANIFEST** **S122483161**
NNW **540-558 W 21ST ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.207 mi.
1095 ft. **Site 8 of 11 in cluster AY**

Relative:
Lower

Actual:
7 ft.

NY MANIFEST:
Name: 540 W 21ST ST HOLDINGS LLC
Address: 540-558 W 21ST ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYR000236521
Facility Status: Not reported
Location Address 1: 540-558 W 21ST ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000236521
Mailing Name: 540 W 21ST ST HOLDINGS LLC
Mailing Contact: 540 W 21ST ST HOLDINGS LLC
Mailing Address 1: 540-558 W 21ST ST

540 W 21ST ST HOLDINGS LLC (Continued) **S122483161**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

BF747 **CON EDISON SERVICE BOX: 3024** **RCRA NonGen / NLR** **1016967649**
SE **273 W 17TH ST** **NY MANIFEST** **NYP004412474**
1/8-1/4 **NEW YORK, NY 10011**
0.208 mi.
1097 ft. **Site 1 of 12 in cluster BF**

Relative: **Higher**

Actual: **22 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140205
Handler Name:	CON EDISON SERVICE BOX:	3024
Handler Address:		273 W 17TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004412474
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported

CON EDISON SERVICE BOX: 3024 (Continued) **1016967649**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140105
Handler Name: CON EDISON SERVICE BOX:	3024
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140205

CON EDISON SERVICE BOX: 3024 (Continued) **1016967649**

Handler Name: CON EDISON SERVICE BOX: 3024
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 273 W 17TH ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004412474
Facility Status: Not reported
Location Address 1: 273 W 17TH ST
Code: BP
Location Address 2: SB3024
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004412474
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported

CON EDISON SERVICE BOX: 3024 (Continued) **1016967649**

Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/05/2014
Trans1 Recv Date:	01/05/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004412474
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002328516GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BE748 **M DISTRICT 2/4/5 GARAGE** **NY AST** **U003074861**
South **2 GANSEVOORT STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.208 mi.
1098 ft. **Site 2 of 10 in cluster BE**

Relative: AST:
Higher

Name:	M DISTRICT 2/4/5 GARAGE
Address:	2 GANSEVOORT STREET
City,State,Zip:	NEW YORK, NY 10014
Region:	STATE
DEC Region:	2

Actual:
20 ft.

M DISTRICT 2/4/5 GARAGE (Continued) **U003074861**

Site Status:	Unregulated/Closed
Facility Id:	2-455768
Program Type:	PBS
UTM X:	584131.43557
UTM Y:	4510308.20211
Expiration Date:	N/A
Site Type:	Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:

Site Id:	20062
Affiliation Type:	Facility Operator
Company Name:	M DISTRICT 2/4/5 GARAGE
Contact Type:	Not reported
Contact Name:	GARAGE SUPERVISOR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 807-8525
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2013-02-26

Site Id:	20062
Affiliation Type:	Facility Owner
Company Name:	NYC DEPARTMENT OF SANITATION
Contact Type:	PROJECT EXECUTIVE
Contact Name:	CHRIS SANDERS
Address1:	125 WORTH STREET - ROOM 823B
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10013
Country Code:	001
Phone:	(646) 885-4856
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-03-06

Site Id:	20062
Affiliation Type:	Mail Contact
Company Name:	NYC DEPT. OF SANITATION
Contact Type:	Not reported
Contact Name:	GERALD CARANNANTE
Address1:	125 WORTH STREET
Address2:	ROOM 823B
City:	NEW YORK
State:	NY
Zip Code:	10013
Country Code:	001
Phone:	(646) 885-4856
EMail:	GCARANN@DSNY.NYC.GOV
Fax Number:	Not reported
Modified By:	LNROSARI

M DISTRICT 2/4/5 GARAGE (Continued) **U003074861**

Date Last Modified: 2016-01-19

Site Id: 20062
Affiliation Type: Emergency Contact
Company Name: NYC DEPARTMENT OF SANITATION
Contact Type: Not reported
Contact Name: BUREAU OF CLEANING & COLLECTION
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 885-5051
EMail: Not reported
Fax Number: Not reported
Modified By: MXAJOKU
Date Last Modified: 2015-11-18

Tank Info:

Tank Number: 11
Tank Id: 227737
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 01/01/2000
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 12/18/2015
Register: True
Modified By: HDDUPIGN
Last Modified: 04/14/2017
Material Name: waste oil/used oil

M DISTRICT 2/4/5 GARAGE (Continued) **U003074861**

Tank Number:	12
Tank Id:	227738
Material Code:	0015
Common Name of Substance:	Motor Oil

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/2000
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/18/2015
Register:	True
Modified By:	HDDUPIGN
Last Modified:	04/14/2017
Material Name:	motor oil

Tank Number:	13
Tank Id:	227739
Material Code:	0015
Common Name of Substance:	Motor Oil

Equipment Records:

E00 - Piping Secondary Containment - None
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J03 - Dispenser - Gravity
D00 - Pipe Type - No Piping

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron

M DISTRICT 2/4/5 GARAGE (Continued) **U003074861**

Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/2000
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/18/2015
Register:	True
Modified By:	HDDUPIGN
Last Modified:	04/14/2017
Material Name:	motor oil

Tank Number:	14
Tank Id:	227740
Material Code:	0015
Common Name of Substance:	Motor Oil

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/2000
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/01/2013
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	motor oil

Tank Number:	15
Tank Id:	248881

Equipment Records:

E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating

M DISTRICT 2/4/5 GARAGE (Continued) **U003074861**

A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/2013
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/18/2015
Register:	True
Modified By:	HDDUPIGN
Last Modified:	04/14/2017
Material Name:	motor oil
Tank Number:	16
Tank Id:	249736

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/29/2013
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/18/2015
Register:	True
Modified By:	HDDUPIGN
Last Modified:	04/14/2017
Material Name:	motor oil

M DISTRICT 2/4/5 GARAGE (Continued) **U003074861**

Tank Number: 3
Tank Id: 36206
Material Code: 0015
Common Name of Substance: Motor Oil

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
J03 - Dispenser - Gravity
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1972
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 04/01/2013
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: motor oil

Tank Number: 4
Tank Id: 36207
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

E00 - Piping Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
J00 - Dispenser - None
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron

M DISTRICT 2/4/5 GARAGE (Continued) **U003074861**

Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1972
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/18/2015
Register:	True
Modified By:	HDDUPIGN
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

Tank Number:	5
Tank Id:	36208
Material Code:	0010
Common Name of Substance:	Hydraulic Oil

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1972
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/18/2015
Register:	True
Modified By:	HDDUPIGN
Last Modified:	04/14/2017
Material Name:	hydraulic oil

Tank Number:	6
Tank Id:	36209
Material Code:	0010
Common Name of Substance:	Hydraulic Oil

Equipment Records:

E00 - Piping Secondary Containment - None

M DISTRICT 2/4/5 GARAGE (Continued) **U003074861**

J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1972
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/18/2015
Register:	True
Modified By:	HDDUPIGN
Last Modified:	04/14/2017
Material Name:	hydraulic oil

BE749 **M DISTRICT 2/4/5 GARAGE** **NY UST** **U004063472**
South **2 GANSEVOORT STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.208 mi.
1098 ft. **Site 3 of 10 in cluster BE**

Relative:
Higher

Actual:
20 ft.

UST:

Name:	M DISTRICT 2/4/5 GARAGE
Address:	2 GANSEVOORT STREET
City,State,Zip:	NEW YORK, NY 10014
Id/Status:	2-455768 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584131.43557
UTM Y:	4510308.20211
Site Type:	Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:

Site Id:	20062
Affiliation Type:	Facility Operator
Company Name:	M DISTRICT 2/4/5 GARAGE
Contact Type:	Not reported
Contact Name:	GARAGE SUPERVISOR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

M DISTRICT 2/4/5 GARAGE (Continued) **U004063472**

Phone:	(212) 807-8525
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2013-02-26

Site Id:	20062
Affiliation Type:	Facility Owner
Company Name:	NYC DEPARTMENT OF SANITATION
Contact Type:	PROJECT EXECUTIVE
Contact Name:	CHRIS SANDERS
Address1:	125 WORTH STREET - ROOM 823B
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10013
Country Code:	001
Phone:	(646) 885-4856
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-03-06

Site Id:	20062
Affiliation Type:	Mail Contact
Company Name:	NYC DEPT. OF SANITATION
Contact Type:	Not reported
Contact Name:	GERALD CARANNANTE
Address1:	125 WORTH STREET
Address2:	ROOM 823B
City:	NEW YORK
State:	NY
Zip Code:	10013
Country Code:	001
Phone:	(646) 885-4856
EMail:	GCARANN@DSNY.NYC.GOV
Fax Number:	Not reported
Modified By:	LNROSARI
Date Last Modified:	2016-01-19

Site Id:	20062
Affiliation Type:	Emergency Contact
Company Name:	NYC DEPARTMENT OF SANITATION
Contact Type:	Not reported
Contact Name:	BUREAU OF CLEANING & COLLECTION
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 885-5051
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXAJOKU
Date Last Modified:	2015-11-18

M DISTRICT 2/4/5 GARAGE (Continued) **U004063472**

Tank Info:

Tank Number:	001
Tank ID:	276648
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	05/18/2018
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	LXZIELIN
Last Modified:	08/06/2018

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None

Tank Number:	002
Tank ID:	276649
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	05/18/2018
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	LXZIELIN
Last Modified:	08/06/2018

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None

M DISTRICT 2/4/5 GARAGE (Continued) **U004063472**

G00 - Tank Secondary Containment - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None

Tank Number:	007
Tank ID:	66881
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	5000
Install Date:	Not reported
Date Tank Closed:	09/01/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Number:	008
Tank ID:	225218
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2500
Install Date:	10/02/2007
Date Tank Closed:	09/29/2016
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2710
Common Name of Substance:	Biodiesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	DAFRANCI

M DISTRICT 2/4/5 GARAGE (Continued) **U004063472**

Last Modified: 04/14/2017

Equipment Records:

B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 009
Tank ID: 225219
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2500
Install Date: 10/02/2007
Date Tank Closed: 09/29/2016
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2710
Common Name of Substance: Biodiesel

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: D
Modified By: DAFRANCI
Last Modified: 04/14/2017

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

Tank Number: 010
Tank ID: 225220
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 10/02/2007

M DISTRICT 2/4/5 GARAGE (Continued) **U004063472**

Date Tank Closed: 09/29/2016
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: D
Modified By: DAFRANCI
Last Modified: 04/14/2017

Equipment Records:

I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
E04 - Piping Secondary Containment - Double walled UG
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 1
Tank ID: 36204
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 12/01/1982
Date Tank Closed: 08/29/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 21
Date Test: 07/25/2003
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F05 - Pipe External Protection - Jacketed

M DISTRICT 2/4/5 GARAGE (Continued) **U004063472**

I04 - Overfill - Product Level Gauge (A/G)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	2
Tank ID:	36205
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	12/01/1982
Date Tank Closed:	08/29/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	21
Date Test:	07/25/2003
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F05 - Pipe External Protection - Jacketed
I04 - Overfill - Product Level Gauge (A/G)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	M5-1
Tank ID:	228104
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	600
Install Date:	06/27/2007
Date Tank Closed:	09/29/2016
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0015
Common Name of Substance:	Motor Oil
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	DAFRANCI
Last Modified:	04/14/2017

Equipment Records:

M DISTRICT 2/4/5 GARAGE (Continued) **U004063472**

G04 - Tank Secondary Containment - Double-Walled (Underground)
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off

Tank Number:	M5-2
Tank ID:	228103
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	600
Install Date:	06/27/2007
Date Tank Closed:	09/29/2016
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0010
Common Name of Substance:	Hydraulic Oil
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	DAFRANCI
Last Modified:	04/14/2017

Equipment Records:

I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
E04 - Piping Secondary Containment - Double walled UG
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	M5-3
Tank ID:	228105
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	600
Install Date:	06/27/2007
Date Tank Closed:	09/29/2016

M DISTRICT 2/4/5 GARAGE (Continued) **U004063472**

Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0015
Common Name of Substance: Motor Oil

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: D
Modified By: DAFRANCI
Last Modified: 04/14/2017

Equipment Records:

K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E04 - Piping Secondary Containment - Double walled UG
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
C03 - Pipe Location - Aboveground/Underground Combination
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: M5-4
Tank ID: 228106
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 06/27/2007
Date Tank Closed: 09/29/2016
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: D
Modified By: DAFRANCI
Last Modified: 04/14/2017

Equipment Records:

B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
J00 - Dispenser - None
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

M DISTRICT 2/4/5 GARAGE (Continued) **U004063472**

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)

BG750 **CON EDISON** **NY MANIFEST** **S117058735**
ENE **324-22 W 23RD ST & 9TH AVE E O** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.208 mi.
1100 ft. **Site 1 of 4 in cluster BG**

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	324-22 W 23RD ST & 9TH AVE E O
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004508685
Facility Status:	Not reported
Location Address 1:	324 W 23 ST & 9TH AVE
Code:	BP
Location Address 2:	SB 4218
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004508685
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/23/2014
Trans1 Recv Date:	04/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004508685
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported

CON EDISON (Continued) **S117058735**

Manifest Tracking Number:	002416642GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BG751 **CON EDISON** **NY MANIFEST** **S117067575**
ENE **FO 324 W 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.208 mi.
1100 ft. **Site 2 of 4 in cluster BG**

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FO 324 W 23RD ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004605911
Facility Status:	Not reported
Location Address 1:	FO 324 W 23RD ST
Code:	BP
Location Address 2:	SB 4218
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004605911
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING

CON EDISON (Continued) **S117067575**

Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/23/2014
Trans1 Recv Date:	07/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004605911
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504476GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BH752 **NYCTA - 14TH ST STATION** **RCRA-VSQG** **1000981362**
SSE **14TH ST & 8TH AVE** **NY MANIFEST** **NY0000973719**
1/8-1/4 **NEW YORK, NY 10011** **NJ MANIFEST**
0.210 mi.
1107 ft. **Site 1 of 19 in cluster BH**

Relative: **Higher**
Actual: **22 ft.**

RCRA-VSQG:

Date Form Received by Agency:		20070101
Handler Name:	NYCTA - 14TH ST STATION	
Handler Address:		14TH ST & 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NY0000973719
Contact Name:		HOWARD MATZA
Contact Address:		JAY ST ROOM 809
Contact City,State,Zip:		BROOKLYN, NY 11201
Contact Telephone:		718-243-4581
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Other
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		JAY ST ROOM 809
Mailing City,State,Zip:		BROOKLYN, NY 11201
Owner Name:		NEW YORK TRANSIT AUTHORITY
Owner Type:		Other
Operator Name:		NEW YORK TRANSIT AUTHORITY
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

NYCTA - 14TH ST STATION (Continued) **1000981362**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NEW YORK TRANSIT AUTHORITY
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	370 JAY ST ROOM 809
Owner/Operator City,State,Zip:	BROOKLYN, NY 11201
Owner/Operator Telephone:	718-243-4581
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NEW YORK TRANSIT AUTHORITY
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	370 JAY ST ROOM 809
Owner/Operator City,State,Zip:	BROOKLYN, NY 11201

NYCTA - 14TH ST STATION (Continued) **1000981362**

Owner/Operator Telephone: 718-243-4581
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NEW YORK TRANSIT AUTHORITY
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 370 JAY ST ROOM 809
Owner/Operator City,State,Zip: BROOKLYN, NY 11201
Owner/Operator Telephone: 718-243-4581
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20060101
Handler Name: NYCTA - 14TH ST STATION
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYCTA - 14TH ST STATION
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19941212
Handler Name: NYCTA - 14TH ST STATION
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

NYCTA - 14TH ST STATION (Continued) **1000981362**

Receive Date:	19960320
Handler Name:	14TH ST STATION / NYCT
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	561599
NAICS Description:	ALL OTHER TRAVEL ARRANGEMENT AND RESERVATION SERVICES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	NYCTA
Address:	14TH ST & 8TH AVE
City,State,Zip:	NEW YORK, NY 10011-0000
Country:	USA
EPA ID:	NY0000973719
Facility Status:	Not reported
Location Address 1:	14TH ST & 8TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NY0000973719
Mailing Name:	NYCTA
Mailing Contact:	MNARK ERMANN
Mailing Address 1:	370 JAY ST RM 809
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11201
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183304581

NJ MANIFEST:

NYCTA - 14TH ST STATION (Continued) **1000981362**

EPA Id:	NY0000973719
Mail Address:	370 JAY ST
Mail City/State/Zip:	BROOKLYN 11201
Facility Phone:	7183304581
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	NJA5075210
EPA ID:	NY0000973719
Date Shipped:	04/28/2004
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/28/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/28/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05170422
Was Load Rejected:	BROOKLYN 11201
Reason Load Was Rejected:	Not reported

NYCTA - 14TH ST STATION (Continued) **1000981362**

Manifest Number:	NJA5009774
EPA ID:	NY0000973719
Date Shipped:	02/19/2004
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/19/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/19/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	03230425
Was Load Rejected:	BROOKLYN 11201
Reason Load Was Rejected:	Not reported

BH753 **CON EDISON** **NY MANIFEST** **S117739803**
SSE **8TH AVE & W 14TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.210 mi.
1107 ft. **Site 2 of 19 in cluster BH**

Relative: **Higher**
Actual: **22 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	8TH AVE & W 14TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004729406
Facility Status:	Not reported
Location Address 1:	8 AVE & W 14 ST
Code:	BP

CON EDISON (Continued) **S117739803**

Location Address 2:	MH32033
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004729406
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	02/10/2015
Trans1 Recv Date:	02/10/2015
Trans2 Recv Date:	02/13/2015
TSD Site Recv Date:	02/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004729406
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610456GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000

CON EDISON (Continued) **S117739803**

Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BH754 **CON EDISON** **NY MANIFEST** **S118091256**
SSE **8TH AVE & 14TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.210 mi.
1107 ft. **Site 3 of 19 in cluster BH**

Relative:
Higher

Actual:
22 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	8TH AVE & 14TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004789400
Facility Status:	Not reported
Location Address 1:	8TH AVE & 14TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004789400
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/03/2015
Trans1 Recv Date:	06/03/2015
Trans2 Recv Date:	Not reported

CON EDISON (Continued) **S118091256**

TSD Site Recv Date:	06/04/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004789400
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002614280GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BH755 **CON EDISON** **RCRA NonGen / NLR** **1018278183**
SSE **8TH AVE & W 14TH ST** **FINDS** **NYP004729406**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.210 mi.
1107 ft. **Site 4 of 19 in cluster BH**

Relative:
Higher

Actual:
22 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20150210
Handler Name:	CON EDISON	
Handler Address:		8TH AVE & W 14TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004729406
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported

CON EDISON (Continued) **1018278183**

Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported

CON EDISON (Continued) **1018278183**

Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150210
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150210
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID:	110067700722

CON EDISON (Continued) **1018278183**

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018278183
Registry ID:	110067700722
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067700722
Name:	CON EDISON
Address:	8TH AVE & W 14TH ST
City,State,Zip:	NEW YORK, NY 10011

BH756 **CON EDISON** **NJ MANIFEST** **S120667073**
SSE **8TH AVE & W 14TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.210 mi.
1107 ft. **Site 5 of 19 in cluster BH**

Relative:
Higher

Actual:
22 ft.

NJ MANIFEST:

EPA Id:	NYP004729406
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610456GBF
EPA ID:	NYP004729406
Date Shipped:	2/10/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

CON EDISON (Continued) **S120667073**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

BH757 **CON EDISON** **NJ MANIFEST** **S120672363**
SSE **8TH AVE & 14TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.210 mi.
1107 ft. **Site 6 of 19 in cluster BH**

Relative:
Higher

Actual:
22 ft.

NJ MANIFEST:

EPA Id:	NYP004789400
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002614280GBF
EPA ID:	NYP004789400

CON EDISON (Continued) **S120672363**

Date Shipped:	6/3/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

BH758 **CON EDISON** **RCRA NonGen / NLR** **1019325036**
SSE **8TH AVE & 14TH ST** **NYP004789400**
1/8-1/4 **NEW YORK, NY 10011**
0.210 mi.
1107 ft. **Site 7 of 19 in cluster BH**

Relative: RCRA NonGen / NLR:
Higher

Actual: Date Form Received by Agency:		20150603
22 ft. Handler Name:	CON EDISON	
Handler Address:		8TH AVE & 14TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004789400
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported

CON EDISON (Continued) **1019325036**

Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A

CON EDISON (Continued) **1019325036**

Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20150603
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20150603
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20160205
Handler Name:	CON EDISON - TRANSFORMER MANHOLE 1644
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY

CON EDISON (Continued) **1019325036**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150603
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150603
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

BH759 **CON EDISON** **NY MANIFEST** **S117066770**
SSE **14 ST & 8TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.210 mi.
1107 ft. **Site 8 of 19 in cluster BH**

Relative: Higher
Actual: 22 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	14 ST & 8TH AVE
City,State,Zip:	NEW YORK, NY 10014

CON EDISON (Continued) **S117066770**

Country: USA
EPA ID: NYP004594628
Facility Status: Not reported
Location Address 1: 14 ST & 8TH AVE
Code: BP
Location Address 2: SB32030
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004594628
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/13/2014
Trans1 Recv Date: 07/13/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/15/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004594628
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002608346GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported

CON EDISON (Continued) **S117066770**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	700
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AQ760 **CON EDISON - TRANSFORMER MANHOLE 2791** **RCRA-LQG** **1024890481**
SSE **73 8TH AVE** **NYP004852667**
1/8-1/4 **NEW YORK, NY 10014**
0.210 mi.
1109 ft. **Site 6 of 8 in cluster AQ**

Relative: **Higher**

Actual: **22 ft.**

RCRA-LQG:

Date Form Received by Agency:	20180410
Handler Name:	CON EDISON - TRANSFORMER MANHOLE 2791
Handler Address:	73 8TH AVE
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYP004852667
Contact Name:	ALYSSA SOTTO
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No

CON EDISON - TRANSFORMER MANHOLE 2791 (Continued) **1024890481**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

CON EDISON - TRANSFORMER MANHOLE 2791 (Continued) **1024890481**

Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170211
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170211
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180410
Handler Name: CON EDISON - TRANSFORMER MANHOLE 2791
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AQ761 **CON EDISON - TRANSFORMER MANHOLE 2791** **NJ MANIFEST** **S123565207**
SSE **73 8TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.210 mi.
1109 ft. **Site 7 of 8 in cluster AQ**

Relative:
Higher

Actual:
22 ft.

NJ MANIFEST:

EPA Id:	NYP004852667
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	ALYSSA SOTTO
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002832326GBF
EPA ID:	NYP004852667
Date Shipped:	10/13/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON - TRANSFORMER MANHOLE 2791 (Continued) **S123565207**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AQ762 **CON EDISON** **NY MANIFEST** **S121967380**
SSE **73 8TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.210 mi.
1109 ft. **Site 8 of 8 in cluster AQ**

Relative: **Higher**
Actual: **22 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	73 8TH AVE
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004852667
Facility Status:	Not reported
Location Address 1:	73 8TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004852667
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

AY763 **535 EAST 21ST STREET** **NY LTANKS** **S104275516**
NNW **535 EAST 21ST STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.210 mi.
1111 ft. **Site 9 of 11 in cluster AY**

Relative: **Lower**
Actual: **7 ft.**

LTANKS:

Name:	535 EAST 21ST STREET
Address:	535 EAST 21ST STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8803752 / 1993-02-25
Facility ID:	8803752
Site ID:	81225

535 EAST 21ST STREET (Continued) **S104275516**

Spill Date:	1988-07-29
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	1993-02-25
SWIS:	2401
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1988-07-29
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-08-02
Spill Record Last Update:	1998-07-20
Spiller Name:	Not reported
Spiller Company:	HARRY SILVERSTEIN
Spiller Address:	429 MAYFAIR DRIVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	75165
DEC Memo:	""
Remarks:	"4K TANK FAILED AN INITIAL SYSTEM- PETRO TITE TEST WITH A GROSS LEAK, WILL EXCAVATE, ISOLATE AND RETEST."

All TTF:

Facility ID:	8803752
Spill Number:	8803752
Spill Tank Test:	1534375
Site ID:	81225
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	81225
Operable Unit ID:	918900
Operable Unit:	01
Material ID:	459286
Material Code:	0002A

535 EAST 21ST STREET (Continued) **S104275516**

Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AZ764 **LUIS PHILLIP CLEANERS** **RCRA NonGen / NLR** **1004756634**
ENE **320 W 23RD ST** **ICIS** **NYD981083371**
1/8-1/4 **NEW YORK, NY 10011** **US AIRS**
0.211 mi. **FINDS**
1113 ft. **Site 3 of 21 in cluster AZ** **ECHO**

Relative: **Higher**
Actual: **20 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	ROYAL CHOICE FRENCH CLEANERS
Handler Address:	320 W 23RD ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYD981083371
Contact Name:	YOUNG DO CHOI
Contact Address:	W 23RD ST
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	212-691-9310
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 23RD ST
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	YOUNG DO CHOI - ROYAL CHOICE FRENCH CLNR
Owner Type:	Private
Operator Name:	YOUNG DO CHOI - ROYAL CHOICE FRENCH CLNR
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported

LUIS PHILLIP CLEANERS (Continued) **1004756634**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D007
Waste Description:	CHROMIUM
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE
Waste Code:	D040
Waste Description:	TRICHLORETHYLENE

LUIS PHILLIP CLEANERS (Continued) **1004756634**

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	YOUNG DO CHOI - ROYAL CHOICE FRENCH CLNR
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	320 W 23RD ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	212-691-9310
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	YOUNG DO CHOI - ROYAL CHOICE FRENCH CLNR
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	320 W 23RD ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	212-691-9310
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	YOUNG DO CHOI - ROYAL CHOICE FRENCH CLNR
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	320 W 23RD ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	212-691-9310
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name:	ROYAL CHOICE FRENCH CLEANERS
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

LUIS PHILLIP CLEANERS (Continued) **1004756634**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ROYAL CHOICE FRENCH CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960411
Handler Name: ROYAL CHOICE FRENCH CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

ICIS:
Enforcement Action ID: NY000A0000262050030400304
FRS ID: 110001605362
Action Name: LUIS PHILLIP CLEANERS 360611111700304
Facility Name: LUIS PHILLIP CLEANERS
Facility Address: 320 W 23RD ST
NEW YORK, NY 10011
Enforcement Action Type: Notice of Violation
Facility County: BRONX
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7216

LUIS PHILLIP CLEANERS (Continued) **1004756634**

Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.745635
Longitude in Decimal Degrees: -73.999348
Permit Type Desc: Not reported
Program System Acronym: NY0000002620500304
Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: 02-1999-1251
FRS ID: 110001605362
Action Name: ROYAL CHOICE FRENCH DRY CLEANERS
Facility Name: ROYAL CHOICE FRENCH CLEANERS
Facility Address: 320 W 23RD ST
NEW YORK CITY, NY 100112201
Enforcement Action Type: CAA 113D1 Action For Penalty
Facility County: NEW YORK
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 113D1
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.745543
Longitude in Decimal Degrees: -73.999087
Permit Type Desc: Not reported
Program System Acronym: 16741
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Facility Name: LUIS PHILLIP CLEANERS
Address: 320 W 23RD ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 7216

Facility Name: LUIS PHILLIP CLEANERS
Address: 320 W 23RD ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 7216

Facility Name: LUIS PHILLIP CLEANERS
Address: 320 W 23RD ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 7216

US AIRS MINOR:
Envid: 1004756634
Region Code: 02
Programmatic ID: AIR NY0000002620500304
Facility Registry ID: 110001605362
D and B Number: Not reported
Primary SIC Code: 7216

LUIS PHILLIP CLEANERS (Continued) **1004756634**

NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002620500304
Facility Registry ID: 110001605362
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1998-06-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500304
Facility Registry ID: 110001605362
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2004-05-05 00:00:00
Activity Status Date: 2004-05-05 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002620500304
Facility Registry ID: 110001605362
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-10-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:
Registry ID: 110001605362

Click Here:

Environmental Interest/Information System:
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the

LUIS PHILLIP CLEANERS (Continued) **1004756634**

estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
AIR MINOR
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004756634
Registry ID:	110001605362
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110001605362
Name:	LUIS PHILLIP CLEANERS
Address:	320 W 23RD ST
City,State,Zip:	NEW YORK, NY 10011

AZ765 **CON EDISON - SERVICE BOX 4219** **NJ MANIFEST** **S120677749**
ENE **320 W 23 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.211 mi.
1113 ft. **Site 4 of 21 in cluster AZ**

Relative:
Higher

Actual:
20 ft.

NJ MANIFEST:

EPA Id:	NYP004858819
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported

CON EDISON - SERVICE BOX 4219 (Continued) **S120677749**

Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014085582JJK
EPA ID:	NYP004858819
Date Shipped:	10/23/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AZ766 **CON EDISON** **NY MANIFEST** **S128017303**
ENE **320 W 23 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.211 mi.
1113 ft. **Site 5 of 21 in cluster AZ**

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	320 W 23 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004858819
Facility Status:	Not reported
Location Address 1:	320 W 23 ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004858819
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2015
Trans1 Recv Date:	10/23/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004858819
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014085582JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S128017303**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	10000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AZ767 **CON EDISON - SERVICE BOX 4219** **RCRA-LQG** **1019325789**
ENE **320 W 23 ST** **NYP004858819**
1/8-1/4 **NEW YORK, NY 10011**
0.211 mi.
1113 ft. **Site 6 of 21 in cluster AZ**

Relative: **Higher**

Actual: **20 ft.**

RCRA-LQG:

Date Form Received by Agency:	20160205
Handler Name:	CON EDISON - SERVICE BOX 4219
Handler Address:	320 W 23 ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004858819
Contact Name:	THERESA BURKARD
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2262
Contact Fax:	Not reported
Contact Email:	BURKARDT@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2015
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private

CON EDISON - SERVICE BOX 4219 (Continued) **1019325789**

Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161107
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON - SERVICE BOX 4219 (Continued) **1019325789**

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20151023
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20151023
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - SERVICE BOX 4219
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

CON EDISON - SERVICE BOX 4219 (Continued) **1019325789**

Evaluation Action Summary:
Evaluations: No Evaluations Found

AZ768 **LUIS PHILLIP CLEANERS** **NY MANIFEST** **S128017217**
ENE **320 W 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.211 mi.
1113 ft. **Site 7 of 21 in cluster AZ**

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:

Name:	LUIS PHILLIP CLEANERS
Address:	320 W 23RD ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYD981083371
Facility Status:	Not reported
Location Address 1:	320 WEST 23RD ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD981083371
Mailing Name:	LUIS PHILLIP CLEANERS
Mailing Contact:	LUIS PHILLIP CLEANERS
Mailing Address 1:	320 WEST 23RD ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2126919310

AZ769 **ROYAL CHICE FRENCH/LUIS PHILLIP/CLNERS** **NY DRYCLEANERS** **S110247826**
ENE **320 WEST 23RD STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.211 mi.
1113 ft. **Site 8 of 21 in cluster AZ**

Relative:
Higher

Actual:
20 ft.

DRYCLEANERS:

Name:	ROYAL CHICE FRENCH/LUIS PHILLIP/CLNERS
Address:	320 WEST 23RD STREET
City,State,Zip:	NEW YORK, NY 10011
Facility ID:	2-6205-00304
Phone Number:	212-691-9310
Region:	Not reported
Registration Effective Date:	N/A
Inspection Date:	2022-10-03 00:00:00
Install Date:	Not reported

ROYAL CHICE FRENCH/LUIS PHILLIP/CLNERS (Continued) **S110247826**

Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Y
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

BB770 **CON EDISON** **NY MANIFEST** **S118463842**
SSE **262 W 15TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.211 mi.
1113 ft. **Site 11 of 24 in cluster BB**

Relative:
Higher

Actual:
22 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	262 W 15TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004857827
Facility Status:	Not reported
Location Address 1:	262 W 15TH ST
Code:	BP
Location Address 2:	SB 2606
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004857827
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/2015
Trans1 Recv Date:	10/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004857827
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **S118463842**

TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014087612JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BB771 **CON EDISON** **RCRA NonGen / NLR** **1012185389**
SSE **78 8TH AVE** **NY MANIFEST** **NYP004161949**
1/8-1/4 **NEW YORK, NY 10023**
0.211 mi.
1114 ft. **Site 12 of 24 in cluster BB**

Relative: **Higher**
Actual: **22 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		78 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10023
EPA ID:		NYP004161949
Contact Name:		DAVID DUKE
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		917-559-8971
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported

CON EDISON (Continued) **1012185389**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

CON EDISON (Continued) **1012185389**

Handler Date of Last Change:	20160815
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20081021
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	78 8TH AVE
City,State,Zip:	NEW YORK, NY 10023
Country:	USA
EPA ID:	NYP004161949
Facility Status:	Not reported
Location Address 1:	78th & 8th AVE

CON EDISON (Continued) **1012185389**

Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004161949
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/21/2008
Trans1 Recv Date: 10/21/2008
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/23/2008
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004161949
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: 001432777FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

CON EDISON (Continued) **1012185389**

Quantity:	125
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	3
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BB772 **80 8TH AVENUE** **NY UST** **U004109418**
SSE **80 EIGHTH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.212 mi.
1119 ft. **Site 13 of 24 in cluster BB**

Relative: **Higher**

Actual: **22 ft.**

UST:

Name:	80 8TH AVENUE
Address:	80 EIGHTH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-111953 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	09/19/2022
UTM X:	584247.90314
UTM Y:	4510366.17656
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	3516
Affiliation Type:	Mail Contact
Company Name:	NEWMARK GRUBB KNIGHT FRANK
Contact Type:	Not reported
Contact Name:	SAM MOHABIR
Address1:	1501 BROADWAY
Address2:	SUITE 1914
City:	NEW YORK
State:	NY
Zip Code:	10036
Country Code:	001
Phone:	(212) 354-2930
EMail:	SMOHABIR@NGKF.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2020-08-06

Site Id:	3516
Affiliation Type:	Facility Owner
Company Name:	BET-ELI CO. % NEWMARK GRUBB KNIGHT FRANK
Contact Type:	OWNER'S REP
Contact Name:	SAM MOHABIR
Address1:	1501 BROADWAY - SUITE 1914
Address2:	Not reported

80 8TH AVENUE (Continued) **U004109418**

City:	NEW YORK
State:	NY
Zip Code:	10036
Country Code:	001
Phone:	(212) 354-2930
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-08-24

Site Id:	3516
Affiliation Type:	Facility Operator
Company Name:	80 8TH AVENUE
Contact Type:	Not reported
Contact Name:	FRANK GUARINO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 929-6404
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-08-24

Site Id:	3516
Affiliation Type:	Emergency Contact
Company Name:	BET-ELI CO. % NEWMARK GRUBB KNIGHT FRANK
Contact Type:	Not reported
Contact Name:	FRANK GUARINO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 929-6404
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-08-24

Tank Info:

Tank Number:	001
Tank ID:	4978
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	10000
Install Date:	06/10/1970
Date Tank Closed:	04/22/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003

80 8TH AVENUE (Continued) **U004109418**

Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MFLEONAR
Last Modified: 08/24/2017

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

BB773 **80 8TH AVENUE** **NY AST** **A100393036**
SSE **80 EIGHTH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.212 mi.
1119 ft. **Site 14 of 24 in cluster BB**

Relative:
Higher

Actual:
22 ft.

AST:
Name: 80 8TH AVENUE
Address: 80 EIGHTH AVENUE
City,State,Zip: NEW YORK, NY 10011
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-111953
Program Type: PBS
UTM X: 584247.90314
UTM Y: 4510366.17656
Expiration Date: 09/19/2022
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 3516
Affiliation Type: Mail Contact
Company Name: NEWMARK GRUBB KNIGHT FRANK
Contact Type: Not reported
Contact Name: SAM MOHABIR
Address1: 1501 BROADWAY
Address2: SUITE 1914
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 354-2930
EMail: SMOHABIR@NGKF.COM
Fax Number: Not reported
Modified By: JSMACRI

80 8TH AVENUE (Continued) **A100393036**

Date Last Modified: 2020-08-06

Site Id: 3516
Affiliation Type: Facility Owner
Company Name: BET-ELI CO. % NEWMARK GRUBB KNIGHT FRANK
Contact Type: OWNER'S REP
Contact Name: SAM MOHABIR
Address1: 1501 BROADWAY - SUITE 1914
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 354-2930
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-08-24

Site Id: 3516
Affiliation Type: Facility Operator
Company Name: 80 8TH AVENUE
Contact Type: Not reported
Contact Name: FRANK GUARINO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 929-6404
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-08-24

Site Id: 3516
Affiliation Type: Emergency Contact
Company Name: BET-ELI CO. % NEWMARK GRUBB KNIGHT FRANK
Contact Type: Not reported
Contact Name: FRANK GUARINO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 929-6404
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-08-24

Tank Info:

Tank Number: 01A
Tank Id: 252024

80 8TH AVENUE (Continued) **A100393036**

Equipment Records:

	H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
	F00 - Pipe External Protection - None
	K00 - Spill Prevention - None
	L99 - Piping Leak Detection - Other
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	G02 - Tank Secondary Containment - Vault (w/access)
	I05 - Overfill - Vent Whistle
	I04 - Overfill - Product Level Gauge (A/G)
	C01 - Pipe Location - Aboveground
	J05 - Dispenser - On Site Heating System (Supply/Return)
	E00 - Piping Secondary Containment - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/22/2014
Capacity Gallons:	6000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	08/24/2017
Material Name:	#2 fuel oil (on-site consumption)

BB774 **NATIONAL ENVIRONMENTAL WASTE SYSTEM** **RCRA NonGen / NLR** **1000446169**
SSE **80 8TH AVE ROOM 303** **FINDS** **NYD986912475**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.212 mi.
1119 ft. **Site 15 of 24 in cluster BB**

Relative: **Higher**
Actual: **22 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	NATIONAL ENVIRONMENTAL WASTE SYSTEM
Handler Address:	80 8TH AVE ROOM 303
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYD986912475
Contact Name:	WILLIAM PARRISH
Contact Address:	8TH AVE ROOM 303
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	212-807-5704
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY

NATIONAL ENVIRONMENTAL WASTE SYSTEM (Continued) **1000446169**

State District:	NYSDEC R2
Mailing Address:	8TH AVE ROOM 303
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	WILLIAM PARRISH
Owner Type:	Private
Operator Name:	WILLIAM PARRISH
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No

NATIONAL ENVIRONMENTAL WASTE SYSTEM (Continued) **1000446169**

Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	X003
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WILLIAM PARRISH
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	WILLIAM PARRISH
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	WILLIAM PARRISH
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name:	NATIONAL ENVIRONMENTAL WASTE SYSTEM
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY

NATIONAL ENVIRONMENTAL WASTE SYSTEM (Continued) **1000446169**

Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NATIONAL ENVIRONMENTAL WASTE SYSTEM
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900911
Handler Name: NATIONAL ENVIRONMENTAL WASTE SYSTEM
Federal Waste Generator Description: Not reported
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004452645

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

NATIONAL ENVIRONMENTAL WASTE SYSTEM (Continued) **1000446169**

corrective action activities required under RCRA.

~~Click this hyperlink~~ while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000446169
Registry ID:	110004452645
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004452645
Name:	NATIONAL ENVIRONMENTAL WASTE SYSTEM
Address:	80 8TH AVE ROOM 303
City,State,Zip:	NEW YORK, NY 10011

BB775 **APARTMENT BUILDING** **NY LTANKS** **S113820429**
SSE **80 8TH AVENUE** **NY Spills** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.212 mi.
1119 ft. **Site 16 of 24 in cluster BB**

Relative:
Higher

Actual:
22 ft.

LTANKS:

Name:	APARTMENT BUILDING
Address:	80 8TH AVENUE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	1305350 / 2014-04-11
Facility ID:	1305350
Site ID:	485913
Spill Date:	2013-08-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SXMAHAT
Referred To:	Not reported
Reported to Dept:	2013-08-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-08-16
Spill Record Last Update:	2015-10-28
Spiller Name:	ROB HILL
Spiller Company:	80 8TH AVENUE
Spiller Address:	80 8TH AVENUE
Spiller County:	999
Spiller Contact:	ROB HILL
Spiller Phone:	(347) 589-0005
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	441030
DEC Memo:	"4/11/14: Mahat DEC Mahat received an email from Mr. David Chan (Rite Way) asking to close the spill. The spill was called in as a TT failure. The tank did not pass the test and it was a dry leak. Hence, the property owner decided to abandon the tank. Three samples were

APARTMENT BUILDING (Continued) **S113820429**

taken form the bottom of the tank for the conformation. Analytical report is uploaded on edocs. The analytes are below DEC guidance value. No further investigation is required by the department as per the closure letter the site is contamnination free. "

Remarks: "Tank test failure."

All Materials:

Site ID:	485913
Operable Unit ID:	1235568
Operable Unit:	01
Material ID:	2234831
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Name:	RESIDENTIAL
Address:	80 8TH AVENUE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	2110105 / 2022-03-02
Facility ID:	2110105
Facility Type:	ER
DER Facility ID:	581046
Site ID:	634141
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2022-03-02
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2022-03-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2022-03-02
Spill Record Last Update:	2022-03-03
Spiller Name:	ALEX CASTLO
Spiller Company:	UNK
Spiller Address:	80 8TH AVENUE / W 14TH
Spiller Company:	999
Contact Name:	ALEX CASTLO
DEC Memo:	"03/02/22-Hiralkumar Patel. 9:13 PM:- spoke with Alex. he inspected the site and noted oil in two sump pits and one ejector pit in

APARTMENT BUILDING (Continued) **S113820429**

building basement and oil/sheen in city sewer system outside the building. asked Alex to send pics/info to DEC Sekhon who responded to the site earlier today. 9:20 AM:- spoke with DEC Sekhon and informed him about discussion with Alex. duplicate of spill # 2110087. case closed."

Remarks: "appx 3,500 gals possible released. clean up in progress. sump pump flooded. product released to sewer plus sheen and odor. release possibly occurred at 0630 am unk."

All Materials:

Site ID:	634141
Operable Unit ID:	1381217
Operable Unit:	01
Material ID:	2395209
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AZ776 **LOUIS PHILIPPE CONDOMINIUM** **NY UST** **U004272214**
ENE **312 WEST 23RD STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.213 mi.
1122 ft. **Site 9 of 21 in cluster AZ**

Relative:
Higher

Actual:
20 ft.

UST:

Name:	LOUIS PHILIPPE CONDOMINIUM
Address:	312 WEST 23RD STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-097020 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	05/07/2022
UTM X:	584489.21972
UTM Y:	4510981.49065
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	2779
Affiliation Type:	Facility Operator
Company Name:	LOUIS PHILIPPE CONDOMINIUM
Contact Type:	Not reported
Contact Name:	CARLOS VASQUEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 468-8468
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY

LOUIS PHILIPPE CONDOMINIUM (Continued) **U004272214**

Date Last Modified: 2017-06-16

Site Id: 2779
Affiliation Type: Emergency Contact
Company Name: LOUIS PHILIPPE CONDOMINIUM
Contact Type: Not reported
Contact Name: IVY STEELE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 243-6722
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-06-12

Site Id: 2779
Affiliation Type: Mail Contact
Company Name: ABILENE, INC.
Contact Type: Not reported
Contact Name: FRANK YAN
Address1: 2402 NEPTUNE AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11224
Country Code: 001
Phone: (718) 372-4210
EMail: FRANK@ABELINEINC.COM
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2017-11-21

Site Id: 2779
Affiliation Type: Facility Owner
Company Name: LOUIS PHILIPPE CONDOMINIUM C/O BUCHBINDER & WARREN
Contact Type: Not reported
Contact Name: Not reported
Address1: ONE UNION SQUARE WEST, 4TH FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 243-6722
EMail: Not reported
Fax Number: Not reported
Modified By: MXLAY
Date Last Modified: 2017-06-16

Tank Info:

Tank Number: 001
Tank ID: 4650

LOUIS PHILIPPE CONDOMINIUM (Continued) **U004272214**

Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	5000
Install Date:	06/01/1960
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)
Tightness Test Method:	34
Date Test:	02/05/2020
Next Test Date:	02/05/2021
Pipe Model:	Not reported
Modified By:	TankSys
Last Modified:	11/16/2020

Equipment Records:

I05 - Overfill - Vent Whistle
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
L99 - Piping Leak Detection - Other
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
J05 - Dispenser - On Site Heating System (Supply/Return)

AZ777 **APT. BUILDING** **NY LTANKS** **S108765788**
ENE **312 WEST 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY**
0.213 mi.
1122 ft. **Site 10 of 21 in cluster AZ**

Relative: **Higher**
Actual: **20 ft.**

LTANKS:

Name:	APT. BUILDING
Address:	312 WEST 23RD ST
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0706771 / 2007-10-11
Facility ID:	0706771
Site ID:	387352
Spill Date:	2007-09-18
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	2007-09-18
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester

APT. BUILDING (Continued) **S108765788**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-09-18
Spill Record Last Update:	2007-10-15
Spiller Name:	Not reported
Spiller Company:	APT. BUILDING
Spiller Address:	12 WEST 23RD ST
Spiller County:	001
Spiller Contact:	MARLON JOSEPH
Spiller Phone:	(718) 624-4842
Spiller Extention:	112
DEC Region:	2
DER Facility ID:	336779
DEC Memo:	"9/19/07 Called 212-593-9100 (# on FIR) and left message for Scott Ross (contact on FIR). Mr. Ross returned my call and left a message. I called him back and he said the tank was not tested. He confirmed that the tank is 2K (consistent with registration) and is not 5K as in the spill report. He said that the tank is a concrete wrapped tank. I called Mark Salamack of Petroleum Tank Cleaners (they did the test). I left a message and requested that he call me back. M. Salamack called me back and said the technician believes the failure is in the fill line. Also he told me the address was incorrect on the Spill Report. The address is 312 NOT 12. Sent ttf letter to: Ivy Steele Chelsea London Co. c/o Buchbinder & Warren One Union Square West New York, NY 10003 Attn: Eva Matos Called Ms. Steele at 212-243-6722 and left message to call me back. Eva Matos called me back and told me the line failed and that PTC will be making the repairs. She also told me to send letter to her attention. I confirmed the mailing address with her. bf 10/9/07 Received fax from Eva Matos Letter included an invoice from PTC showing that the tank was retested and passed. Also, the fill line and vent line were replaced. No mention of contamination. I called Ms. Matos back and left a message on her voice mail. I stated that a letter is needed from PTC regarding any contamination found. Phone: 646-637-9019. bf 10/11/07 On 10/10/07, I received a letter by fax from Mark Salamack. Letter states that the failure was caused by a broken vent line. The fill line was compromised, but not broken. Both were replaced and no contamination was encountered. Tank was tightness tested on 9/27/07 and passed. NFA. bf 10/15/07 On 10/12/07, received message from Eva. She requested a call back regarding whether or not I received letter from PTC. I called her back (646-637-9019) and told her that I received the letter. bf"
Remarks:	"NONE;"

All TTF:

Facility ID:	0706771
Spill Number:	0706771
Spill Tank Test:	1764118
Site ID:	387352
Tank Number:	1
Tank Size:	5000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported

APT. BUILDING (Continued) **S108765788**

Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 387352
Operable Unit ID: 1144557
Operable Unit: 01
Material ID: 2134864
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AR778 **CON EDISON** **NY MANIFEST** **S117741049**
SSW **2 9TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10019**
0.213 mi.
1123 ft. **Site 11 of 14 in cluster AR**

Relative:
Higher

Actual:
15 ft.

NY MANIFEST:
Name: CON EDISON
Address: 2 9TH AVE
City,State,Zip: NEW YORK, NY 10019
Country: USA
EPA ID: NYP004742490
Facility Status: Not reported
Location Address 1: 2 9TH AV
Code: BP
Location Address 2: SB39619
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10019
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004742490
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

CON EDISON (Continued) **S117741049**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	03/04/2015
Trans1 Recv Date:	03/04/2015
Trans2 Recv Date:	03/06/2015
TSD Site Recv Date:	03/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004742490
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610958GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AR779 **CON EDISON** **RCRA NonGen / NLR** **1018279432**
SSW **2 9TH AVE** **FINDS** **NYP004742490**
1/8-1/4 **NEW YORK, NY 10019** **ECHO**
0.213 mi.
1123 ft. **Site 12 of 14 in cluster AR**

Relative: **Higher**
Actual: **15 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150304
Handler Name:	CON EDISON	
Handler Address:		2 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10019
EPA ID:		NYP004742490
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1018279432**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150304
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150304
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1018279432**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067690831

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018279432
Registry ID:	110067690831
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067690831
Name:	CON EDISON
Address:	2 9TH AVE
City,State,Zip:	NEW YORK, NY 10019

AW780 **224 EIGHTH AVE CORP** **NY AST** **U001835567**
East **224 8TH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.213 mi.
1124 ft. **Site 6 of 9 in cluster AW**

Relative:
Higher

Actual:
21 ft.

AST:

Name:	224 EIGHTH AVE CORP
Address:	224 8TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-256900
Program Type:	PBS
UTM X:	584498.28137
UTM Y:	4510850.35851
Expiration Date:	07/14/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

224 EIGHTH AVE CORP (Continued) **U001835567**

Site Id:	10568
Affiliation Type:	Facility Owner
Company Name:	224 EIGHTH AVENUE CORPORATION
Contact Type:	MANAGING AGENT
Contact Name:	SETH WEINSTEIN
Address1:	152 WEST 57TH STREET, 12TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10019
Country Code:	001
Phone:	(212) 262-6274
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-10-09

Site Id:	10568
Affiliation Type:	Facility Operator
Company Name:	224 EIGHTH AVE CORP
Contact Type:	Not reported
Contact Name:	AFRIM KERNAJA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 998-3220
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-10-09

Site Id:	10568
Affiliation Type:	Emergency Contact
Company Name:	224 EIGHTH AVENUE CORPORATION
Contact Type:	Not reported
Contact Name:	SETH WEINSTEIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 307-0500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-10-09

Site Id:	10568
Affiliation Type:	Mail Contact
Company Name:	ABC MANAGEMENT CORP.
Contact Type:	Not reported
Contact Name:	SETH WEINSTEIN
Address1:	152 WEST 57TH STREET

224 EIGHTH AVE CORP (Continued) **U001835567**

Address2:	12TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10019
Country Code:	001
Phone:	(212) 262-6274
EMail:	SETH@ABCMGMT.NET
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-10-18

Tank Info:

Tank Number:	01
Tank Id:	15015
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
I05 - Overfill - Vent Whistle

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/11/2004
Register:	True
Modified By:	nrlombar
Last Modified:	04/14/2017
Material Name:	#4 fuel oil (on-site consumption)

Tank Number:	02
Tank Id:	179405
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
L04 - Piping Leak Detection - Groundwater Well

224 EIGHTH AVE CORP (Continued) **U001835567**

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
C01 - Pipe Location - Aboveground
E01 - Piping Secondary Containment - Diking (AG only)
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/15/2004
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	10/09/2018
Material Name:	#4 fuel oil (on-site consumption)

AT781 **250 WEST 16TH STREET OWNERS CORP.** **NY AST** **A100173288**
SE **250 WEST 16TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.213 mi.
1124 ft. **Site 22 of 23 in cluster AT**

Relative: **Higher**
Actual: **22 ft.**

AST:

Name:	250 WEST 16TH STREET OWNERS CORP.
Address:	250 WEST 16TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-147168
Program Type:	PBS
UTM X:	584339.42143
UTM Y:	4510461.89164
Expiration Date:	08/26/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	4309
Affiliation Type:	Mail Contact
Company Name:	PLYMOUTH MGMT GROUP
Contact Type:	Not reported
Contact Name:	JACK LERNER
Address1:	1776 BROADWAY
Address2:	SUITE 1720
City:	NEW YORK
State:	NY
Zip Code:	10019
Country Code:	001

250 WEST 16TH STREET OWNERS CORP. (Continued) **A100173288**

Phone:	(212) 447-7000 11
EMail:	JLERNER@PLYMOUTHNY.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-11-22

Site Id:	4309
Affiliation Type:	Facility Operator
Company Name:	250 WEST 16TH STREET OWNERS CORP.
Contact Type:	Not reported
Contact Name:	SERGIO SIVIERA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 765-7533
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-11-22

Site Id:	4309
Affiliation Type:	Emergency Contact
Company Name:	250 WEST 16TH STREET OWNERS CORP.
Contact Type:	Not reported
Contact Name:	SERGIO SIVIERA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 765-7533
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-11-22

Site Id:	4309
Affiliation Type:	Facility Owner
Company Name:	250 WEST 16TH STREET OWNERS CORP.
Contact Type:	AGENT
Contact Name:	JACK LERNER
Address1:	250 WEST 16TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 447-7000 11
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-11-22

250 WEST 16TH STREET OWNERS CORP. (Continued) **A100173288**

Tank Info:

Tank Number:	001
Tank Id:	19277
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	I05 - Overfill - Vent Whistle
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
	B00 - Tank External Protection - None
	F00 - Pipe External Protection - None
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	C01 - Pipe Location - Aboveground
	I04 - Overfill - Product Level Gauge (A/G)
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/1973
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	11/22/2017
Material Name:	#2 fuel oil (on-site consumption)

AZ782 **CON EDISON** **NY MANIFEST** **S117067168**
ENE **237-235 W 15 ST & 8TH AV** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.213 mi.
1125 ft. **Site 11 of 21 in cluster AZ**

Relative:
Higher

Actual:
21 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	237-235 W 15 ST & 8TH AV
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004599080
Facility Status:	Not reported
Location Address 1:	237-235 W 15 ST & 8TH AV
Code:	BP
Location Address 2:	SB2602
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

CON EDISON (Continued) **S117067168**

NY MANIFEST:

EPAID:	NYP004599080
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/17/2014
Trans1 Recv Date:	07/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004599080
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002501969GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	700
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S117067168**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BA783 **CONSOLIDATED EDISON** **NY MANIFEST** **1009241333**
North **520 W 23 ST MH4171** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.213 mi.
1127 ft. **Site 9 of 16 in cluster BA**

Relative: **Lower**
Actual: **10 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	520 W 23 ST MH4171
City,State,Zip:	NEW YORK, NY 10003
Country:	USA
EPA ID:	NYP004097556
Facility Status:	Not reported
Location Address 1:	520 W 23 ST MH4171
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004097556
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

BA784 **MARAJS** **NY AST** **A100294956**
North **520 WEST 23RD STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.213 mi.
1127 ft. **Site 10 of 16 in cluster BA**

Relative: **Lower**
Actual: **10 ft.**

AST:

Name:	MARAJS
Address:	520 WEST 23RD STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609043

MARAJS (Continued) **A100294956**

Program Type: PBS
UTM X: 583988.41620
UTM Y: 4511250.76294
Expiration Date: 06/19/2023
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 30890
Affiliation Type: Facility Operator
Company Name: MARAIS
Contact Type: Not reported
Contact Name: OLIVER SIMMONS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 255-0045
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-04-09

Site Id: 30890
Affiliation Type: Emergency Contact
Company Name: MARAIS
Contact Type: Not reported
Contact Name: JAKE KUSHNER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 986-0001
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-04-09

Site Id: 30890
Affiliation Type: Facility Owner
Company Name: MARAJS
Contact Type: MANAGING DIRECTOR OF BUILDING COMPLIANCE
Contact Name: GINA FAZZALARO
Address1: 260 MADISON AVENUE, 12TH FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10016
Country Code: 001
Phone: (212) 986-0001
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-04-09

MARAJS (Continued) **A100294956**

Site Id:	30890
Affiliation Type:	Mail Contact
Company Name:	AKAM ASSOCIATES, INC.
Contact Type:	Not reported
Contact Name:	GINA FAZZALARO
Address1:	260 MADISON AVENUE, 12TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 986-0001
EMail:	AKAMNYCOMPLIANCE@AKAM.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-04-09

Tank Info:

Tank Number:	001
Tank Id:	66202
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	J02 - Dispenser - Suction Dispenser E04 - Piping Secondary Containment - Double walled UG H04 - Tank Leak Detection - Groundwater Well A01 - Tank Internal Protection - Epoxy Liner L09 - Piping Leak Detection - Exempt Suction Piping G03 - Tank Secondary Containment - Vault (w/o access) B01 - Tank External Protection - Painted/Asphalt Coating D01 - Pipe Type - Steel/Carbon Steel/Iron F01 - Pipe External Protection - Painted/Asphalt Coating H01 - Tank Leak Detection - Interstitial - Electronic Monitoring K00 - Spill Prevention - None C01 - Pipe Location - Aboveground I05 - Overfill - Vent Whistle
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/13/2002
Capacity Gallons:	7000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	04/09/2018
Material Name:	#2 fuel oil (on-site consumption)

AR785 **CON EDISON** **NY MANIFEST** **S116551130**
SSW **9TH AVE & LITTLE W 12TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.214 mi.
1130 ft. **Site 13 of 14 in cluster AR**

Relative:
Higher

Actual:
15 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	9TH AVE & LITTLE W 12TH ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004495651
Facility Status:	Not reported
Location Address 1:	9 AVE & LITTLE WEST 12 ST
Code:	BP
Location Address 2:	SB39618
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004495651
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/09/2014
Trans1 Recv Date:	04/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/15/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004495651
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407310GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S116551130**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AR786 **CON EDISON SERVICE BOX: 39618** **RCRA NonGen / NLR** **1017772605**
SSW **9TH AVE & LITTLE W 12TH ST** **FINDS** **NYP004495651**
1/8-1/4 **NEW YORK, NY 10014**
0.214 mi.
1130 ft. **Site 14 of 14 in cluster AR**

Relative: **Higher**
Actual: **15 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140509
Handler Name:	CON EDISON SERVICE BOX:	39618
Handler Address:		9TH AVE & LITTLE W 12TH ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004495651
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported

CON EDISON SERVICE BOX: 39618 (Continued) **1017772605**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON SERVICE BOX: 39618 (Continued) **1017772605**

Historic Generators:

Receive Date:		20140409
Handler Name:	CON EDISON	
Federal Waste Generator Description:		Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20140409
Handler Name:	CON EDISON	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20140509
Handler Name:	CON EDISON SERVICE BOX:	39618
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063784132

Click Here:

CON EDISON SERVICE BOX: 39618 (Continued) **1017772605**

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

BF787 **CON EDISON** **NY MANIFEST** **S117067454**
ESE **FO 252 W 18 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.214 mi.
1132 ft. **Site 2 of 12 in cluster BF**

Relative:
Higher

Actual:
22 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FO 252 W 18 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004603171
Facility Status:	Not reported
Location Address 1:	FO 252 W 18 ST
Code:	BP
Location Address 2:	SB 3267
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004603171
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/21/2014
Trans1 Recv Date:	07/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/25/2014
Part A Recv Date:	Not reported

CON EDISON (Continued) **S117067454**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004603171
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504409GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BB788 **CON EDISON** **NY MANIFEST** **S117067165**
SE **259-257 W 15 ST & 8 AV** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.215 mi.
1133 ft. **Site 17 of 24 in cluster BB**

Relative: **Higher**
Actual: **22 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	259-257 W 15 ST & 8 AV
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004599056
Facility Status:	Not reported
Location Address 1:	259-257 W 15 ST & 8 AV
Code:	BP
Location Address 2:	SB2598
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011

CON EDISON (Continued) **S117067165**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004599056
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/17/2014
Trans1 Recv Date: 07/17/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/17/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004599056
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002503157GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 700
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON (Continued) **S117067165**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BB789 **CON EDISON** **NY MANIFEST** **S118463841**
SE **259 W 15TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.215 mi.
1133 ft. **Site 18 of 24 in cluster BB**

Relative:
Higher

Actual:
22 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	259 W 15TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004857819
Facility Status:	Not reported
Location Address 1:	259 W 15TH ST
Code:	BP
Location Address 2:	SB 2598
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004857819
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/21/2015
Trans1 Recv Date:	10/21/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004857819
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S118463841**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014087611JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AZ790 **CON EDISON SERVICE BOX: 32121** **RCRA NonGen / NLR** **1017773068**
ENE **253 8TH AVE & 22ND ST N OF** **FINDS** **NYP004508461**
1/8-1/4 **NEW YORK, NY 10011**
0.215 mi.
1137 ft. **Site 12 of 21 in cluster AZ**

Relative: RCRA NonGen / NLR:
Higher

Actual: Date Form Received by Agency:		20140522
21 ft. Handler Name:	CON EDISON SERVICE BOX:	32121
Handler Address:		253 8TH AVE & 22ND ST N OF
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004508461
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported

CON EDISON SERVICE BOX: 32121 (Continued) **1017773068**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No

CON EDISON SERVICE BOX: 32121 (Continued) **1017773068**

Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140522
Handler Name: CON EDISON SERVICE BOX:	32121
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON SERVICE BOX: 32121 (Continued) **1017773068**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063760844

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AZ791 **CON EDISON - MANHOLE 32120** **RCRA-LQG** **1017773069**
ENE **8TH AVE & 22ND ST INT** **NYP004508479**
1/8-1/4 **NEW YORK, NY 10011**
0.215 mi.
1137 ft. **Site 13 of 21 in cluster AZ**

Relative: **Higher**

Actual: **21 ft.**

RCRA-LQG:

Date Form Received by Agency:	20180410
Handler Name:	CON EDISON - MANHOLE 32120
Handler Address:	8TH AVE & 22ND ST INT
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004508479
Contact Name:	ALYSSA SOTTO
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No

CON EDISON - MANHOLE 32120 (Continued) **1017773069**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

CON EDISON - MANHOLE 32120 (Continued) **1017773069**

Hazardous Waste Summary:
- Waste Code: D008
- Waste Description: LEAD

Handler - Owner Operator:
- Owner/Operator Indicator: Operator
- Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
- Legal Status: Private
- Date Became Current: 20140422
- Date Ended Current: Not reported
- Owner/Operator Address: 4 IRVING PLACE
- Owner/Operator City,State,Zip: NEW YORK, NY 10003
- Owner/Operator Telephone: 212-460-2757
- Owner/Operator Telephone Ext: Not reported
- Owner/Operator Fax: Not reported
- Owner/Operator Email: Not reported

- Owner/Operator Indicator: Owner
- Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
- Legal Status: Private
- Date Became Current: 20140422
- Date Ended Current: Not reported
- Owner/Operator Address: 4 IRVING PLACE
- Owner/Operator City,State,Zip: NEW YORK, NY 10003
- Owner/Operator Telephone: 212-460-2757
- Owner/Operator Telephone Ext: Not reported
- Owner/Operator Fax: Not reported
- Owner/Operator Email: Not reported

Historic Generators:
- Receive Date: 20180410
- Handler Name: CON EDISON - MANHOLE 32120
- Federal Waste Generator Description: Large Quantity Generator
- State District Owner: NY
- Large Quantity Handler of Universal Waste: No
- Recognized Trader Importer: No
- Recognized Trader Exporter: No
- Spent Lead Acid Battery Importer: No
- Spent Lead Acid Battery Exporter: No
- Current Record: Yes
- Non Storage Recycler Activity: No
- Electronic Manifest Broker: No

- Receive Date: 20140422
- Handler Name: CON EDISON
- Federal Waste Generator Description: Large Quantity Generator
- State District Owner: NY
- Large Quantity Handler of Universal Waste: No
- Recognized Trader Importer: No
- Recognized Trader Exporter: No
- Spent Lead Acid Battery Importer: No
- Spent Lead Acid Battery Exporter: No
- Current Record: No
- Non Storage Recycler Activity: Not reported
- Electronic Manifest Broker: Not reported

CON EDISON - MANHOLE 32120 (Continued) **1017773069**

Receive Date: 20140422
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140522
Handler Name: CON EDISON MANHOLE: 32120
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AZ792 **CON EDISON SERVICE BOX: 32122** **RCRA NonGen / NLR** **1017773067**
ENE **257 8TH AVE & 22ND ST N OF** **FINDS** **NYP004508453**
1/8-1/4 **NEW YORK, NY 10011**
0.215 mi.
1137 ft. **Site 14 of 21 in cluster AZ**

Relative: **Higher**
Actual: **21 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20140522
Handler Name: CON EDISON SERVICE BOX: 32122
Handler Address: 257 8TH AVE & 22ND ST N OF
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYP004508453
Contact Name: THOMAS TEELING
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-3770
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: SENIOR SCIENTIST

CON EDISON SERVICE BOX: 32122 (Continued) **1017773067**

EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported

CON EDISON SERVICE BOX: 32122 (Continued) **1017773067**

Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140522
Handler Name: CON EDISON SERVICE BOX: 32122	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

CON EDISON SERVICE BOX: 32122 (Continued) **1017773067**

NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063760835

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AZ793 **CON EDISON** **RCRA NonGen / NLR** **1018279618**
ENE **22ND ST & 8TH AVE SW COR** **FINDS** **NYP004744520**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.215 mi.
1137 ft. **Site 15 of 21 in cluster AZ**

Relative:
Higher

Actual:
21 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	20150306
Handler Name:	CON EDISON
Handler Address:	22ND ST & 8TH AVE SW COR
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004744520
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported

CON EDISON (Continued) **1018279618**

Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON (Continued) **1018279618**

Historic Generators:

Receive Date:	20150306
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150306
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069388120

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER
Registry ID: 110067693393

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource

CON EDISON (Continued) **1018279618**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018279618
Registry ID:	110067693393
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067693393
Name:	CON EDISON
Address:	22ND ST & 8TH AVE SW COR
City,State,Zip:	NEW YORK, NY 10011

Envid:	1018279618
Registry ID:	110069388120
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069388120
Name:	CON EDISON
Address:	22ND ST & 8TH AVE
City,State,Zip:	NEW YORK, NY 10011

AZ794 **CON EDISON** **NY MANIFEST** **S119075805**
ENE **22ND ST & 8TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.215 mi.
1137 ft. **Site 16 of 21 in cluster AZ**

Relative:
Higher

Actual:
21 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	22ND ST & 8TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004792693
Facility Status:	Not reported
Location Address 1:	W 22ND ST & 8TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004792693
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

CON EDISON (Continued) **S119075805**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/16/2015
Trans1 Recv Date:	06/16/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/24/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004792693
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610834GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AZ795 **CON EDISON** **NY MANIFEST** **S117058856**
ENE **8TH AVE & 22ND ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.215 mi.
1137 ft. **Site 17 of 21 in cluster AZ**

Relative:
Higher

Actual:
21 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	8TH AVE & 22ND ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004509931
Facility Status:	Not reported
Location Address 1:	N/E/C 22 ST & 8TH AVE
Code:	BP
Location Address 2:	SB 32125
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004509931
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/24/2014
Trans1 Recv Date:	04/24/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004509931
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416503GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117058856**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AZ796 **CON EDISON** **RCRA NonGen / NLR** **1019325080**
ENE **22ND ST & 8TH AVE** **NYP004792693**
1/8-1/4 **NEW YORK, NY 10011**
0.215 mi.
1137 ft. **Site 18 of 21 in cluster AZ**

Relative: **Higher**
Actual: **21 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150610
Handler Name:	CON EDISON	
Handler Address:		22ND ST & 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004792693
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported

CON EDISON (Continued) **1019325080**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON (Continued) **1019325080**

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150610
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150610
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - MANHOLE 57291
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150610
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

CON EDISON (Continued) **1019325080**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150610
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AZ797 **CON EDISON** **NJ MANIFEST** **S120672656**
ENE **22ND ST & 8TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.215 mi.
1137 ft. **Site 19 of 21 in cluster AZ**

Relative:
Higher

Actual:
21 ft.

NJ MANIFEST:
EPA Id: NYP004792693
Mail Address: IRVING PL 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 002614226GBF
EPA ID: NYP004792693

CON EDISON (Continued) **S120672656**

Date Shipped:	6/12/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported
Manifest Number:	002614235GBF
EPA ID:	NYP004792693
Date Shipped:	6/10/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

CON EDISON (Continued) **S120672656**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Manifest Number:	002610834GBF
EPA ID:	NYP004792693
Date Shipped:	6/16/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported

CON EDISON (Continued) **S120672656**

Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AZ798 **CON EDISON SERVICE BOX: 32125** **RCRA NonGen / NLR** **1017773214**
ENE **8TH AVE & 22ND ST** **NYP004509931**
1/8-1/4 **NEW YORK, NY 10011**
0.215 mi.
1137 ft. **Site 20 of 21 in cluster AZ**

Relative: **Higher**

Actual: **21 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140524
Handler Name:	CON EDISON SERVICE BOX:	32125
Handler Address:		8TH AVE & 22ND ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004509931
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported

CON EDISON SERVICE BOX: 32125 (Continued) **1017773214**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140424
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140424

CON EDISON SERVICE BOX: 32125 (Continued) **1017773214**

Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20140524
Handler Name: CON EDISON SERVICE BOX:	32125
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

BF799 **NYC DEPT OF EDUCATION - H S 451M - LIBERTY HIGH SC** **RCRA-SQG** **1016974993**
ESE **250 W 18TH ST** **NYR000214536**
1/8-1/4 **NEW YORK, NY 10011**
0.216 mi.
1138 ft. **Site 3 of 12 in cluster BF**

Relative: **Higher**
Actual: **22 ft.**

RCRA-SQG:

Date Form Received by Agency:	20141021
Handler Name:	NYC DEPT OF EDUCATION - H S 451M - LIBERTY HIGH SCHOOL
Handler Address:	250 W 18TH ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYR000214536
Contact Name:	ALEXANDER LEMPERT
Contact Address:	THOMSON AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-472-8501
Contact Fax:	718-472-8500
Contact Email:	ALEMPERT@NYCSCA.ORG
Contact Title:	DIRECTOR
EPA Region:	02
Land Type:	Municipal

NYC DEPT OF EDUCATION - H S 451M - LIBERTY HIGH SCHOOL (Continued) **1016974993**

Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	THOMSON AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	NYC DEPT OF EDUCATION
Owner Type:	Municipal
Operator Name:	NYC DEPT OF SCHOOL FACILITIES
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No

NYC DEPT OF EDUCATION - H S 451M - LIBERTY HIGH SCHOOL (Continued) **1016974993**

Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141204
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYC DEPT OF EDUCATION
Legal Status:	Municipal
Date Became Current:	19680108
Date Ended Current:	Not reported
Owner/Operator Address:	30-30 THOMSON AVE
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-472-8501
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYC DEPT OF SCHOOL FACILITIES
Legal Status:	Municipal
Date Became Current:	19680108
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20141021
Handler Name:	NYC DEPT OF EDUCATION - H S 451M - LIBERTY HIGH SCHOOL
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	611110
NAICS Description:	ELEMENTARY AND SECONDARY SCHOOLS

NYC DEPT OF EDUCATION - H S 451M - LIBERTY HIGH SCHOOL (Continued) **1016974993**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

BF800 **NYC DEPT OF EDUCATION - H S 451M - LIBERTY HIGH SC** **NY AST** **U003392697**
ESE **250 W 18TH ST** **NY MANIFEST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.216 mi.
1138 ft. **Site 4 of 12 in cluster BF**

Relative:
Higher

Actual:
22 ft.

AST:

Name:	LIBERTY HS - MANHATTAN M451
Address:	250 WEST 18TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-238597
Program Type:	PBS
UTM X:	584416.20097
UTM Y:	4510588.85346
Expiration Date:	10/23/2022
Site Type:	School

Affiliation Records:

Site Id:	8943
Affiliation Type:	Facility Operator
Company Name:	LIBERTY HS - MANHATTAN M451
Contact Type:	Not reported
Contact Name:	ALBERT NEGRON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 604-2160
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-11

Site Id:	8943
Affiliation Type:	Mail Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	JOSEPH YOUNGHESE
Address1:	FIELD OPERATIONS-FUEL DIVISION
Address2:	44-36 VERNON BOULEVARD
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5779

NYC DEPT OF EDUCATION - H S 451M - LIBERTY HIGH SCHOOL (Continued) **U003392697**

EMail:	JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-01-25

Site Id:	8943
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	KEN MAHADEO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 210-7918
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2021-05-05

Site Id:	8943
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	MUNENDRA SHARMA
Address1:	44-36 VERNON BOULEVARD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-07-17

Tank Info:

Tank Number:	001
Tank Id:	25110
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm

NYC DEPT OF EDUCATION - H S 451M - LIBERTY HIGH SCHOOL (Continued) **U003392697**

C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/02/1997
Capacity Gallons:	550
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	10/11/2017
Material Name:	diesel
Tank Number:	002
Tank Id:	25109
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
L00 - Piping Leak Detection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/02/1997
Capacity Gallons:	5000
Tightness Test Method:	34
Date Test:	06/18/2020
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	LABATIST
Last Modified:	07/08/2020
Material Name:	#2 fuel oil (on-site consumption)

NYC DEPT OF EDUCATION - H S 451M - LIBERTY HIGH SCHOOL (Continued) **U003392697**

Tank Number: 003
Tank Id: 260421

Equipment Records:

C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/02/1997
Capacity Gallons: 50
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MFLEONAR
Last Modified: 10/11/2017
Material Name: diesel

NY MANIFEST:
Name: NYC DEPT OF EDUCATION - H S 451M - LIBERTY HIGH SCHOOL
Address: 250 W 18TH ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYR000214536
Facility Status: Not reported
Location Address 1: 250 W 18TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000214536
Mailing Name: NYC DEPT OF EDUCATION - H S 451M - LIBERTY HIGH SCHOOL
Mailing Contact: NYC SCHOOK CONTSTRUCTION AUTHO
Mailing Address 1: 30-30 THOMPSON AVE
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101

NYC DEPT OF EDUCATION - H S 451M - LIBERTY HIGH SCHOOL (Continued) **U003392697**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7187525023

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/09/2016
Trans1 Recv Date:	03/09/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/11/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000214536
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010918415JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	23
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	B004
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BI801 **CON EDISON** **NY MANIFEST** **S117067386**
ESE **FO 272 W 19 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.216 mi.
1143 ft. **Site 1 of 5 in cluster BI**

Relative:
Higher

Actual:
22 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FO 272 W 19 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004601902
Facility Status:	Not reported
Location Address 1:	FO 272 W 19 ST
Code:	BP
Location Address 2:	SB 3454
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004601902
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/20/2014
Trans1 Recv Date:	07/20/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004601902
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002608404GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117067386**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AW802 **ENS/21 LLC** **NY AST** **A100166650**
East **264/268 WEST 21ST STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.217 mi.
1145 ft. **Site 7 of 9 in cluster AW**

Relative: **Higher**
Actual: **22 ft.**

AST:

Name:	ENS/21 LLC
Address:	264/268 WEST 21ST STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-604504
Program Type:	PBS
UTM X:	584559.10675
UTM Y:	4510770.70461
Expiration Date:	05/18/2026
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	26376
Affiliation Type:	Facility Operator
Company Name:	ENS/21 LLC
Contact Type:	Not reported
Contact Name:	TONY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

ENS/21 LLC (Continued) **A100166650**

Phone:	(999) 999-9999
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-04-28

Site Id:	26376
Affiliation Type:	Emergency Contact
Company Name:	ENS/21 LLC
Contact Type:	Not reported
Contact Name:	JON KLARISTENFELD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 518-2690 111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-04-28

Site Id:	26376
Affiliation Type:	Facility Owner
Company Name:	ENS/21 LLC
Contact Type:	DIRECTOR OF COMPLIANCE
Contact Name:	STACEY KWIATKOSKI
Address1:	801 SECOND AVENUE, SUITE 404
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 518-2690
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-03-05

Site Id:	26376
Affiliation Type:	Mail Contact
Company Name:	MD SQUARED PROPERTY GROUP, INC.
Contact Type:	Not reported
Contact Name:	COMPLIANCE DEPT.
Address1:	801 2ND AVENUE
Address2:	SUITE 404
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 518-2690
EMail:	COMPLIANCE@MD2PG.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-03-05

ENS/21 LLC (Continued) **A100166650**

Tank Info:

Tank Number:	001
Tank Id:	58026
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

	D10 - Pipe Type - Copper
	J03 - Dispenser - Gravity
	L00 - Piping Leak Detection - None
	H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
	B99 - Tank External Protection - Other
	C02 - Pipe Location - Underground/On-ground
	K00 - Spill Prevention - None
	G99 - Tank Secondary Containment - Other
	A00 - Tank Internal Protection - None
	E00 - Piping Secondary Containment - None
	F00 - Pipe External Protection - None
	I05 - Overfill - Vent Whistle
Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel Tank in Concrete
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/2006
Capacity Gallons:	1500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	03/05/2021
Material Name:	#2 fuel oil (on-site consumption)

BD803 **EIGHTH-19TH COMPANY** **NY AST** **U003384864**
ESE **259-265 WEST 19TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.217 mi.
1148 ft. **Site 5 of 9 in cluster BD**

Relative:
Higher

Actual:
22 ft.

AST:

Name:	EIGHTH-19TH COMPANY
Address:	259-265 WEST 19TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-096121
Program Type:	PBS
UTM X:	584508.10662
UTM Y:	4510643.06260
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

EIGHTH-19TH COMPANY (Continued) **U003384864**

Site Id:	2704
Affiliation Type:	Facility Owner
Company Name:	EIGHTH-19TH COMPANY
Contact Type:	DIRECTOR OF MANAGEMENT
Contact Name:	ROSEMARY PAPARO
Address1:	C/O BUCHBINDER & WARREN-ONE UNION SQUARE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 243-6722
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-06-12

Site Id:	2704
Affiliation Type:	Mail Contact
Company Name:	EIGHTH-19TH COMPANY
Contact Type:	Not reported
Contact Name:	ANDRE MOORE
Address1:	C/O BUCHBINDER & WARREN
Address2:	ONE UNION SQUARE WEST
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 243-6722
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-01-25

Site Id:	2704
Affiliation Type:	Facility Operator
Company Name:	EIGHTH-19TH COMPANY
Contact Type:	Not reported
Contact Name:	RAMON ESTRADA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 922-0212
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-06-12

Site Id:	2704
Affiliation Type:	Emergency Contact
Company Name:	EIGHTH-19TH COMPANY
Contact Type:	Not reported
Contact Name:	ANDRE MOORE
Address1:	Not reported

EIGHTH-19TH COMPANY (Continued) **U003384864**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 243-6722
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-01-25

Tank Info:

Tank Number:	001
Tank Id:	4610
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

	G02 - Tank Secondary Containment - Vault (w/access)
	I05 - Overfill - Vent Whistle
	L09 - Piping Leak Detection - Exempt Suction Piping
	H00 - Tank Leak Detection - None
	E00 - Piping Secondary Containment - None
	K00 - Spill Prevention - None
	F01 - Pipe External Protection - Painted/Asphalt Coating
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	I04 - Overfill - Product Level Gauge (A/G)
	J02 - Dispenser - Suction Dispenser
	C03 - Pipe Location - Aboveground/Underground Combination
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	06/06/1990
Capacity Gallons:	3000
Tightness Test Method:	21
Date Test:	12/18/2017
Next Test Date:	Not reported
Date Tank Closed:	12/19/2017
Register:	True
Modified By:	DAFRANCI
Last Modified:	01/25/2018
Material Name:	#2 fuel oil (on-site consumption)

BB804 **ROSAR REALTY CORP.** **NY UST** **U004341924**
SSE **258 WEST 15TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.219 mi.
1155 ft. **Site 19 of 24 in cluster BB**

Relative:
Higher

Actual:
23 ft.

UST:

Name:	ROSAR REALTY CORP.
Address:	258 WEST 15TH STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-602613 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	05/01/2026
UTM X:	584297.22150
UTM Y:	4510392.39506
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	24570
Affiliation Type:	Mail Contact
Company Name:	ROSAR REALTY CORP.
Contact Type:	SECRETARY
Contact Name:	ROCIO SANZ
Address1:	VILLAGE STATION BOX 507
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10014
Country Code:	001
Phone:	(212) 675-5097
EMail:	OFFICE@SANZMANAGEMENT.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-04-23

Site Id:	24570
Affiliation Type:	Facility Operator
Company Name:	ROSAR REALTY CORP.
Contact Type:	Not reported
Contact Name:	ROCIO SANZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 675-5097
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24570
Affiliation Type:	Emergency Contact
Company Name:	ROSAR REALTY CORP.
Contact Type:	Not reported
Contact Name:	ROCIO SANZ
Address1:	Not reported

ROSAR REALTY CORP. (Continued) **U004341924**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 675-5097
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24570
Affiliation Type:	Facility Owner
Company Name:	ROSAR REALTY CORP.
Contact Type:	SECRETARY
Contact Name:	ROCIO SANZ
Address1:	VILLAGE STATION PO BOX 507
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10014
Country Code:	001
Phone:	(212) 675-5097
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2016-05-05

Tank Info:

Tank Number:	001
Tank ID:	50724
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	2500
Install Date:	11/01/2000
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JSMACRI
Last Modified:	04/23/2021

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
J05 - Dispenser - On Site Heating System (Supply/Return)
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

ROSAR REALTY CORP. (Continued) **U004341924**

B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
L99 - Piping Leak Detection - Other
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

BB805 **258 WEST 15TH ST/MANHATTA** **NY LTANKS** **S104275528**
SSE **258 WEST 15TH STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.219 mi.
1155 ft. **Site 20 of 24 in cluster BB**

Relative:
Higher

Actual:
23 ft.

LTANKS:

Name:	258 WEST 15TH ST/MANHATTA
Address:	258 WEST 15TH STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8807781 / 1992-12-04
Facility ID:	8807781
Site ID:	241507
Spill Date:	1988-12-23
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	B3
Cleanup Ceased:	1992-12-04
SWIS:	3101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1988-12-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-12-30
Spill Record Last Update:	1992-12-04
Spiller Name:	Not reported
Spiller Company:	BELCHER FUEL OIL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	198531
DEC Memo:	""
Remarks:	"SPILL ON SIDEWALK AND IN BASEMENT, HAZMAT USING SORBENT."

All Materials:

Site ID:	241507
Operable Unit ID:	924346
Operable Unit:	01
Material ID:	452558
Material Code:	0002A
Material Name:	#4 fuel oil

258 WEST 15TH ST/MANHATTA (Continued) **S104275528**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	75.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BA806 **CON EDISON SERVICE BOX: 4164** **RCRA NonGen / NLR** **1016143191**
North **505 W 23RD ST** **FINDS** **NYP004259271**
1/8-1/4 **NEW YORK, NY 10014** **ECHO**
0.219 mi. **NY MANIFEST**
1157 ft. **Site 11 of 16 in cluster BA**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130321
Handler Name:	CON EDISON SERVICE BOX:	4164
Handler Address:		505 W 23RD ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004259271
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

CON EDISON SERVICE BOX: 4164 (Continued) **1016143191**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130221
Handler Name: CON EDISON SERVICE BOX:	4164
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130321
Handler Name: CON EDISON SERVICE BOX:	4164

CON EDISON SERVICE BOX: 4164 (Continued) **1016143191**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063898858

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016143191
Registry ID:	110063898858
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110063898858
Name:	CON EDISON SERVICE BOX: 4164
Address:	505 W 23RD ST
City,State,Zip:	NEW YORK, NY 10014

NY MANIFEST:

Name:	CON EDISON
Address:	505 W 23RD ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004259271
Facility Status:	Not reported
Location Address 1:	505 W 23RD ST
Code:	BP
Location Address 2:	SERV BOX 4164
Total Tanks:	Not reported

CON EDISON SERVICE BOX: 4164 (Continued) **1016143191**

Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004259271
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/21/2013
Trans1 Recv Date:	02/21/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/21/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004259271
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010846496JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1

CON EDISON SERVICE BOX: 4164 (Continued) **1016143191**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AT807 **253 W 16 ST** **NY UST** **U004272271**
SE **253 WEST 16TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.219 mi.
1157 ft. **Site 23 of 23 in cluster AT**

Relative:
Higher

Actual:
22 ft.

UST:

Name:	253 W 16 ST
Address:	253 WEST 16TH STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-600282 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	08/20/2026
UTM X:	584361.97796
UTM Y:	4510473.76649
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	22265
Affiliation Type:	Mail Contact
Company Name:	VANDERBILT PROPERTY MANAGEMENT
Contact Type:	AGENT
Contact Name:	STEVEN BIRBACH
Address1:	136 GLENWOOD ROAD
Address2:	P.O. BOX 401
City:	GLENWOOD LANDING
State:	NY
Zip Code:	11547
Country Code:	001
Phone:	(516) 714-4935
EMail:	STEVEB@VANDERBILTPM.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-06-10

Site Id:	22265
Affiliation Type:	Facility Operator
Company Name:	253 WEST 16 OWNERS, INC.
Contact Type:	Not reported
Contact Name:	BETH RAKE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported

253 W 16 ST (Continued) **U004272271**

Country Code:	001
Phone:	(212) 255-1945
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-06-10

Site Id:	22265
Affiliation Type:	Emergency Contact
Company Name:	253 WEST 16 OWNERS, INC.
Contact Type:	AGENT
Contact Name:	STEVEN BIRBACH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 479-9393
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-06-10

Site Id:	22265
Affiliation Type:	Facility Owner
Company Name:	253 WEST 16 OWNERS, INC.
Contact Type:	AGENT
Contact Name:	STEVEN BIRBACH
Address1:	P.O. BOX 401
Address2:	Not reported
City:	GLENWOOD LANDING
State:	NY
Zip Code:	11547
Country Code:	001
Phone:	(516) 714-4935
EMail:	STEVEB@VANDERBILTPM.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-06-10

Tank Info:

Tank Number:	001
Tank ID:	41860
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	3000
Install Date:	10/08/1930
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	-

253 W 16 ST (Continued) **U004272271**

Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	ACDANIEL
Last Modified:	06/10/2021

Equipment Records:

I05 - Overfill - Vent Whistle
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
G00 - Tank Secondary Containment - None
H08 - Tank Leak Detection - Weep holes in Vaults with no access for inspection
J05 - Dispenser - On Site Heating System (Supply/Return)
K99 - Spill Prevention - Other
L99 - Piping Leak Detection - Other
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

BJ808 **FORMER OLYMPIA GARAGE,INC** **NY UST** **U000414031**
SSW **9-19 9TH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.220 mi.
1160 ft. **Site 1 of 4 in cluster BJ**

Relative:
Higher

Actual:
14 ft.

UST:

Name:	FORMER OLYMPIA GARAGE,INC
Address:	9-19 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10014
Id/Status:	2-600640 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583889.60570
UTM Y:	4510321.52934
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	22620
Affiliation Type:	Facility Owner
Company Name:	9TH AVENUE DELAWARE OWNERS, LLC
Contact Type:	SENIOR PROJECT MANAGER, H&H BUILDERS
Contact Name:	LIDO GORI, JR
Address1:	558 HUDSON STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10014
Country Code:	001
Phone:	(212) 924-3100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-03-12

FORMER OLYMPIA GARAGE,INC (Continued) **U000414031**

Site Id:	22620
Affiliation Type:	Mail Contact
Company Name:	H&H BUILDERS, INC
Contact Type:	Not reported
Contact Name:	LIDO GORI, JR.
Address1:	511 CANAL STREET
Address2:	6TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10013
Country Code:	001
Phone:	(212) 924-3100
EMail:	LIDO@HHBUILDERS.NET
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-03-12

Site Id:	22620
Affiliation Type:	Facility Operator
Company Name:	FORMER OLYMPIA GARAGE,INC
Contact Type:	Not reported
Contact Name:	DANIEL MENDELSOHN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 924-3100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-03-12

Site Id:	22620
Affiliation Type:	Emergency Contact
Company Name:	9TH AVENUE DELAWARE OWNERS, LLC
Contact Type:	Not reported
Contact Name:	LIDO GORI, JR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 924-3100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-03-12

Tank Info:

Tank Number:	001
Tank ID:	43159
Tank Status:	Closed - Removed
Material Name:	Closed - Removed

FORMER OLYMPIA GARAGE,INC (Continued) **U000414031**

Capacity Gallons:	4000
Install Date:	12/01/1978
Date Tank Closed:	01/19/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NTFREEMA
Last Modified:	04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
G03 - Tank Secondary Containment - Vault (w/o access)
J02 - Dispenser - Suction Dispenser
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	002
Tank ID:	43160
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1978
Date Tank Closed:	01/19/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NTFREEMA
Last Modified:	04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

FORMER OLYMPIA GARAGE,INC (Continued) **U000414031**

Tank Number: 003
Tank ID: 43161
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1978
Date Tank Closed: 01/19/2015
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NTFREEMA
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

Tank Number: 004
Tank ID: 43162
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1978
Date Tank Closed: 01/19/2015
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NTFREEMA
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser

FORMER OLYMPIA GARAGE,INC (Continued) **U000414031**

B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	005
Tank ID:	43163
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1978
Date Tank Closed:	01/19/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NTFREEMA
Last Modified:	04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None

Tank Number:	006
Tank ID:	43164
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1978
Date Tank Closed:	01/19/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NTFREEMA
Last Modified:	04/14/2017

FORMER OLYMPIA GARAGE,INC (Continued) **U000414031**

Equipment Records:

B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	007
Tank ID:	255248
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/19/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NTFREEMA
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None

Tank Number:	008
Tank ID:	255249
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/19/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

FORMER OLYMPIA GARAGE,INC (Continued) **U000414031**

Pipe Model: Not reported
Modified By: NTFREEMA
Last Modified: 04/14/2017

Equipment Records:

L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

BF809 **257 W 17TH ST** **NY AST** **U003390709**
SE **257 W 17TH ST** **N/A**
1/8-1/4 **NY, NY 10011**
0.220 mi.
1161 ft. **Site 5 of 12 in cluster BF**

Relative:
Higher

Actual:
22 ft.

AST:
Name: 257 W 17TH ST
Address: 257 W 17TH ST
City,State,Zip: NY, NY 10011
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-321958
Program Type: PBS
UTM X: 584491.70708
UTM Y: 4510528.67807
Expiration Date: N/A
Site Type: Other

Affiliation Records:
Site Id: 14984
Affiliation Type: Facility Owner
Company Name: CATHOLIC BOOK PUB CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 257 W 17TH ST
Address2: Not reported
City: NY
State: NY
Zip Code: 10011
Country Code: 001
Phone: (212) 243-4515
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 14984
Affiliation Type: Mail Contact
Company Name: CATHOLIC BOOK PUBLISHING CO.

257 W 17TH ST (Continued) **U003390709**

Contact Type:	Not reported
Contact Name:	Not reported
Address1:	C/O ABC REALTY
Address2:	1775 BROADWAY #520
City:	NY
State:	NY
Zip Code:	10019
Country Code:	001
Phone:	(212) 307-0500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	14984
Affiliation Type:	Facility Operator
Company Name:	257 W 17TH ST
Contact Type:	Not reported
Contact Name:	ABC REALTY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 243-4515
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	14984
Affiliation Type:	Emergency Contact
Company Name:	CATHOLIC BOOK PUB CORP
Contact Type:	Not reported
Contact Name:	SETH WEINSTEIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 307-0500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	19861
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

257 W 17TH ST (Continued) **U003390709**

I04 - Overfill - Product Level Gauge (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1957
Capacity Gallons:	4000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/18/1996
Register:	True
Modified By:	MXLAY
Last Modified:	04/14/2017
Material Name:	diesel

BA810 **CON EDISON SERVICE BOX: 4163** **RCRA NonGen / NLR** **1016143214**
North **517 W 23RD ST** **FINDS** **NYP004259503**
1/8-1/4 **NEW YORK, NY 10014** **ECHO**
0.220 mi. **NY MANIFEST**
1161 ft. **Site 12 of 16 in cluster BA**

Relative: **Lower**
Actual: **10 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130321
Handler Name:	CON EDISON SERVICE BOX:	4163
Handler Address:		517 W 23RD ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004259503
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported

CON EDISON SERVICE BOX: 4163 (Continued) **1016143214**

Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON SERVICE BOX: 4163 (Continued) **1016143214**

Historic Generators:

Receive Date:		20130221
Handler Name:	CON EDISON SERVICE BOX:	4163
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20130321
Handler Name:	CON EDISON SERVICE BOX:	4163
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063917374

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016143214
Registry ID: 110063917374

CON EDISON SERVICE BOX: 4163 (Continued) **1016143214**

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110063917374
Name: CON EDISON SERVICE BOX: 4163
Address: 517 W 23RD ST
City,State,Zip: NEW YORK, NY 10014

NY MANIFEST:
Name: CON EDISON
Address: 517 W 23RD ST
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYP004259503
Facility Status: Not reported
Location Address 1: E 133RD ST & LOCUST AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BRONX
Location State: NY
Location Zip: 10451
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004259503
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 02/21/2013
Trans1 Recv Date: 02/21/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/21/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004259503
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 010846497JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N

CON EDISON SERVICE BOX: 4163 (Continued) **1016143214**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BH811 **CON EDISON** **NY MANIFEST** **S117537348**
SSE **259 W 14TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.220 mi.
1164 ft. **Site 9 of 19 in cluster BH**

Relative:
Higher

Actual:
23 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	259 W 14TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004699062
Facility Status:	Not reported
Location Address 1:	259 W 14TH ST
Code:	BP
Location Address 2:	V # 4155
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004699062
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003

CON EDISON (Continued) **S117537348**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	11/24/2014
Trans1 Recv Date:	11/24/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/02/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004699062
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416572GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AY812 **SYLVOR COMPANY** **NY AST** **U004048441**
NW **120-126 11TH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.221 mi.
1166 ft. **Site 10 of 11 in cluster AY**

Relative:
Lower

Actual:
5 ft.

AST:

Name:	SYLVOR COMPANY
Address:	120-126 11TH AVENUE
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-349208
Program Type:	PBS
UTM X:	584519.72838
UTM Y:	4509961.85005
Expiration Date:	N/A
Site Type:	Unknown

Affiliation Records:

Site Id:	17181
Affiliation Type:	Facility Owner
Company Name:	MEYERS REALTY CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	14 ROBIN HOOD WAY
Address2:	Not reported
City:	WESTFIELD
State:	NJ
Zip Code:	07090
Country Code:	001
Phone:	(201) 233-2334
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	17181
Affiliation Type:	Mail Contact
Company Name:	MEYERS REALTY CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	14 ROBIN HOOD WAY
Address2:	Not reported
City:	WESTFIELD
State:	NJ
Zip Code:	07090
Country Code:	001
Phone:	(201) 233-2334
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	17181
Affiliation Type:	Facility Operator
Company Name:	SYLVOR COMPANY
Contact Type:	Not reported
Contact Name:	SYLVOR CO

SYLVOR COMPANY (Continued) **U004048441**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 929-2728
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	17181
Affiliation Type:	Emergency Contact
Company Name:	MEYERS REALTY CORP
Contact Type:	Not reported
Contact Name:	C W MEYERS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(201) 233-2334
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	33420
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	J02 - Dispenser - Suction Dispenser
	I04 - Overfill - Product Level Gauge (A/G)
	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

SYLVOR COMPANY (Continued) **U004048441**

Date Tank Closed:	03/01/1993
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AY813 **HERTZ PENSKE TRUCK LEASING INC** **RCRA NonGen / NLR** **1000423668**
NNW **542 W 21ST ST** **FINDS** **NYD981563430**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.221 mi.
1166 ft. **Site 11 of 11 in cluster AY**

Relative: **Lower**
Actual: **6 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	HERTZ PENSKE TRUCK LEASING INC
Handler Address:	542 W 21ST ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYD981563430
Contact Name:	J CATAUDELLA
Contact Address:	W 26TH ST
Contact City,State,Zip:	NEW YORK, NY 10001
Contact Telephone:	212-741-9803
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 26TH ST
Mailing City,State,Zip:	NEW YORK, NY 10001
Owner Name:	J & F RIZZO
Owner Type:	Private
Operator Name:	J & F RIZZO
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported

HERTZ PENSKE TRUCK LEASING INC (Continued) **1000423668**

Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F004
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE

HERTZ PENSKE TRUCK LEASING INC (Continued) **1000423668**

SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	J & F RIZZO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	J & F RIZZO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	J & F RIZZO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name:	HERTZ PENSKE TRUCK LEASING INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

HERTZ PENSKE TRUCK LEASING INC (Continued) **1000423668**

Receive Date: 20070101
Handler Name: HERTZ PENSKE TRUCK LEASING INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19861021
Handler Name: HERTZ PENSKE TRUCK LEASING INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004409890

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000423668
Registry ID: 110004409890
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004409890

HERTZ PENSKE TRUCK LEASING INC (Continued) **1000423668**

Name: HERTZ PENSKE TRUCK LEASING INC
Address: 542 W 21ST ST
City,State,Zip: NEW YORK, NY 10011

BK814 **LONDON TERRACE TOWERS OWNERS CORP.** **NY UST U003069072**
NNE **420 WEST 24 STREET** **NY AST N/A**
1/8-1/4 **NEW YORK, NY 11217**
0.221 mi.
1168 ft. **Site 1 of 11 in cluster BK**

Relative:
Higher

Actual:
17 ft.

UST:
Name: LONDON TERRACE TOWERS OWNERS CORP.
Address: 420 WEST 24 STREET
City,State,Zip: NEW YORK, NY 11217
Id/Status: 2-600237 / Inactive
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 584331.37691
UTM Y: 4511201.18168
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 22220
Affiliation Type: Facility Owner
Company Name: LONDON TERRACE TOWERS OWNERS CORP.
Contact Type: Not reported
Contact Name: Not reported
Address1: 420 WEST 24 STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 11217
Country Code: 001
Phone: (212) 675-2000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 22220
Affiliation Type: Mail Contact
Company Name: LONDON TERRACE TOWERS OWNER CORPORATION
Contact Type: Not reported
Contact Name: JOE GRIMMS C\\O KREISEL CO
Address1: 405 WEST 23 STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 11217
Country Code: 001
Phone: (212) 675-2000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

LONDON TERRACE TOWERS OWNERS CORP. (Continued) **U003069072**

Site Id:	22220
Affiliation Type:	Facility Operator
Company Name:	LONDON TERRACE TOWERS OWNERS CORP.
Contact Type:	Not reported
Contact Name:	PAT BRESLEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 675-2000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	22220
Affiliation Type:	Emergency Contact
Company Name:	LONDON TERRACE TOWERS OWNERS CORP.
Contact Type:	Not reported
Contact Name:	PAT BRESLEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 675-2000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	41656
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	10000
Install Date:	Not reported
Date Tank Closed:	11/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

LONDON TERRACE TOWERS OWNERS CORP. (Continued) **U003069072**

H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number:	002
Tank ID:	41657
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	10000
Install Date:	Not reported
Date Tank Closed:	11/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

AST:

Name:	LONDON TERRACE TOWERS OWNERS CORP.
Address:	420 WEST 24 STREET
City,State,Zip:	NEW YORK, NY 11217
Region:	STATE
DEC Region:	2
Site Status:	Inactive
Facility Id:	2-600237
Program Type:	PBS
UTM X:	584331.37691
UTM Y:	4511201.18168
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	22220

LONDON TERRACE TOWERS OWNERS CORP. (Continued) **U003069072**

Affiliation Type:	Facility Owner
Company Name:	LONDON TERRACE TOWERS OWNERS CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	420 WEST 24 STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	11217
Country Code:	001
Phone:	(212) 675-2000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	22220
Affiliation Type:	Mail Contact
Company Name:	LONDON TERRACE TOWERS OWNER CORPORATION
Contact Type:	Not reported
Contact Name:	JOE GRIMMS C\\O KREISEL CO
Address1:	405 WEST 23 STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	11217
Country Code:	001
Phone:	(212) 675-2000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	22220
Affiliation Type:	Facility Operator
Company Name:	LONDON TERRACE TOWERS OWNERS CORP.
Contact Type:	Not reported
Contact Name:	PAT BRESLEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 675-2000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	22220
Affiliation Type:	Emergency Contact
Company Name:	LONDON TERRACE TOWERS OWNERS CORP.
Contact Type:	Not reported
Contact Name:	PAT BRESLEN
Address1:	Not reported
Address2:	Not reported

LONDON TERRACE TOWERS OWNERS CORP. (Continued) **U003069072**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 675-2000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	003
Tank Id:	51049
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
G03 - Tank Secondary Containment - Vault (w/o access)
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
J02 - Dispenser - Suction Dispenser
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	11/01/1994
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/01/1996
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)

BK815 **LONDON TERRACE/CIM CLEANERS** **NY DRYCLEANERS** **S110247162**
NNE **410 W. 24TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.221 mi.
1169 ft. **Site 2 of 11 in cluster BK**

Relative: **Higher**
Actual: **18 ft.**

DRYCLEANERS:

Name:	LONDON TERRACE/CIM CLEANERS
Address:	410 W. 24TH STREET
City,State,Zip:	NEW YORK, NY 10011
Facility ID:	2-6205-00284
Phone Number:	212-243-2514
Region:	Not reported
Registration Effective Date:	3/12/2002 10:36:16:616

LONDON TERRACE/CIM CLEANERS (Continued) **S110247162**

Inspection Date:	2012-10-04 00:00:00
Install Date:	89/01/04
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Y
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

BK816 **LONDON TERRACE CLEANERS** **RCRA-VSQG** **1000190958**
NNE **410 W 24TH ST** **ICIS** **NYD981137185**
1/8-1/4 **NEW YORK, NY 10011** **US AIRS**
0.221 mi. **NY MANIFEST**
1169 ft. **Site 3 of 11 in cluster BK**

Relative: **Higher**
Actual: **18 ft.**

RCRA-VSQG:

Date Form Received by Agency:	20070101
Handler Name:	LONDON TERRACE CLEANERS
Handler Address:	410 W 24TH ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYD981137185
Contact Name:	Not reported
Contact Address:	W 24TH ST
Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 24TH ST
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	OWNERNAME
Owner Type:	Private
Operator Name:	OWNERNAME
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported

LONDON TERRACE CLEANERS (Continued) **1000190958**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:
Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:
Owner/Operator Indicator: Operator

LONDON TERRACE CLEANERS (Continued) **1000190958**

Owner/Operator Name: OWNERNAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: OWNERNAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: OWNERNAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990714
Handler Name: LONDON TERRACE CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: LONDON TERRACE CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

LONDON TERRACE CLEANERS (Continued) **1000190958**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: LONDON TERRACE CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19850924
Handler Name: LONDON TERRACE CLEANERS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

ICIS:
Enforcement Action ID: NY000A0000262050028400308
FRS ID: 110001606995
Action Name: LONDON TERRACE CLEANERS 36061P00G600308
Facility Name: LONDON TERRACE CLEANERS
Facility Address: 410 W 24TH ST
NEW YORK, NY 10011
Enforcement Action Type: Notice of Violation
Facility County: BRONX
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7212
Federal Facility ID: Not reported

LONDON TERRACE CLEANERS (Continued) **1000190958**

Latitude in Decimal Degrees: 40.747335
Longitude in Decimal Degrees: -74.001301
Permit Type Desc: Not reported
Program System Acronym: NY0000002620500284
Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000262050028400302
FRS ID: 110001606995
Action Name: LONDON TERRACE CLEANERS 36061P00G600302
Facility Name: LONDON TERRACE CLEANERS
Facility Address: 410 W 24TH ST
NEW YORK, NY 10011
Enforcement Action Type: Notice of Violation
Facility County: BRONX
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7212
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.747335
Longitude in Decimal Degrees: -74.001301
Permit Type Desc: Not reported
Program System Acronym: NY0000002620500284
Facility NAICS Code: 812320
Tribal Land Code: Not reported

US AIRS MINOR:
Envid: 1000190958
Region Code: 02
Programmatic ID: AIR NY0000002620500284
Facility Registry ID: 110001606995
D and B Number: Not reported
Primary SIC Code: 7212
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002620500284
Facility Registry ID: 110001606995
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500284
Facility Registry ID: 110001606995

LONDON TERRACE CLEANERS (Continued) **1000190958**

Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2001-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500284
Facility Registry ID: 110001606995
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-02-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500284
Facility Registry ID: 110001606995
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-02-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500284
Facility Registry ID: 110001606995
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2001-07-16 00:00:00
Activity Status Date: 2001-07-16 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002620500284
Facility Registry ID: 110001606995
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-02-22 00:00:00
Activity Status Date: 2002-02-22 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

LONDON TERRACE CLEANERS (Continued) **1000190958**

Region Code: 02
Programmatic ID: AIR NY0000002620500284
Facility Registry ID: 110001606995
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1999-09-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500284
Facility Registry ID: 110001606995
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500284
Facility Registry ID: 110001606995
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500284
Facility Registry ID: 110001606995
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-02-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500284
Facility Registry ID: 110001606995
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-02-22 00:00:00
Activity Status Date: 2002-02-22 00:00:00
Activity Group: Enforcement Action

LONDON TERRACE CLEANERS (Continued) **1000190958**

Activity Type: Administrative - Informal
Activity Status: Achieved

NY MANIFEST:
Name: LONDON TERRACE CLEANERS
Address: 410 W 24TH ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYD981137185
Facility Status: Not reported
Location Address 1: 410 WEST 24TH STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD981137185
Mailing Name: LONDON TERRACE CLEANERS
Mailing Contact: LONDON TERRACE
Mailing Address 1: 410 WEST 24TH STREET
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10011
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: N/S

BK817 **LONDON TERRACE TOWERS** **NY AST** **U003074612**
NNE **410 WEST 24 STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.221 mi.
1169 ft. **Site 4 of 11 in cluster BK**

Relative:
Higher

Actual:
18 ft.

AST:
Name: LONDON TERRACE TOWERS
Address: 410 WEST 24 STREET
City,State,Zip: NEW YORK, NY 10011
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-365696
Program Type: PBS
UTM X: 584316.28057
UTM Y: 4511178.03999
Expiration Date: 10/15/2022
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 18583
Affiliation Type: Facility Operator
Company Name: LONDON TERRACE TOWERS

LONDON TERRACE TOWERS (Continued) **U003074612**

Contact Type:	Not reported
Contact Name:	EZEKIEL BATANCOURT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 675-4003
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2012-11-29

Site Id:	18583
Affiliation Type:	Emergency Contact
Company Name:	LONDON TERRACE TOWERS OWNERS, INC.
Contact Type:	Not reported
Contact Name:	EZEKIEL BETANCOURT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 675-4003
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-07

Site Id:	18583
Affiliation Type:	Facility Owner
Company Name:	LONDON TERRACE TOWERS OWNERS, INC.
Contact Type:	COMPLIANCE MANAGER
Contact Name:	PATRICIA PETTWAY-BROWN
Address1:	405 WEST 23 STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 370-9200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-07

Site Id:	18583
Affiliation Type:	Mail Contact
Company Name:	LONDON TERRACE TOWERS OWNERS, INC.
Contact Type:	Not reported
Contact Name:	PATRICIA PETTWAY-BROWN
Address1:	DOUGLAS ELLIMAN PROPERTY MGMT
Address2:	675 THIRD AVENUE 10TH FLOOR
City:	NEW YORK
State:	NY

LONDON TERRACE TOWERS (Continued) **U003074612**

Zip Code:	10017
Country Code:	001
Phone:	(212) 350-2846
EMail:	PATRICIA.PETTWAY-BROWN@ELLIMANPM.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-07

Tank Info:

Tank Number:	003
Tank Id:	49479
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
H05 - Tank Leak Detection - In-Tank System (ATG)
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/1994
Capacity Gallons:	10000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	11/07/2017
Material Name:	#2 fuel oil (on-site consumption)

BK818 **LONDON TERRACE TOWERS** **NY UST** **U004077694**
NNE **410 WEST 24 STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.221 mi.
1169 ft. **Site 5 of 11 in cluster BK**

Relative:
Higher

Actual:
18 ft.

UST:

Name:	LONDON TERRACE TOWERS
Address:	410 WEST 24 STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-365696 / Active
Program Type:	PBS
Region:	STATE

LONDON TERRACE TOWERS (Continued) **U004077694**

DEC Region: 2
Expiration Date: 10/15/2022
UTM X: 584316.28057
UTM Y: 4511178.03999
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 18583
Affiliation Type: Facility Operator
Company Name: LONDON TERRACE TOWERS
Contact Type: Not reported
Contact Name: EZEKIEL BATANCOURT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 675-4003
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 2012-11-29

Site Id: 18583
Affiliation Type: Emergency Contact
Company Name: LONDON TERRACE TOWERS OWNERS, INC.
Contact Type: Not reported
Contact Name: EZEKIEL BETANCOURT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 675-4003
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-11-07

Site Id: 18583
Affiliation Type: Facility Owner
Company Name: LONDON TERRACE TOWERS OWNERS, INC.
Contact Type: COMPLIANCE MANAGER
Contact Name: PATRICIA PETTWAY-BROWN
Address1: 405 WEST 23 STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10011
Country Code: 001
Phone: (212) 370-9200
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-11-07

LONDON TERRACE TOWERS (Continued) **U004077694**

Site Id:	18583
Affiliation Type:	Mail Contact
Company Name:	LONDON TERRACE TOWERS OWNERS, INC.
Contact Type:	Not reported
Contact Name:	PATRICIA PETTWAY-BROWN
Address1:	DOUGLAS ELLIMAN PROPERTY MGMT
Address2:	675 THIRD AVENUE 10TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 350-2846
EMail:	PATRICIA.PETTWAY-BROWN@ELLIMANPM.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-07

Tank Info:

Tank Number:	001
Tank ID:	24522
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	10000
Install Date:	12/01/1931
Date Tank Closed:	11/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)

Tank Number:	002
Tank ID:	24523
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	10000
Install Date:	12/01/1931

LONDON TERRACE TOWERS (Continued) **U004077694**

Date Tank Closed:	11/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

BL819 **CON EDISON** **RCRA NonGen / NLR** **1014395672**
SW **58 LITTLE W 12TH ST** **NJ MANIFEST** **NYP004171377**
1/8-1/4 **NEW YORK, NY 10014** **NY MANIFEST**
0.222 mi.
1170 ft. **Site 1 of 6 in cluster BL**

Relative: **Lower**
Actual: **9 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		58 LITTLE W 12TH ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004171377
Contact Name:		DAVID DUKE
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		917-559-8971
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported

CON EDISON (Continued) **1014395672**

Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160727
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON (Continued) **1014395672**

Historic Generators:

Receive Date:	20090608
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004171377
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DAVID DUKE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

CON EDISON (Continued) **1014395672**

Manifest:

Manifest Number:	003532078JJK
EPA ID:	NYP004171377
Date Shipped:	06/08/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/08/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/09/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	1000 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	58 LITTLE W 12TH ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004171377

CON EDISON (Continued) **1014395672**

Facility Status: Not reported
Location Address 1: 58 LITTLE W. 12TH ST.
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004171377
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: CONSOLIDATED EDISON
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 06/08/2009
Trans1 Recv Date: 06/08/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/09/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004171377
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 003532078JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H111
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

CON EDISON (Continued) **1014395672**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AU820 **CON EDISON - VAULT 3271** **RCRA-LQG 1016967074**
NE **400 W 24 ST** **NY MANIFEST NYP004402095**
1/8-1/4 **NEW YORK, NY 10011**
0.222 mi.
1170 ft. **Site 16 of 16 in cluster AU**

Relative: **Higher**

Actual: **18 ft.**

RCRA-LQG:

Date Form Received by Agency:		20140327
Handler Name:	CON EDISON - VAULT 3271	
Handler Address:		400 W 24 ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004402095
Contact Name:		DENNIS HUACON
Contact Address:		IRVING PLACE, 15TH FL NE
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-2757
Contact Fax:		518-473-8034
Contact Email:		HUACOND@CONED.COM
Contact Title:		ASSOCIATE SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Large Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		2013
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:		Private
Operator Name:		CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No

CON EDISON - VAULT 3271 (Continued) **1016967074**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

CON EDISON - VAULT 3271 (Continued) **1016967074**

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20131207
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20131207
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20140327
Handler Name: CON EDISON - VAULT 3271	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON ED
Address:	400 W 24 ST
City,State,Zip:	NEW YORK, NY 10011

CON EDISON - VAULT 3271 (Continued) **1016967074**

Country:	USA
EPA ID:	NYP004402095
Facility Status:	Not reported
Location Address 1:	400 W 24TH ST
Code:	BP
Location Address 2:	VAULT 3271
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004402095
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	12/07/2013
Trans1 Recv Date:	12/07/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/13/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004402095
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002237643GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON - VAULT 3271 (Continued) **1016967074**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BD821 **245-259 W 20 ST** **NY AST** **U004076978**
East **251 W 20 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.222 mi.
1171 ft. **Site 6 of 9 in cluster BD**

Relative:
Higher

Actual:
22 ft.

AST:

Name:	245-259 W 20 ST
Address:	251 W 20 ST
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-258091
Program Type:	PBS
UTM X:	584508.01552
UTM Y:	4510732.24102
Expiration Date:	07/10/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	10675
Affiliation Type:	Mail Contact
Company Name:	245-259 REALTY CO
Contact Type:	Not reported
Contact Name:	HECTOR ROSALES
Address1:	251 W 20 ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 243-7700
EMail:	245MGT@GMAIL.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-07-03

Site Id:	10675
Affiliation Type:	Facility Operator

245-259 W 20 ST (Continued) **U004076978**

Company Name:	245-259 W 20 ST
Contact Type:	Not reported
Contact Name:	HECTOR ROSALES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 243-7700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	10675
Affiliation Type:	Emergency Contact
Company Name:	245 REALTY LLC
Contact Type:	Not reported
Contact Name:	HECTOR ROSALES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 243-7700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-07-03

Site Id:	10675
Affiliation Type:	Facility Owner
Company Name:	245 REALTY LLC
Contact Type:	MEMBER
Contact Name:	JAY WARTSKI
Address1:	251 WEST 20 ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 243-7700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-07-03

Tank Info:

Tank Number:	237
Tank Id:	13261
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

245-259 W 20 ST (Continued) **U004076978**

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1961
Capacity Gallons:	3000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	07/03/2017
Material Name:	#2 fuel oil (on-site consumption)

BB822 **CHELSEA DEVELOPMENT CO** **NY UST** **U004293462**
SE **255 WEST 15TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.222 mi.
1172 ft. **Site 21 of 24 in cluster BB**

Relative: **Higher**
Actual: **23 ft.**

UST:

Name:	CHELSEA DEVELOPMENT CO
Address:	255 WEST 15TH STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-247553 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	10/23/2022
UTM X:	584321.00419
UTM Y:	4510403.49636
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	9738
Affiliation Type:	Mail Contact
Company Name:	PAGE MANAGEMENT CO., INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	188 AVE OF THE AMERICAS
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10013
Country Code:	001

CHELSEA DEVELOPMENT CO (Continued) **U004293462**

Phone:	(212) 219-3990
EMail:	SOHORENTALS@AOL.COM
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2013-09-30

Site Id:	9738
Affiliation Type:	Facility Operator
Company Name:	CHELSEA DEVELOPMENT CO
Contact Type:	Not reported
Contact Name:	ERWIN RODRIQUEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 453-7520
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-09-04

Site Id:	9738
Affiliation Type:	Emergency Contact
Company Name:	CHELSEA DEVELOPMENT CO
Contact Type:	Not reported
Contact Name:	DONNA SAUNDERS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 219-3990
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-11-06

Site Id:	9738
Affiliation Type:	Facility Owner
Company Name:	CHELSEA DEVELOPMENT CO
Contact Type:	PROPERTY MANAGER
Contact Name:	DONNA SAUNDERS
Address1:	188 AVE OF THE AMERICAS
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10013
Country Code:	001
Phone:	(212) 219-3990
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-11-06

CHELSEA DEVELOPMENT CO (Continued) **U004293462**

Tank Info:

Tank Number:	001
Tank ID:	25477
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	3500
Install Date:	01/01/1959
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	06/05/2018
Next Test Date:	06/05/2019
Pipe Model:	Not reported
Modified By:	TankSys
Last Modified:	01/31/2020

Equipment Records:

B05 - Tank External Protection - Jacketed
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
C03 - Pipe Location - Aboveground/Underground Combination
J05 - Dispenser - On Site Heating System (Supply/Return)
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

BE823 **JOHN'S TAILOR & CLEANER** **RCRA-VSQG** **1001818344**
SSE **6903 8TH AVE** **ICIS** **NYR000078899**
1/8-1/4 **BROOKLYN, NY 11228** **US AIRS**
0.222 mi. **FINDS**
1172 ft. **Site 4 of 10 in cluster BE** **ECHO**
NY MANIFEST

Relative: Higher

Actual: 22 ft.

RCRA-VSQG:

Date Form Received by Agency:		20070101
Handler Name:	JOHNS CLEANERS	
Handler Address:		69-03 8TH AVE
Handler City,State,Zip:		BROOKLYN, NY 11228-1004
EPA ID:		NYR000078899
Contact Name:		JOE CARUSO
Contact Address:		8TH AVE
Contact City,State,Zip:		BROOKLYN, NY 11228-1004
Contact Telephone:		718-238-4324
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02

JOHN'S TAILOR & CLEANER (Continued) **1001818344**

Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	8TH AVE
Mailing City,State,Zip:	BROOKLYN, NY 11228-1004
Owner Name:	JOE CARUSO
Owner Type:	Private
Operator Name:	JOE CARUSO
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No

JOHN'S TAILOR & CLEANER (Continued) **1001818344**

Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE
Waste Code:	D040
Waste Description:	TRICHLORETHYLENE
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	JOE CARUSO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	69-03 8TH AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11228-1004
Owner/Operator Telephone:	718-238-4324
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	JOE CARUSO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	69-03 8TH AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11228-1004
Owner/Operator Telephone:	718-238-4324

JOHN'S TAILOR & CLEANER (Continued) **1001818344**

Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	JOE CARUSO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	69-03 8TH AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11228-1004
Owner/Operator Telephone:	718-238-4324
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: JOHNS CLEANERS	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: JOHNS CLEANERS	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	19991126
Handler Name: JOHNS CLEANERS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

JOHN'S TAILOR & CLEANER (Continued) **1001818344**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

ICIS:

Enforcement Action ID:	NY000A0000261060030100313
FRS ID:	110019715762
Action Name:	JOHN'S TAILOR & CLEANER 36047R187000313
Facility Name:	JOHN'S TAILOR & CLEANER
Facility Address:	6903 8TH AVE BROOKLYN, NY 112281004
Enforcement Action Type:	Notice of Violation
Facility County:	KINGS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.63024
Longitude in Decimal Degrees:	-74.01504
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610600301
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000261060030100305
FRS ID:	110019715762
Action Name:	JOHN'S TAILOR & CLEANER 36047R187000305
Facility Name:	JOHN'S TAILOR & CLEANER
Facility Address:	6903 8TH AVE BROOKLYN, NY 112281004
Enforcement Action Type:	Administrative Order
Facility County:	KINGS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	SCAAAO
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.63024
Longitude in Decimal Degrees:	-74.01504
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610600301
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000261060030100301
FRS ID:	110019715762
Action Name:	JOHN'S TAILOR & CLEANER 36047R187000301
Facility Name:	JOHN'S TAILOR & CLEANER

JOHN'S TAILOR & CLEANER (Continued) **1001818344**

Facility Address:	6903 8TH AVE BROOKLYN, NY 112281004
Enforcement Action Type:	Notice of Violation
Facility County:	KINGS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.63024
Longitude in Decimal Degrees:	-74.01504
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610600301
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

US AIRS MINOR:

Envid:	1001818344
Region Code:	02
Programmatic ID:	AIR NY0000002610600301
Facility Registry ID:	110019715762
D and B Number:	Not reported
Primary SIC Code:	7216
NAICS Code:	812320
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	02
Programmatic ID:	AIR NY0000002610600301
Facility Registry ID:	110019715762
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2001-09-18 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	02
Programmatic ID:	AIR NY0000002610600301
Facility Registry ID:	110019715762
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2002-08-14 00:00:00
Activity Status Date:	2002-08-14 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Formal
Activity Status:	Final Order Issued

Region Code:	02
Programmatic ID:	AIR NY0000002610600301

JOHN'S TAILOR & CLEANER (Continued) **1001818344**

Facility Registry ID: 110019715762
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-04-24 00:00:00
Activity Status Date: 2002-04-24 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610600301
Facility Registry ID: 110019715762
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2006-01-23 00:00:00
Activity Status Date: 2006-01-23 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610600301
Facility Registry ID: 110019715762
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-09-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:
Registry ID: 110019715762

Click Here:

Environmental Interest/Information System:
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

JOHN'S TAILOR & CLEANER (Continued) **1001818344**

corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001818344
Registry ID:	110019715762
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110019715762
Name:	JOHN'S TAILOR & CLEANER
Address:	6903 8TH AVENUE
City,State,Zip:	BROOKLYN, NY 11228

NY MANIFEST:

Name:	JOHNS CLEANERS
Address:	69-03 8TH AVE
City,State,Zip:	BROOKLYN, NY 11228-1004
Country:	USA
EPA ID:	NYR000078899
Facility Status:	Not reported
Location Address 1:	69-03 8TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11228
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000078899
Mailing Name:	JOHNS CLEANERS
Mailing Contact:	JOHNS CLEANERS
Mailing Address 1:	69-03 8TH AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11228
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7182384324

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD000564906
Trans2 State ID:	MIK814262374
Generator Ship Date:	10/22/2014
Trans1 Recv Date:	10/22/2014
Trans2 Recv Date:	10/24/2014
TSD Site Recv Date:	10/24/2014

JOHN'S TAILOR & CLEANER (Continued) **1001818344**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000078899
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CDX107000000
TSDF ID 2:	Not reported
Manifest Tracking Number:	012907961JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	D039
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AW824 **261 WEST 21ST STREET** **NY AST** **U003387093**
East **261 WEST 21ST STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.223 mi.
1176 ft. **Site 8 of 9 in cluster AW**

Relative: **Higher**

Actual: **22 ft.**

AST:

Name:	261 WEST 21ST STREET
Address:	261 WEST 21ST STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-508942
Program Type:	PBS
UTM X:	584512.08076
UTM Y:	4510814.63292
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

261 WEST 21ST STREET (Continued) **U003387093**

Affiliation Records:

Site Id:	21724
Affiliation Type:	Facility Owner
Company Name:	ABRAHAM LEVENSON%HELMSLEY-SPEA
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	60 EAST 42ND STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10165
Country Code:	001
Phone:	(212) 880-0120
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	21724
Affiliation Type:	Mail Contact
Company Name:	ABRAHAM LEVENSON%HELMSLEY-SPEA
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	60 EAST 42ND STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10165
Country Code:	001
Phone:	(212) 880-0120
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	21724
Affiliation Type:	Facility Operator
Company Name:	261 WEST 21ST STREET
Contact Type:	Not reported
Contact Name:	A LEVENSON%HELMSLEY-SPEAR,INC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 243-8884
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	21724
Affiliation Type:	Emergency Contact
Company Name:	ABRAHAM LEVENSON%HELMSLEY-SPEA
Contact Type:	Not reported
Contact Name:	A LEVENSON%HELMSLEY-SPEAR,INC

261 WEST 21ST STREET (Continued) **U003387093**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 880-0120
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	39509
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

	I04 - Overfill - Product Level Gauge (A/G)
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	CGFREEDM
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)

AW825 **261 WEST 21ST ST** **NY UST** **U004274783**
East **261 WEST 21ST STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.223 mi.
1176 ft. **Site 9 of 9 in cluster AW**

Relative: UST:
Higher

Actual: Name:	261 WEST 21ST ST
22 ft. Address:	261 WEST 21ST STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-091677 / Active

261 WEST 21ST ST (Continued) **U004274783**

Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 11/30/2019
UTM X: 584512.08076
UTM Y: 4510814.63292
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 2315
Affiliation Type: Facility Owner
Company Name: CHELSEA 8TH AVENUE, LLC
Contact Type: PROPERTY MANAGER
Contact Name: RAMIN SHALOM
Address1: 347 FIFTH AVE., #1600
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10016
Country Code: 001
Phone: (212) 686-5252
EMail: Not reported
Fax Number: Not reported
Modified By: DXLIVING
Date Last Modified: 2007-05-15

Site Id: 2315
Affiliation Type: Facility Operator
Company Name: 261 WEST 21ST ST
Contact Type: Not reported
Contact Name: ESPERANZA POLANCO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 255-6021
EMail: Not reported
Fax Number: Not reported
Modified By: DXLIVING
Date Last Modified: 2007-05-15

Site Id: 2315
Affiliation Type: Emergency Contact
Company Name: CHELSEA 8TH AVENUE, LLC
Contact Type: Not reported
Contact Name: ESPERANZA POLANCO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (347) 234-0761
EMail: Not reported
Fax Number: Not reported
Modified By: DXLIVING

261 WEST 21ST ST (Continued) **U004274783**

Date Last Modified: 2007-05-15

Site Id: 2315
Affiliation Type: Mail Contact
Company Name: EMPIRE MANAGEMENT
Contact Type: Not reported
Contact Name: RAMIN SHALOM
Address1: 347 FIFTH AVENUE
Address2: #1600
City: NEW YORK
State: NY
Zip Code: 10016
Country Code: 001
Phone: (212) 686-5252
EMail: RAMINEMPIRE@AOL.COM
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2018-06-29

Tank Info:

Tank Number: 001
Tank ID: 11254
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 5000
Install Date: 01/01/1960
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MXLAY
Last Modified: 10/18/2017

Equipment Records:

H08 - Tank Leak Detection - Weep holes in Vaults with no access for inspection
J05 - Dispenser - On Site Heating System (Supply/Return)
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
L99 - Piping Leak Detection - Other

AV826 **CON EDISON** **NY MANIFEST** **S113495637**
SW **38 LITTLE W 12 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.223 mi.
1177 ft. **Site 7 of 8 in cluster AV**

Relative:
Lower

Actual:
11 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	38 LITTLE W 12 ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004293498
Facility Status:	Not reported
Location Address 1:	38 LITTLE W 12 ST
Code:	BP
Location Address 2:	SERVICE BOX # 39345
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004293498
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/14/2013
Trans1 Recv Date:	03/14/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/18/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004293498
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010841239JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S113495637**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AV827 **CON EDISON SERVICE BOX: 39345** **RCRA NonGen / NLR** **1016450323**
SW **38 LITTLE WEST 12TH ST** **NYP004293478**
1/8-1/4 **NEW YORK, NY 10014**
0.223 mi.
1177 ft. **Site 8 of 8 in cluster AV**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130414
Handler Name:	CON EDISON SERVICE BOX:	39345
Handler Address:		38 LITTLE WEST 12TH ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004293478
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported

CON EDISON SERVICE BOX: 39345 (Continued) **1016450323**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON SERVICE BOX: 39345 (Continued) **1016450323**

Historic Generators:
Receive Date: 20130314
Handler Name: CON EDISON SERVICE BOX: 39345
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130414
Handler Name: CON EDISON SERVICE BOX: 39345
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

BL828 **CON EDISON - SERVICE BOX 55818** **RCRA-LQG** **1014395639**
SW **44 LITTLE W12TH ST.** **NY MANIFEST** **NYP004171047**
1/8-1/4 **NEW YORK, NY 10014** **NJ MANIFEST**
0.223 mi.
1177 ft. **Site 2 of 6 in cluster BL**

Relative:
Lower

Actual:
11 ft.

RCRA-LQG:
Date Form Received by Agency: 20100323
Handler Name: CON EDISON - SERVICE BOX 55818
Handler Address: 44 LITTLE W12TH ST.
Handler City,State,Zip: NEW YORK, NY 10014
EPA ID: NYP004171047
Contact Name: FRANKLYN MURRAY
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-2808
Contact Fax: Not reported
Contact Email: MURRAYFR@CONED.COM
Contact Title: Not reported

CON EDISON - SERVICE BOX 55818 (Continued) **1014395639**

EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2009
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	4 IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported

CON EDISON - SERVICE BOX 55818 (Continued) **1014395639**

Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2009

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20090605
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20090605
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20100323
Handler Name:	CON EDISON - SERVICE BOX 55818
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON - SERVICE BOX 55818 (Continued) **1014395639**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20090605
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	44 LITTLE W12TH ST.
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004171047
Facility Status:	Not reported
Location Address 1:	44 LITTLE W12TH ST.
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004171047
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	CONSOLIDATED EDISON
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003

CON EDISON - SERVICE BOX 55818 (Continued) **1014395639**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/05/2009
Trans1 Recv Date:	06/05/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/05/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004171047
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003532072JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

NJ MANIFEST:

EPA Id:	NYP004171047

CON EDISON - SERVICE BOX 55818 (Continued) **1014395639**

Mail Address:	4 IRVING PLACE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	FRANKLYN MURRAY
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	003532072JJK
EPA ID:	NYP004171047
Date Shipped:	06/05/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/05/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/05/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

CON EDISON - SERVICE BOX 55818 (Continued) **1014395639**

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 3500 P

BB829 **256 W 15TH ST.** **NY UST** **U004277346**
SSE **256 W 15 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.223 mi.
1179 ft. **Site 22 of 24 in cluster BB**

Relative:
Higher

Actual:
23 ft.

UST:
Name: 256 W 15TH ST.
Address: 256 W 15 ST
City,State,Zip: NEW YORK, NY 10011
Id/Status: 2-251542 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 03/23/2022
UTM X: 584303.87901
UTM Y: 4510388.78242
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 10097
Affiliation Type: Facility Operator
Company Name: 256 W 15TH ST.
Contact Type: Not reported
Contact Name: JOSHUA ESTREMERA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (787) 307-3477
EMail: Not reported
Fax Number: Not reported
Modified By: JAAVERSA
Date Last Modified: 2018-02-20

Site Id: 10097
Affiliation Type: Emergency Contact
Company Name: 256 CHELSEA, LLC
Contact Type: Not reported
Contact Name: DAVID BRAND
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: 516-244-6378

256 W 15TH ST. (Continued) **U004277346**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2018-02-14

Site Id:	10097
Affiliation Type:	Mail Contact
Company Name:	TURN OF THE RIVER REAL ESTATE AND MANAGMENT
Contact Type:	Not reported
Contact Name:	DAVID BRAND
Address1:	319 WEST 82ND ST
Address2:	SUITE 3R
City:	NY
State:	NY
Zip Code:	10024
Country Code:	001
Phone:	(516) 244-6378
EMail:	DBRAND@TORREALESTATE.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2018-02-05

Site Id:	10097
Affiliation Type:	Facility Owner
Company Name:	256 CHELSEA, LLC
Contact Type:	MANAGER
Contact Name:	DAVID BRAND
Address1:	5 RUTLAND ROAD
Address2:	Not reported
City:	GREAT NECK
State:	NY
Zip Code:	11020
Country Code:	001
Phone:	(516) 244-6378
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2018-02-14

Tank Info:

Tank Number:	001
Tank ID:	11773
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	2500
Install Date:	01/01/1952
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported

256 W 15TH ST. (Continued) **U004277346**

Pipe Model: Not reported
Modified By: DMPOKRZY
Last Modified: 02/14/2018

Equipment Records:

I05 - Overfill - Vent Whistle
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
B99 - Tank External Protection - Other
G00 - Tank Secondary Containment - None
H08 - Tank Leak Detection - Weep holes in Vaults with no access for inspection
J05 - Dispenser - On Site Heating System (Supply/Return)
A01 - Tank Internal Protection - Epoxy Liner
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
L99 - Piping Leak Detection - Other

BG830 **BROADMOOR APTS** **NY UST** **U001834858**
ENE **315 WEST 23RD STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.223 mi.
1179 ft. **Site 3 of 4 in cluster BG**

Relative:
Higher

Actual:
20 ft.

UST:
Name: BROADMOOR APTS
Address: 315 WEST 23RD STREET
City,State,Zip: NEW YORK, NY 10011
Id/Status: 2-315729 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 07/10/2022
UTM X: 584494.50297
UTM Y: 4511016.90137
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 14446
Affiliation Type: Facility Owner
Company Name: 315 WEST 23RD ST OWNERS CORP % MKI
Contact Type: ACCT EXECUTIVE
Contact Name: JOSEPH LASPINA
Address1: 9 EAST 38TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 684-8282
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2012-05-25

Site Id: 14446
Affiliation Type: Mail Contact
Company Name: MAXWELL-KATES, INC.

BROADMOOR APTS (Continued) **U001834858**

Contact Type:	Not reported
Contact Name:	JOSEPH LA SPINA
Address1:	9 EAST 38TH STREET
Address2:	6TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 684-8282
EMail:	JLASPINA@MAXWELLKATES.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-07-17

Site Id:	14446
Affiliation Type:	Facility Operator
Company Name:	BROADMOOR APTS
Contact Type:	Not reported
Contact Name:	JOSEPH LA SPINA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 684-8282
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	14446
Affiliation Type:	Emergency Contact
Company Name:	315 WEST 23RD ST OWNERS CORP % MKI
Contact Type:	Not reported
Contact Name:	AGIM NIKOLAJ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 620-9119
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-07-17

Tank Info:

Tank Number:	001
Tank ID:	12892
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	10000
Install Date:	06/01/1969
Date Tank Closed:	Not reported

BROADMOOR APTS (Continued) **U001834858**

Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	EJCALIFA
Last Modified:	04/14/2017

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)

AZ831 **300 WEST 23RD STREET OWNERS CORP** **NY AST** **A100292054**
ENE **300 WEST 23RD STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.223 mi.
1179 ft. **Site 21 of 21 in cluster AZ**

Relative: **Higher**
Actual: **21 ft.**

AST:

Name:	300 WEST 23RD STREET OWNERS CORP
Address:	300 WEST 23RD STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-311286
Program Type:	PBS
UTM X:	584519.19912
UTM Y:	4510965.43515
Expiration Date:	10/15/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	14261
Affiliation Type:	Mail Contact
Company Name:	DOUGLAS ELLIMAN
Contact Type:	Not reported
Contact Name:	PATRICIA PETTWAY-BROWN
Address1:	675 3RD AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 350-2846
EMail:	PATRICIA.PETTWAY-BROWN@ELLIMANPM.COM

300 WEST 23RD STREET OWNERS CORP (Continued) **A100292054**

Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-07

Site Id:	14261
Affiliation Type:	Facility Owner
Company Name:	300 WEST 23RD ST OWNERS CORP
Contact Type:	COMPLIANCE MANAGER
Contact Name:	PATRICIA PETTWAY-BROWN
Address1:	300 WEST 23RD STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 243-3030
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-07

Site Id:	14261
Affiliation Type:	Facility Operator
Company Name:	300 WEST 23RD STREET OWNERS CORP
Contact Type:	Not reported
Contact Name:	MICHAEL RYAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 243-3030
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-11-16

Site Id:	14261
Affiliation Type:	Emergency Contact
Company Name:	300 WEST 23RD ST OWNERS CORP
Contact Type:	Not reported
Contact Name:	MICHAEL RYAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 243-3030
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-07

Tank Info:

300 WEST 23RD STREET OWNERS CORP (Continued) **A100292054**

Tank Number: 001
Tank Id: 165081
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:
G02 - Tank Secondary Containment - Vault (w/access)
E00 - Piping Secondary Containment - None
F00 - Pipe External Protection - None
J05 - Dispenser - On Site Heating System (Supply/Return)
K00 - Spill Prevention - None
L99 - Piping Leak Detection - Other
D01 - Pipe Type - Steel/Carbon Steel/Iron
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/01/1978
Capacity Gallons: 7500
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MFLEONAR
Last Modified: 11/07/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 001-A
Tank Id: 165083
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
J02 - Dispenser - Suction Dispenser
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - In Place
Pipe Model: Not reported

300 WEST 23RD STREET OWNERS CORP (Continued) **A100292054**

Install Date:	12/01/1931
Capacity Gallons:	7500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)

BF832 **CON EDISON** **NY MANIFEST** **S116551604**
SE **266 W 17 & 8TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.224 mi.
1182 ft. **Site 6 of 12 in cluster BF**

Relative:
Higher

Actual:
23 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	266 W 17 & 8TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004501276
Facility Status:	Not reported
Location Address 1:	266 W 17 & 8TH AVE
Code:	BP
Location Address 2:	SB3034
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004501276
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/15/2014
Trans1 Recv Date:	04/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/15/2014
Part A Recv Date:	Not reported

CON EDISON (Continued) **S116551604**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004501276
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407477GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AX833 **LONDON TERRACE TOWERS-470 W 24TH ST** **NY UST** **1005639795**
NNE **470 W 24TH ST** **NY AST** **N/A**
1/8-1/4 **NEW YORK, NY 10011** **ICIS**
0.225 mi. **US AIRS**
1188 ft. **Site 7 of 7 in cluster AX**

Relative: **Higher**
Actual: **15 ft.**

UST:

Name:	LONDON TERRACE TOWERS
Address:	470 WEST 24TH STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-365688 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	10/29/2022
UTM X:	584135.36715
UTM Y:	4511275.70575
Site Type:	Apartment Building/Office Building

Affiliation Records:

LONDON TERRACE TOWERS-470 W 24TH ST (Continued) **1005639795**

Site Id:	18582
Affiliation Type:	Facility Owner
Company Name:	LONDON TERRACE TOWERS OWNERS, INC.
Contact Type:	COMPLIANCE MANAGER
Contact Name:	PATRICIA PETTWAY-BROWN
Address1:	405 WEST 23RD STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 370-9200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-07

Site Id:	18582
Affiliation Type:	Emergency Contact
Company Name:	LONDON TERRACE TOWERS OWNERS, INC.
Contact Type:	Not reported
Contact Name:	EZEKIEL BETANCOURT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 675-4003
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-07

Site Id:	18582
Affiliation Type:	Mail Contact
Company Name:	DOUGLAS ELLIMAN PROP MGMT
Contact Type:	Not reported
Contact Name:	PATRICIA PETTWAY-BROWN
Address1:	675 THIRD AVENUE
Address2:	5TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 350-2846
EMail:	PATRICIA.PETTWAY-BROWN@ELLIMANPM.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-07

Site Id:	18582
Affiliation Type:	Facility Operator
Company Name:	LONDON TERRACE TOWERS
Contact Type:	Not reported
Contact Name:	EZEKIEL BETANCOURT
Address1:	Not reported

LONDON TERRACE TOWERS-470 W 24TH ST (Continued) **1005639795**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 657-4003
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2012-11-29

Tank Info:

Tank Number:	001
Tank ID:	30620
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	16000
Install Date:	12/01/1931
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None

AST:

Name:	LONDON TERRACE TOWERS
Address:	470 WEST 24TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-365688
Program Type:	PBS
UTM X:	584135.36715
UTM Y:	4511275.70575
Expiration Date:	10/29/2022
Site Type:	Apartment Building/Office Building

LONDON TERRACE TOWERS-470 W 24TH ST (Continued) **1005639795**

Affiliation Records:

Site Id:	18582
Affiliation Type:	Facility Owner
Company Name:	LONDON TERRACE TOWERS OWNERS, INC.
Contact Type:	COMPLIANCE MANAGER
Contact Name:	PATRICIA PETTWAY-BROWN
Address1:	405 WEST 23RD STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 370-9200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-07

Site Id:	18582
Affiliation Type:	Emergency Contact
Company Name:	LONDON TERRACE TOWERS OWNERS, INC.
Contact Type:	Not reported
Contact Name:	EZEKIEL BETANCOURT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 675-4003
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-07

Site Id:	18582
Affiliation Type:	Mail Contact
Company Name:	DOUGLAS ELLIMAN PROP MGMT
Contact Type:	Not reported
Contact Name:	PATRICIA PETTWAY-BROWN
Address1:	675 THIRD AVENUE
Address2:	5TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 350-2846
EMail:	PATRICIA.PETTWAY-BROWN@ELLIMANPM.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-07

Site Id:	18582
Affiliation Type:	Facility Operator
Company Name:	LONDON TERRACE TOWERS
Contact Type:	Not reported
Contact Name:	EZEKIEL BETANCOURT

LONDON TERRACE TOWERS-470 W 24TH ST (Continued) **1005639795**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 657-4003
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2012-11-29

Tank Info:

Tank Number:	002
Tank Id:	64704
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

	F00 - Pipe External Protection - None
	I04 - Overfill - Product Level Gauge (A/G)
	C01 - Pipe Location - Aboveground
	K00 - Spill Prevention - None
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	H05 - Tank Leak Detection - In-Tank System (ATG)
	J02 - Dispenser - Suction Dispenser
	L09 - Piping Leak Detection - Exempt Suction Piping
	E00 - Piping Secondary Containment - None
	G03 - Tank Secondary Containment - Vault (w/o access)
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/1999
Capacity Gallons:	9000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	11/07/2017
Material Name:	#2 fuel oil (on-site consumption)

ICIS:

Enforcement Action ID:	NY000A0000262050033100344
FRS ID:	110001612693
Action Name:	Not reported
Facility Name:	LONDON TERRACE TOWERS-470 W 24TH ST
Facility Address:	470 W 24TH ST NEW YORK, NY 10011
Enforcement Action Type:	Administrative Order

LONDON TERRACE TOWERS-470 W 24TH ST (Continued) **1005639795**

Facility County: NEW YORK
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 6513
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.746544
Longitude in Decimal Degrees: 74.0026475
Permit Type Desc: Not reported
Program System Acronym: NY0000002620500331
Facility NAICS Code: 531110
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000262050033100342
FRS ID: 110001612693
Action Name: Not reported
Facility Name: LONDON TERRACE TOWERS-470 W 24TH ST
Facility Address: 470 W 24TH ST
NEW YORK, NY 10011
Enforcement Action Type: Notice of Violation
Facility County: NEW YORK
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 6513
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.746544
Longitude in Decimal Degrees: 74.0026475
Permit Type Desc: Not reported
Program System Acronym: NY0000002620500331
Facility NAICS Code: 531110
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000262050033100339
FRS ID: 110001612693
Action Name: Not reported
Facility Name: LONDON TERRACE TOWERS-470 W 24TH ST
Facility Address: 470 W 24TH ST
NEW YORK, NY 10011
Enforcement Action Type: Notice of Violation
Facility County: NEW YORK
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 6513
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.746544
Longitude in Decimal Degrees: 74.0026475
Permit Type Desc: Not reported
Program System Acronym: NY0000002620500331
Facility NAICS Code: 531110
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000262050033100336
FRS ID: 110001612693
Action Name: Not reported
Facility Name: LONDON TERRACE TOWERS-470 W 24TH ST

LONDON TERRACE TOWERS-470 W 24TH ST (Continued) **1005639795**

Facility Address:	470 W 24TH ST NEW YORK, NY 10011
Enforcement Action Type:	Notice of Violation
Facility County:	NEW YORK
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	6513
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.746544
Longitude in Decimal Degrees:	74.0026475
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002620500331
Facility NAICS Code:	531110
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000262050033100333
FRS ID:	110001612693
Action Name:	Not reported
Facility Name:	LONDON TERRACE TOWERS-470 W 24TH ST
Facility Address:	470 W 24TH ST NEW YORK, NY 10011
Enforcement Action Type:	Notice of Violation
Facility County:	NEW YORK
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	6513
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.746544
Longitude in Decimal Degrees:	74.0026475
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002620500331
Facility NAICS Code:	531110
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000262050033100330
FRS ID:	110001612693
Action Name:	Not reported
Facility Name:	LONDON TERRACE TOWERS-470 W 24TH ST
Facility Address:	470 W 24TH ST NEW YORK, NY 10011
Enforcement Action Type:	Notice of Violation
Facility County:	NEW YORK
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	6513
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.746544
Longitude in Decimal Degrees:	74.0026475
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002620500331
Facility NAICS Code:	531110
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000262050033100327

LONDON TERRACE TOWERS-470 W 24TH ST (Continued) **1005639795**

FRS ID:	110001612693
Action Name:	Not reported
Facility Name:	LONDON TERRACE TOWERS-470 W 24TH ST
Facility Address:	470 W 24TH ST NEW YORK, NY 10011
Enforcement Action Type:	Notice of Violation
Facility County:	NEW YORK
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	6513
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.746544
Longitude in Decimal Degrees:	74.0026475
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002620500331
Facility NAICS Code:	531110
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000262050033100321
FRS ID:	110001612693
Action Name:	Not reported
Facility Name:	LONDON TERRACE TOWERS-470 W 24TH ST
Facility Address:	470 W 24TH ST NEW YORK, NY 10011
Enforcement Action Type:	Administrative Order
Facility County:	NEW YORK
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	SCAAAO
Facility SIC Code:	6513
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.746544
Longitude in Decimal Degrees:	74.0026475
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002620500331
Facility NAICS Code:	531110
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000262050033100318
FRS ID:	110001612693
Action Name:	Not reported
Facility Name:	LONDON TERRACE TOWERS-470 W 24TH ST
Facility Address:	470 W 24TH ST NEW YORK, NY 10011
Enforcement Action Type:	Notice of Violation
Facility County:	NEW YORK
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	6513
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.746544
Longitude in Decimal Degrees:	74.0026475
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002620500331
Facility NAICS Code:	531110

LONDON TERRACE TOWERS-470 W 24TH ST (Continued) **1005639795**

Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000262050033100317
FRS ID: 110001612693
Action Name: Not reported
Facility Name: LONDON TERRACE TOWERS-470 W 24TH ST
Facility Address: 470 W 24TH ST
NEW YORK, NY 10011
Enforcement Action Type: Notice of Violation
Facility County: NEW YORK
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 6513
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.746544
Longitude in Decimal Degrees: 74.0026475
Permit Type Desc: Not reported
Program System Acronym: NY0000002620500331
Facility NAICS Code: 531110
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000262050033100309
FRS ID: 110001612693
Action Name: Not reported
Facility Name: LONDON TERRACE TOWERS-470 W 24TH ST
Facility Address: 470 W 24TH ST
NEW YORK, NY 10011
Enforcement Action Type: Administrative Order
Facility County: NEW YORK
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 6513
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.746544
Longitude in Decimal Degrees: 74.0026475
Permit Type Desc: Not reported
Program System Acronym: NY0000002620500331
Facility NAICS Code: 531110
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000262050033100306
FRS ID: 110001612693
Action Name: Not reported
Facility Name: LONDON TERRACE TOWERS-470 W 24TH ST
Facility Address: 470 W 24TH ST
NEW YORK, NY 10011
Enforcement Action Type: Notice of Violation
Facility County: NEW YORK
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 6513
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.746544
Longitude in Decimal Degrees: 74.0026475

LONDON TERRACE TOWERS-470 W 24TH ST (Continued) **1005639795**

Permit Type Desc: Not reported
Program System Acronym: NY0000002620500331
Facility NAICS Code: 531110
Tribal Land Code: Not reported

US AIRS (AFS):
Envid: 1005639795
Region Code: 02
County Code: NY061
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
D and B Number: Not reported
Facility Site Name: LONDON TERRACE TOWERS-470 W 24TH ST
Primary SIC Code: 6513
NAICS Code: 531110
Default Air Classification Code: SMI
Facility Type of Ownership Code: Not reported
Air CMS Category Code: SMI
HPV Status: Not reported

US AIRS (AFS):
Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-08-05 00:00:00
Activity Status Date: Not reported
Activity Group: Case File
Activity Type: Case File
Activity Status: Addressed

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Case File
Activity Type: Case File
Activity Status: Resolved

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-08-20 00:00:00
Activity Status Date: Not reported
Activity Group: Case File
Activity Type: Case File
Activity Status: Resolved

LONDON TERRACE TOWERS-470 W 24TH ST (Continued) **1005639795**

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-01-05 00:00:00
Activity Status Date: 2016-05-02 13:21:52
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1999-09-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-11-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-07-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-09-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

LONDON TERRACE TOWERS-470 W 24TH ST (Continued) **1005639795**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-06-05 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-08-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-03-05 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

LONDON TERRACE TOWERS-470 W 24TH ST (Continued) **1005639795**

Activity Date:	2013-08-21 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	02
Programmatic ID:	AIR NY0000002620500331
Facility Registry ID:	110001612693
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2013-12-24 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	02
Programmatic ID:	AIR NY0000002620500331
Facility Registry ID:	110001612693
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2014-02-10 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	02
Programmatic ID:	AIR NY0000002620500331
Facility Registry ID:	110001612693
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2008-09-30 00:00:00
Activity Status Date:	2008-09-30 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Formal
Activity Status:	Final Order Issued
Region Code:	02
Programmatic ID:	AIR NY0000002620500331
Facility Registry ID:	110001612693
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2005-12-12 00:00:00
Activity Status Date:	2005-12-12 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Formal
Activity Status:	Resolved
Region Code:	02
Programmatic ID:	AIR NY0000002620500331
Facility Registry ID:	110001612693

LONDON TERRACE TOWERS-470 W 24TH ST (Continued) **1005639795**

Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-01-06 00:00:00
Activity Status Date: 2014-01-06 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Resolved

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-08-02 00:00:00
Activity Status Date: 2005-08-02 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-08-05 00:00:00
Activity Status Date: 2008-08-05 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-08-20 00:00:00
Activity Status Date: 2013-08-20 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2010-01-05 00:00:00
Activity Status Date: 2016-05-02 13:21:52
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

LONDON TERRACE TOWERS-470 W 24TH ST (Continued) **1005639795**

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 1999-09-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2002-11-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2003-07-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2005-09-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2006-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

LONDON TERRACE TOWERS-470 W 24TH ST (Continued) **1005639795**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2008-06-05 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2008-08-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2013-03-05 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2013-08-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500331
Facility Registry ID: 110001612693
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits

LONDON TERRACE TOWERS-470 W 24TH ST (Continued) **1005639795**

Activity Date:	2013-12-24 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	02
Programmatic ID:	AIR NY0000002620500331
Facility Registry ID:	110001612693
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	Title V Permits
Activity Date:	2014-02-10 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

BF834 **246 WEST 18 ST** **NY AST** **U004045287**
ESE **246 WEST 18 STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.225 mi.
1189 ft. **Site 7 of 12 in cluster BF**

Relative:
Higher

Actual:
23 ft.

AST:

Name:	246 WEST 18 ST
Address:	246 WEST 18 STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-197742
Program Type:	PBS
UTM X:	584519.75107
UTM Y:	4510564.96812
Expiration Date:	N/A
Site Type:	Unknown

Affiliation Records:

Site Id:	6518
Affiliation Type:	Facility Owner
Company Name:	CHELSA ASSDOCIATES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	60 EAST 42ND STREET SUITE 1416
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10165
Country Code:	001
Phone:	(212) 557-5670
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	6518

246 WEST 18 ST (Continued) **U004045287**

Affiliation Type:	Mail Contact
Company Name:	CHELSA ASSDOCIATES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	60 EAST 42ND STREET SUITE 1416
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10165
Country Code:	001
Phone:	(212) 557-5670
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	6518
Affiliation Type:	Facility Operator
Company Name:	246 WEST 18 ST
Contact Type:	Not reported
Contact Name:	JOE RODRIGUEZ SUPER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 557-5670
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	6518
Affiliation Type:	Emergency Contact
Company Name:	CHELSA ASSDOCIATES
Contact Type:	Not reported
Contact Name:	JOE RODRIGUEZ SUPER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 691-9538
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	16897
Material Code:	0009
Common Name of Substance:	Gasoline

246 WEST 18 ST (Continued) **U004045287**

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/1994
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	gasoline

BK835 **CON EDISON SERVICE BOX: 39708** **RCRA NonGen / NLR** **1017773370**
NE **235 9TH AVE & 24TH ST N OF** **FINDS** **NYP004511507**
1/8-1/4 **NEW YORK, NY 10001**
0.225 mi.
1190 ft. **Site 6 of 11 in cluster BK**

Relative: **Higher**

Actual: **19 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140525
Handler Name:	CON EDISON SERVICE BOX:	39708
Handler Address:		235 9TH AVE & 24TH ST N OF
Handler City,State,Zip:		NEW YORK, NY 10001
EPA ID:		NYP004511507
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported

CON EDISON SERVICE BOX: 39708 (Continued) **1017773370**

Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 39708 (Continued) **1017773370**

Sub-Part P Indicator: No

Historic Generators:

Receive Date:	20140425
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140425
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140525
Handler Name: CON EDISON SERVICE BOX:	39708
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063774606

CON EDISON SERVICE BOX: 39708 (Continued) **1017773370**

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

BK836 **CON EDISON SERVICE BOX: 4436** **RCRA NonGen / NLR** **1016677454**
NE **W 24TH ST & 9TH AVE** **FINDS** **NYP004310504**
1/8-1/4 **NEW YORK, NY 10001** **ECHO**
0.226 mi. **NY MANIFEST**
1191 ft. **Site 7 of 11 in cluster BK**

Relative: **Higher**
Actual: **19 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130610
Handler Name:	CON EDISON SERVICE BOX:	4436
Handler Address:		W 24TH ST & 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10001
EPA ID:		NYP004310504
Contact Name:		BENJAMIN BAMONTE
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-894-9549
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		VING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No

CON EDISON SERVICE BOX: 4436 (Continued) **1016677454**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140402
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130510
Handler Name: CON EDISON SERVICE BOX:	4436
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

CON EDISON SERVICE BOX: 4436 (Continued) **1016677454**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130610
Handler Name: CON EDISON SERVICE BOX: 4436
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110058874473

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016677454
Registry ID: 110058874473
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058874473
Name: CON EDISON SERVICE BOX: 4436
Address: W 24TH ST & 9TH AVE
City,State,Zip: NEW YORK, NY 10001

NY MANIFEST:
Name: CON EDISON
Address: W 24TH ST & 9TH AVE
City,State,Zip: NEW YORK, NY 10001
Country: USA
EPA ID: NYP004310504

CON EDISON SERVICE BOX: 4436 (Continued) **1016677454**

Facility Status:	Not reported
Location Address 1:	WEST 24TH ST AND 9TH AVE
Code:	BP
Location Address 2:	SERVICE BOX # 4436
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10001
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004310504
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/10/2013
Trans1 Recv Date:	05/10/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/10/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004310504
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010842874JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON SERVICE BOX: 4436 (Continued) **1016677454**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BM837 **CON EDISON - GAS MAIN MAIN** **RCRA-LQG** **1015746957**
SSW **E HOUSTON AT COLUMBIA** **NYP004249585**
1/8-1/4 **NEW YORK, NY 10002**
0.226 mi.
1194 ft. **Site 1 of 3 in cluster BM**

Relative: **Lower**

Actual: **12 ft.**

RCRA-LQG:

Date Form Received by Agency:	20140327
Handler Name:	CON EDISON - GAS MAIN MAIN
Handler Address:	E HOUSTON AT COLUMBIA
Handler City,State,Zip:	NEW YORK, NY 10002
EPA ID:	NYP004249585
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PL 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON CO OF NY INC
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No

CON EDISON - GAS MAIN MAIN (Continued) **1015746957**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

CON EDISON - GAS MAIN MAIN (Continued) **1015746957**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20130217
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON CO OF NY INC
Legal Status:	Private
Date Became Current:	20130217
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PL
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20140327
Handler Name:	CON EDISON - GAS MAIN MAIN
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130217
Handler Name:	CON EDISON SERVICE BOX: 39346
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20120412
Handler Name:	CON EDISON GAS MAIN MAIN
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY

CON EDISON - GAS MAIN MAIN (Continued) **1015746957**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130317
Handler Name: CON EDISON SERVICE BOX:	39346
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

BM838 **CON EDISON** **NY MANIFEST** **S119073443**
SSW **E HOUSTON AT COLUMBIA** **N/A**
1/8-1/4 **NEW YORK, NY 10002**
0.226 mi.
1194 ft. **Site 2 of 3 in cluster BM**

Relative:
Lower

Actual:
12 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	E HOUSTON AT COLUMBIA
City,State,Zip:	NEW YORK, NY 10002
Country:	USA
EPA ID:	NYP004249585
Facility Status:	Not reported
Location Address 1:	22 LITTLE W 12TH ST
Code:	BP
Location Address 2:	SERV BOX 39346
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004249585

CON EDISON (Continued) **S119073443**

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/17/2013
Trans1 Recv Date:	02/17/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/19/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004249585
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840396JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	8000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **S119073443**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

BJ839 **CON EDISON SERVICE BOX: 39348** **RCRA NonGen / NLR** **1016449947**
SSW **8 LITTLE WEST 12TH ST** **NY MANIFEST** **NYP004256178**
1/8-1/4 **NEW YORK, NY 10011**
0.226 mi.
1195 ft. **Site 2 of 4 in cluster BJ**

Relative: **Lower**
Actual: **13 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130319
Handler Name:	CON EDISON SERVICE BOX:	39348
Handler Address:		8 LITTLE WEST 12TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004256178
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported

CON EDISON SERVICE BOX: 39348 (Continued) **1016449947**

Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130219
Handler Name: CON EDISON SERVICE BOX:	39348
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130319
Handler Name: CON EDISON SERVICE BOX:	39348
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON SERVICE BOX: 39348 (Continued) **1016449947**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	8 LITTLE WEST 12TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004256178
Facility Status:	Not reported
Location Address 1:	8 LITTLE W 12TH ST
Code:	BP
Location Address 2:	SERV BOX 39348
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004256178
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/19/2013
Trans1 Recv Date:	02/19/2013

CON EDISON SERVICE BOX: 39348 (Continued) **1016449947**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004256178
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840419JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BF840 **CON EDISON** **NJ MANIFEST** **S120676644**
SE **250 W 17TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.227 mi.
1198 ft. **Site 8 of 12 in cluster BF**

Relative: NJ MANIFEST:
Higher

Actual: EPA Id:	NYP004837977
23 ft. Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported

CON EDISON (Continued) **S120676644**

Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002613229GBF
EPA ID:	NYP004837977
Date Shipped:	9/14/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

BF841 **CON EDISON** **NY MANIFEST** **S118259819**
SE **250 W 17TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.227 mi.
1198 ft. **Site 9 of 12 in cluster BF**

Relative:
Higher

Actual:
23 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	250 W 17TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004837977
Facility Status:	Not reported
Location Address 1:	250 W 17TH ST
Code:	BP
Location Address 2:	SB 3026
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004837977
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/14/2015
Trans1 Recv Date:	09/14/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/16/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004837977
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002613229GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S118259819**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BF842 **CON EDISON** **RCRA NonGen / NLR** **1019907766**
SE **250 W 17TH ST** **NYP004837977**
1/8-1/4 **NEW YORK, NY 10011**
0.227 mi.
1198 ft. **Site 10 of 12 in cluster BF**

Relative: **Higher**
Actual: **23 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150914
Handler Name:	CON EDISON	
Handler Address:		250 W 17TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004837977
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported

CON EDISON (Continued) **1019907766**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON (Continued) **1019907766**

Historic Generators:
Receive Date: 20150914
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150914
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

BL843 **CON EDISON SERVICE BOX: 39339** **RCRA NonGen / NLR** **1016143126**
SW **LITTLE WEST 12TH ST & 10TH AVE** **NY MANIFEST** **NYP004258562**
1/8-1/4 **NEW YORK, NY 10014**
0.227 mi.
1199 ft. **Site 3 of 6 in cluster BL**

Relative:
Lower

Actual:
7 ft.

RCRA NonGen / NLR:
Date Form Received by Agency: 20130320
Handler Name: CON EDISON SERVICE BOX: 39339
Handler Address: LITTLE WEST 12TH ST & 10TH AVE
Handler City,State,Zip: NEW YORK, NY 10014
EPA ID: NYP004258562
Contact Name: BENJAMIN BAMONTE
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-894-9549
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: OPERATING SUPERVISOR

CON EDISON SERVICE BOX: 39339 (Continued) **1016143126**

EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported

CON EDISON SERVICE BOX: 39339 (Continued) **1016143126**

Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130220
Handler Name: CON EDISON SERVICE BOX:	39339
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130320
Handler Name: CON EDISON SERVICE BOX:	39339
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	LITTLE WEST 12TH ST & 10TH AVE

CON EDISON SERVICE BOX: 39339 (Continued) **1016143126**

City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004258562
Facility Status:	Not reported
Location Address 1:	LITTLE W 12 & 10TH AVE
Code:	BP
Location Address 2:	SERV BOX 39339
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004258562
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/20/2013
Trans1 Recv Date:	02/20/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004258562
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010841206JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported

CON EDISON SERVICE BOX: 39339 (Continued) **1016143126**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BL844 **CON EDISON SERVICE BOX: 55817** **RCRA NonGen / NLR** **1015746882**
SW **10TH AVE & W 12TH ST** **NYP004248817**
1/8-1/4 **NEW YORK, NY 10014**
0.227 mi.
1199 ft. **Site 4 of 6 in cluster BL**

Relative: **Lower**
Actual: **7 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130316
Handler Name:	CON EDISON SERVICE BOX:	55817
Handler Address:		10TH AVE & W 12TH ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004248817
Contact Name:		BENJAMIN BAMONTE
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-894-9549
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No

CON EDISON SERVICE BOX: 55817 (Continued) **1015746882**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130216
Handler Name: CON EDISON SERVICE BOX:	55817
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY

CON EDISON SERVICE BOX: 55817 (Continued) **1015746882**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20120328
Handler Name: CON EDISON SILO VS~9281	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130316
Handler Name: CON EDISON SERVICE BOX:	55817
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

BL845 **CON EDISON** **NY MANIFEST** **S121446749**
SW **10TH AVE & W 12TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.227 mi.
1199 ft. **Site 5 of 6 in cluster BL**

Relative: **Lower**
Actual: **7 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	10TH AVE & W 12TH ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA

CON EDISON (Continued) **S121446749**

EPA ID: NYP004248817
Facility Status: Not reported
Location Address 1: SEC W 12TH ST & 10TH AVE
Code: BP
Location Address 2: SERV BOX 55817
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004248817
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 02/16/2013
Trans1 Recv Date: 02/16/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/16/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004248817
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 010841160JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

CON EDISON (Continued) **S121446749**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BH846 **CON EDISON** **NY MANIFEST** **S116551642**
SSE **74 8 AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.227 mi.
1199 ft. **Site 10 of 19 in cluster BH**

Relative: **Higher**

Actual: **23 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	74 8 AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004501706
Facility Status:	Not reported
Location Address 1:	74 8 AVE
Code:	BP
Location Address 2:	SB32032
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004501706
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047

CON EDISON (Continued) **S116551642**

Trans2 State ID:	Not reported
Generator Ship Date:	04/15/2014
Trans1 Recv Date:	04/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/16/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004501706
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416773GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	800
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BA847 **CON EDISON SERVICE BOX: 4172** **RCRA NonGen / NLR** **1016143324**
North **511 W 23RD ST OPPOSITE** **NY MANIFEST** **NYP004260618**
1/8-1/4 **NEW YORK, NY 10014**
0.228 mi.
1202 ft. **Site 13 of 16 in cluster BA**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130321
Handler Name:	CON EDISON SERVICE BOX: 4172
Handler Address:	511 W 23RD ST OPPOSITE
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYP004260618
Contact Name:	JUAN RODRIGUEZ
Contact Address:	Not reported

CON EDISON SERVICE BOX: 4172 (Continued) **1016143324**

Contact City,State,Zip:	Not reported
Contact Telephone:	347-865-5931
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No

CON EDISON SERVICE BOX: 4172 (Continued) **1016143324**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130221
Handler Name: CON EDISON SERVICE BOX:	4172
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130321
Handler Name: CON EDISON SERVICE BOX:	4172
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON SERVICE BOX: 4172 (Continued) **1016143324**

NY MANIFEST:

Name:	CON EDISON
Address:	511 W 23RD ST OPPOSITE
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004260618
Facility Status:	Not reported
Location Address 1:	OPP 511 W 23RD ST
Code:	BP
Location Address 2:	SERV BOX 4172
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004260618
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/21/2013
Trans1 Recv Date:	02/21/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/21/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004260618
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010846499JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON SERVICE BOX: 4172 (Continued) **1016143324**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BH848 **CON EDISON - TRANSFORMER MANHOLE 1644** **NY MANIFEST** **S123692692**
SSE **72 8TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.228 mi.
1203 ft. **Site 11 of 19 in cluster BH**

Relative:
Higher

Actual:
23 ft.

NY MANIFEST:

Name:	CON EDISON - TRANSFORMER MANHOLE 1644
Address:	72 8TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP005240247
Facility Status:	Not reported
Location Address 1:	72 8TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005240247
Mailing Name:	CON EDISON - TRANSFORMER MANHOLE 1644
Mailing Contact:	ANNAMARIE MOYLAN
Mailing Address 1:	4 IRVING PLACE 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602278

BG849 **CON EDISON** **NY MANIFEST** **S117058843**
ENE **323-11 W 23RD ST & 9TH AVE E O** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.229 mi.
1209 ft. **Site 4 of 4 in cluster BG**

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	323-11 W 23RD ST & 9TH AVE E O
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004509808
Facility Status:	Not reported
Location Address 1:	323 W 23 ST & 9TH AVE
Code:	BP
Location Address 2:	SB 4204
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004509808
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/23/2014
Trans1 Recv Date:	04/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004509808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416587GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117058843**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BI850 **APARTMENT HOUSE** **NY LTANKS S106010363**
ESE **264 W. 19TH ST** **NY Spills N/A**
1/8-1/4 **MANHATTAN, NY**
0.229 mi.
1211 ft. **Site 2 of 5 in cluster BI**

Relative: **Higher**
Actual: **23 ft.**

LTANKS:

Name:	SPILL NUMBER 0209894
Address:	264 W. 19TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0209894 / 2003-03-26
Facility ID:	0209894
Site ID:	147581
Spill Date:	2002-12-30
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	JMROMMEL
Referred To:	Not reported
Reported to Dept:	2002-12-30
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-30
Spill Record Last Update:	2003-03-26

APARTMENT HOUSE (Continued) **S106010363**

Spiller Name:	Not reported
Spiller Company:	HESS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	UNITED CHELSE
Spiller Phone:	(212) 686-2002
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	125638
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL see spill 0209889"
Remarks:	"tank overfill resulted in 10 gal inside house & 10 gal oustide the house - just on land - caller on the way to do the clean up"

All Materials:

Site ID:	147581
Operable Unit ID:	863114
Operable Unit:	01
Material ID:	513312
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	APARTMENT HOUSE
Address:	264 W. 19TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0209889 / 2003-03-26
Facility ID:	0209889
Facility Type:	ER
DER Facility ID:	125638
Site ID:	147580
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	3101
Spill Date:	2002-12-30
Investigator:	JMROMMEL
Referred To:	Not reported
Reported to Dept:	2002-12-30
CID:	390
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-30

APARTMENT HOUSE (Continued) **S106010363**

Spill Record Last Update:	2003-03-26
Spiller Name:	UNK
Spiller Company:	APARTMENT HOUSE ,./
Spiller Address:	264 W. 19TH ST
Spiller Company:	001
Contact Name:	UNK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 12/30/02 Rommel Office Duty See also 0209894. As per Tony at Mystic - Overfill to 2000 gallon above ground tank in basement. Oil came out vent and was contained. No sumps, drains impacted. PTC hired for cleanup. Spoke to super 212-686-2002/917-408-0284 (Herman) who was happy with cleanup. "
Remarks:	"faulty guage caused spill of material - clean up crew enroute to scene now - spill has been contained - and will be cleaned up shortly"
	Not reported

All Materials:

Site ID:	147580
Operable Unit ID:	861130
Operable Unit:	01
Material ID:	513307
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BI851 **UNITED CHELSEA LLC** **NY AST** **U003386864**
ESE **264 WEST 19TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.229 mi.
1211 ft. **Site 3 of 5 in cluster BI**

Relative:
Higher

Actual:
23 ft.

AST:

Name:	UNITED CHELSEA LLC
Address:	264 WEST 19TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-194638
Program Type:	PBS
UTM X:	584471.37038
UTM Y:	4510644.05570
Expiration Date:	06/05/2026
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	6245
Affiliation Type:	Facility Operator
Company Name:	264 WEST 19TH STREET
Contact Type:	Not reported
Contact Name:	MARCO SALAZAR
Address1:	Not reported
Address2:	Not reported

UNITED CHELSEA LLC (Continued) **U003386864**

City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 686-2002
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-09-23

Site Id: 6245
Affiliation Type: Mail Contact
Company Name: UNITED CHELSEA LLC
Contact Type: Not reported
Contact Name: MARK HAROUNIAN
Address1: 33 EAST 33RD STREET, SUITE 1101
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10016
Country Code: 001
Phone: (212) 686-2002
EMail: MARK@LANDMARK-NYC.COM
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-09-23

Site Id: 6245
Affiliation Type: Emergency Contact
Company Name: UNITED CHELSEA LLC
Contact Type: Not reported
Contact Name: MARK HAROUNIAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 686-2002
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-09-23

Site Id: 6245
Affiliation Type: Facility Owner
Company Name: UNITED CHELSEA, LLC
Contact Type: MANAGING MEMBER
Contact Name: MARK HAROUNIAN
Address1: 33 EAST 33RD STREET, SUITE 1101
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10016
Country Code: 001
Phone: (212) 686-2002
EMail: Not reported

UNITED CHELSEA LLC (Continued) **U003386864**

Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-09-23

Tank Info:

Tank Number:	001
Tank Id:	10817
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
L00 - Piping Leak Detection - None
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
J05 - Dispenser - On Site Heating System (Supply/Return)
C03 - Pipe Location - Aboveground/Underground Combination
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/1987
Capacity Gallons:	3500
Tightness Test Method:	21
Date Test:	04/04/2008
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	09/23/2021
Material Name:	#2 fuel oil (on-site consumption)

BE852 **320 WEST 13TH ST** **NY AST** **U004076102**
South **320 WEST 13TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.230 mi.
1212 ft. **Site 5 of 10 in cluster BE**

Relative:
Higher

Actual:
20 ft.

AST:

Name:	320 WEST 13TH ST
Address:	320 WEST 13TH STREET
City,State,Zip:	NEW YORK, NY 10014
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-043990
Program Type:	PBS
UTM X:	584098.12132

320 WEST 13TH ST (Continued) **U004076102**

UTM Y: 4510296.72945
Expiration Date: 12/02/2026
Site Type: Other

Affiliation Records:

Site Id: 440
Affiliation Type: Mail Contact
Company Name: SAGE REALTY CORPORATION
Contact Type: Not reported
Contact Name: GLENN DIBIASE
Address1: 767 THIRD AVE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10017
Country Code: 001
Phone: (212) 758-0437
EMail: GDIBIASE@SAGEREALTY.COM
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-01-04

Site Id: 440
Affiliation Type: Facility Operator
Company Name: 320 WEST 13TH ST
Contact Type: Not reported
Contact Name: SAGE REALTY CORP
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 924-5150
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 440
Affiliation Type: Emergency Contact
Company Name: SAGE REALTY CORP., AS AGENT FOR OWNER
Contact Type: Not reported
Contact Name: CHRIS GALLI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 924-5150
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-10-21

Site Id: 440
Affiliation Type: Facility Owner

320 WEST 13TH ST (Continued) **U004076102**

Company Name:	330 WEST 15TH REALTY LLC
Contact Type:	VP.
Contact Name:	GLENN DIBIASE
Address1:	767 THIRD AVE
Address2:	Not reported
City:	NEW YORK CITY
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 758-0437
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-10-21

Tank Info:

Tank Number:	001
Tank Id:	1202
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	I04 - Overfill - Product Level Gauge (A/G)
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/1938
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	10/21/2021
Material Name:	#2 fuel oil (on-site consumption)

BE853 **MICR ENCODING INC** **RCRA NonGen / NLR** **1004760545**
South **320 W 13TH ST BASEMENT** **FINDS** **NYR000048462**
1/8-1/4 **NEW YORK, NY 10014** **ECHO**
0.230 mi.
1212 ft. **Site 6 of 10 in cluster BE**

Relative: **Higher**
Actual: **20 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	MICR ENCODING INC	
Handler Address:		320 W 13TH ST BASEMENT
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYR000048462
Contact Name:		JOHN CATANZARO
Contact Address:		W 13TH ST BASEMENT
Contact City,State,Zip:		NEW YORK, NY 10014
Contact Telephone:		212-691-6644
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		W 13TH ST BASEMENT
Mailing City,State,Zip:		NEW YORK, NY 10014
Owner Name:		SAGE REALY CORP
Owner Type:		Private
Operator Name:		SAGE REALY CORP
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

MICR ENCODING INC (Continued) **1004760545**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D003
Waste Description:	REACTIVE WASTE
Waste Code:	D006
Waste Description:	CADMIUM
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D018
Waste Description:	BENZENE
Waste Code:	D035
Waste Description:	METHYL ETHYL KETONE
Waste Code:	D040
Waste Description:	TRICHLORETHYLENE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner

MICR ENCODING INC (Continued) **1004760545**

Owner/Operator Name: SAGE REALY CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 320 W 13TH ST
Owner/Operator City,State,Zip: NEW YORK, NY 10014
Owner/Operator Telephone: 212-924-5150
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SAGE REALY CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 320 W 13TH ST
Owner/Operator City,State,Zip: NEW YORK, NY 10014
Owner/Operator Telephone: 212-924-5150
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SAGE REALY CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 320 W 13TH ST
Owner/Operator City,State,Zip: NEW YORK, NY 10014
Owner/Operator Telephone: 212-924-5150
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: MICR ENCODING INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MICR ENCODING INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

MICR ENCODING INC (Continued) **1004760545**

Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980105
Handler Name: MICR ENCODING INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004539349

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004760545
Registry ID: 110004539349
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004539349
Name: MICR ENCODING INC
Address: 320 W 13TH ST BASEMENT
City,State,Zip: NEW YORK, NY 10014

BN854 **DIA ART FOUNDATION** **RCRA-SQG** **1010328618**
NNW **535 W 22ND ST** **NY MANIFEST** **NYR000144089**
1/8-1/4 **NEW YORK, NY 10011**
0.230 mi.
1213 ft. **Site 1 of 3 in cluster BN**

Relative: **Lower**
Actual: **7 ft.**

RCRA-SQG:

Date Form Received by Agency:		20070125
Handler Name:	DIA ART FOUNDATION	
Handler Address:		535 W 22ND ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYR000144089
Contact Name:		MARK WALKER
Contact Address:		W 22ND ST
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		212-293-5593
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		W 22ND ST
Mailing City,State,Zip:		NEW YORK, NY 10011
Owner Name:		DIA ART FOUNDATION
Owner Type:		Private
Operator Name:		MARK WALKER
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

DIA ART FOUNDATION (Continued) **1010328618**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	DIA ART FOUNDATION
Legal Status:	Private
Date Became Current:	19800115
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MARK WALKER
Legal Status:	Private
Date Became Current:	19891015
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

DIA ART FOUNDATION (Continued) **1010328618**

Historic Generators:

Receive Date:		20070124
Handler Name:	DIA ART FOUNDATION	
Federal Waste Generator Description:		Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20070124
Handler Name:	DIA ART FOUNDATION	
Federal Waste Generator Description:		Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20070125
Handler Name:	DIA ART FOUNDATION	
Federal Waste Generator Description:		Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	71212
NAICS Description:	HISTORICAL SITES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	DIA ART FOUNDATION
Address:	535 W 22ND ST
City,State,Zip:	NEW YORK, NY 10011

DIA ART FOUNDATION (Continued) **1010328618**

Country:	USA
EPA ID:	NYR000144089
Facility Status:	Not reported
Location Address 1:	535 WEST 22ND STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000144089
Mailing Name:	DIA ART FOUNDATION
Mailing Contact:	JOHN SPRAGUE
Mailing Address 1:	535 WEST 22ND STREET
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2122935593

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	01/25/2007
Trans1 Recv Date:	01/25/2007
Trans2 Recv Date:	01/31/2007
TSD Site Recv Date:	02/01/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000144089
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	000006158SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported

DIA ART FOUNDATION (Continued) **1010328618**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	250
Units:	P - Pounds
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F003
Waste Code 1_2:	F005
Waste Code 1_3:	D001
Waste Code 1_4:	D035
Waste Code 1_5:	D007
Waste Code 1_6:	Not reported

BJ855 **CON EDISON - SERVICE BOX 35412** **RCRA-LQG** **1016150238**
SSW **53 GANSEVOORT ST** **NYP004289096**
1/8-1/4 **NEW YORK, NY 10014**
0.230 mi.
1214 ft. **Site 3 of 4 in cluster BJ**

Relative: RCRA-LQG:
Lower

Date Form Received by Agency:	20140327
Handler Name:	CON EDISON - SERVICE BOX 35412
Handler Address:	53 GANSEVOORT ST
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYP004289096
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	518-473-8034
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No

Actual:
13 ft.

CON EDISON - SERVICE BOX 35412 (Continued) **1016150238**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

CON EDISON - SERVICE BOX 35412 (Continued) **1016150238**

Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20130213
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20130213
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140327
Handler Name: CON EDISON - SERVICE BOX 35412
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130213
Handler Name: CON EDISON SERVICE BOX: 35412
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

CON EDISON - SERVICE BOX 35412 (Continued) **1016150238**

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

BJ856 **CON EDISON** **NY MANIFEST** **S119073540**
SSW **53 GANSEVOORT ST FRONT OF** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.230 mi.
1214 ft. **Site 4 of 4 in cluster BJ**

Relative:
Lower

Actual:
13 ft.

NY MANIFEST:
Name: CON EDISON
Address: 53 GANSEVOORT ST FRONT OF
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYP004289096
Facility Status: Not reported
Location Address 1: F/O 53 GANSEVOORT ST
Code: BP
Location Address 2: SERV BOX 35412
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004289096
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 02/13/2013
Trans1 Recv Date: 02/13/2013
Trans2 Recv Date: Not reported

CON EDISON (Continued) **S119073540**

TSD Site Recv Date:	02/14/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004289096
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010707314JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BO857 **244 WEST 16TH STREET** **NY AST** **A100291905**
SE **244 WEST 16TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.231 mi.
1219 ft. **Site 1 of 9 in cluster BO**

Relative: **Higher**
Actual: **23 ft.**

AST:

Name:	244 WEST 16TH STREET
Address:	244 WEST 16TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608458
Program Type:	PBS
UTM X:	584369.37618
UTM Y:	4510445.68801
Expiration Date:	02/28/2023

244 WEST 16TH STREET (Continued) **A100291905**

Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 30310
Affiliation Type: Facility Owner
Company Name: WEST 16TH REALTY LLC
Contact Type: MANAGER
Contact Name: THOMAS CARACCIO
Address1: 253-11 80TH AVENUE
Address2: Not reported
City: GLEN OAKS
State: NY
Zip Code: 11004
Country Code: 001
Phone: (718) 343-1336
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 2014-02-19

Site Id: 30310
Affiliation Type: Mail Contact
Company Name: WEST 16TH REALTY LLC
Contact Type: Not reported
Contact Name: THOMAS J. CARACCIO
Address1: 253-11 80TH AVENUE
Address2: Not reported
City: GLEN OAKS
State: NY
Zip Code: 11004
Country Code: 001
Phone: (718) 343-1336
EMail: TOMC@VIKMGT.COM
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2018-01-08

Site Id: 30310
Affiliation Type: Facility Operator
Company Name: 244 WEST 16TH STREET
Contact Type: Not reported
Contact Name: DANNY MARTINEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 651-7924
EMail: Not reported
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2018-01-08

Site Id: 30310
Affiliation Type: Emergency Contact
Company Name: WEST 16TH REALTY LLC
Contact Type: Not reported

244 WEST 16TH STREET (Continued) **A100291905**

Contact Name:	DANNY MARTINEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 214-0619
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2014-02-19

Tank Info:

Tank Number:	001
Tank Id:	65193
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	I05 - Overfill - Vent Whistle
	I04 - Overfill - Product Level Gauge (A/G)
	F00 - Pipe External Protection - None
	B00 - Tank External Protection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	E00 - Piping Secondary Containment - None
	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	K00 - Spill Prevention - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	A00 - Tank Internal Protection - None
	J02 - Dispenser - Suction Dispenser
	C03 - Pipe Location - Aboveground/Underground Combination
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1950
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	01/08/2018
Material Name:	#2 fuel oil (on-site consumption)

BE858 **CON EDISON** **NY MANIFEST** **S121967399**
South **347 W 4TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.231 mi.
1221 ft. **Site 7 of 10 in cluster BE**

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	347 W 4TH ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004858710
Facility Status:	Not reported
Location Address 1:	347 W 4TH ST
Code:	BP
Location Address 2:	SB 785
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004858710
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/2015
Trans1 Recv Date:	10/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004858710
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014085780JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S121967399**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BB859 **APARTMENT BUILDING** **NY LTANKS** **S103238403**
SSE **250 W. 15TH ST** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.231 mi.
1222 ft. **Site 23 of 24 in cluster BB**

Relative: **Higher**
Actual: **23 ft.**

LTANKS:

Name:	APARTMENT BUILDING
Address:	250 W. 15TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9802344 / 2015-04-01
Facility ID:	9802344
Site ID:	138189
Spill Date:	1998-05-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	1998-05-22
CID:	370
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-05-22
Spill Record Last Update:	2015-04-07

APARTMENT BUILDING (Continued) **S103238403**

Spiller Name:	GREG DEMARAS
Spiller Company:	Not reported
Spiller Address:	250 W. 15TH ST
Spiller County:	001
Spiller Contact:	GREG DEMARAS
Spiller Phone:	(212) 868-8320
Spiller Extention:	223
DEC Region:	2
DER Facility ID:	118169
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was M TIBBE 8/15/05 - Haggerty - TJ O'Conner of Dry as a Bone, tank tester, led me to Jack Learner of Plymouth Management, property manager (212)-447-7000. Left message 8/10/05 ----requires additional info 12/19/2005: Issued a letter to the property manager Jack Learner. (Sadique) 2/07/2006: Per PBS 4000 gal AST is in service. No tank was closed or removed. Possible to close after site visit. (Sadique) 8/12/08: Change Lead_DEC field to 'unassigned'. No documentation provided by property owner. Agree with recommendation above, possible to close after site visit. - JG 3/31/09 - Austin - Transferred from Needs Reassignment to Zhune for further work to remediate and close - end 10/28/10- Zhune spoke to Jack Lerner manager of the buildibg from Plymouth Management Group Inc. 212-447-7000 Ext. 222. He requested copy of the spill report. He said the tank was abondoned in place in 2006. The building converted to gas. He will look for documentation and will send it to DEC. Steve Miller Ext 221 smiller@plymuthny.com Assistant Marilyn Kronfle Ext 223 01/21/11-Hiralkumar Patel. 9:45 AM:- visited site. met Ramon Randon, building super. he is working at the site for about 1.5 years. he doesn't know about old tank location or reason for closing. found old petrometer and old supply/return lines capped inside the boiler room. 10:44 AM:- spoke with Mr. Miller at management office. he mentioned that property manager is on vacation and will be back by 01/28/11. DEC requires: 1) info about tank location, 2) reason for closing tank, 3) is tank removed or still in place?, 4) scaled site map including sampling locations for samples collected by ABC in 2006 during tank closing 4/1/15-ABC Tank emailed the a letter dated 2/27/14. The letter stated on May,2006n-ABC-Tank pumped out, cleaned & Washed the interior of (1)4000 gallon buried fuel oil storage tank. July, 2006-ABC Tank obtained (4) end-point soil samples which were submitted to a certified laboratory for anlysis. I was unable to locate the copy of the result from my office since we only keep our records on hand for (7)years. I also reached out to the laboratory but was told they destroy all documents(5) years. October, 2006 ABC Tank filled the (1) 4000 gallon buried tank with a cement slurry to abandon properly in place. As per DEC-Patel during his site visit. He does not recalled any significant contamination or staining at the site. As per TTF guidance this spill is being closed due to no indication of a current release, no information indicating that there may have been a historical release, and no information that this tank test failure will be an issue in the future. Spill Closed. "
Remarks:	"tank test failure, unknown as of yet on further"

All TTF:

Facility ID:	9802344
Spill Number:	9802344
Spill Tank Test:	1545925
Site ID:	138189
Tank Number:	1

APARTMENT BUILDING (Continued) **S103238403**

Tank Size:	4000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	138189
Operable Unit ID:	1062873
Operable Unit:	01
Material ID:	320674
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BB860 **250 W. 15TH ST OWNERS CORP.** **NY AST** **U004067679**
SSE **250 WEST 15TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.231 mi.
1222 ft. **Site 24 of 24 in cluster BB**

Relative:
Higher

Actual:
23 ft.

AST:

Name:	250 W. 15TH ST OWNERS CORP.
Address:	250 WEST 15TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-093173
Program Type:	PBS
UTM X:	584326.84705
UTM Y:	4510376.31496
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	2448
Affiliation Type:	Mail Contact
Company Name:	250 W. 15TH ST. OWNERS CORP.
Contact Type:	Not reported
Contact Name:	JACK LERNER
Address1:	% PLYMOUTH MANAGEMENT GROUP
Address2:	404 PARK AVENUE SOUTH, 14TH FL.
City:	NEW YORK
State:	NY

250 W. 15TH ST OWNERS CORP. (Continued) **U004067679**

Zip Code:	10016
Country Code:	001
Phone:	(212) 447-7000
EMail:	JLERNER@PLYMOUTHNY.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-11-14

Site Id:	2448
Affiliation Type:	Emergency Contact
Company Name:	250 W. 15TH ST. OWNERS CORP. % PLYMOUTH MGMT.
Contact Type:	Not reported
Contact Name:	EDUARDO CASTRO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 366-6428
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-11-14

Site Id:	2448
Affiliation Type:	Facility Operator
Company Name:	250 W. 15TH ST OWNERS CORP.
Contact Type:	Not reported
Contact Name:	EDUARDO CASTRO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 366-6428
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-11-14

Site Id:	2448
Affiliation Type:	Facility Owner
Company Name:	250 W. 15TH ST. OWNERS CORP. % PLYMOUTH MGMT.
Contact Type:	AGENT
Contact Name:	JACK LERNER
Address1:	404 PARK AVE S, 14TH FL
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 447-7000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR

250 W. 15TH ST OWNERS CORP. (Continued) **U004067679**

Date Last Modified: 2006-11-14

Tank Info:

Tank Number: 001
Tank Id: 4290
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
J02 - Dispenser - Suction Dispenser
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - In Place
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 4000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 10/23/2006
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

BF861 **CON EDISON** **NY AST** **U003386290**
SE **248 W 17TH ST** **NY MANIFEST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.232 mi.
1223 ft. **Site 11 of 12 in cluster BF**

Relative: **Higher**

Actual: **23 ft.**

AST:
Name: 248 WEST 17TH STREET
Address: 248 WEST 17TH ST
City,State,Zip: NYC, NY 10011
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-207942
Program Type: PBS
UTM X: 584404.98490
UTM Y: 4510510.19243
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:

CON EDISON (Continued) **U003386290**

Site Id:	7406
Affiliation Type:	Facility Owner
Company Name:	GENERAL REALTY ASSOC OF CHELSE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	80 FIFTH AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 242-7100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	7406
Affiliation Type:	Mail Contact
Company Name:	GENERAL REALTY ASSOC OF CHELSEA
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	80 FIFTH AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 242-7100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	7406
Affiliation Type:	Facility Operator
Company Name:	248 WEST 17TH STREET
Contact Type:	Not reported
Contact Name:	SCOTT MACDONALD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 989-0687
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	7406
Affiliation Type:	Emergency Contact
Company Name:	GENERAL REALTY ASSOC OF CHELSE
Contact Type:	Not reported
Contact Name:	GENERAL REALTY GROUP
Address1:	Not reported

CON EDISON (Continued) **U003386290**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 242-7100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	9652
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	H99 - Tank Leak Detection - Other
	I04 - Overfill - Product Level Gauge (A/G)
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	D02 - Pipe Type - Galvanized Steel
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	G99 - Tank Secondary Containment - Other
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/01/1989
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

NY MANIFEST:

Name:	CON EDISON
Address:	248 W 17TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004861213
Facility Status:	Not reported
Location Address 1:	248 W 17TH ST
Code:	BP
Location Address 2:	SB 3036
Total Tanks:	Not reported
Location City:	NEW YORK

CON EDISON (Continued) **U003386290**

Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004861213
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 10/27/2015
Trans1 Recv Date: 10/27/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/30/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004861213
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014087620JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 500
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks

CON EDISON (Continued) **U003386290**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BL862 **570-578 WEST 193RD STREET** **NY AST** **A100175293**
SW **570-578 WEST 193TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10040**
0.233 mi.
1231 ft. **Site 6 of 6 in cluster BL**

Relative:
Lower

Actual:
6 ft.

AST:

Name:	570-578 WEST 193RD STREET
Address:	570-578 WEST 193TH STREET
City,State,Zip:	NEW YORK, NY 10040
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-601628
Program Type:	PBS
UTM X:	590310.80682
UTM Y:	4523189.63502
Expiration Date:	01/17/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	23590
Affiliation Type:	Facility Owner
Company Name:	1650 CORP. C/O SILVER STAR PROPERTIES
Contact Type:	AGENT
Contact Name:	ARMAN NOGHREH
Address1:	350 5TH AVENUE SUITE 6908
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10118
Country Code:	001
Phone:	(212) 244-2266
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-01-04

Site Id:	23590
Affiliation Type:	Mail Contact
Company Name:	SILVER STAR PROPERTIES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	350 5TH AVENUE
Address2:	SUITE 6908
City:	NEW YORK
State:	NY
Zip Code:	10118

570-578 WEST 193RD STREET (Continued) **A100175293**

Country Code:	001
Phone:	(212) 244-2266
EMail:	NYCSILVERSTAR@YAHOO.COM
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-01-04

Site Id:	23590
Affiliation Type:	Facility Operator
Company Name:	570-578 WEST 193RD STREET
Contact Type:	Not reported
Contact Name:	JULIO MEISES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 239-9388
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-01-08

Site Id:	23590
Affiliation Type:	Emergency Contact
Company Name:	1650 CORP. % SILVER STAR PROPERTIES
Contact Type:	Not reported
Contact Name:	TYRONE CRESCIONI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 837-0426
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-01-08

Tank Info:

Tank Number:	001
Tank Id:	47225
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

570-578 WEST 193RD STREET (Continued) **A100175293**

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1926
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

BP863 **547-551 WEST 21ST STREET REDEVELOPMENT SITE** **NY UST** **U004220631**
NNW **547-551 WEST 21ST STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.233 mi.
1231 ft. **Site 1 of 5 in cluster BP**

Relative: **Lower**
Actual: **6 ft.**

UST:

Name:	547-551 WEST 21ST STREET REDEVELOPMENT SITE
Address:	547-551 WEST 21ST STREET
City,State,Zip:	NEW YORK, NY 10011
Id/Status:	2-612191 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583875.15607
UTM Y:	4511152.30630
Site Type:	Other

Affiliation Records:

Site Id:	492429
Affiliation Type:	Facility Owner
Company Name:	551 WEST 21ST STREET OWNER LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	375 PARK AVE, STE 1504
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10152
Country Code:	001
Phone:	(212) 421-6900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-03-11

Site Id:	492429
Affiliation Type:	Mail Contact

547-551 WEST 21ST STREET REDEVELOPMENT SITE (Continued) **U004220631**

Company Name:	551 WEST 21ST STREET OWNER LLV
Contact Type:	Not reported
Contact Name:	MAX EISENSTEIN
Address1:	375 PARK AVENUE
Address2:	SUITE 1504
City:	NEW YORK
State:	NY
Zip Code:	10152
Country Code:	001
Phone:	(212) 421-2998
EMail:	MAX@SRCAPITALNYC.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-03-11

Site Id:	492429
Affiliation Type:	Facility Operator
Company Name:	547-551 WEST 21ST STREET REDEVELOPMENT SITE
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	N/A
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-03-11

Site Id:	492429
Affiliation Type:	Emergency Contact
Company Name:	551 WEST 21ST STREET OWNER LLC
Contact Type:	Not reported
Contact Name:	MAX EISENSTEIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 421-2998
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-03-11

Tank Info:

Tank Number:	1
Tank ID:	251331
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	750
Install Date:	Not reported

547-551 WEST 21ST STREET REDEVELOPMENT SITE (Continued) **U004220631**

Date Tank Closed: 09/25/2013
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 2
Tank ID: 251332
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 750
Install Date: Not reported
Date Tank Closed: 09/30/2013
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

J00 - Dispenser - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None

BP864 **547-551 WEST 21ST STREET REDEVELOPMENT SITE** **NY MANIFEST** **S119079169**
NNW **547-551 W 21ST ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.233 mi.
1231 ft. **Site 2 of 5 in cluster BP**

Relative:
Lower

Actual:
6 ft.

NY MANIFEST:

Name:	547-551 WEST 21ST STREET REDEVELOPMENT SITE
Address:	547-551 W 21ST ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYR000201616
Facility Status:	Not reported
Location Address 1:	551 W 21ST ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000201616
Mailing Name:	547-551 WEST 21ST STREET REDEVELOPMENT SITE
Mailing Contact:	547-551 WEST 21ST STREET REDEVELOPMENT
Mailing Address 1:	375 PARK AVE - STE 1504
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10152
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7328720239

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	PAD146714878
Trans2 State ID:	Not reported
Generator Ship Date:	10/16/2013
Trans1 Recv Date:	10/16/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/16/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000201616
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	012191452JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N

547-551 WEST 21ST STREET REDEVELOPMENT SITE (Continued) **S119079169**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	49820
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BQ865 **CON EDISON** **NY MANIFEST** **S117739563**
East **266-264 W 22ND ST & 8TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.233 mi.
1232 ft. **Site 1 of 13 in cluster BQ**

Relative: **Higher**
Actual: **22 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	266-264 W 22ND ST & 8TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004726881
Facility Status:	Not reported
Location Address 1:	266 264 W 22 ST & 6 AV
Code:	BP
Location Address 2:	SB4010
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004726881
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S117739563**

Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/05/2015
Trans1 Recv Date:	02/05/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004726881
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002659536GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BQ866 **CON EDISON** **NJ MANIFEST** **S120666851**
East **266-264 W 22ND ST & 8TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.233 mi.
1232 ft. **Site 2 of 13 in cluster BQ**

Relative:
Higher

Actual:
22 ft.

NJ MANIFEST:

EPA Id:	NYP004726881
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002659536GBF
EPA ID:	NYP004726881
Date Shipped:	2/5/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120666851**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

BQ867 **CON EDISON** **RCRA NonGen / NLR** **1018277941**
East **266-264 W 22ND ST & 8TH AVE** **FINDS** **NYP004726881**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.233 mi.
1232 ft. **Site 3 of 13 in cluster BQ**

Relative: **Higher**
Actual: **22 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150206
Handler Name:	CON EDISON	
Handler Address:		266-264 W 22ND ST & 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004726881
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

CON EDISON (Continued) **1018277941**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150206
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150206
Handler Name: CON EDISON	

CON EDISON (Continued) **1018277941**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067696452

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018277941
Registry ID:	110067696452
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067696452
Name:	CON EDISON
Address:	266-264 W 22ND ST & 8TH AVE
City,State,Zip:	NEW YORK, NY 10011

BP868 **551 WEST 21ST STREET** **NY VCP** **S118943245**
NNW **551 WEST 21ST STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.233 mi.
1232 ft. **Site 3 of 5 in cluster BP**

Relative: **Lower**
Actual: **6 ft.**

VCP NYC:

Project ID:	12TMP0122M,12EH-N122M,13CVCP107M
Name:	551 WEST 21ST STREET
Address:	551 WEST 21ST STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Manhattan

551 WEST 21ST STREET (Continued) **S118943245**

BBL:	1.00693000110069E+39
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.747053
Longitude:	-74.006626
Postcode:	4
Community Board:	3
Council District:	99
Census Tract:	1089871
BIN:	1006937502
NTA:	Hudson Yards-Chelsea-Flatiron-Union Square

BP869 **547-551 WEST 21ST STREET REDEVELOPMENT SITE** **RCRA NonGen / NLR** **1016169691**
NNW **547-551 W 21ST ST** **FINDS** **NYR000201616**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.233 mi.
1232 ft. **Site 4 of 5 in cluster BP**

Relative: **Lower**
Actual: **6 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20140410
Handler Name:	547-551 WEST 21ST STREET REDEVELOPMENT SITE
Handler Address:	547-551 W 21ST ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYR000201616
Contact Name:	MAX EISENSTEIN
Contact Address:	PARK AVE, SUITE 2703
Contact City,State,Zip:	NEW YORK, NY 10152
Contact Telephone:	212-421-2998
Contact Fax:	212-421-3095
Contact Email:	MAX@SRCAPITALNYC.COM
Contact Title:	VICE PRESIDENT OF CONSTRUCTION
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 21ST ST
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	551 WEST 21ST STREET OWNER LLC
Owner Type:	Private
Operator Name:	551 WEST 21ST STREET OWNER LLC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No

547-551 WEST 21ST STREET REDEVELOPMENT SITE (Continued) **1016169691**

Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20151117
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: 551 WEST 21ST STREET OWNER LLC

547-551 WEST 21ST STREET REDEVELOPMENT SITE (Continued) **1016169691**

Legal Status:	Private
Date Became Current:	20121015
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	551 WEST 21ST STREET OWNER LLC
Legal Status:	Private
Date Became Current:	20121015
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	551 WEST 21ST STREET OWNER LLC
Legal Status:	Private
Date Became Current:	19121015
Date Ended Current:	Not reported
Owner/Operator Address:	375 PARK AVE
Owner/Operator City,State,Zip:	NEW YORK, NY 10152
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	551 WEST 21ST STREET OWNER LLC
Legal Status:	Private
Date Became Current:	20121015
Date Ended Current:	Not reported
Owner/Operator Address:	375 PARK AVE
Owner/Operator City,State,Zip:	NEW YORK, NY 10152
Owner/Operator Telephone:	212-421-6900
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	551 WEST 21ST STREET OWNER LLC
Legal Status:	Private
Date Became Current:	20121015
Date Ended Current:	Not reported
Owner/Operator Address:	375 PARK AVE
Owner/Operator City,State,Zip:	NEW YORK, NY 10152
Owner/Operator Telephone:	212-421-6900
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

547-551 WEST 21ST STREET REDEVELOPMENT SITE (Continued) **1016169691**

Owner/Operator Indicator:	Owner
Owner/Operator Name:	551 WEST 21ST STREET OWNER LLC
Legal Status:	Private
Date Became Current:	20000101
Date Ended Current:	Not reported
Owner/Operator Address:	375 PARK AVE
Owner/Operator City,State,Zip:	NEW YORK, NY 10152
Owner/Operator Telephone:	212-421-2998
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20140225
Handler Name:	551 WEST 21ST STREET LLC
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140410
Handler Name:	547-551 WEST 21ST STREET REDEVELOPMENT SITE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130722
Handler Name:	547-551 WEST 21ST STREET REDEVELOPMENT SITE
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	23611
NAICS Description:	RESIDENTIAL BUILDING CONSTRUCTION

547-551 WEST 21ST STREET REDEVELOPMENT SITE (Continued) **1016169691**

NAICS Code: 236117
NAICS Description: NEW HOUSING OPERATIVE BUILDERS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055528969

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016169691
Registry ID: 110055528969
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055528969
Name: 547-551 WEST 21ST STREET REDEVELOPMENT SITE
Address: 547-551 W 21ST ST
City,State,Zip: NEW YORK, NY 10011

BA870 **ARTISTS' CONDOMINIUM** **NY UST** **U000407266**
North **521 WEST 23RD STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.234 mi.
1233 ft. **Site 14 of 16 in cluster BA**

Relative:
Lower

Actual:
10 ft.

UST:
Name: ARTISTS' CONDOMINIUM
Address: 521 WEST 23RD STREET
City,State,Zip: NEW YORK, NY 10011
Id/Status: 2-304158 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 02/01/2026
UTM X: 584003.96962
UTM Y: 4511280.76702
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 13850
Affiliation Type: Mail Contact
Company Name: ABC REALTY

ARTISTS' CONDOMINIUM (Continued) **U000407266**

Contact Type:	Not reported
Contact Name:	WILLIAM D. HARRA
Address1:	152 WEST 57TH STREET
Address2:	12TH FL
City:	NEW YORK
State:	NY
Zip Code:	10019
Country Code:	001
Phone:	(212) 307-0500
EMail:	BHARRA@ABCMGMT.NET
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-01-25

Site Id:	13850
Affiliation Type:	Facility Operator
Company Name:	ARTISTS CONDOMINIUM
Contact Type:	Not reported
Contact Name:	IVOR FRASER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 691-3012
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-12-19

Site Id:	13850
Affiliation Type:	Emergency Contact
Company Name:	ARTISTS CONDOMINIUM C/O ABC REALTY
Contact Type:	Not reported
Contact Name:	WILLIAM D. HARRA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 458-1309
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-01-25

Site Id:	13850
Affiliation Type:	Facility Owner
Company Name:	ARTISTS CONDOMINIUM C/O ABC REALTY
Contact Type:	AGENT
Contact Name:	WILLIAM D. HARRA
Address1:	152 WEST 57TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY

ARTISTS' CONDOMINIUM (Continued) **U000407266**

Zip Code:	10019
Country Code:	001
Phone:	(212) 307-0500
EMail:	BHARRA@ABCMGMT.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2020-12-10

Tank Info:

Tank Number:	001
Tank ID:	26074
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	5000
Install Date:	10/01/1952
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	34
Date Test:	09/07/2019
Next Test Date:	09/07/2020
Pipe Model:	Not reported
Modified By:	TankSys
Last Modified:	06/15/2020

Equipment Records:

I05 - Overfill - Vent Whistle
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
E04 - Piping Secondary Containment - Double walled UG
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

BA871 **EMSIG MFG CORP** **RCRA NonGen / NLR** **1000252529**
North **521 W 23RD ST** **FINDS** **NYD000818609**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.234 mi.
1233 ft. **Site 15 of 16 in cluster BA**

Relative: **Lower**
Actual: **10 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	EMSIG MFG CORP	
Handler Address:		521 W 23RD ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYD000818609
Contact Name:		Not reported
Contact Address:		W 23RD ST

EMSIG MFG CORP (Continued) **1000252529**

Contact City,State,Zip:	NEW YORK, NY 10011
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 23RD ST
Mailing City,State,Zip:	NEW YORK, NY 10011
Owner Name:	EMSIG MFG CORP
Owner Type:	Private
Operator Name:	EMSIG MFG CORP
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No

EMSIG MFG CORP (Continued) **1000252529**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	EMSIG MFG CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	EMSIG MFG CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

EMSIG MFG CORP (Continued) **1000252529**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: EMSIG MFG CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: EMSIG MFG CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: EMSIG MFG CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: EMSIG MFG CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800818
Handler Name: EMSIG MFG CORP
Federal Waste Generator Description: Large Quantity Generator

EMSIG MFG CORP (Continued) **1000252529**

State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004332080

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000252529
Registry ID:	110004332080
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004332080
Name:	EMSIG MFG CORP
Address:	521 W 23RD ST
City,State,Zip:	NEW YORK, NY 10011

BA872 **COMMERICAL BUILDLING** **NY LTANKS** **S110762281**
North **521 WEST 23RD STREET** **N/A**
1/8-1/4 **NEW YORK, NY**
0.234 mi.
1233 ft. **Site 16 of 16 in cluster BA**

Relative: **Lower**
Actual: **10 ft.**

LTANKS:

Name:	COMMERICAL BUILDLING
Address:	521 WEST 23RD STREET
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	1010869 / 2012-11-27
Facility ID:	1010869
Site ID:	444486

COMMERICAL BUILDLING (Continued) **S110762281**

Spill Date:	2011-01-24
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	BKFALVEY
Referred To:	Not reported
Reported to Dept:	2011-01-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-01-24
Spill Record Last Update:	2012-11-27
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	BILL
Spiller Phone:	(212) 307-0500
Spiller Extention:	226
DEC Region:	2
DER Facility ID:	399382
DEC Memo:	"TTF letter was sent to A B C Realty 152 W 57th Street 12th Floor New York, NY 10019 Attn: William Harra TTF in edocs. 03/09/11-Hiralkumar Patel. 3:00 PM:- visited site as inspecting property at 535 W 23rd street, a property two doors west from the subject site. met Fraser (917-921-8309), building super. site has building on slab and a photo gallery is located on groundfloor. Fraser mentioned that the tank is located somewhere underneath the gallery floor. he mentioned that after the tank system failed the test, tank was drained using supply line connection in boiler room. boiler room is sub-grade and west of the tank location. inspected boiler room wall adjoining the tank location and found no oil staining or seeping. fill port found sealed. Fraser mentioned that management is planning to remove tank and install new tank at the same location. currently, site is using temp. tank. 6/7/11 Spoke to Seth Freedland, attorney representing the tenant, which is an art gallery. Phone: (212)344-1400 ext.202. He requested that they delay the work for the spill closure until July 2011. I would consider it, but would require a plan to do the investigation. He will contact the condo association and e-mail me back. Case has been open since January 2011. bf 6/7/11 bf: received the folowing e-mail: Resending. Below bounced back& Sorry. Seth D. Friedland Friedland Laifer & Robbins, LLP 62 William Street, Third Floor New York, New York 10005 Tel. 212.344.1400 x. 202 Fax 212.344.8735 email: sfriedland@friedlandlaifer.com This message and any attachments are solely for the use of the intended recipient(s). They may contain privileged and/or confidential information, attorney work product or other information protected from disclosure. If you are not an intended recipient, you are hereby notified that you received this email in error and that any review, dissemination, distribution or copying of this email and any attachment is strictly

COMMERICAL BUILDLING (Continued) **S110762281**

prohibited. If you have received this email in error, please contact the sender immediately and delete the message and any attachment from your system. Thank you for your cooperation. IRS Circular 230 Disclosure: To ensure compliance with requirements imposed by the U.S. Internal Revenue Service, we inform you that any tax advice contained in this communication (including any attachments) is not intended or written to be used, and cannot be used, by any taxpayer for the purpose of (1) avoiding tax-related penalties under the U.S. Internal Revenue Code or (2) promoting, marketing or recommending to another party any tax-related matters addressed herein. From: Seth D. Friedland Sent: Tuesday, June 07, 2011 12:46 PM To: 'bkfalvey@gw.dec.state..ny.us' Cc: Seth D. Friedland Subject: 521 West 23rd Street, NYC -- DEC Spill No. 1010869 - PBS No. 2-304158 Brian: Thanks for taking the time to discuss the above matte this morning. As mentioned, I represent the Steven Kasher Gallery which is the ground level tenant at the condominium building which is the subject of the above PBS case. Our client operates a gallery at the location, and the tank is suspected of being buried under the gallery floor. To accommodate our client s business requirements and to avoid undue disruption of our client s operations, as discussed, I would like to coordinate the proposed tank closure work to be performed during the month of July on a date or dates to be selected. You indicated that you would be amenable to the work being done in July. I will coordinate with the building manager and its consultant in order to propose the schedule of work and let you know. Should you have any questions, of course, please let me know. Thanks again for your assistance. Regards, Seth D. Friedland Friedland Laifer & Robbins, LLP 62 William Street, Third Floor New York, New York 10005 Tel. 212.344.1400 x. 202 Fax 212.344.8735 email: sfriedland@friedlandlaifer.com This message and any attachments are solely for the use of the intended recipient(s). They may contain privileged and/or confidential information, attorney work product or other information protected from disclosure. If you are not an intended recipient, you are hereby notified that you received this email in error and that any review, dissemination, distribution or copying of this email and any attachment is strictly prohibited. If you have received this email in error, please contact the sender immediately and delete the message and any attachment from your system. Thank you for your cooperation. IRS Circular 230 Disclosure: To ensure compliance with requirements imposed by the U.S. Internal Revenue Service, we inform you that any tax advice contained in this communication (including any attachments) is not intended or written to be used, and cannot be used, by any taxpayer for the purpose of (1) avoiding tax-related penalties under the U.S. Internal Revenue Code or (2) promoting, marketing or recommending to another party any tax-related matters addressed herein. 7/27/11 Received call from Rich Lovato of Advanced Site Restoration. Phone: (646)235-4800 and (212)809-1110. Contractor for gallery owner. Tank passed and lines failed ttt. I told him he needs to delineate contamination. He will send work plan. bf 8/14/12 PBS inspection today. Tank is still in use based on the petrometer which shows that there are approximately 1400 gallons of fuel in the tank. NOV issued and sent to William Harra at the above address. PBS settlement conference scheduled for 9/19/12. bf 9/19/12 Nopbody appeared for the PBS conference scheduled for today. bf 9/25/12 Today, received e-mail response from Riteway, contractor for the facility: Hi Brian, I sent this package back on Sept 27, 2011. I did not follow up with you and thought that you had

COMMERICAL BUILDLING (Continued) **S110762281**

closed it. I just received another violation from the client dated 8/14/2012 inspection #31107. Please let me know if you need anything else. From: David Chan [mailto:david@petroleumtek.com] Sent: Tuesday, September 27, 2011 3:34 PM To: 'Brian Falvey' Subject: spill 1010869 Hi Brian, Please find the closure report and supporting documentation for spill # 1010869. If you have any questions please do not hesitate to ask. Best regards, Dave Chan Riteway Tank Maintenance Corp. 700 Hicks Street Brooklyn, NY 11231 718-855-7272 phone 718-855-7244 fax david@petroleumtek.com ----------end---------- 10/1/12 On 9/25/12 received the following e-mail from David Chan of rite-way that also included attachments: site sketch, analytical sample results, closure requerst letter, and ttt tank only test report. ----------start---------- Hi Brian, I sent this package back on Sept 27, 2011. I did not follow up with you and thought that you had closed it. I just received another violation from the client dated 8/14/2012 inspection #31107. Please let me know if you need anything else. ----------end---------- On 9/28/12, received the following e-mail from David Chan which included the same attachments as the 9/25/12 e-mail: ----------start---------- Hi Brian.... ----------end---------- Tank failed because of hole in vent line. Submitted photos show the vent line with a corrosion hole and no visual contamination. Four samples were taken and were below DER- 10 allowances. A tank system test is required to close the spill case. today, responded to Mr. Chan's e-mail with the following: ----------start---------- David, The spill case can not be closed until the Department receives a passing tightness test for the whole system. The owner needs to correct the following registration information: 1. The product stored is #4 oil not #2 oil. 2.The tank overfill prevention is registered as a gauge. A gauge used for overfill prevention is only applicable to aboveground tanks. 3. The tank spill prevention is a catch basin. It is registered as none. 4. Pipe secondary containment is blank. The information correction application is attached. There is no fee for this application transaction and an original copy must be submitted (fax or e-mail copies will be returned unprocessed). Brian ----------end---------- bf 11/13/12 received the following e-mail from David Chan: Dear Brian, Please find the final tank and system test verifying the integrity of the system for the spill closure. I am following up with the owner with regards to their PBS. Please let me know if you need anything else for the closure. Thank you in advance. Best regards, David Chan Riteway Tank Maintenance Corp. 700 Hicks Street Brooklyn, NY 11231 718-855-7272 phone 718-855-7244 fax david@petroleumtek.com 11/27/12 Based on sampling results, case closed. bf"

Remarks: "Bill is the realitor of the building."

All Materials:

Site ID:	444486
Operable Unit ID:	1194933
Operable Unit:	01
Material ID:	2190855
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported

COMMERICAL BUILDLING (Continued) **S110762281**

Recovered: Not reported
Oxygenate: Not reported

BH873 **GETTY** **NY LTANKS** **S104501334**
SSE **63 8TH AVENUE** **NY Spills** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.234 mi.
1236 ft. **Site 12 of 19 in cluster BH**

Relative: **Higher**
Actual: **22 ft.**

LTANKS:

Name:	GETTY
Address:	63 8TH AVENUE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0210903 / 2003-12-24
Facility ID:	0210903
Site ID:	123040
Spill Date:	2003-01-30
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	rjfeng
Referred To:	Not reported
Reported to Dept:	2003-01-30
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-01-30
Spill Record Last Update:	2005-08-31
Spiller Name:	SCOTT MCINTOSH
Spiller Company:	GETTY PETROLEUM
Spiller Address:	1500 HEAMPSTEAD TURNPIKE
Spiller County:	001
Spiller Contact:	SCOTT MCINTOSH
Spiller Phone:	(800) 545-1235
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	251273
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 12/24/2003-Vought-See open spill #9515395 for contaminated groundwater at same location. This spill closed by Vought."
Remarks:	"TANK FAILED THE TEST. "

All TTF:

Facility ID:	0210903
Spill Number:	0210903
Spill Tank Test:	1527989
Site ID:	123040
Tank Number:	1
Tank Size:	4000
Material:	0008

GETTY (Continued) **S104501334**

EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	20
Test Method 2:	USTest 2000/P/LL plus USTest 2000/U
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	123040
Operable Unit ID:	864170
Operable Unit:	01
Material ID:	514274
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	GETTY GAS STATION #58205
Address:	63 8TH AVENUE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9804128 / 2005-03-25
Facility ID:	9804128
Facility Type:	ER
DER Facility ID:	251273
Site ID:	311447
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	3101
Spill Date:	1998-07-01
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	1998-07-01
CID:	266
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1998-07-01
Spill Record Last Update:	2005-03-25
Spiller Name:	SCOTT HANLEY

GETTY (Continued) **S104501334**

Spiller Company: GETTY PETROLEUM CORPORATI
Spiller Address: 4301 BOSTON POST ROAD
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 3/14/03 Reassigned from Rommel to VOUGHT 3/25/05-Vought-File review by Vought: Letter from Tyree Org(Pisel) to DEC Tibbe-2/14/96. Enclosed please find the tank test report for the above referenced site. The three (3) 4000-gallon underground storage tanks passed on December 19, 1995. A 2 stick box was replaced. Letter from Tyree Org(Pisel) to DEC Tibbe-2/14/96. The following recounts the details of the Tyree Bros Environmental Services inspection of the aboce referenced site in repsonse to vapor complaints at a neighboring building. The adjacent building, 302 West 13th Street, with the vapor complaints was also inspected. The building is of four story brick construction with a basement . A reading of one percent (1%) of the LEL was recorded in the basement. The NYC Fire Department also checked the building and the service station. They gave no indication of any problem. Fax cover sheet from Tyree (Pisel) to DEC Tibbe-2/27/96. Drilling scheduled for 2/28/96 and delivery scheduled same day so Tyree can check building for vapors at same time. Fax from Tyree Brothers(Pisel) to DEC Tibbe-3/5/96. Here's the map and boring logs for the 3 wells. Called in spill due to W2 contamination @ groundwater. Found 3 divorced vent lines b/g which were capped. Tyree maintenance is going back to 45 degree a/g vents and install pressurized caps . Letter from Tyree Brothers(Rennie) to DEC Tibbe-7/3/96. Acess gained by Tyree to 302 W 13th St on 12/9/95 and on 2/28/96. Gasoline fumes not found during either site visit. Subsequent site visits being made on a routine schedule however access is not being provided by building owner. Calls to owner by Getty were not answered. Getty and Tyree have been trying to scheudle a seal coating of the basement for the past two months . Quarterly Monitoring Report (Tyree Bros)- Second March 1996 thru December 1996. Three monitoring wells onsite with quarterly sampling and weekly gauging. Groundwater at 20-22' below grade and flow to the west-southwest. March groundwater analyticals show 217ppb xylene(W-2) and ppb MTBE(W-2). October sampling shows no TOGS 1.1 Groundwater Standard exceedence. Letter from Tyree(Rennie) to Owner-4/1/97. ...a sealcoating of wall(s) in an area of the basement should be done to help retard these fumes that may be permeating through the affected wall(s). Tyree is kindly requesting a meeting with you onsite to discuss our workscope and to grant acess to the building... Quarterly Monitoring Reports (Tyree Bros) Jan 1997 thru June 1997. Three monitoring wells onsite with quarterly sampling and weekly gauging. Groundwater at 20-22' below grade and flow to the west. Groundwater sampling shows no TOGS 1.1 Groundwater Standard exceedence. Letter from Tyree Bros(Rennie) to owner-12/5/97. To date we have sent those reports (Quarterly Monitoring Reports) eclosed with the April 1,1997 letter to your attention and have not heard from you since . In order to ensure a safe environment within the basement area, Tyree kindly requests your approval to access the building to perform sealcoating of of the wall(s) . Fax from Tyree(Caputo) to DEC Tibbe-3/30/98. This fax is sent in ordert to inform you that your per your meeting with Tyree personel on December 11, 1997 the three groundwater monitoring wells at the above referenced site have been properly abandoned... . Closure letter requested. Tank Upgrade Report Tyree Org -October 1998. Reason for tank upgrade was federal EPA mandate. One pump

GETTY (Continued) **S104501334**

island located adjacent to 8th Avenue . Surrounding area is commercial buildings and residential buildings. Work performed included excavation of vent lines for assessment and upgrading of two (4000-gallon) gasoline USTs and one (4000-gallon)diesel fuel UST. Nineteen soil endpoint samples collected. Soil analyticals show 6680ppb xylene(S8 4'bg), 4930ppb 1,3,5-trimethylbenzene(S8 4'bg), 12500ppb 1,2,4-trimethylbenzene(S8 4'bg) and SVOCs in soil possibly attributed to fill material. Approximately 170.14 tons of soil were removed from site. Subsurface Investigation Report (Tyree Org)-May 2003. Reason for investigation was DEC directive . Three geoprobe borings were performed. Groundwater at 22' below grade. Soil analyticals show no TAGM 4046 Soil Cleanup Objective exceedence. Groundwater analyicals show 69.1ppb MTBE(MW4) and 124ppb MTBE(MW6). Quarterly Monitoring Reports (Tyree Org) February 2003 thru July 2004. Three monitoring wells onsite. Groundwater at depth of 24-25' below grade and flow to the west. Quarterly monitoring and quarterly groundwater sampling. Groundwater analyticals show No TOGS 1.1 Groundwater Standard exceedence for last four quarters. 3/25/05-Vought-Spill closed by Vought due to lack of groundwater exceedence, minor soil contamination and great depth to groundwater and hence lack of sensitive receptor impact(to basements). "

Remarks: "SOIL CONTAMINATION FOUND DURING TANK UPGRADE. SOIL TO BE STOCKPILED AS NECESSARY."

All Materials:

Site ID:	311447
Operable Unit ID:	1061777
Operable Unit:	01
Material ID:	318849
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	311447
Operable Unit ID:	1061777
Operable Unit:	01
Material ID:	318848
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GETTY 58205
Address:	63 8TH AVENUE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0511590 / 2006-01-09
Facility ID:	0511590
Facility Type:	ER

GETTY (Continued) **S104501334**

DER Facility ID:	251273
Site ID:	357779
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	3101
Spill Date:	2006-01-05
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2006-01-07
CID:	62
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-01-07
Spill Record Last Update:	2006-01-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	""
Remarks:	"Spillage around pump,. Contained to island area. Cleaned up immediately."

All Materials:

Site ID:	357779
Operable Unit ID:	1115053
Operable Unit:	01
Material ID:	2105103
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Name:	GETTY
Address:	63 8TH AVENUE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9515395 / 2005-03-25
Facility ID:	9515395
Facility Type:	ER
DER Facility ID:	251273
Site ID:	123041
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101

GETTY (Continued) **S104501334**

Spill Date:	1996-02-29
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	1996-02-29
CID:	351
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1996-02-29
Spill Record Last Update:	2005-03-25
Spiller Name:	Not reported
Spiller Company:	GETTY
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JOE PISEL
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 12/24/2003-Vought-Spill transferred from Tibbe to Vought. This spill closed and referred to closed spill #9804128 at same location."
Remarks:	"drilling 3 wells on site and found 1 to be contaminated - mark tibbe from dec was already aware of this problem"

All Materials:

Site ID:	123041
Operable Unit ID:	1030047
Operable Unit:	01
Material ID:	355521
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	123041
Operable Unit ID:	1030047
Operable Unit:	01
Material ID:	2096799
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	123041
Operable Unit ID:	1030047
Operable Unit:	01
Material ID:	355522

GETTY (Continued) **S104501334**

Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GETTY#58205
Address:	63 8TH AVENUE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0505090 / 2005-07-28
Facility ID:	0505090
Facility Type:	ER
DER Facility ID:	251273
Site ID:	350049
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	E5
SWIS:	3101
Spill Date:	2005-07-27
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2005-07-27
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2005-07-27
Spill Record Last Update:	2005-07-28
Spiller Name:	UNKNOWN
Spiller Company:	THIRDF PARTY SPILL
Spiller Address:	UNKNOWN
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	"7/28/05//mt// No spill occurred//nfa"
Remarks:	"WAS A HIT DISPENSER PRODUCT HAS BEEN SHUT DOWN PENDING LINE TEST. NONE SPILLED."

All Materials:

Site ID:	350049
Operable Unit ID:	1107631
Operable Unit:	01
Material ID:	2097520
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

GETTY (Continued) **S104501334**

Recovered: .00
Oxygenate: Not reported

Name: GETTY# 58205
Address: 63 8TH AVE
City,State,Zip: MANHATTAN, NY
Spill Number/Closed Date: 0701527 / 2007-05-07
Facility ID: 0701527
Facility Type: ER
DER Facility ID: 341246
Site ID: 381061
DEC Region: 2
Spill Cause: Housekeeping
Spill Class: C4
SWIS: 3101
Spill Date: 2007-05-07
Investigator: smsanges
Referred To: Not reported
Reported to Dept: 2007-05-07
CID: 444
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: Not reported
Remediation Phase: 0
Date Entered In Computer: 2007-05-07
Spill Record Last Update: 2007-12-31
Spiller Name: MIKE CARR
Spiller Company: GETTY# 58205
Spiller Address: 63 8TH AVE
Spiller Company: 001
Contact Name: MIKE CARR
DEC Memo: "minor spill event"
Remarks: "product and water in the sump:"

All Materials:
Site ID: 381061
Operable Unit ID: 1138526
Operable Unit: 01
Material ID: 2128518
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GETTY # 58205
Address: 63 8TH AVE
City,State,Zip: MANHATTAN, NY

GETTY (Continued) **S104501334**

Spill Number/Closed Date:	0607858 / 2006-12-13
Facility ID:	0607858
Facility Type:	ER
DER Facility ID:	341246
Site ID:	371687
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	3101
Spill Date:	2006-10-10
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2006-10-10
CID:	410
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-10-10
Spill Record Last Update:	2007-12-31
Spiller Name:	MIKE CARR
Spiller Company:	GETTY # 58205
Spiller Address:	63 8TH AVE
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	"surface spill - all cleaned up"
Remarks:	"INVESTIGATION ONGOING: SPILL IS CLEANED UP: FDNY ON SITE:"

All Materials:

Site ID:	371687
Operable Unit ID:	1129445
Operable Unit:	01
Material ID:	2119110
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

BH874 **GETTY REALTY CORP 58205** **RCRA NonGen / NLR** **1001171396**
SSE **63 8TH AVE** **FINDS** **NY0001492248**
1/8-1/4 **NEW YORK, NY 10014** **ECHO**
0.234 mi. **NY MANIFEST**
1236 ft. **Site 13 of 19 in cluster BH**

Relative: **Higher**
Actual: **22 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	GETTY REALTY CORP 58205
Handler Address:	63 8TH AVE

GETTY REALTY CORP 58205 (Continued) **1001171396**

Handler City,State,Zip:	NEW YORK, NY 10014-1609
EPA ID:	NY0001492248
Contact Name:	DALE HOLDEN
Contact Address:	JERICHO TNPK
Contact City,State,Zip:	JERICHO, NY 11753
Contact Telephone:	516-286-2600
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	JERICHO TNPK
Mailing City,State,Zip:	JERICHO, NY 11753
Owner Name:	GETTY PETROLEUM CORP
Owner Type:	Private
Operator Name:	GETTY PETROLEUM CORP
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No

GETTY REALTY CORP 58205 (Continued) **1001171396**

TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	GETTY PETROLEUM CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	125 JERICHO TNPK
Owner/Operator City,State,Zip:	JERICHO, NY 11753
Owner/Operator Telephone:	516-286-2600
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GETTY PETROLEUM CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	125 JERICHO TNPK
Owner/Operator City,State,Zip:	JERICHO, NY 11753
Owner/Operator Telephone:	516-286-2600
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GETTY PETROLEUM CORP
Legal Status:	Private

GETTY REALTY CORP 58205 (Continued) **1001171396**

Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 125 JERICHO TNPK
Owner/Operator City,State,Zip: JERICHO, NY 11753
Owner/Operator Telephone: 516-286-2600
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20060101
Handler Name: GETTY REALTY CORP 58205
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: GETTY REALTY CORP 58205
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980708
Handler Name: GETTY REALTY CORP 58205
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

GETTY REALTY CORP 58205 (Continued) **1001171396**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110009462900

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001171396
Registry ID:	110009462900
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009462900
Name:	GETTY REALTY CORP 58205
Address:	63 8TH AVE
City,State,Zip:	NEW YORK, NY 10014

NY MANIFEST:

Name:	GETTY PETROLEUM CORP
Address:	63 8TH AVE
City,State,Zip:	NEW YORK, NY 10014-1609
Country:	USA
EPA ID:	NY0001492248
Facility Status:	Not reported
Location Address 1:	63 8TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NY0001492248
Mailing Name:	GETTY PETROLEUM CORP
Mailing Contact:	STEVE GORDON
Mailing Address 1:	63 8TH AVE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10014
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5162862600

BH875 **GETTY 58205** **NY UST** **U001838782**
SSE **63 EIGHTH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.234 mi.
1236 ft. **Site 14 of 19 in cluster BH**

Relative:
Higher

Actual:
22 ft.

UST:

Name:	GETTY 58205
Address:	63 EIGHTH AVENUE
City,State,Zip:	NEW YORK, NY 10014
Id/Status:	2-326283 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584133.55676
UTM Y:	4510265.69665
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	15196
Affiliation Type:	Facility Operator
Company Name:	GETTY NO. 58205
Contact Type:	Not reported
Contact Name:	VILLAGE GAS, INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 645-9578
EMail:	Not reported
Fax Number:	Not reported
Modified By:	bkfalvey
Date Last Modified:	2008-09-04

Site Id:	15196
Affiliation Type:	Mail Contact
Company Name:	GETTY PETROLEUM MARKETING, INC.
Contact Type:	AUTHORIZED SIGNATURE FOR CLIENT
Contact Name:	SCOTT HANLEY
Address1:	1500 HEMPSTEAD TURNPIKE
Address2:	Not reported
City:	EAST MEADOW
State:	NY
Zip Code:	11554
Country Code:	001
Phone:	(516) 542-4900
EMail:	SHANLEY@GETTY.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-04-04

Site Id:	15196
Affiliation Type:	Facility Owner
Company Name:	GETTY PETROLEUM MARKETING, INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1500 HEMPSTEAD TPK

GETTY 58205 (Continued) **U001838782**

Address2:	Not reported
City:	EAST MEADOW
State:	NY
Zip Code:	11554
Country Code:	001
Phone:	(516) 542-4900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-01-14

Site Id:	15196
Affiliation Type:	Emergency Contact
Company Name:	GETTY PETROLEUM MARKETING, INC.
Contact Type:	Not reported
Contact Name:	SCOTT HANLEY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 324-5110
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-02-03

Tank Info:

Tank Number:	001
Tank ID:	26485
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	09/01/1984
Date Tank Closed:	11/23/2011
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol

Tightness Test Method:	21
Date Test:	01/09/2008
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F05 - Pipe External Protection - Jacketed
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
L08 - Piping Leak Detection - Tank Top Sump
I01 - Overfill - Float Vent Valve
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)

GETTY 58205 (Continued) **U001838782**

K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G00 - Tank Secondary Containment - None
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
H99 - Tank Leak Detection - Other

Tank Number:	002
Tank ID:	26486
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	09/01/1984
Date Tank Closed:	11/23/2011
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	01/09/2008
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
F04 - Pipe External Protection - Fiberglass
G00 - Tank Secondary Containment - None
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
I01 - Overfill - Float Vent Valve
L08 - Piping Leak Detection - Tank Top Sump
F05 - Pipe External Protection - Jacketed
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
H99 - Tank Leak Detection - Other

Tank Number:	003
Tank ID:	26487
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	10/01/1974
Date Tank Closed:	11/23/2011
Registered:	True
Tank Location:	Underground

GETTY 58205 (Continued) **U001838782**

Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	21
Date Test:	01/09/2008
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
I01 - Overfill - Float Vent Valve
L08 - Piping Leak Detection - Tank Top Sump
H99 - Tank Leak Detection - Other
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F05 - Pipe External Protection - Jacketed
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin

BO876 **CON ED** **NY MANIFEST** **S118563615**
SE **242 W 16 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.234 mi.
1237 ft. **Site 2 of 9 in cluster BO**

Relative:
Higher

Actual:
23 ft.

NY MANIFEST:

Name:	CON ED
Address:	242 W 16 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004863813
Facility Status:	Not reported
Location Address 1:	242 W 16 ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004863813
Mailing Name:	CON ED
Mailing Contact:	CON ED
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003

CON ED (Continued) **S118563615**

Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

BO877 **CON EDISON - SERVICE BOX 2822** **NJ MANIFEST** **S120677803**
SE **242 W 16 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.234 mi.
1237 ft. **Site 3 of 9 in cluster BO**

Relative:
Higher

Actual:
23 ft.

NJ MANIFEST:
EPA Id: NYP004863813
Mail Address: IRVING PLACE, 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THERESA BURKARD
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 014085970JJK
EPA ID: NYP004863813
Date Shipped: 11/2/2015
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported

CON EDISON - SERVICE BOX 2822 (Continued) **S120677803**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

BO878 **CON EDISON** **NY MANIFEST** **S117058859**
SE **242-240 W 16TH ST & 8TH AVE E** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.234 mi.
1237 ft. **Site 4 of 9 in cluster BO**

Relative:
Higher

Actual:
23 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	242-240 W 16TH ST & 8TH AVE E
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004509964
Facility Status:	Not reported
Location Address 1:	242 W 16 ST & 8TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004509964
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/24/2014

CON EDISON (Continued) **S117058859**

Trans1 Recv Date:	04/24/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004509964
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002417107GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BO879 **CON EDISON - SERVICE BOX 2822** **RCRA-LQG** **1019325840**
SE **242 W 16 ST** **NYP004863813**
1/8-1/4 **NEW YORK, NY 10011**
0.234 mi.
1237 ft. **Site 5 of 9 in cluster BO**

Relative:
Higher

Actual:
23 ft.

RCRA-LQG:

Date Form Received by Agency:	20160226
Handler Name:	CON EDISON - SERVICE BOX 2822
Handler Address:	242 W 16 ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004863813
Contact Name:	THERESA BURKARD
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2262

CON EDISON - SERVICE BOX 2822 (Continued) **1019325840**

Contact Fax:	Not reported
Contact Email:	BURKARDT@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2015
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

CON EDISON - SERVICE BOX 2822 (Continued) **1019325840**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161107
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20151102
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20151102
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:
Receive Date: 20160226
Handler Name: CON EDISON - SERVICE BOX 2822
Federal Waste Generator Description: Large Quantity Generator

CON EDISON - SERVICE BOX 2822 (Continued) **1019325840**

State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

BK880 **GOLDEN EQUITIES CORP.** **NY AST** **U004046970**
NE **401 WEST 24TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.234 mi.
1238 ft. **Site 8 of 11 in cluster BK**

Relative:
Higher

Actual:
19 ft.

AST:

Name:	GOLDEN EQUITIES CORP.
Address:	401 WEST 24TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-108928
Program Type:	PBS
UTM X:	584317.32566
UTM Y:	4511200.34145
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	3247
Affiliation Type:	Facility Owner
Company Name:	GOLDEN EQUITIES CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	421 7TH AVENUE, SUITE 1500
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 564-7250
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT

GOLDEN EQUITIES CORP. (Continued) **U004046970**

Date Last Modified: 2004-03-04

Site Id: 3247
Affiliation Type: Mail Contact
Company Name: AAG MANAGEMENT, INC.
Contact Type: Not reported
Contact Name: DAVID GROSSMAN
Address1: 421 SEVENTH AVENUE
Address2: SUITE 1500
City: NEW YORK
State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 564-7250
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 3247
Affiliation Type: Facility Operator
Company Name: GOLDEN EQUITIES CORP.
Contact Type: Not reported
Contact Name: DAVID TAYLOR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 206-1790
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 3247
Affiliation Type: Emergency Contact
Company Name: GOLDEN EQUITIES CORP.
Contact Type: Not reported
Contact Name: DAVID TAYLOR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 206-1790
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank Id: 5493

GOLDEN EQUITIES CORP. (Continued) **U004046970**

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - In Place
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 07/09/1996
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

BP881 **PENSKE TRUCK LEASING CO L P** **RCRA NonGen / NLR** **1000382744**
NW **550 W 21ST ST** **FINDS** **NYD981563448**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.235 mi. **NY MANIFEST**
1240 ft. **Site 5 of 5 in cluster BP**

Relative: **Lower**
Actual: **5 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20070101
Handler Name: PENSKE TRUCK LEASING CO L P
Handler Address: 550 W 21ST ST
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYD981563448
Contact Name: Not reported
Contact Address: W 26TH ST
Contact City,State,Zip: NEW YORK, NY 10001
Contact Telephone: Not reported
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY
State District: NYSDEC R2

PENSKE TRUCK LEASING CO L P (Continued) **1000382744**

Mailing Address:	W 26TH ST
Mailing City,State,Zip:	NEW YORK, NY 10001
Owner Name:	LESLIE GARFIELD
Owner Type:	Private
Operator Name:	LESLIE GARFIELD
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

PENSKE TRUCK LEASING CO L P (Continued) **1000382744**

Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F004
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F005
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner

PENSKE TRUCK LEASING CO L P (Continued) **1000382744**

Owner/Operator Name:	LESLIE GARFIELD
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	LESLIE GARFIELD
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	LESLIE GARFIELD
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19950517
Handler Name:	PENSKE TRUCK LEASING CO L P
Federal Waste Generator Description:	Not reported
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name:	PENSKE TRUCK LEASING CO L P
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

PENSKE TRUCK LEASING CO L P (Continued) **1000382744**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: PENSKE TRUCK LEASING CO L P
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19861021
Handler Name: PENSKE TRUCK LEASING CO L P
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004409907

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

PENSKE TRUCK LEASING CO L P (Continued) **1000382744**

ECHO:

Envid:	1000382744
Registry ID:	110004409907
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004409907
Name:	PENSKE TRUCK LEASING CO L P
Address:	550 W 21ST ST
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	PENSKE TRUCK LEASING
Address:	550 W 21ST ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYD981563448
Facility Status:	Not reported
Location Address 1:	550 WEST 21ST STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD981563448
Mailing Name:	PENSKE TRUCK LEASING
Mailing Contact:	WILFREDO SANTIAGO
Mailing Address 1:	550 WEST 21ST STREET
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2017419800

BQ882 **264 WEST 22ND STREET OWNERS INC.** **NY AST** **U003392797**
East **264 WEST 22ND STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.235 mi.
1243 ft. **Site 4 of 13 in cluster BQ**

Relative:
Higher

Actual:
22 ft.

AST:

Name:	264 WEST 22ND STREET OWNERS INC.
Address:	264 WEST 22ND STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-247227
Program Type:	PBS
UTM X:	584631.18381
UTM Y:	4510848.89506
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

264 WEST 22ND STREET OWNERS INC. (Continued) **U003392797**

Affiliation Records:

Site Id:	9707
Affiliation Type:	Facility Owner
Company Name:	264 W. 22ND STREET OWNERS INC
Contact Type:	AGENT
Contact Name:	DAVID WAGNER
Address1:	264 W 22ND STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 382-3600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2011-10-27

Site Id:	9707
Affiliation Type:	Mail Contact
Company Name:	SKILLMAN PLUMBING
Contact Type:	Not reported
Contact Name:	DAVID WAGNER
Address1:	151-01 14TH AVE
Address2:	Not reported
City:	WHITESTONE
State:	NY
Zip Code:	11357
Country Code:	001
Phone:	(718) 457-7229
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2011-10-27

Site Id:	9707
Affiliation Type:	Facility Operator
Company Name:	264 WEST 22ND STREET OWNERS INC.
Contact Type:	Not reported
Contact Name:	ADVANCED MANAGEMENT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 382-3600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9707
Affiliation Type:	Emergency Contact
Company Name:	264 W. 22ND STREET OWNERS INC
Contact Type:	Not reported
Contact Name:	ADVANCED MANAGEMENT

264 WEST 22ND STREET OWNERS INC. (Continued) **U003392797**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 334-9822
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	25431
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	K00 - Spill Prevention - None
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	E00 - Piping Secondary Containment - None
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	L09 - Piping Leak Detection - Exempt Suction Piping
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	12/21/1938
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/26/2011
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

BE883 **345 W. 4TH-306 W. 13TH OWNERS CORP** **NY AST** **U003393103**
South **345 W 4 STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.236 mi.
1248 ft. **Site 8 of 10 in cluster BE**

Relative:
Higher

Actual:
21 ft.

AST:

Name:	345 W. 4TH-306 W. 13TH OWNERS CORP
Address:	345 W 4 STREET
City,State,Zip:	NEW YORK, NY 10014
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-373419
Program Type:	PBS
UTM X:	584116.37400
UTM Y:	4510265.80375
Expiration Date:	10/23/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	18747
Affiliation Type:	Facility Owner
Company Name:	345 W 4TH /306 W 13 ST OWNERS
Contact Type:	PRESIDENT
Contact Name:	SEAN ROBERTS
Address1:	666 BROADWAY, 12TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 259-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-10-27

Site Id:	18747
Affiliation Type:	Mail Contact
Company Name:	C/O ANDREWS ORGANIZATION
Contact Type:	Not reported
Contact Name:	345 W 4TH /306 W 13 ST OWNERS
Address1:	666 BROADWAY 12TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-10-27

Site Id:	18747
Affiliation Type:	Facility Operator
Company Name:	345 W. 4TH-306 W. 13TH OWNERS CORP
Contact Type:	Not reported
Contact Name:	ANGEL COREAS

345 W. 4TH-306 W. 13TH OWNERS CORP (Continued) **U003393103**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 734-1956
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2007-08-17

Site Id:	18747
Affiliation Type:	Emergency Contact
Company Name:	345 W 4TH /306 W 13 ST OWNERS
Contact Type:	Not reported
Contact Name:	ANDREWS ORG.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-10-27

Tank Info:

Tank Number:	052
Tank Id:	26010
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	I04 - Overfill - Product Level Gauge (A/G)
	K00 - Spill Prevention - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	J02 - Dispenser - Suction Dispenser
	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	E00 - Piping Secondary Containment - None
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/28/1953
Capacity Gallons:	2000

345 W. 4TH-306 W. 13TH OWNERS CORP (Continued) **U003393103**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	10/27/2017
Material Name:	#2 fuel oil (on-site consumption)

BD884 **CHELSEA 19 CONDOMINIUM C/O SOLSTICE** **NY AST** **U003390890**
ESE **251 WEST 19TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.237 mi.
1251 ft. **Site 7 of 9 in cluster BD**

Relative:
Higher

Actual:
23 ft.

AST:

Name:	CHELSEA 19 CONDOMINIUM C/O SOLSTICE
Address:	251 WEST 19TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-332372
Program Type:	PBS
UTM X:	584492.62670
UTM Y:	4510656.21858
Expiration Date:	02/13/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	15729
Affiliation Type:	Facility Operator
Company Name:	CHELSEA 19 CONDOMINIUM C/O SOLSTICE
Contact Type:	Not reported
Contact Name:	JEAN JADOTTE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 691-9542
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-08-20

Site Id:	15729
Affiliation Type:	Emergency Contact
Company Name:	CHELSEA 19 CONDOMINIUM % ORSID REALTY CORP.
Contact Type:	Not reported
Contact Name:	JEN JADOTTE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999

CHELSEA 19 CONDOMINIUM C/O SOLSTICE (Continued) **U003390890**

Phone:	(212) 691-9542
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-08-20

Site Id:	15729
Affiliation Type:	Facility Owner
Company Name:	CHELSEA 19 CONDOMINIUM % ORSID REALTY CORP.
Contact Type:	DIR
Contact Name:	PIERRE ZARZOUR
Address1:	251 WEST 19TH ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 753-2329
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-08-20

Site Id:	15729
Affiliation Type:	Mail Contact
Company Name:	CHELSEA 19 CONDOMINIUM % ORSID REALTY CORP.
Contact Type:	Not reported
Contact Name:	PIERRE ZARZOUR
Address1:	257 PARK AVE. STE 303
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10010
Country Code:	001
Phone:	(212) 753-2329
EMail:	AKALAJIAN@SOLCTICE.US.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-06-05

Tank Info:

Tank Number:	001
Tank Id:	39750
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B05 - Tank External Protection - Jacketed
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

CHELSEA 19 CONDOMINIUM C/O SOLSTICE (Continued) **U003390890**

	D01 - Pipe Type - Steel/Carbon Steel/Iron
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/05/2001
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	001
Tank Id:	20322
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	I04 - Overfill - Product Level Gauge (A/G)
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
	E00 - Piping Secondary Containment - None
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	K00 - Spill Prevention - None
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/15/1980
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Affiliation Records:

Site Id:	21870
Affiliation Type:	Facility Owner
Company Name:	Z & R MANAGEMENT%H ZWEIBON

CHELSEA 19 CONDOMINIUM C/O SOLSTICE (Continued) **U003390890**

Contact Type:	Not reported
Contact Name:	Not reported
Address1:	147 EAST 76TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10021
Country Code:	001
Phone:	(212) 879-4842
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	21870
Affiliation Type:	Mail Contact
Company Name:	Z & R MANAGEMENT%H ZWEIBON
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	147 EAST 76TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10021
Country Code:	001
Phone:	(212) 879-4842
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	21870
Affiliation Type:	Facility Operator
Company Name:	251/53 WEST 19TH STREET
Contact Type:	Not reported
Contact Name:	CARMEN LULUZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 929-7173
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	21870
Affiliation Type:	Emergency Contact
Company Name:	Z & R MANAGEMENT%H ZWEIBON
Contact Type:	Not reported
Contact Name:	MARK ZWEIBON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

CHELSEA 19 CONDOMINIUM C/O SOLSTICE (Continued) **U003390890**

Zip Code:	Not reported
Country Code:	001
Phone:	(800) 777-4753
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	39750
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B05 - Tank External Protection - Jacketed
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/05/2001
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	001
Tank Id:	20322
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

CHELSEA 19 CONDOMINIUM C/O SOLSTICE (Continued) **U003390890**

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/15/1980
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

BD885 **SPILL NUMBER 0010929** **NY LTANKS** **S104877546**
ESE **251 W. 19TH ST** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.237 mi.
1251 ft. **Site 8 of 9 in cluster BD**

Relative: **Higher**
Actual: **23 ft.**

LTANKS:

Name:	SPILL NUMBER 0010929
Address:	251 W. 19TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0010929 / 2003-07-29
Facility ID:	0010929
Site ID:	267564
Spill Date:	2000-01-03
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2001-01-04
CID:	322
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-01-04
Spill Record Last Update:	2003-07-29
Spiller Name:	HERB
Spiller Company:	Not reported
Spiller Address:	251 W. 19TH ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported

SPILL NUMBER 0010929 (Continued) **S104877546**

Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	217968
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND "
Remarks:	"tank test failure - leaking manhole cover and this has been repaired already "

All TTF:

Facility ID:	0010929
Spill Number:	0010929
Spill Tank Test:	1526042
Site ID:	267564
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	267564
Operable Unit ID:	832315
Operable Unit:	01
Material ID:	544803
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BR886 **CON EDISON SERVICE BOX: 4436** **RCRA NonGen / NLR** **1016450084**
NNE **445 W 24TH ST** **NY MANIFEST** **NYP004290805**
1/8-1/4 **NEW YORK, NY 10011**
0.237 mi.
1251 ft. **Site 1 of 3 in cluster BR**

Relative:
Higher

Actual:
15 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	20130404
Handler Name:	CON EDISON SERVICE BOX: 4436
Handler Address:	445 W 24TH ST
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004290805
Contact Name:	JUAN RODRIGUEZ
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	347-865-5931

CON EDISON SERVICE BOX: 4436 (Continued) **1016450084**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

CON EDISON SERVICE BOX: 4436 (Continued) **1016450084**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130304
Handler Name: CON EDISON SERVICE BOX:	4436
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130404
Handler Name: CON EDISON SERVICE BOX:	4436
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON SERVICE BOX: 4436 (Continued) **1016450084**

NY MANIFEST:

Name:	CON EDISON
Address:	445 W 24TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004290805
Facility Status:	Not reported
Location Address 1:	445 W 24TH ST
Code:	BP
Location Address 2:	SERV BOX 4436
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004290805
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/04/2013
Trans1 Recv Date:	03/04/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/04/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004290805
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010841216JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON SERVICE BOX: 4436 (Continued) **1016450084**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BR887 **CON EDISON SERVICE BOX: 4436** **NJ MANIFEST** **S120665944**
NNE **445 W 24TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.237 mi.
1251 ft. **Site 2 of 3 in cluster BR**

Relative:
Higher

Actual:
15 ft.

NJ MANIFEST:

EPA Id:	NYP004290805
Mail Address:	Not reported
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JUAN RODRIGUEZ
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015320287JJK
EPA ID:	NYP004290805
Date Shipped:	12/11/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

CON EDISON SERVICE BOX: 4436 (Continued) **S120665944**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

BK888 **SILVERBOW REALTY CO** **NY AST** **U003384541**
NNE **415 WEST 24TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10001**
0.237 mi.
1252 ft. **Site 9 of 11 in cluster BK**

Relative:
Higher

Actual:
17 ft.

AST:

Name:	SILVERBOW REALTY CO
Address:	415 WEST 24TH ST
City,State,Zip:	NEW YORK, NY 10001
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-109142
Program Type:	PBS
UTM X:	584288.87690
UTM Y:	4511215.75501
Expiration Date:	03/24/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	3266
Affiliation Type:	Facility Owner
Company Name:	SILVERBOW REALTY CO, INC C/O AJ CLARKE RECORP
Contact Type:	AGENT
Contact Name:	STEPHEN DENARDO

SILVERBOW REALTY CO (Continued) **U003384541**

Address1:	1881 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10023
Country Code:	001
Phone:	(212) 541-4477
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-05-01

Site Id:	3266
Affiliation Type:	Mail Contact
Company Name:	AJ CLARKE RECORP
Contact Type:	Not reported
Contact Name:	STEPHEN DENARDO
Address1:	1881 BROADWAY
Address2:	4TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10023
Country Code:	001
Phone:	(212) 541-4477
EMail:	SDENARDO@AJCLARKENYC.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-05-01

Site Id:	3266
Affiliation Type:	Facility Operator
Company Name:	SILVERBOW REALTY CO
Contact Type:	Not reported
Contact Name:	TITO MUNOZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 203-5523
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-05-01

Site Id:	3266
Affiliation Type:	Emergency Contact
Company Name:	SILVERBOW REALTY CO, INC C/O AJ CLARKE RECORP
Contact Type:	Not reported
Contact Name:	STEPHEN DENARDO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999

SILVERBOW REALTY CO (Continued) **U003384541**

Phone:	(212) 541-4477
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2012-02-02

Tank Info:

Tank Number:	001
Tank Id:	3935
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	B00 - Tank External Protection - None
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	C01 - Pipe Location - Aboveground
	I04 - Overfill - Product Level Gauge (A/G)
	E00 - Piping Secondary Containment - None
	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/17/1929
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	05/01/2017
Material Name:	#2 fuel oil (on-site consumption)

BK889 **CON EDISON** **NY MANIFEST** **S117319042**
NNE **411 W 24TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.237 mi.
1253 ft. **Site 10 of 11 in cluster BK**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	411 W 24TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004666749
Facility Status:	Not reported
Location Address 1:	411 W 24TH ST
Code:	BP
Location Address 2:	SB 4441

CON EDISON (Continued) **S117319042**

Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004666749
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/26/2014
Trans1 Recv Date:	09/26/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/30/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004666749
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002609694GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds

CON EDISON (Continued) **S117319042**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BS890 **CON EDISON SERVICE BOX: 4162** **RCRA NonGen / NLR** **1016143327**
North **525 W 23RD ST** **NY MANIFEST** **NYP004260642**
1/8-1/4 **NEW YORK, NY 10014**
0.238 mi.
1256 ft. **Site 1 of 7 in cluster BS**

Relative: RCRA NonGen / NLR:
Lower

Actual: Date Form Received by Agency:		20130321
10 ft. Handler Name:	CON EDISON SERVICE BOX:	4162
Handler Address:		525 W 23RD ST
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004260642
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No

CON EDISON SERVICE BOX: 4162 (Continued) **1016143327**

Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130221
Handler Name: CON EDISON SERVICE BOX:	4162
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 4162 (Continued) **1016143327**

Electronic Manifest Broker: Not reported

Receive Date: 20130321
Handler Name: CON EDISON SERVICE BOX: 4162
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 525 W 23RD ST
City,State,Zip: NEW YORK, NY 10014
Country: USA
EPA ID: NYP004260642
Facility Status: Not reported
Location Address 1: 525 W 23RD ST
Code: BP
Location Address 2: SERV BOX 4162
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004260642
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:

CON EDISON SERVICE BOX: 4162 (Continued) **1016143327**

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/21/2013
Trans1 Recv Date:	02/21/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/21/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004260642
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010846500JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BQ891 **NISHI CLEANERS** **RCRA NonGen / NLR** **1010415694**
ENE **244 8TH AVE** **NY MANIFEST** **NYD981559545**
1/8-1/4 **NEW YORK, NY 10011**
0.238 mi.
1258 ft. **Site 5 of 13 in cluster BQ**

Relative: **Higher**
Actual: **22 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	NISHI CLEANERS	
Handler Address:		244 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYD981559545
Contact Name:		CATHERINE KWON
Contact Address:		8TH AVE
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		212-741-0958
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		8TH AVE
Mailing City,State,Zip:		NEW YORK, NY 10011
Owner Name:		CATHERINE KWON
Owner Type:		Private
Operator Name:		CATHERINE KWON
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

NISHI CLEANERS (Continued) **1010415694**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined

Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CATHERINE KWON
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	244 8TH AVE
Owner/Operator City,State,Zip:	NEW YORK, NY 10011
Owner/Operator Telephone:	212-555-1212

NISHI CLEANERS (Continued) **1010415694**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CATHERINE KWON
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 244 8TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CATHERINE KWON
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 244 8TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990714
Handler Name: NISHI CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: NISHI CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NISHI CLEANERS

NISHI CLEANERS (Continued) **1010415694**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19991108
Handler Name: NISHI CLEANERS	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	L & K CLEANERS INCORPORATED
Address:	244 8TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYD981559545
Facility Status:	Not reported
Location Address 1:	244 8TH AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD981559545
Mailing Name:	L & K CLEANERS INCORPORATED
Mailing Contact:	YONUNG HUN KWON
Mailing Address 1:	244 8TH AVENUE
Mailing Address 2:	Not reported

NISHI CLEANERS (Continued) **1010415694**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2127410958

BQ892 **PETERS DRY CLEANERS** **RCRA NonGen / NLR** **1000217529**
ENE **244 8TH AVE** **ICIS** **NYD982534521**
1/8-1/4 **NEW YORK, NY 10011** **US AIRS**
0.238 mi. **FINDS**
1258 ft. **Site 6 of 13 in cluster BQ**

Relative: **Higher**
Actual: **22 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	PETERS DRY CLEANERS	
Handler Address:		244 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYD982534521
Contact Name:		Not reported
Contact Address:		8TH AVE
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		8TH AVE
Mailing City,State,Zip:		NEW YORK, NY 10011
Owner Name:		PAUL KIM
Owner Type:		Private
Operator Name:		PAUL KIM
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

PETERS DRY CLEANERS (Continued) **1000217529**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

PETERS DRY CLEANERS (Continued) **1000217529**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	PAUL KIM
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	PAUL KIM
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	PAUL KIM
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: PETERS DRY CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: PETERS DRY CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

PETERS DRY CLEANERS (Continued) **1000217529**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: PETERS DRY CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19880314
Handler Name: PETERS DRY CLEANERS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

ICIS:

Enforcement Action ID:	NY000A0000262050155600309
FRS ID:	110002367563
Action Name:	NISHI CLEANERS 36061R076200309
Facility Name:	NISHI CLEANERS
Facility Address:	244 EIGHTH AVE NEW YORK, NY 10011
Enforcement Action Type:	Notice of Violation
Facility County:	BRONX
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal

PETERS DRY CLEANERS (Continued) **1000217529**

EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.74494
Longitude in Decimal Degrees:	-73.99875
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002620501556
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000262050155600303
FRS ID:	110002367563
Action Name:	NISHI CLEANERS 36061R076200303
Facility Name:	NISHI CLEANERS
Facility Address:	244 EIGHTH AVE NEW YORK, NY 10011
Enforcement Action Type:	Administrative Order
Facility County:	BRONX
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	SCAAAO
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.74494
Longitude in Decimal Degrees:	-73.99875
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002620501556
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000262050155600301
FRS ID:	110002367563
Action Name:	NISHI CLEANERS 36061R076200301
Facility Name:	NISHI CLEANERS
Facility Address:	244 EIGHTH AVE NEW YORK, NY 10011
Enforcement Action Type:	Notice of Violation
Facility County:	BRONX
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.74494
Longitude in Decimal Degrees:	-73.99875
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002620501556
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

US AIRS MINOR:

Envid:	1000217529
Region Code:	02
Programmatic ID:	AIR NY0000002620501556
Facility Registry ID:	110002367563
D and B Number:	Not reported

PETERS DRY CLEANERS (Continued) **1000217529**

Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002620501556
Facility Registry ID: 110002367563
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-07-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620501556
Facility Registry ID: 110002367563
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2001-07-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620501556
Facility Registry ID: 110002367563
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2001-08-13 00:00:00
Activity Status Date: 2001-08-13 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 02
Programmatic ID: AIR NY0000002620501556
Facility Registry ID: 110002367563
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2001-07-05 00:00:00
Activity Status Date: 2001-07-05 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002620501556

PETERS DRY CLEANERS (Continued) **1000217529**

Facility Registry ID: 110002367563
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2003-05-15 00:00:00
Activity Status Date: 2003-05-15 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002620501556
Facility Registry ID: 110002367563
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-07-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620501556
Facility Registry ID: 110002367563
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-07-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620501556
Facility Registry ID: 110002367563
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-08-13 00:00:00
Activity Status Date: 2001-08-13 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 02
Programmatic ID: AIR NY0000002620501556
Facility Registry ID: 110002367563
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-07-05 00:00:00
Activity Status Date: 2001-07-05 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

PETERS DRY CLEANERS (Continued) **1000217529**

FINDS:
Registry ID: 110002367563

Click Here:

Environmental Interest/Information System:
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

BK893 **OXFORD DRY CLEANERS** **RCRA-SQG** **1000117351**
NE **232 9TH AVENUE** **FINDS** **NYD981492663**
1/8-1/4 **NEW YORK, NY 10001** **ECHO**
0.238 mi. **NY DRYCLEANERS**
1259 ft. **Site 11 of 11 in cluster BK** **NY MANIFEST**

Relative:
Higher

Actual:
19 ft.

RCRA-SQG:

Date Form Received by Agency:		20070101
Handler Name:	ONE HOUR MARTINIZING	
Handler Address:		232 9TH AVE
Handler City,State,Zip:		NEW YORK, NY 10001
EPA ID:		NYD981492663
Contact Name:		Not reported
Contact Address:		9TH AVE
Contact City,State,Zip:		NEW YORK, NY 10001
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2

OXFORD DRY CLEANERS (Continued) **1000117351**

Mailing Address:	9TH AVE
Mailing City,State,Zip:	NEW YORK, NY 10001
Owner Name:	CLIFF MADANER
Owner Type:	Private
Operator Name:	CLIFF MADANER
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

OXFORD DRY CLEANERS (Continued) **1000117351**

Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined

Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CLIFF MADANER
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CLIFF MADANER
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CLIFF MADANER
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

OXFORD DRY CLEANERS (Continued) **1000117351**

Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19990714
Handler Name: ONE HOUR MARTINIZING
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: ONE HOUR MARTINIZING
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ONE HOUR MARTINIZING
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19860709
Handler Name: ONE HOUR MARTINIZING
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:

OXFORD DRY CLEANERS (Continued) **1000117351**

NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19930816
Evaluation Responsible Agency: EPA Contractor/Grantee
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2TRC
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

OXFORD DRY CLEANERS (Continued) **1000117351**

FINDS:
Registry ID: 110013326837

Click Here:

Environmental Interest/Information System:
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000117351
Registry ID:	110013326837
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110013326837
Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001

DRYCLEANERS:

Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001 6602
Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2003-05-28 11:41:46
Inspection Date:	2001-11-15 07:00:00
Install Date:	Not reported
Expiration Date:	02/28/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name: OXFORD DRY CLEANERS

OXFORD DRY CLEANERS (Continued) **1000117351**

Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001 6602
Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2003-05-28 11:41:46
Inspection Date:	2003-06-13 10:35:00
Install Date:	Not reported
Expiration Date:	02/28/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001 6602
Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2003-05-28 11:41:46
Inspection Date:	2004-06-10 08:05:00
Install Date:	Not reported
Expiration Date:	02/28/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001 6602
Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2003-05-28 11:41:46
Inspection Date:	2005-07-12 11:10:00
Install Date:	Not reported
Expiration Date:	02/28/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001 6602
Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2003-05-28 11:41:46
Inspection Date:	2006-06-06 08:05:00
Install Date:	Not reported
Expiration Date:	02/28/2019

OXFORD DRY CLEANERS (Continued) **1000117351**

Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: OXFORD DRY CLEANERS
Address: 232 9TH AVENUE
City,State,Zip: NEW YORK, NY 10001 6602
Facility ID: 2-6205-00294
Phone Number: 2122557317
Region: Not reported
Registration Effective Date: 2003-05-28 11:41:46
Inspection Date: 2007-06-12 11:10:00
Install Date: Not reported
Expiration Date: 02/28/2019
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: OXFORD DRY CLEANERS
Address: 232 9TH AVENUE
City,State,Zip: NEW YORK, NY 10001 6602
Facility ID: 2-6205-00294
Phone Number: 2122557317
Region: Not reported
Registration Effective Date: 2003-05-28 11:41:46
Inspection Date: 2008-06-10 08:20:00
Install Date: Not reported
Expiration Date: 02/28/2019
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: OXFORD DRY CLEANERS
Address: 232 9TH AVENUE
City,State,Zip: NEW YORK, NY 10001 6602
Facility ID: 2-6205-00294
Phone Number: 2122557317
Region: Not reported
Registration Effective Date: 2003-05-28 11:41:46
Inspection Date: 2009-08-13 13:30:00
Install Date: Not reported
Expiration Date: 02/28/2019
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: OXFORD DRY CLEANERS
Address: 232 9TH AVENUE
City,State,Zip: NEW YORK, NY 10001 6602

OXFORD DRY CLEANERS (Continued) **1000117351**

Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2003-05-28 11:41:46
Inspection Date:	2010-06-10 11:00:00
Install Date:	Not reported
Expiration Date:	02/28/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001 6602
Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2003-05-28 11:41:46
Inspection Date:	2011-06-07 11:00:00
Install Date:	Not reported
Expiration Date:	02/28/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001 6602
Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2003-05-28 11:41:46
Inspection Date:	2012-06-20 08:20:00
Install Date:	Not reported
Expiration Date:	02/28/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001 6602
Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2003-05-28 11:41:46
Inspection Date:	2013-06-19 08:20:00
Install Date:	Not reported
Expiration Date:	02/28/2019
Removal Date:	Not reported
Drop Shop:	Not reported

OXFORD DRY CLEANERS (Continued) **1000117351**

Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: OXFORD DRY CLEANERS
Address: 232 9TH AVENUE
City,State,Zip: NEW YORK, NY 10001 6602
Facility ID: 2-6205-00294
Phone Number: 2122557317
Region: Not reported
Registration Effective Date: 2003-05-28 11:41:46
Inspection Date: 2014-08-07 11:00:00
Install Date: Not reported
Expiration Date: 02/28/2019
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: OXFORD DRY CLEANERS
Address: 232 9TH AVENUE
City,State,Zip: NEW YORK, NY 10001 6602
Facility ID: 2-6205-00294
Phone Number: 2122557317
Region: Not reported
Registration Effective Date: 2003-05-28 11:41:46
Inspection Date: 2015-06-24 08:30:00
Install Date: Not reported
Expiration Date: 02/28/2019
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: OXFORD DRY CLEANERS
Address: 232 9TH AVENUE
City,State,Zip: NEW YORK, NY 10001 6602
Facility ID: 2-6205-00294
Phone Number: 2122557317
Region: Not reported
Registration Effective Date: 2003-05-28 11:41:46
Inspection Date: 2016-06-15 08:10:00
Install Date: Not reported
Expiration Date: 02/28/2019
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: OXFORD DRY CLEANERS
Address: 232 9TH AVENUE
City,State,Zip: NEW YORK, NY 10001 6602
Facility ID: 2-6205-00294
Phone Number: 2122557317

OXFORD DRY CLEANERS (Continued) **1000117351**

Region: Not reported
Registration Effective Date: 2003-05-28 11:41:46
Inspection Date: 2017-06-02 08:00:00
Install Date: Not reported
Expiration Date: 02/28/2019
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: OXFORD DRY CLEANERS
Address: 232 9TH AVENUE
City,State,Zip: NEW YORK, NY 10001 6602
Facility ID: 2-6205-00294
Phone Number: 2122557317
Region: Not reported
Registration Effective Date: 2003-05-28 11:41:46
Inspection Date: 2018-06-08 08:30:00
Install Date: Not reported
Expiration Date: 02/28/2019
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: OXFORD DRY CLEANERS
Address: 232 9TH AVENUE
City,State,Zip: NEW YORK, NY 10001 6602
Facility ID: 2-6205-00294
Phone Number: 2122557317
Region: Not reported
Registration Effective Date: 2003-05-28 11:41:46
Inspection Date: 2019-05-02 11:00:00
Install Date: Not reported
Expiration Date: 02/28/2019
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: OXFORD DRY CLEANERS
Address: 232 9TH AVENUE
City,State,Zip: NEW YORK, NY 10001 6602
Facility ID: 2-6205-00294
Phone Number: 2122557317
Region: Not reported
Registration Effective Date: 2019-02-28 16:47:28
Inspection Date: 2001-11-15 07:00:00
Install Date: Not reported
Expiration Date: 03/01/2029
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4

OXFORD DRY CLEANERS (Continued) **1000117351**

Current Business: Not reported

Name: OXFORD DRY CLEANERS
Address: 232 9TH AVENUE
City,State,Zip: NEW YORK, NY 10001 6602
Facility ID: 2-6205-00294
Phone Number: 2122557317
Region: Not reported
Registration Effective Date: 2019-02-28 16:47:28
Inspection Date: 2003-06-13 10:35:00
Install Date: Not reported
Expiration Date: 03/01/2029
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: OXFORD DRY CLEANERS
Address: 232 9TH AVENUE
City,State,Zip: NEW YORK, NY 10001 6602
Facility ID: 2-6205-00294
Phone Number: 2122557317
Region: Not reported
Registration Effective Date: 2019-02-28 16:47:28
Inspection Date: 2004-06-10 08:05:00
Install Date: Not reported
Expiration Date: 03/01/2029
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: OXFORD DRY CLEANERS
Address: 232 9TH AVENUE
City,State,Zip: NEW YORK, NY 10001 6602
Facility ID: 2-6205-00294
Phone Number: 2122557317
Region: Not reported
Registration Effective Date: 2019-02-28 16:47:28
Inspection Date: 2005-07-12 11:10:00
Install Date: Not reported
Expiration Date: 03/01/2029
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: OXFORD DRY CLEANERS
Address: 232 9TH AVENUE
City,State,Zip: NEW YORK, NY 10001 6602
Facility ID: 2-6205-00294
Phone Number: 2122557317
Region: Not reported
Registration Effective Date: 2019-02-28 16:47:28

OXFORD DRY CLEANERS (Continued) **1000117351**

Inspection Date:	2006-06-06 08:05:00
Install Date:	Not reported
Expiration Date:	03/01/2029
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001 6602
Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2019-02-28 16:47:28
Inspection Date:	2007-06-12 11:10:00
Install Date:	Not reported
Expiration Date:	03/01/2029
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001 6602
Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2019-02-28 16:47:28
Inspection Date:	2008-06-10 08:20:00
Install Date:	Not reported
Expiration Date:	03/01/2029
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001 6602
Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2019-02-28 16:47:28
Inspection Date:	2009-08-13 13:30:00
Install Date:	Not reported
Expiration Date:	03/01/2029
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

OXFORD DRY CLEANERS (Continued) **1000117351**

Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001 6602
Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2019-02-28 16:47:28
Inspection Date:	2010-06-10 11:00:00
Install Date:	Not reported
Expiration Date:	03/01/2029
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001 6602
Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2019-02-28 16:47:28
Inspection Date:	2011-06-07 11:00:00
Install Date:	Not reported
Expiration Date:	03/01/2029
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001 6602
Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2019-02-28 16:47:28
Inspection Date:	2012-06-20 08:20:00
Install Date:	Not reported
Expiration Date:	03/01/2029
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001 6602
Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2019-02-28 16:47:28
Inspection Date:	2013-06-19 08:20:00
Install Date:	Not reported

OXFORD DRY CLEANERS (Continued) **1000117351**

Expiration Date:	03/01/2029
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001 6602
Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2019-02-28 16:47:28
Inspection Date:	2014-08-07 11:00:00
Install Date:	Not reported
Expiration Date:	03/01/2029
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001 6602
Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2019-02-28 16:47:28
Inspection Date:	2015-06-24 08:30:00
Install Date:	Not reported
Expiration Date:	03/01/2029
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE
City,State,Zip:	NEW YORK, NY 10001 6602
Facility ID:	2-6205-00294
Phone Number:	2122557317
Region:	Not reported
Registration Effective Date:	2019-02-28 16:47:28
Inspection Date:	2016-06-15 08:10:00
Install Date:	Not reported
Expiration Date:	03/01/2029
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	OXFORD DRY CLEANERS
Address:	232 9TH AVENUE

OXFORD DRY CLEANERS (Continued) **1000117351**

City,State,Zip: NEW YORK, NY 10001 6602
Facility ID: 2-6205-00294
Phone Number: 2122557317
Region: Not reported
Registration Effective Date: 2019-02-28 16:47:28
Inspection Date: 2017-06-02 08:00:00
Install Date: Not reported
Expiration Date: 03/01/2029
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: OXFORD DRY CLEANERS
Address: 232 9TH AVENUE
City,State,Zip: NEW YORK, NY 10001 6602
Facility ID: 2-6205-00294
Phone Number: 2122557317
Region: Not reported
Registration Effective Date: 2019-02-28 16:47:28
Inspection Date: 2018-06-08 08:30:00
Install Date: Not reported
Expiration Date: 03/01/2029
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: OXFORD DRY CLEANERS
Address: 232 9TH AVENUE
City,State,Zip: NEW YORK, NY 10001 6602
Facility ID: 2-6205-00294
Phone Number: 2122557317
Region: Not reported
Registration Effective Date: 2019-02-28 16:47:28
Inspection Date: 2019-05-02 11:00:00
Install Date: Not reported
Expiration Date: 03/01/2029
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

NY MANIFEST:
Name: OXFORD CLEANERS
Address: 232 9TH AVE
City,State,Zip: NEW YORK, NY 10001
Country: USA
EPA ID: NYD981492663
Facility Status: Not reported
Location Address 1: 232 9TH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported

OXFORD DRY CLEANERS (Continued) **1000117351**

Location City:	NEW YORK
Location State:	NY
Location Zip:	10001
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD981492663
Mailing Name:	OXFORD CLEANERS
Mailing Contact:	OXFORD CLEANERS
Mailing Address 1:	232 9TH AVE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10001
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2122439464

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD000564906
Trans2 State ID:	MIK814262374
Generator Ship Date:	12/19/2013
Trans1 Recv Date:	12/19/2013
Trans2 Recv Date:	12/23/2013
TSD Site Recv Date:	12/23/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981492663
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CDX107000000
TSDF ID 2:	Not reported
Manifest Tracking Number:	011613051JJK
Import Indicator:	N
Export Indicator:	Y
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	130
Units:	P - Pounds
Number of Containers:	1

OXFORD DRY CLEANERS (Continued) **1000117351**

Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	D039
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BH894 **BONJOUR CLEANERS** **RCRA NonGen / NLR** **1000265721**
SSE **252 W 14TH ST** **FINDS** **NYD125665075**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.239 mi. **NY MANIFEST**
1260 ft. **Site 15 of 19 in cluster BH**

Relative: **Higher**
Actual: **23 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	BONJOUR CLEANERS	
Handler Address:		252 W 14TH ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYD125665075
Contact Name:		Not reported
Contact Address:		W 14TH ST
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		W 14TH ST
Mailing City,State,Zip:		NEW YORK, NY 10011
Owner Name:		SAM GEORGAS
Owner Type:		Private
Operator Name:		SAM GEORGAS
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No

BONJOUR CLEANERS (Continued) **1000265721**

Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND

BONJOUR CLEANERS (Continued) **1000265721**

SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	SAM GEORGAS
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SAM GEORGAS
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SAM GEORGAS
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: BONJOUR CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: BONJOUR CLEANERS	
Federal Waste Generator Description:	Not a generator, verified

BONJOUR CLEANERS (Continued) **1000265721**

State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: BONJOUR CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19860709
Handler Name: BONJOUR CLEANERS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004382187

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

BONJOUR CLEANERS (Continued) **1000265721**

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000265721
Registry ID:	110004382187
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004382187
Name:	BONJOUR CLEANERS
Address:	252 W 14TH ST
City,State,Zip:	NEW YORK, NY 10011

NY MANIFEST:

Name:	BONJOUR CLEANERS
Address:	252 W 14TH ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYD125665075
Facility Status:	Not reported
Location Address 1:	252 WEST 14TH STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD125665075
Mailing Name:	BONJOUR CLEANERS
Mailing Contact:	BONJOUR CLEANERS
Mailing Address 1:	252 WEST 14 STREET
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2129244863

BT895 **PIER 57** **NY MANIFEST** **S118708625**
West **25 11TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.239 mi.
1261 ft. **Site 1 of 4 in cluster BT**

Relative:
Lower

Actual:
1 ft.

NY MANIFEST:

Name:	PIER 57
Address:	25 11TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYR000226514
Facility Status:	Not reported
Location Address 1:	25 11TH AVENUE

PIER 57 (Continued) **S118708625**

Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000226514
Mailing Name:	PIER 57
Mailing Contact:	PIER 57
Mailing Address 1:	230 PARK AVENUE
Mailing Address 2:	SUITE 1500
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10169
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9172251694

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	08/12/2016
Trans1 Recv Date:	08/12/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/23/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000226514
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980568992
TSDF ID 2:	Not reported
Manifest Tracking Number:	015338773JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

PIER 57 (Continued) **S118708625**

Quantity:	8000
Units:	P - Pounds
Number of Containers:	12
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BT896 **HUDSON DEPOT** **NY AST** **U003074389**
West **11TH AVE & 15TH ST** **NY Spills** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.239 mi.
1261 ft. **Site 2 of 4 in cluster BT**

Relative: **Lower**
Actual: **1 ft.**

AST:

Name:	PIER 57, HUDSON RIVER PARK
Address:	25 ELEVENTH AVENUE
City,State,Zip:	NEW YORK, NY 11356
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-190284
Program Type:	PBS
UTM X:	598154.60601
UTM Y:	4515877.14619
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	5863
Affiliation Type:	Mail Contact
Company Name:	HUDSON RIVER PARK TRUST
Contact Type:	Not reported
Contact Name:	LAURIE SILBERFELD
Address1:	PIER 40, 2FL.
Address2:	WEST HUDSON + WEST STREETS
City:	NEW YORK
State:	NY
Zip Code:	10014
Country Code:	001
Phone:	(212) 627-2020
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-04-13

Site Id:	5863
Affiliation Type:	Facility Operator
Company Name:	PIER 57, HUDSON RIVER PARK
Contact Type:	Not reported
Contact Name:	HUDSON RIVER PARK TRUST
Address1:	Not reported

HUDSON DEPOT (Continued) **U003074389**

Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 627-2020
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BKFALVEY
Date Last Modified:	2013-04-30

Site Id:	5863
Affiliation Type:	Emergency Contact
Company Name:	HUDSON RIVER PARK TRUST
Contact Type:	Not reported
Contact Name:	DANIEL KURTZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 627-2020
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-03-14

Site Id:	5863
Affiliation Type:	Facility Owner
Company Name:	HUDSON RIVER PARK TRUST
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	353 WEST STREET, PIER 40, 2ND FL
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10014
Country Code:	001
Phone:	(212) 627-2020
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-03-14

Tank Info:

Tank Number:	008
Tank Id:	6752
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

HUDSON DEPOT (Continued) **U003074389**

B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/1957
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/01/1995
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	HUD-1
Tank Id:	6746
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G10 - Tank Secondary Containment - Impervious Underlayment
J02 - Dispenser - Suction Dispenser
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	10/01/1986
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/09/2013
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

HUDSON DEPOT (Continued) **U003074389**

Tank Number: HUD-10
Tank Id: 45266
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G10 - Tank Secondary Containment - Impervious Underlayment
F00 - Pipe External Protection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 06/01/1987
Capacity Gallons: 7500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 07/09/2013
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: HUD-11
Tank Id: 55449
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G01 - Tank Secondary Containment - Diking (Aboveground)
J01 - Dispenser - Pressurized Dispenser
C01 - Pipe Location - Aboveground
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported

HUDSON DEPOT (Continued) **U003074389**

Install Date:	11/01/1998
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/01/2004
Register:	True
Modified By:	KXTANG
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	HUD-12
Tank Id:	55450
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
J01 - Dispenser - Pressurized Dispenser
G01 - Tank Secondary Containment - Diking (Aboveground)
H05 - Tank Leak Detection - In-Tank System (ATG)
C01 - Pipe Location - Aboveground

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/1998
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/01/2004
Register:	True
Modified By:	KXTANG
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	HUD-13
Tank Id:	59599
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel

HUDSON DEPOT (Continued) **U003074389**

F99 - Pipe External Protection - Other
H05 - Tank Leak Detection - In-Tank System (ATG)
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
G04 - Tank Secondary Containment - Double-Walled (Underground)
I05 - Overfill - Vent Whistle

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/2001
Capacity Gallons:	650
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/01/2004
Register:	True
Modified By:	KXTANG
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	HUD-2
Tank Id:	6747
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G10 - Tank Secondary Containment - Impervious Underlayment
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
F00 - Pipe External Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	10/01/1986
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/09/2013
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

HUDSON DEPOT (Continued) **U003074389**

Tank Number: HUD-3
Tank Id: 6748
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G10 - Tank Secondary Containment - Impervious Underlayment
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
F00 - Pipe External Protection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 10/01/1986
Capacity Gallons: 4000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 07/09/2013
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: HUD-4
Tank Id: 6749
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
F00 - Pipe External Protection - None
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
L00 - Piping Leak Detection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron

HUDSON DEPOT (Continued) **U003074389**

Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	10/01/1986
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/09/2013
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	HUD-7
Tank Id:	45263
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1987
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/01/2001
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	HUD-8
Tank Id:	45264
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
G99 - Tank Secondary Containment - Other

HUDSON DEPOT (Continued) **U003074389**

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
D02 - Pipe Type - Galvanized Steel

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1987
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/01/2004
Register:	True
Modified By:	KXTANG
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	HUD-9
Tank Id:	45265
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G10 - Tank Secondary Containment - Impervious Underlayment
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1987
Capacity Gallons:	7500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/09/2013
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

HUDSON DEPOT (Continued) **U003074389**

SPILLS:

Name:	HUDSON DEPOT
Address:	11TH AVE & 15TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9911311 / 2004-10-14
Facility ID:	9911311
Facility Type:	ER
DER Facility ID:	134816
Site ID:	159605
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	1999-12-27
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1999-12-27
CID:	390
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-12-27
Spill Record Last Update:	2004-10-14
Spiller Name:	UNK
Spiller Company:	ALLIED WASTE REFUSE CO
Spiller Address:	UNK
Spiller Company:	001
Contact Name:	MIKE ECKERD
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 10/14/04: As per a 10/13/04 NYCT e-mail, neither OSS nor DOB have any further information pertaining to this spill."
Remarks:	"BROKEN LINE ON A TRUCK CAUSED SPILL - ALL WAS CONTAINED AND CLEANED UP AS OF THIS REPORT"

All Materials:

Site ID:	159605
Operable Unit ID:	1090001
Operable Unit:	01
Material ID:	296776
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	30.00
Oxygenate:	Not reported

BT897 **PIER 57 LLC** **RCRA NonGen / NLR** **1018281274**
West **25 11TH AVE** **FINDS** **NYR000226514**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.239 mi.
1261 ft. **Site 3 of 4 in cluster BT**

Relative: **Lower**
Actual: **1 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20190503
Handler Name:	PIER 57 LLC	
Handler Address:		25 11TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYR000226514
Contact Name:		Not reported
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		State
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		Not reported
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

PIER 57 LLC (Continued) **1018281274**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20190503
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SUPER P57 LLC
Legal Status:	Private
Date Became Current:	20160330
Date Ended Current:	Not reported
Owner/Operator Address:	75 ROCKEFELLER PLZ STE 1300
Owner/Operator City,State,Zip:	NEW YORK, NY 10019
Owner/Operator Telephone:	917-559-8296
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SUPER P57 LLC
Legal Status:	Private
Date Became Current:	20160331
Date Ended Current:	Not reported
Owner/Operator Address:	625 RXR PLZ
Owner/Operator City,State,Zip:	UNIONDALE, NY 11556

PIER 57 LLC (Continued) **1018281274**

Owner/Operator Telephone: 917-225-1694
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SUPER P57 LLC
Legal Status: Private
Date Became Current: 20160330
Date Ended Current: Not reported
Owner/Operator Address: 75 ROCKEFELLER PLZ STE 1300
Owner/Operator City,State,Zip: NEW YORK, NY 10019
Owner/Operator Telephone: 917-559-8296
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SUPER P57 LLC
Legal Status: Private
Date Became Current: 20160331
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SUPER P57 LLC
Legal Status: Private
Date Became Current: 20160331
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SUPER P57 LLC
Legal Status: Private
Date Became Current: 20160331
Date Ended Current: Not reported
Owner/Operator Address: 625 RXR PLZ
Owner/Operator City,State,Zip: UNIONDALE, NY 11556
Owner/Operator Telephone: 917-225-1694
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20170418
Handler Name: PIER 57
Federal Waste Generator Description: Not a generator, verified

PIER 57 LLC (Continued) **1018281274**

State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20190503
Handler Name: PIER 57 LLC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20160421
Handler Name: PIER 57	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180605
Handler Name: PIER 57 LLC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	531120
NAICS Description:	LESSORS OF NONRESIDENTIAL BUILDINGS (EXCEPT MINIWAREHOUSES)

Facility Has Received Notices of Violations:

Violations:	No Violations Found

PIER 57 LLC (Continued) **1018281274**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067676447

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018281274
Registry ID:	110067676447
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067676447
Name:	PIER 57 LLC
Address:	25 11TH AVE
City,State,Zip:	NEW YORK, NY 10011

BT898 **PIER 57, HUDSON RIVER PARK** **NY UST** **U004076560**
West **25 ELEVENTH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 11356**
0.239 mi.
1261 ft. **Site 4 of 4 in cluster BT**

Relative:
Lower

Actual:
1 ft.

UST:

Name:	PIER 57, HUDSON RIVER PARK
Address:	25 ELEVENTH AVENUE
City,State,Zip:	NEW YORK, NY 11356
Id/Status:	2-190284 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	598154.60601
UTM Y:	4515877.14619
Site Type:	Other

Affiliation Records:

Site Id:	5863
Affiliation Type:	Mail Contact
Company Name:	HUDSON RIVER PARK TRUST
Contact Type:	Not reported
Contact Name:	LAURIE SILBERFELD
Address1:	PIER 40, 2FL.
Address2:	WEST HUDSON + WEST STREETS
City:	NEW YORK
State:	NY
Zip Code:	10014

PIER 57, HUDSON RIVER PARK (Continued) **U004076560**

Country Code:	001
Phone:	(212) 627-2020
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-04-13

Site Id:	5863
Affiliation Type:	Facility Operator
Company Name:	PIER 57, HUDSON RIVER PARK
Contact Type:	Not reported
Contact Name:	HUDSON RIVER PARK TRUST
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 627-2020
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BKFALVEY
Date Last Modified:	2013-04-30

Site Id:	5863
Affiliation Type:	Emergency Contact
Company Name:	HUDSON RIVER PARK TRUST
Contact Type:	Not reported
Contact Name:	DANIEL KURTZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 627-2020
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-03-14

Site Id:	5863
Affiliation Type:	Facility Owner
Company Name:	HUDSON RIVER PARK TRUST
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	353 WEST STREET, PIER 40, 2ND FL
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10014
Country Code:	001
Phone:	(212) 627-2020
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-03-14

PIER 57, HUDSON RIVER PARK (Continued) **U004076560**

Tank Info:

Tank Number:	HUD-5
Tank ID:	6750
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	7100
Install Date:	01/01/1971
Date Tank Closed:	11/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	ZZ
Date Test:	11/01/1995
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
H05 - Tank Leak Detection - In-Tank System (ATG)
H99 - Tank Leak Detection - Other
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
G03 - Tank Secondary Containment - Vault (w/o access)
I02 - Overfill - High Level Alarm

Tank Number:	HUD-6
Tank ID:	6751
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	7100
Install Date:	01/01/1971
Date Tank Closed:	11/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	ZZ
Date Test:	11/01/1995
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)

PIER 57, HUDSON RIVER PARK (Continued) **U004076560**

H99 - Tank Leak Detection - Other
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
G03 - Tank Secondary Containment - Vault (w/o access)
I02 - Overfill - High Level Alarm

BQ899 **CON EDISON** **NY MANIFEST** **S112209981**
East **F/O 251 W 21ST ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.239 mi.
1264 ft. **Site 7 of 13 in cluster BQ**

Relative:
Higher

Actual:
22 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	F/O 251 W 21ST ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004261384
Facility Status:	Not reported
Location Address 1:	F/O 251 W 21ST ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004261384
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/06/2012
Trans1 Recv Date:	08/06/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/09/2012
Part A Recv Date:	Not reported

CON EDISON (Continued) **S112209981**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004261384
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010464043JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BQ900 **262 WEST 22ND ST/MANH** **NY AST** **S102146045**
East **262 WEST 22ND ST** **NY Spills** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.240 mi.
1265 ft. **Site 8 of 13 in cluster BQ**

Relative: **Higher**
Actual: **22 ft.**

AST:

Name:	262 W 22 ST
Address:	262 WEST 22ND STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-401234
Program Type:	PBS
UTM X:	584557.90160
UTM Y:	4510855.64776
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

262 WEST 22ND ST/MANH (Continued) **S102146045**

Affiliation Records:

Site Id:	19174
Affiliation Type:	Mail Contact
Company Name:	ARIEL/MATH REALTY, LLC
Contact Type:	Not reported
Contact Name:	SHAHRAM JOHN GATAN
Address1:	326 EAST 65TH ST.
Address2:	BOX 316
City:	NEW YORK
State:	NY
Zip Code:	10065
Country Code:	001
Phone:	(917) 353-0301
EMail:	JGATAN1@GMAIL.COM
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-11-20

Site Id:	19174
Affiliation Type:	Facility Operator
Company Name:	262 W 22 ST
Contact Type:	Not reported
Contact Name:	B. RAKE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 255-1945
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-11-20

Site Id:	19174
Affiliation Type:	Emergency Contact
Company Name:	ARIEL/MATH REALTY, LLC
Contact Type:	Not reported
Contact Name:	SHAHRAM JOHN GATAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 353-0301
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-11-20

Site Id:	19174
Affiliation Type:	Facility Owner
Company Name:	ARIEL/MATH REALTY, LLC
Contact Type:	MANAGING MEMBER
Contact Name:	SHAHRAM JOHN GATAN

262 WEST 22ND ST/MANH (Continued) **S102146045**

Address1:	326 EAST 65TH ST., BOX 316
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10065
Country Code:	001
Phone:	(917) 353-0301
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-11-20

Tank Info:

Tank Number:	001
Tank Id:	21777
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	I04 - Overfill - Product Level Gauge (A/G)
	F00 - Pipe External Protection - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	A00 - Tank Internal Protection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	H00 - Tank Leak Detection - None
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	10/01/1945
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/17/2007
Register:	True
Modified By:	CGFREEDM
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

SPILLS:

Name:	262 WEST 22ND ST/MANH
Address:	262 WEST 22ND ST
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9009405 / 1990-11-30
Facility ID:	9009405
Facility Type:	ER
DER Facility ID:	143983
Site ID:	171100
DEC Region:	2

262 WEST 22ND ST/MANH (Continued) **S102146045**

Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	3101
Spill Date:	1990-11-28
Investigator:	FINGER
Referred To:	Not reported
Reported to Dept:	1990-11-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	1990-11-30
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-12-10
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	HUNT'S POINT FUEL
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"TRUCK DRIVER CONTINUALLY OVERFILLS TANK, ONGOING PROBLEM,DEC INVESTIGATED, SPILL CLEANED UP, OIL CO WILL INVESTIGATE SITUATION, POSSIBLE PROBLEM WITH VENT LINE."

All Materials:

Site ID:	171100
Operable Unit ID:	949887
Operable Unit:	01
Material ID:	567679
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BQ901 **CON EDISON** **RCRA NonGen / NLR** **1018278112**
East **262 W 22ND ST** **FINDS** **NYP004728648**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.240 mi.
1265 ft. **Site 9 of 13 in cluster BQ**

Relative: **Higher**
Actual: **22 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150209
Handler Name:	CON EDISON	
Handler Address:		262 W 22ND ST
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004728648
Contact Name:		THOMAS TEELING
Contact Address:		Not reported

CON EDISON (Continued) **1018278112**

Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No

CON EDISON (Continued) **1018278112**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150209
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150209
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON (Continued) **1018278112**

FINDS:
Registry ID: 110067699057

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018278112
Registry ID:	110067699057
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067699057
Name:	CON EDISON
Address:	262 W 22ND ST
City,State,Zip:	NEW YORK, NY 10011

BQ902 **CON EDISON** **NY MANIFEST** **S117739728**
East **262 W 22ND ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.240 mi.
1265 ft. **Site 10 of 13 in cluster BQ**

Relative:
Higher

Actual:
22 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	262 W 22ND ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004728648
Facility Status:	Not reported
Location Address 1:	F/O 262 WEST 22 ST
Code:	BP
Location Address 2:	SB3999
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004728648
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON (Continued) **S117739728**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	02/09/2015
Trans1 Recv Date:	02/09/2015
Trans2 Recv Date:	02/13/2015
TSD Site Recv Date:	02/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004728648
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610313GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BQ903 **CON EDISON** **NJ MANIFEST** **S120667004**
East **262 W 22ND ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.240 mi.
1265 ft. **Site 11 of 13 in cluster BQ**

Relative:
Higher

Actual:
22 ft.

NJ MANIFEST:

EPA Id:	NYP004728648
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610313GBF
EPA ID:	NYP004728648
Date Shipped:	2/9/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120667004**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

BU904 **571-573 WEST 159 STREET** **NY AST** **A100292550**
SW **571-573 WEST 159 STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10032**
0.240 mi.
1266 ft. **Site 1 of 2 in cluster BU**

Relative:
Lower

Actual:
2 ft.

AST:

Name:	571-573 WEST 159 STREET
Address:	571-573 WEST 159 STREET
City,State,Zip:	NEW YORK, NY 10032
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-607292
Program Type:	PBS
UTM X:	589116.38545
UTM Y:	4520975.35139
Expiration Date:	09/08/2025
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	29145
Affiliation Type:	Facility Owner
Company Name:	571 W 159 LLC
Contact Type:	MANAGING AGENT
Contact Name:	DOV SHREBER
Address1:	PO BOX 659
Address2:	Not reported
City:	SPRING VALLEY
State:	NY
Zip Code:	10977
Country Code:	001
Phone:	(718) 305-5008 207
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-09-05

Site Id:	29145
Affiliation Type:	Facility Operator
Company Name:	571-573 WEST 159 STREET
Contact Type:	Not reported
Contact Name:	SIMI GOLD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 982-9896

571-573 WEST 159 STREET (Continued) **A100292550**

EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2019-09-05

Site Id: 29145
Affiliation Type: Mail Contact
Company Name: 571 W 159 LLC
Contact Type: Not reported
Contact Name: JOSEPH RITTERMAN
Address1: PO BOX 659
Address2: Not reported
City: SPRING VALLEY
State: NY
Zip Code: 10977
Country Code: 001
Phone: (718) 305-5008 207
EMail: JRITTERMAN@MGHMANAGEMENT.COM
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2019-09-05

Site Id: 29145
Affiliation Type: Emergency Contact
Company Name: 571 W 159 LLC
Contact Type: Not reported
Contact Name: JOSEPH RITTERMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 305-5008 207
EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2019-09-05

Tank Info:

Tank Number: 001
Tank Id: 62697
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D00 - Pipe Type - No Piping
C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping

571-573 WEST 159 STREET (Continued) **A100292550**

E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/15/1910
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	09/05/2019
Material Name:	#2 fuel oil (on-site consumption)

BO905 **APT HOUSE** **NY LTANKS** **S104619486**
SE **240 WEST 16TH ST** **NY Spills** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.240 mi.
1269 ft. **Site 6 of 9 in cluster BO**

Relative:
Higher

Actual:
24 ft.

LTANKS:

Name:	SPILL NUMBER 9800017
Address:	240 WEST 16TH AT
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9800017 / 1998-04-01
Facility ID:	9800017
Site ID:	84991
Spill Date:	1998-04-01
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1998-04-01
CID:	270
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-04-01
Spill Record Last Update:	1998-04-02
Spiller Name:	Not reported
Spiller Company:	SUZUKI ASSOCIATES
Spiller Address:	240 WEST 16TH AT
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(212) 255-9340
Spiller Extention:	Not reported

APT HOUSE (Continued) **S104619486**

DEC Region: 2
DER Facility ID: 78119
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks: "top of tank was open causing overfill"

All Materials:
Site ID: 84991
Operable Unit ID: 1060400
Operable Unit: 01
Material ID: 325578
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 6.00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: APT HOUSE
Address: 240 WEST 16TH ST
City,State,Zip: MANHATTAN, NY
Spill Number/Closed Date: 9811490 / 2003-02-25
Facility ID: 9811490
Facility Type: ER
DER Facility ID: 257855
Site ID: 320055
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 3101
Spill Date: 1998-12-12
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1998-12-12
CID: 257
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-12-12
Spill Record Last Update: 2003-02-25
Spiller Name: FRANK RIZZO
Spiller Company: CRYSTAL TRANS CORP
Spiller Address: 2010 WHITEPLAINS RD
Spiller Company: 001
Contact Name: FRANK RIZZO
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 2/25/2003 - Closed Due To The Nature / Extent Of The Spill

APT HOUSE (Continued) **S104619486**

Report"
Remarks: "cleanup crew on the scene spill is in basement next to the oil tank "
Not reported

All Materials:
Site ID: 320055
Operable Unit ID: 1072359
Operable Unit: 01
Material ID: 311786
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 6.00
Units: G
Recovered: 6.00
Oxygenate: Not reported

BO906 **SPILL NUMBER 9811171** **NY LTANKS** **S104619852**
SE **240 WEST 16TH ST** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.240 mi.
1269 ft. **Site 7 of 9 in cluster BO**

Relative: **Higher**
Actual: **24 ft.**

LTANKS:
Name: SPILL NUMBER 9811171
Address: 240 WEST 16TH ST
City,State,Zip: NEW YORK CITY, NY
Spill Number/Closed Date: 9811171 / 1998-12-07
Facility ID: 9811171
Site ID: 320054
Spill Date: 1998-12-05
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 1998-12-05
CID: 384
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1998-12-05
Spill Record Last Update: 2002-05-20
Spiller Name: JIM CAREY
Spiller Company: CASTLE OIL CORPORATION
Spiller Address: 290 LOCUST AVENUE
Spiller County: 001
Spiller Contact: SUZUKI
Spiller Phone: Not reported
Spiller Extention: Not reported

SPILL NUMBER 9811171 (Continued) **S104619852**

DEC Region:	2
DER Facility ID:	283382
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE CLEANED BY CASTLE."
Remarks:	"CALLER STATED TANK WAS OVERFILLED. CLEAN UP IS BEING COMPLETED BY CASTLE."

All Materials:

Site ID:	320054
Operable Unit ID:	1068570
Operable Unit:	01
Material ID:	569316
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

BV907 **CON EDISON SERVICE BOX: 37333** **RCRA NonGen / NLR** **1016149782**
SSW **641 HUDSON ST FRONT OF** **FINDS** **NYP004284485**
1/8-1/4 **NEW YORK, NY 10013** **ECHO**
0.241 mi. **NY MANIFEST**
1271 ft. **Site 1 of 3 in cluster BV**

Relative: **Higher**
Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20170728
Handler Name:	CON EDISON SERVICE BOX: 37333
Handler Address:	641 HUDSON ST FRONT OF
Handler City,State,Zip:	NEW YORK, NY 10013
EPA ID:	NYP004284485
Contact Name:	ROBERT LINDELOF
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	917-559-3860
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No

CON EDISON SERVICE BOX: 37333 (Continued) **1016149782**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20171229
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130121

CON EDISON SERVICE BOX: 37333 (Continued) **1016149782**

Handler Name: CON EDISON SERVICE BOX: 37333
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20170728
Handler Name: CON EDISON SERVICE BOX: 37333
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055465660

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016149782
Registry ID: 110055465660
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055465660
Name: CON EDISON SERVICE BOX: 37333

CON EDISON SERVICE BOX: 37333 (Continued) **1016149782**

Address: 641 HUDSON ST FRONT OF
City,State,Zip: NEW YORK, NY 10013

NY MANIFEST:
Name: CON EDISON
Address: 641 HUDSON ST FRONT OF
City,State,Zip: NEW YORK, NY 10013
Country: USA
EPA ID: NYP004284485
Facility Status: Not reported
Location Address 1: 341 HUDSON ST
Code: BP
Location Address 2: SERV BOX 37333
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10013
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004284485
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 01/21/2013
Trans1 Recv Date: 01/21/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/21/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004284485
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 010456062JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N

CON EDISON SERVICE BOX: 37333 (Continued) **1016149782**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BV908 **641 HUDSON STREET** **NY AST** **A100292628**
SSW **641 HUDSON STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.241 mi.
1271 ft. **Site 2 of 3 in cluster BV**

Relative:
Higher

Actual:
16 ft.

AST:

Name:	641 HUDSON STREET
Address:	641 HUDSON STREET
City,State,Zip:	NEW YORK, NY 10014
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-607300
Program Type:	PBS
UTM X:	583957.30119
UTM Y:	4510263.64780
Expiration Date:	01/14/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	29153
Affiliation Type:	Facility Owner
Company Name:	FELIX BERNARDO
Contact Type:	OWNER
Contact Name:	FELIX BERNARDO
Address1:	323 WEST 14 TREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10014
Country Code:	001
Phone:	(212) 255-3732

641 HUDSON STREET (Continued) **A100292628**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2006-11-16

Site Id:	29153
Affiliation Type:	Mail Contact
Company Name:	FELIX BERNARDO
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	323 WEST 14 STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10014
Country Code:	001
Phone:	(212) 255-3732
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29153
Affiliation Type:	Facility Operator
Company Name:	641 HUDSON STREET
Contact Type:	Not reported
Contact Name:	FELIX BERNARDO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 255-3732
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2006-11-16

Site Id:	29153
Affiliation Type:	Emergency Contact
Company Name:	FELIX BERNARDO
Contact Type:	Not reported
Contact Name:	FELIX BERNARDO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 255-3732
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

641 HUDSON STREET (Continued) **A100292628**

Tank Info:

Tank Number:	001
Tank Id:	62707
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
I05 - Overfill - Vent Whistle

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel Tank in Concrete
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	07/13/1996
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

BD909 **238 W 20 STREET** **NY AST** **U001832810**
ESE **238 WEST 20TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.241 mi.
1275 ft. **Site 9 of 9 in cluster BD**

Relative: **Higher**
Actual: **23 ft.**

AST:

Name:	238 W 20 STREET
Address:	238 WEST 20TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-108766
Program Type:	PBS
UTM X:	584523.91454
UTM Y:	4510700.31123
Expiration Date:	N/A
Site Type:	Other

238 W 20 STREET (Continued) **U001832810**

Affiliation Records:

Site Id:	3233
Affiliation Type:	Facility Owner
Company Name:	QUEST ASSOCIATES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	303 EAST 6TH AVE.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 674-0950
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-02-01

Site Id:	3233
Affiliation Type:	Mail Contact
Company Name:	MATEL MANAGEMENT CO.
Contact Type:	Not reported
Contact Name:	JOHN DIFRANCESCO
Address1:	303 EAST 6TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 674-0950
EMail:	JOHN@MATELREALTY.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-02-01

Site Id:	3233
Affiliation Type:	Facility Operator
Company Name:	238 W 20 STREET
Contact Type:	Not reported
Contact Name:	MATEL MANAGEMENT CO.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 674-0950
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	3233
Affiliation Type:	Emergency Contact
Company Name:	QUEST ASSOCIATES
Contact Type:	Not reported
Contact Name:	JOSEPHIKNE MANTHA

238 W 20 STREET (Continued) **U001832810**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 255-7539
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	5475
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	H00 - Tank Leak Detection - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	I04 - Overfill - Product Level Gauge (A/G)
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1959
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/25/2011
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

BH910 **251 WEST 14 ST** **NY AST** **U003386746**
SSE **251 WEST 14TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.242 mi.
1278 ft. **Site 16 of 19 in cluster BH**

Relative:
Higher

Actual:
24 ft.

AST:

Name:	251 WEST 14 ST
Address:	251 WEST 14TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2

251 WEST 14 ST (Continued) **U003386746**

Site Status: Unregulated/Closed
Facility Id: 2-246816
Program Type: PBS
UTM X: 584288.84405
UTM Y: 4510329.71240
Expiration Date: N/A
Site Type: Other

Affiliation Records:

Site Id: 9670
Affiliation Type: Facility Operator
Company Name: 251 WEST 14 ST
Contact Type: Not reported
Contact Name: NA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: Not reported
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2017-04-11

Site Id: 9670
Affiliation Type: Emergency Contact
Company Name: FPNY LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: Not reported
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2017-04-11

Site Id: 9670
Affiliation Type: Facility Owner
Company Name: FPNY LLC
Contact Type: CEO
Contact Name: PAOLA CASALI
Address1: 41 MADISON AVE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10010
Country Code: 001
Phone: (646) 202-2592
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW

251 WEST 14 ST (Continued) **U003386746**

Date Last Modified: 2017-04-11

Site Id: 9670
Affiliation Type: Mail Contact
Company Name: FPNYLCC
Contact Type: Not reported
Contact Name: PAOLA CASALI
Address1: W MADISON AVENUE SUITE 2517
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10010
Country Code: 999
Phone: (929) 392-4670
EMail: CASALI@PIZZAROTTI.NET
Fax Number: Not reported
Modified By: JAAVERSA
Date Last Modified: 2018-10-18

Tank Info:

Tank Number: 001
Tank Id: 10621
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

G01 - Tank Secondary Containment - Diking (Aboveground)
C01 - Pipe Location - Aboveground
D10 - Pipe Type - Copper
B00 - Tank External Protection - None
H04 - Tank Leak Detection - Groundwater Well
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
I03 - Overfill - Automatic Shut-Off
F99 - Pipe External Protection - Other

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 02/01/1954
Capacity Gallons: 1500
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 01/14/2016
Register: True
Modified By: MRBARROW
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

BH911 **CON EDISON** **NY MANIFEST** **S116551845**
SSE **250 W 14 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.242 mi.
1279 ft. **Site 17 of 19 in cluster BH**

Relative:
Higher

Actual:
23 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	250 W 14 ST
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004560708
Facility Status:	Not reported
Location Address 1:	250 W 14 ST
Code:	BP
Location Address 2:	SB2391
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004560708
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/15/2014
Trans1 Recv Date:	04/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/16/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004560708
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406252GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S116551845**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BW912 **CON EDISON - MANHOLE 43109** **NY MANIFEST** **S120958120**
North **W 24TH ST & 10TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.242 mi.
1280 ft. **Site 1 of 8 in cluster BW**

Relative:
Lower

Actual:
12 ft.

NY MANIFEST:

Name:	CON EDISON - MANHOLE 43109
Address:	W 24TH ST & 10TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004914279
Facility Status:	Not reported
Location Address 1:	W 24TH ST & 10TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004914279
Mailing Name:	CON EDISON - MANHOLE 43109
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON - MANHOLE 43109 (Continued) **S120958120**

Mailing Country: USA
Mailing Phone: Not reported

BW913 **CON EDISON SERVICE BOX: 43115** **RCRA NonGen / NLR** **1016148886**
North **W 10TH AVE & 24TH ST** **NY MANIFEST** **NYP004275376**
1/8-1/4 **NEW YORK, NY 10001**
0.242 mi.
1280 ft. **Site 2 of 8 in cluster BW**

Relative: **Lower**
Actual: **12 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130324
Handler Name:	CON EDISON SERVICE BOX:	43115
Handler Address:		W 10TH AVE & 24TH ST
Handler City,State,Zip:		NEW YORK, NY 10001
EPA ID:		NYP004275376
Contact Name:		JOSE MONTALVO
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-427-1331
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported

CON EDISON SERVICE BOX: 43115 (Continued) **1016148886**

Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130224
Handler Name: CON EDISON SERVICE BOX:	43115
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130324
Handler Name: CON EDISON SERVICE BOX:	43115
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON SERVICE BOX: 43115 (Continued) **1016148886**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	W 10TH AVE & 24TH ST
City,State,Zip:	NEW YORK, NY 10001
Country:	USA
EPA ID:	NYP004275376
Facility Status:	Not reported
Location Address 1:	245-247 W 10TH AVE N/O W 24TH ST
Code:	BP
Location Address 2:	SERV BOX 43115
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10001
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004275376
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/25/2013
Trans1 Recv Date:	02/25/2013

CON EDISON SERVICE BOX: 43115 (Continued) **1016148886**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/26/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004275376
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010708011JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BW914 **CONSOLIDATED EDISON** **NY MANIFEST** **1009243145**
North **24 ST & 10 AVE MH43113** **N/A**
1/8-1/4 **NEW YORK, NY 10002**
0.243 mi.
1281 ft. **Site 3 of 8 in cluster BW**

Relative: NY MANIFEST:
Lower

Name:	CONSOLIDATED EDISON
Address:	24 ST & 10 AVE MH43113
City,State,Zip:	NEW YORK, NY 10002
Country:	USA
EPA ID:	NYP004124988
Facility Status:	Not reported
Location Address 1:	24 ST & 10 AVE MH43113
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported

Actual:
13 ft.

CONSOLIDATED EDISON (Continued) **1009243145**

Location City: NEW YORK
Location State: NY
Location Zip: 10002
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004124988
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

BQ915 **CON EDISON** **NY MANIFEST** **S117739736**
East **F/O 260 W 22 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.244 mi.
1287 ft. **Site 12 of 13 in cluster BQ**

Relative:
Higher

Actual:
22 ft.

NY MANIFEST:
Name: CON EDISON
Address: F/O 260 W 22 ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004728739
Facility Status: Not reported
Location Address 1: F/O 260 W 22 ST
Code: BP
Location Address 2: SB4011
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004728739
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported

CON EDISON (Continued) **S117739736**

Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	02/09/2015
Trans1 Recv Date:	02/09/2015
Trans2 Recv Date:	02/13/2015
TSD Site Recv Date:	02/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004728739
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610618GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BH916 **CON EDISON** **NY MANIFEST** **S118463861**
SSE **122 GREENWICH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.244 mi.
1288 ft. **Site 18 of 19 in cluster BH**

Relative: **Higher**
Actual: **23 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	122 GREENWICH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004858157

CON EDISON (Continued) **S118463861**

Facility Status:	Not reported
Location Address 1:	122 GREENWICH AVE
Code:	BP
Location Address 2:	SB 36058
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004858157
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/2015
Trans1 Recv Date:	10/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004858157
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014087616JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S118463861**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BO917 **236 E. 16 ST REALTY LLC** **NY LTANKS** **U003107195**
SE **236 EAST 16TH STREET** **NY UST** **N/A**
1/8-1/4 **BROOKLYN, NY 11226** **NY Spills**
0.245 mi.
1292 ft. **Site 8 of 9 in cluster BO**

Relative: **Higher**

Actual: **24 ft.**

LTANKS:

Name:	CYNAMON RESIDNECE
Address:	236 EAST 16TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0411114 / 2005-11-17
Facility ID:	0411114
Site ID:	336367
Spill Date:	2005-01-13
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	2005-01-13
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-01-18
Spill Record Last Update:	2005-11-17
Spiller Name:	ALLEN CYNAMON
Spiller Company:	CYNAMON RESIDNECE
Spiller Address:	236 EAST 16TH STREET
Spiller County:	001
Spiller Contact:	ALLEN CYNAMON
Spiller Phone:	(718) 859-6788
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	271699
DEC Memo:	"need to send ttf ltr 11/14/05- DEC Piper sent out ttf letter

236 E. 16 ST REALTY LLC (Continued) **U003107195**

11/17/05- DEC Piper received letter from aBC Tank and test pass results. Tank was internally inspected and small hole on top was discovered. Top of tank was dug out, no contamination found, tank repaired, vent line, whistle replaced. Case Closed"

Remarks: "PBS No: 2-602715"

All TTF:

Facility ID:	0411114
Spill Number:	0411114
Spill Tank Test:	1548501
Site ID:	336367
Tank Number:	Not reported
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

Facility ID:	0411114
Spill Number:	0411114
Spill Tank Test:	1548502
Site ID:	336367
Tank Number:	1
Tank Size:	3000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	336367
Operable Unit ID:	1098393
Operable Unit:	01
Material ID:	578563
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

236 E. 16 ST REALTY LLC (Continued) **U003107195**

UST:

Name:	236 E. 16 ST REALTY LLC
Address:	236 EAST 16TH STREET
City,State,Zip:	BROOKLYN, NY 11226
Id/Status:	2-602715 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	01/06/2025
UTM X:	587573.93952
UTM Y:	4499836.13162
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	24671
Affiliation Type:	Facility Owner
Company Name:	236 E. 16 ST REALTY LLC
Contact Type:	MANAGER
Contact Name:	SHARON STEFANSKEG
Address1:	PO BOX 340083
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11234
Country Code:	001
Phone:	(718) 338-8195
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LSZINOMA
Date Last Modified:	2015-02-09

Site Id:	24671
Affiliation Type:	Mail Contact
Company Name:	STEERLING PROPERTY MGMT CORP
Contact Type:	Not reported
Contact Name:	AARON CYNAMON
Address1:	1470 FLATBUSH AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11210
Country Code:	001
Phone:	(718) 859-5445
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LSZINOMA
Date Last Modified:	2015-02-09

Site Id:	24671
Affiliation Type:	Emergency Contact
Company Name:	236 E. 16 ST REALTY LLC
Contact Type:	Not reported
Contact Name:	MIRSAD DJON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

236 E. 16 ST REALTY LLC (Continued) **U003107195**

Zip Code:	Not reported
Country Code:	999
Phone:	(347) 604-1147
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-10-28

Site Id:	24671
Affiliation Type:	Facility Operator
Company Name:	236 E. 16 ST REALTY LLC
Contact Type:	Not reported
Contact Name:	SAID DJON BALIC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 693-1562
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LSZINOMA
Date Last Modified:	2015-02-09

Tank Info:

Tank Number:	001
Tank ID:	51241
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	3000
Install Date:	01/01/2005
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	21
Date Test:	01/20/2005
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	LSZINOMA
Last Modified:	04/14/2017

Equipment Records:

C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
G99 - Tank Secondary Containment - Other
K00 - Spill Prevention - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

236 E. 16 ST REALTY LLC (Continued) **U003107195**

L09 - Piping Leak Detection - Exempt Suction Piping
B05 - Tank External Protection - Jacketed
I05 - Overfill - Vent Whistle

SPILLS:

Name:	236 WEST 16TH ST
Address:	236 WEST 16TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9414887 / 1995-02-13
Facility ID:	9414887
Facility Type:	ER
DER Facility ID:	206979
Site ID:	252668
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	1995-02-13
Investigator:	NIEVES
Referred To:	Not reported
Reported to Dept:	1995-02-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	1995-02-13
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-17
Spill Record Last Update:	2004-05-17
Spiller Name:	Not reported
Spiller Company:	ANTHONY PUMA
Spiller Address:	1640 MCDONALD AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"FAILURE OF CONNECTOR BETWEEN TANK AND HOSE. EQUIPMENT OF FAILURE. POLICE RESPONDED. SORBENT PADS CLEANING UP. LESS THAN 10GLS."

All Materials:

Site ID:	252668
Operable Unit ID:	1012320
Operable Unit:	01
Material ID:	373610
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

BO918 **236 WEST 16 STREET** **NY AST** **U004061731**
SE **236 WEST 16TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10023**
0.245 mi.
1292 ft. **Site 9 of 9 in cluster BO**

Relative:
Higher

Actual:
24 ft.

AST:

Name:	236 WEST 16 STREET
Address:	236 WEST 16TH STREET
City,State,Zip:	NEW YORK, NY 10023
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-607115
Program Type:	PBS
UTM X:	584448.50476
UTM Y:	4510406.30097
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	28969
Affiliation Type:	Facility Owner
Company Name:	OCCIDENTAL MORON LLC % AJ CLARKE R.E.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1881 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10023
Country Code:	001
Phone:	(212) 541-4477
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	28969
Affiliation Type:	Facility Operator
Company Name:	236 WEST 16 STREET
Contact Type:	Not reported
Contact Name:	TONY RIVERA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 924-5067
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	28969
Affiliation Type:	Emergency Contact
Company Name:	OCCIDENTAL MORON LLC % AJ CLARKE R.E.
Contact Type:	Not reported
Contact Name:	TONY RIVERA

236 WEST 16 STREET (Continued) **U004061731**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 924-5067
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	28969
Affiliation Type:	Mail Contact
Company Name:	% AJ CLARKE R.E. CORP
Contact Type:	Not reported
Contact Name:	STEPHEN DENARDO
Address1:	1881 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10023
Country Code:	001
Phone:	(212) 541-4477
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	62338
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	C01 - Pipe Location - Aboveground
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	B00 - Tank External Protection - None
	F00 - Pipe External Protection - None
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported

236 WEST 16 STREET (Continued) **U004061731**

Next Test Date:	Not reported
Date Tank Closed:	04/26/2006
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

BI919 **250 W 19TH STREET** **NY AST** **U004078321**
ESE **250 WEST 19TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.245 mi.
1295 ft. **Site 4 of 5 in cluster BI**

Relative:
Higher

Actual:
23 ft.

AST:

Name:	250 W 19TH STREET
Address:	250 WEST 19TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-600027
Program Type:	PBS
UTM X:	584517.53679
UTM Y:	4510613.86222
Expiration Date:	09/10/2025
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	22016
Affiliation Type:	Facility Operator
Company Name:	250 W 19TH STREET
Contact Type:	Not reported
Contact Name:	PETRIT DEMALIAJ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 418-4481
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-11-23

Site Id:	22016
Affiliation Type:	Emergency Contact
Company Name:	BRE FSC MULTIFAMILY BORROWER LLC
Contact Type:	Not reported
Contact Name:	PETRIT DEMALIAJ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 582-4481
EMail:	Not reported

250 W 19TH STREET (Continued) **U004078321**

Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-11-23

Site Id:	22016
Affiliation Type:	Mail Contact
Company Name:	PETRIT DEMALIAJ
Contact Type:	Not reported
Contact Name:	REI MOYA
Address1:	276 1ST AVENUE LOOP
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10009
Country Code:	001
Phone:	(833) 312-7729
EMail:	DOB.ARRAY@BEAMLIVING.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-11-23

Site Id:	22016
Affiliation Type:	Facility Owner
Company Name:	BRE FSC MULTIFAMILY BORROWER LLC
Contact Type:	COO
Contact Name:	REI MOYA
Address1:	276 1ST AVENUE LOOP
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10009
Country Code:	001
Phone:	(833) 312-7729
EMail:	DOB.ARRAY@BEAMLIVING.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-11-23

Tank Info:

Tank Number:	001
Tank Id:	39964
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

250 W 19TH STREET (Continued) **U004078321**

	L00 - Piping Leak Detection - None
	H99 - Tank Leak Detection - Other
Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1986
Capacity Gallons:	5000
Tightness Test Method:	03
Date Test:	03/01/1996
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	11/23/2021
Material Name:	#2 fuel oil (on-site consumption)

BM920 **CON EDISON SERVICE BOX: 35410** **RCRA NonGen / NLR** **1016150237**
SSW **67 GANSEVOORT ST FRONT OF** **FINDS** **NYP004289088**
1/8-1/4 **NEW YORK, NY 10014** **ECHO**
0.246 mi. **NY MANIFEST**
1297 ft. **Site 3 of 3 in cluster BM**

Relative: **Lower**
Actual: **12 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20170728
Handler Name:	CON EDISON SERVICE BOX:	35410
Handler Address:		67 GANSEVOORT ST FRONT OF
Handler City,State,Zip:		NEW YORK, NY 10014
EPA ID:		NYP004289088
Contact Name:		RICARDO CARTY
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		646-772-3407
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No

CON EDISON SERVICE BOX: 35410 (Continued) **1016150237**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180208
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130213
Handler Name: CON EDISON SERVICE BOX:	35410
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

CON EDISON SERVICE BOX: 35410 (Continued) **1016150237**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20170728
Handler Name:	CON EDISON SERVICE BOX: 35410
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055460772

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016150237
Registry ID:	110055460772
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055460772
Name:	CON EDISON SERVICE BOX: 35410
Address:	67 GANSEVOORT ST FRONT OF
City,State,Zip:	NEW YORK, NY 10014

CON EDISON SERVICE BOX: 35410 (Continued) **1016150237**

NY MANIFEST:

Name:	CON EDISON
Address:	67 GANSEVOORT ST FRONT OF
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004289088
Facility Status:	Not reported
Location Address 1:	F/O 67 GANSEVOORT ST
Code:	BP
Location Address 2:	SERV BOX 35410
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004289088
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/13/2013
Trans1 Recv Date:	02/13/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/14/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004289088
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010707313JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON SERVICE BOX: 35410 (Continued) **1016150237**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BQ921 **EARTH CLEANER** **RCRA NonGen / NLR** **1004762208**
ENE **250 8TH AVE** **ICIS** **NYR000094615**
1/8-1/4 **NEW YORK, NY 10011** **US AIRS**
0.246 mi. **NY DRYCLEANERS**
1301 ft. **Site 13 of 13 in cluster BQ**

Relative: **Higher**
Actual: **22 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	EARTH CLEANER	
Handler Address:		250 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYR000094615
Contact Name:		KWANG YOO
Contact Address:		8TH AVE
Contact City,State,Zip:		NEW YORK, NY 10011
Contact Telephone:		212-989-6060
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		8TH AVE
Mailing City,State,Zip:		NEW YORK, NY 10011
Owner Name:		KWANG T YOO
Owner Type:		Private
Operator Name:		KWANG T YOO
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No

EARTH CLEANER (Continued) **1004762208**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:
Waste Code: D039

EARTH CLEANER (Continued) **1004762208**

Waste Description: TETRACHLOROETHYLENE

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: KWANG T YOO
Legal Status: Private
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 250 8TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 212-989-6060
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: KWANG T YOO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 250 8TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 212-989-6060
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: KWANG T YOO
Legal Status: Private
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 250 8TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10011
Owner/Operator Telephone: 212-989-6060
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: EARTH CLEANER
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No

EARTH CLEANER (Continued) **1004762208**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: EARTH CLEANER	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010227
Handler Name: EARTH CLEANER	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

ICIS:

Enforcement Action ID:	NY000A0000262050161500301
FRS ID:	110004567415
Action Name:	EARTH CLEANER 36061R179400301
Facility Name:	EARTH CLEANER
Facility Address:	250 8TH AVE NEW YORK, NY 100111620
Enforcement Action Type:	Notice of Violation
Facility County:	BRONX
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal

EARTH CLEANER (Continued) **1004762208**

EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.74511
Longitude in Decimal Degrees:	-73.99862
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002620501615
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

US AIRS MINOR:

Envid:	1004762208
Region Code:	02
Programmatic ID:	AIR NY0000002620501615
Facility Registry ID:	110004567415
D and B Number:	Not reported
Primary SIC Code:	7216
NAICS Code:	812320
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	02
Programmatic ID:	AIR NY0000002620501615
Facility Registry ID:	110004567415
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2001-06-09 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	02
Programmatic ID:	AIR NY0000002620501615
Facility Registry ID:	110004567415
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2002-02-15 00:00:00
Activity Status Date:	2002-02-15 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved

Region Code:	02
Programmatic ID:	AIR NY0000002620501615
Facility Registry ID:	110004567415
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2001-06-09 00:00:00
Activity Status Date:	Not reported

EARTH CLEANER (Continued) **1004762208**

Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

DRYCLEANERS:
Name: EARTH CLEANER
Address: 250 EIGTH AVENUE
City,State,Zip: NEW YORK, NY 10011
Facility ID: 2-6205-01615
Phone Number: 212-989-6060
Region: Not reported
Registration Effective Date: 10/16/2001 11:25:41:08
Inspection Date: 07MAY21
Install Date: 00
Expiration Date: Not reported
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

BN922 **DIA ART FOUNDATION** **NY UST U003074426**
NNW **548 W 22ND ST** **NY AST N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.247 mi.
1304 ft. **Site 2 of 3 in cluster BN**

Relative:
Lower

Actual:
6 ft.

UST:
Name: DIA ART FOUNDATION
Address: 548 W 22ND ST
City,State,Zip: NEW YORK, NY 10011
Id/Status: 2-272256 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 583939.34045
UTM Y: 4511223.15111
Site Type: Unknown

Affiliation Records:
Site Id: 11527
Affiliation Type: Facility Owner
Company Name: DIA ART FOUNDATION
Contact Type: Not reported
Contact Name: Not reported
Address1: 155 MERCER
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 431-9232
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

DIA ART FOUNDATION (Continued) **U003074426**

Site Id:	11527
Affiliation Type:	Mail Contact
Company Name:	DIA ART FOUNDATION
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	155 MERCER
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 431-9232
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	11527
Affiliation Type:	Facility Operator
Company Name:	DIA ART FOUNDATION
Contact Type:	Not reported
Contact Name:	JAMES P SCHAEUFELE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 242-0125
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	11527
Affiliation Type:	Emergency Contact
Company Name:	DIA ART FOUNDATION
Contact Type:	Not reported
Contact Name:	JAMES P SCHAEUFELE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 242-0125
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	9202
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91

DIA ART FOUNDATION (Continued) **U003074426**

Capacity Gallons:	5000
Install Date:	Not reported
Date Tank Closed:	12/01/1990
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

AST:

Name:	DIA ART FOUNDATION
Address:	548 W 22ND ST
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-272256
Program Type:	PBS
UTM X:	583939.34045
UTM Y:	4511223.15111
Expiration Date:	N/A
Site Type:	Unknown

Affiliation Records:

Site Id:	11527
Affiliation Type:	Facility Owner
Company Name:	DIA ART FOUNDATION
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	155 MERCER
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 431-9232
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

DIA ART FOUNDATION (Continued) **U003074426**

Site Id:	11527
Affiliation Type:	Mail Contact
Company Name:	DIA ART FOUNDATION
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	155 MERCER
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 431-9232
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	11527
Affiliation Type:	Facility Operator
Company Name:	DIA ART FOUNDATION
Contact Type:	Not reported
Contact Name:	JAMES P SCHAEUFELE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 242-0125
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	11527
Affiliation Type:	Emergency Contact
Company Name:	DIA ART FOUNDATION
Contact Type:	Not reported
Contact Name:	JAMES P SCHAEUFELE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 242-0125
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	002
Tank Id:	41437
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

DIA ART FOUNDATION (Continued) **U003074426**

Equipment Records:
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	09/01/1990
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/1996
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)
Tank Number:	003
Tank Id:	41438
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	09/01/1990
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/1996
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

BE923 **CON EDISON** **NY MANIFEST** **S117067029**
South **21-25 HORATIO ST & HUDSON ST** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.247 mi.
1305 ft. **Site 9 of 10 in cluster BE**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	21-25 HORATIO ST & HUDSON ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004597530
Facility Status:	Not reported
Location Address 1:	21-25 HORATIO ST & HUDSON ST
Code:	BP
Location Address 2:	SB 36917
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004597530
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/16/2014
Trans1 Recv Date:	07/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/16/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004597530
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504368GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117067029**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BF924 **243 WEST 17TH STREET** **NY AST** **U003393431**
SE **243 WEST 17TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.247 mi.
1306 ft. **Site 12 of 12 in cluster BF**

Relative:
Higher

Actual:
23 ft.

AST:

Name:	243 WEST 17TH STREET
Address:	243 WEST 17TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-281255
Program Type:	PBS
UTM X:	584474.34963
UTM Y:	4510492.39781
Expiration Date:	10/11/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	12324
Affiliation Type:	Facility Operator
Company Name:	243 WEST 17TH STREET
Contact Type:	Not reported
Contact Name:	COLUMBIA REIT - 245-249 W. 17TH LLC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

243 WEST 17TH STREET (Continued) **U003393431**

Phone:	(347) 714-0179
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-05-04

Site Id:	12324
Affiliation Type:	Mail Contact
Company Name:	COLUMBIA PROPERTY TRUST
Contact Type:	Not reported
Contact Name:	VERA UJKAJ
Address1:	245-249 WEST 17TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 433-4070
EMail:	VERA.UJKAJ@COLUMBIA.REIT
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-05-04

Site Id:	12324
Affiliation Type:	Emergency Contact
Company Name:	COLUMBIA REIT - 245-249 W. 17TH LLC
Contact Type:	Not reported
Contact Name:	VERA UJKAJ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 433-4070
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-05-04

Site Id:	12324
Affiliation Type:	Facility Owner
Company Name:	COLUMBIA REIT-245-249 W. 17TH LLC
Contact Type:	PROPERTY MANAGER
Contact Name:	VERA UJKAJ
Address1:	245-249 WEST 17TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 433-4070
EMail:	VERA.UJKAJ@COLUMBIA.REIT
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-05-04

243 WEST 17TH STREET (Continued) **U003393431**

Tank Info:

Tank Number:	001
Tank Id:	28081
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
B05 - Tank External Protection - Jacketed
I05 - Overfill - Vent Whistle
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
E12 - Piping Secondary Containment - Double-Walled (AG only)
F04 - Pipe External Protection - Fiberglass
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1980
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	05/04/2021
Material Name:	#2 fuel oil (on-site consumption)

BE925 **CON EDISON** **NY MANIFEST** **S118463852**
South **17 HORATIO ST** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.248 mi.
1308 ft. **Site 10 of 10 in cluster BE**

Relative: **Higher**
Actual: **20 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	17 HORATIO ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004857991
Facility Status:	Not reported
Location Address 1:	17 HORATIO ST
Code:	BP
Location Address 2:	SB 36917
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY

CON EDISON (Continued) **S118463852**

Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004857991
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/2015
Trans1 Recv Date:	10/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004857991
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014087613JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.

CON EDISON (Continued) **S118463852**

Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BH926 **CON EDISON MANHOLE 2392** **RCRA NonGen / NLR** **1014919321**
SSE **246 W 14TH ST & 8 AVE** **NJ MANIFEST** **NYP004234829**
1/8-1/4 **NEW YORK, NY 10011**
0.248 mi.
1308 ft. **Site 19 of 19 in cluster BH**

Relative: **Higher**
Actual: **24 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20110602
Handler Name:	CON EDISON MANHOLE 2392
Handler Address:	246 W 14TH ST & 8 AVE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYP004234829
Contact Name:	DANIELLE SIERRA
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-894-9472
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OFFICE ASSISTANT L1-2
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLAZA RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported

CON EDISON MANHOLE 2392 (Continued) **1014919321**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20111026
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2011

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20110503
Date Ended Current:	Not reported

CON EDISON MANHOLE 2392 (Continued) **1014919321**

Owner/Operator Address: 4 IRVING PLACE, 15TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20110503
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE, 15TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20120306
Handler Name: CON EDISON - MANHOLE 2392
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20110503
Handler Name: CON EDISON MANHOLE 2392
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20110602
Handler Name: CON EDISON MANHOLE 2392
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported

CON EDISON MANHOLE 2392 (Continued) **1014919321**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:
EPA Id: NYP004234829
Mail Address: IRVING PLACE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DENNIS HUACON
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 007658401JJK
EPA ID: NYP004234829
Date Shipped: 5/3/2011
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported

CON EDISON MANHOLE 2392 (Continued) **1014919321**

Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	4,500.00 Pounds

BX927 **CON EDISON** **NJ MANIFEST** **S120672724**
ENE **W 23RD ST & 8TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.248 mi.
1310 ft. **Site 1 of 12 in cluster BX**

Relative:
Higher

Actual:
22 ft.

NJ MANIFEST:

EPA Id:	NYP004793493
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002614091GBF
EPA ID:	NYP004793493
Date Shipped:	6/11/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported

CON EDISON (Continued) **S120672724**

Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

BX928 **CON EDISON** **NY MANIFEST** **S118256850**
ENE **W 23RD ST & 8TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.248 mi.
1310 ft. **Site 2 of 12 in cluster BX**

Relative:
Higher

Actual:
22 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	W 23RD ST & 8TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYP004793493
Facility Status:	Not reported
Location Address 1:	W 23RD ST & 8TH AVE
Code:	BP
Location Address 2:	MH 57290
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

CON EDISON (Continued) **S118256850**

EPAID:	NYP004793493
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/11/2015
Trans1 Recv Date:	06/11/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/15/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004793493
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002614091GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported

CON EDISON (Continued) **S118256850**

Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

BX929 **MTA NYCT - 23RD STREET STATION - A C E LINES** **RCRA-SQG** **1012186960**
ENE **23RD ST & 8TH AVE** **NYR000168245**
1/8-1/4 **NEW YORK, NY 10011**
0.248 mi.
1310 ft. **Site 3 of 12 in cluster BX**

Relative: **Higher**
Actual: **22 ft.**

RCRA-SQG:

Date Form Received by Agency:	20090909
Handler Name:	MTA NYCT - 23RD STREET STATION - A C E LINES
Handler Address:	23RD ST & 8TH AVE
Handler City,State,Zip:	NEW YORK, NY 10011
EPA ID:	NYR000168245
Contact Name:	GERALD LEZEAU
Contact Address:	BROADWAY 5TH FLOOR 503
Contact City,State,Zip:	NEW YORK, NY 10004
Contact Telephone:	646-252-3535
Contact Fax:	Not reported
Contact Email:	GERALD.LEZEAU@NYCT.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	State
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	BROADWAY 5TH FLOOR 503
Mailing City,State,Zip:	NEW YORK, NY 10004
Owner Name:	MTA NYCT
Owner Type:	State
Operator Name:	MTA NYCT
Operator Type:	State
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN

MTA NYCT - 23RD STREET STATION - A C E LINES (Continued) **1012186960**

Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MTA NYCT
Legal Status:	State
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner

MTA NYCT - 23RD STREET STATION - A C E LINES (Continued) **1012186960**

Owner/Operator Name:	MTA NYCT
Legal Status:	State
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 5TH FLOOR 503
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20090909
Handler Name:	MTA NYCT - 23RD STREET STATION - A C E LINES
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	485111
NAICS Description:	MIXED MODE TRANSIT SYSTEMS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

BX930 **NYCT - MH 1027** **RCRA-LQG** **1025504442**
ENE **23RD ST & 8TH AVE** **NYP000975258**
1/8-1/4 **NEW YORK, NY 10011**
0.248 mi.
1310 ft. **Site 4 of 12 in cluster BX**

Relative: **Higher**
Actual: **22 ft.**

RCRA-LQG:

Date Form Received by Agency:		20200218
Handler Name:	NYCT - MH 1027	
Handler Address:		23RD ST & 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP000975258
Contact Name:		DANIEL YU
Contact Address:		BROADWAY
Contact City,State,Zip:		NEW YORK, NY 10004
Contact Telephone:		646-252-5777
Contact Fax:		Not reported
Contact Email:		ENVIRONMENTALPROTECTIONNYCT@NYCT.COM
Contact Title:		LEAD SPECIALIST
EPA Region:		02

NYCT - MH 1027 (Continued) **1025504442**

Land Type:	State
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2019
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	BROADWAY
Mailing City,State,Zip:	NEW YORK, NY 10004
Owner Name:	NEW YORK CITY TRANSIT
Owner Type:	State
Operator Name:	NEW YORK CITY TRANSIT
Operator Type:	State
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No

NYCT - MH 1027 (Continued) **1025504442**

Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211230
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2019

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NEW YORK CITY TRANSIT
Legal Status:	State
Date Became Current:	20200211
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	646-252-5777
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NEW YORK CITY TRANSIT
Legal Status:	State
Date Became Current:	19320101
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	646-252-5777
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20200218
Handler Name: NYCT - MH 1027	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

NYCT - MH 1027 (Continued) **1025504442**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20190410
Handler Name: NEW YORK CITY TRANSIT - MH DMA 1027SP
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20191031
Handler Name: NEW YORK CITY TRANSIT - MH DMA 1027SP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 485111
NAICS Description: MIXED MODE TRANSIT SYSTEMS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

BX931 **CON EDISON MANHOLE: 32124** **RCRA NonGen / NLR** **1017773362**
ENE **8TH AVE & 23RD ST** **NYP004511424**
1/8-1/4 **NEW YORK, NY 10011**
0.248 mi.
1310 ft. **Site 5 of 12 in cluster BX**

Relative:
Higher

Actual:
22 ft.

RCRA NonGen / NLR:
Date Form Received by Agency: 20140524
Handler Name: CON EDISON MANHOLE: 32124
Handler Address: 8TH AVE & 23RD ST
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYP004511424
Contact Name: THOMAS TEELING

CON EDISON MANHOLE: 32124 (Continued) **1017773362**

Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking

CON EDISON MANHOLE: 32124 (Continued) **1017773362**

Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140424
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140424
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140524
Handler Name: CON EDISON MANHOLE: 32124	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CON EDISON MANHOLE: 32124 (Continued) **1017773362**

Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

BX932 **CON EDISON** **NY MANIFEST** **S117736420**
ENE **8TH AVE & 23RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.248 mi.
1310 ft. **Site 6 of 12 in cluster BX**

Relative:
Higher

Actual:
22 ft.

NY MANIFEST:
Name: CON EDISON
Address: 8TH AVE & 23RD ST
City,State,Zip: NEW YORK, NY 10011
Country: USA
EPA ID: NYP004511424
Facility Status: Not reported
Location Address 1: W 8 AVE NSW 23 ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10011
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004511424
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047

CON EDISON (Continued) **S117736420**

Generator Ship Date:	04/24/2014
Trans1 Recv Date:	04/24/2014
Trans2 Recv Date:	04/25/2014
TSD Site Recv Date:	04/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004511424
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416520GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BX933 **MTA NYCT - 23RD STREET STATION - A C E LINES** **NY MANIFEST** **S118464290**
ENE **23RD ST & 8TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.248 mi.
1310 ft. **Site 7 of 12 in cluster BX**

Relative: **Higher**
Actual: **22 ft.**

NY MANIFEST:

Name:	MTA NYCT - 23RD STREET STATION - A C E LINES
Address:	23RD ST & 8TH AVE
City,State,Zip:	NEW YORK, NY 10011
Country:	USA
EPA ID:	NYR000168245
Facility Status:	Not reported
Location Address 1:	23RD ST & 8TH AVE
Code:	BP

MTA NYCT - 23RD STREET STATION - A C E LINES (Continued) **S118464290**

Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000168245
Mailing Name:	MTA NYCT - 23RD STREET STATION - A C E LINES
Mailing Contact:	NARENDRA PATEL
Mailing Address 1:	2 BROADWAY
Mailing Address 2:	RM A21.64
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10001
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6462525777

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJR986628162
Trans2 State ID:	Not reported
Generator Ship Date:	12/16/2015
Trans1 Recv Date:	12/16/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/16/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000168245
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	008273804FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200

MTA NYCT - 23RD STREET STATION - A C E LINES (Continued) **S118464290**

Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BX934 **CON EDISON** **RCRA NonGen / NLR** **1019904080**
ENE **W 23RD ST & 8TH AVE** **NYP004793493**
1/8-1/4 **NEW YORK, NY 10011**
0.248 mi.
1310 ft. **Site 8 of 12 in cluster BX**

Relative: **Higher**
Actual: **22 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150611
Handler Name:	CON EDISON	
Handler Address:		W 23RD ST & 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004793493
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No

CON EDISON (Continued) **1019904080**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150611
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

CON EDISON (Continued) **1019904080**

Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20150611
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

BX935 **MTA NYCT - 23RD STREET STATION - A C E LINES** **NJ MANIFEST** **S120678879**
ENE **23RD ST & 8TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.248 mi.
1310 ft. **Site 9 of 12 in cluster BX**

Relative:
Higher

Actual:
22 ft.

NJ MANIFEST:

EPA Id:	NYR000168245
Mail Address:	BROADWAY 5TH FLOOR 503
Mail City/State/Zip:	NEW YORK, NY 10004
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	GERALD LEZEAU
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	009140442FLE
EPA ID:	NYR000168245
Date Shipped:	3/3/2016
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR986628162
Transporter 2 EPA ID:	Not reported

MTA NYCT - 23RD STREET STATION - A C E LINES (Continued) **S120678879**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10004
Reason Load Was Rejected:	Not reported

Manifest Number:	008273804FLE
EPA ID:	NYR000168245
Date Shipped:	12/16/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR986628162
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

MTA NYCT - 23RD STREET STATION - A C E LINES (Continued) **S120678879**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10004
Reason Load Was Rejected:	Not reported

Manifest Number:	009140444FLE
EPA ID:	NYR000168245
Date Shipped:	3/3/2016
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR986628162
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported

MTA NYCT - 23RD STREET STATION - A C E LINES (Continued) **S120678879**

Was Load Rejected:	NEW YORK, NY 10004
Reason Load Was Rejected:	Not reported
Manifest Number:	008273717FLE
EPA ID:	NYR000168245
Date Shipped:	11/19/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR986628162
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10004
Reason Load Was Rejected:	Not reported

BI936 **237 REALTY NY LLC** **NY AST** **U003385150**
ESE **237 WEST 18TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.248 mi.
1311 ft. **Site 5 of 5 in cluster BI**

Relative: AST:
Higher

Name:	237 REALTY NY LLC
Address:	237 WEST 18TH STREET
City,State,Zip:	NEW YORK, NY 10011
Region:	STATE
DEC Region:	2

Actual:
23 ft.

237 REALTY NY LLC (Continued) **U003385150**

Site Status:	Active
Facility Id:	2-097470
Program Type:	PBS
UTM X:	584471.51851
UTM Y:	4510583.35618
Expiration Date:	02/22/2026
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	2800
Affiliation Type:	Emergency Contact
Company Name:	237 REALTY NY LLC
Contact Type:	Not reported
Contact Name:	ELINOR ARZT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 560-7737
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-11-12

Site Id:	2800
Affiliation Type:	Facility Operator
Company Name:	237 REALTY NY LLC
Contact Type:	Not reported
Contact Name:	ERVIN OLEVIC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 681-6430
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-11-12

Site Id:	2800
Affiliation Type:	Mail Contact
Company Name:	237 REALTY LLC
Contact Type:	Not reported
Contact Name:	MEIR BOUSKILA
Address1:	P.O. BOX 1920
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10116
Country Code:	001
Phone:	(212) 564-2111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL

237 REALTY NY LLC (Continued) **U003385150**

Date Last Modified: 2020-12-11

Site Id: 2800
Affiliation Type: Facility Owner
Company Name: 237 REALTY NY LLC
Contact Type: AGENT
Contact Name: ISAK RADONCIC
Address1: P.O. BOX 1920
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10116
Country Code: 001
Phone: (212) 564-2111
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2020-12-14

Tank Info:

Tank Number: 1
Tank Id: 5135
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/03/1992
Capacity Gallons: 2500
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DMPOKRZY
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

BX937 **CON EDISON SERVICE BOX: 4231** **RCRA NonGen / NLR** **1017772915**
ENE **220-218 W 23RD ST & 8TH AVE** **FINDS** **NYP004506929**
1/8-1/4 **NEW YORK, NY 10011**
0.249 mi.
1313 ft. **Site 10 of 12 in cluster BX**

Relative: **Higher**

Actual: **22 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140522
Handler Name:	CON EDISON SERVICE BOX:	4231
Handler Address:		220-218 W 23RD ST & 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004506929
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 4231 (Continued) **1017772915**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 4231 (Continued) **1017772915**

Electronic Manifest Broker: Not reported

Receive Date: 20140522
Handler Name: CON EDISON SERVICE BOX: 4231
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063802782

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

BX938 **CON EDISON SERVICE BOX: 4242** **RCRA NonGen / NLR** **1017772916**
ENE **206 W 23RD ST & 8TH AVE** **FINDS** **NYP004506937**
1/8-1/4 **NEW YORK, NY 10011**
0.249 mi.
1313 ft. **Site 11 of 12 in cluster BX**

Relative:
Higher

Actual:
22 ft.

RCRA NonGen / NLR:
Date Form Received by Agency: 20140522
Handler Name: CON EDISON SERVICE BOX: 4242
Handler Address: 206 W 23RD ST & 8TH AVE
Handler City,State,Zip: NEW YORK, NY 10011
EPA ID: NYP004506937
Contact Name: THOMAS TEELING
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-3770

CON EDISON SERVICE BOX: 4242 (Continued) **1017772916**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

CON EDISON SERVICE BOX: 4242 (Continued) **1017772916**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140522
Handler Name: CON EDISON SERVICE BOX: 4242	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 4242 (Continued) **1017772916**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063802791

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

BX939 **CON EDISON SERVICE BOX: 4233** **RCRA NonGen / NLR** **1017773228**
ENE **209-207 W 23RD ST & 8TH AVE** **FINDS** **NYP004510087**
1/8-1/4 **NEW YORK, NY 10011**
0.249 mi.
1313 ft. **Site 12 of 12 in cluster BX**

Relative: Higher
Actual: 22 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20140524
Handler Name:	CON EDISON SERVICE BOX:	4233
Handler Address:		209-207 W 23RD ST & 8TH AVE
Handler City,State,Zip:		NEW YORK, NY 10011
EPA ID:		NYP004510087
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported

CON EDISON SERVICE BOX: 4233 (Continued) **1017773228**

Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 4233 (Continued) **1017773228**

Sub-Part P Indicator: No

Historic Generators:

Receive Date: 20140424
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140424
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140524
Handler Name: CON EDISON SERVICE BOX: 4233
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063769863

CON EDISON SERVICE BOX: 4233 (Continued) **1017773228**

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

BS940 **MARY BOONE GALLERY** **NY LTANKS** **S104782023**
North **537-541 W. 24TH ST** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.250 mi.
1319 ft. **Site 2 of 7 in cluster BS**

Relative: **Lower**
Actual: **10 ft.**

LTANKS:

Name:	MARY BOONE GALLERY
Address:	537-541 W. 24TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0005393 / 2007-06-08
Facility ID:	0005393
Site ID:	229980
Spill Date:	2000-08-05
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	kkchanda
Referred To:	Not reported
Reported to Dept:	2000-08-05
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2000-08-05
Spill Record Last Update:	2007-06-11
Spiller Name:	KRIS MAIN
Spiller Company:	Not reported
Spiller Address:	537 -541 W. 24TH ST
Spiller County:	001
Spiller Contact:	KRIS MAIN
Spiller Phone:	(732) 390-5858
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	189550
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 4/22/03 SAMUEL- RCVD TANK CLOSURE & SITE ASSESSMENT REPORT. CONTACT PERSON:- HUGH J FREUND 212 705 7000- ATTORNEY FOR THE MARY BOONE GALLERY (R.P) 2/9/06- DEC Piper spoke w/ LEE WESTCHOTT at

MARY BOONE GALLERY (Continued) **S104782023**

Whitman CO. As per conversation there was free floating product discovered at the property. There is a monitoring well network. It has been recently sampled and Lee will forward a summary status report to the dept. including analytical summaries within the next month. Case referred to Koon Tang. 06/08/06: This spill transferred to S.Kraszewski. - SK 08/14/06: Received a voicemail from Ira Whitman, concerning the status of the site. He gave no callback number. SK reviewed the Tank Closure Report from Fall 2001. It is evident that high levels of VOCs were detected around the fuel oil UST. Lower exceedances were also found around the gasoline USTs and the Oil/Water separator. No mention if GW was encountered; the site lies next tothe Hudson River so GW is probably shallow. No MWs were installed during the investigation. Must know the GW condition above all else at this point. - SK 08/15/06: Called Ira Whitman (732-553-4333) after he left a voicemail. He is no longer the consultant involved with this site, in fact he believes that no firm is involved at all. He was involved on a site project adjacent from this one: Dynamic Delivery was the contractor involved with the clean-up. He said this site already received an NFA. I said, based on the report, the GW condition must be established. He said it might be worth-while to review the reports from the neighboring site, which is also downgradient from this one (closer to the Hudson.) He said to contact a John Houshmand, of Clark Construction, who discovered the tanks during renovation work on the property. - SK 08/18/06: Left a message for John Houshmand (917-553-4333). - SK 08/22/06: John Houshmand called back. He gave me the contact info for Mary Boone, owner of the gallery. Gallery: 212-753-2929, Cell: 917-861-2929. She is not the property owner of the site, she only rents the space. According to John, contractor for the building and several others nearby, after the abatement of the gasoline tanks, fuel oil tank and sump pit the entire area was covered in concrete and established as the Mary Boone Gallery. He also mentioned the adjacent site which supposedly has GW wells and may be useful in characterizing the GW condition for this site. I told John I would look into this other site and get back to him, since he regularly deals with the owner. - SK 08/29/06: I discussed the site situation with JK. The site needs a GW investigation, unfortunately their is no access to the interior so the MWs need to be placed on the sidewalk next to the former gasoline USTs and oil/water separator pit. Also, a soil boring next to the gasoline fill port will be needed. I called John Houshmand (917-553-4333) and explained what work would need to be done. I also asked him for the property owner's contact info since it is not on file. He will find out, plus he asked about other consultants to do the work since The Whitman company had a falling out with Mary Boone. I said to convince her that he seems like a reputable company based on the report. Letter was sent out asking for two MWs, a soil boring and sub-slab soilgas sampling. Property owner is a Samuel Weinberg. - SK 11/09/06: Reassigned from Stephen Kraszewski to Chanda. (Chanda) 01/02/07:Kartik Chnada of DEC sent a letter to Property Owner(Mr.Samuel Weinberg), requring that an additional investigation of GW and additional monitoring wells at the site. A work plan is mandated by 03/02/07 for approval. 01/10/07: Chanda received an e-mail from John Houshmand, Clark Construction Corp.He said that the RP will be retained Long Island Analytical Laboratories(LIAL), Inc. to perform this work. 2/27/07: Chanda received a limited subsurfsce investigstion work plan prepared by LIAL dated on 2/26/07. 2/28/07: Chnada reviewed the limited subsurface investigation work plan. on

MARY BOONE GALLERY (Continued) **S104782023**

2/28/07, the Department conditionaly approves this work plan. On 2/28/07, Chanda sent a letter to RP(Samuel Weingberg)and his consultant (John Hushmand), Michael Veraldi (LIAL), requiring that an investigation summary report be submitted to DEC for review by April 16, 2007. 4/19/07: Chnada received a phone call from Michael Veraldi, LIAL concerning the status of the site. He explained to me the cause of the delay on the investigation work report. 4/23/07: Chanda received a letter from Michael veraldi, LIAL regarding an extension to complete the approved work plan at the site. 4/24/07: Chanda sent a time extension approval letter to the RP(Samuel Weingberg) and his consultant (John Hushmand), Michael Veraldi (LIAL). An Investigation Summary Report must be submitted to the Department by May 4, 2007. (Chanda) 5/24/07: Chanda called John Hushmand (Clark Construction Corp.)and Micheael Veraldi (LIAL) regarding the investigation Summary Report and present site status. Micheal told me all work has been done and he is wating for analytical results. The report will be submited to DEC for review by 5/31/07. 6/6/07: On 6/5/07, Chanda received a Limited sub-surface site investigation report prepared by LIAL dated May 30, 2007. 6/8/07:Kartik Chanda of DEC reviewed the imited sub-surface site investigation report regarding this spill.
The soil samples, grondwater samples and soil vapor samples showed that results is not exceed our NYSDEC and NYSDOH guideline. Chanda discussed with Joe Sun (NYSDEC) regarding the results of soil, groundwater, and soil vapor samples. Based on the information presented to the Department DEC closed this spill case. 6/11/07: Chanda sent a NFA letter to Samual Weinberg, Weinberg Properties and his consultants (John Houshmand, and Miclael Vrraldi) regarding closed this spill case. "

Remarks: "while removing tanks contaminated soil found -"

All Materials:

Site ID:	229980
Operable Unit ID:	826450
Operable Unit:	01
Material ID:	2125258
Material Code:	2645A
Material Name:	BTEX
Case No.:	Not reported
Material FA:	Oxygenates
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	True

Site ID:	229980
Operable Unit ID:	826450
Operable Unit:	01
Material ID:	550119
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	True

Site ID: 229980

MARY BOONE GALLERY (Continued) **S104782023**

Operable Unit ID:	826450
Operable Unit:	01
Material ID:	550118
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	True

Site ID:	229980
Operable Unit ID:	826450
Operable Unit:	01
Material ID:	2125257
Material Code:	0032A
Material Name:	methanol
Case No.:	00067561
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	True

BS941 **508 WEST 24TH STREET - DOB JOB NO. NB - 121181014** **NY VCP** **S127989949**
North **508 WEST 24TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.251 mi.
1323 ft. **Site 3 of 7 in cluster BS**

Relative: **Lower**
Actual: **11 ft.**

VCP NYC:

Project ID:	11TMP0349M,11EH-N349M,12CBCP044M
Name:	508 WEST 24TH STREET - DOB JOB NO. NB - 121181014
Address:	508 WEST 24TH STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Manhattan
BBL:	1.0069500441006899E+19
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.748727
Longitude:	-74.004587
Postcode:	4
Community Board:	3
Council District:	99
Census Tract:	1089697
BIN:	1006957508
NTA:	Hudson Yards-Chelsea-Flatiron-Union Square

BU942 **NYC DEPT SANITATION** **NY LTANKS** **S102660095**
SW **2 BLOOMFIELD ST** **NY Spills** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.255 mi.
1349 ft. **Site 2 of 2 in cluster BU**

Relative: **Lower**

Actual: **4 ft.**

LTANKS:

Name:	2 BLOOMFIELD STREET
Address:	2 BLOOMFIELD STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9505382 / 2007-07-05
Facility ID:	9505382
Site ID:	302328
Spill Date:	1995-08-01
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	1995-08-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-09-26
Spill Record Last Update:	2007-07-05
Spiller Name:	Not reported
Spiller Company:	NYC DEPT OF SANITATION
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	244264
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY 7/5/07. Transered from A. Zhitomirsky to J.Krimgold. 7/5/07. Spill no the concrete floor. Has been cleaned up. NFA. "
Remarks:	"LEAK FROM MOTOR OIL TANK ONTO CONCRETE FLOOR BEING REPAIRED NOW - CLEANED UP"

All Materials:

Site ID:	302328
Operable Unit ID:	1020305
Operable Unit:	01
Material ID:	363374
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

NYC DEPT SANITATION (Continued) **S102660095**

Site ID:	302328
Operable Unit ID:	1020305
Operable Unit:	01
Material ID:	363375
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	100.00
Oxygenate:	Not reported

Name:	NYC DEPT SANITATION
Address:	2 BLOOMFIELD ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0306368 / 2003-10-20
Facility ID:	0306368
Site ID:	132227
Spill Date:	2003-09-16
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2003-09-16
CID:	257
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-09-16
Spill Record Last Update:	2003-10-20
Spiller Name:	Not reported
Spiller Company:	NYC DEPT SANITATION
Spiller Address:	2 BLOOMFIELD ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	113884
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 9/16/03 Rossan, DDO; Contaminated soil letter prepared and sent To: J. Holchandler 44 Beaver Street 8th Floor New York, NY 10004 Ed. 10/20/03 TJD For tracking purposes all open spills on property consolidated into one single primary spill number. The primary spill number for above location is designated as 0305020. Spill #0306368 has been closed and cross-referenced as described above."
Remarks:	"during a tank removal they found contaminted soil "

NYC DEPT SANITATION (Continued) **S102660095**

All Materials:

Site ID:	132227
Operable Unit ID:	872923
Operable Unit:	01
Material ID:	565647
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	MANHATTAN 2 GARAGE
Address:	2 BLOOMFIELD ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	1209358 / 2013-01-09
Facility ID:	1209358
Facility Type:	ER
DER Facility ID:	113884
Site ID:	472422
DEC Region:	2
Spill Cause:	Storm
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2012-11-05
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2012-11-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-11-06
Spill Record Last Update:	2013-01-09
Spiller Name:	Not reported
Spiller Company:	HURRICANE SANDY
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JAY SHAH
DEC Memo:	"11/21/12-Hiralkumar Patel. went to site for inspection. inspected garage floor. no sign of spill noted. as per on-site personnel, 55 gal drum was knocked over during flood and some oil was spilled on water. all cleaned up. 01/09/13-Hiralkumar Patel. after discussion with DEC Austin, case closed based on observations during the site visit on 11/21/12."
Remarks:	"55 gallon on water - cleanup crew in progress"

NYC DEPT SANITATION (Continued) **S102660095**

All Materials:

Site ID:	472422
Operable Unit ID:	1222281
Operable Unit:	01
Material ID:	2220971
Material Code:	0013
Material Name:	lube oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	55.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	NYC SANITATION GARAGE
Address:	2 BLOOMFIELD ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0305020 / 2014-05-21
Facility ID:	0305020
Facility Type:	ER
DER Facility ID:	113884
Site ID:	132226
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2003-08-12
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2003-08-12
CID:	205
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-08-12
Spill Record Last Update:	2014-05-21
Spiller Name:	CALLER
Spiller Company:	2 BLOOMFIELD ST
Spiller Address:	2 BLOOMFIELD ST
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND contaminated soil letter sent to: Liro Engineering 669 West 158th St, NY 10032 10/20/03 TJD For tracking purposes another open spill (0306368) on property has been closed and cross referenced to above spill number. 12/16/2003 Fenley & Nichol submitted a report which outlines the removal of the tank and surrounding soil. End point samples from the sidewalls and bottom show some SVOC hits. Groundwater samples show only MTBE hit. 1/7/03 MT For tracking purposes another open spill (0311250) on property has been closed and

NYC DEPT SANITATION (Continued) **S102660095**

cross referenced to above spill number. 05/21/14-Hiralkumar Patel. due to nature of the spill and based on available information, case closed."
Remarks: "CALLER DIGGING ON SITE AND UNCOVERED OLD TANK, NOT KNOW TO BE THERE."
Not reported

All Materials:
Site ID: 132226
Operable Unit ID: 871817
Operable Unit: 01
Material ID: 502293
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: OTHER
Address: 2 BLOOMFIELD ST
City,State,Zip: MANHATTAN, NY
Spill Number/Closed Date: 0311250 / 2004-01-07
Facility ID: 0311250
Facility Type: ER
DER Facility ID: 113884
Site ID: 132228
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 3101
Spill Date: 2004-01-05
Investigator: MXTIPPLE
Referred To: Not reported
Reported to Dept: 2004-01-05
CID: 404
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-01-05
Spill Record Last Update: 2004-01-07
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: BERNARD MARKOWITZ
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 1/7/04 tipple closing this number and referring it to spill to an open spill on this site # 03-05020"
Remarks: "THIS COMPANY WAS DRILLING TO INSTALL PILLINGS AND FOUND CONTAMINATED

NYC DEPT SANITATION (Continued) **S102660095**

SOIL AND WATER IN THE HOLES. RICK CALVERT IS THE OTHER CONTACT FOR THIS SPILL."

All Materials:

Site ID:	132228
Operable Unit ID:	876608
Operable Unit:	01
Material ID:	500073
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

BS943 **514 WEST 24TH STREET** **NY VCP** **S118943495**
North **514 WEST 24TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.260 mi.
1372 ft. **Site 4 of 7 in cluster BS**

Relative:
Lower

Actual:
11 ft.

VCP NYC:

Project ID:	11TMP0031M,11EH-N031M,15CVCP106M
Name:	514 WEST 24TH STREET
Address:	514 WEST 24TH STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Manhattan
BBL:	1006950047
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Closure
Latitude:	40.748771
Longitude:	-74.004695
Postcode:	4
Community Board:	3
Council District:	99
Census Tract:	1090213
BIN:	1006957511
NTA:	Hudson Yards-Chelsea-Flatiron-Union Square

BW944 **FORMER GETTY SERVICE STATION** **NY LTANKS** **S106703285**
North **239 10TH AVENUE** **NY BROWNFIELDS** **N/A**
1/4-1/2 **NEW YORK, NY 10001** **NY Spills**
0.260 mi.
1373 ft. **Site 4 of 8 in cluster BW**

Relative:
Lower

Actual:
12 ft.

LTANKS:

Name:	GETTY GAS STATION
Address:	239 10TH AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	8806159 / 1994-07-29
Facility ID:	8806159
Site ID:	315130
Spill Date:	1988-10-20
Spill Cause:	Tank Test Failure

FORMER GETTY SERVICE STATION (Continued) **S106703285**

Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	A3
Cleanup Ceased:	1994-07-29
SWIS:	3101
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1988-10-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-11-02
Spill Record Last Update:	2005-03-14
Spiller Name:	TOM DIXON(CONTACT)
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	254062
DEC Memo:	""
Remarks:	"2 4K TKS BOTH L R'S UNREADABLE. GETTY WILL EXCAV & INVES."

All TTF:

Facility ID:	8806159
Spill Number:	8806159
Spill Tank Test:	1534794
Site ID:	315130
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	315130
Operable Unit ID:	921327
Operable Unit:	01
Material ID:	454514
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum

FORMER GETTY SERVICE STATION (Continued) **S106703285**

Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: Not reported

BROWNFIELDS:
Name: FORMER GETTY SERVICE STATION
Address: 239 10TH AVENUE
City,State,Zip: NEW YORK, NY 10001
Program: BCP
Site Code: 488150
Acres: 0.130
HW Code: C231086
SWIS: 3101
Town: New York City
Record Added Date: 10/21/2013
Record Updated Date: 01/13/2014
Update By: BXANDERS
Site Description: "Location: The site is located at the northwest corner of the intersection of West 24th Street and 10th Avenue. The site is approximately 0.13 acres in size. Site Features: The site currently is occupied by a non-operating gasoline service station, including a recently vacated 1-story commercial building last used as a convenience store. Current Zoning and Land Use: The subject property is zoned as M1-5, which allows for commercial and mixed-use buildings. The intended use of the site is for residential and commercial. The site is bounded directly adjacent by an 11-story residential building to the north, a car wash and mixed-use (residential and commercial) building to the south, and across 10th Avenue 4- and 6-story mixed-use buildings and a 20 story residential building. The site is approximately 100 feet away from the High Line Park, which overlooks the site to the east, separated by a one-story art gallery. Past Use of the Site: The site was operated as a small portion of a gas light fixture manufacturing facility that occupied the eastern third of the block in the 1890s. The site then operated as a gasoline filling station from at least 1930 until recent decommissioning in 2013. Since 1988 the site had 8 spill numbers assigned to it, out of which one spill number still remains open. In 1998 twelve 550-gallon gasoline USTs, three 4,000-gallon gasoline USTs, one 275-gallon fuel oil UST, and two fueling pump islands were removed and 1,853 tons of impacted soil was removed. Post excavation soil sampling results identified concentrations of volatile organic compounds (VOCs) exceeding NYSDEC Recommended Soil Cleanup Objectives (RSCOs). Petroleum impacted groundwater was also detected on-site which still remains. Site Geology and Hydrogeology: The geologic conditions at the site consists mainly of fine to medium grained sands mixed with gravels, boulders, construction debris and interbedded layers of silt down to 25 feet below grade (fbg). The Site s topography is generally flat and the surface elevation is approximately 43 feet above mean sea level. Groundwater occurs within the unconsolidated soils at depths ranging from approximately 7 to 10 fbg; based on historical gauging data, there appears to be an appreciable degree of seasonal variation in the direction of groundwater flow at the site, periodically fluctuating between south, southwest and west. "
Env Problem: "Nature and Extent of Contamination: Based upon investigations

FORMER GETTY SERVICE STATION (Continued) **S106703285**

conducted to date, the primary contaminants of concern for the site include petroleum hydrocarbon related volatile organic compounds (VOCs) compounds. Soil: Per 1998 lab results for the end point soil samples collected from 10 feet below grade (SW-7) the highest benzene concentration was detected as 44.5 ppm which exceeded the soil cleanup objective (SCO) for commercial use (to 44 ppm). Other SCO exceedances were ethylbenzene at 198 ppm (restricted residential SCO = 41 ppm), xylene at 1,990 ppm (industrial SCO=1000 ppm), toluene at 479 ppm (resrricted residential SCO=100 ppm) and MTBE at 124 ppm (restricted residential SCO= 100 ppm). Groundwater: Since 2001 twelve (12) monitoring wells have been installed on and off-site (3 on site and 9 off-site) related to the current open spill. Per August 2012 (latest available) monitoring data the highest on-site concentrations detected were: benzene (32 ppb), ethylbenzene (139 ppb), xylene (80.5 ppb) and MTBE (18.3 ppb). Groundwater standards have been exceeded for all of the above analytes. Site related soil vapor and indoor air samples never been analyzed. Special Resources Impacted/Threatened: The site is located in the urban area and Fish and Wildlife Impact Analysis is not warranted. "

Health Problem: "Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 6
Sub Type: P03
Owner Name: Ran Korolik
Owner Company: VHS 239, LLC
Owner Address: 3349 Highway 138, Bldg. C, Suite C
Owner Addr2: Not reported
Owner City,St,Zip: Wall, NJ 07753
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Ashley Forrest Curran
Owner Company: Muhlenberg Libary
Owner Address: 209 West 23rd Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10011-2379
Owner Country: United States of America
Own Op: 1
Sub Type: 06
Owner Name: Ran Korolik
Owner Company: VHS 239, LLC
Owner Address: 3349 Highway 138, Bldg C, Suite C
Owner Addr2: Not reported
Owner City,St,Zip: Wall, NJ 07753

FORMER GETTY SERVICE STATION (Continued) **S106703285**

Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	GETTY#341
Address:	239 10TH AVE.
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0509792 / 2005-11-16
Facility ID:	0509792
Facility Type:	ER
DER Facility ID:	305662
Site ID:	355627
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	D4
SWIS:	3101
Spill Date:	2005-11-15
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2005-11-15
CID:	406
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-11-15
Spill Record Last Update:	2005-11-16
Spiller Name:	UNKNOWN NAME
Spiller Company:	UNKNOWN CUSTOMER
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	"11.16.05 Sharif-Left a messege for Mike Carr, (518)786-3200x223 to follow up the spill .Tyree returned my call to say that spill was cleaned up by the getty operator. No sewer/soil was affected.It was on the concrete."
Remarks:	"1/2 gallon of material released due to customer overfill . Used speedy dry for clean up. Clean up is complete."

All Materials:

Site ID:	355627
Operable Unit ID:	1112975
Operable Unit:	01

FORMER GETTY SERVICE STATION (Continued) **S106703285**

Material ID:	2103021
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BW945 **239 10TH AVE/MANH/GETTY** **NY LTANKS** **S100167969**
North **239 10TH AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.260 mi.
1373 ft. **Site 5 of 8 in cluster BW**

Relative: **Lower**
Actual: **12 ft.**

LTANKS:

Name:	239 10TH AVENUE/GETTY
Address:	239 10TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8806160 / 1994-07-29
Facility ID:	8806160
Site ID:	86009
Spill Date:	1988-10-20
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	A3
Cleanup Ceased:	1994-07-29
SWIS:	3101
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1988-10-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-12-05
Spill Record Last Update:	1994-08-01
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	78946
DEC Memo:	""
Remarks:	"(2) 4K TANKS FAILED."

All TTF:

Facility ID:	8806160
Spill Number:	8806160

239 10TH AVE/MANH/GETTY (Continued) **S100167969**

Spill Tank Test:	1534795
Site ID:	86009
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	86009
Operable Unit ID:	922990
Operable Unit:	01
Material ID:	454515
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Name:	239 10TH AVE/MANH/GETTY
Address:	239 10TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9005116 / 1992-07-16
Facility ID:	9005116
Site ID:	86010
Spill Date:	1990-08-08
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	1992-07-16
SWIS:	3101
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1990-08-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1990-08-14
Spill Record Last Update:	1992-07-28
Spiller Name:	Not reported

239 10TH AVE/MANH/GETTY (Continued) **S100167969**

Spiller Company:	GETTY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	78946
DEC Memo:	""
Remarks:	"4K TANK FAILED AN AIR PRESSURE TEST."

All TTF:

Facility ID:	9005116
Spill Number:	9005116
Spill Tank Test:	1537408
Site ID:	86010
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	86010
Operable Unit ID:	942717
Operable Unit:	01
Material ID:	436177
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

BW946 **239 10TH AVENUE** **NY VCP** **S118943377**
North **239 10TH AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.260 mi.
1373 ft. **Site 6 of 8 in cluster BW**

Relative:
Lower

Actual:
12 ft.

VCP NYC:

Project ID:	14TMP0323M,14EH-N323M,14CVCP243M
Name:	239 10TH AVENUE
Address:	239 10TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Manhattan
BBL:	1006960032

239 10TH AVENUE (Continued) **S118943377**

OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed
Latitude:	40.748502
Longitude:	-74.003595
Postcode:	4
Community Board:	3
Council District:	99
Census Tract:	1090212
BIN:	1006967503
NTA:	Hudson Yards-Chelsea-Flatiron-Union Square

BS947 **EDISON PARKING GARAGE** **NY LTANKS** **S104277387**
North **527 WEST 23RD ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.264 mi.
1394 ft. **Site 5 of 7 in cluster BS**

Relative: LTANKS:
Lower

Actual:
10 ft.

Name:	EDISON PARKING GARAGE
Address:	527 WEST 23RD ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9808740 / 2004-05-27
Facility ID:	9808740
Site ID:	103493
Spill Date:	1998-10-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	1998-10-14
CID:	270
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-10-14
Spill Record Last Update:	2005-08-10
Spiller Name:	FRANK BROCKERAHOFF
Spiller Company:	EDISON PARKING GARAGE
Spiller Address:	527 WEST 23RD ST
Spiller County:	001
Spiller Contact:	FRANK BROCKERAHOFF
Spiller Phone:	(516) 921-9393
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	297702
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was K FOLEY SEE ALSO 86-05564, 95-11782, 96-05688. 5/27/04 Reassigned from Tibbe to K Foley. Remediation work to be performed under spill #96-05688."
Remarks:	"POSS REMOTE"

EDISON PARKING GARAGE (Continued) **S104277387**

All TTF:

Facility ID:	9808740
Spill Number:	9808740
Spill Tank Test:	1546388
Site ID:	103493
Tank Number:	Not reported
Tank Size:	8000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	14
Test Method 2:	VacuTest
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	103493
Operable Unit ID:	1069928
Operable Unit:	01
Material ID:	316229
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BS948 **MENDON LEASING** **NY LTANKS S104275477**
North **527 WEST 23RD STREET** **NY Spills N/A**
1/4-1/2 **NEW YORK, NY 10011**
0.264 mi.
1394 ft. **Site 6 of 7 in cluster BS**

Relative: LTANKS:
Lower

Name:	MENDON LEASING
Address:	527 WEST 23RD STREET
City,State,Zip:	NEW YORK, NY 10011
Spill Number/Closed Date:	9513588 / 2001-02-22
Facility ID:	9513588
Site ID:	216215
Spill Date:	1996-01-26
Spill Cause:	Tank Test Failure
Spill Source:	Tank Truck
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1996-01-26
CID:	349

Actual:
10 ft.

MENDON LEASING (Continued) **S104275477**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1996-01-26
Spill Record Last Update:	2005-08-10
Spiller Name:	TOM FASINI
Spiller Company:	MENDEN LEASING
Spiller Address:	523 W 23RD ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(212) 675-8906
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	197
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE TRANSFERED FROM O'DOWD TO TIBBE ON 02/22/01. REFER TO 96-05688. SEE ALSO 95-11782, 98-08740, 86-05564."
Remarks:	"tested w/water - visual leak - 5 tanks all 550 gallons/ possibilty of a 6th tank that is buried"

All TTF:

Facility ID:	9513588
Spill Number:	9513588
Spill Tank Test:	1544374
Site ID:	216215
Tank Number:	1-5
Tank Size:	550
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	01
Test Method 2:	Petro-Tite/Petro Comp
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	216215
Operable Unit ID:	1028074
Operable Unit:	01
Material ID:	357304
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

MENDON LEASING (Continued) **S104275477**

Name:	MENDON LEASING CORP
Address:	527 WEST 23RD STREET
City,State,Zip:	NEW YORK, NY 10011
Spill Number/Closed Date:	9511782 / 2004-05-27
Facility ID:	9511782
Site ID:	301889
Spill Date:	1995-12-18
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	1995-12-18
CID:	311
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1995-12-18
Spill Record Last Update:	2005-08-10
Spiller Name:	TOM MASINI
Spiller Company:	MENDON LEASING CORP
Spiller Address:	362 KINGSLAND AV
Spiller County:	001
Spiller Contact:	RICH RICTHO
Spiller Phone:	(212) 675-8906
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	197
DEC Memo:	"8/15/96 SEE ALSO 96-05688, 98-08740, 86-05564. (MARK TIBBE) SPILL ORIGINALLY ASSIGNED TO MARTINKAT - FILE TRANSFERRED TO MULQUEEN. TRNSFERED TO TIBBE ON 2/12/01. 4/12/04-Vought-Spill transferred from Tibbe to Rommel as per Rommel. 4/19/04 Reassigned from Rommel to K. Foley. 5/27/04 Remediation work to be performed under spill #96-05688."
Remarks:	"TEST CONDUCTED AND RESULTS RECORDED."

All TTF:

Facility ID:	9511782
Spill Number:	9511782
Spill Tank Test:	1544328
Site ID:	301889
Tank Number:	1-4
Tank Size:	550
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	01
Test Method 2:	Petro-Tite/Petro Comp
Leak Rate:	.00
Gross Fail:	Not reported

MENDON LEASING (Continued) **S104275477**

Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 301889
Operable Unit ID: 1022460
Operable Unit: 01
Material ID: 359107
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: MENDON LEASING
Address: 527 WEST 23RD STREET
City,State,Zip: NEW YORK, NY 10011
Spill Number/Closed Date: 8605564 / 1986-12-03
Facility ID: 8605564
Site ID: 301566
Spill Date: 1986-12-03
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 1986-12-03
SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 1986-12-03
CID: Not reported
Water Affected: GROUND WATER
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1986-12-06
Spill Record Last Update: 2005-08-10
Spiller Name: Not reported
Spiller Company: MENDON LEASING
Spiller Address: 527 W. 23 ST.
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 197
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 10/10/95: This is additional information about material spilled from the translation of the old spill file: UNK AMT. SPILLED REFER TO 96-05688. SEE ALSO 95-11782 AND 98-08740."
Remarks: "ONGOING FOR APPROX. 5 MONTHS & GROUND APPEARS TO BE SATURATED NEAR

MENDON LEASING (Continued) **S104275477**

HUDSON RIVER. REPORTED BY USCG(PO BLYDEN)(212)668-7920"

All Materials:

Site ID:	301566
Operable Unit ID:	902510
Operable Unit:	01
Material ID:	474740
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	MENDON LEASING
Address:	527 WEST 23RD STREET
City,State,Zip:	NEW YORK, NY 10011
Spill Number/Closed Date:	9605688 / 2008-09-22
Facility ID:	9605688
Facility Type:	ER
DER Facility ID:	353585
Site ID:	301890
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	B3
SWIS:	3101
Spill Date:	1996-08-02
Investigator:	jamaison
Referred To:	NFA
Reported to Dept:	1996-08-02
CID:	266
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-08-02
Spill Record Last Update:	2008-09-22
Spiller Name:	Not reported
Spiller Company:	MENDON LEASING
Spiller Address:	527 WEST 23RD STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"SEE ALSO 86-05564, 95-11782, 98-08740, 95-13588. 4/12/04-Vought-Spill transferred from Tibbe to Rommel as per Rommel. 4/19/04 Reassigned from Rommel to K Foley. 5/24/04 Tibbe received voicemail from Curt Schmidt, Fleming Lee Shue (212-675-3225). Replacing AKRF. 5/27/04 Added diesel and #2FO to material spilled to address spills #9808740 and 9511782. Spoke to C. Schmidt. Will set up

MENDON LEASING (Continued) **S104275477**

a site meeting next week. 555 W 23th St(spill #0306399), the Tate building, is adjacent to Mendon property which has a system installed on the first floor (no basement). 6/3/04 Set up meeting with A. Fleming for Monday, 6/7. A. Fleming (office 212-675-3225, cell 917-885-1475). 6/7/04 Met with A. Fleming. System located inside Tate has not been in operation. Arnie needs to look into system manufacturer data to see if they can make changes to the system. Wells haven't been sampled since AKRF lost the job. Will arrange to have wells sampled. 7/15/04 Received call from C. Schmidt, FLS. Wells will be sampled 7/19-7/20. FLS still looking into making changes to existing system. 9/21/04 Spoke with Mohammed Ahmed, Fleming Lee Shue (917-612-6018). He was previously with AKRF. Would like to present all data and propose NFA. He will need to FOIL the file to get AKRF data. 10/13/04 Received summary from FLS proposing closure of site. Background: Site is currently a luxury apartment building with art galleries on the ground floor. The site was historically used for freight transportation and warehouse facilities. The Hudson River is approx 0.25mi to the west. Site was mainly used as a truck rental, fueling and maintenance yard. Hertz formerly occupied the site and built a two-story garage in 1963. Hertz installed six 550gal gas USTs in the adjacent parking area located along 24th Street. Hertz also installed a gas distribution system with 4 dispensers. In 1965, Hertz installed four additional 550gal diesel USTs and a separate dispenser. One 7500gal heating oil tank was installed in the SW portion of the building. CMCR, LTD acquired the site from Hertz and also used the site as a truck rental/leasing facility. In 1985, the site was leased to Mendon Leasing Corp. Mendon reported four spills, 9511782(diesel), 9513588(gas), 9605688(gas), 9808740(#2FO). Costco Wholesale purchased the site in 1998 in anticipation of zoning that would allow a retail development at the site and closed the fuel and gas tanks in place. In July 2000, the Related Companies purchased the property and built the current apartment building that covers the site. Tank testing: In July 1990, Mendon was issued an NOV from the FDNY for failing to do the 10yr tightness testing on the six gas tanks. In March 1991, Mendon has all the gas and diesel tanks tested. The gas tanks passed but the diesel tank failed. The diesel tank was repaired and passed retest. In 1993, the heating oil tank was tested and passed. In 1995, the diesel tanks were tested again and failed. The contents were emptied in 5/96 and filled with polyurethane foam. In Feb 1997, the gas tanks were also emptied and filled with water. Previous Investigations: Several invetigations were conducted between 1993 and 2001. ES Engineering did work on behalf of Greyhound Lines. ERM Northeast did work for DEC. AKRF did work for Costco and Related. Soil and GW has been impcated by on-site releases of petroleum and possibly also off-site sources. Areas within the parking lot on the north side of the former two-story garage building and inside the building, in the vicinity of the heating oil tank, contained free product in soils and GW. Free product in the former parking lot ranged from 0.08 to 1.63'. Free product found inside the former garage building was as thick as 4'. Dissolved-phase VOCs were also detected in GW as high as 5408ppb. No SVOCs were detected. Soil/GW interface is located at approx 8'bgs, flowing west toward Hudson. GW is not tidal. Bedrock approx 63'bgs, sloping S-SW. Remedial Actions: In Dec 1999, four 550gal diesel USTs and six 550gal gas USTs were removed from beneath the open parking lot. The heating oil tank was removed in Oct 2000. Approx 1000 tons of grossly contaminated soils were excavated and disposed of. The free product appeared on the

MENDON LEASING (Continued) **S104275477**

groundwater surface and removed with absorbant pads. The excavations were left open to monitor for free product. No additional free product was observed and excavations were backfilled. No post-ex sampling was completed. The Department issued a letter on 2/12/01 with comments. A remedial workplan consisting of an in-situ remediation for soil and GW using SVE and bioremediation was presented and approved by the Dept. In March-April 2001, six geoprobes were completed. NMW-1 showed total BTEX in GW at 275400ppb, NWM-2 at 156200ppb, and NMW-4 at 1330ppb. Insufficient GW was recovered from NMW-3 and NMW-5. NMW-6 was non-detect. In October 2000, an SVE pilot was performed. An underslab SVE system was designed and installed to remove residual VOCs and to add atmospheric oxygen to allow bioremediation to occur. Air extracted from below the slab was carbon treated before venting to the roof. A vapor barrier was installed beneath the slab. Operation of the system began August 2002 and operated thru August 2003 for 1615hrs. VOCs, carbon dioxide, oxygen and moisture levels were monitored before the input and at the output of the carbon canisters. System inspection and monitoring were conducted daily for the first two weeks and then weekly inspections were made. At startup, VOCs were measured at 20-50ppm. Concentrations dropped from the initiation in August 2002 thru November 2002 when the system was stopped for seven weeks due to equipment problems. Upon restarting the system in Jan 2003, a rebound was measured with VOCs rising to 60ppm. The system was operated for two weeks with a second 4 week idle period(1/7/03-2/25/03). After this rest period, the rebound did not occur. The system operated for a period of four weeks with a continual decrease of VOC concentration. Equipment failure again shut the system down for five weeks(3/27/03-5/1/03). A slight rebound to several ppm occured when the system restarted. The system continued to operate thru June 2003 with day-long shutdown for maintenance with no rebounds observed. Levels of VOCs in the extracted air in June 2003 were zero. Between July 2003 and July 2004, the SVE system was out of service due to major damage in the main section of the blower. In August 2004, the SVE blower and motor were downsized to a 10HP regenerative blower capable of 200 scfm at 80 inches of water. VOCs were measured two days after startup which detected levels of VOCs in extracted air between 2 and 5ppm, indicating that no significant VOCs are being extracted from beneath the building. A total of 10 MWs exist on site. Four(MW-3, ERM-4, MW-14, MW-15) are currently located on the sidewalk. The other six(NMW-1 to NMW-6) are inside the Tate building. Max total BTEX detected in MW-14 at 1990ppb(7/16/02). Max MTBE detected in NMW-2 at 410ppb(8/8/03). By the concentrations of MTBE detected in upgradient wells, MW-14 and MW-15, there may be an off-site source. (There are two gas stations upgradient at 24th St and 10th Ave.) Concentrations of BTEX have been decreasing in source areas. It appears that removal of grossly contaminated soils and free product at the time of the UST removal in 2001 eliminated the primary source of GW contamination. Groundwater samples to be collected 10/16/04. 11/1/04 Spoke to Mohammed Ahmed, FLS (212-675-3225). Approx 3 of free product(gasoline) was detected in MW-14 (sidegradient of tank field) on 8/17/04. One week later, there was no product detected. Sampled again on 10/14/04, no product detected. He suspects that it is from an off-site source. There is a LukOil Station at 239 10th Avenue (open spills #9810383, 9707190). Oct 2004 monitoring report to be submitted this week. 11/16/04 Received status update (FLS, 11/11/04). GW sampling conducted 10/12-10/13/04. No samples were collected from

MENDON LEASING (Continued) **S104275477**

MW-15 located on the sidewalk of 24th St and NMW-1 located inside the Buia Gallery on 23rd St. MW-15 was backfilled during construction of the Tate Bldg. NMW-1 was inaccessible due to an exhibit. BTEX ranged from ND to 1086ppb(MW-14). MTBE ranged from ND to 130ppb(NMW-2). Off-site sources of contamination may be contributing to site conditions. However, it is not clear that it is not from onsite sources. 12/7/04 Issued letter requiring additional delineation around MW-14 and at former upgradient well location MW-15. Report to be submitted by 3/15/05. 12/20/04 Spoke to M. Ahmed, FLS. Will propose re-installation of upgradient MW-15, one well further upgradient (to confirm possible off-site impacts), and one west of MW-14(sidegradient). 12/29/04 Received proposal from FLS to install three additional MWs. 12/30/04 Issued letter approving workplan. 2/18/05 Received report for the installation of MW-14, 15A and 17. According to the report, there appears to be an off-site source on the northwest portion of property along W24th St. Concentrations of BTEX increased from 1086ppb to 2067ppb in MW-14. Report also states that the LukOil station may be contributing to the MTBE concentrations across the site. 3/15/05 Spoke to Mohammed Ahmed, FLS. Requested two Geoprobes across W 24th St to eliminate the Motor Freight Station and Auto Repair Shop as potential sources. 8/15/05 Spoke to M. Ahmed. A. Fleming spoke to NYSDOH at K. Tang's recommendation. NYSDOH requested subslab and indoor air samples. Results expected next week. FLS proposes to use this data to support closure. Explained that there is still dissolved which remains on the corner of the property. Agreed to wait for results to decide next steps. 11/29/05 Email to A. Fleming and M. Ahmed, FLS, provided comments on the October 17th request for spill closure. Regarding the indoor air and soil gas sampling which was performed, it is unclear if the concentrations detected within the building are due to any background interferences within the building. Directed FLS to conduct a full inventory as directed by the NYSDOH guidance for evaluating soil vapor intrusion. An additional round of indoor air samples must be taken at least 24hrs following the removal of any possible VOC sources. Results will be forwarded to NYSDOH. The Departments will determine further action for vapor mitigation, if required, following review. The groundwater data collected to date has been sporadic with five sampling rounds completed within the last three years. Quarterly groundwater sampling and monthly gauging must be completed and results submitted to the Department. Groundwater direction must be confirmed. The groundwater concentrations at MW-14 were as high as 4340ppb total VOCs in the last sampling round in January and have historically been fluctuating. MW-17, which was recently installed west of MW-14, also had readings of 2777ppb total VOCs. The Department requires additional wells be installed across W 24th street, north of MW-14 and MW-17, and west of MW-17. A proposal to remediate the contamination in this area will be required. It is expected that the additional delineation, groundwater and indoor air sampling results, with scaled site and contour maps, will be submitted by the beginning of February. 4/20/06 Requested update from M. Ahmed of FLS. 6/30/06 DEC lead transferred from K. Foley to J.A. Maisonave. - JAM 7/06/06 Requested update from A. Flemming of FLS. Mr. Flemming and I spoke about the history of the site. He still believes the impacts to groundwater at wells MW-14 and MW-17 are from off-site contamination (possibly Lukoil site on 10th Ave and 24th Street). These wells are supposedly up-gradient side of the site. I requested Arnie send me the latest data on the site including

MENDON LEASING (Continued) **S104275477**

groundwater sampling and indoor air sampling data. - JAM 7/25/06 Spoke with A. Flemming a number of times. I do not believe a second round of indoor air sampling was conducted, however a vapor barrier is in place. They conducted site-wide groundwater sampling in May 06. Mr. Flemming believes the latest GW results show that off-site sources are contributing to the GW contamination along W24th Street. He will submit a report of the wells that were sampled (not all were sampled because they were inaccessable). I requested that he state his justification for spill closure in the groundwater sampling report. 10/16/06 Received a call from Steve Panter of Fleming Lee Shue (212) 675-3225. He said the report is ready and will be submitted this week. - JAM 11/14/06 Received the report dated October 20, 2006 via email. The report summarizes all the groundwater analytical data since April 2003. FLS makes the argument that off-site sources are contaminating the sidewalk wells. A summary of all the off-site sources is included as well as a two part technical explanation for the difference between groundwater contamination in the sidewalk MWs and on-site MWs. The first part is a multivariate analysis, and the second is a comparison between Benzene and MTBE. The report is uploaded into edocs. - JAM 11/22/06 Received SVE System Data and Indoor Air Quality Data Summary Report from FLS. Report uploaded to eDocs. 01/22/07 Issued a letter to Greg Gushee The Related Companies, Inc. 60 Columbus Circle New York, NY 10022 with the NYSDEC's position on the FLS report. Chris Magee in Central Office reviewed the report and based on the material presented he does not concur with FLS' conclusion that off-site sources are contributing to the contamination found in the sidewalk wells. The letter states that The Related Companies, Inc. is responsible to monitor and remediate the site. Groundwater must be gauged and sampled quarterly and based on the results the NYSDEC will determine if a remedial strategy is necessary. The letter is uploaded into edocs. - JAM 8/21/07 Reviewed FLS letter submitted to the DEC on April 13, 2007 in response to DEC comments sent on 1/22/07. FLS believes that contamination found in off-site wells on West 24th Street stems from a different source. I sent the letter to Chris Magee in Central Office for review. - JAM 9/06/07 Sent email to Steve Panter at FLS. The email states that, the data are inconclusive and do not prove that an off-site source is affecting the groundwater in the monitoring wells in the sidewalk... The Department cannot approve spill closure at this time. A round of groundwater samples should be collected from all wells to obtain up-to-date groundwater quality data. Results should be submitted with appropriate recommendations for further monitoring and/or remedial activities if necessary. - JAM 1/18/08 Received an email from Jim Harrington in Central Office. Steve Panter from FLS contacted Mr. Harrington stating that they will do another round of sampling but he wants assurance that after the next round of GW sampling the spill case will be closed. Mr. Harrington said he will review the spill case and material forwarded by Mr. Panter. Afterwards, he will contact Region 2 staff for further discussion before responding to Mr. Panter. - JAM 9/22/08 Reviewed the Groundwater Sampling Report/Spill Closure Request submitted by Flemming Lee Shue dated May 12, 2008. All on- and off-site monitoring wells were sampled in February 2008. Groundwater monitoring results show no signicant change in contaminant levels in any of the on-site or off-site wells. The sidewalk wells continue to show exceedences for VOCs in groundwater (i.e. 748ug/L total VOCs in well MW-14 and 829ug/L total VOCs in MW-16) however, the exposure risk from these

MENDON LEASING (Continued) **S104275477**

contaminants is low. The groundwater monitoring report is uploaded to eDocs. Senior technical staff in Central Office supports closure of this spill without meeting recommended objectives because of the low risk of exposure. This spill case was closed and a NFA letter was issued. NFA uploaded to eDocs. - JAM"

Remarks: "CALLER FOUND .7 FEET OF GASOLINE IN A TWO INCH GROUNDWATER MONITORING WELL. LOCATION IS A TRUCK LEASING COMPANY. MARK TIBBE NOTIFIED OF RESULTS. ADDITIONAL MONITORING WELLS TO BE INSTALLED AND SIX TANKS ARE TO BE PULLED."

All Materials:

Site ID:	301890
Operable Unit ID:	1036491
Operable Unit:	01
Material ID:	348432
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	True

Site ID:	301890
Operable Unit ID:	1036491
Operable Unit:	01
Material ID:	348434
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	True

Site ID:	301890
Operable Unit ID:	1036491
Operable Unit:	01
Material ID:	348433
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	True

Site ID:	301890
Operable Unit ID:	1036491
Operable Unit:	01
Material ID:	576796
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material

MENDON LEASING (Continued) **S104275477**

Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	True
Site ID:	301890
Operable Unit ID:	1036491
Operable Unit:	01
Material ID:	576797
Material Code:	2645A
Material Name:	BTEX
Case No.:	Not reported
Material FA:	Oxygenates
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	True

BV949 **53 HORACIO STREET** **NY LTANKS** **S102672567**
SSW **53 HORACIO STREET** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.264 mi.
1395 ft. **Site 3 of 3 in cluster BV**

Relative:
Higher

Actual:
16 ft.

LTANKS:

Name:	53 HORACIO STREET
Address:	53 HORACIO STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9406077 / 1994-08-04
Facility ID:	9406077
Site ID:	205771
Spill Date:	1994-08-04
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	1994-08-04
SWIS:	3101
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1992-08-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-10-19
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	WHALECO OIL CO
Spiller Address:	1 COFFEE STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported

53 HORACIO STREET (Continued) **S102672567**

DEC Region:	2
DER Facility ID:	170869
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks:	"OVERFILLED TANK-CLEAN UP, NO OTHER AGENCIES CALLED ."

All Materials:

Site ID:	205771
Operable Unit ID:	1000282
Operable Unit:	01
Material ID:	379128
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

950
NE
1/4-1/2
0.264 mi.
1396 ft.

ELK INVESTOR - COMMERCIAL BUILDING **NY LTANKS S103517586**
400 WEST 25TH ST **NY AST N/A**
MANHATTAN, NY

Relative:
Higher

Actual:
20 ft.

LTANKS:

Name:	ELK INVESTOR - COMMERCIAL BUILDING
Address:	400 WEST 25TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	1812190 / 2019-08-22
Facility ID:	1812190
Site ID:	584153
Spill Date:	2019-03-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	PXLAKHAN
Referred To:	Not reported
Reported to Dept:	2019-03-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2019-03-12
Spill Record Last Update:	2019-08-22
Spiller Name:	Not reported
Spiller Company:	ELK INVESTOR
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	TODD

ELK INVESTOR - COMMERCIAL BUILDING (Continued) **S103517586**

Spiller Phone:	(646) 296-6795
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	536578
DEC Memo:	"3/12/19 - Obligado - Desk Duty - Called Riteway. Left message. 3/13/19 - Obligado - Tank test was performed after a tank cleaning. Not holding pressure. The tank had a hole on the tank of the tank. A temp tank has been set up. TTF Letter Sent. 03/20/19 - Lakhani Riteway Paul informed that the 3000 gallons AST was emptied. Contaminated debris surrounds the tank. A proposal is being sent to the owner. 07/10/19 - Lakhani DEC Lakhani inspected the tank on 05/17/19 and required Riteway to install four (4) boring in the tank room: one (1) in each corner of the tank. Borings should extend to either groundwater, bedrock or the first depth where no further impact is noticed; whichever comes first. Samples should be collected and analyzed. On 07/09/19, Paul informed that the tank has been removed. 07/11/19 - Lakhani Sample results: 1,2,4-trimethylbenzene 4600 ppb(sample 1). DEC Lakhani inspected the site on 07/10/19. The tank was removed. Four (4) test pits were dug using a hand auger. Results from the samples collected in each corner of the tank room. The sample collected from the southwest corner showed a few minor hits slightly above UUSCOs. Due to the proximity of foundation of the building, DEC Lakhani authorized backfill. Riteway will complete the concrete slab and encapsulate. 08/22/19 - Lakhani The slab was restored in the tank room. The spill has been addressed. Spill is closed."
Remarks:	"cleanup pending"

All Materials:

Site ID:	584153
Operable Unit ID:	1331820
Operable Unit:	01
Material ID:	2341042
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	400 WEST 25TH STREET
Address:	400 WEST 25TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9310011 / 1993-11-17
Facility ID:	9310011
Site ID:	300724
Spill Date:	1993-11-17
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1993-11-17
SWIS:	3101
Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	1993-11-17

ELK INVESTOR - COMMERCIAL BUILDING (Continued) **S103517586**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-11-18
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	243240
DEC Memo:	""
Remarks:	"POSSIBLE GAGE CONTAINED ON SIDEWALK - DRIVER APPLIED SORBENT - P/U."

All Materials:

Site ID:	300724
Operable Unit ID:	991716
Operable Unit:	01
Material ID:	392649
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AST:

Name:	ELK 400 W 25TH LLC
Address:	400 WEST 25TH STREET
City,State,Zip:	NEW YORK, NY 10001
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-252107
Program Type:	PBS
UTM X:	584356.85107
UTM Y:	4511245.05122
Expiration Date:	09/19/2024
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	10145
Affiliation Type:	Emergency Contact
Company Name:	ELK 400 WEST 25TH LLC
Contact Type:	Not reported
Contact Name:	TODD WITTENSTEIN
Address1:	Not reported

ELK INVESTOR - COMMERCIAL BUILDING (Continued) **S103517586**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 296-6795
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2021-10-20

Site Id:	10145
Affiliation Type:	Facility Owner
Company Name:	ELK 400 WEST 25TH LLC
Contact Type:	PARTNER
Contact Name:	TODD WITTENSTEIN
Address1:	489 5TH AVE., 8TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(646) 296-6795
EMail:	TODD@ELKINVESTORS.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2021-10-20

Site Id:	10145
Affiliation Type:	Mail Contact
Company Name:	ELK 400 WEST 25TH LLC
Contact Type:	PARTNER
Contact Name:	TODD WITTENSTEIN
Address1:	489 5TH AVE., 8TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(646) 296-6795
EMail:	TODD@ELKINVESTORS.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2021-10-20

Site Id:	10145
Affiliation Type:	Facility Operator
Company Name:	ELK 400 W 25TH LLC
Contact Type:	Not reported
Contact Name:	ELK 400 W. 25TH LLC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 296-6795

ELK INVESTOR - COMMERCIAL BUILDING (Continued) **S103517586**

EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2021-10-20

Tank Info:

Tank Number: 001
Tank Id: 11818
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1979
Capacity Gallons: 2500
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 07/08/2020
Register: True
Modified By: DAFRANCI
Last Modified: 10/20/2021
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 002
Tank Id: 290846

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
J05 - Dispenser - On Site Heating System (Supply/Return)
E02 - Piping Secondary Containment - Vault (with Access)
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

ELK INVESTOR - COMMERCIAL BUILDING (Continued) **S103517586**

	H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
	L00 - Piping Leak Detection - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	07/27/2020
Capacity Gallons:	2500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DAFRANCI
Last Modified:	10/20/2021
Material Name:	#2 fuel oil (on-site consumption)

BY951 **APARTMENT COMPLEX** **NY LTANKS** **S106703797**
SSE **238 WEST 14TH STREET** **N/A**
1/4-1/2 **NEW YORK, NY**
0.267 mi.
1409 ft. **Site 1 of 3 in cluster BY**

Relative: **Higher**

Actual: **24 ft.**

LTANKS:

Name:	APARTMENT COMPLEX
Address:	238 WEST 14TH STREET
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	9610832 / 1996-12-02
Facility ID:	9610832
Site ID:	239500
Spill Date:	1996-12-02
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1996-12-02
CID:	282
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-02
Spill Record Last Update:	2003-06-18
Spiller Name:	MR CLARE
Spiller Company:	TS TRUCKING INC+CASTLE OI
Spiller Address:	53 SECOND AVE
Spiller County:	001
Spiller Contact:	N/A
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2

APARTMENT COMPLEX (Continued) **S106703797**

DER Facility ID: 196983
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks: "THE PERSON FROM CASTLE OIL WHO WAS ON THE SCENE TOLD HIS DRIVER TO PUMP THE OIL INTO THE TANK MR CLARE STATED.THE TANK HAD A CRACK IN THE SEAM.CASTLE OIL ADDRESS IS 290 LOCUST AVE BRONX NY 10454 OIL WAS CLEANED UP.MANS NAME FROM CASTLE OIL IS NOT AVAILABLE JAMES CAREY IS IN HCHARGE OF CASTLE OIL-718-579-3414"

All Materials:
Site ID: 239500
Operable Unit ID: 1042217
Operable Unit: 01
Material ID: 343051
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 20.00
Units: G
Recovered: 20.00
Oxygenate: Not reported

BN952 **555 WEST 22ND STREET** **NY BROWNFIELDS** **S118950495**
NNW **555 WEST 22ND STREET** **N/A**
1/4-1/2 **NEW YORK, NY 10011**
0.267 mi.
1411 ft. **Site 3 of 3 in cluster BN**

Relative: **Lower**
Actual: **6 ft.**

BROWNFIELDS:
Name: 555 WEST 22ND STREET
Address: 555 WEST 22ND STREET
City,State,Zip: NEW YORK, NY 10011
Program: BCP
Site Code: 525716
Acres: 0.778
HW Code: C231101
SWIS: 3101
Town: New York City
Record Added Date: 04/13/2016
Record Updated Date: 03/16/2021
Update By: HMDUDEK
Site Description: "Location: The site is located in a mixed-use area of the West Chelsea section of the Borough of Manhattan. The site is comprised of five tax lots (approx. 33,671 SF) identified on New York City tax maps as Block 694, Lots 2, 5, 60, 61 and 65. The site is bounded to the north by West 23rd Street, to the east by 10th Avenue, to the south by West 22nd Street, and to the west by 11th Avenue. Lots 5, 60, 61, and 65 were accepted into the Brownfield Cleanup Program on August 4, 2016 (BCA #C231101). The BCA was amended on October 27, 2017 to also include Lot 2. Site Features: Currently a multi-tenant high-rise residential apartment building with ground floor commercial space is under construction. Current Zoning and Land Use: The site is currently zoned C6-3A, C6-3 and M (Commercial, Mixed Buildings and Manufacturing), which allows for residential use. Lots 5, 60, 61, and 65 are currently operating as an active U-Haul facility. Lot 2 is currently vacant. Adjacent properties include mixed use

555 WEST 22ND STREET (Continued) **S118950495**

commercial/residential to the north, industrial/manufacturing and commercial/residential to the east, office space and commercial/residential to the south and the West Side Highway to the west. Past Use of the Site: Historic site uses included: lumber yard, iron works, garage, automotive repair services, and storage and dispensing of petroleum products. It is unknown whether U-Haul continued to dispense gasoline after taking title to the property in the late 1970s/early 1980s. Currently, no vehicle repair or fueling takes place onsite. Prior use of the site for petroleum storage and fueling appear to have historically impacted both soil and groundwater. Three historic spills where noted to be associated with the site, all historic spills have been closed out. A recent spill was reported adjacent to the site, (northeast) in a sidewalk area, this spill is currently open. Site Geology and Hydrogeology: The site incorporates approximately 0.77 acres of fairly level land situated in the City of New York, New York County, New York. The site is mapped on the Jersey City, NY-NJ Quadrant 7.5 Minute Topographic Map, published by the United States Geological Survey (USGS). Review of the topographic map indicates that the site is located approximately 7 feet above sea level (NAVD 88). The site subsurface consists of an approximate 8-9 foot thick layer of historic fill material, followed by sand and gravel deposits. Depth to water is approximately 8-9 feet below ground (ftbg). Based on the proximity to the Hudson River, groundwater is expected to flow to the west. The site is located in FEMA flood zone AE, also known as the 100-year floodplain. "

Env Problem: "Remediation at the site is complete. Prior to remediation the contaminants of concern included certain metals, volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs). Remedial actions have successfully achieved the restricted residential soil cleanup objectives, which allow for the site s residential and commercial use. Endpoint samples collected and analyzed across the site confirmed the success of the remedial action. The site requires an institutional control, in the form of an environmental easement, and engineering controls in the form of a soil cover system. A Site Management Plan (SMP) was completed to manage remaining contamination at the site and includes an Institutional and Engineering Control Plan that identifies all use restrictions and engineering controls for the site and details and steps and media-specific requirements necessary to ensure these controls remain in place and effective."

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2016-08-08 12:49:00
Record Upd: 2019-05-29 09:37:00
Updated By: GWBURKE
Own Op: Document Repository
Sub Type: NNN

555 WEST 22ND STREET (Continued) **S118950495**

Owner Name:	Not reported
Owner Company:	Manhattan Community Board Four
Owner Address:	330 West 42nd Street, 26th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10036
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	andrew orchulli
Owner Company:	22nd and 11th associates, l.l.c
Owner Address:	60 Columbus Circle
Owner Addr2:	c/o the related companies, l.p.
Owner City,St,Zip:	new york, NY 10023
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Andrew Orchulli
Owner Company:	22nd and 11th Associates, L.L.C.
Owner Address:	30 Hudson Yards
Owner Addr2:	c/o The Related Companies, L.P
Owner City,St,Zip:	New York, NY 10001
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New York Public Library - Muhlenberg Branch
Owner Address:	209 West 23rd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10011
Owner Country:	United States of America
HW Code:	C231101
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231101
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231101
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231101
Waste Type:	fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231101
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231101
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231101
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN

555 WEST 22ND STREET (Continued) **S118950495**

Waste Code:	Not reported
HW Code:	C231101
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231101
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231101
Waste Type:	benzo[k]fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231101
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231101
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2-084069
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2019-11-06 13:47:00
Record Updated:	2019-11-06 13:47:00
Updated By:	LXZIELIN
Crossref ID:	C231101-07-16
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2019-11-14 11:28:00
Record Updated:	2019-11-14 11:28:00
Updated By:	NTFREEMA
Crossref ID:	2019000355452
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2019-11-14 14:26:00
Record Updated:	2019-11-14 14:26:00
Updated By:	NTFREEMA
Crossref ID:	9700188
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2016-04-14 10:02:00
Record Updated:	2016-04-14 10:02:00
Updated By:	BXANDERS
Crossref ID:	9000199
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2016-04-14 10:02:00
Record Updated:	2016-04-14 10:02:00
Updated By:	BXANDERS
Crossref ID:	0205608
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2016-04-14 10:02:00
Record Updated:	2016-04-14 10:02:00
Updated By:	BXANDERS

BW953 **507 WEST 24TH STREET** **NY VCP** **S118943187**
North **507 WEST 24TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.270 mi.
1425 ft. **Site 7 of 8 in cluster BW**

Relative: **Lower**
Actual: **12 ft.**

VCP NYC:

Project ID:	09TMP0109M,09EH-N109M,12CVCP047M
Name:	507 WEST 24TH STREET
Address:	507 WEST 24TH STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Manhattan
BBL:	1006960028
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.748562
Longitude:	-74.004154
Postcode:	4
Community Board:	3
Council District:	99
Census Tract:	1090214
BIN:	1006960028
NTA:	Hudson Yards-Chelsea-Flatiron-Union Square

BS954 **VACANT LOT** **NY LTANKS** **S106868700**
North **511 WEST 24TH STREET** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.277 mi.
1461 ft. **Site 7 of 7 in cluster BS**

Relative: **Lower**
Actual: **11 ft.**

LTANKS:

Name:	VACANT LOT
Address:	511 WEST 24TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0412228 / 2005-03-16
Facility ID:	0412228
Site ID:	337632
Spill Date:	2005-02-16
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2005-02-16
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-02-16
Spill Record Last Update:	2005-03-16
Spiller Name:	TIM SIMMONS
Spiller Company:	VACANT LOT
Spiller Address:	511 WEST 24TH STREET
Spiller County:	001

VACANT LOT (Continued) **S106868700**

Spiller Contact:	TIM SIMMONS
Spiller Phone:	(917) 353-7604
Spiller Extention:	CELL
DEC Region:	2
DER Facility ID:	272958
DEC Memo:	"Sangesland spoke with Roux Assoc. Tank excavation with some spillage around tanks. (Tanks had been previously abandoned in place). Now tanks are being pulled. Sangesland asked for several end point soil samples taken from tank grave after removal. Test for VOC & SVOC. 3/16/2005 Sangesland reviewed a report from Roux Assoc. dated 3/9/05 On 2/18/05 Roux collected 6 post-ex samples. One per each side & 2 bottom VOC's - All samples contained low levels of VOC's, but they were ALL BELOW RSCO Stds. SVOC's - Some minor Hits on PAHs consistant with historical fill levels. Results show some contaminants exceed regulatory standards. Samples taken on removed (waste) soils showed much higher VOC & SVOC levels. Roux conclusion says that the contamination source has been removed and the site should be closed out. Based on the soil sampling work performed on the site and the report prepared by Roux Assoc., the NYSDEC agrees with the conclusion and the spill case is closed with: No Further Action - Does Not Meet Standards "
Remarks:	"REMOVING TANK, JUST AN ODOR IN THE SOIL: NOT SURE HOW TO MOVE FORWARD WITH PROJECT:"

All Materials:

Site ID:	337632
Operable Unit ID:	1099574
Operable Unit:	01
Material ID:	579908
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BZ955 **CON EDISON** **NY LTANKS S104516339**
SSE **2 HORATIO ST** **NY MANIFEST N/A**
1/4-1/2 **NEW YORK, NY 10014**
0.279 mi.
1471 ft. **Site 1 of 3 in cluster BZ**

Relative: **Higher**
Actual: **23 ft.**

LTANKS:

Name:	RESIDENCE
Address:	2 HORATIO ST
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	9912024 / 2000-02-08
Facility ID:	9912024
Site ID:	152651
Spill Date:	2000-01-18
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101

CON EDISON (Continued) **S104516339**

Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	2000-01-18
CID:	371
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-01-18
Spill Record Last Update:	2000-02-08
Spiller Name:	CALLER
Spiller Company:	MYSTIC
Spiller Address:	1901 STEINWAY ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	284419
DEC Memo:	""
Remarks:	"SUPER TOLD DRIVER TO FILL WRONG TANK, CAUSING OVERFILL -- CLEAN UP IN PROGRESS AND EXPECTED TO BE COMPLETE."

All Materials:

Site ID:	152651
Operable Unit ID:	1086566
Operable Unit:	01
Material ID:	293911
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Oxygenate:	Not reported

NY MANIFEST:

Name:	CON EDISON
Address:	2 HORATIO ST
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYP004857272
Facility Status:	Not reported
Location Address 1:	2 HORATIO ST
Code:	BP
Location Address 2:	SB 36930
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

CON EDISON (Continued) **S104516339**

NY MANIFEST:

EPAID:	NYP004857272
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/21/2015
Trans1 Recv Date:	10/21/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/21/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004857272
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014087607JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S104516339**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

BZ956 **2 HORATIO ST** **NY LTANKS** **S102673382**
SSE **2 HORATIO ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.279 mi.
1471 ft. **Site 2 of 3 in cluster BZ**

Relative:
Higher

Actual:
23 ft.

LTANKS:

Name:	2 HORATIO ST
Address:	2 HORATIO ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9601839 / 1996-05-09
Facility ID:	9601839
Site ID:	152650
Spill Date:	1996-05-07
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	KATZ
Referred To:	Not reported
Reported to Dept:	1996-05-07
CID:	312
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-05-07
Spill Record Last Update:	1996-05-28
Spiller Name:	Not reported
Spiller Company:	HESS OIL
Spiller Address:	420 HOOK RD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(212) 243-6878
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	129568
DEC Memo:	""
Remarks:	"caller states that it was the bldg owners fault for giving the driver the wrong reading - however it was the driver who overfilled the tank - oil came out of the vent pipe - going to be cleaned up"

All Materials:

Site ID:	152650
Operable Unit ID:	1029477
Operable Unit:	01
Material ID:	351640

2 HORATIO ST (Continued) **S102673382**

Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

CA957 **555 WEST 23RD ST** **NY LTANKS** **S105999938**
NNW **555 WEST 23RD ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.279 mi.
1472 ft. **Site 1 of 3 in cluster CA**

Relative: **Lower**

Actual: **9 ft.**

LTANKS:

Name:	555 WEST 23RD ST
Address:	555 WEST 23RD ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0306399 / 2006-04-07
Facility ID:	0306399
Site ID:	203961
Spill Date:	2003-09-17
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SKCARLSO
Referred To:	NFA (4/7/06)
Reported to Dept:	2003-09-17
CID:	297
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-09-17
Spill Record Last Update:	2006-04-07
Spiller Name:	Not reported
Spiller Company:	LAVIGNE BUILDERS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	CURT SCHMIDT
Spiller Phone:	(212) 675-3225
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	296101
DEC Memo:	"Sangesland sent contaminated soil letter Curt Schmidt said that Mark Tibbe knows about a major spill site just upgradient from this site. 2/5/03 - TRANSFERRED FROM SAWYER TO ROMMEL 3/1/04 Reassigned from Rommel to K Foley. Spill Remediation Plan received 12/22/03 for removal of four 260gal gas USTs, one 500gal gas UST, and one 500gal no. 2 fuel oil UST. Site under development but once contained three buildings. A former auto service and plastic manufacturing existed on

555 WEST 23RD ST (Continued) **S105999938**

site. Five USTs from NW corner were removed 9/29/03 (four 260gal gas USTs and one 500gal gas UST). Soil excavation was postponed due to safety concerns. Will excavate and direct load for disposal. A minimum of four post-ex samples will be collected at PID hot spots on each sidewall. DTW is 6'bgs and therefore a bottom sample will probably not be feasible. If there is potential for structural damage to the adjacent building, two soil samples will be collected from that sidewall. Two samples will be collected from sidewalls greater than 20' in length. Analysis by VOCs (8021) and SVOCs (8270). Spill #9704542 was previously reported for a fuel oil release from UST. Scaled site map with former tank locations/hot spots and Phase I and II reports. There have been site investigations and proposed remediation plans submitted for 543-547 West 23rd St (spill #8605848). There is documented fuel oil and gasoline contamination of groundwater associated with sites to the east that have encroached upon the site. Mendon Leasing, 527 W 23rd file(#9605688,9808740,9511782, 9513588). 3/22/06 Reassigned from Foley to Tang. (KMF) 4/3/06: Reassigned to Andersen. Three sources of contamination: Fuel oil leak from a UST in northeast corner. Gasoline leak from five USTs in northwest corner. Gasoline groundwater contamination from adjacent Mendon Leasing site. All six tanks were removed by Fleming Lee Shue (FLS). The tank closure report was not received. Spoke with FLS and they will resend a report that was sent to Albany. 4/7/06: Received and reviewed tank closure report. Soil was excavated from three areas of contamination. Residual SVOC contamination from urban fill and VOC contamination from the adjacent spill site is present. The site will be redeveloped with a vapor barrier. NFA letter sent. "

Remarks: "CALLERS COMPANY PERFORMING EXCAVATIONS ON SITE, AND SOIL SAMPLES ARE SHOWING GASOLINE CONTAMINATION OF THE SOIL AROUND SOME UNDERGROUND TANK SITES ON THE PROPERTY"

All Materials:

Site ID:	203961
Operable Unit ID:	875124
Operable Unit:	01
Material ID:	503624
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BR958 **CHELSEA HOUSES -NYCHA** **NY LTANKS S103478255**
NNE **431 WEST 25TH ST** **NY Spills N/A**
1/4-1/2 **MANHATTAN, NY**
0.279 mi.
1475 ft. **Site 3 of 3 in cluster BR**

Relative: **Higher**

Actual: **16 ft.**

LTANKS:

Name:	CHELSEA HOUSES -NYCHA
Address:	431 WEST 25TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9806339 / 2013-08-27

CHELSEA HOUSES -NYCHA (Continued) **S103478255**

Facility ID:	9806339
Site ID:	158080
Spill Date:	1998-08-21
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	jkkann
Referred To:	Not reported
Reported to Dept:	1998-08-21
CID:	312
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-08-21
Spill Record Last Update:	2013-08-27
Spiller Name:	FRANK OCELLO
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller County:	001
Spiller Contact:	FRANK OCELLO
Spiller Phone:	(212) 306-3229
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	70246
DEC Memo:	"12/06/05: This spill transferred from J.Kolleeny to S.Kraszewski. 02/06/06: This spill transferred from S.Kraszewski to Q.Abidi. 03/17/06: SK Reviewed Site Assessment Report completed on Nov. 30, 2000 by State Environmental Services, Inc. One 30K tank, which stored #2 Fuel Oil was removed. Six post-excavation samples were taken from the pit and submitted for laboratory analysis. About 900 tons of soil was removed and disposed of. All soil samples were tested for VOCs and SVOCs. None of the samples detected any VOC contaminants. All samples recorded exceedances of the same SVOC compounds: Benzo(a)anthracene, Benzo(b)fluoranthene, Benzo(k)fluoranthene, Benzo(g,h,i)perylene, Chrysene, Dibenzo(a,h)anthracene. The concentrations ranged from 1950 ppb to 498 ppb, which are relatively low. Four of the six samples had SVOC exceedance concentrations of 1000 ppb or less. No samples were taken from the fill lines or fill port. Report lacks a site plan with area of excavation and sample locations. No lab analysis summary table provided either. SK spoke with Chris Sawyer from NYCHA Fuel Oil Remediation. I informed him that they would need to take soil samples from the former fill lines and fill port area. Chris said that Harborview Houses would be included when performed additional soil borings. Sent Chris Email requesting additional soil borings along the fuel lines and next to the fill port. - SK 04/04/06: This spill Transferred from Q. Abidi to Koon Tang. 07/03/09: J.kann - spill transferred to J.Kann. Site assessment report submitted on 2/5/07. Investigative work plan submitted in March 2009. Additional wells to be installed to evaluate groundwater at the site, which is acceptable. One comment was sent on 7/3/09 to GF - A second round of groundwater sampling is proposed one

CHELSEA HOUSES -NYCHA (Continued) **S103478255**

month after the initial sampling is performed. What is the reasoning behind this? Typically two or more months is used. 09/15/09: J.kann - Sampling to be performed two months after initial sampling. Work Plan approved via email on 7/6/09. 2/4/11: J.kann - SAR received on 12/3/10 and edoced. 5/24/12: J.Kann - SAR under review. NYCHA requests closure. Will review entire file for Chelsea Houses. 6/13/12: J.kann - requested in an email of 5/30 that NYCHA gauge the wells at the site before I present to the closure panel. NYCHA sent well gauging data and photo on 6/12 indicating that a product sheen is present in MW5. A response email was sent to NYCHA on 6/13. 10/17/12: J.Kann - requested a follow-up from NYCHA regarding whether or not there is measurable product in MW-5 and/or if a absorbent sock is still present. 5/17/13: J.kann - followed up with NYCHA. They will go out and gauge MW-5 the weeek of May 20. 8/26/13: J.Kann - visited site on July 31st. Observed the removal of sock and gauging of on site wells. No product in all wells. Sock visibly clean (photo). NYCHA indicated that the sock has been clean for several months. Based on observations, the spill will be considered for closure. 8/27/13 J.Kann - completed review of file. Spill closed. Following summarizes site: -30,000 gallon UST removed in 8/2000. -890 tons of contaminated soils removed in 2000 -investigation done in 2006 along fill lines and by fill port (DEC request) -some PAHs detected in grab groundwater sample in 2006 -5 permanent wells installed in 2010 -All gw under TOGS with the exception of MW-5 (3 minor VOC compound exceedences) -Slight sheen subsequently detected in MW-5. Absorbant sock placed in well. -Minor impacts on sock in 2012. -No oil detect on absorbant sock in 2013. -Confirmed no product sheen in well during site visit of 7/31/13. NFA. Email sent to NYCHA on 8/27/13 requesting wells be decommissioned."

Remarks: "will isolate and retest"

All TTF:

Facility ID:	9806339
Spill Number:	9806339
Spill Tank Test:	1546182
Site ID:	158080
Tank Number:	001
Tank Size:	30000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	158080
Operable Unit ID:	1067520
Operable Unit:	01
Material ID:	317502
Material Code:	0001A
Material Name:	#2 fuel oil

CHELSEA HOUSES -NYCHA (Continued) **S103478255**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	CHELSEA HOUSES -NYCHA
Address:	431 WEST 25TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9812239 / 2003-03-25
Facility ID:	9812239
Facility Type:	ER
DER Facility ID:	70246
Site ID:	74958
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	1999-01-04
Investigator:	SACCACIO
Referred To:	Not reported
Reported to Dept:	1999-01-04
CID:	252
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-04
Spill Record Last Update:	2005-01-06
Spiller Name:	ED MALONE
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller Company:	001
Contact Name:	ED MALONE
DEC Memo:	""
Remarks:	"APPROX 100 GAL SPILLED, WHICH HAS BEEN CONTAINED IN THE BOILER ROOM - SPILL CREW ON-SITE FOR CLEAN UP."

All Materials:

Site ID:	74958
Operable Unit ID:	1072834
Operable Unit:	01
Material ID:	312518
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G

CHELSEA HOUSES -NYCHA (Continued) **S103478255**

Recovered: .00
Oxygenate: Not reported

BY959 **APARTMENT BUILDING** **NY LTANKS** **S103558174**
SSE **241 WEST 13TH STREET** **N/A**
1/4-1/2 **NEW YORK, NY**
0.284 mi.
1497 ft. **Site 2 of 3 in cluster BY**

Relative:
Higher

Actual:
24 ft.

LTANKS:

Name:	APARTMENT BUILDING
Address:	241 WEST 13TH STREET
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	9809486 / 2005-06-14
Facility ID:	9809486
Site ID:	84573
Spill Date:	1998-10-28
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	KPSARNOW
Referred To:	Not reported
Reported to Dept:	1998-10-28
CID:	282
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-10-28
Spill Record Last Update:	2005-06-14
Spiller Name:	MEAYOR BOUSKILA
Spiller Company:	WIENERS REALTORS
Spiller Address:	110 PLAZA SUITE 4000
Spiller County:	001
Spiller Contact:	WIENER REALTORS
Spiller Phone:	(212) 564-2111
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	77773
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was M TIBBE Tank only test passed. Replaced fill and vent. will ask for soil sample 8021 & 8270 under fill line. Steve Vartikias = 410-528-5960. Spill Closed on 6/14/05. Spilled was called in because of a failed tank test. The filed was reviewed and the tank was retested and passed the pressure test."
Remarks:	"TANK FAILED THE TEST. "

All TTF:

Facility ID:	9809486
Spill Number:	9809486
Spill Tank Test:	1546463
Site ID:	84573

APARTMENT BUILDING (Continued) **S103558174**

Tank Number:	1
Tank Size:	3000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	84573
Operable Unit ID:	1066756
Operable Unit:	01
Material ID:	316938
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CA960 **UHAUL INC** **NY LTANKS** **S104275573**
NNW **562 WEST 23RD ST** **NY Spills** **N/A**
1/4-1/2 **NEW YORK, NY**
0.286 mi.
1512 ft. **Site 2 of 3 in cluster CA**

Relative:
Lower

Actual:
7 ft.

LTANKS:

Name:	562 W 23RD ST/MANHATTAN
Address:	562 WEST 23RD STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9000199 / 2000-06-21
Facility ID:	9000199
Site ID:	313585
Spill Date:	1990-03-26
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1990-04-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False

UHAUL INC (Continued) **S104275573**

UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1990-05-10
Spill Record Last Update:	2000-06-21
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	284706
DEC Memo:	""
Remarks:	"TANK FAILED AIR PRESSURE TEST."

All Materials:

Site ID:	313585
Operable Unit ID:	938542
Operable Unit:	01
Material ID:	438608
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	UHAUL INC
Address:	562 WEST 23RD ST
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0205608 / 2002-12-10
Facility ID:	0205608
Site ID:	149950
Spill Date:	2002-08-27
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2002-08-28
CID:	405
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-08-28
Spill Record Last Update:	2002-12-10
Spiller Name:	Not reported
Spiller Company:	UHAUL INC

UHAUL INC (Continued) **S104275573**

Spiller Address:	562 WEST 23RD ST
Spiller County:	001
Spiller Contact:	LEVENT ESKICAKIT
Spiller Phone:	(212) 353-8280
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	127520
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE/SANGESLAND 12/10/2002 Sangesland reviewed a report prepared by David Winslow of ATC Associates Inc (212-353-8280). Report states that contamination was found around a buried 1000 gal tank under the floor of the building. The tank was cleaned out and excavated around. Because of foundation issues, the tank could not be removed and not all of the contaminated soil could be removed. Based on the soil conditions, Sangesland requested goundwater samples from the area. ATC took four groundwater samples in the area of this tank. GW is at approx 8 ft below the cement floor level. 3 of 4 samples are clean. One has some VOC hits just over 8020. Based on the location and the inability to excavate further, and that the surrounding water samples were clean, we can conclude that the contamination is localized and not spreading. Spill closed "
Remarks:	"CALLER STATES UPON REMOVAL OF THE UNDERGROUND TANK - FOUND HOLES IN THE TANK AND CONTAMINATED SOIL"

All Materials:

Site ID:	149950
Operable Unit ID:	858216
Operable Unit:	01
Material ID:	519806
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	562 WEST 23RD STREET
Address:	562 WEST 23RD STREET
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	9305627 / 1993-08-06
Facility ID:	9305627
Facility Type:	ER
DER Facility ID:	274954
Site ID:	313586
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C4
SWIS:	3101
Spill Date:	1993-08-05
Investigator:	GRIFFIN
Referred To:	Not reported
Reported to Dept:	1993-08-05
CID:	Not reported

UHAUL INC (Continued) **S104275573**

Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	1993-08-06
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-08-09
Spill Record Last Update:	1996-10-25
Spiller Name:	Not reported
Spiller Company:	ED VILLAVICENCIO
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"TO DO CLEAN UP CALLED TONE TIGHT CO. FOR REMOVAL GOING TO CLEAN-UP PARKING LOT UNDER AIR CONDITIONER AS WEL AS SIDE WALK."

All Materials:

Site ID:	313586
Operable Unit ID:	983781
Operable Unit:	01
Material ID:	395538
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	55.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BW961 **500 WEST 25TH STREET** **NY VCP** **S121133132**
North **500 WEST 25TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.287 mi.
1514 ft. **Site 8 of 8 in cluster BW**

Relative:
Lower

Actual:
13 ft.

VCP NYC:

Project ID:	16TMP0350M,16EH-N257M,17CVCP047M
Name:	500 WEST 25TH STREET
Address:	500 WEST 25TH STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Manhattan
BBL:	1.00696003710069E+19
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed
Latitude:	40.749002
Longitude:	-74.003328
Postcode:	4
Community Board:	3
Council District:	99
Census Tract:	1000000
BIN:	1006960038
NTA:	Hudson Yards-Chelsea-Flatiron-Union Square

BY962 **229 WEST 14TH STREET** **NY LTANKS** **S110490709**
SSE **229 WEST 14TH STREET** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.288 mi.
1519 ft. **Site 3 of 3 in cluster BY**

Relative: **Higher**

Actual: **25 ft.**

LTANKS:

Name:	229 WEST 14TH STREET
Address:	229 WEST 14TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9312989 / 1994-02-03
Facility ID:	9312989
Site ID:	229780
Spill Date:	1994-02-03
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C4
Cleanup Ceased:	1994-02-03
SWIS:	3101
Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	1994-02-03
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-02-04
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	CASTLE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	189394
DEC Memo:	""
Remarks:	"SPILL CONTAINED ON SIDE WALK - CASTLE TO DO CLEAN UP -"

All Materials:

Site ID:	229780
Operable Unit ID:	991476
Operable Unit:	01
Material ID:	388391
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	229 WEST 14TH STREET

229 WEST 14TH STREET (Continued) **S110490709**

Address:	229 WEST 14TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9801147 / 2005-07-08
Facility ID:	9801147
Site ID:	229781
Spill Date:	1998-04-20
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	1998-04-27
CID:	266
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-04-27
Spill Record Last Update:	2005-07-08
Spiller Name:	FATHER PETER
Spiller Company:	OUR LADY OF GUADALUPE CHU
Spiller Address:	229 WEST 14TH STREET
Spiller County:	001
Spiller Contact:	FATHER PETER
Spiller Phone:	(212) 243-5317
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	189394
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 3/11/03 - SAMUEL- File available in active unassigned spill files. 3/3/05 - Austin - Reassigned to Rahman 06/08/05-SR// A letter was sent to the attn of Father Kevin Nelan , same address. 07/08/05-SR// Received Tank Test Pass documents. Tank was tested 0n 5/10/00 and 5/10/05. At both the tests, tank passed.No contamination observed during the process. "
Remarks:	"FURTHER ACTION TO FOLLOW. "

All TTF:

Facility ID:	9801147
Spill Number:	9801147
Spill Tank Test:	1545826
Site ID:	229781
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F

229 WEST 14TH STREET (Continued) **S110490709**

Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 229781
Operable Unit ID: 1058619
Operable Unit: 01
Material ID: 323090
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: CHURCH
Address: 229 WEST 14TH ST
City,State,Zip: MANHATTAN, NY
Spill Number/Closed Date: 1002102 / 2010-07-28
Facility ID: 1002102
Site ID: 435201
Spill Date: 2010-05-24
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Not reported
Cleanup Ceased: Not reported
SWIS: 3101
Investigator: BKFALVEY
Referred To: Not reported
Reported to Dept: 2010-05-24
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2010-05-24
Spill Record Last Update: 2010-07-28
Spiller Name: JAMES WILSON
Spiller Company: OUR LADY OF GUADALUPE
Spiller Address: 229 WEST 14TH ST
Spiller County: 999
Spiller Contact: JAMES WILSON
Spiller Phone: (845) 348-6355
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 390097
DEC Memo: "05/27/10 TTF sent to Church of Our Lady Guadalupe 229 West 14th Street New York, NY 10011(sr) 7/28/10 On 7/26/10, received letter and tank test report from James Wilson of RND Services. Two sets of piping found when tank was uncovered. Product lines were replaced and old lines never plugged and/or removed. Permanent plugs installed in

229 WEST 14TH STREET (Continued) **S110490709**

Remarks: old product lines. Tank passed tightness test on 7/8/10. bf " "Caller reporting tank test failure."

All Materials:

Site ID:	435201
Operable Unit ID:	1185991
Operable Unit:	01
Material ID:	2180758
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

CB963 **168-11 12TH AVENUE** **NY LTANKS** **S104275514**
NNW **168-11 12TH AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.289 mi.
1525 ft. **Site 1 of 3 in cluster CB**

Relative: **Lower**
Actual: **6 ft.**

LTANKS:

Name:	168-11 12TH AVENUE
Address:	168-11 12TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8803037 / 1992-09-30
Facility ID:	8803037
Site ID:	212375
Spill Date:	1988-07-07
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1992-09-30
SWIS:	4101
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1988-07-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-07-08
Spill Record Last Update:	2003-10-15
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2

168-11 12TH AVENUE (Continued) **S104275514**

DER Facility ID: 175986
DEC Memo: ""
Remarks: "3K TANK, NEVER STABILIZED, INITIAL SYSTEM HORNER-EZY CHECK TEST."

All TTF:
Facility ID: 8803037
Spill Number: 8803037
Spill Tank Test: 1534245
Site ID: 212375
Tank Number: Not reported
Tank Size: 0
Material: 0002
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 212375
Operable Unit ID: 918226
Operable Unit: 01
Material ID: 458601
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: G
Recovered: .00
Oxygenate: Not reported

CC964 **COMMERCIAL TTF** **NY LTANKS S103576014**
South **61 JANE AVE** **NY Spills N/A**
1/4-1/2 **MANHATTAN, NY**
0.296 mi.
1561 ft. **Site 1 of 3 in cluster CC**

Relative: **Higher**
Actual: **17 ft.**

LTANKS:
Name: COMMERCIAL TTF
Address: 61 JANE AVE
City,State,Zip: MANHATTAN, NY
Spill Number/Closed Date: 1504935 / 2015-10-13
Facility ID: 1504935
Site ID: 511290
Spill Date: 2015-08-06
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 3101
Investigator: SXMAHAT

COMMERCIAL TTF (Continued) **S103576014**

Referred To:	Not reported
Reported to Dept:	2015-08-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-08-06
Spill Record Last Update:	2015-10-28
Spiller Name:	Not reported
Spiller Company:	PROPERTY OWNER
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	ISRAEL
Spiller Phone:	9176003268
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	465849
DEC Memo:	"8/7/15: Mahat PBS : 2-217808 [crossed referenced] Mailing Address: 61 JANE STREET TENANTS CORP. 217 BROADWAY- SUITE 309 NEW YORK, NY 10007 ATTN: ARLINE KOB DEC Mahat talked to Uden @ 212.255.0570 and left a phone message to pass along the management. DEC is waiting for the response. A TTF Letter has been sent out and it has been uploaded on D2 for reference. 9/28/15: Mahat DEC Mahat left a voice message to Sal @ 212.684.8282 requesting a call back with updated information on the spill case. 10/13/15: Mahat e/c: DEC Mahat received a closure report on the case. The report include repair that was performed and passing pressure test. The report is uploaded on D2 for reference. Based on the report, the Department does not warrant any further investigation on the spill case. Spill case is closed in DEC Spill Database. "
Remarks:	"tank is empty, failed test. Converting from 6 to 2."

All Materials:

Site ID:	511290
Operable Unit ID:	1260553
Operable Unit:	01
Material ID:	2263953
Material Code:	0000
Material Name:	empty
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Name:	OFFICE BUILDING
Address:	61 JANE STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9812196 / 2003-03-03
Facility ID:	9812196

COMMERCIAL TTF (Continued) **S103576014**

Facility Type:	ER
DER Facility ID:	209825
Site ID:	256212
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	3101
Spill Date:	1999-01-02
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1999-01-02
CID:	282
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-02
Spill Record Last Update:	2003-03-03
Spiller Name:	Not reported
Spiller Company:	UNKNOWN FOR NOW
Spiller Address:	SAME
Spiller Company:	001
Contact Name:	SAL SAMMARTANO
DEC Memo:	""
Remarks:	"mystic states thet have a 30 gallon oil spill.they state they have a crew enroute to clean up the spill but the exact cause they do not have or who is responsible yet. "

All Materials:

Site ID:	256212
Operable Unit ID:	1072797
Operable Unit:	01
Material ID:	312479
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

965 ESE 1/4-1/2 0.298 mi. 1576 ft.

APARTMENT
214 WEST 20TH STREET
NEW YORK, NY

NY LTANKS **S107789299**
N/A

Relative: Higher

Actual: 25 ft.

LTANKS:

Name:	APARTMENT
Address:	214 WEST 20TH STREET
City,State,Zip:	NEW YORK, NY

APARTMENT (Continued) **S107789299**

Spill Number/Closed Date:	0601208 / 2006-07-20
Facility ID:	0601208
Site ID:	363391
Spill Date:	2006-05-02
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2006-05-02
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-02
Spill Record Last Update:	2006-07-20
Spiller Name:	MARK
Spiller Company:	COMBINE OIL
Spiller Address:	1479 WILLAIMS BRIDGE
Spiller County:	001
Spiller Contact:	KINSEY CORP -LYNN
Spiller Phone:	(212) 255-3579
Spiller Extention:	209
DEC Region:	2
DER Facility ID:	313572
DEC Memo:	"05/11/06 Sharif Rahman- I left a messege for Lynn to call DEC back regarding the clean up. 07/20/06 Rahman- Rec'd clean up letter from North East Environmental. The spill was a minor one and came out of the vent line. Spill was on the side walk concrete, nothing went to sewer/soil.NFA required."
Remarks:	"oil is contained and speedi dri is being placed down: northeast enviormebtal enroute : is on sidewalk and some may have gotten into storm drain"

All Materials:

Site ID:	363391
Operable Unit ID:	1121446
Operable Unit:	01
Material ID:	2110943
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CD966 **APRT** **NY LTANKS** **S109064236**
ESE **213 WEST 18TH STREET** **N/A**
1/4-1/2 **NEW YORK, NY**
0.303 mi.
1598 ft. **Site 1 of 3 in cluster CD**

Relative:
Higher

Actual:
25 ft.

LTANKS:

Name:	APRT
Address:	213 WEST 18TH STREET
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0800354 / 2010-04-13
Facility ID:	0800354
Site ID:	396095
Spill Date:	2008-04-09
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	LXZIELIN
Referred To:	Not reported
Reported to Dept:	2008-04-09
CID:	474
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-04-09
Spill Record Last Update:	2010-04-13
Spiller Name:	MARLIN JOSEPH
Spiller Company:	APRT
Spiller Address:	213 WEST 18TH STREET
Spiller County:	001
Spiller Contact:	MARLIN JOSEPH
Spiller Phone:	(718) 624-4842
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	345584
DEC Memo:	"04/13/10 - LZ Reviewed a TT report and and a letter from Approved Oil Co.(eDocs), asserting that the fill and vent lines have been repaired, and the tank system has passed the tighntess test. The spill case is closed. 03/29/10 - LZ Sent a certified TTF letter(eDocs) to Friedman Mgt. Corp at 225 West 34th Street New York, NY 10122 4/23/08 bf: sent ttf letter to: Adam Stryker Chelrae Estates, Inc. 225 West 18th St., Suite 2010 New York, NY 10122 4/30/08 Received call from Steve Braun (718)238-1050. Tank is AST. He wanted to know if tank still needs retest. Tank probably failed because of fillbox. I told him tank system needs retest. He will also prepare letter/report and include contasmination findings. bf"
Remarks:	"DRY PORTION LEAK"

All TTF:

Facility ID:	0800354
Spill Number:	0800354
Spill Tank Test:	2384995
Site ID:	396095
Tank Number:	Not reported

APRT (Continued) **S109064236**

Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	True
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	396095
Operable Unit ID:	1153042
Operable Unit:	01
Material ID:	2143820
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CE967 **APT BLDG** **NY LTANKS** **S105997474**
ENE **255 WEST 23RD ST** **NY Spills** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.303 mi.
1600 ft. **Site 1 of 2 in cluster CE**

Relative:
Higher

Actual:
24 ft.

LTANKS:

Name:	255 WEST 23RD ST
Address:	255 WEST 23RD ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0209070 / 2007-06-21
Facility ID:	0209070
Site ID:	79684
Spill Date:	2002-12-04
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	qxabidi
Referred To:	Not reported
Reported to Dept:	2002-12-04
CID:	270
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False

APT BLDG (Continued) **S105997474**

Remediation Phase:	0
Date Entered In Computer:	2002-12-04
Spill Record Last Update:	2007-06-25
Spiller Name:	Not reported
Spiller Company:	HESS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	RUBIN
Spiller Phone:	(718) 624-4842
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	73954
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SUN Notes:by Rorriguez called ray lara of petroleum tank cleaners. he stated that there was a overfill of 30 gallons of oil to the address. The tank gauge was not working. Cleaning the spill right now. Ray Zolker from Hess. 800-437-7265. left a message for him to call. 12/05/2002 Tipple at od desk was called by Hess to request spill numbers 0209070 and 0209079 (since both numbers were issued for the same incident) be referenced to as one number. Tipple closed out # 0209079 and referenced the spill to 0209070. GAUGE ON TANK NOT WORKING 800-437-7265. 212-964-7712. RAY ZOICKER (HESS). 12/20/06: This spill is transferred from Mr. Koon Tang to Q.Abidi. -QA 12/21/06: Called Mr. Rubin (Super of Co op building) at (212)242-7191 he said this spill is cleaned up long time ago. He said to call property Manager regarding documents of the spill. Called Ms. Yvonne (Property Manager) at (212)319-5000 and talked about the information of the spill. She said this spill is cleaned since long time ago. She will send me closing confirmation letter to close the spill. -QA 01/03/06: Called Ms.Yvonne and said to take end point soil sample to find out the contamination in soil of spill area. -QA 02/05/07: Called Ms. Yvonne at (212)319-5000 and reminded her to take soil samples for closing this spill. -QA 06/11/07: Mr. Issac Mungra (Eastmond Company) sent me a report of one soil sample on dated May 30, 2007, which he took 2 ft. under the pipe line in the garden. He also sent a diagram in which he has shown the location of the sample. Soil sample is clean. -QA 06/21/07: I visited Spill site, checked fill port, vent line in the garden area and inside the basement. I didn't see any odor or any stain in the area. I have not found any sign of contamination in this area. This spill is clean (see photos in e-doc). After discussion with Mr. Jon Kolleeny (supervisor), I closed this spill. -QA "
Remarks:	"TANK OVERFILL"

All Materials:

Site ID:	79684
Operable Unit ID:	860492
Operable Unit:	01
Material ID:	516054
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

APT BLDG (Continued) **S105997474**

SPILLS:

Name:	APT BLDG
Address:	255 WEST 23RD ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0209079 / 2002-12-04
Facility ID:	0209079
Facility Type:	ER
DER Facility ID:	73954
Site ID:	79685
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	3101
Spill Date:	2002-12-04
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2002-12-04
CID:	198
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-04
Spill Record Last Update:	2002-12-11
Spiller Name:	RUBEN - SUPERINTENDANT
Spiller Company:	RUDD REALITY MGT
Spiller Address:	255 WEST 23RD ST
Spiller Company:	001
Contact Name:	RAYMOND SOJKA
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE/OD 12/05/2002 SPILL 0209070 and 0209079 are the same spill. Administratively closed 0209079 and referenced all to 0209070. CALLED RUBEN @ 212-242-7191. COMPANY CLEANING THE SPILL @ 1:33PM."
Remarks:	"DRIVER MAKING DELIVERY AND GAUGE WAS DEFECTIVE SHOWING A FALSE CAPACITY CAUSING APPROX 20 GALLONS TO SPILL. SPILL CONTAINED TO CONCRETE PAD."

All Materials:

Site ID:	79685
Operable Unit ID:	860497
Operable Unit:	01
Material ID:	516063
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CE968 **255 W. 23RD ST** **NY LTANKS** **S107410262**
ENE **255 W. 23RD ST** **N/A**
1/4-1/2 **NEW YORK, NY**
0.303 mi.
1600 ft. **Site 2 of 2 in cluster CE**

Relative: **Higher**
Actual: **24 ft.**

LTANKS:

Name:	255 W. 23RD ST
Address:	255 W. 23RD ST
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0205799 / 2003-06-20
Facility ID:	0205799
Site ID:	324079
Spill Date:	2002-09-04
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2002-09-04
CID:	196
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-04
Spill Record Last Update:	2005-10-06
Spiller Name:	YVONNE
Spiller Company:	RUDD MANAGEMENT
Spiller Address:	545 MADISON AVE
Spiller County:	001
Spiller Contact:	RENE LEWIS
Spiller Phone:	(917) 299-7257
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	261053
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 6/11/2003 Sangesland spoke to property manager. She says the old tanks were above ground and were removed. New tanks were installed (above ground also) and new lines run. A.L. Eastmond did all of the tank work. Sangesland asked her to send in a letter requesting closure and to attach photos of the new tanks, statement that there was no contamination and copies of documents proving a new tank was put in. All of this will be sent to Tim DeMeo. 6/18/03 TJD Report from Rudd Mgmt. reviewed. Demeo contacted RUDD and requested a copy of Enginnering report (Velocity) and statement from Mgmt. company that no contamination was found. Mgmt. Company to forward requested documents. 6/20/03 TJD Rudd Mgmt. submitted requested information. No further action required."
Remarks:	"the tank failed the test and is also leaking. this tank is also listed as 24th street tank. request call back in am on 9/05/02 it is tank 2. tank 1 was not leaking."

All TTF:

Facility ID:	0205799

255 W. 23RD ST (Continued) **S107410262**

Spill Number:	0205799
Spill Tank Test:	1527420
Site ID:	324079
Tank Number:	2
Tank Size:	5000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

Facility ID:	0205799
Spill Number:	0205799
Spill Tank Test:	1527421
Site ID:	324079
Tank Number:	1
Tank Size:	5000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	324079
Operable Unit ID:	858307
Operable Unit:	01
Material ID:	519994
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CF969 **CLOSED-LACKOF RECENT INFO** **NY LTANKS** **S102233331**
NE **315 W. 25TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.304 mi.
1607 ft. **Site 1 of 2 in cluster CF**

Relative:
Higher

Actual:
23 ft.

LTANKS:

Name:	CLOSED-LACKOF RECENT INFO
Address:	315 W. 25TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	8908445 / 2003-03-06
Facility ID:	8908445
Site ID:	138350
Spill Date:	1989-11-27
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	1989-11-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-11-29
Spill Record Last Update:	2004-07-19
Spiller Name:	Not reported
Spiller Company:	SAME/MUTUAL DVLPMNT HSG
Spiller Address:	SAME
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	118299
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ADMIN.CLOSED 03/06/2003- Closed Due To The Nature / Extent Of The Spill Report"
Remarks:	"TANK #11&12 BOTH 20K HORNER GROSS LEAKS.CLOSED DUE TO LACK OF ANY RECENT INFO- DOES NOT MEET ANY CLEAN UP REQUIREMENTS."

All TTF:

Facility ID:	8908445
Spill Number:	8908445
Spill Tank Test:	1536463
Site ID:	138350
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00

CLOSED-LACKOF RECENT INFO (Continued) **S102233331**

Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	138350
Operable Unit ID:	933493
Operable Unit:	01
Material ID:	445185
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

CF970 **MUTUAL REDEVELOPMENT HOUSES** **NY LTANKS** **U003127184**
NE **315 WEST 25TH STREET** **NY AST** **N/A**
1/4-1/2 **MANHATTAN, NY 10001**
0.304 mi.
1607 ft. **Site 2 of 2 in cluster CF**

Relative:
Higher

Actual:
23 ft.

LTANKS:

Name:	MUTUAL REDEVELOPMENT HOUSES
Address:	315 WEST 25TH STREET
City,State,Zip:	MANHATTAN, NY 10001
Spill Number/Closed Date:	9602633 / 2005-09-16
Facility ID:	9602633
Site ID:	257575
Spill Date:	1996-05-23
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	TLGIBBON
Referred To:	Not reported
Reported to Dept:	1996-05-23
CID:	323
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-05-23
Spill Record Last Update:	2005-10-11
Spiller Name:	BRENDAN KEANY
Spiller Company:	POWER HOUSE
Spiller Address:	315 W 25TH ST
Spiller County:	001

MUTUAL REDEVELOPMENT HOUSES (Continued) **U003127184**

Spiller Contact:	BRENDAN KEANY
Spiller Phone:	(212) 675-3200
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	24612
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was M TIBBE 6/8/05 - Project transferred to TLGibbons in Central Office, Albany 8/16/05 - Spoke with Brenden Keany, Mutual Redevelopment Houses, Inc., (212) 675-3200. Spill reported 5/23/96 by CDM during removal of twelve (12) 20,000 gal. #2 and #6 fuel oil USTs. The large fuel usage was for a cogen plant which generates electricity for ~3,000 people. After removing tanks and cleaning, went to dual fuel system, reinstalling only six 20,000 gal. #2 fuel oil USTs. Spoke with David Marabello (732-225-7000), CDM project manager during spill. He said that they excavated to the lateral and vertical limits possible, using shoring, without compromising structure of building. Southern portion of excavation encountered bedrock. Sixteen post-excavation samples were collected and evaluated for VOCs and SVOCs. All samples greater than 10 feet bgs. Elevated levels of VOCs and SVOCs were encountered in several samples, hovever, according to 10/2/98 CDM tank closure report, levels not indicative of gross tank failure, rather indicative of chronic spills over time. While some sporadic elevated levels of petroleum remain, everything that was reasonable to be done, was done. Close spill. "
Remarks:	"OLD TANK APPEARED TO HAVE FAILED. TANK IS BEING REMOVED, CONTAMINATED SOIL WAS FOUND DURING REMOVAL PROCESS. INVESTIGATION IS UNDERWAY AT THIS TIME."

All Materials:

Site ID:	257575
Operable Unit ID:	1030194
Operable Unit:	01
Material ID:	352456
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AST:

Name:	MUTUAL REDEVELOPMENT HOUSES, INC.
Address:	315 WEST 25TH STREET
City,State,Zip:	NEW YORK, NY 10001
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-602742
Program Type:	PBS
UTM X:	584568.39402
UTM Y:	4511157.07949
Expiration Date:	08/02/2026
Site Type:	Apartment Building/Office Building

MUTUAL REDEVELOPMENT HOUSES (Continued) **U003127184**

Affiliation Records:

Site Id:	24698
Affiliation Type:	Facility Operator
Company Name:	MUTUAL REDEVELOPMENT HOUSES, INC.
Contact Type:	Not reported
Contact Name:	EDWARD JOHNSON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 675-1942
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-01-29

Site Id:	24698
Affiliation Type:	Emergency Contact
Company Name:	MUTUAL REDEVELOPMENT HOUSES, INC.
Contact Type:	Not reported
Contact Name:	RYAN DZIEDZIECH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 675-3200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-09-13

Site Id:	24698
Affiliation Type:	Facility Owner
Company Name:	MUTUAL REDEVELOPMENT HOUSES, INC.
Contact Type:	GENERAL MANAGER
Contact Name:	RYAN DZIEDZIECH
Address1:	321 EIGHTH AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 675-3200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-09-13

Site Id:	24698
Affiliation Type:	Mail Contact
Company Name:	MUTUAL REDEVELOPMENT HOUSES, INC.
Contact Type:	Not reported
Contact Name:	RYAN DZIEDZIECH, MANAGER

MUTUAL REDEVELOPMENT HOUSES (Continued) **U003127184**

Address1:	321 EIGHTH AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 675-3200
EMail:	RDZIEDZIECH@PENNSOUTH.COOP
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-09-13

Tank Info:

Tank Number:	AST #2
Tank Id:	54517
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	C01 - Pipe Location - Aboveground I04 - Overfill - Product Level Gauge (A/G) H00 - Tank Leak Detection - None I02 - Overfill - High Level Alarm L09 - Piping Leak Detection - Exempt Suction Piping A00 - Tank Internal Protection - None B01 - Tank External Protection - Painted/Asphalt Coating D01 - Pipe Type - Steel/Carbon Steel/Iron F01 - Pipe External Protection - Painted/Asphalt Coating G10 - Tank Secondary Containment - Impervious Underlayment E07 - Piping Secondary Containment - Trench Liner G01 - Tank Secondary Containment - Diking (Aboveground) J02 - Dispenser - Suction Dispenser K99 - Spill Prevention - Other
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1984
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	AST#1
Tank Id:	51876
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

MUTUAL REDEVELOPMENT HOUSES (Continued) **U003127184**

Equipment Records:
K99 - Spill Prevention - Other
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
E07 - Piping Secondary Containment - Trench Liner
G01 - Tank Secondary Containment - Diking (Aboveground)
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1984
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: ACDANIEL
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: AST#3
Tank Id: 51879
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K99 - Spill Prevention - Other
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
E07 - Piping Secondary Containment - Trench Liner
G01 - Tank Secondary Containment - Diking (Aboveground)
J03 - Dispenser - Gravity
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service

MUTUAL REDEVELOPMENT HOUSES (Continued) **U003127184**

Pipe Model:	Not reported
Install Date:	01/01/1984
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	AST4
Tank Id:	61708
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K99 - Spill Prevention - Other
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
J03 - Dispenser - Gravity
E07 - Piping Secondary Containment - Trench Liner
L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/1999
Capacity Gallons:	240
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	AST5
Tank Id:	61709
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

MUTUAL REDEVELOPMENT HOUSES (Continued) **U003127184**

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
G01 - Tank Secondary Containment - Diking (Aboveground)
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H99 - Tank Leak Detection - Other

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	07/01/1998
Capacity Gallons:	240
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	KXTANG
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	AST7
Tank Id:	55901
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
H05 - Tank Leak Detection - In-Tank System (ATG)
E07 - Piping Secondary Containment - Trench Liner
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
G10 - Tank Secondary Containment - Impervious Underlayment
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other
I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported

MUTUAL REDEVELOPMENT HOUSES (Continued) **U003127184**

Install Date:	05/01/1998
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	AST8
Tank Id:	55902
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
G10 - Tank Secondary Containment - Impervious Underlayment
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
F06 - Pipe External Protection - Wrapped
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other
E07 - Piping Secondary Containment - Trench Liner
I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/1998
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

Tank Number:	FUEL #1
Tank Id:	51877
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

MUTUAL REDEVELOPMENT HOUSES (Continued) **U003127184**

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
G01 - Tank Secondary Containment - Diking (Aboveground)
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	01/01/1984
Capacity Gallons:	300
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	KXTANG
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	FUEL #2
Tank Id:	51878
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G01 - Tank Secondary Containment - Diking (Aboveground)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	01/01/1984
Capacity Gallons:	300
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

MUTUAL REDEVELOPMENT HOUSES (Continued) **U003127184**

Date Tank Closed:	Not reported
Register:	True
Modified By:	KXTANG
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

CD971 **VERIZON** **NY LTANKS** **S105999363**
ESE **210 W. 18TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.310 mi.
1636 ft. **Site 2 of 3 in cluster CD**

Relative: **Higher**

Actual: **25 ft.**

LTANKS:

Name:	VERIZON
Address:	210 W. 18TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0303667 / 2003-07-08
Facility ID:	0303667
Site ID:	207814
Spill Date:	2003-07-08
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2003-07-08
CID:	257
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-07-08
Spill Record Last Update:	2003-07-08
Spiller Name:	SAME
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	LLOYD
Spiller Phone:	(914) 450-7239
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	172446
DEC Memo:	""
Remarks:	"contained in a tank room clean up has started"

All Materials:

Site ID:	207814
Operable Unit ID:	871702
Operable Unit:	01
Material ID:	504532
Material Code:	0012A
Material Name:	kerosene
Case No.:	Not reported

VERIZON (Continued) **S105999363**

Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CA972 **186-188 11TH AVENUE - DOB JOB NOS. NB - 121237296** **NY VCP** **S125316887**
NNW **186 11TH AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.310 mi.
1639 ft. **Site 3 of 3 in cluster CA**

Relative: **Lower**
Actual: **7 ft.**

VCP NYC:

Project ID:	12TMP0189M,12EHAN189M,14CVCP166M
Name:	186-188 11TH AVENUE - DOB JOB NOS. NB - 121237296 AND A2 - 122202552
Address:	186 11TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Manhattan
BBL:	1.00695000310069E+19
OER Program:	VCP (Enrolled)
Phase:	Approved Remedial Plan
Latitude:	40.749089
Longitude:	-74.006861
Postcode:	4
Community Board:	3
Council District:	99
Census Tract:	1000000
BIN:	1006950003
NTA:	Hudson Yards-Chelsea-Flatiron-Union Square

CG973 **RESIDENCE** **NY LTANKS** **S105999021**
SSW **92 HORATIO ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.315 mi.
1664 ft. **Site 1 of 2 in cluster CG**

Relative: **Lower**
Actual: **11 ft.**

LTANKS:

Name:	RESIDENCE
Address:	92 HORATIO ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0301865 / 2004-05-25
Facility ID:	0301865
Site ID:	205279
Spill Date:	2003-05-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2003-05-21
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester

RESIDENCE (Continued) **S105999021**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-05-21
Spill Record Last Update:	2004-05-25
Spiller Name:	BERNIE EISNER
Spiller Company:	ORSID REALTY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	ORSID REALTY
Spiller Phone:	(212) 247-2603
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	170463
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 5/22/03 - ROSSAN, DDO - Called Eugene Peck, who confirmed tank failure and advised that tank test failure letter sent to: Mr. Neil B. Davidowitz / Ms. Graham Horatio Arms Inc. c/o Orsid Realty Corp. 1740 Broadway, 2nd Floor New York, NY 10019 4/30/2004 Sangesland sent a second TTF letter to the property manager 5/13/04 tipple updating//system passed subsequent test///documentation to follow//fill& vent both repaired 5/25/04 tipple updating// Eugene Peck on site during excavation//no indication of petroleum contamination//report arrived and reviewed//no further action necessary.. "
Remarks:	"RECOMMEND TO DO ADDITION INVESTIGATION INTO WHICH COMPONENTS ARE LEAKING."

All TTF:

Facility ID:	0301865
Spill Number:	0301865
Spill Tank Test:	1528397
Site ID:	205279
Tank Number:	Not reported
Tank Size:	2500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	205279
Operable Unit ID:	869878
Operable Unit:	01
Material ID:	506350
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

RESIDENCE (Continued) **S105999021**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BZ974 **APT HOUSE** **NY LTANKS** **S107489138**
South **16 JANE STREET** **N/A**
1/4-1/2 **NEW YORK, NY**
0.317 mi.
1676 ft. **Site 3 of 3 in cluster BZ**

Relative: **Higher**
Actual: **24 ft.**

LTANKS:

Name:	APT HOUSE
Address:	16 JANE STREET
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0509778 / 2005-12-12
Facility ID:	0509778
Site ID:	355610
Spill Date:	2005-11-15
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2005-11-15
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-11-15
Spill Record Last Update:	2005-12-12
Spiller Name:	Not reported
Spiller Company:	UNKNOWN FUEL COMPANY
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	(212) 972-5900
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	305645
DEC Memo:	"Sangesland spoke to DEP rep. Apparently several days ago this building had a problem with an oil leak in it's basement. DEP was notified but not DEC. Building Manager is Neil at R.A.Cohen & Associates (212-972-5900 ext 203) Neil said that he has had some work done in the basement on the tank, but he did not know any details and he did not know if the problem was solved. Unless he can describe exactly what happened to the tank and what work has been done, a site visit may be required to confirm that the floor is clean and the repairs have been made. 12/6/05 - Raphael Ketani. I tried calling Neil Gevertz, the building manager, at the above phone number, but

APT HOUSE (Continued) **S107489138**

could only leave a voice mail. He has a new direct phone number: (212) 835-9530. I left a voice mail message there, also. 12/8/05 - Raphael Ketani. Mr. Gevertz called me back. We arranged a site visit on 12/12 at 2PM. 12/12/05 - Raphael Ketani. I met Mr. Gevertz (management company rep.), Mr. John Masini, Vice President M.M.I. Mechanical Inc. (718) 449-4166 (boiler and tank maintenance), and Bill Herrera, superintendent of the building, at the site. The boiler room was fresh painted and dry with no odors. There were no cracks in the floor. No stains were visible on the floor, or on the piping. The spill had been called in due to a defective valve. I saw the replacement valve. The valve appeared to be installed properly. Next, we went to the boiler room. The boiler room showed no signs of spills. There was a new oil pump and assembly on the boiler. There were no odors. Lastly, I checked around the vent and fill pipes. There were no stains. Based on the inspection, I am closing the case. "

Remarks: "OVERFILL OF TANK, NO FURTHER INFO AVAILABLE"

All Materials:

Site ID:	355610
Operable Unit ID:	1112959
Operable Unit:	01
Material ID:	2103005
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CH975 **APT BLDG TTF** **NY LTANKS** **S110140521**
South **15 ABINGDON SQUARE** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.319 mi.
1685 ft. **Site 1 of 2 in cluster CH**

Relative: **Higher**
Actual: **20 ft.**

LTANKS:

Name:	APT BLDG TTF
Address:	15 ABINGDON SQUARE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0909695 / 2010-02-25
Facility ID:	0909695
Site ID:	422421
Spill Date:	2009-12-02
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	LXZIELIN
Referred To:	Not reported
Reported to Dept:	2009-12-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other

APT BLDG TTF (Continued) **S110140521**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-12-02
Spill Record Last Update:	2010-06-30
Spiller Name:	Not reported
Spiller Company:	APT BLDG
Spiller Address:	15 ABINGDON SQUARE
Spiller County:	999
Spiller Contact:	JOE OSTROWSKI
Spiller Phone:	(718) 855-7272
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	371361
DEC Memo:	"TTF Letter sent to PBS Contact address: 6 Square Comp Attn: Joe Alpert 271 Madison Ave - 22nd Flr New York, NY 10016 PBS #2-045675 2/25/10 Received response from David Chan of Riteway Tank Maintenance dated 2/11/10. Tank was pumped out and cleaned. Approximately 10 gallons of product spilled on a cement floor that was in good condition. There were no visible holes or drains in the floor. Manifest provided for disposal of contaminated material. NFA. bf"
Remarks:	"TANK TEST FAILURE ON A 5000 GALLON AST, PBS NUMBER NOT AVAILABLE."

All Materials:

Site ID:	422421
Operable Unit ID:	1178260
Operable Unit:	01
Material ID:	2171479
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

CB976 **23RD ST & EAST RIVER DR** **NY LTANKS** **S105053995**
NNW **600 E.23RD ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.322 mi.
1701 ft. **Site 2 of 3 in cluster CB**

Relative: **Lower**
Actual: **6 ft.**

LTANKS:

Name:	23RD ST & EAST RIVER DR
Address:	600 E.23RD ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9506116 / 2003-04-15
Facility ID:	9506116
Site ID:	84527
Spill Date:	1995-08-17
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	Not reported

23RD ST & EAST RIVER DR (Continued) **S105053995**

SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1995-08-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1995-09-22
Spill Record Last Update:	2003-04-15
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	77731
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE REFER TO 9506959 & SP94396."
Remarks:	"TANK #10 550 GAL US TEST 2000 - LEAK RATE IS FAILED"

All TTF:

Facility ID:	9506116
Spill Number:	9506116
Spill Tank Test:	1544095
Site ID:	84527
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	84527
Operable Unit ID:	1017013
Operable Unit:	01
Material ID:	569850
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G

23RD ST & EAST RIVER DR (Continued) **S105053995**

Recovered: .00
Oxygenate: Not reported

CB977 **GULF GAS STATION** **NY LTANKS** **S100167737**
NNW **600 E.23RD ST, E. RIVER** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.322 mi.
1701 ft. **Site 3 of 3 in cluster CB**

Relative:
Lower

Actual:
6 ft.

LTANKS:

Name:	GULF GAS STATION
Address:	600 E.23RD ST, E. RIVER
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	8906042 / 2006-09-11
Facility ID:	8906042
Site ID:	283247
Spill Date:	1989-09-19
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	JAKOLLEE
Referred To:	OLD PIN JOB
Reported to Dept:	1989-09-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1989-09-20
Spill Record Last Update:	2006-09-11
Spiller Name:	Not reported
Spiller Company:	CUMBERLAND FARMS
Spiller Address:	777 DEDHAM ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(212) 686-4546
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	229732
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was K FOLEY 1/8/04 Reassigned from Sullivan to K Foley. (KMF) REFER TO 9506959 & SP94396. 09/11/06: This spill case is closed to consolidate with open spill 9506959, under which remediation of this area, along with the adjacent-to-the-south Stuyvesant Cove Park and Education Center, is being tracked as part of the DDC consent order. - J. Kolleeny"
Remarks:	"4K CAPACITY. TEST METHOD PETROTITE TO EXCAVATE AND INVESTIGATE INITIALINFORMATION. LEAKAGE .266 GPH"

All TTF:

Facility ID:	8906042
Spill Number:	8906042

GULF GAS STATION (Continued) **S100167737**

Spill Tank Test:	1536050
Site ID:	283247
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	283247
Operable Unit ID:	933693
Operable Unit:	01
Material ID:	446434
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

CC978 **APARTMENT BLDG** **NY LTANKS** **S102673411**
South **299 WEST 12TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.324 mi.
1711 ft. **Site 2 of 3 in cluster CC**

Relative:
Higher

Actual:
19 ft.

LTANKS:

Name:	APARTMENT BLDG
Address:	299 WEST 12TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9603973 / 1996-07-03
Facility ID:	9603973
Site ID:	182231
Spill Date:	1996-06-23
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1996-06-23
CID:	312
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported

APARTMENT BLDG (Continued) **S102673411**

Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-06-23
Spill Record Last Update:	1996-07-08
Spiller Name:	SCOTT
Spiller Company:	AMERADA HESS
Spiller Address:	1 HESS PLAZA
Spiller County:	001
Spiller Contact:	ORLANDO
Spiller Phone:	(212) 645-8487
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	152736
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT "
Remarks:	"faulty petrometer reading - being cleaned up now"

All Materials:

Site ID:	182231
Operable Unit ID:	1031633
Operable Unit:	01
Material ID:	558379
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

979
SW
1/4-1/2
0.325 mi.
1718 ft.

NYCDOS GANESVOORT MTS **NY SWF/LF** **S105841766**
GANESVOORT ST & WESTSIDE (NEAR 14 ST.) **N/A**
NEW YORK, NY 10014

Relative:
Lower

Actual:
3 ft.

SWF/LF:

Name:	NYCDOS GANESVOORT MTS
Address:	GANESVOORT ST & WESTSIDE (NEAR 14 ST.)
City,State,Zip:	NEW YORK, NY 10014
Flag:	INACTIVE
Region Code:	2
Phone Number:	2128378030
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Paul Bekowies
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported

NYCDOS GANESVOORT MTS (Continued) **S105841766**

Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit
Activity Number:	[31T03]
Active:	No
East Coordinate:	583600
North Coordinate:	4510300
Accuracy Code:	Not reported
Regulatory Status:	Permit
Waste Type:	Not reported
Authorization #:	2-6205-00004
Authorization Date:	3/26/1991
Expiration Date:	12/31/2005
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

CG980 **85-89 JANE STREET** **NY VCP** **S125317227**
SSW **89 JANE STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.327 mi.
1726 ft. **Site 2 of 2 in cluster CG**

Relative: **Lower**
Actual: **12 ft.**

VCP NYC:

Project ID:	16TMP0428M,16EH-N313M,17CVCP036M
Name:	85-89 JANE STREET
Address:	89 JANE STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Manhattan
BBL:	1.0064200701006399E+19
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Construction
Latitude:	40.738151
Longitude:	-74.007628
Postcode:	2
Community Board:	3
Council District:	79
Census Tract:	1012152
BIN:	1006420072
NTA:	West Village

CD981 **CLOSED-LACKOF RECENT INFO** **NY LTANKS** **S104275589**
ESE **200 WEST 18TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.329 mi.
1739 ft. **Site 3 of 3 in cluster CD**

Relative: **Higher**
Actual: **26 ft.**

LTANKS:

Name:	CLOSED-LACKOF RECENT INFO
Address:	200 WEST 18TH STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9004954 / 2003-03-06
Facility ID:	9004954
Site ID:	306974
Spill Date:	1990-08-03
Spill Cause:	Tank Test Failure

CLOSED-LACKOF RECENT INFO (Continued) **S104275589**

Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	1990-08-03
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-08-08
Spill Record Last Update:	2003-03-06
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	247909
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ADMIN.CLOSED 03/06/2003- Closed Due To The Nature / Extent Of The Spill Report"
Remarks:	"4K TANK FAILED HORNER EZY CHECK WITH A GROSS LEAK, WILL EXCAVATE, ISOLATE & RETEST.CLOSED DUE TO LACK OF ANY RECENT INFO- DOES NOT MEET ANY CLEAN UP REQUIREMENTS."

All TTF:

Facility ID:	9004954
Spill Number:	9004954
Spill Tank Test:	1537403
Site ID:	306974
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	306974
Operable Unit ID:	945447
Operable Unit:	01
Material ID:	436027

CLOSED-LACKOF RECENT INFO (Continued) **S104275589**

Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

CC982 **317 WEST 12TH ST** **NY LTANKS** **S102660102**
SSW **317 WEST 12TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.330 mi.
1742 ft. **Site 3 of 3 in cluster CC**

Relative: **Higher**
Actual: **17 ft.**

LTANKS:

Name:	317 WEST 12TH ST
Address:	317 WEST 12TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9612484 / 1997-04-21
Facility ID:	9612484
Site ID:	134462
Spill Date:	1997-01-16
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MMMULQUE
Referred To:	Not reported
Reported to Dept:	1997-01-20
CID:	312
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1997-03-11
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-01-20
Spill Record Last Update:	1997-04-21
Spiller Name:	Not reported
Spiller Company:	MRS CARTIER
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	MRS CARTIER
Spiller Phone:	(212) 233-0924
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	115543
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MULQUEEN TWO X 275 AST MANIFOLDED HAD LEAKED IN BASEMENT DUE TO TANK OVERFILL BY FERRANTI OIL. PTC HIRED BY OIL COMPANY TO CLEANUP OVERFILL IN FRONT OF BUILDING AND IN CELLAR NEXT DOOR (VENT LINE DISCHARGE). TANKS BEGAN SWEATING OIL SO LANDLORD HIRED PTC TO REMOVE TANKS AND SWITHCED BUILDING TO GAS HEAT."
Remarks:	"CALLER JUST FOUND THE PAPERWORK ON HIS DESK - CREW RESPONDED THAT

317 WEST 12TH ST (Continued) **S102660102**

NIGHT - PUMPED OUT TANK AND CAME UP WITH 20 GAL LEFT IN IT - UNK HOW MUCH LEAKED BEFORE BEING DISCOVERED - SPEEDY-DRI APPLIED AND A NEW TANK WAS PUT IN"

All Materials:

Site ID:	134462
Operable Unit ID:	1044000
Operable Unit:	01
Material ID:	341131
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

983 **DEL. SPILL /W.28ST.&10AV** **NY LTANKS** **S102671130**
North **W. 26TH ST & 10TH AVE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.336 mi.
1775 ft.

Relative:
Higher

Actual:
14 ft.

LTANKS:

Name:	DEL. SPILL /W.28ST.&10AV
Address:	W. 26TH ST & 10TH AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8605584 / 1986-12-04
Facility ID:	8605584
Site ID:	295262
Spill Date:	1986-12-04
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1986-12-04
SWIS:	3101
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1986-12-04
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1986-12-06
Spill Record Last Update:	2002-03-26
Spiller Name:	Not reported
Spiller Company:	ONDPR TRUCKING
Spiller Address:	702 OAK ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported

DEL. SPILL /W.28ST.&10AV (Continued) **S102671130**

DEC Region:	2
DER Facility ID:	238927
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was "
Remarks:	"NYCFD CONTAINED SPILL WITH SORBENT PADS. UNKNOWN NOTIFIER."

All Materials:

Site ID:	295262
Operable Unit ID:	902966
Operable Unit:	01
Material ID:	474759
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	400.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

CI984 **201 WEST 16TH ST CORP.** **NY LTANKS** **S104877040**
SE **201 WEST 16TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.340 mi.
1794 ft. **Site 1 of 2 in cluster CI**

Relative:
Higher

Actual:
26 ft.

LTANKS:

Name:	201 WEST 16TH ST CORP.
Address:	201 WEST 16TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0008506 / 2005-12-22
Facility ID:	0008506
Site ID:	304546
Spill Date:	2000-10-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	JBTAMBE
Referred To:	Not reported
Reported to Dept:	2000-10-20
CID:	281
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-10-20
Spill Record Last Update:	2005-12-22
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	PAUL MORTON
Spiller Phone:	(212) 557-3600

201 WEST 16TH ST CORP. (Continued) **S104877040**

Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	245998
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD 01/26/04 Transferred from Rommel to Austin 02/17/04: Reassigned from AUSTIN to KRIMGOLD. 12/22/05: Jacob- Tank was closed-in-place around 12/3/01. See file"
Remarks:	"TANK TEST FAILURE AT ABOVE LOCATION. PROEPRTY OWNER HAS BEEN ADVISED OF TEST RESULTS. AT TIME OF CALL UNKNOWN WHAT FURTHER STEPS WILL BE TAKEN. NO CALL BACK REQUESTED."

All TTF:

Facility ID:	0008506
Spill Number:	0008506
Spill Tank Test:	1525943
Site ID:	304546
Tank Number:	1
Tank Size:	8000
Material:	0003
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	304546
Operable Unit ID:	830955
Operable Unit:	01
Material ID:	571846
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

985 SE 1/4-1/2 0.342 mi. 1805 ft.

BUSINESS AT LOCATION
205 WEST 14TH ST
MANHATTAN, NY

NY LTANKS **S106385907**
NY Spills **N/A**

Relative: Higher

Actual: 26 ft.

LTANKS:

Name:	SPILL NUMBER 0400657
Address:	205 WEST 14TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0400657 / 2004-05-10
Facility ID:	0400657
Site ID:	159682

BUSINESS AT LOCATION (Continued) **S106385907**

Spill Date:	2004-04-20
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	CESAWYER
Referred To:	Not reported
Reported to Dept:	2004-04-20
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-04-20
Spill Record Last Update:	2004-05-10
Spiller Name:	ARLENE OR JOEL
Spiller Company:	Not reported
Spiller Address:	205 WEST 14TH STREET
Spiller County:	001
Spiller Contact:	ARLENE OR JOEL
Spiller Phone:	(212) 645-4612
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	134884
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 4/23/2004 Sangesland spoke to Mark at PTC. He said PTC was hired to clean out a tank. During this cleanout a small hole was found. The owner told PTC to take the tank out. Tank was aboveground and wrapped in concrete. Contaminated sand was found in the area behind the concrete wrap. The wrap & contmainated material was removed and so was the tank. Floor under the tank appears in good condition. Clean up should be complete, but Mark will need to conduct one more site visit to comfirm cleanup is complete. 4/29/04 - Sawyer - Spoke to Letty of the management company and she is going to try to obtain the work and disposal documentation for closure. 5/10/04 - Sawyer - Letty of Hand on management sent the receipts from PTC for the removal and disposal of old tank as well as clean up and removal of old fill lines. 17 55 gallon drums of debris for legal disposal. No further Action. Closed."
Remarks:	"REPLACING TANK FOUND HOLES AND SOIL IS CONTAMINATED: "

All Materials:

Site ID:	159682
Operable Unit ID:	884878
Operable Unit:	01
Material ID:	491902
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

BUSINESS AT LOCATION (Continued) **S106385907**

SPILLS:

Name:	BUSINESS AT LOCATION
Address:	205 WEST 14TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	1309135 / 2014-05-16
Facility ID:	1309135
Facility Type:	ER
DER Facility ID:	445002
Site ID:	489910
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2013-12-13
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2013-12-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-12-13
Spill Record Last Update:	2014-05-16
Spiller Name:	Not reported
Spiller Company:	PROPERTY OWNER
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ROB HILL
DEC Memo:	"12/13/13-Zhune spoke to Rob Hill from Riteway. He said the building have two 275 gallons UST. #2 fuel oil conected each other in the basement. The first tank has a leak on top of the tank and spilled 5 gallons of oil onto the floor. Floor is a concrete floor. The oil company came an spread speedi dry on the spill and sent Riteway to check the tank. As per Rob they will replace the tank on Monday 12/16/13 and they will clean the spill underneath the tank. He also said there is no odor in the building. 12/13/13-Zhune spoke to Jimmy (Porter)347-829-0389. He said one of the two tanks have three holes on the top of the tank and spilled oil any time that there is a delivery. Today there was a delivery and oil started coming by one of the big holes. The oil company stopped the delivery and sent Riteway to check the tank. There is oil on the floor covered with speedi dry. He could not say an estimate amount. There is no odor in the building. Kumar Patel inspected the site. 12/13/13-Hiralkumar Patel. alternate address: none no PBS record found. other spill # 0400657 was reported on 04/20/2004 as contamination was found during removal of 1,080 gal #2 fuel oil tank. as per invoice from PTC (dated 04/14/04), they removed seventeen (17) 55-gal drums for legal disposal. as per DEC Sangesland, PTC found contaminated sand in the area behind the concrete wrap of the tank. PTC removed concrete wrap and contaminated material. floor underneath the tank was found in good condition. case closed. 4:00 PM:- visited site. inspected

BUSINESS AT LOCATION (Continued) **S106385907**

basement. no odors noted in basement. site has two 275 gal ASTs on legs, located in southeast corner of the site, along W 14th St. the two ASTs are interconnected at top. the fill line is connected to the tank which is along the foundation wall (tank #1). vent line is connected to tank away from the foundation wall (tank #2). as per one of the technician, who was at site working on sprinkler system, oil started spraying from top of the tank #1, through corrosion holes. observed a pit near the tanks. as per technician, no oil went into pit, but flowed to other side of tank room. found speedy dry on floor. no active leak found from tanks' bottom. 205 LLC. **property owner** c/o Sir Realty Management LLC. **management company** 381 Park Avenue South, Suite 1001 New York, NY 10016 Attn.: William Radmin **property manager** PH. (212) 645-4612 (O) (646) 253-0920 (C) email: wradmin@friedmanroth.com Jose Zapata **building super** Ph. (917) 628-8937 2:30 PM:- left message for Mr. Radmin. 2:38 PM:- left message for Jose. 2:45 PM:- spoke with operator at management office and left message for Mr. Radmin. 2:52 PM:- received call from Mr. Radmin. he mentioned that Statewide boiler company is at site. someone from Statewide will call back. 3:00 PM:- spoke with Rob at Riteway. they are removing both tanks at this time. he mentioned that corrosion holes were developed due to water dripping on tank top. during oil delivery, tank #1 (which is along foundation wall) got full and before oil can move to tank #2 via interconnecting pipe, it started to leak from one of the corrosion hole on top of tank #1. 12/17/13-Hiralkumar Patel. 10:15 AM:- visited site. met crew from Riteway Tank Maintenance. two old 275 gal ASTs have been removed and tank room floor was cleaned. a new 275 gal temporary tank installed in tank room. tank room floor found in good condition, except two locations: a dirt area found along eastern wall of the tank room and a hole found in floor near where leaking tanks were located. a sealed metal plate is located near the hole in tank location area. no petroleum odors noted in area. inspected sewer trap pit, located along south wall of tank room. no sign of impact noted in pit. spoke with Rob at Riteway. informed him that the department requires investigation for possible subsurface contamination in two areas in tank room: one along eastern wall of tank room and hole in floor near former tank location. 11:49 AM:- left message for Mr. Radmin. informed him about required investigation by sealed metal plate in tank room floor and eastern wall of tank room. 12:19 PM:- sent letter to Mr. Radmin requiring subsurface investigation in two locations: along eastern wall of the tank room and by the hole near sealed metal plate. asked him to submit report by the end of 02/28/14. letter emailed to Rob. 12:22 PM:- letter emailed to Mr. Radmin. 01/16/14-Hiralkumar Patel. 1:51 PM:- spoke with Rob inquiring updates. he will check record and call back. 02/21/14-Hiralkumar Patel. 10:05 AM:- spoke with Rob. they removed some contaminated soil from former tank location. they will continue remediation. 10:10 AM:- visited site. inspected excavation in tank room. no petroleum odors noted in excavation. some stained soil noted. 03/25/14-Hiralkumar Patel. 11:20 AM:- received call from Rob. they removed additional contamination after moving on-site tank. Rob believes more contamination at the site, but it can not be removed due to structural issues. aksed Rob to collect endpoint samples from 8260/8270 analyses and submit results, once available. asked him to backfill the excavation as no further excavation possible. 05/12/14-Hiralkumar Patel. 3:34 PM:- spoke with Rob and asked him to submit cleanup report. 05/15/14-Hiralkumar Patel. 1:55 PM:- received

BUSINESS AT LOCATION (Continued) **S106385907**

Remarks:	email from Dave including cleanup report. 05/16/14-Hiralkumar Patel. based on available information, case closed. 10:46 AM:- sent spill closure letter to Mr. Radmin. letter emailed to Mr. Radmin and Dave." "contracted by oil company - in basement - cleanup pending"

All Materials:

Site ID:	489910
Operable Unit ID:	1239481
Operable Unit:	01
Material ID:	2239520
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

CJ986 **SPILL NUMBER 0104073** **NY LTANKS** **S105140204**
ENE **304 8TH AV** **NY Spills** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.349 mi.
1841 ft. **Site 1 of 3 in cluster CJ**

Relative:
Higher

Actual:
25 ft.

LTANKS:

Name:	SPILL NUMBER 0104060
Address:	304 8TH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0104060 / 2001-07-18
Facility ID:	0104060
Site ID:	310569
Spill Date:	2001-07-17
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2001-07-17
CID:	382
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-07-17
Spill Record Last Update:	2001-08-01
Spiller Name:	UNKNOWN
Spiller Company:	Not reported
Spiller Address:	304 8TH AVE
Spiller County:	001
Spiller Contact:	UNKNWON
Spiller Phone:	Not reported

SPILL NUMBER 0104073 (Continued) **S105140204**

Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	250692
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO Hole in tank caused spill onto basement floor. No sumps or drains impacted. NYFD responded stopped leak and contained spill. Owner is Athena (718)271 8452. Remainder of oil cleaned from basement floor using absorbents. Owner reports problem not due to hole in tank but a failed suction line. Repairs completed."
Remarks:	"spill from hole in tank onto basement floor. fd on scene attempting to plug hole but still leaking"

All Materials:

Site ID:	310569
Operable Unit ID:	840682
Operable Unit:	01
Material ID:	532567
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	SPILL NUMBER 0104073
Address:	304 8TH AV
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0104073 / 2001-07-17
Facility ID:	0104073
Facility Type:	ER
DER Facility ID:	256968
Site ID:	318789
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3101
Spill Date:	2001-07-17
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2001-07-17
CID:	270
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-07-17
Spill Record Last Update:	2001-08-01
Spiller Name:	CALLER

SPILL NUMBER 0104073 (Continued) **S105140204**

Spiller Company:	ATHINA STROGHILAS
Spiller Address:	304 8TH AV
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO see spill #0104060"
Remarks:	"lien broke on tank. clean up in progress"

All Materials:

Site ID:	318789
Operable Unit ID:	842592
Operable Unit:	01
Material ID:	532579
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	60.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CK987 **SPILL NUMBER 0201897** **NY LTANKS** **S105995914**
North **543 - 545 WEST 25TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.350 mi.
1849 ft. **Site 1 of 2 in cluster CK**

Relative:
Lower

Actual:
10 ft.

LTANKS:

Name:	SPILL NUMBER 0201897
Address:	543 - 545 WEST 25TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0201897 / 2003-04-11
Facility ID:	0201897
Site ID:	291496
Spill Date:	2002-05-22
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2002-05-22
CID:	207
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-05-22
Spill Record Last Update:	2003-04-11
Spiller Name:	MARK ROBBINS ENV.CONSLT
Spiller Company:	ALSO KNOWN AS:
Spiller Address:	525 WEST 25TH ST

SPILL NUMBER 0201897 (Continued) **S105995914**

Spiller County:	001
Spiller Contact:	JACK FUCHS - OWNER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	236035
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND Question on proper address of this building. Originally called in as 525 W 25th. Later called 543-545 West 25th St. 5/22/02 - Sangesland spoke with Mark Robbins of Hydro Tech (631-462-5866) cell # 516-996-5559 Property owner Jack Fuchs - Whitehall Business Archives, Inc. 40 Worth Street, NY, NY 10013 Hydro Tech was pulling a buried 3,000 gal #2 oil tank from a parking lot. 15 ft to nearest neighbor, south end of tank is at the sidewalk line. They discovered 10 large holes in the tank. The pit has product in it. Hydro will vac out the hole and will excavate out contaminated soil to clean endpoints. If all contamination can not be excavated a remediation plan will be prepared and submitted. 7/2/2002 - Mark Robbins of Hydro Tech submitted a report which outlines the removal of a UST and the over excavation of the tank pit area. Sidewall endpoint samples were all below TAGM levels for VOC and SVOC's except for a handful of slight exceedences. No bottom soil samples were taken because of the presence of ground water. Hydro Tech recommends the installation of a monitoring well in the north side of the excavation area. The well should be monitored for the presence of separate-phase and dissolved phase product. DEC instructs Hydro Tech to install a monitoring well on the site, develop the well and sample for VOC's and SVOC's. The DEC will require 2 rounds of Clean samples taken at least 3 months apart in order to close out. 10/29/2002 - Sangesland reviewed submittal from Hydro Tech Environmental. Water sample taken from monitoring well on site showed no product and sample was clean for everything except a minor hit 1.1 ug/l of Benzene. SVOC all below detect. 4/11/2003 - Sangesland reviewed a submittal from Hydro Tech dated Feb 28, 2003. This report shows the second round of GW sampling. All results were ND, therefore the spill can be closed out. Spill Closed."
Remarks:	"case when assigned call the notifier 516 996 5559 "

All Materials:

Site ID:	291496
Operable Unit ID:	852853
Operable Unit:	01
Material ID:	523311
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CH988 **GOODSTEIN MNGMT** **NY LTANKS** **S102671310**
South **302 W 12TH ST** **N/A**
1/4-1/2 **NYC, NY**
0.351 mi.
1852 ft. **Site 2 of 2 in cluster CH**

Relative:
Higher

Actual:
21 ft.

LTANKS:

Name:	GOODSTEIN MNGMT
Address:	302 W 12TH ST
City,State,Zip:	NYC, NY
Spill Number/Closed Date:	8805303 / 1988-09-29
Facility ID:	8805303
Site ID:	110169
Spill Date:	1988-09-29
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C4
Cleanup Ceased:	1988-09-21
SWIS:	3101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1988-09-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-09-21
Spill Record Last Update:	2007-08-14
Spiller Name:	Not reported
Spiller Company:	HESS
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	96591
DEC Memo:	""
Remarks:	"FAULTY GAUGE READING BY GOODSTEIN. CONTAINED ON PAVEMENT, HESS PERSONNEL DID CLEAN UP."

All Materials:

Site ID:	110169
Operable Unit ID:	922369
Operable Unit:	01
Material ID:	457208
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Oxygenate:	Not reported

CL989 **PUBLIC SCHOOL #33** **NY LTANKS** **U000411085**
NNE **281 9TH AVENUE** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.352 mi.
1860 ft. **Site 1 of 2 in cluster CL**

Relative:
Higher

Actual:
22 ft.

LTANKS:

Name:	PS 33
Address:	281 9TH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9713196 / 2003-03-03
Facility ID:	9713196
Site ID:	224963
Spill Date:	1998-02-26
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1998-02-26
CID:	366
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-02-26
Spill Record Last Update:	2003-03-03
Spiller Name:	Not reported
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller County:	001
Spiller Contact:	JOHN KASE
Spiller Phone:	(718) 391-6590
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	185691
DEC Memo:	""
Remarks:	"CALLER REPORTING OVERFILL AT PUBLIC SCHOOL #33. CLEAN UP WILL BEGIN SHORTLY."

All Materials:

Site ID:	224963
Operable Unit ID:	1059258
Operable Unit:	01
Material ID:	324220
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	60.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

PUBLIC SCHOOL #33 (Continued) **U000411085**

Name:	PUBLIC SCHOOL #33
Address:	281 9TH AVENUE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9614151 / 1997-12-31
Facility ID:	9614151
Site ID:	252801
Spill Date:	1997-03-05
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MMMULQUE
Referred To:	Not reported
Reported to Dept:	1997-03-05
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-03-05
Spill Record Last Update:	1998-01-06
Spiller Name:	ESTON CLARE
Spiller Company:	T & S TRUCKING
Spiller Address:	53 2ND AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(718) 391-6575
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	207077
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MULQUEEN "
Remarks:	"CALLER STATED THAT 5,500GAL WAS ORDERED. TANK STARTED OVERFILLING AT 1,315 GALS."

All Materials:

Site ID:	252801
Operable Unit ID:	1045585
Operable Unit:	01
Material ID:	339261
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CM990 **EXXONMOBIL** **NY LTANKS** **S106703644**
ESE **153-169 SEVENTH AVE** **N/A**
1/4-1/2 **NEW YORK, NY**
0.353 mi.
1865 ft. **Site 1 of 3 in cluster CM**

Relative:
Higher

Actual:
27 ft.

LTANKS:

Name:	EXXONMOBIL
Address:	153-169 SEVENTH AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	9209472 / 1992-12-07
Facility ID:	9209472
Site ID:	188431
Spill Date:	1992-11-13
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	1992-12-07
SWIS:	3101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1992-11-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-11-18
Spill Record Last Update:	2003-12-11
Spiller Name:	Not reported
Spiller Company:	EXXONMOBIL
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	157383
DEC Memo:	""
Remarks:	"PROBABLE FITTING PROBLEM NO CALL BACK NECESSARY"

All TTF:

Facility ID:	9209472
Spill Number:	9209472
Spill Tank Test:	1540850
Site ID:	188431
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported

EXXONMOBIL (Continued) **S106703644**

Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 188431
Operable Unit ID: 976076
Operable Unit: 01
Material ID: 406516
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

CM991 **MOBIL STATION #17Q53** **NY LTANKS** **S106703048**
ESE **153-169 SEVENTH AVE** **N/A**
1/4-1/2 **NEW YORK, NY**
0.353 mi.
1865 ft. **Site 2 of 3 in cluster CM**

Relative:
Higher

Actual:
27 ft.

LTANKS:
Name: MOBIL STATION #17Q53
Address: 153-169 SEVENTH AVE
City,State,Zip: NEW YORK, NY
Spill Number/Closed Date: 9911365 / 2002-09-24
Facility ID: 9911365
Site ID: 188433
Spill Date: 1999-12-28
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 3101
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1999-12-28
CID: 388
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1999-12-28
Spill Record Last Update: 2003-01-08
Spiller Name: Not reported
Spiller Company: EXXONMOBIL
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: CALLER
Spiller Phone: (800) 666-2605
Spiller Extention: Not reported

MOBIL STATION #17Q53 (Continued) **S106703048**

DEC Region:	2
DER Facility ID:	157383
DEC Memo:	""
Remarks:	"used vacutec method tested tank and tank failed. will do a helium pinpoint."

All TTF:

Facility ID:	9911365
Spill Number:	9911365
Spill Tank Test:	1547964
Site ID:	188433
Tank Number:	1
Tank Size:	4000
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	188433
Operable Unit ID:	1085978
Operable Unit:	01
Material ID:	560624
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CM992 **EXXONMOBIL** **NY LTANKS** **S104880835**
ESE **153-169 SEVENTH AVE** **N/A**
1/4-1/2 **NEW YORK, NY**
0.353 mi.
1865 ft. **Site 3 of 3 in cluster CM**

Relative:
Higher

Actual:
27 ft.

LTANKS:

Name:	EXXONMOBIL
Address:	153-169 SEVENTH AVE
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0009966 / 2003-07-11
Facility ID:	0009966
Site ID:	188430
Spill Date:	2000-12-04
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	A1
Cleanup Ceased:	Not reported

EXXONMOBIL (Continued) **S104880835**

SWIS:	3101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2000-12-04
CID:	389
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2000-12-04
Spill Record Last Update:	2003-12-11
Spiller Name:	Not reported
Spiller Company:	EXXONMOBIL
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	157383
DEC Memo:	""
Remarks:	"CALLER REPORTING A SMELL OF GAS IN THE AIR WHICH CALLER STATES HAS BEEN GOING ON FOR A COUPLE OF WEEKS UNK WHAT CAUSED THE SPILL AND UNK WHAT IS BEING DONE ABOUT IT."

All Materials:

Site ID:	188430
Operable Unit ID:	830930
Operable Unit:	01
Material ID:	543890
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

993
SSW
1/4-1/2
0.361 mi.
1906 ft.

328 WEST 12TH STREET **NY LTANKS** **S102672066**
328 WEST 12TH STREET **N/A**
MANHATTAN, NY

Relative:
Higher

Actual:
17 ft.

LTANKS:

Name:	328 WEST 12TH STREET
Address:	328 WEST 12TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9211532 / 1993-01-07
Facility ID:	9211532
Site ID:	162054
Spill Date:	1993-01-07
Spill Cause:	Tank Overfill

328 WEST 12TH STREET (Continued) **S102672066**

Spill Source:	Tank Truck
Spill Class:	C4
Cleanup Ceased:	1993-01-07
SWIS:	3101
Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	1993-01-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-01-08
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	136775
DEC Memo:	""
Remarks:	"CONTAINED ON CONCRETE SIDEWALK WHALECO TO CLEANUP"

All Materials:

Site ID:	162054
Operable Unit ID:	978506
Operable Unit:	01
Material ID:	404927
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CI994 **PRIVATE RES** **NY LTANKS** **S106702479**
SE **160 W 16TH ST** **N/A**
1/4-1/2 **NEW YORK, NY**
0.364 mi.
1923 ft. **Site 2 of 2 in cluster CI**

Relative:
Higher

Actual:
27 ft.

LTANKS:

Name:	PRIVATE RES
Address:	160 W 16TH ST
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0404859 / 2004-08-05
Facility ID:	0404859
Site ID:	317600
Spill Date:	2004-08-03

PRIVATE RES (Continued) **S106702479**

Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	D5
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2004-08-03
CID:	71
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-08-03
Spill Record Last Update:	2004-08-05
Spiller Name:	ALLAN FRY
Spiller Company:	PRIVATE RES
Spiller Address:	160 W 16TH ST
Spiller County:	001
Spiller Contact:	ALLAN FRY
Spiller Phone:	(212) 627-2317
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	255995
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO Resident put the can outside - minor event - closed"
Remarks:	"RESIDENT DISCOVERED A RUSTED GAS CAN LEAKING AN UNKNOWN AMOUNT OF FUEL. HE PUT THE CAN INTO A BOX AND PUT IT OUTSIDE. CLEAN-UP ARRANGEMENTS ARE UNKNOWN."

All Materials:

Site ID:	317600
Operable Unit ID:	888256
Operable Unit:	01
Material ID:	488837
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

995
NNE
1/4-1/2
0.368 mi.
1941 ft.

ELLIOTT HOUSES -NYCHA **NY LTANKS** **S104495199**
426 WEST 27TH ST **NY Spills** **N/A**
NEW YORK CITY, NY

Relative:
Higher

Actual:
19 ft.

LTANKS:

Name:	ELLIOTT HOUSES -NYCHA
Address:	426 WEST 27TH ST
City,State,Zip:	NEW YORK CITY, NY

ELLIOTT HOUSES -NYCHA (Continued) **S104495199**

Spill Number/Closed Date:	9602200 / 2006-02-06
Facility ID:	9602200
Site ID:	309346
Spill Date:	1996-05-15
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SWKRASZE
Referred To:	Not reported
Reported to Dept:	1996-05-15
CID:	257
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-05-15
Spill Record Last Update:	2006-02-06
Spiller Name:	FRANK OCELLO
Spiller Company:	NYCHA
Spiller Address:	250 BRAODWAY
Spiller County:	001
Spiller Contact:	SEBASTIN LOREFICE
Spiller Phone:	(212) 306-3229
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	202268
DEC Memo:	"12/14/05: This spill transferred from J.Kolleeny to S.Kraszewski. 02/06/06: This spill closed to consolidate with open spill #8908401. - SK"
Remarks:	"going to isolate and retest"

All Materials:

Site ID:	309346
Operable Unit ID:	1033758
Operable Unit:	01
Material ID:	352001
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	ELLIOTT HOUSES -NYCHA
Address:	426 WEST 27TH ST
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9002184 / 2006-02-06
Facility ID:	9002184
Site ID:	246287
Spill Date:	1990-05-25

ELLIOTT HOUSES -NYCHA (Continued) **S104495199**

Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SWKRASZE
Referred To:	Not reported
Reported to Dept:	1990-05-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-05-31
Spill Record Last Update:	2006-02-06
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	202268
DEC Memo:	"12/14/05: This spill transferred from J.Kolleeny to S.Kraszewski. 02/06/06: This spill closed to consolidate with open spill #8908401. - SK"
Remarks:	"VISIBLE LEAKS AT GAUGES & (2) MANHOLE COVERS, MANIFOLD TANKS (2) 20K FAILED HORNER EZY CHECK WITH A GROSS LEAK, WILL REPAIR & RETEST."

All TTF:

Facility ID:	9002184
Spill Number:	9002184
Spill Tank Test:	1537127
Site ID:	246287
Tank Number:	001
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

Facility ID:	9002184
Spill Number:	9002184
Spill Tank Test:	1537128
Site ID:	246287
Tank Number:	002
Tank Size:	0

ELLIOTT HOUSES -NYCHA (Continued) **S104495199**

Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	246287
Operable Unit ID:	940253
Operable Unit:	01
Material ID:	436943
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	ELLIOT HOUSES -NYCHA
Address:	426 WEST 27TH ST
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8908401 / 2017-01-25
Facility ID:	8908401
Facility Type:	ER
DER Facility ID:	202268
Site ID:	252274
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	3101
Spill Date:	1989-11-24
Investigator:	jkkann
Referred To:	Not reported
Reported to Dept:	1989-11-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-11-29
Spill Record Last Update:	2017-01-25

ELLIOTT HOUSES -NYCHA (Continued) **S104495199**

Spiller Name: MR CARTER
Spiller Company: NYCHA
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "12/14/05: This spill transferred from J.Kolleeny to S.Kraszewski. 9/22/06: Spill transferred from Kraszewski to Kann. 1/19/10: J.Kann - revised work plan received 11/17/09. WP approved 1/19/10. 9/23/10: J.kann - Quarterly Report recieved 9/01/10. 5/11/12: J.Kann - quarterly report recieved on 5/9/12. 9/6/12: J.kann - quarterly report received on 8/21/12. 1/16/13 : J.kann - 10/24/12 QR rcvd on 1/16/13. 5/21/14: J.Kann - email sent to NYCHA today stating: The Department understands that a recovery system is operating, that monthly VEFR is being performed and that quarterly monitoring is currently being done at the following five sites: Amsterdam Houses Elliott Houses Manhattanville Houses Melrose Houses Baruch Houses Since wells at these five sites have consistently (based on quarterly reports received over the past year) had no product, a sheen or less than 0.08 inch of product in their wells, the Department would like NYCHA to temporarily cease operation of the systems and VEFR at these sites. For the next 4 months, the wells must be monitored to determine if any significant recharge of product occurs. Accurate readings of product thickness must be made, which may require using the gauging method used at South Jamaica Houses on May 19, 2014. In addition, during this 4 month time period, no absorbent socks should be placed in the wells. Data from this monitoring, along with recommendations, must be included in the 2014 3rd quarter monitoring report for these sites, which is due to the Department by October 1, 2014. In the event that a significant recharge is noticed in any of the wells during these 4 months, the Department must be contacted immediately (within 72 hours of gauging). 1/24/17: J.Kann - based on review of Quarterly monitoring reports, The source of petroleum has been removed. The PRS was operated between 1998 and 2014 Free product has not been observed in the accessible monitoring wells since 2007. Since halting the PRS in 2014, free product has not been observed in the accessible monitoring wells and little free product (less than 0.25in) has been observed in the recovery wells. No petroleum related VOCs or SVOCs (listed in Table 3 of CP-51) were detected in groundwater samples collected in April 2015 from the accessible monitoring wells. As per Randy in a discussion of January 20, 2017 if less than 0.25 inches of No. 6 oil has been in on-site wells for 2+ years and contamination has been delineated all around the impacted area and there is nothing off-site and no dissolved phase in wells, spills can be closed. The Closure Letter should contain the contaminated soil clause. Spill closure email will be prepared with contaminated soil clause and sent to NYCHA "
Remarks: "20K TANK - EVERYTIME FILLED ACTIVE FLOW TAKES PLACE INTO BASEMENT THRU WALLS - ABSORBED WITH SPEEDY DRY AND TEMPORARILY TAKING TANK OUT OF SERVICE"

All TTF:
Facility ID: 8908401
Spill Number: 8908401
Spill Tank Test: 1536460
Site ID: 252274
Tank Number: Not reported
Tank Size: 0
Material: 0002

ELLIOTT HOUSES -NYCHA (Continued) **S104495199**

EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	252274
Operable Unit ID:	935780
Operable Unit:	01
Material ID:	445144
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

996
SW
1/4-1/2
0.372 mi.
1966 ft.

514 WEST END AVENUE
514 WEST AVENUE
MANHATTAN, NY

NY LTANKS **S121988592**
N/A

Relative:
Lower

Actual:
3 ft.

LTANKS:

Name:	514 WEST END AVENUE
Address:	514 WEST AVENUE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9414188 / 1995-01-26
Facility ID:	9414188
Site ID:	278357
Spill Date:	1995-01-26
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C4
Cleanup Ceased:	1995-01-26
SWIS:	3101
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1995-01-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-16

514 WEST END AVENUE (Continued) **S121988592**

Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	CASTLE OIL CO
Spiller Address:	290 LOCUST AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	226015
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks:	"TANK OVERFILL- DEFECTIVE GAUGE ON TANK - SPILLED HAS BEEN CONTAINED. WILL BE CLEANED"

All Materials:

Site ID:	278357
Operable Unit ID:	1011603
Operable Unit:	01
Material ID:	372934
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CK997 **PENSKE TRUCK LEASING CO L P** **NY LTANKS** **1000382741**
North **536 W 26TH ST** **NY Spills** **NYD101106565**
1/4-1/2 **NEW YORK, NY 10001** **RCRA NonGen / NLR**
0.377 mi. **FINDS**
1989 ft. **Site 2 of 2 in cluster CK** **ECHO**
NY MANIFEST

Relative:
Lower

Actual:
9 ft.

LTANKS:

Name:	536 WEST 26TH STREET
Address:	536 WEST 26TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9211726 / 1993-01-21
Facility ID:	9211726
Site ID:	144036
Spill Date:	1993-01-13
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1993-01-21
SWIS:	3101
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1993-01-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1993-01-14
Spill Record Last Update:	1995-03-27
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	122793
DEC Memo:	""
Remarks:	"EIR"

All TTF:

Facility ID:	9211726
Spill Number:	9211726
Spill Tank Test:	1541057
Site ID:	144036
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	144036
Operable Unit ID:	976175
Operable Unit:	01
Material ID:	405108
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	PENSKE TRUCK LEASING
Address:	536 WEST 26TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9801954 / 2018-03-28
Facility ID:	9801954

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

Facility Type:	ER
DER Facility ID:	178260
Site ID:	215150
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	1998-05-14
Investigator:	RVKETANI
Referred To:	032818 CLOSURE LETTER TO RP
Reported to Dept:	1998-05-14
CID:	281
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	2003-12-23
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-05-14
Spill Record Last Update:	2018-03-28
Spiller Name:	RICHARD SAUT
Spiller Company:	PENSKE TRUCK LEASING
Spiller Address:	536 WEST 26TH STREET
Spiller Company:	001
Contact Name:	RICHARD SAUT
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL Formerly assigned to Tomasello 4/10/2002 - Someone from Penske Truck Leasing called looking for a closure letter on this site. Sangesland spoke to him. DeMeo was on duty for the day, therefore it was assigned to DeMeo. Sangesland suggested the rep from Penske should send a copy of the original closure report to DeMeo along with a request for closure. 8/29/03 TJD Work plan approved. 12/9/03 TJD Transferred Demeo greater than greater than greater than Rommel. 1/7/04 Reviewed 12/31/03 report from GES proposing 5 additional delineation wells. Spoke to Tony Dellaria, GES, verbally approved additional well locations with the addition of one well downgradient of MW4. Letter to Penske, Route 10, Green Hills, PO Box 7635 Redding PA 19603-7635 Rommel 3/8/04 Spoke to Debra Kaplan,GES. Wells are scheduled for 3/22/04. Rommel. greater than greater than greater than 05/13/04 10:46AM greater than greater than greater than Ms. Rommel, Attached please find the Subsurface Investigation Report for the above-referenced site. The hard copy of the report was sent to you today. If you have any questions, please feel free to call Anthony Dellaria at (631) 420-5095. Thank you. greater than greater than greater than Jennifer Rommel 05/13/04 03:43PM greater than greater than greater than DEC approves the work proposed in the Subsurface Investigation Report dated 5/13/04. At the end of the three months of HIT events, please submit an evaluation of the need for a permanent recovery system. 5/17/04 Received summary, 4 mw installed. Total 8 wells. Product in MW1 and MW4 - quarterly bailing recommended. Rommel 10/14/04 Reassigned from Rommel to Sun. 10/31/04 File Update by Sun: - On 11/22/04, Sun sent a letter to Richard Saut of Penske requiring complete delineation of soil and groundwater contaminations, submittal of an Investigation Summary Report followed by a Remedial

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

Action Plan. The Department set a deadline of 12/10/04 for signing the Stipulation Agreement. The Stipulation Agreement was signed by Penske on 12/10/04 and implemented by the Department on 12/27/04. -On 12/21/04, Sun sent a letter to Richard Saut of Penske informing him that the Department has approved the Remedial Action Plan (RAP)/HypeAir Work Plan prepared by his Consultant, Groundwater & Environmental Service (GES) for the subject site; specifically two in-situ chemical oxidation events at the site via HypeAir air and Hydrogen peroxide injection system. The Department requires that due to the proximity of existing utility corridors, temperature, pH, pressure, oxidation-redox potential (ORP), conductivity and dissolved oxygen (DO) shall be monitored on all the monitoring wells. Any potential accumulation of vapors during the injection activities shall be avoided. (Sun) 02/21/06: Sun received 4th Quarter 2005 Site Status Update Report. Review of this report is pending. (Sun) 02/27/06: The Department approves the GES s request for two (2) additional injection events to be completed in April and May 2006; specifically two in-situ chemical oxidation (Chem-Ox) events at the above referenced site utilizing a hydrogen peroxide, ozone, and persulfate injection system (HypeAir). (Sun) 07/23/07-Sun: On 07/23/07 the Department approves the GES s request for performing enhanced product recovery through the injection of surfactant into MW-5. The Department also approves a series of high intensity targeted (HIT) remediation events using high vacuum extraction at monitoring wells MW-3, MW-4, and MW-5 to reduce residual hydrocarbons impacts on-site for 8-hour events for approximately four (4) months. (Sun) 08/09/07-Sun: On 7/18/07 Joe Sun of DEC was informed by Kevin Heaphy of Parson Brinckerfoff Amercica (PB) that the MTA will be using this site (Lot 60) and the adjacent Fed Ex lot for a mocking pit to build the initial shaft for Tunnel boring machine to be used for the No. 7 subway extension project. In general, the site is slated to be used as a staging area for the project. A meeting was held on 8/9/07 to discuss project among all the key parties, including DEC, MTA, NYCT, Developer, Parson Brinckerfoff (PB), Penske, property owner (Michael Silvermintz)and Penske s consultant, GES. The meeting concluded that PB will first review the GES s investigation and remediation reports and then will discuss with GES and MTA project team to assess if other viable remedial action plans (RAP) can be implemented to expedite the cleanup process. Any new proposed RAP will be submitted to DEC for review and approval. (Sun) 08/23/07-Sun: Sun received 2nd Quarter 2007 Site Status Update Report. Based on laboratory analytical results, a 64% reduction of disslved benzene, toluene, ethylbenze, and total xylenes (BTEX) concentrations has been observed on and off-site since initiating hydrogen peroxide and ozone injections at the site. (sun) 08/30/07: Sun received the following email from Heather Cloud of GES Joe, Penske and GES submitted all historical documents to Kevin Heaphy for his review. He reviewed the documents and we had a follow up call with him and the MTA this past Monday (8/27). During the call, Kevin brought up a suggestion of relocating the wells off-site or installing remote access points in the sidewalk. As discussed at the NYSDEC meeting, we told Kevin that that locating the wells offsite was not an option, and installing remote access points in the sidewalk could not be sufficient for our liquid level measurements and groundwater sampling activities. Additionally, there is a high pressure gas main in the sidewalk, so we would not be able to drill safely in this area. They did not have any additional suggestions or

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

ideas beyond relocating the wells. (Sun) Since they did not have any additional suggestions, it was decided that GES is going to proceed with our approved work plan. We are actually scheduled to conduct our surfactant injection on September 5 and the high vacuum extraction events on the 6th and 7th. Once we get the data back from the first event, we will evaluate the effectiveness and move forward from there. (Sun) 11/19/07-Sun: Sun received the following email from Heather Cloud of GES, Hi Joe, We conducted the Surfactant Injection at MW-5 on September 5, 2007 followed by a high vacuum extraction event on September 7, 2007 to remove and recover residual product at MW-5. Since conducting the injection event, we have not seen any product at MW-5. Groundwater data at MW-5 prior to the injection (July 3, 2007) was 489 ppb BTEX (144 ppb benzene). Following the injection (October 12, 2007), groundwater data at MW-5 was 87 ppb BTEX (66 ppb benzene). Since the injection event, we have conducted 2 high vacuum extraction events on MW-3 and MW-4. These events were completed in September and October. Between the 2 high vacuum extraction events, we have recovered 5 pounds of mass and 1,300 gallons of water. We were at the site today and are at the site tomorrow to complete our 3rd high vacuum extraction event on MW-3, MW-4, and MW-5. The 3rd QTR Site Status Update Report is currently being reviewed by the client, so you should have it shortly. (Sun) 02/15/08-Sun: DEc received the following email from Andrew Cullen of Penske, All, After much review, we have come to the conclusion that we will make an attemp to meet the requirements of the contractor and complete the necessary remediation work required by the NY DEC on two Saturday's per month. However, I need all the parties to understand that our agreement specifically states we need 2 to 3 days per month to perform the necessary remediation. Limiting us to only two days per month may cause the remedial efforts to go past our original estimates. Moreover, MTA also agreed to reimburse Penske for any premium costs assoicated with work that must be scheduled outside of normal working hours (i.e. Monday to Friday 8:00am to 5:00pm) . If at any time we find the contractor is not cooperating, our remedial efforts will require more than 2 days per month, or any invoices for premium costs or damage by the contractor are not paid in accordance with our agreement, we will alert the appropriate parties. I do not anticpate this happening, but given the events that have lead us to this point, I feel compelled to remind everyone of the terms and conditions of our agreement. (Sun) 03/04/08-Sun: Sun sent the following email to all the parties invloved, Penske may have to conduct remedial efforts more often than 2-3 days a month if project demands. The required frequency and nature of remedial efforts will depend on results of on-going remediation to be received in future. If current extraction method does not produce acceptable (to the NYSDEC) results, DEC reserves its rights to require Penske to undertake more aggressive remedial efforts. NYSDEC is not a party to any of the agreements between Penske and MTA, and reserves all rights under the existing Laws and Regulations. (Sun) 03/25/08-Sun: Sun received the 4th Quarter 2007 Site Status Update Report. (Sun) 07/03/08-Sun: Sun received from Heather Cloud of GES on the current site status: We are currently conducting quarterly groundwater monitoring and sampling. Our next groundwater sampling event is scheduled for this month. - Based upon the recent groundwater data, we are not seeing a reduction in the BTEX concentrations. See attached groundwater analytical tables. Therefore, the high vacuum extraction events don't appear to be overly effective at this time.

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

We are currently evaluating alternate options to address the dissolved phase impacts. We are looking at potentially injecting sodium percarbonate or other potential oxidizers. The total BTEX concentrations are primarily comprised of benzene. We have seen great success in reducing benzene levels with sodium percarbonate at other sites. Also, this type of technology is not intrusive at all. With the MTA project going on, we are limited with the technologies that we can go with. - The 1st QTR QMR is currently being reviewed by Penske. You should have this report within the next week or so. (Sun) 8/4/08 - Carlson: Case reassigned to Carlson. Reviewed 1st Quarterly 2008 report. Wells sampled on 1/3/08. Maximum BTEX concentration 5,425 ppb (MW3), maximum MTBE concentration 64 ppb (MW3). Report notes that VEFR is not effective. Sent letter requiring submission of a new RAP and additional delineation by 9/12/08. 9/11/08 - Carlson: Approved extension to 11/14/08 for submission of a new RAP. Scheduled site visit for 9/25/08 to discuss potential locations for an additional delineation well. 9/30/08 - Carlson: Performed site visit on 9/25/08. Met with Heather Cloud of GES, Richard Saut of Penske, Charles Stives of Liro Engineering, as well as representatives from MTA and NYCT. Five monitoring/remediation wells have be destroyed during recent activities. A location was identified for the installation of an additional monitoring well. RAP due 11/14/08. 10/6/08 - Carlson: Reviewed update report dated 9/23/08. Wells sampled on 4/26/08. Maximum BTEX concentration 3,537 ppb (MW3). They are pilot testing sodium percarbonate. 3/20/09 - Carlson: Reviewed Site Status Report dated 2/25/09. Delineation well discussed during 9/30/08 site visit was not installed. Destroyed wells were not replaced. Sodium percarbonate solution was injected into MW-1, MW-2, and MW-4 on 9/20/08. Wells were sampled on 10/25/08. Decreased concentrations were found in MW1 and MW2, but BTEX increased in MW4. Spoke to Heather Cloud at GES. She will submit workplan. Received Remediation and Delineation Work Plan dated 2/10/09. 4/16/09 - Carlson: Meeting held with Penske. Mark requested the addition of another boring. 4/23/09 - Carlson: Meeting held MTA. Access to most of the site not possible for 1 year because the TBM is in operation. Access to the sidewalk can be arranged. MTA will submit a construction timeline. 5/4/09 - Carlson: Received phone message from Sal McCabe - construction timeline will be submitted. 5/7/09: Received update report. Received email from Christopher Ward - mw5 has been located and will be abandoned (under future muck bin). 5/15/09 - Carlson: Received email. MW5 will be abandoned tomorrow. 7/1/09 - Carlson: Received cc of penske access request to sample wells on 7/25 7/2/09 - Carlson: Paul matthews of mta responded - requested sampling be delayed for one month. 7/2/09 - Carlson: I replied saying one month delay is ok. Construction timeline was not submitted as requested at the last meeting. 7/6/09 - Carlson: Received cc of penske access request to sample wells on 8/22/09. 9/18/09 - Carlson: Left voice message for Chris Ward to followup on case status. 11/5/09 - Carlson: Received cc of letter requesting access from MTA to sampling wells. Left voice message for Chris Ward to see if they were given access - need to get phone number for MTA contact Paul Matthews. 11/10/09 - Carlson: GES received access from MTA to sample wells. 2/12/2010: Received cc of letter from GES to MTA - access requested to sample wells on 2/20/2010. Spoke to Chris Ward. Update report will be submitted. 5/26/2010 - Carlson: Received cc of access request by GES to MTA to sample wells on 6/12/2010. 6/25/2010 - Carlson: Received cc of access request by GES to MTA to sample

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

wells on 6/12/2010. Left message for MTA Philip McGrade to followup on status of construction. 6/29/10 - Carlson: Spoke to Paul Matthews at MTA (212-616-4462). TBM is still in operation 5 days/wk 24hr/day. No construction on weekends when GES samples wells. Remedial work on Saturdays would be very difficult due to access on site. Project completion scheduled for 2013. 7/27/2010 - Carlson: Meeting held with Penske on 7/27. NYSDEC to organize meeting with MTA to discuss access/remedial plan. 8/24/2010 - Carlson: Meeting held with MTA and Penske on 8/24. Penske to reinstall wells on a weekend. Wells to be covered with roadplates. Contractor will remove roadplates prior to remedial activitiy at the site. Penske/MTA/NYSDEC to perform site visit to confirm locations of new wells. 9/22/2010 - Carlson: Site meeting held to discuss well installation locations and procedures. GES will prepared updated site plan. 3-11-11. - Breen: Consultant, GES, sent in Site Status Update Report on CD today. Heather Cloud is Operations Manager. Sarken Dressler is the Staff Hydrogeologist. Report for 9610811 is on the same CD. 6/6/12 - Carlson: Reviewed Site Status Update Report dated 4/30/12. Wells sampled on 2/25/12. Wells destroyed in 2008 were not replaced. Max BTEX only 588 in MW-4. Max MTBE only 3 ppb in MW-8. Called MTA Philip McGrade at number in file. Voice mail indicated this is not his number anymore. Left message at this number for help getting status of MTA 7-line extension project at this site. 6/8/12 - Carlson: Left message for Phil McGrade (646 252 8315) to follow up on 7 train extension project. 7/11/12 - Carlson: See new spill 1201147 at site - MTA found a diesel/#2 fuel oil in tank shaft location. Tank was removed. 9/14/12 - Carlson: Reviewed 2nd quarter 2012 update report. Existing wells show low concentrations. Destroyed wells were never replaced. Continue to followup on status of 1201147. Need to contact MTA to get status of MTA project. 11/19/12 - Carlson: Spoke to Paul Matthews at MTA - he isn't involved in project anymore. New contact is Steve Asquith 646-252-8326. Left message for Steve Asquith. 11/26/12 - Carlson: Spoke to Steve Asquith (917-217-4765). He is arranging access with Penske/GES. Send him my email address, he will cc me on correspondence with penske/GES; 11/27/12 - Carlson: Emailed Steve Asquith (sasquith@mtacc.info) - please cc me on correspondence with Penske/GES as discussed during yesterdays phone conversation. 12/11/12 - Carlson: Site meeting with Healther Cloud (GES) and Dave Mariani (Skanska). Well locations were marked out. Wells will be installed in january. 9/17/2013 - Carlson: Received FOIL request from Michael Silvermintz (michaelsilvermintz@gmail.com, 646-831-1443). Forwarded to DEC Silva for processing. 9/23/13 - Carlson: Received phone call from Steve Cambruschini - new owner will purchase this property and redevelop. They intend to sign a new stip. They plan on excavating impacted soil. He will email me for a FOIL request of file. Need to get contact info of new owner to send new stip. 10/10/13: received phone call from Christopher McMahon requesting FOIL review. Sent email to email Gloria Silva for FOIL review. Also, I requested he send me contact info for new owner so I can send new stipulation agreement. 10/28/2013 - Carlson: Reviewed 3rd Quarter 2013 Site Status Report. Monitoring wells gauged and sampled on 9/28/2013. Sheen (0.04ft) in MW-3R. Maximum BTEX concentration 1,410 ppb (MW-3R). 10/29/2013 - Carlson: Issued new Stipulation Agreement to 293 Tenth Ave. Corp, c/o Michael Silvermintz. Signed Stip due by 11/12/2013. RAWP due 30 days after effective date of the Stipulation. 2/21/14 - Carlson: Reviewed RAWP dated January 2014. Site to be excavation, dewatered, and redeveloped. Site will be excavated in

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

former tank area to 11 ft below grade (4 ft below gw table). Excavation will be dewatered in order to extend below groundwater table. Hotspots encountered will be overexcavated, to the extent feasible. Two downgradient wells will be reinstalled in southern portion of property that will not contain a basement. Endpoint samples will be collected as per DER-10. Issued approval letter. 3/31/14 - Raphael Ketani. As of today, I am taking over case management from Ms. Carlson. The contact person is Chris McMahon at Langan Engineering, River Drive Center 1, 619 River Drive, Elmwood, NJ, 07407, (201) 794-6900. The proposed development of the site is as a 7 story combined commercial and office building. 4/9/14 - Raphael Ketani. I made an unannounced site visit. The site contained triple stacked office trailers on the West 26th Street side of the site. Standing from the outside, I could see that there was a lot of activity and equipment on site from the MTA construction next door for the 7 Train tunnel construction. So, I didn't enter the bounds of the site. However, I did take pictures of the site from the outside. I could see that workers were still finishing the brick work outside the MTA building that had been constructed above the tunnel shaft. 4/10/14 - Raphael Ketani. I tried to contact Steve Asquith (917) 217-4765 of the MTA to let him know that I was the new DEC project manager, but I could only leave a message. Later, I contacted Mr. McMahon (201) 794-6900. He told me that the MTA plans to be done with their work and off of the site by the second week in May 2014. Mr. McMahon added that the new owner intended to first demolish the former Fed Ex building that is adjacent to the east of the site during July 2014. Excavation of the entire site will take place to 14 feet below grade. Endpoint samples will be taken as per the plan included in the approved RAWP. I told Mr. McMahon that Langan should follow the soil contamination as much as possible before taking endpoint samples. This way, the samples will be low or non-detect with regard to any analytes and the whole process will go smoothly. Mr. McMahon stated that groundwater was about 8 or 9 feet below grade and asked about sampling the groundwater after the MTA leaves. I told him that this wont be necessary as Langan will dig out all of the contamination below the water table. Mr. McMahon stated that the beginning of redevelopment is planned for either September or October of 2014. I asked Mr. McMahon to send me the endpoint sampling map with a cover letter describing what will take place regarding the endpoint sampling and sample processing. I added that, later, the DEC will need the letter of acceptance from the facility that will receive the soil. Also, I stated, the DEC will need a letter from the facility that will accept the contaminated water that is collected. Mr. McMahon stated that once they know where everything will go, then he will send these letters. After this point, I said, the DEC will need a schedule describing the excavating, endpoint sampling, sample processing, foundation construction and so forth. Mr. McMahon said that he will send this to the DEC. At the end of our conversation, Mr. McMahon asked about the request by the owner for a change in the Stipulation Agreement whereby Penske is let off of the hook. I told Mr. McMahon that this is something Lou Oliva, Region 2 Chief Counsel, will have to work out with Penske. With that, the conversation ended. Mr. Asquith (917) 217-4765 called me back. He said that Skanska, the construction company building the ventilation shaft, is presently cleaning up the site. They told him that they expect to be off of the site by the end of April 2014. 5/2/14 - Raphael Ketani. I reviewed the First Quarter 2014 Site Status Update Report dated 4/29/14 that

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

was submitted by GES. Groundwater sampling took place on 3/15/14 for wells MW-1, MW-2, MW-3R, MW-4, MW-6 to MW-8 and MW-10. MW-9R was not sampled as MTA equipment was over it. There was 0.02' of product in MW-3R. All of the analyses were for just BTEX. MW-1 had results from non-detect to just above the TOGS 1.1.1 standards. MW-3R had the results 660 ppb total xylenes, 913 ppb ethylbenzene, 95.5 ppb benzene, 13.1 ppb toluene. MW-4 results were 237 ppb ethylbenzene, 215 ppb benzene, 18.4 total xylenes, 10.7 ppb toluene. MW-10 had 2 non-detects and 2 very low hits. For MW-2, MW-6 to MW-8, the results were either entirely non-detect or mostly non-detect with one very low hit. MTBE varied in concentration from mostly non-detect to 8.98 ppb. Quarterly sampling is planned for June 2014. 5/19/14 - Raphael Ketani. Today I received a copy of the signed Stipulation Agreement from 293 Tenth Avenue Corporation. It was signed by Michael Silvermintz, President of the corporation, on 5/2/14. I hand delivered the Stip to the Region 2 legal division. According to the schedule in the approved Remedial Action Work Plan dated 1/24/14, the remedial activities are anticipated to take 4 months beginning in October 2014. Later, I was informed that the DEC needed the original signature page in order to make the executed Stipulation Agreement. I contacted Mr. McMahon (201) 794-6900 and asked him to have his client send the original signature page with Mr. Silvermintz' original signature as soon as possible by regular mail. Mr. McMahon agreed to do this. 6/13/14 - Raphael Ketani. The Stipulation Agreement with the original signature of the president of 293 Tenth Avenue Corporation, Mr. Silvermintz, was given to me today. 6/17/14 - Raphael Ketani. The Stipulation Agreement was submitted to the Region 2 legal division for processing. 6/23/14 - Raphael Ketani. The Stipulation Agreement was signed by Venetia Lannon, Region 2 Director, and the original was sent to Mr. Silvermintz. 8/1/14 - Raphael Ketani. I reviewed the second quarter 2014 groundwater monitoring report for the site. The document was titled Site Status Update Report and dated 7/31/14. On 6/21/14, groundwater sampling took place at 6 onsite wells. Groundwater elevations were from 6.04' bgs at MW-8 to 6.71' bgs at MW-6. Flow was to the south. The wells sampled were MW-1, 2, 4, 6, 7 and 8. Wells MW-3R, 9R and 10 were inaccessible at the time. Well MW-5 had been abandoned some time ago. The VOC results for wells MW-1, 2, 6 and 7 were entirely non-detect for BTEX and MTBE. The sample from MW-8 had hits just above and just below the TOGS 1.1.1 standards. The results for MW-4 had 260 ppb of benzene and 424 ppb of ethylbenzene. In addition, a sample was taken from IW-2R on 3/21/13 and had 3530 ppb of benzene. Why this well was not sampled again was not explained. The contamination in the groundwater at MW-4 needs to be addressed. IW-2R needs to be sampled again. Also, wells MW-3R, 9R and 10 need to be made available for sampling, given that their loss is significant as there are not many wells for sampling.
Additionally, I checked the property database ACRIS for the current ownership information. The property is still owned by 293 Tenth Avenue Corporation at 5 Rosewood Lane, Wesley Hills, NY, 10901. The property block and lot are 697 and 56. There is a UCC1 with 540 West 26th Street Property Debt Investors IIA, LLC at 10 East 53rd Street, 37th Floor, NY, NY, 10022. 8/4/14 - Raphael Ketani. A letter was sent today to Mr. Silvermintz of 293 10th Avenue Corporation. In the letter, I stated that the work plan was overdue and that 293 10th Ave was in violation of the Stip. I added that if the work plan is not received by August 22, 2014, then the Department will take legal action. 8/28/14 - Raphael Ketani. Mr. McMahon (201) 794-6900/cell

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

(201) 218-2339 had called and left a message that he wanted to talk to me about the site. I tried to return his call, but could only leave a voice message. 9/8/14 - Raphael Ketani. I spoke to Mr. McMahon (201) 794-6900/cell (201) 218-2339 today about future monitoring work at the site. He said that, right now, the owner is having trouble with the tenant of the building on the other lot. He refuses to move. So, the excavating has been pushed back to March 2015. Mr. McMahon stated that the MTA had destroyed all but two wells on the truck leasing site. He proposed that groundwater sampling be stopped as all of the contamination will be removed by the excavating. The excavating will include the areas of MW-2 and IW-2R, the two most contaminated locations. I asked Mr. McMahon whether end point samples will be taken. He said that the sides of the pit and the bottom will be sampled as per the guidance in the DEC regulations. I told him that the DEC will need manifests for all of the material that is removed. He said that we will get copies of every manifest. I told Mr. McMahon that this will be the approved plan of action for the foreseeable future. With that, the conversation ended. Later, Mr. McMahon sent me an e-mail clarifying and memorializing the excavation plan in more detail. He included 3 figures with the e-mail. 7/9/15 - Raphael Ketani. As I hadn't received any information about the spill case in some time from Mr. McMahon, I sent him an email requesting an update. Mr. McMahon sent a response email today: Progress at the site has been advancing; however, our schedule may have been a bit aggressive when we last spoke. The existing building demolition is nearing completion and we are working with the NYC TA to clear up a couple of issues regarding the building plans and the influence with their neighboring building and subway tunnel. Those issues are supposed to be resolved within the next two weeks and the site will pull their building and start construction immediately thereafter. I actually had put it in my mind to give you a heads up today or tomorrow that construction was going to begin shortly to give you a little advance notice if you were interested in visiting during construction/remediation. My client is VERY eager to start the project and has already signed a lease for 80% of the building that carries very heavy penalties for not meeting certain deadlines that are driving the project forward at this point. I am certain that barring further issues with TA that we will be mobilizing to the site within weeks. 7/10/15 - Raphael Ketani. I responded today by email to Mr. McMahon [(201) 398-4535/cell (201) 218-2339/cmcmahon@langan.com] and stated that the Department requires a report showing the work that had taken place to demolish the building, copies of all manifests for all materials that are removed from the site, copies of manifests for asbestos and asbestos contaminated material disposal - the receiving facility must be permitted for asbestos and the Department needs a copy of this permit, pictures of the demolition and excavation work, end point sample results, groundwater grab sample results (if any samples are taken), manifests for all liquids, contaminated soil and clean soil removed from the site and maps showing where the end point samples were taken. 8/20/15 - Raphael Ketani. Mr. McMahon (201) 398-4535/cell (201) 218-2339 had called and left a message yesterday and I returned his call today. He stated that preliminary construction had begun at the site. However, he stated that the building that was going to be demolished was not on or part of the spill site. It was on an adjacent property. I told him that, in this situation, he didn't need to send the Department any manifests or information regarding the

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

demolition. He added that the groundwater would be prevented from entering the site by the construction of a barrier wall around where the basement would be. A machine would be used which would auger down 10 feet below grade. The auger will have holes in it. Once the auger reaches the target depth, then concrete will be pumped down the auger and the auger withdrawn. This will leave a column of concrete. Mr. McMahon mentioned that this would be like creating a secant pile wall, except that there would be more soil left between the piles. They would auger all around the proposed basement area. Any contaminated soil and groundwater will be collected and sent to appropriate disposal sites which heat the materials as a means of disposal. I told Mr. McMahon that this sounded alright to the Department. 12/1/15 - Raphael Ketani. Melissa Ng, Senior Staff Engineer from Langan (212) 479-5490/mng@langan.com sent Ryan Piper of the Spills Unit an email requesting information regarding the site as she was writing a Phase I for another site nearby. I sent her a copy of the case notes. 12/2/15 - Raphael Ketani. Ms. Ng contacted me directly by email and requested the 1/29/14 Remedial Action Work Plan for the site. I sent her the plan. 12/11/15 - Raphael Ketani. As there have been no updates since 8/20/15, I sent an email to Mr. McMahon [(201) 398-4535/cell (201) 218-2339/cmcmahon@langan.com] requesting information regarding the demolition of the building and the excavating of the site. 6/23/16 - Raphael Ketani. As there have been no reports submitted or progress updates, I sent an email to Mr. McMahon requesting an update, soil and groundwater analytical data, disposal manifests and pictures. Mr. McMahon responded to my email. He stated the following: The majority of the material at the site has been removed in conjunction with the remedial efforts at the site associated with the foundation construction. To date, we have collected 29 post-excavation soil samples and have a single sample that remains to be collected. Of the 29 samples, we have results for 27 of them. Based on a preliminary review of the results, there have been no exceedances of the CP-51 criteria. As of today, trucking is still occurring occasionally at the site. All petroleum impacted material has been shipped to the Bayshore facility in Keasby, NJ for treatment. We have yet to receive the manifests from the foundation contractor, but they were requested last week. I anticipate that it will take a few weeks to compile them. I have provided a link below for you to access recent pictures (6/17/16) of the site and I d be happy to speak with you regarding the project. http://clients.langan.com/lph/default.aspx?postTransaction=1231963216 Mr. McMahon [(973) 560-4861/cmcmahon@langan.com] included a list of 15 pictures which were available at the internet link. Two pictures, 6801 and 6804, showed cylindrical objects sticking up in groups of 3 or 5 with some showing rebar sticking out of them. I sent an email to Mr. McMahon asking him what these structures were. He replied by email that they are concrete and steel filled caissons, which are drilled foundation elements that provide support to the building, several dozen were installed as part of the building foundation construction. The purpose of the picture is to show the waterproofing going beneath the pile caps and grade beams at the site. 9/19/2016 - Colton McPartland. Scanned paper file for DEC Raphael Ketani and placed on computer desktop for future bulk upload once naming convention is received from DEC Jane Obrecht. 9/22/16 - Raphael Ketani. I spoke to Mr. McMahon today by phone. He stated that the foundation has been constructed. Twenty three thousand cubic yards of soil was removed. The contaminated soil was taken to Bayshore for

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

burning and recycling. Thirty post-excavation soil samples were taken. The results were non-detect for VOCs with only a small number of SVOCs. The last groundwater sample was completely non-detect. Samples taken from the dewatering system were clean. Another groundwater sample will be collected very soon. Two 550 gallon tanks were removed and will be registered. Two wells will be installed outside the foundation footprint. A private school will be constructed in the lower part of the building. 2/27/17 - Raphael Ketani. As no communications nor reports had been received in many months regarding the remediation of the site, I sent an email to Mr. McMahon [(973) 560-4861/cmcmahon@langan.com] requesting the documents. A due date of 3/17/17 was set for the submission of the remediation report and the PBS registration. 4/12/17 - Raphael Ketani. I sent an email to Mr. McMahon informing him that the reports were overdue and requesting their immediate submission. Mr. McMahon called me today regarding my email today. He stated that the report was delayed because they wanted to collect a second round of groundwater samples. They did collect the samples and found that one sample had 230 ppb of benzene. So he will recommend quarterly sampling to the client. He added that he had most of the documentation for the report and that it is in draft form right now. I asked him when the DEC might receive the report. He stated that he believed Langan could send it by the end of next week. With that, the conversation ended. 6/16/17 - Raphael Ketani. As the analytical results report was never sent, I sent an email to Mr. McMahon stating that 293 Tenth Avenue Corporation was in violation of the Stipulation Agreement. I added that we required the submission of the report by June 30th, 2016 or else fines and legal action can and may be taken. 6/21/17 - Raphael Ketani. Mr. McMahon (973) 560-4900 called to apologize for not sending the analytical results report. He said that the DEC will receive the report next week. He added that the latest groundwater sample was taken on 6/6/17 from the one remaining well which is outside the secant/foundation wall. He sent me an email with the VOC and SVOC analytical results table. All of the analytical results had decreased significantly, except for benzene. It was 230 ppb in the previous sample and was now 240 ppb in the current sample. He said that he didn't understand why only benzene remained high. He added that the earlier low analytical results for benzene were due to groundwater being pumped from the site. The pumping system was turned off during late 2016 and after this the benzene concentration rose. I told Mr. McMahon that, as a result of the cessation of pumping, the water table at the well may have also risen into some more contaminated soil and, thus, more oil dissolved in the groundwater. However, I could not explain why benzene would be affected, but not the other analytes. Mr. McMahon stated that the well will be sampled 3 months from now in order to see what the long term concentration trend is. I told him that would be fine. With this, the conversation ended. 6/30/17 - Raphael Ketani. I reviewed the Langan Engineers June 2017 DRAFT Remedial Action Report. The site will be developed by constructing a 7 story tall building which will house various facilities, including a multifloor private school. Six USTs containing gasoline and diesel were removed from the site. As a deep foundation was required for the building, a deep pit was dug which included removing 219 tons of petroleum contaminated soil. Initially, a groundwater monitoring well array was installed and elevated concentrations of various analytes were detected in the samples. Site investigations took place during 2002, 2003 and 2004. Wells MW-1 to

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

MW-10 were installed both on and off site. Vacuum extraction events and LNAPL recovery took place. This resulted in the collection of 174.63 gallons of product. Injection wells IW-1 to IW-4 were installed during December 2004. Hydrogen peroxidie, ozone, sodium persulfate, sodium percarbonate and surfactant were injected from 2005 to 2008. The vacuum events were completed during 2007 and 2008 and recovered 4,827 gallons of oil contaminated groundwater. Also, 8.80 lbs. of product were collected in the vapor phase. Quarterly monitoring took place from October 2003 to March 2013. During March 2013, 12 wells were sampled. About 0.01 feet of product was found in MW-3R. BTEX was present in all of the on site water samples and in the off site sample from MW-8. LNAPL thickness varied from 0.01 feet to 0.18 feet and historically appeared in MW-1, MW-4 and MW-5 during monitoring events which took place from 2004 to 2006. The site was remediated in accordance with the January 2014 RAP. Soil and fill were excavated to 11 feet below grade. A total of 364 tons of non-hazardous soil and fill and 11,378 tons of petroleum contaminated soil and fill were removed. The materials were sent to Capital Development in Bangor, Pennsylvania and Bayshore Soil Management in Keasbey, New Jersey. Grace Preprufe 300R, Grace Preprufe 160R and Grace Bituthene 4000 vapor barrier sheeting with a minimum thickness of 20 mil was installed as part of the foundation construction. Grace Preprufe 300R vapor barrier with a thickness of 46 mil was installed beneath the cellar slab, elevator pit slab, first floor slab and on the interior of the elevator pit sidewalls. Grace Prepruf 4000 vapor barrier with a thickness of 62 mil was installed on the exterior elevator pit sidewalls. Grace Preprufe 160R vapor barrier with a thickness of 32 mil was installed on the exterior of the western foundation sidewall and Grace Bituthene 4000 vapor barrier with a thickness of 62 mil was installed on the exterior of the northern, eastern and southern foundation sidewalls. A Health and Safety Plan (HASP), Community Air Monitoring Plan (CAMP), Soil Materials Management Plan (SMMP), Stormwater Pollution Prevention Plan (SPPP) and groundwater dewatering were conducted during the remediation of the site. Utilities and easements were located prior to any invasive work. Excavated soil and fill were screened for contamination. Suspect contaminated soil was stockpiled on site and covered prior to delivery to the disposal facilities. Each dirt hauling truck was inspected for contaminated soil on the undercarriage and tires prior to leaving the site. If contaminated material was present, then it was removed before the truck entered the street. The USTs were encountered at about 7.5 feet below grade in the eastern part of the site. They were 42 inches in diameter and 87 inches long. AARCO removed the two 550 gallon gasoline USTs on 9/26/15. About 630 gallons of mixed liquid was collected and disposed of at Tyree Services Corp. in Farmingdale, NY. Residual sludge and water was drummed and taken to Triumvirate Environmental in Astoria, Queens. The USTs were cleaned and cut up and sent to TNT Scrap in Brooklyn, NY. Thirty soil end point samples (PE-1 to PE-30) were taken from the sidewalls and the bottom of the tank graves from 3/31/16 to 6/28/16. The samples were sent to York Analytical Labs for processing via methods 8260B and 8270C. The analytical results were compared to the CP-51 standards. Five groundwater dewatering samples were collected before treatment from 6/22/16 to 8/11/16 and sent to the lab. The samples were processed via methods 8260B and 8270C. On 7/27/16, two permanent monitoring wells were installed (LMW-1 and LMW-2) to the south of the southern cellar foundation and soilcrete walls. The

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

borings were drilled to 15 and 16 feet below the ground surface. Each well was constructed with a 10 foot long 10 slot screen. Post remediation monitoring was conducted using 5 onsite wells. Wells MW-6 to MW-8 were situated upgradient and across West 26th Street from the site. LMW-1 and LMW-2 were sampled on 8/11/16, 3/16/17 and 6/6/17. MW-6 to MW-8 were sampled on 6/1/17. Table 1 indicated that the results for the PE series of soil end point samples were almost entirely non-detect for VOCs and SVOCs. Table 2 showed that the influent water sample results for Discharge 1, 2 and 5 were almost entirely non-detect for VOCs and SVOCs. The results for Discharge 3 and 4 were more limited, but still showed that there were no detections. The groundwater sample results for LMW-1, LMW-2, and MW-6 to MW-8 were displayed in Table 3. LMW-1 had consistent very low to high (max. 240 ppb) analyte exceedences, but, with the exception of a sample from LMW-2 (3/16/17) and one from MW-8 (6/1/17), the VOC results for the other samples and the SVOC results for all of the samples were almost entirely non-detect. 7/6/17 - Raphael Ketani. I reviewed the Langan Engineers FINAL Remedial Action Report dated 7/5/17. The contents of the FINAL report appeared to be the same as in the DRAFT report. I approved the report without comment. 10/25/17 - Raphael Ketani. I sent an email to Mr. McMahon [(973) 560-4861/cmcmahon@langan.com requesting the latest groundwater analytical data. 12/8/17 - Raphael Ketani. I sent an email to Mr. McMahon requesting the latest groundwater data. 12/14/17 - Raphael Ketani. Mr. McMahon sent me the 12/5/17 and 12/6/17 groundwater sample analytical data for the site. Samples were taken from MW-1, MW-2, MW-6, MW-7 and MW-8. Locations MW-6 to MW-8 were upgradient and across the street to the north. MW-2 was in the southwestern quarter of the site. MW-1 was in the southeastern quarter of the site, but almost in the center of the site. The VOC exceedences for the samples from MW-2 and MW-6 to MW-8 were either none or no more than 19.2 ppb. However, the MW-1 12/5/17 sample had 10 VOC exceedences. Most of the exceedences varied from 6.3 ppb to 73.1 ppb, but benzene was 238 ppb. Mr. McMahon called me on the phone and we discussed the results. We agreed that the benzene result for MW-1 stood out. I commented that it was too high to close the case with. We looked at the historical trend for benzene from MW-1. The decreasing trend was noted. I asked Mr. McMahon whether any treatment solutions has been injected into MW-1. He stated that Langan had not done this. I told him that the Department will require that another round of groundwater sampling take place in order to see whether the decreasing trend continues and whether the benzene concentration has decreased further. He agreed to do more sampling. I also asked him to include a Kendall-Mann trend graph in the next monitoring report. With that, the conversation ended. 3/28/18 - Raphael Ketani. Yesterday, I received Table 1 and Figure 2 for the March 2018 groundwater sampling results. The samples were collected on 3/6/18 and 3/9/18. The VOC results were almost entirely non-detect for the samples from LMW-2 and LMW-6 to LMW-8. Though most of the VOC results for the sample from MW-1 were non-detect, there were still 9 exceedences of the TOGS 1.1.1 standards. The highest exceedences were for total xylenes at 63.7 ppb and benzene at 228 ppb. However, with both analytes, a decreasing concentration trend continued to be present. The SVOC results for all of the samples were almost entirely non-detect.

---------- I reviewed the case file. The information in the case file described the removal of 6 USTs and many

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

tons of oil contaminated soil in the process of digging out the site for a deep foundation. Chemical treatments to remove additional contamination also took place at various times in the past. Based upon this information and the decreasing concentration trends which were evident from the latest versions of Table 1 and Figure 2, I determined that the gross contamination had been removed. Any residual contamination would not be a threat to the public or the environment. Therefore, I closed the spill case effective today and sent a spill closure letter to Peter Rosenthal and Eric DeSimone of Savanna at 430 Park Avenue, 12th Floor, NY, NY, 10022, Mr. McMahon (cmcmahon@langan.com) and Steven Ciambruschini of Langan. "

Remarks: "CALLER RESPONDED TO ABOVE LOCATION TO REMOVE FUEL TANKS. UPON REMOVAL SOME SOIL CONTAMINATION DISCOVERED. TANKS REMOVED AND SOIL EXCAVATION IN PROGRESS. NO CALL BACK REQUESTED."

All Materials:

Site ID:	215150
Operable Unit ID:	1062495
Operable Unit:	01
Material ID:	323866
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	PENSKE TRUCK LEASING CO L P
Handler Address:	536 W 26TH ST
Handler City,State,Zip:	NEW YORK, NY 10001
EPA ID:	NYD101106565
Contact Name:	Not reported
Contact Address:	W 26TH ST
Contact City,State,Zip:	NEW YORK, NY 10001
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W 26TH ST
Mailing City,State,Zip:	NEW YORK, NY 10001
Owner Name:	293 10TH AVE CORP
Owner Type:	Private
Operator Name:	293 10TH AVE CORP

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D008
Waste Description: LEAD

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F004
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: 293 10TH AVE CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: 293 10TH AVE CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: 293 10TH AVE CORP
Legal Status: Private
Date Became Current: Not reported

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990714
Handler Name:	PENSKE TRUCK LEASING CO L P
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name:	PENSKE TRUCK LEASING CO L P
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	PENSKE TRUCK LEASING CO L P
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19861021
Handler Name:	PENSKE TRUCK LEASING CO L P
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004378307

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000382741
Registry ID: 110004378307
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004378307
Name: PENSKE TRUCK LEASING CO L P
Address: 536 W 26TH ST
City,State,Zip: NEW YORK, NY 10001

NY MANIFEST:
Name: PENSKE TRUCK LEASING CO
Address: 536 W 26TH ST
City,State,Zip: NEW YORK, NY 10001
Country: USA
EPA ID: NYD101106565
Facility Status: Not reported
Location Address 1: 536 WEST 26TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10001
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD101106565

PENSKE TRUCK LEASING CO L P (Continued) **1000382741**

Mailing Name:	PENSKE TRUCK LEASING CO
Mailing Contact:	PENSKE TRUCK LEASING CO
Mailing Address 1:	536 WEST 26TH ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10001
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2127419837

CJ998 **260 WEST 26TH STREET - DOB JOB NO. NB-120655237** **NY VCP** **S127989931**
ENE **260 WEST 26TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.380 mi.
2005 ft. **Site 2 of 3 in cluster CJ**

Relative: **Higher**
Actual: **26 ft.**

VCP NYC:

Project ID:	11TMP0246M,11EHAZ246M,11CBCP011M
Name:	260 WEST 26TH STREET - DOB JOB NO. NB-120655237
Address:	260 WEST 26TH STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Manhattan
BBL:	1.0077500041007701E+59
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed
Latitude:	40.746693
Longitude:	-73.995907
Postcode:	4
Community Board:	3
Council District:	91
Census Tract:	1088709
BIN:	1007757502
NTA:	Hudson Yards-Chelsea-Flatiron-Union Square

CN999 **771 WASHINGTON STREET** **NY VCP** **S125317203**
SSW **771 WASHINGTON STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.386 mi.
2036 ft. **Site 1 of 2 in cluster CN**

Relative: **Lower**
Actual: **12 ft.**

VCP NYC:

Project ID:	17TMP0034M,17EH-N034M,19CVCP061M
Name:	771 WASHINGTON STREET
Address:	771 WASHINGTON STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Manhattan
BBL:	1006410075
OER Program:	VCP (Withdrawn), E/RD (Review)
Phase:	Construction
Latitude:	40.737709
Longitude:	-74.00818
Postcode:	2
Community Board:	3
Council District:	79

771 WASHINGTON STREET (Continued) **S125317203**

Census Tract: 1012096
BIN: 1006410075
NTA: West Village

1000 SE 1/4-1/2 0.387 mi. 2044 ft. **APRTMENT BUILDING** **NY LTANKS** **S107416906**
161 WEST 15TH ST **N/A**
MANHATTAN, NY

Relative: Higher
Actual: 28 ft.

LTANKS:

Name:	APRTMENT BUILDING
Address:	161 WEST 15TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0508110 / 2006-01-31
Facility ID:	0508110
Site ID:	353635
Spill Date:	2005-10-06
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2005-10-06
CID:	409
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-10-06
Spill Record Last Update:	2006-01-31
Spiller Name:	CHRIS GORGA
Spiller Company:	APRTMENT BUILDING
Spiller Address:	161 WEST 15TH ST
Spiller County:	001
Spiller Contact:	CHRIS GORGA
Spiller Phone:	(646) 772-1404
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	300979
DEC Memo:	"5,000 gal #2 Oil tank failed tank test TTF letter sent to: Key Real Estate Associates LLC 116 John St. - 17th Floor New York, NY 10038-3427 Attn: Arlene Cobb (212-233-0109) NO PBS number could be found for this building: 161 West 15th St is also known as 79 7th Ave. No PBS found for either address. 12/1/05 - Raphael Ketani. I received a tank test report from Petroleum Tank Cleaners, Inc. ((718) 624-4842). It indicated that the 5,000 gal. (they state 6,000 gal.) tank passed the test, but the vent line was bad. The building owner isn't sure whether he will repair the line or remove the tank. They are requesting that the case be closed. I will send a letter telling them they have to first register the tank. 12/12/05 - Raphael Ketani. I received a call from Arlene Cobb, case manager, Key Real Estate Associates LLC, requesting an extension of the time needed to get a

APRTMENT BUILDING (Continued) **S107416906**

letter to me stating that there was no oil spill at the site. I told her I would give her 2 weeks to get me a letter from PTC stating that there are no old oil spills, no new oil spill, no impact to the soil or the environment, and no impact to any drains. She said she would get it to me. The PBS case is #2-610054. 1/4/06 - Raphael Ketani. I left a message for Ms. Cobb requesting the letter she told me she would send back on 12/12/05. 1/5/06 - Raphael Ketani. I spoke to Mr. Cobb. She said that the coop and management are still debating whether to convert to a dual fuel system (oil & gas). However, for now, the tank will remain empty and the lines disconnected. She said that the air leak during the test was in one of the lines, not the tank. She wanted the case closed. I told her to get me a letter from PTC stating what they did and that there is no contamination or impact to drains or the environment, and to submit a letter from her management company stating that they will not refill and use the system for the foreseeable future. She said she would and that she wanted a closure letter. 1/30/06 - Raphael Ketani. I received a letter from PTC stating that the vent line was the only part of the system that failed the test. With this letter and the system test results that were given to the PBS unit, I am closing this case and sending a NFA letter."

Remarks: "ABOVE LIQUID LEAK."

All TTF:

Facility ID:	0508110
Spill Number:	0508110
Spill Tank Test:	1549380
Site ID:	353635
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	353635
Operable Unit ID:	1111091
Operable Unit:	01
Material ID:	2101134
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

1001
East
1/4-1/2
0.389 mi.
2056 ft.

ANN'S SERVICE CORP
166 WEST 22ND STREET
MANHATTAN, NY

NY LTANKS
NY Spills

S102148346
N/A

Relative:
Higher

Actual:
28 ft.

LTANKS:

Name:	ANN'S SERVICE CORP
Address:	166 WEST 22ND STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9400302 / 2003-02-04
Facility ID:	9400302
Site ID:	178963
Spill Date:	1994-04-07
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1994-04-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1948-12-27
Spill Record Last Update:	2005-07-20
Spiller Name:	KEN MARKS
Spiller Company:	ANN'S CAB
Spiller Address:	161 WEST 21ST STREET
Spiller County:	001
Spiller Contact:	KEN
Spiller Phone:	(212) 929-3678
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	275891
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE refer to 9313932 & SP93529. see also 0006798, 8701597 (SP97155)."
Remarks:	""

All TTF:

Facility ID:	9400302
Spill Number:	9400302
Spill Tank Test:	1542599
Site ID:	178963
Tank Number:	Not reported
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown

ANN'S SERVICE CORP (Continued) **S102148346**

Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported
Facility ID:	9400302
Spill Number:	9400302
Spill Tank Test:	1542600
Site ID:	178963
Tank Number:	001-006
Tank Size:	550
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	01
Test Method 2:	Petro-Tite/Petro Comp
Leak Rate:	-.27
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	178963
Operable Unit ID:	997801
Operable Unit:	01
Material ID:	387623
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	160 W. 22ND STREET
Address:	166 WEST 22ND STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0006798 / 2001-01-02
Facility ID:	0006798
Site ID:	193473
Spill Date:	2000-09-08
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2000-09-08
CID:	389
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

ANN'S SERVICE CORP (Continued) **S102148346**

Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2000-09-08
Spill Record Last Update:	2005-07-20
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller County:	999
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	275891
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND Sangesland responded to the site of a reported contaminated soil location. Owner of the site is excavating what was a parking lot in order to install footings for a new building. Upon excavation, the southwest corner of the property at 160 west 22nd St was found to have petroleum contaminated soil. After contacting DEC rep Mark Tibbe, it was determined that the property directly to the south (161 west 21st st) was a taxi company with an ongoing state PIN cleanup project. Mr. Tibbe stated that the parking lot at 160 west 22nd st did have 3 monitoring wells associated with the ongoing clean up. AKRF rep Mimi Sotiriou (212-340-9790) stated that all contaminated soil would be dug out, sorted, and shipped out with manifest for proper disposal. Since the contamination was only in the extreme southwest corner of 160 west 22nd st, directly adjacent to the property line of the taxi company and within 15 feet of the remediation equipment, it was clear where the source of the contamination was from. 11/1/2000 AKRF sent a letter to DEC stating that 228.75 tons of contaminated soil was removed from the site. AKRF stated that Petroleum contaminated soil was removed from along the southwest border of the property until no petroleum-like odors were observed.... ...Soil was transported to Mt. Hope Recycling of Wharton, New Jersey Since all contaminated soil was removed from this site, this spill number was closed out. IT SHOULD BE NOTED THAT EXISTING CONTAMINATION FROM THE PROPERTY AT 161 WEST 21ST STREET MAY HAVE AN IMPACT ON THE NEW BASEMENT WALL INSTALLED ON THE SOUTHWEST CORNER OF 160 WEST 22ND STREET. Spill closed 1/2/2001 "
Remarks:	"CALLER REPORTING A SPILL OF MATERIAL FROM A POSSIBLE TANK FAILURE ODORS OF GAS ARE BEING REPORTED SPILL WAS DETECTED ON THE SOIL NO CALLBACK AND CLEAN UP CREW IS ON SCENE."

All Materials:

Site ID:	193473
Operable Unit ID:	827710
Operable Unit:	01
Material ID:	547905
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

ANN'S SERVICE CORP (Continued) **S102148346**

SPILLS:

Name:	155-161 W 21 ST/ ANNS CAB
Address:	166 WEST 22ND STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9313932 / 2006-05-25
Facility ID:	9313932
Facility Type:	ER
DER Facility ID:	275891
Site ID:	118499
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	1994-02-25
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	1994-02-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1994-02-28
Spill Record Last Update:	2006-05-25
Spiller Name:	KEN MARKS
Spiller Company:	ANN'S CAB
Spiller Address:	161 WEST 21ST STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"10/10/95: This is additional information about material spilled from the translation of the old spill file: GASOLINE ODOR. see also 8701176, 8701597 (SP97155), 9400302, 9403442, 0006798. (also addresses 160 W 22nd St, 166 W 22nd St) 3/18/04 Received phonecall from Kevin Kleaka, Impact Environmental. Excavation is planned for next Tuesday, 3/23. RAP was previously approved by M. Tibbe. DEC had requested 5day notification. Requested project manager return phonecall (631-269-8800 or cell 516-805-8892) when reassigned.(KMF) 3/22/04 Transferred from Tibbe to Foley. Rommel 3/23/04 Spoke to K. Kleaka, Impact Env. Excavation to begin tomorrow. Tanks have been out since approx 1992-1994. 3/31/05 Spoke to Scott Underhill, URS (518-378-8766). He was hired by Bank of NY to conduct a third party peer review. The bank is putting up funding for the development of the property. 4/5/05 Received update from K. Kleaka, Impact Env. In 3/04, they excavated 340tons of gasoline impacted soil. On 2/14/05, endpoint sampling from 8 locations was conducted and analyzed by 8021. On 3/15/05, additional endpoints were collected from 3 locations and analyzed by 8021. Additional excavation to mitigate residual soil contamination on the northwestern portion of the site will be conducted in 4/05. Construction of building is now to include a second sub-level which will require removing 3-5 feet of bedrock (bedrock is at 17'bgs). GW is at 11-14'bgs. 4/13/05 Spoke to K. Kleaka, Impact Env. They have excavated down to bedrock across most

ANN'S SERVICE CORP (Continued) **S102148346**

of the site. Not much water is accumulating and have not had to dewater. Will schedule site visit and discuss possible modifications to the RAP. 5/17/05 Site visit conducted with owner, Impact, URS and Bank of America. Currently chipping away at bedrock which is about 17'bgs. All soil removed. Almost no groundwater inflitration which is surprising since perched GW was detected at 11-14'bgs. Requested a water sample from the puddle in the NW corner of property. They are contemplating an ORC application. I recommended that if the GW was clean from the bedrock surface, that they not go ahead with ORC. If it is contaminated, they will do ORC pour and will need to monitor effectiveness. Well locations possible along W 21st. Inspected backyard of 166 W 22nd St which is about 8'bgs. Access for equipment, especially for bedrock drilling, would be very difficult but may be able to obtain perched gw samples. 6/6/05 Received results for three grab samples taken from the standing water on site, collected on 5/18/05. BTEX ranged from ND to 2005ppb and MTBE from 128ppb to 1080ppb. Owner requested that the ORC application be eliminated from the RAP. 6/8/05 Email to K. Kleaka and K. Lalezarian. Required that the ORC application be completed along with effectiveness monitoring. Impact to submit revised RAP. 9/9/05 Received revised RAP via email. During the period from 3/24/05 to 5/20/05, 3983 tons of petroleum impacted soil was excavated. It is expected that removal of all source materials will reduce the concentrations found on the perched watertable. However, to address the residual impacts, Impact Env. proposed ORC for bio-enhancement. It will be spread as a dry mixture and the natural formation will provide the water to activate the release. A 6mil vapor barrier and passive vent system will be installed. A MW will be installed along W 21st St. GW samples will be collected before and after the application, analyzed for VOCs and taking field measurements for DTW, pH and DO. Due to physical constraints, no wells are to be installed at 166 W 22nd St. 9/9/05 Approved revised RAP. As discussed with K. Kleaka, the ORC will be applied in a slurry in dry areas and directly mixed with accumulated water in the wet areas. 5/18/06 K. Kleaka, Impact Env, indicates a closure report will be submitted next week. 5/25/06 Reviewed site closure report. The remediation activities completed on the site included the removal and disposal of 3,982.92 tons of petroleum impacted soil and construction fill, confirmatory endpoint soil sampling, certified laboratory analysis, bio-remediation of perched groundwater, and the installation of a vapor barrier in conjunction with a passive subslab ventilation system. After detecting contaminants in soil, all soils were removed to the bedrock surface. 450lbs of ORC was introduced following the detection of VOCs on the perched groundwater. Concentrations of total VOCs in perched water ranged from 165ppb to 3556ppb. MW-1 was installed in order to monitor the effectiveness of the bio-remediation. However, the well did not produce any water and therefore could not be sampled. It appears that the actions taken are protective of human health and the environment."
Not reported

Remarks: "PARKING LOT HAS UNDERGR. STOR. TANKS AT 155 WEST 21ST - POSS. COMING FROM THERE WOULD LIKE A CALL A.S.A.P."

All Materials:

Site ID: 118499
Operable Unit ID: 995975
Operable Unit: 01
Material ID: 2106644
Material Code: 1213A

ANN'S SERVICE CORP (Continued) **S102148346**

Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	True

Site ID:	118499
Operable Unit ID:	995975
Operable Unit:	01
Material ID:	389285
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	True

Name:	166 WEST 22ND STREET
Address:	166 WEST 22ND STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	8701597 / 2003-02-04
Facility ID:	8701597
Facility Type:	ER
DER Facility ID:	275891
Site ID:	118498
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	1987-04-09
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1987-05-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-06-08
Spill Record Last Update:	2005-07-20
Spiller Name:	KEN MARKS
Spiller Company:	ANN'S CAB
Spiller Address:	161 WEST 21ST STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE / / : . CALLED FIRE DEPARTMENT - THEY SAID THAT 161 W 21ST

ANN'S SERVICE CORP (Continued) **S102148346**

STREET IS A TAXI LOT WITH GAS PUMPS. TANKS FROM PUMPSAPPARENTLY SEEPING INTO BASEMENT. transfered from Tomasello to Tibbe on 2/4/2003. 3/31/05 Refer to 8701176 & SP93529, 9313932, 9400302, 9403442, 0006798. Remediation to be completed under spill #9313932.(KMF) "

Remarks: "FIRE DEPT. SERVED VIOLATION ORDER AT SPILL ADDRESS. HAVE ORDERED SPILLER TO RECOVER OIL GAS THATS LEAKING INTO BASEMENT OF 166 WEST 122ND ST"

All Materials:

Site ID:	118498
Operable Unit ID:	908065
Operable Unit:	01
Material ID:	471521
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	ANN'S SERVICE STATION
Address:	166 WEST 22ND STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	8701176 / 1987-05-13
Facility ID:	8701176
Facility Type:	ER
DER Facility ID:	275891
Site ID:	260722
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	3101
Spill Date:	1987-05-12
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	1987-05-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Affected Persons
Cleanup Ceased:	1987-05-13
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1987-05-20
Spill Record Last Update:	2005-07-21
Spiller Name:	Not reported
Spiller Company:	ANN'S SERVICE STATION
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"3/31/05 See other closed spills # 8701597, 9400302, 9407639,

ANN'S SERVICE CORP (Continued) **S102148346**

0006798. Remediation to be completed under spill #9313932.(KMF)"
Remarks: "SPLIT ELBOW OFF FILL LINE HEADER. FUMES IN THE AREA. OWNER CALLED ALVIN PETROLEUM TO TEST IT."

All Materials:
Site ID: 260722
Operable Unit ID: 905668
Operable Unit: 01
Material ID: 471132
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

Name: COMMERCIAL BLDG
Address: 166 WEST 22ND STREET
City,State,Zip: MANHATTAN, NY
Spill Number/Closed Date: 9403442 / 2003-04-14
Facility ID: 9403442
Facility Type: ER
DER Facility ID: 275891
Site ID: 122493
DEC Region: 2
Spill Cause: Unknown
Spill Class: B3
SWIS: 3101
Spill Date: 1994-05-10
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 1994-06-10
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Citizen
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: True
Remediation Phase: 0
Date Entered In Computer: 1994-07-20
Spill Record Last Update: 2005-07-20
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 10/10/95: This is additional information about material spilled from the translation of the old spill file: GASOLINE ODOR. REFER TO 9313931 & SP93529"
Remarks: "CITIZEN SMELL GASOLINE ODOR IN THE 2ND FLOOR AND A TAXICAB COMPANY NEXT TO THE BUILDING IS REMOVING GASOLINE TANK FROM THE GROUND.

ANN'S SERVICE CORP (Continued) **S102148346**

PETROLEUM CONTAMINATION IS NOTED AT THE TANK EXCAVATION. STAIN CITED"

All Materials:

Site ID:	122493
Operable Unit ID:	1000563
Operable Unit:	01
Material ID:	383618
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CO1002 **1 BANK ST/CASTLE COAL** **NY LTANKS** **S102671273**
SSE **1 BANK STREET** **NY AST** **N/A**
1/4-1/2 **NEW YORK, NY**
0.390 mi.
2057 ft. **Site 1 of 3 in cluster CO**

Relative: **Higher**

Actual: **26 ft.**

LTANKS:

Name:	1 BANK ST/CASTLE COAL
Address:	1 BANK STREET
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	8801019 / 1988-05-13
Facility ID:	8801019
Site ID:	161089
Spill Date:	1988-05-02
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Not reported
Cleanup Ceased:	1988-05-13
SWIS:	3101
Investigator:	JCGRATHW
Referred To:	Not reported
Reported to Dept:	1988-05-03
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-05-05
Spill Record Last Update:	1988-05-17
Spiller Name:	Not reported
Spiller Company:	CASTLE COAL & OIL COMPANY
Spiller Address:	1724 EASTCHESTER ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	136003

1 BANK ST/CASTLE COAL (Continued) **S102671273**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GRATHWOL "
Remarks: "SPILL WENT DOWN STREET TO GRENWICH AVE."

All Materials:
Site ID: 161089
Operable Unit ID: 916495
Operable Unit: 01
Material ID: 554793
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 55.00
Units: G
Recovered: 55.00
Oxygenate: Not reported

AST:
Name: 1 BANK ST.
Address: 1 BANK ST.
City,State,Zip: NEW YORK, NY 10014
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-304867
Program Type: PBS
UTM X: 584263.73636
UTM Y: 4510059.73308
Expiration Date: 07/14/2022
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 13910
Affiliation Type: Facility Owner
Company Name: 1 BANK STREET CORP.
Contact Type: PROPERTY MANAGER
Contact Name: MARIA C. GUEVARA
Address1: 415 FIFTH AVE, 2ND FLOOR
Address2: Not reported
City: PELHAM
State: NY
Zip Code: 10803
Country Code: 001
Phone: (914) 999-3121
EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2018-05-09

Site Id: 13910
Affiliation Type: Mail Contact
Company Name: DIRECT PROPERTY MANAGEMENT LLC
Contact Type: Not reported
Contact Name: MARIA C. GUEVARA
Address1: 415 FIFTH AVE., 2ND FLOOR
Address2: Not reported

1 BANK ST/CASTLE COAL (Continued) **S102671273**

City:	PELHAM
State:	NY
Zip Code:	10803
Country Code:	001
Phone:	(914) 999-3121
EMail:	MGUEVARA@DIRECT-MGMT.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-05-09

Site Id:	13910
Affiliation Type:	Facility Operator
Company Name:	1 BANK ST.
Contact Type:	Not reported
Contact Name:	RAMON ORTEGA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 532-9214
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-05-09

Site Id:	13910
Affiliation Type:	Emergency Contact
Company Name:	1 BANK STREET CORP.
Contact Type:	Not reported
Contact Name:	MARIA GUEVARA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 942-3551
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-05-09

Tank Info:

Tank Number:	001
Tank Id:	16285
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None

1 BANK ST/CASTLE COAL (Continued) **S102671273**

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/05/1950
Capacity Gallons:	6000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	05/09/2018
Material Name:	#4 fuel oil (on-site consumption)

CJ1003 **HAG REALITY** **NY LTANKS** **S103824384**
ENE **250 WEST 26TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.391 mi.
2065 ft. **Site 3 of 3 in cluster CJ**

Relative: **Higher**
Actual: **27 ft.**

LTANKS:

Name:	HAG REALITY
Address:	250 WEST 26TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9813015 / 2004-05-20
Facility ID:	9813015
Site ID:	65132
Spill Date:	1999-01-22
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	CESAWYER
Referred To:	Not reported
Reported to Dept:	1999-01-22
CID:	382
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-22
Spill Record Last Update:	2004-05-20
Spiller Name:	GARY SPINDLER
Spiller Company:	HAG REALITY
Spiller Address:	250 WEST 26TH ST

HAG REALITY (Continued) **S103824384**

Spiller County:	001
Spiller Contact:	GARY SPINDLER
Spiller Phone:	(212) 233-0924
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	62614
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 3/11/03 - SAMUEL- File available in active unassigned spill files. 10/16/03 1231 Hrs - Sawyer - Received a fax from the management company a Gary Spindler of Park It Management but it only included an estimate to do the work. 11/25/03 - Sawyer - Called Gary again and ask for the manifest for disposal or some other receipt or ticket to show that the work was done. 4/14/03 - Sawyer - Talked to Ray at PTC and he said they were there only to pump out and clean the tank, but I know from O'Dowd notes that they also did initial cleanu up of the tank room. Also talked to a Danny at DC Environmental about work done at the address. 5/20/04 - Sawyer - Danny at Don Carlo forwarded the documentation on the removal of one 3000 gallon fuel oil AST. No further Action. Closed."
Remarks:	"PROBLEM WITH THE TANKS VALVES. COMPANY WILL BE CLEANING UP."

All Materials:

Site ID:	65132
Operable Unit ID:	1073450
Operable Unit:	01
Material ID:	313287
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CP1004 **28TH UNDER HIGHLINE ASSOCIATES LLC** **NY LTANKS** **S106703590**
North **505 W 27TH ST** **NY MANIFEST** **N/A**
1/4-1/2 **NEW YORK, NY 10001**
0.394 mi.
2082 ft. **Site 1 of 3 in cluster CP**

Relative:
Higher

Actual:
15 ft.

LTANKS:

Name:	CENTRAL IRON
Address:	505 WEST 27TH STREET
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	9109614 / 2003-12-15
Facility ID:	9109614
Site ID:	172881
Spill Date:	1991-12-10
Spill Cause:	Tank Overfill
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1991-12-10

28TH UNDER HIGHLINE ASSOCIATES LLC (Continued) **S106703590**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-12-13
Spill Record Last Update:	2003-12-15
Spiller Name:	Not reported
Spiller Company:	CENTRAL IRON
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	145487
DEC Memo:	""
Remarks:	"2-550 GAL TANKS/500 HEATING OIL."

All Materials:

Site ID:	172881
Operable Unit ID:	959724
Operable Unit:	01
Material ID:	570445
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Name:	28TH UNDER HIGHLINE ASSOCIATES LLC
Address:	505 W 27TH ST
City,State,Zip:	NEW YORK, NY 10001
Country:	USA
EPA ID:	NYR000232488
Facility Status:	Not reported
Location Address 1:	505 W 27TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10001
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000232488
Mailing Name:	28TH UNDER HIGHLINE ASSOCIATES LLC
Mailing Contact:	28TH UNDER HIGHLINE ASSOCIATES LLC
Mailing Address 1:	60 COLUMBUS CIRCLE

28TH UNDER HIGHLINE ASSOCIATES LLC (Continued) **S106703590**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10023
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	08/17/2017
Trans1 Recv Date:	08/17/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/17/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000232488
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	017043971JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	42760
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	D008
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CL1005 **CLOSED-LACKOF RECENT INFO** **NY LTANKS** **S100167612**
NNE **303 9TH AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.396 mi.
2090 ft. **Site 2 of 2 in cluster CL**

Relative:
Higher

Actual:
22 ft.

LTANKS:

Name:	CLOSED-LACKOF RECENT INFO
Address:	303 9TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8807152 / 2003-03-05
Facility ID:	8807152
Site ID:	67824
Spill Date:	1988-11-29
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	1988-11-29
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-11-29
Spill Record Last Update:	2003-03-19
Spiller Name:	Not reported
Spiller Company:	DEPT OF HEALTH CENTER
Spiller Address:	303 9TH AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	64752
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ADMIN.CLOSED 03/05/2003- Closed Due To The Nature / Extent Of The Spill Report"
Remarks:	"TANK FAILED WITH A LEAK RATE OF -.318GPH, WILL EXCAVATE & ISOLATE. CLOSED DUE TO LACK OF ANY RECENT INFO- DOES NOT MEET ANY CLEAN UP REQUIREMENTS."

All TTF:

Facility ID:	8807152
Spill Number:	8807152
Spill Tank Test:	1534940
Site ID:	67824
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported

CLOSED-LACKOF RECENT INFO (Continued) **S100167612**

Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	67824
Operable Unit ID:	922484
Operable Unit:	01
Material ID:	455497
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

1006
SSW
1/4-1/2
0.400 mi.
2111 ft.

393 WEST 12TH ST
393 WEST 12TH ST
MANHATTAN, NY

NY LTANKS **S102399190**
N/A

Relative:
Lower

Actual:
8 ft.

LTANKS:

Name:	393 WEST 12TH ST
Address:	393 WEST 12TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9606714 / 2007-09-10
Facility ID:	9606714
Site ID:	236242
Spill Date:	1996-08-26
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	hrpatel
Referred To:	Not reported
Reported to Dept:	1996-08-26
CID:	365
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1996-08-26
Spill Record Last Update:	2007-09-10
Spiller Name:	VIC
Spiller Company:	A&L AUTO RENTAL SERV. INC
Spiller Address:	393 WEST 12TH ST

393 WEST 12TH ST (Continued) **S102399190**

Spiller County:	001
Spiller Contact:	VIC
Spiller Phone:	(212) 242-0044
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	194620
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL C 3/11/03 - SAMUEL- File available in active unassigned spill files. 03/26/04 - Reassigned from Samuel to Rommel 08/26/05 - Follup letter sent to property owner to address a TTF at the site. It has also been discovered that there is a property transfer in the works and that ATC is the consulting firm handling any environmental work at the site. Therefore, a copy of the spill report and the Region 2 form letter was sent to the ATC project manager for his reference. 8/31/05 - ATC is doing work at the site and believes the tank was removed. A geophysical investigation was performed. The investigation located the remnants of a filler pipe but found no tank. A patch of pavement was observed consistent with the removal of a 500 gal tank. Three borings (one up gradient, two down gradient) were performed and samples taken. ATC asked that an NFA letter be sent based on the analytical results coming back negative for contamination. A letter report would be submitted stating results and concludions. 11/8/05 - No letter report has been recieved so ATC was contacted. Contamination had been detected in one of the borings so no report was sent. The work plan calls for expanding the investigation once the building on site is demolished which should occur in January or February of 2006. At that point additional borings are to be performed to determine the extent of the contamination and subsequent remedial actions will be proposed. 08/18/2006 - IABEILBY: Contacted ATC PM (Jason Hayes, 212-479-5427) to inquire about status of investigation. He stated that further demolition was planned for the site and that the investigation could continue at that point. He was informed that any further contact with the department should be directed to the Region 2 office. NEXT STEP: follow up with consultant to ascertain progress. 8/28/2007 Sangesland spoke to rep from Langan Engineering. He says they have finished work on the site (excavation?endpoints?) He would like to submit a closure report for final review. Case reassigned to Kumar Patel. 08/28/07-Hiralkumar Patel. received message from Jason Hayes from Langan engineering. they excavated contamiated soil during site development and report is ready. Mr. Hayes asked for address to send report. Jason Hayes Langan Engineering Ph. (212) 479-5427 email: jahayes@langan.com sent email to Mr. Hayes requiring submission of closure report alongwith investigation report, that was done in 2005 and during that time found contaminated soil. 08/29/07-Hiralkumar Patel. received email from Mr. Hayes. he mentioned that there was no report produced for investigation work done in 2005. he will include description and analyticals of that work in closure report. 09/10/07-Hiralkumar Patel. received closure report from Mr. Hayes. abstract: - 550 gal gasoline UST that was failed the tightness test was removed at some point between 1996 and 2005 <--------- - depth to groundwater at teh site is estimated at approx. 8 ft bg and presumable flows northwest-west towards the nearby Hudson river - found concrete patch in building (could be UST location), staining on conrete, a sump in the southwest corner and a centrally located floor drain, during 2005 Phase I - site was in use as auto garage in past - Langan performed a GPR survey on Aug. 26, 2005 and did not reveal evidence of USTs -

393 WEST 12TH ST (Continued) **S102399190**

rectangular concrete patched-area was identified along the southern site boundry near the sidewalk, a disconnected fill line was traced from the sidewalk to the potential UST area - fil port in the siewalk is filled with concrete - completed 8 direct-push soil borings at the site - borings were advanced to 10 ft bg - 3 mud-rotary borings were completed as part of a Geotechnical investigation - nine soil samples were collected: one sample from each of geoprobe borings, and one sample from a geotechnical boring (B2) - soil samples were collected from 4 to 10 ft bg - no staining, odor or elevated PID readings were observed in the soil samples with the exception of one soil sample at location E4 - boring E4, adjacent to a sump in the southwest corner of the site, staining and petroleum odor were observed at approx. 9 ft bg - PID readings for boring E4 were observed upto 60 ppm - fill material extended to an approx. depth ranging from 6 ft to 9 ft bg - excavated impacted soil to an approx. depth of 10 ft bg - 4 endpoint samples were collected: one sidewall sample from east, west and north sidewalls and one bottom sample - sidewall samples were collected at approx. 6 inches above the base of the excavation area, approx. 9 ft bg - base sample was collected from a depth of approx. 10 to 10.5 ft bg - sample was not collected from the south sidewall due to the presence of an foundation wall at the southern site border - area of final excavation was approx. 610 sq.ft. with depth of 10 ft bg - groundwater was encountered at approx. 10 ft bg - 220 tons of petroluem impacted soil was removed - found SVOC contamination in sample E2 during 2005 investigation. sample was taken at depth of 3.5-4.5 ft bg. no contamination found in sample E4 where they found heavy PID (60 ppm) - no contamination found in endpoint samples report doens't have information about location of dispenser island and any investigation along old fill line. spoke with Mr. Hayes. he mentioned that they did GPR survey in entire site and didn't found any area that could be location of dispenser island. as per Mr. Hayes, this small gasoline tank was in use to fill up cars under repair and dispeser point could be right on tank. he also mentioned that previous boring E1 was at point where suspected fill line ends inside building and from that point to fill port, fill line runs about 10 ft under sidewalk. no contamination was found in E1. discuss with DEC Austin. based on submitted report, he asked to close the case. case closed."

Remarks: "test = air pressure at 5lbs they discontinued test, they are underground tanks"

All TTF:

Facility ID:	9606714
Spill Number:	9606714
Spill Tank Test:	1544705
Site ID:	236242
Tank Number:	Not reported
Tank Size:	550
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	99
Test Method 2:	Alternate Test per former 613.5(a)(2)(v)
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills

393 WEST 12TH ST (Continued) **S102399190**

Last Modified Date: Not reported

All Materials:
Site ID: 236242
Operable Unit ID: 1034517
Operable Unit: 01
Material ID: 345981
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

1007
NNW
1/4-1/2
0.410 mi.
2163 ft.

201 11TH AVE/MANH/USPS **NY LTANKS** **S100167779**
201 11TH AVENUE **N/A**
NEW YORK CITY, NY

Relative:
Lower

Actual:
4 ft.

LTANKS:
Name: CLOSED-LACKOF RECENT INFO
Address: 201 11TH AVENUE
City,State,Zip: NEW YORK CITY, NY
Spill Number/Closed Date: 8908706 / 2003-03-04
Facility ID: 8908706
Site ID: 131667
Spill Date: 1989-11-27
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: A3
Cleanup Ceased: Not reported
SWIS: 3101
Investigator: ADMIN. CLOSED
Referred To: Not reported
Reported to Dept: 1989-12-04
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1989-12-07
Spill Record Last Update: 2005-11-04
Spiller Name: Not reported
Spiller Company: U S POSTAL SERVICE
Spiller Address: JAMES A FARLEY BLDG
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2

201 11TH AVE/MANH/USPS (Continued) **S100167779**

DER Facility ID: 113443
DEC Memo: ""
Remarks: "4K TANK, SYSTEMS TEST, FAILED VPLT WITH A LEAK RATE OF -.244GPH, WILL EXCAVATE, ISOLATE & RETEST. CLOSED DUE TO LACK OF ANY RECENT INFO - DOES NOT MEET ANY CLEANUP REQUIREMENTS. "

All TTF:
Facility ID: 8908706
Spill Number: 8908706
Spill Tank Test: 1536509
Site ID: 131667
Tank Number: Not reported
Tank Size: 0
Material: 0009
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 131667
Operable Unit ID: 933752
Operable Unit: 01
Material ID: 441896
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: Not reported

Name: 201 11TH AVE/MANH/USPS
Address: 201 11TH AVENUE
City,State,Zip: NEW YORK CITY, NY
Spill Number/Closed Date: 9005469 / 1990-05-11
Facility ID: 9005469
Site ID: 131668
Spill Date: 1990-08-17
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Not reported
Cleanup Ceased: 1990-05-11
SWIS: 3101
Investigator: BATTISTA
Referred To: Not reported
Reported to Dept: 1990-08-17
CID: Not reported
Water Affected: Not reported

201 11TH AVE/MANH/USPS (Continued) **S100167779**

Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-08-20
Spill Record Last Update:	1990-10-16
Spiller Name:	Not reported
Spiller Company:	USPS
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	113443
DEC Memo:	""
Remarks:	"GASKET ON TANK IS LEAKING,SMALL AMOUNT OF CONTAMINATED SOIL, WILL EXPOSE & REPAIR TANK & CLEAN UP, TYREE BROS TO DO WORK."

All Materials:

Site ID:	131668
Operable Unit ID:	943005
Operable Unit:	01
Material ID:	436510
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

1008 **226 WEST 26TH STREET** **NY LTANKS S102673064**
ENE **226 WEST 26TH STREET** **NY Spills N/A**
1/4-1/2 **MANHATTAN, NY**
0.413 mi.
2179 ft.

Relative: **Higher**

Actual: **28 ft.**

LTANKS:

Name:	226 WEST 26TH STREET
Address:	226 WEST 26TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9510264 / 1995-11-16
Facility ID:	9510264
Site ID:	147988
Spill Date:	1995-11-16
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1995-11-16

226 WEST 26TH STREET (Continued) **S102673064**

CID:	216
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-11-16
Spill Record Last Update:	2003-04-15
Spiller Name:	ANTHONY PUMA
Spiller Company:	EMPIRE STATE FUEL OIL
Spiller Address:	1640 MCDONALD AVE
Spiller County:	001
Spiller Contact:	UNKNOWN
Spiller Phone:	(718) 252-0126
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	125971
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE CLEANED BY RP. SEE ALSO 9510269."
Remarks:	"OIL COMPANY WENT TO WRONG LOCATION AND CAUSED A SPILL IN WHICH THEY HAVE CLEANED UP NO NEED FOR DEC TO CALL USED SPEEDY DRY AND PADS UPDATED FORM BY #198"

All Materials:

Site ID:	147988
Operable Unit ID:	1020805
Operable Unit:	01
Material ID:	566954
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	G
Recovered:	4.00
Oxygenate:	Not reported

Name:	226 WEST 26TH STREET
Address:	226 WEST 26TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9510269 / 1995-11-16
Facility ID:	9510269
Site ID:	147989
Spill Date:	1995-11-16
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1995-11-16
CID:	216
Water Affected:	Not reported
Spill Notifier:	Local Agency

226 WEST 26TH STREET (Continued) **S102673064**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-11-16
Spill Record Last Update:	2003-04-15
Spiller Name:	MR PUMA
Spiller Company:	EMPIRE STATE FUEL CO
Spiller Address:	UNKNOWN
Spiller County:	001
Spiller Contact:	EMPIRE STATE
Spiller Phone:	(718) 627-5100
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	125971
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE REFER TO 9510264. "
Remarks:	"THIS SPILL WAS ALREADY CALLED IN 9510264 NOTE QUITE A CHANGE IN WHAT THE SPILLER REPORTED THIS AGENCY REPORTING REQ A SECOND SPILL NUMBER TO COVER THE CHANGE . "

All Materials:

Site ID:	147989
Operable Unit ID:	1024741
Operable Unit:	01
Material ID:	361196
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	150.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	226 WEST 26TH STREET
Address:	226 WEST 26TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0212338 / 2004-06-04
Facility ID:	0212338
Facility Type:	ER
DER Facility ID:	125971
Site ID:	147987
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3101
Spill Date:	2003-03-15
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2003-03-15
CID:	204
Water Affected:	Not reported
Spill Source:	Commercial/Industrial

226 WEST 26TH STREET (Continued) **S102673064**

Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-03-15
Spill Record Last Update:	2004-06-04
Spiller Name:	PAUL SANO
Spiller Company:	K C TRANSPORTERS
Spiller Address:	734 FRANKLIN AVE #131
Spiller Company:	001
Contact Name:	PAUL SANO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 3/15/03 #4 OIL SPRAYED THROUGH CRACKED VENT LINE ONTO SIDEWALK AND INTO AUDIO/VIDEO STUDIO IN BASEMENT, CLEANUP BEGAN BY KC PAUL SANO EASTMAN PICKED UP DEBRIS FROM SPILL SITE FOR DISPOSAL. 7/14/03 REQUEST FOR SPILL CLOSURE WITH NO DOCUMENTATION FROM MICHELE pERTESIS CRAWFORD BODINE COMPANY/ TIPPLE LEFT A MESSAGE ON MS. PERTESIS'S MACHINE INDICATING DISPOSAL MANIFESTS/ PROPER DOCUMENTATION WAS NECESSARY TO CLOSE THE SPILL. 6/4/04 tipple updating// spoke to impacted party, cleanup satisfactory//eastmond removed and disposed of contaminated debris.//nfa"
Remarks:	"CRACKED FILL LINE "

All Materials:

Site ID:	147987
Operable Unit ID:	865795
Operable Unit:	01
Material ID:	560105
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	STREET
Address:	226 WEST 26TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9709329 / 1997-11-12
Facility ID:	9709329
Facility Type:	ER
DER Facility ID:	125971
Site ID:	204891
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	1997-11-11
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1997-11-11
CID:	370

226 WEST 26TH STREET (Continued) **S102673064**

Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-11-11
Spill Record Last Update:	1997-12-09
Spiller Name:	CALLER
Spiller Company:	EMPIRE STATE FUEL OIL CO
Spiller Address:	1640 MCDONALD AVENUE
Spiller Company:	001
Contact Name:	ABOVE CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE SMALL AMOUNT OF OIL. CLEANED BY OIL COMPANY. "
Remarks:	"2 inch hose reel malfunction spill to pavement spill contained cleanup crew enrout"

All Materials:

Site ID:	204891
Operable Unit ID:	1052400
Operable Unit:	01
Material ID:	327682
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	CONSTRUCTION SITE
Address:	226 WEST 26TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9913311 / 2003-03-04
Facility ID:	9913311
Facility Type:	ER
DER Facility ID:	125971
Site ID:	288508
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	2000-02-23
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	2000-02-24
CID:	257
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

226 WEST 26TH STREET (Continued) **S102673064**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-24
Spill Record Last Update:	2003-03-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	INSP RASMUSSEN
DEC Memo:	""
Remarks:	"product is seeping out of the ground"

All Materials:

Site ID:	288508
Operable Unit ID:	1087842
Operable Unit:	01
Material ID:	295170
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CP1009 **10TH AVE. W 27/W 28 ST. G** **NY LTANKS** **S102671142**
NNE **303 10TH AVE** **NY Spills** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.414 mi.
2187 ft. **Site 2 of 3 in cluster CP**

Relative:
Higher

Actual:
16 ft.

LTANKS:

Name:	10TH AVE. W 27/W 28 ST. G
Address:	303 10TH AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8606807 / 1987-02-05
Facility ID:	8606807
Site ID:	225246
Spill Date:	1987-02-05
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	1987-02-05
SWIS:	3101
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	1987-02-05
CID:	Not reported
Water Affected:	UNK
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True

10TH AVE. W 27/W 28 ST. G (Continued) **S102671142**

Remediation Phase:	0
Date Entered In Computer:	1987-02-10
Spill Record Last Update:	2004-12-14
Spiller Name:	Not reported
Spiller Company:	RGR
Spiller Address:	SPILL
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	220188
DEC Memo:	"See PIN 4169, spills #8302630, 9410209, 9410208, 8605682."
Remarks:	"HOPEFULLY THEY WILL START TO CLEAN IT UP. NOTIFIER LT.MC GOVERN NYFD 212-570-4261"

All Materials:

Site ID:	225246
Operable Unit ID:	904394
Operable Unit:	01
Material ID:	472363
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	303 10TH AVE
Address:	303 10TH AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8605682 / 1986-12-05
Facility ID:	8605682
Site ID:	256335
Spill Date:	1986-12-04
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	1986-12-05
SWIS:	3101
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1986-12-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-01-08
Spill Record Last Update:	2005-01-03
Spiller Name:	Not reported
Spiller Company:	UNK NAMED GAS STATION

10TH AVE. W 27/W 28 ST. G (Continued) **S102671142**

Spiller Address:	303 10 AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	220188
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was 10/10/95: This is additional information about material spilled from the translation of the old spill file: POTEN SPILL. See PIN 4169, spills #8302630,8606807,9410208,9410209."
Remarks:	"@"

All Materials:

Site ID:	256335
Operable Unit ID:	902641
Operable Unit:	01
Material ID:	474849
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1000.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	M&L WESTSIDE AUTO REPAIR
Address:	303 10TH AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8302630 / 2007-04-23
Facility ID:	8302630
Facility Type:	ER
DER Facility ID:	220188
Site ID:	270444
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	3101
Spill Date:	1984-05-09
Investigator:	JBVOUGHT
Referred To:	SIR DUE 07/22/06 (PIN JOB)
Reported to Dept:	1984-05-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1986-06-10
Spill Record Last Update:	2007-04-24

10TH AVE. W 27/W 28 ST. G (Continued) **S102671142**

Spiller Name:	Not reported
Spiller Company:	ALEX GOFFMAN
Spiller Address:	303-309 10TH AVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"09/25/95: PIN-4169 - ASSIGNED TO CHRIS FOR TRACKING PURPOSES. 10/6/03 See also PIN 4169, spill #s 8605682, 8606807, 9410208, 9410209. 1/8/04 Reassigned from Tomasello to K Foley. 06/20/06: Re-assigned from Foley to Yau. (Yau) 06/22/06: Prepared and sent an old spill letter to property owner through certified mail. A site investigation report (SIR) is expected to be due on 07/22/06. (Yau) 06/27/06: Owner called to inquire about the spill. Stated that he brought the property recently (around 2002) and had no idea where is the spill was. Told him that DEC will look into it and call him back with the exact location of the spill. (Yau) 08/02/06: Owner called to request an update to the site. Told him that a review is underway. Found that DEC had a PIN job for this site. Unsure whether the cleanup is complete. If the cleanup is incomplete, the owner might have to re-do the cleanup. Will call owner back as soon as review is completed. (Yau) 10/16/06 Reassign from Yau to Chanda (Chanda) 12/12/06-Vought-Spill reassigned from DEC Chanda to DEC Vought. 03/20/07-Vought-File review by Vought: See also open spill #0603967 at same location. Videotape-unknown date (circa 19884)-tape showing well being bailed with free product thickness of 1 . Registered CSL Letter sent by DEC Yau to Tenth Gas Inc (address as per Property Shark). FOIL request from Brinkerhoff-8/18/06. Vought called AG Bechard for status of PIN case. PIN case assigned to AG John Nyhoff. Vought called Nyhoff and left message to return call. 3/20/07-Vought-See also closed spill numbers: 8605682, 9410208, 9410209 and 8302630(Open pin #). Vought spoke to DEC Krimgold who is preparing Consent Order for PBS violations and requested to add remedial requirements. Conference call with DEC Urda, AG Nyoff and AG Riggi showed that approximately 354K still owed to AG for past cleanup costs. Due to same ownership (Citigas) prior costs may be included in Consent Order. Vought submitted CAP for below requirements to DEC Urda. Riggi and Nyhoff also approved submission of Final ISR and closure of spill as any new funds spent by the DEC need a new PIN number since settlement already reached with old responsible party. Vought called Snyder, summarized consent order and left message to return call. 03/21/07-Vought-Left message for AG Nyhoff to call Vought with status of PIN. Vought and DEC Urda spoke with AG Nyoff and as per Nyoff default judgement was made against former owner of property resulting in lean of approximately 354K. 3/26/07-Vought-Received ISR from Nyoff. Vought left message for Nyoff to return call with which party was found responsible (Alex Goffman or Westside Tripple Auto Repair). 4/23/07-Final ISR submitted to DEC Austin for review and spill closed by Vought. "
Remarks:	""

All Materials:

Site ID:	270444
Operable Unit ID:	894766
Operable Unit:	01
Material ID:	481492
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum

10TH AVE. W 27/W 28 ST. G (Continued) **S102671142**

Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	M&L WESTSIDE AUTO REPAIR
Address:	303 10TH AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8302630 / 2007-04-23
Facility ID:	8302630
Facility Type:	ER
DER Facility ID:	220188
Site ID:	270444
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	3101
Spill Date:	1984-05-09
Investigator:	JBVOUGHT
Referred To:	SIR DUE 07/22/06 (PIN JOB)
Reported to Dept:	1984-05-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1986-06-10
Spill Record Last Update:	2007-04-24
Spiller Name:	Not reported
Spiller Company:	WESTSIDE TRIPLE AUTO REPAIR
Spiller Address:	303-309 10TH AVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"09/25/95: PIN-4169 - ASSIGNED TO CHRIS FOR TRACKING PURPOSES. 10/6/03 See also PIN 4169, spill #s 8605682, 8606807, 9410208, 9410209. 1/8/04 Reassigned from Tomasello to K Foley. 06/20/06: Re-assigned from Foley to Yau. (Yau) 06/22/06: Prepared and sent an old spill letter to property owner through certified mail. A site investigation report (SIR) is expected to be due on 07/22/06. (Yau) 06/27/06: Owner called to inquire about the spill. Stated that he brought the property recently (around 2002) and had no idea where is the spill was. Told him that DEC will look into it and call him back with the exact location of the spill. (Yau) 08/02/06: Owner called to request an update to the site. Told him that a review is underway. Found that DEC had a PIN job for this site. Unsure whether the cleanup is complete. If the cleanup is incomplete, the owner might have to re-do the cleanup. Will call owner back as soon as review is completed. (Yau) 10/16/06 Reassign from Yau to Chanda (Chanda) 12/12/06-Vought-Spill reassigned from DEC Chanda to DEC Vought. 03/20/07-Vought-File review by Vought: See also open spill #0603967 at same location. Videotape-unknown date (circa 19884)-tape showing

10TH AVE. W 27/W 28 ST. G (Continued) **S102671142**

well being bailed with free product thickness of 1 . Registered CSL Letter sent by DEC Yau to Tenth Gas Inc (address as per Property Shark). FOIL request from Brinkerhoff-8/18/06. Vought called AG Bechard for status of PIN case. PIN case assigned to AG John Nyhoff. Vought called Nyhoff and left message to return call. 3/20/07-Vought-See also closed spill numbers: 8605682, 9410208, 9410209 and 8302630(Open pin #). Vought spoke to DEC Krimgold who is preparing Consent Order for PBS violations and requested to add remedial requirements. Conference call with DEC Urda, AG Nyoff and AG Riggi showed that approximately 354K still owed to AG for past cleanup costs. Due to same ownership (Citigas) prior costs may be included in Consent Order. Vought submitted CAP for below requirements to DEC Urda. Riggi and Nyhoff also approved submission of Final ISR and closure of spill as any new funds spent by the DEC need a new PIN number since settlement already reached with old responsible party. Vought called Snyder, summarized consent order and left message to return call. 03/21/07-Vought-Left message for AG Nyhoff to call Vought with status of PIN. Vought and DEC Urda spoke with AG Nyoff and as per Nyoff default judgement was made against former owner of property resulting in lean of approximately 354K. 3/26/07-Vought-Received ISR from Nyoff. Vought left message for Nyoff to return call with which party was found responsible (Alex Goffman or Westside Tripple Auto Repair). 4/23/07-Final ISR submitted to DEC Austin for review and spill closed by Vought. "

Remarks: ""

All Materials:

Site ID:	270444
Operable Unit ID:	894766
Operable Unit:	01
Material ID:	481492
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

CQ1010 **FEDERAL BUILDING THE** **SEMS-ARCHIVE** **1015735567**
ENE **252 7TH AVE** **RCRA NonGen / NLR** **NY2470000157**
1/4-1/2 **NEW YORK, NY 10001**
0.420 mi.
2216 ft. **Site 1 of 2 in cluster CQ**

Relative:
Higher

Actual:
29 ft.

SEMS Archive:

Site ID:	0203218
EPA ID:	NY2470000157
Name:	FEDERAL BUILDING
Address:	252-7TH AVENUE
Address 2:	Not reported
City,State,Zip:	NEW YORK, NY 10001
Cong District:	15
FIPS Code:	36061
FF:	Y
NPL:	Not on the NPL

FEDERAL BUILDING THE (Continued) **1015735567**

Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	02
Site ID:	0203218
EPA ID:	NY2470000157
Site Name:	FEDERAL BUILDING
NPL:	N
FF:	Y
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1989-12-31 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	02
Site ID:	0203218
EPA ID:	NY2470000157
Site Name:	FEDERAL BUILDING
NPL:	N
FF:	Y
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	1989-12-31 05:00:00
Qual:	N
Current Action Lead:	Fed Fac

Region:	02
Site ID:	0203218
EPA ID:	NY2470000157
Site Name:	FEDERAL BUILDING
NPL:	N
FF:	Y
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1989-10-30 05:00:00
Finish Date:	1989-10-30 05:00:00
Qual:	Not reported
Current Action Lead:	Fed Fac

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	FEDERAL BUILDING THE	
Handler Address:		252 7TH AVE
Handler City,State,Zip:		NEW YORK, NY 10001
EPA ID:		NY2470000157
Contact Name:		LINDA GOLDBLUM
Contact Address:		7TH AVE

FEDERAL BUILDING THE (Continued) **1015735567**

Contact City,State,Zip:	NEW YORK, NY 10001
Contact Telephone:	718-951-3452
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	7TH AVE
Mailing City,State,Zip:	NEW YORK, NY 10001
Owner Name:	GENERAL SERVICES ADMINISTRATION
Owner Type:	Federal
Operator Name:	GENERAL SERVICES ADMINISTRATION
Operator Type:	Federal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	The site is federally-owned, The site is federally-operated
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No

FEDERAL BUILDING THE (Continued) **1015735567**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	GENERAL SERVICES ADMINISTRATION
Legal Status:	Federal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GENERAL SERVICES ADMINISTRATION
Legal Status:	Federal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GENERAL SERVICES ADMINISTRATION
Legal Status:	Federal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

FEDERAL BUILDING THE (Continued) **1015735567**

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GENERAL SERVICES ADMINISTRATION
Legal Status:	Federal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20040524
Handler Name: FEDERAL BUILDING THE	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: FEDERAL BUILDING THE	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: FEDERAL BUILDING THE	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19830620
Handler Name: FEDERAL BUILDING THE	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

FEDERAL BUILDING THE (Continued) **1015735567**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violation:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19850226
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported

FEDERAL BUILDING THE (Continued) **1015735567**

Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

CQ1011 **FEDERAL BUILDING SITE** **NY HSWDS** **S108146443**
ENE **252 7TH AVE** **N/A**
1/4-1/2 **NEW YORK, NY 10001**
0.420 mi.
2216 ft. **Site 2 of 2 in cluster CQ**

Relative:
Higher

Actual:
29 ft.

HSWDS:

Facility ID:	Not reported
Region:	2
Facility Status:	Unknown
Owner Type:	F
Owner:	General Services Admin.
Owner Address:	26 Federal Plaza
Owner Phone:	212-267-8787
Operator Type:	F
Operator:	Same
Operator:	Same
Operator Phone:	Unknown
EPA ID:	NY2470000157
Registry:	Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID:	Unknown
RCRA Permitted:	Unknown
Site Code:	5-office
Owner City State:	NY, NY 10278
Operator City State:	Not reported
Quadrange:	Unknown
Latitude:	Unknown
Longitude:	Unknown
Acres:	0.00
Operator Date:	Unknown
Close Date:	Unknown
Completed:	PA/SI
Active:	Not reported
PCB's Disposed:	No
Pesticides Disposed:	No
Metals Disposed:	No
Asbestos Disposed:	No
Volatile Organic Compounds Disposed:	No
Semi Volatile Organic Compounds Disposed:	No
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	None
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Substance:	Not reported
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	Not reported
Analytical Info Exists for TCLP:	Not reported

FEDERAL BUILDING SITE (Continued) **S108146443**

Threat to Environment/Public Health:	Unknown
Surface Water Contamination:	Unknown
Surface Water Body Class:	Unknown
Groundwater Contamination:	Unknown
Groundwater Classification:	Unknown
Drinking Water Contamination:	Unknown
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	Unknown
Hazardous Exposure:	Unknown
Site Has Controlled Acess:	Unknown
Ambient Air Contamination:	Unknown
Direct Contact:	Unknown
EPA Hazardous Ranking System Score:	Unknown
Inventory:	F
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	0
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

CO1012 **THE DERMOT COMPANY** **NY LTANKS** **S109064333**
SSE **207-209 WEST 11TH STREET** **N/A**
1/4-1/2 **NEW YORK, NY**
0.423 mi.
2231 ft. **Site 2 of 3 in cluster CO**

Relative:
Higher

Actual:
26 ft.

LTANKS:

Name:	THE DERMOT COMPANY
Address:	207-209 WEST 11TH STREET
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0801458 / 2008-12-23
Facility ID:	0801458
Site ID:	397380
Spill Date:	2008-05-06
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4

THE DERMOT COMPANY (Continued) **S109064333**

Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	2008-05-07
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-05-07
Spill Record Last Update:	2008-12-23
Spiller Name:	CARMEN SANTIAGO
Spiller Company:	APRT
Spiller Address:	207-209 WEST 11TH STREET
Spiller County:	001
Spiller Contact:	CARMEN SANTIAGO
Spiller Phone:	(646) 673-6714
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	346805
DEC Memo:	"6/6/08 bf: Sent ttf letter to: Carmen Santiago The Dermot Company 320 West 57th St., 5th Floor New York, NY 10019 12/23/08 Yesterday, DEC received letter, dated 11/20/2008, from Robert Urban of Pro Test. On 11/18/08, tank was isolated, repaired and retested. manhole was regasketed and rebolted and repaired and tightened loose connections. No evidence of contamination found inside the tank wault. Passing tank test report attached. According to tank test report, tank is wrapped with bricks on basement floor. NFA. bf"
Remarks:	"dry leak: called yesterday but computers were down:"

All TTF:

Facility ID:	0801458
Spill Number:	0801458
Spill Tank Test:	2486038
Site ID:	397380
Tank Number:	Not reported
Tank Size:	2000
Material:	Not reported
EPA UST:	Not reported
UST:	True
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	397380
Operable Unit ID:	1154348
Operable Unit:	01

THE DERMOT COMPANY (Continued) **S109064333**

Material ID:	2145141
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CO1013 **X** **NY LTANKS** **S106123800**
SSE **201 W. 11TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.424 mi.
2239 ft. **Site 3 of 3 in cluster CO**

Relative: **Higher**
Actual: **26 ft.**

LTANKS:

Name:	X
Address:	201 W. 11TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0301325 / 2004-10-20
Facility ID:	0301325
Site ID:	69102
Spill Date:	2003-05-06
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	CESAWYER
Referred To:	Not reported
Reported to Dept:	2003-05-06
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-05-06
Spill Record Last Update:	2004-10-20
Spiller Name:	SAME
Spiller Company:	Not reported
Spiller Address:	201 W. 11TH ST
Spiller County:	001
Spiller Contact:	WM WEIDMAN-CARDINAL TANK
Spiller Phone:	(718) 625-4350
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	65736
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER DEC Sigona sent notification to property owner regarding the reported tank test failure. 1/7/04-Vought-Spill transferred from Vought to Austin. 01/27/04 - Sawyer - Spill transferred from Austin to Sawyer. 4/30/2004 SS sent a new ttf ltr 5/6/2004 Rep from Superior Management Inc called to say they no longer manage this building. New

X (Continued) **S106123800**

Contact: Knightsbridge Mgt. 235 West 48th St, NY,NY 10036 Property Manager: Celia Parascandola 212-977-5000 10/19/04 - Sawyer - Called Celia and left a message. 10/20/04 - Sawyer - Received documentation from Celia Parascandola of Knightbridge Management for repairs made to their boiler. The tank is aboveground and the repairs appear to be above the product line. No further action required. Closed. "

Remarks: "RECOMMEND TO ISOLATE AND RE-TEST"

All TTF:

Facility ID:	0301325
Spill Number:	0301325
Spill Tank Test:	1528347
Site ID:	69102
Tank Number:	Not reported
Tank Size:	3000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

Facility ID:	0301325
Spill Number:	0301325
Spill Tank Test:	1528348
Site ID:	69102
Tank Number:	1
Tank Size:	2000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	69102
Operable Unit ID:	869345
Operable Unit:	01
Material ID:	505818
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

X (Continued) **S106123800**

Oxygenate: Not reported

CP1014 **311 10TH AVENUE** **NY VCP** **S125316992**
NNE **311 10TH AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.426 mi.
2248 ft. **Site 3 of 3 in cluster CP**

Relative:
Higher

Actual:
16 ft.

VCP NYC:

Project ID:	14TMP0176M,14EHAN176M,19CVCP078M
Name:	311 10TH AVENUE
Address:	311 10TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Manhattan
BBL:	1006990037
OER Program:	VCP (Enrolled)
Phase:	Approved Remedial Plan
Latitude:	40.750742
Longitude:	-74.00196
Postcode:	4
Community Board:	3
Council District:	99
Census Tract:	1090611
BIN:	1006990037
NTA:	Hudson Yards-Chelsea-Flatiron-Union Square

1015 **APARTMENT BLDG.- TTF** **NY LTANKS** **S106869275**
ESE **135 W. 17TH ST.** **N/A**
1/4-1/2 **NEW YORK, NY**
0.426 mi.
2251 ft.

Relative:
Higher

Actual:
29 ft.

LTANKS:

Name:	APARTMENT BLDG.- TTF
Address:	135 W. 17TH ST.
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0501089 / 2005-11-02
Facility ID:	0501089
Site ID:	344227
Spill Date:	2005-04-26
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2005-04-26
CID:	406
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False

APARTMENT BLDG.- TTF (Continued) **S106869275**

Remediation Phase:	0
Date Entered In Computer:	2005-04-26
Spill Record Last Update:	2005-11-02
Spiller Name:	JOHN HETLAND
Spiller Company:	APARTMENT BLDG.
Spiller Address:	135 W. 17TH ST.
Spiller County:	001
Spiller Contact:	JOHN HETLAND
Spiller Phone:	(212) 989-7806
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	290866
DEC Memo:	"4/27/05-Vought-Spill assigned to Rahman to send out tank test letter. 04/27/05-SR// A TTF ltr was sent. 5/26/2005 Joe Ostrowski,(914)777-1930 Northeast Environmental asked for a 5 day time extension to submit the paperwork on this site. The tank was isolated and passed a retest. The problem was found in the fill line. Sangesland told Mr. Ostrowski to repair the fill line, take photos of the fill line area and submit copies of the tank test passing. 06/01/05- SR// Received copies of tank test pass. 10.18.05 Sharif-Spoke with A1 crown. They were hired to retest the tank and it passed.I left a messege for Joe, Northeast Environmental to call back DEC cause' we did not receive any documentation about the fill line repair.Also sent a letter to Andrews Building Corp. 11.02.05 Sharif-The fixed the line and the boiler is back on operation."
Remarks:	"Tank test Failure."

All TTF:

Facility ID:	0501089
Spill Number:	0501089
Spill Tank Test:	1548845
Site ID:	344227
Tank Number:	Not reported
Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	344227
Operable Unit ID:	1102881
Operable Unit:	01
Material ID:	583101
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

APARTMENT BLDG.- TTF (Continued) **S106869275**

Recovered: .00
Oxygenate: Not reported

CN1016 **SUPERIOR PRINTING INK CO INC** **NY LTANKS** **1000215465**
SSW **70 BETHUNE ST** **NY UST** **NYT000603548**
1/4-1/2 **NEW YORK, NY 10014** **NY BROWNFIELDS**
0.432 mi. **NY Spills**
2279 ft. **Site 2 of 2 in cluster CN** **RCRA NonGen / NLR**
FINDS
Relative: Lower **ECHO**
NY MANIFEST
Actual: 10 ft.

LTANKS:

Name:	SUPERIOR INKS
Address:	70 BETHUNE STREET
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	0312534 / 2004-02-23
Facility ID:	0312534
Site ID:	292057
Spill Date:	2004-02-10
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2004-02-11
CID:	403
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-02-11
Spill Record Last Update:	2006-01-31
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	ROGER POLE
Spiller Phone:	(212) 741-3600
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	186169
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD Send TTF letter Duplicate spill- this number is closed Ref to #0312310 - Cris Sawyer"
Remarks:	"tank test failed"

All TTF:

Facility ID:	0312534
Spill Number:	0312534
Spill Tank Test:	1528969
Site ID:	292057

SUPERIOR PRINTING INK CO INC (Continued) **1000215465**

Tank Number: 001
Tank Size: 7500
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 292057
Operable Unit ID: 877786
Operable Unit: 01
Material ID: 555235
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: L
Recovered: .00
Oxygenate: Not reported

UST:
Name: SUPERIOR INK
Address: 70 BETHUNE STREET
City,State,Zip: NEW YORK, NY 10014
Id/Status: 2-042951 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 583656.51956
UTM Y: 4510042.22191
Site Type: Manufacturing (Other than Chemical)/Processing

Affiliation Records:
Site Id: 367
Affiliation Type: Facility Owner
Company Name: SUPERIOR PRINTING INK CO INC
Contact Type: Not reported
Contact Name: Not reported
Address1: 70 BETHUNE ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10014
Country Code: 001
Phone: (212) 741-3600
EMail: Not reported
Fax Number: Not reported

SUPERIOR PRINTING INK CO INC (Continued) **1000215465**

Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 367
Affiliation Type: Mail Contact
Company Name: SUPERIOR PRINTING INK CO INC
Contact Type: Not reported
Contact Name: LISA DEROSA
Address1: 70 BETHUNE STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10014
Country Code: 001
Phone: (212) 741-3600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 367
Affiliation Type: Facility Operator
Company Name: SUPERIOR INK
Contact Type: Not reported
Contact Name: SUPERIOR PRINTING INK CO INC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 741-3600
EMail: Not reported
Fax Number: Not reported
Modified By: nrlombar
Date Last Modified: 2004-05-28

Site Id: 367
Affiliation Type: Emergency Contact
Company Name: SUPERIOR PRINTING INK CO INC
Contact Type: Not reported
Contact Name: ROGER PAUL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 346-5261
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001

SUPERIOR PRINTING INK CO INC (Continued) **1000215465**

Tank ID:	1096
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	7500
Install Date:	Not reported
Date Tank Closed:	05/27/2004
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	18
Date Test:	11/24/1999
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	nrlombar
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
D10 - Pipe Type - Copper
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

BROWNFIELDS:

Name:	70 BETHUNE STREET
Address:	70 BETHUNE STREET
City,State,Zip:	NEW YORK, NY 10014
Program:	BCP
Site Code:	373205
Acres:	0.730
HW Code:	C231058
SWIS:	3101
Town:	New York City
Record Added Date:	11/08/2006
Record Updated Date:	12/17/2007
Update By:	SMMARTIN
Site Description:	"This is a new BCP application and pertains to the 70 Bethune Street property located in Manhattan, New York County. This site is approximately 0.73 acres in size. Currently the site is vacant and future use of this site will be for residential use with some commercial space and a parking garage. Past uses include a bakery and an ink manufacturer. The building, built in 1909, has three stories, "L" shaped, with one basement level, and 25,000 square feet footprint. The basement slab is four feet below gound surface. The building lies on the western portion of the block between West and Washington Streets. It extends approx 220 feet along Bethune Street and approx 140 feet along West 12th Street from West Street. On part of the property east of the building along Bethune Street is a parking lot and loading dock. The building will be demolished in

SUPERIOR PRINTING INK CO INC (Continued) **1000215465**

	early 2007. Nearby land use includes residential, commercial, and industrial. This BCP application was reviewed and the Department of Environmental Conservation determined that the application was not eligible for inclusion in the BCP. The cleanup of the site continued under the Spills Program (see spill no. 0312310) and was closed November 2007."
Env Problem:	"Known contaminants at this site are petroleum, SVOCs, and metals. The site is underlain throughout with about eight feet of historic fill. Petroluem had impacted the groundwater; the fuel oil tank was removed and a dual phase extraction system has been running to remediate the groundwater. Soil gas was also sampled at six locations. Monitoring wells were installed on the sidewalk around the site. "
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	NNN
Owner Name:	BENJAMIN JOSEPH
Owner Company:	BETHUNE WEST ASSOCIATES, LLC
Owner Address:	60 COLUMBUS CIRCLE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10023
Owner Country:	United States of America
Own Op:	6
Sub Type:	NNN
Owner Name:	BENJAMIN JOSEPH
Owner Company:	BETHUNE WEST ASSOCIATES, LLC
Owner Address:	60 COLUMBUS CIRCLE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10023
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	SUPERIOR INKS
Address:	70 BETHUNE STREET
City,State,Zip:	NEW YORK, NY

SUPERIOR PRINTING INK CO INC (Continued) **1000215465**

Spill Number/Closed Date:	0312310 / 2007-10-12
Facility ID:	0312310
Facility Type:	ER
DER Facility ID:	186169
Site ID:	225522
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	2004-02-05
Investigator:	kkchanda
Referred To:	Not reported
Reported to Dept:	2004-02-05
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-02-05
Spill Record Last Update:	2007-10-12
Spiller Name:	ROBIN HEATH
Spiller Company:	SUPERIOR INKS
Spiller Address:	70 BETHUNE STREET
Spiller Company:	001
Contact Name:	ROBIN HEATH
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER This spill number remains open. A second number (#0312534) was called in by the tank test company and this second number has been closed out. Spill Number 0312534 was a tank test failure. Site has both a failed tank and contaminated soil. 3/22/2004 - A contractor spoke to Sawyer concerning the work to be done on the site. 12/16/05- DEC Piper spoke w/ Robin Heath. He will have someone contact the dept regarding the site. 12/29/05- DEC Piper received call from Dick Brownell of Malcolm Pirnie (consultant) regarding site. As per conversation, there is a dual phase extraction sytem running periodically at the site. There is currently free phase product in two of the monitoring wells. A file exists. File should be transferred to Remediation Group. 1/11/06- DEC Piper File transferred to Koon Tang. Remediation required. 1/12/06 - assigned to Jon Kolleeny Group. - KST 02/02/06: This spill transferred from J.Kolleeny to S.Kraszewski. Spoke with Richard Brownell from Malcolm Pirnie (914-641-2424). I inquired about the trench recovery system installed in September 1994 and any monitoring data available for the site and the wells. The trench system was installed as a dual-phase extraction system for several recovery wells located in the former tank area and the boiler room. The system operated from Nove 2004 to Nov 2005 when the motor broke down and had to be repaired. the motor is almost finished and the system will be operational soon. For the duration of the remediation process at this site, free product has been observed in the boiler room, Richard said. Bimonthly O+M reports have been keeping track of the system for some time since little free product was being recovered. I asked Richard to summarize the data

SUPERIOR PRINTING INK CO INC (Continued) **1000215465**

from the O+M reports along with a site diagram with the trench system on it along with the MWs surrounding the perimeter of the site. Also, the site will be undergoing redevelopment which will involve the excvation and removal of the soil on-site. This would be considered source removal of contaminated soils. For now, the system will be started up when ready and run until the data suggests otherwise. I also mentioned that in the near future, GW samples will be required to assess the degree of contamination present in the GW. Richard said no GW samples have been taken in quite some time. - SK 03/01/06: Richard Brownell from Malcom Pirnie returned my call to update me on site progress. The oil recovery system motor is fixed and ran for several days, extracting several gallons of oil. This oil had been collecting for 2.5 months while the system was under repair. When the system had been running in the past, oil was being extracted from two recovery wells, but now only one exhibits free product. This recovery well is located in the boiler room, near the former USTs. He will write up an update report for the site and send it out to me; due by 03/10/06. 03/10/06: Reviewed Summary of Oil Recovery System Results submitted by Malcolm Pirnie. Volume of oil recovered by the system over time shows a decline in product recovered. The system was shut down due to mechanical difficulties from November 17 2005 until February 24, 2006. No SVE data is given in the report. Product measurements seemed to be made randomly at different monitoring wells, few have current product thickness measurements. Some show one measurement with ND given and no follow-up measurements made. - SK 03/15/06: SK spoke with Richard Brownell about the summary report. I told him that SVE air sampling and GW sampling is needed, since it is long overdue. The GW samples must be analyzed for VOCs and SVOCs while air samples can be taken with a PID at the influent and effluent ports of the system. Spoke to J.Kolleeny about the report. He said to ask about the Monitoring and Maintenance Plan for the system before writing up a response letter. - SK 03/17/06: Spoke with Dick Brownell. I asked him if the recovery system had a Monitoring and Maintenance plan. He said he wasn't sure and probably didn't, but he would check to make sure. I said if none is found then he should put together a plan to cover activities from this point on. I told him that I would Email him the Excel tables to use as a template. He said that sounds good. Also, he mentioned about the RAP and if I had a copy. The only copy I have is a draft RAP from Malcom and Pirnie. Dick said he will check if Langan Engineers had sent a copy to DEC. Malcom and Pirnie is currently working on scheduling a round of MW measurements and samplings for analysis. I sent out the Email with the Monitoring and Maintenance tables. - SK 04/10/06: Dick Brownell called with news that they would be taking GW samples either Wednesday or Thursday this week. However, the SVE system is still out of service due to motor problems, so no influent or effluent air samples will be taken. Dick will let me know when exactly they will be collecting samples. - SK 04/17/06: Dick Brownell from Malcom Pirnie called. The sampling will be rescheduled for the 26th. He mentioned that the monitoring well with free product, BB-12, may be widened with a four inch slotted PVC pipe in order to vacuum out oil and water. This may remove the remaining product that is left on-site. No other wells exhibit any product. I asked Dick to write me up a letter summarizing the scope of this work. He said I should have it by Thursday. - SK 04/28/06: SK received a call from Malcom Pirnie, informing me that a letter requesting the installation of the MW where BB-12 is currently located. This work involves cutting a 4' by

SUPERIOR PRINTING INK CO INC (Continued) **1000215465**

4' section and excavating down to the water level and then removal of any free product encountered. If free product enters the pit consistently then a 4 inch slotted PVC will be advanced for continued product recovery. - SK 05/02/06: Sent out approval letter for additional oil recovery work. Also, the GW investigation results should be included in the oil recovery report. Spoke yesterday will Wyn Davies and gave him verbal approval and mentioned that four endpoint samples from the excavation would be needed. Work should begin by early next week, May 8-10. - SK 06/19/06: Reviewed New Sump Pit Proposal from Malcolm Pirnie dated June 19, 2006. Spoke with Wyn Davies about the proposed Sump Pit #2. I asked for 4 grab samples from the pit instead of 2. MW data and soil grab samples analysis results were included. All four soil grab samples detected slight SVOC exceedances. Water samples from MW-5 detected slight VOC contamination above TOGS, but no BTEX above TOGS. Discussed the proposal with J.Kolleeny. Gave Wyn a verbal approval followed by an approval letter. - SK 06/26/06: Dick Brownell (office:914-641-2424) from Malcolm Pirnie called. The additional sump pit has been installed, they seem to have found the pocket of oil and taken care of it, at least for now. Workers vacuumed out the pit to draw down the water. The recovery system is operational once again and Dick said they will have a report for me in July. BB-10, a monitoring point located next to the former tank location, has a 1/4 sheen. - SK 07/07/06: Dick Brownell (cell:914-806-9934) from Malcolm Pirnie called to inform me that no free product remains in any of the recovery wells. The isolated product from the second sump pit has abated. Also, he has found out that this site is slated for redevelopment sometime later this year. I told him that it looks like we are on the verge of closure, but I would prefer to visit the site and discuss this with my supervisor. A site visit is scheduled for July 19 at 10AM. - SK 07/19/06: Visited on-site with Dick Brownell from Malcolm Pirnie, Harold Rubin the RP and Dave Uteson the attorney for the developers interested in the site. We discussed the status of the recovery system. 11/09/06: Reassigned to Stephen Kraszewski to Chanda.(Chanda) 12/26/06: Kartik Chanda of DEC reviewed enter file and called Dick Brownel (office:914-641-2424) to get the update information regarding this site and left message to call back. 12/28/06: Chanda received a phone call from Mr.Dick Brownel(Malcolm Pirnie) he informed to DEC that his company is no longer with this site. This project have new consultant (Mr.Joe Landes ph:212-479-5400) assigned this site and the property has been transfered to new owner. 01/02/07: Chanda called Mr. Joe Landes (New Consultant) to get update information regarding this site. Left massage to call back. 01/02/07: Kartik Chanda of DEC sent a letter to the RP (Mr.Harold Rubin, requiring that a work report be submitted to DEC for review by 02/15/07. 01/04/07: Chanda received a phone call from new consultant LANGAN ENGINEERING & ENVIRONMENTAL SERVICES,P.C (Mr. John Gavras , Ph. 212-479-5406). Chanda sent a copy of previous letter to Mr.John and discuss regarding the site update status. 01/11/07: Chanda received an e-mail from John Gavras (Consultant).He gave the new owner's name and contact information: Bryan N. Cho, Vice President Bethune West Associates, LLC c/o The Related companies 60 Columbus Circle,18th Floor New York, NY 10023 2/15/07: Chanda received an additional sump pit excavation report prepared by Lagan Engineering and Environmantal Services dated on February 13, 2007. 3/01/07: Chanda received a Remedial Action Plan from Attorny (David Yudelson), prepared by Langan Engineering and Environmental Services dated

SUPERIOR PRINTING INK CO INC (Continued) **1000215465**

December 2006. 3/22/07: Kartik Chanda has reviewed the RAP and approved on 3/21/07. Chanda sent approval letter to RP(Bryan N. Cho) and his attorney (David Yudelson) and consultant (John M. Gavras), requiring that the RAP be implemented by may 6, 2007, and the Department requires five days advanced notice of any remedial work of the site. 9/6/07: On 8/28/07, Joe Sun (NYSDEC) visited the site and directed three post-remediation grab samples be collected from standing groundwater within the footprint of the proposed building. In addition, groundwater samples were collected from existing monitoring wells MW-5 and MW-6 located along West 12th Street. 9/21/07: Chanda received an electronic copy of Request for spill closure letter with the remedial action activities for this spill case. 9/24/07: Chanda received a hard copy of the remedial action activities report from Mr. David Yudelson (Sive, Paget & Riesel, P.C.). 10/5/07: Chanda reviewed the remedial action activities report and has the followings comments: 1. Excavation of petroleum-impacted soil in July to September, 2007. 2. This report indicates that post-remediation soil samples were collected bottom of the excavation. In total, 11 bottom soil samples and 7 sidewall soil samples were collected from the excavation. The level of contamination were below the TAGM RSCOs. Several SVOCs (Benzo(a)pyrene, 2-Methylnaphthalene) were detected in the four (4) end point samples and the level is not high. 3. VOCs and SVOCs were not detected of the post-remediation groundwater samples collected on the site. 4. The chlorinated VOC tetrachloroethene (PCE) was detected in the three (3) groundwater samples ranging from 12.9 ppb to 18 ppb. In addition the 2-dichloroethene (DEC)was detected at a concentration of 6.1 ppb. The proposed RAP indicated that In order to be protective of the health of the future residents, an appropriate vapor barrier (Grace Prepruf 300R) and passive sub-slab depressurization system (SSDS) will be installed in to the foundation construction. 10/12/07: Chanda discussed with Joe Sun (Supervisor) regarding the findings of the remedial action report and reviewed the passive SSDS and detail design of the suction pits on 10/11/07. Based on the information presented to the Department. DEC closed this spill. (Joe & Chanda) A NFA letter was issued to Mr. Bryan N. Cho (RP), Mr. David Yudelson(Attorney)and john Gavras (Langan) "

Remarks: "UNKNOWN AT THIS WHAT CAUSED SPILL AND HOW MUCH FURTHER INVESTIGATING:"

All Materials:

Site ID:	225522
Operable Unit ID:	877544
Operable Unit:	01
Material ID:	497529
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date Form Received by Agency: 20070101

SUPERIOR PRINTING INK CO INC (Continued) **1000215465**

Handler Name:	SUPERIOR PRINTING INK CO INC
Handler Address:	70 BETHUNE ST
Handler City,State,Zip:	NEW YORK, NY 10014
EPA ID:	NYT000603548
Contact Name:	Not reported
Contact Address:	BETHUNE ST
Contact City,State,Zip:	NEW YORK, NY 10014
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	BETHUNE ST
Mailing City,State,Zip:	NEW YORK, NY 10014
Owner Name:	SUPERIOR PRINTING INK CO INC
Owner Type:	Private
Operator Name:	SUPERIOR PRINTING INK CO INC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No

SUPERIOR PRINTING INK CO INC (Continued) **1000215465**

Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	K086
Waste Description:	SOLVENT WASHES AND SLUDGES, CAUSTIC WASHES AND SLUDGES, OR WATER WASHES AND SLUDGES FROM CLEANING TUBS AND EQUIPMENT USED IN THE FORMULATION OF INK FROM PIGMENTS, DRIERS, SOAPS, AND STABILIZERS CONTAINING CHROMIUM AND LEAD.
Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SUPERIOR PRINTING INK CO INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SUPERIOR PRINTING INK CO INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999

SUPERIOR PRINTING INK CO INC (Continued) **1000215465**

Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SUPERIOR PRINTING INK CO INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19950419
Handler Name: SUPERIOR PRINTING INK CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: SUPERIOR PRINTING INK CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SUPERIOR PRINTING INK CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

SUPERIOR PRINTING INK CO INC (Continued) **1000215465**

Receive Date: 19800721
Handler Name: SUPERIOR PRINTING INK CO INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

SUPERIOR PRINTING INK CO INC (Continued) **1000215465**

Evaluation Action Summary:

Evaluation Date:	19960926
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2STP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:

Registry ID: 110001135003

Click Here:

Environmental Interest/Information System:

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000215465
Registry ID:	110001135003
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110001135003
Name:	SUPERIOR PRINTING INK CO INC
Address:	70 BETHUNE ST
City,State,Zip:	NEW YORK, NY 10014

NY MANIFEST:

Name:	SUPERIOR PRINTING INK
Address:	70 BETHUNE STREET
City,State,Zip:	NEW YORK, NY 10014
Country:	USA
EPA ID:	NYD000603548
Facility Status:	Not reported
Location Address 1:	70 BETHUNE STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported

SUPERIOR PRINTING INK CO INC (Continued) **1000215465**

Location City: NEW YORK
Location State: NY
Location Zip: 10014
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD000603548
Mailing Name: SUPERIOR PRINTING INK
Mailing Contact: SUPERIOR PRINTING INK
Mailing Address 1: 70 BETHUNE STREET
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10014
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2127413600

CR1017 **514-520 WEST 28TH STREET** **NY BROWNFIELDS** **S112818548**
North **514-520 WEST 28TH STREET** **N/A**
1/4-1/2 **NEW YORK, NY 10001**
0.439 mi.
2320 ft. **Site 1 of 4 in cluster CR**

Relative:
Higher

Actual:
14 ft.

BROWNFIELDS:
Name: 514-520 WEST 28TH STREET
Address: 514-520 WEST 28TH STREET
City,State,Zip: NEW YORK, NY 10001
Program: BCP
Site Code: 477443
Acres: 0.510
HW Code: C231082
SWIS: 3101
Town: New York City
Record Added Date: 01/02/2013
Record Updated Date: 12/31/2014
Update By: BXANDERS
Site Description: "Location: The site is located at 514 - 520 West 28th Street in New York City, New York County and has an area of approximately 0.51 acres. It is between 10th and 11th Avenues and is bounded to the north by West 28th Street and the south by West 27th Street. Commercial structures are adjacent to the east and west boundaries. Site Features: Presently, the site is undergoing redevelopment. Prior to remediation and redevelopment, the two lots that made up the site contained a vehicle rental company and a scrap yard. Current Zoning and Land Use: The site is zoned commercial (C6-3) and is located in a commercial and residential area of the West Chelsea section of the Borough of Manhattan. Past Use of the Site: The site has been occupied by several residential structures, laundry cleaning, metal works, manufacturing, motor freight storage, automobile repair and a scrap yard. Site Geology and Hydrogeology: Prior to remediation, subsurface material present below the site included historic fill from prior developments that may have been used to stabilize soil or to elevate the existing ground. The fill included concrete, brick, cinders, and other construction debris mixed, silt, sand and gravel and was generally present from 1-10 feet below ground. Below the fill the shallow subsurface soil at the site consists of sands and silts,

514-520 WEST 28TH STREET (Continued) **S112818548**

glacial till intermixed with lean clay. Depth to bedrock ranged from 15 to 25 feet below grade. The surface geology of Manhattan generally includes very thin layers of unconsolidated glacial deposits underlain by bedrock. Groundwater at the site is encountered at approximately 8 to 11 feet below ground surface. Regional groundwater flow direction is westerly toward the Hudson "

Env Problem: "Soil: Investigations found no evidence of significant VOC contamination in soil. Trimethylbenzenes and xylenes were present in one of the 21 soil samples at concentrations above their unrestricted use SCOs, but well below residential use SCOs. PAHs were observed in about half of the samples at concentrations indicative of historic fill. Metals are also present in soil at concentrations typical of historic fill and urban background. However, mercury concentrations ranged from non-detect to 69.6 parts per million (ppm). The unrestricted use SCO for mercury is 0.18 ppm; restricted residential is 0.81 ppm. The entire site has been excavated beyond the site boundary on all side and and to bedrock over about two-thirds of the site. The remaining soil meets unrestricted SCOs for all constituents. Groundwater: Cis-1,2-dichloroethene (DCE) was found in groundwater samples from two wells near the north-west corner of the site at concentrations up to 260 ppb. DCE has been documented in up-gradient groundwater and is not due to an on-site source. Soil Vapor: The presence of chlorinated VOCs in soil vapor and groundwater presents the possibility of vapor intrusion to future on-site buildings. The maximum concentrations of tetrachloroethene (PCE) and trichloroethene (TCE) were detected along the west boundary at the respective concentrations of 308 micrograms per cubic meter (ug/m3) and 828 ug/m3. The site has been excavated to below the water table and the new on-site building will have a water vapor barrier USTs Two USTs were exhumed in August 2013 and disposed of off-site. Two more wells were removed during the site remediation activities."

Health Problem: "The site is fenced and covered by concrete, people will not come into contact with site related soil and groundwater contamination unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains its water from a different source not affected by this contamination. Volatile organic compounds may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air or buildings, is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site related contaminants due to soil vapor intrusion does not represent a concern for the site in its current condition. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-01-03 10:39:00
Record Upd: 2014-11-24 13:11:00
Updated By: JAMORAS
Own Op: 6

514-520 WEST 28TH STREET (Continued) **S112818548**

Sub Type:	P03
Owner Name:	Greg Gushee
Owner Company:	28th Highline Associates, L.L.C.
Owner Address:	c/o Related Companies, 60 Columbus Circle
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10023
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Ashley Curran
Owner Company:	New York Public Library
Owner Address:	Muhlenberg Branch
Owner Addr2:	209 West 23rd Street
Owner City,St,Zip:	New York, NY 10011-2379
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Not reported
Owner Company:	28th Highline Associates, L.L.C.
Owner Address:	c/o Related Companies
Owner Addr2:	60 Columbus Circle
Owner City,St,Zip:	New York, NY 10023
Owner Country:	United States of America
HW Code:	C231082
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	ZINC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	TETRACHLOROETHYLENE (PCE)

514-520 WEST 28TH STREET (Continued) **S112818548**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	1,2,4-TRIMETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	BENZO[K]FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	COPPER
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	1,3,5-Trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	NICKEL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	BARIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231082
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C231082-03-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2014-11-18 15:34:00
Record Updated:	2014-11-18 15:34:00
Updated By:	MDMACCAB

CS1018 **COMMERCIAL BUILDING** **NY LTANKS** **S105994894**
North **260 11TH AVE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.441 mi.
2328 ft. **Site 1 of 2 in cluster CS**

Relative: **Lower**
Actual: **8 ft.**

LTANKS:

Name:	COMMERCIAL BUILDING
Address:	260 11TH AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	0109855 / 2005-06-27
Facility ID:	0109855
Site ID:	275745
Spill Date:	2002-01-09
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MJHAGGER
Referred To:	Not reported
Reported to Dept:	2002-01-11
CID:	282
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-01-11
Spill Record Last Update:	2005-06-27
Spiller Name:	ISAAC MUNGRA
Spiller Company:	COMMERCIAL BUILDING
Spiller Address:	260 11TH AVE
Spiller County:	001
Spiller Contact:	ISAAC MUNGRA
Spiller Phone:	(718) 624-4842
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	224181
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 6/27/05 - Haggerty - Recieved an invoice from Petroleum Tank Cleaners, Inc. detailing the clean-up and disposal of contaminats from the site. 18.89 tons of contaminated soil was removed and properly disposed of. "
Remarks:	"LEAKING TANK CAUSED THE SPILL SOME OF THE PRODUCT WENT INTO THE SUMP PIT.SPILL OCCURRED ON JAN 9TH. THEY SETUP A TEMPORARY TANK AND PUMPED OUT THE DAMAGED TANK. THE SPILL HAS NOT BEEN CLEANED UP AS OF YET. "

All Materials:

Site ID:	275745
Operable Unit ID:	848206
Operable Unit:	01
Material ID:	527499
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

COMMERCIAL BUILDING (Continued) **S105994894**

Units: G
Recovered: .00
Oxygenate: Not reported

CT1019 **SPILL NUMBER 0110039** **NY LTANKS** **S105994953**
East **153 W 23RD ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.442 mi.
2335 ft. **Site 1 of 3 in cluster CT**

Relative:
Higher

Actual:
30 ft.

LTANKS:

Name:	SPILL NUMBER 0110039
Address:	153 W 23RD ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0110039 / 2003-04-11
Facility ID:	0110039
Site ID:	139032
Spill Date:	2002-01-18
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2002-01-18
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-01-18
Spill Record Last Update:	2003-04-11
Spiller Name:	PAM
Spiller Company:	Not reported
Spiller Address:	153 W 23RD ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	118830
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE CLEANED BY OIL CO."
Remarks:	"CUSTOMER INSISTED THEY DELIVER 1300 GALLONS & STORANGE TANK ONLY TOOK 1200 GALLONS - SPILL CONTAINTED - CLEAN UP CREW ENROUTE"

All Materials:

Site ID:	139032
Operable Unit ID:	847154
Operable Unit:	01
Material ID:	527671
Material Code:	0003A
Material Name:	#6 fuel oil

SPILL NUMBER 0110039 (Continued) **S105994953**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CR1020 **526-532 WEST 28TH STREET** **NY VCP** **S125317138**
North **526 WEST 28TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.443 mi.
2338 ft. **Site 2 of 4 in cluster CR**

Relative: **Lower**
Actual: **13 ft.**

VCP NYC:

Project ID:	14TMP0086M,14EHAN086M,14CVCP241M
Name:	526-532 WEST 28TH STREET
Address:	526 WEST 28TH STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Manhattan
BBL:	1.00699004910069E+19
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed
Latitude:	40.751326
Longitude:	-74.003086
Postcode:	4
Community Board:	3
Council District:	99
Census Tract:	1090205
BIN:	1006997504
NTA:	Hudson Yards-Chelsea-Flatiron-Union Square

CR1021 **507-515 WEST 28TH STREET** **NY VCP** **S125317124**
North **507 WEST 28TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.447 mi.
2358 ft. **Site 3 of 4 in cluster CR**

Relative: **Higher**
Actual: **15 ft.**

VCP NYC:

Project ID:	13TMP0009M,13EHAN009M,13CVCP106M
Name:	507-515 WEST 28TH STREET
Address:	507 WEST 28TH STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Manhattan
BBL:	1.0070000451007001E+69
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.751219
Longitude:	-74.002786
Postcode:	4
Community Board:	3
Council District:	99
Census Tract:	1090201
BIN:	1007000027
NTA:	Hudson Yards-Chelsea-Flatiron-Union Square

CT1022 **APARTMENT BUILDING** **NY LTANKS** **S111317486**
East **148 WEST 24TH STREET** **NY Spills** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.449 mi.
2372 ft. **Site 2 of 3 in cluster CT**

Relative:
Higher

Actual:
30 ft.

LTANKS:

Name:	APARTMENT BUILDING
Address:	148 WEST 24TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0500940 / 2005-04-22
Facility ID:	0500940
Site ID:	344050
Spill Date:	2005-04-22
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2005-04-22
CID:	408
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	Not reported
Meets Standard:	True
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2005-04-22
Spill Record Last Update:	2005-04-22
Spiller Name:	PETER MURRAY
Spiller Company:	ABC REALTY
Spiller Address:	152 WEST 57TH STREET
Spiller County:	001
Spiller Contact:	ISAAC MUNGRA
Spiller Phone:	(718) 378-7000
Spiller Extention:	28
DEC Region:	2
DER Facility ID:	123067
DEC Memo:	"Sangesland spoke to Rene at PTC. Overfill out of vent line onto sidewalk. He was on the site and said it was just about cleaned up. They will return tomorrow to steam clean the sidewalk. No drains/sewers involved. No spill in basement."
Remarks:	"material is on sidewalk, speedi dry will be put down shortly."

All Materials:

Site ID:	344050
Operable Unit ID:	1102704
Operable Unit:	01
Material ID:	582926
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

APARTMENT BUILDING (Continued) **S111317486**

SPILLS:

Name:	APARTMENT BUILDING
Address:	148 WEST 24TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0400670 / 2004-04-21
Facility ID:	0400670
Facility Type:	ER
DER Facility ID:	123067
Site ID:	144367
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2004-04-20
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2004-04-20
CID:	444
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-04-20
Spill Record Last Update:	2004-04-21
Spiller Name:	PETER MURRARY
Spiller Company:	APARTMENT BUILDING
Spiller Address:	148 WEST 24TH STREET
Spiller Company:	001
Contact Name:	PETER MURRARY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND 4/21/2004 Sangesland spoke to Peter Murray (building super). He said the spill was all outside from the vent line and all to the cement sidewalk. No spill inside, no drains, no soil impacted. Spill all cleaned up by T&S Trucking Spill Closed"
Remarks:	"5000 GALLON TANK THE GAUGE READ SOMETHING ELES, THE OIL LEAKED OUT DUE TO DEFECTIVE GAUGE, IN PROCESS OF BEING CLEANED UP: NO DRAINS EFFECTIVE: "

All Materials:

Site ID:	144367
Operable Unit ID:	884887
Operable Unit:	01
Material ID:	491914
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

APARTMENT BUILDING (Continued) **S111317486**

Name:	COMMERCIAL BUILDING
Address:	148 WEST 24TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	1108489 / 2011-10-05
Facility ID:	1108489
Facility Type:	ER
DER Facility ID:	410782
Site ID:	456224
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2011-10-05
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2011-10-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-10-05
Spill Record Last Update:	2011-10-06
Spiller Name:	Not reported
Spiller Company:	BUILDING OWNER
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MICHAEL SAVINO
DEC Memo:	"Spill occurred due to faulty gauge. AST 5000 gallon in the basement.Micheael Savino from state wide oil returned my call and said its all cleaned up. No spill in the tank room or basement.Case closed.(sr) ** PBS: 2-291374 ** I called the building Management @(212)989-6680, Mr Wandy confirmed that the clean up was satisfactory.(sr)"
Remarks:	"on concrete - cleanup crew enr -"

All Materials:

Site ID:	456224
Operable Unit ID:	1206365
Operable Unit:	01
Material ID:	2203429
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

CR1023 **PARKING LOT OF** **NY LTANKS** **S103558674**
North **515 WEST 28TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.458 mi.
2416 ft. **Site 4 of 4 in cluster CR**

Relative:
Higher

Actual:
14 ft.

LTANKS:

Name:	PARKING LOT OF
Address:	515 WEST 28TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9811167 / 1998-12-07
Facility ID:	9811167
Site ID:	86623
Spill Date:	1998-12-05
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1998-12-05
CID:	384
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-12-05
Spill Record Last Update:	2002-05-14
Spiller Name:	ANTHONY MILANESE
Spiller Company:	EAST COAST PETRO INC
Spiller Address:	340 JACKSON AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	79443
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE CLEANED BY RP."
Remarks:	"OVERFILL DUE TO ORDERING BY CUSTOMER. PETRO WILL BE DOING CLEAN UP."

All Materials:

Site ID:	86623
Operable Unit ID:	1068562
Operable Unit:	01
Material ID:	315017
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

CT1024 **SPILL NUMBER 0110441** **NY LTANKS** **S105995063**
East **142 WEST 24TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.458 mi.
2419 ft. **Site 3 of 3 in cluster CT**

Relative:
Higher

Actual:
31 ft.

LTANKS:

Name:	SPILL NUMBER 0110441
Address:	142 WEST 24TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0110441 / 2002-01-31
Facility ID:	0110441
Site ID:	66626
Spill Date:	2002-01-31
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2002-01-31
CID:	211
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-01-31
Spill Record Last Update:	2002-02-01
Spiller Name:	PAMELA
Spiller Company:	FM RING PROPERTIES
Spiller Address:	142 WEST 24TH ST
Spiller County:	001
Spiller Contact:	JIM CAREY
Spiller Phone:	(718) 579-3413
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	63774
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE "
Remarks:	"CASTLE SPILL CREW ON SITE - PROPERTY MANAGER ORDERED TOO MUCH FUEL LEADING TO OVERFILL"

All Materials:

Site ID:	66626
Operable Unit ID:	848927
Operable Unit:	01
Material ID:	528065
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

CU1025 **NYC DEPT OF SANITATION** **NY LTANKS** **S109583684**
NNW **640 WEST 26TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.460 mi.
2431 ft. **Site 1 of 4 in cluster CU**

Relative: LTANKS:
Lower

Actual:
6 ft.

Name:	NYC DEPT OF SANITATION
Address:	640 WEST 26TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0813987 / 2009-05-22
Facility ID:	0813987
Site ID:	411708
Spill Date:	2009-03-26
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	hrpatel
Referred To:	Not reported
Reported to Dept:	2009-03-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-03-26
Spill Record Last Update:	2009-05-22
Spiller Name:	JAY SHAW
Spiller Company:	NYC DEPT OF SANITATION
Spiller Address:	640 WEST 26TH ST
Spiller County:	999
Spiller Contact:	MICHAEL SEPE
Spiller Phone:	(516) 818-8767
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	360906
DEC Memo:	"03/27/09-Hiralkumar Patel. spoke with MIke at F&N. he mentioned they have schedule isolation test on 03/30/09. Mike will call back with result of isolation test. as per NYC Dept. of sanitation, tank is been empty for more than a year. PBS #: 2-605738. Neil Gallagher Director Bureau Building Maintenance 52-35 58th Street Room 410 Woodside, NY 11377 Ph. (718) 334-9100/9117 (646) 235-3182 (C) FAX (718) 334-9334 05/20/09-Hiralkumar Patel. spoke with Jason (631-586-4900 Ext. 180) at F&N regarding isolation test result. he will call back. received message from Jason. 05/22/09-Hiralkumar Patel. spoke with Jason. Jason mentioned that during initial test, oil/water separator was connected to the tank system and test was inconclusive. they disocnnected oil/water separator from tank system and then tested tank system and system passed. asked Jason to send copy of test result. received tank test result. test result forwarded to DEC Falvey for review. case closed. "
Remarks:	"TANK TEST FAILURE ON A 1000 GALLON UST. TANK IS EMPTY. UNK IF ANY PRODUCT SPILLED."

NYC DEPT OF SANITATION (Continued) **S109583684**

All Materials:

Site ID:	411708
Operable Unit ID:	1168187
Operable Unit:	01
Material ID:	2159797
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

CU1026 **NYC SANITATION** **NY LTANKS** **S117535323**
NNW **640 WEST 26TH STREET** **N/A**
1/4-1/2 **NEW YORK, NY**
0.460 mi.
2431 ft. **Site 2 of 4 in cluster CU**

Relative: **Lower**

Actual: **6 ft.**

LTANKS:

Name:	NYC SANITATION
Address:	640 WEST 26TH STREET
City,State,Zip:	NEW YORK, NY
Spill Number/Closed Date:	1410686 / Not Reported
Facility ID:	1410686
Site ID:	504387
Spill Date:	2015-02-04
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MSHOQUE
Referred To:	Not reported
Reported to Dept:	2015-02-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	1
Date Entered In Computer:	2015-02-04
Spill Record Last Update:	2022-03-10
Spiller Name:	AL NIGNONE
Spiller Company:	NYC SANITATION
Spiller Address:	640 WEST 26TH STREET
Spiller County:	999
Spiller Contact:	AL NIGNONE
Spiller Phone:	(718) 334-9100
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	459269
DEC Memo:	"2-4-15 - Obligado (Desk Duty) - I called AARco and left message to

NYC SANITATION (Continued) **S117535323**

call back DEc. 2-5-15 - Obligado - I called Aarco again, left another message for John Bananno 08-03-2018 As per Remediation Section B Chief Vadim Brevdo, this spill case is reassigned from Vadim Brevdo to MD. S. Hoque as project manager effective August 3, 2018. -MDH 10/23/2018-M.Hoque: Spoke to AARCO(Kathrine and Mike)and discussed the latest status of the spill case. AARCO sent the tank test report. The report stated that a dry portion of the tank was leaked. Tank test was conducted on 2/4/2015 and was failed. Mike told that the tank was emptied. NYC Sanitation did not contact with AARCO for further investigation. (MDH) 4/2/2021-M.Hoque: An email sent to Carlos R. Maldonado-Roubert, Project Director, Public Buildings, Transportation Program Unit Tanks & Remediation requested to submit a site update report. (MDH) 4/8/2021-M.Hoque: The email below received from DDC: From: Aliberti, Jerry (DDC) Thu 4/8/2021 11:55 AM To: Hoque, MD S (DEC) Cc: Roberts, Harvey ; Heede, Connor ; Roger Stevens (PMS Construction Management) ; Tom Larison ; Wesolowski, Martin (Wesolowskim@liro.com); Samani, Afsar (DDC) ; Maldonado-Rouber, Carlos (DDC) ; Fullwood, Harvey (DDC) ; Walton, Ricardo (DDC) ; Brevdo, Vadim (DEC) Good morning MD S Hoque, Thanks for bringing this open spill to our attention. Through our Consent Order with NY State, DDC routinely addresses these spills with monitoring from DEC s Vadim Brevdo and his staff. This spill was generated by a DSNY contractor quite some time ago, but was never disclosed to DDC. However unfortunate that this spill has gone unnoticed by DDC, I m glad to inform you that funding is currently being procured to replace all 7 petroleum storage tanks at this site. Our design consultant, LiRo, and construction manager, PMS, are ready and able to commence this work as soon as the funds are allocated hopefully within 2 to 3 months. Feel free to contact me if you have any questions or concerns. Best regards, Jerry Aliberti, CCM - Deputy Program Director - Public Buildings Division Transportation Program Unit New York City Department of Design + Construction - 30-30 Thomson Avenue - Long Island City, NY 11101 T: 718-391-1073 - M: 917-731-6613 - aliberti@ddc.nyc.gov At 1:56 pm, another email received from Mr. Harvey Roberts of AECOM. Contract PW348-63 will add the Manhattan Repair Shop to its Site List. From: Roberts, Harvey To: Aliberti, Jerry (DDC) ; Brevdo, Vadim (DEC) ; Hoque, MD S (DEC) Jerry, Harvey Roberts Project Manager 605 Third Avenue, 2nd Floor New York, NY 10158 Direct: (212)896-0371 4/9/2021-M.Hoque: At 2:40 pm, Carlos Rouber(347-598-3941) of NYC DDC called me to discuss how to go forward to complete the site remediation. He said that AECOM will work for DDC and it will take 2 to 3 months to start the remediation. Hw will keep the Department updated on this matter. (MDH) 9/9/2021-M. Hoque: Sent an email to Harvey Roberts and others/DDC/AECOM regarding status of the site remediation. (MDH) 9/13/2021-M. Hoque: On September 13, 2021, below email received from the Consultant Attention MD Hoque: DDC has assigned The Manhattan Boro Repair Shop to Contract PW348-71, being performed by the firm, PMS. The PMS scope of work is to remove and replace seven USTs, including piping and related equipment. PMS is currently performing the site inspections needed to prepare its Pre-Design report. Harvey Roberts Project Manager 605 Third Avenue, 2nd Floor New York, NY 10158 3/10/2022-M. Hoque: The email below received for AECOM: From: Roberts, Harvey Sent: Thursday, March 10, 2022 12:06 PM To: Hoque, MD S (DEC) ; Aliberti, Jerry (DDC) Cc: Heede, Connor ; Roger Stevens (PMS Construction Management) ; Tom Larison ; Wesolowski, Martin (Wesolowskim@liro.com) ; Samani, Afsar (DDC) ; Maldonado-Rouber,

NYC SANITATION (Continued) **S117535323**

Carlos (DDC) ; Fullwood, Harvey (DDC) ; Walton, Ricardo (DDC) ; Heede, Connor Subject: RE: NYSDEC Spill case # 1410686, 640 W 26th Street, Manhattan, NY (DSNY Manhattan Boro Repair Shop) Mr. Hoque, NYCDDC transferred the remedial responsibility for Spill Case #1410686, DSNY Manhattan Borough Repair Shop, located at 640 West 26th Street, to another contractor. It is my understanding that NYCDDC the new contractor will replace the tank systems at the facility. Harvey Roberts Project Manager 605 Third Avenue, 2nd Floor New York, NY 10158 Direct: (212)896-0371"

Remarks: "caller reporting a failed tank test on a 1,000 gallon tank. tan will removed and replaced."

All Materials:

Site ID:	504387
Operable Unit ID:	1253734
Operable Unit:	01
Material ID:	2256047
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

1027 ENE 1/4-1/2 0.466 mi. 2463 ft.

OLD GAS STATION **NY LTANKS** **S103824054**
276 7TH AVE **N/A**
MANHATTAN, NY

Relative: Higher

Actual: 31 ft.

LTANKS:

Name:	OLD GAS STATION
Address:	276 7TH AVE
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9813276 / 2002-10-24
Facility ID:	9813276
Site ID:	116261
Spill Date:	1999-01-29
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1999-01-29
CID:	270
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1999-01-29

OLD GAS STATION (Continued) **S103824054**

Spill Record Last Update:	2009-09-23
Spiller Name:	CALLER
Spiller Company:	OLD GAS STATION
Spiller Address:	276 7TH AVE
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	(212) 340-9812
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	101195
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE see file."
Remarks:	"CONTAMINATED SOIL AND GROUNDWATER DISCOVERED DURING TANK REMOVAL"

All Materials:

Site ID:	116261
Operable Unit ID:	1073717
Operable Unit:	01
Material ID:	310004
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

1028
NNE
1/4-1/2
0.468 mi.
2473 ft.

MANHATTAN GENERAL MAIL FACILITY **SEMS-ARCHIVE** **1003864514**
WEST 29TH & 9TH AVE **NY6180000352**
NEW YORK, NY 10001

Relative:
Higher

Actual:
29 ft.

SEMS Archive:

Site ID:	0203777
EPA ID:	NY6180000352
Name:	MANHATTAN GENERAL MAIL FACILITY
Address:	WEST 29TH & 9TH AVE
Address 2:	Not reported
City,State,Zip:	NEW YORK, NY 10001
Cong District:	15
FIPS Code:	36061
FF:	Y
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	02
Site ID:	0203777
EPA ID:	NY6180000352
Site Name:	MANHATTAN GENERAL MAIL FACILITY
NPL:	N
FF:	Y
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1

MANHATTAN GENERAL MAIL FACILITY (Continued) **1003864514**

Start Date:	Not reported
Finish Date:	1993-09-15 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse
Region:	02
Site ID:	0203777
EPA ID:	NY6180000352
Site Name:	MANHATTAN GENERAL MAIL FACILITY
NPL:	N
FF:	Y
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1992-07-17 04:00:00
Finish Date:	1992-07-17 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0203777
EPA ID:	NY6180000352
Site Name:	MANHATTAN GENERAL MAIL FACILITY
NPL:	N
FF:	Y
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	1993-09-15 04:00:00
Qual:	N
Current Action Lead:	Fed Fac

1029 South 1/4-1/2 0.469 mi. 2478 ft. **UNKNOWN RESIDENCE** **NY LTANKS** **S118263503**
55 PERRY ST **N/A**
MANHATTAN, NY

Relative: Higher

Actual: 24 ft.

LTANKS:

Name:	UNKNOWN RESIDENCE
Address:	55 PERRY ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	1506662 / 2015-11-05
Facility ID:	1506662
Site ID:	514089
Spill Date:	2015-09-23
Spill Cause:	Tank Test Failure
Spill Source:	Unknown
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2015-09-23

UNKNOWN RESIDENCE (Continued) **S118263503**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-09-23
Spill Record Last Update:	2015-11-05
Spiller Name:	RENE LEWIS
Spiller Company:	UNKNOWN RESIDENCE
Spiller Address:	55 PERRY ST
Spiller County:	999
Spiller Contact:	RENE LEWIS
Spiller Phone:	(917) 569-8323
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	468566
DEC Memo:	"pbs-2-603465 9/23/15- DeC Piper spoke with Rene Lewis. He will email contact info for Building. "
Remarks:	"DRY LEAK"

All Materials:

Site ID:	514089
Operable Unit ID:	1263296
Operable Unit:	01
Material ID:	2266985
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

CU1030 **601 WEST 26TH STREET** **NY LTANKS** **S104275653**
NNW **601 WEST 26TH STREET** **NY Spills** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.470 mi.
2479 ft. **Site 3 of 4 in cluster CU**

Relative: **Lower**
Actual: **7 ft.**

LTANKS:

Name:	601 WEST 26TH STREET
Address:	601 WEST 26TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9100519 / 1997-10-16
Facility ID:	9100519
Site ID:	154650
Spill Date:	1991-04-12
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	TJDEMEO

601 WEST 26TH STREET (Continued) **S104275653**

Referred To:	Not reported
Reported to Dept:	1991-04-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-04-17
Spill Record Last Update:	2005-08-02
Spiller Name:	Not reported
Spiller Company:	OWNER
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	131104
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 05/18/2001 Reassigned from Finger to Demeo"
Remarks:	"20K TANK, TANK DORMANT FOR 4YRS,WATER GETTING INTO TANK VIA FILL LINE,OIL FLOATED OUT ONTO CONCRETEBASEMENT FLOOR IN TANKROOM,VAC TRUCK & SPEEDY DRY WAS USED."

All Materials:

Site ID:	154650
Operable Unit ID:	951519
Operable Unit:	01
Material ID:	426710
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	150.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	601 WEST 26TH STREET
Address:	601 WEST 26TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9304676 / 2006-05-22
Facility ID:	9304676
Facility Type:	ER
DER Facility ID:	131104
Site ID:	154651
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3101
Spill Date:	1993-07-14
Investigator:	SMSANGES

601 WEST 26TH STREET (Continued) **S104275653**

Referred To:	Not reported
Reported to Dept:	1993-07-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-07-14
Spill Record Last Update:	2006-05-22
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND 05/18/2001 Reassigned from Tomasello to Demeo 3/25/2004 Reassigned from Demeo to Sangesland 2/28/2005 Sangesland received a note from John Raguso stating that Emteque was going to begin it's remediation process at the site. The contractor will mobilize and then clean and close the remaining tanks onsite. Once the permits have been finalized, the contractor will then begin the major construction phase of the project to break ground, put in the required shoring and conduct the required remediation/soil removal activities. Contact: John Raguso 631-271-6622 7/7/05 Excavation has begun on the western tank field. When all soil is removed down to the water table (10-13 ft) the pit will be kept open and a vac truck will be on site for several days to vac out any petroleum floating on the water table. The site has several structural issues with surrounding buildings and a Security wall Several end points will be taken, but we already know that this whole area was coal ash fill from the late 1800's. We will expect to see SVOC's, but we do NOT want to see any VOC's. They will dig down to the water table, so that is as much soil removal as can be done. This work (on western tank field) should be finished by 7/15/05. Then similar work will be done on the eastern tank field John Raguso cell #646-529-6531 3/13/2006 Sangesland completed the review of a Spill Closure Petition Report prepared by Emteque Corp. (John Raguso - 631-774-9519) The report provides a history of the site including details of the 6 USTs on site. 3 were closed out several years ago and the other 3 were closed out in 2005 during this closure process. In additon, large soil excavations were made in the areas around these 6 tanks (3 eastern tanks & 3 western tanks) Due to structural issues, all of the contaminated soil could not be removed, but an overwhelming majority (over 95% according to Emteque) of the contaminated soil was removed. The end point sampling conducted in Oct 2005, show VOC and SVOC below TAGM and the GW samples were very good, with only some minor hits . The one item of some concern was Benzene. All 5 GW samples taken were above TAGM for benzene. The TAGM GW limit is 0.7ppb and the levels in all 5 GW samples ranged from 8.2ppb up to 43ppb. 3/30/2006 Sangesland confirmed with John Raguso at Emteque that another round of GW samples will be taken in April '06. If these numbers show a decline, the case may be closed due to natural attenuation. 5/22/2006

601 WEST 26TH STREET (Continued) **S104275653**

Sangesland reviewed a submittal from John Raguso of Emteque. As requested by the DEC, another round of groundwater samples were taken at the site. These samples showed the expected drop in contamination levels. While there are still some slight exceedences of the GW standards, the NYSDEC believes these levels will attenuate naturally over time. Based on the high commercial usage level of the area and the history of train yards, gas stations and historical fill the site is OK to close out as is with no further action Closure letter was sent to 601 West Associates c/o John Raguso with specific requirement to properly close out all monitoring wells on the site."

Remarks: "GAGE LINE BROKE ? CONTAINED IN BOILER RM. AND TANK ROOM - PETROL TANK CLEANER IS SUCKING UP OIL NOW. SENT TO DEP."

All Materials:

Site ID:	154651
Operable Unit ID:	986355
Operable Unit:	01
Material ID:	398160
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2500.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	COMMERCIAL PROPERTY
Address:	601 WEST 26TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	1211206 / 2012-12-04
Facility ID:	1211206
Facility Type:	ER
DER Facility ID:	131104
Site ID:	474343
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	3101
Spill Date:	2012-11-18
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2012-11-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-11-18
Spill Record Last Update:	2012-12-04
Spiller Name:	Not reported
Spiller Company:	EAST COAST PATROLEUM

601 WEST 26TH STREET (Continued) **S104275653**

Spiller Address: Not reported
Spiller Company: 999
Contact Name: ANTHONY MILANESE
DEC Memo: "spill to sidewalk during tank fill. cleanup done by oil delivery company. "
Remarks: "1507 THE SPILL WAS DUE TO A TANK OVER FLOW ONTO ASPHALT. THE SPILL IS CONTAINED. THE CLEAN UP HAS BEEN CONDUCTED."

All Materials:
Site ID: 474343
Operable Unit ID: 1224182
Operable Unit: 01
Material ID: 2222354
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

Name: 26 TH & 11TH AVE
Address: 601 WEST 26TH STREET
City,State,Zip: MANHATTAN, NY
Spill Number/Closed Date: 0406966 / 2005-10-06
Facility ID: 0406966
Facility Type: ER
DER Facility ID: 131104
Site ID: 198670
DEC Region: 2
Spill Cause: Other
Spill Class: D4
SWIS: 3101
Spill Date: 2004-09-23
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 2004-09-23
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-09-23
Spill Record Last Update: 2005-10-06
Spiller Name: REBECCA TUMMON
Spiller Company: IN FRONT 601 21ST STREET
Spiller Address: 26 TH & 11TH AVE
Spiller Company: 001
Contact Name: REBECCA TUMMON
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 10-06-05: Contamination discovered in boring for #7 line

601 WEST 26TH STREET (Continued) **S104275653**

extension in front of 601 West 26th Street. A second boring in the area (0407003) was also contaminated. Exisiting spill # 0311818. Closed and referred. Boring log and notes in eDocs."

Remarks: "DURING DRILLING FOUND A STRONG ODOR AND CONTAMINATED SOIL: 20-50 PPM: INVESTIGATION WAS FOR NYC TRANSIT"

Name:	IN BASEMENT OF WAREHOUSE
Address:	601 WEST 26TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	1106143 / 2013-03-26
Facility ID:	1106143
Facility Type:	ER
DER Facility ID:	408426
Site ID:	453819
DEC Region:	2
Spill Cause:	Other
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2011-08-28
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2011-08-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-08-28
Spill Record Last Update:	2013-03-26
Spiller Name:	SANDY HAHN
Spiller Company:	RXRSL OWNER LLC
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	TODD HASSOLD
DEC Memo:	"08/28/11-Hiralkumar Patel. 9:45 PM:- visited site. met Todd from Recovery. inspected boiler room. found water and oil in boiler room. Todd mentioned that they could not inspect the entire boiler room as water in rear of the boiler room is deeper and water level was rising. spoke with Mario, building super. he mentioned that there are no drains in the boiler room floor and only one sump pit in entire boiler room. sump pit has four pumps inside it. they had 3,000 gal vacuum truck which can not hold all the water/oil in the boiler room. also, they were not sure about condition in rear of the boiler room. absorbent pads were on water. as water level was rising, Todd was worried about impact to electric panels which is about 10 higher than water level in boiler room. Todd requested to turn on sump pumps to throw water only from bottom into city sewer system. he mentioned that by lowering water level, oil may impact the wall and other structure, but that can be cleaned easily with power wash at later time. but he was worried about impacting electric panels and other part of basement as water level was rising. after discussing with DEC Austin, approved Todd's request to turn on sump pumps so they can

601 WEST 26TH STREET (Continued) **S104275653**

lower the water level in boiler room. after they remove most of the water (only), they will remove remaining water/oil into vacuum truck. asked Todd to secure sump area with absorbent pads and booms to prevent any oil get into city sewer system. also asked him to turn off pumps frequently to check boiler room for any unusual thing. asked Todd to call with update. Mario mentioned that the entire tank system is turned off. Mario Onichimiuk **building super** Ph. (917) 817-1927 Todd Hassold Recovery Environmental Services, Inc. PH. (973) 940-3144 (O) (973) 896-6185 (C) Fax (973) 940-3146 email: thassold@recoverysrvs.com 08/29/11-Hiralkumar Patel. 9:45 AM:- visited site. cleanup crew was still on-site removing oil. two sump pumps were still working. currently, contractor is skimming off oil from top of water. after water level dropped, super inspected the rear end of the boiler room and found two buckets were knocked down during flooding and caused spill. inspected tank room which is in garage area. site has two 20,000 gal #6 oil ASTs. no spill inside the tank room. boiler room is right underneath the tank room location. as per super, no leak noticed from any fuel piping. asked Mario to call back for re-inspection, once basement is dry. 5:09 PM:- received call from Tom from Recovery. he mentioned that during cleanup, they found oil/water separator in back of the boiler room. he requested a site inspection. 08/30/11-Hiralkumar Patel. 11:00 AM:- visited site. met Tom from Recovery. inspected boiler room. Tom mentioned that sump pumps were turned off yesterday night and when they left, area around sump was clean. but they found more oil this morning. during cleanup last night, they found oil/water separator in boiler room. inspected oil/water separator. found oil on top of oil/water separator, but no indication of any oil overflowed the separator. two pipes enters into oil/water separator. one pipe goes to a loading dock above the boiler room (contractor will find out where this pipe comes from) and second pipe goes into a tunnel located at the west end of the boiler room. there is an hatch boiler room ceiling in area where the oil/water separator inlet pipe crosses to loading dock. tunnel is located along the boiler room ceiling in west end of the boiler room. this tunnel runs east-west and then north-south. this tunnel structure is completely within building footprint and underneath the loading dock area. found oil leak from the northern most end of the tunnel. currently active tanks are located right above the northern end of the tunnel and currently active supply/return lines running aboveground in tunnel. no sign of leak found from currently active lines. found two sumps in the tunnel: first along the western wall of the north-south portion of the tunnel and another along the southern wall of the east-west portion of the tunnel. found a pipe coming out of the western wall of the tunnel in the area south of sump in north-south section. Tom closed the valve on this pipe and water flow into the separator was dropped. as purpose of this inlet pipe was unknown, asked Tom to leave valve open. Mario mentioned that there were three 20,000 gal #6 oil USTs abandoned-in-place behind the western wall of the tunnel (north-south section). found oil seepage from the northern wall of the ease-west section of the tunnel. as sump pumps in tunnel are connected to the oil/water separator, it looks like whatever oil seeped into the tunnel was thrown into oil/water separator. as there was no oil recovery from the separator, oil followed the water discharge pipe into the main sump. informed Mario that main sump pumps must not be used until the cleanup is completed as water coming into sump may be contaminated (dissolved phase). all water from basement must be disposed off as contaminated

601 WEST 26TH STREET (Continued) **S104275653**

material. as per Mario, the former 20,000 gal tanks were under the loading dock platform. Mario gave copy of tank abandonment documents. as per the documents: - Don Carlo Environmental abandoned three (3) 20,000 gal USTs on 07/10/2001. tanks were abandoned using foam and lines were discontinued and closed - Malbro Inc. abandoned three (3) 20,000 gal USTs in Aug. and Sep. of 2005. tanks and all associated piping were filled with lightweight cellular concrete slurry mixture during inspection, found a 3,000 gal diesel AST for emergency generator. Mario mentioned that emergency generator is located on first floor. during inspection, found a coned vault in boiler room containing high voltage lines. this coned vault is located on other side of boiler room, opposite of the main sump in the boiler room. met with Sandy Hahn, property manager. informed her that leak in the boiler room, could be left over spilled material inside the concrete vault (if any) around the former 20,000 gal USTs. due to heavy rain over the weekend (harricane Irene), water may have entered around the abandoned tanks and pushed oil into the tunnel which end up into main sump via oil/water separator. asked her to submit a scaled site map with old/current tanks, piping, tunnel, sumps (in passage as well as boiler room) and oil/water separator. asked her to find out purpose of the pipe that comes out from the old UST area. also asked her to investigate in the old tank area. RXR SL Owner LLC. **property owner** c/o RXR Realty 601 West 26th Street, Suite 1260 New York, NY 10001 Attn.: Sandra Hahn **property manager** Director of Operations PH. (212) 400-2440 (212) 924-3880 (917) 574-4085 (C) Fax (212) 727-3752 email: shahn@rxrrealty.com alternate addresses: 601-649 West 26th Street, 600-650 West 27th Street, 245-259 11th Ave, 198-218 12th Ave PBS #s: 2-600389, 2-604877, 2-607987, 2-611131 as per PBS #: 2-600389 (which is expired), site has/had following tanks: - three 20,000 gal ASTs in vault with access and currently active - three 20,000 gal #6 oil ASTs in vault with access and closed-in-place as per PBS #: 2-604877 (which is expired), site has one 10,000 gal diesel AST on legs. diesel tank installed in Apr. 2000. as per PBS #: 2-607987, site has one 275 gal waste oil AST on legs. as per PBS #: 2-611131, site has one 10,000 gal diesel AST in contact with imprevious barrier. tank was installed in Jan. 2000. other spills #: 9100519, 9106840, 9304676, 9412158, 0311818, 0406966, 0407003, 0911011 spill #: 9100519 was reported on 04/12/1991 as 150 gal #6 oil spilled onto basement floor. oil spilled as water entered into tank through fill line. case closed. spill #: 9106840 was reported on 09/25/1991 as #6 oil spilled into tnak room. case closed. spill #: 9304676 was reported on 07/14/1993 as 2,500 gal #6 oil spilled into tank and boiler room. case closed after investigation/remediation. spill #: 9412158 was reported on 12/12/1994 as 15 gal gasoline spilled onto road pavement. case closed. spill #: 0311818 was reported on 01/21/2004 as 4,000 gal #4 oil spill. spill was reported by anonynomous caller. spill was closed and merged with spill #: 9304676. spill #: 0406966 was reported on 09/23/2004 by NYC Transit. they found petroleum odors and contaminated soil in boring installed in front of 601 W 26th street. this boring was installed as part of 7 line extension project. case closed and merged with spill #: 0311818. spill #: 0407003 was reported on 09/24/2004 by NYC Transit. they found petroleum odors and contaminated soil in boring installed in front of 601 W 26th street. this boring was installed as part of 7 line extension project. case closed and merged with spill #: 0311818. spill #: 0911011 was reported on 01/12/2010 due to dielectric fluid spilled in vault (probably vault in boiler room). case closed. found

601 WEST 26TH STREET (Continued) **S104275653**

files on e-docs for spill #: 9304676, 0406966 and 0407003. review of documents under spill #: 9304676
--*-

601 WEST 26TH STREET (Continued) **S104275653**

installing more monitoring wells) found around the western tank field - Emteque installed three (3) 4-inch monitoring well through the sidewalk equally spaced around the northeast corner of the intersection of 12th Ave and 26th street - three wells (MW-6, MW-7 and MW-8) were installed to a depth of 14 ft bg with 10 ft of screen - wells were set aprpox. 7 ft into the water table - no evidence of fuel oil contamination was identified in wells - soil samples collected at the water table during the well installation - no contamination found in soil samples collected during well installation - advanced five (5) soil borings (ETFSB-1 through ETFSB-5), to a depth of 12-16 ft bg, through the basement floor over the eastern tank field, collecting soil samples to a depth of approx. 4 ft below the groundwater table - soil samples collected at the water table during soil boring installation - no contmaination found in soil samples collected from soil boring in eastern tank field - 1 inch piezometers installed in three borings (ETFSB-1, ETFSB-2 and ETFSB-3) surrounding the tank field to the south and east - tunnel's wall contains groundwater on west side of eastern tank field - access was not provided to the north side of the eastern tank field - free phase product found on water in eastern tank field area - investigation revealed that contamination associated with leak from the house tank appears to be contained within the vicinity of the house tank between the south wall, the north adjacent tank, the western tank tunnel and has not migrated more than 10 ft east of the tank 4) 06/16/2003: Revised Proposed Petroleum Contamination Corrective Action Plan: - groundwater local to the western tank field is approx. 10 ft below the first floor slab, approx. 6 ft below surrounding grade and flowing predominantly westerly - groundwater lcoal to the eastern tank field is approx. 10 ft below the parking garage of the FBI unit and apparently not flowing, since the groundwater flow is restricted on its western margin by the tank tunnel and to the south and east by basement boiler room walls - a small local easterlly gradient in the vicinity of the plume around western tank field and also in eastern tank field is being induced by dewatering to prevent flooding of the building basement 5) Spill Closure Petition Report: <--------- missing 6) 05/12/2006: Spill Closure Petition Report - Update #1: - collected groundwater samples from well MW-1 and recovery wells RW-1, RW-2, RW-3 and RW-4 - found minor VOC contamination during second round (maximum 46 ppb Benzene in RW-1) - removed almost 53,000 gal of contaminated groundwater and 1,637 tons of soil from the site
- review of documents under spill #s: 0406966 and 0407003
+-/+-/+-/

601 WEST 26TH STREET (Continued) **S104275653**

petroleum odor and black staining were noted in the soil (PID: 83 ppm) at 6 ft bg. boring was extended to 11 ft bg. strong petroleum odors persisted in entire boring length (PID from 60 to 70 ppm). boring SB2-4 was temianted at 11 ft bg (due to obstruction) and was abandoned. based on notes from MTA, both borings were installed on eastern property line, but the #6 oil storage tanks (associated with spill #: 9304676) were located along the western side of the property. contamination found in borings under the west sidewalk of 11th ave, could be result of petroleum release from other tanks on property (owned by tenants).
+-/+-/+-/

601 WEST 26TH STREET (Continued) **S104275653**

(C) Fax (212) 867-9715 email: mborello@ebsllcnyc.com based on given information, a FBI rents building space on north side of eastern tank vault. 10:03 AM:- left message at FBI (212-384-5000). 09/01/11-Hiralkumar Patel. 8:00 AM:- received message from Mr. Borello. 12:25 PM:- spoke with Mr. Borello. he mentioned that based on available information, the new tanks are located right above the old western tank vault. they have collected water sample yesterday. he will submit scaled site map and water sample result by 09/08/11. 12:58 PM:- spoke with Eric at Emteque regarding missing initial spill closure report. Eric will check file and submit report, if available. Eric mentioned that they did Phase I report for Chase bank (lender) in 2010. Eric Telemaque Emteque PH. (212) 631-9000 email: eric@emteque.com 9/2/11-Vought-Received call from and spoke to Todd Hassold (Recovery Environmental Ph:973-896-6185) who noted that he had urgent issue on hand in that he was recovering approximately 25,000-gallons of oil/water mixture a day from the oil/water separator (source of water was seepage from adjacent Hudson River) and source of oil still undetermined. Hassold noted the liquid is mostly water with minor petroleum sheen. Hassold noted also that he was in the process of submitting a NYCDEP Discharge Permit Application to dispose of the water from the oil/water separator. Hassold noted that Clean Harbors was closed (disposal facility) and that he did not have the storage capacity for the 25,000-gallons per day over the weekend and such was requesting an emergency permit to discharge to the sewer. Vought spoke to DEC Elburn who noted that due to Hurricane (causing of flooding) that DEC had an emergency permit reqiuirement exemption and as such no permit was needed for DEC. DEC Elburn noted however that NYCDEP also needed to be contacted (NYCDEP Leslie Lipton Ph:718-595-4730). Hassold called Lipton and as per Hassold, Lipton did not respond but Hassold was told by another DEP employee to call 311. Vought suggested that Hassold send an email with a description of the issue to DEC Vought as soon as possible so that he may forward email to DEC Patel, Elburn and DEP Lipton. Vought received email from Thomas Domke (VP Operations Recovery Environmental) confirming phone conversation but not including any details of issue. Vought sent reply email with cc to DEC Patel, Elburn and DEC Lipton that a full description is needed and that Vought on vacation for next two weeks and as such all parties should be copied on full description. Vought and all parties received full description and Vought reviewed description with DEC Water Unit Elburn and sent reply email that DEC had no objections to discharge to sewers as long as NYCDEP requirements were met also. 09/07/11-Hiralkumar Patel. 10:41 AM:- received call from Todd. he mentioned that NYC DEP approved water discharge to city sewer. now the entire boiler room is dry. 10:50 AM:- received call from Mr. Borello. he mentioned that no dissolved contamination found in water sample collected from boiler room last week. asked him to submit result for review. he also mentioned that they are waiting for result of water sample that was collected to get DEP permit to discharge water from oil/water separator into city sewer system. currently, they are planning to drill some holes in tunnel walls for further investigation. Mr. Borello will submit scaled site map today. 12:21 PM:- received message from Eric. he did not found spill closure report prepared probably in Oct. 2005. 09/08/11-Hiralkumar Patel. 10:22 AM:- received email from Mr. Borello including site map (including oil tanks on property), desgin of oil/water separator system and groundwater sample result. no dissolved contmaination

601 WEST 26TH STREET (Continued) **S104275653**

found in water sample. as per the submitted site map, the entire site has total of fifteen (15) tanks: - one 5,000 gal tank at the end of garage ramp (from W 27th street), owned by property owner - two 20,000 gal tanks (currently in-service #6 oil tanks) in loading dock area, owned by property owner - one 10,000 gal tank in loading dock area, owned by Broadview - one 3,000 gal tank (diesel tank) in loading dock ramp, owned by Level III - four 275 gal tanks on 3rd floor, owned by property owner - four 275 gal tanks on 4th floor, owned by Broadview - two 250 gal tanks on 6th floor, owned by Level III reviewed PBS record again. PBS #: 2-600389 - three 20,000 gal in-service #6 oil ASTs in vault with access and three 20,000 gal closed-in-place #6 oil ASTs in vault with access. this PBS registration has expired in July 2006. as per PBS record, tanks owned by previous property owner. as per available information, the remaining three tanks were also closed-in-place in 2005. this PBS registration needs to be renewed/updated/closed with correct information (tanks closed/new property owner). PBS #: 2-604877 - one 10,000 gal diesel AST on legs/saddles. as per PBS record, tank owned by Wiltel Communications Group, Inc. this registration has expired in Dec. 2010. this registration needs to be renewed. PBS #: 2-607987 - one 275 gal waste oil AST on legs/saddles. as per PBS record, tank owned by Verizon. registration currently active. PBS #: 2-611131 - one 10,000 gal diesel AST in contact with imprevious barrier. tank was installed in Jan. 2000. as per PBS record, tank owned by Level III Communications LLC. registration currently active. this registration may need to be updated because as per Mr. Borello, Level III owns a 3,000 gal diesel AST (which is located in loading dock ramp). 2:27 PM:- spoke with Timothy Kimball at Level III Communications. he confirmed that Level III owns 10,000 gal diesel tank which is located in loading dock area and a generator is located next to the tank. he mentioned that they don't own 3,000 gal diesel tank. he also confirmed that they don't have any day tanks on 6th floor. during conversation, he mentioned that Level 3 Communication acquired Wiltel Communications Group in 2007-2008. informed him that the tank registration under Wiltel Communication (for 10,000 gal diesel tank) has not been closed out properly. asked him to close the PBS registration that is under Wiltel Communications's name. Timothy Kimball Level 3 Communications LLC. (also owns Wiltel Communications Group) Ph. (720) 888-4744 email: timothy.kimball@level3.com 2:51 PM:- left message Gregory Myka (315-432-8486) at Verizon to confirm that Verizon only owns one 275 gal waste oil tank at the site. 3:05 PM:- left message for Mr. Borello and informed him that tanks' information provided on map is not accurate. 4:36 PM:- received message from Mr. Myka from Verizon. he confirmed that they have only one 275 gal waste oil tank at the site. they don't have any other tanks. 4:42 PM:- received message from Mr. Borello. he mentioned that he got tank's information from chief engineer. but they will do site survey and talk to each tenant to find out exact number of tanks and its owners. 09/09/11-Hiralkumar Patel. 9:18 AM:- visited site. inspected boiler room. no oil or sheen found on water in entire boiler room. boiler room walls/floor and other oil impacted structures were cleaned. found clean water going into main sump from oil/water separator. frac tank was on W 27th street, but wasn't connected to main sump. 9:27 AM:- spoke with Mr. Borello. informed him that there are multiple PBS records for the subject site. he requested copy of PBS records. 3:49 PM:- sent email to Mr. Borello including PBS records. asked him to submit all on-site tank's information (location, size, owner etc.) by

601 WEST 26TH STREET (Continued) **S104275653**

the end of 09/16/11. informed him that PBS registrations must be updated/renewed immediately. email copied to Ms. Hahn. 09/14/11-Hiralkumar Patel. 10:43 AM:- spoke with Todd. he mentioned that insurance company requested an estimate for investigation. Todd is preparing the estimate and will submit to insurance company. 09/19/11-Hiralkumar Patel. received PBS application package in FedEx. as per submitted application, site has following tanks: - two 20,000 gal #6 oil ASTs in loading dock area; tank owned by property owner - one 5,000 gal #2 oil AST in basement (at end of garage ramp from W 27th street); tank owned by property owner - one 250 gal #2 oil AST in generator room on 3rd floor; tank being used to start up the generator; tank owned by property owner - one 250 gal #2 oil AST on 3rd floor along 12th Ave side by Verizon; tank being used to start up the generator; tank owed by property owner - two 250 gal ASTs on 3rd floor along 11th ave side; both tanks are closed-in-place; tanks owned by property owner - one 10,000 gal diesel tank in loading dock; tank owned by Broad View Network - one 250 gal #2 oil tank under the generator in central office on 4th floor; tank owned by Broad View Network - one 250 gal #2 oil tank closed-in-place in central office on 4th floor; tank owned by Broad View Network - one 250 gal #2 oil tank under the generator in data center on 4th floor; tank owned by Broad View Network - one 250 gal #2 oil tank closed-in-place in data center on 4th floor; tank owned by Broad View Network - one 10,000 gal diesel tank in loading dock (PBS #: 2-611131); tank owned by Level 3 Communication - one 247 gal waste oil tank in basement (PBS #: 2-607987); tank owned by Verizon - one 1,000 gal waste oil tank in basement; tank owned by FBI - one 500 gal oil tank on 2nd floor; tank owned by FBI there is no information about 3,000 gal AST observed in loading dock area. 09/20/11-Hiralkumar Patel. 12:18 PM:- received message from Mr. Borello. 4:29 PM:- spoke with Mr. Borello. he mentioned that they drilled some holes in both side tank vaults and found oil pouring out from holes. as such they will break larger access to these vaults for further inspection/cleanup. he will send pics that he collected today. he will also schedule a site inspection, once larger holes made in wall. 4:31 PM:- receive email from Mr. Borello including a pic and a video showing oil pouring out of vault. 09/23/11-Hiralkumar Patel. 1:18 PM:- received call from Todd. he mentioned that they drilled small holes in both vaults and found product coming out from eastern vault only. only water came out through holes in western vault. based on that observations, they made 18 inches by 24 inches hole in western wall of the eastern vault (vault towards the boiler room). found free product in the vault. Todd mentioned that the hole is about 2 ft above the product level in vault, so they are not concerned about overflow through this hole. as there is heavy rain for today and tomorrow, asked Todd to secure the hole to prevent any spill in boiler room, if water level rise in vault. scheduled a site inspection at 3:30 PM on 09/26/11. 1:55 PM:- spoke with Mr. Borello. informed him about possibilty of oil overflow from hole in eastern vault due to heavy rain. Mr. Borello has already spoken with building management/super and they will inspect area frequently. if any spill noticed, they will call contractor for cleanup. also informed Mr. Borello about no information on PBS application about 3,000 gal tank observed in loading dock area. Mr. Borello will confirm that and will submit revised PBS application. 09/26/11-Hiralkumar Patel. 3:30 PM:- visited site. inspected hole made in eastern tank vault area. found free product and water in hole. the area behind the wall was filled with construction debris

601 WEST 26TH STREET (Continued) **S104275653**

and filled with large concrete/stone pieces. met Ms. Hahn, Todd, Tom and Mike. informed them that the department requires delineation of soil/groundwater contamination on north and east side of eastern tank vault. no investigation needed on west and south of the eastern tank vault (as it is in tunnel area). Tom mentioned that they only found some water from holes mades in western tank vault area. asked Mike to prepare a scaled site map for area around tank vaults. asked Ms. Hahn to submit an investigation work plan for delineation. during meeting, Mike confirmed that the 3,000 gal diesel AST observed in loading dock area is owned by Broad View Network and there is no 10,000 gal tank owned by Broad View Network. Mike will submit revised PBS application to DEC Nick. forwarded previously received (incorrect) PBS application (which includes a check) to DEC Nick. asked him not to process application as a new updated PBS application will be submitted. 10/12/11-Hiralkumar Patel. received email from Ms. Hahn (at 11:39 AM on 09/30/11) including copy of revised PBS application and letter describing tank owners. PBS application was sent to PBS unit. as per revised tank owner letter, Broad View Network owns 3,000 gal diesel tank in loading dock and not the 10,000 gal diesel tank as mentioned in earlier PBS application submitted on 09/19/11. all other tank info is the same. 10/26/11-Hiralkumar Patel. 4:18 PM:- received email from Joe Horowitz (Horow137@aol.com) including copy of letter from DEP with conditional authorization for water discharge. 11/02/11-Hiralkumar Patel. 3:21 PM:- received email from Mike including a draft work plan for review. he proposed to install nine soil borings which will be converted to monitoring wells. these borings/wells are proposed around two sets of abandoned USTs. draft work plan doesn't include a work schedule. also need a site map with structures in basement (tunnel, sumps in tunnel, main sump in boiler room, oil/water separator and boring/well locations). 11/14/11-Hiralkumar Patel. 9:45 AM:- spoke with Mike. informed him that the draft work plan looks fine except it is missing two things: work schedule and a site map with structures in cellar (tunnel, sumps in tunnel etc.). he will submit final work plan. 02/03/12-Hiralkumar Patel. 4:31 PM:- left message for Mike. 4:32 PM:- sent email to Mike, Ms. Hahn and Todd inquiring update. 5:08 PM:- received email from Mike. they are in process of obtaining bids from drilling companies and will start work once contractor is selected. he mentioned that oil/water separator is working fine and no additional oil observed in basement. 02/07/12-Hiralkumar Patel. 2:13 PM:- sent email to Mike and asked him about schedule for contractor selection. also asked him about the amount of oil recovered since the oil/water separator turned on. email copied to Ms. Hahn. 02/21/12-Hiralkumar Patel. 11:15 AM:- received email from Mike. they are in final stage of hiring drilling contractor and will schedule work shortly. till now, they recovered less than 55 gal of oil. 07/24/12-Hiralkumar Patel. 2:27 PM:- received email from Mike. they have installed numerous borings and wells at the site. they are having some logistical problems in few areas and requested a site visit. 07/26/12-Hiralkumar Patel. 3:42 PM:- left message for Mike. asked him to submit status report for work done till now, prior to any site visit. 3:47 PM:- sent email to Mike and asked to submit status report for work done till now. informed him that site visit can be done only after completing review of the additional information. email copied to Ms. Hahn. 07/27/12-Hiralkumar Patel. 9:51 AM:- received email from Mike including site map and field notes. as per field notes, four wells installed at the site: two wells (Point A and Point B) on the west

601 WEST 26TH STREET (Continued) **S104275653**

side and two wells (Point G and Point H) on the east side of the former tank field. fuel oil smell noted during installation of wells Point A and Point B. Mike mentioned that a third well could not be installed on east side (in the FBI space) due to refusal. he also mentioned that driller is hesitant to drill in the boiler room due to possible flooding. 11:28 AM:- spoke with Mike. he mentioned that installation of four wells was completed on 07/23/12. dark soil and petroleum odors were noted during installation of wells Point A and Point B on the west side of the tank field. no sign of contamination observed in wells on east side (Point G and Point H) in FBI parking space. he does not know about any product on water as wells are not developed yet. asked him to develope the four wells, define site-specific groundwater flow direction and collect groundwater samples for VOC/SVOC analysis. informed him that wells should not be installed in basement boiler room due to possible flooding issues. asked him to submit detailed boring/well logs for review. 11:47 AM:- sent email to Mike and asked to submit boring/well logs, results of groundwater samples and site-specific groundwater flow direction by the end of 08/20/12. email copied to Ms. Hahn. 09/07/12-Hiralkumar Patel. 11:53 AM:- received email from Mike including soil boring logs and soil/gw data. received boring logs for borings Point A, Point B, Point G and Point H. Point A and Point B were installed in RXR Parking Garage and fuel oil smell noted in both borings at 10 ft depth. wells were installed to 25-30 ft depth in Point A and Point B. borings Point G and Point H were installed in FBI parking space. in Point G, bedrock encountered at 16 ft depth. found PID readings in Point A and Point B, but PID unit is not included in logs. as per lab report, four soil samples collected. one soil sample from 10 ft depth from each of four borings. no VOC contamination found in soil samples, but some SVOC compounds were detected (below cleanup standard) in soil samples. as per lab report, four groundwater samples collected from borings. no contamination found in groundwater samples. the site map does not show location of Point H. needs revised boring logs (with PID unit) and site map (with boring locations). 10/03/12-Hiralkumar Patel. 2:28 PM:- sent email to Mike. asked him to submit revised boring logs and site map. also asked him about amount of product removed till date using on-site recovery system. email copied to Ms. Hahn. 11/26/12-Hiralkumar Patel. went to site for inspection to see impact after hurricane Sandy. met with Mario. he mentioned that the entire basement was full of water, but no more oil observed on water. the oil/water separator, as part of the on-going cleanup, was emptied out right before storm. as boilers were damaged during storm, they have temporary boilers on street. they are also in process of converting to #2 oil. 01/15/13-Hiralkumar Patel. received message from Mike (at 1:11 PM on 01/14/13). he mentioned that he is waiting for response for data he submitted on 09/07/12. 11:33 AM:- sent email to Mike and informed him that the department responded on 10/03/12 and asked for revised boring logs and product recovery data, which has not received yet. 11:37 AM:- received email from Mike including copy of email that he sent on 10/09/12. email included revised boring logs and site map. 12:14 PM:- received email from Mike. they recovered less than 55 gal oil since oil/water separator installed. reviewed available boring logs, site map and sample results. borings A, B, G and H were installed to a depth of 25-30 ft bg (except boring G which was installed at 16 ft bg). maximum PID reading of 2 ppm was recorded at 10 ft in boring B which is located southwest of the former tank rooms. soil and

601 WEST 26TH STREET (Continued) **S104275653**

groundwater samples were collected from these four borings. no contamination found in soil or groundwater samples. 12:23 PM:- spoke with Mike. asked him to submit depth of borings/wells and former tank room reference to single point. 3:14 PM:- received email from Mike. he mentioned that points G and H inside the FBI space were to a depth of 15 ft and would be below the 6 USTs that were closed in place. he also mentioned that points A and B were advanced to a depth of 20 ft but from street grade and are not below the USTs. 01/30/13-Hiralkumar Patel. discussed with DEC Austin. based on site history, available sampling data and observations during site visit after hurricane Sandy, Austin asked to close the case. 1:59 PM:- sent email to Mike. asked him to submit spill closure report. email copied to Ms. Hahn. 02/28/13-Hiralkumar Patel. 2:43 PM:- sent email to Mike inquiring about closure report. email copied to Ms. Hahn. 03/22/13-Hiralkumar Patel. 4:50 PM:- received email from Sharon Dyal (sdyal@ebsllcnyc.com) from Environmental Building Solutions, including spill closure report. 03/26/13-Hiralkumar Patel. based on available information, case closed. 2:45 PM:- sent spill closure letter to Ms. Hahn. letter emailed to Ms. Hahn and Mike."

Remarks: "weather related - cleanup starting"

All Materials:

Site ID:	453819
Operable Unit ID:	1203975
Operable Unit:	01
Material ID:	2200714
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	500.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	601 WEST 26TH STREET
Address:	601 WEST 26TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0407003 / 2005-10-06
Facility ID:	0407003
Facility Type:	ER
DER Facility ID:	131104
Site ID:	127577
DEC Region:	2
Spill Cause:	Other
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2004-09-24
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2004-09-24
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

601 WEST 26TH STREET (Continued) **S104275653**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-09-24
Spill Record Last Update:	2005-10-06
Spiller Name:	REBECCA TUMMON
Spiller Company:	SIDEWALK OF 11TH AVE
Spiller Address:	601 WEST 26TH STREET
Spiller Company:	001
Contact Name:	REBECCA TUMMON
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE Boring on 11th Avenue. 10-06-05: Contamination discoveredin borings performed for #7 line extension. Contamination found in another boring in the area (0406966). Spill already exists for site 0311818. Closed and referred. Boring log and notes in eDocs."
Remarks:	"FOUND CONTAMINATED SOIL WWHILE DRILLING: MONITORING GROUND NOW; PID ARE BETWWEN 50-300PPM"

All Materials:

Site ID:	127577
Operable Unit ID:	890313
Operable Unit:	01
Material ID:	484846
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Name:	601 WEST 26TH STREET
Address:	601 WEST 26TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0311818 / 2006-03-30
Facility ID:	0311818
Facility Type:	ER
DER Facility ID:	131104
Site ID:	180561
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	2004-01-21
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2004-01-21
CID:	444
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

601 WEST 26TH STREET (Continued) **S104275653**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-01-21
Spill Record Last Update:	2006-03-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND Cross ref #9304676 1/21/2004 Sangesland contacted several parties associated with the spill in this building. Apparently on 1/20/2004 a leak was discovered in an elbow of the fill line in the basement Tunnel Room of this address. Building Manager: Harold Brody - Responsible Party According to Paul at New York Combustion (718-763-6100), Mr. Brody called NY Comb. to ask them to come and fix the leaking pipe. Paul informed Mr. Brody that a spill would need to be reported. Neither Mr. Brody or Paul reported the spill. Romeo Santos at Don Carlo Environmental (718-857-2100) was hired either evening of 1/20 or morning of 1/21 to do the actual clean up of the oil. Mr. Santos says that he called in the Anonymous spill report #0311818 earlier this morning and then he sub contracted the cleanup work to Petroleum Tank Cleaners. All clean up work is complete. Paul from New York Combustion finished the pipe repair work. 1/23/2004 PTC called to say that they in fact DID NOT complete the clean up at the site. PTC was hired only to vac out the liquid portion of the spill. PTC was told by Don Carlo Enviornmental that they will be responsible for the final cleanup. Don Carlo says the clean up was done by PTC and DC will not be doing any further work. In frustration, Sangesland sent DEC Enironmental Control Officer Paul Blanton to visit the site. He asked why the owner or consultants failed to call in the spill within the 2 hours required by law. There was considerable finger pointing and no one took responsibility for the error. There was some discussion of how the oil went into a second unused tank. No ticket was issued. 3/31/2004 As of this date, the case is still open. No follow up documentation has been submitted to the DEC to close out this case. 10-06-05: NYCT performing borings for #7 line extension. Two boring performedin the area of this facility noted strong contamination (04-06966 & 04-07003). Boring logs and notes in eDocs. MCT 3/30/2006 Sangesland closed this case and referenced this to spill #9304676. All tanks on site were removed. Impacted Soil was excavated. Still some impacted GW as of 10/05 Consultant will take another round of GW samples in 4/06. This spill is closed "
Remarks:	"718-857-1800- DC Enviormental phone, this is the only info I could get out of caller. Might be a leak in the fill line."

All Materials:

Site ID:	180561
Operable Unit ID:	879413
Operable Unit:	01
Material ID:	497061
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4000.00
Units:	G
Recovered:	.00

601 WEST 26TH STREET (Continued) **S104275653**

Oxygenate: Not reported

CU1031 **ELECTRICAL BUSS COMPARTMENT** **NY LTANKS** **S101341240**
NNW **601 W 26TH ST** **NY Spills** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.470 mi.
2479 ft. **Site 4 of 4 in cluster CU**

Relative:
Lower

Actual:
7 ft.

LTANKS:

Name:	601 W. 26TH ST
Address:	601 W. 26TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9412158 / 1994-12-12
Facility ID:	9412158
Site ID:	120666
Spill Date:	1994-12-12
Spill Cause:	Tank Failure
Spill Source:	Passenger Vehicle
Spill Class:	C4
Cleanup Ceased:	1994-12-12
SWIS:	3101
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1994-12-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-01-27
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	Unknown Vehicle
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	104757
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks:	"SPILL CONTAINED ON ROAD PAVEMENT. F.D. RESPONDED & SANITATION APPEAR SAND & P/UP"

All Materials:

Site ID:	120666
Operable Unit ID:	1005924
Operable Unit:	01
Material ID:	374490
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum

ELECTRICAL BUSS COMPARTMENT (Continued) **S101341240**

Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	ELECTRICAL BUSS COMPARTMENT
Address:	601 W 26TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	1403083 / 2014-06-20
Facility ID:	1403083
Facility Type:	ER
DER Facility ID:	451320
Site ID:	496428
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	D5
SWIS:	3101
Spill Date:	2014-06-20
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2014-06-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-06-20
Spill Record Last Update:	2014-06-20
Spiller Name:	Not reported
Spiller Company:	CONN ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"6/20/14 TJD Mahat contacted Con Edison ERT desk to confirm notification has been made to NYCDEP. ERT states NYCDEP and USEPA were notified. As per ERT, contractor removed copper piping with asbestos wrap to an unknown location. No furhter action required by DEC - spill closed."
Remarks:	"Caller advised more than 1 pound of asbestos has been removed from an electrical buss compartment unknown who took the product."

All Materials:

Site ID:	496428
Operable Unit ID:	1245916
Operable Unit:	01
Material ID:	2246986
Material Code:	0026A
Material Name:	asbestos
Case No.:	01332214
Material FA:	Hazardous Material

ELECTRICAL BUSS COMPARTMENT (Continued) **S101341240**

Quantity:	1.00
Units:	L
Recovered:	Not reported
Oxygenate:	Not reported

1032 NE 1/4-1/2 0.484 mi. 2556 ft. **APARTMENT BUILDING** **NY LTANKS** **S102662670**
347 WEST 29TH ST **N/A**
MANHATTAN, NY

Relative: Higher

Actual: 30 ft.

LTANKS:

Name:	APARTMENT BUILDING
Address:	347 WEST 29TH ST
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9608521 / 1996-11-22
Facility ID:	9608521
Site ID:	111829
Spill Date:	1996-10-08
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1996-10-09
CID:	297
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-10-09
Spill Record Last Update:	2004-07-20
Spiller Name:	Not reported
Spiller Company:	BAYSIDE FUEL OIL CORP
Spiller Address:	1810 SHORE PRKWY
Spiller County:	001
Spiller Contact:	SONDRA STEIN
Spiller Phone:	(212) 988-0688
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	97777
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was M TIBBE Bayside cleaned."
Remarks:	"CALLER IS THE APARTMENT COMPLEX OWNER AND RECIEVED A CALL FROM HER SUPERINTENDANT THATH THE OIL DELIVERY DRIVER SPILLED AN UNKNOWN AMOUNT OF OIL INTO A FLOWER GARDEN IN THE FRONT OF THE BLDG - WHEN THE CALLER CONTACTED THE OIL COMPANY THEY DID NOT GET BACK TO HER - CALLER WOULD LIKE A CALL BACK FOR MORE INFORMATION"

All Materials:

Site ID:	111829
Operable Unit ID:	1039727

APARTMENT BUILDING (Continued) **S102662670**

Operable Unit:	01
Material ID:	344258
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CS1033 **271 11TH AVE/MANHATTAN** **NY LTANKS** **S102671246**
North **271 11TH AVE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.486 mi.
2567 ft. **Site 2 of 2 in cluster CS**

Relative: **Lower**

Actual: **9 ft.**

LTANKS:

Name:	271 11TH AVE/MANHATTAN
Address:	271 11TH AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8710036 / 1988-12-29
Facility ID:	8710036
Site ID:	255435
Spill Date:	1988-02-29
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Not reported
Cleanup Ceased:	1988-12-29
SWIS:	3101
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1988-02-29
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-03-02
Spill Record Last Update:	1989-01-19
Spiller Name:	Not reported
Spiller Company:	WATERFRONT REALTY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	209227
DEC Memo:	""
Remarks:	"SPILL CONTAINED IN TANK VAULT ROOM OF BUILDING, OCCURRED DURING DELIVERY."

All Materials:

271 11TH AVE/MANHATTAN (Continued) **S102671246**

Site ID:	255435
Operable Unit ID:	914958
Operable Unit:	01
Material ID:	461823
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1000.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CV1034 **117 W 13TH ST/MANHATTAN** **NY LTANKS** **S104275588**
SE **117 WEST 13TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.489 mi.
2583 ft. **Site 1 of 2 in cluster CV**

Relative: **Higher**
Actual: **28 ft.**

LTANKS:

Name:	117 W 13TH ST/MANHATTAN
Address:	117 WEST 13TH STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9004345 / 1995-05-25
Facility ID:	9004345
Site ID:	73731
Spill Date:	1990-07-19
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1995-05-25
SWIS:	3101
Investigator:	WILSON
Referred To:	Not reported
Reported to Dept:	1990-07-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-07-25
Spill Record Last Update:	1995-05-25
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	69367
DEC Memo:	""
Remarks:	"FUEL CAME OUT OF VENT, WILL USE SPEEDY DRY & CLEAN UP, WILL PICK UP & DISPOSE OF."

117 W 13TH ST/MANHATTAN (Continued) **S104275588**

All Materials:

Site ID:	73731
Operable Unit ID:	944697
Operable Unit:	01
Material ID:	435447
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CW1035 **522-532 WEST 29TH STREET** **NY VCP** **S125317135**
North **522 WEST 29TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.490 mi.
2585 ft. **Site 1 of 4 in cluster CW**

Relative:
Higher
Actual:
14 ft.

VCP NYC:

Project ID:	13TMP0427M,13EHAN427M,13CVCP151M
Name:	522-532 WEST 29TH STREET
Address:	522 WEST 29TH STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Manhattan
BBL:	1.0070000491007E+29
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed
Latitude:	40.751955
Longitude:	-74.00266
Postcode:	4
Community Board:	3
Council District:	99
Census Tract:	1090204
BIN:	1007007501
NTA:	Hudson Yards-Chelsea-Flatiron-Union Square

CW1036 **HIGH RIDGE ENTERPRISES** **NY LTANKS** **S104275619**
North **524 WEST 29TH STREET** **NY Spills** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.493 mi.
2605 ft. **Site 2 of 4 in cluster CW**

Relative:
Higher
Actual:
14 ft.

LTANKS:

Name:	CLOSED-LACKOF RECENT INFO
Address:	524 WEST 29TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	9008960 / 2003-03-04
Facility ID:	9008960
Site ID:	235183
Spill Date:	1990-11-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	A3

HIGH RIDGE ENTERPRISES (Continued) **S104275619**

Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	1990-11-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1990-11-19
Spill Record Last Update:	2005-07-21
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	148161
DEC Memo:	""
Remarks:	"4K TANK FAILED HORNER EZY CHECK WITH A LEAK RATE RATE OF -.16GPH,WILL EXCAVATE & ISOLATE, POSSIBLE LINE FAILURE. CLOSED DUE TO LACK OF ANY RECENT INFO - DOES NOT MEET ANY CLEANUP REQUIREMENTS. "

All TTF:

Facility ID:	9008960
Spill Number:	9008960
Spill Tank Test:	1537886
Site ID:	235183
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	235183
Operable Unit ID:	946159
Operable Unit:	01
Material ID:	554502
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum

HIGH RIDGE ENTERPRISES (Continued) **S104275619**

Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	HIGH RIDGE ENTERPRISES
Address:	524 WEST 29TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0307633 / 2012-03-12
Facility ID:	0307633
Facility Type:	ER
DER Facility ID:	148161
Site ID:	176283
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	3101
Spill Date:	2003-10-20
Investigator:	aaobliga
Referred To:	NFA
Reported to Dept:	2003-10-20
CID:	365
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	2004-02-10
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-20
Spill Record Last Update:	2012-03-12
Spiller Name:	WALTER SEELIG
Spiller Company:	HIGH RIDGE ENTERPRISES
Spiller Address:	P.O. BOX 2542
Spiller Company:	001
Contact Name:	WALTER SEELIG
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 10/20/03. Contaminated soil letter sent to Walter Seelig (High Ridge Enterpr.). Also see spill # 9008960. YK. 11/21/03 Rommel Met Brian McCabe, senior geologist, on site. Soil samples collected from 8 to 16 feet below grade were contaminated. Groundwater (15 to 18 feet) was also sampled during the investigation and were impacted by BTEX and MTBE. They will excavate what soil they can and install a minimum of three monitoring wells (one outside by remote fills). Spill 9008960 reported TTF of 4000 gallon gas UST 11/14/1990 STIPULATION SIGNED RD 2/18/04. 3/18/04-Vought-Spoke with Rob Ferguson (631-586-4900). Subsurface Investigation report sent to DEC on 2/3/2004. Ferguson will send small CAP upon receiving subsurface investigation report review. Ferguson requires review of subsurface investigation as per STIP. Vought requested that another copy of the Subsurface investigation be sent to DEC. 4/1/04-Vought-Spoke with Tom Melia (F&N) and he requested that he be point of contact. Spill transferred from Rommel to Vought. 4/6/04-Vought-File review by

HIGH RIDGE ENTERPRISES (Continued) **S104275619**

Vought: Contaminated soil letter sent form DEC Krimgold to High Ridge Enterprises. Site meeting minutes (Fenley & Nicol Brian McCabe)-11/25/03. Site meetin on 11/24/03. In attendance were DEC Rommel, F&N McCabe, F&N Melia and F&N Hole. The results of the sampling indicated that the contamination is located in the northern portion of the building. The effected area extended from the north end od the 4000 gallon tank excavation to the front of the building, approximately thirty five feet and from the center for the 550-gallon tank excavation west to the side of the building, approximately twenty feet. DEC recommended additional soil excavation without comprimising structural intergrity and required 1)installation of one well inside the building after backfilling completed 2)installation of two wells on sidewalk at the location of the former remote fills and twenty feet west of the bay door. Letter from Fenley & Nicol(Thomas Melia) to DEC(Rommel)-12/18/03. The new owner of the building indicated that his intended use for the building is as an art gallery . During building remodeling excavation was performed and tanks were discovered under floor. Two gasoline USTs (one 4000-gallon and one 550-gallon) were removed and were in separate lcoations fifteen to twenty feet apart. Upon removal of the bottom slab the soil encountered was saturated with liquid phase hydrocarbon . Depth to water expected to be 18' below grade. F&N proposes delineation of soil and groundwater contamination, installation of wells and additional soil excavation. See also Spill #9008960 reported in 1990 for tank test failure and administratively closed on 3/4/03. Letter from DEC Rommel-12/4/03. Letter approving installation of wells on the sidewalk on the south side of West 29th Street between 10th and 11th Avenues and requesting expediting of sidewalk permits. Letter from F&N(Melia) to DEC Rommel-12/18/03. At this time we are continuing our efforts to delineate the extent of the contamination... . Three monitoring wells installed (one inside and two outside building). At this time the owener of ther property feels that it would be too far costly to excavate the contaminated soil without jeopardizing the structural integrity of the building, and would prefer that we install an air sparge/soil vapor extraction (As/SVE) system to remediate the hydrocarbon impact . Please indicate your approval below. No approval indicated by DEC Rommel. Stipulation Agreement-1/15/04. Stip with deadline of 2/13/04 sent to: Walter Seeling High Ridge Enterprises, Inc. P.O. Box 2542 York, Pa. 17405. Subsurface Investigation Report (F&N-Melia 631-586-4900x190) -3/19/04. Investigation consisted of six soil borings, six temporary groundwater monitoring points and three monitoring wells. The central and eastern units are currently vacant and undergoing renovations for use as an art gallery . Depth to groundwater is 8-9' and flows northwest. Soil analyticals show 35ppb benzene(SP-1 at 12'), 882ppb benzene(SP-2 at 12'), 14ppb (SP-3 at 12'), 4900ppb benzene(SP-4 at 12'), 817ppb benzene(SP-5 at 12'). Groundwater analyticals show 2.5 ppb benzene(TW-1), 1459ppb benzene(TW-2), 45ppb benzene(YW-3), 2109ppb benzene(TW-4), 254ppb benzene(TW-5), 11ppb benzene(TW-6), 1200ppb benzene(FN-1), 206ppb benzene(FN-2), 4.2ppb benzene(FN-3). Report recommends Air Spage/Soil Vapor extraction system. NYSDEC requires: 1)signing of Stipulation before any further correspondence l 2)presence or absence of free product and interim remedial recovery if present 3)surrounding area site plan including property usage 4)additional wells east of FN-2 and well north of FN-2 to calculate required radius of influence for system design. 4/6/04-Vought called F&N(Milea) to repeat Stipulation requirement and left message to

HIGH RIDGE ENTERPRISES (Continued) **S104275619**

return call to DEC. 4/7/04-Vought-Received faxed copy of STIP already implemented by DEC Kunkel on 2/18/04 (Copy of original not in file). 4/8/04-Vought-Sent letter to High Ridge requiring well installation north of FN2 and east of FN2, submission of monitoring well data and surrounding property sketch. 4/16/04-Vought-Wells will be installed next week (tentatively). Wells for pilot test will also installed. Mailing address is: High Ridge Enterprises P.O. Box 2542 York, Pa. 17405 4/18/04-Vought-Received message from David Oloke (F&N-631-586-4900x144) that he is new project manager for site. Vought called David and two additional well installed (one north of FN2 and one east of FN2). All onsite wells were sampled. No free product in new wells. Four vapor wells installed and air sparge well will be installed. DEC will receive pilot test report by 7/15/04. 6/23/04-Vought-Spoke with David and initial results faxed on 6/9/04. .5 of free product in well in 1 vapor well sent for fingerprinting. EFR not effective. DEC requires recovery of free product and submission of pilot test. 9/2/04-Vought-File review by Vought: Groundwater results (F&N)-6/23/04. Groundwater analyticals show 1.2ppb benzene(FN5), 1.8ppb benzene(FN4), 14ppb benzene(FN3), 26ppb xylene(FN3), 474ppb benzene(FN2), 621ppb MTBE(FN2), 8ppb toluene(FN2), 2065ppb benzene(FN1), 47170ppb MTBE(FN1), 4106ppb toluene(FN1) and 2761ppb xylene(FN1). Addendum to the direction beneath the site was found to be toward the north. Property uSubsurface Investigation Report (F&N)-7/14/04. On 5/7/04 two additional monitoring wells were installed. On June 4, 2004 the AS/SVE pilot tests were conducted . One inch of floating product was detected in P2. The results of the AS pilot test indicated that the introduction of air pressure into the formation below the contaminant zone is a viable remediation technique . Report recommends commencement of an interim remedial measure to recover product from P-2 via weekly EFR. Report also recommends installation of another well to replace P2. Vought called David from F&N to approve of workplan. Well installation will be included with final remedial action plan. Vought sent letter approving of proposed workplan (installation of well at P2 and IRM) and included requirement of determination of groundwater flow direction and surrounding property sketch. 9/3/04-Vought-Received fax from Oloke (F&N). The groundwater flow sage of downgradient sites to the north are a parking garage and an art studio. Vought called Oloke and approved workplan as per 9/2/04 letter. Vought called Oloke and he will begin drafting RAP for submission to DEC. 9/29/04-Vought-Spoke to David F&N and he will be sending RAP in overnight. 10/1/04-Vought-Reviewed RAP received by DEC on 10/30/04. Site is currently occupied by a masonary block structure which is subdivided into three sections. An art gallery occupies the western unit. The central and eastern units are currently vacant and are undergoing renovations for use as an art gallery. RAP proposes weekly recovery of free product from FN2 via a peristaltic pump until well is converted to a 2 product recovery well designated at FN6. Two additional wells will be installed in the interior of the building. Monthly groundwater monitoring and quarterly sampling. Five air sparge and four SVE wells will be installed in the interior of the building. Remedial system will be installed on the roof of the building. Daily monitoring for the first week, weekly monitoring for the first month, monthly maintenance visits and effluent sampling, quarterly effluent sampling and groundwater sampling. Vought sent letter approving of RAP. 10/28/04-Vought-Spoke to David(F&N) and FN1 must be reinstalled due to it was a bent well. Wells will be

HIGH RIDGE ENTERPRISES (Continued) **S104275619**

installed during the next few days. 9/27/05 - SPILL TRANSFERRED FROM VOUGHT TO OBLIGADO 11/9/05 - Obligado - Review System STartup Report. AS/SVE system consists of 5 HP compressor and 3.5 hp blower and 5 air sparge wells and four soil vapor extraction wells. Effluent air stack results show 31.4 ug/m3 for benzene. Operation and maintenance schedule proposes monthly SVE effluentmonitoring and Quarterly Status Reports. System started in May 2005. Due to noise generation, the system only runs from 9pm to 6am. Quarterly Status Report - Groundwater analyticals show 4.7 ppb benzene (FN3), 50.1 ppb MTBE (FN2), 78.3 ppb MTBE SVE5, 1.7 ppb MTBE SVE3. Benzene effluent show 46.74 ug/m3. 5/15/06 - Obligado - Called David Oloke. Asked that he send recent Quarterly Status Reports. 5/22/06 - Obligado - 2Q06 Quarterly Status Report, submitted by Fenley Nicol, Inc. Ground water analyticals show 9 ppb benzene 35 ppb MTBE in FN3 and and 3.7 ppb benzene in FN4. Benzene effluent below STIP limits. There is duplicated data on Table 2 Air Sampling Results, probably a cut and paste error, call Dave Oloke, he said he will look into it at send a new table with the electronic copy. Report recommends continuing system operation. 6/23/06 - Obligado - Called David Oloke. Asked for the corrected Table. He said he will email it to me. 10/23/06 - Obligado - Called David Oloke. Left message requesting most recent quarterly status report. David Oloke call me back and said he would send the report shortly and he would correct the typo on Table 2. 1/30/07 - Obligado - Review 3Q06 monitoring report. Typo in 2Q06 table has been fixed in cumulative table. AS/SVE system online and working at 100% maximum capacity. Air samples collected monthly. Benzene in gw exceeds standard at 4 ppb. in 2 wells. All effluent below STIP guidance. Benzene detected in VES/AS effluent at 4.86 ug/m3 in 6/06. Recommends continued operation of the system. Review 4Q06 monitoring report - AS/SVE system operating at 100% capacity 9 hours per day. All effluent samples below STIP guidance. BTEX effluent at 361.71 ug/m3 during 10/27/06 Report recommends continued operation of system. GW results show minor exceedences of Benzene - max concentration at 8 ppb in FN3. However gw monitoring does not include FN1 where highest contamination was found. 9/13/07 - Obligado - Review 1Q07 monitoring report. According to the report, the AS/SVE syste is running at 100% capacity. System is still pulling vapors, at a flow rate of 50 cfm and a concentration in March 07 of 111.30 ug/m3 BTEX. Benzene (12.8 ug/m3) was below the STIP limit. Recommends continued operation of AS/SVE system. 10/26/07 - Obligado - Review 2Q07/3Q07 monitoring report. Benzene detected during quarterly monitoring at MW3 adn MW4 slightly above standards. Analytical results of air stream were below the max benzene STIP Limit. Recommneds continued operation of the AS/SVE System. 9/3/08 - Obligado - Review 1Q08 monitoring report. AS/SVE running for 9 hours a day at 100% capacity. Effluent collected monthly. Benzene detected slightly above standards in MW2,3,4,and5. System effluent ND for BTEX. 6/3/09 - Obligado - REview 1Q09 monitoring report. Requests to shut down system for a 1 year post remedial monitoring period to determine if system was effective and monitor for rebound. Sent a letter to Seeling cc to David Oloke approving system shut down temporarily but requiring sampling of monitoring wells MW1, MW6, adn MW7 beneath the building as required by approved RAWP. Required 90 days to submit an update report on system shutdown and additional sampling. 12/3/09 - Obligad - Met with David Oloke on site. The AS/SVE system was down as proposed. According to David they were unable to collect ground water samples from the three sampling

HIGH RIDGE ENTERPRISES (Continued) **S104275619**

points. According to David the water he collected was too silty. He recommended doing an exposure assessment to close the spill number or to install the well in an alternate location in the building entrance. I told him I would review the spill file to determine if that location was acceptable. 12/22/09 - Sent email to Mr. Oloke - The Department has determined that the proposed location is cross-gradient and outside the of the source area, and would not provide the necessary data to confirm the site remedation was successful. As such, the Department reiterates its requirement in the June 2, 2009 letter, to sample the 3 monitoring wells FN1, FN6, and FN7 (as originally proposed in the approved RAWP) and submit a Monitoring Report within 90 days of this notice. If sufficient ground water can not be obtained from these sampling points (after exhausting all available well sampling and well development techniques), than a Remedial Investigation Work Plan (RIWP) to install a new monitoring well in the gallery in between FN1, FN6, and FN7 must be submitted within 90 days of this notice. The RIWP should contain an implementation schedule. 10/9/10 - Obligado - Email from David Oloke I would like to inform you that we're scheduled to be onsite to install one groundwater monitoring well on the sidewalk directionally towards the source area beneath the building in order to determine the current groundwater quality beneath the site. We scheduled for Monday 25 through Wednesday 27. 1/14/11 - Obligado - Email from David Oloke We are set to go back to High Ridge, 524 West 29th Street in Manhattan on Monday 1/17/11 to install the groundwater monitoring well for spill inactivation. The client is making plans to be onsite as well . 1/19/11 - Obligado Email from David Oloke We core drilled through the foundation wall and could not get the well rods to the desired depth due to refusal. So we back to square one. Our client spoke with the tenant again yesterday to see if he will allow us access into the building. 4/1/11 - Obligado - I sent email to David Oloke related to potential alternative methods for obtaining ground water samples at the site since the diagonal well method was not successful, such as snaking new tubing into the existing system wells, and high vaccuum extraction to obtain ground water samples from the sparge wells. I asked Mr. Oloke to look into these options, as well as any other methods and report back the findings to the DEC. 3/12/12 - Obligado - I reviewed a Site Status Report. They collected samples from MW1, MW6, and MW7 under the gallery slab using the vacuum extraction technicque. Samples were collected in June and November of 2011. During the most recent sampling event in NOvember, the maximum VOCs was 117.3 ug/L in MW-7. MW1 had 63.42 ug/L total VOCs, and MW6 had 59.75 ug/L VOCs. Several compounds were slightly above standards. The greatest exceedence was 36 ug/L napthalene in MW7, which is above the standard of 10 ug/L. In NOvember they turned on the AS/SVE system and allowed it to run for four weeks. At the end of the four weeks , air samples were collected and all the targeted VOCs were ND. Based on the above, they requested closure. Ground water contamination has been greatly reduced. The AS/SVE system reached asymptotic recovery rates. Additional remediation is not warranted nor feasible. After discussion with DEC Hussein and Ketani, this spill is closed. A spill closure letter ahs been sent to Walter Seeling, cc to David Oloke."

Remarks: "caller was hired to remove a few tanks from the site - x-ref spill # 9008960 - they encountered contaminated soil - they are stockpiling soil now"

HIGH RIDGE ENTERPRISES (Continued) **S104275619**

All Materials:

Site ID:	176283
Operable Unit ID:	874031
Operable Unit:	01
Material ID:	501158
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CV1037 **SPOONS** **NY LTANKS S106868734**
SE **110 WEST 14TH STREET** **NY Spills N/A**
1/4-1/2 **MANHATTAN, NY**
0.494 mi.
2610 ft. **Site 2 of 2 in cluster CV**

Relative: **Higher**

Actual: **29 ft.**

LTANKS:

Name:	SPOONS
Address:	110 WEST 14TH STREET
City,State,Zip:	MANHATTAN, NY
Spill Number/Closed Date:	0412387 / 2005-11-08
Facility ID:	0412387
Site ID:	337798
Spill Date:	2005-02-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2005-02-21
CID:	409
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-02-22
Spill Record Last Update:	2005-11-15
Spiller Name:	CHRIS GORGA
Spiller Company:	SPOONS
Spiller Address:	110 WEST 14TH STREET
Spiller County:	001
Spiller Contact:	CHRIS GORGA
Spiller Phone:	(646) 772-1404
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	273142
DEC Memo:	"ttf letter needed 3/10 ttf letter sent//mt 8/25/05 - Raphael Ketani.

SPOONS (Continued) **S106868734**

Case transferred from Tipple to Ketani. 9/1/05 - Raphael Ketani. I received a FAX from J.M. Mechanical ((718) 991-2300) on 8/30/05 with a 3/10/05 letter that was sent by Michelle Tipple concerning the tank tightness testing that was to be performed. J.M. Mechanical wanted to know what was supposed to be the next step in the tank evaluation procedure. I spoke to Joseph Zengotita of J.M. and he told me that they tested the tank and it could not hold the pressure. They found that the manhole gasket was rotten and replaced it. Then they redid the test and found that the pressure was holding. I next spoke to Jamie Perna ((212) 977-0000, ext. 236) of Mann Realty Associates regarding the building and the tank. She told me (from her file) that the PBS number is 2-605982, the tank is above ground, but in contact with the ground, and that it holds 1,500 gals of #2 oil. The expiration date of the PBS permit is 5/17/09. She told me that the property manager is Debbie Perna (ext. 238 - her mother). Ms. Perna's cell is (347) 723-8402. I spoke to Debbie Perna and told her to send me a copy of the successful tightness test results report from J.M. Mechanical, a statement that the source of the pressure leak was the rotten manhole gasket and that it has been replaced, and that there was no release of product from the tank or system and no environmental impact. She said she would do this. 9/15/05 - Raphael Ketani. Martina Mauleon, secretary for J.M. Mechanical, called asking what information did DEC want regarding the tank testing. I told her that if the second tightness test was successful, then she should include wording that J.M. Mechanical believes the rotten manhole gasket was the problem and it has been replaced, that the second test passed (include the actual test report), that there wasn't an oil leak, and that there was no environmental damage. She said she would send the letter to Ms. Perna. I told her that would be fine. 10/17/05 - Raphael Ketani. I spoke to Debbie Perna by cell phone. She said she had called J.M. Mechanical and they told her she should get the tank test report this week. Ms. Perna said she will FAX it to me ASAP. 11/8/05 - Raphael Ketani. I finally received the successful tank test from J.M. Mechanical. Everything looks good. So I am closing the case."

Remarks: ""

All TTF:

Facility ID:	0412387
Spill Number:	0412387
Spill Tank Test:	1548609
Site ID:	337798
Tank Number:	1
Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

SPOONS (Continued) **S106868734**

Site ID: 337798
Operable Unit ID: 1099810
Operable Unit: 01
Material ID: 580058
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: Not reported
Oxygenate: Not reported

SPILLS:
Name: STORE
Address: 110 WEST 14TH STREET
City,State,Zip: MANHATTAN, NY
Spill Number/Closed Date: 0404381 / 2004-07-23
Facility ID: 0404381
Facility Type: ER
DER Facility ID: 273142
Site ID: 154049
DEC Region: 2
Spill Cause: Unknown
Spill Class: C5
SWIS: 3101
Spill Date: 2004-07-21
Investigator: MXTIPPLE
Referred To: Not reported
Reported to Dept: 2004-07-23
CID: 405
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Citizen
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-07-23
Spill Record Last Update: 2004-07-23
Spiller Name: CORINTHIAN GUY
Spiller Company: STORE
Spiller Address: 110 WEST 14TH ST.
Spiller Company: 001
Contact Name: CORINTHIAN GUY
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 7/23/04 not controlled or petroleum related//referred to 311 and doh..nfa"
Remarks: "LIVES UPSTAIRS AND DOWNSTAIRS STORE IS RELEASING FUMES TO HIS APARTMENTM THERE ARE ROACHES COMING FROM DOWNSTAIRS, THEY ARE REPAIRING THE STORE DOWNSTAIRS"

All Materials:
Site ID: 154049

SPOONS (Continued) **S106868734**

Operable Unit ID:	887559
Operable Unit:	01
Material ID:	488383
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

1038 ENE 1/4-1/2 0.495 mi. 2612 ft. **241 WEST 28TH STREET** **NY BROWNFIELDS** **S125465251**
241 WEST 28TH STREET **N/A**
NEW YORK, NY 10001

Relative: Higher

Actual: 28 ft.

BROWNFIELDS:

Name:	241 WEST 28TH STREET
Address:	241 WEST 28TH STREET
City,State,Zip:	NEW YORK, NY 10001
Program:	BCP
Site Code:	592785
Acres:	0.670
HW Code:	C231139
SWIS:	3101
Town:	New York City
Record Added Date:	08/06/2019
Record Updated Date:	12/28/2021
Update By:	MDMACCAB
Site Description:	"Location The 29,315 square foot (0.67 acre) site is within the Chelsea neighborhood of Manhattan, bearing the addresses 241 251 West 28th Street and 240 250 West 29th Street. The site is bound by West 29th Street to the north, a 13 story commercial office building and a 12 story commercial office building to the east, West 28th Street to the south, and a five story industrial manufacturing building and a seven story public institutional building to the west. Current Zoning and Land Use The current zoning designation is M1 6D, which permits residential, commercial, and industrial uses. The current surrounding parcel uses are a combination of residential, commercial, industrial, and institutional. The site is presently (December 2021) undergoing construction of two residential towers.. Past Use of the Site The site had been occupied by commercial and industrial facilities as early as 1890. Past site uses included a lumber yard (circa 1890), a fur processing and cleaning company (1927 1934), an auto repair facility (circa 1934), garages with petroleum bulk storage (1930 to 2011) and parking facilities with hydraulic lifts and suspected hydraulic USTs (1920 2014). During its operation as a parking lot and garage, the site was assigned a NYC restrictive E zoning designation in April 2011 for hazardous materials (E 137), air quality, and noise (E 276). Site Geology and Hydrogeology Subsurface stratigraphy at the site consists of historic fill underlain by native soil consisting of silt, sand, gravel, and boulders overlying bedrock. The fill extends to varying depths ranging from about 3 to 20 feet below grade and generally consists of loose, black to gray to brown, fine to coarse sand, with varying amounts of gravel, silt, rock fragments, brick,

241 WEST 28TH STREET (Continued) **S125465251**

	tile, concrete and ash. Mica schist bedrock was encountered at depths ranging from about 21 feet below grade in the southern portion of the site to 63 feet below grade near the northeast corner. Groundwater depth ranges from about 15.8 to 17.4 feet below grade. Regional groundwater is inferred to flow 0.75 miles west toward the Hudson River, following the influence of local topography."
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in soil were primarily associated with historic fill present across the site that included metals and semi volatile organic compound (SVOCs). Ten underground storage tanks (USTs) were located and properly exhumed and properly disposed of off-site. Contaminants associated with historic fill were present across the site. Volatile organic compounds (VOCs) were present in groundwater above water quality standards. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are nearly complete at the site and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2019-11-12 13:59:00
Record Upd:	2021-09-07 15:47:00
Updated By:	MDMACCAB
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	n/a
Owner Company:	New York Public Library - Muhlenberg Branch
Owner Address:	209 West 23rd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10011
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Vikki Barbero
Owner Company:	Manhattan Community Board 5
Owner Address:	450 Seventh Avenue, Suite 2109
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10123
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Susi Yu
Owner Company:	241 West 28th Street Owner LLC
Owner Address:	c/o MAG Partners
Owner Addr2:	41 Flatbush Avenue, 1st and 2nd Floors
Owner City,St,Zip:	Brooklyn, NY 11217
Owner Country:	United States of America
Own Op:	6

241 WEST 28TH STREET (Continued) **S125465251**

Sub Type:	E
Owner Name:	Jon Dario
Owner Company:	249 W 28th Street Properties, LP
Owner Address:	c/o Edison Properties, LLC
Owner Addr2:	110 Edison Place, Suite 300
Owner City,St,Zip:	Newark, NJ 07102
Owner Country:	United States of America
HW Code:	C231139
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231139
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231139
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231139
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231139
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231139
Waste Type:	methylene chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231139
Waste Type:	cresol(s)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231139
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231139
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231139
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231139
Waste Type:	cadmium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231139
Waste Type:	perfluorooctanoic acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231139
Waste Type:	Perfluorooctane Sulfonic Acid

241 WEST 28TH STREET (Continued) **S125465251**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231139
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231139
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C231139
Waste Type:	phenol
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2009358
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2021-03-01 10:13:00
Record Updated:	2021-03-01 10:13:00
Updated By:	MDMACCAB
Crossref ID:	9901067
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2019-09-06 16:01:00
Record Updated:	2019-09-06 16:01:00
Updated By:	MDMACCAB
Crossref ID:	2100042
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2021-05-28 09:54:00
Record Updated:	2021-05-28 09:54:00
Updated By:	JHOCONNE
Crossref ID:	2-600623
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2021-10-29 14:07:00
Record Updated:	2021-10-29 14:07:00
Updated By:	MDMACCAB
Crossref ID:	C231139-11-19
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2021-09-07 15:37:00
Record Updated:	2021-09-07 15:37:00
Updated By:	MDMACCAB
Crossref ID:	2021000488505
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2021-12-14 11:36:00
Record Updated:	2021-12-14 11:36:00
Updated By:	MDMACCAB

CW1039 **534 WEST 29TH STREET** **NY VCP** **S118943338**
North **534 WEST 29TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.496 mi.
2617 ft. **Site 3 of 4 in cluster CW**

Relative: **Lower**
Actual: **13 ft.**

VCP NYC:

Project ID:	14TMP0228M,14EHAN228M,14CVCP199M
Name:	534 WEST 29TH STREET
Address:	534 WEST 29TH STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Manhattan
BBL:	1007000053
OER Program:	VCP (Enrolled)
Phase:	Construction
Latitude:	40.75204
Longitude:	-74.002862
Postcode:	4
Community Board:	3
Council District:	99
Census Tract:	1090447
BIN:	1007000053
NTA:	Hudson Yards-Chelsea-Flatiron-Union Square

1040 **HELIPORT W 30TH ST/MANH - TTF** **NY LTANKS** **S100145501**
NNE **HELIPORT/W.30TH ST & 12TH** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.498 mi.
2631 ft.

Relative: **Higher**
Actual: **24 ft.**

LTANKS:

Name:	HELIPORT W 30TH ST/MANH - TTF
Address:	HELIPORT/W.30TH ST & 12TH
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8903684 / 2014-10-27
Facility ID:	8903684
Site ID:	116887
Spill Date:	1989-07-13
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	1989-07-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1989-07-14
Spill Record Last Update:	2014-10-27
Spiller Name:	Not reported
Spiller Company:	PORT AUTHORITY
Spiller Address:	Not reported
Spiller County:	999

HELIPORT W 30TH ST/MANH - TTF (Continued) **S100145501**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	101690
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MILLER DEC SIGONA REASSIGNED TO MILLER ON 1/23/98 3/5/10 - Austin - Reassigned as TTF to Jake Krimgold for further investigation. - end 08/13/12 - LZ As Randy Austin requested, the spill has been reassigned to Tim DeMeo 8/24/12 TJD Spill cross-referenced to PBS#. 10/09/14-Hiralkumar Patel. reviewed available documents for DEC DeMeo. site name: West 30th Street Heliport PBS #: 2-342211. as per PBS record, the site has/had following tanks: - one (1) 8,000 gal other product AST on saddles, in-service, installed in Apr. 1997 - one (1) 8,000 gal other product AST on soil, converted to non-regulated use, installed in Apr. 1997 (this could be same tank as above) 10/27/14 TJD File review - based upon above information obtained from Patel. - eleven (11) 550 gal other product USTs, closed-in-place, in Apr. 1997 - five (5) 550 gal other product USTs, closed prior to Mar. 1991 other spills #: 8804707, 8901091, 9504121 spill # 8804707 was reported on 08/29/1988 by USCG due to petroleum patch. case closed. spill # 8901091 was reported on 05/04/1989 due to tank test failure for eight (8) 550 gal jet fuel tanks. case closed. spill # 9504121 was reported on 07/06/1995 by USCG due to 40 gal jet fuel spill result of collision between two helicopters. case closed. reviewed documents on e-docs for PBS: - 12/18/1988: tanks 9 to 16 (550 gal jet A fuel) were passed - 12/07/1991: tanks 1 to 8 (550 gal jet A fuel) were passed - 06/11/2007: N. D. Eryou sent letter to DEC Falvey. he mentioned that the eleven (11) 550 gal USTs owned by Port Authority and they were conveyed with the land lease to NYS DOT (Aviation Division). he was not present during tanks abandonment in 1997, but believed that NYSDOT was going to remove the USTs as part of the stormwater upgrades that were underway as part of the immeidate adjacent Route 9 upgrades. 10/27/14 TJD File review. Based upon summarized review discussed above - (8) 550 gallon UST's passed tightness tests (Tanks 9 to 16) prior to reported spill (1988). Remaining (8) 550 gallon UST's (Tanks 1 to 8) passed a tighness test subsequent to reported spill (1991). As per PBS inspection 1/9/07 (Falvey) all UST's have been permanently closed on site. New 8K AST's are currently in operation at this facility. A total of (3) spill reports have been reported and closed at this facility since initial TTF report. Unknown what tank # failed the tighness test, however, all UST's are reported out of service. Due to proximity of the failure to the Hudson River if a significant petroleum discharge had occurred impacts to the adjacent surface waters would have been observed. No further action is required at this time. Spill is administratively closed."
Remarks:	"550 GALLON TANK FAILED HORNER EZY CHECK WITH A LEAK RATE OF .179GPH, TANK #8, PARTIALLY PUMPED OUT TANK, WILL FINISH PUMPING TANK LATER TODAY."

All TTF:

Facility ID:	8903684
Spill Number:	8903684
Spill Tank Test:	1535707
Site ID:	116887
Tank Number:	Not reported
Tank Size:	0

HELIPORT W 30TH ST/MANH - TTF (Continued) **S100145501**

Material:	0011
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	116887
Operable Unit ID:	931312
Operable Unit:	01
Material ID:	447763
Material Code:	0011
Material Name:	jet fuel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

CW1041 **542 WEST 29TH STREET** **NY BROWNFIELDS** **S125298846**
North **538-542 WEST 29TH STREET** **N/A**
1/4-1/2 **MANHATTAN, NY 10001**
0.499 mi.
2636 ft. **Site 4 of 4 in cluster CW**

Relative: **Lower**
Actual: **13 ft.**

BROWNFIELDS:

Name:	542 WEST 29TH STREET
Address:	538-542 WEST 29TH STREET
City,State,Zip:	MANHATTAN, NY 10001
Program:	BCP
Site Code:	588955
Acres:	0.227
HW Code:	C231136
SWIS:	3101
Town:	New York City
Record Added Date:	05/29/2019
Record Updated Date:	09/30/2021
Update By:	SMQUANDT
Site Description:	"Location The site is located at 538-542 West 29th Street in the Chelsea neighborhood of Manhattan, and is identified on the Manhattan Borough Tax Map as Block 700, Lots 55, 56, and 57. The proposed BCP site includes all three tax lots. The site is located on southern side of West 29th Street and is bound by West 29th Street to the north, mixed-use residential/commercial buildings followed by the elevated High Line and Tenth Avenue to the east, a multi-story residential apartment building followed by West 28th Street to the south, and a multi-story mixed-use residential and commercial building followed by Eleventh Avenue to the west. The No. 7 subway southern extension runs north-south below Eleventh Avenue, which is

542 WEST 29TH STREET (Continued) **S125298846**

about 200 feet to the west of the proposed BCP site. Site Features The site occupies a footprint of about 9,900-sqaure-feet (0.227 acres) and is currently improved with one three-story commercial building (Lot 55), one three-story mixed-use commercial and residential building (Lot 56), and one two-story warehouse (Lot 57). The buildings are currently vacant. Current Zoning and Land Use According to the New York City Planning Commission (NYCPC) Zoning Map 8b, dated January 22, 2015, the site is located in a C6-3 commercial district. C6-3 includes a wide range of high bulk commercial uses. Buildings in this district are often corporate headquarters, large hotels, department stores, and entertainment facilities in high-rise mixed buildings. The existing zoning is consistent with the proposed commercial-use development. The surrounding area is primarily commercial and residential, but also includes manufacturing buildings, subway tunnels, public parks, churches, schools and day care centers. One sensitive receptor, Bright Horizons Day Care at Hudson Yards, is located within the immediate area (less than mile) of the site, about 100 feet to the north at 529 West 29th Street. The nearest ecological receptor is the Hudson River, located about 1,300 feet west of the site. As a result of the City Environmental Quality Review (CEQR) process, Block 700, Lots 55, 56, and 57 were assigned an E-Designation (E-142) on June 23, 2005 by the New York City Department of City Planning (NYCDCP) as part of the High Line/West Chelsea Rezoning (CEQR No. 03DCP069M). The E-Designation requires coordination with the New York City Office of Environmental Remediation (OER) to obtain a Notice to Proceed (NTP) or a Notice of No Objection (NNO) prior to obtaining building permits. The E-Designation addresses environmental requirements for hazardous materials (Hazmat), noise (window wall attenuation and alternative means of ventilation), and air quality during development. Past Use of the Site The site and surrounding area have been developed since the early 1800 s. The site was developed prior to 1890 with two unspecified use buildings which were demolished between 1899 and 1922. Lot 57 was formerly used as a lumber storage yard (1909-1944) and various auto repair facilities over a span of about 50 years (1945-1994). In 1995, the Lot 57 was purchased by Gotham Seafood Corporation, a seafood wholesaler. Sanborn maps indicate that Lots 55 and 56 were improved with mixed use-residential and commercial developments from about 1890 to 2005. Certificates of Occupancy (CO) provided by the New York City Department of Buildings (NYCDOB) identified an auto repair shop within Lot 56 in 1924 and 2012. In addition, available CO s for Lot 55 dated 1970 and 1987 identified manufacturing and a heating plant with potential fuel storage. Currently, all of the lots are vacant. Adjoining properties were historically used for residential, commercial, industrial and manufacturing operations. Site Geology and Hydrogeology Historic fill material was encountered immediately beneath the building foundation slabs and extends to depths varying from about 7.5 to 10 feet below grade surface (bgs) at 540 West 29th Street (Lots 56), and from about 3 to 12 feet bgs at 542 West 29th Street (Lot 57). Historic fill material was encountered below the cellar slab at 538 West 29th Street (Lot 55) at depths ranging from 3 to 5 feet below cellar grade. The historic fill predominately consists of brown fine- to medium-grained sand with varying amounts of gravel, concrete, asphalt, charcoal, slag, ash, wood, brick, and glass. The layer of historic fill is typical for this area of New York City. The fill layer is underlain by native soils typically consisting of

542 WEST 29TH STREET (Continued) **S125298846**

	reddish-brown to olive, fine- to medium grained silty sand with varying amounts of gravel and silt. Petroleum impacts, evidenced by odors, staining, and/or photoionization detector (PID) readings above background levels, were apparent in two soil borings (SB03 and SB06) at depths ranging from about 0 to 10 feet bgs and 14 to 15 feet bgs, respectively. Groundwater was encountered at depths ranging from 3.2 feet below cellar grade at 538 West 29th Street (Lot 55), 9.2 to 11 feet bgs at 540 West 29th Street (Lot 56) and from 8 to 11.51 feet bgs at 542 West 29th Street (Lot 57). Based on the well gauging results, groundwater appears to flow west toward the Hudson River, which is relatively consistent with regional topography."
Env Problem:	"Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available."
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2019-09-26 10:17:00
Record Upd:	2021-09-07 16:23:00
Updated By:	MDMACCAB
Own Op:	1
Sub Type:	P03
Owner Name:	Michael Zampetti
Owner Company:	W29 Owner LLC
Owner Address:	148 Madison Avenue, 16th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10016
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Michael Zampetti
Owner Company:	W29 Owner LLC
Owner Address:	148 Madison Avenue, 16th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10016
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New York Public Library - Muhlenberg
Owner Address:	209 West 23rd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10011
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Manhattan Community Board 4

542 WEST 29TH STREET (Continued) **S125298846**

Owner Address:	330 West 42nd Street, 26th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 11106
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	1805506
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2019-07-19 15:54:00
Record Updated:	2019-07-19 15:54:00
Updated By:	MDMACCAB
Crossref ID:	1805508
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2019-07-19 15:54:00
Record Updated:	2019-07-19 15:54:00
Updated By:	MDMACCAB

1042 **MARKITE CO.** **FUSRAP** **1016603386**
SSE **155 WAVERLY PLACE** **N/A**
1/2-1 **NEW YORK, NY**
0.644 mi.
3401 ft.

Relative: **Higher**

Actual: **19 ft.**

FUSRAP:

Site Name:	MARKITE CO.
Site Id:	NY.49
Site Status:	Eliminated from consideration under FUSRAP
Designated Name:	Not Designated
Alternate Name:	None
Location Street Address:	155 WAVERLY PLACE
Location City:	NEW YORK
Location State:	NY
Location County:	Not reported
Evaluation Year:	1987
Site Oprerations:	Conducted experiments with very small amounts of uranium and thorium.
Site Disposition:	Eliminated - Handled limited amounts of radioactive materials - Potential for contamination remote
Radioactice Materials Handled:	Yes
Primary Radioactivce Materials Handled:	Uranium, Thorium
Radiological Survey(S):	None Indicated
Long Term Care Requirements:	Not reported
Historical Operations:	Not reported
Website URL:	http://www.lm.doe.gov/Considered_Sites/Markite_Co_-_NY_49

1043 East 1/2-1 0.645 mi. 3405 ft.

FORMER GUARDIAN CLEANERS
27-35 WEST 24TH STREET
NEW YORK, NY 10010

NY SHWS **S113916768**
NY ENG CONTROLS **N/A**
NY INST CONTROL

Relative: Higher

Actual: 38 ft.

SHWS:

Name:	FORMER GUARDIAN CLEANERS
Address:	27-35 WEST 24TH STREET
City,State,Zip:	NEW YORK, NY 10010
Program:	HW
Site Code:	440109
Classification:	C
Region:	2
Acres:	0.227
HW Code:	231073
Record Add:	09/22/2010
Record Upd:	05/29/2021
Updated By:	JHOCONNE

Site Description: "Location: The site is located at 27-35 West 24th Street in the Borough of New York, New York. It is located on the northern side of West 24th Street. The site is designated as Block 826, Lot 19. Site Features: The site is a rectangular shaped parcel of land measuring approximately 9,000 square feet and is improved with an one 11-story building with a basement. Current Zoning and Land Use: The building on site is used for office space and a restaurant/bar on the first floor and part of the basement. The site is zoned M1-6, which allows industrial and manufacturing. The current use of the site complies with the zoning code. Past Use of the Site: A dry cleaning facility formerly occupied the restaurant/bar space until approximately 1990. The former dry cleaning operations are believed to have contributed to the known contamination found in groundwater and soil vapor on the site. Site Geology and Hydrogeology: The subsurface lithology was homogenous throughout the site. The subsurface soil was noted to consist of urban fill material and brown coarse grain sand. Based upon boring logs from various site investigations, groundwater is encountered 8-10 feet beneath the basement slab except along the western property boundary where the water table is shallower, resulting in the need to actively pump out water entering the service elevator pit. "

Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were chlorinated volatile organic compounds (VOCs) such as tetrachloroethene (PCE), trichloroethene (TCE), and cis-1,2-dichloroethene (DCE) which were detected in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."

Health Problem: "Direct contact with contaminants in the soil or groundwater is unlikely because the site is entirely covered with a building. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system was installed

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

beneath the on-site building to prevent vapors beneath the slab from entering the building. Sampling at an adjacent structure indicates soil vapor intrusion is not a concern. Access to the other adjacent building was denied and soil vapor intrusion may be a potential exposure pathway at that structure. "

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-02-24 09:04:00
Record Upd:	2015-07-06 04:46:00
Updated By:	HRAHMED
Own Op:	1
Sub Type:	06
Owner Name:	Michael Orbach
Owner Company:	West 24-27 Realty LLC
Owner Address:	70 West 36th Street, Suite 10B
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10018
Owner Country:	United States of America
HW Code:	231073
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	231073
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	231073
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	R2-0777-09-11
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2015-02-10 11:32:00
Record Updated:	2015-02-10 11:32:00
Updated By:	HRAHMED
Crossref ID:	2015000002658
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2015-02-09 15:54:00
Record Updated:	2015-02-09 16:00:00
Updated By:	HRAHMED

ENG CONTROLS:

Name:	FORMER GUARDIAN CLEANERS
Address:	27-35 WEST 24TH STREET
City,State,Zip:	NEW YORK, NY 10010
Site Code:	440109
HW Code:	231073
Control Code:	12

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

Control Type:	ENG
Date Record Added:	06/26/2015
Date Rec Updated:	01/25/2018
Updated By:	JJTEETER
Site Description:	"Location: The site is located at 27-35 West 24th Street in the Borough of New York, New York. It is located on the northern side of West 24th Street. The site is designated as Block 826, Lot 19. Site Features: The site is a rectangular shaped parcel of land measuring approximately 9,000 square feet and is improved with an one 11-story building with a basement. Current Zoning and Land Use: The building on site is used for office space and a restaurant/bar on the first floor and part of the basement. The site is zoned M1-6, which allows industrial and manufacturing. The current use of the site complies with the zoning code. Past Use of the Site: A dry cleaning facility formerly occupied the restaurant/bar space until approximately 1990. The former dry cleaning operations are believed to have contributed to the known contamination found in groundwater and soil vapor on the site. Site Geology and Hydrogeology: The subsurface lithology was homogenous throughout the site. The subsurface soil was noted to consist of urban fill material and brown coarse grain sand. Based upon boring logs from various site investigations, groundwater is encountered 8-10 feet beneath the basement slab except along the western property boundary where the water table is shallower, resulting in the need to actively pump out water entering the service elevator pit. "
Env Problem:	"Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were chlorinated volatile organic compounds (VOCs) such as tetrachloroethene (PCE), trichloroethene (TCE), and cis-1,2-dichloroethene (DCE) which were detected in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem:	"Direct contact with contaminants in the soil or groundwater is unlikely because the site is entirely covered with a building. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system was installed beneath the on-site building to prevent vapors beneath the slab from entering the building. Sampling at an adjacent structure indicates soil vapor intrusion is not a concern. Access to the other adjacent building was denied and soil vapor intrusion may be a potential exposure pathway at that structure. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

Dell:	Not reported
Record Add:	2011-02-24 09:04:00
Record Upd:	2015-07-06 04:46:00
Updated By:	HRAHMED
Own Op:	1
Sub Type:	06
Owner Name:	Michael Orbach
Owner Company:	West 24-27 Realty LLC
Owner Address:	70 West 36th Street, Suite 10B
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10018
Owner Country:	United States of America
HW Code:	231073
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	231073
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	231073
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	R2-0777-09-11
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2015-02-10 11:32:00
Record Updated:	2015-02-10 11:32:00
Updated By:	HRAHMED
Crossref ID:	2015000002658
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2015-02-09 15:54:00
Record Updated:	2015-02-09 16:00:00
Updated By:	HRAHMED
Name:	FORMER GUARDIAN CLEANERS
Address:	27-35 WEST 24TH STREET
City,State,Zip:	NEW YORK, NY 10010
Site Code:	440109
HW Code:	231073
Control Code:	13
Control Type:	ENG
Date Record Added:	06/26/2015
Date Rec Updated:	01/25/2018
Updated By:	JJTEETER
Site Description:	"Location: The site is located at 27-35 West 24th Street in the Borough of New York, New York. It is located on the northern side of West 24th Street. The site is designated as Block 826, Lot 19. Site Features: The site is a rectangular shaped parcel of land measuring approximately 9,000 square feet and is improved with an one 11-story building with a basement. Current Zoning and Land Use: The building on site is used for office space and a restaurant/bar on the first floor and part of the basement. The site is zoned M1-6, which allows industrial and manufacturing. The current use of the site complies with the zoning code. Past Use of the Site: A dry cleaning facility

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

formerly occupied the restaurant/bar space until approximately 1990. The former dry cleaning operations are believed to have contributed to the known contamination found in groundwater and soil vapor on the site. Site Geology and Hydrogeology: The subsurface lithology was homogenous throughout the site. The subsurface soil was noted to consist of urban fill material and brown coarse grain sand. Based upon boring logs from various site investigations, groundwater is encountered 8-10 feet beneath the basement slab except along the western property boundary where the water table is shallower, resulting in the need to actively pump out water entering the service elevator pit. "

Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were chlorinated volatile organic compounds (VOCs) such as tetrachloroethene (PCE), trichloroethene (TCE), and cis-1,2-dichloroethene (DCE) which were detected in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."

Health Problem: "Direct contact with contaminants in the soil or groundwater is unlikely because the site is entirely covered with a building. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system was installed beneath the on-site building to prevent vapors beneath the slab from entering the building. Sampling at an adjacent structure indicates soil vapor intrusion is not a concern. Access to the other adjacent building was denied and soil vapor intrusion may be a potential exposure pathway at that structure. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2011-02-24 09:04:00
Record Upd: 2015-07-06 04:46:00
Updated By: HRAHMED
Own Op: 1
Sub Type: 06
Owner Name: Michael Orbach
Owner Company: West 24-27 Realty LLC
Owner Address: 70 West 36th Street, Suite 10B
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
HW Code: 231073
Waste Type: tetrachloroethene (PCE)

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	231073
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	231073
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	R2-0777-09-11
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2015-02-10 11:32:00
Record Updated:	2015-02-10 11:32:00
Updated By:	HRAHMED
Crossref ID:	2015000002658
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2015-02-09 15:54:00
Record Updated:	2015-02-09 16:00:00
Updated By:	HRAHMED
Name:	FORMER GUARDIAN CLEANERS
Address:	27-35 WEST 24TH STREET
City,State,Zip:	NEW YORK, NY 10010
Site Code:	440109
HW Code:	231073
Control Code:	15
Control Type:	ENG
Date Record Added:	06/26/2015
Date Rec Updated:	01/25/2018
Updated By:	JJTEETER
Site Description:	"Location: The site is located at 27-35 West 24th Street in the Borough of New York, New York. It is located on the northern side of West 24th Street. The site is designated as Block 826, Lot 19. Site Features: The site is a rectangular shaped parcel of land measuring approximately 9,000 square feet and is improved with an one 11-story building with a basement. Current Zoning and Land Use: The building on site is used for office space and a restaurant/bar on the first floor and part of the basement. The site is zoned M1-6, which allows industrial and manufacturing. The current use of the site complies with the zoning code. Past Use of the Site: A dry cleaning facility formerly occupied the restaurant/bar space until approximately 1990. The former dry cleaning operations are believed to have contributed to the known contamination found in groundwater and soil vapor on the site. Site Geology and Hydrogeology: The subsurface lithology was homogenous throughout the site. The subsurface soil was noted to consist of urban fill material and brown coarse grain sand. Based upon boring logs from various site investigations, groundwater is encountered 8-10 feet beneath the basement slab except along the western property boundary where the water table is shallower, resulting in the need to actively pump out water entering the service elevator pit. "
Env Problem:	"Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were chlorinated volatile organic compounds (VOCs) such as

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

	tetrachloroethene (PCE), trichloroethene (TCE), and cis-1,2-dichloroethene (DCE) which were detected in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem:	"Direct contact with contaminants in the soil or groundwater is unlikely because the site is entirely covered with a building. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system was installed beneath the on-site building to prevent vapors beneath the slab from entering the building. Sampling at an adjacent structure indicates soil vapor intrusion is not a concern. Access to the other adjacent building was denied and soil vapor intrusion may be a potential exposure pathway at that structure. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-02-24 09:04:00
Record Upd:	2015-07-06 04:46:00
Updated By:	HRAHMED
Own Op:	1
Sub Type:	06
Owner Name:	Michael Orbach
Owner Company:	West 24-27 Realty LLC
Owner Address:	70 West 36th Street, Suite 10B
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10018
Owner Country:	United States of America
HW Code:	231073
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	231073
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	231073
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	R2-0777-09-11
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2015-02-10 11:32:00

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

Record Updated: 2015-02-10 11:32:00
Updated By: HRAHMED
Crossref ID: 2015000002658
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-02-09 15:54:00
Record Updated: 2015-02-09 16:00:00
Updated By: HRAHMED

INST CONTROL:
Name: FORMER GUARDIAN CLEANERS
Address: 27-35 WEST 24TH STREET
City,State,Zip: NEW YORK, NY 10010
Site Code: 440109
Control Name: Environmental Easement
HW Code: 231073
Control Code: J
Control Type: INST
Dt record added: 06/26/2015
Dt rec updated: 01/25/2018
Updated By: JJTEETER
Site Code: 440109
Site Description: "Location: The site is located at 27-35 West 24th Street in the Borough of New York, New York. It is located on the northern side of West 24th Street. The site is designated as Block 826, Lot 19. Site Features: The site is a rectangular shaped parcel of land measuring approximately 9,000 square feet and is improved with an one 11-story building with a basement. Current Zoning and Land Use: The building on site is used for office space and a restaurant/bar on the first floor and part of the basement. The site is zoned M1-6, which allows industrial and manufacturing. The current use of the site complies with the zoning code. Past Use of the Site: A dry cleaning facility formerly occupied the restaurant/bar space until approximately 1990. The former dry cleaning operations are believed to have contributed to the known contamination found in groundwater and soil vapor on the site. Site Geology and Hydrogeology: The subsurface lithology was homogenous throughout the site. The subsurface soil was noted to consist of urban fill material and brown coarse grain sand. Based upon boring logs from various site investigations, groundwater is encountered 8-10 feet beneath the basement slab except along the western property boundary where the water table is shallower, resulting in the need to actively pump out water entering the service elevator pit. "
Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were chlorinated volatile organic compounds (VOCs) such as tetrachloroethene (PCE), trichloroethene (TCE), and cis-1,2-dichloroethene (DCE) which were detected in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem: "Direct contact with contaminants in the soil or groundwater is unlikely because the site is entirely covered with a building. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system was installed beneath the on-site building to prevent vapors beneath the slab from entering the building. Sampling at an adjacent structure indicates soil vapor intrusion is not a concern. Access to the other adjacent building was denied and soil vapor intrusion may be a potential exposure pathway at that structure. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2011-02-24 09:04:00
Record Upd: 2015-07-06 04:46:00
Updated By: HRAHMED
Own Op: 1
Sub Type: 06
Owner Name: Michael Orbach
Owner Company: West 24-27 Realty LLC
Owner Address: 70 West 36th Street, Suite 10B
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
HW Code: 231073
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 231073
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 231073
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: R2-0777-09-11
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-02-10 11:32:00
Record Updated: 2015-02-10 11:32:00
Updated By: HRAHMED
Crossref ID: 2015000002658
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-02-09 15:54:00
Record Updated: 2015-02-09 16:00:00
Updated By: HRAHMED

Name: FORMER GUARDIAN CLEANERS
Address: 27-35 WEST 24TH STREET

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

City,State,Zip: NEW YORK, NY 10010
Site Code: 440109
Control Name: Site Management Plan
HW Code: 231073
Control Code: 32
Control Type: INST
Dt record added: 06/26/2015
Dt rec updated: 01/25/2018
Updated By: JJTEETER
Site Code: 440109
Site Description: "Location: The site is located at 27-35 West 24th Street in the Borough of New York, New York. It is located on the northern side of West 24th Street. The site is designated as Block 826, Lot 19. Site Features: The site is a rectangular shaped parcel of land measuring approximately 9,000 square feet and is improved with an one 11-story building with a basement. Current Zoning and Land Use: The building on site is used for office space and a restaurant/bar on the first floor and part of the basement. The site is zoned M1-6, which allows industrial and manufacturing. The current use of the site complies with the zoning code. Past Use of the Site: A dry cleaning facility formerly occupied the restaurant/bar space until approximately 1990. The former dry cleaning operations are believed to have contributed to the known contamination found in groundwater and soil vapor on the site. Site Geology and Hydrogeology: The subsurface lithology was homogenous throughout the site. The subsurface soil was noted to consist of urban fill material and brown coarse grain sand. Based upon boring logs from various site investigations, groundwater is encountered 8-10 feet beneath the basement slab except along the western property boundary where the water table is shallower, resulting in the need to actively pump out water entering the service elevator pit. "
Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were chlorinated volatile organic compounds (VOCs) such as tetrachloroethene (PCE), trichloroethene (TCE), and cis-1,2-dichloroethene (DCE) which were detected in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem: "Direct contact with contaminants in the soil or groundwater is unlikely because the site is entirely covered with a building. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system was installed beneath the on-site building to prevent vapors beneath the slab from entering the building. Sampling at an adjacent structure indicates soil vapor intrusion is not a concern. Access to the other adjacent building was denied and soil vapor intrusion may be a potential exposure pathway at that structure. "
Dump: False
Structure: False

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2011-02-24 09:04:00
Record Upd: 2015-07-06 04:46:00
Updated By: HRAHMED
Own Op: 1
Sub Type: 06
Owner Name: Michael Orbach
Owner Company: West 24-27 Realty LLC
Owner Address: 70 West 36th Street, Suite 10B
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
HW Code: 231073
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 231073
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 231073
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: R2-0777-09-11
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-02-10 11:32:00
Record Updated: 2015-02-10 11:32:00
Updated By: HRAHMED
Crossref ID: 2015000002658
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-02-09 15:54:00
Record Updated: 2015-02-09 16:00:00
Updated By: HRAHMED

Name: FORMER GUARDIAN CLEANERS
Address: 27-35 WEST 24TH STREET
City,State,Zip: NEW YORK, NY 10010
Site Code: 440109
Control Name: Landuse Restriction
HW Code: 231073
Control Code: 25
Control Type: INST
Dt record added: 06/26/2015
Dt rec updated: 01/25/2018
Updated By: JJTEETER
Site Code: 440109
Site Description: "Location: The site is located at 27-35 West 24th Street in the Borough of New York, New York. It is located on the northern side of

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

West 24th Street. The site is designated as Block 826, Lot 19. Site Features: The site is a rectangular shaped parcel of land measuring approximately 9,000 square feet and is improved with an one 11-story building with a basement. Current Zoning and Land Use: The building on site is used for office space and a restaurant/bar on the first floor and part of the basement. The site is zoned M1-6, which allows industrial and manufacturing. The current use of the site complies with the zoning code. Past Use of the Site: A dry cleaning facility formerly occupied the restaurant/bar space until approximately 1990. The former dry cleaning operations are believed to have contributed to the known contamination found in groundwater and soil vapor on the site. Site Geology and Hydrogeology: The subsurface lithology was homogenous throughout the site. The subsurface soil was noted to consist of urban fill material and brown coarse grain sand. Based upon boring logs from various site investigations, groundwater is encountered 8-10 feet beneath the basement slab except along the western property boundary where the water table is shallower, resulting in the need to actively pump out water entering the service elevator pit. "

Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were chlorinated volatile organic compounds (VOCs) such as tetrachloroethene (PCE), trichloroethene (TCE), and cis-1,2-dichloroethene (DCE) which were detected in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."

Health Problem: "Direct contact with contaminants in the soil or groundwater is unlikely because the site is entirely covered with a building. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system was installed beneath the on-site building to prevent vapors beneath the slab from entering the building. Sampling at an adjacent structure indicates soil vapor intrusion is not a concern. Access to the other adjacent building was denied and soil vapor intrusion may be a potential exposure pathway at that structure. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2011-02-24 09:04:00
Record Upd: 2015-07-06 04:46:00
Updated By: HRAHMED
Own Op: 1
Sub Type: 06

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

Owner Name: Michael Orbach
Owner Company: West 24-27 Realty LLC
Owner Address: 70 West 36th Street, Suite 10B
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
HW Code: 231073
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 231073
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 231073
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: R2-0777-09-11
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-02-10 11:32:00
Record Updated: 2015-02-10 11:32:00
Updated By: HRAHMED
Crossref ID: 2015000002658
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-02-09 15:54:00
Record Updated: 2015-02-09 16:00:00
Updated By: HRAHMED

Name: FORMER GUARDIAN CLEANERS
Address: 27-35 WEST 24TH STREET
City,State,Zip: NEW YORK, NY 10010
Site Code: 440109
Control Name: IC/EC Plan
HW Code: 231073
Control Code: 34
Control Type: INST
Dt record added: 06/26/2015
Dt rec updated: 01/25/2018
Updated By: JJTEETER
Site Code: 440109
Site Description: "Location: The site is located at 27-35 West 24th Street in the Borough of New York, New York. It is located on the northern side of West 24th Street. The site is designated as Block 826, Lot 19. Site Features: The site is a rectangular shaped parcel of land measuring approximately 9,000 square feet and is improved with an one 11-story building with a basement. Current Zoning and Land Use: The building on site is used for office space and a restaurant/bar on the first floor and part of the basement. The site is zoned M1-6, which allows industrial and manufacturing. The current use of the site complies with the zoning code. Past Use of the Site: A dry cleaning facility formerly occupied the restaurant/bar space until approximately 1990. The former dry cleaning operations are believed to have contributed to the known contamination found in groundwater and soil vapor on the site. Site Geology and Hydrogeology: The subsurface lithology was

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

homogenous throughout the site. The subsurface soil was noted to consist of urban fill material and brown coarse grain sand. Based upon boring logs from various site investigations, groundwater is encountered 8-10 feet beneath the basement slab except along the western property boundary where the water table is shallower, resulting in the need to actively pump out water entering the service elevator pit. "

Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were chlorinated volatile organic compounds (VOCs) such as tetrachloroethene (PCE), trichloroethene (TCE), and cis-1,2-dichloroethene (DCE) which were detected in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."

Health Problem: "Direct contact with contaminants in the soil or groundwater is unlikely because the site is entirely covered with a building. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system was installed beneath the on-site building to prevent vapors beneath the slab from entering the building. Sampling at an adjacent structure indicates soil vapor intrusion is not a concern. Access to the other adjacent building was denied and soil vapor intrusion may be a potential exposure pathway at that structure. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2011-02-24 09:04:00
Record Upd: 2015-07-06 04:46:00
Updated By: HRAHMED
Own Op: 1
Sub Type: 06
Owner Name: Michael Orbach
Owner Company: West 24-27 Realty LLC
Owner Address: 70 West 36th Street, Suite 10B
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
HW Code: 231073
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 231073
Waste Type: cis-1,2-dichloroethene

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 231073
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: R2-0777-09-11
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-02-10 11:32:00
Record Updated: 2015-02-10 11:32:00
Updated By: HRAHMED
Crossref ID: 2015000002658
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-02-09 15:54:00
Record Updated: 2015-02-09 16:00:00
Updated By: HRAHMED

Name: FORMER GUARDIAN CLEANERS
Address: 27-35 WEST 24TH STREET
City,State,Zip: NEW YORK, NY 10010
Site Code: 440109
Control Name: Ground Water Use Restriction
HW Code: 231073
Control Code: 08
Control Type: INST
Dt record added: 06/26/2015
Dt rec updated: 01/25/2018
Updated By: JJTEETER
Site Code: 440109
Site Description: "Location: The site is located at 27-35 West 24th Street in the Borough of New York, New York. It is located on the northern side of West 24th Street. The site is designated as Block 826, Lot 19. Site Features: The site is a rectangular shaped parcel of land measuring approximately 9,000 square feet and is improved with an one 11-story building with a basement. Current Zoning and Land Use: The building on site is used for office space and a restaurant/bar on the first floor and part of the basement. The site is zoned M1-6, which allows industrial and manufacturing. The current use of the site complies with the zoning code. Past Use of the Site: A dry cleaning facility formerly occupied the restaurant/bar space until approximately 1990. The former dry cleaning operations are believed to have contributed to the known contamination found in groundwater and soil vapor on the site. Site Geology and Hydrogeology: The subsurface lithology was homogenous throughout the site. The subsurface soil was noted to consist of urban fill material and brown coarse grain sand. Based upon boring logs from various site investigations, groundwater is encountered 8-10 feet beneath the basement slab except along the western property boundary where the water table is shallower, resulting in the need to actively pump out water entering the service elevator pit. "
Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were chlorinated volatile organic compounds (VOCs) such as tetrachloroethene (PCE), trichloroethene (TCE), and cis-1,2-dichloroethene (DCE) which were detected in soil, groundwater

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

	and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem:	"Direct contact with contaminants in the soil or groundwater is unlikely because the site is entirely covered with a building. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system was installed beneath the on-site building to prevent vapors beneath the slab from entering the building. Sampling at an adjacent structure indicates soil vapor intrusion is not a concern. Access to the other adjacent building was denied and soil vapor intrusion may be a potential exposure pathway at that structure. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-02-24 09:04:00
Record Upd:	2015-07-06 04:46:00
Updated By:	HRAHMED
Own Op:	1
Sub Type:	06
Owner Name:	Michael Orbach
Owner Company:	West 24-27 Realty LLC
Owner Address:	70 West 36th Street, Suite 10B
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10018
Owner Country:	United States of America
HW Code:	231073
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	231073
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	231073
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	R2-0777-09-11
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2015-02-10 11:32:00
Record Updated:	2015-02-10 11:32:00
Updated By:	HRAHMED

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

Crossref ID: 2015000002658
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-02-09 15:54:00
Record Updated: 2015-02-09 16:00:00
Updated By: HRAHMED

Name: FORMER GUARDIAN CLEANERS
Address: 27-35 WEST 24TH STREET
City,State,Zip: NEW YORK, NY 10010
Site Code: 440109
Control Name: Monitoring Plan
HW Code: 231073
Control Code: 31
Control Type: INST
Dt record added: 06/26/2015
Dt rec updated: 01/25/2018
Updated By: JJTEETER
Site Code: 440109
Site Description: "Location: The site is located at 27-35 West 24th Street in the Borough of New York, New York. It is located on the northern side of West 24th Street. The site is designated as Block 826, Lot 19. Site Features: The site is a rectangular shaped parcel of land measuring approximately 9,000 square feet and is improved with an one 11-story building with a basement. Current Zoning and Land Use: The building on site is used for office space and a restaurant/bar on the first floor and part of the basement. The site is zoned M1-6, which allows industrial and manufacturing. The current use of the site complies with the zoning code. Past Use of the Site: A dry cleaning facility formerly occupied the restaurant/bar space until approximately 1990. The former dry cleaning operations are believed to have contributed to the known contamination found in groundwater and soil vapor on the site. Site Geology and Hydrogeology: The subsurface lithology was homogenous throughout the site. The subsurface soil was noted to consist of urban fill material and brown coarse grain sand. Based upon boring logs from various site investigations, groundwater is encountered 8-10 feet beneath the basement slab except along the western property boundary where the water table is shallower, resulting in the need to actively pump out water entering the service elevator pit. "
Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were chlorinated volatile organic compounds (VOCs) such as tetrachloroethene (PCE), trichloroethene (TCE), and cis-1,2-dichloroethene (DCE) which were detected in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem: "Direct contact with contaminants in the soil or groundwater is unlikely because the site is entirely covered with a building. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to movement of radon gas from the

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system was installed beneath the on-site building to prevent vapors beneath the slab from entering the building. Sampling at an adjacent structure indicates soil vapor intrusion is not a concern. Access to the other adjacent building was denied and soil vapor intrusion may be a potential exposure pathway at that structure. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2011-02-24 09:04:00
Record Upd: 2015-07-06 04:46:00
Updated By: HRAHMED
Own Op: 1
Sub Type: 06
Owner Name: Michael Orbach
Owner Company: West 24-27 Realty LLC
Owner Address: 70 West 36th Street, Suite 10B
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
HW Code: 231073
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 231073
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 231073
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: R2-0777-09-11
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-02-10 11:32:00
Record Updated: 2015-02-10 11:32:00
Updated By: HRAHMED
Crossref ID: 2015000002658
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-02-09 15:54:00
Record Updated: 2015-02-09 16:00:00
Updated By: HRAHMED

Name: FORMER GUARDIAN CLEANERS
Address: 27-35 WEST 24TH STREET
City,State,Zip: NEW YORK, NY 10010
Site Code: 440109
Control Name: O&M Plan

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

HW Code: 231073
Control Code: 33
Control Type: INST
Dt record added: 06/26/2015
Dt rec updated: 01/25/2018
Updated By: JJTEETER
Site Code: 440109
Site Description: "Location: The site is located at 27-35 West 24th Street in the Borough of New York, New York. It is located on the northern side of West 24th Street. The site is designated as Block 826, Lot 19. Site Features: The site is a rectangular shaped parcel of land measuring approximately 9,000 square feet and is improved with an one 11-story building with a basement. Current Zoning and Land Use: The building on site is used for office space and a restaurant/bar on the first floor and part of the basement. The site is zoned M1-6, which allows industrial and manufacturing. The current use of the site complies with the zoning code. Past Use of the Site: A dry cleaning facility formerly occupied the restaurant/bar space until approximately 1990. The former dry cleaning operations are believed to have contributed to the known contamination found in groundwater and soil vapor on the site. Site Geology and Hydrogeology: The subsurface lithology was homogenous throughout the site. The subsurface soil was noted to consist of urban fill material and brown coarse grain sand. Based upon boring logs from various site investigations, groundwater is encountered 8-10 feet beneath the basement slab except along the western property boundary where the water table is shallower, resulting in the need to actively pump out water entering the service elevator pit. "
Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were chlorinated volatile organic compounds (VOCs) such as tetrachloroethene (PCE), trichloroethene (TCE), and cis-1,2-dichloroethene (DCE) which were detected in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem: "Direct contact with contaminants in the soil or groundwater is unlikely because the site is entirely covered with a building. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system was installed beneath the on-site building to prevent vapors beneath the slab from entering the building. Sampling at an adjacent structure indicates soil vapor intrusion is not a concern. Access to the other adjacent building was denied and soil vapor intrusion may be a potential exposure pathway at that structure. "
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False

FORMER GUARDIAN CLEANERS (Continued) **S113916768**

Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2011-02-24 09:04:00
Record Upd: 2015-07-06 04:46:00
Updated By: HRAHMED
Own Op: 1
Sub Type: 06
Owner Name: Michael Orbach
Owner Company: West 24-27 Realty LLC
Owner Address: 70 West 36th Street, Suite 10B
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
HW Code: 231073
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 231073
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 231073
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: R2-0777-09-11
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-02-10 11:32:00
Record Updated: 2015-02-10 11:32:00
Updated By: HRAHMED
Crossref ID: 2015000002658
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-02-09 15:54:00
Record Updated: 2015-02-09 16:00:00
Updated By: HRAHMED

1044
SSW
1/2-1
0.729 mi.
3849 ft.

PIER 45 STORAGE/BERTHN **FUDS** **1024899360**
N/A

NEW YORK CITY, NY

Relative:
Lower

Actual:
4 ft.

FUDS:
EPA Region: 2
Installation ID: NY29799F956000
Congressional District Number: 10
Name: PIER 45 STORAGE/BERTHN
FUDS Number: C02NY1099
City: NEW YORK CITY
State: NY
County: NEW YORK
Object ID: 6951
USACE Division: NAD
USACE District: New England District (NAE)

PIER 45 STORAGE/BERTHN (Continued) **1024899360**

Status:	Properties without projects
Current Owner:	Not reported
EMS Map Link:	https://fudsportal.usace.army.mil/ems/ems/inventory/map/map?id=54899
Eligibility:	Eligible
Has Projects:	No
NPL Status:	Not on the NPL
Property History:	The Navy used Pier 45 as a receiving station for refurbishing and disposal of Naval waste materials.
Project Required:	No
Feature Description:	Not reported
Latitude:	40.73277778
Longitude:	-74.01027778

1045 South 1/2-1 0.757 mi. 3995 ft.

HUDSON DRY CLEANERS **NY SHWS S110246833**
462 HUDSON STREET **NY DRYCLEANERS N/A**
MANHATTAN, NY 10014

Relative: Higher

Actual: 16 ft.

SHWS:

Name:	HUDSON DRY CLEANERS
Address:	462 HUDSON STREET
City,State,Zip:	MANHATTAN, NY 10014
Program:	HW
Site Code:	486480
Classification:	P
Region:	2
Acres:	0.570
HW Code:	231085
Record Add:	09/04/2013
Record Upd:	07/11/2019
Updated By:	MJCRUDEN

Site Description: "Location: The 25,000 square foot (0.57 acre) site is located at 462 Hudson Street in the Borough of Manhattan in an urban area. The site is bordered by Hudson Street to the west, Barrow Street to the north, one and two-family brownstones to the east, and by Morton Street to the south. Site Features: The site is occupied by two 6-story apartment buildings with commercial uses on the first floor along Hudson St. The dry cleaner occupies the northwest corner of the first floor of the northern building. Current Zoning/Use(s): The site is zoned as C1-6/R6 for commercial and residential uses. Historical Use(s): The on-site building was constructed in 1925. A dry cleaner has operated at the site since at least 1986. The site is a RCRA large quantity generator (EPA ID # NYD981141948) of spent solvent, waste code F002. A monitoring well installed in Hudson Street, directly to the west of the dry cleaner during an evaluation of 75 Morton St by NYCSCA yielded a gw sample containing 2,900 ug/l PCE. Site Topography, Geology and Hydrogeology: The Site is generally level and is at an elevation of approximately 36 feet above mean sea level. The geology of New York County consists of unconsolidated glacial deposits overlying crystalline bedrock. Soil cores collected during investigation on a nearby site generally consisted of historic fill material containing brown sand and silt with fine gravel and brick fragments to a depth of 8 to 15 feet below ground surface (bgs). The Site is located 1300 feet east of the Hudson River. Groundwater in the vicinity of the site was encountered at approximately 27 feet bgs and is expected to flow to the west towards

HUDSON DRY CLEANERS (Continued) **S110246833**

the Hudson River."

Env Problem: "Nature and Extent of Contamination: Information is based on the results of a site characterization investigation performed at the nearby property at 75 Morton Street by the NYC School Construction Authority. That investigation was triggered by the discovery of elevated levels of cVOCs in groundwater on that site. The subsequent Supplemental Site Investigation (SSI) indicated that elevated concentrations of cVOCs (namely PCE) existed along the adjacent sidewalk on the eastern side of Hudson Street. The SSI ascertained that the 75 Morton Street site was not a source of the contamination. Eleven temporary groundwater wells were installed on and upgradient from the Morton Street property and samples were collected for lab analysis. One well was installed immediately in front of and downgradient from the Hudson Cleaners site. Groundwater: Tetrachloroethylene (PCE) was detected at elevated concentrations in groundwater samples taken immediately in front of the Hudson Cleaners site. PCE was detected at a concentration of 2900 ppb at that location, with concentrations decreasing in the downgradient direction consistent with the inferred contaminant plume. The groundwater flow direction was confirmed to be from east to west based on surveyed groundwater elevation measurements collected during the 75 Morton St. SSI. Building owners' contractor completed Phase II scope of work at and around Hudson Dry Cleaners in the fall of 2016. The groundwater sample taken in front of this site had only 2.1 ppb PCE, versus 2900 ppb in May 2013. Soil Vapor & Indoor Air: The RP s consultant mobilized to the site on 27 November 2017 to collected six collocated sub-slab and indoor air samples (IA-01/SV-01 through IA-06/SV-06) and one ambient air sample (OA-01). According to the NYSDOH SVI Guidance Matrix the response actions for samples IA-01/SV-01 (1200 / 1300 ug/m3 PCE)and IA-02/SV-02 (120 / 140 ug/m3 PCE)are Mitigate . The Mitigate response action at these locations was triggered by the presence of PCE in the indoor air and soil vapor. Sample set IA-01/SV-01 was collected from the basement of Hudson Cleaners, and sample set IA-02/SV-02 was collected from just east Hudson Cleaners footprint. Significant Threat: Evaluation of significant threat will be made following completion of the Site Characterization."

Health Problem: "Volatile organic compounds may move into the soil vapor (air spaces within the soil), which in turn may move into nearby buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Soil vapor intrusion sampling identified impacts in indoor air quality in one portion of the on-site building that represents a health concern. Further, environmental sampling is necessary to determine if soil vapor intrusion is a concern for off-site buildings."

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported

HUDSON DRY CLEANERS (Continued) **S110246833**

Updated By:	Not reported
Own Op:	4
Sub Type:	E
Owner Name:	Byung Woo Kim
Owner Company:	Hudson Kim Cleaners, Inc.
Owner Address:	462 Hudson Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10014
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Michael Vinocur
Owner Company:	Building Equity Management LLC
Owner Address:	1261 Broadway
Owner Addr2:	Suite 812
Owner City,St,Zip:	New York, NY 10001
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

DRYCLEANERS:

Name:	HUDSON KIM'S CLEANERS
Address:	462 HUDSON ST.
City,State,Zip:	NEW YORK, NY 10014
Facility ID:	2-6205-00290
Phone Number:	212-242-4518
Region:	Not reported
Registration Effective Date:	9/8/2003 11:12:38:006
Inspection Date:	2023-01-17 00:00:00
Install Date:	90/02/17
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Y
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

1046
North
1/2-1
0.792 mi.
4180 ft.

LIRR WEST SIDE YARD **NY SHWS** **S113916804**
12TH AVE AND W 33RD ST **N/A**
MANHATTAN, NY 10001

Relative:
Lower

Actual:
11 ft.

SHWS:

Name:	LIRR WEST SIDE YARD
Address:	12TH AVE AND W 33RD ST
City,State,Zip:	MANHATTAN, NY 10001
Program:	HW
Site Code:	478613

LIRR WEST SIDE YARD (Continued) **S113916804**

Classification: P
Region: 2
Acres: 0.803
HW Code: 231083
Record Add: 02/05/2013
Record Upd: 10/25/2021
Updated By: DJEATON
Site Description: "Location: The LIRR West Side Yard Site (site) is located at the southeast corner of 12th Ave and W 33rd St in midtown Manhattan. This is the northwest corner of the Long Island Railroad's West Side Yard (WSY), where commuter trains which have discharged at Penn Station are stored for their next outbound trip. The West Side Highway lies immediately to the west. The northern end of the High Line Park traverses part of the site. Site Features: The site is largely flat, and is almost completely filled with railroad tracks. Small maintenance buildings are present along the western ends of the storage tracks. Current Zoning and Land Use: The WSY is currently used for the storage of passenger trains. Periodic and routine cleaning and washing of the interior of the passenger train cars is performed. The site is zoned for commercial use. Past Use of the Site: The WSY has been utilized for railroad operations for over 100 years. Location: The LIRR West Side Yard Site (site) is located at the southeast corner of 12th Ave and W 33rd St in midtown Manhattan. This is the northwest corner of the Long Island Railroad's West Side Yard (WSY), where commuter trains which have discharged at Penn Station are stored for their next outbound trip. The West Side Highway lies immediately to the west. The northern end of the High Line Park traverses part of the site. Site Features: The site is largely flat and is almost completely filled with railroad tracks. Small maintenance buildings are present along the western ends of the storage tracks. Current Zoning and Land Use: The WSY is currently used for the storage of passenger trains. Periodic and routine cleaning and washing of the interior of the passenger train cars is performed. The site is zoned for commercial use. Past Use of the Site: The WSY has been utilized for railroad operations for over 100 years. Currently and historically, the LIRR has not stored any petroleum products in tanks or bulk containers in the western portion of the WSY, nor has maintenance activities involved the use of petroleum products. This site was previously reported to and investigated under the Spills program as spill no. 0407411, beginning late 2004. Contamination was discovered in a soil boring on the site during a Phase II Environmental Site Investigation of the WSY for the NY Jets organization, which was then reported to the DEC. Site Geology and Hydrogeology: The northwest corner of the WSY is immediately underlain by a layer of historic fill, approximately 20 to 30 feet thick. Site contamination appears to have been co-deposited with this fill, which was used to extend the Hudson River shoreline westward circa 1900. Below the historic fill exists a native low permeable silty clay to clay unit. Groundwater is present beneath the WSY within the urban fill at a depth of approximately 5 to 7 ft bgs (below ground surface), flowing in a northwesterly direction. "
Env Problem: "Nature and Extent of Contamination: Prior to Completion of Remediation Based upon investigations conducted to date, the primary contaminant of concern is coal tar. Soil- The most significant visual evidence of contamination, including staining, hydrocarbon and naphthalene-like odors and elevated PID readings, was observed within

LIRR WEST SIDE YARD (Continued) **S113916804**

the fill deposits in soil borings SB-05 through SB-08, between 15 and 40 feet below grade, and starting at least 10 to 20 feet below the water table. Seventeen of the 20 subsurface soil samples exhibited detectable concentrations of PAHs, with total PAH concentrations ranging from 0.3 ppm in SB-03 (20.5 - 22.5 feet) to a maximum of 1,818 ppm in SB-05 (25 - 27 feet), adjacent to the West Side Yard along the east side of 12th Avenue in the vicinity of the historic observed area of contamination. This sample had visual evidence of contamination, which also exhibited the highest BTEX concentration, but were below the Industrial Use SCOs. Soil samples from SB-06 (21 - 23 feet) and SB-08 (30 - 33 feet) were sent for forensic fingerprint analysis. The analysis suggests that the sample contained pyrogenic material derived from coal and not petroleum, and the PAH distribution was very similar to tars formed from MGPs utilizing carbureted water gas processes. Groundwater- NAPL was not identified in any of the groundwater monitoring wells. However, six of the 17 groundwater samples identified BTEX and PAH compounds at concentrations above Class GA standards. These samples were collected at or in the vicinity of soil borings which exhibited soil contamination and were screened at a depth intercepting the zone of soil contamination observed at 15 to 40 feet below grade. Off-site wells demonstrate that this contamination is not migrated farther off-site. Soil Vapor and Indoor Air- Soil vapor and indoor air have not been evaluated."

Health Problem: "Since the site is fenced and covered by asphalt or concrete, people will not come into contact with site related soil and groundwater contamination unless they dig below the surface. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Currently there are no occupied buildings on the site. The potential for soil vapor intrusion on- and offsite areas should be evaluated if a change of use is proposed. "

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Not reported
Sub Type: Not reported
Owner Name: Not reported
Owner Company: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported
Owner Country: Not reported

LIRR WEST SIDE YARD (Continued) **S113916804**

HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

1047 SSW 1/2-1 0.835 mi. 4409 ft. **PIER 42 STORAGE/BERTHN** **FUDS** **1024899359 N/A**

NEW YORK CITY, NY

Relative: Lower

Actual: 5 ft.

FUDS:

EPA Region:	2
Installation ID:	NY29799F955900
Congressional District Number:	10
Name:	PIER 42 STORAGE/BERTHN
FUDS Number:	C02NY1098
City:	NEW YORK CITY
State:	NY
County:	NEW YORK
Object ID:	6950
USACE Division:	NAD
USACE District:	New England District (NAE)
Status:	Properties without projects
Current Owner:	Not reported
EMS Map Link:	https://fudsportal.usace.army.mil/ems/ems/inventory/map/map?id=54900
Eligibility:	Eligible
Has Projects:	No
NPL Status:	Not on the NPL
Property History:	The Navy used Pier 42 as a receiving station for refurbishing and disposal of Naval garbage and ashes. The City of New York was contracted by the US Government to make daily collection (garbage, ashes) along all of the piers leased and used by the Navy. The Department of Navy also used Pier 42 as a receiving and transporting station for Armed Forces personnel.
Project Required:	No
Feature Description:	Not reported
Latitude:	40.73111111
Longitude:	-74.01027778

1048
West
1/2-1
0.936 mi.
4943 ft.

STEVENS INSTITUTE OF TECHNOLOGY
CASTLE POINT TER
HOBOKEN CITY, NJ

NJ SHWS **S109300115**
N/A

Relative:
Higher

Actual:
95 ft.

SHWS:

Name:	STEVENS INSTITUTE OF TECHNOLOGY
Address:	CASTLE POINT TER
City,State,Zip:	HOBOKEN CITY, NJ
Site ID:	22064
Status:	Active
Home Owner:	No
PI Number:	017640

Detail As Of April 2012:

X Coord Site:	Not reported
X Coord PI:	Not reported
Y Coord Site:	Not reported
Y Coord PI:	Not reported

1049
WNW
1/2-1
0.947 mi.
4999 ft.

UNION DRY DOCK & REPAIR CO
901 SINATRA DR
HOBOKEN CITY, NJ 07030

NJ SHWS **U000362325**
NJ UST **N/A**
NJ AIRS
NJ Financial Assurance
NJ NPDES

Relative:
Higher

Actual:
23 ft.

SHWS:

Name:	UNION DRY DOCK & REPAIR CO
Address:	901 SINATRA DR
City,State,Zip:	HOBOKEN CITY, NJ
Site ID:	21300
Status:	Active
Home Owner:	No
PI Number:	013004

Detail As Of April 2012:

X Coord Site:	Not reported
X Coord PI:	Not reported
Y Coord Site:	Not reported
Y Coord PI:	Not reported

Name:	UNION DRY DOCK & REPAIR CO
Address:	901 SINATRA DR
City,State,Zip:	HOBOKEN CITY, NJ
Site ID:	21300
Status:	Active
Home Owner:	Not reported
PI Number:	013004

Detail As Of April 2012:

X Coord Site:	Not reported
X Coord PI:	Not reported
Y Coord Site:	Not reported
Y Coord PI:	Not reported

Name:	UNION DRY DOCK & REPAIR
Address:	901 SINATRA DR
City,State,Zip:	HOBOKEN CITY, NJ
Site ID:	21300
Status:	Active

UNION DRY DOCK & REPAIR CO (Continued) **U000362325**

Home Owner: Not reported
PI Number: 766151

Detail As Of April 2012:
X Coord Site: Not reported
X Coord PI: Not reported
Y Coord Site: Not reported
Y Coord PI: Not reported

UST:
Facility ID: 013004

Contact:
Owner Name: Not Identified Not Identified
Organization: Not Identified
Contact Type(UST Reg): Facility Operator
Contact Address (UST Reg): Not reported
Contact Address 2 (UST Reg): Not reported
Conact City,St,Zip (UST Reg): Not reported

Owner Name: GEORGE DREYER
Organization: ROBERT J BURKE PRESIDENT
Contact Type(UST Reg): Tank Owner
Contact Address (UST Reg): PO BOX M1539
Contact Address 2 (UST Reg): Not reported
Conact City,St,Zip (UST Reg): Hoboken, NJ 07030

Tanks:
Tank Id: TANK-1
Tank Number: E1
Tank Status: **Removed**
Tank Status Date: 10/05/1993
Install Date: 01/01/1985
Tank Contents: Unleaded Gasoline
Tank Size: 2000
Tank Compliance: No
Overfill: No
Compliance Monitoring?: No
Overfill Protection: No
Spill Containment: No
Tank Wellhead Protection: Not reported
Tank/Pipe Construction Type: Tank Fiberglass-reinforced plastic
Tank/Pipe Construction Type: Pipe Bare steel
Tank/Pipe Monitor: Pipe None
Tank/Pipe Monitor: Tank None

Tank Id: TANK-2
Tank Number: E2
Tank Status: **Removed**
Tank Status Date: 10/05/1993
Install Date: 01/01/1985
Tank Contents: Light Diesel Fuel (No. 1-D)
Tank Size: 2000
Tank Compliance: No

UNION DRY DOCK & REPAIR CO (Continued) **U000362325**

Overfill:	No
Compliance Monitoring?:	No
Overfill Protection:	No
Spill Containment:	No
Tank Wellhead Protection:	Not reported
Tank/Pipe Construction Type:	Tank Fiberglass-reinforced plastic
Tank/Pipe Construction Type:	Pipe Bare steel
Tank/Pipe Monitor:	Pipe None
Tank/Pipe Monitor:	Tank None

AIRS:

Name:	UNION DRY DOCK & REPAIR CO
Address:	901 SINATRA DR
City,State,Zip:	HOBOKEN, NJ 07030
Emission Year:	Not reported
Facility Number:	12524
NAICS Code:	Not reported
Pollutant Name:	Not reported
Tons/Year lbs/Year For Taps 1000 Tons/Year For CO2:	Not reported
Tons/Season (5/1-9/30):	Not reported
Lbs/Day Peak Ozone Season (6/1-8/31):	Not reported
Lbs/Day Co-season (12/1-2/31):	Not reported
Permit of Emission:	PERMIT
X Coordinate:	624124
Y Coordinate:	697590
Coordinate Units:	NJ State Plane (NAD83) - USFEET
Coordinate Type:	GPS
Active Number:	GEN160001
Active Type Description:	(GP-019) Portable Equipment
Document Status:	Terminated
Expiration Date:	05/28/2020
Active Flag:	N
NAICS Description:	Not reported
TPY of Fugitive Emissions:	Not reported
TPY of Non-Fugitive Emissions:	Not reported
Ozone Season Non-Fugitives:	Not reported
Ozone Season Fugitive:	Not reported
May Sep Fugitive QTY:	Not reported
May Sep Total QTY:	Not reported
Effective Start Date:	03/30/2016

Name:	UNION DRY DOCK & REPAIR CO
Address:	901 SINATRA DR
City,State,Zip:	HOBOKEN, NJ 07030
Emission Year:	Not reported
Facility Number:	12524
NAICS Code:	Not reported
Pollutant Name:	Not reported
Tons/Year lbs/Year For Taps 1000 Tons/Year For CO2:	Not reported
Tons/Season (5/1-9/30):	Not reported
Lbs/Day Peak Ozone Season (6/1-8/31):	Not reported
Lbs/Day Co-season (12/1-2/31):	Not reported
Permit of Emission:	PERMIT
X Coordinate:	624124
Y Coordinate:	697590
Coordinate Units:	NJ State Plane (NAD83) - USFEET
Coordinate Type:	GPS

UNION DRY DOCK & REPAIR CO (Continued) **U000362325**

Active Number:	PCP040001
Active Type Description:	Construction of New Source
Document Status:	Superseded (Archived)
Expiration Date:	10/31/2009
Active Flag:	N
NAICS Description:	Not reported
TPY of Fugitive Emissions:	Not reported
TPY of Non-Fugitive Emissions:	Not reported
Ozone Season Non-Fugitives:	Not reported
Ozone Season Fugitive:	Not reported
May Sep Fugitive QTY:	Not reported
May Sep Total QTY:	Not reported
Effective Start Date:	11/01/2004
Name:	UNION DRY DOCK & REPAIR CO
Address:	901 SINATRA DR
City,State,Zip:	HOBOKEN, NJ 07030
Emission Year:	Not reported
Facility Number:	12524
NAICS Code:	Not reported
Pollutant Name:	Not reported
Tons/Year lbs/Year For Taps 1000 Tons/Year For CO2:	Not reported
Tons/Season (5/1-9/30):	Not reported
Lbs/Day Peak Ozone Season (6/1-8/31):	Not reported
Lbs/Day Co-season (12/1-2/31):	Not reported
Permit of Emission:	PERMIT
X Coordinate:	624124
Y Coordinate:	697590
Coordinate Units:	NJ State Plane (NAD83) - USFEET
Coordinate Type:	GPS
Active Number:	PCP040002
Active Type Description:	Construction of New Source
Document Status:	Denied
Expiration Date:	Not reported
Active Flag:	N
NAICS Description:	Not reported
TPY of Fugitive Emissions:	Not reported
TPY of Non-Fugitive Emissions:	Not reported
Ozone Season Non-Fugitives:	Not reported
Ozone Season Fugitive:	Not reported
May Sep Fugitive QTY:	Not reported
May Sep Total QTY:	Not reported
Effective Start Date:	Not reported
Name:	UNION DRY DOCK & REPAIR CO
Address:	901 SINATRA DR
City,State,Zip:	HOBOKEN, NJ 07030
Emission Year:	Not reported
Facility Number:	12524
NAICS Code:	Not reported
Pollutant Name:	Not reported
Tons/Year lbs/Year For Taps 1000 Tons/Year For CO2:	Not reported
Tons/Season (5/1-9/30):	Not reported
Lbs/Day Peak Ozone Season (6/1-8/31):	Not reported
Lbs/Day Co-season (12/1-2/31):	Not reported
Permit of Emission:	PERMIT
X Coordinate:	624124

UNION DRY DOCK & REPAIR CO (Continued) **U000362325**

Y Coordinate:	697590
Coordinate Units:	NJ State Plane (NAD83) - USFEET
Coordinate Type:	GPS
Active Number:	PCP160001
Active Type Description:	Construction of New Source
Document Status:	Withdrawn
Expiration Date:	Not reported
Active Flag:	N
NAICS Description:	Not reported
TPY of Fugitive Emissions:	Not reported
TPY of Non-Fugitive Emissions:	Not reported
Ozone Season Non-Fugitives:	Not reported
Ozone Season Fugitive:	Not reported
May Sep Fugitive QTY:	Not reported
May Sep Total QTY:	Not reported
Effective Start Date:	Not reported

Name:	UNION DRY DOCK & REPAIR CO
Address:	901 SINATRA DR
City,State,Zip:	HOBOKEN, NJ 07030
Emission Year:	Not reported
Facility Number:	12524
NAICS Code:	Not reported
Pollutant Name:	Not reported
Tons/Year lbs/Year For Taps 1000 Tons/Year For CO2:	Not reported
Tons/Season (5/1-9/30):	Not reported
Lbs/Day Peak Ozone Season (6/1-8/31):	Not reported
Lbs/Day Co-season (12/1-2/31):	Not reported
Permit of Emission:	PERMIT
X Coordinate:	624124
Y Coordinate:	697590
Coordinate Units:	NJ State Plane (NAD83) - USFEET
Coordinate Type:	GPS
Active Number:	PCP050001
Active Type Description:	Construction of New Source
Document Status:	Terminated
Expiration Date:	05/28/2020
Active Flag:	N
NAICS Description:	Not reported
TPY of Fugitive Emissions:	Not reported
TPY of Non-Fugitive Emissions:	Not reported
Ozone Season Non-Fugitives:	Not reported
Ozone Season Fugitive:	Not reported
May Sep Fugitive QTY:	Not reported
May Sep Total QTY:	Not reported
Effective Start Date:	12/12/2005

Name:	UNION DRY DOCK & REPAIR CO
Address:	901 SINATRA DR
City,State,Zip:	HOBOKEN, NJ 07030
Emission Year:	Not reported
Facility Number:	12524
NAICS Code:	Not reported
Pollutant Name:	Not reported
Tons/Year lbs/Year For Taps 1000 Tons/Year For CO2:	Not reported
Tons/Season (5/1-9/30):	Not reported
Lbs/Day Peak Ozone Season (6/1-8/31):	Not reported

UNION DRY DOCK & REPAIR CO (Continued) **U000362325**

Lbs/Day Co-season (12/1-2/31):	Not reported
Permit of Emission:	PERMIT
X Coordinate:	624124
Y Coordinate:	697590
Coordinate Units:	NJ State Plane (NAD83) - USFEET
Coordinate Type:	GPS
Active Number:	PCP100001
Active Type Description:	Compliance Plan Change
Document Status:	Terminated
Expiration Date:	12/26/2019
Active Flag:	N
NAICS Description:	Not reported
TPY of Fugitive Emissions:	Not reported
TPY of Non-Fugitive Emissions:	Not reported
Ozone Season Non-Fugitives:	Not reported
Ozone Season Fugitive:	Not reported
May Sep Fugitive QTY:	Not reported
May Sep Total QTY:	Not reported
Effective Start Date:	12/15/2010

Name:	UNION DRY DOCK & REPAIR CO
Address:	901 SINATRA DR
City,State,Zip:	HOBOKEN, NJ 07030
Emission Year:	Not reported
Facility Number:	12524
NAICS Code:	Not reported
Pollutant Name:	Not reported
Tons/Year lbs/Year For Taps 1000 Tons/Year For CO2:	Not reported
Tons/Season (5/1-9/30):	Not reported
Lbs/Day Peak Ozone Season (6/1-8/31):	Not reported
Lbs/Day Co-season (12/1-2/31):	Not reported
Permit of Emission:	PERMIT
X Coordinate:	624124
Y Coordinate:	697590
Coordinate Units:	NJ State Plane (NAD83) - USFEET
Coordinate Type:	GPS
Active Number:	PCP100002
Active Type Description:	Modification
Document Status:	Terminated
Expiration Date:	10/30/2019
Active Flag:	N
NAICS Description:	Not reported
TPY of Fugitive Emissions:	Not reported
TPY of Non-Fugitive Emissions:	Not reported
Ozone Season Non-Fugitives:	Not reported
Ozone Season Fugitive:	Not reported
May Sep Fugitive QTY:	Not reported
May Sep Total QTY:	Not reported
Effective Start Date:	02/23/2011

Name:	UNION DRY DOCK & REPAIR CO
Address:	901 SINATRA DR
City,State,Zip:	HOBOKEN, NJ 07030
Emission Year:	Not reported
Facility Number:	12524
NAICS Code:	Not reported
Pollutant Name:	Not reported

UNION DRY DOCK & REPAIR CO (Continued) **U000362325**

Tons/Year lbs/Year For Taps 1000 Tons/Year For CO2:	Not reported
Tons/Season (5/1-9/30):	Not reported
Lbs/Day Peak Ozone Season (6/1-8/31):	Not reported
Lbs/Day Co-season (12/1-2/31):	Not reported
Permit of Emission:	PERMIT
X Coordinate:	624124
Y Coordinate:	697590
Coordinate Units:	NJ State Plane (NAD83) - USFEET
Coordinate Type:	GPS
Active Number:	PCP040003
Active Type Description:	Construction of New Source
Document Status:	Superseded (Archived)
Expiration Date:	12/27/2009
Active Flag:	N
NAICS Description:	Not reported
TPY of Fugitive Emissions:	Not reported
TPY of Non-Fugitive Emissions:	Not reported
Ozone Season Non-Fugitives:	Not reported
Ozone Season Fugitive:	Not reported
May Sep Fugitive QTY:	Not reported
May Sep Total QTY:	Not reported
Effective Start Date:	12/28/2004

NJ Financial Assurance:

Name:	UNION DRY DOCK & REPAIR CO
Address:	901 SINATRA DR
City,State,Zip:	HOBOKEN CITY, NJ
Dispositon Date:	11/13/2017
RFS Disposition Description:	APPROVED
Institution:	PORT IMPERIAL MARINE FACILITIES LLC
RFS Type Description:	Remediation Trust Fund
PI Number:	766151
Activity Class Code:	RFS
Act Class Decode:	Remediation Funding Source
Document Title:	E20170117 Union Dry Dock

Name:	UNION DRY DOCK & REPAIR CO
Address:	901 SINATRA DR
City,State,Zip:	HOBOKEN CITY, NJ
Dispositon Date:	02/09/2018
RFS Disposition Description:	APPROVED
Institution:	PORT IMPERIAL MARINE FACILITIES LLC
RFS Type Description:	Remediation Trust Fund
PI Number:	766151
Activity Class Code:	RFS
Act Class Decode:	Remediation Funding Source
Document Title:	E20170117 Union Dry Dock

Name:	UNION DRY DOCK & REPAIR CO
Address:	901 SINATRA DR
City,State,Zip:	HOBOKEN CITY, NJ
Dispositon Date:	02/09/2018
RFS Disposition Description:	RELEASED
Institution:	PORT IMPERIAL MARINE FACILITIES LLC
RFS Type Description:	Remediation Trust Fund
PI Number:	766151
Activity Class Code:	RFS

UNION DRY DOCK & REPAIR CO (Continued) **U000362325**

Act Class Decode: Remediation Funding Source
Document Title: E20170117 Union Dry Dock

Name: UNION DRY DOCK & REPAIR CO
Address: 901 SINATRA DR
City,State,Zip: HOBOKEN CITY, NJ
Dispositon Date: 09/19/2018
RFS Disposition Description: REDUCED
Institution: PORT IMPERIAL MARINE FACILITIES LLC
RFS Type Description: Remediation Trust Fund
PI Number: 766151
Activity Class Code: RFS
Act Class Decode: Remediation Funding Source
Document Title: E20170117 Union Dry Dock

Name: UNION DRY DOCK & REPAIR CO
Address: 901 SINATRA DR
City,State,Zip: HOBOKEN CITY, NJ
Dispositon Date: 04/11/2019
RFS Disposition Description: REDUCED
Institution: PORT IMPERIAL MARINE FACILITIES LLC
RFS Type Description: Remediation Trust Fund
PI Number: 766151
Activity Class Code: RFS
Act Class Decode: Remediation Funding Source
Document Title: E20170117 Union Dry Dock

Name: UNION DRY DOCK & REPAIR CO
Address: 901 SINATRA DR
City,State,Zip: HOBOKEN CITY, NJ
Dispositon Date: 11/14/2019
RFS Disposition Description: REDUCED
Institution: PORT IMPERIAL MARINE FACILITIES LLC
RFS Type Description: Remediation Trust Fund
PI Number: 766151
Activity Class Code: RFS
Act Class Decode: Remediation Funding Source
Document Title: E20170117 Union Dry Dock

Name: UNION DRY DOCK & REPAIR CO
Address: 901 SINATRA DR
City,State,Zip: HOBOKEN CITY, NJ
Dispositon Date: 11/05/2020
RFS Disposition Description: REDUCED
Institution: PORT IMPERIAL MARINE FACILITIES LLC
RFS Type Description: Remediation Trust Fund
PI Number: 766151
Activity Class Code: RFS
Act Class Decode: Remediation Funding Source
Document Title: E20170117 Union Dry Dock

Name: UNION DRY DOCK & REPAIR CO
Address: 901 SINATRA DR
City,State,Zip: HOBOKEN CITY, NJ
Dispositon Date: 11/16/2021
RFS Disposition Description: REDUCED
Institution: PORT IMPERIAL MARINE FACILITIES LLC

UNION DRY DOCK & REPAIR CO (Continued) **U000362325**

RFS Type Description:	Remediation Trust Fund
PI Number:	766151
Activity Class Code:	RFS
Act Class Decode:	Remediation Funding Source
Document Title:	E20170117 Union Dry Dock

NJPDES:

Name:	UNION DRY DOCK & REPAIR CO
Address:	901 SINATRA DRIVE
City,State,Zip:	HOBOKEN, NJ 07030
NJPDES Permit Number:	NJ0104728
Facility Telephone:	2019635833
Facility Contact:	OPERATOR
Facility Municipality:	HOBOKEN CITY
Facility Enforcement region:	NORTHERN
Discharger Classification:	Not reported
Discharger Category Code:	Not reported
Document Status:	Not reported
Facility Primary SIC code:	Not reported
Facility Ownership:	PRIVATE
Facility Discharge Basin code:	Not reported
Facility Discharge Basin name:	Not reported
Facility Lat/Long:	0 0
Site X Coordinate:	Not reported
Site X Coordinate:	Not reported
Facility Lot number:	1
Facility Block number:	259
Permittee Name:	UNION DRY DOCK & REPAIR CO
Permittee Address:	901 SINATRA DRIVE
Permittee PO Box:	Not reported
Permittee City,St,Zip:	HOBOKEN, NJ 07030 1303
Category Description:	RENEWAL
Date Permit Application Received:	05/22/1998
Date Draft Permit Issued:	05/09/2000
Date Final Permit Issued:	06/23/2000
Date Final Permit Effective:	07/01/2000
Date Final Permit Expires:	06/30/2005
PI Number:	Not reported
Regional Office:	Not reported
Permit Category:	STORMWATER

1050 West 1/2-1 0.985 mi. 5201 ft.

STEVENS INSTITUTE OF TECHNOLOGY **NJ SHWS** **S109314436**
600 SINATRA DR **N/A**
HOBOKEN CITY, NJ

Relative: Higher

Actual: 45 ft.

SHWS:

Name:	STEVENS INSTITUTE OF TECHNOLOGY
Address:	600 SINATRA DR
City,State,Zip:	HOBOKEN CITY, NJ
Site ID:	92532
Status:	Closed
Home Owner:	No
PI Number:	017639

Detail As Of April 2012:

X Coord Site:	Not reported

STEVENS INSTITUTE OF TECHNOLOGY (Continued) **S109314436**

X Coord PI: Not reported
Y Coord Site: Not reported
Y Coord PI: Not reported

Count: 10 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
HOBOKEN CITY	S125905711	JACKSON STREET ROW BETWEEN 7TH & 8	JACKSON ST BETWEEN 7TH & 8TH	07030	NJ SHWS, NJ ENG CONTROLS
HOBOKEN CITY	S121974612	TARRAGON CORPORATION BLOCK 103	1101 MADISON & 1100 1110 JEFFE	07030	NJ SHWS, NJ ENG CONTROLS
MANHATTAN	S121493093	WEST 29TH STREET GW	WEST 29TH STREET AT 10TH AVENU	10001	NY SHWS
MANHATTAN	S113922053	PROPOSED FEDERAL EXPRESS DISTRIBUT	BETWEEN 17TH & 18TH STREETS &	10011	NY VCP
NEW YORK	S121933879	CE - E. 21ST ST. WORKS	EAST 20TH - EAST 22ND STS.	10010	NY SHWS
NEW YORK	1014201302	TOTTENVILLE COPPER CO.	W. 29TH ST	10001	SEMS-ARCHIVE, LEAD SMELTERS
NEW YORK	S105912830	NYC DOS WEST 30TH STREET RECYCLING	WEST 3OTH STREET & WEST SIDE H	10001	NY SWF/LF
NEW YORK	1024334538	NYC STEAM PIPE RUPTURE 2018	5TH AVENUE AND W 21ST STREET	10010	SEMS, FINDS
NEW YORK	S113916762	WEST 9TH STREET GW	WEST 9TH STREET	10011	NY SHWS
NEW YORK	1026603693	HOSPITAL FOR JOINT DISEASES	HOSP FOR JT. DISEASES ORTHO IN	10003	PRP

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 19

Source: EPA
Telephone: N/A
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 10
Telephone 206-553-8665

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 19

Source: EPA
Telephone: N/A
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 19

Source: EPA
Telephone: N/A
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 05/25/2021
Date Data Arrived at EDR: 06/24/2021
Date Made Active in Reports: 09/20/2021
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 12/29/2021
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 19

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 04/25/2022
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 19

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 04/25/2022
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 02/28/2022
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/17/2022
Number of Days to Update: 15

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 02/28/2022
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/17/2022
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 02/28/2022
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/17/2022
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 02/28/2022
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/17/2022
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 02/28/2022
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/17/2022
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 11/15/2021
Date Data Arrived at EDR: 11/16/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 84

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 02/07/2022
Next Scheduled EDR Contact: 05/23/2022
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 11/19/2021
Date Data Arrived at EDR: 11/19/2021
Date Made Active in Reports: 02/14/2022
Number of Days to Update: 87

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/23/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 11/19/2021
Date Data Arrived at EDR: 11/19/2021
Date Made Active in Reports: 02/14/2022
Number of Days to Update: 87

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/23/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 03/01/2022
Date Made Active in Reports: 03/10/2022
Number of Days to Update: 9

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 03/22/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

NY SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 01/06/2022
Date Data Arrived at EDR: 01/06/2022
Date Made Active in Reports: 01/07/2022
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/08/2022
Next Scheduled EDR Contact: 05/23/2022
Data Release Frequency: Annually

NJ SHWS: Known Contaminated Sites in New Jersey

The Known Contaminated Sites in New Jersey includes sites under the purview of the Site Remediation Program which have contamination present at levels greater than the applicable cleanup criteria for soil and/or groundwater standards. The sites appearing in Known Contaminated Sites in New Jersey are classified as either active, where the site is assigned to a specific remedial program area, or pending, where the site is awaiting assignment to a specific remedial program area. Sites where no further action (NFA) designation has been given are not included in this report unless there are other areas of identified contamination which have not been remediated. This report includes sites being remediated under all of the various regulatory programs administered by the Site Remediation Program such as: Federal Superfund Program, Federal Resource Conservation and Recovery Act (RCRA), New Jersey's Industrial Site Recovery Act (ISRA), New Jersey's Underground Storage of Hazardous Substances Act, New Jersey's Spill Compensation and Control Act, New Jersey's Solid Waste Management Act, New Jersey's Water Pollution Control Act.

Date of Government Version: 11/01/2021
Date Data Arrived at EDR: 12/02/2021
Date Made Active in Reports: 02/23/2022
Number of Days to Update: 83

Source: New Jersey Department of Environmental Protection
Telephone: 609-292-8761
Last EDR Contact: 02/14/2022
Next Scheduled EDR Contact: 05/30/2022
Data Release Frequency: Varies

Lists of state and tribal landfills and solid waste disposal facilities

NY SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 12/21/2021
Date Data Arrived at EDR: 12/27/2021
Date Made Active in Reports: 03/22/2022
Number of Days to Update: 85

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 12/22/2021
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Quarterly

NJ SWF/LF: Solid Waste Facility Directory

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 08/16/2021
Date Data Arrived at EDR: 10/27/2021
Date Made Active in Reports: 01/19/2022
Number of Days to Update: 84

Source: Department of Environmental Protection
Telephone: 609-984-6741
Last EDR Contact: 01/28/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: Annually

Lists of state and tribal leaking storage tanks

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 05/28/2021
Date Data Arrived at EDR: 06/22/2021
Date Made Active in Reports: 09/20/2021
Number of Days to Update: 90

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/28/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85
Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85
Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

NY LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 03/15/2022
Date Data Arrived at EDR: 03/15/2022
Date Made Active in Reports: 03/16/2022
Number of Days to Update: 1
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/15/2022
Next Scheduled EDR Contact: 05/23/2022
Data Release Frequency: Varies

NY HIST LTANKS: Listing of Leaking Storage Tanks
A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing
A listing of all FEMA owned underground storage tanks.

Date of Government Version: 10/14/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 02/01/2022
Number of Days to Update: 88
Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 02/07/2022
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Varies

NY UST: Petroleum Bulk Storage (PBS) Database
Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 12/16/2021
Date Data Arrived at EDR: 12/16/2021
Date Made Active in Reports: 03/01/2022
Number of Days to Update: 75
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/22/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NJ UST: Underground Storage Tank Data

Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 10/25/2021
Date Data Arrived at EDR: 11/18/2021
Date Made Active in Reports: 02/04/2022
Number of Days to Update: 78

Source: Department of Environmental Protection
Telephone: 609-341-3121
Last EDR Contact: 01/31/2022
Next Scheduled EDR Contact: 05/16/2022
Data Release Frequency: Varies

NY CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

NY MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

NY CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 12/16/2021
Date Data Arrived at EDR: 12/16/2021
Date Made Active in Reports: 03/01/2022
Number of Days to Update: 75

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/22/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

NY MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 12/16/2021
Date Data Arrived at EDR: 12/16/2021
Date Made Active in Reports: 03/01/2022
Number of Days to Update: 75

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/22/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

NY AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 12/16/2021
Date Data Arrived at EDR: 12/16/2021
Date Made Active in Reports: 03/01/2022
Number of Days to Update: 75

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/22/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: No Update Planned

NY CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

NY MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 10/14/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/06/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 02/09/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 05/28/2021
Date Data Arrived at EDR: 06/22/2021
Date Made Active in Reports: 09/20/2021
Number of Days to Update: 90

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

NY TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 12/16/2021
Date Data Arrived at EDR: 12/16/2021
Date Made Active in Reports: 03/01/2022
Number of Days to Update: 75

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 03/22/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

NY RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/23/2021
Date Data Arrived at EDR: 12/13/2021
Date Made Active in Reports: 03/02/2022
Number of Days to Update: 79

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 03/16/2022
Next Scheduled EDR Contact: 06/27/2022
Data Release Frequency: Varies

NY ENV RES DECL: Environmental Restrictive Declarations

The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 11/23/2021
Date Data Arrived at EDR: 12/15/2021
Date Made Active in Reports: 03/01/2022
Number of Days to Update: 76

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 03/15/2022
Next Scheduled EDR Contact: 06/27/2022
Data Release Frequency: Varies

NY ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 01/06/2022
Date Data Arrived at EDR: 01/06/2022
Date Made Active in Reports: 01/07/2022
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 02/08/2022
Next Scheduled EDR Contact: 05/23/2022
Data Release Frequency: Quarterly

NJ ENG CONTROLS: Declaration Environmental Restriction/Deed Notice Sites

Legal Document that restricts the use of contaminated property; holds owner(s) to the regulatory/statutory requirements for cleanup.

Date of Government Version: 11/25/2021
Date Data Arrived at EDR: 11/29/2021
Date Made Active in Reports: 02/15/2022
Number of Days to Update: 78

Source: Department of Environmental Protection
Telephone: 609-341-3121
Last EDR Contact: 02/14/2022
Next Scheduled EDR Contact: 05/30/2022
Data Release Frequency: Varies

NY INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 01/06/2022
Date Data Arrived at EDR: 01/06/2022
Date Made Active in Reports: 01/07/2022
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 02/08/2022
Next Scheduled EDR Contact: 05/23/2022
Data Release Frequency: Quarterly

NJ INST CONTROL: Classification Exception Area Sites

A Classification Exception Area is an institutional control providing notice that ground water contamination exists in a particular location above State standards.

Date of Government Version: 11/25/2021
Date Data Arrived at EDR: 11/29/2021
Date Made Active in Reports: 02/14/2022
Number of Days to Update: 77

Source: Department of Environmental Protection
Telephone: 609-341-3121
Last EDR Contact: 02/14/2022
Next Scheduled EDR Contact: 05/30/2022
Data Release Frequency: Varies

Lists of state and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 01/06/2022
Date Data Arrived at EDR: 01/06/2022
Date Made Active in Reports: 01/07/2022
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 02/08/2022
Next Scheduled EDR Contact: 05/23/2022
Data Release Frequency: Semi-Annually

NY VCP NYC: Voluntary Cleanup Program Listing NYC

New York City voluntary cleanup program sites.

Date of Government Version: 12/06/2021
Date Data Arrived at EDR: 12/08/2021
Date Made Active in Reports: 01/06/2022
Number of Days to Update: 29

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 03/09/2022
Next Scheduled EDR Contact: 06/20/2022
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 03/16/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Varies

NJ VCP: Voluntary Cleanup Program Sites

Through the VCP, responsible parties, developers, local officials, or individuals may work with the department to remediate non-priority contaminated sites that pose no immediate threat to human health or the environment.

Date of Government Version: 01/12/2018
Date Data Arrived at EDR: 05/22/2018
Date Made Active in Reports: 07/02/2018
Number of Days to Update: 41

Source: Department of Environmental Protection
Telephone: 609-341-3121
Last EDR Contact: 03/23/2022
Next Scheduled EDR Contact: 07/11/2022
Data Release Frequency: Varies

Lists of state and tribal brownfield sites

NY BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 01/06/2022
Date Data Arrived at EDR: 01/06/2022
Date Made Active in Reports: 01/07/2022
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 02/08/2022
Next Scheduled EDR Contact: 05/23/2022
Data Release Frequency: Semi-Annually

NJ BROWNFIELDS: Brownfields Database

Brownfields are identified as former or current commercial or industrial use sites that are presently vacant or underutilized, on which there is suspected to have been a discharge of a contamination to the soil or groundwater at concentrations greater than applicable cleanup criteria.

Date of Government Version: 03/26/2020
Date Data Arrived at EDR: 04/16/2020
Date Made Active in Reports: 04/23/2020
Number of Days to Update: 7

Source: Department of Environmental Protection
Telephone: 609-292-1251
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Annually

NY ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 01/06/2022
Date Data Arrived at EDR: 01/06/2022
Date Made Active in Reports: 01/07/2022
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/08/2022
Next Scheduled EDR Contact: 05/23/2022
Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 02/23/2022
Date Data Arrived at EDR: 03/10/2022
Date Made Active in Reports: 03/10/2022
Number of Days to Update: 0

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 03/15/2022
Next Scheduled EDR Contact: 06/27/2022
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 12/21/2021
Date Data Arrived at EDR: 12/27/2021
Date Made Active in Reports: 03/22/2022
Number of Days to Update: 85

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 12/22/2021
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Quarterly

NY SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 03/01/2022
Next Scheduled EDR Contact: 06/20/2022
Data Release Frequency: No Update Planned

NJ SWRCY: Approved Class B Recycling Facilities

"Class B recyclable material" means a source separated recyclable material which is subject to Department approval prior to receipt, storage, processing or transfer at a recycling center in accordance with N.J.S.A. 13:1E-99.34b.

Date of Government Version: 11/18/2020
Date Data Arrived at EDR: 01/27/2021
Date Made Active in Reports: 04/16/2021
Number of Days to Update: 79

Source: Department of Environmental Protection
Telephone: 609-984-6650
Last EDR Contact: 01/26/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: Varies

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 01/24/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: Varies

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 01/13/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 01/28/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 11/16/2021
Date Data Arrived at EDR: 11/18/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 82

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/23/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: No Update Planned

NY DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 01/06/2022
Date Data Arrived at EDR: 01/06/2022
Date Made Active in Reports: 01/07/2022
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/08/2022
Next Scheduled EDR Contact: 05/23/2022
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 11/16/2021
Date Data Arrived at EDR: 11/18/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 82

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/23/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: Quarterly

NY PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 02/01/2022
Next Scheduled EDR Contact: 05/16/2022
Data Release Frequency: Varies

NJ PFAS: PFAS Contamination Site Location

A listing of occurrences of Perfluorinated Chemicals in Untreated New Jersey Drinking Water Sources.

Date of Government Version: 01/20/2022
Date Data Arrived at EDR: 02/23/2022
Date Made Active in Reports: 03/15/2022
Number of Days to Update: 20

Source: Department of Environmental Protectionh
Telephone: 609-292-5550
Last EDR Contact: 02/14/2022
Next Scheduled EDR Contact: 05/30/2022
Data Release Frequency: Varies

Local Lists of Registered Storage Tanks

NY HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

NY HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

NY LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 11/01/2021
Date Data Arrived at EDR: 11/02/2021
Date Made Active in Reports: 01/24/2022
Number of Days to Update: 83

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 01/31/2022
Next Scheduled EDR Contact: 05/16/2022
Data Release Frequency: Quarterly

NJ LIENS: Environmental LIENS

A listing of properties with environmental liens. The listing includes sites from the Site Remediation & Waste Management Program Sites where the Department has placed either a 1st Priority or Regular Spill Fund Lien against. 1st Priority Type Lien - a lien placed against the property where the discharged occurred providing that the owners of the property have some responsibility towards the discharge. First Priority Lien is superior to other types of liens. Non-Priority (Regular) Type Lien - a lien placed against the Responsible Party & their revenues and all real and personal property, other than the real property comprising the location of the discharge.

Date of Government Version: 01/26/2022
Date Data Arrived at EDR: 02/24/2022
Date Made Active in Reports: 03/15/2022
Number of Days to Update: 19

Source: Department of Environmental Protection
Telephone: 609-341-3121
Last EDR Contact: 02/07/2022
Next Scheduled EDR Contact: 05/23/2022
Data Release Frequency: Varies

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 19

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/15/2021
Date Data Arrived at EDR: 12/16/2021
Date Made Active in Reports: 03/10/2022
Number of Days to Update: 84

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 03/21/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

NY SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 03/15/2022
Date Data Arrived at EDR: 03/15/2022
Date Made Active in Reports: 03/16/2022
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/15/2022
Next Scheduled EDR Contact: 05/23/2022
Data Release Frequency: Varies

NY HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

NY SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

NJ SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 06/15/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/11/2013
Number of Days to Update: 39

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

NY SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

NJ SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 09/02/1997
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/06/2013
Number of Days to Update: 62

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 02/28/2022
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/17/2022
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 10/26/2021
Date Data Arrived at EDR: 11/16/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 84

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 02/15/2022
Next Scheduled EDR Contact: 05/30/2022
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 04/25/2022
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 01/07/2022
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 02/08/2022
Next Scheduled EDR Contact: 05/23/2022
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 12/13/2021
Date Data Arrived at EDR: 12/17/2021
Date Made Active in Reports: 03/17/2022
Number of Days to Update: 90

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 03/21/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 02/01/2022
Next Scheduled EDR Contact: 05/16/2022
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 02/03/2022
Next Scheduled EDR Contact: 05/16/2022
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/17/2020
Date Made Active in Reports: 09/10/2020
Number of Days to Update: 85

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 03/18/2022
Next Scheduled EDR Contact: 06/27/2022
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 08/14/2020
Date Made Active in Reports: 11/04/2020
Number of Days to Update: 82

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 02/18/2022
Next Scheduled EDR Contact: 05/30/2022
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 10/18/2021
Date Data Arrived at EDR: 10/20/2021
Date Made Active in Reports: 01/10/2022
Number of Days to Update: 82

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 01/19/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 19

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 06/13/2022
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 10/20/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 11/12/2021
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/25/2022
Number of Days to Update: 22

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 05/16/2022
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 01/20/2022
Date Data Arrived at EDR: 01/20/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 64

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 01/07/2022
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/29/2021
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 07/29/2021
Date Data Arrived at EDR: 08/24/2021
Date Made Active in Reports: 11/19/2021
Number of Days to Update: 87

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 84

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 02/28/2022
Next Scheduled EDR Contact: 06/13/2022
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 02/28/2022
Next Scheduled EDR Contact: 06/13/2022
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 02/04/2022
Next Scheduled EDR Contact: 05/16/2022
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84
Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 03/28/2022
Next Scheduled EDR Contact: 07/11/2022
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data
Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80
Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 01/24/2022
Next Scheduled EDR Contact: 05/08/2022
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 01/14/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 70

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 01/03/2022
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 23

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 01/04/2022
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 07/26/2021
Date Data Arrived at EDR: 07/27/2021
Date Made Active in Reports: 10/22/2021
Number of Days to Update: 87

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 01/31/2022
Next Scheduled EDR Contact: 05/16/2022
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 02/17/2022
Next Scheduled EDR Contact: 05/30/2022
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 19

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 05/03/2022
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 11/02/2021
Date Data Arrived at EDR: 11/22/2021
Date Made Active in Reports: 02/14/2022
Number of Days to Update: 84

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 02/23/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: Semi-Annually

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 03/21/2022
Date Data Arrived at EDR: 03/22/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 3

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 03/14/2022
Next Scheduled EDR Contact: 06/13/2022
Data Release Frequency: Quarterly

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 05/06/2020
Date Data Arrived at EDR: 05/27/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 78

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 02/24/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 02/24/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 12/14/2021
Date Data Arrived at EDR: 12/15/2021
Date Made Active in Reports: 03/10/2022
Number of Days to Update: 85

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 03/04/2022
Next Scheduled EDR Contact: 06/20/2022
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 11/04/2021
Date Data Arrived at EDR: 11/22/2021
Date Made Active in Reports: 02/25/2022
Number of Days to Update: 95

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 02/28/2022
Next Scheduled EDR Contact: 06/13/2022
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 01/11/2022
Date Made Active in Reports: 02/14/2022
Number of Days to Update: 34

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 01/11/2022
Next Scheduled EDR Contact: 04/25/2022
Data Release Frequency: Varies

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 02/22/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 01/01/2022
Date Data Arrived at EDR: 01/04/2022
Date Made Active in Reports: 01/10/2022
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 01/04/2022
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 11/15/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/01/2022
Number of Days to Update: 78

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 02/17/2022
Next Scheduled EDR Contact: 05/30/2022
Data Release Frequency: Quarterly

NY AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 01/31/2022
Date Data Arrived at EDR: 02/01/2022
Date Made Active in Reports: 02/10/2022
Number of Days to Update: 9

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Annually

NJ AIRS: Emissions Inventory Listing

An emission inventory is an estimate of air pollutant emissions in a given area. Emission inventories are fundamental building blocks used to develop air quality control strategies on a local, regional and national level. Emission inventories are also used to estimate the progress of an air quality program.

Date of Government Version: 11/04/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 01/27/2022
Number of Days to Update: 83

Source: Department of Environmental Protection
Telephone: 609-984-5483
Last EDR Contact: 01/24/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: Varies

NY COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 12/21/2021
Date Data Arrived at EDR: 12/27/2021
Date Made Active in Reports: 03/16/2022
Number of Days to Update: 79

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 03/28/2022
Next Scheduled EDR Contact: 07/11/2022
Data Release Frequency: Quarterly

NJ COAL ASH: Coal Ash Listing

Coal combustion survey ash listing.

Date of Government Version: 05/10/2010
Date Data Arrived at EDR: 05/12/2010
Date Made Active in Reports: 06/28/2010
Number of Days to Update: 47

Source: Department of Environmental Protection
Telephone: 609-984-6985
Last EDR Contact: 01/24/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: Varies

NY DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 12/10/2021
Date Data Arrived at EDR: 12/10/2021
Date Made Active in Reports: 03/01/2022
Number of Days to Update: 81

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 03/07/2022
Next Scheduled EDR Contact: 06/20/2022
Data Release Frequency: Annually

NJ DRYCLEANERS: Drycleaner List
A listing of registered drycleaners.

Date of Government Version: 01/27/2022
Date Data Arrived at EDR: 02/02/2022
Date Made Active in Reports: 02/03/2022
Number of Days to Update: 1
Source: Department of Environmental Protection
Telephone: 609-292-2795
Last EDR Contact: 01/31/2022
Next Scheduled EDR Contact: 05/16/2022
Data Release Frequency: Varies

NY E DESIGNATION: E DESIGNATION SITE LISTING
The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 12/13/2021
Date Data Arrived at EDR: 12/17/2021
Date Made Active in Reports: 12/30/2021
Number of Days to Update: 13
Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 03/15/2022
Next Scheduled EDR Contact: 06/27/2022
Data Release Frequency: Semi-Annually

NJ Financial Assurance: Financial Assurance Information Listing
Financial Assurance information.

Date of Government Version: 11/26/2021
Date Data Arrived at EDR: 11/29/2021
Date Made Active in Reports: 02/14/2022
Number of Days to Update: 77
Source: Department of Environmental Protection
Telephone: 609-341-3121
Last EDR Contact: 02/14/2022
Next Scheduled EDR Contact: 05/30/2022
Data Release Frequency: Semi-Annually

NY Financial Assurance 1: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 12/21/2021
Date Data Arrived at EDR: 12/22/2021
Date Made Active in Reports: 03/16/2022
Number of Days to Update: 84
Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 03/28/2022
Next Scheduled EDR Contact: 07/11/2022
Data Release Frequency: Quarterly

NY Financial Assurance 2: Financial Assurance Information Listing
A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 06/11/2020
Date Data Arrived at EDR: 06/16/2020
Date Made Active in Reports: 09/02/2020
Number of Days to Update: 78
Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 03/07/2022
Next Scheduled EDR Contact: 06/20/2022
Data Release Frequency: Varies

NY HSWDS: Hazardous Substance Waste Disposal Site Inventory
The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 10/29/2021
Date Made Active in Reports: 01/19/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 01/28/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: Quarterly

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 01/07/2022
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Annually

NY SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 11/04/2021
Date Data Arrived at EDR: 11/16/2021
Date Made Active in Reports: 02/04/2022
Number of Days to Update: 80

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: No Update Planned

NJPDES: New Jersey Pollutant Discharge Elimination System Dischargers

The NJPDES contains the names, addresses and other information of all permitted New Jersey Pollutant Discharge Elimination Sytem dischargers.

Date of Government Version: 11/22/2021
Date Data Arrived at EDR: 11/22/2021
Date Made Active in Reports: 02/09/2022
Number of Days to Update: 79

Source: Department of Environmental Protection
Telephone: 609-984-4428
Last EDR Contact: 02/24/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: Varies

NY VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 12/01/2018
Date Data Arrived at EDR: 02/13/2019
Date Made Active in Reports: 06/13/2019
Number of Days to Update: 120

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 02/08/2022
Next Scheduled EDR Contact: 05/23/2022
Data Release Frequency: Varies

NY UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 11/29/2021
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 84

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 03/01/2022
Next Scheduled EDR Contact: 06/13/2022
Data Release Frequency: Quarterly

NJ UIC: Underground Injection Wells Database

A listing of underground injection well locations. The UIC Program is responsible for regulating the construction, operation, permitting, and closure of injection wells that place fluids underground for storage or disposal.

Date of Government Version: 01/09/2009
Date Data Arrived at EDR: 02/25/2009
Date Made Active in Reports: 03/11/2009
Number of Days to Update: 14

Source: Department of Environmental Protection
Telephone: 609-292-0407
Last EDR Contact: 01/24/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: Varies

NY COOLING TOWERS: Registered Cooling Towers

This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 10/05/2021
Date Data Arrived at EDR: 10/11/2021
Date Made Active in Reports: 01/05/2022
Number of Days to Update: 86

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 01/12/2022
Next Scheduled EDR Contact: 04/25/2022
Data Release Frequency: Varies

NYC LEAD: Lead-based Paint Testing Results

The results of the inspections for all classrooms serving students under six in applicable buildings. Identifies all classrooms, whether there was observation of peeling paint, and if there was, standard response protocol was followed.

Date of Government Version: 03/24/2021
Date Data Arrived at EDR: 08/17/2021
Date Made Active in Reports: 08/17/2021
Number of Days to Update: 0

Source: New York City Department of Education
Telephone: 212-374-5141
Last EDR Contact: 02/04/2022
Next Scheduled EDR Contact: 05/16/2022
Data Release Frequency: Varies

NYC LEAD 2: Recent Lead Paint Violations

Pursuant to New York City?s Housing Maintenance Code, the Department of Housing Preservation and Development (HPD) issues violations against conditions in rental dwelling units that have been verified to violate the New York City Housing Maintenance Code (HMC) or the New York State Multiple Dwelling Law (MDL). Violations are issued when an inspection verifies that a violation of the HMC or MDL exists. It is closed when the violation is corrected, as observed/verified by HPD or as certified by the landlord.

Date of Government Version: 11/02/2021
Date Data Arrived at EDR: 11/03/2021
Date Made Active in Reports: 01/24/2022
Number of Days to Update: 82

Source: New York City Department of Housing Preservation & Development
Telephone: 212-863-8200
Last EDR Contact: 02/02/2022
Next Scheduled EDR Contact: 05/16/2022
Data Release Frequency: Varies

PCS INACTIVE: Listing of Inactive PCS Permits

An inactive permit is a facility that has shut down or is no longer discharging.

Date of Government Version: 11/05/2014
Date Data Arrived at EDR: 01/06/2015
Date Made Active in Reports: 05/06/2015
Number of Days to Update: 120

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 12/29/2021
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Semi-Annually

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 07/14/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 55

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 12/29/2021
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Semi-Annually

MINES MRDS: Mineral Resources Data System

Mineral Resources Data System

Date of Government Version: 04/06/2018
Date Data Arrived at EDR: 10/21/2019
Date Made Active in Reports: 10/24/2019
Number of Days to Update: 3

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 02/24/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: Varies

PCS ENF: Enforcement data

No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 12/29/2021
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

NJ RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the New Jersey Department of Environmental Protection in New Jersey.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/24/2013
Number of Days to Update: 176

Source: New Jersey Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

NY RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

NJ RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the New Jersey Department of Environmental Protection in New Jersey.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: New Jersey Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

COUNTY RECORDS

CORTLAND COUNTY:

NY AST - CORTLAND: Cortland County Storage Tank Listing
A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 01/24/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: Quarterly

NY UST - CORTLAND: Cortland County Storage Tank Listing
A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 01/24/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: Quarterly

NASSAU COUNTY:

NY AST - NASSAU: Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 01/24/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: No Update Planned

NY AST NCFM: Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 02/07/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: Varies

NY TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 01/24/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: Varies

NY UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 01/24/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: No Update Planned

NY UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 02/07/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: Varies

ROCKLAND COUNTY:

NY AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 02/25/2022
Next Scheduled EDR Contact: 06/13/2022
Data Release Frequency: No Update Planned

NY UST - ROCKLAND: Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 02/25/2022
Next Scheduled EDR Contact: 06/13/2022
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

NY AST - SUFFOLK: Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 01/24/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: No Update Planned

NY TANKS SUFFOLK: Storage Tank Database
This county is not included in the state?s database. These are facilities that have no tank information in the storage tank database.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 01/24/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: Varies

NY UST - SUFFOLK: Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 01/24/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

NY AST - WESTCHESTER: Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 11/15/2021
Date Data Arrived at EDR: 11/18/2021
Date Made Active in Reports: 02/04/2022
Number of Days to Update: 78

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 01/24/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: Semi-Annually

NY UST - WESTCHESTER: Listing of Storage Tanks
A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 11/15/2021
Date Data Arrived at EDR: 11/18/2021
Date Made Active in Reports: 02/04/2022
Number of Days to Update: 78

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 01/24/2022
Next Scheduled EDR Contact: 05/09/2022
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 11/11/2021
Date Data Arrived at EDR: 11/12/2021
Date Made Active in Reports: 02/01/2022
Number of Days to Update: 81

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 02/11/2022
Next Scheduled EDR Contact: 05/23/2022
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 01/07/2022
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 01/10/2022
Next Scheduled EDR Contact: 04/25/2022
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 02/14/2022
Next Scheduled EDR Contact: 05/30/2022
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 01/10/2022
Next Scheduled EDR Contact: 04/25/2022
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 06/20/2022
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.
Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

Â© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

FULTON
401W16TH ST, 400 W17TH ST, 420W18TH ST, 420W19THST
NEW YORK, NY 10011

TARGET PROPERTY COORDINATES

Latitude (North):	40.743633 - 40ˆ 44’ 37.08’’
Longitude (West):	74.004304 - 74ˆ 0’ 15.49’’
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	584066.1
UTM Y (Meters):	4510564.0
Elevation:	14 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	14317809 JERSEY CITY, NJ
Version Date:	2019
Northeast Map:	14115942 CENTRAL PARK, NY
Version Date:	2019
Southeast Map:	14115940 BROOKLYN, NY
Version Date:	2019
Northwest Map:	14327276 WEEHAWKEN, NJ
Version Date:	2019

EDR’s GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General WNW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 14 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
3604970182F	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
3604970069F	FEMA FIRM Flood data
3604970088F	FEMA FIRM Flood data
3604970201F	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
JERSEY CITY	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Location Relative to TP:	1/2 - 1 Mile NE
Site Name:	MANHATTAN GENERAL MAIL FACILITY
Site EPA ID Number:	NY6180000352
Groundwater Flow Direction:	NOT AVAILABLE.
Inferred Depth to Water:	not available. Saturated layers impacted by salt water intrusion are present in the overburden. It is generally inferred that the depth to the uppermost 'aquifer' is greater than 70 feet at the surface of the bedrock/sediment interface.
Hydraulic Connection:	Detailed hydraulic connection information is not available. Glacial till and outwash deposit sediments overlie the Manhattan Schist, the uppermost bedrock unit at the site. The surface elevation of bedrock decreases to the southwest of the site.
Sole Source Aquifer:	No information about a sole source aquifer is available
Data Quality:	Information is inferred in the CERCLIS investigation report(s)

* ©1996 Site--specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT **GEOLOGIC AGE IDENTIFICATION**

Era:	Paleozoic	Category:	Stratified Sequence
System:	Ordovicias		
Series:	Lower Ordovician and Cambrian carbonate rocks		
Code:	OC *(decoded above as Era, System & Series)*		

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name:	URBAN LAND
Soil Surface Texture:	variable
Hydrologic Group:	Not reported
Soil Drainage Class:	Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel:	Not Reported
Depth to Bedrock Min:	> 10 inches
Depth to Bedrock Max:	> 10 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	USGS40000830960	1/8 - 1/4 Mile SSW
A2	USGS40000830982	1/4 - 1/2 Mile SW
B3	USGS40000830930	1/4 - 1/2 Mile South
B4	USGS40000830932	1/4 - 1/2 Mile South
B5	USGS40000830931	1/4 - 1/2 Mile South
6	USGS40000830929	1/4 - 1/2 Mile SSE
7	USGS40000831406	1/4 - 1/2 Mile North
8	USGS40000830876	1/4 - 1/2 Mile SSW
9	USGS40000831419	1/4 - 1/2 Mile North
C10	USGS40000830855	1/4 - 1/2 Mile SSW
C11	USGS40000830815	1/2 - 1 Mile SSW
14	USGS40000831497	1/2 - 1 Mile NNE
15	USGS40000831418	1/2 - 1 Mile NE
16	USGS40000831552	1/2 - 1 Mile North
17	USGS40000831335	1/2 - 1 Mile ENE
E18	USGS40000830493	1/2 - 1 Mile South
30	USGS40000831625	1/2 - 1 Mile NNE
G31	USGS40000830392	1/2 - 1 Mile SSW
G32	USGS40000830393	1/2 - 1 Mile SSW
G33	USGS40000830394	1/2 - 1 Mile SSW
34	USGS40000831078	1/2 - 1 Mile East
35	USGS40000830321	1/2 - 1 Mile South
36	USGS40000831703	1/2 - 1 Mile NNE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
D12	NYWS40000055383	1/2 - 1 Mile SE
D13	NYWS40000055384	1/2 - 1 Mile SE
F19	NYWS40000113574	1/2 - 1 Mile East
F20	NYWS40000101312	1/2 - 1 Mile East
F22	NYREG1000008647	1/2 - 1 Mile East
F23	NYREG1000008646	1/2 - 1 Mile East
F24	NYWS40000069123	1/2 - 1 Mile East
F25	NYWS40000066015	1/2 - 1 Mile East
F26	NYWS40000056525	1/2 - 1 Mile East
F27	NYWS40000056571	1/2 - 1 Mile East
F28	NYWS40000113447	1/2 - 1 Mile East
29	NYREG1000005759	1/2 - 1 Mile ESE

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	NYOG10000040233	0 - 1/8 Mile NNE

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A2	NYOG10000040236	0 - 1/8 Mile NNE
A3	NYOG10000040235	0 - 1/8 Mile NNE
A4	NYOG10000040234	0 - 1/8 Mile NE
A5	NYOG10000040237	0 - 1/8 Mile NNE
A6	NYOG10000040232	0 - 1/8 Mile NE
A7	NYOG10000040238	0 - 1/8 Mile North
8	NYOG10000040221	1/8 - 1/4 Mile SSE
B9	NYOG10000040239	1/8 - 1/4 Mile North
A10	NYOG10000040231	1/8 - 1/4 Mile NE
A11	NYOG10000040224	1/8 - 1/4 Mile North
A12	NYOG10000040230	1/8 - 1/4 Mile NE
A13	NYOG10000040229	1/8 - 1/4 Mile NE
A14	NYOG10000040227	1/8 - 1/4 Mile NNE
A15	NYOG10000040228	1/8 - 1/4 Mile NNE
A16	NYOG10000040226	1/8 - 1/4 Mile NNE
B17	NYOG10000040240	1/8 - 1/4 Mile NNW
A18	NYOG10000040225	1/8 - 1/4 Mile North
B19	NYOG10000040241	1/8 - 1/4 Mile NNW
B20	NYOG10000040242	1/8 - 1/4 Mile NNW
B21	NYOG10000040243	1/8 - 1/4 Mile NNW
B22	NYOG10000040223	1/8 - 1/4 Mile North
B23	NYOG10000040244	1/8 - 1/4 Mile NNW
B24	NYOG10000040222	1/8 - 1/4 Mile NNW
C25	NYOG10000040218	1/8 - 1/4 Mile SW
C26	NYOG10000040219	1/8 - 1/4 Mile SW
C27	NYOG10000040217	1/8 - 1/4 Mile SW
D28	NYOG10000040268	1/4 - 1/2 Mile SSW
D29	NYOG10000040267	1/4 - 1/2 Mile SSW
D30	NYOG10000040158	1/4 - 1/2 Mile South
D31	NYOG10000040157	1/4 - 1/2 Mile South
32	NYOG10000040269	1/4 - 1/2 Mile North
33	NYOG10000040266	1/4 - 1/2 Mile South
E34	NYOG10000040254	1/2 - 1 Mile SE
E35	NYOG10000040255	1/2 - 1 Mile SE
36	NYOG10000040303	1/2 - 1 Mile South
F37	NYOG10000040293	1/2 - 1 Mile East
F38	NYOG10000040292	1/2 - 1 Mile East
39	NYOG10000040132	1/2 - 1 Mile NE
40	NYOG10000040278	1/2 - 1 Mile South
41	NYOG10000040133	1/2 - 1 Mile ENE
42	NYOG10000040156	1/2 - 1 Mile South
43	NYOG10000040270	1/2 - 1 Mile NNE
44	NYOG10000040143	1/2 - 1 Mile East
45	NYOG10000040271	1/2 - 1 Mile NNE

PHYSICAL SETTING SOURCE MAP - 6920743.2s



0 1/4 1/2 1 Miles

- County Boundary
- Major Roads
- Contour Lines
- Airports
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	Fulton	CLIENT:	Hillmann Environmental Co.
ADDRESS:	401w16th St, 400 W17th St, 420w18th St, 420w19thst New York NY 10011	CONTACT:	Joanne Bedkowski
LAT/LONG:	40.743633 / 74.004304	INQUIRY #:	6920743.2s
		DATE:	March 31, 2022 6:44 am

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A1
SSW
1/8 - 1/4 Mile
Higher

FED USGS **USGS40000830960**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 249. 1	Type:	Well
Description:	W13ST-W	HUC:	02030101
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Pleistocene Series	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	30.3
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

A2
SW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000830982**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 96	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	33
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

B3
South
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000830930**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 245. 1	Type:	Well
Description:	GANS-A	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	590	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

B4
South
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000830932**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 247. 1	Type:	Well

Description:	GANS-B	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	590	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

B5
South **FED USGS** **USGS40000830931**
1/4 - 1/2 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 236. 1	Type:	Well
Description:	GANS-GEO-01/W	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	82.5	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

6
SSE **FED USGS** **USGS40000830929**
1/4 - 1/2 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 117	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	39
Well Depth Units:	ft	Well Hole Depth:	40
Well Hole Depth Units:	ft		

7
North **FED USGS** **USGS40000831406**
1/4 - 1/2 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 154	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	63
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

8
SSW
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000830876**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 33	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	40
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

9
North
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000831419**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 176. 1	Type:	Well
Description:	WEST 26TH STREET	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	19990902
Well Depth:	596.3	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	4	Level reading date:	2002-10-09
Feet below surface:	Not Reported	Feet to sea level:	3.54
Note:	Not Reported		
Level reading date:	2002-06-25	Feet below surface:	Not Reported
Feet to sea level:	3.48	Note:	Not Reported
Level reading date:	2002-04-03	Feet below surface:	Not Reported
Feet to sea level:	4.09	Note:	Not Reported
Level reading date:	2002-01-09	Feet below surface:	Not Reported
Feet to sea level:	4.00	Note:	Not Reported

C10
SSW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000830855**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 166	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Pleistocene Series	Aquifer Type:	Not Reported

Construction Date:	Not Reported	Well Depth:	40
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

C11
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000830815**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 62	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	90
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

D12
SE
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000055383**

DEC Well #:	NY309	Well Depth (ft):	640
Bedrock Depth (ft):	25	Groundwater Depth (ft):	20
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	12
Casing 1 Length (ft):	25	Casing 2 Diameter (in):	8
Casing 2 Length (ft):	78	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	100
Well Purpose:	Geothermal	Driller Registration #:	NYRD10461

D13
SE
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000055384**

DEC Well #:	NY310	Well Depth (ft):	960
Bedrock Depth (ft):	25	Groundwater Depth (ft):	0
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	12
Casing 1 Length (ft):	25	Casing 2 Diameter (in):	8
Casing 2 Length (ft):	76	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	3
Well Purpose:	Geothermal	Driller Registration #:	NYRD10461

14
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000831497**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 239. 1	Type:	Well
Description:	26B-CS-BW	HUC:	02030101

Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Pleistocene Series	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	41.9
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

15
NE
1/2 - 1 Mile
Higher

FED USGS **USGS40000831418**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 227. 1	Type:	Well
Description:	WEST 30 ST-A	HUC:	02030101
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	New England crystalline-rock aquifers		
Formation Type:	Basement Complex	Aquifer Type:	Not Reported
Construction Date:	20031114	Well Depth:	192
Well Depth Units:	ft	Well Hole Depth:	600.5
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	13	Level reading date:	2005-02-09
Feet below surface:	Not Reported	Feet to sea level:	9.03
Note:	Not Reported		

Level reading date:	2004-11-29	Feet below surface:	Not Reported
Feet to sea level:	9.18	Note:	Not Reported
Level reading date:	2004-11-10	Feet below surface:	Not Reported
Feet to sea level:	9.16	Note:	Not Reported
Level reading date:	2004-07-21	Feet below surface:	Not Reported
Feet to sea level:	9.80	Note:	Not Reported
Level reading date:	2004-06-28	Feet below surface:	Not Reported
Feet to sea level:	9.69	Note:	Not Reported
Level reading date:	2004-06-16	Feet below surface:	Not Reported
Feet to sea level:	9.54	Note:	Not Reported
Level reading date:	2004-04-21	Feet below surface:	Not Reported
Feet to sea level:	9.82	Note:	Not Reported
Level reading date:	2004-04-12	Feet below surface:	Not Reported
Feet to sea level:	9.75	Note:	Not Reported
Level reading date:	2004-03-15	Feet below surface:	Not Reported
Feet to sea level:	9.74	Note:	Not Reported
Level reading date:	2004-03-03	Feet below surface:	Not Reported
Feet to sea level:	10.04	Note:	Not Reported
Level reading date:	2004-03-03	Feet below surface:	Not Reported
Feet to sea level:	9.64	Note:	Not Reported
Level reading date:	2004-02-18	Feet below surface:	Not Reported

Feet to sea level:	10.12	Note:	Not Reported
Level reading date:	2004-01-07	Feet below surface:	Not Reported
Feet to sea level:	10.09	Note:	Not Reported

16
North
1/2 - 1 Mile
Lower

FED USGS **USGS40000831552**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 83	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand and Gravel	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	25
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

17
ENE
1/2 - 1 Mile
Higher

FED USGS **USGS40000831335**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 240. 1	Type:	Well
Description:	W30ST-C	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	600	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

E18
South
1/2 - 1 Mile
Higher

FED USGS **USGS40000830493**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 199	Type:	Well
Description:	GROVE STREET-A	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	644.77	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

F19
East
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000113574**

DEC Well #:	U9238	Well Depth (ft):	205
Bedrock Depth (ft):	19	Groundwater Depth (ft):	22
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	40	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	10
Well Purpose:	Domestic	Driller Registration #:	NYRD10972

F20
East
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000101312**

DEC Well #:	SV4594	Well Depth (ft):	150
Bedrock Depth (ft):	-999	Groundwater Depth (ft):	38
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	140	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	15
Well Purpose:	Domestic	Driller Registration #:	NYRD10972

E21
South
1/2 - 1 Mile
Higher

Site ID:	16311
Groundwater Flow:	NOT REPORTED
Water Table Depth:	4.96-5.92
Date:	10/01/92

AQUIFLOW **4531**

F22
East
1/2 - 1 Mile
Higher

NY WELLS **NYREG1000008647**

Well Number:	N014096D	Owner:	Lockheed Martin Corporation
Well Depth:	445	Diameter:	20
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

F23
East
1/2 - 1 Mile
Higher

NY WELLS **NYREG1000008646**

Well Number:	N014096D	Owner:	Lockheed Martin Corporation
Well Depth:	445	Diameter:	20
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

F24
East
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000069123**

DEC Well #:	OE4403	Well Depth (ft):	160
Bedrock Depth (ft):	20	Groundwater Depth (ft):	0
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	20	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	1.5
Well Purpose:	Domestic	Driller Registration #:	NYRD10013

F25
East
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000066015**

DEC Well #:	OD2883	Well Depth (ft):	60
Bedrock Depth (ft):	20	Groundwater Depth (ft):	15
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	20	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	30
Well Purpose:	Domestic	Driller Registration #:	NYRD10230

F26
East
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000056525**

DEC Well #:	O11213	Well Depth (ft):	145
Bedrock Depth (ft):	6	Groundwater Depth (ft):	30
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	38	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	30
Well Purpose:	Domestic	Driller Registration #:	NYRD10972

F27
East
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000056571**

DEC Well #:	O11263	Well Depth (ft):	445
Bedrock Depth (ft):	68	Groundwater Depth (ft):	35
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	80	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	3
Well Purpose:	Domestic	Driller Registration #:	NYRD10972

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

F28
East
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000113447**

DEC Well #:	U9104	Well Depth (ft):	285
Bedrock Depth (ft):	23	Groundwater Depth (ft):	23
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	40	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	7
Well Purpose:	Domestic	Driller Registration #:	NYRD10972

29
ESE
1/2 - 1 Mile
Higher

NY WELLS **NYREG1000005759**

Well Number:	N007623D	Owner:	S. L. Hersch - Ruby Lane Stores
Well Depth:	19	Diameter:	0
Casing Length:	0	Screen Diameter:	1
Screen Length:	4		

30
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000831625**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 219	Type:	Well
Description:	WEST 34 ST-B	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	625.7	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

G31
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000830392**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 130	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	35
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G32
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000830393**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 131	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	35
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

G33
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000830394**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 132	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	35
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

34
East
1/2 - 1 Mile
Higher

FED USGS **USGS40000831078**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 161. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	23	Well Depth Units:	ft
Well Hole Depth:	23	Well Hole Depth Units:	ft

35
South
1/2 - 1 Mile
Higher

FED USGS **USGS40000830321**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 40	Type:	Well

Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	52
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

36
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000831703**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	NY 220	Type:	Well
Description:	WEST 37 ST-A	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	651.4	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

1G
South
1/2 - 1 Mile
Lower

Site ID:	16311
Groundwater Flow:	NOT REPORTED
Water Table Depth:	4.96-5.92
Date:	10/01/92

AQUIFLOW **4531**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

A1
NNE **OIL_GAS** **NYOG10000040233**
0 - 1/8 Mile

API #:	31061237080000	Well Name:	Geothermal 11
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Refunded Fee	Well Type:	Not Listed
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	Not Reported	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	1500
Measured Length:	1500		

A2
NNE **OIL_GAS** **NYOG10000040236**
0 - 1/8 Mile

API #:	31061237110000	Well Name:	Geothermal 14
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Expired Permit	Well Type:	Not Listed
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	Not Reported	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	0
Measured Length:	0		

A3
NNE **OIL_GAS** **NYOG10000040235**
0 - 1/8 Mile

API #:	31061237100000	Well Name:	Geothermal 13
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Expired Permit	Well Type:	Not Listed
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	Not Reported	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	0
Measured Length:	0		

A4
NE **OIL_GAS** **NYOG10000040234**
0 - 1/8 Mile

API #:	31061237090000	Well Name:	Geothermal 12
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Expired Permit	Well Type:	Not Listed
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	Not Reported	Plug Date:	Not Reported

Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	0
Measured Length:	0		

A5
NNE **OIL_GAS** **NYOG10000040237**
0 - 1/8 Mile

API #:	31061237120000	Well Name:	Geothermal 15
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Cancelled	Well Type:	Not Listed
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	Not Reported	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	0
Measured Length:	0		

A6
NE **OIL_GAS** **NYOG10000040232**
0 - 1/8 Mile

API #:	31061237080000	Well Name:	Geothermal 11
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Expired Permit	Well Type:	Not Listed
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	Not Reported	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	0
Measured Length:	0		

A7
North **OIL_GAS** **NYOG10000040238**
0 - 1/8 Mile

API #:	31061237130000	Well Name:	Geothermal 16
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Cancelled	Well Type:	Not Listed
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	Not Reported	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	0
Measured Length:	0		

Map ID
Direction
Distance

Database EDR ID Number

8
SSE **OIL_GAS** **NYOG10000040221**
1/8 - 1/4 Mile

API #:	31061236890000	Well Name:	Geothermal 1
Owner:	Chelsea Ventura LLC	Operator:	2304
Well Status:	Active	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	22-SEP-06	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	1150
Measured Length:	1150		

B9
North **OIL_GAS** **NYOG10000040239**
1/8 - 1/4 Mile

API #:	31061237140000	Well Name:	Geothermal 17
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Cancelled	Well Type:	Not Listed
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	Not Reported	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	0
Measured Length:	0		

A10
NE **OIL_GAS** **NYOG10000040231**
1/8 - 1/4 Mile

API #:	31061237070000	Well Name:	Geothermal 10
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Expired Permit	Well Type:	Not Listed
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	Not Reported	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	0
Measured Length:	0		

A11
North **OIL_GAS** **NYOG10000040224**
1/8 - 1/4 Mile

API #:	31061237000000	Well Name:	Geothermal 3
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Cancelled	Well Type:	Not Listed
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	Not Reported	Plug Date:	Not Reported

Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	0
Measured Length:	0		

A12
NE
1/8 - 1/4 Mile

OIL_GAS **NYOG10000040230**

API #:	31061237060000	Well Name:	Geothermal 9
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Expired Permit	Well Type:	Not Listed
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	Not Reported	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	0
Measured Length:	0		

A13
NE
1/8 - 1/4 Mile

OIL_GAS **NYOG10000040229**

API #:	31061237050000	Well Name:	Geothermal 8
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Expired Permit	Well Type:	Not Listed
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	Not Reported	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	0
Measured Length:	0		

A14
NNE
1/8 - 1/4 Mile

OIL_GAS **NYOG10000040227**

API #:	31061237030000	Well Name:	Geothermal 6
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Active	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	12-FEB-08	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	1510
Measured Length:	1510		

Map ID
Direction
Distance

Database EDR ID Number

A15
NNE
1/8 - 1/4 Mile

OIL_GAS **NYOG10000040228**

API #:	31061237040000	Well Name:	Geothermal 7
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Expired Permit	Well Type:	Not Listed
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	Not Reported	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	0
Measured Length:	0		

A16
NNE
1/8 - 1/4 Mile

OIL_GAS **NYOG10000040226**

API #:	31061237020000	Well Name:	Geothermal 5
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Active	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	12-FEB-08	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	1510
Measured Length:	1510		

B17
NNW
1/8 - 1/4 Mile

OIL_GAS **NYOG10000040240**

API #:	31061237150000	Well Name:	Geothermal 18
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Cancelled	Well Type:	Not Listed
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	Not Reported	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	0
Measured Length:	0		

A18
North
1/8 - 1/4 Mile

OIL_GAS **NYOG10000040225**

API #:	31061237010000	Well Name:	Geothermal 4
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Cancelled	Well Type:	Not Listed
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	Not Reported	Plug Date:	Not Reported

Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	0
Measured Length:	0		

B19
NNW
1/8 - 1/4 Mile

OIL_GAS **NYOG10000040241**

API #:	31061237160000	Well Name:	Geothermal 19
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Active	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	29-APR-08	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	NA - Geoexchange
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	1460
Measured Length:	1460		

B20
NNW
1/8 - 1/4 Mile

OIL_GAS **NYOG10000040242**

API #:	31061237170000	Well Name:	Geothermal 20
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Active	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	29-APR-08	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	1510
Measured Length:	1510		

B21
NNW
1/8 - 1/4 Mile

OIL_GAS **NYOG10000040243**

API #:	31061237180000	Well Name:	Geothermal 21
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Active	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	30-MAY-08	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	1800
Measured Length:	1800		

Map ID
Direction
Distance

Database EDR ID Number

B22
North
1/8 - 1/4 Mile

OIL_GAS **NYOG10000040223**

API #:	31061236990000	Well Name:	Geothermal 2
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Cancelled	Well Type:	Not Listed
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	Not Reported	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	0
Measured Length:	0		

B23
NNW
1/8 - 1/4 Mile

OIL_GAS **NYOG10000040244**

API #:	31061237190000	Well Name:	Geothermal 22
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Active	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	30-MAY-08	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	NA - Geoexchange
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	1510
Measured Length:	1510		

B24
NNW
1/8 - 1/4 Mile

OIL_GAS **NYOG10000040222**

API #:	31061236980000	Well Name:	Geothermal 1
Owner:	General Theological Seminary	Operator:	2327
Well Status:	Active	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	30-MAY-08	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	NA - Geoexchange
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	1510
Measured Length:	1510		

C25
SW
1/8 - 1/4 Mile

OIL_GAS **NYOG10000040218**

API #:	31061236760000	Well Name:	GW-2
Owner:	Diane Von Furstenberg Studio L.P.	Operator:	2293
Well Status:	Active	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	25-JAN-07	Plug Date:	Not Reported

Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	1500
Measured Length:	1500		

C26
SW
1/8 - 1/4 Mile

OIL_GAS **NYOG10000040219**

API #:	31061236770000	Well Name:	GW-3
Owner:	Diane Von Furstenberg Studio L.P.	Operator:	2293
Well Status:	Active	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	26-JAN-07	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	1350
Measured Length:	1350		

C27
SW
1/8 - 1/4 Mile

OIL_GAS **NYOG10000040217**

API #:	31061236750000	Well Name:	GW-1
Owner:	Diane Von Furstenberg Studio L.P.	Operator:	2293
Well Status:	Active	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	26-JAN-07	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	1300
Measured Length:	1300		

D28
SSW
1/4 - 1/2 Mile

OIL_GAS **NYOG10000040268**

API #:	31061237390000	Well Name:	W13 St - C
Owner:	New York City Dept. of Environmental Protection		
Operator:	2127	Well Status:	Plugged and Abandoned
Well Type:	Stratigraphic	Permit Date:	Not Reported
Drill Date:	Not Reported	Completion Date:	30-JUL-96
Plug Date:	Not Reported	Field Name:	North Collins
Formation:	Manhattan Schist	Borehole Slant:	Vertical
State Owned Lease:	NA	Proposed Depth:	0
True Depth:	577	Measured Length:	577

Map ID
Direction
Distance

Database EDR ID Number

D29
SSW
1/4 - 1/2 Mile

OIL_GAS **NYOG10000040267**

API #:	31061237380000	Well Name:	W13 St - B
Owner:	New York City Dept. of Environmental Protection		
Operator:	2127	Well Status:	Plugged and Abandoned
Well Type:	Stratigraphic	Permit Date:	Not Reported
Drill Date:	Not Reported	Completion Date:	10-JUL-96
Plug Date:	Not Reported	Field Name:	Not Applicable
Formation:	Manhattan Schist	Borehole Slant:	Vertical
State Owned Lease:	NA	Proposed Depth:	0
True Depth:	573	Measured Length:	573

D30
South
1/4 - 1/2 Mile

OIL_GAS **NYOG10000040158**

API #:	31061210820000	Well Name:	Gans St - B
Owner:	New York City Dept. of Environmental Protection		
Operator:	2127	Well Status:	Plugged and Abandoned
Well Type:	Stratigraphic	Permit Date:	Not Reported
Drill Date:	Not Reported	Completion Date:	13-SEP-04
Plug Date:	Not Reported	Field Name:	Not Applicable
Formation:	Not Applicable	Borehole Slant:	Vertical
State Owned Lease:	NA	Proposed Depth:	590
True Depth:	590	Measured Length:	590

D31
South
1/4 - 1/2 Mile

OIL_GAS **NYOG10000040157**

API #:	31061210810000	Well Name:	Gans St - A
Owner:	New York City Dept. of Environmental Protection		
Operator:	2127	Well Status:	Plugged and Abandoned
Well Type:	Stratigraphic	Permit Date:	Not Reported
Drill Date:	Not Reported	Completion Date:	26-AUG-04
Plug Date:	Not Reported	Field Name:	Not Applicable
Formation:	Not Applicable	Borehole Slant:	Vertical
State Owned Lease:	NA	Proposed Depth:	590
True Depth:	590	Measured Length:	590

32
North
1/4 - 1/2 Mile

OIL_GAS **NYOG10000040269**

API #:	31061237400000	Well Name:	W26 St - A
Owner:	New York City Dept. of Environmental Protection		
Operator:	2127	Well Status:	Plugged and Abandoned
Well Type:	Stratigraphic	Permit Date:	Not Reported
Drill Date:	Not Reported	Completion Date:	01-OCT-99

Plug Date:	Not Reported	Field Name:	Not Applicable
Formation:	Fordham Gneiss	Borehole Slant:	Vertical
State Owned Lease:	NA	Proposed Depth:	0
True Depth:	596	Measured Length:	596

33
South
1/4 - 1/2 Mile

OIL_GAS **NYOG10000040266**

API #:	31061237370000	Well Name:	W12 St - A
Owner:	New York City Dept. of Environmental Protection		
Operator:	2127	Well Status:	Plugged and Abandoned
Well Type:	Stratigraphic	Permit Date:	Not Reported
Drill Date:	Not Reported	Completion Date:	16-JUL-97
Plug Date:	Not Reported	Field Name:	Not Applicable
Formation:	Manhattan Schist	Borehole Slant:	Vertical
State Owned Lease:	NA	Proposed Depth:	0
True Depth:	576	Measured Length:	576

E34
SE
1/2 - 1 Mile

OIL_GAS **NYOG10000040254**

API #:	31061237260000	Well Name:	Valhalla 1
Owner:	Terrapin Industries LLC	Operator:	2356
Well Status:	Inactive	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	12-MAR-07	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Unknown
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	800	True Depth:	640
Measured Length:	640		

E35
SE
1/2 - 1 Mile

OIL_GAS **NYOG10000040255**

API #:	31061237270000	Well Name:	Valhalla 2
Owner:	Terrapin Industries LLC	Operator:	2356
Well Status:	Inactive	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	16-MAR-07	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Unknown
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	800	True Depth:	960
Measured Length:	960		

Map ID
Direction
Distance

Database EDR ID Number

36
South
1/2 - 1 Mile

OIL_GAS **NYOG10000040303**

API #:	31061237870000	Well Name:	1
Owner:	Perry Street Associates LLC	Operator:	2459
Well Status:	Cancelled	Well Type:	Not Listed
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	Not Reported	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	0
Measured Length:	0		

F37
East
1/2 - 1 Mile

OIL_GAS **NYOG10000040293**

API #:	31061237650000	Well Name:	Geothermal 2
Owner:	Ancona Jack	Operator:	2426
Well Status:	Temporarily Abandoned	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	23-JAN-09	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Manhattan Schist
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	1100
Measured Length:	1100		

F38
East
1/2 - 1 Mile

OIL_GAS **NYOG10000040292**

API #:	31061237640000	Well Name:	Geothermal 1
Owner:	Ancona Jack	Operator:	2426
Well Status:	Temporarily Abandoned	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	23-JAN-09	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Manhattan Schist
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	1120
Measured Length:	1120		

39
NE
1/2 - 1 Mile

OIL_GAS **NYOG10000040132**

API #:	31061210540000	Well Name:	W. 30 St. - A
Owner:	U.S. Geological Survey	Operator:	2370
Well Status:	Active	Well Type:	Stratigraphic
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	14-NOV-03	Plug Date:	Not Reported

Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	550	True Depth:	600
Measured Length:	600		

40
South
1/2 - 1 Mile

OIL_GAS **NYOG10000040278**

API #:	31061237490000	Well Name:	Charles - 1
Owner:	New York City Dept. of Environmental Protection		
Operator:	2127	Well Status:	Plugged and Abandoned
Well Type:	Stratigraphic	Permit Date:	Not Reported
Drill Date:	Not Reported	Completion Date:	11-AUG-97
Plug Date:	Not Reported	Field Name:	Not Applicable
Formation:	Manhattan Schist	Borehole Slant:	Vertical
State Owned Lease:	NA	Proposed Depth:	0
True Depth:	576	Measured Length:	576

41
ENE
1/2 - 1 Mile

OIL_GAS **NYOG10000040133**

API #:	31061210550000	Well Name:	W. 30 St. - C
Owner:	New York City Dept. of Environmental Protection		
Operator:	2127	Well Status:	Plugged and Abandoned
Well Type:	Stratigraphic	Permit Date:	Not Reported
Drill Date:	Not Reported	Completion Date:	22-APR-04
Plug Date:	Not Reported	Field Name:	Not Applicable
Formation:	Not Applicable	Borehole Slant:	Vertical
State Owned Lease:	NA	Proposed Depth:	600
True Depth:	600	Measured Length:	600

42
South
1/2 - 1 Mile

OIL_GAS **NYOG10000040156**

API #:	31061210800000	Well Name:	Grove St - A
Owner:	New York City Dept. of Environmental Protection		
Operator:	2127	Well Status:	Plugged and Abandoned
Well Type:	Stratigraphic	Permit Date:	Not Reported
Drill Date:	Not Reported	Completion Date:	19-MAY-01
Plug Date:	Not Reported	Field Name:	Not Applicable
Formation:	Not Applicable	Borehole Slant:	Vertical
State Owned Lease:	NA	Proposed Depth:	645
True Depth:	0	Measured Length:	0

Map ID
Direction
Distance

Database EDR ID Number

43
NNE
1/2 - 1 Mile

OIL_GAS **NYOG10000040270**

API #:	31061237410000	Well Name:	W34 St - B
Owner:	New York City Dept. of Environmental Protection		
Operator:	2127	Well Status:	Plugged and Abandoned
Well Type:	Stratigraphic	Permit Date:	Not Reported
Drill Date:	Not Reported	Completion Date:	13-OCT-98
Plug Date:	Not Reported	Field Name:	Not Applicable
Formation:	Not Applicable	Borehole Slant:	Vertical
State Owned Lease:	NA	Proposed Depth:	0
True Depth:	626	Measured Length:	626

44
East
1/2 - 1 Mile

OIL_GAS **NYOG10000040143**

API #:	31061210650000	Well Name:	W. 30 St. - B
Owner:	New York City Dept. of Environmental Protection		
Operator:	2127	Well Status:	Plugged and Abandoned
Well Type:	Stratigraphic	Permit Date:	Not Reported
Drill Date:	Not Reported	Completion Date:	Not Reported
Plug Date:	Not Reported	Field Name:	Not Applicable
Formation:	Not Applicable	Borehole Slant:	Vertical
State Owned Lease:	NA	Proposed Depth:	600
True Depth:	0	Measured Length:	0

45
NNE
1/2 - 1 Mile

OIL_GAS **NYOG10000040271**

API #:	31061237420000	Well Name:	W37 St - A
Owner:	New York City Dept. of Environmental Protection		
Operator:	2127	Well Status:	Plugged and Abandoned
Well Type:	Stratigraphic	Permit Date:	Not Reported
Drill Date:	Not Reported	Completion Date:	16-NOV-98
Plug Date:	Not Reported	Field Name:	Not Applicable
Formation:	Manhattan Schist	Borehole Slant:	Vertical
State Owned Lease:	NA	Proposed Depth:	0
True Depth:	651	Measured Length:	651

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: NY Radon

Radon Test Results

County	Town	Num Tests	Avg Result	Geo Mean	Max Result
NEW YORK	NYC (BRONX)	91	1.59	0.85	16
NEW YORK	NYC (KINGS)	416	1.93	1.19	28.2
NEW YORK	NYC (NEW YORK)	108	2.15	0.98	49.5
NEW YORK	NYC (QUEENS)	501	1.24	0.77	23.8
NEW YORK	NYC (RICHMOND)	225	1.44	0.76	14.1

Federal EPA Radon Zone for NEW YORK County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for NEW YORK COUNTY, NY

Number of sites tested: 31

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.690 pCi/L	90%	10%	0%
Basement	1.490 pCi/L	81%	19%	0%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

Â© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX F

OTHER DOCUMENTS

430 WEST 17 STREET, Manhattan 10011
Residential: Multi-Family Elevator Building
Owner: NYC HOUSING AUTHORITY
Block: 714 Lot: 31
Property Characteristics:

- Lot Area: 80,408 sq ft (500' x 184')
- # of Buildings: 4 Year built: 1963
- Building frontage: 152' (Building frontage along the street measured in feet.)
- # of floors: 7 Building Area: 298,470 sq ft
- Total Units: 375 Residential Units: 375
- Primary zoning: R8 Commercial Overlay: C2-5
- Floor Area Ratio: 3.71
  Max. Allowable Residential FAR: 6.02
  Max. Allowable Commercial FAR: 0
  Max. Allowable Facility FAR: 6.5
  The Maximum Allowable Floor Area Ratios are exclusive of bonuses for plazas, plaza-connected open areas, arcades or other amenities.
  FAR may depend on street widths or other characteristics. Contact City Planning Dept. for latest information.

427 WEST 17 STREET, Manhattan 10011
Residential: Multi-Family Elevator Building
Owner: NYC HOUSING AUTHORITY
Block: 715 Lot: 10
Property Characteristics:

- Lot Area: 89,700 sq ft (575' x 184')
- # of Buildings: 4 Year built: 1965
- Building frontage: 160.83' (Building frontage along the street measured in feet.)
- # of floors: 7 Building Area: 253,070 sq ft
- Total Units: 272 Residential Units: 272
- Primary zoning: R8 Commercial Overlay: C2-5
- Floor Area Ratio: 2.82
  Max. Allowable Residential FAR: 6.02
  Max. Allowable Commercial FAR: 0
  Max. Allowable Facility FAR: 6.5
  The Maximum Allowable Floor Area Ratios are exclusive of bonuses for plazas, plaza-connected open areas, arcades or other amenities.
  FAR may depend on street widths or other characteristics. Contact City Planning Dept. for latest information.

401 WEST 19 STREET, Manhattan 10011
Residential: Multi-Family Elevator Building
Owner: NYC HOUSING AUTHORITY
Block: 717 Lot: 19
Property Characteristics:

- Lot Area: 29,275 sq ft (375' x 78.83')
- # of Buildings: 1 Year built: 1965
- Building frontage: 160' (Building frontage along the street measured in feet.)
- # of floors: 7 Building Area: 45,420 sq ft
- Total Units: 36 Residential Units: 36
- Primary zoning: R8 Commercial Overlay: C2-5
- Floor Area Ratio: 1.55
  Max. Allowable Residential FAR: 6.02
  Max. Allowable Commercial FAR: 0
  Max. Allowable Facility FAR: 6.5
  The Maximum Allowable Floor Area Ratios are exclusive of bonuses for plazas, plaza-connected open areas, arcades or other amenities.
  FAR may depend on street widths or other characteristics. Contact City Planning Dept. for latest information.

401 WEST 18 STREET, Manhattan 10011
Residential: Multi-Family Elevator Building
Owner: NYC HOUSING AUTHORITY
Block: 716 Lot: 17
Property Characteristics:

- Lot Area: 62,560 sq ft (330' x 184')
- # of Buildings: 3 Year built: 1963
- Building frontage: 160' (Building frontage along the street measured in feet.)
- # of floors: 7 Building Area: 253,070 sq ft
- Total Units: 291 Residential Units: 291
- Primary zoning: R8 Commercial Overlay: C2-5
- Floor Area Ratio: 4.05
  Max. Allowable Residential FAR: 6.02
  Max. Allowable Commercial FAR: 0
  Max. Allowable Facility FAR: 6.5
  The Maximum Allowable Floor Area Ratios are exclusive of bonuses for plazas, plaza-connected open areas, arcades or other amenities.
  FAR may depend on street widths or other characteristics. Contact City Planning Dept. for latest information.

Open RECORDS

(/)

Request a Record

Please make your request specific so you receive the fastest service. After you submit a FOIL request you will receive a confirmation number so you can track the status of the response. The agency will notify you about how much time is required to respond to your request.

Category (optional)

Selecting a category helps clarify which agency will receive the request by listing agencies grouped by categories.

Environment

Agency (required)

Select the agency that will handle your request.

Department of Environmental Protection (DEP)

Request Title (required)

FOIL Request

77 characters remaining

Note: The agency, category, and title of your request will be visible to the public. Do not enter personal information here.

Ex: Queens Blvd Roadwork Permit.

Request Description (required)

Records regarding above and underground storage tanks, permits and/or violations, spills, hazardous material and any other information of environmental concern as we are conducting a Phase I Environmental Site Assessment. (My ref#: Z3-4898), Time frame: 01/01/1963 - 03/28/2022 - Fulton - Various addresses (see attached address listing), Manhattan, NY 10011

4638 characters remaining

Note: The request details you write here will not be visible to the public. However, the agency may post a description of the records provided.

Ex: Roadwork permits for work done in on Queens Blvd. between 40th and 45th streets, Borough of Queens, in September and October 2017.

Upload File (optional, must be less than 20 Mb)

Clear File

Fulton.pdf

Personal Information

First and last name fields are required. The Email field is optional but recommended. If you do not provide an email you must enter either a phone number, fax number, or address in the Alternate Contact Information section.

This information will not be publicly viewable on this site. You must provide contact information so that the agency can respond to your request for records.

First Name (required)

Joanne

25 characters remaining

Last Name (required)

Bedkowski

55 characters remaining

Email

jbedkowski@hillmanngroup.com

Alternate Contact Information

No information entered in this section will be visible to the public.

Fields are included in case alternate contact method is needed.

Title

Z3-4898

57 characters remaining

Organization

Hillmann Consulting, LLC

104 characters remaining

Phone

(908) 688-7800

Fax

(908) 686-2636

Address

Address Line 1

1600 Route 22 East

Address Line 2

Suite 107

City

Union

State / U.S. Territory

New Jersey

Zip

07083

Submit Request

Directory of City Agencies (http://www1.nyc.gov/nyc-resources/agencies.page)

Contact NYC Government (http://www1.nyc.gov/home/contact-us.page)

City Employees (https://a127-ess.nyc.gov)

Notify NYC (http://www.nyc.gov/notifynyc)

CityStore (http://a856-citystore.nyc.gov/)

Stay Connected (http://www1.nyc.gov/connect/social-media.page)

NYC Mobile Apps (http://www1.nyc.gov/connect/applications.page)

Maps (http://www1.nyc.gov/nyc-resources/nyc-maps.page)

Resident Toolkit (http://www1.nyc.gov/nyc-resources/resident-toolkit.page)

Search

City of New York. 2016 All Rights Reserved,
NYC is a trademark and service mark of the City of New York
Privacy Policy (http://www1.nyc.gov/home/privacy-policy.page).
Terms of Use (http://www1.nyc.gov/home/terms-of-use.page).

Fulton and Elliott-Chelsea
Property Profile

Developments: Fulton
Borough: Manhattan

BUILDING#	STAIRHALL#	ADDRESS	ZIP CODE	RESIDENTIAL	BLOCK	LOT	BIN	AMP#	HZ	FACILITY
1	001	401 WEST 16TH STREET	10011	YES	714	31	1078408	NY005001360	2	
1	001	413 WEST 16TH STREET	10011		714	31	1078408	NY005001360	2	
2	002	418 WEST 17TH STREET	10011	YES	714	31	1078411	NY005001360	2	
2	002	420 WEST 17TH STREET	10011		714	31	1078411	NY005001360	2	COMPUTER LAB
2	002	422 WEST 17TH STREET	10011		714	31	1078411	NY005001360	2	
3	003	400 WEST 17TH STREET	10011		714	31	1078409	NY005001360	2	
3	003	412 WEST 17TH STREET	10011	YES	714	31	1078409	NY005001360	2	
4	004	430 WEST 17TH STREET	10011		714	31	1078410	NY005001360	2	
4	004	434 WEST 17TH STREET	10011	YES	714	31	1078410	NY005001360	2	
5	005	427 WEST 17TH STREET	10011	YES	715	10	1078420	NY005001360	2	
5	005	431 WEST 17TH STREET	10011		715	10	1078420	NY005001360	2	
6	006	419 WEST 17TH STREET	10011	YES	715	10	1078419	NY005001360	2	
6	006	420 WEST 18TH STREET	10011		715	10	1078419	NY005001360	2	TWO STOREROOMS
6	006	421 WEST 17TH STREET	10011		715	10	1078419	NY005001360	2	DEVELOPMENT MANAGEMENT OFFICE
7	007	117 9TH AVENUE	10011		715	10	1078418	NY005001360	2	
7	007	119 9TH AVENUE	10011		715	10	1078418	NY005001360	2	SENIOR CENTER
7	007	121 9TH AVENUE	10011	YES	715	10	1078418	NY005001360	2	
8	008	401 WEST 18TH STREET	10011	YES	716	17	1078443	NY005001360	2	
8	008	411 WEST 18TH STREET	10011		716	17	1078443	NY005001360	2	
9	009	420 WEST 19TH STREET	10011	YES	716	17	1078445	NY005001360	2	
9	009	422 WEST 19TH STREET	10011		716	17	1078445	NY005001360	2	
10	010	400 WEST 19TH STREET	10011		716	17	1078444	NY005001360	2	
10	010	412 WEST 19TH STREET	10011	YES	716	17	1078444	NY005001360	2	
11	011	401 WEST 19TH STREET	10011	YES	717	19	1012576	NY005001360	2	
11	011	419 WEST 19TH STREET	10011		717	19	1012576	NY005001360	2	
12	012	432GAR WEST 18TH STREET	10011		715	10	1087110	NY005001360	2	GARAGE

Notes:
- *RESIDENTIAL indicates a residential mailing address.*
- *AMP# = Asset Management Project number*
- *BIN = Building Identification Number*
- *HZ = Hurricane Zone*

Open RECORDS

(/)

Your request has been submitted! ×

You can expect an acknowledgment from the City of New York within 5 business days. The agency will use the contact information you provided.

All messages from the City of New York and/or the information and documents you requested will be posted to this page.

FOIL-2022-826-01508

Title:
Under Review

Open

Department of Environmental Protection (DEP)

Acknowledgment
Due Date:
04/04/2022

Contact the Agency

Responses

Directory of City Agencies (http://www1.nyc.gov/nyc-resources/agencies.page)

Contact NYC Government (http://www1.nyc.gov/home/contact-us.page)

City Employees (https://a127-ess.nyc.gov)

Notify NYC (http://www.nyc.gov/notifynyc)

CityStore (http://a856-citystore.nyc.gov/)

Stay Connected (http://www1.nyc.gov/connect/social-media.page)

NYC Mobile Apps (http://www1.nyc.gov/connect/applications.page)

Maps (http://www1.nyc.gov/nyc-resources/nyc-maps.page)

Resident Toolkit (http://www1.nyc.gov/nyc-resources/resident-toolkit.page)

City of New York. 2016 All Rights Reserved,
NYC is a trademark and service mark of the City of New York
Privacy Policy (http://www1.nyc.gov/home/privacy-policy.page).
Terms of Use (http://www1.nyc.gov/home/terms-of-use.page).

FIRE DEPARTMENT – CITY OF NEW YORK

Public Records Unit / Tanks Section

9 MetroTech Center
Brooklyn, New York 11201-3857
(718) 999-2441 or 2442

Fuel Tank Special Report Request Form

SECTION A **CUSTOMER INFORMATION**

Please print the required information below.

Hillmann Consulting, LLC - Joanne Bedkowski
Name

1600 Route 22 East, Suite 107
Address

Union, NJ 07083
State Zip Code

908-688-7800, Fax: 908-686-2636
Telephone Number

OFFICE USE ONLY

Cashier / Search No.

PRU Staff
Accepted By/Initials:

Searched By:

Total Amount:

Note: Please make sure you complete this form and attach all required documents. Enclose a check or money order made payable to the **NYC Fire Department and a stamped self-addressed envelope (with postage).** Mail checks or money orders directly to the address and unit listed above. **DO NOT MAIL CASH.**

SECTION B **FUEL TANK REPORT - FEE $10.00 / PER REPORT**

401-413	West 16th Street	Manhattan
House Number	Street Name	Borough

- [x] THE TOTAL AMOUNT AND SIZE OF EXISTING FUEL OIL / HEATING TANKS
- [x] THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED FUEL OIL / HEATING TANKS
- [ ] THE TOTAL AMOUNT AND SIZE OF EXISTING BURIED MOTOR VEHICLE TANKS
- [ ] THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED BURIED MOTOR VEHICLE TANKS
- [ ] MOST RECENT TANK / PIPING TEST RESULTS
- [ ] HISTORY OF BURIED TANKS LEAKS

Note: Requests will be responded to within 10 business days.

FIRE DEPARTMENT – CITY OF NEW YORK

Public Records Unit / Tanks Section

9 MetroTech Center
Brooklyn, New York 11201-3857
(718) 999-2441 or 2442

Fuel Tank Special Report Request Form

SECTION A **CUSTOMER INFORMATION**

Please print the required information below.

Hillmann Consulting, LLC - Joanne Bedkowski
Name

1600 Route 22 East, Suite 107
Address

Union, NJ 07083
State Zip Code

908-688-7800, Fax: 908-686-2636
Telephone Number

OFFICE USE ONLY

Cashier / Search No.

PRU Staff
Accepted By/Initials:

Searched By:

Total Amount:

Note: Please make sure you complete this form and attach all required documents. Enclose a check or money order made payable to the **NYC Fire Department and a stamped self-addressed envelope (with postage).** Mail checks or money orders directly to the address and unit listed above. **DO NOT MAIL CASH**.

SECTION B **FUEL TANK REPORT - FEE $10.00 / PER REPORT**

400-434	West 17th Street	Manhattan
House Number	Street Name	Borough

- [x] THE TOTAL AMOUNT AND SIZE OF EXISTING FUEL OIL / HEATING TANKS
- [x] THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED FUEL OIL / HEATING TANKS
- [ ] THE TOTAL AMOUNT AND SIZE OF EXISTING BURIED MOTOR VEHICLE TANKS
- [ ] THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED BURIED MOTOR VEHICLE TANKS
- [ ] MOST RECENT TANK / PIPING TEST RESULTS
- [ ] HISTORY OF BURIED TANKS LEAKS

Note: Requests will be responded to within 10 business days.

PR3 (July-08)

FIRE DEPARTMENT – CITY OF NEW YORK

Public Records Unit / Tanks Section

9 MetroTech Center
Brooklyn, New York 11201-3857
(718) 999-2441 or 2442

Fuel Tank Special Report Request Form

SECTION A **CUSTOMER INFORMATION**

Please print the required information below.

Hillmann Consulting, LLC - Joanne Bedkowski
Name

1600 Route 22 East, Suite 107
Address

Union, NJ 07083
State Zip Code

908-688-7800, Fax: 908-686-2636
Telephone Number

OFFICE USE ONLY

Cashier / Search No.

PRU Staff
Accepted By/Initials:

Searched By:

Total Amount:

Note: Please make sure you complete this form and attach all required documents. Enclose a check or money order made payable to the **NYC Fire Department and a stamped self-addressed envelope (with postage).** Mail checks or money orders directly to the address and unit listed above. **DO NOT MAIL CASH.**

SECTION B **FUEL TANK REPORT - FEE $10.00 / PER REPORT**

419-431	West 17th Street	Manhattan
House Number	Street Name	Borough

- [x] **THE TOTAL AMOUNT AND SIZE OF EXISTING FUEL OIL / HEATING TANKS**
- [x] **THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED FUEL OIL / HEATING TANKS**
- [ ] **THE TOTAL AMOUNT AND SIZE OF EXISTING BURIED MOTOR VEHICLE TANKS**
- [ ] **THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED BURIED MOTOR VEHICLE TANKS**
- [ ] **MOST RECENT TANK / PIPING TEST RESULTS**
- [ ] **HISTORY OF BURIED TANKS LEAKS**

Note: Requests will be responded to within 10 business days.

PR3 (July-08)

FIRE DEPARTMENT – CITY OF NEW YORK

Public Records Unit / Tanks Section

9 MetroTech Center
Brooklyn, New York 11201-3857
(718) 999-2441 or 2442

Fuel Tank Special Report Request Form

SECTION A **CUSTOMER INFORMATION**

Please print the required information below.

Hillmann Consulting, LLC - Joanne Bedkowski
Name

1600 Route 22 East, Suite 107
Address

Union, NJ 07083
State Zip Code

908-688-7800, Fax: 908-686-2636
Telephone Number

OFFICE USE ONLY

Cashier / Search No.

PRU Staff
Accepted By/Initials:

Searched By:

Total Amount:

Note: Please make sure you complete this form and attach all required documents. Enclose a check or money order made payable to the **NYC Fire Department and a stamped self-addressed envelope (with postage).** Mail checks or money orders directly to the address and unit listed above. **DO NOT MAIL CASH.**

SECTION B **FUEL TANK REPORT - FEE $10.00 / PER REPORT**

420-432	West 18th Street	Manhattan
House Number	Street Name	Borough

- [x] **THE TOTAL AMOUNT AND SIZE OF EXISTING FUEL OIL / HEATING TANKS**
- [x] **THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED FUEL OIL / HEATING TANKS**
- [ ] **THE TOTAL AMOUNT AND SIZE OF EXISTING BURIED MOTOR VEHICLE TANKS**
- [ ] **THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED BURIED MOTOR VEHICLE TANKS**
- [ ] **MOST RECENT TANK / PIPING TEST RESULTS**
- [ ] **HISTORY OF BURIED TANKS LEAKS**

Note: Requests will be responded to within 10 business days.

PR3 (July-08)

FIRE DEPARTMENT – CITY OF NEW YORK

Public Records Unit / Tanks Section

9 MetroTech Center
Brooklyn, New York 11201-3857
(718) 999-2441 or 2442

Fuel Tank Special Report Request Form

SECTION A **CUSTOMER INFORMATION**

Please print the required information below.

Hillmann Consulting, LLC - Joanne Bedkowski
Name

1600 Route 22 East, Suite 107
Address

Union, NJ 07083
State Zip Code

908-688-7800, Fax: 908-686-2636
Telephone Number

OFFICE USE ONLY

Cashier / Search No.

PRU Staff
Accepted By/Initials:

Searched By:

Total Amount:

Note: Please make sure you complete this form and attach all required documents. Enclose a check or money order made payable to the **NYC Fire Department and a stamped self-addressed envelope (with postage).** Mail checks or money orders directly to the address and unit listed above. **DO NOT MAIL CASH.**

SECTION B **FUEL TANK REPORT - FEE $10.00 / PER REPORT**

401-411	West 18th Street	Manhattan
House Number	Street Name	Borough

- [x] THE TOTAL AMOUNT AND SIZE OF EXISTING FUEL OIL / HEATING TANKS
- [x] THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED FUEL OIL / HEATING TANKS
- [ ] THE TOTAL AMOUNT AND SIZE OF EXISTING BURIED MOTOR VEHICLE TANKS
- [ ] THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED BURIED MOTOR VEHICLE TANKS
- [ ] MOST RECENT TANK / PIPING TEST RESULTS
- [ ] HISTORY OF BURIED TANKS LEAKS

Note: Requests will be responded to within 10 business days.

PR3 (July-08)

FIRE DEPARTMENT – CITY OF NEW YORK

Public Records Unit / Tanks Section

9 MetroTech Center
Brooklyn, New York 11201-3857
(718) 999-2441 or 2442

Fuel Tank Special Report Request Form

SECTION A **CUSTOMER INFORMATION**

Please print the required information below.

Hillmann Consulting, LLC - Joanne Bedkowski
Name

1600 Route 22 East, Suite 107
Address

Union, NJ 07083
State Zip Code

908-688-7800, Fax: 908-686-2636
Telephone Number

OFFICE USE ONLY

Cashier / Search No.

PRU Staff
Accepted By/Initials:

Searched By:

Total Amount:

Note: Please make sure you complete this form and attach all required documents. Enclose a check or money order made payable to the **NYC Fire Department and a stamped self-addressed envelope (with postage).** Mail checks or money orders directly to the address and unit listed above. **DO NOT MAIL CASH.**

SECTION B **FUEL TANK REPORT - FEE $10.00 / PER REPORT**

117-121	9th Avenue	Manhattan
House Number	Street Name	Borough

- [x] **THE TOTAL AMOUNT AND SIZE OF EXISTING FUEL OIL / HEATING TANKS**
- [x] **THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED FUEL OIL / HEATING TANKS**
- [ ] **THE TOTAL AMOUNT AND SIZE OF EXISTING BURIED MOTOR VEHICLE TANKS**
- [ ] **THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED BURIED MOTOR VEHICLE TANKS**
- [ ] **MOST RECENT TANK / PIPING TEST RESULTS**
- [ ] **HISTORY OF BURIED TANKS LEAKS**

Note: Requests will be responded to within 10 business days.

FIRE DEPARTMENT – CITY OF NEW YORK

Public Records Unit / Tanks Section

9 MetroTech Center
Brooklyn, New York 11201-3857
(718) 999-2441 or 2442

Fuel Tank Special Report Request Form

SECTION A **CUSTOMER INFORMATION**

Please print the required information below.

Hillmann Consulting, LLC - Joanne Bedkowski
Name

1600 Route 22 East, Suite 107
Address

Union, NJ 07083
State Zip Code

908-688-7800, Fax: 908-686-2636
Telephone Number

OFFICE USE ONLY

Cashier / Search No.

PRU Staff
Accepted By/Initials:

Searched By:

Total Amount:

Note: Please make sure you complete this form and attach all required documents. Enclose a check or money order made payable to the **NYC Fire Department and a stamped self-addressed envelope (with postage).** Mail checks or money orders directly to the address and unit listed above. **DO NOT MAIL CASH.**

SECTION B **FUEL TANK REPORT - FEE $10.00 / PER REPORT**

400-422	West 19th Street	Manhattan
House Number	Street Name	Borough

- [x] THE TOTAL AMOUNT AND SIZE OF EXISTING FUEL OIL / HEATING TANKS
- [x] THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED FUEL OIL / HEATING TANKS
- [ ] THE TOTAL AMOUNT AND SIZE OF EXISTING BURIED MOTOR VEHICLE TANKS
- [ ] THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED BURIED MOTOR VEHICLE TANKS
- [ ] MOST RECENT TANK / PIPING TEST RESULTS
- [ ] HISTORY OF BURIED TANKS LEAKS

Note: Requests will be responded to within 10 business days.

PR3 (July-08)

FIRE DEPARTMENT – CITY OF NEW YORK

Public Records Unit / Tanks Section

9 MetroTech Center
Brooklyn, New York 11201-3857
(718) 999-2441 or 2442

Fuel Tank Special Report Request Form

SECTION A **CUSTOMER INFORMATION**

Please print the required information below.

Hillmann Consulting, LLC - Joanne Bedkowski
Name

1600 Route 22 East, Suite 107
Address

Union, NJ 07083
State Zip Code

908-688-7800, Fax: 908-686-2636
Telephone Number

OFFICE USE ONLY

Cashier / Search No.

PRU Staff
Accepted By/Initials:

Searched By:

Total Amount:

Note: Please make sure you complete this form and attach all required documents. Enclose a check or money order made payable to the **NYC Fire Department and a stamped self-addressed envelope (with postage).** Mail checks or money orders directly to the address and unit listed above. **DO NOT MAIL CASH**.

SECTION B **FUEL TANK REPORT - FEE $10.00 / PER REPORT**

401-419	West 19th Street	Manhattan
House Number	Street Name	Borough

- [x] **THE TOTAL AMOUNT AND SIZE OF EXISTING FUEL OIL / HEATING TANKS**
- [x] **THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED FUEL OIL / HEATING TANKS**
- [ ] **THE TOTAL AMOUNT AND SIZE OF EXISTING BURIED MOTOR VEHICLE TANKS**
- [ ] **THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED BURIED MOTOR VEHICLE TANKS**
- [ ] **MOST RECENT TANK / PIPING TEST RESULTS**
- [ ] **HISTORY OF BURIED TANKS LEAKS**

Note: Requests will be responded to within 10 business days.

PR3 (July-08)

Public Records Center

MENU

Public Records Menu

FAQs

See All FAQs

- How to contact NYSDEC about FOIL?
- Response time to my FOIL request?
- Exceptions to disclosing records?
- Fees I have to pay?
- Can I inspect documents first?
- Processing of my request?
- How I pay fees?
- How do I appeal a denial of access?

View File(s) | View Message(s)

Request Type: Freedom of Information Law Request

Description: A FOIL request is a request for any "record" under NY's Freedom of Information Law (Article 6 of the Public Officers Law). Section 86 defines a "record" as: "any information kept, held, filed, produced or reproduced by, with or for an agency or the state legislature, in any physical form whatsoever including, but not limited to, reports, statements, examinations, memoranda, opinions, folders, files, books, manuals, pamphlets, forms, papers, designs, drawings, maps, photos, letters, microfilms, computer tapes or discs, rules, regulations or codes. NYSDEC maintains records in a variety of forms, or media, such as in hard copy (on paper), as recordings, as photographs, in electronic form, etc.

Contact E-Mail: jbedkowski@hillmanngroup.com

Reference No: W098706-032822

UPLOAD DATE

Files:	03/28/2022	Fulton.pdf

Powered by GovQA

Type of Record(s) Requested:	Other
Description of Record(s) Requested:	Records regarding above and underground storage tanks, permits and/or violations, spills, hazardous material and any other information of environmental concern as we are conducting a Phase I Environmental Site Assessment. (My ref#: Z3-4898), Time frame: 01/01/1963 - 03/28/2022 - Fulton - Various addresses (see attached address listing), Manhattan, NY 10011
NYSDEC Office processing the Request:	Region 2 (New York City) Covers the counties of Brooklyn Bronx Manhattan Queens and Staten Island **If your request pertains to just one Region, select that Region. If your request pertains to more than one Region, select Central Office. If you're unsure which Region your request pertains to, select Central Office. The Department will route your request to the appropriate Region(s)**
Preferred Method to Receive Records:	Electronic copies **NYSDEC will use its best efforts to provide records via the method you select. However, in some cases a particular delivery method is not feasible In such cases NYSDEC will deliver the records via an alternative method**

Please note not all public documents are available in electronic format. If the document(s) requested are not available electronically, we will make them available for inspection or by paper copy in accordance with the Public Records Law.

New Message Cancel

Messages 2

Print Messages (PDF

On 3/28/2022 6:12:48 PM, New York DEC Support wrote:

Powered by GovQA

Thank you for your Freedom of Information Law (FOIL) request. Your request has been received and is being processed. Your request was received in this office on 3/28/2022 and given the reference number FOIL #W098706-032822 for tracking purposes. You may expect the Department's response to your request no later than **4/26/2022**.

Record Requested: **Records regarding above and underground storage tanks, permits and/or violations, spills, hazardous material and any other information of environmental concern as we are conducting a Phase I Environmental Site Assessment. (My ref#: Z3-4898), Time frame: 01/01/1963 - 03/28/2022 - Fulton - Various addresses (see attached address listing), Manhattan, NY 10011**

You can monitor the progress of your request at the link below and you'll receive an email when your request has been completed. Again, thank you for using the FOIL Center.

https://mycusthelp.com/NEWYORKDEC/_rs/RequestLogin.aspx

New York State Department of Environmental Conservation, Record Access Office

---

Track the issue status and respond at:
https://newyorkdec.mycusthelp.com/webapp//_rs/RequestEdit.aspx?rid=98706

On 3/28/2022 6:12:48 PM, Joanne Bedkowski wrote:

Request Created on Public Portal

Powered by GovQA

Fulton and Elliott-Chelsea
Property Profile

Developments: Fulton
Borough: Manhattan

BUILDING#	STAIRHALL#	ADDRESS	ZIP CODE	RESIDENTIAL	BLOCK	LOT	BIN	AMP#	HZ	FACILITY
1	001	401 WEST 16TH STREET	10011	YES	714	31	1078408	NY005001360	2	
1	001	413 WEST 16TH STREET	10011		714	31	1078408	NY005001360	2	
2	002	418 WEST 17TH STREET	10011	YES	714	31	1078411	NY005001360	2	
2	002	420 WEST 17TH STREET	10011		714	31	1078411	NY005001360	2	COMPUTER LAB
2	002	422 WEST 17TH STREET	10011		714	31	1078411	NY005001360	2	
3	003	400 WEST 17TH STREET	10011		714	31	1078409	NY005001360	2	
3	003	412 WEST 17TH STREET	10011	YES	714	31	1078409	NY005001360	2	
4	004	430 WEST 17TH STREET	10011		714	31	1078410	NY005001360	2	
4	004	434 WEST 17TH STREET	10011	YES	714	31	1078410	NY005001360	2	
5	005	427 WEST 17TH STREET	10011	YES	715	10	1078420	NY005001360	2	
5	005	431 WEST 17TH STREET	10011		715	10	1078420	NY005001360	2	
6	006	419 WEST 17TH STREET	10011	YES	715	10	1078419	NY005001360	2	
6	006	420 WEST 18TH STREET	10011		715	10	1078419	NY005001360	2	TWO STORERCOMS
6	006	421 WEST 17TH STREET	10011		715	10	1078419	NY005001360	2	DEVELOPMENT MANAGEMENT OFFICE
7	007	117 9TH AVENUE	10011		715	10	1078418	NY005001360	2	
7	007	119 9TH AVENUE	10011		715	10	1078418	NY005001360	2	SENIOR CENTER
7	007	121 9TH AVENUE	10011	YES	715	10	1078418	NY005001360	2	
8	008	401 WEST 18TH STREET	10011	YES	716	17	1078443	NY005001360	2	
8	008	411 WEST 18TH STREET	10011		716	17	1078443	NY005001360	2	
9	009	420 WEST 19TH STREET	10011	YES	716	17	1078445	NY005001360	2	
9	009	422 WEST 19TH STREET	10011		716	17	1078445	NY005001360	2	
10	010	400 WEST 19TH STREET	10011		716	17	1078444	NY005001360	2	
10	010	412 WEST 19TH STREET	10011	YES	716	17	1078444	NY005001360	2	
11	011	401 WEST 19TH STREET	10011	YES	717	19	1012576	NY005001360	2	
11	011	419 WEST 19TH STREET	10011		717	19	1012576	NY005001360	2	
12	012	432GAR WEST 18TH STREET	10011		715	10	1087110	NY005001360	2	GARAGE

Notes:
- *RESIDENTIAL indicates a residential mailing address.*
- *AMP# = Asset Management Project number*
- *BIN = Building Identification Number*
- *HZ = Hurricane Zone*

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

401 WEST 16 STREET **MANHATTAN 10011** **BIN# 1078408**

9 AVENUE	89 - 89	Health Area	: 5600	Tax Block	: 714
WEST 16 STREET	401 - 413	Census Tract	: 83	Tax Lot	: 31
FULTON HOUSES BUILDING 1	NO NUMBER	Community Board	: 104	Condo	: NO
		Buildings on Lot	: 4	Vacant	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, HIGH LINE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	YES	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	Yes		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	5	0
Violations-DOB	15	1
Violations-OATH/ECB	3	0
Jobs/Filings	11	
ARA / LAA Jobs	0	
Total Jobs	11	
Actions	63	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 401 WEST 16 STREET MANHATTAN **BIN: 1078408 Block: 714 Lot: 31**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

CO 27136:	M000027136.PDF
CO 16181:	M000016181.PDF
CO 3187:	M000003187.PDF

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Form 55

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

No. 27136 AVC

Date December 19,1940

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.37. Building Code).

This certificate supersedes C. O. No.

To the owner or owners of the building or premises:

THIS CERTIFIES that the new—~~altered~~—~~existing~~—building—premises located at

89-109 Ninth Avenue
65' front

Block 714 Lot 31 to 38

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~or Alt~~ No.— 130-1940 Construction classification—nonfireproof

Occupancy classification—commercial . Height 1 stories, 13 feet.

Date of completion—October 28,1940 . Located in unrestricted Use District.

A Area 2 . Height Zone at time of issuance of permit 3989-1940

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED			USE
		MALE	FEMALE	TOTAL	
1st Story	on ground				Gasoline service station and accessory building;office, lubritorium, repairs,laundry parking and storage for more than five (5) motor vehicles.
					Six (6) 550 gallon gasoline tanks approved by Fire Department December 5,1940.

Borough Superintendent.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there by any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaing the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form—244-19.9 Certificate of Occupancy. 8A-2007-29-I.S.

BUREAU OF BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

HVC **CERTIFICATE OF OCCUPANCY No. 16181** 19 30

Supersedes Certificate of Occupancy No. 3187

To the owner or owners of the building: New York Mar.4, 19 30.

THIS CERTIFIES that the building located on Block 714, Lot 21

known as 415-25 West 16th Street 150' front

under a permit, Application No. 1826 Alt of 1929 conforms to the approved plans and specifications accompanying said permit and any approved amendments thereto, and to the requirements of the building code and all other laws and ordinances and to the rules and regulations of the board of standards and appeals, applicable to a building of its class and kind, except that in the case of a building heretofore existing and for which no previous certificate of occupancy has been issued and which has not been altered or converted since March 14, 1916, to a use that changed its classification as defined in the building code, this certificate confirms and continues the existing uses to which the building has been put; and

CERTIFIES FURTHER that the building is of nonfireproof construction within the meaning of the building code and may be used and occupied as a business building as hereinafter qualified, in a n unrestricted district under the building zone resolution, subject to all the privileges, requirements, limitations and conditions prescribed by law or as hereinafter specified.

STORY	LIVE LOADS (Lbs. per Sq. Ft.)	PERSONS ACCOMMODATED			USE
		MALE	FEMALE	TOTAL	
1st Story on ground				5	Garage for more than 5 autos

This certificate is issued to Niewenhous Co.,Inc., 51 Madison Avenue, City., for the owner or owners.

The superimposed, uniformly distributed loads, or their equivalent concentrated loads in any story shall not exceed the live loads specified above; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

Unless specifically stated above, the building or any part thereof, if certified as a public building, shall not be used as a building in which persons are harbored to receive medical, charitable or other care or treatment, such as a hospital, asylum, etc., or in which persons are held or detained under legal restraint, such as a police station, jail, etc.; nor shall it be used as a motion picture theatre as defined in section 30, chapter 3, Code of Ordinances; nor as a theatre or opera house or other building intended to be used for theatrical or operatic purposes, or for public entertainment of any kind, for the accommodation of more than 300 persons.

Unless specifically stated above, the building or any part thereof, if certified as a residence building, shall not be used as a tenement house as defined in the tenement house law; nor shall it be used as any form of residence building having more than 15 sleeping rooms; nor shall it be used as a lodging house within the meaning of Sec. 1305 of the Greater New York Charter.

Unless specifically stated above, the building or any part thereof, if certified as a business building, shall not be used as a garage, motor vehicle repair shop or oil selling station as defined in section 1, chapter 10, Code of Ordinances; nor shall it be used for the generation or compression of acetylene; nor as a factory building as defined in the labor law; nor as a grain elevator; nor as a coal pocket.

Except as otherwise noted above, the building, or any part thereof, if located elsewhere than in an unrestricted district, shall not be used for any of the purposes enumerated in paragraph (a) of section 4 of the building zone resolution; nor for any trade, industry or use that is noxious or offensive by reason of the emission of odor, dust, smoke, gas or noise; nor for any kind of manufacturing not already prohibited, except that, if located in a business district, not more than twenty-five per cent. of the total floor space may be so used, or space equal to the area of the lot in any case.

Except as otherwise noted above, the building, if certified as a garage, may not be used for more than five cars on any portion of a street between two intersecting streets, in which portion there exists an exit from or an entrance to a public school, or in which portion there exists any hospital maintained as a charitable institution; and in no case within a distance of 200 feet from the nearest exit from or entrance to a public school; nor within two hundred feet of any hospital maintained as a charitable institution.

If the building has, at any time previous to the issuance of this certificate, been the subject of an appeal to the board of appeals or of a petition to the board of standards and appeals resulting in modification or variation of law or any lawful requirement, the construction and arrangement of the building as specified in the resolution granting such modification or variation, must be maintained, and all conditions imposed by either board must be observed.

No change or re-arrangement in the structural parts of the building, or affecting the lighting or ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located, until an approval of the same has been obtained from the superintendent of buildings.

This certificate supersedes each and every previously issued certificate of occupancy for this building or any part thereof, and each and every such previously issued certificate shall be null and void; and this certificate in turn becomes null and void upon the issuance of any new lawful certificate.

This certificate does not in any way relieve the owner or owners, or any other person or persons in possession or control of the building, or any part thereof, from obtaining such other permits or licenses as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

This certificate does not authorize the use or operation of any elevator in the building without the special certificate required by section 563 of the building code.

If the building is or is required to be equipped with standpipes or other fire extinguishing or gas shut off appliances, this certificate is not complete until such standpipes or other appliances have been inspected by the fire department (or by the Tenement House Department, in the case of a gas shut off in a tenement house) and approved in writing, either in a separate certificate or by endorsement upon this certificate. (Space for such endorsement is provided on page 4 of this certificate.)

If this certificate is marked "Temporary," it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to a tenement house unless also approved by the tenement house commissioner; and it must be replaced by a full certificate as soon as the entire building is completed according to law and ready for occupancy.

The word "class" as used in this certificate refers to the classification of buildings in the building code (section 70).

This certificate is issued in accordance with the provisions of section 411-a of the Greater New York Charter and of section 5 of chapter 5 (Building Code) of the Code of Ordinances of the City of New York.

Examined.

.....

Superintendent of Buildings, Borough of Manhattan.

Additional copies of this certificate will be issued, upon written request, to persons having a proprietary interest in the building.

Form 150-1b-3 Certificate of Occupancy

8A-2045-20 B

BUREAU OF BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

Cd CERTIFICATE OF OCCUPANCY No. 1921

THIS CERTIFIES that the building located on Block 714 Lot 22-26

known as 415-25 West 16 Street.
150' front.

conforms substantially to the approved plans and specifications of N. B. Application No. 148 1921
and to all the requirements of the BUILDING CODE AND BUILDING ZONE RESOLUTION of the City of New York

for a non-fireproof, cellar, basement & 1 story Garage & Office.

and that the several floors may sustain the live loads, accommodate the number of persons, and be occupied as follows:

FLOORS	Live Load per Square Foot in POUNDS	Number and Classification Persons on each Floor	OCCUPANCY
Cellar	---		Heating Apparatus
Basement	---	15	Garage
1st Floor	120 60	15	Garage Office

This certificate is issued to Heneken Realty Co.

owners of the aforesaid building, address 543 W. 28 St., N.Y.City.

in accordance with the provisions of Section 5, Article 1, Chapter 5 of the Code of Ordinances of the City of New York, and Chapter 503, Section 411-a of the Greater New York Charter.

DATED May 18, 1921.

Superintendent of Buildings.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

DOB Violation Display for 062021EARCX00077

Premises: 401 WEST 16 STREET MANHATTAN **BIN: 1078408 Block: 714 Lot: 31**

Issue Date: 06/20/2021
Violation Category: V - DOB VIOLATION - ACTIVE
Violation Type: EARCX - FAILURE TO SUBMIT EER
Violation Number: 00077
Device No.:
OATH/ECB No.:
Infraction Codes:
Description: FAILURE TO SUBMIT AN EER PER AD. CODE SEC. 28-308.4 - MULTIPLE YEARS (2020)

Disposition:
Code: **Date:**
Inspector:
Comments:

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises: **BIN:** **Block:** **Lot:**

VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE	NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Environmental Protection

Register with CATS
Login into CATS

.gov always open

NYC DEP CATS Information

SEARCH INFORMATION

Searching For Data...

Contacting Database...Please Wait

Search By :	BBL
***Application# :**	
***Borough :**	Manhattan
***Block :**	714
***Lot :**	31
***Premise House# :**	
***Premise Street :**	
***Premise Borough :**	-- Select Borough --
***Captcha :**	 Input symbols

Search Clear

No Record Found.

Please be advised that application numbers starting with 'C' are associated to boilers, 'P' are associated with industrials and 'G' are associated with Gas stations.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

400 WEST 17 STREET **MANHATTAN 10011** **BIN# 1078409**

9 AVENUE	103 - 103	**Health Area**	: 5600	**Tax Block**	: 714
WEST 17 STREET	400 - 412	**Census Tract**	: 83	**Tax Lot**	: 31
FULTON HOUSES BUILDING 3	NO NUMBER	**Community Board**	: 104	**Condo**	: NO
		Buildings on Lot	: 4	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	YES	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	Yes		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	1	0
Violations-DOB	20	1
Violations-OATH/ECB	2	0
Jobs/Filings	6	
ARA / LAA Jobs	1	
Total Jobs	7	
Actions	45	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 400 WEST 17 STREET MANHATTAN **BIN: 1078409 Block: 714 Lot: 31**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

CO 8737:	M000008737.PDF
CO 35249:	M000035249.PDF
CO 39506:	M000039506.PDF

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Form—244-1923 Certificate of Occupancy. SA-3087-23-L

BUREAU OF BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

HVC **CERTIFICATE OF OCCUPANCY No.** 192 4

Supersedes Certificate of Occupancy No.

To the owner or owners of the building: New York Oct. 28 1924

THIS CERTIFIES that the building located on Block 714 , Lot 28-40-41

known as 407-11 West 16th Street--408-12 West 17th Street
70' 8" front

under a permit, Application No. 241 N.B. of 1924, conforms to the approved plans and specifications accompanying said permit and any approved amendments thereto, and to the requirements of the building code and all other laws and ordinances and to the rules and regulations of the board of standards and appeals, applicable to a building of its class and kind, except that in the case of a building heretofore existing and for which no previous certificate of occupancy has been issued and which has not been altered or converted since March 14, 1916, to a use that changed its classification as defined in the building code, this certificate confirms and continues the existing uses to which the building has been put; and

CERTIFIES FURTHER that the building is of non-fireproof construction within the meaning of the building code and may be used and occupied as a business building as hereinafter qualified, in an unrestricted district under the building zone resolution, subject to all the privileges, requirements, limitations, and conditions prescribed by law or as hereinafter specified.

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
1st Story on ground					Garage more than 5 autos.

This certificate is issued to James R. Torrance, Architect
85 Ninth Avenue City , for the owner or owners.

The superimposed, uniformly distributed loads, or their equivalent concentrated loads in any story shall not exceed the live loads specified above; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

Unless specifically stated above, the building or any part thereof, if certified as a public building, shall not be used as a building in which persons are harbored to receive medical, charitable or other care or treatment, such as a hospital, asylum, etc., or in which persons are held or detained under legal restraint, such as a police station, jail, etc.; nor shall it be used as a motion picture theatre as defined in section 30, chapter 3, Code of Ordinances; nor as a theatre or opera house or other building intended to be used for theatrical or operatic purposes, or for public entertainment of any kind, for the accommodation of more than 300 persons.

Unless specifically stated above, the building or any part thereof, if certified as a residence building, shall not be used as a tenement-house as defined in the tenement house law; nor shall it be used as any form of residence building having more than 15 sleeping rooms; nor shall it be used as a lodging house within the meaning of Sec. 1305 of the Greater New York Charter.

Unless specifically stated above, the building or any part thereof, if certified as a business building, shall not be used as a garage, motor-vehicle repair shop or oil selling station as defined in section 1, chapter 10, Code of Ordinances; nor shall it be used for the generation or compression of acetylene; nor as a factory building as defined in the labor law; nor as a grain elevator; nor as a coal pocket; but if approved as a factory building for less than twenty-five persons, it shall not be used for any other purpose.

Except as otherwise noted above, the building, or any part thereof, if located elsewhere than in an unrestricted district, shall not be used for any of the purposes enumerated in paragraph (a) of section 4 of the building zone resolution; nor for any trade, industry or use that is noxious or offensive by reason of the emission of odor, dust, smoke, gas or noise; nor for any kind of manufacturing not already prohibited, except that, if located in a business district, not more than twenty-five per cent. of the total floor space may be so used, or space equal to the area of the lot in any case.

Except as otherwise noted above, the building, if certified as a garage, may not be used for more than five cars on any portion of a street between two intersecting streets, in which portion there exists an exit from or an entrance to a public school, or in which portion there exists any hospital maintained as a charitable institution; and in no case within a distance of 200 feet from the nearest exit from or entrance to a public school; nor within two hundred feet of any hospital maintained as a charitable institution.

If the building has, at any time previous to the issuance of this certificate, been the subject of an appeal to the board of appeals or of a petition to the board of standards and appeals resulting in modification or variation of law or any lawful requirement, the construction and arrangement of the building as specified in the resolution granting such modification or variation, must be maintained, and all conditions imposed by either board must be observed.

No change or re-arrangement in the structural parts of the building, or affecting the lighting or ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located, until an approval of the same has been obtained from the superintendent of buildings.

This certificate supersedes each and every previously issued certificate of occupancy for this building or any part thereof, and each and every such previously issued certificate shall be null and void; and this certificate in turn becomes null and void upon the issuance of any new lawful certificate.

This certificate does not in any way relieve the owner or owners, or any other person or persons in possession or control of the building, or any part thereof, from obtaining such other permits or licenses as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

This certificate does not authorize the use or operation of any elevator in the building without the special certificate required by section 563 of the building code.

If the building is or is required to be equipped with standpipes or other fire extinguishing appliances, this certificate is not complete until such standpipes or other appliances have been inspected by the fire department and approved in writing, either in a separate certificate or by endorsement upon this certificate. (Space for such endorsement is provided on page 4 of this certificate.)

If this certificate is marked "Temporary," it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to a tenement house unless also approved by the tenement house commissioner; and it must be replaced by a full certificate as soon as the entire building is completed according to law and ready for occupancy.

The word "class" as used in this certificate refers to the classification of buildings in the building code (section 70).

This certificate is issued in accordance with the provisions of section 411-a of the Greater New York Charter and of section 5 of chapter 5 (Building Code) of the Code of Ordinances of the City of New York.

Examined.

Superintendent of Buildings, Borough of Manhattan.

Additional copies of this certificate will be issued, upon written request, to persons having a proprietary interest in the building.

Form 55-3M-10-46-423-114

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

No. 3929

Date February 25, 1949

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No.

To the owner or owners of the building or premises:

THIS CERTIFIES that the ~~new~~ altered—~~existing~~—building—premises located at 427-429 West 16th street, 414-428 West 17th st, Block 714 Lots 19 & 20 Lots 42 to 49, incl.

———, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

~~N.B. or~~ Alt. No.— 2508-1948 Construction classification———

Occupancy classification— Commercial . Height——— stories,——— feet.

Date of completion— February 14, 1949 . Located in an unrestricted Use District.

B Area 14 Height Zone at time of issuance of permit ———

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
On ground					Parking lot for more than five (5) motor vehicles.

Borough Superintendent.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form 84 (10.5M 7013172491) — 114

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

No. 30506

Date February 18, 1952

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No. 25767

To the owner or owners of the building or premises:

THIS CERTIFIES that the new—~~altered existing~~—building—premises located at

414-428 West 17th Street Block 714 Lot 42

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. or ~~Alt~~ No.— 115-1950 Construction classification—Class 3 nonfireproof

Occupancy classification— Commercial Bldg. . Height 1 stories, 16 feet.

Date of completion— February 14, 1952 . Located in Unrestricted Use District.

A Area 2 . Height Zone at time of issuance of permit 1814-1950.

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
Cellar	on ground			1	Boiler room and storage.
1st story	on ground			20	Garage for more than five (5) motor vehicles and Parking and storage of more than five (5) motor vehicles on vacant part of lot.
					Fuel Oil installation approved by Fire Department December 12, 1950.
					Garage Use and gasoline tank installation approved by Fire Department January 5, 1951.

Borough Superintendent.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

DOB Violation Display for 061919FISPHAZ88223

Premises: 400 WEST 17 STREET MANHATTAN **BIN: 1078409 Block: 714 Lot: 31**

Issue Date:	06/19/2019	**Violation Category:**	V - DOB VIOLATION - ACTIVE
Violation Type:	FISP - FACADE SAFETY PROGRAM		
Violation Number:	HAZ88223	**Device No.:**	00813108
OATH/ECB No.:			
Infraction Codes:			
Description:			
Disposition:			
Code:	**Date:**		
Inspector:			
Comments:			

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises:							BIN:	Block:	Lot:
VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE		NAME	

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

430 WEST 17 STREET — **MANHATTAN 10011** — **BIN# 1078410**

WEST 17 STREET	430 - 434	**Health Area**	: 5600	**Tax Block**	: 714
FULTON HOUSES BUILDING 4	NO NUMBER	**Census Tract**	: 83	**Tax Lot**	: 31
		Community Board	: 104	**Condo**	: NO
		Buildings on Lot	: 4	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	YES	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	Yes		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	3	0
Violations-DOB	16	2
Violations-OATH/ECB	2	0
Jobs/Filings	7	
ARA / LAA Jobs	0	
Total Jobs	7	
Actions	54	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 430 WEST 17 STREET MANHATTAN **BIN: 1078410 Block: 714 Lot: 31**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

CO 35715: M000035715.PDF
CO 35715

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

55-22M-71145 414

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

No.
Date June 6, 1949

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No.

To the owner or owners of the building or premises:

THIS CERTIFIES that the ~~new~~—altered—~~existing~~—building—premises located at 430-438 West 17th street Lots 50, 51, 52, Block 714 Lot s 53, 54.

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. or Alt. No.— 360-1949 Construction classification—

Occupancy classification— Commercial . Height stories, feet.

Date of completion— June 3, 1949 . Located in Unrestricted Use District.

Area 2 times . Height Zone at time of issuance of permit A

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
On ground					PARKING LOT for more than five (5) motor vehicles.

Borough Superintendent

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

DOB Violation Display for 061919FISPHAZ88224

Premises: 430 WEST 17 STREET MANHATTAN **BIN: 1078410 Block: 714 Lot: 31**

Issue Date: 06/19/2019
Violation Type: FISP - FACADE SAFETY PROGRAM
Violation Number: HAZ88224
OATH/ECB No.:
Infraction Codes:
Description:

Violation Category: V - DOB VIOLATION - ACTIVE
Device No.: 00813110

Disposition:
Code: **Date:**
Inspector:
Comments:

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

DOB Violation Display for 121721HVCAT500998

Premises: 430 WEST 17 STREET MANHATTAN **BIN: 1078410 Block: 714 Lot: 31**

Issue Date:	12/17/2021	**Violation Category:**	V - DOB VIOLATION - ACTIVE
Violation Type:	HVCAT5 - NYCHA ELEVATOR PERIODIC INSPECTION/TEST		
Violation Number:	00998	**Device No.:**	1P26865

DOB Mobile Violation Number: 1P26865/13-3/2018-10-31
OATH/ECB No.:
Infraction Codes:
Description: FAILURE TO PERFORM CATEGORY 5 INSPECTION

Disposition:
Code: **Date:**
Inspector:
Comments:

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises: **BIN:** **Block:** **Lot:**

VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE	NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

418 WEST 17 STREET **MANHATTAN 10011** **BIN# 1078411**

WEST 17 STREET	418 - 422	**Health Area**	: 5600	**Tax Block**	: 714
FULTON HOUSES BUILDING 2	NO NUMBER	**Census Tract**	: 83	**Tax Lot**	: 31
		Community Board	: 104	**Condo**	: NO
		Buildings on Lot	: 4	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	YES	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	Yes		
Number of Dwelling Units:	219		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	12	0
Violations-DOB	13	0
Violations-OATH/ECB	6	1
Jobs/Filings	20	
ARA / LAA Jobs	4	
Total Jobs	24	
Actions	24	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 418 WEST 17 STREET MANHATTAN **BIN: 1078411 Block: 714 Lot: 31**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

CO 60402:	M000060402.PDF
COFO 40402-TEMP:	M000040402.PDF
COFO 60670-TEMP:	M000060670.PDF
COFO 61185TEMP:	M000061185.PDF
COFO 61505:	M000061505.PDF
COFO 65737:	M000065737.PDF
COFO 73863:	M000073863.PDF
JOB 122036215:	122036215T001.PDF 122036215-02.PDF

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Form 54-C (Rev. 4/62)-BOM-601036(62) 114

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

Date October 29, 1964 No. 60402 TEMPORARY

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. - - -

THIS CERTIFIES that the new—~~altered existing~~—building—premises located at 418 West 17th Street - Robert Fulton Houses Bldg # 2 Block 714 Lot 21,28,31, s/ 42, 50

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the ..... side of ..... distant ..... feet ..... from the corner formed by the intersection of ..... and .....

running thence * SEE ..... feet; thence ..... feet;

thence STATEMENT ..... feet; thence ..... feet;

running thence "A" ..... feet; thence ..... feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~New~~ No. 194-1960 Construction classification— Class 1, Fireproof

Occupancy classification— Hereafter Erected Class "A" Mult. Dwelling Height 25 stories, 214'-11 3/4" feet.

Date of completion— - - - Located in Unrestricted(datum 15.9') Zoning District.

at time of issuance of permit. 4638-1963

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: 131-63-BZY and The City Planning Commission: 101-SR (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Cellar	On ground		Storage and utilities.
1st story	100 75 40		Lobby. Perambulator room Three (3) apartments.
2nd to 25th story, incl.	40 each		Nine (9) apartments on each story.
			Standpipe System approved by Fire Department - October 21, 1964.
			NOTE: This is a TEMPORARY Certificate of Occupancy, issued to expire December 14, 1964.

THIS CERTIFICATE SHALL NOT BE CONSTRUED A CERTIFICATE ... USE ... UNDER ARTICLE 301 OF THE ... BUILDING LAW.

... (1960) Adm. Code ...

"Prior to the ... February ... structure as ... stated in the ... ily posied under ... class and maintained in the ... ance bell of ... structures"

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

Form 54-40M-7(16001503) 114

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

No. 40402

Date October 31, 1952

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No.

To the owner or owners of the building or premises: XXX XXXXX

THIS CERTIFIES that the new—altered—existing—building—premises located at 25 West 104th Street

Block 1840 Lot 26

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter ~~have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.~~ Class 3 nonfireproof

N.B. or Alt. No.— 253-52 Old Law Tenement Class "A" Construction classification— 53

Occupancy classification— Mult.Dwell.(Single room Occ.) Height 5 stories, residence feet.

Date of completion— October 23, 1952 Located in Use District.

B Area 1½ Height Zone at time of issuance of permit 657-1952

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
Cellar					Boiler room, storage, tenants' laundry and office for building.
1st story					Two (2) apartments, four (4) rooms, single room occupancy and one (1) room used as Manager's office.
2nd story				4 3 5	Two (2) apartments and five (5) rooms, single room occupancy.
3rd story					Two (2) apartments and one (1) vacant apartment.
4th & 5th stories					Fifteen (15) rooms, single room occupancy, on each story.
				NOTE:	The 3rd story front east apartment to remain vacant.
					Sprinkler system approved by Fire Department June 27, 1952. Fire Alarm system approved by Fire Department July 1, 1952. Watchman's Time Detector system approved by Fire Department July 1, 1952. Fuel Oil installation approved by Fire Department September 23, 1952.

Joseph S. Heenan
Borough Superintendent

(Page 1)

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form 54-C (Rev. 4/62)-80M-6010.06(62) 114

ac

DEPARTMENT OF BUILDINGS

TEMPORARY

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

Date December 21, 1964 No. 60670

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. 60402 Temp.

THIS CERTIFIES that the new—~~xxxxxxxxx~~—building—premises located at 418 West 17th Street -Robert Fulton Houses Bldg.#2 Block 714 Lot 21,28,31, & 42,50

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the ..... side of ..... distant ..... feet ..... from the corner formed by the intersection of ..... and .....

running thence *See ..... feet; thence ..... feet;

thence STATEMENT ..... feet, thence ..... feet;

running thence *A* ..... feet; thence ..... feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. or Alt. No.— ~~xxxx~~ 194-1960 Construction classification— Class 1 Fireproof

Occupancy classification— Hereafter Erected Class "A" Mult. Dwell. Height 25 stories, 214'-11 3/4" feet.

Date of completion— ------ Located in Unrestricted Zoning District.

at time of issuance of permit. 4638-1963 (datum 15.9'

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: 131-63-BZY **and The City Planning Commission:** (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Cellar	On ground		Storage and utilities.
1st Story	100 75 40		Lobby. Perambulator room Three (3) Apartments.
2nd to 25th Story, Incl.	40 each		Nine (9) apartments on each story.

Standpipe System approved by Fire Department - October 21, 1964.

NOTE: This is a TEMPROARY Certificate of Occupancy, issued for a period of ninety (90) days, commencing December 21, 1964.

NOTE: Time to complete construction is extended to December 15, 1965.

Sec. 6.1.2.3 ... Building Code, C.26-273.0 Adm. Code

"Prior to the occ... of a structure erected or altered after January 1, 1938, the aut... shall cause a ... of said structure as stated in the co... permanently posted under glass and maint... of such structures."

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

Form 54-C (Rev. 4/62)-80M-601036(62) 114

ac

DEPARTMENT OF BUILDINGS

TEMPORARY

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

Date March 24, 1965 No. 61185

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. 60670

THIS CERTIFIES that the new ~~erected or altered~~—building—premises located at 418 West 17th Street-Robert Fulton Houses Bldg.2 Block 714 Lot 21,28,31, & 48 & 50

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the ____ side of distant ____ feet from the corner formed by the intersection of ____ and ____

running thence ____ feet; thence ____ feet;
thence ____ feet; thence ____ feet;
running thence ____ feet; thence ____ feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~Bldg~~ Dt. No.— 194-1960 Construction classification— Class 1 Fireproof

Occupancy classification— Unrestricted Hereafter Erected . Height 25 stories 214'-11 3/4" feet.

Date of completion— Class "A" Fait. Shell. . Located in Unrestricted Zoning District.

at time of issuance of permit. 463-1963 (datum 15.9'

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: 131-63-BZY **and The City Planning Commission:** (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces ____

Off-Street Loading Berths ____

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE 61505
Cellar	On ground		Storage and utilities.
1st Story	100 75 40		Lobby. Perambulator room. Three (3) Apartments.
2nd to 25th Story, Incl.	40 each		Nine (9) apartments on each story.
			Standpipe System approved by Fire Department October 21, 1964.
		NOTE:	Time to complete construction is extended to December 15, 1965.
		NOTE:	This is a TEMPORARY Certificate of Occupancy, issued for a period of ninety (90) days, commencing March 24, 1965.
			Sec. 6.1.2.3 sub-4 Building Code, C.26-273.0 Adm. Code "Prior to the occupancy of a structure erected or altered after January 1, 1938, the authorized occupancy of each floor of said structure as stated in the certificate of occupancy shall be permanently posted under glass and maintained in the main entrance hall of such structures."

THIS CERTIFICATE SHALL ALSO BE CONSIDERED A CERTIFICATE OF COMPLIANCE OR OCCUPANCY UNDER SECTION 301 OF THE MULTIPLE DWELLING LAW.

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

Form 84 C (Rev. 4/62)-80M 601036(62) 114

ac

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

Date May 21, 1965 No. 61505

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. 61185 Temp.

THIS CERTIFIES that the new ~~building~~—building—premises located at 418 West 17th Street (Robert Fulton Houses Bldg.8 Block 714 Lot 21,28,31, 42 & 50

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the ..... side of ..... distant ..... feet from the corner formed by the intersection of ..... and .....

running thence #SEE STATEMENT S.A.# ..... feet; thence ..... feet; thence ..... feet; thence ..... feet; running thence ..... feet; thence .....

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~xxxx~~ No.— 194-1960 Construction classification— Class 1 Fireproof

Occupancy classification hereafter Erected Class "A" Mult. Dwell. Height 25 stories, 214'-11 3/8" feet. (Datum 15.97)

Date of completion—April 14, 1965 Located in Unrestricted Zoning District.

at time of issuance of permit. 2547-1962; 4638-1963

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals and The City Planning Commission: Cal.No. 131-63 Filed 12/9/63 approved 1/14/64 Extended to 12/15/65. (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Cellar	On ground	2	N.Y.Steam, storage, electric service room and incinerator room and tank and pump room.
1st Story	40 75 100		Three (3) Apartments, Perambulator room - and Building lobby.
2nd to 25th Story, Incl.	40 each		Nine (9) Apartments on each story.
		NOTE:	Outdoor Parking for twenty six (26) motor vehicles.
		NOTE:	Parking to be used exclusively for the parking of passenger motor vehicles of tenants on premises except as otherwise provided in Subdivision 1(b) of Section 60 of the Multiple Dwelling Law.
			Standpipe System approved by Fire Department October 21, 1964.
		NOTE:	Premises under control of New York City Housing Authority.

THIS CERTIFICATE DOES NOT INCLUDE ANY CONDITIONS KNOWN TO EXIST AT THE TIME OF ITS ISSUANCE WHICH MAY NOT CONFORM TO PROVISIONS OF THE BUILDING CODE OR OTHER LAWS OR REGULATIONS APPLICABLE THERETO.

Sec. 6.1.2.3 sub-4 Building Code, C.26-273.0 Adm. Code

Prior to the occupancy of a structure erected or altered after January 1, 1938, the ~~owner~~ agency of each floor of said structure as stated in the certificate of occupancy shall be permanently posted under glass and maintained in the main entrance hall of such structure.

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

Form 54-C (Rev. 4/62)-42M-701190(63) 114

DEPARTMENT OF BUILDINGS

ac

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

Date April 1, 1968 No. 65737

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate AMENDS supersedes C. O. No. 61505

THIS CERTIFIES that the ~~new~~ altered—~~existing~~—building—premises located at

418 West 17th Street; Building # 2 Block 714 Lot 31

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the side of

distant feet from the corner formed by the intersection of

and

running thence "SEE STATEMENT "A" feet; thence feet;

thence of Alt. 1591-1967 feet; thence feet;

running thence feet; thence feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646e of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

~~New~~ Alt. No.—1591-1967 Construction classification— Class 1 Fireproof

Occupancy classification— Hereafter Erected Class "C" Mult. Dwell. Height 25 stories, 214-11 3/4" feet.

Date of completion— March 28, 1968 Located in M 1-5, C 2-5 Zoning District.

at time of issuance of permit 956-1968

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: and The City Planning Commission: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces AMENDED C.O. #73863

Off-Street Loading Berths DATED 10-10-73

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Cel.	On Ground	2	N.Y.Steam, storage, electric service room and incinerator room and tank and pump room.
1st	40,75, 100		Three (3) apartments, tenants' association room and perambulator room.
2nd to 25th Incl.	40 each		Nine (9) apartments on each story.
		NOTE:	Outdoor parking for twenty-six (26) motor vehicles.
		NOTE:	Parking to be used exclusively for the parking of passenger motor vehicles of tenants of premises except as otherwise provided in Subdivision 1(b) of Section 60 of the Multiple Dwelling Law.
			Standpipe System approved by Fire Department October 21, 1964.
		NOTE:	Premises under control of New York City Housing Authority.
		NOTE:	This is an AMENDED Certificate of Occupancy.

THIS CERTIFICATE SHALL ALSO BE CONSIDERED A CERTIFICATE OF COMPLIANCE OR OCCUPANCY UNDER SECTION 301 OF THE MULTIPLE DWELLING LAW.

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

POSTING MUST BE POSTED WITHIN THE BUILDING IN ACCORDANCE WITH RULES OF THE DEPARTMENT PROMULGATED MARCH 31ST, 1967

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

Date October 10, 1973 No. 73853

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate ~~supersedes~~ amends C. O. No. 65737

THIS CERTIFIES that the ~~new—altered—existing—~~ building—~~premises~~ located at 418 West 17th Street - Fulton Houses—Bldg. #2 Block 714 Lot 31

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the ~~side of~~ southwest ~~feet from the~~ corner formed by the intersection of Ninth Avenue and West 17th Street

running thence south 164.04 feet; thence ~~west 374.00~~ feet;
thence ~~north 92.02~~ feet; thence ~~west 126.03~~ feet;
running thence ~~north 92.01~~ feet; thence ~~east 500.10~~ feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646e of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. or Alt. No.— 159-73 Construction classification— Class 1 fireproof

Occupancy classification— Hereafter Erected · Height 25 stories, 214'11 3/4 feet.

Date of completion— Class "A" Mult. Dwell. · Located in M 1-5, C 2-5 Zoning District.

at time of issuance of permit. October 2, 1973

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: and The City Planning Commission: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces

Off-Street Loading Berths

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Cellar	on ground		Storage, Electric service room, incinerator and tank rooms, pump room.
1st	40 75, 100 75	 3 5	Three (3) apartments, Lobby, Tenant Association room, Pest Control field office.
2nd to 25th incl.	40 each		Nine (9) apartments each floor.
		NOTE:	Outdoor parking for twenty-six (26) motor vehicles.
		NOTE:	This is an AMENDED Certificate of Occupancy for change of use on first (1st) story only.

THIS CERTIFICATE OF ... BE POSTED WITHIN THE BUILDING ... WITH THE RULES OF THE DEPARTMENT ... MARCH 31ST, 1967.

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

NYC Buildings

Certificate of Occupancy

CO Number: 122036215T001

This certifies that the premises described herein conforms substantially to the approved plans and specifications and to the requirements of all applicable laws, rules and regulations for the uses and occupancies specified. No change of use or occupancy shall be made unless a new Certificate of Occupancy is issued. *This document or a copy shall be available for inspection at the building at all reasonable times.*

A.

Borough: Manhattan	**Block Number:** 00714	**Certificate Type:** Temporary
Address: 418 WEST 17TH STREET	**Lot Number(s):** 31	**Effective Date:** 04/26/2016
Building Identification Number (BIN): 1078411	**Building Type:** Altered	**Expiration Date:** 07/25/2016

This building is subject to this Building Code: Prior to 1968 Code

For zoning lot metes & bounds, please see BISWeb.

B.

Construction classification: 1 (Prior to 1968 Code designation)

Building Occupancy Group classification: R-2 (2008 Code)

Multiple Dwelling Law Classification: HAEA

No. of stories: 25 **Height in feet:** 214 **No. of dwelling units:** 219

C.

Fire Protection Equipment:
Standpipe system, Fire alarm system, Sprinkler system

D.

Type and number of open spaces:
None associated with this filing.

E.

This Certificate is issued with the following legal limitations:
None

Outstanding requirements for obtaining Final Certificate of Occupancy:

There are 13 outstanding requirements. Please refer to BISWeb for further detail.

Borough Comments: None

Borough Commissioner

Commissioner

DOCUMENT CONTINUES ON NEXT PAGE

NYC Buildings

Certificate of Occupancy

CO Number: 122036215T001

Permissible Use and Occupancy

All Building Code occupancy group designations below are 2008 designations.

Floor From To	Maximum persons permitted	Live load lbs per sq. ft.	Building Code occupancy group	Dwelling or Rooming Units	Zoning use group	Description of use
CEL		OG	R-2		2	STORAGE, ELECTRIC SERVICE ROOM, INCINERATOR AND TANK ROOMS, PUMP ROOM
001	3	100	R-2		2	LOBBY, TENANT ASSOCIATION ROOM.
001	5	75	R-2		2	PEST CONTROL FIELD OFFICE
001		40	R-2	3	2	THREE (3) APARTMENTS
001	3	100	R-2		3	COMPUTER TRAINING FACILITY
002 025		40	R-2	9	2	NINE (9) APARTMENTS PER FLOOR

NOTE: OUTDOOR PARKING FOR TWENTY-SIX (26) MOTOR VEHICLES

END OF SECTION

Borough Commissioner

Commissioner

END OF DOCUMENT

NYC Buildings

Certificate of Occupancy

CO Number: 122036215T002

This certifies that the premises described herein conforms substantially to the approved plans and specifications and to the requirements of all applicable laws, rules and regulations for the uses and occupancies specified. No change of use or occupancy shall be made unless a new Certificate of Occupancy is issued. *This document or a copy shall be available for inspection at the building at all reasonable times.*

A.

Borough: Manhattan	**Block Number:** 00714	**Certificate Type:** Temporary
Address: 418 WEST 17TH STREET	**Lot Number(s):** 31	**Effective Date:** 08/03/2016
Building Identification Number (BIN): 1078411	**Building Type:** Altered	**Expiration Date:** 11/01/2016

This building is subject to this Building Code: Prior to 1968 Code

For zoning lot metes & bounds, please see BISWeb.

B.

Construction classification: 1 (Prior to 1968 Code designation)

Building Occupancy Group classification: R-2 (2014/2008 Code)

Multiple Dwelling Law Classification: HAEA

No. of stories: 25 **Height in feet:** 214 **No. of dwelling units:** 219

C. **Fire Protection Equipment:**
Standpipe system, Fire alarm system, Sprinkler system

D. **Type and number of open spaces:**
None associated with this filing.

E. **This Certificate is issued with the following legal limitations:**
None

Outstanding requirements for obtaining Final Certificate of Occupancy:

There are 13 outstanding requirements. Please refer to BISWeb for further detail.

Borough Comments: None

Borough Commissioner

Commissioner

DOCUMENT CONTINUES ON NEXT PAGE

NYC Buildings

Certificate of Occupancy

CO Number: 122036215T002

Permissible Use and Occupancy

All Building Code occupancy group designations below are 2008 designations.

Floor From To	Maximum persons permitted	Live load lbs per sq. ft.	Building Code occupancy group	Dwelling or Rooming Units	Zoning use group	Description of use
CEL		OG	R-2		2	STORAGE, ELECTRIC SERVICE ROOM, INCINERATOR AND TANK ROOMS, PUMP ROOM
001	3	100	R-2		2	LOBBY, TENANT ASSOCIATION ROOM.
001	5	75	R-2		2	PEST CONTROL FIELD OFFICE
001		40	R-2	3	2	THREE (3) APARTMENTS
001	3	100	R-2		3	COMPUTER TRAINING FACILITY
002 025		40	R-2	9	2	NINE (9) APARTMENTS PER FLOOR

NOTE: OUTDOOR PARKING FOR TWENTY-SIX (26) MOTOR VEHICLES

END OF SECTION

Borough Commissioner

Commissioner

END OF DOCUMENT

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

OATH/ECB Violation Details

Click here for more information about Severity, Violation and Hearing Statuses

Premises: 418 WEST 17 STREET MANHATTAN **Filed At: 418 WEST 17 STREET , MANHATTAN , NY 10011**

BIN: 1078411 Block: 714 Lot: 31 **Community Board: 104**

OATH/ECB Violation Summary

VIOLATION OPEN

OATH/ECB Violation Number: 35542581L

Severity: CLASS - 2 **Certification Status:** NO COMPLIANCE RECORDED

Penalty Balance Due: $0.00 **Hearing Status:** PUBLICLY-OWNED

Respondent Information

Name: NEWYORK CITY HOUSING AUTH **Publicly Owned**

Mailing Address: 90 CHURCH STREET , NEW YORK , NY 10007

Violation Details

Violation Date: 12/18/2020 **Violation Type:** CONSTRUCTION

Served Date: 12/18/2020 **Inspection Unit:** FACADE INSPECTION AND AUDIT UNIT

Infraction Codes	Section of Law	Standard Description
204	28-302.1	FAILURE TO MAINTAIN BUILDING WALL(S) OR APPURTENANCES

Specific Violation Condition(s) and Remedy:

FAILURE TO MAINTAIN EXTERIOR FACADE AND APPURTENANCES.SOUTH ELEVATIONEXPOSURE 3,OBSERVED STEP CRACKS ON FACADE LOCADED ON THE 11TH FLOOR,AIR CONDITIONED NOT PROPERLY SUPPORTED ON 18TH FLOOR.WEST ELEVATION EXPO

Issuing Inspector ID: 3340 **DOB Violation Number:** 12182020LLFAKA01

Issued as Aggravated Level: NO

Dept. of Buildings Compliance History and Events

Certification Status: NO COMPLIANCE RECORDED **Compliance On:**

A Certificate of Correction must be submitted to the Administrative Enforcement Unit (AEU) for all violations. A violation that is not dismissed by OATH/ECB will continue to remain ACTIVE or "open" on DOB records until acceptable proof is submitted to the AEU, even if you have paid the penalty imposed by OATH/ECB.

OATH/ECB Hearing Information

Hearing Status: PUBLICLY-OWNED

OATH/ECB Penalty Information

Penalty Imposed: $1,250.00

Adjustments: $-1,250.00 **Amount Paid:** $0.00

Penalty Balance Due: $0.00 **Court Docket Date:** 09/30/2021

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Work Permit Data

Premises: 418 WEST 17 STREET MANHATTAN **Filed At: 418 WEST 17 STREET MANHATTAN**

BIN: 1078411 Block: 714 Lot: 31 **Job Type: A2 - ALTERATION TYPE 2**

View Permit History | Printable (PDF) version of this Permit

DOB NOW: *Inspections*

Job No:	123040093			**Fee:**	EXEMPT
Permit No:	123040093-01-EW-MH	**Issued:**	06/01/2021	**Expires:**	05/31/2022
Seq. No.:	02	**Filing Date:**	06/01/2021 ERENEWAL	**Status:**	ISSUED
Work:		**Proposed Job Start:**	04/28/2021	**Work Approved:**	06/06/2017

ALTERATION TYPE 2 - MECH/HVAC
PARTIAL AND NON-STRUCTURAL INTERIOR DEMOLITION IN TRASH HOIST AREA AT BOTH CELLAR AND 1ST FLOOR, AS WELL AS, INSTALLATION OF NEW 2H.R. C.M.U WALL WITH A HOIST REPLACEMENT -VERTICAL RECIPROCATING CONVEYOR. AS WELL AS RE-ROUTING THE BRANCH PIPING ONLY FROM EXISTING DRAIN TO THE EXISTING LEADER. NO CHANGE IN USE,OCCUPANCY AND /OR ERGESS

Use: RES - RESID. BLDG - OLD CODE **Landmark:** NO **Stories:** 25

Site Fill: NOT APPLICABLE

Review is requested under Building Code: 2008

Total Number of Dwelling Units at Location:	216
Number of Dwelling Units Occupied During Construction:	216
Altering 10% or more of the existing floor surface area of the building:	No

Issued to: JOSEPH KRAJCZEWSKI

GC SAFETY REGISTRATION: GC 004331

Business: WDF INC

144 EAST 44TH STREET 8TH FL NEW YORK NY 10017

Phone: 212-696-1124

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Work Permit Data

Premises: 418 WEST 17 STREET MANHATTAN **Filed At: 418 WEST 17 STREET MANHATTAN**

BIN: 1078411 Block: 714 Lot: 31 **Job Type: A3 - ALTERATION TYPE 3**

View Permit History

Job No:	103151615			**Fee:**	EXEMPT
Permit No:	103151615-01-EQ-SH	**Issued:**	10/23/2003	**Expires:**	11/01/2004
Seq. No.:	03	**Filing Date:**	10/23/2003 RENEWAL	**Status:**	ISSUED
Work:		**Proposed Job Start:**	05/16/2002	**Work Approved:**	05/16/2002

ALTERATION TYPE 3 - CONSTRUCTION EQUIPMENT - SIDEWALK-SHED
INSTALLAATION OF HEAVY DUTY SIDEWALK SHE D DURING REMOVING ASBESTOS CONT
ININGROOFING MATERIALS NO CHANGE IN USE EGRESS OR OCCUPANCY.

Use: COM - COMMERCIAL BUILDINGS - OLD CODE **Landmark:** NO **Stories:** 0

Review is requested under Building Code: 1968

Issued to: EMMANUEL MICHIELAKIS

GENERAL CONTRACTOR: GC 020547

Business: AKRO GC INC
19-41 46TH ST ASTORIA NY 11105

Phone: 718-877-1666

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises:							BIN:	Block:	Lot:
VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE		NAME	

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

105 9 AVENUE **MANHATTAN 10011** **BIN# 1078418**

9 AVENUE	105 - 127	**Health Area**	: 5600	**Tax Block**	: 715
WEST 17 STREET	401 - 401	**Census Tract**	: 83	**Tax Lot**	: 10
WEST 18 STREET	400 - 400	**Community Board**	: 104	**Condo**	: NO
FULTON HOUSES BUILDING 7	NO NUMBER	**Buildings on Lot**	: 4	**Vacant**	: NO
FULTON HOUSES COMMUNITY CENTER	NO NUMBER				

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s): WEST 17 STREET, WEST 18 STREET
DOB Special Place Name:
DOB Building Remarks:

Landmark Status:		**Special Status:**	N/A
Local Law:	YES	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES

Additional BINs for Building: NONE
HPD Multiple Dwelling: Yes

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	17	0
Violations-DOB	53	1
Violations-OATH/ECB	9	0
Jobs/Filings	42	
ARA / LAA Jobs	3	
Total Jobs	45	
Actions	212	

OR Enter Action Type:
OR Select from List: Select...
AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 105 9 AVENUE MANHATTAN **BIN: 1078418 Block: 715 Lot: 10**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

COFO 23984:	M000023984.PDF
COFO 24749:	M000024749.PDF
COFO 40626:	M000040626.PDF
COFO 48063:	M000048063.PDF
COFO 29145:	M000029145.PDF
CO 60602TEMP:	M000060602.PDF
COFO 62735:	M000062735.PDF
COFO 27816:	M000027816.PDF
COFO 23984:	M000023984.PDF
COFO 24749:	M000024749.PDF
COFO 40626:	M000040626.PDF
COFO 48063:	M000048063.PDF
COFO 29145:	M000029145.PDF
COFO 60602-TEMP:	M000060602.PDF
COFO 62735:	M000062735.PDF
COFO 35639-TEMP:	M000035639.PDF
COFO 35668:	M000035668.PDF
COFO 60602-TEMP:	M000060602.PDF
COFO 35669:	M000035669.PDF
JOB 121914447:	121914447T001.PDF

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Form—344-1935 Certificate of Occupancy. 8A-2087-35-Bld

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

HVC CERTIFICATE OF OCCUPANCY No. 23984 193 8

Supersedes Certificate of Occupancy No.

To the owner or owners of the ~~building~~ lot New York September 28 1938.

THIS CERTIFIES that the ~~building~~ located on Block 715, Lot 29-30

known as 111-115 Ninth Avenue,

~~Under application No. 19 the application to the approved plans and specifications accompanying said application and amendments thereto and the requirements of the building code and of the rules and regulations of the board of standards and appeals applicable to a building of its class and kind except that in the case of a building in existence and for which a previous certificate of occupancy has been issued which has not been altered or converted since the 19 to a use that changed the classification of the building under the building code, this certificate confirms and continues the existing use for which the building has been heretofore used.~~

CERTIFIES FURTHER that the ~~building~~ lot ~~construction authorized by the above-mentioned application No.~~ ~~of the building erected~~ may be used and occupied as a parking and storage space ~~qualified~~, in a unrestricted district under the building zone resolution, subject to all the privileges, requirements, limitations and conditions prescribed by law or as hereinafter specified.

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED			USE
		MALE	FEMALE	TOTAL	
					Parking and storage of more than five (5) motor vehicles.
		Area of lot 52'10" x 100'0"			

This certificate is issued to Charles Dommar, 92-9th Avenue, City. , for the owner or owners.

The superimposed, uniformly distributed loads, or their equivalent concentrated loads in any story shall not exceed the live loads specified above; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

Unless specifically stated above, the building or any part thereof, if certified as a public building, shall not be used as a building in which persons are harbored to receive medical, charitable or other care or treatment, such as a hospital, asylum, etc., or in which persons are held or detained under legal restraint, such as a police station, jail, etc.; nor shall it be used as a motion picture theatre as defined in section 30, chapter 3, Code of Ordinances; nor as a theatre or opera house or other building intended to be used for theatrical or operatic purposes, or for public entertainment of any kind, for the accommodation of more than 300 persons.

Unless specifically stated above, the building or any part thereof, if certified as a residence building, shall not be used as a tenement house as defined in the tenement house law; nor shall it be used as any form of residence building having more than 15 sleeping rooms; nor shall it be used as a lodging house within the meaning of Sec. 1305 of the Greater New York Charter.

Unless specifically stated above, the building or any part thereof, if certified as a business building, shall not be used as a garage, motor vehicle repair shop or oil selling station as defined in section 1, chapter 10, Code of Ordinances; nor shall it be used for the generation or compression of acetylene; nor as a factory building as defined in the labor law; nor as a grain elevator; nor as a coal pocket.

Except as otherwise noted above, the building, or any part thereof, if located elsewhere than in an unrestricted district, shall not be used for any of the purposes enumerated in paragraph (a) of section 4 of the building zone resolution; nor for any trade, industry or use that is noxious or offensive by reason of the emission of odor, dust, smoke, gas or noise; nor for any kind of manufacturing not already prohibited, except that, if located in a business district, not more than twenty-five per cent. of the total floor space may be so used, or space equal to the area of the lot in any case.

Except as otherwise noted above, the building, if certified as a garage, may not be used for more than five cars on any portion of a street between two intersecting streets, in which portion there exists an exit from or an entrance to a public school, or in which portion there exists any hospital maintained as a charitable institution; and in no case within a distance of 200 feet from the the nearest exit from or entrance to a public school; nor within two hundred feet of any hospital maintained as a charitable institution.

If the building has, at any time previous to the issuance of this certificate, been the subject of an appeal to the board of appeals or of a petition to the board of standards and appeals resulting in modification or variation of law or any lawful requirement, the construction and arrangement of the building as specified in the resolution granting such modification or variation, must be maintained, and all conditions imposed by either board must be observed.

No change or re-arrangement in the structural parts of the building, or affecting the lighting or ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located, until an approval of the same has been obtained from the commissioner of buildings.

This certificate supersedes each and every previously issued certificate of occupancy for this building or any part thereof, and each and every such previously issued certificate shall be null and void; and this certificate in turn becomes null and void upon the issuance of any new lawful certificate.

This certificate does not in any way relieve the owner or owners, or any other person or persons in possession or control of the building, or any part thereof, from obtaining such other permits or licenses as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

This certificate does not authorize the use or operation of any elevator in the building without the special certificate required by section 563 of the building code.

If the building is or is required to be equipped with standpipes or other fire extinguishing or gas shut off appliances, this certificate is not complete until such standpipes or other appliances have been inspected by the fire department (or by the Tenement House Department in the case of a gas shut off in a tenement house) and approved in writing, either in a separate certificate or by endorsement upon this certificate. (Space for such endorsement is provided on page 4 of this certificate.)

If this certificate is marked "Temporary," it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to a tenement house unless also approved by the tenement house commissioner; and it must be replaced by a full certificate as soon as the entire building is completed according to law and ready for occupancy.

The word "class" as used in this certificate refers to the classification of buildings in the building code (section 70).

This certificate is issued in accordance with the provisions of section 411-a of the Greater New York Charter and of section 5 of chapter 5 (Building Code) of the Code of Ordinances of the City of New York.

Examined. A.H.M

Thomas J. Sullivan

Commissioner of Buildings, Borough of Manhattan.

Additional copies of this certificate will be issued, upon written request, for use in the building.

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN , CITY OF NEW YORK HVC

No. 24749

Date May 19,1939

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1 to 2.1.3.7 (Building Code).

This certificate supersedes C. O. No. 23984

To the owner or owners of the building or premises:

THIS CERTIFIES that the new—altered—existing building—premises located at

111-15 Ninth Avenue

52'10" front Block 715 Lot 29-30

conforms substantially to the approved plans and specifications and to the requirements of the building code and [illegible] and to the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and that all provisions of section 648C of the New York Charter have been complied with as certified by the Fire Commissioner to the Borough Superintendent.

N.B. or Alt. No. F.O.744-38 & Curb Cut permit M100-39 Construction classification

Occupancy classification— gasoline station and parking lot Height stories feet

Date of completion— . Located in unrestricted Use District.

Area Height Zone at time of issuance of permit

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
On ground					Gasoline service station and parking and storage of more than five (5) motor vehicles.
					Area of parking lot 52'10" x 100'0"
					One (1) 550 gallon gasoline tank approved by the Fire Department March 14,1939.

SUPERSEDED BY C.O. 40626

Borough Superintendent.

(P- 1)

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof, from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form 54-3581 701421(51) 114

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

No. 31626

Date December 30, 1952

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No. 24749

To the owner or owners of the building or premises:

THIS CERTIFIES that the new—~~alteration~~—building—~~addition~~—located at

111-117 Ninth Avenue

Block 715 Lot 29 & 31

~~This~~, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~Book~~ No.— 161-1949 Construction classification— Class 5 Retail

Occupancy classification— Commercial Bldg. Height 1 stories, 18'-8" & 16'-8" feet

Date of completion— December 22, 1952 Located in Unrestricted Use District.

A Area 2 Height Zone at time of issuance of permit 2519-1949

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft	PERSONS ACCOMMODATED			USE
		MALE	FEMALE	TOTAL	
1st Story	On ground				Motor Vehicle Repair Shop, Gasoline Service Station, Lubritorium, and Parking and storage of more than five (5) motor vehicles on unoccupied part of lot. Gasoline tanks approved by Fire Department September 22, 1950. Motor Vehicle Repair Shop approved by Fire Department September 22, 1950.

See 6133 [illegible]

Borough Superintendent

(Page 1)

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located;

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form 54-86M-713020(56) 114

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

No. 48063

Date October 3, 1957

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1 to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No. 40626

To the owner or owners of the building or premises:

THIS CERTIFIES that the new ~~altered existing~~ building—premises located at

115 Fifth Avenue Block 715 Lot 29-31

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~Permit~~ No.— 154-1956 Construction classification— Class 3 nonfireproof

Occupancy classification—Commercial Bldg. . Height 1 stories, 14 feet.

Date of completion—September 25, 1957 . Located in Unrestricted Use District.

1 Area 2 . Height Zone at time of issuance of permit 1027-1954;159-1957; 2528-1956

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
1st story	on ground	5		5	Gasoline service station, lubritorium, auto laundry, motor vehicle repair shop and Parking and storage of more than five (5) motor vehicles on vacant portion of premises.
					Gasoline tank installation approved by Fire Department May 1957.
					Fuel Oil installation approved by Fire Department September 3, 1957.

Sec. [illegible] C26-1278.0 Adm. Code

"Prior to [illegible] erected or altered after January 1, 1938, [illegible] each floor of said structure as stated in the [illegible] permanently posted under glass and maintained in the main entrance hall of such structure."

Borough Superintendent

CERTIFICATE WILL BE NULL AND VOID IF ALTERED IN ANY MANNER OR ADDITIONS ARE MADE THERETO

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form 55-20M-13041 -[redacted]-114

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN , CITY OF NEW YORK JS

No. 29145

Date July 11, 1942

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No.

To the owner or owners of the building or [redacted]

THIS CERTIFIES that the [redacted]—altered—[redacted]—building—[redacted] located at

119 Ninth Avenue
26'-1-1/2" front Block 715 Lot 32

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

[redacted]Alt. No.— 2043-41 Construction classification— Nonfireproof

Occupancy classification— Old Law Tenement Class A Mult.Dwlg. . Height 5 stories, 55 feet.

Date of completion— July 8, 1942 . Located in Unrestricted Use District.

A Area 2 . Height Zone at time of issuance of permit 3842-42

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
Cellar	on ground			2	Store and storage.
1st Story	120			15	Stores and two (2) apartments.
2nd Story	40				Four (4) apartments.
3rd Story	40				Four (4) apartments.
4th Story	40				Four (4) apartments.
5th Story	40				Four (4) apartments.

[redacted]

Borough Superintendent.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there by any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form 54-C (Rev. 4/62)-80M-601036(62) 114

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

Date December 9, 1964 No. 69602 TEMPORARY

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. 60024

THIS CERTIFIES that the new ~~erected~~ ~~altered~~ building—premises located at #7 117-121 Ninth Avenue - (Robt Fulton Hse Bldg) Block 715 Lot 10 to 50

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the W W Conor ~~xxxx~~ side of Nineth Avenue distant feet from the corner formed by the intersection of and

running thence S SEE feet; thence feet;
thence STATEMENT feet; thence feet;
running thence "A" feet; thence feet;
to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~Xxx~~ Alt. No. 196-1960 Construction classification Class 1, Fireproof
Occupancy classification Hereafter Erected Class "A" Mult. Dwellings. Height Bsmt & 6 stories, 60'-5" feet.
Date of completion ~~- - -~~ Located Unrestricted Zoning District.
at time of issuance of permit. 4638-1963

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: 196-63-BZY **and The City Planning Commission:** (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Cellar	On ground	2	Meter room.
Basement	100	270	Meeting room # 1, kitchen and kitchen storage,
		150	Club rooms and meeting room,
		26	Woodwork, arts and crafts,
	75	85	Perambulator, incinerator, tank and pump rooms.
		5	Offices, coat room.
	120		Examination room and storage.
1st to 6th story, incl.	40 each		Six (6) apartments on each story.
		NOTE:	Time to complete construction is extended to December 15, 1965.
		NOTE:	This is a TEMPORARY Certificate of Occupancy, issued for a period of ninety (90) days, commencing December 9, 1964.

...720 ...Bldg. Code
...for January
...structure is
...posted under
...of such structures."

...RECEIVED A CERTIFICATE
...301 OF THE

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

Form 54-C (Rev. 4/62)-80M-601036(62) 114

ac

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

Date January 27, 1966 No. [illegible]

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. 61089 Temp.

THIS CERTIFIES that the new ~~altered existing~~—building—premises located at 119 Ninth Avenue; Bldg. # 7(Robert Fulton Houses) Block 715 Lot 10 to 50

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the northwest ~~side~~ ~~distant~~ XXX feet from the corner formed by the intersection of 9th Avenue and West 17th Street

running thence *SEE STATEMENT "A" feet; thence ..... feet;

thence ..... feet; thence ..... feet;

running thence ..... feet; thence ..... feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~XXXX~~ No.— 199-1960 Construction classification— Class 1 Fireproof

Occupancy classification— Hereafter Erected Class 2 Mult. Dwell.; Height Bsmt. & 6 stories, 60'-5" feet.

Date of completion— December 14, 1965 ; Located in Unrestricted Zoning District.

at time of issuance of permit. 4638-1963

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals and The City Planning Commission: Cal. No. 136-63-BZY, Filed 12/9/63, approved 1/14/64, Extended to December 15, 1965 (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Cellar	On Ground	2	Gas meter room, electric service room and N.Y.Steam.
Basement	100	270	Meeting room # 1 with kitchen, kitchen storage and chair storage,
		57	Meeting room # 2,
		69 (Not more than (49 persons in (each club rm.	Two (2) club rooms.
		55	Woodworking room, arts and crafts room, library and toilets.
		107	Lounge and lobby.
	75	50	Director's offices, coat room, perambulator room, incinerator, tank and pump rooms.
	120		Nurses office, lab, examination rooms, reception and record room, waiting room, toilets and storage.
1st to 6th Story, Incl.	40 each		Six (6) apartments on each story.
		NOTE:	Outdoor parking for five (5) motor vehicles.
		NOTE:	Parking space to be used solely for the parking of passenger motor vehicles of tenants on premises except as otherwise provided in Subdivision 1(b) of Section 60 of the Multiple Dwelling Law.
NOTE:	Premises under control of New York City Housing Authority.		

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Sec. 6123. sub[illegible]

[illegible] Adm. Code

[illegible]r to the occup[illegible] sp[illegible] [illegible] the ed[illegible] form[illegible]

[illegible], 1968, the author[illegible] [illegible] said structure o[illegible]

stated in the certific[illegible] [illegible] [illegible] only permitted

[illegible]ss and maintain[illegible] [illegible] [illegible] of such occupa[illegible]

[illegible] CERTIFICATE SHALL ALSO BE CONSIDERED A CERTIFICATE
[illegible] COMPLIANCE OR OCCU[illegible] [illegible] SECTION 301 OF THE
[illegible] TYPLE DWELLING LAW.

Borough Superintendent

Form 55–20M-13041 114

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN , CITY OF NEW YORK HVC

No. 27816

Date June 17,1941

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No.

To the owner or owners of the building ~~or premises~~:

THIS CERTIFIES that the new—~~existing~~—building—~~premises~~ located at

109 Ninth Avenue-401-3 West 17th Street Block 715 Lot 29-30

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued: and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~Old~~ No.— 69-1941 Construction classification— metal

Occupancy classification— commercial . Height 1 stories, 10'0" feet.

Date of completion— June 4, 1941 . Located in unrestricted Use District.

A Area 2 . Height Zone at time of issuance of permit 1708-1941

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED			USE
		MALE	FEMALE	TOTAL	
Cellar					Storage
1st Story	100			45	Dining car

Sec. 6.1.2.3 sub-4 Building Code, C.26-272.0 Adm. Code

Prior to the occupation of any structure erected or altered after January 1st, 1938 the authorized occupancy of each floor of such structure, as stated in the certificate of occupancy, shall be permanently posted under glass and maintained in the main entrance hall of such structure.

Chester W Caudell

Borough Superintendent

(Page 1)

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there by any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form—344-1935 Certificate of Occupancy. BA-2087-35-Bro

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

HVC CERTIFICATE OF OCCUPANCY No. 23984 193 8

Supersedes Certificate of Occupancy No.

To the owner or owners of the ~~building~~ lot New York September 28 1938.

THIS CERTIFIES that the ~~building~~ located on Block 715 , Lot 29-30

known as 111-115 Ninth Avenue ,

~~under application No.~~ ~~19~~ ~~conforms to the approved plans and~~ ~~specifications accompanying said application and any approved amendments thereto and complies with the requirements~~ ~~of the building code and with other laws relating to the rules and regulations of the board of standards~~ ~~and appeals applicable to a building of its class and kind except that in the case of a building~~ ~~heretofore existing and for which a previous certificate of occupancy has been issued and which has~~ ~~not been altered or converted since March 1, 1938, to a use that changes the classification of use~~ ~~or occupancy, the certificate confirms and continues the existing use or uses for which the building has been~~ ~~used.~~

CERTIFIES FURTHER that the ~~building~~ ~~is~~ ~~erected~~ lot ~~on the above-~~ ~~mentioned lot~~ and may be used and occupied as a parking and storage space ~~for the following purposes~~ ~~qualified~~, in a unrestricted district under the building zone resolution, subject to all the privileges, requirements, limitations and conditions prescribed by law or as hereinafter specified.

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED			USE
		MALE	FEMALE	TOTAL	
					Parking and storage of more than five (5) motor vehicles.
		Area of lot 52'10" x 100'0"			

This certificate is issued to Charles Dommar, 92-9th Avenue, City. , for the owner or owners.

The superimposed, uniformly distributed loads, or their equivalent concentrated loads in any story shall not exceed the live loads specified above; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

Unless specifically stated above, the building or any part thereof, if certified as a public building, shall not be used as a building in which persons are harbored to receive medical, charitable or other care or treatment, such as a hospital, asylum, etc., or in which persons are held or detained under legal restraint, such as a police station, jail, etc.; nor shall it be used as a motion picture theatre as defined in section 30, chapter 3, Code of Ordinances; nor as a theatre or opera house or other building intended to be used for theatrical or operatic purposes, or for public entertainment of any kind, for the accommodation of more than 300 persons.

Unless specifically stated above, the building or any part thereof, if certified as a residence building, shall not be used as a tenement house as defined in the tenement house law; nor shall it be used as any form of residence building having more than 15 sleeping rooms; nor shall it be used as a lodging house within the meaning of Sec. 1305 of the Greater New York Charter.

Unless specifically stated above, the building or any part thereof, if certified as a business building, shall not be used as a garage, motor vehicle repair shop or oil selling station as defined in section 1, chapter 10, Code of Ordinances; nor shall it be used for the generation or compression of acetylene; nor as a factory building as defined in the labor law; nor as a grain elevator; nor as a coal pocket.

Except as otherwise noted above, the building, or any part thereof, if located elsewhere than in an unrestricted district, shall not be used for any of the purposes enumerated in paragraph (a) of section 4 of the building zone resolution; nor for any trade, industry or use that is noxious or offensive by reason of the emission of odor, dust, smoke, gas or noise; nor for any kind of manufacturing not already prohibited, except that, if located in a business district, not more than twenty-five per cent. of the total floor space may be so used, or space equal to the area of the lot in any case.

Except as otherwise noted above, the building, if certified as a garage, may not be used for more than five cars on any portion of a street between two intersecting streets, in which portion there exists an exit from or an entrance to a public school, or in which portion there exists any hospital maintained as a charitable institution; and in no case within a distance of 200 feet from the the nearest exit from or entrance to a public school; nor within two hundred feet of any hospital maintained as a charitable institution.

If the building has, at any time previous to the issuance of this certificate, been the subject of an appeal to the board of appeals or of a petition to the board of standards and appeals resulting in modification or variation of law or any lawful requirement, the construction and arrangement of the building as specified in the resolution granting such modification or variation, must be maintained, and all conditions imposed by either board must be observed.

No change or re-arrangement in the structural parts of the building, or affecting the lighting or ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located, until an approval of the same has been obtained from the commissioner of buildings.

This certificate supersedes each and every previously issued certificate of occupancy for this building or any part thereof, and each and every such previously issued certificate shall be null and void; and this certificate in turn becomes null and void upon the issuance of any new lawful certificate.

This certificate does not in any way relieve the owner or owners, or any other person or persons in possession or control of the building, or any part thereof, from obtaining such other permits or licenses as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

This certificate does not authorize the use or operation of any elevator in the building without the special certificate required by section 563 of the building code.

If the building is or is required to be equipped with standpipes or other fire extinguishing or gas shut off appliances, this certificate is not complete until such standpipes or other appliances have been inspected by the fire department (or by the Tenement House Department in the case of a gas shut off in a tenement house) and approved in writing, either in a separate certificate or by endorsement upon this certificate. (Space for such endorsement is provided on page 4 of this certificate.)

If this certificate is marked "Temporary," it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to a tenement house unless also approved by the tenement house commissioner; and it must be replaced by a full certificate as soon as the entire building is completed according to law and ready for occupancy.

The word "class" as used in this certificate refers to the classification of buildings in the building code (section 70).

This certificate is issued in accordance with the provisions of section 411-a of the Greater New York Charter and of section 5 of chapter 5 (Building Code) of the Code of Ordinances of the City of New York.

Examined. A.H.M

Commissioner of Buildings, Borough of Manhattan.

Additional copies of this certificate will be issued, upon written request, for [illegible] in the building.

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN , CITY OF NEW YORK HVC

No. 24749

Date May 19,1939

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1 to 2.1.3.7 Building Code).

This certificate supersedes C. O. No. 23984

To the owner or owners of the building or premises:

THIS CERTIFIES that the new—altered—existing—building—premises located at

111-15 Ninth Avenue

52'10" front Block 715 Lot 29-30

conforms substantially to the approved plans and specifications and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals applicable to a building of its class and kind at the time the permit was issued, and

CERTIFIES FURTHER that any provisions of section 646 of the New York Charter have been complied with, and that the Commissioner finds the premises safe and fit for the following purposes and that the use and occupancy is classified as follows:

N.B. as Alt. No. F.O.744-38 & Curb Cut permit M100-39 Construction classification

Occupancy classification— gasoline station and parking lot Height stories feet

Date of completion— . Located in unrestricted Use District.

Area Height Zone at time of issuance of permit

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
On ground					Gasoline service station and parking and storage of more than five (5) motor vehicles.
					Area of parking lot 52'10" x 100'0"
					One (1) 550 gallon gasoline tank approved by the Fire Department March 14,1939.

SUPERSEDED BY C.O. 40626

Borough Superintendent.

(P. - 1)

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof, from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form 54-35M 701421(51) 114

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

No. 396826

Date December 30, 1952

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 21.3.1. to 21.3.7. Building Code.)

This certificate supersedes C. O. No. 24749

To the owner or owners of the building or premises:

THIS CERTIFIES that the new—~~alteration~~—building—~~premises~~—located at

111-117 Ninth Avenue Block 715 Lot 29 & 31

———, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~Application~~ No.— 161-1949 Construction classification— Class 5 Metal

Occupancy classification— Commercial Bldg. . Height 1 stories, 18'-8" & 16'-6" feet.

Date of completion— December 22, 1952 . Located in Unrestricted Use District.

A Area 2 . Height Zone at time of issuance of permit 2519-1949

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
1st story	On ground				Motor Vehicle Repair Shop, Gasoline Service Station, Lubritorium, and Parking and storage of more than five (5) motor vehicles on unoccupied part of lot. Gasoline tanks approved by Fire Department September 22, 1950. Motor Vehicle Repair Shop approved by Fire Department September 22, 1950.

See 6123

Borough Superintendent

(Page 1)

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located;

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire-alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form 54-86M-713020(56) 114

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN , THE CITY OF NEW YORK

No. 48063

Date October 3, 1957

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No. 40626

To the owner or owners of the building or premises:

THIS CERTIFIES that the new ~~altered existing~~ building—premises located at

115 Fifth Avenue Block 715 Lot 29-31

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~Amdt.~~ No.— 154-1956 Construction classification— nonfireproof Class 3

Occupancy classification—Commercial Bldg. . Height 1 stories, 14 feet.

Date of completion—September 25, 1957 . Located in Unrestricted Use District.

1 Area 2 . Height Zone at time of issuance of permit 1027-1954; 159-1957; 2528-1956

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
1st story	on ground	5		5	Gasoline service station, lubritorium, auto laundry, motor vehicle repair shop and Parking and storage of more then five (5) motor vehicles on vacant portion of premises.
					Gasoline tank installation approved by Fire Department May 1957.
					Fuel Oil installation approved by Fire Department September 3, 1957.
					Sec. C26-[illegible] C26-[illegible].0 Adm. Code "Prior to the [illegible] constructed or altered after January 1, 1938, [illegible] each floor of said structure as stated in the [illegible] permanently posted under glass and maintained in the main entrance hall of such structure."

Thomas F. Conlon

Borough Superintendent

CERTIFICATE WILL BE NULL AND VOID IF ALTERED IN ANY MANNER OR ADDITIONS ARE MADE THERETO

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form 55-2M-11041 -4[illegible]-114

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK JS

No. 29145

Date July 11, 1942

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No.

To the owner or owners of the building or [illegible]

THIS CERTIFIES that the [illegible]—altered—[illegible]—building—[illegible] located at

119 Ninth Avenue
26'-1-1/2" front Block 715 Lot 32

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

[illegible] Alt. No.— 2043-41 Construction classification— Nonfireproof

Occupancy classification— Old Law Tenement Class A Mult.Dwlg. Height 5 stories, 55 feet.

Date of completion— July 8, 1942 Located in Unrestricted Use District.

A Area 2 Height Zone at time of issuance of permit 3842-42

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
Cellar	on ground			2	Store and storage.
1st Story	120			15	Stores and two (2) apartments.
2nd Story	40				Four (4) apartments.
3rd Story	40				Four (4) apartments.
4th Story	40				Four (4) apartments.
5th Story	40				Four (4) apartments.

[illegible]

Borough Superintendent.

(Page 1)

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there by any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form 54-C (Rev. 4/62)-80M-6010.36(62) 114

DEPARTMENT OF BUILDINGS

ob

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

Date December 9, 1964 No. 60602 TEMPORARY

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. 60024

THIS CERTIFIES that the new ~~extended alteration~~ building—premises located at #7 117-121 Ninth Avenue - (Robt Fulton Hse Ple) Block 715 Lot 10 to 50

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the NW Corner ~~xxxxx~~ side of Nineth Avenue distant feet from the corner formed by the intersection of and

running thence SEE feet; thence feet;
thence STATEMENT feet; thence feet;
running thence "A" feet; thence feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~Xxx~~ Alt. No. 197-1960 Construction classification Class 1, Fireproof

Occupancy classification Hereafter Erected Class "A" Mult. Dwellings. Height Bsmt & 6 stories, 60'-5" feet. Date of completion— Located Unrestricted Zoning District.

at time of issuance of permit. 4638-1963

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: 136-63-BZY and The City Planning Commission: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Cellar	On ground	2	Meter room.
Basement	100	270	Meeting room # 1, kitchen and kitchen storage.
		150	Club rooms and meeting room.
		26	Woodwork, arts and crafts.
	75	85	Perambulator, incinerator, tank and pump rooms.
		5	Offices, coat room.
	120		Examination room and storage.
1st to 6th story, incl.	40 each		Six (6) apartments on each story.
		NOTE:	Time to complete construction is extended to December 15, 1965.
		NOTE:	This is a TEMPORARY Certificate of Occupancy, issued for a period of ninety (90) days, commencing December 9, 1964.

...730 Adm. Code
...ued after January
...ch structure as
...conspicuously posted under
...ion hall of such structures."

...ISSUED A CERTIFICATE
...301 OF THE

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

Form 54-C (Rev. 4/62)-80M-601036(62) 314

ac

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

Date January 27, 1966 No. 62335

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. 61089 Temp.

THIS CERTIFIES that the new ~~altered existing~~—building—premises located at 119 Ninth Avenue; Bldg. # 7(Robert Fulton Houses) Block 715 Lot 10 to 50

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the northwest ~~side~~ ~~distant~~ ~~feet~~ from the corner formed by the intersection of 9th Avenue and West 17th Street

running thence *SEE STATEMENT "A" feet; thence ..... feet;

thence ..... feet; thence ..... feet;

running thence ..... feet; thence ..... feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~M.D.~~ No.— 199-1960 Construction classification— Class 1 Fireproof

Occupancy classification—Hereafter Erected Class 5 Mult. Dwell.; Height Bsmt. & 6 stories, 60'-5" feet.

Date of completion— December 14, 1965 ; Located in Unrestricted Zoning District.

at time of issuance of permit. 4638-1963

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals and The City Planning Commission: Cal. No. 136-63-BZY, Riled 12/9/63, approved 1/14/64, Extended to December 15, 1965 (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Cellar	On Ground	2	Gas meter room, electric service room and N.Y.Steam.
Basement	100	270	Meeting room # 1 with kitchen, kitchen storage and chair storage.
		57	Meeting room # 2,
		69 (Not more than 49 persons in each club rm.)	Two (2) club rooms.
		55	Woodworking room, arts and crafts room, library and toilets.
		107	Lounge and lobby.
	75	50	Director's offices, coat room, perambulator room, incinerator, tank and pump rooms.
	120		Nurses office, lab, examination rooms, reception and record room, waiting room, toilets and storage.
1st to 6th Story, Incl.	40 each		Six (6) apartments on each story.
		NOTE:	Outdoor parking for five (5) motor vehicles.
		NOTE:	Parking space to be used solely for the parking of passenger motor vehicles of tenants on premises except as otherwise provided in Subdivision 1(b) of Section 60 of the Multiple Dwelling Law.
NOTE:	Premises under control of New York City Housing Authority.		

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Sec. 6123 sub [illegible] Bldg. [illegible] Adm. Code
[illegible] prior to the occup[illegible] [illegible] or like ad[illegible] [illegible]
[illegible] 1903, the author[illegible] [illegible] said structure a[illegible]
stated in the certific[illegible] [illegible] [illegible] only permitted
[illegible] and maintained in the [illegible] [illegible] of such [illegible]

[illegible] CERTIFICATE SHALL ALSO BE CONSIDERED A CERTIFICATE
[illegible] COMPLIANCE OR OCCU[illegible] [illegible] SECTION 301 OF THE
[illegible] TIPLE DWELLING LAW.

Borough Superintendent

55-22M-71145 414

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

No.

Date May 17th, 1949

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No. 17609

To the owner or owners of the building or premises:

THIS CERTIFIES that the ~~new~~—altered—existing—building—~~premises~~ located at

2015-2021 Fifth Avenue - 2 East 125th Street Block 1749 Lot s.69, 70, 70½,

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. or Alt. No.— 1597-1947

Occupancy classification— Heretofore Erected Existing Class "A" Hotel

Construction classification— Class 3 Nonfireproof

Height 4 stories, 48 feet.

Date of completion— May 14, 1949

Area B 1½ Located in business Use District.

Height Zone at time of issuance of permit 50-1948; 2865-1947

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (If regular numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	Use
Cellar	on ground				Storage for stores & boiler room.
1st story	120	40	18	58	(Five (5) stores, restaurant and (luncheonette.
2nd story	120	20	10	30	(Four (4) hotel rooms, hotel office, (business offices, dining room in (conjunction with first story (restaurant.
3rd story	40				Twenty-three (23) hotel rooms
4th story	40				Twenty-four (24) hotel rooms.

This building complies with Section 67 of the Multiple Dwelling Law.

Interior Fire Alarm approved by Fire Department May 16, 1949.

Watchman's Time Detector approved by Fire Department May 16, 1949.

Sprinkler System approved by Plumbing Division May 14, 1949.

Borough Superintendent.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 6[illegible]. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy

55-22M-71145 114

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

No.

Date May 23, 1949

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No. 16833-

To the owner or owners of the building or premises:

THIS CERTIFIES that the ~~new~~ altered ~~existing~~ building—premises located at

145 Central Park West, 1-7 West 74th street, 2-4 West 75th street. Block 1127 Lot 29

———, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent. Class 1

~~N.B.~~ Alt. No.— 524-1942 Construction classification— Fireproof.

Occupancy classification—Hereafter Erected Class A Mult.Dwell. Height 27 stories, 298' 4" feet.

Date of completion— May 16, 1949 Located in Residence Use District.

B Area 1½ Height Zone at time of issuance of permit 2410-1948

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
Cellar	on ground				Boiler room, storage and Tenants' laundry.
1st story					One (1) Doctor's apartment and office, one (1) superintendent's apartment, nine (9) Maid's rooms and doctor's offices.
2d story					Eight (8) apartments.
3d story					Seven (7) apartments.
4th-8th story incl.					Eight (8) apartments on each story.
9th & 10th stories,					Seven (7) apartments on each story.
11th story					Nine (9) apartments.
12th story					Seven (7) apartments.
13th story					Eight (8) apartments.
14th & 15th stories,					Seven (7) apartments on each story.
16th story					Five (5) apartments.
17th story					Four (4) apartments.
18th-25th story, incl.					Two (2) apartments on each story.
26th story					One (1) apartment and One-half (½) apartment.
27th story					One (1) apartment and one-half (½) apartment.
					Standpipe system approved by Fire Department. April 26, 1949.

Borough Superintendent.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form 54-C (Rev. 4/62)-80M-6010J6(62) 114

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

Date December 9, 1964 No. 60602

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. 60024

THIS CERTIFIES that the new ~~erected~~ ~~altered~~ building—premises located at #7 117-121 Ninth Avenue - (Robt Fulton Hse Bldg) Block 715 Lot 10 to 50

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the ~~xxxxx~~ side of Ninth Avenue distant N W Corner feet from the corner formed by the intersection of and

running thence S SEE ..... feet; thence ..... feet;
thence ..... STATEMENT ..... feet; thence ..... feet;
running thence ..... "A" ..... feet; thence ..... feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~Xxx~~ Alt. No. 177-1960 Construction classification Class 1, Fireproof

Occupancy classification Hereafter Erected Class "A" Mult. Dwellings. Height Bsmt & 6 stories, 60'-5" feet. Located Unrestricted Zoning District.

Date of completion ~~- - -~~ at time of issuance of permit. 4638-1963

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: 136-63-BZY **and The City Planning Commission:** (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Cellar	On ground	2	Meter room.
Basement	100	270	Meeting room # 1, kitchen and kitchen storage.
		150	Club rooms and meeting room.
		26	Woodwork, arts and crafts,
	75	65	Perambulator, incinerator, tank and pump rooms.
		5	Offices, coat room.
	120		Examination room and storage.
1st to 6th story, incl.	40 each		Six (6) apartments on each story.
		NOTE:	Time to complete construction is extended to December 15, 1965.
		NOTE:	This is a TEMPORARY Certificate of Occupancy, issued for a period of ninety (90) days, commencing December 9, 1964.

730 ... Code
... for January
... structure is
... posted under
... such structures."

... CERTIFICATE
... 301 OF THE

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

55-22M-71145 114

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN , CITY OF NEW YORK

No.

Date May 23, 1949

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No. 35639-

To the owner or owners of the building or premises:

THIS CERTIFIES that the new—altered—existing—building—premises located at

121 Ninth Avenue Block 715 Lot 33

———— , conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

Bldg. Alt. No.— 1164-1945 Construction classification— Class 3 nonfireproof

Occupancy classification— Commercial and Residence , Height 2 stories, 27 feet.

Date of completion— May 23, 1949 , Located in unrestricted Use District.

A Area 2 times Height Zone at time of issuance of permit 2092-1946, 1341-1946

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED			USE
		MALE	FEMALE	TOTAL	
Cellar	on ground				Boiler room and storage.
1st story	120	9	1	10	Store.
2d story					Two (2) apartments.

Borough Superintendent.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

NYC Buildings

Certificate of Occupancy

CO Number: 121914447T001

This certifies that the premises described herein conforms substantially to the approved plans and specifications and to the requirements of all applicable laws, rules and regulations for the uses and occupancies specified. No change of use or occupancy shall be made unless a new Certificate of Occupancy is issued. *This document or a copy shall be available for inspection at the building at all reasonable times.*

A.

Borough: Manhattan	**Block Number:** 00715	**Certificate Type:** Temporary
Address: 119 9TH AVENUE	**Lot Number(s):** 10	**Effective Date:** 02/03/2021
Building Identification Number (BIN): 1078418	**Building Type:** Altered	**Expiration Date:** 05/04/2021

This building is subject to this Building Code: Prior to 1968 Code

For zoning lot metes & bounds, please see BISWeb.

B.

Construction classification: 1 (Prior to 1968 Code designation)

Building Occupancy Group classification: R-2 (2014/2008 Code)

Multiple Dwelling Law Classification: HAEA

No. of stories: 6 **Height in feet:** 60 **No. of dwelling units:** 0

C. **Fire Protection Equipment:**
Fire alarm system, Sprinkler system

D. **Type and number of open spaces:**
None associated with this filing.

E. **This Certificate is issued with the following legal limitations:**
Board of Standards and Appeals - Recording Info: 136-63-BZY

Outstanding requirements for obtaining Final Certificate of Occupancy:

There are 15 outstanding requirements. Please refer to BISWeb for further detail.

Borough Comments: None

Borough Commissioner

Commissioner

DOCUMENT CONTINUES ON NEXT PAGE

NYC Buildings

Certificate of Occupancy

CO Number: 121914447T001

Permissible Use and Occupancy

All Building Code occupancy group designations below are 2008 designations.

Floor From	To	Maximum persons permitted	Live load lbs per sq. ft.	Building Code occupancy group	Dwelling or Rooming Units	Zoning use group	Description of use
CEL		2	OG	U		2	GAS METER ROOM, ELECTRIC SERVICE ROOM AND N.Y.STEAM.
BAS		19	100	R-2		2	UNISEX HANDICAP TOILET, JANITOR CLOSET, CHAIR/TABLE STORAGE, ACCESSORY OFFICES, TEACHING KITCHEN, PANTRY, KITCHEN AND I.T. ROOM.
BAS		270	100	R-2 A-3		2	MEETING ROOM #1
BAS		57	100	R-2		2	MEETING ROOM #2
BAS		74	100	R-2		2	CLUB ROOM(NOT MORE THAN 74 PERSONS IN BOTH ROOMS)
BAS		55	100	R-2		2	CLASSROOMS,CLOSET, STORAGE
BAS		20	100	R-2		2	LOUNGE AREA CLOSETS, ELECTRICAL CLOSET #1, JANITOR CLOSET, KITCHEN STORAGE,TOILET, LOCKER ROOM, CHEF AND COOK OFFICE, LOBBY AND RECEPTION AREA.
BAS		27	75	R-2		2	COAT ROOM, COAT CLOSET, PERAMBULATOR ROOM, INCINERATOR, TANK AND PUMP ROOM GALLERY, VESTIBULE, OFFICE
BAS		18	120	R-2		2	OPEN SPACE OFFICES, UNISEX STAFF TOILETS, WOMEN AND MENS TOILETS, MEETING ROOM, ELECTRICAL CLOSET #2 AND STORAGE ROOM.
001	006		40	R-2	6	2	SIX (6) APARTMENTS PER FLOOR

NOTE: OUTDOOR PARKING FOR FIVE (5) MOTOR VEHICLES. PARKING SPACE TO BE USED SOLELY FOR THE PARKING OF PASSENGER MOTOR VEHICLES OF TENANTS ON PREMISES EXCEPT AS OTHERWISE PROVIED IN SUBDIVISIONÜ (B) IF THE MULTILPE LAW. NOTE: PRESMISES UNDER CONTROL OF NEW YORK CITY HOUSING AUTHORITY

END OF SECTION

Borough Commissioner

Commissioner

END OF DOCUMENT

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

DOB Violation Display for 062021EARCX00078

Premises: 105 9 AVENUE MANHATTAN **BIN: 1078418 Block: 715 Lot: 10**

Issue Date:	06/20/2021	**Violation Category:**	V - DOB VIOLATION - ACTIVE
Violation Type:	EARCX - FAILURE TO SUBMIT EER		
Violation Number:	00078	**Device No.:**	
OATH/ECB No.:			
Infraction Codes:			
Description:	FAILURE TO SUBMIT AN EER PER AD. CODE SEC. 28-308.4 - MULTIPLE YEARS (2020)		
Disposition:			
Code:		**Date:**	
Inspector:			
Comments:			

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Work Permit Data

Premises: 105 9 AVENUE MANHATTAN **Filed At: 119 9TH AVE. MANHATTAN**

BIN: 1078418 Block: 715 Lot: 10 **Job Type: A2 - ALTERATION TYPE 2**

View Permit History

DOB NOW: *Inspections*

Job No:	123211540			**Fee:**	EXEMPT
Permit No:	123211540-02-EW-MH	**Issued:**	09/16/2019	**Expires:**	05/01/2020
Seq. No.:	02	**Filing Date:**	09/16/2019 ERENEWAL	**Status:**	ISSUED
Work:		**Proposed Job Start:**	04/10/2019	**Work Approved:**	05/07/2018

ALTERATION TYPE 2 - MECH/HVAC
COMMUNITY CENTER RENOVATION - REMOVAL OF EXISTING INTERIOR PARTITIONS, PLUMBING CHASE WALLS AND METAL PARTITIONS, REMOVAL OF INTERIOR METAL DOORS, FRAMES, HARDWARE, TRIM AND RELATED ITEMS, REMOVAL OF EXISTING PLUMBING FIXTURES AND CAPPING OF EXISTING PIPES. NO NEW PLUMBING WORK. NO CHANGE IN USE, EGRESS OR OCCUPANCY.

Use: RES - RESID. BLDG - OLD CODE **Landmark:** NO **Stories:** 6
Site Fill: NOT APPLICABLE
Review is requested under Building Code: 1968

Total Number of Dwelling Units at Location: 36
Number of Dwelling Units Occupied During Construction: 36
Altering 10% or more of the existing floor surface area of the building: No

Issued to: AHMAD REYAZ

GENERAL CONTRACTOR - NON-REGISTERED: GC 014698

Business: ACS SYSTEM ASSOCIATES INC
160 WEST LINCOLN AVE MOUNT VERNON NY 10550 **Phone:** 914-665-5800

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Work Permit Data

Premises: 105 9 AVENUE MANHATTAN **Filed At: 119 9TH AVE. MANHATTAN**

BIN: 1078418 Block: 715 Lot: 10 **Job Type: A2 - ALTERATION TYPE 2**

View Permit History

DOB NOW: *Inspections*

Job No:	123211540			**Fee:**	EXEMPT
Permit No:	123211540-01-EW-MH	**Issued:**	05/01/2020	**Expires:**	05/01/2021
Seq. No.:	03	**Filing Date:**	05/01/2020 ERENEWAL	**Status:**	ISSUED
Work:		**Proposed Job Start:**	04/10/2019	**Work Approved:**	05/07/2018

ALTERATION TYPE 2 - MECH/HVAC
COMMUNITY CENTER RENOVATION - REMOVAL OF EXISTING INTERIOR PARTITIONS, PLUMBING CHASE WALLS AND METAL PARTITION, REMOVAL INTERIOR METAL DOORS, FRAMES, HARDWARE, TRIM AND RELATED ITEMS. NO CHANGE IN USE, EGRESS OR OCCUPANCY.

Use: RES - RESID. BLDG - OLD CODE **Landmark:** NO **Stories:** 6

Site Fill: NOT APPLICABLE

Review is requested under Building Code: 1968

Total Number of Dwelling Units at Location: 36

Number of Dwelling Units Occupied During Construction: 36

Altering 10% or more of the existing floor surface area of the building: No

---

Issued to: AHMAD REYAZ

GENERAL CONTRACTOR - NON-REGISTERED: GC 014698

Business: ACS SYSTEM ASSOCIATES INC
160 WEST LINCOLN AVE MOUNT VERNON NY 10550

Phone: 914-665-5800

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Work Permit Data

Premises: 105 9 AVENUE MANHATTAN **Filed At: 119 9 AVENUE MANHATTAN**

BIN: 1078418 Block: 715 Lot: 10 **Job Type: A2 - ALTERATION TYPE 2**

View Permit History

DOB NOW: *Inspections*

Job No:	122003465			**Fee:**	EXEMPT
Permit No:	122003465-01-EW-MH	**Issued:**	04/26/2019	**Expires:**	11/30/2020
Seq. No.:	03	**Filing Date:**	04/26/2019 ERENEWAL	**Status:**	ISSUED
Work:		**Proposed Job Start:**	11/21/2017	**Work Approved:**	05/30/2014

ALTERATION TYPE 2 - MECH/HVAC
PROPOSED FILING FOR MECHANICAL WORK TO REMOVE EXISTING UNIT VENTILATOR FANS, DUCT WORK AND LIMITED FIN TUBE RADIATORS. REPLACE WITH NEW SPLIT TYPE UNIT VENTILATORS, VARIABLE REFRIGERANT FLOW TYPE SPLIT HEAT PUMP SYSTEM, LIMITED FIN TUBE RADIATOR REPLACEMENT, PIPING, NEW EXHAUSTS, SHEET METAL AND CONTROLS. FILED ALL AS PER PLANS HEREWITH.

Use: RES - RESID. BLDG - OLD CODE **Landmark:** NO **Stories:** 6

Site Fill: NOT APPLICABLE

Review is requested under Building Code: 2008

Issued to: AHMAD REYAZ

GENERAL CONTRACTOR - NON-REGISTERED: GC 014698

Business: ACS SYSTEM ASSOCIATES INC
160 WEST LINCOLN AVE MOUNT VERNON NY 10550

Phone: 914-665-5800

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Work Permit Data

Premises: 105 9 AVENUE MANHATTAN **Filed At: 119 9TH AVE. MANHATTAN**

BIN: 1078418 Block: 715 Lot: 10 **Job Type: A2 - ALTERATION TYPE 2**

Job No:	120239811			**Fee:**	EXEMPT
Permit No:	120239811-01-EW-MH	**Issued:**	01/21/2010	**Expires:**	05/01/2010
Seq. No.:	01	**Filing Date:**	01/11/2010 INITIAL	**Status:**	ISSUED
Work:		**Proposed Job Start:**	01/21/2010	**Work Approved:**	01/11/2010

ALTERATION TYPE 2 - MECH/HVAC

REPLACEMENT OF AIR CONDITIONING UNITS.NO CHANGE IN USE EGRESS OR OCCUPANCY.

Use: RES - RESID. BLDG - OLD CODE **Landmark:** N/A **Stories:** 6

Site Fill: NOT APPLICABLE

Review is requested under Building Code: 2008

Issued to: RUDOLPH SAPORITO

GENERAL CONTRACTOR - NON-REGISTERED: GC 003924

Business: COMMERCIAL COOLING SERVIC

225 49TH STREET BROOKLYN NY 11220

Phone: 718-492-2691

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Work Permit Data

Premises: 105 9 AVENUE MANHATTAN **Filed At: 117 NINTH AVENUE MANHATTAN**

BIN: 1078418 Block: 715 Lot: 10 **Job Type: A3 - ALTERATION TYPE 3**

View Permit History

Job No:	103151740			**Fee:**	EXEMPT
Permit No:	103151740-01-EQ-SH	**Issued:**	11/07/2002	**Expires:**	11/01/2003
Seq. No.:	02	**Filing Date:**	11/07/2002 RENEWAL	**Status:**	ISSUED
Work:		**Proposed Job Start:**	05/16/2002	**Work Approved:**	05/16/2002

ALTERATION TYPE 3 - CONSTRUCTION EQUIPMENT - SIDEWALK-SHED
INSTALLATION OF HEAVY DUTY SIDEWALK SHED DURING REMOVING ASBESTOS-CONTAINING ROOFING MATERIALS. NO CHANGE IN USE, EGRESS OR OCCUPANCY.

Use: E - BUSINESS **Landmark:** NO **Stories:** 0

Review is requested under Building Code: 1968

Issued to: EMMANUEL MACHELAKIS

GENERAL CONTRACTOR: GC 020547

Business: AKRO GENERAL CONTR. INC.
19 41 46TH STREET ASTORIA NY 11105

Phone: 718-777-1666

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises: **BIN:** **Block:** **Lot:**

VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE	NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Environmental Protection

Register with CATS
Login into CATS

NYC.gov always open

NYC DEP CATS Information

SEARCH INFORMATION

Searching For Data...

Contacting Database...Please Wait

Search By :	BBL
***Application# :**	
***Borough :**	Manhattan
***Block :**	715
***Lot :**	10
***Premise House# :**	
***Premise Street :**	
***Premise Borough :**	-- Select Borough --
***Captcha :**	Input symbols

Search Clear

No Record Found.

Please be advised that application numbers starting with 'C' are associated to boilers, 'P' are associated with industrials and 'G' are associated with Gas stations.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

417 WEST 17 STREET — **MANHATTAN 10011** — **BIN# 1078419**

WEST 17 STREET	417 - 421	Health Area	: 5600	Tax Block	: 715
WEST 18 STREET	420 - 432	Census Tract	: 83	Tax Lot	: 10
FULTON HOUSES BUILDING 6	NO NUMBER	Community Board	: 104	Condo	: NO
		Buildings on Lot	: 4	Vacant	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	YES	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	1087110		
HPD Multiple Dwelling:	Yes		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	11	0
Violations-DOB	18	1
Violations-OATH/ECB	7	0
Jobs/Filings	25	
ARA / LAA Jobs	4	
Total Jobs	29	
Actions	76	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 417 WEST 17 STREET MANHATTAN **BIN: 1078419 Block: 715 Lot: 10**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

CO 328951:	NO C/Os ISSUED OR NO IMAGE AVAILABLE
CO 38534:	M000038534.PDF
CO 32469:	M000032469.PDF

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF [redacted], CITY OF NEW YORK

No. [redacted]

Date May 28, 1951

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No.

To the owner or owners of the building or premises:

THIS CERTIFIES that the ~~new~~—altered—~~existing~~—building—premises located at

420 East 156th Street

Block 715 Lot 46

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

~~New~~ Alt. No.— 1657-1947 Construction classification—Class 3 nonfireproof

Occupancy classification— Commercial Building Height 3 stories, 40 feet.

Date of completion— May 25, 1951 . Located in Unrestricted Use District.

Area 1⅓ , Height Zone at time of issuance of permit 720-1951; 2542-1950; 2672-1950; 669-1948; 489-1948.

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS (Lbs. per Sq. Ft.)	PERSONS ACCOMMODATED			USE
		MALE	FEMALE	TOTAL	
Cellar	On ground				Boiler room and storage.
Basement	50	2	3	5	Office on each story
1st story	50				(one occupant)
2nd story					One (1) family.
3rd story					One (1) family.

[redacted]

Borough Superintendent

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form 55-20M-13041 114

DEPARTMENT OF HOUSING AND BUILDINGS

JT/lc BOROUGH OF MANHATTAN , CITY OF NEW YORK

No.

Date January 23, 1947

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No.

To the owner or owners of the building or premises:

THIS CERTIFIES that the ~~new~~—altered—~~existing~~—building—~~premises~~ located at

430 West 18th street
20 ft. 6½ ins. front Block 715 Lot 47

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

~~New~~ Alt. No.— 904-46 Construction classification— Nonfireproof

Occupancy classification— Commercial . Height Cellar & 1 stories, 43 feet.

Date of completion— January 21, 1947 . Located in Unrestricted Use District.

A Area 2 times. Height Zone at time of issuance of permit 1515-46; 1430-46;

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED			USE
		MALE	FEMALE	TOTAL	
Cellar	on ground				Storage
1st story	300	4	—	4	Baling
Mezzanine	50	1	--	1	Office

Borough Superintendent.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there by any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

DOB Violation Display for 120208C0402VF

Premises: 417 WEST 17 STREET MANHATTAN **BIN: 1078419 Block: 715 Lot: 10**

Issue Date: 12/02/2008
Violation Type: C - CONSTRUCTION
Violation Number: 0402VF
OATH/ECB No.:
Infraction Codes:
Description:

Violation Category: V - DOB VIOLATION - ACTIVE
Device No.:

Disposition:
Code: **Date:**
Inspector:
Comments:

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises: **BIN:** **Block:** **Lot:**

VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE	NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

ALSO SEE OTHER BIN(S) BELOW

427 WEST 17 STREET — **MANHATTAN 10011** — **BIN# 1078420**

WEST 17 STREET	427 - 431	**Health Area**	: 5600	**Tax Block**	: 715
FULTON HOUSES BUILDING 5	NO NUMBER	**Census Tract**	: 83	**Tax Lot**	: 10
		Community Board	: 104	**Condo**	: NO
		Buildings on Lot	: 4	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	YES	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	1811903		
HPD Multiple Dwelling:	Yes		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No
Freshwater Wetlands Map Check:	No
Coastal Erosion Hazard Area Map Check:	No
Special Flood Hazard Area Check:	Yes

Click here for more information

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	5	0
Violations-DOB	15	1
Violations-OATH/ECB	4	0
Jobs/Filings	5	
ARA / LAA Jobs	1	
Total Jobs	6	
Actions	22	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 427 WEST 17 STREET MANHATTAN **BIN: 1078420 Block: 715 Lot: 10**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

CO 20964: M000020964.PDF

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Form -214-1935 Certificate of Occupancy. BA-2087-35-Bu

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

CERTIFICATE OF OCCUPANCY No. 20964 1936

Supersedes Certificate of Occupancy No.

To the owner or owners of the building: New York Jan. 10 1936

THIS CERTIFIES that the building located on Block 715, Lot 17

known as 431-35 West 17th Street
37.6" front

under a permit, Application No. 143 N.B. of 1935, conforms to the approved plans and specifications accompanying said permit and any approved amendments thereto, and to the requirements of the building code and all other laws and ordinances and to the rules and regulations of the board of standards and appeals, applicable to a building of its class and kind, except that in the case of a building heretofore existing and for which no previous certificate of occupancy has been issued and which has not been altered or converted since March 14, 1916, to a use that changed its classification as defined in the building code, this certificate confirms and continues the existing uses to which the building has been put; and

CERTIFIES FURTHER that the building is of nonfireproof construction within the meaning of the building code and may be used and occupied as a business building as hereinafter qualified, in a unrestricted district under the building zone resolution, subject to all the privileges, requirements, limitations and conditions prescribed by law or as hereinafter specified.

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED			USE
		MALE	FEMALE	TOTAL	
Cellar					Boiler room
1st story	300			15	Automobile Repair Shop

This certificate is issued to Moore and Hunsiedel, Architects
303 Willis Avenue, City.
, for the owner or owners.

The superimposed, uniformly distributed loads, or their equivalent concentrated loads in any story shall not exceed the live loads specified above; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

Unless specifically stated above, the building or any part thereof, if certified as a public building, shall not be used as a building in which persons are harbored to receive medical, charitable or other care or treatment, such as a hospital, asylum, etc., or in which persons are held or detained under legal restraint, such as a police station, jail, etc.; nor shall it be used as a motion picture theatre as defined in section 30, chapter 3, Code of Ordinances; nor as a theatre or opera house or other building intended to be used for theatrical or operatic purposes, or for public entertainment of any kind, for the accommodation of more than 300 persons.

Unless specifically stated above, the building or any part thereof, if certified as a residence building, shall not be used as a tenement house as defined in the tenement house law; nor shall it be used as any form of residence building having more than 15 sleeping rooms; nor shall it be used as a lodging house within the meaning of Sec. 1305 of the Greater New York Charter.

Unless specifically stated above, the building or any part thereof, if certified as a business building, shall not be used as a garage, motor vehicle repair shop or oil selling station as defined in section 1, chapter 10, Code of Ordinances; nor shall it be used for the generation or compression of acetylene; nor as a factory building as defined in the labor law; nor as a grain elevator; nor as a coal pocket.

Except as otherwise noted above, the building, or any part thereof, if located elsewhere than in an unrestricted district, shall not be used for any of the purposes enumerated in paragraph (a) of section 4 of the building zone resolution; nor for any trade, industry or use that is noxious or offensive by reason of the emission of odor, dust, smoke, gas or noise; nor for any kind of manufacturing not already prohibited, except that, if located in a business district, not more than twenty-five per cent. of the total floor space may be so used, or space equal to the area of the lot in any case.

Except as otherwise noted above, the building, if certified as a garage, may not be used for more than five cars on any portion of a street between two intersecting streets, in which portion there exists an exit from or an entrance to a public school, or in which portion there exists any hospital maintained as a charitable institution; and in no case within a distance of 200 feet from the the nearest exit from or entrance to a public school; nor within two hundred feet of any hospital maintained as a charitable institution.

If the building has, at any time previous to the issuance of this certificate, been the subject of an appeal to the board of appeals or of a petition to the board of standards and appeals resulting in modification or variation of law or any lawful requirement, the construction and arrangement of the building as specified in the resolution granting such modification or variation, must be maintained, and all conditions imposed by either board must be observed.

No change or re-arrangement in the structural parts of the building, or affecting the lighting or ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located, until an approval of the same has been obtained from the commissioner of buildings.

This certificate supersedes each and every previously issued certificate of occupancy for this building or any part thereof, and each and every such previously issued certificate shall be null and void; and this certificate in turn becomes null and void upon the issuance of any new lawful certificate.

This certificate does not in any way relieve the owner or owners, or any other person or persons in possession or control of the building, or any part thereof, from obtaining such other permits or licenses as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

This certificate does not authorize the use or operation of any elevator in the building without the special certificate required by section 563 of the building code.

If the building is or is required to be equipped with standpipes or other fire extinguishing or gas shut off appliances, this certificate is not complete until such standpipes or other appliances have been inspected by the fire department (or by the Tenement House Department in the case of a gas shut off in a tenement house) and approved in writing, either in a separate certificate or by endorsement upon this certificate. (Space for such endorsement is provided on page 4 of this certificate.)

If this certificate is marked "Temporary," it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to a tenement house unless also approved by the tenement house commissioner; and it must be replaced by a full certificate as soon as the entire building is completed according to law and ready for occupancy.

The word "class" as used in this certificate refers to the classification of buildings in the building code (section 70).

This certificate is issued in accordance with the provisions of section 411-a of the Greater New York Charter and of section 5 of chapter 5 (Building Code) of the Code of Ordinances of the City of New York.

Examined. GG

84

Commissioner of Buildings, Borough of Manhattan. MK

Additional copies of this certificate will be issued, upon written request, to persons having a proprietary interest in the building.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

DOB Violation Display for 061919FISPHAZ88225

Premises: 427 WEST 17 STREET MANHATTAN **BIN: 1078420 Block: 715 Lot: 10**

Issue Date:	06/19/2019	**Violation Category:**	V - DOB VIOLATION - ACTIVE
Violation Type:	FISP - FACADE SAFETY PROGRAM		
Violation Number:	HAZ88225	**Device No.:**	00801447
OATH/ECB No.:			
Infraction Codes:			
Description:			
Disposition:			
Code:	**Date:**		
Inspector:			
Comments:			

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises: **BIN:** **Block:** **Lot:**

VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE	NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

433 WEST 17 STREET — **MANHATTAN 10011** — **BIN# 1811900**

WEST 17 STREET 433 - 435

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	5	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 433 WEST 17 STREET MANHATTAN **BIN: 1811900 Block: 715 Lot: 10**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

CO 1624: M000001624.PDF

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Form 190—1919 Certificate of Occupancy

SA-2045-19 CK

BUREAU OF BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

CERTIFICATE OF OCCUPANCY No. 1024 1920

715

THIS CERTIFIES that the building located on Block 715 Lot 15

known as 433-35 East 17 St.
37½ front.

conforms substantially to the approved plans and specifications of N. B. Application No. 74 1919 and to all the requirements of the BUILDING CODE AND BUILDING ZONE RESOLUTION of the City of New York

for a non-fireproof, cellar & 1 story, offies & Lumber Yard.

and that the several floors may sustain the live loads, accommodate the number of persons, and be occupied as follows:

FLOORS	Live Load per Square Foot in POUNDS	Number and Classification Persons on each Floor	OCCUPANCY
Cellar	----		STORAGE
1st Floor	60 and ground	15 employees	OFFICE & LUMBER YARD

VIOLATIONS PENDING

1/9/20

This certificate is issued to Hobart Lloyd Lumber Co.

owners of the aforesaid building, address 452 E. 15 St., N.Y.City.

in accordance with the provisions of Section 5, Article 1, Chapter 5 of the Code of Ordinances of the City of New York, and Chapter 503, Section 411-a of the Greater New York Charter.

DATED Jan. 8, 1920.

Superintendent of Buildings

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Permits In-Process / Issued by Premises

NO PREVIOUSLY ISSUED PERMITS FOUND FOR THIS PROPERTY

Page:

Premises: 433 WEST 17 STREET MANHATTAN BIN: 1811900 Block: 715 Lot: 10

NUMBER	JOB TYPE	SEQ NO	ISSUED DATE	EXPIRATION DATE	STATUS	APPLICANT NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises: **BIN:** **Block:** **Lot:**

VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE	NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

443 WEST 17 STREET **MANHATTAN 10011** **BIN# 1811901**

WEST 17 STREET 443 - 443

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	15	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 443 WEST 17 STREET MANHATTAN **BIN: 1811901 Block: 715 Lot: 10**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

CO 20282:	M000020282.PDF
CO 2706:	M000002706.PDF
CO 25677:	M000025677.PDF
CO 44319:	M000044319.PDF

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Form -244-1931 Certificate of Occupancy. 8A-2687-31-C.P.

DEPARTMENT

BUREAU OF BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

HVC **CERTIFICATE OF OCCUPANCY No. 20282 193 5**

Supersedes Certificate of Occupancy No. 2703

To the owner or owners of the building: New York April 1, 1935

THIS CERTIFIES that the building located on Block 715, Lot 27

known as 411 West 17th Street
25' front

under a permit. Application No. 1883 Alt of 19 34 conforms to the approved plans and specifications accompanying said permit and any approved amendments thereto, and to the requirements of the building code and all other laws and ordinances and to the rules and regulations of the board of standards and appeals, applicable to a building of its class and kind, except that in the case of a building heretofore existing and for which no previous certificate of occupancy has been issued and which has not been altered or converted since March 14, 1916, to a use that changed its classification as defined in the building code, this certificate confirms and continues the existing uses to which the building has been put; and

CERTIFIES FURTHER that the building is of nonfireproof construction within the meaning of the building code and may be used and occupied as a business building as hereinafter qualified, in a n unrestricted district under the building zone resolution, subject to all the privileges, requirements, limitations and conditions prescribed by law or as hereinafter specified.

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
Cellar				3	Storage
1st Story	120-60			5	Garage and Office
2nd "	100				Storage
3rd "	50				Storage
4th "	60			2	Storage
5th-Penthouse	40				Not to be occupied

This certificate is issued to Charles M. Spindler, 164 Montague St. Bklyn. , for the owner or owners.

The superimposed, uniformly distributed loads, or their equivalent concentrated loads in any story shall not exceed the live loads specified above; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

Unless specifically stated above, the building or any part thereof, if certified as a public building, shall not be used as a building in which persons are harbored to receive medical, charitable or other care or treatment, such as a hospital, asylum, etc., or in which persons are held or detained under legal restraint, such as a police station, jail, etc.; nor shall it be used as a motion picture theatre as defined in section 30, chapter 5, Code of Ordinances; nor as a theatre or opera house or other building intended to be used for theatrical or operatic purposes, or for public entertainment of any kind, for the accommodation of more than 300 persons.

Unless specifically stated above, the building or any part thereof, if certified as a residence building, shall not be used as a tenement house as defined in the tenement house law; nor shall it be used as any form of residence building having more than 15 sleeping rooms; nor shall it be used as a lodging house within the meaning of Sec. 1305 of the Greater New York Charter.

Unless specifically stated above, the building or any part thereof, if certified as a business building, shall not be used as a garage, motor vehicle repair shop or oil selling station as defined in section 1, chapter 10, Code of Ordinances; nor shall it be used for the generation or compression of acetylene; nor as a factory building as defined in the labor law; nor as a grain elevator; nor as a coal pocket.

Except as otherwise noted above, the building, or any part thereof, if located elsewhere than in an unrestricted district, shall not be used for any of the purposes enumerated in paragraph (a) of section 4 of the building zone resolution; nor for any trade, industry or use that is noxious or offensive by reason of the emission of odor, dust, smoke, gas or noise; nor for any kind of manufacturing not already prohibited, except that, if located in a business district, not more than twenty-five per cent. of the total floor space may be so used, or space equal to the area of the lot in any case.

Except as otherwise noted above, the building, if certified as a garage, may not be used for more than five cars on any portion of a street between two intersecting streets, in which portion there exists an exit from or an entrance to a public school, or in which portion there exists any hospital maintained as a charitable institution; and in no case within a distance of 200 feet from the nearest exit from or entrance to a public school; nor within two hundred feet of any hospital maintained as a charitable institution.

If the building has, at any time previous to the issuance of this certificate, been the subject of an appeal to the board of appeals or of a petition to the board of standards and appeals resulting in modification or variation of law or any lawful requirement, the construction and arrangement of the building as specified in the resolution granting such modification or variation, must be maintained, and all conditions imposed by either board must be observed.

No change or re-arrangement in the structural parts of the building, or affecting the lighting or ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height, shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located, until an approval of the same has been obtained from the superintendent of buildings.

This certificate supersedes each and every previously issued certificate of occupancy for this building or any part thereof, and each and every such previously issued certificate shall be null and void; and this certificate in turn becomes null and void upon the issuance of any new lawful certificate.

This certificate does not in any way relieve the owner or owners, or any other person or persons in possession or control of the building, or any part thereof, from obtaining such other permits or licenses as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

This certificate does not authorize the use or operation of any elevator in the building without the special certificate required by section 563 of the building code.

If the building is or is required to be equipped with standpipes or other fire extinguishing or gas shut off appliances, this certificate is not complete until such standpipes or other appliances have been inspected by the fire department (or by the Tenement House Department in the case of a gas shut off in a tenement house) and approved in writing, either in a separate certificate or by endorsement upon this certificate. (Space for such endorsement is provided on page 4 of this certificate.)

If this certificate is marked "Temporary," it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to a tenement house unless also approved by the tenement house commissioner; and it must be replaced by a full certificate as soon as the entire building is completed according to law and ready for occupancy.

The word "class" as used in this certificate refers to the classification of buildings in the building code (section 70).

This certificate is issued in accordance with the provisions of section 411-a of the Greater New York Charter and of section 5 of chapter 5 (Building Code) of the Code of Ordinances of the City of New York.

Examined. GS

Superintendent of Buildings, Borough of Manhattan.
Commissioner

Additional copies of this certificate will be issued, upon written request, to persons having a proprietary interest in the building.

Form—150-1920 Certificate of Occupancy

6A-2045-20 B

BUREAU OF BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

CERTIFICATE OF OCCUPANCY No. 192 1

THIS CERTIFIES that the building located on Block 713 Lot 27-28

known as 409-11 East 17 Street.

conforms substantially to the approved plans and specifications of filed Application No. 646 19 20
and to all the requirements of the BUILDING CODE AND BUILDING ZONE RESOLUTION of the City of New York

for a non-fireproof, 1 story Garage.

and that the several floors may sustain the live loads, accommodate the number of persons, and be occupied as follows:

FLOORS	Live Load per Square Foot in POUNDS	Number and Classification Persons on each Floor	OCCUPANCY
1st Floor	-----	5	GARAGE

4197

This certificate is issued to Hoppes, Gray & Co.
owner of the aforesaid building, address 411 E. 17 St., N.Y.City.

in accordance with the provisions of Section 5, Article 1, Chapter 5 of the Code of Ordinances of the City of New York, and Chapter 503, Section 411-a of the Greater New York Charter.

DATED Feb. 4, 1921.

Superintendent of Buildings

Form 55

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

HVC
No. 25677

Date January 22,1940

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1 to 2.1.3.7. Building Code).

This certificate supersedes C. O. No.

To the owner or owners of the building or premises:

THIS CERTIFIES that the new ~~altered~~ ~~existing~~ building ~~premises~~ located at

443 West 17th Street
25'0" front Block 715 Lot 11

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of section 646f of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~xxxx~~ No.— 209-1939 Construction classification—nonfireproof

Occupancy classification—commercial . Height 1 stories, 14'6" feet.

Date of completion—January 18-1940 . Located in unrestricted Use District.

B . Area 2 . Height Zone at time of issuance of permit 4855-1939

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
1st Story	200			3	Storage

SUPERSEDED BY C.O. 44316

Borough Superintendent

(Page 1)

ACTING BOROUGH SUPERINTENDENT

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there by any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaing the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifiies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§.646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

A.H.M

Form 54-44.5M-701496(54) 114

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

No. 44319

Date June 30,1955

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No. 25677

To the owner or owners of the building or premises:

THIS CERTIFIES that the new—altered—existing—building—premises located at

443 West 17th Street Block 715 Lot 11

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. or Alt. No.— 807-1955 Construction classification— Class 3 nonfireproof

Occupancy classification— Commercial Building Height 1 stories, 12 feet.

Date of completion— June 29,1955 Located in Unrestricted Use District.

Area B 1½ Height Zone at time of issuance of permit

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
1st Story	On ground	4		4	Motor vehicle repair shop.

Sec. 6.1.2.3 sub-4 Building Code, C.26-273.0 Adm. Code

"Prior to the commencement of any structure erected or altered after January 1, 1938, the limitation of each floor of such structure as stated in the certificate of occupancy shall be permanently posted under glass and maintained in the main entrance hall of such structures."

Joseph E. Herman
Borough Superintendent

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Permits In-Process / Issued by Premises

NO PREVIOUSLY ISSUED PERMITS FOUND FOR THIS PROPERTY

Page:

Premises: 443 WEST 17 STREET MANHATTAN BIN: 1811901 Block: 715 Lot: 10

NUMBER	JOB TYPE	SEQ NO	ISSUED DATE	EXPIRATION DATE	STATUS	APPLICANT NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises: **BIN:** **Block:** **Lot:**

VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE	NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

411 WEST 17 STREET — **MANHATTAN 10011** — **BIN# 1811902**

WEST 17 STREET 411 - 411

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	1811905		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	18	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 411 WEST 17 STREET MANHATTAN **BIN: 1811902 Block: 715 Lot: 10**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

COFO 2706: M000002706.PDF

COFO 20282: M000020282.PDF

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Form—190-1920 Certificate of Occupancy

8A-2045-20 B

BUREAU OF BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

CERTIFICATE OF OCCUPANCY No. 192 1

THIS CERTIFIES that the building located on Block 713 Lot 27-28

known as 409-11 East 17 Street.

conforms substantially to the approved plans and specifications of filed Application No. 646 19 20
and to all the requirements of the BUILDING CODE AND BUILDING ZONE RESOLUTION of the City of New York

for a non-fireproof, 1 story Garage.

and that the several floors may sustain the live loads, accommodate the number of persons, and be occupied as follows:

FLOORS	Live Load per Square Foot in POUNDS	Number and Classification Persons on each Floor	OCCUPANCY
1st Floor	-----	5	GARAGE

4197

2/4/21

This certificate is issued to Koppel, Gray & Co.

owner of the aforesaid building, address 411 E. 17 St., N.Y.City.

in accordance with the provisions of Section 5, Article 1, Chapter 5 of the Code of Ordinances of the City of New York, and Chapter 503, Section 411-a of the Greater New York Charter.

DATED Feb. 4, 1921.

Superintendent of Buildings

Form -244-1931 Certificate of Occupancy. 8A-2087-31-C.P.

DEPARTMENT
BUREAU OF BUILDINGS
BOROUGH OF MANHATTAN, CITY OF NEW YORK

HVC **CERTIFICATE OF OCCUPANCY No. 20282 193 5**

Supersedes Certificate of Occupancy No. 2703

To the owner or owners of the building: New York April 1, 1935

THIS CERTIFIES that the building located on Block 715, Lot 27

known as 411 West 17th Street
25' front

under a permit. Application No. 1685 Alt of 19 34 conforms to the approved plans and specifications accompanying said permit and any approved amendments thereto, and to the requirements of the building code and all other laws and ordinances and to the rules and regulations of the board of standards and appeals, applicable to a building of its class and kind, except that in the case of a building heretofore existing and for which no previous certificate of occupancy has been issued and which has not been altered or converted since March 14, 1916, to a use that changed its classification as defined in the building code; this certificate confirms and continues the existing uses to which the building has been put; and

CERTIFIES FURTHER that the building is of non fireproof construction within the meaning of the building code and may be used and occupied as a business building as hereinafter qualified, in a n unrestricted district under the building zone resolution, subject to all the privileges, requirements, limitations and conditions prescribed by law or as hereinafter specified.

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
Cellar				8	Storage
1st Story	120-60			5	Garage and Office
2nd "	100				Storage
3rd "	50				Storage
4th "	60			2	Storage
5th-Pent House	40				Not to be occupied

This certificate is issued to Charles M. Spindler, 164 Montague St. Bklyn. , for the owner or owners.

The superimposed, uniformly distributed loads, or their equivalent concentrated loads in any story shall not exceed the live loads specified above; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

Unless specifically stated above, the building or any part thereof, if certified as a public building, shall not be used as a building in which persons are harbored to receive medical, charitable or other care or treatment, such as a hospital, asylum, etc., or in which persons are held or detained under legal restraint, such as a police station, jail, etc.; nor shall it be used as a motion picture theatre as defined in section 30, chapter 3, Code of Ordinances; nor as a theatre or opera house or other building intended to be used for theatrical or operatic purposes, or for public entertainment of any kind, for the accommodation of more than 300 persons.

Unless specifically stated above, the building or any part thereof, if certified as a residence building, shall not be used as a tenement house as defined in the tenement house law; nor shall it be used as any form of residence building having more than 15 sleeping rooms; nor shall it be used as a lodging house within the meaning of Sec. 1305 of the Greater New York Charter.

Unless specifically stated above, the building or any part thereof, if certified as a business building, shall not be used as a garage, motor vehicle repair shop or oil selling station as defined in section 1, chapter 10, Code of Ordinances; nor shall it be used for the generation or compression of acetylene; nor as a factory building as defined in the labor law; nor as a grain elevator; nor as a coal pocket.

Except as otherwise noted above, the building, or any part thereof, if located elsewhere than in an unrestricted district, shall not be used for any of the purposes enumerated in paragraph (a) of section 4 of the building zone resolution; nor for any trade, industry or use that is noxious or offensive by reason of the emission of odor, dust, smoke, gas or noise; nor for any kind of manufacturing not already prohibited, except that, if located in a business district, not more than twenty-five per cent. of the total floor space may be so used, or space equal to the area of the lot in any case.

Except as otherwise noted above, the building, if certified as a garage, may not be used for more than five cars on any portion of a street between two intersecting streets, in which portion there exists an exit from or an entrance to a public school, or in which portion there exists any hospital maintained as a charitable institution; and in no case within a distance of 200 feet from the nearest exit from or entrance to a public school; nor within two hundred feet of any hospital maintained as a charitable institution.

If the building has, at any time previous to the issuance of this certificate, been the subject of an appeal to the board of appeals or of a petition to the board of standards and appeals resulting in modification or variation of law or any lawful requirement, the construction and arrangement of the building as specified in the resolution granting such modification or variation, must be maintained, and all conditions imposed by either board must be observed.

No change or re-arrangement in the structural parts of the building, or affecting the lighting or ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located, until an approval of the same has been obtained from the superintendent of buildings.

This certificate supersedes each and every previously issued certificate of occupancy for this building or any part thereof, and each and every such previously issued certificate shall be null and void; and this certificate in turn becomes null and void upon the issuance of any new lawful certificate.

This certificate does not in any way relieve the owner or owners, or any other person or persons in possession or control of the building, or any part thereof, from obtaining such other permits or licenses as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

This certificate does not authorize the use or operation of any elevator in the building without the special certificate required by section 563 of the building code.

If the building is or is required to be equipped with standpipes or other fire extinguishing or gas shut off appliances, this certificate is not complete until such standpipes or other appliances have been inspected by the fire department (or by the Tenement House Department in the case of a gas shut off in a tenement house) and approved in writing, either in a separate certificate or by endorsement upon this certificate. (Space for such endorsement is provided on page 4 of this certificate.)

If this certificate is marked "Temporary," it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to a tenement house unless also approved by the tenement house commissioner; and it must be replaced by a full certificate as soon as the entire building is completed according to law and ready for occupancy.

The word "class" as used in this certificate refers to the classification of buildings in the building code (section 70).

This certificate is issued in accordance with the provisions of section 411-a of the Greater New York Charter and of section 5 of chapter 5 (Building Code) of the Code of Ordinances of the City of New York.

Examined.

Superintendent of Buildings, Borough of Manhattan.
Commissioner

Additional copies of this certificate will be issued, upon written request, to persons having a proprietary interest in the building.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Permits In-Process / Issued by Premises

NO PREVIOUSLY ISSUED PERMITS FOUND FOR THIS PROPERTY

Page:

Premises: 411 WEST 17 STREET MANHATTAN BIN: 1811902 Block: 715 Lot: 10

NUMBER	JOB TYPE	SEQ NO	ISSUED DATE	EXPIRATION DATE	STATUS	APPLICANT NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises: **BIN:** **Block:** **Lot:**

VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE	NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

425 WEST 17 STREET — **MANHATTAN 10011** — **BIN# 1811903**

WEST 17 STREET 425 - 427

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	1078420		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	6	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	37	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 425 WEST 17 STREET MANHATTAN **BIN: 1811903 Block: 715 Lot: 10**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

CO 23313:	M000023313.PDF
CO 30298:	M000030298.PDF

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Form—244-1935 Certificate of Occupancy. HOUSING AND BA-2087-35-Bld 60

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

HVC CERTIFICATE OF OCCUPANCY No. 28818 193[8]

Supersedes Certificate of Occupancy No.

To the owner or owners of the building: New York January 17, 19[38].

THIS CERTIFIES that the building located on Block 715, Lot 19-20

known as 425-7 West 17th Street
50.0' front

under a permit, Application No. 38 H.B. of 19[37], conforms to the approved plans and specifications accompanying said permit and any approved amendments thereto, and to the requirements of the building code and all other laws and ordinances and to the rules and regulations of the board of standards and appeals, applicable to a building of its class and kind, except that in the case of a building heretofore existing and for which no previous certificate of occupancy has been issued and which has not been altered or converted since March 14, 1916, to a use that changed its classification as defined in the building code, this certificate confirms and continues the existing uses to which the building has been put; and

CERTIFIES FURTHER that the building is of fireproof construction within the meaning of the building code and may be used and occupied as a business building as hereinafter qualified, in an unrestricted district under the building zone resolution, subject to all the privileges, requirements, limitations and conditions prescribed by law or as hereinafter specified.

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
Cellar					Storage
1st Story	120			15	Storage of meat
2nd "	150-60			5	Storage of meat and office

This certificate is issued to Jacob J. Closter, architect
303 West 42nd Street, City
, for the owner or owners.

The superimposed, uniformly distributed loads, or their equivalent concentrated loads in any story shall not exceed the live loads specified above; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

Unless specifically stated above, the building or any part thereof, if certified as a public building, shall not be used as a building in which persons are harbored to receive medical, charitable or other care or treatment, such as a hospital, asylum, etc., or in which persons are held or detained under legal restraint, such as a police station, jail, etc.; nor shall it be used as a motion picture theatre as defined in section 30, chapter 3, Code of Ordinances; nor as a theatre or opera house or other building intended to be used for theatrical or operatic purposes, or for public entertainment of any kind, for the accommodation of more than 300 persons.

Unless specifically stated above, the building or any part thereof, if certified as a residence building, shall not be used as a tenement house as defined in the tenement house law; nor shall it be used as any form of residence building having more than 15 sleeping rooms; nor shall it be used as a lodging house within the meaning of Sec. 1305 of the Greater New York Charter.

Unless specifically stated above, the building or any part thereof, if certified as a business building, shall not be used as a garage, motor vehicle repair shop or oil selling station as defined in section 1, chapter 10, Code of Ordinances; nor shall it be used for the generation or compression of acetylene; nor as a factory building as defined in the labor law; nor as a grain elevator; nor as a coal pocket.

Except as otherwise noted above, the building, or any part thereof, if located elsewhere than in an unrestricted district, shall not be used for any of the purposes enumerated in paragraph (a) of section 4 of the building zone resolution; nor for any trade, industry or use that is noxious or offensive by reason of the emission of odor, dust, smoke, gas or noise; nor for any kind of manufacturing not already prohibited, except that, if located in a business district, not more than twenty-five per cent. of the total floor space may be so used, or space equal to the area of the lot in any case.

Except as otherwise noted above, the building, if certified as a garage, may not be used for more than five cars on any portion of a street between two intersecting streets, in which portion there exists an exit from or an entrance to a public school, or in which portion there exists any hospital maintained as a charitable institution; and in no case within a distance of 200 feet from the the nearest exit from or entrance to a public school; nor within two hundred feet of any hospital maintained as a charitable institution.

If the building has, at any time previous to the issuance of this certificate, been the subject of an appeal to the board of appeals or of a petition to the board of standards and appeals resulting in modification or variation of law or any lawful requirement, the construction and arrangement of the building as specified in the resolution granting such modification or variation, must be maintained, and all conditions imposed by either board must be observed.

No change or re-arrangement in the structural parts of the building, or affecting the lighting or ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located, until an approval of the same has been obtained from the commissioner of buildings.

This certificate supersedes each and every previously issued certificate of occupancy for this building or any part thereof, and each and every such previously issued certificate shall be null and void; and this certificate in turn becomes null and void upon the issuance of any new lawful certificate.

This certificate does not in any way relieve the owner or owners, or any other person or persons in possession or control of the building, or any part thereof, from obtaining such other permits or licenses as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

This certificate does not authorize the use or operation of any elevator in the building without the special certificate required by section 563 of the building code.

If the building is or is required to be equipped with standpipes or other fire extinguishing or gas shut off appliances, this certificate is not complete until such standpipes or other appliances have been inspected by the fire department (or by the Tenement House Department in the case of a gas shut off in a tenement house) and approved in writing, either in a separate certificate or by endorsement upon this certificate. (Space for such endorsement is provided on page 4 of this certificate.)

If this certificate is marked "Temporary," it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to a tenement house unless also approved by the tenement house commissioner; and it must be replaced by a full certificate as soon as the entire building is completed according to law and ready for occupancy.

The word "class" as used in this certificate refers to the classification of buildings in the building code (section 70).

This certificate is issued in accordance with the provisions of section 411-a of the Greater New York Charter and of section 5 of chapter 5 (Building Code) of the Code of Ordinances of the City of New York.

Examined. A.H.M

Victor H. Tomlet

Acting Borough Superintendent

Commissioner of Buildings, Borough of Manhattan.

Department of Housing and Buildings

Additional copies of this certificate will be issued, upon written request, to persons having a proprietary interest in the building.

Form 55-20M-11041 114

DEPARTMENT OF HOUSING AND BUILDINGS

JT /lc

BOROUGH OF MANHATTAN, CITY OF NEW YORK

No. 30293

Date May 12, 1944

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No. 3313

To the owner or owners of the building or premises:

THIS CERTIFIES that the new—~~altered~~—~~existing~~—building—~~premises~~ located at

425-427 West 17th street

Block 715 Lot 19 & 20

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

~~XXNB~~, or Alt. No. 754-1944 Construction classification—Fireproof

Occupancy classification—[illegible] . Height 2 stories, 28 feet.

Date of completion— — . Located in Unrestricted Use District.

A Area 2 times . Height Zone at time of issuance of permit 511-1937

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
Cellar	On ground				Storage and Engine room.
1st story	150 and 120.	6	--	6	Storage chickens.
2d story	60 lbs.	7	15	22	Office, storage, and eviscerating poultry.
					Fuel Oil, Fire Department approval May 11, 1944.
					NOTE: Not more than five (5) persons engaged in eviscerating poultry.

Borough Superintendent.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there by any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

NO PREVIOUSLY ISSUED PERMITS FOUND FOR THIS PROPERTY

425 WEST 17 STREET — **MANHATTAN 10011** — **BIN# 1811903**

WEST 17 STREET 425 - 427

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	1078420		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	6	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	37	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

NO RECORDS WERE FOUND FOR BOILER FILE

425 WEST 17 STREET — **MANHATTAN 10011** — **BIN# 1811903**

WEST 17 STREET 425 - 427

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	1078420		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	6	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	37	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

437 WEST 17 STREET — **MANHATTAN 10011** — **BIN# 1811904**

WEST 17 STREET 437 - 437

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	1	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	26	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 437 WEST 17 STREET MANHATTAN **BIN: 1811904 Block: 715 Lot: 10**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

THERE ARE NO CERTIFICATES OF OCCUPANCY ON FILE FOR THIS ADDRESS

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Permits In-Process / Issued by Premises

NO PREVIOUSLY ISSUED PERMITS FOUND FOR THIS PROPERTY

Page:

Premises: 437 WEST 17 STREET MANHATTAN BIN: 1811904 Block: 715 Lot: 10

NUMBER	JOB TYPE	SEQ NO	ISSUED DATE	EXPIRATION DATE	STATUS	APPLICANT NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises: **BIN:** **Block:** **Lot:**

VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE	NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

406 WEST 18 STREET — **MANHATTAN 10011** — **BIN# 1811906**

WEST 18 STREET 406 - 406

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	8	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 406 WEST 18 STREET MANHATTAN **BIN: 1811906 Block: 715 Lot: 10**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

CO 33719: M000033719.PDF

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Form 33-BBM-30144—[illegible] 114

DEPARTMENT OF HOUSING AND BUILDINGS

JT-BOROUGH OF MANHATTAN , CITY OF NEW YORK

No. 33719

Date February 25, 1948

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No.

To the owner or owners of the building or premises:

THIS CERTIFIES that the ~~new~~—altered—~~addition~~—building—~~premises~~ located at

404-406 West 18th street, 127 Ninth avenue Part of Block 715 Lot 35

———, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

, CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

~~N.B. or~~ Alt. No.— 2378-1946 Construction classification— ---

Occupancy classification— Commercial . Height--- stories- feet.

Date of completion— February 19, 1948 . Located in Unrestricted Use District.

A Area 2 times . Height-Zone at time of issuance of permit ---

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED			USE
		MALE	FEMALE	TOTAL	
					Parking lot for more than five (5) motor vehicles.

Borough Superintendent.

C1788

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

NO PREVIOUSLY ISSUED PERMITS FOUND FOR THIS PROPERTY

406 WEST 18 STREET — **MANHATTAN 10011** — **BIN# 1811906**

WEST 18 STREET 406 - 406

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	8	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

NO RECORDS WERE FOUND FOR BOILER FILE

406 WEST 18 STREET — **MANHATTAN 10011** — **BIN# 1811906**

WEST 18 STREET 406 - 406

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	8	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

418 WEST 18 STREET — **MANHATTAN 10011** — **BIN# 1811908**

WEST 18 STREET 418 - 418

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	10	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 418 WEST 18 STREET MANHATTAN **BIN: 1811908 Block: 715 Lot: 10**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

THERE ARE NO CERTIFICATES OF OCCUPANCY ON FILE FOR THIS ADDRESS

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

NO PREVIOUSLY ISSUED PERMITS FOUND FOR THIS PROPERTY

418 WEST 18 STREET — **MANHATTAN 10011** — **BIN# 1811908**

WEST 18 STREET 418 - 418

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	10	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

- Elevator Records
- Electrical Applications
- Permits In-Process / Issued
- Illuminated Signs Annual Permits
- Plumbing Inspections
- Open Plumbing Jobs / Work Types
- Facades
- Marquee Annual Permits
- Boiler Records
- DEP Boiler Information
- Crane Information
- After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

NO RECORDS WERE FOUND FOR BOILER FILE

418 WEST 18 STREET — **MANHATTAN 10011** — **BIN# 1811908**

WEST 18 STREET 418 - 418

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	10	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

434 WEST 18 STREET — **MANHATTAN 10011** — **BIN# 1811909**

WEST 18 STREET 434 - 434

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	8	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 434 WEST 18 STREET MANHATTAN **BIN: 1811909 Block: 715 Lot: 10**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

THERE ARE NO CERTIFICATES OF OCCUPANCY ON FILE FOR THIS ADDRESS

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Permits In-Process / Issued by Premises

NO PREVIOUSLY ISSUED PERMITS FOUND FOR THIS PROPERTY

Page:

Premises: 434 WEST 18 STREET MANHATTAN BIN: 1811909 Block: 715 Lot: 10

NUMBER	JOB TYPE	SEQ NO	ISSUED DATE	EXPIRATION DATE	STATUS	APPLICANT NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises: **BIN:** **Block:** **Lot:**

VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE	NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

404 WEST 18 STREET — **MANHATTAN 10011** — **BIN# 1811910**

WEST 18 STREET 404 - 404

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	8	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 404 WEST 18 STREET MANHATTAN **BIN: 1811910 Block: 715 Lot: 10**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

THERE ARE NO CERTIFICATES OF OCCUPANCY ON FILE FOR THIS ADDRESS

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

NO PREVIOUSLY ISSUED PERMITS FOUND FOR THIS PROPERTY

404 WEST 18 STREET — **MANHATTAN 10011** — **BIN# 1811910**

WEST 18 STREET 404 - 404

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	8	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises: **BIN:** **Block:** **Lot:**

VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE	NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

408 WEST 18 STREET — **MANHATTAN 10011** — **BIN# 1811911**

WEST 18 STREET 408 - 408

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	8	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 408 WEST 18 STREET MANHATTAN **BIN: 1811911 Block: 715 Lot: 10**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

THERE ARE NO CERTIFICATES OF OCCUPANCY ON FILE FOR THIS ADDRESS

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Permits In-Process / Issued by Premises

NO PREVIOUSLY ISSUED PERMITS FOUND FOR THIS PROPERTY

Page:

Premises: 408 WEST 18 STREET MANHATTAN BIN: 1811911 Block: 715 Lot: 10

NUMBER	JOB TYPE	SEQ NO	ISSUED DATE	EXPIRATION DATE	STATUS	APPLICANT NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises: **BIN:** **Block:** **Lot:**

VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE	NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

NO PREVIOUSLY ISSUED PERMITS FOUND FOR THIS PROPERTY

410 WEST 18 STREET — **MANHATTAN 10011** — **BIN# 1811912**

WEST 18 STREET 410 - 410

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	9	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

NO RECORDS WERE FOUND FOR BOILER FILE

410 WEST 18 STREET — **MANHATTAN 10011** — **BIN# 1811912**

WEST 18 STREET 410 - 410

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	9	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

410 WEST 18 STREET — **MANHATTAN 10011** — **BIN# 1811912**

WEST 18 STREET 410 - 410

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: WCH - WEST CHELSEA

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	9	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 410 WEST 18 STREET MANHATTAN **BIN: 1811912 Block: 715 Lot: 10**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

THERE ARE NO CERTIFICATES OF OCCUPANCY ON FILE FOR THIS ADDRESS

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

409 WEST 17 STREET — **MANHATTAN 10011** — **BIN# 1811905**

WEST 17 STREET 409 - 411

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... | Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	1811902		
HPD Multiple Dwelling:	No		
Special District:	WCH - WEST CHELSEA		

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	10	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

- Elevator Records
- Electrical Applications
- Permits In-Process / Issued
- Illuminated Signs Annual Permits
- Plumbing Inspections
- Open Plumbing Jobs / Work Types
- Facades
- Marquee Annual Permits
- Boiler Records
- DEP Boiler Information
- Crane Information
- After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 409 WEST 17 STREET MANHATTAN **BIN: 1811905 Block: 715 Lot: 10**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

CO 42197: M000042197.PDF

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Form 54-111M-701311(52) [redacted] 114

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN , CITY OF NEW YORK

No. 42197

Date February 11, 1954

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No. 2706

To the owner or owners of the building or premises:

THIS CERTIFIES that the [redacted]—altered [redacted]g—building—premises located at

409 West 17th Street Block 715 Lot 28

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent. Class 3

[redacted] Alt. No. 1475-1953 Construction classification—nonfireproof

Occupancy classification—Commercial Bldg. . Height 1 stories, 12'-6" feet.

Date of completion— January 29, 1954 . Located in Unrestricted Use District.

A Area 2 . Height Zone at time of issuance of permit [redacted]

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
Cellar	on ground				Boiler room
1st story	on ground & 120			5	Non-storage garage for not more than five (5) motor vehicles, loading platform and storage. Garage Use approved by Fire Department September 22, 1952.

Borough Superintendent

CERTIFICATE WILL BE NULL AND VOID IF ALTERED IN ANY MANNER OR ADDITIONS ARE MADE THERETO.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the buildings; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division, unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Permits In-Process / Issued by Premises

NO PREVIOUSLY ISSUED PERMITS FOUND FOR THIS PROPERTY

Page:

Premises: 409 WEST 17 STREET MANHATTAN BIN: 1811905 Block: 715 Lot: 10

NUMBER	JOB TYPE	SEQ NO	ISSUED DATE	EXPIRATION DATE	STATUS	APPLICANT NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises:							BIN:	Block:	Lot:
VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE		NAME	

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

412 WEST 18 STREET — **MANHATTAN 10011** — **BIN# 1811907**

WEST 18 STREET 412 - 412

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... | Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		
Special District:	WCH - WEST CHELSEA		

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	11	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 412 WEST 18 STREET MANHATTAN **BIN: 1811907 Block: 715 Lot: 10**

Download the Adobe Acrobat Reader if you are unable to open the PDF files

To report a problem with any of these images, please use the CO Image Problem Form

THERE ARE NO CERTIFICATES OF OCCUPANCY ON FILE FOR THIS ADDRESS

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Permits In-Process / Issued by Premises

NO PREVIOUSLY ISSUED PERMITS FOUND FOR THIS PROPERTY

Page:

Premises: 412 WEST 18 STREET MANHATTAN BIN: 1811907 Block: 715 Lot: 10

NUMBER	JOB TYPE	SEQ NO	ISSUED DATE	EXPIRATION DATE	STATUS	APPLICANT NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises:							BIN:	Block:	Lot:
VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE		NAME	

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

414 WEST 18 STREET — **MANHATTAN 10011** — **BIN# 1811913**

WEST 18 STREET 414 - 414

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... | Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		
Special District:	WCH - WEST CHELSEA		

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	1	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	12	

OR Enter Action Type: [ ]

OR Select from List: [Select...]

AND [Show Actions]

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 414 WEST 18 STREET MANHATTAN **BIN: 1811913 Block: 715 Lot: 10**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

THERE ARE NO CERTIFICATES OF OCCUPANCY ON FILE FOR THIS ADDRESS

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Permits In-Process / Issued by Premises

NO PREVIOUSLY ISSUED PERMITS FOUND FOR THIS PROPERTY

Page:

Premises: 414 WEST 18 STREET MANHATTAN BIN: 1811913 Block: 715 Lot: 10

NUMBER	JOB TYPE	SEQ NO	ISSUED DATE	EXPIRATION DATE	STATUS	APPLICANT NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises:							BIN:	Block:	Lot:
VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE		NAME	

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

432 GAR WEST 18 STREET — **MANHATTAN 10011** — **BIN# 1087110**

WEST 18 STREET 432 GAR - 432 GAR

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104	**Condo**	: NO
Buildings on Lot	: 4	**Vacant**	: NO

View DCP Addresses... | Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		
Special District:	WCH - WEST CHELSEA		

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Total Actions	0	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 432 GAR WEST 18 STREET MANHATTAN **BIN: 1087110 Block: 715 Lot: 10**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

THERE ARE NO CERTIFICATES OF OCCUPANCY ON FILE FOR THIS ADDRESS

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Permits In-Process / Issued by Premises

NO PREVIOUSLY ISSUED PERMITS FOUND FOR THIS PROPERTY

Page:

Premises: 432 GAR WEST 18 STREET MANHATTAN BIN: 1087110 Block: 715 Lot: 10

NUMBER	JOB TYPE	SEQ NO	ISSUED DATE	EXPIRATION DATE	STATUS	APPLICANT NAME

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises:							BIN:	Block:	Lot:
VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE		NAME	

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

416 WEST 18 STREET — **MANHATTAN 10011** — **BIN# 1811914**

WEST 18 STREET 416 - 416

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... | Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		
Special District:	WCH - WEST CHELSEA		

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	16	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 416 WEST 18 STREET MANHATTAN **BIN: 1811914 Block: 715 Lot: 10**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

THERE ARE NO CERTIFICATES OF OCCUPANCY ON FILE FOR THIS ADDRESS

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

NO PREVIOUSLY ISSUED PERMITS FOUND FOR THIS PROPERTY

416 WEST 18 STREET — **MANHATTAN 10011** — **BIN# 1811914**

WEST 18 STREET 416 - 416

Health Area	: 5600	**Tax Block**	: 715
Census Tract	: 83	**Tax Lot**	: 10
Community Board	: 104		

View DCP Addresses... | Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		
Special District:	WCH - WEST CHELSEA		

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	16	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises:							BIN:	Block:	Lot:
VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE		NAME	

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

401 WEST 18 STREET		**MANHATTAN 10011**		**BIN# 1078443**	
9 AVENUE	129 - 129	**Health Area**	: 5600	**Tax Block**	: 716
9 AVENUE	141 - 145	**Census Tract**	: 89	**Tax Lot**	: 17
WEST 18 STREET	401 - 413	**Community Board**	: 104	**Condo**	: NO
FULTON HOUSES BUILDING 8	NO NUMBER	**Buildings on Lot**	: 3	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	9 AVENUE, 10 AVENUE		
DOB Special Place Name:	LOT 15 + 17 REAPPORTIONED		
DOB Building Remarks:	NEW LOT-17 = 129-145 NINTH AVE + 401-423 WEST 18 ST + 400-422 WEST 19 ST		
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES

Additional BINs for Building: NONE
HPD Multiple Dwelling: Yes

Special District: UNKNOWN

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	3	0
Violations-DOB	37	1
Violations-OATH/ECB	3	0
Jobs/Filings	6	
ARA / LAA Jobs	1	
Total Jobs	7	
Actions	226	

OR Enter Action Type: [ ]
OR Select from List: [Select...]
AND [Show Actions]

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 401 WEST 18 STREET MANHATTAN **BIN: 1078443 Block: 716 Lot: 17**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

CO 4273:	M000004273.PDF
CO 24242:	M000024242.PDF
CO 60505-TEMP:	M000060505.PDF
CO 60848TEMP:	M000060848.PDF
CO 61493:	M000061493.PDF
CO 30467:	M000030467.PDF
CO 31234:	M000031234.PDF
CO 21528:	M000021528.PDF
CO 22114:	M000022114.PDF

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Form—1921 Certificate of Occupancy

SA-2045-21-CK

BUREAU OF BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

G- CERTIFICATE OF OCCUPANCY No. 192 2

THIS CERTIFIES that the building located on Block 716 Lot 36

known as 139 Ninth Avenue.
"22'-4" front.

conforms substantially to the approved plans and specifications of Alt, Application No. 501 19 21 and to all the requirements of the BUILDING CODE AND BUILDING ZONE RESOLUTION of the City of New York

for a non-fireproof, cellar & 3 story Store & Dwelling.

and that the several floors may sustain the live loads, accommodate the number of persons, and be occupied as follows:

FLOORS	Live Load per Square Foot in POUNDS	Number and Classification Persons on each Floor	OCCUPANCY
Cellar	---		Storage
1st Floor	---	3	Store
2nd Floor	---	3	1 family dwelling
3rd Floor	---	3	1 family dwelling.

Not more than 2 families to cook independantly on the premises.

This certificate is issued to Frances Baer,

owner of the aforesaid building, address 137 - 9th Ave., N.Y.City.

in accordance with the provisions of Section 5, Article 1, Chapter 5 of the Code of Ordinances of the City of New York, and Chapter 503, Section 411-a of the Greater New York Charter.

DATED Jan. 23, 1922.

Superintendent of Buildings

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN , CITY OF NEW YORK hvc

No. 24242

Date December 9, 1938

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive, Administrative Code (2.1.3.1 to 2.1.3.7.) B.C.)

This certificate supersedes C. O. #

To the owner or owners of the building or premises:

THIS CERTIFIES that the ~~new~~—altered—~~existing~~—building—premises located at
143-9th Avenue
22'4" front
Block 716 Lot 38
, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

~~New~~ Alt. No.—614-1936 Construction classification—~~non~~fireproof

Occupancy classification—Mult.Dwell.Class A . Height 4 stories, 45'0" feet.
Old Law Tenement

Date of completion—November 21, 1938 . Located in business Use District.

A Area— 2 . Height— . Zone at time of issuance of permit—2065-1938 .

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals:

(Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED			USE
		MALE	FEMALE	TOTAL	
Cellar					Bakery
1st Story	100			50	Restaurant
2nd to 4th Story	40 on each				Two (2) Apartments on each floor.

Note: Fuel oil installation approved by Fire Department September 27, 1938.

Borough Superintendent.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof, from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§.646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form 54 C (Rev. 4/62)-BOM-60M-6/63(62) 114

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

Date November 20, 1964 No. 60505 TEMPORARY

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. - - -

THIS CERTIFIES that the new ~~altered existing~~ building - premises located at

401-411 West 18th Street Robt. Fulton Hses Bldg 8 Block 716 Lot 17, 51

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the northwest ~~Corner~~ 9th Avenue & West 18th Street distant Zero feet from the corner formed by the intersection of 9th Avenue and West 18th Street

running thence * SEE feet; thence ..... feet;

thence STATEMENT feet; thence ..... feet;

running thence "A" feet; thence ..... feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~Alt.~~ No.--200-1960 Construction classification--Class 1, Fireproof

Occupancy classification--Hereafter Erected Class "A" Mult. Dwelling Height Bsmt & 6 stories, 59'-7" feet. Located in Unrestricted Datum 14.9 Zoning District.

Date of completion- - - - at time of issuance of permit. 4638-1963

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: 137-63-BZY and The City Planning Commission: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Basement	On ground 120 75 100	2	Incinerator, tank, pump and electric rooms. and lobby and loggia
1st to 6th story, incl	40 each		Six (6) apartments on each story.

NOTE: This is a TEMPORARY Certificate of Occupancy, issued to expire December 14, 1964.

THIS CERTIFICATE ... CERTIFICATE OF COMPLIANCE ... VIOLATION ...

Sec. 6.1.2.3 sub-4 Building Code, C26-273.0 Adm. Code

Prior to the occupancy of any ... erected or altered after January 1, 1938, ... shall be permanently ... stated ... plans and maintained in the main entrance hall of such structure

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

Form 54-C (Rev. 4/62)-80M-6010J6(62) 114

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

Date January 25, 1965 No. 60848 TEMPORARY

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. 60505

THIS CERTIFIES that the new ~~[illegible]~~ building—premises located at 401-411 West 18th Street Robt. Fulton Houses Bldg #8 Block 716 Lot 1751

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the northwest corner ~~[illegible]~~ of 9th Avenue & West 18th Street distant Zero feet from the corner formed by the intersection of Ninth Avenue and West 18th Street

running thence * SEE ..... feet; thence ..... feet;

thence STATEMENT ..... feet; thence ..... feet;

running thence "A" ..... feet; thence ..... feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~[illegible]~~ No. 200-1960 Construction classification—Class 1, Fireproof

Occupancy classification—Hereafter Erected Class "A" Mult. Dwelling Height Bsmt & 6 stories, 59'-7" feet.

Date of completion ~~[illegible]~~ Located in Unrestricted Datum 14.9 Zoning District.

at time of issuance of permit 4638-1963

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: 137-63-BZY, extended to December 15, 1965 **and The City Planning Commission:** (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Basement	On ground 120 75 100	2	Incinerator, tank, pump and electric rooms. and lobby and loggia.
1st to 6th story, incl	40 each		Six (6) apartments on each story.
		NOTE:	This is a TEMPORARY Certificate of Occupancy, issued for a period of ninety (90) days, commencing January 25, 1965.

THIS CERTIFICATE [illegible] BE CONSIDERED A CERTIFICATE OF [illegible] UNDER SECTION [illegible] OF THE MULTIPLE DWELLING LAW.

Sec 6123 sub-4 Building Code, C26 2750 Adm. Code

"Prior to the occupancy of a structure erected or altered after January 1, 1938, the authorized occupancy of such structure as stated in the certificate of [illegible] shall be posted under glass and maintained in the main entrance hall of such structures."

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

Form 54-C (Rev. 4/62)-80M-601036(62) 114

80

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN , THE CITY OF NEW YORK

Date May 20, 1965 No. 61493

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. 60848 Temp.

THIS CERTIFIES that the new—~~XXXXXXXXX~~—building—premises located at 401-411 West 18th Street-(Robert Fulton Houses Bldg. (#8)) Block 716 Lot 17-51

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the Northwest ~~XXXX~~ ~~XXXX~~ from the corner formed by the intersection of 9th Avenue and West 18th Street

running thence *SEE ..... feet; thence ..... feet;

thence STATEMENT "A" ..... feet; thence ..... feet;

running thence ..... feet; thence ..... feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~XXX~~ No.— 200-1960 Construction classification— Class 1 Fireproof

Occupancy classification— Hereafter Erected Class "A" Mult. Dwell. Height Bsmt. & 6 stories, 59'-7" (Datum ~~XXXX~~) feet. Zoning District. Located in Unrestricted

Date of completion— April 19, 1965

at time of issuance of permit. 2547-1962 & 4638-1963

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals and The City Planning Commission: Cal.No. 137-63-BZY, Filed 12-9-63, Approved 1-14-64, Extended to 12/15/65. (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Basement	On ground 120	2	Tank and pump room, N.Y.Steam, Perambulator room, two (2) tenants storage rooms,
	75 100		Electric service room, incinerator rooms, Building lobby and loggia.
1st to 6th Story, Incl.	40 each		Six (6) Apartments on each story.
		NOTE:	Outdoor Parking for five (5) motor vehicles.
		NOTE:	Parking to be used solely for the parking of passenger motor vehicles of tenants on premises except as otherwise provided in Subdivision 1(b) of Section 60 of the Multiple Dwelling Law.
		NOTE:	Premises under control of New York City Housing Authority.

Sec. 6.1.2.3 sub-4 Building Code, C26-273.0 Adm. Code

Prior to the occupancy of a structure erected or altered after January 1, 1938, the authorized [illegible] of each floor of said structure as stated in the certificate of [illegible] shall be permanently posted under glass and maintained in the main entrance hall of such structure.

~~THIS CERTIFICATE SHALL ALSO BE CONSIDERED A CERTIFICATE~~ OF COMPLIANCE OR OCCUPANCY UNDER SECTION 301 OF THE MULTIPLE DWELLING LAW.

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

55-SM-101343 114

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

JT /lc

No. 30467

Date August 23, 1944

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No.

To the owner or owners of the building or premises:

THIS CERTIFIES that the new—~~altered~~—~~existing~~—building—premises located at ~~XXXXXXXXXX~~ 409 West 18th street 25 ft. 0 ins. front Block 716 Lot 29, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. or ~~Alt.~~ No.— 17-1944 Construction classification— Nonfireproof

Occupancy classification— Commercial Height 1 stories, 15 feet.

Date of completion— August 17, 1944 Located in Unrestricted Use District.

A Area 2 Height Zone at time of issuance of permit 485-1944.

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
1st story	On ground			10	Trucking terminal.

Borough Superintendent.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there by any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof, from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form 55-20M-12041 [illegible] 114

DEPARTMENT OF HOUSING AND BUILDINGS

'/1c BOROUGH OF MANHATTAN , CITY OF NEW YORK

No.

Date September 26, 1945

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No. 30467

To the owner or owners of the building or premises:

THIS CERTIFIES that the new—altered existing—building premises located at

409 West 18th street
25 ft. front Block 716 Lot 29

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

(N.B.) or Alt. No. 1179-1945 Construction classification— Nonfireproof

Occupancy classification— Commercial . Height One stories, 15 feet.

Date of completion—August 29, 1945 . Located in Unrestricted Use District.

A Area 2 . Height Zone at time of issuance of permit 1392-1945.

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
1st story	On ground	10	--	10	Trucking Terminal and Storage Garage for not more than four (4) trucks. Fire Equipment, Fire Department approval February 21, 1945.

Edward P. Kearney
Borough Superintendent.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there by any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form—244-1935 Certificate of Occupancy. BA-2087-35-Bu-80

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

KCH CERTIFICATE OF OCCUPANCY No. 21528 1936

Supersedes Certificate of Occupancy No.

To the owner or owners of the building: New York August 11 1936

THIS CERTIFIES that the building located on Block 716, Lot 18

known as 431 West 18th Street

under a permit, Application No. 2212 "front Alt. 726 1936 conforms to the approved plans and specifications accompanying said permit and any approved amendments thereto, and to the requirements of the building code and all other laws and ordinances and to the rules and regulations of the board of standards and appeals, applicable to a building of its class and kind, except that in the case of a building heretofore existing and for which no previous certificate of occupancy has been issued and which has not been altered or converted since March 14, 1916, to a use that changed its classification as defined in the building code, this certificate confirms and continues the existing uses to which the building has been put; and

CERTIFIES FURTHER that the building is of nonfireproof construction within the meaning of the building code and may be used and occupied as a residence building as hereinafter qualified, in an unrestricted district under the building zone resolution, subject to all the privileges, requirements, limitations and conditions prescribed by law or as hereinafter specified.

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED			USE
		MALE	FEMALE	TOTAL	
					Class A Multiple Dwelling
Cellar					Storage
1st story	40				Two Apartments
2nd "	40				Two Apartments
3rd "	40				Two Apartments

This certificate is issued to Louis Gootkin
80 Van Cortlandt Pk.South Bx, for the owner or owners.

The superimposed, uniformly distributed loads, or their equivalent concentrated loads in any story shall not exceed the live loads specified above; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

Unless specifically stated above, the building or any part thereof, if certified as a public building, shall not be used as a building in which persons are harbored to receive medical, charitable or other care or treatment, such as a hospital, asylum, etc., or in which persons are held or detained under legal restraint, such as a police station, jail, etc.; nor shall it be used as a motion picture theatre as defined in section 30, chapter 3, Code of Ordinances; nor as a theatre or opera house or other building intended to be used for theatrical or operatic purposes, or for public entertainment of any kind, for the accommodation of more than 300 persons.

Unless specifically stated above, the building or any part thereof, if certified as a residence building, shall not be used as a tenement house as defined in the tenement house law; nor shall it be used as any form of residence building having more than 15 sleeping rooms; nor shall it be used as a lodging house within the meaning of Sec. 1305 of the Greater New York Charter.

Unless specifically stated above, the building or any part thereof, if certified as a business building, shall not be used as a garage, motor vehicle repair shop or oil selling station as defined in section 1, chapter 10, Code of Ordinances; nor shall it be used for the generation or compression of acetylene; nor as a factory building as defined in the labor law; nor as a grain elevator; nor as a coal pocket.

Except as otherwise noted above, the building, or any part thereof, if located elsewhere than in an unrestricted district, shall not be used for any of the purposes enumerated in paragraph (a) of section 4 of the building zone resolution; nor for any trade, industry or use that is noxious or offensive by reason of the emission of odor, dust, smoke, gas or noise; nor for any kind of manufacturing not already prohibited, except that, if located in a business district, not more than twenty-five per cent. of the total floor space may be so used, or space equal to the area of the lot in any case.

Except as otherwise noted above, the building, if certified as a garage, may not be used for more than five cars on any portion of a street between two intersecting streets, in which portion there exists an exit from or an entrance to a public school, or in which portion there exists any hospital maintained as a charitable institution; and in no case within a distance of 200 feet from the the nearest exit from or entrance to a public school; nor within two hundred feet of any hospital maintained as a charitable institution.

If the building has, at any time previous to the issuance of this certificate, been the subject of an appeal to the board of appeals or of a petition to the board of standards and appeals resulting in modification or variation of law or any lawful requirement, the construction and arrangement of the building as specified in the resolution granting such modification or variation, must be maintained, and all conditions imposed by either board must be observed.

No change or re-arrangement in the structural parts of the building, or affecting the lighting or ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located, until an approval of the same has been obtained from the commissioner of buildings.

This certificate supersedes each and every previously issued certificate of occupancy for this building or any part thereof, and each and every such previously issued certificate shall be null and void; and this certificate in turn becomes null and void upon the issuance of any new lawful certificate.

This certificate does not in any way relieve the owner or owners, or any other person or persons in possession or control of the building, or any part thereof, from obtaining such other permits or licenses as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

This certificate does not authorize the use or operation of any elevator in the building without the special certificate required by section 563 of the building code.

If the building is or is required to be equipped with standpipes or other fire extinguishing or gas shut off appliances, this certificate is not complete until such standpipes or other appliances have been inspected by the fire department (or by the Tenement House Department in the case of a gas shut off in a tenement house) and approved in writing, either in a separate certificate or by endorsement upon this certificate. (Space for such endorsement is provided on page 4 of this certificate.)

If this certificate is marked "Temporary," it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to a tenement house unless also approved by the tenement house commissioner; and it must be replaced by a full certificate as soon as the entire building is completed according to law and ready for occupancy.

The word "class" as used in this certificate refers to the classification of buildings in the building code (section 70).

This certificate is issued in accordance with the provisions of section 411-a of the Greater New York Charter and of section 5 of chapter 5 (Building Code) of the Code of Ordinances of the City of New York.

Examined.

Samuel Gross

Commissioner of Buildings, Borough of Manhattan.

Additional copies of this certificate will be issued, upon written request, to persons having a proprietary interest in the building.

Form—244-1935 Certificate of Occupancy. 8A-2087-35-Bu

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

HVC CERTIFICATE OF OCCUPANCY No. 2111 193 7

Supersedes Certificate of Occupancy No.

To the owner or owners of the building: New York Feb. 2, 1937

THIS CERTIFIES that the building located on Block 716, Lot 17

known as 433 West 18th Street 25' front

under a permit, Application No. 1989 Alt of 1936 conforms to the approved plans and specifications accompanying said permit and any approved amendments thereto, and to the requirements of the building code and all other laws and ordinances and to the rules and regulations of the board of standards and appeals, applicable to a building of its class and kind, except that in the case of a building heretofore existing and for which no previous certificate of occupancy has been issued and which has not been altered or converted since March 14, 1916, to a use that changed its classification as defined in the building code, this certificate confirms and continues the existing uses to which the building has been put; and

CERTIFIES FURTHER that the building is of nonfireproof construction within the meaning of the building code and may be used and occupied as a residence building as hereinafter qualified, in an unrestricted district under the building zone resolution, subject to all the privileges, requirements, limitations and conditions prescribed by law or as hereinafter specified.

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
					Multiple Dwelling Class A
Cellar					Storage
Basement	40				One (1) Apartment
1st Story to 3rd Story	40 on each				Two (2) Apartments on each floor

This certificate is issued to Kaiser Painting Co., 100 East 10th Street, City. for the owner or owners.

The superimposed, uniformly distributed loads, or their equivalent concentrated loads in any story shall not exceed the live loads specified above; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

Unless specifically stated above, the building or any part thereof, if certified as a public building, shall not be used as a building in which persons are harbored to receive medical, charitable or other care or treatment, such as a hospital, asylum, etc., or in which persons are held or detained under legal restraint, such as a police station, jail, etc.; nor shall it be used as a motion picture theatre as defined in section 30, chapter 3, Code of Ordinances; nor as a theatre or opera house or other building intended to be used for theatrical or operatic purposes, or for public entertainment of any kind, for the accommodation of more than 300 persons.

Unless specifically stated above, the building or any part thereof, if certified as a residence building, shall not be used as a tenement house as defined in the tenement house law; nor shall it be used as any form of residence building having more than 15 sleeping rooms; nor shall it be used as a lodging house within the meaning of Sec. 1305 of the Greater New York Charter.

Unless specifically stated above, the building or any part thereof, if certified as a business building, shall not be used as a garage, motor vehicle repair shop or oil selling station as defined in section 1, chapter 10, Code of Ordinances; nor shall it be used for the generation or compression of acetylene; nor as a factory building as defined in the labor law; nor as a grain elevator; nor as a coal pocket.

Except as otherwise noted above, the building, or any part thereof, if located elsewhere than in an unrestricted district, shall not be used for any of the purposes enumerated in paragraph (a) of section 4 of the building zone resolution; nor for any trade, industry or use that is noxious or offensive by reason of the emission of odor, dust, smoke, gas or noise; nor for any kind of manufacturing not already prohibited, except that, if located in a business district, not more than twenty-five per cent. of the total floor space may be so used, or space equal to the area of the lot in any case.

Except as otherwise noted above, the building, if certified as a garage, may not be used for more than five cars on any portion of a street between two intersecting streets, in which portion there exists an exit from or an entrance to a public school, or in which portion there exists any hospital maintained as a charitable institution; and in no case within a distance of 200 feet from the the nearest exit from or entrance to a public school; nor within two hundred feet of any hospital maintained as a charitable institution.

If the building has, at any time previous to the issuance of this certificate, been the subject of an appeal to the board of appeals or of a petition to the board of standards and appeals resulting in modification or variation of law or any lawful requirement, the construction and arrangement of the building as specified in the resolution granting such modification or variation, must be maintained, and all conditions imposed by either board must be observed.

No change or re-arrangement in the structural parts of the building, or affecting the lighting or ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located, until an approval of the same has been obtained from the commissioner of buildings.

This certificate supersedes each and every previously issued certificate of occupancy for this building or any part thereof, and each and every such previously issued certificate shall be null and void; and this certificate in turn becomes null and void upon the issuance of any new lawful certificate.

This certificate does not in any way relieve the owner or owners, or any other person or persons in possession or control of the building, or any part thereof, from obtaining such other permits or licenses as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

This certificate does not authorize the use or operation of any elevator in the building without the special certificate required by section 563 of the building code.

If the building is or is required to be equipped with standpipes or other fire extinguishing or gas shut off appliances, this certificate is not complete until such standpipes or other appliances have been inspected by the fire department (or by the Tenement House Department in the case of a gas shut off in a tenement house) and approved in writing, either in a separate certificate or by endorsement upon this certificate. (Space for such endorsement is provided on page 4 of this certificate.)

If this certificate is marked "Temporary," it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to a tenement house unless also approved by the tenement house commissioner; and it must be replaced by a full certificate as soon as the entire building is completed according to law and ready for occupancy.

The word "class" as used in this certificate refers to the classification of buildings in the building code (section 70).

This certificate is issued in accordance with the provisions of section 411-a of the Greater New York Charter and of section 5 of chapter 5 (Building Code) of the Code of Ordinances of the City of New York.

Examined. JB

Samuel Ehrlich

Commissioner of Buildings, Borough of Manhattan.

Additional copies of this certificate will be issued, upon written request, to persons having a proprietary interest in the building. FCK

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

DOB Violation Display for 101518FISPHAZ87639

Premises: 401 WEST 18 STREET MANHATTAN BIN: 1078443 Block: 716 Lot: 17

Issue Date:	10/15/2018	**Violation Category:**	V - DOB VIOLATION - ACTIVE
Violation Type:	FISP - FACADE SAFETY PROGRAM		
Violation Number:	HAZ87639	**Device No.:**	00801452
OATH/ECB No.:			
Infraction Codes:			
Description:			
Disposition:			
Code:	**Date:**		
Inspector:			
Comments:			

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises:							BIN:	Block:	Lot:
VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE		NAME	

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Environmental Protection

Register with CATS
Login into CATS

NYC.gov always open

NYC DEP CATS Information

SEARCH INFORMATION

Searching For Data...

Contacting Database...Please Wait

Search By :	BBL
*Application# :	
*Borough :	Manhattan
*Block :	716
*Lot :	17
*Premise House# :	
*Premise Street :	
*Premise Borough :	-- Select Borough --
*Captcha :	Input symbols

Search Clear

No Record Found.

Please be advised that application numbers starting with 'C' are associated to boilers, 'P' are associated with industrials and 'G' are associated with Gas stations.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

OBSOLETE BIN RETAINED FOR HISTORICAL PURPOSE ONLY

400 WEST 19 STREET — **MANHATTAN 10011** — **BIN# 1078444**

WEST 19 STREET 400 - 412

Health Area	: 5600	**Tax Block**	: 716
Census Tract	: 89	**Tax Lot**	: 17
Community Board	: 104	**Condo**	: NO
Buildings on Lot	: 3	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents View Challenge Results Pre - BIS PA View Certificates of Occupancy

Cross Street(s):	BRANDON ROMERO PLAZA, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:	LOTS 15 & 17 REAPPORTIONED -- PLEASE SEE BIN 1078445 (3/17)		
Landmark Status:		**Special Status:**	BIN OBSOLETE
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES

Additional BINs for Building: 1078443 1078445
HPD Multiple Dwelling: Yes

Special District: UNKNOWN

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	1	0
Violations-DOB	11	1
Violations-OATH/ECB	2	0
Jobs/Filings	3	
ARA / LAA Jobs	0	
Total Jobs	3	
Actions	40	

OR Enter Action Type:
OR Select from List: Select...
AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 400 WEST 19 STREET MANHATTAN **BIN: 1078444 Block: 716 Lot: 17**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

CO 60565TEMP:	M000060565.PDF
CO 60649-TEMP:	M000060649.PDF
CO 61150-TEMP:	M000061150.PDF
CO 61514:	M000061514.PDF
CO 25024:	M000025024.PDF

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Form 54 C (Rev. 4/62)-BOM 60M 6/1/36(62) [illegible] 114

eb

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

No. 60565 TEMPORARY

Date December 4, 1964

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. - - -

THIS CERTIFIES that the new ~~[illegible]~~ building—premises located at 400-412 West 19th Street Block 716 Lot 1751.

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the N.W.C. side of distant 0'-0" feet from the corner formed by the intersection of Ninth Avenue and West 18th Street

running thence * SEE ..... feet; thence ..... feet;

thence STATE MENT ..... feet; thence ..... feet;

running thence *A* ..... feet; thence .....

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~[illegible]~~ No. 202-1960 Construction classification—Class 1, Fireproof

Occupancy classification—Hereafter Erected Class "A" Height Bsmt & 6 stories, 59'-10 1/8" feet.

Date of completion— - - - , Located in Unrestricted Zoning District.

at time of issuance of permit. 4698-1963 Datum 14.9

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: and The City Planning Commission: 139-63-BZY (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Basement	On ground & 120,100,75	2	Tank and pump and incinerator rooms, lobby and loggia.
1st to 6th story, incl.	40 each		Six (6) apartments on each story.
			NOTE: Time to complete construction is extended to December 15, 1965.
			NOTE: This is a TEMPORARY Certificate of Occupancy, issued for a period of ninety (90) days, commencing December 4, 1964.

THIS CE[illegible]
OF COMP[illegible]
MULTIPL[illegible]

Sec. 6.1.2.3 [illegible] Building Code [illegible] Code

Prior to the [illegible] January

1, 193[illegible] [illegible] 85

stated in [illegible] [illegible]

class and [illegible] in the [illegible] [illegible]

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

Form 54-C (Rev. 4/64)-80M 6010316162) 114

ab

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

Date December 17, 1964 No. 60645 TEMPORARY

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. 60565

THIS CERTIFIES that the new—~~altered~~—building—premises located at 400-412 West 19th Street Block 716 Lot 17, 51

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the N.W.C. side of distant 0'-0" feet from the corner formed by the intersection of Ninth Avenue and West 18th Street

running thence * SEE ..... feet; thence ..... feet;

thence STATEMENT ..... feet; thence ..... feet;

running thence "A" ..... feet; thence ..... feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~Work~~ No.-202-1960

Construction classification—Class 1, Fireproof

Occupancy classification—Hereafter Erected Class "A" Mult. Dwelling Height Apmt # 6 stories, 59'-10 1/8" feet.

Date of completion— - - - Located in Unrestricted Datum Living District.

at time of issuance of permit. 4658-1963

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: 159-63-BZY and The City Planning Commission: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Basement	On ground & 120,100,75	2	Tank and pump and incinerator rooms, lobby and loggia.
1st to 6th story, incl	40 each		Six (6) apartments on each story.
			NOTE: Time to complete construction is extended to December 15, 1965.
			NOTE: This is a TEMPORARY Certificate of Occupancy, issued for a period of ninety (90) days, commencing December 17, 1964.

Sec. 6.1.2.3 sub-d ... Code, C 26 2730 Adm. Code

Prior to the ... 1933 ... stated ... Pars and ...

OFFICE COPY—DEPARTMENT OF BUILDINGS

Borough Superintendent

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

Form 54-C (Rev. 4/62)-80M-6010316(62) 114

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN , THE CITY OF NEW YORK

Date March 17, 1965 No. 61150 TEMPORARY

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. 60649

THIS CERTIFIES that the new ~~building~~ building—premises located at 400-412 West 19th Street (Holt Filton Houses Bldg # 10) Block 716 Lot 17.51

That the zoning lot and premises above referred to are situated bounded and described as follows:

BEGINNING at a point on the N.W.C. side of West 18th Street

distant 0'-0" feet from the corner formed by the intersection of

Ninth Avenue and West 18th Street

running thence "SEE STATEMENT "A" ..... feet; thence ..... feet;

thence ..... feet; thence ..... feet;

running thence ..... feet; thence ..... feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~Block~~ No. 202-1960 Construction classification—Class 1, Fireproof

Occupancy classification—Hereafter Erected Class "A" Multi. Dwelling Height Cellar & 6 stories, 59'-10 1/8" feet.

Date of completion— — — , Located in Unrestricted Zoning District.

at time of issuance of permit 4638-1963

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: 139-63-BZY, extended to December 15, 1965 **and The City Planning Commission:** (Calendar numbers to be inserted later)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Basement	On ground & 120.100.75	2	Tank and pump and incinerator rooms, lobby and loggia.
1st to 6th story, incl.	40 each		Six (6) apartments on each story.
		NOTE	This is a TEMPORARY Certificate of Occupancy, issued for a period of ninety (90) days, commencing March 17, 1965.

THIS CERTIFICATE DOES NOT SUPERSEDE A CERTIFICATE OF COMPLIANCE ISSUED UNDER SECTION 301 OF THE ~~BUILDING~~ CODE.

Sec. 6[illegible] of the Building Code

"Prior to the [illegible] after January 1, 1938, the [illegible] as stated in the [illegible] glass and maintained in the [illegible] of such structures."

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

Form 54-C (Rev. 4/62) 80M 6010360(62) 114

80

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

Date May 26, 1965 No. 61514

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. 61150

THIS CERTIFIES that the new ~~XXXXXXXXXX~~ building—premises located at 400-412 West 19th Street (Robert Fulton Houses Bldg. # 10) Block 716 Lot 8 17-51

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the northwest ~~XXXXX~~ ~~XXXX~~ feet from the corner formed by the intersection of ~~XXXXX~~ and 9th Avenue and West 18th Street

running thence "SEE STATEMENT "A" feet; thence ..... feet;

thence ..... feet; thence ..... feet;

running thence ..... feet; thence ..... feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~of Alt.~~ No.— 202-1960 Construction classification— Class 1 Fireproof

Occupancy classification— Hereafter Erected Class "A" Mult. Dwell. Height, B & 6 stories, 59'-10 1/8" feet. Located in Unrestricted Zoning District.

Date of completion— April 19, 1965 at time of issuance of permit. 2547-1962; 4638-1963

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals and The City Planning Commission: Cal.No. 139-63-BZY, Filed 12/9/63, Approved 1/14/64, Extended to 12/15/65. (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Basement	On ground 120 75 100	2	Tank and pump room, H.I.Steam, Two (2) tenants storage rooms. Incinerator rooms, electric service room, Perambulator room and Building lobby and loggia.
1st to 6th Story, Incl.	40 each		Six (6) apartments on each story.
		NOTE:	Outdoor parking for five (5) motor vehicles.
		NOTE:	Parking to be used solely for the parking of passenger motor vehicles of tenants on premises except as otherwise provided in Subdivision 1(b) of Section 60 of the Multipel Dwelling Law.
		NOTE:	Premises under control of New York City Housing Authority.

Sec. 6.1.2.3 sub-4 Building Code, C.26-273.0 Adm. Code "Prior to the occupancy of a structure erected or altered after January 1, 1938, the authorized occupancy of each floor of said structure as stated in the certificate of occupancy shall be permanently posted under glass and maintained in the main entrance hall of such structures."

THIS CERTIFICATE SHALL ALSO BE CONSIDERED A CERTIFICATE OF COMPLIANCE OR OCCUPANCY UNDER SECTION 301 OF THE MULTIPLE DWELLING LAW.

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft	PERSONS ACCOMMODATED	USE

Borough Superintendent

Form 55

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN , CITY OF NEW YORK RBC

No. 25024

Date Aug. 21, 1939

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code).

This certificate supersedes C. O. No.

To the owner or owners of the building or premises:

THIS CERTIFIES that the ~~new~~—altered—~~existing~~—building—premises located at

406 West 19th Street
25'0" Front

Block 716 Lot 40

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent;

~~New~~ or Alt. No.— 338-39 Construction classification— Non-fireproof

Occupancy classification— Class B. Mult.Dwell Heretofore Converted Height Base & 4 stories, 48'0" feet.

Date of completion— 8-10-39 . Located in Unrestricted Use District.

B Area 1½ . Height Zone at time of issuance of permit 1425-39

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
Cellar					Boiler Room
Basement					Five (5) Furnished Rooms
1-2-3-4 stories					Six (6) Furnished Rooms each floor

Borough Superintendent.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof, from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§.646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

AAM

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

DOB Violation Display for 101518FISPHAZ87640

Premises: 400 WEST 19 STREET MANHATTAN **BIN: 1078444 Block: 716 Lot: 17**

Issue Date:	10/15/2018	**Violation Category:**	V - DOB VIOLATION - ACTIVE
Violation Type:	FISP - FACADE SAFETY PROGRAM		
Violation Number:	HAZ87640	**Device No.:**	00801450
OATH/ECB No.:			
Infraction Codes:			
Description:			
Disposition:			
Code:	**Date:**		
Inspector:			
Comments:			

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises:							BIN:	Block:	Lot:
VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE		NAME	

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

418 WEST 19 STREET — **MANHATTAN 10011** — **BIN# 1078445**

WEST 19 STREET	418 - 422	**Health Area**	: 5600	**Tax Block**	: 716
FULTON HOUSES BUILDING 9	NO NUMBER	**Census Tract**	: 89	**Tax Lot**	: 17
WEST 18 STREET	NO NUMBER	**Community Board**	: 104	**Condo**	: NO
		Buildings on Lot	: 3	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	BRANDON ROMERO PLAZA, 10 AVENUE		
DOB Special Place Name:	LTS 15&17 REAPPORTIONED (3/17)		
DOB Building Remarks:	NEW LT 15=425-433 W18 ST & NEW LT 17=129-145 9 AV/401-423 W18 ST/400-422 W19 ST		
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	Yes		
Special District:	UNKNOWN		

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	28	0
Violations-DOB	21	1
Violations-OATH/ECB	11	0
Jobs/Filings	32	
ARA / LAA Jobs	3	
Total Jobs	35	
Actions	47	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 418 WEST 19 STREET MANHATTAN **BIN: 1078445 Block: 716 Lot: 17**

Download the **Adobe Acrobat Reader** if you are unable to open the PDF files

To report a problem with any of these images, please use the **CO Image Problem Form**

CO 61055-TEMP:	M000061055.PDF
CO 61494:	M000061494.PDF
CO 9931:	M000009931.PDF
JOB 100225285:	NO C/Os ISSUED OR NO IMAGE AVAILABLE

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Form 54-C (Rev. 4/62)—80M-6/61036(62) 114

ab

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

Date March 4, 1965 No. 61055 REVISED

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. - - -

THIS CERTIFIES that the new ~~altered existing~~ building—premises located at 420 West 19th Street - Robt. Fulton Houses - Bldg # 9 Block 716 Lot 17-51

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the northwest side corner distant 0'-0" feet from the corner formed by the intersection of 9th Avenue and West 18th Street

running thence ~~USE~~ ..... feet; thence ..... feet;

thence STATEMENT ..... feet; thence ..... feet;

running thence "A" ..... feet; thence ..... feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~or~~ Alt. No.—201-1960 Construction classification— Class 1, Fireproof

Occupancy classification— ~~Hereafter~~ Hereafter Erected Class "A" Mult. Dwelling Height 25 stories, 215'-8 1/8" feet.

Date of completion— - - - Located in Unrestricted Datum Zoning District.

at time of issuance of permit. 4638-1963

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: 198-63-BZY, extended to December 15, 1965 **and The City Planning Commission:** (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Cellar	On ground	2	Tank and pump room, steam service room, electric and incinerator rooms.
1st story	100 75 40		Lobby, Perambulator room, three (3) apartments.
2nd to 25th story, incl	40 each		Nine (9) apartments on each story.
			Standpipe System approved by Fire Department - October 29, 1964
		NOTE:	This is a TEMPORARY Certificate of Occupancy, issued for a period of ninety days, (90) days, commencing March 4, 1965.
			THIS CERTIFICATE ... AND IS ... CERTIFIED A CERTIFICATE OF COMPLIANCE FOR ... SECTION 301 OF THE MULTIPLE ...
			Sec. 6.1.2.3 sub-4 Building Code, C26-273.0 Adm. Code "Prior to the ... issued after January 1, 1938, the ... of said structure as stated in the certificate of occupancy shall be permanently posted under glass and maintained in the main entrance hall of such structure."

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

Form 54-C (Rev. 4/62)-80M-601036(62) 114

86

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN , THE CITY OF NEW YORK

Date May 20, 1965 No. 61491

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. 61055 Temp.

THIS CERTIFIES that the new building—premises located at 420 West 19th Street (Robert Fulton Houses Bldg. #9) Block 716 Lots 17-51

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the Northwest of the corner formed by the intersection of 9th Avenue and West 18th Street

running thence "SEE STATEMENT "A" feet; thence ..... feet;
thence ..... feet; thence ..... feet;
running thence ..... feet; thence ..... feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. Alt. No.—201-1960 Construction classification— Class 1 Fireproof

Occupancy classification— Hereafter Erected Class "A" Mult. Dwell; Height 25 stories, 215'-8 1/8" (Datum 14.9) feet.

Date of completion— May 14, 1965 Located in Unrestricted Zoning District.

at time of issuance of permit. 2547-1960; 4638-1963

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: Cal.No. 138-63-BZY, Filed 12-9-63, approved 1-14-64, Extended to 12/15/65. **and The City Planning Commission:** (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Cellar	On ground	2	Storage space, tank and pump room, N.Y. Steam, Electric service room and incinerator room.
1st Story	100 75 40		Building lobby Perambulator room Three (3) A partments.
2nd to 25th Story, Incl.	40 each		Nine (9) apartments on each story.
			Standpipe System approved by Fire Department October 29, 1964.
		NOTE:	Outdoor parking for twenty-six (26) motor vehicles.
		NOTE:	Parking to be used solely for the parking of passenger motor vehicles of tenants on premises except as otherwise provided in Subdivision 1(b) of Section 60 of the Multiple Dwelling Law.
		NOTE:	Premises under control of New York City Housing Authority.

THIS CERTIFICATE ALSO IS CONSIDERED A CERTIFICATE OF COMPLIANCE OR OCCUPANCY UNDER SECTION 301 OF THE MULTIPLE DWELLING LAW

Sec. 6.1.2.3 sub-4 Building Code, C.26-273.0 Adm. Code "Prior to the occupancy of a structure erected or altered after January 1, 1938, the authorized occupancy of each floor of said structure as stated in the certificate of occupancy shall be permanently posted under glass and maintained in the main entrance hall of such structures."

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

Form—244-1924 Certificate of Occupancy. 34-2087-24-8

BUREAU OF BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

CERTIFICATE OF OCCUPANCY No. 2231 192 5

Supersedes Certificate of Occupancy No.

To the owner or owners of the building: New York Sept.11 1925

THIS CERTIFIES that the building located on Block 716 , Lot 49

known as 422 West 19th Street
25' front

under a permit, Application No. 1616 Alt of 19 25 conforms to the approved plans and specifications accompanying said permit and any approved amendments thereto, and to the requirements of the building code and all other laws and ordinances and to the rules and regulations of the board of standards and appeals, applicable to a building of its class and kind, except that in the case of a building heretofore existing and for which no previous certificate of occupancy has been issued and which has not been altered or converted since March 14, 1916, to a use that changed its classification as defined in the building code, this certificate confirms and continues the existing uses to which the building has been put; and

CERTIFIES FURTHER that the building is of non-fireproof construction within the meaning of the building code and may be used and occupied as a residence building as hereinafter qualified, in a r unrestricted district under the building zone resolution, subject to all the privileges, requirements, limitations, and conditions prescribed by law or as hereinafter specified.

Story	Live Loads Lbs per sq. ft.	Persons Accommodated			Use
		Male	Female	Total	
1st Story					Non-housekeeping apartments
2nd "					
3rd "					
4th "					

This certificate is issued to Frank Klein, architect
422 West 19th Street, City. , for the owner or owners.

(Over.)

The superimposed, uniformly distributed loads, or their equivalent concentrated loads in any story shall not exceed the live loads specified above; the number of persons of either sex in any story shall not exceed that specified when sex is indicated; nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

Unless specifically stated above, the building or any part thereof, if certified as a public building, shall not be used as a building in which persons are harbored to receive medical, charitable or other care or treatment, such as a hospital, asylum, etc., or in which persons are held or detained under legal restraint, such as a police station, jail, etc.; nor shall it be used as a motion picture theatre as defined in section 30, chapter 3, Code of Ordinances; nor as a theatre or opera house or other building intended to be used for theatrical or operatic purposes, or for public entertainment of any kind, for the accommodation of more than 300 persons.

Unless specifically stated above, the building or any part thereof, if certified as a residence building, shall not be used as a tenement house as defined in the tenement house law; nor shall it be used as any form of residence building having more than 15 sleeping rooms; nor shall it be used as a lodging house within the meaning of Sec. 1305 of the Greater New York Charter.

Unless specifically stated above, the building or any part thereof, if certified as a business building, shall not be used as a garage, motor vehicle repair shop or oil selling station as defined in section 1, chapter 10, Code of Ordinances; nor shall it be used for the generation or compression of acetylene; nor as a factory building as defined in the labor law; nor as a grain elevator; nor as a coal pocket; but, if approved as a factory building for less than twenty-five persons, it shall not be used for any other purpose.

Except as otherwise noted above, the building, or any part thereof, if located elsewhere than in an unrestricted district, shall not be used for any of the purposes enumerated in paragraph (a) of section 4 of the building zone resolution; nor for any trade, industry or use that is noxious or offensive by reason of the emission of odor, dust, smoke, gas or noise; nor for any kind of manufacturing not already prohibited, except that, if located in a business district, not more than twenty-five per cent of the total floor space may be so used, or space equal to the area of the lot in any case.

Except as otherwise noted above, the building, if certified as a garage, may not be used for more than five cars on any portion of a street between two intersecting streets, in which portion there exists an exit from or an entrance to a public school, or in which portion there exists any hospital maintained as a charitable institution; and in no case within a distance of 200 feet from the nearest exit from or entrance to a public school; nor within two hundred feet of any hospital maintained as a charitable institution.

If the building has, at any time previous to the issuance of this certificate, been the subject of an appeal to the board of appeals or of a petition to the board of standards and appeals resulting in modification or variation of law or any lawful requirement, the construction and arrangement of the building as specified in the resolution granting such modification or variation, must be maintained, and all conditions imposed by either board must be observed.

No change or re-arrangement in the structural parts of the building, or affecting the lighting or ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located, until an approval of the same has been obtained from the superintendent of buildings.

This certificate supersedes each and every previously issued certificate of occupancy for this building or any part thereof, and each and every such previously issued certificate shall be null and void; and this certificate in turn becomes null and void upon the issuance of any new lawful certificate.

This certificate does not in any way relieve the owner or owners, or any other person or persons in possession or control of the building, or any part thereof, from obtaining such other permits or licenses as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

This certificate does not authorize the use or operation of any elevator in the building without the special certificate required by section 563 of the building code.

If the building is or is required to be equipped with standpipes or other fire extinguishing or gas shut off appliances, this certificate is not complete until such standpipes or other appliances have been inspected by the fire department (or by the Tenement House Department, in the case of a gas shut off in a tenement house) and approved in writing, either in a separate certificate or by endorsement upon this certificate. (Space for such endorsement is provided on page 4 of this certificate.)

If this certificate is marked "Temporary," it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to a tenement house unless also approved by the tenement house commissioner; and it must be replaced by a full certificate as soon as the entire building is completed according to law and ready for occupancy.

The word "class" as used in this certificate refers to the classification of buildings in the building code (section 70).

This certificate is issued in accordance with the provisions of section 411-a of the Greater New York Charter and of section 5 of chapter 5 (Building Code) of the Code of Ordinances of the City of New York.

Examined, 20

Superintendent of Buildings, Borough of Manhattan.

Additional copies of this certificate will be issued, upon written request, to persons having a proprietary interest in the building.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

DOB Violation Display for 012420FISPHAZ88625

Premises: 418 WEST 19 STREET MANHATTAN BIN: 1078445 Block: 716 Lot: 17

Issue Date:	01/24/2020	**Violation Category:**	V - DOB VIOLATION - ACTIVE
Violation Type:	FISP - FACADE SAFETY PROGRAM		
Violation Number:	HAZ88625	**Device No.:**	00801451
OATH/ECB No.:			
Infraction Codes:			
Description:			
Disposition:			
Code:	**Date:**		
Inspector:			
Comments:			

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Work Permit Data

Premises: 418 WEST 19 STREET MANHATTAN **Filed At: 420 WEST 19 STREET MANHATTAN**

BIN: 1078445 Block: 716 Lot: 17 **Job Type: A2 - ALTERATION TYPE 2**

View Permit History | Printable (PDF) version of this Permit

DOB NOW: *Inspections*

Job No:	123040100			**Fee:**	EXEMPT
Permit No:	123040100-01-EW-MH	**Issued:**	06/01/2021	**Expires:**	05/31/2022
Seq. No.:	02	**Filing Date:**	06/01/2021 ERENEWAL	**Status:**	ISSUED
Work:		**Proposed Job Start:**	04/28/2021	**Work Approved:**	06/06/2017

ALTERATION TYPE 2 - MECH/HVAC
PARTIAL AND NON-STRUCTURAL INTERIOR DEMOLITION IN TRASH HOIST AREA AT BOTH CELLAR AND 1ST FLOOR, AS WELL AS, INSTALLATION OF NEW 2H.R. C.M.U WALL WITH A HOIST REPLACEMENT -VERTICAL RECIPROCATING CONVEYOR. AS WELL AS RE-ROUTING THE BRANCH PIPING ONLY FROM EXISTING DRAIN TO THE EXISTING LEADER. NO CHANGE IN USE,OCCUPANCY AND /OR ERGESS

Use: RES - RESID. BLDG - OLD CODE **Landmark:** NO **Stories:** 25

Site Fill: NOT APPLICABLE

Review is requested under Building Code: 2008

Total Number of Dwelling Units at Location: 216

Number of Dwelling Units Occupied During Construction: 216

Altering 10% or more of the existing floor surface area of the building: No

Issued to: JOSEPH KRAJCZEWSKI

GC SAFETY REGISTRATION: GC 004331

Business: WDF INC

144 EAST 44TH STREET 8TH FL NEW YORK NY 10017

Phone: 212-696-1124

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises:							BIN:	Block:	Lot:
VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE		NAME	

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

401 WEST 19 STREET **MANHATTAN 10011** **BIN# 1012576**

9 AVENUE	149 - 157	**Health Area**	: 5600	**Tax Block**	: 717
WEST 19 STREET	401 - 433	**Census Tract**	: 89	**Tax Lot**	: 19
FULTON HOUSES BUILDING 11	NO NUMBER	**Community Board**	: 104	**Condo**	: NO
		Buildings on Lot	: 1	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	BRANDON ROMERO PLAZA, 10 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES

Additional BINs for Building: NONE
HPD Multiple Dwelling: Yes

Special District: UNKNOWN

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No	
Freshwater Wetlands Map Check:	No	Click here for more information
Coastal Erosion Hazard Area Map Check:	No	
Special Flood Hazard Area Check:	Yes	

Department of Finance Building Classification: D1-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	6	0
Violations-DOB	33	0
Violations-OATH/ECB	5	0
Jobs/Filings	17	
ARA / LAA Jobs	0	
Total Jobs	17	
Actions	163	

OR Enter Action Type:
OR Select from List: Select...
AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

C of O PDF Listing for Property

For Certificates of Occupancy requested on or after March 1, 2021, see DOB NOW.

Premises: 401 WEST 19 STREET MANHATTAN **BIN: 1012576 Block: 717 Lot: 19**

Download the Adobe Acrobat Reader if you are unable to open the PDF files

To report a problem with any of these images, please use the CO Image Problem Form

CO 9758:	M000009758.PDF
CO 60889-TEMP:	M000060889.PDF
CO 61582:	M000061582.PDF
CO 45861:	M000045861.PDF

Back

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Form—1644-1024 Certificate of Occupancy. 3A-0007-34-S

BUREAU OF BUILDINGS

BOROUGH OF MANHATTAN, CITY OF NEW YORK

HVC **CERTIFICATE OF OCCUPANCY No. 3758 192 5**

Supersedes Certificate of Occupancy No.

To the owner or owners of the building: New York July 14 19 25

THIS CERTIFIES that the building located on Block 717, Lot 35

known as 151 Ninth Avenue N.W.C.19th Street
26'3" front

under a permit, Application No. 811 Alt of 19 25 conforms to the approved plans and specifications accompanying said permit and any approved amendments thereto, and to the requirements of the building code and all other laws and ordinances and to the rules and regulations of the board of standards and appeals, applicable to a building of its class and kind, except that in the case of a building heretofore existing and for which no previous certificate of occupancy has been issued and which has not been altered or converted since March 14, 1916, to a use that changed its classification as defined in the building code, this certificate confirms and continues the existing uses to which the building has been put; and

CERTIFIES FURTHER that the building is of non-fireproof construction within the meaning of the building code and may be used and occupied as a business&residence building as hereinafter qualified, in a n unrestricted district under the building zone resolution, subject to all the privileges, requirements, limitations, and conditions prescribed by law or as hereinafter specified.

Story	Live Loads Lbs. per sq. ft.	Persons Accommodated			Use
		Male	Female	Total	
Cellar					Storage
1st Story				5 each	Stores
2nd, 3rd & 4th Story					Tenement

This certificate is issued to J.Pollack, Inc. Contractor
383 West 47th Street, City. , for the owner or owners.

...rved. ... d by either board must

No change or re-arrangement in the structural parts of the building, or affecting the lighting or ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located, until an approval of the same has been obtained from the superintendent of buildings.

This certificate supersedes each and every previously issued certificate of occupancy for this building or any part thereof, and each and every such previously issued certificate shall be null and void; and this certificate in turn becomes null and void upon the issuance of any new lawful certificate.

This certificate does not in any way relieve the owner or owners, or any other person or persons in possession or control of the building, or any part thereof, from obtaining such other permits or licenses as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

This certificate does not authorize the use or operation of any elevator in the building without the special certificate required by section 563 of the building code.

If the building is or is required to be equipped with standpipes or other fire extinguishing or gas shut off appliances, this certificate is not complete until such standpipes or other appliances have been inspected by the fire department (or by the Tenement House Department, in the case of a gas shut off in a tenement house) and approved in writing, either in a separate certificate or by endorsement upon this certificate. (Space for such endorsement is provided on page 4 of this certificate.)

If this certificate is marked "Temporary," it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to a tenement house unless also approved by the tenement house commissioner; and it must be replaced by a full certificate as soon as the entire building is completed according to law and ready for occupancy.

The word "class" as used in this certificate refers to the classification of buildings in the building code (section 70).

This certificate is issued in accordance with the provisions of section 411-a of the Greater New York Charter and of section 5 of chapter 5 (Building Code) of the Code of Ordinances of the City of New York.

Examined

.....
Superintendent of Buildings, Borough of Manhattan.

Additional copies of this certificate will be issued, upon written request, to persons having a proprietary interest in the building.

Form 54-C (Rev. 4/62)-80M 60[illegible](62) [illegible] 114

DEPARTMENT OF BUILDINGS

eb

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

No. 60889

Date January 29, 1965

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. - - -

THIS CERTIFIES that the new ~~altered existing~~ building—premises located at Block 717 Lot 19-38

401-419 West 19th Steet - Bldg # 11

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the Northwest Corner of Ninth Avenue

distant 01-0" feet from the corner formed by the intersection of

Ninth Avenue and West 19th Street feet;

running thence South 78'-10" feet; thence west 375'-0" feet;

thence south 72'-0" feet; thence east 375'-0" feet;

running thence feet; thence feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~Ex-Alt.~~ No. 203-1960 Construction classification—Class 1, Fireproof

Occupancy classification—Hereafter Erected Class "A" Mult. Dwelling Height Located in Unrestricted Part 4 & 6 stories, 59'-5" feet. Datum Zoning District.

Date of completion—

at time of issuance of permit. 4638-1963

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: 140-63-BZY extended to 12/15/65 (Calendar numbers to be inserted here) **and The City Planning Commission:**

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Basement	On ground 120 75 100	2	Pump and tank room, tenant storage. Perambulator and utility rooms, lobby and loggia.
1st to 6th storyinel.	40 each		Six (6) apartments on each story.
		NOTE:	This is a TEMPORARY Certificate of Occupancy, issued for a period of ninety (90) days, commencing January 29, 1965.

OF COMPLIANCE [illegible] ARTICLE 301 OF THE MULTIPLE DWELLING LAW.

Sec. 6.1.2.3 sub-4 Building Code, C.26-273.0 Adm. Code "Prior to the occupancy of a structure erected or altered after January 1, 1938, the authorized occupancy of said structure as stated in the certificate of occupancy shall be conspicuously posted under glass and maintained in the main entrance of such structure."

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft	PERSONS ACCOMMODATED	USE

Borough Superintendent

Form 51-C (Rev. 4/62)-80M-601030(62)

80

DEPARTMENT OF BUILDINGS

BOROUGH OF MANHATTAN, THE CITY OF NEW YORK

Date June 7, 1965 No. 61582

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. 60889 Temp

THIS CERTIFIES that the new building—premises located at 401-419 West 19th St. (Robert Fulton Houses Bldg. 11 Block 717 Lot a 19-38

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the northwest side of 9th Avenue from the corner formed by the intersection of and West 19th Street

running thence north 78'-10" feet; thence west 375'-0" feet;

thence south 72'-0" feet; thence east 375'-0" feet;

running thence feet; thence feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. Application No.— 203-1960 Construction classification— Class 1 Fireproof

Occupancy classification— Hereafter Erected Class "A" Mult. Dwelling Height Bsmt. & 6 stories, 59'-5" feet.

Date of completion— June 1, 1965 Located in Unrestricted Zoning District, Datum 14'-0"

at time of issuance of permit, 2547-1962; 4638-1963

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals and The City Planning Commission: Cal. No. 140-63-BZY filed 12-9-63, approved 1-14-64, Extended to December 15, 1965. (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Basement	On ground 120 75 100	2	Pump and tank room (N.Y.Steam) Two (2) tenants storage rooms. Perambulator and incinerator rooms, electric service room - and - Building lobby and loggia.
1st to 6th Story, Incl.	40 each		Six (6) apartments on each story.
		NOTE:	Outdoor parking for six (6) motor vehicles.
		NOTE:	Parking to be used solely for the parking of passenger motor vehicles of tenants on premises except as otherwise provided in Subdivision 1(b) of Section 60 of the Multiple Dwelling Law.
		NOTE:	Premises under control of New York City Housing Authority.

Sec. 6.1.2.3 sub-4 Building Code, C26-273.0 Adm. Code

Prior to the occupancy of a structure erected or altered after January 1, 1938, the authorized occupancy of each floor of said structure as stated in the certificate of occupancy shall be permanently posted under glass and maintained in the main entrance hall of such structures.

THIS CERTIFICATE SHALL ALSO BE CONSIDERED A CERTIFICATE OF COMPLIANCE OR OCCUPANCY UNDER SECTION 301 OF THE MULTIPLE DWELLING LAW

Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

Form 54-115M-701627(53) 114

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF MANHATTAN , CITY OF NEW YORK

No. 45861

Date June 20, 1956

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No.

To the owner or owners of the building or premises:

THIS CERTIFIES that the ~~new~~—altered—~~existing~~—building—premises located at

421 West 19th Street Block 717 Lot 25

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

~~N.B. or~~ Alt. No.— 592-1955 Construction classification— Class 3 nonfireproof

Occupancy classification—Old Law Tenement , Height Bsmt. & 4 stories, 45 feet.

Date of completion— Class "A" Mult. Dwell. June 16, 1956 . Located in Unrestricted Use District.

B Area 2 . Height Zone at time of issuance of permit 182-1956; 1244-1955

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED			USE
		MALE	FEMALE	TOTAL	
Cellar	on ground				Boiler room and storage.
Basement	40				Two (2) apartments.
1st to 4th story, incl.	40 each				Two (2) apartments on each story.

Borough Superintendent

CERTIFICATE WILL BE NULL AND VOID IF ALTERED IN ANY MANNER OR ADDITIONS ARE MADE THERETO.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

NYC Buildings

NYC

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

NO RECORDS WERE FOUND FOR BOILER FILE

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises:							BIN:	Block:	Lot:
VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE		NAME	

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Joanne Bedkowski

From: New York DEC Support <newyorkdec@mycusthelp.net>
Sent: Wednesday, March 30, 2022 4:49 PM
To: Joanne Bedkowski
Subject: Freedom of Information Law Request :: W098706-032822

--- Please respond above this line ---

Region 2 - Long Island City
P: (718) 482-4912 | F:
www.dec.ny.gov

RE: PUBLIC RECORDS REQUEST of 3/28/2022, Reference # W098706-032822

Date: 03/30/2022

Dear Ms. Joanne Bedkowski,

I write in response to your Freedom of Information Law (FOIL) request seeking:

> *Records regarding above and underground storage tanks, permits and/or violations, spills, hazardous material and any other information of environmental concern as we are conducting a Phase I Environmental Site Assessment. (My ref#: Z3-4898), Time frame: 01/01/1963 - 03/28/2022 - Fulton - Various addresses (see attached address listing), Manhattan, NY 10011*

Please be advised that a diligent search of the files maintained by DEC produced no responsive records.

If you believe you have been unlawfully denied access to responsive records, you have the right to appeal. Any such appeal must be submitted in writing and within thirty (30) days of the date of this email. Appeals must be directed to:

FOIL Appeals Officer
Office of General Counsel
New York State Department of Environmental Conservation
625 Broadway, 14th Floor
Albany, NY 12233-1500

Your FOIL request is now closed. If I can be of further assistance, please contact me at (718) 482-4912 and reference FOIL #W098706-032822, or simply reply to this email. Thank you.

Sincerely,

Region 2 FOIL Coordinator

Joanne Bedkowski

From: New York DEC Support <newyorkdec@mycusthelp.net>
Sent: Monday, March 28, 2022 6:13 PM
To: Joanne Bedkowski
Subject: FOIL Request :: W098706-032822

Dear Joanne:

Thank you for your Freedom of Information Law (FOIL) request. Your request has been received and is being processed. Your request was received in this office on 3/28/2022 and given the reference number FOIL #W098706-032822 for tracking purposes. You may expect the Department's response to your request no later than **4/26/2022**.

Record Requested: **Records regarding above and underground storage tanks, permits and/or violations, spills, hazardous material and any other information of environmental concern as we are conducting a Phase I Environmental Site Assessment. (My ref#: Z3-4898), Time frame: 01/01/1963 - 03/28/2022 - Fulton - Various addresses (see attached address listing), Manhattan, NY 10011**

You can monitor the progress of your request at the link below and you'll receive an email when your request has been completed. Again, thank you for using the FOIL Center.

https://mycusthelp.com/NEWYORKDEC/_rs/RequestLogin.aspx

New York State Department of Environmental Conservation, Record Access Office

---

Track the issue status and respond at: https://newyorkdec.mycusthelp.com/webapp//_rs/RequestEdit.aspx?rid=98706

Joanne Bedkowski

From: donotreply@records.nyc.gov
Sent: Monday, March 28, 2022 5:51 PM
To: Joanne Bedkowski
Subject: [OpenRecords] Request FOIL-2022-826-01508 Submitted to Department of Environmental Protection (DEP)

Your request FOIL-2022-826-01508 has been successfully submitted to the Department of Environmental Protection (DEP). The details of your request are shown below.

Request Title: FOIL Request

Request Description: Records regarding above and underground storage tanks, permits and/or violations, spills, hazardous material and any other information of environmental concern as we are conducting a Phase I Environmental Site Assessment. (My ref#: Z3-4898), Time frame: 01/01/1963 - 03/28/2022 - Fulton - Various addresses (see attached address listing), Manhattan, NY 10011

Attached File: Fulton.pdf: Fulton.pdf

Requester's Contact Information

Name:
Joanne Bedkowski
Title:
Z3-4898
Organization:
Hillmann Consulting, LLC
Email:
jbedkowski@hillmanngroup.com
Phone Number:
(908) 688-7800
Fax Number:
(908) 686-2636
Street Address (line 1):
1600 Route 22 East
Street Address (line 2):
Suite 107
City:
Union
State:
NJ
Zip Code:
07083

You can view the request and take any necessary action at the following webpage: https://a860-openrecords.nyc.gov/request/view/FOIL-2022-826-01508.

APPENDIX G

PROJECT PERSONNEL QUALIFICATIONS

Chris Hirschmann, CHMM

Director, Site Investigation & Remediation Services

EDUCATION:

B.S. Environmental Science, Cornell University

M.S., Environmental Science, NJIT – Rutgers University

CERTIFICATION:

OSHA 40-Hour HAZWOPER

OSHA HAZWOPER Supervisor

OSHA 10-Hour Construction

Certified Hazardous Materials Manager (CHMM) #14701

NJDEP Subsurface Evaluator #572258

Hazardous Waste Management Certification

Site Remediation Basics Certification

New York City Office of Environmental Remediation (NYCOER) Brownfield Certification (TurboTraining)

OSHA 30-Hour 1910 General Industry Training

YEARS OF EXPERIENCE:

With Hillmann: 12

Total: 14

PROFESSIONAL EXPERIENCE:

Mr. Hirschmann is currently the Director, Site Investigation & Remediation Services at Hillmann Consulting, LLC. As such, he is responsible for managing and implementing soil, groundwater, and soil vapor subsurface investigations and remediation; regulatory compliance; storage tank closure and install; and third party document review.

Mr. Hirschmann has extensive experience in evaluating and investigating sites for subsurface contamination and instituting remedial activities for commercial and industrial properties (including City & State regulatory & brownfield programs). He also performs SPCC plan preparation and hazardous materials management; and performs Phase I environmental site assessments to meet due diligence requirements under CERCLA, including the quality assurance of technical reports.

Representative experience includes:

The Doe Fund, Bronx, NY:

Identified as a spill case with confirmed soil, groundwater and soil/vapor contamination with the New York State Department of Environmental Conservation (NYSDEC) and brownfield and e-designation site with New York State Office of Environmental Remediation (NYCOER). Mr. Hirschmann functioned as the project director for Hillmann and prepared the remedial investigation work plan (RIWP), conducted remedial investigation activities and prepared a Remedial Investigation Report (RIR). Based on the RIR Hillmann prepared a Remedial Action Work Plan (RAWP) that was subsequently approved by the NYSDEC and NYCOER. Under the direction of Mr. Hirschmann, Hillmann provided oversight and direction of remedial activities, including implementation of a Community Air Monitoring Plan, during site redevelopment activities.

Women in Need, Brooklyn, NY:

Identified as an e-designation and brownfield case with soil and soil/vapor contamination with NYCOER. Mr. Hirschmann functioned as the project director for Hillmann and prepared the remedial investigation work plan (RIWP), conducted remedial investigation activities and prepared a Remedial Investigation Report (RIR). Based on the RIR Hillmann designed and prepared a Remedial Action Work Plan (RAWP) that was subsequently approved by the NYCOER. Under the direction of Mr. Hirschmann, Hillmann provided oversight and direction of remedial activities during site redevelopment activities.

TLK Manor, Bronx, NY:

Identified as a contaminated property under the purview of NYCDEP, Hillmann provided investigation and remediation services related to redevelopment activities. Mr. Hirschmann functioned as the project director and conducted the remedial investigation and prepared a Remedial Action Work Plan based on the results of the soil, groundwater and soil/vapor investigation. During redevelopment

HILLMANN CONSULTING

activities, under the direction of Mr. Hirschmann, Hillmann provided oversight and direction of remedial activities including implementation of a Community Air Monitoring Plan.

BP Real Estate Fund, Queens, NY

Hillmann was retained to address the e-designation on the property for hazardous materials prior to redevelopment activities. Mr. Hirschmann functioned as the project director and prepared a Remedial Investigation Workplan, conducted the Remedial Investigation soil, groundwater and soil vapor sampling activities and issued the Remedial Investigation Report to the NYCOER. The NYCOER subsequently removed the e-designation from the property after review and approval of project documents.

AIG, Bernardsville, NJ:

The Property had a leaking underground storage tank (UST) identified as a spill case with the New Jersey Department of Environmental Protection (NJDEP) and contained widespread soil and groundwater contamination. Hillmann provided investigation and remedial activities at the site including: delineation of soil and groundwater contamination, preparation of remedial action plans for the NJDEP, enhanced fluid recovery for groundwater remediation, injection remediation of groundwater including chemical oxidation material and microbe material to break down and remediate the elevated contaminants found in the groundwater. Mr. Hirschmann was the project manager and NJDEP certified Subsurface Evaluator for the remedial activities.

City of Newark, New Jersey:

Hillmann provided investigation and remediation activities for five City owned brownfield properties. Mr. Hirschmann functioned as the project manager for oversight, design, implementation and management of soil and groundwater remedial investigations at the properties.

Unique People Services, Bronx, New York

Identified as a contaminated property under the purview of NYCDEP, Hillmann provided investigation and remediation services related to redevelopment activities. Mr. Hirschmann functioned as the project director and conducted the remedial investigation and prepared a Remedial Action Work Plan based on the results of the soil, groundwater and soil/vapor investigation. During redevelopment activities, under the direction of Mr. Hirschmann, Hillmann provided oversight and direction of remedial activities including implementation of a Community Air Monitoring Plan.

Notias Construction, NY, NY:

Hillmann provided environmental investigation activities for 5 separate sites in Manhattan, NY. Mr. Hirschmann functioned as the project manager and prepared Phase II Investigation workplans for soil and soil-vapor sampling, directed site investigation activities and prepared Remedial Investigation Reports for each site. Where

HILLMANN CONSULTING

contamination was identified, Mr. Hirschmann prepared Remedial Action Work Plans for slated redevelopment activities.

AIG: Northeastern States: Hillmann provides ongoing environmental consulting for this client including decommissioning of fuel oil storage tanks, investigation and remediation of fuel oil contaminated soil and groundwater. Mr. Hirschmann provides third-party oversight on behalf of this client to ensure the contractors/consultants onsite are performing project activities in accordance with industry and regulatory protocol. When applicable on certain projects, Mr. Hirschmann will also direct full remedial investigation and remedial activities as the project manager.

HILLMANN
CONSULTING

Etan Hindin

Senior Project Manager

EDUCATION:

B.S. Biology, Bar Ilan University, Ramat Gan, Israel

CERTIFICATIONS:

US EPA AHERA Asbestos Inspector

New York State Asbestos Project Monitor

New York State Air Sampling Technician

NJDEP GIS Training

Environmental Audit and Site Assessments (Rutgers NJAES)

40-hr OSHA Hazardous Waste Operations and Emergency Response (HAZWOPER) Training

8-hr OSHA HAZWOPER Refresher Training

YEARS OF EXPERIENCE:

With Hillmann: 1 year

Total: 11 years

PROFESSIONAL EXPERIENCE:

As a Senior Project and Account Manager, Mr. Etan Hindin advises private and public sector clients on a broad range of environmental projects including due diligence (Phase I and II), regulatory compliance, HSE audits, soil and groundwater remediation, and mold investigations and asbestos surveys. Mr. Hindin is responsible for proposing project services, bidding, managing projects, and meeting with clients.

Mr. Hindin has conducted Phase I's of commercial and industrial sites throughout the country and has provided EH&S consulting to Fortune 500 companies. He is particularly well versed in environmental, health and safety regulations and he strives to provide creative, effective, and efficient solutions to complex environmental problems.

Representative experience includes:

Enviro-Sciences (of Delaware), Inc.: From 2011 to 2018, Mr. Hindin served as a Project Manager at Enviro-Sciences (of Delaware), Inc. where he designed sampling programs, oversaw abatement projects, and performed clearance sampling for mold and asbestos. He also managed environmental due diligence projects of commercial and industrial sites, throughout the US. Mr. Hindin often trained entry-level consultants in database review, report writing, and assessment protocols while working to improve report templates to comply with changing regulations and ASTM standards.

NJDEP Watershed Ambassadors Program: From 2010 to 2011, Mr. Hindin worked as a New Jersey Watershed Ambassador for the NJDEP where he monitored water quality utilizing NJDEP protocols and online reporting software, utilized GIS, NJGeoWeb, and DataMiner to research assigned water bodies and surrounding areas. Mr. Hindin also presented on watershed management, resource conservation, sustainability, and environmental regulations.