PHASE I ENVIRONMENTAL SITE ASSESSMENT

for

27-21 44th DRIVE, 44-18 PURVES STREET
Long Island City, New York

Prepared For:

Silvercup Properties, LLC
42-22 22nd Street
Long Island City, New York 11101

Prepared By:

Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.
21 Penn Plaza
360 West 31st Street, 8th Floor
New York, New York 10001

Jason Hayes, P.E., LEED AP
Associate

January 13, 2014
Langan Project No. 170281401

LANGAN

TABLE OF CONTENTS

1.0 EXECUTIVE SUMMARY 1

2.0 INTRODUCTION 1

2.1 Scope of the ESA 1

2.2 Assumptions, Limitations, and Exceptions 2

3.0 SITE DESCRIPTION 4

3.1 Location and Description 4

3.2 Description of Site Improvements 4

3.3 Title Records 5

4.0 USER PROVIDED INFORMATION 8

4.1 User Questionnaire and Owner/Operator Questionnaires 8

4.2 Previous Environmental Reports 8

5.0 ENVIRONMENTAL RECORDS 10

5.1 Federal Agency Database Findings 12

5.2 State Agency Database Findings 12

5.3 Local Regulatory Agency Findings 15

5.4 Physical Setting Sources 17

5.4.1 Topography 17

5.4.2 Geology 17

5.4.3 Hydrology 17

5.5 Historical Use Information 18

5.5.1 Aerial Photographs 18

5.5.2 Sanborn Fire Insurance Maps 18

5.5.3 Historical USGS Topographic Quadrangles 22

5.5.4 City Directories 23

5.5.5 Environmental Lien Search 23

6.0 SITE RECONNAISSANCE 24

6.1 Methodology and Limiting Conditions 24
6.1.1 Date and Time of Inspection 24
6.2 General Site Setting and Reconnaissance Observations 24
7.0 INTERVIEWS 28
7.1 Site Owner/ User 28
7.2 Site Occupants 28
7.3 Owners/Tenants of Adjacent Properties 28
8.0 ADDITIONAL SERVICES 29
8.1 Radon 29
8.2 Asbestos-Containing Material, Lead-Based Paint, and PCBs 29
9.0 DEVIATIONS AND DATA GAPS 30
9.1 Deviations 30
9.2 Data Gaps 30
10.0 FINDINGS, OPINIONS, AND CONCLUSIONS 31
11.0 REFERENCES 33
12.0 STATEMENT OF QUALIFICATIONS AND SIGNATURES 34

FIGURES

Figure 1 Site Location Map

APPENDICES

Appendix A Site Reconnaissance Photographs
Appendix B User Questionnaire
Appendix C Previous Environmental Report
Appendix D Environmental Data Resources Inc. ™ Report
Appendix E Freedom of Information Act Requests
Appendix F New York City Department of Building Records
Appendix G New York City Planning Commission Zoning Map
Appendix H Aerial Photographs
Appendix I Sanborn Fire Insurance Maps
Appendix J Historical USGS Topographic Quadrangle Maps Summary
Appendix K City Directory Abstract
Appendix L Environmental Lien Search
Appendix M Resumes

1.0 EXECUTIVE SUMMARY

Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C. (Langan) prepared this Phase I Environmental Site Assessment (ESA) on behalf of Silvercup Properties, LLC (the "User") for the property located at 27-21 44th Drive and 44-18 Purves Street ("Subject Property") in Queens, New York. The Subject Property occupies Tax Block 268, Lots 4, 22, and 23 in the Long Island City neighborhood of the borough of Queens. This Phase I ESA was performed in support of potential acquisition of the Subject Property.

The Subject Property is located in an urban area characterized by commercial and manufacturing buildings and vacant land on the block bordered by Jackson Avenue to the north, Purves Street to the east, Thomson Avenue to the south, and 44th Drive to the west. The approximately 14,145 square-foot Subject Property is developed with a one-story commercial building with garage/warehouse space on Lot 4. Lots 22 and 23 are vacant with no observable improvements. The sidewalk elevation along Purves Street (east side of Subject Property) is approximately el 8 (Queens Highway Datum). The sidewalk elevation along 44th Drive (west side of Subject Property) is approximately 15 feet higher than the sidewalk elevation along Purves Street.

Based on a previous investigations conducted at the Subject Property, groundwater depth ranges from approximately 5 to 10 feet below grade surface (bgs). Based on topography, regional groundwater flow is inferred to be to the west to southwest towards the East River. The New York City Metropolitan Transit Authority (MTA) M and E subway lines extend underneath Jackson Avenue approximately 175 feet north of the Subject Property.

This Phase I ESA was conducted in accordance with the American Society for Testing and Materials (ASTM) Practice E1527-05 and E1527-13 (Standard Practice for ESA: Phase I ESA Process), and the United States Environmental Protection Agency's (USEPA) 2006 All Appropriate Inquiry (AAI) Rule (40 CFR Part 312) now in effect. To the extent that ASTM 1527-13 differs in definition and terminology from ASTM 1527-05, this report follows the current ASTM 1527-13 terminology. Completion of a Phase I ESA in accordance with the ASTM Practice and AAI Rule is needed to qualify for the bona fide prospective purchaser liability protections available under the Comprehensive Environmental Response Compensation and Liability Act (CERCLA). The objective of this Phase I ESA was to identify the presence or likely presence, use, or release on the Subject Property of hazardous substances or petroleum products as defined in ASTM E1527-13 as a recognized environmental condition (REC).

The Phase I ESA identified the following RECs, de minimis conditions, and other environmental concerns associated with the Subject Property:

REC 1 – Historic Site Use

Historic use of Lot 4 includes a garage with a gasoline tank in 1936; a paper warehouse and photo chemical warehouse in 1947; and an auto body shop from 1977 to at least 2006. Lots 22 and 23 were part of an operation identified as "Controller Manufacturing" between 1936 and 1950. From 1970 through 2006, Lot 22 is shown as welding and repairs with city directory listings that include Rozilda labs, leather goods, plating equipment, manufacturing and Artisan Designs. The historic uses involve the storage, application, and disposal of hazardous substances. Leaks, spills, or discharges of solvents, petroleum products, polychlorinated biphenyls (PCB), metals and/or other hazardous substances used at the historic facilities may have adversely impacted soil, groundwater, and/or soil vapor.

REC 2 – Documented Site Contamination

Soil and groundwater contaminant concentrations were identified above New York State standards. Elevated soil and groundwater concentrations of petroleum volatile organic compounds (VOC) were detected adjacent to the suspected tank. Additionally, chlorinated VOCs were identified in groundwater. Onsite PCE groundwater concentrations ranged from non-detect along the southwestern portion of the site to 950 µg/L at a monitoring well in the northeastern portion of Lot 22. Onsite TCE concentrations ranged from non-detect along the southwestern portion of the site to 150 µg/L in the northeastern portion of Lot 22.

REC 3 – NYSDEC Spill and Potential On-Site Underground Storage Tank

A gasoline underground storage tank (UST) is potentially located in the Lot 4 building basement. The tank was identified on a 1936 Sanborn map and previous reports indicate the presence of a vent pipe that was traced to a concrete patch in the basement floor. Remnants of a concrete dispenser island were visible immediately behind the garage door. Site constraints prevented a geophysical survey to document the presence of the tank. Petroleum staining, odor and elevated field instrument readings were identified in the vicinity of the potential UST. Elevated concentrations of petroleum volatile organic compounds (VOCs) were detected within the impacted soil. Based on these observations and associated analytical data, a spill was called in to the New York State Department of Environmental Conservation (NYSDEC) and Spill No. 1302045 was assigned.

REC 4 – Surrounding Property Use

Current and historic uses of the adjoining and/or surrounding properties include gasoline filling stations, manufacturing facilities, auto repair stations/garages with gasoline tanks, iron works,

drycleaners, a chemical laboratory, an oil-burning utility company, and printing facilities. Additionally, two open spills (Spill Numbers 1000528 and 9913082) were identified on properties less than 700 feet from the Subject Properties. Voluntary Cleanup Program and Brownfield Cleanup Program sites with documented soil and groundwater contamination were identified on surrounding properties. Monitoring wells were identified on surrounding properties, which may indicate past or current environmental monitoring. Leaks, spills, or discharges of solvents, petroleum products, and/or other hazardous substances associated with surrounding property use may have adversely impacted groundwater and/or soil vapor beneath the Subject Property.

De Minimis Condition

Staining was observed on the Lot 4 building office and basement floor and the garage/warehouse walls and floor. The concrete floor slab beneath each area of staining appeared to be competent and significant subsurface impact is unlikely.

Non-ASTM Environmental Concerns

The building was constructed in the 1930s, potentially with materials that contain asbestos, lead-based paint, or polychlorinated biphenyls (PCBs). In addition, the building contained fluorescent light ballasts, which may contain PCBs.

No Historic RECs (HRECs) or Controlled RECs (CRECs) were identified.

2.0 INTRODUCTION

Langan was retained by Silvercup Properties, LLC (the "User") to prepare a Phase I Environmental Site Assessment (ESA) for the property located at 27-21 44th Drive and 44-18 Purves Street ("Subject Property") in Queens, New York. The Subject Property occupies Tax Block 268, Lots 4, 22, and 23 in the Long Island City neighborhood of the borough of Queens. This Phase I ESA was performed in support of potential acquisition of the Subject Property by Silvercup Properties, LLC.

The purpose of this ESA is to accomplish the following:

> (1) Identify Recognized Environmental Conditions (RECs) in connection with the Subject Property, as defined in The Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, Designation E1527-13, which states: The presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: (1) due to any release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of a future release to the environment. The term is not intended to include de minimis conditions that generally do not present a material risk of harm to public health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies.
>
> (2) Be consistent with the criteria of United Stated Environmental Protection Agency 40 CFR Part 312 Subpart C Standards and Practices §312.20 All Appropriate Inquiries.

2.1 Scope of the ESA

This ESA was conducted utilizing a standard of good commercial and customary practice that is consistent with ASTM E1527-13. Any significant scope-of-work additions, deletions, or deviations to ASTM E1527-13 are noted in Section 9.0 of this report. In general, the scope of this assessment consisted of obtaining information from the User; reviewing reasonably ascertainable information and environmental data relating to the Subject Property; reviewing maps and records maintained by federal, state, and local regulatory agencies; interviewing

persons knowledgeable about the Subject Property; and conducting a site inspection. The specific scope of this assessment included the following:

1. A site reconnaissance to inspect on-site conditions and assess the Subject Property and surrounding property uses and natural surface features. Photographs taken as part of the site reconnaissance are provided in Appendix A.
2. A review of the responses to a User/Client Questionnaire. The completed Questionnaire is provided in Appendix B.
3. A review of a previous environmental report for the Subject Property. The report is provided in Appendix C.
4. A review of environmental databases maintained by the USEPA, state, and local agencies within the approximate minimum search distance. The environmental database report was provided by Environmental Data Resources, Inc. (EDR), and is included in Appendix D.
5. Filing of Freedom of Information Act (FOIA) requests with federal, state, and local agencies. Copies of the FOIA requests are included in Appendix E.
6. A review of New York City Department of Buildings (NYCDOB) records, zoning resolutions and a Planning Commission Zoning Map. Available NYCDOB records and the Zoning Map are included in Appendices F and G, respectively.
7. A review of physical characteristics of the Subject Property through a review of referenced sources for topographic, geologic, soils, and hydrologic data.
8. A review and interpretation of aerial photographs, Sanborn Fire Insurance Maps (Sanborn Maps), historical topographic maps, and city directories to identify previous activities on and in the vicinity of the Subject Property. Copies are included in Appendices H, I, J and K, respectively.
9. A review of an Environmental Lien search for the Subject Property. A copy of the environmental lien search report is included as Appendix L.
10. A review of published radon occurrence maps to evaluate whether the Subject Property is located in an area with a propensity for elevated radon levels.

2.2 Assumptions, Limitations, and Exceptions

This Phase I ESA report was prepared for the User for the property at 27-21 44th Drive and 44-18 Purves Street (Tax Block 268, Lots 4, 22, and 23) in Queens, New York. The report is intended to be used in its entirety. Excerpts taken from this report are not necessarily representative of the assessment findings. Langan cannot assume responsibility for use of this

report for any property other than the Subject Property addressed herein, or by any other third party without a written authorization from Langan.

Langan's scope of services, which is described in Section 2.1, was limited to that agreed to with the User and no other services beyond those explicitly stated are implied. The services performed and agreed upon for this effort comports to those prescribed in the ASTM Standard E 1527-05 and E1527-13. To the extent that ASTM 1527-13 differs in definition and terminology from ASTM 1527-05, this report follows the current ASTM 1527-13 terminology. Sampling (e.g. soil borings and groundwater sampling) was not performed as part of this Phase I ESA.

This Phase I ESA was not intended to be a definitive investigation of possible environmental impacts at the Subject Property. The purpose of this investigation was limited to determining if there is reason to suspect the possibility of RECs at the Subject Property. It should be understood that even the most comprehensive Phase I ESA may fail to detect environmental liabilities at a particular Subject Property. Therefore, Langan cannot "insure" or "certify" that the Subject Property is free of environmental impacts. No expressed or implied representation or warranty is included or intended in this report, except that our services were performed, within the limits prescribed by our client, with the customary standard of care exercised by professionals performing similar services under similar circumstances within the same jurisdiction.

The conclusions, opinions, and recommendations provided in this report are based solely on the specific activities as required for the performance of ASTM E1527-05 and E1527-13 and are intended exclusively for the purpose stated herein, at the specified Subject Property, as it existed at the time of our site visit.

3.0 SITE DESCRIPTION

3.1 Location and Description

The Subject Property is located at 27-21 44th Drive and 44-18 Purves Street and occupies Tax Block 268, Lots 4, 22, and 23 in Queens, New York. The Subject Property is located in the Long Island City neighborhood of the borough of Queens on the block bordered by Jackson Avenue to the north, Purves Street to the east, Thomson Avenue to the south, and 44th Drive to the west. The approximately 14,145 square-foot Subject Property is developed with a one-story commercial building with garage/warehouse space on Lot 4. Lots 22 and 23 are vacant with no observable improvements. A Site location Map is included as Figure 1. Site reconnaissance photographs are presented in Appendix A.

Based on observations of the surrounding area during the site reconnaissance, the Subject Property is located in an urban area primarily characterized by commercial and manufacturing buildings and vacant land. The sidewalk elevation along Purves Street (east side of Subject Property) is approximately el 8 (Queens Highway Datum). The sidewalk elevation along 44th Drive (west side of Subject Property) is approximately 15 feet higher than the sidewalk elevation along Purves Street.

Based on a previous investigations conducted at the Subject Property groundwater depth ranges from approximately 5 to 10 feet below grade surface (bgs). Based on topography, regional groundwater flow is inferred to be to the west to southwest towards the East River. The New York City Metropolitan Transit Authority (MTA) M and E subway lines extend underneath Jackson Avenue approximately 175 feet north of the Subject Property.

3.2 Description of Site Improvements

Improvements at the Subject Property are summarized in the following table:

SITE IMPROVEMENTS	
Size of the Subject Property	Lot 4: 9,600 square feet; Lot 22: 2,500 square feet; Lot 23: 2,500 square feet
Buildings/Spaces/Structures	Lot 4: 1-story commercial building with warehouse/garage and full basement; Lots 22 and 23: vacant
Surface Water	Surface water is not located on the Subject Property.

SITE IMPROVEMENTS	
Potable Water Source	New York City
Sanitary and Storm Sewer Utilities	New York City
Electrical Utilities	Con Edison
Construction Completion Date	Circa 1931
General Construction Type	Brick and concrete masonry
Cooling and Ventilation System Type	Window air conditioning and ventilation fans.
Heating System Type	Wall-mounted electric heating units
Emergency Power	N/A

3.3 Title Records

Langan researched ownership records for the Subject Property at the Automated City Register Information System (ACRIS) website (http://www.nyc.gov/html/dof/html/jump/acris.shtml). Available deed information is listed in the following table:

Block 268, Lot 4		
Date	**First Party**	**Second Party**
9/14/2011	Electric Realty Company, LLC	44 LIC LLC
9/14/2011	Electric Realty Company, LLC	44 LIC LLC
2/29/2000	Eagle Electric Manufacturing	Electric Realty Company, LLC
10/8/1971	Latouraine Bickfords Foods Inc.	Eagle Electric Mfg Co Inc.
Block 268, Lot 22		
Date	**First Party**	**Second Party**
7/18/2013	4418 Purves LLC	44 LIC LLC
2/3/2010	Parisi Roth LLC	4418 Purves LLC

Block 268, Lot 22 (continued)		
Date	**First Party**	**Second Party**
11/21/2007	Purves Studios LLC	Parisi Roth LLC
7/11/2007	Purves Studios LLC	Parisi Roth LLC
3/9/2007	Purves Studios LLC	Thomson Purves, LLC
7/27/2001	Sara Garden Armstrong	Purves Studios LLC
6/16/2000	Alkeda Corp	Armstrong, Sara Garden
5/2/1998	Weiss, Kurry	Alkeda Corp
Block 268, Lot 22		
Date	**First Party**	**Second Party**
7/18/2013	4418 Purves LLC	44 LIC LLC
2/3/2010	Parisi Roth LLC	4418 Purves LLC
11/14/2007	Parisi, Dino	Parisi Roth LLC
7/11/2007	Parisi, Dino	Parisi Roth LLC
6/6/2006	Lonschein (Referee, Richard	Parisi, Dino
3/13/2001	Coleman, James	Plaza Homes LLC
9/4/1985	Coleman, Alyce M	Coleman, James W
11/29/1976	Welsh Alice Extrix Of	Alyce M Coleman
12/19/1974	Woodwhi Corporation	Alyce M Coleman

The use of the Subject Property (Lot 4) as an electric manufacturing facility between 1971 and 2011 is considered a REC.

4.0 USER PROVIDED INFORMATION

4.1 User Questionnaire and Owner/Operator Questionnaires

As per ASTM E1527-13, a questionnaire was provided to the User in order to obtain specialized User knowledge. Mark Gold, Principal with Silvercup Properties, LLC, completed the User questionnaire. Mr. Gold indicated that he is not aware of environmental leins or activity and use limitations filed against the property. Additionally, Mr. Gold is not aware of specialized knowledge about the property and believes the property reasonably represents the fair market value. Mr. Gold indicated that he is aware of past uses, chemicals present at the property, and spills and provided a previous environmental report that provided additional detail. The completed questionnaire is included in Appendix B and the previous environmental report is included in Appendix C.

An owner/operator questionnaire was provided to the owner's representative during the Phase I site reconnaissance; however, the completed questionnaire was not completed at the time this Phase I report was finalized.

4.2 Previous Environmental Reports

One previous environmental report was available for review. The report is summarized below and included in Appendix C.

October 2013, Phase II Subsurface Investigation Report, prepared by Environmental Business Consultants (ECB)

The subsurface investigation was conducted to investigate environmental conditions identified in an October 2011 Phase I ESA prepared for Lot 4 by EBC and to investigate general environmental conditions on Lots 22 and 23. The report included a brief summary of the 2011 Phase I ESA which identified previous site uses as a photo chemical warehouse, garage with a gasoline tank, paper warehouse, metal plating, welding and repairs, leather goods. These previous site uses are considered a REC because of the potential impact to soil, groundwater and/or soil vapor at the Subject Property.

The Phase II investigation included collection and analysis of soil and groundwater samples. Observations and laboratory results are summarized by media type below.

- Soil – Petroleum staining and odor was identified in the vicinity of the underground tanks on southwestern side of Lot 4. Field screening with a photoionization detector (PID) found readings up to 300 ppm. Additionally, elevated concentrations of petroleum volatile organic compounds (VOCs) were detected within one soil sample collected adjacent to the tanks; however, only n-propylbenzene was reported above New York State Department of Environmental Conservation (NYSDEC) Unrestricted Use Soil Cleanup Objectives (SCOs). Based on these observations and associated analytical data, a spill was called in to NYSDEC and Spill No. 1302045 was assigned. Soil samples collected on lots 22 and 23 identified detections of chlorinated VOCs; however, chlorinated concentrations were below New York State's unrestricted use SCOs. Metals were not analyzed as part of this investigation.
- Groundwater – Chlorinated VOCs were identified in groundwater above New York State groundwater standards. Onsite PCE concentrations ranged from non-detect along the southwestern portion of the site to 950 µg/L at a monitoring well in the northeastern portion of Lot 22. Onsite TCE concentrations ranged from non-detect along the southwestern portion of the site to 150 µg/L in the northeastern portion of Lot 22. Additionally, several petroleum VOCs and SOVCs were identified above New York State groundwater standards in the vicinity of the tanks in Lot 4.

Documented soil and groundwater exceedances of New York State standards are considered a REC.

5.0 ENVIRONMENTAL RECORDS

A regulatory database search was provided by EDR and is included in Appendix C. The EDR report provides a listing of sites identified on select federal and state standard source environmental databases within the approximate search radius specified by ASTM E1527-13. Langan reviewed each environmental database on a record-by-record basis to evaluate whether the sites identified represent a potential for environmental impact to the Subject Property. Langan also reviewed "Orphan Sites" listed within the report. Orphan Sites are those sites that could not be mapped due to inadequate address information. Any Orphan Sites that were identified by Langan within the ASTM search radii, either during the site reconnaissance or by cross-referencing to mapped listings, are addressed in the discussion below.

The following table lists the number of sites identified in standard and additional environmental record databases, within the prescribed search radius and appearing in the EDR Report.

DATABASE RECORD SUMMARY			
Database Reviewed (Date of government version)	**Minimum Search Area**	**Subject Property listed**	**Number of Sites Within Minimum Search Area**
USEPA DATABASES			
National Priorities List (NPL)	1 Mile Radius	No	0
Delisted NPL	1/2 Mile Radius	No	0
Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS) and CERCLIS-NFRAP	1/2 Mile Radius	No	0
Resource Conservation and Recovery Act (RCRA) Corrective Reports (CORRACTS) (7/11/2013)	1 Mile Radius	No	3
RCRA Treatment, Storage, and Disposal Facilities (TSDF)	1/2 Mile Radius	No	0
RCRA Generators (7/11/2013)	Subject Property and Adjoining	No	0
FINDS	Subject Property	No	0
Environmental Response Notification System (ERNS)	Subject Property	No	0

DATABASE RECORD SUMMARY			
Database Reviewed (Date of government version)	**Minimum Search Area**	**Subject Property listed**	**Number of Sites Within Minimum Search Area**
Engineering Controls (EC) Sites Lists	Subject Property	No	0
Institutional Controls (IC) Sites Lists	Subject Property	No	0
NYSDEC DATABASES			
Hazardous Waste Disposal Sites (SHWS) (11/13/2013)	1 Mile Radius	No	14
Hazardous Substance Waste Disposal Site Inventory (HSWDS)	1/2 Mile Radius	No	0
Solid Waste or Landfill Facilities (SWF/LF) (10/8/2013)	1/2 Mile Radius	No	2
Leaking Storage Tanks (LTANKS) (9/25/2013)	1/2 Mile Radius	No	45
SPILLS Information Database (NY SPILLS) (9/25/2013)	1/8 Mile Radius	No	17
EC Sites Lists	Subject Property	No	0
IC Sites Lists	Subject Property	No	0
NY Voluntary Cleanup Program (VCP) (11/13/2013)	1/2 Mile Radius	No	3
Brownfields (11/13/2013)	1/2 Mile Radius	No	2
Solid Waste Disposal Sites Registered Recycling Facility List (SWRCY)	1/2 Mile Radius	No	0
Chemical Bulk Storage (CBS) Underground storage tank (UST) and aboveground storage tanks (AST) Databases	Subject Property and Adjoining	No	0
Major Oil Storage Facilities (MOSF) UST and AST Databases	Subject Property and Adjoining	No	0
Registered and Historical Drycleaners (DRYCLEANERS) (10/17/2013)	1/4 Mile Radius	No	1
Petroleum Bulk Storage Facilities (PBS) UST and AST Databases	Subject Property and Adjoining	Yes	0
EDR (PROPRIETARY) DATABASES			
EDR Former Manufactured Gas Plant (MGP) Sites	1 Mile Radius (N/A)	No	0

N/A Not Applicable; databases with a "Not Applicable" Minimum Search Radius are databases reviewed as part of the Phase I ESA but not required as per ASTM E1527-13.

A description of the reviewed databases is provided in the EDR Report (Appendix D). A summary of sites identified within the prescribed search area is presented below:

5.1 Federal Agency Database Findings

No NPL, Delisted NPL, CERCLIS and CERCLIS-NFRAP, RCRA Generators, RCRA TSDF, EC, IC, FINDS or ERNS sites were listed within their respective minimum search distances as specified by ASTM E1527-13. Information regarding other sites located on the Federal Agency database within the search radius of the Subject Property is provided below.

CORRACTS

CORRACTS is a list of handlers with RCRA Corrective Action Activity. Three CORRACTS sites were identified within the search criteria. Based on distance from the Subject Property (over 3,000 feet), the sites are not considered RECs.

5.2 State Agency Database Findings

No HSDWS, SWRCY, EC, IC, PBS UST and AST, CBS UST and AST, or MOSF listings were identified within their respective minimum search distances as specified by ASTM E1527-13. Information regarding other sites located on State agency databases within the search radius of the Subject Property is provided below.

SHWS

The State Hazardous Waste Sites (SHWS) records are states' equivalent to CERCLIS. The SHWS database in maintained by the NYSDEC. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup will be paid for by potentially responsible parties. Fourteen sites within one mile of the Subject Property were identified on the SHWS list; however, all sites are located more than 1,700 feet from the Subject Property and are not considered RECs.

Solid Waste or Landfill Facilities

The Solid Waste Facilities/Landfill (SWF/LF) database is an inventor of solid waste disposal facilities or landfills in a particular state. The Subject Property was not included in the SWF/LF database. Two SWF/LF facilities were identified within a ½-mile radius; however, they are located more than 1,800 feet from the Subject Property and are not considered RECs.

Leaking Storage Tanks Database

The Leaking Storage Tanks (LTANKS) database contains an inventory of reported leaking storage tank incidents, including leaking USTs and ASTs. The primary causes of the LTANK

incidents include tank test failures, tank failures, and tank overfills. As per ASTM E1527-13, the approximate minimum search distance required for LTANK incidents is within ½ mile of the Subject Property. The Subject Property was not listed in the LTANK/HIST LTANK database; however, 45 LTANK incidents were identified at other properties within a ½-mile radius. Forty-three of the LTANK incidents are closed. One of open incidents is located more than 2,300 feet from the Subject Property and is not considered a REC. The remaining open incident is described below:

Site Name: Court Plaza

Site Address: 5 Court Square

Location: Approximately 650 feet west of the Subject Property

Description: Spill No. 1000528 was reported on April 13, 2010. A 2,000-gallon #2 fuel oil tank failed a tank test after oil was observed on water in subway tunnel directly underneath the site. Based on its close proximity to the Subject Property, this open LTANK incident is considered a REC as the release may have impacted soil vapor or groundwater at the Subject Property.

Spills Database

The Spills database, maintained and updated by NYSDEC, is an inventory of sites where spills have been identified and reported to the NYSDEC. The Subject Property was not listed in the Spills database within the EDR report; however, a search of the online database identified an open spill at the Subject Property.

Site Name: Vacant Business Place

Site Address: 27-21 44th Place

Location: Subject Property

Description: Spill No. 1302045 was reported on May 29, 2013. The spill indicated an unknown amount of gasoline that affected soil and groundwater. The spill has not been closed. Based on the impact to soil and groundwater at the Subject Property, this spill is considered a REC.

Seventeen spills were identified within 1/8 mile of the Subject Property. Sixteen of the Spills incidents are closed. The remaining open incident is described below:

Site Name: Gasgo

Site Address: 27-01 Jackson Avenue

Location: Approximately 400 feet north of the Subject Property

Description: Spill No. 9913082 was reported on February 16, 2000 when contaminated soil was discovered during removal of ten underground storage tanks. Contaminated soil (698 tons) was removed and the spill was closed by NYSDEC. In May 2013, additional information was identified that indicated the potential for off-site migration of petroleum contamination that was unknown at the time of the spill closure. The spill number was reopened and remains open at the time this Phase I ESA was finalized. This incident is considered a REC as the release may have impacted soil vapor or groundwater at the Subject Property.

VCP

Voluntary Cleanup Agreements Program uses private monies to get contaminated sites remediated to levels allowing the sites' productive use. The Subject Property was not listed in the VCP database; however, three VCP sites were identified within the search criteria. Of the three site, two of the sites are located more than 1,600 feet from the Subject Property and are not considered RECs. The remaining VCP site is described below:

Site Name: Outlet City, Queens Blvd & Jackson Ave

Site Address: Queens Blvd & Jackson Ave

Location: Approximately 1,400 feet northeast of the Subject Property

Description: The 2.5- acre site is located on Jackson Avenue between Orchard Street to the east, Queens Boulevard to the west, and the Long Island Railroad yard to the south. The site is contaminated with creosote, petroleum, and solvents. Total VOCs were detected in groundwater up to 30,000 ppb. Creosote in the form of both light non-aqueous phase liquid (LNAPL) and dense non-aqueous phase liquid (DNAPL) are present at the site. Based on the documented soil and groundwater contamination at this site and its proximity to the Subject Property, this site is considered a REC as the release may have impacted soil vapor or groundwater at the Subject Property.

Brownfields

The Brownfields database is a list of contaminated sites enrolled in the New York State Brownfield Cleanup Program. The Subject Property was not listed in the Brownfields database. Two properties were identified in the database; however, one of the sites is located more than 2,400 feet from the Subject Property and is not considered a REC. The remaining Brownfield site is described below:

Site Name: Queens Plaza Residential Development

Site Address: 28-10 Jackson Avenue

Location: Approximately 1,000 feet east of the Subject Property

Description: The 0.5- acre site (a portion of the Outlet City development described in the VCP section above) had a release of approximately 5,000-gallons of creosote with extensive soil and groundwater contamination that includes the presence of LNAPL and residual DNAPL. This site is considered a REC as the release may have impacted soil vapor or groundwater at the Subject Property.

Drycleaners

The NY Dry Cleaners database includes registered dry cleaning facilities in the State of New York. The Subject Property was not included in the NY DRYCLEANERS list; however, one NY Dry Cleaner was identified within 1/4-mile of the Subject Property and is described below:

Site Name: Top Star Fabricare

Site Address: 43-43 Queens Street

Location: Approximately 660 feet east of the Subject Property.

Description: No additional information was provided. Due to the lack of information and the close proximity to the Subject Property, the drycleaner is considered a REC as the potential leaks or spills of petroleum products, solvents and/or other hazardous materials typically found at these facilities may have adversely impacted groundwater and/or soil vapor at the Subject Property.

5.3 Local Regulatory Agency Findings

FOIA Requests

FOIA requests were submitted during the week of December 3, 2013 to the following federal, state, and local agencies via written correspondence:

- New York City Department of Environmental Protection (NYCDEP);
- New York City Department of Health (NYCDOH);
- New York City Fire Department (FDNY);
- New York State Department of Health (NYSDOH);
- NYSDEC; and

- USEPA, Region 2.

Responses have not yet been received. Should future responses alter the conclusions of this Phase I ESA, an addendum will be issued. Copies of the FOIA requests are included in Appendix E.

NYCDOB

Langan conducted a records search through the NYCDOB online query system on December 5, 2013. Copies of the NYCDOB property profile and COs are included in Appendix F. The following is a summary of findings.

Lot 4

Lot 4 has a Department of Finance classification of G2- Garage/Gas Station. A records search identified one building on the lot and the Certificate of Occupancy (CO) documents a one story garage and Buick factory. There are no open Environmental Control Board (ECB) violations related to the Subject Property. The classification of the Subject Property as a Garage/Gas Station is considered a REC.

Lot 22

The Subject Property has a Department of Finance classification of V1-Vacant Land. Certificate of Occupancy (CO) documents issued in 1957 indicates a one story factory and office building with cellar and boiler room. Boiler records indicate one boiler; however, the year of installation is unknown. There are no open Environmental Control Board (ECB) violations related to the Subject Property.

Lot 23

NYCDOB property profile was not found for this block/lot.

Zoning Department

According to the New York City Planning Commission Zoning Map 9b, the Subject Property is located in a M1-5/R9 manufacturing district. According to the zoning map and the list of City Environmental Quality Review Environmental Designations available on the New York City Department of City Planning website, the Subject Property is not listed with a restrictive E-Designation. A copy of the zoning map is provided in Appendix G.

5.4 Physical Setting Sources

5.4.1 Topography

The Subject Property is at an elevation of approximately 14 feet NGVD 1929, based on the USGS 7.5-series, Brooklyn, NY-NJ Topographic Quadrangle map, dated 1995. The sidewalk elevation along Purves Street (east side of Subject Property) is approximately el 8 (Queens Highway Datum). The sidewalk elevation along 44th Drive (west side of Subject Property) is approximately 15 feet higher than the sidewalk elevation along Purves Street.

5.4.2 Geology

Geological surface features (e.g., rock outcroppings) were not observed at the Subject Property. Based on a review of the Bedrock and Engineering Geologic Maps of New York County and Parts of Kings and Queens Counties, New York and Parts of Bergen and Hudson Counties New Jersey, by Charles A. Baskerville (1994), the Site is underlain by bedrock of the Cambrian-Ordovician Hartland formation, which consists of inter-bedded mica schist, gneiss, and amphibolite. According to a geotechnical investigation conducted by Langan in the area, depth to bedrock is approximately 50 to 70 ft bgs. The general subsurface condition of the site consists of about 10 ft of fill, underlain by medium well graded sand with various amounts of silt, cobbles, and boulders, to the top of bedrock.

5.4.3 Hydrology

Groundwater flow is typically topographically influenced, as shallow groundwater tends to originate in areas of topographic highs and flow towards areas of topographic lows, such as rivers, stream valleys, ponds, and wetlands. A broader, interconnected hydrogeological network often governs groundwater flow at depth or in the bedrock aquifer. Groundwater depth and flow direction are also subject to hydrogeologic and anthropogenic variables such as precipitation, evaporation, extent of vegetation cover, utilities, and coverage by impervious surfaces. Other factors influencing groundwater include depth to bedrock, the presence of artificial fill, and variability in local geology and groundwater sources or sinks. Based on a previous investigations conducted at the Subject Property groundwater depth ranges from approximately 5 to 10 feet bgs. Based on topography, regional groundwater flow is inferred to be to the west to southwest towards the East River. MTA subway tunnels border the Subject Property to the north underneath Jackson Avenue. The tunnels may provide a hydraulic barrier to groundwater flow originating north of the Subject Property.

Groundwater in New York City is not used as a potable water source. Potable water provided to the City of New York is derived from surface impoundments in the Croton, Catskill, and Delaware watersheds.

5.5 Historical Use Information

Langan reviewed available historic resources (including aerial photographs, Sanborn and topographic maps, and city directories) dated 1889 to 2011. Findings of the review are presented below.

5.5.1 Aerial Photographs

Langan reviewed aerial photographs of the Subject Property and surrounding areas for the years 1924, 1941, 1954, 1966, 1975, 1984, 1994-1995, 2006, 2008 – 2009, and 2011. The photographs indicate that the Subject Property has been located in a densely developed urban area and improved with a multiple-story building on Lot 22 since at least 1924. The 1941 map indicates the Subject Property is improved with one-story buildings on Lots 4 and 22. The 2008 photograph does not show the Subject Property. The building on Lot 22 is no longer identified in the 2009 photograph. Surrounding properties have been generally occupied by multiple-story buildings. The review of the aerial photographs did not reveal evidence of RECs. Copies of aerial photographs are included in Appendix H.

5.5.2 Sanborn Fire Insurance Maps

Langan reviewed Sanborn Maps for the Subject Property for the years 1889, 1915, 1936, 1947, 1950, 1970, 1977, 1979, 1980, 1985, 1986, 1988, 1989, 1990-1996, 1999, and 2001-2006. Sanborn Maps constitute a database of prior uses of real property for many cities and towns in the United States. Copies of the maps are provided in Appendix I. A summary of the Sanborn Maps is presented on the following table.

SANBORN MAP SUMMARY	
YEAR	**COMMENTS**
1889	**Subject Property:** The Subject Property is located on the block identified as 194 and contains six lots; one contains a two-story residential building with basement. **Surrounding Area:** Surrounding properties are primarily multiple-story residential and commercial buildings, including material junk yards and the County Court House. The following REC was identified: • A garage is located at 15 Purves Street, approximately 50 feet east of the Subject Property.

SANBORN MAP SUMMARY	
YEAR	**COMMENTS**
1915	**Subject Property:** The Subject Property contains a total of three lots; one contains a two-story residential building with basement. **Surrounding Area:** Surrounding properties are primarily multiple-story residential office, and commercial buildings including the County Court House, the Manhattan Steam Bakery, and American Express Co.. The following REC was identified: • A N.Y. Substation is located at the adjoining property to the east of the Subject Property.
1936	**Subject Property:** The Subject Property is on the block identified as Block 268 and is depicted as a garage with a gasoline tank (Lot 4) and a controller manufacturing facility (Lot 22). The two-story residential building is no longer shown on Lot 23. **Surrounding Area:** Surrounding properties are primarily multiple-story residential office, and commercial buildings. The following RECs were identified: • A N.Y. Substation is located at the adjoining property to the east of the Subject Property; • A filling station with four gasoline tanks is located at the adjoining property to the west of the Subject Property; • An iron works is located at 44-12 Purves Street, approximately 40 feet north of the Subject Property; • A garage with a gasoline tank is located at 44-33 Purves Street, approximately 100 feet east of the Subject Property; • A garage with a gasoline tank is located at 26-36 Jackson Avenue, approximately150 feet northeast of the Subject Property; • A gasoline tank is located at 44-25 Purves Street; approximately 75 feet east of the Subject Property; • A manufacturer of bottles is located at 28-31 Thomson Avenue, approximately 150 feet south of the Subject Property; • A laundry facility is located at 27-01 Jackson Avenue, approximately 225 feet northeast of the Subject Property; • A printing facility is located at 27-12 Thomson Avenue, approximately 150 feet southwest of the Subject Property.

SANBORN MAP SUMMARY	
YEAR	**COMMENTS**
1947	**Subject Property:** The Subject Property is depicted as paper warehouse (Lot 4) and a controller manufacturing facility (Lot 22), a building identified as "stage" is located on Lot 23. Lot 4 is also identified as a photo chemical warehouse. **Surrounding Area:** Surrounding properties are primarily multiple-story residential office, and commercial buildings. The following RECs were identified: • An iron works is located at the adjoining property to the east of the Subject Property; • A filling station with four gasoline tanks is located at the adjoining property to the west of the Subject Property; • A chemical lab is located at the adjoining property south of the Subject Property; • A contractors yard with two gasoline tanks is located at the adjoining property to the south of the Subject Property; • A contractors yard with a gasoline tank is located at 44-17 Purves Street, approximately 50 feet east of the Subject Property; • A manufacturer of welding equipment is located at 26-26 Jackson Avenue, approximately 100 feet northeast of the Subject Property; • A manufacturer of printing inks is located at 44-23 Purves Street, approximately 50 feet east of the Subject Property; • A garage and disinfectant warehouse is located at 43-30 Dutch Kills, approximately 150 feet east of the Subject Property;
1950	**Subject Property:** The Subject Property is unchanged. **Surrounding Area:** Surrounding properties are generally unchanged.
1970	**Subject Property:** The Subject Property contains a building depicted as commercial/manufacturing (Lot 4), a multi-story welding facility (Lot 22) and a vacant lot (Lot 23). Lot 23 is now depicted as a portion of a larger lot. **Surrounding Area:** The surrounding area remains primarily unchanged, the northern adjoining properties are now depicted as a junk yard and parking, the southern adjoining property is now a paper facility and no longer contains gasoline tanks. The following REC was identified: • A filling station is located at 27-01 Jackson Avenue, approximately 320 feet northeast of the Subject Property;
1977,1979	**Subject Property:** The Subject Property is unchanged with the exception of Lot 4 is now depicted as an auto body shop. **Surrounding Area:** The surrounding area remains primarily unchanged with the exception of the chemical lab located at the adjoining property to the south is now an auto repair shop.

SANBORN MAP SUMMARY	
YEAR	**COMMENTS**
1980, 1985, 1986	**Subject Property:** The Subject Property is unchanged. **Surrounding Area:** The surrounding area remains primarily unchanged with the exception of the filling station with four gasoline tanks located at the adjoining property to the west is now depicted as an auto repair and parking facility and no longer contains the tanks.
1988-1996	**Subject Property:** The Subject Property is unchanged. **Surrounding Area:** The surrounding area remains primarily unchanged with the exception of Eagle Electric Manufacturing Company located at 27-12 Thomson Avenue, approximately 150 feet southwest of the Subject Property. The junk yard located on the adjoining property to the north is no longer labeled.
1999	**Subject Property:** The Subject Property is unchanged. **Surrounding Area:** The surrounding area remains primarily unchanged with the exception of the adjoining property to the north is now depicted as a warehouse and an oil burner utility company is located at 44-39 Purves Street, approximately 140 feet southeast of the Subject Property.
2001-2006	**Subject Property:** The Subject Property is unchanged with the exception of Lot 23 is now labeled as storage. **Surrounding Area:** The surrounding area remains primarily unchanged with the exception of the gasoline tank located at 44-17 Purves Street is no longer shown.

Langan's Sanborn Map review revealed that the Subject Property was developed with a two-story residential building with a basement as early as 1889. In 1936, the Subject Property included a garage with gasoline tank (Lot 4) and a manufacturer of controllers (Lot 22). Between 1947 and 1950 Lot 4 was a paper warehouse and photo chemical warehouse. Lot 22 has been a welding and repair facility since 1970. Lot 4 has been an auto body shop since 1977. Lot 23 has been a storage facility since 2001. The use of the Subject Property as a garage, manufacturer, photochemical warehouse, and auto body shop are considered RECs. Potential spills or leaks of petroleum products, solvents, or other hazardous substances at the above facilities may have adversely impacted groundwater and/or soil at the Subject Property. Surrounding properties have been primarily occupied by manufacturing, commercial, residential and office buildings.

The following RECs were identified on surrounding properties:

- Gasoline storage was located at the following properties:
    - 27-17 Thomson Avenue from 1936 to 1979;
    - 44-33 Purves Street, approximately 100 feet east of the Subject Property since 1936;
    - 44-25 Purves Street, approximately 75 feet east of the Subject Property in 1936;

  - 26-36 Jackson Avenue, approximately 150 feet northeast of the Subject Property in 1936;
  - 28-11 Thomson Avenue (adjoining property to the south) from 1947 to 1950;
  - 44-17 Purves Street, approximately 50 feet east of the Subject Property in 1947 to 1999;
  - 27-01 Jackson Avenue, approximately 320 feet northeast of the Subject Property since 1970.
- A N.Y. Substation was located at 44-13 Purves Street (adjoining property to the east) between 1915 and 1936;
- A printing facility was located at 27-12 Thomson Avenue, approximately 150 feet southwest of the Subject Property in 1936;
- Iron works were located at the following properties:
  - 44-12 Purves Street, approximately 40 feet north of the Subject Property in 1936;
  - 44-19 Purves Street (adjoining property to the east) between 1947 and 1950
- A laundry facility was located at 27-01 Jackson Avenue, approximately 225 feet northeast of the Subject Property in 1936;
- A chemical lab was located at 27-33 44th Drive (adjoining property to the south) from 1947 to 1970;
- An oil burning utility company was located at 44-39 Purves Street, approximately 150 feet southeast since 1999;
- Manufacturing facilities were located at the following properties:
  - 28-31 Jackson Avenue, approximately 150 feet south of the Subject Property in 1936;
  - 26-26 Jackson Avenue, approximately 100 feet northeast of the Subject Property;
  - 44-23 Purves Street, approximately 50 feet east of the Subject Property, from 1947 to 1999;
- Garages/Auto Repair facilities were located at the following properties:
  - 15 Purves Street, approximately 50 feet east the Subject Property in 1989
  - 43-30 Dutch Kills, approximately 150 feet east of the Subject Property in 1947;
  - 27-33 44th Drive (adjoining property to the south) from 1977;
  - 27-17 Thomson Avenue (adjoining property to the west) from 1980.

5.5.3 Historical USGS Topographic Quadrangles

Langan reviewed historical USGS Topographic Quadrangles obtained from EDR for information regarding past uses of the Subject Property. Quadrangle maps were available for the Subject

Property for the years 1897, 1900, 1924, 1947, 1956, 1966, 1967, 1979, and 1995. Based on a review of the historic topographic maps, the Subject Property was developed within a densely developed urban area as early as 1897. The Dutch Kills Creek is located approximately 1,300 feet southeast of the Subject Property and the East River is located approximately 4,250 feet west of the Subject Property. The Long Island Railroad tracks are located approximately 300 feet southeast of the Subject Property. The review of historic topographic maps did not reveal evidence of RECs. Copies of the topographic maps are provided in Appendix J.

5.5.4 City Directories

The City Directory Abstract, obtained from EDR, is a review of available business directories, including city, cross-reference, and telephone directories, at approximately five-year intervals for the years spanning 1922 through 2013. A copy of the City Directory Abstract is provided in Appendix K. The Subject Property was listed in the directory for several commercial businesses including an auto repair, garage, professional boxing and car rental facilities between 1934 and 2013.

Surrounding property listings included various commercial and manufacturing businesses. An unidentified factory was listed at 44-19 Purves Street (adjoining property to the east) in 1945. A cleaning facility was listed at 44-24 Purves Street (adjoining property to the south) in 1934. . Based on the proximity of the facility to the Subject Property, the historical use as a cleaning facility constitutes a REC.

5.5.5 Environmental Lien Search

Langan contracted EDR to conduct an Environmental Lien search for the Subject Property. The results of the search, which included a compilation of available data and verification of the findings with the appropriate regulatory authorities, revealed that there are no Environmental Liens or other Activity and Use Limitations (AUL) associated with the Subject Property. A copy of the Environmental Lien Search is provided in Appendix L.

6.0 SITE RECONNAISSANCE

6.1 Methodology and Limiting Conditions

The Site reconnaissance was conducted in a systematic manner focusing on the spatial extent of the Subject Property and then progressing to the adjoining and surrounding properties. The assessment of the adjoining and surrounding properties was limited to identifying, if possible, any indications of past or current use that may involve the use, storage, disposal, or generation of hazardous substances or petroleum products; noting the general type of current use; the general topography of the surrounding area; and providing a general description of adjoining or adjacent structures.

6.1.1 Date and Time of Inspection

The Site reconnaissance was performed at 7:30 am on December 10, 2013 by Jessica Alzamora of Langan. The weather at the time of the initial inspection is described as snowing and approximately 30°F. Ms. Alzamora was accompanied during the Site reconnaissance by Adam Jolly, a representative of the site owner.

6.2 General Site Setting and Reconnaissance Observations

The approximately 14,145 square-foot Subject Property is developed with a one-story commercial building with garage/warehouse space on Lot 4. Lots 22 and 23 are vacant with no observable improvements. The sidewalk elevation along 44th Drive (western entrance of the building) was observed to be approximately 15 feet higher than the sidewalk elevation along Purves Street (eastern site boundary).

The building was vacant at the time of the inspection and in poor condition. Several areas of the building were observed to have deteriorated flooring, walls, and ceilings, including a loft located on the north side of the building, which was inaccessible due to deteriorated flooring. The roof was also inaccessible at the time of the inspection.

The basement was approximately 15 feet tall and had painted brick walls, fluorescent lighting and concrete floors. Wall-mounted, electric heating units, window fans and air-conditioning units were observed in the building. Portions of the concrete flooring appeared to be in poor condition. Approximately ten one-gallon paint containers, one five-gallon container of cement, and five one-quart containers of enamel and cleaners were observed at the time of the inspection. Staining was observed on the concrete flooring in the vicinity of the containers, however the concrete appeared to be in good condition at these location. Floor drains were not

observed. A water heater and a broken water pipe were leaking along the southern wall of the basement. An out-of-service coal boiler was identified in the basement near the northern wall.

The first floor of the building contains a lobby area and office. Finishing materials include 12-inch by 12-inch floor tiles and carpet, painted brick walls with wood panels, and drop ceilings with fluorescent lighting. There was debris throughout the office building.

The loft and roof were not accessible at the time of the inspection. The loft flooring was in poor condition with visible deterioration. A review of aerial photographs of the building indicates the roof is coated with a tar compound and contains two units located on the north side of the building and a skylight.

Pits, Ponds, Lagoons

Langan did not observe pits, ponds, or lagoons on the Subject Property.

Pools of Liquid

Liquid was observed in the basement of the building due to a broken water pipe. The water is seen to drain to a nearby room that was full of debris and the flooring was not visible.

Storm Drains, Wells, and Cisterns

Storm drains, wells, and cisterns were not observed at the Subject Property.

Polychlorinated Biphenyl (PCB) Transformers and Suspect Equipment

Fluorescent lighting ballasts observed throughout the Subject Property may contain PCBs. Other suspect PCB-containing equipment was not observed.

Storage Containers, Drums, and Chemical Storage Areas

Approximately ten one-gallon paint containers, one five-gallon container of cement, and five one-quart containers of enamel and cleaners were observed in the basement. Staining was observed on the concrete flooring in the vicinity of the containers, however the concrete appeared to be in good condition.

Air Emissions or Wastewater Discharges

Air emissions or wastewater discharges were not observed on the Subject Property.

Sumps

A sump was observed in the basement of the building. No staining was observed in the location of the sump.

USTs or ASTs

USTs or ASTs were not observed at the Subject Property, however, a patch of concrete and evidence of previous environmental borings were observed in the area where a potential UST is presumed to be located near the western wall of the basement.

Monitoring Wells or Remedial Activities

Several monitoring wells were observed at the Subject Property, five of wells were installed by Langan as part of the concurrent environmental investigation, and two from previous investigation work at the Subject Property.

Stained or Discolored Soil

Stained or discolored soil was not observed at the Subject Property.

Leachate or Seeps

Leachate or seeps were not observed at the Subject Property.

Adjoining and Surrounding Property Uses

The Subject Property is adjoined by Purves Street followed by a two-story commercial building identified as "Sculpture Center" to the east; vacant lots to the south; 44th Drive followed by a one-story garage identified as "Global Auto Electric d/b/a Manny Auto Electric" to the west; and a two-story commercial building identified as "JME Enterprises, Inc." and "L.I.C Auto Repair" and a one-story commercial building identified as "Queens Plaza Automotive Warehouse" to the north. An active filling station was identified at the northeast corner of the intersection of 43rd Avenue and Jackson Avenue, approximately 275 feet northeast of the Subject Property. The surrounding area is primarily comprised of multiple-story retail, commercial, manufacturing, and vacant land.

Site Reconnaissance Conclusions

The following REC was identified on the Subject Property:

- UST – A suspect gasoline UST is located near the west wall in the basement of the building. Leaks or spill of petroleum products associated with the UST has the potential to adversely impact groundwater and/or soil vapor at the Subject Property.

The following RECs were identified on surrounding properties:

- Auto repair facilities identified as "JME Enterprises, Inc." /"L.I.C Auto Repair" and "Queens Plaza Automotive Warehouse" adjoin the property to the north;
- A filling station was observed at 27-19 43rd Avenue, approximately 275 feet of the Subject Property.

Based on the close proximity to the Subject Property, these facilities have the potential to adversely impact groundwater and/or soil vapor at the Subject Property and are considered RECs.

The following are considered additional (non-ASTM) environmental concerns:

- Based on the ages of the building, ACM, LBP, and PCB may be present in building materials;
- Water infiltration observed in the building creates the potential for mold growth

The following are considered de minimis conditions:

- Staining was observed on the concrete floor in the first floor office and garage/warehouse and near the east entrance in the basement; however, the concrete in these locations appeared to be in good condition. The staining is therefore considered a de minimis condition.

7.0 INTERVIEWS

7.1 Site Owner/ User

A owner questionnaire was provided to Adam Joly, a representative of the site owner, during the site reconnaissance on December 10, 2013. The questionnaire was not completed by the time this report was finalized.

A User questionnaire was provided to Mark Gold, Principle of Silvercup Properties, LLC. The completed questionnaire was received on December 31, 2013 and is discussed in further detail in Section 4.1. The completed questionnaire is included in Appendix B.

7.2 Site Occupants

The Subject Property is currently vacant.

7.3 Owners/Tenants of Adjacent Properties

Owners/tenants of adjacent properties were not interviewed as part of this Phase I ESA.

8.0 ADDITIONAL SERVICES

8.1 Radon

Radon is a colorless, odorless radioactive gas that results from the natural breakdown of uranium minerals in soil, rock, and water, which subsequently enters the atmosphere. It can concentrate in buildings, entering through cracks and other penetrations of a building foundation. Some areas are more likely to have elevated concentrations of radon than others, reflecting subsurface lithologic conditions.

According to the USEPA radon map, Queens is considered a Zone 3 area, which indicates the predicted average indoor radon levels are less than 2 picoCuries per liter (pCi/L). The NYSDOH maintains a database of radon test results on a local and county level. According to the NYSDOH, a total of 413 radon tests have been conducted in New York County with results indicating that 0.3 % of living areas and 3% of basements have radon concentrations above 4 pCi/L, the USEPA action level. According to the NY Radon database as reported in the EDR Radius Map Report, a total of 81 radon tests have been conducted in Queens County with an average radon level of 0.6205 pCi/L for living area and 0.970 pCi/L for basement. Based on this data, it is unlikely that elevated levels of radon gas are present at the Subject Property.

8.2 Asbestos-Containing Material, Lead-Based Paint, and PCBs

A formal survey to identify ACM, LBP and/or PCB-containing material was not conducted as part of this Phase I ESA. The building was constructed in the 1930s, potentially with building materials that contain ACM, LBP, or PCBs. In addition, the building contained fluorescent light ballasts, which can contain PCBs. These materials should be identified and handled appropriately prior to any demolition or renovation activities at the Subject Property.

9.0 DEVIATIONS AND DATA GAPS

9.1 Deviations

Langan has performed a Phase I ESA of the Subject Property utilizing a standard of good commercial and customary practice that is consistent with the ASTM E 1527-05 and E1527-13. Significant deviations were not made to the above referenced standards.

9.2 Data Gaps

In order to address data gaps, additional sources of information may be consulted. According to ASTM E 1527-13, Section 8.3.2.3, "historical research is complete when either: (1) the objectives in 8.3.1 through 8.3.2.2 are achieved; or (2) data failure is encountered. Data failure occurs when all standard historical sources that are reasonably ascertainable and likely to be useful have been reviewed and yet the objectives have not been met. If data failure is encountered, the report shall document the failure and, if any of the standard historical sources were excluded, give the reasons for the exclusion."

This Phase I ESA was completed without data gaps, with the exception that responses to all FOIA requests have not been and interviews with the site owner and adjacent property owners were not conducted. Sufficient information has been provided from other data sources to render conclusions regarding the presence of RECs at the Subject Property. As such, this data gap is not expected to impact the overall conclusions of the Phase I. Should additional information provided in the FOIA responses alter the conclusions of this Phase I ESA, we will issue an addendum to this report.

10.0 FINDINGS, OPINIONS, AND CONCLUSIONS

This Phase I ESA was conducted in accordance with the ASTM Practice E1527-13 (Standard Practice for ESA: Phase I ESA Process) and the USEPA AAI Rule. The objective of this Phase I ESA was to identify the presence or likely presence, use, or release on the Subject Property of hazardous substances or petroleum products as defined in ASTM E1527-13 as a REC.

The Phase I ESA identified the following RECs, de minimis conditions, and other environmental concerns associated with the Subject Property:

REC 1 – Historic Site Use

Historic use of Lot 4 includes a garage with a gasoline tank in 1936; a paper warehouse and photo chemical warehouse in 1947; and an auto body shop from 1977 to at least 2006. Lots 22 and 23 were part of an operation identified as "Controller Manufacturing" between 1936 and 1950. From 1970 through 2006, Lot 22 is shown as welding and repairs with city directory listings that include Rozilda labs, leather goods, plating equipment, manufacturing and Artisan Designs. The historic uses involve the storage, application, and disposal of hazardous substances. Leaks, spills, or discharges of solvents, petroleum products, polychlorinated biphenyls (PCB), metals and/or other hazardous substances used at the historic facilities may have adversely impacted soil, groundwater, and/or soil vapor.

REC 2 – Documented Site Contamination

Soil and groundwater contaminant concentrations were identified above New York State standards. Elevated soil and groundwater concentrations of petroleum volatile organic compounds (VOC) were detected adjacent to the suspected tank. Additionally, chlorinated VOCs were identified in groundwater. Onsite PCE groundwater concentrations ranged from non-detect along the southwestern portion of the site to 950 µg/L at a monitoring well in the northeastern portion of Lot 22. Onsite TCE concentrations ranged from non-detect along the southwestern portion of the site to 150 µg/L in the northeastern portion of Lot 22.

REC 3 – NYSDEC Spill and Potential On-Site Underground Storage Tank

A gasoline underground storage tank (UST) is potentially located in the Lot 4 building basement. The tank was identified on a 1936 Sanborn map and previous reports indicate the presence of a vent pipe that was traced to a concrete patch in the basement floor. Remnants of a concrete dispenser island were visible immediately behind the garage door. Site constraints prevented a geophysical survey to document the presence of the tank. Petroleum staining, odor and

elevated field instrument readings were identified in the vicinity of the potential UST. Elevated concentrations of petroleum volatile organic compounds (VOCs) were detected within the impacted soil. Based on these observations and associated analytical data, a spill was called in to the New York State Department of Environmental Conservation (NYSDEC) and Spill No. 1302045 was assigned.

REC 4 – Surrounding Property Use

Current and historic uses of the adjoining and/or surrounding properties include gasoline filling stations, manufacturing facilities, auto repair stations/garages with gasoline tanks, iron works, drycleaners, a chemical laboratory, an oil-burning utility company, and printing facilities. Additionally, two open spills (Spill Numbers 1000528 and 9913082) were identified on properties less than 700 feet from the Subject Properties. Voluntary Cleanup Program and Brownfield Cleanup Program sites with documented soil and groundwater contamination were identified on surrounding properties. Monitoring wells were identified on surrounding properties, which may indicate past or current environmental monitoring. Leaks, spills, or discharges of solvents, petroleum products, and/or other hazardous substances associated with surrounding property use may have adversely impacted groundwater and/or soil vapor beneath the Subject Property.

De Minimis Condition

Staining was observed on the Lot 4 building office and basement floor and the garage/warehouse walls and floor. The concrete floor slab beneath each area of staining appeared to be competent and significant subsurface impact is unlikely.

Non-ASTM Environmental Concerns

The building was constructed in the 1930s, potentially with materials that contain asbestos, lead-based paint, or polychlorinated biphenyls (PCBs). In addition, the building contained fluorescent light ballasts, which may contain PCBs.

No Historic RECs (HRECs) or Controlled RECs (CRECs) were identified.

11.0 REFERENCES

The following references were reviewed as part of this Phase I ESA:

(1) Environmental Data Resources, Inc. December 2, 2013. Aerial Photo Decade Package.

(2) Environmental Data Resources, Inc. December 2, 2013. City Directory Abstract.

(3) Environmental Data Resources, Inc. December 9, 2013. Environmental Lien Search.

(4) Environmental Data Resources, Inc. December 2, 2013. Historical Topographic Map Report.

(5) Environmental Data Resources, Inc. December 2, 2013. Radius Map with GeoCheck.

(6) Environmental Data Resources, Inc. December 2, 2013. Sanborn Map Report.

(7) Environmental Protection Agency, USEPA Map of Radon Zones

(8) New York City Department of Buildings, Building Information System, http://www.nyc.gov/html/dob/html/bis/bis.shtml, retrieved December 5, 2013.

(9) New York City Planning Commission. Zoning Map 9b.

(10) City Online Register, http://www.nyc.gov/html/dof/html/jump/acris.shtml, retrieved December 5, 2013.

(11) NYCityMap, http://gis.nyc.gov/doitt/nycitymap/

12.0 STATEMENT OF QUALIFICATIONS AND SIGNATURES


Langan declares that, to the best of its professional knowledge and belief, the personnel who performed this Phase I ESA meet the definition of Environmental Professional as defined in Subsection 312 10 of 40 CFR 312 and that they have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the Subject Properties. They have developed and performed the AAIs in conformance with the standards and practices set forth in 40 CFR Part 312. Resumes outlining the qualifications of the Environmental Professionals who performed this Phase I ESA are provided in Appendix L.

Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.



Jason Hayes, P.E., LEED AP
Associate

FIGURES



WARNING: IT IS A VIOLATION OF THE NYS EDUCATION LAW ARTICLE 145 FOR ANY PERSON, UNLESS HE IS ACTING UNDER THE DIRECTION OF A LICENSED PROFESSIONAL ENGINEER, TO ALTER THIS ITEM IN ANY WAY.

NOTE: BASE MAP FROM USGS "BROOKLYN QUADRANGLE" 7.5-MINUTE SERIES QUADRANGLE MAP, DATED JULY 2007.

LANGAN

21 Penn Plaza, 360 West 31st Street, 8th Floor
New York, NY 10001
T: 212.479.5400 F: 212.479.5444 www.langan.com

Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.
Langan Engineering and Environmental Services, Inc.
Langan CT, Inc.
Langan International LLC
Collectively known as Langan

Project	27-21 44TH DRIVE, 44-18 PURVES STREET BLOCK No. 268, LOT Nos. 4, 22, 23 QUEENS NEW YORK
Drawing Title	SITE LOCATION PLAN
Project No.	170281401
Date	12/13/2013
Scale	N.T.S.
Drawn By	JPA
Submission Date	–
Drawing No.	1
Sheet	1 of 2

© 2013 Langan

Filename: \\langan.com\data\NY\data4\170281401\Cadd Data - 170281401\SheetFiles\Environmental\Phase I\Figure 1 - Site Location Plan.dwg Date: 12/13/2013 Time: 12:06 User: jalzamora Style Table: Langan.stb Layout: ANSIA-BP

APPENDIX A- SITE RECONNAISSANCE PHOTOGRAPHS

Appendix A - Site Reconnaissance Photographs
Phase I Environmental Site Assessment
27-21 44th Drive and 44-18 Purves Street
Queens, New York
Langan Project No. 170281401



Photo 1: View of Site facing east, from 44th Drive



Photo 2: View of Site facing west, from Purves Street.



Photo 3: View of vacant garage/warehouse located in the southern portion of the building on the Subject Property, facing northeast.



Photo 4: View of window ventilation and florescent light fixtures, typical.



Photo 5: View of heating units and damaged ceilings, typical.



Photo 6: View of metal plate in flooring of garage/warehouse section of the building.




Photo 7: View of water heater in garage/warehouse building.



Photo 8: View of stained walls and flooring in the garage/warehouse section of the building.



Photo 9: View of sink and stained flooring in the office building



Photo 10: View of leaking water pipe and pooled water in basement of building along western wall.



Photo 11: View of sump in basement of building.



Photo 12: View of basement.



Photo 13: View of chemicals identified in the basement near the eastern entrance of the building.



Photo 14: View of patched concrete in location of historical UST in basement.



Photo 15: View of out-of-service coal boiler near northern portion of basement.



Photo 16: View of possible former UST fill port location on sidewalk of 44th Drive.



Photo 17: View of eastern adjoining properties, facing east.



Photo 18: View of southern adjoining properties, facing southeast from 44th Drive.



Photo 19: View of western adjoining property, facing west on 44th Drive.



Photo 20: View of northern adjoining property, facing northeast from 44th Drive.



Photo 21: View of northern adjoining property, facing north from Purves Street.

APPENDIX B- USER QUESTIONNAIRE

LANGAN

ASTM PRACTICE E 1527-13: USER/CLIENT QUESTIONNAIRE

Please complete the below form and return to
Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.

In order to qualify for one of the Landowner Liability Protections (LLPs) offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2001 (the "Brownfields Amendments"), 188 the user must conduct the following inquiries required by 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31. These inquiries must also be conducted by the EPA Brownfield Assessment and Characterization grantees. The user should provide the following information to the environmental professional. Failure to conduct these inquiries could result in a determination that "all appropriate inquires" is not complete.

General Information

User/Client Name (s): SILVERCUP PROPERTIES LLC

Property Name: 44TH-PURVES LIC

Address: 27-21 44TH DRIVE, LONG ISLAND CITY, NY, 11101

QUEENS BLOCK 268, LOTS 4, 22, 23

Property Type: VACANT BUILDING AND VACANT LAND

Type of Property Transaction:

- Purchase of property ☒
- Financing of property ☐
- Sale of property ☐
- Ground Lease ☐
- Build to Suit Lease ☐
- Other_____

Reason Why Phase I ESA is required: ENVIRONMENTAL DUE DILIGENCE

Site Contact (s): MARK GOLD

Required Information

The citation at the end of each item (e.g. 40 CFR 312.XX) is the section of EPA's November 1, 2005 AAI Final Rule which discusses that item.

(1.) Environmental liens that are filed or recorded against the property (40 CFR 312.25).

Yes	No
☐	☒

Did a search of recorded land title records (or judicial records, where appropriate, see Note 1 below) identify any environmental liens filed or recorded against the property under federal, tribal, state or local law?

Note 1 – In certain jurisdictions, federal, tribal, state or local statutes or regulations specify that environmental liens and AULs be filed in judicial records rather than in land title records. In such cases judicial records must be searched for environmental liens and AULs.

LANGAN

	Yes	No
(2.) Activity and use limitations that are in place on the property or that have been filed or recorded against the property (40 CFR 312.26(a)(1)(v) and (vi)). Did a search of recorded land title records (or judicial records where appropriate, see Note 1 above) identify any AULs, such as engineering controls, land use restrictions or institutional controls that are in place at the property and/or have been filed or recorded against the property under federal, tribal, state or local law?	☐	☒
(3.) Specialized knowledge or experience of the person seeking to qualify for the LLP (40 CFR 312.28). Do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?	☐	☒
(4.) Relationship of the purchase price to the fair market value of the property if it were not contaminated (40 CFR 312.29).	**Yes**	**No**
(a.) Does the purchase price being paid for this property reasonably reflect the fair market value of the property? [If no, proceed to Part 5.]	☒	☐
(b.) If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property?	☐	☐

	Yes	No	report attached
(5.) Commonly known or reasonably known or reasonably ascertainable information about the property (40 CFR 312.30). Are you aware of commonly known or reasonably ascertainable information about the property that would help the environmental professional to identify conditions indicative of releases or threatened releases? For example, as user,	☒	☐	
(a.) Do you know the past uses of the property?	☒	☐	
(b.) Do you know of specific chemicals that are present or once were present at the property?	☒	☐	
(c.) Do you know of spills or other chemical releases that have taken place at the property?	☒	☐	
(d.) Do you know of any environmental cleanups that have taken place at the property?	☐	☒	

	Yes	No	
(6.) The degree of obviousness of the presence or likely presence of contamination at the property, and the ability to detect the contamination by appropriate investigation (40 CFR 312.31). Based on your knowledge and experience related to the property are there any obvious indicators that point to the presence or likely presence of releases at the property?	☒	☐	report attached

SIGNATURE:

It is understood that the information presented in this form is an integral part of the Phase I ESA process and that Langan will evaluate and rely on this information in the development of the final Phase I ESA report.

Completed By: Mark Gold

Print/Type Name: MARK GOLD

Title: PRINCIPAL

Company: SILVERCUP PROPERTIES

Date: 12/31/2013

APPENDIX C- PREVIOUS ENVIRONMENTAL REPORT

27 - 21 44th Drive, Long Island City, Queens

Supplemental Due Diligence Materials



Brookfield Financial

Table of Contents

UST Clean-up Estimate

Phase II Subsurface Investigation Report

Disclaimer: *This information is considered Confidential Information as defined by the confidentiality agreement. Ownership and Broker are providing this data for informational purposes only and do not make any representations on the accuracy or completeness of these reports. You should not rely on these reports and you should consult with your own professionals on matters such as zoning, environmental, brownfields, phase I and phase II.*

UST Clean-up Estimate

Cost Estimate - Tank Removal and Remediation Conducted by Environmental Contractor Prior to Construction of New Building

	Rate	Units	Quantity	Cost
Permits	$2,500	Lump Sum	1	$2,500
Tank Removal (550 gal gas tank)*	$5,000	Lump Sum	1	$5,000
Waste Characterization Soil Sample	$1,200	per sample	1	$1,200
End Point Soil Samples	$250	per sample	5	$1,250
Contaminated Soil Excavation and Loading	$3,000	per day	1	$3,000
Soil Transportation and Disposal**	$45	per ton	140	$6,300
Pump Truck	$850	per day	1	$850
Gasoline Disposal	$1.50	per gal	550	$825
Contaminated Water Disposal	$0.72	per gal	4,000	$2,880
Ground Water Sample	$250	per sample	1	$250
Chemical Oxidants	$2.75	per lb	500	$1,375
Consultant Oversite	$800	per day	3	$2,400
Reporting (Tank Removal Report)	$1,200	per report	1	$1,200
Reporting (Tank Reg/Dereg with PBS)	$1,000	1 time filing	1	$500

TOTAL* **$29,530**

* Assumes the gas tank is not encased in concrete, if in concrete add $ 3,000
** Assumes area of 20ft by 20ft and 7ft deep = 103yd3 or ~140 tons
*** Assumes no backfill required for excavation

Phase II Subsurface Investigation Report

PHASE II

SUBSURFACE INVESTIGATION REPORT

OCTOBER 2013

EBC Project No: VHL1102

27-21 44th Drive, 44-18 Purves Street
Long Island City, NY 11101

Block 268, Lots 4, 22, & 23



Prepared for:

44 LIC, LLC
184 N. 8th Street
Brooklyn, NY 11211

EBC

ENVIRONMENTAL BUSINESS CONSULTANTS

1808 Middle Country Road. Ridge, NY 11961 Ph: 631.504.6000 Fax: 631.924.2870

TABLE OF CONTENTS
27-21 44th Drive, 44-18 Purves Street
Long Island City, Queens, NY 11101

1.0 INTRODUCTION 1
1.1 Site Location and Description 1
1.2 Site Background 1
1.2.1 Phase I Environmental Site Assessment, October 2011 1

2.0 SUBSURFACE INVESTIGATION 3
2.1 Soil Sampling 3
2.1.1 Soil Results 3
2.2 Groundwater Sampling 4
2.2.1 Groundwater Sample Results 4

3.0 CONCLUSIONS 5

4.0 REFERENCES 6

4.0 REFERENCES 6

TABLES

Table 1 Soil Analytical Results, Volatile Organic Compounds
Table 2 Soil Analytical Results, Semi-Volatile Organic Compounds
Table 3 Groundwater Analytical Results, Volatile Organic Compounds
Table 4 Groundwater Analytical Results, Semi-Volatile Organic Compounds

FIGURES

Figure 1 Site Location Map
Figure 2 Site Plan

APPENDICES

Appendix A Soil Boring Logs
Appendix B Laboratory Reports

1.0 INTRODUCTION

Environmental Business Consultants (EBC) has prepared the following Phase II Subsurface Investigation Report for properties located at 27-21 44th Drive and 44-18 Purves Street (Block 268, Lots 4, 22, 23), in Long Island City, Queens, New York 11101 ("the Site"). The subsurface investigation was conducted to investigate recognized environmental conditions identified in a Phase I Environmental Site Assessment report prepared for Lot 4 by EBC in October 2011 as well as the general environmental condition of Lots 22 and 23. The work was conducted on behalf of 44 LIC LLC to identify and characterize potential contaminants within the surface/subsurface soils and groundwater at the Site to support future redevelopment.

1.1 Site Location and Description

The Site is located in the City of New York and Borough of Brooklyn (Kings County) and is identified as Block 268, Lots 4, 22 and 23. The Site includes three adjoining lots located between Purves Street and 44th Drive with frontage on both streets. Lot 4 is a square shaped lot consisting of 100.4 feet of street frontage on 44th Drive, and a maximum of 98.46 feet deep. Lot 4 is developed with a 1-story warehouse and full walkout cellar that opens to the adjoining lots along Purves Street which is at a lower elevation. The building can be accessed from 44th Drive or from the cellar level through Lots 22 and 23.

Lots 22 and 23 are adjacent rectangular lots each with 25 feet of frontage along Purves Street and are 100 feet deep. Both lots are currently vacant with vegetative cover. The total area of the three lots combined is 14,600 ft^2 (0.335 acres). The property is owned by 44 LIC, LLC.

The area surrounding the subject property consists of a mix of residential and commercial properties. The elevation of the Site is approximately 17 feet above the National Geodetic Vertical Datum (NGVD). The depth to groundwater beneath the Site was encountered at approximately 9 feet below basement level on Lot 4 and below surface grade of Lots 22 and 23. Based on regional groundwater contour maps, groundwater is expected to flow to the west toward the East River.

1.2 Site Background

1.2.1 Phase I Environmental Site Assessment, October 2011

A Phase I Environmental Site Assessment (ESA) was completed by Environmental Business Consultants, in October of 2011 for a portion of the Site (Block 268, Lot 4).

The Phase I report indicated that historical information (DOB records, Sanborn Maps, City Directory listings, and internet search) reviewed for the subject site identified the subject site as being developed in the early 1920's with the one-story building (with full basement) that currently stands at the site. In 1936, the building was used as a first floor parking garage, and the basement was used for storage of furniture. The 1936 Sanborn map shows a gasoline tank in the front of the building. In 1947, the basement was used as a paper warehouse, and the first floor parking garage space was used as a photo chemical warehouse. The gasoline tank is not drawn on the 1947 Sanborn map. The 1970 Sanborn map simply labels the building as commercial or manufacturing in 1960, but city directory listings

provided for 1962 indicate the building was used as an automotive/truck rental facility. All of the Sanborn maps from 1977 to 2006 label the building as an auto body shop, which correlates with the city directory listings and internet findings, which note Tul Mor Auto Service, Inc. in 1970, Alvic Foreign Auto Repair in 1983, NE Auto Repair, Inc. in 2000 and Northeastern Auto Repair, Inc. in the mid 2000's.

EBC concluded that based upon reconnaissance of the subject and surrounding properties, interviews and review of historical records and regulatory agency databases, the following recognized environmental conditions were noted for the site:

- Evidence indicating the presence of a gasoline underground storage tank underneath the concrete slab of the basement floor. The 1936 Sanborn map notes a gasoline tank near the front of the building. A vent pipe indicative of a gasoline tank is visible on the roof of the building near the southern garage door, and the remnants of a concrete dispenser island are visible immediately behind the garage door. The vent pipe was traced to the basement to a patch in the concrete floor.

Based on the age of the gasoline tank (85 years), EBC recommended the following actions:

- A Phase II Subsurface Investigation to include the collection and laboratory analysis of both soil and groundwater samples.
- Remove the gasoline tank and collect endpoint soil samples in accordance with NYS DER 10 / Technical Guidance for Site Investigation and Remediation
- Properly register and deregister the underground storage tank with the NYSDEC by completing and submitting a NYSDEC Petroleum Bulk Storage Application.
- Submit a Tank Removal Affidavit with the New York City Fire Department.
- Submit a Tank Closure Report to the NYSDEC.

Although the Phase I Report did not include recommendations for lots 22 and 23, the environmental history of both lots were evaluated in the Phase I. Lots 22 and 23 were originally developed prior to 1885 as 2 and 3-story residential buildings. From 1936 through 1950 both lots were part of an operation identified as "Controller Manufacturing". From 1970 through 2006 Lot 22 is shown as "welding and Repairs with directory listings that include Rozilda labs, Leather Goods, plating equipment, manufacturing and Artisan Designs. Lot 23 is shown as vacant from 1970 on with a single listing for Russell Cress Co. in 2005. The building on Lot 22 was demolished in 2008 and both lots are vacant.

2.0 SUBSURFACE INVESTIGATION

The field work portion of the Phase II was performed on May 10 and 17, 2013 and consisted of the collection and analysis of soil and groundwater samples. Drilling services were provided by Eastern Environmental Solutions of Manorville, NY. Analytical services were provided by Phoenix Environmental Laboratories (Phoenix) of 587 East Middle Turnpike, Manchester, CT 06040, a New York State ELAP certified environmental laboratory (ELAP Certification No. 11301)

2.1 Soil Sampling

Four soil borings were performed in Lots 22 and 23 to a depth of 20 feet below grade on May 10, 2013. Due to restricted access an additional two borings were performed around the suspect tank in Lot 4 of the Site to a depth of 10 feet below the basement slab on May 17, 2013. The approximate locations of the tank and the soil borings are shown on **Figure 2**.

Soil samples from each soil boring location were collected using a five foot steel dual tube sampler with acetate liners and Geoprobe direct-push equipment. For each of the soil borings, soil samples were collected continuously from grade to the termination depth of the soil boring. Soil cores were field screened for the presence of VOCs with a photo-ionization detector (PID) and visually inspected for evidence of contamination by a qualified environmental professional. Boring logs are provided in **Appendix A**.

During the May 10, 2013 site visit four soil borings were advanced to 20 feet below grade in Lots 22 and 23 (44-18 Purves Street). A sample was retained from the groundwater interface (7-10') of soil boring B1 and B2. A deeper sample was retained (12-15') from soil sample locations B3 and B4. Soil boring B2 exhibited a slight odor and low PID (10-20 ppm) readings around the groundwater interface. Due to limited access to the building basement on Lot 4 no borings were performed on May 10, 2013

An additional two soil borings were performed on May 17, 2013 around the suspect underground storage tank on Lot 4 of the Site. A soil sample was retained from the interval that exhibited the highest degree of contamination (B1(5-8'), B2(4-7')). Both borings showed physical evidence of petroleum contamination with PID readings from 0-400 ppm.

2.1.1 Soil Results

All of the soil samples were collected in pre-cleaned, laboratory supplied glassware, stored in a cooler with ice and delivered by laboratory dispatched courier to Phoenix Laboratories. Soil sample results were compared to the NYSDEC Part 375-6 Unrestricted Use Cleanup Objectives (UUSCOs) and Restricted Residential Soil Cleanup Objectives (RRSCOs). Analytical data for the soil samples are summarized in **Tables 1** through **2**, and a copy of the laboratory analytical reports are included in **Appendix B**.

VOCs

Only One VOC (n-Propylbenzene) was detected within the soil samples above its corresponding NYSDEC Part 375.6 Unrestricted Soil Cleanup Objectives (USCOs). The compound was detected within soil boring Tank B2. Soil sample B3(12-15') showed detections of cis-1,2-Dichloroethene, Tetrachloroethene, and Trichloroethene, but the levels were below UUSCOs.

SVOCs
No SVOCs were reported above their corresponding UUSCOs in any of the soil samples retained.

2.2 Groundwater Sampling

Following the installation of soil boring B1, B3, B4, Tank B1, and Tank B2, EBC installed a 1-inch diameter temporary PVC monitoring well. A groundwater sample was collected from the temporary monitoring well utilizing disposable polyethylene tubing, and a low-flow peristaltic pump.

The groundwater sample was collected in pre-cleaned, laboratory supplied glassware, stored in a cooler with ice. Groundwater samples GW1, GW3, and GW4 were submitted for analysis of VOCs by EPA Method 8260. Groundwater samples Tank GW1 and Tank GW2 were submitted for analysis of VOCs by EPA Method 8260 and SVOCs by EPA Method 8270 (CP51 List), to Phoenix Environmental Laboratories (Phoenix) of 587 East Middle Turnpike, Manchester, CT 06040, a New York State ELAP certified environmental laboratory (ELAP Certification No. 11301).

2.2.1 Groundwater Sample Results

Groundwater sample results were compared to the water quality standards specified in NYSDEC Groundwater Quality Standards (GQSs). Analytical data for the groundwater samples are summarized in **Tables 3 and 4** and a copy of the laboratory analytical report is provided in **Appendix B.**

VOCs
Several chlorinated VOCs were detected within the groundwater samples collected from locations GW1, GW3, and GW4. In addition, several petroleum VOCs were detected within the groundwater samples collected from locations Tank GW1 and Tank GW2. The findings are summarized below:

GW1	Tetrachloroethene (19 µg/L)
GW3	1,1,1-Trichloroethane (18 µg/L), cis-1,2-Dichloroethene (190 µg/L), Tetrachloroethene (950 µg/L), trans-1,2-Dichloroethene (6.6 µg/L), Trichloroethene (150 µg/L), and Vinyl Chloride (5.6 µg/L).
GW4	1,1,1-Trichloroethane (15 µg/L), cis-1,2-Dichloroethene (130 µg/L), Tetrachloroethene (610 µg/L), trans-1,2-Dichloroethene (14 µg/L), Trichloroethene (90 µg/L), and Vinyl Chloride (5.1 µg/L).
Tank GW1	n-Propylbenzene (21 µg/L).
Tank GW2	Isopropylbenzene (47 µg/L), Naphthalene (66 µg/L), n-Propylbenzene (110 µg/L).

SVOCs
Several SVOCs were detected within the groundwater samples Tank GW1 and Tank GW2. The findings are summarized below:

Tank GW1	Benzo(a)anthracene (11 µg/L), Benzo(b)fluoranthene (13 µg/L), Benzo(k)fluoranthene (5.1 µg/L), Chrsyene (11 µg/L), Indeno(1,2,3-cd)pyrene (5.8 µg/L).
*Tank GW2	Fluoranthene (73 µg/L), Naphthalene (57 µg/L), Phenanthrene (51 µg/L), Pyrene (69 µg/L).

*Due to a matrix interference and/or the presence of a large amount of non-target material in the sample, an elevated Report Limit (RL) was reported for the semivolatile analysis.

3.0 CONCLUSIONS

Subsurface soils at the site are primarily made up of urban fill material to a maximum depth of 4 feet, followed by a silty sand to approximately 15 feet below grade and coarse sand to the boring terminus. The groundwater was encountered at a depth of approximately 9 feet below grade of Lots 22 and 23.

Lots 22 and 23
No VOCs or SVOCs were detected above UUSCOs within any of the soil samples from Lots 22 and 23. Groundwater samples showed concentrations of several chlorinated VOCs above NYSDEC Groundwater Quality Standards including tetrachloroethene (PCE) at a concentration of 950 ug/L. Based on the historic use of the lots for controller manufacturing, leather goods and plating equipment and the chlorinated solvent detections in soil, it's possible that the contaminants are site related.

Lot 4
Elevated concentrations of petroleum VOCs were detected within one soil sample, but only one VOC, n-Propylbenzene, was reported above its respective UUSCO. No SVOCs were detected above UUSCOs within either of the soil samples retained. The groundwater results showed several petroleum VOCs and SVOCs over NYSDEC Groundwater Quality Standards in each sample including n-propylbenzene. Based on field observations and the elevated levels of petroleum VOCs in soil and groundwater in the vicinity of the UST, a spill was reported to the NYSDEC as required by Law (Spill No. 1302045).

4.0 REFERENCES

6 NYCRR Part 375 Environmental Remediation Programs Subparts 375-6

NYSDEC, Division of Water, June 1998, Addendum April 2000, *Technical and Administrative Guidance Series 1:1:1, Ambient Water Quality Standards and Guidance Values and Groundwater Effluent Limitations.*

Environmental Business Consultants, October 2011, *Phase I Environmental Site Assessment, 27-21 44th Drive, Long Island City, NY.*

TABLES

TABLE 1
27-21 44th Drive
Queens, NY
Soil Analytical Results
Volatile Organic Compounds

COMPOUND	NYSDEC Part 375.6 Unrestricted Use Soil Cleanup Objectives	NYDEC Part 375.6 Restricted Residential Soil Cleanup Objectives*	B1 (7-10') µg/Kg		B2 (7-10') µg/Kg		B3 (12-15') µg/Kg		B4 (12-15) µg/Kg		TANK B1 (5-8') µg/Kg		TANK B2 (4-7') µg/Kg	
			Result	RL	Result	RL	Result	RL	Result	RL	Result	RL	Result	RL
1,1,1,2-Tetrachlorothane			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
1,1,1-Trichloroethane	680	100,000	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
1,1,2,2-Tetrachloroethane			ND	4.2	ND	4.4	ND	3.2	ND	3.3	ND	7	ND	940
1,1,2-Trichloroethane			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
1,1-Dichloroethane	270	26,000	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
1,1-Dichloroethene	330	100,000	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
1,1-Dichloropropene			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
1,2,3-Trichlorobenzene			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
1,2,3-Trichloropropane			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
1,2,4-Trichlorobenzene			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
1,2,4-Trimethylbenzene	3,600	52,000	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
1,2-Dibromo-3-chloropropane			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
1,2-Dibromoethane			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
1,2-Dichlorobenzene	1,100	100,000	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
1,2-Dichloroethane	20	3,100	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
1,2-Dichloropropane			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
1,3,5-Trimethylbenzene	8,400	52,000	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
1,3-Dichlorobenzene	2,400	4,900	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
1,3-Dichloropropane			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
1,4-Dichlorobenzene	1,800	13,000	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
2,2-Dichloropropane			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
2-Chlorotoluene			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
2-Hexanone (Methyl Butyl Ketone)			ND	35	ND	36	ND	27	ND	27	ND	58	ND	7,900
2-Isopropyltoluene			ND	7	**12**	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
4-Chlorotoluene			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
4-Methyl-2-Pentanone			ND	35	ND	36	ND	27	ND	27	ND	58	ND	7,900
Acetone	50	100,000	ND	35	ND	36	ND	27	ND	27	ND	50	ND	31,000
Acrylonitrile			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Benzene	60	4,800	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Bromobenzene			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Bromochloromethane			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Bromodichloromethane			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Bromoform			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Bromomethane			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Carbon Disulfide			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Carbon tetrachloride	760	2,400	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Chlorobenzene	1,100	100,000	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Chloroethane			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Chloroform	370	49,000	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Chloromethane			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
cis-1,2-Dichloroethene	250	100,000	ND	7	ND	7.3	**90**	5.3	**12**	5.5	ND	12	ND	1,600
cis-1,3-Dichloropropene			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Dibromochloromethane			ND	4.2	ND	4.4	ND	3.2	ND	3.3	ND	7	ND	940
Dibromomethane			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Dichlorodifluoromethane		100,000	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Ethylbenzene	1,000	41,000	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Hexachlorobutadiene			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Isopropylbenzene			ND	7	ND	7.3	ND	5.3	ND	5.5	**32**	12	**2,000**	1,600
m&p-Xylenes	260		ND	7	ND	7.3	ND	5.3	ND	5.5	**16**	12	ND	1,600
Methyl Ethyl Ketone (2-Butanone)	120	100,000	ND	42	ND	44	ND	32	ND	33	ND	70	ND	9,400
Methyl t-butyl ether (MTBE)	930	100,000	ND	14	ND	15	ND	11	ND	11	ND	23	ND	3,100
Methylene chloride	50	100,000	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Naphthalene	12,000		ND	7	**39**	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
n-Butylbenzene	12,000	100,000	ND	7	**21**	7.3	ND	5.3	ND	5.5	**18**	12	**4,000**	1,600
n-Propylbenzene	3,900	100,000	ND	7	ND	7.3	ND	5.3	ND	5.5	**51**	12	**4,500**	1,600
o-Xylene	260	100,000	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
p-Isopropyltoluene			ND	7	**25**	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
sec-Butylbenzene	11,000	100,000	ND	7	**35**	7.3	ND	5.3	ND	5.5	**18**	12	**1,700**	1,600
Styrene			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
tert-Butylbenzene	5,900	100,000	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Tetrachloroethene	1,300	19,000	ND	7	ND	7.3	**630**	290	**92**	5.5	ND	12	ND	1,600
Tetrahydrofuran (THF)			ND	14	ND	15	ND	11	ND	11	ND	23	ND	3,100
Toluene	700	100,000	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Total Xylenes			ND	7	ND	7.3	ND	5.3	ND	5.5	16	12	ND	1,600
trans-1,2-Dichloroethene	190	100,000	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
trans-1,3-Dichloropropene			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
trabs-1,4-dichloro-2-butene			ND	14	ND	15	ND	11	ND	11	ND	23	ND	3,100
Trichloroethene	470	21,000	ND	7	ND	7.3	**64**	5.3	**11**	5.5	ND	12	ND	1,600
Trichlorofluoromethane			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Trichlorotrifluoroethane			ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Vinyl Chloride	20	900	ND	7	ND	7.3	ND	5.3	ND	5.5	ND	12	ND	1,600
Total BTEX Concentration			**0.0**		**25.0**		**0.0**		**0.0**		**0.0**		**0.0**	
Total VOCs Concentration			**0.0**		**132.0**		**784.0**		**115.0**		**151.0**		**12200.0**	

Notes:

** - 6 NYCRR Part 375-6 Remedial Program Soil Cleanup Objectives
ND - Not-detected
RL - Reporting Limit
Bold/highlighted- Indicated exceedance of the NYSDEC UUSCO Guidance Value
Bold/highlighted- Indicated exceedance of the NYSDEC RRSCO Guidance Value

TABLE 2
27-21 44th Drive
Queens, NY
Soil Analytical Results
Semi-Volatile Organic Compounds

COMPOUND	NYSDEC Part 375.6 Unrestricted Use Soil Cleanup Objectives	NYDEC Part 375.6 Restricted Residential Soil Cleanup Objectives*	B1 (7-10') µg/Kg		B2 (7-10') µg/Kg		B3 (12-15') µg/Kg		B4 (12-15) µg/Kg		TANK B1 (5-8') µg/Kg		TANK B2 (4-7') µg/Kg	
			Result	RL	Result	RL	Result	RL	Result	RL	Result	RL	Result	RL
Acenaphthene	20,000	100,000	ND	270	ND	270	ND	270	ND	270	ND	310	ND	3,100
Acenaphthylene	100,000	100,000	ND	270	ND	270	ND	270	ND	270	ND	310	ND	3,100
Anthracene	100,000	100,000	ND	270	ND	270	ND	270	ND	270	ND	310	ND	3,100
Benz(a)anthracene	1,000	1,000	ND	270	ND	270	ND	270	ND	270	**680**	310	ND	3,100
Benzo(a)pyrene	1,000	1,000	ND	270	ND	270	ND	270	ND	270	**580**	310	ND	3,100
Benzo(b)fluoranthene	1,000	1,000	ND	270	ND	270	ND	270	ND	270	**700**	310	ND	3,100
Benzo(ghi)perylene	100,000	100,000	ND	270	ND	270	ND	270	ND	270	**410**	310	ND	3,100
Benzo(k)fluoranthene	800	3,900	ND	270	ND	270	ND	270	ND	270	ND	310	ND	3,100
Chrysene	1,000	3,900	ND	270	ND	270	ND	270	ND	270	**820**	310	ND	3,100
Dibenz(a,h)anthracene	330	330	ND	270	ND	270	ND	270	ND	270	ND	310	ND	3,100
Fluoranthene	100,000	100,000	ND	270	ND	270	ND	270	ND	270	**1,600**	310	ND	3,100
Fluorene	30,000	100,000	ND	270	ND	270	ND	270	ND	270	ND	310	ND	3,100
Indeno(1,2,3-cd)pyrene	500	500	ND	270	ND	270	ND	270	ND	270	ND	310	ND	3,100
Naphthalene	12,000	100,000	ND	270	ND	270	ND	270	ND	270	**310**	310	ND	3,100
Phenanthrene	100,000	100,000	ND	270	ND	270	ND	270	ND	270	**1,100**	310	ND	3,100
Pyrene	100,000	100,000	ND	270	ND	270	ND	270	ND	270	**1,700**	310	ND	3,100

Notes:

* - NYSDEC Technical and Administative Guidance Memorandum 4046, 1994

** - 6 NYCRR Part 375-6 Remedial Program Soil Cleanup Objectives

ND - Not-detected

NA - Not Analyzed

Bold/highlighted- Indicated exceedance of the NYSDEC UUSCO Guidance Value

Bold/highlighted- Indicated exceedance of the NYSDEC RRSCO Guidance Value

TABLE 3
27-21 44th Drive
Queens, NY
Groundwater Analytical Results
Volatile Organic Compounds

Compound	NYSDEC Groundwater Quality Standards	GW1		GW3		GW4		TANK GW1		TANK GW2	
	µg/L	µg/L		µg/L		µg/L		µg/L		µg/L	
	µg/L	Result	RL	Result	RL	Result	RL	Result	RL	Result	RL
1,1,1,2-Tetrachlorothane	5	ND	1	ND	1	ND	2	ND	20	ND	40
1,1,1-Trichloroethane	5	ND	1	**18**	1	**15**	2	ND	20	ND	40
1,1,2,2-Tetrachloroethane	5	ND	0.5	ND	0.5	ND	1	ND	10	ND	20
1,1,2-Trichloroethane	1	ND	1	ND	1	ND	2	ND	20	ND	40
1,1-Dichloroethane	5	ND	1	**1.7**	1	**3.1**	2	ND	20	ND	40
1,1-Dichloroethene	5	ND	1	**1.4**	1	ND	2	ND	20	ND	40
1,1-Dichloropropene		ND	1	ND	1	ND	2	ND	20	ND	40
1,2,3-Trichlorobenzene		ND	1	ND	1	ND	2	ND	20	ND	40
1,2,3-Trichloropropane	0.04	ND	1	ND	1	ND	2	ND	20	ND	40
1,2,4-Trichlorobenzene		ND	1	ND	1	ND	2	ND	20	ND	40
1,2,4-Trimethylbenzene	5	ND	1	ND	1	ND	2	ND	20	ND	40
1,2-Dibromo-3-chloropropane	0.04	ND	1	ND	1	ND	2	ND	20	ND	40
1,2-Dichlorobenzene	5	ND	1	ND	1	ND	2	ND	20	ND	40
1,2-Dichloroethane	0.6	ND	1	ND	1	ND	2	ND	20	ND	40
1,2-Dichloropropane	0.94	ND	0.6	ND	0.6	ND	1.2	ND	12	ND	24
1,3,5-Trimethylbenzene	5	ND	1	ND	1	ND	2	ND	20	ND	40
1,2-Dibromoethane		ND	1	ND	1	ND	2	ND	20	ND	40
1,3-Dichlorobenzene	5	ND	1	ND	1	ND	2	ND	20	ND	40
1,3-Dichloropropane	5	ND	1	ND	1	ND	2	ND	20	ND	40
1,4-Dichlorobenzene	5	ND	1	ND	1	ND	2	ND	20	ND	40
2,2-Dichloropropane	5	ND	1	ND	1	ND	2	ND	20	ND	40
2-Chlorotoluene	5	ND	1	ND	1	ND	2	ND	20	ND	40
2-Hexanone (Methyl Butyl Ketone)		ND	5	ND	5	ND	10	ND	100	ND	200
2-Isopropyltoluene	5	ND	1	ND	1	ND	2	ND	20	ND	40
4-Chlorotoluene	5	ND	1	ND	1	ND	2	ND	20	ND	40
4-Methyl-2-Pentanone		ND	5	ND	5	ND	10	ND	100	ND	200
Acetone		ND	25	ND	25	ND	50	ND	500	ND	1,000
Acrylonitrile	5	ND	5	ND	5	ND	10	ND	100	ND	200
Benzene	1	ND	0.7	ND	0.7	ND	1.4	ND	14	ND	28
Bromobenzene	5	ND	1	ND	1	ND	2	ND	20	ND	40
Bromochloromethane	5	ND	1	ND	1	ND	2	ND	20	ND	40
Bromodichloromethane		ND	0.5	ND	0.5	ND	1	ND	10	ND	20
Bromoform		ND	1	ND	1	ND	2	ND	20	ND	40
Bromomethane	5	ND	1	ND	1	ND	2	ND	20	ND	40
Carbon Disulfide	60	ND	5	ND	5	ND	10	ND	100	ND	200
Carbon tetrachloride	5	ND	1	ND	1	ND	2	ND	20	ND	40
Chlorobenzene	5	ND	1	ND	1	ND	2	ND	20	ND	40
Chloroethane	5	ND	1	ND	1	ND	2	ND	20	ND	40
Chloroform	7	ND	1	ND	1	ND	2	ND	20	ND	40
Chloromethane	60	ND	1	ND	1	ND	2	ND	20	ND	40
cis-1,2-Dichloroethene	5	**4.2**	1	**190**	10	**130**	20	ND	20	ND	40
cis-1,3-Dichloropropene		ND	0.5	ND	0.5	ND	1	ND	10	ND	20
Dibromochloromethane		ND	0.5	ND	0.5	ND	1	ND	10	ND	20
Dibromomethane	5	ND	1	ND	1	ND	2	ND	20	ND	40
Dichlorodifluoromethane	5	ND	1	ND	1	ND	2	ND	20	ND	40
Ethylbenzene	5	ND	1	ND	1	ND	2	ND	20	ND	40
Hexachlorobutadiene	0.5	ND	0.4	ND	0.4	ND	0.8	ND	8	ND	16
Isopropylbenzene	5	ND	1	ND	1	ND	2	ND	20	**47**	40
m&p-Xylenes	5	ND	1	ND	1	ND	2	ND	20	ND	40
Methyl Ethyl Ketone (2-Butanone)		ND	5	ND	5	ND	10	ND	100	ND	200
Methyl t-butyl ether (MTBE)	10	ND	1	ND	1	ND	2	ND	20	ND	40
Methylene chloride	5	ND	1	ND	1	ND	2	ND	20	ND	40
Naphthalene	10	ND	1	ND	1	ND	2	ND	20	ND	40
n-Butylbenzene	5	ND	1	ND	1	ND	2	ND	20	**66**	40
n-Propylbenzene	5	ND	1	ND	1	ND	2	**21**	20	**110**	40
o-Xylene	5	ND	1	ND	1	ND	2	ND	20	ND	40
p-Isopropyltoluene		ND	1	ND	1	ND	2	ND	20	ND	40
sec-Butylbenzene	5	ND	1	ND	1	ND	2	ND	20	ND	40
Styrene	5	ND	1	ND	1	ND	2	ND	20	ND	40
tert-Butylbenzene	5	ND	1	ND	1	ND	2	ND	20	ND	40
Tetrachloroethene	5	**19**	1	**950**	50	**610**	20	ND	20	ND	40
Tetrahydrofuran (THF)		ND	2.5	ND	2.5	ND	5	ND	50	ND	100
Toluene	5	**1.8**	1	ND	1	ND	2	ND	20	ND	40
Total Xylenes	5	ND	1	ND	1	ND	2	ND	20	ND	40
trans-1,2-Dichloroethene	5	ND	1	**6.6**	1	**14**	2	ND	20	ND	40
trans-1,3-Dichloropropene	0.4	ND	0.5	ND	0.5	ND	1	ND	10	ND	20
trans-1,4-dichloro-2-butene	5	ND	5	ND	5	ND	10	ND	100	ND	200
Trichloroethene	5	**3.2**	1	**150**	10	**90**	20	ND	20	ND	40
Trichlorofluoromethane	5	ND	1	ND	1	ND	2	ND	20	ND	40
Trichlorotrifluoroethane		ND	1	ND	1	ND	2	ND	20	ND	40
Vinyl Chloride	2	ND	1	**5.6**	1	**5.1**	2	ND	20	ND	40


Notes:
ND - Not detected
Bold/highlighted- Indicated exceedance of the NYSDEC Groundwater Standard

TABLE 4
27-21 44th Drive
Queens, NY
Groundwater Analytical Results
Volatile Organic Compounds

Compound	NYSDEC Groundwater Quality Standards µg/L	TANK GW1 µg/L		TANK GW2 µg/L	
		Result	RL	Result	RL
2-Methylnaphthalene		**0.98**	0.1	ND	*50
Acenaphthene	20	**1.4**	0.1	ND	*50
Acenaphthylene		**1.1**	0.1	ND	*50
Anthracene	50	**4.3**	0.1	ND	*50
Benz(a)anthracene	0.002	**11**	0.02	ND	*50
Benzo(a)pyrene		**11**	0.02	ND	*50
Benzo(b)fluoranthene	0.002	**13**	0.02	ND	*50
Benzo(ghi)perylene		**7.5**	0.1	ND	*50
Benzo(k)fluoranthene	0.002	**5.1**	0.02	ND	*50
Chrysene	0.002	**11**	0.02	ND	*50
Dibenzo(a,h)anthracene		**1.5**	0.01	ND	*50
Fluoranthene	50	**19**	0.1	**73**	*50
Fluorene	50	**1.4**	0.1	ND	*50
Indeno(1,2,3-cd)pyrene	0.002	**5.8**	0.02	ND	*50
Naphthalene	10	**1.5**	0.1	**57**	*50
Phenanthrene	50	**14**	0.07	**51**	*50
Pyrene	50	**21**	0.1	**69**	*50

Notes:
ND - Not detected
* - Due to a matrix interference and/or the presence of a large amount of non-target material in the sample, an elevated RL was reported for the semivolatile analysis.
Bold/highlighted- Indicated exceedance of the NYSDEC Groundwater Standard

FIGURES




USGS Brooklyn Quadrangle 1995, Contour Interval = 10 feet

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
Phone 631.504.6000
Fax 631. 924 .2870

27-21 44TH DRIVE & 44-18/20 PURVES STREET
LONG ISLAND CITY, NY

FIGURE 1 SITE LOCATION MAP



EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
Phone 631.504.6000
Fax 631. 924 .2870

27-21 44TH DRIVE, 44-18 PURVES STREET
QUEENS, NY 11101

FIGURE 2 SITE PLAN

APPENDIX A
SOIL BORING LOGS

Geologic Boring Log Details

ENVIRONMENTAL BUSINESS CONSULTANTS

B1 Boring Log

Location: Performed in the rear of Lot 23.		Depth to Water (ft. from grade.)		Site Elevation Datum
Site Name: VHL1102	Address: 27-21 44th Drive, 4418 Purves Street Long Island City, Queens	Date	DTW	Ground Elevation
		Groundwater depth		
Drilling Company: Eastern Environmental Solutions, Inc.	Method: Geoprobe	9 feet		Well Specifications
Date Started: 5/10/2013	Date Completed: 5/10/2013			None
Completion Depth: 20 Feet	Geologist Dominick Mosca			

B1 (NTS)	DEPTH (ft below grade)	SAMPLES Recovery (in.)	Blow per 6 in.	PID (ppm)	SOIL DESCRIPTION
	0				
	to 5	29		0.0	3" - Top soil. 26" - Dark fill material in a firm silty sand matrix.
	to 10	30		0.0	14" - Moist brown silty sand, little to no gravel. No odor, No PID. 16" - Saturated brown, sandy loam. No gravel, No PID, No odor. **Retained Soil Sample B1 (7-10')*
	to 15	32		0.0	12" - Saturated brown silty sand with fine gravel. No odor, No PID. 20" - Coarse sand and gravel. No odor, No PID.
	to 20	18		0.0	18" - Saturated coarse sand and gravel. No PID, no odor.

Geologic Boring Log Details

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS

B2 Boring Log

Location: Performed in the rear of Lot 22.		Depth to Water (ft. from grade.)		Site Elevation Datum
Site Name: VHL1102	Address: 27-21 44th Drive, 4418 Purves Street Long Island City, Queens	Date	DTW	Ground Elevation
		Groundwater depth		
Drilling Company: Eastern Environmental Solutions, Inc.	Method: Geoprobe	9 feet		Well Specifications
Date Started: 5/10/2013	Date Completed: 5/10/2013			None
Completion Depth: 20 Feet	Geologist Dominick Mosca			

B2 (NTS)	DEPTH (ft below grade)	SAMPLES Recovery (in.)	Blow per 6 in.	PID (ppm)	SOIL DESCRIPTION
	0				
	to 5	20		0.0	2" - Top soil. 8" - Sandy fill, brick, gravel, dark moist sandy soil. 10" - Fine brown sand with fine gravel and trace silt. No odor, No PID.
	to 10	32		0-50	12" - Fine brown sand and gravel. 12" - Saturated grey sandy loam. Petroleum odor. PID 0-50ppm. 7" - Saturated brown sand with gravel. Slight odor. **Retained Soil Sample B2 (7-10')*
	to 15	42		0.0	20" - Moist, brown to grey fine sandy loam with little to no gravel. No PID, no odor. 20" - Saturated, grey fine silty sand with approximately 10% gravel. No odor, No PID.
	to 20	24		0-3	24" - Saturated brown coarse sand and gravel. Bottom 8" had slight petroleum odor.

Geologic Boring Log Details

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS

B3 Boring Log

Location: Performed in the front portion of Lot 23.		Depth to Water (ft. from grade.)		Site Elevation Datum
Site Name: VHL1102	Address: 27-21 44th Drive, 4418 Purves Street Long Island City, Queens	Date	DTW	Ground Elevation
		Groundwater depth		
Drilling Company: Eastern Environmental Solutions, Inc.	Method: Geoprobe	9 feet		Well Specifications
Date Started: 5/10/2013	Date Completed: 5/10/2013			None
Completion Depth: 20 Feet	Geologist Dominick Mosca			

B3 (NTS)	DEPTH (ft below grade)	SAMPLES Recovery (in.)	Blow per 6 in.	PID (ppm)	SOIL DESCRIPTION
	0				
	to 5	35		0.0	1" - Top soil. 6" - Concrete. 5" - Sandy fill material comprised of brick, wood, etc. 23" - Moist, brown silty sand with assorted gravel for the bottom 8".
	to 10	30		0.0	28" - Moist brown sandy clay. No gravel, No PID, No odor. 2" - Saturated silty sand with fine gravel.
	to 15	36		0.0	25" - Saturated brown silty sand and fine gravel. 11" - Dark brown sandy clay, no gravel. PID 0-5ppm, No odor. **Retained Soil Sample B3 (12-15')*
	to 20	30		0.0	25" - Firm, saturated, dark brown clay with no gravel. No odor, No PID. 5" - Coarse sand and gravel. No PID, no odor.

Geologic Boring Log Details

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS

B4 Boring Log

Location: Performed in front portion of Lot 22.		Depth to Water (ft. from grade.)		Site Elevation Datum
Site Name: VHL1102	Address: 27-21 44th Drive, 4418 Purves Street Long Island City, Queens	Date	DTW	Ground Elevation
		Groundwater depth		
Drilling Company: Eastern Environmental Solutions, Inc.	Method: Geoprobe	9 feet		Well Specifications
Date Started: 5/10/2013	Date Completed: 5/10/2013			None
Completion Depth: 20 Feet	Geologist Dominick Mosca			

B4 (NTS)	DEPTH (ft below grade)	SAMPLES Recovery (in.)	Blow per 6 in.	PID (ppm)	SOIL DESCRIPTION
	0				
	to 5	40		0.0	4" - Top soil. 36" - Fine brown silty sand with assorted gravel. No PID, no odor.
	to 10	22		0.0	22" - Moist brown silty sand with gravel. No odor, no PID.
	to 15	42		0.0	20" - Moist, brown to grey fine sandy loam with little to no gravel. No PID, no odor. 20" - Saturated, grey fine silty sand with approximately 10% gravel. No odor, No PID. **Retained Soil Sample B4 (12-15')*
	to 20	30		0.0	30" - Saturated medium sand with approx. 50% gravel. No odor, No PID. **Retained Groundwater Sample GW4.*

Geologic Boring Log Details

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS

Tank B1 Boring Log

Location: Performed adjacent to the suspect UST (toward Purves Street).			Depth to Water (ft. from grade.)	Site Elevation Datum
Site Name: VHL1102	Address: 27-21 44th Drive, 4418 Purves Street Long Island City, Queens		Date / DTW	Ground Elevation
			Groundwater depth	
Drilling Company: Eastern Environmental Solutions, Inc.	Method: Geoprobe		9 feet	Well Specifications
Date Started: 5/12/2013	Date Completed: 5/12/2013			None
Completion Depth: 10 Feet	Geologist Dominick Mosca			

Tank B1 (NTS)	DEPTH (ft below grade)	SAMPLES Recovery (in.)	Blow per 6 in.	PID (ppm)	SOIL DESCRIPTION
	0				
	to 5	50		200.0	30" - Fill material. 20" - Saturated silty sand. Stained black, heavy petroleum odor. PID 100-200ppm.
	to 10	50		300.0	50" - Saturated silty sand with fine gravel. Stained black with heavy petroleum odor, PID 0-300ppm. *Retained Soil Sample B1 (5-7')*

Geologic Boring Log Details

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS

Tank B2 Boring Log

Location: Performed toward the rear wall.			Depth to Water (ft. from grade.)		Site Elevation Datum
Site Name: VHL1102	Address: 27-21 44th Drive, 4418 Purves Street Long Island City, Queens		Date	DTW	Ground Elevation
			Groundwater depth		
Drilling Company: Eastern Environmental Solutions, Inc.	Method: Geoprobe		9 feet		Well Specifications
Date Started: 5/12/2013	Date Completed: 5/12/2013				None
Completion Depth: 10 Feet	Geologist Dominick Mosca				

Tank B2 (NTS)	DEPTH (ft below grade)	SAMPLES Recovery (in.)	Blow per 6 in.	PID (ppm)	SOIL DESCRIPTION
	0				
	to	35		0-10	15" - Concrete 10" - Dark brown silty sand with gravel. Slight petroleum odor.
	5				
	to	40		280.0	40" - Stained black silty sand with fine gravel. PID 100-280ppm. **Retained Soil Sample B2 (5-7')*
	10				

APPENDIX B
LABORATORY REPORTS

PHOENIX
Environmental Laboratories, Inc.

Monday, May 20, 2013

Attn: Mr. Charles B. Sosik, P.G.
Environmental Business Consultants
1808 Middle Country Rd
Ridge NY 11961-2406

Project ID: 4416-4418 PURVES ST.
Sample ID#s: BD71472 - BD71478

This laboratory is in compliance with the NELAC requirements of procedures used except where indicated.

This report contains results for the parameters tested, under the sampling conditions described on the Chain Of Custody, as received by the laboratory.

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

A scanned version of the COC form accompanies the analytical report and is an exact duplicate of the original.

If you have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext. 200.

Sincerely yours,

Phyllis Shiller

Laboratory Director

NELAC - #NY11301
CT Lab Registration #PH-0618
MA Lab Registration #MA-CT-007
ME Lab Registration #CT-007
NH Lab Registration #213693-A,B
NJ Lab Registration #CT-003
NY Lab Registration #11301
PA Lab Registration #68-03530
RI Lab Registration #63
VT Lab Registration #VT11301

PHOENIX

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

SDG Comments

May 20, 2013

SDG I.D.: GBD71472

BD71476 - The pH in the preserved vial was greater than 2.

PHOENIX

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

Analysis Report

May 20, 2013

FOR: Attn: Mr. Charles B. Sosik, P.G.
Environmental Business Consultants
1808 Middle Country Rd
Ridge NY 11961-2406

Sample Information		Custody Information		Date	Time
Matrix:	SOIL	Collected by:		05/10/13	0:00
Location Code:	EBC	Received by:	LB	05/13/13	17:14
Rush Request:	72 Hour	Analyzed by:	see "By" below		
P.O.#:					

Laboratory Data

SDG ID: GBD71472
Phoenix ID: BD71472

Project ID: 4416-4418 PURVES ST.
Client ID: B1 7-10

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
Percent Solid	85		%	05/13/13	JL	E160.3
Soil Extraction SVOA PAH	Completed			05/13/13	BJ/V	SW3545
Field Extraction	Completed			05/10/13		SW5035
Volatiles						
1,1,1,2-Tetrachloroethane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
1,1,1-Trichloroethane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
1,1,2,2-Tetrachloroethane	ND	4.2	ug/Kg	05/15/13	R/J	SW8260
1,1,2-Trichloroethane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
1,1-Dichloroethane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
1,1-Dichloroethene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
1,1-Dichloropropene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
1,2,3-Trichlorobenzene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
1,2,3-Trichloropropane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
1,2,4-Trichlorobenzene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
1,2,4-Trimethylbenzene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
1,2-Dibromo-3-chloropropane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
1,2-Dibromoethane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
1,2-Dichlorobenzene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
1,2-Dichloroethane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
1,2-Dichloropropane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
1,3,5-Trimethylbenzene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
1,3-Dichlorobenzene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
1,3-Dichloropropane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
1,4-Dichlorobenzene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
2,2-Dichloropropane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
2-Chlorotoluene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260
2-Hexanone	ND	35	ug/Kg	05/15/13	R/J	SW8260
2-Isopropyltoluene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260

Project ID: 4416-4418 PURVES ST.
Client ID: B1 7-10

Phoenix I.D.: BD71472

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
4-Chlorotoluene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
4-Methyl-2-pentanone	ND	35	ug/Kg	05/15/13	R/J	SW8260	
Acetone	ND	35	ug/Kg	05/15/13	R/J	SW8260	
Acrylonitrile	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Benzene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Bromobenzene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Bromochloromethane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Bromodichloromethane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Bromoform	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Bromomethane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Carbon Disulfide	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Carbon tetrachloride	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Chlorobenzene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Chloroethane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Chloroform	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Chloromethane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
cis-1,2-Dichloroethene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
cis-1,3-Dichloropropene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	1
Dibromochloromethane	ND	4.2	ug/Kg	05/15/13	R/J	SW8260	
Dibromomethane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Dichlorodifluoromethane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Ethylbenzene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Hexachlorobutadiene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Isopropylbenzene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
m&p-Xylene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Methyl Ethyl Ketone	ND	42	ug/Kg	05/15/13	R/J	SW8260	
Methyl t-butyl ether (MTBE)	ND	14	ug/Kg	05/15/13	R/J	SW8260	
Methylene chloride	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Naphthalene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
n-Butylbenzene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
n-Propylbenzene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
o-Xylene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
p-Isopropyltoluene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
sec-Butylbenzene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Styrene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
tert-Butylbenzene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Tetrachloroethene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Tetrahydrofuran (THF)	ND	14	ug/Kg	05/15/13	R/J	SW8260	1
Toluene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Total Xylenes	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
trans-1,2-Dichloroethene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
trans-1,3-Dichloropropene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
trans-1,4-dichloro-2-butene	ND	14	ug/Kg	05/15/13	R/J	SW8260	
Trichloroethene	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Trichlorofluoromethane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Trichlorotrifluoroethane	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
Vinyl chloride	ND	7.0	ug/Kg	05/15/13	R/J	SW8260	
QA/QC Surrogates							
% 1,2-dichlorobenzene-d4	103		%	05/15/13	R/J	70 - 130 %	
% Bromofluorobenzene	90		%	05/15/13	R/J	70 - 130 %	

Project ID: 4416-4418 PURVES ST. Phoenix I.D.: BD71472
Client ID: B1 7-10

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
% Dibromofluoromethane	104		%	05/15/13	R/J	70 - 130 %
% Toluene-d8	94		%	05/15/13	R/J	70 - 130 %
Semivolatiles-STARS/CP-51						
Acenaphthene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Acenaphthylene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Anthracene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benz(a)anthracene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benzo(a)pyrene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benzo(b)fluoranthene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benzo(ghi)perylene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benzo(k)fluoranthene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Chrysene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Dibenz(a,h)anthracene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Fluoranthene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Fluorene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Indeno(1,2,3-cd)pyrene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Naphthalene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Phenanthrene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Pyrene	ND	270	ug/Kg	05/16/13	DD	SW 8270
QA/QC Surrogates						
% 2-Fluorobiphenyl	95		%	05/16/13	DD	30 - 130 %
% Nitrobenzene-d5	94		%	05/16/13	DD	30 - 130 %
% Terphenyl-d14	104		%	05/16/13	DD	30 - 130 %

1 = This parameter is not certified by NY NELAC for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quanitation) ND=Not Detected BRL=Below Reporting Level

Comments:

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.
This report must not be reproduced except in full as defined by the attached chain of custody.



Phyllis Shiller, Laboratory Director
May 20, 2013
Reviewed and Released by: Greg Lawrence, Assistant Lab Director

PHOENIX

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

Analysis Report

May 20, 2013

FOR: Attn: Mr. Charles B. Sosik, P.G.
Environmental Business Consultants
1808 Middle Country Rd
Ridge NY 11961-2406

Sample Information		Custody Information		Date	Time
Matrix:	SOIL	Collected by:		05/10/13	0:00
Location Code:	EBC	Received by:	LB	05/13/13	17:14
Rush Request:	72 Hour	Analyzed by:	see "By" below		
P.O.#:					

Laboratory Data

SDG ID: GBD71472
Phoenix ID: BD71473

Project ID: 4416-4418 PURVES ST.
Client ID: B2 7-10

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
Percent Solid	83		%	05/13/13	JL	E160.3
Soil Extraction SVOA PAH	Completed			05/13/13	BJ/V	SW3545
Field Extraction	Completed			05/10/13		SW5035
Volatiles						
1,1,1,2-Tetrachloroethane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
1,1,1-Trichloroethane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
1,1,2,2-Tetrachloroethane	ND	4.4	ug/Kg	05/15/13	R/J	SW8260
1,1,2-Trichloroethane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
1,1-Dichloroethane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
1,1-Dichloroethene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
1,1-Dichloropropene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
1,2,3-Trichlorobenzene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
1,2,3-Trichloropropane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
1,2,4-Trichlorobenzene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
1,2,4-Trimethylbenzene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
1,2-Dibromo-3-chloropropane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
1,2-Dibromoethane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
1,2-Dichlorobenzene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
1,2-Dichloroethane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
1,2-Dichloropropane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
1,3,5-Trimethylbenzene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
1,3-Dichlorobenzene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
1,3-Dichloropropane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
1,4-Dichlorobenzene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
2,2-Dichloropropane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
2-Chlorotoluene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260
2-Hexanone	ND	36	ug/Kg	05/15/13	R/J	SW8260
2-Isopropyltoluene	12	7.3	ug/Kg	05/15/13	R/J	SW8260

Project ID: 4416-4418 PURVES ST.
Client ID: B2 7-10

Phoenix I.D.: BD71473

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
4-Chlorotoluene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
4-Methyl-2-pentanone	ND	36	ug/Kg	05/15/13	R/J	SW8260	
Acetone	ND	36	ug/Kg	05/15/13	R/J	SW8260	
Acrylonitrile	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Benzene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Bromobenzene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Bromochloromethane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Bromodichloromethane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Bromoform	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Bromomethane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Carbon Disulfide	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Carbon tetrachloride	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Chlorobenzene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Chloroethane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Chloroform	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Chloromethane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
cis-1,2-Dichloroethene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
cis-1,3-Dichloropropene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	1
Dibromochloromethane	ND	4.4	ug/Kg	05/15/13	R/J	SW8260	
Dibromomethane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Dichlorodifluoromethane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Ethylbenzene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Hexachlorobutadiene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Isopropylbenzene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
m&p-Xylene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Methyl Ethyl Ketone	ND	44	ug/Kg	05/15/13	R/J	SW8260	
Methyl t-butyl ether (MTBE)	ND	15	ug/Kg	05/15/13	R/J	SW8260	
Methylene chloride	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Naphthalene	39	7.3	ug/Kg	05/15/13	R/J	SW8260	
n-Butylbenzene	21	7.3	ug/Kg	05/15/13	R/J	SW8260	
n-Propylbenzene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
o-Xylene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
p-Isopropyltoluene	25	7.3	ug/Kg	05/15/13	R/J	SW8260	
sec-Butylbenzene	35	7.3	ug/Kg	05/15/13	R/J	SW8260	
Styrene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
tert-Butylbenzene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Tetrachloroethene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Tetrahydrofuran (THF)	ND	15	ug/Kg	05/15/13	R/J	SW8260	1
Toluene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Total Xylenes	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
trans-1,2-Dichloroethene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
trans-1,3-Dichloropropene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
trans-1,4-dichloro-2-butene	ND	15	ug/Kg	05/15/13	R/J	SW8260	
Trichloroethene	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Trichlorofluoromethane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Trichlorotrifluoroethane	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
Vinyl chloride	ND	7.3	ug/Kg	05/15/13	R/J	SW8260	
QA/QC Surrogates							
% 1,2-dichlorobenzene-d4	87		%	05/15/13	R/J	70 - 130 %	
% Bromofluorobenzene	108		%	05/15/13	R/J	70 - 130 %	

Project ID: 4416-4418 PURVES ST. Phoenix I.D.: BD71473
Client ID: B2 7-10

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
% Dibromofluoromethane	101		%	05/15/13	R/J	70 - 130 %
% Toluene-d8	94		%	05/15/13	R/J	70 - 130 %
Semivolatiles-STARS/CP-51						
Acenaphthene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Acenaphthylene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Anthracene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benz(a)anthracene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benzo(a)pyrene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benzo(b)fluoranthene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benzo(ghi)perylene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benzo(k)fluoranthene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Chrysene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Dibenz(a,h)anthracene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Fluoranthene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Fluorene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Indeno(1,2,3-cd)pyrene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Naphthalene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Phenanthrene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Pyrene	ND	270	ug/Kg	05/16/13	DD	SW 8270
QA/QC Surrogates						
% 2-Fluorobiphenyl	37		%	05/16/13	DD	30 - 130 %
% Nitrobenzene-d5	40		%	05/16/13	DD	30 - 130 %
% Terphenyl-d14	47		%	05/16/13	DD	30 - 130 %

1 = This parameter is not certified by NY NELAC for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quanitation) ND=Not Detected BRL=Below Reporting Level

Comments:

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.
This report must not be reproduced except in full as defined by the attached chain of custody.



Phyllis Shiller, Laboratory Director
May 20, 2013
Reviewed and Released by: Greg Lawrence, Assistant Lab Director

PHOENIX

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

Analysis Report

May 20, 2013

FOR: Attn: Mr. Charles B. Sosik, P.G.
Environmental Business Consultants
1808 Middle Country Rd
Ridge NY 11961-2406

Sample Information		Custody Information		Date	Time
Matrix:	SOIL	Collected by:		05/10/13	0:00
Location Code:	EBC	Received by:	LB	05/13/13	17:14
Rush Request:	72 Hour	Analyzed by:	see "By" below		
P.O.#:					

Laboratory Data

SDG ID: GBD71472
Phoenix ID: BD71474

Project ID: 4416-4418 PURVES ST.
Client ID: B3 12-15

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
Percent Solid	86		%	05/13/13	JL	E160.3
Soil Extraction SVOA PAH	Completed			05/13/13	BJ/V	SW3545
Field Extraction	Completed			05/10/13		SW5035
Volatiles						
1,1,1,2-Tetrachloroethane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
1,1,1-Trichloroethane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
1,1,2,2-Tetrachloroethane	ND	3.2	ug/Kg	05/15/13	R/J	SW8260
1,1,2-Trichloroethane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
1,1-Dichloroethane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
1,1-Dichloroethene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
1,1-Dichloropropene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
1,2,3-Trichlorobenzene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
1,2,3-Trichloropropane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
1,2,4-Trichlorobenzene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
1,2,4-Trimethylbenzene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
1,2-Dibromo-3-chloropropane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
1,2-Dibromoethane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
1,2-Dichlorobenzene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
1,2-Dichloroethane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
1,2-Dichloropropane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
1,3,5-Trimethylbenzene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
1,3-Dichlorobenzene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
1,3-Dichloropropane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
1,4-Dichlorobenzene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
2,2-Dichloropropane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
2-Chlorotoluene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260
2-Hexanone	ND	27	ug/Kg	05/15/13	R/J	SW8260
2-Isopropyltoluene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260

Project ID: 4416-4418 PURVES ST.
Client ID: B3 12-15

Phoenix I.D.: BD71474

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
4-Chlorotoluene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
4-Methyl-2-pentanone	ND	27	ug/Kg	05/15/13	R/J	SW8260	
Acetone	ND	27	ug/Kg	05/15/13	R/J	SW8260	
Acrylonitrile	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Benzene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Bromobenzene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Bromochloromethane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Bromodichloromethane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Bromoform	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Bromomethane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Carbon Disulfide	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Carbon tetrachloride	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Chlorobenzene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Chloroethane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Chloroform	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Chloromethane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
cis-1,2-Dichloroethene	90	5.3	ug/Kg	05/15/13	R/J	SW8260	
cis-1,3-Dichloropropene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	1
Dibromochloromethane	ND	3.2	ug/Kg	05/15/13	R/J	SW8260	
Dibromomethane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Dichlorodifluoromethane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Ethylbenzene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Hexachlorobutadiene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Isopropylbenzene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
m&p-Xylene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Methyl Ethyl Ketone	ND	32	ug/Kg	05/15/13	R/J	SW8260	
Methyl t-butyl ether (MTBE)	ND	11	ug/Kg	05/15/13	R/J	SW8260	
Methylene chloride	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Naphthalene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
n-Butylbenzene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
n-Propylbenzene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
o-Xylene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
p-Isopropyltoluene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
sec-Butylbenzene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Styrene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
tert-Butylbenzene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Tetrachloroethene	630	290	ug/Kg	05/15/13	R/J	SW8260	
Tetrahydrofuran (THF)	ND	11	ug/Kg	05/15/13	R/J	SW8260	1
Toluene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Total Xylenes	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
trans-1,2-Dichloroethene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
trans-1,3-Dichloropropene	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
trans-1,4-dichloro-2-butene	ND	11	ug/Kg	05/15/13	R/J	SW8260	
Trichloroethene	64	5.3	ug/Kg	05/15/13	R/J	SW8260	
Trichlorofluoromethane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Trichlorotrifluoroethane	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
Vinyl chloride	ND	5.3	ug/Kg	05/15/13	R/J	SW8260	
QA/QC Surrogates							
% 1,2-dichlorobenzene-d4	103		%	05/15/13	R/J	70 - 130 %	
% Bromofluorobenzene	97		%	05/15/13	R/J	70 - 130 %	

Project ID: 4416-4418 PURVES ST. Phoenix I.D.: BD71474
Client ID: B3 12-15

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
% Dibromofluoromethane	101		%	05/15/13	R/J	70 - 130 %
% Toluene-d8	92		%	05/15/13	R/J	70 - 130 %
Semivolatiles-STARS/CP-51						
Acenaphthene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Acenaphthylene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Anthracene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benz(a)anthracene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benzo(a)pyrene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benzo(b)fluoranthene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benzo(ghi)perylene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benzo(k)fluoranthene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Chrysene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Dibenz(a,h)anthracene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Fluoranthene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Fluorene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Indeno(1,2,3-cd)pyrene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Naphthalene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Phenanthrene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Pyrene	ND	270	ug/Kg	05/16/13	DD	SW 8270
QA/QC Surrogates						
% 2-Fluorobiphenyl	87		%	05/16/13	DD	30 - 130 %
% Nitrobenzene-d5	86		%	05/16/13	DD	30 - 130 %
% Terphenyl-d14	96		%	05/16/13	DD	30 - 130 %

1 = This parameter is not certified by NY NELAC for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quanitation) ND=Not Detected BRL=Below Reporting Level

Comments:

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.
This report must not be reproduced except in full as defined by the attached chain of custody.



Phyllis Shiller, Laboratory Director
May 20, 2013
Reviewed and Released by: Greg Lawrence, Assistant Lab Director

PHOENIX
Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

Analysis Report

May 20, 2013

FOR: Attn: Mr. Charles B. Sosik, P.G.
Environmental Business Consultants
1808 Middle Country Rd
Ridge NY 11961-2406

Sample Information		Custody Information		Date	Time
Matrix:	SOIL	Collected by:		05/10/13	0:00
Location Code:	EBC	Received by:	LB	05/13/13	17:14
Rush Request:	72 Hour	Analyzed by:	see "By" below		
P.O.#:					

Laboratory Data

SDG ID: GBD71472
Phoenix ID: BD71475

Project ID: 4416-4418 PURVES ST.
Client ID: B4 12-15

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
Percent Solid	85		%	05/13/13	JL	E160.3
Soil Extraction SVOA PAH	Completed			05/13/13	BJ/V	SW3545
Field Extraction	Completed			05/10/13		SW5035
Volatiles						
1,1,1,2-Tetrachloroethane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
1,1,1-Trichloroethane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
1,1,2,2-Tetrachloroethane	ND	3.3	ug/Kg	05/15/13	R/J	SW8260
1,1,2-Trichloroethane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
1,1-Dichloroethane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
1,1-Dichloroethene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
1,1-Dichloropropene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
1,2,3-Trichlorobenzene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
1,2,3-Trichloropropane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
1,2,4-Trichlorobenzene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
1,2,4-Trimethylbenzene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
1,2-Dibromo-3-chloropropane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
1,2-Dibromoethane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
1,2-Dichlorobenzene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
1,2-Dichloroethane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
1,2-Dichloropropane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
1,3,5-Trimethylbenzene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
1,3-Dichlorobenzene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
1,3-Dichloropropane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
1,4-Dichlorobenzene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
2,2-Dichloropropane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
2-Chlorotoluene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260
2-Hexanone	ND	27	ug/Kg	05/15/13	R/J	SW8260
2-Isopropyltoluene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
4-Chlorotoluene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
4-Methyl-2-pentanone	ND	27	ug/Kg	05/15/13	R/J	SW8260	
Acetone	ND	27	ug/Kg	05/15/13	R/J	SW8260	
Acrylonitrile	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Benzene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Bromobenzene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Bromochloromethane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Bromodichloromethane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Bromoform	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Bromomethane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Carbon Disulfide	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Carbon tetrachloride	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Chlorobenzene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Chloroethane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Chloroform	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Chloromethane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
cis-1,2-Dichloroethene	12	5.5	ug/Kg	05/15/13	R/J	SW8260	
cis-1,3-Dichloropropene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	1
Dibromochloromethane	ND	3.3	ug/Kg	05/15/13	R/J	SW8260	
Dibromomethane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Dichlorodifluoromethane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Ethylbenzene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Hexachlorobutadiene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Isopropylbenzene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
m&p-Xylene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Methyl Ethyl Ketone	ND	33	ug/Kg	05/15/13	R/J	SW8260	
Methyl t-butyl ether (MTBE)	ND	11	ug/Kg	05/15/13	R/J	SW8260	
Methylene chloride	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Naphthalene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
n-Butylbenzene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
n-Propylbenzene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
o-Xylene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
p-Isopropyltoluene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
sec-Butylbenzene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Styrene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
tert-Butylbenzene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Tetrachloroethene	92	5.5	ug/Kg	05/15/13	R/J	SW8260	
Tetrahydrofuran (THF)	ND	11	ug/Kg	05/15/13	R/J	SW8260	1
Toluene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Total Xylenes	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
trans-1,2-Dichloroethene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
trans-1,3-Dichloropropene	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
trans-1,4-dichloro-2-butene	ND	11	ug/Kg	05/15/13	R/J	SW8260	
Trichloroethene	11	5.5	ug/Kg	05/15/13	R/J	SW8260	
Trichlorofluoromethane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Trichlorotrifluoroethane	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
Vinyl chloride	ND	5.5	ug/Kg	05/15/13	R/J	SW8260	
QA/QC Surrogates							
% 1,2-dichlorobenzene-d4	102		%	05/15/13	R/J	70 - 130 %	
% Bromofluorobenzene	92		%	05/15/13	R/J	70 - 130 %	

Project ID: 4416-4418 PURVES ST.
Client ID: B4 12-15

Phoenix I.D.: BD71475

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
% Dibromofluoromethane	98		%	05/15/13	R/J	70 - 130 %
% Toluene-d8	93		%	05/15/13	R/J	70 - 130 %
Semivolatiles-STARS/CP-51						
Acenaphthene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Acenaphthylene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Anthracene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benz(a)anthracene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benzo(a)pyrene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benzo(b)fluoranthene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benzo(ghi)perylene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Benzo(k)fluoranthene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Chrysene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Dibenz(a,h)anthracene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Fluoranthene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Fluorene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Indeno(1,2,3-cd)pyrene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Naphthalene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Phenanthrene	ND	270	ug/Kg	05/16/13	DD	SW 8270
Pyrene	ND	270	ug/Kg	05/16/13	DD	SW 8270
QA/QC Surrogates						
% 2-Fluorobiphenyl	90		%	05/16/13	DD	30 - 130 %
% Nitrobenzene-d5	89		%	05/16/13	DD	30 - 130 %
% Terphenyl-d14	107		%	05/16/13	DD	30 - 130 %

1 = This parameter is not certified by NY NELAC for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quanitation) ND=Not Detected BRL=Below Reporting Level

Comments:

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.
This report must not be reproduced except in full as defined by the attached chain of custody.



Phyllis Shiller, Laboratory Director
May 20, 2013
Reviewed and Released by: Greg Lawrence, Assistant Lab Director

PHOENIX

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

Analysis Report

May 20, 2013

FOR: Attn: Mr. Charles B. Sosik, P.G.
Environmental Business Consultants
1808 Middle Country Rd
Ridge NY 11961-2406

Sample Information		Custody Information		Date	Time
Matrix:	GROUND WATER	Collected by:		05/10/13	0:00
Location Code:	EBC	Received by:	LB	05/13/13	17:14
Rush Request:	72 Hour	Analyzed by:	see "By" below		
P.O.#:					

Laboratory Data

SDG ID: GBD71472
Phoenix ID: BD71476

Project ID: 4416-4418 PURVES ST.
Client ID: GW1

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
Volatiles							
1,1,1,2-Tetrachloroethane	ND	1.0	ug/L	05/16/13	R/T	SW8260	
1,1,1-Trichloroethane	ND	1.0	ug/L	05/16/13	R/T	SW8260	
1,1,2,2-Tetrachloroethane	ND	0.50	ug/L	05/16/13	R/T	SW8260	
1,1,2-Trichloroethane	ND	1.0	ug/L	05/16/13	R/T	SW8260	
1,1-Dichloroethane	ND	1.0	ug/L	05/16/13	R/T	SW8260	
1,1-Dichloroethene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
1,1-Dichloropropene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
1,2,3-Trichlorobenzene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
1,2,3-Trichloropropane	ND	1.0	ug/L	05/16/13	R/T	SW8260	
1,2,4-Trichlorobenzene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
1,2,4-Trimethylbenzene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
1,2-Dibromo-3-chloropropane	ND	1.0	ug/L	05/16/13	R/T	SW8260	
1,2-Dibromoethane	ND	1.0	ug/L	05/16/13	R/T	SW8260	
1,2-Dichlorobenzene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
1,2-Dichloroethane	ND	0.60	ug/L	05/16/13	R/T	SW8260	
1,2-Dichloropropane	ND	1.0	ug/L	05/16/13	R/T	SW8260	
1,3,5-Trimethylbenzene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
1,3-Dichlorobenzene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
1,3-Dichloropropane	ND	1.0	ug/L	05/16/13	R/T	SW8260	
1,4-Dichlorobenzene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
2,2-Dichloropropane	ND	1.0	ug/L	05/16/13	R/T	SW8260	
2-Chlorotoluene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
2-Hexanone	ND	5.0	ug/L	05/16/13	R/T	SW8260	
2-Isopropyltoluene	ND	1.0	ug/L	05/16/13	R/T	SW8260	1
4-Chlorotoluene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
4-Methyl-2-pentanone	ND	5.0	ug/L	05/16/13	R/T	SW8260	
Acetone	ND	25	ug/L	05/16/13	R/T	SW8260	

Project ID: 4416-4418 PURVES ST. Phoenix I.D.: BD71476

Client ID: GW1

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
Acrylonitrile	ND	5.0	ug/L	05/16/13	R/T	SW8260	
Benzene	ND	0.70	ug/L	05/16/13	R/T	SW8260	
Bromobenzene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
Bromochloromethane	ND	1.0	ug/L	05/16/13	R/T	SW8260	
Bromodichloromethane	ND	0.50	ug/L	05/16/13	R/T	SW8260	
Bromoform	ND	1.0	ug/L	05/16/13	R/T	SW8260	
Bromomethane	ND	1.0	ug/L	05/16/13	R/T	SW8260	
Carbon Disulfide	ND	5.0	ug/L	05/16/13	R/T	SW8260	
Carbon tetrachloride	ND	1.0	ug/L	05/16/13	R/T	SW8260	
Chlorobenzene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
Chloroethane	ND	1.0	ug/L	05/16/13	R/T	SW8260	
Chloroform	ND	1.0	ug/L	05/16/13	R/T	SW8260	
Chloromethane	ND	1.0	ug/L	05/16/13	R/T	SW8260	
cis-1,2-Dichloroethene	4.2	1.0	ug/L	05/16/13	R/T	SW8260	
cis-1,3-Dichloropropene	ND	0.50	ug/L	05/16/13	R/T	SW8260	1
Dibromochloromethane	ND	0.50	ug/L	05/16/13	R/T	SW8260	
Dibromomethane	ND	1.0	ug/L	05/16/13	R/T	SW8260	
Dichlorodifluoromethane	ND	1.0	ug/L	05/16/13	R/T	SW8260	
Ethylbenzene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
Hexachlorobutadiene	ND	0.40	ug/L	05/16/13	R/T	SW8260	
Isopropylbenzene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
m&p-Xylene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
Methyl ethyl ketone	ND	5.0	ug/L	05/16/13	R/T	SW8260	
Methyl t-butyl ether (MTBE)	ND	1.0	ug/L	05/16/13	R/T	SW8260	
Methylene chloride	ND	1.0	ug/L	05/16/13	R/T	SW8260	
Naphthalene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
n-Butylbenzene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
n-Propylbenzene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
o-Xylene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
p-Isopropyltoluene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
sec-Butylbenzene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
Styrene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
tert-Butylbenzene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
Tetrachloroethene	19	1.0	ug/L	05/16/13	R/T	SW8260	
Tetrahydrofuran (THF)	ND	2.5	ug/L	05/16/13	R/T	SW8260	1
Toluene	1.8	1.0	ug/L	05/16/13	R/T	SW8260	
Total Xylenes	ND	1.0	ug/L	05/16/13	R/T	SW8260	
trans-1,2-Dichloroethene	ND	1.0	ug/L	05/16/13	R/T	SW8260	
trans-1,3-Dichloropropene	ND	0.50	ug/L	05/16/13	R/T	SW8260	
trans-1,4-dichloro-2-butene	ND	5.0	ug/L	05/16/13	R/T	SW8260	
Trichloroethene	3.2	1.0	ug/L	05/16/13	R/T	SW8260	
Trichlorofluoromethane	ND	1.0	ug/L	05/16/13	R/T	SW8260	
Trichlorotrifluoroethane	ND	1.0	ug/L	05/16/13	R/T	SW8260	
Vinyl chloride	ND	1.0	ug/L	05/16/13	R/T	SW8260	
QA/QC Surrogates							
% 1,2-dichlorobenzene-d4	101		%	05/16/13	R/T	70 - 130 %	
% Bromofluorobenzene	85		%	05/16/13	R/T	70 - 130 %	
% Dibromofluoromethane	98		%	05/16/13	R/T	70 - 130 %	
% Toluene-d8	92		%	05/16/13	R/T	70 - 130 %	

Project ID: 4416-4418 PURVES ST. Phoenix I.D.: BD71476
Client ID: GW1

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference

1 = This parameter is not certified by NY NELAC for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quanitation) ND=Not Detected BRL=Below Reporting Level

Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.
This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director
May 20, 2013
Reviewed and Released by: Greg Lawrence, Assistant Lab Director

PHOENIX

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

Analysis Report

May 20, 2013

FOR: Attn: Mr. Charles B. Sosik, P.G.
Environmental Business Consultants
1808 Middle Country Rd
Ridge NY 11961-2406

Sample Information		Custody Information		Date	Time
Matrix:	GROUND WATER	Collected by:		05/10/13	0:00
Location Code:	EBC	Received by:	LB	05/13/13	17:14
Rush Request:	72 Hour	Analyzed by:	see "By" below		
P.O.#:					

Laboratory Data

SDG ID: GBD71472
Phoenix ID: BD71477

Project ID: 4416-4418 PURVES ST.
Client ID: GW3

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
Volatiles							
1,1,1,2-Tetrachloroethane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
1,1,1-Trichloroethane	18	1.0	ug/L	05/15/13	R/T	SW8260	
1,1,2,2-Tetrachloroethane	ND	0.50	ug/L	05/15/13	R/T	SW8260	
1,1,2-Trichloroethane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
1,1-Dichloroethane	1.7	1.0	ug/L	05/15/13	R/T	SW8260	
1,1-Dichloroethene	1.4	1.0	ug/L	05/15/13	R/T	SW8260	
1,1-Dichloropropene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
1,2,3-Trichlorobenzene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
1,2,3-Trichloropropane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
1,2,4-Trichlorobenzene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
1,2,4-Trimethylbenzene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
1,2-Dibromo-3-chloropropane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
1,2-Dibromoethane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
1,2-Dichlorobenzene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
1,2-Dichloroethane	ND	0.60	ug/L	05/15/13	R/T	SW8260	
1,2-Dichloropropane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
1,3,5-Trimethylbenzene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
1,3-Dichlorobenzene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
1,3-Dichloropropane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
1,4-Dichlorobenzene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
2,2-Dichloropropane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
2-Chlorotoluene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
2-Hexanone	ND	5.0	ug/L	05/15/13	R/T	SW8260	
2-Isopropyltoluene	ND	1.0	ug/L	05/15/13	R/T	SW8260	1
4-Chlorotoluene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
4-Methyl-2-pentanone	ND	5.0	ug/L	05/15/13	R/T	SW8260	
Acetone	ND	25	ug/L	05/15/13	R/T	SW8260	

Project ID: 4416-4418 PURVES ST. Phoenix I.D.: BD71477

Client ID: GW3

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
Acrylonitrile	ND	5.0	ug/L	05/15/13	R/T	SW8260	
Benzene	ND	0.70	ug/L	05/15/13	R/T	SW8260	
Bromobenzene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Bromochloromethane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Bromodichloromethane	ND	0.50	ug/L	05/15/13	R/T	SW8260	
Bromoform	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Bromomethane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Carbon Disulfide	ND	5.0	ug/L	05/15/13	R/T	SW8260	
Carbon tetrachloride	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Chlorobenzene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Chloroethane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Chloroform	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Chloromethane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
cis-1,2-Dichloroethene	190	10.0	ug/L	05/15/13	R/T	SW8260	
cis-1,3-Dichloropropene	ND	0.50	ug/L	05/15/13	R/T	SW8260	1
Dibromochloromethane	ND	0.50	ug/L	05/15/13	R/T	SW8260	
Dibromomethane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Dichlorodifluoromethane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Ethylbenzene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Hexachlorobutadiene	ND	0.40	ug/L	05/15/13	R/T	SW8260	
Isopropylbenzene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
m&p-Xylene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Methyl ethyl ketone	ND	5.0	ug/L	05/15/13	R/T	SW8260	
Methyl t-butyl ether (MTBE)	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Methylene chloride	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Naphthalene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
n-Butylbenzene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
n-Propylbenzene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
o-Xylene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
p-Isopropyltoluene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
sec-Butylbenzene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Styrene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
tert-Butylbenzene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Tetrachloroethene	950	50.0	ug/L	05/15/13	R/T	SW8260	
Tetrahydrofuran (THF)	ND	2.5	ug/L	05/15/13	R/T	SW8260	1
Toluene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Total Xylenes	ND	1.0	ug/L	05/15/13	R/T	SW8260	
trans-1,2-Dichloroethene	6.6	1.0	ug/L	05/15/13	R/T	SW8260	
trans-1,3-Dichloropropene	ND	0.50	ug/L	05/15/13	R/T	SW8260	
trans-1,4-dichloro-2-butene	ND	5.0	ug/L	05/15/13	R/T	SW8260	
Trichloroethene	150	10.0	ug/L	05/15/13	R/T	SW8260	
Trichlorofluoromethane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Trichlorotrifluoroethane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Vinyl chloride	5.6	1.0	ug/L	05/15/13	R/T	SW8260	
QA/QC Surrogates							
% 1,2-dichlorobenzene-d4	101		%	05/15/13	R/T	70 - 130 %	
% Bromofluorobenzene	82		%	05/15/13	R/T	70 - 130 %	
% Dibromofluoromethane	98		%	05/15/13	R/T	70 - 130 %	
% Toluene-d8	96		%	05/15/13	R/T	70 - 130 %	


Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference

1 = This parameter is not certified by NY NELAC for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quanitation) ND=Not Detected BRL=Below Reporting Level

Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.
This report must not be reproduced except in full as defined by the attached chain of custody.



Phyllis Shiller, Laboratory Director
May 20, 2013
Reviewed and Released by: Greg Lawrence, Assistant Lab Director

PHOENIX

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

Analysis Report

May 20, 2013

FOR: Attn: Mr. Charles B. Sosik, P.G.
Environmental Business Consultants
1808 Middle Country Rd
Ridge NY 11961-2406

Sample Information		Custody Information		Date	Time
Matrix:	GROUND WATER	Collected by:		05/10/13	0:00
Location Code:	EBC	Received by:	LB	05/13/13	17:14
Rush Request:	72 Hour	Analyzed by:	see "By" below		
P.O.#:					

Laboratory Data

SDG ID: GBD71472
Phoenix ID: BD71478

Project ID: 4416-4418 PURVES ST.
Client ID: GW4

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
Volatiles							
1,1,1,2-Tetrachloroethane	ND	2.0	ug/L	05/15/13	R/T	SW8260	
1,1,1-Trichloroethane	15	2.0	ug/L	05/15/13	R/T	SW8260	
1,1,2,2-Tetrachloroethane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
1,1,2-Trichloroethane	ND	2.0	ug/L	05/15/13	R/T	SW8260	
1,1-Dichloroethane	3.1	2.0	ug/L	05/15/13	R/T	SW8260	
1,1-Dichloroethene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
1,1-Dichloropropene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
1,2,3-Trichlorobenzene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
1,2,3-Trichloropropane	ND	2.0	ug/L	05/15/13	R/T	SW8260	
1,2,4-Trichlorobenzene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
1,2,4-Trimethylbenzene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
1,2-Dibromo-3-chloropropane	ND	2.0	ug/L	05/15/13	R/T	SW8260	
1,2-Dibromoethane	ND	2.0	ug/L	05/15/13	R/T	SW8260	
1,2-Dichlorobenzene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
1,2-Dichloroethane	ND	1.2	ug/L	05/15/13	R/T	SW8260	
1,2-Dichloropropane	ND	2.0	ug/L	05/15/13	R/T	SW8260	
1,3,5-Trimethylbenzene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
1,3-Dichlorobenzene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
1,3-Dichloropropane	ND	2.0	ug/L	05/15/13	R/T	SW8260	
1,4-Dichlorobenzene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
2,2-Dichloropropane	ND	2.0	ug/L	05/15/13	R/T	SW8260	
2-Chlorotoluene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
2-Hexanone	ND	10	ug/L	05/15/13	R/T	SW8260	
2-Isopropyltoluene	ND	2.0	ug/L	05/15/13	R/T	SW8260	1
4-Chlorotoluene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
4-Methyl-2-pentanone	ND	10	ug/L	05/15/13	R/T	SW8260	
Acetone	ND	50	ug/L	05/15/13	R/T	SW8260	

Project ID: 4416-4418 PURVES ST.
Client ID: GW4

Phoenix I.D.: BD71478

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
Acrylonitrile	ND	10	ug/L	05/15/13	R/T	SW8260	
Benzene	ND	1.4	ug/L	05/15/13	R/T	SW8260	
Bromobenzene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Bromochloromethane	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Bromodichloromethane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Bromoform	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Bromomethane	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Carbon Disulfide	ND	10	ug/L	05/15/13	R/T	SW8260	
Carbon tetrachloride	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Chlorobenzene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Chloroethane	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Chloroform	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Chloromethane	ND	2.0	ug/L	05/15/13	R/T	SW8260	
cis-1,2-Dichloroethene	130	20.0	ug/L	05/15/13	R/T	SW8260	
cis-1,3-Dichloropropene	ND	1.0	ug/L	05/15/13	R/T	SW8260	1
Dibromochloromethane	ND	1.0	ug/L	05/15/13	R/T	SW8260	
Dibromomethane	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Dichlorodifluoromethane	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Ethylbenzene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Hexachlorobutadiene	ND	0.80	ug/L	05/15/13	R/T	SW8260	
Isopropylbenzene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
m&p-Xylene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Methyl ethyl ketone	ND	10	ug/L	05/15/13	R/T	SW8260	
Methyl t-butyl ether (MTBE)	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Methylene chloride	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Naphthalene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
n-Butylbenzene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
n-Propylbenzene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
o-Xylene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
p-Isopropyltoluene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
sec-Butylbenzene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Styrene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
tert-Butylbenzene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Tetrachloroethene	610	20.0	ug/L	05/15/13	R/T	SW8260	
Tetrahydrofuran (THF)	ND	5.0	ug/L	05/15/13	R/T	SW8260	1
Toluene	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Total Xylenes	ND	2.0	ug/L	05/15/13	R/T	SW8260	
trans-1,2-Dichloroethene	14	2.0	ug/L	05/15/13	R/T	SW8260	
trans-1,3-Dichloropropene	ND	1.0	ug/L	05/15/13	R/T	SW8260	
trans-1,4-dichloro-2-butene	ND	10	ug/L	05/15/13	R/T	SW8260	
Trichloroethene	90	20.0	ug/L	05/15/13	R/T	SW8260	
Trichlorofluoromethane	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Trichlorotrifluoroethane	ND	2.0	ug/L	05/15/13	R/T	SW8260	
Vinyl chloride	5.1	2.0	ug/L	05/15/13	R/T	SW8260	
QA/QC Surrogates							
% 1,2-dichlorobenzene-d4	100		%	05/15/13	R/T	70 - 130 %	
% Bromofluorobenzene	82		%	05/15/13	R/T	70 - 130 %	
% Dibromofluoromethane	98		%	05/15/13	R/T	70 - 130 %	
% Toluene-d8	87		%	05/15/13	R/T	70 - 130 %	

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference

1 = This parameter is not certified by NY NELAC for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quanitation) ND=Not Detected BRL=Below Reporting Level

Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.
This report must not be reproduced except in full as defined by the attached chain of custody.



Phyllis Shiller, Laboratory Director
May 20, 2013
Reviewed and Released by: Greg Lawrence, Assistant Lab Director

PHOENIX

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

QA/QC Report

May 20, 2013

QA/QC Data

SDG I.D.: GBD71472

Parameter	Blank	LCS %	LCSD %	LCS RPD	MS %	MSD %	MS RPD	% Rec Limits	% RPD Limits	
QA/QC Batch 230739, QC Sample No: BD71313 (BD71474 (45X))										
Volatiles - Soil										
Tetrachloroethene	ND	106	100	5.8	103	93	10.2	70 - 130	30	
Comment:										
Additional 8260 criteria: 10% of compounds can be outside of acceptance criteria as long as recovery is 40-160%.										
QA/QC Batch 230307, QC Sample No: BD71443 (BD71472, BD71473, BD71474, BD71475)										
Polynuclear Aromatic HC - Soil										
Acenaphthene	ND	88	88	0.0	91	93	2.2	30 - 130	30	
Acenaphthylene	ND	86	86	0.0	92	92	0.0	30 - 130	30	
Anthracene	ND	91	91	0.0	94	92	2.2	30 - 130	30	
Benz(a)anthracene	ND	87	88	1.1	89	90	1.1	30 - 130	30	
Benzo(a)pyrene	ND	84	85	1.2	84	86	2.4	30 - 130	30	
Benzo(b)fluoranthene	ND	96	96	0.0	98	102	4.0	30 - 130	30	
Benzo(ghi)perylene	ND	81	81	0.0	96	87	9.8	30 - 130	30	
Benzo(k)fluoranthene	ND	98	101	3.0	90	95	5.4	30 - 130	30	
Chrysene	ND	88	88	0.0	92	91	1.1	30 - 130	30	
Dibenz(a,h)anthracene	ND	80	80	0.0	99	91	8.4	30 - 130	30	
Fluoranthene	ND	91	92	1.1	95	94	1.1	30 - 130	30	
Fluorene	ND	90	90	0.0	94	94	0.0	30 - 130	30	
Indeno(1,2,3-cd)pyrene	ND	82	82	0.0	82	74	10.3	30 - 130	30	
Naphthalene	ND	86	81	6.0	87	88	1.1	30 - 130	30	
Phenanthrene	ND	92	94	2.2	96	95	1.0	30 - 130	30	
Pyrene	ND	88	90	2.2	94	92	2.2	30 - 130	30	
% 2-Fluorobiphenyl	89	88	85	3.5	87	86	1.2	30 - 130	30	
% Nitrobenzene-d5	90	79	75	5.2	85	86	1.2	30 - 130	30	
% Terphenyl-d14	96	96	96	0.0	94	93	1.1	30 - 130	30	
Comment:										
Additional 8270 criteria: 20% of compounds can be outside of acceptance criteria as long as recovery is at least 10%. (Acid surrogates acceptance range for aqueous samples: 15-110%, for soils 30-130%)										
QA/QC Batch 230521, QC Sample No: BD71482 (BD71472, BD71473, BD71474, BD71475)										
Volatiles - Soil										
1,1,1,2-Tetrachloroethane	ND	112	108	3.6	103	112	8.4	70 - 130	30	
1,1,1-Trichloroethane	ND	94	89	5.5	90	97	7.5	70 - 130	30	
1,1,2,2-Tetrachloroethane	ND	96	94	2.1	<40	<40	NC	70 - 130	30	m
1,1,2-Trichloroethane	ND	97	101	4.0	90	89	1.1	70 - 130	30	
1,1-Dichloroethane	ND	95	92	3.2	91	95	4.3	70 - 130	30	
1,1-Dichloroethene	ND	91	85	6.8	91	97	6.4	70 - 130	30	
1,1-Dichloropropene	ND	101	94	7.2	94	105	11.1	70 - 130	30	
1,2,3-Trichlorobenzene	ND	92	103	11.3	78	80	2.5	70 - 130	30	
1,2,3-Trichloropropane	ND	98	88	10.8	90	92	2.2	70 - 130	30	
1,2,4-Trichlorobenzene	ND	89	97	8.6	77	81	5.1	70 - 130	30	
1,2,4-Trimethylbenzene	ND	93	89	4.4	86	96	11.0	70 - 130	30	

QA/QC Data

SDG I.D.: GBD71472

Parameter	Blank	LCS %	LCSD %	LCS RPD	MS %	MSD %	MS RPD	% Rec Limits	% RPD Limits
1,2-Dibromo-3-chloropropane	ND	120	130	8.0	112	112	0.0	70 - 130	30
1,2-Dibromoethane	ND	98	104	5.9	94	92	2.2	70 - 130	30
1,2-Dichlorobenzene	ND	95	94	1.1	87	95	8.8	70 - 130	30
1,2-Dichloroethane	ND	98	100	2.0	95	96	1.0	70 - 130	30
1,2-Dichloropropane	ND	97	96	1.0	92	96	4.3	70 - 130	30
1,3,5-Trimethylbenzene	ND	94	86	8.9	87	99	12.9	70 - 130	30
1,3-Dichlorobenzene	ND	96	92	4.3	86	96	11.0	70 - 130	30
1,3-Dichloropropane	ND	99	99	0.0	95	97	2.1	70 - 130	30
1,4-Dichlorobenzene	ND	92	90	2.2	84	91	8.0	70 - 130	30
2,2-Dichloropropane	ND	96	92	4.3	88	94	6.6	70 - 130	30
2-Chlorotoluene	ND	104	95	9.0	95	108	12.8	70 - 130	30
2-Hexanone	ND	77	86	11.0	101	97	4.0	70 - 130	30
2-Isopropyltoluene	ND	97	93	4.2	93	104	11.2	70 - 130	30
4-Chlorotoluene	ND	97	91	6.4	92	103	11.3	70 - 130	30
4-Methyl-2-pentanone	ND	92	103	11.3	99	92	7.3	70 - 130	30
Acetone	ND	64	71	10.4	112	96	15.4	70 - 130	30
Acrylonitrile	ND	93	102	9.2	100	89	11.6	70 - 130	30
Benzene	ND	91	87	4.5	87	94	7.7	70 - 130	30
Bromobenzene	ND	106	100	5.8	99	109	9.6	70 - 130	30
Bromochloromethane	ND	104	103	1.0	101	100	1.0	70 - 130	30
Bromodichloromethane	ND	92	92	0.0	87	90	3.4	70 - 130	30
Bromoform	ND	112	116	3.5	106	108	1.9	70 - 130	30
Bromomethane	ND	99	89	10.6	89	106	17.4	70 - 130	30
Carbon Disulfide	ND	83	77	7.5	83	91	9.2	70 - 130	30
Carbon tetrachloride	ND	108	103	4.7	100	114	13.1	70 - 130	30
Chlorobenzene	ND	102	98	4.0	94	103	9.1	70 - 130	30
Chloroethane	ND	94	87	7.7	93	100	7.3	70 - 130	30
Chloroform	ND	88	85	3.5	84	88	4.7	70 - 130	30
Chloromethane	ND	97	95	2.1	105	106	0.9	70 - 130	30
cis-1,2-Dichloroethene	ND	94	95	1.1	92	91	1.1	70 - 130	30
cis-1,3-Dichloropropene	ND	96	98	2.1	89	91	2.2	70 - 130	30
Dibromochloromethane	ND	111	110	0.9	104	109	4.7	70 - 130	30
Dibromomethane	ND	97	102	5.0	96	94	2.1	70 - 130	30
Dichlorodifluoromethane	ND	106	102	3.8	112	115	2.6	70 - 130	30
Ethylbenzene	ND	95	89	6.5	90	100	10.5	70 - 130	30
Hexachlorobutadiene	ND	80	91	12.9	90	100	10.5	70 - 130	30
Isopropylbenzene	ND	105	94	11.1	97	113	15.2	70 - 130	30
m&p-Xylene	ND	95	90	5.4	91	99	8.4	70 - 130	30
Methyl ethyl ketone	ND	64	76	17.1	97	84	14.4	70 - 130	30
Methyl t-butyl ether (MTBE)	ND	85	87	2.3	86	84	2.4	70 - 130	30
Methylene chloride	ND	78	77	1.3	80	80	0.0	70 - 130	30
Naphthalene	ND	102	122	17.9	90	89	1.1	70 - 130	30
n-Butylbenzene	ND	80	79	1.3	80	90	11.8	70 - 130	30
n-Propylbenzene	ND	103	94	9.1	94	109	14.8	70 - 130	30
o-Xylene	ND	97	94	3.1	91	99	8.4	70 - 130	30
p-Isopropyltoluene	ND	99	94	5.2	93	106	13.1	70 - 130	30
sec-Butylbenzene	ND	90	83	8.1	87	100	13.9	70 - 130	30
Styrene	ND	90	88	2.2	88	93	5.5	70 - 130	30
tert-Butylbenzene	ND	103	94	9.1	96	109	12.7	70 - 130	30
Tetrachloroethene	ND	109	99	9.6	101	114	12.1	70 - 130	30
Tetrahydrofuran (THF)	ND	87	97	10.9	93	82	12.6	70 - 130	30
Toluene	ND	92	90	2.2	88	94	6.6	70 - 130	30
trans-1,2-Dichloroethene	ND	86	81	6.0	82	87	5.9	70 - 130	30

Parameter	Blank	LCS %	LCSD %	LCS RPD	MS %	MSD %	MS RPD	% Rec Limits	% RPD Limits	
trans-1,3-Dichloropropene	ND	94	97	3.1	90	87	3.4	70 - 130	30	
trans-1,4-dichloro-2-butene	ND	97	107	9.8	99	96	3.1	70 - 130	30	
Trichloroethene	ND	106	101	4.8	>150	>150	NC	70 - 130	30	m
Trichlorofluoromethane	ND	97	90	7.5	93	102	9.2	70 - 130	30	
Trichlorotrifluoroethane	ND	103	96	7.0	105	111	5.6	70 - 130	30	
Vinyl chloride	ND	105	101	3.9	107	112	4.6	70 - 130	30	
% 1,2-dichlorobenzene-d4	102	100	102	2.0	102	102	0.0	70 - 130	30	
% Bromofluorobenzene	94	95	97	2.1	96	94	2.1	70 - 130	30	
% Dibromofluoromethane	97	96	100	4.1	97	93	4.2	70 - 130	30	
% Toluene-d8	96	94	95	1.1	93	92	1.1	70 - 130	30	

Comment:

Additional 8260 criteria: 10% of compounds can be outside of acceptance criteria as long as recovery is 40-160%.

QA/QC Batch 230757, QC Sample No: BD71493 (BD71476, BD71477 (50, 10X) , BD71478 (20X))

Volatiles - Ground Water

1,1,1,2-Tetrachloroethane	ND	94	91	3.2	94	91	3.2	70 - 130	30	
1,1,1-Trichloroethane	ND	85	83	2.4	97	83	15.6	70 - 130	30	
1,1,2,2-Tetrachloroethane	ND	103	108	4.7	117	112	4.4	70 - 130	30	
1,1,2-Trichloroethane	ND	95	95	0.0	106	108	1.9	70 - 130	30	
1,1-Dichloroethane	ND	106	109	2.8	111	105	5.6	70 - 130	30	
1,1-Dichloroethene	ND	103	107	3.8	117	102	13.7	70 - 130	30	
1,1-Dichloropropene	ND	95	98	3.1	112	110	1.8	70 - 130	30	
1,2,3-Trichlorobenzene	ND	102	112	9.3	116	119	2.6	70 - 130	30	
1,2,3-Trichloropropane	ND	97	100	3.0	107	101	5.8	70 - 130	30	
1,2,4-Trichlorobenzene	ND	98	101	3.0	108	111	2.7	70 - 130	30	
1,2,4-Trimethylbenzene	ND	100	100	0.0	112	108	3.6	70 - 130	30	
1,2-Dibromo-3-chloropropane	ND	100	104	3.9	114	112	1.8	70 - 130	30	
1,2-Dibromoethane	ND	89	91	2.2	102	105	2.9	70 - 130	30	
1,2-Dichlorobenzene	ND	98	98	0.0	103	99	4.0	70 - 130	30	
1,2-Dichloroethane	ND	78	81	3.8	80	84	4.9	70 - 130	30	
1,2-Dichloropropane	ND	98	98	0.0	109	109	0.0	70 - 130	30	
1,3,5-Trimethylbenzene	ND	96	97	1.0	107	104	2.8	70 - 130	30	
1,3-Dichlorobenzene	ND	99	99	0.0	103	100	3.0	70 - 130	30	
1,3-Dichloropropane	ND	107	106	0.9	113	109	3.6	70 - 130	30	
1,4-Dichlorobenzene	ND	98	98	0.0	101	98	3.0	70 - 130	30	
2,2-Dichloropropane	ND	110	107	2.8	120	104	14.3	70 - 130	30	
2-Chlorotoluene	ND	103	104	1.0	110	105	4.7	70 - 130	30	
2-Hexanone	ND	104	103	1.0	119	113	5.2	70 - 130	30	
2-Isopropyltoluene	ND	98	98	0.0	106	103	2.9	70 - 130	30	
4-Chlorotoluene	ND	100	100	0.0	108	105	2.8	70 - 130	30	
4-Methyl-2-pentanone	ND	100	101	1.0	124	123	0.8	70 - 130	30	
Acetone	ND	90	89	1.1	54	41	27.4	70 - 130	30	m
Acrylonitrile	ND	125	132	5.4	141	123	13.6	70 - 130	30	l,m
Benzene	ND	104	110	5.6	113	128	12.4	70 - 130	30	
Bromobenzene	ND	100	100	0.0	106	103	2.9	70 - 130	30	
Bromochloromethane	ND	113	109	3.6	122	107	13.1	70 - 130	30	
Bromodichloromethane	ND	82	83	1.2	92	94	2.2	70 - 130	30	
Bromoform	ND	101	99	2.0	93	90	3.3	70 - 130	30	
Bromomethane	ND	116	117	0.9	90	86	4.5	70 - 130	30	
Carbon Disulfide	ND	104	106	1.9	130	119	8.8	70 - 130	30	
Carbon tetrachloride	ND	73	72	1.4	75	73	2.7	70 - 130	30	
Chlorobenzene	ND	99	100	1.0	103	99	4.0	70 - 130	30	
Chloroethane	ND	112	114	1.8	121	105	14.2	70 - 130	30	

QA/QC Data

SDG I.D.: GBD71472

Parameter	Blank	LCS %	LCSD %	LCS RPD	MS %	MSD %	MS RPD	% Rec Limits	% RPD Limits	
Chloroform	ND	99	95	4.1	110	93	16.7	70 - 130	30	
Chloromethane	ND	97	96	1.0	112	96	15.4	70 - 130	30	
cis-1,2-Dichloroethene	ND	121	122	0.8	130	110	16.7	70 - 130	30	
cis-1,3-Dichloropropene	ND	101	102	1.0	116	118	1.7	70 - 130	30	
Dibromochloromethane	ND	96	97	1.0	96	94	2.1	70 - 130	30	
Dibromomethane	ND	91	93	2.2	99	100	1.0	70 - 130	30	
Dichlorodifluoromethane	ND	82	79	3.7	99	89	10.6	70 - 130	30	
Ethylbenzene	ND	98	97	1.0	106	103	2.9	70 - 130	30	
Hexachlorobutadiene	ND	86	85	1.2	95	95	0.0	70 - 130	30	
Isopropylbenzene	ND	101	101	0.0	113	113	0.0	70 - 130	30	
m&p-Xylene	ND	102	100	2.0	106	102	3.8	70 - 130	30	
Methyl ethyl ketone	ND	98	101	3.0	101	85	17.2	70 - 130	30	
Methyl t-butyl ether (MTBE)	ND	101	97	4.0	135	130	3.8	70 - 130	30	m
Methylene chloride	ND	98	103	5.0	99	86	14.1	70 - 130	30	
Naphthalene	ND	106	108	1.9	140	142	1.4	70 - 130	30	m
n-Butylbenzene	ND	101	99	2.0	105	103	1.9	70 - 130	30	
n-Propylbenzene	ND	104	104	0.0	114	110	3.6	70 - 130	30	
o-Xylene	ND	108	106	1.9	107	103	3.8	70 - 130	30	
p-Isopropyltoluene	ND	99	97	2.0	109	108	0.9	70 - 130	30	
sec-Butylbenzene	ND	96	94	2.1	107	103	3.8	70 - 130	30	
Styrene	ND	106	106	0.0	105	100	4.9	70 - 130	30	
tert-Butylbenzene	ND	95	96	1.0	105	102	2.9	70 - 130	30	
Tetrachloroethene	ND	92	90	2.2	102	103	1.0	70 - 130	30	
Tetrahydrofuran (THF)	ND	117	117	0.0	121	94	25.1	70 - 130	30	
Toluene	ND	91	92	1.1	108	112	3.6	70 - 130	30	
trans-1,2-Dichloroethene	ND	119	115	3.4	116	112	3.5	70 - 130	30	
trans-1,3-Dichloropropene	ND	96	94	2.1	109	110	0.9	70 - 130	30	
trans-1,4-dichloro-2-butene	ND	130	129	0.8	130	129	0.8	70 - 130	30	
Trichloroethene	ND	100	99	1.0	108	107	0.9	70 - 130	30	
Trichlorofluoromethane	ND	78	80	2.5	94	82	13.6	70 - 130	30	
Trichlorotrifluoroethane	ND	92	88	4.4	106	99	6.8	70 - 130	30	
Vinyl chloride	ND	110	108	1.8	116	101	13.8	70 - 130	30	
% 1,2-dichlorobenzene-d4	101	99	100	1.0	100	101	1.0	70 - 130	30	
% Bromofluorobenzene	83	95	95	0.0	89	89	0.0	70 - 130	30	
% Dibromofluoromethane	95	103	99	4.0	103	95	8.1	70 - 130	30	
% Toluene-d8	92	91	93	2.2	99	107	7.8	70 - 130	30	

Comment:

Additional 8260 criteria: 10% of compounds can be outside of acceptance criteria as long as recovery is 40-160%.

QA/QC Batch 230579, QC Sample No: BD78745 (BD71477, BD71478 (2X))

Volatiles - Ground Water

1,1,1,2-Tetrachloroethane	ND	96	95	1.0	103			70 - 130	30	
1,1,1-Trichloroethane	ND	92	85	7.9	103			70 - 130	30	
1,1,2,2-Tetrachloroethane	ND	105	105	0.0	116			70 - 130	30	
1,1,2-Trichloroethane	ND	97	93	4.2	102			70 - 130	30	
1,1-Dichloroethane	ND	101	95	6.1	135			70 - 130	30	m
1,1-Dichloroethene	ND	110	99	10.5	127			70 - 130	30	
1,1-Dichloropropene	ND	93	84	10.2	131			70 - 130	30	m
1,2,3-Trichlorobenzene	ND	108	105	2.8	105			70 - 130	30	
1,2,3-Trichloropropane	ND	99	96	3.1	110			70 - 130	30	
1,2,4-Trichlorobenzene	ND	105	104	1.0	108			70 - 130	30	
1,2,4-Trimethylbenzene	ND	110	106	3.7	118			70 - 130	30	
1,2-Dibromo-3-chloropropane	ND	103	102	1.0	116			70 - 130	30	

QA/QC Data

SDG I.D.: GBD71472

Parameter	Blank	LCS %	LCSD %	LCS RPD	MS %	MSD %	MS RPD	% Rec Limits	% RPD Limits	
1,2-Dibromoethane	ND	91	90	1.1	99			70 - 130	30	
1,2-Dichlorobenzene	ND	102	100	2.0	109			70 - 130	30	
1,2-Dichloroethane	ND	76	72	5.4	98			70 - 130	30	
1,2-Dichloropropane	ND	98	93	5.2	111			70 - 130	30	
1,3,5-Trimethylbenzene	ND	108	103	4.7	117			70 - 130	30	
1,3-Dichlorobenzene	ND	107	103	3.8	112			70 - 130	30	
1,3-Dichloropropane	ND	107	106	0.9	119			70 - 130	30	
1,4-Dichlorobenzene	ND	106	102	3.8	110			70 - 130	30	
2,2-Dichloropropane	ND	>150	135	NC	138			70 - 130	30	l,m
2-Chlorotoluene	ND	113	108	4.5	119			70 - 130	30	
2-Hexanone	ND	100	103	3.0	109			70 - 130	30	
2-Isopropyltoluene	ND	108	102	5.7	120			70 - 130	30	
4-Chlorotoluene	ND	109	105	3.7	120			70 - 130	30	
4-Methyl-2-pentanone	ND	97	93	4.2	110			70 - 130	30	
Acetone	ND	84	83	1.2	104			70 - 130	30	
Acrylonitrile	ND	113	116	2.6	147			70 - 130	30	m
Benzene	ND	98	90	8.5	149			70 - 130	30	m
Bromobenzene	ND	107	105	1.9	114			70 - 130	30	
Bromochloromethane	ND	107	103	3.8	124			70 - 130	30	
Bromodichloromethane	ND	88	83	5.8	95			70 - 130	30	
Bromoform	ND	100	99	1.0	109			70 - 130	30	
Bromomethane	ND	101	98	3.0	96			70 - 130	30	
Carbon Disulfide	ND	104	97	7.0	147			70 - 130	30	m
Carbon tetrachloride	ND	78	73	6.6	95			70 - 130	30	
Chlorobenzene	ND	105	101	3.9	115			70 - 130	30	
Chloroethane	ND	102	98	4.0	144			70 - 130	30	m
Chloroform	ND	97	91	6.4	111			70 - 130	30	
Chloromethane	ND	98	92	6.3	123			70 - 130	30	
cis-1,3-Dichloropropene	ND	110	103	6.6	115			70 - 130	30	
Dibromochloromethane	ND	99	99	0.0	104			70 - 130	30	
Dibromomethane	ND	93	89	4.4	99			70 - 130	30	
Dichlorodifluoromethane	ND	99	91	8.4	99			70 - 130	30	
Ethylbenzene	ND	105	100	4.9	118			70 - 130	30	
Hexachlorobutadiene	ND	97	95	2.1	104			70 - 130	30	
Isopropylbenzene	ND	119	113	5.2	124			70 - 130	30	
m&p-Xylene	ND	106	103	2.9	120			70 - 130	30	
Methyl ethyl ketone	ND	88	86	2.3	125			70 - 130	30	
Methyl t-butyl ether (MTBE)	ND	93	87	6.7	122			70 - 130	30	
Methylene chloride	ND	90	87	3.4	115			70 - 130	30	
Naphthalene	ND	115	113	1.8	111			70 - 130	30	
n-Butylbenzene	ND	112	106	5.5	119			70 - 130	30	
n-Propylbenzene	ND	119	113	5.2	120			70 - 130	30	
o-Xylene	ND	111	107	3.7	122			70 - 130	30	
p-Isopropyltoluene	ND	111	105	5.6	118			70 - 130	30	
sec-Butylbenzene	ND	107	102	4.8	119			70 - 130	30	
Styrene	ND	107	105	1.9	122			70 - 130	30	
tert-Butylbenzene	ND	109	104	4.7	120			70 - 130	30	
Tetrahydrofuran (THF)	ND	105	97	7.9	132			70 - 130	30	m
Toluene	ND	99	93	6.3	110			70 - 130	30	
trans-1,2-Dichloroethene	ND	109	102	6.6	131			70 - 130	30	m
trans-1,3-Dichloropropene	ND	104	98	5.9	109			70 - 130	30	
trans-1,4-dichloro-2-butene	ND	136	137	0.7	141			70 - 130	30	l,m
Trichlorofluoromethane	ND	89	81	9.4	94			70 - 130	30	

QA/QC Data

SDG I.D.: GBD71472

Parameter	Blank	LCS %	LCSD %	LCS RPD	MS %	MSD %	MS RPD	% Rec Limits	% RPD Limits	
Trichlorotrifluoroethane	ND	103	94	9.1	106			70 - 130	30	
Vinyl chloride	ND	107	100	6.8	135			70 - 130	30	m
% 1,2-dichlorobenzene-d4	100	99	99	0.0	100			70 - 130	30	
% Bromofluorobenzene	84	90	91	1.1	97			70 - 130	30	
% Dibromofluoromethane	95	99	100	1.0	99			70 - 130	30	
% Toluene-d8	93	92	91	1.1	90			70 - 130	30	

Comment:

Additional 8260 criteria: 10% of compounds can be outside of acceptance criteria as long as recovery is 40-160%.

I = This parameter is outside laboratory lcs/lcsd specified recovery limits.
m = This parameter is outside laboratory ms/msd specified recovery limits.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

RPD - Relative Percent Difference
LCS - Laboratory Control Sample
LCSD - Laboratory Control Sample Duplicate
MS - Matrix Spike
MS Dup - Matrix Spike Duplicate
NC - No Criteria
Intf - Interference

Phyllis Shiller, Laboratory Director
May 20, 2013

Sample Criteria Exceedences Report

GBD71472 - EBC

Requested Criteria: 375, 375RRS, 375RS

State: NY

SampNo	Acode	Phoenix Analyte	Criteria	Result	RL	Criteria	RL Criteria	Analysis Units

*** No Data to Display ***

Phoenix Laboratories does not assume responsibility for the data contained in this report. It is provided as an additional tool to identify requested criteria exceedences. All efforts are made to ensure the accuracy of the data (obtained from appropriate agencies). A lack of exceedence information does not necessarily suggest conformance to the criteria. It is ultimately the site professional's responsibility to determine appropriate compliance.

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

NY # 11301

NY Temperature Narration

May 20, 2013

SDG I.D.: GBD71472

The samples in this delivery group were received at 4°C.
(Note acceptance criteria is above freezing up to 6°C)

4°C w/ C of R

NY/NJ CHAIN OF CUSTODY RECORD

Temp Pg 1 of 1

PHOENIX *Environmental Laboratories, Inc.*

587 East Middle Turnpike, P.O. Box 370, Manchester, CT 06040
Email: info@phoenixlabs.com Fax (860) 645-0823
Client Services (860) 645-8726

Data Delivery:
☐ Fax #:
☑ Email:

Customer: EBC
Address: 1808 Middle Country Road Ridge, NY 11961

Project: ~~4548 and 4~~ 4416-4418 Purves St
Report to:
Invoice to: EBC

Project P.O:
Phone #: (631) 504 6000
Fax #:

Client Sample - Information - Identification

Sampler's Signature: Date: 5-10-13

Matrix Code:
DW=drinking water WW=wastewater S=soil/solid O=oil
GW=groundwater SL=sludge A=air X=other

Analysis Request

Phoenix Sample #	Customer Sample Identification	Sample Matrix	Date Sampled	Time Sampled	VOCs 8260	cVOCs 8260 CP-51 List	Soil VOA [ ] Methanol [ ] Bisulfate [ ] H2O	GL Soil container 8 oz	GL Soil container 4 oz	40 ml VOA Vial [ ]	GL Amber 1000ml [ ] As is [ ] HCl	PL As is [ ] 250ml [ ] As is [ ] H2SO4	PL H2SO4 [ ] 250ml [ ] 500ml [ ] 1000ml	PL HNO3 250ml [ ] 500ml	PL NaOH 250ml	Bacteria Bottle
71472	B1 (7-10)	S	5-10-13		X	X		2	1	1						
71473	B2 (7-10)	"	"		"	"		"	"	"						
71474	B3 (12-15)	"	"		"	"		"	"	"						
71475	B4 (12-15)	"	"		"	"										
71476	GW1	GW	"		"	"				3						
71477	GW3	"	"		"	"				1						
71478	GW4	"	"		"	"										

Relinquished by:	Accepted by:	Date	Time:
		5-13-13	2:00 P
	Lora Bryda	5-13-13	17:14

Comments, Special Requirements or Regulations:

Turnaround:
☐ 1 Day*
☐ 2 Days*
☐ 3 Days*
☑ 5 Days
☐ 10 Days
☐ Other
* SURCHARGE APPLIES

NJ
☐ Res. Criteria
☐ Non-Res. Criteria
☐ Impact to GW Soil Cleanup Criteria
☐ GW Criteria

NY
☐ TOGS GA GW
☐ CP-51 Soil
☑ NY375 Unrestricted Soil
☑ NY375 Residential Soil
☑ NY375 Restricted Non-Residential Soil

Data Format
☐ Phoenix Std Report
☑ Excel
☑ PDF
☐ GIS/Key
☐ EQuIS
☐ NJ Hazsite EDD
☐ NY EZ EDD (ASP)
☐ Other

Data Package
☐ NJ Reduced Deliv. *
☐ NY Enhanced (ASP B) *
☐ Other

State where samples were collected: NY

PHOENIX
Environmental Laboratories, Inc.

Thursday, May 23, 2013

Attn: Mr. Charles B. Sosik, P.G.
Environmental Business Consultants
1808 Middle Country Rd
Ridge NY 11961-2406

Project ID: 27-21 44TH
Sample ID#s: BD80732 - BD80737

This laboratory is in compliance with the NELAC requirements of procedures used except where indicated.


This report contains results for the parameters tested, under the sampling conditions described on the Chain Of Custody, as received by the laboratory.

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

A scanned version of the COC form accompanies the analytical report and is an exact duplicate of the original.

If you have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext. 200.

Sincerely yours,



Phyllis Shiller
Laboratory Director

NELAC - #NY11301
CT Lab Registration #PH-0618
MA Lab Registration #MA-CT-007
ME Lab Registration #CT-007
NH Lab Registration #213693-A,B
NJ Lab Registration #CT-003
NY Lab Registration #11301
PA Lab Registration #68-03530
RI Lab Registration #63
VT Lab Registration #VT11301

PHOENIX

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

SDG Comments

May 23, 2013

SDG I.D.: GBD80732

BD80734 - The pH in the preserved vial was greater than 2.

BD80735 - The pH in the preserved vial was greater than 2.

PHOENIX

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

Analysis Report

May 23, 2013

FOR: Attn: Mr. Charles B. Sosik, P.G.
Environmental Business Consultants
1808 Middle Country Rd
Ridge NY 11961-2406

Sample Information		Custody Information		Date	Time
Matrix:	SOIL	Collected by:		05/17/13	0:00
Location Code:	EBC	Received by:	LB	05/17/13	15:00
Rush Request:	72 Hour	Analyzed by:	see "By" below		
P.O.#:					

Laboratory Data

SDG ID: GBD80732
Phoenix ID: BD80732

Project ID: 27-21 44TH
Client ID: B1 5-8

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
Percent Solid	75		%	05/17/13	JL	E160.3
Soil Extraction SVOA PAH	Completed			05/17/13	BJ/V	SW3545
Field Extraction	Completed			05/17/13		SW5035
Volatiles						
1,1,1,2-Tetrachloroethane	ND	12	ug/Kg	05/18/13	R/J	SW8260
1,1,1-Trichloroethane	ND	12	ug/Kg	05/18/13	R/J	SW8260
1,1,2,2-Tetrachloroethane	ND	7.0	ug/Kg	05/18/13	R/J	SW8260
1,1,2-Trichloroethane	ND	12	ug/Kg	05/18/13	R/J	SW8260
1,1-Dichloroethane	ND	12	ug/Kg	05/18/13	R/J	SW8260
1,1-Dichloroethene	ND	12	ug/Kg	05/18/13	R/J	SW8260
1,1-Dichloropropene	ND	12	ug/Kg	05/18/13	R/J	SW8260
1,2,3-Trichlorobenzene	ND	12	ug/Kg	05/18/13	R/J	SW8260
1,2,3-Trichloropropane	ND	12	ug/Kg	05/18/13	R/J	SW8260
1,2,4-Trichlorobenzene	ND	12	ug/Kg	05/18/13	R/J	SW8260
1,2,4-Trimethylbenzene	ND	12	ug/Kg	05/18/13	R/J	SW8260
1,2-Dibromo-3-chloropropane	ND	12	ug/Kg	05/18/13	R/J	SW8260
1,2-Dibromoethane	ND	12	ug/Kg	05/18/13	R/J	SW8260
1,2-Dichlorobenzene	ND	12	ug/Kg	05/18/13	R/J	SW8260
1,2-Dichloroethane	ND	12	ug/Kg	05/18/13	R/J	SW8260
1,2-Dichloropropane	ND	12	ug/Kg	05/18/13	R/J	SW8260
1,3,5-Trimethylbenzene	ND	12	ug/Kg	05/18/13	R/J	SW8260
1,3-Dichlorobenzene	ND	12	ug/Kg	05/18/13	R/J	SW8260
1,3-Dichloropropane	ND	12	ug/Kg	05/18/13	R/J	SW8260
1,4-Dichlorobenzene	ND	12	ug/Kg	05/18/13	R/J	SW8260
2,2-Dichloropropane	ND	12	ug/Kg	05/18/13	R/J	SW8260
2-Chlorotoluene	ND	12	ug/Kg	05/18/13	R/J	SW8260
2-Hexanone	ND	58	ug/Kg	05/18/13	R/J	SW8260
2-Isopropyltoluene	ND	12	ug/Kg	05/18/13	R/J	SW8260

Project ID: 27-21 44TH
Client ID: B1 5-8

Phoenix I.D.: BD80732

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
4-Chlorotoluene	ND	12	ug/Kg	05/18/13	R/J	SW8260	
4-Methyl-2-pentanone	ND	58	ug/Kg	05/18/13	R/J	SW8260	
Acetone	ND	50	ug/Kg	05/18/13	R/J	SW8260	
Acrylonitrile	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Benzene	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Bromobenzene	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Bromochloromethane	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Bromodichloromethane	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Bromoform	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Bromomethane	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Carbon Disulfide	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Carbon tetrachloride	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Chlorobenzene	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Chloroethane	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Chloroform	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Chloromethane	ND	12	ug/Kg	05/18/13	R/J	SW8260	
cis-1,2-Dichloroethene	ND	12	ug/Kg	05/18/13	R/J	SW8260	
cis-1,3-Dichloropropene	ND	12	ug/Kg	05/18/13	R/J	SW8260	1
Dibromochloromethane	ND	7.0	ug/Kg	05/18/13	R/J	SW8260	
Dibromomethane	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Dichlorodifluoromethane	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Ethylbenzene	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Hexachlorobutadiene	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Isopropylbenzene	32	12	ug/Kg	05/18/13	R/J	SW8260	
m&p-Xylene	16	12	ug/Kg	05/18/13	R/J	SW8260	
Methyl Ethyl Ketone	ND	70	ug/Kg	05/18/13	R/J	SW8260	
Methyl t-butyl ether (MTBE)	ND	23	ug/Kg	05/18/13	R/J	SW8260	
Methylene chloride	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Naphthalene	ND	12	ug/Kg	05/18/13	R/J	SW8260	
n-Butylbenzene	18	12	ug/Kg	05/18/13	R/J	SW8260	
n-Propylbenzene	51	12	ug/Kg	05/18/13	R/J	SW8260	
o-Xylene	ND	12	ug/Kg	05/18/13	R/J	SW8260	
p-Isopropyltoluene	ND	12	ug/Kg	05/18/13	R/J	SW8260	
sec-Butylbenzene	18	12	ug/Kg	05/18/13	R/J	SW8260	
Styrene	ND	12	ug/Kg	05/18/13	R/J	SW8260	
tert-Butylbenzene	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Tetrachloroethene	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Tetrahydrofuran (THF)	ND	23	ug/Kg	05/18/13	R/J	SW8260	1
Toluene	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Total Xylenes	16	12	ug/Kg	05/18/13	R/J	SW8260	
trans-1,2-Dichloroethene	ND	12	ug/Kg	05/18/13	R/J	SW8260	
trans-1,3-Dichloropropene	ND	12	ug/Kg	05/18/13	R/J	SW8260	
trans-1,4-dichloro-2-butene	ND	23	ug/Kg	05/18/13	R/J	SW8260	
Trichloroethene	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Trichlorofluoromethane	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Trichlorotrifluoroethane	ND	12	ug/Kg	05/18/13	R/J	SW8260	
Vinyl chloride	ND	12	ug/Kg	05/18/13	R/J	SW8260	
QA/QC Surrogates							
% 1,2-dichlorobenzene-d4	97		%	05/18/13	R/J	70 - 130 %	
% Bromofluorobenzene	128		%	05/18/13	R/J	70 - 130 %	

Project ID: 27-21 44TH
Client ID: B1 5-8

Phoenix I.D.: BD80732

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
% Dibromofluoromethane	90		%	05/18/13	R/J	70 - 130 %
% Toluene-d8	112		%	05/18/13	R/J	70 - 130 %
Semivolatiles-STARS/CP-51						
Acenaphthene	ND	310	ug/Kg	05/22/13	DD	SW 8270
Acenaphthylene	ND	310	ug/Kg	05/22/13	DD	SW 8270
Anthracene	ND	310	ug/Kg	05/22/13	DD	SW 8270
Benz(a)anthracene	680	310	ug/Kg	05/22/13	DD	SW 8270
Benzo(a)pyrene	580	310	ug/Kg	05/22/13	DD	SW 8270
Benzo(b)fluoranthene	700	310	ug/Kg	05/22/13	DD	SW 8270
Benzo(ghi)perylene	410	310	ug/Kg	05/22/13	DD	SW 8270
Benzo(k)fluoranthene	ND	310	ug/Kg	05/22/13	DD	SW 8270
Chrysene	820	310	ug/Kg	05/22/13	DD	SW 8270
Dibenz(a,h)anthracene	ND	310	ug/Kg	05/22/13	DD	SW 8270
Fluoranthene	1600	310	ug/Kg	05/22/13	DD	SW 8270
Fluorene	ND	310	ug/Kg	05/22/13	DD	SW 8270
Indeno(1,2,3-cd)pyrene	ND	310	ug/Kg	05/22/13	DD	SW 8270
Naphthalene	310	310	ug/Kg	05/22/13	DD	SW 8270
Phenanthrene	1100	310	ug/Kg	05/22/13	DD	SW 8270
Pyrene	1700	310	ug/Kg	05/22/13	DD	SW 8270
QA/QC Surrogates						
% 2-Fluorobiphenyl	72		%	05/22/13	DD	30 - 130 %
% Nitrobenzene-d5	65		%	05/22/13	DD	30 - 130 %
% Terphenyl-d14	111		%	05/22/13	DD	30 - 130 %

1 = This parameter is not certified by NY NELAC for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quanitation) ND=Not Detected BRL=Below Reporting Level

Comments:

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.
This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director
May 23, 2013
Reviewed and Released by: Greg Lawrence, Assistant Lab Director

PHOENIX

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

Analysis Report

May 23, 2013

FOR: Attn: Mr. Charles B. Sosik, P.G.
Environmental Business Consultants
1808 Middle Country Rd
Ridge NY 11961-2406

Sample Information		Custody Information		Date	Time
Matrix:	SOIL	Collected by:		05/17/13	0:00
Location Code:	EBC	Received by:	LB	05/17/13	15:00
Rush Request:	72 Hour	Analyzed by:	see "By" below		
P.O.#:					

Laboratory Data

SDG ID: GBD80732
Phoenix ID: BD80733

Project ID: 27-21 44TH
Client ID: B2 4-7

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
Percent Solid	74		%	05/17/13	JL	E160.3
Soil Extraction SVOA PAH	Completed			05/17/13	BJ/V	SW3545
Field Extraction	Completed			05/17/13		SW5035
Volatiles						
1,1,1,2-Tetrachloroethane	ND	1600	ug/Kg	05/18/13	R/J	SW8260
1,1,1-Trichloroethane	ND	1600	ug/Kg	05/18/13	R/J	SW8260
1,1,2,2-Tetrachloroethane	ND	940	ug/Kg	05/18/13	R/J	SW8260
1,1,2-Trichloroethane	ND	1600	ug/Kg	05/18/13	R/J	SW8260
1,1-Dichloroethane	ND	1600	ug/Kg	05/18/13	R/J	SW8260
1,1-Dichloroethene	ND	1600	ug/Kg	05/18/13	R/J	SW8260
1,1-Dichloropropene	ND	1600	ug/Kg	05/18/13	R/J	SW8260
1,2,3-Trichlorobenzene	ND	1600	ug/Kg	05/18/13	R/J	SW8260
1,2,3-Trichloropropane	ND	1600	ug/Kg	05/18/13	R/J	SW8260
1,2,4-Trichlorobenzene	ND	1600	ug/Kg	05/18/13	R/J	SW8260
1,2,4-Trimethylbenzene	ND	1600	ug/Kg	05/18/13	R/J	SW8260
1,2-Dibromo-3-chloropropane	ND	1600	ug/Kg	05/18/13	R/J	SW8260
1,2-Dibromoethane	ND	1600	ug/Kg	05/18/13	R/J	SW8260
1,2-Dichlorobenzene	ND	1600	ug/Kg	05/18/13	R/J	SW8260
1,2-Dichloroethane	ND	1600	ug/Kg	05/18/13	R/J	SW8260
1,2-Dichloropropane	ND	1600	ug/Kg	05/18/13	R/J	SW8260
1,3,5-Trimethylbenzene	ND	1600	ug/Kg	05/18/13	R/J	SW8260
1,3-Dichlorobenzene	ND	1600	ug/Kg	05/18/13	R/J	SW8260
1,3-Dichloropropane	ND	1600	ug/Kg	05/18/13	R/J	SW8260
1,4-Dichlorobenzene	ND	1600	ug/Kg	05/18/13	R/J	SW8260
2,2-Dichloropropane	ND	1600	ug/Kg	05/18/13	R/J	SW8260
2-Chlorotoluene	ND	1600	ug/Kg	05/18/13	R/J	SW8260
2-Hexanone	ND	7900	ug/Kg	05/18/13	R/J	SW8260
2-Isopropyltoluene	ND	1600	ug/Kg	05/18/13	R/J	SW8260

Project ID: 27-21 44TH
Client ID: B2 4-7

Phoenix I.D.: BD80733

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
4-Chlorotoluene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
4-Methyl-2-pentanone	ND	7900	ug/Kg	05/18/13	R/J	SW8260	
Acetone	ND	31000	ug/Kg	05/18/13	R/J	SW8260	
Acrylonitrile	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Benzene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Bromobenzene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Bromochloromethane	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Bromodichloromethane	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Bromoform	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Bromomethane	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Carbon Disulfide	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Carbon tetrachloride	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Chlorobenzene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Chloroethane	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Chloroform	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Chloromethane	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
cis-1,2-Dichloroethene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
cis-1,3-Dichloropropene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	1
Dibromochloromethane	ND	940	ug/Kg	05/18/13	R/J	SW8260	
Dibromomethane	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Dichlorodifluoromethane	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Ethylbenzene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Hexachlorobutadiene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Isopropylbenzene	2000	1600	ug/Kg	05/18/13	R/J	SW8260	
m&p-Xylene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Methyl Ethyl Ketone	ND	9400	ug/Kg	05/18/13	R/J	SW8260	
Methyl t-butyl ether (MTBE)	ND	3100	ug/Kg	05/18/13	R/J	SW8260	
Methylene chloride	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Naphthalene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
n-Butylbenzene	4000	1600	ug/Kg	05/18/13	R/J	SW8260	
n-Propylbenzene	4500	1600	ug/Kg	05/18/13	R/J	SW8260	
o-Xylene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
p-Isopropyltoluene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
sec-Butylbenzene	1700	1600	ug/Kg	05/18/13	R/J	SW8260	
Styrene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
tert-Butylbenzene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Tetrachloroethene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Tetrahydrofuran (THF)	ND	3100	ug/Kg	05/18/13	R/J	SW8260	1
Toluene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Total Xylenes	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
trans-1,2-Dichloroethene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
trans-1,3-Dichloropropene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
trans-1,4-dichloro-2-butene	ND	3100	ug/Kg	05/18/13	R/J	SW8260	
Trichloroethene	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Trichlorofluoromethane	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Trichlorotrifluoroethane	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
Vinyl chloride	ND	1600	ug/Kg	05/18/13	R/J	SW8260	
QA/QC Surrogates							
% 1,2-dichlorobenzene-d4	97		%	05/18/13	R/J	70 - 130 %	
% Bromofluorobenzene	144		%	05/18/13	R/J	70 - 130 %	3

Project ID: 27-21 44TH
Client ID: B2 4-7

Phoenix I.D.: BD80733

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
% Dibromofluoromethane	99		%	05/18/13	R/J	70 - 130 %
% Toluene-d8	109		%	05/18/13	R/J	70 - 130 %
Semivolatiles-STARS/CP-51						
Acenaphthene	ND	3100	ug/Kg	05/21/13	DD	SW 8270
Acenaphthylene	ND	3100	ug/Kg	05/21/13	DD	SW 8270
Anthracene	ND	3100	ug/Kg	05/21/13	DD	SW 8270
Benz(a)anthracene	ND	3100	ug/Kg	05/21/13	DD	SW 8270
Benzo(a)pyrene	ND	3100	ug/Kg	05/21/13	DD	SW 8270
Benzo(b)fluoranthene	ND	3100	ug/Kg	05/21/13	DD	SW 8270
Benzo(ghi)perylene	ND	3100	ug/Kg	05/21/13	DD	SW 8270
Benzo(k)fluoranthene	ND	3100	ug/Kg	05/21/13	DD	SW 8270
Chrysene	ND	3100	ug/Kg	05/21/13	DD	SW 8270
Dibenz(a,h)anthracene	ND	3100	ug/Kg	05/21/13	DD	SW 8270
Fluoranthene	ND	3100	ug/Kg	05/21/13	DD	SW 8270
Fluorene	ND	3100	ug/Kg	05/21/13	DD	SW 8270
Indeno(1,2,3-cd)pyrene	ND	3100	ug/Kg	05/21/13	DD	SW 8270
Naphthalene	ND	3100	ug/Kg	05/21/13	DD	SW 8270
Phenanthrene	ND	3100	ug/Kg	05/21/13	DD	SW 8270
Pyrene	ND	3100	ug/Kg	05/21/13	DD	SW 8270
QA/QC Surrogates						
% 2-Fluorobiphenyl	*Diluted Out		%	05/21/13	DD	30 - 130 %
% Nitrobenzene-d5	*Diluted Out		%	05/21/13	DD	30 - 130 %
% Terphenyl-d14	*Diluted Out		%	05/21/13	DD	30 - 130 %

1 = This parameter is not certified by NY NELAC for this matrix. NY NELAC does not offer certification for all parameters at this time.
3 = This parameter exceeds laboratory specified limits.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quanitation) ND=Not Detected BRL=Below Reporting Level


Comments:

Elevated surrogate recovery was observed for volatiles due to matrix interference.

* Due to a matrix interference and/or the presence of a large amount of non-target material in the sample, an elevated RL was reported for the semivolatile analysis.

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.
This report must not be reproduced except in full as defined by the attached chain of custody.



Phyllis Shiller, Laboratory Director
May 23, 2013
Reviewed and Released by: Greg Lawrence, Assistant Lab Director

PHOENIX

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

Analysis Report

May 23, 2013

FOR: Attn: Mr. Charles B. Sosik, P.G.
Environmental Business Consultants
1808 Middle Country Rd
Ridge NY 11961-2406

Sample Information		Custody Information		Date	Time
Matrix:	GROUND WATER	Collected by:		05/17/13	0:00
Location Code:	EBC	Received by:	LB	05/17/13	15:00
Rush Request:	72 Hour	Analyzed by:	see "By" below		
P.O.#:					

Laboratory Data

SDG ID: GBD80732
Phoenix ID: BD80734

Project ID: 27-21 44TH
Client ID: GW1

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
Semi-Volatile Extraction	Completed			05/17/13	I/D	SW3520	
Volatiles							
1,1,1,2-Tetrachloroethane	ND	20	ug/L	05/19/13	R/T	SW8260	
1,1,1-Trichloroethane	ND	20	ug/L	05/19/13	R/T	SW8260	
1,1,2,2-Tetrachloroethane	ND	10	ug/L	05/19/13	R/T	SW8260	
1,1,2-Trichloroethane	ND	20	ug/L	05/19/13	R/T	SW8260	
1,1-Dichloroethane	ND	20	ug/L	05/19/13	R/T	SW8260	
1,1-Dichloroethene	ND	20	ug/L	05/19/13	R/T	SW8260	
1,1-Dichloropropene	ND	20	ug/L	05/19/13	R/T	SW8260	
1,2,3-Trichlorobenzene	ND	20	ug/L	05/19/13	R/T	SW8260	
1,2,3-Trichloropropane	ND	20	ug/L	05/19/13	R/T	SW8260	
1,2,4-Trichlorobenzene	ND	20	ug/L	05/19/13	R/T	SW8260	
1,2,4-Trimethylbenzene	ND	20	ug/L	05/19/13	R/T	SW8260	
1,2-Dibromo-3-chloropropane	ND	20	ug/L	05/19/13	R/T	SW8260	
1,2-Dibromoethane	ND	20	ug/L	05/19/13	R/T	SW8260	
1,2-Dichlorobenzene	ND	20	ug/L	05/19/13	R/T	SW8260	
1,2-Dichloroethane	ND	12	ug/L	05/19/13	R/T	SW8260	
1,2-Dichloropropane	ND	20	ug/L	05/19/13	R/T	SW8260	
1,3,5-Trimethylbenzene	ND	20	ug/L	05/19/13	R/T	SW8260	
1,3-Dichlorobenzene	ND	20	ug/L	05/19/13	R/T	SW8260	
1,3-Dichloropropane	ND	20	ug/L	05/19/13	R/T	SW8260	
1,4-Dichlorobenzene	ND	20	ug/L	05/19/13	R/T	SW8260	
2,2-Dichloropropane	ND	20	ug/L	05/19/13	R/T	SW8260	
2-Chlorotoluene	ND	20	ug/L	05/19/13	R/T	SW8260	
2-Hexanone	ND	100	ug/L	05/19/13	R/T	SW8260	
2-Isopropyltoluene	ND	20	ug/L	05/19/13	R/T	SW8260	1
4-Chlorotoluene	ND	20	ug/L	05/19/13	R/T	SW8260	
4-Methyl-2-pentanone	ND	100	ug/L	05/19/13	R/T	SW8260	

Project ID: 27-21 44TH
Client ID: GW1

Phoenix I.D.: BD80734

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
Acetone	ND	500	ug/L	05/19/13	R/T	SW8260	
Acrylonitrile	ND	100	ug/L	05/19/13	R/T	SW8260	
Benzene	ND	14	ug/L	05/19/13	R/T	SW8260	
Bromobenzene	ND	20	ug/L	05/19/13	R/T	SW8260	
Bromochloromethane	ND	20	ug/L	05/19/13	R/T	SW8260	
Bromodichloromethane	ND	10	ug/L	05/19/13	R/T	SW8260	
Bromoform	ND	20	ug/L	05/19/13	R/T	SW8260	
Bromomethane	ND	20	ug/L	05/19/13	R/T	SW8260	
Carbon Disulfide	ND	100	ug/L	05/19/13	R/T	SW8260	
Carbon tetrachloride	ND	20	ug/L	05/19/13	R/T	SW8260	
Chlorobenzene	ND	20	ug/L	05/19/13	R/T	SW8260	
Chloroethane	ND	20	ug/L	05/19/13	R/T	SW8260	
Chloroform	ND	20	ug/L	05/19/13	R/T	SW8260	
Chloromethane	ND	20	ug/L	05/19/13	R/T	SW8260	
cis-1,2-Dichloroethene	ND	20	ug/L	05/19/13	R/T	SW8260	
cis-1,3-Dichloropropene	ND	10	ug/L	05/19/13	R/T	SW8260	1
Dibromochloromethane	ND	10	ug/L	05/19/13	R/T	SW8260	
Dibromomethane	ND	20	ug/L	05/19/13	R/T	SW8260	
Dichlorodifluoromethane	ND	20	ug/L	05/19/13	R/T	SW8260	
Ethylbenzene	ND	20	ug/L	05/19/13	R/T	SW8260	
Hexachlorobutadiene	ND	8.0	ug/L	05/19/13	R/T	SW8260	
Isopropylbenzene	ND	20	ug/L	05/19/13	R/T	SW8260	
m&p-Xylene	ND	20	ug/L	05/19/13	R/T	SW8260	
Methyl ethyl ketone	ND	100	ug/L	05/19/13	R/T	SW8260	
Methyl t-butyl ether (MTBE)	ND	20	ug/L	05/19/13	R/T	SW8260	
Methylene chloride	ND	20	ug/L	05/19/13	R/T	SW8260	
Naphthalene	ND	20	ug/L	05/19/13	R/T	SW8260	
n-Butylbenzene	ND	20	ug/L	05/19/13	R/T	SW8260	
n-Propylbenzene	21	20	ug/L	05/19/13	R/T	SW8260	
o-Xylene	ND	20	ug/L	05/19/13	R/T	SW8260	
p-Isopropyltoluene	ND	20	ug/L	05/19/13	R/T	SW8260	
sec-Butylbenzene	ND	20	ug/L	05/19/13	R/T	SW8260	
Styrene	ND	20	ug/L	05/19/13	R/T	SW8260	
tert-Butylbenzene	ND	20	ug/L	05/19/13	R/T	SW8260	
Tetrachloroethene	ND	20	ug/L	05/19/13	R/T	SW8260	
Tetrahydrofuran (THF)	ND	50	ug/L	05/19/13	R/T	SW8260	1
Toluene	ND	20	ug/L	05/19/13	R/T	SW8260	
Total Xylenes	ND	20	ug/L	05/19/13	R/T	SW8260	
trans-1,2-Dichloroethene	ND	20	ug/L	05/19/13	R/T	SW8260	
trans-1,3-Dichloropropene	ND	10	ug/L	05/19/13	R/T	SW8260	
trans-1,4-dichloro-2-butene	ND	100	ug/L	05/19/13	R/T	SW8260	
Trichloroethene	ND	20	ug/L	05/19/13	R/T	SW8260	
Trichlorofluoromethane	ND	20	ug/L	05/19/13	R/T	SW8260	
Trichlorotrifluoroethane	ND	20	ug/L	05/19/13	R/T	SW8260	
Vinyl chloride	ND	20	ug/L	05/19/13	R/T	SW8260	
QA/QC Surrogates							
% 1,2-dichlorobenzene-d4	102		%	05/19/13	R/T	70 - 130 %	
% Bromofluorobenzene	95		%	05/19/13	R/T	70 - 130 %	
% Dibromofluoromethane	101		%	05/19/13	R/T	70 - 130 %	
% Toluene-d8	101		%	05/19/13	R/T	70 - 130 %	

Project ID: 27-21 44TH
Client ID: GW1

Phoenix I.D.: BD80734


Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
Semivolatiles by SIM						
2-Methylnaphthalene	0.98	0.10	ug/L	05/22/13	DD	8270(SIM)
Acenaphthene	1.4	0.10	ug/L	05/22/13	DD	8270(SIM)
Acenaphthylene	1.1	0.10	ug/L	05/22/13	DD	8270(SIM)
Anthracene	4.3	0.10	ug/L	05/22/13	DD	8270(SIM)
Benz(a)anthracene	11	0.020	ug/L	05/22/13	DD	8270(SIM)
Benzo(a)pyrene	11	0.020	ug/L	05/22/13	DD	8270(SIM)
Benzo(b)fluoranthene	13	0.020	ug/L	05/22/13	DD	8270(SIM)
Benzo(ghi)perylene	7.5	0.10	ug/L	05/22/13	DD	8270(SIM)
Benzo(k)fluoranthene	5.1	0.020	ug/L	05/22/13	DD	8270(SIM)
Chrysene	11	0.020	ug/L	05/22/13	DD	8270(SIM)
Dibenz(a,h)anthracene	1.5	0.010	ug/L	05/22/13	DD	8270(SIM)
Fluoranthene	19	0.10	ug/L	05/22/13	DD	8270(SIM)
Fluorene	1.4	0.10	ug/L	05/22/13	DD	8270(SIM)
Indeno(1,2,3-cd)pyrene	5.8	0.020	ug/L	05/22/13	DD	8270(SIM)
Naphthalene	1.5	0.10	ug/L	05/22/13	DD	8270(SIM)
Phenanthrene	14	0.070	ug/L	05/22/13	DD	8270(SIM)
Pyrene	21	0.10	ug/L	05/22/13	DD	8270(SIM)
QA/QC Surrogates						
% 2-Fluorobiphenyl	66		%	05/22/13	DD	30 - 130 %
% Nitrobenzene-d5	59		%	05/22/13	DD	30 - 130 %
% Terphenyl-d14	73		%	05/22/13	DD	30 - 130 %

1 = This parameter is not certified by NY NELAC for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quanitation) ND=Not Detected BRL=Below Reporting Level

Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.
This report must not be reproduced except in full as defined by the attached chain of custody.



Phyllis Shiller, Laboratory Director
May 23, 2013
Reviewed and Released by: Greg Lawrence, Assistant Lab Director

PHOENIX

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

Analysis Report

May 23, 2013

FOR: Attn: Mr. Charles B. Sosik, P.G.
Environmental Business Consultants
1808 Middle Country Rd
Ridge NY 11961-2406

Sample Information		Custody Information		Date	Time
Matrix:	GROUND WATER	Collected by:		05/17/13	0:00
Location Code:	EBC	Received by:	LB	05/17/13	15:00
Rush Request:	72 Hour	Analyzed by:	see "By" below		
P.O.#:					

Laboratory Data

SDG ID: GBD80732
Phoenix ID: BD80735

Project ID: 27-21 44TH
Client ID: GW2

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
Semi-Volatile Extraction	Completed			05/17/13	I/D	SW3520	
Volatiles							
1,1,1,2-Tetrachloroethane	ND	40	ug/L	05/19/13	R/T	SW8260	
1,1,1-Trichloroethane	ND	40	ug/L	05/19/13	R/T	SW8260	
1,1,2,2-Tetrachloroethane	ND	20	ug/L	05/19/13	R/T	SW8260	
1,1,2-Trichloroethane	ND	40	ug/L	05/19/13	R/T	SW8260	
1,1-Dichloroethane	ND	40	ug/L	05/19/13	R/T	SW8260	
1,1-Dichloroethene	ND	40	ug/L	05/19/13	R/T	SW8260	
1,1-Dichloropropene	ND	40	ug/L	05/19/13	R/T	SW8260	
1,2,3-Trichlorobenzene	ND	40	ug/L	05/19/13	R/T	SW8260	
1,2,3-Trichloropropane	ND	40	ug/L	05/19/13	R/T	SW8260	
1,2,4-Trichlorobenzene	ND	40	ug/L	05/19/13	R/T	SW8260	
1,2,4-Trimethylbenzene	ND	40	ug/L	05/19/13	R/T	SW8260	
1,2-Dibromo-3-chloropropane	ND	40	ug/L	05/19/13	R/T	SW8260	
1,2-Dibromoethane	ND	40	ug/L	05/19/13	R/T	SW8260	
1,2-Dichlorobenzene	ND	40	ug/L	05/19/13	R/T	SW8260	
1,2-Dichloroethane	ND	24	ug/L	05/19/13	R/T	SW8260	
1,2-Dichloropropane	ND	40	ug/L	05/19/13	R/T	SW8260	
1,3,5-Trimethylbenzene	ND	40	ug/L	05/19/13	R/T	SW8260	
1,3-Dichlorobenzene	ND	40	ug/L	05/19/13	R/T	SW8260	
1,3-Dichloropropane	ND	40	ug/L	05/19/13	R/T	SW8260	
1,4-Dichlorobenzene	ND	40	ug/L	05/19/13	R/T	SW8260	
2,2-Dichloropropane	ND	40	ug/L	05/19/13	R/T	SW8260	
2-Chlorotoluene	ND	40	ug/L	05/19/13	R/T	SW8260	
2-Hexanone	ND	200	ug/L	05/19/13	R/T	SW8260	
2-Isopropyltoluene	ND	40	ug/L	05/19/13	R/T	SW8260	1
4-Chlorotoluene	ND	40	ug/L	05/19/13	R/T	SW8260	
4-Methyl-2-pentanone	ND	200	ug/L	05/19/13	R/T	SW8260	

Project ID: 27-21 44TH
Client ID: GW2

Phoenix I.D.: BD80735

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
Acetone	ND	1000	ug/L	05/19/13	R/T	SW8260	
Acrylonitrile	ND	200	ug/L	05/19/13	R/T	SW8260	
Benzene	ND	28	ug/L	05/19/13	R/T	SW8260	
Bromobenzene	ND	40	ug/L	05/19/13	R/T	SW8260	
Bromochloromethane	ND	40	ug/L	05/19/13	R/T	SW8260	
Bromodichloromethane	ND	20	ug/L	05/19/13	R/T	SW8260	
Bromoform	ND	40	ug/L	05/19/13	R/T	SW8260	
Bromomethane	ND	40	ug/L	05/19/13	R/T	SW8260	
Carbon Disulfide	ND	200	ug/L	05/19/13	R/T	SW8260	
Carbon tetrachloride	ND	40	ug/L	05/19/13	R/T	SW8260	
Chlorobenzene	ND	40	ug/L	05/19/13	R/T	SW8260	
Chloroethane	ND	40	ug/L	05/19/13	R/T	SW8260	
Chloroform	ND	40	ug/L	05/19/13	R/T	SW8260	
Chloromethane	ND	40	ug/L	05/19/13	R/T	SW8260	
cis-1,2-Dichloroethene	ND	40	ug/L	05/19/13	R/T	SW8260	
cis-1,3-Dichloropropene	ND	20	ug/L	05/19/13	R/T	SW8260	1
Dibromochloromethane	ND	20	ug/L	05/19/13	R/T	SW8260	
Dibromomethane	ND	40	ug/L	05/19/13	R/T	SW8260	
Dichlorodifluoromethane	ND	40	ug/L	05/19/13	R/T	SW8260	
Ethylbenzene	ND	40	ug/L	05/19/13	R/T	SW8260	
Hexachlorobutadiene	ND	16	ug/L	05/19/13	R/T	SW8260	
Isopropylbenzene	47	40	ug/L	05/19/13	R/T	SW8260	
m&p-Xylene	ND	40	ug/L	05/19/13	R/T	SW8260	
Methyl ethyl ketone	ND	200	ug/L	05/19/13	R/T	SW8260	
Methyl t-butyl ether (MTBE)	ND	40	ug/L	05/19/13	R/T	SW8260	
Methylene chloride	ND	40	ug/L	05/19/13	R/T	SW8260	
Naphthalene	ND	40	ug/L	05/19/13	R/T	SW8260	
n-Butylbenzene	66	40	ug/L	05/19/13	R/T	SW8260	
n-Propylbenzene	110	40	ug/L	05/19/13	R/T	SW8260	
o-Xylene	ND	40	ug/L	05/19/13	R/T	SW8260	
p-Isopropyltoluene	ND	40	ug/L	05/19/13	R/T	SW8260	
sec-Butylbenzene	ND	40	ug/L	05/19/13	R/T	SW8260	
Styrene	ND	40	ug/L	05/19/13	R/T	SW8260	
tert-Butylbenzene	ND	40	ug/L	05/19/13	R/T	SW8260	
Tetrachloroethene	ND	40	ug/L	05/19/13	R/T	SW8260	
Tetrahydrofuran (THF)	ND	100	ug/L	05/19/13	R/T	SW8260	1
Toluene	ND	40	ug/L	05/19/13	R/T	SW8260	
Total Xylenes	ND	40	ug/L	05/19/13	R/T	SW8260	
trans-1,2-Dichloroethene	ND	40	ug/L	05/19/13	R/T	SW8260	
trans-1,3-Dichloropropene	ND	20	ug/L	05/19/13	R/T	SW8260	
trans-1,4-dichloro-2-butene	ND	200	ug/L	05/19/13	R/T	SW8260	
Trichloroethene	ND	40	ug/L	05/19/13	R/T	SW8260	
Trichlorofluoromethane	ND	40	ug/L	05/19/13	R/T	SW8260	
Trichlorotrifluoroethane	ND	40	ug/L	05/19/13	R/T	SW8260	
Vinyl chloride	ND	40	ug/L	05/19/13	R/T	SW8260	
QA/QC Surrogates							
% 1,2-dichlorobenzene-d4	100		%	05/19/13	R/T	70 - 130 %	
% Bromofluorobenzene	104		%	05/19/13	R/T	70 - 130 %	
% Dibromofluoromethane	98		%	05/19/13	R/T	70 - 130 %	
% Toluene-d8	105		%	05/19/13	R/T	70 - 130 %	

Project ID: 27-21 44TH
Client ID: GW2

Phoenix I.D.: BD80735

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
Polynuclear Aromatic HC						
2-Methylnaphthalene	ND	50	ug/L	05/22/13	DD	SW 8270
Acenaphthene	ND	50	ug/L	05/22/13	DD	SW 8270
Acenaphthylene	ND	50	ug/L	05/22/13	DD	SW 8270
Anthracene	ND	50	ug/L	05/22/13	DD	SW 8270
Benz(a)anthracene	ND	50	ug/L	05/22/13	DD	SW 8270
Benzo(a)pyrene	ND	50	ug/L	05/22/13	DD	SW 8270
Benzo(b)fluoranthene	ND	50	ug/L	05/22/13	DD	SW 8270
Benzo(ghi)perylene	ND	50	ug/L	05/22/13	DD	SW 8270
Benzo(k)fluoranthene	ND	50	ug/L	05/22/13	DD	SW 8270
Chrysene	ND	50	ug/L	05/22/13	DD	SW 8270
Dibenz(a,h)anthracene	ND	50	ug/L	05/22/13	DD	SW 8270
Fluoranthene	73	50	ug/L	05/22/13	DD	SW 8270
Fluorene	ND	50	ug/L	05/22/13	DD	SW 8270
Indeno(1,2,3-cd)pyrene	ND	50	ug/L	05/22/13	DD	SW 8270
Naphthalene	57	50	ug/L	05/22/13	DD	SW 8270
Phenanthrene	51	50	ug/L	05/22/13	DD	SW 8270
Pyrene	69	50	ug/L	05/22/13	DD	SW 8270
QA/QC Surrogates						
% 2-Fluorobiphenyl	*Diluted Out		%	05/22/13	DD	30 - 130 %
% Nitrobenzene-d5	*Diluted Out		%	05/22/13	DD	30 - 130 %
% Terphenyl-d14	*Diluted Out		%	05/22/13	DD	30 - 130 %

1 = This parameter is not certified by NY NELAC for this matrix. NY NELAC does not offer certification for all parameters at this time.


RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quanitation) ND=Not Detected BRL=Below Reporting Level

Comments:

Elevated reporting limits for volatiles due to the presence of non-target compounds.

* Due to a matrix interference and/or the presence of a large amount of non-target material in the sample, an elevated RL was reported for the semivolatile analysis.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.
This report must not be reproduced except in full as defined by the attached chain of custody.



Phyllis Shiller, Laboratory Director
May 23, 2013
Reviewed and Released by: Greg Lawrence, Assistant Lab Director

PHOENIX

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

Analysis Report

May 23, 2013

FOR: Attn: Mr. Charles B. Sosik, P.G.
Environmental Business Consultants
1808 Middle Country Rd
Ridge NY 11961-2406

Sample Information		Custody Information		Date	Time
Matrix:	SOIL	Collected by:		05/17/13	0:00
Location Code:	EBC	Received by:	LB	05/17/13	15:00
Rush Request:	72 Hour	Analyzed by:	see "By" below		
P.O.#:					

Laboratory Data

SDG ID: GBD80732
Phoenix ID: BD80736

Project ID: 27-21 44TH
Client ID: TRIP BLANK HIGH

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
Percent Solid	100	1	%	05/17/13		E160.3
Field Extraction	Completed			05/17/13		SW5035
Volatiles						
1,1,1,2-Tetrachloroethane	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,1,1-Trichloroethane	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,1,2,2-Tetrachloroethane	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,1,2-Trichloroethane	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,1-Dichloroethane	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,1-Dichloroethene	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,1-Dichloropropene	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,2,3-Trichlorobenzene	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,2,3-Trichloropropane	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,2,4-Trichlorobenzene	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,2,4-Trimethylbenzene	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,2-Dibromo-3-chloropropane	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,2-Dibromoethane	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,2-Dichlorobenzene	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,2-Dichloroethane	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,2-Dichloropropane	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,3,5-Trimethylbenzene	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,3-Dichlorobenzene	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,3-Dichloropropane	ND	250	ug/Kg	05/18/13	R/J	SW8260
1,4-Dichlorobenzene	ND	250	ug/Kg	05/18/13	R/J	SW8260
2,2-Dichloropropane	ND	250	ug/Kg	05/18/13	R/J	SW8260
2-Chlorotoluene	ND	250	ug/Kg	05/18/13	R/J	SW8260
2-Hexanone	ND	1300	ug/Kg	05/18/13	R/J	SW8260
2-Isopropyltoluene	ND	250	ug/Kg	05/18/13	R/J	SW8260
4-Chlorotoluene	ND	250	ug/Kg	05/18/13	R/J	SW8260

Project ID: 27-21 44TH
Client ID: TRIP BLANK HIGH

Phoenix I.D.: BD80736

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
4-Methyl-2-pentanone	ND	1300	ug/Kg	05/18/13	R/J	SW8260	
Acetone	ND	5000	ug/Kg	05/18/13	R/J	SW8260	
Acrylonitrile	ND	500	ug/Kg	05/18/13	R/J	SW8260	
Benzene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Bromobenzene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Bromochloromethane	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Bromodichloromethane	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Bromoform	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Bromomethane	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Carbon Disulfide	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Carbon tetrachloride	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Chlorobenzene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Chloroethane	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Chloroform	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Chloromethane	ND	250	ug/Kg	05/18/13	R/J	SW8260	
cis-1,2-Dichloroethene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
cis-1,3-Dichloropropene	ND	250	ug/Kg	05/18/13	R/J	SW8260	1
Dibromochloromethane	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Dibromomethane	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Dichlorodifluoromethane	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Ethylbenzene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Hexachlorobutadiene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Isopropylbenzene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
m&p-Xylene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Methyl Ethyl Ketone	ND	3000	ug/Kg	05/18/13	R/J	SW8260	
Methyl t-butyl ether (MTBE)	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Methylene chloride	ND	500	ug/Kg	05/18/13	R/J	SW8260	
Naphthalene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
n-Butylbenzene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
n-Propylbenzene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
o-Xylene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
p-Isopropyltoluene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
sec-Butylbenzene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Styrene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
tert-Butylbenzene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Tetrachloroethene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Tetrahydrofuran (THF)	ND	500	ug/Kg	05/18/13	R/J	SW8260	1
Toluene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Total Xylenes	ND	250	ug/Kg	05/18/13	R/J	SW8260	
trans-1,2-Dichloroethene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
trans-1,3-Dichloropropene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
trans-1,4-dichloro-2-butene	ND	500	ug/Kg	05/18/13	R/J	SW8260	
Trichloroethene	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Trichlorofluoromethane	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Trichlorotrifluoroethane	ND	250	ug/Kg	05/18/13	R/J	SW8260	
Vinyl chloride	ND	250	ug/Kg	05/18/13	R/J	SW8260	
QA/QC Surrogates							
% 1,2-dichlorobenzene-d4	101		%	05/18/13	R/J	70 - 130 %	
% Bromofluorobenzene	93		%	05/18/13	R/J	70 - 130 %	
% Dibromofluoromethane	111		%	05/18/13	R/J	70 - 130 %	

Project ID: 27-21 44TH
Client ID: TRIP BLANK HIGH

Phoenix I.D.: BD80736

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
% Toluene-d8	102		%	05/18/13	R/J	70 - 130 %

1 = This parameter is not certified by NY NELAC for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quanitation) ND=Not Detected BRL=Below Reporting Level

Comments:

TRIP BLANK INCLUDED 100% SOLID ASSUMED

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.
This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director
May 23, 2013
Reviewed and Released by: Greg Lawrence, Assistant Lab Director

PHOENIX

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

Analysis Report

May 23, 2013

FOR: Attn: Mr. Charles B. Sosik, P.G.
Environmental Business Consultants
1808 Middle Country Rd
Ridge NY 11961-2406

Sample Information		Custody Information		Date	Time
Matrix:	SOIL	Collected by:		05/17/13	0:00
Location Code:	EBC	Received by:	LB	05/17/13	15:00
Rush Request:	72 Hour	Analyzed by:	see "By" below		
P.O.#:					

Laboratory Data

SDG ID: GBD80732
Phoenix ID: BD80737

Project ID: 27-21 44TH
Client ID: TRIP BLANK LOW

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
Percent Solid	100	1	%	05/17/13		E160.3
Field Extraction	Completed			05/17/13		SW5035
Volatiles						
1,1,1,2-Tetrachloroethane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
1,1,1-Trichloroethane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
1,1,2,2-Tetrachloroethane	ND	3.0	ug/Kg	05/18/13	R/J	SW8260
1,1,2-Trichloroethane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
1,1-Dichloroethane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
1,1-Dichloroethene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
1,1-Dichloropropene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
1,2,3-Trichlorobenzene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
1,2,3-Trichloropropane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
1,2,4-Trichlorobenzene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
1,2,4-Trimethylbenzene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
1,2-Dibromo-3-chloropropane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
1,2-Dibromoethane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
1,2-Dichlorobenzene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
1,2-Dichloroethane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
1,2-Dichloropropane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
1,3,5-Trimethylbenzene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
1,3-Dichlorobenzene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
1,3-Dichloropropane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
1,4-Dichlorobenzene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
2,2-Dichloropropane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
2-Chlorotoluene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
2-Hexanone	ND	25	ug/Kg	05/18/13	R/J	SW8260
2-Isopropyltoluene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260
4-Chlorotoluene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260

Project ID: 27-21 44TH
Client ID: TRIP BLANK LOW

Phoenix I.D.: BD80737

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference	
4-Methyl-2-pentanone	ND	25	ug/Kg	05/18/13	R/J	SW8260	
Acetone	ND	50	ug/Kg	05/18/13	R/J	SW8260	
Acrylonitrile	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Benzene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Bromobenzene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Bromochloromethane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Bromodichloromethane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Bromoform	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Bromomethane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Carbon Disulfide	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Carbon tetrachloride	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Chlorobenzene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Chloroethane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Chloroform	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Chloromethane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
cis-1,2-Dichloroethene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
cis-1,3-Dichloropropene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	1
Dibromochloromethane	ND	3.0	ug/Kg	05/18/13	R/J	SW8260	
Dibromomethane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Dichlorodifluoromethane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Ethylbenzene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Hexachlorobutadiene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Isopropylbenzene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
m&p-Xylene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Methyl Ethyl Ketone	ND	30	ug/Kg	05/18/13	R/J	SW8260	
Methyl t-butyl ether (MTBE)	ND	10	ug/Kg	05/18/13	R/J	SW8260	
Methylene chloride	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Naphthalene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
n-Butylbenzene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
n-Propylbenzene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
o-Xylene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
p-Isopropyltoluene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
sec-Butylbenzene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Styrene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
tert-Butylbenzene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Tetrachloroethene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Tetrahydrofuran (THF)	ND	10	ug/Kg	05/18/13	R/J	SW8260	1
Toluene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Total Xylenes	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
trans-1,2-Dichloroethene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
trans-1,3-Dichloropropene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
trans-1,4-dichloro-2-butene	ND	10	ug/Kg	05/18/13	R/J	SW8260	
Trichloroethene	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Trichlorofluoromethane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Trichlorotrifluoroethane	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
Vinyl chloride	ND	5.0	ug/Kg	05/18/13	R/J	SW8260	
QA/QC Surrogates							
% 1,2-dichlorobenzene-d4	100		%	05/18/13	R/J	70 - 130 %	
% Bromofluorobenzene	93		%	05/18/13	R/J	70 - 130 %	
% Dibromofluoromethane	109		%	05/18/13	R/J	70 - 130 %	

Project ID: 27-21 44TH
Client ID: TRIP BLANK LOW

Phoenix I.D.: BD80737

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
% Toluene-d8	107		%	05/18/13	R/J	70 - 130 %

1 = This parameter is not certified by NY NELAC for this matrix. NY NELAC does not offer certification for all parameters at this time.


RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quanitation) ND=Not Detected BRL=Below Reporting Level

Comments:

TRIP BLANK INCLUDED 100% SOLID ASSUMED

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.
This report must not be reproduced except in full as defined by the attached chain of custody.



Phyllis Shiller, Laboratory Director
May 23, 2013
Reviewed and Released by: Greg Lawrence, Assistant Lab Director

PHOENIX

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

QA/QC Report

May 23, 2013

QA/QC Data

SDG I.D.: GBD80732

Parameter	Blank	LCS %	LCSD %	LCS RPD	MS %	MSD %	MS RPD	% Rec Limits	% RPD Limits	
QA/QC Batch 231177, QC Sample No: BD70474 (BD80732, BD80736 (50X) , BD80737)										
Volatiles - Soil										
1,1,1,2-Tetrachloroethane	ND	108	109	0.9	105	103	1.9	70 - 130	30	
1,1,1-Trichloroethane	ND	104	104	0.0	87	92	5.6	70 - 130	30	
1,1,2,2-Tetrachloroethane	ND	105	106	0.9	111	107	3.7	70 - 130	30	
1,1,2-Trichloroethane	ND	112	111	0.9	105	103	1.9	70 - 130	30	
1,1-Dichloroethane	ND	115	116	0.9	109	108	0.9	70 - 130	30	
1,1-Dichloroethene	ND	120	121	0.8	88	86	2.3	70 - 130	30	
1,1-Dichloropropene	ND	112	111	0.9	108	107	0.9	70 - 130	30	
1,2,3-Trichlorobenzene	ND	103	102	1.0	103	98	5.0	70 - 130	30	
1,2,3-Trichloropropane	ND	104	103	1.0	98	96	2.1	70 - 130	30	
1,2,4-Trichlorobenzene	ND	103	102	1.0	109	101	7.6	70 - 130	30	
1,2,4-Trimethylbenzene	ND	115	113	1.8	111	104	6.5	70 - 130	30	
1,2-Dibromo-3-chloropropane	ND	98	100	2.0	94	90	4.3	70 - 130	30	
1,2-Dibromoethane	ND	104	106	1.9	102	100	2.0	70 - 130	30	
1,2-Dichlorobenzene	ND	109	107	1.9	108	103	4.7	70 - 130	30	
1,2-Dichloroethane	ND	95	94	1.1	89	88	1.1	70 - 130	30	
1,2-Dichloropropane	ND	112	112	0.0	108	107	0.9	70 - 130	30	
1,3,5-Trimethylbenzene	ND	113	111	1.8	110	103	6.6	70 - 130	30	
1,3-Dichlorobenzene	ND	112	110	1.8	112	106	5.5	70 - 130	30	
1,3-Dichloropropane	ND	105	107	1.9	104	103	1.0	70 - 130	30	
1,4-Dichlorobenzene	ND	111	108	2.7	110	104	5.6	70 - 130	30	
2,2-Dichloropropane	ND	91	109	18.0	98	98	0.0	70 - 130	30	
2-Chlorotoluene	ND	115	115	0.0	112	105	6.5	70 - 130	30	
2-Hexanone	ND	90	88	2.2	56	55	1.8	70 - 130	30	m
2-Isopropyltoluene	ND	111	110	0.9	110	103	6.6	70 - 130	30	
4-Chlorotoluene	ND	112	110	1.8	113	106	6.4	70 - 130	30	
4-Methyl-2-pentanone	ND	105	101	3.9	91	89	2.2	70 - 130	30	
Acetone	ND	105	85	21.1	44	<40	NC	70 - 130	30	m
Acrylonitrile	ND	108	110	1.8	104	102	1.9	70 - 130	30	
Benzene	ND	113	112	0.9	110	109	0.9	70 - 130	30	
Bromobenzene	ND	112	110	1.8	109	105	3.7	70 - 130	30	
Bromochloromethane	ND	95	106	10.9	92	90	2.2	70 - 130	30	
Bromodichloromethane	ND	103	103	0.0	99	97	2.0	70 - 130	30	
Bromoform	ND	109	109	0.0	98	97	1.0	70 - 130	30	
Bromomethane	ND	107	120	11.5	53	64	18.8	70 - 130	30	m
Carbon Disulfide	ND	117	118	0.9	96	95	1.0	70 - 130	30	
Carbon tetrachloride	ND	99	103	4.0	78	92	16.5	70 - 130	30	
Chlorobenzene	ND	111	111	0.0	109	105	3.7	70 - 130	30	
Chloroethane	ND	110	111	0.9	<40	<40	NC	70 - 130	30	m
Chloroform	ND	92	111	18.7	86	84	2.4	70 - 130	30	
Chloromethane	ND	108	116	7.1	93	102	9.2	70 - 130	30	
cis-1,2-Dichloroethene	ND	124	122	1.6	117	114	2.6	70 - 130	30	

Parameter	Blank	LCS %	LCSD %	LCS RPD	MS %	MSD %	MS RPD	% Rec Limits	% RPD Limits	
cis-1,3-Dichloropropene	ND	106	108	1.9	108	108	0.0	70 - 130	30	
Dibromochloromethane	ND	105	107	1.9	102	99	3.0	70 - 130	30	
Dibromomethane	ND	105	103	1.9	97	97	0.0	70 - 130	30	
Dichlorodifluoromethane	ND	115	118	2.6	97	97	0.0	70 - 130	30	
Ethylbenzene	ND	111	111	0.0	113	108	4.5	70 - 130	30	
Hexachlorobutadiene	ND	100	99	1.0	104	93	11.2	70 - 130	30	
Isopropylbenzene	ND	119	118	0.8	116	110	5.3	70 - 130	30	
m&p-Xylene	ND	115	115	0.0	115	110	4.4	70 - 130	30	
Methyl ethyl ketone	ND	87	86	1.2	51	46	10.3	70 - 130	30	m
Methyl t-butyl ether (MTBE)	ND	105	109	3.7	117	118	0.9	70 - 130	30	
Methylene chloride	ND	110	110	0.0	109	107	1.9	70 - 130	30	
Naphthalene	ND	102	102	0.0	101	97	4.0	70 - 130	30	
n-Butylbenzene	ND	110	110	0.0	109	99	9.6	70 - 130	30	
n-Propylbenzene	ND	120	119	0.8	117	110	6.2	70 - 130	30	
o-Xylene	ND	119	119	0.0	117	113	3.5	70 - 130	30	
p-Isopropyltoluene	ND	115	113	1.8	114	106	7.3	70 - 130	30	
sec-Butylbenzene	ND	111	110	0.9	111	104	6.5	70 - 130	30	
Styrene	ND	115	114	0.9	116	112	3.5	70 - 130	30	
tert-Butylbenzene	ND	113	112	0.9	109	103	5.7	70 - 130	30	
Tetrachloroethene	ND	114	114	0.0	111	106	4.6	70 - 130	30	
Tetrahydrofuran (THF)	ND	109	105	3.7	78	94	18.6	70 - 130	30	
Toluene	ND	112	110	1.8	109	105	3.7	70 - 130	30	
trans-1,2-Dichloroethene	ND	121	123	1.6	115	114	0.9	70 - 130	30	
trans-1,3-Dichloropropene	ND	102	107	4.8	104	103	1.0	70 - 130	30	
trans-1,4-dichloro-2-butene	ND	107	118	9.8	105	104	1.0	70 - 130	30	
Trichloroethene	ND	119	114	4.3	106	103	2.9	70 - 130	30	
Trichlorofluoromethane	ND	105	105	0.0	<40	<40	NC	70 - 130	30	m
Trichlorotrifluoroethane	ND	112	115	2.6	96	95	1.0	70 - 130	30	
Vinyl chloride	ND	118	121	2.5	117	116	0.9	70 - 130	30	
% 1,2-dichlorobenzene-d4	103	98	98	0.0	97	96	1.0	70 - 130	30	
% Bromofluorobenzene	96	98	99	1.0	98	97	1.0	70 - 130	30	
% Dibromofluoromethane	110	105	107	1.9	83	102	20.5	70 - 130	30	
% Toluene-d8	102	102	101	1.0	102	102	0.0	70 - 130	30	

Comment:

Additional 8260 criteria: 10% of compounds can be outside of acceptance criteria as long as recovery is 40-160%.

QA/QC Batch 231008, QC Sample No: BD80191 (BD80734, BD80735)

Semivolatiles - Ground Water

2-Methylnaphthalene	ND	78	79	1.3				30 - 130	20	
Acenaphthene	ND	81	79	2.5				30 - 130	20	
Acenaphthylene	ND	81	81	0.0				30 - 130	20	
Anthracene	ND	82	83	1.2				30 - 130	20	
Benz(a)anthracene	ND	88	87	1.1				30 - 130	20	
Benzo(a)pyrene	ND	86	86	0.0				30 - 130	20	
Benzo(b)fluoranthene	ND	96	100	4.1				30 - 130	20	
Benzo(ghi)perylene	ND	90	90	0.0				30 - 130	20	
Benzo(k)fluoranthene	ND	97	92	5.3				30 - 130	20	
Chrysene	ND	89	89	0.0				30 - 130	20	
Dibenz(a,h)anthracene	ND	85	85	0.0				30 - 130	20	
Fluoranthene	ND	91	92	1.1				30 - 130	20	
Fluorene	ND	90	90	0.0				30 - 130	20	
Indeno(1,2,3-cd)pyrene	ND	86	86	0.0				30 - 130	20	
Naphthalene	ND	85	86	1.2				30 - 130	20	

Parameter	Blank	LCS %	LCSD %	LCS RPD	MS %	MSD %	MS RPD	% Rec Limits	% RPD Limits	
Phenanthrene	ND	85	85	0.0				30 - 130	20	
Pyrene	ND	90	91	1.1				30 - 130	20	
% 2-Fluorobiphenyl	86	82	81	1.2				30 - 130	20	
% Nitrobenzene-d5	94	65	67	3.0				30 - 130	20	
% Terphenyl-d14	105	100	100	0.0				30 - 130	20	

Comment:

Additional 8270 criteria:20% of compounds can be outside of acceptance criteria as long as recovery is at least 10%. (Acid surrogates acceptance range for aqueous samples: 15-110%, for soils 30-130%)

QA/QC Batch 231171, QC Sample No: BD80709 (BD80733 (200X))

Volatiles - Soil

1,1,1,2-Tetrachloroethane	ND	104	102	1.9	97	98	1.0	70 - 130	30	
1,1,1-Trichloroethane	ND	103	102	1.0	101	101	0.0	70 - 130	30	
1,1,2,2-Tetrachloroethane	ND	91	93	2.2	99	105	5.9	70 - 130	30	
1,1,2-Trichloroethane	ND	106	105	0.9	100	102	2.0	70 - 130	30	
1,1-Dichloroethane	ND	109	108	0.9	108	107	0.9	70 - 130	30	
1,1-Dichloroethene	ND	115	114	0.9	110	113	2.7	70 - 130	30	
1,1-Dichloropropene	ND	109	107	1.9	102	102	0.0	70 - 130	30	
1,2,3-Trichlorobenzene	ND	92	89	3.3	58	54	7.1	70 - 130	30	m
1,2,3-Trichloropropane	ND	97	96	1.0	89	95	6.5	70 - 130	30	
1,2,4-Trichlorobenzene	ND	88	85	3.5	69	61	12.3	70 - 130	30	m
1,2,4-Trimethylbenzene	ND	106	103	2.9	<40	<40	NC	70 - 130	30	m
1,2-Dibromo-3-chloropropane	ND	91	96	5.3	90	95	5.4	70 - 130	30	
1,2-Dibromoethane	ND	100	99	1.0	95	98	3.1	70 - 130	30	
1,2-Dichlorobenzene	ND	99	96	3.1	44	<40	NC	70 - 130	30	m
1,2-Dichloroethane	ND	91	90	1.1	88	88	0.0	70 - 130	30	
1,2-Dichloropropane	ND	107	106	0.9	104	106	1.9	70 - 130	30	
1,3,5-Trimethylbenzene	ND	105	102	2.9	60	56	6.9	70 - 130	30	m
1,3-Dichlorobenzene	ND	100	97	3.0	84	80	4.9	70 - 130	30	
1,3-Dichloropropane	ND	102	101	1.0	96	98	2.1	70 - 130	30	
1,4-Dichlorobenzene	ND	97	95	2.1	75	68	9.8	70 - 130	30	m
2,2-Dichloropropane	ND	97	122	22.8	96	113	16.3	70 - 130	30	
2-Chlorotoluene	ND	107	104	2.8	62	56	10.2	70 - 130	30	m
2-Hexanone	ND	74	72	2.7	<40	<40	NC	70 - 130	30	m
2-Isopropyltoluene	ND	106	103	2.9	75	72	4.1	70 - 130	30	
4-Chlorotoluene	ND	101	99	2.0	67	59	12.7	70 - 130	30	m
4-Methyl-2-pentanone	ND	92	94	2.2	57	68	17.6	70 - 130	30	m
Acetone	ND	77	67	13.9	49	53	7.8	70 - 130	30	l,m
Acrylonitrile	ND	99	96	3.1	95	104	9.0	70 - 130	30	
Benzene	ND	109	108	0.9	88	86	2.3	70 - 130	30	
Bromobenzene	ND	103	101	2.0	50	40	22.2	70 - 130	30	m
Bromochloromethane	ND	114	112	1.8	88	112	24.0	70 - 130	30	
Bromodichloromethane	ND	99	99	0.0	96	97	1.0	70 - 130	30	
Bromoform	ND	102	101	1.0	92	96	4.3	70 - 130	30	
Bromomethane	ND	104	113	8.3	112	112	0.0	70 - 130	30	
Carbon Disulfide	ND	112	110	1.8	116	116	0.0	70 - 130	30	
Carbon tetrachloride	ND	100	100	0.0	99	100	1.0	70 - 130	30	
Chlorobenzene	ND	106	103	2.9	70	63	10.5	70 - 130	30	m
Chloroethane	ND	106	104	1.9	109	108	0.9	70 - 130	30	
Chloroform	ND	107	106	0.9	100	104	3.9	70 - 130	30	
Chloromethane	ND	105	110	4.7	107	110	2.8	70 - 130	30	
cis-1,2-Dichloroethene	ND	116	144	21.5	104	103	1.0	70 - 130	30	l
cis-1,3-Dichloropropene	ND	100	101	1.0	91	91	0.0	70 - 130	30	

QA/QC Data

SDG I.D.: GBD80732

Parameter	Blank	LCS %	LCSD %	LCS RPD	MS %	MSD %	MS RPD	% Rec Limits	% RPD Limits	
Dibromochloromethane	ND	102	102	0.0	92	95	3.2	70 - 130	30	
Dibromomethane	ND	100	100	0.0	91	93	2.2	70 - 130	30	
Dichlorodifluoromethane	ND	116	116	0.0	114	117	2.6	70 - 130	30	
Ethylbenzene	ND	107	105	1.9	66	57	14.6	70 - 130	30	m
Hexachlorobutadiene	ND	96	91	5.3	66	67	1.5	70 - 130	30	m
Isopropylbenzene	ND	114	112	1.8	71	64	10.4	70 - 130	30	m
m&p-Xylene	ND	109	106	2.8	63	53	17.2	70 - 130	30	m
Methyl ethyl ketone	ND	71	69	2.9	46	52	12.2	70 - 130	30	l,m
Methyl t-butyl ether (MTBE)	ND	100	102	2.0	111	114	2.7	70 - 130	30	
Methylene chloride	ND	104	100	3.9	111	111	0.0	70 - 130	30	
Naphthalene	ND	96	95	1.0	<40	<40	NC	70 - 130	30	m
n-Butylbenzene	ND	101	99	2.0	<40	<40	NC	70 - 130	30	m
n-Propylbenzene	ND	111	110	0.9	59	50	16.5	70 - 130	30	m
o-Xylene	ND	113	110	2.7	66	59	11.2	70 - 130	30	m
p-Isopropyltoluene	ND	108	105	2.8	67	62	7.8	70 - 130	30	m
sec-Butylbenzene	ND	106	105	0.9	64	59	8.1	70 - 130	30	m
Styrene	ND	108	105	2.8	<40	<40	NC	70 - 130	30	m
tert-Butylbenzene	ND	109	107	1.9	79	78	1.3	70 - 130	30	
Tetrachloroethene	ND	110	109	0.9	104	105	1.0	70 - 130	30	
Tetrahydrofuran (THF)	ND	97	97	0.0	94	106	12.0	70 - 130	30	
Toluene	ND	106	105	0.9	78	73	6.6	70 - 130	30	
trans-1,2-Dichloroethene	ND	115	112	2.6	111	109	1.8	70 - 130	30	
trans-1,3-Dichloropropene	ND	95	98	3.1	91	89	2.2	70 - 130	30	
trans-1,4-dichloro-2-butene	ND	95	102	7.1	78	80	2.5	70 - 130	30	
Trichloroethene	ND	119	113	5.2	103	103	0.0	70 - 130	30	
Trichlorofluoromethane	ND	103	102	1.0	104	102	1.9	70 - 130	30	
Trichlorotrifluoroethane	ND	111	110	0.9	113	113	0.0	70 - 130	30	
Vinyl chloride	ND	113	115	1.8	108	109	0.9	70 - 130	30	
% 1,2-dichlorobenzene-d4	104	99	98	1.0	98	99	1.0	70 - 130	30	
% Bromofluorobenzene	96	97	98	1.0	99	100	1.0	70 - 130	30	
% Dibromofluoromethane	112	104	103	1.0	109	111	1.8	70 - 130	30	
% Toluene-d8	102	101	102	1.0	103	101	2.0	70 - 130	30	

Comment:

Additional 8260 criteria: 10% of compounds can be outside of acceptance criteria as long as recovery is 40-160%.

QA/QC Batch 231371, QC Sample No: BD80734 (BD80734 (20X) , BD80735 (40X))

Volatiles - Ground Water

1,1,1,2-Tetrachloroethane	ND	84	86	2.4	86	86	0.0	70 - 130	30	
1,1,1-Trichloroethane	ND	83	82	1.2	84	82	2.4	70 - 130	30	
1,1,2,2-Tetrachloroethane	ND	83	84	1.2	92	91	1.1	70 - 130	30	
1,1,2-Trichloroethane	ND	89	89	0.0	89	86	3.4	70 - 130	30	
1,1-Dichloroethane	ND	85	85	0.0	88	85	3.5	70 - 130	30	
1,1-Dichloroethene	ND	81	80	1.2	85	80	6.1	70 - 130	30	
1,1-Dichloropropene	ND	80	79	1.3	78	76	2.6	70 - 130	30	
1,2,3-Trichlorobenzene	ND	86	86	0.0	85	90	5.7	70 - 130	30	
1,2,3-Trichloropropane	ND	82	84	2.4	92	91	1.1	70 - 130	30	
1,2,4-Trichlorobenzene	ND	82	83	1.2	83	86	3.6	70 - 130	30	
1,2,4-Trimethylbenzene	ND	78	80	2.5	78	76	2.6	70 - 130	30	
1,2-Dibromo-3-chloropropane	ND	82	81	1.2	88	89	1.1	70 - 130	30	
1,2-Dibromoethane	ND	87	89	2.3	91	89	2.2	70 - 130	30	
1,2-Dichlorobenzene	ND	84	85	1.2	85	84	1.2	70 - 130	30	
1,2-Dichloroethane	ND	89	87	2.3	88	86	2.3	70 - 130	30	
1,2-Dichloropropane	ND	84	85	1.2	87	85	2.3	70 - 130	30	

QA/QC Data

SDG I.D.: GBD80732

Parameter	Blank	LCS %	LCSD %	LCS RPD	MS %	MSD %	MS RPD	% Rec Limits	% RPD Limits	
1,3,5-Trimethylbenzene	ND	82	84	2.4	83	81	2.4	70 - 130	30	
1,3-Dichlorobenzene	ND	84	87	3.5	85	84	1.2	70 - 130	30	
1,3-Dichloropropane	ND	83	85	2.4	90	91	1.1	70 - 130	30	
1,4-Dichlorobenzene	ND	84	86	2.4	84	83	1.2	70 - 130	30	
2,2-Dichloropropane	ND	58	57	1.7	52	52	0.0	70 - 130	30	l,m
2-Chlorotoluene	ND	87	88	1.1	85	85	0.0	70 - 130	30	
2-Hexanone	ND	85	82	3.6	89	82	8.2	70 - 130	30	
2-Isopropyltoluene	ND	84	85	1.2	85	83	2.4	70 - 130	30	
4-Chlorotoluene	ND	84	86	2.4	85	85	0.0	70 - 130	30	
4-Methyl-2-pentanone	ND	89	91	2.2	91	91	0.0	70 - 130	30	
Acetone	ND	77	77	0.0	64	56	13.3	70 - 130	30	m
Acrylonitrile	ND	87	86	1.2	89	87	2.3	70 - 130	30	
Benzene	ND	80	81	1.2	79	77	2.6	70 - 130	30	
Bromobenzene	ND	86	88	2.3	87	86	1.2	70 - 130	30	
Bromochloromethane	ND	88	86	2.3	92	88	4.4	70 - 130	30	
Bromodichloromethane	ND	86	86	0.0	87	86	1.2	70 - 130	30	
Bromoform	ND	89	91	2.2	90	89	1.1	70 - 130	30	
Bromomethane	ND	91	94	3.2	66	70	5.9	70 - 130	30	m
Carbon Disulfide	ND	71	71	0.0	90	85	5.7	70 - 130	30	
Carbon tetrachloride	ND	81	82	1.2	72	74	2.7	70 - 130	30	
Chlorobenzene	ND	85	86	1.2	86	84	2.4	70 - 130	30	
Chloroethane	ND	81	82	1.2	89	83	7.0	70 - 130	30	
Chloroform	ND	87	86	1.2	90	85	5.7	70 - 130	30	
Chloromethane	ND	82	83	1.2	89	83	7.0	70 - 130	30	
cis-1,2-Dichloroethene	ND	86	86	0.0	90	83	8.1	70 - 130	30	
cis-1,3-Dichloropropene	ND	82	82	0.0	80	80	0.0	70 - 130	30	
Dibromochloromethane	ND	84	85	1.2	88	89	1.1	70 - 130	30	
Dibromomethane	ND	88	88	0.0	90	87	3.4	70 - 130	30	
Dichlorodifluoromethane	ND	76	76	0.0	80	75	6.5	70 - 130	30	
Ethylbenzene	ND	79	81	2.5	83	80	3.7	70 - 130	30	
Hexachlorobutadiene	ND	75	78	3.9	76	76	0.0	70 - 130	30	
Isopropylbenzene	ND	83	86	3.6	84	81	3.6	70 - 130	30	
m&p-Xylene	ND	80	81	1.2	84	80	4.9	70 - 130	30	
Methyl ethyl ketone	ND	89	88	1.1	98	90	8.5	70 - 130	30	
Methyl t-butyl ether (MTBE)	ND	76	77	1.3	90	91	1.1	70 - 130	30	
Methylene chloride	ND	83	83	0.0	92	87	5.6	70 - 130	30	
Naphthalene	ND	82	81	1.2	95	89	6.5	70 - 130	30	
n-Butylbenzene	ND	82	84	2.4	80	79	1.3	70 - 130	30	
n-Propylbenzene	ND	82	85	3.6	82	80	2.5	70 - 130	30	
o-Xylene	ND	87	88	1.1	85	82	3.6	70 - 130	30	
p-Isopropyltoluene	ND	82	84	2.4	82	80	2.5	70 - 130	30	
sec-Butylbenzene	ND	81	83	2.4	83	80	3.7	70 - 130	30	
Styrene	ND	88	89	1.1	87	84	3.5	70 - 130	30	
tert-Butylbenzene	ND	84	86	2.4	83	82	1.2	70 - 130	30	
Tetrachloroethene	ND	78	79	1.3	79	78	1.3	70 - 130	30	
Tetrahydrofuran (THF)	ND	89	89	0.0	96	92	4.3	70 - 130	30	
Toluene	ND	83	83	0.0	84	80	4.9	70 - 130	30	
trans-1,2-Dichloroethene	ND	84	83	1.2	87	82	5.9	70 - 130	30	
trans-1,3-Dichloropropene	ND	81	82	1.2	81	80	1.2	70 - 130	30	
trans-1,4-dichloro-2-butene	ND	72	78	8.0	73	73	0.0	70 - 130	30	
Trichloroethene	ND	84	84	0.0	84	82	2.4	70 - 130	30	
Trichlorofluoromethane	ND	78	77	1.3	82	78	5.0	70 - 130	30	
Trichlorotrifluoroethane	ND	74	72	2.7	78	74	5.3	70 - 130	30	

QA/QC Data

SDG I.D.: GBD80732

Parameter	Blank	LCS %	LCSD %	LCS RPD	MS %	MSD %	MS RPD	% Rec Limits	% RPD Limits
Vinyl chloride	ND	86	85	1.2	87	79	9.6	70 - 130	30
% 1,2-dichlorobenzene-d4	100	100	100	0.0	101	101	0.0	70 - 130	30
% Bromofluorobenzene	96	100	101	1.0	100	99	1.0	70 - 130	30
% Dibromofluoromethane	99	102	100	2.0	103	100	3.0	70 - 130	30
% Toluene-d8	101	101	102	1.0	98	99	1.0	70 - 130	30

Comment:

Additional 8260 criteria: 10% of compounds can be outside of acceptance criteria as long as recovery is 40-160%.

QA/QC Batch 231017, QC Sample No: BD80840 (BD80732, BD80733)

Polynuclear Aromatic HC - Soil

Acenaphthene	ND	70	69	1.4	72	76	5.4	30 - 130	30
Acenaphthylene	ND	74	76	2.7	74	79	6.5	30 - 130	30
Anthracene	ND	76	75	1.3	76	78	2.6	30 - 130	30
Benz(a)anthracene	ND	80	76	5.1	77	81	5.1	30 - 130	30
Benzo(a)pyrene	ND	75	73	2.7	77	81	5.1	30 - 130	30
Benzo(b)fluoranthene	ND	81	84	3.6	85	93	9.0	30 - 130	30
Benzo(ghi)perylene	ND	92	90	2.2	90	88	2.2	30 - 130	30
Benzo(k)fluoranthene	ND	86	79	8.5	91	94	3.2	30 - 130	30
Chrysene	ND	75	74	1.3	93	84	10.2	30 - 130	30
Dibenz(a,h)anthracene	ND	86	86	0.0	87	89	2.3	30 - 130	30
Fluoranthene	ND	77	74	4.0	83	86	3.6	30 - 130	30
Fluorene	ND	76	77	1.3	80	83	3.7	30 - 130	30
Indeno(1,2,3-cd)pyrene	ND	88	86	2.3	91	88	3.4	30 - 130	30
Naphthalene	ND	77	75	2.6	78	83	6.2	30 - 130	30
Phenanthrene	ND	80	78	2.5	79	82	3.7	30 - 130	30
Pyrene	ND	75	74	1.3	85	87	2.3	30 - 130	30
% 2-Fluorobiphenyl	68	69	69	0.0	76	81	6.4	30 - 130	30
% Nitrobenzene-d5	62	61	61	0.0	63	67	6.2	30 - 130	30
% Terphenyl-d14	80	80	78	2.5	94	96	2.1	30 - 130	30

Comment:

Additional 8270 criteria: 20% of compounds can be outside of acceptance criteria as long as recovery is at least 10%. (Acid surrogates acceptance range for aqueous samples: 15-110%, for soils 30-130%)

l = This parameter is outside laboratory lcs/lcsd specified recovery limits.
m = This parameter is outside laboratory ms/msd specified recovery limits.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

RPD - Relative Percent Difference
LCS - Laboratory Control Sample
LCSD - Laboratory Control Sample Duplicate
MS - Matrix Spike
MS Dup - Matrix Spike Duplicate
NC - No Criteria
Intf - Interference

Phyllis Shiller, Laboratory Director
May 23, 2013

Sample Criteria Exceedences Report

GBD80732 - EBC

Requested Criteria: 375, 375RRS, 375RS

State: NY

SampNo	Acode	Phoenix Analyte	Criteria	Result	RL	Criteria	RL Criteria	Analysis Units
BD80733	$8260MAR	Vinyl chloride	NY / 375-6.8 Volatiles / Residential	ND	1600	210	210	ug/Kg
BD80733	$8260MAR	Vinyl chloride	NY / 375-6.8 Volatiles / Residential Restricted	ND	1600	900	900	ug/Kg
BD80733	$8260MAR	Vinyl chloride	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	1600	20	20	ug/Kg
BD80733	$8260MAR	1,1-Dichloroethene	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	1600	330	330	ug/Kg
BD80733	$8260MAR	Acetone	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	31000	50	50	ug/Kg
BD80733	$8260MAR	Methylene chloride	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	1600	50	50	ug/Kg
BD80733	$8260MAR	trans-1,2-Dichloroethene	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	1600	190	190	ug/Kg
BD80733	$8260MAR	1,1-Dichloroethane	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	1600	270	270	ug/Kg
BD80733	$8260MAR	cis-1,2-Dichloroethene	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	1600	250	250	ug/Kg
BD80733	$8260MAR	Methyl Ethyl Ketone	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	9400	120	120	ug/Kg
BD80733	$8260MAR	Chloroform	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	1600	370	370	ug/Kg
BD80733	$8260MAR	1,1,1-Trichloroethane	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	1600	680	680	ug/Kg
BD80733	$8260MAR	Methyl t-butyl ether (MTBE)	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	3100	930	930	ug/Kg
BD80733	$8260MAR	Carbon tetrachloride	NY / 375-6.8 Volatiles / Residential	ND	1600	1400	1400	ug/Kg
BD80733	$8260MAR	Carbon tetrachloride	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	1600	760	760	ug/Kg
BD80733	$8260MAR	Benzene	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	1600	60	60	ug/Kg
BD80733	$8260MAR	1,2-Dichloroethane	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	1600	20	20	ug/Kg
BD80733	$8260MAR	Trichloroethene	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	1600	470	470	ug/Kg
BD80733	$8260MAR	Toluene	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	1600	700	700	ug/Kg
BD80733	$8260MAR	Tetrachloroethene	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	1600	1300	1300	ug/Kg
BD80733	$8260MAR	Chlorobenzene	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	1600	1100	1100	ug/Kg
BD80733	$8260MAR	Ethylbenzene	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	1600	1000	1000	ug/Kg
BD80733	$8260MAR	n-Propylbenzene	NY / 375-6.8 Volatiles / Unrestricted Use Soil	4500	1600	3900	3900	ug/Kg
BD80733	$8260MAR	1,2-Dichlorobenzene	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	1600	1100	1100	ug/Kg
BD80733	$8260MAR	Total Xylenes	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	1600	260	260	ug/Kg
BD80733	$8270SSR	Benz(a)anthracene	NY / 375-6.8 Semivolatiles / Residential	ND	3100	1000	1000	ug/Kg
BD80733	$8270SSR	Benz(a)anthracene	NY / 375-6.8 Semivolatiles / Residential Restricted	ND	3100	1000	1000	ug/Kg
BD80733	$8270SSR	Benz(a)anthracene	NY / 375-6.8 Semivolatiles / Unrestricted Use Soil	ND	3100	1000	1000	ug/Kg
BD80733	$8270SSR	Chrysene	NY / 375-6.8 Semivolatiles / Residential	ND	3100	1000	1000	ug/Kg
BD80733	$8270SSR	Chrysene	NY / 375-6.8 Semivolatiles / Unrestricted Use Soil	ND	3100	1000	1000	ug/Kg
BD80733	$8270SSR	Benzo(b)fluoranthene	NY / 375-6.8 Semivolatiles / Residential	ND	3100	1000	1000	ug/Kg
BD80733	$8270SSR	Benzo(b)fluoranthene	NY / 375-6.8 Semivolatiles / Residential Restricted	ND	3100	1000	1000	ug/Kg
BD80733	$8270SSR	Benzo(b)fluoranthene	NY / 375-6.8 Semivolatiles / Unrestricted Use Soil	ND	3100	1000	1000	ug/Kg
BD80733	$8270SSR	Benzo(k)fluoranthene	NY / 375-6.8 Semivolatiles / Residential	ND	3100	1000	1000	ug/Kg
BD80733	$8270SSR	Benzo(k)fluoranthene	NY / 375-6.8 Semivolatiles / Unrestricted Use Soil	ND	3100	800	800	ug/Kg
BD80733	$8270SSR	Benzo(a)pyrene	NY / 375-6.8 Semivolatiles / Residential	ND	3100	1000	1000	ug/Kg
BD80733	$8270SSR	Benzo(a)pyrene	NY / 375-6.8 Semivolatiles / Residential Restricted	ND	3100	1000	1000	ug/Kg
BD80733	$8270SSR	Benzo(a)pyrene	NY / 375-6.8 Semivolatiles / Unrestricted Use Soil	ND	3100	1000	1000	ug/Kg
BD80733	$8270SSR	Indeno(1,2,3-cd)pyrene	NY / 375-6.8 Semivolatiles / Residential	ND	3100	500	500	ug/Kg
BD80733	$8270SSR	Indeno(1,2,3-cd)pyrene	NY / 375-6.8 Semivolatiles / Residential Restricted	ND	3100	500	500	ug/Kg
BD80733	$8270SSR	Indeno(1,2,3-cd)pyrene	NY / 375-6.8 Semivolatiles / Unrestricted Use Soil	ND	3100	500	500	ug/Kg
BD80733	$8270SSR	Dibenz(a,h)anthracene	NY / 375-6.8 Semivolatiles / Residential	ND	3100	330	330	ug/Kg

Sample Criteria Exceedences Report

GBD80732 - EBC

Requested Criteria: 375, 375RRS, 375RS

State: NY

SampNo	Acode	Phoenix Analyte	Criteria	Result	RL	Criteria	RL Criteria	Analysis Units
BD80733	$8270SSR	Dibenz(a,h)anthracene	NY / 375-6.8 Semivolatiles / Residential Restricted	ND	3100	330	330	ug/Kg
BD80733	$8270SSR	Dibenz(a,h)anthracene	NY / 375-6.8 Semivolatiles / Unrestricted Use Soil	ND	3100	330	330	ug/Kg
BD80736	$8260MER	Vinyl chloride	NY / 375-6.8 Volatiles / Residential	ND	250	210	210	ug/Kg
BD80736	$8260MER	Vinyl chloride	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	250	20	20	ug/Kg
BD80736	$8260MER	Acetone	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	5000	50	50	ug/Kg
BD80736	$8260MER	Methylene chloride	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	500	50	50	ug/Kg
BD80736	$8260MER	trans-1,2-Dichloroethene	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	250	190	190	ug/Kg
BD80736	$8260MER	Methyl Ethyl Ketone	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	3000	120	120	ug/Kg
BD80736	$8260MER	Benzene	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	250	60	60	ug/Kg
BD80736	$8260MER	1,2-Dichloroethane	NY / 375-6.8 Volatiles / Unrestricted Use Soil	ND	250	20	20	ug/Kg

Phoenix Laboratories does not assume responsibility for the data contained in this report. It is provided as an additional tool to identify requested criteria exceedences. All efforts are made to ensure the accuracy of the data (obtained from appropriate agencies). A lack of exceedence information does not necessarily suggest conformance to the criteria. It is ultimately the site professional's responsibility to determine appropriate compliance.

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

NY Temperature Narration

May 23, 2013

SDG I.D.: GBD80732

The samples in this delivery group were received at 4°C.
(Note acceptance criteria is above freezing up to 6°C)

NY/NJ CHAIN OF CUSTODY RECORD

4°W/C+TP Temp Pg 1 of 1

PHOENIX
Environmental Laboratories, Inc.

587 East Middle Turnpike, P.O. Box 370, Manchester, CT 06040
Email: info@phoenixlabs.com Fax (860) 645-0823
Client Services (860) 645-8726

Data Delivery:
☐ Fax #:
☑ Email:

Customer: EBC
Address: 1808 Middle Country Road Ridge, NY

Project: 27-21 44th Drive
Report to: EBC
Invoice to:

Project P.O:
Phone #: (631) 504 6000
Fax #:

Client Sample - Information - Identification

Sampler's Signature: Date: 5-17-13

Matrix Code:
DW=drinking water WW=wastewater S=soil/solid O=oil
GW=groundwater SL=sludge A=air X=other

Analysis Request

Phoenix Sample #	Customer Sample Identification	Sample Matrix	Date Sampled	Time Sampled	VOCs 8260	SVOCs 8270 CP51 List	Soil Vial H2O	Soil VOA [ ] Methanol [ ] S. Bisulfate [ ] H2O	GL Soil container ( ) oz	GL Soil container ( ) oz	40 ml VOA Vial [ ] As is [ ] HCl	GL Amber 1000ml [ ] As is [ ] H2SO4	PL As is [ ] 250ml [ ] 500ml [ ] 1000ml	PL H2SO4 [ ] 250ml [ ] 500ml [ ] 1000ml	PL HNO3 250ml	PL NaOH 250ml	Bacteria Bottle
80732	B1 (5-8)	S	5-17-13		X	X		2	1	1							
80733	B2 (4-7)	S	"		"	"		2	1	1							
80734	GW1	GW	"		"	"					3	1					
80735	GW2	GW	"		"	"					3	1					
80736	Trip Blank w/ Ice							1									
80737	TB Low level							2									

Relinquished by:	Accepted by:	Date:	Time:
for RS	Crandice	5-17-13	12:00
		5/17/13	1500

Comments, Special Requirements or Regulations:

Turnaround:
☐ 1 Day*
☐ 2 Days*
☐ 3 Days*
☑ 5 Days
☐ 10 Days
☐ Other
* SURCHARGE APPLIES

NJ
☐ Res. Criteria
☐ Non-Res. Criteria
☐ Impact to GW Soil Cleanup Criteria
☐ GW Criteria

NY
☐ TOGS GA GW
☐ CP-51 Soil
☑ NY375 Unrestricted Soil
☑ NY375 Residential Soil
☑ NY375 Restricted Non-Residential Soil

Data Format
☐ Phoenix Std Report
☑ Excel
☑ PDF
☐ GIS/Key
☐ EQuIS
☐ NJ Hazsite EDD
☐ NY EZ EDD (ASP)
☐ Other

Data Package
☐ NJ Reduced Deliv. *
☐ NY Enhanced (ASP B) *
☐ Other

State where samples were collected: NY

APPENDIX D- ENVIRONMENTAL DATA RESOURCES INC. ™ REPORT

27-21 44th Drive and 44-18 Purves Street
44-18 Purves Street
Long Island City, NY 11101

Inquiry Number: 3798265.2s
December 02, 2013

The EDR Radius Map™ Report with GeoCheck®

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	942
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-8
Physical Setting Source Map Findings	A-9
Physical Setting Source Records Searched	A-31

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

44-18 PURVES STREET
LONG ISLAND CITY, NY 11101

COORDINATES

Latitude (North):	40.7467000 - 40˚ 44' 48.12''
Longitude (West):	73.9415000 - 73˚ 56' 29.40''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	589364.6
UTM Y (Meters):	4510966.5
Elevation:	14 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	40073-F8 BROOKLYN, NY
Most Recent Revision:	1995
North Map:	40073-G8 CENTRAL PARK, NY NJ
Most Recent Revision:	1995

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	2010, 2011
Source:	USDA

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL---------- National Priority List

EXECUTIVE SUMMARY

Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

CERCLIS ---------- Comprehensive Environmental Response, Compensation, and Liability Information System
FEDERAL FACILITY ---------- Federal Facility Site Information listing

Federal CERCLIS NFRAP site List

CERC-NFRAP ---------- CERCLIS No Further Remedial Action Planned

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROL ---------- Sites with Institutional Controls
LUCIS ---------- Land Use Control Information System

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State and tribal leaking storage tank lists

NY HIST LTANKS ---------- Listing of Leaking Storage Tanks
INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

NY TANKS ---------- Storage Tank Faciliy Listing
NY CBS UST ---------- Chemical Bulk Storage Database
NY MOSF AST ---------- Major Oil Storage Facilities Database
INDIAN UST ---------- Underground Storage Tanks on Indian Land
FEMA UST ---------- Underground Storage Tank Listing

State and tribal institutional control / engineering control registries

NY RES DECL ---------- Restrictive Declarations Listing

State and tribal voluntary cleanup sites

INDIAN VCP ---------- Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

NY ERP ---------- Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---------- A Listing of Brownfields Sites

EXECUTIVE SUMMARY

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9	Torres Martinez Reservation Illegal Dump Site Locations
ODI	Open Dump Inventory
NY SWRCY	Registered Recycling Facility List
NY SWTIRE	Registered Waste Tire Storage & Facility List
INDIAN ODI	Report on the Status of Open Dumps on Indian Lands

Local Lists of Hazardous waste / Contaminated Sites

US CDL	Clandestine Drug Labs
NY DEL SHWS	Delisted Registry Sites
US HIST CDL	National Clandestine Laboratory Register

Local Land Records

LIENS 2	CERCLA Lien Information
NY LIENS	Spill Liens Information

Records of Emergency Release Reports

HMIRS	Hazardous Materials Information Reporting System
NY Hist Spills	SPILLS Database
NY SPILLS 90	SPILLS 90 data from FirstSearch
NY SPILLS 80	SPILLS 80 data from FirstSearch

Other Ascertainable Records

DOT OPS	Incident and Accident Data
DOD	Department of Defense Sites
FUDS	Formerly Used Defense Sites
CONSENT	Superfund (CERCLA) Consent Decrees
ROD	Records Of Decision
UMTRA	Uranium Mill Tailings Sites
US MINES	Mines Master Index File
TRIS	Toxic Chemical Release Inventory System
TSCA	Toxic Substances Control Act
FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing
SSTS	Section 7 Tracking Systems
ICIS	Integrated Compliance Information System
PADS	PCB Activity Database System
MLTS	Material Licensing Tracking System
RADINFO	Radiation Information Database
RAATS	RCRA Administrative Action Tracking System
RMP	Risk Management Plans
NY HSWDS	Hazardous Substance Waste Disposal Site Inventory
NY UIC	Underground Injection Control Wells
NY AIRS	Air Emissions Data
INDIAN RESERV	Indian Reservations
SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing
NY COAL ASH	Coal Ash Disposal Site Listing
NY Financial Assurance	Financial Assurance Information Listing

LEAD SMELTERS ---------- Lead Smelter Sites
2020 COR ACTION ---------- 2020 Corrective Action Program List
COAL ASH EPA ---------- Coal Combustion Residues Surface Impoundments List
PRP ---------- Potentially Responsible Parties
PCB TRANSFORMER ---------- PCB Transformer Registration Database
US FIN ASSUR ---------- Financial Assurance Information
EPA WATCH LIST ---------- EPA WATCH LIST
COAL ASH DOE ---------- Steam-Electric Plant Operation Data

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP ---------- EDR Proprietary Manufactured Gas Plants

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal RCRA CORRACTS facilities list

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 07/11/2013 has revealed that there are 3 CORRACTS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ACTIVE STEEL DRUM CO INC	***52-30 34TH ST***	***SSE 1/2 - 1 (0.748 mi.)***	***237***	***751***
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
KOSAN INDUSTRIAL CORP	***5-49 49TH AVE***	***W 1/2 - 1 (0.599 mi.)***	***234***	***704***
CON EDISON - RAVENSWOOD TUNNEL	***3854 VERNON BLVD NW COR***	***N 1/2 - 1 (0.857 mi.)***	***AS241***	***840***

EXECUTIVE SUMMARY

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 07/11/2013 has revealed that there are 2 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROCKROSE CONSTRUCTION CORP	43-29 CRESCENT ST	NNW 1/8 - 1/4 (0.142 mi.)	N93	220
GOTHAM CENTER TOWER B-2	42-01 28TH STREET	NNE 1/8 - 1/4 (0.242 mi.)	AH177	491

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 07/11/2013 has revealed that there are 5 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
COURT SQUARE	***45-18 COURT SQ***	***WSW 0 - 1/8 (0.103 mi.)***	***H52***	***101***
MTA NYCT 11TH STREET & JACKSON	JACKSON AVE & 45TH AVE	W 1/8 - 1/4 (0.134 mi.)	J85	203
MTA NYCT - VENT PLANT 6406-7	JACKSON AVE & 45TH AVE	W 1/8 - 1/4 (0.134 mi.)	J86	205
KOREA NEWS	***42-22 27TH ST***	***NNE 1/8 - 1/4 (0.214 mi.)***	***W148***	***350***

Lower Elevation	Address	Direction / Distance	Map ID	Page
MTA NYCT - VENT PLANT 5103	HUNTER ST & 43RD AVE	N 0 - 1/8 (0.107 mi.)	G57	121

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 07/11/2013 has revealed that there are 8 RCRA-CESQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LIRR - HUNTERS POINT YARD	***SKILLMAN AVE & 27TH ST***	***SSE 1/8 - 1/4 (0.170 mi.)***	***115***	***265***
MTA NYCT - JACKSON & WEST SUBS	***28-20 JACKSON AVE***	***NE 1/8 - 1/4 (0.208 mi.)***	***V146***	***345***
SUBACCHI FURNITYRE-46-24 28TH	***46-24 28TH STREET***	***SSE 1/8 - 1/4 (0.216 mi.)***	***152***	***373***
IDEAL LABEL INC	***43-10 23RD ST 2ND FLOOR***	***NW 1/8 - 1/4 (0.225 mi.)***	***AC162***	***423***
LAGUARDIA COMMUNITY COLLEGE	***29-10 THOMSON AVE***	***ESE 1/8 - 1/4 (0.228 mi.)***	***AD165***	***443***
OUTLET CITY INC	***42-16 WEST ST***	***ENE 1/8 - 1/4 (0.230 mi.)***	***AE168***	***458***

Lower Elevation	Address	Direction / Distance	Map ID	Page
EAGLE ELECTRIC MANUFACTURING C	***45-31 COURT SQ***	***SW 1/8 - 1/4 (0.128 mi.)***	***M78***	***159***

Lower Elevation	Address	Direction / Distance	Map ID	Page
NYCT - FLUSHING AVENUE LINE (#	***DAVIS & 23RD ST***	***WSW 1/8 - 1/4 (0.224 mi.)***	***AB156***	***390***

State- and tribal - equivalent CERCLIS

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 11/13/2013 has revealed that there are 14 NY SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WILSON HANLEY, INC.	***21-11 44TH AVENUE***	***NW 1/4 - 1/2 (0.326 mi.)***	***195***	***540***
FRESH CLEANERS & LAUNDRY INC	***39-26 30TH ST***	***NE 1/2 - 1 (0.576 mi.)***	***233***	***688***
AMTRAK SUNNYSIDE YARD	***39-29 HONEYWELL STREET***	***NE 1/2 - 1 (0.620 mi.)***	***235***	***710***
Class Code: Significant threat to the public health or environment - action required.				
D D K PRO CLEANERS	***38-68 13TH ST***	***N 1/2 - 1 (0.712 mi.)***	***236***	***723***
JUNG SUN LAUNDRY SITE	***37-10 24TH STREET***	***NNE 1/2 - 1 (0.794 mi.)***	***238***	***759***
Class Code: Significant threat to the public health or environment - action required.				
STANDARD MOTOR PRODUCTS INC	***37-18 NORTHERN BLVD SIT***	***ENE 1/2 - 1 (0.898 mi.)***	***AT242***	***864***
Class Code: Significant threat to the public health or environment - action required.				
LEVCO METALS PROPERTY	***34-11 36TH STREET***	***NE 1/2 - 1 (0.959 mi.)***	***246***	***899***
KAUFMAN ASTORIA STUDIOS	***34-12 36TH ST***	***NE 1/2 - 1 (0.966 mi.)***	***247***	***907***

Lower Elevation	Address	Direction / Distance	Map ID	Page
NATIONAL RUBBER & BACKING CORP	***38-31 9TH ST***	***N 1/2 - 1 (0.834 mi.)***	***239***	***762***
Class Code: Significant threat to the public health or environment - action required.				
RAVENSWOOD POWER STATION	***38-54 VERNON BOULEVARD***	***N 1/2 - 1 (0.856 mi.)***	***AS240***	***781***
S & G WOODWORKING INC	***1155 MANHATTAN AVE - MA***	***SW 1/2 - 1 (0.944 mi.)***	***244***	***894***
FORMER MANHATTAN ADHESIVES PLA	425-459 GREENPOINT AVEN	S 1/2 - 1 (0.951 mi.)	245	898
FORMER NEY SMELTING AND REFINI	269 FREEMAN STREET	SSW 1/2 - 1 (0.981 mi.)	248	924
460 KINGSLAND AVENUE LLC	***460 KINGSLAND AVE***	***S 1/2 - 1 (0.991 mi.)***	***249***	***927***

NY VAPOR REOPENED: "Vapor intrusion" refers to the process by which volatile chemicals move from a subsurface source into the indoor air of overlying or adjacent buildings. The subsurface source can either be contaminated groundwater or contaminated soil which releases vapors into the pore spaces in the soil. Improvements in analytical techniques and knowledge gained from site investigations in New York and other states has led to an increased awareness of soil vapor as a medium of concern and of the potential for exposures from the soil vapor intrusion pathway. Based on this additional information, New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

A review of the NY VAPOR REOPENED list, as provided by EDR, and dated 01/01/2013 has revealed that

there is 1 NY VAPOR REOPENED site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
STANDARD MOTOR PRODUCTS, INC.	***37-18 NORTHERN BOULEVA***	***RENE 1/2 - 1 (0.898 mi.)***	***AT243***	***893***

State and tribal landfill and/or solid waste disposal site lists

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 10/08/2013 has revealed that there are 2 NY SWF/LF sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
C&H SAND AND STONE; CORP.	***21-16 JACKSON AVENUE***	***WSW 1/4 - 1/2 (0.343 mi.)***	***AL200***	***553***
UNITED WASTE REMOVAL;INC.	2116 JACKSON AVENUE	WSW 1/4 - 1/2 (0.344 mi.)	AL201	555

State and tribal leaking storage tank lists

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 09/25/2013 has revealed that there are 45 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
COURT PLAZA Spill Number/Closed Date: 1000528 / Not Reported	5 COURT SQUARE	WSW 0 - 1/8 (0.124 mi.)	H73	148
42-64 HUNTER STREET Spill Number/Closed Date: 9310213 / 11/22/1993	42-64 HUNTER STREET	NNE 1/8 - 1/4 (0.131 mi.)	L82	196
SPILL NUMBER 0303917 Spill Number/Closed Date: 0209560 / 2/17/2006 Spill Number/Closed Date: 0303917 / 1/7/2004	26-32 SKILLMAN AVE	S 1/8 - 1/4 (0.187 mi.)	U131	313
MID TOWN OPERATING COMPANY TTF Spill Number/Closed Date: 0911288 / 1/21/2010	42-50 24TH ST	NNW 1/8 - 1/4 (0.222 mi.)	Z154	387
OUTLET CITY INC Spill Number/Closed Date: 9600688 / 5/27/2003	***42-16 WEST ST***	***ENE 1/8 - 1/4 (0.230 mi.)***	***AE168***	***458***
ON SIDEWALK Spill Number/Closed Date: 0110585 / 7/31/2003	47-15 PEARSON PL	SSW 1/4 - 1/2 (0.263 mi.)	AJ188	510
J MANHEIMER INC Spill Number/Closed Date: 9206718 / 7/29/1993	***47-22 PEARSON PL***	***SSW 1/4 - 1/2 (0.275 mi.)***	***AJ190***	***513***
CONDEA SUPPLY CORP Spill Number/Closed Date: 0306979 / 6/21/2006	21-21 44TH RD	WNW 1/4 - 1/2 (0.280 mi.)	191	517
FALIDAS ASSCOCIATES	***25-01 QUEENS PLAZA N***	***NNE 1/4 - 1/2 (0.302 mi.)***	***192***	***518***
SPILL NUMBER 0012047 Spill Number/Closed Date: 0012047 / 10/30/2003	21ST ST/44TH RD	WNW 1/4 - 1/2 (0.330 mi.)	198	551

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LA GUARDIA COMMUNITY COLLEGE	***31-10 THOMSON AVE***	***ESE 1/4 - 1/2 (0.352 mi.)***	***202***	***556***
Spill Number/Closed Date: 0110443 / 1/31/2002				
OFFICE BUILDING	29-27 NORTHERN BLVD	NE 1/4 - 1/2 (0.361 mi.)	203	570
Spill Number/Closed Date: 0612458 / 2/16/2007				
GETTY #344	***31-05 QUEENS BOULEVARD***	***E 1/4 - 1/2 (0.379 mi.)***	***AM204***	***571***
Spill Number/Closed Date: 0612273 / 2/8/2007				
GETTY S/S #344 - GETTY PROPERT	***31-05 QUEENS BLVD***	***E 1/4 - 1/2 (0.379 mi.)***	***AM205***	***596***
Spill Number/Closed Date: 9909630 / 12/2/2004				
Spill Number/Closed Date: 0009849 / 1/5/2007				
BLACK BEAR COMPANY	27-10 HUNTERS POINT AVE	S 1/4 - 1/2 (0.398 mi.)	206	605
Spill Number/Closed Date: 0501474 / 8/16/2005				
LOVOUR HOME	2512 41ST AVE	NNE 1/4 - 1/2 (0.399 mi.)	AN207	606
Spill Number/Closed Date: 0700688 / 2/17/2010				
APRT	2403 41ST AVE	NNE 1/4 - 1/2 (0.417 mi.)	AO208	608
Spill Number/Closed Date: 0711618 / 4/2/2008				
CLOSED-LACKOF RECENT INFO	40-40 CRESCENT ST	NNE 1/4 - 1/2 (0.419 mi.)	AN209	609
Spill Number/Closed Date: 9105613 / 3/14/2003				
24-03 41ST AVE	***24-03 41ST AVE***	***NNE 1/4 - 1/2 (0.420 mi.)***	***AO210***	***610***
Spill Number/Closed Date: 8709565 / 2/25/1993				
MANHOLE 14413	***QUEENS PLAZA NORTH***	***NNW 1/4 - 1/2 (0.421 mi.)***	***211***	***614***
Spill Number/Closed Date: 0100062 / 6/16/2003				
STRUCTURAL DISPLAY CO., INC	12-12 23RD AVENUE	NW 1/4 - 1/2 (0.425 mi.)	212	616
Spill Number/Closed Date: 9814023 / 9/5/2012				
INTERNATIONAL MASONRY INS	12-07 44TH AVE	WNW 1/4 - 1/2 (0.428 mi.)	213	625
Spill Number/Closed Date: 0103153 / 3/31/2006				
GULF MOKIN GAS	***23-01 41ST AVE***	***N 1/4 - 1/2 (0.437 mi.)***	***216***	***629***
Spill Number/Closed Date: 0308076 / 1/7/2004				
Spill Number/Closed Date: 0808735 / 8/28/2009				
32-32 QUEENS BLVD/SUNOCO	32-32 QUEENS BLVD	ESE 1/4 - 1/2 (0.453 mi.)	218	634
Spill Number/Closed Date: 8905358 / Not Reported				
MONARCH CONSTUCTION	11-17 43RD AVE	NW 1/4 - 1/2 (0.455 mi.)	219	638
Spill Number/Closed Date: 9516355 / 3/20/1996				
32-00 SKILLMAN AVE	32-00 SKILLMAN AVE	E 1/4 - 1/2 (0.460 mi.)	AP221	645
Spill Number/Closed Date: 0302379 / 7/29/2005				
CLOSED-LACKOF RECENT INFO	***32-00 SKILLMAN AVE***	***E 1/4 - 1/2 (0.460 mi.)***	***AP222***	***646***
Spill Number/Closed Date: 9207976 / 3/6/2003				
SPILL NUMBER 0103168	***10-20 44TH RD***	***WNW 1/4 - 1/2 (0.465 mi.)***	***AQ223***	***651***
Spill Number/Closed Date: 0103168 / 8/27/2002				
10-22 44TH RD	10-22 44TH ROAD	WNW 1/4 - 1/2 (0.465 mi.)	AQ224	667
Spill Number/Closed Date: 9411116 / 1/20/1995				
NYCTA - SUPERIOR REED BLDG	***29-50 NORTHERN BLVD***	***NE 1/4 - 1/2 (0.473 mi.)***	***225***	***669***
Spill Number/Closed Date: 9100729 / 11/30/2000				
RESIDANCE	1120 43RD ROAD	NW 1/4 - 1/2 (0.473 mi.)	AR226	672
Spill Number/Closed Date: 0708879 / 12/19/2007				
X	11-20 43RD RD	NW 1/4 - 1/2 (0.473 mi.)	AR227	674
Spill Number/Closed Date: 0210116 / 2/28/2006				
COMMERCIAL BUILDING	40-23 24TH ST'	NNE 1/4 - 1/2 (0.478 mi.)	229	683
Spill Number/Closed Date: 0506977 / 1/5/2006				

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
43-41 32ND PLACE Spill Number/Closed Date: 9303078 / 6/25/1993	43-41 32ND PLACE	E 1/4 - 1/2 (0.481 mi.)	AP230	684
KAL REALTY Spill Number/Closed Date: 9806658 / 6/15/2005	29-24 40TH AVE	NE 1/4 - 1/2 (0.497 mi.)	231	685
CLOSED-LACKOF RECENT INFO Spill Number/Closed Date: 8709369 / 3/13/2003	29024 40TH AVENUE	NE 1/4 - 1/2 (0.499 mi.)	232	687

Lower Elevation	Address	Direction / Distance	Map ID	Page
SPILL NUMBER 0105318 Spill Number/Closed Date: 0105318 / 6/30/2003	***43-09 HUNTERS STREET***	***NNW 0 - 1/8 (0.101 mi.)***	***F47***	***94***
TAXI STAND Spill Number/Closed Date: 0713239 / 4/22/2008	22-10 JACKSON AVE	WSW 1/4 - 1/2 (0.316 mi.)	194	538
47-20 30TH ST Spill Number/Closed Date: 8708435 / 11/2/1992	47-20 30TH ST	SE 1/4 - 1/2 (0.327 mi.)	AK196	545
I G FEDERAL ELECTRICAL SUPPLY Spill Number/Closed Date: 0110569 / 3/1/2002	***47-20 30TH ST***	***SE 1/4 - 1/2 (0.327 mi.)***	***AK197***	***546***
ST. FRANCIS OF ASSISI Spill Number/Closed Date: 8704696 / 1/25/1989	45-02 21ST AVE.	W 1/4 - 1/2 (0.338 mi.)	199	552
ANDREA ELECTRONICS Spill Number/Closed Date: 9709895 / 12/17/2002	***11-40 45TH DRIVE***	***W 1/4 - 1/2 (0.432 mi.)***	***214***	***626***
11-15 45TH AVENUE Spill Number/Closed Date: 9402499 / 5/20/1994	11-15 45TH AVENUE	W 1/4 - 1/2 (0.437 mi.)	215	628
SPILL NUMBER 0208486 Spill Number/Closed Date: 0208486 / 11/17/2003	23-30 50TH AVE	SSW 1/4 - 1/2 (0.453 mi.)	217	632
THYPIN STEEL Spill Number/Closed Date: 9312128 / 1/14/1994	***49-49 30TH STREET***	***SSE 1/4 - 1/2 (0.474 mi.)***	***228***	***675***

State and tribal registered storage tank lists

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, and dated 11/13/2013 has revealed that there are 16 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CAB MANAGEMENT CORP	27-34 JACKSON AVENUE	NE 0 - 1/8 (0.112 mi.)	E62	129
CITICORP AT COURT SQUARE	25-01 JACKSON AVENUE	WSW 0 - 1/8 (0.123 mi.)	H70	140
43-00 CRESCENT ST.	***43-00 CRESCENT ST***	***NNW 1/8 - 1/4 (0.155 mi.)***	***N102***	***239***
21-45 44TH DRIVE	21-45 44TH DRIVE	WNW 1/8 - 1/4 (0.167 mi.)	O109	255
SATT REALTY CORP.	***26-32 SKILLMAN AVENUE***	***S 1/8 - 1/4 (0.187 mi.)***	***U130***	***309***
BAGWIN BROTHERS SERVICE CENTER	42-37 CRESCENT STREET	N 1/8 - 1/4 (0.198 mi.)	X140	333
PARKING LOT	***23-14 44TH ROAD***	***NW 1/8 - 1/4 (0.202 mi.)***	***144***	***339***
OUTLET CITY INC	***42-16 WEST ST***	***ENE 1/8 - 1/4 (0.230 mi.)***	***AE169***	***468***
GANDER & WHITE SHIPPING, INC.	***21-44 44TH ROAD***	***WNW 1/8 - 1/4 (0.231 mi.)***	***170***	***474***
KRK EXPEDITING CO INC	42-21 CRESCENT ST	N 1/8 - 1/4 (0.235 mi.)	AG173	482

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MIDTOWN OPERATING CORP	42-50 24TH STREET	N 1/8 - 1/4 (0.238 mi.)	Z176	487
42-15 CRESENT ST	42-15 CRESCENT STREET	N 1/8 - 1/4 (0.245 mi.)	AG184	505

Lower Elevation	Address	Direction / Distance	Map ID	Page
GASGO PETROLEUM INC	27-01 JACKSON AVENUE	NNE 0 - 1/8 (0.060 mi.)	D35	57
CITYWIDE SELF STORAGE	45-55 PEARSON STREET	SW 1/8 - 1/4 (0.171 mi.)	Q117	273
GAP REALTY CO	***45-56 PEARSON ST***	***SW 1/8 - 1/4 (0.193 mi.)***	***135***	***322***
FORDHAM ROAD CONCRETE	47-17 27TH STREET	SSE 1/8 - 1/4 (0.245 mi.)	AI181	497

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, and dated 11/13/2013 has revealed that there are 25 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LONG ISLAND CITY COURTHOUSE	25-10 COURTHOUSE SQUAREW	0 - 1/8 (0.078 mi.)	37	67
MINI M,ICRO SUPPLI INC	27-35 JACKSON AVE	NE 0 - 1/8 (0.109 mi.)	E61	126
CAB MANAGEMENT CORP	27-34 JACKSON AVENUE	NE 0 - 1/8 (0.112 mi.)	E63	131
CITICORP AT COURT SQUARE	25-01 JACKSON AVENUE	WSW 0 - 1/8 (0.123 mi.)	H68	137
5 COURT SQUARE	***5 COURT SQUARE***	***WSW 0 - 1/8 (0.124 mi.)***	***H72***	***144***
2415 44TH ROAD LLC	***43-32 CRESCENT STREET***	***NNW 1/8 - 1/4 (0.140 mi.)***	***N90***	***210***
KATT CORPORATION	43-29 CRESCENT STREET	NNW 1/8 - 1/4 (0.142 mi.)	N94	221
TWO COURT SQUARE	23-21 44 DRIVE	WNW 1/8 - 1/4 (0.143 mi.)	O95	224
4308 CRESCENT STREET	4308 CRESCENT STREET	NNW 1/8 - 1/4 (0.151 mi.)	N99	230
2415 44TH ROAD LLC	24-15 44TH ROAD	NW 1/8 - 1/4 (0.156 mi.)	P105	248
RML CO.	***24-20 JACKSON AVENUE***	***WSW 1/8 - 1/4 (0.171 mi.)***	***R120***	***281***
EAGLE ELECTRIC MFG CO INC	***43-35 24TH STREET***	***NNW 1/8 - 1/4 (0.180 mi.)***	***126***	***302***
MORBECK CORP	***24-15 43 AVE***	***NNW 1/8 - 1/4 (0.189 mi.)***	***132***	***315***
STAR JOURNAL BUILDING	42-26 28TH STREET	NNE 1/8 - 1/4 (0.194 mi.)	137	329
BRANCO LEATHER INC	***44-02 23RD ST***	***NW 1/8 - 1/4 (0.216 mi.)***	***151***	***370***
KASSABIAN REALTY LLC	***43-10 23RD ST***	***NW 1/8 - 1/4 (0.225 mi.)***	***AC161***	***420***
LAGUARDIA COMMUNITY COLLEGE	29-10 THOMSON AVENUE	ESE 1/8 - 1/4 (0.228 mi.)	AD166	453
23-10 43TH AVE	***23-10 43TH AVE***	***NNW 1/8 - 1/4 (0.231 mi.)***	***AF171***	***477***
42-15 CRESENT ST	42-15 CRESCENT STREET	N 1/8 - 1/4 (0.245 mi.)	AG183	503
TWO GOTHAM CENTER	42-09 28TH ST	NNE 1/8 - 1/4 (0.245 mi.)	AH185	507

Lower Elevation	Address	Direction / Distance	Map ID	Page
45-30 COURT SQUARE	***45-30 COURT SQUARE***	***SW 1/8 - 1/4 (0.128 mi.)***	***M79***	***187***
EAGLE ELECTRIC MFG CO INC	***45-31 COURT SQ***	***SW 1/8 - 1/4 (0.128 mi.)***	***M81***	***192***
45-17 PEARSON ST 45-18 CRT SQ	***45-17 PEARSON ST (45-18***	***SW 1/8 - 1/4 (0.166 mi.)***	***Q108***	***250***
CITYWIDE SELF STORAGE	45-55 PEARSON STREET	SW 1/8 - 1/4 (0.171 mi.)	Q118	277
46-20 27TH STREET LLC	46-20 27TH STREET	SSE 1/8 - 1/4 (0.199 mi.)	Y143	337

NY CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there are 3 NY CBS AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
44-43 PURVES ST	*44-43 PURVES ST*	*ESE 0 - 1/8 (0.040 mi.)*	*A9*	*14*
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
EAGLE ELECTRIC MANUFACTURING C	*45-31 COURT SQ*	*SW 1/8 - 1/4 (0.128 mi.)*	*M78*	*159*
ANTHONY CONCRETE	*47-17 27TH ST*	*SSE 1/8 - 1/4 (0.245 mi.)*	*AI180*	*495*

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 11/13/2013 has revealed that there are 3 NY CBS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
44-43 PURVES ST	*44-43 PURVES ST*	*ESE 0 - 1/8 (0.040 mi.)*	*A9*	*14*
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
EAGLE ELECTRIC MANUFACTURING C	*45-31 COURT SQ*	*SW 1/8 - 1/4 (0.128 mi.)*	*M78*	*159*
ANTHONY CONCRETE	*47-17 27TH ST*	*SSE 1/8 - 1/4 (0.245 mi.)*	*AI180*	*495*

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: Environmental Remediation sites that have engineering controls in place.

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 11/13/2013 has revealed that there is 1 NY ENG CONTROLS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
21-16 44TH RD	*21-16 44TH RD*	*WNW 1/4 - 1/2 (0.306 mi.)*	*193*	*524*

Environmental Remediation sites that have institutional controls in place.

A review of the NY INST CONTROL list, as provided by EDR, and dated 11/13/2013 has revealed that there is 1 NY INST CONTROL site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
21-16 44TH RD	*21-16 44TH RD*	*WNW 1/4 - 1/2 (0.306 mi.)*	*193*	*524*

State and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, and dated 11/13/2013 has revealed that there are 3 NY VCP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
OUTLET CITY, QUEENS BLVD. & JA	QUEENS BLVD. & JACKSON	NE 1/4 - 1/2 (0.268 mi.)	189	511
21-16 44TH RD	***21-16 44TH RD***	***WNW 1/4 - 1/2 (0.306 mi.)***	***193***	***524***
CLOSED-LACKOF RECENT INFO	***32-00 SKILLMAN AVE***	***E 1/4 - 1/2 (0.460 mi.)***	***AP222***	***646***

State and tribal Brownfields sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 11/13/2013 has revealed that there are 2 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
QUEENS PLAZA RESIDENTIAL DEVEL	28-10 JACKSON AVENUE	NE 1/8 - 1/4 (0.193 mi.)	V133	321
SWINGSTELL, LLC	***32-00 SKILLMAN AVENUE***	***E 1/4 - 1/2 (0.460 mi.)***	***AP220***	***639***

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Registered Storage Tanks

NY HIST UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY HIST UST list, as provided by EDR, and dated 01/01/2002 has revealed that there are 7 NY HIST UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
43-00 CRESCENT ST.	***43-00 CRESCENT ST***	***NNW 1/8 - 1/4 (0.155 mi.)***	***N102***	***239***
SATT REALTY CORP.	***26-32 SKILLMAN AVENUE***	***S 1/8 - 1/4 (0.187 mi.)***	***U130***	***309***
PARKING LOT	***23-14 44TH ROAD***	***NW 1/8 - 1/4 (0.202 mi.)***	***144***	***339***
OUTLET CITY INC	***42-16 WEST ST***	***ENE 1/8 - 1/4 (0.230 mi.)***	***AE169***	***468***
GANDER & WHITE SHIPPING, INC.	***21-44 44TH ROAD***	***WNW 1/8 - 1/4 (0.231 mi.)***	***170***	***474***
42-15 CRESENT ST	42-15 CRESCENT ST	N 1/8 - 1/4 (0.245 mi.)	AG182	501

Lower Elevation	Address	Direction / Distance	Map ID	Page
GAP REALTY CO	***45-56 PEARSON ST***	***SW 1/8 - 1/4 (0.193 mi.)***	***135***	***322***

EXECUTIVE SUMMARY

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 09/25/2013 has revealed that there are 17 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MANHOLE # 514 Spill Number/Closed Date: 0003644 / 9/27/2001	44-27 PERVES ST	ESE 0 - 1/8 (0.034 mi.)	A4	10
COMMERCIAL LOT Spill Number/Closed Date: 0706566 / 10/17/2007	44 -15 PURVIS STREET	NE 0 - 1/8 (0.038 mi.)	A6	11
44-43 PURVES ST Spill Number/Closed Date: 9713189 / 5/14/1998	***44-43 PURVES ST***	***ESE 0 - 1/8 (0.040 mi.)***	***A9***	***14***
VAULT#3073 Spill Number/Closed Date: 0506520 / 1/10/2008	2740 THOMASON AVE	S 0 - 1/8 (0.046 mi.)	B17	26
SPILL NUMBER 0208224 Spill Number/Closed Date: 0208224 / 11/8/2002	JACKSON AV & 44TH DR	WNW 0 - 1/8 (0.057 mi.)	C33	54
MANHOLE # 2353 Spill Number/Closed Date: 0409173 / 1/13/2005	JACKSON VAE/DUTCHKILL S	NNE 0 - 1/8 (0.089 mi.)	E40	76
43-40 COURT SQUARE / QUEE Spill Number/Closed Date: 8702187 / 6/17/1987	43-40 COURT SQUARE	WSW 0 - 1/8 (0.107 mi.)	H58	122
DUTCH KILL/SCRAP YARD Spill Number/Closed Date: 9204680 / 7/23/1992	DUTCH KILL	ESE 0 - 1/8 (0.113 mi.)	64	133
MINI MICRO Spill Number/Closed Date: 0108045 / 11/14/2001	27-35 JACKSON AVE	NNE 0 - 1/8 (0.121 mi.)	I67	135
1 COURT SQUARE Spill Number/Closed Date: 9110791 / 1/17/1992	1 COURT SQUARE	WSW 0 - 1/8 (0.123 mi.)	H69	139
MANHOLE 4440 Spill Number/Closed Date: 9901252 / 1/7/2000	4327 QUEENS ST	ENE 0 - 1/8 (0.124 mi.)	K71	143

Lower Elevation	Address	Direction / Distance	Map ID	Page
CONED MANHOLE#515 Spill Number/Closed Date: 0405105 / 10/23/2006	PURVES STREET/JACKSON	N 0 - 1/8 (0.051 mi.)	D27	44
COMMERCIAL AREA Spill Number/Closed Date: 0405305 / 10/28/2004	PERVES ST/ OF JACKSON A	N 0 - 1/8 (0.053 mi.)	D29	48
RESIDENTS Spill Number/Closed Date: 0208454 / 9/29/2003	10-33 JACKSON AVE	N 0 - 1/8 (0.055 mi.)	D30	49
GASGO Spill Number/Closed Date: 9913082 / Not Reported	27-01 JACKSON AVE	NNE 0 - 1/8 (0.079 mi.)	38	70
SPILL NUMBER 0105318 Spill Number/Closed Date: 9809062 / 10/21/1998	***43-09 HUNTERS STREET***	***NNW 0 - 1/8 (0.101 mi.)***	***F47***	***94***
49 HUNTER PLACE/S.I. Spill Number/Closed Date: 9011053 / 1/17/1991	49 HUNTER PLACE	NNW 0 - 1/8 (0.101 mi.)	F49	99

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 07/11/2013 has revealed that there are 35 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
S N B INC	***44-16 PURVES ST***	***E 0 - 1/8 (0.030 mi.)***	***A2***	***8***
A A A STAMP & SEAL	***26-20 JACKSON AVE***	***N 0 - 1/8 (0.041 mi.)***	***D12***	***18***
A-1 AUTO COLLISION INC	***2831 THOMSON AVE***	***SSE 0 - 1/8 (0.045 mi.)***	***B16***	***23***
NYCTA	***44TH DR & JACKSON AVE***	***WNW 0 - 1/8 (0.057 mi.)***	***C34***	***55***
NYSDOT - THOMSON AVENUE BRIDGE	***JACKSON AVE & DUTCH KIL***	***NNE 0 - 1/8 (0.089 mi.)***	***E41***	***77***
NYCT - COURT SQUARE STA G LINE	***JACKSON ST & COURT SQ***	***W 1/8 - 1/4 (0.134 mi.)***	***J84***	***197***
KENT BRAGALINE INC	***27-45 JACKSON AVE***	***NE 1/8 - 1/4 (0.135 mi.)***	***I89***	***208***
AEROSOURCE INC	***25-19 43RD AVE***	***NNW 1/8 - 1/4 (0.151 mi.)***	***N98***	***227***
FEDERAL PACIFIC ELECTRIC CO	***4300 CRESCENT ST***	***NNW 1/8 - 1/4 (0.155 mi.)***	***N101***	***234***
CLEANCO INDUSTRIAL SERVICES OF	***10-39 44TH DR***	***WNW 1/8 - 1/4 (0.167 mi.)***	***O110***	***257***
DENTSPLY TRU-BYTE	10-39 44TH DR	WNW 1/8 - 1/4 (0.167 mi.)	O111	258
ROSS WATCH CASE CORP	***21-30-42 44TH DR***	***WNW 1/8 - 1/4 (0.167 mi.)***	***O112***	***260***
JAGUAR GOLD PRODUCT	***21-30 44TH DR***	***WNW 1/8 - 1/4 (0.167 mi.)***	***O113***	***261***
E ZAPPI DERMATOPATHOLOGY LAB I	***21-51 44TH DR***	***WNW 1/8 - 1/4 (0.167 mi.)***	***O114***	***263***
INTERNATIONAL DESIGN CENTER	***29-10 THOMPSON AVE 9TH***	***SE 1/8 - 1/4 (0.175 mi.)***	***S121***	***285***
NYSDOT G CAMPBELL PAINTING D25	***THOMPSON AVE BRIDGE***	***ESE 1/8 - 1/4 (0.176 mi.)***	***S122***	***286***
PERENNIALLY GREEN INC	***23-13 44TH DR***	***WNW 1/8 - 1/4 (0.177 mi.)***	***123***	***288***
J BROTHERS AUTO BODY INC	***28-20 42ND RD***	***NE 1/8 - 1/4 (0.180 mi.)***	***T127***	***306***
ANOCA PLATING SERVICE CORP	***27-04 42ND RD***	***NNE 1/8 - 1/4 (0.194 mi.)***	***W136***	***328***
CON EDISON MANHOLE 954	***47TH ST & SKILLMAN AVE***	***S 1/8 - 1/4 (0.197 mi.)***	***138***	***331***
EPPY PLATING	***42-40 CRESCENT ST***	***N 1/8 - 1/4 (0.198 mi.)***	***X142***	***336***
STANDARD FINISHING CO INC	***43-10 23RD ST 2ND FLOOR***	***NW 1/8 - 1/4 (0.225 mi.)***	***AC159***	***413***
GRUBER DISPLAY COMPANY	***43-10 23RD ST***	***NW 1/8 - 1/4 (0.225 mi.)***	***AC160***	***418***
SCRIPTO EVERGLIDE	***29-10 THOMSON AVE***	***ESE 1/8 - 1/4 (0.228 mi.)***	***AD164***	***440***
BURNHAM PRODUCTS CORP	***42-24 ORCHARD ST***	***ESE 1/8 - 1/4 (0.228 mi.)***	***AD167***	***457***
MTA NYCT - COURT SQUARE EFA LI	***23RD ST & 43RD RD***	***NNW 1/8 - 1/4 (0.236 mi.)***	***AF174***	***484***
CON ED - V 7677	W/S 24 ST/42 RD	N 1/8 - 1/4 (0.246 mi.)	186	509

Lower Elevation	Address	Direction / Distance	Map ID	Page
SEAL-KAP PACKAGING INC	***11-5 44TH DR***	***N 0 - 1/8 (0.048 mi.)***	***D23***	***38***
CENTRALIZED LAB SERVICES INC	***43-25 HUNTER ST***	***NNW 0 - 1/8 (0.100 mi.)***	***F44***	***85***
ROGERS ENGRAVING CO INC	***45-61 COURT SQ***	***SW 1/8 - 1/4 (0.128 mi.)***	***M80***	***190***
STERNBERGER MOTOR - G A P REAL	***45-55 PEARSON ST APT U***	***SW 1/8 - 1/4 (0.171 mi.)***	***Q119***	***279***
MATSON MFG CO INC	***45-17 PEARSON ST***	***SW 1/8 - 1/4 (0.177 mi.)***	***Q124***	***291***
MICHELANGELO SCULPTURE	***27-01 47TH AVE***	***SSE 1/8 - 1/4 (0.218 mi.)***	***Y153***	***385***
CITY SPORTS & GRAPHIC	***45-12 DAVIS ST***	***WSW 1/8 - 1/4 (0.224 mi.)***	***AA155***	***388***
MTA NYCT - COURT HOUSE SQ STA	***JACKSON AVE & 23RD ST***	***WSW 1/8 - 1/4 (0.224 mi.)***	***AB157***	***401***

EXECUTIVE SUMMARY

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 11/01/2013 has revealed that there are 35 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
A A A STAMP & SEAL	***26-20 JACKSON AVE***	***N 0 - 1/8 (0.041 mi.)***	***D12***	***18***
A-1 AUTO COLLISION INC	***2831 THOMSON AVE***	***SSE 0 - 1/8 (0.045 mi.)***	***B16***	***23***
COURT SQUARE	***45-18 COURT SQ***	***WSW 0 - 1/8 (0.103 mi.)***	***H52***	***101***
NYCT - COURT SQUARE STA G LINE	***JACKSON ST & COURT SQ***	***W 1/8 - 1/4 (0.134 mi.)***	***J84***	***197***
MTA NYCT 11TH STREET & JACKSON	JACKSON AVE & 45TH AVE	W 1/8 - 1/4 (0.134 mi.)	J87	206
CON EDISON	JACKSON AVE & COURT SQU	W 1/8 - 1/4 (0.134 mi.)	J88	207
KENT BRAGALINE INC	***27-45 JACKSON AVE***	***NE 1/8 - 1/4 (0.135 mi.)***	***I89***	***208***
ROCKROSE CONSTRUCTION CORP	***4329 CRESCENT STREET***	***NNW 1/8 - 1/4 (0.141 mi.)***	***N91***	***213***
AEROSOURCE INC	***25-19 43RD AVE***	***NNW 1/8 - 1/4 (0.151 mi.)***	***N98***	***227***
FEDERAL PACIFIC ELECTRIC CO	***4300 CRESCENT ST***	***NNW 1/8 - 1/4 (0.155 mi.)***	***N101***	***234***
NYCDEP	CRESCENT & 43RD AVE	NNW 1/8 - 1/4 (0.155 mi.)	N103	246
LIRR - HUNTERS POINT YARD	***SKILLMAN AVE & 27TH ST***	***SSE 1/8 - 1/4 (0.170 mi.)***	***115***	***265***
PERENNIALLY GREEN INC	***23-13 44TH DR***	***WNW 1/8 - 1/4 (0.177 mi.)***	***123***	***288***
J BROTHERS AUTO BODY INC	***28-20 42ND RD***	***NE 1/8 - 1/4 (0.180 mi.)***	***T127***	***306***
CONSOLIDATED EDISON	PEARSON ST & JACKSON AV	WSW 1/8 - 1/4 (0.181 mi.)	R128	308
CON EDISON MANHOLE 954	***47TH ST & SKILLMAN AVE***	***S 1/8 - 1/4 (0.197 mi.)***	***138***	***331***
MTA NYCT - JACKSON & WEST SUBS	***28-20 JACKSON AVE***	***NE 1/8 - 1/4 (0.208 mi.)***	***V146***	***345***
KOREA NEWS	***42-22 27TH ST***	***NNE 1/8 - 1/4 (0.214 mi.)***	***W148***	***350***
SUBACCHI FURNITYRE-46-24 28TH	***46-24 28TH STREET***	***SSE 1/8 - 1/4 (0.216 mi.)***	***152***	***373***
STANDARD FINISHING CO INC	***43-10 23RD ST 2ND FLOOR***	***NW 1/8 - 1/4 (0.225 mi.)***	***AC159***	***413***
IDEAL LABEL INC	***43-10 23RD ST 2ND FLOOR***	***NW 1/8 - 1/4 (0.225 mi.)***	***AC162***	***423***
LAGUARDIA COMMUNITY COLLEGE	***29-10 THOMSON AVE***	***ESE 1/8 - 1/4 (0.228 mi.)***	***AD165***	***443***
OUTLET CITY INC	***42-16 WEST ST***	***ENE 1/8 - 1/4 (0.230 mi.)***	***AE168***	***458***
INTERNATIONAL DESIGN CENTER	***29-10 THOMPSON AVENUE***	***ESE 1/8 - 1/4 (0.236 mi.)***	***AD175***	***486***
NYC EDC - GOTHAM CENTER TOWER	***42-01 28TH STREET***	***NNE 1/8 - 1/4 (0.244 mi.)***	***AH179***	***493***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CENTRALIZED LAB SERVICES INC	***43-25 HUNTER ST***	***NNW 0 - 1/8 (0.100 mi.)***	***F44***	***85***
MTA NYCT - VENT PLANT 5103	HUNTER ST & 43RD AVE	N 0 - 1/8 (0.107 mi.)	G56	114
CON EDISON	45-34 COURT SQ	SW 1/8 - 1/4 (0.128 mi.)	M77	158
EAGLE ELECTRIC MANUFACTURING C	***45-31 COURT SQ***	***SW 1/8 - 1/4 (0.128 mi.)***	***M78***	***159***
STERNBERGER WAREHOUSE	45-55 PEARSON ST	SW 1/8 - 1/4 (0.171 mi.)	Q116	272
STERNBERGER MOTOR - G A P REAL	***45-55 PEARSON ST APT U***	***SW 1/8 - 1/4 (0.171 mi.)***	***Q119***	***279***
MATSON MFG CO INC	***45-17 PEARSON ST***	***SW 1/8 - 1/4 (0.177 mi.)***	***Q124***	***291***
MICHELANGELO SCULPTURE	***27-01 47TH AVE***	***SSE 1/8 - 1/4 (0.218 mi.)***	***Y153***	***385***
NYCT - FLUSHING AVENUE LINE (#	***DAVIS & 23RD ST***	***WSW 1/8 - 1/4 (0.224 mi.)***	***AB156***	***390***
MTA NYCT - COURT HOUSE SQ STA	***JACKSON AVE & 23RD ST***	***WSW 1/8 - 1/4 (0.224 mi.)***	***AB157***	***401***

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 11/01/2013 has revealed that there are 2 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MTA NYCT - JACKSON & WEST SUBS	***28-20 JACKSON AVE***	***NE 1/8 - 1/4 (0.208 mi.)***	***V146***	***345***
KOREA NEWS	42-22 27TH ST	NNE 1/8 - 1/4 (0.214 mi.)	W149	364

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 10/17/2013 has revealed that there is 1 NY DRYCLEANERS site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
TOP STAR FABRICARE	43-43 QUEENS STREET	ENE 1/8 - 1/4 (0.125 mi.)	K76	158

NY E DESIGNATION: Lots designation with an ?E? on the Zoning Maps of the City of New York for potential hazardous material contamination, air and/or noise quality impacts.

A review of the NY E DESIGNATION list, as provided by EDR, and dated 09/17/2013 has revealed that there are 17 NY E DESIGNATION sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LOT 6,TAXBLOCK 433	26-15 JACKSON AVENUE	NNW 0 - 1/8 (0.045 mi.)	D14	20
LOT 8,TAXBLOCK 433	26-11 JACKSON AVENUE	NW 0 - 1/8 (0.046 mi.)	18	27
LOT 5,TAXBLOCK 433	26-19 JACKSON AVENUE	NNW 0 - 1/8 (0.046 mi.)	D19	31
LOT 12,TAXBLOCK 433	25-25 44 DRIVE	WNW 0 - 1/8 (0.080 mi.)	39	73
LOT 8,TAXBLOCK 432	27-35 JACKSON AVENUE	NE 0 - 1/8 (0.109 mi.)	E60	123
LOT 27,TAXBLOCK 431	42-74 HUNTER STREET	NNE 0 - 1/8 (0.124 mi.)	L75	156
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
LOT 4,TAXBLOCK 433	26-21 JACKSON AVENUE	N 0 - 1/8 (0.048 mi.)	D22	35
LOT 1,TAXBLOCK 433	26-27 JACKSON AVENUE	N 0 - 1/8 (0.051 mi.)	D26	40
LOT 2,TAXBLOCK 433	26-25 JACKSON AVENUE	N 0 - 1/8 (0.051 mi.)	D28	45
LOT 3,TAXBLOCK 433	26-23 JACKSON AVENUE	N 0 - 1/8 (0.055 mi.)	D31	50
LOT 35,TAXBLOCK 433	43-15 HUNTER STREET	NNW 0 - 1/8 (0.099 mi.)	F42	78
LOT 31,TAXBLOCK 433	43-25 HUNTER STREET	NNW 0 - 1/8 (0.100 mi.)	F43	81
LOT 36,TAXBLOCK 433	43-11 HUNTER STREET	NNW 0 - 1/8 (0.100 mi.)	F45	88
LOT 37,TAXBLOCK 433	43-09 HUNTER STREET	NNW 0 - 1/8 (0.101 mi.)	F46	91
LOT 41,TAXBLOCK 433	27-10 43 AVENUE	N 0 - 1/8 (0.101 mi.)	G48	96
LOT 39,TAXBLOCK 433	27-06 43 AVENUE	N 0 - 1/8 (0.103 mi.)	G53	107
LOT 38,TAXBLOCK 433	27-02 43 AVENUE	N 0 - 1/8 (0.105 mi.)	G55	111

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR US Hist Auto Stat: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Auto Stat list, as provided by EDR, has revealed that there are 37 EDR US

EXECUTIVE SUMMARY

Hist Auto Stat sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	4412 PURVES ST	E 0 - 1/8 (0.027 mi.)	A1	8
Not reported	4427 PURVES ST	ESE 0 - 1/8 (0.033 mi.)	A3	9
Not reported	4435 PURVES ST	ESE 0 - 1/8 (0.036 mi.)	A5	11
Not reported	4443 PURVES ST	ESE 0 - 1/8 (0.039 mi.)	A7	13
Not reported	2801 THOMSON AVE	SSW 0 - 1/8 (0.040 mi.)	B8	13
Not reported	2811 THOMSON AVE	S 0 - 1/8 (0.040 mi.)	B10	16
Not reported	2723 44TH DR	WNW 0 - 1/8 (0.040 mi.)	C11	17
Not reported	2718 THOMSON AVE	SSW 0 - 1/8 (0.043 mi.)	B13	20
Not reported	2831 THOMSON AVE	SSE 0 - 1/8 (0.045 mi.)	B15	23
Not reported	2719 THOMSON AVE	SW 0 - 1/8 (0.047 mi.)	20	34
Not reported	2615 JACKSON AVE	NNW 0 - 1/8 (0.047 mi.)	D21	35
Not reported	2604 JACKSON AVE	NW 0 - 1/8 (0.050 mi.)	C24	40
Not reported	2707 44TH DR	WNW 0 - 1/8 (0.051 mi.)	C25	40
Not reported	2413 44TH DR	WNW 0 - 1/8 (0.109 mi.)	59	123
Not reported	2722 JACKSON AVE	NE 0 - 1/8 (0.113 mi.)	I65	135
Not reported	5 COURT SQ	WSW 0 - 1/8 (0.124 mi.)	H74	156
Not reported	4243 27TH ST	N 1/8 - 1/4 (0.132 mi.)	L83	197
Not reported	4329 CRESCENT ST	NNW 1/8 - 1/4 (0.141 mi.)	N92	219
Not reported	4315 CRESCENT ST	NNW 1/8 - 1/4 (0.147 mi.)	N97	227
Not reported	4305 CRESCENT ST	NNW 1/8 - 1/4 (0.151 mi.)	N100	233
Not reported	2415 44TH RD	NW 1/8 - 1/4 (0.155 mi.)	P104	247
Not reported	2413 44TH RD	NW 1/8 - 1/4 (0.156 mi.)	P106	250
Not reported	2413 44	NW 1/8 - 1/4 (0.157 mi.)	P107	250
Not reported	2820 42ND RD	NE 1/8 - 1/4 (0.179 mi.)	T125	302
Not reported	4237 CRESCENT ST	N 1/8 - 1/4 (0.197 mi.)	X139	333
Not reported	4235 CRESCENT ST	N 1/8 - 1/4 (0.203 mi.)	X145	345
Not reported	4233 CRESCENT ST	N 1/8 - 1/4 (0.209 mi.)	X147	349
Not reported	4309 23RD ST	NNW 1/8 - 1/4 (0.233 mi.)	AF172	482
Not reported	4206 27TH ST	NNE 1/8 - 1/4 (0.243 mi.)	178	493

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	2626 JACKSON AVE	N 0 - 1/8 (0.056 mi.)	D32	53
Not reported	2701 JACKSON AVE	NNE 0 - 1/8 (0.062 mi.)	D36	66
Not reported	2706 43RD AVE	N 0 - 1/8 (0.102 mi.)	G50	100
Not reported	2707 43RD AVE	N 0 - 1/8 (0.103 mi.)	G51	101
Not reported	2702 43RD AVE	N 0 - 1/8 (0.104 mi.)	G54	110
Not reported	4620 27TH ST	SSE 1/8 - 1/4 (0.198 mi.)	Y141	335
Not reported	4506 DAVIS ST	WSW 1/8 - 1/4 (0.225 mi.)	AA158	413
Not reported	4557 DAVIS ST	SW 1/8 - 1/4 (0.226 mi.)	AA163	440

EDR US Hist Cleaners: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Cleaners list, as provided by EDR, has revealed that there are 6 EDR US

EXECUTIVE SUMMARY

Hist Cleaners sites within approximately 0.25 miles of the target property.


Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	2501 JACKSON AVE	W 0 - 1/8 (0.115 mi.)	J66	135
Not reported	4320 CRESCENT ST	NNW 1/8 - 1/4 (0.146 mi.)	N96	226
Not reported	4507 28TH ST	SE 1/8 - 1/4 (0.183 mi.)	129	309
Not reported	2704 42ND RD	NNE 1/8 - 1/4 (0.193 mi.)	W134	322
Not reported	4231 CRESCENT ST	N 1/8 - 1/4 (0.214 mi.)	X150	369
Not reported	4420 30TH ST	ESE 1/8 - 1/4 (0.248 mi.)	AD187	510

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 20 records.

Site Name	Database(s)
NYSDOT BIN 1066220	FINDS, NY MANIFEST
NYCDEP	RCRA NonGen / NLR, FINDS, NY MANIFEST
CONSOLIDATED EDISON	RCRA NonGen / NLR, NY MANIFEST
NYCDOT	RCRA NonGen / NLR, FINDS, NY MANIFEST
CONSOLIDATED EDISON	RCRA NonGen / NLR, NY MANIFEST
NYSDOT	RCRA NonGen / NLR, FINDS, NY MANIFEST
NYSDOT	RCRA NonGen / NLR, FINDS, NY MANIFEST
CONSOLIDATED EDISON	RCRA NonGen / NLR, NY MANIFEST
CONSOLIDATED EDISON	RCRA NonGen / NLR, NY MANIFEST
CONSOLIDATED EDISON	RCRA NonGen / NLR, NY MANIFEST
CONSOLIDATED EDISON	RCRA NonGen / NLR, NY MANIFEST
CONSOLIDATED EDISON	RCRA NonGen / NLR, NY MANIFEST
CONSOLIDATED EDISON	RCRA NonGen / NLR, NY MANIFEST
CONSOLIDATED EDISON	RCRA NonGen / NLR, NY MANIFEST
CON ED	RCRA-CESQG, NY MANIFEST
NYCTA	RCRA-CESQG, FINDS, NY MANIFEST
CONSOLIDATED EDISON	RCRA NonGen / NLR, NY MANIFEST
CONSOLIDATED EDISON CO #3000	NY MANIFEST
MTA EXISTING RAIL YARD	RCRA NonGen / NLR
NYCDOT BRIDGES BIN 2247260	RCRA NonGen / NLR, FINDS

OVERVIEW MAP - 3798265.2s




This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 27-21 44th Drive and 44-18 Purves Street ADDRESS: 44-18 Purves Street Long Island City NY 11101 LAT/LONG: 40.7467 / 73.9415	CLIENT: Langan Engineering, Inc. CONTACT: Jessica Alzamora INQUIRY #: 3798265.2s DATE: December 02, 2013 10:55 am

Copyright © 2013 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

DETAIL MAP - 3798265.2s



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Oil & Gas pipelines from USGS
- 100-year flood zone
- 500-year flood zone
- National Wetland Inventory
- State Wetlands

0 1/16 1/8 1/4 Miles

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 27-21 44th Drive and 44-18 Purves Street ADDRESS: 44-18 Purves Street Long Island City NY 11101 LAT/LONG: 40.7467 / 73.9415	CLIENT: Langan Engineering, Inc. CONTACT: Jessica Alzamora INQUIRY #: 3798265.2s DATE: December 02, 2013 10:58 am

Copyright © 2013 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	TP		NR	NR	NR	NR	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
CERCLIS	0.500		0	0	0	NR	NR	0
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site List								
CERC-NFRAP	0.500		0	0	0	NR	NR	0
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	0	3	NR	3
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		0	2	NR	NR	NR	2
RCRA-SQG	0.250		2	3	NR	NR	NR	5
RCRA-CESQG	0.250		0	8	NR	NR	NR	8
Federal institutional controls / engineering controls registries								
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
LUCIS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
State- and tribal - equivalent CERCLIS								
NY SHWS	1.000		0	0	1	13	NR	14
NY VAPOR REOPENED	1.000		0	0	0	1	NR	1
State and tribal landfill and/or solid waste disposal site lists								
NY SWF/LF	0.500		0	0	2	NR	NR	2
State and tribal leaking storage tank lists								
NY LTANKS	0.500		2	4	39	NR	NR	45
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
State and tribal registered storage tank lists								
NY TANKS	0.250		0	0	NR	NR	NR	0
NY UST	0.250		3	13	NR	NR	NR	16
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY AST	0.250		5	20	NR	NR	NR	25
NY CBS AST	0.250		1	2	NR	NR	NR	3
NY MOSF AST	0.500		0	0	0	NR	NR	0
NY MOSF	0.500		0	0	0	NR	NR	0
NY CBS	0.250		1	2	NR	NR	NR	3
INDIAN UST	0.250		0	0	NR	NR	NR	0
FEMA UST	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY ENG CONTROLS	0.500		0	0	1	NR	NR	1
NY INST CONTROL	0.500		0	0	1	NR	NR	1
NY RES DECL	0.125		0	NR	NR	NR	NR	0
State and tribal voluntary cleanup sites								
NY VCP	0.500		0	0	3	NR	NR	3
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
NY ERP	0.500		0	0	0	NR	NR	0
NY BROWNFIELDS	0.500		0	1	1	NR	NR	2
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
NY SWRCY	0.500		0	0	0	NR	NR	0
NY SWTIRE	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	0	NR	0
US HIST CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	7	NR	NR	NR	7
NY HIST AST	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
Local Land Records								
LIENS 2	TP		NR	NR	NR	NR	NR	0
NY LIENS	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125		17	NR	NR	NR	NR	17
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		7	28	NR	NR	NR	35
DOT OPS	TP		NR	NR	NR	NR	NR	0
DOD	1.000		0	0	0	0	NR	0
FUDS	1.000		0	0	0	0	NR	0
CONSENT	1.000		0	0	0	0	NR	0
ROD	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
FINDS	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	0	NR	NR	0
NY UIC	TP		NR	NR	NR	NR	NR	0
NY MANIFEST	0.250		5	30	NR	NR	NR	35
PA MANIFEST	0.250		0	0	NR	NR	NR	0
NJ MANIFEST	0.250		0	2	NR	NR	NR	2
NY DRYCLEANERS	0.250		0	1	NR	NR	NR	1
NY SPDES	TP		NR	NR	NR	NR	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY E DESIGNATION	0.125		17	NR	NR	NR	NR	17
INDIAN RESERV	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	0	NR	0
EDR US Hist Auto Stat	0.250		21	16	NR	NR	NR	37
EDR US Hist Cleaners	0.250		1	5	NR	NR	NR	6

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1
East
< 1/8
0.027 mi.
145 ft.

4412 PURVES ST
LONG ISLAND CITY, NY 11101

EDR US Hist Auto Stat **1015498124**
N/A

Site 1 of 8 in cluster A

Relative:
Higher

Actual:
18 ft.

EDR Historical Auto Stations:
Name: C T RIDE DISCOUNT AUTO REPAIR
Year: 2010
Address: 4412 PURVES ST

A2
East
< 1/8
0.030 mi.
158 ft.

S N B INC
44-16 PURVES ST
LONG ISLAND CITY, NY

RCRA NonGen / NLR **1000990347**
FINDS **NYR000003061**

Site 2 of 8 in cluster A

Relative:
Higher

Actual:
19 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: S N B INC
Facility address: 44-16 PURVES ST
LONG ISLAND CITY, NY 11101
EPA ID: NYR000003061
Mailing address: PO BOX 640-786
FLUSHING, NY 113640788
Contact: WALTER SCHMIDICHEN
Contact address: PO BOX 640-786
FLUSHING, NY 113640788
Contact country: US
Contact telephone: (718) 224-3711
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: WESLH BROS
Owner/operator address: 44-30 PURVES ST
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 729-7330
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: WESLH BROS
Owner/operator address: 44-30 PURVES ST
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 729-7330
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No

S N B INC (Continued) **1000990347**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: S N B INC
Classification: Not a generator, verified

Date form received by agency: 04/13/1995
Facility name: S N B INC
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110004512661

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

A3 **EDR US Hist Auto Stat** **1015498797**
ESE **4427 PURVES ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.033 mi.
176 ft. **Site 3 of 8 in cluster A**

Relative:
Higher

Actual:
20 ft.

EDR Historical Auto Stations:

Name: PURVIS AUTO REPAIR
Year: 2001
Address: 4427 PURVES ST

Name: PURVIS AUTO REPAIR
Year: 2002
Address: 4427 PURVES ST

Name: PURVIS AUTO REPAIR
Year: 2003
Address: 4427 PURVES ST

Name: PURVIS AUTO REPAIR

(Continued) **1015498797**

Year: 2004
Address: 4427 PURVES ST

Name: PURVIS AUTO REPAIR
Year: 2005
Address: 4427 PURVES ST

Name: PURVIS AUTO REPAIR
Year: 2006
Address: 4427 PURVES ST

Name: PURVIS AUTO REPAIR INC
Year: 2007
Address: 4427 PURVES ST

A4 **MANHOLE # 514** **NY Spills** **S104653985**
ESE **44-27 PERVES ST** **N/A**
< 1/8 **QUEENS, NY**
0.034 mi.
178 ft. **Site 4 of 8 in cluster A**

Relative: Higher

Actual: 20 ft.

SPILLS:

Facility ID:	0003644
DER Facility ID:	241946
Facility Type:	ER
Site ID:	299059
DEC Region:	2
Spill Date:	6/24/2000
Spill Number/Closed Date:	0003644 / 9/27/2001
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	6/24/2000
CID:	281
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	6/24/2000
Spill Record Last Update:	10/10/2001
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller Company:	001
Contact Name:	BRIAN JOYCE
Contact Phone:	(212) 580-6763
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"Con Ed e2mis Notes:6/24/00 2gal unknown oil on 1000gal water in manhole. Sample returned <1ppm PCB.6/25/00 Cleanup

MANHOLE # 514 (Continued) **S104653985**

completed. Oil was solidified and structure was double washed with slix. Liquids removed by tanker and solids by vactor. No earthen sump. (KMF 10/10/01)

Remarks: ABOVE MATERIAL DISCOVERED AT ABOVE LOCATION ON TOP OF 1,000 GALLONSWATER. SAMPLE HAS BEEN TAKEN AND CLEANUP IS PENDING LAB RESULTS.CON ED # 132002. NO CALL BACK REQUESTED.

Material:

Site ID:	299059
Operable Unit ID:	826047
Operable Unit:	01
Material ID:	551961
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

A5 **EDR US Hist Auto Stat** **1015499124**
ESE **4435 PURVES ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.036 mi.
191 ft. **Site 5 of 8 in cluster A**

Relative: Higher

Actual: 21 ft.

EDR Historical Auto Stations:

Name:	PURVIS AUTO REPAIR
Year:	1999
Address:	4435 PURVES ST
Name:	PURVIS AUTO REPAIR
Year:	2000
Address:	4435 PURVES ST

A6 **COMMERCIAL LOT** **NY Spills** **S108764477**
NE **44 -15 PURVIS STREET** **N/A**
< 1/8 **LONG ISLAND, NY**
0.038 mi.
199 ft. **Site 6 of 8 in cluster A**

Relative: Higher

Actual: 16 ft.

SPILLS:

Facility ID:	0706566
DER Facility ID:	336512
Facility Type:	ER
Site ID:	387108
DEC Region:	2
Spill Date:	9/12/2007
Spill Number/Closed Date:	0706566 / 10/17/2007
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response.

COMMERCIAL LOT (Continued) **S108764477**

	Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	hrpatel
Referred To:	Not reported
Reported to Dept:	9/12/2007
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/12/2007
Spill Record Last Update:	10/17/2007
Spiller Name:	CHARLIE SCHMINDGALL
Spiller Company:	COMMERCIAL LOT
Spiller Address:	44 -15 PURVIS STREET
Spiller City,St,Zip:	LONG ISLAND, NY
Spiller Company:	001
Contact Name:	CHARLIE SCHMINDGALL
Contact Phone:	(631) 224-1680
DEC Memo:	10/11/07-Hiralkumar Patel. left message for Charlie at agressive environmental.10/15/07-Hiralkumar Patel. received message from Charlie. he will send report.10/17/07-Hiralkumar Patel. received Phase II report from Charlie. abstract:- no structure on property; only cars and construction equipments- during Phase I, a possible UST was oted in the south-east corner of the property- no tanks/anamolies found during GPR survey by Impact environmental- total six soil borings were performed, all borings were drilled to 15 ft bg- water table stands between 13 and 14 ft bg- soil samples were collected every five ft and were field screened- six soil samples were collected (one from each boring)- soil samples from boring 1, 2, 5 & 6 were taken at water table as no PID found- soil samples from boring 3 & 4 were taken at 5 ft bg as found little high PID (5 - 10 ppm) than background values (1 - 2 ppm)- no VOCs found in any samples- few SVOCs found in sample # 3 & 4based on available report, case closed.
Remarks:	SOIL TESTING LEVELS WERE VERY VERY LOW BUT CALLER WANTED DEC TO CHECK OUT

Material:

Site ID:	387108
Operable Unit ID:	1144325
Operable Unit:	01
Material ID:	2134622
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

COMMERCIAL LOT (Continued) **S108764477**

Tank Test:

A7
ESE
< 1/8
0.039 mi.
208 ft.

Relative:
Higher

Actual:
22 ft.

4443 PURVES ST **EDR US Hist Auto Stat** **1015499477**
LONG ISLAND CITY, NY 11101 **N/A**

Site 7 of 8 in cluster A

EDR Historical Auto Stations:

Name:	PURVIS AUTO REPAIR
Year:	2007
Address:	4443 PURVES ST
Name:	PURVIS AUTO REPAIR
Year:	2008
Address:	4443 PURVES ST
Name:	PURVIS AUTO REPAIR
Year:	2009
Address:	4443 PURVES ST
Name:	PURVIS AUTO REPAIR
Year:	2010
Address:	4443 PURVES ST
Name:	PURVIS AUTO REPAIR
Year:	2011
Address:	4443 PURVES ST
Name:	PURVIS AUTO REPAIR
Year:	2012
Address:	4443 PURVES ST

B8
SSW
< 1/8
0.040 mi.
209 ft.

Relative:
Higher

Actual:
20 ft.

2801 THOMSON AVE **EDR US Hist Auto Stat** **1015386139**
LONG ISLAND CITY, NY 11101 **N/A**

Site 1 of 6 in cluster B

EDR Historical Auto Stations:

Name:	JEMA COACH AUTO BODY
Year:	1999
Address:	2801 THOMSON AVE
Name:	ART AUTOMOTIVE LTD
Year:	2006
Address:	2801 THOMSON AVE
Name:	JEMA COACH AUTO BODY
Year:	2008
Address:	2801 THOMSON AVE
Name:	JEMA COACH AUTO BODY
Year:	2009
Address:	2801 THOMSON AVE

(Continued) **1015386139**

Name: JEMA COACH AUTO BODY
Year: 2010
Address: 2801 THOMSON AVE

A9 **44-43 PURVES ST** **NY CBS AST** **S102638733**
ESE **44-43 PURVES ST** **NY Spills** **N/A**
< 1/8 **LONG ISLAND CITY, NY** **NY CBS**
0.040 mi.
211 ft. **Site 8 of 8 in cluster A**

Relative:
Higher

Actual:
23 ft.

CBS AST:

CBS Number:	2-000087
ICS Number:	2-125780
PBS Number:	Not reported
MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	ACTIVE FACILITY
Facility Type:	MANUFACTURING
Telephone:	(718) 937-1413
Facility Town:	NEW YORK CITY
Region:	STATE
Expiration Date:	07/07/2001
Total Capacity of All Active Tanks(gal):	0
Operator:	S & M AUTOMATIC PRECISION CO.
Emergency Contact:	G. MIGNAT
Emergency Phone:	(718) 457-9855
Owner Name:	S & M AUTOMATIC PRECISION CO.
Owner Address:	44-43 PURVES ST
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Owner Telephone:	(718) 937-1413
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	S & M AUTOMATIC PRECISION CO.
Mail Contact Addr:	44-43 PURVES ST
Mail Contact Addr2:	Not reported
Mail Contact Contact:	G. MIGNAT
Mail Contact City,St,Zip:	LONG ISLAND CITY, NY 11101
Mail Phone:	(718) 937-1413
Tank Id:	001
CAS Number:	127184
Federal ID:	Not reported
Tank Status:	0
Install Date:	06/79
Tank Closed:	12/99
Capacity (Gal):	500
Chemical:	Tetrachloroethylene
Tank Location:	ABOVEGROUND
Tank Type:	Steel/carbon steel
Total Tanks:	0
Tank Secret:	False
Tank Containment:	Diking
Tank Error Status:	No Missing Data
Date Entered:	07/07/1989
Certified Date:	04/14/1999
Substance:	More than one Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	Painted/Asphalt Coating

44-43 PURVES ST (Continued) **S102638733**

Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	0
Pipe Containment:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Haz Percent:	50
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	04/01/93
Is It There:	False
Delinquent:	False
Date Expired:	07/07/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	04/01/1999

SPILLS:

Facility ID:	9713189
DER Facility ID:	154694
Facility Type:	ER
Site ID:	184909
DEC Region:	2
Spill Date:	2/26/1998
Spill Number/Closed Date:	9713189 / 5/14/1998
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	2/26/1998
CID:	205
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2/26/1998
Spill Record Last Update:	5/22/1998
Spiller Name:	CALLER
Spiller Company:	MARISOL INC
Spiller Address:	213 WEST UNION AVE
Spiller City,St,Zip:	BOUND BROOK, NJ 08805-
Spiller Company:	001
Contact Name:	CALLER

44-43 PURVES ST (Continued) **S102638733**

Contact Phone: (732) 469-5100
DEC Memo: Not reported
Remarks: hose broke on tank truck while delivering product.caller is attorney for company.

Material:
Site ID: 184909
Operable Unit ID: 1056121
Operable Unit: 01
Material ID: 324213
Material Code: 0059A
Material Name: SOLVENTS
Case No.: Not reported
Material FA: Other
Quantity: 100
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

CBS:
CBS Number: 2-000087
Program Type: CBS
Facility Status: Unregulated
Expiration Date: N/A
Dec Region: 2
UTMX: 589363.32235999
UTMY: 4511253.1193899

B10 **EDR US Hist Auto Stat** **1015387175**
South **2811 THOMSON AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.040 mi.
213 ft. **Site 2 of 6 in cluster B**

Relative: Higher

Actual: 19 ft.

EDR Historical Auto Stations:
Name: MARLING AUTO REPR CORPORATION
Year: 1999
Address: 2811 THOMSON AVE

Name: MARLING AUTO REPR CORPORATION
Year: 2000
Address: 2811 THOMSON AVE

Name: MARLING AUTO REPR INC
Year: 2003
Address: 2811 THOMSON AVE

C11
WNW
< 1/8
0.040 mi.
213 ft.

EDR US Hist Auto Stat **1015381120**
N/A

2723 44TH DR
LONG ISLAND CITY, NY 11101

Site 1 of 5 in cluster C

Relative:
Higher

Actual:
16 ft.

EDR Historical Auto Stations:

Name:	NORTHEASTERN AUTO REPAIR INCORPORATED
Year:	1999
Address:	2723 44TH DR
Name:	NORTHEASTERN AUTO REPAIR INCORPORATED
Year:	2000
Address:	2723 44TH DR
Name:	NORTHEASTERN AUTO REPAIR INC
Year:	2001
Address:	2723 44TH DR
Name:	NORTHEASTERN AUTO REPAIR INC
Year:	2002
Address:	2723 44TH DR
Name:	NORTHEASTERN AUTO REPAIR INC
Year:	2003
Address:	2723 44TH DR
Name:	NORTHEASTERN AUTO REPAIR INC
Year:	2004
Address:	2723 44TH DR
Name:	NORTHEASTERN AUTO REPAIR INC
Year:	2007
Address:	2723 44TH DR
Name:	NORTHEASTERN AUTO REPAIR INC
Year:	2008
Address:	2723 44TH DR
Name:	NORTHEASTERN AUTO REPAIR INC
Year:	2009
Address:	2723 44TH DR
Name:	NORTHEASTERN AUTOMOBILE REPAIR INCOR
Year:	2011
Address:	2723 44TH DR
Name:	NORTHEASTERN AUTO REPAIR INC
Year:	2012
Address:	2723 44TH DR

D12 North < 1/8 0.041 mi. 219 ft. | **A A A STAMP & SEAL**
26-20 JACKSON AVE
QUEENS, NY 11101

RCRA NonGen / NLR **1001224371**
FINDS **NYR000055889**
NY MANIFEST

Site 1 of 15 in cluster D

Relative: Higher

Actual: 14 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	A A A STAMP & SEAL
Facility address:	26-20 JACKSON AVE QUEENS, NY 11101
EPA ID:	NYR000055889
Mailing address:	JACKSON AVE QUEENS, NY 11101
Contact:	BARRY GOLDMAN
Contact address:	JACKSON AVE QUEENS, NY 11101
Contact country:	US
Contact telephone:	(718) 361-8087
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	JULIUS REINHARDT
Owner/operator address:	1 WOODHOLLOW LANE OLD BROOKVILLE, NY 11545
Owner/operator country:	US
Owner/operator telephone:	(718) 897-0310
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	JULIUS REINHARDT
Owner/operator address:	1 WOODHOLLOW LANE OLD BROOKVILLE, NY 11545
Owner/operator country:	US
Owner/operator telephone:	(718) 897-0310
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

A A A STAMP & SEAL (Continued) **1001224371**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: A A A STAMP & SEAL
Classification: Not a generator, verified

Date form received by agency: 06/08/1998
Facility name: A A A STAMP & SEAL
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110008103809

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000055889
Country: USA
Mailing Name: AAA STAMP & SEAL
Mailing Contact: BARRY GOLDMAN
Mailing Address: 26-20 JACKSON AVE
Mailing Address 2: Not reported
Mailing City: QUEENS
Mailing State: NY
Mailing Zip: 11101
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-361-8087

Document ID: NYC5398244
Manifest Status: Not reported
Trans1 State ID: ILD984908202
Trans2 State ID: SCD987574647
Generator Ship Date: 10/13/1998
Trans1 Recv Date: 10/13/1998
Trans2 Recv Date: 10/21/1998
TSD Site Recv Date: 10/29/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000055889
Trans1 EPA ID: SCD077995488
Trans2 EPA ID: Not reported
TSDF ID: LP3931NY

A A A STAMP & SEAL (Continued) **1001224371**

Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	98

B13 **EDR US Hist Auto Stat** **1015380671**
SSW **2718 THOMSON AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.043 mi.
225 ft. **Site 3 of 6 in cluster B**

Relative:
Higher

Actual:
20 ft.

EDR Historical Auto Stations:

Name:	MANNY AUTO ELECTRIC CORP
Year:	2002
Address:	2718 THOMSON AVE

D14 **LOT 6,TAXBLOCK 433** **NY E DESIGNATION** **S108469575**
NNW **26-15 JACKSON AVENUE** **N/A**
< 1/8 **QUEENS, NY 11101**
0.045 mi.
238 ft. **Site 2 of 15 in cluster D**

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Tax Lot(s):	6
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	G2
Land Use Category:	10
Number of Easements:	0

LOT 6,TAXBLOCK 433 (Continued) **S108469575**

Owner, Type of Code:	Not reported
Owner Name:	N J F PROPERTIES INC
Lot Area:	000004267
Total Building Floor Area:	00000003433
Commercial Floor Area:	00000003433
Office Floor Area:	00000000000
Retail Floor Area:	00000000000
Garage Floor Area:	00000003433
Storage Floor Area:	00000000000
Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	001.00
Residential Units:	00000
Non and Residential Units:	00001
Lot Frontage:	0042.67
Lot Depth:	0100.00
Building Frontage:	0042.92
Building Depth:	0080.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000054000
Total Assessed Value:	00000117000
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1941
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0000.80
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330006
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000342
Y Coordinate:	0211651
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1
Tax Lot(s):	6

LOT 6,TAXBLOCK 433 (Continued) **S108469575**

E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Window Wall Attenuation & Alternate Ventilation
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	G2
Land Use Category:	10
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	N J F PROPERTIES INC
Lot Area:	000004267
Total Building Floor Area:	00000003433
Commercial Floor Area:	00000003433
Office Floor Area:	00000000000
Retail Floor Area:	00000000000
Garage Floor Area:	00000003433
Storage Floor Area:	00000000000
Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	001.00
Residential Units:	00000
Non and Residential Units:	00001
Lot Frontage:	0042.67
Lot Depth:	0100.00
Building Frontage:	0042.92
Building Depth:	0080.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000054000
Total Assessed Value:	00000117000
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1941

LOT 6,TAXBLOCK 433 (Continued) **S108469575**

Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0000.80
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330006
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000342
Y Coordinate:	0211651
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

B15 **EDR US Hist Auto Stat** **1015388679**
SSE **2831 THOMSON AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.045 mi.
240 ft. **Site 4 of 6 in cluster B**

Relative:
Higher

Actual:
21 ft.

EDR Historical Auto Stations:

Name:	KHANS AUTO REPAIR & COLLISSION
Year:	2011
Address:	2831 THOMSON AVE
Name:	KHANS AUTO REPAIR & COLLISSION
Year:	2012
Address:	2831 THOMSON AVE

B16 **A-1 AUTO COLLISION INC** **RCRA NonGen / NLR** **1000102743**
SSE **2831 THOMSON AVE** **NY MANIFEST** **NYD986884872**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.045 mi.
240 ft. **Site 5 of 6 in cluster B**

Relative:
Higher

Actual:
21 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	A-1 AUTO COLLISION INC
Facility address:	2831 THOMSON AVE LONG ISLAND CITY, NY 111012902
EPA ID:	NYD986884872
Mailing address:	THOMSON AVE LONG ISLAND CITY, NY 11101

A-1 AUTO COLLISION INC (Continued) **1000102743**

Contact: Not reported
Contact address: THOMSON AVE
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: GLEN TOMPKINS
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: GLEN TOMPKINS
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: A-1 AUTO COLLISION INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: A-1 AUTO COLLISION INC
Classification: Not a generator, verified

A-1 AUTO COLLISION INC (Continued) **1000102743**

Date form received by agency: 12/04/1989
Facility name: A-1 AUTO COLLISION INC
Classification: Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYD986884872
Country: USA
Mailing Name: A 1 AUTO COLLISION INCORPORATED
Mailing Contact: TOMPKINS R GLEN
Mailing Address: 2831 THOMSON AVENUE
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-786-0024

Document ID: NJA1317333
Manifest Status: Completed copy
Trans1 State ID: NJDEPS103
Trans2 State ID: Not reported
Generator Ship Date: 920218
Trans1 Recv Date: 920218
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920219
Part A Recv Date: 920227
Part B Recv Date: 920303
Generator EPA ID: NYD986884872
Trans1 EPA ID: NJD986608941
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: F003 - UNKNOWN
Quantity: 00105
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 92

Document ID: NJA0963706
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJDEPS103
Trans2 State ID: Not reported
Generator Ship Date: 901206
Trans1 Recv Date: 901206
Trans2 Recv Date: Not reported
TSD Site Recv Date: 901207
Part A Recv Date: 901231
Part B Recv Date: 910115
Generator EPA ID: NYD986884872
Trans1 EPA ID: NJD980787147
Trans2 EPA ID: Not reported

A-1 AUTO COLLISION INC (Continued) **1000102743**

TSDF ID:	NJD002454544
Waste Code:	F003 - UNKNOWN
Quantity:	00070
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	90

B17 **VAULT#3073** **NY Spills** **S107408525**
South **2740 THOMASON AVE** **N/A**
< 1/8 **QUEENS, NY**
0.046 mi.
241 ft. **Site 6 of 6 in cluster B**

Relative:
Higher

Actual:
18 ft.

SPILLS:

Facility ID:	0506520
DER Facility ID:	299029
Facility Type:	ER
Site ID:	351752
DEC Region:	2
Spill Date:	8/25/2005
Spill Number/Closed Date:	0506520 / 1/10/2008
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	8/26/2005
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	8/26/2005
Spill Record Last Update:	1/10/2008
Spiller Name:	ERT DESK'
Spiller Company:	VAULT#3073
Spiller Address:	2740 THOMASON AVE
Spiller City,St,Zip:	QUEENS, NY
Spiller Company:	001
Contact Name:	ERT DESK'
Contact Phone:	(212) 580-8383
DEC Memo:	01/10/08 - See eDocs for Con Ed report detailing cleanup and closure.160721. 8/25/2005 15:00 HRS. T. DIDONATO #26557, SPLICER WITH EQUIPMENT GROUP, REPORTS ON LOCATION FOR INSPECTION OF V-3073 (ACCT # C3238) AND WHILE REMOVING A DEFECTIVE SUMP PUMP AT 14:40 HRS. HE FOUND APPROX. 1 QT UNKNOWN OIL MIXED IN WITH DIRT ON FLOOR OF VAULT. TRANSFORMER WILL BE PRESSURE-TESTED TO DETERMINE IF IT IS LEAKING.NO OIL FOUND IN SUMP PIT OR SUMP PUMP PIPING. SPILL APPEARS TO BE CONTAINED. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. NO PRIVATE

VAULT#3073 (Continued) **S107408525**

PROPERTY AFFECTED. NO FIRE OR SMOKE INVOLVED. ENV STOP TAG 44487 PLACED. OIL SAMPLE WILL BE TAKEN ON "E" PRIORITY TURNAROUND. CHAIN OF CUSTODY FORM DD-12108 MARKED FOR PCB TEST. CLEANUP PENDING PRESSURE TEST RESULTS AND PCB SAMPLE RESULTS.** TRANSFORMER INFORMATION FROM E.C.C. WAREHOUSE:** Serial ID: 8172233, MFG Code: GE, KVA: 500, Mfr. Date: 05/01/1948, Install Date: 11/17/1993.** HISTORICAL PCB RESULTS DATED 06/27/2001: 26 PPM, LAB SEQ # 01-05129-001.-- W. WAINWRIGHT #17344 --8/25/2005 15:47 HRS. -- T. DIDONATO REPORTS HE IS CONDEMNING TRANSFORMER DUE TO OIL LEAK AND HE WILL TAKE AN OIL SAMPLE FROM TRANSFORMER. UNABLE TO GET A LIQUID SAMPLE FROM STRUCTURE. ** INITIAL CLEANUP PENDING PCB RESULTS FROM CHEM LAB.** FINAL CLEANUP PENDING TRANSFORMER REMOVAL. -- W.W. #17344 --8/25/2005 16:00 HRS. -- T. DIDONATO REPORTS SAMPLE WILL BE SENT TO CHEM LAB USING CHAIN OF CUSTODY FORM # DD-12019 (WAS PREVIOUSLY REPORTED AS # DD-12018). -- W.W. #17344 Lab Sequence Number: 05-08946-001 Aroclor 1260 19.3 ppm EPA 608/8082.8/26/2005 13:40 HRS. -- ENV. DESK SUPERVISOR D. HEARNS REPORTS HE SPOKE WITH SHIFT MANAGER K. SUDOL AND TRANSFORMER WILL NOT BE REMOVED UNTIL SOMETIME NEXT WEEK. INCIDENT TO BE REMOVED FROM 72-HOUR DEMINIMIS BECAUSE CLEANUP CANNOT BE COMPLETED UNTIL TRANSFORMER IS REMOVED.INCIDENT TYPE CHANGED TO "SPILL - DIELECTRIC" AND SHORT DESCRIPTION UPDATED FROM "UNKNOWN OIL" TO "TRANSFORMER OIL" (AS PER UPDATE ON 8/25/2005 15:47 HRS. -- W.W. #17344 --

Remarks: from transformer will condenm: coned # 160721: no to 4 questions: need to deenergize feeder coming off 72 hour clock:

Material:

Site ID:	351752
Operable Unit ID:	1109257
Operable Unit:	01
Material ID:	2099248
Material Code:	0020A
Material Name:	TRANSFORMER OIL
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

---

18 **LOT 8,TAXBLOCK 433** **NY E DESIGNATION** **S108469582**
NW **26-11 JACKSON AVENUE** **N/A**
< 1/8 **QUEENS, NY 11101**
0.046 mi.
244 ft.

Relative: Higher

Actual: 15 ft.

E DESIGNATION:

Tax Lot(s):	8
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.

LOT 8,TAXBLOCK 433 (Continued) **S108469582**

Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	F1
Land Use Category:	06
Number of Easements:	0
Owner, Type of Code:	P
Owner Name:	26 JACKSON AVENUE LLC
Lot Area:	000006450
Total Building Floor Area:	00000015500
Commercial Floor Area:	00000015500
Office Floor Area:	00000006500
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000009000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	002.00
Residential Units:	00000
Non and Residential Units:	00003
Lot Frontage:	0064.42
Lot Depth:	0100.00
Building Frontage:	0064.00
Building Depth:	0100.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000090000
Total Assessed Value:	00000266400
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1961
Year Built Code:	Not reported
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0002.40
Maximum Allowable Far:	10.00

LOT 8,TAXBLOCK 433 (Continued) **S108469582**

Borough Code:	4
Borough Tax Block And Lot:	4004330008
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000308
Y Coordinate:	0211612
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

Tax Lot(s):	8
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Window Wall Attenuation & Alternate Ventilation
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	F1
Land Use Category:	06
Number of Easements:	0
Owner, Type of Code:	P
Owner Name:	26 JACKSON AVENUE LLC
Lot Area:	000006450
Total Building Floor Area:	00000015500
Commercial Floor Area:	00000015500
Office Floor Area:	00000006500
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000

LOT 8,TAXBLOCK 433 (Continued) **S108469582**

Storage Floor Area:	00000000000
Factory Floor Area:	00000009000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	002.00
Residential Units:	00000
Non and Residential Units:	00003
Lot Frontage:	0064.42
Lot Depth:	0100.00
Building Frontage:	0064.00
Building Depth:	0100.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000090000
Total Assessed Value:	00000266400
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1961
Year Built Code:	Not reported
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0002.40
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330008
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000308
Y Coordinate:	0211612
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

D19 **LOT 5,TAXBLOCK 433** **NY E DESIGNATION** **S108469573**
NNW **26-19 JACKSON AVENUE** **N/A**
< 1/8 **QUEENS, NY 11101**
0.046 mi.
244 ft. **Site 3 of 15 in cluster D**

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Tax Lot(s):	5
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	K9
Land Use Category:	05
Number of Easements:	0
Owner, Type of Code:	P
Owner Name:	ISABEL NADEL
Lot Area:	000002500
Total Building Floor Area:	00000005050
Commercial Floor Area:	00000005050
Office Floor Area:	00000000000
Retail Floor Area:	00000002525
Garage Floor Area:	00000000000
Storage Floor Area:	00000002525
Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	002.00
Residential Units:	00000
Non and Residential Units:	00001
Lot Frontage:	0025.00
Lot Depth:	0100.00
Building Frontage:	0025.00
Building Depth:	0100.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5

LOT 5,TAXBLOCK 433 (Continued) **S108469573**

Basement Type Grade:	5
Land Assessed Value:	00000027000
Total Assessed Value:	00000069750
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1916
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0002.02
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330005
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000383
Y Coordinate:	0211644
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

Tax Lot(s):	5
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Window Wall Attenuation & Alternate Ventilation
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC

LOT 5,TAXBLOCK 433 (Continued) **S108469573**

All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	K9
Land Use Category:	05
Number of Easements:	0
Owner, Type of Code:	P
Owner Name:	ISABEL NADEL
Lot Area:	000002500
Total Building Floor Area:	00000005050
Commercial Floor Area:	00000005050
Office Floor Area:	00000000000
Retail Floor Area:	00000002525
Garage Floor Area:	00000000000
Storage Floor Area:	00000002525
Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	002.00
Residential Units:	00000
Non and Residential Units:	00001
Lot Frontage:	0025.00
Lot Depth:	0100.00
Building Frontage:	0025.00
Building Depth:	0100.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000027000
Total Assessed Value:	00000069750
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1916
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0002.02
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330005
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000383
Y Coordinate:	0211644
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006

LOT 5,TAXBLOCK 433 (Continued) **S108469573**

Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

20
SW
< 1/8
0.047 mi.
247 ft.

2719 THOMSON AVE
LONG ISLAND CITY, NY 11101

EDR US Hist Auto Stat **1015380738**
N/A

Relative:
Higher

Actual:
16 ft.

EDR Historical Auto Stations:

Name: MANNY AUTO ELECTRIC CORP
Year: 2001
Address: 2719 THOMSON AVE

Name: MANNY AUTO ELECTRIC CORP
Year: 2003
Address: 2719 THOMSON AVE

Name: MANNY AUTO ELECTRIC CORP
Year: 2004
Address: 2719 THOMSON AVE

Name: MANNY AUTO ELECTRIC CORP
Year: 2006
Address: 2719 THOMSON AVE

Name: MANNY AUTO ELECTRIC CORP
Year: 2007
Address: 2719 THOMSON AVE

Name: MANNY AUTO ELECTRIC CORP
Year: 2008
Address: 2719 THOMSON AVE

Name: MANNY AUTO ELECTRIC CORP
Year: 2009
Address: 2719 THOMSON AVE

Name: MANNY AUTO ELECTRIC CO
Year: 2010
Address: 2719 THOMSON AVE

Name: MANNY AUTOMOBILE ELECTRIC CORPORATIO
Year: 2011
Address: 2719 THOMSON AVE

Name: MANNY AUTO ELECTRIC CORP
Year: 2012
Address: 2719 THOMSON AVE

D21
NNW
< 1/8
0.047 mi.
249 ft.

2615 JACKSON AVE — **EDR US Hist Auto Stat** — **1015373208** — **N/A**
LONG ISLAND CITY, NY 11101

Site 4 of 15 in cluster D

Relative: Higher

Actual: 14 ft.

EDR Historical Auto Stations:

Name:	MOE TAXI & BLACK CAR SRVC CTR
Year:	2001
Address:	2615 JACKSON AVE
Name:	MOE TAXI & BLACK CAR SRVC CTR
Year:	2002
Address:	2615 JACKSON AVE
Name:	MOE TAXI & BLACK CAR SERVICE CENTER
Year:	2006
Address:	2615 JACKSON AVE
Name:	MOE TAXI & BLACK CAR SERVICE CENTER
Year:	2007
Address:	2615 JACKSON AVE
Name:	CT RIDE DISCOUNT AUTO REPAIR
Year:	2008
Address:	2615 JACKSON AVE
Name:	CT RIDE DISCOUNT AUTO REPAIR
Year:	2009
Address:	2615 JACKSON AVE

D22
North
< 1/8
0.048 mi.
251 ft.

LOT 4,TAXBLOCK 433 — **NY E DESIGNATION** — **S109318001** — **N/A**
26-21 JACKSON AVENUE
QUEENS, NY 11101

Site 5 of 15 in cluster D

Relative: Lower

Actual: 13 ft.

E DESIGNATION:

Tax Lot(s):	4
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC

LOT 4,TAXBLOCK 433 (Continued) **S109318001**

Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	S2
Land Use Category:	04
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	26-21 JACKSON
Lot Area:	000002000
Total Building Floor Area:	00000003500
Commercial Floor Area:	00000001155
Office Floor Area:	00000000000
Retail Floor Area:	00000001155
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	003.00
Residential Units:	00002
Non and Residential Units:	00003
Lot Frontage:	0020.00
Lot Depth:	0100.00
Building Frontage:	0020.00
Building Depth:	0055.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000004551
Total Assessed Value:	00000019780
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1930
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0001.75
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330004
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000385
Y Coordinate:	0211681
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005

LOT 4,TAXBLOCK 433 (Continued) **S109318001**

Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1
Tax Lot(s):	4
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Window Wall Attenuation & Alternate Ventilation
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	S2
Land Use Category:	04
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	26-21 JACKSON
Lot Area:	000002000
Total Building Floor Area:	00000003500
Commercial Floor Area:	00000001155
Office Floor Area:	00000000000
Retail Floor Area:	00000001155
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	003.00
Residential Units:	00002
Non and Residential Units:	00003
Lot Frontage:	0020.00
Lot Depth:	0100.00
Building Frontage:	0020.00
Building Depth:	0055.00
Proximity Code:	0
Irregular Lot Code:	N

LOT 4,TAXBLOCK 433 (Continued) **S109318001**

Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000004551
Total Assessed Value:	00000019780
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1930
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0001.75
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330004
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000385
Y Coordinate:	0211681
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

D23 **SEAL-KAP PACKAGING INC** **RCRA NonGen / NLR** **1000275468**
North **11-5 44TH DR** **FINDS** **NYD061944187**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.048 mi.
256 ft. **Site 6 of 15 in cluster D**

Relative:
Lower

Actual:
13 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	SEAL-KAP PACKAGING INC
Facility address:	11-5 44TH DR LONG ISLAND CITY, NY 11101
EPA ID:	NYD061944187
Mailing address:	44TH DR LONG ISLAND CITY, NY 11101
Contact:	Not reported
Contact address:	44TH DR LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

SEAL-KAP PACKAGING INC (Continued) **1000275468**

Owner/Operator Summary:
Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: SEAL-KAP PACKAGING INC
Classification: Not a generator, verified

Date form received by agency: 12/31/1979
Facility name: SEAL-KAP PACKAGING INC
Classification: Not a generator, verified

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 03/19/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

SEAL-KAP PACKAGING INC (Continued) **1000275468**

FINDS:

Registry ID: 110004362715

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

C24 **EDR US Hist Auto Stat** **1015372098**
NW **2604 JACKSON AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.050 mi.
266 ft. **Site 2 of 5 in cluster C**

Relative:
Higher

Actual:
15 ft.

EDR Historical Auto Stations:
Name: LJ REPAIR & MAINTENANCE
Year: 2006
Address: 2604 JACKSON AVE

C25 **EDR US Hist Auto Stat** **1015379566**
WNW **2707 44TH DR** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.051 mi.
270 ft. **Site 3 of 5 in cluster C**

Relative:
Higher

Actual:
16 ft.

EDR Historical Auto Stations:
Name: CH AUTO REPAIR
Year: 2003
Address: 2707 44TH DR

Name: CH AUTO REPAIR INC
Year: 2004
Address: 2707 44TH DR

D26 **LOT 1,TAXBLOCK 433** **NY E DESIGNATION** **S109317996**
North **26-27 JACKSON AVENUE** **N/A**
< 1/8 **QUEENS, NY 11101**
0.051 mi.
271 ft. **Site 7 of 15 in cluster D**

Relative:
Lower

Actual:
13 ft.

E DESIGNATION:
Tax Lot(s): 1
E-No: E-104
Effective Date: 7/26/2001
Satisfaction Date: Not reported
Ceqr Number: 00DCP055Q
Ulurp Number: 000406(A)ZMQ
Zoning Map No: 8d, 9b
Description: Underground Gasoline Storage Tanks* Testing Protocol.

LOT 1,TAXBLOCK 433 (Continued) **S109317996**

Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	F4
Land Use Category:	06
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	2627 REALTY CORP
Lot Area:	000002000
Total Building Floor Area:	00000003900
Commercial Floor Area:	00000003900
Office Floor Area:	00000000000
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000003900
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	002.00
Residential Units:	00000
Non and Residential Units:	00001
Lot Frontage:	0020.00
Lot Depth:	0100.00
Building Frontage:	0020.00
Building Depth:	0100.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	3
Basement Type Grade:	5
Land Assessed Value:	00000027000
Total Assessed Value:	00000061200
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1945
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0001.95
Maximum Allowable Far:	10.00

LOT 1,TAXBLOCK 433 (Continued) **S109317996**

Borough Code:	4
Borough Tax Block And Lot:	4004330001
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000446
Y Coordinate:	0211678
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

Tax Lot(s):	1
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Window Wall Attenuation & Alternate Ventilation
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	F4
Land Use Category:	06
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	2627 REALTY CORP
Lot Area:	000002000
Total Building Floor Area:	00000003900
Commercial Floor Area:	00000003900
Office Floor Area:	00000000000
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000

LOT 1,TAXBLOCK 433 (Continued) **S109317996**

Storage Floor Area:	00000000000
Factory Floor Area:	00000003900
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	002.00
Residential Units:	00000
Non and Residential Units:	00001
Lot Frontage:	0020.00
Lot Depth:	0100.00
Building Frontage:	0020.00
Building Depth:	0100.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	3
Basement Type Grade:	5
Land Assessed Value:	00000027000
Total Assessed Value:	00000061200
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1945
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0001.95
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330001
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000446
Y Coordinate:	0211678
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

D27 **CONED MANHOLE#515** **NY Spills** **S106698169**
North **PURVES STREET/JACKSON** **N/A**
< 1/8 **QUEENS, NY**
0.051 mi.
271 ft. **Site 8 of 15 in cluster D**

Relative:
Lower

Actual:
13 ft.

SPILLS:

Facility ID:	0405105
DER Facility ID:	135180
Facility Type:	ER
Site ID:	160044
DEC Region:	2
Spill Date:	8/9/2004
Spill Number/Closed Date:	0405105 / 10/23/2006
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	8/10/2004
CID:	444
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	8/10/2004
Spill Record Last Update:	10/23/2006
Spiller Name:	ERT DESK
Spiller Company:	CONED MANHOLE #515
Spiller Address:	PURVES STREET/JACKSON
Spiller City,St,Zip:	QUEENS, NY
Spiller Company:	001
Contact Name:	ERT DESK
Contact Phone:	(212) 580-8383
DEC Memo:	10/23/06 - See e-docs for Con Ed report detailing cleanup and closure.Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"e2mis no. 154784:APPROX 2-GALLONS OF UNKNOWN OIL ON 150 GALLONS OF WATER IN MH-515. IT APPEARS TO BE CONTAINED. CLEANUP PENDING TEST RESULT.Lab Sequence Number: 04-06282-001 PCB <1 ppm.
Remarks:	on 150 gallons of water: TAKING OFF THE 24 HR CLOCK: NEED TIME TO GET REPAIRED ON MIDNIGHT SHIFT: NO TO 5 QUESTIOS: CONED # 154784

Material:

Site ID:	160044
Operable Unit ID:	887979
Operable Unit:	01
Material ID:	489124
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons

CONED MANHOLE#515 (Continued) **S106698169**

Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

D28 **LOT 2,TAXBLOCK 433** **NY E DESIGNATION** **S109317998**
North **26-25 JACKSON AVENUE** **N/A**
< 1/8 **QUEENS, NY 11101**
0.051 mi.
271 ft. **Site 9 of 15 in cluster D**

Relative:
Lower

Actual:
13 ft.

E DESIGNATION:

Tax Lot(s):	2
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	S2
Land Use Category:	04
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	26-25 JACKSON L.L.C.
Lot Area:	000002000
Total Building Floor Area:	00000002400
Commercial Floor Area:	00000000800
Office Floor Area:	00000000000
Retail Floor Area:	00000000800
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	003.00

LOT 2,TAXBLOCK 433 (Continued) **S109317998**

Residential Units:	00002
Non and Residential Units:	00003
Lot Frontage:	0020.00
Lot Depth:	0100.00
Building Frontage:	0020.00
Building Depth:	0040.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000006240
Total Assessed Value:	00000022380
Land Exempt Value:	00000001430
Total Exempt Value:	00000001430
Year Built:	1900
Year Built Code:	Not reported
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0001.20
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330002
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000415
Y Coordinate:	0211703
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

Tax Lot(s):	2
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Window Wall Attenuation & Alternate Ventilation
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115

LOT 2,TAXBLOCK 433 (Continued) **S109317998**

Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	S2
Land Use Category:	04
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	26-25 JACKSON L.L.C.
Lot Area:	000002000
Total Building Floor Area:	00000002400
Commercial Floor Area:	00000000800
Office Floor Area:	00000000000
Retail Floor Area:	00000000800
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	003.00
Residential Units:	00002
Non and Residential Units:	00003
Lot Frontage:	0020.00
Lot Depth:	0100.00
Building Frontage:	0020.00
Building Depth:	0040.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000006240
Total Assessed Value:	00000022380
Land Exempt Value:	00000001430
Total Exempt Value:	00000001430
Year Built:	1900
Year Built Code:	Not reported
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0001.20
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330002
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000415
Y Coordinate:	0211703
Zoning Map:	09B

LOT 2,TAXBLOCK 433 (Continued) **S109317998**

Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

D29
North
< 1/8
0.053 mi.
280 ft.

Relative:
Lower

Actual:
12 ft.

COMMERCIAL AREA **NY Spills** **S106698303**
PERVES ST/ OF JACKSON AV **N/A**
QUEENS, NY

Site 10 of 15 in cluster D

SPILLS:

Facility ID:	0405305
DER Facility ID:	150632
Facility Type:	ER
Site ID:	179492
DEC Region:	2
Spill Date:	8/14/2004
Spill Number/Closed Date:	0405305 / 10/28/2004
Spill Cause:	Equipment Failure
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	8/14/2004
CID:	71
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	8/14/2004
Spill Record Last Update:	10/28/2004
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY 10003
Spiller Company:	999
Contact Name:	ERT DESK
Contact Phone:	(212) 580-8383
DEC Memo:	ERT desk reports Location- e/s Purves St., 500 ft s/o Jackson Ave, Queen, LIC - Vactor vehicle #60624 inadvertently released 1500 gallons of oil/water substance onto street and sewer. The back latch was not fully engaged, thus when the vactor reached it capacity (1500

COMMERCIAL AREA (Continued) **S106698303**

gallons) and the vacuum stopped, the seal from the rear latched opened thus releasing it contents. Con Edison crews quickly repaired rear vactor and then vacuumed the affected sewer pumping 1500 gallons + 500 gallons from another vactor = 2000 gallons. I responded to location along with DEC Tim DeMeo & DEP Keith Williams. There were NO signs of oil in the affected sewer. Both DEC & DEP were satisfied with Con Edison's cleanup operations to the affected street & sewer. DEP Williams indicated that this sewer was a combination type which leads to a sewer treatment plant. Cleanup operation completed.

Remarks: BROKEN SEAL ON VACTOR TRUCK LEAKED 1500 GAL WHICH RAN INTO A STORM DRAIN. CLEAN UP PENDING - CREWS ON SITE. eMIS # 154890.

Material:

Site ID:	179492
Operable Unit ID:	888087
Operable Unit:	01
Material ID:	489419
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1500
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

D30 **RESIDENTS** **NY Spills** **S106009288**
North **10-33 JACKSON AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.055 mi.
292 ft. **Site 11 of 15 in cluster D**

Relative:
Lower

Actual:
11 ft.

SPILLS:

Facility ID:	0208454
DER Facility ID:	226966
Facility Type:	ER
Site ID:	279512
DEC Region:	2
Spill Date:	11/14/2002
Spill Number/Closed Date:	0208454 / 9/29/2003
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	11/14/2002
CID:	282
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported

RESIDENTS (Continued) **S106009288**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	11/14/2002
Spill Record Last Update:	9/29/2003
Spiller Name:	SAME
Spiller Company:	MYSTIC CARRIERS
Spiller Address:	19-01 STEINWAY STREET
Spiller City,St,Zip:	ASTORIA, NY 11105-
Spiller Company:	001
Contact Name:	PABLO RODRIGUEZ
Contact Phone:	(800) 635-3835
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO"9/29/03 TJDMinor spill. Cleaned by Mystic with absorbents. No further action required.
Remarks:	a faulty vent alarm caused the spill.the spill was cleaned upby mystic Not reported

Material:

Site ID:	279512
Operable Unit ID:	859877
Operable Unit:	01
Material ID:	515458
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	Yes
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

D31 **LOT 3,TAXBLOCK 433** **NY E DESIGNATION** **S109317999**
North **26-23 JACKSON AVENUE** **N/A**
< 1/8 **QUEENS, NY 11101**
0.055 mi.
292 ft. **Site 12 of 15 in cluster D**

Relative:
Lower

Actual:
11 ft.

E DESIGNATION:

Tax Lot(s):	3
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115

LOT 3,TAXBLOCK 433 (Continued) **S109317999**

Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	S2
Land Use Category:	04
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	MARIA KUI
Lot Area:	000002000
Total Building Floor Area:	00000003351
Commercial Floor Area:	00000001106
Office Floor Area:	00000000000
Retail Floor Area:	00000001106
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	003.00
Residential Units:	00002
Non and Residential Units:	00003
Lot Frontage:	0020.00
Lot Depth:	0100.00
Building Frontage:	0020.00
Building Depth:	0050.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000005291
Total Assessed Value:	00000019537
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1931
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0001.68
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330003
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000413
Y Coordinate:	0211660
Zoning Map:	09B

LOT 3,TAXBLOCK 433 (Continued) **S109317999**

Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1
Tax Lot(s):	3
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Window Wall Attenuation & Alternate Ventilation
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	S2
Land Use Category:	04
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	MARIA KUI
Lot Area:	000002000
Total Building Floor Area:	00000003351
Commercial Floor Area:	00000001106
Office Floor Area:	00000000000
Retail Floor Area:	00000001106
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	003.00
Residential Units:	00002

LOT 3,TAXBLOCK 433 (Continued) **S109317999**

Non and Residential Units:	00003
Lot Frontage:	0020.00
Lot Depth:	0100.00
Building Frontage:	0020.00
Building Depth:	0050.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000005291
Total Assessed Value:	00000019537
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1931
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0001.68
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330003
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000413
Y Coordinate:	0211660
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

D32 **EDR US Hist Auto Stat** **1015374181**
North **2626 JACKSON AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.056 mi.
296 ft. **Site 13 of 15 in cluster D**

Relative:
Lower

Actual:
13 ft.

EDR Historical Auto Stations:

Name:	CT RIDE DISCOUNT AUTO REPAIR
Year:	2002
Address:	2626 JACKSON AVE
Name:	CT RIDE DISCOUNT AUTO REPAIR
Year:	2003
Address:	2626 JACKSON AVE
Name:	CT RIDE DISCOUNT AUTO REPAIR
Year:	2004

(Continued) **1015374181**

Address: 2626 JACKSON AVE

Name: CT RIDE DISCOUNT AUTO REPAIR
Year: 2005
Address: 2626 JACKSON AVE

Name: CT RIDE DISCOUNT AUTO REPAIR
Year: 2006
Address: 2626 JACKSON AVE

C33 **SPILL NUMBER 0208224** **NY Spills** **S106009138**
WNW **JACKSON AV & 44TH DR** **N/A**
< 1/8 **QUEENS, NY**
0.057 mi.
300 ft. **Site 4 of 5 in cluster C**

Relative:
Higher

Actual:
16 ft.

SPILLS:

Facility ID:	0208224
DER Facility ID:	231269
Facility Type:	ER
Site ID:	285206
DEC Region:	2
Spill Date:	11/8/2002
Spill Number/Closed Date:	0208224 / 11/8/2002
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	11/8/2002
CID:	297
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	11/8/2002
Spill Record Last Update:	11/8/2002
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	NEW YORK, NY 10003
Spiller Company:	001
Contact Name:	KEVIN MCARDLE
Contact Phone:	(212) 580-6763
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"e2mis no. 145-953:11/08/02=0140HRSVEHICLE #603 SPILLED APPROX. 9-GALLONS OF HYDRAUKIC FLUID FROM 2" HOSE REEL DRIVE ONTO ASPHALT AT JACKSON AVE & 44 DRIVE. IT IS CONTAINED. NO SEWERS OR WATERWAYS EFFECTED. DIAPERS PLACED.CLEANUP IN PROGRESS.11/08/02=030HRSCLEANUP COMPLETED. VEHICLE WILL BE TURNED IN TO TRANSP.
Remarks:	AN HYDRAULIC LINE RUPTURED ON A CON ED REEL VEHICLE, CLEAN UP CREWS

SPILL NUMBER 0208224 (Continued) **S106009138**

ON SITE - CON ED SPILL #145953

Material:

Site ID:	285206
Operable Unit ID:	859742
Operable Unit:	01
Material ID:	515225
Material Code:	0010
Material Name:	Hydraulic Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	9
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

C34 **NYCTA** **RCRA NonGen / NLR** **1004759192**
WNW **44TH DR & JACKSON AVE** **FINDS** **NYR000001032**
< 1/8 **LONG ISLAND CITY, NY**
0.057 mi.
301 ft. **Site 5 of 5 in cluster C**

Relative:
Higher

Actual:
16 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NYCTA
Facility address:	44TH DR & JACKSON AVE LONG ISLAND CITY, NY 11101
EPA ID:	NYR000001032
Mailing address:	LIVINGSTON ST BROOKLYN, NY 112015190
Contact:	JOHN HENSLEY
Contact address:	LIVINGSTON ST BROOKLYN, NY 112015190
Contact country:	US
Contact telephone:	(516) 867-7395
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NEW YORK CITY TRANSIT AUTHORITY
Owner/operator address:	130 LIVINGSTON ST BROOKLYN, NY 11201
Owner/operator country:	US
Owner/operator telephone:	(718) 694-5290
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NEW YORK CITY TRANSIT AUTHORITY
Owner/operator address:	130 LIVINGSTON ST

NYCTA (Continued) **1004759192**

BROOKLYN, NY 11201
Owner/operator country: US
Owner/operator telephone: (718) 694-5290
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCTA
Classification: Not a generator, verified

Date form received by agency: 02/28/1995
Facility name: NYCTA
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110008088835

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

D35 NNE < 1/8 0.060 mi. 315 ft. **GASGO PETROLEUM INC**
27-01 JACKSON AVENUE
LONG ISLAND CITY, NY 11101

NY UST **U000394734**
N/A

Site 14 of 15 in cluster D

Relative: Lower

Actual: 13 ft.

UST:

Id/Status:	2-090565 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	2017/08/24
UTM X:	589379.1875
UTM Y:	4511273.5
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	2216
Affiliation Type:	Emergency Contact
Company Name:	MAZZA & AVENA INC
Contact Type:	Not reported
Contact Name:	MICHAEL MAZZA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 539-5284
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	6/8/2007

Site Id:	2216
Affiliation Type:	Facility Owner
Company Name:	MAZZA & AVENA INC
Contact Type:	PRESIDENT
Contact Name:	BALBIR S. SANDHU
Address1:	166-11 27TH AVENUE
Address2:	Not reported
City:	FLUSHING
State:	NY
Zip Code:	11358
Country Code:	001
Phone:	(718) 539-5284
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	6/8/2007

Site Id:	2216
Affiliation Type:	Mail Contact
Company Name:	MAZZA & AVENA INC
Contact Type:	Not reported
Contact Name:	MICHAEL MAZZA
Address1:	166-11 27TH AVENUE
Address2:	Not reported
City:	FLUSHING
State:	NY

GASGO PETROLEUM INC (Continued) **U000394734**

Zip Code:	11358
Country Code:	001
Phone:	(718) 539-5284
EMail:	SANDHU025@YAHOO.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/12/2012

Site Id:	2216
Affiliation Type:	On-Site Operator
Company Name:	GASGO PETROLEUM INC
Contact Type:	Not reported
Contact Name:	BALBIR S. SANDHU
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 433-2687
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	6/8/2007

Tank Info:

Tank Number:	001
Tank ID:	3507
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1956
Date Tank Closed:	02/01/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None

GASGO PETROLEUM INC (Continued) **U000394734**

Tank Number: 002
Tank ID: 3508
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1956
Date Tank Closed: 02/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
H00 - Tank Leak Detection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None

Tank Number: 003
Tank ID: 3509
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1966
Date Tank Closed: 02/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
H00 - Tank Leak Detection - None

GASGO PETROLEUM INC (Continued) **U000394734**

B00 - Tank External Protection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 004
Tank ID: 3510
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1966
Date Tank Closed: 02/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
H00 - Tank Leak Detection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None

Tank Number: 005
Tank ID: 3511
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1966
Date Tank Closed: 02/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

GASGO PETROLEUM INC (Continued) **U000394734**

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None
I00 - Overfill - None

Tank Number:	006
Tank ID:	3512
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1966
Date Tank Closed:	02/01/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number:	007
Tank ID:	3513
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1966
Date Tank Closed:	02/01/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

GASGO PETROLEUM INC (Continued) **U000394734**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser

Tank Number: 008
Tank ID: 3514
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1966
Date Tank Closed: 02/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
H00 - Tank Leak Detection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None

Tank Number: 009
Tank ID: 3515
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1966
Date Tank Closed: 02/01/2000

GASGO PETROLEUM INC (Continued) **U000394734**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None

Tank Number: 010
Tank ID: 3516
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1966
Date Tank Closed: 02/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 011

GASGO PETROLEUM INC (Continued) **U000394734**

Tank ID: 3517
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 02/01/2000
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 01/12/2012

Equipment Records:

B00 - Tank External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
C01 - Pipe Location - Aboveground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
E04 - Piping Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 012
Tank ID: 3518
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 02/01/2000
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 01/12/2012

Equipment Records:

J01 - Dispenser - Pressurized Dispenser
A03 - Tank Internal Protection - Fiberglass Liner (FRP)

GASGO PETROLEUM INC (Continued) **U000394734**

F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B04 - Tank External Protection - Fiberglass
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 013
Tank ID: 55357
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 02/01/2000
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 01/12/2012

Equipment Records:

J01 - Dispenser - Pressurized Dispenser
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
E04 - Piping Secondary Containment - Double-Walled (Underground)
B04 - Tank External Protection - Fiberglass
H05 - Tank Leak Detection - In-Tank System (ATG)
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin

Tank Number: 014
Tank ID: 55358
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 02/01/2000
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground

GASGO PETROLEUM INC (Continued) **U000394734**

Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 01/12/2012

Equipment Records:

J01 - Dispenser - Pressurized Dispenser
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
E04 - Piping Secondary Containment - Double-Walled (Underground)
B04 - Tank External Protection - Fiberglass
H05 - Tank Leak Detection - In-Tank System (ATG)
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin

D36 **EDR US Hist Auto Stat** **1015378948**
NNE **2701 JACKSON AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.062 mi.
327 ft. **Site 15 of 15 in cluster D**

Relative:
Lower

Actual:
13 ft.

EDR Historical Auto Stations:

Name: 2701 SERVICE STATION
Year: 2002
Address: 2701 JACKSON AVE

Name: JACKSON AVE AUTO REPAIR INC
Year: 2003
Address: 2701 JACKSON AVE

Name: GASGO PETROLEUM INC
Year: 2004
Address: 2701 JACKSON AVE

Name: NESTOR AUTO REPAIR INC
Year: 2005
Address: 2701 JACKSON AVE

Name: GASGO PETROLEUM INC
Year: 2006
Address: 2701 JACKSON AVE

Name: GASGO PETROLEUM INC
Year: 2007
Address: 2701 JACKSON AVE

Name: GASGO PETROLEUM INC

(Continued) **1015378948**

Year: 2008
Address: 2701 JACKSON AVE

Name: GASGO PETROLEUM INC
Year: 2009
Address: 2701 JACKSON AVE

Name: GASGO PETROLEUM INC
Year: 2010
Address: 2701 JACKSON AVE

Name: NESTOR AUTOMOBILE REPAIR INCORPORATE
Year: 2011
Address: 2701 JACKSON AVE

Name: NESTOR AUTO REPAIR INC
Year: 2012
Address: 2701 JACKSON AVE

---

37 **LONG ISLAND CITY COURTHOUSE** **NY AST** **U004159736**
West **25-10 COURTHOUSE SQUARE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.078 mi.
413 ft.

Relative:
Higher

Actual:
16 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-217042
Program Type: PBS
UTM X: 589236.58372
UTM Y: 4511172.6204700004
Expiration Date: 2017/10/15
Site Type: Municipality (Incl. Waste Water Treatment Plants,

Affiliation Records:
Site Id: 8192
Affiliation Type: On-Site Operator
Company Name: LONG ISLAND CITY COURTHOUSE
Contact Type: Not reported
Contact Name: JAMES GLENKA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 392-4230
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 12/22/2010

Site Id: 8192
Affiliation Type: Mail Contact
Company Name: NYC DEPT OF CITYWIDE ADMINISTRATIVE SERVICES
Contact Type: Not reported

LONG ISLAND CITY COURTHOUSE (Continued) **U004159736**

Contact Name:	THOMAS DECKER
Address1:	1 CENTRE STREET
Address2:	16TH FLOOR NORTH
City:	NEW YORK
State:	NY
Zip Code:	10007
Country Code:	001
Phone:	(212) 669-4890
EMail:	TDECKER@DCAS.NYC.GOV
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	12/23/2010

Site Id:	8192
Affiliation Type:	Emergency Contact
Company Name:	DCAS - JOSEPH WAGNER CHIEF ENGINEER
Contact Type:	Not reported
Contact Name:	THOMAS DECKER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 560-9176
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	9/5/2012

Site Id:	8192
Affiliation Type:	Facility Owner
Company Name:	DCAS - JOSEPH WAGNER CHIEF ENGINEER
Contact Type:	CHIEF ENGINEER
Contact Name:	JOSEPH WAGNER
Address1:	1 CENTRE STREET, 16TH FLOOR NORTH
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10007
Country Code:	001
Phone:	(212) 669-7244
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	11/6/2012

Tank Info:

Tank Number:	1
Tank Id:	22457
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I00 - Overfill - None

LONG ISLAND CITY COURTHOUSE (Continued) **U004159736**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1958
Capacity Gallons:	8000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	12/22/2010
Material Name:	#2 Fuel Oil (On-Site Consumption)

Tank Number:	2
Tank Id:	22458
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I00 - Overfill - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1958
Capacity Gallons:	12000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR

LONG ISLAND CITY COURTHOUSE (Continued) **U004159736**

Last Modified:	12/22/2010
Material Name:	#2 Fuel Oil (On-Site Consumption)
Tank Number:	3
Tank Id:	22459
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I00 - Overfill - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1958
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	12/22/2010
Material Name:	#2 Fuel Oil (On-Site Consumption)

---

38 **GASGO** **NY Spills** **S104510008**
NNE **27-01 JACKSON AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.079 mi.
416 ft.

Relative:
Lower

Actual:
13 ft.

SPILLS:

Facility ID:	9913082
DER Facility ID:	101610
Facility Type:	ER
Site ID:	116791
DEC Region:	2
Spill Date:	2/16/2000
Spill Number/Closed Date:	9913082 / Not Reported
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	JKKANN
Referred To:	WP APPRVD 5/23/13

GASGO (Continued) **S104510008**

Reported to Dept:	2/17/2000
CID:	323
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2/17/2000
Spill Record Last Update:	5/23/2013
Spiller Name:	MICHAEL MAZZA
Spiller Company:	GASGO
Spiller Address:	27-01 JACKSON AV
Spiller City,St,Zip:	LONG ISLAND CITY, ZZ
Spiller Company:	999
Contact Name:	FRANCIS ONAGA
Contact Phone:	(732) 390-0969
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ROMMEL"2/17/2000 ECO Lum was at the site and wrote a ticket for failure to notify. After Lum issued ticket, this call was received on the Hotline. Rommel said the site appeared to be within standards, tanks were excavated, soil was stock piled and covered. Anticipate sample report to be submitted soon.07/18/2005: Sent letter to Michael Mazza, site owner, requesting information. M. Brand NYSDEC DER Albany.07/27/2005: Spoke with Michael Mazza, site owner. Site was completely renovated, 10 old tanks removed, four new tanks installed, 600-700 tons of contaminated soil removed. Mazza will send in information. M. Brand NYSDEC DER Albany.08/03/2005: Received information from site owner. Information included:- Disposal tickets and invoices for the off-site disposal of 698.01 tons of contaminated soil;- Laboratory analyses for samples of stockpiled soil;- Test results for gasoline dispensers and new tanks dated 09/19/2002 (for new tanks installed in 2000);- Petroleum Bulk Storage Registration Certificate for four new tanks installed on 02/01/2000; and,- Invoice for recent inspection (03/01/2004) of facility and underground tanks by the NYC Fire Department Bureau of Fire Protection. M. Brand NYSDEC DER Albany.09/07/2005: Information reviewed and determined to be acceptable documentation of site cleanup. Site closed and NFA letter sent to site owner. M. Brand NYSDEC DER Albany.5/10/13-Vought-Received email from NYCOER Shaminder Chawla (Ph:212-442-3007 email ShaminderC@dep.nyc.gov) that "I have one Pre-App meeting today at 10 AM. Site is an old Gas station with closed spill #9913082. BTEX in soil: 139,000 ppb BTEX in gw: 353,700 ppb Attached figure indicates gw plume migration. If you are available, I like to talk about this around 9.45 AM". Attached to email was PDF with site plan and soil and groundwater data that was recently collected in 5/3/13. Vought spoke with RSE and spill reopened due to possible off-site migration of petroleum contaminants that was unknown at the time of this closure, Environmental conditions related to this spill case which were unknown to the Department at the time of this closure and information received, in whole or part, after the Department's spill case closure, which indicates the corrective action was not sufficiently protective of human health and/or the environment. Spill assigned to DEC Kann as

GASGO (Continued) **S104510008**

per RSE and Vought provided information for Kann to NYCOER Chawla. Groundwater analyticals recently collected show up to 353,700ppb BTEX and soil up to 139,000ppb BTEX. OER Chawla noted that a new purchaser has three weeks to decide to buy the site and their decision is partially based on DEC requirements and would like to set up a meeting on 5/13 to discuss. OER Chawla noted that they are looking to develop site with a slab on grade foundation with ground floor retail shops. OER Chawla noted that tank location was excavated to 11'bg to groundwater and sidewalk along 43rd Street was also excavated to 11'bg as part of a utility installation. Vought noted that a RAP must be approved prior to site development.5/10/13: J.Kann - left a phone message for Shaminder Chawla (OER) and also sent an email to him requesting any additional information that he may have on the site (i.e. is there a complete report that was prepared by Advanced Cleanup Technologies?).5/13/13: J.Kann - received a Phase II from ACT. A tank closure report from 2000 was also submitted. Scheduled a meeting for Wednesday may 15 at 9am. Spoke to Shaminder Chawla at OER and Paul Stewart of ACT. Meeting time is acceptable.5/15/13: J.Kann - met with potential buyer of the property, their attorney and environmental consultant. Shaminder Chawla of OER was also present. Sign in sheet is edoced. Discussed steps in moving forward and possible requirements for remediation (which includes off-site gw well installation and sampling, as well as on-site excavation below groundwater).5/23/13: J.Kann - recvd a work plan from ACT on 5/22/13 which included the installation of 5 off site wells. Approval letter was sent on 5/23 noting that one proposed well was on the other side of a subway line (edoced).

Remarks: WHILE UNCOVERING TANKS FOR REMOVAL, CONTAMINATED SOIL WAS DISCOVERED. SAMPLES TAKEN.

Material:

Site ID:	116791
Operable Unit ID:	1087622
Operable Unit:	01
Material ID:	294942
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

39
WNW
< 1/8
0.080 mi.
421 ft.

LOT 12,TAXBLOCK 433
25-25 44 DRIVE
QUEENS, NY 11101

NY E DESIGNATION

S108469532
N/A

Relative:
Higher

Actual:
17 ft.

E DESIGNATION:

Tax Lot(s):	12
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	O6
Land Use Category:	05
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	2525 44 DRIVE LLC C/O
Lot Area:	000020000
Total Building Floor Area:	00000004320
Commercial Floor Area:	00000004320
Office Floor Area:	00000004320
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	001.00
Residential Units:	00000
Non and Residential Units:	00001
Lot Frontage:	0128.00
Lot Depth:	0115.50
Building Frontage:	0080.00
Building Depth:	0054.00
Proximity Code:	0
Irregular Lot Code:	Y
Lot Type:	3

LOT 12,TAXBLOCK 433 (Continued) **S108469532**

Basement Type Grade:	5
Land Assessed Value:	00000202500
Total Assessed Value:	00000315000
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1964
Year Built Code:	Not reported
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0000.22
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330012
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000165
Y Coordinate:	0211633
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

Tax Lot(s):	12
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Window Wall Attenuation & Alternate Ventilation
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC

LOT 12,TAXBLOCK 433 (Continued) **S108469532**

All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	O6
Land Use Category:	05
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	2525 44 DRIVE LLC C/O
Lot Area:	000020000
Total Building Floor Area:	00000004320
Commercial Floor Area:	00000004320
Office Floor Area:	00000004320
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	001.00
Residential Units:	00000
Non and Residential Units:	00001
Lot Frontage:	0128.00
Lot Depth:	0115.50
Building Frontage:	0080.00
Building Depth:	0054.00
Proximity Code:	0
Irregular Lot Code:	Y
Lot Type:	3
Basement Type Grade:	5
Land Assessed Value:	00000202500
Total Assessed Value:	00000315000
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1964
Year Built Code:	Not reported
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0000.22
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330012
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000165
Y Coordinate:	0211633
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006

LOT 12,TAXBLOCK 433 (Continued) **S108469532**

Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

E40
NNE
< 1/8
0.089 mi.
471 ft.

MANHOLE # 2353
JACKSON VAE/DUTCHKILL STR
QUEENS, NY

NY Spills **S106720457**
N/A

Site 1 of 6 in cluster E

Relative:
Higher

Actual:
14 ft.

SPILLS:

Facility ID:	0409173
DER Facility ID:	269247
Facility Type:	ER
Site ID:	334038
DEC Region:	2
Spill Date:	11/11/2004
Spill Number/Closed Date:	0409173 / 1/13/2005
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	11/11/2004
CID:	41
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	11/19/2004
Spill Record Last Update:	5/31/2005
Spiller Name:	ERT DESK
Spiller Company:	MANHOLE # 2353
Spiller Address:	JACKSON VAE/DUTCHKILL STR
Spiller City,St,Zip:	QUEENS, NY
Spiller Company:	001
Contact Name:	ERT DESK
Contact Phone:	(212) 580-8383
DEC Memo:	11/11/04 1326hrs - Paul Kelly found 1 gallon unknown oil on 300 gallons water in M2353. No fire/smoke involved. No sewers or waterways affected. No private property affected. Sample taken. Env. stop tag # 42315 placed. Clean up pending test results. UPDATE 11/11/04 18:27 HRS AS PER PRIOR SOAAX ON DESK THIS IS BEING CLEANED AS 50-499, A TANKER HAS BEEN ORDERED, NO EPA REQUIRED PER MANIFEST PROGRAM, THIS FEEDER 1Q07 IS CURRENTLY OFF.UPDATE 11/11/04 18:53 HRS ENV SUPV J. DEKANCHUK REPORTS FINDING AN EARTHEN SUMP, INCIDENT TO BE REMOVED FROM 24 HOUR PROGRAM.UPDATE 11/11/04 19:48 HRS EPA NYP 004 126 801 ISSUED FOR 3 BARRELS OF WASTE AND PPE.Lab Sequence Number: 04-09409-001 - PCBs < 1 ppmOPERATING SUPERVISOR J. DEKANCHUK REPORTS 50 - 499 CLEAN UP PERFORMED. CORP. TANKER REMOVED 590 GALS OF WATER FROM MH 2353. ENVIRONMENTAL OPS CREW REMOVED THREE BARRELS OF SOLID WASTE. A EARTHEN SUMP WAS FOUND. SUMP WAS DUG OUT TO CLEAN SOIL AND

MANHOLE # 2353 (Continued) **S106720457**

SAMPLED. SUMP WAS SEALED WITH CEMENT. MH WAS DOUBLE WASHED WITH BIO GEN 760, WASH WATER WAS PUMPED INTO TANKER. BARRELS WERE PICKED UP BY ASTORIA TRANSPORTATION. A S PER PHONE CALL TO ASTORIA CHEM LAB PCB RESULTS WERE LESS THAN ONE PPM. ENVIRONMENTAL TAG # 42315 WAS REMOVED JOB IS COMPLETE AS OF 2215 HRS11-11-04

Remarks: ON 300 GALLONS OF WATER: CONED # 156214

Material:

Tank Test:

E41
NNE
< 1/8
0.089 mi.
472 ft.

Relative:
Higher

Actual:
14 ft.

NYSDOT - THOMSON AVENUE BRIDGE
JACKSON AVE & DUTCH KILLS RD
LONG ISLAND CITY, NY

RCRA NonGen / NLR **1000554113**
FINDS **NYD986965705**

Site 2 of 6 in cluster E

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NYSDOT - THOMSON AVENUE BRIDGE
Facility address:	JACKSON AVE & DUTCH KILLS RD LONG ISLAND CITY, NY 11101
EPA ID:	NYD986965705
Mailing address:	JACKSON AVE LONG ISLAND CITY, NY 11101
Contact:	JOSEPH FARO
Contact address:	JACKSON AVE LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	(718) 786-7017
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYSDOT
Owner/operator address:	ONE HUNTERS POINT PLZ LONG ISLAND CITY, NY 11101
Owner/operator country:	US
Owner/operator telephone:	(718) 482-4801
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NYSDOT
Owner/operator address:	ONE HUNTERS POINT PLZ LONG ISLAND CITY, NY 11101
Owner/operator country:	US
Owner/operator telephone:	(718) 482-4801
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

NYSDOT - THOMSON AVENUE BRIDGE (Continued) **1000554113**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYSDOT - THOMSON AVENUE BRIDGE
Classification: Not a generator, verified

Date form received by agency: 08/02/1991
Facility name: NYSDOT - THOMSON AVENUE BRIDGE
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110008064995

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

F42 **LOT 35,TAXBLOCK 433** **NY E DESIGNATION** **S108469561**
NNW **43-15 HUNTER STREET** **N/A**
< 1/8 **QUEENS, NY 11101**
0.099 mi.
522 ft. **Site 1 of 7 in cluster F**

Relative:
Lower

Actual:
11 ft.

E DESIGNATION:
Tax Lot(s): 35
E-No: E-104
Effective Date: 7/26/2001
Satisfaction Date: Not reported
Ceqr Number: 00DCP055Q
Ulurp Number: 000406(A)ZMQ
Zoning Map No: 8d, 9b
Description: Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code: QN

LOT 35,TAXBLOCK 433 (Continued) **S108469561**

Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	B2
Land Use Category:	01
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	43-15 HUNTER STREET,
Lot Area:	000002500
Total Building Floor Area:	00000001992
Commercial Floor Area:	00000000000
Office Floor Area:	00000000000
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	002.00
Residential Units:	00002
Non and Residential Units:	00002
Lot Frontage:	0025.00
Lot Depth:	0100.00
Building Frontage:	0025.00
Building Depth:	0036.00
Proximity Code:	2
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	2
Land Assessed Value:	00000003330
Total Assessed Value:	00000018679
Land Exempt Value:	00000001430
Total Exempt Value:	00000001430
Year Built:	1920
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0000.80
Maximum Allowable Far:	10.00
Borough Code:	4

LOT 35,TAXBLOCK 433 (Continued) **S108469561**

Borough Tax Block And Lot:	4004330035
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000273
Y Coordinate:	0211765
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1
Tax Lot(s):	35
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Window Wall Attenuation & Alternate Ventilation
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	B2
Land Use Category:	01
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	43-15 HUNTER STREET,
Lot Area:	000002500
Total Building Floor Area:	00000001992
Commercial Floor Area:	00000000000
Office Floor Area:	00000000000
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000

LOT 35,TAXBLOCK 433 (Continued) **S108469561**

Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	002.00
Residential Units:	00002
Non and Residential Units:	00002
Lot Frontage:	0025.00
Lot Depth:	0100.00
Building Frontage:	0025.00
Building Depth:	0036.00
Proximity Code:	2
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	2
Land Assessed Value:	00000003330
Total Assessed Value:	00000018679
Land Exempt Value:	00000001430
Total Exempt Value:	00000001430
Year Built:	1920
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0000.80
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330035
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000273
Y Coordinate:	0211765
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

F43 **LOT 31,TAXBLOCK 433** **NY E DESIGNATION** **S108469556**
NNW **43-25 HUNTER STREET** **N/A**
< 1/8 **QUEENS, NY 11101**
0.100 mi.
526 ft. **Site 2 of 7 in cluster F**

Relative:
Lower

Actual:
11 ft.

E DESIGNATION:

Tax Lot(s):	31
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported

LOT 31,TAXBLOCK 433 (Continued) **S108469556**

Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	F1
Land Use Category:	06
Number of Easements:	0
Owner, Type of Code:	P
Owner Name:	CENTRALIZED LABORATOR
Lot Area:	000014292
Total Building Floor Area:	00000020000
Commercial Floor Area:	00000020000
Office Floor Area:	00000010000
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000010000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	002.00
Residential Units:	00000
Non and Residential Units:	00001
Lot Frontage:	0100.00
Lot Depth:	0200.00
Building Frontage:	0100.00
Building Depth:	0100.00
Proximity Code:	0
Irregular Lot Code:	Y
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000193500
Total Assessed Value:	00000549000
Land Exempt Value:	00000193500
Total Exempt Value:	00000549000
Year Built:	1930
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000

LOT 31,TAXBLOCK 433 (Continued) **S108469556**

Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0001.40
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330031
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000226
Y Coordinate:	0211723
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

Tax Lot(s):	31
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Window Wall Attenuation & Alternate Ventilation
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	F1
Land Use Category:	06
Number of Easements:	0
Owner, Type of Code:	P
Owner Name:	CENTRALIZED LABORATOR
Lot Area:	000014292
Total Building Floor Area:	00000020000

LOT 31,TAXBLOCK 433 (Continued) **S108469556**

Commercial Floor Area:	00000020000
Office Floor Area:	00000010000
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000010000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	002.00
Residential Units:	00000
Non and Residential Units:	00001
Lot Frontage:	0100.00
Lot Depth:	0200.00
Building Frontage:	0100.00
Building Depth:	0100.00
Proximity Code:	0
Irregular Lot Code:	Y
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000193500
Total Assessed Value:	00000549000
Land Exempt Value:	00000193500
Total Exempt Value:	00000549000
Year Built:	1930
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0001.40
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330031
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000226
Y Coordinate:	0211723
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

F44 **CENTRALIZED LAB SERVICES INC** **RCRA NonGen / NLR** **1000418525**
NNW **43-25 HUNTER ST** **FINDS** **NYD057430100**
< 1/8 **LONG ISLAND CITY, NY 11101** **NY MANIFEST**
0.100 mi.
526 ft. **Site 3 of 7 in cluster F**

Relative:
Lower

Actual:
11 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	CENTRALIZED LAB SERVICES INC
Facility address:	43-25 HUNTER ST LONG ISLAND CITY, NY 11101
EPA ID:	NYD057430100
Mailing address:	HUNTER ST LONG ISLAND CITY, NY 11101
Contact:	Not reported
Contact address:	HUNTER ST LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

CENTRALIZED LAB SERVICES INC (Continued) **1000418525**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: CENTRALIZED LAB SERVICES INC
Classification: Not a generator, verified

Date form received by agency: 12/31/1979
Facility name: CENTRALIZED LAB SERVICES INC
Classification: Unverified

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 07/17/1989
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004360851

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD057430100
Country: USA
Mailing Name: CENTRALIZED LAB SERVICES INC
Mailing Contact: CENTRALIZED LAB SERVICES INC
Mailing Address: 43-25 HUNTER ST
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-786-2300

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: Not reported
Generator Ship Date: 2008-11-19

CENTRALIZED LAB SERVICES INC (Continued) **1000418525**

Trans1 Recv Date:	2008-11-19
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-11-19
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD057430100
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	80.0
Units:	P - Pounds
Number of Containers:	4.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	002447732FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2008-10-10
Trans1 Recv Date:	2008-10-10
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-10-10
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD057430100
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	130.0
Units:	P - Pounds
Number of Containers:	13.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	002446217FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N

CENTRALIZED LAB SERVICES INC (Continued) **1000418525**

Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

F45 **LOT 36,TAXBLOCK 433** **NY E DESIGNATION** **S108469562**
NNW **43-11 HUNTER STREET** **N/A**
< 1/8 **QUEENS, NY 11101**
0.100 mi.
526 ft. **Site 4 of 7 in cluster F**

Relative:
Lower

Actual:
11 ft.

E DESIGNATION:

Tax Lot(s):	36
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	F9
Land Use Category:	06
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	43-11 HUNTER STREET,
Lot Area:	000002500
Total Building Floor Area:	00000000500
Commercial Floor Area:	00000000500
Office Floor Area:	00000000000
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000000500
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001

LOT 36,TAXBLOCK 433 (Continued) **S108469562**

Number of Floors:	001.00
Residential Units:	00000
Non and Residential Units:	00001
Lot Frontage:	0025.00
Lot Depth:	0100.00
Building Frontage:	0020.00
Building Depth:	0025.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000029250
Total Assessed Value:	00000033885
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1916
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0000.20
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330036
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000306
Y Coordinate:	0211744
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

Tax Lot(s):	36
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Window Wall Attenuation & Alternate Ventilation
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26

LOT 36,TAXBLOCK 433 (Continued) **S108469562**

Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	F9
Land Use Category:	06
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	43-11 HUNTER STREET,
Lot Area:	000002500
Total Building Floor Area:	00000000500
Commercial Floor Area:	00000000500
Office Floor Area:	00000000000
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000000500
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	001.00
Residential Units:	00000
Non and Residential Units:	00001
Lot Frontage:	0025.00
Lot Depth:	0100.00
Building Frontage:	0020.00
Building Depth:	0025.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000029250
Total Assessed Value:	00000033885
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1916
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0000.20
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330036
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000306
Y Coordinate:	0211744

LOT 36,TAXBLOCK 433 (Continued) **S108469562**

Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

F46 **LOT 37,TAXBLOCK 433** **NY E DESIGNATION** **S108469563**
NNW **43-09 HUNTER STREET** **N/A**
< 1/8 **QUEENS, NY 11101**
0.101 mi.
531 ft. **Site 5 of 7 in cluster F**

Relative:
Lower

Actual:
12 ft.

E DESIGNATION:

Tax Lot(s):	37
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	B1
Land Use Category:	01
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	43-09 HUNTER STREET,
Lot Area:	000002500
Total Building Floor Area:	00000001900
Commercial Floor Area:	00000000000
Office Floor Area:	00000000000
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000

LOT 37,TAXBLOCK 433 (Continued) **S108469563**

Storage Floor Area:	00000000000
Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	002.00
Residential Units:	00002
Non and Residential Units:	00002
Lot Frontage:	0025.00
Lot Depth:	0100.00
Building Frontage:	0025.00
Building Depth:	0038.00
Proximity Code:	3
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	2
Land Assessed Value:	00000003187
Total Assessed Value:	00000017572
Land Exempt Value:	00000001430
Total Exempt Value:	00000001430
Year Built:	1920
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0000.76
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330037
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000313
Y Coordinate:	0211785
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

Tax Lot(s):	37
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Window Wall Attenuation & Alternate Ventilation
Borough Code:	QN

LOT 37,TAXBLOCK 433 (Continued) **S108469563**

Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	B1
Land Use Category:	01
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	43-09 HUNTER STREET,
Lot Area:	000002500
Total Building Floor Area:	00000001900
Commercial Floor Area:	00000000000
Office Floor Area:	00000000000
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	002.00
Residential Units:	00002
Non and Residential Units:	00002
Lot Frontage:	0025.00
Lot Depth:	0100.00
Building Frontage:	0025.00
Building Depth:	0038.00
Proximity Code:	3
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	2
Land Assessed Value:	00000003187
Total Assessed Value:	00000017572
Land Exempt Value:	00000001430
Total Exempt Value:	00000001430
Year Built:	1920
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0000.76
Maximum Allowable Far:	10.00
Borough Code:	4

LOT 37,TAXBLOCK 433 (Continued) **S108469563**

Borough Tax Block And Lot:	4004330037
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000313
Y Coordinate:	0211785
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

F47 **SPILL NUMBER 0105318** **NY LTANKS** **S105135086**
NNW **43-09 HUNTERS STREET** **NY Spills** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.101 mi.
531 ft. **Site 6 of 7 in cluster F**

Relative:
Lower

Actual:
12 ft.

LTANKS:

Site ID:	242115
Spill Number/Closed Date:	0105318 / 6/30/2003
Spill Date:	8/16/2001
Spill Cause:	Tank Overfill
Spill Source:	Commercial Vehicle
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	8/16/2001
CID:	207
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	8/16/2001
Spill Record Last Update:	6/30/2003
Spiller Name:	CALLER
Spiller Company:	MB TRUCKING
Spiller Address:	1281 VIELE AV
Spiller City,St,Zip:	BRONX, NY 10474-
Spiller County:	001
Spiller Contact:	GABE RICCI
Spiller Phone:	(718) 328-3275
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	262305

SPILL NUMBER 0105318 (Continued) **S105135086**

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"
Remarks: cleanup completed

Material:
Site ID: 242115
Operable Unit ID: 842224
Operable Unit: 01
Material ID: 533792
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 3
Units: Gallons
Recovered: 3
Resource Affected: Not reported
Oxygenate: False

Tank Test:

SPILLS:
Facility ID: 9809062
DER Facility ID: 262305
Facility Type: ER
Site ID: 325643
DEC Region: 2
Spill Date: 10/20/1998
Spill Number/Closed Date: 9809062 / 10/21/1998
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 4101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 10/20/1998
CID: 282
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/20/1998
Spill Record Last Update: 5/14/2002
Spiller Name: MR THOMSEN
Spiller Company: MR THOMSEN
Spiller Address: 43-09 HUNTERS STREET
Spiller City,St,Zip: LONG ISLAND CITY, NY 11101-
Spiller Company: 001
Contact Name: MR THOMSEN
Contact Phone: (212) 932-0480

SPILL NUMBER 0105318 (Continued) **S105135086**

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE"CLEANED BY RP.
Remarks: PIPE FAILED LEADING TO THE TANK.TANK IS IN THE BASEMENT.SPILL WENT ONTO THE PLATFORM NEAR THE TANK SPILL WAS CLEANED UP THEY STATEDEXACT AMOUNT WAS UNKNOWN.

Material:
Site ID: 325643
Operable Unit ID: 1070254
Operable Unit: 01
Material ID: 316526
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

G48 **LOT 41,TAXBLOCK 433** **NY E DESIGNATION** **S108469568**
North **27-10 43 AVENUE** **N/A**
< 1/8 **QUEENS, NY 11101**
0.101 mi.
534 ft. **Site 1 of 8 in cluster G**

Relative:
Lower

Actual:
12 ft.

E DESIGNATION:
Tax Lot(s): 41
E-No: E-104
Effective Date: 7/26/2001
Satisfaction Date: Not reported
Ceqr Number: 00DCP055Q
Ulurp Number: 000406(A)ZMQ
Zoning Map No: 8d, 9b
Description: Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code: QN
Community District: 402
Census Tract: 19
Census Block: 2048
School District: 30
City Council District: 26
Fire Company: L115
Health Area: 41
Police Precinct: 108
Zone District 1: M1-6/R10
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: LIC
Special Purpose District2: Not reported
All Components1: M1-6/R10/LIC
All Components2: Not reported
Split Boundary Indicator: N
Building Class: G9

LOT 41,TAXBLOCK 433 (Continued) **S108469568**

Land Use Category:	07
Number of Easements:	0
Owner, Type of Code:	P
Owner Name:	COMASKEY HOLDINGS,
Lot Area:	000002000
Total Building Floor Area:	00000002250
Commercial Floor Area:	00000002250
Office Floor Area:	00000000250
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000002000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	001.00
Residential Units:	00000
Non and Residential Units:	00001
Lot Frontage:	0025.00
Lot Depth:	0080.00
Building Frontage:	0025.00
Building Depth:	0080.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000027000
Total Assessed Value:	00000063000
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1916
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0001.13
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330041
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000399
Y Coordinate:	0211751
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

LOT 41,TAXBLOCK 433 (Continued) **S108469568**

Tax Lot(s):	41
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Window Wall Attenuation & Alternate Ventilation
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	G9
Land Use Category:	07
Number of Easements:	0
Owner, Type of Code:	P
Owner Name:	COMASKEY HOLDINGS,
Lot Area:	000002000
Total Building Floor Area:	00000002250
Commercial Floor Area:	00000002250
Office Floor Area:	00000000250
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000002000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	001.00
Residential Units:	00000
Non and Residential Units:	00001
Lot Frontage:	0025.00
Lot Depth:	0080.00
Building Frontage:	0025.00
Building Depth:	0080.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000027000
Total Assessed Value:	00000063000
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000

LOT 41,TAXBLOCK 433 (Continued) **S108469568**

Year Built:	1916
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0001.13
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330041
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000399
Y Coordinate:	0211751
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

F49 **49 HUNTER PLACE/S.I.** **NY Spills** **S102146133**
NNW **49 HUNTER PLACE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.101 mi.
535 ft. **Site 7 of 7 in cluster F**

Relative:
Lower

Actual:
11 ft.

SPILLS:

Facility ID:	9011053
DER Facility ID:	59223
Facility Type:	ER
Site ID:	60720
DEC Region:	2
Spill Date:	1/17/1991
Spill Number/Closed Date:	9011053 / 1/17/1991
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	4301
Investigator:	JAMES
Referred To:	Not reported
Reported to Dept:	1/17/1991
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	1/17/1991
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

49 HUNTER PLACE/S.I. (Continued) **S102146133**

Date Entered In Computer:	1/29/1991
Spill Record Last Update:	9/30/2004
Spiller Name:	Not reported
Spiller Company:	DONITA ARUNY
Spiller Address:	49 HUNTER PLACE
Spiller City,St,Zip:	STATEN ISLAND, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	DURING ROUTINE MAINTENANCE OF OIL STORAGE SYSTEM OIL WAS DISCOVERED INMORNING,OIL FOUND ON FLOOR IN BASEMENT, CITGO REPAIRING LINES, DEC TO FOLLOW UP AS NEEDED.

Material:

Site ID:	60720
Operable Unit ID:	948079
Operable Unit:	01
Material ID:	431147
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

G50 **EDR US Hist Auto Stat** **1015379502**
North **2706 43RD AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.102 mi.
538 ft. **Site 2 of 8 in cluster G**

Relative:
Lower

Actual:
12 ft.

EDR Historical Auto Stations:

Name:	RUNWELL AUTO REPAIRS
Year:	1999
Address:	2706 43RD AVE
Name:	RUNWELL AUTO REPAIRS
Year:	2000
Address:	2706 43RD AVE
Name:	RUNWELL AUTO REPAIRS
Year:	2001
Address:	2706 43RD AVE
Name:	RUNWELL AUTO REPAIRS
Year:	2002
Address:	2706 43RD AVE
Name:	RUNWELL AUTO REPAIRS
Year:	2003
Address:	2706 43RD AVE

(Continued) **1015379502**

Name: RUNWELL AUTO REPAIRS INC
Year: 2004
Address: 2706 43RD AVE

Name: RUNWELLS AUTO SHOP & REPAIR INC
Year: 2005
Address: 2706 43RD AVE

Name: RUNWELLS AUTO SHOP & REPAIR INC
Year: 2006
Address: 2706 43RD AVE

Name: RUNWELLS AUTO SHOP & REPAIR INC
Year: 2007
Address: 2706 43RD AVE

Name: RUNWELLS AUTO SHOP & REPAIR INC
Year: 2008
Address: 2706 43RD AVE

G51 **EDR US Hist Auto Stat** **1015379565**
North **2707 43RD AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.103 mi.
543 ft. **Site 3 of 8 in cluster G**

Relative:
Lower

Actual:
12 ft.

EDR Historical Auto Stations:

Name: ENGINE FACTORY
Year: 1999
Address: 2707 43RD AVE

Name: ENGINE FACTORY
Year: 2000
Address: 2707 43RD AVE

Name: ENGINE FACTORY
Year: 2003
Address: 2707 43RD AVE

Name: ENGINE FACTORY
Year: 2004
Address: 2707 43RD AVE

H52 **COURT SQUARE** **RCRA-SQG** **1000694118**
WSW **45-18 COURT SQ** **FINDS** **NYD987003910**
< 1/8 **LONG ISLAND CITY, NY** **NY MANIFEST**
0.103 mi.
545 ft. **Site 1 of 8 in cluster H**

Relative:
Higher

Actual:
14 ft.

RCRA-SQG:
Date form received by agency: 08/28/2012
Facility name: TRANE CO THE
Facility address: 45-18 COURT SQ
LONG ISLAND CITY, NY 11101
EPA ID: NYD987003910
Mailing address: COURT SQ

COURT SQUARE (Continued) **1000694118**

LONG ISLAND CITY, NY 11101
Contact: TOM E KELLY
Contact address: COURT SQ
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: (718) 269-3647
Contact email: THOMAS.KELLY@TRANE.COM
EPA Region: 02
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: THE TRANE CO
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1994
Owner/Op end date: Not reported

Owner/operator name: THE TRANE CO
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1994
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2007
Facility name: TRANE CO THE

COURT SQUARE (Continued) **1000694118**

Site name: COURT SQUARE
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Facility name: TRANE CO THE
Site name: COURT SQUARE
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: TRANE CO THE
Site name: COURT SQUARE
Classification: Not a generator, verified

Date form received by agency: 05/12/1992
Facility name: TRANE CO THE
Site name: COURT SQUARE
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: D008
Waste name: LEAD

Violation Status: No violations found

FINDS:

Registry ID: 110008075830

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD987003910
Country: USA
Mailing Name: COURT SQUARE
Mailing Contact: WILLIAM R KLEIN
Mailing Address: 60 EAST 56 STREET
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10022
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-751-4620

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000081205
Trans2 State ID: NJD071629976
Generator Ship Date: 24-Apr-2013 00:00:00

COURT SQUARE (Continued) **1000694118**

Trans1 Recv Date:	24-Apr-2013 00:00:00
Trans2 Recv Date:	26-Apr-2013 00:00:00
TSD Site Recv Date:	10-May-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987003910
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	800
Units:	P - Pounds
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	003310586SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	NYB5586084
Manifest Status:	Completed copy
Trans1 State ID:	HL4120
Trans2 State ID:	Not reported
Generator Ship Date:	920623
Trans1 Recv Date:	920623
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	920623
Part A Recv Date:	920716
Part B Recv Date:	920702
Generator EPA ID:	NYD987003910
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00020
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	92

Document ID:	Not reported
Manifest Status:	Not reported

COURT SQUARE (Continued) **1000694118**

Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2012-08-22
Trans1 Recv Date:	2012-08-22
Trans2 Recv Date:	2012-09-05
TSD Site Recv Date:	2012-09-06
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987003910
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	800.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	003309111SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2012-08-22
Trans1 Recv Date:	2012-08-22
Trans2 Recv Date:	2012-09-05
TSD Site Recv Date:	2012-09-06
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987003910
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	800.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	003309111SKS

COURT SQUARE (Continued) **1000694118**

Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000081205
Trans2 State ID:	NJD071629976
Generator Ship Date:	2012-11-07
Trans1 Recv Date:	2012-11-07
Trans2 Recv Date:	2012-11-12
TSD Site Recv Date:	2012-11-19
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987003910
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	1200.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	003310531SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

G53 **LOT 39,TAXBLOCK 433** **NY E DESIGNATION** **S108469566**
North **27-06 43 AVENUE** **N/A**
< 1/8 **QUEENS, NY 11101**
0.103 mi.
545 ft. **Site 4 of 8 in cluster G**

Relative:
Lower

Actual:
12 ft.

E DESIGNATION:

Tax Lot(s):	39
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	G2
Land Use Category:	10
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	LIEBERMAN, DONALD
Lot Area:	000004000
Total Building Floor Area:	00000004000
Commercial Floor Area:	00000004000
Office Floor Area:	00000000000
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000004000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	001.00
Residential Units:	00000
Non and Residential Units:	00001
Lot Frontage:	0050.00
Lot Depth:	0080.00
Building Frontage:	0050.00
Building Depth:	0080.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5

LOT 39,TAXBLOCK 433 (Continued) **S108469566**

Basement Type Grade:	5
Land Assessed Value:	00000054000
Total Assessed Value:	00000121950
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1931
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0001.00
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330039
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000360
Y Coordinate:	0211769
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

Tax Lot(s):	39
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Window Wall Attenuation & Alternate Ventilation
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC

LOT 39,TAXBLOCK 433 (Continued) **S108469566**

All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	G2
Land Use Category:	10
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	LIEBERMAN, DONALD
Lot Area:	000004000
Total Building Floor Area:	00000004000
Commercial Floor Area:	00000004000
Office Floor Area:	00000000000
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000004000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	001.00
Residential Units:	00000
Non and Residential Units:	00001
Lot Frontage:	0050.00
Lot Depth:	0080.00
Building Frontage:	0050.00
Building Depth:	0080.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000054000
Total Assessed Value:	00000121950
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1931
Year Built Code:	E
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0001.00
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330039
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000360
Y Coordinate:	0211769
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006

LOT 39,TAXBLOCK 433 (Continued) **S108469566**

Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

G54 **EDR US Hist Auto Stat** **1015379128**
North **2702 43RD AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.104 mi.
548 ft. **Site 5 of 8 in cluster G**

Relative:
Lower

Actual:
12 ft.

EDR Historical Auto Stations:

Name: HUNTER AUTO
Year: 2001
Address: 2702 43RD AVE

Name: HUNTER AUTO
Year: 2002
Address: 2702 43RD AVE

Name: T & T AUTO REPAIR & AUTO BODY
Year: 2004
Address: 2702 43RD AVE

Name: T AUTO REPAIR & AUTO BODY
Year: 2006
Address: 2702 43RD AVE

Name: T & T AUTO REPAIR & AUTO BODY
Year: 2007
Address: 2702 43RD AVE

Name: T & T AUTO REPAIR & AUTO BODY
Year: 2008
Address: 2702 43RD AVE

Name: TNT AUTO BODY
Year: 2010
Address: 2702 43RD AVE

Name: TNT AUTO BODY
Year: 2011
Address: 2702 43RD AVE

Name: TNT AUTO BODY
Year: 2012
Address: 2702 43RD AVE

G55 **LOT 38,TAXBLOCK 433** **NY E DESIGNATION** **S108469565**
North **27-02 43 AVENUE** **N/A**
< 1/8 **QUEENS, NY 11101**
0.105 mi.
557 ft. **Site 6 of 8 in cluster G**

Relative:
Lower

Actual:
12 ft.

E DESIGNATION:

Tax Lot(s):	38
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	G9
Land Use Category:	07
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	P A R 328 ASSOCIATES,
Lot Area:	000002000
Total Building Floor Area:	00000004000
Commercial Floor Area:	00000004000
Office Floor Area:	00000002000
Retail Floor Area:	00000000000
Garage Floor Area:	00000002000
Storage Floor Area:	00000000000
Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	002.00
Residential Units:	00000
Non and Residential Units:	00002
Lot Frontage:	0025.00
Lot Depth:	0080.00
Building Frontage:	0025.00
Building Depth:	0080.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	3

LOT 38,TAXBLOCK 433 (Continued) **S108469565**

Basement Type Grade:	5
Land Assessed Value:	00000027000
Total Assessed Value:	00000123750
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1916
Year Built Code:	E
Year Altered1:	1996
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0002.00
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330038
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000368
Y Coordinate:	0211816
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

Tax Lot(s):	38
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Window Wall Attenuation & Alternate Ventilation
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	2048
School District:	30
City Council District:	26
Fire Company:	L115
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-6/R10
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-6/R10/LIC

LOT 38,TAXBLOCK 433 (Continued) **S108469565**

All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	G9
Land Use Category:	07
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	P A R 328 ASSOCIATES,
Lot Area:	000002000
Total Building Floor Area:	00000004000
Commercial Floor Area:	00000004000
Office Floor Area:	00000002000
Retail Floor Area:	00000000000
Garage Floor Area:	00000002000
Storage Floor Area:	00000000000
Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	002.00
Residential Units:	00000
Non and Residential Units:	00002
Lot Frontage:	0025.00
Lot Depth:	0080.00
Building Frontage:	0025.00
Building Depth:	0080.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	3
Basement Type Grade:	5
Land Assessed Value:	00000027000
Total Assessed Value:	00000123750
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1916
Year Built Code:	E
Year Altered1:	1996
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0002.00
Maximum Allowable Far:	10.00
Borough Code:	4
Borough Tax Block And Lot:	4004330038
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000368
Y Coordinate:	0211816
Zoning Map:	09B
Sanborn Map:	401 025
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006

LOT 38,TAXBLOCK 433 (Continued) **S108469565**

Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

G56 **MTA NYCT - VENT PLANT 5103** **NY MANIFEST** **S110306083**
North **HUNTER ST & 43RD AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.107 mi.
563 ft. **Site 7 of 8 in cluster G**

Relative:
Lower

Actual:
12 ft.

NY MANIFEST:

EPA ID:	NYR000171173
Country:	USA
Mailing Name:	MTA NYCT - VENT PLANT 5103
Mailing Contact:	MTA NYCT - VENT PLANT 5103
Mailing Address:	2 BROADWAY ROOM A27.64
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	646-252-5777
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2010-04-01
Trans1 Recv Date:	2010-04-01
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-04-01
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171173
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	120.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	000959575GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

MTA NYCT - VENT PLANT 5103 (Continued) **S110306083**

Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2010-04-01
Trans1 Recv Date: 2010-04-01
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-04-01
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000171173
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 400.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 000959575GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2011-02-15
Trans1 Recv Date: 2011-02-15
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2011-02-15
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000171173
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 100.0
Units: P - Pounds
Number of Containers: 1.0

MTA NYCT - VENT PLANT 5103 (Continued) **S110306083**

Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	001056812GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2011-02-15
Trans1 Recv Date:	2011-02-15
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2011-02-15
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171173
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	001056812GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193

MTA NYCT - VENT PLANT 5103 (Continued) **S110306083**

Trans2 State ID:	Not reported
Generator Ship Date:	2011-06-24
Trans1 Recv Date:	2011-06-24
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2011-06-24
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171173
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	40.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	003534930JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2010-04-01
Trans1 Recv Date:	2010-04-01
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-04-01
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171173
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	400.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	000959575GBF
Import Ind:	N

MTA NYCT - VENT PLANT 5103 (Continued) **S110306083**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2010-04-01
Trans1 Recv Date:	2010-04-01
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-04-01
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171173
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	120.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	000959575GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2010-05-06
Trans1 Recv Date:	2010-05-06
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-05-06
Part A Recv Date:	Not reported

MTA NYCT - VENT PLANT 5103 (Continued) **S110306083**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171173
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	120.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	001055884GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2010-05-06
Trans1 Recv Date:	2010-05-06
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-05-06
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171173
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	120.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	001055884GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

MTA NYCT - VENT PLANT 5103 (Continued) **S110306083**

Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2010-05-06
Trans1 Recv Date:	2010-05-06
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-05-06
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171173
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	120.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	001055884GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2010-10-07
Trans1 Recv Date:	2010-10-07
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-10-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171173
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported

MTA NYCT - VENT PLANT 5103 (Continued) **S110306083**

Quantity:	217.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	006877405JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

G57 **MTA NYCT - VENT PLANT 5103** **RCRA-SQG** **1012211710**
North **HUNTER ST & 43RD AVE** **NYR000171173**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.107 mi.
563 ft. **Site 8 of 8 in cluster G**

Relative:
Lower

Actual:
12 ft.

RCRA-SQG:

Date form received by agency:	12/29/2009
Facility name:	MTA NYCT - VENT PLANT 5103
Facility address:	HUNTER ST & 43RD AVE LONG ISLAND CITY, NY 11101
EPA ID:	NYR000171173
Mailing address:	BROADWAY 5TH FLOOR 503 NEW YORK, NY 10004
Contact:	GERALD LEZEAU
Contact address:	BROADWAY 5TH FLOOR 503 NEW YORK, NY 10004
Contact country:	US
Contact telephone:	(646) 252-3535
Contact email:	GERALD.LEZEAU@NYCT.COM
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	MTA NYCT
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	03/01/1968

MTA NYCT - VENT PLANT 5103 (Continued) **1012211710**

Owner/Op end date: Not reported

Owner/operator name: MTA NYCT
Owner/operator address: BROADWAY 5TH FLOOR 503
NEW YORK, NY 10004
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: 03/01/1968
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:
Waste code: D008
Waste name: LEAD

Violation Status: No violations found

H58 **43-40 COURT SQUARE / QUEE** **NY Spills** **S104495129**
WSW **43-40 COURT SQUARE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.107 mi.
566 ft. **Site 2 of 8 in cluster H**

Relative:
Higher

Actual:
14 ft.

SPILLS:
Facility ID: 8702187
DER Facility ID: 112689
Facility Type: ER
Site ID: 130778
DEC Region: 2
Spill Date: 6/17/1987
Spill Number/Closed Date: 8702187 / 6/17/1987
Spill Cause: Human Error
Spill Class: Not reported
SWIS: 4101
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 6/17/1987
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial

43-40 COURT SQUARE / QUEE (Continued) **S104495129**

Spill Notifier:	Police Department
Cleanup Ceased:	6/17/1987
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	6/19/1987
Spill Record Last Update:	11/26/1996
Spiller Name:	Not reported
Spiller Company:	EAGLE ELECTRIC
Spiller Address:	43-40 COURT SQUARE
Spiller City,St,Zip:	QUEENS, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	FORK LIFT ACCIDENT RUPTURED CONTAINERS, MATERIALS MIXED AFTER ACCIDENT AND CAUSED A GAS TO FORM.

Material:

Tank Test:

---

59 **EDR US Hist Auto Stat** **1015355789**
WNW **2413 44TH DR** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.109 mi.
576 ft.

Relative:
Higher

Actual:
16 ft.

EDR Historical Auto Stations:

Name:	GREGS AUTO BODY SHOP
Year:	2003
Address:	2413 44TH DR
Name:	GREGS AUTO BODY SHOP
Year:	2004
Address:	2413 44TH DR

E60 **LOT 8,TAXBLOCK 432** **NY E DESIGNATION** **S108469581**
NE **27-35 JACKSON AVENUE** **N/A**
< 1/8 **QUEENS, NY 11101**
0.109 mi.
578 ft. **Site 3 of 6 in cluster E**

Relative:
Higher

Actual:
15 ft.

E DESIGNATION:

Tax Lot(s):	8
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code:	QN

LOT 8,TAXBLOCK 432 (Continued) **S108469581**

Community District:	402
Census Tract:	19
Census Block:	1004
School District:	30
City Council District:	26
Fire Company:	E258
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-5/R9
Zone District 2:	M1-5/R7-3
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-5/R9/LIC
All Components2:	M1-5/R7-3
Split Boundary Indicator:	Y
Building Class:	F2
Land Use Category:	06
Number of Easements:	1
Owner, Type of Code:	Not reported
Owner Name:	27-35 JACKSON AVENUE
Lot Area:	000022500
Total Building Floor Area:	00000078500
Commercial Floor Area:	00000078500
Office Floor Area:	00000016500
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000
Storage Floor Area:	00000016500
Factory Floor Area:	00000045500
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	004.00
Residential Units:	00000
Non and Residential Units:	00004
Lot Frontage:	0225.00
Lot Depth:	0099.75
Building Frontage:	0220.00
Building Depth:	0090.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000350100
Total Assessed Value:	00001291500
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1965
Year Built Code:	Not reported
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0003.49
Maximum Allowable Far:	07.52
Borough Code:	4

LOT 8,TAXBLOCK 432 (Continued) **S108469581**

Borough Tax Block And Lot:	4004320008
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000782
Y Coordinate:	0211864
Zoning Map:	09B
Sanborn Map:	401 024
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1
Tax Lot(s):	8
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Window Wall Attenuation & Alternate Ventilation
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	1004
School District:	30
City Council District:	26
Fire Company:	E258
Health Area:	41
Police Precinct:	108
Zone District 1:	M1-5/R9
Zone District 2:	M1-5/R7-3
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-5/R9/LIC
All Components2:	M1-5/R7-3
Split Boundary Indicator:	Y
Building Class:	F2
Land Use Category:	06
Number of Easements:	1
Owner, Type of Code:	Not reported
Owner Name:	27-35 JACKSON AVENUE
Lot Area:	000022500
Total Building Floor Area:	00000078500
Commercial Floor Area:	00000078500
Office Floor Area:	00000016500
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000
Storage Floor Area:	00000016500

LOT 8,TAXBLOCK 432 (Continued) **S108469581**

Factory Floor Area:	00000045500
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	004.00
Residential Units:	00000
Non and Residential Units:	00004
Lot Frontage:	0225.00
Lot Depth:	0099.75
Building Frontage:	0220.00
Building Depth:	0090.00
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	5
Land Assessed Value:	00000350100
Total Assessed Value:	00001291500
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1965
Year Built Code:	Not reported
Year Altered1:	0000
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0003.49
Maximum Allowable Far:	07.52
Borough Code:	4
Borough Tax Block And Lot:	4004320008
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000782
Y Coordinate:	0211864
Zoning Map:	09B
Sanborn Map:	401 024
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

E61 **MINI M,ICRO SUPPLI INC** **NY AST** **U003388903**
NE **27-35 JACKSON AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.109 mi.
578 ft. **Site 4 of 6 in cluster E**

Relative:
Higher

Actual:
15 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-283118

MINI M,ICRO SUPPLI INC (Continued) **U003388903**

Program Type:	PBS
UTM X:	589473.25162999996
UTM Y:	4511320.2492399998
Expiration Date:	2017/10/23
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	12486
Affiliation Type:	Facility Owner
Company Name:	27-35 JACKSON AVENUE PROPERTY LLC
Contact Type:	OWNER
Contact Name:	PHYLLIS SHIH
Address1:	27-35 JACKSON AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 482-8600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	11/13/2012

Site Id:	12486
Affiliation Type:	Mail Contact
Company Name:	MINI MICRO SUPPLY INC
Contact Type:	Not reported
Contact Name:	PHYLLIS SHIH
Address1:	27-35 JACKSON AVE
Address2:	Not reported
City:	L.I.C.
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 482-8600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	12486
Affiliation Type:	On-Site Operator
Company Name:	MINI M,ICRO SUPPLI INC
Contact Type:	Not reported
Contact Name:	RAY LIANG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 482-8600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	11/13/2012

MINI M,ICRO SUPPLI INC (Continued) **U003388903**

Site Id:	12486
Affiliation Type:	Emergency Contact
Company Name:	27-35 JACKSON AVENUE PROPERTY LLC
Contact Type:	Not reported
Contact Name:	RAY LIANG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 482-8600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	11/13/2012

Tank Info:

Tank Number:	005
Tank Id:	14851
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
H99 - Tank Leak Detection - Other
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other
L09 - Piping Leak Detection - Exempt Suction Piping
E02 - Piping Secondary Containment - Vault (with Access)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/1965
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	11/13/2012
Material Name:	#2 Fuel Oil (On-Site Consumption)

Tank Number:	008
Tank Id:	14852
Material Code:	0001

MINI M,ICRO SUPPLI INC (Continued) **U003388903**

Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

E02 - Piping Secondary Containment - Vault (with Access)
C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other
L09 - Piping Leak Detection - Exempt Suction Piping
H99 - Tank Leak Detection - Other
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/1965
Capacity Gallons:	8000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	11/13/2012
Material Name:	#2 Fuel Oil (On-Site Consumption)

E62 **CAB MANAGEMENT CORP** **NY UST** **1000551189**
NE **27-34 JACKSON AVENUE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.112 mi.
589 ft. **Site 5 of 6 in cluster E**

Relative: Higher

Actual: 15 ft.

UST:

Id/Status:	2-017647 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	2017/10/23
UTM X:	589472.16082999995
UTM Y:	4511319.68095
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	151
Affiliation Type:	On-Site Operator
Company Name:	CAB MANAGEMENT CORP
Contact Type:	Not reported
Contact Name:	CAB MANAGEMENT CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

CAB MANAGEMENT CORP (Continued) **1000551189**

Phone:	(718) 937-8668
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	9/30/2010

Site Id:	151
Affiliation Type:	Emergency Contact
Company Name:	CAB MANAGEMENT CORP
Contact Type:	Not reported
Contact Name:	JAMES VASEY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(914) 455-2380
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	9/30/2010

Site Id:	151
Affiliation Type:	Mail Contact
Company Name:	CAB MANAGEMENT CORP
Contact Type:	Not reported
Contact Name:	JAMES VASEY
Address1:	27-34 JACKSON AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 937-8668
EMail:	JVASEY@CMCNYC.BIZ
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	10/8/2013

Site Id:	151
Affiliation Type:	Facility Owner
Company Name:	CAB MANAGEMENT CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	27-34 JACKSON AVE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 937-8668
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	10/8/2013

CAB MANAGEMENT CORP (Continued) **1000551189**

Tank Info:

Tank Number:	001
Tank ID:	27075
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	08/01/1983
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	21
Date Test:	10/06/2011
Next Test Date:	10/06/2016
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	10/08/2013

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
D02 - Pipe Type - Galvanized Steel
F08 - Pipe External Protection - Retrofitted Impressed Current
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
B08 - Tank External Protection - Retrofitted Impressed Current
G05 - Tank Secondary Containment - Synthetic Liner
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None

E63 **CAB MANAGEMENT CORP** **NY AST** **A100352965**
NE **27-34 JACKSON AVENUE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.112 mi.
589 ft. **Site 6 of 6 in cluster E**

Relative:
Higher

Actual:
15 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-017647
Program Type:	PBS
UTM X:	589472.16082999995
UTM Y:	4511319.68095
Expiration Date:	2017/10/23
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	151
Affiliation Type:	On-Site Operator
Company Name:	CAB MANAGEMENT CORP
Contact Type:	Not reported

CAB MANAGEMENT CORP (Continued) **A100352965**

Contact Name:	CAB MANAGEMENT CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 937-8668
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	9/30/2010

Site Id:	151
Affiliation Type:	Emergency Contact
Company Name:	CAB MANAGEMENT CORP
Contact Type:	Not reported
Contact Name:	JAMES VASEY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(914) 455-2380
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	9/30/2010

Site Id:	151
Affiliation Type:	Mail Contact
Company Name:	CAB MANAGEMENT CORP
Contact Type:	Not reported
Contact Name:	JAMES VASEY
Address1:	27-34 JACKSON AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 937-8668
EMail:	JVASEY@CMCNYC.BIZ
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	10/8/2013

Site Id:	151
Affiliation Type:	Facility Owner
Company Name:	CAB MANAGEMENT CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	27-34 JACKSON AVE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101

CAB MANAGEMENT CORP (Continued) **A100352965**

Country Code:	001
Phone:	(718) 937-8668
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	10/8/2013

Tank Info:

Tank Number:	002
Tank Id:	236118
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
E00 - Piping Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/01/1998
Capacity Gallons:	300
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	10/08/2013
Material Name:	Waste Oil/Used Oil

---

64 **DUTCH KILL/SCRAP YARD** **NY Spills** **S102143117**
ESE **DUTCH KILL** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.113 mi.
595 ft.

Relative:
Higher

Actual:
18 ft.

SPILLS:

Facility ID:	9204680
DER Facility ID:	110138
Facility Type:	ER
Site ID:	127567
DEC Region:	2
Spill Date:	7/23/1992
Spill Number/Closed Date:	9204680 / 7/23/1992
Spill Cause:	Unknown

DUTCH KILL/SCRAP YARD (Continued) **S102143117**

Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	7/23/1992
CID:	Not reported
Water Affected:	NEWTOWN CREEK
Spill Source:	Unknown
Spill Notifier:	Federal Government
Cleanup Ceased:	7/23/1992
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	7/28/1992
Spill Record Last Update:	9/30/2004
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TANG"10/10/95: This is additional information about material spilled from the translation of the old spill file: SHEEN.
Remarks:	SHEEN CONFIRMED NON-RECOVERABLE BY USCG.

Material:

Site ID:	127567
Operable Unit ID:	972187
Operable Unit:	01
Material ID:	412378
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

I65 **EDR US Hist Auto Stat** **1015381090**
NE **2722 JACKSON AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.113 mi.
596 ft. **Site 1 of 3 in cluster I**

Relative:
Higher

Actual:
15 ft.

EDR Historical Auto Stations:
Name: BEARDSLEE TRANSMISSION EQUIPT COMPANY INCORPORATED
Year: 2000
Address: 2722 JACKSON AVE

J66 **EDR US Hist Cleaners** **1015027946**
West **2501 JACKSON AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.115 mi.
606 ft. **Site 1 of 6 in cluster J**

Relative:
Higher

Actual:
15 ft.

EDR Historical Cleaners:
Name: SUN CLEANERS
Year: 2005
Address: 2501 JACKSON AVE

Name: SUN CLEANERS
Year: 2006
Address: 2501 JACKSON AVE

Name: SUN CLEANERS
Year: 2007
Address: 2501 JACKSON AVE

Name: SUN CLEANERS
Year: 2008
Address: 2501 JACKSON AVE

Name: SUN CLEANERS
Year: 2010
Address: 2501 JACKSON AVE

Name: SUN CLEANERS
Year: 2011
Address: 2501 JACKSON AVE

Name: SUN CLEANERS
Year: 2012
Address: 2501 JACKSON AVE

I67 **MINI MICRO** **NY Spills** **S105235939**
NNE **27-35 JACKSON AVE** **N/A**
< 1/8 **JACKSON HEIGHTS, NY**
0.121 mi.
639 ft. **Site 2 of 3 in cluster I**

Relative:
Higher

Actual:
16 ft.

SPILLS:
Facility ID: 0108045
DER Facility ID: 108921
Facility Type: ER
Site ID: 125949
DEC Region: 2

MINI MICRO (Continued) **S105235939**

Spill Date:	11/7/2001
Spill Number/Closed Date:	0108045 / 11/14/2001
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	11/7/2001
CID:	282
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	11/8/2001
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	11/7/2001
Spill Record Last Update:	7/19/2004
Spiller Name:	SAME
Spiller Company:	NEWLITE FUEL OIL COMPANY
Spiller Address:	8725 MYRTLE AVE
Spiller City,St,Zip:	GLENDALE, NY 11385-
Spiller Company:	001
Contact Name:	JOSEPH VESSIO
Contact Phone:	(718) 459-1223
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO"11/08/01: MF S/I/LORI CHENG, MANAGER OF MINI MICRO. SHE TOD ME APPX 100 GALLONS OF #2FO SPILLED DUE TO GASKET PROBLEM ON THE BOILER. NEWLITE FUEL SENT A CREW LAST NITE TO CLEAN. THE CLEAN UP DEBRIS IS ON SITE, ON PLACTIC & COVERED/PLASTIC. SOME LEAKAGE NOTICED. SPEEDY DRY & PADS WERE APPLIED TO THE SPILLAGE & SWEEP UP. SOME SPEEDY DRY STILL ON THE FLOOR. STAINING ALSO ON THE FLOOR, THE CONCRETE FLOOR HAS SMALL CRACKES IN IT. THERE IS A FLOOR DRAIN WHICH AN UNKNOWN AMOUNT OF PRODUCT ENTERED. A LITTLE MORE CLEAN UP STILL HAS TO BE DONE & THE DEBRIS DISPOSED OF. CALLED LISA HOUER, TRISTATE 718-861-3159. A CREW IS ON THE WAY THERE NOW, THEY WILL SWEEP UP THE SPEEDY DRY & CLEAN A LITTLE BETTER UNDER THE BOILER. THE DEBRIS WILL BE REMOVED TODAY & DISPOSED OF TOMORROW. SHE WILL SENT THE RECEIPT TO TIM.
Remarks:	gasket on the manhole failed gauge was not giving reading properly.

Material:

Site ID:	125949
Operable Unit ID:	846082
Operable Unit:	01
Material ID:	552697
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

MINI MICRO (Continued) **S105235939**

Tank Test:

H68 **CITICORP AT COURT SQUARE** **NY AST** **A100293558**
WSW **25-01 JACKSON AVENUE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.123 mi.
648 ft. **Site 3 of 8 in cluster H**

Relative:
Higher

Actual:
15 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-455040
Program Type:	PBS
UTM X:	589180.09545999998
UTM Y:	4511172.6065400001
Expiration Date:	2014/02/15
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	19999
Affiliation Type:	Mail Contact
Company Name:	CUSHMAN & WAKEFIELD
Contact Type:	Not reported
Contact Name:	FRED VARONE
Address1:	25-01 JACKSON AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 248-0715
EMail:	Not reported
Fax Number:	Not reported
Modified By:	cgfreedm
Date Last Modified:	4/13/2004

Site Id:	19999
Affiliation Type:	Emergency Contact
Company Name:	CITIBANK, N.A.
Contact Type:	Not reported
Contact Name:	KEITH OWEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 785-5955
EMail:	Not reported
Fax Number:	Not reported
Modified By:	exrossan
Date Last Modified:	3/17/2004

Site Id:	19999
Affiliation Type:	On-Site Operator
Company Name:	CITICORP AT COURT SQUARE

CITICORP AT COURT SQUARE (Continued) **A100293558**

Contact Type:	Not reported
Contact Name:	CUSHMAN AND WAKEFIELD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 248-1937
EMail:	Not reported
Fax Number:	Not reported
Modified By:	cgfreedm
Date Last Modified:	4/13/2004

Site Id:	19999
Affiliation Type:	Facility Owner
Company Name:	CITIBANK, N.A.
Contact Type:	CHIEF ENGINEER
Contact Name:	FRED VARONE
Address1:	25-01 JACKSON AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 248-1937
EMail:	Not reported
Fax Number:	Not reported
Modified By:	cgfreedm
Date Last Modified:	4/13/2004

Tank Info:

Tank Number:	04
Tank Id:	178526
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

F02 - Pipe External Protection - Original Sacrificial Anode
I02 - Overfill - High Level Alarm
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
A01 - Tank Internal Protection - Epoxy Liner
F06 - Pipe External Protection - Wrapped
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported

CITICORP AT COURT SQUARE (Continued) **A100293558**

Install Date:	06/01/1988
Capacity Gallons:	275
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	cgfreedm
Last Modified:	04/13/2004
Material Name:	Diesel

H69 **1 COURT SQUARE** **NY Spills** **S102142523**
WSW **1 COURT SQUARE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.123 mi.
648 ft. **Site 4 of 8 in cluster H**

Relative:
Higher

Actual:
15 ft.

SPILLS:

Facility ID:	9110791
DER Facility ID:	194524
Facility Type:	ER
Site ID:	236132
DEC Region:	2
Spill Date:	1/16/1992
Spill Number/Closed Date:	9110791 / 1/17/1992
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	4101
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1/16/1992
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1/17/1992
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2/3/1992
Spill Record Last Update:	9/30/2004
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TANG"
Remarks:	SPEEDI DRI APPLIED, PICKED UP & DISPOSED.

Material:

Site ID:	236132
Operable Unit ID:	960930
Operable Unit:	01

1 COURT SQUARE (Continued) **S102142523**

Material ID:	415868
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

H70 **CITICORP AT COURT SQUARE** **NY UST** **U004062303**
WSW **25-01 JACKSON AVENUE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.123 mi.
648 ft. **Site 5 of 8 in cluster H**

Relative:
Higher

Actual:
15 ft.

UST:

Id/Status:	2-455040 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	2014/02/15
UTM X:	589180.09545999998
UTM Y:	4511172.6065400001
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	19999
Affiliation Type:	Mail Contact
Company Name:	CUSHMAN & WAKEFIELD
Contact Type:	Not reported
Contact Name:	FRED VARONE
Address1:	25-01 JACKSON AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 248-0715
EMail:	Not reported
Fax Number:	Not reported
Modified By:	cgfreedm
Date Last Modified:	4/13/2004

Site Id:	19999
Affiliation Type:	Emergency Contact
Company Name:	CITIBANK, N.A.
Contact Type:	Not reported
Contact Name:	KEITH OWEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported

CITICORP AT COURT SQUARE (Continued) **U004062303**

Country Code:	999
Phone:	(516) 785-5955
EMail:	Not reported
Fax Number:	Not reported
Modified By:	exrossan
Date Last Modified:	3/17/2004

Site Id:	19999
Affiliation Type:	On-Site Operator
Company Name:	CITICORP AT COURT SQUARE
Contact Type:	Not reported
Contact Name:	CUSHMAN AND WAKEFIELD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 248-1937
EMail:	Not reported
Fax Number:	Not reported
Modified By:	cgfreedm
Date Last Modified:	4/13/2004

Site Id:	19999
Affiliation Type:	Facility Owner
Company Name:	CITIBANK, N.A.
Contact Type:	CHIEF ENGINEER
Contact Name:	FRED VARONE
Address1:	25-01 JACKSON AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 248-1937
EMail:	Not reported
Fax Number:	Not reported
Modified By:	cgfreedm
Date Last Modified:	4/13/2004

Tank Info:

Tank Number:	01
Tank ID:	36937
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	6000
Install Date:	06/01/1988
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel

Tightness Test Method:	NN

CITICORP AT COURT SQUARE (Continued) **U004062303**

Date Test: 04/19/2003
Next Test Date: Not reported
Pipe Model: C
Modified By: cgfreedm
Last Modified: 04/13/2004

Equipment Records:

E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F04 - Pipe External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass

Tank Number: 02
Tank ID: 178524
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 6000
Install Date: 06/01/1988
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 00
Date Test: 04/19/2003
Next Test Date: Not reported
Pipe Model: C
Modified By: cgfreedm
Last Modified: 04/13/2004

Equipment Records:

J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
B04 - Tank External Protection - Fiberglass

Tank Number: 03
Tank ID: 178525
Tank Status: In Service
Material Name: In Service

CITICORP AT COURT SQUARE (Continued) **U004062303**

Capacity Gallons:	6000
Install Date:	06/01/1988
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	00
Date Test:	04/19/2003
Next Test Date:	Not reported
Pipe Model:	C
Modified By:	cgfreedm
Last Modified:	04/13/2004

Equipment Records:

J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F04 - Pipe External Protection - Fiberglass
E00 - Piping Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass

K71 **MANHOLE 4440** **NY Spills** **S103936850**
ENE **4327 QUEENS ST** **N/A**
< 1/8 **QUEENS, NY**
0.124 mi.
654 ft. **Site 1 of 2 in cluster K**

Relative:
Higher

Actual:
15 ft.

SPILLS:

Facility ID:	9901252
DER Facility ID:	243541
Facility Type:	ER
Site ID:	301394
DEC Region:	2
Spill Date:	5/3/1999
Spill Number/Closed Date:	9901252 / 1/7/2000
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	5/3/1999
CID:	382
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

MANHOLE 4440 (Continued) **S103936850**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	5/3/1999
Spill Record Last Update:	6/14/2000
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	BILL MURPHY
Contact Phone:	(212) 580-6763
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"Con ed e2mis notes:Found undiaperable sheen on approx 800 gallons of water. <1.00ppmhow performed? Structure was double washed using bio gen 760. cleaned 100%Reports found undiaperable sheen on approx 800 gallons of water in mh.Double washed structure with biogen 760 - 100% cleaned. Also inspected structrue and found no damage. Tag removed. Flush reports he put 10 gallons of cement in sump.
Remarks:	SHEEN FOUND ON 800 GAL OF WATER CONTAINED IN MANHOLE. CLEAN UP PENDING LAB RESULTS. CON ED 124-599.

Material:

Site ID:	301394
Operable Unit ID:	1079956
Operable Unit:	01
Material ID:	304798
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

H72 **5 COURT SQUARE** **NY AST U003397123**
WSW **5 COURT SQUARE** **NY HIST AST N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.124 mi.
654 ft. **Site 6 of 8 in cluster H**

Relative:
Higher

Actual:
14 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-603367
Program Type:	PBS
UTM X:	589183.38974999997
UTM Y:	4511109.3627899997
Expiration Date:	2018/03/09
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	25285

5 COURT SQUARE (Continued) **U003397123**

Affiliation Type:	Facility Owner
Company Name:	COURT SQUARE LLC
Contact Type:	MANAGER
Contact Name:	BENNY SOKOL
Address1:	152 W 57 ST 12TH FL.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10019
Country Code:	001
Phone:	(212) 315-3390
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	3/18/2013

Site Id:	25285
Affiliation Type:	Mail Contact
Company Name:	FISHER ASSOCIATES
Contact Type:	Not reported
Contact Name:	BENNY SOKOL
Address1:	152 WEST 57TH STREET
Address2:	12TH FL
City:	NEW YORK
State:	NY
Zip Code:	10019
Country Code:	001
Phone:	(212) 315-3390
EMail:	BSOKOL@FISHERASSOC.NET
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	3/18/2013

Site Id:	25285
Affiliation Type:	Emergency Contact
Company Name:	COURT SQUARE LLC
Contact Type:	Not reported
Contact Name:	VASILE DUMNICI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(347) 273-4382
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	1/29/2008

Site Id:	25285
Affiliation Type:	On-Site Operator
Company Name:	COURT SQUARE LLC
Contact Type:	Not reported
Contact Name:	VASILE DUMNICI
Address1:	Not reported
Address2:	Not reported

5 COURT SQUARE (Continued) **U003397123**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 257-0944
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	3/18/2013

Tank Info:

Tank Number:	001
Tank Id:	54019
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None
K00 - Spill Prevention - None
A01 - Tank Internal Protection - Epoxy Liner
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
J05 - Dispenser - On Site Heating System (Supply/Return)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/24/1954
Capacity Gallons:	2020
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	KAKYER
Last Modified:	03/18/2013
Material Name:	#2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number:	2-603367
SWIS Code:	6301
Operator:	LARRY GANGAWAY
Facility Phone:	(718) 784-9303
Facility Addr2:	Not reported
Facility Type:	Not reported
Emergency:	LARRY GANGAWAY
Emergency Tel:	(718) 781-9303
Old PBSNO:	Not reported
Date Inspected:	Not reported

5 COURT SQUARE (Continued) **U003397123**

Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	COURT SQUARE ASSOCIATES
Owner Address:	1775 BROADWAY
Owner City,St,Zip:	NEW YORK, NY 10019
Federal ID:	Not reported
Owner Tel:	(212) 315-3390
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	JACK BERKOVICH
Mailing Name:	FISHER ASSOCIATES
Mailing Address:	1775 BROADWAY, SUITE 515
Mailing Address 2:	Not reported
Mailing City,St,Zip:	NEW YORK, NY 10019
Mailing Telephone:	(212) 315-3390
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	03/11/1998
Expiration:	03/09/2003
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	2000
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	2000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	1
Tank External:	1
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	1
Tank Containment:	None
Leak Detection:	00
Overfill Protection:	00
Dispenser Method:	Gravity
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported

5 COURT SQUARE (Continued) **U003397123**

Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

H73 **COURT PLAZA** **NY LTANKS** **S110309405**
WSW **5 COURT SQUARE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.124 mi.
654 ft. **Site 7 of 8 in cluster H**

Relative:
Higher

Actual:
14 ft.

LTANKS:

Site ID:	431696
Spill Number/Closed Date:	1000528 / Not Reported
Spill Date:	4/13/2010
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	RVKETANI
Referred To:	082413 TETRA TECH RECVD DRAWINGS COMMENTS FROM MTA
Reported to Dept:	4/13/2010
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	1
Date Entered In Computer:	4/13/2010
Spill Record Last Update:	8/26/2013
Spiller Name:	Not reported
Spiller Company:	FISHER
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	RENE LEWIS
Spiller Phone:	(917) 299-9302
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	25193
DEC Memo:	04/13/10-Hiralkumar Patel. as oil was found on water in subway tunnel underneath the subject building, asked building manager to do tank test on a 2,000 gal #2 oil tank.2:00 PM:- visited site. met Mr. Sokol, property manager. Eastmond did fill line test and it failed. asked Mr. Sokol, to seal fill port to prevent further release. fill port at the site is about 15 ft away from the area where oil found seeping into subway tunnel. asked Mr. Sokol to do tank only test also to confirm no leak from tank.Court Square LLC. **property owner**c/o Fisher Associates **management office**Carnegie Hall Tower 152 West 57th Street, 12th FloorNew York, NY 10019Attn.: Benny Sokol **property manager**Ph. (212) 315-3390 Ext. 214 (O) (347) 273-0998 (C)Fax (212) 937-8814email: bsokol@fisherassoc.net04/15/10-Hiralkumar Patel. received email from Mr. Sokol (at 6:53 PM on 04/13/10) with

COURT PLAZA (Continued) **S110309405**

their insurance company info.Hub International **insurance broker**contact: Cynthia ChinPH. (212) 338-285810:09 AM:- spoke with Mr. Sokol. Eastmond is at the site to do tank only test and then will expose the fill line. asked Mr. Sokol to wait for excavation along fill line as may need approval from MTA.10:14 AM:- spoke with Haroon in System Safety at MTA. Haroon mentioned that contractor doesn't need any approval from MTA for sidewalk breaking or fill line repair. asked Haroon to send someone to the site to guide contractor if deeper excavation is required (due to proximity to the subway structure).Haroon Aslam **spill case manager in MTA**PH. (646) 252-3607 (646) 252-5777email: haroon.aslam@nyct.com10:18 AM:- spoke with Mr. Sokol. asked him to finish tank only test first and expose fill line. informed Mr. Sokol that no deeper excavation should be performed until MTA approves the work.11:45 AM:- visited site. met Mr. Sokol and Haroon. eastmond crew was working to test tank. spoke with Rene at Eastmond. they have applied for DOT permit and expect to start work on 04/19/10. inspected track area with Mr. Sokol and Haroon. area was in same condition with little more oil than previous site visit. some odors at the end of platform in leak area. Haroon asked to contact Rajen Udeshi at MTA about approval for excavation near subway structure.04/16/10-Hiralkumar Patel.9:38 AM:- sent email to Mr. Sokol with Mr. Udeshi's contact info.Rajen UdeshiCapital Program Management2 Broadway, 7th FloorNew York, NY 10004Ph. (646) 252-3673email: rajen.udeshi@nyct.com04/16/10-Hiralkumar Patel.11:01 AM:- received email from Mr. Sokol. after installing new fill and vent line and repairing manhole on tank, Eastmond tested tank system and it passed the test. Mr. Sokol will submit test result, once available.04/19/10-Hiralkumar Patel.11:55 AM:- spoke with Jen at MTA. they haven't got fingerprint sample results back yet.12:47 PM:- received email from Mr. Sokol. they spoke with MTA who approved to excavated up to four feet without any engineer report. so Eastmond will expose old fill line tomorrow. Mr. Sokol also mentioned that their insurance company has hired Tetra Tech.2:51 PM:- received message from Sandra from Tetra Tech.Sandra GaurinTetra Tech EM Inc.Ph. (973) 384-9799 (O) (973) 659-9996 Ext. 245 (201) 572-0835 (C)Fax (973) 659-1287email: sandra.gaurin@tetratech.com3:20 PM:- left message for Ms. Gaurin.04/20/10-Hiralkumar Patel.2:15 PM:- visited site. met Ms. Gaurin, Mr. Sokol and Rene. Eastmond crew exposed old fill line. when contractor tried to pull out fill line from ground, fill line separated in two pieces from coupling. no broken threads observed on pipe and looks like fill line was not properly installed. found that piece of fill line towards building was anchored in ground at coupling joint. piece of fill line towards building was corroded but no holes found. corrosion holes found in piece of fill line towards sidewalk. fresh oil found under fill line. asked Ms. Gaurin to get DOT and MTA permits before further work. Eastmond will cover excavation with plastic and then backfill with clean sand as need permit for further work. Eastmond collected two soil samples (from same area) for fingerprint and age analysis.inspected subwary track area with Ms. Gaurin. found oil on tracks. asked Ms. Gaurin to submit claim number and insurance claim handler's information.asked Mr. Sokol to submit tank test result.04/23/10-Hiralkumar Patel. received email from Ms. Gaurin (at 5:24 PM on 04/21/10) with contact info for project manager at insurance company. Ms. Gaurin is preparing work plan for further work and asked whether groundwater sample from temporary geoprobe is sufficient for initial groundwater quality check or permanent well is required.Dawn KrigstinIronshore

COURT PLAZA (Continued) **S110309405**

Environmental **insurance carrier**Ph. (646) 826-6785email: Dawn.Krigstin@Ironshore.comspoke with Ms. Gaurin and informed her that permanent well is not required right now, but will be required if finds groundwater contamination in groundwater sample via temporary geoprobe.04/23/10-Hiralkumar Patel. received email from Mr. Sokol (at 7:51 PM on 04/22/10) with tank test result.12:34 PM:- received email from Jen from MTA including result of fingerpint analysis. sample collected from subway track area was found #2 oil.04/26/10-Hiralkumar Patel.10:18 AM:- received call from Mr. Daniels, environmental person at Chartis insurance which is second insurance company for the site. Mr. Daniels mentioned that both insurance companies are involved in project. asked Mr. Daniels to submit insurance claim project manager's info and clear information about who is going to handle entire cleanup project.Larry DanielsChartis InsuranceAIGPh. (201) 631-7233 (O) (917) 783-6035 (C) Fax (201) 631-5053email: larry.daniels@chartisinsurance.com11:03 AM:- received email from Tanya Crawford, analyst working on insurance claim at Chartis.Tanya Crawford **analyst**Chartis101 Hudson Street - 29th FloorJersey City, NJ 07302Ph. (201) 631-7158Fax (866) 467-3498email: tanya.crawford@chartisinsurance.comChartis Claim Number: 182-1115351:11 PM:- received email from Mr. Sokol with copy of delivery record from 01/07/08 to 04/01/10.3:43 PM:- received email from Mr. Sokol with sample results. fingerprint analysis indicates #2 oil and found heavy VOC contamination in soil sample.04/27/10-Hiralkumar Patel.4:01 PM:- after discussion with DEC Austin, as fingerprint analysis results match (#2 oil) and proximity of the subject site to the impacted subway area, spill #: 1000435 will be closed and investigated under spill #: 1000528.3:03 PM:- received email from Mr. Daniels and Ms. Gaurin requesting copy of MTA's fingerprint analysis result.04/28/10-Hiralkumar Patel.11:05 AM:- sent email to Mr. Daniels and Ms. Gaurin with copy of MTA's fingerprint analysis result.11:08 AM:- sent letter to Mr. Sokol requiring soil delineation along remote fill line, endpoint samples and at least one groundwater sample near source area. letter emailed to Mr. Sokol, Ms. Aslam, Mr. Udeshi, Ms. Gaurin, Mr. Krigstin, Mr. Daniels and Ms. Crawford.05/21/10-Hiralkumar Patel.1:29 PM:- left message for Ms. Gaurin inquiring updates.3:59 PM:- received email from Ms. Gaurin. she got drawings from MTA and now will prepare work plan for soil investigation. will submit work plan to DEC and MTA for approval next week. will apply for NYC DOT permit on 05/24/10.06/01/10-Hiralkumar Patel. received email from Ms. Gaurin (at 9:13 AM on 05/28/10) requesting deadline extension.11:00 AM:- received call from Ms. Gaurin. she mentioned that currently they are preparing work plan and will submit by end of 06/04/10. she requested 45 days extension as work plan needs to be reviewed/approved by DEC and MTA and also they need permit from DOT. based on available information, approved her request.06/08/10-Hiralkumar Patel.10:31 AM:- received work plan from Ms. Gaurin. proposes to install 12 soil borings to a depth of 10-15 ft bg. will collect two soil samples (highest PID and deepest dry) from each boring. will install one temporary well point to collect groundwater water in area where old fill line was located. will collect one more soil sample from the deepest visually impacted material for a forensic fingerprint analysis to find date of the release.work plan is not acceptable as doesn't include work schedule and also site map included in work plan doesn't include the site address and location of old fill line.06/10/10-Hiralkumar Patel.1:03 PM:- received email from Jen from

COURT PLAZA (Continued) **S110309405**

MTA. she confirmed that no more oil leak found on tracks. she asked for updates.1:32 PM:- sent email to Jen informing that the department is currently reviewing the work plan for subsurface investigation.1:36 PM:- spoke with Ms. Gaurin. asked her to submit revised work plan including timeline for report submission and general site map showing the subject site, old fill line and proposed boring locations.06/16/10-Hiralkumar Patel.4:34 PM:- received email from Ms. Gaurin with revised work plan. she proposes to submit report by end of 08/16/10.06/17/10-Hiralkumar Patel.2:21 PM:- sent work plan approval letter to Mr. Sokol requiring to submit report by end of 08/16/10. letter emailed to Mr. Udeshi, Mr. Aslam, Ms. Gaurin, Mr. Krigstin and Ms. Crawford.07/27/10-Hiralkumar Patel.11:38 AM:- received email from Ms. Gaurin. she mentioned that they have got required NYCDOT permits, but still waiting for approval from MTA. they are revising engineered drawings for MTA this week and hopefully will be in the field on August 9th. due to delay in getting approval from MTA, Ms. Gaurin requested deadline extension, for report submission, till 09/16/10.07/28/10-Hiralkumar Patel.11:25 AM:- sent email to Ms. Gaurin approving her request to submit report by 09/16/10. email copied to Mr. Sokol.08/04/10-Hiralkumar Patel.11:18 AM:- received email from Ms. Gaurin. she confirmed that work will start on 08/09/10. Francis Ronquillo (cell # 619-602-1745) from tetratech will supervise the field activities.09/07/10-Hiralkumar Patel.2:20 PM:- left message for Ms. Gaurin.4:16 PM:- received message from Ms. Gaurin. she is preparing report and will submit by 09/16/10. she mentioned that contamination found in soil samples and free product found on water.09/16/10-Hiralkumar Patel.4:24 PM:- received investigation report from Ms. Gaurin. abstract:- GPR survey indicated another line along the previously excavated remote fill line, which was later found as cable line- installed 12 soil borings to depth of 10-15 ft bg- soil under the sidewalk was poorly graded sandy soil with very little gravel- soil samples were collected either at highest PID reading or deepest dry- one temporary well installed in proximity of the source area- found free product on water sample from temporary well- groundwater was encountered at approx. 15 ft bg- one soil sample was collected at 11 ft depth from boring TTB-1 (closer to source area) forensic fingerprint analysis (results will be submitted once available)- no contamination found in borings installed near the building foundation wall (south side), but contamination found towards the street curb (towards subway) (north side)- recommends further delineation in east and west directionsoil analyticals:
----------TTB-1-------TTB-2-------TTB-5-------TTB-6---
----TTB-7 3-5 ft 3-5 ft 5-6 ft 6-7 ft 4-6
ftToluene----------4,990------16,600-------2,
130Ethylbenzene----------3,000------12,500-------2,
160Xylene----------20,400------85,600------13,300------17,
200-------6,560Naphthalene----------14,200------13,700-------2,
330------20,900------10,
800----------TTB-8-------TTB-9-------TTB-10 4-6 ft
6-8 ft 5-6.5
ftToluene----------5,490----------13,
500Ethylbenzene----------3,420----------11,
300Xylene----------32,100-------7,580-------66,
700Naphthalene----------16,300----------5,79009/20/
10-Hiralkumar Patel. after discussing with DEC Austin, case transferred to DEC Vadim due to groundwater contamination and impact

COURT PLAZA (Continued) **S110309405**

to the MTA tunnel.**refer to spill # 1000435 also.**11/8/10 - reassigned from Tibbe to JMOCONNE - sent email to TetraTech (Gaurin) asking for reports/work plans submitted but not reviewed (JOC)01/14/11 - spoke with Sandra Gaurin, Tetratech. She will prepare and provide two separate documents: work plan for installing permanent well at location of former temp to allow removal of free product in the short term; separate work plan for delineation of contam soil and gw - to be written as dynamic work plan - will include some means to evaluate whether oil migrated down along outside front (north side) of building where fill line enters building; same along inside of wall (basement has soil floor); will include sensitive receptor survey; recognized that MTA approval is needed for all work due to proximity of subway (JOC)11/28/11 - Raphael Ketani. I reviewed the Tetra Tech Inc. 11/23/11 response letter to the DEC 10/11/11 letter commenting on the additional Site Investigation Work Plan and the Interim Remedial Measure Work Plan dated April 2010. The letter described the tentative work schedule. During this week, the NYCDOT permit applications are supposed to be processed. I spoke to Sandra Gaurin (gor-in) of Tetra Tech (973) 630-8040 about this. She said that some changes were required. So the applications were resubmitted. She is hopeful that the applications will finally be accepted so that December 12 field activities can commence. I also asked her why Tetra Tech was going to use the Membrane Inter Phase screening. She said that this was Mr. O'Connell's suggestion so that Tetra Tech doesn't have to go back and forth with doing many rounds of soil sampling and taking many soil samples that need to be sent off for analysis. She said that the vapor analysis from the penetration points will tell them where the worst contamination is. I told her that the DEC will still require that soil end points be taken after all of the soil that can be excavated has been removed. She said that she expected to do in-situ treatment due to the close location to the subway. I asked her what type of building was being serviced by the fuel system. She said that it's a residential/commercial building near the court house.The letter also dealt with vertical delineation of the contamination and soil and groundwater sampling. I approved the 11/23/11 Tetra Tech letter in an e-mail to Ms. Gaurin.12/5/11 - Raphael Ketani. Ms. Gaurin (973) 630-8040 sent me an e-mail. The MIP investigation will take place between 12/19 and 12/22, and the recovery well installation will take place on 1/3/12.3/7/12 - Raphael Ketani. Today I received the TetraTech March 2012 Remedial Investigation Report. The soil and groundwater were sampled on 12/21/11. Four MIPS and two soil borings (SB-1 and SB-2) were installed. MIP-1 was installed next to the old fuel line. MIP-2 was 15 feet southwest of MIP-1 and MIP-4 was 6 feet to the northeast. The soil results for MIP-2 did not have any VOC exceedences and no BNA (bases-neutral-acid) hits. The soil results for MIP-4 at 9 feet bgs were: 3360 ppb ethylbenzene, 5310 ppb toulene, and 59,300 ppb total xylenes. The deeper soil results for MIP-4 had only one exceedence, 945 ppb of total xylenes. The great majority of the soil contamination at MIP-1 was in the 10.5 foot to 12 foot interval. These results were up to: 10,800 ppb ethylbenzene, 6240 ppb toluene, 67,100 ppb total xylenes, 23,700 ppb naphthalene, and 284 ppb benzene. There were no significant detections for the BNA analytes. The other MIP results and the results from the regular soil borings were either without exceedences or non-detect. A groundwater sample was taken at MIP-3, which is about 35 away from the old fuel line. The results were entirely non-detect.The RIR also included the

COURT PLAZA (Continued) **S110309405**

figures from the 2010 soil testing and sampling. The testing and sampling locations defined the limits of the investigation area. The results indicated that there were significant exceedences at TTB-1, 2, 5, 6, 8 and 10. I spoke to Ms. Gaurin (973) 630-8040 about the RIR. I told her that soil removal or remediation should take place at the locations of MIP-1, MIP-4, and TTB-1, 2, 5, 6, 8 and 10. I also told her that the groundwater sample which was taken at MIP-3 didn't reflect the groundwater conditions near the spill site as it was too far away (about 35 feet distance). Ms. Gaurin said that there had been a few inches of product on the water table, but it had disappeared. I asked her why the MIP-3 sampling didn't find the product. She responded that the MTA had been collecting the product that had seeped into the subway. So she assumed it had all gone there. I told her that the DEC didn't believe that this was true and that there should be some product near the old fuel pipe. I asked Ms. Gaurin to submit a work plan for excavating the contaminated soil in the affected areas. She said that excavation couldn't be done as there were too many utilities. I then told her to try treatment solutions. She said that she wasn't sure they would work. Lastly, I told Ms. Gaurin to submit a site plan showing where the utilities are in relationship to the MIP locations and the TTB locations. She said that she will.In the end, I determined that soil treatment and the installation of a well right next to MIP-1 would be necessary. I sent an e-mail to Ms. Gaurin (973) 630-8040 stating that the second investigation had been inadequate regarding the delineation of the soil contamination. I mentioned in the e-mail that high soil contamination was found at TTB-1, 2, 5, 6, 8 and 10, and at MIP-1 and MIP-4. I also stated that borings should have been performed extending away from these locations until the limit of the soil contamination had been found. Lastly, I asked for a scaled drawing showing where all of the utilities were.Ms. Gaurin responded by e-mail that the TTB series of borings were meant for only internal TetraTech use in order to evaluate the MIP responses. That is why they were in the appendices. She also stated that they were performed in 2010 and don't reflect current conditions.12/11/12 - Raphael Ketani. Ms. Gaurin (973) 630-8040 called to say that she just recently realized that the DEC hadn't been sent the information that was requested some time ago. She said that the project manager had left and so things came to a standstill regarding the project. She will send the DEC the information very soon. 12/24/12 - Raphael Ketani. I reviewed the Addendum to the Remedial Investigation Report dated April 2012 and revised December 2012. The information in the revised Addendum confirmed the results of the earlier March 2012 Remedial Investigation Report and contained additional data.The additional information and data consisted of the fact that only 4 Membrane Interface Probe MIP locations could be installed due to the presence and density of the utilities. In the Addendum, it is stated that there is universal refusal at 20 feet bgs. However, it is not mentioned whether this is due to the presence of the subway tunnel. Also, the silt content of the soil markedly increased from about 14 to 15 feet bgs. Again, this may be due to the method of subway tunnel construction - the silt acting as a protective layer from ground vibration from the street above. Groundwater recovery was limited to 11 to 14 feet bgs.MIP-1 had a strong Flame Ionization Detection (FID) response at 12 feet, but less below 12.5 feet. MIP-2 near the former TTB-5 location had an FID response starting at 5 feet with the strongest response at 10 to 12 feet bgs. The response declined below

COURT PLAZA (Continued) **S110309405**

this horizon. MIP-3, which is 35 feet to the west of the former fill pipe location, had lower FID responses than MIP-2 at 12 and 16 feet below grade. MIP-4 near the former location of TTB-10 had FID responses starting at 6.5 feet bgs. There was no FID response at 12 feet bgs. Soil impacts appear to diminish to the west. A soil sample taken where the fill line had entered the building did not indicate contamination. There were no reports of product in the subway since the line was replaced during April 2010. There were significant VOC exceedences at TTB-1, 2 and 5 to 10 (but not at TTB-4 and 11 to 13). There were also significant VOC exceedences at the locations of MIP-1, MIP-4. This implies that there is still high soil contamination along the west and north sides of the 15 foot by 15 foot main impact area. The highest soil contamination was found between 3 feet and 8 feet bgs. VOC groundwater results were high at TTGW-1 (15 feet bgs). The groundwater sample which was taken at MIP-3 didn't reflect the groundwater conditions near the spill site as it was too far away (about 35 feet distance). TetraTech recommended allowing Monitored Natural Attenuation to remediate the remaining contamination. They would also conduct groundwater monitoring.12/26/12 - Raphael Ketani. A letter was drafted and submitted to Hassan Hussein, EE III and supervisor of Unit C in Region 2, for his review. In the letter, the DEC requested that a method be determined for remediating the soil contamination at TTB-1, 2 and 5 to 10, and at MIP-1 and MIP-4. It was also requested that they find a way to reduce the VOC contamination in the groundwater. Court Square LLC was given until January 18, 2013 to submit a remedial action work plan.The latest ownership information for 5 Court Square (block and lot 81 and 9) is: Court Square LLC, c/o Fisher Associates Real Estate, 152 West 57th Street, 12th Floor, NY, 10019.12/27/12 - Raphael Ketani. Mr. Hussein approved the letter and it was sent out. 1/18/2013 - Raphael Ketani. I received the January 2013 Remedial Action Work Plan and began my review.1/23/13 - Raphael Ketani. I finished my review of the RAWP. TetraTech will use RegenoOx to reduce or remove the soil contamination at TTB-1, 2, 5 and 10 and MIP-1 and MIP-4. Seven temporary injection points will be installed 10 feet apart. About 1440 lbs. of solution will be injected between 3 to 8 feet below grade. ORC Advanced will be used to remediate the groundwater at TT-GW1. They will inject 120 lbs. of solution at 4 temporary points. The solution will be injected between 15 and 20 feet below grade. Two sampling events will be performed on a quarterly basis after the injections are completed. Soil and groundwater samples will be taken from 4 temporary points within the injection area. The soil and groundwater samples will be tested for VOCs and SVOCs. The work schedule will be submitted after they get approvals from the NYC DOT and the MTA. The Remedial Action Report will be submitted after the treatments and sampling are completed. CP-51 standards will be used to compare the soil results. TOGS 1.1.1 standards will be used to compare the groundwater results.I found the RAWP to be deficient for the following reasons:(1) they intend to address the soil contamination at TTB-1, 2, 5 and 10. However, the DEC's letter approving the revised April 2012 Remedial Investigation Report Addendum (Revised December 2012) dated 12/27/12 instructed Court Square LLC to remediate the soil contamination at TTB-1, 2 and 5 TO 10, not 5 and 10.(2) there is no discussion regarding the siltyness of the soil and its impact on the movement of the solution(3) the site is near the subway tunnel, will the MTA only give approval to the injections if the solution is in a weak form? if

COURT PLAZA (Continued) **S110309405**

so, then the solution may not be effective(4) Figure 2 - Treatment Area Map = the actual solution injection locations are not shownAdditionally, Court Square LLC must consider the following before the injections take place:(1) they need to comply with the Federal underground injection control (UIC) regulations. Also, they should review the DEC guidance (IGP-22);(2) information is needed regarding the dosing of the solutions (i.e. mass of chemical per mass of VOCs and SVOCs);(3) how will the conditions in the subsurface be kept oxic?(4) it is recommended that groundwater be extracted from the proposed injecton area to minimize displacement of the dissolved plume. The pre-extracted water could be used to prepare the treatment solutions;(5) how will the treatment solutions be prevented from migrating off site? are there downgradient control wells? A response letter was drafted for the review of Mr. Hussein. The letter stated the above deficiencies and listed the 5 above pre-injection items. The submission of a revised Remedial Action Work Plan was requested with a due date for the work plan of March 1, 2013. Mr. Hussein approved the letter and it was sent out. 3/1/13 - Raphael Ketani. Ms. Gaurin (973) 630-8040 sent an e-mail requesting an extension of the submission deadline for the work plan to March 15, 2013. She said that they needed to get additional contractor quotes. I granted the extension.3/21/13 - Raphael Ketani. I received and reviewed the revised Remedial Action Work Plan dated March 2013. Tetra Tech plans to inject the treatment solutions at the 10 locations indicated in the DEC 1/25/13 letter. These are TTB-1, TTB-2, TTB-5 to TTB-10 and MIP-1 and MIP-4. About 1440 lbs. of RegenOx will be injected at a depth of 3 to 8 feet bgs. A 5% solution will be used. There will be two rounds of injections two weeks apart. About 120 lbs. of ORC Advanced will be injected into the saturated zone at 15 to 20 feet bgs at the locations TTGW-1, TTB-5 to TTB-7 and TTB-9. The treatment solutions will be allowed to work for 9 to 12 months. After this period of time, there will be two rounds of confirmatory soil and groundwater sampling on a quarterly basis. The samples will be tested for VOCs and SVOCs. If the MTA doesn't approve the plan, then excavation will take place in order to remove the contamination. A USEPA form 40 CFR Part 144 will be submitted to the EPA.I approved the revised work plan in an e-mail to Ms. Gaurin and indicated that the DEC would like the work to proceed as soon as possible.5/15/13 - Raphael Ketani. I tried to contact Ms. Gaurin (973) 630-8040 regarding progress at the site, but could only leave a voice message and send an e-mail.Later, Ms. Gaurin sent me an e-mail stating: We submitted draft engineering drawings to the MTA just after receiving your approval and we only heard back from them last week. We need to pick up the marked up copies of our drawings and address their comments. Then we will resubmit the drawings for review/approval which may take MTA several weeks. We will contact you as soon as we receive MTA approval and are ready to schedule the injection.8/23/13 - Raphael Ketani. I hadn't received any correspondences from Ms. Gaurin regarding progress at the site. Therefore, I sent her an e-mail requesting an update.8/24/13 - Raphael Ketani. Ms. Gaurin sent me an e-mail today stating that Tetra Tech received the comments on the drawings from the MTA. Tetra Tech intends to resubmit the drawings with the responses to the comments sometime during September 2013. Until the drawings are finalized, a drilling contractor will not be retained or scheduled. It is expected that no work will take place until October or later.

Remarks: leaking fill line/repairs and clean up pending

COURT PLAZA (Continued) **S110309405**

Material:

Site ID:	431696
Operable Unit ID:	1183167
Operable Unit:	01
Material ID:	2177365
Material Code:	0002A
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

H74 **EDR US Hist Auto Stat** **1015520616**
WSW **5 COURT SQ** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.124 mi.
654 ft. **Site 8 of 8 in cluster H**

Relative:
Higher

Actual:
14 ft.

EDR Historical Auto Stations:

Name:	AIRPORT CAR SERVICE
Year:	2003
Address:	5 COURT SQ
Name:	AIRPORT CAR SERVICE
Year:	2011
Address:	5 COURT SQ

L75 **LOT 27,TAXBLOCK 431** **NY E DESIGNATION** **S108469548**
NNE **42-74 HUNTER STREET** **N/A**
< 1/8 **QUEENS, NY 11101**
0.124 mi.
657 ft. **Site 1 of 3 in cluster L**

Relative:
Higher

Actual:
15 ft.

E DESIGNATION:

Tax Lot(s):	27
E-No:	E-104
Effective Date:	7/26/2001
Satisfaction Date:	Not reported
Ceqr Number:	00DCP055Q
Ulurp Number:	000406(A)ZMQ
Zoning Map No:	8d, 9b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code:	QN
Community District:	402
Census Tract:	19
Census Block:	1003
School District:	30
City Council District:	26
Fire Company:	E258

LOT 27,TAXBLOCK 431 (Continued) **S108469548**

Health Area:	41
Police Precinct:	108
Zone District 1:	M1-5/R7-3
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	LIC
Special Purpose District2:	Not reported
All Components1:	M1-5/R7-3/LIC
All Components2:	Not reported
Split Boundary Indicator:	N
Building Class:	B9
Land Use Category:	01
Number of Easements:	0
Owner, Type of Code:	Not reported
Owner Name:	FELIPE C PAEZ
Lot Area:	000001115
Total Building Floor Area:	00000001180
Commercial Floor Area:	00000000000
Office Floor Area:	00000000000
Retail Floor Area:	00000000000
Garage Floor Area:	00000000000
Storage Floor Area:	00000000000
Factory Floor Area:	00000000000
Other Floor Area:	00000000000
Floor Area,Total Bld Source Code:	7
Number of Buildings:	00001
Number of Floors:	002.00
Residential Units:	00002
Non and Residential Units:	00002
Lot Frontage:	0025.00
Lot Depth:	0044.58
Building Frontage:	0025.00
Building Depth:	0024.00
Proximity Code:	2
Irregular Lot Code:	N
Lot Type:	5
Basement Type Grade:	1
Land Assessed Value:	00000001683
Total Assessed Value:	00000009592
Land Exempt Value:	00000000000
Total Exempt Value:	00000000000
Year Built:	1901
Year Built Code:	E
Year Altered1:	2002
Year Altered2:	0000
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	0001.06
Maximum Allowable Far:	05.00
Borough Code:	4
Borough Tax Block And Lot:	4004310027
Condominium Number:	00000
Census Tract 2:	0019
X Coordinate:	1000661
Y Coordinate:	0212059
Zoning Map:	09B

LOT 27,TAXBLOCK 431 (Continued) **S108469548**

Sanborn Map:	401 024
Tax Map:	40302
E Designation No:	E-104
Date of RPAD Data:	11/2005
Date of DCAS Data:	01/2006
Date of Zoning Data:	11/2005
Date of Major Property Data:	11/2005
Date of Landmark Data:	12/2005
Date of Base Map Data:	01/2006
Date of Mass Appraisal Data:	11/2005
Date of Political and Adm Data:	08/2005
Pluto-Base Map Indicator:	1

K76
ENE
1/8-1/4
0.125 mi.
662 ft.

Relative:
Higher

Actual:
16 ft.

TOP STAR FABRICARE **NY DRYCLEANERS** **S110248144**
43-43 QUEENS STREET **N/A**
LI CITY, NY 11101

Site 2 of 2 in cluster K

DRYCLEANERS:

Facility ID:	2-6304-00678
Phone Number:	718-784-4332
Region:	Not reported
Registration Effective Date:	10/5/2007
Inspection Date:	07SEP12
Install Date:	98
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

M77
SW
1/8-1/4
0.128 mi.
677 ft.

Relative:
Lower

Actual:
13 ft.

CON EDISON **NY MANIFEST** **S113495763**
45-34 COURT SQ **N/A**
QUEENS, NY 11101

Site 1 of 5 in cluster M

NY MANIFEST:

EPA ID:	NYP004294823
Country:	USA
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-3770
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported

CON EDISON (Continued) **S113495763**

Generator Ship Date:	20-Mar-2013 00:00:00
Trans1 Recv Date:	20-Mar-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	20-Mar-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004294823
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	400
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	002017269GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

M78 **EAGLE ELECTRIC MANUFACTURING CO** **RCRA-CESQG** **1000279162**
SW **45-31 COURT SQ** **NY CBS AST** **NYD001287986**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **NY MANIFEST**
0.128 mi. **NY CBS**
677 ft. **Site 2 of 5 in cluster M** **US AIRS**

Relative:
Lower

Actual:
13 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	COOPER WIRING DEVICES (EAGLE ELECTRIC)
Facility address:	45-01 COURT SQ LONG ISLAND CITY, NY 11101
EPA ID:	NYD001287986
Mailing address:	COURT SQ LONG ISLAND CITY, NY 11101
Contact:	SAED ABUASI
Contact address:	COURT SQ LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	(718) 361-4821
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	COOPER INDUSTRIES
Owner/operator address:	600 TRAVIS HOUSTON, TX 77002
Owner/operator country:	US
Owner/operator telephone:	(713) 209-8618
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	03/16/2000
Owner/Op end date:	Not reported

Owner/operator name:	COOPER INDUSTRIES
Owner/operator address:	600 TRAVIS HOUSTON, TX 77002
Owner/operator country:	US
Owner/operator telephone:	(713) 209-8618
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	03/16/2000
Owner/Op end date:	Not reported

Owner/operator name:	COOPER INDUSTRIES
Owner/operator address:	600 TRAVIS HOUSTON, TX 77002
Owner/operator country:	Not reported
Owner/operator telephone:	(713) 209-8618
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	03/16/2000
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: COOPER WIRING DEVICES (EAGLE ELECTRIC)
Classification: Small Quantity Generator

Date form received by agency: 01/20/2005
Facility name: COOPER WIRING DEVICES (EAGLE ELECTRIC)
Classification: Large Quantity Generator

Date form received by agency: 02/05/2002
Facility name: COOPER WIRING DEVICES (EAGLE ELECTRIC)
Classification: Large Quantity Generator

Date form received by agency: 01/14/2002
Facility name: COOPER WIRING DEVICES (EAGLE ELECTRIC)
Site name: COOPER WIRING DEVICES
Classification: Small Quantity Generator

Date form received by agency: 01/01/2001
Facility name: COOPER WIRING DEVICES (EAGLE ELECTRIC)
Site name: EAGLE ELECTRIC MFG CO
Classification: Large Quantity Generator

Date form received by agency: 10/17/2000
Facility name: COOPER WIRING DEVICES (EAGLE ELECTRIC)
Site name: COOPER WIRING DEVICES
Classification: Large Quantity Generator

Date form received by agency: 02/18/1998
Facility name: COOPER WIRING DEVICES (EAGLE ELECTRIC)
Site name: EAGLE ELECTRIC MFG CO INC
Classification: Large Quantity Generator

Date form received by agency: 05/24/1996
Facility name: COOPER WIRING DEVICES (EAGLE ELECTRIC)
Site name: EAGLE ELECTRIC MFG INC
Classification: Large Quantity Generator

Date form received by agency: 02/18/1994
Facility name: COOPER WIRING DEVICES (EAGLE ELECTRIC)
Site name: EAGLE ELECTRIC MFG. CO. INC.
Classification: Large Quantity Generator

Date form received by agency: 03/25/1992
Facility name: COOPER WIRING DEVICES (EAGLE ELECTRIC)
Site name: EAGLE ELECTRIC MANUFACTURING
Classification: Large Quantity Generator

Date form received by agency: 03/01/1990
Facility name: COOPER WIRING DEVICES (EAGLE ELECTRIC)
Site name: EAGLE ELECTRIC MANUFACTURING COMPANY
Classification: Large Quantity Generator

Date form received by agency: 10/31/1985

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Facility name: COOPER WIRING DEVICES (EAGLE ELECTRIC)
Site name: COOPER WIRING DEVICES
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: D000
Waste name: Not Defined

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D007
Waste name: CHROMIUM

Waste code: F001
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F002
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F005
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F006
Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

Waste code: F007
Waste name: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS

Waste code: F008
Waste name: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS WHERE CYANIDES ARE USED IN THE PROCESS.

Facility Has Received Notices of Violations:

Regulation violated: SR - 373-3.3b & 373-3.9d1
Area of violation: Generators - General
Date violation determined: 02/12/1999
Date achieved compliance: 10/27/1999
Violation lead agency: EPA
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 03/31/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: 18000
Paid penalty amount: Not reported

Regulation violated: SR - 373-3.3b & 373-3.9d1
Area of violation: Generators - General
Date violation determined: 02/12/1999
Date achieved compliance: 10/27/1999
Violation lead agency: EPA
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 12/21/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 32508
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 10/01/1996
Date achieved compliance: 10/22/1996
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/01/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 04/12/1994
Date achieved compliance: 07/11/1994
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/13/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 04/12/1994
Date achieved compliance: 07/11/1994
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/13/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 12/18/1987
Date achieved compliance: 04/14/1988
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/02/1988
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 10/15/1987
Date achieved compliance: 06/08/1988
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 10/15/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Final penalty amount: 500
Paid penalty amount: 500

Evaluation Action Summary:
Evaluation date: 05/09/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/27/1999
Evaluation: CASE DEVELOPMENT INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 02/12/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 10/27/1999
Evaluation lead agency: EPA

Evaluation date: 09/24/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 10/22/1996
Evaluation lead agency: State

Evaluation date: 02/09/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 07/11/1994
Evaluation lead agency: State

Evaluation date: 02/09/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 07/11/1994
Evaluation lead agency: State

Evaluation date: 12/18/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 04/14/1988
Evaluation lead agency: State

Evaluation date: 10/15/1987
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Manifest
Date achieved compliance: 06/08/1988
Evaluation lead agency: State

CBS AST:
CBS Number: 2-000041
ICS Number: 2-125791
PBS Number: Not reported
MOSF Number: Not reported

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

SPDES Number:	Not reported
Facility Status:	ACTIVE FACILITY
Facility Type:	MANUFACTURING
Telephone:	(718) 937-8000
Facility Town:	NEW YORK CITY
Region:	STATE
Expiration Date:	05/12/1999
Total Capacity of All Active Tanks(gal):	0
Operator:	CHARLES FARLEY
Emergency Contact:	ANTHONY TORCIA
Emergency Phone:	(718) 937-8000
Owner Name:	EAGLE ELECTRIC MFG CO. INC.
Owner Address:	45-31 COURT SQUARE
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Owner Telephone:	(718) 937-8000
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	EAGLE ELECTRIC MFG CO. INC.
Mail Contact Addr:	45-31 COURT SQUARE
Mail Contact Addr2:	Not reported
Mail Contact Contact:	ANTHONY TORCIA
Mail Contact City,St,Zip:	LONG ISLAND CITY, NY 11101
Mail Phone:	(718) 937-8000

Tank Id:	1
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	0
Install Date:	11/87
Tank Closed:	07/99
Capacity (Gal):	4300
Chemical:	Sodium hydroxide
Tank Location:	ABOVEGROUND
Tank Type:	Fiberglass coated steel
Total Tanks:	0
Tank Secret:	False
Tank Containment:	Diking
Tank Error Status:	No Missing Data
Date Entered:	05/12/1989
Certified Date:	02/26/1997
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	0
Pipe Containment:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	Catch Basin
Haz Percent:	50
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	Not reported
Is Updated:	False

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Renew Date:	06/14/93
Is It There:	False
Delinquent:	False
Date Expired:	05/12/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	09/06/2001

NY MANIFEST:

EPA ID:	NYD001287986
Country:	USA
Mailing Name:	EAGLE ELECTRIC MANUFACTURING CO
Mailing Contact:	EAGLE ELECTRIC MANUFACTURING CO
Mailing Address:	45-31 COURT SQUARE
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-937-8000

Document ID:	NYA6405507
Manifest Status:	Completed copy
Trans1 State ID:	CT1469A
Trans2 State ID:	CT3372A
Generator Ship Date:	871117
Trans1 Recv Date:	871117
Trans2 Recv Date:	871117
TSD Site Recv Date:	871118
Part A Recv Date:	871127
Part B Recv Date:	871201
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	CTD980521280
Trans2 EPA ID:	CTD980521280
TSDF ID:	CDD001287986
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	36820
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	87

Document ID:	NYA6405516
Manifest Status:	Completed copy
Trans1 State ID:	CTG60164
Trans2 State ID:	Not reported
Generator Ship Date:	871105
Trans1 Recv Date:	871105
Trans2 Recv Date:	871105
TSD Site Recv Date:	871106

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Part A Recv Date:	871113
Part B Recv Date:	871120
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	CTD980521280
Trans2 EPA ID:	Not reported
TSDF ID:	CDD001287986
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	31920
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	87

Document ID:	NYA6405561
Manifest Status:	Completed copy
Trans1 State ID:	S2908
Trans2 State ID:	Not reported
Generator Ship Date:	880119
Trans1 Recv Date:	880119
Trans2 Recv Date:	880119
TSD Site Recv Date:	880119
Part A Recv Date:	880122
Part B Recv Date:	880127
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	CTD980521280
Trans2 EPA ID:	Not reported
TSDF ID:	CDD980756415
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	00026
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	88

Document ID:	NYA6405489
Manifest Status:	Completed copy
Trans1 State ID:	G-60164
Trans2 State ID:	92472CT
Generator Ship Date:	880105
Trans1 Recv Date:	880105
Trans2 Recv Date:	880105
TSD Site Recv Date:	880106
Part A Recv Date:	880121
Part B Recv Date:	880112
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	CTD980521280
Trans2 EPA ID:	CTD980521280
TSDF ID:	CDD980756415
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	00030
Units:	Y - Cubic yards* (.85 tons)

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 88

Document ID: NYA6405687
Manifest Status: Completed copy
Trans1 State ID: G-60164CT
Trans2 State ID: S2908CT
Generator Ship Date: 880223
Trans1 Recv Date: 880223
Trans2 Recv Date: 880223
TSD Site Recv Date: 880224
Part A Recv Date: 880226
Part B Recv Date: 880307
Generator EPA ID: NYD001287986
Trans1 EPA ID: CTD980521280
Trans2 EPA ID: Not reported
TSDF ID: CDD980756415
Waste Code: F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity: 00029
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 88

Document ID: NYA6405669
Manifest Status: Completed copy
Trans1 State ID: G-60164CT
Trans2 State ID: 95910-CT
Generator Ship Date: 880405
Trans1 Recv Date: 880405
Trans2 Recv Date: 880405
TSD Site Recv Date: 880406
Part A Recv Date: 880411
Part B Recv Date: 880419
Generator EPA ID: NYD001287986
Trans1 EPA ID: CTD980521280
Trans2 EPA ID: Not reported
TSDF ID: CDD980756415
Waste Code: F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity: 41700
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 88

Document ID: NYA6405723
Manifest Status: Completed copy

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Trans1 State ID:	CT-3371A
Trans2 State ID:	CTS2496
Generator Ship Date:	890905
Trans1 Recv Date:	890905
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890906
Part A Recv Date:	890911
Part B Recv Date:	890920
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	CTD980521280
Trans2 EPA ID:	Not reported
TSDF ID:	CDD980756415
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	37882
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	89

Document ID:	NYA6405642
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	CT-3371A
Trans2 State ID:	CT
Generator Ship Date:	900405
Trans1 Recv Date:	900405
Trans2 Recv Date:	900405
TSD Site Recv Date:	900406
Part A Recv Date:	900502
Part B Recv Date:	900508
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	CTD980521280
Trans2 EPA ID:	CTD980521280
TSDF ID:	CDD980756415
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	27840
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	90

Document ID:	NYA3019972
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	CT-3371A
Trans2 State ID:	S2498-CT
Generator Ship Date:	900612
Trans1 Recv Date:	900612
Trans2 Recv Date:	900612
TSD Site Recv Date:	900628
Part A Recv Date:	900731
Part B Recv Date:	900813
Generator EPA ID:	NYD001287986

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Trans1 EPA ID: CTD980521280
Trans2 EPA ID: Not reported
TSDF ID: CTD980521280
Waste Code: F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity: 26280
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 90

Document ID: NYA6405876
Manifest Status: Completed copy
Trans1 State ID: CT3371A
Trans2 State ID: V4165CT
Generator Ship Date: 910723
Trans1 Recv Date: 910723
Trans2 Recv Date: 910723
TSD Site Recv Date: 910724
Part A Recv Date: 910731
Part B Recv Date: 910812
Generator EPA ID: NYD001287986
Trans1 EPA ID: CTD983872748
Trans2 EPA ID: CTD983872748
TSDF ID: CDD980756415
Waste Code: F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity: 28528
Units: P - Pounds
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91

Document ID: NYB5110155
Manifest Status: Completed copy
Trans1 State ID: CT92478
Trans2 State ID: Not reported
Generator Ship Date: 941101
Trans1 Recv Date: 941101
Trans2 Recv Date: Not reported
TSD Site Recv Date: 941101
Part A Recv Date: 941109
Part B Recv Date: 941121
Generator EPA ID: NYD001287986
Trans1 EPA ID: CTD983872748
Trans2 EPA ID: Not reported
TSDF ID: CDD980756415
Waste Code: F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity: 23800
Units: P - Pounds
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Specific Gravity: 100
Year: 94

Document ID: NYB5110182
Manifest Status: Completed copy
Trans1 State ID: V18963LT
Trans2 State ID: Not reported
Generator Ship Date: 940804
Trans1 Recv Date: 940804
Trans2 Recv Date: Not reported
TSD Site Recv Date: 940805
Part A Recv Date: 940815
Part B Recv Date: 940822
Generator EPA ID: NYD001287986
Trans1 EPA ID: CTD983872748
Trans2 EPA ID: Not reported
TSDF ID: CDD980756415
Waste Code: F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity: 24493
Units: P - Pounds
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 94

Document ID: NJA2086136
Manifest Status: Completed copy
Trans1 State ID: 08690
Trans2 State ID: Not reported
Generator Ship Date: 950606
Trans1 Recv Date: 950606
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950609
Part A Recv Date: 950703
Part B Recv Date: 950622
Generator EPA ID: NYD001287986
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00726
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: NYB6582195
Manifest Status: Completed copy
Trans1 State ID: S2908
Trans2 State ID: Not reported
Generator Ship Date: 960502

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Trans1 Recv Date:	960502
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	960503
Part A Recv Date:	960510
Part B Recv Date:	960521
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	CTD983872748
Trans2 EPA ID:	Not reported
TSDF ID:	CDD980756415
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	33847
Units:	P - Pounds
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	96

Document ID:	NYB6786738
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	3009A
Trans2 State ID:	Not reported
Generator Ship Date:	960801
Trans1 Recv Date:	960801
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	960801
Part A Recv Date:	960819
Part B Recv Date:	960827
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	CTD983872748
Trans2 EPA ID:	Not reported
TSDF ID:	CDD980756415
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	21653
Units:	P - Pounds
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	96

Document ID:	NYC6585603
Manifest Status:	Not reported
Trans1 State ID:	MAD039322250
Trans2 State ID:	NJD986607380
Generator Ship Date:	11/18/2002
Trans1 Recv Date:	11/18/2002
Trans2 Recv Date:	11/21/2002
TSD Site Recv Date:	12/18/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	NCD000648451
Trans2 EPA ID:	Not reported
TSDF ID:	Not reported

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Waste Code: U080 - METHYLENE CHLORIDE
Quantity: 00900
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00020
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: U080 - METHYLENE CHLORIDE
Quantity: 00300
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 00010
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2002

Document ID: NYC7410238
Manifest Status: Not reported
Trans1 State ID: NY55817JC
Trans2 State ID: NJT16L8D
Generator Ship Date: 10/27/2004
Trans1 Recv Date: 10/27/2004
Trans2 Recv Date: 10/29/2004
TSD Site Recv Date: 11/07/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001287986
Trans1 EPA ID: TXR000050930
Trans2 EPA ID: Not reported
TSDF ID: KYD053348
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00600
Units: P - Pounds
Number of Containers: 003
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2004

Document ID: NYA3525366
Manifest Status: Completed copy

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Trans1 State ID:	S95636
Trans2 State ID:	Not reported
Generator Ship Date:	861105
Trans1 Recv Date:	861105
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	861105
Part A Recv Date:	861107
Part B Recv Date:	861112
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	NYD050592807
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000691949
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	00030
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	86

Document ID:	NYA6405588
Manifest Status:	Completed copy
Trans1 State ID:	CT-3371A
Trans2 State ID:	Not reported
Generator Ship Date:	880503
Trans1 Recv Date:	880503
Trans2 Recv Date:	880503
TSD Site Recv Date:	880504
Part A Recv Date:	880517
Part B Recv Date:	880512
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	CTD980521280
Trans2 EPA ID:	Not reported
TSDF ID:	CDD980756415
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	00018
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	88

Document ID:	NYA6405651
Manifest Status:	Completed copy
Trans1 State ID:	CT-G60164
Trans2 State ID:	S2497GK
Generator Ship Date:	880419
Trans1 Recv Date:	880419
Trans2 Recv Date:	880419
TSD Site Recv Date:	880420
Part A Recv Date:	880422
Part B Recv Date:	880428
Generator EPA ID:	NYD001287986

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Trans1 EPA ID: CTD980521280
Trans2 EPA ID: Not reported
TSDF ID: CDD980756415
Waste Code: F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity: 00026
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 88

Click this hyperlink while viewing on your computer to access
108 additional NY_MANIFEST: record(s) in the EDR Site Report.

EPA ID: CDD001287986
Country: USA
Mailing Name: EAGLE MANUFACTURING CO- EXPORTER
Mailing Contact: EAGLE MANUFACTURING CO- EXPORTER
Mailing Address: 45-31 COURT SQUARE-EXPORTER
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-937-8000

Document ID: NYA6405507
Manifest Status: Completed copy
Trans1 State ID: CT1469A
Trans2 State ID: CT3372A
Generator Ship Date: 871117
Trans1 Recv Date: 871117
Trans2 Recv Date: 871117
TSD Site Recv Date: 871118
Part A Recv Date: 871127
Part B Recv Date: 871201
Generator EPA ID: NYD001287986
Trans1 EPA ID: CTD980521280
Trans2 EPA ID: CTD980521280
TSDF ID: CDD001287986
Waste Code: F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity: 36820
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 87

Document ID: NYA6405516
Manifest Status: Completed copy
Trans1 State ID: CTG60164
Trans2 State ID: Not reported

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Generator Ship Date:	871105
Trans1 Recv Date:	871105
Trans2 Recv Date:	871105
TSD Site Recv Date:	871106
Part A Recv Date:	871113
Part B Recv Date:	871120
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	CTD980521280
Trans2 EPA ID:	Not reported
TSDF ID:	CDD001287986
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	31920
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	87

Document ID:	NYA6405561
Manifest Status:	Completed copy
Trans1 State ID:	S2908
Trans2 State ID:	Not reported
Generator Ship Date:	880119
Trans1 Recv Date:	880119
Trans2 Recv Date:	880119
TSD Site Recv Date:	880119
Part A Recv Date:	880122
Part B Recv Date:	880127
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	CTD980521280
Trans2 EPA ID:	Not reported
TSDF ID:	CDD980756415
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	00026
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	88

Document ID:	NYA6405489
Manifest Status:	Completed copy
Trans1 State ID:	G-60164
Trans2 State ID:	92472CT
Generator Ship Date:	880105
Trans1 Recv Date:	880105
Trans2 Recv Date:	880105
TSD Site Recv Date:	880106
Part A Recv Date:	880121
Part B Recv Date:	880112
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	CTD980521280
Trans2 EPA ID:	CTD980521280

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

TSDF ID: CDD980756415
Waste Code: F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity: 00030
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 88

Document ID: NYA6405687
Manifest Status: Completed copy
Trans1 State ID: G-60164CT
Trans2 State ID: S2908CT
Generator Ship Date: 880223
Trans1 Recv Date: 880223
Trans2 Recv Date: 880223
TSD Site Recv Date: 880224
Part A Recv Date: 880226
Part B Recv Date: 880307
Generator EPA ID: NYD001287986
Trans1 EPA ID: CTD980521280
Trans2 EPA ID: Not reported
TSDF ID: CDD980756415
Waste Code: F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity: 00029
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 88

Document ID: NYA6405669
Manifest Status: Completed copy
Trans1 State ID: G-60164CT
Trans2 State ID: 95910-CT
Generator Ship Date: 880405
Trans1 Recv Date: 880405
Trans2 Recv Date: 880405
TSD Site Recv Date: 880406
Part A Recv Date: 880411
Part B Recv Date: 880419
Generator EPA ID: NYD001287986
Trans1 EPA ID: CTD980521280
Trans2 EPA ID: Not reported
TSDF ID: CDD980756415
Waste Code: F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity: 41700
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 88

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Document ID:	NYA6405723
Manifest Status:	Completed copy
Trans1 State ID:	CT-3371A
Trans2 State ID:	CTS2496
Generator Ship Date:	890905
Trans1 Recv Date:	890905
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890906
Part A Recv Date:	890911
Part B Recv Date:	890920
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	CTD980521280
Trans2 EPA ID:	Not reported
TSDF ID:	CDD980756415
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	37882
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	89

Document ID:	NYA6405642
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	CT-3371A
Trans2 State ID:	CT
Generator Ship Date:	900405
Trans1 Recv Date:	900405
Trans2 Recv Date:	900405
TSD Site Recv Date:	900406
Part A Recv Date:	900502
Part B Recv Date:	900508
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	CTD980521280
Trans2 EPA ID:	CTD980521280
TSDF ID:	CDD980756415
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	27840
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	90

Document ID:	NYA3019972
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	CT-3371A
Trans2 State ID:	S2498-CT
Generator Ship Date:	900612
Trans1 Recv Date:	900612
Trans2 Recv Date:	900612
TSD Site Recv Date:	900628
Part A Recv Date:	900731

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Part B Recv Date: 900813
Generator EPA ID: NYD001287986
Trans1 EPA ID: CTD980521280
Trans2 EPA ID: Not reported
TSDF ID: CTD980521280
Waste Code: F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity: 26280
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 90

Document ID: NYA6405876
Manifest Status: Completed copy
Trans1 State ID: CT3371A
Trans2 State ID: V4165CT
Generator Ship Date: 910723
Trans1 Recv Date: 910723
Trans2 Recv Date: 910723
TSD Site Recv Date: 910724
Part A Recv Date: 910731
Part B Recv Date: 910812
Generator EPA ID: NYD001287986
Trans1 EPA ID: CTD983872748
Trans2 EPA ID: CTD983872748
TSDF ID: CDD980756415
Waste Code: F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity: 28528
Units: P - Pounds
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 91

Document ID: NYB5110155
Manifest Status: Completed copy
Trans1 State ID: CT92478
Trans2 State ID: Not reported
Generator Ship Date: 941101
Trans1 Recv Date: 941101
Trans2 Recv Date: Not reported
TSD Site Recv Date: 941101
Part A Recv Date: 941109
Part B Recv Date: 941121
Generator EPA ID: NYD001287986
Trans1 EPA ID: CTD983872748
Trans2 EPA ID: Not reported
TSDF ID: CDD980756415
Waste Code: F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity: 23800
Units: P - Pounds
Number of Containers: 001

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 94

Document ID: NYB5110182
Manifest Status: Completed copy
Trans1 State ID: V18963LT
Trans2 State ID: Not reported
Generator Ship Date: 940804
Trans1 Recv Date: 940804
Trans2 Recv Date: Not reported
TSD Site Recv Date: 940805
Part A Recv Date: 940815
Part B Recv Date: 940822
Generator EPA ID: NYD001287986
Trans1 EPA ID: CTD983872748
Trans2 EPA ID: Not reported
TSDF ID: CDD980756415
Waste Code: F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity: 24493
Units: P - Pounds
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 94

Document ID: NJA2086136
Manifest Status: Completed copy
Trans1 State ID: 08690
Trans2 State ID: Not reported
Generator Ship Date: 950606
Trans1 Recv Date: 950606
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950609
Part A Recv Date: 950703
Part B Recv Date: 950622
Generator EPA ID: NYD001287986
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00726
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: NYB6582195
Manifest Status: Completed copy
Trans1 State ID: S2908

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Trans2 State ID:	Not reported
Generator Ship Date:	960502
Trans1 Recv Date:	960502
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	960503
Part A Recv Date:	960510
Part B Recv Date:	960521
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	CTD983872748
Trans2 EPA ID:	Not reported
TSDF ID:	CDD980756415
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	33847
Units:	P - Pounds
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	96

Document ID:	NYB6786738
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	3009A
Trans2 State ID:	Not reported
Generator Ship Date:	960801
Trans1 Recv Date:	960801
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	960801
Part A Recv Date:	960819
Part B Recv Date:	960827
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	CTD983872748
Trans2 EPA ID:	Not reported
TSDF ID:	CDD980756415
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	21653
Units:	P - Pounds
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	96

Document ID:	NYC6585603
Manifest Status:	Not reported
Trans1 State ID:	MAD039322250
Trans2 State ID:	NJD986607380
Generator Ship Date:	11/18/2002
Trans1 Recv Date:	11/18/2002
Trans2 Recv Date:	11/21/2002
TSD Site Recv Date:	12/18/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	NCD000648451

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Trans2 EPA ID: Not reported
TSDF ID: Not reported
Waste Code: U080 - METHYLENE CHLORIDE
Quantity: 00900
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00020
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: U080 - METHYLENE CHLORIDE
Quantity: 00300
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 00010
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2002

Document ID: NYC7410238
Manifest Status: Not reported
Trans1 State ID: NY55817JC
Trans2 State ID: NJT16L8D
Generator Ship Date: 10/27/2004
Trans1 Recv Date: 10/27/2004
Trans2 Recv Date: 10/29/2004
TSD Site Recv Date: 11/07/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001287986
Trans1 EPA ID: TXR000050930
Trans2 EPA ID: Not reported
TSDF ID: KYD053348
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00600
Units: P - Pounds
Number of Containers: 003
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2004

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Document ID:	NYA3525366
Manifest Status:	Completed copy
Trans1 State ID:	S95636
Trans2 State ID:	Not reported
Generator Ship Date:	861105
Trans1 Recv Date:	861105
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	861105
Part A Recv Date:	861107
Part B Recv Date:	861112
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	NYD050592807
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000691949
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	00030
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	86

Document ID:	NYA6405588
Manifest Status:	Completed copy
Trans1 State ID:	CT-3371A
Trans2 State ID:	Not reported
Generator Ship Date:	880503
Trans1 Recv Date:	880503
Trans2 Recv Date:	880503
TSD Site Recv Date:	880504
Part A Recv Date:	880517
Part B Recv Date:	880512
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	CTD980521280
Trans2 EPA ID:	Not reported
TSDF ID:	CDD980756415
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	00018
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	88

Document ID:	NYA6405651
Manifest Status:	Completed copy
Trans1 State ID:	CT-G60164
Trans2 State ID:	S2497GK
Generator Ship Date:	880419
Trans1 Recv Date:	880419
Trans2 Recv Date:	880419
TSD Site Recv Date:	880420
Part A Recv Date:	880422

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Part B Recv Date:	880428
Generator EPA ID:	NYD001287986
Trans1 EPA ID:	CTD980521280
Trans2 EPA ID:	Not reported
TSDF ID:	CDD980756415
Waste Code:	F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity:	00026
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	88

Click this hyperlink while viewing on your computer to access
108 additional NY_MANIFEST: record(s) in the EDR Site Report.

CBS:

CBS Number:	2-000041
Program Type:	CBS
Facility Status:	Unregulated
Expiration Date:	N/A
Dec Region:	2
UTMX:	589216.38766999
UTMY:	4511035.8664899

AIRS (AFS):

Airs Minor Details:

EPA plant ID:	110000323169
Plant name:	EAGLE ELECTRIC MANUFACTURING CO
Plant address:	45-31 COURT SQ LONG ISLAND CITY, NY 11101
County:	QUEENS
Region code:	02
Dunn & Bradst #:	001287986
Air quality cntrl region:	043
Sic code:	3699
Sic code desc:	ELECTRICAL EQUIPMENT AND SUPPLIES, NEC
North Am. industrial classf:	335931
NAIC code description:	Current-Carrying Wiring Device Manufacturing
Default compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Default classification:	POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Govt facility:	ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT
Current HPV:	Not reported

Historical Compliance Minor Sources:

State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1001
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1004

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1102
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1002
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1003
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1101
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1103
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: SIP SOURCE

Compliance & Violation Data by Minor Sources:
Air program code: SIP SOURCE
Plant air program pollutant: SULFUR DIOXIDE
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

Air program code: SIP SOURCE
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported

EAGLE ELECTRIC MANUFACTURING CO (Continued) **1000279162**

Turnover compliance: Not reported

M79 **45-30 COURT SQUARE** **NY AST** **U003384691**
SW **45-30 COURT SQUARE** **NY HIST AST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.128 mi.
677 ft. **Site 3 of 5 in cluster M**

Relative:
Lower

Actual:
13 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-092673
Program Type:	PBS
UTM X:	589165.14954000001
UTM Y:	4511102.4818799999
Expiration Date:	2017/02/14
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	2404
Affiliation Type:	Facility Owner
Company Name:	MICHAEL GELLING
Contact Type:	MEMBER
Contact Name:	MICHAEL GELLING
Address1:	9520 FALLS BRIDGE LANE
Address2:	Not reported
City:	POTOMAC
State:	MD
Zip Code:	20854
Country Code:	001
Phone:	(917) 716-3469
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	8/15/2012

Site Id:	2404
Affiliation Type:	Mail Contact
Company Name:	Not reported
Contact Type:	Not reported
Contact Name:	MICHAEL GELLING
Address1:	9520 FALLS BRIDGE LANE
Address2:	Not reported
City:	POTOMAC
State:	MD
Zip Code:	20854
Country Code:	001
Phone:	(917) 716-3469
EMail:	MRGELLING@GMAIL.COM
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	8/15/2012

Site Id:	2404
Affiliation Type:	On-Site Operator
Company Name:	45-30 COURT SQUARE
Contact Type:	Not reported

45-30 COURT SQUARE (Continued) **U003384691**

Contact Name:	SABAHETA MRKULIC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 482-3959
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	2404
Affiliation Type:	Emergency Contact
Company Name:	MICHAEL GELLING
Contact Type:	Not reported
Contact Name:	THERESIA SCHATZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 533-3450
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank Id:	4244
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1916
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported

45-30 COURT SQUARE (Continued) **U003384691**

Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DXLIVING
Last Modified:	05/08/2007
Material Name:	#2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number:	2-092673
SWIS Code:	6301
Operator:	ALFRED HERTRICH
Facility Phone:	(718) 729-2766
Facility Addr2:	45030 COURT SQUARE
Facility Type:	APARTMENT BUILDING
Emergency:	COASTAL PETROLEUM TANK CORP
Emergency Tel:	(212) 475-4263
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	FREDERICK SCHATZ
Owner Address:	28-31 43RD STREET
Owner City,St,Zip:	LONG ISLAND CITY, NY 11103
Federal ID:	Not reported
Owner Tel:	(718) 721-7682
Owner Type:	Private Resident
Owner Subtype:	Not reported
Mailing Contact:	Not reported
Mailing Name:	FREDERICK SCHATZ
Mailing Address:	28-31 43RD STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	LONG ISLAND CITY, NY 11103
Mailing Telephone:	(718) 721-7682
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	05/05/1997
Expiration:	05/07/2002
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	2000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service

45-30 COURT SQUARE (Continued) **U003384691**

Install Date:	Not reported
Capacity (Gal):	2000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	None
Leak Detection:	0
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
SPDES Number:	Not reported
Lat/Long:	Not reported

M80 **ROGERS ENGRAVING CO INC** **RCRA NonGen / NLR** **1000217522**
SW **45-61 COURT SQ** **FINDS** **NYD002405645**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.128 mi.
677 ft. **Site 4 of 5 in cluster M**

Relative:
Lower

Actual:
13 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ROGERS ENGRAVING CO INC
Facility address:	45-61 COURT SQ LONG ISLAND CITY, NY 11101
EPA ID:	NYD002405645
Mailing address:	COURT SQ LONG ISLAND CITY, NY 11101
Contact:	JOSEPH DUFFY
Contact address:	COURT SQ LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	(718) 786-6225
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported

ROGERS ENGRAVING CO INC (Continued) **1000217522**

Owner/Op end date: Not reported

Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: ROGERS ENGRAVING CO INC
Classification: Not a generator, verified

Date form received by agency: 11/26/1980
Facility name: ROGERS ENGRAVING CO INC
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110004341178

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

M81 **EAGLE ELECTRIC MFG CO INC** **NY AST** **U003393333**
SW **45-31 COURT SQ** **NY HIST AST** **N/A**
1/8-1/4 **LIC, NY 11104**
0.128 mi.
677 ft. **Site 5 of 5 in cluster M**

Relative:
Lower

Actual:
13 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-017418
Program Type:	PBS
UTM X:	589175.28622999997
UTM Y:	4511109.1542400001
Expiration Date:	2017/02/09
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	132
Affiliation Type:	Emergency Contact
Company Name:	ARRIC LOFTS CONDOMINIUM
Contact Type:	Not reported
Contact Name:	DUMITRU CULETU
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 706-1721
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	1/11/2013

Site Id:	132
Affiliation Type:	On-Site Operator
Company Name:	45-31 COURT SQ
Contact Type:	Not reported
Contact Name:	DUMITRU CULETU
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 706-7185
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	1/11/2013

Site Id:	132
Affiliation Type:	Mail Contact
Company Name:	DOUG ELLIMAN PROPERTY MGMT
Contact Type:	Not reported
Contact Name:	PATRICIA PETTWAY-BROWN
Address1:	675THIRD AVE--5TH FLOOR
Address2:	Not reported
City:	NY

EAGLE ELECTRIC MFG CO INC (Continued) **U003393333**

State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 350-2846
EMail:	PATRACIA-PETTWAY-BROWN@ELLIMAMNPR.COM
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	1/11/2013

Site Id:	132
Affiliation Type:	Facility Owner
Company Name:	ARRIC LOFTS CONDOMINIUM
Contact Type:	MGR
Contact Name:	PATRICIA PETTWAY-BROWN
Address1:	45-31 COURT SQ
Address2:	Not reported
City:	LIC
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 706-7185
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	1/11/2013

Tank Info:

Tank Number:	001
Tank Id:	27006
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I05 - Overfill - Vent Whistle
G03 - Tank Secondary Containment - Vault (w/o access)
C00 - Pipe Location - No Piping
F04 - Pipe External Protection - Fiberglass
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1955
Capacity Gallons:	20000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True

EAGLE ELECTRIC MFG CO INC (Continued) **U003393333**

Modified By: msbaptis
Last Modified: 01/17/2007
Material Name: #6 Fuel Oil (On-Site Consumption)

Tank Number: 002
Tank Id: 27007
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F04 - Pipe External Protection - Fiberglass
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle
G03 - Tank Secondary Containment - Vault (w/o access)
Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - In Place
Pipe Model: Not reported
Install Date: 01/01/1955
Capacity Gallons: 20000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 02/07/2012
Register: True
Modified By: MSBAPTIS
Last Modified: 01/11/2013
Material Name: #6 Fuel Oil (On-Site Consumption)

HIST AST:
PBS Number: 2-017418
SWIS Code: 6301
Operator: EAGLE ELECTRIC MFG CO INC
Facility Phone: (718) 937-8000
Facility Addr2: 45031 COURT SQ
Facility Type: Not reported
Emergency: ALFRED PIZZUTO
Emergency Tel: (914) 962-6467
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: ENGLE ELECTRIC MFG CO INC
Owner Address: 45-31 COURT SQ
Owner City,St,Zip: LIC, NY 11104
Federal ID: Not reported
Owner Tel: (718) 937-8000
Owner Type: Corporate/Commercial

EAGLE ELECTRIC MFG CO INC (Continued) **U003393333**

Owner Subtype:	Not reported
Mailing Contact:	AL PIZZUTO
Mailing Name:	EAGLE ELECTRIC MFG CO INC
Mailing Address:	45-31 COURT SQ
Mailing Address 2:	Not reported
Mailing City,St,Zip:	LIC, NY 11104
Mailing Telephone:	(718) 937-8000
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	09/30/1999
Expiration:	10/23/2002
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	40000
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	20000
Product Stored:	NOS 5 OR 6 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	04
Tank Containment:	Diking
Leak Detection:	0
Overfill Protection:	46
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

Tank ID:	002

EAGLE ELECTRIC MFG CO INC (Continued) **U003393333**

Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	20000
Product Stored:	NOS 5 OR 6 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	04
Tank Containment:	Diking
Leak Detection:	0
Overfill Protection:	46
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

L82 **42-64 HUNTER STREET** **NY LTANKS** **S102619659**
NNE **42-64 HUNTER STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY**
0.131 mi.
693 ft. **Site 2 of 3 in cluster L**

Relative:
Higher

Actual:
15 ft.

LTANKS:

Site ID:	119063
Spill Number/Closed Date:	9310213 / 11/22/1993
Spill Date:	11/22/1993
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	11/22/1993
Cleanup Meets Standard:	True
SWIS:	4101
Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	11/22/1993
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	11/23/1993
Spill Record Last Update:	9/30/2004
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported

42-64 HUNTER STREET (Continued) **S102619659**

Spiller City,St,Zip:	NN
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	103436
DEC Memo:	Not reported
Remarks:	CUST. REPORTED LEAK - SVC. MN. APPLIED MAGNA-OATCH - APPLIED SPEEDI DRY & P/U & DISPOSED WILL REPAIR TANK ROMORROW - ISLAND TANK CO. TO REPAIR.

Material:

Site ID:	119063
Operable Unit ID:	989155
Operable Unit:	01
Material ID:	392841
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

L83 **EDR US Hist Auto Stat** **1015489097**
North **4243 27TH ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.132 mi.
699 ft. **Site 3 of 3 in cluster L**

Relative: Higher

Actual: 14 ft.

EDR Historical Auto Stations:

Name:	AUTO EXPRESS
Year:	2011
Address:	4243 27TH ST

J84 **NYCT - COURT SQUARE STA G LINE** **RCRA NonGen / NLR** **1001203144**
West **JACKSON ST & COURT SQ** **FINDS** **NYR000045062**
1/8-1/4 **LONG ISLAND CITY, NY** **NY MANIFEST**
0.134 mi.
707 ft. **Site 2 of 6 in cluster J**

Relative: Higher

Actual: 16 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NYCT - COURT SQUARE STA G LINE
Facility address:	JACKSON ST & COURT SQ LONG ISLAND CITY, NY 11101
EPA ID:	NYR000045062
Mailing address:	JAY ST ROOM 819 BROOKLYN, NY 11201

NYCT - COURT SQUARE STA G LINE (Continued) **1001203144**

Contact:	JAMES CRANDALL
Contact address:	JAY ST ROOM 819 BROOKLYN, NY 11201
Contact country:	US
Contact telephone:	(718) 243-4581
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NEW YORK CITY TRANSIT
Owner/operator address:	370 JAY ST ROOM 819 BROOKLYN, NY 11201
Owner/operator country:	Not reported
Owner/operator telephone:	(718) 243-4581
Legal status:	Other
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/0001
Owner/Op end date:	Not reported

Owner/operator name:	NEW YORK CITY TRANSIT
Owner/operator address:	370 JAY ST ROOM 819 BROOKLYN, NY 11201
Owner/operator country:	US
Owner/operator telephone:	(718) 243-4581
Legal status:	Other
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	NEW YORK CITY TRANSIT
Owner/operator address:	370 JAY ST ROOM 819 BROOKLYN, NY 11201
Owner/operator country:	US
Owner/operator telephone:	(718) 243-4581
Legal status:	Other
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No

NYCT - COURT SQUARE STA G LINE (Continued) **1001203144**

Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCT - COURT SQUARE STA G LINE
Classification: Not a generator, verified

Date form received by agency: 06/11/2001
Facility name: NYCT - COURT SQUARE STA G LINE
Classification: Small Quantity Generator

Date form received by agency: 09/22/1997
Facility name: NYCT - COURT SQUARE STA G LINE
Classification: Small Quantity Generator

Hazardous Waste Summary:
Waste code: D000
Waste name: Not Defined

Waste code: D008
Waste name: LEAD

Violation Status: No violations found

FINDS:

Registry ID: 110007908078

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000045062
Country: USA
Mailing Name: NYCTA
Mailing Contact: TOM ABDALLAH
Mailing Address: COURT SQUARE 28 20 JACKSON AVE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10004
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 646-252-3500

Document ID: NJA4049894
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported

NYCT - COURT SQUARE STA G LINE (Continued) **1001203144**

Generator Ship Date:	07/31/2002
Trans1 Recv Date:	07/31/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/31/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000045062
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	S8424
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00100
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2002

Document ID:	NJA3174065
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	07/31/2000
Trans1 Recv Date:	07/31/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/08/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000045062
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	S8424
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00600
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2000

Document ID:	NJA3292434
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	05/18/2001
Trans1 Recv Date:	05/18/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/23/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000045062
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported

NYCT - COURT SQUARE STA G LINE (Continued) **1001203144**

TSDF ID: S8424
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00300
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2001

Document ID: NJA3204930
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 06/21/2001
Trans1 Recv Date: 06/21/2001
Trans2 Recv Date: 06/27/2001
TSD Site Recv Date: 06/27/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000045062
Trans1 EPA ID: NJD002200046
Trans2 EPA ID: Not reported
TSDF ID: H10376
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00122
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00097
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2001

Document ID: NJA3266160
Manifest Status: Not reported
Trans1 State ID: NJD980772768
Trans2 State ID: Not reported
Generator Ship Date: 08/03/2001
Trans1 Recv Date: 08/03/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/03/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000045062
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSDF ID: 06993
Waste Code: D008 - LEAD 5.0 MG/L TCLP

NYCT - COURT SQUARE STA G LINE (Continued) **1001203144**

Quantity: 01000
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2001

Document ID: NYB9515961
Manifest Status: Not reported
Trans1 State ID: NY0000291823
Trans2 State ID: Not reported
Generator Ship Date: 09/28/2001
Trans1 Recv Date: 09/28/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/14/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000045062
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: 1A375
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00500
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2001

Document ID: NYG3192318
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 01/04/2002
Trans1 Recv Date: 01/04/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/08/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000045062
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: PD1010NY
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 00580
Units: K - Kilograms (2.2 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2002

NYCT - COURT SQUARE STA G LINE (Continued) **1001203144**

Document ID:	PAE8688374
Manifest Status:	Not reported
Trans1 State ID:	NJR000005124
Trans2 State ID:	Not reported
Generator Ship Date:	03/10/1998
Trans1 Recv Date:	03/10/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/08/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000045062
Trans1 EPA ID:	PAD085690592
Trans2 EPA ID:	Not reported
TSDF ID:	PAAH0492
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00020
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00
Year:	98

J85 **MTA NYCT 11TH STREET & JACKSON AVENUE SUBSTATION** **RCRA-SQG** **1000789619**
West **JACKSON AVE & 45TH AVE** **NYD987010808**
1/8-1/4 **QUEENS, NY 11101**
0.134 mi.
707 ft. **Site 3 of 6 in cluster J**

Relative:
Higher

Actual:
16 ft.

RCRA-SQG:

Date form received by agency:	08/13/2012
Facility name:	MTA NYCT 11TH STREET & JACKSON AVENUE SUBSTATION
Facility address:	JACKSON AVE & 45TH AVE QUEENS, NY 11101
EPA ID:	NYD987010808
Mailing address:	BROADWAY 5TH FL 503 NEW YORK, NY 10004
Contact:	GERALD LEZEAU
Contact address:	BROADWAY 5TH FL 503 NEW YORK, NY 10004
Contact country:	US
Contact telephone:	(646) 252-3535
Contact email:	GERALD.LEZEAU@NYCT.COM
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	MTA NYCT
Owner/operator address:	BROADWAY 5TH FL 503 NEW YORK, NY 10004
Owner/operator country:	US
Owner/operator telephone:	(646) 252-3535

MTA NYCT 11TH STREET & JACKSON AVENUE SUBSTATION (Continued) **1000789619**

Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: 03/01/1968
Owner/Op end date: Not reported

Owner/operator name: MTA NYCT
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: 03/01/1968
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2007
Facility name: MTA NYCT 11TH STREET & JACKSON AVENUE SUBSTATION
Site name: NYCTA - 11TH STREET SUBSTATION
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Facility name: MTA NYCT 11TH STREET & JACKSON AVENUE SUBSTATION
Site name: NYCTA - 11TH STREET SUBSTATION
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: MTA NYCT 11TH STREET & JACKSON AVENUE SUBSTATION
Site name: NYCTA - 11TH STREET SUBSTATION
Classification: Not a generator, verified

Date form received by agency: 08/03/1992
Facility name: MTA NYCT 11TH STREET & JACKSON AVENUE SUBSTATION
Site name: NYCTA - 11TH STREET SUBSTATION
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: D008
Waste name: LEAD

MTA NYCT 11TH STREET & JACKSON AVENUE SUBSTATION (Continued) **1000789619**

Violation Status: No violations found

J86 **MTA NYCT - VENT PLANT 6406-7** **RCRA-SQG** **1012211711**
West **JACKSON AVE & 45TH AVE** **NYR000171181**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.134 mi.
707 ft. **Site 4 of 6 in cluster J**

Relative:
Higher

Actual:
16 ft.

RCRA-SQG:

Date form received by agency:	12/29/2009
Facility name:	MTA NYCT - VENT PLANT 6406-7
Facility address:	JACKSON AVE & 45TH AVE LONG ISLAND CITY, NY 11101
EPA ID:	NYR000171181
Mailing address:	BROADWAY 5TH FLOOR 503 NEW YORK, NY 10004
Contact:	GERALD LEZEAU
Contact address:	BROADWAY 5TH FLOOR 503 NEW YORK, NY 10004
Contact country:	US
Contact telephone:	(646) 252-3535
Contact email:	GERALD.LEZEAU@NYCT.COM
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	MTA NYCT
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	03/01/1968
Owner/Op end date:	Not reported

Owner/operator name:	MTA NYCT
Owner/operator address:	BROADWAY 5TH FLOOR 503 NEW YORK, NY 10004
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	03/01/1968
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

MTA NYCT - VENT PLANT 6406-7 (Continued) **1012211711**

On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Hazardous Waste Summary:

Waste code:	D008
Waste name:	LEAD

Violation Status: No violations found

J87 **MTA NYCT 11TH STREET & JACKSON AVENUE SUBSTATION** **NY MANIFEST** **S113813823**
West **JACKSON AVE & 45TH AVE** **N/A**
1/8-1/4 **QUEENS, NY 11101**
0.134 mi.
707 ft. **Site 5 of 6 in cluster J**

Relative:
Higher

Actual:
16 ft.

NY MANIFEST:

EPA ID:	NYD987010808
Country:	USA
Mailing Name:	MTA NYCT 11TH STREET & JACKSON AVENUE SUBSTATION
Mailing Contact:	MTA NYCT 11TH STREET & JACKSON AVENUE SUBSTATION
Mailing Address:	JACKSON AVE & 45TH AVE
Mailing Address 2:	Not reported
Mailing City:	QUEENS
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	28-Jun-2013 00:00:00
Trans1 Recv Date:	28-Jun-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	28-Jun-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987010808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	3
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

MTA NYCT 11TH STREET & JACKSON AVENUE SUBSTATION (Continued) **S113813823**

Year:	2013
Manifest Tracking Num:	010407299JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

J88 **CON EDISON** **NY MANIFEST** **S113495500**
West **JACKSON AVE & COURT SQUARE** **N/A**
1/8-1/4 **QUEENS, NY 11101**
0.134 mi.
707 ft. **Site 6 of 6 in cluster J**

Relative:
Higher

Actual:
16 ft.

NY MANIFEST:

EPA ID:	NYP004292074
Country:	USA
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-3770

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07-Mar-2013 00:00:00
Trans1 Recv Date:	07-Mar-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08-Mar-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004292074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	500
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	002016593GBF

CON EDISON (Continued) **S113495500**

Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

I89 **KENT BRAGALINE INC** **RCRA NonGen / NLR** **1001493668**
NE **27-45 JACKSON AVE** **FINDS** **NYR000075630**
1/8-1/4 **LONG ISLAND CITY, NY** **NY MANIFEST**
0.135 mi.
714 ft. **Site 3 of 3 in cluster I**

Relative:
Higher

Actual:
16 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	KENT BRAGALINE INC
Facility address:	27-45 JACKSON AVE LONG ISLAND CITY, NY 11101
EPA ID:	NYR000075630
Mailing address:	JACKSON AVE LONG ISLAND CITY, NY 11101
Contact:	ALBERT TROY
Contact address:	JACKSON AVE LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	(718) 784-2012
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	KENT BRAGALINE INC
Owner/operator address:	27-45 JACKSON AVE LONG ISLAND CITY, NY 11101
Owner/operator country:	US
Owner/operator telephone:	(718) 784-2012
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	KENT BRAGALINE INC
Owner/operator address:	27-45 JACKSON AVE LONG ISLAND CITY, NY 11101
Owner/operator country:	US
Owner/operator telephone:	(718) 784-2012
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

KENT BRAGALINE INC (Continued) **1001493668**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: KENT BRAGALINE INC
Classification: Not a generator, verified

Date form received by agency: 08/19/1999
Facility name: KENT BRAGALINE INC
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004555810

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000075630
Country: USA
Mailing Name: KENT BRAGALINE
Mailing Contact: KENT BRAGALINE
Mailing Address: 27-45 JACKSON AVE
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-274-3339

KENT BRAGALINE INC (Continued) **1001493668**

Document ID:	NYG1002078
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	09/13/1999
Trans1 Recv Date:	09/13/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/14/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000075630
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	PD1011NY
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	99

N90 **2415 44TH ROAD LLC** **NY AST** **U003395749**
NNW **43-32 CRESCENT STREET** **NY HIST AST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.140 mi.
741 ft. **Site 1 of 13 in cluster N**

Relative:
Higher

Actual:
14 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-600777
Program Type:	PBS
UTM X:	589288.01636000001
UTM Y:	4511381.96435
Expiration Date:	2003/04/15
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	22754
Affiliation Type:	Facility Owner
Company Name:	2415 44 ROAD LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	C/O ROCKROSE 309 EAST 45TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 984-1741
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

2415 44TH ROAD LLC (Continued) **U003395749**

Site Id:	22754
Affiliation Type:	Mail Contact
Company Name:	2415 ROAD LLC
Contact Type:	Not reported
Contact Name:	SUPER FACILITY MANAGER
Address1:	C/O ROCKROSE
Address2:	309 EAST 45TH STREET
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 984-1741
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	22754
Affiliation Type:	On-Site Operator
Company Name:	2415 44TH ROAD LLC
Contact Type:	Not reported
Contact Name:	CHARLES SINGER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 937-1738
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	22754
Affiliation Type:	Emergency Contact
Company Name:	2415 44 ROAD LLC
Contact Type:	Not reported
Contact Name:	COASTAL COMBUSTION CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 475-4263
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank Id:	43713
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

2415 44TH ROAD LLC (Continued) **U003395749**

Equipment Records:

F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	#2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number:	2-600777
SWIS Code:	6301
Operator:	CHARLES SINGER
Facility Phone:	(718) 937-1738
Facility Addr2:	43032 CRESCENT STREET
Facility Type:	APARTMENT BUILDING
Emergency:	COASTAL COMBUSTION CORP
Emergency Tel:	(212) 475-4263
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	2415 44 ROAD LLC
Owner Address:	C/O ROCKROSE 309 EAST 45TH STREET
Owner City,St,Zip:	NEW YORK, NY 10017
Federal ID:	Not reported
Owner Tel:	(212) 984-1741
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	SUPER FACILITY MANAGER
Mailing Name:	2415 ROAD LLC
Mailing Address:	C/O ROCKROSE
Mailing Address 2:	309 EAST 45TH STREET
Mailing City,St,Zip:	NEW YORK, NY 10017
Mailing Telephone:	(212) 984-1741
Owner Mark:	Second Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

2415 44TH ROAD LLC (Continued) **U003395749**

Certification Flag:	False
Certification Date:	04/21/1998
Expiration:	04/15/2003
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	2500
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	2500
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	0
Tank External:	00
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	00
Tank Containment:	Diking
Leak Detection:	00
Overfill Protection:	04
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

N91 **ROCKROSE CONSTRUCTION CORP** **NY MANIFEST** **S108981768**
NNW **4329 CRESCENT STREET** **NY Spills** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.141 mi.
743 ft. **Site 2 of 13 in cluster N**

Relative:
Higher

Actual:
14 ft.

NY MANIFEST:

EPA ID:	NYR000153924
Country:	USA
Mailing Name:	ROCKROSE CONSTRUCTION CORP
Mailing Contact:	ROCKROSE CONSTRUCTION CORP
Mailing Address:	290 PARK AVE SOUTH
Mailing Address 2:	14TH FL
Mailing City:	NEW YORK

ROCKROSE CONSTRUCTION CORP (Continued) **S108981768**

Mailing State: NY
Mailing Zip: 10010
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-984-1705

NY MANIFEST:
No Manifest Records Available

SPILLS:
Facility ID: 0710509
DER Facility ID: 341415
Facility Type: ER
Site ID: 391813
DEC Region: 2
Spill Date: 1/4/2008
Spill Number/Closed Date: 0710509 / 11/16/2009
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 4101
Investigator: rvketani
Referred To: Not reported
Reported to Dept: 1/4/2008
CID: 444
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1/4/2008
Spill Record Last Update: 11/16/2009
Spiller Name: ANDREW RUDKO
Spiller Company: CONSTRUCTION SITE
Spiller Address: 4329 CRESCENT STREET
Spiller City,St,Zip: LONG ISLAND CITY, NY
Spiller Company: 999
Contact Name: ANDREW RUDKO
Contact Phone: (646) 388-9526
DEC Memo: I spoke with Andrew. The tank has been reoved and cont. soil has been stockpiled. This soil needs to be removed due to space limitations. He feels that they are not able to find clean endpoints. A gepprobe will be out on Fri 1/ 11/ 07- 1/9/08 - Raphael Ketani. An abandoned gasoline tank was discovered and contaminated soil beneath it on 1/4/08. The contact is Andrew Rudko of AKRF, Inc. (646) 388-9526.I spoke to Mr. Rudko about the site. The site is a small triangular area. He said that it used to be a car repair replace with one 550 gal. tank and one pump. He said the tank was abandoned in place with concrete. The great majority of the soil has been excavated, but the contractor is waiting to get a hauler for the gasoline contaminated soil. The site will be a temporary parking lot for the building and parking lot across the street. Groundwater is at about 14 feet - he

ROCKROSE CONSTRUCTION CORP (Continued) **S108981768**

has drilled nearby at another site and hit water there at that depth. I told Mr. Rudko that additional borings will be needed to see whether the contamination had migrated under the streets. He said he will do borings to the edge of the property, and if contamination is found, then he will get the permits and do borings further out.2/7/08 - Raphael Ketani. I tried to contact Mr. Rudko, but could only leave a message.Mr. Rudko returned my call. He said that they had removed the gas tank and found lots of contamination. Initially, they excavated 9 truck loads of soil and shipped it out. Then, on 2/5/08, they excavated more soil until the site was jammed up with excavated soil. This was also shipped out. Mr. Rudko feels that the contamination extends all the way to the Hunter Street sidewalk and maybe under it. I told him that he needs to delineate the extent of the contamination. Mr. Rudko said that they will use ORC to remediate any soil that can not be removed. I told him that DEC wants all of the contaminated soil either removed or treated. 2/19/08 - Raphael Ketani. I had tried to make an unannounced site visit last thursday, but was unsuccessful. I could not find the site. I called up Mr. Rudko and he told me the site is at the intersection of Crescent Street, Hunter Street, and 44th Road. I will make another attempt at a site visit.I found the site. It consisted of a big water filled pit and a pile of slightly odoress artificial fill material. I met Mark Accetturi, Environmental Specialist of AKRF (646) 388-9521, at the site. There was no sheen on the water. Mr. Accetturi told me that the pit had been dry until the recent rains. The water level was about 10 feet below grade. I told him that AKRF should get someone to suck out the water. He said that this will be done in the near future. There was a large pile of artificial fill (soil mixed with other material) with slight odor of gasoline. Mr. Accetturi told me that they had taken out the one tank from about the middle of the hole and two lifts from the Citicorp (southwest) side of the hole. A black pipe with a metal clamp was sticking out of the sidewall at the southwest side. It was not apparent where the pipe went to. The area around the hole had concrete pavement. I was told by the excavator operator that 12 trucks were scheduled to come today to take away the soil pile. I took 5 pictures. I noticed a 4 story building across the street with commercial space at the street level and residences above. A commercial building abutted the site property. There was nothing much else to see. So I left.3/12/08 - Raphael Ketani. Today I received a progress report and remedial action plan dated 3/11/08 from Mr. Rudko, Senior Vice President of AKRF. The report and plan stated that a 550 gal. gasoline tank was discovered on site which was resting on soil. The soil beneath the tank was contaminated, though the tank appeared to be intact. Contaminated soil was removed from the site. Four borings were advanced to the groundwater to delineate the extent of soil contamination. Two sites of contamination were discovered. One to the east and extending from the tank and another separate one to the southwest (maybe related to a broken sewer pipe). Contaminated groundwater was pumped out and the excavation was backfilled after 2/20/08. AKRF will install 4 wells in order to monitor the groundwater conditions. Water and soil treatment will be proposed if the contamination persists.The analytical results were as follows:groundwater; SB-1=no VOCs, few low SVOC hits SB-2=VOC hits to 1394 ppb total xylenes, no SVOCs SB-3=no VOCs and no SVOCs SB-4=VOC hits to 2370 ppb total xylenes, no SVOCs SB-5=no VOCs and no SVOCssoil; EP-1=few low VOCs, combustion SVOCs in thousands of ppb EP-2=no VOCs, combustion SVOCs in high thousands of ppb to 713,300

ROCKROSE CONSTRUCTION CORP (Continued) **S108981768**

ppb EP-4=1 significant VOC, naphthalene 6000 ppb, high SVOCs in high thousands to 62000 ppb EP-1S=no VOCs, no SVOCs WC-4=VOCs in tens of thousands ppb to 150,000 ppb with total xylenes at 640,000 ppb, SVOC hits but none significant EP-1B=many very low VOCs, no SVOCs EP-1N=many very low VOCs, no SVOCs EP-1W=many very low VOCs, no SVOCs EP-1E=11 VOCs to 83,100 ppb, 3600 ppb naphthalene, combustion SVOCs, but not significant I spoke to Mr. Rudko. He said that they are not sure how far the contaminated soil extends. So they are not done excavating. If it extends off site, then they will consider using ORC or another treatment solution to remediate the contamination. He said that he also needs to determine the direction of groundwater flow. He said that bedrock dips to the south and so he thinks that's the direction of groundwater flow, but he'll see. 4/1/08 - Raphael Ketani. I spoke to Mr. Rudko (646) 388-9526. He said that nothing is happening right now at the site. He is trying to line up a driller to install borings on all 3 sides of the site. He will take soil and groundwater samples. He will keep me posted.8/19/08 - Raphael Ketani. I tried to reach Mr. Rudko, but could only leave a message regarding groundwater and soil sampling, and delineation of the extent of the contamination.9/3/08 - Raphael Ketani. I tried to reach Mr. Rudko, but could only leave a message regarding groundwater and soil sampling, and delineation of the extent of the contamination.As there has been no contact with Mr. Rudko in 5 months and he is not reachable, I sent a letter to Ivan Moskowitz, Esq. at Swidler Berlin LLP, 405 Lexington Avenue, NY, 10174. He is the lawyer representing the owners of the site, 4329 Crescent LLC, 399 Park Avenue, NY, 10022-4614. The block and lot are 4343 and 0001. The main address is 4319 Crescent Street.9/11/08 - Raphael Ketani. The letter to 4329 Crescent LLC, c/o Swidler Berlin LLP came back NOT DELIVERABLE AS ADDRESSED. 9/15/08 - Raphael Ketani. I tried to reach Mr. Rudko, but could only leave a message regarding groundwater and soil sampling, and delineation of the extent of the contamination.Also, I sent the 9/3/08 letter to 4329 Crescent LLC at 399 Park Avenue, and to Swidler Berlin LLP the corrected zip code of 10017. 9/22/08 - Raphael Ketani. The letter to Swidler Berlin LLP came back with a Post Office indicating Not Deliverable As Addressed. I called up a phone number for Swidler Berlin (212) 891-9536 and was told that Swidler Berlin no longer exists. One of their offices merged with Bingam McCutchen (the same phone number as above). She said that Mr. Moskowitz works for Bingam McCutchen and that his direct number is (212) 705-7537.I called Mr. Moskowitz, but could only leave a message regarding the site. Mr. Moskowitz called me back. He said that he still represent 4329 Crescent LLC. He will contact them to see why there is no progress with the investigation.9/25/08 - Raphael Ketani. Patricia Dunphy of Rockrose Development Corp. (212) 984-1795 called earlier this week regarding the site. I tried to return her call, but could only leave a voice mail. Later this morning, I received a call from Steven Eisner (212) 984-1705 of Rockrose. He said that the reason the sidewalk wells weren't installed is because they are doing foundation dewatering across the street to the west at 3000 Crescent Street. The building that was there was knocked down 3 weeks ago. He said that once the foundation is put in, then they will install the wells. I asked him whether they had found any contaminated water. He said no. He said he will let me know when the foundation dewatering is done in 6 to 8 weeks. 10/27/08 - Raphael Ketani. I tried to contact Mr. Eisner regarding the dewatering of the neighboring site, but could only leave a message.Mr. Eisner called me back. He said that the

ROCKROSE CONSTRUCTION CORP (Continued) **S108981768**

foundation wont be installed until February 2009. Then they will install 4 wells.2/13/09 - Raphael Ketani. I spoke to Mr. Eisner. He said that the foundation construction and dewatering is still taking place. He said that the wells will probably be installed at the end of February and a report will be submitted to DEC by March 13. I said that would be alright. Mr. Eisner added that Mr. Rudko is no longer with AKRF and the case is now being handled by Kate Bruner of AKRF (646) 388-9525. 2/17/09 - Raphael Ketani. Kate Brunner called me to say that she will give me an update regarding the project at the end of February.2/26/09 - Raphael Ketani. Ms. Brunner called. She said that the dewatering for the foundation should end in a week. The well installation will take place in mid-March with a 4" geoprobe.3/16/09 - Raphael Ketani. Mr. Eisner (212) 984-1705 called to say that they are still working on the foundation for the building across the street. They expect to finish in May. Once they're finished, then they will install the wells. 4/23/09 - Raphael Ketani. I talked to Ms. Brunner (212) 696-0670. She said that the construction contractor had finished dewatering the site a couple of weeks ago. She added that applications had been submitted to the City for sidewalk permits. There is a tentative date of 5/4/09 for starting the boring work.7/13/09 - Raphael Ketani. I spoke to Ms. Brunner. She said that she had received the soil and groundwater analytical report. However, she was out. So the review couldn't take place until she had a chance to look at it. She said that the results looked very good. Right now, the report is undergoing internal review. Once AKRF is done with it, then the report will be forwarded to DEC. I told her to send the report as soon as possible.9/11/09 - Raphael Ketani. I left a message for Ms. Brunner that the DEC never received the groundwater analytical report.9/14/09 - Raphael Ketani. Ms. Brunner (212) 696-0670 called me today. She said that the groundwater survey didn't take place until July 2009 due to access problems. The developer they were working with as a client has split into two entities. One entity is responsible for pursuing the environmental evaluation and reporting. This is the client and this entity is still reviewing the environmental report. However, Ms. Brunner said that she expects to send the DEC the environmental report in two weeks. She added that the analyticals were all non-detect.9/25/09 - Raphael Ketani. Today I received the Supplemental Subsurface Investigation dated 9/24/09 and submitted by AKRF. I began my review. 9/29/09 - Raphael Ketani. I finished my review. They recovered soil samples from only 2 of the 4 borings that were attempted on 5/11/09. They state that, for technical reasons, they could not recover soil samples from MW-1 and MW-3, but they don't explain what this means. Soil samples were submitted for MW-2 and MW-4. MW-2 is at the eastern corner of the site and MW-4 is at the southwest corner of the site. Groundwater flow is to the east. The soil samples were completely non-detect for VOCs. There were a number of SVOC hits, but they were all below TAGM, except for some benzo series hits which were just slightly above TAGM. Groundwater samples for the four wells were entirely non-detect for VOCs. Samples from wells MW-1 to MW-3 were completely non-detect for SVOCs. The groundwater sample from MW-4 had a number of SVOC hits, but they were below TAGM, except for five combustion product hits (mostly the benzo series) which were slightly above TAGM.From re-reviewing the 3/11/08 investigation report, it appears that there are a lot of ashes and cinders at the site. This was determined by the presence of high concentrations of the combustion product SVOC analytes in soil samples from various locations. From the end point

ROCKROSE CONSTRUCTION CORP (Continued) **S108981768**

sample results for EP-1N, EP-1S, EP-1W, and EP-1B, it appears that the contaminated soil was removed. However, the results for EP-1E showed several SVOC hits to 4300ppb, including naphthalene and 2-methylnaphthalene, and four other low level SVOCs, but all of the other SVOCs were non-detect. The VOCs were all non-detect, also. It seems as if they did a reasonable job of digging out the contamination.Though questions remain regarding the 03/11/08 report and the 9/24/09 report:1) the 3/11/08 report lists boring locations SB-1, SB-2, and SB-4, but the data package shows EP-1, EP-2 , and EP-4. Are these the same borings? Also, what happened with the soil sample for SB-3?2) why were no borings conducted between W SB-1 and MW-2?3) what does the number "434" mean on Figure 2 from the 3/11/08 report?4) there is no explanation as to why they couldn't recover soil samples from MW-1 and MW-3, except to say that "for technical reasons" they couldn't do it. What are the technical reasons?5) a number of VOCs are listed as above TAGM on Figure 3 in the 9/24/09 report for the soil sample from EP-1E. However, these analytes are not in the analytical data report for the end point samples. Where did this information come from and how much above TAGM are the hits?Aside from answering these questions, the DEC requires that they perform one more soil borings. One halfway between W SB-1 and MW-2. 10/9/09 - Raphael Ketani. Ms. Brunner called me back. She answered the five questions:1) SB-1, SB-2, and SB-4 are EP-1, EP-2, and EP-4. There was some confusion regarding the numbering of the samples due to the previous use of a different numbering system. 2) we agreed to have one more soil boring performed halfway between W SB-1 and MW-2 just to see what the contamination is, if any3) number "434" is the block number from the block and lot tax maps4) soil samples couldn't be recovered because they kept hitting refusal. The geoprobe wasn't strong enough to apply enough torque to get a sample and the sampling tool was thin so that a stronger machine would have broken the tool. They stepped out from these locations and sampled elsewhere with a heavier rig.5) the analytes for EP-1E come from the 2008 report. Ms. Brunner just wanted to show what had been detected PRIOR to excavation of the site. 10/15/09 - Raphael Ketani. I received an e-mail today from Ms. Brunner regarding the location of the additional boring that DEC had requested (see E-docs). I sent a response e-mail in which I approved the location.11/5/09 - Raphael Ketani. I tried to contact Ms. Brunner (212) 696-0670, but could only leave a voice mail.11/6/09 - Raphael Ketani. I received the following e-mail from Ms. Brunner:The soil boring was completed at 43-29 Crescent Street as planned. We got the preliminary VOC and SVOC data back and all concentrations are less than TAGM RSCOs so we'll be requesting closure. We are preparing a revised report for submittal to DEC and we are still on-track to get you the report in mid-November.11/16/09 - Raphael Ketani. Today I received the 11/12/09 Supplemental Subsurface Investigation report from Ms. Brunner at AKRF. I review the report for the soil analyses for SB-5. The results were completely non-detect for VOCs and SVOCs. Based upon the soil and groundwater analytical results in the case file, I have determined that there are minimal impacts to the environment and to people. Therefore, I am closing the spill case.

Remarks: FOUND BURIED GASOLINE TANK IN GROUND AND FOUND CONTAMINATED SOIL

Material:

Site ID: 391813
Operable Unit ID: 1148847
Operable Unit: 01

ROCKROSE CONSTRUCTION CORP (Continued) **S108981768**

Material ID: 2139342
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

N92 **EDR US Hist Auto Stat** **1015493785**
NNW **4329 CRESCENT ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.141 mi.
743 ft. **Site 3 of 13 in cluster N**

Relative:
Higher

Actual:
14 ft.

EDR Historical Auto Stations:

Name: QUALITY AUTO REPAIR
Year: 1999
Address: 4329 CRESCENT ST

Name: QUALITY AUTO REPAIR
Year: 2000
Address: 4329 CRESCENT ST

Name: QUALITY AUTO REPAIR
Year: 2001
Address: 4329 CRESCENT ST

Name: QUALITY AUTO REPAIR
Year: 2004
Address: 4329 CRESCENT ST

Name: QUALITY AUTO REPAIR
Year: 2005
Address: 4329 CRESCENT ST

Name: QUALITY AUTO REPAIR
Year: 2006
Address: 4329 CRESCENT ST

Name: QUALITY AUTO REPAIR
Year: 2007
Address: 4329 CRESCENT ST

Name: QUALITY AUTO REPAIR
Year: 2012
Address: 4329 CRESCENT ST

N93 **ROCKROSE CONSTRUCTION CORP** **RCRA-LQG** **1010566745**
NNW **43-29 CRESCENT ST** **NYR000153924**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.142 mi.
750 ft. **Site 4 of 13 in cluster N**

Relative:
Higher

Actual:
14 ft.

RCRA-LQG:

Date form received by agency:	01/24/2008
Facility name:	ROCKROSE CONSTRUCTION CORP
Facility address:	43-29 CRESCENT ST LONG ISLAND CITY, NY 11101
EPA ID:	NYR000153924
Mailing address:	PARK AVE SOUTH 14TH FLOOR NEW YORK, NY 10010
Contact:	STEPHEN A EISNER
Contact address:	PARK AVE SOUTH 14TH FLOOR NEW YORK, NY 10010
Contact country:	US
Contact telephone:	(212) 984-1705
Contact email:	STEVEE@ROCKROSE.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	ROCKROSE CONSTRUCTION CORP
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	05/31/2007
Owner/Op end date:	Not reported
Owner/operator name:	43-29 CRESCENT LLC
Owner/operator address:	PARK AVE SOUTH 14TH FLOOR NEW YORK, NY 10010
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	11/11/2006
Owner/Op end date:	Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

ROCKROSE CONSTRUCTION CORP (Continued) **1010566745**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/23/2008
Facility name: ROCKROSE CONSTRUCTION CORP
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: D008
Waste name: LEAD

Violation Status: No violations found

N94 **KATT CORPORATION** **NY AST** **A100294658**
NNW **43-29 CRESCENT STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.142 mi.
750 ft. **Site 5 of 13 in cluster N**

Relative:
Higher

Actual:
14 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-609251
Program Type: PBS
UTM X: 589287.45632
UTM Y: 4511386.3985700002
Expiration Date: 2008/09/18
Site Type: Other

Affiliation Records:
Site Id: 31096
Affiliation Type: Facility Owner
Company Name: KATT CORPORATION
Contact Type: Not reported
Contact Name: Not reported
Address1: 43-29 CRESCENT ST.
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 937-4573
EMail: Not reported
Fax Number: Not reported

KATT CORPORATION (Continued) **A100294658**

Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 31096
Affiliation Type: Mail Contact
Company Name: KATT CORPORATION
Contact Type: Not reported
Contact Name: GAMALIEL RUIZ
Address1: 43-29 CRESCENT STREET
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 937-4573
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 31096
Affiliation Type: On-Site Operator
Company Name: KATT CORPORATION
Contact Type: Not reported
Contact Name: GAMALIEL RUIZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 937-4573
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 31096
Affiliation Type: Emergency Contact
Company Name: KATT CORPORATION
Contact Type: Not reported
Contact Name: GAMALIEL RUIZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 937-4573
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001

KATT CORPORATION (Continued) **A100294658**

Tank Id: 66943
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
G10 - Tank Secondary Containment - Impervious Underlayment
D00 - Pipe Type - No Piping
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location: 1
Tank Type: Stainless Steel Alloy
Tank Status: In Service
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 55
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Waste Oil/Used Oil

Tank Number: 002
Tank Id: 66944
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

I00 - Overfill - None
A00 - Tank Internal Protection - None
G10 - Tank Secondary Containment - Impervious Underlayment
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
B00 - Tank External Protection - None

Tank Location: 1
Tank Type: Stainless Steel Alloy
Tank Status: In Service
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 55
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True

KATT CORPORATION (Continued) **A100294658**

Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Waste Oil/Used Oil

O95 **TWO COURT SQUARE** **NY AST** **A100350441**
WNW **23-21 44 DRIVE** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.143 mi.
754 ft. **Site 1 of 7 in cluster O**

Relative:
Higher

Actual:
16 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-611356
Program Type: PBS
UTM X: 589147.96811000002
UTM Y: 4511261.5783299999
Expiration Date: 2015/04/01
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 435241
Affiliation Type: Facility Owner
Company Name: PERRENNELLY GREEN INC
Contact Type: VICE PRESIDENT
Contact Name: THOMAS A. BARRETT
Address1: 23-21 44 DRIVE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (347) 648-0195
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 6/8/2010

Site Id: 435241
Affiliation Type: Mail Contact
Company Name: CUSHMAN & WAKEFIELD, INC.
Contact Type: Not reported
Contact Name: KEVIN GAVIN
Address1: 23-21 44 DRIVE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (347) 648-0110
EMail: KEVIN.GAVIN@CITI.COM
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 6/8/2010

Site Id: 435241
Affiliation Type: On-Site Operator

TWO COURT SQUARE (Continued) **A100350441**

Company Name:	TWO COURT SQ
Contact Type:	Not reported
Contact Name:	DOMENICO VEZZA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 648-0100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	5/25/2010

Site Id:	435241
Affiliation Type:	Emergency Contact
Company Name:	PERRENNELLY GREEN INC
Contact Type:	Not reported
Contact Name:	KEVIN GAVIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 648-0100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	5/25/2010

Tank Info:

Tank Number:	001
Tank Id:	234565
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
A01 - Tank Internal Protection - Epoxy Liner
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
E12 - Piping Secondary Containment - Double-Wall (Aboveground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service

TWO COURT SQUARE (Continued) **A100350441**

Pipe Model:	Not reported
Install Date:	01/01/2006
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	05/25/2010
Material Name:	#2 Fuel Oil (On-Site Consumption)

Tank Number:	002
Tank Id:	234566
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
A01 - Tank Internal Protection - Epoxy Liner
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/2006
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	05/25/2010
Material Name:	#2 Fuel Oil (On-Site Consumption)

N96 **EDR US Hist Cleaners** **1015060699**
NNW **4320 CRESCENT ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.146 mi.
769 ft. **Site 6 of 13 in cluster N**

Relative:
Higher

Actual:
14 ft.

EDR Historical Cleaners:

Name:	HUANG & PAUL LAUNDROMANT INC
Year:	2003
Address:	4320 CRESCENT ST

(Continued) **1015060699**

Name: HUANG & PAUL LAUNDROMAT INC
Year: 2005
Address: 4320 CRESCENT ST

Name: HUANG & PAUL LAUNDROMAT INC
Year: 2007
Address: 4320 CRESCENT ST

Name: HUANG & PAUL LAUNDROMAT INC
Year: 2008
Address: 4320 CRESCENT ST

Name: HUANG & PAUL LAUNDROMAT INC
Year: 2009
Address: 4320 CRESCENT ST

N97 **EDR US Hist Auto Stat** **1015493080**
NNW **4315 CRESCENT ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.147 mi.
775 ft. **Site 7 of 13 in cluster N**

Relative:
Higher

Actual:
14 ft.

EDR Historical Auto Stations:
Name: EURO SPORT COLLISION REPAIR INC
Year: 2002
Address: 4315 CRESCENT ST

Name: EURO SPORT COLLISION REPAIR
Year: 2003
Address: 4315 CRESCENT ST

Name: EURO SPORT COLLISION REPAIR
Year: 2004
Address: 4315 CRESCENT ST

N98 **AEROSOURCE INC** **RCRA NonGen / NLR** **1000553955**
NNW **25-19 43RD AVE** **FINDS** **NYD986963932**
1/8-1/4 **LONG ISLAND CITY, NY** **NY MANIFEST**
0.151 mi.
797 ft. **Site 8 of 13 in cluster N**

Relative:
Higher

Actual:
14 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: AEROSOURCE INC
Facility address: 25-19 43RD AVE
LONG ISLAND CITY, NY 111014208
EPA ID: NYD986963932
Mailing address: 43RD AVE
LONG ISLAND CITY, NY 11101
Contact: Not reported
Contact address: 43RD AVE
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02

AEROSOURCE INC (Continued) **1000553955**

Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: AEROSOURCE INC
Owner/operator address: UNKNOWN
UNKNOWN, NY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: AEROSOURCE INC
Owner/operator address: UNKNOWN
UNKNOWN, NY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: AEROSOURCE INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: AEROSOURCE INC
Classification: Not a generator, verified

Date form received by agency: 07/22/1991
Facility name: AEROSOURCE INC
Classification: Small Quantity Generator

Violation Status: No violations found

AEROSOURCE INC (Continued) **1000553955**

Evaluation Action Summary:
Evaluation date: 05/02/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004473258

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD986963932
Country: USA
Mailing Name: AEROSOURCE INCORPORATION
Mailing Contact: MITCH SHULMAN
Mailing Address: 11 CAMPUS DR
Mailing Address 2: Not reported
Mailing City: SOMERSET
Mailing State: NJ
Mailing Zip: 08873
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-392-5800

Document ID: NJA1206298
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 910913
Trans1 Recv Date: 910913
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910917
Part A Recv Date: 911007
Part B Recv Date: 911004
Generator EPA ID: NYD986963932
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00212
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91

AEROSOURCE INC (Continued) **1000553955**

Document ID:	NJA1214952
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPS869
Trans2 State ID:	Not reported
Generator Ship Date:	910830
Trans1 Recv Date:	910830
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910906
Part A Recv Date:	910912
Part B Recv Date:	910926
Generator EPA ID:	NYD986963932
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00389
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	91

Document ID:	NJA1199083
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS869
Trans2 State ID:	Not reported
Generator Ship Date:	910802
Trans1 Recv Date:	910802
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910807
Part A Recv Date:	910815
Part B Recv Date:	910826
Generator EPA ID:	NYD986963932
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	02334
Units:	P - Pounds
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	91

N99 **4308 CRESCENT STREET** **NY AST** **A100366141**
NNW **4308 CRESCENT STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.151 mi.
797 ft. **Site 9 of 13 in cluster N**

Relative:
Higher

Actual:
14 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-611954

4308 CRESCENT STREET (Continued) **A100366141**

Program Type: PBS
UTM X: 589050.33444999997
UTM Y: 4510380.42093
Expiration Date: 2017/10/23
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 477961
Affiliation Type: Facility Owner
Company Name: 4300 CRESCENT LLC
Contact Type: VICE PRESIDENT
Contact Name: CHRISTOPHER S. LA PUNZINA
Address1: 666 FIFTH AVENUE, 5TH FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10103
Country Code: 001
Phone: (212) 847-3700
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 1/17/2013

Site Id: 477961
Affiliation Type: Mail Contact
Company Name: ROCKROSE DEVELOPMENT CORPORATION
Contact Type: Not reported
Contact Name: JOSEPH FLANAGAN
Address1: 666 FIFTH AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10103
Country Code: 001
Phone: (212) 847-3780
EMail: JOSEPH.FLANAGAN@ROCKROSE.COM
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 1/17/2013

Site Id: 477961
Affiliation Type: On-Site Operator
Company Name: 4308 CRESCENT STREET
Contact Type: Not reported
Contact Name: KEVIN FORDE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 628-1373
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 1/17/2013

4308 CRESCENT STREET (Continued) **A100366141**

Site Id:	477961
Affiliation Type:	Emergency Contact
Company Name:	4300 CRESCENT LLC
Contact Type:	Not reported
Contact Name:	JOSEPH FLANAGAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 210-1717
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	1/17/2013

Tank Info:

Tank Number:	001
Tank Id:	246976
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J01 - Dispenser - Pressurized Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
I02 - Overfill - High Level Alarm

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/23/2012
Capacity Gallons:	20000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMMOLOUG
Last Modified:	01/17/2013
Material Name:	#2 Fuel Oil (On-Site Consumption)

N100 **EDR US Hist Auto Stat** **1015492430**
NNW **4305 CRESCENT ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.151 mi.
799 ft. **Site 10 of 13 in cluster N**

Relative:
Higher

Actual:
14 ft.

EDR Historical Auto Stations:

Name:	ANTONS AUTO REPR
Year:	2000
Address:	4305 CRESCENT ST
Name:	ANTONS AUTO REPAIR
Year:	2001
Address:	4305 CRESCENT ST
Name:	ANTONS AUTO REPAIR
Year:	2002
Address:	4305 CRESCENT ST
Name:	ANTONS AUTO REPAIR
Year:	2003
Address:	4305 CRESCENT ST
Name:	ANTONS AUTO REPAIR
Year:	2004
Address:	4305 CRESCENT ST
Name:	ANTONS AUTO REPAIR
Year:	2005
Address:	4305 CRESCENT ST
Name:	ANTONS AUTO REPAIR
Year:	2006
Address:	4305 CRESCENT ST
Name:	ANTONS AUTO REPAIR
Year:	2007
Address:	4305 CRESCENT ST
Name:	ANTONS AUTO REPAIR
Year:	2008
Address:	4305 CRESCENT ST
Name:	ANTONS AUTO REPAIR
Year:	2009
Address:	4305 CRESCENT ST
Name:	ANTONS AUTO REPAIR
Year:	2010
Address:	4305 CRESCENT ST
Name:	ANTONS AUTOMOBILE REPAIR
Year:	2011
Address:	4305 CRESCENT ST
Name:	ANTONS AUTO REPR
Year:	2012
Address:	4305 CRESCENT ST

N101 **FEDERAL PACIFIC ELECTRIC CO** **RCRA NonGen / NLR** **1000212443**
NNW **4300 CRESCENT ST** **FINDS** **NYD001268325**
1/8-1/4 **LONG ISLAND CITY, NY** **NY MANIFEST**
0.155 mi.
816 ft. **Site 11 of 13 in cluster N**

Relative:
Higher

Actual:
14 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	FEDERAL PACIFIC ELECTRIC CO
Facility address:	4300 CRESCENT ST LONG ISLAND CITY, NY 111014207
EPA ID:	NYD001268325
Mailing address:	CRESCENT ST LONG ISLAND CITY, NY 11101
Contact:	Not reported
Contact address:	CRESCENT ST LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

FEDERAL PACIFIC ELECTRIC CO (Continued) **1000212443**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: FEDERAL PACIFIC ELECTRIC CO
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: FEDERAL PACIFIC ELECTRIC CO
Classification: Not a generator, verified

Date form received by agency: 09/26/1985
Facility name: FEDERAL PACIFIC ELECTRIC CO
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 01/11/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110001582537

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD001268325
Country: USA
Mailing Name: AMERICAN PROPERTIES CORPORATION
Mailing Contact: C/O TINICUM INVESTORS
Mailing Address: 85 2ND AVE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10017
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-786-7300

Document ID: NJA0369424

FEDERAL PACIFIC ELECTRIC CO (Continued) **1000212443**

Manifest Status:	Completed copy
Trans1 State ID:	NJSWAS300
Trans2 State ID:	Not reported
Generator Ship Date:	871223
Trans1 Recv Date:	871223
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	871223
Part A Recv Date:	871230
Part B Recv Date:	880105
Generator EPA ID:	NYD001268325
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00550
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	010
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	87

Document ID:	NJA0403482
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJSWAS300
Trans2 State ID:	Not reported
Generator Ship Date:	880414
Trans1 Recv Date:	880414
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880414
Part A Recv Date:	880601
Part B Recv Date:	880420
Generator EPA ID:	NYD001268325
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported

FEDERAL PACIFIC ELECTRIC CO (Continued) **1000212443**

TSDF ID:	NJD991291105
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00520
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	88

Document ID:	NJA0534650
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJSWAS300
Trans2 State ID:	Not reported
Generator Ship Date:	881104
Trans1 Recv Date:	881104
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	881104
Part A Recv Date:	881122
Part B Recv Date:	881220
Generator EPA ID:	NYD001268325
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	88

Document ID:	NJA0334940
Manifest Status:	Completed copy
Trans1 State ID:	NJSWAS300
Trans2 State ID:	Not reported
Generator Ship Date:	870918
Trans1 Recv Date:	870918
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870918
Part A Recv Date:	871006
Part B Recv Date:	870925
Generator EPA ID:	NYD001268325
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	02500
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	87

FEDERAL PACIFIC ELECTRIC CO (Continued) **1000212443**

Document ID:	NYA3544885
Manifest Status:	Completed copy
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	870603
Trans1 Recv Date:	870603
Trans2 Recv Date:	870608
TSD Site Recv Date:	870609
Part A Recv Date:	870609
Part B Recv Date:	870615
Generator EPA ID:	NYD001268325
Trans1 EPA ID:	DCD981735244
Trans2 EPA ID:	DCD981735244
TSDF ID:	OHD083377010
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00020
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	132
Year:	87

Document ID:	NJA0403467
Manifest Status:	Completed copy
Trans1 State ID:	NJSWAS300
Trans2 State ID:	Not reported
Generator Ship Date:	880411
Trans1 Recv Date:	880411
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880411
Part A Recv Date:	880418
Part B Recv Date:	880419
Generator EPA ID:	NYD001268325
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00275
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00495
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	009
Container Type:	DM - Metal drums, barrels

FEDERAL PACIFIC ELECTRIC CO (Continued) **1000212443**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	88

N102 **43-00 CRESCENT ST.** **NY UST** **U001840988**
NNW **43-00 CRESCENT ST** **NY HIST UST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.155 mi.
818 ft. **Site 12 of 13 in cluster N**

Relative:
Higher

Actual:
14 ft.

UST:

Id/Status:	2-480606 / Unregulated
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589296.38959999999
UTM Y:	4511415.8164299997
Site Type:	Unknown

Affiliation Records:

Site Id:	21452
Affiliation Type:	Mail Contact
Company Name:	43-00 CRESCENT ST REALTY CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	309 E. 45 STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 697-4422
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

43-00 CRESCENT ST. (Continued) **U001840988**

Site Id:	21452
Affiliation Type:	Facility Owner
Company Name:	43-00 CRESCENT ST REALTY CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	309 E. 45 STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 697-4422
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	21452
Affiliation Type:	On-Site Operator
Company Name:	43-00 CRESCENT ST.
Contact Type:	Not reported
Contact Name:	ROCKROSE CONSTRUCTION CORP.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 697-4422
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	21452
Affiliation Type:	Emergency Contact
Company Name:	43-00 CRESCENT ST REALTY CORP.
Contact Type:	Not reported
Contact Name:	DAN HARDER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 628-6504
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank ID:	41093
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91

43-00 CRESCENT ST. (Continued) **U001840988**

Capacity Gallons:	6000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None

Tank Number:	002
Tank ID:	41094
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	5000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None

43-00 CRESCENT ST. (Continued) **U001840988**

Tank Number:	003
Tank ID:	41095
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	1000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number:	004
Tank ID:	41096
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	5000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

B00 - Tank External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
I00 - Overfill - None
H00 - Tank Leak Detection - None

43-00 CRESCENT ST. (Continued) **U001840988**

A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 005
Tank ID: 41097
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 500
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None

HIST UST:
PBS Number: 2-480606
SPDES Number: Not reported
Emergency Contact: DAN HARDER
Emergency Telephone: (212) 628-6504
Operator: ROCKROSE CONSTRUCTION CORP.
Operator Telephone: (212) 697-4422
Owner Name: 43-00 CRESCENT ST REALTY CORP.
Owner Address: 309 E. 45 STREET
Owner City,St,Zip: NEW YORK, NY 10017
Owner Telephone: (212) 697-4422
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Name: 43-00 CRESCENT ST REALTY CORP.
Mailing Address: 309 E. 45 STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10017
Mailing Contact: Not reported
Mailing Telephone: (212) 697-4422
Owner Mark: Second Owner

43-00 CRESCENT ST. (Continued) **U001840988**

Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	43000 CRESCENT ST
SWIS ID:	6301
Old PBS Number:	032085
Facility Type:	Not reported
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	Not reported
Expiration Date:	05/16/1995
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed Before April 1, 1991
Install Date:	Not reported
Capacity (gals):	6000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
Lat/long:	Not reported

Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	Closed Before April 1, 1991

43-00 CRESCENT ST. (Continued) **U001840988**

Install Date:	Not reported
Capacity (gals):	5000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
Lat/long:	Not reported

Tank Id:	003
Tank Location:	UNDERGROUND
Tank Status:	Closed Before April 1, 1991
Install Date:	Not reported
Capacity (gals):	1000
Product Stored:	UNKNOWN
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
Lat/long:	Not reported

Tank Id:	004
Tank Location:	UNDERGROUND
Tank Status:	Closed Before April 1, 1991
Install Date:	Not reported
Capacity (gals):	5000
Product Stored:	NOS 1,2, OR 4 FUEL OIL

43-00 CRESCENT ST. (Continued) **U001840988**

Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
Lat/long:	Not reported

Tank Id:	005
Tank Location:	UNDERGROUND
Tank Status:	Closed Before April 1, 1991
Install Date:	Not reported
Capacity (gals):	500
Product Stored:	UNKNOWN
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
Lat/long:	Not reported

N103 **NYCDEP** **NY MANIFEST** **S113813857**
NNW **CRESCENT & 43RD AVE** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.155 mi.
820 ft. **Site 13 of 13 in cluster N**

Relative:
Higher

Actual:
14 ft.

NY MANIFEST:

EPA ID:	NYP003665684
Country:	USA
Mailing Name:	NYCDEP
Mailing Contact:	MOHAMED ABDELAD

NYCDEP (Continued) **S113813857**

Mailing Address:	96-05 HORACE HARDING EXPRESSWAY
Mailing Address 2:	Not reported
Mailing City:	CORONA
Mailing State:	NY
Mailing Zip:	11368
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	22-May-2013 00:00:00
Trans1 Recv Date:	22-May-2013 00:00:00
Trans2 Recv Date:	29-May-2013 00:00:00
TSD Site Recv Date:	31-May-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP003665684
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	008760363JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

P104 **EDR US Hist Auto Stat** **1015355925**
NW **2415 44TH RD** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.155 mi.
821 ft. **Site 1 of 4 in cluster P**

Relative:
Higher

Actual:
15 ft.

EDR Historical Auto Stations:

Name:	A M G AUTO REPAIR
Year:	1999
Address:	2415 44TH RD
Name:	AMG AUTO REPAIR
Year:	2011

(Continued) **1015355925**

Address: 2415 44TH RD

Name: AMG AUTO REPAIR
Year: 2012
Address: 2415 44TH RD

P105 **2415 44TH ROAD LLC** **NY AST** **A100300808**
NW **24-15 44TH ROAD** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.156 mi.
824 ft. **Site 2 of 4 in cluster P**

Relative:
Higher

Actual:
15 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated
Facility Id: 2-600776
Program Type: PBS
UTM X: 589177.33453999995
UTM Y: 4511345.8810299998
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 22753
Affiliation Type: Facility Owner
Company Name: ROCKROSE DEVELOPMENT CORPORATION
Contact Type: Not reported
Contact Name: Not reported
Address1: 290 PARK AVENUE SOUTH
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10010
Country Code: 001
Phone: (212) 375-1155
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 22753
Affiliation Type: Mail Contact
Company Name: COASTAL COMBUSTION CORPORATION
Contact Type: Not reported
Contact Name: SERV. DEPT.
Address1: 1310 JERICHO TURNPIKE
Address2: P.O. BOX 23
City: NEW HYDE PARK
State: NY
Zip Code: 11040
Country Code: 001
Phone: (800) 734-4328
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

2415 44TH ROAD LLC (Continued) **A100300808**

Site Id:	22753
Affiliation Type:	On-Site Operator
Company Name:	2415 44TH ROAD LLC
Contact Type:	Not reported
Contact Name:	ISHMAL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 784-9303
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	22753
Affiliation Type:	Emergency Contact
Company Name:	ROCKROSE DEVELOPMENT CORPORATION
Contact Type:	Not reported
Contact Name:	COASTAL COMBUSTION
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(800) 734-4328
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank Id:	43712
Material Code:	0000
Common Name of Substance:	Empty

Equipment Records:

C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported

2415 44TH ROAD LLC (Continued) **A100300808**

Capacity Gallons:	2020
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	Empty

P106 **EDR US Hist Auto Stat** **1015355790**
NW **2413 44TH RD** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.156 mi.
826 ft. **Site 3 of 4 in cluster P**

Relative:
Higher

Actual:
15 ft.

EDR Historical Auto Stations:

Name:	GREGS AUTO BODY SHOP
Year:	2011
Address:	2413 44TH RD
Name:	GREGS AUTO BODY SHOP
Year:	2012
Address:	2413 44TH RD

P107 **EDR US Hist Auto Stat** **1015355788**
NW **2413 44** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.157 mi.
827 ft. **Site 4 of 4 in cluster P**

Relative:
Higher

Actual:
15 ft.

EDR Historical Auto Stations:

Name:	GREGS AUTO BODY SHOP
Year:	1999
Address:	2413 44
Name:	GREGS AUTO BODY SHOP
Year:	2000
Address:	2413 44

Q108 **45-17 PEARSON ST 45-18 CRT SQ** **NY AST** **U000406504**
SW **45-17 PEARSON ST (45-18 CRT SQ)** **NY HIST AST** **N/A**
1/8-1/4 **LIC, NY 11101**
0.166 mi.
874 ft. **Site 1 of 6 in cluster Q**

Relative:
Lower

Actual:
11 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Facility Id:	2-207098
Program Type:	PBS
UTM X:	589099.14234999998
UTM Y:	4511079.4832199998
Expiration Date:	N/A

45-17 PEARSON ST 45-18 CRT SQ (Continued) **U000406504**

Site Type: Other

Affiliation Records:

Site Id: 7331
Affiliation Type: Facility Owner
Company Name: RICHARD ZIRINSKY
Contact Type: Not reported
Contact Name: Not reported
Address1: 60 E 56TH ST 7TH FL
Address2: Not reported
City: NY
State: NY
Zip Code: 10022
Country Code: 001
Phone: (212) 751-4627
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 12/14/2004

Site Id: 7331
Affiliation Type: Mail Contact
Company Name: RICHARD ZIRINSKY
Contact Type: Not reported
Contact Name: Not reported
Address1: 60 E 56TH ST 7TH FL
Address2: Not reported
City: NY
State: NY
Zip Code: 10022
Country Code: 001
Phone: (212) 751-4627
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 12/14/2004

Site Id: 7331
Affiliation Type: On-Site Operator
Company Name: 45-17 PEARSON ST 45-18 CRT SQ
Contact Type: Not reported
Contact Name: LONG ISLAND CITY REALTY CO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 751-4627
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 7331
Affiliation Type: Emergency Contact
Company Name: RICHARD ZIRINSKY
Contact Type: Not reported

45-17 PEARSON ST 45-18 CRT SQ (Continued) **U000406504**

Contact Name:	LONG ISLAND CITY REALTY CO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 751-4627
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank Id:	24945
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
H99 - Tank Leak Detection - Other

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	6700
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/1990
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	#2 Fuel Oil (On-Site Consumption)

Tank Number:	002
Tank Id:	24946
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

45-17 PEARSON ST 45-18 CRT SQ (Continued) **U000406504**

I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/1990
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	#2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number:	2-207098
SWIS Code:	6301
Operator:	LONG ISLAND CITY REALTY CO
Facility Phone:	(212) 751-4627
Facility Addr2:	45017 PEARSON ST
Facility Type:	Not reported
Emergency:	LONG ISLAND CITY REALTY CO
Emergency Tel:	(212) 751-4627
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	RICHARD ZIRINSKY
Owner Address:	60 E 56TH ST 7TH FL
Owner City,St,Zip:	NY, NY 10022
Federal ID:	Not reported
Owner Tel:	(212) 751-4627
Owner Type:	Not reported
Owner Subtype:	Not reported
Mailing Contact:	Not reported
Mailing Name:	RICHARD ZIRINSKY
Mailing Address:	60 E 56TH ST 7TH FL
Mailing Address 2:	Not reported
Mailing City,St,Zip:	NY, NY 10022
Mailing Telephone:	(212) 751-4627
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Certification Flag:	False
Certification Date:	01/07/1988
Expiration:	01/07/1993
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	Minor Data Missing

45-17 PEARSON ST 45-18 CRT SQ (Continued) **U000406504**

Owner Screen: Minor Data Missing
Tank Screen: 0
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 63
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: UNDERGROUND, VAULTED, WITH ACCESS
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (Gal): 6700
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 9
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 08/01/1990
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 002
Tank Location: UNDERGROUND, VAULTED, WITH ACCESS
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (Gal): 5000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing

45-17 PEARSON ST 45-18 CRT SQ (Continued) **U000406504**

Date Closed:	08/01/1990
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

O109 **21-45 44TH DRIVE** **NY UST** **U004122104**
WNW **21-45 44TH DRIVE** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.167 mi.
880 ft. **Site 2 of 7 in cluster O**

Relative:
Higher

Actual:
16 ft.

UST:

Id/Status:	2-610851 / Unregulated
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588181.06611000001
UTM Y:	4511490.1296499996
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	398441
Affiliation Type:	Facility Owner
Company Name:	21-45 44TH DRIVE LLC
Contact Type:	MEMBER
Contact Name:	STUART SUNA
Address1:	42-22 22ND STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 906-2198
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	5/30/2008

Site Id:	398441
Affiliation Type:	Mail Contact
Company Name:	LANGAN ENGINEERING & ENVIRONMENTAL SERVICES
Contact Type:	Not reported
Contact Name:	JOEL LANDES
Address1:	21 PENN PLAZA
Address2:	360 WEST 31ST STREET, 8TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 479-5400
EMail:	KMERRILL@LANGAN.COM
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	12/2/2010

21-45 44TH DRIVE (Continued) **U004122104**

Site Id:	398441
Affiliation Type:	On-Site Operator
Company Name:	21-45 44TH DRIVE
Contact Type:	Not reported
Contact Name:	MARK GOLD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 906-2191
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	5/30/2008

Site Id:	398441
Affiliation Type:	Emergency Contact
Company Name:	21-45 44TH DRIVE LLC
Contact Type:	Not reported
Contact Name:	MARK GOLD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 906-2191
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	5/30/2008

Tank Info:

Tank Number:	1
Tank ID:	223364
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	01/01/1946
Date Tank Closed:	07/31/2008
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	CGFREEDM
Last Modified:	12/02/2010

Equipment Records:

21-45 44TH DRIVE (Continued) **U004122104**

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None

O110 **CLEANCO INDUSTRIAL SERVICES OF NY INC** **RCRA NonGen / NLR** **1000151535**
WNW **10-39 44TH DR** **FINDS** **NYD066969700**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.167 mi.
880 ft. **Site 3 of 7 in cluster O**

Relative:
Higher

Actual:
16 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	CLEANCO INDUSTRIAL SERVICES OF NY INC
Facility address:	10-39 44TH DR LONG ISLAND CITY, NY 11101
EPA ID:	NYD066969700
Mailing address:	44TH DR LONG ISLAND CITY, NY 11101
Contact:	KEVIN MCDERMOTT
Contact address:	44TH DR LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	(718) 784-8311
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	CLEANCO INDUSTRIAL SERVICES OF NY INC
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	CLEANCO INDUSTRIAL SERVICES OF NY INC
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

CLEANCO INDUSTRIAL SERVICES OF NY INC (Continued) **1000151535**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: CLEANCO INDUSTRIAL SERVICES OF NY INC
Classification: Not a generator, verified

Date form received by agency: 07/10/1981
Facility name: CLEANCO INDUSTRIAL SERVICES OF NY INC
Classification: Unverified

Violation Status: No violations found

FINDS:

Registry ID: 110004365240

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

O111 **DENTSPLY TRU-BYTE** **RCRA NonGen / NLR** **1009399910**
WNW **10-39 44TH DR** **NYR000138743**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.167 mi.
880 ft. **Site 4 of 7 in cluster O**

Relative:
Higher

Actual:
16 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: DENTSPLY TRU-BYTE
Facility address: 10-39 44TH DR
LONG ISLAND CITY, NY 111017013
EPA ID: NYR000138743
Mailing address: W COLLEGE AVE
YORK, PA 174050872
Contact: WAYNE BOLLINGER
Contact address: W COLLEGE AVE

DENTSPLY TRU-BYTE (Continued) **1009399910**

YORK, PA 174050872
Contact country: US
Contact telephone: (717) 849-4240
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: DENTSPLY TRU-BYTE
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 03/23/2006
Owner/Op end date: Not reported

Owner/operator name: WAYNE BOLLINGER
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 03/23/2006
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/27/2006
Facility name: DENTSPLY TRU-BYTE
Classification: Large Quantity Generator

Date form received by agency: 03/26/2006
Facility name: DENTSPLY TRU-BYTE
Classification: Large Quantity Generator

Violation Status: No violations found

O112 **ROSS WATCH CASE CORP** **RCRA NonGen / NLR** **1000376253**
WNW **21-30-42 44TH DR** **FINDS** **NYD053175196**
1/8-1/4 **LONG ISLAND CITY, NY**
0.167 mi.
880 ft. **Site 5 of 7 in cluster O**

Relative:
Higher

Actual:
16 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ROSS WATCH CASE CORP
Facility address:	21-30-42 44TH DR LONG ISLAND CITY, NY 111014710
EPA ID:	NYD053175196
Mailing address:	44TH DR LONG ISLAND CITY, NY 11101
Contact:	Not reported
Contact address:	44TH DR LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ROSS WATCH CASE CORP
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	ROSS WATCH CASE CORP
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

ROSS WATCH CASE CORP (Continued) **1000376253**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: ROSS WATCH CASE CORP
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: ROSS WATCH CASE CORP
Classification: Not a generator, verified

Date form received by agency: 08/18/1980
Facility name: ROSS WATCH CASE CORP
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110008002874

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

O113 **JAGUAR GOLD PRODUCT** **RCRA NonGen / NLR** **1000446330**
WNW **21-30 44TH DR** **FINDS** **NYD986912392**
1/8-1/4 **LONG ISLAND CITY, NY**
0.167 mi.
880 ft. **Site 6 of 7 in cluster O**

Relative: Higher

Actual: 16 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: JAGUAR GOLD PRODUCT
Facility address: 21-30 44TH DR
LONG ISLAND CITY, NY 111014710
EPA ID: NYD986912392
Mailing address: 44TH DR
LONG ISLAND CITY, NY 11101
Contact: Not reported
Contact address: 44TH DR
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

JAGUAR GOLD PRODUCT (Continued) **1000446330**

Owner/operator name: JAGUAR GOLD PRODUCT
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: JAGUAR GOLD PRODUCT
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: JAGUAR GOLD PRODUCT
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: JAGUAR GOLD PRODUCT
Classification: Not a generator, verified

Date form received by agency: 09/10/1990
Facility name: JAGUAR GOLD PRODUCT
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110009479171

Environmental Interest/Information System

JAGUAR GOLD PRODUCT (Continued) **1000446330**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

O114 **E ZAPPI DERMATOPATHOLOGY LAB INC** **RCRA NonGen / NLR** **1001197237**
WNW **21-51 44TH DR** **FINDS** **NYR000036426**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.167 mi.
880 ft. **Site 7 of 7 in cluster O**

Relative:
Higher

Actual:
16 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	E ZAPPI DERMATOPATHOLOGY LAB INC
Facility address:	21-51 44TH DR DBA RECYCLING SYSTEMS LONG ISLAND CITY, NY 11101
EPA ID:	NYR000036426
Mailing address:	44TH DR DBA RECYCLING SYSTEMS LONG ISLAND CITY, NY 11101
Contact:	JEROLD GIBBS
Contact address:	44TH DR DBA RECYCLING SYSTEMS LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	(718) 458-9078
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	DAWNMARK REALTY
Owner/operator address:	23-01 44TH DR LONG ISLAND CITY, NY 11101
Owner/operator country:	US
Owner/operator telephone:	(718) 786-0403
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	DAWNMARK REALTY
Owner/operator address:	23-01 44TH DR LONG ISLAND CITY, NY 11101
Owner/operator country:	US
Owner/operator telephone:	(718) 786-0403
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

E ZAPPI DERMATOPATHOLOGY LAB INC (Continued) **1001197237**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Historical Generators:
- Date form received by agency: 01/01/2006
- Facility name: E ZAPPI DERMATOPATHOLOGY LAB INC
- Classification: Not a generator, verified

- Date form received by agency: 03/07/1997
- Facility name: E ZAPPI DERMATOPATHOLOGY LAB INC
- Classification: Conditionally Exempt Small Quantity Generator

Facility Has Received Notices of Violations:
- Regulation violated: Not reported
- Area of violation: Generators - General
- Date violation determined: 03/04/1997
- Date achieved compliance: 07/02/1997
- Violation lead agency: State
  - Enforcement action: WRITTEN INFORMAL
  - Enforcement action date: 03/04/1997
  - Enf. disposition status: Not reported
  - Enf. disp. status date: Not reported
  - Enforcement lead agency: State
  - Proposed penalty amount: Not reported
  - Final penalty amount: Not reported
  - Paid penalty amount: Not reported

- Regulation violated: Not reported
- Area of violation: LDR - General
- Date violation determined: 03/04/1997
- Date achieved compliance: 07/02/1997
- Violation lead agency: State
  - Enforcement action: WRITTEN INFORMAL
  - Enforcement action date: 03/04/1997
  - Enf. disposition status: Not reported
  - Enf. disp. status date: Not reported
  - Enforcement lead agency: State
  - Proposed penalty amount: Not reported
  - Final penalty amount: Not reported
  - Paid penalty amount: Not reported

E ZAPPI DERMATOPATHOLOGY LAB INC (Continued) **1001197237**

Evaluation Action Summary:
Evaluation date: 01/22/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 07/02/1997
Evaluation lead agency: State

Evaluation date: 01/22/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 07/02/1997
Evaluation lead agency: State

FINDS:

Registry ID: 110004532881

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

---

115 **LIRR - HUNTERS POINT YARD** **RCRA-CESQG** **1008374549**
SSE **SKILLMAN AVE & 27TH ST** **NY MANIFEST** **NYR000132985**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.170 mi.
896 ft.

Relative:
Higher

Actual:
14 ft.

RCRA-CESQG:
Date form received by agency: 01/01/2007
Facility name: LIRR - HUNTERS POINT YARD
Facility address: SKILLMAN AVE & 27TH ST
LONG ISLAND CITY, NY 11101
EPA ID: NYR000132985
Mailing address: 183RD ST - DEPT 3147
HOLLIS, NY 11423
Contact: LEWIS D WUNDERLICH
Contact address: 183RD ST - DEPT 3147
HOLLIS, NY 11423
Contact country: US
Contact telephone: (718) 558-3252
Contact email: LWUNDER@LIRR.ORG
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any

LIRR - HUNTERS POINT YARD (Continued) **1008374549**

time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	MTA LONG ISLAND RAILROAD
Owner/operator address:	SUTPHIN BLVD
	JAMAICA, NY 11435
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	06/29/2005
Owner/Op end date:	Not reported
Owner/operator name:	NO NAME FOUND
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	06/29/2005
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Facility name:	LIRR - HUNTERS POINT YARD
Classification:	Conditionally Exempt Small Quantity Generator
Date form received by agency:	06/30/2005
Facility name:	LIRR - HUNTERS POINT YARD
Classification:	Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

EPA ID:	NYR000132985

LIRR - HUNTERS POINT YARD (Continued) **1008374549**

Country:	USA
Mailing Name:	LONG ISLAND RAILROAD
Mailing Contact:	ADAM MCCOOL
Mailing Address:	93-59 183RD ST
Mailing Address 2:	Not reported
Mailing City:	HOLLIS
Mailing State:	NY
Mailing Zip:	11423
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-558-3359

Document ID:	NYH1459854
Manifest Status:	Not reported
Trans1 State ID:	NYD986938645
Trans2 State ID:	Not reported
Generator Ship Date:	09/20/2005
Trans1 Recv Date:	09/20/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/27/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000132985
Trans1 EPA ID:	CFD1677NY
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00200
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	Not reported

Document ID:	NYH1459854
Manifest Status:	Not reported
Trans1 State ID:	NYD986938645
Trans2 State ID:	Not reported
Generator Ship Date:	09/20/2005
Trans1 Recv Date:	09/20/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/27/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000132985
Trans1 EPA ID:	CFD1677NY
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00200
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.

LIRR - HUNTERS POINT YARD (Continued) **1008374549**

Specific Gravity:	01.00
Year:	2005
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2012-07-26
Trans1 Recv Date:	2012-07-26
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-07-26
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000132985
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	110.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	008923025JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2012-07-26
Trans1 Recv Date:	2012-07-26
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-07-26
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000132985
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	3000.0
Units:	P - Pounds

LIRR - HUNTERS POINT YARD (Continued) **1008374549**

Number of Containers:	6.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	008923025JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2012-07-26
Trans1 Recv Date:	2012-07-26
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-07-26
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000132985
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	110.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	008923025JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported

LIRR - HUNTERS POINT YARD (Continued) **1008374549**

Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2012-07-26
Trans1 Recv Date:	2012-07-26
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-07-26
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000132985
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	110.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	008923025JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2012-07-26
Trans1 Recv Date:	2012-07-26
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-07-26
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000132985
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	3000.0
Units:	P - Pounds
Number of Containers:	6.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	008923025JJK

LIRR - HUNTERS POINT YARD (Continued) **1008374549**

Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2012-07-26
Trans1 Recv Date:	2012-07-26
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-07-26
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000132985
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	110.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	008923025JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Q116
SW
1/8-1/4
0.171 mi.
904 ft.

STERNBERGER WAREHOUSE
45-55 PEARSON ST
LONG ISLAND CITY, NY 11101

Site 2 of 6 in cluster Q

NY MANIFEST **1009231834**
N/A

Relative:
Lower

Actual:
11 ft.

NY MANIFEST:

EPA ID:	NYP000789529
Country:	USA
Mailing Name:	STERNBERGER WAREHOUSE
Mailing Contact:	STERNBERGER WAREHOUSE
Mailing Address:	45-55 PEARSON ST
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-482-0300

Document ID:	NYA2204865
Manifest Status:	Completed copy
Trans1 State ID:	NY64503GJ
Trans2 State ID:	Not reported
Generator Ship Date:	860317
Trans1 Recv Date:	860317
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	860317
Part A Recv Date:	860321
Part B Recv Date:	860325
Generator EPA ID:	NYP000789529
Trans1 EPA ID:	NYD049178296
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049178296
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00042
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00107
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00100
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	86

Q117 **CITYWIDE SELF STORAGE** **NY UST** **U004081629**
SW **45-55 PEARSON STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.171 mi.
904 ft. **Site 3 of 6 in cluster Q**

Relative:
Lower

Actual:
11 ft.

UST:

Id/Status:	2-081566 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	2015/01/03
UTM X:	589133.75289
UTM Y:	4511017.0601700004
Site Type:	Other

Affiliation Records:

Site Id:	1707
Affiliation Type:	Mail Contact
Company Name:	CITIWIDE SELF STORAGE
Contact Type:	Not reported
Contact Name:	MIGUEL A VALOIS
Address1:	45-55 PEARSON ST
Address2:	Not reported
City:	LIC
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 482-0300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	8/7/2012

Site Id:	1707
Affiliation Type:	On-Site Operator
Company Name:	CITYWIDE SELF STORAGE
Contact Type:	Not reported
Contact Name:	MIGUEL A VALOIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 482-0300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	8/7/2012

Site Id:	1707
Affiliation Type:	Emergency Contact
Company Name:	JRK NEW YORK STORAGE I LLC
Contact Type:	Not reported
Contact Name:	RICHARD VESPI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

CITYWIDE SELF STORAGE (Continued) **U004081629**

Zip Code:	Not reported
Country Code:	999
Phone:	(718) 482-0300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	1/3/2005

Site Id:	1707
Affiliation Type:	Facility Owner
Company Name:	JRK NEW YORK STORAGE I LLC
Contact Type:	GENERAL MGR
Contact Name:	GLENN GOLD
Address1:	11766 WILSHIRE BLVD #1450
Address2:	Not reported
City:	LOS ANGELES
State:	CA
Zip Code:	90025
Country Code:	001
Phone:	(310) 268-8344
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	8/7/2012

Tank Info:

Tank Number:	001
Tank ID:	2915
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1967
Date Tank Closed:	06/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

CITYWIDE SELF STORAGE (Continued) **U004081629**

Tank Number:	002
Tank ID:	2916
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1967
Date Tank Closed:	06/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None

Tank Number:	003
Tank ID:	2917
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1967
Date Tank Closed:	06/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping

CITYWIDE SELF STORAGE (Continued) **U004081629**

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	004
Tank ID:	2918
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	12/01/1975
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None

Tank Number:	005
Tank ID:	2919
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	12/01/1975
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

CITYWIDE SELF STORAGE (Continued) **U004081629**

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None

Q118 **CITYWIDE SELF STORAGE** **NY AST** **A100193870**
SW **45-55 PEARSON STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.171 mi.
904 ft. **Site 4 of 6 in cluster Q**

Relative:
Lower

Actual:
11 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-081566
Program Type:	PBS
UTM X:	589133.75289
UTM Y:	4511017.0601700004
Expiration Date:	2015/01/03
Site Type:	Other

Affiliation Records:

Site Id:	1707
Affiliation Type:	Mail Contact
Company Name:	CITIWIDE SELF STORAGE
Contact Type:	Not reported
Contact Name:	MIGUEL A VALOIS
Address1:	45-55 PEARSON ST
Address2:	Not reported
City:	LIC
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 482-0300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	8/7/2012

Site Id:	1707
Affiliation Type:	On-Site Operator
Company Name:	CITYWIDE SELF STORAGE
Contact Type:	Not reported
Contact Name:	MIGUEL A VALOIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 482-0300

CITYWIDE SELF STORAGE (Continued) **A100193870**

EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 8/7/2012

Site Id: 1707
Affiliation Type: Emergency Contact
Company Name: JRK NEW YORK STORAGE I LLC
Contact Type: Not reported
Contact Name: RICHARD VESPI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 482-0300
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 1/3/2005

Site Id: 1707
Affiliation Type: Facility Owner
Company Name: JRK NEW YORK STORAGE I LLC
Contact Type: GENERAL MGR
Contact Name: GLENN GOLD
Address1: 11766 WILSHIRE BLVD #1450
Address2: Not reported
City: LOS ANGELES
State: CA
Zip Code: 90025
Country Code: 001
Phone: (310) 268-8344
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 8/7/2012

Tank Info:

Tank Number: 006
Tank Id: 62393
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A01 - Tank Internal Protection - Epoxy Liner
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin

CITYWIDE SELF STORAGE (Continued) **A100193870**

C01 - Pipe Location - Aboveground
I01 - Overfill - Float Vent Valve
E12 - Piping Secondary Containment - Double-Wall (Aboveground)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/17/1992
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	08/07/2012
Material Name:	#6 Fuel Oil (On-Site Consumption)

Q119 **STERNBERGER MOTOR - G A P REALTY** **RCRA NonGen / NLR** **1000789790**
SW **45-55 PEARSON ST APT UNKNOWN** **FINDS** **NYD987012549**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **NY MANIFEST**
0.171 mi.
904 ft. **Site 5 of 6 in cluster Q**

Relative:
Lower

Actual:
11 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	STERNBERGER MOTOR - G A P REALTY
Facility address:	45-55 PEARSON ST APT UNKNOWN MULTIPLE UNITS ON THE SITE LONG ISLAND CITY, NY 11101
EPA ID:	NYD987012549
Mailing address:	PEARSON ST LONG ISLAND CITY, NY 11101
Contact:	Not reported
Contact address:	PEARSON ST LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MICHAEL GLUCK
Owner/operator address:	45-55 PEARSON ST LONG ISLAND CITY, NY 11101
Owner/operator country:	US
Owner/operator telephone:	(718) 361-2121
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	MICHAEL GLUCK
Owner/operator address:	45-55 PEARSON ST

STERNBERGER MOTOR - G A P REALTY (Continued) **1000789790**

LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 361-2121
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: STERNBERGER MOTOR - G A P REALTY
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: STERNBERGER MOTOR - G A P REALTY
Classification: Not a generator, verified

Date form received by agency: 08/18/1992
Facility name: STERNBERGER MOTOR - G A P REALTY
Classification: Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 07/23/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110004494128

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

STERNBERGER MOTOR - G A P REALTY (Continued) **1000789790**

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYD987012549
Country:	USA
Mailing Name:	STERNBERGER MOTOR
Mailing Contact:	STERNBERGER MOTOR
Mailing Address:	44-55 PEARSON STREET
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	Not reported
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-361-2121

Document ID:	NYB4124376
Manifest Status:	Completed copy
Trans1 State ID:	DEC1A036
Trans2 State ID:	Not reported
Generator Ship Date:	920922
Trans1 Recv Date:	920922
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	920925
Part A Recv Date:	Not reported
Part B Recv Date:	921005
Generator EPA ID:	NYD987012549
Trans1 EPA ID:	NYD980592570
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	01200
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	92

R120 **RML CO.** **NY AST** **U003396594**
WSW **24-20 JACKSON AVENUE** **NY HIST AST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.171 mi.
904 ft. **Site 1 of 2 in cluster R**

Relative:
Higher

Actual:
16 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-602342
Program Type:	PBS
UTM X:	589102.41793999996
UTM Y:	4511116.0493200002
Expiration Date:	2017/10/26

RML CO. (Continued) **U003396594**

Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 24299
Affiliation Type: On-Site Operator
Company Name: RML CO.
Contact Type: Not reported
Contact Name: DAVID MORSE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (914) 674-0063
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 24299
Affiliation Type: Emergency Contact
Company Name: RML CO.
Contact Type: Not reported
Contact Name: DAVID MORSE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (914) 674-0063
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 24299
Affiliation Type: Facility Owner
Company Name: RML II, LLC
Contact Type: MANAGER
Contact Name: DAVID MORSE
Address1: 57 JUDSON AVE
Address2: Not reported
City: DOBBS FERRY
State: NY
Zip Code: 10522
Country Code: 001
Phone: (914) 674-0063
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 6/3/2010

Site Id: 24299
Affiliation Type: Mail Contact
Company Name: RML II, LLC
Contact Type: MANAGER

RML CO. (Continued) **U003396594**

Contact Name:	DAVID MORSE
Address1:	57 JUDSON AVE
Address2:	Not reported
City:	DOBBS FERRY
State:	NY
Zip Code:	10522
Country Code:	001
Phone:	(914) 674-0063
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	6/3/2010

Tank Info:

Tank Number:	001
Tank Id:	49828
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
G99 - Tank Secondary Containment - Other
K00 - Spill Prevention - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/30/1968
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	CGFREEDM
Last Modified:	06/03/2010
Material Name:	#2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number:	2-602342
SWIS Code:	6301
Operator:	DAVID MORSE
Facility Phone:	(914) 674-0063
Facility Addr2:	Not reported
Facility Type:	Not reported
Emergency:	DAVID MORSE

RML CO. (Continued) **U003396594**

Emergency Tel:	(914) 674-0063
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	RML CO.
Owner Address:	57 JUDSON AVENUE
Owner City,St,Zip:	DOBBS FERRY, NY 10522
Federal ID:	Not reported
Owner Tel:	(914) 674-0063
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	DAVID MORSE
Mailing Name:	RML CO.
Mailing Address:	57 JUDSON AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	DOBBS FERRY, NY 10522
Mailing Telephone:	(914) 674-0063
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	06/21/2000
Expiration:	07/17/2005
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	1500
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City Code:	01
Region:	2
Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	1500
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	0
Tank External:	01
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	00
Tank Containment:	Double-Walled
Leak Detection:	00
Overfill Protection:	04
Dispenser Method:	Suction
Date Tested:	Not reported

RML CO. (Continued) **U003396594**

Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

S121 **INTERNATIONAL DESIGN CENTER** **RCRA NonGen / NLR** **1000446329**
SE **29-10 THOMPSON AVE 9TH FL** **FINDS** **NYD986904100**
1/8-1/4 **LONG ISLAND CITY, NY**
0.175 mi.
925 ft. **Site 1 of 2 in cluster S**

Relative:
Higher

Actual:
24 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	INTERNATIONAL DESIGN CENTER
Facility address:	29-10 THOMPSON AVE 9TH FL LONG ISLAND CITY, NY 11101
EPA ID:	NYD986904100
Mailing address:	THOMPSON AVE 9TH FL LONG ISLAND CITY, NY 11101
Contact:	Not reported
Contact address:	THOMPSON AVE 9TH FL LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	PERRY VELLA
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	PERRY VELLA
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

INTERNATIONAL DESIGN CENTER (Continued) **1000446329**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: INTERNATIONAL DESIGN CENTER
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: INTERNATIONAL DESIGN CENTER
Classification: Not a generator, verified

Date form received by agency: 06/14/1990
Facility name: INTERNATIONAL DESIGN CENTER
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004448287

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

S122 **NYSDOT G CAMPBELL PAINTING D253009** **RCRA NonGen / NLR** **1000458443**
ESE **THOMPSON AVE BRIDGE** **FINDS** **NYD986943264**
1/8-1/4 **LONG ISLAND CITY, NY 11100**
0.176 mi.
928 ft. **Site 2 of 2 in cluster S**

Relative:
Higher

Actual:
22 ft.

RCRA NonGen / NLR:

Date form received by agency: 01/01/2007
Facility name: NYSDOT G CAMPBELL PAINTING D253009
Facility address: THOMPSON AVE BRIDGE
LONG ISLAND CITY, NY 11100
EPA ID: NYD986943264
Mailing address: COLLEGE POINT BLVD
FLUSHING, NY 11354
Contact: GEORGE CAMPBELL
Contact address: COLLEGE POINT BLVD

NYSDOT G CAMPBELL PAINTING D253009 (Continued) **1000458443**

FLUSHING, NY 11354
Contact country: US
Contact telephone: (718) 353-8330
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYSDOT
Owner/operator address: BLD 5 HARRIMAN STATE CAMPUS
ALBANY, NY 12232
Owner/operator country: US
Owner/operator telephone: (518) 457-6195
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYSDOT
Owner/operator address: BLD 5 HARRIMAN STATE CAMPUS
ALBANY, NY 12232
Owner/operator country: US
Owner/operator telephone: (518) 457-6195
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYSDOT G CAMPBELL PAINTING D253009
Classification: Not a generator, verified

Date form received by agency: 03/08/1991
Facility name: NYSDOT G CAMPBELL PAINTING D253009
Classification: Not a generator, verified

Violation Status: No violations found

NYSDOT G CAMPBELL PAINTING D253009 (Continued) **1000458443**

FINDS:

Registry ID: 110008048175

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

123
WNW
1/8-1/4
0.177 mi.
933 ft.

Relative:
Higher

Actual:
16 ft.

PERENNIALLY GREEN INC **RCRA NonGen / NLR** **1000871666**
23-13 44TH DR **FINDS** **NY0000082826**
LONG ISLAND CITY, NY 11101 **NY MANIFEST**

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: PERENNIALLY GREEN INC
Facility address: 23-13 44TH DR
LONG ISLAND CITY, NY 111014711
EPA ID: NY0000082826
Mailing address: JACKSON AVE
LONG ISLAND CITY, NY 11101
Contact: Not reported
Contact address: JACKSON AVE
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: PERENNIALLY GREEN INC
Owner/operator address: 153 E 53RD ST
NEW YORK, NY 10022
Owner/operator country: US
Owner/operator telephone: (212) 559-2421
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PERENNIALLY GREEN INC
Owner/operator address: 153 E 53RD ST
NEW YORK, NY 10022
Owner/operator country: US
Owner/operator telephone: (212) 559-2421
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

PERENNIALLY GREEN INC (Continued) **1000871666**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: PERENNIALLY GREEN INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: PERENNIALLY GREEN INC
Classification: Not a generator, verified

Date form received by agency: 12/21/1993
Facility name: PERENNIALLY GREEN INC
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004310576

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NY0000082826
Country: USA
Mailing Name: CUSHMAN & WAKEFIELD
Mailing Contact: FRED VARONE
Mailing Address: 250 JACKSON AVE
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip4: Not reported

PERENNIALLY GREEN INC (Continued) **1000871666**

Mailing Country: USA
Mailing Phone: 718-248-2000

Document ID: NJA1808044
Manifest Status: Completed copy
Trans1 State ID: DL8600869
Trans2 State ID: 08690
Generator Ship Date: 940303
Trans1 Recv Date: 940303
Trans2 Recv Date: 940307
TSD Site Recv Date: 940308
Part A Recv Date: 940311
Part B Recv Date: 940318
Generator EPA ID: NY0000082826
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: ILD984908202
TSDF ID: NJD002182897
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00476
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 94

Document ID: NJA1740672
Manifest Status: Completed copy
Trans1 State ID: NJDEPE086
Trans2 State ID: Not reported
Generator Ship Date: 940223
Trans1 Recv Date: 940223
Trans2 Recv Date: Not reported
TSD Site Recv Date: 940225
Part A Recv Date: 940307
Part B Recv Date: 940311
Generator EPA ID: NY0000082826
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00476
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00476
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 94

Q124 **MATSON MFG CO INC** **RCRA NonGen / NLR** **1000384219**
SW **45-17 PEARSON ST** **FINDS** **NYD088488598**
1/8-1/4 **LONG ISLAND CITY, NY** **NY MANIFEST**
0.177 mi.
935 ft. **Site 6 of 6 in cluster Q**

Relative:
Lower

Actual:
10 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	MATSON MFG CO INC
Facility address:	45-17 PEARSON ST LONG ISLAND CITY, NY 111014307
EPA ID:	NYD088488598
Mailing address:	PEARSON ST LONG ISLAND CITY, NY 11101
Contact:	Not reported
Contact address:	PEARSON ST LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	INTERNATIONAL FASTENER RESEARCH CORP.
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	INTERNATIONAL FASTENER RESEARCH CORP.
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

MATSON MFG CO INC (Continued) **1000384219**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: MATSON MFG CO INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: MATSON MFG CO INC
Classification: Not a generator, verified

Date form received by agency: 08/07/1980
Facility name: MATSON MFG CO INC
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 04/17/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110009468931

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD088488598
Country: USA
Mailing Name: MATSON MFG CO INC
Mailing Contact: HARRY C. HAINES SUPERVIS
Mailing Address: 45-17 PEARSON ST
Mailing Address 2: Not reported
Mailing City: LONG IS CY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-786-1744

Document ID: NYO3018465

MATSON MFG CO INC (Continued) **1000384219**

Manifest Status:	Completed copy
Trans1 State ID:	NY2A029
Trans2 State ID:	Not reported
Generator Ship Date:	830606
Trans1 Recv Date:	830606
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	830605
Part A Recv Date:	030628
Part B Recv Date:	030628
Generator EPA ID:	NYD088488598
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	F003 - UNKNOWN
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	100
Year:	83

Document ID:	NYO2736774
Manifest Status:	Completed copy
Trans1 State ID:	NY2A029
Trans2 State ID:	Not reported
Generator Ship Date:	831215
Trans1 Recv Date:	831215
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	831215
Part A Recv Date:	031227
Part B Recv Date:	031227
Generator EPA ID:	NYD088488598
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	F003 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	100
Year:	83

Document ID:	NYO2736207
Manifest Status:	Completed copy
Trans1 State ID:	NY2A029

MATSON MFG CO INC (Continued) **1000384219**

Trans2 State ID:	Not reported
Generator Ship Date:	831128
Trans1 Recv Date:	831128
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	831128
Part A Recv Date:	031207
Part B Recv Date:	031207
Generator EPA ID:	NYD088488598
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	F003 - UNKNOWN
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	100
Year:	83

Document ID:	NYA1446264
Manifest Status:	Completed copy
Trans1 State ID:	XB72HPNJ
Trans2 State ID:	Not reported
Generator Ship Date:	841218
Trans1 Recv Date:	841218
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	841218
Part A Recv Date:	841220
Part B Recv Date:	841227
Generator EPA ID:	NYD088488598
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	01155
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	84

Document ID:	NYO4111677
Manifest Status:	Completed copy
Trans1 State ID:	NY2A029
Trans2 State ID:	Not reported
Generator Ship Date:	840608
Trans1 Recv Date:	840608
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	840608
Part A Recv Date:	840613
Part B Recv Date:	840620
Generator EPA ID:	NYD088488598
Trans1 EPA ID:	NYD077444263

MATSON MFG CO INC (Continued) **1000384219**

Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	100
Year:	84

Document ID:	NYO3705408
Manifest Status:	Completed copy
Trans1 State ID:	NY2A029
Trans2 State ID:	Not reported
Generator Ship Date:	840828
Trans1 Recv Date:	840828
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	840828
Part A Recv Date:	840831
Part B Recv Date:	840910
Generator EPA ID:	NYD088488598
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	01155
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	100
Year:	84

Document ID:	NYO3144636
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NY2A029
Trans2 State ID:	Not reported
Generator Ship Date:	840327
Trans1 Recv Date:	840327
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	840327
Part A Recv Date:	840530
Part B Recv Date:	840409
Generator EPA ID:	NYD088488598
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	F003 - UNKNOWN
Quantity:	00330
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	100

MATSON MFG CO INC (Continued) **1000384219**

Year: 84

Document ID: CTA0078430
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 6691JWNY
Trans2 State ID: X612XBNJ
Generator Ship Date: 860115
Trans1 Recv Date: 860115
Trans2 Recv Date: 860123
TSD Site Recv Date: 860117
Part A Recv Date: 860219
Part B Recv Date: 860131
Generator EPA ID: NYD088488598
Trans1 EPA ID: CTD981069099
Trans2 EPA ID: CTD981069099
TSDF ID: CTD018656819
Waste Code: F007 - PLATING BATH SOL FM ELECTROPLATING OPER
Quantity: 00570
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 86

Document ID: NYO1546911
Manifest Status: Completed copy
Trans1 State ID: NY2A029
Trans2 State ID: Not reported
Generator Ship Date: 820611
Trans1 Recv Date: 820611
Trans2 Recv Date: Not reported
TSD Site Recv Date: 820611
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD088488598
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: F003 - UNKNOWN
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: Not reported
Specific Gravity: 100
Year: 82

Document ID: NYO1145043
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 02A-029
Trans2 State ID: Not reported
Generator Ship Date: 820225
Trans1 Recv Date: 820225

MATSON MFG CO INC (Continued) **1000384219**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	820225
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD088488598
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	F003 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	100
Year:	82

Document ID:	NYA3812488
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	860626
Trans1 Recv Date:	860626
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	860626
Part A Recv Date:	860813
Part B Recv Date:	860630
Generator EPA ID:	NYD088488598
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00002
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	86

Document ID:	NYA3812477
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	97763GT
Trans2 State ID:	Not reported
Generator Ship Date:	860626
Trans1 Recv Date:	860626
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	860626

MATSON MFG CO INC (Continued) **1000384219**

Part A Recv Date:	860813
Part B Recv Date:	860630
Generator EPA ID:	NYD088488598
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	011
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00090
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00022
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	86

Document ID:	NYA3128646
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	18946GL
Trans2 State ID:	Not reported
Generator Ship Date:	860725
Trans1 Recv Date:	860725
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	860725
Part A Recv Date:	860903
Part B Recv Date:	860801
Generator EPA ID:	NYD088488598
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	P106 - SODIUM CYANIDE
Quantity:	00500
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.

MATSON MFG CO INC (Continued) **1000384219**

Specific Gravity: 100
Year: 86

Document ID: NYA2072457
Manifest Status: Completed copy
Trans1 State ID: 97763GJ
Trans2 State ID: Not reported
Generator Ship Date: 860129
Trans1 Recv Date: 860129
Trans2 Recv Date: Not reported
TSD Site Recv Date: 860129
Part A Recv Date: 860204
Part B Recv Date: 860204
Generator EPA ID: NYD088488598
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: F001 - UNKNOWN
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 86

Document ID: NYO1603242
Manifest Status: Generator copy
Trans1 State ID: 2A029
Trans2 State ID: Not reported
Generator Ship Date: 810619
Trans1 Recv Date: 810619
Trans2 Recv Date: Not reported
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD088488598
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: F003 - UNKNOWN
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: Not reported
Specific Gravity: 100
Year: 80-81

Document ID: NYO1603251
Manifest Status: TSDF copy
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 810410

MATSON MFG CO INC (Continued) **1000384219**

Trans1 Recv Date:	Not reported
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	810313
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD088488598
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	Not reported
Waste Code:	Not reported
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	80-81

Document ID:	NYO1586826
Manifest Status:	Completed copy
Trans1 State ID:	02A-029
Trans2 State ID:	Not reported
Generator Ship Date:	811027
Trans1 Recv Date:	811027
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	811027
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD088488598
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	F005 - UNKNOWN
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	80-81

Document ID:	NYO2721177
Manifest Status:	Completed copy
Trans1 State ID:	NY2A029
Trans2 State ID:	Not reported
Generator Ship Date:	830909
Trans1 Recv Date:	830909
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	830909
Part A Recv Date:	030922
Part B Recv Date:	030922
Generator EPA ID:	NYD088488598
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263

MATSON MFG CO INC (Continued) **1000384219**

Waste Code: F001 - UNKNOWN
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: Not reported
Specific Gravity: 100
Year: 83

Document ID: NYO2058264
Manifest Status: Completed copy
Trans1 State ID: NY2A029
Trans2 State ID: Not reported
Generator Ship Date: 821208
Trans1 Recv Date: 821208
Trans2 Recv Date: Not reported
TSD Site Recv Date: 821208
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD088488598
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: F003 - UNKNOWN
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: Not reported
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: Not reported
Specific Gravity: 100
Year: 82

Document ID: NYO2446218
Manifest Status: Completed copy
Trans1 State ID: NY2A029
Trans2 State ID: Not reported
Generator Ship Date: 820910
Trans1 Recv Date: 820910
Trans2 Recv Date: Not reported
TSD Site Recv Date: 820910
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD088488598
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: F003 - UNKNOWN
Quantity: 00325

MATSON MFG CO INC (Continued) **1000384219**

Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	100
Year:	82

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

T125 **EDR US Hist Auto Stat** **1015387833**
NE **2820 42ND RD** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.179 mi.
947 ft. **Site 1 of 2 in cluster T**

Relative:
Higher

Actual:
19 ft.

EDR Historical Auto Stations:

Name:	JACKMAN BROTHERS AUTO BODY
Year:	1999
Address:	2820 42ND RD
Name:	JACKMAN BROTHERS AUTO BODY
Year:	2000
Address:	2820 42ND RD
Name:	JACKMAN BROTHERS AUTO BODY
Year:	2001
Address:	2820 42ND RD
Name:	JACKMAN BROTHERS AUTO BODY
Year:	2002
Address:	2820 42ND RD
Name:	JACKMAN BROTHERS AUTO BODY
Year:	2003
Address:	2820 42ND RD

---

126 **EAGLE ELECTRIC MFG CO INC** **NY AST** **U003393332**
NNW **43-35 24TH STREET** **NY HIST AST** **N/A**
1/8-1/4 **LIC, NY 11101**
0.180 mi.
949 ft.

Relative:
Higher

Actual:
15 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-017388
Program Type:	PBS
UTM X:	589213.47773000004
UTM Y:	4511415.5948200002
Expiration Date:	2008/02/21
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	130
Affiliation Type:	Facility Owner

EAGLE ELECTRIC MFG CO INC (Continued) **U003393332**

Company Name:	ELECTRIC REALTY LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	457 KNICKERBOCKER AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 919-0824
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	10/28/2004

Site Id:	130
Affiliation Type:	Mail Contact
Company Name:	ELECTRIC REALTY
Contact Type:	Not reported
Contact Name:	AL PIZZUTO
Address1:	457 KNICKERBOCKER AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 919-0824
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	10/28/2004

Site Id:	130
Affiliation Type:	On-Site Operator
Company Name:	BENFEILD ELECTRIC
Contact Type:	Not reported
Contact Name:	BENFEILD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 706-8600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	130
Affiliation Type:	Emergency Contact
Company Name:	ELECTRIC REALTY LLC
Contact Type:	Not reported
Contact Name:	TED LACHMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported

EAGLE ELECTRIC MFG CO INC (Continued) **U003393332**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 919-0824
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank Id:	27003
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
D00 - Pipe Type - No Piping
I05 - Overfill - Vent Whistle
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F04 - Pipe External Protection - Fiberglass
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	#6 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number:	2-017388
SWIS Code:	6301
Operator:	EAGLE ELECTRIC MFG CO INC
Facility Phone:	(718) 937-8000
Facility Addr2:	43035 24TH STREET
Facility Type:	Not reported
Emergency:	ALFRED PIZZUTO
Emergency Tel:	(914) 962-6467
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported

EAGLE ELECTRIC MFG CO INC (Continued) **U003393332**

Owner Name:	EAGLE ELECTRIC MFG CO INC
Owner Address:	45-31 COURT SQ
Owner City,St,Zip:	LIC, NY 11101
Federal ID:	Not reported
Owner Tel:	(718) 937-8000
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	AL PIZZUTO
Mailing Name:	EAGLE ELECTRIC MFG CO INC
Mailing Address:	45-31 COURT SQ
Mailing Address 2:	Not reported
Mailing City,St,Zip:	LIC, NY 11101
Mailing Telephone:	(718) 937-8000
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	09/30/1999
Expiration:	10/23/2002
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	4000
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	4000
Product Stored:	NOS 5 OR 6 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	01
Pipe Location:	None
Pipe Type:	NONE
Pipe Internal:	None
Pipe External:	04
Tank Containment:	Diking
Leak Detection:	00
Overfill Protection:	46
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False

EAGLE ELECTRIC MFG CO INC (Continued) **U003393332**

Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

T127 **J BROTHERS AUTO BODY INC** **RCRA NonGen / NLR** **1004760310**
NE **28-20 42ND RD** **FINDS** **NYR000039644**
1/8-1/4 **LONG ISLAND CITY, NY** **NY MANIFEST**
0.180 mi.
952 ft. **Site 2 of 2 in cluster T**

Relative:
Higher

Actual:
19 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: J BROTHERS AUTO BODY INC
Facility address: 28-20 42ND RD
LONG ISLAND CITY, NY 11101
EPA ID: NYR000039644
Mailing address: 42ND RD
LONG ISLAND CITY, NY 11101
Contact: PATRICK JACKMAN
Contact address: 42ND RD
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: (718) 784-2888
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: J BROTHERS AUTO BODY INC
Owner/operator address: 28-20 42ND RD
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 784-2888
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: J BROTHERS AUTO BODY INC
Owner/operator address: 28-20 42ND RD
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 784-2888
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No

J BROTHERS AUTO BODY INC (Continued) **1004760310**

Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Facility name:	J BROTHERS AUTO BODY INC
Classification:	Not a generator, verified

Date form received by agency:	05/22/1997
Facility name:	J BROTHERS AUTO BODY INC
Classification:	Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004534549

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYR000039644
Country:	USA
Mailing Name:	JACKMAN BROTHERS AUTO BODY
Mailing Contact:	DARICK JACKMAN
Mailing Address:	28-20 42ND ROAD
Mailing Address 2:	Not reported
Mailing City:	LIC
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-784-2888

Document ID:	NJA2963795
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	06/30/1998
Trans1 Recv Date:	06/30/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/1998
Part A Recv Date:	Not reported

J BROTHERS AUTO BODY INC (Continued) **1004760310**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000039644
Trans1 EPA ID:	NJD002454544
Trans2 EPA ID:	Not reported
TSDF ID:	50160
Waste Code:	F003 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	98

Document ID:	NJA3069086
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	10/07/1999
Trans1 Recv Date:	10/07/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/11/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000039644
Trans1 EPA ID:	NJD002454544
Trans2 EPA ID:	Not reported
TSDF ID:	50160
Waste Code:	F003 - UNKNOWN
Quantity:	00045
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	99

R128 **CONSOLIDATED EDISON** **NY MANIFEST** **1009239522**
WSW **PEARSON ST & JACKSON AVE** **N/A**
1/8-1/4 **QUEENS, NY 11101**
0.181 mi.
957 ft. **Site 2 of 2 in cluster R**

Relative:
Higher

Actual:
16 ft.

NY MANIFEST:

EPA ID:	NYP004062386
Country:	USA
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-2808

CONSOLIDATED EDISON (Continued) **1009239522**

Document ID:	NYE0671445
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/12/2000
Trans1 Recv Date:	09/12/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/14/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004062386
Trans1 EPA ID:	NYD980593636
Trans2 EPA ID:	Not reported
TSDF ID:	GX3213
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity:	01093
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2000

---

129 **EDR US Hist Cleaners** **1015062971**
SE **4507 28TH ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.183 mi.
964 ft.

Relative:
Higher

Actual:
20 ft.

EDR Historical Cleaners:

Name:	JIFFY JEFFS LAUNDROMAT
Year:	1999
Address:	4507 28TH ST
Name:	JIFFY JEFFS LAUNDROMAT
Year:	2000
Address:	4507 28TH ST

U130 **SATT REALTY CORP.** **NY UST** **U001839678**
South **26-32 SKILLMAN AVENUE** **NY HIST UST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.187 mi.
985 ft. **Site 1 of 2 in cluster U**

Relative:
Higher

Actual:
14 ft.

UST:

Id/Status:	2-349429 / Unregulated
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589385.55319000001
UTM Y:	4510876.7618100001
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	17202
Affiliation Type:	Facility Owner

SATT REALTY CORP. (Continued) **U001839678**

Company Name:	SATT REALTY CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	26132 SKILLMAN AVE.
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(800) 521-1132
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	17202
Affiliation Type:	Mail Contact
Company Name:	AMERICAN PLUME
Contact Type:	Not reported
Contact Name:	ANTHONY TRENTO
Address1:	P.O. BOX 566
Address2:	Not reported
City:	CLARKS SUMMIT
State:	PA
Zip Code:	18411
Country Code:	001
Phone:	(800) 521-1132
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	17202
Affiliation Type:	On-Site Operator
Company Name:	SATT REALTY CORP.
Contact Type:	Not reported
Contact Name:	ANTHONY TRENTO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 729-1552
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	17202
Affiliation Type:	Emergency Contact
Company Name:	SATT REALTY CORP.
Contact Type:	Not reported
Contact Name:	ANTHONY TRENTO
Address1:	Not reported
Address2:	Not reported
City:	Not reported

SATT REALTY CORP. (Continued) **U001839678**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 729-1552
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank ID:	33501
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	Not reported
Date Tank Closed:	08/01/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

G00 - Tank Secondary Containment - None
C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

HIST UST:

PBS Number:	2-349429
SPDES Number:	Not reported
Emergency Contact:	ERNEST TRENTO
Emergency Telephone:	(516) 671-2766
Operator:	ANTHONY TRENTO % ERNEST TRENTO
Operator Telephone:	(718) 729-1552
Owner Name:	ERNEST TRENTO
Owner Address:	15 MICHAEL F STREET
Owner City,St,Zip:	LOCUST VALLEY, NY 11560
Owner Telephone:	(516) 671-2766
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	SATT REALTY CORP.
Mailing Address:	26-32 SKILLMAN AVENUE

SATT REALTY CORP. (Continued) **U001839678**

Mailing Address 2:	Not reported
Mailing City,St,Zip:	LONG ISLAND CITY, NY 11101
Mailing Contact:	Not reported
Mailing Telephone:	(718) 729-1552
Owner Mark:	Second Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	26032 SKILLMAN AVE
SWIS ID:	6301
Old PBS Number:	Not reported
Facility Type:	MANUFACTURING
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	10/27/2000
Expiration Date:	10/26/2005
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	6000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (gals):	6000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Stainless steel alloy
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Diking
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Gravity
Date Tested:	Not reported
Next Test Date:	12/27/1987
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True

SATT REALTY CORP. (Continued) **U001839678**

Lat/long: Not reported

U131 **SPILL NUMBER 0303917** **NY LTANKS** **S105999403**
South **26-32 SKILLMAN AVE** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY**
0.187 mi.
985 ft. **Site 2 of 2 in cluster U**

Relative:
Higher

Actual:
14 ft.

LTANKS:

Site ID:	283736
Spill Number/Closed Date:	0209560 / 2/17/2006
Spill Date:	12/17/2002
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	Con Ed Unassigned
Referred To:	Not reported
Reported to Dept:	12/17/2002
CID:	198
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	12/17/2002
Spill Record Last Update:	2/17/2006
Spiller Name:	ERNEST
Spiller Company:	Not reported
Spiller Address:	26-32 SKILLMAN AVE
Spiller City,St,Zip:	LONG ISLAND CITY, NY
Spiller County:	001
Spiller Contact:	ERNEST
Spiller Phone:	(718) 729-1552
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	228002
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE"CALLED ERNEST TRENTO, CO-OWNER FOR THIS PROPERTY, WHO CONFIRMED THAT THE TANK FAILED TIGHTNESS TEST.TANK TEST FAILURE LETTER WILL BE SENT, VIA THE MAIL, TODAY.E.R. 1/14/04 TIPPLE Sent request for documentation.12/19/05 Feroze. Spill is transferred from Ketani to Feroze.02/01/06. Feroze . Phone No. 718- 729-1552 is not in service. PBS of this site is #2-349429.TTF is sent:Satt realty Corp.26-32 Skillman Ave,Long Island City. NY 11101.02/17/06. Feroze, According to PBS documents the tank is closed and removed from the place. There was a leak in dry portion of the tank. Consultation with DEc Jake the slill is closed.
Remarks:	CALLER AGENCY CALLED TO DO TANK TEST - TEST RESULTED IN DRY LEAKAGE.

Material:

Site ID:	283736
Operable Unit ID:	860830

SPILL NUMBER 0303917 (Continued) **S105999403**

Operable Unit:	01
Material ID:	512980
Material Code:	0003A
Material Name:	#6 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	283736
Spill Tank Test:	1527845
Tank Number:	1
Tank Size:	6000
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Horner EZ Check I or II

Site ID:	280781
Spill Number/Closed Date:	0303917 / 1/7/2004
Spill Date:	7/14/2003
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	CESAWYER
Referred To:	Not reported
Reported to Dept:	7/14/2003
CID:	405
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	7/14/2003
Spill Record Last Update:	1/7/2004
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	26-32 SKILLMAN AVE
Spiller City,St,Zip:	LONG ISLAND CITY, NY 11101-
Spiller County:	001
Spiller Contact:	ANTIL ANTOINE
Spiller Phone:	(413) 246-2664
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	228002

SPILL NUMBER 0303917 (Continued) **S105999403**

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SAWYER"Tank test failure letter sent to:Mr. Ernie Trentoc/o American PlumePO Box 566Clarks Summit, PA 184119/17/03 TRANSFERRED FROM TIPPLE TO SAWYER11/26/03 1042 Hrs - Sawyer - Received an extensive fax from the lawyer J. James Carriero for the tank closure that happened on 8/1/03. All disposal, removal and end point sample analysis is contained in this report. A "No Further Action" letter will be sent to Ernie Trento. Closed.
Remarks: uncover - repair - retest

Material:
Site ID: 280781
Operable Unit ID: 872173
Operable Unit: 01
Material ID: 504775
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

132
NNW
1/8-1/4
0.189 mi.
998 ft.

Relative:
Higher

Actual:
15 ft.

MORBECK CORP **NY AST U003389869**
24-15 43 AVE **NY HIST AST N/A**
LONG ISLAND CITY, NY 11101

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-309052
Program Type: PBS
UTM X: 589254.16087999998
UTM Y: 4511458.8288599998
Expiration Date: 2018/07/10
Site Type: Manufacturing (Other than Chemical)/Processing

Affiliation Records:
Site Id: 14071
Affiliation Type: Facility Owner
Company Name: AB MARBEC REALTY CORP
Contact Type: PRESIDENT
Contact Name: AVROHOM BECKER
Address1: 1684 59TH STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11204
Country Code: 001

MORBECK CORP (Continued) **U003389869**

Phone:	(718) 633-2236
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	6/3/2013

Site Id:	14071
Affiliation Type:	Mail Contact
Company Name:	AB MARBEC REALTY CORP
Contact Type:	PRESIDENT
Contact Name:	AVROHOM BECKER
Address1:	1684 59TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11204
Country Code:	001
Phone:	(718) 633-2236
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	6/3/2013

Site Id:	14071
Affiliation Type:	On-Site Operator
Company Name:	AB MARBEC REALTY CORP
Contact Type:	Not reported
Contact Name:	CALVIN COOKS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 706-6420
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	14071
Affiliation Type:	Emergency Contact
Company Name:	AB MARBEC REALTY CORP
Contact Type:	Not reported
Contact Name:	AVROHOM BECKER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 633-2236
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	6/3/2013

MORBECK CORP (Continued) **U003389869**

Tank Info:

Tank Number:	00A
Tank Id:	17769
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle
B01 - Tank External Protection - Painted/Asphalt Coating
C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/10/1960
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMMOLOUG
Last Modified:	06/03/2013
Material Name:	#2 Fuel Oil (On-Site Consumption)

Tank Number:	00B
Tank Id:	17770
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron

MORBECK CORP (Continued) **U003389869**

Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/10/1960
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMMOLOUG
Last Modified:	06/03/2013
Material Name:	#2 Fuel Oil (On-Site Consumption)

Tank Number:	00C
Tank Id:	17771
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
I05 - Overfill - Vent Whistle

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/10/1960
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMMOLOUG
Last Modified:	06/03/2013
Material Name:	#2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number:	2-309052
SWIS Code:	6301
Operator:	MORBECK REALTY
Facility Phone:	(718) 392-7096
Facility Addr2:	24015 43 AVE
Facility Type:	Not reported
Emergency:	MORRIS BECKER
Emergency Tel:	(718) 633-2236

MORBECK CORP (Continued) **U003389869**

Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	MORBECK CORP
Owner Address:	24-15 43 AVE
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Federal ID:	Not reported
Owner Tel:	(718) 392-7096
Owner Type:	Not reported
Owner Subtype:	Not reported
Mailing Contact:	Not reported
Mailing Name:	MORBECK CORP
Mailing Address:	24-15 43 AVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	LONG ISLAND CITY, NY 11101
Mailing Telephone:	(718) 392-7096
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	07/20/1987
Expiration:	07/20/1992
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	9000
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	True
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City Code:	01
Region:	2

Tank ID:	00A
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	3000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	None
Leak Detection:	0
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported

MORBECK CORP (Continued) **U003389869**

Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 00B
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 3000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 00C
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 3000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing

MORBECK CORP (Continued) **U003389869**

Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

V133 **QUEENS PLAZA RESIDENTIAL DEVELOPMENT** **NY BROWNFIELDS** **S108524793**
NE **28-10 JACKSON AVENUE** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.193 mi.
1017 ft. **Site 1 of 2 in cluster V**

Relative:
Higher

Actual:
18 ft.

BROWNFIELDS:
Program: BCP
Site Code: 379475
Site Description: Location: This Brownfield site is approximately 0.5 acres in size and is a portion of the Outlet City VCP site(#V00081) located at 28-10 Jackson Avenue, Long Island City. The site is located in Queens County, on Jackson Ave between Orchard Street to the east, Queens Blvd. to the west and Long Island Railroad yard to the south. The G-Train runs underneath Jackson Avenue bordering the site to the north. The nearest residential structure is located approximately 100ft to the west across Orchard street. Site Features: This 0.5 acre site is an empty lot in a congested commercial/industrial area of Queens County. Current Zoning/Uses(s): The current zoning at the site is Industrial and Retail. The surrounding area is zoned Special Long Island City Mixed Use District (LIC) and is a longstanding mix of residential, commercial, industrial and cultural uses at varying densities.Historical Uses: The site had formerly been used for chemical manufacturing. From 1901-1978, West Chemical Co. owned the property and manufactured commercial and disinfectant products such as disinfectants, insecticides, soaps, floor wax, and paper products dispensing machines. Manufacturing operations employed various chemical substances including creosote, coal and acids, cresylic acids, degreasing solvents, iodine, and assorted oils and pesticides. Metal plating and gasoline filling operations were also conducted at the property. Intended use for this site is to build a multi-tenant high-rise residential apartment building with ground floor commercial space and a basement.The Remedial Work Plan was publicly noticed in June/July 2007 and was approved by the state on August 16,2007. The remedial action has not yet been done (Sept. 2011).Site Geology and Hydrogeology: Site geology consists of mostly sand at varying depths due to presence of shallow bedrock. Groundwater is approximately 8 -10ft below grade.
Env Problem: The release of approximately 5000 gallons of creosote caused extensive soil and groundwater contamination that includes the presence of LNAPL and residual DNAPL. This site is considered a significant threat to the environment.Contaminants in soil which exceed soil cleanup objectives primarily include: Naphthalene, 2-Methylnaphthalene, Acenaphtene, Dibenzofuran, Flourene, Benzene, Ethylbenzene, and total Xylenes.Contaminants in groundwater which exceed groundwater standards primarily include: 2-methylphenol, phenol, Napthalene, 2-methylnaphthalene, benzene, Toluene, Ethylbenzene, and total xylenes.
Health Problem: The remedial investigation documented that subsurface soils and groundwater are contaminated with volatile organic compounds, semi volatile organic compounds, and chlorinated solvents. Exposures via

QUEENS PLAZA RESIDENTIAL DEVELOPMENT (Continued) **S108524793**

drinking water are not expected because this mixed industrial/residential neighborhood is served by public water. The new building proposed for the site will include a vapor barrier and sub-slab depressurization system to prevent exposures via vapor intrusion. Additionally, the site will be capped with asphalt and managed through the site management plan which minimizes the potential for direct contact with residual soil contamination.

W134 **EDR US Hist Cleaners** **1015031981**
NNE **2704 42ND RD** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.193 mi.
1017 ft. **Site 1 of 4 in cluster W**

Relative:
Higher

Actual:
18 ft.

EDR Historical Cleaners:

Name:	UTICA LAUNDRY CORP
Year:	2006
Address:	2704 42ND RD
Name:	UTICA LAUNDRY CORP
Year:	2007
Address:	2704 42ND RD
Name:	UTICA LAUNDRY CORP
Year:	2008
Address:	2704 42ND RD
Name:	UTICA LAUNDRY CORP
Year:	2009
Address:	2704 42ND RD

---

135 **GAP REALTY CO** **NY UST** **U000724472**
SW **45-56 PEARSON ST** **NY HIST UST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.193 mi.
1019 ft.

Relative:
Lower

Actual:
9 ft.

UST:

Id/Status:	2-600746 / Unregulated
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589134.61719000002
UTM Y:	4511015.4052200001
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	22724
Affiliation Type:	Facility Owner
Company Name:	MICHAEL GLUCK-GEN. PARTNER
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	45-55 PEARSON ST
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY

GAP REALTY CO (Continued) **U000724472**

Zip Code:	11101
Country Code:	001
Phone:	(718) 361-2121
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	22724
Affiliation Type:	Mail Contact
Company Name:	GAP REALTY CO
Contact Type:	Not reported
Contact Name:	DOUG BEHRMANN
Address1:	45-55 PEARSON ST
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 361-2121
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	22724
Affiliation Type:	On-Site Operator
Company Name:	GAP REALTY CO
Contact Type:	Not reported
Contact Name:	DOUG BEHRMANN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 745-9682
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	22724
Affiliation Type:	Emergency Contact
Company Name:	MICHAEL GLUCK-GEN. PARTNER
Contact Type:	Not reported
Contact Name:	DOUG BEHRMANN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 745-9682
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT

GAP REALTY CO (Continued) **U000724472**

Date Last Modified: 3/4/2004

Tank Info:

Tank Number: D1
Tank ID: 43537
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 05/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground

Tank Number: G1
Tank ID: 43535
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 05/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

I00 - Overfill - None

GAP REALTY CO (Continued) **U000724472**

H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: G2
Tank ID: 43536
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 05/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

HIST UST:
PBS Number: 2-600746
SPDES Number: Not reported
Emergency Contact: DOUG BEHRMANN
Emergency Telephone: (718) 745-9682
Operator: DOUG BEHRMANN
Operator Telephone: (718) 745-9682
Owner Name: MICHAEL GLUCK-GEN. PARTNER
Owner Address: 45-55 PEARSON ST
Owner City,St,Zip: LONG ISLAND CITY, NY 11101
Owner Telephone: (718) 361-2121
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: GAP REALTY CO
Mailing Address: 45-55 PEARSON ST
Mailing Address 2: Not reported

GAP REALTY CO (Continued) **U000724472**

Mailing City,St,Zip:	LONG ISLAND CITY, NY 11101
Mailing Contact:	DOUG BEHRMANN
Mailing Telephone:	(718) 361-2121
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	45056 PEARSON ST
SWIS ID:	6301
Old PBS Number:	Not reported
Facility Type:	TRUCKING/TRANSPORTATION
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	Not reported
Expiration Date:	05/08/1997
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City:	01
Region:	2

Tank Id:	D1
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	DIESEL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	05/01/1992
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

GAP REALTY CO (Continued) **U000724472**

Tank Id:	G1
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	05/01/1992
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	G2
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	05/01/1992
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

W136 **ANOCA PLATING SERVICE CORP** **RCRA NonGen / NLR** **1000166062**
NNE **27-04 42ND RD** **FINDS** **NYD041565748**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.194 mi.
1024 ft. **Site 2 of 4 in cluster W**

Relative:
Higher

Actual:
18 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ANOCA PLATING SERVICE CORP
Facility address:	27-04 42ND RD LONG ISLAND CITY, NY 111014112
EPA ID:	NYD041565748
Mailing address:	42ND RD LONG ISLAND CITY, NY 11101
Contact:	Not reported
Contact address:	42ND RD LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	SAMUEL HUREWITZ
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	SAMUEL HUREWITZ
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

ANOCA PLATING SERVICE CORP (Continued) **1000166062**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: ANOCA PLATING SERVICE CORP
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: ANOCA PLATING SERVICE CORP
Classification: Not a generator, verified

Date form received by agency: 08/18/1980
Facility name: ANOCA PLATING SERVICE CORP
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/25/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004354341

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

137
NNE
1/8-1/4
0.194 mi.
1025 ft.

STAR JOURNAL BUILDING **NY AST** **A100296154**
42-26 28TH STREET **N/A**
LONG ISLAND CITY, NY 11101

Relative:
Higher

Actual:
20 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-607562
Program Type: PBS
UTM X: 589547.09658000001
UTM Y: 4511504.8855699999
Expiration Date: 2007/04/03
Site Type: Other

STAR JOURNAL BUILDING (Continued) **A100296154**

Affiliation Records:

Site Id:	29414
Affiliation Type:	Facility Owner
Company Name:	CREATIVE ESTATES INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	42--46 28TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 729-5131
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	29414
Affiliation Type:	Mail Contact
Company Name:	CREATIVE ESTATES INC
Contact Type:	Not reported
Contact Name:	CHARLES M. FERTITTA
Address1:	42-26 28TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 729-5131
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	29414
Affiliation Type:	On-Site Operator
Company Name:	STAR JOURNAL BUILDING
Contact Type:	Not reported
Contact Name:	RYES PYLON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 729-5131
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	29414
Affiliation Type:	Emergency Contact
Company Name:	CREATIVE ESTATES INC
Contact Type:	Not reported
Contact Name:	ROBERT FERTITTA

STAR JOURNAL BUILDING (Continued) **A100296154**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 746-2726
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank Id:	63193
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	#2 Fuel Oil (On-Site Consumption)

138
South
1/8-1/4
0.197 mi.
1040 ft.

CON EDISON MANHOLE 954
47TH ST & SKILLMAN AVE
LONG ISLAND CITY, NY 11101

RCRA NonGen / NLR **1010326800**
NY MANIFEST **NYP004143129**

Relative:
Higher

Actual:
14 ft.

RCRA NonGen / NLR:

Date form received by agency:	11/17/2006
Facility name:	CON EDISON MANHOLE 954
Facility address:	47TH ST & SKILLMAN AVE LONG ISLAND CITY, NY 11101
EPA ID:	NYP004143129

CON EDISON MANHOLE 954 (Continued) **1010326800**

Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: MICHAEL DAUGHTREY
Contact address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact country: US
Contact telephone: (212) 580-8383
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/16/2006
Facility name: CON EDISON MANHOLE 954
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 11/15/2006
Facility name: CON EDISON MANHOLE 954
Site name: CON EDISON
Classification: Unverified

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004143129
Country: USA
Mailing Name: CONSOLIDATAED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-460-2808

CON EDISON MANHOLE 954 (Continued) **1010326800**

Document ID:	NYE1286631
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	06/24/2006
Trans1 Recv Date:	06/24/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/26/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004143129
Trans1 EPA ID:	12446JT
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity:	00168
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2006

X139 **EDR US Hist Auto Stat** **1015488606**
North **4237 CRESCENT ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.197 mi.
1040 ft. **Site 1 of 6 in cluster X**

Relative:
Higher

Actual:
17 ft.

EDR Historical Auto Stations:

Name:	BAGWIN BROTHERS SVC CTR INC
Year:	2010
Address:	4237 CRESCENT ST

X140 **BAGWIN BROTHERS SERVICE CENTER, INC.** **NY UST** **U004046068**
North **42-37 CRESCENT STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.198 mi.
1043 ft. **Site 2 of 6 in cluster X**

Relative:
Higher

Actual:
17 ft.

UST:

Id/Status:	2-609460 / Unregulated
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589390.39372000005
UTM Y:	4511532.4145799996
Site Type:	Other

Affiliation Records:

Site Id:	31304
Affiliation Type:	Mail Contact
Company Name:	BAGWIN BROTHERS SERVICE CENTER INC
Contact Type:	Not reported
Contact Name:	MICHAEL BAGWIN
Address1:	42-37 CHESCENT STREET

BAGWIN BROTHERS SERVICE CENTER, INC. (Continued) **U004046068**

Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 786-5656
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	31304
Affiliation Type:	On-Site Operator
Company Name:	BAGWIN BROTHERS SERVICE CENTER, INC.
Contact Type:	Not reported
Contact Name:	MICHAEL BAGWIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 786-5656
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2/24/2009

Site Id:	31304
Affiliation Type:	Emergency Contact
Company Name:	BAGWIN BROTHERS SERVICE CENTER, INC.
Contact Type:	Not reported
Contact Name:	MICHAEL BAGWIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 786-5656
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2/24/2009

Site Id:	31304
Affiliation Type:	Facility Owner
Company Name:	BAGWIN BROTHERS SERVICE CENTER, INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	42-37 CRESCENT STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 786-5656

BAGWIN BROTHERS SERVICE CENTER, INC. (Continued) **U004046068**

EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2/24/2009

Tank Info:

Tank Number: 001
Tank ID: 67522
Tank Status: A
Material Name: A
Capacity Gallons: 200
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: LXZIELIN
Last Modified: 05/16/2012

Equipment Records:

G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None

Y141 **EDR US Hist Auto Stat** **1015507532**
SSE **4620 27TH ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.198 mi.
1043 ft. **Site 1 of 3 in cluster Y**

Relative:
Lower

Actual:
13 ft.

EDR Historical Auto Stations:

Name: T & M AUTO SPECIALIST
Year: 2003
Address: 4620 27TH ST

Name: SKILLMAN AUTO INC
Year: 2004
Address: 4620 27TH ST

Name: LIC AUTO GROUP
Year: 2005
Address: 4620 27TH ST

X142 **EPPY PLATING** **RCRA NonGen / NLR** **1000440607**
North **42-40 CRESCENT ST** **FINDS** **NYD078517307**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.198 mi.
1048 ft. **Site 3 of 6 in cluster X**

Relative:
Higher

Actual:
17 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	EPPY PLATING
Facility address:	42-40 CRESCENT ST LONG ISLAND CITY, NY 11101
EPA ID:	NYD078517307
Mailing address:	CRESCENT ST LONG ISLAND CITY, NY 11101
Contact:	Not reported
Contact address:	CRESCENT ST LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

EPPY PLATING (Continued) **1000440607**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: EPPY PLATING
Classification: Not a generator, verified

Date form received by agency: 12/31/1979
Facility name: EPPY PLATING
Classification: Not a generator, verified

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 04/09/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004370190

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Y143 **46-20 27TH STREET LLC** **NY AST** **A100183492**
SSE **46-20 27TH STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.199 mi.
1050 ft. **Site 2 of 3 in cluster Y**

Relative:
Lower

Actual:
13 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated
Facility Id: 2-606925
Program Type: PBS
UTM X: 589458.58097999997
UTM Y: 4510905.84301
Expiration Date: N/A
Site Type: Other

Affiliation Records:
Site Id: 28780
Affiliation Type: Mail Contact
Company Name: 46-20 27TH STREET LLC
Contact Type: Not reported

46-20 27TH STREET LLC (Continued) **A100183492**

Contact Name:	SHAHRAM NASSI
Address1:	54 EAST 11TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 777-9131
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	8/8/2007

Site Id:	28780
Affiliation Type:	On-Site Operator
Company Name:	46-20 27TH STREET LLC
Contact Type:	Not reported
Contact Name:	SHAHRAM NASSI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 777-9131
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	8/8/2007

Site Id:	28780
Affiliation Type:	Emergency Contact
Company Name:	46-20 27TH STREET LLC % SHAHRAM NASSI
Contact Type:	Not reported
Contact Name:	SHAHRAM NASSI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 777-9131
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	8/8/2007

Site Id:	28780
Affiliation Type:	Facility Owner
Company Name:	46-20 27TH STREET LLC % SHAHRAM NASSI
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	54 EAST 11TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003

46-20 27TH STREET LLC (Continued) **A100183492**

Country Code:	001
Phone:	(212) 777-9131
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	8/8/2007

Tank Info:

Tank Number:	001
Tank Id:	62051
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

I00 - Overfill - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
A00 - Tank Internal Protection - None
G10 - Tank Secondary Containment - Impervious Underlayment
B00 - Tank External Protection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/01/2006
Register:	True
Modified By:	NRLOMBAR
Last Modified:	08/08/2007
Material Name:	Waste Oil/Used Oil

144
NW
1/8-1/4
0.202 mi.
1066 ft.

PARKING LOT **NY UST** **U001831742**
23-14 44TH ROAD **NY HIST UST** **N/A**
LONG ISLAND CITY, NY 11101

Relative:
Higher

Actual:
17 ft.

UST:

Id/Status:	2-064319 / Unregulated
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589101.66958999995
UTM Y:	4511360.8470999999
Site Type:	Other

Affiliation Records:

Site Id:	1335

PARKING LOT (Continued) **U001831742**

Affiliation Type:	Facility Owner
Company Name:	PERENNIALLY GREEN, INC.
Contact Type:	VICE PRESIDENT
Contact Name:	BRAIN M. MACDONALD
Address1:	23-14, 44TH RD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(212) 615-8027
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	9/20/2005

Site Id:	1335
Affiliation Type:	Mail Contact
Company Name:	PERENNIALLY GREEN, INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	C/O ALONSO ANDALKAR & KAHN
Address2:	920 BROADWAY, 16TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10010
Country Code:	001
Phone:	(212) 598-5900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	9/20/2005

Site Id:	1335
Affiliation Type:	On-Site Operator
Company Name:	PARKING LOT
Contact Type:	Not reported
Contact Name:	PERENIALLY GREEN, INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 615-8027
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	9/20/2005

Site Id:	1335
Affiliation Type:	Emergency Contact
Company Name:	PERENNIALLY GREEN, INC.
Contact Type:	Not reported
Contact Name:	KEITH OWEN
Address1:	Not reported
Address2:	Not reported

PARKING LOT (Continued) **U001831742**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 248-4939
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	9/20/2005

Tank Info:

Tank Number:	001
Tank ID:	2371
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1500
Install Date:	Not reported
Date Tank Closed:	01/01/1988
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	09/20/2005

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I00 - Overfill - None

Tank Number:	002
Tank ID:	2372
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1500
Install Date:	Not reported
Date Tank Closed:	01/01/1988
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN

PARKING LOT (Continued) **U001831742**

Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 09/20/2005

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None

Tank Number: 003
Tank ID: 2373
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1500
Install Date: Not reported
Date Tank Closed: 01/01/1988
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 09/20/2005

Equipment Records:

H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None

HIST UST:
PBS Number: 2-064319
SPDES Number: Not reported
Emergency Contact: ROBERT OUMANO
Emergency Telephone: (718) 784-1035
Operator: FRANCO-AMERICAN NOVELTY CO INC
Operator Telephone: (718) 784-1035

PARKING LOT (Continued) **U001831742**

Owner Name:	ROBERT OUMANO
Owner Address:	23-14 44TH ROAD
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Owner Telephone:	(718) 784-1035
Owner Type:	Not reported
Owner Subtype:	Not reported
Mailing Name:	CITICORP
Mailing Address:	23-14 44TH ROAD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	LON ISLAND CITY, NY 11101
Mailing Contact:	Not reported
Mailing Telephone:	(718) 784-1035
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	23014 44TH ROAD
SWIS ID:	6301
Old PBS Number:	Not reported
Facility Type:	Not reported
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	01/14/1987
Expiration Date:	01/14/1992
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	4500
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	True
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City:	01
Region:	2
Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (gals):	1500
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported

PARKING LOT (Continued) **U001831742**

Dispenser: Gravity
Date Tested: Not reported
Next Test Date: 12/27/1987
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
Lat/long: Not reported

Tank Id: 002
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (gals): 1500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: None
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: Not reported
Next Test Date: 12/27/1987
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
Lat/long: Not reported

Tank Id: 003
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (gals): 1500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: None
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: Not reported
Next Test Date: 12/27/1987

PARKING LOT (Continued) **U001831742**

Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
Lat/long:	Not reported

X145 **EDR US Hist Auto Stat** **1015488529**
North **4235 CRESCENT ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.203 mi.
1071 ft. **Site 4 of 6 in cluster X**

Relative:
Higher

Actual:
18 ft.

EDR Historical Auto Stations:

Name:	MALTA COLLISION
Year:	2005
Address:	4235 CRESCENT ST
Name:	MALTA COLLISION
Year:	2006
Address:	4235 CRESCENT ST
Name:	MALTA COLLISION
Year:	2007
Address:	4235 CRESCENT ST
Name:	MALTA COLLISION
Year:	2008
Address:	4235 CRESCENT ST
Name:	MALTA COLLISION
Year:	2011
Address:	4235 CRESCENT ST
Name:	MALTA COLLISION
Year:	2012
Address:	4235 CRESCENT ST

V146 **MTA NYCT - JACKSON & WEST SUBSTA SS 26** **RCRA-CESQG** **1001818289**
NE **28-20 JACKSON AVE** **FINDS** **NYR000078238**
1/8-1/4 **LONG ISLAND CITY, NY** **NJ MANIFEST**
0.208 mi. **NY MANIFEST**
1097 ft. **Site 2 of 2 in cluster V**

Relative:
Higher

Actual:
18 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	MTA NYCT - JACKSON & WEST SUBSTA SS 26
Facility address:	28-20 JACKSON AVE LONG ISLAND CITY, NY 11101
EPA ID:	NYR000078238
Mailing address:	BROADWAY 3RD FLOOR NEW YORK, NY 10004
Contact:	WILLIAM JEHLE
Contact address:	BROADWAY 3RD FLOOR NEW YORK, NY 10004
Contact country:	US

MTA NYCT - JACKSON & WEST SUBSTA SS 26 (Continued) **1001818289**

Contact telephone: (646) 252-3500
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: MTA NEW YORK CITY TRANSIT
Owner/operator address: 2 BROADWAY 3RD FLOOR
NEW YORK, NY 10019
Owner/operator country: US
Owner/operator telephone: (646) 252-3500
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MTA NEW YORK CITY TRANSIT
Owner/operator address: 2 BROADWAY 3RD FLOOR
NEW YORK, NY 10019
Owner/operator country: US
Owner/operator telephone: (646) 252-3500
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

MTA NYCT - JACKSON & WEST SUBSTA SS 26 (Continued) **1001818289**

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: MTA NYCT - JACKSON & WEST SUBSTA SS 26
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/22/2000
Facility name: MTA NYCT - JACKSON & WEST SUBSTA SS 26
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004557391

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NJ MANIFEST:

Manifest Code:	NJA5028151
EPA ID:	NYR000078238
Date Shipped:	09/13/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/13/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/13/2004
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	Not reported
Transporter-1 EPA Facility Name:	Not reported
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported

MTA NYCT - JACKSON & WEST SUBSTA SS 26 (Continued) **1001818289**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	12170422
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

NY MANIFEST:

EPA ID:	NYR000078238
Country:	USA
Mailing Name:	NYCTA
Mailing Contact:	EVA MOUSSA
Mailing Address:	2 BROADWAY 2ND FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	646-252-3789

Document ID:	NYB6716025
Manifest Status:	Not reported
Trans1 State ID:	57994JL
Trans2 State ID:	Not reported
Generator Ship Date:	08/19/2004
Trans1 Recv Date:	08/19/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/20/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000078238
Trans1 EPA ID:	NY0000148163
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00300
Units:	P - Pounds
Number of Containers:	003

MTA NYCT - JACKSON & WEST SUBSTA SS 26 (Continued) **1001818289**

Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2004

Document ID:	NJA5028151
Manifest Status:	Not reported
Trans1 State ID:	S8424
Trans2 State ID:	Not reported
Generator Ship Date:	09/13/2004
Trans1 Recv Date:	09/13/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/13/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000078238
Trans1 EPA ID:	NYD046765574
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	01200
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2004

X147 **EDR US Hist Auto Stat** **1015488482**
North **4233 CRESCENT ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.209 mi.
1101 ft. **Site 5 of 6 in cluster X**

Relative:
Higher

Actual:
18 ft.

EDR Historical Auto Stations:

Name:	NICK & CHARLIES AUTO REPAIR
Year:	1999
Address:	4233 CRESCENT ST
Name:	NICK & CHARLIES AUTO REPAIR
Year:	2000
Address:	4233 CRESCENT ST
Name:	JOHNS AUTO CTR
Year:	2001
Address:	4233 CRESCENT ST
Name:	MALTA COLLISION INC
Year:	2002
Address:	4233 CRESCENT ST
Name:	MALTA COLLISION INC
Year:	2003
Address:	4233 CRESCENT ST
Name:	QUEEN PLAZA AUTO REPAIR
Year:	2004

(Continued) **1015488482**

Address: 4233 CRESCENT ST

Name: MALTA COLLISION INC
Year: 2006
Address: 4233 CRESCENT ST

Name: MALTA COLLISION INC
Year: 2009
Address: 4233 CRESCENT ST

Name: MALTA COLLISION INCORPORATED
Year: 2011
Address: 4233 CRESCENT ST

Name: MALTA COLLISION INC
Year: 2012
Address: 4233 CRESCENT ST

W148 **KOREA NEWS** **RCRA-SQG** **1000694281**
NNE **42-22 27TH ST** **FINDS** **NYD987005857**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **NY MANIFEST**
0.214 mi.
1128 ft. **Site 3 of 4 in cluster W**

Relative:
Higher

Actual:
19 ft.

RCRA-SQG:
Date form received by agency: 01/01/2007
Facility name: KOREA NEWS
Facility address: 42-22 27TH ST
LONG ISLAND CITY, NY 11101
EPA ID: NYD987005857
Mailing address: 27TH ST
LONG ISLAND CITY, NY 11101
Contact: LEE KYUNG
Contact address: 27TH ST
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: (212) 555-1212
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: KOREA NEWS
Owner/operator address: 42-22 27TH ST
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 482-1111
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

KOREA NEWS (Continued) **1000694281**

Owner/operator name: KOREA NEWS
Owner/operator address: 42-22 27TH ST
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 482-1111
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: KOREA NEWS
Classification: Small Quantity Generator

Date form received by agency: 06/12/1992
Facility name: KOREA NEWS
Classification: Small Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: TSD IS-Preparedness and Prevention
Date violation determined: 07/30/2010
Date achieved compliance: 08/13/2010
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/16/2010
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 09/16/2010
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 07/30/2010
Date achieved compliance: 08/16/2010
Violation lead agency: State

KOREA NEWS (Continued) **1000694281**

Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/16/2010
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 09/16/2010
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Container Use and Management
Date violation determined: 07/30/2010
Date achieved compliance: 07/30/2010
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/16/2010
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 09/16/2010
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Container Use and Management
Date violation determined: 07/30/2010
Date achieved compliance: 08/13/2010
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/16/2010
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 09/16/2010
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 07/30/2010
Date achieved compliance: 08/16/2010
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/16/2010
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 09/16/2010
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 07/30/2010
Date achieved compliance: 08/16/2010
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL

KOREA NEWS (Continued) **1000694281**

Enforcement action date: 09/16/2010
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 09/16/2010
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 07/30/2010
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Preparedness and Prevention
Date achieved compliance: 08/13/2010
Evaluation lead agency: State

Evaluation date: 07/30/2010
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 08/16/2010
Evaluation lead agency: State

Evaluation date: 07/30/2010
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Container Use and Management
Date achieved compliance: 08/13/2010
Evaluation lead agency: State

Evaluation date: 07/30/2010
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 08/16/2010
Evaluation lead agency: State

Evaluation date: 07/30/2010
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/16/2010
Evaluation lead agency: State

Evaluation date: 07/30/2010
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Container Use and Management
Date achieved compliance: 07/30/2010
Evaluation lead agency: State

FINDS:

Registry ID: 110004491292

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

KOREA NEWS (Continued) **1000694281**

NY MANIFEST:

EPA ID:	NYD987005857
Country:	USA
Mailing Name:	KOREA NEWS
Mailing Contact:	KOREA NEWS
Mailing Address:	42-22 27TH ST
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-482-1111

Document ID:	NJA1828461
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPE086
Trans2 State ID:	Not reported
Generator Ship Date:	940701
Trans1 Recv Date:	940701
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	940706
Part A Recv Date:	Not reported
Part B Recv Date:	940715
Generator EPA ID:	NYD987005857
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00988
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	94

Document ID:	NJA2055469
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPE086
Trans2 State ID:	Not reported
Generator Ship Date:	950209
Trans1 Recv Date:	950209
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950209
Part A Recv Date:	Not reported
Part B Recv Date:	950222
Generator EPA ID:	NYD987005857
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00988
Units:	P - Pounds
Number of Containers:	002

KOREA NEWS (Continued) **1000694281**

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: NJA2693878
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 08690
Trans2 State ID: Not reported
Generator Ship Date: 961018
Trans1 Recv Date: 961018
Trans2 Recv Date: Not reported
TSD Site Recv Date: 961023
Part A Recv Date: 961106
Part B Recv Date: 961114
Generator EPA ID: NYD987005857
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: D011 - SILVER 5.0 MG/L TCLP
Quantity: 00495
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 96

Document ID: NJA2521321
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 08690
Trans2 State ID: 00602
Generator Ship Date: 960726
Trans1 Recv Date: 960726
Trans2 Recv Date: 960730
TSD Site Recv Date: 960730
Part A Recv Date: Not reported
Part B Recv Date: 960821
Generator EPA ID: NYD987005857
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: NYD980769947
TSDF ID: NJD002182897
Waste Code: D011 - SILVER 5.0 MG/L TCLP
Quantity: 00495
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 96

Document ID: NJA2221692
Manifest Status: Completed copy
Trans1 State ID: 08690

KOREA NEWS (Continued) **1000694281**

Trans2 State ID:	Not reported
Generator Ship Date:	960403
Trans1 Recv Date:	960403
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	960411
Part A Recv Date:	960410
Part B Recv Date:	960426
Generator EPA ID:	NYD987005857
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00495
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	96

Document ID:	NJA2085380
Manifest Status:	Completed copy
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	960503
Trans1 Recv Date:	960503
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	960507
Part A Recv Date:	960509
Part B Recv Date:	960521
Generator EPA ID:	NYD987005857
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00990
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	96

Document ID:	NJA4013876
Manifest Status:	Not reported
Trans1 State ID:	SCR000075150
Trans2 State ID:	Not reported
Generator Ship Date:	01/14/2002
Trans1 Recv Date:	01/14/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/18/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987005857
Trans1 EPA ID:	NJD002182897

KOREA NEWS (Continued) **1000694281**

Trans2 EPA ID:	Not reported
TSDF ID:	08690
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00480
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2002

Document ID:	NYC7197210
Manifest Status:	Not reported
Trans1 State ID:	NY83381JN
Trans2 State ID:	NJ044T465
Generator Ship Date:	02/19/2004
Trans1 Recv Date:	02/19/2004
Trans2 Recv Date:	02/24/2004
TSD Site Recv Date:	03/01/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987005857
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00400
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYC7212148
Manifest Status:	Not reported
Trans1 State ID:	NY83318JN
Trans2 State ID:	Not reported
Generator Ship Date:	04/19/2004
Trans1 Recv Date:	04/19/2004
Trans2 Recv Date:	04/23/2004
TSD Site Recv Date:	04/29/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987005857
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00700
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

KOREA NEWS (Continued) **1000694281**

Year: 2004

Document ID: NYC7247035
Manifest Status: Not reported
Trans1 State ID: NY55817L
Trans2 State ID: T465GLNJ
Generator Ship Date: 08/16/2004
Trans1 Recv Date: 08/16/2004
Trans2 Recv Date: 08/20/2004
TSD Site Recv Date: 08/30/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987005857
Trans1 EPA ID: TXR000050930
Trans2 EPA ID: Not reported
TSDF ID: KYD053348
Waste Code: D011 - SILVER 5.0 MG/L TCLP
Quantity: 00800
Units: P - Pounds
Number of Containers: 007
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2004

Document ID: NYC7248126
Manifest Status: Not reported
Trans1 State ID: NYAT8305
Trans2 State ID: NJT16L8D
Generator Ship Date: 10/25/2004
Trans1 Recv Date: 10/25/2004
Trans2 Recv Date: 10/29/2004
TSD Site Recv Date: 11/07/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987005857
Trans1 EPA ID: TXR000050930
Trans2 EPA ID: Not reported
TSDF ID: KYD053348
Waste Code: D003 - NON-LISTED REACTIVE WASTES
Quantity: 00800
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2004

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 2008-09-10
Trans1 Recv Date: 2008-09-10

KOREA NEWS (Continued) **1000694281**

Trans2 Recv Date:	2008-09-16
TSD Site Recv Date:	2008-09-16
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987005857
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	Not reported
Quantity:	900.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000124881SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2008-02-27
Trans1 Recv Date:	2008-02-27
Trans2 Recv Date:	2008-02-28
TSD Site Recv Date:	2008-03-01
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987005857
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	1200.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000083187SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N

KOREA NEWS (Continued) **1000694281**

Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2008-06-20
Trans1 Recv Date:	2008-06-20
Trans2 Recv Date:	2008-06-26
TSD Site Recv Date:	2008-07-08
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987005857
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	1600.0
Units:	P - Pounds
Number of Containers:	4.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	001253079SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2008-03-21
Trans1 Recv Date:	2008-03-21
Trans2 Recv Date:	2008-04-04
TSD Site Recv Date:	2008-04-04
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987005857
Trans1 EPA ID:	Not reported

KOREA NEWS (Continued) **1000694281**

Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	Not reported
Quantity:	400.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000124880SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2008-02-27
Trans1 Recv Date:	2008-02-27
Trans2 Recv Date:	2008-02-28
TSD Site Recv Date:	2008-03-01
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987005857
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	1200.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000083187SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

KOREA NEWS (Continued) **1000694281**

Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 2008-09-10
Trans1 Recv Date: 2008-09-10
Trans2 Recv Date: 2008-09-16
TSD Site Recv Date: 2008-09-16
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987005857
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: Not reported
Quantity: 900.0
Units: P - Pounds
Number of Containers: 3.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2008
Manifest Tracking Num: 000124881SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 2008-03-21
Trans1 Recv Date: 2008-03-21
Trans2 Recv Date: 2008-04-04
TSD Site Recv Date: 2008-04-04
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987005857
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: Not reported
Quantity: 400.0
Units: P - Pounds
Number of Containers: 1.0

KOREA NEWS (Continued) **1000694281**

Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000124880SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2008-06-20
Trans1 Recv Date:	2008-06-20
Trans2 Recv Date:	2008-06-26
TSD Site Recv Date:	2008-07-08
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987005857
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	1600.0
Units:	P - Pounds
Number of Containers:	4.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	001253079SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930

KOREA NEWS (Continued) **1000694281**

Trans2 State ID:	OKD981588791
Generator Ship Date:	2008-11-05
Trans1 Recv Date:	2008-11-05
Trans2 Recv Date:	2008-11-12
TSD Site Recv Date:	2008-11-14
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987005857
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	600.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000124888SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Click this hyperlink while viewing on your computer to access
80 additional NY_MANIFEST: record(s) in the EDR Site Report.

W149 **KOREA NEWS** **NJ MANIFEST** **S109533774**
NNE **42-22 27TH ST** **N/A**
1/8-1/4 **LONG ISLAND, NY 11101**
0.214 mi.
1128 ft. **Site 4 of 4 in cluster W**

Relative:
Higher

Actual:
19 ft.

NJ MANIFEST:

Manifest Code:	002592048SKS
EPA ID:	NYD987005857
Date Shipped:	11/4/2011
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

KOREA NEWS (Continued) **S109533774**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	KOREA NEWS
Transporter-1 EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDF EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
QTY Units:	Pounds
Transporter SEQ ID:	1.00
Transporter-1 Date:	11/4/2011
Waste SEQ ID:	1.00
Waste Type Code 2:	D011
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	11/14/2011
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	Not reported
Reason Load Was Rejected:	Not reported
Waste Code:	D002
Manifest Year:	2011 New Jersey Manifest Data
Quantity:	800.00
Unit:	Pounds
Hand Code:	H141

Manifest Code:	002593605SKS
EPA ID:	NYD987005857
Date Shipped:	7/29/2011
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

KOREA NEWS (Continued) **S109533774**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	KOREA NEWS
Transporter-1 EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDF EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
QTY Units:	Pounds
Transporter SEQ ID:	1.00
Transporter-1 Date:	7/29/2011
Waste SEQ ID:	1.00
Waste Type Code 2:	D011
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	8/8/2011
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	Not reported
Reason Load Was Rejected:	Not reported
Waste Code:	D002
Manifest Year:	2011 New Jersey Manifest Data
Quantity:	1,200.00
Unit:	Pounds
Hand Code:	H141

Manifest Code:	002595858SKS
EPA ID:	NYD987005857
Date Shipped:	9/6/2011
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported

KOREA NEWS (Continued) **S109533774**

Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	KOREA NEWS
Transporter-1 EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDF EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
QTY Units:	Pounds
Transporter SEQ ID:	1.00
Transporter-1 Date:	9/6/2011
Waste SEQ ID:	1.00
Waste Type Code 2:	D011
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	9/15/2011
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	Not reported
Reason Load Was Rejected:	Not reported
Waste Code:	D002
Manifest Year:	2011 New Jersey Manifest Data
Quantity:	400.00
Unit:	Pounds
Hand Code:	H141

Manifest Code:	000124881SKS
EPA ID:	NYD987005857
Date Shipped:	09/10/2008
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	NJD071629976
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/10/2008
Date Trans2 Transported Waste:	09/16/2008
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

KOREA NEWS (Continued) **S109533774**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/16/2008
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	Not reported
Transporter-1 EPA Facility Name:	Not reported
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D001
Manifest Year:	2008 New Jersey Manifest Data
Quantity:	900
Unit:	P
Hand Code:	H061

Manifest Code:	000124880SKS
EPA ID:	NYD987005857
Date Shipped:	03/21/2008
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	NJD071629976
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/21/2008
Date Trans2 Transported Waste:	04/04/2008
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported

KOREA NEWS (Continued) **S109533774**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/09/2008
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	Not reported
Transporter-1 EPA Facility Name:	Not reported
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D001
Manifest Year:	2008 New Jersey Manifest Data
Quantity:	400
Unit:	P
Hand Code:	H061

X150 **EDR US Hist Cleaners** **1015059399**
North **4231 CRESCENT ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.214 mi.
1131 ft. **Site 6 of 6 in cluster X**

Relative:
Higher

Actual:
18 ft.

EDR Historical Cleaners:

Name:	CLEANING & RESTORATION
Year:	2003
Address:	4231 CRESCENT ST
Name:	CLEANING & RESTORATION
Year:	2004
Address:	4231 CRESCENT ST
Name:	CLEANING & RESTORATION
Year:	2005
Address:	4231 CRESCENT ST
Name:	CLEANING & RESTORATION
Year:	2006
Address:	4231 CRESCENT ST

151
NW
1/8-1/4
0.216 mi.
1142 ft.

BRANCO LEATHER INC
44-02 23RD ST
LONG ISLAND CITY, NY 11101

NY AST **U003384065**
NY HIST AST **N/A**

Relative:
Higher

Actual:
17 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-081345
Program Type:	PBS
UTM X:	589109.69863
UTM Y:	4511409.3499100003
Expiration Date:	2012/03/24
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	1694
Affiliation Type:	Mail Contact
Company Name:	BRANCO LEATHER INC.
Contact Type:	Not reported
Contact Name:	BERNARDO DRUKER
Address1:	4402 23RD ST
Address2:	STUDIO #18 5TH FLOOR
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 361-1401
EMail:	LICARTCENTER@AOL.COM
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2/20/2007

Site Id:	1694
Affiliation Type:	On-Site Operator
Company Name:	BRANCO LEATHER INC
Contact Type:	Not reported
Contact Name:	EDGAR PEREZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 361-1401
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2/20/2007

Site Id:	1694
Affiliation Type:	Emergency Contact
Company Name:	BERNARDO DRUKER
Contact Type:	Not reported
Contact Name:	EDGAR PEREZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported

BRANCO LEATHER INC (Continued) **U003384065**

State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 361-1401
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2/20/2007

Site Id:	1694
Affiliation Type:	Facility Owner
Company Name:	BERNARDO DRUKER
Contact Type:	PRESIDENT
Contact Name:	BERNARDO DRUKER
Address1:	44-02 23RD ST
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 361-1401
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2/20/2007

Tank Info:

Tank Number:	001
Tank Id:	2905
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

F02 - Pipe External Protection - Original Sacrificial Anode
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Location:	1
Tank Type:	Steel Tank in Concrete
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	07/15/1981
Capacity Gallons:	7500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

BRANCO LEATHER INC (Continued) **U003384065**

Date Tank Closed:	Not reported
Register:	True
Modified By:	DXLIVING
Last Modified:	02/20/2007
Material Name:	#2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number:	2-081345
SWIS Code:	6301
Operator:	EDGAR PEREZ
Facility Phone:	(718) 361-1114
Facility Addr2:	44002 23RD ST
Facility Type:	MANUFACTURING
Emergency:	EDGAR PEREZ
Emergency Tel:	(718) 361-1114
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	BERNARDO DRUKER
Owner Address:	44-02 23RD ST
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Federal ID:	Not reported
Owner Tel:	(718) 361-1114
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	Not reported
Mailing Name:	BERNARDO DRUKER
Mailing Address:	44-02 23RD ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	LONG ISLAND CITY, NY 11101
Mailing Telephone:	(718) 361-1114
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	12/28/2001
Expiration:	03/24/2007
Renew Flag:	False
Renew Date:	11/13/2001
Total Capacity:	7500
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported

BRANCO LEATHER INC (Continued) **U003384065**

Capacity (Gal):	7500
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	None
Leak Detection:	0
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
SPDES Number:	Not reported
Lat/Long:	Not reported

---

152 **SUBACCHI FURNITYRE-46-24 28TH ST** **RCRA-CESQG** **1000144031**
SSE **46-24 28TH STREET** **NY MANIFEST** **NYD045440997**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **US AIRS**
0.216 mi.
1143 ft.

Relative:
Higher

Actual:
15 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	SUBACCHI FURNITURE
Facility address:	46-24 28TH ST LONG ISLAND CITY, NY 11101
EPA ID:	NYD045440997
Mailing address:	28TH ST LONG ISLAND CITY, NY 11101
Contact:	STEPHEN VOLPE
Contact address:	28TH ST LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	(718) 361-0551
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from

SUBACCHI FURNITYRE-46-24 28TH ST (Continued) **1000144031**

the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: STEPHEN VOLPE
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: STEPHEN VOLPE
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: SUBACCHI FURNITURE
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 06/02/1986
Facility name: SUBACCHI FURNITURE
Classification: Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 07/23/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

SUBACCHI FURNITYRE-46-24 28TH ST (Continued) **1000144031**

Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

NY MANIFEST:
EPA ID: NYD045440997
Country: USA
Mailing Name: SUBACCHI FURNITURE
Mailing Contact: SUBACCHI FURNITURE
Mailing Address: 46-24 28TH STREET
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-361-0551

Document ID: NJA0381442
Manifest Status: Completed copy
Trans1 State ID: NJDEPS-10
Trans2 State ID: Not reported
Generator Ship Date: 880106
Trans1 Recv Date: 880106
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880106
Part A Recv Date: 880115
Part B Recv Date: 880114
Generator EPA ID: NYD045440997
Trans1 EPA ID: NJD980787147
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: F005 - UNKNOWN
Quantity: 00135
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 88

Document ID: NJA0628795
Manifest Status: Completed copy
Trans1 State ID: NJDEPS103
Trans2 State ID: Not reported
Generator Ship Date: 890912
Trans1 Recv Date: 890912
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890912
Part A Recv Date: 890918
Part B Recv Date: 890922
Generator EPA ID: NYD045440997
Trans1 EPA ID: NJD980787147
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: F005 - UNKNOWN

SUBACCHI FURNITYRE-46-24 28TH ST (Continued) **1000144031**

Quantity:	00160
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	89

Document ID:	NJA0629429
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	891206
Trans1 Recv Date:	891206
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	891207
Part A Recv Date:	891211
Part B Recv Date:	891218
Generator EPA ID:	NYD045440997
Trans1 EPA ID:	NJD980787147
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F005 - UNKNOWN
Quantity:	00200
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	89

Document ID:	NJA0840449
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPS103
Trans2 State ID:	Not reported
Generator Ship Date:	900306
Trans1 Recv Date:	900306
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900306
Part A Recv Date:	900327
Part B Recv Date:	900402
Generator EPA ID:	NYD045440997
Trans1 EPA ID:	NJD980787147
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F005 - UNKNOWN
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	90

SUBACCHI FURNITYRE-46-24 28TH ST (Continued) **1000144031**

Document ID:	NJA0977216
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPS103
Trans2 State ID:	Not reported
Generator Ship Date:	910115
Trans1 Recv Date:	910115
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910115
Part A Recv Date:	910131
Part B Recv Date:	910212
Generator EPA ID:	NYD045440997
Trans1 EPA ID:	NJD980787147
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F003 - UNKNOWN
Quantity:	00085
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	91

Document ID:	NYH0127674
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	07/13/2000
Trans1 Recv Date:	07/13/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/13/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD045440997
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	PW8913
Waste Code:	F003 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYH0153108
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	10/26/2000
Trans1 Recv Date:	10/26/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/26/2000
Part A Recv Date:	Not reported

SUBACCHI FURNITYRE-46-24 28TH ST (Continued) **1000144031**

Part B Recv Date: Not reported
Generator EPA ID: NYD045440997
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: PX3640
Waste Code: F003 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYH0152127
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: Not reported
Generator Ship Date: 10/19/2000
Trans1 Recv Date: 10/19/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/19/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD045440997
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: PX3640
Waste Code: F003 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2000

Document ID: NJA0229734
Manifest Status: Completed copy
Trans1 State ID: NJDEPS-10
Trans2 State ID: Not reported
Generator Ship Date: 860922
Trans1 Recv Date: 860922
Trans2 Recv Date: Not reported
TSD Site Recv Date: 860923
Part A Recv Date: 860929
Part B Recv Date: 860930
Generator EPA ID: NYD045440997
Trans1 EPA ID: NJD980787147
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00115
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001

SUBACCHI FURNITYRE-46-24 28TH ST (Continued) **1000144031**

Container Type: TT - Cargo tank, tank trucks
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 86

Document ID: NJA0271998
Manifest Status: Completed copy
Trans1 State ID: NJDEPS-10
Trans2 State ID: Not reported
Generator Ship Date: 880620
Trans1 Recv Date: 880620
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880621
Part A Recv Date: 880628
Part B Recv Date: 880701
Generator EPA ID: NYD045440997
Trans1 EPA ID: NJD980787147
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: F005 - UNKNOWN
Quantity: 00120
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 88

Document ID: NJA0297475
Manifest Status: Completed copy
Trans1 State ID: NJDEPS-10
Trans2 State ID: Not reported
Generator Ship Date: 880907
Trans1 Recv Date: 880907
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880907
Part A Recv Date: 880913
Part B Recv Date: 880913
Generator EPA ID: NYD045440997
Trans1 EPA ID: NJD980787147
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: F005 - UNKNOWN
Quantity: 00105
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 88

Document ID: NYB8311671
Manifest Status: Completed copy
Trans1 State ID: PD9938

SUBACCHI FURNITYRE-46-24 28TH ST (Continued) **1000144031**

Trans2 State ID: Not reported
Generator Ship Date: 961206
Trans1 Recv Date: 961206
Trans2 Recv Date: Not reported
TSD Site Recv Date: 961206
Part A Recv Date: 961230
Part B Recv Date: 961224
Generator EPA ID: NYD045440997
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: F005 - UNKNOWN
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 089
Year: 96

Document ID: NYG0359217
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: Not reported
Generator Ship Date: 03/04/1998
Trans1 Recv Date: 03/04/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/04/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD045440997
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: PX3640
Waste Code: F005 - UNKNOWN
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 98

Document ID: NYH0371439
Manifest Status: Not reported
Trans1 State ID: 62096PA
Trans2 State ID: Not reported
Generator Ship Date: 07/12/2004
Trans1 Recv Date: 07/12/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/12/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD045440997
Trans1 EPA ID: NYD082785429

SUBACCHI FURNITYRE-46-24 28TH ST (Continued) **1000144031**

Trans2 EPA ID: Not reported
TSDF ID: NYD082785
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2004

Document ID: NYH0479835
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: Not reported
Generator Ship Date: 01/11/2005
Trans1 Recv Date: 01/11/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/11/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD045440997
Trans1 EPA ID: 70600JR
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: F003 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: Not reported

Document ID: NJA0139770
Manifest Status: Completed copy
Trans1 State ID: S-10339
Trans2 State ID: Not reported
Generator Ship Date: 860623
Trans1 Recv Date: 860623
Trans2 Recv Date: Not reported
TSD Site Recv Date: 860623
Part A Recv Date: 860701
Part B Recv Date: 860701
Generator EPA ID: NYD045440997
Trans1 EPA ID: NJD980787147
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00135
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100

SUBACCHI FURNITYRE-46-24 28TH ST (Continued) **1000144031**

Year: 86

Document ID: NJA0288027
Manifest Status: Completed copy
Trans1 State ID: NJDEPS-10
Trans2 State ID: Not reported
Generator Ship Date: 870505
Trans1 Recv Date: 870505
Trans2 Recv Date: Not reported
TSD Site Recv Date: 870505
Part A Recv Date: 870507
Part B Recv Date: 870512
Generator EPA ID: NYD045440997
Trans1 EPA ID: NJD980787147
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00140
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 87

Document ID: NJA0253789
Manifest Status: Completed copy
Trans1 State ID: DECAL#990
Trans2 State ID: Not reported
Generator Ship Date: 861203
Trans1 Recv Date: 861203
Trans2 Recv Date: Not reported
TSD Site Recv Date: 861204
Part A Recv Date: 861209
Part B Recv Date: 861210
Generator EPA ID: NYD045440997
Trans1 EPA ID: NJD980787147
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00105
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 86

Document ID: NJA1009739
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 900619
Trans1 Recv Date: 900619

SUBACCHI FURNITYRE-46-24 28TH ST (Continued) **1000144031**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900619
Part A Recv Date:	900817
Part B Recv Date:	900627
Generator EPA ID:	NYD045440997
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F005 - UNKNOWN
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	90

Document ID:	NYG0021375
Manifest Status:	Completed copy
Trans1 State ID:	14467AK
Trans2 State ID:	Not reported
Generator Ship Date:	970318
Trans1 Recv Date:	970318
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	970318
Part A Recv Date:	970325
Part B Recv Date:	970327
Generator EPA ID:	NYD045440997
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	F005 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	089
Year:	97

Click this hyperlink while viewing on your computer to access
24 additional NY_MANIFEST: record(s) in the EDR Site Report.

AIRS (AFS):

Airs Minor Details:

EPA plant ID:	110012644193
Plant name:	SUBACCHI FURNITYRE-46-24 28TH ST
Plant address:	46-24 28TH STREET LONG ISLAND CITY, NY 11101
County:	QUEENS
Region code:	02
Dunn & Bradst #:	Not reported
Air quality cntrl region:	043
Sic code:	2499

SUBACCHI FURNITYRE-46-24 28TH ST (Continued) **1000144031**

Sic code desc: WOOD PRODUCTS, NEC
North Am. industrial classf: Not reported
NAIC code description: Not reported
Default compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Default classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Govt facility: ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT
Current HPV: Not reported

Historical Compliance Minor Sources:

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1002
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1004
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1102
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1001
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1003
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1101
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1103
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204

SUBACCHI FURNITYRE-46-24 28TH ST (Continued) **1000144031**

Air prog code hist file: SIP SOURCE

Compliance & Violation Data by Minor Sources:
Air program code: SIP SOURCE
Plant air program pollutant: VOLATILE ORGANIC COMPOUNDS
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: Not reported
Repeat violator date: Not reported
Turnover compliance: Not reported

Y153 **MICHELANGELO SCULPTURE** **RCRA NonGen / NLR** **1004761796**
SSE **27-01 47TH AVE** **FINDS** **NYR000090498**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **NY MANIFEST**
0.218 mi.
1151 ft. **Site 3 of 3 in cluster Y**

Relative:
Lower

Actual:
12 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: MICHELANGELO SCULPTURE
Facility address: 27-01 47TH AVE
LONG ISLAND CITY, NY 11101
EPA ID: NYR000090498
Mailing address: PRINCE ST
NEW YORK, NY 11012
Contact: DOMENICO RANIERI
Contact address: PRINCE ST
NEW YORK, NY 11012
Contact country: US
Contact telephone: (212) 982-5150
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: DOMENICO RANIERI
Owner/operator address: 55 PRINCE ST
NEW YORK, NY 11012
Owner/operator country: US
Owner/operator telephone: (212) 982-5150
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: DOMENICO RANIERI
Owner/operator address: 55 PRINCE ST
NEW YORK, NY 11012
Owner/operator country: US
Owner/operator telephone: (212) 982-5150
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

MICHELANGELO SCULPTURE (Continued) **1004761796**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: MICHELANGELO SCULPTURE
Classification: Not a generator, verified

Date form received by agency: 10/13/2000
Facility name: MICHELANGELO SCULPTURE
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004565015

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000090498
Country: USA
Mailing Name: MICHELANGELO SCULPTURE
Mailing Contact: DOMENICO KANIERI
Mailing Address: 27-01 47TH AVE
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-982-5150

MICHELANGELO SCULPTURE (Continued) **1004761796**

Document ID:	NYG1812807
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	10/20/2000
Trans1 Recv Date:	10/20/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000090498
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00450
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	080
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00100
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Z154 **MID TOWN OPERATING COMPANY TTF** **NY LTANKS** **S110140580**
NNW **42-50 24TH ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY**
0.222 mi.
1170 ft. **Site 1 of 2 in cluster Z**

Relative:
Higher

Actual:
16 ft.

LTANKS:

Site ID:	424084
Spill Number/Closed Date:	0911288 / 1/21/2010
Spill Date:	1/20/2010
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	1/20/2010
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1/20/2010

MID TOWN OPERATING COMPANY TTF (Continued) **S110140580**

Spill Record Last Update:	1/21/2010
Spiller Name:	RON SHERMAN
Spiller Company:	MID TOWN OPERATING COMPANY
Spiller Address:	42-50 24TH ST
Spiller City,St,Zip:	LONG ISLAND CITY, NY
Spiller County:	999
Spiller Contact:	SHAWN KERRIGAN
Spiller Phone:	(610) 278-7203
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	373035
DEC Memo:	1/21/2010 Sangesland spoke to Shawn at Crompco. He said the tank failed a test yesterday and a spill report was called in. Today they isolated the tank and retested. He said the tank passed, but the "suction line inside the tank" failed. Sangesland asked Shawn to call back and talk directly to Jake Krimgold to determine if this can be closed out.1/21/10. J.Krimgold spoke to Shawn from Crompco. Agreed that the failure of the suction line inside the tank could not lead to a release. Case closed.
Remarks:	TANK TEST FAILURE ON A 4000 GALLON UST

Material:

Site ID:	424084
Operable Unit ID:	1179879
Operable Unit:	01
Material ID:	2173702
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

AA155 **CITY SPORTS & GRAPHIC** **RCRA NonGen / NLR** **1000990064**
WSW **45-12 DAVIS ST** **FINDS** **NYR000000232**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.224 mi.
1182 ft. **Site 1 of 3 in cluster AA**

Relative:
Lower

Actual:
9 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	CITY SPORTS & GRAPHIC
Facility address:	45-12 DAVIS ST LONG ISLAND CITY, NY 111014306
EPA ID:	NYR000000232
Mailing address:	DAVIS ST LONG ISLAND CITY, NY 11101
Contact:	Not reported
Contact address:	DAVIS ST LONG ISLAND CITY, NY 11101
Contact country:	US

CITY SPORTS & GRAPHIC (Continued) **1000990064**

Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: HYUNG HO KIM
Owner/operator address: 45-12 DAVIS ST
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 361-5240
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: HYUNG HO KIM
Owner/operator address: 45-12 DAVIS ST
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 361-5240
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: CITY SPORTS & GRAPHIC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: CITY SPORTS & GRAPHIC
Classification: Not a generator, verified

Date form received by agency: 02/22/1995
Facility name: CITY SPORTS & GRAPHIC

CITY SPORTS & GRAPHIC (Continued) **1000990064**

Classification: Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 11/19/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004511252

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AB156 **NYCT - FLUSHING AVENUE LINE (#7 LINE)** **RCRA-CESQG** **1005417217**
WSW **DAVIS & 23RD ST** **FINDS** **NYR000103416**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **NY MANIFEST**
0.224 mi.
1184 ft. **Site 1 of 2 in cluster AB**

Relative:
Lower

Actual:
12 ft.

RCRA-CESQG:
Date form received by agency: 01/01/2007
Facility name: NYCT - FLUSHING AVENUE LINE (#7 LINE)
Facility address: DAVIS & 23RD ST
LONG ISLAND CITY, NY 11101
EPA ID: NYR000103416
Mailing address: 370 JAY STREET, ROOM 819
BROOKLYN, NY 11201
Contact: JOSEPHINE F BROWN
Contact address: 370 JAY STREET, ROOM 819
BROOKLYN, NY 11201
Contact country: US
Contact telephone: (718) 243-4581
Contact email: JOBROWN4@NYCT.COM
EPA Region: 02
Land type: State
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of

NYCT - FLUSHING AVENUE LINE (#7 LINE) (Continued) **1005417217**

any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	NO NAME FOUND
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	06/01/1953
Owner/Op end date:	Not reported

Owner/operator name:	MTA NEW YORK CITY TRANSIT
Owner/operator address:	2 BROADWAY 3RD FL
	NEW YORK, NY 10004
Owner/operator country:	US
Owner/operator telephone:	(646) 252-3500
Legal status:	Other
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Facility name:	NYCT - FLUSHING AVENUE LINE (#7 LINE)
Classification:	Small Quantity Generator

Date form received by agency:	02/09/2004
Facility name:	NYCT - FLUSHING AVENUE LINE (#7 LINE)
Classification:	Large Quantity Generator

Date form received by agency:	01/17/2002
Facility name:	NYCT - FLUSHING AVENUE LINE (#7 LINE)
Site name:	MTA NYCT - FLUSHING LINE #7
Classification:	Large Quantity Generator

NYCT - FLUSHING AVENUE LINE (#7 LINE) (Continued) **1005417217**

Facility Has Received Notices of Violations:
- Regulation violated: SR - 371.1(f)(7)
- Area of violation: Listing - General
- Date violation determined: 01/24/2005
- Date achieved compliance: 05/23/2005
- Violation lead agency: State
- Enforcement action: WRITTEN INFORMAL
- Enforcement action date: 04/15/2005
- Enf. disposition status: Not reported
- Enf. disp. status date: Not reported
- Enforcement lead agency: State
- Proposed penalty amount: Not reported
- Final penalty amount: Not reported
- Paid penalty amount: Not reported

Evaluation Action Summary:
- Evaluation date: 01/24/2005
- Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
- Area of violation: Listing - General
- Date achieved compliance: 05/23/2005
- Evaluation lead agency: State

FINDS:

Registry ID: 110012193205

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

NY MANIFEST:
- EPA ID: NYR000103416
- Country: USA
- Mailing Name: NYC TR AUTHORITY CPM ENG
- Mailing Contact: ROY PARDEE JR.
- Mailing Address: 130 LIVINGSTON ST RM 8007
- Mailing Address 2: Not reported
- Mailing City: BROOKLYN
- Mailing State: NY
- Mailing Zip: 11201
- Mailing Zip4: Not reported
- Mailing Country: USA
- Mailing Phone: 718-694-1448

- Document ID: NYG3567303
- Manifest Status: Not reported
- Trans1 State ID: NYD077444263
- Trans2 State ID: Not reported

NYCT - FLUSHING AVENUE LINE (#7 LINE) (Continued) **1005417217**

Generator Ship Date:	12/24/2002
Trans1 Recv Date:	12/24/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/24/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000103416
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	40579PANY
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00030
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	04000
Units:	P - Pounds
Number of Containers:	008
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2002

Document ID:	NYG3329955
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	05/03/2002
Trans1 Recv Date:	05/03/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/07/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000103416
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYPD1010
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	01250
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2002

Document ID:	NYG3330009
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	05/08/2002
Trans1 Recv Date:	05/08/2002

NYCT - FLUSHING AVENUE LINE (#7 LINE) (Continued) **1005417217**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/10/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000103416
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	PD1011NY
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	03000
Units:	P - Pounds
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2002

Document ID:	NYG3328461
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	04/08/2002
Trans1 Recv Date:	04/08/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/09/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000103416
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	PD1011NY
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	03600
Units:	P - Pounds
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2002

Document ID:	NYG3494178
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	09/20/2002
Trans1 Recv Date:	09/20/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/23/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000103416
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	PD1010NY
Waste Code:	D008 - LEAD 5.0 MG/L TCLP

NYCT - FLUSHING AVENUE LINE (#7 LINE) (Continued) **1005417217**

Quantity:	07000
Units:	P - Pounds
Number of Containers:	013
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2002

Document ID:	NYG3494241
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	09/23/2002
Trans1 Recv Date:	09/23/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/24/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000103416
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	PD1010NY
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	07000
Units:	P - Pounds
Number of Containers:	013
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2002

Document ID:	NYG3388104
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	06/12/2002
Trans1 Recv Date:	06/12/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/19/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000103416
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYPD1011
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00200
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2002

NYCT - FLUSHING AVENUE LINE (#7 LINE) (Continued) **1005417217**

Document ID:	NYG3388203
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	06/13/2002
Trans1 Recv Date:	06/13/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/18/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000103416
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	PD1011
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	02400
Units:	P - Pounds
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2002

Document ID:	NYG3389859
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	06/28/2002
Trans1 Recv Date:	06/28/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/01/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000103416
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	PP5193
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	03000
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2002

Document ID:	NYG3391623
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	08/06/2002
Trans1 Recv Date:	08/06/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/06/2002
Part A Recv Date:	Not reported

NYCT - FLUSHING AVENUE LINE (#7 LINE) (Continued) **1005417217**

Part B Recv Date: Not reported
Generator EPA ID: NYR000103416
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: 68235AKNY
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 01500
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

Document ID: NYG3391632
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 08/02/2002
Trans1 Recv Date: 08/02/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/06/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000103416
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: PP5193NY
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 02000
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

Document ID: NYG3328722
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 04/12/2002
Trans1 Recv Date: 04/12/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/17/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000103416
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: NYPD1010
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 01200
Units: P - Pounds
Number of Containers: 003

NYCT - FLUSHING AVENUE LINE (#7 LINE) (Continued) **1005417217**

Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

Document ID: NYG3388275
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 06/17/2002
Trans1 Recv Date: 06/17/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/18/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000103416
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: PP5193
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00650
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

Document ID: NYG3330234
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 05/13/2002
Trans1 Recv Date: 05/13/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/15/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000103416
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: PD1011NY
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00800
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

Document ID: NYG3331413
Manifest Status: Not reported
Trans1 State ID: NYD077444263

NYCT - FLUSHING AVENUE LINE (#7 LINE) (Continued) **1005417217**

Trans2 State ID: Not reported
Generator Ship Date: 11/07/2002
Trans1 Recv Date: 11/07/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/08/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000103416
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: 40580PANY
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 03600
Units: P - Pounds
Number of Containers: 006
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

Document ID: NYG3331485
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 05/30/2002
Trans1 Recv Date: 05/30/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/31/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000103416
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: PD1011NY
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 02000
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

Document ID: NYG3564504
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 11/26/2002
Trans1 Recv Date: 11/26/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/27/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000103416
Trans1 EPA ID: NYD077444263

NYCT - FLUSHING AVENUE LINE (#7 LINE) (Continued) **1005417217**

Trans2 EPA ID: Not reported
TSDF ID: 40579PANY
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 02900
Units: P - Pounds
Number of Containers: 006
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

Document ID: NYG3331674
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 06/03/2002
Trans1 Recv Date: 06/03/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/04/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000103416
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: PD1011NY
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 01500
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

Document ID: NYG3328857
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 04/16/2002
Trans1 Recv Date: 04/16/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/17/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000103416
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: NYPD1010
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 06000
Units: P - Pounds
Number of Containers: 009
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00

NYCT - FLUSHING AVENUE LINE (#7 LINE) (Continued) **1005417217**

Year:	2002
Document ID:	NYG3328965
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	04/19/2002
Trans1 Recv Date:	04/19/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000103416
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYPD1010
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	02700
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2002

Click this hyperlink while viewing on your computer to access
74 additional NY_MANIFEST: record(s) in the EDR Site Report.

AB157 **MTA NYCT - COURT HOUSE SQ STA 45TH ROAD** **RCRA NonGen / NLR** **1004762726**
WSW **JACKSON AVE & 23RD ST** **FINDS** **NYR000099846**
1/8-1/4 **LONG ISLAND CITY, NY** **NY MANIFEST**
0.224 mi.
1184 ft. **Site 2 of 2 in cluster AB**

Relative:
Lower

Actual:
12 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	MTA NYCT - COURT HOUSE SQ STA 45TH ROAD
Facility address:	JACKSON AVE & 23RD ST 7 LINE LONG ISLAND CITY, NY 11101
EPA ID:	NYR000099846
Mailing address:	BROADWAY 2ND FL NEW YORK, NY 10004
Contact:	WILLIAM JEHLE
Contact address:	BROADWAY 2ND FL NEW YORK, NY 10004
Contact country:	US
Contact telephone:	(646) 252-3500
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MTA NEW YORK CITY TRANSIT
Owner/operator address:	2 BROADWAY 2ND FL

MTA NYCT - COURT HOUSE SQ STA 45TH ROAD (Continued) **1004762726**

NEW YORK, NY 10004
Owner/operator country: US
Owner/operator telephone: (646) 252-3500
Legal status: Other
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: MTA NEW YORK CITY TRANSIT
Owner/operator address: 2 BROADWAY 2ND FL
NEW YORK, NY 10004
Owner/operator country: US
Owner/operator telephone: (646) 252-3500
Legal status: Other
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: MTA NYCT - COURT HOUSE SQ STA 45TH ROAD
Classification: Not a generator, verified

Date form received by agency: 08/13/2001
Facility name: MTA NYCT - COURT HOUSE SQ STA 45TH ROAD
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110012235401

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MTA NYCT - COURT HOUSE SQ STA 45TH ROAD (Continued) **1004762726**

NY MANIFEST:

EPA ID:	NYR000099846
Country:	USA
Mailing Name:	NEW YORK CITY TRANSIT
Mailing Contact:	DERRICK MILLS
Mailing Address:	2 BROADWAY
Mailing Address 2:	ROOM A27.64
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	646-252-3500

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986908085
Trans2 State ID:	Not reported
Generator Ship Date:	2010-02-05
Trans1 Recv Date:	2010-02-05
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-02-12
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099846
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	Not reported
Quantity:	500.0
Units:	P - Pounds
Number of Containers:	5.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	003404900JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H132

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	2011-10-28
Trans1 Recv Date:	2011-10-28

MTA NYCT - COURT HOUSE SQ STA 45TH ROAD (Continued) **1004762726**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2011-10-28
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099846
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	1000.0
Units:	P - Pounds
Number of Containers:	5.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000423270WAS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2012-04-20
Trans1 Recv Date:	2012-04-20
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-04-20
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099846
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	220.0
Units:	P - Pounds
Number of Containers:	4.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	003635402JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N

MTA NYCT - COURT HOUSE SQ STA 45TH ROAD (Continued) **1004762726**

Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2012-04-20
Trans1 Recv Date:	2012-04-20
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-04-20
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099846
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	440.0
Units:	P - Pounds
Number of Containers:	8.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	003635402JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2012-04-20
Trans1 Recv Date:	2012-04-20
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-04-20
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099846
Trans1 EPA ID:	Not reported

MTA NYCT - COURT HOUSE SQ STA 45TH ROAD (Continued) **1004762726**

Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	55.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	003635402JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2012-10-09
Trans1 Recv Date:	2012-10-09
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-10-09
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099846
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	250.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	008921406JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

MTA NYCT - COURT HOUSE SQ STA 45TH ROAD (Continued) **1004762726**

Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-10-09
Trans1 Recv Date: 2012-10-09
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-10-09
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000099846
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 60.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 008921406JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 2009-09-23
Trans1 Recv Date: 2009-09-23
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-09-23
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000099846
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 400.0
Units: P - Pounds
Number of Containers: 4.0

MTA NYCT - COURT HOUSE SQ STA 45TH ROAD (Continued) **1004762726**

Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	000195120WAS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	2010-11-30
Trans1 Recv Date:	2010-11-30
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-11-30
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099846
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	900.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	000201878WAS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986908085

MTA NYCT - COURT HOUSE SQ STA 45TH ROAD (Continued) **1004762726**

Trans2 State ID:	NYD986908085
Generator Ship Date:	2010-04-13
Trans1 Recv Date:	2010-04-13
Trans2 Recv Date:	2010-04-21
TSD Site Recv Date:	2010-04-22
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099846
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	Not reported
Quantity:	125.0
Units:	P - Pounds
Number of Containers:	6.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	003404361JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H132

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986908085
Trans2 State ID:	Not reported
Generator Ship Date:	2010-02-05
Trans1 Recv Date:	2010-02-05
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-02-12
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099846
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	Not reported
Quantity:	500.0
Units:	P - Pounds
Number of Containers:	5.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	003404900JJK
Import Ind:	N

MTA NYCT - COURT HOUSE SQ STA 45TH ROAD (Continued) **1004762726**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H132

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2012-04-20
Trans1 Recv Date:	2012-04-20
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-04-20
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099846
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	55.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	003635402JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2012-04-20
Trans1 Recv Date:	2012-04-20
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-04-20
Part A Recv Date:	Not reported

MTA NYCT - COURT HOUSE SQ STA 45TH ROAD (Continued) **1004762726**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099846
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	220.0
Units:	P - Pounds
Number of Containers:	4.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	003635402JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	2012-04-20
Trans1 Recv Date:	2012-04-20
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-04-20
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099846
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	440.0
Units:	P - Pounds
Number of Containers:	8.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	003635402JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

MTA NYCT - COURT HOUSE SQ STA 45TH ROAD (Continued) **1004762726**

Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	NYG2972979
Manifest Status:	Not reported
Trans1 State ID:	NJD054126164
Trans2 State ID:	Not reported
Generator Ship Date:	09/28/2001
Trans1 Recv Date:	09/28/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/18/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099846
Trans1 EPA ID:	NYD049836679
Trans2 EPA ID:	Not reported
TSDF ID:	0440465ME
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00800
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2001

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	2008-10-10
Trans1 Recv Date:	2008-10-10
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-10-10
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099846
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	1200.0
Units:	P - Pounds
Number of Containers:	6.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000196588WAS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N

MTA NYCT - COURT HOUSE SQ STA 45TH ROAD (Continued) **1004762726**

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AA158 **EDR US Hist Auto Stat** **1015502450**
WSW **4506 DAVIS ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.225 mi.
1187 ft. **Site 2 of 3 in cluster AA**

Relative:
Lower

Actual:
9 ft.

EDR Historical Auto Stations:
Name: DAVIS ST AUTO REPAIR INC
Year: 2011
Address: 4506 DAVIS ST

Name: DAVIS ST AUTO REPAIR INC
Year: 2012
Address: 4506 DAVIS ST

AC159 **STANDARD FINISHING CO INC** **RCRA NonGen / NLR** **1001119285**
NW **43-10 23RD ST 2ND FLOOR** **NY MANIFEST** **NYR000025726**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **US AIRS**
0.225 mi.
1190 ft. **Site 1 of 4 in cluster AC**

Relative:
Higher

Actual:
16 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: STANDARD FINISHING CO INC
Facility address: 43-10 23RD ST 2ND FLOOR
LAT 4045 LONG 7356
LONG ISLAND CITY, NY 11101
EPA ID: NYR000025726
Mailing address: 23RD ST 2ND FLOOR
LAT 4045 LONG 7356
LONG ISLAND CITY, NY 11101
Contact: Not reported
Contact address: 23RD ST 2ND FLOOR
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: HOWARD HALPERN
Owner/operator address: 43-10 23RD ST
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 729-4700
Legal status: Private

STANDARD FINISHING CO INC (Continued) **1001119285**

Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: HOWARD HALPERN
Owner/operator address: 43-10 23RD ST
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 729-4700
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: STANDARD FINISHING CO INC
Classification: Not a generator, verified

Date form received by agency: 07/14/1999
Facility name: STANDARD FINISHING CO INC
Classification: Small Quantity Generator

Date form received by agency: 06/18/1996
Facility name: STANDARD FINISHING CO INC
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYR000025726
Country: USA
Mailing Name: STANDARD FINISHING CO INC
Mailing Contact: HOWARD HALPERN
Mailing Address: 43-10 23RD STREET 2ND FLOOR
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip4: Not reported

STANDARD FINISHING CO INC (Continued) **1001119285**

Mailing Country: USA
Mailing Phone: 718-729-4700

Document ID: NJA2606604
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 2809
Trans2 State ID: Not reported
Generator Ship Date: 960625
Trans1 Recv Date: 960625
Trans2 Recv Date: Not reported
TSD Site Recv Date: 960625
Part A Recv Date: 960715
Part B Recv Date: 960722
Generator EPA ID: NYR000025726
Trans1 EPA ID: NJD002454544
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00400
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 008
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 080
Waste Code: Not reported
Quantity: 00300
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 006
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 080
Waste Code: Not reported
Quantity: 00200
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 080
Year: 96

Document ID: NYG0415098
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 03/10/1998
Trans1 Recv Date: 03/10/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/10/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000025726
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: NYPD1010
Waste Code: D001 - NON-LISTED IGNITABLE WASTES

STANDARD FINISHING CO INC (Continued) **1001119285**

Quantity: 00495
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 009
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 98

Document ID: NYG0582714
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 03/10/1998
Trans1 Recv Date: 03/10/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/10/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000025726
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: NYPD1010
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00030
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 98

AIRS (AFS):

Airs Minor Details:
EPA plant ID: 110001583091
Plant name: STANDARD FINISHING CO INC
Plant address: 43-10 23RD STREET
LONG ISLAND CITY, NY 11101
County: QUEENS
Region code: 02
Dunn & Bradst #: 001233048

STANDARD FINISHING CO INC (Continued) **1001119285**

Air quality cntrl region:	043
Sic code:	2641
Sic code desc:	PAPER COATING AND GLAZING (DISC. 1987, 2671 OR 2672)
North Am. industrial classf:	322222
NAIC code description:	Coated and Laminated Paper Manufacturing
Default compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Default classification:	POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Govt facility:	ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT
Current HPV:	Not reported

Historical Compliance Minor Sources:

State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1002
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1101
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1103
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1202
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1204
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1001
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1003
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1004
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1102
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1104
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1201
Air prog code hist file:	SIP SOURCE

STANDARD FINISHING CO INC (Continued) **1001119285**

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

Compliance & Violation Data by Minor Sources:
Air program code: SIP SOURCE
Plant air program pollutant: VOLATILE ORGANIC COMPOUNDS
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: Not reported
Repeat violator date: Not reported
Turnover compliance: Not reported

AC160 **GRUBER DISPLAY COMPANY** **RCRA NonGen / NLR** **1000162507**
NW **43-10 23RD ST** **FINDS** **NYD002021103**
1/8-1/4 **LONG ISLAND CITY, NY**
0.225 mi.
1190 ft. **Site 2 of 4 in cluster AC**

Relative:
Higher

Actual:
16 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: GRUBER DISPLAY CO INC
Facility address: 43-10 23RD ST
LONG ISLAND CITY, NY 11101
EPA ID: NYD002021103
Mailing address: 23RD ST
LONG ISLAND CITY, NY 11101
Contact: Not reported
Contact address: 23RD ST
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported

GRUBER DISPLAY COMPANY (Continued) **1000162507**

Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: GRUBER DISPLAY CO INC
Classification: Not a generator, verified

Date form received by agency: 12/31/1979
Facility name: GRUBER DISPLAY CO INC
Classification: Not a generator, verified

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 07/31/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110009464454

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AC161 **KASSABIAN REALTY LLC** **NY AST** **U003388914**
NW **43-10 23RD ST** **NY HIST AST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.225 mi.
1190 ft. **Site 3 of 4 in cluster AC**

Relative:
Higher

Actual:
16 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-283339
Program Type:	PBS
UTM X:	589162.42394999997
UTM Y:	4511490.3652600003
Expiration Date:	2017/07/14
Site Type:	Other

Affiliation Records:

Site Id:	12505
Affiliation Type:	Facility Owner
Company Name:	KASSABIAN REALTY LLC
Contact Type:	MANAGER
Contact Name:	LEON KASSABIAN
Address1:	43-10 23RD ST
Address2:	Not reported
City:	LONG ISLAND
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-7800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	3/27/2007

Site Id:	12505
Affiliation Type:	Mail Contact
Company Name:	KASSABIAN REALTY LLC
Contact Type:	Not reported
Contact Name:	VASKEN KASSABIAN
Address1:	43-10 23RD ST
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-7800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	6/1/2012

Site Id:	12505
Affiliation Type:	On-Site Operator
Company Name:	KASSABIAN REALTY LLC
Contact Type:	Not reported
Contact Name:	LEON KASSABIAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported

KASSABIAN REALTY LLC (Continued) **U003388914**

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 784-7800
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 12505
Affiliation Type: Emergency Contact
Company Name: KASSABIAN REALTY LLC
Contact Type: Not reported
Contact Name: LEON KASSABIAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 784-7800
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 14891
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/15/1985
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported

KASSABIAN REALTY LLC (Continued) **U003388914**

Register: True
Modified By: DMMOLOUG
Last Modified: 06/01/2012
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:
PBS Number: 2-283339
SWIS Code: 6301
Operator: VASKEN KASSABIAN
Facility Phone: (718) 784-7800
Facility Addr2: 43010 23RD ST
Facility Type: MANUFACTURING
Emergency: VASKEN KASSABIAN
Emergency Tel: (718) 784-7800
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: KASSABIAN REALTY CO
Owner Address: 43-10 23RD ST
Owner City,St,Zip: LONG ISLAND, NY 11101
Federal ID: Not reported
Owner Tel: (718) 784-7800
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: VASKEN KASSABIAN
Mailing Name: KASSABIAN REALTY LLC
Mailing Address: 43-10 23RD ST
Mailing Address 2: Not reported
Mailing City,St,Zip: LONG ISLAND CITY, NY 11101
Mailing Telephone: (718) 784-7800
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag: False
Certification Date: 07/07/1997
Expiration: 07/14/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 5000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 63
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 5000

KASSABIAN REALTY LLC (Continued) **U003388914**

Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	None
Leak Detection:	0
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
SPDES Number:	Not reported
Lat/Long:	Not reported

AC162 **IDEAL LABEL INC** **RCRA-CESQG** **1001405121**
NW **43-10 23RD ST 2ND FLOOR** **NY MANIFEST** **NYR000065680**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.225 mi.
1190 ft. **Site 4 of 4 in cluster AC**

Relative:
Higher

Actual:
16 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	IDEAL LABEL INC
Facility address:	43-10 23RD ST 2ND FLOOR FRONT OFFICE LONG ISLAND CITY, NY 11101
EPA ID:	NYR000065680
Mailing address:	23RD ST 2ND FLOOR FRONT OFFICE LONG ISLAND CITY, NY 11101
Contact:	HERBERT BOOKBINDER
Contact address:	23RD ST 2ND FLOOR FRONT OFFICE LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	(718) 729-8844
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from

IDEAL LABEL INC (Continued) **1001405121**

the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: LARRY LASSABIAN
Owner/operator address: 43-10 23RD ST 1ST FLOOR
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 784-7800
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: LARRY LASSABIAN
Owner/operator address: 43-10 23RD ST 1ST FLOOR
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 784-7800
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: IDEAL LABEL INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/06/1999
Facility name: IDEAL LABEL INC
Classification: Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP000862714
Country: USA
Mailing Name: ECLADOR INTERNATIONAL CORPORATION

IDEAL LABEL INC (Continued) **1001405121**

Mailing Contact:	ECLADOR INTERNATIONAL CORPORATION
Mailing Address:	43-10 23RD STREET
Mailing Address 2:	Not reported
Mailing City:	LONG ISLANDCITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-784-0900

Document ID:	NYH0060435
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	12/21/1999
Trans1 Recv Date:	12/21/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/21/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	PX3640
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	99

Document ID:	NYH0139932
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2000
Trans1 Recv Date:	10/19/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/19/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

IDEAL LABEL INC (Continued) **1001405121**

Document ID:	NYG1192284
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	05/13/1999
Trans1 Recv Date:	05/13/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/13/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	PX3640
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	99

Document ID:	NYH0427752
Manifest Status:	Not reported
Trans1 State ID:	62096PA
Trans2 State ID:	Not reported
Generator Ship Date:	06/01/2004
Trans1 Recv Date:	06/01/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/01/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYH0507024
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	10/17/2005
Trans1 Recv Date:	10/17/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/17/2005
Part A Recv Date:	Not reported

IDEAL LABEL INC (Continued) **1001405121**

Part B Recv Date: Not reported
Generator EPA ID: NYR000065680
Trans1 EPA ID: 62096PA
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: Not reported

Document ID: NYH0306828
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: Not reported
Generator Ship Date: 08/19/2002
Trans1 Recv Date: 08/19/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/19/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000065680
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: 23138PA
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2002

Document ID: NYH0507024
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: Not reported
Generator Ship Date: 10/17/2005
Trans1 Recv Date: 10/17/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/17/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000065680
Trans1 EPA ID: 62096PA
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002

IDEAL LABEL INC (Continued) **1001405121**

Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2005

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2008-02-22
Trans1 Recv Date:	2008-02-22
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-02-22
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	110.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	001028366FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2009-10-21
Trans1 Recv Date:	2009-10-21
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-10-22
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported

IDEAL LABEL INC (Continued) **1001405121**

Quantity:	110.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002495049FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	PAD982661381
Generator Ship Date:	2012-02-10
Trans1 Recv Date:	2012-02-10
Trans2 Recv Date:	2012-02-10
TSD Site Recv Date:	2012-02-17
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID040098352
Waste Code:	Not reported
Quantity:	110.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	005154976FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

IDEAL LABEL INC (Continued) **1001405121**

Document ID:	NYH0223452
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	10/24/2001
Trans1 Recv Date:	10/24/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/24/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	PX3640
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2001

Document ID:	NYH0343557
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	05/12/2003
Trans1 Recv Date:	05/12/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/12/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	23138PA
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2003

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	PAD982661381
Generator Ship Date:	2012-02-10
Trans1 Recv Date:	2012-02-10
Trans2 Recv Date:	2012-02-10
TSD Site Recv Date:	2012-02-17
Part A Recv Date:	Not reported

IDEAL LABEL INC (Continued) **1001405121**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID040098352
Waste Code:	Not reported
Quantity:	110.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	005154976FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2008-02-22
Trans1 Recv Date:	2008-02-22
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-02-22
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	110.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	001028366FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

IDEAL LABEL INC (Continued) **1001405121**

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: Not reported
Generator Ship Date: 2008-02-22
Trans1 Recv Date: 2008-02-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2008-02-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000065680
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: Not reported
Quantity: 110.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2008
Manifest Tracking Num: 001028366FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

EPA ID: NYR000065680
Country: USA
Mailing Name: IDEAL LABEL INC
Mailing Contact: NORA USSEGLIO
Mailing Address: 43-10 23RD ST
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 516-729-8844

Document ID: NYH0060435
Manifest Status: Not reported

IDEAL LABEL INC (Continued) **1001405121**

Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	12/21/1999
Trans1 Recv Date:	12/21/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/21/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	PX3640
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	99

Document ID:	NYH0139932
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2000
Trans1 Recv Date:	10/19/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/19/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYG1192284
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	05/13/1999
Trans1 Recv Date:	05/13/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/13/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680

IDEAL LABEL INC (Continued) **1001405121**

Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	PX3640
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	99

Document ID:	NYH0427752
Manifest Status:	Not reported
Trans1 State ID:	62096PA
Trans2 State ID:	Not reported
Generator Ship Date:	06/01/2004
Trans1 Recv Date:	06/01/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/01/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYH0507024
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	10/17/2005
Trans1 Recv Date:	10/17/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/17/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	62096PA
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.

IDEAL LABEL INC (Continued) **1001405121**

Specific Gravity: 01.00
Year: Not reported

Document ID: NYH0306828
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: Not reported
Generator Ship Date: 08/19/2002
Trans1 Recv Date: 08/19/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/19/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000065680
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: 23138PA
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2002

Document ID: NYH0507024
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: Not reported
Generator Ship Date: 10/17/2005
Trans1 Recv Date: 10/17/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/17/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000065680
Trans1 EPA ID: 62096PA
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2005

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: Not reported
Generator Ship Date: 2008-02-22

IDEAL LABEL INC (Continued) **1001405121**

Trans1 Recv Date:	2008-02-22
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-02-22
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	110.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	001028366FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2009-10-21
Trans1 Recv Date:	2009-10-21
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-10-22
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	110.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002495049FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N

IDEAL LABEL INC (Continued) **1001405121**

Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	PAD982661381
Generator Ship Date:	2012-02-10
Trans1 Recv Date:	2012-02-10
Trans2 Recv Date:	2012-02-10
TSD Site Recv Date:	2012-02-17
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID040098352
Waste Code:	Not reported
Quantity:	110.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	005154976FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	NYH0223452
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	10/24/2001
Trans1 Recv Date:	10/24/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/24/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680

IDEAL LABEL INC (Continued) **1001405121**

Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	PX3640
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2001

Document ID:	NYH0343557
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	05/12/2003
Trans1 Recv Date:	05/12/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/12/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	23138PA
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2003

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	PAD982661381
Generator Ship Date:	2012-02-10
Trans1 Recv Date:	2012-02-10
Trans2 Recv Date:	2012-02-10
TSD Site Recv Date:	2012-02-17
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID040098352
Waste Code:	Not reported
Quantity:	110.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.

IDEAL LABEL INC (Continued) **1001405121**

Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	005154976FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2008-02-22
Trans1 Recv Date:	2008-02-22
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-02-22
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	110.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	001028366FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2008-02-22

IDEAL LABEL INC (Continued) **1001405121**

Trans1 Recv Date:	2008-02-22
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-02-22
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000065680
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	110.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	001028366FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

AA163 **EDR US Hist Auto Stat** **1015504743**
SW **4557 DAVIS ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.226 mi.
1195 ft. **Site 3 of 3 in cluster AA**

Relative:
Lower

Actual:
9 ft.

EDR Historical Auto Stations:

Name:	BELLO LONG ISLAND CITY AUTO REPAIR INCORPORATED
Year:	1999
Address:	4557 DAVIS ST
Name:	BELLO LONG ISLAND CITY AUTO REPAIR INCORPORATED
Year:	2000
Address:	4557 DAVIS ST

AD164 **SCRIPTO EVERGLIDE** **RCRA NonGen / NLR** **1000260925**
ESE **29-10 THOMSON AVE** **FINDS** **NYD981086416**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.228 mi.
1204 ft. **Site 1 of 6 in cluster AD**

Relative:
Higher

Actual:
30 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	SCRIPTO EVERGLIDE
Facility address:	29-10 THOMSON AVE LONG ISLAND CITY, NY 11101

SCRIPTO EVERGLIDE (Continued) **1000260925**

EPA ID: NYD981086416
Mailing address: THOMSON AVE
LONG ISLAND CITY, NY 11101
Contact: Not reported
Contact address: THOMSON AVE
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: SCRIPTO EVERGLIDE
Classification: Not a generator, verified

SCRIPTO EVERGLIDE (Continued) **1000260925**

Date form received by agency: 07/08/1999
Facility name: SCRIPTO EVERGLIDE
Classification: Not a generator, verified

Date form received by agency: 05/30/1985
Facility name: SCRIPTO EVERGLIDE
Classification: Large Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 06/27/1984
Date achieved compliance: 05/29/1985
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/27/1985
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 09/17/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/27/1984
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/29/1985
Evaluation lead agency: State

FINDS:

Registry ID: 110009471687

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AD165 **LAGUARDIA COMMUNITY COLLEGE** **RCRA-CESQG** **1001090143**
ESE **29-10 THOMSON AVE** **NY MANIFEST** **NYR000019760**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **NY Spills**
0.228 mi.
1204 ft. **Site 2 of 6 in cluster AD**

Relative:
Higher

Actual:
30 ft.

RCRA-CESQG:

Date form received by agency:	02/01/2012
Facility name:	LAGUARDIA COMMUNITY COLLEGE
Facility address:	29-10 THOMSON AVE LONG ISLAND CITY, NY 11101
EPA ID:	NYR000019760
Mailing address:	THOMSON AVE LONG ISLAND CITY, NY 11101
Contact:	PETER JAYASEKARA
Contact address:	THOMSON AVE LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	(718) 482-5507
Contact email:	PJAYASEK@LAGCC.CUNY.EDU
EPA Region:	02
Land type:	Municipal
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	LAGUARDIA COMMUNITY COLLEGE
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	08/26/1998
Owner/Op end date:	Not reported

Owner/operator name:	CITY UNIVERSITY OF NEW YORK
Owner/operator address:	E 80TH ST NEW YORK, NY 10021
Owner/operator country:	US
Owner/operator telephone:	(212) 794-5735
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	08/26/1998
Owner/Op end date:	Not reported

LAGUARDIA COMMUNITY COLLEGE (Continued) **1001090143**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2007
Facility name: LAGUARDIA COMMUNITY COLLEGE
Site name: NYC LAGUARDIA COMMUNITY COLLEGE
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Facility name: LAGUARDIA COMMUNITY COLLEGE
Site name: NYC LAGUARDIA COMMUNITY COLLEGE
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: LAGUARDIA COMMUNITY COLLEGE
Site name: NYC LAGUARDIA COMMUNITY COLLEGE
Classification: Not a generator, verified

Date form received by agency: 02/14/1996
Facility name: LAGUARDIA COMMUNITY COLLEGE
Site name: NYC LAGUARDIA COMMUNITY COLLEGE
Classification: Small Quantity Generator

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

LAGUARDIA COMMUNITY COLLEGE (Continued) **1001090143**

Waste code: D005
Waste name: BARIUM

Waste code: D007
Waste name: CHROMIUM

Waste code: D008
Waste name: LEAD

Waste code: D011
Waste name: SILVER

Waste code: F002
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: B001
Waste name: B001

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 08/10/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

NY MANIFEST:
EPA ID: NYD001726496
Country: USA
Mailing Name: SCRIPTO EVERGLIDE INCORPORATED
Mailing Contact: STANLEY KLEIN
Mailing Address: 29-10 THOMSON AVENUE
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101

LAGUARDIA COMMUNITY COLLEGE (Continued) **1001090143**

Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-784-7191

Document ID:	NYB7595055
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	7946
Trans2 State ID:	Not reported
Generator Ship Date:	960515
Trans1 Recv Date:	960515
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	960520
Part A Recv Date:	960528
Part B Recv Date:	960614
Generator EPA ID:	NYR000019760
Trans1 EPA ID:	MA5000002394
Trans2 EPA ID:	Not reported
TSDF ID:	AZ0000337360
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	03100
Units:	P - Pounds
Number of Containers:	031
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	96

Document ID:	NYB7595883
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	PTH7945MN
Trans2 State ID:	Not reported
Generator Ship Date:	960417
Trans1 Recv Date:	960417
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	960422
Part A Recv Date:	960503
Part B Recv Date:	960523
Generator EPA ID:	NYR000019760
Trans1 EPA ID:	MA5000002394
Trans2 EPA ID:	Not reported
TSDF ID:	AZ0000337360
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	02944
Units:	P - Pounds
Number of Containers:	031
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00030
Units:	P - Pounds
Number of Containers:	001
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

LAGUARDIA COMMUNITY COLLEGE (Continued) **1001090143**

Year: 96

Document ID: NYB7214283
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: PTH7945
Trans2 State ID: Not reported
Generator Ship Date: 960619
Trans1 Recv Date: 960619
Trans2 Recv Date: Not reported
TSD Site Recv Date: 960621
Part A Recv Date: 960703
Part B Recv Date: 960725
Generator EPA ID: NYR000019760
Trans1 EPA ID: MA5000002394
Trans2 EPA ID: Not reported
TSDF ID: AZ0000337360
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 00100
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00180
Units: P - Pounds
Number of Containers: 006
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 96

Document ID: NYB7597926
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: PTH7945
Trans2 State ID: Not reported
Generator Ship Date: 960321
Trans1 Recv Date: 960321
Trans2 Recv Date: Not reported
TSD Site Recv Date: 960325
Part A Recv Date: 960401
Part B Recv Date: 960417
Generator EPA ID: NYR000019760
Trans1 EPA ID: MA5000002394
Trans2 EPA ID: Not reported
TSDF ID: AZ0000337360
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 03600
Units: P - Pounds
Number of Containers: 036
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 96

LAGUARDIA COMMUNITY COLLEGE (Continued) **1001090143**

Document ID:	NYG2530881
Manifest Status:	Not reported
Trans1 State ID:	WID988566543
Trans2 State ID:	Not reported
Generator Ship Date:	09/19/2000
Trans1 Recv Date:	09/19/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/25/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000019760
Trans1 EPA ID:	AZ0000337360
Trans2 EPA ID:	Not reported
TSDF ID:	WI010
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	00545
Units:	P - Pounds
Number of Containers:	007
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	00424
Units:	P - Pounds
Number of Containers:	015
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	2000

EPA ID:	NYR000019760
Country:	USA
Mailing Name:	LAGUARDIA COMMUNITY COLLEGE BLDG C
Mailing Contact:	JOHN BLAKE
Mailing Address:	29-10 THOMSONAVENUE
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	914-681-6384

Document ID:	NYB7595055
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	7946
Trans2 State ID:	Not reported
Generator Ship Date:	960515
Trans1 Recv Date:	960515
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	960520
Part A Recv Date:	960528
Part B Recv Date:	960614
Generator EPA ID:	NYR000019760
Trans1 EPA ID:	MA5000002394
Trans2 EPA ID:	Not reported

LAGUARDIA COMMUNITY COLLEGE (Continued) **1001090143**

TSDF ID:	AZ0000337360
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	03100
Units:	P - Pounds
Number of Containers:	031
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	96

Document ID:	NYB7595883
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	PTH7945MN
Trans2 State ID:	Not reported
Generator Ship Date:	960417
Trans1 Recv Date:	960417
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	960422
Part A Recv Date:	960503
Part B Recv Date:	960523
Generator EPA ID:	NYR000019760
Trans1 EPA ID:	MA5000002394
Trans2 EPA ID:	Not reported
TSDF ID:	AZ0000337360
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	02944
Units:	P - Pounds
Number of Containers:	031
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00030
Units:	P - Pounds
Number of Containers:	001
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	96

Document ID:	NYB7214283
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	PTH7945
Trans2 State ID:	Not reported
Generator Ship Date:	960619
Trans1 Recv Date:	960619
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	960621
Part A Recv Date:	960703
Part B Recv Date:	960725
Generator EPA ID:	NYR000019760
Trans1 EPA ID:	MA5000002394
Trans2 EPA ID:	Not reported
TSDF ID:	AZ0000337360
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP

LAGUARDIA COMMUNITY COLLEGE (Continued) **1001090143**

Quantity: 00100
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00180
Units: P - Pounds
Number of Containers: 006
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 96

Document ID: NYB7597926
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: PTH7945
Trans2 State ID: Not reported
Generator Ship Date: 960321
Trans1 Recv Date: 960321
Trans2 Recv Date: Not reported
TSD Site Recv Date: 960325
Part A Recv Date: 960401
Part B Recv Date: 960417
Generator EPA ID: NYR000019760
Trans1 EPA ID: MA5000002394
Trans2 EPA ID: Not reported
TSDF ID: AZ0000337360
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 03600
Units: P - Pounds
Number of Containers: 036
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 96

Document ID: NYG2530881
Manifest Status: Not reported
Trans1 State ID: WID988566543
Trans2 State ID: Not reported
Generator Ship Date: 09/19/2000
Trans1 Recv Date: 09/19/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/25/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000019760
Trans1 EPA ID: AZ0000337360
Trans2 EPA ID: Not reported
TSDF ID: WI010
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 00545
Units: P - Pounds

LAGUARDIA COMMUNITY COLLEGE (Continued) **1001090143**

Number of Containers:	007
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	00424
Units:	P - Pounds
Number of Containers:	015
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	2000

SPILLS:

Facility ID:	1204466
DER Facility ID:	421726
Facility Type:	ER
Site ID:	467353
DEC Region:	2
Spill Date:	8/3/2012
Spill Number/Closed Date:	1204466 / 9/10/2012
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	4101
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	8/3/2012
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	8/3/2012
Spill Record Last Update:	9/10/2012
Spiller Name:	Not reported
Spiller Company:	LAGUARDIA COMMUNITY COLLEGE
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	PETER JAYASEAARA
Contact Phone:	(347) 865-1291
DEC Memo:	8/6/12-Vought-Primary off-hours responder. Vought called Peter Jayaseaara (Ph:347-865-1291) and spoke to Joeseph who noted that that approximately 500 gallons of #2 fuel oil was released from a 200-gallon #2 fuel oil AST in a vault and that the oil was leaking out of secondary contaiment vault and was impacted a drain in the boiler room in sub-basement of LaGuardia Community College. Jayaseaara noted that FDNY Hazmat was on-scene and that he also called Triumvirate Inc (response company) and they were enroute to the site. Vought called RSE and DEC Demeo (secondary responder) who performed site visit. This spill assigned to Vought as Demeo not an option in UIS (as Demeo recently transferred). Spill to be

LAGUARDIA COMMUNITY COLLEGE (Continued) **1001090143**

transferred to Demeo upon availability in UIS.8/8/12-Vought-Spill transferred from Vought to DEC Demeo as now available as PM in UIS.8/4/12 TJDRecall - 2K AST for emergency generator leaked from supply piping feeding 100 gallon day tank on roof of structure. Leaking piping was uncapped return line inside secondary containment. Estimated 1500 gallons of diesel fuel leaked inside secondary containment. Containment vault was not tight - allowed product to migrate into adjoining sub-basement rooms. Building personnel shut power to affected areas of building which shut down transfer pump to rooftop day tank. Drainage trenches in basement had minor impacts due to migration of product - prior to DEC arrival absorbents were put in place to prevent further migration of product to sump pit. Facility owner retained Triumvirate Environmental for emergency cleanup - they responded with vac truck and recovered seperate phase product from tank vault and affected adjoining rooms. DEC required trenches and sump pit to be cleaned prior to putting sump pump back in service. Needs follow-up inspection.8/7/12 TJDSite inspection. DEC was contacted by Laguardia College EH&S personnel requesting reinspection as cleanup was reported to have been completed and required repairs had been made. At time of inspection, DEC met with EH&S Manager (Michael Spath from CUNY) and Triumvirate Environmental personnel. All required cleanup actions have been completed - affected concrete surfaces, trenches and sump pit have been degreased and pressure washed. Standing water in trenches and sump pit appear free of seperate phase product and sheen. DEC authorized EH&S staff to return sump pump to service. As per Laguardia College personnel, 2K AST is to remain out of service as a determination is made regarding the need for this tank. Required cleanup actions have been completed. Awaiting closure documentation.9/10/12 TJDFile review. All required closure documentation has been received. A total of 6 drums (contaminated absorbents) and 5,237 gallons of oil/water mixture were recovered and properly disposed of as part of remedial process. No further action is required. Spill closed.

Remarks: 2251 THE CALLER STATED A REPORT OF A LARGE SPILL WAS CAUSED BY A FAILED UNIT. WATER WAS IMPACTED. THE SPILL IS NOT CONTAINED. THE CLEAN UP IS PENDING THE CALLERS ARRIVAL ON SCENE. THE CALLER WILL UPDATE NYSDEC UPON ARRIVAL.

Material:

Site ID:	467353
Operable Unit ID:	1217310
Operable Unit:	01
Material ID:	2215578
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	500
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

AD166 **LAGUARDIA COMMUNITY COLLEGE** **NY AST** **A100294736**
ESE **29-10 THOMSON AVENUE** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.228 mi.
1204 ft. **Site 3 of 6 in cluster AD**

Relative:
Higher

Actual:
30 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609660
Program Type:	PBS
UTM X:	589698.54067999998
UTM Y:	4511012.1067199996
Expiration Date:	2015/04/13
Site Type:	School

Affiliation Records:

Site Id:	59011
Affiliation Type:	Mail Contact
Company Name:	LAGUARDIA COMMUNITY COLLEGE
Contact Type:	Not reported
Contact Name:	YURY FASTOVSKY
Address1:	31-10 THOMSON AVENUE
Address2:	ROOM MB 79
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 482-5582
EMail:	YFASTOVSKY@LAGCC.CUNY.EDU
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	11/1/2013

Site Id:	59011
Affiliation Type:	Emergency Contact
Company Name:	DASNY
Contact Type:	Not reported
Contact Name:	PUBLIC SAFETY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 482-5555
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	10/3/2012

Site Id:	59011
Affiliation Type:	Facility Owner
Company Name:	DASNY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	515 BROADWAY, STE 100
Address2:	Not reported
City:	ALBANY

LAGUARDIA COMMUNITY COLLEGE (Continued) **A100294736**

State:	NY
Zip Code:	12207-2919
Country Code:	001
Phone:	(518) 257-3000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	10/3/2012

Site Id:	59011
Affiliation Type:	On-Site Operator
Company Name:	LAGUARDIA COMMUNITY COLLEGE
Contact Type:	Not reported
Contact Name:	YURY FASTOVSKY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 482-5582
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	11/1/2013

Tank Info:

Tank Number:	C1
Tank Id:	179577
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	01/01/1972
Capacity Gallons:	20000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/27/2013

LAGUARDIA COMMUNITY COLLEGE (Continued) **A100294736**

Register:	True
Modified By:	NRLOMBAR
Last Modified:	11/01/2013
Material Name:	#6 Fuel Oil (On-Site Consumption)

Tank Number:	C2
Tank Id:	179578
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	01/01/1972
Capacity Gallons:	15000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/27/2013
Register:	True
Modified By:	NRLOMBAR
Last Modified:	11/01/2013
Material Name:	#6 Fuel Oil (On-Site Consumption)

Tank Number:	C3
Tank Id:	179579
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None

LAGUARDIA COMMUNITY COLLEGE (Continued) **A100294736**

F01 - Pipe External Protection - Painted/Asphalt Coating
I02 - Overfill - High Level Alarm

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1992
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	10/03/2012
Material Name:	Diesel

Tank Number:	C4
Tank Id:	179603
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
K00 - Spill Prevention - None
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
H02 - Tank Leak Detection - Interstitial - Manual Monitoring

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1992
Capacity Gallons:	100
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	10/03/2012
Material Name:	Diesel

AD167 **BURNHAM PRODUCTS CORP** **RCRA NonGen / NLR** **1000315395**
ESE **42-24 ORCHARD ST** **FINDS** **NYD001726496**
1/8-1/4 **LONG ISLAND CITY, NY**
0.228 mi.
1204 ft. **Site 4 of 6 in cluster AD**

Relative:
Higher

Actual:
30 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	BURNHAM PRODUCTS CORP
Facility address:	42-24 ORCHARD ST LONG ISLAND CITY, NY 11101
EPA ID:	NYD001726496
Mailing address:	ORCHARD ST LONG ISLAND CITY, NY 11101
Contact:	MURRAY BORENSTEIN
Contact address:	ORCHARD ST LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	(718) 784-7191
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	SCRIPTO INC
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	SCRIPTO INC
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

BURNHAM PRODUCTS CORP (Continued) **1000315395**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: BURNHAM PRODUCTS CORP
Classification: Not a generator, verified

Date form received by agency: 03/12/1981
Facility name: BURNHAM PRODUCTS CORP
Classification: Not a generator, verified

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 06/16/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/27/1984
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110009464409

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AE168 **OUTLET CITY INC** **RCRA-CESQG** **1000546989**
ENE **42-16 WEST ST** **FINDS** **NYD053174041**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **NY LTANKS**
0.230 mi. **NY MANIFEST**
1216 ft. **Site 1 of 2 in cluster AE** **NY Spills**

Relative: Higher

Actual: 16 ft.

RCRA-CESQG:
Date form received by agency: 01/01/2007
Facility name: OUTLET CITY INC
Facility address: 42-16 WEST ST
LONG ISLAND CITY, NY 11101
EPA ID: NYD053174041
Mailing address: WEST ST
LONG ISLAND CITY, NY 11101
Contact: Not reported

OUTLET CITY INC (Continued) **1000546989**

Contact address: WEST ST
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: OUTLET CITY INC
Owner/operator address: 42-16 WEST ST
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 786-4500
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: OUTLET CITY INC
Owner/operator address: 42-16 WEST ST
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 786-4500
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No

OUTLET CITY INC (Continued) **1000546989**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: OUTLET CITY INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/01/2001
Facility name: OUTLET CITY INC
Site name: AKRF-MODELL'S OUTLET CITY, INC.
Classification: Large Quantity Generator

Date form received by agency: 07/14/1999
Facility name: OUTLET CITY INC
Classification: Small Quantity Generator

Date form received by agency: 07/16/1997
Facility name: OUTLET CITY INC
Classification: Large Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - Records/Reporting
Date violation determined: 07/19/2000
Date achieved compliance: 10/16/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/19/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 03/01/2000
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Records/Reporting
Date achieved compliance: 10/16/2000
Evaluation lead agency: State

FINDS:

Registry ID: 110009467166

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

OUTLET CITY INC (Continued) **1000546989**

LTANKS:

Site ID:	254707
Spill Number/Closed Date:	9600688 / 5/27/2003
Spill Date:	3/26/1996
Spill Cause:	Tank Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	4/15/1996
CID:	365
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	4/15/1996
Spill Record Last Update:	4/8/2004
Spiller Name:	D. ROTH
Spiller Company:	OUTLET CITY
Spiller Address:	42-16 WEST STREET
Spiller City,St,Zip:	LONG ISLAND CITY, NY 11101-
Spiller County:	001
Spiller Contact:	R. PIERCE
Spiller Phone:	(201) 621-2230
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	208621
DEC Memo:	Not reported
Remarks:	Contaminated water soil and groundwater were found during site assessment.

Material:

Site ID:	254707
Operable Unit ID:	1028363
Operable Unit:	01
Material ID:	354084
Material Code:	0059A
Material Name:	SOLVENTS
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	254707
Operable Unit ID:	1028363
Operable Unit:	01
Material ID:	354083
Material Code:	0057A

OUTLET CITY INC (Continued) **1000546989**

Material Name:	PESTICIDES
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	254707
Operable Unit ID:	1028363
Operable Unit:	01
Material ID:	354081
Material Code:	0018A
Material Name:	TAR
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	254707
Operable Unit ID:	1028363
Operable Unit:	01
Material ID:	354082
Material Code:	0056A
Material Name:	PAINT THINNERS
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

NY MANIFEST:

EPA ID:	NYD053174041
Country:	USA
Mailing Name:	OUTLET CITY INC
Mailing Contact:	SHARON
Mailing Address:	42-16 WEST STREET
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-786-4500

Document ID:	NJA2758094
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPES58

OUTLET CITY INC (Continued) **1000546989**

Trans2 State ID:	Not reported
Generator Ship Date:	970627
Trans1 Recv Date:	970627
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	970627
Part A Recv Date:	980317
Part B Recv Date:	980414
Generator EPA ID:	NYD053174041
Trans1 EPA ID:	NJ0000027193
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D026 - CRESOL 200.0 MG/L TCLP
Quantity:	00025
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	97

Document ID:	NYB7496208
Manifest Status:	Not reported
Trans1 State ID:	NYD980592570
Trans2 State ID:	NJD054126164
Generator Ship Date:	09/28/2000
Trans1 Recv Date:	09/28/2000
Trans2 Recv Date:	10/04/2000
TSD Site Recv Date:	10/10/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD053174041
Trans1 EPA ID:	OHD066060609
Trans2 EPA ID:	Not reported
TSDF ID:	14887AD
Waste Code:	D026 - CRESOL 200.0 MG/L TCLP
Quantity:	00200
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.10
Year:	2000

Document ID:	NJA1471371
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS699
Trans2 State ID:	Not reported
Generator Ship Date:	920618
Trans1 Recv Date:	920618
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	920618
Part A Recv Date:	Not reported
Part B Recv Date:	920703
Generator EPA ID:	NYD053174041
Trans1 EPA ID:	NJD980772768

OUTLET CITY INC (Continued) **1000546989**

Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00200
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	03300
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	92

Document ID:	NYG0827694
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	31124MA
Trans2 State ID:	0027402
Generator Ship Date:	971217
Trans1 Recv Date:	971217
Trans2 Recv Date:	971219
TSD Site Recv Date:	971229
Part A Recv Date:	980108
Part B Recv Date:	980127
Generator EPA ID:	NYD053174041
Trans1 EPA ID:	CTD982191942
Trans2 EPA ID:	CTD982191942
TSDF ID:	OHD980681571
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	120
Year:	97

Document ID:	NJA3128296
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	06/07/1999
Trans1 Recv Date:	06/07/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/07/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD053174041
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	S6993

OUTLET CITY INC (Continued) **1000546989**

Waste Code:	U051 - CREOSOTE
Quantity:	00020
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	99

SPILLS:

Facility ID:	0301857
DER Facility ID:	208621
Facility Type:	ER
Site ID:	254706
DEC Region:	2
Spill Date:	5/21/2003
Spill Number/Closed Date:	0301857 / 5/27/2003
Spill Cause:	Housekeeping
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	5/21/2003
CID:	205
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	5/21/2003
Spill Record Last Update:	5/27/2003
Spiller Name:	D. ROTH
Spiller Company:	OUTLET CITY
Spiller Address:	42-16 WEST STREET
Spiller City,St,Zip:	LONG ISLAND CITY, NY 11101-
Spiller Company:	001
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	DEC / ANTHONY SIGONA ON SITE

Material:

Site ID:	254706
Operable Unit ID:	869876
Operable Unit:	01
Material ID:	506343
Material Code:	0180A
Material Name:	CREOSOTE
Case No.:	08001589
Material FA:	Hazardous Material
Quantity:	0
Units:	Gallons

OUTLET CITY INC (Continued) **1000546989**

Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	254706
Operable Unit ID:	869876
Operable Unit:	01
Material ID:	506342
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9813882
DER Facility ID:	208621
Facility Type:	ER
Site ID:	308118
DEC Region:	2
Spill Date:	10/1/1998
Spill Number/Closed Date:	9813882 / 7/22/2005
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates a file or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)
SWIS:	4101
Investigator:	EXHAMPST
Referred To:	Not reported
Reported to Dept:	2/16/1999
CID:	366
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2/16/1999
Spill Record Last Update:	7/22/2005
Spiller Name:	DAVID A ROTH
Spiller Company:	OUTLET CITY
Spiller Address:	42-16 WEST ST
Spiller City,St,Zip:	LONG ISLAND CITY, NY 11101-
Spiller Company:	001
Contact Name:	MARCUS SIMMONS
Contact Phone:	(212) 696-0670
DEC Memo:	7/22/05, Hampston: See also 9600688, 0301857. Site under VCA V00081 and listed as P site (2-41-020). UST removal as part of VCA in 2003. Site investigation/assessment continuing under VCA.
Remarks:	CALLER REPORTING THAT DURING SITE INVESTIGATION, MULTIPLE TYPES OF

OUTLET CITY INC (Continued) **1000546989**

HAZARDOUS MATERIALS WERE FOUND IN SOIL SAMPLES. REQ DEC FOLLOW UP.

Material:

Site ID:	308118
Operable Unit ID:	1074608
Operable Unit:	01
Material ID:	310593
Material Code:	0056A
Material Name:	PAINT THINNERS
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	308118
Operable Unit ID:	1074608
Operable Unit:	01
Material ID:	310590
Material Code:	0018A
Material Name:	TAR
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	308118
Operable Unit ID:	1074608
Operable Unit:	01
Material ID:	310592
Material Code:	0036B
Material Name:	CARBOLIC ACID
Case No.:	00108952
Material FA:	Hazardous Material
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	308118
Operable Unit ID:	1074608
Operable Unit:	01
Material ID:	310594
Material Code:	0057A
Material Name:	PESTICIDES
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

AE169 **OUTLET CITY INC** **NY UST** **U001836097**
ENE **42-16 WEST ST** **NY HIST UST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.230 mi.
1216 ft. **Site 2 of 2 in cluster AE**

Relative:
Higher

Actual:
16 ft.

UST:

Id/Status:	2-237981 / Unregulated
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589662.85900000005
UTM Y:	4511385.9358099997
Site Type:	Unknown

Affiliation Records:

Site Id:	8894
Affiliation Type:	Facility Owner
Company Name:	OUTLET CITY INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	42-16 WEST ST
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(728) 786-4580
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	8894
Affiliation Type:	Mail Contact
Company Name:	OUTLET CITY INC
Contact Type:	Not reported
Contact Name:	JOSEPH CONLEY
Address1:	42-16 WEST ST
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 786-4500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	8894
Affiliation Type:	On-Site Operator
Company Name:	OUTLET CITY INC
Contact Type:	Not reported
Contact Name:	NINO TASSI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

OUTLET CITY INC (Continued) **U001836097**

Zip Code:	Not reported
Country Code:	001
Phone:	(728) 786-4580
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	8894
Affiliation Type:	Emergency Contact
Company Name:	OUTLET CITY INC
Contact Type:	Not reported
Contact Name:	JOSEPH CONLEY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 286-4588
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank ID:	17346
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	7500
Install Date:	Not reported
Date Tank Closed:	08/01/1989
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

OUTLET CITY INC (Continued) **U001836097**

Tank Number: 002
Tank ID: 17347
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 7500
Install Date: Not reported
Date Tank Closed: 08/01/1989
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 003
Tank ID: 17348
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 10000
Install Date: Not reported
Date Tank Closed: 08/01/1989
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping

OUTLET CITY INC (Continued) **U001836097**

F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 004
Tank ID: 17349
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 10000
Install Date: Not reported
Date Tank Closed: 08/01/1989
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

HIST UST:
PBS Number: 2-237981
SPDES Number: Not reported
Emergency Contact: JOSEPH CONLEY
Emergency Telephone: (718) 286-4588
Operator: NINO TASSI
Operator Telephone: (728) 786-4580
Owner Name: OUTLET CITY INC
Owner Address: 42-16 WEST ST
Owner City,St,Zip: LONG ISLAND CITY, NY 11101
Owner Telephone: (728) 786-4580
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: OUTLET CITY INC
Mailing Address: 42-16 WEST ST
Mailing Address 2: Not reported
Mailing City,St,Zip: LONG ISLAND CITY, NY 11101
Mailing Contact: JOSEPH CONLEY
Mailing Telephone: (718) 786-4500
Owner Mark: First Owner

OUTLET CITY INC (Continued) **U001836097**

Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	42016 WEST ST
SWIS ID:	6301
Old PBS Number:	Not reported
Facility Type:	Not reported
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	07/20/1987
Expiration Date:	07/20/1992
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	No Missing Data
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	7500
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	08/01/1989
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place

OUTLET CITY INC (Continued) **U001836097**

Install Date:	Not reported
Capacity (gals):	7500
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	08/01/1989
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	003
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	10000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	08/01/1989
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	004
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	10000
Product Stored:	NOS 1,2, OR 4 FUEL OIL

OUTLET CITY INC (Continued) **U001836097**

Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	08/01/1989
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

---

170 WNW 1/8-1/4 0.231 mi. 1221 ft.

GANDER & WHITE SHIPPING, INC.
21-44 44TH ROAD
LONG ISLAND CITY, NY 11101

NY UST **U003065874**
NY HIST UST **N/A**

Relative: Higher

Actual: 17 ft.

UST:

Id/Status:	2-600010 / Unregulated
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588933.14479000005
UTM Y:	4511402.4546499997
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	22000
Affiliation Type:	Facility Owner
Company Name:	GANDER & WHITE SHIPPING, INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	21-44 44TH RD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-8444
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	22000
Affiliation Type:	Mail Contact
Company Name:	GANDER & WHITE SHIPPING, INC.
Contact Type:	Not reported

GANDER & WHITE SHIPPING, INC. (Continued) **U003065874**

Contact Name:	PAUL CANNON
Address1:	21-44 44TH ROAD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-8444
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	22000
Affiliation Type:	On-Site Operator
Company Name:	GANDER & WHITE SHIPPING, INC.
Contact Type:	Not reported
Contact Name:	PAUL CANNON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 784-8444
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	22000
Affiliation Type:	Emergency Contact
Company Name:	GANDER & WHITE SHIPPING, INC.
Contact Type:	Not reported
Contact Name:	PAUL CANNON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 784-8444
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank ID:	39946
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	3000
Install Date:	Not reported
Date Tank Closed:	11/18/2002
Registered:	True

GANDER & WHITE SHIPPING, INC. (Continued) **U003065874**

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 03
Date Test: 06/01/1998
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

HIST UST:
PBS Number: 2-600010
SPDES Number: Not reported
Emergency Contact: PAUL CANNON
Emergency Telephone: (718) 784-8444
Operator: PAUL CANNON
Operator Telephone: (718) 784-8444
Owner Name: GANDER & WHITE SHIPPING, INC.
Owner Address: 21-44 44TH RD
Owner City,St,Zip: LONG ISLAND CITY, NY 11101
Owner Telephone: (718) 784-8444
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: GANDER & WHITE SHIPPING, INC.
Mailing Address: 21-44 44TH RD
Mailing Address 2: Not reported
Mailing City,St,Zip: LONG ISLAND CITY, NY 11101
Mailing Contact: PAUL CANNON
Mailing Telephone: (718) 784-8444
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2: Not reported
SWIS ID: 6301
Old PBS Number: Not reported
Facility Type: TRUCKING/TRANSPORTATION
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 01/04/1996
Expiration Date: 03/13/2001

GANDER & WHITE SHIPPING, INC. (Continued) **U003065874**

Renew Flag:	False
Renewal Date:	11/13/2001
Total Capacity:	3000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City:	01
Region:	2
Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (gals):	3000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Diking
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	06/01/1998
Next Test Date:	06/01/2003
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

AF171 **23-10 43TH AVE** **NY AST** **U003385771**
NNW **23-10 43TH AVE** **NY HIST AST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.231 mi.
1222 ft. **Site 1 of 3 in cluster AF**

Relative:
Higher

Actual:
15 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-158623
Program Type:	PBS
UTM X:	589184.83565999998
UTM Y:	4511487.3042900003
Expiration Date:	2018/02/03
Site Type:	Apartment Building/Office Building

Affiliation Records:

23-10 43TH AVE (Continued) **U003385771**

Site Id:	5319
Affiliation Type:	Facility Owner
Company Name:	LONG ISLAND CITY CENTER, LLC
Contact Type:	DIRECTOR OF SUSTAINABILITY
Contact Name:	ROBERT SALVATORE
Address1:	1212 AVENUE OF THE AMERICAS (C/O STAWKI PARTNERS)
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10036
Country Code:	001
Phone:	(212) 697-8601
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	3/7/2013

Site Id:	5319
Affiliation Type:	Mail Contact
Company Name:	SUN GARD AVAILABILITY SERVICES
Contact Type:	Not reported
Contact Name:	GLENN GORLICH
Address1:	777 CENTRAL BOULEVARD
Address2:	Not reported
City:	CARLSTADT
State:	NJ
Zip Code:	07072
Country Code:	001
Phone:	(201) 729-2422
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	3/7/2013

Site Id:	5319
Affiliation Type:	On-Site Operator
Company Name:	SUN GARD AVAILABILITY SERVICES
Contact Type:	Not reported
Contact Name:	PETER CECERE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 391-7000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	3/7/2013

Site Id:	5319
Affiliation Type:	Emergency Contact
Company Name:	LONG ISLAND CITY CENTER, LLC
Contact Type:	Not reported
Contact Name:	SHARON REICHOLD
Address1:	Not reported

23-10 43TH AVE (Continued) **U003385771**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 391-4181
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	3/7/2013

Tank Info:

Tank Number:	TANK1
Tank Id:	8530
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E01 - Piping Secondary Containment - Diking (Aboveground)
J07 - Dispenser - Loading Rack/Transfer Pump
B00 - Tank External Protection - None
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/16/2001
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMMOLOUG
Last Modified:	03/07/2013
Material Name:	#2 Fuel Oil (On-Site Consumption)

Tank Number:	TANK2
Tank Id:	219000
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating

23-10 43TH AVE (Continued) **U003385771**

J03 - Dispenser - Gravity
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I01 - Overfill - Float Vent Valve
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/16/2001
Capacity Gallons:	330
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMMOLOUG
Last Modified:	03/07/2013
Material Name:	#2 Fuel Oil (On-Site Consumption)

Tank Number:	TANK3
Tank Id:	219001
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

J00 - Dispenser - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I03 - Overfill - Automatic Shut-Off
B01 - Tank External Protection - Painted/Asphalt Coating
G04 - Tank Secondary Containment - Double-Walled (Underground)
K00 - Spill Prevention - None
I02 - Overfill - High Level Alarm

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/16/2001
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMMOLOUG
Last Modified:	03/07/2013

23-10 43TH AVE (Continued) **U003385771**

Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number:	2-158623
SWIS Code:	6301
Operator:	PETER CECERE
Facility Phone:	(718) 391-7000
Facility Addr2:	23010 43TH AVE
Facility Type:	OTHER
Emergency:	PETER CECERE
Emergency Tel:	(718) 391-7769
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	CORDISCO INC
Owner Address:	5851 WEST SIDE AVENUE
Owner City,St,Zip:	NORTH BERGEN, NJ 07047
Federal ID:	Not reported
Owner Tel:	(201) 295-4329
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	MIKE DETORRES
Mailing Name:	CORDISCO INC
Mailing Address:	5851 WEST SIDE AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	NORTH BERGEN, NJ 07047
Mailing Telephone:	(201) 869-8300
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	02/04/2000
Expiration:	02/03/2003
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	5000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	5000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	0

23-10 43TH AVE (Continued) **U003385771**

Tank External:	00
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	Epoxy Liner
Pipe External:	00
Tank Containment:	None
Leak Detection:	0
Overfill Protection:	6
Dispenser Method:	Gravity
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

AF172 **EDR US Hist Auto Stat** **1015492607**
NNW **4309 23RD ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.233 mi.
1228 ft. **Site 2 of 3 in cluster AF**

Relative:
Higher

Actual:
15 ft.

EDR Historical Auto Stations:

Name:	JOE SAL AUTO BODY
Year:	2011
Address:	4309 23RD ST

AG173 **KRK EXPEDITING CO INC** **NY UST** **U000401652**
North **42-21 CRESCENT ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.235 mi.
1241 ft. **Site 1 of 4 in cluster AG**

Relative:
Higher

Actual:
20 ft.

UST:

Id/Status:	2-303690 / Unregulated
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589406.43241999997
UTM Y:	4511553.7025699997
Site Type:	Unknown

Affiliation Records:

Site Id:	13811
Affiliation Type:	Facility Owner
Company Name:	KRK EXPEDITING CO INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	42-21 CRESCENT ST
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101

KRK EXPEDITING CO INC (Continued) **U000401652**

Country Code:	001
Phone:	(718) 729-7588
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	13811
Affiliation Type:	Mail Contact
Company Name:	KRK EXPEDITING CO INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	42-21 CRESCENT ST
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 729-7588
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	13811
Affiliation Type:	On-Site Operator
Company Name:	KRK EXPEDITING CO INC
Contact Type:	Not reported
Contact Name:	KRK EXPEDITING CO INC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 729-7588
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	13811
Affiliation Type:	Emergency Contact
Company Name:	KRK EXPEDITING CO INC
Contact Type:	Not reported
Contact Name:	MR JOSEPH MCCARTHY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 729-7588
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

KRK EXPEDITING CO INC (Continued) **U000401652**

Tank Info:

Tank Number:	001
Tank ID:	16224
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	03/01/1980
Date Tank Closed:	09/01/1991
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel

AF174 **MTA NYCT - COURT SQUARE EFA LINE** **RCRA NonGen / NLR** **1004762640**
NNW **23RD ST & 43RD RD** **FINDS** **NYR000098988**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.236 mi.
1246 ft. **Site 3 of 3 in cluster AF**

Relative:
Higher

Actual:
15 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	MTA NYCT - COURT SQUARE EFA LINE
Facility address:	23RD ST & 43RD RD LONG ISLAND CITY, NY 11101
EPA ID:	NYR000098988
Mailing address:	BROADWAY 3RD FLOOR NEW YORK, NY 10004
Contact:	WILLIAM JEHLE
Contact address:	BROADWAY 3RD FLOOR NEW YORK, NY 10004
Contact country:	US
Contact telephone:	(646) 252-3500
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

MTA NYCT - COURT SQUARE EFA LINE (Continued) **1004762640**

Owner/Operator Summary:
Owner/operator name: MTA NEW YORK CITY TRANSIT
Owner/operator address: 2 BROADWAY 3RD FLOOR
NEW YORK, NY 10004
Owner/operator country: US
Owner/operator telephone: (646) 252-3500
Legal status: Other
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: MTA NEW YORK CITY TRANSIT
Owner/operator address: 2 BROADWAY 3RD FLOOR
NEW YORK, NY 10004
Owner/operator country: US
Owner/operator telephone: (646) 252-3500
Legal status: Other
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: MTA NYCT - COURT SQUARE EFA LINE
Classification: Not a generator, verified

Date form received by agency: 07/13/2001
Facility name: MTA NYCT - COURT SQUARE EFA LINE
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110007905017

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

MTA NYCT - COURT SQUARE EFA LINE (Continued) **1004762640**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AD175 **INTERNATIONAL DESIGN CENTER** **NY MANIFEST** **S106866721**
ESE **29-10 THOMPSON AVENUE** **NY Spills** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.236 mi.
1248 ft. **Site 5 of 6 in cluster AD**

Relative:
Higher

Actual:
30 ft.

NY MANIFEST:

EPA ID:	NYD986904100
Country:	USA
Mailing Name:	INTERNATIONAL DESIGN CENTER
Mailing Contact:	JOHN WRIGHT
Mailing Address:	29-10 THOMPSON AVENUE
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-729-2459

NY MANIFEST:

No Manifest Records Available

SPILLS:

Facility ID:	0412340
DER Facility ID:	273172
Facility Type:	ER
Site ID:	337831
DEC Region:	2
Spill Date:	2/18/2005
Spill Number/Closed Date:	0412340 / 5/16/2005
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2/18/2005
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2/22/2005
Spill Record Last Update:	2/22/2008
Spiller Name:	JURGIS NEMICKS

INTERNATIONAL DESIGN CENTER (Continued) **S106866721**

Spiller Company:	LAGUARDIA COLLEGE
Spiller Address:	2910 THOMPSON AVE
Spiller City,St,Zip:	LONG ISLAND CITY, NY
Spiller Company:	001
Contact Name:	JURGIS NEMICKS
Contact Phone:	(718) 609-2556
DEC Memo:	3/3/05 - Austin - Received 2/23/05 correspondece from Testwell Labs regarding this spill - forwarded to Tipple - end3/4/05 Tipple reviewed submittal, called Charles Schnugg from Testwell Labs, Confirmed that when removing the Hydraulic oil, it would be skimmed from the top down to prevent additional smear of the oil.5/16/05 reviewed submittal, called and clarified details, all cleaned, NFA
Remarks:	ELEVATOR PISTON NEEDS TO BE REPLACED AND THE PRODUCT IS ELEVATOR HYDROLIC FLUID IS IN THE CASING. THERE IS ABOUT 110 GALLONS AND THE PIT 48 FEET DOWN. AND GROUNDWATER IS 15 FT. FROM THE BOTTOM OF TEH CASING. THE BOTTOM OF THE CASING IS NOT CLOSED OFF AND TEH WATER IS COMING INTO THE CASING. ALL THE FLUID IS ON TOP OF THIS WATER BUT IT HAS BEEN CONTAINED. VAC TRUCK IS BEING SCHEDULED.

Material:

Site ID:	337831
Operable Unit ID:	1099842
Operable Unit:	01
Material ID:	580119
Material Code:	0064A
Material Name:	UNKNOWN MATERIAL
Case No.:	Not reported
Material FA:	Other
Quantity:	110
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Z176 **MIDTOWN OPERATING CORP** **NY UST** **U001835096**
North **42-50 24TH STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.238 mi.
1258 ft. **Site 2 of 2 in cluster Z**

Relative:
Higher

Actual:
17 ft.

UST:

Id/Status:	2-269336 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	2017/07/10
UTM X:	589289.82622000005
UTM Y:	4511554.0727500003
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	11264
Affiliation Type:	Facility Owner
Company Name:	MIDTOWN OPERATING CORP
Contact Type:	PRESIDENT

MIDTOWN OPERATING CORP (Continued) **U001835096**

Contact Name:	RONALD SHERMAN
Address1:	42-50 24TH ST
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 937-2080
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/16/2008

Site Id:	11264
Affiliation Type:	Mail Contact
Company Name:	MIDTOWN OPERATING CORP
Contact Type:	Not reported
Contact Name:	MR. RONALD SHERMAN
Address1:	42-50 24TH ST
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 937-2080
EMail:	RSTAXI2AOL.COM
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	5/17/2012

Site Id:	11264
Affiliation Type:	On-Site Operator
Company Name:	MIDTOWN OPERATING CORP
Contact Type:	Not reported
Contact Name:	RON SHERMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 937-2080
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/10/2011

Site Id:	11264
Affiliation Type:	Emergency Contact
Company Name:	MIDTOWN OPERATING CORP
Contact Type:	Not reported
Contact Name:	MR HUGH MCKEAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported

MIDTOWN OPERATING CORP (Continued) **U001835096**

Country Code:	999
Phone:	(718) 937-2080
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/16/2008

Tank Info:

Tank Number:	001
Tank ID:	13604
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	04/01/1972
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	21
Date Test:	03/24/2011
Next Test Date:	03/24/2016
Pipe Model:	Not reported
Modified By:	MSBAPTIS
Last Modified:	05/17/2012

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F08 - Pipe External Protection - Retrofitted Impressed Current
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
B08 - Tank External Protection - Retrofitted Impressed Current
K01 - Spill Prevention - Catch Basin
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number:	002
Tank ID:	13605
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	07/01/1977
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

MIDTOWN OPERATING CORP (Continued) **U001835096**

Tightness Test Method: 21
Date Test: 03/24/2011
Next Test Date: 03/24/2016
Pipe Model: Not reported
Modified By: MSBAPTIS
Last Modified: 05/17/2012

Equipment Records:

A03 - Tank Internal Protection - Fiberglass Liner (FRP)
B08 - Tank External Protection - Retrofitted Impressed Current
K01 - Spill Prevention - Catch Basin
D01 - Pipe Type - Steel/Carbon Steel/Iron
F08 - Pipe External Protection - Retrofitted Impressed Current
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
H05 - Tank Leak Detection - In-Tank System (ATG)
I00 - Overfill - None

Tank Number: 003
Tank ID: 13606
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 11/01/1961
Date Tank Closed: 01/24/2008
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 02/22/2008

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
I00 - Overfill - None

Tank Number: 004
Tank ID: 13607
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 1080

MIDTOWN OPERATING CORP (Continued) **U001835096**

Install Date:	11/01/1961
Date Tank Closed:	01/24/2008
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	02/22/2008

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
I00 - Overfill - None

AH177 **GOTHAM CENTER TOWER B-2** **RCRA-LQG** **1012186279**
NNE **42-01 28TH STREET** **NYR000161406**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.242 mi.
1279 ft. **Site 1 of 3 in cluster AH**

Relative:
Higher

Actual:
23 ft.

RCRA-LQG:

Date form received by agency:	04/16/2010
Facility name:	GOTHAM CENTER TOWER B-2
Facility address:	42-01 28TH STREET LONG ISLAND CITY, NY 11101
EPA ID:	NYR000161406
Mailing address:	ROCKEFELLER PLAZA 12TH FLOOR NEW YORK, NY 10111
Contact:	GEORGE HATZMANN
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 715-0528
Contact email:	GHATZMAN@TISHMANSPEYER.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than

GOTHAM CENTER TOWER B-2 (Continued) **1012186279**

100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	LIC SITE B OWNER L.L.C. C/O TISHMAN SPE
Owner/operator address:	ROCKEFELLER PLAZA 12TH FLOOR
	NEW YORK, NY 10111
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	10/08/2008
Owner/Op end date:	Not reported

Owner/operator name:	NEW YORK CITY ECONOMIC DEVELOPMENT CORP
Owner/operator address:	WILLIAM ST
	NEW YORK, NY 10038
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Other
Owner/Operator Type:	Owner
Owner/Op start date:	10/07/2008
Owner/Op end date:	Not reported

Owner/operator name:	LIC SITE B-2 OWNER LLC-C/O TISHMAN SPEYE
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	10/08/2008
Owner/Op end date:	Not reported

Owner/operator name:	LIC SITE B OWNER L.L.C. C/O TISHMAN SPE
Owner/operator address:	ROCKEFELLER PLAZA 12TH FLOOR
	NEW YORK, NY 10111
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	10/08/2008
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

GOTHAM CENTER TOWER B-2 (Continued) **1012186279**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/09/2009
Facility name: GOTHAM CENTER TOWER B-2
Site name: GOTHAM CENTER TOWER B-2
Classification: Large Quantity Generator

Date form received by agency: 12/17/2008
Facility name: GOTHAM CENTER TOWER B-2
Site name: GOTHAM CENTER TOWER B-2
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: D008
Waste name: LEAD

Waste code: D008
Waste name: LEAD

Violation Status: No violations found

---

178 **EDR US Hist Auto Stat** **1015486495**
NNE **4206 27TH ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.243 mi.
1285 ft.

Relative:
Higher

Actual:
22 ft.

EDR Historical Auto Stations:
Name: AUTO EXPRESS
Year: 2002
Address: 4206 27TH ST

AH179 **NYC EDC - GOTHAM CENTER TOWER B-2** **NY MANIFEST** **S109826458**
NNE **42-01 28TH STREET** **NY Spills** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.244 mi.
1290 ft. **Site 2 of 3 in cluster AH**

Relative:
Higher

Actual:
23 ft.

NY MANIFEST:
EPA ID: NYR000161406
Country: USA
Mailing Name: NYC EDC - GOTHAM CENTER TOWER B-2
Mailing Contact: FUMILIO COPPARD
Mailing Address: 110 WILLIAM ST
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10038
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 858-251-9980

NYC EDC - GOTHAM CENTER TOWER B-2 (Continued) **S109826458**

NY MANIFEST:

No Manifest Records Available

SPILLS:

Facility ID:	0902823
DER Facility ID:	364033
Facility Type:	ER
Site ID:	414887
DEC Region:	2
Spill Date:	6/9/2009
Spill Number/Closed Date:	0902823 / 9/7/2011
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	6/9/2009
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	6/9/2009
Spill Record Last Update:	5/1/2012
Spiller Name:	LEE BENEDICT NYC ECONOMIC DEVELOPMENT CORP
Spiller Company:	OWNER OF THE PROPERTY
Spiller Address:	42-01 28TH ST
Spiller City,St,Zip:	LONG ISLAND CITY, NY
Spiller Company:	999
Contact Name:	LEE BENEDICT NYC ECONOMIC DEVELOPMENT CORP
Contact Phone:	(212) 312-3623
DEC Memo:	Former 3 level municipal parking garage at corner of Jackson Ave and Queens Plaza South. Owner Contact: Lee Benedict - NYC Economic Development Corp. 212-312-3623Consultant Contact: Mohamed Ahmed - Fleming Lee Shue 212-675-322507/02/09 CSL was sent to NYC Economic Development Corp.110 William Street, 6th FloorNew York City, NY 10038Attn: Lee Benedict(sr)08/04/09 Rec'd letter requesting extension to perform subsurface investigation from Fleming Lee & Shue.(sr)12/17/09 Remedial Work Plan in file.STIP has been sent out for RP's signature.(sr)05/10/10 Work Plan dated Jan 06,2010 approved.(sr)09/07/11 Reviewing Investigation Summary Report prepared by Fleming Lee Shue. Investigation was performed in Nov/December 2010 to delineate the contamination found in proximity to the former filling station, to determine if the contamination had impacted the ground water beneath the site.Seventeen soil borings were advanced to depths ranging from 20 to 26 ft and three ground water monitoring wells were installed and sampled.Two wells were advanced downgradient and one well was advanced upgradient of the spill.VOCS in soil and ground water are slightly above the CP-51 guidance value.No further action required.Case closed.All reports are in edocs.(sr)** Spill

NYC EDC - GOTHAM CENTER TOWER B-2 (Continued) **S109826458**

closure letter issued and was sent toLIC Site B, L.L.C.C/O Tishman Speyer45 Rockefeller PlazaNew York, NY 10111Attention: Patrick Shiels&New York City Economic Development Corporation (NYCEDC)110 William Street, 6th FloorNew York, NY 10038.Attention: Kay Zias

Remarks: Clean up is pending. Soil will be excavated.

Material:

Site ID:	414887
Operable Unit ID:	1171259
Operable Unit:	01
Material ID:	2163051
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

AI180 **ANTHONY CONCRETE** **NY CBS AST** **S102639396**
SSE **47-17 27TH ST** **NY CBS** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.245 mi.
1293 ft. **Site 1 of 2 in cluster AI**

Relative:
Lower

Actual:
11 ft.

CBS AST:

CBS Number:	2-000181
ICS Number:	2-700754
PBS Number:	Not reported
MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	ACTIVE FACILITY
Facility Type:	MANUFACTURING
Telephone:	(718) 729-4351
Facility Town:	NEW YORK CITY
Region:	STATE
Expiration Date:	09/22/1997
Total Capacity of All Active Tanks(gal):	0
Operator:	LEE PRINCIPE
Emergency Contact:	CHARLES LUGINBILL
Emergency Phone:	(201) 933-8800
Owner Name:	SIKA CORPORATION
Owner Address:	201 POLITO AVE.
Owner City,St,Zip:	LYNDHURST, NJ 07071
Owner Telephone:	(201) 933-8800
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	SIKA CORPORATION
Mail Contact Addr:	201 POLITO AVE.
Mail Contact Addr2:	Not reported
Mail Contact Contact:	CHARLES LUGINBILL
Mail Contact City,St,Zip:	LYNDHURST, NJ 07071
Mail Phone:	(201) 933-8800

ANTHONY CONCRETE (Continued) **S102639396**

Tank Id:	18011
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	0
Install Date:	04/85
Tank Closed:	00/00
Capacity (Gal):	275
Chemical:	Sodium hydroxide
Tank Location:	ABOVEGROUND
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Containment:	None
Tank Error Status:	No Missing Data
Date Entered:	09/22/1989
Certified Date:	08/31/1995
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	OTHER
Pipe Internal:	None
Pipe External:	0
Pipe Containment:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	None
Haz Percent:	2
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	06/07/93
Is It There:	False
Delinquent:	False
Date Expired:	09/22/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	06/06/1997

Tank Id:	18012
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	0
Install Date:	04/85
Tank Closed:	00/00
Capacity (Gal):	275
Chemical:	Sodium hydroxide
Tank Location:	ABOVEGROUND
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Containment:	None

ANTHONY CONCRETE (Continued) **S102639396**

Tank Error Status:	No Missing Data
Date Entered:	09/22/1989
Certified Date:	08/31/1995
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	OTHER
Pipe Internal:	None
Pipe External:	0
Pipe Containment:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	None
Haz Percent:	2
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	06/07/93
Is It There:	False
Delinquent:	False
Date Expired:	09/22/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	06/06/1997

CBS:

CBS Number:	2-000181
Program Type:	CBS
Facility Status:	Unregulated
Expiration Date:	N/A
Dec Region:	2
UTMX:	589308.28916000
UTMY:	4510560.0018600

AI181 **FORDHAM ROAD CONCRETE** **NY UST** **U004118669**
SSE **47-17 27TH STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.245 mi.
1293 ft. **Site 2 of 2 in cluster AI**

Relative:
Lower

Actual:
11 ft.

UST:

Id/Status:	2-610744 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	2013/02/01
UTM X:	589308.28916000004
UTM Y:	4510560.0018600002
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	391815
Affiliation Type:	Facility Owner

FORDHAM ROAD CONCRETE (Continued) **U004118669**

Company Name:	FORDHAM ROAD CONCRETE CORP.
Contact Type:	PRESIDENT
Contact Name:	ARTHUR GEORGE REIS
Address1:	47-17 27TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 433-0111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	bkfalvey
Date Last Modified:	11/6/2008

Site Id:	391815
Affiliation Type:	Mail Contact
Company Name:	FORDHAM ROAD CONCRETE CORP.
Contact Type:	Not reported
Contact Name:	GEORGE REIS
Address1:	47-17 27TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 433-0111
EMail:	NYCONREADYMIX@AOL.COM
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	1/4/2008

Site Id:	391815
Affiliation Type:	On-Site Operator
Company Name:	FORDHAM ROAD CONCRETE
Contact Type:	Not reported
Contact Name:	GEORGE REIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 433-0111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	bkfalvey
Date Last Modified:	11/6/2008

Site Id:	391815
Affiliation Type:	Emergency Contact
Company Name:	FORDHAM ROAD CONCRETE CORP.
Contact Type:	Not reported
Contact Name:	GEORGE REIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported

FORDHAM ROAD CONCRETE (Continued) **U004118669**

State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 417-9474
EMail:	Not reported
Fax Number:	Not reported
Modified By:	bkfalvey
Date Last Modified:	11/6/2008

Tank Info:

Tank Number:	001
Tank ID:	221027
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	02/01/1998
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	CGFREEDM
Last Modified:	09/17/2013

Equipment Records:

B04 - Tank External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
D10 - Pipe Type - Copper
J02 - Dispenser - Suction Dispenser
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
E04 - Piping Secondary Containment - Double-Walled (Underground)

Tank Number:	002
Tank ID:	221028
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	3000
Install Date:	02/01/1998
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008

FORDHAM ROAD CONCRETE (Continued) **U004118669**

Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: CGFREEDM
Last Modified: 09/17/2013

Equipment Records:

E04 - Piping Secondary Containment - Double-Walled (Underground)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
D10 - Pipe Type - Copper
J02 - Dispenser - Suction Dispenser
G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

Tank Number: 003
Tank ID: 241665
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 2000
Install Date: 02/01/1985
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: 02/01/1995
Pipe Model: Not reported
Modified By: CGFREEDM
Last Modified: 09/17/2013

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
L00 - Piping Leak Detection - None

FORDHAM ROAD CONCRETE (Continued) **U004118669**

Tank Number:	004
Tank ID:	241666
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	2000
Install Date:	02/01/1985
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	02/01/1995
Pipe Model:	Not reported
Modified By:	CGFREEDM
Last Modified:	09/17/2013

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
K00 - Spill Prevention - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle

AG182 **42-15 CRESENT ST** **NY HIST UST** **U001833283**
North **42-15 CRESCENT ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.245 mi.
1294 ft. **Site 2 of 4 in cluster AG**

Relative:
Higher

Actual:
21 ft.

HIST UST:

PBS Number:	2-155969
SPDES Number:	Not reported
Emergency Contact:	ALAN KAHN
Emergency Telephone:	(212) 947-0155
Operator:	ALAN KAHN/GOE
Operator Telephone:	(718) 937-9611
Owner Name:	ALAN KAHN ASSOC.
Owner Address:	240 WEST 35TH STREET
Owner City,St,Zip:	NEW YORK, NY 10018
Owner Telephone:	(212) 947-0155
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	42-15 CRESCENT ST.
Mailing Address:	42-15 CRESCENT ST.
Mailing Address 2:	LONG ISLAND CITY
Mailing City,St,Zip:	NEW YORK, NY 11101
Mailing Contact:	SUPERINTENDENT OR MANAGER

42-15 CRESENT ST (Continued) **U001833283**

Mailing Telephone:	(718) 937-9611
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	42015 CRESCENT ST
SWIS ID:	6301
Old PBS Number:	Not reported
Facility Type:	Not reported
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	08/12/1997
Expiration Date:	08/24/2002
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	12000
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (gals):	12000
Product Stored:	NOS 5 OR 6 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Diking
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
Lat/long:	Not reported

AG183 **42-15 CRESENT ST** **NY AST** **A100298588**
North **42-15 CRESCENT STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.245 mi.
1294 ft. **Site 3 of 4 in cluster AG**

Relative:
Higher

Actual:
21 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-155969
Program Type:	PBS
UTM X:	589412.74254999997
UTM Y:	4511562.54959
Expiration Date:	2017/08/24
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	5081
Affiliation Type:	Facility Owner
Company Name:	ALAN KAHN ASSOC.
Contact Type:	AGENT
Contact Name:	ALAN KAHN
Address1:	123 WILLIAM ST 22ND FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 947-0155
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	9/6/2012

Site Id:	5081
Affiliation Type:	Mail Contact
Company Name:	SUPERINTENDENT OR MANAGER
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	42-15 CRESCENT STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-4324
EMail:	AKAHNINC@AOL.COM
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	9/6/2012

Site Id:	5081
Affiliation Type:	On-Site Operator
Company Name:	42-15 CRESENT ST
Contact Type:	Not reported
Contact Name:	ALAN KAHN
Address1:	Not reported
Address2:	Not reported
City:	Not reported

42-15 CRESENT ST (Continued) **A100298588**

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 937-9611
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 6/19/2006

Site Id: 5081
Affiliation Type: Emergency Contact
Company Name: ALAN KAHN ASSOC.
Contact Type: Not reported
Contact Name: ALAN KAHN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 571-7959
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 9/6/2012

Tank Info:

Tank Number: 002
Tank Id: 212273
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 04/03/2006
Capacity Gallons: 6000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported

42-15 CRESENT ST (Continued) **A100298588**

Register:	True
Modified By:	NRLOMBAR
Last Modified:	06/19/2006
Material Name:	#6 Fuel Oil (On-Site Consumption)

AG184 **42-15 CRESENT ST** **NY UST** **U004076474**
North **42-15 CRESCENT STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.245 mi.
1294 ft. **Site 4 of 4 in cluster AG**

Relative:
Higher

Actual:
21 ft.

UST:

Id/Status:	2-155969 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	2017/08/24
UTM X:	589412.74254999997
UTM Y:	4511562.54959
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	5081
Affiliation Type:	Facility Owner
Company Name:	ALAN KAHN ASSOC.
Contact Type:	AGENT
Contact Name:	ALAN KAHN
Address1:	123 WILLIAM ST 22ND FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 947-0155
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	9/6/2012

Site Id:	5081
Affiliation Type:	Mail Contact
Company Name:	SUPERINTENDENT OR MANAGER
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	42-15 CRESCENT STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-4324
EMail:	AKAHNINC@AOL.COM
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	9/6/2012

Site Id:	5081
Affiliation Type:	On-Site Operator

42-15 CRESENT ST (Continued) **U004076474**

Company Name:	42-15 CRESENT ST
Contact Type:	Not reported
Contact Name:	ALAN KAHN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 937-9611
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	6/19/2006

Site Id:	5081
Affiliation Type:	Emergency Contact
Company Name:	ALAN KAHN ASSOC.
Contact Type:	Not reported
Contact Name:	ALAN KAHN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 571-7959
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	9/6/2012

Tank Info:

Tank Number:	001
Tank ID:	8473
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	12000
Install Date:	Not reported
Date Tank Closed:	05/30/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	06/19/2006

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

42-15 CRESENT ST (Continued) **U004076474**

J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
G03 - Tank Secondary Containment - Vault (w/o access)
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)

AH185 **TWO GOTHAM CENTER** **NY AST** **A100356942**
NNE **42-09 28TH ST** **N/A**
1/8-1/4 **QUEENS, NY 11101**
0.245 mi.
1294 ft. **Site 3 of 3 in cluster AH**

Relative:
Higher

Actual:
23 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-611586
Program Type:	PBS
UTM X:	589568.73852000001
UTM Y:	4511513.9805899998
Expiration Date:	2014/08/07
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	449064
Affiliation Type:	Facility Owner
Company Name:	LIC SITE B-2 OWNER,LLC
Contact Type:	MGR
Contact Name:	LAWRENCE J. SPAHN
Address1:	42-09 28TH ST
Address2:	Not reported
City:	LIC
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 361-4500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	5/12/2011

Site Id:	449064
Affiliation Type:	Mail Contact
Company Name:	TISHMAN SPEYER
Contact Type:	Not reported
Contact Name:	LAWRENCE J. SPAHN
Address1:	42-09 28TH ST
Address2:	Not reported
City:	LIC
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 361-4500
EMail:	Not reported
Fax Number:	Not reported

TWO GOTHAM CENTER (Continued) **A100356942**

Modified By: MSBAPTIS
Date Last Modified: 5/12/2011

Site Id: 449064
Affiliation Type: On-Site Operator
Company Name: TWO GOTHAM CENTER
Contact Type: Not reported
Contact Name: LAWRENCE J. SPAHN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 361-4500
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 5/12/2011

Site Id: 449064
Affiliation Type: Emergency Contact
Company Name: LIC SITE B-2 OWNER,LLC
Contact Type: Not reported
Contact Name: PAUL SCIALLIS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 652-9924
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 5/12/2011

Tank Info:

Tank Number: C617796
Tank Id: 239265
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
K01 - Spill Prevention - Catch Basin
C01 - Pipe Location - Aboveground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm

TWO GOTHAM CENTER (Continued) **A100356942**

	F05 - Pipe External Protection - Jacketed
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/07/2009
Capacity Gallons:	13000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	05/12/2011
Material Name:	#2 Fuel Oil (On-Site Consumption)

186
North
1/8-1/4
0.246 mi.
1298 ft.

CON ED - V 7677 **RCRA NonGen / NLR** **1007206106**
W/S 24 ST/42 RD **NYP004003646**
ASTORIA, NY 11105

Relative:
Higher

Actual:
18 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/28/1998
Facility name:	CON ED - V 7677
Facility address:	W/S 24 ST/42 RD ASTORIA, NY 111050000
EPA ID:	NYP004003646
Mailing address:	CONSOLIDATED EDISON INC 4 IRVING PL RM 310 NEW YORK, NY 100030000
Contact:	ANTHONY DRUMMINGS
Contact address:	CONSOLIDATED EDISON INC NEW YORK, NY 100030000
Contact country:	US
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON ED - V 7677 (Continued) **1007206106**

Historical Generators:
Date form received by agency: 02/27/1998
Facility name: CON ED - V 7677
Classification: Not a generator, verified

Date form received by agency: 02/26/1998
Facility name: CON ED - V 7677
Classification: Large Quantity Generator

Violation Status: No violations found

AD187 **EDR US Hist Cleaners** **1015061951**
ESE **4420 30TH ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.248 mi.
1310 ft. **Site 6 of 6 in cluster AD**

Relative: Higher

Actual: 30 ft.

EDR Historical Cleaners:
Name: FRESH LOOK LAUNDROMAT INC
Year: 2006
Address: 4420 30TH ST

Name: FRESH LOOK LAUNDROMAT INC
Year: 2007
Address: 4420 30TH ST

AJ188 **ON SIDEWALK** **NY LTANKS** **S105995094**
SSW **47-15 PEARSON PL** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.263 mi.
1389 ft. **Site 1 of 2 in cluster AJ**

Relative: Higher

Actual: 16 ft.

LTANKS:
Site ID: 287873
Spill Number/Closed Date: 0110585 / 7/31/2003
Spill Date: 2/5/2002
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 4101
Investigator: MXTIPPLE
Referred To: Not reported
Reported to Dept: 2/5/2002
CID: 397
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2/5/2002
Spill Record Last Update: 7/31/2003
Spiller Name: CALLER
Spiller Company: BRIDGE TRANSPORTATION

ON SIDEWALK (Continued) **S105995094**

Spiller Address:	176 27TH ST
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	233188
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE"7/31/2003 tipple updating//sidewalk has been cleaned.//nfa
Remarks:	DRIVER OVERFILLED THE TANK

Material:

Site ID:	287873
Operable Unit ID:	849053
Operable Unit:	01
Material ID:	528206
Material Code:	0002A
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	12
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

189
NE
1/4-1/2
0.268 mi.
1416 ft.

Relative: Higher

Actual: 22 ft.

OUTLET CITY, QUEENS BLVD. & JACKSON AVE. **NY VCP** **S105684691**
QUEENS BLVD. & JACKSON AVE., L.I.C. **N/A**
LONG ISLAND CITY, NY 11101

VCP:

Program Type:	VCP
Site Code:	58261
HW Code:	V00081
Site Class:	A
SWIS:	4101
Region:	2
Town:	New York City
Acres:	2.500
Date Record Added:	11/30/2000
Date Record Updated:	11/16/2012
Updated By:	JAMORAS
Site Description:	Location: The site is located in Queens County, on Jackson Ave between Orchard Street to the east, Queens Blvd. to the west and Long Island Railroad yard to the south. The G-Train runs underneath Jackson Avenue bordering the site to the north. The nearest residential structure is located approximately 100ft to the west across Orchard street. Site Features: This 2.5 acre site consists of 12 multi-story buildings and associated parking area located in a congested commercial/industrial area of Queens County. The only occupied structure on-site is a NYC Transit Authority building.

OUTLET CITY, QUEENS BLVD. & JACKSON AVE. (Continued) **S105684691**

Current Zoning/Uses(s): The current zoning at the site is Industrial and Retail. The surrounding area is zoned Special Long Island City Mixed Use District (LIC) and is a longstanding mix of residential, commercial, industrial and cultural uses at varying densities.Historical Uses: The site had formerly been used for chemical manufacturing. From 1901-1978, West Chemical Co. owned the property and manufactured commercial and disinfectant products such as disinfectants, insecticides, soaps, floor wax, and paper products dispensing machines. Manufacturing operations employed various chemical substances including creosote, coal and acids, cresylic acids, degreasing solvents, iodine, and assorted oils and pesticides. Metal plating and gasoline filling operations were also conducted at the property. In 11/78, Outlet City acquired title to the property from West Chemical. During Outlet City's ownership, a flea market and various vendor operations have been conducted at the property. The site is being investigated under the Voluntary Cleanup Program (VCP) under a 1997 agreement. Previous investigations in the late 1980's and early 1990's led to the property entering the VCP.Site Geology and Hydrogeology: Site geology consists of mostly sand at varying depths due to presence of shallow bedrock. Groundwater is approximately 8 -10ft below grade

Env Problem: Nature and Extent of Contamination: The site is contaminated with creosote, petroleum, and solvents. Both soil and groundwater are affected. The majority of the contamination is located in Areas D and E where Creosote in the form of both LNAPL (Light Non-Aqueous Phase Liquid) and DNAPL (Dense Non-Aqueous Phase Liquid) is present. LNAPL in Area D & E ranges from 0 - 6ft.Total on-site VOCs (Volatile Organic Compounds) including both chlorinated hydrocarbons and petroleum constituents are present in groundwater from non-detect - 30,000ppb. Total on-site SVOCs (Semi-Volatile Organic Compounds) are present in groundwater from non-detect to over 100,000ppb. An off-site investigation has not been completed at this site. A ventilation IRM is in place in the basement of building No. 4, where creosote LNAPL enters the basement during large rain events. The ventilation system was designed and installed in 2004. The ventilation system was started up on June 8, 2004. The final engineering report for this IRM was approved in September 2006. Bi-annual air testing is collected to evaluate the effectiveness of the ventilation IRM.

Health Problem: Exposures to contaminated groundwater is not expected because the area is served by public water. Soils contaminated with etrachloroethene are beneath the site, however, exposure to this soil is not expected because the site is capped with asphalt. Indoor air samples collected in a portion of the on-site building contained levels of tetrachloroethene that exceeded the New York State Department of Health Guideline for tetrachloroethene in Indoor Air. NYSDOH and NYSDEC will evaluate the need for additional investigations to determine the potential for soil vapor intrusion into structures near the site.

AJ190 **J MANHEIMER INC** **NY LTANKS** **U001837339**
SSW **47-22 PEARSON PL** **NY UST** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101** **NY MANIFEST**
0.275 mi. **NY Spills**
1452 ft. **Site 2 of 2 in cluster AJ**

Relative:
Higher

Actual:
16 ft.

LTANKS:

Site ID:	174994
Spill Number/Closed Date:	9206718 / 7/29/1993
Spill Date:	9/10/1992
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	7/29/1993
Cleanup Meets Standard:	True
SWIS:	4101
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	9/10/1992
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	9/14/1992
Spill Record Last Update:	7/29/1993
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	147125
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "BATTSTA"07/29/93: AIR TEST PASSED PRECISION RETEST WITH WATER PASSED CLOSED IN PLACE WITH FOAM SEE K ODOWDS LETTER 4722P.
Remarks:	TO PUMP TANK OUT & INVEST POLL AIR POCKET.

Material:

Site ID:	174994
Operable Unit ID:	970511
Operable Unit:	01
Material ID:	407415
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

J MANHEIMER INC (Continued) **U001837339**

Tank Test:
- Site ID: 174994
- Spill Tank Test: 1540542
- Tank Number: Not reported
- Tank Size: 0
- Test Method: 00
- Leak Rate: 0
- Gross Fail: Not reported
- Modified By: Spills
- Last Modified: 10/1/2004
- Test Method: Unknown

UST:
- Id/Status: 2-369810 / Unregulated
- Program Type: PBS
- Region: STATE
- DEC Region: 2
- Expiration Date: N/A
- UTM X: 589268.80539999995
- UTM Y: 4510740.7940800004
- Site Type: Manufacturing (Other than Chemical)/Processing

Affiliation Records:
- Site Id: 18654
- Affiliation Type: Facility Owner
- Company Name: J MANHEIMER INC
- Contact Type: Not reported
- Contact Name: Not reported
- Address1: 47-22 PEARSON PL
- Address2: Not reported
- City: LONG ISLAND CITY
- State: NY
- Zip Code: 11101
- Country Code: 001
- Phone: (718) 392-7800
- EMail: Not reported
- Fax Number: Not reported
- Modified By: CGFREEDM
- Date Last Modified: 12/14/2004

- Site Id: 18654
- Affiliation Type: Mail Contact
- Company Name: J MANHEIMER INC
- Contact Type: Not reported
- Contact Name: MICHAEL I. LONDNER
- Address1: 47-22 PEARSON PL
- Address2: Not reported
- City: LONG ISLAND CITY
- State: NY
- Zip Code: 11101
- Country Code: 001
- Phone: (718) 392-7800
- EMail: Not reported
- Fax Number: Not reported
- Modified By: CGFREEDM
- Date Last Modified: 12/14/2004

J MANHEIMER INC (Continued) **U001837339**

Site Id:	18654
Affiliation Type:	On-Site Operator
Company Name:	J MANHEIMER INC
Contact Type:	Not reported
Contact Name:	J MANHEIMER INC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 392-7800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	18654
Affiliation Type:	Emergency Contact
Company Name:	J MANHEIMER INC
Contact Type:	Not reported
Contact Name:	MICHAEL I. LONDNER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 368-4906
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank ID:	21329
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	5000
Install Date:	12/01/1940
Date Tank Closed:	08/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	10
Date Test:	07/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

J MANHEIMER INC (Continued) **U001837339**

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
A01 - Tank Internal Protection - Epoxy Liner
G00 - Tank Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H03 - Tank Leak Detection - Vapor Well

NY MANIFEST:

EPA ID:	NYD980781322
Country:	USA
Mailing Name:	SHOWMAN FABRICATORS INC
Mailing Contact:	ED MARRERO
Mailing Address:	47-22 PEARSON PLACE
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-392-7800

NY MANIFEST:

No Manifest Records Available

SPILLS:

Facility ID:	8900343
DER Facility ID:	147125
Facility Type:	ER
Site ID:	174993
DEC Region:	2
Spill Date:	4/12/1989
Spill Number/Closed Date:	8900343 / 4/26/1989
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	4101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	4/12/1989
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	4/26/1989
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	5/22/1989
Spill Record Last Update:	5/27/2003
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported

J MANHEIMER INC (Continued) **U001837339**

Spiller City,St,Zip: ***Update***, ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Not reported
Remarks: VALVE ACCIDENTLY OPENED, SPILL INITIALLY ON CONCRETE FLOOR, THEN RAN TO GROUND OUTSIDE.

Material:
Site ID: 174993
Operable Unit ID: 926745
Operable Unit: 01
Material ID: 451684
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 250
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

191 WNW 1/4-1/2 0.280 mi. 1476 ft. **CONDEA SUPPLY CORP** **NY LTANKS** **U003241856**
21-21 44TH RD **N/A**
LONG ISLAND CITY, NY

Relative: Higher

Actual: 16 ft.

LTANKS:
Site ID: 59951
Spill Number/Closed Date: 0306979 / 6/21/2006
Spill Date: 10/2/2003
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 4101
Investigator: HRPATEL
Referred To: Not reported
Reported to Dept: 10/2/2003
CID: 257
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 10/2/2003
Spill Record Last Update: 6/21/2006
Spiller Name: MICHAEL MIAO
Spiller Company: CONDEA SUPPLY CORP
Spiller Address: 21-21 44TH RD

CONDEA SUPPLY CORP (Continued) **U003241856**

Spiller City,St,Zip:	LONG ISLAND CITY, NY
Spiller County:	001
Spiller Contact:	MICHAEL MIAO
Spiller Phone:	(718) 392-3232
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	58600
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"Sent TTF letter05/22/06-Hiralkumar Patel. Left message for Jim at Protest.06/21/06-Hiralkumar Patel. Visited site. manager gave me tank test result. test done on 11/11/2003 and whole system passed test. loose manhole cover was reason behind failure first time.based on available information, case is closed.
Remarks:	Not reported

Material:

Site ID:	59951
Operable Unit ID:	875736
Operable Unit:	01
Material ID:	500576
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

192
NNE
1/4-1/2
0.302 mi.
1592 ft.

FALIDAS ASSCOCIATES
25-01 QUEENS PLAZA N
LONG ISLAND CITY, NY 11101

RCRA-CESQG **1007264881**
NY LTANKS **NYR000123547**
NY MANIFEST
NJ MANIFEST

Relative:
Higher

Actual:
25 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	FALIDAS ASSCOCIATES
Facility address:	25-01 QUEENS PLAZA N LONG ISLAND CITY, NY 11101
EPA ID:	NYR000123547
Mailing address:	QUEENS PLAZA N LONG ISLAND CITY, NY 11101
Contact:	GEORGE V FALIDAS
Contact address:	QUEENS PLAZA N LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	(718) 392-0514
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time;

FALIDAS ASSCOCIATES (Continued) **1007264881**

or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	FALIDAS ASSOCIATES
Owner/operator address:	QUEENS PLAZA N LONG ISLAND CITY, NY 11101
Owner/operator country:	US
Owner/operator telephone:	(718) 392-0514
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	04/04/1984
Owner/Op end date:	Not reported

Owner/operator name:	GEORGE FALIDAS
Owner/operator address:	QUEENS PLAZA N LONG ISLAND CITY, NY 11101
Owner/operator country:	US
Owner/operator telephone:	(718) 392-0514
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	04/04/1984
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Facility name:	FALIDAS ASSCOCIATES
Classification:	Conditionally Exempt Small Quantity Generator

FALIDAS ASSCOCIATES (Continued) **1007264881**

Date form received by agency: 03/30/2004
Facility name: FALIDAS ASSCOCIATES
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

LTANKS:
Site ID: 237933
Spill Number/Closed Date: 8905133 / 11/19/1992
Spill Date: 8/23/1989
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: 11/19/1992
Cleanup Meets Standard: False
SWIS: 4101
Investigator: BATTISTA
Referred To: Not reported
Reported to Dept: 8/23/1989
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 9/6/1989
Spill Record Last Update: 1/7/2004
Spiller Name: Not reported
Spiller Company: FALIDAS ASSOCIATES
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 195968
DEC Memo: Not reported
Remarks: 5K TANK FAILED HORNER EZY CHECK, STOPPED TEST, MANHOLE LEAKING, WILL REPLACE GASKET & RETEST.

Material:
Site ID: 237933
Operable Unit ID: 930454
Operable Unit: 01
Material ID: 445573
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

FALIDAS ASSCOCIATES (Continued) **1007264881**

Tank Test:

Site ID:	237933
Spill Tank Test:	1535902
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

Site ID:	66252
Spill Number/Closed Date:	0305348 / 5/21/2007
Spill Date:	8/1/2003
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates a file or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	8/20/2003
CID:	216
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	8/20/2003
Spill Record Last Update:	5/21/2007
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	GEORGE FALIDAS
Spiller Phone:	(718) 392-0514
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	63466
DEC Memo:	On 7/14/05, J Peck called RIR Com. Cynthia Roby doesn't work there now. Left mesasage to return call concerning spill. Could not determine owner of property from Property Shark or Acris. Called George Falidas on 7/14/05, left message to call back. On 1/19/05, reattempted to determine owner of property. No success. 3/30/07 - Austin - Trasferred to Ketani for further review - end5/21/07 - Raphael Ketani. I reactiviated the case today. There was very little in the case file. Some printed pages for spill #0305345 (which doesn't pertain to the case, except the memo from Mr. Sigona to Mr. Hassan), an 11/7/05 letter from Joseph Peck of DEC to George Faildas regarding the spill, printouts from Google Earth and Property Shark, and a printout of the spill report for this case.I did a search of

FALIDAS ASSCOCIATES (Continued) **1007264881**

ACRIS, the NYC Property Tax database, and Property Shark and determined that 25-15 Queens Plaza North is just one part of the range of properties (25-01 to 25-27 Queens Plaza North) owned by Falidas Associates. It is also known by Bridge Plaza North. The block and lot are: 00415 and 0004. I called up George Falidas (718) 392-0514 of Falidas Associates and was connected to his brother, John Falidas.I made a field visit and met John Falidas. He showed me the basement of one of the properties owned by Falidas Associates and which is near to where the tank failed 2 buildings away. We entered a work room rented by a garment making company. The floor and walls and bathroom were clean. There were no signs of oil and no oil odors. Mr. Falidas said that he had paid lots of money to get the oil cleaned up years ago and the responsible party never paid anything to him. Mr. Falidas had a package of documents from the EPA and the DEC and showed them to me. These were the RCRA Subtitle C Site Identification Form, letters from South Mall Analytical Labs to PTC, and a DEC Spill Report. He gave me copies of these documents. I was particularly interested in the old DEC spill report form as this document wasn't in the case file.Next, I visited the 2 story building between Mr. Falidas' building and the site of origin of the spill. I met Sandro Cestaro of Atlantic Precious Metal Casting, Inc. (718) 937-7100. He showed me his basement. There were some signs of a thin film of mud in one corner of the basement, but no signs or odors of oil, even though this was the building where the oil first entered. Lastly, I went to the site of the oil spill. The auto parts service place had burned completely, according to the old spill report case notes. This site was 41-22 to 41-30 27 Street. The site was sold to developers who later built an apartment building that was finished in early 2007. This building is listed as 41-28 27 Street. I met the super., Leonardo Colon. He took me to the lowest point in the building. This was a parking garage. There were no signs of oil nor any odors. He said he was new here and didn't know much about the building. The building management company is Golden Management and the contact person is Brandon Wechsler (718) 230-2600, ext 111.I took 3 pictures of the apartment building and the neighboring properties. I remember seeing the dig out for the foundation for the building when I passed by the site many months back. They went down below the bottom of the foundation for the neighboring building which contains Atlantic Precious. This is a depth of about 15 feet or so. Based upon my site visits and the fact that the old auto parts area has been dug out, and the lack of evidence of a spill, I am closing the spill case.

Remarks: SPILL AT A COMMERCIAL BLD CALLER IS A TENANT AND REQ A CALL FROM DEC SPILL HAS NOT BEEN CLEANED UP BEEN SMELLING THIS FOR ABOUT 3 WEEKS

Material:

Site ID:	66252
Operable Unit ID:	871982
Operable Unit:	01
Material ID:	502602
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported

FALIDAS ASSCOCIATES (Continued) **1007264881**

Oxygenate: False

Tank Test:

NY MANIFEST:

EPA ID:	NYR000123547
Country:	USA
Mailing Name:	FALIDAS ASSOCIATES
Mailing Contact:	N/S
Mailing Address:	25-15 QUEENS BLVD
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-392-0514

Document ID:	NJA5082592
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Trans2 State ID:	50059
Generator Ship Date:	12/03/2004
Trans1 Recv Date:	12/03/2004
Trans2 Recv Date:	02/07/2005
TSD Site Recv Date:	02/07/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000123547
Trans1 EPA ID:	NYR000080549
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	00330
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2004

NJ MANIFEST:

Manifest Code:	NJA5082592
EPA ID:	NYR000123547
Date Shipped:	12/03/2004
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYR000080549
Transporter 2 EPA ID:	NJD986607380
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

FALIDAS ASSCOCIATES (Continued) **1007264881**

Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/03/2004
Date Trans2 Transported Waste:	02/07/2005
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/07/2005
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	Not reported
Transporter-1 EPA Facility Name:	Not reported
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	03150595
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

193
WNW
1/4-1/2
0.306 mi.
1618 ft.

21-16 44TH RD
21-16 44TH RD
LONG ISLAND CITY, NY

NY Spills **S103560285**
NY ENG CONTROLS **N/A**
NY INST CONTROL
NY VCP

Relative:
Higher

Actual:
18 ft.

SPILLS:

Facility ID:	8808385
DER Facility ID:	88420
Facility Type:	ER
Site ID:	99512
DEC Region:	2
Spill Date:	1/20/1989
Spill Number/Closed Date:	8808385 / 11/14/1994

21-16 44TH RD (Continued) **S103560285**

Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1/20/1989
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	11/14/1994
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1/23/1989
Spill Record Last Update:	3/30/2004
Spiller Name:	MR GOULD
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	PETROLEUM TANK CLEANING REWELDING COUPLINGS & RELINING TANK & PIPING REPLACED.

Material:

Site ID:	99512
Operable Unit ID:	924799
Operable Unit:	01
Material ID:	453147
Material Code:	0003A
Material Name:	#6 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	99512
Spill Tank Test:	1535107
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

21-16 44TH RD (Continued) **S103560285**

ENG CONTROLS:

Site Code:	58239
HW Code:	V00366
Control Code:	13
Control Type:	ENG
Date Record Added:	12/12/2008
Date Rec Updated:	08/16/2011
Updated By:	SRHEIGEL
Site Description:	Location: The site is located at 21-16 44th Road, LIC, NY 11101 (Tax Block 438, Lot 26). The site occupies the northweastern portion of the block bounded by 44th Rd. to the north, 44th Dr. to the south, 21st St. to the west and 23rd St. to the east. The site is in urban area. The property is approximately 1/2 mile from the East River. Site Features: The Information Technology HS building and its court yard occupy the site. Current Zonning/Use(s): The site is used as a High School. The surrounding area is zoned M3-1 Heavy Manufacturing. The adjacent parcels are currently used for a combination of commercial, manufacturing, and residential.Historical Use(s): The site was formerly occupied by a four story, 30,000 square foot warehouse and its court yard. It was historically operated as a cloth manufacturing factory, a metal plating factory, and a 5,000 square foot parking lot. The plating factory had one dry well on the first floor, one in the courtyard, and two in the basement. During the plating processes the waste from the metal cleaning and plating baths were disposed of through these dry wells. Following implementation of remedial actions, the building was renovated and is currently occupied by the Information Technology High School. The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The remedial systems are operating under a NYSDEC-approved Site Management Plan which has provisions for frequent system monitoring, maintenance, and periodic reporting.Site Geology and Hydrogeology: The site is underlain by 2 to 5 feet of urban fill materials. Below this there are interbeded layers of sand, clay and marl of Cretaceous and Pleistocene age. The bed rock is 23 to 29 feet below grade. The groundwater is 12 to 15 feet below grade and flows generally south.
Env Problem:	Nature and Extent of Contamination: Prior to Remediation:a) contaminants: The Phase I and Phase II Investigation identified the contaminants of concern as chlorinated volatile organic compounds (CVOCs), particularly PCE and its breakdown products in soil, groundwater, and soil vapor; metals in the dry well sediments; and lead-contaminated soil in the parking lot. The site contamination was related to the previous manufacturing industries which operated in the former warehouse building. b) areal/depth extent: The plating factory occupied the first floor and the basement of the building and it had drum storage areas inside and in the court yard adjacent to the building. The sources of contamination under the building in soil and groundwater were determined to be four dry wells and a drum storage area in the court yard.c) concentrations: PCE in soil ranged from 0 to 300 ppm; in groundwater 5 ppb to 36,000 ppb; and 5 ppbv to 80,0000 ppbv in soil gas. Post-Remediation: A Subslab Depressurization System (SSDS), and a groundwater pump and treatment systems are currently operating under a NYSDEC-approved Site Management Plan (SMP). The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The SMP has provisions for frequent system monitoring and maintenance, and for periodic reporting to NYSDEC. There are Deed Restrictions

21-16 44TH RD (Continued) **S103560285**

recorded against the site.

Health Problem: The Site was a former warehouse and has been redeveloped as an Information and Technology High School. Contaminated soils beneath the building have been removed and disposed of off-site. Human exposures to residual contaminated soil is unlikely as the site is covered by the on-site building and pavement. Ingestion of groundwater as a potable drinking water source is not expected since the area is served by public water supply. Potential exposures via soil vapor intrusion into the school have been mitigated by the installation and operation of sub-slab depressurization system, a vapor barrier, a eight-inch thick competent concrete slab, and the building's positive-pressure heating and ventilation system. Monthly sampling of soil vapor and quarterly sampling of groundwater will ensure that remedial systems are working properly.

Site Code: 58239
HW Code: V00366
Control Code: 15
Control Type: ENG
Date Record Added: 12/12/2008
Date Rec Updated: 08/16/2011
Updated By: SRHEIGEL
Site Description: Location: The site is located at 21-16 44th Road, LIC, NY 11101 (Tax Block 438, Lot 26). The site occupies the northweastern portion of the block bounded by 44th Rd. to the north, 44th Dr. to the south, 21st St. to the west and 23rd St. to the east. The site is in urban area. The property is approximately 1/2 mile from the East River. Site Features: The Information Technology HS building and its court yard occupy the site. Current Zonning/Use(s): The site is used as a High School. The surrounding area is zoned M3-1 Heavy Manufacturing. The adjacent parcels are currently used for a combination of commercial, manufacturing, and residential.Historical Use(s): The site was formerly occupied by a four story, 30,000 square foot warehouse and its court yard. It was historically operated as a cloth manufacturing factory, a metal plating factory, and a 5,000 square foot parking lot. The plating factory had one dry well on the first floor, one in the courtyard, and two in the basement. During the plating processes the waste from the metal cleaning and plating baths were disposed of through these dry wells. Following implementation of remedial actions, the building was renovated and is currently occupied by the Information Technology High School. The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The remedial systems are operating under a NYSDEC-approved Site Management Plan which has provisions for frequent system monitoring, maintenance, and periodic reporting.Site Geology and Hydrogeology: The site is underlain by 2 to 5 feet of urban fill materials. Below this there are interbeded layers of sand, clay and marl of Cretaceous and Pleistocene age. The bed rock is 23 to 29 feet below grade. The groundwater is 12 to 15 feet below grade and flows generally south.

Env Problem: Nature and Extent of Contamination: Prior to Remediation:a) contaminants: The Phase I and Phase II Investigation identified the contaminants of concern as chlorinated volatile organic compounds (CVOCs), particularly PCE and its breakdown products in soil, groundwater, and soil vapor; metals in the dry well sediments; and lead-contaminated soil in the parking lot. The site contamination was related to the previous manufacturing industries which operated in

21-16 44TH RD (Continued) **S103560285**

the former warehouse building. b) areal/depth extent: The plating factory occupied the first floor and the basement of the building and it had drum storage areas inside and in the court yard adjacent to the building. The sources of contamination under the building in soil and groundwater were determined to be four dry wells and a drum storage area in the court yard.c) concentrations: PCE in soil ranged from 0 to 300 ppm; in groundwater 5 ppb to 36,000 ppb; and 5 ppbv to 80,0000 ppbv in soil gas. Post-Remediation: A Subslab Depressurization System (SSDS), and a groundwater pump and treatment systems are currently operating under a NYSDEC-approved Site Management Plan (SMP). The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The SMP has provisions for frequent system monitoring and maintenance, and for periodic reporting to NYSDEC. There are Deed Restrictions recorded against the site.

Health Problem: The Site was a former warehouse and has been redeveloped as an Information and Technology High School. Contaminated soils beneath the building have been removed and disposed of off-site. Human exposures to residual contaminated soil is unlikely as the site is covered by the on-site building and pavement. Ingestion of groundwater as a potable drinking water source is not expected since the area is served by public water supply. Potential exposures via soil vapor intrusion into the school have been mitigated by the installation and operation of sub-slab depressurization system, a vapor barrier, a eight-inch thick competent concrete slab, and the building's positive-pressure heating and ventilation system. Monthly sampling of soil vapor and quarterly sampling of groundwater will ensure that remedial systems are working properly.

Site Code: 58239
HW Code: V00366
Control Code: 18
Control Type: ENG
Date Record Added: 12/12/2008
Date Rec Updated: 08/16/2011
Updated By: SRHEIGEL
Site Description: Location: The site is located at 21-16 44th Road, LIC, NY 11101 (Tax Block 438, Lot 26). The site occupies the northweastern portion of the block bounded by 44th Rd. to the north, 44th Dr. to the south, 21st St. to the west and 23rd St. to the east. The site is in urban area. The property is approximately 1/2 mile from the East River. Site Features: The Information Technology HS building and its court yard occupy the site. Current Zonning/Use(s): The site is used as a High School. The surrounding area is zoned M3-1 Heavy Manufacturing. The adjacent parcels are currently used for a combination of commercial, manufacturing, and residential.Historical Use(s): The site was formerly occupied by a four story, 30,000 square foot warehouse and its court yard. It was historically operated as a cloth manufacturing factory, a metal plating factory, and a 5,000 square foot parking lot. The plating factory had one dry well on the first floor, one in the courtyard, and two in the basement. During the plating processes the waste from the metal cleaning and plating baths were disposed of through these dry wells. Following implementation of remedial actions, the building was renovated and is currently occupied by the Information Technology High School. The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The remedial systems are operating under a

21-16 44TH RD (Continued) **S103560285**

NYSDEC-approved Site Management Plan which has provisions for frequent system monitoring, maintenance, and periodic reporting.Site Geology and Hydrogeology: The site is underlain by 2 to 5 feet of urban fill materials. Below this there are interbeded layers of sand, clay and marl of Cretaceous and Pleistocene age. The bed rock is 23 to 29 feet below grade. The groundwater is 12 to 15 feet below grade and flows generally south.

Env Problem: Nature and Extent of Contamination: Prior to Remediation:a) contaminants: The Phase I and Phase II Investigation identified the contaminants of concern as chlorinated volatile organic compounds (CVOCs), particularly PCE and its breakdown products in soil, groundwater, and soil vapor; metals in the dry well sediments; and lead-contaminated soil in the parking lot. The site contamination was related to the previous manufacturing industries which operated in the former warehouse building. b) areal/depth extent: The plating factory occupied the first floor and the basement of the building and it had drum storage areas inside and in the court yard adjacent to the building. The sources of contamination under the building in soil and groundwater were determined to be four dry wells and a drum storage area in the court yard.c) concentrations: PCE in soil ranged from 0 to 300 ppm; in groundwater 5 ppb to 36,000 ppb; and 5 ppbv to 80,0000 ppbv in soil gas. Post-Remediation: A Subslab Depressurization System (SSDS), and a groundwater pump and treatment systems are currently operating under a NYSDEC-approved Site Management Plan (SMP). The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The SMP has provisions for frequent system monitoring and maintenance, and for periodic reporting to NYSDEC. There are Deed Restrictions recorded against the site.

Health Problem: The Site was a former warehouse and has been redeveloped as an Information and Technology High School. Contaminated soils beneath the building have been removed and disposed of off-site. Human exposures to residual contaminated soil is unlikely as the site is covered by the on-site building and pavement. Ingestion of groundwater as a potable drinking water source is not expected since the area is served by public water supply. Potential exposures via soil vapor intrusion into the school have been mitigated by the installation and operation of sub-slab depressurization system, a vapor barrier, a eight-inch thick competent concrete slab, and the building's positive-pressure heating and ventilation system. Monthly sampling of soil vapor and quarterly sampling of groundwater will ensure that remedial systems are working properly.

Site Code: 58239
HW Code: V00366
Control Code: 12
Control Type: ENG
Date Record Added: 12/12/2008
Date Rec Updated: 08/16/2011
Updated By: SRHEIGEL
Site Description: Location: The site is located at 21-16 44th Road, LIC, NY 11101 (Tax Block 438, Lot 26). The site occupies the northweastern portion of the block bounded by 44th Rd. to the north, 44th Dr. to the south, 21st St. to the west and 23rd St. to the east. The site is in urban area. The property is approximately 1/2 mile from the East River. Site Features: The Information Technology HS building and its court yard occupy the site. Current Zonning/Use(s): The site is used as a

21-16 44TH RD (Continued) **S103560285**

High School. The surrounding area is zoned M3-1 Heavy Manufacturing. The adjacent parcels are currently used for a combination of commercial, manufacturing, and residential.Historical Use(s): The site was formerly occupied by a four story, 30,000 square foot warehouse and its court yard. It was historically operated as a cloth manufacturing factory, a metal plating factory, and a 5,000 square foot parking lot. The plating factory had one dry well on the first floor, one in the courtyard, and two in the basement. During the plating processes the waste from the metal cleaning and plating baths were disposed of through these dry wells. Following implementation of remedial actions, the building was renovated and is currently occupied by the Information Technology High School. The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The remedial systems are operating under a NYSDEC-approved Site Management Plan which has provisions for frequent system monitoring, maintenance, and periodic reporting.Site Geology and Hydrogeology: The site is underlain by 2 to 5 feet of urban fill materials. Below this there are interbeded layers of sand, clay and marl of Cretaceous and Pleistocene age. The bed rock is 23 to 29 feet below grade. The groundwater is 12 to 15 feet below grade and flows generally south.

Env Problem: Nature and Extent of Contamination: Prior to Remediation:a) contaminants: The Phase I and Phase II Investigation identified the contaminants of concern as chlorinated volatile organic compounds (CVOCs), particularly PCE and its breakdown products in soil, groundwater, and soil vapor; metals in the dry well sediments; and lead-contaminated soil in the parking lot. The site contamination was related to the previous manufacturing industries which operated in the former warehouse building. b) areal/depth extent: The plating factory occupied the first floor and the basement of the building and it had drum storage areas inside and in the court yard adjacent to the building. The sources of contamination under the building in soil and groundwater were determined to be four dry wells and a drum storage area in the court yard.c) concentrations: PCE in soil ranged from 0 to 300 ppm; in groundwater 5 ppb to 36,000 ppb; and 5 ppbv to 80,0000 ppbv in soil gas. Post-Remediation: A Subslab Depressurization System (SSDS), and a groundwater pump and treatment systems are currently operating under a NYSDEC-approved Site Management Plan (SMP). The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The SMP has provisions for frequent system monitoring and maintenance, and for periodic reporting to NYSDEC. There are Deed Restrictions recorded against the site.

Health Problem: The Site was a former warehouse and has been redeveloped as an Information and Technology High School. Contaminated soils beneath the building have been removed and disposed of off-site. Human exposures to residual contaminated soil is unlikely as the site is covered by the on-site building and pavement. Ingestion of groundwater as a potable drinking water source is not expected since the area is served by public water supply. Potential exposures via soil vapor intrusion into the school have been mitigated by the installation and operation of sub-slab depressurization system, a vapor barrier, a eight-inch thick competent concrete slab, and the building’s positive-pressure heating and ventilation system. Monthly sampling of soil vapor and quarterly sampling of groundwater will ensure that remedial systems are working properly.

21-16 44TH RD (Continued) **S103560285**

INST CONTROL:
Site Code: 58239
Control Name: Soil Management Plan
HW Code: V00366
Control Code: 14
Control Type: INST
Dt record added: 12/12/2008
Dt rec updated: 08/16/2011
Updated By: SRHEIGEL
Site Code: 58239
Site Description: Location: The site is located at 21-16 44th Road, LIC, NY 11101 (Tax Block 438, Lot 26). The site occupies the northweastern portion of the block bounded by 44th Rd. to the north, 44th Dr. to the south, 21st St. to the west and 23rd St. to the east. The site is in urban area. The property is approximately 1/2 mile from the East River. Site Features: The Information Technology HS building and its court yard occupy the site. Current Zonning/Use(s): The site is used as a High School. The surrounding area is zoned M3-1 Heavy Manufacturing. The adjacent parcels are currently used for a combination of commercial, manufacturing, and residential.Historical Use(s): The site was formerly occupied by a four story, 30,000 square foot warehouse and its court yard. It was historically operated as a cloth manufacturing factory, a metal plating factory, and a 5,000 square foot parking lot. The plating factory had one dry well on the first floor, one in the courtyard, and two in the basement. During the plating processes the waste from the metal cleaning and plating baths were disposed of through these dry wells. Following implementation of remedial actions, the building was renovated and is currently occupied by the Information Technology High School. The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The remedial systems are operating under a NYSDEC-approved Site Management Plan which has provisions for frequent system monitoring, maintenance, and periodic reporting.Site Geology and Hydrogeology: The site is underlain by 2 to 5 feet of urban fill materials. Below this there are interbeded layers of sand, clay and marl of Cretaceous and Pleistocene age. The bed rock is 23 to 29 feet below grade. The groundwater is 12 to 15 feet below grade and flows generally south.
Env Problem: Nature and Extent of Contamination: Prior to Remediation:a) contaminants: The Phase I and Phase II Investigation identified the contaminants of concern as chlorinated volatile organic compounds (CVOCs), particularly PCE and its breakdown products in soil, groundwater, and soil vapor; metals in the dry well sediments; and lead-contaminated soil in the parking lot. The site contamination was related to the previous manufacturing industries which operated in the former warehouse building. b) areal/depth extent: The plating factory occupied the first floor and the basement of the building and it had drum storage areas inside and in the court yard adjacent to the building. The sources of contamination under the building in soil and groundwater were determined to be four dry wells and a drum storage area in the court yard.c) concentrations: PCE in soil ranged from 0 to 300 ppm; in groundwater 5 ppb to 36,000 ppb; and 5 ppbv to 80,0000 ppbv in soil gas. Post-Remediation: A Subslab Depressurization System (SSDS), and a groundwater pump and treatment systems are currently operating under a NYSDEC-approved Site Management Plan (SMP). The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The

21-16 44TH RD (Continued) **S103560285**

SMP has provisions for frequent system monitoring and maintenance, and for periodic reporting to NYSDEC. There are Deed Restrictions recorded against the site.

Health Problem: The Site was a former warehouse and has been redeveloped as an Information and Technology High School. Contaminated soils beneath the building have been removed and disposed of off-site. Human exposures to residual contaminated soil is unlikely as the site is covered by the on-site building and pavement. Ingestion of groundwater as a potable drinking water source is not expected since the area is served by public water supply. Potential exposures via soil vapor intrusion into the school have been mitigated by the installation and operation of sub-slab depressurization system, a vapor barrier, a eight-inch thick competent concrete slab, and the building's positive-pressure heating and ventilation system. Monthly sampling of soil vapor and quarterly sampling of groundwater will ensure that remedial systems are working properly.

Site Code: 58239
Control Name: Deed Restriction
HW Code: V00366
Control Code: A
Control Type: INST
Dt record added: 12/12/2008
Dt rec updated: 08/16/2011
Updated By: SRHEIGEL
Site Code: 58239

Site Description: Location: The site is located at 21-16 44th Road, LIC, NY 11101 (Tax Block 438, Lot 26). The site occupies the northweastern portion of the block bounded by 44th Rd. to the north, 44th Dr. to the south, 21st St. to the west and 23rd St. to the east. The site is in urban area. The property is approximately 1/2 mile from the East River. Site Features: The Information Technology HS building and its court yard occupy the site. Current Zonning/Use(s): The site is used as a High School. The surrounding area is zoned M3-1 Heavy Manufacturing. The adjacent parcels are currently used for a combination of commercial, manufacturing, and residential.Historical Use(s): The site was formerly occupied by a four story, 30,000 square foot warehouse and its court yard. It was historically operated as a cloth manufacturing factory, a metal plating factory, and a 5,000 square foot parking lot. The plating factory had one dry well on the first floor, one in the courtyard, and two in the basement. During the plating processes the waste from the metal cleaning and plating baths were disposed of through these dry wells. Following implementation of remedial actions, the building was renovated and is currently occupied by the Information Technology High School. The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The remedial systems are operating under a NYSDEC-approved Site Management Plan which has provisions for frequent system monitoring, maintenance, and periodic reporting.Site Geology and Hydrogeology: The site is underlain by 2 to 5 feet of urban fill materials. Below this there are interbeded layers of sand, clay and marl of Cretaceous and Pleistocene age. The bed rock is 23 to 29 feet below grade. The groundwater is 12 to 15 feet below grade and flows generally south.

Env Problem: Nature and Extent of Contamination: Prior to Remediation:a) contaminants: The Phase I and Phase II Investigation identified the contaminants of concern as chlorinated volatile organic compounds

21-16 44TH RD (Continued) **S103560285**

(CVOCs), particularly PCE and its breakdown products in soil, groundwater, and soil vapor; metals in the dry well sediments; and lead-contaminated soil in the parking lot. The site contamination was related to the previous manufacturing industries which operated in the former warehouse building. b) areal/depth extent: The plating factory occupied the first floor and the basement of the building and it had drum storage areas inside and in the court yard adjacent to the building. The sources of contamination under the building in soil and groundwater were determined to be four dry wells and a drum storage area in the court yard.c) concentrations: PCE in soil ranged from 0 to 300 ppm; in groundwater 5 ppb to 36,000 ppb; and 5 ppbv to 80,0000 ppbv in soil gas. Post-Remediation: A Subslab Depressurization System (SSDS), and a groundwater pump and treatment systems are currently operating under a NYSDEC-approved Site Management Plan (SMP). The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The SMP has provisions for frequent system monitoring and maintenance, and for periodic reporting to NYSDEC. There are Deed Restrictions recorded against the site.

Health Problem: The Site was a former warehouse and has been redeveloped as an Information and Technology High School. Contaminated soils beneath the building have been removed and disposed of off-site. Human exposures to residual contaminated soil is unlikely as the site is covered by the on-site building and pavement. Ingestion of groundwater as a potable drinking water source is not expected since the area is served by public water supply. Potential exposures via soil vapor intrusion into the school have been mitigated by the installation and operation of sub-slab depressurization system, a vapor barrier, a eight-inch thick competent concrete slab, and the building's positive-pressure heating and ventilation system. Monthly sampling of soil vapor and quarterly sampling of groundwater will ensure that remedial systems are working properly.

Site Code: 58239
Control Name: Ground Water Use Restriction
HW Code: V00366
Control Code: 08
Control Type: INST
Dt record added: 12/12/2008
Dt rec updated: 08/16/2011
Updated By: SRHEIGEL
Site Code: 58239
Site Description: Location: The site is located at 21-16 44th Road, LIC, NY 11101 (Tax Block 438, Lot 26). The site occupies the northweastern portion of the block bounded by 44th Rd. to the north, 44th Dr. to the south, 21st St. to the west and 23rd St. to the east. The site is in urban area. The property is approximately 1/2 mile from the East River. Site Features: The Information Technology HS building and its court yard occupy the site. Current Zonning/Use(s): The site is used as a High School. The surrounding area is zoned M3-1 Heavy Manufacturing. The adjacent parcels are currently used for a combination of commercial, manufacturing, and residential.Historical Use(s): The site was formerly occupied by a four story, 30,000 square foot warehouse and its court yard. It was historically operated as a cloth manufacturing factory, a metal plating factory, and a 5,000 square foot parking lot. The plating factory had one dry well on the first floor, one in the courtyard, and two in the basement. During the

21-16 44TH RD (Continued) **S103560285**

plating processes the waste from the metal cleaning and plating baths were disposed of through these dry wells. Following implementation of remedial actions, the building was renovated and is currently occupied by the Information Technology High School. The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The remedial systems are operating under a NYSDEC-approved Site Management Plan which has provisions for frequent system monitoring, maintenance, and periodic reporting.Site Geology and Hydrogeology: The site is underlain by 2 to 5 feet of urban fill materials. Below this there are interbeded layers of sand, clay and marl of Cretaceous and Pleistocene age. The bed rock is 23 to 29 feet below grade. The groundwater is 12 to 15 feet below grade and flows generally south.

Env Problem: Nature and Extent of Contamination: Prior to Remediation:a) contaminants: The Phase I and Phase II Investigation identified the contaminants of concern as chlorinated volatile organic compounds (CVOCs), particularly PCE and its breakdown products in soil, groundwater, and soil vapor; metals in the dry well sediments; and lead-contaminated soil in the parking lot. The site contamination was related to the previous manufacturing industries which operated in the former warehouse building. b) areal/depth extent: The plating factory occupied the first floor and the basement of the building and it had drum storage areas inside and in the court yard adjacent to the building. The sources of contamination under the building in soil and groundwater were determined to be four dry wells and a drum storage area in the court yard.c) concentrations: PCE in soil ranged from 0 to 300 ppm; in groundwater 5 ppb to 36,000 ppb; and 5 ppbv to 80,0000 ppbv in soil gas. Post-Remediation: A Subslab Depressurization System (SSDS), and a groundwater pump and treatment systems are currently operating under a NYSDEC-approved Site Management Plan (SMP). The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The SMP has provisions for frequent system monitoring and maintenance, and for periodic reporting to NYSDEC. There are Deed Restrictions recorded against the site.

Health Problem: The Site was a former warehouse and has been redeveloped as an Information and Technology High School. Contaminated soils beneath the building have been removed and disposed of off-site. Human exposures to residual contaminated soil is unlikely as the site is covered by the on-site building and pavement. Ingestion of groundwater as a potable drinking water source is not expected since the area is served by public water supply. Potential exposures via soil vapor intrusion into the school have been mitigated by the installation and operation of sub-slab depressurization system, a vapor barrier, a eight-inch thick competent concrete slab, and the building’s positive-pressure heating and ventilation system. Monthly sampling of soil vapor and quarterly sampling of groundwater will ensure that remedial systems are working properly.

Site Code: 58239
Control Name: Landuse Restriction
HW Code: V00366
Control Code: 25
Control Type: INST
Dt record added: 12/12/2008
Dt rec updated: 08/16/2011
Updated By: SRHEIGEL

21-16 44TH RD (Continued) **S103560285**

Site Code: 58239

Site Description: Location: The site is located at 21-16 44th Road, LIC, NY 11101 (Tax Block 438, Lot 26). The site occupies the northweastern portion of the block bounded by 44th Rd. to the north, 44th Dr. to the south, 21st St. to the west and 23rd St. to the east. The site is in urban area. The property is approximately 1/2 mile from the East River. Site Features: The Information Technology HS building and its court yard occupy the site. Current Zonning/Use(s): The site is used as a High School. The surrounding area is zoned M3-1 Heavy Manufacturing. The adjacent parcels are currently used for a combination of commercial, manufacturing, and residential.Historical Use(s): The site was formerly occupied by a four story, 30,000 square foot warehouse and its court yard. It was historically operated as a cloth manufacturing factory, a metal plating factory, and a 5,000 square foot parking lot. The plating factory had one dry well on the first floor, one in the courtyard, and two in the basement. During the plating processes the waste from the metal cleaning and plating baths were disposed of through these dry wells. Following implementation of remedial actions, the building was renovated and is currently occupied by the Information Technology High School. The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The remedial systems are operating under a NYSDEC-approved Site Management Plan which has provisions for frequent system monitoring, maintenance, and periodic reporting.Site Geology and Hydrogeology: The site is underlain by 2 to 5 feet of urban fill materials. Below this there are interbeded layers of sand, clay and marl of Cretaceous and Pleistocene age. The bed rock is 23 to 29 feet below grade. The groundwater is 12 to 15 feet below grade and flows generally south.

Env Problem: Nature and Extent of Contamination: Prior to Remediation:a) contaminants: The Phase I and Phase II Investigation identified the contaminants of concern as chlorinated volatile organic compounds (CVOCs), particularly PCE and its breakdown products in soil, groundwater, and soil vapor; metals in the dry well sediments; and lead-contaminated soil in the parking lot. The site contamination was related to the previous manufacturing industries which operated in the former warehouse building. b) areal/depth extent: The plating factory occupied the first floor and the basement of the building and it had drum storage areas inside and in the court yard adjacent to the building. The sources of contamination under the building in soil and groundwater were determined to be four dry wells and a drum storage area in the court yard.c) concentrations: PCE in soil ranged from 0 to 300 ppm; in groundwater 5 ppb to 36,000 ppb; and 5 ppbv to 80,0000 ppbv in soil gas. Post-Remediation: A Subslab Depressurization System (SSDS), and a groundwater pump and treatment systems are currently operating under a NYSDEC-approved Site Management Plan (SMP). The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The SMP has provisions for frequent system monitoring and maintenance, and for periodic reporting to NYSDEC. There are Deed Restrictions recorded against the site.

Health Problem: The Site was a former warehouse and has been redeveloped as an Information and Technology High School. Contaminated soils beneath the building have been removed and disposed of off-site. Human exposures to residual contaminated soil is unlikely as the site is covered by the on-site building and pavement. Ingestion of groundwater as a potable drinking water source is not expected since

21-16 44TH RD (Continued) **S103560285**

the area is served by public water supply. Potential exposures via soil vapor intrusion into the school have been mitigated by the installation and operation of sub-slab depressurization system, a vapor barrier, a eight-inch thick competent concrete slab, and the building's positive-pressure heating and ventilation system. Monthly sampling of soil vapor and quarterly sampling of groundwater will ensure that remedial systems are working properly.

Site Code: 58239
Control Name: Building Use Restriction
HW Code: V00366
Control Code: 26
Control Type: INST
Dt record added: 12/12/2008
Dt rec updated: 08/16/2011
Updated By: SRHEIGEL
Site Code: 58239
Site Description: Location: The site is located at 21-16 44th Road, LIC, NY 11101 (Tax Block 438, Lot 26). The site occupies the northweastern portion of the block bounded by 44th Rd. to the north, 44th Dr. to the south, 21st St. to the west and 23rd St. to the east. The site is in urban area. The property is approximately 1/2 mile from the East River. Site Features: The Information Technology HS building and its court yard occupy the site. Current Zonning/Use(s): The site is used as a High School. The surrounding area is zoned M3-1 Heavy Manufacturing. The adjacent parcels are currently used for a combination of commercial, manufacturing, and residential.Historical Use(s): The site was formerly occupied by a four story, 30,000 square foot warehouse and its court yard. It was historically operated as a cloth manufacturing factory, a metal plating factory, and a 5,000 square foot parking lot. The plating factory had one dry well on the first floor, one in the courtyard, and two in the basement. During the plating processes the waste from the metal cleaning and plating baths were disposed of through these dry wells. Following implementation of remedial actions, the building was renovated and is currently occupied by the Information Technology High School. The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The remedial systems are operating under a NYSDEC-approved Site Management Plan which has provisions for frequent system monitoring, maintenance, and periodic reporting.Site Geology and Hydrogeology: The site is underlain by 2 to 5 feet of urban fill materials. Below this there are interbeded layers of sand, clay and marl of Cretaceous and Pleistocene age. The bed rock is 23 to 29 feet below grade. The groundwater is 12 to 15 feet below grade and flows generally south.
Env Problem: Nature and Extent of Contamination: Prior to Remediation:a) contaminants: The Phase I and Phase II Investigation identified the contaminants of concern as chlorinated volatile organic compounds (CVOCs), particularly PCE and its breakdown products in soil, groundwater, and soil vapor; metals in the dry well sediments; and lead-contaminated soil in the parking lot. The site contamination was related to the previous manufacturing industries which operated in the former warehouse building. b) areal/depth extent: The plating factory occupied the first floor and the basement of the building and it had drum storage areas inside and in the court yard adjacent to the building. The sources of contamination under the building in soil and groundwater were determined to be four dry wells and a drum

21-16 44TH RD (Continued) **S103560285**

storage area in the court yard.c) concentrations: PCE in soil ranged from 0 to 300 ppm; in groundwater 5 ppb to 36,000 ppb; and 5 ppbv to 80,0000 ppbv in soil gas. Post-Remediation: A Subslab Depressurization System (SSDS), and a groundwater pump and treatment systems are currently operating under a NYSDEC-approved Site Management Plan (SMP). The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The SMP has provisions for frequent system monitoring and maintenance, and for periodic reporting to NYSDEC. There are Deed Restrictions recorded against the site.

Health Problem: The Site was a former warehouse and has been redeveloped as an Information and Technology High School. Contaminated soils beneath the building have been removed and disposed of off-site. Human exposures to residual contaminated soil is unlikely as the site is covered by the on-site building and pavement. Ingestion of groundwater as a potable drinking water source is not expected since the area is served by public water supply. Potential exposures via soil vapor intrusion into the school have been mitigated by the installation and operation of sub-slab depressurization system, a vapor barrier, a eight-inch thick competent concrete slab, and the building's positive-pressure heating and ventilation system. Monthly sampling of soil vapor and quarterly sampling of groundwater will ensure that remedial systems are working properly.

VCP:

Program Type:	VCP
Site Code:	58239
HW Code:	V00366
Site Class:	C
SWIS:	4101
Region:	2
Town:	New York City
Acres:	.800
Date Record Added:	11/30/2000
Date Record Updated:	04/16/2013
Updated By:	JHOCONNE
Site Description:	Location: The site is located at 21-16 44th Road, LIC, NY 11101 (Tax Block 438, Lot 26). The site occupies the northweastern portion of the block bounded by 44th Rd. to the north, 44th Dr. to the south, 21st St. to the west and 23rd St. to the east. The site is in urban area. The property is approximately 1/2 mile from the East River. Site Features: The Information Technology HS building and its court yard occupy the site. Current Zonning/Use(s): The site is used as a High School. The surrounding area is zoned M3-1 Heavy Manufacturing. The adjacent parcels are currently used for a combination of commercial, manufacturing, and residential.Historical Use(s): The site was formerly occupied by a four story, 30,000 square foot warehouse and its court yard. It was historically operated as a cloth manufacturing factory, a metal plating factory, and a 5,000 square foot parking lot. The plating factory had one dry well on the first floor, one in the courtyard, and two in the basement. During the plating processes the waste from the metal cleaning and plating baths were disposed of through these dry wells. Following implementation of remedial actions, the building was renovated and is currently occupied by the Information Technology High School. The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The remedial systems are operating under a

21-16 44TH RD (Continued) **S103560285**

NYSDEC-approved Site Management Plan which has provisions for frequent system monitoring, maintenance, and periodic reporting.Site Geology and Hydrogeology: The site is underlain by 2 to 5 feet of urban fill materials. Below this there are interbeded layers of sand, clay and marl of Cretaceous and Pleistocene age. The bed rock is 23 to 29 feet below grade. The groundwater is 12 to 15 feet below grade and flows generally south.

Env Problem: Nature and Extent of Contamination: Prior to Remediation:a) contaminants: The Phase I and Phase II Investigation identified the contaminants of concern as chlorinated volatile organic compounds (CVOCs), particularly PCE and its breakdown products in soil, groundwater, and soil vapor; metals in the dry well sediments; and lead-contaminated soil in the parking lot. The site contamination was related to the previous manufacturing industries which operated in the former warehouse building. b) areal/depth extent: The plating factory occupied the first floor and the basement of the building and it had drum storage areas inside and in the court yard adjacent to the building. The sources of contamination under the building in soil and groundwater were determined to be four dry wells and a drum storage area in the court yard.c) concentrations: PCE in soil ranged from 0 to 300 ppm; in groundwater 5 ppb to 36,000 ppb; and 5 ppbv to 80,0000 ppbv in soil gas. Post-Remediation: A Subslab Depressurization System (SSDS), and a groundwater pump and treatment systems are currently operating under a NYSDEC-approved Site Management Plan (SMP). The terms of the Voluntary Cleanup Agreement have been met. The remediation at the site has been completed. The SMP has provisions for frequent system monitoring and maintenance, and for periodic reporting to NYSDEC. There are Deed Restrictions recorded against the site.

Health Problem: The Site was a former warehouse and has been redeveloped as an Information and Technology High School. Contaminated soils beneath the building have been removed and disposed of off-site. Human exposures to residual contaminated soil is unlikely as the site is covered by the on-site building and pavement. Ingestion of groundwater as a potable drinking water source is not expected since the area is served by public water supply. Potential exposures via soil vapor intrusion into the school have been mitigated by the installation and operation of sub-slab depressurization system, a vapor barrier, a eight-inch thick competent concrete slab, and the building's positive-pressure heating and ventilation system. Monthly sampling of soil vapor and quarterly sampling of groundwater will ensure that remedial systems are working properly.

---

194 **TAXI STAND** **NY LTANKS** **S109064181**
WSW **22-10 JACKSON AVE** **N/A**
1/4-1/2 **LONG ISLAND, NY**
0.316 mi.
1666 ft.

Relative:
Lower

Actual:
11 ft.

LTANKS:

Site ID:	394963
Spill Number/Closed Date:	0713239 / 4/22/2008
Spill Date:	3/14/2008
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported

TAXI STAND (Continued) **S109064181**

Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	3/14/2008
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	3/14/2008
Spill Record Last Update:	5/2/2008
Spiller Name:	BOB URBAN
Spiller Company:	TAXI STAND
Spiller Address:	2210 JACKSON AVE
Spiller City,St,Zip:	LONG ISLAND, NY
Spiller County:	001
Spiller Contact:	BOB URBAN
Spiller Phone:	(631) 321-4670
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	344508
DEC Memo:	3/14/08 bf: Sent ttf to:Plaxall5-46 46th Ave.Long Island City, NY 111014/18/08 Received call from Bob Arcaro, consultant handling spill closure. Lione failed during FDNY 10 year precision test. Dry leak at the stage II reovery line. Replaced faulty fittings and retested on 4/9/08 and line passed. Will be sending me a letter. i emailed ttf letter to him: arcarora@aol.com. bf4/22/08 Yesterday, I received an email from R. Arcaro with a letter attached confirming the findings he stated on the phone on 4/18/08. NFA. bf
Remarks:	DRY LEAK

Material:

Site ID:	394963
Operable Unit ID:	1151910
Operable Unit:	01
Material ID:	2142675
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	394963
Spill Tank Test:	2384844
Tank Number:	Not reported
Tank Size:	4000
Test Method:	03
Leak Rate:	0

TAXI STAND (Continued) **S109064181**

Gross Fail: Not reported
Modified By: Watchdog
Last Modified: 3/14/2008
Test Method: Horner EZ Check I or II

195
NW
1/4-1/2
0.326 mi.
1721 ft.

WILSON HANLEY, INC.
21-11 44TH AVENUE
LONG ISLAND CITY, NY 11101

NY SHWS **1001362336**
NY AST **N/A**
NY HIST AST

Relative:
Higher

Actual:
19 ft.

SHWS:
Program: HW
Site Code: 384281
Classification: N
Region: 2
Acres: .037
HW Code: 241110
Record Add: 07/13/2007
Record Upd: 06/11/2008
Updated By: MOBARRIE
Site Description: Site will be investigated as part of the off-site to adjacent site 241107.
Env Problem: Not reported
Health Problem: Not reported
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Owner
Sub Type: NNN
Owner Name: THOMAS C. WILSON, INC.
Owner Company: THOMAS C. WILSON, INC.
Owner Address: 21-11 44TH AVENUE
Owner Addr2: Not reported
Owner City,St,Zip: LONG ISLAND CITY, NY 11101
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

WILSON HANLEY, INC. (Continued) **1001362336**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-017663
Program Type:	PBS
UTM X:	588936.06883
UTM Y:	4511482.4266299997
Expiration Date:	2017/10/23
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	153
Affiliation Type:	Emergency Contact
Company Name:	THOMAS C WILSON INC
Contact Type:	Not reported
Contact Name:	JOHN J. HEEKIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 729-3360
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	9/10/2007

Site Id:	153
Affiliation Type:	On-Site Operator
Company Name:	THOMAS C WILSON INC
Contact Type:	Not reported
Contact Name:	JOHN J.HEEKIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 729-3360
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	9/10/2007

Site Id:	153
Affiliation Type:	Facility Owner
Company Name:	WILSON HANLEY, INC.
Contact Type:	TREASURER
Contact Name:	JOHN J.HEEKIN
Address1:	21-11 44TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001

WILSON HANLEY, INC. (Continued) **1001362336**

Phone:	(718) 729-3360
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	10/30/2012

Site Id:	153
Affiliation Type:	Mail Contact
Company Name:	WILSON HANLEY, INC.
Contact Type:	TREASURER
Contact Name:	JOHN J.HEEKIN
Address1:	21-11 44TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 729-3360
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	10/30/2012

Tank Info:

Tank Number:	001
Tank Id:	27076
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/09/1944
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	KAKYER
Last Modified:	10/30/2012

WILSON HANLEY, INC. (Continued) **1001362336**

Material Name: #2 Fuel Oil (On-Site Consumption)

Tank Number: 002
Tank Id: 27077
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

I00 - Overfill - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 08/01/1981
Capacity Gallons: 600
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER
Last Modified: 10/30/2012
Material Name: Other

HIST AST:

PBS Number: 2-017663
SWIS Code: 6301
Operator: ROBERT C. LENARDI
Facility Phone: (718) 729-3360
Facility Addr2: 21011 44TH AVENUE
Facility Type: OTHER
Emergency: ROBERT C. LENARDI
Emergency Tel: (516) 626-1388
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: THOMAS C WILSON INC
Owner Address: 21-11 44TH AVENUE
Owner City,St,Zip: LONG ISLAND CITY, NY 11101
Federal ID: Not reported
Owner Tel: (718) 729-3360
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: THOMAS C WILSON INC

WILSON HANLEY, INC. (Continued) **1001362336**

Mailing Address:	21-11 44TH AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	LONG ISLAND CITY, NY 11101
Mailing Telephone:	(718) 729-3360
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	10/10/1997
Expiration:	10/23/2002
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	3600
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	3000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	None
Leak Detection:	0
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
SPDES Number:	Not reported
Lat/Long:	Not reported

AK196 **47-20 30TH ST** **NY LTANKS** **S100167498**
SE **47-20 30TH ST** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.327 mi.
1725 ft. **Site 1 of 2 in cluster AK**

Relative:
Lower

Actual:
11 ft.

LTANKS:

Site ID:	153441
Spill Number/Closed Date:	8708435 / 11/2/1992
Spill Date:	12/31/1987
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	11/2/1992
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	12/31/1987
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2/1/1988
Spill Record Last Update:	5/12/1994
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	279923
DEC Memo:	Not reported
Remarks:	5K TANK CANNOT MAINTAIN LEVEL IN STANDPIPE, PRODUCT LEVEL BELOW TANK TOP, POSSIBLE PIPE PROBLEM.

Material:

Site ID:	153441
Operable Unit ID:	913049
Operable Unit:	01
Material ID:	463825
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

47-20 30TH ST (Continued) **S100167498**

Tank Test:

Site ID:	153441
Spill Tank Test:	1532879
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

AK197 **I G FEDERAL ELECTRICAL SUPPLY** **NY LTANKS** **U000401648**
SE **47-20 30TH ST** **NY UST** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101** **NY HIST UST**
0.327 mi.
1728 ft. **Site 2 of 2 in cluster AK**

Relative:
Lower

Actual:
11 ft.

LTANKS:

Site ID:	153440
Spill Number/Closed Date:	0110569 / 3/1/2002
Spill Date:	1/30/2002
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2/4/2002
CID:	396
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2/4/2002
Spill Record Last Update:	3/1/2002
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	NN
Spiller County:	999
Spiller Contact:	LARRY
Spiller Phone:	(718) 729-5700
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	130179
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "VOUGHT"3/1/2002-VOUGHT-Initial tank test performed by ProTest Laboratories. Second and third tank test performed by Federal Electrical Supply Corporation (718-729-5700). The reason for spill report was initial tank test failure. As a result of failure vent

I G FEDERAL ELECTRICAL SUPPLY (Continued) **U000401648**

line, fill line, suction line and return line were replaced by Petroleum Tank Cleaners. Tank was tested again on 2-6-2002 and failed again because testers failed to close off return line to day tank. Tank and system was tested for third time and passed on 2-14-2002. Isaac Mungra and Anthony (PTC) confirmed that there was no soil or groundwater contamination. Tank tests and repair invoices were provided. Spill closed by Vought.

Remarks: Not reported

Material:

Site ID:	153440
Operable Unit ID:	847652
Operable Unit:	01
Material ID:	528190
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	153440
Spill Tank Test:	1526857
Tank Number:	1
Tank Size:	4500
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Horner EZ Check I or II

UST:

Id/Status:	2-303658 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	2017/07/14
UTM X:	589676.12798999995
UTM Y:	4510756.9250999996
Site Type:	Other

Affiliation Records:

Site Id:	13807
Affiliation Type:	Mail Contact
Company Name:	JOMEIRA REALTY COMPANY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	47-20 30TH ST
Address2:	Not reported
City:	LONG ISLAND CITY

I G FEDERAL ELECTRICAL SUPPLY (Continued) **U000401648**

State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 729-5700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	13807
Affiliation Type:	On-Site Operator
Company Name:	I G FEDERAL ELECTRICAL SUPPLY
Contact Type:	Not reported
Contact Name:	I G FEDERAL ELECTRICAL SUPPLY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 729-5700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	13807
Affiliation Type:	Emergency Contact
Company Name:	JOMEIRA REALTY COMPANY
Contact Type:	Not reported
Contact Name:	IRA FRIEDMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(914) 833-1275
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	4/18/2007

Site Id:	13807
Affiliation Type:	Facility Owner
Company Name:	JOMEIRA REALTY COMPANY
Contact Type:	REP
Contact Name:	IRA FREIDMAN
Address1:	47-20 30TH ST
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 729-5700
EMail:	Not reported
Fax Number:	Not reported

I G FEDERAL ELECTRICAL SUPPLY (Continued) **U000401648**

Modified By: msbaptis
Date Last Modified: 4/18/2007

Tank Info:

Tank Number: 001
Tank ID: 16220
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4500
Install Date: 10/30/1984
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 11/30/2006
Next Test Date: 11/30/2011
Pipe Model: Not reported
Modified By: MSBAPTIS
Last Modified: 05/22/2012

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

HIST UST:

PBS Number: 2-303658
SPDES Number: Not reported
Emergency Contact: IRA FRIEDMAN
Emergency Telephone: (914) 833-1656
Operator: I G FEDERAL ELECTRICAL SUPPLY
Operator Telephone: (718) 729-5700
Owner Name: JOMEIRA REALTY COMPANY
Owner Address: 47-20 30TH ST
Owner City,St,Zip: LONG ISLAND CITY, NY 11101
Owner Telephone: (718) 729-5700
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: JOMEIRA REALTY COMPANY
Mailing Address: 47-20 30TH ST
Mailing Address 2: Not reported
Mailing City,St,Zip: LONG ISLAND CITY, NY 11101
Mailing Contact: Not reported

I G FEDERAL ELECTRICAL SUPPLY (Continued) **U000401648**

Mailing Telephone:	(718) 729-5700
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	47020 30TH ST
SWIS ID:	6301
Old PBS Number:	Not reported
Facility Type:	Not reported
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	01/05/1999
Expiration Date:	07/14/2002
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	4500
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (gals):	4500
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	12/01/1998
Next Test Date:	12/01/2003
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

198
WNW
1/4-1/2
0.330 mi.
1740 ft.

SPILL NUMBER 0012047
21ST ST/44TH RD
LONG ISLAND CITY, NY

NY LTANKS **S104950592**
N/A

Relative:
Higher

Actual:
17 ft.

LTANKS:

Site ID:	297242
Spill Number/Closed Date:	0012047 / 10/30/2003
Spill Date:	2/9/2001
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2/9/2001
CID:	396
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2/9/2001
Spill Record Last Update:	10/30/2003
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	240507
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KRIMGOLD"
Remarks:	caller states that there is fuel oil all over the road and getting in to storm sewers....believes that it is from a tank over fill...spill is on the east side of 21st.nfd.

Material:

Tank Test:

199 West 1/4-1/2 0.338 mi. 1786 ft.

ST. FRANCIS OF ASSISI
45-02 21ST AVE.
NEW YORK CITY, NY

NY LTANKS **S100167428** **N/A**

Relative: Lower

Actual: 13 ft.

LTANKS:

Site ID:	242102
Spill Number/Closed Date:	8704696 / 1/25/1989
Spill Date:	9/4/1987
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	c4
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	9/4/1987
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	9/11/1987
Spill Record Last Update:	8/19/2004
Spiller Name:	Not reported
Spiller Company:	ST. FRANCIS OF ASSISI
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	198980
DEC Memo:	Not reported
Remarks:	SYSTEM FAILURE- WILL CONTACT CHURCH AND OFFER TO EXCAVATE AND RETEST. CONTACT- JOE FITZPATRICK (718 726-7568)./RETESTED-06/30/88 BY NAT MOSER 3,000 GAL TANK ISOLATED TANK-LEAKING AT -0.142 GPH.

Material:

Site ID:	242102
Operable Unit ID:	911172
Operable Unit:	01
Material ID:	467320
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

ST. FRANCIS OF ASSISI (Continued) **S100167428**

Tank Test:

Site ID:	242102
Spill Tank Test:	1531564
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

AL200 **C&H SAND AND STONE; CORP.** **NY SWF/LF** **S105841940**
WSW **21-16 JACKSON AVENUE** **NY Spills** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101**
0.343 mi.
1813 ft. **Site 1 of 2 in cluster AL**

Relative:
Lower

Actual:
13 ft.

SWF/LF:

Flag:	INACTIVE
Region Code:	2
Phone Number:	7189372979
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	HUGH FLAHERTY
Contact Address:	21-16 Jackson Avenue
Contact Addr2:	Not reported
Contact City,St,Zip:	Long Island City, NY 11101
Contact Email:	Not reported
Contact Phone:	7189372979
Activity Desc:	C&D processing - registration
Activity Number:	[41W87]
Active:	No
East Coordinate:	588784
North Coordinate:	4510969
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported

Flag:	INACTIVE
Region Code:	2
Phone Number:	5165377525
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported

C&H SAND AND STONE; CORP. (Continued) **S105841940**

Owner Phone: Not reported
Contact Name: JOHN CLAUSE
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: C&D processing - registration
Activity Number: [41W89]
Active: No
East Coordinate: 588784
North Coordinate: 4510969
Accuracy Code: Not reported
Regulatory Status: Not reported
Waste Type: Not reported
Authorization #: Not reported
Authorization Date: Not reported
Expiration Date: Not reported

SPILLS:
Facility ID: 1206533
DER Facility ID: 423842
Facility Type: ER
Site ID: 469536
DEC Region: 2
Spill Date: 10/2/2012
Spill Number/Closed Date: 1206533 / 10/3/2012
Spill Cause: Unknown
Spill Class: Not reported
SWIS: 4101
Investigator: JBVOUGHT
Referred To: Not reported
Reported to Dept: 10/2/2012
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/2/2012
Spill Record Last Update: 10/3/2012
Spiller Name: Not reported
Spiller Company: HEALTY BRAND OIL INC
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: BRAD GREEN
Contact Phone: (718) 937-0806
DEC Memo: 10/3/12-Vought-Duty desk officer. Spill closed a biodegradable cooking oil and non-petroleum spill.
Remarks: anonymous caller reports oil on floor area of facility/cooking oil has exited building and entered storm drain...this has been on going issue for several years

C&H SAND AND STONE; CORP. (Continued) **S105841940**

Material:

Site ID:	469536
Operable Unit ID:	1219429
Operable Unit:	01
Material ID:	2217932
Material Code:	0820A
Material Name:	COOKING OIL
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

AL201 **UNITED WASTE REMOVAL;INC.** **NY SWF/LF** **S105841795**
WSW **2116 JACKSON AVENUE** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101**
0.344 mi.
1818 ft. **Site 2 of 2 in cluster AL**

Relative:
Lower

Actual:
13 ft.

SWF/LF:

Flag:	INACTIVE
Region Code:	2
Phone Number:	7187846611
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	LIRR
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit
Activity Number:	[41T67]
Active:	No
East Coordinate:	Not reported
North Coordinate:	Not reported
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported

202
ESE
1/4-1/2
0.352 mi.
1858 ft.

LA GUARDIA COMMUNITY COLLEGE
31-10 THOMSON AVE
LONG ISLAND CITY, NY 11101

NY LTANKS **S105995066**
NY MANIFEST **N/A**

Relative:
Higher

Actual:
24 ft.

LTANKS:

Site ID:	89365
Spill Number/Closed Date:	0110443 / 1/31/2002
Spill Date:	1/31/2002
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	4101
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	1/31/2002
CID:	211
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1/31/2002
Spill Record Last Update:	9/19/2003
Spiller Name:	KAREN MCCORMACK
Spiller Company:	LAGUARDIA COMM COLLEGE
Spiller Address:	31-10 THOMSON AV
Spiller City,St,Zip:	LONG ISLAND CITY, ZZ
Spiller County:	001
Spiller Contact:	KAREN MCCORMACK
Spiller Phone:	(718) 482-5580
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	81624
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE"01/31/2002 SPILL TO SIDEWALK ONLY, NO IMPACT TO SOILS,SEWERS ETC. OIL COMPANY CONTAINED AND CLEANED IMMEDIATELY. SUPERINTENDANT ERFAN VERIFIED CLEANUP COMPLETE.
Remarks:	SCHOOL ORDERED TOO MUCH PRODUCT LEADING TO OVERFILL - CLEAN UP CREW ON THE WAY

Material:

Site ID:	89365
Operable Unit ID:	847549
Operable Unit:	01
Material ID:	528067
Material Code:	0002A
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	7
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported

LA GUARDIA COMMUNITY COLLEGE (Continued) **S105995066**

Oxygenate: False

Tank Test:

NY MANIFEST:

EPA ID:	NY0000202374
Country:	USA
Mailing Name:	LA GUARDIA COMMUNITY COLLEGE
Mailing Contact:	GODFREY CHEE PING
Mailing Address:	31-10 THOMSON AVE
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-482-5749

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-29
Trans1 Recv Date:	2012-02-29
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	42.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

LA GUARDIA COMMUNITY COLLEGE (Continued) **S105995066**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-29
Trans1 Recv Date:	2012-02-29
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	5.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-29
Trans1 Recv Date:	2012-02-29
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	8.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0

LA GUARDIA COMMUNITY COLLEGE (Continued) **S105995066**

Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-29
Trans1 Recv Date:	2012-02-29
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	10.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-29
Trans1 Recv Date:	2012-02-29

LA GUARDIA COMMUNITY COLLEGE (Continued) **S105995066**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	116.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-29
Trans1 Recv Date:	2012-02-29
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	39.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N

LA GUARDIA COMMUNITY COLLEGE (Continued) **S105995066**

Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-29
Trans1 Recv Date:	2012-02-29
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	6.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-29
Trans1 Recv Date:	2012-02-29
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202374
Trans1 EPA ID:	Not reported

LA GUARDIA COMMUNITY COLLEGE (Continued) **S105995066**

Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	58.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-29
Trans1 Recv Date:	2012-02-29
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	2.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

LA GUARDIA COMMUNITY COLLEGE (Continued) **S105995066**

Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 2012-02-29
Trans1 Recv Date: 2012-02-29
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-03-02
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NY0000202374
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 2.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 004542897FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 2012-02-29
Trans1 Recv Date: 2012-02-29
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-03-02
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NY0000202374
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 251.0
Units: P - Pounds
Number of Containers: 1.0

LA GUARDIA COMMUNITY COLLEGE (Continued) **S105995066**

Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-29
Trans1 Recv Date:	2012-02-29
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	116.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988

LA GUARDIA COMMUNITY COLLEGE (Continued) **S105995066**

Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-29
Trans1 Recv Date:	2012-02-29
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	41.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-29
Trans1 Recv Date:	2012-02-29
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	52.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N

LA GUARDIA COMMUNITY COLLEGE (Continued) **S105995066**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-29
Trans1 Recv Date:	2012-02-29
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	5.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-29
Trans1 Recv Date:	2012-02-29
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported

LA GUARDIA COMMUNITY COLLEGE (Continued) **S105995066**

Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	45.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-29
Trans1 Recv Date:	2012-02-29
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	27.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

LA GUARDIA COMMUNITY COLLEGE (Continued) **S105995066**

Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-29
Trans1 Recv Date:	2012-02-29
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	2.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-29
Trans1 Recv Date:	2012-02-29
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported

LA GUARDIA COMMUNITY COLLEGE (Continued) **S105995066**

Quantity:	12.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-29
Trans1 Recv Date:	2012-02-29
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	1.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004542897FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

LA GUARDIA COMMUNITY COLLEGE (Continued) **S105995066**

Click this hyperlink while viewing on your computer to access
64 additional NY_MANIFEST: record(s) in the EDR Site Report.

203
NE
1/4-1/2
0.361 mi.
1908 ft.

OFFICE BUILDING
29-27 NORTHERN BLVD
LONG ISLAND, NY

NY LTANKS **S108467715**
N/A

Relative:
Higher

Actual:
28 ft.

LTANKS:

Site ID:	377316
Spill Number/Closed Date:	0612458 / 2/16/2007
Spill Date:	2/14/2007
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2/14/2007
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2/14/2007
Spill Record Last Update:	2/21/2007
Spiller Name:	BOB LAGA
Spiller Company:	OFFICE BUILDING
Spiller Address:	29-76 NORTHERN BLVD
Spiller City,St,Zip:	LONG ISLAND, NY
Spiller County:	001
Spiller Contact:	BOB LAGA
Spiller Phone:	(718) 762-5200
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	326872
DEC Memo:	A CSL letter was NOT sent to Mr. Laga. Based on his experience, he knows the standard DEC routine on cases like this.Sangesland left a voice message reviewing the proceedure:Pulled tank, Excavate soil, Sample endpoints for VOC/SVOC, Submit report with results & manifests.02/16/07 Rahman- Closure report from Franklin Company.VOC and Naphthalene are non detect in th e end point sample taken from the tank vault.Tank was 500 gallon, no holes/corrosion observed.SVOC(Benzo group) levels are slightly above the TAGM, which can be artributed as fill material.NFA required.address corrected from 29-76 to 29-27 as per a request from Franklin Company(Bob).
Remarks:	CONTAMINATED SOIL FOUND AFTER PULLING TANK: 500 GALLON T ANK

Material:

Site ID:	377316

OFFICE BUILDING (Continued) **S108467715**

Operable Unit ID:	1134859
Operable Unit:	01
Material ID:	2124741
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

AM204 **GETTY #344** **NY LTANKS** **U004062912**
East **31-05 QUEENS BOULEVARD** **NY UST** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101** **NY HIST UST**
0.379 mi. **NY AST**
2000 ft. **Site 1 of 2 in cluster AM** **NY Spills**

Relative:
Higher

Actual:
43 ft.

LTANKS:

Site ID:	377088
Spill Number/Closed Date:	0612273 / 2/8/2007
Spill Date:	2/8/2007
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2/8/2007
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2/8/2007
Spill Record Last Update:	2/8/2007
Spiller Name:	MIKE CARR
Spiller Company:	LUK OIL
Spiller Address:	3105 QUEENS BLVD
Spiller City,St,Zip:	LONG ISLAND, NY
Spiller County:	001
Spiller Contact:	MIKE CARR
Spiller Phone:	(518) 369-7822
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	309823
DEC Memo:	All cleaned up.Sharif stopped by the site.
Remarks:	DELIVERY OVERFILL AND IS ALL CLEANED UP: FDNY RESPONDED AND TYREE AND

GETTY #344 (Continued) **U004062912**

ABSORBANT USED AND LETTER REPORT TO BE FORWARDED TO DEC:

Material:

Site ID:	377088
Operable Unit ID:	1134643
Operable Unit:	01
Material ID:	2124520
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40
Units:	Gallons
Recovered:	40
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

UST:

Id/Status:	2-145688 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	2014/04/08
UTM X:	589981.44035000005
UTM Y:	4511107.1311499998
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	4184
Affiliation Type:	On-Site Operator
Company Name:	GETTY #344
Contact Type:	Not reported
Contact Name:	SAMI RAFAAT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 433-0539
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	10/8/2009

Site Id:	4184
Affiliation Type:	Emergency Contact
Company Name:	GETTY PETROLEUM MARKETING, INC.
Contact Type:	Not reported
Contact Name:	SCOTT HANLEY
Address1:	Not reported
Address2:	Not reported
City:	Not reported

GETTY #344 (Continued) **U004062912**

State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 324-5110
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2/3/2012

Site Id:	4184
Affiliation Type:	Mail Contact
Company Name:	GETTY PETROLEUM MARKETING, INC.
Contact Type:	AUTHORIZED SIGNATURE FOR CLIENT
Contact Name:	SCOTT HANLEY
Address1:	1500 HEMPSTEAD TURNPIKE
Address2:	Not reported
City:	EAST MEADOW
State:	NY
Zip Code:	11554
Country Code:	001
Phone:	(516) 542-4900
EMail:	SHANLEY@GETTY.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	4/4/2012

Site Id:	4184
Affiliation Type:	Facility Owner
Company Name:	GETTY PETROLEUM MARKETING, INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1500 HEMPSTEAD TURNPIKE
Address2:	Not reported
City:	EAST MEADOW
State:	NY
Zip Code:	11554
Country Code:	001
Phone:	(516) 542-4900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2/3/2012

Tank Info:

Tank Number:	001
Tank ID:	28167
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	06/01/1976
Date Tank Closed:	10/06/2009
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol

GETTY #344 (Continued) **U004062912**

Tightness Test Method: 21
Date Test: 06/20/2008
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 10/08/2009

Equipment Records:

G00 - Tank Secondary Containment - None
K01 - Spill Prevention - Catch Basin
D02 - Pipe Type - Galvanized Steel
F07 - Pipe External Protection - Retrofitted Sacrificial Anode
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
A99 - Tank Internal Protection - Other
B07 - Tank External Protection - Retrofitted Sacrificial Anode
E00 - Piping Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 002
Tank ID: 28168
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 4000
Install Date: 06/01/1976
Date Tank Closed: 10/06/2009
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 21
Date Test: 06/20/2008
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 10/08/2009

Equipment Records:

G00 - Tank Secondary Containment - None
K01 - Spill Prevention - Catch Basin
D02 - Pipe Type - Galvanized Steel
F07 - Pipe External Protection - Retrofitted Sacrificial Anode
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
A99 - Tank Internal Protection - Other
B07 - Tank External Protection - Retrofitted Sacrificial Anode
E00 - Piping Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 003

GETTY #344 (Continued) **U004062912**

Tank ID: 28169
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 4000
Install Date: 06/01/1976
Date Tank Closed: 10/06/2009
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 21
Date Test: 06/20/2008
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 10/08/2009

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F07 - Pipe External Protection - Retrofitted Sacrificial Anode
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
K01 - Spill Prevention - Catch Basin
A99 - Tank Internal Protection - Other
B07 - Tank External Protection - Retrofitted Sacrificial Anode
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 013
Tank ID: 59221
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

GETTY #344 (Continued) **U004062912**

G00 - Tank Secondary Containment - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	014
Tank ID:	59222
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	11/01/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None

Tank Number:	015
Tank ID:	59223
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	11/01/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT

GETTY #344 (Continued) **U004062912**

Last Modified: 03/04/2004

Equipment Records:

G00 - Tank Secondary Containment - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None
I00 - Overfill - None

Tank Number: 016
Tank ID: 59224
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None

Tank Number: 017
Tank ID: 59225
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

GETTY #344 (Continued) **U004062912**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 018
Tank ID: 59226
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None

Tank Number: 019
Tank ID: 59227
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/2000

GETTY #344 (Continued) **U004062912**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None

Tank Number: 020
Tank ID: 59228
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None

Tank Number: 021

GETTY #344 (Continued) **U004062912**

Tank ID: 59229
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:
C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 022
Tank ID: 59230
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
F00 - Pipe External Protection - None

GETTY #344 (Continued) **U004062912**

H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None

Tank Number:	023
Tank ID:	212675
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	05/22/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JMKRIMGO
Last Modified:	07/14/2006

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None

Tank Number:	024
Tank ID:	212676
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	05/22/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JMKRIMGO
Last Modified:	07/14/2006

Equipment Records:

GETTY #344 (Continued) **U004062912**

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None

Tank Number:	025
Tank ID:	212677
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	05/22/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JMKRIMGO
Last Modified:	07/14/2006

Equipment Records:

C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
I00 - Overfill - None

HIST UST:

PBS Number:	2-145688
SPDES Number:	Not reported
Emergency Contact:	LUIS OCHOTORENA
Emergency Telephone:	(718) 729-6500
Operator:	BARBIR SINGH
Operator Telephone:	(718) 706-0317
Owner Name:	LEEMILTS PETROLEUM INC
Owner Address:	125 JERICHO TURNPIKE
Owner City,St,Zip:	JERICHO, NY 11753
Owner Telephone:	(516) 338-6500
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	GETTY
Mailing Address:	125 JERICHO TURNPIKE

GETTY #344 (Continued) **U004062912**

Mailing Address 2:	Not reported
Mailing City,St,Zip:	JERICHO, NY 11735
Mailing Contact:	SCOTT HANLEY
Mailing Telephone:	(516) 338-6500
Owner Mark:	Third Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	Not reported
SWIS ID:	6301
Old PBS Number:	Not reported
Facility Type:	RETAIL GASOLINE SALES
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	01/05/2001
Expiration Date:	01/03/2006
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	12420
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City:	01
Region:	2

Tank Id:	013
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	11/01/2000
Test Method:	Not reported
Deleted:	False
Updated:	True

GETTY #344 (Continued) **U004062912**

Lat/long: Not reported

Tank Id: 014
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Not reported
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 11/01/2000
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 015
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Not reported
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 11/01/2000
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

GETTY #344 (Continued) **U004062912**

Tank Id: 016
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Not reported
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 11/01/2000
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 017
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Not reported
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 11/01/2000
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 018
Tank Location: UNDERGROUND
Tank Status: Closed-Removed

GETTY #344 (Continued) **U004062912**

Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Not reported
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 11/01/2000
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 019
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Not reported
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 11/01/2000
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 020
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE

GETTY #344 (Continued) **U004062912**

Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Not reported
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 11/01/2000
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 021
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Not reported
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 11/01/2000
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 022
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None

GETTY #344 (Continued) **U004062912**

Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	11/01/2000
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-145688
Program Type:	PBS
UTM X:	589981.44035000005
UTM Y:	4511107.1311499998
Expiration Date:	2014/04/08
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	4184
Affiliation Type:	On-Site Operator
Company Name:	GETTY #344
Contact Type:	Not reported
Contact Name:	SAMI RAFAAT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 433-0539
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	10/8/2009

Site Id:	4184
Affiliation Type:	Emergency Contact
Company Name:	GETTY PETROLEUM MARKETING, INC.
Contact Type:	Not reported
Contact Name:	SCOTT HANLEY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999

GETTY #344 (Continued) **U004062912**

Phone:	(718) 324-5110
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2/3/2012

Site Id:	4184
Affiliation Type:	Mail Contact
Company Name:	GETTY PETROLEUM MARKETING, INC.
Contact Type:	AUTHORIZED SIGNATURE FOR CLIENT
Contact Name:	SCOTT HANLEY
Address1:	1500 HEMPSTEAD TURNPIKE
Address2:	Not reported
City:	EAST MEADOW
State:	NY
Zip Code:	11554
Country Code:	001
Phone:	(516) 542-4900
EMail:	SHANLEY@GETTY.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	4/4/2012

Site Id:	4184
Affiliation Type:	Facility Owner
Company Name:	GETTY PETROLEUM MARKETING, INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1500 HEMPSTEAD TURNPIKE
Address2:	Not reported
City:	EAST MEADOW
State:	NY
Zip Code:	11554
Country Code:	001
Phone:	(516) 542-4900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2/3/2012

Tank Info:

Tank Number:	004
Tank Id:	49455
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
K01 - Spill Prevention - Catch Basin
I05 - Overfill - Vent Whistle
G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
D10 - Pipe Type - Copper
J02 - Dispenser - Suction Dispenser

GETTY #344 (Continued) **U004062912**

L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/01/1997
Capacity Gallons:	240
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	10/08/2009
Material Name:	#2 Fuel Oil (On-Site Consumption)

Tank Number:	005
Tank Id:	49456
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
K01 - Spill Prevention - Catch Basin
D00 - Pipe Type - No Piping
J00 - Dispenser - None
A00 - Tank Internal Protection - None
I01 - Overfill - Float Vent Valve
B05 - Tank External Protection - Jacketed
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/01/1997
Capacity Gallons:	180
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	10/08/2009
Material Name:	Waste Oil/Used Oil

Tank Number:	010
Tank Id:	49460
Material Code:	9999
Common Name of Substance:	Other

GETTY #344 (Continued) **U004062912**

Equipment Records:
I02 - Overfill - High Level Alarm
G04 - Tank Secondary Containment - Double-Walled (Underground)
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/1995
Capacity Gallons:	120
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/01/1996
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	Other

Tank Number:	011
Tank Id:	49461
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:
I02 - Overfill - High Level Alarm
G04 - Tank Secondary Containment - Double-Walled (Underground)
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D10 - Pipe Type - Copper
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/1995
Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/01/1996
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	#2 Fuel Oil (On-Site Consumption)

GETTY #344 (Continued) **U004062912**

Tank Number: 012
Tank Id: 51892
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A99 - Tank Internal Protection - Other
G04 - Tank Secondary Containment - Double-Walled (Underground)
B05 - Tank External Protection - Jacketed
D00 - Pipe Type - No Piping
H99 - Tank Leak Detection - Other
I05 - Overfill - Vent Whistle

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1996
Capacity Gallons: 180
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 08/01/1997
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Waste Oil/Used Oil

Tank Number: 04A
Tank Id: 56352
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:
G04 - Tank Secondary Containment - Double-Walled (Underground)
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
K01 - Spill Prevention - Catch Basin
I05 - Overfill - Vent Whistle
J00 - Dispenser - None
A00 - Tank Internal Protection - None
D10 - Pipe Type - Copper
B05 - Tank External Protection - Jacketed
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 02/01/1997
Capacity Gallons: 240
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported

GETTY #344 (Continued) **U004062912**

Register: True
Modified By: NRLOMBAR
Last Modified: 10/08/2009
Material Name: Lube Oil

SPILLS:
Facility ID: 0601451
DER Facility ID: 309823
Facility Type: ER
Site ID: 363688
DEC Region: 2
Spill Date: 5/9/2006
Spill Number/Closed Date: 0601451 / 1/4/2007
Spill Cause: Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 4101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 5/9/2006
CID: 444
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 5/9/2006
Spill Record Last Update: 1/4/2007
Spiller Name: MIKE CARR
Spiller Company: GETTY #344
Spiller Address: 3105 QUEENS BLVD
Spiller City,St,Zip: LONG ISLAND, NY
Spiller Company: 001
Contact Name: MIKE CARR
Contact Phone: (518) 369-7822
DEC Memo: This site is contaminated, but this spill number is closed out and referenced to spill #0513247
Remarks: soil staining under dispenser: will dig out: please see spill # 05-13247

Material:
Site ID: 363688
Operable Unit ID: 1121753
Operable Unit: 01
Material ID: 2111237
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported

GETTY #344 (Continued) **U004062912**

Oxygenate: False

Tank Test:

Facility ID:	0601907
DER Facility ID:	309823
Facility Type:	ER
Site ID:	364262
DEC Region:	2
Spill Date:	5/22/2006
Spill Number/Closed Date:	0601907 / 10/24/2008
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	5/22/2006
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	5/22/2006
Spill Record Last Update:	10/24/2008
Spiller Name:	JOSEPH GAVIN
Spiller Company:	GETTY #00344
Spiller Address:	3105 QUEENS BLVD
Spiller City,St,Zip:	LONG ISLAND, NY
Spiller Company:	001
Contact Name:	JOSEPH GAVIN
Contact Phone:	(631) 694-9696
DEC Memo:	Tyree report says: Joints were tightened & "re-doped". Sump is contained. Lines and leak detectors were tested and passed.
Remarks:	2 LEAKING DISPENSERS #3 & 4: AND CONATINED FOUND DURING INSPECTION

Material:

Site ID:	364262
Operable Unit ID:	1122294
Operable Unit:	01
Material ID:	2111767
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

GETTY #344 (Continued) **U004062912**

Tank Test:

Facility ID:	0513247
DER Facility ID:	309823
Facility Type:	ER
Site ID:	359705
DEC Region:	2
Spill Date:	2/17/2006
Spill Number/Closed Date:	0513247 / 10/24/2008
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2/17/2006
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2/17/2006
Spill Record Last Update:	10/24/2008
Spiller Name:	ROBERT
Spiller Company:	MONTGOMERY DISTRIBUTORS
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	ROBERT DELGADIO
Contact Phone:	(516) 683-0200
DEC Memo:	Couplings in dispensers leaking into containment pans.Pumps shut down. Repairs made. System pressure tested/passedvac out dispenser pans.Tyree report says NO soil dig out. Spill was to sealed containment under dispenser. Lines were tightened and "re-doped" stains to cement "drive mat" No product loss - System pressure tested & Passed.
Remarks:	SHEER VALVES LEAKING AND POOR INVENTORY AND DRY STAINING:

Material:

Site ID:	359705
Operable Unit ID:	1116900
Operable Unit:	01
Material ID:	2107352
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported

GETTY #344 (Continued) **U004062912**

Oxygenate: False

Tank Test:

AM205 **GETTY S/S #344 - GETTY PROPERTIES** **NY LTANKS** **S104278677**
East **31-05 QUEENS BLVD** **NY MANIFEST** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY** **NY Spills**
0.379 mi.
2000 ft. **Site 2 of 2 in cluster AM**

Relative:
Higher

Actual:
43 ft.

LTANKS:

Site ID:	298006
Spill Number/Closed Date:	9909630 / 12/2/2004
Spill Date:	11/8/1999
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	11/8/1999
CID:	233
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	11/8/1999
Spill Record Last Update:	12/2/2004
Spiller Name:	Not reported
Spiller Company:	GETTY #344
Spiller Address:	31-05 QUEENS BLVD
Spiller City,St,Zip:	LONG ISLAND CITY, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	241103
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "VOUGHT"04/12/04TRANSFERRED FROM ODOWD TO VOGUHT12/2/04-Vought-This spill closed and referred to open spill #0009849.
Remarks:	u/g tank failed test tyree to make repair retest to be schedule

Material:

Site ID:	298006
Operable Unit ID:	1084383
Operable Unit:	01
Material ID:	298706
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported

GETTY S/S #344 - GETTY PROPERTIES (Continued) **S104278677**

Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	298006
Spill Tank Test:	1547824
Tank Number:	Not reported
Tank Size:	4000
Test Method:	20
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	USTest 2000/P/LL plus USTest 2000/U

Site ID:	298004
Spill Number/Closed Date:	0009849 / 1/5/2007
Spill Date:	11/30/2000
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	WXSUN
Referred To:	Not reported
Reported to Dept:	11/30/2000
CID:	389
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	11/30/2000
Spill Record Last Update:	1/5/2007
Spiller Name:	Not reported
Spiller Company:	GETTY GAS STATION
Spiller Address:	31-05 QUEENS BLVD
Spiller City,St,Zip:	LONG ISLAND CITY, NY -
Spiller County:	001
Spiller Contact:	ERIC EWALD
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	241103
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "VOUGHT"3/14/03 REASSIGNED FROM ROMMEL TO VOUGHT.08/31/2005 - Feng - Transferred from Vought to Feng.10/18/2005 - Feng - Spill#: 04-10119 has been consolidated into this spill#.10/27/2005 - Feng - Quarterly Monitoring Report, 8/2005 - 10/2005. 4 monitoring wells onsite. and

GETTY S/S #344 - GETTY PROPERTIES (Continued) **S104278677**

there are 4 proposed SVE wells located in north and south side of former 10 (550-gallon) USTs. groundwater flows to north at depth of 24.79' to 27.07' bg. W-1, BTEX below MDL most of the time, MTBE, decreasing, 83ppb this quarter. W-2, below MDL. W-3, both decreasing, 181 BTEX and MTBE below MDL. W-4, below MDL all the time.2/27/2006 - Feng - Quarterly Monitoring Report, 11/2005 - 1/2006. The site is an active Getty gasoline retail station. Groundwater flows to norht at the depth of 24.71' to 27.58' bg. 4 monitoring wells onsite. W-1, MDL BTEX, decreased and 25 ppb MTBE. W-2, MDL both. W-3, decreased and 118 ppb BTEX, increased and 20 ppb MTBE. W-4, MDL both. (RJF)08/21/2006-Sun-Quarterly Monitoring Report, April 2006 - July, 2006. The site is an active Getty gasoline retail station. Groundwater flows to norht at the depth of 24.61' to 25.49' bg. 4 monitoring wells onsite. W-1, MDL BTEX, 26.4 ppb MTBE. W-2, MDL both. W-3, dry, and W-4, MDL both. (Sun)01/05/07: Based on the Quarterly Report dated 10/16/06, BTEX concentrations are non-detect and MTBE concentrations ranged from non-detect to 15 ppb. Spill is closed and NFA letter will be issued. (Sun)

Remarks: CALLER REPORTING A SPILL OF PETROLEUM FOUND TO BE INPACTED SOIL LIKELY FROM A TANK FAILURE. NO CLEAN UP AS OF YET AND NO CALLBACK NECESSARY

Material:

Site ID:	298004
Operable Unit ID:	830828
Operable Unit:	01
Material ID:	543782
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

NY MANIFEST:

EPA ID:	NYR000043505
Country:	USA
Mailing Name:	GETTY PETROLEUM CORP
Mailing Contact:	STEVE GORDON
Mailing Address:	31-05 QUEENS BLVD
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-706-0317

NY MANIFEST:

GETTY S/S #344 - GETTY PROPERTIES (Continued) **S104278677**

No Manifest Records Available

SPILLS:

Facility ID:	0807230
DER Facility ID:	241103
Facility Type:	ER
Site ID:	404569
DEC Region:	2
Spill Date:	9/25/2008
Spill Number/Closed Date:	0807230 / 11/24/2008
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	9/26/2008
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/26/2008
Spill Record Last Update:	6/15/2009
Spiller Name:	ROBERT HOLLAND
Spiller Company:	GETTY 344
Spiller Address:	3105 QUEENS BLVD
Spiller City,St,Zip:	LONG ISLAND CITY, NY
Spiller Company:	999
Contact Name:	ROBERT HOLLAND
Contact Phone:	(631) 404-5355
DEC Memo:	Aboveground motor oil tank. Oil poured into interstitial space while tank was being filled.
Remarks:	CALLER STATES THAT THERE WAS MOTOR OIL FOUND IN THE INTERSTIAL SPACE OF A TANK. NO PRODUCT WAS SPILLED. THERE WAS ALSO AN0THER PRODUCT FOUND IN THE SUMP. PUMP OUT IS PENDING.

Material:

Site ID:	404569
Operable Unit ID:	1161216
Operable Unit:	01
Material ID:	2152409
Material Code:	0015
Material Name:	Motor Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	404569

GETTY S/S #344 - GETTY PROPERTIES (Continued) **S104278677**

Operable Unit ID:	1161216
Operable Unit:	01
Material ID:	2152410
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9705058
DER Facility ID:	241103
Facility Type:	ER
Site ID:	298005
DEC Region:	2
Spill Date:	7/28/1997
Spill Number/Closed Date:	9705058 / 12/2/2004
Spill Cause:	Housekeeping
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	7/28/1997
CID:	266
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	7/28/1997
Spill Record Last Update:	12/2/2004
Spiller Name:	LOU OCHOTORENA
Spiller Company:	GETTY OIL CORPORATION
Spiller Address:	30-23 GREEN POINT AVENUE
Spiller City,St,Zip:	LONG ISLAND CITY, NY 11101-
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "VOUGHT"12/5/03-Vought-Transferred from O'Dowd to Vought on 12/5/03.12/2/04-Vought-This spill closed and referred to open spill #0009849.
Remarks:	7 YARDS OF CONTAMINATED SOIL FOUND DURING REMOVAL OF A 550 GALLON WASTE OIL TANK.

Material:

GETTY S/S #344 - GETTY PROPERTIES (Continued) **S104278677**

Site ID:	298005
Operable Unit ID:	1048381
Operable Unit:	01
Material ID:	334280
Material Code:	0022
Material Name:	Waste Oil/Used Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	0902163
DER Facility ID:	241103
Facility Type:	ER
Site ID:	414198
DEC Region:	2
Spill Date:	5/22/2009
Spill Number/Closed Date:	0902163 / 9/24/2009
Spill Cause:	Other
Spill Class:	Not reported
SWIS:	4101
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	5/22/2009
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	5/22/2009
Spill Record Last Update:	9/29/2009
Spiller Name:	MATT BOECKEL
Spiller Company:	GETTY 344
Spiller Address:	31-05 QUEENS BLVD
Spiller City,St,Zip:	LONG ISLAND CITY, NY
Spiller Company:	999
Contact Name:	MATT BOECKEL
Contact Phone:	(631) 249-3150
DEC Memo:	05/22/09 CSL was sent to Getty Petroleum Marketing1500 Hempstead TurnpikeEast Meadow, NY 11554Attn: Scott Hanley08/31/09- Tyree sent the Subsurface Investigation Report dated June/22/09. The report stated that the piping and the four(4) product dispensers were removed in May 2009. The USTs has been drain of all fuel and are scheduled to be abondoned. On May 22,2009 the subsurface investigation activities were initiated , Based upon recent analytical datas it appears that the source of the soil and

GETTY S/S #344 - GETTY PROPERTIES (Continued) **S104278677**

groundwater contamination is located in the area of the USTs and pump island.A total of seven (7)soil/groundwater borings were installed as part of the investigation. Soil samples were collested from ground surface to depths ranging from thirty-five(35) feet to forty (40) feet below grade. Groundwater was encountered at (27) feet below grade.The analytical results for soil samples indicate No VOCs exceeding the RSCOs. Some SVOC'S were slighly exceding the RSCOs for the samples ND-W, ND-E, WD-N, WD-S and B-TFE(13-14 ft).The analytical results for grounswater indicate Methyl-tert Butyl Ether and Benzene slighly exceeding the RSCOs. SVOC"s ara not exceding the RSCOs.As per Scott Hanley Getty Marketing (516) 542-5023 and Kevin Shean Getty Realty Corporation (516) 478-5400 there is no plan for developing the site until 20015. The site is going to be used for vehicle repair inside and for storage of vehicle outside. Getty Marketing leased the property. Getty Realty Corporation owns the property. Spill Closed

Remarks: CALLER STATES THAT THEY GOT TEST RESULTS BACK FROM A PHASE 2 SHOWING SOIL CONTAMINATION CLEAN UP IS PENDING.

Material:

Site ID:	414198
Operable Unit ID:	1170588
Operable Unit:	01
Material ID:	2162324
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	0800383
DER Facility ID:	241103
Facility Type:	ER
Site ID:	396128
DEC Region:	2
Spill Date:	4/10/2008
Spill Number/Closed Date:	0800383 / 7/9/2008
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	4/10/2008
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported

GETTY S/S #344 - GETTY PROPERTIES (Continued) **S104278677**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	4/10/2008
Spill Record Last Update:	7/9/2008
Spiller Name:	MIKE CARR\\
Spiller Company:	GETTY#344
Spiller Address:	3105 QUEENS BLVD
Spiller City,St,Zip:	LONG ISLAND CITY, NY
Spiller Company:	001
Contact Name:	MIKE CARR\\
Contact Phone:	(518) 369-7822 CELL
DEC Memo:	Tyree Closure letter dated 7/8/2008 states:"The above noted site utilizes one 4,000 gallon premium grade gasoline underground storage tank (UST), one 4,000 gallon regular grade gasoline UST and one 4,000 gallon diesel fuel UST. On April 10, 2008 WCC Tank Technology, Inc. performed an inspection of the interior tank lining for all three USTs. The results of the inspection revealed that the tanks failed on the visual inspection and the tank lining thickness. The tanks did pass on the tank metal thickness. It should also be noted that the three tanks were tightness tested and all passed, as such there was no release to the environment. A copy of the tank inspection report is included with this report. The NYSDEC was immediately notified and spill No. 08-00383 was assigned to the site. The three tanks were re-lined subsequent to the initial inspection. On June 20, 2008 the three tanks and the associated piping system were tightness tested. The results of the tightness test indicated that all of the tanks and the associated piping passed. A copy of the tightness testing report is included with this report."Based on this information, the DEC is closing this spill case.
Remarks:	LINE TEST FAILED

Material:

Site ID:	396128
Operable Unit ID:	1153074
Operable Unit:	01
Material ID:	2143854
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	0410119
DER Facility ID:	241103
Facility Type:	ER
Site ID:	335029
DEC Region:	2
Spill Date:	12/11/2004
Spill Number/Closed Date:	0410119 / 10/18/2005

GETTY S/S #344 - GETTY PROPERTIES (Continued) **S104278677**

Spill Cause:	Traffic Accident
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	rjfeng
Referred To:	Not reported
Reported to Dept:	12/11/2004
CID:	27
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	12/13/2004
Spill Record Last Update:	10/18/2005
Spiller Name:	Not reported
Spiller Company:	GETTY #344
Spiller Address:	31-05 QUEENS BLVD
Spiller City,St,Zip:	LONG ISLAND CITY, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	08/31/2005 - Feng - Transferred from Vought to Feng.10/18/2005 - Feng - spill consolidated with spill #: 00-09849 in same location.
Remarks:	Caller reports a car backed into a gas pump. Spill is contained in the dispencer sump and it has been cleaned up. Callers cell number is 518.369.7822.

Material:

Site ID:	335029
Operable Unit ID:	1097138
Operable Unit:	01
Material ID:	577091
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	2
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

206
South
1/4-1/2
0.398 mi.
2102 ft.

BLACK BEAR COMPANY
27-10 HUNTERS POINT AVE
QUEENS, NY

NY LTANKS

S106972606
N/A

Relative:
Higher

Actual:
14 ft.

LTANKS:

Site ID:	345633
Spill Number/Closed Date:	0501474 / 8/16/2005
Spill Date:	5/5/2005
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	4101
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	5/5/2005
CID:	71
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	5/5/2005
Spill Record Last Update:	11/9/2007
Spiller Name:	ABRAHAM WEXLER
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	ABRAHAM WEXLER
Spiller Phone:	(718) 731-7011
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	291869
DEC Memo:	5/6/05 mt/// tank now being emptied, ttf letter sent///////5/23/05 mt//// tank emptied and cleaned, may be closed in place//attempted calling # in fax..Not in service.5/31/05 mt/updating//black bear company retained Richard Baldwin to conduct investigation//8/16/05 Tipple observed samples from gw interface, no visual or olfactory evidence of petroleum contamination//Tank must be removed or properly abandon in place as soon as feasible, no further action necessary to remediate contaminants at this site.Spill Closed
Remarks:	WET PORTION LEAK

Material:

Site ID:	345633
Operable Unit ID:	1103350
Operable Unit:	01
Material ID:	583562
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2500

BLACK BEAR COMPANY (Continued) **S106972606**

Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 345633
Spill Tank Test: 1548874
Tank Number: Not reported
Tank Size: 7500
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Watchdog
Last Modified: 5/5/2005
Test Method: Horner EZ Check I or II

AN207 **LOVOUR HOME** **NY LTANKS** **S108639404**
NNE **2512 41ST AVE** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.399 mi.
2107 ft. **Site 1 of 2 in cluster AN**

Relative:
Higher

Actual:
34 ft.

LTANKS:
Site ID: 380071
Spill Number/Closed Date: 0700688 / 2/17/2010
Spill Date: 4/18/2007
Spill Cause: Tank Test Failure
Spill Source: Tank Truck
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 4101
Investigator: bkfalvey
Referred To: Not reported
Reported to Dept: 4/18/2007
CID: 444
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 4/18/2007
Spill Record Last Update: 2/17/2010
Spiller Name: ERIC LOVOUR
Spiller Company: LOVOUR HOME
Spiller Address: 2512 41ST AVE
Spiller City,St,Zip: LONG ISLAND CITY, NY
Spiller County: 001
Spiller Contact: ERIC LOVOUR
Spiller Phone: (718) 392-2123
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 329555

LOVOUR HOME (Continued) **S108639404**

DEC Memo: 4/25/07 bf: sent ttf letter to:Eric LevorQueens Plaza Realty Corp.25-12 41 AvenueLong Island City, NY 11101-38825/25/07 received passing tightness test results by fax from Eric Lovor. Tried calling him at number on fax:(718)392-2123. No answer. To close this spill, he needs to submit a response to ttf letter. bf5/29/07 Called E. Levor again and there was no answer. Called Emergency Contact # from PBS facility info (718)263-2418 and left message to call me back. bf6/4/07 Called E. Levor at (718)392-2123. The number is no longer in service. I then left a message at (718)263-2418. bf6/5/07 Received 2 messages from Edith Levor to call back. (718)392-2123. Called her at 3:45 Pm and she said that the tank failed the test because there were two sets of vent pipes. The old vent pipe was never disconnected. She said she will call Advanced Tank after she hangs up with me and have them prepare a response to the ttf letter. bf11/8/07 Called E. Levor. Left message that i still have not received letter from Advanced Tank and to call me back. Called Vinnie the Tank Doctor (718)727-0666. He said that there was an open line from a hot water heater and he plugged the line. No contaminated soil was found. He faxed paperwork to E. Levor. He was not in his office and requested I call him Monday. He will check to see if he still has the fax. bf11/26/07 Received message from E. Levor. Called her back and left message on her machine. bf1/22/10 Inspected site and issued NOV for expired registration, failure to monitor unmetered tank for leaks, and failure to contain/reomve petroleum discharge. Administrative settlement conference is scheduled for 2/17/10 at 10:30 AM. bf2/17/10 PBS Settlement Conference held today. Attended by Edith and Eric levor. Provided 6/7/07 letter from Tank Doctor Inc. stating that 2 unused lines from top of tank were disconnected in building. Removed lines and tank retested and passed. NFA. bf

Remarks: PBS No: 2-607688

Material:

Site ID:	380071
Operable Unit ID:	1137562
Operable Unit:	01
Material ID:	2127510
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	380071
Spill Tank Test:	1550766
Tank Number:	1
Tank Size:	1500
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	4/18/2007

LOVOUR HOME (Continued) **S108639404**

Test Method: Horner EZ Check I or II

AO208 **APRT** **NY LTANKS** **S108983070**
NNE **2403 41ST AVE** **N/A**
1/4-1/2 **QUEENS, NY**
0.417 mi.
2203 ft. **Site 1 of 2 in cluster AO**

Relative:
Higher

Actual:
28 ft.

LTANKS:

Site ID:	393128
Spill Number/Closed Date:	0711618 / 4/2/2008
Spill Date:	2/4/2008
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	2/4/2008
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2/4/2008
Spill Record Last Update:	3/30/2009
Spiller Name:	MARLIN JOSEPH
Spiller Company:	APRT
Spiller Address:	2403 41ST AVE
Spiller City,St,Zip:	QUEENS, NY
Spiller County:	001
Spiller Contact:	MARLIN JOSEPH
Spiller Phone:	(718) 624-4842
Spiller Extention:	112
DEC Region:	2
DER Facility ID:	342746
DEC Memo:	2/21/08 Called Dominic Casamento (718)278-0806. left message to call me back. Sent ttf letter to:Dominic Casamento2403 41st LLC14-38 31st DriveLong Island City, NY 11106Mr. Casamento called back later in the day. He said Petroleum Tank Cleaners will be coming back on Monday to make necessary repairs. He said they told him it was a dry leak. I confirmed the above address as his mailing address. He is on vacation and will be returning Monday. bf4/2/08 received fax from M. Salamack of PTC. Tank was emptied and lines and tank were isolated. vent line was hit by a vehicle as tank is under a driveway area. Vent line was replaced to a different area to prevent future accidents. Tank was retesed 3/10/08 and passed. Test results attached. NFA. bf
Remarks:	DRY PORTION LEAK

Material:

APRT (Continued) **S108983070**

Site ID:	393128
Operable Unit ID:	1150101
Operable Unit:	01
Material ID:	2140683
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	393128
Spill Tank Test:	2384605
Tank Number:	Not reported
Tank Size:	1500
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	2/4/2008
Test Method:	Horner EZ Check I or II

AN209 **CLOSED-LACKOF RECENT INFO** **NY LTANKS** **S100153363**
NNE **40-40 CRESCENT ST** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.419 mi.
2214 ft. **Site 2 of 2 in cluster AN**

Relative:
Higher

Actual:
34 ft.

LTANKS:

Site ID:	271352
Spill Number/Closed Date:	9105613 / 3/14/2003
Spill Date:	8/23/1991
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	8/23/1991
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	9/17/1991
Spill Record Last Update:	10/24/2003
Spiller Name:	Not reported

CLOSED-LACKOF RECENT INFO (Continued) **S100153363**

Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	220855
DEC Memo:	Not reported
Remarks:	THREE 2K TANKS SIPHONED. PETROTITE.CLOSED DUE TO LACK OF ANY RECENT INFO - DOES NOT MEET ANY CLEANUP REQUIREMENTS.

Material:

Site ID:	271352
Operable Unit ID:	956119
Operable Unit:	01
Material ID:	421399
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	271352
Spill Tank Test:	1538951
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

AO210 **24-03 41ST AVE** **NY LTANKS** **U003066518**
NNE **24-03 41ST AVE** **NY UST** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101**
0.420 mi.
2219 ft. **Site 2 of 2 in cluster AO**

Relative:
Higher

Actual:
30 ft.

LTANKS:

Site ID:	174701
Spill Number/Closed Date:	8709565 / 2/25/1993
Spill Date:	2/10/1988
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	2/25/1993
Cleanup Meets Standard:	False

24-03 41ST AVE (Continued) **U003066518**

SWIS:	4101
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	2/10/1988
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2/23/1988
Spill Record Last Update:	5/12/1994
Spiller Name:	Not reported
Spiller Company:	LAMBERT PETA
Spiller Address:	24-03 41ST. STREET
Spiller City,St,Zip:	L.I.C., NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	146914
DEC Memo:	Not reported
Remarks:	-0.491 G.P.H. DETECTED LEAK RATE COMING FROM A 1500 GALLON TANK . THE COMPANY OWNING THE TANK HAS BEEN NOTIFIED BUT HAS NOT CONFIRMED ANY ACTIONS REGARDING THIS FAILURE.

Material:

Site ID:	174701
Operable Unit ID:	914644
Operable Unit:	01
Material ID:	464893
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	174701
Spill Tank Test:	1533215
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

24-03 41ST AVE (Continued) **U003066518**

UST:

Id/Status:	2-095265 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	2017/06/12
UTM X:	589499.50413000002
UTM Y:	4511838.0478299996
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	2629
Affiliation Type:	Facility Owner
Company Name:	2403 41ST LLC
Contact Type:	OWNER
Contact Name:	DOMINIC CASAMARO
Address1:	14-38 31 DRIVE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 278-0806
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	3/27/2012

Site Id:	2629
Affiliation Type:	Mail Contact
Company Name:	2403 41ST LLC
Contact Type:	Not reported
Contact Name:	DOMINIC CASAMENTO
Address1:	14-38 31 DRIVE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 278-0806
EMail:	DCANDS@ACK.COM
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	3/27/2012

Site Id:	2629
Affiliation Type:	On-Site Operator
Company Name:	24-03 41ST AVE
Contact Type:	Not reported
Contact Name:	MANUEL MUNOZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 228-7882

24-03 41ST AVE (Continued) **U003066518**

EMail: Not reported
Fax Number: Not reported
Modified By: DXLIVING
Date Last Modified: 4/5/2007

Site Id: 2629
Affiliation Type: Emergency Contact
Company Name: 2403 41ST LLC
Contact Type: Not reported
Contact Name: DOMINIC CASAMENTO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (201) 259-1434
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank ID: 4513
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 1500
Install Date: 12/01/1950
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 03/04/2013
Next Test Date: 03/04/2018
Pipe Model: Not reported
Modified By: BKFALVEY
Last Modified: 07/29/2013

Equipment Records:

G00 - Tank Secondary Containment - None
H99 - Tank Leak Detection - Other
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
K00 - Spill Prevention - None

211
NNW
1/4-1/2
0.421 mi.
2222 ft.

MANHOLE 14413
QUEENS PLAZA NORTH
QUEENS, NY

NY LTANKS
NY Spills

S104950693
N/A

Relative:
Higher

Actual:
18 ft.

LTANKS:

Site ID:	63771
Spill Number/Closed Date:	0100062 / 6/16/2003
Spill Date:	4/3/2001
Spill Cause:	Tank Failure
Spill Source:	Commercial Vehicle
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	4/3/2001
CID:	382
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	4/3/2001
Spill Record Last Update:	6/16/2003
Spiller Name:	UNKNOWN
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	***UPDATE***, NY
Spiller County:	001
Spiller Contact:	FIREFIGHTER GIORDANO
Spiller Phone:	(917) 769-0483
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	61550
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"
Remarks:	saddle tank on tractor trailer became dislodged and spilled oil onto roadway and did enter sewer system. hazmat on scene

Material:

Site ID:	63771
Operable Unit ID:	838626
Operable Unit:	01
Material ID:	539338
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

MANHOLE 14413 (Continued) **S104950693**

Tank Test:

SPILLS:

Facility ID:	0403163
DER Facility ID:	162666
Facility Type:	ER
Site ID:	195222
DEC Region:	2
Spill Date:	6/22/2004
Spill Number/Closed Date:	0403163 / 9/23/2004
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	SKARAKHA
Referred To:	Not reported
Reported to Dept:	6/22/2004
CID:	41
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	6/22/2004
Spill Record Last Update:	9/23/2004
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	ERT DESK
Contact Phone:	(212) 580-8383
DEC Memo:	e2mis no 153985U.G. REPORTS FINDING APPROX 2 QTS OF AN UNKNOWN OIL ON APPROX 1000 GALS OF WATER. PCB SAMPLE TAKEN. Lab Sequence Number: 04-04877-001PCBs < 1 ppmTHE SAMPLE HAD THE PCB SURROGATE OUT OF THE QC LIMITS. RE-EXTRACTION AND RE-ANALYSIS WAS NOT POSSIBLE SINCE ALL OF THE ORIGINAL SAMPLE WAS UTILIZED. THE REPORTED PCB VALUE IS THE MINIMUM CONCENTRATION DETECTED IN THE SAMPLE.STANFORD ENVIROMENTAL OPS REPORTS EATHREN SUMP IN STRUCTURE.UPDATE: 22-JUN-2004 STANFORD REPORTS DOUBLE WASHED STRUCTURE WITH BIO GEN 760. REMOVED ALL LIQUIDS. SEALED SUMP.
Remarks:	2 quarts unknown oil - earthen sump found in manhole. Queens Plaza North at Crescent Street.

Material:

Site ID:	195222
Operable Unit ID:	886628
Operable Unit:	01
Material ID:	490758
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported

MANHOLE 14413 (Continued) **S104950693**

Material FA:	Petroleum
Quantity:	2
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

212
NW
1/4-1/2
0.425 mi.
2242 ft.

Relative:
Higher

Actual:
18 ft.

STRUCTURAL DISPLAY CO., INC **NY LTANKS** **S103824757**
12-12 23RD AVENUE **N/A**
LONG ISLAND CITY, NY 11106

LTANKS:

Site ID:	164528
Spill Number/Closed Date:	9814023 / 9/5/2012
Spill Date:	7/7/1998
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	2/19/1999
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2/19/1999
Spill Record Last Update:	9/5/2012
Spiller Name:	Not reported
Spiller Company:	1212 43RD AVE
Spiller Address:	1212 23RD AVE
Spiller City,St,Zip:	LONG ISLAND CITY, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	138718
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ROMMEL"4/12/04-Vought-Spill transferred from Tomasello to Rommel as per Rommel.04/11/06 - DER rem Bureau E staff sent out RFI letter to site owner (Rwz LLc). Department gave owner until 4/28/06 to respond.04/20/06 - Staff received call from Liam Horgan (212.785-0266 liam@art-corp.net), Assessment Resources & Technologies, Inc. (hired by owner), indicated he would send site data to Department. ORC remediation of groundwater is ongoing. 07/19/06 - Staff received

STRUCTURAL DISPLAY CO., INC (Continued) **S103824757**

remedial summary report from Assessment Resources & Technologies, Inc. (A.R.T., Inc.). Report indicates site has been treated with ORC using injection field of wells since October 2003. The reports indicates that the ORC Injection Field is effectively remediating the groundwater contamination. Additional monitoring well sampling is planned for August 2006. 08/14/06 - DER, Bureau E staff received call from Bob Corroon (representing RWZ LLC)requesting status of site closure by Department. Staff indicated project transferred back down to region 2. It is anticipated that they willl review data gathered in August and make a determination as to whether or not site can be closed.05/29/07 - DER, Bureau E staff received call from Bob Corroon (representing RWZ LLC)(rcorroon@ix.netcom.com and (212)751-4620, ext 103) requesting status of site closure by Dept and an interest to close spill. Evidently, property is up for sale. Staff indicated project transferred back down to Region 2. Staff to provide Mr. Corroon with Regional project contact. Staff provided information to Mr. Corroon, via email, in P.M. on May 29.10/24/07-Zhune discussed with Randy and based on the data he asked me to transfer this case to the remediation group. 02/20/08 - Debra Shapiro, consultant for the current site owner called and asked about the report prepared by ART company to make further recommendations of investigation, remedy or closure. Debra stated ART's report was prepared by ART for the previous site owner and she does not have it. I asked Zhune to locate report if available.6/4/2008 Mimi from ELM (212-581-8023 ext 3) called to ask about the status of the report. She sent another copy of her companies plan in early May 2008. After the call Sangesland tracked the report to Vadim's office. Mimi will contact Vadim to set up a new case manager and a file review by DEC.6/4/08 DEC Case Manager transferred from V. Brevdo to J.A. Maisonave. - JAM6/26/08 Telephone conversation with Mimi R. from ELM. We discussed rpt dated May 5, 2008. Conceptual remedy is to excavate two areas of soil contamination. Latest GW results are from July 2007, and suggest no adverse impacts to GW. DEC suggests that an up to date round of GW samples be collected to verify. We will schedule a meeting when GW sample results are available. Rpt is uploaded to eDocs as three different files. - JAM7/18/08 Received a memo today via email from ELM summarizing groundwater sampling results for the July 7, 2008 sampling event. Minor concentrations of VOCs were detected in the wells downgradient of the former tank field (Benzene detected at 363ug/L and total VOCs at 571ug/L in well MW-1(ART)). Memo uploaded to eDocs. - JAM7/23/08 Meeting held at Region 2 offices on July 22, 2008.Attendence:Joseph Maisonave, NYSDECJonathan Kolleeny, NYSDECMimi Raygorodetsky, ELMDik Glass, RLIC RealtyMichael DelCioppo, RLIC RealtyMeeting was held to discuss future remedial plans for site. ELM's first proposal was to excavate two areas of site; northwest corner and north central areas have soil contamination.Issues:1) The northwest corner of the site, location of the two former USTs, has residual soil (from 10'-18') and groundwater contamination (Benzene and MTBE detected in July 2008 sampling event). ELM will excavate the area but requests leaving a 1:1 slope on the sidewall adjacent to the sidewalk to eliminate the requirement to shore and stabilize the sidewalk.The NYSDEC does not suggest leaving a 1:1 slope because the most contaminated soil (based on boring logs and analytical sampling) will be left in place. The NYSDEC requests a proposal to fully address soil contamination in the northwest corner.2) The north-central area of the site contains 2 oil/water separators and petroleum impacts were observed in the field, however, laboratory

STRUCTURAL DISPLAY CO., INC (Continued) **S103824757**

data were returned with no exceedences for VOCs. ELM requests leaving that soil in place after removing the oil water separators.The NYSDEC requests that two groundwater monitoring wells be installed directly downgradient from the oil water separators and sampled to be sure that groundwater is not impacted. Grossly contaminated soil should be removed when removing the oil/water separators and end-point soil samples should be collected.I expect a summary report for the installation of the two wells with groundwater analytical results and a remedial action proposal for the soil in the northwest corner of the site. - JAM8/25/08 Spoke to Mimi R. today. The current structure foundation was removed as well as two oil water separators and 1 UST. No end-point samples were collected. ELM is proposing doing GPR to locate more potential USTs and installing the 2 downgradiet monitoring wells that the DEC requested in the last meeting. - JAM9/18/08 Reviewed the Spill Investigation and Remediation Work Plan dated Sept. 3, 2008 submitted by ELM. The work plam proposes the following:1. Use ground-penetrating radar to conduct a geophysical survey and to determine whether there are any remaining underground tanks.2. Advance a minimum of 3 soil borings, one in each location of two oil/water separators and one UST, which were removed during deconstruction of the former building.3. Install two monitoring wells in the northeast portion of the site.4. Inject RegenOx in the area of the former USTs in the norhtwest portion of the site.I sent an approval letter today with one requirment. Confirmatory soil sampling must be performed subsequent to the RegenOx injections. Soil borings should be advanced as close as possible to former "T" boring locations to collect confirmatory samples.ELM also plans to install a vapor barrier and a passive venting system beneath the foundation of the new structure, which will be built on the northern portion of the site. The rest of the site will be capped with either asphalt, concrete of clean fill. The work plan and the approval letter are uploaded to eDocs. - JAM9/22/08 ELM notified Dennis McChesney at the EPA about the RegenOx injection, as per EPA UIC Program regulations. EPA will review and respond. - JAM10/03/08 Visited the site today. ELM advanced 5 soil borings yesterday and installed the two monitoring wells along 43rd Ave today. Visibly contaminated soil and odors were observed in each soil boring, however PID readings were relatively low (max reading was around 200ppm). Soil samples were taken at each boring from the interval with the highest PID reading, which was directly above the water table at each boring location. The RegenOx injection will occur when EPA UIC Program approval is given. - JAM10/20/08 Spoke with Rich Kampf at ELM. ELM proposes to expand the RegenOx injection area to include the "D-boring" area. I verbally approved this proposal and asked for a formal addendum to the remedial work plan. I requested that ELM submit the supporting calculations for the amount of RegenOx to be injected. I also requested the Investigation Summary Report from work performed in early October 2008 be submitted as well. - JAM10/29/08 Reviewed the Addendum to Spill Investigation and Remediation Work Plan submitted by ELM dated October 29, 2008. This addendum summarizes investigations performed on October 2 and 3, 2008 as per the approved work plan date September 3, 2008. ELM advanced 5 soil borings (SB-1 through SB-5) and installed 2 monitoring wells at locations SB-4 and SB-5. Evidence of soil contamination was found near the water table (interval 10-15 feet) in all soil borings. Compounds detected were Ethylbenzene, Xylenes and Naphthalene. Groundwater contamination was observed in both wells MW-4 and MW-5. Compounds detected were

STRUCTURAL DISPLAY CO., INC (Continued) **S103824757**

Benzene, Ethylbenzene, Xylene and Naphthalene. Please see table in report for concentrations.ELM proposes expanding RegenOx injections to address contamination observed in this area (D-boring area). ELM will inject 200lbs of RegenOx in each of 23 injection points. A total of 4,200 lbs of RegenOx will be injected at the D-boring area. Rpt is uploaded to eDocs.I sent a letter today approving this work plan. Confirmatory soil and groundwater sampling must be conducted quarterly beginning one month after the RegenOx injections to evaluate its effectiveness. Approval letter uploaded to eDocs. - JAM10/30/08 RegenOx injections commenced in the T-boring area today. I visited the site to witness the first injection point. ELM estimates the injections will take 8 days for both the T-boring and D-boring areas. - JAM12/10/08 Received call from Mimi Raygorodetsky and follow-up email was received from Nicole Gorelick. ELM will perform confirmatory soil & GW sampling at site on 12/11/08 and 12/12/08 to evaluate effectiveness of RegenOx injections. Email is uploaded to eDocs. - JAM12/15/08 Received a call from Nicole Gorelick at ELM. Soil borings were advanced in the T-boring area and the D-boring area on Friday, 12/12/08 to evaluate the effectiveness of the RegenOx injections. When trying to sample wells ELMMW-5 and MW-1 (ART), they appeared to be damaged from construction activities on-site and could not be sampled. Ms. Gorelick said she will be back at the site tomorrow to sample wells MW-2 (ART), MW-3 (ART) and ERMMW-5. A summary report will be submitted when results are available. - JAM12/16/08 Visited site today. I walked site with Mimi Raygorodetsky and Nicole Gorelick from ELM and saw 5 wells, two of which were damaged by construction activities (MW-1 ART and ELMMW-4). I said that these monitoring wells may need to be reinstalled based on results from other 3 monitoring wells, which were sampled today. A rpt summarizing soil samples collected last week and GW samples collected today will be submitted. - JAM1/12/09 Received an email report today from ELM titled Post-Injection Effectiveness Monitoring. ELM completed the in-situ chemical oxidation using RegenOx from October 30 through November 12, 2008. The effectiveness monitoring consisted of collecting soil samples from five soil borings and groundwater samples from accessible wells on- and off-site.Monitoring wells ELM MW-4, MW-2(ART) and MW-3(ART) were sampled on December 16, 2008. MW-1 (ART) and ELM MW-5 were not sampled because they were destroyed by construction activities on-site. Groundwater quality improved significantly in well ELM MW-4, however, groundwater quality in MW-2 (ART) showed increases for Benzene and MTBE. VOC concentrations in MW-3(ART) remained non-detect.Soil samples showed some improvement post-injection, however there were also increases in some conpounds that ELM attributes to sample variability and intervals between separate sample events were not exactly duplicated.Since the overall soil and groundwater conditions improved, ELM proposes that no additional injection rounds be performed in the T and D boring areas. ELM says that ELM MW-1 will be replaced within the next two weeks and groundwater monitoring events will continue. Email report uploaded to eDocs. - JAM1/14/09 Emailed Mimi Raygorodetsky at ELM and said that DEC would like to see GW results from replacement well MW-1 before determining if future injections are not necessary. - JAM1/15/09 Received a call from Nicole Gorelick at ELM. They will be reinstalling well MW-1 tomorrow morning and sampling the well next Friday. - JAM2/3/09 Received an email from Mimi Raygorodetsky at ELM on 2/2/09. Monitoring well ELM MW-1R was installed on January 16, 2009 to replace the previously

STRUCTURAL DISPLAY CO., INC (Continued) **S103824757**

destroyed well ART-MW-1. ELM MW-1R was installed out of the building footprint and approximately 10 feet away from the previous well (see figure). The well was sampled on January 23, 2009 and while purging, petroleum odors and a sheen were observed. Groundwater sample results showed eight VOCs detected above TOGS. Most notable was Benzene at 267ug/L.Since sediments was noted in well ELM MW-4 during the last sampling event, ELM attempted to purge the well on January 19. 2009. While purging, petroleum odors and a sheen was observed.I spoke with Mimi today and sent a follow-up email which stated:"I have reviewed the data you have provided in the last two emails. The DEC will not require additional remediation at this time; however, quarterly groundwater monitoring should continue for at least two additional events and monitoring reports should be submitted to the DEC for review. Based on those groundwater results, additional sampling may be required."ELM's email is uploaded to eDocs. - JAM7/15/09 Received a "Remedial Action Report" prepared by ELM dated June 26. 2009. The report summarizes all investigative and remedial work performed on-site to date, including a summary of the Phase I and Phase II Site Investigations. The following is included in the report:Section 3 REMEDIATION1. Pre-demolition removal of ASTs, one 1,200-gallon lube oil UST, sediment from trenches and drains within the on-site structures and oil and sludges from the oil-water separators located on-site - Jan 2008.2. Removal of 2 oil-water separators and an adjacent UST during demolition from the D-boring area - July 2008.3. RegenOx injection program - Oct 3 - Nov 12, 2008.4. Effectiveness monitoring of soil and groundwater - Dec 2008.5. Re-installation and sampling of ELM-1R in the T-boring area - Jan 2009.6. Soil excavation and removal for construction purposes - Nov 2008 - Feb 20097. Installation of passive SSDS - Feb 20098. Installation of a 15-ml poly sheeting soil vapor barrier - Feb 2009.9. Capping of the site with impermeable surfaces and clean fill in landscaped area - Scheduled for Spring 2009.10 Qrtly GW monitoring - Ongoing.The report is uploaded to eDocs without the Attachments. - JAM7/21/09 Reviewed the Quarterly Groundwater Sampling Report submitted by ELM on July 1, 2009. On April 24, 2009, groundwater samples were collected from groundwater monitoring wells ART MW-2 and ART MW-3. ELM-MW-1R was found to be filled with sediment and could not be sampled and ELM-MW-5 was destroyed during construction activities. ELM-MW-4 contained 1.1 feet of free product and could not be sampled. Total VOC concentrations from ART-MW-2 and ART-MW-3 are 108ug/L and 46ug/L, respectively. Report uploaded to eDocs.I called Mimi Raygorodetsky at ELM today to discuss future work. Mimi said that on Friday, July 24, 2009, ELM will perform another round of groundwater sampling, collect a sample of the product for fingerprint analysis, and perform the first product recovery event. Product recovery will be performed weekly, thereafter. I also requested that at least 3 monitoring wells be installed. Two to replace the destroyed wells ELM-MW-1R and ELM-MW-5, and one to installed downgradient and across the street of ELM-MW-4 and ELM-MW-5. I also requested that an up-to-date groundwater flow direction be calculated.ELM will submit a work plan to reinstall the wells within 2 weeks. - JAM8/31/09 Reviewed the Spill Investigation and Remediation Work Plan submitted by ELM dated August 7, 2009 and submitted via email on August 18, 2009. ELM proposed gauging and bailing product from well ELMMW-4 on a weekly basis and to collect a sample of the product for fingerprint analysis. The first gauging and bailing event occurred on July21, 2009. A sample of the product was collected on that date as

STRUCTURAL DISPLAY CO., INC (Continued) **S103824757**

well.Additional work includes reinstalling monitoring wells ELMMW-1R and ELMMW-5 that were destroyed during construction of the new building. An off-site monitoring well will be installed down-gradient and across the street from ELMMW-4.I wrote a letter today approving the work plan with the following adjustments:1.Vacuum enhanced fluid recovery should be implemented on ELMMW-4.2.At least one additional monitoring well should be installed approximately 15 to 20 feet to the east of well ELMMW-4 to delineate the free product plume. If product is encountered in this well, another well should be installed further to the east.3.Soil sampling should be conducted during installation of the well across 43rd Avenue and the well to the east of well ELMMW-4. Soil should be continuously screened with a PID. Two (2) soil samples should be collected from each well for laboratory analysis: one sample from the soil interval with the highest PID reading, and another sample from the interval directly above the water table. If there are no elevated PID readings, only the sample from above the water table need be collected.The work plan and my approval letter are uploaded to eDocs. - JAM10/1/09 Received Quarterly Groundwater Monitoring Rpt for 3rd Qtr 2009 submitted by ELM via email on 9/30/09 and dated 8/28/09. GW samples were collected from wells ART MW-2 and ATR MW-3 on July 24, 2009. Wells ELM MW-1 and ELM MW-5 were not sampled because they were destroyed and well ELM MW-4 was not sampled because it contained 3.3 feet of free product. Sample results showed very minor levels of dissolved phase VOCs in ART MW-2 and ART MW-3. ELM states that there was an overall reduction in VOCs since RegenOx injection. Report with sample result tables is uploaded to eDocs.ELM has been monitoring the wells weekly for free product and, if free product is detected it is being hand bailed. On 10/1/09 I visited the site to observe the first vacuum enhanced fluid recovery event on well ELM MW-4. Additional wells will be drilled as per my letter dated 8/31/09. A summary report of all product gauging and recovery events will follow. - JAM10/16/09 Received updated weekly product recovery table submitted by ELM. On October 15, 2009, well ELM-MW-4 contained 0.22ft of free product, which was recovered using a bailer. The delineation wells are scheduled to be installed on Monday, October, 26. - JAM10/23/09 Received updated weekly product recovery table submitted by ELM. On October 22, 2009, well ELM-MW-4 contained 0.19ft of free product, which was recovered using a bailer. Delineation wells will be installed next week 10/26 through 10/28. - JAM10/28/09 Visited site today to observe install'n of 4 additional monitoring wells. At time of my visit, three wells were installed and none showed any signs of contamination. Next week all wells will be surveyed and sampled for dissolved phase contamination. - JAM12/2/09 Reviewed the Product Recovery Table submitted by ELM on 11/20/09 and 12/2/09. The last three recovery events are tabulated below:Date Prod. dpth DTW P.Thck Final DTW Prod Removed10/29/09 16.35 16.53 0.18 16.86 0.4 11/18/09 14.33 14.46 0.13 14.58 0.2 12/2/09 14.46 14.62 0.16 14.75 1.2 ELM will continue to visit the site to recover product weekly. A report will be submitted summarizing the installation of the additional monitoring wells. - JAM3/19/10 Reviewed Well Install'n and Quarterly Groundwater Sampling Rpt for 4th Qtr 2009 submitted by ERM, dated Dec. 17, 2009. On October 27 and 28, 2009, 2 new monitoring wells and 2 replacement wells were installed. Soil samples were collected from new wells only because soil data is already available for replacement wells. According to data, no VOCs or SVOCs were detected that exceeded SCOs in either of newly installed monitoring wells. Free product also was not observed in any of 4

STRUCTURAL DISPLAY CO., INC (Continued) **S103824757**

newly installed wells.Groundwater samples were collected from all accessible wells without product on November 4, 2009 (ELM MW-4 was not sampled because it contained free product). No VOCs or SVOCs were detected in groundwater samples from ELM MW-6 and ELM MW-7 exceeding NYSDEC TOGS. The other wells each contained several VOCs, with some VOC concentrations exceeding TOGS.On October 1, 2009, ERM performed one VEFR event on well ERM MW-4 and removed approx. 50 gallons of free product/water mixture. ERM recommends continuing to sample GW quarterly for at least 2 more quarters. Product continues to be bailed from ERM MW-4 on a weekly basis. Well Installation and Quarterly Groundwater Sampling Report is uploaded to eDocs. - JAM3/19/10 Received call from Mimi Raygorodetsky and Jesse Mausner at ERM. In Feb. 2010, approx. 1.5 feet of free product was measured in well ERM-MW-4. ERM plans to schedule another VEFR event. I advised ERM to install more wells and/or soil borings in close proximity to well ERM MW-4 to determine where product originated from. Due to heavy rain events, product may have been desorbed from soil column near well ERM MW-4. Recommendations for future work will be included in next quarterly monitoring rpt (to be submitted). - JAM4/28/10 Reviewed the Quarterly Monitoring Report submitted by ELM dated April 8, 2010 submitted via email on April 16, 2010. Groundwater samples were collected on February 3, 2010 and results continue to show a reduction of VOCs in ELM-MW-1R, ART-MW-2 and ART-MW-3. The report does not summarize free product gauging and recovery events since April 2009. The next sampling event is scheduled for May 2010. Report uploaded to eDocs.I issued an email today notifying the RP that product monitoring and recovery should be performed monthly and that DEC should receive monthly updates. I also requested that the data from the monthly events be summarized in the quarterly monitoring/sampling reports. Email uploaded to eDocs. - JAM4/29/10 Received Free Product Remdiation Scope of Work submitted by ELM on April 28, 2010 via email. Work plan proposes using Laser Induced Fluorescence / Ultraviolet Optical Scanning Tool (LIF/UVOST) to delineate free product plume around ELM-MW-4. LIF/UVOST will be advanced into subsurface using direct-push geoprobe and will obtain real time scan of subsurface. ELM proposes installing permanent monitoring wells where mobil phase product is detected.I issued an approval letter on April 28, 2010 with the following requirements:1. Each boring should be extended to a depth 5 feet below the water table or the extent feasible since bedrock is shallow in the area.2. At any location where residual or free phase petroleum contamination is encountered, a permanent monitoring well should be installed. At a minimum, one monitoring well should be installed between existing wells ELM-MW-4 and ELM-MW-73. During monitoring well installation, soil should be continuously screened with a PID. Soil samples should be collected from the soil interval with the highest PID reading, and another sample from the interval directly above the water table. If there are no PID readings but contamination was detected using UVOST, then a soil sample should be collected from depth intervals where UVOST detected contamination.The work plan and approval letter are uploaded to eDocs. - JAM5/7/10 Site Visit. LIF/UVOST investigation completed today with six borings advanced around ELM-MW-4. Free phase product was observed in four of the six borings around well ELM-MW-4. Three monitoring wells will be installed and soil and grounwater samples will be collected.Product is delineated toward the street. Product most likely extends beneath the building. A summary report will be submitted when soil and groundwater sample results are

STRUCTURAL DISPLAY CO., INC (Continued) **S103824757**

returned. -JAM6/8/10 Spoke to Emily from ELM today. All the wells were gauged this month and approx. 5 inches of product was contained in well ELM-MW-4. She will submit a letter documenting the gauging event and will include a submission date for the investigation summary report. - JAM03/01/11: This spill case transferred from J. Maisonave to J. Kolleeny. Reviewed LNAPL Remediation Rpt by ELM, dated 2/17/11 (in eDocs). Rpt presents product gauging data and GW sampling data, showing free product in well ELM-MW4 has been reduced to 0.08 ft; most notable dissolved-phase impact was in well ELM-MW-1R2, which had 100 ug/L of benzene in Oct. 2010 (up from 65 ug/L benzene in July 2010). Rpt requests spill closure. I sent letter (in eDocs) to Michael Del Cioppo, cc's to Dik Glass, Emily Guyer & Mimi Raygorodetsky, saying spill cannot yet be closed due to measurable free product and other impacts; required continued product recovery (suggested by vac truck), and quarterly GW sampling, until no measurable product in wells, at which point spill closure will be reconsidered. - J. Kolleeny08/23/11: On Aug. 5, 2011, spoke with Emily Guyer of ELM (consultant), discussed various approaches to product recovery and conditions for spill closure. She suggested use of absorbent socks to remove product from well MW-4, which has persistent small amounts of product (several inches). I agreed to give this a try, since she indicated that vac truck was not very effective and constant use would be cost prohibitive. I also requested GW sampling on at least semi-annual basis. On 8/15/11, received email from Ms. Guyer with attached memo (in eDocs) summarizing our discussion and proposing use of absorbent socks and semi-annual sampling as remedial approach moving forward, and stating that once sufficient data are collected, ELM will re-evaluate effectiveness of this approach. On 8/23/11, I sent email (in eDocs) to Michael Del Cioppo, cc's to Emily Guyer, Mimi Raygorodetsky & Pete Zimmerman of ELM, approving this proposal. - J. Kolleeny07/25/12: Received phone call from Mimi Raygorodetsky of ELM, stating that they've been following approved plan of absorbent socks/manual bailing of traces of product in well MW-4, and as of April 2012, there has been no LNAPL in well; they then performed a round of GW sampling and found very low VOC levels (below TOGS); she stated they will submit a letter rpt summarizing product recovery work, GW sampling results, and requesting spill closure. - JK08/08/12: Received email from Mimi R. of ELM, asking if I've had chance to review closure request rpt she sent over on 7/25/12. I responded that I never received rpt. She determined that because rpt pdf file, sent by email on 7/25/12, was "secured" (ELM does this for all their pdfs that have an electronic signature), DEC's servers would not accept email with attachment. She unsecured rpt and re-sent. Will review. - J. Kolleeny08/20/12: After review of ELM's Product Recovery Rpt and Request for Spill Closure dated 7/23 12 (in eDocs), I sent email to Mimi Raygorodetsky on 8/15/12 noting that rpt contains inconsistencies in text and graph regarding product thickness, in hundredths of inches vs. hundredths of feet. Mimi replied that my observation is correct; they will revise rpt and re-issue under cover name of Integral Consulting, which has taken over ELM. - J. Kolleeny09/05/12: On 9/4/12, received Revised Product Recovery Rpt and Request for Spill Closure by Integral Consulting, Inc., dated 8/27/12 (in eDocs). Rpt summarizes measurement and recovery of free product in well MW-4 since DEC approved use of absorbent socks to address product in that well, and results of round of GW sampling performed on 6/6-7/12. Rpt presents graph showing product thickness

STRUCTURAL DISPLAY CO., INC (Continued) **S103824757**

in inches from 7/26/11 through 5/21/12, with measurements fluctuating from about 2.5 to 4.5 inches until 4/1/12, after which product thickness decreased dramatically and then was non-detect for 4 events. Text states that 1.08 inches of product (i.e., 0.09 ft) were detected on 4/13/12, but that no measurable product has been detected in well for four separate events since 4/19/12. GW samples collected in June 2012 from 6 on-site and 4 off-site wells (including well MW-4) showed low levels of VOCs in several wells, up to about 70 ug/L total VOCs in ELM-MW-5R. These minor impacts appear to be adequately delineated by clean (or nearly clean) sentinel wells, indicating there is no off-site migration of contamination. Based on absence of measurable free product in MW-4 for 4 consecutive gauging events and minor, delineated residual dissolved GW impacts with no off-site migration, Integral requests spill closure. On 9/5/12, I closed spill case and sent spill closure letter (in eDocs) by email to Michael Del Cioppo, cc's to Mimi Raygorodetsky, James L'Esperance & Pete Zimmerman of Integral, advising in email that DEC should be notified when wells have been decommissioned and provided with documentation of this. - J. Kolleeny

Remarks: TESTED TANK. TANK FAILED.

Material:

Site ID:	164528
Operable Unit ID:	1074904
Operable Unit:	01
Material ID:	310729
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	164528
Spill Tank Test:	1546863
Tank Number:	Not reported
Tank Size:	10000
Test Method:	99
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Alternate Test per 613.5a2v

213
WNW
1/4-1/2
0.428 mi.
2262 ft.

INTERNATIONAL MASONRY INS
12-07 44TH AVE
LONG ISLAND CITY, NY

NY LTANKS **S105055142**
N/A

Relative:
Higher

Actual:
15 ft.

LTANKS:

Site ID:	197925
Spill Number/Closed Date:	0103153 / 3/31/2006
Spill Date:	6/21/2001
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	6/21/2001
CID:	323
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	6/21/2001
Spill Record Last Update:	3/31/2006
Spiller Name:	DENNIS HOLLOWAY
Spiller Company:	INTERNATIONAL MASONRY INS
Spiller Address:	12-07 44TH AV
Spiller City,St,Zip:	LONG ISLAND CITY, ZZ
Spiller County:	001
Spiller Contact:	DENNIS HOLLOWAY
Spiller Phone:	(718) 706-9139
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	164722
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO"12/30/02 TJDInternational Masonary Institute contacted to provide a summary of activities at site including complete analytical data from sampling event. Fax transmission with incomplete data had been received. Demeo left message with John Cozultini who will have the appropriate individual repond to NYSDEC request for addional information.1/2/02 TJDDennis Holaway (International Masonary Institute) called today in response to DEC request for additional information. A complete set of laboratory data faxed to DEC this morning. Lab analysis reveals chemical concentrations above TAGM. Remedial work is required.Tank is reportably a 2,500 gal UST buried inside building. No PBS registration is found for this address. Mr. Hollaway was provided contact information for (5) environmental contractors. A contractor will be selected and a work plan submitted.Based on 11/28/01 tank closure report - which indicated only SVOC contamination - and 10/5/01 DEC Region 2 telephone conference which requested soil borings per approved work plan, additional borings were advanced and analyzed and determined that fill across site placed during construction of building was contaminated with low level SVOC's. Case closed.

INTERNATIONAL MASONRY INS (Continued) **S105055142**

Remarks: Not reported

Material:
Site ID: 197925
Operable Unit ID: 839740
Operable Unit: 01
Material ID: 535248
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 197925
Spill Tank Test: 1526410
Tank Number: 1
Tank Size: 3000
Test Method: 03
Leak Rate: 0
Gross Fail: F
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

---

214 West 1/4-1/2 0.432 mi. 2279 ft.

ANDREA ELECTRONICS **NY LTANKS S102959964**
11-40 45TH DRIVE **NY MANIFEST N/A**
LONG ISLAND CITY, NY

Relative: Lower

Actual: 13 ft.

LTANKS:
Site ID: 179039
Spill Number/Closed Date: 9709895 / 12/17/2002
Spill Date: 11/25/1997
Spill Cause: Tank Test Failure
Spill Source: Non Major Facility > 1,100 gal
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 4101
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 11/25/1997
CID: 282
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0

ANDREA ELECTRONICS (Continued) **S102959964**

Date Entered In Computer: 11/25/1997
Spill Record Last Update: 3/4/2003
Spiller Name: ANDREW FALINO
Spiller Company: ANDREA ELECTRONICS
Spiller Address: 11-40 45TH DRIVE
Spiller City,St,Zip: LONG ISLAND CITY, NY 11101-
Spiller County: 001
Spiller Contact: ANDREW FALINO
Spiller Phone: (718) 729-8500
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 150284
DEC Memo: Not reported
Remarks: Anthony Sigona from DEC was on the scene also.tank failed the test he did not get the name of the electrical manufacturing factory PBS number is 2-195383

Material:
Site ID: 179039
Operable Unit ID: 1052939
Operable Unit: 01
Material ID: 328224
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 179039
Spill Tank Test: 1545485
Tank Number: 1
Tank Size: 10000
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

NY MANIFEST:
EPA ID: NYD001360692
Country: USA
Mailing Name: ANDREA RADIO
Mailing Contact: ANDREA RADIO
Mailing Address: 11-40 45TH ROAD
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11104
Mailing Zip4: Not reported

ANDREA ELECTRONICS (Continued) **S102959964**

Mailing Country: USA
Mailing Phone: 718-729-8500

NY MANIFEST:
No Manifest Records Available

---

215 West 1/4-1/2 0.437 mi. 2307 ft.

11-15 45TH AVENUE
11-15 45TH AVENUE
LONG ISLAND CITY, NY

NY LTANKS **S102672507**
N/A

Relative: Lower

Actual: 12 ft.

LTANKS:

Site ID:	265495
Spill Number/Closed Date:	9402499 / 5/20/1994
Spill Date:	5/20/1994
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	5/20/1994
Cleanup Meets Standard:	True
SWIS:	4101
Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	5/20/1994
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	5/25/1994
Spill Record Last Update:	9/30/2004
Spiller Name:	Not reported
Spiller Company:	GOTHAM PETRO
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	216332
DEC Memo:	Not reported
Remarks:	SPILL CONTAINED ON SIDEWALK - CLEAN UP CREW ON SCENE (GOTHAM).

Material:

Site ID:	265495
Operable Unit ID:	996297
Operable Unit:	01
Material ID:	382692
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum

11-15 45TH AVENUE (Continued) **S102672507**

Quantity: -5
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

216
North
1/4-1/2
0.437 mi.
2308 ft.

Relative:
Higher

Actual:
27 ft.

GULF MOKIN GAS **NY LTANKS S106124280**
23-01 41ST AVE **NY Spills N/A**
LONG ISLAND CITY, NY

LTANKS:
Site ID: 237638
Spill Number/Closed Date: 0308076 / 1/7/2004
Spill Date: 10/30/2003
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station
Spill Class: Known release that creates potential for fire or hazard. (Highly Improbable)
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 4101
Investigator: KMFOLEY
Referred To: Not reported
Reported to Dept: 10/30/2003
CID: 257
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 10/30/2003
Spill Record Last Update: 2/6/2004
Spiller Name: Not reported
Spiller Company: CUMBERLAND FARMS
Spiller Address: 777 DEDHAM ST
Spiller City,St,Zip: CANTON, MA 02021-
Spiller County: 001
Spiller Contact: BRIAN BERKLE
Spiller Phone: (610) 278-7203
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 195731
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "K FOLEY"12/15/03 Letter addressed to Sigona from Environmental Systems Group. On 10/30/03, Crompco conducted precision test on tanks. One 4000gal diesel UST failed the test. Energy Storage Systems reviewed the test data and suggested the test technician failed to plug the air eliminator on the pumps and therefore the tanks failed. On 12/9/03, Crompco retested the tanks and plugged the air eliminator and the tank passed.12/19/03Spoke to Andy at Energy Storage systems.As per Sigona’s recommendation, he will submit a report

GULF MOKIN GAS (Continued) **S106124280**

summarizing the first and second testing episodes. Rommel12/23/03
Received letter from Mort Turoff at Energy Storage systems
summarizing first and second tests. Diesel tank passed on 12/9/03
retest. Results on file. (KMF)1/9/04 Sent NFA. (KMF)

Remarks: liquid level failure

Material:

Site ID:	237638
Operable Unit ID:	874384
Operable Unit:	01
Material ID:	568462
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	406141
Spill Number/Closed Date:	0808735 / 8/28/2009
Spill Date:	11/3/2008
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	11/3/2008
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	11/3/2008
Spill Record Last Update:	8/28/2009
Spiller Name:	TJ OCONNOR
Spiller Company:	GULF STATION
Spiller Address:	23-01 41ST AVE
Spiller City,St,Zip:	LONG ISLAND CITY, NY
Spiller County:	999
Spiller Contact:	TJ OCONNOR
Spiller Phone:	(516) 678-5115
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	195731

GULF MOKIN GAS (Continued) **S106124280**

DEC Memo: TTF1/15/09. J.Krimgold reviewed the letter-report submitted by Energy Fueling systems Corp and dated 12/22/08. According to the information provided in this letter, a 2000 gal tank failed the test due to a damaged (cut)vent pipe. The failed pipe was abbendoned in place and new pipe run was installed. Tank with pipe was retested and passed the test. NFA.
Remarks: TANK TEST FAILURE ON A 2000 GALLON UST. UNK IF ANY PRODUCT WAS SPILLED.

Material:
Site ID: 406141
Operable Unit ID: 1162749
Operable Unit: 01
Material ID: 2154029
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 406141
Spill Tank Test: 2486875
Tank Number: 1
Tank Size: 2000
Test Method: 21
Leak Rate: 0
Gross Fail: Not reported
Modified By: JMKRIMGO
Last Modified: 1/15/2009
Test Method: Horner EZY3/EZY3 Locator Plus

SPILLS:
Facility ID: 9611967
DER Facility ID: 195731
Facility Type: ER
Site ID: 298938
DEC Region: 2
Spill Date: 1/3/1997
Spill Number/Closed Date: 9611967 / 1/10/1997
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 4101
Investigator: KATZ
Referred To: Not reported
Reported to Dept: 1/3/1997
CID: 267
Water Affected: Not reported
Spill Source: Tank Truck
Spill Notifier: Fire Department

GULF MOKIN GAS (Continued) **S106124280**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1/3/1997
Spill Record Last Update:	9/23/2009
Spiller Name:	MR GOODE
Spiller Company:	C DAVISON TRUCKING
Spiller Address:	2824 AVE X
Spiller City,St,Zip:	BROOKLYN, NY 11235-
Spiller Company:	001
Contact Name:	FF REGAN
Contact Phone:	(718) 476-6288
DEC Memo:	Not reported
Remarks:	tank truck making a delivery to gas station and spilled 25 gallonsdue to air in the line gasoline is now in the sewer systemreq dec call back ff regan at 917-769-0483

Material:

Site ID:	298938
Operable Unit ID:	1039826
Operable Unit:	01
Material ID:	340614
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

217
SSW
1/4-1/2
0.453 mi.
2391 ft.

Relative:
Lower

Actual:
9 ft.

SPILL NUMBER 0208486 **NY LTANKS** **S105997319**
23-30 50TH AVE **N/A**
LONG ISLAND CITY, NY

LTANKS:

Site ID:	268804
Spill Number/Closed Date:	0208486 / 11/17/2003
Spill Date:	11/15/2002
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	11/15/2002

SPILL NUMBER 0208486 (Continued) **S105997319**

CID:	322
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	11/15/2002
Spill Record Last Update:	11/17/2003
Spiller Name:	ANTHONY VERDERAM
Spiller Company:	Not reported
Spiller Address:	23-30 50TH AVE
Spiller City,St,Zip:	LONG ISLAND CITY, NY
Spiller County:	001
Spiller Contact:	ANTHONY VERDERAM
Spiller Phone:	(718) 786-1100
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	218966
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "VOUGHT"Sent tank test failure letter to Varderame. 11/15/2002 ARS11/14/2003-Vought-Reviewed report dated 6/26/03 from Verderame Realty (Bruce Bauer 718-786-1100). Site will no longer be using oil and will be converting to gas. Closure of a 2000-gallon #2 fuel oil UST and collection of post excavatin endpoint samples by Bluestone Environmental (Andrew Cozzi 732-469-5188). "The UST excavation base was at approximately 8 to 8.5 feet below the concrete floor". "The soil in the excavation was a fill that consisted of dark brown sand with construction debris such as bricks and pieces of concrete". Five soil samples were submitted for analyses for 8260/8270. Soil analyticals show two 1,3,5-trimethylbenzene exceedances up to 9110ppb, benzo(a)anthracene up to 1010ppb, benzo(a)pyrene up to 631ppb, benzo(b)fluoranthene up to 1110ppb, benzo(k)fluoranthene up to 579ppb, and chrysene up to 1210ppb. These exceedances are attributable to fill material. Spill closed by Vought after conference with DEC Rommel.
Remarks:	tank test failure - it will be cleaned and retested next week

Material:

Site ID:	268804
Operable Unit ID:	859901
Operable Unit:	01
Material ID:	565791
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	268804
Spill Tank Test:	1527719

SPILL NUMBER 0208486 (Continued) **S105997319**

Tank Number:	1
Tank Size:	2500
Test Method:	03
Leak Rate:	0
Gross Fail:	F
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Horner EZ Check I or II

218
ESE
1/4-1/2
0.453 mi.
2391 ft.

Relative:
Higher

Actual:
31 ft.

32-32 QUEENS BLVD/SUNOCO **NY LTANKS** **S100145562**
32-32 QUEENS BLVD **N/A**
NEW YORK CITY, NY

LTANKS:

Site ID:	310058
Spill Number/Closed Date:	8905358 / Not Reported
Spill Date:	8/30/1989
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station
Spill Class:	Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	4/9/2004
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	RJFENG
Referred To:	OFFSITE IWP AND A RAWP DUE 1/13/2012
Reported to Dept:	8/30/1989
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	1
Date Entered In Computer:	8/31/1989
Spill Record Last Update:	7/26/2013
Spiller Name:	Not reported
Spiller Company:	SUNOCO AA
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	250287
DEC Memo:	3/94: MW-4 had a sheen of product. MW-1 had 7500 ppb, MW-2 had 9600 ppb and MW-3 had 350 ppb of benzene.8/94: Installed MW-5,6 & 7. MW-4 had 0.19 ft of LPH. Depth to water 13 ft. The SVE system is operable and manifolded to MW-2,3 & 4. MW-1 had 3000 ppb, MW-2 had 5200 ppb, MW-3 had 360 ppb, MW-5 had 1400 ppb, MW-6 had 590 ppb and MW-7 had 24 ppb benzene. Sunoco will investigate and submit current tank test results. 12/10/2003 Reassigned from Tipple to Sun.02/03/2004-Sun-File Update by Sun:Quarterly Monitoring and Sampling Report (October through December 2003), by EnviroTrac (Anthony Fiorentine,

32-32 QUEENS BLVD/SUNOCO (Continued) **S100145562**

631-471-1500): On 11/08/2003, liquid phase hydrocarbons (LPH) were detected in MW-4 at a thickness of 0.20 feet (ft.). The depth to water ranged from 22.78 ft. (MW-6) to 26.00 ft. (MW-4) below the surface on 11/8/2003. Six (6) wells (MW-1,2, 3, 5, 6 & 7) were sampled on 11/8/2003. BTEX concentrations ranged from not detected (ND) in 3 of the 7 wells to 58,000 micrograms per liter (ug/l) (MW-2).MTBE concentrations ranged from ND (MW-3) to 3,800 ug/l (MW-7). On 11/8/2003 and 12/21/2003, a three percent Biosolve surfactant and water solution was injected into MW-4. MW-4 was then han surged with a surge block and groundwater was removed from a down-gradient well (MW-7) with a submersible pump. LPH was not detected during the December 2003 short term remediation event (STRE).03/11/2004-Sun-File Update by Sun: On 03/10/2004, Sun sent a letter and Stipulation Agreement to Russell Hammond of Sunoco requiring complete delineation of soil and groundwater contamination, submittal of an Investigation Summary Report followed by a Remedial Action Plan. The Department set a deadline of March 31, 2004 for signing the Stipulation Agreement by the Respondent.10/31/05: Project reassigned from Sun to Andersen. Enhanced fluid recovery and Biosolve application are being utilized in two hotspots, MW2 and MW4.12/8/05: December 8 meeting between Sunoco, DEC, and EnviroTrac. Biosolve remediation is not very successful. EnviroTrac and Sunoco think that source may be present and plan to do soil borings to identify source. Soil is likely very heterogenous. Site is now a pay commuter parking lot, so work can only be done on weekends.1/4/06: Reviewed the quarterly report dated January 2006. Six wells sampled on November 20, 2005. Trace amounts of LPH in MW-4. Max BTEX 28,300 (MW-2) and 560 ppb (MW-2). Biosolve last used in August 2005. 5/3/06: Reviewed the first quarterly 2006 report. Wells sampled on 1/21/06. LPH is present in MW 4 at a depth of 0.25 ft. Max BTEX 22,900 in MW2. Max MTBE 91 ppb in MW7. Sent RAP required letter, due 7/3/06.8/18/06: Meeting on 8/17/06 with Sunoco, EAR, and NYSDEC. RAP submitted. Regenox will be used. Three monthly Regenox installations will be completed. Regenox will be injected into twelve temporary borings, with injection span the vertical interval 15 to 35 feet below grade. Monitoring wells will be gauged and sampled monthly during Regenox application. RAP approved.10/20/06: First mobilization to drill borings for Regenox application will occur on 10/21/06 8am-4pm.11/9/06: Second mobilization for Regenox application will occur on 11/11/06.12/18/06: Sent email to Jamie Brown of EAR to followup on status of next quarterly report. Received email from Jamie Brown:"The next report will be completed and submitted to you mid - January 2007. Please let me know if you have any other questions."2/13/07: Emailed Jamie Brown to followup on the status of the next quarterly report.2/20/07: Reviewed update report. Regenox in use. Wells sampled on 12/23/06. Max BTEX 58,900 ppb (MW4), max MTBE 220 ppb (MW7). LPH in MW2 at depth of 0.48 ppb. 3/23/07: Meeting on 3/22/07 with Sunoco, NYSDEC, and EnviroTrac. LPH appeared last quarter because the Regenox mobilized contaminants. The second phase of Regenox application may be scheduled for April 2007.4/13/07: Regenox application scheduled for 4/14/07.6/11/07: Received update report. Wells sampled on 3/24/07. Max BTEX 37,400 ppb (MW4), max MTBE 120 ppb (MW7). LPH in MW2 at a depth of 0.29 ft. Product recovered from MW2 and an absorbent sock put in well. Overall decrease in contaminant concentration. 10/12/07: Emailed Russell Hammond regarding overdue report.10/16/07: Received email from Russell Hammond. Report will be submitted by the end of this week.3/18/08:

32-32 QUEENS BLVD/SUNOCO (Continued) **S100145562**

Reviewed October 2007 - December 2007 Project Status Report. Max BTEX 47,100 ppb (MW4). Max MTBE 140 ppb (MW2). When will the next phase of Regenox application occur?3/19/08: Received email from Karen Waryas (Waryas@ENVIRO-ASMNT.COM):"Phase 2 of the Regenox application at SUN-LIC32-32 occurred in April andMay of 2007. It was mentioned in the June 2007 PSR, but regretfully wasnot put into the site history section of the September or December 2007PSRs. I apologize for this oversight, and it will be remedied forfuture submissions. I put in an inquiry with my supervisor today as towhen the third phase is expected to occur and will let you know as soonas I hear any information."5/15/08 - Carlson: Reviewed January - March 2008 Project Status Report. Wells sampled on 3/22/08. Maximum BTEX concentration 23,600 ppb (MW2). Maximum MTBE concentration 74 ppb (MW2). Geochemical parameters are being monitored to evaluate progress of Regenox. When will third phase of Regenox occur?9/4/08 - Carlson: Reviewed April - June 2008 Project Status Report. Wells sampled on 6/28/08. Maximum BTEX concentration 31,800 ppb (MW2). Maximum MTBE concentration 110 ppb (MW7). General increase in contaminant concentrations. When will third phase on Regenox application occur?10/8/08 - Carlson: Meeting with Russell Hammond of Sunoco and Karen Waryas of EAR. Regenox won't be used again. Workplan for soil borings due by 10/30/08. A new RAP will be required afterwards. 11/5/08 - Carlson: Received email with Subsurface Summary letter. Email stated that a workplan will be submitted in two weeks.12/22/08 - Carlson: Reviewed July 2008 - September 2008 Project Status Report. Wells sampled on 9/20/08. Maximum BTEX concentration 29,700 ppb (MW2). No mention of overdue workplan in report. Emailed Karen to followup on workplan submittal.12/29/08 - Carlson: Received email from Karen. Workplan will be submitted when Russell Hammond gets back from vacation.1/8/09 - Carlson: Approved investigation workplan for installation of three soil borings.1/28/09 - Carlson: Reviewed September 2008 - December 2008 Update Report. Wells sampled on 12/20/08. Maximum BTEX concentration 37,620 ppb (MW4). On-site borings will be completed.1/29/09 - Carlson: Meeting with Sunoco and Envirotrac.4/5/09 - Carlson: Received investigation letter-report dated April 8, 2009. Three soil borings installed. High soil impact in all borings. A workplan for additional soil delineation will be submitted by may 8th.5/22/09 - Carlson: Reviewed update report. Wells sampled on 3/28/09. Maximum BTEX concentration 37,700 ppb (MW4). Maximum MTBE concentration 64 ppb (MW2). Workplan for additional delineation overdue.6/1/09 - Carlson: Meeting held with Sunoco and EAR.6/5/09 - Carlson: Reviewed work plan dated 5/29/09. Five soil borings proposed. Sent email requiring revision workplan with 1) deeper minimum boring depth to account for smear zone and 2) continuous sampling of entire boring for all on-site borings except SB1. Revised work plan due in 30 days.8/6/09 - Carlson: Approved revised work plan. Investigation Report due in 90 days.10/6/09 - Carlson: Reviewed update report. Wells sampled on June 27, 2009. High dissolved concentrations in MW2 and MW4. No update on work plan implementation provided.12/3/09 - Carlson: Reviewed update report. Wells sampled on 9/19/09. Trace LNAPL in MW1. Maximum BTEX concentration 27,800 ppb (MW2). Investigation report overdue.12/8/2009 - Carlson: Meeting with Sunoco. Upgradient source?, access issue on upgradient property.3/18/2010 - Carlson: Received notification. Field work scheduled for 3/20/2010.3/19/2010 - Carlson: Reviewed October 2009 - December 2009 Quarterly Update Report. LNAPL sheen in MW1 in October 2009. However, low dissolved concentrations

32-32 QUEENS BLVD/SUNOCO (Continued) **S100145562**

in MW1 in December 2009. Field work cancelled, will probably be rescheduled for next Saturday.4/7/2010 - Carlson: Received notification - field work scheduled for 4/7 and 4/10.7/2/2010 - Carlson: Reviewed January - March 2010 update report and RIR. SB4 - SB 6 installed. Soil and gw impact in SB4. Three more borings will be installed, as per 7/17/09 work plan.9/9/2010 - Carlson: Reviewed April - June 2010 Quarterly Report. SB- 7 - 9 installed. Soil impact in SB- 4, 7, 8, 9. Issued letter requiring work plan for installation of three monitoring wells at SB-4, SB-7, and to the south of SB-9, and one soil boring adjacent to MW1. Due 10/11/2010.1/31/11 - Obligado - I reviewed an investigation workplan. The workplan didn't propose a well at SB7. I emailed a letter to Jaime Brown and Russel hammond requiring revised work plan with well at SB7. Due within 15 days.3/30/11 - Obligado - I reviewed a revised work plan which incorporated the changes I requested. Sent approval letter.11/28/11 - Carlson: Reviewed 2nd and 3rd Quarter 2011 Update Reports. MW8-10 installed. Groundwater impact in all three new monitoring wells. 11/30/11 - Carlson: Issued letter requiring an off-site delineation work plan and a remedial action plan by 1/13/2012.2/10/2012 - Carlson: Reviewed December 2011 update report. Delineation workplan and RAWP to be submitted.1/10/2013 - Reviewed 1Q2012 dated 4/2012, 2Q2012 dated 7/2012 and 3Q2012 dated 10/2012. DTW 22.57 (MW-7) to 28.44 (MW-8) on 9/15/2012. MW-6, 30 BTEX, 1.2 MTBE. MW-2, 25,100 BTEX, less than 140 MTBE. MW-9, 34,030 BTEX, less than 400 MTBE. MW-4, 18,399 BTEX, less than 250 MTBE. MW-8, 798 BTEX, less than 76 MTBE. MW-7, 2,790 BTEX, less than 100 MTBE. MW-1, 18.1 BTEX, less than 13 MTBE. MW-3, 10.3 BTEX, less than 21 MTBE. MW-10, 15,740 BTEX, less than 93 MTBE. 4/5/2013 - 4Q2012, 1/9/2013, by CGE. Groundwater sampled on 12/15/2012. DTW 22.87 (MW-7) to 28.62 (MW-8). NO LNAPL. MW-6, 96 BTEX. MW-9, 27,650 BTEX, less than 190 MTBE. MW-4, 23,210 BTEX, less than 280 MTBE. MW-8, 1,851 BTEX, less than 160 MTBE. MW-2, 24,220 BTEX, less than 62 MTBE. MW-7, 2,040 BTEX, 31 MTBE. MW-1, 22.4 BTEX, less than 9.0 MTBE. MW-10, 15,960 BTEX,, less than 150 MTBE.7/26/2013 - 1Q2013, 4/2013, by CGE. The monitoring was done on 3/23/2013. DTW 22.81 (MW-7) to 28.77 (MW-8). NO LNAPL. MW-6, 170 BTEX, 6.1 MTBE. MW-2, 21,780 BTEX, <76 MTBE. MW-9, 35,130 BTEX, <290 MTBE. MW-4, 22,684 BTEX, <270 MTBE. MW-7, 1,870 BTEX, <42 MTBE. MW-10, 10,440 BTEX, <110 MTBE.

Remarks: (5) 550 GALLON TANKS FAILED PETRO TITE WITH A LEAK RATE OF 0.737GPH, WILL EXCAVATE & TEST (5) MORE TANKS ON 8/31/89.

Material:

Site ID:	310058
Operable Unit ID:	930572
Operable Unit:	01
Material ID:	445794
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

32-32 QUEENS BLVD/SUNOCO (Continued) **S100145562**

Tank Test:

Site ID:	310058
Spill Tank Test:	1535939
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

219
NW
1/4-1/2
0.455 mi.
2402 ft.

MONARCH CONSTUCTION **NY LTANKS** **S102673327**
11-17 43RD AVE **N/A**
LONG ISLAND CITY, NY

Relative:
Higher

Actual:
17 ft.

LTANKS:

Site ID:	113903
Spill Number/Closed Date:	9516355 / 3/20/1996
Spill Date:	3/20/1996
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	3/20/1996
CID:	349
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	3/20/1996
Spill Record Last Update:	4/1/1996
Spiller Name:	FRANK ODONNELL
Spiller Company:	BAERENKLAU OIL CO
Spiller Address:	740 JAMAICA AVE
Spiller City,St,Zip:	BROOKLYN, NY 11208-
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	99380
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KRIMGOLD"
Remarks:	on pavement only - cleaned up

MONARCH CONSTUCTION (Continued) **S102673327**

Material:
Site ID: 113903
Operable Unit ID: 1027324
Operable Unit: 01
Material ID: 352872
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: Yes
Resource Affected: Not reported
Oxygenate: False

Tank Test:

AP220 **SWINGSTELL, LLC** **NY UST** **U000407641**
East **32-00 SKILLMAN AVENUE** **NY HIST UST** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101** **NY AST**
0.460 mi. **NY BROWNFIELDS**
2428 ft. **Site 1 of 4 in cluster AP**

Relative:
Higher

Actual:
34 ft.

UST:
Id/Status: 2-032891 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 2018/09/29
UTM X: 590061.99912000005
UTM Y: 4511134.5334999999
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 252
Affiliation Type: Facility Owner
Company Name: SWINGSTELL, LLC
Contact Type: PERMIT COORD.
Contact Name: KATINA V. VAZQUEZ
Address1: 156 WILLIAM ST., 10TH FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10038
Country Code: 001
Phone: (212) 406-0030
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 8/16/2013

Site Id: 252
Affiliation Type: On-Site Operator
Company Name: SWINGSTELL, LLC
Contact Type: Not reported
Contact Name: SMAJLIE SEDANOVIC

SWINGSTELL, LLC (Continued) **U000407641**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 335-2580
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	8/16/2013

Site Id:	252
Affiliation Type:	Emergency Contact
Company Name:	SWINGSTELL, LLC
Contact Type:	Not reported
Contact Name:	SMAJLIE SEDANOVIC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 335-2580
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	8/16/2013

Site Id:	252
Affiliation Type:	Mail Contact
Company Name:	STELLAR MANAGEMENT
Contact Type:	Not reported
Contact Name:	KATINA V. VAZQUEZ
Address1:	156 WILLIAM STREET
Address2:	10TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 843-3783
EMail:	KVAZQUEZ@STELLARMANAGEMENT.COM
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	10/21/2013

Tank Info:

Tank Number:	0001
Tank ID:	27133
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	20000
Install Date:	Not reported
Date Tank Closed:	05/08/2008
Registered:	True
Tank Location:	Underground

SWINGSTELL, LLC (Continued) **U000407641**

Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	09/03/2003
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	dxliving
Last Modified:	07/02/2008

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None

HIST UST:

PBS Number:	2-032891
SPDES Number:	Not reported
Emergency Contact:	WILTON ATKINS
Emergency Telephone:	(718) 729-9600
Operator:	G. LOVETT
Operator Telephone:	(718) 729-9600
Owner Name:	ACCO USA,INC.
Owner Address:	32-00 SKILLMAN AVE
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Owner Telephone:	(718) 729-9600
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	ACCO USA,INC.
Mailing Address:	32-00 SKILLMAN AVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	LONG ISLAND CITY, NY 11101
Mailing Contact:	MR. WILTON ATKINS
Mailing Telephone:	(718) 729-9600
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	32000 SKILLMAN AVE
SWIS ID:	6301
Old PBS Number:	Not reported
Facility Type:	MANUFACTURING
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	10/29/1997
Expiration Date:	10/23/2002

SWINGSTELL, LLC (Continued) **U000407641**

Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	20000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City:	01
Region:	2
Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (gals):	20000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	11/01/1992
Next Test Date:	11/01/1997
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-032891
Program Type:	PBS
UTM X:	590061.99912000005
UTM Y:	4511134.5334999999
Expiration Date:	2018/09/29
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	252
Affiliation Type:	Facility Owner
Company Name:	SWINGSTELL, LLC
Contact Type:	PERMIT COORD.
Contact Name:	KATINA V. VAZQUEZ

SWINGSTELL, LLC (Continued) **U000407641**

Address1:	156 WILLIAM ST., 10TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 406-0030
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	8/16/2013

Site Id:	252
Affiliation Type:	On-Site Operator
Company Name:	SWINGSTELL, LLC
Contact Type:	Not reported
Contact Name:	SMAJLIE SEDANOVIC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 335-2580
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	8/16/2013

Site Id:	252
Affiliation Type:	Emergency Contact
Company Name:	SWINGSTELL, LLC
Contact Type:	Not reported
Contact Name:	SMAJLIE SEDANOVIC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 335-2580
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	8/16/2013

Site Id:	252
Affiliation Type:	Mail Contact
Company Name:	STELLAR MANAGEMENT
Contact Type:	Not reported
Contact Name:	KATINA V. VAZQUEZ
Address1:	156 WILLIAM STREET
Address2:	10TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001

SWINGSTELL, LLC (Continued) **U000407641**

Phone:	(212) 843-3783
EMail:	KVAZQUEZ@STELLARMANAGEMENT.COM
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	10/21/2013

Tank Info:

Tank Number:	0002
Tank Id:	223944
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/2008
Capacity Gallons:	15000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	08/19/2013
Material Name:	#6 Fuel Oil (On-Site Consumption)

BROWNFIELDS:

Program:	BCP
Site Code:	57873
Site Description:	The site is located in an urban area of Queens Co. and is surrounded by mixed industrial and residential uses. The site facility occupies an entire city block. The sites contamination resulted from the release of lubricating oils, paint thinners, solvents and related contaminated materials generated and used during the manufacturing process. Volunteer decided to not transition to Brownfield Cleanup Program, and the project remains in the Voluntary Cleanup Program. See Site #V00331.
Env Problem:	Not reported
Health Problem:	Not reported

AP221 **32-00 SKILLMAN AVE** **NY LTANKS** **S105999143**
East **32-00 SKILLMAN AVE** **N/A**
1/4-1/2 **QUEENS, NY**
0.460 mi.
2428 ft. **Site 2 of 4 in cluster AP**

Relative:
Higher

Actual:
34 ft.

LTANKS:

Site ID:	72446
Spill Number/Closed Date:	0302379 / 7/29/2005
Spill Date:	6/5/2003
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	LNKLAAS
Referred To:	Not reported
Reported to Dept:	6/5/2003
CID:	405
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	6/5/2003
Spill Record Last Update:	7/29/2005
Spiller Name:	EVILEN
Spiller Company:	Not reported
Spiller Address:	32-00 SKILLMAN AVE
Spiller City,St,Zip:	QUEENS, NY
Spiller County:	001
Spiller Contact:	EVILEN
Spiller Phone:	(212) 843-3751
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	68380
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE"June 29,04 letter sent by Tipple07/28/05 Tank was cleaned, retested, and passed 09/25/03. No sign of release. Closed. LNK.
Remarks:	tank will be cleaned and then retest the lines

Material:

Site ID:	72446
Operable Unit ID:	869214
Operable Unit:	01
Material ID:	506858
Material Code:	0002A
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

32-00 SKILLMAN AVE (Continued) **S105999143**

Tank Test:

AP222 **CLOSED-LACKOF RECENT INFO** **NY LTANKS** **S100494133**
East **32-00 SKILLMAN AVE** **NY Spills** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY** **NY VCP**
0.460 mi.
2428 ft. **Site 3 of 4 in cluster AP**

Relative:
Higher

Actual:
34 ft.

LTANKS:

Site ID:	221004
Spill Number/Closed Date:	9207976 / 3/6/2003
Spill Date:	10/9/1992
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	10/9/1992
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	10/16/1992
Spill Record Last Update:	3/6/2003
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	307503
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ADMIN.CLOSED"03/06/2003- Closed Due To The Nature / Extent Of The Spill Report
Remarks:	SUSPECT PLUMBING LEAKS,EIR.CLOSED DUE TO LACK OF ANY RECENT INFO-DOES NOT MEET ANY CLEAN UP REQUIREMENTS.

Material:

Site ID:	221004
Operable Unit ID:	971614
Operable Unit:	01
Material ID:	408582
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum

CLOSED-LACKOF RECENT INFO (Continued) **S100494133**

Quantity: -1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 221004
Spill Tank Test: 1540694
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

SPILLS:
Facility ID: 0511334
DER Facility ID: 307503
Facility Type: ER
Site ID: 357465
DEC Region: 2
Spill Date: 12/29/2005
Spill Number/Closed Date: 0511334 / 8/11/2008
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 4101
Investigator: rmpiper
Referred To: Not reported
Reported to Dept: 12/29/2005
CID: 408
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 12/29/2005
Spill Record Last Update: 8/11/2008
Spiller Name: ERIC KOVICH
Spiller Company: INDUSTRIAL FACILITY
Spiller Address: 32-00 SKILLMAN AVE
Spiller City,St,Zip: LOND ISLAND CITY, NY
Spiller Company: 001
Contact Name: ERIC KOVICH
Contact Phone: (610) 458-1077 101
DEC Memo: Sangesland did a search and could not find an open spill on this site.Why were they doing quarterly monitoring on the site? Is there an old spill number with a different address?05/17/06-Vought-Spill

CLOSED-LACKOF RECENT INFO (Continued) **S100494133**

transferred from DEC Vought to DEC Piper as per DEC Austin.2/26/07- DEC Piper left message at GES requesting callback and info.5/7/07- DECP iper receoved fax from GES stating oil dicovery is separate fro mPerc cont. There is a 20K #2 oil tank adjacent to the MW. It is believed that oil was pumped in from delivery due to wrong fill. Oil has reoccured in well. CSL sent to Mgmt. Agent.5/10/07- DECP iper spoke w. owner. He informed me there is no way oil was delivered to MW. In that case lines or tank may be leaking. He will test tank and lines and perform subsurface investigation.7/20/07- DEC Piper recieved tank test results. Tank failed Inspection revealed a hole on top of tank. Samples were collected thrpough bottom of tank though are clean of VOC and slight SVOCs. 2/3/08- DEC Piper spoke w. Don Carlo Env. Borings were completed around tank. and along street. Street samples were clean though boring made by others showed contamination. Adjacent boring were clean. Piper instructed Danny Sing to have proposal generated to clean and inspect tank and perform borings though bottom.4/16/08- DEC Piper - I met Don Carlo, Danny Sing and Ted Yen on site. I explained to them that product was discovered in the mw-11 adjacent ot the fill. The tank failed a tightness test and samples were collected from the ends of the tank. Further investigation is needed. Two borings down to groundwater will be completed adjacent to fill, and three boring will be conducted through the bottom of the tank. A third boring and gw sample will be collected in the boiler rooom which is downgradient of the tank.I recieved additional boring results. Soil and groundwater were below tagm. No free product was observed. Tank was slurriyed after inspection. Based on work to date, this spill is closed. See e--docs if warranted.

Remarks: CALLER HAS FOUND OIL FLOATING IN TOP OF THE WELLS DURING A QUARTERLY SAMPLING EVENT. oNE WELL WAS AFFECTED AND IS NEAR THE BOILER ROOM OF THE BUILDING. UNKNOWN AS TO HOW THE PRODUCT GOT INTO THE WELL AND SMELLS LIKE A FUEL OIL MATERIAL. HAS NOT BEEN EXCATED IT YET.

Material:

Site ID:	357465
Operable Unit ID:	1114741
Operable Unit:	01
Material ID:	2104803
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

VCP:

Program Type:	VCP
Site Code:	57579
HW Code:	V00331
Site Class:	A
SWIS:	4101

CLOSED-LACKOF RECENT INFO (Continued) **S100494133**

Region: 2
Town: New York City
Acres: 1.800
Date Record Added: 11/30/2000
Date Record Updated: 10/10/2012
Updated By: JHOCONNE
Site Description: Location:The Site is located in an urban area of Long Island City, Queens at 32-00 Skillman Avenue and is surrounded by mixed commercial, industrial and residential uses. The former ACCO Brands, Inc. (ACCO) facility is bounded by Skillman Avenue and the Sunnyside Rail Yard to the north; 32nd Place to the east; Queens Blvd. to the south; and Van Dam Street to the west. Surrounding land uses include multi-family residential properties, community and educational institutions, and various commercial, industrial, and retail uses.Site Features:The Site is approximately 1.8 acres in size and the former ACCO facility occupies the entire city block.Current Zoning/Use(s):The site was formerly owned by ACCO Brands Inc., which was a subsidiary of Fortune Brands, Inc. The site is located in an industrial zoned area. The upper floors of the Site are currently used for commercial and light industrial purposes, the basement is unoccupied, and a penthouse which houses a private racquet club, fitness center, spa and restaurant occupies the rooftop of the Site.Historical Use(s):The facility was constructed in 1950 and ACCO (or its predecessor corporations) occupied the facility from 1952. The site was reportedly occupied by several automotive service centers and gasoline stations prior to 1950. During their occupancy of the facility, ACCO manufactured staplers and stapler components. Paints, thinners, solvents and cleaners were used as part of the manufacturing process and may have led to site contamination. Wastes generated included paint filters, sludge, rags, and paint.Operable Units:The Site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination." Operable unit 1 (OU-1) is the on-Site source area which included the basement of the building. Operable unit 2 (OU-2) consists of the off-Site dissolved groundwater plume and associated soil vapor issues.Site Geology and Hydrogeology:The site is underlain by silty sand with varying amounts of gravel, silts and clays. Soil borings indicate a laterally pervasive low permeability layer beneath the entire footprint of and to the west of the Site. Parts of the low permeability layer, which dips to the south-southeast, are compromised by a layer of organic peat. TCE has been detected in the shallow, intermediate and deep aquifer zones at the Site. Depth to groundwater in the shallow aquifer is approximately 10 grade with a flow to the northwest. Depth to groundwater in the intermediate aquifer is 35 below grade with a flow to the west-northwest. Depth to groundwater in the deep aquifer is 60 below grade with a flow to the north-northwest.
Env Problem: Nature and Extent of Contamination:OU-1 Soil - Based upon investigations conducted to date, the primary contaminants of concern for OU-1 soils include trichloroethene (TCE) and its breakdown products that were noted in an unlined pit in the basement of the facility. The extent of impacted soils is confined to the western half of the footprint of the basement. Concentrations of TCE found in soils on site ranged from 79 ppm to 256 ppm, which exceeds the Soil

CLOSED-LACKOF RECENT INFO (Continued) **S100494133**

Cleanup Objectives (SCO) for the protection of groundwater (0.47 ppm). Maximum concentrations were noted at a depth of 16-16.5 feet below the basement floor. OU-1 Groundwater - TCE and its breakdown products were encountered in both shallow groundwater samples collected at approximately 15 below grade and deep groundwater samples collected at approximately 49 below grade. Concentrations of TCE in shallow groundwater on site ranged from 108 ppb to 129,000 ppb, which exceeds the Groundwater Standard of 5 ppb. Concentrations of TCE found in deep groundwater on site ranged from 700 ppb to 1280 ppb. Maximum groundwater contaminant concentrations are encountered in the western half of the Site.OU-1 Soil Vapor - The maximum sub-slab soil vapor concentration of TCE found in samples collected beneath the on-site building were 160,000 ug/m3 in the eastern portion of the basement and 260,000 ug/m3 in the northern portion of the basement.OU-2 Groundwater TCE and its breakdown products were encountered in shallow, intermediate and deep groundwater samples. Depth to groundwater is approximately 10 below ground surface (bgs) in the shallow aquifer, approximately 35 bgs in the intermediate aquifer, and approximately 60 bgs in the deep aquifer. Maximum concentrations of TCE found in shallow off-site groundwater samples were 140,000 ppb. Maximum concentrations of TCE found in intermediate off-site groundwater samples were 45,800 ppb. Maximum concentrations of TCE found in deep off-site groundwater samples were 65 ppb. Approximate plume length is 500 down gradient from the site.OU 2 Soil Vapor - Off-site studies of soil vapor intrusion were conducted at the several locations. Concentrations of TCE in sub-slab and indoor air samples collected in two off-site locations during the Remedial Investigation exceeded the recommended action levels as established by NYSDOH. Vapor mitigation systems have been installed in these buildings.

Health Problem: Direct contact with contaminants in the soil is unlikely because the site is covered with a building and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for people to inhale site contaminants in the indoor air due to vapor intrusion in the on-site building. A soil vapor extraction system was installed beneath the on-site building, which prevents vapors beneath the slab from entering the building. Sub-slab depressurization systems (systems that ventilate/remove the air beneath the building) have been installed in off-site buildings to prevent inhalation of site contaminants in indoor air due to soil vapor intrusion.

AQ223 **SPILL NUMBER 0103168** **NY LTANKS** **S105055149**
WNW **10-20 44TH RD** **NY Spills** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.465 mi.
2455 ft. **Site 1 of 2 in cluster AQ**

Relative:
Higher

Actual:
14 ft.

LTANKS:

Site ID:	210325
Spill Number/Closed Date:	0103168 / 8/27/2002
Spill Date:	2/13/1998
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	6/22/2001
CID:	205
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	6/22/2001
Spill Record Last Update:	4/7/2003
Spiller Name:	Not reported
Spiller Company:	RYDER TRUCK.
Spiller Address:	10-20 44TH RD
Spiller City,St,Zip:	LONG ISLAND CITY, NY
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	174355
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE"ORIGINAL SPILL # 97-12701 SENT TO REGION 1 REFERS TO SATURATED SOIL.08/27/2002 CLOSED THIS SPILL NUMBER, SEE SPILL # 97-12701
Remarks:	caller was told by region office to call hotline for new number.

Material:

Site ID:	210325
Operable Unit ID:	841870
Operable Unit:	01
Material ID:	535262
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

SPILL NUMBER 0103168 (Continued) **S105055149**

Tank Test:

SPILLS:

Facility ID:	9714321
DER Facility ID:	174355
Facility Type:	ER
Site ID:	210327
DEC Region:	2
Spill Date:	3/25/1998
Spill Number/Closed Date:	9714321 / 8/27/2002
Spill Cause:	Human Error
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	IXMUNTEA
Referred To:	Not reported
Reported to Dept:	3/25/1998
CID:	370
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	3/25/1998
Spill Record Last Update:	8/27/2002
Spiller Name:	Not reported
Spiller Company:	CLEAN HARBORS
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	ABOVE CALLER
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MUNTEANU"08/27/2002 CLOSED THIS SPILL # AND 01-03168. SPILL IS OPEN UNDER 3 97-12701
Remarks:	while filling truck - overfill spill to containment abd cleaned

Material:

Site ID:	210327
Operable Unit ID:	1057192
Operable Unit:	01
Material ID:	325289
Material Code:	0015
Material Name:	Motor Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15
Units:	Gallons
Recovered:	25
Resource Affected:	Not reported
Oxygenate:	False

SPILL NUMBER 0103168 (Continued) **S105055149**

Tank Test:

Facility ID:	9712701
DER Facility ID:	174355
Facility Type:	ER
Site ID:	210326
DEC Region:	2
Spill Date:	2/12/1998
Spill Number/Closed Date:	9712701 / Not Reported
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	AXDORONO
Referred To:	GWMR (06/03/13) REVIEWED
Reported to Dept:	2/13/1998
CID:	370
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	5
Date Entered In Computer:	2/13/1998
Spill Record Last Update:	7/31/2013
Spiller Name:	Not reported
Spiller Company:	RYDER TRUCK
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller Company:	001
Contact Name:	CARRIE VINCH
Contact Phone:	(609) 896-8066
DEC Memo:	Spill originally sent to r1. It is in queens county. Bob Corcoran 07/10/0108/27/2002 CLOSED SPILL 01-03168 AND REFERRED THIS # TO 97-14321 4/7/03 TIPPLE REVIEWED CORRECTIVE ACTION PLAN SUBMITTED BY GZA REMEDIATION ONGOING8/14/03 WEDNESDAY MTG. AT RYDER FACILITY, RYDER TO ADDRESS REMEDIATION OF GAS CONTAMINANTS BELOW THE GARAGE FACILITY//TEST PIT WITH HORIZONTAL APPLICATION// FENTONS // REMEDIAL PLAN TO FOLLOW// CONTINUE MONITOR PROGRAM OUTSIDE BUILDING. 12/10/03 mt/// Transferred from Tipple to Rommel8/4/04Monitoring groundwater quarterly for a few years, 90 ppb MTBE, 72 ppb Benzene Groundwater in parking lot where dispenser island used to be. Proposing semi annual sampling. Tanks replaced. Few hundred yards soil removed 2001. Indoor issue - tanks removed 1992. Oil water separator still in place possibly another source. No permanent monitoring wells. Rommel9/15/04Reviewed Remedial Investigation Report dated 5/18/04 - objective to delineate near former diesel UST. one temp well installed, gw 15200 ppb Xylene, 7200 Toluene, 2300 Benzene, 2900 Ethylbenzene.Soil borings to west and south of Nov 2002 boreholes. GW 11-12 ft bg. sands some clay to the west of former USTs. Max soil contamination 3 - 6'.Left vm message for Ben Aldrich 973-256-7800:Closure and replacement of O/W separator scheduled summer 2004?Historic gw sampling.Historic reports.Delineate gw and

SPILL NUMBER 0103168 (Continued) **S105055149**

soil contaminationSubmit map summarizing all soil results greater than TAGM.Propose remediation.Rommel10/15/04 Transferred from Rommel to Foley. (KMF)4/27/05 Received 2004 Annual GW Monitoring Report. GZA sampled wells on 2/18/04 and 10/6/04. Objective is to determine effectiveness of MNA. Not sampling for geochemical indicators. Sampling for TBA. MW-1,2,3,4,6 were purged and sampled. The sample from MW-5 was not analyzed since no target compounds were detected during previous sampling events. MW-1 exhibited a petroleum odor and slight sheen during both events. MW-2 had a slight odor but no sheen. MW-3 did not exhibit odor and ran dry during purging. MW-4 had a slight odor during both. MW-5 ran 2.9ppm on the PID and MW-6 ran 1.1ppm on the PID. Purge water from MW-5 had a strong organic or sulfur odor in Feb. MW-6 had a slight odor in Feb.Oct 04- BTEX ranged from ND(MW-2,3,4) to 164ppb(MW-1). MTBE ranged from ND(MW-4) to 41ppb(MW-1).12/22/05 Annual report received. MW-1, within the former source area, continued to exhibit low concentrations of most targeted compounds, including MTBE. Napthalene and TBA have increased, perhaps due to biodegradation. Napthalene and TBA were detected in low concentrations in MW-2 and benzene at a slight exceedance. In MW-3, MTBE was detected at its lowest conc to date, while TBA was at its highest to date. Xylenes were detected above MDL for the first time. MW-4 did not contain any targeted compounds exceeding GWQS. MW-6 contained MTBE at a slight exceedance. Napthalene, 1,2,4-trimethylbenzene and total xylenes were detected above standard for the first time in MW-6 during the 10/05 event. Semi-annual sampling continues. An annual report will be submitted 12/06.3/22/06 Reassigned from Foley to Tang.(KMF)04/12/2007: This spill case was transferred to A. Doronova. - AD04/13/2007: Reviewed UST closure report and oil/water separator system closure report submitted by GZA, dated October 2006. UST closure report states that one 5,000-gallon UST was abandoned in place. During UST closure four samples were taken through four holes drilled two feet below the bottom of UST. No targeted VOC or PAH compounds were detected at concentrations exceeding their respective RSCOs in any of the soil samples. Based on this information GZA recommends NFA for this UST.During oil/water separator closure GZA performed some activities including: Collecting and analysing composite soil samples from the impacted area; collecting and analysing 5 post-excavation soil samples; removing from the site approximately 112 tons of impacted soil. Four of five post-excavation soil samples had elevated PID readings from 267 to 458 ppm. Lab results indicated elevated concentrations of VOC in these 4 samples. The excavation of contaminated soil could not be done because of structural building components. GZA is currently in preparation of RAP to address the impacted soils and groundwater at the site. AD04/16/2007: Spoke with Ben Alter of GZA. He told me that RAP will be ready for submittal around June 2007. They already installed new groundwater monitoring wells in the vicinity of closed oil/water separator to better delineate GW contamination. I ask him to submit also a complete and detailed map of the site, which he promised to do. AD05/02/2007: Received a letter from Ben Alter of GZA with attached soil sampling map and monitoring well location map. Submitted maps are not exactly what I asked for. Locations of oil-water separator, 5,000 gallon UST and 8 diesel former USTs are not indicated on both maps. Soil borings and end-point soil samples are not time color-coded. Will wait for RAP submittal. AD05/14/2007: Spoke to Mr. Alter of GZA. Asked him about date of RAP submittal. He said it will be ready before July. He

SPILL NUMBER 0103168 (Continued) **S105055149**

will also send revised maps for the site. GZA will do sampling round including newly installed wells MW-7 and MW-8 in two weeks. Analytical results will be submitted in RAP. AD05/18/2007: Received a map with locations of abandoned UST and oil/water separator with indication of the excavated limit. AD08/2007: Spoke to Ben Alter of GZA regarding RAP submittal. He said that the owner still did not decide on the plan. Promised to call me back. AD10/07/2007: Received a call from Tyree Env. This company is a new consultant for the site. They will prepare and submit RAP to DEC. AD11/07/2007: Received a call from Robert Ott of Tyree Env. (phone: 631-249-3150, ext 280) He asked for a meeting with us to discuss remedial action plan for this site. Scheduled the meeting for Tuesday November 13, 2007. AD11/13/2007: Jon Kolleeny and I attended a meeting with Robert Ott of Tyree Env. Tyree Env. will prepare work plan for delineation of contamination inside the building and then propose remedial action plan for the area of concern. AD01/18/2008: Called and left a message to R. Ott regarding investigation work plan submission. AD01/29/2008: Spoke with Robert Ott of Tyree. He said that work plan proposal was submitted to the owner for approval. Asked me if we can send them a letter to expedite the plan's review. AD01/30/2008: Sent a Investigation Needed Letter to Ms. Carry Anne Vinch of Ryder with a request to expedite investigation plan submission. AD03/03/2008: Spoke with R. Ott of Tyree. He said that scope of work was approved by owner and now they in a process of the work plan preparation. He plans to submit it in the beginning of April 2008. AD04/17/2008: Received a letter from Ryder. It states that Tyree Brothers Env. Services (TBES) did propose to implement investigation work for Ryder, but however Ryder did not retained them to perform any work, or prepare any plans. It says, that Ryder is presently reviewing options to move this site to closure. Called and left a message to Ms. Vinch of Ryder. AD04/25/2008: Called and left a message to Ms. Vinch of Ryder. Spoke with J. Kolleeny regarding this site. Sent Ms. Vinch an email, stating that we will prepare STIP for the site to ensure timely cleanup. AD04/30/2008: Received a phone call from Ms. Vinch of Ryder. She requested a meeting with DEC at the site. Told her that it can be arranged in DEC building. Ms. Vinch will call latter with a date for the meeting. AD05/14/2008: Did not receive any calls from Ms. Vinch of Ryder. Called and left a message. AD05/15/2008: Received a call from Ms. Vinch of Ryder. Scheduled a meeting with them on May 29, 2008. AD05/27/2008: Received Annual Groundwater Monitoring report. Will review. AD05/29/2008: Received a call from Ms. Vinch. She asked to re-schedule the meeting for Thursday, June 5, 2008 due unavailability of their consultant. AD06/05/2008: J. Kolleeny and I attended the meeting with Carrie Vinch 0f Ryder Truck and Brian Moore of CHCI. We discussed current site conditions. It was agreed that a work plan for additional groundwater investigation will be submitted to DEC in the mid-June. Based on the results of the investigation, recommendations will be made for further actions. AD07/16/2008: Received an email from Brian Moore of CHCI saying:Ms. Doronova - Thank you for taking time out of your busy schedule to meet with us last month to discuss the status of the assessment activities underway at the above-referenced Ryder facility at 10-20 44th Road in Long Island City.We are putting the final touches into the work plan being developed to address the items we discussed during our meeting last month, and we will be submitting it shortly for your review and approval. We appreciate the opportunity you provided for us to discuss the cases at this

SPILL NUMBER 0103168 (Continued) **S105055149**

property, and we look forward to your review of the scope when submitted. Please do not hesitate to contact us should you have any questions, comments, or concerns.Most sincerely,Brian D. MooreCarriageHouse Consulting, Inc.Ph: 508.315.3146Cell: 508.479.356007/23/2008: Received PDF version of the work plan from Brian Moore. Will review. Downloaded to eDocs. AD07/28/2008: Received a hard copy of the work plan AD07/30/2008: Sent an approval letter to Ms. Carry-Vinch with the following comments: Two soil samples per boring must be collected: one - directly above the water table and the second - from the sampling interval with the highest PID reading. In the absence of any field indication of contamination, a single soil sample just above the water table should be collected; Laboratory analysis for VOCs and SVOCs, specified on page 3 (third paragraph from top of the page) of the work plan, must be conducted for all samples collected. AD08/22/2008: Received an email from B. Moore of CHCI saying: "Ms. Doronova - In preparing the driller for the new well installation work planned forthis facility (DEC already approved), we have reviewed the previous wellconstruction details more in-depth and would like DEC to re-considerplans for well replacement. In lieu of replacement of MW-3 and 4, we would like to have DEC approve augmenting the network in thoseareas to confirm hydrological conditions and better assist with the conceptual model development for this location in general.Please review the attached and let us know if it meets with your approval.Original went into regular mail last night.We have proactively pre-marked for this work, and await your authorizationto proceed with the revised scope. Thanks again,Brian D. MooreCarriageHouse Consulting, Inc.Ph: 508.315.3146Cell: 508.479.3560http://www.carriagehouseinfo.com"Downloaded the WP addendum to eDocs. Will review. AD09/09/2008: Reviewed the revised WP. Sent an approval letter to K. Zias (cc: J. Kolleeny of DEC and B. Moore of CHCI). AD09/18/2008: Received an email from B. Moore of CHCI, saying: "Ms. Doronova -CHCI anticipates initiating the drilling portion of this Work Plan at this site beginning next Wed., by 10AM or 11AM, continuing through the end ofThursday.We look forward to potentially seeing you there if you decide to visit.Sincerely,Brian D. MooreCarriageHouse Consulting, Inc."Will visit the site. AD09/24/2008: Visited the site. Met with B. Moore of CHCI at the site. They already completed installation of the replacement for MW-3. Observed installation of the monitoring well MW-4S and PID screening of soil samples. PID ranged from ND to 942 ppm (v) at 10' depth. Asked B. Moore to collect soil sample from this interval for lab. analysis. CHCI will complete installation of 3 wells at the parking lot today, and will continue to install wells inside the building tomorrow. Wells will be sampled in two weeks. AD09/25/2008: Received a call from B. Moore of CHCI. He said that they installed well MW-9 with difficulties and he was questioning if it is reasonable to install well MW-10. The highest PID reading from boring for MW-9 was - 848 ppm (v). Discussed this with J. Kolleeny. Asked B. Moore to move location for well MW-10 10-15 feet to the east from MW-9. AD10/16/2008: Received a phone call from B. Moore of CHCI. During GW sampling they discovered a free product in the monitoring well MW-1. It looks as weathered light fuel oil. They collected a sample for fingerprint analysis and groundwater sample for lab analysis. The free product was bailed out of the well to find recovery rate. All data will be analyzed and conclusions and recommendations will be made. AD11/05/2008: Spoke with B. Moore of

SPILL NUMBER 0103168 (Continued) **S105055149**

CHCI. Asked him about MW-01. He said that absorbent sock was placed into the well to collect the free product. Yesterday, they replaces the sock. CHCI proposes to implement IRM for this well by installing skimmer to recover free product. Requested to submit a brief work plan for this IRM for our approval. AD12/18/2008: Received a phone call from B. Moore of CHCI. He was at the site to check for free product in well MW-1. He said that CHCI will propose to install additional well to delineate the free product. Asked him to submit brief work plan with the proposed well location. Also requested to send me an email stating the current field findings. AD02/09/2009: Received a phone call from B. Moore regarding UST closure report and oil/water separator system closure report, which was submitted by GZA in October 2006. UST closure report stated that one 5,000-gallon UST was abandoned in place. During UST closure four samples were taken through four holes drilled two feet below the bottom of UST. No targeted VOC or PAH compounds were detected at concentrations exceeding their respective RSCOs in any of the soil samples. Based on this information GZA recommended NFA for this UST. Mr. Moore was wondering if NFA letter could be issued by DEC for this particular tank. Later received an email from Mr. Moore saying:"Ms. Doronova - As we have discussed, the attached Work Plan addendum is based on the presence of NAPL in well MW-1. Historical GW flow has fluctuated, and that is the reason for the two well placement downgradient of the current/former UST areas.Thank you again for your consideration in these matters, and we look forwardto getting these new wells installed and then complete the SSI!Sincerely,Brian D. MooreCarriageHouse Consulting, Inc.Ph: 508.315.3146Cell: 508.479.3560"DL the work plan to eDocs. Will review. AD02/23/2009: Reviewed the work plan. CHCI proposes to install two additional wells in the southern and southwestern portions of the site to delineate the extent of LNAPL. Wells will be located downgradient from well MW-1 and current/former UST areas. Will send a letter. AD02/24/2009: Sent an approval letter with a comment regarding soil sampling interval. AD02/26/2009: Visited the site to observe installation of additional wells. Met at the site Nathan Stevens - hydrogeologist of CHCI. GeoSearch company was subcontracted to perform the installation. Wells MW-13 and MW-14 were installed downgradient of well MW-1.Headspace PID readings ranged from 1,7ppm at 15’ bgs to 53.5ppm at 8-10’ bgs for MW-14 and from 1.6ppm at 15’ bgs to 188ppm at 6-8’ bgs for MW-13. Soil from intervals with highest PID readings and just above the water table interval were collected for lab analysis. Took some pictures. DL them to Ryder Truck file. Results of current soil sampling and following groundwater sampling will be presented in ASI summary report. AD 03/12/2009: Spoke with B. Moore regarding UST closure report, which was submitted by GZA in October 2006. Asked him to submit a letter request. AD03/16/2009: Received the letter from CHCI which states that no evidence of petroleum release was encountered during the in-place closure of this UST and requests to issue a letter affirming this conclusion. Mr. Moore was wondering if NFA letter could be issued by DEC for this particular tank. Discussed with J. Kolleeny this request. No NFA can be issued, because no any spill cases were open for this tank. Will prepare a statement letter. AD03/26/2009: In response to CHCI request sent the statement letter, which says that the Department agrees, based on information provided, that open spill case 9712701 is not associated with this particular UST. AD06/12/2009: Called and spoke with B. Moore of CHCI regarding the summary report submission. He said that

SPILL NUMBER 0103168 (Continued) **S105055149**

the report will be submitted till the end of June 2009. AD06/24/2009: Received an e-mail from B. Moore of CHCI saying:"Ms. Doronova - As a follow up to our telephone call the other day, I wanted to send this email confirming the status of the Supplemental Site Investigation Report planned for the for the Ryder Facility at 10-20 44th Road in Long Island City.To-date, we have compiled the data from more than twenty individual reports from the last 17 years into this investigation (greater than individual 100 soil samples on-site) and we have supplemented that data set with a round of soil borings and well installation work in 9/2008, followed by additional drilling in 2/2009, and initiated passive NAPL recovery activities in one of the former UST areas. Please note that we have been continuing our monthly visits to keep track of the NAPL and sheens in site-related wells as part of the DEC approved IRM. In fact, we are out there his morning checking the wells again for NAPL. We have identified a single subsurface investigation report missing from the file from 2002, and have requested a copy of the same get pulled from the former consultant's archive. This report has the construction details on MW-5, and is believed to be the only missing report to our file. Once received, reviewed, and incorporated, the SSI will be complete. As we have not received this single final report yet, I would be more comfortable getting and incorporating the information from MW-5 construction into this SSI rather than rushing it to completion in the next six days. So taking into consideration our continued monitoring efforts at this site, we would like to receive your authorization to complete the SSI including the data from MW-5 installation to offer a full and complete investigation for the file, and serve as a basis for associated conclusions and further recommendations related to remediation.This site remains a big priority for Ryder, and we really want the SSI to serve the intended purpose outlined in our previous correspondence and meetings, as well as the DER-10 Guidance. Please give me a call if you have any questions or require additional information in considering our request.Respectfully,Brian D. MooreCarriageHouse Consulting, Inc.Ph: 508.315.3146Cell: 508.479.3560"Called and spoke with Brian. Postponed the report submission till July 15, 2009. Sent him the report from April 29, 2002, with the construction details on MW-5 installation, which was missing from their files. AD07/10/2009: Received a call from B. Moore. He said that CHCI plans to continue delineation of GW contamination and asked to postpone Investigation Report submission, so they can include work plan for additional investigation into this report. Approved the postponement of the submission till August 1, 2009. AD07/31/2009: Received Supplemental Site Investigation Report from CHCI. DL pdf copy to eDocs. Will review. AD09/25/2009: Received an e-mail from B. Moore of CHCI saying:"Ms. Doronova - Attached please find the electronic copy of the Work Plan Addendum for continued NAPL recovery efforts at the Ryder facility at 10-20 44th Road in LIC, NY. We have continued our monthly visits, and desire to do so through December, reporting results from the same in Jan, 2010. For the next 12 months, CHCI and Ryder also desire to conduct quarterly NAPL monitoring and groundwater sampling at this location, inclusive of sampling for select MNA parameters.Any changes in NAPL recovery strategy will be discussed and presented in the Jan, 2010 IRM Status Update report. We also propose a Jan 2011 IRM Status Update report.Thank you for your attention to these matters, and please get in touch with any questions or comments, hard copy in mail.Brian D. MooreCarriageHouse Consulting, Inc.Ph:

SPILL NUMBER 0103168 (Continued) **S105055149**

508.315.3146Cell: 508.479.3560"DL to eDocs. Will review. AD10/27/2009: Reviewed the work plan addendum. It proposes to decrease LNAPL recovery frequency from monthly to quarterly due to low free product recovery rates, starting in January 2010, and also to conduct quarterly groundwater monitoring for a period of one year to collect and analyze data for further remedial actions. AD10/30/2009: Discussed the work plan with J. Kolleeny of DEC. Issued an approval letter with the following comments: " - Quarterly groundwater monitoring at the site should start before the end of this year; - If the results of the first groundwater monitoring event indicate highly elevated levels of contamination in the site wells, then DEC may require that a more active remedial approach be developed."AD05/03/2010: Received a Groundwater Monitoring report for 1st quarter of 2010. DL pdf copy to eDocs. Will review. AD06/10/2010: Reviewed the report. It states that on February 25 through 26, 2010 CHCI conducted the quarterly monitoring well gauging, monitoring, NAPL recovery, and sampling at this site. The thickness of NAPL detected in well MW-1 was a "sheen" (less than 0.01 feet) during the February 25, 2010 gauging and sampling event, and NAPL was not detected in wells MW-13 and MW-14.On February 25 and 26, 2010 CHCI performed groundwater monitoring and sampling at the site. Groundwater monitoring activities also included the measurement of temperature, conductivity, dissolved oxygen (DO), oxidation-reduction potential (ORP), and acidity/alkalinity (pH) at each of the site's sixteen (16) wells. CHCI collected groundwater samples from the 16 site wells. Samples from six out sixteen wells were ND for TVOCs (wells: MW-3, MW-3S, MW-4S, MW-5, MW-8, MW-9. Four monitoring wells (MW-2, MW-4, MW-6 and MW-12) exhibited very low TVOCs concentration ranging fron 1.1ppb in well MW-4 to 5ppb in well MW-12. Moderate TVOCs were detected in two site wells: MW-1 - 428ppb, and well MW-13 - 412ppb.Most contaminated site wells are: well MW-10 - 7,249ppb, well MW-11 - 4,555ppb and well MW-14 - 7,964ppb.During the monitoring visit, NAPL has been recovered from the monitoring well network using deployment/recovery of absorbent booms to facilitate NAPL recovery. During previous reporting periods, NAPL recovery efforts had included deployment of a passive Keck-brand skimmer in well MW-1, but repeated comparisons to the effectiveness of adsorbent booms indicated greater recovery rates were achieved using the passive booms rather than the skimmer.During this reporting period, only passive booms were utilized to adsorb NAPL present in wells MW-1, MW-13, and MW-14. Boom replacement were conducted for wells MW-13 and MW-14 with one (1) 1.5" boom each, and for MW-1 with one (1) 3" boom. Approximately 4.613 gallons of NAPL in total have been recovered since program start, and approximately 0.45 gallons were recovered during this reporting period. CHCI will continue quarterly monitoring and recovery activities, with the next sampling and IRM visits scheduled for May and August, 2010. No response is needed. AD07/29/2010: Received a Groundwater Monitoring report for 2nd quarter of 2010. DL pdf copy to eDocs. Will review. AD10/16/2010: Received a Groundwater Monitoring report for third quarter of 2010. DL pdf copy to eDocs. Will review. AD12/17/2010: Reviewed the report. It states that on August 24 through 25, 2010 CHCI conducted the quarterly monitoring well gauging, monitoring, NAPL recovery, and sampling. NAPL was not detected in any of the on site wells. Groundwater monitoring activities also included the measurement of temperature, conductivity, dissolved oxygen (DO), oxidation-reduction potential (ORP), and acidity/alkalinity (pH) at each of the site's sixteen (16)

SPILL NUMBER 0103168 (Continued) **S105055149**

monitoring wells. CHCI collected groundwater samples from the sixteen (16) wells for analyses of VOCs. During the sampling event of August 24 and 25, 2010, samples from six out sixteen wells were ND for TVOCs (wells: MW-3, MW-3S, MW-4S, MW-5, MW-8, MW-9. Five monitoring wells (MW-2, MW-4, MW-6 and MW-12 and MW-14) exhibited very low TVOCs concentration ranging from 3.6ppb in well MW-6 to 18ppb in well MW-14. Moderate levels of TVOCs were detected in three site wells: MW-1 - 413ppb, MW-11 - 610ppb and well MW-13 - 359ppb. Most contaminated site wells are: well MW-10 - 9,595ppb, which is increase from 7,249ppb, and well MW-7 - 3,394ppb.During this reporting period, only passive booms were utilized to adsorb NAPL present in wells MW-1, MW-13, and MW-14. The three booms currently being used in the wells were all removed and replaced, as they were at their absorbent capacity. These booms include one (1) 1.5" boom each for MW-13 and MW-14, and one (1) 3" boom for MW-1. Since start of the NAPL recovery activities in 2008, approximately 5.933 gallons of NAPL have been recovered from the groundwater monitoring well network, approximately 0.88 gallons of which were recovered during this reporting period. Recovered NAPL and absorbents continue to be stored onsite, placed inside a 55-gallon capacity drum set within a secondary containment. No response is needed. AD03/25/2011: Received a phone call from B. Moore of CHCI. He asked if they can sample the wells. Told him that since the site is on quarterly GW monitoring no approval from DEC is needed. Later received an e-mail from B. Moore of CHCI saying:"Ainura - As we discussed this morning, we were expecting a letter back from DEC in time to authorize the sampling event for this month (March 2011) to align with previous years so we may compare in future submittals. Based on our discussion, we acknowledge that (at a minimum) Annual groundwater monitoring is currently required at this site, and potentially more frequent for those wells exhibiting higher concentrations (e.g., MW-7/10). We would appreciate also learning how DEC staff has been implementing CP-51 on soil objectives/cleanup levels, and we were considering an off-site downgradient well on the distant side of 44th Drive, and pilot testing remedial additive injections under the building to stabilize GW conditions around the former UST area. Thank you in advance for your attention to these matters, and we look forward to hearing back from you. Brian Moore"Sent him an e-mail saying:"Hi, Brian: As per our afternoon phone conversation, CHCI should proceed with quarterly groundwater sampling according to NYSDEC correspondence from October 30, 2009, and based on the new and historical data, a remedial action plan to address residual groundwater contamination at the site should be prepared and submitted to DEC in a timely manner. If you would like to exclude some of the wells from the groundwater sampling program, based on their ND results for VOCs, you should propose it in your next report or in an official letter. Sincerely, Ainura"AD06/20/2011: Received an e-mail from Brian Moore saying:"Ms. Doronova - Attached please find the GMG outlining results from the March sampling event at Site #9712701, which we are also sending you a hard copy of and a disk with the attached eCopy (in DEC naming convention). The work plan was developed with the intention of obtaining authorization to initiate feasibility evaluations at this site and preliminary RIR activities, including pilot testing/bench-scale tests in efforts to stabilize site groundwater conditions and allow for bioremediation to continue. I hope you have a pleasant long weekend, and look forward to your review of the attached. Thanks in advance for your time. Brian D. MooreCarriageHouse Consulting, Inc."DL the report to eDocs.

SPILL NUMBER 0103168 (Continued) **S105055149**

Will review. AD06/21/2011: Reviewed the Remedial Investigation Work Plan dated May 27, 2011 pertaining to the above-referenced site, submitted by Carriage House Consulting, Inc. (CHCI), which stated that high levels of VOCs remain in two wells in the former USTs area and that free product sheen was present in wells MW-01, MW-13 and MW-14. The work plan proposes a soil and groundwater investigation in the vicinity of former gasoline USTs. CHCI will install two additional monitoring wells and two injection wells at the site, with collection of soil and groundwater samples for laboratory analysis. A report summarizing all findings, with conclusions and recommendations for further remedial action, will be prepared and submitted to DEC.The site plan with locations of the proposed wells is missing. Called and spoke with B. Moore regarding submission of the site map. Also asked to indicated on the map - locations of the former USTs fields. He agreed to re-submit the work plan. AD06/28/2011: Received a Remedial Investigation Work Plan Addendum dated June 28, 2011, submitted by Carriage House Consulting, Inc. The work plan includes the required site map with depiction of the proposed wells locations. CHCI will install two additional monitoring wells and two injection wells at the site, with collection of soil samples for bench-scale analysis and groundwater samples for VOCs and field parameters analysis as a preparation for a pilot study. Location of injection well IW-01 is questionalbe. Called and spoke with B. Moore regarding relocation of the proposed injection well IW-01 up gradient of highly contaminated monitoring well MW-07. He agreed to this change. AD07/05/2011: Discussed with Brian Moore details of the anticipated pilot study work plan. Requested some info on the free product identification. Discused the addendum to the work plan with J. Kolleeny. Will issue an approval letter. AD07/06/2011: Approved the addendum to the investigation work plan with the following comments:" Two soil samples must be collected from each boring/well and analyzed for VOCs and SVOCs - one from the sampling interval with the highest PID reading and the second from the interval directly above the water table-. In the absence of any field indications of contamination, a single soil sample should be collected from just above the water table. Proposed injection well IW-01 should be relocated up-gradient of monitoring well MW-07."Based on the result of this investigation a work plan for anticipated pilot study will be submitted to DEC.Sent the letter to Carrie Vinch of Ryder Truck. DL pdf copy of the letter to eDocs. AD07/07/2011: Received a Remedial Investigation Work Plan Confirmation, submitted by Carriage House Consulting, Inc. (CHCI) on behalf of Ryder Transportation Services. Will review. AD09/09/2011: Reviewed the WP Confirmation from CHCI. CHCI states that, out of sixteen site wells in total, elevated levels of dissolved groundwater contamination remain in only six monitoring wells: MW-01, MW-07, MW-10, MW-11, MW-13 and MW-14. Based on the data, CHCI recommends continuing quarterly groundwater monitoring for these six wells while reducing the frequency of groundwater monitoring for ten other wells from a quarterly to an annual basis, due to insignificant VOC levels in those wells. Monitoring reports will continue to be prepared and submitted to DEC on a quarterly basis. Tpo send a letter. AD09/23/2011: Received an e-mail from B. Moore saying:"Ms. Doronova - We have tentatively scheduled the groundwater sampling event for the Ryder location at 10-20 44th Road in Long Island City, NY under DEC Case #9712701 for 9/29/11 and 9/30/11 (second day if required to complete Task). In the event this schedule changes during the next few days, we will give you a call or email you to advise. Have a nice

SPILL NUMBER 0103168 (Continued) **S105055149**

weekend! Brian Moore"AD10/06/2011: Discussed the CHCI recommendation with J. Kolleeny of DEC. Issued and sent an approval letter to C. Vinch of RyderTruck. DL pdf copy of the letter to eDocs. AD12/08/2011: Received an e-mail from CHC saying:"Ainura Doronova - Per your request I am forwarding to you the Groundwater Monitoring Report for the Ryder site in Long Island City. The hard copy with included CD was delivered via UPS today. Please do not hesitate to call if you need anything more.Regards, Estee SchmaltzCarriageHouse Consulting, Inc.8 Pleasant StreetSouth Natick, Massachusetts508.315.3146"DL the pdf copy of the report to eDocs. AD01/20/2012: Reviewed the report.02/23/2012: Received the following e-mail from CHCI:"Ainura Doronova - The Groundwater Monitoring Report for the Ryder Facility in Long Island City has been delivered to the NYSDEC. Please find attached an electronic version for your records and review. Also included in this report is a request from the Department to issue correspondence authorizing the installation of a monitoring well within the 44th Drive right of way as depicted on Figure 5 for distribution to the appropriate City and Borough entities. Please let me know if you need additional information, or if there are additional forms to fill out for this next step. Regards,Estee SchmaltzCarriageHouse Consulting, Inc.8 Pleasant StreetSouth Natick, Massachusetts508.315.3146eschmaltz@carriagehouseinfo.com"DL to eDocs. Will review. AD03/07/2012: Reviewed the report. It states that during the sampling event of December 29, 2011, GW samples were collected from five of the six wells. Moderatly elevated levels of VOCs were detected in samples collected from wells MW-1 (370ppb) and MW-13 (251ppb) on the western portion of the parcel; and significant levels of VOCs were detected in samples collected from wells MW-7 (3,812ppb), MW-10 (16,731ppb) on the eastern portion of the site. Well MW-11 had 316ppb. During the monitoring visits NAPL has been recovered from the existing and expanded site-related monitoring well network using absorbent booms. During previous reporting periods, NAPL recovery efforts had included deployment of a passive Keck-brand skimmer in well MW-1, but comparison indicated greater recovery rates were achieved using the passive booms rather than the skimmer.During this reporting period, only passive booms were utilized to absorb NAPL present in wells MW-1, MW-13, and MW-14. The boom located in well MW-1 was flipped on December 29, 2011 because it was not at its absorbent capacity. The booms located in wells MW-13 and MW-14 were removed and replaced. Since the expansion of the site-related groundwater monitoring well network, and the increase in site monitoring and NAPL recovery activities in 2008, approximately 8.133 gallons of NAPL have been recovered, approximately 0.53 gallons of which were recovered during this reporting period. Recovered NAPL and absorbents continue to be stored on site, placed inside a 55-gallon capacity drum set within a secondary containment.The analytical results from the December 29, 2011 sampling event demonstrate that many of the dissolved hydrocarbon concentrations in groundwater have remained relatively stable since the March and September 2011 sampling events. The only exception is well MW-10, whose results increased since the September 2011 sampling event. Physical and geochemical monitoring results from this event indicate that groundwater conditions at this property are generally anaerobic, reducing, and slightly basic.CHCI will proceed with implementation of the DEC approved work plan and request to issue a Sidewalk Permit letter for installation of off-site well across 44th Drive. To issue

SPILL NUMBER 0103168 (Continued) **S105055149**

a letter. AD03/13/2012: Issued and sent a Sidewalk Permit Request letter to B. Moore of CHCI. DL pdf copy of the letter to eDocs. AD06/05/2012: Received a hard copy of the Groundwater Monitoring Report for the first quarter of 2012. DL pdf copy to eDocs. Will review. AD06/27/2012: Reviewed the report. It states that during the sampling event on March 27 and 28, 2012 CHCI conducted monitoring well gauging, geochemical monitoring, NAPL recovery, and sample collection. Wells MW-4 and MW-4S were inaccessible during this monitoring event until March 28, 2012. During the March 2012 event, light NAPL was not detected in any of the wells monitored. During this reporting period, only passive booms were utilized to absorb NAPL present in wells MW-1, MW-13, and MW-14. Since the expansion of the monitoring well network, and the increase in site monitoring and NAPL recovery activities in 2008, approximately 8.573 gallons of NAPL have been recovered from the site monitoring well network, approximately 0.44 gallons of which were recovered during this reporting period.Groundwater samples were collected from thirteen of the nineteen wells. Samples collected from wells MW-1, MW-13 on the western portion of the parcel and samples collected from wells MW-7, MW-10 and MW-11 on the eastern portion of the parcel indicated concentrations above Standards. The TVOCs ranged from 1.4ppb in well MW-2 to 9,987ppb in well MW-10.Low levels of VOCs indicated in the following wells:1. MW-2 - 1.4ppb;2. MW-3 - 1.6ppb;3. MW-3S - 41ppb;4. MW-4 - 6.7ppb;5. MW-6 - 2.9ppb;6. MW-12 - 5.1ppb;7. MW-14 - 8.5ppb.Moderatly elevated levels of VOCs were detected in samples collected from wells:8. MW-1 - 404ppb;9. MW-11 - 361ppb;10. MW-13 - 228.3ppbSignificant levels of VOCs were detected in samples collected from wells:11. MW-7 - 3,374,1 ppb slight decrease from 3,812ppb in December 2011;12. MW-10 - 9,987ppb a decrease from 16,731ppb in December 2011.In addition to expanding the monitoring well network during the next quarter, CHCI will also be initiating the bench-scale pilot study with the goal of increasing aerobic degradation, which also requires new well installation activities pursuant to the approved Work Plans.Upon completion of the delineation work for soil and groundwater impact, CHCI will evaluate evidence of natural attenuation and/or biodegradation processes at this site. AD08/22/2012: received the following e-mail from B. Moore:"Ainura - We are mailing a hard copy to you today at your office, but we have attached our eCopy for your use and Department records. we hope to install the off-site well early next month, and will advise you of our schedule!Brian D. MooreCarriageHouse Consulting, Inc.Ph: 508.315.3146Cell: 508.479.3560http://www.carriagehouseinfo.com"DL PDF copy of the report to eDocs. Will review. AD09/21/2012: Reviewed the report. It states that on June 25, 2012, CHCI personnel conducted the quarterly site groundwater monitoring including monitoring wells gauging, geochemical monitoring, NAPL recovery, and GW sample collection.During the June 2012 event, light NAPL was not detected in any of the wells monitored. During this reporting period, only passive booms were utilized to absorb NAPL present in wells MW-1,MW-13, and MW-14.CHCI collected groundwater samples from 6 wells: MW-1, MW-7, MW-10, MW-11, MW-13, and MW-14.During the sampling event of June 25, 2012, samples from all six sampled wells yielded concentrations of one or more of the targeted analytes above the Class GA Groundwater Standards. The samples collected included wells MW-1, MW-13, and MW-14 on the western portion of the site and samples from wells MW-7, MW-10, and MW-11 on the eastern portion of the site.Moderatly elevated levels of VOCs were detected in samples

SPILL NUMBER 0103168 (Continued) **S105055149**

collected from wells:1. MW-1 - 280ppb from 404ppb in March 2012;2. MW-11 - 549ppb from 361ppb;3. MW-13 - 255ppb from 228.3ppbSignificant levels of VOCs were detected in samples collected from wells:4. MW-7 - 2,080ppb a decrease from 3,374,1 ppb in March 2012;5. MW-10 - 5,809ppb a decrease from 9,987ppb in March 2012.The report states that the analytical results from the June 2012 sampling event appear to demonstrate that the magnitude of dissolved hydrocarbon concentrations in groundwater has remained relatively stable and consistent with the 2011 sampling results. The exception is in samples collected from well MW-10, whose results have demonstrated a greater degree of variability throughout the year but are still relatively consistent with previous historical sampling results.Upon completion of the delineation work for soil and groundwater impact, the remedial investigation will evaluate whether geophysical conditions in the impacted formation yield evidence of natural attenuation and/or biodegradation processes at this site. CCI states that the data contained in this report demonstrate that groundwater quality at this site, while varying over time, remains above the applicable GA Standards, confirming the necessity of the remaining remedial investigative activities from the approved work plans. AD12/07/2012: Received Groundwater Monitoring Report for the 3rd Quarter of 2012. DL the report to eDocs. Will review. AD01/14/2013: Reviewed the report. It states that on September 27, 2012, CHCI conducted the quarterly site groundwater monitoring event including monitoring well gauging, geochemical monitoring, NAPL recovery, and sample collection. CHCI collected groundwater samples from monitoring wells MW-1, MW-7, MW-10, MW-11, MW-13, MW-14, and MW-15.During the sampling event of September 27, 2012, samples from all seven of the sampled wells yielded concentrations of one or more of the targeted analytes above the Class GA Groundwater Standards. The samples collected included wells MW-1, MW-13, MW-14, and MW-15 on the western portion of the parcel and samples from wells MW-7, MW-10, and MW-11 on the eastern portion of the parcel.Well MW-15 was ND. Well MW-14 had 3.5 ppb of TVOCs.Moderatly elevated levels of VOCs were detected in samples collected from wells:1. MW-1 - 232ppb from 280ppb in June 2012;2. MW-11 - 390ppb from 549ppb in June 2012;3. MW-13 - 222ppb from 255ppb in June 2012Significant levels of VOCs were detected in samples collected from wells:4. MW-7 - 1,705ppb a decrease from 2,080ppb in June 2012;5. MW-10 - 2,144ppb a decrease from 5,809ppb in June 2012.During this reporting period, only passive booms were utilized to absorb NAPL present in wells MW-1, MW-13, and MW-14. Therefore, gauging results reflect conditions at the property upon arrival and removal of the spent or partially spent booms. The booms include one 3-inch diameter boom for MW-1, and one 1.5-inch diameter boom each for MW-13 and MW-14. All three booms were replaced on September 27, 2012 as they were at their adsorptive capacity.Since the expansion of the site-related groundwater monitoring well network, and the increase in site monitoring and NAPL recovery activities in 2008, approximately 9.713 gallons of NAPL have been recovered from the site-related groundwater monitoring well network, approximately 0.44 gallons of which were recovered during this reporting period. Recovered NAPL and absorbents continue to be stored onsite, placed inside a 55-gallon capacity drum set within a secondary containment.CHCI states that the analytical results from the September 2012 sampling event demonstrate that the magnitude of dissolved hydrocarbon concentrations in groundwater has remained relatively stable and consistent with the 2011 sampling results. The

SPILL NUMBER 0103168 (Continued) **S105055149**

exception is in samples from MW-10, whose results have demonstrated a greater degree of variability throughout the year, with the most recent sampling results yielding the lowest amount of total VOCs to date, but are still relatively consistent with previous historical sampling results. Results from well MW-14 have yielded consistently low detections, and no analytes at all were detected from the new well, MW-15. Physical and geochemical monitoring results from this eventindicate that groundwater conditions at this property are generally anaerobic, reducing, and slightly acidic.The horizontal extent of the dissolved impact associated with these two AOCs is now defined by the newly-installed MW-15 in the downgradient direction, as this well did not yield any detections of VOCs. As part of the next quarter's field activities, CHCI will be initiating the bench-scale pilot study with the goal of increasing aerobic degradation, which also requires new well installation activities pursuant to the approved Work Plans.Upon completion of the delineation work for soil and groundwater impact, the Remedial Investigation will evaluate whether geophysical conditions in the impacted formation yield evidence of natural attenuation and/or biodegradation processes at this site. CHCI will continue with remedial investigative activities at the site. AD03/15/2013: Received a Groundwater Monitoring Report - Work Plan Addendum from CHCI. DL the report to eDocs. Will review. AD03/28/2013: Reviewed the report. It states that the site now has a network of seventeen (17) groundwater monitoring wells to monitor the extent of spill impact associated with this site. On December 19, 2012, CHCI conducted the quarterly site groundwater monitoring including wells gauging, geochemical monitoring, NAPL recovery, and GW samples collection. During the December 2012 event, LNAPL was not detected in any of the site wells monitored.CHCI collected groundwater samples from 7 monitoring wells: MW-1, MW-7, MW-10, MW-11, MW-13, MW-14, and MW-15.GW data - TVOCs (ppb):Non-detect or low levels of TVOCs:Well MW-15 was ND. Well MW-14 had 20 ppb of TVOCs.Moderatly elevated levels of VOCs were detected in samples collected from wells:1. MW-1 - 264ppb an increase from 232ppb in September 2012;2. MW-11 - 724ppb an increase from 390ppb in September 2012;3. MW-13 - 248ppb an increase from 222ppb in September 2012Significant levels of VOCs were detected in samples collected from wells:4. MW-7 - 1,654ppb a decrease from 1,705ppb in September 2012;5. MW-10 - 1,756ppb a decrease from 2,144ppb in September 2012.Based on the historic GW data, CHCI proposes application of Enhanced Fluid Recovery (EFR) technique on eight selected site wells instead previously proposed chemical oxidant injection. Quarterly groundwater sampling will continue at the site. Summary report with conclusions and recommendations for further actions will be submitted to DEC.03/29/2013: called and spoke with Esther Schmaltz of CHCI regarding details of the work plan addendum. She will sens an e-mail clarifying the proposed actions. Later received the following e-mail from Ms. Schmaltz:"Ainura Doronova - Per our phone conversation here is a brief outline of the activities we will be conducting at they Ryder site next Tuesday and Wednesday:(i) Install a total of four (4) monitoring and extraction wells within the area of the former gasoline USTs within the service bays of the building at the same exact locations previously-demarcated and authorized by the Department for drilling;(ii) Perform a single EFR event utilizing all accessible wells within the on-site building (MW-7, MW-10, MW-11, MW-12, new wells: MW-16, MW-17, MW-18, MW-19);(iii) Perform one (1)

SPILL NUMBER 0103168 (Continued) **S105055149**

limited periodic monitoring event of groundwater conditions within the target area approximately two (2) weeks and approximately six (6) weeks following completion of the EFR event - select wells;Please let me know if you need any additional information. Thank you for your assistance. Regards,Estee SchmaltzCarriageHouse Consulting, Inc."Discussed the work plan addendum with J. Kolleeny of DEC. Issued and sent an approval letter to Carrie Vinch with the following comment:" If EFR will not be effective in VOCs reductions in these wells, alternative remediation technologies should be proposed for the site."DL pdf copy of the letter to eDocs. AD06/03/2013: Received 1st quarter 2013 groundwater monitoring report from CHCI. DL to eDocs. Will review. AD07/15/2013: Reviewed the report. It states that on March 14 and 15, 2013, CHCI conducted the quarterly site groundwater monitoring event; including monitoring well gauging, geochemical monitoring, NAPL recovery, and sample collection.Free product:During the March 2013 event, light NAPL was detected only in monitoring well MW-1 as a petroleum sheen. Since the expansion of the site-related groundwater monitoring well network, and the increase in site monitoring and NAPL recovery activities in 2008, approximately 10.593 gallons of NAPL have been recovered from the groundwater monitoring well network, approximately 0.44 gallons of which were recovered during this reporting period. Recovered NAPL and absorbents continue to be stored on-site, placed inside a 55-gallon capacity drum set within a secondary containment.GW sampling:Groundwater monitoring activities included the measurement of temperature, conductivity, dissolved oxygen (DO), oxidation-reduction potential (ORP), and acidity/alkalinity (pH) at nine (9) of the site's monitoring wells.CHCI collected groundwater samples from the seventeen (17) monitoring wells (MW-1, MW-2, MW-3, MW-3S, MW-4, MW-4S, MW-5, MW-6, MW-7, MW-8, MW-9, MW-10, MW-11, MW-12, MW-13, MW-14, andMW-15).GW data - TVOCs (ppb):Non-detect or low levels of TVOCs:Wells; MW-2, MW-3, MW-4, MW-4S, MW-5, MW-6, MW-8, MW-9, MW-12, MW-14 and MW-15 were ND. Moderatly elevated levels of VOCs were detected in samples collected from wells:1. MW-1 - 336 ppb an increase from 264ppb in December 2012;2. MW-13 - 236ppb a slight decrease from 248ppb December 2012Significant levels of VOCs were detected in samples collected from wells:3. MW-7 - 1,956ppb an increase from 1,654ppb in December 2012;4. MW-10 - 1389ppb a decrease from 1,756ppb in December 2012.5. MW-11 - 706 ppb a slight decrease from 724ppb in December 2012.GW data indicates that groundwater at the site localized in two areas: eastern part of the property inside the garage 9wells MW-7, MW-10 and MW-11), and the vicinity of the diesel USTs in the south-western part of the site (well MW-1 with free product and MW-13).CHCI states that the horizontal extent of the dissolved impact associated with these two areas of concern is now defined by the newly-installed MW-15 in the southwest direction. As part of the next quarter's field activities, the wells previously-authorized for installation as part of the EFR activities will be installed, and an EFR event will be scheduled and implemented at this site to expedite GW cleanup. This remediation technique is being considered in replacement or in advance of the bench-scale pilot study for chemical enhancement of aerobic and/or anaerobic degradation mechanisms previously authorized by the Department, and the degree of 'rebound' documented following the EFR activities will help further determine the degree of source area impact remaining at this parcel. NRN. AD

Remarks: took soil samples at above location - soil was saturated - now

SPILL NUMBER 0103168 (Continued) **S105055149**

waiting for samples to return

Material:

Site ID:	210326
Operable Unit ID:	1058914
Operable Unit:	01
Material ID:	327294
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	True
Site ID:	210326
Operable Unit ID:	1058914
Operable Unit:	01
Material ID:	2106684
Material Code:	1213A
Material Name:	MTBE (METHYL-TERT-BUTYL ETHER)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	True
Site ID:	210326
Operable Unit ID:	1058914
Operable Unit:	01
Material ID:	327293
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	True

Tank Test:

AQ224 **10-22 44TH RD** **NY LTANKS** **S101341172**
WNW **10-22 44TH ROAD** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.465 mi.
2455 ft. **Site 2 of 2 in cluster AQ**

Relative:
Higher

Actual:
14 ft.

LTANKS:

Site ID:	191465
Spill Number/Closed Date:	9411116 / 1/20/1995
Spill Date:	11/18/1994
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial

10-22 44TH RD (Continued) **S101341172**

Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1/20/1995
Cleanup Meets Standard:	True
SWIS:	4101
Investigator:	MMMULQUE
Referred To:	Not reported
Reported to Dept:	11/18/1994
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1/27/1995
Spill Record Last Update:	3/17/2003
Spiller Name:	Not reported
Spiller Company:	RYDER TRUCK
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	159694
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MULQUEEN"10/10/95: This is additional information about material spilled from the translation of the old spill file: VIRGIN MOTOR OIL.
Remarks:	E.I.K. FOR VIRGIN MOTOR OIL UST TANK 580GL. LEAK ABOVE THE LEVEL OF THE OIL IN THE TANK. FOUND THAT THE VENT PIPE WAS BROKEN -VENT PIPE REPLACED, TANK RETESTED

Material:

Site ID:	191465
Operable Unit ID:	1008988
Operable Unit:	01
Material ID:	376978
Material Code:	0022
Material Name:	Waste Oil/Used Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	191465
Spill Tank Test:	1543371
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0

10-22 44TH RD (Continued) **S101341172**

Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

---

225 NE 1/4-1/2 0.473 mi. 2495 ft.

NYCTA - SUPERIOR REED BLDG
29-50 NORTHERN BLVD
LONG ISLAND CITY, NY 11101

RCRA NonGen / NLR 1004762971
FINDS NYR000102319
NY LTANKS
NY MANIFEST

Relative: Higher

Actual: 24 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NYCTA - SUPERIOR REED BLDG
Facility address:	29-50 NORTHERN BLVD LONG ISLAND CITY, NY 11101
EPA ID:	NYR000102319
Mailing address:	JAY ST ROOM 819 BROOKLYN, NY 11201
Contact:	JAMES CRANDALL
Contact address:	JAY ST ROOM 819 BROOKLYN, NY 11201
Contact country:	US
Contact telephone:	(718) 243-4581
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NEW YORK CITY TRANSIT
Owner/operator address:	370 JAY ST ROOM 819 BROOKLYN, NY 11201
Owner/operator country:	US
Owner/operator telephone:	(718) 243-4581
Legal status:	Other
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	NEW YORK CITY TRANSIT
Owner/operator address:	370 JAY ST ROOM 819 BROOKLYN, NY 11201
Owner/operator country:	US
Owner/operator telephone:	(718) 243-4581
Legal status:	Other
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No

NYCTA - SUPERIOR REED BLDG (Continued) **1004762971**

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCTA - SUPERIOR REED BLDG
Classification: Not a generator, verified

Date form received by agency: 11/27/2001
Facility name: NYCTA - SUPERIOR REED BLDG
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110012185349

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

LTANKS:
Site ID: 292496
Spill Number/Closed Date: 9100729 / 11/30/2000
Spill Date: 4/18/1991
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 4101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 4/18/1991
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported

NYCTA - SUPERIOR REED BLDG (Continued) **1004762971**

Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	4/23/1991
Spill Record Last Update:	12/30/2002
Spiller Name:	Not reported
Spiller Company:	URS CONSULTANTS
Spiller Address:	282 DELAWARE AVE
Spiller City,St,Zip:	BUFFALO, NY 14202
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	236777
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE"SEE ALSO 94-08603. sEE FILETransfered from Hale to Tibbe.
Remarks:	5K TANK FAILED PETRO TITE WITH A GROSS LEAK, TANK OUT OF SERVICE FOR 12YRS, NO ACTION YET DETERMINED, TANK TEST WAS DONE WITH WATER.

Material:

Site ID:	292496
Operable Unit ID:	954268
Operable Unit:	01
Material ID:	426913
Material Code:	0002A
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	292496
Spill Tank Test:	1538471
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

NY MANIFEST:

EPA ID:	NYR000102319
Country:	USA
Mailing Name:	NYCTA - SUPERIOR REED BLDG
Mailing Contact:	N/S
Mailing Address:	370 JAY ST RM 819
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN

NYCTA - SUPERIOR REED BLDG (Continued) **1004762971**

Mailing State:	NY
Mailing Zip:	11201
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-243-4581

Document ID:	NJA3185837
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	11/28/2001
Trans1 Recv Date:	11/28/2001
Trans2 Recv Date:	12/07/2001
TSD Site Recv Date:	12/07/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000102319
Trans1 EPA ID:	NJD002200046
Trans2 EPA ID:	Not reported
TSDF ID:	H10376
Waste Code:	F004 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2001

AR226 **RESIDANCE** **NY LTANKS** **S108957731**
NW **1120 43RD ROAD** **N/A**
1/4-1/2 **QUEENS, NY**
0.473 mi.
2497 ft. **Site 1 of 2 in cluster AR**

Relative:
Higher

Actual:
16 ft.

LTANKS:

Site ID:	389866
Spill Number/Closed Date:	0708879 / 12/19/2007
Spill Date:	11/14/2007
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	11/14/2007
CID:	404
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	11/14/2007

RESIDANCE (Continued) **S108957731**

Spill Record Last Update:	12/19/2007
Spiller Name:	MARLON JOSEPH
Spiller Company:	RESIDANCE
Spiller Address:	1120 43RD ROAD
Spiller City,St,Zip:	QUEENS, NY
Spiller County:	001
Spiller Contact:	MARLON JOSEPH
Spiller Phone:	(718) 624-4842
Spiller Extention:	112
DEC Region:	2
DER Facility ID:	339444
DEC Memo:	11/20/07 bf: Sent ttf letter to:Harold RosenbergJ&B Realty LLC216 Cedar AvenueHewlett Bay Park, NY 1155712/13/07 Received call from Mohammad 718-784-5210. Tank was retested by PTC and passed. They did not know of 2nd fillport, so 1st test result was a failure. I told him to send a letter from PTC explaining this and the tank test results. bf12/19/07 Received letter from PTC by fax confirming the above. Passing tightness test results were included. NFA. bf
Remarks:	dry portion leak;

Material:

Site ID:	389866
Operable Unit ID:	1146990
Operable Unit:	01
Material ID:	2137380
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	389866
Spill Tank Test:	1815876
Tank Number:	1
Tank Size:	5000
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	11/14/2007
Test Method:	Horner EZ Check I or II

AR227 **X** **NY LTANKS** **S105997827**
NW **11-20 43RD RD** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.473 mi.
2497 ft. **Site 2 of 2 in cluster AR**

Relative:
Higher

Actual:
16 ft.

LTANKS:

Site ID:	300672
Spill Number/Closed Date:	0210116 / 2/28/2006
Spill Date:	1/7/2003
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	4101
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	1/7/2003
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1/7/2003
Spill Record Last Update:	2/28/2006
Spiller Name:	HAROLD ROSENBERG
Spiller Company:	Not reported
Spiller Address:	11-20 43RD RD
Spiller City,St,Zip:	LONG ISLAND CITY, NY
Spiller County:	001
Spiller Contact:	HAROLD ROSENBERG
Spiller Phone:	(718) 784-5210
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	243201
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SAWYER"ARAKHAN 1/7/03 TTF LETTER FAXED AND MAILED TO FACILITY PERSONNEL.1/7/04-Vought-Spill transferred from Vought to Austin.01/27/04 - Sawyer - Spill transferred from Austin to Sawyer.11/28/05- DEC Piper spoke w/ Harold Rosenberg, Faxed old ttf letter. He stated that work was done on tank, then it passed. He will send info.2/10/06- DEC Piper spoke w/ Harold Rosenberg again requesting info. He stated that it was sent though I have never received info. He will send it again.2/28/06- DEC Piper reviewed invoices from PTC.As per invoices and conversation w/ Joe, minor repairs were made to the system. A loose connection in the system was responsible. Closed. E-docs.
Remarks:	Not reported

Material:

Site ID:	300672
Operable Unit ID:	863330
Operable Unit:	01
Material ID:	513517
Material Code:	0001A

X (Continued) **S105997827**

Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 300672
Spill Tank Test: 1527903
Tank Number: 1
Tank Size: 5000
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

228
SSE
1/4-1/2
0.474 mi.
2501 ft.

Relative:
Lower

Actual:
12 ft.

THYPIN STEEL
49-49 30TH STREET
LONG ISLAND CITY, NY

NY LTANKS **U000416651**
NY AST **N/A**
NY HIST AST
NY MANIFEST
NY Spills

LTANKS:
Site ID: 88995
Spill Number/Closed Date: 9312128 / 1/14/1994
Spill Date: 1/14/1994
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: 1/14/1994
Cleanup Meets Standard: True
SWIS: 4101
Investigator: CAMMISA
Referred To: Not reported
Reported to Dept: 1/14/1994
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/18/1994
Spill Record Last Update: 9/30/2004
Spiller Name: Not reported
Spiller Company: WHALECO FUEL OIL
Spiller Address: 1 COFFEY ST.
Spiller City,St,Zip: BROOKLYN, NY
Spiller County: 001
Spiller Contact: Not reported

THYPIN STEEL (Continued) **U000416651**

Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	81338
DEC Memo:	Not reported
Remarks:	WILL SEND AT SOMEONE W/ SPEEDY DRY.

Material:

Site ID:	88995
Operable Unit ID:	990742
Operable Unit:	01
Material ID:	391124
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Facility Id:	2-116211
Program Type:	PBS
UTM X:	589645.39324999996
UTM Y:	4510449.5729999999
Expiration Date:	N/A
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	3896
Affiliation Type:	Facility Owner
Company Name:	MANHASSET BAY ASSOC
Contact Type:	MANAGER
Contact Name:	RICHARD THYPIN
Address1:	P.O. BOX 309
Address2:	Not reported
City:	PRINCETON
State:	NJ
Zip Code:	08542
Country Code:	001
Phone:	(718) 937-2700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	7/30/2007

Site Id:	3896
Affiliation Type:	Mail Contact

THYPIN STEEL (Continued) **U000416651**

Company Name:	MANHASSET BAY ASSOC
Contact Type:	Not reported
Contact Name:	RICHARD THYPIN
Address1:	P.O. BOX 309
Address2:	Not reported
City:	PRINCETON
State:	NJ
Zip Code:	08542
Country Code:	001
Phone:	(609) 497-0796
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	3896
Affiliation Type:	On-Site Operator
Company Name:	MBA LONG ISLAND CITY
Contact Type:	Not reported
Contact Name:	MBA LONG ISLAND CITY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(609) 498-0796
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	3896
Affiliation Type:	Emergency Contact
Company Name:	MANHASSET BAY ASSOC
Contact Type:	Not reported
Contact Name:	RICHARD THYPIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(609) 497-0796
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	004
Tank Id:	55775
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

THYPIN STEEL (Continued) **U000416651**

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
B05 - Tank External Protection - Jacketed

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/01/2003
Register:	True
Modified By:	KXTANG
Last Modified:	07/30/2007
Material Name:	#2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number:	2-116211
SWIS Code:	6301
Operator:	THYPIN STEEL CO INC
Facility Phone:	(718) 937-2700
Facility Addr2:	49049 30TH STREET
Facility Type:	TRUCKING/TRANSPORTATION
Emergency:	GARY GOLDIN
Emergency Tel:	(718) 967-3780
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	MANHASSET BAY ASSOC
Owner Address:	C/O THYPIN STEEL CO. 49-49 30TH STREET
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Federal ID:	Not reported
Owner Tel:	(718) 937-2700
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	Not reported
Mailing Name:	MANHASSET BAY ASSOC
Mailing Address:	C/O THYPIN STEEL CO
Mailing Address 2:	49-49 30TH STREET
Mailing City,St,Zip:	LONG ISLAND CITY, NY 11101
Mailing Telephone:	(718) 937-2700
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	Not reported

THYPIN STEEL (Continued) **U000416651**

Expiration:	03/24/2002
Renew Flag:	False
Renew Date:	11/13/2001
Total Capacity:	2000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City Code:	01
Region:	2

Tank ID:	004
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	2000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	0
Tank External:	05
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	00
Tank Containment:	None
Leak Detection:	00
Overfill Protection:	06
Dispenser Method:	Gravity
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

NY MANIFEST:

EPA ID:	NYR000121863
Country:	USA
Mailing Name:	THYPIN STEEL BUILDING FORMER
Mailing Contact:	MBA LLC
Mailing Address:	215 NASSAU ST
Mailing Address 2:	Not reported
Mailing City:	PRINCETON
Mailing State:	NJ
Mailing Zip:	08542
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	609-658-5395

THYPIN STEEL (Continued) **U000416651**

NY MANIFEST:

No Manifest Records Available

SPILLS:

Facility ID:	9607116
DER Facility ID:	81338
Facility Type:	ER
Site ID:	88996
DEC Region:	2
Spill Date:	9/5/1996
Spill Number/Closed Date:	9607116 / 12/29/2005
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	EXHAMPST
Referred To:	Not reported
Reported to Dept:	9/5/1996
CID:	204
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/5/1996
Spill Record Last Update:	12/29/2005
Spiller Name:	MR GAMA
Spiller Company:	TYPHIN STEEL
Spiller Address:	49-49 30TH STREET
Spiller City,St,Zip:	LONG ISLAND CITY, NY
Spiller Company:	001
Contact Name:	BOB DECK
Contact Phone:	(718) 624-4842
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ROMMEL"This Spill cleanup project has been reassigned from DEC (Sigona)to Rommel on 2/2/2004.12/29/05 Transferred to E. Hampston via Spills Initiative. Contacted possible owner Richard Typhin (#609-497-0796) and left message regarding spill, requested call back.Site owner responded. Spill cleaned. Faxing disposal receipts (filed in eDocs).
Remarks:	Cross over line broke

Material:

Site ID:	88996
Operable Unit ID:	1038272
Operable Unit:	01
Material ID:	346384
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50
Units:	Gallons

THYPIN STEEL (Continued) **U000416651**

Recovered:	50
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9607319
DER Facility ID:	81338
Facility Type:	ER
Site ID:	88997
DEC Region:	2
Spill Date:	9/10/1996
Spill Number/Closed Date:	9607319 / 9/16/1996
Spill Cause:	Human Error
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	LUCE
Referred To:	Not reported
Reported to Dept:	9/10/1996
CID:	205
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/10/1996
Spill Record Last Update:	12/24/2003
Spiller Name:	CALLER
Spiller Company:	WHALECO FUEL OIL
Spiller Address:	1 COFFEY STREET
Spiller City,St,Zip:	BROOKLYN, NY 11231-
Spiller Company:	001
Contact Name:	THYPIN STEEL INC.
Contact Phone:	(718) 706-4557
DEC Memo:	Not reported
Remarks:	tank overfill.

Material:

Site ID:	88997
Operable Unit ID:	1038480
Operable Unit:	01
Material ID:	346588
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15
Units:	Gallons
Recovered:	15
Resource Affected:	Not reported
Oxygenate:	False

THYPIN STEEL (Continued) **U000416651**

Tank Test:

Facility ID:	9808784
DER Facility ID:	81338
Facility Type:	ER
Site ID:	70479
DEC Region:	2
Spill Date:	10/15/1998
Spill Number/Closed Date:	9808784 / 12/8/1998
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	MMMULQUE
Referred To:	Not reported
Reported to Dept:	10/15/1998
CID:	382
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	10/15/1998
Spill Record Last Update:	12/8/1998
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	ST
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MULQUEEN"PTC HIRED BY TYPHIN STEEL TO DO CLEAN UP.
Remarks:	CALLER STATES THAT HE PARKS IFO THE ABOVE ADDRESS AND HE NOTICED A LARGE PUDDLE OF DIESEL FUEL IFO BUSINESS.

Material:

Site ID:	70479
Operable Unit ID:	1069974
Operable Unit:	01
Material ID:	316269
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

THYPIN STEEL (Continued) **U000416651**

Tank Test:

229
NNE
1/4-1/2
0.478 mi.
2522 ft.

COMMERCIAL BUILDING **NY LTANKS** **S107410496**
40-23 24TH ST' **N/A**
LONG ISLAND CITY, NY

Relative:
Higher

Actual:
32 ft.

LTANKS:

Site ID:	352289
Spill Number/Closed Date:	0506977 / 1/5/2006
Spill Date:	9/8/2005
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	9/8/2005
CID:	409
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	9/8/2005
Spill Record Last Update:	2/3/2006
Spiller Name:	VINNY LOVARI
Spiller Company:	COMMERCIAL BUILDING
Spiller Address:	40-23 24TH ST'
Spiller City,St,Zip:	LONG ISLAND CITY, NY
Spiller County:	001
Spiller Contact:	VINNY LOVARI
Spiller Phone:	(718) 967-9424
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	299586
DEC Memo:	11/30/2005 Sangesland spoke to rep at Island tank. She said the site was dug out and endpoints were clean. She said a closure report would be sent ASAP.1/4/06-Hiralkumar Patel. Here is the summary of the report from Island Environmental Tank, Inc.* According to owner, the tank has previously been used for the purpose of storing #2 heating oil and owner doesn't know when this tank was installed.* UST was installed horizontally in the backfill material, with the top of the tank located approximately 4' below the surface.* A 1080 gal. capacity tank was removed in the presence of Mr. Vinny Lovari of Island Tank Enviromental. After removal from cavity, tank has been cut and washed and removed oil and water mixture with vac/truck.* No groundwater or static surface water was encountered in the tank cavity.* Tank had pits and holes.* Tank cavity was excavated approximately 30 cubic yard of soil in 55 gal. drums and disposed at Jamaica Recycling Inc. Jamaica, NY.* Tank cavity was backfilled and

COMMERCIAL BUILDING (Continued) **S107410496**

compacted in place.* 6 samples were taken out from cavity and tested at Severn Trent Laboratory, Edison, NJ.* The metal tank and all metal tank system components were removed from teh owner's property and disposed of as scrap metal at John Iron & Metal Co.,Inc. 33 Arthur Kill Road, Staten Island, NY.1/5/06-Hiralkumar Patel. No Further Action required letter has been sent to Mr. John Domenico.Case closed as per Mr. Jeff Vought.02/03/06-Hiralkumar Patel. Send out NFA again through fax (212-689-6082) as per John's request.

Remarks: tnak removal found oil on the tank. THERE IS 3 OR 4 DRUMS THAT NEES TO BE REMOVED. THE TANK HAS BEEN CUT UP.

Material:

Site ID:	352289
Operable Unit ID:	1109795
Operable Unit:	01
Material ID:	2099814
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

AP230 **43-41 32ND PLACE** **NY LTANKS** **S100560351**
East **43-41 32ND PLACE** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.481 mi.
2539 ft. **Site 4 of 4 in cluster AP**

Relative:
Higher

Actual:
37 ft.

LTANKS:

Site ID:	307482
Spill Number/Closed Date:	9303078 / 6/25/1993
Spill Date:	6/8/1993
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	6/25/1993
Cleanup Meets Standard:	True
SWIS:	4101
Investigator:	GRIFFIN
Referred To:	Not reported
Reported to Dept:	6/8/1993
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	6/9/1993

43-41 32ND PLACE (Continued) **S100560351**

Spill Record Last Update:	7/19/1993
Spiller Name:	Not reported
Spiller Company:	ACCO USA INC.
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	248321
DEC Memo:	Not reported
Remarks:	SOIL FOUND UNDER 1200 GAL U/G TANK - TO STOCK PILE SOIL AND SEND SAMPLES TO LAB.

Material:

Site ID:	307482
Operable Unit ID:	981294
Operable Unit:	01
Material ID:	400169
Material Code:	0002A
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

231
NE
1/4-1/2
0.497 mi.
2623 ft.

KAL REALTY **NY LTANKS** **S103478273**
29-24 40TH AVE **N/A**
LONG ISLAND CITY, NY

Relative:
Higher

Actual:
29 ft.

LTANKS:

Site ID:	172099
Spill Number/Closed Date:	9806658 / 6/15/2005
Spill Date:	8/28/1998
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	GWHEITZM
Referred To:	Not reported
Reported to Dept:	8/31/1998
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported

KAL REALTY (Continued) **S103478273**

Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	8/31/1998
Spill Record Last Update:	6/15/2005
Spiller Name:	CLIFF WENGLEN
Spiller Company:	KAL REALTY
Spiller Address:	29-24 40TH AV
Spiller City,St,Zip:	LONG ISLAND CITY, NY
Spiller County:	001
Spiller Contact:	CLIFF WENGLEN
Spiller Phone:	(718) 784-2842
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	144848
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "M TIBBE"NO PREVIOUS SPILL REPORT6/15/05 Heitzman: See PBS #2-23865. 3000-gallon #2 fuel tank closed January 1999, and replaced with 1500-gallon above ground, suction piped #2 fuel tank. Spill closed.
Remarks:	TANK PREVIOUSLY TESTED AND FAILED - ON RETEST FAILED AGAIN

Material:

Site ID:	172099
Operable Unit ID:	1067880
Operable Unit:	01
Material ID:	317808
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	172099
Spill Tank Test:	1546206
Tank Number:	1
Tank Size:	0
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Horner EZ Check I or II

232
NE
1/4-1/2
0.499 mi.
2636 ft.

CLOSED-LACKOF RECENT INFO
29024 40TH AVENUE
LONG ISLAND CITY, NY

NY LTANKS **S100144984**
N/A

Relative:
Higher

Actual:
27 ft.

LTANKS:

Site ID:	125139
Spill Number/Closed Date:	8709369 / 3/13/2003
Spill Date:	2/3/1988
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	2/3/1988
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2/10/1988
Spill Record Last Update:	3/13/2003
Spiller Name:	Not reported
Spiller Company:	KAL REALTY (OWNER)
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	108274
DEC Memo:	Not reported
Remarks:	CONTACT: CLIFFORD WENGLIM AT KAL REALTY. 3K TANK SYSTEM FAILED PETROTITE/ LEAK RATE = -.673GPHCLOSED DUE TO LACK OF ANY RECENT INFO - DOES NOT MEET ANY CLEANUP REQUIREMENTS.

Material:

Site ID:	125139
Operable Unit ID:	914629
Operable Unit:	01
Material ID:	464694
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Gallons
Recovered:	Yes
Resource Affected:	Not reported
Oxygenate:	False

CLOSED-LACKOF RECENT INFO (Continued) **S100144984**

Tank Test:
- Site ID: 125139
- Spill Tank Test: 1533169
- Tank Number: Not reported
- Tank Size: 0
- Test Method: 00
- Leak Rate: 0
- Gross Fail: Not reported
- Modified By: Spills
- Last Modified: 10/1/2004
- Test Method: Unknown

233
NE
1/2-1
0.576 mi.
3042 ft.

FRESH CLEANERS & LAUNDRY INC
39-26 30TH ST
LONG ISLAND CITY, NY 11101

RCRA-SQG **1001125032**
NY SHWS **NYR000034363**
NY MANIFEST
NY BROWNFIELDS

Relative:
Higher

Actual:
35 ft.

RCRA-SQG:
- Date form received by agency: 05/01/2007
- Facility name: FRESH CLEANERS & LAUNDRY INC
- Facility address: 39-26 30TH ST
  LONG ISLAND CITY, NY 11101
- EPA ID: NYR000034363
- Mailing address: 30TH ST
  LONG ISLAND CITY, NY 11101
- Contact: MOON S PARK
- Contact address: 30TH ST
  LONG ISLAND CITY, NY 11101
- Contact country: US
- Contact telephone: (718) 786-9734
- Contact email: Not reported
- EPA Region: 02
- Land type: Private
- Classification: Small Small Quantity Generator
- Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
- Owner/operator name: FRESH CLEANERS & LAUNDRY INC
- Owner/operator address: Not reported
  Not reported
- Owner/operator country: Not reported
- Owner/operator telephone: Not reported
- Legal status: Private
- Owner/Operator Type: Owner
- Owner/Op start date: 03/16/2007
- Owner/Op end date: Not reported

- Owner/operator name: MOON S PARK
- Owner/operator address: Not reported
  Not reported
- Owner/operator country: Not reported

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 03/16/2007
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/30/2007
Facility name: FRESH CLEANERS & LAUNDRY INC
Classification: Small Quantity Generator

Date form received by agency: 01/01/2006
Facility name: FRESH CLEANERS & LAUNDRY INC
Site name: BRIDGE CLEANERS
Classification: Small Quantity Generator

Date form received by agency: 01/13/1997
Facility name: FRESH CLEANERS & LAUNDRY INC
Site name: BRIDGE CLEANERS
Classification: Small Quantity Generator

Hazardous Waste Summary:
Waste code: D007
Waste name: CHROMIUM

Waste code: D039
Waste name: TETRACHLOROETHYLENE

Waste code: D040
Waste name: TRICHLOROETHYLENE

Waste code: F002
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:

Regulation violated:	Not reported
Area of violation:	Generators - General
Date violation determined:	04/27/2006
Date achieved compliance:	07/02/2007
Violation lead agency:	EPA
Enforcement action:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date:	11/16/2012
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	EPA
Proposed penalty amount:	Not reported
Final penalty amount:	35098
Paid penalty amount:	Not reported

Regulation violated:	Not reported
Area of violation:	Generators - General
Date violation determined:	04/27/2006
Date achieved compliance:	07/02/2007
Violation lead agency:	EPA
Enforcement action:	INITIAL 3008(A) COMPLIANCE
Enforcement action date:	03/29/2007
Enf. disposition status:	Dropped
Enf. disp. status date:	10/01/2011
Enforcement lead agency:	EPA
Proposed penalty amount:	35098
Final penalty amount:	Not reported
Paid penalty amount:	Not reported

Regulation violated:	Not reported
Area of violation:	Generators - General
Date violation determined:	04/27/2006
Date achieved compliance:	07/02/2007
Violation lead agency:	EPA
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	05/18/2006
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	EPA
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported

Evaluation Action Summary:

Evaluation date:	10/01/2011
Evaluation:	NOT A SIGNIFICANT NON-COMPLIER
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	EPA

Evaluation date:	08/18/2011
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 07/02/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 05/29/2006
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 04/27/2006
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 07/02/2007
Evaluation lead agency: EPA

Evaluation date: 08/28/2002
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

SHWS:
Program: HW
Site Code: 440982
Classification: N
Region: 2
Acres: .173
HW Code: 241127
Record Add: 10/15/2010
Record Upd: 10/31/2013
Updated By: MJKOMORO
Site Description: LOCATION: The site is located in an urban area. Buildings within the city block are primarily commercial. There are residential units including a three story apt building along 29th Street. The downgradient block also contains a limited number of residential buildings. See Site No. C241127SITE FEATURES: A 7500 square foot one-story concrete building occupies the entire lot. The back of the lot abuts adjacent buildings. The building has no basement.CURRENT ZONING: This section of Long Island City is zoned Special Purpose District which allows mixed residential and commercial use. The specific designation for the site is M1-3/R7X. HISTORICAL USES: The site was occupied by a commercial laundry and dry cleaner up until 2011, when the DEC investigation of the property began. Records indicate at least 10 years of use as a dry-cleaner. The building is currently vacant. SITE HYDROLOGY/GEOLOGY: Groundwater elevation levels vary from 11.04 AMSL to 10.01 AMSL in the vicinity of the site. Soils in the area are primarily sand.
Env Problem: NATURE AND EXTENT OF CONTAMINATION: Samples collected in 2009 on the property adjacent to the Bridge Cleaners site identified dry-cleaning related compounds trichloroethene (TCE)and tetrachloroethene (PCE) in the soil vapor and groundwater. There was no evidence of PCE use on the adjacent property. The higher results were closer to the common

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

property line. PCE was found at 910 ppb in groundwater along the common property boundary, decreasing to 120 ppb approximately 100 feet away. PCE was measured at 16,900 ug/m3 in the soil vapor. The groundwater standard for both PCE and TCE is 5 ppb. In April 2011, the site operator obtained 2 soil samples from beneath the Bridge Cleaners slab and found tetrachloroethene (PCE) at 3.45 ppm and 0.757 ppm. The unrestricted soil cleanup objective is 1.3ppm for PCE. In September 2011, the owner independently obtained samples of soils and groundwater under the building,and provided results to DEC in November 2011. The three groundwater results under the building were 537 ppb, 841 ppb and 1470 ppb PCE. Fifteen soil samples were below the unrestricted soil cleanup objectives for PCE. Groundwater samples also contained TCE in the 11-12.5 ppb range. After unsuccessfully attempting to obtain site access for a more thorough investigation, NYSDEC conducted an offsite investigation in February 2012. Groundwater elevations show groundwater flow from northeast to southwest. Concentrations of PCE and TCE upgradient of the site were approximately 21 ppb and 1 ppb respectively. Downgradient concentrations were 440 ppb and 32 ppb respectively. One of 14 soil samples, at side gradient monitoring well MW-4, contained PCE at 3.3 ppm. The depth of this contamination was 29-30 feet below grade.

Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	On-Site Operator
Sub Type:	03
Owner Name:	Bridge Cleaners
Owner Company:	Bridge Cleaners
Owner Address:	39-26 30th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	01
Owner Name:	Not reported
Owner Company:	Zhong Chaung Properties LLC
Owner Address:	37-24 30th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

NY MANIFEST:
EPA ID: NYR000034363
Country: USA
Mailing Name: BRIDGE CLEANERS
Mailing Contact: YOUNG YOO
Mailing Address: 39-26 30TH ST
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-706-1077

Document ID: NYC4872317
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NYGF2859
Trans2 State ID: MO001
Generator Ship Date: 970925
Trans1 Recv Date: 970925
Trans2 Recv Date: 970930
TSD Site Recv Date: 971001
Part A Recv Date: 971103
Part B Recv Date: 971024
Generator EPA ID: NYR000034363
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: MOD095038998
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 97

Document ID: NYC5907644
Manifest Status: Not reported
Trans1 State ID: SCD987574647
Trans2 State ID: ILD984908202
Generator Ship Date: 09/23/1999
Trans1 Recv Date: 09/23/1999
Trans2 Recv Date: 09/23/1999
TSD Site Recv Date: 10/01/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000034363
Trans1 EPA ID: OHD980587364
Trans2 EPA ID: Not reported
TSDF ID: T104414

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00780
Units:	P - Pounds
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	99

Document ID:	NYC5499213
Manifest Status:	Not reported
Trans1 State ID:	ILD984908202
Trans2 State ID:	SCD987574647
Generator Ship Date:	01/12/1999
Trans1 Recv Date:	01/12/1999
Trans2 Recv Date:	01/13/1999
TSD Site Recv Date:	01/19/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000034363
Trans1 EPA ID:	OHD980587364
Trans2 EPA ID:	Not reported
TSDF ID:	NYLP3931
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00585
Units:	P - Pounds
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	99

Document ID:	NYC5555621
Manifest Status:	Not reported
Trans1 State ID:	ILD984908202
Trans2 State ID:	SCD987574647
Generator Ship Date:	05/07/1999
Trans1 Recv Date:	05/07/1999
Trans2 Recv Date:	05/12/1999
TSD Site Recv Date:	05/16/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000034363
Trans1 EPA ID:	OHD980587364
Trans2 EPA ID:	Not reported
TSDF ID:	AM6252NY
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	01560
Units:	P - Pounds
Number of Containers:	085
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	99

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Document ID:	NYC5565598
Manifest Status:	Not reported
Trans1 State ID:	ILD984908202
Trans2 State ID:	SCD987574647
Generator Ship Date:	03/16/1999
Trans1 Recv Date:	03/16/1999
Trans2 Recv Date:	03/17/1999
TSD Site Recv Date:	03/19/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000034363
Trans1 EPA ID:	OHD980587364
Trans2 EPA ID:	Not reported
TSDF ID:	LP3931NY
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00390
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	99

Document ID:	NYC5892254
Manifest Status:	Not reported
Trans1 State ID:	ILD984908202
Trans2 State ID:	SCD987574647
Generator Ship Date:	08/24/1999
Trans1 Recv Date:	08/24/1999
Trans2 Recv Date:	09/01/1999
TSD Site Recv Date:	09/08/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000034363
Trans1 EPA ID:	OHD980587364
Trans2 EPA ID:	Not reported
TSDF ID:	AM6252NY
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00390
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	99

Document ID:	NYC5679066
Manifest Status:	Not reported
Trans1 State ID:	ILD984908202
Trans2 State ID:	SCD987574647
Generator Ship Date:	07/02/1999
Trans1 Recv Date:	07/02/1999
Trans2 Recv Date:	07/07/1999
TSD Site Recv Date:	07/15/1999
Part A Recv Date:	Not reported

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Part B Recv Date: Not reported
Generator EPA ID: NYR000034363
Trans1 EPA ID: OHD980587364
Trans2 EPA ID: Not reported
TSDF ID: AM6252NY
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00480
Units: P - Pounds
Number of Containers: 004
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99

Document ID: NYC5933542
Manifest Status: Not reported
Trans1 State ID: ILD984908202
Trans2 State ID: SCD987574647
Generator Ship Date: 11/16/1999
Trans1 Recv Date: 11/16/1999
Trans2 Recv Date: 11/24/1999
TSD Site Recv Date: 11/30/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000034363
Trans1 EPA ID: OHD980587364
Trans2 EPA ID: Not reported
TSDF ID: AM6252NY
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00390
Units: P - Pounds
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99

Document ID: NYC6918390
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: NJD071629976
Generator Ship Date: 11/05/2002
Trans1 Recv Date: 11/05/2002
Trans2 Recv Date: 11/08/2002
TSD Site Recv Date: 11/11/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000034363
Trans1 EPA ID: OHD980587364
Trans2 EPA ID: Not reported
TSDF ID: NY384168J
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00975
Units: P - Pounds
Number of Containers: 003

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2002

Document ID: NYC6740561
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: NJD071629976
Generator Ship Date: 07/25/2002
Trans1 Recv Date: 07/25/2002
Trans2 Recv Date: 08/02/2002
TSD Site Recv Date: 08/02/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000034363
Trans1 EPA ID: OHD980587364
Trans2 EPA ID: Not reported
TSDF ID: NYGF1411
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00390
Units: P - Pounds
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2002

Document ID: NYC6806575
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: NJD071629976
Generator Ship Date: 06/04/2002
Trans1 Recv Date: 06/04/2002
Trans2 Recv Date: 06/07/2002
TSD Site Recv Date: 06/07/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000034363
Trans1 EPA ID: OHD980587364
Trans2 EPA ID: Not reported
TSDF ID: NY94885JE
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00585
Units: P - Pounds
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2002

Document ID: NYC6660584
Manifest Status: Not reported
Trans1 State ID: SCR000075150

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Trans2 State ID:	Not reported
Generator Ship Date:	02/09/2002
Trans1 Recv Date:	02/09/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/15/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000034363
Trans1 EPA ID:	OHD980587364
Trans2 EPA ID:	Not reported
TSDF ID:	NJXAB6384
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00780
Units:	P - Pounds
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2002

Document ID:	NYG0325764
Manifest Status:	Not reported
Trans1 State ID:	NJ420
Trans2 State ID:	Not reported
Generator Ship Date:	04/12/2004
Trans1 Recv Date:	04/12/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/15/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000034363
Trans1 EPA ID:	NJD000564906
Trans2 EPA ID:	Not reported
TSDF ID:	NJD000564
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00390
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYG2019366
Manifest Status:	Not reported
Trans1 State ID:	NJ420
Trans2 State ID:	Not reported
Generator Ship Date:	11/12/2004
Trans1 Recv Date:	11/12/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/18/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000034363
Trans1 EPA ID:	NJD000564906

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Trans2 EPA ID: Not reported
TSDF ID: NJD000564
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00090
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2004

Document ID: NYG2019618
Manifest Status: Not reported
Trans1 State ID: NJ420
Trans2 State ID: Not reported
Generator Ship Date: 09/03/2004
Trans1 Recv Date: 09/03/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/09/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000034363
Trans1 EPA ID: NJD000564906
Trans2 EPA ID: Not reported
TSDF ID: NJD000564
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00390
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2004

Document ID: NYG2018214
Manifest Status: Not reported
Trans1 State ID: NJ420
Trans2 State ID: Not reported
Generator Ship Date: 05/27/2004
Trans1 Recv Date: 05/27/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/02/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000034363
Trans1 EPA ID: NJD000564906
Trans2 EPA ID: Not reported
TSDF ID: NJD000564
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00520
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Year: 2004

Document ID: NYG2018745
Manifest Status: Not reported
Trans1 State ID: NJ420
Trans2 State ID: Not reported
Generator Ship Date: 07/27/2004
Trans1 Recv Date: 07/27/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/29/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000034363
Trans1 EPA ID: NJD000564906
Trans2 EPA ID: Not reported
TSDF ID: NJD000564
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00650
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2004

Document ID: NYG2019114
Manifest Status: Not reported
Trans1 State ID: NJ420
Trans2 State ID: Not reported
Generator Ship Date: 10/11/2004
Trans1 Recv Date: 10/11/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/14/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000034363
Trans1 EPA ID: NJD000564906
Trans2 EPA ID: Not reported
TSDF ID: NJD000564
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00780
Units: P - Pounds
Number of Containers: 006
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2004

Document ID: NYG4447602
Manifest Status: Not reported
Trans1 State ID: NJD000564906
Trans2 State ID: Not reported
Generator Ship Date: 02/24/2006
Trans1 Recv Date: 02/24/2006

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/03/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000034363
Trans1 EPA ID:	NJ420
Trans2 EPA ID:	Not reported
TSDF ID:	NJD000564906
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00520
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2006

Document ID:	NYG4242249
Manifest Status:	Not reported
Trans1 State ID:	NJD000564906
Trans2 State ID:	Not reported
Generator Ship Date:	07/27/2006
Trans1 Recv Date:	07/27/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/04/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000034363
Trans1 EPA ID:	NJ420
Trans2 EPA ID:	Not reported
TSDF ID:	NJD000564906
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00080
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00390
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00160
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2006

Click this hyperlink while viewing on your computer to access
118 additional NY_MANIFEST: record(s) in the EDR Site Report.

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

BROWNFIELDS:
Program: BCP
Site Code: 480014
Site Description: LOCATION: This is an off-site of the The Bridge Cleaners site located at 39-26 30th Street in Long Island City, an urban area. SITE FEATURES: A 7500 square foot one-story concrete building occupies the entire lot. The back of the lot abuts adjacent buildings. The building has no basement.CURRENT ZONING: This section of Long Island City is zoned Special Purpose District which allows mixed residential and commercial use. The specific designation for the site is M1-3/R7X. Buildings within the city block are primarily commercial. There are residential units including a three story apt building along 29th Street. The downgradient block also contains a limited number of residential buildings.HISTORICAL USES: The site was occupied by a commercial laundry and dry cleaner up until 2011, when the DEC investigation of the property began. Records indicate at least 10 years of use as a dry-cleaner. The building is currently vacant. SITE HYDROLOGY/GEOLOGY: Groundwater elevation levels vary from 11.04 AMSL to 10.01 AMSL in the vicinity of the site. Soils in the area are primarily sand.
Env Problem: NATURE AND EXTENT OF CONTAMINATION: Samples collected in 2009 on the property adjacent to the Bridge Cleaners site identified dry-cleaning related compounds trichloroethene (TCE)and tetrachloroethene (PCE) in the soil vapor and groundwater. There was no evidence of PCE use on the adjacent property. The higher results were closer to the common property line. PCE was found at 910 ppb in groundwater along the common property boundary, decreasing to 120 ppb approximately 100 feet away. PCE was measured at 16,900 ug/m3 in the soil vapor. The groundwater standard for both PCE and TCE is 5 ppb. In April 2011, the site operator obtained 2 soil samples from beneath the Bridge Cleaners slab and found tetrachloroethene (PCE) at 3.45 ppm and 0.757 ppm. The unrestricted soil cleanup objective is 1.3ppm for PCE. In September 2011, the owner independently obtained samples of soils and groundwater under the building,and provided results to DEC in November 2011. The three groundwater results under the building were 537 ppb, 841 ppb and 1470 ppb PCE. Fifteen soil samples were below the unrestricted soil cleanup objectives for PCE. Groundwater samples also contained TCE in the 11-12.5 ppb range. After unsuccessfully attempting to obtain site access for a more thorough investigation, NYSDEC conducted an offsite investigation in February 2012. Groundwater elevations show groundwater flow from northeast to southwest. Concentrations of PCE and TCE upgradient of the site were approximately 21 ppb and 1 ppb respectively. Downgradient concentrations were 440 ppb and 32 ppb respectively. One of 14 soil samples, at side gradient monitoring well MW-4, contained PCE at 3.3 ppm. The depth of this contamination was 29-30 feet below grade. Significant Threat: "The site presents a significant environmental threat due to the ongoing releases of contaminants from source areas into groundwater."
Health Problem: Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air or buildings, is referred to as soil vapor intrusion. Furthermore,

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

environmental sampling indicates that soil vapor intrusion represents a concern for on and off-site structures and additional evaluation is necessary to determine the extent of exposure to contamination in this media.

Program: BCP
Site Code: 464609
Site Description: LOCATION: The Bridge Cleaners site is located at 39-26 30th Street in Long Island City, an urban area. SITE FEATURES: A 7500 square foot one-story concrete building occupies the entire lot. The back of the lot abuts adjacent buildings. The building has no basement.CURRENT ZONING: This section of Long Island City is zoned Special Purpose District which allows mixed residential and commercial use. The specific designation for the site is M1-3/R7X. Buildings within the city block are primarily commercial. There are residential units including a three story apt building along 29th Street. The downgradient block also contains a limited number of residential buildings.HISTORICAL USES: The site was occupied by a commercial laundry and dry cleaner up until 2011, when the DEC investigation of the property began. Records indicate at least 10 years of use as a dry-cleaner. The building is currently vacant. SITE HYDROLOGY/GEOLOGY: Groundwater elevation levels vary from 11.04 AMSL to 10.01 AMSL in the vicinity of the site. Soils in the area are primarily sand.5/17/13-DEC signed the Brownfield Cleanup Agreement for this site.
Env Problem: NATURE AND EXTENT OF CONTAMINATION: Samples collected in 2009 on the property adjacent to the Bridge Cleaners site identified dry-cleaning related compounds trichloroethene (TCE)and tetrachloroethene (PCE) in the soil vapor and groundwater. There was no evidence of PCE use on the adjacent property. The higher results were closer to the common property line. PCE was found at 910 ppb in groundwater along the common property boundary, decreasing to 120 ppb approximately 100 feet away. PCE was measured at 16,900 ug/m3 in the soil vapor. The groundwater standard for both PCE and TCE is 5 ppb. In April 2011, the site operator obtained 2 soil samples from beneath the Bridge Cleaners slab and found tetrachloroethene (PCE) at 3.45 ppm and 0.757 ppm. The unrestricted soil cleanup objective is 1.3ppm for PCE. In September 2011, the owner independently obtained samples of soils and groundwater under the building,and provided results to DEC in November 2011. The three groundwater results under the building were 537 ppb, 841 ppb and 1470 ppb PCE. Fifteen soil samples were below the unrestricted soil cleanup objectives for PCE. Groundwater samples also contained TCE in the 11-12.5 ppb range. After unsuccessfully attempting to obtain site access for a more thorough investigation, NYSDEC conducted an offsite investigation in February 2012. Groundwater elevations show groundwater flow from northeast to southwest. Concentrations of PCE and TCE upgradient of the site were approximately 21 ppb and 1 ppb respectively. Downgradient concentrations were 440 ppb and 32 ppb respectively. One of 14 soil samples, at side gradient monitoring well MW-4, contained PCE at 3.3 ppm. The depth of this contamination was 29-30 feet below grade, and below the water table at 25.5 feet.
Health Problem: Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air or buildings, is referred to as soil vapor intrusion. Furthermore, environmental sampling indicates that soil vapor intrusion represents a concern for on and off-site structures and additional evaluation is necessary to determine the extent of exposure to contamination in this media.

---

234 West 1/2-1 0.599 mi. 3161 ft. **KOSAN INDUSTRIAL CORP** **CORRACTS** **1000150474**
5-49 49TH AVE **RCRA NonGen / NLR** **NYD061949228**
LONG ISLAND CITY, NY 11101 **FINDS**
NY MANIFEST

Relative: Lower

Actual: 7 ft.

CORRACTS:

EPA ID:	NYD061949228
EPA Region:	02
Area Name:	SITEWIDE
Actual Date:	20040113
Action:	CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority
NAICS Code(s):	32551 Paint and Coating Manufacturing
Original schedule date:	Not reported
Schedule end date:	Not reported

EPA ID:	NYD061949228
EPA Region:	02
Area Name:	SITEWIDE
Actual Date:	19950228
Action:	CA225NF - Stabilization Measures Evaluation, This facility, is not amenable to stabilization activity at the, present time, because it appears to be technically infeasible or, inappropriate
NAICS Code(s):	32551 Paint and Coating Manufacturing
Original schedule date:	Not reported
Schedule end date:	Not reported

EPA ID:	NYD061949228
EPA Region:	02
Area Name:	SITEWIDE
Actual Date:	19950425
Action:	CA050 - RFA Completed
NAICS Code(s):	32551 Paint and Coating Manufacturing
Original schedule date:	Not reported
Schedule end date:	Not reported

EPA ID:	NYD061949228
EPA Region:	02
Area Name:	SITEWIDE
Actual Date:	19950425
Action:	CA070NO - RFA Determination Of Need For An RFI, RFI is Not Necessary
NAICS Code(s):	32551 Paint and Coating Manufacturing
Original schedule date:	Not reported

KOSAN INDUSTRIAL CORP (Continued) **1000150474**

Schedule end date: Not reported

EPA ID: NYD061949228
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 19950425
Action: CA210T - CA Responsibility Referred To A Non-RCRA Federal Authority, Corrective Action referred to another non-RCRA Federal Authority
NAICS Code(s): 32551
Paint and Coating Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD061949228
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 19930908
Action: CA075HI - CA Prioritization, Facility or area was assigned a high corrective action priority
NAICS Code(s): 32551
Paint and Coating Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: KOSAN INDUSTRIAL CORP
Facility address: 5-49 49TH AVE
LONG ISLAND CITY, NY 111015610
EPA ID: NYD061949228
Mailing address: 49TH AVE
LONG ISLAND CITY, NY 11101
Contact: Not reported
Contact address: 49TH AVE
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: STEPHEN GALGANO
Owner/operator address: 465 LOGAN ST
BROOKLYN, NY 11208
Owner/operator country: US
Owner/operator telephone: (212) 277-3333
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: STEPHEN GALGANO
Owner/operator address: 465 LOGAN ST

KOSAN INDUSTRIAL CORP (Continued) **1000150474**

OPERCITY, NY 99999
Owner/operator country: US
Owner/operator telephone: (212) 277-3333
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibilty indicator: Transferred to the program or state equivalent.

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: KOSAN INDUSTRIAL CORP
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: KOSAN INDUSTRIAL CORP
Classification: Not a generator, verified

Date form received by agency: 11/19/1980
Facility name: KOSAN INDUSTRIAL CORP
Classification: Not a generator, verified

Date form received by agency: 08/18/1980
Facility name: KOSAN INDUSTRIAL CORP
Classification: Large Quantity Generator

Corrective Action Summary:
Event date: 09/08/1993
Event: CA Prioritization, Facility or area was assigned a high corrective action priority.

Event date: 02/28/1995
Event: Stabilization Measures Evaluation,This facility is not amenable to stabilization activity at the present time, because it appears to be technically infeasible or inappropriate.

Event date: 04/25/1995
Event: RFA Determination Of Need For An RFI, RFI is Not Necessary;

KOSAN INDUSTRIAL CORP (Continued) **1000150474**

Event date: 04/25/1995
Event: CA Responsibility Referred To A Non-RCRA Federal Authority, Corrective Action referred to another non-RCRA Federal Authority.

Event date: 04/25/1995
Event: RFA Completed

Event date: 01/13/2004
Event: CA Prioritization, Facility or area was assigned a low corrective action priority.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 05/13/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110000616539

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD061949228
Country: USA
Mailing Name: KOSAN INDUSTRIAL CORP
Mailing Contact: THOMAS GILCHRIST OWNER SE
Mailing Address: 5-49 49ATH AVENUE
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-784-8385

Document ID: NYO3019401
Manifest Status: Completed copy
Trans1 State ID: NY2A074
Trans2 State ID: Not reported
Generator Ship Date: 830616
Trans1 Recv Date: 830616
Trans2 Recv Date: Not reported
TSD Site Recv Date: 830616
Part A Recv Date: 030628

KOSAN INDUSTRIAL CORP (Continued) **1000150474**

Part B Recv Date:	030628
Generator EPA ID:	NYD061949228
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000824334
Waste Code:	F003 - UNKNOWN
Quantity:	01100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	020
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	100
Year:	83

Document ID:	NYO3080565
Manifest Status:	Completed copy
Trans1 State ID:	NY2A074
Trans2 State ID:	Not reported
Generator Ship Date:	830831
Trans1 Recv Date:	830831
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	830831
Part A Recv Date:	030913
Part B Recv Date:	030913
Generator EPA ID:	NYD061949228
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000824334
Waste Code:	F003 - UNKNOWN
Quantity:	00385
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	007
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	83

Document ID:	NYO1651896
Manifest Status:	Completed copy
Trans1 State ID:	NY2A074
Trans2 State ID:	Not reported
Generator Ship Date:	821117
Trans1 Recv Date:	821117
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	821117
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD061949228

KOSAN INDUSTRIAL CORP (Continued) **1000150474**

Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000824334
Waste Code:	F003 - UNKNOWN
Quantity:	00550
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	010
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	82

Document ID:	NYO1650393
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NY2A074
Trans2 State ID:	Not reported
Generator Ship Date:	820703
Trans1 Recv Date:	820703
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	820730
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD061949228
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000824334
Waste Code:	F003 - UNKNOWN
Quantity:	00715
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	013
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	82

Document ID:	NYO1650717
Manifest Status:	Completed copy
Trans1 State ID:	NY2A074
Trans2 State ID:	Not reported
Generator Ship Date:	820915
Trans1 Recv Date:	820915
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	820915
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD061949228
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000824334
Waste Code:	F003 - UNKNOWN
Quantity:	00550
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	010
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.

KOSAN INDUSTRIAL CORP (Continued) **1000150474**

Specific Gravity:	100
Year:	82
Document ID:	NYO2904912
Manifest Status:	Completed copy
Trans1 State ID:	NY2A074
Trans2 State ID:	Not reported
Generator Ship Date:	830210
Trans1 Recv Date:	830210
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	830210
Part A Recv Date:	030222
Part B Recv Date:	030222
Generator EPA ID:	NYD061949228
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000824334
Waste Code:	F003 - UNKNOWN
Quantity:	00825
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	015
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	83

235
NE
1/2-1
0.620 mi.
3273 ft.

AMTRAK SUNNYSIDE YARD **NY SHWS** **S103575644**
39-29 HONEYWELL STREET **NY LTANKS** **N/A**
LONG ISLAND CITY, NY **NY Spills**

Relative:
Higher

Actual:
23 ft.

SHWS:

Program:	HW
Site Code:	57794
Classification:	SIGNIFICANT THREAT TO THE PUBLIC HEALTH OR ENVIRONMENT - ACTION REQUIRED.
Region:	2
Acres:	133.000
HW Code:	241006
Record Add:	11/18/1999
Record Upd:	05/28/2013
Updated By:	JHOCONNE

Site Description: Location:Sunnyside Yard (the Site) is located at 39-29 Honeywell Street, Long Island City, Queens County, New York.Site Features:The Site is a railroad maintenance and storage facility that currently encompasses approximately 133 acres. Newtown Creek, which defines the border between Queens and Kings Counties, is located less than 0.5 mile south of the western portion of the Site. The Site is bordered by commercial/residential properties, with Northern Boulevard located to the north, 42nd Place located to the east, Thompson Avenue to the west, and Skillman Avenue located to the south. Current Zoning/Use:The Site is located in Manufacturing Zone (M1-1) and used as a railroad maintenance and storage facility Historic Use:The Yard was originally constructed in the early 1900's by the Pennsylvania Tunnel and Terminal Company, a subsidiary of Pennsylvania Railroad (later known as the Penn Central Transportation Company). On April 1,

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

1976, the Consolidated Rail Corporation (Conrail) acquired the Site, and the same day conveyed it to Amtrak, which has continued to operate it as a storage and maintenance facility for railroad rolling stock. Prior to September 29, 1961, a portion of the yard was owned by Long Island Rail Road (LIRR). Today, the LIRR maintains a right-of-way through the Yard. The Long Island Railroad (LIRR) is constructing tunnels through the Yard as part of its East Side Access (ESA) project. An extensive cleanup program was completed in 1996 to remove PCB contaminated sediment from impacted sewer manholes with subsequent sampling to identify sewer segments and manholes with recurring PCB contaminated sediment impacts.Operable Units:The site is divided into six operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. The operable units for this site are: Operable unit 1 (OU1) is the soil above the water table within the footprint of the High Speed Trainset Facility Service and Inspection (HSTF S and I) Building.Operable unit 2 (OU2) is the soil above the water table within the footprint of the HSTF S and I Building ancillary structures.Operable unit 3 (OU3) is the soil and separate phase petroleum hydrocarbon accumulation above the water table and soil below the water table within 8 acres in the north central portion of the Site.Operable unit 4 (OU4) is the soil above the water table (unsaturated zone) at the Site, excluding OU-1, OU-2, and OU-3. Operable unit 5 (OU5) is the sewer system (water and sediment) beneath the Site. Operable unit 6 (OU6) is the groundwater and saturated soil beneath the Site. Site Geology and Hydrology:Historic fill on the Site is predominantly comprised of reworked glacial deposits (unstratified sand, silt, clay and gravel) and railroad ballast, with lesser amounts of ash, cinders and construction debris. With the exception of paved areas, land occupied by buildings, and vegetated areas, the railroad ballast is ubiquitous at the land surface throughout the Site. Groundwater beneath the Site occurs in fill deposits, wetlands, or the Upper Pleistocene glacial deposits. The saturated Upper Pleistocene deposits comprise the Upper Glacial aquifer. The depth to groundwater across the Site varies from one to fifteen feet below ground surface. Groundwater within the shallow deposits flows predominantly west across the Site. However, groundwater between Queens Boulevard and Honeywell Street flows northerly and northwesterly toward the buried flow path of the Dutch Kills Creek and/or East River. In the deeper deposits, groundwater predominantly flows west across the Site.

Env Problem: Nature and Extent of Contamination:Prior to Remediation:Remedial investigations have been conducted in multiple phases under NYSDEC oversight pursuant to the consent order. Seventeen specific areas of concern (AOC) were identified of concern (COCs). The following environmental exposure pathways and ecological risks have been identified for the Site:The Site poses an environmental threat associated with the potential impacts of contaminants to groundwater from soils impacted by the COC's. Continued migration of contaminated groundwater from off-site sources poses a potential environmental threat to on-site groundwater. Off-site sources will be addressed by remedial programs for the respective neighboring sites, as appropriate. There are no wetlands or other exposure pathways to fish and wildlife receptors in the Site.Operable Unit 1: Polychlorinated biphenyls (PCBs) were detected in 16 of 19 soil samples; all but one

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

were less than 1 parts per million (ppm). The maximum concentration was 2 ppm. Six semi-volatile organic compounds (SVOCs), specifically carcinogenic polycyclic aromatic hydrocarbons (cPAHs), were detected above Technical and Administrative Guidance Memo (TAGM) 4046 Recommended Soil Cleanup Objectives (RSCOs) at depths up to three feet below ground surface (bgs). However, there was only one exceedance of the site specific soil cleanup level (SSSCL) of 10 ppm. Operable Unit 2: The soil above groundwater was sampled at depths up to three feet bgs. PCBs were detected in 15 of the 20 samples at a maximum concentration of 4.5 ppm. The other compounds of concern (COCs), lead and total cPAHs, were also detected at levels below the SSSCLs of 1000 ppm and 25 ppm respectively. Therefore, No Action was selected in the Record of Decision (ROD). Operable Unit 3:Surface Soil - The SSSCLs were exceeded for PCBs (2 out of 102 samples); lead (3 out of 3) and cPAHs (2 out of 27). The maximum concentration for PCBs was 73 ppm; for lead it was 1,080 ppm and cPAHs 108 ppm. Additionally, half an acre of visible petroleum contaminated surface soil was delineated at an average depth of one foot bgs. Subsurface Soil - There were no exceedances of the SSSCLs for the COCs.Waste Materials - The waste material onsite consists of PCB contaminated petroleum present in: (1) surface soils as mentioned above; (2) a potentially mobile separate phase hydrocarbon (SPH) plume floating over the groundwater surface; (3) a residual SPH trapped in soil pores below the water table; and (4) residues in underground structures. Sixty-five samples of SPH were collected and analyzed for PCBs. The maximum concentration was 360 ppm. SPH and sludge samples taken from underground structures contained PCB concentrations of 512 and 517 ppm respectively.Operable Unit 4:Surface Soil - There were exceedances of the SSSCLs for PCBs (60 out of 786 samples); lead (52 out of 471); and cPAHs (31 out of 436). The maximum PCB concentration was 25,000 ppm; cPAH was 113 ppm and lead was 7,020 ppm.Subsurface Soil - There were exceedances in soil samples for the SSSCLs viz. PCBs (13 of 455); lead (17 of 354) and cPAHs (18 of 376). The maximum PCB concentration was 3500 ppm; lead was 2600 ppm and cPAH was 119 ppm.Operable Unit 5:Sewer Sediment - PCBs were detected in 29 samples of sediment from the sewers at concentrations ranging from 0.053 ppm at MH-69 to 120 ppm at MH-6. PCB concentrations at MH-6 (one sample) and MH-38 (two samples) exceeded the 25 ppm NYSDEC-approved site specific soil cleanup level. MH-6 was remediated as an IRM in October 2011.Sewer Water - Discrete water samples (filtered and unfiltered) were collected from 12 manhole locations and analyzed for PCBs during performance of the OU-5 RI. PCBs were detected in 17 of 39 unfiltered samples with concentrations ranging from 0.14 parts per billion (ppb) to a high of 83 ppb. Five of the unfiltered samples, one from MH-3, three from MH-6 and one from MH-40 exceeded the 1 ppb waste water effluent limit. The waste water effluent limit is appropriate since the sewer discharges to a Waste Water Treatment Plant. Only one of the 39 filtered samples (MH-3) contained PCBs at a concentration (1.8 ppb) slightly exceeding the 1 ppb waste water effluent limit.Operable Unit 6:Saturated Subsurface Soil - A total of 159 samples of soil were collected from 29 boring locations. There were no exceedances of the SSSCLs for the COCs.Groundwater - Three plumes of chlorinated volatile organic compounds (CVOCs) were defined at the site. However, none of these were attributable to site operations, but are attributable to off-site sources. No site related groundwater contamination of concern was identified.Post Remediation:Remediation has been

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

	completed in OU-1 where 472 tons of contaminated soil, fill and debris were excavated and disposed of along with 280 cubic yards of concrete and asphalt and 2,450 gallons of liquid. A No Action ROD was issued for OU-2. Remediation has been initiated at OU-3 and OU-4. The OU-5 ROD for cleaning the sewers was issued on March 27, 2011, and the OU-6 ROD (No Action) was issued on March 30, 2010.
Health Problem:	Groundwater in the area of the site is not used as a source of potable water. Access to the site is controlled, preventing trespassers from coming in contact with contaminated soils.
Dump:	True
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1910
Disp Term:	unknown
Lat/Long:	40:45:03:0 / 73:56:01:0
Dell:	False
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	11/18/1999 12:00:00 PM
Updated By:	INITIAL
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	PENNSYLVANIA RAILROAD - AMTRAK
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	PENNSYLVANIA RAILROAD - AMTRAK
Owner Address:	400 N. CAPITOL ST. NW
Owner Addr2:	Not reported
Owner City,St,Zip:	WASHINGTON, DC 20001
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	JOSEPH P. DEVITO
Owner Company:	PENNSYLVANIA RAILROAD - AMTRAK
Owner Address:	39-29 HONEYWELL ST.
Owner Addr2:	Not reported
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Queens Public Library
Owner Address:	Sunnyside Branch
Owner Addr2:	43-06 Greenpoint Avenue
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	National Rail Passenger Corporation

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Owner Address:	400 North Capitol Street NW
Owner Addr2:	Not reported
Owner City,St,Zip:	Washington, DC 20001
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Amtrak - Sunnyside Yard
Owner Address:	39-29 Honeywell Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	01
Owner Name:	Not reported
Owner Company:	Amtrak and New Jersey Transit Corp
Owner Address:	39-29 Honeywell Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Sunnyside, NY 11101
Owner Country:	United States of America
HW Code:	241006
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	1,1,2-TRICHLORETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	BENZ(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	1,2,4-TRICHLOROBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	BENZO[K]FLUORANTHENE

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: P-79652
Cross Ref Type Code: 11
Cross Ref Type: ICS ID
Record Added Date: 11/18/1999 12:00:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: INITIAL

LTANKS:
Site ID: 97453
Spill Number/Closed Date: 9013163 / 3/14/2003
Spill Date: 3/23/1991
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 4101
Investigator: ADMIN. CLOSED
Referred To: Not reported
Reported to Dept: 3/26/1991
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 4/4/1991
Spill Record Last Update: 3/30/2004
Spiller Name: Not reported
Spiller Company: AMTRAK
Spiller Address: 39-29 HONEYWELL STREET
Spiller City,St,Zip: LONG ISLAND CITY, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 86808
DEC Memo: Not reported
Remarks: 20K TANK FAILED,CONTRACTOR WILL PUMP TANK,PRESENTLY ROUX ASSOCIATES PERFORMING SITE ASSESSMENT,SITE IS PART OF RIFF PROJECT,JAMES QUINN, DEC REMEDIAL ACTION (518-457-3395).CLOSED DUE TO LACK OF ANY RECENT INFO - DOES NOT MEET ANY CLEANUP REQUIREMENTS.

Material:
Site ID: 97453
Operable Unit ID: 950385
Operable Unit: 01
Material ID: 426055
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Material FA:	Petroleum
Quantity:	-1
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	97453
Spill Tank Test:	1538365
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

Site ID:	97456
Spill Number/Closed Date:	9207333 / 11/24/2003
Spill Date:	1/1/1991
Spill Cause:	Tank Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	9/24/1992
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	9/28/1992
Spill Record Last Update:	11/24/2003
Spiller Name:	ENVIRONMENTAL DEPT
Spiller Company:	NATIONAL RAILROAD PASS
Spiller Address:	400 WEST 31ST STREET, 4TH
Spiller City,St,Zip:	NEW YORK, NY 10001-
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	86808
DEC Memo:	Not reported
Remarks:	ALL 14 TANKS CLEANED AND FILLED W/CONCRETE 4 TEST BORINES DONE 2/10/92, 4 EA MONITORING WELLS 3/3/92 INDICATES CONTAMINATED SOIL AND G/W CLOSED SITE 1960

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Material:

Site ID:	97456
Operable Unit ID:	970974
Operable Unit:	01
Material ID:	407971
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

SPILLS:

Facility ID:	8703955
DER Facility ID:	86808
Facility Type:	ER
Site ID:	97452
DEC Region:	2
Spill Date:	8/12/1987
Spill Number/Closed Date:	8703955 / 8/12/1987
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates a file or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)
SWIS:	4101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	8/12/1987
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Railroad Car
Spill Notifier:	Local Agency
Cleanup Ceased:	8/12/1987
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	8/18/1987
Spill Record Last Update:	11/24/2003
Spiller Name:	ENVIRONMENTAL DEPT
Spiller Company:	NATIONAL RAILROAD PASS
Spiller Address:	400 WEST 31ST STREET, 4TH
Spiller City,St,Zip:	NEW YORK, NY 10001-
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	FIRE ON LOCOMOTIVE CARRYING TRANSFORMER.

Material:

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Site ID:	97452
Operable Unit ID:	907846
Operable Unit:	01
Material ID:	470160
Material Code:	0017A
Material Name:	PCB OIL
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9804210
DER Facility ID:	86808
Facility Type:	ER
Site ID:	219140
DEC Region:	2
Spill Date:	7/2/1998
Spill Number/Closed Date:	9804210 / 8/27/1998
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	7/3/1998
CID:	365
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	7/3/1998
Spill Record Last Update:	11/24/2003
Spiller Name:	ENVIRONMENTAL DEPT
Spiller Company:	NATIONAL RAILROAD PASSENG
Spiller Address:	400 WEST 31ST STREET, 4TH
Spiller City,St,Zip:	NEW YORK, NY 10001-
Spiller Company:	001
Contact Name:	RICHARD MOHLENHOFF
Contact Phone:	(212) 630-7246
DEC Memo:	Not reported
Remarks:	Small railroad tie fire occurred last night - drum near by spilled - clean up in progress

Material:

Site ID:	219140
Operable Unit ID:	1065071

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Operable Unit:	01
Material ID:	318926
Material Code:	0021
Material Name:	Transmission Fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	0103793
DER Facility ID:	86808
Facility Type:	ER
Site ID:	219136
DEC Region:	2
Spill Date:	7/10/2001
Spill Number/Closed Date:	0103793 / 6/26/2003
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	7/10/2001
CID:	382
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	7/10/2001
Spill Record Last Update:	3/30/2004
Spiller Name:	ENVIRONMENTAL DEPT
Spiller Company:	NATIONAL RAILROAD PASS
Spiller Address:	400 WEST 31ST STREET, 4TH
Spiller City,St,Zip:	NEW YORK, NY 10001-
Spiller Company:	001
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	A leak from either pipe or tank of a low ph car wash fluid - leak found while repairing tank. most contained to inside area but some seepage into ground. clean up in progress by clean harbors and amtrack Not reported

Material:

Site ID:	219136
Operable Unit ID:	840419

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Operable Unit:	01
Material ID:	535869
Material Code:	0045A
Material Name:	CLEANING CHEMICALS/PRODUCTS
Case No.:	Not reported
Material FA:	Other
Quantity:	50
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9102570
DER Facility ID:	86808
Facility Type:	ER
Site ID:	97454
DEC Region:	2
Spill Date:	6/4/1991
Spill Number/Closed Date:	9102570 / 6/4/1991
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	6/4/1991
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Railroad Car
Spill Notifier:	Local Agency
Cleanup Ceased:	6/4/1991
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	6/12/1991
Spill Record Last Update:	11/24/2003
Spiller Name:	Not reported
Spiller Company:	STAR ENTERPRISE
Spiller Address:	Not reported
Spiller City,St,Zip:	DELAWARE CITY, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TANG"06/04/91: NYCFD HAZ MAT (SCOTT KIRCHHOFER) FIRST NOTIFIED BY A LIRR EMPLOYEE ABOUT SMELLING AN ODOR & NOTICING A HISSING NOISE ON TOP OF TANK, NYCDEP ON SCENE,NYCFD SLOWED THE LEAK SIGNIFICANTLY. Spill Site Investigation has been consolidated under Spill No.8503066 and Site Investigation and Remediation is BeingSupervised by Hazardous Waste Remediation Under DEC Site No.241006 Under the State Superfund Registry as a Class 2 SuperfundSite.
Remarks:	LEAK FROM TANK CAR,STREETS CLOSED FROM 31ST ST TO STEINWAY ALONG

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

NORTHERN BLV,NYCFD ATTEMPTING TO SEAL THE LEAK,GATX LEASED THE RR CAR TO ANOTHER COMPANY FOR TRANSPORT,EPA(JOHN HIGGINS)TO RESPOND

Material:

Site ID:	97454
Operable Unit ID:	953473
Operable Unit:	01
Material ID:	425081
Material Code:	0599A
Material Name:	LPG
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9903705
DER Facility ID:	86808
Facility Type:	ER
Site ID:	219143
DEC Region:	2
Spill Date:	6/29/1999
Spill Number/Closed Date:	9903705 / 11/24/2003
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	6/30/1999
CID:	390
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	6/30/1999
Spill Record Last Update:	11/24/2003
Spiller Name:	ROBERT LAROSA
Spiller Company:	NATIONAL RAILROAD PASS
Spiller Address:	400 WEST 31ST STREET, 4TH
Spiller City,St,Zip:	NEW YORK, NY 10001-
Spiller Company:	001
Contact Name:	ROBERT LAVELLE
Contact Phone:	(212) 630-7245
DEC Memo:	Not reported
Remarks:	NOTICED SPIIL DURING EXCAVATION - APPEARS TO BE OLD SPILL

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Material:

Site ID:	219143
Operable Unit ID:	1078257
Operable Unit:	01
Material ID:	303613
Material Code:	0022
Material Name:	Waste Oil/Used Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	219143
Operable Unit ID:	1078257
Operable Unit:	01
Material ID:	303614
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

236
North
1/2-1
0.712 mi.
3759 ft.

Relative:
Higher

Actual:
16 ft.

D D K PRO CLEANERS **NY SHWS S109826034**
38-68 13TH ST **NY MANIFEST N/A**
LONG ISLAND CITY, NY 11101

SHWS:

Program:	HW
Site Code:	439625
Classification:	P
Region:	2
Acres:	.110
HW Code:	241126
Record Add:	09/08/2010
Record Upd:	09/20/2011
Updated By:	JBVOUGHT

Site Description: The Site is located in the Long Island City section of Queens in a zoned manufacturing area with residential zoning approximately 300 feet to the south. The Site had been a residential building with garages beginning in 1898, was vacant from 1947-1950, was used for sheet metal work from 1967-1983 and was converted from sheet metal work to dry cleaning in 1997. The Site is currently an active dry cleaning facility. The one-story building foundation is slab-on-grade

D D K PRO CLEANERS (Continued) **S109826034**

and contains dry cleaning machines, garment storage area, storage, boiler room, office, customer service area, bathroom and partial basement. The building covers the entire footprint of the site. The building has three 4th-generation dry cleaning machines on a secondary containment concrete slab, five washers and a dryer, several empty 15-gal waste containers, spill containment material container, a spotting stand, ten press machines, three sets of shirt machines, four air compressors, two refrigerated dryers and a sump. The Site and building are approximately 5000 square feet in size (0.11 acres). A residential building is located immediately to the northwest (0.01 miles), a stonework building is to the northeast, a fine arts furniture building to the southwest and 13th Street to the southeast.

Env Problem: Based upon investigations conducted to date, the primary contaminants of concern at the site include tetrachloroethene (PCE) and dichloroethene (DCE). One round of groundwater sample collection was performed in June 2009 via two Geoprobe borings located in the sidewalk in front of the site building. Groundwater samples were analyzed via EPA Methods 8260/8270. No soil samples were collected for analysis during the investigation. The following maximum concentrations with contaminants were observed in groundwater: 26ppb PCE and 63ppb DCE. These results demonstrate that groundwater standards have been exceeded for PCE and DCE. The nearest surface water body is the East River, which is located approximately 2000 feet (0.3 miles) to the west. Groundwater is approximately 7 to 8 feet below grade and most likely flows west under the Site to the East River, however direction of flow has not been specifically determined to date. Site characterization is required to evaluate the presence or absence of hazardous waste on the site, and to collect data sufficient to determine if the site poses a significant threat to public health or the environment.

Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Owner
Sub Type: NNN
Owner Name: Maryuhn Young Moon
Owner Company: Best DDK Cleaners
Owner Address: 471 Tulane Court
Owner Addr2: Not reported
Owner City,St,Zip: Paramus, NJ 07654
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported

D D K PRO CLEANERS (Continued) **S109826034**

Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

NY MANIFEST:
EPA ID: NYR000164277
Country: USA
Mailing Name: D D K PRO CLEANERS
Mailing Contact: KYAW
Mailing Address: 38-68 13TH ST
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-784-2407

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000081205
Trans2 State ID: Not reported
Generator Ship Date: 28-May-2013 00:00:00
Trans1 Recv Date: 28-May-2013 00:00:00
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12-Jun-2013 00:00:00
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000164277
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: RID084802842
Waste Code: Not reported
Quantity: 660
Units: P - Pounds
Number of Containers: 6
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 003308229SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H020

D D K PRO CLEANERS (Continued) **S109826034**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000081205
Trans2 State ID:	Not reported
Generator Ship Date:	28-May-2013 00:00:00
Trans1 Recv Date:	28-May-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12-Jun-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	480
Units:	P - Pounds
Number of Containers:	6
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	003308229SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000081205
Trans2 State ID:	Not reported
Generator Ship Date:	31-Jan-2013 00:00:00
Trans1 Recv Date:	31-Jan-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	15-Feb-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	110
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1

D D K PRO CLEANERS (Continued) **S109826034**

Year:	2013
Manifest Tracking Num:	003308603SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000081205
Trans2 State ID:	Not reported
Generator Ship Date:	31-Jan-2013 00:00:00
Trans1 Recv Date:	31-Jan-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	15-Feb-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	440
Units:	P - Pounds
Number of Containers:	4
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	003308603SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000081205
Trans2 State ID:	Not reported
Generator Ship Date:	31-Jan-2013 00:00:00
Trans1 Recv Date:	31-Jan-2013 00:00:00

D D K PRO CLEANERS (Continued) **S109826034**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	15-Feb-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	120
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	003308603SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000081205
Trans2 State ID:	NJD071629976
Generator Ship Date:	04-Mar-2013 00:00:00
Trans1 Recv Date:	04-Mar-2013 00:00:00
Trans2 Recv Date:	07-Mar-2013 00:00:00
TSD Site Recv Date:	18-Mar-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	110
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	003308886SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N

D D K PRO CLEANERS (Continued) **S109826034**

Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000081205
Trans2 State ID:	NJD071629976
Generator Ship Date:	04-Mar-2013 00:00:00
Trans1 Recv Date:	04-Mar-2013 00:00:00
Trans2 Recv Date:	07-Mar-2013 00:00:00
TSD Site Recv Date:	18-Mar-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	240
Units:	P - Pounds
Number of Containers:	4
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	003308886SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000081205
Trans2 State ID:	NJD071629976
Generator Ship Date:	04-Mar-2013 00:00:00
Trans1 Recv Date:	04-Mar-2013 00:00:00
Trans2 Recv Date:	07-Mar-2013 00:00:00
TSD Site Recv Date:	18-Mar-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported

D D K PRO CLEANERS (Continued) **S109826034**

Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	770
Units:	P - Pounds
Number of Containers:	7
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	003308886SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000081205
Trans2 State ID:	Not reported
Generator Ship Date:	08-Apr-2013 00:00:00
Trans1 Recv Date:	08-Apr-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	16-Apr-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	770
Units:	P - Pounds
Number of Containers:	7
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	003403011SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

D D K PRO CLEANERS (Continued) **S109826034**

Mgmt Method Type Code: H020

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: OKD981588791
Generator Ship Date: 2010-01-28
Trans1 Recv Date: 2010-01-28
Trans2 Recv Date: 2010-02-23
TSD Site Recv Date: 2010-02-25
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000164277
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: OHD980587364
Waste Code: Not reported
Quantity: 780.0
Units: P - Pounds
Number of Containers: 4.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 002051873SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H020

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: OHR000110858
Generator Ship Date: 2009-05-06
Trans1 Recv Date: 2009-05-06
Trans2 Recv Date: 2009-05-14
TSD Site Recv Date: 2009-05-15
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000164277
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: OHD980587364
Waste Code: Not reported
Quantity: 15.0
Units: P - Pounds
Number of Containers: 8.0

D D K PRO CLEANERS (Continued) **S109826034**

Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	001805322SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	OHR000110858
Generator Ship Date:	2009-05-06
Trans1 Recv Date:	2009-05-06
Trans2 Recv Date:	2009-05-14
TSD Site Recv Date:	2009-05-15
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	195.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	001805322SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930

D D K PRO CLEANERS (Continued) **S109826034**

Trans2 State ID:	NJD071629976
Generator Ship Date:	2009-11-11
Trans1 Recv Date:	2009-11-11
Trans2 Recv Date:	2009-11-13
TSD Site Recv Date:	2009-11-25
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	385.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	000281979CEX
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2011-09-29
Trans1 Recv Date:	2011-09-29
Trans2 Recv Date:	2011-10-06
TSD Site Recv Date:	2011-10-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	110.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	002592157SKS
Import Ind:	N

D D K PRO CLEANERS (Continued) **S109826034**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2011-09-29
Trans1 Recv Date:	2011-09-29
Trans2 Recv Date:	2011-10-06
TSD Site Recv Date:	2011-10-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	550.0
Units:	P - Pounds
Number of Containers:	5.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	002592157SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2011-11-28
Trans1 Recv Date:	2011-11-28
Trans2 Recv Date:	2011-12-01
TSD Site Recv Date:	2011-12-02
Part A Recv Date:	Not reported

D D K PRO CLEANERS (Continued) **S109826034**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	550.0
Units:	P - Pounds
Number of Containers:	5.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	002592410SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2011-11-28
Trans1 Recv Date:	2011-11-28
Trans2 Recv Date:	2011-12-01
TSD Site Recv Date:	2011-12-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	330.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	002592410SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

D D K PRO CLEANERS (Continued) **S109826034**

Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2011-11-28
Trans1 Recv Date:	2011-11-28
Trans2 Recv Date:	2011-12-01
TSD Site Recv Date:	2011-12-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	80.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	002592410SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2011-04-01
Trans1 Recv Date:	2011-04-01
Trans2 Recv Date:	2011-04-07
TSD Site Recv Date:	2011-04-08
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported

D D K PRO CLEANERS (Continued) **S109826034**

Quantity:	660.0
Units:	P - Pounds
Number of Containers:	6.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	002593637SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2011-04-01
Trans1 Recv Date:	2011-04-01
Trans2 Recv Date:	2011-04-07
TSD Site Recv Date:	2011-04-08
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	330.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	002593637SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

D D K PRO CLEANERS (Continued) **S109826034**

Click this hyperlink while viewing on your computer to access
62 additional NY_MANIFEST: record(s) in the EDR Site Report.

EPA ID:	NYR000001917
Country:	USA
Mailing Name:	LAMODE QUEENS
Mailing Contact:	SUNS WON AHN
Mailing Address:	38-68 13TH ST
Mailing Address 2:	Not reported
Mailing City:	QUEENS
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-729-2844

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000081205
Trans2 State ID:	Not reported
Generator Ship Date:	28-May-2013 00:00:00
Trans1 Recv Date:	28-May-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12-Jun-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	660
Units:	P - Pounds
Number of Containers:	6
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	003308229SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000081205

D D K PRO CLEANERS (Continued) **S109826034**

Trans2 State ID:	Not reported
Generator Ship Date:	28-May-2013 00:00:00
Trans1 Recv Date:	28-May-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12-Jun-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	480
Units:	P - Pounds
Number of Containers:	6
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	003308229SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000081205
Trans2 State ID:	Not reported
Generator Ship Date:	31-Jan-2013 00:00:00
Trans1 Recv Date:	31-Jan-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	15-Feb-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	110
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	003308603SKS
Import Ind:	N

D D K PRO CLEANERS (Continued) **S109826034**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000081205
Trans2 State ID:	Not reported
Generator Ship Date:	31-Jan-2013 00:00:00
Trans1 Recv Date:	31-Jan-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	15-Feb-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	440
Units:	P - Pounds
Number of Containers:	4
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	003308603SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000081205
Trans2 State ID:	Not reported
Generator Ship Date:	31-Jan-2013 00:00:00
Trans1 Recv Date:	31-Jan-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	15-Feb-2013 00:00:00
Part A Recv Date:	Not reported

D D K PRO CLEANERS (Continued) **S109826034**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	120
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	003308603SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000081205
Trans2 State ID:	NJD071629976
Generator Ship Date:	04-Mar-2013 00:00:00
Trans1 Recv Date:	04-Mar-2013 00:00:00
Trans2 Recv Date:	07-Mar-2013 00:00:00
TSD Site Recv Date:	18-Mar-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	110
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	003308886SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

D D K PRO CLEANERS (Continued) **S109826034**

Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000081205
Trans2 State ID:	NJD071629976
Generator Ship Date:	04-Mar-2013 00:00:00
Trans1 Recv Date:	04-Mar-2013 00:00:00
Trans2 Recv Date:	07-Mar-2013 00:00:00
TSD Site Recv Date:	18-Mar-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	240
Units:	P - Pounds
Number of Containers:	4
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	003308886SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000081205
Trans2 State ID:	NJD071629976
Generator Ship Date:	04-Mar-2013 00:00:00
Trans1 Recv Date:	04-Mar-2013 00:00:00
Trans2 Recv Date:	07-Mar-2013 00:00:00
TSD Site Recv Date:	18-Mar-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported

D D K PRO CLEANERS (Continued) **S109826034**

Quantity:	770
Units:	P - Pounds
Number of Containers:	7
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	003308886SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000081205
Trans2 State ID:	Not reported
Generator Ship Date:	08-Apr-2013 00:00:00
Trans1 Recv Date:	08-Apr-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	16-Apr-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	770
Units:	P - Pounds
Number of Containers:	7
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	003403011SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

D D K PRO CLEANERS (Continued) **S109826034**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	OKD981588791
Generator Ship Date:	2010-01-28
Trans1 Recv Date:	2010-01-28
Trans2 Recv Date:	2010-02-23
TSD Site Recv Date:	2010-02-25
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	780.0
Units:	P - Pounds
Number of Containers:	4.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	002051873SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	OHR000110858
Generator Ship Date:	2009-05-06
Trans1 Recv Date:	2009-05-06
Trans2 Recv Date:	2009-05-14
TSD Site Recv Date:	2009-05-15
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	15.0
Units:	P - Pounds
Number of Containers:	8.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0

D D K PRO CLEANERS (Continued) **S109826034**

Year:	2009
Manifest Tracking Num:	001805322SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	OHR000110858
Generator Ship Date:	2009-05-06
Trans1 Recv Date:	2009-05-06
Trans2 Recv Date:	2009-05-14
TSD Site Recv Date:	2009-05-15
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	195.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	001805322SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2009-11-11
Trans1 Recv Date:	2009-11-11

D D K PRO CLEANERS (Continued) **S109826034**

Trans2 Recv Date:	2009-11-13
TSD Site Recv Date:	2009-11-25
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	385.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	000281979CEX
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2011-09-29
Trans1 Recv Date:	2011-09-29
Trans2 Recv Date:	2011-10-06
TSD Site Recv Date:	2011-10-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	110.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	002592157SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N

D D K PRO CLEANERS (Continued) **S109826034**

Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2011-09-29
Trans1 Recv Date:	2011-09-29
Trans2 Recv Date:	2011-10-06
TSD Site Recv Date:	2011-10-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	550.0
Units:	P - Pounds
Number of Containers:	5.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	002592157SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2011-11-28
Trans1 Recv Date:	2011-11-28
Trans2 Recv Date:	2011-12-01
TSD Site Recv Date:	2011-12-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported

D D K PRO CLEANERS (Continued) **S109826034**

Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	550.0
Units:	P - Pounds
Number of Containers:	5.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	002592410SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2011-11-28
Trans1 Recv Date:	2011-11-28
Trans2 Recv Date:	2011-12-01
TSD Site Recv Date:	2011-12-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	330.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	002592410SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

D D K PRO CLEANERS (Continued) **S109826034**

Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 2011-11-28
Trans1 Recv Date: 2011-11-28
Trans2 Recv Date: 2011-12-01
TSD Site Recv Date: 2011-12-02
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000164277
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: RID084802842
Waste Code: Not reported
Quantity: 80.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 2011
Manifest Tracking Num: 002592410SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 2011-04-01
Trans1 Recv Date: 2011-04-01
Trans2 Recv Date: 2011-04-07
TSD Site Recv Date: 2011-04-08
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000164277
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: RID084802842
Waste Code: Not reported
Quantity: 660.0
Units: P - Pounds
Number of Containers: 6.0

D D K PRO CLEANERS (Continued) **S109826034**

Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	002593637SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2011-04-01
Trans1 Recv Date:	2011-04-01
Trans2 Recv Date:	2011-04-07
TSD Site Recv Date:	2011-04-08
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	330.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	002593637SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Click this hyperlink while viewing on your computer to access
62 additional NY_MANIFEST: record(s) in the EDR Site Report.

237
SSE
1/2-1
0.748 mi.
3949 ft.

ACTIVE STEEL DRUM CO INC
52-30 34TH ST
LONG ISLAND CITY, NY 11101

CORRACTS **1000265123**
RCRA NonGen / NLR **NYD003933355**
FINDS
NY MANIFEST

Relative:
Higher

Actual:
21 ft.

CORRACTS:

EPA ID:	NYD003933355
EPA Region:	02
Area Name:	SITEWIDE
Actual Date:	20040113
Action:	CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority
NAICS Code(s):	332439 81149 42184 Other Metal Container Manufacturing Other Personal and Household Goods Repair and Maintenance
Original schedule date:	Not reported
Schedule end date:	Not reported

EPA ID:	NYD003933355
EPA Region:	02
Area Name:	SITEWIDE
Actual Date:	19930908
Action:	CA075HI - CA Prioritization, Facility or area was assigned a high corrective action priority
NAICS Code(s):	332439 81149 42184 Other Metal Container Manufacturing Other Personal and Household Goods Repair and Maintenance
Original schedule date:	Not reported
Schedule end date:	Not reported

EPA ID:	NYD003933355
EPA Region:	02
Area Name:	SITEWIDE
Actual Date:	19950919
Action:	CA225NR - Stabilization Measures Evaluation, This facility is, not amenable to stabilization activity at the, present time for reasons other than (1) it appears to be technically, infeasible or inappropriate (NF) or (2) there is a lack of technical, information (IN). Reasons for this conclusion may be the status of, closure at the facility, the degree of risk, timing considerations, the status of corrective action work at the facility, or other, administrative considerations
NAICS Code(s):	332439 81149 42184 Other Metal Container Manufacturing Other Personal and Household Goods Repair and Maintenance
Original schedule date:	Not reported
Schedule end date:	Not reported

EPA ID:	NYD003933355
EPA Region:	02
Area Name:	SITEWIDE
Actual Date:	19950928
Action:	CA050 - RFA Completed
NAICS Code(s):	332439 81149 42184 Other Metal Container Manufacturing Other Personal and Household Goods Repair and Maintenance
Original schedule date:	Not reported

ACTIVE STEEL DRUM CO INC (Continued) **1000265123**

Schedule end date: Not reported

EPA ID: NYD003933355
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 19950928
Action: CA070NO - RFA Determination Of Need For An RFI, RFI is Not Necessary
NAICS Code(s): 332439 81149 42184
Other Metal Container Manufacturing
Other Personal and Household Goods Repair and Maintenance
Original schedule date: Not reported
Schedule end date: Not reported

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: ACTIVE STEEL DRUM CO INC
Facility address: 52-30 34TH ST
LONG ISLAND CITY, NY 111013202
EPA ID: NYD003933355
Mailing address: 34TH ST
LONG ISLAND CITY, NY 11101
Contact: Not reported
Contact address: 34TH ST
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: BARRY K. FINE
Owner/operator address: 27 LAWRANCE LANE
OPERCITY, NY 99999
Owner/operator country: US
Owner/operator telephone: (516) 665-4375
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: BARRY K FINE
Owner/operator address: 27 LAWRANCE LANE
BAY SHORE, NY 11706
Owner/operator country: US
Owner/operator telephone: (516) 665-4375
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibilty indicator: Transferred to the program or state equivalent.

Handler Activities Summary:
U.S. importer of hazardous waste: No

ACTIVE STEEL DRUM CO INC (Continued) **1000265123**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: ACTIVE STEEL DRUM CO INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: ACTIVE STEEL DRUM CO INC
Classification: Not a generator, verified

Date form received by agency: 11/19/1980
Facility name: ACTIVE STEEL DRUM CO INC
Classification: Not a generator, verified

Date form received by agency: 08/18/1980
Facility name: ACTIVE STEEL DRUM CO INC
Classification: Large Quantity Generator

Corrective Action Summary:
Event date: 09/08/1993
Event: CA Prioritization, Facility or area was assigned a high corrective action priority.

Event date: 09/19/1995
Event: Stabilization Measures Evaluation,This facility is not amenable to stabilization activity at the present time for reasons other than 1- it appears to be technically infeasible or inappropriate (NF) or 2- there is a lack of technical information (IN). Reasons for this conclusion may be the status of closure at the facility, the degree of risk, timing considerations, the status of corrective action work at the facility, or other administrative considerations.

Event date: 09/28/1995
Event: RFA Completed

Event date: 09/28/1995
Event: RFA Determination Of Need For An RFI, RFI is Not Necessary;

Event date: 01/13/2004
Event: CA Prioritization, Facility or area was assigned a low corrective action priority.

ACTIVE STEEL DRUM CO INC (Continued) **1000265123**

Facility Has Received Notices of Violations:
- Regulation violated: Not reported
- Area of violation: Generators - General
- Date violation determined: 11/13/1984
- Date achieved compliance: 05/13/1987
- Violation lead agency: State
  - Enforcement action: WRITTEN INFORMAL
  - Enforcement action date: 09/22/1987
  - Enf. disposition status: Not reported
  - Enf. disp. status date: Not reported
  - Enforcement lead agency: State
  - Proposed penalty amount: Not reported
  - Final penalty amount: Not reported
  - Paid penalty amount: Not reported

Evaluation Action Summary:
- Evaluation date: 04/27/1987
- Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
- Area of violation: Not reported
- Date achieved compliance: Not reported
- Evaluation lead agency: State

- Evaluation date: 11/13/1984
- Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
- Area of violation: Generators - General
- Date achieved compliance: 05/13/1987
- Evaluation lead agency: State

FINDS:

Registry ID: 110000616432

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
- EPA ID: NYD003933355
- Country: USA
- Mailing Name: ACTIVE STEEL DRUM
- Mailing Contact: FINE BARRY K PRESIDENT
- Mailing Address: 52-30 34TH ST
- Mailing Address 2: Not reported
- Mailing City: LONG ISLAND CITY
- Mailing State: NY
- Mailing Zip: 11101
- Mailing Zip4: 3202
- Mailing Country: USA
- Mailing Phone: 212-786-9300

ACTIVE STEEL DRUM CO INC (Continued) **1000265123**

Document ID:	NJO0174158
Manifest Status:	Completed copy
Trans1 State ID:	S3002BN
Trans2 State ID:	Not reported
Generator Ship Date:	830603
Trans1 Recv Date:	830603
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	830603
Part A Recv Date:	030614
Part B Recv Date:	030614
Generator EPA ID:	NYD003933355
Trans1 EPA ID:	NJD096865837
Trans2 EPA ID:	Not reported
TSDF ID:	NJD096865837
Waste Code:	D000 - NON-LISTED TOXIC WASTES
Quantity:	06000
Units:	P - Pounds
Number of Containers:	012
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	02400
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	048
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	100
Year:	83

Document ID:	NYO1554021
Manifest Status:	Completed copy
Trans1 State ID:	NYJA045
Trans2 State ID:	Not reported
Generator Ship Date:	830504
Trans1 Recv Date:	830504
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	830504
Part A Recv Date:	030509
Part B Recv Date:	030509
Generator EPA ID:	NYD003933355
Trans1 EPA ID:	NJD096865837
Trans2 EPA ID:	Not reported
TSDF ID:	NJD096865837
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00950
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	019
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	83

Document ID:	NYO1748151
Manifest Status:	Completed copy

ACTIVE STEEL DRUM CO INC (Continued) **1000265123**

Trans1 State ID:	NYOH003
Trans2 State ID:	Not reported
Generator Ship Date:	830407
Trans1 Recv Date:	830407
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	830408
Part A Recv Date:	030502
Part B Recv Date:	030502
Generator EPA ID:	NYP000775650
Trans1 EPA ID:	OHD075006304
Trans2 EPA ID:	Not reported
TSDF ID:	OHD055522429
Waste Code:	U220 - TOLUENE
Quantity:	00030
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	83

Document ID:	NYO1748187
Manifest Status:	Completed copy
Trans1 State ID:	NYOH003
Trans2 State ID:	Not reported
Generator Ship Date:	830409
Trans1 Recv Date:	830409
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	830411
Part A Recv Date:	030502
Part B Recv Date:	030502
Generator EPA ID:	NYD003933355
Trans1 EPA ID:	OHD075006304
Trans2 EPA ID:	Not reported
TSDF ID:	OHD055522429
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00023
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	002
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	83

Document ID:	NYO1031967
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	840718
Trans1 Recv Date:	840718
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	840719
Part A Recv Date:	840904
Part B Recv Date:	840726
Generator EPA ID:	NYD003933355

ACTIVE STEEL DRUM CO INC (Continued) **1000265123**

Trans1 EPA ID:	OHD075006304
Trans2 EPA ID:	Not reported
TSDF ID:	OHD055522429
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00012
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	84

EPA ID:	NYP000775650
Country:	USA
Mailing Name:	ACTIVE STEEL DRUM
Mailing Contact:	UNKNOWN
Mailing Address:	52-30 34TH ST
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip4:	3202
Mailing Country:	USA
Mailing Phone:	212-786-9300

Document ID:	NJO0174158
Manifest Status:	Completed copy
Trans1 State ID:	S3002BN
Trans2 State ID:	Not reported
Generator Ship Date:	830603
Trans1 Recv Date:	830603
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	830603
Part A Recv Date:	030614
Part B Recv Date:	030614
Generator EPA ID:	NYD003933355
Trans1 EPA ID:	NJD096865837
Trans2 EPA ID:	Not reported
TSDF ID:	NJD096865837
Waste Code:	D000 - NON-LISTED TOXIC WASTES
Quantity:	06000
Units:	P - Pounds
Number of Containers:	012
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	02400
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	048
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	100
Year:	83

ACTIVE STEEL DRUM CO INC (Continued) **1000265123**

Document ID:	NYO1554021
Manifest Status:	Completed copy
Trans1 State ID:	NYJA045
Trans2 State ID:	Not reported
Generator Ship Date:	830504
Trans1 Recv Date:	830504
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	830504
Part A Recv Date:	030509
Part B Recv Date:	030509
Generator EPA ID:	NYD003933355
Trans1 EPA ID:	NJD096865837
Trans2 EPA ID:	Not reported
TSDF ID:	NJD096865837
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00950
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	019
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	83

Document ID:	NYO1748151
Manifest Status:	Completed copy
Trans1 State ID:	NYOH003
Trans2 State ID:	Not reported
Generator Ship Date:	830407
Trans1 Recv Date:	830407
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	830408
Part A Recv Date:	030502
Part B Recv Date:	030502
Generator EPA ID:	NYP000775650
Trans1 EPA ID:	OHD075006304
Trans2 EPA ID:	Not reported
TSDF ID:	OHD055522429
Waste Code:	U220 - TOLUENE
Quantity:	00030
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	83

Document ID:	NYO1748187
Manifest Status:	Completed copy
Trans1 State ID:	NYOH003
Trans2 State ID:	Not reported
Generator Ship Date:	830409
Trans1 Recv Date:	830409
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	830411
Part A Recv Date:	030502

ACTIVE STEEL DRUM CO INC (Continued) **1000265123**

Part B Recv Date:	030502
Generator EPA ID:	NYD003933355
Trans1 EPA ID:	OHD075006304
Trans2 EPA ID:	Not reported
TSDF ID:	OHD055522429
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00023
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	002
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	83

Document ID:	NYO1031967
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	840718
Trans1 Recv Date:	840718
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	840719
Part A Recv Date:	840904
Part B Recv Date:	840726
Generator EPA ID:	NYD003933355
Trans1 EPA ID:	OHD075006304
Trans2 EPA ID:	Not reported
TSDF ID:	OHD055522429
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00012
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	84

238
NNE
1/2-1
0.794 mi.
4193 ft.

JUNG SUN LAUNDRY SITE **NY SHWS** **S110246984**
37-10 24TH STREET **NY DRYCLEANERS** **N/A**
LONG ISLAND CITY, NY 11101

Relative:
Higher

Actual:
19 ft.

SHWS:

Program:	HW
Site Code:	374812
Classification:	SIGNIFICANT THREAT TO THE PUBLIC HEALTH OR ENVIRONMENT - ACTION REQUIRED.
Region:	2
Acres:	.480
HW Code:	241102
Record Add:	12/13/2006
Record Upd:	10/08/2013
Updated By:	JAMORAS
Site Description:	Location: The Site is located in a mixed residential/commercial/light industrial area of Long Island City (Borough of Queens), NY. The location of the Site is the west corner of the intersection of 24th

JUNG SUN LAUNDRY SITE (Continued) **S110246984**

Street and 37th Avenue. Site Features: The site consists of four property lots. The main site features included single story buildings on three lots and an open area on the fourth lot. There were three inter-connected single story buildings, which occupied three adjacent lots. Recently (late summer 2013)the new owner demolished the structures on two lots down to the slab. The previous owner still owns one lot and the abandoned structure on that lot is still there. Approximately one third of the Site is made up of the fourth lot, which has and continues to be an open area which extends to the west up to 23rd Street. The open area also houses a tractor trailer sized metal storage container. The site is currently secured with a fence and a lockable gate. Current Zoning and Land Use: The site property is currently inactive and is zoned for commercial use. The surrounding parcels are currently used for a combination of commercial, light industrial and utility right-of-ways. The nearest residential area is located north (upgradient) of the site, on the other side of 37th Avenue. There is a residential area approximately 400 feet south (downgradient) of the Site, on the south side of 38th Avenue. Past Use of the Site: From the 1930s to the late 1980s, the Site was used as a commercial laundry. The Site was utilized as a commercial dry cleaner from the late 1980s to the mid 1990s. Prior uses that appear to have led to site contamination include poor housekeeping and spills associated with the dry cleaning operation. An adjacent property owner conducted a Phase I Environmental Site Assessment in September 2003, a Phase 2 Limited Subsurface Investigation in October 2003 and a Phase 2 Limited Groundwater Investigation in December 2003. The Department conducted a Site Characterization from August 2007 through March 2010. In October 2010, the Site was placed on the Registry of Inactive Hazardous Waste Disposal Sites as a Class 2 site.Site Geology and Hydrogeology: Subsurface material consists of sand and some silt and urban fill. The depth to the groundwater varies from approximately 13 to 15 feet below the ground surface. On-site groundwater flow direction is relatively flat; the general flow direction appears to be towards the southwest.

Env Problem: Nature and Extent of Contamination: The primary contaminants of concern at the site are tetrachloroethene (PCE) and its degradation products trichloroethene (TCE), cis-1,2-dichloroethene (cis-1,2-DCE), trans-1,2-dichloroethene (trans-1,2-DCE) and vinyl chloride (VC). Soil - During 2012 remedial investigation PCE, TCE and 1,2-DCE have been found in on-site soils at concentrations up to 83 parts per million (ppm), 0.22 ppm and 0.17 ppm respectively. The unrestricted use RSCOs for PCE has been exceeded. Groundwater - PCE, TCE, cis-1,2-DCE, trans-1,2-DCE and VC have been detected in on-site shallow groundwater at concentrations up to 11000 parts per billion (ppb), 1200 ppb, 21000 ppb, 130 ppb and 390 ppb respectively. Groundwater standards have been exceeded for PCE, TCE, cis-1,2-dichloroethene, trans-1,2-Dichloroethene, vinyl chloride and chloroform. Per April and June 2012 groundwater data, the groundwater plume has migrated approximately 400 feet off-site. Soil Vapor & Indoor Air: PCE and TCE were detected in on-site soil vapor at levels up to 280,000 microgram per cubic meter (g/m3) and 130,000 g/m3, respectively, and off-site at levels up to 13,000 g/m3 and 420 g/m3, respectively. Special Resources Impacted/Threatened: The site is located in the urban area and Fish and Wildlife Impact Analysis is not warranted. Significant Threat: The site poses a significant environmental threat because the area overlies a sole-source aquifer

JUNG SUN LAUNDRY SITE (Continued) **S110246984**

	and because there is an ongoing release of PCE and TCE from soil into groundwater.
Health Problem:	Contact with contaminated soil is not expected since it is located at depth and covered by buildings, asphalt and concrete. Ingestion of contaminated groundwater is not likely since the area is served with public water. Site-related contaminants are present in soil vapor. Therefore, there is a potential for soil vapor intrusion to occur in on-site and off-site structures. Investigation of this potential pathway is recommended.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	5/6/2010 3:30:00 PM
Record Upd:	9/19/2013 3:00:00 PM
Updated By:	kbdilige
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tienya Smith
Owner Company:	Queens Library: Long Island City Branch
Owner Address:	37-44 21 Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	01
Owner Name:	Tong Yang
Owner Company:	Jung Sun Laundry Corp.
Owner Address:	37-10 24th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	01
Owner Name:	Not reported
Owner Company:	Feiyang Group, LLC
Owner Address:	82-19 Grenfell Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Kew Gardens, NY 11415
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	01
Owner Name:	c/o Tony X.F. Yang
Owner Company:	Feiyang Group, LLC
Owner Address:	37-08 24th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	01
Owner Name:	Gurpal Cheema
Owner Company:	New Generation Development LLC.

JUNG SUN LAUNDRY SITE (Continued) **S110246984**

Owner Address: 37-10 24th Street
Owner Addr2: Not reported
Owner City,St,Zip: Queens, NY 11101
Owner Country: United States of America
HW Code: 241102
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 241102
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 0711317
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 3/31/2009 11:06:00 AM
Record Updated: 3/31/2009 11:06:00 AM
Updated By: JAAVERSA

DRYCLEANERS:
Facility ID: 2-6304-00393
Phone Number: 718-937-0428
Region: Not reported
Registration Effective Date: N/A
Inspection Date: 04SEP21
Install Date: 88/99/04
Drop Shop: Y
Shutdown: Not reported
Alternate Solvent: WATER
Current Business: Not reported

---

239 **NATIONAL RUBBER & BACKING CORP** **RCRA NonGen / NLR** **1000259753**
North **38-31 9TH ST** **NY SHWS** **NYD990690190**
1/2-1 **LONG ISLAND CITY, NY 11101** **NY LTANKS**
0.834 mi. **NY HIST UST**
4406 ft. **NY HIST AST**
NY MANIFEST
Relative: **NY VCP**
Lower **NY CBS**

Actual: **13 ft.**

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: NATIONAL RUBBER & BACKING CORP
Facility address: 38-31 9TH ST
LONG ISLAND CITY, NY 11101
EPA ID: NYD990690190
Mailing address: 9TH ST
LONG ISLAND CITY, NY 11101
Contact: MARC HALPERN
Contact address: 9TH ST
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: (718) 784-7945
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NATIONAL RUBBER & BACKING CORP
Classification: Not a generator, verified

Date form received by agency: 08/22/1996
Facility name: NATIONAL RUBBER & BACKING CORP
Site name: NATIONAL RUBBER ADHESIVES INC
Classification: Large Quantity Generator

Date form received by agency: 02/21/1992
Facility name: NATIONAL RUBBER & BACKING CORP
Site name: NATIONAL RUBBER AND BACKING
Classification: Large Quantity Generator

Date form received by agency: 11/08/1985

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Facility name: NATIONAL RUBBER & BACKING CORP
Classification: Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 08/19/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 08/03/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

SHWS:
Program: HW
Site Code: 58713
Classification: SIGNIFICANT THREAT TO THE PUBLIC HEALTH OR ENVIRONMENT - ACTION REQUIRED.
Region: 2
Acres: 1.000
HW Code: 241028
Record Add: 11/18/1999
Record Upd: 03/27/2013
Updated By: JAQUINN
Site Description: LOCATION: The site is located in an urban/industrial section of Long Island City at the intersection of 9th Street between 38th Avenue and 40th Avenue. It is located on the east side of 9th Street, approximately 0.4 miles north of the Queensboro Bridge. SITE FEATURES: The property extends 335 feet from the north to the south and 117 feet from the west to the east. The entire property is occupied by a 30,000 square feet, one story, slab-on-grand masonry building. A small courtyard is located in the central portion of the building on the western side. The site and surrounding areas are generally level.CURRRENT ZONING/USE(S): The site is currently zoned commercial. The site is currently used as a marble fabrication shop, an automotive repair shop, and a production studio. Another tenant occupies the other one-third of the building for storage of sheet metal and supplies for an off-site manufacturing business. No metal fabrication, cutting, or manufacturing associated with this business takes place on this site. PAST USE OF SITE: National Rubber Adhesives, Inc. operated a manufacturing facility for adhesives until 1995 and operated at this location for 62 years. (National Rubber Adhesives, Inc. occupied the northern two-thirds of the building.) Five underground storage tanks (USTs) were closed in-place, including one toluene, two gasoline, one methyl ethyl ketone (MEK) and one heptane UST. OPERABLE UNIT(S): The site is being managed through two operable units (OU). OU1 is for off-site work and OU2 is for on-site work. Each OU will include investigating for soil and groundwater contamination. SITE GEOLOGY AND HYDROGEOLOGY: The site is approximately 15 to 20 feet above mean sea level. The nearest surface water body is the East River, approximately one quarter mile west of the site. Groundwater was observed approximately 5 to 10 feet below

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

	ground surface and flows in a westerly direction toward the East River. The depth to bedrock varies across the investigation area from 10 to 15 feet below surface.
Env Problem:	NATURE AND EXTENT OF CONTAMINATION:Based upon investigations to date, the primary contaminants of concern at the site include toluene. Toluene has been detected at levels as high as 280,000,000 parts per billion (ppb) in groundwater in MW-2, which is above the respective groundwater standard of 5 ppb. Other wells have shown levels of toluene in the 10,000s ppb. Benzene, ethylbenzene, and xylenes have all been shown to be elevated. These previous investigations have identified exceedances of standards, criteria and guidance for those contaminants in soil as well. Elevated levels of benzene and toluene were also noted in the soil vapor as well. The groundwater plume appears to be migrating off-site, however the extent of the plume is unknown. In 2011, the concentration of toluene was found as high as 130,000 ppb in an off-site location. Off-site impacts have been delineated and the extent of the toluene plume does not appear to impact the East River. SPECIAL RESOURCES IMPACTED/THREATENED : None known.SIGNIFICANT THREAT: A significant threat is posed from potential exposure to site related contaminants from soil vapor intrusion both on and off-site structures. Exposures to contaminated groundwater are not expected because public water serves the area residents.
Health Problem:	Elevated levels of volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), and metals have been identified in soil and groundwater at this site. The area is paved and served by pubic water so exposures to contaminated soils and groundwater are unlikely. Due to the high levels of VOCs in on-site groundwater, there is the potential for exposures related to soil vapor intrusion in surrounding buildings. A soil vapor investigation is planned as part of the ongoing remedial investigation.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	unknown
Disp Term:	unknown
Lat/Long:	40:45:30:0 / 73:56:39:0
Dell:	False
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	11/18/1999 12:00:00 PM
Updated By:	INITIAL
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	National Rubber Adhesives, Inc.
Owner Address:	38-31 9th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11385
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	UNKNOWN
Owner Address:	25 KNICKERBOCKER AVE.
Owner Addr2:	Not reported

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Owner City,St,Zip: BROOKLYN, NY 11101
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: E
Owner Name: Not reported
Owner Company: UNKNOWN3
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: National Rubber Adhesives, Inc.
Owner Address: 25 Knickerbocker Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11208
Owner Country: United States of America
HW Code: 241028
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 241028
Waste Type: TOLUENE U-220 (F005 WASTE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 241028
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 241028
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C241028
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 5/27/2008 11:08:00 AM
Record Updated: 5/27/2008 11:08:00 AM
Updated By: DMMOLOUG
Crossref ID: V00662
Cross Ref Type Code: 04
Cross Ref Type: VC Site ID
Record Added Date: 8/4/2003 1:42:00 PM
Record Updated: 8/4/2003 1:42:00 PM
Updated By: ajsylves
Crossref ID: NYD990690190
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 11/18/1999 12:00:00 PM
Record Updated: 5/10/2001 4:31:00 PM
Updated By: REGTRANS

LTANKS:
Site ID: 127024
Spill Number/Closed Date: 9602231 / Not Reported
Spill Date: 3/1/1996

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates a file or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	PECK
Referred To:	Not reported
Reported to Dept:	5/16/1996
CID:	266
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	1
Date Entered In Computer:	5/16/1996
Spill Record Last Update:	5/11/2004
Spiller Name:	YALE BLOCK
Spiller Company:	NATIONAL RUBBER ADHESIVES
Spiller Address:	38-31 9TH STREET
Spiller City,St,Zip:	LONG ISLAND CITY, NY 11101-
Spiller County:	001
Spiller Contact:	YALE BLOCK
Spiller Phone:	(718) 497-5200
Spiller Extention:	234
DEC Region:	2
DER Facility ID:	109736
DEC Memo:	Not reported
Remarks:	PHASE 1 AND PARTIAL PHASE 2 SITE ASSESSMENT PERFORMED AT SPILLER'S REQUEST. CALLER KNEW THAT THERE WERE UNDERGROUND STORAGE TANKS THAT HAD BEEN CLOSED IN PLACE. SOME OF THIS CONTAMINATION POSSIBLY DATE BACK 50 YEARS OR MORE. CALLER WILL CONTACT REGION 2 OFFICE FOR FURTHER INFORMATION.

Material:

Site ID:	127024
Operable Unit ID:	1033794
Operable Unit:	01
Material ID:	352039
Material Code:	0042A
Material Name:	XYLENE (MIXED)
Case No.:	01330207
Material FA:	Hazardous Material
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	127024
Operable Unit ID:	1033794
Operable Unit:	01
Material ID:	352040
Material Code:	0230A
Material Name:	ETHYLBENZENE
Case No.:	00100414

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Material FA:	Hazardous Material
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	127024
Operable Unit ID:	1033794
Operable Unit:	01
Material ID:	352038
Material Code:	0041B
Material Name:	TOLUOL
Case No.:	00108883
Material FA:	Hazardous Material
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

HIST UST:

PBS Number:	2-145203
SPDES Number:	Not reported
Emergency Contact:	YALE
Emergency Telephone:	(201) 894-9112
Operator:	NATIONAL RUBBER ADH INC.
Operator Telephone:	(718) 784-7945
Owner Name:	NATIONAL RUBBER ADHESIVES,INC.
Owner Address:	38-31 9TH STREET
Owner City,St,Zip:	LONG ISLAND CITY, NY 11104
Owner Telephone:	(718) 784-7945
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	NATIONAL ADHESIVES, INC.
Mailing Address:	38-31 9TH STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	LONG ISLAND CITY, NY 11101
Mailing Contact:	Not reported
Mailing Telephone:	(718) 784-7945
Owner Mark:	Second Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	38031 9TH ST
SWIS ID:	6301
Old PBS Number:	Not reported
Facility Type:	MANUFACTURING
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	12/01/1997

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Expiration Date:	11/24/2002
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	3000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	2-000015
Town or City:	NEW YORK CITY
County Code:	63
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNKNOWN
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	None
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	09/01/1994
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

HIST AST:

PBS Number:	2-145203
SWIS Code:	6301
Operator:	NATIONAL RUBBER ADH INC.
Facility Phone:	(718) 784-7945
Facility Addr2:	38031 9TH ST
Facility Type:	MANUFACTURING
Emergency:	YALE
Emergency Tel:	(201) 894-9112
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	NATIONAL RUBBER ADHESIVES,INC.
Owner Address:	38-31 9TH STREET
Owner City,St,Zip:	LONG ISLAND CITY, NY 11104
Federal ID:	Not reported
Owner Tel:	(718) 784-7945
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	Not reported
Mailing Name:	NATIONAL ADHESIVES, INC.
Mailing Address:	38-31 9TH STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	LONG ISLAND CITY, NY 11101
Mailing Telephone:	(718) 784-7945
Owner Mark:	Second Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	12/01/1997
Expiration:	11/24/2002
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	3000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	2-000015
Town or City:	NEW YORK CITY
County Code:	63
Town or City Code:	01
Region:	2

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Tank ID:	008
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	3000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	0
Tank External:	05
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	00
Tank Containment:	Diking
Leak Detection:	00
Overfill Protection:	04
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

NY MANIFEST:

EPA ID:	NYD990690190
Country:	USA
Mailing Name:	NATIONAL RUBBER & ADHESIVES INC
Mailing Contact:	NATIONAL RUBBER & ADHESIVES INC
Mailing Address:	38-31 NINTH STREET
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-784-7945

Document ID:	NJA0247263
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPS-10
Trans2 State ID:	Not reported
Generator Ship Date:	870212
Trans1 Recv Date:	870212
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870212
Part A Recv Date:	870320
Part B Recv Date:	870305
Generator EPA ID:	NYD990690190
Trans1 EPA ID:	NJD000813477
Trans2 EPA ID:	Not reported
TSDF ID:	NJD080631369
Waste Code:	X940 - NJ UNKNOWN

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Quantity:	09600
Units:	P - Pounds
Number of Containers:	019
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	87

Document ID:	NJA2137832
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPE632
Trans2 State ID:	Not reported
Generator Ship Date:	961010
Trans1 Recv Date:	961010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	961010
Part A Recv Date:	961105
Part B Recv Date:	961031
Generator EPA ID:	NYD990690190
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00400
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	06000
Units:	P - Pounds
Number of Containers:	010
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	96

Document ID:	NJA4094772
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	02/27/2002
Trans1 Recv Date:	02/27/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/27/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD990690190
Trans1 EPA ID:	NJD980536593
Trans2 EPA ID:	Not reported
TSDF ID:	NJDEP5016
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	06000
Units:	P - Pounds

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Number of Containers: 015
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 02400
Units: P - Pounds
Number of Containers: 008
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: U044 - CHLOROFORM
Quantity: 00200
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2002

Document ID: NJA1176296
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJDEPS632
Trans2 State ID: Not reported
Generator Ship Date: 911010
Trans1 Recv Date: 911010
Trans2 Recv Date: Not reported
TSD Site Recv Date: 911010
Part A Recv Date: 911101
Part B Recv Date: 911106
Generator EPA ID: NYD990690190
Trans1 EPA ID: NJD991291584
Trans2 EPA ID: Not reported
TSDF ID: NJD980536593
Waste Code: U044 - CHLOROFORM
Quantity: 10000
Units: P - Pounds
Number of Containers: 070
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91

Document ID: NJA0981404
Manifest Status: Completed copy
Trans1 State ID: NJDEPE632
Trans2 State ID: Not reported
Generator Ship Date: 950526
Trans1 Recv Date: 950526
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950530
Part A Recv Date: 950606
Part B Recv Date: 950613
Generator EPA ID: NYD990690190
Trans1 EPA ID: NJD991291584

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00800
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	01200
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	03500
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	95

Document ID:	NJA2768510
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPE632
Trans2 State ID:	Not reported
Generator Ship Date:	970610
Trans1 Recv Date:	970610
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	970612
Part A Recv Date:	Not reported
Part B Recv Date:	970710
Generator EPA ID:	NYD990690190
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	D022 - CHLOROFORM 6.0 MG/L TCLP
Quantity:	08400
Units:	P - Pounds
Number of Containers:	014
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	97

Document ID:	NJA2783045
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	12/14/1998
Trans1 Recv Date:	12/14/1998
Trans2 Recv Date:	Not reported

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

TSD Site Recv Date: 12/16/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD990690190
Trans1 EPA ID: NJD980536593
Trans2 EPA ID: Not reported
TSDF ID: NJDEP5016
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 04400
Units: P - Pounds
Number of Containers: 011
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 98

Document ID: NJA2782909
Manifest Status: Not reported
Trans1 State ID: NJD080631369
Trans2 State ID: Not reported
Generator Ship Date: 04/21/1998
Trans1 Recv Date: 04/21/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/21/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD990690190
Trans1 EPA ID: NJD980536593
Trans2 EPA ID: Not reported
TSDF ID: NJDEP5016
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 02800
Units: P - Pounds
Number of Containers: 007
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 98

Document ID: NJA0981219
Manifest Status: Completed copy
Trans1 State ID: NJDEPS632
Trans2 State ID: Not reported
Generator Ship Date: 920619
Trans1 Recv Date: 920619
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920619
Part A Recv Date: Not reported
Part B Recv Date: 920708
Generator EPA ID: NYD990690190
Trans1 EPA ID: NJD991291584
Trans2 EPA ID: Not reported
TSDF ID: NJD980536593
Waste Code: D022 - CHLOROFORM 6.0 MG/L TCLP
Quantity: 06750

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Units:	P - Pounds
Number of Containers:	009
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	92

Document ID:	NJA0755037
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	920115
Trans1 Recv Date:	920115
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	920115
Part A Recv Date:	920127
Part B Recv Date:	920129
Generator EPA ID:	NYD990690190
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	U044 - CHLOROFORM
Quantity:	10500
Units:	P - Pounds
Number of Containers:	021
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	92

Document ID:	NJA1883086
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPE632
Trans2 State ID:	Not reported
Generator Ship Date:	950314
Trans1 Recv Date:	950314
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950314
Part A Recv Date:	950321
Part B Recv Date:	950417
Generator EPA ID:	NYD990690190
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	01600
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	08400
Units:	P - Pounds
Number of Containers:	012

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	95

Document ID:	NJA0165006
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	860203
Trans1 Recv Date:	860203
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	860204
Part A Recv Date:	860303
Part B Recv Date:	860212
Generator EPA ID:	NYD990690190
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID:	NJD080631369
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	21000
Units:	P - Pounds
Number of Containers:	042
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	86

Document ID:	NJA0366527
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS103
Trans2 State ID:	Not reported
Generator Ship Date:	870929
Trans1 Recv Date:	870929
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870929
Part A Recv Date:	871005
Part B Recv Date:	871014
Generator EPA ID:	NYD990690190
Trans1 EPA ID:	NJD000813477
Trans2 EPA ID:	Not reported
TSDF ID:	NJD080631369
Waste Code:	U044 - CHLOROFORM
Quantity:	15500
Units:	P - Pounds
Number of Containers:	031
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	87

Document ID:	NJA0980837
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPS632

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Trans2 State ID:	Not reported
Generator Ship Date:	901121
Trans1 Recv Date:	901121
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	901121
Part A Recv Date:	901231
Part B Recv Date:	910102
Generator EPA ID:	NYD990690190
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	U044 - CHLOROFORM
Quantity:	10500
Units:	P - Pounds
Number of Containers:	021
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	90

Document ID:	NJA2176962
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPE632
Trans2 State ID:	Not reported
Generator Ship Date:	950929
Trans1 Recv Date:	950929
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	951002
Part A Recv Date:	951010
Part B Recv Date:	951019
Generator EPA ID:	NYD990690190
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00400
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	08400
Units:	P - Pounds
Number of Containers:	012
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	95

Document ID:	NJA1164168
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	910619

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Trans1 Recv Date:	910619
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910619
Part A Recv Date:	910629
Part B Recv Date:	910709
Generator EPA ID:	NYD990690190
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	U044 - CHLOROFORM
Quantity:	07600
Units:	P - Pounds
Number of Containers:	019
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	91

Document ID:	NJA0981124
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS632
Trans2 State ID:	Not reported
Generator Ship Date:	921110
Trans1 Recv Date:	921110
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	921110
Part A Recv Date:	Not reported
Part B Recv Date:	921120
Generator EPA ID:	NYD990690190
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	D022 - CHLOROFORM 6.0 MG/L TCLP
Quantity:	14700
Units:	P - Pounds
Number of Containers:	021
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	92

Document ID:	NJA0755345
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPE632
Trans2 State ID:	Not reported
Generator Ship Date:	940523
Trans1 Recv Date:	940523
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	940523
Part A Recv Date:	940603
Part B Recv Date:	940607
Generator EPA ID:	NYD990690190
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	02000
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	94

Document ID:	NJA1882894
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPE632
Trans2 State ID:	Not reported
Generator Ship Date:	941011
Trans1 Recv Date:	941011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	941011
Part A Recv Date:	941019
Part B Recv Date:	941024
Generator EPA ID:	NYD990690190
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	01200
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	94

Document ID:	NJA1882977
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPE632
Trans2 State ID:	Not reported
Generator Ship Date:	941214
Trans1 Recv Date:	941214
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	941214
Part A Recv Date:	941221
Part B Recv Date:	950103
Generator EPA ID:	NYD990690190
Trans1 EPA ID:	NJD991291584
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00800
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	94

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

VCP:

Program Type:	VCP
Site Code:	57620
HW Code:	V00173
Site Class:	N
SWIS:	4101
Region:	2
Town:	New York City
Acres:	Not reported
Date Record Added:	11/30/2000
Date Record Updated:	02/01/2005
Updated By:	RJCOZZY
Site Description:	The property is located within an urban industrialized section of Long Island City. The site extends 335 feet from the north to the south and 117 feet from the west to the east. The entire site is occupied by a 30,000 square feet, one story building. There is a small courtyard in the central portion of the building, on its western side. The site is approximately 15 to 20 feet above mean sea level. The nearest surface water body is the East River, approximately one quarter mile west of the site.See Registry Site # 241028 and Brownfield Cleanup Program Site # C241028.
Env Problem:	See Registry Site # 241028 and Brownfield Cleanup Program Site # C241028
Health Problem:	Not reported

CBS:

CBS Number:	2-000015
Program Type:	CBS
Facility Status:	Unregulated
Expiration Date:	N/A
Dec Region:	2
UTMX:	589256.22733000
UTMY:	4512690.5957800

AS240 **RAVENSWOOD POWER STATION** **NY SHWS** **S102239646**
North **38-54 VERNON BOULEVARD** **NY LTANKS** **N/A**
1/2-1 **LONG ISLAND CITY, NY** **NY MOSF UST**
0.856 mi. **NY CBS AST**
4519 ft. **Site 1 of 2 in cluster AS** **NY MANIFEST**
NY Spills
Relative: **NY VCP**
Lower **NY SPDES**
NY MOSF
Actual: **NY CBS**
12 ft.

SHWS:

Program:	HW
Site Code:	416958
Classification:	P
Region:	2
Acres:	Not reported
HW Code:	241119
Record Add:	07/23/2009

RAVENSWOOD POWER STATION (Continued) **S102239646**

Record Upd: 10/31/2013
Updated By: GWCROSS
Site Description: Location: The Ravenswood former MGP site is located at 38-54 Vernon Boulevard in the Long Island City section of the Borough of Queens. The property is noted as Tax Lot 1 in part of block 357 on the Tax Map of the City of New York, Queens CountyThe site is located within the boundary of a complex of active electric and steam generating facilities in a predominantly industrial and commercial area. The site is bordered on the east by light industrial and commercial buildings and on the west by the East River. The site formerly housed a Manufactured Gas Plant operated by Con Edison and its predecessor companies. The precise location of the MGP structures has not been fully established because of the extensive reworking of the property associated with construction of the power plants which now occupy and surround the original MGP site.Remedial History: A portion of the site was remediated under the Voluntary Cleanup Program. See site V000368. The principal VCP issue was the presence of a No. 6 oil spill from an in-plant pipeline. Petroleum-impacted soil was excavated in 2005. No MGP tar-contaminated soil was identified at that time, but MGP related structures or soil contamination may remain in other portions of the site or at depth.
Env Problem: Extensive soil removal has taken place on the site, both for the construction of the power plants that occupy the site, and for remediation of a No. 6 oil spill. Although it appears that significant portions of the former MGP have been excavated down to bedrock, it is not known to what extent MGP structures and MGP soil contamination may remain in the deep subsurface.A bedrock steam tunnel lies beneath the East River at this location, allowing waste steam from the turbine plants to be provided to the steam-heat distribution system in Manhattan. Tar from the former MGP can be seen dripping from the roof of this tunnel, roughly 150 feet below ground surface. The source of the tar has not been determined. The tunnel can not be accessed by the public, and is only occasionally used by utility workers. Engineering controls are in place to prevent direct contact with the tar by utility workers.
Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Owner
Sub Type: NNN
Owner Name: Not reported
Owner Company: SE Ravenswood Trust
Owner Address: 37-20 37th Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101

RAVENSWOOD POWER STATION (Continued) **S102239646**

Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

LTANKS:

Site ID:	239188
Spill Number/Closed Date:	9613378 / 2/13/1997
Spill Date:	2/12/1997
Spill Cause:	Tank Overfill
Spill Source:	Commercial Vehicle
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	2/12/1997
CID:	252
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2/12/1997
Spill Record Last Update:	11/12/2003
Spiller Name:	TIM SOILCH
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY 10003
Spiller County:	001
Spiller Contact:	STEVE ROMERO
Spiller Phone:	(212) 580-6763
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	244873
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"
Remarks:	UPON FILLING AIR COMPRESSOR DIESEL FUEL SPILLED ON TO PAVEMENTSPILL HAS BEEN CLEANED UP

Material:

Site ID:	239188
Operable Unit ID:	1040956
Operable Unit:	01
Material ID:	338486
Material Code:	0008

RAVENSWOOD POWER STATION (Continued) **S102239646**

Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	8
Units:	Gallons
Recovered:	8
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	239166
Spill Number/Closed Date:	9601426 / 5/30/1996
Spill Date:	4/28/1996
Spill Cause:	Tank Failure
Spill Source:	Passenger Vehicle
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	4/28/1996
CID:	312
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	4/28/1996
Spill Record Last Update:	6/27/1996
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	NEW YORK, NY 10003
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	(0) -
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	244873
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"
Remarks:	hole in gas tank - cleaned up

Material:

Site ID:	239166
Operable Unit ID:	1029072
Operable Unit:	01
Material ID:	566843
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported

RAVENSWOOD POWER STATION (Continued) **S102239646**

Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: 5
Resource Affected: Not reported
Oxygenate: False

Tank Test:

MOSF UST:
Id/Status: 2-1960 / ACTIVE FACILITY
SWIS Code: 63
Facility Town: NEW YORK CITY
Contact Phone: (718) 706-2707
Emerg Contact: SHIFT SUPERVISOR
Emergency Telephone: (718) 706-2753
CBS Number: 2-000063
SPDES Num: 0-005193
Total Tanks: 24
Total Capacity: 4337274
Avg Throughput: 149854
License Stat: 1
Facility Type: MANUFACTURING
Prod Xfer Options: AC
Expiration Date: 03/31/2003
Applic Rcvd: 01/05/2001
Operator: DOMINIC DI GIORGIO
Owner Name: KEYSPAN-RAVENSWOOD SERVICES CORPORATION
Owner Address: ONE METROTECH CENTER
Owner City,St,Zip: BROOKLYN, NY 11201-3851
Owner Telephone: (631) 391-6140
Owner Type: Corporate/Commercial
Owner Status: 1
Owner Mark: Second Owner
Mail To Name: KEYSPAN ENERGY
Mail To Address: 445 BROADHOLLOW ROAD
Mail To Address 2: Not reported
Mail City,St,Zip: MELVILLE, NY 11747-
Mail To Contact: ROBERT D. TEETZ
Mail To Telephone: (631) 391-6140
Legal Agent Name: OFFICE OF THE SECRETARY OF THE COMPANY
Legal Agent Address: ONE METROTECH CENTER
Legal Agent City,St,Zip: BROOKLYN, NY 11201-3851
Date Filed: 03/99

Tank ID: F06-1
Tank Location: UNDERGROUND, VAULTED, WITH ACCESS
Install Date: 02/63
Capacity (Gal): 858022
Product: NOS 5 OR 6 FUEL OIL
Tank Status: Temporarily Out Of Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Aboveground/Underground Combination

RAVENSWOOD POWER STATION (Continued) **S102239646**

Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	20
Second Contain:	10
Leak Detection:	None
Overfill Protection:	23
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Latitude:	40|45|30
Longitude:	73|56|56
Status of Data:	Complete
Inspected Date:	08/05/1999
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/27/2000
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	F06-2
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS
Install Date:	02/63
Capacity (Gal):	842175
Product:	NOS 5 OR 6 FUEL OIL
Tank Status:	Temporarily Out Of Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	20
Second Contain:	10
Leak Detection:	None
Overfill Protection:	23
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Latitude:	40|45|30
Longitude:	73|56|56
Status of Data:	Complete
Inspected Date:	08/05/1999
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/27/2000
Federal Id No:	Not reported
COI Date:	/ /

RAVENSWOOD POWER STATION (Continued) **S102239646**

Tank ID:	F06-3
Tank Location:	UNDERGROUND
Install Date:	12/48
Capacity (Gal):	741465
Product:	NOS 5 OR 6 FUEL OIL
Tank Status:	Temporarily Out Of Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	20
Second Contain:	50
Leak Detection:	None
Overfill Protection:	23
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Latitude:	40|45|30
Longitude:	73|56|56
Status of Data:	Complete
Inspected Date:	08/05/1999
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/27/2000
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	RGSPIPELINE
Tank Location:	Not reported
Install Date:	00/00
Capacity (Gal):	362000
Product:	NOS 5 OR 6 FUEL OIL
Tank Status:	Temporarily Out Of Service
Tank Type:	Not reported
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Underground
Pipe Type:	Not reported
Pipe Internal:	Fiberglass Liner (FRP)
Pipe External:	Not reported
Second Contain:	None
Leak Detection:	Other
Overfill Protection:	Not reported
Dispenser:	Not reported
Test Date:	Not reported
Date Closed:	02/00
Latitude:	40|45|30
Longitude:	73|56|56
Status of Data:	Major Errors
Inspected Date:	08/05/1999

RAVENSWOOD POWER STATION (Continued) **S102239646**

Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/27/2000
Federal Id No: Not reported
COI Date: / /

Tank ID: T04
Tank Location: UNDERGROUND
Install Date: 12/70
Capacity (Gal): 1000
Product: KEROSENE
Tank Status: Temporarily Out Of Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Contain: 8
Leak Detection: None
Overfill Protection: Product Level Gauge
Dispenser: Suction
Test Date: /
Date Closed: Not reported
Latitude: 40|45|30
Longitude: 73|56|56
Status of Data: Complete
Inspected Date: 08/05/1999
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/27/2000
Federal Id No: Not reported
COI Date: / /

MOSF:
Facility ID: 2-1960
Program Type: MOSF
Tank Status: Active
Expiration Date: 2014/03/31
Dec Region: 2
UTMX: 589041.39688000
UTMY: 4512702.2995199

Facility ID: 2-1980
Program Type: MOSF
Tank Status: No Longer MOSF
Expiration Date: N/A

RAVENSWOOD POWER STATION (Continued) **S102239646**

Dec Region: 2
UTMX: 588348.02693000
UTMY: 4510881.1985099

CBS AST:

CBS Number:	2-000366
ICS Number:	Not reported
PBS Number:	Not reported
MOSF Number:	2-1960
SPDES Number:	0-005193
Facility Status:	ACTIVE FACILITY
Facility Type:	UTILITY
Telephone:	(718) 706-2707
Facility Town:	NEW YORK CITY
Region:	STATE
Expiration Date:	03/28/2002
Total Capacity of All Active Tanks(gal):	6000
Operator:	KEYSPAN-RAVENSWOOD SERVICES GR
Emergency Contact:	SHIFT SUPERVISOR
Emergency Phone:	(718) 706-2753
Owner Name:	LIC FUNDING, LP
Owner Address:	C/O MERRILL LYNCH SOUTH TOWER 14 FLOOR
Owner City,St,Zip:	NEW YORK, NY 10080-4114
Owner Telephone:	(212) 236-7203
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	KEYSPAN ENERGY
Mail Contact Addr:	445 BROADHOLLOW ROAD
Mail Contact Addr2:	Not reported
Mail Contact Contact:	ROBERT D. TEETZ
Mail Contact City,St,Zip:	MELVILLE, NY 11747
Mail Phone:	(631) 391-6140

Tank Id:	C-30
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	12/65
Tank Closed:	12/99
Capacity (Gal):	2000
Chemical:	Sodium hydroxide
Tank Location:	ABOVEGROUND
Tank Type:	Steel/carbon steel
Total Tanks:	3
Tank Secret:	False
Tank Containment:	Diking
Tank Error Status:	No Missing Data
Date Entered:	03/28/2000
Certified Date:	03/28/2000
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	1
Pipe Containment:	None,None

RAVENSWOOD POWER STATION (Continued) **S102239646**

Pipe Flag:	None,None
Leak Detection:	None,None
Overfill Protection:	04
Haz Percent:	50
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	40|45|39 / 77|56|49
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	40|45|39 / 77|56|49
Fiscal Amt for Registration Fee Correct:	40|45|39 / 77|56|49
Renewal Has Been Printed for Facility:	40|45|39 / 77|56|49
Pre-Printed Renewal App Last Printed:	40|45|39 / 77|56|49

Tank Id:	A30
CAS Number:	7664939
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	12/65
Tank Closed:	04/97
Capacity (Gal):	2000
Chemical:	Sulfuric acid
Tank Location:	ABOVEGROUND
Tank Type:	Steel/carbon steel
Total Tanks:	5
Tank Secret:	False
Tank Containment:	Diking
Tank Error Status:	No Missing Data
Date Entered:	06/15/1989
Certified Date:	03/28/2000
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	STAINLESS STEEL ALLOY
Pipe Internal:	None
Pipe External:	0
Pipe Containment:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Haz Percent:	93
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	40|45|39 / 73|56|49
Is Updated:	False
Renew Date:	03/01/93
Is It There:	False
Delinquent:	False
Date Expired:	06/15/95

RAVENSWOOD POWER STATION (Continued) **S102239646**

Owner Mark:	2
Certificate Needs to be Printed:	40|45|39 / 73|56|49
Fiscal Amt for Registration Fee Correct:	40|45|39 / 73|56|49
Renewal Has Been Printed for Facility:	40|45|39 / 73|56|49
Pre-Printed Renewal App Last Printed:	40|45|39 / 73|56|49

Tank Id:	EH30
CAS Number:	7681529
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	12/65
Tank Closed:	12/99
Capacity (Gal):	4000
Chemical:	Sodium hypochlorite
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Type:	Other
Total Tanks:	5
Tank Secret:	False
Tank Containment:	None
Tank Error Status:	No Missing Data
Date Entered:	06/15/1989
Certified Date:	03/28/2000
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	Other
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	Other
Pipe External:	1
Pipe Containment:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Haz Percent:	15
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	40|45|39 / 73|56|49
Is Updated:	False
Renew Date:	03/01/93
Is It There:	False
Delinquent:	False
Date Expired:	06/15/95
Owner Mark:	2
Certificate Needs to be Printed:	40|45|39 / 73|56|49
Fiscal Amt for Registration Fee Correct:	40|45|39 / 73|56|49
Renewal Has Been Printed for Facility:	40|45|39 / 73|56|49
Pre-Printed Renewal App Last Printed:	40|45|39 / 73|56|49

Tank Id:	WH30
CAS Number:	7681529
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	12/65
Tank Closed:	12/99

RAVENSWOOD POWER STATION (Continued) **S102239646**

Capacity (Gal):	4000
Chemical:	Sodium hypochlorite
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Type:	Other
Total Tanks:	5
Tank Secret:	False
Tank Containment:	None
Tank Error Status:	No Missing Data
Date Entered:	06/15/1989
Certified Date:	03/28/2000
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	Other
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	Other
Pipe External:	1
Pipe Containment:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Haz Percent:	15
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	40|45|39 / 73|56|49
Is Updated:	False
Renew Date:	03/01/93
Is It There:	False
Delinquent:	False
Date Expired:	06/15/95
Owner Mark:	2
Certificate Needs to be Printed:	40|45|39 / 73|56|49
Fiscal Amt for Registration Fee Correct:	40|45|39 / 73|56|49
Renewal Has Been Printed for Facility:	40|45|39 / 73|56|49
Pre-Printed Renewal App Last Printed:	40|45|39 / 73|56|49

Tank Id:	WH12
CAS Number:	7681529
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	12/62
Tank Closed:	12/99
Capacity (Gal):	4000
Chemical:	Sodium hypochlorite
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Type:	Other
Total Tanks:	5
Tank Secret:	False
Tank Containment:	None
Tank Error Status:	No Missing Data
Date Entered:	06/15/1989
Certified Date:	03/28/2000
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	Other
External Protection:	Painted/Asphalt Coating

RAVENSWOOD POWER STATION (Continued) **S102239646**

Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	Other
Pipe External:	1
Pipe Containment:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Haz Percent:	15
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	40|45|39 / 73|56|49
Is Updated:	False
Renew Date:	03/01/93
Is It There:	False
Delinquent:	False
Date Expired:	06/15/95
Owner Mark:	2
Certificate Needs to be Printed:	40|45|39 / 73|56|49
Fiscal Amt for Registration Fee Correct:	40|45|39 / 73|56|49
Renewal Has Been Printed for Facility:	40|45|39 / 73|56|49
Pre-Printed Renewal App Last Printed:	40|45|39 / 73|56|49

Click this hyperlink while viewing on your computer to access
9 additional NY_AST_CBS: record(s) in the EDR Site Report.

NY MANIFEST:

EPA ID:	NYR000072447
Country:	USA
Mailing Name:	KEYSPAN ENERGY RAVENSWOOD GENERATING STA
Mailing Contact:	E MILLER
Mailing Address:	38-54 VERNON BLVD
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11105
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-963-5407

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD000692061
Trans2 State ID:	Not reported
Generator Ship Date:	2012-03-27
Trans1 Recv Date:	2012-03-27
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-27
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported

RAVENSWOOD POWER STATION (Continued) **S102239646**

Quantity:	400.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	000531202VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	2012-09-05
Trans1 Recv Date:	2012-09-05
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-09-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	125.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	000679220VES
Import Ind:	N
Export Ind:	Y
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

RAVENSWOOD POWER STATION (Continued) **S102239646**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-27
Trans1 Recv Date:	2012-02-27
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-02-27
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	1.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	000681669VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-27
Trans1 Recv Date:	2012-02-27
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-02-27
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	5.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0

RAVENSWOOD POWER STATION (Continued) **S102239646**

Year:	2012
Manifest Tracking Num:	000681669VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-27
Trans1 Recv Date:	2012-02-27
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-02-27
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	10.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	000681669VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-27
Trans1 Recv Date:	2012-02-27

RAVENSWOOD POWER STATION (Continued) **S102239646**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-02-27
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	15.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	000681669VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD000692061
Generator Ship Date:	2011-01-25
Trans1 Recv Date:	2011-01-25
Trans2 Recv Date:	2011-01-28
TSD Site Recv Date:	2011-01-28
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	45.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000214878VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N

RAVENSWOOD POWER STATION (Continued) **S102239646**

Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD000692061
Generator Ship Date:	2011-01-25
Trans1 Recv Date:	2011-01-25
Trans2 Recv Date:	2011-01-28
TSD Site Recv Date:	2011-01-28
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	80.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000214878VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported

RAVENSWOOD POWER STATION (Continued) **S102239646**

Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	75.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	1.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

RAVENSWOOD POWER STATION (Continued) **S102239646**

Mgmt Method Type Code: H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	5.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	300.0
Units:	P - Pounds
Number of Containers:	2.0

RAVENSWOOD POWER STATION (Continued) **S102239646**

Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	3.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369

RAVENSWOOD POWER STATION (Continued) **S102239646**

Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	10.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	600.0
Units:	P - Pounds
Number of Containers:	6.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N

RAVENSWOOD POWER STATION (Continued) **S102239646**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	2011-12-05
Trans1 Recv Date:	2011-12-05
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2011-12-05
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000563392VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	04-Jun-2013 00:00:00
Trans1 Recv Date:	04-Jun-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07-Jun-2013 00:00:00
Part A Recv Date:	Not reported

RAVENSWOOD POWER STATION (Continued) **S102239646**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	10
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	000680222VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	04-Jun-2013 00:00:00
Trans1 Recv Date:	04-Jun-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07-Jun-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	1
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	000680222VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

RAVENSWOOD POWER STATION (Continued) **S102239646**

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD080631369
Trans2 State ID: Not reported
Generator Ship Date: 04-Jun-2013 00:00:00
Trans1 Recv Date: 04-Jun-2013 00:00:00
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07-Jun-2013 00:00:00
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000072447
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD980536593
Waste Code: Not reported
Quantity: 10
Units: P - Pounds
Number of Containers: 1
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 000680222VES
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD080631369
Trans2 State ID: Not reported
Generator Ship Date: 04-Jun-2013 00:00:00
Trans1 Recv Date: 04-Jun-2013 00:00:00
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07-Jun-2013 00:00:00
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000072447
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD980536593
Waste Code: Not reported

RAVENSWOOD POWER STATION (Continued) **S102239646**

Quantity:	10
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	000680222VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Click this hyperlink while viewing on your computer to access
7 additional NY_MANIFEST: record(s) in the EDR Site Report.

EPA ID:	NYP000072447
Country:	USA
Mailing Name:	KEYSPAN
Mailing Contact:	KEYSPAN
Mailing Address:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD000692061
Trans2 State ID:	Not reported
Generator Ship Date:	2012-03-27
Trans1 Recv Date:	2012-03-27
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-27
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	400.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.

RAVENSWOOD POWER STATION (Continued) **S102239646**

Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	000531202VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	2012-09-05
Trans1 Recv Date:	2012-09-05
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-09-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	125.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	000679220VES
Import Ind:	N
Export Ind:	Y
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-27

RAVENSWOOD POWER STATION (Continued) **S102239646**

Trans1 Recv Date:	2012-02-27
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-02-27
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	1.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	000681669VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-27
Trans1 Recv Date:	2012-02-27
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-02-27
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	5.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	000681669VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N

RAVENSWOOD POWER STATION (Continued) **S102239646**

Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-27
Trans1 Recv Date:	2012-02-27
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-02-27
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	10.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	000681669VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-27
Trans1 Recv Date:	2012-02-27
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-02-27
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447

RAVENSWOOD POWER STATION (Continued) **S102239646**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	15.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	000681669VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD000692061
Generator Ship Date:	2011-01-25
Trans1 Recv Date:	2011-01-25
Trans2 Recv Date:	2011-01-28
TSD Site Recv Date:	2011-01-28
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	45.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000214878VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported

RAVENSWOOD POWER STATION (Continued) **S102239646**

Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD000692061
Generator Ship Date:	2011-01-25
Trans1 Recv Date:	2011-01-25
Trans2 Recv Date:	2011-01-28
TSD Site Recv Date:	2011-01-28
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	80.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000214878VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	75.0
Units:	P - Pounds

RAVENSWOOD POWER STATION (Continued) **S102239646**

Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	1.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported

RAVENSWOOD POWER STATION (Continued) **S102239646**

Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	5.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	300.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES

RAVENSWOOD POWER STATION (Continued) **S102239646**

Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	3.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07

RAVENSWOOD POWER STATION (Continued) **S102239646**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	10.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	600.0
Units:	P - Pounds
Number of Containers:	6.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N

RAVENSWOOD POWER STATION (Continued) **S102239646**

Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD080631369
Trans2 State ID: Not reported
Generator Ship Date: 2011-12-05
Trans1 Recv Date: 2011-12-05
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2011-12-05
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000072447
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD980536593
Waste Code: Not reported
Quantity: 200.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2011
Manifest Tracking Num: 000563392VES
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD080631369
Trans2 State ID: Not reported
Generator Ship Date: 04-Jun-2013 00:00:00
Trans1 Recv Date: 04-Jun-2013 00:00:00
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07-Jun-2013 00:00:00
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000072447
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD980536593

RAVENSWOOD POWER STATION (Continued) **S102239646**

Waste Code:	Not reported
Quantity:	10
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	000680222VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	04-Jun-2013 00:00:00
Trans1 Recv Date:	04-Jun-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07-Jun-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	1
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	000680222VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

RAVENSWOOD POWER STATION (Continued) **S102239646**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	04-Jun-2013 00:00:00
Trans1 Recv Date:	04-Jun-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07-Jun-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	10
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	000680222VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	04-Jun-2013 00:00:00
Trans1 Recv Date:	04-Jun-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07-Jun-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	10
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1

RAVENSWOOD POWER STATION (Continued) **S102239646**

Year:	2013
Manifest Tracking Num:	000680222VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Click this hyperlink while viewing on your computer to access
7 additional NY_MANIFEST: record(s) in the EDR Site Report.

EPA ID:	NYP004137816
Country:	USA
Mailing Name:	CONSOLDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-2808

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD000692061
Trans2 State ID:	Not reported
Generator Ship Date:	2012-03-27
Trans1 Recv Date:	2012-03-27
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-03-27
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	400.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	000531202VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N

RAVENSWOOD POWER STATION (Continued) **S102239646**

Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	2012-09-05
Trans1 Recv Date:	2012-09-05
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-09-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	125.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	000679220VES
Import Ind:	N
Export Ind:	Y
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-27
Trans1 Recv Date:	2012-02-27
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-02-27
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447

RAVENSWOOD POWER STATION (Continued) **S102239646**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	1.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	000681669VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-27
Trans1 Recv Date:	2012-02-27
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-02-27
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	5.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	000681669VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported

RAVENSWOOD POWER STATION (Continued) **S102239646**

Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-27
Trans1 Recv Date:	2012-02-27
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-02-27
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	10.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	000681669VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	2012-02-27
Trans1 Recv Date:	2012-02-27
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-02-27
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	15.0
Units:	P - Pounds

RAVENSWOOD POWER STATION (Continued) **S102239646**

Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	000681669VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD000692061
Generator Ship Date:	2011-01-25
Trans1 Recv Date:	2011-01-25
Trans2 Recv Date:	2011-01-28
TSD Site Recv Date:	2011-01-28
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	45.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000214878VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported

RAVENSWOOD POWER STATION (Continued) **S102239646**

Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD000692061
Generator Ship Date:	2011-01-25
Trans1 Recv Date:	2011-01-25
Trans2 Recv Date:	2011-01-28
TSD Site Recv Date:	2011-01-28
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	80.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000214878VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	75.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES

RAVENSWOOD POWER STATION (Continued) **S102239646**

Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	1.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07

RAVENSWOOD POWER STATION (Continued) **S102239646**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	5.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	300.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N

RAVENSWOOD POWER STATION (Continued) **S102239646**

Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	3.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593

RAVENSWOOD POWER STATION (Continued) **S102239646**

Waste Code:	Not reported
Quantity:	10.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD080631369
Generator Ship Date:	2011-06-07
Trans1 Recv Date:	2011-06-07
Trans2 Recv Date:	2011-06-07
TSD Site Recv Date:	2011-06-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	600.0
Units:	P - Pounds
Number of Containers:	6.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000516461VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

RAVENSWOOD POWER STATION (Continued) **S102239646**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	2011-12-05
Trans1 Recv Date:	2011-12-05
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2011-12-05
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	000563392VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	04-Jun-2013 00:00:00
Trans1 Recv Date:	04-Jun-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07-Jun-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	10
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1

RAVENSWOOD POWER STATION (Continued) **S102239646**

Year:	2013
Manifest Tracking Num:	000680222VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	04-Jun-2013 00:00:00
Trans1 Recv Date:	04-Jun-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07-Jun-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	1
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	000680222VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	04-Jun-2013 00:00:00
Trans1 Recv Date:	04-Jun-2013 00:00:00

RAVENSWOOD POWER STATION (Continued) **S102239646**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07-Jun-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	10
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	000680222VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	04-Jun-2013 00:00:00
Trans1 Recv Date:	04-Jun-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07-Jun-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	10
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	000680222VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N

RAVENSWOOD POWER STATION (Continued) **S102239646**

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Click this hyperlink while viewing on your computer to access
7 additional NY_MANIFEST: record(s) in the EDR Site Report.

SPILLS:
Facility ID: 0006765
DER Facility ID: 244873
Facility Type: ER
Site ID: 239118
DEC Region: 2
Spill Date: 9/7/2000
Spill Number/Closed Date: 0006765 / 1/16/2001
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 4101
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 9/7/2000
CID: 322
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 9/7/2000
Spill Record Last Update: 1/16/2001
Spiller Name: UNKNOWN
Spiller Company: UNKNOWN
Spiller Address: UNKNOWN
Spiller City,St,Zip: UNKNOWN, NY
Spiller Company: 999
Contact Name: DOUG VOOS
Contact Phone: (516) 545-4007
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"Inforamtion received from KeySpan indicates that samples similar to extremely weathered turbine lube oil. All PCB results <1 ppm. Soil drummed.
Remarks: stain of unknown origin on the bluestone - samples taken and clean up pending lab results -

Material:
Site ID: 239118
Operable Unit ID: 827696
Operable Unit: 01
Material ID: 547873

RAVENSWOOD POWER STATION (Continued) **S102239646**

Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	1305911
DER Facility ID:	343924
Facility Type:	ER
Site ID:	486497
DEC Region:	2
Spill Date:	9/5/2013
Spill Number/Closed Date:	1305911 / 9/6/2013
Spill Cause:	Unknown
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	9/5/2013
CID:	Not reported
Water Affected:	EAST RIVER
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/5/2013
Spill Record Last Update:	9/6/2013
Spiller Name:	Not reported
Spiller Company:	TRANS CANADA POWER PLANT
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	PAUL SERVA
Contact Phone:	Not reported
DEC Memo:	during lube change, 40 gal spilled to lower level .Some entered drain. Kens marine en route to boom and determine if any entered river. Spill being cleaned inside on concrete. Spill cleaned, closed. No recovery made in river.
Remarks:	clean up underway/kens marine en route eta 0720 for boom deployment on east river outfall (discharge tunnel)Approx. 1/2 gal. has entered discharge tunnel

Material:

Site ID:	486497

RAVENSWOOD POWER STATION (Continued) **S102239646**

Operable Unit ID:	1236146
Operable Unit:	01
Material ID:	2235488
Material Code:	0013
Material Name:	Lube Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9806863
DER Facility ID:	244873
Facility Type:	ER
Site ID:	239229
DEC Region:	2
Spill Date:	9/4/1998
Spill Number/Closed Date:	9806863 / Not Reported
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	HEHUSSEI
Referred To:	CON ED DIVESTED
Reported to Dept:	9/4/1998
CID:	312
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	9/4/1998
Spill Record Last Update:	7/22/2013
Spiller Name:	KEN YAEGER
Spiller Company:	TRANSCANADA POWER
Spiller Address:	38-54 VERNON BLVD
Spiller City,St,Zip:	LONG ISLAND CITY, NY 11101
Spiller Company:	001
Contact Name:	HAHN
Contact Phone:	(718) 706-2753
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"Site investigation being conducted as part of divestiture process. Work plan submitted to DEC on 9/17/98.6/16/10 - changed DEC lead from Krimgold to JMOCONNE (JOC)4/14/11 - J.kann - DEC lead changed to J.Kann.07/22/13 - Re-assigned from Kann to Hussein (JOC)
Remarks:	SOIL BORINGS SHOW OIL CONTAMINATION AROUND 12 TO 14 FEET DOWN - THIS IS BY THE STEAM PLANT ON THE COMPLEX

RAVENSWOOD POWER STATION (Continued) **S102239646**

Material:

Site ID:	239229
Operable Unit ID:	1064470
Operable Unit:	01
Material ID:	318001
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9806885
DER Facility ID:	244873
Facility Type:	ER
Site ID:	239230
DEC Region:	2
Spill Date:	9/3/1998
Spill Number/Closed Date:	9806885 / 9/18/1998
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	9/4/1998
CID:	322
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/4/1998
Spill Record Last Update:	9/18/1998
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"9/4/98: update - gauge repalced, oil cleaned up.
Remarks:	retired fuel line became charged with steam the gauge on linebroke releasing the fuel - fuel leaked into a containment areacaller unsure on if clean up was done or not

RAVENSWOOD POWER STATION (Continued) **S102239646**

Material:

Site ID:	239230
Operable Unit ID:	1064486
Operable Unit:	01
Material ID:	318020
Material Code:	0003A
Material Name:	#6 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	17
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9608086
DER Facility ID:	244873
Facility Type:	ER
Site ID:	239175
DEC Region:	2
Spill Date:	9/28/1996
Spill Number/Closed Date:	9608086 / 10/2/1996
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	4101
Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	9/28/1996
CID:	275
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/28/1996
Spill Record Last Update:	10/17/1996
Spiller Name:	TIM SOILCH
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY 10003
Spiller Company:	001
Contact Name:	TIM SOLICH
Contact Phone:	(212) 580-6763
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ZHITOMIRSKY"
Remarks:	spilled from truck - all cleaned

Material:

Site ID:	239175

RAVENSWOOD POWER STATION (Continued) **S102239646**

Operable Unit ID:	1036344
Operable Unit:	01
Material ID:	343830
Material Code:	0015
Material Name:	Motor Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	Yes
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

VCP:

Program Type:	VCP
Site Code:	56967
HW Code:	V00368
Site Class:	C
SWIS:	4101
Region:	2
Town:	New York City
Acres:	Not reported
Date Record Added:	11/30/2000
Date Record Updated:	04/05/2007
Updated By:	dcwalsh
Site Description:	The proposed Ravenswood 250-Megawatt (MW) Combined Cycle Generating Station site is located at 38-54 Vernon Boulevard in the Long Island City section of the Borough and County of Queens, New York and denoted as Tax Lot 1 in part of block 357 on the Tax Map of the City of New York, Queens County. The site is located within the boundary of an active electric and steam generating facility in a predominantly industrial and commercial area. The area addressed by this Voluntary Cleanup Agreement is the footprint of a proposed 250-MW combined cycle electric generating plant. The site is bordered on the east by light industrial and commercial buildings; on the south by the existing Ravenswood Generating Station; on the north by the existing Ravenswood Gas Turbine facility; and on the west by the existing Ravenswood Steam Plant and the East River. The site was formerly a Manufactured Gas Plant operated by Con Edison and its predecessor companies. The site is currently occupied by a paved parking lot for Ravenswood employees. Site investigation has been completed at the site.
Env Problem:	The Site investigation conducted at the site revealed the presence of petroleum contamination related to a release from an on-site no. 6 oil pipeline. In addition, the site is underlain by former MGP facilities, including gas holders, piping and drip pots. Investigation has not revealed any areas of discrete coal tar deposits, however, the volunteer has proposed to open all encountered pipes and drip pots, drain them and permanently closed them in place or remove them if they interfere with future construction activities.

RAVENSWOOD POWER STATION (Continued) **S102239646**

The area of petroleum contamination will be excavated and removed. The volunteer submitted and the Department approved a Remedial Action Work Plan for the site which consisted of the above remedies. This RAWP has been implemented, and the volunteer has submitted the Remedial Action Summary Report, which is under review by NYSDEC and NYSDOH.

Health Problem: Human exposures to contaminated soil and groundwater are unlikely. Most of the contaminated soil has been removed, the site is fenced and secured, and the site will be covered with buildings and pavement. Exposure to groundwater is unlikely since the area is served by a public water supply.

SPDES:

Permit Number:	NY0005193
State-Region:	02
Expiration Date:	10/31/2017
Current Major Minor Status:	Major
Primary Facility SIC Code:	4911
State Water Body Name:	EAST R
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	999.900000
Total App Design Flow(MGD):	Not reported
UDF1:	DMR
Lat/Long:	40.759667 / -73.946056
DMR Cognizant Official:	KEN YAGER
UDF2:	001702
UDF3:	I
FIPS County Code:	NY081

Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	TC RAVENSWOOD, LLC
Non-Gov Permit Street Address:	RAVENSWOOD GENERATING STATION
Non-Gov Permit Supplemental Location:	38-54 VERNON BLVD
Non-Gov Permit City:	LONG ISLAND CITY
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11101
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	TC RAVENSWOOD, LLC
Non-Gov Facility Street Address:	RAVENSWOOD GENERATING STATION
Non-Gov Facility Supplemental Location:	38-54 VERNON BLVD
Non-Gov Facility City:	LONG ISLAND CITY
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11101
State Water Body:	02030201020

UDF2:	001702
UDF3:	I
FIPS County Code:	NY081

Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	TC RAVENSWOOD, LLC
Non-Gov Permit Street Address:	RAVENSWOOD GENERATING STATION
Non-Gov Permit Supplemental Location:	38-54 VERNON BLVD
Non-Gov Permit City:	LONG ISLAND CITY
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11101

RAVENSWOOD POWER STATION (Continued) **S102239646**

Non-Gov Facility Affiliation Type Desc: Owner
Non-Gov Facility Org Formal Name: TC RAVENSWOOD, LLC
Non-Gov Facility Street Address: RAVENSWOOD GENERATING STATION
Non-Gov Facility Supplemental Location: 110 TURNPIKE RD, SUITE 203
Non-Gov Facility City: WESTBOROUGH
Non-Gov Facility State Code: MA
Non-Gov Facility Zip Code: 01581
State Water Body: 02030201020

UDF2: 001702
UDF3: I
FIPS County Code: NY081

Non-Gov Permit Affiliation Type Desc: Permittee
Non-Gov Permit Org Formal Name: TC RAVENSWOOD, LLC
Non-Gov Permit Street Address: 110 TURNPIKE RD, SUITE 203
Non-Gov Permit Supplemental Location: Not reported
Non-Gov Permit City: WESTBOROUGH
Non-Gov Permit State Code: MA
Non-Gov Permit Zip Code: 01581
Non-Gov Facility Affiliation Type Desc: Mailing Address
Non-Gov Facility Org Formal Name: TC RAVENSWOOD, LLC
Non-Gov Facility Street Address: RAVENSWOOD GENERATING STATION
Non-Gov Facility Supplemental Location: 38-54 VERNON BLVD
Non-Gov Facility City: LONG ISLAND CITY
Non-Gov Facility State Code: NY
Non-Gov Facility Zip Code: 11101
State Water Body: 02030201020

UDF2: 001702
UDF3: I
FIPS County Code: NY081

Non-Gov Permit Affiliation Type Desc: Permittee
Non-Gov Permit Org Formal Name: TC RAVENSWOOD, LLC
Non-Gov Permit Street Address: 110 TURNPIKE RD, SUITE 203
Non-Gov Permit Supplemental Location: Not reported
Non-Gov Permit City: WESTBOROUGH
Non-Gov Permit State Code: MA
Non-Gov Permit Zip Code: 01581
Non-Gov Facility Affiliation Type Desc: Owner
Non-Gov Facility Org Formal Name: TC RAVENSWOOD, LLC
Non-Gov Facility Street Address: RAVENSWOOD GENERATING STATION
Non-Gov Facility Supplemental Location: 110 TURNPIKE RD, SUITE 203
Non-Gov Facility City: WESTBOROUGH
Non-Gov Facility State Code: MA
Non-Gov Facility Zip Code: 01581
State Water Body: 02030201020

MOSF:
Facility ID: 2-1960
Program Type: MOSF
Tank Status: Active
Expiration Date: 2014/03/31
Dec Region: 2
UTMX: 589041.39688000
UTMY: 4512702.2995199

RAVENSWOOD POWER STATION (Continued) **S102239646**

Facility ID: 2-1980
Program Type: MOSF
Tank Status: No Longer MOSF
Expiration Date: N/A
Dec Region: 2
UTMX: 588348.02693000
UTMY: 4510881.1985099

CBS:
CBS Number: 2-000063
Program Type: CBS
Facility Status: Active
Expiration Date: 2014/06/28
Dec Region: 2
UTMX: 588961
UTMY: 4512613

CBS Number: 2-000366
Program Type: CBS
Facility Status: Unregulated
Expiration Date: N/A
Dec Region: 2
UTMX: 588938.75384000
UTMY: 4512559.8492299

AS241 **CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE** **CORRACTS** **1000111639**
North **3854 VERNON BLVD NW CORNER** **RCRA-LQG** **NYD003917960**
1/2-1 **LONG ISLAND CITY, NY 11101** **NY MANIFEST**
0.857 mi. **NJ MANIFEST**
4523 ft. **Site 2 of 2 in cluster AS**

Relative: Lower

Actual: 12 ft.

CORRACTS:

EPA ID: NYD003917960
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 19941201
Action: CA070NO - RFA Determination Of Need For An RFI, RFI is Not Necessary
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD003917960
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 19941201
Action: CA050 - RFA Completed
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

RCRA-LQG:
Date form received by agency: 03/12/2007
Facility name: CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Facility address: 3854 VERNON BLVD NW CORNER
LONG ISLAND CITY, NY 11101

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

EPA ID: NYD003917960
Mailing address: VERNON BLVD NW CORNER
LONG ISLAND CITY, NY 11101
Contact: WARREN MILLER
Contact address: VERNON BLVD NW CORNER
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: (978) 578-9757
Contact email: MILLERW@CONED.COM
EPA Region: 02
Land type: Private
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 04/02/1957
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 04/02/1957
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 03/11/2007
Facility name: CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Classification: Large Quantity Generator

Date form received by agency: 03/11/2007
Facility name: CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Classification: Large Quantity Generator

Date form received by agency: 02/21/2006
Facility name: CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Site name: CON EDISON - RAVENSWOOD SITE
Classification: Large Quantity Generator

Date form received by agency: 02/25/2004
Facility name: CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Site name: CON EDISON - RAVENSWOOD SITE
Classification: Large Quantity Generator

Date form received by agency: 05/31/2002
Facility name: CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Site name: CON EDISION - RAVENSWOOD SITE
Classification: Large Quantity Generator

Date form received by agency: 01/01/2001
Facility name: CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Site name: RAVENSWOOD GENERATING STATION
Classification: Large Quantity Generator

Date form received by agency: 02/26/1998
Facility name: CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Site name: CON ED - REVENSWOOD GENERATING STATION
Classification: Large Quantity Generator

Date form received by agency: 03/29/1996
Facility name: CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Site name: CON EDISON-RAVENSWOOD GENERATING STATION
Classification: Large Quantity Generator

Date form received by agency: 03/28/1994
Facility name: CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Site name: CON EDISON - RAVENSWOOD GENERATING STA
Classification: Large Quantity Generator

Date form received by agency: 03/15/1993
Facility name: CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Site name: CON EDISON - RAVENSWOOD GENERATING STA
Classification: Large Quantity Generator

Date form received by agency: 02/28/1992

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Facility name: CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Site name: CON ED - RAVENSWOOD STATION
Classification: Large Quantity Generator

Date form received by agency: 09/23/1991
Facility name: CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Site name: CON EDISON - RAVENSWOOD GENERATING STA
Classification: Large Quantity Generator

Date form received by agency: 03/01/1990
Facility name: CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Site name: CONSOLIDATED EDISON COMPANY OF NEW YORK
Classification: Large Quantity Generator

Date form received by agency: 08/18/1980
Facility name: CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Site name: CON EDISON - RAVENSWOOD GENERATING STA
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: D006
Waste name: CADMIUM

Waste code: D007
Waste name: CHROMIUM

Waste code: D008
Waste name: LEAD

Waste code: B002
Waste name: B002

Waste code: B007
Waste name: B007

Corrective Action Summary:
Event date: 12/01/1994
Event: RFA Determination Of Need For An RFI, RFI is Not Necessary;

Event date: 12/01/1994
Event: RFA Completed

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 08/30/1994
Date achieved compliance: 10/23/1997
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 10/23/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 09/29/1993
Date achieved compliance: 11/08/1993
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/29/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 05/08/1991
Date achieved compliance: 10/15/1991
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/08/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 01/31/1990
Date achieved compliance: 05/17/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/09/1990
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/14/1988
Date achieved compliance: 06/21/1988
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/12/1988
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Area of violation: LDR - General
Date violation determined: 03/14/1988
Date achieved compliance: 06/21/1988
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/12/1988
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 01/18/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 08/30/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 10/23/1997
Evaluation lead agency: State

Evaluation date: 08/24/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 11/08/1993
Evaluation lead agency: State

Evaluation date: 03/12/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 10/15/1991
Evaluation lead agency: State

Evaluation date: 01/31/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/17/1990
Evaluation lead agency: State

Evaluation date: 03/14/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 06/21/1988
Evaluation lead agency: State

Evaluation date: 03/14/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 06/21/1988
Evaluation lead agency: State

Evaluation date: 04/22/1987

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/13/1986
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

NY MANIFEST:
EPA ID: NYD003917960
Country: USA
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-460-2808

Document ID: NYA1249506
Manifest Status: Completed copy
Trans1 State ID: 2A-100
Trans2 State ID: Not reported
Generator Ship Date: 841029
Trans1 Recv Date: 841029
Trans2 Recv Date: Not reported
TSD Site Recv Date: 841029
Part A Recv Date: 841108
Part B Recv Date: 841116
Generator EPA ID: NYD003917960
Trans1 EPA ID: NYD066969700
Trans2 EPA ID: Not reported
TSDF ID: NYT370010878
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00200
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 84

Document ID: NYO2703429
Manifest Status: Completed copy
Trans1 State ID: IL-001
Trans2 State ID: Not reported
Generator Ship Date: 840814
Trans1 Recv Date: 840814
Trans2 Recv Date: Not reported
TSD Site Recv Date: 840815

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Part A Recv Date:	840817
Part B Recv Date:	840828
Generator EPA ID:	NYD003917960
Trans1 EPA ID:	ILD069506160
Trans2 EPA ID:	Not reported
TSDF ID:	ILD000672121
Waste Code:	B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity:	38240
Units:	P - Pounds
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	84

Document ID:	NYO2703438
Manifest Status:	Completed copy
Trans1 State ID:	IL-001
Trans2 State ID:	Not reported
Generator Ship Date:	840815
Trans1 Recv Date:	840815
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	840816
Part A Recv Date:	840820
Part B Recv Date:	840828
Generator EPA ID:	NYD003917960
Trans1 EPA ID:	ILD069506160
Trans2 EPA ID:	Not reported
TSDF ID:	ILD000672121
Waste Code:	B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity:	36640
Units:	P - Pounds
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	84

Document ID:	NYO2703501
Manifest Status:	Completed copy
Trans1 State ID:	IL-001
Trans2 State ID:	Not reported
Generator Ship Date:	840820
Trans1 Recv Date:	840820
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	000000
Part A Recv Date:	840823
Part B Recv Date:	840828
Generator EPA ID:	NYD003917960
Trans1 EPA ID:	ILD069506160
Trans2 EPA ID:	Not reported
TSDF ID:	ILD000672121
Waste Code:	B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity:	31140
Units:	P - Pounds

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 84

Document ID: NYO2703519
Manifest Status: Completed copy
Trans1 State ID: IL-001
Trans2 State ID: Not reported
Generator Ship Date: 840820
Trans1 Recv Date: 840820
Trans2 Recv Date: Not reported
TSD Site Recv Date: 840821
Part A Recv Date: 840823
Part B Recv Date: 840828
Generator EPA ID: NYD003917960
Trans1 EPA ID: ILD069506160
Trans2 EPA ID: Not reported
TSDF ID: ILD000672121
Waste Code: B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity: 30240
Units: P - Pounds
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 84

Document ID: NYO3089151
Manifest Status: Completed copy
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 840619
Trans1 Recv Date: 840619
Trans2 Recv Date: Not reported
TSD Site Recv Date: 840620
Part A Recv Date: 840626
Part B Recv Date: 840625
Generator EPA ID: NYD003917960
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID: NY7890008975
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00500
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 84

Document ID: NYA2458026
Manifest Status: Completed copy

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Trans1 State ID:	2A-100
Trans2 State ID:	Not reported
Generator Ship Date:	850606
Trans1 Recv Date:	850606
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	850606
Part A Recv Date:	850614
Part B Recv Date:	850614
Generator EPA ID:	NYD003917960
Trans1 EPA ID:	NYD066969700
Trans2 EPA ID:	Not reported
TSDF ID:	NYT370010878
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	03970
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	85

Document ID:	NYA3408355
Manifest Status:	Completed copy
Trans1 State ID:	BARGE
Trans2 State ID:	Not reported
Generator Ship Date:	860428
Trans1 Recv Date:	860428
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	860428
Part A Recv Date:	860501
Part B Recv Date:	860507
Generator EPA ID:	NYD003917960
Trans1 EPA ID:	NYD980593636
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980593636
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	03322
Units:	T - Tons
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	86

Document ID:	NYA3820342
Manifest Status:	Completed copy
Trans1 State ID:	BARGE
Trans2 State ID:	Not reported
Generator Ship Date:	870430
Trans1 Recv Date:	870430
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870506
Part A Recv Date:	870505
Part B Recv Date:	870521
Generator EPA ID:	NYD003917960

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Trans1 EPA ID: NYD980593636
Trans2 EPA ID: Not reported
TSDF ID: NYD980593636
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00016
Units: T - Tons
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 87

Document ID: NYA3820432
Manifest Status: Completed copy
Trans1 State ID: 22174GU
Trans2 State ID: Not reported
Generator Ship Date: 870420
Trans1 Recv Date: 870420
Trans2 Recv Date: Not reported
TSD Site Recv Date: 870420
Part A Recv Date: 870427
Part B Recv Date: 870429
Generator EPA ID: NYD003917960
Trans1 EPA ID: ILD000805911
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00240
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 87

Document ID: NYA5616297
Manifest Status: Completed copy
Trans1 State ID: 22174GW
Trans2 State ID: Not reported
Generator Ship Date: 870810
Trans1 Recv Date: 870810
Trans2 Recv Date: Not reported
TSD Site Recv Date: 870810
Part A Recv Date: 870817
Part B Recv Date: 870818
Generator EPA ID: NYD003917960
Trans1 EPA ID: ILD000805911
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00240
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Specific Gravity: 100
Year: 87

Document ID: NYA6465546
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 870205
Trans1 Recv Date: 870205
Trans2 Recv Date: Not reported
TSD Site Recv Date: 870205
Part A Recv Date: 870331
Part B Recv Date: 870219
Generator EPA ID: NYD003917960
Trans1 EPA ID: ILD000805911
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00240
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 87

Document ID: NYA5616288
Manifest Status: Completed copy
Trans1 State ID: 22174GU
Trans2 State ID: Not reported
Generator Ship Date: 870908
Trans1 Recv Date: 870908
Trans2 Recv Date: Not reported
TSD Site Recv Date: 870908
Part A Recv Date: 870923
Part B Recv Date: 870915
Generator EPA ID: NYD003917960
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00240
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 87

Document ID: NYA5559894
Manifest Status: Completed copy
Trans1 State ID: 22174GV
Trans2 State ID: Not reported
Generator Ship Date: 880128

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Trans1 Recv Date:	880128
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880128
Part A Recv Date:	880208
Part B Recv Date:	880203
Generator EPA ID:	NYD003917960
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00240
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	88

Document ID:	NYA3820410
Manifest Status:	Completed copy
Trans1 State ID:	XG977C(NJ
Trans2 State ID:	Not reported
Generator Ship Date:	880831
Trans1 Recv Date:	880831
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880831
Part A Recv Date:	880913
Part B Recv Date:	880909
Generator EPA ID:	NYD003917960
Trans1 EPA ID:	NJD000603563
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980593636
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	01000
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	88

Document ID:	NYA9648404
Manifest Status:	Completed copy
Trans1 State ID:	AP6277NY
Trans2 State ID:	Not reported
Generator Ship Date:	891016
Trans1 Recv Date:	891016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	891016
Part A Recv Date:	891020
Part B Recv Date:	891020
Generator EPA ID:	NYD003917960
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00258
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	89

Document ID:	NYC0021453
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	891229
Trans1 Recv Date:	891229
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	891229
Part A Recv Date:	900109
Part B Recv Date:	900105
Generator EPA ID:	NYD003917960
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00258
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	89

Document ID:	NYA9798772
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	891206
Trans1 Recv Date:	891206
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	891206
Part A Recv Date:	891213
Part B Recv Date:	891218
Generator EPA ID:	NYD003917960
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00258
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	89

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Document ID:	NYC0121779
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	900220
Trans1 Recv Date:	900220
Trans2 Recv Date:	900220
TSD Site Recv Date:	900220
Part A Recv Date:	900312
Part B Recv Date:	900306
Generator EPA ID:	NYD003917960
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00258
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	90

Document ID:	NYC0270922
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	7636
Generator Ship Date:	900518
Trans1 Recv Date:	900518
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900518
Part A Recv Date:	900709
Part B Recv Date:	900716
Generator EPA ID:	NYD003917960
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00258
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	90

Click this hyperlink while viewing on your computer to access
625 additional NY_MANIFEST: record(s) in the EDR Site Report.

NJ MANIFEST:

Manifest Code:	NJA5009586
EPA ID:	NYD003917960
Date Shipped:	05/12/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/12/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/20/2005
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	Not reported
Transporter-1 EPA Facility Name:	Not reported
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06220522
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5212626
EPA ID:	NYD003917960
Date Shipped:	07/12/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/12/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/12/2005
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	Not reported
Transporter-1 EPA Facility Name:	Not reported
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08250521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5212628
EPA ID:	NYD003917960
Date Shipped:	07/13/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD063147797
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/13/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/14/2005
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	Not reported
Transporter-1 EPA Facility Name:	Not reported
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08240521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5212627
EPA ID:	NYD003917960
Date Shipped:	07/14/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD063147797
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/14/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/14/2005
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	Not reported
Transporter-1 EPA Facility Name:	Not reported
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08240521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5212778
EPA ID:	NYD003917960
Date Shipped:	07/14/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD063147797
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/14/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/14/2005
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	Not reported
Transporter-1 EPA Facility Name:	Not reported
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08240521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5212623
EPA ID:	NYD003917960
Date Shipped:	07/15/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD063147797
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/15/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/15/2005
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	Not reported
Transporter-1 EPA Facility Name:	Not reported
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08240521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5212625
EPA ID:	NYD003917960
Date Shipped:	07/15/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD063147797
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/15/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/15/2005
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	Not reported
Transporter-1 EPA Facility Name:	Not reported
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08240521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5212777
EPA ID:	NYD003917960
Date Shipped:	07/15/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD063147797
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Date Trans1 Transported Waste:	07/15/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/15/2005
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	Not reported
Transporter-1 EPA Facility Name:	Not reported
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08240521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5212624
EPA ID:	NYD003917960
Date Shipped:	07/18/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/18/2005

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/20/2005
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	Not reported
Transporter-1 EPA Facility Name:	Not reported
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08290521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5067385
EPA ID:	NYD003917960
Date Shipped:	11/04/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/04/2004
Date Trans2 Transported Waste:	Not reported

CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE (Continued) **1000111639**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/04/2004
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	Not reported
Transporter-1 EPA Facility Name:	Not reported
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	12280421
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

AT242 **STANDARD MOTOR PRODUCTS INC** **RCRA-SQG** **1000310304**
ENE **37-18 NORTHERN BLVD SITE 1** **NY SHWS** **NYD001315266**
1/2-1 **LONG ISLAND CITY, NY 11101** **NY LTANKS**
0.898 mi. **NY MANIFEST**
4741 ft. **Site 1 of 2 in cluster AT** **PA MANIFEST**
NY Spills
Relative: **NY VCP**
Higher **NY CBS**

Actual: **24 ft.**

RCRA-SQG:

Date form received by agency:	01/01/2007
Facility name:	STANDARD MOTOR PRODUCTS INC
Facility address:	37-18 NORTHERN BLVD SITE 1 LONG ISLAND CITY, NY 11101
EPA ID:	NYD001315266
Mailing address:	NORTHERN BLVD LONG ISLAND CITY, NY 11101

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Contact:	MURRAY ROSE
Contact address:	NORTHERN BLVD LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	(718) 392-0200
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	STANDARD MOTOR PRODUCTS
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	STANDARD MOTOR PRODUCTS
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Facility name:	STANDARD MOTOR PRODUCTS INC

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Classification: Small Quantity Generator

Date form received by agency: 03/30/1998
Facility name: STANDARD MOTOR PRODUCTS INC
Classification: Large Quantity Generator

Date form received by agency: 03/19/1996
Facility name: STANDARD MOTOR PRODUCTS INC
Classification: Large Quantity Generator

Date form received by agency: 02/23/1994
Facility name: STANDARD MOTOR PRODUCTS INC
Classification: Large Quantity Generator

Date form received by agency: 02/06/1992
Facility name: STANDARD MOTOR PRODUCTS INC
Site name: STANDARD MOTOR PRODUCTS
Classification: Large Quantity Generator

Date form received by agency: 03/01/1990
Facility name: STANDARD MOTOR PRODUCTS INC
Site name: STANDARD MOTOR PRODUCTS
Classification: Large Quantity Generator

Date form received by agency: 07/12/1984
Facility name: STANDARD MOTOR PRODUCTS INC
Classification: Large Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 04/06/2007
Date achieved compliance: 06/30/2008
Violation lead agency: EPA
Enforcement action: VERBAL INFORMAL
Enforcement action date: 04/12/2007
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 6nycrr372.2(a)(8)
Area of violation: Generators - General
Date violation determined: 05/14/1999
Date achieved compliance: 05/28/1999
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/14/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 04/13/1994
Date achieved compliance: 06/01/1994
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/13/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 09/26/1988
Date achieved compliance: 12/23/1988
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/20/1988
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 01/27/1987
Date achieved compliance: 12/28/1988
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 03/20/2013
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 04/06/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 06/30/2008
Evaluation lead agency: EPA

Evaluation date: 08/19/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/06/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/28/1999
Evaluation lead agency: EPA

Evaluation date: 10/16/1995
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/28/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 06/01/1994
Evaluation lead agency: State

Evaluation date: 09/26/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 12/23/1988
Evaluation lead agency: State

Evaluation date: 01/27/1987
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - General
Date achieved compliance: 12/28/1988
Evaluation lead agency: State

SHWS:
Program: HW
Site Code: 58682
Classification: SIGNIFICANT THREAT TO THE PUBLIC HEALTH OR ENVIRONMENT - ACTION REQUIRED.
Region: 2
Acres: 1.100
HW Code: 241016
Record Add: 11/18/1999
Record Upd: 05/28/2013
Updated By: JHOCONNE
Site Description: Location:The site is located at 37-18 Northern Boulevard, Long Island City, Queens County, New York in the northwestern section of the county. Bordering the Site is Northern Boulevard to the north; Amtraks Sunnyside Railroad Yard (Sunnyside Yard) to the south; 39th Street, an automobile dealership, and a Hess (formerly Merit) gasoline station to the east; and commercial and industrial properties to the west. Site Features:The Site is approximately rectangular in shape and occupies approximately one acre of land. The Site contains a six-story industrial building with approximately 42,000 square feet per floor. A narrow strip of land on the south side of the property contains a loading dock and a dirt access path for vehicles. This strip of land is owned by the Metropolitan Transportation Authority (MTA) and is part of a long-term lease to

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Standard Motor Products. Current Zoning/Use(s):The site is being used for commercial office space. There is a commercial vegetable farm occupying part of the buildings roof. Historical Use(s): The Site has historically been involved in industrial and manufacturing activities since 1919. A small plating line for chrome plating of small machine parts operated from approximately 1975 to 1984. The site was previously used for painting automobile parts prior to distribution. In 1984, aqueous based paints replaced the previously used solvent-based paints. All painting operations were gradually eliminated between 1990 and 1991. The site also housed several other processes and included die-casting operations that ceased in the 1970s; rubber production that was eliminated around 1985; and degreasing which utilized chlorinated solvents that ended in 1990.Until March 2008, automobile parts and components at the site were primarily manufactured in the basement within recent years. The manufacturing operations included metal fabrication and machining, plastic injection molding, and assembly. A small photography laboratory for production of newsletters, brochures also operated. Hazardous or toxic materials involved in plant operations are lubricating oils for machinery, caustics for degreasing, phenolics used in molding processes, epoxies for coil production, and water-based inks involved in their small-scale printing. All wastes were temporarily stored on-site in secure containers prior to off-site disposal at a licensed treatment, storage, and disposal (TSD) facility.The Record of Decision was issued on March 23, 2009, and the Remedial Design/Remedial Action Order on Consent was signed in April 2010.Site Geology and Hydrogeology:The Site is underlain by the following units (in order by increasing depth): urban fill, Upper Pleistocene glacial deposits (including both till and channel deposits), and bedrock. The fill is predominantly comprised of reworked glacial deposits (sand, silt, clay, and gravel) and railroad ballast with minor amounts of construction debris and other materials. The Upper Pleistocene glacial deposits consist mainly of ground moraine deposits (unstratified, poorly sorted mixture of sand, silt, clay, and gravel). Bedrock was encountered at a depth of 74 feet below land surface (i.e. 53 feet below mean sea level).The groundwater beneath the Site occurs under water table (unconfined) conditions. The depth to groundwater in the vicinity of the Site is approximately 5 feet below ground surface (bgs) but may be influenced by surface runoff that results in standing water across most of the Site during rain events. The water table occurs in either fill or glacial deposits. Groundwater elevation data show that flow is primarily from east to west beneath the Site. Due to the proximity to the East River, the hydraulic gradients are gentle which is consistent with the regional groundwater contour map and the groundwater contours present on the adjacent Sunnyside Yard property. Vertical groundwater movement is restricted by the Gardiners Clay where present or by the Precambrian bedrock which is considered to be the bottom hydrogeologic boundary of the groundwater flow system. The groundwater flow rate was estimated to be 0.78 feet/day.

Env Problem: Nature and Extent of Contamination: A site investigation in 1990 was initiated after an oily sheen was observed in a puddled area on the southeast side of the property. Soil samples from this area revealed elevated levels of petroleum hydrocarbons and volatile organic compounds (VOCs), primarily 1,1,1-trichloroethane. Approximately 2,700 sq. ft. of soil was excavated to a depth of 18 inches and stockpiled on-site. Further investigation determined that soils in

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

the area of the rear loading platform contained elevated levels of petroleum hydrocarbons and VOCs (trichloroethane TCA, triclhoroethene - TCE and other related chlorinated VOCs). Contaminated soils extended beyond the area excavated. Subsequent groundwater samples taken indicated contamination with TCA and lead. The highest levels of groundwater contamination are adjacent to the loading dock at the back of the building. Soil - Arsenic was detected at 19 ppm, which is above the applicable soil cleanup objectives (SCOs). Groundwater - Tetrachloroethylene (PCE) has been found at concentrations of up to 17 ppb. Trichloroethylene (TCE) has been found at concentrations of up to 78 ppb. Cis-1,2-Dichloroethene (cis-1,2-DCE) has been found at concentrations of up to 93 ppb. Vinyl chloride (VC) has been found at concentrations of up to 31 ppb. 1,1,1-Trichloroethane 1,1,1-TCA) has been found at concentrations of up to 180 ppb.Soil Vapor- The highest concentrations of chlorinated VOCs were detected at SB-05. Sub-slab samples contained PCE at concentration of up to 620 ug/m3. TCE and cis-1,2-DCE have been found at concentrations of up to 2,800 ug/m3 and up to 52 ug/m3 respectively. Chlorinated ethanes were found and included 1,1,1-TCA and 1,1-DCA at concentrations up to 5,200 ug/m3 and up to 450 ug/m3 respectively.Significant Threat: The site presents a significant environmental threat. An Interim Remedial Measure (IRM) consisting of a sub-slab depressurization system (SSDS) has been installed in the building and is currently in operation.

Health Problem: The on-site structure will have an active sub-slab depressurization system which will prevent contamination from entering the building via soil vapor intrusion. A air sparge/soil vapor extraction system will address contaminants present in the groundwater. Exposure to site-related contaminants in drinking water are not expected because public water serves the area.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: unknown
Disp Term: unknown
Lat/Long: 40:45:07:0 / 73:55:31:0
Dell: False
Record Add: 11/18/1999 12:00:00 PM
Record Upd: 2/29/2008 11:07:00 AM
Updated By: SMMARTIN
Own Op: Document Repository
Sub Type: NNN
Owner Name: Roz Rubinstein
Owner Company: Queens Public Library Broadway Branch
Owner Address: 40-20 Broadway
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11103
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Gordon Johnson
Owner Company: Metropolitan Transporation Auth.
Owner Address: 347 Madion Aeve.
Owner Addr2: 9th Floor
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Own Op:	Owner
Sub Type:	E
Owner Name:	Jeff Rosenblum, Acumen Capital Partners, LLC
Owner Company:	37-18 Northern Blvd., LLC
Owner Address:	37-18 Northern Boulevard
Owner Addr2:	Suite 300
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
HW Code:	241016
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241016
Waste Type:	ETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241016
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241016
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241016
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241016
Waste Type:	1,1,1 TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241016
Waste Type:	1,1-DICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241016
Waste Type:	METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241016
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2-477869
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	1/4/2007 3:05:00 PM
Record Updated:	1/4/2007 3:05:00 PM
Updated By:	SMMARTIN
Crossref ID:	NYD001315266
Cross Ref Type Code:	05
Cross Ref Type:	EPA Site ID
Record Added Date:	11/18/1999 12:00:00 PM
Record Updated:	5/10/2001 4:31:00 PM
Updated By:	REGTRANS

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

LTANKS:

Site ID:	153383
Spill Number/Closed Date:	9509528 / 3/23/2004
Spill Date:	11/1/1995
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	4101
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	11/1/1995
CID:	357
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	11/1/1995
Spill Record Last Update:	3/23/2004
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	NN
Spiller County:	999
Spiller Contact:	AVIS REDMAN
Spiller Phone:	(718) 392-0200
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	130150
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MARTINKAT"02/18/04: Reassigned from KRIMGOLD to Martinkat.
Remarks:	OIL IN TANK ROOM

Material:

Site ID:	153383
Operable Unit ID:	1020065
Operable Unit:	01
Material ID:	360474
Material Code:	0002A
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

NY MANIFEST:

EPA ID:	NYD001315266
Country:	USA
Mailing Name:	STANDARD MOTOR PRODUCTS
Mailing Contact:	STANDARD MOTOR PRODUCTS
Mailing Address:	37-18 NORTHERN BLVD
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-392-0200

Document ID:	NYA3088372
Manifest Status:	Completed copy
Trans1 State ID:	18946GL
Trans2 State ID:	Not reported
Generator Ship Date:	860415
Trans1 Recv Date:	860415
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	860415
Part A Recv Date:	860423
Part B Recv Date:	860421
Generator EPA ID:	NYD001315266
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	F003 - UNKNOWN
Quantity:	00770
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	014
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	86

Document ID:	NYA3823266
Manifest Status:	Completed copy
Trans1 State ID:	18946-GL/
Trans2 State ID:	Not reported
Generator Ship Date:	870120
Trans1 Recv Date:	870120
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870120
Part A Recv Date:	870130
Part B Recv Date:	870130
Generator EPA ID:	NYD001315266
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	F001 - UNKNOWN
Quantity:	01100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	020

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00020
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00020
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	87

Document ID:	NYA6352317
Manifest Status:	Completed copy
Trans1 State ID:	97763GT
Trans2 State ID:	Not reported
Generator Ship Date:	880317
Trans1 Recv Date:	880317
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880317
Part A Recv Date:	880329
Part B Recv Date:	880321
Generator EPA ID:	NYD001315266
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	F001 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00600
Units:	P - Pounds
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	88

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Document ID:	NYA6352065
Manifest Status:	Completed copy
Trans1 State ID:	97763GT
Trans2 State ID:	Not reported
Generator Ship Date:	880224
Trans1 Recv Date:	880224
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880224
Part A Recv Date:	880229
Part B Recv Date:	880308
Generator EPA ID:	NYD001315266
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	F003 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00011
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	88

Document ID:	NYA7756155
Manifest Status:	Completed copy
Trans1 State ID:	NL6934
Trans2 State ID:	Not reported
Generator Ship Date:	891003
Trans1 Recv Date:	891003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	891003
Part A Recv Date:	891012
Part B Recv Date:	891013
Generator EPA ID:	NYD001315266
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 01320
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 024
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 89

Document ID: NYB2205090
Manifest Status: Completed copy
Trans1 State ID: MM5929
Trans2 State ID: Not reported
Generator Ship Date: 891219
Trans1 Recv Date: 891219
Trans2 Recv Date: Not reported
TSD Site Recv Date: 891219
Part A Recv Date: 891228
Part B Recv Date: 891229
Generator EPA ID: NYD001315266
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: D007 - CHROMIUM 5.0 MG/L TCLP
Quantity: 00880
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 016
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 89

Document ID: NYC0303658
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 900605
Trans1 Recv Date: 900605
Trans2 Recv Date: Not reported
TSD Site Recv Date: 900605
Part A Recv Date: 900730
Part B Recv Date: 900611
Generator EPA ID: NYD001315266
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00045
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	90

Document ID:	NYC0044133
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	900202
Trans1 Recv Date:	900202
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900202
Part A Recv Date:	900214
Part B Recv Date:	900214
Generator EPA ID:	NYD001315266
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00045
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	90

Document ID:	NYB2460393
Manifest Status:	Completed copy
Trans1 State ID:	23561B
Trans2 State ID:	Not reported
Generator Ship Date:	910129
Trans1 Recv Date:	910129
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910130
Part A Recv Date:	910206
Part B Recv Date:	910219
Generator EPA ID:	NYD001315266
Trans1 EPA ID:	NYD000691949
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000691949
Waste Code:	F001 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00110
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	91

Document ID:	NYC0686362
Manifest Status:	Completed copy
Trans1 State ID:	GF4780
Trans2 State ID:	Not reported
Generator Ship Date:	910122
Trans1 Recv Date:	910122
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910122
Part A Recv Date:	910211
Part B Recv Date:	910204
Generator EPA ID:	NYD001315266
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00045
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	91

Document ID:	NYC1168479
Manifest Status:	Completed copy
Trans1 State ID:	GF4780
Trans2 State ID:	Not reported
Generator Ship Date:	910826
Trans1 Recv Date:	910826
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910826
Part A Recv Date:	910906
Part B Recv Date:	910910
Generator EPA ID:	NYD001315266

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00045
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	91

Document ID:	NYB2460375
Manifest Status:	Completed copy
Trans1 State ID:	23561B
Trans2 State ID:	Not reported
Generator Ship Date:	910129
Trans1 Recv Date:	910129
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910130
Part A Recv Date:	910206
Part B Recv Date:	910219
Generator EPA ID:	NYD001315266
Trans1 EPA ID:	NYD000691949
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000691949
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00275
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	01815
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	033
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00660
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	012
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	91

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Document ID:	NYB2460411
Manifest Status:	Completed copy
Trans1 State ID:	23561B
Trans2 State ID:	Not reported
Generator Ship Date:	910129
Trans1 Recv Date:	910129
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910130
Part A Recv Date:	910206
Part B Recv Date:	910219
Generator EPA ID:	NYD001315266
Trans1 EPA ID:	NYD000691949
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000691949
Waste Code:	F003 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	91

Document ID:	NJA1015502
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS103
Trans2 State ID:	NJDEPS103
Generator Ship Date:	910129
Trans1 Recv Date:	910129
Trans2 Recv Date:	910131
TSD Site Recv Date:	910131
Part A Recv Date:	910206
Part B Recv Date:	910220
Generator EPA ID:	NYD001315266
Trans1 EPA ID:	NYD000691949

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Trans2 EPA ID: NYD000691949
TSDF ID: NJD002454544
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00660
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 012
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 91

Document ID: NYB2222928
Manifest Status: Completed copy
Trans1 State ID: NY23561B
Trans2 State ID: Not reported
Generator Ship Date: 910604
Trans1 Recv Date: 910604
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910604
Part A Recv Date: 910614
Part B Recv Date: 910620
Generator EPA ID: NYD001315266
Trans1 EPA ID: NYD000691949
Trans2 EPA ID: Not reported
TSDF ID: NYD000691949
Waste Code: F001 - UNKNOWN
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 91

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Document ID:	NYC1059693
Manifest Status:	Completed copy
Trans1 State ID:	7766
Trans2 State ID:	Not reported
Generator Ship Date:	910706
Trans1 Recv Date:	910706
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910706
Part A Recv Date:	910719
Part B Recv Date:	910715
Generator EPA ID:	NYD001315266
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00045
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	91

Document ID:	NYC1288912
Manifest Status:	Completed copy
Trans1 State ID:	GF4780
Trans2 State ID:	Not reported
Generator Ship Date:	911016
Trans1 Recv Date:	911016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	911016
Part A Recv Date:	911101
Part B Recv Date:	911104
Generator EPA ID:	NYD001315266
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00045
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	91

Document ID:	NYB1581084
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NY23561B
Trans2 State ID:	Not reported
Generator Ship Date:	910716
Trans1 Recv Date:	910716
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910723
Part A Recv Date:	910726

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Part B Recv Date:	910815
Generator EPA ID:	NYD001315266
Trans1 EPA ID:	NYD000691949
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000691949
Waste Code:	F001 - UNKNOWN
Quantity:	00275
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	03200
Units:	P - Pounds
Number of Containers:	008
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	01320
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	024
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	91

Document ID:	NYB1581102
Manifest Status:	Completed copy
Trans1 State ID:	NY23561B
Trans2 State ID:	Not reported
Generator Ship Date:	910716
Trans1 Recv Date:	910716
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910723
Part A Recv Date:	910726
Part B Recv Date:	910802
Generator EPA ID:	NYD001315266
Trans1 EPA ID:	NYD000691949
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000691949
Waste Code:	F003 - UNKNOWN
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Waste Code:	Not reported
Quantity:	02800
Units:	P - Pounds
Number of Containers:	007
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00500
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	91

Document ID:	NYB2552580
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	ME25756
Trans2 State ID:	Not reported
Generator Ship Date:	910927
Trans1 Recv Date:	910927
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910930
Part A Recv Date:	911009
Part B Recv Date:	911031
Generator EPA ID:	NYD001315266
Trans1 EPA ID:	NYD000691949
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000691949
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00325
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	065
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 91

Click this hyperlink while viewing on your computer to access
363 additional NY_MANIFEST: record(s) in the EDR Site Report.

PA MANIFEST:
Year: 2010
Manifest Number: 000895430GBF
Manifest Type: T
Generator EPA Id: NYD001315266
Generator Date: 04/07/2010
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: 718-316-4332
TSD Epa Id: PAD067098822
TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 550 INDUSTRIAL DRIVE
TSD Facility City: LEWISBERRY
TSD Facility State: PA
Facility Telephone: Not reported
Page Number: 1
Line Number: 4
Waste Number: D002
Container Number: 1
Container Type: Fiberboard or plastic drums, barrels, kegs
Waste Quantity: 2
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2010
Manifest Number: 000895431GBF
Manifest Type: T
Generator EPA Id: NYD001315266
Generator Date: 04/07/2010
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: 718-316-4332
TSD Epa Id: PAD067098822
TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 550 INDUSTRIAL DRIVE
TSD Facility City: LEWISBERRY
TSD Facility State: PA
Facility Telephone: Not reported
Page Number: 1
Line Number: 1
Waste Number: D009
Container Number: 1
Container Type: Fiberboard or plastic drums, barrels, kegs
Waste Quantity: 10

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2010
Manifest Number:	000895430GBF
Manifest Type:	T
Generator EPA Id:	NYD001315266
Generator Date:	04/07/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	718-316-4332
TSD Epa Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	D002
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	10
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2010
Manifest Number:	000895430GBF
Manifest Type:	T
Generator EPA Id:	NYD001315266
Generator Date:	04/07/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	718-316-4332
TSD Epa Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	200
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Date TSP Sig:	Not reported
Year:	2010
Manifest Number:	000895430GBF
Manifest Type:	T
Generator EPA Id:	NYD001315266
Generator Date:	04/07/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	718-316-4332
TSD Epa Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	80
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2010
Manifest Number:	000895431GBF
Manifest Type:	T
Generator EPA Id:	NYD001315266
Generator Date:	04/07/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	718-316-4332
TSD Epa Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	U151
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	10
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2008

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Manifest Number:	000141753SKS
Manifest Type:	T
Generator EPA Id:	NYD001315266
Generator Date:	06/30/2008
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	718-316-4332
TSD Epa Id:	PAD987367216
TSD Date:	Not reported
TSD Facility Name:	AERC COM INC ADVANCED ENVIRONMENTAL RECYCLING
TSD Facility Address:	2591 MITCHELL AVENUE
TSD Facility City:	ALLENTOWN
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D002
Container Number:	3
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	300
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2008
Manifest Number:	000141753SKS
Manifest Type:	T
Generator EPA Id:	NYD001315266
Generator Date:	06/30/2008
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	718-316-4332
TSD Epa Id:	PAD987367216
TSD Date:	Not reported
TSD Facility Name:	AERC COM INC ADVANCED ENVIRONMENTAL RECYCLING
TSD Facility Address:	2591 MITCHELL AVENUE
TSD Facility City:	ALLENTOWN
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	3
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	300
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2006
Manifest Number:	PAH043327
Manifest Type:	T
Generator EPA Id:	NYD001315266

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Generator Date:	03/20/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD Epa Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	718-316-4332
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	30
Unit:	Gallons (liquids only)
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2006
Manifest Number:	PAH043327
Manifest Type:	T
Generator EPA Id:	NYD001315266
Generator Date:	03/20/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD Epa Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	718-316-4332
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	55
Unit:	Gallons (liquids only)
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2006
Manifest Number:	PAH043327
Manifest Type:	T
Generator EPA Id:	NYD001315266
Generator Date:	03/20/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Contact Name:	Not reported
Contact Phone:	Not reported
TSD Epa Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	718-316-4332
Page Number:	1
Line Number:	4
Waste Number:	D008
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	5
Unit:	Gallons (liquids only)
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2006
Manifest Number:	PAH043327
Manifest Type:	T
Generator EPA Id:	NYD001315266
Generator Date:	03/20/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD Epa Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	718-316-4332
Page Number:	1
Line Number:	3
Waste Number:	D002
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	5
Unit:	Gallons (liquids only)
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

SPILLS:

Facility ID:	9006846
DER Facility ID:	130150
Facility Type:	ER
Site ID:	153382
DEC Region:	2
Spill Date:	9/21/1990
Spill Number/Closed Date:	9006846 / 10/15/1990
Spill Cause:	Human Error
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response.

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Willing Responsible Party. Corrective action taken.
SWIS: 4101
Investigator: FINGER
Referred To: Not reported
Reported to Dept: 9/21/1990
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 9/25/1990
Spill Record Last Update: 9/2/2004
Spiller Name: Not reported
Spiller Company: STANDARD MOTOR PRO
Spiller Address: 37-18 NORTHERN BLVD
Spiller City,St,Zip: LONG ISLAND CITY, NY
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Not reported
Remarks: DRUMS FELL OFF TRUCK, SPILLED ONTO SOIL AREA, SPEEDY DRY WAS APPLIED, WILL PICK UP & REMOVE CONTAMINATED SOIL.

Material:
Site ID: 153382
Operable Unit ID: 947356
Operable Unit: 01
Material ID: 434292
Material Code: 0022
Material Name: Waste Oil/Used Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9900754
DER Facility ID: 130150
Facility Type: ER
Site ID: 153384
DEC Region: 2
Spill Date: 4/20/1999
Spill Number/Closed Date: 9900754 / 6/11/2002
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 4101

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	4/20/1999
CID:	366
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	4/20/1999
Spill Record Last Update:	9/2/2004
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"CON ED E2MIS NOTES 7-08-994-20-99 1100hrs.An undiaperable sheen found on 500 gals of water in Vault #unknown, no secondary or primary cables in structure, contained, no sewers or waterways affected. Sample to be taken.Lab Seq#99-04008 <1ppm 4-20-99 2000hrs.5-01-99 18:00hrs. CLeanup completed & Env. Tag #24760 removed.UPDATE - 5/4/99 - NO LEAKING COMPANY EQUIPMENT. INCIDENT IS CLOSED.
Remarks:	PRODUCT FOUND IN VAULT AND IS CONTAINED ON WATER. SAMPLES TO BE TAKEN AND CLEAN UP TO BEGIN.CON ED #124344.

Material:

Site ID:	153384
Operable Unit ID:	1079518
Operable Unit:	01
Material ID:	307875
Material Code:	0064A
Material Name:	UNKNOWN MATERIAL
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

VCP:

Program Type:	VCP
Site Code:	58683
HW Code:	V00257
Site Class:	N
SWIS:	4101

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Region:	2
Town:	New York City
Acres:	Not reported
Date Record Added:	11/30/2000
Date Record Updated:	10/19/2001
Updated By:	REEVANS
Site Description:	See Registry Site # 241016
Env Problem:	Not reported
Health Problem:	Not reported

CBS:

CBS Number:	2-000153
Program Type:	CBS
Facility Status:	Unregulated
Expiration Date:	N/A
Dec Region:	2
UTMX:	591047.33773000
UTMY:	4511892.8172899

AT243 **STANDARD MOTOR PRODUCTS, INC.** **NY VAPOR REOPENED** **S101008344**
ENE **37-18 NORTHERN BOULEVARD** **NY CBS AST** **N/A**
1/2-1 **LONG ISLAND CITY, NY 11101**
0.898 mi.
4743 ft. **Site 2 of 2 in cluster AT**

Relative:
Higher

Actual:
24 ft.

VAPOR REOPENED:

Site Code:	241016
Facility Status:	Complete

CBS AST:

CBS Number:	2-000153
ICS Number:	2-021443
PBS Number:	Not reported
MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	INACTIVE FACILITY
Facility Type:	Not reported
Telephone:	(718) 392-0200
Facility Town:	NEW YORK CITY
Region:	STATE
Expiration Date:	07/27/1991
Total Capacity of All Active Tanks(gal):	0
Operator:	MURRAY ROSE
Emergency Contact:	CRAIG SWANBURG
Emergency Phone:	(516) 795-7147
Owner Name:	STANDARD MOTOR PRODUCTS, INC.
Owner Address:	37-18 NORTHERN BOULEVARD
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Owner Telephone:	(718) 392-0200
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	STANDARD MOTOR PRODUCTS, INC.
Mail Contact Addr:	37-18 NORTHERN BOULEVARD
Mail Contact Addr2:	Not reported
Mail Contact Contact:	MURRAY L. ROSE
Mail Contact City,St,Zip:	LONG ISLAND CITY, NY 11101
Mail Phone:	(718) 392-0200

STANDARD MOTOR PRODUCTS, INC. (Continued) **S101008344**

Tank Id:	061
CAS Number:	71556
Federal ID:	Not reported
Tank Status:	0
Install Date:	01/77
Tank Closed:	07/91
Capacity (Gal):	1000
Chemical:	1,1,1-Trichloroethane
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Type:	Steel/carbon steel
Total Tanks:	0
Tank Secret:	False
Tank Containment:	None
Tank Error Status:	Major Data Missing (which is on the certificate)
Date Entered:	07/27/1989
Certified Date:	07/27/1989
Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Pipe Containment:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	08/20/91
Is It There:	False
Delinquent:	False
Date Expired:	07/27/91
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	08/20/1991

244
SW
1/2-1
0.944 mi.
4986 ft.

S & G WOODWORKING INC **RCRA-CESQG 1008892201**
1155 MANHATTAN AVE - MAIN FLOO **NY SHWS NYR000135772**
BROOKLYN, NY 11222 **NY MANIFEST**

Relative:
Lower

Actual:
11 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	S & G WOODWORKING INC
Facility address:	1155 MANHATTAN AVE - MAIN FLOO BROOKLYN, NY 11222
EPA ID:	NYR000135772
Mailing address:	MANHATTAN AVE - MAIN FLOOR BROOKLYN, NY 11222
Contact:	MOSHE GRANIT

S & G WOODWORKING INC (Continued) **1008892201**

Contact address: MANHATTAN AVE - MAIN FLOOR
BROOKLYN, NY 11222
Contact country: US
Contact telephone: (718) 389-5602
Telephone ext.: 19
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: NO NAME FOUND
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Other
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1983
Owner/Op end date: Not reported

Owner/operator name: NO NAME FOUND
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Other
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1983
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No

S & G WOODWORKING INC (Continued) **1008892201**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: S & G WOODWORKING INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 12/07/2005
Facility name: S & G WOODWORKING INC
Classification: Small Quantity Generator

Violation Status: No violations found

SHWS:
Program: HW
Site Code: 421914
Classification: N
Region: 2
Acres: 3.865
HW Code: 224138
Record Add: 11/17/2009
Record Upd: 08/26/2011
Updated By: MJKOMORO
Site Description: LOCATION: The Greenpoint Manufacturing and Design Center (GMDC) property is located at 1155-1205 Manhattan Avenue which is an urban area of Brooklyn (Kings County) in New York City. SITE FEATURES: The property is nearly entirely covered by structures, with only one small area covered with other impervious material located along the northern edge of the property along Newtown Creek. There are eight contiguous four to six-story building on the property. The property borders Newtown Creek on the north side. CURRENT ZONING/USE: This property is currently in use for many separate commercial uses, primarily by small businesses and artisans. The surrounding uses are varied - the property adjacent to the west is indicated as having residential and commercial use but appears commercial; the properties to the east across Manhattan Avenue are indicated as being factory/industrial uses, but appear to be commercial with residential above. HISTORICAL USE(s): The property has a long industrial/commercial history, but went through an extensive remedial effort overseen by local agencies in the 1990's. The property owners have done significant renovations on the buildings and have conducted at least two recent investigations which identified limited groundwater contamination, but did not identify any significant soil contamination.
Env Problem: NATURE AND EXTENT OF CONTAMINATION: Only two (of ten) temporary groundwater sampling wells located in the basement of the structure at 1155 Manhattan Avenue showed evidence of contamination. Each contained one chlorinated VOC slightly above standards. Tetrachloroethylene was identified at 21ppb; chloroform was identified at 12 ppb. Groundwater standards are 5 ppb and 7 ppb respectively. Soil samples from these borings were below unrestricted standards for the same compounds. Samples taken from permanent wells did not identify any VOC contamination. Based on professional judgment, the slight exceedances of groundwater standards, adjacent

S & G WOODWORKING INC (Continued) **1008892201**

to the Newtown Creek Superfund Site, do not constitute a significant threat to the environment. No further investigations are warranted at this time. Site designation was changed from "P" to "N."

Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Owner
Sub Type:	01
Owner Name:	Manhattan Avenue Holding Corp.
Owner Company:	Manhattan Avenue Holding Corp.
Owner Address:	1155 Manhattan Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Paul Parkhill
Owner Company:	Greenpoint Manufacturing & Design Center
Owner Address:	1155 Manhattan Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

NY MANIFEST:

EPA ID:	NYR000135772
Country:	USA
Mailing Name:	SG WOODWORKING INC
Mailing Contact:	ZOGALA
Mailing Address:	1155 MANHATTAN AVENUE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11222
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-389-5602

S & G WOODWORKING INC (Continued) **1008892201**

NY MANIFEST:
No Manifest Records Available

---

245 South 1/2-1 0.951 mi. 5020 ft.

Relative: Lower

Actual: 7 ft.

FORMER MANHATTAN ADHESIVES PLANT **NY SHWS** **S105972443**
425-459 GREENPOINT AVENUE **N/A**
BROOKLYN, NY

SHWS:

Program:	HW
Site Code:	58916
Classification:	N
Region:	2
Acres:	Not reported
HW Code:	224009
Record Add:	11/18/1999
Record Upd:	12/16/2003
Updated By:	kstang
Site Description:	The site did not qualify for addition to the Registry of Inactive Hazardous Disposal Sites. Manhattan Adhesives is currently an empty factory building that is located at the foot of the Greenpoint Ave., Bridge in Brooklyn. Besides the Manhattan Adhesives factory, about 10 feet from the northeast wall is a manhole (not a sewer or drain) into which liquid waste was allegedly discharged. This waste came from a condemned oil storage site located at the intersection of Rt. 280, and the NJ Turnpike in NJ. The manhole is suspected of being the opening to an underground tank; however, the quantity of the waste allegedly dumped exceeds the capacity of most tanks. This information was obtained from the State Senate Committee on Crime and the Brooklyn District Attorney's office. Phase I State Superfund has been completed. A partial phase II investigation was completed during 1985 and recommended no further action. The Responsible Party has agreed to undertake an investigation in 1986. An investigation has not found hazardous waste on-site.
Env Problem:	Not reported
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	FRANK CASTIGLIONE
Owner Address:	32-02 COLLEGE POINT BLVD.
Owner Addr2:	Not reported
Owner City,St,Zip:	FLUSHING, NY 11354
Owner Country:	United States of America

FORMER MANHATTAN ADHESIVES PLANT (Continued) **S105972443**

Own Op:	Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Frank Castiglione
Owner Address:	32-02 College Point Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Flushing, NY 11354
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

246
NE
1/2-1
0.959 mi.
5063 ft.

Relative:
Higher

Actual:
39 ft.

LEVCO METALS PROPERTY **NY SHWS** **U003391190**
34-11 36TH STREET **NY AST** **N/A**
LONG ISLAND CITY, NY 11101 **NY HIST AST**
NY MANIFEST
NY Spills
NY VCP

SHWS:

Program:	HW
Site Code:	58675
Classification:	COMPLETED
Region:	2
Acres:	.500
HW Code:	241009
Record Add:	11/18/1999
Record Upd:	05/16/2012
Updated By:	JHOCONNE
Site Description:	See also Site no. V00600Location:The Levco Metals Finishers property is located in an urban area of New York City in an industrial part of Long Island City, Queens County. The address is 34-11 36th Street. Site Features:The entire site is occupied by a one story building which covers approximately 21,900 sq.ft. Historical Use:Levco was a metal finishing facility which conducted metal stripping, etching, and plating processes for over 30 years. Industrial operations ceased in November 1990. In March 1996, the Record of Decision (ROD) was executed, which recommended delisting of the site from the Registry. The site has been delisted from the Registry in May 1996. The ROD also recommended additional groundwater monitoring on a semi-annual basis.
Env Problem:	Nature and Extent of Contamination:Interim Remedial Measures (IRMs) consisting of excavation and off-site disposal of soil achieved the main remedial goals of the removal of hazardous waste in the former sump area and the cleanup of on-site soil to levels protective of the public health and the environment. Additional remedial action commenced in 2005 under the Voluntary Cleanup Program (see site no. V00600) which is intended to address residual contaminants in the groundwater. An off-site vapor investigation was completed in 2010 which concluded that there were no off-site vapor issues.Soil: Prior to IRM: elevated concentrations of volatile organic compounds (e.g.,

LEVCO METALS PROPERTY (Continued) **U003391190**

	2 ppm trichloroethane; 3.5 ppm trichloroethene) and metals (e.g. 21.2 ppm cadmium; 12 ppm chromium) were detected in the soil beneath the sump area. Contaminated soil from this area was excavated and disposed off site in October 1994.Groundwater : On-Site groundwater is contaminated as a result of disposal activities. Predominant contaminants above Class GA groundwater standards are trichloroethene, 1,1,1-trichloroethane, and cis-1,2-dichloroethene. The ROD recommended additional groundwater monitoring on a semi-annual basis. From 1996 to 2001, several rounds of groundwater monitoring have been conducted and showed that the contaminant levels in the groundwater beneath the site have not declined to acceptable levels. Further remediation of groundwater is being addressed under site no. V00600. Soil gas: An off-site vapor investigation was completed in 2010 which concluded that there were no off-site vapor issues.
Health Problem:	Soil and groundwater are contaminated with volatile organic compounds (VOCs). Exposure to contaminated groundwater is not expected since the area is served by public water. Contaminated soil is subsurface, therefore exposure is unlikely. A soil vapor extraction system is in place on-site to remediate VOCs in soil and soil vapor. Therefore, inhalation exposure via soil vapor exposure has been minimized. Additional data is needed to evaluate the potential for off-site exposure due to soil vapor intrusion.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	unknown
Disp Term:	1990
Lat/Long:	40:45:32:0 / 73:55:20:0
Dell:	False
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	11/18/1999 12:00:00 PM
Updated By:	INITIAL
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	KAUFMAN ASTORIA STUDIOS
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	CHARLES LEVA(DECEASED)
Owner Company:	Levco Metals
Owner Address:	34-11 36TH. STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	GEORGE S. KAUFMAN
Owner Company:	KAUFMAN ASTORIA STUDIOS
Owner Address:	34-12 36TH ST.
Owner Addr2:	Not reported

LEVCO METALS PROPERTY (Continued) **U003391190**

Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Kaufman Astoria Studios
Owner Address:	34-12 36th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
HW Code:	241009
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-334979
Program Type:	PBS
UTM X:	590557.77422999998
UTM Y:	4512160.55492
Expiration Date:	2017/11/16
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	15954
Affiliation Type:	On-Site Operator
Company Name:	3411 36TH AVENUE
Contact Type:	Not reported
Contact Name:	DIMITRIOS TSAKONAS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 249-1400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	10/11/2007

Site Id:	15954
Affiliation Type:	Facility Owner
Company Name:	DIMITRIOS TSAKONAS
Contact Type:	MANAGING AGENT
Contact Name:	ANNIE ASSOULINE
Address1:	415 EAST 75TH ST. APT 1FW
Address2:	Not reported

LEVCO METALS PROPERTY (Continued) **U003391190**

City:	NEW YORK
State:	NY
Zip Code:	10021
Country Code:	001
Phone:	(212) 249-1400
EMail:	ASAPROP@AOL.COM
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	10/11/2007

Site Id:	15954
Affiliation Type:	Mail Contact
Company Name:	DIMITRIOS TSAKONAS
Contact Type:	MANAGING AGENT
Contact Name:	ANNIE ASSOULINE
Address1:	415 EAST 75TH ST. APT 1FW
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10021
Country Code:	001
Phone:	(212) 249-1400
EMail:	ASAPROP@AOL.COM
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	10/11/2007

Site Id:	15954
Affiliation Type:	Emergency Contact
Company Name:	DIMITRIOS TSAKONAS
Contact Type:	Not reported
Contact Name:	AGRON KOLNDREKHA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 606-7237
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	1/3/2013

Tank Info:

Tank Number:	001
Tank Id:	20924
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None

LEVCO METALS PROPERTY (Continued) **U003391190**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1940
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	dxliving
Last Modified:	10/11/2007
Material Name:	#2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number:	2-334979
SWIS Code:	6301
Operator:	DIMITRIOS TSAKONAS
Facility Phone:	(718) 461-7357
Facility Addr2:	34011 36TH AVENUE
Facility Type:	Not reported
Emergency:	GREGORY ORTIS
Emergency Tel:	(718) 937-8437
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	DIMITRIOS TSAKONAS
Owner Address:	3161 38TH ST
Owner City,St,Zip:	ASTORIA, NY 11103
Federal ID:	Not reported
Owner Tel:	(718) 461-7357
Owner Type:	Not reported
Owner Subtype:	Not reported
Mailing Contact:	Not reported
Mailing Name:	DIMITRIOS TSAKONAS
Mailing Address:	3161 38TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	ASTORIA, NY 11103
Mailing Telephone:	(718) 461-7357
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	11/16/1987
Expiration:	11/16/1992
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	3000

LEVCO METALS PROPERTY (Continued) **U003391190**

FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	63
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	3000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	None
Leak Detection:	0
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
SPDES Number:	Not reported
Lat/Long:	Not reported

NY MANIFEST:

EPA ID:	NYD001316777
Country:	USA
Mailing Name:	LEVCO METAL FINISHES
Mailing Contact:	N/S
Mailing Address:	450 7TH AVE PENTHOUSE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10123
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-729-5200

NY MANIFEST:

No Manifest Records Available

LEVCO METALS PROPERTY (Continued) **U003391190**

SPILLS:

Facility ID:	8607571
DER Facility ID:	143329
Facility Type:	ER
Site ID:	170332
DEC Region:	2
Spill Date:	2/28/1987
Spill Number/Closed Date:	8607571 / 3/30/1987
Spill Cause:	Housekeeping
Spill Class:	Not reported
SWIS:	4101
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	3/12/1987
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	3/30/1987
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	3/13/1987
Spill Record Last Update:	2/18/2004
Spiller Name:	Not reported
Spiller Company:	LEVCO
Spiller Address:	34-11 36 ST.
Spiller City,St,Zip:	QUEENS, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was " " / / : PAUL DECKER (CERT. ENG. TEST. CO.) WILL SEND LAB RESULTS TO AUSTIN; MEETING WILL BE ARRANGED TO DEVELOP FURTHER STRAGETY. / / : PAUL DECKER (CERT. ENG. TEST. CO.) WILL SEND LAB RESULTS TO AUSTIN; MEETING WILL BE ARRANGED TO DEVELOP FURTHER STRATEGY. 10/10/95: This is additional information about material spilled from the translation of the old spill file: TRICHLORETHYLENE.
Remarks:	NOTIFIED OF CONTAMINATION BY CONSULTANT FOR PROPERTY OWNER.

Material:

Tank Test:

VCP:

Program Type:	VCP
Site Code:	57131
HW Code:	V00600
Site Class:	A
SWIS:	4101
Region:	2
Town:	New York City
Acres:	.500

LEVCO METALS PROPERTY (Continued) **U003391190**

Date Record Added: 07/23/2002
Date Record Updated: 06/11/2013
Updated By: JHOCONNE
Site Description: See also Site no. 241009Location:The Levco Metals Finishers property is located in an urban area of New York City in an industrial part of Long Island City, Queens County. The address is 34-11 36th Street. Site Features:The entire site is occupied by a one story building which covers approximately 21,900 sq.ft. Historical Use:Levco was a metal finishing facility which conducted metal stripping, etching, and plating processes for over 30 years. Industrial operations ceased in November 1990. In March 1996, under the State Superfund Program the Record of Decision (ROD) was executed, which recommended delisting of the site from the Registry. The site has been delisted from the Registry in May 1996. The ROD also recommended additional groundwater monitoring on a semi-annual basis. The additional groundwater monitoring is being addressed under the Voluntary Cleanup Program. Hydrogeology:Groundwater flows to the east.
Env Problem: Nature and Extent of Contamination:Interim Remedial Measures (IRMs) consisting of excavation and off-site disposal of soil achieved the main remedial goals of the removal of hazardous waste in the former sump area and the cleanup of on-site soil to levels protective of the public health and the environment. These actions were completed under the State Superfund (SSF) Program. Additional remedial action commenced in 2005 under the Voluntary Cleanup Program (see site no. V00600) which is intended to address residual contaminants in the groundwater. An off-site vapor investigation was completed in 2010 under the SSF Program which concluded that there were no off-site vapor issues.Soil - Prior to IRM: elevated concentrations of volatile organic compounds (e.g., 2 ppm trichloroethane; 3.5 ppm trichloroethene) and metals (e.g. 21.2 ppm cadmium; 12 ppm chromium) were detected in the soil beneath the sump area. Contaminated soil from this area was excavated and disposed off site in October 1994 under the SSF Program.Groundwater - On-Site groundwater is contaminated as a result of disposal activities. Predominant contaminants above Class GA groundwater standards are trichloroethene, 1,1,1-trichloroethane, and cis-1,2-dichloroethene. The SSF Record of Decision (ROD) recommended additional groundwater monitoring on a semi-annual basis. From 1996 to 2001, several rounds of groundwater monitoring have been conducted and showed that the contaminant levels in the groundwater beneath the site have not declined to acceptable levels. Further remediation of groundwater is being addressed under site no. V00600. Soil gas - An off-site vapor investigation was completed in 2010 which concluded that there were no off-site vapor issues.
Health Problem: Soil and groundwater are contaminated with volatile organic compounds (VOCs). Exposure to contaminated groundwater is not expected since the area is served by public water. Contaminated soil is subsurface and will be removed as part of a site-wide redevelopment. A sub-slab depressurization system will be incorporated into the new building to prevent soil vapor intrusion from site related contaminants of concern.

247
NE
1/2-1
0.966 mi.
5100 ft.

KAUFMAN ASTORIA STUDIOS
34-12 36TH ST
ASTORIA, NY 11106

NY SHWS **U001831683**
NY MANIFEST **N/A**
NY Spills

Relative:
Higher

Actual:
37 ft.

SHWS:

Program:	HW
Site Code:	460318
Classification:	N
Region:	2
Acres:	.920
HW Code:	241139
Record Add:	01/25/2012
Record Upd:	12/17/2012
Updated By:	KALEWAND

Site Description: Location: The Site is located at 34-12 36th Avenue, Long Island City, NY in an urban area. It consists of a four-story public school building with a partial basement and a total floor area of approximately 40,000 square feet. The school occupies the first 3 floors and the owner occupies the top floor.Site Features: The Site is bounded by 36th Avenue to the north followed by two four-story residential buildings, 35th Street to the east followed by two-story commercial buildings, two-story commercial and residential properties to the south, and three- and four-story residential with first floor commercial spaces to the west.Current Zoning/Use(s):The site is zoned as M1-1, and is surrounded by industrial, commercial and residential uses.Historic Use(s):The Site was a commercial building occupied by various manufacturing and warehousing entities including a cosmetic manufacturing firm from at least 1934 to approximately 1967. The Site was renovated for use as a public school in 2002. Site Topography, Geology and Hydrogeology:The Site is generally level and the surrounding area slopes downward from north to south.The geology of Queens County consists of unconsolidated glacial deposits overlying crystalline bedrock at about 80 feet below ground surface (bgs). Soil cores collected during prior investigations generally consisted of fill material containing brown sandy silt with some gravel, to a depth of 8 feet bgs. The Site is located 1.1 miles east of the East River and approximately 1.5 miles northeast of Newtown Creek. Groundwater is at 18 to 21 feet bgs. The hydraulic gradient direction is towards the southwest.The site did not qualify for addition to the Registry of Inactive Hazardous Waste Disposal Sites.

Env Problem: Nature and Extent of Contamination: The Supplemental Site Investigation (SSI) dated April 2012 indicated that the presence of tetra-chloroethylene (PCE) and its breakdown products at elevated concentrations in the underlying groundwater. The subsequent Addendum to the SSI performed in June 2012 revealed the presence of these chlorinated volatile organic compounds (CVOCs) at even higher concentrations in nearby upgradient locations.Soil ? There were no volatile organic compounds detected in soil samples at concentrations at or above the Unrestricted Use Soil Cleanup Objectives (UUSCOs). Twelve of sixty-five semi-volatile organic compounds (SVOCs) were detected in one or more soil samples. However, none were detected above the UUSCOs. Seven of the eight metals analyzed for were detected, but only lead and silver were detected at concentrations exceeding the UUSCOs. These were attributed to the characteristics of the fill material. PCBs were not detected in any of the soil samples.Groundwater ? On-site: Three VOCs, namely PCE (450 ppb), tri-chloroethylene (TCE-15 ppb), and cis-1,2-dichloroethylene (DCE-24

KAUFMAN ASTORIA STUDIOS (Continued) **U001831683**

ppb)were detected in groundwater samples at levels exceeding groundwater standards.Off-site: PCE and one or more of its breakdown products were detected above Class GA Standards in all of the groundwater samples save one. The highest concentrations of these CVOCs were detected in samples from monitoring wells located directly in front of the dry cleaning concern at 35-45 35th Street (13,600 ppb) and at the intersection of 35th Street and 36th Avenue (5,500 ppb -50 feet southwest of the dry cleaning concern) northeast of and directly upgradient of the Site.Sub-slab soil vapor ? Sixteen petroleum and chlorinated solvent related VOCs were detected in one or more of the four sub-slab soil vapor samples. Concentrations of 1,1-Dichloroethane (DCA), 1,2,4-Trimethylbenzene (TMB), 1,3,5-Trimethylbenzene, cis-1,2-Dichloroethene (DCE), PCE and TCE were detected at concentrations greater than the range of published background concentrations. PCE and TCE were detected at concentrations exceeding the NYSDOH Air Guideline Values (AGVs) in all four samples. Indoor Air ? Fifteen petroleum and chlorinated solvent related VOCs were detected in at least one of the two indoor air samples. The concentrations of 1,2,4-TMB, 1,3,5-TMB and PCE exceeded the range of corresponding background indoor air concentrations. However, the concentration of PCE was below the corresponding NYSDOH AGV. A subsequent indoor air sampling event confirmed these findings. Outdoor Air ? PCE was detected in the outdoor air sample at a concentration well below the concentrations found in indoor air and TCE was not detected in the outdoor air sample, indicating that the presence of these compounds in indoor air did not originate from ambient conditions. Significant Threat:The results of the SSI groundwater analysis revealed that PCE, TCE and cis-1,2-DCE were detected at concentrations above the NYSDEC groundwater standard on-site. The presence of these VOCs in groundwater did not appear to be attributable to an on-site source as there was no corresponding detections at high concentrations in soil samples. However, as the Addendum to the SSI revealed there are greater levels of CVOC contamination in nearby off-site upgradient locations and this is most likely the source of on-site CVOC contamination.CVOCs detected at elevated concentrations in sub-slab soil vapor and indoor air are attributable to the the contamination in groundwater. Comparisons of the sub-slab soil vapor concentrations of PCE and TCE to indoor air concentrations indicate that the vapor intrusion pathway is complete and, as per the NYSDOH decision matrices, mitigation is the recommended action. Therefore, a Sub-Slab Depressurization System is scheduled to be installed during the summer break.

Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	On-Site Operator

KAUFMAN ASTORIA STUDIOS (Continued) **U001831683**

Sub Type:	NNN
Owner Name:	Lee Guterman
Owner Company:	NYSCA
Owner Address:	30-30 Thomson Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Sharif El Fouly
Owner Company:	Sharif Designs Ltd.
Owner Address:	34-12 36th Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11106
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

NY MANIFEST:

EPA ID:	NY0000009092
Country:	USA
Mailing Name:	KAUFMAN ASTORIA STUDIOS
Mailing Contact:	TOM ADDIVINOLA
Mailing Address:	34-12 36TH ST
Mailing Address 2:	Not reported
Mailing City:	ASTORIA
Mailing State:	NY
Mailing Zip:	11106
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-392-5600

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	18-Jan-2013 00:00:00
Trans1 Recv Date:	18-Jan-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05-Feb-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	200

KAUFMAN ASTORIA STUDIOS (Continued) **U001831683**

Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	010560991JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	11-Jun-2013 00:00:00
Trans1 Recv Date:	11-Jun-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	26-Jun-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	350
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	011095730JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported

KAUFMAN ASTORIA STUDIOS (Continued) **U001831683**

Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	2012-04-24
Trans1 Recv Date:	2012-04-24
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-05-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	009633462JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	OH0000000539
Generator Ship Date:	2012-11-09
Trans1 Recv Date:	2012-11-09
Trans2 Recv Date:	2012-11-21
TSD Site Recv Date:	2012-12-12
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	562.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2012

KAUFMAN ASTORIA STUDIOS (Continued) **U001831683**

Manifest Tracking Num:	010098579JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	2012-07-26
Trans1 Recv Date:	2012-07-26
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-08-01
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	350.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	010098619JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	2012-07-03
Trans1 Recv Date:	2012-07-03
Trans2 Recv Date:	Not reported

KAUFMAN ASTORIA STUDIOS (Continued) **U001831683**

TSD Site Recv Date:	2012-07-15
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	350.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	010098873JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	2011-12-15
Trans1 Recv Date:	2011-12-15
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2011-12-30
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CDX480000000
Waste Code:	Not reported
Quantity:	250.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	009375889JJK
Import Ind:	N
Export Ind:	Y
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N

KAUFMAN ASTORIA STUDIOS (Continued) **U001831683**

Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	2011-08-03
Trans1 Recv Date:	2011-08-03
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2011-08-16
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	300.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	008825624JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	2012-04-24
Trans1 Recv Date:	2012-04-24
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-05-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

KAUFMAN ASTORIA STUDIOS (Continued) **U001831683**

TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	009633462JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	2012-07-26
Trans1 Recv Date:	2012-07-26
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-08-01
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	350.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	010098619JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

KAUFMAN ASTORIA STUDIOS (Continued) **U001831683**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	2012-07-03
Trans1 Recv Date:	2012-07-03
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-07-15
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	350.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	010098873JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

EPA ID:	NYD986973634
Country:	USA
Mailing Name:	EMMIS BROADCASTING INCORPORATED
Mailing Contact:	RICHARD A. JAMES
Mailing Address:	34-12 36TH STREET
Mailing Address 2:	Not reported
Mailing City:	ASTORIA
Mailing State:	NY
Mailing Zip:	11106
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-706-7690

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	18-Jan-2013 00:00:00
Trans1 Recv Date:	18-Jan-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05-Feb-2013 00:00:00

KAUFMAN ASTORIA STUDIOS (Continued) **U001831683**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	010560991JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	11-Jun-2013 00:00:00
Trans1 Recv Date:	11-Jun-2013 00:00:00
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	26-Jun-2013 00:00:00
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	350
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	011095730JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N

KAUFMAN ASTORIA STUDIOS (Continued) **U001831683**

Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	2012-04-24
Trans1 Recv Date:	2012-04-24
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-05-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	009633462JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	OH0000000539
Generator Ship Date:	2012-11-09
Trans1 Recv Date:	2012-11-09
Trans2 Recv Date:	2012-11-21
TSD Site Recv Date:	2012-12-12
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010

KAUFMAN ASTORIA STUDIOS (Continued) **U001831683**

Waste Code:	Not reported
Quantity:	562.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	010098579JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	2012-07-26
Trans1 Recv Date:	2012-07-26
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-08-01
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	350.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	010098619JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

KAUFMAN ASTORIA STUDIOS (Continued) **U001831683**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	2012-07-03
Trans1 Recv Date:	2012-07-03
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-07-15
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	350.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	010098873JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	2011-12-15
Trans1 Recv Date:	2011-12-15
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2011-12-30
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CDX480000000
Waste Code:	Not reported
Quantity:	250.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0

KAUFMAN ASTORIA STUDIOS (Continued) **U001831683**

Year:	2011
Manifest Tracking Num:	009375889JJK
Import Ind:	N
Export Ind:	Y
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	2011-08-03
Trans1 Recv Date:	2011-08-03
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2011-08-16
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	300.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	008825624JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	2012-04-24
Trans1 Recv Date:	2012-04-24

KAUFMAN ASTORIA STUDIOS (Continued) **U001831683**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-05-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	009633462JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	2012-07-26
Trans1 Recv Date:	2012-07-26
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-08-01
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	350.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	010098619JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N

KAUFMAN ASTORIA STUDIOS (Continued) **U001831683**

Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	2012-07-03
Trans1 Recv Date:	2012-07-03
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2012-07-15
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000009092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD083377010
Waste Code:	Not reported
Quantity:	350.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	010098873JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

SPILLS:

Facility ID:	1010245
DER Facility ID:	398753
Facility Type:	ER
Site ID:	443842
DEC Region:	2
Spill Date:	12/31/2010
Spill Number/Closed Date:	1010245 / 12/31/2010
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	4101
Investigator:	HRAHMED
Referred To:	Not reported

KAUFMAN ASTORIA STUDIOS (Continued) **U001831683**

Reported to Dept:	12/31/2010
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	12/31/2010
Spill Record Last Update:	12/31/2010
Spiller Name:	Not reported
Spiller Company:	METRO FUEL
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	RENEE LEWIS
Contact Phone:	Not reported
DEC Memo:	12/31/10-HRAHMED-Spoke to Rene Lewis (917 420 8330) of Alliance Mechanical. As per him, 5-7 gal of #6 oil spill from the vent line due to overfill. Noticed oil stain on the wall and side walk. PTC powewashed the wall and the sidewalk. There was no spill in the tankroom. Uploaded closure report and some picture in eDocs.This case is closed.
Remarks:	Caller advised overfill of tank. Clean up is in process.

Material:

Site ID:	443842
Operable Unit ID:	1194289
Operable Unit:	01
Material ID:	2190050
Material Code:	0003A
Material Name:	#6 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

248
SSW
1/2-1
0.981 mi.
5180 ft.

FORMER NEY SMELTING AND REFINING COMPANY **NY SHWS** **S113916765**
269 FREEMAN STREET **N/A**
GREENPOINT, NY 11222

Relative:
Lower

Actual:
12 ft.

SHWS:

Program:	HW
Site Code:	439622
Classification:	N
Region:	2
Acres:	1.200

FORMER NEY SMELTING AND REFINING COMPANY (Continued) **S113916765**

HW Code: 224144
Record Add: 09/08/2010
Record Upd: 10/31/2013
Updated By: MJKOMORO
Site Description: Location:The Site is located across multiple addresses in the Greenpoint section of Brooklyn, NY. The addresses for the Site include 257, 259, 263, & 269 Freeman Street and 230, 238, 242 Eagle Street. 269 Freeman Street is also known as 105 Provost Street. The Newtown Creek Water Pollution Control Plant (WPCP) is located directly east of the Site.Site Features:The original Site encompassed five separate buildings and three yards that occupy seven separate lots. The buildings are no more than 2 stories in height. The entire Site is approximately 1.2 acres in size. There are manufacturing buildings to the north, south and west of the Site.Current Zoning/Uses:The area (and properties) is zoned M3-1 which includes heavy manufacturing and industrial uses along with certain commercial uses. Properties on the site are currently used for the manufacturing of air conditioning duct work, a distribution center for paint and varnish, parking, and staging of various contracting equipment.- 263-269 Freeman and 242 Eagle Street are currently used for the manufacturing of air conditioning duct work and accessories- 238 Eagle street is currently used for the distribution of paint and varnish. - The Yard portion east of 238 Eagle Street is currently an unused dirt yard. Historical Uses:In the early 1900?s the site was used as a cooperage for wooden barrel and cask production. From approximately 1942 to 1982, the property was occupied by Reliable Machine Company that had numerous paint spraying locations on the property. In 1982, Ney Smelting and Refining Company took ownership of the property in 1982 and renovated the buildings and used the property for smelting of lead, tin and zinc. Smelting operations ceased in 2003.Site Geology and Hydrogeology:Shallow boring logs indicate the Site overlies historic fill. The soil type below the fill is not known. Depth to groundwater is approximately 10 feet below grade and may be tidally influenced due to the close proximity to the Newtown Creek. Groundwater flow may also be affected by the adjacent Newtown Creek WPCP. Groundwater flow direction is estimated to be to the northeastMiscellaneous:There are no PBS, CBS records for the multiple addresses of the Site.
Env Problem: The site is covered with multiple buildings and parking facilities. One small area of the site contains a dirt construction yard that is largely underlain by a concrete slab.The shallow subsurface soil is comprised of historic fill that contains building debris such as brick and concrete, ash, and soil. This material contains elevated concentrations of inorganics that are generally below allowable concentrations at industrial sites. SVOCs are also present in the soil at the site but also do not exceed standards for industrial areas. No VOCs were detected at levels that cause concern. Data from TCLP analyses were all below hazardous waste thresholds.Groundwater is sporadically impacted by PCE and breakdown products. There is no continuous plume of impacted groundwater as would be observed if a source of PCE was present.
Health Problem: Not reported
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported

FORMER NEY SMELTING AND REFINING COMPANY (Continued) **S113916765**

Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Owner
Sub Type:	02
Owner Name:	Greenpoint Group, LLC
Owner Company:	Greenpoint Group, LLC
Owner Address:	269 Freeman Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	03
Owner Name:	Michael Kustanovich
Owner Company:	Aleta Group, Inc.
Owner Address:	242 Eagle Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	09
Owner Name:	Haim Boiangiu
Owner Company:	Abbot Paint & Varnish
Owner Address:	238 Eagle St.
Owner Addr2:	Not reported
Owner City,St,Zip:	Green Point, NY 11222
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	03
Owner Name:	Geno Camali
Owner Company:	259 Freeman, LLC
Owner Address:	304 Harrington Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	Closter, NJ 07624
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	03
Owner Name:	Herb Lowenstein
Owner Company:	238 Eagle Realty Co. LLC.
Owner Address:	3006 Davis Pl
Owner Addr2:	Not reported
Owner City,St,Zip:	Oceanside, NY 11572
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

249
South
1/2-1
0.991 mi.
5233 ft.

460 KINGSLAND AVENUE LLC
460 KINGSLAND AVE
BROOKLYN, NY 11222

NY SHWS **U003074537**
NY HIST UST **N/A**
NY AST
NY MANIFEST
NY Spills

Relative:
Lower

Actual:
9 ft.

SHWS:

Program:	HW
Site Code:	415641
Classification:	P
Region:	2
Acres:	3.500
HW Code:	224135
Record Add:	06/25/2009
Record Upd:	09/15/2010
Updated By:	SRHEIGEL

Site Description: The Site is located at 460 Kingsland Avenue in the northernmost section of Brooklyn within a commercial/industrial area and is approximately 3.5 acres in size. It is bordered by Newtown Creek to the east, Kingsland Avenue to the west, Greenpoint Avenue to the north (adjacent to Newtown Creek WPCP), and the Former ExxonMobil Brooklyn Terminal (Mobil Brooklyn Refinery) to the south. Topographic elevations at the Site are approximately 7 feet above mean sea level (amsl) within the southeastern portion of the Site and gradually rise to approximately 11 ft amsl within the northwestern portion of the Site.The Site is currently vacant but was most recently used as a trucking distribution hub. The site has two abutting one-story buildings divided into storage and office space. Exterior areas are paved and used for delivery and shipping purposes, as well as the staging of delivery vehicles. The Site was historically operated as part of the former Mobil Brooklyn Refinery (SOCONY), which itself was a continuation of petroleum refining and storage operations that were prevalent in Greenpoint since the mid-Nineteenth Century. As part of the earlier petroleum refining and storage operations, the southern region of the Site was used for petroleum bulk storage purposes whereas improvements in the northern region of the Site included a distillery and a boiler works storage yard. Under former operations, the Site also served as a petroleum bulk storage yard that included three petroleum bulk storage tanks, two chemical bulk storage tanks containing acids, and an API-type oil/water separator along the southern Site boundary. The site was reportedly used by Mobil?s Technical Services Division (TSD) for study of petroleum product uses.After refinery operations at the former Mobil Brooklyn Refinery ceased in 1966, the Site was sold in 1967 and redeveloped with the existing commercial building in 1968 and occupied by miscellaneous trucking operations. In addition, fifteen underground storage tanks containing diesel fuel, heating oil, and waste oil were maintained during the operation of the commercial/transfer facilities and were removed in 1994. A spill (#9402812) reported during the tank removal initiated site investigation and characterization activities. In addition, ExxonMobil has performed some investigation of the site as part of the remediation of the former Mobil Brooklyn Refinery.The initial investigation activities indicated petroleum-impacted soils existed within the shallow subsurface beneath the Site and that free-phase petroleum product was also located within the shallow subsurface. More recent sampling seeking to close the open spill identified PCB contamination in shallow soil under the asphalt pavement and indicated limited groundwater contamination from PCBs exists.

460 KINGSLAND AVENUE LLC (Continued) **U003074537**

Env Problem:	Soil sampling indicates that hazardous waste disposal has occurred at the site. Groundwater sampling at the site indicates that PCBs may be present in the shallow groundwater at levels above the NYSAWQS. Additional site characterization is necessary to examine complete nature and extent in groundwater and soil and to determine if a significant amount of waste is present.Petroleum impacts are present in site in shallow and deeper soils, and in groundwater from former refining operations on and near the site.
Health Problem:	As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Owner
Sub Type:	02
Owner Name:	Not reported
Owner Company:	NEW SAG LLC
Owner Address:	2 GALASSO PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	MASPETH, NY 11378
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	SALVATORE TROVATO
Owner Company:	REVEAL KINGSLAND LLC
Owner Address:	X
Owner Addr2:	Not reported
Owner City,St,Zip:	X, NY 11222
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	FRANK GALASSO
Owner Company:	NEWSAG LLC
Owner Address:	X
Owner Addr2:	Not reported
Owner City,St,Zip:	X, NY 11222
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

460 KINGSLAND AVENUE LLC (Continued) **U003074537**

HIST UST:

PBS Number:	2-318035
SPDES Number:	Not reported
Emergency Contact:	CARL BEZNOTT
Emergency Telephone:	(913) 344-3000
Operator:	STEVE SHINNERS
Operator Telephone:	(913) 344-3000
Owner Name:	YELLOW FREIGHT SYSTEM, INC
Owner Address:	10990 ROE AVE
Owner City,St,Zip:	OVERLAND PARK, KS 66211
Owner Telephone:	(913) 345-3000
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	YELLOW FREIGHT SYSTEM, INC
Mailing Address:	10990 ROE AVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	OVERLAND PARK, KS 66211
Mailing Contact:	ENVIRONMENTAL SERVICES
Mailing Telephone:	(913) 344-3000
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	460 KINGSLAND AVE
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	TRUCKING/TRANSPORTATION
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	09/04/1992
Expiration Date:	07/20/1997
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	275
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2
Tank Id:	006
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	DIESEL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Not reported
Pipe Location:	Underground

460 KINGSLAND AVENUE LLC (Continued) **U003074537**

Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Submersible
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 07/01/1994
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 007
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: DIESEL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Not reported
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Submersible
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 07/01/1994
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 015
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 1000
Product Stored: UNKNOWN
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None

460 KINGSLAND AVENUE LLC (Continued) **U003074537**

Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 07/01/1994
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated
Facility Id: 2-318035
Program Type: PBS
UTM X: 589315.25375000003
UTM Y: 4509558.9214300001
Expiration Date: N/A
Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:
Site Id: 14649
Affiliation Type: Facility Owner
Company Name: YELLOW FREIGHT SYSTEM, INC
Contact Type: Not reported
Contact Name: Not reported
Address1: 10990 ROE AVE
Address2: Not reported
City: OVERLAND PARK
State: KS
Zip Code: 66211
Country Code: 001
Phone: (913) 345-3000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 14649
Affiliation Type: Mail Contact
Company Name: YELLOW FREIGHT SYSTEM, INC
Contact Type: Not reported
Contact Name: ENVIRONMENTAL SERVICES
Address1: 10990 ROE AVE
Address2: Not reported
City: OVERLAND PARK
State: KS
Zip Code: 66211
Country Code: 001
Phone: (913) 344-3000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT

460 KINGSLAND AVENUE LLC (Continued) **U003074537**

Date Last Modified: 3/4/2004

Site Id: 14649
Affiliation Type: On-Site Operator
Company Name: YELLOW FREIGHT SYSTEM, INC
Contact Type: Not reported
Contact Name: STEVE SHINNERS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (913) 344-3000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 14649
Affiliation Type: Emergency Contact
Company Name: YELLOW FREIGHT SYSTEM, INC
Contact Type: Not reported
Contact Name: CARL BEZNOTT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (913) 344-3000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 014
Tank Id: 48533
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
I00 - Overfill - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed

460 KINGSLAND AVENUE LLC (Continued) **U003074537**

Pipe Model:	Not reported
Install Date:	07/01/1994
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/01/1994
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	Other

Tank Number:	017
Tank Id:	48535
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1978
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	Other

NY MANIFEST:

EPA ID:	NYR000165910
Country:	USA
Mailing Name:	460 KINGSLAND AVENUE LLC
Mailing Contact:	STEVE TRIFILETTI
Mailing Address:	460 KINGSLAND AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11222
Mailing Zip4:	Not reported
Mailing Country:	USA

460 KINGSLAND AVENUE LLC (Continued) **U003074537**

Mailing Phone: 631-232-2600

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD045995693
Trans2 State ID: MAD084814136
Generator Ship Date: 2009-11-02
Trans1 Recv Date: 2009-11-02
Trans2 Recv Date: 2009-11-06
TSD Site Recv Date: 2009-11-20
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000165910
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: MID048090633
Waste Code: Not reported
Quantity: 454.0
Units: K - Kilograms (2.2 pounds)
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 006444509JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H132

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD080631369
Trans2 State ID: Not reported
Generator Ship Date: 2010-03-26
Trans1 Recv Date: 2010-03-26
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-04-02
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000165910
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD980536593
Waste Code: Not reported
Quantity: 1638.0
Units: K - Kilograms (2.2 pounds)
Number of Containers: 9.0

460 KINGSLAND AVENUE LLC (Continued) **U003074537**

Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	000346858VES
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

SPILLS:

Facility ID:	9403747
DER Facility ID:	251993
Facility Type:	ER
Site ID:	312530
DEC Region:	2
Spill Date:	6/16/1994
Spill Number/Closed Date:	9403747 / 12/26/2002
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	SJMILLER
Referred To:	Not reported
Reported to Dept:	6/16/1994
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/22/1994
Spill Record Last Update:	10/3/2003
Spiller Name:	Not reported
Spiller Company:	YELOW FREIGHT LINE
Spiller Address:	460 KINGSLAND AVENUE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MILLER"SEE EARLY, OPEN SPILL REPORT NO. 9402812.10/10/95: This is additional information about material spilled from the translation of the old spill file: PETRO & HYDRO CARBON.12/26/02, MILLER CLOSED SPILL REPORT 9403747 AND CROSS-REFERENCED IT WITH OPEN, EARLIER SPILL REPORT NO. 9402812.

460 KINGSLAND AVENUE LLC (Continued) **U003074537**

Remarks: SPILL PREVIOUSLY REPORTED

Material:

Site ID:	312530
Operable Unit ID:	997426
Operable Unit:	01
Material ID:	383917
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9402812
DER Facility ID:	251993
Facility Type:	ER
Site ID:	312529
DEC Region:	2
Spill Date:	5/19/1994
Spill Number/Closed Date:	9402812 / 3/27/2009
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	5/26/1994
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	7/22/1994
Spill Record Last Update:	3/31/2009
Spiller Name:	Not reported
Spiller Company:	YELLOW FREIGHT SYSTEM
Spiller Address:	10990 ROE AVENUE
Spiller City,St,Zip:	OVERLAND PARK, KS 662
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ROMMEL" ALSO SEE LATER, CLOSED SPILL REPORT NO. 9403747.10/10/95: This is additional information about material spilled from the translation of the old spill file: HEAVY FUEL OIL.03/29/04Related to

460 KINGSLAND AVENUE LLC (Continued) **U003074537**

Mobil Greenpoint spillTransferred from Miller to Rommel.10/12/04Received call from John Harrison, EcolSciences, Rockaway, NJ, 973-366-9500, representing potential buyer. Plans to FOIA the file. Rommel3/4/05 - Mr. Arthur Max, a consultant representing the current owner called to inquire about what it takes to close out the case. His Number is 201-867-6777. Transfer it to Alex Zhitomirsky. - KST3/31/2005 According to Arthur Max Yellow Freight pulled some tanks in 1994. They found and removed most of the soil contamination. DEC asked to remove more contamination around the perimeter. Woodward Clyde stated that due to the Mobil spill and high background contamination there is no point in removing more soil. Weintraub real estate company was hired by Yellow Freight. Alex Zhitomirsky requested on March 4, 2005, that the responsible party should submit documentation supporting their case to NYSDEC. AZ9/26/2005 Conversation with Arthur Max. They want to buy this property and inquired what should be done in order to close this spill. I responded that site assessment should be performed. Gw wells installed at the property and along the perimetr of the property in order to compare background contamination with the site contamination. AZ1/17/2006 I left a message for Arthur Max. Investigation/delineation is pending. AZ1/18/2006 I contacted Arthur Max (Weintraub, Casey - Realtors 201-876-6777). He informed me that they sold this property in November 2005 to Sagres, LLC 2 Galasso Place, Maspeth, NY 11378 718-456-1800(?)(they are in the same building as Galasso Trucking).I contacted Frank Galasso (partner) at 718-456-1800. He said that I should talk to Phil Galasso (partner)516-965-7766. He will ask him to contact me ASAP. AZ4/3/2006 I contacted Phil Galasso (Reveal New Sag LLC.)516-965-7766. He will file for FOIL and have his consultant contact me. AZ6/13/2006 I left a message for John Urda (DEC Legal)requesting his assistance with this case. AZ6/14/2006 Jon Kolleeny recommended to refer this case to J. Urda. J. Urda recommended to send RP a short form STIP. J. Kolleeny supported this recommendation. A short form STIP was sent to Phil Galasso, Sagres LLC, 2 Galasso Place, Maspeth, NY 11378 AZ6/27/2006 Received a message from Steve Russo (212-421-2150). Left a message for Steve Russo. AZ6/27/2006 Conversation with Steve Russo, attorney for the owner (Reveal New Sag). He works for Sive Paget company(212-421-2150). They will send me report for review. I will get back to them when I review the report. AZ6/28/2006 The report does not contain a map showing the locations of the old excavated tanks (15 USTs). No borings were installed near the old tank field. Fingerprint analyses were not attached. AZ7/27/2006 Left a message for Steve Russo (Sive, Paget & Riesel). AZ 8/2/2006 Conversation with Steve Russo (212-421-2150). I conveyed to him that the report lacks essential information:borings/wells were not installed near the old tank field; there is no map showing the old excavated tanks (15 USTs), fingerprint analyses were not attached to the report. DEC requested new borings/wells installation, mointoring of the new wells and fingerprint analyses of the free phase. He will get back to me with a plan of actin in a week. AZ8/10/06 I sent e-mail to Steven Russo Sive, Paget & Riesel, P.C. at 460 Park Avenue New York, New York 10022(212) 421-2150 confirming the additional items that should be submitted to DEC:1. A sampling plan providing for the installation of groundwater wells and collection of soil samples proximate to the area where the former Yellow Freight USTs were excavated 2. Reflect the former UST location on the map or maps accompanying the supplemental sampling plan 3. Provide results of historic and new

460 KINGSLAND AVENUE LLC (Continued) **U003074537**

fingerprint analysis of petroleum, if any, collected from the newly installed monitoring wells or, if no free product is collected from the wells, from soil samples. AZ1/31/2007 I contacted Steven Russo @ (212) 421-2150 (Sive, Paget & Riesel). Exxon Mobil is preparing an extensive sampling plan for this site which will be submitted within a month. He will send me fingerprint analyses and a map with tank locations. He will forward a sampling plan as soon as it will be available. AZ2/6/2007 Received historical and current fingerprint analyses from Steve Russo. He stated that "we are hoping to finalize access issues with Exxon Mobil in the next week so that a work plan to more fully investigate the site can be submitted shortly." AZ4/13/2007 Received e-mail from Ed Hampston (DER Albany). He received proposed investigation plan (part of investigations associated with the former Mobil Refinery/Terminal from Exxon) and forwarded it to Reg. 2. E. Hampston will likely to request some of their borings go beyond the first impermeable layer they encounter (or nest wells) to see if there is deeper contamination. I reviewed the Exxon proposals and discussed the work plan with Ed. I suggested increasing the number of wells (they initially suggested 3 wells), advancing wells at the locations of the former Yellow Freight tanks, advancing wells near the Exxon plume boundaries, performing fingerprint analyses on all samples, compiling detailed groundwater and soil plume maps. AZ11/1/2007 Reviewed Investigation Report by Roux Associates dated August 2, 2007 and received on August 21, 2007. Nine soil borings and three new shallow aquifer wells wells and three new regional aquifer monitoring wells were completed. SVOC and metals were detected at concentrations greater than the NYSDEC Restricted Commercial Use Criteria in the shallow subsurface beneath the property. with the highest concentrations present in the vicinity of SB-4, SB-7, SB-9. PCBs were also detected at three soil borings with the highest concentrations observed at SB-6. Although petroleum staining was observed throughout the shallow subsurface, only globules of free product were observed at two locations that were associated historic petroleum storage operations. There were no observed visual impacts within the regional aquifer. VOC and SVOCs are present in groundwater above the NYSDEC AWQSGV within the shallow aquifer. PCB were detected in one location within the sallow aquifer at monitoring well KNW-4. Within the regional aquifer, only minor concentrations of petroleum and chlorinated compounds were observed in gw above the guidance level. According to the report, data indicated that the free product plume present within the regional aquifer beneath the Exxon Mobil Brooklyn Terminal to the south of the property does not extend to the north beneath the property. AZ 12-27-2007 Letters to Phil Galasso and Exxon Mobil were sent out by DEC (Ed Hampston - Central Office). The DEC letters required further investigation and remediation of the site. AZ1-9-2008 Meeting with Philip Galasso (Revael New Sag), John Urda, Ed Hapston, Alan Michaels (by phone NYSDEC), Michael Bogin (Steve, Paget), Dan Buget. AZ8-12-2008 The owner is proceeding with the sale of the property. The existing building will be demolished for a "clean fill" recycling operation. As part of the demo, they intend to dig out around the building footprint, and want to know if this will be enough to close the UST spill. I recommended taking the end point samples. Also, a work plan containing a site map with UST locations, hot spots (based on the previous investigations), the excavation area and proposed sampling locations should be submitted to DEC. I conveyed my suggestions to John Urda and Ed Hampston. AZ10-27-2008 I have

460 KINGSLAND AVENUE LLC (Continued) **U003074537**

received an e-mail from Ed Hampston who forwarded a request for spill closure by Leggette, Brashears @ Graham. I e-mailed my response to John Urda and Ed Hampstead. AZ10-29-2008 Conference call with John Urda and Michael Bogin. DEC requested that New Sag investigate and remediate area in front of the building at the locations of the former USTs (diesel, waste oil and heating oil tanks). According to September 19, 1994 closure report, waste oil tank had 3 holes and soil in the USTs area exhibited VOC exceedances. Also, VOC concentrations in the former USTs area exceeded the background concentrations. DEC (Mike Mulqueen 2-27-1995) requested further investigation and remediation. AZ1-8-2008 A conference call with Central office was held (V.Brevdo, J. Urda, Ed Hampston, Alan Michaels, Joseph White). The site was discussed. Central Office will work with Exxon Mobil to address PCB contamination. AZ2/4/2009 A meeting was held among Alex Zhitomirsky, John Urda, Vadim Brevdo, Allan Michaels, Ed Hampston of DEC and Phil Galasso and Michael Bogin representing Mr. Galasso. Phil Galasso and Michael Bogin presented information that appears to support their conviction that PCB contamination and remaining petroleum contamination plums are part of a greater Exxon Mobil plume (Greenpoint plume) and, therefore, should be investigated/remediated by Exxon Mobil. It was decided that Albany (Ed Hempston and Allan Michaels) will call a meeting with Exxon Mobil so the other party can present their case. If information presented by 460 Kingsland owners is confirmed then this spill number will be closed and referred to a main spill number of Greenpoint (Exxon Mobil)spill for further investigation/remediation. AZ3-27-2009 After consultation with V. Brevdo, J. Urda and Ed Hampston this spill number is closed. According to Ed Hampston, all further activities for this site will be tracked under spill #8800244 (this is the spill Central Ofiice has PIN attached). Ed Hampston intends to create a P site for 460 Kingsland. AZ

Remarks: FOUNDATION TEST BARINGS-OIL MAY BE FROM ADJACENT MOBIL REFINERY

Material:

Site ID:	312529
Operable Unit ID:	996611
Operable Unit:	01
Material ID:	567174
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	0307959
DER Facility ID:	251993
Facility Type:	ER
Site ID:	107522
DEC Region:	2
Spill Date:	10/28/2003

460 KINGSLAND AVENUE LLC (Continued) **U003074537**

Spill Number/Closed Date:	0307959 / 11/13/2003
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	2401
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	10/28/2003
CID:	207
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	10/28/2003
Spill Record Last Update:	11/13/2003
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	FDNY DISP 381
Contact Phone:	(718) 965-8300
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO"10/28/2003 - ROSSAN, DDO; Called FDNY Disp. 381, who confirmed that clean-up is been done by the Sanitation Dept. using Spedi-dri. and sand. Advised that the NYS-DEP be informed. FDNY called again to cinfirmed that amount of diesel spilled is 200 gallons.Discussed with Michelle, who decided to visit spill site. Ed.10/29/03 Tipple conducted site visit//sand still on roadway//three drums of mostly liquid oil on site//called FDNY, located captain who responded, by the time the FD arrived, the truck responsible for the spill was long gone. Upon interviewing individuals who worked adjacent to the facility the truck was a dark green fuel iol truck, no one interviewed noticed the name of the company. NO RP IDENTIFIED. put drums on drum run.11/13/03 TJDContainers emptied on 11/7/03 as part of R2 drum run. See spill #9930008. Spill closed.
Remarks:	cleanup in progress

Material:

Site ID:	107522
Operable Unit ID:	874334
Operable Unit:	01
Material ID:	501480
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

460 KINGSLAND AVENUE LLC (Continued) **U003074537**

Tank Test:

Count: 20 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BRONX	1010488291	NYSDOT BIN 1066220	GRANT HIGHWAY OVER CROSS BRONX	11101	FINDS, NY MANIFEST
BRONX	1000458300	NYCDEP	TUNNEL #3 ROOSEVELT ISLAND	10468	RCRA NonGen / NLR, FINDS, NY MANIFEST
BROOKLYN	1007207157	CONSOLIDATED EDISON	VS2299-47TH & 43RD	11201	RCRA NonGen / NLR, NY MANIFEST
LONG ISLAND CITY	1004758973	NYCDOT	39TH STREET BRIDGE(SUNNY SIDE)	11101	RCRA NonGen / NLR, FINDS, NY MANIFEST
LONG ISLAND CITY	1007208435	CONSOLIDATED EDISON	TM 632 40 AVE & CRESECNT ST		RCRA NonGen / NLR, NY MANIFEST
LONG ISLAND CITY	1004758556	NYSDOT	CLEARVIEW EXP #14	11101	RCRA NonGen / NLR, FINDS, NY MANIFEST
LONG ISLAND CITY	1004758555	NYSDOT	CLEARVIEW EXPWAY #13	11101	RCRA NonGen / NLR, FINDS, NY MANIFEST
LONG ISLAND CITY	1007112483	MTA EXISTING RAIL YARD	QUEENS ST - DEAD END	11101	RCRA NonGen / NLR
LONG ISLAND CITY	1007208408	CONSOLIDATED EDISON	TM6766-JACKSON AVE & CRDANE ST		RCRA NonGen / NLR, NY MANIFEST
QUEENS	1007206732	CONSOLIDATED EDISON	7598 - 21ST & 43 AVE		RCRA NonGen / NLR, NY MANIFEST
QUEENS	1007206606	CONSOLIDATED EDISON	V 4551 - 44 AVE & 22 ST		RCRA NonGen / NLR, NY MANIFEST
QUEENS	1007206690	CONSOLIDATED EDISON	VS 7533 - 43 AVE & 38 ST		RCRA NonGen / NLR, NY MANIFEST
QUEENS	1007206568	CONSOLIDATED EDISON	V 8013 - 33RD & CRESCENT ST		RCRA NonGen / NLR, NY MANIFEST
QUEENS	1007206626	CONSOLIDATED EDISON	VS 8487 - QUEENS BLVD & 38 ST		RCRA NonGen / NLR, NY MANIFEST
QUEENS	1007206681	CONSOLIDATED EDISON	V 9093 - 36 ST & QUEENS BLVD	11357	RCRA NonGen / NLR, NY MANIFEST
QUEENS	1004755718	NYCDOT BRIDGES BIN 2247260	JACKSON AVE BRIDGE OVER	11101	RCRA NonGen / NLR, FINDS
QUEENS	1006810334	CON ED	11 ST QUEENS PLAZA SOUTH		RCRA-CESQG, NY MANIFEST
QUEENS	1001489235	NYCTA	QUEENSBORO PLAZA		RCRA-CESQG, FINDS, NY MANIFEST
QUEENS	1007206689	CONSOLIDATED EDISON	V3601-34TH ST & 43RD AVE	11428	RCRA NonGen / NLR, NY MANIFEST
QUEENS COUNTY	S112209750	CONSOLIDATED EDISON CO #3000	ROUTE 133 AND STONE		NY MANIFEST

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 04/26/2013
Date Data Arrived at EDR: 05/09/2013
Date Made Active in Reports: 07/10/2013
Number of Days to Update: 62

Source: EPA
Telephone: N/A
Last EDR Contact: 11/11/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 04/26/2013
Date Data Arrived at EDR: 05/09/2013
Date Made Active in Reports: 07/10/2013
Number of Days to Update: 62

Source: EPA
Telephone: N/A
Last EDR Contact: 11/11/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

DELISTED NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 04/26/2013
Date Data Arrived at EDR: 05/09/2013
Date Made Active in Reports: 07/10/2013
Number of Days to Update: 62

Source: EPA
Telephone: N/A
Last EDR Contact: 11/11/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Quarterly

Federal CERCLIS list

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 04/26/2013
Date Data Arrived at EDR: 05/29/2013
Date Made Active in Reports: 08/09/2013
Number of Days to Update: 72

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 11/11/2013
Next Scheduled EDR Contact: 03/10/2014
Data Release Frequency: Quarterly

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 10/09/2012
Date Made Active in Reports: 12/20/2012
Number of Days to Update: 72

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 10/11/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Varies

Federal CERCLIS NFRAP site List

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 04/26/2013
Date Data Arrived at EDR: 05/29/2013
Date Made Active in Reports: 08/09/2013
Number of Days to Update: 72

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 11/11/2013
Next Scheduled EDR Contact: 03/10/2014
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 07/11/2013
Date Data Arrived at EDR: 08/08/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 36

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 10/02/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 07/11/2013
Date Data Arrived at EDR: 08/08/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 36

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 10/02/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 07/11/2013
Date Data Arrived at EDR: 08/08/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 36

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 10/02/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 07/11/2013
Date Data Arrived at EDR: 08/08/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 36

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 10/02/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 07/11/2013
Date Data Arrived at EDR: 08/08/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 36

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 10/02/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Varies

Federal institutional controls / engineering controls registries

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 06/17/2013
Date Data Arrived at EDR: 06/21/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 104

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 09/10/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 06/17/2013
Date Data Arrived at EDR: 06/21/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 104

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 09/10/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Varies

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 08/20/2013
Date Data Arrived at EDR: 08/23/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 70

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 11/18/2013
Next Scheduled EDR Contact: 03/03/2014
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 01/17/2013
Date Made Active in Reports: 02/15/2013
Number of Days to Update: 29

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 10/01/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Annually

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 11/13/2013
Date Data Arrived at EDR: 11/13/2013
Date Made Active in Reports: 11/18/2013
Number of Days to Update: 5

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 11/13/2013
Next Scheduled EDR Contact: 03/03/2014
Data Release Frequency: Annually

VAPOR REOPENED: Vapor Intrustion Legacy Site List
New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2013
Date Data Arrived at EDR: 02/20/2013
Date Made Active in Reports: 03/15/2013
Number of Days to Update: 23
Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 11/22/2013
Next Scheduled EDR Contact: 03/03/2014
Data Release Frequency: Varies

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register
Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 10/08/2013
Date Data Arrived at EDR: 10/09/2013
Date Made Active in Reports: 11/14/2013
Number of Days to Update: 36
Source: Department of Environmental Conservation
Telephone: 518-457-2051
Last EDR Contact: 10/07/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Semi-Annually

State and tribal leaking storage tank lists

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 09/25/2013
Date Data Arrived at EDR: 09/26/2013
Date Made Active in Reports: 11/15/2013
Number of Days to Update: 50
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 11/22/2013
Next Scheduled EDR Contact: 03/03/2014
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks
A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 03/01/2013
Date Data Arrived at EDR: 03/01/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 42
Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Quarterly

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 02/01/2013
Date Data Arrived at EDR: 05/01/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 184
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 11/01/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 08/01/2013
Date Data Arrived at EDR: 08/02/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 91
Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Semi-Annually

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 08/27/2012
Date Data Arrived at EDR: 08/28/2012
Date Made Active in Reports: 10/16/2012
Number of Days to Update: 49
Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Quarterly

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 08/27/2013
Date Data Arrived at EDR: 08/27/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 66
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 09/12/2011
Date Data Arrived at EDR: 09/13/2011
Date Made Active in Reports: 11/11/2011
Number of Days to Update: 59
Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 08/20/2013
Date Data Arrived at EDR: 08/23/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 70
Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 07/29/2013
Date Data Arrived at EDR: 07/30/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 94
Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

State and tribal registered storage tank lists

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 11/13/2013
Date Data Arrived at EDR: 11/13/2013
Date Made Active in Reports: 11/18/2013
Number of Days to Update: 5

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 11/13/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Quarterly

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 11/13/2013
Date Data Arrived at EDR: 11/13/2013
Date Made Active in Reports: 11/18/2013
Number of Days to Update: 5

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 11/13/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: Varies

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 11/13/2013
Date Data Arrived at EDR: 11/13/2013
Date Made Active in Reports: 11/18/2013
Number of Days to Update: 5

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 11/13/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 11/13/2013
Date Data Arrived at EDR: 11/13/2013
Date Made Active in Reports: 11/18/2013
Number of Days to Update: 5

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 11/13/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Quarterly

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 11/13/2013
Date Data Arrived at EDR: 11/13/2013
Date Made Active in Reports: 11/18/2013
Number of Days to Update: 5

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 11/13/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Quarterly

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 08/01/2013
Date Data Arrived at EDR: 08/02/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 91

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Semi-Annually

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 09/28/2012
Date Data Arrived at EDR: 11/07/2012
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 156

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 11/01/2014
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 08/20/2013
Date Data Arrived at EDR: 08/23/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 70

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 05/10/2011
Date Data Arrived at EDR: 05/11/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 34

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Semi-Annually

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 02/28/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 43

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 07/29/2013
Date Data Arrived at EDR: 08/01/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 92

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Quarterly

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 02/05/2013
Date Data Arrived at EDR: 02/06/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 65

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Quarterly

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 02/21/2013
Date Data Arrived at EDR: 02/26/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 45

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Quarterly

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010
Date Data Arrived at EDR: 02/16/2010
Date Made Active in Reports: 04/12/2010
Number of Days to Update: 55

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 10/17/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

ENG CONTROLS: Registry of Engineering Controls
Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 11/13/2013
Date Data Arrived at EDR: 11/13/2013
Date Made Active in Reports: 11/18/2013
Number of Days to Update: 5
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 11/13/2013
Next Scheduled EDR Contact: 03/03/2014
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls
Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 11/13/2013
Date Data Arrived at EDR: 11/13/2013
Date Made Active in Reports: 11/18/2013
Number of Days to Update: 5
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 11/13/2013
Next Scheduled EDR Contact: 03/03/2014
Data Release Frequency: Quarterly

RES DECL: Restrictive Declarations Listing
A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/18/2010
Date Data Arrived at EDR: 12/23/2010
Date Made Active in Reports: 02/11/2011
Number of Days to Update: 50
Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 09/27/2013
Next Scheduled EDR Contact: 01/08/2014
Data Release Frequency: No Update Planned

State and tribal voluntary cleanup sites

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27
Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 09/28/2012
Date Data Arrived at EDR: 10/02/2012
Date Made Active in Reports: 10/16/2012
Number of Days to Update: 14
Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 10/01/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Varies

VCP: Voluntary Cleanup Agreements
New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 11/13/2013
Date Data Arrived at EDR: 11/13/2013
Date Made Active in Reports: 11/20/2013
Number of Days to Update: 7
Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 11/13/2013
Next Scheduled EDR Contact: 03/03/2014
Data Release Frequency: Semi-Annually

State and tribal Brownfields sites

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 11/13/2013
Date Data Arrived at EDR: 11/13/2013
Date Made Active in Reports: 11/18/2013
Number of Days to Update: 5

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 11/13/2013
Next Scheduled EDR Contact: 03/03/2014
Data Release Frequency: Quarterly

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 11/13/2013
Date Data Arrived at EDR: 11/13/2013
Date Made Active in Reports: 11/18/2013
Number of Days to Update: 5

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 11/13/2013
Next Scheduled EDR Contact: 03/03/2014
Data Release Frequency: Semi-Annually

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 06/24/2013
Date Data Arrived at EDR: 06/25/2013
Date Made Active in Reports: 08/09/2013
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 09/24/2013
Next Scheduled EDR Contact: 01/08/2014
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: No Update Planned

SWRCY: Registered Recycling Facility List
A listing of recycling facilities.

Date of Government Version: 10/08/2013
Date Data Arrived at EDR: 10/09/2013
Date Made Active in Reports: 11/14/2013
Number of Days to Update: 36

Source: Department of Environmental Conservation
Telephone: 518-402-8705
Last EDR Contact: 10/07/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Semi-Annually

SWTIRE: Registered Waste Tire Storage & Facility List
A listing of facilities registered to accept waste tires.

Date of Government Version: 08/01/2006
Date Data Arrived at EDR: 11/15/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 10/22/2013
Next Scheduled EDR Contact: 02/03/2014
Data Release Frequency: Annually

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US CDL: Clandestine Drug Labs
A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 08/06/2013
Date Data Arrived at EDR: 09/11/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 22

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 09/04/2013
Next Scheduled EDR Contact: 12/16/2013
Data Release Frequency: Quarterly

DEL SHWS: Delisted Registry Sites
A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 11/13/2013
Date Data Arrived at EDR: 11/13/2013
Date Made Active in Reports: 11/18/2013
Number of Days to Update: 5

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 11/13/2013
Next Scheduled EDR Contact: 03/03/2014
Data Release Frequency: Annually

US HIST CDL: National Clandestine Laboratory Register
A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/01/2007
Date Data Arrived at EDR: 11/19/2008
Date Made Active in Reports: 03/30/2009
Number of Days to Update: 131

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 03/23/2009
Next Scheduled EDR Contact: 06/22/2009
Data Release Frequency: No Update Planned

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/06/2013
Date Data Arrived at EDR: 04/25/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 11/13/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 08/19/2013
Date Data Arrived at EDR: 08/20/2013
Date Made Active in Reports: 09/11/2013
Number of Days to Update: 22

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 11/08/2013
Next Scheduled EDR Contact: 02/24/2014
Data Release Frequency: Varies

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/27/2013
Number of Days to Update: 55

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 10/01/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Annually

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 09/25/2013
Date Data Arrived at EDR: 09/26/2013
Date Made Active in Reports: 11/15/2013
Number of Days to Update: 50

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 11/22/2013
Next Scheduled EDR Contact: 03/03/2014
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 07/11/2013
Date Data Arrived at EDR: 08/08/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 36

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 10/02/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Varies

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 08/07/2012
Date Made Active in Reports: 09/18/2012
Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 11/06/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 10/18/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 02/26/2013
Date Made Active in Reports: 03/13/2013
Number of Days to Update: 15

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 09/10/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 06/30/2013
Date Data Arrived at EDR: 08/07/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 57

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 09/30/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 04/26/2013
Date Data Arrived at EDR: 06/11/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 143

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 09/13/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010
Date Data Arrived at EDR: 10/07/2011
Date Made Active in Reports: 03/01/2012
Number of Days to Update: 146

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 11/26/2013
Next Scheduled EDR Contact: 03/10/2014
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 08/01/2013
Date Data Arrived at EDR: 09/05/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 28

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 09/05/2013
Next Scheduled EDR Contact: 12/16/2013
Data Release Frequency: Semi-Annually

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 07/31/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 44

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 11/27/2013
Next Scheduled EDR Contact: 03/10/2014
Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2006
Date Data Arrived at EDR: 09/29/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 64

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 09/24/2013
Next Scheduled EDR Contact: 01/08/2014
Data Release Frequency: Every 4 Years

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 11/21/2013
Next Scheduled EDR Contact: 03/10/2014
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 11/21/2014
Next Scheduled EDR Contact: 03/10/2014
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 07/20/2011
Date Data Arrived at EDR: 11/10/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 61

Source: Environmental Protection Agency
Telephone: 202-564-5088
Last EDR Contact: 10/09/2014
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 06/01/2013
Date Data Arrived at EDR: 07/17/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 107

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 10/18/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 07/22/2013
Date Data Arrived at EDR: 08/02/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 91

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 09/10/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Quarterly

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 09/30/2013
Date Data Arrived at EDR: 10/09/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 23

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 10/09/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 03/08/2013
Date Data Arrived at EDR: 03/21/2013
Date Made Active in Reports: 07/10/2013
Number of Days to Update: 111

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 09/11/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 05/08/2012
Date Data Arrived at EDR: 05/25/2012
Date Made Active in Reports: 07/10/2012
Number of Days to Update: 46

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 02/26/2013
Date Made Active in Reports: 04/19/2013
Number of Days to Update: 52

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 11/25/2013
Next Scheduled EDR Contact: 03/10/2014
Data Release Frequency: Biennially

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 09/10/2013
Date Data Arrived at EDR: 09/12/2013
Date Made Active in Reports: 11/18/2013
Number of Days to Update: 67

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 09/12/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Quarterly

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 11/01/2013
Date Data Arrived at EDR: 11/07/2013
Date Made Active in Reports: 11/18/2013
Number of Days to Update: 11

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 11/07/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Annually

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 10/17/2013
Date Data Arrived at EDR: 10/17/2013
Date Made Active in Reports: 11/14/2013
Number of Days to Update: 28

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 09/16/2013
Next Scheduled EDR Contact: 12/30/2013
Data Release Frequency: Varies

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 07/15/2013
Date Data Arrived at EDR: 07/17/2013
Date Made Active in Reports: 09/09/2013
Number of Days to Update: 54

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 10/10/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AIRS: Air Emissions Data
Point source emissions inventory data.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 08/02/2012
Date Made Active in Reports: 10/03/2012
Number of Days to Update: 62

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING
The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 09/17/2013
Date Data Arrived at EDR: 10/02/2013
Date Made Active in Reports: 11/14/2013
Number of Days to Update: 43

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 09/24/2013
Next Scheduled EDR Contact: 01/08/2014
Data Release Frequency: Varies

INDIAN RESERV: Indian Reservations
This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 12/08/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 34

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 10/18/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Semi-Annually

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing
The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 03/07/2011
Date Data Arrived at EDR: 03/09/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 54

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 11/18/2013
Next Scheduled EDR Contact: 02/03/2014
Data Release Frequency: Varies

US AIRS MINOR: Air Facility System Data
A listing of minor source facilities.

Date of Government Version: 01/23/2013
Date Data Arrived at EDR: 01/30/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-5962
Last EDR Contact: 09/30/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Annually

FEDLAND: Federal and Indian Lands
Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 10/18/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: N/A

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 06/30/2013
Date Data Arrived at EDR: 08/13/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 31

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 11/15/2013
Next Scheduled EDR Contact: 02/24/2014
Data Release Frequency: Quarterly

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 03/04/2013
Date Data Arrived at EDR: 03/15/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 56

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 11/18/2013
Next Scheduled EDR Contact: 03/03/2014
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 11/11/2011
Date Data Arrived at EDR: 05/18/2012
Date Made Active in Reports: 05/25/2012
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 11/15/2013
Next Scheduled EDR Contact: 02/24/2014
Data Release Frequency: Varies

COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 10/08/2013
Date Data Arrived at EDR: 10/09/2013
Date Made Active in Reports: 11/14/2013
Number of Days to Update: 36

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 10/07/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Varies

COAL ASH DOE: Sleam-Electric Plan Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 10/15/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 08/17/2010
Date Data Arrived at EDR: 01/03/2011
Date Made Active in Reports: 03/21/2011
Number of Days to Update: 77
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 09/13/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Varies

Financial Assurance 2: Financial Assurance Information Listing
A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 10/31/2008
Date Data Arrived at EDR: 11/25/2008
Date Made Active in Reports: 12/11/2008
Number of Days to Update: 16
Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 10/07/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 10/15/2013
Date Data Arrived at EDR: 10/16/2013
Date Made Active in Reports: 11/14/2013
Number of Days to Update: 29
Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 10/07/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Quarterly

LEAD SMELTER 1: Lead Smelter Sites
A listing of former lead smelter site locations.

Date of Government Version: 01/29/2013
Date Data Arrived at EDR: 02/14/2013
Date Made Active in Reports: 02/27/2013
Number of Days to Update: 13
Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 09/24/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites
A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36
Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)
The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 01/23/2013
Date Data Arrived at EDR: 01/30/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 100
Source: EPA
Telephone: 202-564-5962
Last EDR Contact: 09/30/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Annually

PRP: Potentially Responsible Parties
A listing of verified Potentially Responsible Parties

Date of Government Version: 04/15/2013
Date Data Arrived at EDR: 07/03/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 72

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 10/04/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Quarterly

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 02/01/2011
Date Data Arrived at EDR: 10/19/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 83

Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 11/01/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR US Hist Auto Stat: EDR Exclusive Historic Gas Stations
EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR US Hist Cleaners: EDR Exclusive Historic Dry Cleaners
EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR US Hist Cleaners: EDR Proprietary Historic Dry Cleaners - Cole

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: N/A
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR US Hist Auto Stat: EDR Proprietary Historic Gas Stations - Cole

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: N/A
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

Cortland County Storage Tank Listing
A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/23/2013
Date Data Arrived at EDR: 08/28/2013
Date Made Active in Reports: 09/12/2013
Number of Days to Update: 15

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Quarterly

Cortland County Storage Tank Listing
A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/23/2013
Date Data Arrived at EDR: 08/28/2013
Date Made Active in Reports: 09/12/2013
Number of Days to Update: 15

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Quarterly

NASSAU COUNTY:

Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 05/21/2003
Date Data Arrived at EDR: 05/27/2003
Date Made Active in Reports: 06/09/2003
Number of Days to Update: 13

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 10/07/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Varies

Registered Tank Database

A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 05/21/2003
Date Data Arrived at EDR: 05/27/2003
Date Made Active in Reports: 06/09/2003
Number of Days to Update: 13

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 10/07/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: No Update Planned

Storage Tank Database

A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Varies

ROCKLAND COUNTY:

Petroleum Bulk Storage Database

A listing of aboveground storage tank sites located in Rockland County.

Date of Government Version: 09/19/2013
Date Data Arrived at EDR: 09/20/2013
Date Made Active in Reports: 11/13/2013
Number of Days to Update: 54

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 09/10/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Quarterly

Petroleum Bulk Storage Database

A listing of underground storage tank sites located in Rockland County.

Date of Government Version: 09/19/2013
Date Data Arrived at EDR: 09/20/2013
Date Made Active in Reports: 11/13/2013
Number of Days to Update: 54

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 09/10/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Quarterly

SUFFOLK COUNTY:

Storage Tank Database

A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 07/08/2013
Date Data Arrived at EDR: 09/10/2013
Date Made Active in Reports: 11/25/2013
Number of Days to Update: 76

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: No Update Planned

Storage Tank Database

A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 07/08/2013
Date Data Arrived at EDR: 09/10/2013
Date Made Active in Reports: 11/25/2013
Number of Days to Update: 76

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 09/11/2013
Date Data Arrived at EDR: 09/12/2013
Date Made Active in Reports: 11/13/2013
Number of Days to Update: 62

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Varies

Listing of Storage Tanks
A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 09/11/2013
Date Data Arrived at EDR: 09/12/2013
Date Made Active in Reports: 11/13/2013
Number of Days to Update: 62

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 07/30/2013
Date Data Arrived at EDR: 08/19/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 45

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 11/22/2013
Next Scheduled EDR Contact: 03/03/2014
Data Release Frequency: Annually

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 07/19/2012
Date Made Active in Reports: 08/28/2012
Number of Days to Update: 40

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 10/18/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 07/24/2013
Date Made Active in Reports: 08/19/2013
Number of Days to Update: 26

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 10/21/2013
Next Scheduled EDR Contact: 02/03/2014
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 06/21/2013
Date Made Active in Reports: 08/05/2013
Number of Days to Update: 45

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 11/25/2013
Next Scheduled EDR Contact: 03/10/2014
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 05/01/2013
Date Data Arrived at EDR: 08/14/2013
Date Made Active in Reports: 09/20/2013
Number of Days to Update: 37

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 10/21/2013
Next Scheduled EDR Contact: 02/03/2014
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 08/09/2013
Date Made Active in Reports: 09/27/2013
Number of Days to Update: 49

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 09/16/2013
Next Scheduled EDR Contact: 12/30/2013
Data Release Frequency: Annually

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data
Source: Rextag Strategies Corp.
Telephone: (281) 769-2247
U.S. Electric Transmission and Power Plants Systems Digital GIS Data

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

27-21 44TH DRIVE AND 44-18 PURVES STREET
44-18 PURVES STREET
LONG ISLAND CITY, NY 11101

TARGET PROPERTY COORDINATES

Latitude (North):	40.7467 - 40° 44' 48.12''
Longitude (West):	73.9415 - 73° 56' 29.40''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	589364.6
UTM Y (Meters):	4510966.5
Elevation:	14 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	40073-F8 BROOKLYN, NY
Most Recent Revision:	1995
North Map:	40073-G8 CENTRAL PARK, NY NJ
Most Recent Revision:	1995

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principal investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General SSW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 14 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County	FEMA Flood Electronic Data
QUEENS, NY	YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property: 360497 - FEMA DFIRM Flood data

Additional Panels in search area:
3604970032B - FEMA Q3 Flood data
3604970040B - FEMA Q3 Flood data
3604970039B - FEMA Q3 Flood data
3604970048B - FEMA Q3 Flood data
3604970047B - FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
BROOKLYN	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius: 1.25 miles
Status: Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site-specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Paleozoic
System:	Ordovician
Series:	Ordovician
Code:	Oe *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Eugeosynclinal Deposits

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	USGS40000831273	0 - 1/8 Mile WSW
2	USGS40000831198	1/8 - 1/4 Mile ESE
3	USGS40000831141	1/4 - 1/2 Mile SW
4	USGS40000831282	1/4 - 1/2 Mile West
5	USGS40000831481	1/4 - 1/2 Mile NNW
6	USGS40000831487	1/4 - 1/2 Mile NNE
7	USGS40000831118	1/4 - 1/2 Mile SE
8	USGS40000831434	1/4 - 1/2 Mile ENE
9	USGS40000831211	1/4 - 1/2 Mile ESE
A10	USGS40000830996	1/4 - 1/2 Mile SSE
A11	USGS40000830959	1/2 - 1 Mile SSE
12	USGS40000831006	1/2 - 1 Mile SW
13	USGS40000831119	1/2 - 1 Mile WSW
14	USGS40000831512	1/2 - 1 Mile NE
15	USGS40000831012	1/2 - 1 Mile SE
16	USGS40000831272	1/2 - 1 Mile East
17	USGS40000831480	1/2 - 1 Mile ENE
18	USGS40000831691	1/2 - 1 Mile North
19	USGS40000830940	1/2 - 1 Mile SW
20	USGS40000831488	1/2 - 1 Mile WNW
21	USGS40000831511	1/2 - 1 Mile NE
22	USGS40000831605	1/2 - 1 Mile NE
23	USGS40000831744	1/2 - 1 Mile North
24	USGS40000831177	1/2 - 1 Mile West
25	USGS40000831755	1/2 - 1 Mile NNE
26	USGS40000830700	1/2 - 1 Mile SSW
B27	USGS40000831271	1/2 - 1 Mile East
B28	USGS40000831231	1/2 - 1 Mile East
29	USGS40000831669	1/2 - 1 Mile NE
C30	USGS40000831319	1/2 - 1 Mile East
31	USGS40000831796	1/2 - 1 Mile NNW
32	USGS40000831165	1/2 - 1 Mile ESE
33	USGS40000831093	1/2 - 1 Mile ESE
C34	USGS40000831350	1/2 - 1 Mile East
35	USGS40000830776	1/2 - 1 Mile SW
36	USGS40000830981	1/2 - 1 Mile ESE
37	USGS40000831048	1/2 - 1 Mile WSW
38	USGS40000831882	1/2 - 1 Mile North
39	USGS40000830559	1/2 - 1 Mile South
40	USGS40000831496	1/2 - 1 Mile ENE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

PHYSICAL SETTING SOURCE MAP - 3798265.2s



- County Boundary
- Major Roads
- Contour Lines
- Airports
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME: 27-21 44th Drive and 44-18 Purves Street ADDRESS: 44-18 Purves Street Long Island City NY 11101 LAT/LONG: 40.7467 / 73.9415	CLIENT: Langan Engineering, Inc. CONTACT: Jessica Alzamora INQUIRY #: 3798265.2s DATE: December 02, 2013 10:59 am

Copyright © 2013 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
WSW **FED USGS** **USGS40000831273**
0 - 1/8 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404446073563501		
Monloc name:	Q 1738. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.746213
Longitude:	-73.9426378	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	15.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	146
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

2
ESE **FED USGS** **USGS40000831198**
1/8 - 1/4 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404442073561801		
Monloc name:	Q 171. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7451019
Longitude:	-73.9379154	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	46.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	500
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

3
SW **FED USGS** **USGS40000831141**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404437073564201		
Monloc name:	Q 398. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.743713
Longitude:	-73.9445823	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	2.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	67
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

4
West **FED USGS** **USGS40000831282**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404447073565301		
Monloc name:	Q 399. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7464907
Longitude:	-73.9476379	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	13.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	68
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

5
NNW **FED USGS** **USGS40000831481**
1/4 - 1/2 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404506073564201		
Monloc name:	Q 962. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7517684
Longitude:	-73.9445823	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	20.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	195
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

6
NNE **FED USGS** **USGS40000831487**
1/4 - 1/2 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404507073552001		
Monloc name:	Q 2721. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030101	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7520462
Longitude:	-73.938471	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	35.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	300
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

7
SE **FED USGS** **USGS40000831118**
1/4 - 1/2 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404435073560801		
Monloc name:	Q 1632. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7431575
Longitude:	-73.9351376	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	18.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	63
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

8
ENE **FED USGS** **USGS40000831434**
1/4 - 1/2 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404500073560601		
Monloc name:	Q 2445. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7501018
Longitude:	-73.934582	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	26.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	110
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

9
ESE **FED USGS** **USGS40000831211**
1/4 - 1/2 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404443073560101		
Monloc name:	Q 2333. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7453797
Longitude:	-73.9331931	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	25.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	37
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

A10
SSE **FED USGS** **USGS40000830996**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404426073561401		
Monloc name:	Q 1502. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7406576
Longitude:	-73.9368043	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	15.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	93
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

A11
SSE **FED USGS** **USGS40000830959**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404424073561501		
Monloc name:	Q 1638. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.740102
Longitude:	-73.9370821	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	13.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	73
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

12
SW **FED USGS** **USGS40000831006**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404427073565601		
Monloc name:	Q 17. 1		
Monloc type:	Well		
Monloc desc:	5601		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7409353
Longitude:	-73.9484713	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	17.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	175
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

13
WSW **FED USGS** **USGS40000831119**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404435073570601		
Monloc name:	Q 423. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7431575
Longitude:	-73.9512492	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	17.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	69
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

14
NE **FED USGS** **USGS40000831512**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404510073560402		
Monloc name:	Q 3122. 2		
Monloc type:	Well		
Monloc desc:	LAT/LONG UPDATES FROM SIM 3066		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7528889
Longitude:	-73.934	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from Digital Map		
Horiz coord refsys:	NAD83	Vert measure val:	43
Vert measure units:	feet	Vertacc measure val:	1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Northern Atlantic Coastal Plain aquifer system		
Formation type:	Glacial Aquifer, Upper		

Aquifer type:	Unconfined single aquifer		
Construction date:	20000614	Welldepth:	55
Welldepth units:	ft	Wellholedepth:	55
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 54

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-23		14.42	2004-12-17		14.55
2004-11-17		14.54	2004-10-26		14.52
2004-09-22		14.49	2004-08-24		14.35
2004-07-22		14.13	2004-06-23		14.03
2004-05-25		14.13	2004-04-29		14.10
2004-03-17		14.12	2004-02-25		14.21
2003-12-29		14.24	2003-11-26		14.13
2003-10-30		14.14	2003-09-26		14.23
2003-08-28		14.26	2003-07-30		14.13
2003-06-26		14.16	2003-05-28		13.85
2003-04-24		13.78	2003-03-19		13.57
2003-02-26		13.54	2003-01-30		13.38
2002-12-23		13.35	2002-11-22		13.32
2002-10-23		13.10	2002-09-24		12.84
2002-08-28		12.70	2002-07-18		12.76
2002-06-26		12.80	2002-05-30		12.78
2002-04-26		12.72	2002-03-19		12.90
2002-02-26		13.05	2002-01-29		13.20
2001-12-27		13.45	2001-11-20		13.83
2001-10-23		14.58	2001-09-25		15.36
2001-08-22		15.17	2001-07-25		15.02
2001-06-27		15.06	2001-05-23		14.75
2001-04-24		14.44	2001-03-19		14.03
2001-02-26		13.78	2001-01-31		13.48
2000-12-20		12.91	2000-11-29		12.89
2000-10-24		13.00	2000-09-27		12.86
2000-08-28		12.82	2000-07-24		12.56

15
SE
1/2 - 1 Mile
Higher

FED USGS **USGS40000831012**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404428073555701		
Monloc name:	Q 122. 1		
Monloc type:	Well		
Monloc desc:	5701		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7412131
Longitude:	-73.9320819	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	42.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	125
Welldepth units:	ft	Wellholedepth:	140
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

16
East **FED USGS** **USGS40000831272**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404446073554701		
Monloc name:	Q 1258. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.746213
Longitude:	-73.9293041	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	55.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	63
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

17
ENE **FED USGS** **USGS40000831480**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404506073555401		
Monloc name:	Q 13. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7517685
Longitude:	-73.9312486	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	24.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	89
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

18
North **FED USGS** **USGS40000831691**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404522073562401		
Monloc name:	Q 1221. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7562128
Longitude:	-73.9395821	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	17.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	178
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

19
SW **FED USGS** **USGS40000830940**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404422073570401		
Monloc name:	Q 395. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7395464
Longitude:	-73.9506936	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	7.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	74
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

20
WNW **FED USGS** **USGS40000831488**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404507073571101		
Monloc name:	Q 161. 1		
Monloc type:	Well		
Monloc desc:	1101		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7520462
Longitude:	-73.9526381	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	5.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	228
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

21
NE **FED USGS** **USGS40000831511**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404510073555301		
Monloc name:	Q 1635. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7528796
Longitude:	-73.9309708	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	3.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	40
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

22
NE **FED USGS** **USGS40000831605**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404516073560001		
Monloc name:	Q 1912. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7545462
Longitude:	-73.9329153	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	40.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	400
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

23
North **FED USGS** **USGS40000831744**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404525073564001		
Monloc name:	Q 1272. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7570461
Longitude:	-73.9440267	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	195
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

24
West **FED USGS** **USGS40000831177**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404440073572401		
Monloc name:	Q 966. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7445463
Longitude:	-73.9562493	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	8.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	200
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

25
NNE **FED USGS** **USGS40000831755**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404526073561101		
Monloc name:	Q 95. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7573239
Longitude:	-73.9359709	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	20.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	92
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

26
SSW **FED USGS** **USGS40000830700**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404407073564401		
Monloc name:	K 692. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7353799
Longitude:	-73.9451379	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	3.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	88
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

B27
East **FED USGS** **USGS40000831271**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404446073553501		
Monloc name:	Q 453. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.746213
Longitude:	-73.9259706	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	68.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	147
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

B28
East **FED USGS** **USGS40000831231**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404444073553501		
Monloc name:	Q 425. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7456575
Longitude:	-73.9259706	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	75.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	159
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

29
NE **FED USGS** **USGS40000831669**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404520073555301		
Monloc name:	Q 1246. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7556573
Longitude:	-73.9309708	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	42.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	220
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

C30
East **FED USGS** **USGS40000831319**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404451073553401		
Monloc name:	Q 386. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7476019
Longitude:	-73.9256929	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	75.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	222
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

31
NNW **FED USGS** **USGS40000831796**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404529073564901		
Monloc name:	Q 165. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7581572
Longitude:	-73.9465268	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	5.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	205
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

32
ESE **FED USGS** **USGS40000831165**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404439073553401		
Monloc name:	Q 1098. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7442686
Longitude:	-73.9256929	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	72.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	215
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

33
ESE **FED USGS** **USGS40000831093**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404433073553601		
Monloc name:	Q 388. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.742602
Longitude:	-73.9262484	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	70.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	203
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

C34
East
1/2 - 1 Mile
Higher

FED USGS **USGS40000831350**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404453073553301		
Monloc name:	Q 602. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7481574
Longitude:	-73.9254151	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	50.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	159
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

35
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000830776**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404411073570601		
Monloc name:	K 465. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7364909
Longitude:	-73.9512491	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	400
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

36
ESE **FED USGS** **USGS40000830981**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404425073553901		
Monloc name:	Q 387. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7403798
Longitude:	-73.9270818	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	64.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	176
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

37
WSW **FED USGS** **USGS40000831048**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404430073572801		
Monloc name:	Q 422. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7417686
Longitude:	-73.9573604	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	7.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	66
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

38
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000831882**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404536073562601		
Monloc name:	Q 954. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7601016
Longitude:	-73.9401377	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	12.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	301
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

39
South
1/2 - 1 Mile
Lower

FED USGS **USGS40000830559**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404359073562801		
Monloc name:	K 711. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7331577
Longitude:	-73.9406933	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	Not Reported
Vert measure units:	Not Reported	Vertacc measure val:	Not Reported
Vert accmeasure units:	Not Reported		
Vertcollection method:	Not Reported		
Vert coord refsys:	Not Reported	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	74
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

40
ENE **FED USGS** **USGS40000831496**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404508073552901		
Monloc name:	Q 389. 1		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030201	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.752324
Longitude:	-73.9243039	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	35.0
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	84
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for QUEENS County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for QUEENS COUNTY, NY

Number of sites tested: 81

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.620 pCi/L	97%	0%	3%
Basement	0.970 pCi/L	93%	6%	1%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX E- FREEDOM OF INFORMATION ACT REQUESTS

LANGAN
ENGINEERING & ENVIRONMENTAL SERVICES

Technical Excellence
Practical Experience
Client Responsiveness

December 3, 2013

New York State Department of Health
Attn: Record Access Officer
Corning Tower, Room 2348
Albany, NY 12237

Re: Freedom of Information Request
27-21 44th Drive and 44-18 Purves Street
Long Island City, New York
Block 268, Lots 4, 22, and 23
Langan Project No.: 170281401

Dear Sir or Madam:

Pursuant to the Federal Freedom of Information Act (5 U.S.C 552 et seq.) dealing with the examination and duplication of documents maintained by public agencies, Langan is requesting any information or copies of files regarding environmental conditions on the above property, such as environmental permits, notices of violations, spill/discharge incidents, storage or disposal of hazardous substances, Underground Storage Tanks (USTs), Leaking Underground Storage Tanks (LTANKs), asbestos abatement, and any other environmental reports that your department may have.

The subject property includes 27-19 through 27-27 44th Drive (Block 268, Lot 4), and 44-18 through 44-22 Purves Drive (Block 268 Lots 22 and 23) in Long Island City, New York and is bounded by 27-19 44th Drive and 44-12 through 44-16 Purves Street (Block 268, Lot 8) to the north, Purves Street to the east, 44th Drive to the west, and 27-33 44th Drive (Block 268, Lot 1) and 44-24 through 44-28 Purves Street (Block 268, Lots 24 and 25) to the south.

Please contact me at 212-479-5487 with any questions or send your response to my attention at jalzamora@langan.com or at the below address:

Langan Engineering and Environmental Services, P.C.
21 Penn Plaza
360 West 31st Street, 8th floor
New York, New York 10001-2727

Thank you in advance for your cooperation.

Sincerely,
Langan Engineering and Environmental Services, Inc. PC

Jessica Alzamora

Jessica Alzamora
Senior Staff Engineer

LANGAN
ENGINEERING & ENVIRONMENTAL SERVICES

Technical Excellence
Practical Experience
Client Responsiveness

December 3, 2013

Rene Bryant
New York City Department of Health
125 Worth Street
Box 31C
New York, NY 10013

Re: Freedom of Information Request
27-21 44th Drive and 44-18 Purves Street
Long Island City, New York
Block 268, Lots 4, 22, and 23
Langan Project No.: 170281401

Dear Sir or Madam:

Pursuant to the Federal Freedom of Information Act (5 U.S.C 552 et seq.) dealing with the examination and duplication of documents maintained by public agencies, Langan is requesting any information or copies of files regarding environmental conditions on the above property, such as environmental permits, notices of violations, spill/discharge incidents, storage or disposal of hazardous substances, Underground Storage Tanks (USTs), Leaking Underground Storage Tanks (LTANKs), asbestos abatement, and any other environmental reports that your department may have.

The subject property includes 27-19 through 27-27 44th Drive (Block 268, Lot 4), and 44-18 through 44-22 Purves Drive (Block 268 Lots 22 and 23) in Long Island City, New York and is bounded by 27-19 44th Drive and 44-12 through 44-16 Purves Street (Block 268, Lot 8) to the north, Purves Street to the east, 44th Drive to the west, and 27-33 44th Drive (Block 268, Lot 1) and 44-24 through 44-28 Purves Street (Block 268, Lots 24 and 25) to the south.

Please contact me at 212-479-5487 with any questions or send your response to my attention at jalzamora@langan.com or at the below address:

Langan Engineering and Environmental Services, P.C.
21 Penn Plaza
360 West 31st Street, 8th floor
New York, New York 10001-2727

Thank you in advance for your cooperation.

Sincerely,
Langan Engineering and Environmental Services, Inc. PC

Jessica Alzamora

Jessica Alzamora
Senior Staff Engineer

LANGAN
ENGINEERING & ENVIRONMENTAL SERVICES

Technical Excellence
Practical Experience
Client Responsiveness

December 3, 2013

Attn: Records Access Officer
New York City Department of Environmental Protection
Bureau of Legal Affairs
59-17 Junction Boulevard, 19th Floor
Corona, New York 11368

Re: Freedom of Information Request
27-21 44th Drive and 44-18 Purves Street
Long Island City, New York
Block 268, Lots 4, 22, and 23
Langan Project No.: 170281401

Dear Sir or Madam:

Pursuant to the Federal Freedom of Information Act (5 U.S.C 552 et seq.) dealing with the examination and duplication of documents maintained by public agencies, Langan is requesting any information or copies of files regarding environmental conditions on the above property, such as environmental permits, notices of violations, spill/discharge incidents, storage or disposal of hazardous substances, Underground Storage Tanks (USTs), Leaking Underground Storage Tanks (LTANKs), asbestos abatement, and any other environmental reports that your department may have.

The subject property includes 27-19 through 27-27 44th Drive (Block 268, Lot 4), and 44-18 through 44-22 Purves Drive (Block 268 Lots 22 and 23) in Long Island City, New York and is bounded by 27-19 44th Drive and 44-12 through 44-16 Purves Street (Block 268, Lot 8) to the north, Purves Street to the east, 44th Drive to the west, and 27-33 44th Drive (Block 268, Lot 1) and 44-24 through 44-28 Purves Street (Block 268, Lots 24 and 25) to the south.

Please contact me at 212-479-5487 with any questions or send your response to my attention at jalzamora@langan.com or at the below address:

Langan Engineering and Environmental Services, P.C.
21 Penn Plaza
360 West 31st Street, 8th floor
New York, New York 10001-2727

Thank you in advance for your cooperation.

Sincerely,
Langan Engineering and Environmental Services, Inc. PC

Jessica Alzamora

Jessica Alzamora
Senior Staff Engineer

December 3, 2013

Fire Department, City of New York
Bureau of Revenue Management
9 MetroTech East
Brooklyn, New York 11201-3857

Re: Freedom of Information Request
27-21 44th Drive and 44-18 Purves Street
Long Island City, New York
Block 268, Lots 4, 22, and 23
Langan Project No.: 170281401

Dear Sir or Madam:

Pursuant to the Federal Freedom of Information Act (5 U.S.C 552 et seq.) dealing with the examination and duplication of documents maintained by public agencies, Langan is requesting any information or copies of files regarding environmental conditions on the above property, such as environmental permits, notices of violations, spill/discharge incidents, storage or disposal of hazardous substances, Underground Storage Tanks (USTs), Leaking Underground Storage Tanks (LTANKs), asbestos abatement, and any other environmental reports that your department may have.

The subject property includes 27-19 through 27-27 44th Drive (Block 268, Lot 4), and 44-18 through 44-22 Purves Drive (Block 268 Lots 22 and 23) in Long Island City, New York and is bounded by 27-19 44th Drive and 44-12 through 44-16 Purves Street (Block 268, Lot 8) to the north, Purves Street to the east, 44th Drive to the west, and 27-33 44th Drive (Block 268, Lot 1) and 44-24 through 44-28 Purves Street (Block 268, Lots 24 and 25) to the south.

Please contact me at 212-479-5487 with any questions or send your response to my attention at jalzamora@langan.com or at the below address:

Langan Engineering and Environmental Services, P.C.
21 Penn Plaza
360 West 31st Street, 8th floor
New York, New York 10001-2727

Thank you in advance for your cooperation.

Sincerely,
Langan Engineering and Environmental Services, Inc. PC

Jessica Alzamora

Jessica Alzamora
Senior Staff Engineer

Request Confirmation

Request Information

Tracking Number : *EPA-R2-2014-001566*

Requester Name : Mrs. Jessica Alzamora

Date Submitted : 12/03/2013

Request Status : Submitted

Description :

The subject property includes 27-19 through 27-27 44th Drive (Block 268, Lot 4), and 44-18 through 44-22 Purves Drive (Block 268 Lots 22 and 23) in Long Island City, New York and is bounded by 27-19 44th Drive and 44-12 through 44-16 Purves Street (Block 268, Lot 8) to the north, Purves Street to the east, 44th Drive to the west, and 27-33 44th Drive (Block 268, Lot 1) and 44-24 through 44-28 Purves Street (Block 268, Lots 24 and 25) to the south.

You created this PDF from an application that is not licensed to print to novaPDF printer (http://www.novapdf.com) /3/2013

APPENDIX F- NEW YORK CITY DEPARTMENT OF BUILDING RECORDS

THE CITY OF NEW YORK

BUREAU OF BUILDINGS

BOROUGH OF QUEENS

No. 19225

CERTIFICATE OF OCCUPANCY

ISSUED 8/20/25 192 TO Nelson Bros of

PREMISES Nott Ave E.O. 59 & Thomson Ave

in accordance with Chapter 503, Laws of 1916 and Section 5, Art. 1, Chapter 5 of the Code of Ordinances, City of New York.

THIS CERTIFIES that the NEW BUILDING situated on the above mentioned premises has been completed and conforms substantially to the approved plans and specifications, and to the requirements of all Laws, Ordinances and Rules and Regulations of the Board of Standards and Appeals applicable thereto, and permission is hereby granted for its occupancy for the purpose specified below:

Stories	Classification	Construction
1	Garage & Factory	Brick

Floors	Occupancy	Live Load Per Sq. Ft. in Pounds	Number of Persons
Cellar			
Basement			
1st Floor	Garage & Factory		
2nd Floor			
3rd Floor			
4th Floor			
5th Floor			
6th Floor			

B. Application 16978/24 192

John Murray
Superintendent of Buildings
Borough of Queens

CERTIFICATE OF CONFORMITY

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

44-18 PURVIS STREET — **QUEENS 11101** — **BIN# 4003510**

PURVES STREET 44-18 - 44-18

Health Area	: 720	**Tax Block**	: 268
Census Tract	: 19	**Tax Lot**	: 22
Community Board	: 402	**Condo**	: NO
Buildings on Lot	: 1	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	JACKSON AVENUE, DEAD END		
DOB Special Place Name:			
DOB Building Remarks:	NEW ADDRESS 28-23 THOMSON AVE. LTS. MERGE		
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Little 'E' Restricted:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	NO
Additional BINs for Building:	NONE		

Special District: LIC - LONG ISLAND CITY MIXED USE

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, or Coastal Erosion Hazard Area. Click here for more information

Department of Finance Building Classification: V1-VACANT LAND

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	2	0
Violations-DOB	2	0
Violations-ECB (DOB)	0	0
Jobs/Filings	1	
ARA / LAA Jobs	1	
Total Jobs	2	
Actions	28	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

27-21 44 DRIVE — **QUEENS 11101** — **BIN# 4003505**

44 DRIVE 27-21 - 27-21

Health Area	: 720	**Tax Block**	: 268
Census Tract	: 19	**Tax Lot**	: 4
Community Board	: 402	**Condo**	: NO
Buildings on Lot	: 1	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	JACKSON AVENUE, THOMSON AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Little 'E' Restricted:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	NO
Additional BINs for Building:	NONE		

Special District: LIC - LONG ISLAND CITY MIXED USE

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, or Coastal Erosion Hazard Area. Click here for more information

Department of Finance Building Classification: G2-GARAGE/GAS STAT'N

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	2	0
Violations-ECB (DOB)	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	21	

OR Enter Action Type:

OR Select from List:


Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

APPENDIX G- NEW YORK CITY PLANNING COMMISSION ZONNING MAP



C1-1 C1-2 C1-3 C1-4 C1-5 C2-1 C2-2 C2-3 C2-4 C2-5

NOTE: Where no dimensions for zoning district boundaries appear on the zoning maps, such dimensions are determined in Article VII, Chapter 8 (Location of District Boundaries) of the Zoning Resolution.

ZONING MAP

THE NEW YORK CITY PLANNING COMMISSION

Major Zoning Classifications:

The number(s) and/or letter(s) that follows an **R**, **C** or **M** District designation indicates use, bulk and other controls as described in the text of the Zoning Resolution.

R – RESIDENTIAL DISTRICT

C – COMMERCIAL DISTRICT

M – MANUFACTURING DISTRICT

SPECIAL PURPOSE DISTRICT
The letter(s) within the shaded area designates the special purpose district as described in the text of the Zoning Resolution.

AREA(S) REZONED

Effective Date(s) of Rezoning:

05-08-2013 C 130076 ZMM

Special Requirements:

For a list of lots subject to CEQR environmental requirements, see APPENDIX C.

For a list of lots subject to "D" restrictive declarations, see APPENDIX D.

For Inclusionary Housing designated areas on this map, see APPENDIX F.

CITY MAP CHANGE(S):

▲ 10-12-2013 C 130007 MMM

N

MAP KEY

8c	9a	9c
8d	**9b**	9d
12c	13a	13c

© Copyrighted by the City of New York

NOTE: Zoning information as shown on this map is subject to change. For the most up-to-date zoning information for this map, visit the Zoning section of the Department of City Planning website: **www.nyc.gov/planning** or contact the Zoning Information Desk at (212) 720-3291.

ZONING MAP **9b**

APPENDIX H- AERIAL PHOTOGRAPHS

27-21 44th Drive and 44-18 Purves Street
44-18 Purves Street
Long Island City, NY 11101

Inquiry Number: 3798265.5
December 02, 2013

The EDR Aerial Photo Decade Package

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Date EDR Searched Historical Sources:

Aerial Photography December 02, 2013

Target Property:

44-18 Purves Street

Long Island City, NY 11101

Year	*Scale*	*Details*	*Source*
1924	Aerial Photograph. Scale: 1"=500'	Panel #: 40073-F8, Brooklyn, NY;/Flight Date: January 01, 1924	EDR
1941	Aerial Photograph. Scale: 1"=500'	Panel #: 40073-F8, Brooklyn, NY;/Flight Date: January 01, 1941	EDR
1954	Aerial Photograph. Scale: 1"=500'	Panel #: 40073-F8, Brooklyn, NY;/Flight Date: February 23, 1954	EDR
1966	Aerial Photograph. Scale: 1"=500'	Panel #: 40073-F8, Brooklyn, NY;/Flight Date: February 23, 1966	EDR
1975	Aerial Photograph. Scale: 1"=500'	Panel #: 40073-F8, Brooklyn, NY;/Flight Date: April 01, 1975	EDR
1984	Aerial Photograph. Scale: 1"=500'	Panel #: 40073-F8, Brooklyn, NY;/Flight Date: January 01, 1984	EDR
1994	Aerial Photograph. Scale: 1"=500'	Panel #: 40073-F8, Brooklyn, NY;/Flight Date: January 01, 1994	EDR
1995	Aerial Photograph. Scale: 1"=500'	Panel #: 40073-F8, Brooklyn, NY;/DOQQ - acquisition dates: March 13, 1995	EDR
2006	Aerial Photograph. Scale: 1"=500'	Panel #: 40073-F8, Brooklyn, NY;/Flight Year: 2006	EDR
2008	Aerial Photograph. Scale: 1"=500'	Panel #: 40073-F8, Brooklyn, NY;/Flight Year: 2008	EDR
2009	Aerial Photograph. Scale: 1"=500'	Panel #: 40073-F8, Brooklyn, NY;/Flight Year: 2009	EDR
2011	Aerial Photograph. Scale: 1"=500'	Panel #: 40073-F8, Brooklyn, NY;/Flight Year: 2011	EDR



INQUIRY #: 3798265.5

YEAR: 1924

= 500'

N


INQUIRY #: 3798265.5
YEAR: 1941
= 500'
N


INQUIRY #: 3798265.5
YEAR: 1954
= 500'
N


INQUIRY #: 3798265.5
YEAR: 1966
= 500'
N



INQUIRY #: 3798265.5

YEAR: 1975

= 500'

N


INQUIRY #: 3798265.5
YEAR: 1984
= 500'
N



INQUIRY #: 3798265.5

YEAR: 1994

= 500'

N


INQUIRY #: 3798265.5
YEAR: 1995
= 500'
N


INQUIRY #: 3798265.5
YEAR: 2006
= 500'
N




INQUIRY #: 3798265.5

YEAR: 2008

= 500'

N


INQUIRY #: 3798265.5
YEAR: 2009
= 500'
N


INQUIRY #: 3798265.5
YEAR: 2011
= 500'
N

APPENDIX I- SANBORN FIRE INSURANCE MAPS

27-21 44th Drive and 44-18 Purves Street
44-18 Purves Street
Long Island City, NY 11101

Inquiry Number: 3798265.3
December 02, 2013

Certified Sanborn® Map Report

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

12/02/13

Site Name:
27-21 44th Drive and 44-18
44-18 Purves Street
Long Island City, NY 11101

Client Name:
Langan Engineering, Inc.
360 W. 31st Street
New York, NY 10001

EDR Inquiry # 3798265.3

Contact: Jessica Alzamora

EDR® Environmental Data Resources Inc

The complete Sanborn Library collection has been searched by EDR, and fire insurance maps covering the target property location provided by Langan Engineering, Inc. were identified for the years listed below. The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by Sanborn Library LLC, the copyright holder for the collection.

Certified Sanborn Results:

Site Name: 27-21 44th Drive and 44-18 Purves Street
Address: 44-18 Purves Street
City, State, Zip: Long Island City, NY 11101
Cross Street:
P.O. # 170281401
Project: 27-21 44th Drive
Certification # D3A8-4CA6-9D89

Maps Provided:

2006	1999	1991	1980	1936
2005	1996	1990	1979	1915
2004	1995	1989	1977	1898
2003	1994	1988	1970	
2002	1993	1986	1950	
2001	1992	1985	1947	

Sanborn® Library search results
Certification # D3A8-4CA6-9D89

The Sanborn Library includes more than 1.2 million Sanborn fire insurance maps, which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ✓ Library of Congress
- ✓ University Publications of America
- ✓ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Langan Engineering, Inc. (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


Sanborn Sheet Thumbnails

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.


2006 Source Sheets




Volume 1, Sheet 24



Volume 1, Sheet 25



Volume 1, Sheet 26




Volume 1, Sheet 28


2005 Source Sheets



Volume 1, Sheet 24



Volume 1, Sheet 25



Volume 1, Sheet 26


2004 Source Sheets



Volume 1, Sheet 24



Volume 1, Sheet 25



Volume 1, Sheet 26


2003 Source Sheets




Volume 1, Sheet 24



Volume 1, Sheet 25



Volume 1, Sheet 26



Volume 1, Sheet 28


2002 Source Sheets




Volume 1, Sheet 24



Volume 1, Sheet 25



Volume 1, Sheet 26



Volume 1, Sheet 28


2001 Source Sheets




Volume 1, Sheet 24



Volume 1, Sheet 25



Volume 1, Sheet 26



Volume 1, Sheet 28


1999 Source Sheets




Volume 1, Sheet 24



Volume 1, Sheet 25



Volume 1, Sheet 26



Volume 1, Sheet 28

1996 Source Sheets



Volume 1, Sheet 24



Volume 1, Sheet 25



Volume 1, Sheet 26

1995 Source Sheets



Volume 1, Sheet 24



Volume 1, Sheet 25



Volume 1, Sheet 26



Volume 1, Sheet 28

1994 Source Sheets



Volume 1, Sheet 24



Volume 1, Sheet 25



Volume 1, Sheet 26


1993 Source Sheets



Volume 1, Sheet 24



Volume 1, Sheet 25



Volume 1, Sheet 26

1992 Source Sheets



Volume 1, Sheet 24



Volume 1, Sheet 25



Volume 1, Sheet 26

1991 Source Sheets



Volume 1, Sheet 24




Volume 1, Sheet 25




Volume 1, Sheet 26

1990 Source Sheets



Volume 1, Sheet 26



Volume 1, Sheet 25



Volume 1, Sheet 24


1989 Source Sheets



Volume 1, Sheet 26



Volume 1, Sheet 25



Volume 1, Sheet 24

1988 Source Sheets



Volume 1, Sheet 28



Volume 1, Sheet 26




Volume 1, Sheet 25




Volume 1, Sheet 24

1986 Source Sheets



Volume 1, Sheet 28



Volume 1, Sheet 26




Volume 1, Sheet 25




Volume 1, Sheet 24

1985 Source Sheets



Volume 1, Sheet 25



Volume 1, Sheet 24



Volume 1, Sheet 26

1980 Source Sheets



Volume 1, Sheet 24




Volume 1, Sheet 25



Volume 1, Sheet 26

1979 Source Sheets



Volume 1, Sheet 26



Volume 1, Sheet 25



Volume 1, Sheet 24


1977 Source Sheets




Volume 1, Sheet 25



Volume 1, Sheet 26




Volume 1, Sheet 28



Volume 1, Sheet 24


1970 Source Sheets



Volume 1, Sheet 26



Volume 1, Sheet 25



Volume 1, Sheet 24

1950 Source Sheets



Volume 1, Sheet 24



Volume 1, Sheet 25



Volume 1, Sheet 26

1947 Source Sheets



Volume 1, Sheet 24



Volume 1, Sheet 25



Volume 1, Sheet 26


1936 Source Sheets



Volume 1, Sheet 24



Volume 1, Sheet 25



Volume 1, Sheet 26

1915 Source Sheets




Volume 1, Sheet 24



Volume 1, Sheet 25



Volume 1, Sheet 26



Volume 1, Sheet 28

1898 Source Sheets



Volume 1, Sheet 24




Volume 1, Sheet 25



Volume 1, Sheet 26

2006 Certified Sanborn Map



Certification # D3A8-4CA6-9D89


Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	2006

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600






Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26
Volume 1, Sheet 28

N

2005 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	2005

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600






Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26

N

2004 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	2004

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26

N

2003 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	2003

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26
Volume 1, Sheet 28

0 Feet 150 300 600

N

2002 Certified Sanborn Map



Certification # D3A8-4CA6-9D89


Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	2002

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26
Volume 1, Sheet 28

N

2001 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	2001

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600






Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26
Volume 1, Sheet 28

N

1999 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	1999

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26
Volume 1, Sheet 28

N

1996 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name: 27-21 44th Drive and 44-18 Purves Street
Address: 44-18 Purves Street
City, ST, ZIP: Long Island City NY 11101
Client: Langan Engineering, Inc.
EDR Inquiry: 3798265.3
Order Date: 12/2/2013 12:04:02 PM
Certification # D3A8-4CA6-9D89
Copyright: 1996

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26

N

1995 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name: 27-21 44th Drive and 44-18 Purves Street
Address: 44-18 Purves Street
City, ST, ZIP: Long Island City NY 11101
Client: Langan Engineering, Inc.
EDR Inquiry: 3798265.3
Order Date: 12/2/2013 12:04:02 PM
Certification # D3A8-4CA6-9D89
Copyright: 1995

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26
Volume 1, Sheet 28

N

1994 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	1994

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26

N

1993 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	1993

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26

N

1992 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	1992

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26

0 Feet 150 300 600

N

1991 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	1991

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26

N

1990 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	1990

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 26
Volume 1, Sheet 25
Volume 1, Sheet 24

N

1989 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	1989

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 26
Volume 1, Sheet 25
Volume 1, Sheet 24

N

1988 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	1988

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 28
Volume 1, Sheet 26
Volume 1, Sheet 25
Volume 1, Sheet 24

N

1986 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	1986

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 28
Volume 1, Sheet 26
Volume 1, Sheet 25
Volume 1, Sheet 24

N

1985 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	1985

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 25
Volume 1, Sheet 24
Volume 1, Sheet 26

0 Feet 150 300 600

N

1980 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	1980

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26

N

1979 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	1979

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 26
Volume 1, Sheet 25
Volume 1, Sheet 24

N

1977 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D3A8-4CA6-9D89

Site Name: 27-21 44th Drive and 44-18 Purves Street
Address: 44-18 Purves Street
City, ST, ZIP: Long Island City NY 11101
Client: Langan Engineering, Inc.
EDR Inquiry: 3798265.3
Order Date: 12/2/2013 12:04:02 PM
Certification # D3A8-4CA6-9D89
Copyright: 1977

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 25
Volume 1, Sheet 26
Volume 1, Sheet 28
Volume 1, Sheet 24

0 Feet 150 300 600

N

1970 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D3A8-4CA6-9D89

Site Name: 27-21 44th Drive and 44-18 Purves Street
Address: 44-18 Purves Street
City, ST, ZIP: Long Island City NY 11101
Client: Langan Engineering, Inc.
EDR Inquiry: 3798265.3
Order Date: 12/2/2013 12:04:02 PM
Certification # D3A8-4CA6-9D89
Copyright: 1970

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 26
Volume 1, Sheet 25
Volume 1, Sheet 24

0 Feet 150 300 600

N

1950 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	1950

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26

N

1947 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	1947

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26

N

1936 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	1936

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26

N

1915 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # D3A8-4CA6-9D89

Site Name: 27-21 44th Drive and 44-18 Purves Street
Address: 44-18 Purves Street
City, ST, ZIP: Long Island City NY 11101
Client: Langan Engineering, Inc.
EDR Inquiry: 3798265.3
Order Date: 12/2/2013 12:04:02 PM
Certification # D3A8-4CA6-9D89
Copyright: 1915

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26
Volume 1, Sheet 28

0 Feet 150 300 600

N

1898 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # D3A8-4CA6-9D89

Site Name:	27-21 44th Drive and 44-18 Purves Street
Address:	44-18 Purves Street
City, ST, ZIP:	Long Island City NY 11101
Client:	Langan Engineering, Inc.
EDR Inquiry:	3798265.3
Order Date:	12/2/2013 12:04:02 PM
Certification #	D3A8-4CA6-9D89
Copyright:	1898

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26

N

APPENDIX J- HISTORICAL USGS TOPOGRAPHIC QUADRANGLE MAPS SUMMARY

27-21 44th Drive and 44-18 Purves Street
44-18 Purves Street
Long Island City, NY 11101

Inquiry Number: 3798265.4
December 02, 2013

EDR Historical Topographic Map Report

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
800.352.0050
www.edrnet.com

EDR Historical Topographic Map Report

Environmental Data Resources, Inc.s (EDR) Historical Topographic Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topographic Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the early 1900s.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Historical Topographic Map



N	TARGET QUAD NAME: BROOKLYN MAP YEAR: 1900 SERIES: 15 SCALE: 1:62500	SITE NAME: 27-21 44th Drive and 44-18 Purves Street ADDRESS: 44-18 Purves Street Long Island City, NY 11101 LAT/LONG: 40.7467 / -73.9415	CLIENT: Langan Engineering, Inc. CONTACT: Jessica Alzamora INQUIRY#: 3798265.4 RESEARCH DATE: 12/02/2013

Historical Topographic Map




N	TARGET QUAD NAME: BROOKLYN MAP YEAR: 1924 REVISED FROM :1900 SERIES: 15 SCALE: 1:62500	SITE NAME: 27-21 44th Drive and 44-18 Purves Street ADDRESS: 44-18 Purves Street Long Island City, NY 11101 LAT/LONG: 40.7467 / -73.9415	CLIENT: Langan Engineering, Inc. CONTACT: Jessica Alzamora INQUIRY#: 3798265.4 RESEARCH DATE: 12/02/2013

Historical Topographic Map




N	TARGET QUAD		SITE NAME:	27-21 44th Drive and 44-18 Purves Street	CLIENT:	Langan Engineering, Inc.
	NAME:	BROOKLYN			CONTACT:	Jessica Alzamora
	MAP YEAR:	1947	ADDRESS:	44-18 Purves Street Long Island City, NY 11101	INQUIRY#:	3798265.4
	SERIES:	7.5	LAT/LONG:	40.7467 / -73.9415	RESEARCH DATE:	12/02/2013
	SCALE:	1:25000				

Historical Topographic Map




N	TARGET QUAD				
	NAME:	BROOKLYN	SITE NAME:	27-21 44th Drive and 44-18 Purves Street	CLIENT: Langan Engineering, Inc.
	MAP YEAR:	1956	ADDRESS:	44-18 Purves Street Long Island City, NY 11101	CONTACT: Jessica Alzamora
	SERIES:	7.5	LAT/LONG:	40.7467 / -73.9415	INQUIRY#: 3798265.4
	SCALE:	1:24000			RESEARCH DATE: 12/02/2013

Historical Topographic Map




N	TARGET QUAD		SITE NAME:	27-21 44th Drive and 44-18 Purves Street	CLIENT:	Langan Engineering, Inc.
	NAME:	BROOKLYN			CONTACT:	Jessica Alzamora
	MAP YEAR:	1967	ADDRESS:	44-18 Purves Street Long Island City, NY 11101	INQUIRY#:	3798265.4
					RESEARCH DATE:	12/02/2013
	SERIES:	7.5	LAT/LONG:	40.7467 / -73.9415		
	SCALE:	1:24000				

Historical Topographic Map




N	TARGET QUAD				
	NAME:	BROOKLYN	SITE NAME:	27-21 44th Drive and 44-18 Purves Street	CLIENT: Langan Engineering, Inc.
	MAP YEAR:	1979	ADDRESS:	44-18 Purves Street	CONTACT: Jessica Alzamora
	PHOTOREVISED FROM :	1967		Long Island City, NY 11101	INQUIRY#: 3798265.4
	SERIES:	7.5	LAT/LONG:	40.7467 / -73.9415	RESEARCH DATE: 12/02/2013
	SCALE:	1:24000			

Historical Topographic Map



N	TARGET QUAD NAME: BROOKLYN MAP YEAR: 1995 SERIES: 7.5 SCALE: 1:24000	SITE NAME: 27-21 44th Drive and 44-18 Purves Street ADDRESS: 44-18 Purves Street Long Island City, NY 11101 LAT/LONG: 40.7467 / -73.9415	CLIENT: Langan Engineering, Inc. CONTACT: Jessica Alzamora INQUIRY#: 3798265.4 RESEARCH DATE: 12/02/2013

Historical Topographic Map




N	ADJOINING QUAD NAME: HARLEM MAP YEAR: 1897 SERIES: 15 SCALE: 1:62500	SITE NAME: 27-21 44th Drive and 44-18 Purves Street ADDRESS: 44-18 Purves Street Long Island City, NY 11101 LAT/LONG: 40.7467 / -73.9415	CLIENT: Langan Engineering, Inc. CONTACT: Jessica Alzamora INQUIRY#: 3798265.4 RESEARCH DATE: 12/02/2013

Historical Topographic Map




N	ADJOINING QUAD NAME: CENTRAL PARK MAP YEAR: 1947 SERIES: 7.5 SCALE: 1:25000	SITE NAME: 27-21 44th Drive and 44-18 Purves Street ADDRESS: 44-18 Purves Street Long Island City, NY 11101 LAT/LONG: 40.7467 / -73.9415	CLIENT: Langan Engineering, Inc. CONTACT: Jessica Alzamora INQUIRY#: 3798265.4 RESEARCH DATE: 12/02/2013

Historical Topographic Map



RESERVOIR
Mt Sinai Hospital
Metropolitan Museum of Art
Guggenheim Museum
Lenox Hill Hospital
Madison Ave Hospital
Doctors Hospital
Misericordia Hospital
Industrial Arts Sch
Coler Mem Hosp and Home
Lighthouse
Heliport
Blackwells Island (Welfare Island)
Roosevelt
HUNTER COLLEGE
Foundling Hospital
Richman High Sch
Cornell Univ Med Col
New York Hospital
Rockefeller Institute
Aviation Trades High Sch
Sch for Deaf
Goldwater Mem Hosp
City Hospital
Midtown Hospital
Tunnel
UNITED NATIONS HEADQUARTERS
Mill Rock
Hallets Pt
Pot Cove
Hallets Cove
Athletic Field
Foot Bridge
Hell Gate Bridge
Wards Island
MANHATTAN
Astoria
Astoria Hospital
St Georges Ch
Boys Club
Health Center
Radio Tower (WLIB)
St Demetrios Sch
Long Island City
St Ritas Sch
St Patricks Sch
Long I City High Sch
Army Pictorial Center
Sunnyside Yards
Parcel Post Sta
Queensboro Bridge
Triborough Bridge
Hell Gate
Pumping Sta
Boat Basin
Jefferson Park
Mt Sinai Hospital
Metropolitan Hospital
Bus Garage
Armory
Voc High Sch
Fire Sta
Play Ground
Park
Tunnel
Lighthouse
Gibbs Pt
Rainey Park
Queens Br Park
Oil
Gas
Nurses Res
Hosp Clinic
Ewing Mem Hospital
Lexington Hospital
Beth David Hospital
Coggenheim Museum
Museum History
Frick Collection
Sewage Disposal
Stadium
Welfare Center
Play Ground
Light
Piles
Pumping Sta
Immaculate Concept
Astoria Hospital
Boulevard Hospital
Queensboro
Triborough
Grand
Broadway
Crescent
Northern
Vernon
Sutton
Franklin
Lexington
Madison
Park
East River
Hell Gate
Long Island City
Astoria
Blackwells Island
Roosevelt
Tunnel
Bridge
Toll
Transit
Rapid
Expressway
Boulevard
Avenue
Street
Drive
Place
Crescent
Tracks
Lane
Ramp
Subway
Sta
Fire Sta
Hospital
Nurses Res
Oil
Gas
Light
Piles
Foot Bridge
Pumping Sta
Play Ground
Park
Tunnel
Lighthouse
Heliport
Gibbs Pt
Rainey Park
Queens Br Park
Hosp Clinic
Ewing Mem Hospital
Lexington Hospital
Beth David Hospital
Coggenheim Museum
Museum History
Frick Collection
Sewage Disposal
Stadium
Welfare Center
Jefferson Park
Mt Sinai Hospital
Metropolitan Hospital
Bus Garage
Armory
Voc High Sch
Fire Sta
Play Ground
Park
Tunnel
Lighthouse

Historical Topographic Map




N	ADJOINING QUAD NAME: CENTRAL PARK MAP YEAR: 1966 SERIES: 7.5 SCALE: 1:24000	SITE NAME: 27-21 44th Drive and 44-18 Purves Street ADDRESS: 44-18 Purves Street Long Island City, NY 11101 LAT/LONG: 40.7467 / -73.9415	CLIENT: Langan Engineering, Inc. CONTACT: Jessica Alzamora INQUIRY#: 3798265.4 RESEARCH DATE: 12/02/2013

Historical Topographic Map



N	ADJOINING QUAD NAME: CENTRAL PARK MAP YEAR: 1979 PHOTOREVISED FROM :1966 SERIES: 7.5 SCALE: 1:24000	SITE NAME: 27-21 44th Drive and 44-18 Purves Street ADDRESS: 44-18 Purves Street Long Island City, NY 11101 LAT/LONG: 40.7467 / -73.9415	CLIENT: Langan Engineering, Inc. CONTACT: Jessica Alzamora INQUIRY#: 3798265.4 RESEARCH DATE: 12/02/2013

Historical Topographic Map



N	ADJOINING QUAD NAME: CENTRAL PARK MAP YEAR: 1995 SERIES: 7.5 SCALE: 1:24000	SITE NAME: 27-21 44th Drive and 44-18 Purves Street ADDRESS: 44-18 Purves Street Long Island City, NY 11101 LAT/LONG: 40.7467 / -73.9415	CLIENT: Langan Engineering, Inc. CONTACT: Jessica Alzamora INQUIRY#: 3798265.4 RESEARCH DATE: 12/02/2013

APPENDIX K- CITY DIRECTORY ABSTRACT

27-21 44th Drive and 44-18 Purves Street
4418 Purves Street
Long Island City, NY 11101

Inquiry Number: 3798265.6
December 04, 2013

The EDR-City Directory Abstract

Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at five year intervals.

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1922 through 2013. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 660 feet of the target property.

A summary of the information obtained is provided in the text of this report.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Year	*Source*	*TP*	*Adjoining*	*Text Abstract*	*Source Image*
2013	Cole Information Services	-	X	X	-
2008	Cole Information Services	-	X	X	-
2005	Hill-Donnelly Information Services	-	X	X	-
2000	Cole Information Services	-	X	X	-
1996	NYNEX	-	-	-	-
1991	NYNEX Information Resource Company	-	X	X	-
1983	New York Telephone	-	X	X	-
1976	New York Telephone	-	X	X	-
1970	New York Telephone	-	X	X	-
1967	New York Telephone	-	X	X	-
1962	New York Telephone Directory	-	X	X	-
1950	New York Telephone	-	-	-	-
1945	New York Telephone	-	X	X	-
1939	New York Telephone Company	-	X	X	-
1934	R. L. Polk & Co.	-	X	X	-
1922	The Metropolitan Directory Co.	-	-	-	-

EXECUTIVE SUMMARY

SELECTED ADDRESSES

The following addresses were selected by the client, for EDR to research. An "X" indicates where information was identified.

Address	*Type*	*Findings*
2719 44th Drive	Client Entered	X
2721 44th Drive	Client Entered	X
2723 44th Drive	Client Entered	X
2725 44th Drive	Client Entered	
2727 44th Drive	Client Entered	
4422 Purves Street	Client Entered	X
2733 44th Drive	Client Entered	
2717 Thompson Ave	Client Entered	
4424 Purves Street	Client Entered	X
4426 Purves Street	Client Entered	X
4428 Purves Street	Client Entered	X
4417 Purves Street	Client Entered	X
4419 Purves Street	Client Entered	X
4421 Purves Street	Client Entered	X
4412 Purves Street	Client Entered	X
4414 Purves Street	Client Entered	X
4416 Purves Street	Client Entered	X

FINDINGS

TARGET PROPERTY INFORMATION

ADDRESS

4418 Purves Street
Long Island City, NY 11101

FINDINGS DETAIL

Target Property research detail.

FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

44TH DR

2719 44TH DR

Year	Uses	Source
2013	NASTASI RACING CAR CORP	Cole Information Services
	QUEENS PLAZA	Cole Information Services
2008	NAS INTERNATIONAL INC	Cole Information Services

2723 44TH DR

Year	Uses	Source
2013	NORTHEASTERN AUTO REPAIR INC	Cole Information Services
2008	NORTHEASTERN AUTO REPAIR INC	Cole Information Services

44th Drive

2719 44th Drive

Year	Uses	Source
2005	Nastasi Racing Car Corp	Hill-Donnelly Information Services
2000	Nastasi Racg Car	Cole Information Services

2721 44th Drive

Year	Uses	Source
1967	Wm Berg Inc	New York Telephone
1962	Jackson Cabinet Corp	New York Telephone Directory
	Berg Rent A Car Svce	New York Telephone Directory
	Berg Truck Rentl Co Inc	New York Telephone Directory
	Berg Trucking Co	New York Telephone Directory
1945	Packaging div	New York Telephone
1939	Ideal Garage	New York Telephone Company

2723 44th Drive

Year	Uses	Source
2000	NE Auto Repair Inc	Cole Information Services
1983	Alvic Foreign Auto Repr	New York Telephone
1970	Tul Mor Auto Service Inc	New York Telephone
	Tul Mor Auto Svce Inc	New York Telephone

Year	Uses	Source
1962	Berg Rent A Car Svce	New York Telephone Directory
	Berg Truck Rental Co Inc	New York Telephone Directory

PURVES ST

4412 PURVES ST

Year	Uses	Source
2013	PURVES AUTOMOBILE REPAIR	Cole Information Services
	NONE JAROSLAW	Cole Information Services
	RICAMBI SPORT	Cole Information Services
2008	BARKO AUTOMOTIVE	Cole Information Services
	GUTMANN NORTH AMERICA CORP	Cole Information Services

4416 PURVES ST

Year	Uses	Source
2008	SP PERFORMANCE INTERNATIONAL INC	Cole Information Services

4419 PURVES ST

Year	Uses	Source
2013	SCULPTURE CENTER INC	Cole Information Services
2008	SCULPTURE CENTER INC	Cole Information Services

4426 PURVES ST

Year	Uses	Source
2008	RICAMBI SPORT	Cole Information Services

Purves Street

4412 Purves Street

Year	Uses	Source
2005	Barko Automotive 1 R	Hill-Donnelly Information Services
	S 5 P Performance Intl Inc	Hill-Donnelly Information Services
1939	Ellis Wm A auto sprngs	New York Telephone Company

4414 Purves Street

Year	Uses	Source
1934	Simms Arth truck driver	R. L. Polk & Co.
	Armour Walter Mattie lab	R. L. Polk & Co.
	Smith Herman rigger	R. L. Polk & Co.
	Gonzalez Rais film fcty	R. L. Polk & Co.

Year	Uses	Source
1934	Martin Daisy drss opr	R. L. Polk & Co.

4416 Purves Street

Year	Uses	Source
1991	Gimme Seltzer Manhattan	NYNEX Information Resource Company
1983	Leber Katz b	New York Telephone
1934	Christian Oliver Lillian porter	R. L. Polk & Co.
	Christian Sonny Bertha musician	R. L. Polk & Co.
	Yates John Delia	R. L. Polk & Co.

4417 Purves Street

Year	Uses	Source
1976	Consolidated Concrete Cutting Corp	New York Telephone
1970	Expert Concrete Breakers Inc	New York Telephone
	Consolidated Concrete Cuting Corp	New York Telephone
1967	Expert Concrete Breakers Inc	New York Telephone
1962	Expert Concrete Breakers Inc	New York Telephone Directory
1945	Expert Concrete Breakers Inc	New York Telephone

4419 Purves Street

Year	Uses	Source
2005	Global Instalation Corp	Hill-Donnelly Information Services
2000	Globe Gates	Cole Information Services
	Glob Gates Inc	Cole Information Services
1991	GLOBE GATES INC	NYNEX Information Resource Company
	GLOBE GATES	NYNEX Information Resource Company
1983	European Gates Co	New York Telephone
1970	Concrete Breaking Co	New York Telephone
	HOWNOR ASSOCS INC	New York Telephone
1967	Hownor Assocs Inc	New York Telephone
	Concrete Breaking Co	New York Telephone
1945	Factory	New York Telephone
	Getomer Equip Co	New York Telephone
	Baltic Mach & Tool Co	New York Telephone

4421 Purves Street

Year	Uses	Source
2000	Russell Cress Co	Cole Information Services
1945	Concrete Breaking Co	New York Telephone

FINDINGS

4422 Purves Street

Year	*Uses*	*Source*
1934	Robinsson DAvid Mamie professional boxer	R. L. Polk & Co.

4424 Purves Street

Year	*Uses*	*Source*
1934	JAvakian Gabriel Alice carpet clnr	R. L. Polk & Co.
	Greer Clara Mrs maid	R. L. Polk & Co.
	Snelson Chas A clk	R. L. Polk & Co.
	Snelson Pearl wid Chas	R. L. Polk & Co.
	Robinson Isabelle walter	R. L. Polk & Co.
	Browder Florence wid Nicholas maid	R. L. Polk & Co.

4426 Purves Street

Year	*Uses*	*Source*
2000	Bartellino Vincent	Cole Information Services
1945	F R Mach Wks	New York Telephone

4428 Purves Street

Year	*Uses*	*Source*
1934	Solomon Bert Charlotte pipemkr	R. L. Polk & Co.
	Glover Grace wid Jos dom	R. L. Polk & Co.

FINDINGS

TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

Address Researched	Address Not Identified in Research Source
4418 Purves Street	2013, 2008, 2005, 2000, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

ADJOINING PROPERTY: ADDRESSES NOT IDENTIFIED IN RESEARCH SOURCE

The following Adjoining Property addresses were researched for this report, and the addresses were not identified in research source.

Address Researched	Address Not Identified in Research Source
2717 Thompson Ave	2013, 2008, 2005, 2000, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2719 44TH DR	2005, 2000, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2719 44th Drive	2013, 2008, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2721 44th Drive	2013, 2008, 2005, 2000, 1996, 1991, 1983, 1976, 1970, 1950, 1934, 1922
2723 44TH DR	2005, 2000, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2723 44th Drive	2013, 2008, 2005, 1996, 1991, 1976, 1967, 1950, 1945, 1939, 1934, 1922
2725 44th Drive	2013, 2008, 2005, 2000, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2727 44th Drive	2013, 2008, 2005, 2000, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2733 44th Drive	2013, 2008, 2005, 2000, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
4412 PURVES ST	2005, 2000, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
4412 Purves Street	2013, 2008, 2000, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
4414 Purves Street	2013, 2008, 2005, 2000, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
4416 PURVES ST	2013, 2005, 2000, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
4416 Purves Street	2013, 2008, 2005, 2000, 1996, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
4417 Purves Street	2013, 2008, 2005, 2000, 1996, 1991, 1983, 1950, 1939, 1934, 1922
4419 PURVES ST	2005, 2000, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
4419 Purves Street	2013, 2008, 1996, 1976, 1962, 1950, 1939, 1934, 1922
4421 Purves Street	2013, 2008, 2005, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
4422 Purves Street	2013, 2008, 2005, 2000, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
4424 Purves Street	2013, 2008, 2005, 2000, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
4426 PURVES ST	2013, 2005, 2000, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
4426 Purves Street	2013, 2008, 2005, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
4428 Purves Street	2013, 2008, 2005, 2000, 1996, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

APPENDIX L- ENVIRONMENTAL LIEN SEARCH

27-21 44th Drive and 44-18 Purves Street
44-18 Purves Street
Long Island City, NY 11101

Inquiry Number: 3798265.7
December 09, 2013

EDR Environmental Lien and AUL Search

Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
800.352.0050
www.edrnet.com

EDR Environmental Lien and AUL Search

The EDR Environmental Lien and AUL Search Report provides results from a search of available current land title records for environmental cleanup liens and other activity and use limitations, such as engineering controls and institutional controls.

A network of professional, trained researchers, following established procedures, uses client supplied address information to:

- search for parcel information and/or legal description;
- search for ownership information;
- research official land title documents recorded at jurisdictional agencies such as recorders' offices, registries of deeds, county clerks' offices, etc.;
- access a copy of the deed;
- search for environmental encumbering instrument(s) associated with the deed;
- provide a copy of any environmental encumbrance(s) based upon a review of key words in the instrument(s) (title, parties involved, and description); and
- provide a copy of the deed or cite documents reviewed.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EDR Environmental Lien and AUL Search

TARGET PROPERTY INFORMATION

ADDRESS

44-18 Purves Street
27-21 44th Drive and 44-18 Purves Street
Long Island City, NY 11101

RESEARCH SOURCE

Source 1:

Queens Recorder
Queens, NY

PROPERTY INFORMATION

Deed 1:

Type of Deed:	Deed
Title is vested in:	44 LIC LLC
Title received from:	Electric Realty Co. LLC
Deed Dated	9/14/2011
Deed Recorded:	8/27/2013
Book:	NA
Page:	NA
Volume:	NA
Instrument:	2013071900952001
Docket:	NA
Land Record Comments:	See Exhibit
Miscellaneous Comments:	NA
Legal Description:	See Exhibit
Legal Current Owner:	44 LIC LLC
Parcel # / Property Identifier:	Blk. 268 / Lot 4
Comments:	See Exhibit

Deed 2:

Type of Deed:	Deed
Title is vested in:	44 LIC LLC
Title received from:	4418 Purves LLC
Deed Dated	7/18/2013
Deed Recorded:	8/27/2013
Book:	NA
Page:	NA
Volume:	NA
Instrument:	2013071900952002
Docket:	NA
Land Record Comments:	

EDR Environmental Lien and AUL Search

	See Exhibit
Miscellaneous Comments:	NA
Legal Description:	See Exhibit
Legal Current Owner:	44 LIC LLC
Parcel # / Property Identifier:	Blk. 268 / Lot 23, Blk. 268 / Lot 22
Comments:	See Exhibit

ENVIRONMENTAL LIEN

Environmental Lien: Found ☐ Not Found ☒

OTHER ACTIVITY AND USE LIMITATIONS (AULs)

AULs: Found ☐ Not Found ☒

Deed Exhibit 1

NYC DEPARTMENT OF FINANCE
OFFICE OF THE CITY REGISTER

This page is part of the instrument. The City Register will rely on the information provided by you on this page for purposes of indexing this instrument.The information on this page will control for indexing purposes in the event of any conflict with the rest of the document.

2013071900952001001E83D3

RECORDING AND ENDORSEMENT COVER PAGE **PAGE 1 OF 5**

Document ID: 2013071900952001 Document Date: 09-14-2011 Preparation Date: 07-19-2013
Document Type: DEED
Document Page Count: 4

PRESENTER:
ALL NEW YORK TITLE AGENCY (PICK-UP VICKIE)
222 BLOOMINGDALE ROAD
SUITE 306 (ANY2011-7428C LS)
WHITE PLAINS, NY 10605
914-686-5600
JKAMNA@ALLNYT.COM

RETURN TO:
SEIDEN & SCHEIN, P.C.
570 LEXINGTON AVENUE, 14TH FLOOR
NEW YORK, NY 10022
ATTN: ALVIN SCHEIN, ESQ.

PROPERTY DATA

Borough	Block	Lot	Unit	Address
QUEENS	268	4	Entire Lot	27-21 44TH DRIVE

Property Type: OTHER

CROSS REFERENCE DATA

CRFN_____ *or* DocumentID_____ *or* _____ Year_____ Reel____ Page_____ *or* File Number_____

PARTIES

GRANTOR/SELLER:
ELECTRIC REALTY COMPANY, L. L. C.
C/O KRAUPNER GROUP, 457 KNICKERBOCKER AVENUE
BROOKLYN, NY 11237

GRANTEE/BUYER:
44 LIC LLC
C/O VOREA HOLDINGS, LLC, 184 N. 8TH STREET
NEW YORK, NY 11237

FEES AND TAXES

Mortgage :

Mortgage Amount:	$	0.00
Taxable Mortgage Amount:	$	0.00
Exemption:		
TAXES: County (Basic):	$	0.00
City (Additional):	$	0.00
Spec (Additional):	$	0.00
TASF:	$	0.00
MTA:	$	0.00
NYCTA:	$	0.00
Additional MRT:	$	0.00
TOTAL:	$	0.00
Recording Fee:	$	57.00
Affidavit Fee:	$	0.00

Filing Fee: $ 250.00
NYC Real Property Transfer Tax: $ 0.00
NYS Real Estate Transfer Tax: $ 0.00

RECORDED OR FILED IN THE OFFICE OF THE CITY REGISTER OF THE CITY OF NEW YORK
Recorded/Filed 08-27-2013 09:44
City Register File No.(CRFN): **2013000341299**

City Register Official Signature

A NY.11.7428C

QUITCLAIM DEED

by and between

ELECTRIC REALTY COMPANY, L.L.C.,
as Grantor

and

44 LIC LLC,
as Grantee

AS OF
Dated: September 14, 2011

Premises:
27-21 44th Drive
Long Island City, New York

Record and return to:

Alvin Schein, Esq.
Seiden & Schein, P.C.
570 Lexington Avenue, 14th floor
New York, New York 10022

Block:	268
Lot:	4
County:	Queens

QUITCLAIM DEED

THIS INDENTURE, made as of the 14th day of September, 2011

BETWEEN

ELECTRIC REALTY COMPANY, L.L.C., a Delaware limited liability company having an address at c/o Kraupner Group, 457 Knickerbocker Avenue, Brooklyn, New York 11237 (the "Grantor"),

AND

44 LIC LLC, a New York limited liability company having an address at c/o Vorea Holdings, LLC 184 N. 8th Street, New York, New York 11237 (the "Grantee").

WITNESSETH, that Grantor, in consideration of Ten Dollars ($10.00) and other valuable consideration paid by Grantee, does hereby remise, release and quitclaim unto Grantee, the heirs or successors and assigns of Grantee forever,

ALL that certain plot, piece or parcel of land, with the buildings and improvements thereon erected, situate, lying and being in the in the City of New York, County of Queens and State of New York, and known as part of 27-21 44th Drive, Long Island City, New York (the "Property"), as more particularly described on Schedule A annexed hereto and made a part hereof,

TOGETHER WITH all right, title and interest, if any, of Grantor in and to any streets and roads abutting the above described Property to the center lines thereof;

TOGETHER WITH the appurtenances and all the estate and rights of Grantor in and to said Property; and

TO HAVE AND TO HOLD the Property herein granted unto Grantee, the heirs or successors and assigns of Grantee, forever.

AND Grantor, in compliance with Section 13 of the Lien Law, covenants that Grantor will receive the consideration for this conveyance and will hold the right to receive such consideration as a trust fund to be applied first for the purpose of paying the cost of the improvements at the Property and will apply the same first to the payment of the cost of the improvements before using any part of the total of the same for any other purpose.

IN WITNESS WHEREOF, Grantor has duly executed this deed the day and year first above written.

ELECTRIC REALTY COMPANY, L.L.C.,
a New York limited liability company

By: _____
Name: Eileen Ludwig Greenland
Title: Authorized Signatory

ACKNOWLEDGMENT

STATE OF NEW YORK)
) ss.:
COUNTY OF NEW YORK)

On the 20th day of September in the year 2011, before me, the undersigned, a Notary Public in and for said State, personally appeared EILEEN LUDWIG GREENLAND, personally known to me or proved to me on the basis of satisfactory evidence to be the individual whose name is subscribed to the within instrument and acknowledged to me that she executed the same in her capacity, and that by her signature on the instrument, the individual, or the person upon behalf of which the individual acted, executed the instrument.

Notary Public

KEVIN P. GROARKE
Notary Public, State of New York
No. 4664596
Qualified in Westchester County
Commisssion Expires February 28, 2015

SEAL SEAL

SCHEDULE A
ANY2011-7242C

ALL those certain plots, pieces or parcels of land situate, lying and being in the Borough and County of Queens, City and State of New York, more particularly bounded and described as follows:

BEGINNING at a point on the easterly side of 44th Drive (Nott Avenue) distant 59.94 feet northerly from the corner formed by the intersection of the easterly side of 44th Drive with the northeasterly side of Thomson Avenue;

RUNNING thence northerly along the easterly side of 44th Drive, 100.04 feet;

THENCE easterly and parallel with the southerly side of Jackson Avenue, 92.11 feet;


THENCE southerly along a line forming an interior angle of 90 degrees 21' 40" with the last mentioned course, 75.00 feet;

THENCE easterly parallel with the southerly side of Jackson Avenue, 10.00 feet;

THENCE southerly parallel with the westerly side of Purves Street, 25.00 feet;

THENCE westerly along a line forming an interior angle of 89 degrees 38' 20" with the last mentioned course, 98.54 feet to the easterly side of 44th Drive, at the point or place of BEGINNING.

NYC DEPARTMENT OF FINANCE
OFFICE OF THE CITY REGISTER



2013071900952001001S4D52

SUPPORTING DOCUMENT COVER PAGE **PAGE 1 OF 1**

Document ID: 2013071900952001 Document Date: 09-14-2011 Preparation Date: 07-19-2013
Document Type: DEED

ASSOCIATED TAX FORM ID: 2013071900319

SUPPORTING DOCUMENTS SUBMITTED:

	Page Count
RP - 5217 REAL PROPERTY TRANSFER REPORT	4

FOR CITY USE ONLY

C1. County Code | | C2. Date Deed Recorded | | / | / | (Month / Day / Year)

C3. Book | | C4. Page | |

OR

C5. CRFN | |

REAL PROPERTY TRANSFER REPORT

STATE OF NEW YORK
STATE BOARD OF REAL PROPERTY SERVICES

RP - 5217NYC

(Rev 11/2002)

CITY REGISTER

JUN 24 2013

PROPERTY INFORMATION

1. Property Location: 27-21 (STREET NUMBER) | 44TH DRIVE (STREET NAME) | QUEENS (BOROUGH) | (ZIP CODE)

2. Buyer Name: 44 LIC LLC (LAST NAME / COMPANY) | (FIRST NAME)

(LAST NAME / COMPANY) | (FIRST NAME)

3. Tax Billing Address — Indicate where future Tax Bills are to be sent if other than buyer address (at bottom of form): C/O VOREA HOLDINGS LLC (LAST NAME / COMPANY) | (FIRST NAME)

184 N 8TH STREET (STREET NUMBER AND STREET NAME) | WILLIAMSBURG (CITY OR TOWN) | NY (STATE) | 11211 (ZIP CODE)

4. Indicate the number of Assessment Roll parcels transferred on the deed: 1 # of Parcels OR ☐ Part of a Parcel

4A. Planning Board Approval - N/A for NYC

4B. Agricultural District Notice - N/A for NYC

5. Deed Property Size: (FRONT FEET) X (DEPTH) OR (ACRES)

Check the boxes below as they apply:

6. Ownership Type is Condominium ☐

7. New Construction on Vacant Land ☐

8. Seller Name: ELECTRIC REALTY COMPANY, L.L.C. (LAST NAME / COMPANY) | (FIRST NAME)

(LAST NAME / COMPANY) | (FIRST NAME)

9. Check the box below which most accurately describes the use of the property at the time of sale:

A ☐ One Family Residential
B ☐ 2 or 3 Family Residential
C ☐ Residential Vacant Land
D ☐ Non-Residential Vacant Land
E ☑ Commercial
F ☐ Apartment
G ☐ Entertainment / Amusement
H ☐ Community Service
I ☐ Industrial
J ☐ Public Service

SALE INFORMATION

10. Sale Contract Date: 9 / 9 / 2011 (Month / Day / Year)

11. Date of Sale / Transfer: 9 / 9 / 2011 (Month / Day / Year)

12. Full Sale Price $ 0

(Full Sale Price is the total amount paid for the property including personal property. This payment may be in the form of cash, other property or goods, or the assumption of mortgages or other obligations.) *Please round to the nearest whole dollar amount.*

13. Indicate the value of personal property included in the sale

14. Check one or more of these conditions as applicable to transfer:

A ☐ Sale Between Relatives or Former Relatives
B ☐ Sale Between Related Companies or Partners in Business
C ☐ One of the Buyers is also a Seller
D ☐ Buyer or Seller is Government Agency or Lending Institution
E ☐ Deed Type not Warranty or Bargain and Sale (Specify Below)
F ☐ Sale of Fractional or Less than Fee Interest (Specify Below)
G ☐ Significant Change in Property Between Taxable Status and Sale Dates
H ☐ Sale of Business is Included in Sale Price
I ☐ Other Unusual Factors Affecting Sale Price (Specify Below)
J ☑ None

ASSESSMENT INFORMATION - Data should reflect the latest Final Assessment Roll and Tax Bill

15. Building Class: G, 2

16. Total Assessed Value (of all parcels in transfer):

17. Borough, Block and Lot / Roll Identifier(s) (If more than three, attach sheet with additional identifier(s))

QUEENS 268 4

CERTIFICATION

I certify that all of the items of information entered on this form are true and correct (to the best of my knowledge and belief) and I understand that the making of any willful false statement of material fact herein will subject me to the provisions of the penal law relative to the making and filing of false instruments.

BUYER

BUYER SIGNATURE | DATE

C/O VOREA HOLDINGS LLC 184 8TH STREET

STREET NUMBER | STREET NAME (AFTER SALE)

WILLIAMSBURG

CITY OR TOWN | NY (STATE) | 11211 (ZIP CODE)

BUYER'S ATTORNEY

LAST NAME | FIRST NAME

AREA CODE | TELEPHONE NUMBER

SELLER

SELLER SIGNATURE | DATE

2011091300126201

CERTIFICATION

I certify that all of the items of information entered on this form are true and correct (to the best of my knowledge and belief) and understand that the making of any willful false statement of material fact herein will subject me to the provisions of the penal law relative to the making and filing of false instruments.

BUYER		BUYER'S ATTORNEY	
BUYER SIGNATURE	DATE 2/22/12	LAST NAME	FIRST NAME
C/O VOREA HOLDINGS LLC 184 8TH STREET		AREA CODE	TELEPHONE NUMBER
STREET NUMBER STREET NAME (AFTER SALE)			
WILLIAMSBURG	NY 11211	SELLER	
CITY OR TOWN	STATE ZIP CODE	SELLER SIGNATURE	DATE 9/20/11

ELECTRIC REALTY COMPANY, LLC

2011091300126201

FOR CITY USE ONLY

C1. County Code | | C2. Date Deed Recorded | / / | Month Day Year

C3. Book OR C4. Page

C5. CRFN

REAL PROPERTY TRANSFER REPORT

STATE OF NEW YORK
STATE BOARD OF REAL PROPERTY SERVICES

RP - 5217NYC

PROPERTY INFORMATION

1. Property Location: 27-21 (STREET NUMBER) | 44TH DRIVE (STREET NAME) | QUEENS (BOROUGH) | 11101 (ZIP CODE)

2. Buyer Name: 44 LIC LLC (LAST NAME / COMPANY) | (FIRST NAME)

CITY REGISTER

(LAST NAME / COMPANY) | (FIRST NAME)

JUL 24 2013

3. Tax Billing Address — Indicate where future Tax Bills are to be sent if other than buyer address (at bottom of form)

(LAST NAME / COMPANY) | (FIRST NAME)

(STREET NUMBER AND STREET NAME) | (CITY OR TOWN) | (STATE) | (ZIP CODE)

4. Indicate the number of Assessment Roll parcels transferred on the deed: 1 # of Parcels OR ☐ Part of a Parcel

4A. Planning Board Approval - N/A for NYC

4B. Agricultural District Notice - N/A for NYC

5. Deed Property Size: (FRONT FEET) X (DEPTH) OR (ACRES)

Check the boxes below as they apply:

6. Ownership Type is Condominium ☐

7. New Construction on Vacant Land ☐

8. Seller Name: ELECTRIC REALTY COMPANY, L. L. C. (LAST NAME / COMPANY) | (FIRST NAME)

(LAST NAME / COMPANY) | (FIRST NAME)

9. Check the box below which most accurately describes the use of the property at the time of sale:

A ☐ One Family Residential
B ☐ 2 or 3 Family Residential
C ☐ Residential Vacant Land
D ☐ Non-Residential Vacant Land
E ☑ Commercial
F ☐ Apartment
G ☐ Entertainment / Amusement
H ☐ Community Service
I ☐ Industrial
J ☐ Public Service

SALE INFORMATION

10. Sale Contract Date: 9 / 9 / 2011 (Month Day Year)

11. Date of Sale / Transfer: 9 / 14 / 2011 (Month Day Year)

12. Full Sale Price $ 0

(Full Sale Price is the total amount paid for the property including personal property. This payment may be in the form of cash, other property or goods, or the assumption of mortgages or other obligations.) *Please round to the nearest whole dollar amount.*

13. Indicate the value of personal property included in the sale

14. Check one or more of these conditions as applicable to transfer:

A ☐ Sale Between Relatives or Former Relatives
B ☐ Sale Between Related Companies or Partners in Business
C ☐ One of the Buyers is also a Seller
D ☐ Buyer or Seller is Government Agency or Lending Institution
E ☐ Deed Type not Warranty or Bargain and Sale (Specify Below)
F ☐ Sale of Fractional or Less than Fee Interest (Specify Below)
G ☐ Significant Change in Property Between Taxable Status and Sale Dates
H ☐ Sale of Business is Included in Sale Price
I ☐ Other Unusual Factors Affecting Sale Price (Specify Below)
J ☑ None

ASSESSMENT INFORMATION - Data should reflect the latest Final Assessment Roll and Tax Bill

15. Building Class: G 2

16. Total Assessed Value (of all parcels in transfer): 1,651,150

17. Borough, Block and Lot / Roll Identifier(s) (If more than three, attach sheet with additional identifier(s))

QUEENS 268 4

CERTIFICATION

I certify that all of the items of information entered on this form are true and correct (to the best of my knowledge and belief) and understand that the making of any willful false statement of material fact herein will subject me to the provisions of the penal law relative to the making and filing of false instruments.

BUYER		BUYER'S ATTORNEY	
BUYER SIGNATURE	DATE	LAST NAME	FIRST NAME
C/O VOREA HOLDINGS, LLC 184 N. 8TH STREET			
STREET NUMBER / STREET NAME (AFTER SALE)		AREA CODE	TELEPHONE NUMBER
		SELLER	
NEW YORK / CITY OR TOWN	NY / STATE	11237 / ZIP CODE	SELLER SIGNATURE / DATE

2013071900319201

Deed Exhibit 2

NYC DEPARTMENT OF FINANCE
OFFICE OF THE CITY REGISTER

This page is part of the instrument. The City Register will rely on the information provided by you on this page for purposes of indexing this instrument.The information on this page will control for indexing purposes in the event of any conflict with the rest of the document.

2013071900952002002E7397

RECORDING AND ENDORSEMENT COVER PAGE **PAGE 1 OF 5**

Document ID: 2013071900952002 Document Date: 07-18-2013 Preparation Date: 07-19-2013
Document Type: DEED
Document Page Count: 4

PRESENTER:
ALL NEW YORK TITLE AGENCY (PICK-UP VICKIE)
222 BLOOMINGDALE ROAD
SUITE 306 (ANY2011-7428C LS)
WHITE PLAINS, NY 10605
914-686-5600
JKAMNA@ALLNYT.COM

RETURN TO:
SEIDEN & SCHEIN, P.C.
570 LEXINGTON AVENUE, 14TH FLOOR
NEW YORK, NY 10022

PROPERTY DATA

Borough	Block	Lot		Unit	Address
QUEENS	268	22	Entire Lot		44-18 PURVES STREET

Property Type: OTHER

Borough	Block	Lot		Unit	Address
QUEENS	268	23	Entire Lot		44-22 PURVES STREET

Property Type: OTHER

CROSS REFERENCE DATA

CRFN_____ *or* DocumentID_____ *or* _____ Year_____ Reel____ Page_____ *or* File Number_____

PARTIES

GRANTOR/SELLER:
4418 PURVES LLC
410 OGDEN AVENUE
TEANECK, NJ 07666

GRANTEE/BUYER:
44 LIC LLC
31-87 STEINWAY STREET, SUITE 5
ASTORIA, NY 11103

FEES AND TAXES

Mortgage :

Mortgage Amount:	$	0.00
Taxable Mortgage Amount:	$	0.00
Exemption:		
TAXES: County (Basic):	$	0.00
City (Additional):	$	0.00
Spec (Additional):	$	0.00
TASF:	$	0.00
MTA:	$	0.00
NYCTA:	$	0.00
Additional MRT:	$	0.00
TOTAL:	$	0.00
Recording Fee:	$	60.00
Affidavit Fee:	$	0.00

Filing Fee: $ 250.00
NYC Real Property Transfer Tax: $ 108,176.25
NYS Real Estate Transfer Tax: $ 16,484.00

RECORDED OR FILED IN THE OFFICE OF THE CITY REGISTER OF THE CITY OF NEW YORK
Recorded/Filed 08-27-2013 09:44
City Register File No.(CRFN): **2013000341300**

City Register Official Signature

AM-11-7428C

— Bargain and Sale Deed, with Covenant against Grantor's Acts — Individual or Corporation (Single Sheet)

CONSULT YOUR LAWYER BEFORE SIGNING THIS INSTRUMENT—THIS INSTRUMENT SHOULD BE USED BY LAWYERS ONLY.

THIS INDENTURE, made the 18TH day of July in the year 2013

BETWEEN 4418 PURVES LLC, 410 OGDEN AVENUE, TEANECK, NEW JERSEY, 07666

party of the first part, and 44 LIC LLC, 31-87 STEINWAY STREET, SUITE 5, ASTORIA, NEW YORK 11103
party of the second part,
WITNESSETH, that the party of the first part, in consideration of TEN ($10.00) dollars
paid by the party of the second part, does hereby grant and release unto the party of the second part, the heirs or successors and assigns of the party of the second part forever,

All that certain Lot, piece or parcel of land, with the buildings and improvements thereon erected, situate, lying and being in the County of Queens, Block 268, Lots 22 and 23 and known as 44-18 Purves Street, Long Island City, New York, the property being transferred being the same premises described in the deed to the party of the first part herein by deed dated 2/3/2010 recorded 2/17/2010 in CRFN 201000005432, See Schedule A annexed hereto for a metes and bounds description.

TOGETHER with all right, title and interest, if any, of the party of the first part in and to any streets and roads abutting the above described premises to the center lines thereof; TOGETHER with the appurtenances and all the estate and rights of the party of the first part in and to said premises; TO HAVE AND TO HOLD the premises herein granted unto the party of the second part, the heirs or successors and assigns of the party of the second part forever.

AND the party of the first part covenants that the party of the first part has not done or suffered anything whereby the said premises have been encumbered in any way whatever, except as aforesaid.
AND the party of the first part, in compliance with Section 13 of the Lien Law, covenants that the party of the first part will receive the consideration for this conveyance and will hold the right to receive such consideration as a trust fund to be applied first for the purpose of paying the cost of the improvement and will apply the same first to the payment of the cost of the improvement before using any part of the total of the same for any other purpose. The word "party" shall be construed as if it read "parties" whenever the sense of this indenture so requires.

IN WITNESS WHEREOF, the party of the first part has duly executed this deed the day and year first above written.

4418 PURVES, LLC

IN PRESENCE OF:

NORMAN N. RATZERSDORFER, MANAGER

ACKNOWLEDGEMENT TAKEN IN NEW YORK STATE

State of New York, County of NEW YORK, ss:

On the 18TH day of JUNE in the year 2013, before me, the undersigned, personally appeared NORMAN RATZERSDORFER, personally known to me or proved to me on the basis of satisfactory evidence to be the individual(s) whose name(s) is (are) subscribed to the within instrument and acknowledged to me that he/she/they executed the same in his/her/their capacity(ies), and that by his/her/their signature(s) on the instrument, the individual(s), or the person upon behalf of which the individual(s) acted, executed the instrument.

JACK WAINER
Notary Public, State of New York
No. 01WA4846218
Qualified in Nassau County
Commission Expires Sept. 30, 20 17

SEAL

ACKNOWLEDGEMENT BY SUBSCRIBING WITNESS TAKEN IN NEW YORK STATE

State of New York, County of , ss:

On the day of in the year , before me, the undersigned, a Notary Public in and for said State, personally appeared , the subscribing witness to the foregoing instrument, with whom I am personally acquainted, who, being by me duly sworn, did depose and say that he/she/they reside(s) in

(if the place of residence is in a city, include the street and street number if any, thereof);

that he/she/they know(s) to be the individual described in and who executed the foregoing instrument; that said subscribing witness was present and saw said execute the same; and that said witness at the same time subscribed his/her/their name(s) as a witness thereto

ACKNOWLEDGEMENT TAKEN IN NEW YORK STATE

State of New York, County of , ss:

On the day of in the year , before me, the undersigned, personally appeared , personally known to me or proved to me on the basis of satisfactory evidence to be the individual(s) whose name(s) is (are) subscribed to the within instrument and acknowledged to me that he/she/they executed the same in his/her/their capacity(ies), and that by his/her/their signature(s) on the instrument, the individual(s), or the person upon behalf of which the individual(s) acted, executed the instrument.

ACKNOWLEDGEMENT TAKEN OUTSIDE NEW YORK STATE

*State of , County of , ss:

*(Or insert District of Columbia, Territory, Possession or Foreign County)

On the day of in the year , before me the undersigned personally appeared Personally known to me or proved to me on the basis of satisfactory evidence to be the individual(s) whose name(s) is (are) subscribed to the within instrument and acknowledged to me that he/she/they executed the same in his/her/their capacity(ies), that by his/her/their signature(s) on the instrument, the individual(s) or the person upon behalf of which the individual(s) acted, executed the instrument, and that such individual make such appearance before the undersigned in the

(add the city or political subdivision and the state or country or other place the acknowledgement was taken).

Bargain and Sale Deed With Covenants

Title No. ANY 2011-7428C

4418 PURVES, LLC
TO
44 LIC, LLC

SECTION:

BLOCK: 268

LOT: 22 and 23

COUNTY OR TOWN: QUEENS

RETURN BY MAIL TO:

SEIDEN & SCHEIN, P.C.
570 LEXINGTON, AVENUE, 14TH FLOOR
NEW YORK, NEW YORK 10022

MADISON TITLE AGENCY L.L.C.
1125 OCEAN AVENUE
LAKEWOOD, NJ 08701
P:(732)905-9400
F:(732)905-9420
WWW.MADISONTITLE.COM

ALL NEW YORK TITLE AGENCY, INC.

Title No. ANY2011-7428C

SCHEDULE A

Amended 06-26-2013

PARCEL 1 - LOT 22

ALL that certain plot, piece or parcel of land situate, lying and being in the Borough of Queens, County of Queens, City and State of New York, known and designated as Lot No. 15 in Block No. 1, on a certain map entitled, "Thomson' Extension Map of Long Island City at Hunter's Point, made by Peter Van Alst, C.S. for James Thomson dated May 1, 1867" and filed in the Queens County Clerk's Office, with said lot is bounded and described as follows:

BEGINNING at a point on the westerly side of Purves Street (formerly known as Thomson Street) distant 175 feet southerly from the corner formed by the intersection of the westerly side of Purves Street with the southerly side of Jackson Avenue;

RUNNING thence southerly along said side of Purves Street, 25 feet;

THENCE westerly parallel with Jackson Avenue, 100 feet;

THENCE northerly parallel with Purves Street, 25 feet;

THENCE easterly parallel with Jackson Avenue, 100 feet to the westerly side of Purves Street, at the point or place of BEGINNING.

PARCEL 2 - LOT 23

ALL that certain plot, piece or parcel of land situate, lying and being in the Borough and County of Queens, City and State of New York, known as and by Lot Number 23 in Tax Block 268 as the Tax Map existed on June 6, 2006 and being bounded and described as follows:

BEGINNING at a point on the westerly side of Purvis Street distant 276 feet northerly from the corner formed by the intersection of the westerly side of Purvis Street with the northeasterly side of Thomson Avenue;

RUNNING thence westerly at right angles to the westerly side of Purvis Street, 100 feet;

THENCE northerly parallel to the westerly side of Purvis Street, 25 feet;

THENCE easterly again at right angles to the westerly side of Purvis Street, 100 feet to


- continued on next page -

SCHEDULE A (continued)

the westerly side of Purvis Street;

THENCE southerly along the westerly side of Purvis Street, 25 feet to the point or place of BEGINNING.

NYC DEPARTMENT OF FINANCE
OFFICE OF THE CITY REGISTER



2013071900952002002SBD16

SUPPORTING DOCUMENT COVER PAGE **PAGE 1 OF 1**

Document ID: 2013071900952002 Document Date: 07-18-2013 Preparation Date: 07-19-2013
Document Type: DEED

ASSOCIATED TAX FORM ID: 2013071600419

SUPPORTING DOCUMENTS SUBMITTED:

	Page Count
DEP CUSTOMER REGISTRATION FORM FOR WATER AND SEWER BILLING	2
RP - 5217 REAL PROPERTY TRANSFER REPORT	2

FOR CITY USE ONLY

C1. County Code ____ C2. Date Deed Recorded ____ / ____ / ____ (Month / Day / Year)

C3. Book OR C5. CRFN ____ C4. Page ____

REAL PROPERTY TRANSFER REPORT

STATE OF NEW YORK
STATE BOARD OF REAL PROPERTY SERVICES

RP - 5217NYC

PROPERTY INFORMATION

1. Property Location: 44-18 (STREET NUMBER) | PURVES STREET (STREET NAME) | QUEENS (BOROUGH) | 11101 (ZIP CODE)

2. Buyer Name: 44 LIC LLC (LAST NAME / COMPANY) | (FIRST NAME)

(LAST NAME / COMPANY) | (FIRST NAME)

3. Tax Billing Address: Indicate where future Tax Bills are to be sent if other than buyer address (at bottom of form) (LAST NAME / COMPANY) | (FIRST NAME)

(STREET NUMBER AND STREET NAME) | (CITY OR TOWN) | (STATE) | (ZIP CODE)

4. Indicate the number of Assessment Roll parcels transferred on the deed: 2 # of Parcels OR ☐ Part of a Parcel

4A. Planning Board Approval - N/A for NYC

4B. Agricultural District Notice - N/A for NYC

5. Deed Property Size: ____ (FRONT FEET) X ____ (DEPTH) OR ____ (ACRES)

Check the boxes below as they apply:

6. Ownership Type is Condominium ☐

7. New Construction on Vacant Land ☐

8. Seller Name: 4418 PURVES LLC (LAST NAME / COMPANY) | (FIRST NAME)

(LAST NAME / COMPANY) | (FIRST NAME)

9. Check the box below which most accurately describes the use of the property at the time of sale:

A ☐ One Family Residential
B ☐ 2 or 3 Family Residential
C ☐ Residential Vacant Land
D ☐ Non-Residential Vacant Land
E ☑ Commercial
F ☐ Apartment
G ☐ Entertainment / Amusement
H ☐ Community Service
I ☐ Industrial
J ☐ Public Service

SALE INFORMATION

10. Sale Contract Date: 4 / 24 / 2013 (Month / Day / Year)

11. Date of Sale / Transfer: 7 / 18 / 2013 (Month / Day / Year)

12. Full Sale Price $ 4,121,000

(Full Sale Price is the total amount paid for the property including personal property. This payment may be in the form of cash, other property or goods, or the assumption of mortgages or other obligations.) *Please round to the nearest whole dollar amount.*

13. Indicate the value of personal property included in the sale ____

14. Check one or more of these conditions as applicable to transfer:

A ☐ Sale Between Relatives or Former Relatives
B ☐ Sale Between Related Companies or Partners in Business
C ☐ One of the Buyers is also a Seller
D ☐ Buyer or Seller is Government Agency or Lending Institution
E ☐ Deed Type not Warranty or Bargain and Sale (Specify Below)
F ☐ Sale of Fractional or Less than Fee Interest (Specify Below)
G ☐ Significant Change in Property Between Taxable Status and Sale Dates
H ☐ Sale of Business is Included in Sale Price
I ☐ Other Unusual Factors Affecting Sale Price (Specify Below)
J ☑ None

ASSESSMENT INFORMATION - Data should reflect the latest Final Assessment Roll and Tax Bill

15. Building Class: V1

16. Total Assessed Value (of all parcels in transfer): 93,600

17. Borough, Block and Lot / Roll Identifier(s) (If more than three, attach sheet with additional identifier(s))

QUEENS 268 22 | QUEENS 268 23 |

20130716004192O102

CERTIFICATION

I certify that all of the items of information entered on this form are true and correct (to the best of my knowledge and belief) and understand that the making of any willful false statement of material fact herein will subject me to the provisions of the penal law relative to the making and filing of false instruments.

BUYER		BUYER'S ATTORNEY	
BUYER SIGNATURE	DATE 7/19/13	LAST NAME	FIRST NAME
31-87 STEINWAY STREET, SUITE 5		AREA CODE	TELEPHONE NUMBER
STREET NUMBER / STREET NAME (AFTER SALE)			
ASTORIA / NY / 11103		SELLER	
CITY OR TOWN / STATE / ZIP CODE		SELLER SIGNATURE	DATE 7/18/13

2013071600419201

The City of New York
Department of Environmental Protection
Bureau of Customer Services
59-17 Junction Boulevard
Flushing, NY 11373-5108

www.nyc.gov/dep

Customer Registration Form for Water and Sewer Billing

Property and Owner Information:

(1) **Property receiving service: BOROUGH: QUEENS** **BLOCK: 268** **LOT: 22**

(2) **Property Address: 44-18 PURVES STREET, QUEENS, NY 11101**

(3) **Owner's Name:** **44 LIC LLC**

Additional Name:

Affirmation:

☑ Your water & sewer bills will be sent to the property address shown above.

Customer Billing Information:

Please Note:

A. Water and sewer charges are the legal responsibility of the owner of a property receiving water and/or sewer service. The owner's responsibility to pay such charges is not affected by any lease, license or other arrangement, or any assignment of responsibility for payment of such charges. Water and sewer charges constitute a lien on the property until paid. In addition to legal action against the owner, a failure to pay such charges when due may result in foreclosure of the lien by the City of New York, the property being placed in a lien sale by the City or Service Termination.

B. Original bills for water and/or sewer service will be mailed to the owner, **at the property address or to an alternate mailing address**. DEP will provide a duplicate copy of bills to one other party (such as a managing agent), however, any failure or delay by DEP in providing duplicate copies of bills shall in no way relieve the owner from his/her liability to pay all outstanding water and sewer charges. Contact DEP at (718) 595-7000 during business hours or visit www.nyc.gov/dep to provide us with the other party's information.

Owner's Approval:

The undersigned certifies that he/she/it is the owner of the property receiving service referenced above; that he/she/it has read and understands Paragraphs A & B under the section captioned "Customer Billing Information"; and that the information supplied by the undersigned on this form is true and complete to the best of his/her/its knowledge.

Print Name ~~of Owner~~:

Signature: _____ Date (mm/dd/yyyy) 7/18/2013

Name and Title of Person Signing for Owner, if applicable:

SEE ATTACHED PAGE FOR ADDITIONAL APPLICABLE PROPERTIES

BCS-7CRF-ACRIS REV. 8/08

2013071600419101

The City of New York
Department of Environmental Protection
Bureau of Customer Services
59-17 Junction Boulevard
Flushing, NY 11373-5108

www.nyc.gov/dep

Customer Registration Form for Water and Sewer Billing

Borough	Block	Lot	Street	City	State	Zip
QUEENS	268	23	44-22 PURVES STREET	NY	NY	11101

20130716004191O102

APPENDIX M- RESUMES

Jessica P. Alzamora, PE, LEED AP

Senior Staff Engineer/ Project Scientist
Environmental Engineering & Construction Monitoring



8 years in the industry ~ 7 years with Langan

Ms. Alzamora has over eight years of experience in environmental, site/civil, and geotechnical engineering. Her experience involves site investigation and remediation, environmental site assessments, utility assessments and design, water system analysis, and stormwater management design in New York, New Jersey, Nevada, and Connecticut. Her construction/field experience includes remedial excavation oversight, excavation and disposal of contaminated soils, installation and sampling of groundwater monitoring wells, soil sampling, health and safety air-monitoring, construction oversite/inspection, earthwork inspection, caisson installation, pavement inspection, and general surveying practices. Ms. Alzamora has experience in the evaluation of laboratory analytical data, design of sub-slab depressurization and soil vapor extraction systems, and preparation of construction documents and environmental reports (investigation, spill closure, final engineering reports, remedial action plans, health and safety plans). Ms. Alzamora is proficient in the latest Microsoft applications, AutoCAD, Land Development Desktop, and gINT.

Selected Projects

Teterboro Airport, 22 Acre Site, Teterboro, NJ
New York City School Construction Authority,
Multiple PCB Sites, New York, NY
McCarren Park Pool Reconstruction, Brooklyn, NY
711 Stewart Avenue, Garden City, NY
Hudson Mews Property-Marty Fine Parcel, New York, NY
627-641 Smith Street, Brooklyn, NY
216 West 76th Street, New York, NY
500 West 23rd Street, New York, NY
Gotham West/Studio City, New York, NY
1113 York Avenue, New York, NY
Con Edison, East 60th Street Generating Station, NY
2950 Atlantic Avenue, East New York, Brooklyn, NY
255 4th Avenue, Brooklyn, NY
New York Police Academy, Queens, NY
West 59th Street, New York, NY
Kingsbridge Armory, Bronx, NY
Public Safety Answer Center II - Bronx, NY
River Place II, New York, NY
Gateway at Bronx Terminal Market, Bronx, NY
Red Bull Arena, Harrison, NJ
Goldman Sachs World Headquarters, New York, NY
FDNY Rescue No. 3, Bronx, NY
Novartis East Village Expansion, East Hanover, NJ
New York Botanical Gardens, Bronx, NY

Education

B.S., Civil Engineering
University of Connecticut

A.S., Engineering Science
Manchester Community College

Professional Registration

Professional Engineer (PE) in NY

LEED Accredited Professional (LEED AP)

Affiliations

American Society of Civil Engineers (ASCE)

United States Green Building Council (USGBC)

LANGAN

Cooper Union Academic Building, New York, NY
The Curve Mixed-Use Development, Clark County, NV
Storage West Town Center, Las Vegas, NV
Walgreens Retail Center, CT
University of Hartford's Integrated Science and Technology Complex (ISET), Hartford, CT

Jason J. Hayes, PE, LEED AP

Associate
Environmental Engineering & Project Management



13 years in the industry

Mr. Hayes has 13 years of experience in New York, New Jersey, California, Washington, Oregon and Alaska. His experience includes Environmental Protection Agency (EPA), New York State (NYS) Brownfield's application, investigation, and remediation; New York City Department of Environmental Protection (NYCDEP) and New York City Office of Environmental Remediation (OER) E-designated site application, investigation, and remediation; Phase I and II Environmental Site Assessments; contaminated building cleanup and demolition; Underground Storage Tank (UST) permitting, removal specifications, and closure reporting; soil vapor intrusion investigation and mitigation system design (sub-slab depressurization systems, etc.); development of screening-level groundwater contaminant (volatile organic compounds - VOCs) plume migration models; environmental analysis; and oversight, design and specification generation for remediation operations with contaminants of concern to include polychlorinated biphenyls (PCBs), solvents, mercury, arsenic, petroleum products, asbestos, mold and lead.

Selected Projects

New York Police Academy, Queens, NY
Gateway at Bronx Terminal Market, Bronx, NY
Jacob Javits Convention Center, New York, NY
Yankee Stadium Development, Bronx, NY
Bushwick Inlet Park, Brooklyn, NY
Silvercup West, Queens, NY
29 Flatbush, Brooklyn, NY
Gowanus Village I, Brooklyn, NY
Sullivan Street Hotel, New York, New York
Riker's Island, Co-Generation Plant, Bronx, NY
The Shops at Atlas Park, Glendale, NY
Memorial Sloan-Kettering Cancer Center, New York, NY
Element West 59th Street, New York, NY
Teterboro Airport, Teterboro, NJ
Proposed New York JETS Stadium, New York, NY
Former Con Edison Manufactured Gas Plant (MGP) Sites, New York, NY
7 World Trade Center, New York, NY
Peter Cooper Village, New York, NY

Selected Publications, Reports, and Presentations

NYC Mayor's Office of Environmental Remediation – Big Apple Brownfield Workshop – Presented on Soil Vapor Intrusion Remedies (e.g., SSD Systems, Vapor Barriers, Modified HVAC)

Education

M.S., Environmental Engineering
Columbia University

B.Sc., Chemistry, Environmental Toxicology
Humboldt State University

Business Administration (minor)
Humboldt State University

Professional Registration

Professional Engineer (PE) in NY

LEED Accredited Professional (LEED AP)

OSHA 40-Hour HAZWOPER

OSHA HAZWOPER Site Supervisor

Affiliations

US Green Building Council, NYC Chapter (USGBC)

Urban Land Institute (ULI)

NAIOP

National Brownfield Partnership

LANGAN

Joel B. Landes, PE

Senior Associate/ Program Director
Environmental Engineering & Project Management



37 years in the industry ~ 13 years with Langan

Mr. Landes has over thirty-seven years of diversified experience directing environmental engineering and consulting projects for Fortune 500 manufacturing firms, real estate developers and public utilities. His experience includes management of environmental compliance for a major pharmaceutical company and as an environmental affairs consultant for private clients. He has expertise redeveloping former industrial, chemical, petroleum storage and manufactured gas plant sites into residential and commercial use through the New York State Brownfield Cleanup Program. He has lead environmental studies for acquisitions and divestitures of pharmaceutical and industrial facilities; industrial site selection and permitting.

He currently oversees all Langan environmental services in the New York City Metropolitan area including Phase I and II Environmental Site Assessments, remedial investigations, feasibility studies; remedial measure design and implementation.

Selected Projects

BROWNFIELD CLEANUP PROGRAM

The Shops at Atlas Park, Glendale, Queens, NY
Gateway at Bronx Terminal Market, Bronx, NY

INDUSTRIAL

711 Stewart Avenue, Garden City, NY
Acme/Whitehead, Brooklyn, NY
Waterside Generating Plan and Office Building, New York, NY
FSM Partners, New York, NY
Consolidated Edison of New York, Multiple Former MGP Facilities, Various Locations, New York, NY
Sterling Drug, Inc., Rensselaer, NY
Fresh Kills Landfill, New York City Department of Sanitation, Staten Island, NY
Property Investigation for Village of Sleepy Hollow, Tarrytown, NY
Vehicle Service Facility, City of Yonkers, NY
Crane Company, Roseland, NJ
Confidential Industrial Client, Environmental Risk Management, Bound Brook, NJ
Confidential Client, Superfund Site Remediation, Bound Brook, NJ
Elizabethtown Gas Company, Elizabeth, NJ

Education

Graduate Studies in
Business Management
Union College

M.E., Environmental Planning
and Management
The Cooper Union

B.S., Chemical Engineering
Polytechnic Institute of Brooklyn

Professional Registration

Professional Engineer (PE) in NY, NJ

Affiliations

New York Building Congress

NYC Partnerships of Brownfield Professionals

Business Council of New York State

Environmental Business Association

National Brownfield Association – NYS Chapter

LANGAN

Ethicon, Somerville, NJ
Indiana General, Keasbey, NJ
Sumitomo Machinery, Teterboro, NJ
Schmid Labs, West Patterson, NJ
L&F Products, ISRA/ECRA Cleanup, Belle Mead, NJ
CPC International, Various Locations, NY and IL
Pnemo Abex, Cleveland, OH
NL Chemicals, Various Locations, NJ and MI
Copper Processing Plant, Sofia, Bulgaria
Steel Processing Plant, Environmental Assessment, Pernik, Bulgaria
American Home Products, Mexico
Confidential Pharmaceutical Acquisition, Europe, Caribbean, and Africa
Colgate-Palmolive, Paris, France, Mexico City, Mexico, Brazil, Argentina and South America
Pfizer Pharmaceutical Company, PA and Europe
Riverwood Capital, US, Mexico, Central and South America
Sterling Drug, Puerto Rico
Laport, Ltd., Chile, South America

POWER

Sithe Energy, Kenilworth, NJ
Confidential Independent Power Producer Siting Analysis, Midwest, Mid-Atlantic and Southern, United States
Confidential IPP, Various Locations, VA
Florida Power and Light (FPL), Miami, FL
TXU Energy, Dallas, TX
Confidential Independent Power Producer, Midwest, Mid-Atlantic and Southern United States

AIRPORTS

American Airlines Terminals, Environmental Assessments, Queens, NY
JFK International Airport, International Arrivals Building, Jamaica, Queens, NY
Nippon Cargo, Jamaica, Queens, NY
JFK International Airport, Eastern Airlines Hangar, Jamaica, Queens, NY
First Aviation Services Hangar and Terminal at Teterboro Airport, Teterboro, NJ

TRANSPORTATION

New Jersey Turnpike Authority, East Brunswick, NJ

HOSPITAL

Memorial Sloan-Kettering Cancer Center, New York, NY
Memorial Sloan-Kettering Cancer Center, 1133 York Avenue, New York, NY
Memorial Sloan-Kettering Cancer Center, 64th Street, New York, NY
Memorial Sloan-Kettering Cancer Center, 74th Street, New York, NY
Memorial Sloan-Kettering Cancer Center, West Harrison, NY

COMMERCIAL

Jacob K. Javits Convention Center Expansion, New York, NY
7 World Trade Center, New York, NY

Atlantic Avenue Service Center, Brooklyn, NY
Yamato Transport, Tuckahoe, NY and Leonia, NJ
Mutual Oil Company, RI

HIGHER EDUCATION

Columbia University, Manhattanville Development Project, New York, NY
Columbia University Real Estate Group, 220 East 138th Street, Bronx, NY
Columbia University Real Estate Group, 1734 Bathgate Avenue, Bronx, NY
Columbia University Real Estate Group, 1745 Bathgate Avenue, Bronx, NY
Columbia University, The Studebaker Building Renovation, New York, NY
City University of New York (CUNY) John Jay College Expansion,
New York, NY

K-12 EDUCATION

PS 192, New York, NY

RESIDENTIAL AND MIXED-USE

Sullivan Street Residential, New York, NY
475 Ninth Avenue, New York, NY
River Place I and II, New York, NY
10 Chelsea, New York, NY
Silvercup West, Long Island City, NY
Superior Ink, New York, NY
Peter Cooper Village/Stuyvesant Town, MGP Consultations, New York, NY
Duane Street Condominium, New York, NY
Archstone Clinton, New York, NY

PARKS AND RECREATION

Highline Park, New York, NY
Yankee Stadium Redevelopment Project, Bronx, NY
Proposed New York Jets Stadium, New York, NY
AMF Bowling Centers, Phase I ESA's, 285 Locations, United States

EXPERT WITNESS

Confidential Client, Expert Affidavit, New York, NY
Confidential Client, Four New York Properties, New York, NY
Confidential Client, Expert Review and Remediation, Yonkers, NY
Confidential Client, Senior Environmental Consulting, Brooklyn, NY
Expert Affidavit, Confidential Client, New York, NY
Underground Storage Tank Removals, New York, NY